# TRANSPORT AND WORKS ACT 1992 TOWN AND COUNTRY PLANNING ACT 1990

#### PLANNING (LISTED BUILDINGS AND CONSERVATION AREAS) ACT 1990

## PROPOSED LONDON UNDERGROUND (NORTHERN LINE EXTENSION) ORDER

PROOF OF EVIDENCE

OF

Jonathan R A Gammon Engineering

**FOR** 

TRANSPORT FOR LONDON (TfL)

**DOCUMENT TFL2/B** 

October 2013

#### APPENDIX TO PROOF OF EVIDENCE

#### Contents

APPENDIX 1	1 TABLES	1
Table 1 Table 2 Table 3	Summary of the typical ground conditions along the NLE route Building Damage Classification Summary of analysis phases outlined in LUL Standard 1-050 Issue A2 (January 2009) and LUL Guidelines on ground movement due to tunneling.	1 2 3
APPENDIX 2	2 FIGURES	5
Figure 1.	Scheme Layout	7
Figure 2.	Geological Profile of reference design alignment (1 of 3)	8
Figure 3.	Geological Profile of reference design alignment (2 of 3)	9
Figure 4.	Geological Profile of reference design alignment (3 of 3)	10
Figure 5.	EPBM Schematic	11
Figure 6.	SCL Diagram	12
Figure 7.	SGI Diagram lining	13
Figure 8.	Battersea Station –Configuration sheet 1	14
Figure 9.	Battersea Station –Configuration sheet 2	15
Figure 10.	Battersea Station – Crossover box	17
Figure 11.	Battersea Station – Overrun Tunnels	18
Figure 12.	Proposed cross passages 5 and 6	19
Figure 13.	Battersea Station – Worksite drawings	20
Figure 14.	Battersea Station – Conveyor Route	21
Figure 15.	Cross passage locations	22
Figure 16.	Northbound Horizontal and Vertical Track Alignment Sheet 1	23
Figure 17.	Northbound Horizontal and Vertical Track Alignment Sheet 2	24
Figure 18.	Northbound Horizontal and Vertical Track Alignment Sheet 3	25
Figure 19.	Northbound Horizontal and Vertical Track Alignment Sheet 4	26
Figure 20.	Northbound Horizontal and Vertical Track Alignment Sheet 5	27
Figure 21.	Northbound Horizontal and Vertical Track Alignment Sheet 6	28
Figure 22.	Northbound Horizontal and Vertical Track Alignment Sheet 7	29
Figure 23.	Northbound Horizontal and Vertical Track Alignment Sheet 8	30
Figure 24.	Northbound Horizontal and Vertical Track Alignment Sheet 9	31
Figure 25.	Northbound Horizontal and Vertical Track Alignment Sheet 10	32 33
Figure 26.	Northbound Horizontal and Vertical Track Alignment Sheet 11	34
Figure 27.	Northbound Horizontal and Vertical Track Alignment Sheet 12	35
Figure 28. Figure 29.	Nine Elms Station – Configuration sheet 1 Nine Elms Station – Configuration sheet 2	36
Figure 30.	Nine Elms Station – Configuration sheet 2  Nine Elms Station – Worksite Layout	37
Figure 31.	Cross passage CP1 and CP2	38
Figure 31.	Cross passage – CP3	39
Figure 33.	Kennington Green – Alternatives	41
Figure 34.	Kennington Green – Configuration	43
Figure 35.	Kennington Green – Work site layout	44

Figure 36.	Kennington Park – Configuration	45		
Figure 37.	Kennington Park – Worksite Layout	46		
Figure 38.	Gallery Tunnels	47		
Figure 39.	Step Plate Junction	49		
Figure 40.	Kennington Station - Cross Passages			
Figure 41.	Surface settlement contours sheet 1 of 5			
Figure 42.	Surface settlement contours sheet 2 of 5	52		
Figure 43.	Surface settlement contours sheet 3 of 5	53		
Figure 44.	Surface settlement contours sheet 4 of 5			
Figure 45.	Surface settlement contours sheet 5 of 5			
Figure 46.	Surface settlement contours- gallery tunnel			
Figure 47.	Typical running tunnel section			
Figure 48.	Typical tunnel cross section	59		
APPENDIX	3 OBJECTIONS	61		
, a i Litoix	0 00000110110	01		
ADDENDIV	4 DOCUMENTO	0.5		
APPENDIX	4 DOCUMENTS	85		
4.1 Fire and	Safety and Tunnel Ventilation Strategy	86		
4.2 Flood Risk Assessment				
4.3 Kennington Station Shaft				
_				
<b>APPENDIX</b>	5 GLOSSARY	133		

### Appendix 1

#### **Tables**

Table 1 Summary of the typical ground conditions along the NLE route

I I			Loose to dense clayey sandy gravel with
			occasional cobbles to soft to firm sandy
			gravelly clay. Gravel and cobbles comprise
			flint, brick and concrete with occasional ash,
Made	+5.50 to		clinker, metal and timber. Localised
Ground	+1.60	0.50 to 3.95	contamination evident.
0.00.110	12.00	0.50 to 5.55	Soft grey clay with varying quantities of
	+4.60 to -		organic material, including localised bands of
Alluvium	0.75	0.00 to 3.95	fibrous peat. Locally absent.
	0110		Loose to dense brown sandy gravel varying to
			sand & gravel or locally very gravelly sand.
River			Gravel is predominantly flint. (River Terrace
Terrace	+4.10 to -	1.25 to	Deposits may be up to 22.85m deep in local
Deposits	1.95	10.00	scour features)
- 1			Stiff to very stiff grey brown becoming bluey
			grey fissured clay with sand and silt
			laminations, thin bands and nodules of
			calcareous material, pyrite or selenite, and
			fragments of wood. The base of the London
London			Clay is marked by a thin layer of sandy gravelly
Clay	0.00 to -	19.0 to	clay (Harwich Formation) and on occasions
Formation	9.00	37.00	with particularly sandy in the basal layers
			A complex accumulation of deposits including:
			Very stiff/hard shelly clay with occasional
			limestone concretions (Upper Shelly Clay)
			Very dense interbedded silts, sands and very
			stiff/hard clays. Water bearing (Laminated
			Beds)
			Very stiff/hard shelly clay with numerous
			calcareous nodules (Lower Shelly Clay)
			Very stiff/hard mottled clays with thin bands
			of very dense silt (Lower Mottled Clay)
			Rounded gravel pebbles over very dense
			green find to medium sand (Upnor Formation)
Lambeth	-19.00 to -	5.95 to	Base of the Lambeth Group is often
Group	41.60	18.90	misinterpreted as Thanet Sand.
Thanet	-23.00 to -	8.50 to	Very dense greyish green silty fine sand
Sand	56.80	12.20	
			Moderately weak to moderately strong
Upper	-63.90 to -	Base not	medium density white chalk with flint bands
Chalk	69.00	penetrated	(Grade B2)

**Table 2 Building Damage Classification** 

		Building D	amage Classification <sup>1</sup>	
1	2	3	4	5
Risk Category	Max Tensile Strain %	Description of Degree of Damage	Description of Typical Damage and Likely Form of Repair for Typical Masonry buildings	Approx <sup>2</sup> Crack Width (mm)
0	0.05 or less	Negligible	Hairline cracks.	
1	More than 0.05 and not exceeding 0.075	Very Slight	Fine cracks easily treated during normal redecorations. Perhaps isolated slight fracture in building. Cracks in exterior brickwork visible upon close inspection.	0.1 to 1
2	More than 0.075 and not exceeding 0.15	Slight	Cracks easily filled. Redecoration probably required. Several slight fractures inside building. Exterior cracks visible; some repointing may be required for weather-tightness. Doors and windows may stick slightly.	1 to 5
3	More than 0.15 and not exceeding 0.3	Moderate	Cracks may require cutting out and patching. Recurrent cracks can be masked by suitable linings. Repointing and possibly replacement of a small amount of exterior brickwork may be required. Doors and windows sticking. Utility services may be interrupted. Weather tightness often impaired.	5 to 15 or a number of cracks greated than 3
4	More than 0.3	Severe	Extensive repair involving removal and replacement of sections of walls, especially over doors and windows required. Windows and door frames distorted. Floor slopes noticeably. Walls lean or bulge noticeably, some loss of bearing in beams. Utility services disrupted.	15 to 25 but also depends on number of cracks
5		Very Severe	Major repair required involving partial or complete reconstruction. Beams lose bearing, walls lean badly and require shoring. Windows broken by distortion. Danger of instability.	Usually greate than 25 but depends on number of cracks

#### Notes

The table is based on the work of Burland et al (1977) and includes typical
maximum tensile strains for the various damage categories (column 2) used in
phase 2 settlement analysis.

## Table 3 Summary of analysis phases outlined in LUL Standard 1-050 Issue A2 (January 2009) and LUL Guidelines on ground movement due to tunneling.

Phase	Clause	Description
1 (Green field predictions of settlement)	3.6.1.4 (1-050) or 2.3 (LUL Guidelines)	1. Settlement predictions for bored tunnels should be produced using empirically validated methods such as O'Reilly and New (1982), using parameters for ground loss determine from case histories.  2. For excavations, assessment should be undertaken using models validated by empirical date based on case studies of similar excavations.  3. For buildings that experience less than 10mm no further assessment is necessary.  4. Buildings with settlement or heave greater than 10mm or predicted ground slope of 1:500 or steeper are subject to a Phase 2 assessment.
2	3.6.1.5 (1-050) or 2.4 (LUL Guidelines)	5. The movements predicted for green field conditions are imposed on buildings. (Buildings are assumed to behave flexibly and their own stiffness has no influence on ground settlement).  6. The potential for damage is defined using the procedures described by Burland et al. (1977, cited in CIRIA 200, 2001) and placed into one of six risk categories (numbered 0 – 5).  7. Buildings assessed to be in risk category 0, 1 or 2 are not subjected to further assessment. (Exceptions include listed buildings or building with shallow foundation in close proximity to excavations),  8. All buildings which are placed in risk category 3 or above are subject to a Phase 3 assessment.
3*	3.6.1.6 (1-050) or 2.5 (LUL Guidelines)	Each building is considered separately. The assessment will involve the development of a building specific detail model rather than the more generic model forms used in Phase 2.

<sup>\*</sup>Phase 3 level of detail exceeds the requirements of the Reference Design and should be carried out during the detailed design phase.

## Appendix 2

## **Figures**




Figure 1: Scheme Layout




Figure 2: Geological Profile of reference design alignment (1 of 3)




Figure 3: Geological Profile of reference design alignment (2 of 3)




Figure 4: Geological Profile of reference design alignment (3 of 3)





Figure 5 Earth Pressure Balance TBM Schematic




Figure 6 SCL lining



Figure 7 SGI lining




Section showing sequence of spaces from entrance to platform




Ground level plan showing station and cross-over in outline within the completed master plan

Figure 8 Battersea Station-Configuration - Sheet 1



Ticket hall & upper concourse plan



Platform level plan at Battersea Station

Figure 9 Battersea Station-Configuration - Sheet 2




Figure 10: Battersea Station- Crossover box




Figure 11: Battersea Station Overrun Tunnels




Figure 12 Cross Passage –CP1 and CP2




Figure 13: Battersea Station – Worksite




Figure 14: Battersea Station Overrun Tunnels




Figure 12 – Cross Passage Locations




Figure 16 – Northbound Horizontal and Vertical Track Alignment Sheet 1




Figure 17 – Northbound Horizontal and Vertical Track Alignment Sheet 2




Figure 18 – Northbound Horizontal and Vertical Track Alignment Sheet 3



Figure 19 – Northbound Horizontal and Vertical Track Alignment Sheet 4





Figure 20 – Northbound Horizontal and Vertical Track Alignment Sheet 5






Figure 21 – Northbound Horizontal and Vertical Track Alignment Sheet 6




Figure 22 – Northbound Horizontal and Vertical Track Alignment Sheet 7




Figure 23 – Northbound Horizontal and Vertical Track Alignment Sheet 8




Figure 24 – Northbound Horizontal and Vertical Track Alignment Sheet 9




Figure 25 – Northbound Horizontal and Vertical Track Alignment Sheet 10




Figure 26 – Northbound Horizontal and Vertical Track Alignment Sheet 11






Figure 27 – Northbound Horizontal and Vertical Track Alignment Sheet 12




Existing site layout at Nine Elms




Approved Sainsbury's scheme showing phases 1 & 2

Figure 28 Nine Elms Plans Configuration – Sheet 1



Aspects of the station entrance building



Ticket hall ground level plan

Figure 29 Nine Elms Plans Configuration – Sheet 2