

Defect Id	Date Inspected	Road Id	Road Name	Location	Description	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
282278	02-Sep-2010	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrwest os 219	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	30-Sep-2010	28 Day Defect
282727	05-Sep-2010	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(INSTRUCTED) - (RICH) A205 urrd west jn potman av	NULL	2L	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	22-Oct-2009	Low Priority De
283862	09-Sep-2010	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrw jc lewin rd	NULL	2M	Post Defect	Damaged/Deformed	Permanent	07-Oct-2010	28 Day Defect
283863	09-Sep-2010	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrw os 218	NULL	2H	Footways And Cycle Tracks	Block profile	Permanent	16-Sep-2010	7 Day Defect
283864	09-Sep-2010	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrw os 245	NULL	2H	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	16-Sep-2010	7 Day Defect
284969	16-Sep-2010	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 URRW os 333 wb	NULL	2M	Footways And Cycle Tracks	Block profile	Permanent	14-Oct-2010	28 Day Defect
287483	30-Sep-2010	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 URRW 60m east priest bridge	NULL	2M	Footways And Cycle Tracks	Blacktop : fretting	Permanent	28-Oct-2010	28 Day Defect
287484	30-Sep-2010	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 URRW 50m east priests bridge	NULL	2M	Safety Fences: Metal/Concrete	Damaged/deformed	Permanent	28-Oct-2010	28 Day Defect
289144	07-Oct-2010	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrw os 244a lc 43	NULL	1A	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	04-Nov-2010	EMG - 24hr Defe
289144	07-Oct-2010	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrw os 244a lc 43	NULL	1A	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Temporary	08-Oct-2010	EMG - 24hr Defe
289863	12-Oct-2010	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrw os 160	NULL	2H	Footways And Cycle Tracks	Block profile	Permanent	19-Oct-2010	7 Day Defect
289865	12-Oct-2010	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrw os 177	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	09-Nov-2010	28 Day Defect
289868	12-Oct-2010	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd w o/s 98 jn grosvenor	NULL	2H	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	19-Oct-2010	7 Day Defect
292953	27-Oct-2010	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(INSTRUCTED) - (RICH) A205 urrdw o/s 122	NULL	2M	Footways And Cycle Tracks	Kerb/channel block alignment	Permanent	24-Nov-2010	28 Day Defect
293346	29-Oct-2010	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - A205 Upper Richmond Road JW Sheen Lane	Missing Bollard.	2M	Post Defect	Missing	Permanent	26-Nov-2010	28 Day Defect
294724	04-Nov-2010	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(INSTRUCTED) - (RICH) A205 urrd o/s 186	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	02-Dec-2010	28 Day Defect
294726	04-Nov-2010	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(SUPERSEDED) - (RICH) A205 urrd w jn palewell pk	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	16-Oct-2009	28 Day Defect
297624	18-Nov-2010	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd west jn lewin rd	NULL	2H	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	25-Nov-2010	7 Day Defect
299112	25-Nov-2010	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 URRW op east sheen av	NULL	1A	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	23-Dec-2010	EMG - 24hr Defe
299112	25-Nov-2010	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 URRW op east sheen av	NULL	1A	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Temporary	26-Nov-2010	EMG - 24hr Defe

301302	10-Dec-2010	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - A205 Upper Richmond Road West os 166-168	Blister Paving is Damaged and Customer Complaint.	2H	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	17-Dec-2010	7 Day Defect
302060	15-Dec-2010	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd jn richmond park o/s 34	NULL	1A	Footways And Cycle Tracks	Block profile	Permanent	12-Jan-2011	EMG - 24hr Defe
302060	15-Dec-2010	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd jn richmond park o/s 34	NULL	1A	Footways And Cycle Tracks	Block profile	Temporary	16-Dec-2010	EMG - 24hr Defe
304677	06-Jan-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd w o/s 208	NULL	2H	Footways And Cycle Tracks	Standing Water	Permanent	13-Jan-2011	7 Day Defect
305962	12-Jan-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - A205, Upper richmond J/W Palewell Park	Metal Post knocked over Carriageway.	1A	Post Defect	Damaged/Deformed	Permanent	09-Feb-2011	EMG - 24hr Defe
307395	19-Jan-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - A205, Upper Richmond Road West	Post with loading bay sign in footway has been knocked over!	1A	Post Defect	Damaged/Deformed	Permanent	16-Feb-2011	EMG - 24hr Defe
307395	19-Jan-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - A205, Upper Richmond Road West	Post with loading bay sign in footway has been knocked over!	1A	Post Defect	Damaged/Deformed	Temporary	20-Jan-2011	EMG - 24hr Defe
307310	19-Jan-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - A205 Upper Richmond Road West JW Paynesf	2 Dislodged kerb stones	1A	Footways And Cycle Tracks	Kerb/channel block alignment	Permanent	16-Feb-2011	EMG - 24hr Defe
307710	20-Jan-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd jn lewin rd	NULL	1A	Footways And Cycle Tracks	Cracking	Permanent	17-Feb-2011	EMG - 24hr Defe
307710	20-Jan-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd jn lewin rd	NULL	1A	Footways And Cycle Tracks	Cracking	Temporary	21-Jan-2011	EMG - 24hr Defe
307712	20-Jan-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd jn palewell park	NULL	2H	Footways And Cycle Tracks	Block profile	Permanent	27-Jan-2011	7 Day Defect
307713	20-Jan-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd os 275-285	NULL	2H	Footways And Cycle Tracks	Block profile	Permanent	27-Jan-2011	7 Day Defect
307714	20-Jan-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd jn wallerton gds	NULL	2M	Footways And Cycle Tracks	Block profile	Permanent	17-Feb-2011	28 Day Defect
309575	28-Jan-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - A205, Upper Richmond Rd west J/W Sheen	Dislodge bell bollard	1A	Post Defect	Damaged/Deformed	Permanent	25-Feb-2011	EMG - 24hr Defe
309575	28-Jan-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - A205, Upper Richmond Rd west J/W Sheen	Dislodge bell bollard	1A	Post Defect	Damaged/Deformed	Temporary	29-Jan-2011	EMG - 24hr Defe
315962	02-Mar-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 URRW jw wallorton gdns	NULL	1A	Post Defect	Damaged/Deformed	Permanent	30-Mar-2011	EMG - 24hr Defe
315962	02-Mar-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 URRW jw wallorton gdns	NULL	1A	Post Defect	Damaged/Deformed	Temporary	03-Mar-2011	EMG - 24hr Defe
318825	17-Mar-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrw os 180	NULL	2H	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	24-Mar-2011	7 Day Defect
318827	17-Mar-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(SELECTED) - (RICH) A205 urrw os 197	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	14-Apr-2011	28 Day Defect
320736	29-Mar-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(SELECTED) - A205 urrw os 170	NULL	2H	Footways And Cycle Tracks	Slab rocking	Permanent	05-Apr-2011	7 Day Defect

320737	29-Mar-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(SELECTED) - A205 urrw jc sutherland gdns	NULL	2M	Footways And Cycle Tracks	Block profile	Permanent	26-Apr-2011	28 Day Defect
320740	29-Mar-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(SELECTED) - (RICH) A205 urrd w o/s 216 hare hound	NULL	2H	Footways And Cycle Tracks	Slab rocking	Permanent	05-Apr-2011	7 Day Defect
320741	29-Mar-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(SELECTED) - (RICH) A205 urrd w jn lewin rd	NULL	2H	Footways And Cycle Tracks	Accident damage	Permanent	05-Apr-2011	7 Day Defect
321203	30-Mar-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - A205 urrw os 188 jc portman rd	NULL	1A	Post Defect	Damaged/Deformed	Permanent	27-Apr-2011	EMG - 24hr Defe
321203	30-Mar-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - A205 urrw os 188 jc portman rd	NULL	1A	Post Defect	Damaged/Deformed	Temporary	31-Mar-2011	EMG - 24hr Defe
322981	07-Apr-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 URRW op 327 LC 49	NULL	2H	Footways And Cycle Tracks	Slab rocking	Permanent	14-Apr-2011	7 Day Defect
325242	19-Apr-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - A205 Upper Richmond Rd West 50M east Pri	Found By Inspector - SB Req re-setting	2M	Safety Bollards: Face/Structure/ Fixings	Accident damage	Permanent	17-May-2011	28 Day Defect
328612	11-May-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(SUPERSEDED) - (RICH) A205 urrd w o/s 254 jn sheen ln	NULL	2H	Post Defect	Accident damage	Permanent	18-May-2011	7 Day Defect
328613	11-May-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(REF TO NOT) - (RICH) A205 urrd w o/s 299-309	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	08-Jun-2011	28 Day Defect
330282	19-May-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 URRW op avenue gdns	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	16-Jun-2011	28 Day Defect
330264	19-May-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(SUPERSEDED) - (RICH) A205 URRW op avenue gdns	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	16-Jun-2011	28 Day Defect
330876	23-May-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrw jc lewin rd	NULL	2H	Footways And Cycle Tracks	Block profile	Permanent	30-May-2011	7 Day Defect
332825	02-Jun-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 URR west jw avenue gdns	NULL	1A	Footways And Cycle Tracks	Block profile	Permanent	30-Jun-2011	EMG - 24hr Defe
332825	02-Jun-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 URR west jw avenue gdns	NULL	1A	Footways And Cycle Tracks	Block profile	Temporary	03-Jun-2011	EMG - 24hr Defe
335627	16-Jun-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd west os 206	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	14-Jul-2011	28 Day Defect
335628	16-Jun-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd west o/s 212b	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	14-Jul-2011	28 Day Defect
335992	17-Jun-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - A205 Upper Richmond Rd West O/S No-144 L	Sunken Footway Slabs	1A	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	15-Jul-2011	EMG - 24hr Defe
335992	17-Jun-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - A205 Upper Richmond Rd West O/S No-144 L	Sunken Footway Slabs	1A	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Temporary	18-Jun-2011	EMG - 24hr Defe
336564	22-Jun-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrw os 186	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	20-Jul-2011	28 Day Defect
336569	22-Jun-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(SELECTED) - (RICH) A205 urrd west o/s 172	NULL	2M	Footways And Cycle Tracks	Slab rocking	Permanent	20-Jul-2011	28 Day Defect

338673	30-Jun-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd w o/s 136	NULL	2H	Footways And Cycle Tracks	Slab rocking	Permanent	07-Jul-2011	7 Day Defect
338674	30-Jun-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd w o/s 343	NULL	2H	Footways And Cycle Tracks	Slab rocking	Permanent	07-Jul-2011	7 Day Defect
338675	30-Jun-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(SUPERSEDE D) - (RICH) A205 urrd w o/s 299	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	28-Jul-2011	28 Day Defect
338676	30-Jun-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(CANCELLED) - (RICH) A205 urrd w j gilpin av	NULL	2M	Footways And Cycle Tracks	Block profile	Permanent	28-Jul-2011	28 Day Defect
340670	08-Jul-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - Upper Richmond Road West	Collapsed pavement outside No.132	1A	Footways And Cycle Tracks	Collapsed	Permanent	05-Aug-2011	EMG - 24hr Defe
340670	08-Jul-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - Upper Richmond Road West	Collapsed pavement outside No.132	1A	Footways And Cycle Tracks	Collapsed	Temporary	09-Jul-2011	EMG - 24hr Defe
341981	14-Jul-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 URRW jw sheen ln	NULL	2H	Footways And Cycle Tracks	Block profile	Permanent	21-Jul-2011	7 Day Defect
344512	28-Jul-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(SUPERSEDE D) - (RICH) A205 urrd w o/s 317	NULL	2H	Footways And Cycle Tracks	Block profile	Permanent	04-Aug-2011	7 Day Defect
344513	28-Jul-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(SUPERSEDE D) - (RICH) A205 urrd w o/s 309	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	25-Aug-2011	28 Day Defect
344514	28-Jul-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(SUPERSEDE D) - (RICH) A205 urrd w	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	25-Aug-2011	28 Day Defect
344515	28-Jul-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(SUPERSEDE D) - (RICH) A205 urrd w o/s 239	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	25-Aug-2011	28 Day Defect
344516	28-Jul-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(SUPERSEDE D) - (RICH) A205 urrd w jn wallerton gds	NULL	2M	Post Defect	Accident damage	Permanent	25-Aug-2011	28 Day Defect
344539	28-Jul-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd w o/s 317	NULL	2H	Footways And Cycle Tracks	Block profile	Permanent	04-Aug-2011	7 Day Defect
344540	28-Jul-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(SUPERSEDE D) - (RICH) A205 urrd w o/s 309	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	25-Aug-2011	28 Day Defect
344541	28-Jul-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(SUPERSEDE D) - (RICH) A205 urrd w	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	25-Aug-2011	28 Day Defect
344542	28-Jul-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd w o/s 239	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	25-Aug-2011	28 Day Defect
344543	28-Jul-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd w jn wallerton gds	NULL	2M	Post Defect	Accident damage	Permanent	25-Aug-2011	28 Day Defect
345554	04-Aug-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(SELECTED) - (RICH) A205 urrd west opp preist bridge	NULL	2M	Footways And Cycle Tracks	Blacktop : extensive cracking	Permanent	01-Sep-2011	28 Day Defect
345555	04-Aug-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(CANCELLED) - (RICH) A205 urrd west opp npreist bridge	NULL	2M	Footways And Cycle Tracks	Blacktop : extensive cracking	Permanent	01-Sep-2011	28 Day Defect
345557	04-Aug-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd west o/s 52	NULL	2H	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	11-Aug-2011	7 Day Defect

345558	04-Aug-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(SELECTED) - (RICH) A205 urrd w jn grosvenor gds	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	01-Sep-2011	28 Day Defect
346196	09-Aug-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 URRW opp Avenue gdns	NULL	2M	Post Defect	Damaged/Deformed	Permanent	06-Sep-2011	28 Day Defect
349490	01-Sep-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 U R RD west os 335	NULL	1A	Footways And Cycle Tracks	Collapsed	Permanent	29-Sep-2011	EMG - 24hr Defe
349490	01-Sep-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 U R RD west os 335	NULL	1A	Footways And Cycle Tracks	Collapsed	Temporary	02-Sep-2011	EMG - 24hr Defe
351263	09-Sep-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - A205-Upper Richmond Rd West. Sheen Ln.	1 unstable Paving Slab in the Eastbound Footway.	1A	Footways And Cycle Tracks	Slab rocking	Permanent	07-Oct-2011	EMG - 24hr Defe
351600	13-Sep-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrw os 50 at ped lights	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	11-Oct-2011	28 Day Defect
351602	13-Sep-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrw os 170 lc59	NULL	2H	Footways And Cycle Tracks	Slab rocking	Permanent	20-Sep-2011	7 Day Defect
351603	13-Sep-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrw os 227-237	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	11-Oct-2011	28 Day Defect
351608	13-Sep-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd west o/s 106	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	11-Oct-2011	28 Day Defect
351609	13-Sep-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd west o/s 162	NULL	2M	Footways And Cycle Tracks	Cracking around ironwork	Permanent	11-Oct-2011	28 Day Defect
353777	22-Sep-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(CANCELLED) - (RICH) A205 URRW jw thornton rd	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	20-Oct-2011	28 Day Defect
361164	27-Oct-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 u r rd west jw portman av	NULL	2M	Post Defect	Damaged/Deformed	Permanent	24-Nov-2011	28 Day Defect
363143	08-Nov-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(SELECTED) - (RICH) A205 urrw os 203	NULL	2M	Footways And Cycle Tracks	Block profile	Permanent	06-Dec-2011	28 Day Defect
363145	08-Nov-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrw os 188a	NULL	2H	Footways And Cycle Tracks	Block profile	Permanent	15-Nov-2011	7 Day Defect
363151	08-Nov-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(SUPERSEDED) - (RICH) A205 urrd west o/s 186	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	06-Dec-2011	28 Day Defect
363790	10-Nov-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - A205, URRW, O/S 197	Sunken paving in f/w	1A	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	08-Dec-2011	EMG - 24hr Defe
363790	10-Nov-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - A205, URRW, O/S 197	Sunken paving in f/w	1A	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Temporary	11-Nov-2011	EMG - 24hr Defe
366530	24-Nov-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd west jn richmond pk rd	NULL	2H	Footways And Cycle Tracks	Block profile	Permanent	01-Dec-2011	7 Day Defect
368392	06-Dec-2011	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 URRW os 170	NULL	2H	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	13-Dec-2011	7 Day Defect
373805	12-Jan-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(SELECTED) - (RICH) A205 UURW os 166	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	09-Feb-2012	28 Day Defect

378903	09-Feb-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 URRW jw palewell pk	NULL	2H	Footways And Cycle Tracks	Block profile	Permanent	16-Feb-2012	7 Day Defect
384835	08-Mar-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 u r rd west jw lewin rd	NULL	1A	Post Defect	Damaged/Deformed	Permanent	05-Apr-2012	EMG - 24hr Defe
384835	08-Mar-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 u r rd west jw lewin rd	NULL	1A	Post Defect	Damaged/Deformed	Temporary	09-Mar-2012	EMG - 24hr Defe
384836	08-Mar-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 u r rd west jw queens rd	NULL	2H	Footways And Cycle Tracks	Slab cracking	Permanent	15-Mar-2012	7 Day Defect
384838	08-Mar-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 u r rd west jw grosvenor gdn	NULL	2M	Footways And Cycle Tracks	Block profile	Permanent	05-Apr-2012	28 Day Defect
384839	08-Mar-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 u r rd west os 48	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	05-Apr-2012	28 Day Defect
384840	08-Mar-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(SELECTED) - (RICH) A205 urrd west op the willoughbys	NULL	2L	Footways And Cycle Tracks	Blacktop : fretting	Permanent	08-Mar-2022	Low Priority De
385575	13-Mar-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - A205 Upper Richond Rd Wst j/w Sheen Lane	Loose Tactile/ Trip Hazard.	1A	Footways And Cycle Tracks	Loose/rocking	Permanent	10-Apr-2012	EMG - 24hr Defe
385989	15-Mar-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 u r rd west jw kings rd	NULL	2H	Footways And Cycle Tracks	Slab rocking	Permanent	22-Mar-2012	7 Day Defect
385991	15-Mar-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 u r rd west os 240	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	12-Apr-2012	28 Day Defect
385992	15-Mar-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 u r rd west os 335	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	12-Apr-2012	28 Day Defect
385993	15-Mar-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 u r rd west os 239-249	NULL	1A	Footways And Cycle Tracks	Block profile	Permanent	12-Apr-2012	EMG - 24hr Defe
385993	15-Mar-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 u r rd west os 239-249	NULL	1A	Footways And Cycle Tracks	Block profile	Temporary	16-Mar-2012	EMG - 24hr Defe
386924	22-Mar-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 URRW jw queens rd	NULL	2H	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	29-Mar-2012	7 Day Defect
386925	22-Mar-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 u r rd west jw thornon rd	NULL	1A	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	19-Apr-2012	EMG - 24hr Defe
386925	22-Mar-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 u r rd west jw thornon rd	NULL	1A	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Temporary	24-Oct-2008	EMG - 24hr Defe
388301	03-Apr-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - A205-Upper Richmond Road West. Sheen Ln.	1 Hole in the Westbound Footway.	1A	Footways And Cycle Tracks	Blacktop : potholes>25mm	Permanent	01-May-2012	EMG - 24hr Defe
388301	03-Apr-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - A205-Upper Richmond Road West. Sheen Ln.	1 Hole in the Westbound Footway.	1A	Footways And Cycle Tracks	Blacktop : potholes>25mm	Temporary	04-Apr-2012	EMG - 24hr Defe
388609	04-Apr-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrw os 166	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	02-May-2012	28 Day Defect
388610	04-Apr-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 URRW op 190	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	02-May-2012	28 Day Defect

390856	19-Apr-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - o/s 50 Upper Richmond Road West (A205)	Ponding - Lift and relay slabs	2M	Footways And Cycle Tracks	Standing Water	Permanent	17-May-2012	28 Day Defect
390877	19-Apr-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 URRW jw sheen ln	NULL	2H	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	26-Apr-2012	7 Day Defect
391636	24-Apr-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd west bo/a 114-116	NULL	2M	Footways And Cycle Tracks	Localised edge deterioration	Permanent	22-May-2012	28 Day Defect
391866	25-Apr-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - o/s 212 Upper Richmond Road West (A205)	Ponding - Lift and relay slabs - X=520666 & Y=175419	2M	Footways And Cycle Tracks	Standing Water	Permanent	23-May-2012	28 Day Defect
391867	25-Apr-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - o/s 212B Upper Richmond Road West (A205)	Ponding - Lift and relay slabs - X=520650 & Y=175401	2M	Footways And Cycle Tracks	Standing Water	Permanent	23-May-2012	28 Day Defect
391869	25-Apr-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - o/s 188 Upper Richmond Road West (A205)	Ponding - Lift and relay slabs - X=520734 & Y=175424	2M	Footways And Cycle Tracks	Standing Water	Permanent	23-May-2012	28 Day Defect
391876	25-Apr-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - o/s 220 Upper Richmond Road West (A205)	Ponding - Lift and relay slabs - X=520612 & Y=175423	2M	Footways And Cycle Tracks	Standing Water	Permanent	23-May-2012	28 Day Defect
391924	25-Apr-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - o/s 222 Upper Richmond Road West (A205)	Ponding - Lift and relay slabs - X=520608 & Y=175422	2M	Footways And Cycle Tracks	Standing Water	Permanent	23-May-2012	28 Day Defect
391874	25-Apr-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - o/s 184 Upper Richmond Road West (A205)	Ponding - Lift and relay slabs - X=520759 & Y=175413	2M	Footways And Cycle Tracks	Standing Water	Permanent	23-May-2012	28 Day Defect
395100	10-May-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 u r rd west jw kings rd	NULL	2H	Footways And Cycle Tracks	Slab rocking	Permanent	17-May-2012	7 Day Defect
395101	10-May-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 u r rd west jw grosvenor grd	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	07-Jun-2012	28 Day Defect
397591	22-May-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) Sheen ln jw A205 URRW	NULL	1A	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	19-Jun-2012	EMG - 24hr Defe
397591	22-May-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) Sheen ln jw A205 URRW	NULL	1A	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Temporary	23-May-2012	EMG - 24hr Defe
401112	11-Jun-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - A205 Upper Richmond Road JW Sheen Lane	Dislodged Bell Bollard	1A	Post Defect	Damaged/Deformed	Permanent	09-Jul-2012	EMG - 24hr Defe
401112	11-Jun-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - A205 Upper Richmond Road JW Sheen Lane	Dislodged Bell Bollard	1A	Post Defect	Damaged/Deformed	Temporary	12-Jun-2012	EMG - 24hr Defe
401113	11-Jun-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - A205 Upper Richmond Rd JW Sheen Lane	Dislodged paving slabs	1A	Footways And Cycle Tracks	Accident damage	Permanent	09-Jul-2012	EMG - 24hr Defe
401113	11-Jun-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - A205 Upper Richmond Rd JW Sheen Lane	Dislodged paving slabs	1A	Footways And Cycle Tracks	Accident damage	Temporary	12-Jun-2012	EMG - 24hr Defe
401697	14-Jun-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 u r rd west jw queens rd	NULL	2H	Footways And Cycle Tracks	Slab cracking	Permanent	21-Jun-2012	7 Day Defect
402449	19-Jun-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(CANCELLED) - (RICH) A205 urrw os 197	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	17-Jul-2012	28 Day Defect
404915	05-Jul-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 u r rd west os 134	NULL	2H	Footways And Cycle Tracks	Slab rocking	Permanent	12-Jul-2012	7 Day Defect

406450	17-Jul-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 u r rd west so 184	NULL	2M	Footways And Cycle Tracks	Block profile	Permanent	14-Aug-2012	28 Day Defect
406452	17-Jul-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 u r rd west jw sheen lane	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	14-Aug-2012	28 Day Defect
406454	17-Jul-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 u r rd west os 287-297	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	14-Aug-2012	28 Day Defect
406458	17-Jul-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 URRW op 40	NULL	2M	Footways And Cycle Tracks	Blacktop : fretting	Permanent	14-Aug-2012	28 Day Defect
406464	17-Jul-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 URRW os 134	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	14-Aug-2012	28 Day Defect
406469	17-Jul-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 URRW os 197	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	14-Aug-2012	28 Day Defect
406459	17-Jul-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 URRW op priests bridge	NULL	2M	Footways And Cycle Tracks	Blacktop : fretting	Permanent	14-Aug-2012	28 Day Defect
413732	20-Sep-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 up rich rd west jw gilpin av	NULL	2H	Footways And Cycle Tracks	Slab rocking	Permanent	27-Sep-2012	7 Day Defect
413733	20-Sep-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 up rich rd west os 210	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Oct-2012	28 Day Defect
414873	27-Sep-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrw opp 50 at ped crossing	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	25-Oct-2012	28 Day Defect
414871	27-Sep-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrw jc sutherland gdns	NULL	2M	Footways And Cycle Tracks	Block profile	Permanent	25-Oct-2012	28 Day Defect
415853	04-Oct-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd west jn av gds	NULL	2H	Footways And Cycle Tracks	Block profile	Permanent	11-Oct-2012	7 Day Defect
415854	04-Oct-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd west o/s 227 - 237	NULL	2H	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	11-Oct-2012	7 Day Defect
418783	23-Oct-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(INSTRUCTED) - A205, Upper Richmond Rd West, O/S 122	Damaged filter drain	1A	Footways And Cycle Tracks	Filter drain damage	Permanent	20-Nov-2012	EMG - 24hr Defe
418783	23-Oct-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(INSTRUCTED) - A205, Upper Richmond Rd West, O/S 122	Damaged filter drain	1A	Footways And Cycle Tracks	Filter drain damage	Temporary	24-Oct-2012	EMG - 24hr Defe
419075	25-Oct-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd west o/s 227-237	NULL	2H	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	01-Nov-2012	7 Day Defect
419076	25-Oct-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd west o/s 275-285	NULL	2H	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	01-Nov-2012	7 Day Defect
419077	25-Oct-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd west o/s 317	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	22-Nov-2012	28 Day Defect
419078	25-Oct-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd west o/s 256 barclays	NULL	2H	Footways And Cycle Tracks	Slab rocking	Permanent	01-Nov-2012	7 Day Defect
419080	25-Oct-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrd west opp the willoughbys	NULL	2M	Footways And Cycle Tracks	Blacktop : extensive cracking	Permanent	22-Nov-2012	28 Day Defect



423658	22-Nov-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 u r rd west jw richmnd par r	NULL	1A	Post Defect	Damaged/Deformed	Permanent	20-Dec-2012	EMG - 24hr Defe
423658	22-Nov-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 u r rd west jw richmnd par r	NULL	1A	Post Defect	Damaged/Deformed	Temporary	23-Nov-2012	EMG - 24hr Defe
423656	22-Nov-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 up r rd west jw avenue gardn	NULL	2H	Footways And Cycle Tracks	Block profile	Permanent	29-Nov-2012	7 Day Defect
423657	22-Nov-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(SELECTED) - (RICH) A205 up rich rd west os 166-168	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	20-Dec-2012	28 Day Defect
424859	29-Nov-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 u r rd west os 254 jw shen l	NULL	2H	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	06-Dec-2012	7 Day Defect
424861	29-Nov-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 up rich rd west os 210	NULL	2H	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	06-Dec-2012	7 Day Defect
427226	13-Dec-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(SELECTED) - (RICH) A205 urrd o/s 325	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	10-Jan-2013	28 Day Defect
428764	27-Dec-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - A205 Upper Richmond Road West. o/s Hamptons estate agents	Trip hazzard, raised block paving on f/w	1A	Footways And Cycle Tracks	Loose/rocking	Permanent	24-Jan-2013	EMG - 24hr Defe
428764	27-Dec-2012	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - A205 Upper Richmond Road West. o/s Hamptons estate agents	Trip hazzard, raised block paving on f/w	1A	Footways And Cycle Tracks	Loose/rocking	Temporary	28-Dec-2012	EMG - 24hr Defe
431374	17-Jan-2013	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(SELECTED) - (RICH) A205 u r rd west os 313	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	14-Feb-2013	28 Day Defect
431375	17-Jan-2013	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(SELECTED) - (RICH) A205 u r rd west os 317	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	14-Feb-2013	28 Day Defect
432144	24-Jan-2013	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 u r w os 297 sheen uncovered	NULL	2H	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	31-Jan-2013	7 Day Defect
432145	24-Jan-2013	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 u r w os 309 pizza express	NULL	2H	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	31-Jan-2013	7 Day Defect
432148	24-Jan-2013	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 up r w os 70 lc 85	NULL	2H	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	31-Jan-2013	7 Day Defect
432149	24-Jan-2013	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 u r w jw southernland grdns	NULL	2H	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	31-Jan-2013	7 Day Defect
433016	29-Jan-2013	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - (RICH) A205 urrw os 211	NULL	2H	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	05-Feb-2013	7 Day Defect
434666	11-Feb-2013	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - A205 Upper Richmond Road West, No.209	Damaged tarmac on pavement.	1A	Footways And Cycle Tracks	Pothole	Permanent	11-Mar-2013	EMG - 24hr Defe
434666	11-Feb-2013	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(COMPLETED) - A205 Upper Richmond Road West, No.209	Damaged tarmac on pavement.	1A	Footways And Cycle Tracks	Pothole	Temporary	12-Feb-2013	EMG - 24hr Defe
444745	01-May-2013	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Rd West J/W Priests Bridge	One Way Signpost been hit - req new Wide Base Post - Private Feed	2M	Post Defect	Accident damage	Permanent	29-May-2013	28 Day Defect
445010	02-May-2013	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper rich rd west jn lewin	NULL	1	Footways And Cycle Tracks	Pothole	Permanent	30-May-2013	Priority 1

445010	02-May-2013	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper rich rd west jn lewin	NULL	1	Footways And Cycle Tracks	Pothole	Temporary	03-May-2013	Priority 1
446564	09-May-2013	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 u r rd west os 311 321	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	06-Jun-2013	28 Day Defect
450005	24-May-2013	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road JW Wallorton Gns	Damaged metal bollard PEM982596 T41999 24-May-2013	1E	Post Defect	Damaged/Deformed	Permanent	21-Jun-2013	Priority 1 (ECO)
461788	23-Jul-2013	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 u r rd west jw thorn ton rd A205 u r rd	NULL	2H	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	30-Jul-2013	7 Day Defect
467311	20-Aug-2013	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 u r rd wst jw queens rd A205 u r rd ws	NULL	1	Footways And Cycle Tracks	Slab rocking	Permanent	17-Sep-2013	Priority 1
467311	20-Aug-2013	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 u r rd wst jw queens rd A205 u r rd ws	NULL	1	Footways And Cycle Tracks	Slab rocking	Temporary	21-Aug-2013	Priority 1
488141	17-Dec-2013	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 urrd west jn hartford av	NULL	2M	Safety Fences: Metal/Concrete	Accident damage	Permanent	14-Jan-2014	28 Day Defect
488142	17-Dec-2013	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 urrd west o/s 138	NULL	2M	Footways And Cycle Tracks	Slab rocking	Permanent	14-Jan-2014	28 Day Defect
488143	17-Dec-2013	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 urrd west o/s 126	NULL	2M	Footways And Cycle Tracks	Standing Water	Permanent	14-Jan-2014	28 Day Defect
488145	17-Dec-2013	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW jc queens rd A205 URRW jc queens	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	14-Jan-2014	28 Day Defect
488147	17-Dec-2013	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrw jc sutherland gdns A205 urrw jc s	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	14-Jan-2014	28 Day Defect
494031	21-Jan-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 u r rd west jw queens rd A205 u r rd w	NULL	1	Footways And Cycle Tracks	Slab rocking	Permanent	18-Feb-2014	Priority 1
494031	21-Jan-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 u r rd west jw queens rd A205 u r rd w	NULL	1	Footways And Cycle Tracks	Slab rocking	Temporary	22-Jan-2014	Priority 1
494032	21-Jan-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 u r rd west os 60 lc 86 A205 u r rd we	NULL	2H	Footways And Cycle Tracks	Shallow spalling at joints/cracks	Permanent	28-Jan-2014	7 Day Defect
494040	21-Jan-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 richmond pk rd o/s 339-341	NULL	2M	Footways And Cycle Tracks	Block profile	Permanent	18-Feb-2014	28 Day Defect
494042	21-Jan-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 URR W jn preist bridge	NULL	1	Footways And Cycle Tracks	Single crack	Permanent	18-Feb-2014	Priority 1
494042	21-Jan-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 URR W jn preist bridge	NULL	1	Footways And Cycle Tracks	Single crack	Temporary	22-Jan-2014	Priority 1
496497	03-Feb-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 upper richmond road west,out side 437	Make safe 2 knock down bollard	1E	Safety Bollards: Face/Structure/ Fixings	Damaged/deformed	Permanent	03-Mar-2014	Priority 1 (ECO)
496497	03-Feb-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 upper richmond road west,out side 437	Make safe 2 knock down bollard	1E	Safety Bollards: Face/Structure/ Fixings	Damaged/deformed	Temporary	04-Feb-2014	Priority 1 (ECO)
499635	18-Feb-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west o/s 219 A205 urrd west o/s	NULL	1	Footways And Cycle Tracks	Accident damage	Permanent	18-Mar-2014	Priority 1

499635	18-Feb-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west o/s 219 A205 urrd west o/s	NULL	1	Footways And Cycle Tracks	Accident damage	Temporary	19-Feb-2014	Priority 1
499639	18-Feb-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper richmond rd west o/s 128A A205 u	NULL	1	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Mar-2014	Priority 1
499639	18-Feb-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper richmond rd west o/s 128A A205 u	NULL	1	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Temporary	19-Feb-2014	Priority 1
499640	18-Feb-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper richmond west rd o/s 197 A205 u	NULL	2M	Footways And Cycle Tracks	Wear	Permanent	18-Mar-2014	28 Day Defect
499641	18-Feb-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper richmond west rd o/s 207 A205 u	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Mar-2014	28 Day Defect
499642	18-Feb-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRD west o/s 246A A205 URRD west o/s	NULL	2M	Footways And Cycle Tracks	Wear	Permanent	18-Mar-2014	28 Day Defect
500348	21-Feb-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road West j/w Queens Road	Make Safe very loose pieces of broken pavings which are set into a drain cover	1	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	22-Feb-2014	Priority 1
504302	10-Mar-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 upper Richmond Road East entrance to Priests bridge	make safe damaged bollard (T49997)	1	Safety Bollards, Face/Structure/ Fixings	Damaged/deformed	Permanent	11-Mar-2014	Priority 1
506095	18-Mar-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrw os 239-249 A205 urrw os 239-249	NULL	2M	Post Defect	Accident damage	Permanent	15-Apr-2014	28 Day Defect
506351	18-Mar-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 u r rd west jw queens rd	NULL	2H	Footways And Cycle Tracks	Slab rocking	Permanent	25-Mar-2014	7 Day Defect
512696	22-Apr-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west jn eastf sheen av A205 urrd	NULL	2M	Footways And Cycle Tracks	Block profile	Permanent	20-May-2014	28 Day Defect
524669	17-Jun-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 u rrd west o/s 214 PH A205 u rrd west	NULL	2M	Footways And Cycle Tracks	Cracking around ironwork	Permanent	15-Jul-2014	28 Day Defect
524662	17-Jun-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west o/s 1-9 mitchel crt A205 urr	NULL	2M	Footways And Cycle Tracks	Cracking around ironwork	Permanent	15-Jul-2014	28 Day Defect
524667	17-Jun-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west o/s 180a A205 urrd west o/s	NULL	1	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	15-Jul-2014	Priority 1
524667	17-Jun-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west o/s 180a A205 urrd west o/s	NULL	1	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Temporary	18-Jun-2014	Priority 1
530303	22-Jul-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 Upper Rich West o/s no 236 A205 Upper	NULL	2M	Footways And Cycle Tracks	Pothole	Permanent	19-Aug-2014	28 Day Defect
530302	22-Jul-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 Upper Rich West @ Sheen Rd A205 Upper	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	19-Aug-2014	28 Day Defect
530304	22-Jul-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 Upper Rich West o/s PH opp 333 A205 Up	NULL	2M	Footways And Cycle Tracks	Slab cracking	Permanent	19-Aug-2014	28 Day Defect
530305	22-Jul-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 Upper Rich West jct Rich park Rd A205	NULL	1	Footways And Cycle Tracks	Loose/rocking	Permanent	19-Aug-2014	Priority 1
530305	22-Jul-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 Upper Rich West jct Rich park Rd A205	NULL	1	Footways And Cycle Tracks	Loose/rocking	Temporary	23-Jul-2014	Priority 1

534074	19-Aug-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper richmond rd w. os 180 A205 upper	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	16-Sep-2014	28 Day Defect
534147	19-Aug-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper r.mond rd w. jct grosve	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	16-Sep-2014	28 Day Defect
538856	19-Sep-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road West O/S No.179	Make safe broken zebra crossing post. (T54325)	1	Post Defect	Damaged/Deformed	Permanent	17-Oct-2014	Priority 1
538856	19-Sep-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road West O/S No.179	Make safe broken zebra crossing post. (T54325)	1	Post Defect	Damaged/Deformed	Temporary	20-Sep-2014	Priority 1
539334	23-Sep-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper richmond rd west os 254 A205 upp	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	21-Oct-2014	28 Day Defect
539335	23-Sep-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper richmond rd west os 122 A205 upp	NULL	1	Footways And Cycle Tracks	Other	Permanent	21-Oct-2014	Priority 1
539335	23-Sep-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper richmond rd west os 122 A205 upp	NULL	1	Footways And Cycle Tracks	Other	Temporary	24-Sep-2014	Priority 1
539391	23-Sep-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper r.mond rd w. os 52	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	21-Oct-2014	28 Day Defect
539392	23-Sep-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper r.mond rd west opp 48	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	21-Oct-2014	28 Day Defect
539393	23-Sep-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper r.mond rd west os 207	NULL	2M	Footways And Cycle Tracks	Other	Permanent	21-Oct-2014	28 Day Defect
539394	23-Sep-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upp r.mond rd west os 311	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	21-Oct-2014	28 Day Defect
539909	25-Sep-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road West O/S 84-88	Sectioned of Paving Slabs cracked	1	Footways And Cycle Tracks	Cracking	Permanent	23-Oct-2014	Priority 1
539909	25-Sep-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road West O/S 84-88	Sectioned of Paving Slabs cracked	1	Footways And Cycle Tracks	Cracking	Temporary	26-Sep-2014	Priority 1
539971	25-Sep-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road West O/S Tanning Shop	Trip Hazard	1E	Footways And Cycle Tracks	Loose/rocking	Permanent	23-Oct-2014	Priority 1 (ECO)
540946	02-Oct-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road west o/s 84-88	Make safe rocking slab causing trip hazard (T54589)	1E	Footways And Cycle Tracks	Slab cracking	Permanent	30-Oct-2014	Priority 1 (ECO)
540946	02-Oct-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road west o/s 84-88	Make safe rocking slab causing trip hazard (T54589)	1E	Footways And Cycle Tracks	Slab cracking	Temporary	03-Oct-2014	Priority 1 (ECO)
543458	17-Oct-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	Upper Richmond Road from the junction with Grosvenor Gardens (o/s 78 Richmond Road ) to outside 84 Upper Richmond Road	paving slabs change to modular paving with block edging to modular with block edging matching the existing footway	2M	Footways And Cycle Tracks	Slab cracking	Permanent	14-Nov-2014	28 Day Defect
543960	21-Oct-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 Upper Richmond West W/B opp Lewin Rd A	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Nov-2014	28 Day Defect
543961	21-Oct-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 Upper Richmond West E/B outside no 210	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Nov-2014	28 Day Defect

543962	21-Oct-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 Upper Richmond West E/B opp Palewell P	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Nov-2014	28 Day Defect
543965	21-Oct-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 Upper Richmond West E/B outside no 180	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Nov-2014	28 Day Defect
545461	30-Oct-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205, Upper Richmond Road West j.n Sheen Lane	Bell bollard damaged and some bricks on c/w	1E	Post Defect	Damaged/Deformed	Permanent	27-Nov-2014	Priority 1 (ECO)
545461	30-Oct-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205, Upper Richmond Road West j.n Sheen Lane	Bell bollard damaged and some bricks on c/w	1E	Post Defect	Damaged/Deformed	Temporary	31-Oct-2014	Priority 1 (ECO)
546204	05-Nov-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond road West jnc east sheen lane	2 areas of footway flooding	1	Footways And Cycle Tracks	Other	Permanent	06-Nov-2014	Priority 1
548381	18-Nov-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 u rrd west o/s 169 A205 u rrd west o/s	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	16-Dec-2014	28 Day Defect
548384	18-Nov-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 u rrd west opp 126 A205 u rrd west opp	NULL	2H	Footways And Cycle Tracks	Cracking around ironwork	Permanent	25-Nov-2014	7 Day Defect
550938	02-Dec-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road at the junction of Kings Road	Belisha still lying on pavement since a traffic accident in September,	1	Post Defect	Accident damage	Permanent	30-Dec-2014	Priority 1
550938	02-Dec-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road at the junction of Kings Road	Belisha still lying on pavement since a traffic accident in September,	1	Post Defect	Accident damage	Temporary	03-Dec-2014	Priority 1
553855	22-Dec-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper r.mond rd w. os118 opp gordon av	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	19-Jan-2015	28 Day Defect
554303	27-Dec-2014	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road West o/s 251	Large Metal frame o/s need removing.	1E	Footways And Cycle Tracks	Other	Permanent	24-Jan-2015	Priority 1 (ECO)
562513	17-Feb-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Up Richmond Rd West o/s 72	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	17-Mar-2015	28 Day Defect
567157	17-Mar-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper r.mond rd w. jct wallorton gdns	NULL	1	Post Defect	Accident damage	Permanent	14-Apr-2015	Priority 1
567157	17-Mar-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper r.mond rd w. jct wallorton gdns	NULL	1	Post Defect	Accident damage	Temporary	18-Mar-2015	Priority 1
570169	08-Apr-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Rd West o/s 214	rocking slab	1E	Footways And Cycle Tracks	Loose/rocking	Permanent	06-May-2015	Priority 1 (ECO)
570619	10-Apr-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205, Upper Richmond Road West o/s 220	Make safe location with temp pgrs	1	Footways And Cycle Tracks	Other	Permanent	11-Apr-2015	Priority 1
570793	13-Apr-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road West jnc Sheen Lane	2 loose tactiles on footway	1	Footways And Cycle Tracks	Loose/rocking	Permanent	14-Apr-2015	Priority 1
570791	13-Apr-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205, Upper Richmond Road West o/s 327	missing utilitys cover on f.w	1	Footways And Cycle Tracks	Collapsed	Temporary	14-Apr-2015	Priority 1
571380	16-Apr-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road West jnc Paynesfield Rd	loose kerb	1	Footways And Cycle Tracks	Kerb/channel block alignment	Permanent	17-Apr-2015	Priority 1
571970	21-Apr-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper r.mond rd w. jct sheen lane os 2	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	19-May-2015	28 Day Defect

571972	21-Apr-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper r.mond rd w.jct r.mond pk rd os2	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	19-May-2015	28 Day Defect
572339	23-Apr-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 upper richmond road west	loose utility cover	1	Footways And Cycle Tracks	Loose/rocking	Permanent	24-Apr-2015	Priority 1
572359	23-Apr-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Sheen Lane o/s 137A WB (on Jctn with upper Richmond Road West)	Loose Slab/Make safe.	1	Footways And Cycle Tracks	Loose/rocking	Permanent	24-Apr-2015	Priority 1
574773	11-May-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond RD Sutherland RD	Install New Sheild On Column 87	2M	Post Defect	Missing	Permanent	08-Jun-2015	28 Day Defect
579910	16-Jun-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 upper rich rd west o/s 180	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	14-Jul-2015	28 Day Defect
579911	16-Jun-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 upper rich rd west o/s 170	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	14-Jul-2015	28 Day Defect
579913	16-Jun-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 upper rich rd west o/s 150	NULL	1	Footways And Cycle Tracks	Cracking around ironwork	Permanent	14-Jul-2015	Priority 1
579913	16-Jun-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 upper rich rd west o/s 150	NULL	1	Footways And Cycle Tracks	Cracking around ironwork	Temporary	17-Jun-2015	Priority 1
579914	16-Jun-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 upper rich rd W opp 54	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	14-Jul-2015	28 Day Defect
579916	16-Jun-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 upper rich road west o/s 323	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	14-Jul-2015	28 Day Defect
579915	16-Jun-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 upper rich rd W jct hertford ave	NULL	1	Safety Fences: Metal/Concrete	Accident damage	Permanent	14-Jul-2015	Priority 1
579915	16-Jun-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 upper rich rd W jct hertford ave	NULL	1	Safety Fences: Metal/Concrete	Accident damage	Temporary	17-Jun-2015	Priority 1
585189	21-Jul-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 up rich rd W o/s 203	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Aug-2015	28 Day Defect
585192	21-Jul-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 up rich rd W jct hertford ave	NULL	2M	Footways And Cycle Tracks	Accident damage	Permanent	18-Aug-2015	28 Day Defect
585194	21-Jul-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 up rich rd W o/s 172-176	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Aug-2015	28 Day Defect
586282	28-Jul-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road West j/w Priest Bridge	Missing KLB	1	Safety Bollards: Face/Structure/ Fixings	Missing	Permanent	29-Jul-2015	Priority 1
589519	18-Aug-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 up rich rd west os 313 WB A205 up rich	uneven ASP req reset 3s SLPF Slab profile : uneven/trips/gap ( XY:520692.9 175419.2 ) ( Ref:LSO600178 ) LSO600178_D SCN2968.JPG LSO600178_D SCN2969.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	15-Sep-2015	28 Day Defect

589520	18-Aug-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 up rich rd west opp the willoughbys wb	fw req 6mm dbm 3s \$ ACCD Accident damage ( XY:521443.6 175466.8 ) ( Ref:LSO600179 ) LSO600179_D SCN2970.JPG LSO600179_D SCN2971.JPG	2M	Footways And Cycle Tracks	Accident damage	Permanent	15-Sep-2015	28 Day Defect
589530	18-Aug-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 up rich rd W jct palewell park wb	2x sites req reset blocks 3s BKPF Block profile ( XY:520707.3 175419.3 ) ( Ref:LSO403011 ) LSO403011_D SCN4751.JPG LSO403011_D SCN4752.JPG	2M	Footways And Cycle Tracks	Block profile	Permanent	15-Sep-2015	28 Day Defect
592387	08-Sep-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road West j/w Thornton Ave	Footway Loose and broken	1	Footways And Cycle Tracks	Kerb/channel block alignment	Permanent	06-Oct-2015	Priority 1
592387	08-Sep-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road West j/w Thornton Ave	Footway Loose and broken	1	Footways And Cycle Tracks	Kerb/channel block alignment	Temporary	09-Sep-2015	Priority 1
594494	22-Sep-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 up rich road west eb os 172 A205 up ri	FWMH REQ c30 3S CKIR Cracking around ironwork ( XY:520788.3 175446.7 ) ( Ref:LSO600304 ) LSO600304_D SCN3484.JPG LSO600304_D SCN3485.JPG	2M	Footways And Cycle Tracks	Cracking around ironwork	Permanent	20-Oct-2015	28 Day Defect
595223	24-Sep-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper richmond rd west jw thornton rd	TM left behind to be cleared	1	Footways And Cycle Tracks	Other	Permanent	25-Sep-2015	Priority 1
599386	20-Oct-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 upper richmond road W o/s 169	req rst mods/blocks 3s \$ SLPF Slab profile : uneven/trips/gap ( XY:521141.5 175450.1 ) ( Ref:LSO403342 ) LSO403342_D SCN0802.JPG LSO403342_D SCN0803.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	17-Nov-2015	28 Day Defect
603217	11-Nov-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road West j/w Sheen Lane	Removal of Sand Bags from traffic island	1	Footways And Cycle Tracks	Other	Permanent	12-Nov-2015	Priority 1
604243	17-Nov-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper richmond rd west os 120 EB A205	depressed blocks req rst \$@3s SLPF Slab profile : uneven/trips/gap ( XY:521043.7 175455 ) ( Ref:LSO204401 ) LSO204401_D SCI0076.JPG LSO204401_D SCI0077.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	15-Dec-2015	28 Day Defect
604241	17-Nov-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper richmond rd west os 218 A205 upp	T61147.tree stump req ms 3s OTHR Other ( XY:520618.6 175421.8 ) ( Ref:LSO204400 ) LSO204400_D SCI0074.JPG LSO204400_D SCI0075.JPG	1	Footways And Cycle Tracks	Other	Permanent	15-Dec-2015	Priority 1

604241	17-Nov-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper richmond rd west os 218 A205 upp	T61147.tree stump req ms 3s OTHR Other ( XY:520618.6 175421.8 ) ( Ref:LSO204400 ) LSO204400_D SCI0074.JPG LSO204400_D SCI0075.JPG	1	Footways And Cycle Tracks	Other	Temporary	18-Nov-2015	Priority 1
608228	14-Dec-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205, Upper Richmond Road West Junction with Shottfield Avenue NB side	Lift the Kerbstones and raise the carriageway to facilitate drainage of ponding then re-bed the kerbstones so they are no longer sunken with the carriageway.	2M	Footways And Cycle Tracks	Kerb/channel block alignment	Permanent	11-Jan-2016	28 Day Defect
608243	14-Dec-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205, Upper Richmond Road West Junction with Shottfield Avenue SB side	Lift the Kerbstones and raise the carriageway to facilitate drainage of ponding then re-bed the kerbstones so they are no longer sunken with the carriageway.	2M	Footways And Cycle Tracks	Kerb/channel block alignment	Permanent	11-Jan-2016	28 Day Defect
608428	15-Dec-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205, Upper Richmond Road West Junction with Hertford Avenue, NB side of Hertford Avenue	Lift the Kerbstones and raise the carriageway to facilitate drainage of ponding then re-bed the kerbstones so they are no longer sunken with the carriageway	2M	Footways And Cycle Tracks	Kerb/channel block alignment	Permanent	12-Jan-2016	28 Day Defect
608630	15-Dec-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 upper rich rd W o/s 309	2x sites req rst slabs/kerbs 3s \$ SLPF Slab profile : uneven/trips/gap ( XY:520726.4 175424.9 ) ( Ref:LSO403544 ) LSO403544_D SCN1363.JPG LSO403544_D SCN1364.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	12-Jan-2016	28 Day Defect
608626	15-Dec-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 up rich rd W opp jct priests bridge	fw uneven req rst mods 3s SLPF Slab profile : uneven/trips/gap ( XY:521373.1 175463.7 ) ( Ref:LSO403533 ) LSO403533_D SCN1318.JPG LSO403533_D SCN1319.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	12-Jan-2016	28 Day Defect
608627	15-Dec-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 up rich rd W jct grosvenor gdns	req new fillet 3s CKIR Cracking around ironwork ( XY:521202.3 175467.3 ) ( Ref:LSO403534 ) LSO403534_D SCN1323.JPG LSO403534_D SCN1324.JPG	2H	Footways And Cycle Tracks	Cracking around ironwork	Permanent	22-Dec-2015	7 Day Defect
608615	15-Dec-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRD west opp preist bridge A205 URRD	req 6mm 3s \$@ BECK Blacktop : extensive cracking ( XY:521401.9 175480.4 ) ( Ref:LSO106773 ) LSO106773_D SCN1321.JPG LSO106773_D SCN1322.JPG	2M	Footways And Cycle Tracks	Blacktop : extensive cracking	Permanent	12-Jan-2016	28 Day Defect



608617	15-Dec-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west o/s 297 fairlawn mansions A2	rst mods 3S SLPF Slab profile : uneven/trips/gap ( XY:520759.1 175428.4 ) ( Ref:LSO106783 ) LSO106783_D SCN1365.JPG LSO106783_D SCN1366.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	12-Jan-2016	28 Day Defect
608482	15-Dec-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205, Upper Richmond Road West Junction with Hertford Avenue, SB corner of Hertford Avenue.	Pooling at Junction	2M	Footways And Cycle Tracks	Kerb/channel block alignment	Permanent	12-Jan-2016	28 Day Defect
608484	15-Dec-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205, Upper Richmond Road West Junction with Grosvenor Gardens, NB side of Grosvenor Gardens.	Pooling at Junction	2M	Footways And Cycle Tracks	Kerb/channel block alignment	Permanent	12-Jan-2016	28 Day Defect
608488	15-Dec-2015	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205, Upper Richmond Road West Junction with Grosvenor Gardens, SB side of Grosvenor Gardens.	Pooling at Junction	2M	Footways And Cycle Tracks	Kerb/channel block alignment	Permanent	12-Jan-2016	28 Day Defect
613092	19-Jan-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper r.mond rd w. WB os 205 A205 uppe	uneven blocks req rst\$ @ 4D SLPF Slab profile : uneven/trips/gap ( XY:520874.1 175443.3 ) ( Ref:LSO204695 ) LSO204695_D SCI0159.JPG LSO204695_D SCI0160.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	16-Feb-2016	28 Day Defect
613093	19-Jan-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper r.mond rd w. WB os 257 A205 uppe	uneven ASP req rst 3D SLPF Slab profile : uneven/trips/gap ( XY:520782.3 175431.3 ) ( Ref:LSO204696 ) LSO204696_D SCI0161.JPG LSO204696_D SCI0164.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	16-Feb-2016	28 Day Defect
615329	01-Feb-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205,Upper Richmond Road West, jw Sutherland Gardens	Flyposting	1	Footways And Cycle Tracks	Other	Permanent	02-Feb-2016	Priority 1
616900	08-Feb-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper R R West o/s 218	Void in f/w whre tree used to be	1	Footways And Cycle Tracks	Collapsed	Permanent	07-Mar-2016	Priority 1
616900	08-Feb-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper R R West o/s 218	Void in f/w whre tree used to be	1	Footways And Cycle Tracks	Collapsed	Temporary	09-Feb-2016	Priority 1
618442	16-Feb-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW jn priest bridge sb fw A205 URRW	rst asp point up 3D CKIR Cracking around ironwork ( XY:521410.7 175481 ) ( Ref:LSO107184 ) LSO107184_D SCN2809.JPG LSO107184_D SCN2810.JPG	2M	Footways And Cycle Tracks	Cracking around ironwork	Permanent	15-Mar-2016	28 Day Defect

618437	16-Feb-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW o/s 60 sb fw A205 URRW o/s 60 sb	rst ASP cvr 3D \$@ SLPF Slab profile : uneven/trips/gap ( XY:521260.4 175470.3 ) ( Ref:LSO107185 ) LSO107185_D SCN2811.JPG LSO107185_D SCN2812.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	15-Mar-2016	28 Day Defect
618438	16-Feb-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW o/s 68 sb fw A205 URRW o/s 68 s	RST mods blocks 3D \$@ SLPF Slab profile : uneven/trips/gap ( XY:521246.9 175469.1 ) ( Ref:LSO107186 ) LSO107186_D SCN2813.JPG LSO107186_D SCN2814.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	15-Mar-2016	28 Day Defect
618439	16-Feb-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW o/s 74 sb fw A205 URRW o/s 74 s	RST mods 3D @ SLPF Slab profile : uneven/trips/gap ( XY:521222.8 175467.7 ) ( Ref:LSO107187 ) LSO107187_D SCN2815.JPG LSO107187_D SCN2816.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	15-Mar-2016	28 Day Defect
618441	16-Feb-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW jn sheen lane sb fw A205 URRW jn	3 site kerbs mods 3N SLPF Slab profile : uneven/trips/gap ( XY:520511.1 175407.3 ) ( Ref:LSO107190 ) LSO107190_D SCN2824.JPG LSO107190_D SCN2825.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	15-Mar-2016	28 Day Defect
618443	16-Feb-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW o/s 196 sb fw A205 URRW o/s 196	rst mods blocks 3D SLPF Slab profile : uneven/trips/gap ( XY:520711.4 175437.6 ) ( Ref:LSO107189 ) LSO107189_D SCN2822.JPG LSO107189_D SCN2823.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	15-Mar-2016	28 Day Defect
618445	16-Feb-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRD W o./S 197 nb cw A205 URRD W o./	RST fw cvr x2 3D BKPF Block profile ( XY:520897.1 175444.5 ) ( Ref:LSO107202 ) LSO107202_D SCN2848.JPG LSO107202_D SCN2849.JPG	2M	Footways And Cycle Tracks	Block profile	Permanent	15-Mar-2016	28 Day Defect
622582	14-Mar-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper rich rd w os 172 eb A205 upper r	cracking around cover req c30 3d CKIR Cracking around ironwork ( XY:520794.5 175446.7 ) ( Ref:LSO601332 ) LSO601332_D SCN5550.JPG LSO601332_D SCN5551.JPG	2M	Footways And Cycle Tracks	Cracking around ironwork	Permanent	11-Apr-2016	28 Day Defect
622581	14-Mar-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper rich rd w os 172 eb A205 upper r	rocking mods req reset 3d SROK Slab rocking ( XY:520797.5 175447.6 ) ( Ref:LSO601331 ) LSO601331_D SCN5548.JPG LSO601331_D SCN5549.JPG	2M	Footways And Cycle Tracks	Slab rocking	Permanent	11-Apr-2016	28 Day Defect

622648	14-Mar-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper rich rd w os 172 eb	NULL	2M	Footways And Cycle Tracks	Slab rocking	Permanent	11-Apr-2016	28 Day Defect
622649	14-Mar-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper rich rd w os 172 eb	NULL	2M	Footways And Cycle Tracks	Cracking around ironwork	Permanent	11-Apr-2016	28 Day Defect
622650	14-Mar-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper rich rd w jnc kings roa	NULL	2M	Footways And Cycle Tracks	Loose/rocking	Permanent	11-Apr-2016	28 Day Defect
622651	14-Mar-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper rich rd w jnc grosvenor	NULL	2M	Footways And Cycle Tracks	Block profile	Permanent	11-Apr-2016	28 Day Defect
629522	19-Apr-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west sb fw o/s 361 A205 urrd west	rst block 3D BKPF Block profile ( XY:520532.8 175398.4 ) ( Ref:LSO107681 ) LSO107681_D SCI0019.JPG LSO107681_D SCI0020.JPG	2M	Footways And Cycle Tracks	Block profile	Permanent	17-May-2016	28 Day Defect
629517	19-Apr-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west nb cw o/s 176-172 A205 urrd	rst mods blocks point up 3D CKIR Cracking around ironwork ( XY:520795.8 175448.7 ) ( Ref:LSO107665 ) LSO107665_D SCI0001.JPG LSO107665_D SCI0002.JPG	2M	Footways And Cycle Tracks	Cracking around ironwork	Permanent	17-May-2016	28 Day Defect
634533	17-May-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper rich rd west opp portman av wb A	missing fillet req new 3d CRCK Cracking ( XY:520771.9 175429.1 ) ( Ref:LSO205001 ) LSO205001_D SCN6343.JPG LSO205001_D SCN6344.JPG	2M	Footways And Cycle Tracks	Cracking	Permanent	14-Jun-2016	28 Day Defect
634683	17-May-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 up rich rd W o/s 349	fw uneven req rst mods 3d SLPF Slab profile : uneven/trips/gap ( XY:520571.7 175403.9 ) ( Ref:LSO403621 ) LSO403621_D SCN1816.JPG LSO403621_D SCN1817.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	14-Jun-2016	28 Day Defect
634684	17-May-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 up rich rd W o/s 275 sheengate mans	T64329 req new C30 3d@ CKIR Cracking around ironwork ( XY:520758.7 175429.4 ) ( Ref:LSO403622 )	1	Footways And Cycle Tracks	Cracking around ironwork	Permanent	14-Jun-2016	Priority 1
634684	17-May-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 up rich rd W o/s 275 sheengate mans	T64329 req new C30 3d@ CKIR Cracking around ironwork ( XY:520758.7 175429.4 ) ( Ref:LSO403622 )	1	Footways And Cycle Tracks	Cracking around ironwork	Temporary	18-May-2016	Priority 1
634717	17-May-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper rich rd west opp portma	NULL	2M	Footways And Cycle Tracks	Cracking	Permanent	14-Jun-2016	28 Day Defect
634718	17-May-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper rich rd west os 197 wb	NULL	1	Footways And Cycle Tracks	Accident damage	Permanent	14-Jun-2016	Priority 1
634718	17-May-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper rich rd west os 197 wb	NULL	1	Footways And Cycle Tracks	Accident damage	Temporary	18-May-2016	Priority 1

634719	17-May-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 up rich rd west os 176 eb	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	14-Jun-2016	28 Day Defect
640602	21-Jun-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urr rd west jn shotfield rd nb fw A205	rst kerbs mods blocks 3D BECK Blacktop : extensive cracking ( XY:521107.5 175447.4 ) ( Ref:LSO108205 ) LSO108205_D SCN0388.JPG LSO108205_D SCN0389.JPG	2M	Footways And Cycle Tracks	Blacktop : extensive cracking	Permanent	19-Jul-2016	28 Day Defect
640606	21-Jun-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urr rd west jn grosvenor gds sb fw A20	rst mods blocks 3D \$ SLPF Slab profile : uneven/trips/gap ( XY:521216.8 175466.9 ) ( Ref:LSO108209 ) LSO108209_D SCN0398.JPG LSO108209_D SCN0399.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	19-Jul-2016	28 Day Defect
640621	21-Jun-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urr rd west jn grosvenor gdns eb A	uneven blocks req reset 3d BKPF Block profile ( XY:521203.2 175466.4 ) ( Ref:LSO205205 ) LSO205205_D SCN6849.JPG LSO205205_D SCN6850.JPG	2M	Footways And Cycle Tracks	Block profile	Permanent	19-Jul-2016	28 Day Defect
640618	21-Jun-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper rich rd west opp 44 wb A205 uppe	uneven mods blocks req reset 3d SLPF Slab profile : uneven/trips/gap ( XY:521344.4 175462.4 ) ( Ref:LSO205202 ) LSO205202_D SCN6843.JPG LSO205202_D SCN6844.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	19-Jul-2016	28 Day Defect
640620	21-Jun-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 up rich rd west jn sutherland gdns eb	uneven mods blocks req reset 3n SLPF Slab profile : uneven/trips/gap ( XY:521300.6 175471.9 ) ( Ref:LSO205204 ) LSO205204_D SCN6847.JPG LSO205204_D SCN6848.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	19-Jul-2016	28 Day Defect
640622	21-Jun-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 up rich rd west os 94 eb A205 up rich	uneven mods req reset 3n \$ SLPF Slab profile : uneven/trips/gap ( XY:521148.3 175462.8 ) ( Ref:LSO205206 ) LSO205206_D SCN6851.JPG LSO205206_D SCN6852.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	19-Jul-2016	28 Day Defect
646243	21-Jul-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 up rich rd os 78 eb A205 up rich rd os	uneven mods blocks req reset 3n \$ SLPF Slab profile : uneven/trips/gap ( XY:521196.3 175465.9 ) ( Ref:LSO205320 ) LSO205320_D SCN7149.JPG LSO205320_D SCN7150.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Aug-2016	28 Day Defect

646242	21-Jul-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 up rich rd jn grosvenor gdns eb A205 u	cover req new fillet 3d CKIR Cracking around ironwork ( XY:521202.6 175466.6 ) ( Ref:LSO205319 ) LSO205319_D SCN7147.JPG LSO205319_D SCN7148.JPG	2M	Footways And Cycle Tracks	Cracking around ironwork	Permanent	18-Aug-2016	28 Day Defect
650708	16-Aug-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 richmond pk rd jn urrd w nb A205 richm	T65561ms rst st furn 3D ACCD Accident damage ( XY:520607.3 175410 ) ( Ref:LSO108519 ) LSO108519_D SCN1310.JPG LSO108519_D SCN1311.JPG	1	Post Defect	Accident damage	Permanent	13-Sep-2016	Priority 1
650708	16-Aug-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 richmond pk rd jn urrd w nb A205 richm	T65561ms rst st furn 3D ACCD Accident damage ( XY:520607.3 175410 ) ( Ref:LSO108519 ) LSO108519_D SCN1310.JPG LSO108519_D SCN1311.JPG	1	Post Defect	Accident damage	Temporary	17-Aug-2016	Priority 1
654348	12-Sep-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road West O/S No.62, near j/w Sutherland Garden	Damaged Thames water cover on footway (Refer to Sec 81)	1	Footways And Cycle Tracks	Wear	Temporary	13-Sep-2016	Priority 1
655528	20-Sep-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 Upper Rich rd West o/s 216 Nb A205 Upp	req relay mods 3D SLPF Slab profile : uneven/trips/gap ( XY:520628.7 175423.8 ) ( Ref:LSO350427 ) LSO350427_D SCI0001.JPG LSO350427_D SCI0002.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Oct-2016	28 Day Defect
655533	20-Sep-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 Upp Rich rd W o/s 299-309 Sb A205 Upp	req relay mods 3D SLPF Slab profile : uneven/trips/gap ( XY:520729.5 175425.4 ) ( Ref:LSO350432 ) LSO350432_D SCI0001.JPG LSO350432_D SCI0002.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Oct-2016	28 Day Defect
659427	12-Oct-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 URRW o/s 62 Opp East Sheen Primary School.	Missing TW Box C in f/w	1E	Footways And Cycle Tracks	Wear	Temporary	13-Oct-2016	Priority 1 (ECO)
665264	22-Nov-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd W sb fw o/s 128-130 A205 urrd W	rst mods blocks 3D @ \$ STWT Standing water ( XY:521024.6 175455 ) ( Ref:LSO109078 ) LSO109078_D SCN0952.JPG LSO109078_D SCN0953.JPG	2M	Footways And Cycle Tracks	Standing Water	Permanent	20-Dec-2016	28 Day Defect
669222	20-Dec-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 up rich rd w opp avenue gardens wb A20	uneven mods req reset 3n\$ SLPF Slab profile : uneven/trips/gap ( XY:521081.3 175446 ) ( Ref:LSO205921 ) LSO205921_D SCI0003.JPG LSO205921_D SCI0004.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	17-Jan-2017	28 Day Defect

669729	28-Dec-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road West	Damaged metal bollard on footway. (T67093)	1E	Post Defect	Damaged/Deformed	Permanent	25-Jan-2017	Priority 1 (ECO)
669729	28-Dec-2016	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road West	Damaged metal bollard on footway. (T67093)	1E	Post Defect	Damaged/Deformed	Temporary	29-Dec-2016	Priority 1 (ECO)
673137	24-Jan-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 up rich rd w os 170 eb A205 up rich rd	uneven mods blocks req reset 3d SLPF Slab profile : uneven/trips/gap ( XY:520808.2 175453 ) ( Ref:LSO206093 ) LSO206093_D SCI0005.JPG LSO206093_D SCI0006.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	21-Feb-2017	28 Day Defect
673138	24-Jan-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 up rich rd w os 176 eb A205 up rich rd	uneven mods blocks req reset 3n SLPF Slab profile : uneven/trips/gap ( XY:520782 175448.3 ) ( Ref:LSO206094 ) LSO206094_D SCI0007.JPG LSO206094_D SCI0008.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	21-Feb-2017	28 Day Defect
673139	24-Jan-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 up rich rd w os 238 eb A205 up rich rd	mods req reset 3n\$ SLPF Slab profile : uneven/trips/gap ( XY:520555.2 175413.3 ) ( Ref:LSO206095 ) LSO206095_D SCI0009.JPG LSO206095_D SCI0010.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	21-Feb-2017	28 Day Defect
673169	24-Jan-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 up rich rd west eb o/s 96	req rst mods 3d SLPF Slab profile : uneven/trips/gap ( XY:521140.1 175462.3 ) ( Ref:LSO404653 ) LSO404653_D SCN5013.JPG LSO404653_D SCN5014.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	21-Feb-2017	28 Day Defect
673170	24-Jan-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 up rich rd west eb o/s 170	req rst mods 3d SLPF Slab profile : uneven/trips/gap ( XY:520811.5 175453.2 ) ( Ref:LSO404654 ) LSO404654_D SCN5016.JPG LSO404654_D SCN5017.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	21-Feb-2017	28 Day Defect
673171	24-Jan-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 up rich rd west eb o/s 178	req rst mods/blocks 3d SLPF Slab profile : uneven/trips/gap ( XY:520782.6 175447.4 ) ( Ref:LSO404655 ) LSO404655_D SCN5019.JPG LSO404655_D SCN5020.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	21-Feb-2017	28 Day Defect
678054	21-Feb-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 upper rich rd W eb o/s 122	req new aco drain 3n\$ CKIR Cracking around ironwork ( XY:521038.1 175454.5 ) ( Ref:LSO404775 ) LSO404775_D SCN5295.JPG LSO404775_D SCN5296.JPG	2M	Footways And Cycle Tracks	Cracking around ironwork	Permanent	21-Mar-2017	28 Day Defect

683210	21-Mar-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 172-176 eb A205 URRW os 172-1	reset mods blocks 3D SLPF Slab profile : uneven/trips/gap ( XY:520800.8 175448.6 ) ( Ref:LSO309636 ) LSO309636_D SCI0004.JPG LSO309636_D SCI0005.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Apr-2017	28 Day Defect
687539	19-Apr-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west o/s 240 sb fw A205 urrd west	rst mods cvr 3D @ SLPF Slab profile : uneven/trips/gap ( XY:520549.8 175412.5 ) ( Ref:LSO106592 ) LSO106592_D SCN1061.JPG LSO106592_D SCN1062.JPG LSO106592_D SCN4966.JPG LSO106592_D SCN4967.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	17-May-2017	28 Day Defect
687554	19-Apr-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd w nb fw o/s 333	NULL	1	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	17-May-2017	Priority 1
687554	19-Apr-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd w nb fw o/s 333	NULL	1	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Temporary	20-Apr-2017	Priority 1
691878	16-May-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW 238 sb A205 URRW 238 sb	reset mods blocks 3N @ SLPF Slab profile : uneven/trips/gap ( XY:520555 175412.9 ) ( Ref:LSO309943 ) LSO309943_D SCI0026.JPG LSO309943_D SCI0027.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	13-Jun-2017	28 Day Defect
691874	16-May-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 up rich rd w os 321 wb A205 up rich rd	uneven mods blocks req reset 3n SLPF Slab profile : uneven/trips/gap ( XY:520668 175416.6 ) ( Ref:LSO206669 ) LSO206669_D SCI0006.JPG LSO206669_D SCI0007.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	13-Jun-2017	28 Day Defect
697514	20-Jun-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 172-176 eb A205 URRW os 172-17	reset mods pointing 3D SLPF Slab profile : uneven/trips/gap ( XY:520798 175447.7 ) ( Ref:LSO310133 ) LSO310133_D SCI0005.JPG LSO310133_D SCI0006.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Jul-2017	28 Day Defect
697515	20-Jun-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW jc grovsenor ave eb A205 URRW jc	T69681 reset fw mods 3D SLPF Slab profile : uneven/trips/gap ( XY:521140.7 175461.8 ) ( Ref:LSO310134 ) LSO310134_D SCI0003.JPG LSO310134_D SCI0004.JPG	1	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Jul-2017	Priority 1

697515	20-Jun-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW jc grovsenor ave eb A205 URRW jc	T69681 reset fw mods 3D SLPF Slab profile : uneven/trips/gap ( XY:521140.7 175461.8 ) ( Ref:LSO310134 ) LSO310134_D SCI0003.JPG LSO310134_D SCI0004.JPG	1	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Temporary	21-Jun-2017	Priority 1
701710	18-Jul-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW jc sutherlands garden eb A205 URR	resetblocks new pointing 3D BKPF Block profile ( XY:521301.8 175472.4 ) ( Ref:LSO310369 ) LSO310369_D SCI0001.JPG LSO310369_D SCI0002.JPG	2M	Footways And Cycle Tracks	Block profile	Permanent	15-Aug-2017	28 Day Defect
704345	04-Aug-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 URRW start of Priests Bridge Road	Clear Graffiti on illuminated no entry bollard ( 2 eyes and a smile )	1	Safety Bollards: Face/Structure/ Fixings	Graffiti General	Permanent	01-Sep-2017	Priority 1
704345	04-Aug-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 URRW start of Priests Bridge Road	Clear Graffiti on illuminated no entry bollard ( 2 eyes and a smile )	1	Safety Bollards: Face/Structure/ Fixings	Graffiti General	Temporary	05-Aug-2017	Priority 1
707272	22-Aug-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 316a wb A205 URRW os 316a wb	reset block 3D BKPF Block profile ( XY:520531.8 175398.1 ) ( Ref:LSO310609 ) LSO310609_D SCI0011.JPG LSO310609_D SCI0012.JPG	2M	Footways And Cycle Tracks	Block profile	Permanent	19-Sep-2017	28 Day Defect
707274	22-Aug-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW oa 180 eb A205 URRW oa 180 eb	reset mods blocks 3D SLPF Slab profile : uneven/trips/gap ( XY:520772.8 175445.9 ) ( Ref:LSO310623 ) LSO310623_D SCI0055.JPG LSO310623_D SCI0056.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	19-Sep-2017	28 Day Defect
707275	22-Aug-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW oa 106 eb A205 URRW oa 106 eb	reset mods blocks 3D \$ SLPF Slab profile : uneven/trips/gap ( XY:521100.4 175459.1 ) ( Ref:LSO310624 ) LSO310624_D SCI0057.JPG LSO310624_D SCI0058.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	19-Sep-2017	28 Day Defect
707277	22-Aug-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 196 eb A205 URRW os 196 eb	T70391 reset sunken mods 3D SLPF Slab profile : uneven/trips/gap ( XY:520713.6 175436 ) ( Ref:LSO310628 ) LSO310628_D SCI0053.JPG LSO310628_D SCI0054.JPG	1	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	19-Sep-2017	Priority 1
707277	22-Aug-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 196 eb A205 URRW os 196 eb	T70391 reset sunken mods 3D SLPF Slab profile : uneven/trips/gap ( XY:520713.6 175436 ) ( Ref:LSO310628 ) LSO310628_D SCI0053.JPG LSO310628_D SCI0054.JPG	1	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Temporary	23-Aug-2017	Priority 1



711005	19-Sep-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west jn sutherland gds sb fw A	rst cvr 3D @ CKIR Cracking around ironwork ( XY:521285.8 175472.2 ) ( Ref:LSO110304 ) LSO110304_D SCN9346.JPG LSO110304_D SCN9347.JPG	2M	Footways And Cycle Tracks	Cracking around ironwork	Permanent	17-Oct-2017	28 Day Defect
711169	20-Sep-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road West o/s 170	fw Slabs broken	1E	Footways And Cycle Tracks	Slab cracking	Permanent	18-Oct-2017	Priority 1 (ECO)
711169	20-Sep-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road West o/s 170	fw Slabs broken	1E	Footways And Cycle Tracks	Slab cracking	Temporary	21-Sep-2017	Priority 1 (ECO)
715394	17-Oct-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 upper richmond road W eb o/s 244	req rst acco drain 3d CKIR Cracking around ironwork ( XY:520537.9 175410.2 ) ( Ref:LSO405990 ) LSO405990_D SCI0654.JPG LSO405990_D SCI0655.JPG	2M	Footways And Cycle Tracks	Cracking around ironwork	Permanent	14-Nov-2017	28 Day Defect
715393	17-Oct-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 upper richmond rd W eb o/s 238	req rst acco drain 3d CKIR Cracking around ironwork ( XY:520555.2 175413.5 ) ( Ref:LSO405989 ) LSO405989_D SCI0651.JPG LSO405989_D SCI0652.JPG	2M	Footways And Cycle Tracks	Cracking around ironwork	Permanent	14-Nov-2017	28 Day Defect
715389	17-Oct-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 upper rich rd west eb o/s 166-168	sunken req rst mods/blocks 3d SLPF Slab profile : uneven/trips/gap ( XY:520817 175455 ) ( Ref:LSO405985 ) LSO405985_D SCI0639.JPG LSO405985_D SCI0640.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	14-Nov-2017	28 Day Defect
715385	17-Oct-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 upper richmond rd west eb o/s 64	sunken req rst mods 3d SLPF Slab profile : uneven/trips/gap ( XY:521255.1 175469.8 ) ( Ref:LSO405981 ) LSO405981_D SCI0626.JPG LSO405981_D SCI0627.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	14-Nov-2017	28 Day Defect
715388	17-Oct-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 upper richmond rd west eb o/s 142	req rst rocking tactile 3d SROK Slab rocking ( XY:520950.5 175458.9 ) ( Ref:LSO405984 ) LSO405984_D SCI0636.JPG LSO405984_D SCI0637.JPG	2M	Footways And Cycle Tracks	Slab rocking	Permanent	14-Nov-2017	28 Day Defect
715391	17-Oct-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 upper richmond rd west eb o/s 190	req new mod 3d SLCK Slab cracking ( XY:520731 175440 ) ( Ref:LSO405987 ) LSO405987_D SCI0645.JPG LSO405987_D SCI0646.JPG	2M	Footways And Cycle Tracks	Slab cracking	Permanent	14-Nov-2017	28 Day Defect

715413	17-Oct-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 up rich rd west os 78 eb A205 up rich	overgrown req cut back 3d OVGV Overgrown by vegetation ( XY:521196.8 175466.3 ) ( Ref:LSO207478 ) LSO207478_D SCI0012.JPG LSO207478_D SCI0013.JPG	2M	Footways And Cycle Tracks	Overgrown by vegetation	Permanent	14-Nov-2017	28 Day Defect
715414	17-Oct-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 up rich road w os 130 eb A205 up rich	rocking slab req reset 3n\$ SLPF Slab profile : uneven/trips/gap ( XY:521007.4 175456.7 ) ( Ref:LSO207479 ) LSO207479_D SCI0014.JPG LSO207479_D SCI0015.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	14-Nov-2017	28 Day Defect
715415	17-Oct-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 up rich rd west jn portman av eb A205	bollard req reset 3n\$ COPT Physical condition of post ( XY:520751.7 175440 ) ( Ref:LSO207481 ) LSO207481_D SCI0018.JPG LSO207481_D SCI0019.JPG	2M	Post Defect	Physical condition of post	Permanent	14-Nov-2017	28 Day Defect
716818	24-Oct-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road West O/S No.236 - 244	Make safe loose gully covers causing trip hazard. (T71046)	1	Footways And Cycle Tracks	Other	Permanent	21-Nov-2017	Priority 1
716818	24-Oct-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road West O/S No.236 - 244	Make safe loose gully covers causing trip hazard. (T71046)	1	Footways And Cycle Tracks	Other	Temporary	25-Oct-2017	Priority 1
718527	06-Nov-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road West, Richmond JN Priest bridge	repair damaged PGR	1E	Safety Fences: Metal/Concrete	Damaged/deformed	Permanent	04-Dec-2017	Priority 1 (ECO)
718527	06-Nov-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road West, Richmond JN Priest bridge	repair damaged PGR	1E	Safety Fences: Metal/Concrete	Damaged/deformed	Temporary	07-Nov-2017	Priority 1 (ECO)
720963	21-Nov-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 up rich rd w os east sheen school wb A	cover req new fillet 3n\$ CKIR Cracking around ironwork ( XY:521285.3 175460.2 ) ( Ref:LSO207587 ) LSO207587_D SCI0001.JPG LSO207587_D SCI0002.JPG	2M	Footways And Cycle Tracks	Cracking around ironwork	Permanent	19-Dec-2017	28 Day Defect
720965	21-Nov-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 up rich rd w os 78 eb A205 up rich rd	reset mods blocks 3n\$ SLPF Slab profile : uneven/trips/gap ( XY:521196.6 175466.3 ) ( Ref:LSO207589 ) LSO207589_D SCI0005.JPG LSO207589_D SCI0006.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	19-Dec-2017	28 Day Defect
725385	19-Dec-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) @A205 UP RICH WEST RD	NULL	2H	Safety Bollards: Face/Structure/ Fixings	Lamp failure	Permanent	26-Dec-2017	7 Day Defect
725386	19-Dec-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) @A205 UP RICH WEST RD OP LP 96	NULL	2H	Safety Bollards: Face/Structure/ Fixings	Lamp failure	Permanent	26-Dec-2017	7 Day Defect

725479	19-Dec-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 up rich road west os 106-102 eb A205 u	mods blocks req reset 3n\$ SLPF Slab profile : uneven/trips/gap ( XY:521106.2 175459.9 ) ( Ref:LSO207738 ) LSO207738_D SCI0003.JPG LSO207738_D SCI0004.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	16-Jan-2018	28 Day Defect
725480	19-Dec-2017	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 up rich road west os 224 eb A205 up ri	mods blocks req reset 3n\$ SLPF Slab profile : uneven/trips/gap ( XY:520601.4 175421 ) ( Ref:LSO207739 ) LSO207739_D SCI0005.JPG LSO207739_D SCI0006.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	16-Jan-2018	28 Day Defect
729025	16-Jan-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper richmond road w os 208 eb A205 u	mods blocks req reset 3n@ SLPF Slab profile : uneven/trips/gap ( XY:520663 175430.3 ) ( Ref:LSO207874 ) LSO207874_D SCI0019.JPG LSO207874_D SCI0020.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	13-Feb-2018	28 Day Defect
729720	19-Jan-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road West opposite. the Willoughbys.	make safe knocked over KLB	1	Safety Bollards; Face/Structure/ Fixings	Base Light Damaged	Permanent	16-Feb-2018	Priority 1
729720	19-Jan-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road West opposite. the Willoughbys.	make safe knocked over KLB	1	Safety Bollards; Face/Structure/ Fixings	Base Light Damaged	Temporary	20-Jan-2018	Priority 1
735463	20-Feb-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 upper richmond rd w eb o/s 180	sunken req rst mods 3d SLPF Slab profile : uneven/trips/gap ( XY:520770.1 175445.7 ) ( Ref:LSO406535 ) LSO406535_D SCI0288.JPG LSO406535_D SCI0289.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	20-Mar-2018	28 Day Defect
735464	20-Feb-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 upper richmond rd w eb o/s 178	sunken req rst mods 3d SLPF Slab profile : uneven/trips/gap ( XY:520779.1 175446 ) ( Ref:LSO406536 ) LSO406536_D SCI0292.JPG LSO406536_D SCI0293.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	20-Mar-2018	28 Day Defect
739729	20-Mar-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 150 nb A205 URRW os 150 nb	req new pointing 3D CRCK Cracking ( XY:520877.1 175456.4 ) ( Ref:LSO311871 ) LSO311871_D SCI0005.JPG LSO311871_D SCI0006.JPG	2M	Footways And Cycle Tracks	Cracking	Permanent	17-Apr-2018	28 Day Defect
739731	20-Mar-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW jc palewell park eb A205 URRW jc	reset tactile 3D SLPF Slab profile : uneven/trips/gap ( XY:520707.2 175419.5 ) ( Ref:LSO311886 ) LSO311886_D SCI0035.JPG LSO311886_D SCI0036.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	17-Apr-2018	28 Day Defect

739713	20-Mar-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west o/s 178 sb fw A205 urrd west	rst mods3D @ SROK Slab rocking ( XY:520778.4 175446.3 ) ( Ref:LSO111788 ) LSO111788_D SCN7863.JPG LSO111788_D SCN7864.JPG	2M	Footways And Cycle Tracks	Slab rocking	Permanent	17-Apr-2018	28 Day Defect
739717	20-Mar-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west o/s 311 NB fw A205 urrd wes	req fillet 3D @ CRCK Cracking ( XY:520704.3 175420.5 ) ( Ref:LSO111801 ) LSO111801_D SCN7901.JPG LSO111801_D SCN7902.JPG	2M	Footways And Cycle Tracks	Cracking	Permanent	17-Apr-2018	28 Day Defect
744866	24-Apr-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW jc portman ave eb A205 URRW jc po	reset metal bollard 3D COPT Physical condition of post ( XY:520761.4 175441.6 ) ( Ref:LSO312122 ) LSO312122_D SCI0029.JPG LSO312122_D SCI0030.JPG	2M	Post Defect	Physical condition of post	Permanent	22-May-2018	28 Day Defect
748392	22-May-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper richmond road w jn sheen ln eb A	mod req reset 3n@ SLPF Slab profile : uneven/trips/gap ( XY:520510.3 175407.4 ) ( Ref:LSO208737 ) LSO208737_D SCI0084.JPG LSO208737_D SCI0085.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	19-Jun-2018	28 Day Defect
748397	22-May-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper richmond road west os 100 eb A20	mods blocks req reset 3n@ SLPF Slab profile : uneven/trips/gap ( XY:521117.5 175460.8 ) ( Ref:LSO208742 ) LSO208742_D SCI0099.JPG LSO208742_D SCI0100.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	19-Jun-2018	28 Day Defect
748400	22-May-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper rich rd w os the willoughbys eb	T347 damaged klb base req new 3d@ ACCD Accident damage ( XY:521416.1 175474.9 ) ( Ref:LSO208745 ) LSO208745_D SCI0109.JPG LSO208745_D SCI0111.JPG	1	Safety Bollards: Face/Structure/ Fixings	Accident damage	Permanent	19-Jun-2018	Priority 1
748400	22-May-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper rich rd w os the willoughbys eb	T347 damaged klb base req new 3d@ ACCD Accident damage ( XY:521416.1 175474.9 ) ( Ref:LSO208745 ) LSO208745_D SCI0109.JPG LSO208745_D SCI0111.JPG	1	Safety Bollards: Face/Structure/ Fixings	Accident damage	Temporary	23-May-2018	Priority 1
749058	28-May-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) @A205 Upper Richmond Road W/B	NULL	2H	Safety Bollards: Face/Structure/ Fixings	Lamp failure	Permanent	04-Jun-2018	7 Day Defect
750234	05-Jun-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	Priest Bridge Rd jw A205 Upper Richmond Rd	KLB	1	Safety Bollards: Face/Structure/ Fixings	Shell Missing/Detached	Permanent	06-Jun-2018	Priority 1

752260	19-Jun-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west o/s sheen primary school A20	rst mods 3D @ SLPF Slab profile : uneven/trips/gap ( XY:521314.5 175462.5 ) ( Ref:LSO112572 ) LSO112572_D SCN5681.JPG LSO112572_D SCN5682.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	17-Jul-2018	28 Day Defect
752262	19-Jun-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west nb fw o/s 203 A205 urrd west	2S site rst mods cover 3D @ SLPF Slab profile : uneven/trips/gap ( XY:520878.7 175443.9 ) ( Ref:LSO112574 ) LSO112574_D SCN5687.JPG LSO112574_D SCN5686.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	17-Jul-2018	28 Day Defect
752263	19-Jun-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west nb fw o/s 207 A205 urrd west	rst cover mod 3D @ SLPF Slab profile : uneven/trips/gap ( XY:520870.8 175443 ) ( Ref:LSO112575 ) LSO112575_D SCN5689.JPG LSO112575_D SCN5690.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	17-Jul-2018	28 Day Defect
752265	19-Jun-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west nb fw o/s 319 A205 urrd west	rst asp 3D @ SLPF Slab profile : uneven/trips/gap ( XY:520674.8 175417.1 ) ( Ref:LSO112578 ) LSO112578_D SCN5697.JPG LSO112578_D SCN5698.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	17-Jul-2018	28 Day Defect
752282	19-Jun-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 up rich rd w jn richmond park rd wb A2	bollard req reset 3n@ COPT Physical condition of post ( XY:520607.4 175409.9 ) ( Ref:LSO208881 ) LSO208881_D SCI0133.JPG LSO208881_D SCI0134.JPG	2M	Post Defect	Physical condition of post	Permanent	17-Jul-2018	28 Day Defect
752278	19-Jun-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper richmond road west os 205a w A20	stop cocks req reset 3n\$ CKIR Cracking around ironwork ( XY:520873.7 175443.1 ) ( Ref:LSO208877 ) LSO208877_D SCI0120.JPG LSO208877_D SCI0121.JPG	2M	Footways And Cycle Tracks	Cracking around ironwork	Permanent	17-Jul-2018	28 Day Defect
756850	24-Jul-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 309 nb A205 URRW os 309 nb	T996 req new pointing 3D CKIR Cracking around ironwork ( XY:520724.9 175423.2 ) ( Ref:LSO312568 ) LSO312568_D SCN6068.jpg LSO312568_D SCN6069.jpg	1	Footways And Cycle Tracks	Cracking around ironwork	Permanent	21-Aug-2018	Priority 1

756850	24-Jul-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 309 nb A205 URRW os 309 nb	T996 req new pointing 3D CKIR Cracking around ironwork ( XY:520724.9 175423.2 ) ( Ref:LSO312568 ) LSO312568_D SCN6068.jpg LSO312568_D SCN6069.jpg	1	Footways And Cycle Tracks	Cracking around ironwork	Temporary	25-Jul-2018	Priority 1
756846	24-Jul-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205upper richmond road west os 56 eb A205u	blocks req reset 3n\$ BKPF Block profile ( XY:521278.6 175471.5 ) ( Ref:LSO209020 ) LSO209020_D SCI0001.JPG LSO209020_D SCI0002.JPG	2M	Footways And Cycle Tracks	Block profile	Permanent	21-Aug-2018	28 Day Defect
756847	24-Jul-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper richmond road w os 60 eb A205 up	stopcock mods req reset 3n\$ SLPF Slab profile : uneven/trips/gap ( XY:521266.3 175470.8 ) ( Ref:LSO209021 ) LSO209021_D SCI0004.JPG LSO209021_D SCI0005.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	21-Aug-2018	28 Day Defect
760880	21-Aug-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 48 eb A205 URRW os 48 eb	reset blocks 3D BKPF Block profile ( XY:521313.1 175473 ) ( Ref:LSO312757 ) LSO312757_D SCN6494.jpg LSO312757_D SCN6495.jpg	2M	Footways And Cycle Tracks	Block profile	Permanent	18-Sep-2018	28 Day Defect
760883	21-Aug-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW opp 245 eb A205 URRW opp 245 eb	reset mods 3D SLPF Slab profile : uneven/trips/gap ( XY:520789.5 175446.8 ) ( Ref:LSO312760 ) LSO312760_D SCN6500.jpg LSO312760_D SCN6501.jpg	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Sep-2018	28 Day Defect
760884	21-Aug-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 325 sb A205 URRW os 325 sb	reset slabs 3D SLPF Slab profile : uneven/trips/gap ( XY:520658.3 175414.3 ) ( Ref:LSO312768 ) LSO312768_D SCN6516.jpg LSO312768_D SCN6517.jpg	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Sep-2018	28 Day Defect
760892	21-Aug-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrrd west nb fw jn sutherland gds A20	rst fw cvr 3D @ ACCD Accident damage ( XY:521283.3 175472.4 ) ( Ref:LSO112948 ) LSO112948_D SCN6837.JPG LSO112948_D SCN6838.JPG	2M	Footways And Cycle Tracks	Accident damage	Permanent	18-Sep-2018	28 Day Defect
760893	21-Aug-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrrd west nb fw O/S 107 A205 urrrd we	rst mods point up 3D SLPF Slab profile : uneven/trips/gap ( XY:520805.3 175447.1 ) ( Ref:LSO112949 ) LSO112949_D SCN6840.JPG LSO112949_D SCN6841.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Sep-2018	28 Day Defect

765248	18-Sep-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 upper rich rd W eb o/s 180	sunken req rst blocks 3d BKPF Block profile ( XY:520769.4 175446.3 ) ( Ref:LSO407860 ) LSO407860_D SC06710.JPG LSO407860_D SC06711.JPG	2M	Footways And Cycle Tracks	Block profile	Permanent	16-Oct-2018	28 Day Defect
769751	23-Oct-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 52 eb A205 URRW os 52 eb	RESET MODS 3d SLPF Slab profile : uneven/trips/gap ( XY:521303.2 175471.4 ) ( Ref:LSO313061 ) LSO313061_D SCN7151.jpg LSO313061_D SCN7152.jpg	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	20-Nov-2018	28 Day Defect
769752	23-Oct-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 150 eb A205 URRW os 150 eb	req new pointing 3D CRCK Cracking ( XY:520876.3 175456.2 ) ( Ref:LSO313062 ) LSO313062_D SCN7153.jpg LSO313062_D SCN7154.jpg	2M	Footways And Cycle Tracks	Cracking	Permanent	20-Nov-2018	28 Day Defect
769753	23-Oct-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 182 eb A205 URRW os 182 eb	reset mods blocks new pointing 3D BKPF Block profile ( XY:520764.3 175443.1 ) ( Ref:LSO313063 ) LSO313063_D SCN7155.jpg LSO313063_D SCN7156.jpg	2M	Footways And Cycle Tracks	Block profile	Permanent	20-Nov-2018	28 Day Defect
769757	23-Oct-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW opp avenue gardens wb A205 URRW o	reset mods 3D \$ SLPF Slab profile : uneven/trips/gap ( XY:521081.3 175445.5 ) ( Ref:LSO313069 ) LSO313069_D SCN7167.jpg LSO313069_D SCN7168.jpg	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	20-Nov-2018	28 Day Defect
769737	23-Oct-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 up rich rd w jn portman av eb A205 up	blocks req reset 3n\$ ACCD Accident damage ( XY:520762.2 175442.1 ) ( Ref:LSO209561 ) LSO209561_D SCI0004.JPG LSO209561_D SCI0005.JPG	2M	Footways And Cycle Tracks	Accident damage	Permanent	20-Nov-2018	28 Day Defect
769738	23-Oct-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 up rich rd w os 236 eb A205 up rich rd	blocks req reset 3n\$ BKPF Block profile ( XY:520560.6 175414 ) ( Ref:LSO209562 ) LSO209562_D SCI0007.JPG LSO209562_D SCI0008.JPG	2M	Footways And Cycle Tracks	Block profile	Permanent	20-Nov-2018	28 Day Defect
769739	23-Oct-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper richmond road west os 327 A205 u	blocks req reset 3n@ BKPF Block profile ( XY:520649.4 175413.8 ) ( Ref:LSO209564 ) LSO209564_D SCI0013.JPG LSO209564_D SCI0014.JPG	2M	Footways And Cycle Tracks	Block profile	Permanent	20-Nov-2018	28 Day Defect
772013	09-Nov-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road west os 150 EB FW	fw defect around BT Cover	1	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	10-Nov-2018	Priority 1

773191	20-Nov-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper richmond rd w os 193 wb	NULL	2M	Footways And Cycle Tracks	Cracking around ironwork	Permanent	18-Dec-2018	28 Day Defect
773192	20-Nov-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 up rich rd w jn palewell park	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Dec-2018	28 Day Defect
775775	11-Dec-2018	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Road Rd jw Wallorton Gardens	z knocked over metal bollard	1	Safety Bollards: Face/Structure/ Fixings	Damaged/deformed	Permanent	12-Dec-2018	Priority 1
780231	22-Jan-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 URRW os 224 EB	blocks req reset 3D SLPF Slab profile : uneven/trips/gap ( XY:520601.4 175420.8 ) ( Ref:LSO408195 ) LSO408195_D SC07731.JPG LSO408195_D SC07732.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	19-Feb-2019	28 Day Defect
780067	22-Jan-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper richmond rd w os 109 eb A205 upp	cover req fillet 3n\$ CKIR Cracking around ironwork ( XY:521085 175458 ) ( Ref:LSO209977 ) LSO209977_D SCI0004.JPG LSO209977_D SCI0005.JPG	2M	Footways And Cycle Tracks	Cracking around ironwork	Permanent	19-Feb-2019	28 Day Defect
780066	22-Jan-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper richmond rd w os 64 eb A205 uppe	reset blocks new fillet 3n\$ CKIR Cracking around ironwork ( XY:521253.9 175469.8 ) ( Ref:LSO209976 ) LSO209976_D SCI0001.JPG LSO209976_D SCI0002.JPG	2M	Footways And Cycle Tracks	Cracking around ironwork	Permanent	19-Feb-2019	28 Day Defect
780068	22-Jan-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper richmond rd w jn milton rd eb A2	x2 covers req fillet 3n\$ CKIR Cracking around ironwork ( XY:520576 175416.5 ) ( Ref:LSO209978 ) LSO209978_D SCI0007.JPG LSO209978_D SCI0008.JPG	2M	Footways And Cycle Tracks	Cracking around ironwork	Permanent	19-Feb-2019	28 Day Defect
783976	19-Feb-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW opp avenue gardens sb A205 URRW o	reset mods 3D\$ SLPF Slab profile : uneven/trips/gap ( XY:521082.8 175445.2 ) ( Ref:LSO313805 ) LSO313805_D SCN8776.jpg LSO313805_D SCN8777.jpg	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	19-Mar-2019	28 Day Defect
783978	19-Feb-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 203 sb A205 URRW os 203 sb	reset mods blocks pointing 3D SLPF Slab profile : uneven/trips/gap ( XY:520879.2 175443 ) ( Ref:LSO313807 ) LSO313807_D SCN8780.jpg LSO313807_D SCN8781.jpg	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	19-Mar-2019	28 Day Defect



783759	19-Feb-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 upper richmond rd w os church wb A205	mods req reset 3n\$ SLPF Slab profile : uneven/trips/gap ( XY:521072.3 175445.5 ) ( Ref:LSO210113 ) LSO210113_D SCI0001.JPG LSO210113_D SCI0002.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	19-Mar-2019	28 Day Defect
784354	22-Feb-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 UPPER RICHMOND RD WEST J/ PRIESTS BRIDGE	PGR AND POSTS KNOCKED DOWN	1E	Safety Fences: Metal/Concrete	Accident damage	Permanent	22-Mar-2019	Priority 1 (ECO)
784354	22-Feb-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 UPPER RICHMOND RD WEST J/ PRIESTS BRIDGE	PGR AND POSTS KNOCKED DOWN	1E	Safety Fences: Metal/Concrete	Accident damage	Temporary	23-Feb-2019	Priority 1 (ECO)
792245	23-Apr-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west sb fw o/s 106 A205 urrd we	2x sites pointing rsy blocks 3D @ CKIR Cracking around ironwork ( XY:521106.9 175458.3 ) ( Ref:LSO114244 ) LSO114244_tu 013.jpg LSO114244_tu 014.jpg	2M	Footways And Cycle Tracks	Cracking around ironwork	Permanent	21-May-2019	28 Day Defect
792621	24-Apr-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west sb fw 213 jn east sheen av A20	req mortar fillet 3D @ NB FW CRCK Cracking ( XY:520852 175441 ) ( Ref:LSO114282 ) LSO114282_w e 051.jpg LSO114282_w e 052.jpg	2M	Footways And Cycle Tracks	Cracking	Permanent	22-May-2019	28 Day Defect
792624	24-Apr-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west o/s 351 nb fw A205 urrd west	2X site rst fw cvr mods 3D @ CKIR Cracking around ironwork ( XY:520564.2 175402.7 ) ( Ref:LSO114290 ) LSO114290_w e 077.jpg LSO114290_w e 078.jpg	2M	Footways And Cycle Tracks	Cracking around ironwork	Permanent	22-May-2019	28 Day Defect
795846	21-May-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd wst os 9 11 mitch court A205 urrd	req rst mods 3D @ SLPF Slab profile : uneven/trips/gap ( XY:521357 175460.7 ) ( Ref:LSO210304 ) LSO210304_D SCI0035.JPG LSO210304_D SCI0036.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Jun-2019	28 Day Defect
795848	21-May-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west sb fw jw grovsnor rd A205 ur	req reset blocks fillet 3D @ SLPF Slab profile : uneven/trips/gap ( XY:521300.3 175473.4 ) ( Ref:LSO210306 ) LSO210306_D SCI0041.JPG LSO210306_D SCI0040.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Jun-2019	28 Day Defect
795849	21-May-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west sb fw OS 170 A205 urrd west	req rst mods fillet 3D @ SLPF Slab profile : uneven/trips/gap ( XY:521100.7 175459.2 ) ( Ref:LSO210307 ) LSO210307_D SCI0042.JPG LSO210307_D SCI0043.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Jun-2019	28 Day Defect

795850	21-May-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west sb fw os 170 A205 urrd west	Req rst blocks fillet 3D @ SLPF Slab profile : uneven/trips/gap ( XY:521098.3 175459.1 ) ( Ref:LSO210308 ) LSO210308_D SCI0044.JPG LSO210308_D SCI0045.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Jun-2019	28 Day Defect
795851	21-May-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west nb cw jw east sheen lne A205	Req rst mods tree roots 3D@ SLPF Slab profile : uneven/trips/gap ( XY:520829.3 175435.4 ) ( Ref:LSO210315 ) LSO210315_D SCI0059.JPG LSO210315_D SCI0060.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Jun-2019	28 Day Defect
796023	21-May-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west nb f/w o/s 345 A205 urrd west	rsyt mod cvr 3D @ SLPF Slab profile : uneven/trips/gap ( XY:520583.6 175405 ) ( Ref:LSO114635 ) LSO114635_D SCI0034.JPG LSO114635_D SCI0035.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Jun-2019	28 Day Defect
796024	21-May-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west nb f/w o/s 217 e sheen ln A2	req new acco drain 3D @ CRCK Cracking ( XY:520812.3 175437.1 ) ( Ref:LSO114636 ) LSO114636_D SCI0037.JPG LSO114636_D SCI0038.JPG	2M	Footways And Cycle Tracks	Cracking	Permanent	18-Jun-2019	28 Day Defect
797187	30-May-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Rd West jw Wallorton Gardens (Sheen)	¿MBollard knocked out	1	Safety Bollards: Face/Structure/ Fixings	Damaged/deformed	Permanent	27-Jun-2019	Priority 1
797187	30-May-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 Upper Richmond Rd West jw Wallorton Gardens (Sheen)	¿MBollard knocked out	1	Safety Bollards: Face/Structure/ Fixings	Damaged/deformed	Temporary	31-May-2019	Priority 1
803691	16-Jul-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 275-285 wb A205 URRW os 275-28	reset mods blocks fillet 3D @ 2x sites SLPF Slab profile : uneven/trips/gap ( XY:520759.7 175428.3 ) ( Ref:LSO314245 ) LSO314245_D SCN9857.jpg LSO314245_D SCN9858.jpg	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	13-Aug-2019	28 Day Defect
803649	16-Jul-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west nb fw o/s 199 A205 urrd west	rst fw cvr 3D @ CKIR Cracking around ironwork ( XY:520891.8 175444.6 ) ( Ref:LSO115022 ) LSO115022_D SCI0500.JPG LSO115022_D SCI0501.JPG	2M	Footways And Cycle Tracks	Cracking around ironwork	Permanent	13-Aug-2019	28 Day Defect

803648	16-Jul-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrrd west nb fw o/s 201-203 A205 urrr	2x sites rst vvr mods fillet 3D @ SLPF Slab profile : uneven/trips/gap ( XY:520878.3 175443.4 ) ( Ref:LSO115021 ) LSO115021_D SCI0497.JPG LSO115021_D SCI0498.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	13-Aug-2019	28 Day Defect
803650	16-Jul-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrrd west sb fw o/s 158 A205 urrrd we	2X sitev rst mods point up 3D @ SLPF Slab profile : uneven/trips/gap ( XY:520845.1 175452.8 ) ( Ref:LSO115023 ) LSO115023_D SCI0503.JPG LSO115023_D SCI0504.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	13-Aug-2019	28 Day Defect
803930	18-Jul-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	226 on A205 Upper Richmond Road West,	concrete has broken away and has formed a trip hazard	1	Footways And Cycle Tracks	Other	Permanent	19-Jul-2019	Priority 1
804753	24-Jul-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	Queens Rd jw A205 URRW	leaning Post, said these jobs will be done during the day as a trial run.damaged post removed made safe time 1015 to 1032-FAR	1	Post Defect	Damaged/Deformed	Permanent	21-Aug-2019	Priority 1
804753	24-Jul-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	Queens Rd jw A205 URRW	leaning Post, said these jobs will be done during the day as a trial run.damaged post removed made safe time 1015 to 1032-FAR	1	Post Defect	Damaged/Deformed	Temporary	25-Jul-2019	Priority 1
808825	20-Aug-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 up rich rd wst wb fw os 244 A205 up ri	T5640ms req reset asp 3D@ SLPF Slab profile : uneven/trips/gap ( XY:520538.6 175410.5 ) ( Ref:LSO210729 ) LSO210729_D SCI0676.JPG LSO210729_D SCI0677.JPG	1	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	17-Sep-2019	Priority 1
808825	20-Aug-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 up rich rd wst wb fw os 244 A205 up ri	T5640ms req reset asp 3D@ SLPF Slab profile : uneven/trips/gap ( XY:520538.6 175410.5 ) ( Ref:LSO210729 ) LSO210729_D SCI0676.JPG LSO210729_D SCI0677.JPG	1	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Temporary	21-Aug-2019	Priority 1
810494	05-Sep-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 URRW o/s 108 - SW14 8BS	f/w defect around BT Cover	1	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	03-Oct-2019	Priority 1
810494	05-Sep-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 URRW o/s 108 - SW14 8BS	f/w defect around BT Cover	1	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Temporary	06-Sep-2019	Priority 1

812037	17-Sep-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW opp avenue gardens sb A205 URRW	req 6mm 3D @ BFRT Blacktop : fretting ( XY:521081.8 175445.4 ) ( Ref:LSO314651 ) LSO314651_D SCN0765.jpg LSO314651_D SCN0766.jpg	2M	Footways And Cycle Tracks	Blacktop : fretting	Permanent	15-Oct-2019	28 Day Defect
812039	17-Sep-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW jc avenue gardens nb A205 URRW j	reset blocks fillet 3D \$ BKPF Block profile ( XY:521085.5 175457.7 ) ( Ref:LSO314653 ) LSO314653_D SCN0769.jpg LSO314653_D SCN0770.jpg	2M	Footways And Cycle Tracks	Block profile	Permanent	15-Oct-2019	28 Day Defect
812040	17-Sep-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 162 nb A205 URRW os 162 nb	reset mods blocks fillet 3D \$ SLPF Slab profile : uneven/trips/gap ( XY:520833.5 175450.9 ) ( Ref:LSO314654 ) LSO314654_D SCN0771.jpg LSO314654_D SCN0772.jpg	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	15-Oct-2019	28 Day Defect
812041	17-Sep-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 179 sb A205 URRW os 179 sb	reset mods blocks fillet 3D \$ SLPF Slab profile : uneven/trips/gap ( XY:520973.5 175445.5 ) ( Ref:LSO314672 ) LSO314672_D SCN0809.jpg LSO314672_D SCN0810.jpg	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	15-Oct-2019	28 Day Defect
816575	22-Oct-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 upper richmond rd w eb o/s 212a	uneven req rst blocks fillet 3d SLPF Slab profile : uneven/trips/gap ( XY:520653.9 175428.2 ) ( Ref:LSO409870 ) LSO409870_Picture 018.jpg LSO409870_Picture 019.jpg	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	19-Nov-2019	28 Day Defect
816576	22-Oct-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	a205 upper richmond rd w eb o/s 78	uneven req rst blocks 3d\$ BKPF Block profile ( XY:521196.4 175466.1 ) ( Ref:LSO409871 ) LSO409871_Picture 027.jpg LSO409871_Picture 028.jpg	2M	Footways And Cycle Tracks	Block profile	Permanent	19-Nov-2019	28 Day Defect
821174	19-Nov-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 128a nb A205 URRW os 128a nb	reset mods 3D \$ STWT Standing water ( XY:521026.1 175454.7 ) ( Ref:LSO314971 ) LSO314971_D SCN1508.jpg LSO314971_D SCN1509.jpg	2M	Footways And Cycle Tracks	Standing Water	Permanent	17-Dec-2019	28 Day Defect
821163	19-Nov-2019	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrd west sb fw o/s 196 A205 urrd west	raise up mods 3D @ SLPF Slab profile : uneven/trips/gap ( XY:520713 175437 ) ( Ref:LSO116228 ) LSO116228_D SCN0254.JPG LSO116228_D SCN0255.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	17-Dec-2019	28 Day Defect

829492	21-Jan-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 98 nb A205 URRW os 98 nb	T8043 reset mods blocks 3D @ SLPF Slab profile : uneven/trips/gap ( XY:521123.2 175460.1 ) ( Ref:LSO315265 ) LSO315265_D SCN2144.jpg LSO315265_D SCN2145.jpg	1	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Feb-2020	Priority 1
829492	21-Jan-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 98 nb A205 URRW os 98 nb	T8043 reset mods blocks 3D @ SLPF Slab profile : uneven/trips/gap ( XY:521123.2 175460.1 ) ( Ref:LSO315265 ) LSO315265_D SCN2144.jpg LSO315265_D SCN2145.jpg	1	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Temporary	22-Jan-2020	Priority 1
829493	21-Jan-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 48 nb A205 URRW os 48 nb	reset mods blocks fillet 3D \$ SLPF Slab profile : uneven/trips/gap ( XY:521312.5 175472.9 ) ( Ref:LSO315268 ) LSO315268_D SCN2140.jpg LSO315268_D SCN2141.jpg	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Feb-2020	28 Day Defect
829494	21-Jan-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 64 nb A205 URRW os 64 nb	reset mods blocks fillet 3D \$ SLPF Slab profile : uneven/trips/gap ( XY:521254.2 175469.7 ) ( Ref:LSO315269 ) LSO315269_D SCN2142.jpg LSO315269_D SCN2143.jpg	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Feb-2020	28 Day Defect
829495	21-Jan-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 236 nb A205 URRW os 236 nb	reset mods blocks fillet 3D @ SLPF Slab profile : uneven/trips/gap ( XY:520560.6 175414.2 ) ( Ref:LSO315270 ) LSO315270_D SCN2146.jpg LSO315270_D SCN2147.jpg	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Feb-2020	28 Day Defect
829496	21-Jan-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 351 sb A205 URRW os 351 sb	reset mods blocks 3x covers 3D \$ SLPF Slab profile : uneven/trips/gap ( XY:520565.7 175402.7 ) ( Ref:LSO315274 ) LSO315274_D SCN2159.jpg LSO315274_D SCN2160.jpg	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Feb-2020	28 Day Defect
829715	22-Jan-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 Upper Richmond Rd os 62	fillet around LP86 re repair LSO116563	2M	Footways And Cycle Tracks	Other	Permanent	19-Feb-2020	28 Day Defect
829718	22-Jan-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 Upper Richmond Road os 172 to 176	slabs req reset around tree pit LSO116565	2M	Footways And Cycle Tracks	Other	Permanent	19-Feb-2020	28 Day Defect
829720	22-Jan-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 Upper Richmond Rd os 341	fw slabs req reset LSO116572	2M	Footways And Cycle Tracks	Other	Permanent	19-Feb-2020	28 Day Defect

834055	18-Feb-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 urrw wb fw os 351a A205 urrw wb fw os	Req reset sunken mods 3D@ SLPF Slab profile : uneven/trips/gap ( XY:520565 175402.6 ) ( Ref:LSO211437 ) LSO211437_IMG_0221.JPG LSO211437_IMG_0220.JPG	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	17-Mar-2020	28 Day Defect
843825	21-Apr-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW jw richmond park rd sb A205 URRW	metal bollard req resetting 3D @ COPT Physical condition of post ( XY:520607.9 175409.1 ) ( Ref:LSO211489 ) LSO211489_IMG_0340.JPG LSO211489_IMG_0341.JPG	2M	Post Defect	Physical condition of post	Permanent	19-May-2020	28 Day Defect
843826	21-Apr-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW jw richmond park rd sb A205 URRW	req new filllet 3D @ CRCK Cracking ( XY:520601.8 175408 ) ( Ref:LSO211490 ) LSO211490_IMG_0342.JPG LSO211490_IMG_0343.JPG	2M	Footways And Cycle Tracks	Cracking	Permanent	19-May-2020	28 Day Defect
849013	19-May-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 281 sb A205 URRW os 281 sb	reset mods blocks 3D @ SLPF Slab profile : uneven/trips/gap ( XY:520755.7 175428.1 ) ( Ref:LSO315783 ) LSO315783_IMG_1171.jpg LSO315783_IMG_1172.jpg	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	16-Jun-2020	28 Day Defect
849014	19-May-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 327 sb A205 URRW os 327 sb	reset mods blocks fillet 3D @ SLPF Slab profile : uneven/trips/gap ( XY:520651.6 175414.3 ) ( Ref:LSO315784 ) LSO315784_IMG_1173.jpg LSO315784_IMG_1174.jpg	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	16-Jun-2020	28 Day Defect
849018	19-May-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 232 nb A205 URRW os 232 nb	reset mods blocks fillet 3D \$ SLPF Slab profile : uneven/trips/gap ( XY:520574.2 175416 ) ( Ref:LSO315788 ) LSO315788_IMG_1182.jpg LSO315788_IMG_1183.jpg	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	16-Jun-2020	28 Day Defect
849019	19-May-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 226 nb A205 URRW os 226 nb	req new fillet 3D CRCK Cracking ( XY:520590.3 175419.6 ) ( Ref:LSO315789 ) LSO315789_IMG_1184.jpg LSO315789_IMG_1185.jpg	2M	Footways And Cycle Tracks	Cracking	Permanent	16-Jun-2020	28 Day Defect
849020	19-May-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 192 nb A205 URRW os 192 nb	reset slot drainage fillet 3D @ ?? ELRK Loose/rocking ( XY:520721.8 175437.1 ) ( Ref:LSO315790 ) LSO315790_IMG_1186.jpg LSO315790_IMG_1187.jpg	2M	Footways And Cycle Tracks	Loose/rocking	Permanent	16-Jun-2020	28 Day Defect

852466	09-Jun-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 URRW o/s 246 and opp 240	¿ 2 x broken Drains	1	Footways And Cycle Tracks	Other	Permanent	07-Jul-2020	Priority 1
852466	09-Jun-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	A205 URRW o/s 246 and opp 240	¿ 2 x broken Drains	1	Footways And Cycle Tracks	Other	Temporary	10-Jun-2020	Priority 1
853601	16-Jun-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 158 nb A205 URRW os 158 nb	req new fillet 3D @ 4x sites CRCK Cracking ( XY:520844.2 175452.9 ) ( Ref:LSO316012 ) LSO316012_IMG_1665.jpg LSO316012_IMG_1666.jpg	2M	Footways And Cycle Tracks	Cracking	Permanent	14-Jul-2020	28 Day Defect
853602	16-Jun-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW so 170 nb A205 URRW so 170 nb	reset mods blocks fillet 3D @ SLPF Slab profile : uneven/trips/gap ( XY:520801.3 175448.8 ) ( Ref:LSO316013 ) LSO316013_IMG_1667.jpg LSO316013_IMG_1668.jpg	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	14-Jul-2020	28 Day Defect
853603	16-Jun-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 182 jc portman ave nb A205 URR	reset metal bollard 3D @ COPT Physical condition of post ( XY:520761.2 175442 ) ( Ref:LSO316014 ) LSO316014_IMG_1669.jpg LSO316014_IMG_1670.jpg	2M	Post Defect	Physical condition of post	Permanent	14-Jul-2020	28 Day Defect
853605	16-Jun-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 217 sb A205 URRW os 217 sb	req new fillet 3D @ CRCK Cracking ( XY:520820.6 175437.6 ) ( Ref:LSO316018 ) LSO316018_IMG_1677.jpg LSO316018_IMG_1678.jpg	2M	Footways And Cycle Tracks	Cracking	Permanent	14-Jul-2020	28 Day Defect
853606	16-Jun-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW jc east sheen ave sb A205 URRW j	new reset blocks 3D @ BKPF Block profile ( XY:520830.4 175436.4 ) ( Ref:LSO316019 ) LSO316019_IMG_1679.jpg LSO316019_IMG_1680.jpg	2M	Footways And Cycle Tracks	Block profile	Permanent	14-Jul-2020	28 Day Defect
858180	21-Jul-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 62 nb A205 URRW os 62 nb	req new fillet 3D @ CRCK Cracking ( XY:521259.3 175469.9 ) ( Ref:LSO316248 ) LSO316248_IMG_2188.jpg LSO316248_IMG_2189.jpg	2M	Footways And Cycle Tracks	Cracking	Permanent	18-Aug-2020	28 Day Defect
858181	21-Jul-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 64 nb A205 URRW os 64 nb	reset mods blocks 3D \$ SLPF Slab profile : uneven/trips/gap ( XY:521251.6 175470.1 ) ( Ref:LSO316249 ) LSO316249_IMG_2190.jpg LSO316249_IMG_2191.jpg	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	18-Aug-2020	28 Day Defect

858182	21-Jul-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 92 nb A205 URRW os 92 nb	req new fillet 3D @ 3x sites CRCK Cracking ( XY:521154.9 175462 ) ( Ref:LSO316250 ) LSO316250_IMG_2192.jpg LSO316250_IMG_2193.jpg	2M	Footways And Cycle Tracks	Cracking	Permanent	18-Aug-2020	28 Day Defect
862885	18-Aug-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 201 sb	NULL	2M	Footways And Cycle Tracks	Cracking	Permanent	15-Sep-2020	28 Day Defect
862886	18-Aug-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 351 sb	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	15-Sep-2020	28 Day Defect
862887	18-Aug-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 325 nb	NULL	2M	Footways And Cycle Tracks	Block profile	Permanent	15-Sep-2020	28 Day Defect
862888	18-Aug-2020	0000A205_6/00015	A205,UPPER RICHMOND ROAD WEST,E/B,(SHEEN LN TO MIDDLE OF WILLOUGHBYS),SW14	(RICH) A205 URRW os 176 nb	NULL	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	15-Sep-2020	28 Day Defect