

LCS code	M134	Asset No	M134/	/CW74			
Line	Metropol	itan		Location	BARBICAN	I - MOORG	ATE
Owner	LUL			Maintainer	Civils & Tr	k Mngr SSI	-
Structure Covered Way			Asset subject special inspections	,			
PI Inspection frequency		Date of last PI	20/10/10	Date of this PI	18/07/2014	Ellipse order number	52123669- 001

Summary position

	This structure has been examined in accordance with engineering standard S1060 and found to be:						
	CCN http://llinkdms.mr.int/livelink/livelink.exe?func=ll&objaction=overview&objid=309319482 designed to standards						
ſ	From Principal Inspection Report	Assessment	Assessment Rating from Structural Assessment Report				
	Condition 79.17% Lowest Item score 6	No assessment	Pass 🗸	Fail	Capacity Ratio 999		

Elements classified B2 or less (scoring 6 or less)				
Element No	Element			
4	(Abutment) * 4 Condition (General Surface) (A4A) Isolated cracks ranged from hairline to 3mm, seepage stain and leachate noted to wall (6)			
6	(Abutment) * 6 Deck Support / Capping Beam (A4A) Concrete Various old standing h/l - 2mm max fractures Areas of seepage, water staining, leaching, and corrosion staining			
12	(Spanning Members) * 12 Bottom Face (Flange and Deck Soffit) (A4A) Isolated cracks and leaching			
13	(Spanning Members) * 13 Sides (Web) (A4A) Cracks and leaching noted			
12	(Spanning Members) * 12 Bottom Face (Flange and Deck Soffit) (A4A) RC Concrete – minor isolated hairline cracks			
9	(Supports) * 9 Condition (A24A) Isolated h/I fractures			

Performance Rating to S1060 Clause 3.5.10	General Condition Standard (see asset condition assessment standard 1-03	*LU 31) Information
Ideal	More Information required Grey	
Desirable 🗸	OR	
Essential minimum condition	Failure to meet duty (Extra inspections or protection required)	%
Unacceptable	Failure to meet duty E1 (Withdrawn from duty)	%
Failure	Immediate replacement, modification or overhaul required	%
*Inspection Review Engineer (IRE) Information ACA Concerns etc	Extraordinary operations or D maintenance regime required	%
	Major overhaul required after 1-5 years C	1%
	Major overhaul required after 6-10 years	%
X1813832 concrete	No major overhaul required A	99%
	Indicate, tick as appropr	iate Total 100%

*Note: LU information to be completed by the IRE.