



LCS code	M134	Asset No	M134/CW75		
Line	Metropolitan	Location	BARBICAN - MOORGATE		
Owner	London Underground Ltd	Maintainer	Civils & Trk Mngr SSL		
Structure	Covered Way	Asset subject to special inspections	Yes		
PI Inspection frequency	4years	Date of last PI	24/03/10	Date of this PI	19/07/2013 15/07/14
				Ellipse order number	51870041-001

Summary position

This structure has been examined in accordance with engineering standard S1060 and found to be:

CCN <http://linkdms.mr.int/livelink/livelink.exe?func=ll&objaction=overview&objid=309319090>
designed to standards – hence CR set ass 999

From Principal Inspection Report		Assessment Rating from Structural Assessment Report						
Condition score	83.33%	Lowest Item score	6	No assessment	Pass	Fail	Capacity Ratio	999

Elements classified B2 or less (scoring 6 or less)

Element No	Element
4 (north) 12	(Abutment) * 4 Condition (General Surface) (A4A) isolated vertical fractures and leaching (Spanning Members) * 12 Bottom Face (Flange and Deck Soffit) (A4A) isolate fractures and leaching to concrete slab

General Condition Standard (see asset condition assessment standard 1-031)	*LU Information
More Information required	Grey
OR	
Failure to meet duty (Extra inspections or protection required)	E2 %
Failure to meet duty (Withdrawn from duty)	E1 %
Immediate replacement, modification or overhaul required	D %
Extraordinary operations or maintenance regime required	
Major overhaul required after 1-5 years	C <input checked="" type="checkbox"/> 1%
Major overhaul required after 6-10 years	B %
No major overhaul required Life > 10 years,	A <input checked="" type="checkbox"/> 99%
Indicate, tick as appropriate	
Total 100%	