Bridges & Structures Principal Inspection Report Referral A0g



M134 M134/CW75 LCS code Asset No Line **Metropolitan** Location **BARBICAN - MOORGATE** LUL Owner Maintainer Civils & Trk Mgr. SSL Asset subject to Structure **Covered Way** special inspections Ellipse order 53988384-PI Inspection 24/04/2018 4yrs 24/03/10 Date of last PI Date of this PI number 001 frequency

Summary position

This structure has been examined in accordance with engineering standard S1060 and found to be:

From Principal Inspection Report	Assessment Rating from Structural Assessment Report		
Condition score 83.33% Lowest Item 6	No V Pass	Fail Capacity 999	

Elements classified B2 or less (scoring 6 or less)

Element No Element

4 12 (Abutment) * 4 Condition (General Surface) (A4A) (Spanning Members) * 12 Bottom Face (Flange) (A4A)

Performance Rating to S1060 Clause 3.5.10	General Condition Standard (see asset condition assessment standard 1-031)	*LU Information
Ideal 🗸	More Information required Grey	
Desirable	OR	
Essential minimum condition	Failure to meet duty (Extra inspections or protection required)	%
Unacceptable	Failure to meet duty E1	%
Failure	Immediate replacement, modification or overhaul required	%
*Inspection Review Engineer (IRE) Information ACA Concerns etc.	Extraordinary operations or maintenance regime required	
	Major overhaul required after 1-5 years C	%
	Major overhaul required after 6-10 years	%
	No major overhaul required A \checkmark Life > 10 years,	100%
	Total 100%	

*Note: LU information to be completed by the IRE.