

2024-03-09-135148.jpg

Type: Site Visit Photo - Site made safe

Uploaded By: System

Uploaded on 09 Mar 2024 13:55

Date/Time Taken: 09 Mar 2024 13:55

File Id: 14527187

Client Ref:

Job Status: Completed

Gang: DCALLOUTNE

On/Off Site: 09 Mar 2024 13:49 - 09 Mar 2024 17:44

Site Visit Status: Completed - First time permanent repair

Requested Repair Type:

Inspector:

Inspection Date/Time: 09 Mar 2024 13:08

Lat: 51.5725 Lng: 0.0150313



2024-03-09-135159.jpg

Type: Site Visit Photo - Before Work Commenced

Uploaded By: System

Uploaded on 09 Mar 2024 13:55

Date/Time Taken: 09 Mar 2024 13:55

File Id: 14527189

Client Ref:

Job Status: Completed

Gang: DCALLOUTNE

On/Off Site: 09 Mar 2024 13:49 - 09 Mar 2024 17:44

Site Visit Status: Completed - First time permanent repair

Requested Repair Type:

Inspector:

Inspection Date/Time: 09 Mar 2024 13:08

Lat: 51.5725 Lng: 0.0150313



2024-03-09-135208.jpg

Type: Site Visit Photo - Before Work Commenced

Uploaded By: System

Uploaded on 09 Mar 2024 13:56

Date/Time Taken: 09 Mar 2024 13:56

File Id: 14527191

Client Ref:

Job Status: Completed

Gang: DCALLOUTNE

On/Off Site: 09 Mar 2024 13:49 - 09 Mar 2024 17:44

Site Visit Status: Completed - First time permanent repair

Requested Repair Type:

Inspector:

Inspection Date/Time: 09 Mar 2024 13:08

Lat: 51.5725 Lng: 0.0150313



2024-03-09-161316.jpg

Type: Site Visit Photo - Interim Photo

Uploaded By: System

Uploaded on 09 Mar 2024 16:17

Date/Time Taken: 09 Mar 2024 16:17

File Id: 14527355

Client Ref:

Job Status: Completed

Gang: DCALLOUTNE

On/Off Site: 09 Mar 2024 13:49 - 09 Mar 2024 17:44

Site Visit Status: Completed - First time permanent repair

Requested Repair Type:

Inspector:

Inspection Date/Time: 09 Mar 2024 13:08

Lat: 51.5725 Lng: 0.0150313



2024-03-09-161323.jpg

Type: Site Visit Photo - Interim Photo

Uploaded By: System

Uploaded on 09 Mar 2024 17:30

Date/Time Taken: 09 Mar 2024 17:30

File Id: 14527447

Client Ref:

Job Status: Completed

Gang: DCALLOUTNE

On/Off Site: 09 Mar 2024 13:49 - 09 Mar 2024 17:44

Site Visit Status: Completed - First time permanent repair

Requested Repair Type:

Inspector:

Inspection Date/Time: 09 Mar 2024 13:08

Lat: 51.5725 Lng: 0.0150313



2024-03-09-172931.jpg

Type: Site Visit Photo - After Work Completed

Uploaded By: System

Uploaded on 09 Mar 2024 17:45

Date/Time Taken: 09 Mar 2024 17:45

File Id: 14527474

Client Ref:

Job Status: Completed

Gang: DCALLOUTNE

On/Off Site: 09 Mar 2024 13:49 - 09 Mar 2024 17:44

Site Visit Status: Completed - First time permanent repair

Requested Repair Type:

Inspector:

Inspection Date/Time: 09 Mar 2024 13:08

Lat: 51.5725 Lng: 0.0150313



2024-03-09-174350.jpg

Type: Site Visit Photo - After Work Completed

Uploaded By: System

Uploaded on 09 Mar 2024 17:47

Date/Time Taken: 09 Mar 2024 17:47

File Id: 14527478

Client Ref:

Job Status: Completed

Gang: DCALLOUTNE

On/Off Site: 09 Mar 2024 13:49 - 09 Mar 2024 17:44

Site Visit Status: Completed - First time permanent repair

Requested Repair Type:

Inspector:

Inspection Date/Time: 09 Mar 2024 13:08

Lat: 51.5725 Lng: 0.0150313

