



Hazardous Material Asset Register - Summary



Run date: 19/08/2024

Line:

Risk Assessment Status: Active, Draft, Inactive
Hazardous Material Status: All
Hazardous Material Type: All

V044-V - VIC Line - Oxford Circus to Green Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
70991	ACTIVE	V	V044-V-SBLO	Road SBLO - VIC - Oxford Circus to Green Park	Tunnel Ring Caulking	Asbestos	Surveyed – Not Detected				Timber packing, clay between tunnel ring no 1325 RHS	10	662	R726776Rev1		
70967	ACTIVE	V	V044-V-SBLO	Road SBLO - VIC - Oxford Circus to Green Park	Boarding / Panels	Asbestos	Known	270			Open & Closed Coded Track Disconnection Box with Delta Choke Fitted - 3x Brown composite panels within - Tunnel ring No 540		1	R400230		
70968	ACTIVE	V	V044-V-SBLO	Road SBLO - VIC - Oxford Circus to Green Park	Other Electrical Boxes	Asbestos	Presumed	450		RHS	10 Core box to tunnel wall - Tunnel ring No 900		1	R400230		
70998	ACTIVE	V	V044-V-SBLO	Road SBLO - VIC - Oxford Circus to Green Park	Tunnel Ring Caulking	Asbestos	Surveyed – Not Detected	644		RHS	Timber packing, clay between tunnel rings no 1289 RHS	10		R726776Rev1		
70999	ACTIVE	V	V044-V-SBLO	Road SBLO - VIC - Oxford Circus to Green Park	Tunnel Ring Caulking	Asbestos	Known	648		RHS	Amosite and chrysotile rope/grout between tunnel rings no 1296 RHS	10		R726776Rev1		
70997	ACTIVE	V	V044-V-SBLO	Road SBLO - VIC - Oxford Circus to Green Park	Tunnel Ring Caulking	Asbestos	Surveyed – Not Detected	654		RHS	Timber packing, clay between tunnel ring no 1308 RHS	10		R726776Rev1		
70996	ACTIVE	V	V044-V-SBLO	Road SBLO - VIC - Oxford Circus to Green Park	Tunnel Ring Caulking	Asbestos	Surveyed – Not Detected	655		RHS	Timber packing, clay between Tunnel rings no 1311 RHS	10		R726776Rev1		
70995	ACTIVE	V	V044-V-SBLO	Road SBLO - VIC - Oxford Circus to Green Park	Tunnel Ring Caulking	Asbestos	Surveyed – Not Detected	660		RHS	Timber packing, clay between tunnel ring no 1320 RHS	10		R726776Rev1		
70994	ACTIVE	V	V044-V-SBLO	Road SBLO - VIC - Oxford Circus to Green Park	Tunnel Ring Caulking	Asbestos	Surveyed – Not Detected	660		RHS	Timber packing, clay between tunnel ring no 1321 RHS	10		R726776Rev1		
70993	ACTIVE	V	V044-V-SBLO	Road SBLO - VIC - Oxford Circus to Green Park	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected	661			Timber packing, clay between tunnel rings no 1323 RHS	10		R726776Rev1		
70992	ACTIVE	V	V044-V-SBLO	Road SBLO - VIC - Oxford Circus to Green Park	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected	662			Timber packing, clay between tunnel ring no 1324 RHS	10		R726776Rev1		
70990	ACTIVE	V	V044-V-SBLO	Road SBLO - VIC - Oxford Circus to Green Park	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected	664		RHS	Timber packing, clay between tunnel rings no 1328 RHS	10		R726776Rev1		
70980	DRAFT	V	V044-V-SBLO	Road SBLO - VIC - Oxford Circus to Green Park	Tunnel Ring Caulking	Asbestos	Known	680		LHS	Tunnel ring caulking where noise shelf meets metal tunnel rings. Concealed/hidden. Revealed as part of breakout works. Tunnel ring No 1280-1296 LHS			R74525		
70982	ACTIVE	V	V044-V-SBLO	Road SBLO - VIC - Oxford Circus to Green Park	Tunnel Ring Caulking	Asbestos	Known	683			Tunnel ring caulking where noise shelf meets metal tunnel rings. Concealed/hidden. Revealed as part of breakout works. Tunnel ring No 1280-1296 RHS			R74525		
70984	ACTIVE	V	V044-V-SBLO	Road SBLO - VIC - Oxford Circus to Green Park	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected	695	698	RHS	Wood/grout debris to tunnel ring flanges - Tunnel ring No 1316 RHS			R71282		
70987	ACTIVE	V	V044-V-SBLO	Road SBLO - VIC - Oxford Circus to Green Park		Asbestos	Sampled – Not Detected				Concrete, paper debris - noise shelf plinth - Tunnel ring No 1317 RHS			R712826		



Hazardous Material Asset Register - Summary



V044-V - VIC Line - Oxford Circus to Green Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
70989	ACTIVE	V	V044-V-SBLO	Road SBLO - VIC - Oxford Circus to Green Park		Asbestos	Sampled – Not Detected				Concrete, paper debris - noise shelf plinth - Tunnel ring no 1316 RHS			R712826		
70986	ACTIVE	V	V044-V-SBLO	Road SBLO - VIC - Oxford Circus to Green Park	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected	695	698	RHS	Wood/grout debris to tunnel ring flanges - Tunnel ring caulking 1318 RHS			R712826		

V047-V - VIC Line - Victoria Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
67681	ACTIVE	V	V047-V-SBLO	Road SBLO (Plt4) - VIC - Victoria Stn	Pit Blocks	Asbestos	Removed				Pit blocks throughout platform pit are non asbestos. Note: Previously identified asbestos packing was removed by DCUK project reference HM00756 2023					

V059-V - VIC Line - Brixton Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
67903	ACTIVE	V	V059-V-NBLO	Road NBLO (Plt1) - VIC - Brixton Stn	Pit Blocks	Asbestos	Surveyed – Not Detected				All pit blocks were inspected. Confirmed Non asbestos. Report Reference R672101					