



Hazardous Material Asset Register - Summary



Run date: 19/08/2024

Line:

Risk Assessment Status: Active, Draft, Inactive  
Hazardous Material Status: All  
Hazardous Material Type: All

M117-M - H&C Line - Euston Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
53579	ACTIVE	H	M117-M-IRLO	Road IRLO (Plt1) - H&C - Euston Sq Stn	Cable Sheath	Asbestos	Known	0	131	LHS	1no Asbestos sheathed cable 0-131metres to Platform Wall LHS			R401623		
53580	ACTIVE	H	M117-M-IRLO	Road IRLO (Plt1) - H&C - Euston Sq Stn	Other Electrical Boxes	Asbestos	Presumed	80			CTB Box - P - Asbestos Components within		1	R401623		
53581	ACTIVE	H	M117-M-IRLO	Road IRLO (Plt1) - H&C - Euston Sq Stn	Other Electrical Boxes	Asbestos	Presumed	87			10-Core Box - P - Asbestos components within		1	R401623		
53582	ACTIVE	H	M117-M-ORLO	Road ORLO (Plt2) - H&C - Euston Sq Stn	Other Electrical Boxes	Asbestos	Presumed	89			10-Core Box - P - Asbestos components within		1	R401624		