

## **Record of Periodic Inspection**

#### Site Details

Site Number 22/00001/U Site Type Junction

Address A238 HIGH STREET MERTON - A238 KINGSTON RD - A219 MERTON RD - A219 MORDEN RD

#### **Periodic Inspection**

Maintenance Date			
(Periodic Inspection Date)	06-Nov-2016 09:36	Engineer Name	
Inspection Type	Full	Inspection Status	COMPLETE
Controller Details	STCL T800 MK 1 UTC Cntr, Integral Facilities	Monitoring Details	UTC

#### Questionnaire

#### Visual Inspection

Visua	I Inspection	
1	Are all aspects working and clearly visible?	Yes
2	Are all aspects correctly aligned?	Yes
3	Are the Cut-away hoods in good condition and aligned correctly?	n/a
4	Are the Tunnel hoods in good condition and aligned correctly?	n/a
5	Are the Louvred hoods in good condition and aligned correctly?	n/a
6	Is the site free from see through problems?	Yes
7	Are all Reg Signs (including Secret Signs) Present, secure and working correctly?	Yes
8	Are Blind Spot Safety Mirrors fitted, aligned correctly and in good condition?	n/a
9	Is the site free from foliage obstructing traffic signal visibility and/or detector operation?	Yes
10	Are Audio/Tactiles fitted and working correctly?	Yes
11	Are all PBU's present and secure?	Yes
12	Is all Traffic Control Equipment Clean?	Yes
13	Are all post caps present and secure?	Yes
14	Is the site free from non contractual equipment (if no identify type in comments)?	No - lamp columns, bollards, corner ballards, bins, road signs, cash machine,
14.1	Identify equipment type	tube station, bike racks, CCTV. n/a
15	Is the non contractual equipment fitted in safe condition?	n/a
16	Is the site free from graffiti?	No - stickers on posts 2,7,8,8,10,11.
		stickers on PBU's 5,11. cable ties around posts 3,4,6,7,10.
		posters around posts 2,4,6.
		sticker on NRT aspect poles 4. follow up required.
17	Is the site free from any cosmetic damage?	No - copex out poles 2,3,4 (4 = x3) copex
		1xtoo short), 6,9, 4,10, 11. RM blurred poles 4,5,6,11. black paint
		cracked PBU's 1,5,7,10. yellow paint
		cracked PBU's pole 10. copex too short for alignment poles 4,10 & 11.
		follow up required.



## **Record of Periodic Inspection**

#### Site Details

Site Number 22/000001/U Site Type Junction

Address A238 HIGH STREET MERTON - A238 KINGSTON RD - A219 MERTON RD -A219 MORDEN RD

#### **Periodic Inspection**

Maintenance Date (Periodic Inspection Date) Inspection Type Controller Details	06-Nov-2016 09:36 Full STCL T800 MK 1 UTC Cntr, Integral Facilities	Engineer Name Inspection Status Monitoring Details	COMPLETE UTC
Questionnaire			
19 Are the controller, P and equipment seat	JL and ESP sealed and free from corrosion (including ducts ar ed correctly?	nd door seals) Yes	

20	Is the controller, PJL and ESP free from vermin infestation?	Yes
21	Ensure the controller, PJL and ESP are clean and free from debris.	Yes
22	Ensure all locks, including bolts are present and working correctly.	Yes
23	Is all Above Ground Detection aligned correctly and secured?	n/a
24	Is Video Detection fitted, clean and secure?	n/a
25	Are all covers, pit lids and access panels free from defects and secure?	No - pit cover by pole 4 is not properly fitted (see pic). f/up reqd - no tools to lift cover - trip hazard.
26	Is the site equipment free from any Health and Safety risk?	No - as above.
27	Confirm the operation of PE Cell (site dimming)?	n/a
28	Are all road markings clearly visible?	No - all stop lines , ped studs, cycle marks, look left & rights & centre of junction yellow box are faded & require repainting. f/up reqd.



## **Record of Periodic Inspection**

#### Site Details

Site Number 22/000001/U Site Type Junction

Address A238 HIGH STREET MERTON - A238 KINGSTON RD - A219 MERTON RD -A219 MORDEN RD

**Periodic Inspection** 

Maintenance Date

(Peric Inspe	tenance Date odic Inspection Date) otion Type oller Details	06-Nov-2016 09:36 Full STCL T800 MK 1 UTC Cntr, Integral Facilities	Engineer Name Inspection Statu Monitoring Deta	us COMPLETE
	tionnaire			
Site L	Documentation			
1	ls log book present (p	provide a new one if log book is not present or current one is ne	arly full)	Yes
2	Is the documentation missing)?	wallet present (provide a new one if the current one is defective	e or	Yes
3	ls Timing Sheet pres	ent on site correct to SFM records?		Yes
3.1	Issue No			21
4 4.1	Is current SLD preser	nt?		Yes 10
7.1				
5	Is the site layout in a	ccordance with the SLD?		Yes
6	Are all road markings	s as shown on SLD?		No - road markings have changed on site see RLD on SLD/22/001/10.
7	ls TfL Spec present (	applies only to junctions)?		Yes
7.1	Issue number of TfL S			8
8 8.1	Is the Manufacturer's Configuration number	Controller Spec present?		Yes 22001
8.2	Issue number	of Spec		9
9	Is a RAM sheet pres	ent (provide one if none present)?		No - RAM sheet left in site folder, was not one in folder. all okay.
10	Is the Loop Identificat	tion card present and correct?		Yes
11	Is the Magnetometer	Identification card present and correct?		n/a
12	Remove old issue pa	perwork and tidy remainder into document wallet.		Yes



## **Record of Periodic Inspection**

#### Site Details

Site Number 22/000001/U Site Type Junction

Address A238 HIGH STREET MERTON - A238 KINGSTON RD - A219 MERTON RD - A219 MORDEN RD

#### **Periodic Inspection**

Maintenance Date			
(Periodic Inspection Date)	06-Nov-2016 09:36	Engineer Name	
Inspection Type	Full	Inspection Status	COMPLETE
Controller Details	STCL T800 MK 1 UTC Cntr, Integral Facilities	Monitoring Details	UTC

#### Questionnaire

#### Handset/Controller Checks

Hand	set/Controller Checks	
1	Check all detection / inputs insert the correct demands?	Yes
2	Is all detection set to normal operation?	Yes
3	Is the input sense correct for each detector (e.g. Inverted for on crossing detection)?	Yes
4	Ensure Scoot detection is setup and working correctly.	Yes
5	Ensure the Speed Measurement Detection is working correctly.	n/a
6	Is the timetable for Audibles as per the specification/Ram Sheet?	Yes
7	Ensure all RAM data is correct to the latest specification / RAM sheet.	Yes
8	Ensure all timings are as per the latest timing sheet.	Yes
9	Ensure all timetable entries are as per the latest timing sheet.	No - not on timing sheet but in controller. please see questionnaire to check the diagram.FOLLOW UP REQD.
10	Ensure Controller clock settings and date are correct.	No - week = 47 changed to 44 - all okay.
11 11.1	Ensure controller mode of operation is correct. Mode of operation	Yes UTC
12 12.1	Does the manufacturers spec. match the configuration running in the controller? Note the configuration running	Yes 2209 (9)
13	Are the controller fault log/s clear?	Yes
14	For standalone pedestrian crossings (only) confirm the operation and correct wiring of the controller Red Lamp Monitoring.	n/a
15	Is the ancillary equipment operating correctly (e.g. OMU, IMU)?	No - IBUS bot receiving buses data. has site ID config okay. checked ariel receiver, called tech support (voltage). it is old model. advised to put back for follow up by d kaggwa tech support as diagnosis would take considerable time.
16	Are all changeable batteries less than 5.5 years old (i.e. if they are more than 5.5 years old they require replacement)?	Yes
17	Ensure all replaceable batteries are labelled with an install date. (Use the site controller installed date if labels not present)	Yes



## **Record of Periodic Inspection**

#### Site Details

Site Number 22/000001/U Site Type Junction

Address A238 HIGH STREET MERTON - A238 KINGSTON RD - A219 MERTON RD - A219 MORDEN RD

#### **Periodic Inspection**

Maintenance Date			
(Periodic Inspection Date)	06-Nov-2016 09:36	Engineer Name	
Inspection Type	Full	Inspection Status	COMPLETE
Controller Details	STCL T800 MK 1 UTC Cntr, Integral Facilities	Monitoring Details	UTC

#### Questionnaire

Electrical Checks

1	Take the meter reading (for sites fitted with electricity meters)	n/a
2	Check all wiring within feeder pillar particularly for conductor condition, integrity of insulation and security of all anchorages, barriers, termination/connections and components	Yes
3	Check all earth connections within the controller, ESP and PJL (where fitted) are present and tightly secured	Yes
4	Check all warning labels/circuit identification labels are not missing, damaged, or illegible	Yes
5	Confirm the Earth Fault Loop Impedance at the maintenance socket within tolerance (<= 1.47 Ohms)	Yes
5.1	Impedance (Ohms)	0.26
6	Confirm the Operation of the maintenance socket RCD - a) 0.5 x no trip	Pass
7 7.1	Confirm the Operation of the maintenance socket RCD - b) 1 x (<= 200mS) Positive Cycle	Pass 17.2
7.2	Negative Cycle	17.2
8 8.1	Confirm the Operation of the maintenance socket RCD - c) 5 x (<= 40mS) Positive Cycle	Pass 15.2
8.2	Negative Cycle	15.2
9	Confirm the Operation of the maintenance socket RCD - d) RCD trips by pushing the button	Pass
10	Confirm the Earth Fault Loop Impedance at all LV push button front covers is within tolerance. (detail any failures) - (action on failure) → Pole number / Reading / Fault Button	n/a



## **Record of Periodic Inspection**

#### Site Details

Site Number 22/000001/U Site Type Junction

Address A238 HIGH STREET MERTON - A238 KINGSTON RD - A219 MERTON RD - A219 MORDEN RD

**Periodic Inspection** 

Maintenance Date			
(Periodic Inspection Date)	06-Nov-2016 09:36	Engineer Name	
Inspection Type	Full	Inspection Status	COMPLETE
Controller Details	STCL T800 MK 1 UTC Cntr, Integral Facilities	Monitoring Details	UTC

## Questionnaire

Asset	Check	

.1	Assets	n/a
	Are all assets in accordance with the following list? (NB, assets found onsite that are in addition to the equipment list must be added by selecting the 'No' option.)	No - peek sovarota MTS4E det card. IBUS receiver on pole 2 signal head. NRT box sign (AVNSP) on pole 10. site equipment to be added to list.
.1	Rate	3
	Rate the condition of the Ancillary Equipment (e.g. RM/UTC) (1-Very Bad, 2-Poor, 3-Acceptable, 4-Good, 5-Excellent)	Yes
.1	Rate	3
	Rate the condition of the detection (1-Very Bad, 2-Poor, 3-Acceptable, 4-Good, 5-Excellent)	Yes
.1	Rate	3
	Rate the condition of the poles and infrastructure equipment (1-Very Bad, 2-Poor, 3-Acceptable, 4-Good, 5-Excellent)	Yes
.1	Rate	3
	Rate the condition of the lanterns and optical equipment (1-Very Bad, 2-Poor, 3-Acceptable, 4-Good, 5-Excellent)	Yes
.1	Rate	3
	Rate the condition of the controller and associated equipment (1-Very Bad, 2-Poor, 3- Acceptable, 4-Good, 5-Excellent)	Yes
	Rate the condition of the controller and associated equipment (1-Very Rad 2-Poor 3-	YAS

. . . . . .



### **Record of Periodic Inspection**

Site Details

Site Number 22/000001/U Site Type Junction

Address A238 HIGH STREET MERTON - A238 KINGSTON RD - A219 MERTON RD - A219 MORDEN RD

Periodic Inspection

Maintenance Date			
(Periodic Inspection Date)	06-Nov-2016 09:36	Engineer Name	
Inspection Type	Full	Inspection Status	COMPLETE
Controller Details	STCL T800 MK 1 UTC Cntr, Integral Facilities	Monitoring Details	UTC

Site Equipment List Location Details Controller Controller 1 JH0301 - Pudsey Diamond Supply Pillar, Type A JH0301 - Pudsey Diamond Supply Pillar, Type A JH0301 - Pudsey Diamond Supply Pillar, Type A JL0000 - BT Termination Post (large). PJL 841191 - STCL T800 MK 1 UTC Cntr, Integral Facilities OLM180 - Integral Comb'd Red/All Lmp Mon (SPCL) OMU111 - Siemens OMU (Bus Processor) Beacons XTU908 - IPOTU Gemini2 (Serial) and router VL4101 - Siemens ST4R 4 Channel Detector Controller Mounted VL4101 - Siemens ST4R 4 Channel Detector Controller Mounted VL4101 - Siemens ST4R 4 Channel Detector Controller Mounted Other Other 1 ZBP100 - LT Buses Bus Beacon Pole (3.5 metres) ZBP100 - LT Buses Bus Beacon Pole (3.5 metres) ZBP102 - LT Buses Bus Beacon Pole (4.2 metres) ZBP102 - LT Buses Bus Beacon Pole (4.2 metres) AVI211 - Bus Beacon, Radio Type (LT Property), SLE Mnf AVI211 - Bus Beacon, Radio Type (LT Property), SLE Mnf AVI212 - Bus Beacon, Wired Type (LT Property), SLE Mnf AVI212 - Bus Beacon, Wired Type (LT Property), SLE Mnf AVI221 - SLE Radio LAN Transmitter/Receiver (LT Property), Pole Mounted In-Road SD In-Road SD 1 VLLSCO - In-Road Detector SCOOT Loop VLLSCU - In-Road Detector Uni-Directional SCOOT Loop In-Road Non-SD In-Road Non-SD 1 VLL1LP - In-Road Detector Single Loop Pole Pole 1 PCU001 - Black Coated Pole (4.0m) Unsp LP2300 - 2 Aspect Lantern Anti-Phantom Lntn HI (Elite+) Peek HM1001 - Push Button Unit HT1K01 - Tactile Rotating Cone within Push Button (Radix) WP1501 - 1 Lamp ELV Wait Indicator (Ped Legend) Microsense Pole 2 PCU001 - Black Coated Pole (4.0m) Unsp LP3300 - 3 Aspect Anti-Phantom Lntn HI (Elite+) Peek LP3300 - 3 Aspect Anti-Phantom Lntn HI (Elite+) Peek LP2300 - 2 Aspect Lantern Anti-Phantom Lntn HI (Elite+) Peek HM1001 - Push Button Unit HT1K01 - Tactile Rotating Cone within Push Button (Radix)



## **Record of Periodic Inspection**

Site Details

Site Number 22/00001/U Site Type Junction

Address A238 HIGH STREET MERTON - A238 KINGSTON RD - A219 MERTON RD - A219 MORDEN RD

**Periodic Inspection** 

Maintenance Date			
(Periodic Inspection Date)	06-Nov-2016 09:36	Engineer Name	
Inspection Type	Full	Inspection Status	COMPLETE
Controller Details	STCL T800 MK 1 UTC Cntr, Integral Facilities	Monitoring Details	UTC

#### Site Equipment List

Location Details

ocation Details
BP3302 - NLT Box Sign Anti-Phantom (3 Tube) Peek (Elite) BSB403 - X BUSES Secret Sign (Backlite) TSUK
BSLB01 - Liquid Crystal Secret Sign "No Right Turn" Microsense
BSLB01 - Liquid Crystal Secret Sign "No Right Turn" Microsense
WP1501 - 1 Lamp ELV Wait Indicator (Ped Legend) Microsense
Pole 3
PCU001 - Black Coated Pole (4.0m) Unsp
LP2300 - 2 Aspect Lantern Anti-Phantom Lntn HI (Elite+) Peek
HM1001 - Push Button Unit
HT1K01 - Tactile Rotating Cone within Push Button (Radix)
WP1501 - 1 Lamp ELV Wait Indicator (Ped Legend) Microsense
Pole 4
PCU001 - Black Coated Pole (4.0m) Unsp
LP3300 - 3 Aspect Anti-Phantom Lntn HI (Elite+) Peek
LP3300 - 3 Aspect Anti-Phantom Lntn HI (Elite+) Peek
LP2300 - 2 Aspect Lantern Anti-Phantom Lntn HI (Elite+) Peek
LP1300 - 1 Aspect Lantern Anti-Phantom Lntn HI (Elite+) Peek
HM1001 - Push Button Unit
HT1K01 - Tactile Rotating Cone within Push Button (Radix)
BSLB01 - Liquid Crystal Secret Sign "No Right Turn" Microsense
WP1501 - 1 Lamp ELV Wait Indicator (Ped Legend) Microsense
Pole 5
PCU001 - Black Coated Pole (4.0m) Unsp
LP2300 - 2 Aspect Lantern Anti-Phantom Lntn HI (Elite+) Peek
HM1001 - Push Button Unit
HT1K01 - Tactile Rotating Cone within Push Button (Radix)
WP1501 - 1 Lamp ELV Wait Indicator (Ped Legend) Microsense
Pole 6
PCU001 - Black Coated Pole (4.0m) Unsp
LP3300 - 3 Aspect Anti-Phantom Lntn HI (Elite+) Peek
LP3300 - 3 Aspect Anti-Phantom Lntn HI (Elite+) Peek
LP3300 - 3 Aspect Anti-Phantom Lntn HI (Elite+) Peek
LP2300 - 2 Aspect Lantern Anti-Phantom Lntn HI (Elite+) Peek
HM1001 - Push Button Unit
HT1K01 - Tactile Rotating Cone within Push Button (Radix)
BP3302 - NLT Box Sign Anti-Phantom (3 Tube) Peek (Elite)
BSB401 - NRT Secret Sign (Backlite) TSUK
BSB403 - X BUSES Secret Sign (Backlite) TSUK
WP1501 - 1 Lamp ELV Wait Indicator (Ped Legend) Microsense
Pole 7
PCU001 - Black Coated Pole (4.0m) Unsp
LP2300 - 2 Aspect Lantern Anti-Phantom Lntn HI (Elite+) Peek
HM1001 - Push Button Unit
HT1K01 - Tactile Rotating Cone within Push Button (Radix)
BSB401 - NRT Secret Sign (Backlite) TSUK
WP1501 - 1 Lamp ELV Wait Indicator (Ped Legend) Microsense
Pole 8
PCU001 - Black Coated Pole (4.0m) Unsp
LP3300 - 3 Aspect Anti-Phantom Lntn HI (Elite+) Peek
LP2300 - 2 Aspect Lantern Anti-Phantom Lntn HI (Elite+) Peek



## **Record of Periodic Inspection**

Site Details

Site Number 22/00001/U Site Type Junction

Address A238 HIGH STREET MERTON - A238 KINGSTON RD - A219 MERTON RD - A219 MORDEN RD

**Periodic Inspection** 

Maintenance Date			
(Periodic Inspection Date)	06-Nov-2016 09:36	Engineer Name	
Inspection Type	Full	Inspection Status	COMPLETE
Controller Details	STCL T800 MK 1 UTC Cntr, Integral Facilities	Monitoring Details	UTC

#### Site Equipment List

Location Details

HM1001 - Push Button Unit HT1K01 - Tactile Rotating Cone within Push Button (Radix) BP3305 - TL Box Sign Anti-Phantom (3 Tube) Peek

WP1501 - 1 Lamp ELV Wait Indicator (Ped Legend) Microsense

Pole 9

PCU001 - Black Coated Pole (4.0m) Unsp

LP2300 - 2 Aspect Lantern Anti-Phantom Lntn HI (Elite+) Peek

HM1001 - Push Button Unit

HT1K01 - Tactile Rotating Cone within Push Button (Radix)

BP3305 - TL Box Sign Anti-Phantom (3 Tube) Peek

WP1501 - 1 Lamp ELV Wait Indicator (Ped Legend) Microsense Pole 10

PCU001 - Black Coated Pole (4.0m) Unsp

LP3300 - 3 Aspect Anti-Phantom Lntn HI (Elite+) Peek

LP3300 - 3 Aspect Anti-Phantom Lntn HI (Elite+) Peek

HM1001 - Push Button Unit

HT1K01 - Tactile Rotating Cone within Push Button (Radix)

BSLB01 - Liquid Crystal Secret Sign "No Right Turn" Microsense

WP1501 - 1 Lamp ELV Wait Indicator (Ped Legend) Microsense Pole 11

PCU001 - Black Coated Pole (4.0m) Unsp

LP3300 - 3 Aspect Anti-Phantom Lntn HI (Elite+) Peek

LP2300 - 2 Aspect Lantern Anti-Phantom Lntn HI (Elite+) Peek

HM1001 - Push Button Unit

HT1K01 - Tactile Rotating Cone within Push Button (Radix)

WP1501 - 1 Lamp ELV Wait Indicator (Ped Legend) Microsense