



# Hazardous Material Asset Register - Detail for SharePoint



The purpose of this report is to detail the presence of any known (K), Presumed (P) or Strongly Presumed (SP) Asbestos Containing Materials (ACMs) within this location / asset. Any areas inaccessible during previous asbestos surveys are presumed (P) to contain ACMs until confirmed otherwise. All inaccessible areas will need to be surveyed prior to work being undertaken in these areas. Prior to any intrusive works commencing a Hazardous Materials Impact Assessment (F6048) must be submitted to hazardousmaterials@tfl.gov.uk All staff / contractors working on this property must remain vigilant during their works and if any suspect material is encountered which is likely to be disturbed, contact the Hazardous Materials team prior to continuing the impacted works. Associated photographs can be found listed against the Maximo Reference number on the subsequent report.

Run date: 07/12/2022 Line: JNP Assessment Status: All Material Status: All Material Type: All

Ref.	Status	Status Date	Main Line	Location Code	Location Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Positio	Notes	Qty. Metre	Qty. Units	Lead Paint %	Surface Code	Asbestos Type	Assessme Score	Date of Last Reinspectio	Report Ref.	Above False Ceiling	Below False Floor
<a href="#">1054</a>	ACTIVE	14/04/2014	J	B081-00-1/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Above - Supalux Tiles						0			YES	
							<b>Ref.</b>	<b>Material: Asbestos Type</b>	<b>Material : Condition Code</b>	<b>Material : Product Type</b>	<b>Material : Surface Code</b>	<b>Priority : Disturbance</b>	<b>Priority : Exposure</b>	<b>Priority : Maint. Activity</b>	<b>Priority : Occupant Activity</b>							
							1054															
<a href="#">1053</a>	ACTIVE	14/04/2014	J	B081-00-1/236/FLR-01	Floor - 1 - Passage - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Beneath - Rubber Tiles						0				YES
							<b>Ref.</b>	<b>Material: Asbestos Type</b>	<b>Material : Condition Code</b>	<b>Material : Product Type</b>	<b>Material : Surface Code</b>	<b>Priority : Disturbance</b>	<b>Priority : Exposure</b>	<b>Priority : Maint. Activity</b>	<b>Priority : Occupant Activity</b>							
							1053															
<a href="#">2401</a>	ACTIVE	14/04/2014	J	B081-00-1/291/CLG-01	Ceiling: Suspended - 1 - DSM Office - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Above - Supalux Tiles						0			YES	
							<b>Ref.</b>	<b>Material: Asbestos Type</b>	<b>Material : Condition Code</b>	<b>Material : Product Type</b>	<b>Material : Surface Code</b>	<b>Priority : Disturbance</b>	<b>Priority : Exposure</b>	<b>Priority : Maint. Activity</b>	<b>Priority : Occupant Activity</b>							
							2401															
<a href="#">2280</a>	ACTIVE	14/04/2014	J	B081-00-1/316/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Above - Supalux Tiles						0			YES	
							<b>Ref.</b>	<b>Material: Asbestos Type</b>	<b>Material : Condition Code</b>	<b>Material : Product Type</b>	<b>Material : Surface Code</b>	<b>Priority : Disturbance</b>	<b>Priority : Exposure</b>	<b>Priority : Maint. Activity</b>	<b>Priority : Occupant Activity</b>							
							2280															
<a href="#">1056</a>	ACTIVE	14/04/2014	J	B081-00-1/316/FLR-01	Floor - 1 - Locker Room - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Beneath - Rubber Tiles						0				Yes
							<b>Ref.</b>	<b>Material: Asbestos Type</b>	<b>Material : Condition Code</b>	<b>Material : Product Type</b>	<b>Material : Surface Code</b>	<b>Priority : Disturbance</b>	<b>Priority : Exposure</b>	<b>Priority : Maint. Activity</b>	<b>Priority : Occupant Activity</b>							
							1056															
<a href="#">1058</a>	ACTIVE	14/04/2014	J	B081-00-1/317/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Above - Supalux Tiles						0			Yes	
							<b>Ref.</b>	<b>Material: Asbestos Type</b>	<b>Material : Condition Code</b>	<b>Material : Product Type</b>	<b>Material : Surface Code</b>	<b>Priority : Disturbance</b>	<b>Priority : Exposure</b>	<b>Priority : Maint. Activity</b>	<b>Priority : Occupant Activity</b>							
							1058															
<a href="#">2449</a>	ACTIVE	14/04/2014	J	B081-00-1/317/FLR-01	Floor - 1 - Locker Room - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Beneath - Rubber Tiles						0				YES
							<b>Ref.</b>	<b>Material: Asbestos Type</b>	<b>Material : Condition Code</b>	<b>Material : Product Type</b>	<b>Material : Surface Code</b>	<b>Priority : Disturbance</b>	<b>Priority : Exposure</b>	<b>Priority : Maint. Activity</b>	<b>Priority : Occupant Activity</b>							
							2449															
<a href="#">1060</a>	ACTIVE	14/04/2014	J	B081-00-1/412/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Above - Supalux						0			Yes	
							<b>Ref.</b>	<b>Material: Asbestos Type</b>	<b>Material : Condition Code</b>	<b>Material : Product Type</b>	<b>Material : Surface Code</b>	<b>Priority : Disturbance</b>	<b>Priority : Exposure</b>	<b>Priority : Maint. Activity</b>	<b>Priority : Occupant Activity</b>							
							1060															
<a href="#">1062</a>	ACTIVE	14/04/2014	J	B081-00-1/451/FLR-01	Floor - 1 - Tenancy - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Beneath - Wooden Floor						0				YES



# Hazardous Material Asset Register - Detail for SharePoint



Ref.	Status	Status Date	Main Line	Location Code	Location Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Positio	Notes	Qty. Metre	Qty. Units	Lead Paint %	Surface Code	Asbestos Type	Assessme Score	Date of Last Reinspectio	Report Ref.	Above False Ceiling	Below False Floor	
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							1062																
<a href="#">1063</a>	ACTIVE	14/04/2014	J	B081-00-1/452/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Above - Supalux Tiles						0				yes	
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							1063																
<a href="#">2525</a>	ACTIVE	14/04/2014	J	B081-00-1/452/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Above - Supalux Tiles						0				yes	
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							2525																
<a href="#">1065</a>	ACTIVE	14/04/2014	J	B081-00-1/488/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Above - Supalux						0				yes	
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							1065																
<a href="#">20226</a>	ACTIVE	23/06/2014	J	B081-00-1/663	Switch Cupboard - Station Building - Stanmore Stn	Other Electrical Boxes	Asbestos	Presumed				Electrical box					Encapsulated medium density materials	Chrysotile	5				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							20226	1	0	2	1	1	0	0	0								
<a href="#">2402</a>	ACTIVE	28/04/2015	J	B081-00-1/951	Disused Room - Station Building - Stanmore Stn	No Access	Asbestos	No Access: Presumed				Room Not Surveyed						0					
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							2402																
<a href="#">1071</a>	ACTIVE	14/04/2014	J	B081-00-2/011/CLG-01	Ceiling: Solid - 1 - Ticket Office - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Above - Plasterboard						0				Yes	
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							1071																
<a href="#">1072</a>	ACTIVE	14/04/2014	J	B081-00-2/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Beneath - Rubber Tiles						0					YES
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							1072																
<a href="#">1073</a>	ACTIVE	14/04/2014	J	B081-00-2/021/CLG-01	Ceiling: Solid - 1 - POM - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Above - Plasterboard						0				Yes	
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							1073																
<a href="#">1074</a>	ACTIVE	14/04/2014	J	B081-00-2/021/FLR-01	Floor - 1 - POM - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Beneath - Rubber Tiles						0					YES



# Hazardous Material Asset Register - Detail for SharePoint



Ref.	Status	Status Date	Main Line	Location Code	Location Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Positio	Notes	Qty. Metre	Qty. Units	Lead Paint %	Surface Code	Asbestos Type	Assessme Score	Date of Last Reinspectio	Report Ref.	Above False Ceiling	Below False Floor	
							<b>Ref.</b>	<b>Material: Asbestos Type</b>	<b>Material : Condition Code</b>	<b>Material : Product Type</b>	<b>Material : Surface Code</b>	<b>Priority : Disturbance</b>	<b>Priority : Exposure</b>	<b>Priority : Maint. Activity</b>	<b>Priority : Occupant Activity</b>								
							1074																
<a href="#">2454</a>	ACTIVE	14/04/2014	J	B081-00-2/031/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Above - Plasterboard						0				Yes	
							<b>Ref.</b>	<b>Material: Asbestos Type</b>	<b>Material : Condition Code</b>	<b>Material : Product Type</b>	<b>Material : Surface Code</b>	<b>Priority : Disturbance</b>	<b>Priority : Exposure</b>	<b>Priority : Maint. Activity</b>	<b>Priority : Occupant Activity</b>								
							2454																
<a href="#">1077</a>	ACTIVE	14/04/2014	J	B081-00-2/081/FLR-01	Floor - 1 - Lobby - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Beneath - Rubber Tiles						0				YES	
							<b>Ref.</b>	<b>Material: Asbestos Type</b>	<b>Material : Condition Code</b>	<b>Material : Product Type</b>	<b>Material : Surface Code</b>	<b>Priority : Disturbance</b>	<b>Priority : Exposure</b>	<b>Priority : Maint. Activity</b>	<b>Priority : Occupant Activity</b>								
							1077																
<a href="#">45152</a>	ACTIVE	18/06/2020	J	B081-00-2/261	Platform 1 - Northbound Local - Station Building - Stanmore Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Track - Signalling Equipment					Asbestos reinforced composites	Chrysotile	4	02/09/2004		N	N
							<b>Ref.</b>	<b>Material: Asbestos Type</b>	<b>Material : Condition Code</b>	<b>Material : Product Type</b>	<b>Material : Surface Code</b>	<b>Priority : Disturbance</b>	<b>Priority : Exposure</b>	<b>Priority : Maint. Activity</b>	<b>Priority : Occupant Activity</b>								
							45152	1	0	1	0	2											
<a href="#">45153</a>	ACTIVE	18/06/2020	J	B081-00-2/332	Store - Station Building - Stanmore Stn	Cement Cowlings/Flues	Asbestos	Known				Cement Cowl to External Wall (Platform 2 Side) - Amosite & Chrysotile					Encapsulated medium density materials	Amphibole excluding crocidolite	4	19/07/2019		N	N
							<b>Ref.</b>	<b>Material: Asbestos Type</b>	<b>Material : Condition Code</b>	<b>Material : Product Type</b>	<b>Material : Surface Code</b>	<b>Priority : Disturbance</b>	<b>Priority : Exposure</b>	<b>Priority : Maint. Activity</b>	<b>Priority : Occupant Activity</b>								
							45153	2	0	1	1												
<a href="#">1099</a>	ACTIVE	23/06/2014	J	B081-00-2/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Stanmore Stn	Isolator Switches	Asbestos	Strongly Presumed				5 x Isolator Switches - 1 x 30 amps, & 3 x 60 amps, & 1 x 100 amps	5				Encapsulated medium density materials	Chrysotile	8	28/01/2002			
							<b>Ref.</b>	<b>Material: Asbestos Type</b>	<b>Material : Condition Code</b>	<b>Material : Product Type</b>	<b>Material : Surface Code</b>	<b>Priority : Disturbance</b>	<b>Priority : Exposure</b>	<b>Priority : Maint. Activity</b>	<b>Priority : Occupant Activity</b>								
							1099	1	0	2	1	1	1	1	1							1	
<a href="#">1100</a>	ACTIVE	23/06/2014	J	B081-00-2/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Stanmore Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x Isolator Switches - 1 x 60 amps	1				Encapsulated medium density materials	Chrysotile	8	28/01/2002			
							<b>Ref.</b>	<b>Material: Asbestos Type</b>	<b>Material : Condition Code</b>	<b>Material : Product Type</b>	<b>Material : Surface Code</b>	<b>Priority : Disturbance</b>	<b>Priority : Exposure</b>	<b>Priority : Maint. Activity</b>	<b>Priority : Occupant Activity</b>								
							1100	1	0	2	1	1	1	1	1							1	
<a href="#">2460</a>	ACTIVE	23/06/2014	J	B081-00-2/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Stanmore Stn	Isolator Switches	Asbestos	Strongly Presumed				8 x Isolator Switches - 7 x 60 amps, & 1 x 200 amps	8				Encapsulated medium density materials	Chrysotile	8	28/01/2002			
							<b>Ref.</b>	<b>Material: Asbestos Type</b>	<b>Material : Condition Code</b>	<b>Material : Product Type</b>	<b>Material : Surface Code</b>	<b>Priority : Disturbance</b>	<b>Priority : Exposure</b>	<b>Priority : Maint. Activity</b>	<b>Priority : Occupant Activity</b>								
							2460	1	0	2	1	1	1	1	1							1	
<a href="#">1101</a>	ACTIVE	28/04/2015	J	B081-00-2/661/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Stanmore Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1 x Transformer Box	1				Asbestos reinforced composites	Chrysotile	7	28/01/2002			



# Hazardous Material Asset Register - Detail for SharePoint



Ref.	Status	Status Date	Main Line	Location Code	Location Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Positio	Notes	Qty. Metre	Qty. Units	Lead Paint %	Surface Code	Asbestos Type	Assessme Score	Date of Last Reinspectio	Report Ref.	Above False Ceiling	Below False Floor
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							1101	1	0	2	0	1	1	1	1							
<a href="#">20224</a>	ACTIVE	28/04/2015	J	B081-00-2/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Stanmore Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				2x Tencore Boxes				Asbestos reinforced composites	Chrysotile	5				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							20224	1	0	1	0	1	1	0	1							
<a href="#">1102</a>	ACTIVE	23/06/2014	J	B081-00-2/662/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Stanmore Stn	Isolator Switches	Asbestos	Strongly Presumed				1no Switch Boxes - Wall 3 Insulation within (1x30amps)	1			Encapsulated medium density materials	Chrysotile	8	28/01/2002			
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							1102	1	0	2	1	1	1	0	2							
<a href="#">1103</a>	ACTIVE	23/06/2014	J	B081-00-2/662/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Stanmore Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es)	3			Asbestos reinforced composites	Chrysotile	7	12/07/2012			
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							1103	1	0	2	0	1	1	0	2							
<a href="#">1092</a>	ACTIVE	28/04/2015	J	B081-10-2/411/WAL-001	Wall: Internal - 1 - Store - Signals Building - Stanmore Stn	LUL Heaters	Asbestos	Strongly Presumed				1977 Heat oven Heater	1			Encapsulated medium density materials	Chrysotile	7	24/03/2009			
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							1092	1	0	1	1	1	1	1	1							
<a href="#">2461</a>	ACTIVE	28/04/2015	J	B081-10-2/665/WAL-001	Wall: Internal - 1 - Switch Room - Signals Building - Stanmore Stn	Isolator Switches	Asbestos	Strongly Presumed				4x Switch Boxes - Wall 1 (3x60amp, 1x 30amp)	4			Encapsulated medium density materials	Chrysotile	10	28/01/2002			
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							2461	1	1	2	1	1	1	1	2							
<a href="#">1105</a>	ACTIVE	28/04/2015	J	B081-10-2/665/WAL-002	Wall: Internal - 2 - Switch Room - Signals Building - Stanmore Stn	Cable Ducts: Bitumen	Asbestos	Presumed				2x Bitumen Ducts to external wall	2			Encapsulated medium density materials	Chrysotile	7	24/03/2009			
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							1105	1	1	1	1	1	0	1	1							
<a href="#">27450</a>	ACTIVE	12/05/2022	J	B081-J-SBLO	Road SBLO (Plt2) - JUB - Stanmore to Buffer	Westinghouse Boxes	Asbestos	Presumed	0		LHS	Trackside equipment westinghouse small Manage. To be reinspected in 12 months 30/03/2017	1			Asbestos reinforced composites	Chrysotile	6	10/12/2008			
												Notes from 2021 re-inspection: Tencore										



# Hazardous Material Asset Register - Detail for SharePoint



Ref.	Status	Status Date	Main Line	Location Code	Location Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Positio	Notes	Qty. Metre	Qty. Units	Lead Paint %	Surface Code	Asbestos Type	Assessme Score	Date of Last Reinspectio	Report Ref.	Above False Ceiling	Below False Floor
							<b>Ref.</b>	<b>Material: Asbestos Type</b>	<b>Material : Condition Code</b>	<b>Material : Product Type</b>	<b>Material : Surface Code</b>	<b>Priority : Disturbance</b>	<b>Priority : Exposure</b>	<b>Priority : Maint. Activity</b>	<b>Priority : Occupant Activity</b>							
							27450	1	0	1	0	1	1	1	1							
<a href="#">25979</a>	ACTIVE	12/05/2022	J	B081-J-SBLO	Road SBLO (Plt2) - JUB - Stanmore to Buffer	Signal Boxes	Asbestos	Presumed	23		LHS	Trackside equipment tencore box Manage. To be reinspected in 12 months 30/03/2017	2			Asbestos reinforced composites	Chrysotile	6	10/12/2008			
							<b>Ref.</b>	<b>Material: Asbestos Type</b>	<b>Material : Condition Code</b>	<b>Material : Product Type</b>	<b>Material : Surface Code</b>	<b>Priority : Disturbance</b>	<b>Priority : Exposure</b>	<b>Priority : Maint. Activity</b>	<b>Priority : Occupant Activity</b>							
							25979	1	0	1	0	1	1	1	1							
<a href="#">25981</a>	ACTIVE	12/05/2022	J	B081-J-SBLO	Road SBLO (Plt2) - JUB - Stanmore to Buffer	Signal Boxes	Asbestos	Presumed	45		LHS	Trackside equipment tencore box Manage. To be reinspected in 12 months 30/03/2017	1			Asbestos reinforced composites	Chrysotile	6	10/12/2008			
							<b>Ref.</b>	<b>Material: Asbestos Type</b>	<b>Material : Condition Code</b>	<b>Material : Product Type</b>	<b>Material : Surface Code</b>	<b>Priority : Disturbance</b>	<b>Priority : Exposure</b>	<b>Priority : Maint. Activity</b>	<b>Priority : Occupant Activity</b>							
							25981	1	0	1	0	1	1	1	1							
<a href="#">27432</a>	ACTIVE	12/05/2022	J	B081-J-SBLO	Road SBLO (Plt2) - JUB - Stanmore to Buffer	Signal Boxes	Asbestos	Presumed	57		LHS	Trackside equipment tencore box Manage. To be reinspected in 12 months 30/03/2017	1			Asbestos reinforced composites	Chrysotile	6	10/12/2008			
							<b>Ref.</b>	<b>Material: Asbestos Type</b>	<b>Material : Condition Code</b>	<b>Material : Product Type</b>	<b>Material : Surface Code</b>	<b>Priority : Disturbance</b>	<b>Priority : Exposure</b>	<b>Priority : Maint. Activity</b>	<b>Priority : Occupant Activity</b>							
							27432	1	0	1	0	1	1	1	1							

## Hazardous Materials - Photographs for SharePoint

Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

<b>Reference:</b>	1054	
<b>Description:</b>	Asbestos: No Access: Presumed B081-00-1/236/CLG-01: Ceiling: Suspended - 1 - Passage - Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	Void	
<b>Comments:</b>	Above - Supalux Tiles	
<b>Reference:</b>	1053	
<b>Description:</b>	Asbestos: No Access: Presumed B081-00-1/236/FLR-01: Floor - 1 - Passage - Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	Void	
<b>Comments:</b>	Beneath - Rubber Tiles	
<b>Reference:</b>	2401	
<b>Description:</b>	Asbestos: No Access: Presumed B081-00-1/291/CLG-01: Ceiling: Suspended - 1 - DSM Office - Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	Void	
<b>Comments:</b>	Above - Supalux Tiles	
<b>Reference:</b>	2280	
<b>Description:</b>	Asbestos: No Access: Presumed B081-00-1/316/CLG-01: Ceiling: Suspended - 1 - Locker Room - Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	Void	
<b>Comments:</b>	Above - Supalux Tiles	

Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

<b>Reference:</b>	1056	
<b>Description:</b>	Asbestos: No Access: Presumed B081-00-1/316/FLR-01: Floor - 1 - Locker Room - Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	Void	
<b>Comments:</b>	Beneath - Rubber Tiles	
<b>Reference:</b>	1058	
<b>Description:</b>	Asbestos: No Access: Presumed B081-00-1/317/CLG-01: Ceiling: Suspended - 1 - Locker Room - Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	Void	
<b>Comments:</b>	Above - Supalux Tiles	
<b>Reference:</b>	2449	
<b>Description:</b>	Asbestos: No Access: Presumed B081-00-1/317/FLR-01: Floor - 1 - Locker Room - Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	Void	
<b>Comments:</b>	Beneath - Rubber Tiles	
<b>Reference:</b>	1060	
<b>Description:</b>	Asbestos: No Access: Presumed B081-00-1/412/CLG-01: Ceiling: Solid - 1 - Store - Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	Void	
<b>Comments:</b>	Above - Supalux	

Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

<b>Reference:</b>	1062	
<b>Description:</b>	Asbestos: No Access: Presumed B081-00-1/451/FLR-01: Floor - 1 - Tenancy - Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	Void	
<b>Comments:</b>	Beneath - Wooden Floor	
<b>Reference:</b>	1063	
<b>Description:</b>	Asbestos: No Access: Presumed B081-00-1/452/CLG-01: Ceiling: Solid - 1 - Tenancy - Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	Void	
<b>Comments:</b>	Above - Supalux Tiles	
<b>Reference:</b>	2525	
<b>Description:</b>	Asbestos: No Access: Presumed B081-00-1/452/CLG-01: Ceiling: Solid - 1 - Tenancy - Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	Void	
<b>Comments:</b>	Above - Supalux Tiles	
<b>Reference:</b>	1065	
<b>Description:</b>	Asbestos: No Access: Presumed B081-00-1/488/CLG-01: Ceiling: Suspended - 1 - Lobby - Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	Void	
<b>Comments:</b>	Above - Supalux	



Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

<b>Reference:</b>	20226	
<b>Description:</b>	Asbestos: Presumed B081-00-1/663: Switch Cupboard - Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	Other Electrical Boxes	
<b>Comments:</b>	Electrical box	
<b>Reference:</b>	2402	
<b>Description:</b>	Asbestos: No Access: Presumed B081-00-1/951: Disused Room - Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	No Access	
<b>Comments:</b>	Room Not Surveyed	
<b>Reference:</b>	1071	
<b>Description:</b>	Asbestos: No Access: Presumed B081-00-2/011/CLG-01: Ceiling: Solid - 1 - Ticket Office - Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	Void	
<b>Comments:</b>	Above - Plasterboard	
<b>Reference:</b>	1072	
<b>Description:</b>	Asbestos: No Access: Presumed B081-00-2/011/FLR-01: Floor - 1 - Ticket Office - Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	Void	
<b>Comments:</b>	Beneath - Rubber Tiles	

Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

<b>Reference:</b>	1073	
<b>Description:</b>	Asbestos: No Access: Presumed B081-00-2/021/CLG-01: Ceiling: Solid - 1 - POM - Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	Void	
<b>Comments:</b>	Above - Plasterboard	
<b>Reference:</b>	1074	
<b>Description:</b>	Asbestos: No Access: Presumed B081-00-2/021/FLR-01: Floor - 1 - POM - Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	Void	
<b>Comments:</b>	Beneath - Rubber Tiles	
<b>Reference:</b>	2454	
<b>Description:</b>	Asbestos: No Access: Presumed B081-00-2/031/CLG-01: Ceiling: Solid - 1 - Mess Room - Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	Void	
<b>Comments:</b>	Above - Plasterboard	
<b>Reference:</b>	1077	
<b>Description:</b>	Asbestos: No Access: Presumed B081-00-2/081/FLR-01: Floor - 1 - Lobby - Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	Void	
<b>Comments:</b>	Beneath - Rubber Tiles	

Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

<b>Reference:</b>	45152	
<b>Description:</b>	Asbestos: Strongly Presumed B081-00-2/261: Platform 1 - Northbound Local - Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	Other Electrical Boxes	
<b>Comments:</b>	Track - Signalling Equipment	
<b>Reference:</b>	45153	
<b>Description:</b>	Asbestos: Known B081-00-2/332: Store - Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	Cement Cowlings/Flues	
<b>Comments:</b>	Cement Cowl to External Wall (Platform 2 Side) - Amosite & Chrysotile	
<b>Reference:</b>	1099	
<b>Description:</b>	Asbestos: Strongly Presumed B081-00-2/661/WAL-001: Wall: Internal - 1 - Switch Room - Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	Isolator Switches	
<b>Comments:</b>	5 x Isolater Switches - 1 x 30 amps, & 3 x 60 amps, & 1 x 100 amps	
<b>Reference:</b>	1100	
<b>Description:</b>	Asbestos: Strongly Presumed B081-00-2/661/WAL-002: Wall: Internal - 2 - Switch Room - Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	Isolator Switches	
<b>Comments:</b>	1 x Isolater Switches - 1 x 60 amps	

Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

<b>Reference:</b>	2460
<b>Description:</b>	Asbestos: Strongly Presumed B081-00-2/661/WAL-003: Wall: Internal - 3 - Switch Room - Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified
<b>Hazard Area:</b>	Isolator Switches
<b>Comments:</b>	8 x Isolater Switches - 7 x 60 amps, & 1 x 200 amps

<b>Reference:</b>	1101
<b>Description:</b>	Asbestos: Strongly Presumed B081-00-2/661/WAL-004: Wall: Internal - 4 - Switch Room Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified
<b>Hazard Area:</b>	Other Electrical Boxes
<b>Comments:</b>	1 x Transformer Box

<b>Reference:</b>	20224
<b>Description:</b>	Asbestos: Strongly Presumed B081-00-2/662/WAL-002: Wall: Internal - 2 - Switch Room Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified
<b>Hazard Area:</b>	Other Electrical Boxes
<b>Comments:</b>	2x Tencore Boxes

Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

<b>Reference:</b>	1102
<b>Description:</b>	Asbestos: Strongly Presumed B081-00-2/662/WAL-003: Wall: Internal - 3 - Switch Roo Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified
<b>Hazard Area:</b>	Isolator Switches
<b>Comments:</b>	1no Switch Boxes - Wall 3 Insulation within (1x30amps)

<b>Reference:</b>	1103
<b>Description:</b>	Asbestos: Presumed B081-00-2/662/WAL-003: Wall: Internal - 3 - Switch Roo Station Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified
<b>Hazard Area:</b>	Other Electrical Boxes
<b>Comments:</b>	Transformer Box(es)

<b>Reference:</b>	1092
<b>Description:</b>	Asbestos: Strongly Presumed B081-10-2/411/WAL-001: Wall: Internal - 1 - Store - Signals Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified
<b>Hazard Area:</b>	LUL Heaters
<b>Comments:</b>	1977 Heat oven Heater



Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

<b>Reference:</b>	2461	
<b>Description:</b>	Asbestos: Strongly Presumed B081-10-2/665/WAL-001: Wall: Internal - 1 - Switch Room - Signals Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	Isolator Switches	
<b>Comments:</b>	4x Switch Boxes - Wall 1 (3x60amp, 1x 30amp)	
<b>Reference:</b>	1105	
<b>Description:</b>	Asbestos: Presumed B081-10-2/665/WAL-002: Wall: Internal - 2 - Switch Room - Signals Building - Stanmore Stn <b>Start(m):</b> Not Specified <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	Cable Ducts: Bitumen	
<b>Comments:</b>	2x Bitumen Ducts to external wall	
<b>Reference:</b>	27450	
<b>Description:</b>	Asbestos: Presumed B081-J-SBLO: Road SBLO (Plt2) - JUB - Stanmore to Buffer <b>Start(m):</b> 0 <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	Westinghouse Boxes	
<b>Comments:</b>	Trackside equipment westinghouse small Manage. To be reinspected in 12 months 30/03/2017  Notes from 2021 re-inspection: Tencore	
<b>Reference:</b>	25979	
<b>Description:</b>	Asbestos: Presumed B081-J-SBLO: Road SBLO (Plt2) - JUB - Stanmore to Buffer <b>Start(m):</b> 23 <b>Finish(m):</b> Not Specified	
<b>Hazard Area:</b>	Signal Boxes	
<b>Comments:</b>	Trackside equipment tencore box Manage. To be reinspected in 12 months 30/03/2017	



Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

<b>Reference:</b>	25981
<b>Description:</b>	Asbestos: Presumed B081-J-SBLO: Road SBLO (Plt2) - JUB - Stanmore to Buffe <b>Start(m): 45 Finish(m): Not Specified</b>
<b>Hazard Area:</b>	Signal Boxes
<b>Comments:</b>	Trackside equipment tencore box Manage. To be reinspected in 12 months 30/03/2017
<b>Reference:</b>	27432
<b>Description:</b>	Asbestos: Presumed B081-J-SBLO: Road SBLO (Plt2) - JUB - Stanmore to Buffe <b>Start(m): 57 Finish(m): Not Specified</b>
<b>Hazard Area:</b>	Signal Boxes
<b>Comments:</b>	Trackside equipment tencore box Manage. To be reinspected in 12 months 30/03/2017