



Hazardous Material Asset Register - Detail for SharePoint



The purpose of this report is to detail the presence of any known (K), Presumed (P) or Strongly Presumed (SP) Asbestos Containing Materials (ACMs) within this location / asset. Any areas inaccessible during previous asbestos surveys are presumed (P) to contain ACMs until confirmed otherwise. All inaccessible areas will need to be surveyed prior to work being undertaken in these areas. Prior to any intrusive works commencing a Hazardous Materials Impact Assessment (F6048) must be submitted to [redacted]@tfl.gov.uk All staff / contractors working on this property must remain vigilant during their works and if any suspect material is encountered which is likely to be disturbed, contact the Hazardous Materials team prior to continuing the impacted works. Associated photographs can be found listed against the Maximo Reference number on the subsequent report.

Run date: 20/02/2024 Line: JNP Assessment Status: All Material Status: All Material Type: All

Ref.	Status	Status Date	Main Line	Location Code	Location Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Positio	Notes	Qty. Metre	Qty. Units	Lead Paint %	Surface Code	Asbestos Type	Assessme Score	Date of Last Reinspectio	Report Ref.	Above False Ceiling	Below False Floor	
27738	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Cable Sheath	Asbestos	Known	0		RHS	Woven cable sheath, Entry: platform wall, route: JH1 2x15mmØ, OTX 1x45mmØ Notes from 2021 re-inspection: No cable OTC on JH 1		3		Unencapsula medium density or encapsulated highly friable materials	Chrysotile	8	23/10/2008				
27739	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Cable Sheath	Asbestos	Known	3	418	LHS	Woven cable sheath, Entry: OTX, route: 1x45mmØ JH5		1		Unencapsula medium density or encapsulated highly friable materials	Chrysotile	9	23/10/2008				
27740	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	4		RHS	Trackside equipment Westinghouse small					Chrysotile	1	23/10/2008				
27741	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	9		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008				
68506	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Signal Boxes	Asbestos	Presumed	91		RHS	Trackside equipment: Type 79		1			Chrysotile	1					
35015	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	154		RHS	Trackside equipment Westinghouse small					Chrysotile	1	23/10/2008				
27751	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Ducts	Asbestos	Presumed	450		LHS	Cable Ducts		7			Chrysotile	1	03/05/2013				



Hazardous Material Asset Register - Detail for SharePoint



Ref.	Status	Status Date	Main Line	Location Code	Location Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Positio	Notes	Qty. Metre	Qty. Units	Lead Paint %	Surface Code	Asbestos Type	Assessme Score	Date of Last Reinspectio	Report Ref.	Above False Ceiling	Below False Floor	
27755	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	610		RHS	Trackside equipment Westinghouse large 623 GR Tencore x 1 Notes from 2021 re-inspection: LWH remains, 10 core removed		1			Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							27755	1															
27757	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	611		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							27757	1															
27756	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	611		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							27756	1															
27759	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	613		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							27759	1															
27761	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	614		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							27761	1															
27762	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	614		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							27762	1															
27764	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	617		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							27764	1															
27765	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	639		RHS	Trackside equipment Westinghouse small					Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							27765	1															
27767	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	778		RHS	Trackside equipment Westinghouse small					Chrysotile	1	23/10/2008				



Hazardous Material Asset Register - Detail for SharePoint



Ref.	Status	Status Date	Main Line	Location Code	Location Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Positio	Notes	Qty. Metre	Qty. Units	Lead Paint %	Surface Code	Asbestos Type	Assessme Score	Date of Last Reinspectio	Report Ref.	Above False Ceiling	Below False Floor	
							Ref.	Material: Asbestos Type			Material : Condition Code	Material : Product Type	Material : Surface Code			Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity				
							27767	1															
27768	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	782		RHS	Trackside equipment Westinghouse small					Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type			Material : Condition Code	Material : Product Type	Material : Surface Code			Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity				
							27768	1															
35016	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Signal Boxes	Asbestos	Presumed	929		RHS	Trackside equipment type 79					Chrysotile	1	03/05/2013				
							Ref.	Material: Asbestos Type			Material : Condition Code	Material : Product Type	Material : Surface Code			Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity				
							35016	1															
35567	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Signal Boxes	Asbestos	Known	1052	1064	RHS	Signal section cloth, Entry: trackside equipmentboxes, route: 5-15mmØ in between trackside equipment boxes					Unencapsula medium density or encapsulated highly friable materials	Chrysotile	8	23/10/2008			
							Ref.	Material: Asbestos Type			Material : Condition Code	Material : Product Type	Material : Surface Code			Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity				
							35567	1		1	2	2	2										
27769	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	1053		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type			Material : Condition Code	Material : Product Type	Material : Surface Code			Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity				
							27769	1															
27770	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	1053		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type			Material : Condition Code	Material : Product Type	Material : Surface Code			Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity				
							27770	1															
27771	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	1054		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type			Material : Condition Code	Material : Product Type	Material : Surface Code			Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity				
							27771	1															
27772	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	1054		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type			Material : Condition Code	Material : Product Type	Material : Surface Code			Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity				
							27772	1															
27773	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	1055		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type			Material : Condition Code	Material : Product Type	Material : Surface Code			Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity				
							27773	1															
27777	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	1124		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008				



Hazardous Material Asset Register - Detail for SharePoint



Ref.	Status	Status Date	Main Line	Location Code	Location Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Positio	Notes	Qty. Metre	Qty. Units	Lead Paint %	Surface Code	Asbestos Type	Assessme Score	Date of Last Reinspectio	Report Ref.	Above False Ceiling	Below False Floor	
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							27777	1															
27776	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Signal Boxes	Asbestos	Known	1124	1311	RHS	Trackside equipment section cloth, Entry: trackside equipment boxes, route: 5-15mmØ in between trackside equipment boxes.				Unencapsula highly friable	Chrysotile	12	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							27776	1	3	2	3	3											
27778	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	1125		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							27778	1															
27779	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	1126		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							27779	1															
27782	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	1127		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							27782	1															
27783	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	1128		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							27783	1															
35017	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	1129		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							35017	1															
27784	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	1129		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							27784	1															
27788	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Cable Sheath	Asbestos	Known	1326		RHS	Woven cable sheath, Entry: OTX/service duct, route: 3x15mmØ between JH3-4, exit: trackside equipment boxes		3		Unencapsula medium density or encapsulated highly friable materials	Chrysotile	8	23/10/2008				







Hazardous Material Asset Register - Detail for SharePoint



Ref.	Status	Status Date	Main Line	Location Code	Location Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Positio	Notes	Qty. Metre	Qty. Units	Lead Paint %	Surface Code	Asbestos Type	Assessme Score	Date of Last Reinspectio	Report Ref.	Above False Ceiling	Below False Floor
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							27788	1	1	2	2	2										
27792	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	1330		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008			
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							27792	1														
27790	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	1330		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008			
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							27790	1														
27791	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	1330		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008			
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							27791	1														
27795	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	1347		LHS	Rail gap indicator Notes from 2021 re-inspection: Trackside equipment westinghouse large		1			Chrysotile	1	03/05/2013			
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							27795	1														
27796	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	1350		RHS	Trackside equipment Westinghouse small					Chrysotile	1	23/10/2008			
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							27796	1														
27798	ACTIVE	20/02/2024	N	N126-N-SBFA	Road SBFA - NOR - Angel to Old Street	Westinghouse Boxes	Asbestos	Presumed	1352		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008			
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							27798	1														

Hazardous Materials - Photographs for SharePoint





Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	27738	
Description:	Asbestos: Known N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 0 Finish(m): Not Specified	
Hazard Area:	Cable Sheath	
Comments:	Woven cable sheath, Entry: platform wall, route: JH1 2x15mmØ, OTX 1x45mmØ Notes from 2021 re-inspection: No cable OTC on JH 1	
Reference:	27739	
Description:	Asbestos: Known N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 3 Finish(m): 418	
Hazard Area:	Cable Sheath	
Comments:	Woven cable sheath, Entry: OTX, route: 1x45mmØ JH5	
Reference:	27740	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 4 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse small	
Reference:	27741	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 9 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	





Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	68506	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 91 Finish(m): Not Specified	
Hazard Area:	Signal Boxes	
Comments:	Trackside equipment: Type 79	
Reference:	35015	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 154 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse small	
Reference:	27751	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 450 Finish(m): Not Specified	
Hazard Area:	Ducts	
Comments:	Cable Ducts	
Reference:	27755	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 610 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large 623 GR Tencore x 1 Notes from 2021 re-inspection: LWH remains, 10 core removed	





Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	27756	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 611 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	27757	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 611 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	27759	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 613 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	27761	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 614 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	

Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	27762	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 614 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	27764	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 617 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	27765	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 639 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse small	
Reference:	27767	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 778 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse small	




Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	27768	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 782 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse small	
Reference:	35016	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 929 Finish(m): Not Specified	
Hazard Area:	Signal Boxes	
Comments:	Trackside equipment type 79	
Reference:	35567	
Description:	Asbestos: Known N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 1052 Finish(m): 1064	
Hazard Area:	Signal Boxes	
Comments:	Signal section cloth, Entry: trackside equipmentboxes, route: 5-15mmØ in between trackside equipment boxes	
Reference:	27769	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 1053 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	



Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	27770	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 1053 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	27771	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 1054 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	27772	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 1054 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	27773	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 1055 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	

Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	27777	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 1124 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	27776	
Description:	Asbestos: Known N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 1124 Finish(m): 1311	
Hazard Area:	Signal Boxes	
Comments:	Trackside equipment section cloth, Entry: trackside equipment boxes, route: 5-15mmØ in between trackside equipment boxes.	
Reference:	27778	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 1125 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	27779	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 1126 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	



Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	27782	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 1127 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	27783	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 1128 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	27784	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 1129 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	35017	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 1129 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	

Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	27788	
Description:	Asbestos: Known N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 1326 Finish(m): Not Specified	
Hazard Area:	Cable Sheath	
Comments:	Woven cable sheath, Entry: OTX/service duct, route; 3x15mmØ between JH3-4, exit: trackside equipment boxes	
Reference:	27792	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 1330 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	27791	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 1330 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	27790	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 1330 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	

Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	27795	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 1347 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Rail gap indicator Notes from 2021 re-inspection: Trackside equipment westinghouse large	
Reference:	27796	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 1350 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse small	
Reference:	27798	
Description:	Asbestos: Presumed N126-N-SBFA: Road SBFA - NOR - Angel to Old Street Start(m): 1352 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	