

**From:** Davis Aaron (ST) [REDACTED] tfl [REDACTED]  
**Sent:** 16 March 2021 13:27  
**To:** [REDACTED] conwayaecom.com>  
**Cc:** O'Rourke Robert [REDACTED] tfl [REDACTED]  
**Subject:** RE: A40 Westway average speed camera system.

Hi [REDACTED]

I've had a look on the A40 and A3220 at the signs for the new 30mph enforcement zone.

Thanks for getting the 30mph signs done on the A3220 (although I'm not sure about the carriageway roundels?) and the 40mph signs done on the A40 westbound exit. However there are still 40mph signs on the Wood Lane gantry that require removing as this is still part of the new 30mph zone. Are these being planned to be removed?

Regards

Aaron

**From:** [REDACTED] conwayaecom.com>  
**Sent:** 10 March 2021 14:30  
**To:** Davis Aaron (ST) [REDACTED] tfl [REDACTED]  
**Subject:** RE: A40 Westway average speed camera system.

Aaron,

Hopefully the remaining signs will be completed by the end of the week

Regards,

[REDACTED]  
**Operations Planner**  
[REDACTED]

**From:** Davis Aaron (ST) [REDACTED] tfl [REDACTED]  
**Sent:** 10 March 2021 14:26  
**To:** [REDACTED] conwayaecom.com>  
**Subject:** FW: A40 Westway average speed camera system.

**External Message:** Do not click or open links or attachments unless you recognise the sender and know the content is safe.

Hi [REDACTED]

Any news on the remaining signs?

Regards

Aaron

**From:** Davis Aaron (ST)  
**Sent:** 03 March 2021 15:25  
**To:** [REDACTED] conwayaecom.com>

Cc: [REDACTED] <[\[REDACTED\]@conwayaecom.com](mailto:[REDACTED]@conwayaecom.com)>; O'Rourke Robert  
[REDACTED] <[\[REDACTED\]@tfl](mailto:[REDACTED]@tfl)> Bawn Darrell [REDACTED] <[\[REDACTED\]@tfl](mailto:[REDACTED]@tfl)>  
Subject: RE: A40 Westway average speed camera system.

Hi [REDACTED]

I'm not sure if you still had works to complete on both the A40 and A3220 but upon driving it today there were a few items still missing.

- A3220 Northbound nearside 30mph sign missing
- A3220 Northbound carriageway roundels
- A40 Westbound exit – The 40mph speed limit should begin where, on the opposing carriageway, the 30mph begins. Therefore the 40mph signs as you rejoin the A40 from Wood Lane and on the gantry should be further back or removed.

Could you let me know when you are able to complete these works so we can make the limit fully enforceable.

I've reattached the supporting document with the proposed location points.

Regards

Aaron

From: [REDACTED] <[\[REDACTED\]@conwayaecom.com](mailto:[REDACTED]@conwayaecom.com)>  
Sent: 24 February 2021 16:10  
To: Davis Aaron (ST) [REDACTED] <[\[REDACTED\]@tfl](mailto:[REDACTED]@tfl)>  
Subject: RE: A40 Westway average speed camera system.

Aaron,

I have been speaking with the night supervisors about installing the signs this weekend. I am speaking with them again tonight and I will send you an update later this evening

Regards,

[REDACTED]  
**Operations Planner**  
[REDACTED]

From: Davis Aaron (ST) [REDACTED] <[\[REDACTED\]@tfl](mailto:[REDACTED]@tfl)>  
Sent: 24 February 2021 16:00  
To: [REDACTED] <[\[REDACTED\]@conwayaecom.com](mailto:[REDACTED]@conwayaecom.com)>  
Subject: FW: A40 Westway average speed camera system.

**External Message:** Do not click or open links or attachments unless you recognise the sender and know the content is safe.

Hi [REDACTED]

Do you have a date for the signage work on the Westway yet?

Regards

Aaron

From: Davis Aaron (ST)  
Sent: 16 February 2021 15:10  
To: [REDACTED] <[REDACTED]@conwayaecom.com>  
Cc: [REDACTED] <[REDACTED]@conwayaecom.com>; O'Rourke Robert  
[REDACTED] <[REDACTED]@tfl>  
Subject: RE: A40 Westway average speed camera system.

Hi [REDACTED]

Thanks for that but are you able to give us a firm date so we can include it in any comms that we have to put out? We have the traffic order signed off so it is just down to the signing to make it legal and enforceable.

Regards

Aaron

From: [REDACTED] <[REDACTED]@conwayaecom.com>  
Sent: 09 February 2021 13:26  
To: Davis Aaron (ST) <[REDACTED]@tfl>  
Cc: [REDACTED] <[REDACTED]@conwayaecom.com>  
Subject: RE: A40 Westway average speed camera system.

Aaron,

We are aiming to start these works at the beginning of March

Regards,

[REDACTED]  
**Operations Planner**  
[REDACTED]

From: [REDACTED] <[REDACTED]@conwayaecom.com>  
Sent: 08 February 2021 15:25  
To: [REDACTED] <[REDACTED]@conwayaecom.com>  
Subject: FW: A40 Westway average speed camera system.  
Importance: High

Hi [REDACTED]

Can you respond back to Aaron please.

Thanks

[REDACTED]  
**Core Services Manager**  
**CONWAY AECOM**  
**29 North Acton Road**  
**London**  
**NW106PE**  
[REDACTED]



From: Davis Aaron (ST) [redacted] [tfl](#) [redacted]  
Sent: 08 February 2021 15:03  
To: [redacted] [conwayaecom.com](#)>  
Subject: RE: A40 Westway average speed camera system.

External Message: Do not click or open links or attachments unless you recognise the sender and know the content is safe.

Hi [redacted]

Do we have any timescales yet for the works?

Regards

Aaron

From: [redacted] [conwayaecom.com](#)>  
Sent: 03 February 2021 10:45  
To: [redacted] [conwayaecom.com](#)>  
Cc: [redacted] [conwayaecom.com](#)>; Davis Aaron (ST) [redacted] [tfl](#)  
Subject: FW: A40 Westway average speed camera system.  
Importance: High

Hi [redacted]

We need to plan this in on the Westway and get [redacted] involved with a Mewp.

Thanks

[redacted]  
**Core Services Manager**  
**CONWAY AECOM**  
**29 North Acton Road**  
**London**  
**NW106PE**





From: [REDACTED] <[\[REDACTED\]@conwayaecom.com](mailto:[REDACTED]@conwayaecom.com)>  
Sent: 28 January 2021 13:05  
To: [REDACTED] <[\[REDACTED\]@kaspasigns.co.uk](mailto:[REDACTED]@kaspasigns.co.uk)>  
Cc: [REDACTED] <[\[REDACTED\]@conwayaecom.com](mailto:[REDACTED]@conwayaecom.com)>; [REDACTED] <[\[REDACTED\]@conwayaecom.com](mailto:[REDACTED]@conwayaecom.com)>  
Subject: FW: A40 Westway average speed camera system.  
Importance: High

Good Afternoon [REDACTED]

Hope you are well

Can you please quote for the following signs as per below email, as per the attached

30 mph  
40 mph

Qty to be confirmed

*As these limits are short term can the illumination for the terminal signs can be:*  
1) LED solar battery backed.  
2) Done in pairs so the same type of illumination is on the nearside and offside.

**Kind Regards**

[REDACTED]  
**Fleet and Depot Manager  
Conway Aecom Ltd  
29 North Acton Road, NW10 6PE**

[REDACTED]



THINK BEFORE YOU PRINT - SAVE PAPER

From: [REDACTED] <[\[REDACTED\]@conwayaecom.com](mailto:[REDACTED]@conwayaecom.com)>  
Sent: 28 January 2021 12:58  
To: [REDACTED] <[\[REDACTED\]@conwayaecom.com](mailto:[REDACTED]@conwayaecom.com)>  
Subject: FW: A40 Westway average speed camera system.  
Importance: High

Hi [REDACTED]

Can you see if you can get a price for the 2 items below and more 30mph and 40mph signs see Attached.

Thanks

[REDACTED]  
**Core Services Manager**  
**CONWAY AECOM**  
**29 North Acton Road**  
**London**  
**NW106PE**



From: Davis Aaron (ST) [REDACTED] <[\[REDACTED\]@tfl](mailto:[REDACTED]@tfl)>  
Sent: 15 January 2021 11:27  
To: [REDACTED] <[\[REDACTED\]@conwayaecom.com](mailto:[REDACTED]@conwayaecom.com)>  
Cc: Robert Orourke TFL [REDACTED] <[\[REDACTED\]@tfl](mailto:[REDACTED]@tfl)>; [REDACTED] <[\[REDACTED\]@conwayaecom.com](mailto:[REDACTED]@conwayaecom.com)>  
Subject: RE: A40 Westway average speed camera system.

**External Message:** Do not click or open links or attachments unless you recognise the sender and know the content is safe.

Hi [REDACTED]

I've just raised a task order NW8\_HTO/312 for additional 30mph and 40mph signage on the A40 and A3220 to ensure we can fully enforce the temporary speed limit.

Richard Nunn, one of our colleagues who deals with the enforcement cameras, has taken some photos on his dashcam of the required sign locations and also added them onto some drawings. I've added these photos to the order but I've also attached to this mail. For the

30mph signs on the northbound A3220 could they be placed 5m north of the bridge overhang.

Also they've requested that,

*As these limits are short term can the illumination for the terminal signs can be:*

- 1) LED solar battery backed.
- 2) Done in pairs so the same type of illumination is on the nearside and offside.

Is it possible we could get this priced and installed as soon as possible as they are keen to get this enforceable?

Regards

Aaron

From: [REDACTED] <[REDACTED]@conwayaecom.com>  
Sent: 11 December 2020 06:17  
To: [REDACTED] <[REDACTED]@conwayaecom.com>; [REDACTED] <[REDACTED]@conwayaecom.com>  
Cc: Davis Aaron (ST) <[REDACTED]@tfl.gov.uk>; O'Rourke Robert <[REDACTED]@[REDACTED]>  
Subject: RE: A40 Westway average speed camera system.  
Importance: High

Hi [REDACTED],

Thank you if you could put it on a spreadsheet for us please.

Thanks

[REDACTED]  
**Core Services Manager**  
**CONWAY AECOM**  
**29 North Acton Road**  
**London**  
**NW106PE**  
[REDACTED]



From: [REDACTED] <[\[REDACTED\]@conwayaecom.com](mailto:[REDACTED]@conwayaecom.com)>  
Sent: 11 December 2020 01:15  
To: [REDACTED] <[\[REDACTED\]@conwayaecom.com](mailto:[REDACTED]@conwayaecom.com)>; [REDACTED]  
<[\[REDACTED\]@conwayaecom.com](mailto:[REDACTED]@conwayaecom.com)>  
Cc: Aaron Davis TFL [REDACTED] <[\[REDACTED\]@tfl.gov.uk](mailto:[REDACTED]@tfl.gov.uk)>; Robert Orourke TFL  
[REDACTED]  
Subject: RE: A40 Westway average speed camera system.

[REDACTED]

I will arrange someone to carry out a survey and measure up the signs on Saturday night.

Regards,

[REDACTED]

CONWAY AECOM

[REDACTED]

North Acton Lane | Park Royal | London | NW10 6PE



From: [REDACTED]  
Sent: 10 December 2020 14:50  
To: [REDACTED] <[\[REDACTED\]@conwayaecom.com](mailto:[REDACTED]@conwayaecom.com)>; [REDACTED]  
<[\[REDACTED\]@conwayaecom.com](mailto:[REDACTED]@conwayaecom.com)>  
Cc: Aaron Davis TFL [REDACTED] <[\[REDACTED\]@tfl.gov.uk](mailto:[REDACTED]@tfl.gov.uk)>; Robert Orourke TFL  
[REDACTED]  
Subject: FW: A40 Westway average speed camera system.  
Importance: High

Hi [REDACTED]

Please see Aaron's email below, can you get someone to carry out a survey and measure up the signs.

Thanks

[REDACTED]

**Core Services Manager**  
**CONWAY AECOM**  
**29 North Acton Road**  
**London**  
**NW106PE**

[REDACTED]





**From:** Davis Aaron ([redacted] [tfl](#))  
**Sent:** 10 December 2020 12:53  
**To:** [redacted] [conwayaecom.com](mailto:conwayaecom.com)>  
**Cc:** Robert Orourke TFL [redacted]  
**Subject:** FW: A40 Westway average speed camera system.

**External Message:** Do not click or open links or attachments unless you recognise the sender and know the content is safe.

Hi [redacted]

Are you able to provide details and a schedule of the 30mph signs that have been installed on the Westway as per the request below?

Regards

Aaron

**From:** O'Rourke Robert [redacted] [tfl](#)  
**Sent:** 10 December 2020 09:58  
**To:** Nunn Richard (ST) [redacted] [tfl](#); Davis Aaron (ST) [redacted] [tfl](#)  
**Cc:** Skelton Phil (ST) [redacted] [tfl](#); Lockett Felicity (ST) [redacted] [tfl](#); Steward Gary (ST) [redacted] [tfl](#); Bawn Darrell [redacted] [tfl](#); Lumley Mark [redacted] [tfl](#)  
**Subject:** RE: A40 Westway average speed camera system.

Richard

Thanks for this.

Aaron can please ask for CA to provide details and a schedule of the 30mph signs that have been installed, I am sure we have the date of the TMO. If they do not have all the sign details there is a closure of the Westway this weekend and they can carryout a survey and measure up the signs.

Richard the speed limit has been in place for more than six months so I do not think it would be advisable to erect the new speed limit in force signs unless we need to change the limits of the 30mph zone.

Regards Robert

**From:** Lumley Mark [redacted] <[redacted]@tfl>  
**Sent:** 09 December 2020 15:31  
**To:** O'Rourke Robert [redacted] <[redacted]@tfl>; Davis Aaron (ST) [redacted] <[redacted]@tfl>; Bawn Darrell [redacted] <[redacted]@tfl>; Steward Gary (ST) [redacted] <[redacted]@tfl>  
**Cc:** Skelton Phil (ST) [redacted] <[redacted]@tfl>; Nunn Richard (ST) [redacted] <[redacted]@tfl>; Lockett Felicity (ST) [redacted] <[redacted]@tfl>  
**Subject:** RE: A40 Westway average speed camera system.  
**Importance:** High

Rob / Aaron / Darrell / Gary

Not sure if anyone is able to respond to Richard as soon as possible as tis is high on Carl's list and t may be that Richard has managed to find a solution.

Thanks

Kind Regards

**Mark Lumley**  
ITS Operations Manager – NM Asset Operations

**From:** Nunn Richard (ST) <Richard.Nunn@tfl>  
**Sent:** 08 December 2020 09:32  
**To:** O'Rourke Robert [redacted] <[redacted]@tfl>; Davis Aaron (ST) [redacted] <[redacted]@tfl>  
**Cc:** Lumley Mark [redacted] <[redacted]@tfl>; Skelton Phil (ST) [redacted] <[redacted]@tfl>  
**Subject:** FW: A40 Westway average speed camera system.

Rob,  
Aaron,

A40 Westway.

I have listed the 878 sign locations and sizes and sent yesterday to the Met for comment. (Survey done on Google Apr 2019 capture)

Being enforcement would take place on a road that doesn't look or feel like a 30 means they need to ensure enough 878 warning signs exist.

The next key issue is the 30mph 670s / 1065s which is tricky on this section due to some existing Lamp columns in parts of the links.

What I could do with is a location of the temp 30s installed, details of sizes and illumination of any Terminals.

Do you have the dates they TMO came in force taking out the 40 limit.

I wondered if at the entry points we could use 7032 signs. They have a 6 month max on street period from time of new 30 implemented and used for unlit sections.

West bound is unlit at entry.

# NEW 30 MPH SPEED LIMIT IN FORCE


Figure 8-12 Diagram 7032 (S13-6-38)  
New 30 mph speed limit in force

878 SIGNS EXISTING ON A40 AND 2 ON SLIPS

WEST BOUND EXISTING 878.1 ASC										
		WEST SIGNS INSIDE SPEED CHK WEST BOUND	ADJ TO	LOC	E	N	DISTANCE ON A40	DISTANCE ON SLIP		
1	ENTRY	SHURTY WITH CAMERA	by Padd Gm	LARGE	gantry	526803	181695	start		
2	ENTRY	Balled to LIC	Padd onslip	SMALL	LC	526942	181803	start		
3	RPTR	Balled to cites	Q2 Western Rd	SMALL	cites	525055	181609	1800	950	
4	RPTR	Balled to cites	Matton Road	SMALL	cites	524120	181321	1130		



EAST BOUND EXISTING 878.1 ASC										
		EAST SIGNS INSIDE SPEED CHK EAST BOUND	ADJ TO	LOC	E	N	DISTANCE ON A40	DISTANCE ON SLIP		
1	ENTRY	A40 STARTING POINT	by Padd Gm	LARGE	LC	526803	181695	start		
2	ENTRY	WOOD LANE ON SLIP	A40 Flyover	Small	LC	521194	181095	1250	950	
3	RPTR	Balled to cites	Matton Road	SMALL	cites	524120	181321	1130		
4	RPTR	Balled to cites	Q2 Western Rd	SMALL	cites	525055	181829			
1	ENTRY	MISSING 878 ENTRY SIGN ON WEST X ROUTE	opp Shallwell Dr	SMALL	cites	524120	181321	800		
2	RPTR	Balled to cites	Matton Road	SMALL	cites	524120	181321	800		



Will arrange a meeting once I have enough information regarding the existing 670 / 1065 signs and locations.

Regards Richard

PPD ITS

**From:** Nunn Richard (ST)  
**Sent:** 04 December 2020 14:48  
**To:** O'Rourke Robert [tfl]  
**Cc:** Davis Aaron (ST) [tfl]  
**Subject:** A40 Westway average speed camera system.

Rob,

I have been asked to assist with the average speed camera system on the A40 Westway to make it enforceable for the temp 30mph restriction.

I have discussed the current camera network with the Police at Sidcup and have left voice mails with Siemens to get an update with the current system.

Once Siemens respond I need to make contact to discuss signage and the boundary requirements for the 30 limit and TMOs.


Having just installed the A10 ASC system in Enfield I have an understanding of the current signage requirements. The signage for road works needs looking at in more detail as one issue here is not being street lit.

I will make contact once I have the technical details from Siemens to ensure the system will operate as required.


If yourself or Aaron have any information crucial to getting this implemented at this early stage for me picking this up please do not hesitate to call.

Regards Richard

---

 Fri 14/09/2020 15:37  
O'Rourke Robert  
FW: 3607 - A40 Westway (between West Cross Route and Royal Oak), Demag Joint Load Mitigation Access: Stage 2 Road Safety Audit

To: Luntley Mark  
Cc: Davis Aaron (ST)  
This message was sent with High Importance.

 3607\_A40\_Westway\_Emergency\_Measure.docx  
3 MB

---

Mark

We have now received the stage 2 safety report relating to the use of the Maurer plates on the Westway. As previously indicated it is essential that the 30mph speed limit on the Westway is fully enforceable.

As previously discussed we are happy to move the start points and end points of the limit to match the average speed camera sections. However we do need confirmation of the required locations so we can redraft the order and move the signs.

I am on leave next week but I would be grateful if you would liaise with Aaron (copied) to confirm the exact points required.

Regards Robert

**Richard Nunn** FIHE

Assistant Project Manager – ITS and Lighting



**TRANSPORT FOR LONDON**

Surface Transport | Projects and Programmes Directorate | Asset Renewals and Upgrades  
Palestra House | [REDACTED] | 197 Blackfriars Road | London SE1 8NJ



\*\*\*\*\*

The contents of this e-mail and any attached files are confidential. If you have received this email in error, please notify us immediately at [postmaster@tfl.gov.uk](mailto:postmaster@tfl.gov.uk) and remove it from your system. If received in error, please do not use, disseminate, forward, print or copy this email or its content. Transport for London excludes any warranty and any liability as to the quality or accuracy of the contents of this email and any attached files.

Transport for London is a statutory corporation whose principal office is at 5 Endeavour Square, London, E20 1JN. Further information about Transport for London's subsidiary companies can be found on the following link: <http://www.tfl.gov.uk/corporate/about-tfl/>

Although TfL have scanned this email (including attachments) for viruses, recipients are advised to carry out their own virus check before opening any attachments, as TfL accepts no liability for any loss, or damage which may be caused by viruses.

\*\*\*\*\*