

Incident Reporting Form

Reference Number IRF001009828

Initiated By: ISF000290247

Incident Details

Date: 10-Jun-2019

Time: 7:28

Day: Monday

Station or site name: Hillingdon

Line or Department: Piccadilly (JNP)

Initial delay

There was an initial delay of 3 minutes

Train Specific Information

Train set number: 246

Stock type: 1973

Car number: 174

Direction: East

No cancellation

No station specific information reported for this IRF**Staff involved in incident**

Surname: [REDACTED]

First name: [REDACTED]

Staff No.: 9813811

Grade: TO21

Gender: M

Location: TOM NORTHFIELDS

Involvement: Central to Incident

Recorded On Holistic Report Yes No

Duty Number: TOp

Surname: [REDACTED]

First name: [REDACTED]

Staff No.: 3685112

Grade: ILIS

Gender: M

Location: CIRCLE & HAMM SCM

Involvement: Assisted

Recorded On Holistic Report Yes No

Duty Number: LIS

Surname: [REDACTED]

First name: [REDACTED]

Staff No.: 9847096

Grade: TO21

Gender: M

Location: TOM NORTHFIELDS

Involvement: Central to Incident

Recorded On Holistic Report Yes No

Duty Number: TOp

Other people involved in incident: None**There were no related injuries****There were no related Traction current arrangements****No consequential cancellation or reformation****No crime committed****No fire or smoke****No assets involved****No SPAD was reported as part of this IRF****A near miss did not occur****Incident Description :-** Delayed departure

At Hillingdon doors failed to open on T246 TOp instructed to carry on to Ickenham, Piccadilly SC informed & they contacted T246

TOp advised to trip & reset door open MCB. This done doors opened & T246 continued eastbound with no further issue Memo requested from TOp1

Train download requested

A delay of three minutes was recorded

Further DRM spoke with TOp1.

TOp1 did not bring T242 from depot, DRM & TOp discussed doors failing to open & TOp1 will in future, in addition to other door checks, check MCBs & reset if required.

TOp2 who did bring T242 from Northfields depot stated that they may have cut out the door open MCBs & were not aware of the change in policy regarding these MCBs, DRM & TOp2 discussed this & TOp2 now aware, no further action required

Findings of immediate investigation (basic cause) :- Staff error

Person responsible for filing this IRF: - [REDACTED]