



Hazardous Material Asset Register - Summary



Run date: 19/08/2024

Line:

Risk Assessment Status: Active, Draft, Inactive
Hazardous Material Status: All
Hazardous Material Type: All

B071-00 - Station Building - Paddington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
48551	ACTIVE	H	B071-00-2/002	Booking Hall - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boxing and panels in false ceiling and to walls and ceiling			R329701	Y	
48433	ACTIVE	H	B071-00-2/003	Booking Hall - Station Building - Paddington Stn	Mastic	Asbestos	Sampled – Not Detected				Concrete render to ceiling - Throughout Sampled 2no. times			R656151		
48524	ACTIVE	H	B071-00-2/011	POM - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels to wall above ticket office window in false ceiling			R329701	Y	
48424	ACTIVE	H	B071-00-2/012	Office - Station Building - Paddington Stn	Mastic	Asbestos	Sampled – Not Detected				Concrete render to ceiling and beams - throughout			R656151		
48528	ACTIVE	H	B071-00-2/012/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Ticket Office - Supalux ceiling tiles to suspended ceiling			R329701		
48527	ACTIVE	H	B071-00-2/012/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Toilet - Supalux ceiling tiles to suspended ceiling			R329701		
48508	ACTIVE	H	B071-00-2/013	Station Supervisors Office - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels and boxing in false ceiling to walls and ceiling			R329701	Y	
48507	ACTIVE	H	B071-00-2/013/CLG-01	Ceiling: Suspended - 1 - Station Supervisors Office - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux ceiling tiles to suspended ceiling			R329701		
48529	ACTIVE	H	B071-00-2/023/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux ceiling tiles to suspended ceiling			R329701		
48517	ACTIVE	H	B071-00-2/024	POM - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boxing and panels within false ceiling to walls and ceiling			R329701	Y	
48516	ACTIVE	H	B071-00-2/024/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux ceiling tiles to suspended ceiling			R329701		
48422	ACTIVE	H	B071-00-2/032	Mess Room - Station Building - Paddington Stn	Mastic	Asbestos	Sampled – Not Detected				Concrete render to ceiling and beams - throughout			R656151		
48531	ACTIVE	H	B071-00-2/032/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux ceiling tiles to suspended ceiling			R329701		
48530	ACTIVE	H	B071-00-2/032/FLR-01	Floor - 1 - Mess Room - Station Building - Paddington Stn	Vinyl tiles	Asbestos	Sampled – Not Detected				Blue floor tiles to floor - 6m²	6		R329701		
48511	ACTIVE	H	B071-00-2/033	Mess/Locker - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boxing and panel in false ceiling to walls and ceiling			R329701	Y	



Hazardous Material Asset Register - Summary



B071-00 - Station Building - Paddington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
48509	ACTIVE	H	B071-00-2/033	Mess/Locker - Station Building - Paddington Stn	LUL Heaters	Asbestos	Sampled – Not Detected				Lining to LTB heater unit (Asset number B071 018) - 1no.		1	R329701		
48510	ACTIVE	H	B071-00-2/033/CLG-02	Ceiling: Suspended - 1 - Mess/Locker - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux ceiling tiles to suspended ceiling			R329701		
48425	ACTIVE	H	B071-00-2/037	Toilet - Station Building - Paddington Stn	Mastic	Asbestos	Sampled – Not Detected				Concrete render to ceiling and beams - throughout			R656151		
48533	ACTIVE	H	B071-00-2/037/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux ceiling tiles to suspended ceiling			R329701		
48532	ACTIVE	H	B071-00-2/037/FLR-01	Floor - 1 - Toilet - Station Building - Paddington Stn	Vinyl tiles	Asbestos	Sampled – Not Detected				Blue floor tiles to floor - 4m²	4		R329701		
48513	ACTIVE	H	B071-00-2/038	Lobby - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boxing and panels within false ceiling to walls and ceiling			R329701	Y	
48512	ACTIVE	H	B071-00-2/038/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux ceiling tiles to suspended ceiling			R329701		
48515	ACTIVE	H	B071-00-2/039	Toilet - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boxing and panels within false ceiling to walls and ceiling			R329701	Y	
48514	ACTIVE	H	B071-00-2/039/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux ceiling tiles to suspended ceiling			R329701		
48552	ACTIVE	H	B071-00-2/072	Circulation Area - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boxing and panels in false ceiling to walls and ceiling			R329701	Y	
48434	ACTIVE	H	B071-00-2/073	Circulation Area - Station Building - Paddington Stn	Mastic	Asbestos	Sampled – Not Detected				Concrete render to ceiling - Throughout Sampled 2no. times			R656151		
48427	ACTIVE	H	B071-00-2/081	Bin Store - Station Building - Paddington Stn	Mastic	Asbestos	Sampled – Not Detected				Concrete render to ceiling and beams - throughout			R656151		
48537	ACTIVE	H	B071-00-2/151	UMC - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels to walls and to the ceiling where the voids are, especially by escalator 1			R329701		
48538	ACTIVE	H	B071-00-2/151	UMC - Station Building - Paddington Stn	Caulking	Asbestos	Sampled – Not Detected				Grout/wood/caulking to flanges of tunnel rings to walls - Throughout			R329701		
48536	ACTIVE	H	B071-00-2/152	UMC - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux beading to glass section of door to UMC - 2lm	2		R329701		
48435	ACTIVE	H	B071-00-2/202	Passage - Station Building - Paddington Stn	Mastic	Asbestos	Sampled – Not Detected				Concrete render to ceiling - Throughout			R656151		
48549	ACTIVE	H	B071-00-2/203	Passage - Station Building - Paddington Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Bitumen cable ducts within wall cavity to midway access hatch - 2x4			R329701		



Hazardous Material Asset Register - Summary



B071-00 - Station Building - Paddington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
48550	ACTIVE	H	B071-00-2/203	Passage - Station Building - Paddington Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Bitumen cable ducts within wall cavity access hatch, end of corridor by ramp on the ticket office side - 2x4			R329701		
48553	ACTIVE	H	B071-00-2/204	Passage - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels around access loft hatch			R329701		
48556	ACTIVE	H	B071-00-2/205	Passage - Station Building - Paddington Stn	No Access	Asbestos	No Access: Presumed				No safe access to stand on ceiling in loft area. AIB infill panels in ceiling voids previously identified in ECS4697SO1			R329701	Y	
48555	ACTIVE	H	B071-00-2/205	Passage - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels to suspended ceiling			R329701		
48548	ACTIVE	H	B071-00-2/207	Passage - Station Building - Paddington Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Bitumen cable ducts within wall cavity (cable run) opposite station supervisors office 2/751 - 8no.		8	R329701		
48426	ACTIVE	H	B071-00-2/237	Passage - Station Building - Paddington Stn	Mastic	Asbestos	Sampled – Not Detected				Concrete render to ceiling and beams - throughout			R656151		
48534	ACTIVE	H	B071-00-2/237	Passage - Station Building - Paddington Stn	Vinyl tiles	Asbestos	Sampled – Not Detected				Blue floor tiles to floor - 8m²			R329701		
48535	ACTIVE	H	B071-00-2/237/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux ceiling tiles to suspended ceiling			R329701		
48429	ACTIVE	H	B071-00-2/238	Passage - Station Building - Paddington Stn	Mastic	Asbestos	Sampled – Not Detected				Concrete render to ceiling and beams - throughout			R656151		
48519	ACTIVE	H	B071-00-2/239	Lobby - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boxing and panels in suspended ceiling to air conditioning			R329701	Y	
48518	ACTIVE	H	B071-00-2/239/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux ceiling tiles to suspended ceiling			R329701		
48492	ACTIVE	H	B071-00-2/240	Lobby - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Fixed supalux panels to suspended ceiling and stairs			R329701		
48470	ACTIVE	H	B071-00-2/241/FLR-01	Floor - 1 - Locker Room - Station Building - Paddington Stn	Vinyl tiles	Asbestos	Known				Red floor tiles to floor - 8m²	8		R329701		
48471	ACTIVE	H	B071-00-2/241/FLR-01	Floor - 1 - Locker Room - Station Building - Paddington Stn	Vinyl tiles	Asbestos	Known				Beige floor tiles to floor - 12m²	12		R329701		
48472	ACTIVE	H	B071-00-2/241/WAL-004	Wall: Internal - 4 - Locker Room - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels above door to wall 4			R329701		
48496	ACTIVE	H	B071-00-2/242	Lobby - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boxing to wall by room 2.732			R329701		
48495	ACTIVE	H	B071-00-2/242	Lobby - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels to lower level ceiling downstairs			R329701		



Hazardous Material Asset Register - Summary



B071-00 - Station Building - Paddington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
48497	ACTIVE	H	B071-00-2/242	Lobby - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panel above door 3/731			R329701		
48498	ACTIVE	H	B071-00-2/242	Lobby - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boxing/panels to wall by the ticket hall door, wall, ceiling			R329701		
68116	ACTIVE	H	B071-00-2/261	Platform 1 - Station Building - Paddington Stn	Void	Asbestos	Surveyed – Not Detected				No identified ACMs behind cable trunking and green panels					
48554	ACTIVE	H	B071-00-2/261	Platform 1 - Station Building - Paddington Stn	Glazing Rope	Asbestos	Sampled – Not Detected				Rope to skylight at high level - Throughout			R329701		
48559	ACTIVE	H	B071-00-2/262	Platform 2 - Station Building - Paddington Stn	Other Electrical Boxes	Asbestos	Presumed				Presumed ACM's within switchboxes to wall - 5no.		5	R329701		
68117	ACTIVE	H	B071-00-2/262	Platform 2 - Station Building - Paddington Stn	Void	Asbestos	Surveyed – Not Detected				No identified ACMs behind cable trunking and green panels			R679612		
48421	ACTIVE	H	B071-00-2/262	Platform 2 - Station Building - Paddington Stn	Debris: Other	Asbestos	Sampled – Not Detected				Panel/board debris in cess under Platform 2 - 1m²	1		R623626		Y
48430	ACTIVE	H	B071-00-2/291	Office - Station Building - Paddington Stn	Mastic	Asbestos	Sampled – Not Detected				Concrete render to ceiling and beams - throughout			R656151		
48525	ACTIVE	H	B071-00-2/316	Mess/Locker - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boxing and panels in false ceiling to walls and ceiling			R329701	Y	
48483	ACTIVE	H	B071-00-2/331	Mess Room - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels to wall & ceiling in false ceiling The ceiling panels were presumed to contain asbestos in report ECS4697SO1			R329701		
48457	ACTIVE	H	B071-00-2/341	Mess Room - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux ceiling tiles to half of suspended ceiling			R329701		
48458	ACTIVE	H	B071-00-2/341	Mess Room - Station Building - Paddington Stn	LUL Heaters	Asbestos	Sampled – Not Detected				Lining to LTB heater unit (Asset number B071 007) - <1m²	1		R329701		
48431	ACTIVE	H	B071-00-2/351	Kitchen - Station Building - Paddington Stn	Mastic	Asbestos	Sampled – Not Detected				Concrete render to ceiling and beams - throughout			R656151		
48428	ACTIVE	H	B071-00-2/401	SVC - Station Building - Paddington Stn	Mastic	Asbestos	Sampled – Not Detected				Concrete render to ceiling and beams - throughout			R656151		
48436	ACTIVE	H	B071-00-2/402	Bin Store - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels to suspended ceiling			R329701		
48432	ACTIVE	H	B071-00-2/413	Store - Station Building - Paddington Stn	Mastic	Asbestos	Sampled – Not Detected				Concrete render to ceiling and beams - throughout			R656151		
48494	ACTIVE	H	B071-00-2/418	Toilet - Station Building - Paddington Stn	Boarding: AIB	Asbestos	Presumed				Asbestos insulation board underneath heater Identified in ECS4697SO1 Not present during 2012 management survey			R329701		



Hazardous Material Asset Register - Summary



B071-00 - Station Building - Paddington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
48476	ACTIVE	H	B071-00-2/457	ATM - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Fixed supalux panels to suspended ceiling in false ceiling			R329701	Y	
48545	ACTIVE	H	B071-00-2/607	Stairs: Linear - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux debris to floor in loft space			R329701		
48547	ACTIVE	H	B071-00-2/607	Stairs: Linear - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panel to suspended ceiling at the top of the stairs			R329701		
48546	ACTIVE	H	B071-00-2/607	Stairs: Linear - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels to floor			R329701		
48463	ACTIVE	H	B071-00-2/661	Switch Room - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Fixed supalux panels to suspended ceiling			R329701		
48462	ACTIVE	H	B071-00-2/661	Switch Room - Station Building - Paddington Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Presumed ACM's within switchboxes to walls 3 & 4 - 4no.		4	R329701		
48442	ACTIVE	H	B071-00-2/662	Switch Room - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels fixed to ceiling			R329701		
48443	ACTIVE	H	B071-00-2/662	Switch Room - Station Building - Paddington Stn	No Access	Asbestos	No Access: Presumed				No access within false ceiling - Fixed suspended tiles			R329701		
48441	ACTIVE	H	B071-00-2/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Paddington Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Presumed ACM's within switchbox to wall 2			R329701		
48506	ACTIVE	H	B071-00-2/663	Switch Cupboard - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels to fixed suspended ceiling			R329701		
48505	ACTIVE	H	B071-00-2/663/WAL-002	Wall: Internal - 2 - Switch Cupboard - Station Building - Paddington Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Presumed ACM's within switchboxes and busbars to walls 2 - 4no.		4	R329701		
48503	ACTIVE	H	B071-00-2/664	Switch Room - Station Building - Paddington Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Presumed ACM's within switchboxes and busbars to walls 2 & 4 - 7no.		7	R329701		
48504	ACTIVE	H	B071-00-2/664	Switch Room - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels to fixed suspended ceiling			R329701		
48459	ACTIVE	H	B071-00-2/665	Switch Cupboard - Station Building - Paddington Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel panels to floor - 2m² No access underneath	2		R329701		
48460	ACTIVE	H	B071-00-2/665/WAL-002	Wall: Internal - 2 - Switch Cupboard - Station Building - Paddington Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Presumed ACM's within switchboxes and busbars to wall 2 - 6no.		6	R329701		
48480	ACTIVE	H	B071-00-2/666	Switch Room - Station Building - Paddington Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Bitumen cable ducts to floor by wall - 3no.			R329701		
48481	ACTIVE	H	B071-00-2/666	Switch Room - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels/boxing to ceiling, RSJ and wall			R329701		
48479	ACTIVE	H	B071-00-2/666/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Paddington Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Presumed ACM's within switchbox and busbar to wall 2			R329701		



Hazardous Material Asset Register - Summary



B071-00 - Station Building - Paddington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
48482	ACTIVE	H	B071-00-2/666/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels above door to wall 4			R329701		
48491	ACTIVE	H	B071-00-2/668	Switch Cupboard - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels to walls and suspended ceiling			R329701		
48490	ACTIVE	H	B071-00-2/669	Switch Cupboard - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels to walls and suspended ceiling			R329701		
48488	ACTIVE	H	B071-00-2/711	CER - Station Building - Paddington Stn	Other Boarding	Asbestos	Sampled – Not Detected				Brown bakelite panel to equipment to walls - throughout			R329701		
48489	ACTIVE	H	B071-00-2/711	CER - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boxing/clad to walls			R329701		
48487	ACTIVE	H	B071-00-2/711	CER - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Fixed supalux panels and boxing to suspended ceiling			R329701		
48466	ACTIVE	H	B071-00-2/712	Relay Room - Station Building - Paddington Stn	Vinyl tiles	Asbestos	Known				Green marley tiles to walls - 64m²	64		R329701		
48467	ACTIVE	H	B071-00-2/712	Relay Room - Station Building - Paddington Stn	Other Boarding	Asbestos	Known				Brown panel boxing to equipment to walls - 3no.		3	R329701		
48468	ACTIVE	H	B071-00-2/712	Relay Room - Station Building - Paddington Stn	Other Boarding	Asbestos	Known				Brown panel to equipment to centre of the room - 2no.		2	R329701		
48438	ACTIVE	H	B071-00-2/746	CER - Station Building - Paddington Stn	No Access	Asbestos	No Access: Presumed				No access within false ceiling - Fixed suspended tiles			R329701	Y	
48439	ACTIVE	H	B071-00-2/746	CER - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Air conditioning metal ductwork with supalux boxing to walls			R329701		
48437	ACTIVE	H	B071-00-2/746/CLG-01	Ceiling: Suspended - 1 - CER - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels to fixed suspended ceiling			R329701		
48440	ACTIVE	H	B071-00-2/746/FLR-01	Floor - 1 - CER - Station Building - Paddington Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Bitumen cable ducts to floor by wall 1 - 4no.		4	R329701		
48521	ACTIVE	H	B071-00-2/747	SCR - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Fixed supalux panels to ceiling and walls			R329701		
48461	ACTIVE	H	B071-00-2/761	Vent Shaft - Station Building - Paddington Stn	Mastic	Asbestos	Sampled – Not Detected				Non asbestos gators air conditioning ductwork - 5no.		5	R329701		
48469	ACTIVE	H	B071-00-2/762	Store - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux boxing above door - 1m²	1		R329701		
48464	ACTIVE	H	B071-00-2/765/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Paddington Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Presumed ACM's within switchbox to wall 1 - 1no.		1	R329701		
48465	ACTIVE	H	B071-00-2/765/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels to wall 4 in false ceiling			R329701	Y	



Hazardous Material Asset Register - Summary



B071-00 - Station Building - Paddington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
48526	ACTIVE	H	B071-00-2/771	Pump Room - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boxing to wall 1			R329701		
48520	ACTIVE	H	B071-00-2/787	Cable Shaft - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panel to walls and ceiling			R329701		
48523	ACTIVE	H	B071-00-2/901	Station Control Room - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels to walls and in false ceiling			R329701	Y	
48522	ACTIVE	H	B071-00-2/901	Station Control Room - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boxing to walls and in false ceiling			R329701	Y	
48477	ACTIVE	H	B071-00-2/903/WAL-001	Wall: Internal - 1 - Lobby - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels to wall 1 above door - 2no.		2	R329701		
48484	ACTIVE	H	B071-00-2/904/CLG-01	Ceiling: Suspended - 1 - Pump Room - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panel to suspended ceiling			R329701		
48485	ACTIVE	H	B071-00-2/904/WAL-001	Wall: Internal - 1 - Pump Room - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panel to wall 1			R329701		
48473	ACTIVE	H	B071-00-2/906	Cupboard - Station Building - Paddington Stn	Vinyl tiles	Asbestos	Known				Red floor tiles to floor - 2m²	2		R329701		
48475	ACTIVE	H	B071-00-2/906	Cupboard - Station Building - Paddington Stn	No Access	Asbestos	No Access: Presumed				No access above suspended ceiling			R329701		
48474	ACTIVE	H	B071-00-2/906	Cupboard - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels to fixed suspended ceiling			R329701		
48493	ACTIVE	H	B071-00-2/951	Disused Room - Station Building - Paddington Stn	Non Asbestos Boarding	Asbestos	Surveyed – Not Detected				Non-asbestos fibreboard to walls by stairs			R329701		
48486	ACTIVE	H	B071-00-2/952	Disused Room - Station Building - Paddington Stn	Non Asbestos Boarding	Asbestos	Surveyed – Not Detected				Non-asbestos fibreboard to ceiling and stairs			R329701		
48478	ACTIVE	H	B071-00-2/953/WAL-002	Wall: Internal - 2 - Store - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panel door to wall 2			R329701		
48539	ACTIVE	H	B071-00-3/161	LMC - Station Building - Paddington Stn	Caulking	Asbestos	Sampled – Not Detected				Grout/wood/caulking to flanges of tunnel rings to walls - Throughout			R329701		
48540	ACTIVE	H	B071-00-3/162	Pump Room - Station Building - Paddington Stn	Caulking	Asbestos	Sampled – Not Detected				Grout/wood/caulking to flanges of tunnel rings to walls - Throughout			R329701		
68985	ACTIVE	H	B071-00-3/263	Platform 3 - Station Building - Paddington Stn	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Invert - Grout - To tunnel rings flanges throughout.			R718678		
48544	ACTIVE	H	B071-00-3/263	Platform 3 - Station Building - Paddington Stn	Gasket :Pipework	Asbestos	Presumed				Gasket to pipework fire hydrant by room 3/406			R329701		
68982	ACTIVE	H	B071-00-3/263	Platform 3 - Station Building - Paddington Stn	Debris: Cement	Asbestos	Known				Invert - Loose cement panel debris - <1m - To floor in pit 5, next to room 3/706	1		R718678		Y



Hazardous Material Asset Register - Summary



B071-00 - Station Building - Paddington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
68118	ACTIVE	H	B071-00-3/263	Platform 3 - Station Building - Paddington Stn	Void	Asbestos	Surveyed – Not Detected				No identified ACMs behind cable trunking and green panels			R679612		
68984	ACTIVE	H	B071-00-3/263	Platform 3 - Station Building - Paddington Stn	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Invert - Metal tunnel rings - concrete infill - To walls, floor throughout.			R718678		
68983	ACTIVE	H	B071-00-3/263	Platform 3 - Station Building - Paddington Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen cable ducts - total 1 no - To platform wall in pit 5, next to room 3/706.		1	R718678		Y
68119	ACTIVE	H	B071-00-3/264	Platform 4 - Station Building - Paddington Stn	Void	Asbestos	Surveyed – Not Detected				No identified ACMs behind cable trunking and green panels			R679612		
48542	ACTIVE	H	B071-00-3/264	Platform 4 - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panel outer wall (wall 1) of the store 3/407			R329701		
48543	ACTIVE	H	B071-00-3/264	Platform 4 - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels to roof of store 3/407			R329701		
68987	ACTIVE	H	B071-00-3/264	Platform 4 - Station Building - Paddington Stn	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Invert - Concrete - To tunnel rings flanges throughout.			R718678		
48541	ACTIVE	H	B071-00-3/264	Platform 4 - Station Building - Paddington Stn	Gasket :Pipework	Asbestos	Presumed				Gasket to pipework flange fire hydrant store between rooms 3/706 and 3/406 - 1no.		1	R329701		
68986	ACTIVE	H	B071-00-3/264	Platform 4 - Station Building - Paddington Stn	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Invert -Metal tunnel rings - concrete infill - To walls, floor throughout.			R718678		
48450	ACTIVE	H	B071-00-3/381	CER - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux panel/boxing to walls 2 & 3 - 8m²	8		R329701		
48451	ACTIVE	H	B071-00-3/381/ FLR-01	Floor - 1 - CER - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux debris to floor from boxing - <1m²	1		R329701		
48453	ACTIVE	H	B071-00-3/406	Switch Room - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panel to wall 4 by the door			R329701		
48455	ACTIVE	H	B071-00-3/407	Cupboard - Station Building - Paddington Stn	No Access	Asbestos	No Access: Presumed				No access within false ceiling - Fixed suspended tiles			R329701		
48454	ACTIVE	H	B071-00-3/407	Cupboard - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels and boxing to fixed suspended ceiling and wall 2			R329701		
48448	ACTIVE	H	B071-00-3/661	Switch Room - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels above door to wall 4 and to walls 2 & 3 where cable pass into walls			R329701		
48447	ACTIVE	H	B071-00-3/661/ FLR-01	Floor - 1 - Switch Room - Station Building - Paddington Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Bitumen cable duct to floor by wall 2 - 2no.		2	R329701		
48445	ACTIVE	H	B071-00-3/706	IMR - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels/boxing above both doors to walls and ceiling			R329701		
48446	ACTIVE	H	B071-00-3/706	IMR - Station Building - Paddington Stn	Other Boarding	Asbestos	Presumed				Brown bakelite panels to walls by desk area - 4no.		4	R329701		
48456	ACTIVE	H	B071-00-3/711/ WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Paddington Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Presumed ACM's within switchboxes to wall 4			R329701		



Hazardous Material Asset Register - Summary



B071-00 - Station Building - Paddington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
48444	ACTIVE	H	B071-00-3/712	Relay Room - Station Building - Paddington Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Presumed ACM's within electrical boxes (distribution boxes 600V) to walls 2 & 4 - 2no.		2	R329701		
48452	ACTIVE	H	B071-00-3/713/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Paddington Stn	Durasteel	Asbestos	Strongly Presumed				Durasteel panels to floor - 2m² No access underneath		1	R329701		
48449	ACTIVE	H	B071-00-3/714/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Paddington Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Presumed ACM's within electric boxes 600V to wall 3 - 3no.		3	R329701		
48499	ACTIVE	H	B071-00-3/731	CER - Station Building - Paddington Stn	Other Electrical Boxes	Asbestos	Presumed				Combination fuse boxes Identified in ECS4697SO1 Not present during 2012 management survey			R329701		
48500	ACTIVE	H	B071-00-3/731	CER - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panel above door to corridoe 2/242			R329701		
48502	ACTIVE	H	B071-00-3/902	Locker Room - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boxing to wall and ceiling			R329701		
48501	ACTIVE	H	B071-00-3/902	Locker Room - Station Building - Paddington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels to fixed suspended ceiling			R329701		

D119-00 - Station Building - Bayswater Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
69288	ACTIVE	H	D119-00-1/662	Switch Room - Station Building - Bayswater Stn	Isolator Switches	Asbestos	Strongly Presumed				Materials in combination fuse switch		1	R326457		
69301	ACTIVE	H	D119-00-2/261	Platform 1 - Station Building - Bayswater Stn	Glazing Rope	Asbestos	Strongly Presumed				Strongly presumed asbestos rope to glass canopy above staircase 1/601 & 1/603. Main canopy is concrete					
69302	ACTIVE	H	D119-00-2/262	Platform 2 - Station Building - Bayswater Stn	Glazing Rope	Asbestos	Strongly Presumed				Strongly presumed asbestos rope to glass canopy above staircase 1/602 & 1/604. Main canopy is concrete					
69307	ACTIVE	H	D119-00-2/262	Platform 2 - Station Building - Bayswater Stn	Cable Ducts: Cement	Asbestos	Known				Platform Invert - Inside - 8x Concrete cable ducts to head wall 0m		8	R498401		Y
69304	ACTIVE	H	D119-00-2/262	Platform 2 - Station Building - Bayswater Stn	Cement Troughing	Asbestos	Known				Platform Invert - Outside - Asbestos cement troughing (0.5m), under platform behind cables at 90m	1		R498401		Y
69306	ACTIVE	H	D119-00-2/262	Platform 2 - Station Building - Bayswater Stn	Cable Ducts: Cement	Asbestos	Known				Platform Invert - Inside - 8x Concrete cable ducts to head wall 92m		8	R498401		Y
69305	ACTIVE	H	D119-00-2/262	Platform 2 - Station Building - Bayswater Stn	Cement Troughing	Asbestos	Known				Platform Invert - Outside - Asbestos cement troughing (0.5m), under platform behind cables at 92m	1		R498401		Y
69289	ACTIVE	H	D119-00-2/661	Switch Room - Station Building - Bayswater Stn	Isolator Switches	Asbestos	Removed				2x blue combination fuse boxes presumed to contain asbestos insulating materials within have been removed and replaced with new electrical boxes/equipment.			R326457		



Hazardous Material Asset Register - Summary



M115-00 - Station Building - Great Portland Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
70265	ACTIVE	H	M115-00-3/261	Platform 1 - Station Building - Great Portland Street Stn	Cable Ducts: Bitumen	Asbestos	Known				Invert - Bitumen ducts - total 14 no - To east wall in east end chamber		14	R710077		Y
70266	ACTIVE	H	M115-00-3/261	Platform 1 - Station Building - Great Portland Street Stn	Cable Ducts: Bitumen	Asbestos	Known				Invert - Bitumen ducts - total 18 no - To west wall in east end chamber		18	R710077		Y
70264	ACTIVE	H	M115-00-3/261	Platform 1 - Station Building - Great Portland Street Stn	Cable Ducts: Bitumen	Asbestos	Known				Invert - Bitumen ducts - total 2 no - To soffit in east end chamber		2	R710077		Y
70272	ACTIVE	H	M115-00-3/262	Platform 2 - Station Building - Great Portland Street Stn	Cable Ducts: Bitumen	Asbestos	Known				Invert - Bitumen ducts - total 18 no - To concrete approx. 20m from west end of invert		18	R710077		Y
70267	ACTIVE	H	M115-00-3/262	Platform 2 - Station Building - Great Portland Street Stn	Cable Ducts: Bitumen	Asbestos	Known				Invert - Bitumen ducts - total 18 no - To west wall within east chamber section		18	R710077		Y
70268	ACTIVE	H	M115-00-3/262	Platform 2 - Station Building - Great Portland Street Stn	Cable Ducts: Bitumen	Asbestos	Known				Invert - Bitumen ducts - total 10 no - To east wall within east chamber section		10	R710077		Y
70269	ACTIVE	H	M115-00-3/262	Platform 2 - Station Building - Great Portland Street Stn	Cable Ducts: Bitumen	Asbestos	Known				Invert - Bitumen ducts - total 2 no - To trackside wall within east chamber section		2	R710077		Y
70271	ACTIVE	H	M115-00-3/262	Platform 2 - Station Building - Great Portland Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen ducts - total 4 no - To east wall end in main section of invert		4	R710077		Y

M117-00 - Station Building - Euston Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
53558	ACTIVE	H	M117-00-2/661/WAL-002	Wall: Internal - 2 - Switch Cupboard - Station Building - Euston Square Stn	Cable: Sheath	Asbestos	Presumed				1mL Asbestos Bitumen Cable Wrap - Presumed	1		R375751		
53557	ACTIVE	H	M117-00-2/661/WAL-002	Wall: Internal - 2 - Switch Cupboard - Station Building - Euston Square Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Box - SP Asbestos components within			R375751		
68891	ACTIVE	H	M117-00-2/776	Fan Room - Station Building - Euston Square Stn	Bitumen	Asbestos	Sampled – Not Detected				Resin residues to floor	1				
53578	ACTIVE	H	M117-00-2/776	Fan Room - Station Building - Euston Square Stn		Asbestos	Sampled – Not Detected				The following items within this room have been sampled and confirmed non-asbestos: White compound / fire stop - Walls 1 & 3 Mastic to Vent Duct Joints Mastic to Vent Duct Penetrations to Walls White dust / debris to CMS Resin Residues to Floor			R679609		
68889	ACTIVE	H	M117-00-2/776	Fan Room - Station Building - Euston Square Stn	Mastic	Asbestos	Sampled – Not Detected				White mastic to fire stops throughout					
68890	ACTIVE	H	M117-00-2/776	Fan Room - Station Building - Euston Square Stn	Mastic	Asbestos	Sampled – Not Detected				Mastic to vent ducts joints	3				



Hazardous Material Asset Register - Summary



M117-00 - Station Building - Euston Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
70252	ACTIVE	H	M117-00-3/261	Platform 1 - Station Building - Euston Square Stn	Cable Sheath	Asbestos	Known				Invert - Braided redundant cable - total 1 no - In pit		1	R710076		
70255	ACTIVE	H	M117-00-3/261	Platform 1 - Station Building - Euston Square Stn	Cable Ducts: Bitumen	Asbestos	Known				Invert - Bitumen cable ducts - total 8 no - To tall wall		8	R710076		Y
70254	ACTIVE	H	M117-00-3/261	Platform 1 - Station Building - Euston Square Stn	Cable Ducts: Bitumen	Asbestos	Known				Invert - Bitumen cable ducts - total 4 no - To trackside wall		4	R710076		Y
70253	ACTIVE	H	M117-00-3/261	Platform 1 - Station Building - Euston Square Stn	Cable Ducts: Bitumen	Asbestos	Known				Invert - Bitumen cable ducts - total 16 no - To dividing wall		16	R710076		Y
70251	ACTIVE	H	M117-00-3/261	Platform 1 - Station Building - Euston Square Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Invert - Supalux panels - throughout - Around lid of manhole and to floor			R710076		Y
70249	ACTIVE	H	M117-00-3/261	Platform 1 - Station Building - Euston Square Stn	Cable Ducts: Bitumen	Asbestos	Known				Invert - Bitumen cable ducts - total 30 no throughout - To walls dividing mid-way		30	R710076		Y
70246	ACTIVE	H	M117-00-3/261	Platform 1 - Station Building - Euston Square Stn	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Invert - Grout/ wood/ lead - To tunnel rings flanges throughout			R710076		
53570	ACTIVE	H	M117-00-3/261	Platform 1 - Station Building - Euston Square Stn	Cable Ducts: Bitumen	Asbestos	Known				Bitumen ducts, 30no & 6no at entry and exit inverts, 24no within partition walls at Platform 1 Invert		50	R497726		Y
70256	ACTIVE	H	M117-00-3/261	Platform 1 - Station Building - Euston Square Stn	Cable Ducts: Bitumen	Asbestos	Known				Invert - Bitumen - total 12 no - To ceiling of switch room - 3/663		12	R710076		Y
70244	ACTIVE	H	M117-00-3/261	Platform 1 - Station Building - Euston Square Stn	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Invert - Metal tunnel rings - concrete infill - To walls and floor			R710076		
70258	ACTIVE	H	M117-00-3/262	Platform 2 - Station Building - Euston Square Stn	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Invert - Grout/ wood/ lead - To tunnel rings flanges throughout			R710076		
70257	ACTIVE	H	M117-00-3/262	Platform 2 - Station Building - Euston Square Stn	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Invert - Metal tunnel rings - concrete infill - To walls and floor			R710076		
70259	ACTIVE	H	M117-00-3/262	Platform 2 - Station Building - Euston Square Stn	Cable Ducts: Bitumen	Asbestos	Known				Invert - Bitumen cable ducts - total >18 no - To dividing wall		18	R710076		Y
53572	ACTIVE	H	M117-00-3/262	Platform 2 - Station Building - Euston Square Stn	Cable Ducts: Bitumen	Asbestos	Known				Bitumen ducts, 36no, to platform walls within invert at Platform 2 Invert		36	R497726		Y
53573	ACTIVE	H	M117-00-3/661	Switch Room - Station Building - Euston Square Stn	Other Electrical Boxes	Asbestos	Presumed				7no Transformer Boxes - P - Asbestos components within - W2 & W5		7	R644377		
53561	ACTIVE	H	M117-00-3/661	Switch Room - Station Building - Euston Square Stn	Isolator Switches	Asbestos	Strongly Presumed				10no Switch Boxes - SP asbestos components within - W1 & W2		10	R375751		
53562	ACTIVE	H	M117-00-3/662	Switch Room - Station Building - Euston Square Stn	Isolator Switches	Asbestos	Strongly Presumed				5no Switch Boxes - SP Asbestos Components within		5	R375751		
53563	ACTIVE	H	M117-00-3/711	Relay Room - Station Building - Euston Square Stn	Bitumen	Asbestos	Known				Bitumen Adhesive - 15m2 - to walls - was used to adhere Vinyl Tiles to Wall - which have since been removed - should be SP behind any remaining Vinyl Tiles see 53564.	15		R588376		



Hazardous Material Asset Register - Summary



M117-00 - Station Building - Euston Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
53565	ACTIVE	H	M117-00-3/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Euston Square Stn	Other Boarding	Asbestos	Presumed				Black Composite Panel, to 600v zed fuses box on wall2		1	R588376		
53564	ACTIVE	H	M117-00-3/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Euston Square Stn	Vinyl tiles	Asbestos	Known				Green Marley tiles, 2m2, to wall 3 behind fuse panel Bitumen Adhesive known to be present behind see 53563	2		R588376		
53567	ACTIVE	H	M117-00-3/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Euston Square Stn	Cable Duct: Other	Asbestos	Presumed				Cable Ducts to floor by wall3 by corner			R588376		
53574	ACTIVE	H	M117-00-3/713	Relay Room - Station Building - Euston Square Stn	Bitumen	Asbestos	Known				Bitumen Adhesive - to walls - was used to adhere Vinyl Tiles to Wall - which have since been removed - should be SP behind any remaining Vinyl Tiles			R644377		
53576	ACTIVE	H	M117-00-3/713	Relay Room - Station Building - Euston Square Stn	Other Boarding	Asbestos	Known				Black composite panel, 1no, to wall 2 (LED Fuse) on racking		1	R644377		
53575	ACTIVE	H	M117-00-3/713	Relay Room - Station Building - Euston Square Stn	Other Electrical Boxes	Asbestos	Presumed				1no Transformer Box to racking - P - Asbestos components within - W2		1	R644377		
53560	ACTIVE	H	M117-00-3/713	Relay Room - Station Building - Euston Square Stn	Vinyl tiles	Asbestos	Known				Green Marley Tiles to Walls - remnants remain behind racking where could not be removed previously.	5		R375751		
68888	ACTIVE	H	M117-00-3/731	CER - Station Building - Euston Square Stn	Isolator Switches	Asbestos	Strongly Presumed				Strongly Presumed Asbestos within combination fuse switches		2	R679609		
53559	ACTIVE	H	M117-00-3/731	CER - Station Building - Euston Square Stn	Isolator Switches	Asbestos	Strongly Presumed				2no Switch Boxes - SP Asbestos components within		2	R375751		
68892	ACTIVE	H	M117-00-3/731	CER - Station Building - Euston Square Stn	Void	Asbestos	Surveyed – Not Detected				No identified ACMs below raised floor					

M169-00 - Station Building - Edgware Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
70250	ACTIVE	H	M169-00-1/579	Stairs: Linear - Station Building - Edgware Road Stn	Isolator Switches	Asbestos	Presumed				Combination fuse switches. To Wall 3. Possible ACMs within fuse boxes		2	R378826		
70248	ACTIVE	H	M169-00-1/661	Switch Room - Station Building - Edgware Road Stn	Isolator Switches	Asbestos	Presumed				Combination fuse switches. To Walls 1&3. Possible ACMs within fuse boxes		10	R378826		
70247	ACTIVE	H	M169-00-1/662	Switch Room - Station Building - Edgware Road Stn	Isolator Switches	Asbestos	Presumed				Combination fuse switch. To Wall 1. Possible ACMs within fuse box		6	R378826		
70243	ACTIVE	H	M169-00-1/951	Switch Room - Station Building - Edgware Road Stn	Isolator Switches	Asbestos	Presumed				Combination fuse switch. To Wall 1. Possible ACMs within fuse box		1	R378826		
70245	ACTIVE	H	M169-00-2/263	Platform 3 - Station Building - Edgware Road Stn	Isolator Switches	Asbestos	Presumed				Combination fuse switch. (Between platforms 3 &4) Possible ACMs within fuse box		1	R378826		



Hazardous Material Asset Register - Summary



M169-00 - Station Building - Edgware Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
70280	ACTIVE	H	M169-00-2/711	Relay Room - Station Building - Edgware Road Stn	Control Panels	Asbestos	Strongly Presumed				Panel in control panel. Used as shelf in panel at back (Located within 2/701)		1	R378826		
70278	ACTIVE	H	M169-00-2/711	Relay Room - Station Building - Edgware Road Stn	Vinyl tiles	Asbestos	Known				Red Marley floor tiles. Some tiles taken up in corner of room	20		R378826		
70279	ACTIVE	H	M169-00-2/711	Relay Room - Station Building - Edgware Road Stn	Other Boarding	Asbestos	Presumed				Composite materials within various electrical equipment. Throughout			R378826		
70241	ACTIVE	H	M169-00-2/746	Equipment - Station Building - Edgware Road Stn	Cable Sheath	Asbestos	Strongly Presumed				Woven cable insulation. To wall 2		2	R378826		
70242	ACTIVE	H	M169-00-2/746	Equipment - Station Building - Edgware Road Stn	Other Electrical Boxes	Asbestos	Presumed				Materials within various electrical equipment. Throughout			R378826		
70270	ACTIVE	H	M169-00-2/781	Signal Equipment - Station Building - Edgware Road Stn	Other Electrical Boxes	Asbestos	Presumed				Materials within various electrical equipment. Throughout			R378826		
70263	ACTIVE	H	M169-00-2/781	Signal Equipment - Station Building - Edgware Road Stn	Vinyl tiles	Asbestos	Known				Marley tiles to wall. Throughout	50		R378826		
70273	ACTIVE	H	M169-00-2/781	Signal Equipment - Station Building - Edgware Road Stn	Cable: Sheath	Asbestos	Strongly Presumed				Woven cable insulation			R378826		

M175-00 - Station Building - Westbourne Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
70234	ACTIVE	H	M175-00-1/001	Booking Hall - Station Building - Westbourne Park Stn	Boarding: Cement	Asbestos	Known				Loft Space above. Cement sheeting. Encapsulated during works in 2013	6		R370106		
70233	ACTIVE	H	M175-00-1/031	Mess Room - Station Building - Westbourne Park Stn	Bitumen	Asbestos	Known				Bitumen Pad. Beneath sink		1	R370106		
70235	ACTIVE	H	M175-00-1/236	Passage - Station Building - Westbourne Park Stn	Boarding: Cement	Asbestos	Known				Asbestos cement board to ceiling	5		R370106		
70238	ACTIVE	H	M175-00-1/661	Switch Room - Station Building - Westbourne Park Stn	Isolator Switches	Asbestos	Presumed				Combination fuse switch. To Wall 1. Possible ACMs within fuse box		1	R370106		
70236	ACTIVE	H	M175-00-1/662	Switch Room - Station Building - Westbourne Park Stn	Isolator Switches	Asbestos	Presumed				Combination fuse switches. To Walls 1&3. Possible ACMs within fuse boxes		11	R370106		
70237	ACTIVE	H	M175-00-1/662	Switch Room - Station Building - Westbourne Park Stn	Other Electrical Boxes	Asbestos	Presumed				Transformers. To Walls 1&3. Possible ACMs within		4			
70239	ACTIVE	H	M175-00-2/261	Platform 1 - Station Building - Westbourne Park Stn	Westing house Boxes	Asbestos	Presumed				Possible ACMs within Westinghouse Boxes. To tail end of platform		6	R370106		
70240	ACTIVE	H	M175-00-2/262	Platform 2 - Station Building - Westbourne Park Stn	Isolator Switches	Asbestos	Presumed				Possible ACMs within switchgear On wall middle of platform		1	R370106		



Hazardous Material Asset Register - Summary



M179-00 - Station Building - Latimer Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
69226	ACTIVE	H	M179-00-1/281	Office - Station Building - Latimer Road Stn	Boarding: AIB	Asbestos	Strongly Presumed				Suspect board in ceiling, infill panel within void. No access, fixed ceiling prevents access			R370110	Y	
69228	ACTIVE	H	M179-00-1/661	Switch Room - Station Building - Latimer Road Stn	Other Electrical Boxes	Asbestos	Presumed				Transformers. Presumed asbestos materials within. To Wall 1&4		4	R370110		
69227	ACTIVE	H	M179-00-1/661	Switch Room - Station Building - Latimer Road Stn	Isolator Switches	Asbestos	Presumed				Presumed asbestos materials within Switch gear. To Wall 1,3&4.		7	R370110		

M185-00 - Station Building - Shepherds Bush Market Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
69223	ACTIVE	H	M185-00-1/001	Booking Hall - Station Building - Shepherds Bush Market Stn		Asbestos	No Access: Presumed				Boxing to ceiling - No access within			R370109		
69224	ACTIVE	H	M185-00-1/011	Office - Station Building - Shepherds Bush Market Stn		Asbestos	No Access: Presumed				No access behind plasterboard - Wall 5			R370109		
69222	ACTIVE	H	M185-00-1/412	Store - Station Building - Shepherds Bush Market Stn		Asbestos	Room: Surveyed – No Known Asbestos				No access during re-inspection, further investigation if works are required within this room. Presumed amosite asbestos. Now accessed. Supalux boarding. Identified Area NAD.			R370109		
70231	INACTIVE	H	M185-00-1/412	Store - Station Building - Shepherds Bush Market Stn	Non Asbestos Boarding	Asbestos	Room: Surveyed – No Known Asbestos				Previously NA. Now inspected. Supalux boarding. Area NAD			R370109		
69220	ACTIVE	H	M185-00-1/661	Switch Room - Station Building - Shepherds Bush Market Stn	Isolator Switches	Asbestos	Presumed				Presumed asbestos materials within Switch box. To Wall 1		1	R370109		
69221	ACTIVE	H	M185-00-1/662	Switch Room - Station Building - Shepherds Bush Market Stn	Isolator Switches	Asbestos	Presumed				Presumed asbestos materials within Switch boxes/electrical equipment. To Walls		7	R370109		
70232	ACTIVE	H	M185-00-1/662	Switch Room - Station Building - Shepherds Bush Market Stn	Other Electrical Boxes	Asbestos	Presumed				Transformers. To Walls 1&3. Possible ACMs within		5			

M187-00 - Station Building - Goldhawk Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
70230	ACTIVE	H	M187-00-1/001	Booking Hall - Station Building - Goldhawk Road Stn	Cable: Sheath	Asbestos	Strongly Presumed				Loose Sheathed cable. Hanging in front of entrance & station sign high level adjacent to 1/452	2		R370105		
70228	ACTIVE	H	M187-00-1/661	Switch Room - Station Building - Goldhawk Road Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer. To Wall 1. Possible ACMs within		1	R370105		
70227	ACTIVE	H	M187-00-1/661	Switch Room - Station Building - Goldhawk Road Stn	Isolator Switches	Asbestos	Presumed				Combination fuse switches. To Walls 2&3. Possible ACMs within fuse boxes		6	R370105		



Hazardous Material Asset Register - Summary



M187-00 - Station Building - Goldhawk Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
70229	ACTIVE	H	M187-00-1/747	Switch Room - Station Building - Goldhawk Road Stn	Isolator Switches	Asbestos	Presumed				Combination fuse switches. To Wall 1. Possible ACMs within fuse boxes		1	R370105		

M189-00 - Station Building - Hammersmith Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
69258	ACTIVE	H	M189-00-1/001	Booking Hall - Station Building - Hammersmith Stn	Glazing Rope	Asbestos	Presumed				Presumed asbestos rope gaskets to upright glazing (100m)	100		R326503		
69259	ACTIVE	H	M189-00-1/001	Booking Hall - Station Building - Hammersmith Stn	Glazing Rope	Asbestos	Presumed				Presumed asbestos rope gaskets to upright glazing (500m)	500		R326503		
69260	ACTIVE	H	M189-00-1/022	POM - Station Building - Hammersmith Stn	Other Boarding	Asbestos	Removed				Presumed asbestos lining within safe within old safe. Suspected safe identified on 25/08/2012 within report R326503 has been removed by others and replaced.		1	R326503		
69261	ACTIVE	H	M189-00-1/201	Passage - Station Building - Hammersmith Stn	Glazing Rope	Asbestos	Presumed				Presumed asbestos rope gaskets within ceiling skylights			R326503		
69264	ACTIVE	H	M189-00-1/261	Platform 1 - Station Building - Hammersmith Stn	Isolator Switches	Asbestos	Presumed				Presumed asbestos insulating materials within combination fuse box		1	R326503		
69265	ACTIVE	H	M189-00-1/261	Platform 1 - Station Building - Hammersmith Stn	Glazing Rope	Asbestos	Presumed				Presumed asbestos rope seals to skylight			R326503		
69269	ACTIVE	H	M189-00-1/262	Platform 2 - Station Building - Hammersmith Stn	Westing house Boxes	Asbestos	Presumed				Presumed asbestos insulating materials within Westinghouse box both sides of A/602		1	R326503		
69271	ACTIVE	H	M189-00-1/262	Platform 2 - Station Building - Hammersmith Stn	Other Boarding	Asbestos	Strongly Presumed				Strongly presumed paxoline board within EP Valve		1	R326503		
69267	ACTIVE	H	M189-00-1/262	Platform 2 - Station Building - Hammersmith Stn	Glazing Rope	Asbestos	Presumed				Presumed asbestos rope seals to skylights	500		R326503		
69270	ACTIVE	H	M189-00-1/263	Platform 3 - Station Building - Hammersmith Stn	Westing house Boxes	Asbestos	Presumed				Presumed asbestos insulating materials within Westinghouse box both sides of A/602		1	R326503		
69268	ACTIVE	H	M189-00-1/263	Platform 3 - Station Building - Hammersmith Stn	Glazing Rope	Asbestos	Presumed				Presumed asbestos rope seals to skylight	500		R326503		
69272	ACTIVE	H	M189-00-1/263	Platform 3 - Station Building - Hammersmith Stn	Other Boarding	Asbestos	Strongly Presumed						1	R326503		
70577	ACTIVE	H	M189-00-1/455	Tenancy - Station Building - Hammersmith Stn		Asbestos	Room: Surveyed – No Known Asbestos				Tenancy 1/455 and 1/456 No ACMs detected following a refurbishment survey Report R745876					
69277	ACTIVE	H	M189-00-1/552	Yard - Station Building - Hammersmith Stn	Westing house Boxes	Asbestos	Presumed				Presumed asbestos insulating materials within Westinghouse boxes		12	R326503		



Hazardous Material Asset Register - Summary



M189-00 - Station Building - Hammersmith Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
69263	ACTIVE	H	M189-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Hammersmith Stn	Isolator Switches	Asbestos	Presumed				Presumed asbestos insulating materials within switch boxes		10	R326503		
69262	ACTIVE	H	M189-00-1/661/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Hammersmith Stn	Isolator Switches	Asbestos	Presumed				Presumed asbestos insulating materials switch boxes		1	R326503		