



Hazardous Material Asset Register - Summary



Run date: 19/08/2024

Line: Northern

Risk Assessment Status: Active, Inactive
Hazardous Material Status: All
Hazardous Material Type: All

N021-00 - Station Building - Edgware Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|------------------------|--|------------------------|--------------------------|-----------------------------|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 44882 | ACTIVE | N | N021-00-0/576 | Stairs - Station Building - Edgware Stn | Cable: Sheath | Asbestos | Not Found during Inspection | | | | Black Braided Cable to window wall 1, 1st window Reinspection 17-03-2023 - No longer present/possibly removed by 3rd parties. | | | | N | N |
| 44881 | ACTIVE | N | N021-00-0/576 | Stairs - Station Building - Edgware Stn | Bakerlite | Asbestos | Presumed | | | | Bakelite switch under stairs cabinet Reinspected 17-03-2023 | | | | N | N |
| 44887 | ACTIVE | N | N021-00-0/706 | Interlocking Machine - Station Building - Edgware Stn | Bitumen | Asbestos | Strongly Presumed | | | | Adhesive to Green & Grey tiles on Walls & Ceilings Reinspected 17-03-2023 | | | | N | N |
| 44888 | ACTIVE | N | N021-00-0/706 | Interlocking Machine - Station Building - Edgware Stn | Cable Ducts: Bitumen | Asbestos | Strongly Presumed | | | | 6x Bitumen Ducts - 2x to Wall 4 & 4x to Wall 1 Reinspected 17-03-2023 | | | | N | N |
| 44889 | ACTIVE | N | N021-00-0/706 | Interlocking Machine - Station Building - Edgware Stn | Other Boarding | Asbestos | Known | | | | 4x Light & Dark Brown Composite Panels - 1x to wall to right hand side upper level, 1x to back of fuses, 1x to side of main switch frame Reinspected 17-03-2023 | | 4 | | N | N |
| 44891 | ACTIVE | N | N021-00-0/706 | Interlocking Machine - Station Building - Edgware Stn | Other Electrical Boxes | Asbestos | Not Found during Inspection | | | | Materials within Signal cabinet | | | | N | N |
| 44890 | ACTIVE | N | N021-00-0/706 | Interlocking Machine - Station Building - Edgware Stn | Rope Gaskets | Asbestos | Known | | | | 2x Gaskets to metal tube electric heater to Wall 3 Reinspected 17-03-2023 | | 2 | | N | N |
| 44886 | ACTIVE | N | N021-00-0/707 | Interlocking Machine - Station Building - Edgware Stn | Cable Ducts: Bitumen | Asbestos | Strongly Presumed | | | | Bitumen Ducts to Wall 1 at High Level Reinspected 17-03-2023 | | | | N | N |
| 42548 | INACTIVE | N | N021-00-0/707 85075940 | Interlocking Machine - Station Building - Edgware Stn Room Asset | Other Electrical Boxes | Asbestos | Presumed | | | | This record was incorrectly created. Refer to 25844, 25845 & 25846 | | | | | |
| 44885 | ACTIVE | N | N021-00-0/707 | Interlocking Machine - Station Building - Edgware Stn | Cable: Sheath | Asbestos | Presumed | | | | Braided Cable bunches throughout walls Reinspected 17-03-2023 | | | | N | N |
| 42324 | INACTIVE | N | N021-00-0/707 | Interlocking Machine - Station Building - Edgware Stn | PCBs | Polychlorinated biphenyl | Presumed | | | | Duplicate record - Refer to 25847 | | 4 | | N | N |
| 44883 | ACTIVE | N | N021-00-0/707/ WAL-001 | Wall: Internal - 1 - Interlocking Machine - Station Building - Edgware Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline boarding Reinspected 17-03-2023 | | | | N | N |
| 25850 | ACTIVE | N | N021-00-0/707/ WAL-002 | Wall: Internal - 2 - Interlocking Machine - Station Building - Edgware Stn | Other Boarding | Asbestos | Presumed | | | | Approx 12 Paxoline boards Wall 2 Reinspected 17-03-2023 | | 12 | | | |
| 25847 | INACTIVE | N | N021-00-0/707/ WAL-002 | Wall: Internal - 2 - Interlocking Machine - Station Building - Edgware Stn | PCBs | Polychlorinated biphenyl | Presumed | | | | W2 - 18 x medium silver cyclinder PCB's wall mounted on silver plates - faircondition | | 18 | | N | N |
| 25845 | ACTIVE | N | N021-00-0/707/ WAL-003 | Wall: Internal - 3 - Interlocking Machine - Station Building - Edgware Stn | Other Electrical Boxes | Asbestos | Presumed | | | | LTE electrical box Wall 3 Reinspected 17-03-2023 | | 1 | | | |



Hazardous Material Asset Register - Summary



N021-00 - Station Building - Edgware Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|------------------------|---------------|------------------------------------|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 25846 | ACTIVE | N | N021-00-0/707/WAL-003 | Wall: Internal - 3 - Interlocking Machine - Station Building - Edgware Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer box on floor - Insulation within presumed to contain asbestos Reinspected 17-03-2023 | | 2 | | | |
| 25844 | ACTIVE | N | N021-00-0/707/WAL-004 | Wall: Internal - 4 - Interlocking Machine - Station Building - Edgware Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | 2x 100amps Electrical boxes Reinspected 17-03-2023 | | 2 | | | |
| 44884 | INACTIVE | N | N021-00-0/707/WAL-004 | Wall: Internal - 4 - Interlocking Machine - Station Building - Edgware Stn | Other Boarding | Asbestos | Presumed | | | | Duplicate | | | | N | N |
| 25849 | ACTIVE | N | N021-00-0/707/WAL-004 | Wall: Internal - 4 - Interlocking Machine - Station Building - Edgware Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline Boarding Wall 4 Reinspected 17-03-2023 | | 2 | | | |
| 67961 | ACTIVE | N | N021-00-0/951 | Disused - Station Building - Edgware Stn | Vinyl tiles | Asbestos | Known | | | | Green marley tiles to wall and ceilings - Refer to 4-Rail report R643426 | | | R643426 | | |
| 44866 | ACTIVE | N | N021-00-0/951 | Disused - Station Building - Edgware Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | 2x Bitumen Duct at high level to Wall 3 Reinspected 17-03-2023 | | 2 | | N | N |
| 44865 | ACTIVE | N | N021-00-0/951 | Disused - Station Building - Edgware Stn | Bitumen | Asbestos | Known | | | | Adhesive to Green & Grey tiles on Walls & Ceilings Reinspected 17-03-2023 | | | | N | N |
| 67962 | ACTIVE | N | N021-00-0/951 | Disused - Station Building - Edgware Stn | Bitumen | Asbestos | Known | | | | Adhesive to green and grey tiles to wall and ceiling | | | R643426 | | |
| 67965 | ACTIVE | N | N021-00-0/951 | Disused - Station Building - Edgware Stn | Vinyl tiles | Asbestos | Known | | | | Grey marley tiles to ceilings - Refer to 4-Rail report R643426 | | | | | |
| 44878 | ACTIVE | N | N021-00-0/952 | Disused - Station Building - Edgware Stn | Isolator Switches | Asbestos | Known | | | | Materials within current rail isolation switch 534 within cess by P-Way Store | | | | N | N |
| 44880 | ACTIVE | N | N021-00-0/952 | Disused - Station Building - Edgware Stn | Cement Troughing | Asbestos | Presumed | | | | Cement troughing below current rail isolation section switch 534 within concrete slab | | | | N | N |
| 44877 | ACTIVE | N | N021-00-0/952 | Disused - Station Building - Edgware Stn | Isolator Switches | Asbestos | Known | | | | Materials within current rail isolation switch 533 within cess by P-Way Store | | | | N | N |
| 44879 | ACTIVE | N | N021-00-0/952 | Disused - Station Building - Edgware Stn | Cement Troughing | Asbestos | Presumed | | | | Cement troughing below current rail isolation section switch 533 within concrete slab | | | | N | N |
| 8230 | ACTIVE | N | N021-00-1/001 | Booking Hall - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19828 | INACTIVE | N | N021-00-1/001 | Booking Hall - Station Building - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8231 | ACTIVE | N | N021-00-1/011 | Ticket Office - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Presumed | | | | | | | | | |
| 19804 | ACTIVE | N | N021-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Boarding; Fibreglass - Lagging above Plasterboard Ceiling | | | | YES | |



Hazardous Material Asset Register - Summary



N021-00 - Station Building - Edgware Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|-----------------|---------------|------------------------------------|----------|-----------|-----------------|-----------------------------|-------------|------------|-------------|---------------------|-------------------|
| 19830 | ACTIVE | N | N021-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 19829 | ACTIVE | N | N021-00-1/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Edgware Stn | Void | Asbestos | No Access: Presumed | | | | Beneath wooden floor | | | | | YES |
| 19831 | ACTIVE | N | N021-00-1/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Edgware Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Wooden floor | | | | | YES |
| 8232 | ACTIVE | N | N021-00-1/021 | POM - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Presumed | | | | | | | | | |
| 19832 | ACTIVE | N | N021-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Boarding above Plasterboard | | | | YES | |
| 19430 | ACTIVE | N | N021-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 8233 | ACTIVE | N | N021-00-1/031 | Mess Room - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19880 | ACTIVE | N | N021-00-1/031 | Mess Room - Station Building - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 8234 | ACTIVE | N | N021-00-1/032 | Office - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19833 | ACTIVE | N | N021-00-1/032 | Office - Station Building - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8235 | ACTIVE | N | N021-00-1/036 | Toilet: Unisex - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19834 | INACTIVE | N | N021-00-1/036 | Toilet: Unisex - Station Building - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8236 | ACTIVE | N | N021-00-1/047 | Kitchen - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19675 | INACTIVE | N | N021-00-1/047 | Kitchen - Station Building - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8237 | ACTIVE | N | N021-00-1/071 | Circulation Area - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19835 | ACTIVE | N | N021-00-1/071/CLG-01 | Ceiling: Suspended - 1 - Circulation Area - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Steel Panel Ceiling | | | | YES | |



Hazardous Material Asset Register - Summary



N021-00 - Station Building - Edgware Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|---------------|------------------------------------|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 8238 | ACTIVE | N | N021-00-1/081 | Lobby - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Presumed | | | | | | | | | |
| 19837 | ACTIVE | N | N021-00-1/081/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Boarding above Plasterboard | | | | YES | |
| 19431 | ACTIVE | N | N021-00-1/081/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 19836 | ACTIVE | N | N021-00-1/081/FLR-01 | Floor - 1 - Lobby - Station Building - Edgware Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Wooden floor | | | | | YES |
| 20333 | ACTIVE | N | N021-00-1/081/FLR-01 | Floor - 1 - Lobby - Station Building - Edgware Stn | Void | Asbestos | No Access: Presumed | | | | Computer Flooring - No access beneath | | | | | N |
| 8239 | ACTIVE | N | N021-00-1/082 | Lobby - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19839 | ACTIVE | N | N021-00-1/082/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Plasterboard | | | | YES | |
| 19838 | ACTIVE | N | N021-00-1/082/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 8241 | ACTIVE | N | N021-00-1/236 | Passage - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19841 | ACTIVE | N | N021-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 19842 | ACTIVE | N | N021-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Plasterboard | | | | YES | |
| 8242 | ACTIVE | N | N021-00-1/237 | Passage - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19843 | ACTIVE | N | N021-00-1/237/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 19844 | ACTIVE | N | N021-00-1/237/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Plasterboard | | | | YES | |
| 8243 | ACTIVE | N | N021-00-1/238 | Passage - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19433 | ACTIVE | N | N021-00-1/238/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Fibreglass Lagging above Acoustic Panels | | | | YES | |
| 8244 | ACTIVE | N | N021-00-1/239 | Passage - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |



Hazardous Material Asset Register - Summary



N021-00 - Station Building - Edgware Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 19845 | ACTIVE | N | N021-00-1/239/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Fibreglass Lagging above Acoustic Panels | | | | YES | |
| 8245 | ACTIVE | N | N021-00-1/240 | Passage - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19445 | ACTIVE | N | N021-00-1/240/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Fibreglass Lagging above Plasterboard | | | | YES | |
| 19846 | ACTIVE | N | N021-00-1/240/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Fibreglass Lagging above Wood | | | | YES | |
| 19894 | ACTIVE | N | N021-00-1/240/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 8246 | ACTIVE | N | N021-00-1/241 | Passage - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 8247 | ACTIVE | N | N021-00-1/242 | Passage - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19680 | ACTIVE | N | N021-00-1/242/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Fibreglass Lagging above Plasterboard | | | | YES | |
| 19895 | ACTIVE | N | N021-00-1/242/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 8248 | ACTIVE | N | N021-00-1/281 | Station Supervisor Office - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19896 | ACTIVE | N | N021-00-1/281/CLG-01 | Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 19897 | ACTIVE | N | N021-00-1/281/CLG-01 | Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Plasterboard | | | | YES | |
| 8249 | ACTIVE | N | N021-00-1/306 | Office - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8250 | ACTIVE | N | N021-00-1/316 | Office - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19898 | ACTIVE | N | N021-00-1/316/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Acoustic Panel | | | | YES | |
| 8251 | ACTIVE | N | N021-00-1/317 | Locker Room - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |



Hazardous Material Asset Register - Summary



N021-00 - Station Building - Edgware Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|-----------------|---------------|------------------------------------|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 19446 | ACTIVE | N | N021-00-1/317/CLG-01 | Ceiling: Suspended - 1 - Locker Room - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Plasterboard | | | | YES | |
| 19899 | ACTIVE | N | N021-00-1/317/CLG-01 | Ceiling: Suspended - 1 - Locker Room - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard, Wood Boxing | | | | | |
| 8252 | ACTIVE | N | N021-00-1/331 | Mess Room - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19900 | ACTIVE | N | N021-00-1/331 | Mess Room - Station Building - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 8253 | ACTIVE | N | N021-00-1/332 | Mess Room - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19901 | ACTIVE | N | N021-00-1/332/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 19902 | ACTIVE | N | N021-00-1/332/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Fibreglass Lagging above false ceiling | | | | YES | |
| 8254 | ACTIVE | N | N021-00-1/341 | Mess Room - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19903 | ACTIVE | N | N021-00-1/341 | Mess Room - Station Building - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 19806 | ACTIVE | N | N021-00-1/341/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 19447 | ACTIVE | N | N021-00-1/341/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 8256 | ACTIVE | N | N021-00-1/401 | Store - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19905 | INACTIVE | N | N021-00-1/401 | Store - Station Building - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8257 | ACTIVE | N | N021-00-1/402 | Store - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19681 | INACTIVE | N | N021-00-1/402 | Store - Station Building - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8258 | ACTIVE | N | N021-00-1/403 | Store - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |



Hazardous Material Asset Register - Summary



N021-00 - Station Building - Edgware Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|-----------------|---------------|------------------------------------|----------|-----------|-----------------|------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 19906 | INACTIVE | N | N021-00-1/403 | Store - Station Building - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8259 | ACTIVE | N | N021-00-1/404 | Store - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19907 | INACTIVE | N | N021-00-1/404 | Store - Station Building - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8260 | ACTIVE | N | N021-00-1/411 | Store - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19883 | ACTIVE | N | N021-00-1/411 | Store - Station Building - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8261 | ACTIVE | N | N021-00-1/412 | Store - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19908 | ACTIVE | N | N021-00-1/412/ DOR-01 | Door - 1 - Store - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Panels on Door - Supalux | | | | | |
| 8262 | ACTIVE | N | N021-00-1/413 | Store - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19448 | ACTIVE | N | N021-00-1/413/ DOR-01 | Door - 1 - Store - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Panels on Door - Supalux | | | | | |
| 8263 | ACTIVE | N | N021-00-1/414 | CER - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19909 | INACTIVE | N | N021-00-1/414 | CER - Station Building - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8264 | ACTIVE | N | N021-00-1/415 | Store - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19910 | INACTIVE | N | N021-00-1/415 | Store - Station Building - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8265 | ACTIVE | N | N021-00-1/416 | Toilet: Male - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19305 | ACTIVE | N | N021-00-1/416/ CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above fasle ceiling | | | | YES | |
| 19911 | ACTIVE | N | N021-00-1/416/ CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |



Hazardous Material Asset Register - Summary



N021-00 - Station Building - Edgware Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 8266 | ACTIVE | N | N021-00-1/417 | Toilet: Female - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 8267 | ACTIVE | N | N021-00-1/418 | Toilet: Unisex - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 44457 | ACTIVE | N | N021-00-1/446 | Bicycle Shed - Station Building - Edgware Stn | | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 8269 | ACTIVE | N | N021-00-1/451 | Tenancy - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Presumed | | | | | | | | | |
| 19914 | ACTIVE | N | N021-00-1/451/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - Edgware Stn | No Access | Asbestos | No Access: Presumed | | | | No access above false ceiling | | | | | |
| 8270 | ACTIVE | N | N021-00-1/452 | Disused Room - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19915 | INACTIVE | N | N021-00-1/452 | Disused Room - Station Building - Edgware Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Tenancy | | | | | |
| 8271 | ACTIVE | N | N021-00-1/453 | Disused Room - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19916 | INACTIVE | N | N021-00-1/453 | Disused Room - Station Building - Edgware Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Tenancy | | | | | |
| 8272 | ACTIVE | N | N021-00-1/601 | Stairs: Linear - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19917 | INACTIVE | N | N021-00-1/601 | Stairs: Linear - Station Building - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8273 | ACTIVE | N | N021-00-1/602 | Stairs: Linear - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19450 | INACTIVE | N | N021-00-1/602 | Stairs: Linear - Station Building - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8274 | ACTIVE | N | N021-00-1/603 | Stairs: Linear - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19918 | INACTIVE | N | N021-00-1/603 | Stairs: Linear - Station Building - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8275 | ACTIVE | N | N021-00-1/604 | Stairs: Linear - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | | | | | | |



Hazardous Material Asset Register - Summary



N021-00 - Station Building - Edgware Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 19919 | ACTIVE | N | N021-00-1/636 | Overbridge - Station Building - Edgware Stn | | Asbestos | Room: Surveyed – No Known Asbestos | | | | No Asbestos Visible | | | | | |
| 8276 | ACTIVE | N | N021-00-1/661 | Switch Room - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19884 | INACTIVE | N | N021-00-1/661 | Switch Room - Station Building - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 45413 | ACTIVE | N | N021-00-1/661/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Edgware Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 4x Transformer - Presumed asbestos materials within Reinspected 17-03-2023 | | 3 | | | |
| 45412 | INACTIVE | N | N021-00-1/661/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Edgware Stn | | Asbestos | Presumed | | | | 3x Transformers - Presumed asbestos materials within | | | | | |
| 44861 | ACTIVE | N | N021-00-1/661/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Edgware Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 2x Combination Switches - Strongly presumed asbestos materials within Reinspected 17-03-2023 | | 2 | | N | N |
| 44862 | ACTIVE | N | N021-00-1/661/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Edgware Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 10x Combination Switches - Strongly presumed asbestos materials within Reinspected 17-03-2023 | | 10 | | N | N |
| 44863 | ACTIVE | N | N021-00-1/661/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Edgware Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 4x Combination Switches - Strongly presumed asbestos materials within Reinspected 17-03-2023 | | 4 | | N | N |
| 8278 | ACTIVE | N | N021-00-1/731 | CER - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19682 | INACTIVE | N | N021-00-1/731 | CER - Station Building - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8279 | ACTIVE | N | N021-00-1/746 | SCR - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19921 | ACTIVE | N | N021-00-1/746 | SCR - Station Building - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8280 | ACTIVE | N | N021-00-1/761 | Disused Room - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8281 | ACTIVE | N | N021-00-1/776 | Equipment Room - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19495 | INACTIVE | N | N021-00-1/776 | Equipment Room - Station Building - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8282 | ACTIVE | N | N021-00-1/801 | Office - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19964 | ACTIVE | N | N021-00-1/801/CLG-01 | Ceiling: Solid - 1 - Office - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Acoustic Panels | | | | | |



Hazardous Material Asset Register - Summary



N021-00 - Station Building - Edgware Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 19503 | ACTIVE | N | N021-00-1/801/CLG-01 | Ceiling: Solid - 1 - Office - Station Building - Edgware Stn | Void | Asbestos | No Access: Presumed | | | | No Access 3m+ High | | | | YES | |
| 8283 | ACTIVE | N | N021-00-1/802 | Office - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19965 | ACTIVE | N | N021-00-1/802/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Acoustic Panels | | | | | |
| 19966 | ACTIVE | N | N021-00-1/802/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Edgware Stn | Void | Asbestos | No Access: Presumed | | | | No Access 3m+ High | | | | YES | |
| 8284 | ACTIVE | N | N021-00-1/803 | Office - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19967 | ACTIVE | N | N021-00-1/803/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Acoustic Panels | | | | | |
| 19684 | ACTIVE | N | N021-00-1/803/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above False Ceiling | | | | YES | |
| 8285 | ACTIVE | N | N021-00-1/804 | Office - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19504 | ACTIVE | N | N021-00-1/804/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above False Ceiling | | | | YES | |
| 19968 | ACTIVE | N | N021-00-1/804/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel, Boxing Wood | | | | | |
| 8287 | ACTIVE | N | N021-00-2/081 | Lobby - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Presumed | | | | | | | | | |
| 19443 | ACTIVE | N | N021-00-2/081/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Corrugated Sheets; Breeze Block Walls; Metal Support, Plastic Cable above False Ceiling | | | | YES | |
| 19971 | ACTIVE | N | N021-00-2/081/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel. Tile ‘Ceramaguard’ | | | | | |
| 8288 | ACTIVE | N | N021-00-2/082 | Lobby - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19505 | ACTIVE | N | N021-00-2/082/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Edgware Stn | Void | Asbestos | No Access: Presumed | | | | Above Plasterboard | | | | YES | |
| 19972 | ACTIVE | N | N021-00-2/082/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 8289 | ACTIVE | N | N021-00-2/083 | Lobby - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N021-00 - Station Building - Edgware Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------|--|------------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 19973 | INACTIVE | N | N021-00-2/083 | Lobby - Station Building - Edgware Stn | No Access | Asbestos | Surveyed – Not Detected | | | | NAD 26/02/2016 | | | | | |
| 8290 | ACTIVE | N | N021-00-2/131 | LEER - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | | | | | | |
| 8291 | ACTIVE | N | N021-00-2/132 | LEER - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | | | | | | |
| 8292 | ACTIVE | N | N021-00-2/261 | Platform 1 - Northbound Main - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – Asbestos Known | | | | | | | | | |
| 19974 | ACTIVE | N | N021-00-2/261 | Platform 1 - Northbound Main - Station Building - Edgware Stn | Cable Ducts: Cement | Asbestos | Known | | | | Cable ducts 2 x 100mm under nosing at buffer stop end - Chrysotile Reinspected 17-03-2023 (No access to inspect closely as track area | | 2 | | | |
| 8293 | ACTIVE | N | N021-00-2/262 | Platform 2 - Northbound Local - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – Asbestos Known | | | | | | | | | |
| 25835 | ACTIVE | N | N021-00-2/262 | Platform 2 - Northbound Local - Station Building - Edgware Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Signal Cabinet - presumed insulating materials Reinspected 17-03-2023 | | 1 | | | |
| 19975 | ACTIVE | N | N021-00-2/262 | Platform 2 - Northbound Local - Station Building - Edgware Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 3x 10mm Cable nr Signal Box Reinspected 17-03-2023 | | 3 | | | |
| 25836 | ACTIVE | N | N021-00-2/262 | Platform 2 - Northbound Local - Station Building - Edgware Stn | Other Electrical Boxes | Asbestos | Removed | | | | 2x Boxes - Insulation within | | 2 | | | |
| 67959 | ACTIVE | N | N021-00-2/262 | Platform 2 - Northbound Local - Station Building - Edgware Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Green gloss - Cleats to columns - 4.91% | | | R739276 | | |
| 67955 | ACTIVE | N | N021-00-2/262 | Platform 2 - Northbound Local - Station Building - Edgware Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Green gloss - 4th single column from south gable end - 0.21% | | | R739276 | | |
| 67952 | ACTIVE | N | N021-00-2/262 | Platform 2 - Northbound Local - Station Building - Edgware Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Green gloss - Cross bracing 7th bay from north gable end - 1.12% | | | R739276 | | |
| 67953 | ACTIVE | N | N021-00-2/262 | Platform 2 - Northbound Local - Station Building - Edgware Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Green gloss - Cross bracing 2nd bay from south gable end - 0.13% | | | R739276 | | |
| 67957 | ACTIVE | N | N021-00-2/262 | Platform 2 - Northbound Local - Station Building - Edgware Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Green gloss - Lattice beams (top of stair 1/603) 9.01% | | | R739276 | | |
| 67949 | ACTIVE | N | N021-00-2/262 | Platform 2 - Northbound Local - Station Building - Edgware Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Green gloss - 4th double column from North gable end - 8.92% | | | R739276 | | |
| 8294 | ACTIVE | N | N021-00-2/263 | Platform 3 - Southbound Local - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Strongly Presumed | | | | | | | | | |
| 19808 | ACTIVE | N | N021-00-2/263 | Platform 3 - Southbound Local - Station Building - Edgware Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 3x 10mm Cable nr Signal Box Reinspected 17-03-2023 | | 3 | | | |



Hazardous Material Asset Register - Summary



N021-00 - Station Building - Edgware Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|------------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 25838 | ACTIVE | N | N021-00-2/263 | Platform 3 - Southbound Local - Station Building - Edgware Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Signal cabinet presumed to contain asbestos Not inspected within as no electrician present during 2023 reinspection. Reinspected 17-03-2023 | | | | | |
| 25837 | ACTIVE | N | N021-00-2/263 | Platform 3 - Southbound Local - Station Building - Edgware Stn | Westing house Boxes | Asbestos | Presumed | | | | 3x Westinghouse boxes on brick wall Not inspected within as no electrician present in 2023 reinspection | | 3 | | | |
| 67956 | ACTIVE | N | N021-00-2/263 | Platform 3 - Southbound Local - Station Building - Edgware Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Green gloss - 4th single column from south gable end - 0.21% | | | R739276 | | |
| 67958 | ACTIVE | N | N021-00-2/263 | Platform 3 - Southbound Local - Station Building - Edgware Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Green gloss - Lattice beams (top of stair 1/603) 9.01% | | | R739276 | | |
| 67951 | ACTIVE | N | N021-00-2/263 | Platform 3 - Southbound Local - Station Building - Edgware Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Green gloss - Cross bracing 7th bay from north gable end - 1.12% | | | R739276 | | |
| 67950 | ACTIVE | N | N021-00-2/263 | Platform 3 - Southbound Local - Station Building - Edgware Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Green gloss - 4th double column from north gable end - 8.92% | | | R739276 | | |
| 67954 | ACTIVE | N | N021-00-2/263 | Platform 3 - Southbound Local - Station Building - Edgware Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Green gloss - Cross bracing 2nd bay from south gable end - 0.13% | | | R739276 | | |
| 8295 | ACTIVE | N | N021-00-2/316 | Locker Room - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19685 | INACTIVE | N | N021-00-2/316 | Locker Room - Station Building - Edgware Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction - Portacabin | | | | | |
| 8296 | ACTIVE | N | N021-00-2/317 | Locker Room - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19976 | ACTIVE | N | N021-00-2/317 | Locker Room - Station Building - Edgware Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction - Portacabin | | | | | |
| 19977 | INACTIVE | N | N021-00-2/317 | Locker Room - Station Building - Edgware Stn | Debris: Cement | Asbestos | Removed | | | | Cement debris external 2/317 by fencing | | | | | |
| 8297 | ACTIVE | N | N021-00-2/331 | Mess Room - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Presumed | | | | | | | | | |
| 19506 | ACTIVE | N | N021-00-2/331 | Mess Room - Station Building - Edgware Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | LU Heater - Foam insulation Board | | | | | |
| 19978 | ACTIVE | N | N021-00-2/331 | Mess Room - Station Building - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 19979 | ACTIVE | N | N021-00-2/331/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 19980 | ACTIVE | N | N021-00-2/331/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Edgware Stn | Void | Asbestos | No Access: Presumed | | | | Above Plasterboard | | | | YES | |



Hazardous Material Asset Register - Summary



N021-00 - Station Building - Edgware Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 8300 | ACTIVE | N | N021-00-2/411 | Store - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19686 | INACTIVE | N | N021-00-2/411 | Store - Station Building - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8301 | ACTIVE | N | N021-00-2/412 | Store - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19983 | INACTIVE | N | N021-00-2/412 | Store - Station Building - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8302 | ACTIVE | N | N021-00-2/413 | Store - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19984 | INACTIVE | N | N021-00-2/413 | Store - Station Building - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8303 | ACTIVE | N | N021-00-2/414 | Store - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19985 | INACTIVE | N | N021-00-2/414 | Store - Station Building - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8304 | ACTIVE | N | N021-00-2/416 | Toilet: Unisex - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19508 | ACTIVE | N | N021-00-2/416/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Acoustic Panels | | | | | |
| 19986 | ACTIVE | N | N021-00-2/416/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Corrugated Steel Roof; Breeze Block, Concrete, Plaster Walls; Fibreglass packing infill by beams, Plastic Cables above False Ceiling | | | | YES | |
| 8305 | ACTIVE | N | N021-00-2/417 | Toilet: Unisex - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19987 | INACTIVE | N | N021-00-2/417 | Toilet: Unisex - Station Building - Edgware Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | | | | | | |
| 8307 | ACTIVE | N | N021-00-2/661 | LEER - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | | | | | | |
| 8308 | ACTIVE | N | N021-00-2/706 | IMR - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8309 | ACTIVE | N | N021-00-2/707 | IMR - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N021-00 - Station Building - Edgware Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 8310 | ACTIVE | N | N021-00-2/731 | CER - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19306 | ACTIVE | N | N021-00-2/731 | CER - Station Building - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | Surveyed by 4-Rail Services - Refer to ID Report R657026 for construction information. No asbestos visible | | | | | |
| 8311 | INACTIVE | N | N021-00-2/761 | Auto Kiosk - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19426 | ACTIVE | N | N021-00-2/761 | Auto Kiosk - Station Building - Edgware Stn | No Access | Asbestos | Room: Surveyed – No Known Asbestos | | | | Green Booth on platform | | | | | |
| 8312 | ACTIVE | N | N021-00-2/786 | Switch Room - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Strongly Presumed | | | | | | | | | |
| 20031 | ACTIVE | N | N021-00-2/786/WAL-004 | Wall: Internal - 4 - Switch Room - Station Building - Edgware Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Electrical Boxes Not inspected within as no electrician present during 2023 reinspection. | | 1 | | | |
| 8313 | ACTIVE | N | N021-00-2/787 | Switch Room - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 20032 | ACTIVE | N | N021-00-2/787/CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 20033 | ACTIVE | N | N021-00-2/787/CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - Edgware Stn | Void | Asbestos | No Access: Presumed | | | | Sealed No Access above, presumed same structure as adjacent rooms | | | | YES | |
| 19887 | ACTIVE | N | N021-00-2/787/FLR-01 | Floor - 1 - Switch Room - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal CMS, Plastic Cables beneath Metal Cased Floor Tiles | | | | | YES |
| 20222 | ACTIVE | N | N021-00-2/787/WAL-004 | Wall: Internal - 4 - Switch Room - Station Building - Edgware Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 1x Blue Iron clad isolators Not inspected within as no electrician present during 2023 reinspection. | | 1 | | | |
| 8314 | ACTIVE | N | N021-00-2/801 | Training Room - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 20034 | ACTIVE | N | N021-00-2/801/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel. Tile ‘Ceramaguard’ | | | | | |
| 20035 | ACTIVE | N | N021-00-2/801/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Corrugated Steel Roof; Breeze Block, Concrete, Plaster Walls; Fibreglass packing infill by beams, Plastic Cables above False Ceiling | | | | YES | |
| 8315 | ACTIVE | N | N021-00-2/802 | SCR - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |



Hazardous Material Asset Register - Summary



N021-00 - Station Building - Edgware Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|------------------------------------|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 20037 | ACTIVE | N | N021-00-2/802/CLG-01 | Ceiling: Suspended - 1 - SCR - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Corrugated Steel Roof; Breeze Block, Concrete, Plaster Walls; Fibreglass packing infill by beams, Plastic Cables above False Ceiling | | | | YES | |
| 20036 | ACTIVE | N | N021-00-2/802/CLG-01 | Ceiling: Suspended - 1 - SCR - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel. Tile ‘Ceramaguard’ | | | | | |
| 8316 | ACTIVE | N | N021-00-2/803 | Training Room - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 20223 | ACTIVE | N | N021-00-2/803/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Corrugated Steel Roof, Wooden Panel; Breeze Block, Concrete, Plaster Walls; Fibreglass packing infill by beams, Plastic Cables; W3 Cast iron down pipes, to floor in plasterboard/wood boxing above False Ceiling. | | | | YES | |
| 20038 | ACTIVE | N | N021-00-2/803/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel. | | | | | |
| 20039 | ACTIVE | N | N021-00-2/803/FLR-01 | Floor - 1 - Office - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal CMS, Plastic Cables; Metal Cased Floor Tiles beneath Solid Concrete & PVC | | | | | YES |
| 20040 | ACTIVE | N | N021-00-2/803/FLR-02 | Floor - 2 - Office - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal CMS, Plastic Cables; Metal Cased Floor Tiles beneath Solid Concrete & PVC | | | | | YES |
| 8317 | ACTIVE | N | N021-00-2/804 | SCR - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 20041 | ACTIVE | N | N021-00-2/804/CLG-01 | Ceiling: Solid - 1 - SCR - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel. | | | | | |
| 20042 | ACTIVE | N | N021-00-2/804/CLG-01 | Ceiling: Solid - 1 - SCR - Station Building - Edgware Stn | Void | Asbestos | Surveyed – Not Detected | | | | Corrugated Steel Roof, Wooden Panel; Breeze Block, Concrete, Plaster Walls; Fibreglass packing infill by beams, Plastic Cables above Acoustic Panel | | | | YES | |
| 8318 | ACTIVE | N | N021-00-2/805 | Store - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Presumed | | | | | | | | | |
| 19732 | ACTIVE | N | N021-00-2/805/CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel. | | | | | |
| 20043 | ACTIVE | N | N021-00-2/805/CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Edgware Stn | Void | Asbestos | No Access: Presumed | | | | Above Acoustic Panel | | | | YES | |
| 8319 | ACTIVE | N | N021-00-2/902 | Toilet: Unisex - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 20044 | ACTIVE | N | N021-00-2/902/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 20045 | ACTIVE | N | N021-00-2/902/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Edgware Stn | Void | Asbestos | No Access: Presumed | | | | Above Plasterboard | | | | YES | |



Hazardous Material Asset Register - Summary



N021-00 - Station Building - Edgware Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|--------------------|-------------|------------|-------------|---------------------|-------------------|
| 8320 | ACTIVE | N | N021-00-2/903 | Toilet: Unisex - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19215 | ACTIVE | N | N021-00-2/903/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 20046 | ACTIVE | N | N021-00-2/903/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Edgware Stn | Void | Asbestos | No Access: Presumed | | | | Above Plasterboard | | | | YES | |
| 8321 | ACTIVE | N | N021-00-2/952 | Disused Room - Station Building - Edgware Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N022-04 - P Way Accommodation - Edgware To Burnt Oak

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 8333 | ACTIVE | N | N022-04-0/661 | Equipment Room - P Way Accommodation - Edgware To Burnt Oak | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N023-00 - Station Building - Burnt Oak Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 8335 | ACTIVE | N | N023-00-1/001 | Booking Hall - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19753 | ACTIVE | N | N023-00-1/001/CLG-01 | Ceiling: Solid - 1 - Booking Hall - Station Building - Burnt Oak Stn | Void | Asbestos | Surveyed – Not Detected | | | | Tiles, Wooden Struts, Water Tank, Fibreglass Lagging above False Ceiling | | | | YES | |
| 8336 | ACTIVE | N | N023-00-1/011 | Ticket Office - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19367 | ACTIVE | N | N023-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Burnt Oak Stn | Void | Asbestos | Surveyed – Not Detected | | | | All Concrete & Render; W4 Breeze Block & Render; W1 New cement block w/t cables passing through - above Polystyrene Tiles | | | | YES | |
| 19754 | ACTIVE | N | N023-00-1/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Burnt Oak Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid Concrete beneath Computer Flooring | | | | | YES |
| 8337 | ACTIVE | N | N023-00-1/021 | POM - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19670 | ACTIVE | N | N023-00-1/021/FLR-01 | Floor - 1 - POM - Station Building - Burnt Oak Stn | Void | Asbestos | No Access: Presumed | | | | Beneath false wooden floor | | | | | YES |
| 8338 | ACTIVE | N | N023-00-1/031 | Mess Room - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N023-00 - Station Building - Burnt Oak Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|----------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 19756 | ACTIVE | N | N023-00-1/031 | Mess Room - Station Building - Burnt Oak Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - Foam Board Insulation | | | | | |
| 19755 | ACTIVE | N | N023-00-1/031/WAL-002 | Wall: Internal - 2 - Mess Room - Station Building - Burnt Oak Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Suplax Boarding | | | | | |
| 8339 | ACTIVE | N | N023-00-1/037 | Toilet: Unisex - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19757 | ACTIVE | N | N023-00-1/037 | Toilet: Unisex - Station Building - Burnt Oak Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Room | | | | | |
| 8340 | ACTIVE | N | N023-00-1/071 | Circulation Area - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19758 | ACTIVE | N | N023-00-1/071 | Circulation Area - Station Building - Burnt Oak Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8341 | ACTIVE | N | N023-00-1/081 | Lobby - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19759 | ACTIVE | N | N023-00-1/081/FLR-01 | Floor - 1 - Lobby - Station Building - Burnt Oak Stn | Void | Asbestos | No Access: Presumed | | | | Beneath false wooden floor | | | | | YES |
| 8342 | ACTIVE | N | N023-00-1/281 | Station Supervisor Office - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19760 | ACTIVE | N | N023-00-1/281 | Station Supervisor Office - Station Building - Burnt Oak Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - Foam Board Insulation | | | | | |
| 19368 | ACTIVE | N | N023-00-1/281/CLG-01 | Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Burnt Oak Stn | Void | Asbestos | No Access: Presumed | | | | Above Polystyrene Tiles | | | | YES | |
| 8343 | ACTIVE | N | N023-00-1/331 | Mess Room - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19761 | ACTIVE | N | N023-00-1/331 | Mess Room - Station Building - Burnt Oak Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 19762 | ACTIVE | N | N023-00-1/331 | Mess Room - Station Building - Burnt Oak Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - Foam Board Insulation | | | | | |
| 19763 | ACTIVE | N | N023-00-1/331/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Burnt Oak Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Polystyrene Tiles | | | | YES | |
| 8344 | ACTIVE | N | N023-00-1/406 | Store - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19764 | ACTIVE | N | N023-00-1/406 | Store - Station Building - Burnt Oak Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N023-00 - Station Building - Burnt Oak Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 8345 | ACTIVE | N | N023-00-1/407 | Store - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19765 | ACTIVE | N | N023-00-1/407 | Store - Station Building - Burnt Oak Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8346 | ACTIVE | N | N023-00-1/417 | Toilet: Disabled - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19671 | ACTIVE | N | N023-00-1/417 | Toilet: Disabled - Station Building - Burnt Oak Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Room | | | | | |
| 8347 | ACTIVE | N | N023-00-1/451 | Tenancy - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19766 | ACTIVE | N | N023-00-1/451/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - Burnt Oak Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 19369 | ACTIVE | N | N023-00-1/451/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - Burnt Oak Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Suplax Tiles | | | | | |
| 8348 | ACTIVE | N | N023-00-1/453 | Disused Room - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19878 | ACTIVE | N | N023-00-1/453 | Disused Room - Station Building - Burnt Oak Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8349 | ACTIVE | N | N023-00-1/481 | Switch Cupboard - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19767 | ACTIVE | N | N023-00-1/481 | Switch Cupboard - Station Building - Burnt Oak Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8350 | ACTIVE | N | N023-00-1/576 | Stairs: Linear - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19768 | ACTIVE | N | N023-00-1/576 | Stairs: Linear - Station Building - Burnt Oak Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8351 | ACTIVE | N | N023-00-1/577 | Stairs: Linear - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19769 | ACTIVE | N | N023-00-1/577 | Stairs: Linear - Station Building - Burnt Oak Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8352 | ACTIVE | N | N023-00-1/601 | Stairs: Linear - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19770 | ACTIVE | N | N023-00-1/601 | Stairs: Linear - Station Building - Burnt Oak Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N023-00 - Station Building - Burnt Oak Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 8353 | ACTIVE | N | N023-00-1/602 | Stairs: Linear - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19370 | ACTIVE | N | N023-00-1/602 | Stairs: Linear - Station Building - Burnt Oak Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 19672 | ACTIVE | N | N023-00-1/636 | Overbridge - Station Building - Burnt Oak Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8354 | ACTIVE | N | N023-00-1/747 | SCR - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19771 | ACTIVE | N | N023-00-1/747 | SCR - Station Building - Burnt Oak Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Room | | | | | |
| 8355 | ACTIVE | N | N023-00-2/261 | Platform 1 - Northbound Local - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19773 | ACTIVE | N | N023-00-2/261/CLG-01 | Ceiling: Solid - 1 - Platform 1 - Station Building - Burnt Oak Stn | Rope Gaskets | Asbestos | Surveyed – Not Detected | | | | No Asbestos in Glazing Rope | | | | | |
| 19802 | ACTIVE | N | N023-00-2/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Burnt Oak Stn | Void | Asbestos | Surveyed – Not Detected | | | | Beneath Manholes except 4 & 5 | | | | | YES |
| 19772 | ACTIVE | N | N023-00-2/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Burnt Oak Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Manholes 4 & 5 | | | | | YES |
| 8356 | ACTIVE | N | N023-00-2/262 | Platform 2 - Southbound Local - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19775 | ACTIVE | N | N023-00-2/262/CLG-01 | Ceiling: Solid - 1 - Platform 2 - Station Building - Burnt Oak Stn | Rope Gaskets | Asbestos | Surveyed – Not Detected | | | | No Asbestos in Glazing Rope | | | | | |
| 19371 | ACTIVE | N | N023-00-2/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Burnt Oak Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Manholes 4 & 5 | | | | | YES |
| 19774 | ACTIVE | N | N023-00-2/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Burnt Oak Stn | Void | Asbestos | Surveyed – Not Detected | | | | Beneath Manholes except 4 & 5 | | | | | YES |
| 8357 | ACTIVE | N | N023-00-2/401 | Bin Store - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19673 | ACTIVE | N | N023-00-2/401/CLG-01 | Ceiling: Solid - 1 - Bin Store - Station Building - Burnt Oak Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 19776 | ACTIVE | N | N023-00-2/401/CLG-01 | Ceiling: Solid - 1 - Bin Store - Station Building - Burnt Oak Stn | Void | Asbestos | No Access: Presumed | | | | Above Plasterboard | | | | YES | |
| 8358 | ACTIVE | N | N023-00-2/411 | Store - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N023-00 - Station Building - Burnt Oak Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|-------------------------|-------------|------------|-------------|---------------------|-------------------|
| 19777 | ACTIVE | N | N023-00-2/411/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Burnt Oak Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 19372 | ACTIVE | N | N023-00-2/411/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Burnt Oak Stn | Void | Asbestos | No Access: Presumed | | | | Above Plasterboard | | | | YES | |
| 8359 | ACTIVE | N | N023-00-2/436 | Waiting Room - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19778 | ACTIVE | N | N023-00-2/436 | Waiting Room - Station Building - Burnt Oak Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Room | | | | | |
| 8360 | ACTIVE | N | N023-00-2/661 | Switch Cupboard - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19382 | ACTIVE | N | N023-00-2/661 | Switch Cupboard - Station Building - Burnt Oak Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Room | | | | | |
| 8361 | ACTIVE | N | N023-00-2/662 | Switch Room - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19822 | ACTIVE | N | N023-00-2/662 | Switch Room - Station Building - Burnt Oak Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Room | | | | | |
| 8362 | ACTIVE | N | N023-00-2/711 | Relay Room - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8363 | ACTIVE | N | N023-00-2/731 | CER - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19824 | ACTIVE | N | N023-00-2/731 | CER - Station Building - Burnt Oak Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 19823 | ACTIVE | N | N023-00-2/731/FLR-01 | Floor - 1 - CER - Station Building - Burnt Oak Stn | Void | Asbestos | No Access: Presumed | | | | Beneath False Floor | | | | | YES |
| 8364 | ACTIVE | N | N023-00-2/761 | Equipment Room - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19384 | ACTIVE | N | N023-00-2/761/CLG-01 | Ceiling: Solid - 1 - Equipment Room - Station Building - Burnt Oak Stn | Void | Asbestos | No Access: Presumed | | | | Above Plasterboard | | | | YES | |
| 19827 | ACTIVE | N | N023-00-2/761/CLG-01 | Ceiling: Solid - 1 - Equipment Room - Station Building - Burnt Oak Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 19674 | ACTIVE | N | N023-00-2/761/FLR-01 | Floor - 1 - Equipment Room - Station Building - Burnt Oak Stn | Void | Asbestos | No Access: Presumed | | | | Beneath wooden floor | | | | | YES |
| 8365 | ACTIVE | N | N023-00-2/951 | Store - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N023-00 - Station Building - Burnt Oak Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|---------------------|-------------|------------|-------------|---------------------|-------------------|
| 19383 | ACTIVE | N | N023-00-2/951 | Store - Station Building - Burnt Oak Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8366 | ACTIVE | N | N023-00-2/952 | Disused Room - Station Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19825 | ACTIVE | N | N023-00-2/952 | Disused Room - Station Building - Burnt Oak Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |

N025-00 - Station Building - Colindale Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|--------------|---------------------|-------------------|
| 8368 | ACTIVE | N | N025-00-1/001 | Booking Hall - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19245 | ACTIVE | N | N025-00-1/001 | Booking Hall - Station Building - Colindale Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 46513 | ACTIVE | N | N025-00-1/001 | Booking Hall - Station Building - Colindale Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux panel above door to 1/746 - 1no.x<1m ² | 1 | 1 | R647076 Rev3 | | |
| 46516 | ACTIVE | N | N025-00-1/001 | Booking Hall - Station Building - Colindale Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux panel and wood to wall between 1/081 and 1/452 - 3m ² | 3 | | R647076 Rev3 | | |
| 46517 | ACTIVE | N | N025-00-1/001 | Booking Hall - Station Building - Colindale Stn | Mastic | Asbestos | Sampled – Not Detected | | | | Putty to metal window - Throughout | | | R647076 Rev3 | | |
| 46514 | ACTIVE | N | N025-00-1/001 | Booking Hall - Station Building - Colindale Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux panel above door to 1/081 - 1no.x<1m ² | 1 | 1 | R647076 Rev3 | | |
| 46512 | ACTIVE | N | N025-00-1/001 | Booking Hall - Station Building - Colindale Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux panel above door to 1/661 - 1no.x<1m ² | 1 | 1 | R647076 Rev3 | | |
| 46515 | ACTIVE | N | N025-00-1/001 | Booking Hall - Station Building - Colindale Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux panel above door to 1/406 - 1no.x<1m ² | 1 | 1 | R647076 Rev3 | | |
| 46511 | ACTIVE | N | N025-00-1/001/CLG-01 | Ceiling: Suspended - 1 - Booking Hall - Station Building - Colindale Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux ceiling tiles on metal/ wooden framework to suspended ceiling - 16no.x6m ² | 6 | 16 | R647076 Rev3 | | |
| 8369 | ACTIVE | N | N025-00-1/011 | Ticket Office - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19628 | ACTIVE | N | N025-00-1/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Colindale Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Lino - False Wooden Floor | | | | | YES |
| 8370 | ACTIVE | N | N025-00-1/021 | POM - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19630 | ACTIVE | N | N025-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Colindale Stn | Void | Asbestos | Surveyed – Not Detected | | | | Terracotta, Wood, Concrete above False Ceiling | | | | YES | |



Hazardous Material Asset Register - Summary



N025-00 - Station Building - Colindale Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|--------------|---------------------|-------------------|
| 46518 | ACTIVE | N | N025-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Colindale Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux ceiling tiles on metal/ wooden framework to suspended ceiling - 8no.x6m ² | 6 | 8 | R647076 Rev3 | | |
| 19246 | ACTIVE | N | N025-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Colindale Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Ceiling Tiles | | | | | |
| 19247 | ACTIVE | N | N025-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Colindale Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Ceiling Tiles | | | | | |
| 19629 | ACTIVE | N | N025-00-1/021/FLR-01 | Floor - 1 - POM - Station Building - Colindale Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Lino - False Wooden Floor | | | | | YES |
| 8371 | ACTIVE | N | N025-00-1/031 | Mess Room - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19631 | ACTIVE | N | N025-00-1/031 | Mess Room - Station Building - Colindale Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 19874 | ACTIVE | N | N025-00-1/031/FLR-01 | Floor - 1 - Mess Room - Station Building - Colindale Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Lino - False Wooden Floor | | | | | YES |
| 46519 | ACTIVE | N | N025-00-1/031/SNK-01 | Sink - 1 - Mess Room - Station Building - Colindale Stn | Bitumen | Asbestos | Sampled – Not Detected | | | | Acoustic panel below sink to wall 2 - 2no. | | 2 | R647076 Rev3 | | |
| 8372 | ACTIVE | N | N025-00-1/036 | Toilet: Unisex - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19242 | ACTIVE | N | N025-00-1/036/FLR-01 | Floor - 1 - Toilet - Station Building - Colindale Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Lino - False Wooden Floor | | | | | YES |
| 8373 | ACTIVE | N | N025-00-1/071 | Circulation Area - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19632 | ACTIVE | N | N025-00-1/071 | Circulation Area - Station Building - Colindale Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8374 | ACTIVE | N | N025-00-1/081 | Lobby - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19633 | ACTIVE | N | N025-00-1/081/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Colindale Stn | Glazing Rope | Asbestos | Surveyed – Not Detected | | | | No Rope in Skylight | | | | | |
| 8375 | ACTIVE | N | N025-00-1/082 | Lobby - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 46520 | ACTIVE | N | N025-00-1/082 | Lobby - Station Building - Colindale Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux ceiling tiles on fixed metal/ wooden framework to suspended ceiling - 4m ² | 4 | | R647076 Rev3 | | |
| 19635 | ACTIVE | N | N025-00-1/082/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Colindale Stn | Void | Asbestos | Surveyed – Not Detected | | | | Terracotta, Wood, Concrete above False Ceiling | | | | YES | |
| 19634 | ACTIVE | N | N025-00-1/082/FLR-01 | Floor - 1 - Lobby - Station Building - Colindale Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Vinyl - False Wooden Floor | | | | | YES |



Hazardous Material Asset Register - Summary



N025-00 - Station Building - Colindale Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 8376 | ACTIVE | N | N025-00-1/201 | Passage - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19637 | INACTIVE | N | N025-00-1/201 | Passage - Station Building - Colindale Stn | Boarding: AIB | Asbestos | Removed | | | | External Cladding Boarding to underside of overbridge - Amosite 3lm- This item now removed under HM00016 by DCUK on 21/08/2021 | 3 | | | N | N |
| 19638 | ACTIVE | N | N025-00-1/201/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Colindale Stn | Void | Asbestos | Surveyed – Not Detected | | | | Roof Tiles, Fascia Soffit, Rain Water Guttering above Wooden Ceiling | | | | YES | |
| 19636 | ACTIVE | N | N025-00-1/201/FLR-01 | Floor - 1 - Passage - Station Building - Colindale Stn | Void | Asbestos | Surveyed – Not Detected | | | | Void: Wood - Hardboard | | | | | YES |
| 8377 | ACTIVE | N | N025-00-1/281 | Station Supervisor Office - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19248 | ACTIVE | N | N025-00-1/281 | Station Supervisor Office - Station Building - Colindale Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard - Walls | | | | | |
| 19639 | ACTIVE | N | N025-00-1/281/CLG-01 | Ceiling: Solid - 1 - Station Supervisor Office - Station Building - Colindale Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 19420 | ACTIVE | N | N025-00-1/281/CLG-01 | Ceiling: Solid - 1 - Station Supervisor Office - Station Building - Colindale Stn | Void | Asbestos | No Access: Presumed | | | | Above Plasterboard | | | | YES | |
| 8378 | ACTIVE | N | N025-00-1/316 | Locker Room - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19640 | ACTIVE | N | N025-00-1/316 | Locker Room - Station Building - Colindale Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8379 | ACTIVE | N | N025-00-1/406 | Store - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19616 | ACTIVE | N | N025-00-1/406 | Store - Station Building - Colindale Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8380 | ACTIVE | N | N025-00-1/407 | Store - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19249 | ACTIVE | N | N025-00-1/407 | Store - Station Building - Colindale Stn | Cable Duct: Other | Asbestos | No Access: Presumed | | | | Possible redundant cable duct encapsulated below Lino. Re-Inspected 08/07/2014 - Not Found | | | | | |
| 8381 | ACTIVE | N | N025-00-1/416 | Toilet: Unisex - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19641 | ACTIVE | N | N025-00-1/416/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Colindale Stn | Glazing Rope | Asbestos | Surveyed – Not Detected | | | | No Rope in Skylight | | | | | |



Hazardous Material Asset Register - Summary



N025-00 - Station Building - Colindale Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|--------------|---------------------|-------------------|
| 8382 | ACTIVE | N | N025-00-1/446 | Bicycle Shed - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19642 | ACTIVE | N | N025-00-1/446 | Bicycle Shed - Station Building - Colindale Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 46521 | ACTIVE | N | N025-00-1/446 | Bicycle Shed - Station Building - Colindale Stn | Bitumen | Asbestos | Sampled – Not Detected | | | | Bitumen damp proof course to base of walls - 8m throughout | 8 | | R647076 Rev3 | | |
| 8383 | ACTIVE | N | N025-00-1/451 | Tenancy - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19643 | ACTIVE | N | N025-00-1/451 | Tenancy - Station Building - Colindale Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access - Tenancy | | | | | |
| 8384 | ACTIVE | N | N025-00-1/452 | Mess Room - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19691 | ACTIVE | N | N025-00-1/452 | Mess Room - Station Building - Colindale Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Boarding within Cupboard | | | | | |
| 19688 | ACTIVE | N | N025-00-1/452 | Mess Room - Station Building - Colindale Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Insulation within Heater - Foam | | | | | |
| 19690 | ACTIVE | N | N025-00-1/452 | Mess Room - Station Building - Colindale Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 19307 | ACTIVE | N | N025-00-1/452/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Colindale Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 19689 | ACTIVE | N | N025-00-1/452/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Colindale Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above False Ceiling | | | | YES | |
| 19687 | ACTIVE | N | N025-00-1/452/FLR-01 | Floor - 1 - Mess Room - Station Building - Colindale Stn | Cable Duct: Other | Asbestos | No Access: Presumed | | | | Redundant Cable Duct - Encapsulated. Re inspected 08/07/2014 - The room has since been refurbished | | | | | |
| 46522 | ACTIVE | N | N025-00-1/452/SNK-01 | Sink - 1 - Mess Room - Station Building - Colindale Stn | Bitumen | Asbestos | Sampled – Not Detected | | | | Acoustic panels under sink unit to wall 3 - 2no. | | 2 | R647076 Rev3 | | |
| 8385 | ACTIVE | N | N025-00-1/453 | ATM - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 46523 | ACTIVE | N | N025-00-1/453 | ATM - Station Building - Colindale Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux panel to wall 4 - 3m² | 3 | | R647076 Rev3 | | |



Hazardous Material Asset Register - Summary



N025-00 - Station Building - Colindale Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-------------------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|--------------|---------------------|-------------------|
| 19692 | ACTIVE | N | N025-00-1/453 | ATM - Station Building - Colindale Stn | Cable Duct: Other | Asbestos | Presumed | | | | Possible redundant cable duct encapsulated below Lino. (No access 2023 re-inspection. Door way sealed with Supalux) NO ACCESS DURING 2020 REINSPECTION WITHIN THE ROOM / VOID NOT IN USE AND SEALED UP WITH SUPALUX BOARDING IN MAIN TICKETHALL AREA - SEE PHOTO | | | | | |
| 8386 | ACTIVE | N | N025-00-1/551 | Yard - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 46524 | ACTIVE | N | N025-00-1/551 | Yard - Station Building - Colindale Stn | Bitumen | Asbestos | Sampled – Not Detected | | | | Bitumen damp proof course to base of brickwork by bike shed - 8m | 8 | | R647076 Rev3 | | |
| 19693 | ACTIVE | N | N025-00-1/551 | Yard - Station Building - Colindale Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8387 | ACTIVE | N | N025-00-1/601 | Stairs: Linear - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19308 | ACTIVE | N | N025-00-1/601 | Stairs: Linear - Station Building - Colindale Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8388 | ACTIVE | N | N025-00-1/602 | Stairs: Linear - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19665 | ACTIVE | N | N025-00-1/602 | Stairs: Linear - Station Building - Colindale Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8389 | ACTIVE | N | N025-00-1/661 | Switch Room - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19695 | ACTIVE | N | N025-00-1/661 | Switch Room - Station Building - Colindale Stn | Cable: Wrap | Asbestos | Surveyed – Not Detected | | | | Insulation Tape | | | | | |
| 46528 | ACTIVE | N | N025-00-1/661 | Switch Room - Station Building - Colindale Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux panel on concrete slab to ceiling by wall 3 (water leaking from ceiling) - <1m ² | 1 | | R647076 Rev3 | | |
| 44348 | ACTIVE | N | N025-00-1/661/CLG-01 80892650 | Ceiling: Solid - 1 - Switch Room - Station Building - Colindale Stn Ceiling: Solid | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Boarding by light fitting above wall 3 surveyed and is supalux Panel is supalux in 2020 reinspection however possible cement panel may have been removed historically, possible cement residue could be present | | 1 | | N | N |
| 20338 | ACTIVE | N | N025-00-1/661/FLR-01 | Floor - 1 - Switch Room - Station Building - Colindale Stn | Void | Asbestos | No Access: Presumed | | | | No Access Beneath Hatch in Floor | | | | | N |



Hazardous Material Asset Register - Summary



N025-00 - Station Building - Colindale Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|--------------------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|---------------|---------------------|-------------------|
| 20336 | ACTIVE | N | N025-00-1/661/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Colindale Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 x 30amp Switchbox to wall 1 No electrician on site during 2023 reinspection to open box for inspection - therefore cannot score materials within | | 1 | | N | N |
| 44347 | ACTIVE | N | N025-00-1/661/WAL-001 80892646 | Wall: Internal - 1 - Switch Room - Station Building - Colindale Stn Wall: Internal | Other Boarding | Asbestos | Presumed | | | | Paxoline boarding to wall 1 Reinspected 17-03-2023 New non acm brown composite panel | | 1 | | N | N |
| 20335 | ACTIVE | N | N025-00-1/661/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Colindale Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | 4 x Tranformer Boxes by wall 1 No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 4 | | N | N |
| 20337 | ACTIVE | N | N025-00-1/661/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Colindale Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 x 100amp Switch Box to wall 2 No electrician on site during 2023 reinspection to open box for inspection - therefore cannot score material within | | 1 | | N | N |
| 46527 | ACTIVE | N | N025-00-1/661/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Colindale Stn | Cable: Sheath | Asbestos | Sampled – Not Detected | | | | Cable wrapping to cable (meter box) to wall 2 - 1no. x 2m | 2 | 1 | R647076 Rev3 | | |
| 46525 | ACTIVE | N | N025-00-1/661/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Colindale Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | Bitumen cable ducts within cable trench to wall 2 with cables within - 2no. Reinspected 17-03-2023 | | 2 | R647076 Rev3 | | |
| 19694 | ACTIVE | N | N025-00-1/661/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Colindale Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes - 5 x 60amp, 1 x 100amp, 3 x 30amp to wall 3 No electrician on site during 2023 reinspection to open box for inspection - therefore cannot score material within | | 9 | | N | N |
| 46526 | ACTIVE | N | N025-00-1/661/WAL-004 | Wall: Internal - 4 - Switch Room - Station Building - Colindale Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux panel to wall 4 above door - 1no. x <1m² | 1 | 1 | R647076 Rev3 | | |
| 8390 | ACTIVE | N | N025-00-1/746 | SCR - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19309 | ACTIVE | N | N025-00-1/746/CLG-01 | Ceiling: Suspended - 1 - SCR - Station Building - Colindale Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Ceiling Tiles | | | | | |
| 46509 | ACTIVE | N | N025-00-1/746/CLG-01 | Ceiling: Suspended - 1 - SCR - Station Building - Colindale Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Plaster and supalux ceiling tiles on metal framework to fixed suspended ceiling - 4m² | 4 | | R647076 Rev03 | | |
| 8391 | ACTIVE | N | N025-00-2/081 | Lobby - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19697 | ACTIVE | N | N025-00-2/081 | Lobby - Station Building - Colindale Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 46529 | ACTIVE | N | N025-00-2/081/FLR-01 | Floor - 1 - Lobby - Station Building - Colindale Stn | Bitumen | Asbestos | Sampled – Not Detected | | | | Asphalt on concrete slab to floor - 10m² | 10 | | R647076 Rev3 | | |



Hazardous Material Asset Register - Summary



N025-00 - Station Building - Colindale Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|--------------|---------------------|-------------------|
| 8392 | ACTIVE | N | N025-00-2/261 | Platform 1 - Northbound Local - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 46554 | ACTIVE | N | N025-00-2/261 | Platform 1 - Northbound Local - Station Building - Colindale Stn | Cable Ducts: Cement | Asbestos | Removed | | | | Cement pipe/sleeve concealed within wall of 2/701 on Platform 1 side - 1no. - Removed by DCUK on 08/11/2021 under HM00016 | | 1 | R647076 Rev3 | | |
| 46553 | ACTIVE | N | N025-00-2/261 | Platform 1 - Northbound Local - Station Building - Colindale Stn | Cement Cowlings/ Flues | Asbestos | Removed | | | | Cement cowl to wall of 2/701 on Platform 1 side - 1no. Removed by DCUK on 08/11/2021. | | 1 | R647076 Rev3 | | |
| 46552 | ACTIVE | N | N025-00-2/261 | Platform 1 - Northbound Local - Station Building - Colindale Stn | Boarding: AIB | Asbestos | Removed | | | | Medium density board to underside of overbridge of Platform 1 canopy adjacent to room 2/081 and 2/761 - 5m Removed 21/08/2021 | 5 | | R647076 Rev3 | | |
| 46550 | ACTIVE | N | N025-00-2/261 | Platform 1 - Northbound Local - Station Building - Colindale Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Braided cables to 2/706 wall end of platform 1 departure end - 2no. Reinspected 17-03-2023 | | 2 | R647076 Rev3 | | |
| 46549 | ACTIVE | N | N025-00-2/261 | Platform 1 - Northbound Local - Station Building - Colindale Stn | Other Electrical Boxes | Asbestos | Removed | | | | Materials within old signal boxes to north side of bridge wall - 1no. - Removed by DCUK between 8/11/2021 to 13/11/2021 under HM00016 | | 2 | R647076 Rev3 | | |
| 46532 | ACTIVE | N | N025-00-2/261 | Platform 1 - Northbound Local - Station Building - Colindale Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Car park side - Supalux panel to platform wall trackside midway - <1m² | 1 | | R647076 Rev3 | | |
| 46530 | ACTIVE | N | N025-00-2/261 | Platform 1 - Northbound Local - Station Building - Colindale Stn | Roofing Tiles | Asbestos | Sampled – Not Detected | | | | Roof tiles on bitumen on wood to roof of 3/436 - 16m² | 16 | | R647076 Rev3 | | |
| 19699 | INACTIVE | N | N025-00-2/261 | Platform 1 - Northbound Local - Station Building - Colindale Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Under Platform Nosing - 2 x Cables to 1/2 Platform terminate in Switch Box Not possible to inspect as on track - PWT-EH needed - (access 2020 was during TH) - therefore cannot score material within | | 2 | | | |
| 19666 | ACTIVE | N | N025-00-2/261 | Platform 1 - Northbound Local - Station Building - Colindale Stn | Cable: Sheath | Asbestos | Removed | | | | 3x Braided Cables to signal equipment - attached to underside of Road Bridge crossing Platforms 1 & 2 - Encapsulated - Removed by DCUK between 08/11/2021-13/11/201 under HM00016 | | 3 | | N | N |
| 19700 | ACTIVE | N | N025-00-2/261 | Platform 1 - Northbound Local - Station Building - Colindale Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Under Platform Nosing - 2 x Cables to 1/2 Platform terminate in Switch Box Not possible to inspect as on track - PWT-EH needed - (access 2023 was during TH) - therefore cannot score material within | | 1 | | | |
| 44349 | ACTIVE | N | N025-00-2/261 | Platform 1 - Northbound Local - Station Building - Colindale Stn | Boarding: Cement | Asbestos | Surveyed – Not Detected | | | | Metal corrugated sheeting to both platforms 1 & 2 canopy (top side) / Rubber rope within glazing bars | | | R647076 | N | N |
| 46531 | ACTIVE | N | N025-00-2/261 | Platform 1 - Northbound Local - Station Building - Colindale Stn | Roofing Tiles | Asbestos | Sampled – Not Detected | | | | Bitumen roof felt under roof tiles to roof of 3/436 - 16m² | 16 | | R647076 Rev3 | | |



Hazardous Material Asset Register - Summary



N025-00 - Station Building - Colindale Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|--------------|---------------------|-------------------|
| 46548 | ACTIVE | N | N025-00-2/261 | Platform 1 - Northbound Local - Station Building - Colindale Stn | Cable: Sheath | Asbestos | Removed | | | | Braided cables to old signal box running from north side of bridge - 3no. x 30m - Removed by DCUK between 08/11/2021- 13/11/2021 under HM00016 | 30 | 3 | R647076 Rev3 | | |
| 46551 | ACTIVE | N | N025-00-2/261 | Platform 1 - Northbound Local - Station Building - Colindale Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Presumed ACM's within old signal lamp to 2/706 wall end of platform 1 departure end - 1no. Reinspected externally 17-03-2023 (No Electrician to inspect internal) | | 1 | R647076 Rev3 | | |
| 19698 | ACTIVE | N | N025-00-2/261/ FLR-01 | Floor - 1 - Platform 1 - Station Building - Colindale Stn | Void | Asbestos | Surveyed – Not Detected | | | | No Void beneath concrete; inspection covers - ducts - plastic, ceramic, concrete, pvc cables | | | | | YES |
| 8393 | ACTIVE | N | N025-00-2/262 | Platform 2 - Southbound Local - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19703 | ACTIVE | N | N025-00-2/262 | Platform 2 - Southbound Local - Station Building - Colindale Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 2 Northend Platform Ramp - 7x15mm & 1 x 35mm Cables - Cable Run off along Plt 2 & Cable Run over Track; 4x 35mm Cables - into penetration into IMR Not closely inspected as beyond platform ramp 17-03-2023 | | 12 | | | |
| 46560 | INACTIVE | N | N025-00-2/262 | Platform 2 - Southbound Local - Station Building - Colindale Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Materials within old signal lamp to 2/706 wall end of platform 1 departure end - 1no. Duplicate of 46551 | | 1 | R647076 Rev3 | | |
| 46559 | INACTIVE | N | N025-00-2/262 | Platform 2 - Southbound Local - Station Building - Colindale Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Braided cables to 2/706 wall end of platform 1 departure end - 2no. | | 2 | R647076 Rev3 | | |
| 46556 | ACTIVE | N | N025-00-2/262 | Platform 2 - Southbound Local - Station Building - Colindale Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Platform 2 S/B track side 1 - Materials within 10 core box to platform wall - trackside adjacent to 2/661 - 1no. No access during 2023 re-inspection. track access required | | 1 | R647076 Rev3 | | |
| 19704 | ACTIVE | N | N025-00-2/262 | Platform 2 - Southbound Local - Station Building - Colindale Stn | Westing house Boxes | Asbestos | Presumed | | | | Platform 2 Northend Platform Ramp - Westhouse Fuse Boxes - Insulation Inside Possible removed check at next inspection No electrician on site during 2023 reinspection to open boxes - therefore cannot score material within. Also track access required with PWT-EH. 1x 10 core present to IMR external wall by OTX structure on ramp at platform 2 at north end. | | 3 | | N | N |
| 46557 | ACTIVE | N | N025-00-2/262 | Platform 2 - Southbound Local - Station Building - Colindale Stn | Cable: Sheath | Asbestos | Removed | | | | Braided cables to old signal box running from north side of bridge - 3no. x 30m - Removed by DCUK between 08/11/2021 - 13/11/2021 under HM00016 | 30 | 3 | R647076 Rev3 | | |



Hazardous Material Asset Register - Summary



N025-00 - Station Building - Colindale Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|--------------|---------------------|-------------------|
| 19702 | ACTIVE | N | N025-00-2/262 | Platform 2 - Southbound Local - Station Building - Colindale Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | Platform 2 Southend Platform Ramp - Westhouse Fuse Boxes - Insulation Inside (NB these may have previously been opened and no asbestos was evident, however unable to trace paperwork to confirm) No access during 2023 reinspection, track access required | | 4 | | | |
| 19310 | ACTIVE | N | N025-00-2/262 | Platform 2 - Southbound Local - Station Building - Colindale Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 2 Southend Platform Ramp - 7 x 15mm & 1 x 35mm white cables No access during 2023 re-inspection as track access required | | 8 | | | |
| 46558 | ACTIVE | N | N025-00-2/262 | Platform 2 - Southbound Local - Station Building - Colindale Stn | Other Electrical Boxes | Asbestos | Removed | | | | Materials within old signal boxes to north side of bridge wall - 2no. - Removed by DCUK between 08/11/2021 - 13/11/2021 under HM00016 | | 1 | R647076 Rev3 | | |
| 46555 | ACTIVE | N | N025-00-2/262 | Platform 2 - Southbound Local - Station Building - Colindale Stn | Cable: Sheath | Asbestos | Presumed | | | | Trackside Platform 2 S/B track grounds - Braided cables within cable run composite retaining wall and road bridge - 3no. Small, 1no. large - 3no. small cable Removed by DCUK between 08/11/2021 - 13/11/2021 under HM00016 - one active cable remain on cable run | | 4 | R647076 Rev3 | | |
| 46534 | ACTIVE | N | N025-00-2/262 | Platform 2 - Southbound Local - Station Building - Colindale Stn | Roofing Tiles | Asbestos | Sampled – Not Detected | | | | Bitumen roof felt under roof tiles to roof of 3/436 - 16m² | 16 | | R647076 Rev3 | | |
| 46533 | ACTIVE | N | N025-00-2/262 | Platform 2 - Southbound Local - Station Building - Colindale Stn | Roofing Tiles | Asbestos | Sampled – Not Detected | | | | Roof tiles on bitumen on wood to roof of 3/436 - 16m² | 16 | | R647076 Rev3 | | |
| 68827 | ACTIVE | N | N025-00-2/262 | Platform 2 - Southbound Local - Station Building - Colindale Stn | | Asbestos | Surveyed – Not Detected | | | | Metal corrugated sheeting to both platforms 1 & 2 canopy (top side) / Rubber rope within glazing bars | | | R647076 | | |
| 19701 | ACTIVE | N | N025-00-2/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Colindale Stn | Void | Asbestos | Surveyed – Not Detected | | | | No Void beneath concrete; inspection covers - ducts - plastic, ceramic, concrete, pvc cables | | | | | YES |
| 8394 | ACTIVE | N | N025-00-2/411 | Store - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19705 | ACTIVE | N | N025-00-2/411/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Colindale Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Ceiling | | | | | |
| 46535 | ACTIVE | N | N025-00-2/411/FLR-01 | Floor - 1 - Store - Station Building - Colindale Stn | Bitumen | Asbestos | Sampled – Not Detected | | | | Asphalt on concrete slab to floor - 4m² | 4 | | R647076 Rev3 | | |
| 19876 | ACTIVE | N | N025-00-2/411/FLR-01 | Floor - 1 - Store - Station Building - Colindale Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Wooden floor | | | | | YES |
| 8395 | ACTIVE | N | N025-00-2/412 | Store - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N025-00 - Station Building - Colindale Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|------------------------|---|------------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|--------------|---------------------|-------------------|
| 19311 | ACTIVE | N | N025-00-2/412 | Store - Station Building - Colindale Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8396 | ACTIVE | N | N025-00-2/413 | Store - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19421 | ACTIVE | N | N025-00-2/413 | Store - Station Building - Colindale Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel on wall | | | | | |
| 19667 | ACTIVE | N | N025-00-2/413/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Colindale Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 46536 | ACTIVE | N | N025-00-2/413/FLR-01 | Floor - 1 - Store - Station Building - Colindale Stn | Bitumen | Asbestos | Sampled – Not Detected | | | | Asphalt on concrete slab to floor - 4m² | 4 | | R647076 Rev3 | | |
| 8397 | ACTIVE | N | N025-00-2/436 | Waiting Room - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19706 | ACTIVE | N | N025-00-2/436 | Waiting Room - Station Building - Colindale Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Insulation within Heater - Foam | | | | | |
| 8398 | ACTIVE | N | N025-00-2/661 | Switch Room - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19312 | ACTIVE | N | N025-00-2/661 | Switch Room - Station Building - Colindale Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Boarding & Panel above door - Supalux | | | | | |
| 44350 | ACTIVE | N | N025-00-2/661 | Switch Room - Station Building - Colindale Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer No electrician on site during 2023 reinspection to open box - therefore cannot score material within | | 1 | | N | N |
| 46537 | ACTIVE | N | N025-00-2/661/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Colindale Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux panel to ceiling - no access above as fixed - 2m² | 2 | | R647076 Rev3 | | |
| 46538 | ACTIVE | N | N025-00-2/661/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Colindale Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux panel to wall 2 - 2m² | 2 | | R647076 Rev3 | | |
| 19707 | ACTIVE | N | N025-00-2/661/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Colindale Stn | Isolator Switches | Asbestos | Known | | | | Combination Switch Box Blue 1 x 30amp to wall 2 No electrician on site during 2023 reinspection to open box - therefore cannot score | | 1 | | N | N |
| 43215 | ACTIVE | N | N025-00-2/706 | Imr - Station Building - Colindale | Cable: Sheath | Asbestos | Strongly Presumed | | | | 4 x 35mm Cables within J hanger to wall 3 leading outside to track Reinspected 17-03-2023 | | 4 | | N | N |
| 43214 | INACTIVE | N | N025-00-2/706 | Imr - Station Building - Colindale | Cable: Sheath | Asbestos | Strongly Presumed | | | | 2No Cables - External wall to IMR - Encapsulated DUPLICATE OF 46551 | | 2 | | N | N |
| 44351 | ACTIVE | N | N025-00-2/706 80100065 | Imr - Station Building - Colindale Room Assets | Other Boarding | Asbestos | Presumed | | | | Paxoline boarding throughout Reinspected 17-03-2023 | | | | N | N |
| 42335 | INACTIVE | N | N025-00-2/706 | Imr - Station Building - Colindale | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | 2 x blue cylinder PCB's on paxoline board | | 2 | | N | N |



Hazardous Material Asset Register - Summary



N025-00 - Station Building - Colindale Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|--------------|---------------------|-------------------|
| 8399 | ACTIVE | N | N025-00-2/761 | CER - Station Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19710 | ACTIVE | N | N025-00-2/761 | CER - Station Building - Colindale Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Suplax Panel, Boxing - Plasterboard | | | | | |
| 46539 | ACTIVE | N | N025-00-2/761 | CER - Station Building - Colindale Stn | Mastic | Asbestos | Sampled – Not Detected | | | | Putty to windows to wall 2 and 4 - 3no. x 2m | 2 | 3 | R647076 Rev3 | | |
| 19752 | ACTIVE | N | N025-00-2/761/CLG-01 | Ceiling: Solid - 1 - CER - Station Building - Colindale Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Ceiling | | | | | |
| 46547 | ACTIVE | N | N025-00-2/761/FLR-01 | Floor - 1 - CER - Station Building - Colindale Stn | Bitumen | Asbestos | Known | | | | Asphalt on concrete slab to floor under new tiles - 8m ² Reinspected 17-03-2023 | 8 | | R647076 Rev3 | | |
| 46541 | ACTIVE | N | N025-00-2/761/FLR-01 | Floor - 1 - CER - Station Building - Colindale Stn | Vinyl tiles | Asbestos | Sampled – Not Detected | | | | Grey floor tiles and backing on new screed on asphlat on concrete slab to floor - 8m ² | 8 | | R647076 Rev3 | | |
| 46546 | ACTIVE | N | N025-00-2/761/FLR-01 | Floor - 1 - CER - Station Building - Colindale Stn | Bitumen | Asbestos | Known | | | | Asphalt on concrete to floor - 8m Reinspected 17-03-2023 | 8 | | R647076 Rev3 | | |
| 46545 | ACTIVE | N | N025-00-2/761/FLR-01 | Floor - 1 - CER - Station Building - Colindale Stn | Vinyl tiles | Asbestos | Known | | | | Grey floor tile and backing - contaminated with asphalts to floor - 8m ² Reinspected 17-03-2023 | 8 | | R647076 Rev3 | | |

N031-00 - Station Building - Hendon Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 8403 | ACTIVE | N | N031-00-1/001 | Booking Hall - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18212 | ACTIVE | N | N031-00-1/001 | Booking Hall - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8404 | ACTIVE | N | N031-00-1/011 | Ticket Office - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 53528 | ACTIVE | N | N031-00-1/011 | Ticket Office - Station Building - Hendon Central Stn | Glazing Rope | Asbestos | Surveyed – Not Detected | | | | Skylight to roof - New rubber gasket. Only visible from Roof (VC) | | | | | |
| 46454 | ACTIVE | N | N031-00-1/011 | Ticket Office - Station Building - Hendon Central Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | White matt paint applied to the false ceiling - Thickness: 0.09mm Analysis: 0.03% | | | R661826 | N | N |
| 46453 | ACTIVE | N | N031-00-1/011 | Ticket Office - Station Building - Hendon Central Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Cream matt paint applied to walls - Thickness: 0.28mm Analysis: 0.02% | | | R661826 | N | N |
| 46452 | ACTIVE | N | N031-00-1/011 | Ticket Office - Station Building - Hendon Central Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Cream matt paint applied to walls - Thickness: 0.22mm Analysis: <0.01% | | | R661826 | N | N |



Hazardous Material Asset Register - Summary



N031-00 - Station Building - Hendon Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18138 | ACTIVE | N | N031-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Hendon Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Wood, pvc cables, copper pipe - rock wool lagging above false ceiling | | | | YES | |
| 17881 | ACTIVE | N | N031-00-1/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Hendon Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, PVC Cables, Supalux Debris, Metal beneath Computer Floor | | | | | YES |
| 8405 | ACTIVE | N | N031-00-1/021 | POM - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17689 | ACTIVE | N | N031-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Hendon Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Wood, Air Con, Plaster, Rock Wool above False Ceiling | | | | YES | |
| 17688 | ACTIVE | N | N031-00-1/021/FLR-01 | Floor - 1 - POM - Station Building - Hendon Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Metal, PVC Cables Beneath Computer Floor | | | | | YES |
| 8406 | ACTIVE | N | N031-00-1/031 | Mess Room - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18139 | ACTIVE | N | N031-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Hendon Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid Ceiling, Metal Air Con, PVC Cable & Lagging to, Boxing Rock Wool above False Ceiling | | | | YES | |
| 17690 | ACTIVE | N | N031-00-1/031/WAL-003 | Wall: Internal - 3 - Mess Room - Station Building - Hendon Central Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 17691 | ACTIVE | N | N031-00-1/031/WAL-004 | Wall: Internal - 4 - Mess Room - Station Building - Hendon Central Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 8407 | ACTIVE | N | N031-00-1/036 | Toilet: Unisex - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17693 | ACTIVE | N | N031-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Hendon Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plasterboards Walls Solid, Ceiling Metal Pipe, Lagging, Rock Wool above False Ceiling | | | | YES | |
| 17692 | ACTIVE | N | N031-00-1/036/WAL-001 | Wall: Internal - 1 - Toilet - Station Building - Hendon Central Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 19072 | ACTIVE | N | N031-00-1/036/WAL-004 | Wall: Internal - 4 - Toilet - Station Building - Hendon Central Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 8408 | ACTIVE | N | N031-00-1/071 | Circulation Area - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17694 | ACTIVE | N | N031-00-1/071 | Circulation Area - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N031-00 - Station Building - Hendon Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 8409 | ACTIVE | N | N031-00-1/081 | Lobby - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18223 | ACTIVE | N | N031-00-1/081 | Lobby - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8410 | ACTIVE | N | N031-00-1/082 | Lobby - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17695 | ACTIVE | N | N031-00-1/082/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Hendon Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Wood, PVC Cables, Copper pipe above False Ceiling | | | | YES | |
| 17696 | ACTIVE | N | N031-00-1/082/WDW-01 | Window - 1 - Lobby - Station Building - Hendon Central Stn | Glazing Rope | Asbestos | Surveyed – Not Detected | | | | Glass Roof/ Window. Skylight to roof. New with rubber gasket only visible from roof (VC) | | 1 | | Y | |
| 8411 | ACTIVE | N | N031-00-1/083 | Lobby - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17697 | ACTIVE | N | N031-00-1/083/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Hendon Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Wood, PVC Cables, Conduit above False Ceiling | | | | YES | |
| 18140 | ACTIVE | N | N031-00-1/083/FLR-01 | Floor - 1 - Lobby - Station Building - Hendon Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, PVC Cable beneath Computer Floor | | | | | YES |
| 8412 | ACTIVE | N | N031-00-1/084 | Lobby - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17698 | ACTIVE | N | N031-00-1/084 | Lobby - Station Building - Hendon Central Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Room | | | | | |
| 18565 | ACTIVE | N | N031-00-1/136 | Lift Shaft - Station Building - Hendon Central Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Room | | | | | |
| 8413 | ACTIVE | N | N031-00-1/186 | Station Entrance - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18083 | ACTIVE | N | N031-00-1/186 | Station Entrance - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8414 | ACTIVE | N | N031-00-1/236 | Passage - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17700 | ACTIVE | N | N031-00-1/236 | Passage - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 17699 | ACTIVE | N | N031-00-1/236 | Passage - Station Building - Hendon Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Fibreglass Lagging above Wooden Hatch | | | | | |
| 8415 | ACTIVE | N | N031-00-1/237 | Passage - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N031-00 - Station Building - Hendon Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18141 | ACTIVE | N | N031-00-1/237/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Hendon Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Skylight to roof. New with rubber gasket. Only visible from roof. (VC) | | | | YES | |
| 17701 | ACTIVE | N | N031-00-1/237/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Hendon Central Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 8416 | ACTIVE | N | N031-00-1/291 | Station Supervisor Office - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17703 | ACTIVE | N | N031-00-1/291/CLG-01 | Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Hendon Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Air Con, Pipe Work Lagging, Rock Wall, Walls Concrete, Plaster Tiles? Above False Ceiling | | | | YES | |
| 17702 | ACTIVE | N | N031-00-1/291/WAL-001 | Wall: Internal - 1 - Station Supervisor Office - Station Building - Hendon Central Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 8417 | ACTIVE | N | N031-00-1/292 | Training Room - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17704 | ACTIVE | N | N031-00-1/292/CLG-01 | Ceiling: Suspended - 1 - Training Room - Station Building - Hendon Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Breeze Block, Concrete, Pipe Work + Lagging, Rock Wall above False Ceiling | | | | YES | |
| 8418 | ACTIVE | N | N031-00-1/311 | Office - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 53529 | ACTIVE | N | N031-00-1/311 | Office - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | Skylight to roof. New with rubber gasket. Only visible from roof. (VC) | | | | | |
| 18142 | ACTIVE | N | N031-00-1/311/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Hendon Central Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18084 | ACTIVE | N | N031-00-1/311/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Hendon Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plaster Board, block walls, plaster above Supalux tiles | | | | YES | |
| 8419 | ACTIVE | N | N031-00-1/351 | Mess Room - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17706 | ACTIVE | N | N031-00-1/351/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Hendon Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Plasterboard, Conduit, PVC Cable above false Ceiling | | | | YES | |
| 17705 | ACTIVE | N | N031-00-1/351/WAL-004 | Wall: Internal - 4 - Mess Room - Station Building - Hendon Central Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 8420 | ACTIVE | N | N031-00-1/411 | Store - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N031-00 - Station Building - Hendon Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17707 | ACTIVE | N | N031-00-1/411 | Store - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8421 | ACTIVE | N | N031-00-1/416 | Toilet: Unisex - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17708 | ACTIVE | N | N031-00-1/416 | Toilet: Unisex - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8422 | ACTIVE | N | N031-00-1/426 | Toilet: Female - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18143 | ACTIVE | N | N031-00-1/426/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Hendon Central Stn | Glazing Rope | Asbestos | Surveyed – Not Detected | | | | Glass Roof - No rope seals present. (VC) | | | | | |
| 8423 | ACTIVE | N | N031-00-1/427 | Toilet: Male - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17709 | ACTIVE | N | N031-00-1/427 | Toilet: Male - Station Building - Hendon Central Stn | Glazing Rope | Asbestos | Surveyed – Not Detected | | | | Glass Roof - Glazing Rope. Glazing replaced by Close Brothers and no asbestos was detected. Refer to 4-Rail report R681726 | | | | | |
| 8424 | ACTIVE | N | N031-00-1/451 | Tenancy - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17710 | ACTIVE | N | N031-00-1/451 | Tenancy - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8425 | ACTIVE | N | N031-00-1/452 | Tenancy - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19178 | ACTIVE | N | N031-00-1/452/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - Hendon Central Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 19548 | ACTIVE | N | N031-00-1/452/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - Hendon Central Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Tiles | | | | YES | |
| 8426 | ACTIVE | N | N031-00-1/453 | Tenancy - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19550 | ACTIVE | N | N031-00-1/453/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - Hendon Central Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Tiles | | | | YES | |
| 19549 | ACTIVE | N | N031-00-1/453/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - Hendon Central Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |



Hazardous Material Asset Register - Summary



N031-00 - Station Building - Hendon Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 8427 | ACTIVE | N | N031-00-1/454 | Tenancy - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 46335 | ACTIVE | N | N031-00-1/454 | Tenancy - Station Building - Hendon Central Stn | Glazing Rope | Asbestos | Presumed | | | | Room 1/454 & 1/455 Rope within glazing bars to skylights to ceiling - 1no. | | 1 | R685276 | N | N |
| 46336 | ACTIVE | N | N031-00-1/454 | Tenancy - Station Building - Hendon Central Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Room 1/454 & 1/455 White matt and cream matt to wall and ceiling Thickness: 610µm Analysis: 0.48% | | | R685277 | N | N |
| 46337 | ACTIVE | N | N031-00-1/454 | Tenancy - Station Building - Hendon Central Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Room 1/454 & 1/455 Cream matt to top wall, boxing and cable management system Thickness: 590µm Analysis: 0.08% | | | R685277 | N | N |
| 8428 | ACTIVE | N | N031-00-1/455 | Tenancy - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8429 | ACTIVE | N | N031-00-1/576 | Stairs: Linear - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19179 | ACTIVE | N | N031-00-1/576 | Stairs: Linear - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8430 | ACTIVE | N | N031-00-1/577 | Stairs: Linear - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19551 | ACTIVE | N | N031-00-1/577 | Stairs: Linear - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8431 | ACTIVE | N | N031-00-1/601 | Stairs: Linear - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19552 | ACTIVE | N | N031-00-1/601 | Stairs: Linear - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8432 | ACTIVE | N | N031-00-1/603 | Stairs: Linear - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19553 | ACTIVE | N | N031-00-1/603 | Stairs: Linear - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8433 | ACTIVE | N | N031-00-1/631 | Stairs: Spiral - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19180 | ACTIVE | N | N031-00-1/631 | Stairs: Spiral - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N031-00 - Station Building - Hendon Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 19612 | ACTIVE | N | N031-00-1/636 | Overbridge - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8434 | ACTIVE | N | N031-00-1/746 | SCR - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19554 | ACTIVE | N | N031-00-1/746 | SCR - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8435 | ACTIVE | N | N031-00-1/776 | Plant Room - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19555 | ACTIVE | N | N031-00-1/776/CLG-01 80903936 | Ceiling: Solid - 1 - Plant Room - Station Building - Hendon Central Stn Ceiling: Solid | Void | Asbestos | No Access: Presumed | | | | Above false ceiling. Fixed ceiling. No access | | | | YES | |
| 19748 | ACTIVE | N | N031-00-1/776/CLG-01 | Ceiling: Solid - 1 - Plant Room - Station Building - Hendon Central Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Plasterboard - 4no Pads Supalux | | | | | |
| 8436 | ACTIVE | N | N031-00-1/777 | Plant Room - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19556 | ACTIVE | N | N031-00-1/777 | Plant Room - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8437 | ACTIVE | N | N031-00-1/951 | Locker Room - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19181 | ACTIVE | N | N031-00-1/951/CLG-01 | Ceiling: Suspended - 1 - Locker Room - Station Building - Hendon Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid, PVC Cables, Conduit above False Ceiling | | | | YES | |
| 19557 | ACTIVE | N | N031-00-1/951/WAL-003 | Wall: Internal - 3 - Locker Room - Station Building - Hendon Central Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | LUL Heater with foam panel | | 1 | | | |
| 8438 | ACTIVE | N | N031-00-1/952 | Mess Room - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19241 | ACTIVE | N | N031-00-1/952 | Mess Room - Station Building - Hendon Central Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | LUL Heater with foam panel | | 1 | | | |
| 19558 | ACTIVE | N | N031-00-1/952 | Mess Room - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 8439 | ACTIVE | N | N031-00-2/081 | Lobby - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19559 | ACTIVE | N | N031-00-2/081/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Hendon Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid, Conduit, PVC Cables, Air Con, Lagging Rock Wool above False Ceiling | | | | YES | |



Hazardous Material Asset Register - Summary



N031-00 - Station Building - Hendon Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 8440 | ACTIVE | N | N031-00-2/082 | Lobby - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8441 | ACTIVE | N | N031-00-2/083 | Lobby - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8442 | ACTIVE | N | N031-00-2/131 | Lift Pump Room - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19560 | ACTIVE | N | N031-00-2/131 | Lift Pump Room - Station Building - Hendon Central Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Room | | | | | |
| 8443 | ACTIVE | N | N031-00-2/136 | Passage - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8444 | ACTIVE | N | N031-00-2/236 | Passage - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19820 | ACTIVE | N | N031-00-2/236 | Passage - Station Building - Hendon Central Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Part Plasterboard | | | | | |
| 8445 | ACTIVE | N | N031-00-2/261 | Platform 1 - Northbound Local - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19182 | ACTIVE | N | N031-00-2/261 | Platform 1 - Northbound Local - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 67986 | ACTIVE | N | N031-00-2/261 | Platform 1 - Northbound Local - Station Building - Hendon Central Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | White gloss - Cable management system pipes to columns - 0.44% | | | R739278 | | |
| 67990 | ACTIVE | N | N031-00-2/261 | Platform 1 - Northbound Local - Station Building - Hendon Central Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Black gloss - Cable management system pipes to columns - 0.38% | | | R739278 | | |
| 67980 | ACTIVE | N | N031-00-2/261 | Platform 1 - Northbound Local - Station Building - Hendon Central Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | White gloss - metal columns - 0.02% | | | R739278 | | |
| 67984 | ACTIVE | N | N031-00-2/261 | Platform 1 - Northbound Local - Station Building - Hendon Central Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Black gloss - Metal columns - <0.02% | | | R739278 | | |
| 67982 | ACTIVE | N | N031-00-2/261 | Platform 1 - Northbound Local - Station Building - Hendon Central Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Green gloss - Metal columns - 0.11% | | | R739278 | | |
| 67994 | ACTIVE | N | N031-00-2/261 | Platform 1 - Northbound Local - Station Building - Hendon Central Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Green gloss - Platform canopy - 3.65% | | | R739278 | | |



Hazardous Material Asset Register - Summary



N031-00 - Station Building - Hendon Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 67988 | ACTIVE | N | N031-00-2/261 | Platform 1 - Northbound Local - Station Building - Hendon Central Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Green gloss - Cable management system pipes to columns - 0.28% | | | R739278 | | |
| 67992 | ACTIVE | N | N031-00-2/261 | Platform 1 - Northbound Local - Station Building - Hendon Central Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | White gloss - Platform canopy - 0.05% | | | R739278 | | |
| 8446 | ACTIVE | N | N031-00-2/262 | Platform 2 - Southbound Local - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19561 | ACTIVE | N | N031-00-2/262 | Platform 2 - Southbound Local - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 67987 | ACTIVE | N | N031-00-2/262 | Platform 2 - Southbound Local - Station Building - Hendon Central Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | White gloss - Cable management system pipes to columns - 0.44% | | | R739278 | | |
| 67989 | ACTIVE | N | N031-00-2/262 | Platform 2 - Southbound Local - Station Building - Hendon Central Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Green gloss - Cable management system pipes to columns - 0.28% | | | R739278 | | |
| 67995 | ACTIVE | N | N031-00-2/262 | Platform 2 - Southbound Local - Station Building - Hendon Central Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Green gloss - Platform canopy - 3.65% | | | R739278 | | |
| 67983 | ACTIVE | N | N031-00-2/262 | Platform 2 - Southbound Local - Station Building - Hendon Central Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Green gloss - Metal columns - 0.11% | | | R739278 | | |
| 67985 | ACTIVE | N | N031-00-2/262 | Platform 2 - Southbound Local - Station Building - Hendon Central Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Black gloss - Metal columns - <0.02% | | | R739278 | | |
| 67993 | ACTIVE | N | N031-00-2/262 | Platform 2 - Southbound Local - Station Building - Hendon Central Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | White gloss - Platform canopy - 0.05% | | | R739278 | | |
| 67981 | ACTIVE | N | N031-00-2/262 | Platform 2 - Southbound Local - Station Building - Hendon Central Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | White gloss - Metal columns - 0.02% | | | R739278 | | |
| 67991 | ACTIVE | N | N031-00-2/262 | Platform 2 - Southbound Local - Station Building - Hendon Central Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Black gloss - Cable management system pipes to columns - 0.38% | | | R739278 | | |
| 8447 | ACTIVE | N | N031-00-2/301 | Office - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19183 | ACTIVE | N | N031-00-2/301/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Hendon Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plaster Tiles, Computer Tiles, Solid, PVC Cable, Conduit Lagging to Pipe Rock Wool above Supalux Tiles | | | | YES | |
| 19562 | ACTIVE | N | N031-00-2/301/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Hendon Central Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |



Hazardous Material Asset Register - Summary



N031-00 - Station Building - Hendon Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 8448 | ACTIVE | N | N031-00-2/302 | GSM Office - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19564 | ACTIVE | N | N031-00-2/302/CLG-01 | Ceiling: Suspended - 1 - GSM Office - Station Building - Hendon Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete Ceiling, Copper Pipe, Lagging Rock Wall PVC Cables, Conduit above False Ceiling | | | | YES | |
| 19563 | ACTIVE | N | N031-00-2/302/WAL-002 | Wall: Internal - 2 - GSM Office - Station Building - Hendon Central Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 8449 | ACTIVE | N | N031-00-2/303 | Office - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19613 | ACTIVE | N | N031-00-2/303/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Hendon Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid, Wood, PVC Cable, Lagging Rock Wool above False Ceiling | | | | YES | |
| 8450 | ACTIVE | N | N031-00-2/361 | Mess Room - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19565 | ACTIVE | N | N031-00-2/361 | Mess Room - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 19566 | ACTIVE | N | N031-00-2/361/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Hendon Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid, PVC Cable, Pipe Work, Lagging Rock Wool above False Ceiling | | | | YES | |
| 8451 | ACTIVE | N | N031-00-2/401 | Bin Store - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19567 | ACTIVE | N | N031-00-2/401 | Bin Store - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8452 | ACTIVE | N | N031-00-2/402 | Bin Store - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19568 | ACTIVE | N | N031-00-2/402 | Bin Store - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8453 | ACTIVE | N | N031-00-2/406 | Store - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19184 | ACTIVE | N | N031-00-2/406 | Store - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8454 | ACTIVE | N | N031-00-2/411 | Store - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19569 | ACTIVE | N | N031-00-2/411 | Store - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N031-00 - Station Building - Hendon Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 8455 | ACTIVE | N | N031-00-2/412 | Store - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19570 | ACTIVE | N | N031-00-2/412 | Store - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8456 | ACTIVE | N | N031-00-2/413 | Store - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19185 | ACTIVE | N | N031-00-2/413 | Store - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8457 | ACTIVE | N | N031-00-2/414 | Store - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19571 | ACTIVE | N | N031-00-2/414 | Store - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8458 | ACTIVE | N | N031-00-2/415 | Store - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19572 | ACTIVE | N | N031-00-2/415 | Store - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8459 | ACTIVE | N | N031-00-2/416 | Toilet: Unisex - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19573 | ACTIVE | N | N031-00-2/416/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Hendon Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid - Pointed Artex above False Ceiling | | | | YES | |
| 8460 | ACTIVE | N | N031-00-2/436 | Waiting Room - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8461 | ACTIVE | N | N031-00-2/451 | Tenancy - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19186 | ACTIVE | N | N031-00-2/451 | Tenancy - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8462 | ACTIVE | N | N031-00-2/551 | Yard - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19619 | ACTIVE | N | N031-00-2/551 | Yard - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8463 | ACTIVE | N | N031-00-2/552 | Yard - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N031-00 - Station Building - Hendon Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 19873 | ACTIVE | N | N031-00-2/552 | Yard - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8464 | ACTIVE | N | N031-00-2/603 | Stairs: Linear - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8465 | ACTIVE | N | N031-00-2/661 | Switch Room - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19243 | ACTIVE | N | N031-00-2/661/WAL-001 80904302 | Wall: Internal - 1 - Switch Room - Station Building - Hendon Central Stn Wall: Internal | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | 1 x Transformer Box. Presumed asbestos insulating materials within. No access to inspect internally. Electrical isolation required. 13/09/2023 | | 1 | | | |
| 20340 | ACTIVE | N | N031-00-2/661/WAL-001 80904302 | Wall: Internal - 1 - Switch Room - Station Building - Hendon Central Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 2 x 100 amp Switch Boxes. Presumed asbestos insulating materials within. No access to inspect internally. Electrical isolations required 13/09/2023 | | 2 | | | |
| 19620 | ACTIVE | N | N031-00-2/661/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Hendon Central Stn | Other Electrical Boxes | Asbestos | Room: Surveyed: Asbestos Presumed | | | | 1 x Transformer Box | | 1 | | | |
| 20343 | INACTIVE | N | N031-00-2/661/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Hendon Central Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 2 x Switch Boxes | | 2 | | | |
| 20339 | ACTIVE | N | N031-00-2/661/WAL-002 80904303 | Wall: Internal - 2 - Switch Room - Station Building - Hendon Central Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 7 x 100 amp, 1 x 60 amp Switch Boxes. Presumed asbestos insulating materials within. No access to inspect internally. Electrical isolation required 13/09/2023 | | 8 | | | |
| 20344 | INACTIVE | N | N031-00-2/661/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Hendon Central Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 8 x Switch Boxes | | 8 | | | |
| 64654 | ACTIVE | N | N031-00-2/661/WAL-003 80904304 | Wall: Internal - 3 - Switch Room - Station Building - Hendon Central Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 1x combination fuse box 100amps. No access to inspect internally. Electrical isolations required. 13/09/2023 | | 1 | | | |
| 20341 | ACTIVE | N | N031-00-2/661/WAL-003 80904304 | Wall: Internal - 3 - Switch Room - Station Building - Hendon Central Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 x 100 amp Switch Box. Presumed asbestos insulating materials within. No access to inspect internally. Electrically isolations required 13/09/2023 | | 1 | | | |
| 20346 | ACTIVE | N | N031-00-2/661/WAL-004 80904305 | Wall: Internal - 4 - Switch Room - Station Building - Hendon Central Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 x Switch Box. Presumed asbestos insulating materials within. No access to inspect internally. Electrical isolations required. 13/09/2023 | | 1 | | | |
| 20345 | INACTIVE | N | N031-00-2/661/WAL-004 | Wall: Internal - 4 - Switch Room - Station Building - Hendon Central Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | 3 x Transformer Boxes. Presumed asbestos containing materials within | | 3 | | | |



Hazardous Material Asset Register - Summary



N031-00 - Station Building - Hendon Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|--------------------------------|--|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 20342 | ACTIVE | N | N031-00-2/661/WAL-004 80904305 | Wall: Internal - 4 - Switch Room - Station Building - Hendon Central Stn Wall: Internal | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | 3 x Transformer Boxes. Presumed asbestos containing materials within. No access to inspect internally. Electrical isolations required. 13/09/2023 | | 3 | | | |
| 8466 | ACTIVE | N | N031-00-2/662 | Switch Room - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19621 | ACTIVE | N | N031-00-2/662 | Switch Room - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8467 | ACTIVE | N | N031-00-2/663 | Switch Room - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19622 | ACTIVE | N | N031-00-2/663 | Switch Room - Station Building - Hendon Central Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Room | | | | | |
| 8468 | ACTIVE | N | N031-00-2/731 | CER - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19624 | ACTIVE | N | N031-00-2/731/FLR-01 | Floor - 1 - CER - Station Building - Hendon Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | PVC Cable, Trunking, Concrete beneath Computer Floor | | | | | YES |
| 8469 | ACTIVE | N | N031-00-2/761 | Equipment Room - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19244 | ACTIVE | N | N031-00-2/761 | Equipment Room - Station Building - Hendon Central Stn | Gasket :Pipework | Asbestos | Surveyed – Not Detected | | | | Compressed Cardboard | | | | | |
| 8470 | ACTIVE | N | N031-00-2/951 | Disused Room - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19625 | ACTIVE | N | N031-00-2/951/WAL-004 | Wall: Internal - 4 - Disused Room - Station Building - Hendon Central Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels | | | | | |
| 8471 | ACTIVE | N | N031-00-2/952 | Store - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19626 | ACTIVE | N | N031-00-2/952 | Store - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8472 | ACTIVE | N | N031-00-A/778 | Plant Room - Station Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19627 | ACTIVE | N | N031-00-A/778 | Plant Room - Station Building - Hendon Central Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N033-00 - Station Building - Brent Cross Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|--------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 8479 | ACTIVE | N | N033-00-1/001 | Booking Hall - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17851 | ACTIVE | N | N033-00-1/001 | Booking Hall - Station Building - Brent Cross Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8480 | ACTIVE | N | N033-00-1/011 | Ticket Office - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17853 | ACTIVE | N | N033-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Brent Cross Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Plaster & Tiles | | | | YES | |
| 17852 | ACTIVE | N | N033-00-1/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Brent Cross Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Floor | | | | | YES |
| 8481 | ACTIVE | N | N033-00-1/021 | POM - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18388 | ACTIVE | N | N033-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Brent Cross Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Plaster & Tiles | | | | YES | |
| 18158 | ACTIVE | N | N033-00-1/021/FLR-01 | Floor - 1 - POM - Station Building - Brent Cross Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Floor | | | | | YES |
| 8482 | ACTIVE | N | N033-00-1/031 | Mess Room - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17854 | ACTIVE | N | N033-00-1/031 | Mess Room - Station Building - Brent Cross Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 8483 | ACTIVE | N | N033-00-1/036 | Toilet: Unisex - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17855 | ACTIVE | N | N033-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Brent Cross Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Plaster & Tiles | | | | YES | |
| 8484 | ACTIVE | N | N033-00-1/071 | Circulation Area - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17856 | ACTIVE | N | N033-00-1/071 | Circulation Area - Station Building - Brent Cross Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8485 | ACTIVE | N | N033-00-1/081 | Lobby - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17857 | ACTIVE | N | N033-00-1/081/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Brent Cross Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Plaster & Tiles | | | | YES | |



Hazardous Material Asset Register - Summary



N033-00 - Station Building - Brent Cross Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 18389 | ACTIVE | N | N033-00-1/081/FLR-01 | Floor - 1 - Lobby - Station Building - Brent Cross Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Floor | | | | | YES |
| 8486 | ACTIVE | N | N033-00-1/082 | Lobby - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17858 | ACTIVE | N | N033-00-1/082/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Brent Cross Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 17859 | ACTIVE | N | N033-00-1/082/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Brent Cross Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 8487 | ACTIVE | N | N033-00-1/201 | Passage - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17860 | ACTIVE | N | N033-00-1/201 | Passage - Station Building - Brent Cross Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8488 | ACTIVE | N | N033-00-1/316 | Locker Room - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17861 | ACTIVE | N | N033-00-1/316 | Locker Room - Station Building - Brent Cross Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8489 | ACTIVE | N | N033-00-1/371 | Store - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18390 | ACTIVE | N | N033-00-1/371 | Store - Station Building - Brent Cross Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8490 | ACTIVE | N | N033-00-1/372 | Mess Room - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18225 | ACTIVE | N | N033-00-1/372/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Brent Cross Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 18474 | ACTIVE | N | N033-00-1/372/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Brent Cross Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 8491 | ACTIVE | N | N033-00-1/401 | Bin Store - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17862 | ACTIVE | N | N033-00-1/401 | Bin Store - Station Building - Brent Cross Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8492 | ACTIVE | N | N033-00-1/402 | Bin Store - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N033-00 - Station Building - Brent Cross Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17863 | ACTIVE | N | N033-00-1/402 | Bin Store - Station Building - Brent Cross Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8493 | ACTIVE | N | N033-00-1/406 | Store - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17864 | ACTIVE | N | N033-00-1/406 | Store - Station Building - Brent Cross Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8494 | ACTIVE | N | N033-00-1/407 | Store - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18391 | ACTIVE | N | N033-00-1/407 | Store - Station Building - Brent Cross Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8495 | ACTIVE | N | N033-00-1/416 | Toilet: Female - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19081 | ACTIVE | N | N033-00-1/416/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Brent Cross Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete & Fibre Glass Lagging above Supalux Tiles | | | | YES | |
| 17865 | ACTIVE | N | N033-00-1/416/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Brent Cross Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 17866 | ACTIVE | N | N033-00-1/416/WDW-01 | Window - 1 - Toilet - Station Building - Brent Cross Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Window Frames : White Gloss Coating - Thickness 0.19mm : Analysis 1.43% | | | | | |
| 8496 | ACTIVE | N | N033-00-1/417 | Toilet: Male - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18392 | ACTIVE | N | N033-00-1/417/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Brent Cross Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 17867 | ACTIVE | N | N033-00-1/417/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Brent Cross Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 17868 | ACTIVE | N | N033-00-1/417/WDW-01 | Window - 1 - Toilet - Station Building - Brent Cross Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Window Frames : White Gloss Coating - Thickness 0.19mm : Analysis 1.43% | | | | | |
| 17869 | ACTIVE | N | N033-00-1/417/WDW-02 | Window - 2 - Toilet - Station Building - Brent Cross Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Window Frames : White Gloss Coating - Thickness 0.19mm : Analysis 1.43% | | | | | |
| 8497 | ACTIVE | N | N033-00-1/418 | Shower Room - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18159 | ACTIVE | N | N033-00-1/418 | Shower Room - Station Building - Brent Cross Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Window Frames : White Gloss Coating - Thickness 0.19mm : Analysis 1.43%. No windows in shower room. Possibly blocked off, check external | | | | | |



Hazardous Material Asset Register - Summary



N033-00 - Station Building - Brent Cross Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|--------------------------------|---|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 17870 | ACTIVE | N | N033-00-1/418/CLG-01 | Ceiling: Suspended - 1 - Shower Room - Station Building - Brent Cross Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18393 | ACTIVE | N | N033-00-1/418/CLG-01 | Ceiling: Suspended - 1 - Shower Room - Station Building - Brent Cross Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 8498 | ACTIVE | N | N033-00-1/551 | Yard - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17871 | ACTIVE | N | N033-00-1/551 | Yard - Station Building - Brent Cross Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8499 | ACTIVE | N | N033-00-1/661 | Switch Room - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Strongly Presumed | | | | | | | | | |
| 17872 | ACTIVE | N | N033-00-1/661 | Switch Room - Station Building - Brent Cross Stn | Cable Duct: Other | Asbestos | Strongly Presumed | | | | Approx 6x Cable Ducts. To floor by Wall 1 & 4 in corner. | | 6 | | | |
| 20347 | ACTIVE | N | N033-00-1/661/WAL-001 80896377 | Wall: Internal - 1 - Switch Room - Station Building - Brent Cross Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 x Fuse Box 30 amp. Presumed asbestos insulating materials within. No access internally to inspect during re-inspection. Electrical isolations required. | | 1 | | | |
| 17873 | ACTIVE | N | N033-00-1/661/WAL-001 80896377 | Wall: Internal - 1 - Switch Room - Station Building - Brent Cross Stn Wall: Internal | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | 4 x Transformer Boxes - Presumed asbestos containing materials within. No access internally to inspect during re-inspection. Electrical isolations required. | | 4 | | | |
| 20348 | ACTIVE | N | N033-00-1/661/WAL-002 80896378 | Wall: Internal - 2 - Switch Room - Station Building - Brent Cross Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | Electrical Box. Presumed asbestos insulating materials within. No access internally to inspect during re-inspection. Electrical isolations required. | | 1 | | | |
| 19494 | ACTIVE | N | N033-00-1/661/WAL-003 80896379 | Wall: Internal - 3 - Switch Room - Station Building - Brent Cross Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 4 x 60 amp, 2 x 100 amp Combination Fuse Switches. Presumed asbestos insulating materials within. No access internally to inspect during re-inspection. Electrical isolations required. | | 6 | | | |
| 8500 | ACTIVE | N | N033-00-1/662 | Computer Equipment Cupboard - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18394 | ACTIVE | N | N033-00-1/662 | Computer Equipment Cupboard - Station Building - Brent Cross Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8501 | ACTIVE | N | N033-00-1/663 | Switch Cupboard - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17874 | ACTIVE | N | N033-00-1/663/WLS | Walls: Internal - Switch Cupboard - Station Building - Brent Cross Stn | No Access | Asbestos | Surveyed – Not Detected | | | | New Build - Wall 2 Electrical Equipment | | | | | |



Hazardous Material Asset Register - Summary



N033-00 - Station Building - Brent Cross Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 8502 | ACTIVE | N | N033-00-1/746 | SCR - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17876 | ACTIVE | N | N033-00-1/746 | SCR - Station Building - Brent Cross Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8503 | ACTIVE | N | N033-00-A/261 | Platform 1 - Northbound Local - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17877 | ACTIVE | N | N033-00-A/261 | Platform 1 - Northbound Local - Station Building - Brent Cross Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 67969 | ACTIVE | N | N033-00-A/261 | Platform 1 - Northbound Local - Station Building - Brent Cross Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Blue gloss - metal canopy columns - 3.25% | | | R739277 | | |
| 67975 | ACTIVE | N | N033-00-A/261 | Platform 1 - Northbound Local - Station Building - Brent Cross Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Blue matt - Canopy - 0.36% | | | R739277 | | |
| 67971 | ACTIVE | N | N033-00-A/261 | Platform 1 - Northbound Local - Station Building - Brent Cross Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Black gloss - metal canopy columns - 4.6% | | | R739277 | | |
| 67966 | ACTIVE | N | N033-00-A/261 | Platform 1 - Northbound Local - Station Building - Brent Cross Stn | Lead/Leading | Lead Paint/Lead | Known | | | | White gloss - metal canopy columns - 1.12% | | | R739277 | | |
| 67977 | ACTIVE | N | N033-00-A/261 | Platform 1 - Northbound Local - Station Building - Brent Cross Stn | Lead/Leading | Lead Paint/Lead | Known | | | | White gloss - Canopy - 27.1% | | | R739277 | | |
| 67973 | ACTIVE | N | N033-00-A/261 | Platform 1 - Northbound Local - Station Building - Brent Cross Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Cream gloss - Canopy - 21% | | | R739277 | | |
| 8504 | ACTIVE | N | N033-00-A/262 | Platform 2 - Southbound Local - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18160 | ACTIVE | N | N033-00-A/262 | Platform 2 - Southbound Local - Station Building - Brent Cross Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 67972 | ACTIVE | N | N033-00-A/262 | Platform 2 - Southbound Local - Station Building - Brent Cross Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Black gloss - metal canopy columns - 4.6% | | | R739277 | | |
| 67978 | ACTIVE | N | N033-00-A/262 | Platform 2 - Southbound Local - Station Building - Brent Cross Stn | Lead/Leading | Lead Paint/Lead | Known | | | | White gloss - Canopy - 27.1% | | | R739277 | | |
| 67970 | ACTIVE | N | N033-00-A/262 | Platform 2 - Southbound Local - Station Building - Brent Cross Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Blue gloss - metal canopy columns - 3.25% | | | R739277 | | |



Hazardous Material Asset Register - Summary



N033-00 - Station Building - Brent Cross Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 67968 | ACTIVE | N | N033-00-A/262 | Platform 2 - Southbound Local - Station Building - Brent Cross Stn | Lead/Leading | Lead Paint/Lead | Known | | | | White gloss - metal canopy columns - 1.12% | | | R739277 | | |
| 67976 | ACTIVE | N | N033-00-A/262 | Platform 2 - Southbound Local - Station Building - Brent Cross Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Blue matt - Canopy - 0.36% | | | R739277 | | |
| 67974 | ACTIVE | N | N033-00-A/262 | Platform 2 - Southbound Local - Station Building - Brent Cross Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Cream gloss - Canopy - 21% | | | R739277 | | |
| 8505 | ACTIVE | N | N033-00-A/411 | Waiting Room - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18395 | ACTIVE | N | N033-00-A/411 | Waiting Room - Station Building - Brent Cross Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | YES | |
| 8506 | ACTIVE | N | N033-00-A/601 | Stairs: Linear - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17878 | ACTIVE | N | N033-00-A/601 | Stairs: Linear - Station Building - Brent Cross Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8507 | ACTIVE | N | N033-00-A/602 | Stairs: Linear - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17879 | ACTIVE | N | N033-00-A/602 | Stairs: Linear - Station Building - Brent Cross Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8508 | ACTIVE | N | N033-00-A/661 | Relay Room - Station Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N041-00 - Station Building - Golders Green Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---------------------|-------------|------------|-------------|---------------------|-------------------|
| 8512 | ACTIVE | N | N041-00-1/001 | Booking Hall - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18088 | ACTIVE | N | N041-00-1/001/CLG-01 | Ceiling: Suspended - 1 - Booking Hall - Station Building - Golders Green Stn | Void | Asbestos | No Access: Presumed | | | | Above false ceiling | | | | YES | |
| 17752 | ACTIVE | N | N041-00-1/001/CLG-01 | Ceiling: Suspended - 1 - Booking Hall - Station Building - Golders Green Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 8513 | ACTIVE | N | N041-00-1/011 | Ticket Office - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N041-00 - Station Building - Golders Green Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 17754 | ACTIVE | N | N041-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 18298 | ACTIVE | N | N041-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Golders Green Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux & Acoustic Tiles | | | | | |
| 17753 | ACTIVE | N | N041-00-1/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Golders Green Stn | Void | Asbestos | No Access: Presumed | | | | Beneath tiles | | | | | YES |
| 8514 | ACTIVE | N | N041-00-1/021 | POM - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17755 | ACTIVE | N | N041-00-1/021 | POM - Station Building - Golders Green Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Boarding on Wall - Non Asbestos | | | | | |
| 8515 | ACTIVE | N | N041-00-1/031 | Office - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17756 | ACTIVE | N | N041-00-1/031 | Office - Station Building - Golders Green Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater with foam insulation. Vent grid - Solid | | | | | |
| 17757 | ACTIVE | N | N041-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Golders Green Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding | | | | | |
| 17758 | ACTIVE | N | N041-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Fibreglass above false ceiling | | | | YES | |
| 8516 | ACTIVE | N | N041-00-1/036 | Toilet: Unisex - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18299 | ACTIVE | N | N041-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Golders Green Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 17759 | ACTIVE | N | N041-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plaster, Concrete, Fibreglass lagging above false ceiling | | | | YES | |
| 8517 | ACTIVE | N | N041-00-1/047 | Kitchen - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18300 | ACTIVE | N | N041-00-1/047 | Kitchen - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 17760 | ACTIVE | N | N041-00-1/047/CLG-01 | Ceiling: Suspended - 1 - Kitchen - Station Building - Golders Green Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard Tiles | | | | | |
| 17761 | ACTIVE | N | N041-00-1/047/CLG-01 | Ceiling: Suspended - 1 - Kitchen - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above plasterboard tiles | | | | YES | |



Hazardous Material Asset Register - Summary



N041-00 - Station Building - Golders Green Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 8518 | ACTIVE | N | N041-00-1/071 | Circulation Area - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17763 | ACTIVE | N | N041-00-1/071 | Circulation Area - Station Building - Golders Green Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 18301 | ACTIVE | N | N041-00-1/071/CLG-01 | Ceiling: Suspended - 1 - Circulation Area - Station Building - Golders Green Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Tiles | | | | YES | |
| 17762 | ACTIVE | N | N041-00-1/071/CLG-01 | Ceiling: Suspended - 1 - Circulation Area - Station Building - Golders Green Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 8519 | ACTIVE | N | N041-00-1/081 | Lobby - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19414 | ACTIVE | N | N041-00-1/081 | Lobby - Station Building - Golders Green Stn | Void | Asbestos | No Access: Presumed | | | | Behind wood panels. No wood panels visible | | | | | |
| 18568 | ACTIVE | N | N041-00-1/081/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Acoustic Panel | | | | YES | |
| 8520 | ACTIVE | N | N041-00-1/082 | Lobby - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17764 | ACTIVE | N | N041-00-1/082/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Golders Green Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Lay in tiles/ Plasterboard | | | | | |
| 17765 | ACTIVE | N | N041-00-1/082/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 18302 | ACTIVE | N | N041-00-1/136 | Lift Shaft - Station Building - Golders Green Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Room | | | | | |
| 19076 | ACTIVE | N | N041-00-1/137 | Lift Shaft - Station Building - Golders Green Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Room | | | | | |
| 8521 | ACTIVE | N | N041-00-1/201 | Passage - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17766 | ACTIVE | N | N041-00-1/201/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | Bituminous Ceiling | | | | | |
| 8522 | ACTIVE | N | N041-00-1/202 | Passage - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17767 | ACTIVE | N | N041-00-1/202/FLR-01 | Floor - 1 - Passage - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | Bituminous Flooring | | | | | |



Hazardous Material Asset Register - Summary



N041-00 - Station Building - Golders Green Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|-------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 8523 | ACTIVE | N | N041-00-1/203 | Passage - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17768 | ACTIVE | N | N041-00-1/203/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Golders Green Stn | Void | Asbestos | No Access: Presumed | | | | No Access above Tiled Ceiling | | | | N | |
| 20350 | INACTIVE | N | N041-00-1/203/CLG-02 | Ceiling: Solid - 2 - Passage - Station Building - Golders Green Stn | No Access | Asbestos | No Access: Presumed | | | | No Access above Tiled Ceiling | | | | N | |
| 20351 | ACTIVE | N | N041-00-1/203/FLR-01 | Floor - 1 - Passage - Station Building - Golders Green Stn | No Access | Asbestos | No Access: Presumed | | | | No access beneath Hatch in floor | | | | | N |
| 20352 | ACTIVE | N | N041-00-1/203/WLS | Walls: Internal - Passage - Station Building - Golders Green Stn | Lead/Leading | Lead Paint/Lead | Presumed | | | | Possible Lead Paint to Walls and Pipework | | | | N | N |
| 8524 | ACTIVE | N | N041-00-1/204 | Passage - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18148 | ACTIVE | N | N041-00-1/204 | Passage - Station Building - Golders Green Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Room | | | | | |
| 8525 | ACTIVE | N | N041-00-1/236 | Passage - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17769 | ACTIVE | N | N041-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete & Breeze Block beneath false ceiling | | | | YES | |
| 18303 | ACTIVE | N | N041-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Golders Green Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux & Acoustic Tiles | | | | | |
| 8526 | ACTIVE | N | N041-00-1/237 | Passage - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17770 | ACTIVE | N | N041-00-1/237 | Passage - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Non visible | | | | | |
| 8527 | ACTIVE | N | N041-00-1/238 | Passage - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17771 | ACTIVE | N | N041-00-1/238/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Golders Green Stn | Void | Asbestos | No Access: Presumed | | | | Above steel ceiling | | | | YES | |
| 8528 | ACTIVE | N | N041-00-1/239 | Lobby - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N041-00 - Station Building - Golders Green Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 17772 | ACTIVE | N | N041-00-1/239/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Steel above Acoustic Panels | | | | YES | |
| 8529 | ACTIVE | N | N041-00-1/311 | Locker Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18304 | ACTIVE | N | N041-00-1/311/CLG-01 | Ceiling: Suspended - 1 - Locker Room - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal Sheets; Lagging - Fibreglass above Lay in tiles | | | | YES | |
| 8530 | ACTIVE | N | N041-00-1/316 | Locker Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17773 | ACTIVE | N | N041-00-1/316/CLG-01 | Ceiling: Suspended - 1 - Locker Room - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plasterboard; Fibreglass Lagging above false ceiling | | | | YES | |
| 8531 | ACTIVE | N | N041-00-1/317 | Locker Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18149 | ACTIVE | N | N041-00-1/317 | Locker Room - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8532 | ACTIVE | N | N041-00-1/341 | Mess Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17774 | ACTIVE | N | N041-00-1/341 | Mess Room - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 17775 | ACTIVE | N | N041-00-1/341/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Steel above Acoustic Panels | | | | YES | |
| 8533 | ACTIVE | N | N041-00-1/401 | Bin Store - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17776 | ACTIVE | N | N041-00-1/401 | Bin Store - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8534 | ACTIVE | N | N041-00-1/402 | Bin Store - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18305 | ACTIVE | N | N041-00-1/402 | Bin Store - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8535 | ACTIVE | N | N041-00-1/406 | Store - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17777 | ACTIVE | N | N041-00-1/406 | Store - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N041-00 - Station Building - Golders Green Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 8536 | ACTIVE | N | N041-00-1/407 | Store - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17778 | ACTIVE | N | N041-00-1/407/CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Acoustic Panels | | | | YES | |
| 8537 | ACTIVE | N | N041-00-1/411 | Store - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17779 | ACTIVE | N | N041-00-1/411 | Store - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8538 | ACTIVE | N | N041-00-1/413 | Store - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18150 | ACTIVE | N | N041-00-1/413 | Store - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8539 | ACTIVE | N | N041-00-1/414 | Store - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19077 | ACTIVE | N | N041-00-1/414 | Store - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8540 | ACTIVE | N | N041-00-1/415 | Store - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18306 | ACTIVE | N | N041-00-1/415 | Store - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8541 | ACTIVE | N | N041-00-1/416 | Toilet: Male - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17780 | ACTIVE | N | N041-00-1/416 | Toilet: Male - Station Building - Golders Green Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Wooden Panels above Windows | | | | | |
| 17781 | ACTIVE | N | N041-00-1/416/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Fibreglass Lagging above Acoustic Panel | | | | YES | |
| 8542 | ACTIVE | N | N041-00-1/417 | Toilet: Female - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17782 | ACTIVE | N | N041-00-1/417 | Toilet: Female - Station Building - Golders Green Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Boxing Plasterboard | | | | | |
| 8543 | ACTIVE | N | N041-00-1/418 | Toilet: Male - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N041-00 - Station Building - Golders Green Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|--------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 18569 | ACTIVE | N | N041-00-1/418/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Acoustic Panels | | | | YES | |
| 8544 | ACTIVE | N | N041-00-1/419 | Toilet: Female - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17783 | ACTIVE | N | N041-00-1/419/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Acoustic Panels | | | | YES | |
| 8545 | ACTIVE | N | N041-00-1/420 | Toilet: Unisex - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17784 | ACTIVE | N | N041-00-1/420 | Toilet: Unisex - Station Building - Golders Green Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Room | | | | | |
| 8546 | ACTIVE | N | N041-00-1/451 | Tenancy - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18307 | ACTIVE | N | N041-00-1/451 | Tenancy - Station Building - Golders Green Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Tenancy | | | | | |
| 8547 | ACTIVE | N | N041-00-1/452 | Tenancy - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17785 | ACTIVE | N | N041-00-1/452 | Tenancy - Station Building - Golders Green Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Tenancy | | | | | |
| 8548 | ACTIVE | N | N041-00-1/481 | Void - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17786 | ACTIVE | N | N041-00-1/481 | Void - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8549 | ACTIVE | N | N041-00-1/551 | Yard - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20029 | ACTIVE | N | N041-00-1/551 | Yard - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8550 | ACTIVE | N | N041-00-1/552 | Passage - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17787 | ACTIVE | N | N041-00-1/552 | Passage - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8551 | ACTIVE | N | N041-00-1/661 | Switch Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



| N041-00 - Station Building - Golders Green Stn | | | | | | | | | | | | | | | | |
|--|--------|-------------|--------------------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
| 19493 | ACTIVE | N | N041-00-1/661/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | Re Inspected 24/07/2014 - nothing on this wall | | | | | |
| 18308 | ACTIVE | N | N041-00-1/661/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | Re Inspected 24/07/2014 | | | | | |
| 18151 | ACTIVE | N | N041-00-1/661/WAL-004 80917029 | Wall: Internal - 4 - Switch Room - Station Building - Golders Green Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | 3 x Transformer Boxes No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 3 | | N | N |
| 20353 | ACTIVE | N | N041-00-1/661/WAL-004 80917029 | Wall: Internal - 4 - Switch Room - Station Building - Golders Green Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 x Switch Box 30amp No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | | |
| 20357 | ACTIVE | N | N041-00-1/661/WAL-004 80917029 | Wall: Internal - 4 - Switch Room - Station Building - Golders Green Stn Wall: Internal | Void | Asbestos | No Access: Presumed | | | | No access behind wall hatch. High level. High level access required | | | | | N |
| 20355 | ACTIVE | N | N041-00-1/661/WAL-006 | Wall: Internal - 6 - Switch Room - Station Building - Golders Green Stn | Other Electrical Boxes | Asbestos | Surveyed – Not Detected | | | | 1 x Transformer Box | | 1 | | N | N |
| 20354 | ACTIVE | N | N041-00-1/661/WAL-006 80917031 | Wall: Internal - 6 - Switch Room - Station Building - Golders Green Stn Wall: Internal | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Switch Boxes - 5 x 100 amp, 3 x 60 amp No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 8 | | N | N |
| 64655 | ACTIVE | N | N041-00-1/662 | Switch Room - Station Building - Golders Green Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Electrical equipment presumed to contain asbestos insulating materials within | | | | | |
| 8552 | ACTIVE | N | N041-00-1/731 | CER - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17789 | ACTIVE | N | N041-00-1/731/FLR-01 | Floor - 1 - CER - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Beneath Computer Tiles | | | | | YES |
| 8553 | ACTIVE | N | N041-00-1/746 | SCR - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17791 | ACTIVE | N | N041-00-1/746 | SCR - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8554 | ACTIVE | N | N041-00-1/776 | Equipment Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17792 | ACTIVE | N | N041-00-1/776 | Equipment Room - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8555 | ACTIVE | N | N041-00-1/801 | Mess Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N041-00 - Station Building - Golders Green Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 17794 | ACTIVE | N | N041-00-1/801 | Mess Room - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 17793 | ACTIVE | N | N041-00-1/801 | Mess Room - Station Building - Golders Green Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | | | | | | |
| 18309 | ACTIVE | N | N041-00-1/801/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Golders Green Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 17795 | ACTIVE | N | N041-00-1/801/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete & Breeze Block above false ceiling | | | | YES | |
| 8556 | ACTIVE | N | N041-00-1/802 | DSM Office - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17797 | ACTIVE | N | N041-00-1/802/CLG-01 | Ceiling: Suspended - 1 - DSM Office - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 17796 | ACTIVE | N | N041-00-1/802/CLG-01 | Ceiling: Suspended - 1 - DSM Office - Station Building - Golders Green Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard Tiles | | | | | |
| 8557 | ACTIVE | N | N041-00-1/803 | DSM Office - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18310 | ACTIVE | N | N041-00-1/803/CLG-01 | Ceiling: Suspended - 1 - DSM Office - Station Building - Golders Green Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard Tiles | | | | | |
| 17798 | ACTIVE | N | N041-00-1/803/CLG-01 | Ceiling: Suspended - 1 - DSM Office - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 8558 | ACTIVE | N | N041-00-1/804 | DSM Office - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18152 | ACTIVE | N | N041-00-1/804/CLG-01 | Ceiling: Suspended - 1 - DSM Office - Station Building - Golders Green Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard Tiles | | | | | |
| 19078 | ACTIVE | N | N041-00-1/804/CLG-01 | Ceiling: Suspended - 1 - DSM Office - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, metal ducting above false ceiling | | | | YES | |
| 8559 | ACTIVE | N | N041-00-1/805 | DSM Office - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17799 | ACTIVE | N | N041-00-1/805 | DSM Office - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N041-00 - Station Building - Golders Green Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 8560 | ACTIVE | N | N041-00-1/971 | Passage - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Strongly Presumed | | | | | | | | | |
| 25872 | ACTIVE | N | N041-00-1/971 | Passage - Station Building - Golders Green Stn | Other Electrical Boxes | Asbestos | No Access: Presumed | | | | Materials within E5 Switchcupboard by 1/452 | | | | | |
| 17800 | ACTIVE | N | N041-00-1/971 | Passage - Station Building - Golders Green Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1x Distribution board within E6 Cupboard by 1/451 (E Switch key unlocks padlock) No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 25870 | ACTIVE | N | N041-00-1/971 | Passage - Station Building - Golders Green Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 1x Switchbox within E6 switchcupboard by 1/451 (E switch key unlocks padlock) No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 25871 | ACTIVE | N | N041-00-1/971 | Passage - Station Building - Golders Green Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Trunking within E6 switchcupboard by 1/451 (materials within) E switchroom key unlocks padlock) No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 8561 | ACTIVE | N | N041-00-A/041 | Canteen - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18311 | ACTIVE | N | N041-00-A/041/CLG-01 | Ceiling: Suspended - 1 - Canteen - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete/ Supalux Panel above false ceiling | | | | YES | |
| 17801 | ACTIVE | N | N041-00-A/041/CLG-01 | Ceiling: Suspended - 1 - Canteen - Station Building - Golders Green Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard Tiles | | | | | |
| 8562 | ACTIVE | N | N041-00-A/042 | Canteen - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17802 | ACTIVE | N | N041-00-A/042/CLG-01 | Ceiling: Suspended - 1 - Canteen - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete Supalux Blocks above Plaster Tiles | | | | YES | |
| 8563 | ACTIVE | N | N041-00-A/047 | Kitchen - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17803 | ACTIVE | N | N041-00-A/047/CLG-01 | Ceiling: Suspended - 1 - Kitchen - Station Building - Golders Green Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard / Tiles | | | | | |



Hazardous Material Asset Register - Summary



N041-00 - Station Building - Golders Green Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|-----------------|--|----------|-----------|-----------------|--------------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 17804 | ACTIVE | N | N041-00-A/047/CLG-01 | Ceiling: Suspended - 1 - Kitchen - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concreteabove false ceiling | | | | YES | |
| 8564 | ACTIVE | N | N041-00-A/050 | Larder - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17806 | ACTIVE | N | N041-00-A/050 | Larder - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8565 | ACTIVE | N | N041-00-A/051 | Larder - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17805 | ACTIVE | N | N041-00-A/051 | Larder - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8566 | ACTIVE | N | N041-00-A/081 | Lobby - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18312 | ACTIVE | N | N041-00-A/081 | Lobby - Station Building - Golders Green Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Room | | | | | |
| 8567 | ACTIVE | N | N041-00-A/082 | Lobby - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17807 | ACTIVE | N | N041-00-A/082 | Lobby - Station Building - Golders Green Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Room | | | | | |
| 8568 | ACTIVE | N | N041-00-A/084 | Lobby - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17808 | ACTIVE | N | N041-00-A/084 | Lobby - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8569 | ACTIVE | N | N041-00-A/261 | Platform 1 - Northbound Local - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17809 | ACTIVE | N | N041-00-A/261 | Platform 1 - Northbound Local - Station Building - Golders Green Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Boarding on Wall - Non Asbestos | | | | | |
| 18374 | ACTIVE | N | N041-00-A/261 | Platform 1 - Northbound Local - Station Building - Golders Green Stn | Lagging | Asbestos | Surveyed – Not Detected | | | | Bronzo Tape on Pipes | | | | | |
| 68041 | ACTIVE | N | N041-00-A/261 | Platform 1 - Northbound Local - Station Building - Golders Green Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Cream gloss - Canopy columns - 7.78% | | | R739279 | | |
| 68025 | ACTIVE | N | N041-00-A/261 | Platform 1 - Northbound Local - Station Building - Golders Green Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Green gloss - Canopy columns - 16.7% | | | R739279 | | |



Hazardous Material Asset Register - Summary



N041-00 - Station Building - Golders Green Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|--------------------------------------|--|-----------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 44007 | ACTIVE | N | N041-00-A/261 | Platform 1 - Northbound Local - Station Building - Golders Green Stn | | Lead Paint/Lead | Presumed | | | | Upon re - inspection possible lead paint on all upstands and canopy support was reported | | | | | |
| 68047 | ACTIVE | N | N041-00-A/261 | Platform 1 - Northbound Local - Station Building - Golders Green Stn | Lead/Leading | Lead Paint/Lead | Known | | | | White gloss - Canopy - 19.4% | | | R739279 | | |
| 17810 | ACTIVE | N | N041-00-A/261/ FLR-01 80917714 | Floor - 1 - Platform 1 - Station Building - Golders Green Stn Floor | Debris: Cement | Asbestos | Known | | | | Extensive cementitious debris below Platform; Extensive surface pick undertaken; however any further excavation will require further investigation No access beneath platforms during traffic in 2023 re-inspection. | | | | | YES |
| 8570 | ACTIVE | N | N041-00-A/262 | Platform 2 - Northbound Local - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44008 | ACTIVE | N | N041-00-A/262 | Platform 2 - Northbound Local - Station Building - Golders Green Stn | | Lead Caulking | Presumed | | | | Upon re - inspection possible lead paint on all upstands and canopy support was reported | | | | | |
| 68042 | ACTIVE | N | N041-00-A/262 | Platform 2 - Northbound Local - Station Building - Golders Green Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Cream gloss - Canopy columns - 7.78% | | | R739279 | | |
| 68036 | ACTIVE | N | N041-00-A/262 | Platform 2 - Northbound Local - Station Building - Golders Green Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Green gloss - Canopy columns - 16.7% | | | R739279 | | |
| 68099 | ACTIVE | N | N041-00-A/262 | Platform 2 - Northbound Local - Station Building - Golders Green Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Black matt - Column bases - 0.05% | | | R739279 | | |
| 68049 | ACTIVE | N | N041-00-A/262 | Platform 2 - Northbound Local - Station Building - Golders Green Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Cream gloss - Canopy - 19.4% | | | R739279 | | |
| 17811 | ACTIVE | N | N041-00-A/262/ FLR-01 80917743 | Floor - 1 - Platform 2 - Station Building - Golders Green Stn Floor | Debris: Cement | Asbestos | Strongly Presumed | | | | Asbestos debris maybe present within clay bed/soil/rubble beneath platform No access beneath platforms during traffic in 2023 re-inspection. | | | | N | YES |
| 8571 | ACTIVE | N | N041-00-A/263 | Platform 3 - Northbound Main - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44009 | ACTIVE | N | N041-00-A/263 | Platform 3 - Northbound Main - Station Building - Golders Green Stn | | Lead Caulking | Presumed | | | | Upon re - inspection possible lead paint on all upstands and canopy support was reported | | | | | |
| 68052 | ACTIVE | N | N041-00-A/263 | Platform 3 - Northbound Main - Station Building - Golders Green Stn | Lead/Leading | Lead Paint/Lead | Known | | | | White Gloss Canopy 19.4% | | | R739279 | | |
| 68100 | ACTIVE | N | N041-00-A/263 | Platform 3 - Northbound Main - Station Building - Golders Green Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Black matt - Column bases - 0.05% | | | R739279 | | |



Hazardous Material Asset Register - Summary



N041-00 - Station Building - Golders Green Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|--------------------------------------|--|-----------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 68043 | ACTIVE | N | N041-00-A/263 | Platform 3 - Northbound Main - Station Building - Golders Green Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Cream gloss - Canopy columns - 7.78% | | | R739279 | | |
| 68038 | ACTIVE | N | N041-00-A/263 | Platform 3 - Northbound Main - Station Building - Golders Green Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Green gloss - Canopy columns - 16.7% | | | R739279 | | |
| 18375 | ACTIVE | N | N041-00-A/263/ FLR-01 80917758 | Floor - 1 - Platform 3 - Station Building - Golders Green Stn Floor | Debris: Cement | Asbestos | Strongly Presumed | | | | Asbestos debris maybe present within clay bed/soil/rubble beneath platform No access to area beneath platform during traffic in 2023 reinspection. | | | | | YES |
| 8572 | ACTIVE | N | N041-00-A/264 | Platform 4 - Northbound Main - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 68044 | ACTIVE | N | N041-00-A/264 | Platform 4 - Northbound Main - Station Building - Golders Green Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Cream gloss - Canopy columns - 7.78% | | | R739279 | | |
| 68039 | ACTIVE | N | N041-00-A/264 | Platform 4 - Northbound Main - Station Building - Golders Green Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Green gloss - Canopy supports - 16.7% | | | R739279 | | |
| 68053 | ACTIVE | N | N041-00-A/264 | Platform 4 - Northbound Main - Station Building - Golders Green Stn | Lead/Leading | Lead Paint/Lead | Known | | | | White gloss to canopy columns 19.4% | | | R739279 | | |
| 17812 | ACTIVE | N | N041-00-A/264/ CLG-01 | Ceiling: Solid - 1 - Platform 4 - Station Building - Golders Green Stn | Glazing Rope | Asbestos | Known | | | | Glazing Rope seals from Glazing on Canopy - Chrysotile - Partially Removed | | | | N | N |
| 20358 | ACTIVE | N | N041-00-A/264/ CLG-01 | Ceiling: Solid - 1 - Platform 4 - Station Building - Golders Green Stn | Lead/Leading | Lead Paint/Lead | Presumed | | | | Upon re - inspection possible lead paint on all upstands and canopy support was reported | | | | N | N |
| 17813 | ACTIVE | N | N041-00-A/264/ FLR-01 80917776 | Floor - 1 - Platform 4 - Station Building - Golders Green Stn Floor | Debris: Cement | Asbestos | Strongly Presumed | | | | Asbestos debris maybe present within clay bed/soil/rubble beneath platform No access to area beneath platform during traffic in 2023 reinspection. | | | | N | YES |
| 8573 | ACTIVE | N | N041-00-A/265 | Platform 5 - Southbound Local - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 68040 | ACTIVE | N | N041-00-A/265 | Platform 5 - Southbound Local - Station Building - Golders Green Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Green gloss - Canopy supports - 16.7% | | | R739279 | | |
| 44921 | ACTIVE | N | N041-00-A/265 | Platform 5 - Southbound Local - Station Building - Golders Green Stn | Lead/Leading | Lead Paint/Lead | Presumed | | | | Possible Green Lead Paint on all Upstands & Canopy support | | | | N | N |
| 68054 | ACTIVE | N | N041-00-A/265 | Platform 5 - Southbound Local - Station Building - Golders Green Stn | Lead/Leading | Lead Paint/Lead | Known | | | | White gloss to canopy columns 19.4% | | | R739279 | | |



Hazardous Material Asset Register - Summary



N041-00 - Station Building - Golders Green Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 68046 | ACTIVE | N | N041-00-A/265 | Platform 5 - Southbound Local - Station Building - Golders Green Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Cream gloss - Canopy columns - 7.78% | | | R739279 | | |
| 17814 | ACTIVE | N | N041-00-A/265/CLG-01 | Ceiling: Solid - 1 - Platform 5 - Station Building - Golders Green Stn | Glazing Rope | Asbestos | Known | | | | Glazing Rope seals from Glazing on Canopy - Chrysotile - Partially Removed | | | | N | N |
| 17815 | ACTIVE | N | N041-00-A/265/FLR-01 | Floor - 1 - Platform 5 - Station Building - Golders Green Stn | Debris: Cement | Asbestos | Strongly Presumed | | | | Asbestos debris maybe present within clay bed/soil/rubble beneath platform No access to area beneath platform during traffic in 2020 reinspection | | | | N | YES |
| 8574 | ACTIVE | N | N041-00-A/291 | DMT Office - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19079 | ACTIVE | N | N041-00-A/291/CLG-01 | Ceiling: Suspended - 1 - DMT Office - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal Blocks above false ceiling | | | | YES | |
| 8575 | ACTIVE | N | N041-00-A/292 | Station Supervisor Office - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17816 | ACTIVE | N | N041-00-A/292/CLG-01 | Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Golders Green Stn | Void | Asbestos | No Access: Presumed | | | | Above false ceiling | | | | Y | N |
| 8576 | ACTIVE | N | N041-00-A/311 | Toilet: Unisex - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18376 | ACTIVE | N | N041-00-A/311/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Golders Green Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 17818 | ACTIVE | N | N041-00-A/311/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Breeze Blocks & Plaster above false ceiling | | | | YES | |
| 17817 | ACTIVE | N | N041-00-A/311/CLG-02 | Ceiling: Solid - 2 - Toilet - Station Building - Golders Green Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18153 | ACTIVE | N | N041-00-A/311/CLG-02 | Ceiling: Solid - 2 - Toilet - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Breeze Blocks & Plaster above false ceiling | | | | YES | |
| 8577 | ACTIVE | N | N041-00-A/312 | Office - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17820 | ACTIVE | N | N041-00-A/312/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Fibreglass Lagging; Timber, Plaster, Glass Paint; Panels above false ceiling | | | | YES | |



Hazardous Material Asset Register - Summary



N041-00 - Station Building - Golders Green Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 17819 | ACTIVE | N | N041-00-A/312/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Golders Green Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 8578 | ACTIVE | N | N041-00-A/313 | Office - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18570 | ACTIVE | N | N041-00-A/313 | Office - Station Building - Golders Green Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Supalux panel behind heater | | | | | |
| 8579 | ACTIVE | N | N041-00-A/316 | Locker Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18377 | ACTIVE | N | N041-00-A/316 | Locker Room - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8580 | ACTIVE | N | N041-00-A/317 | Locker Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17821 | ACTIVE | N | N041-00-A/317 | Locker Room - Station Building - Golders Green Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 8581 | ACTIVE | N | N041-00-A/318 | Locker Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17822 | ACTIVE | N | N041-00-A/318 | Locker Room - Station Building - Golders Green Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 8582 | ACTIVE | N | N041-00-A/331 | Tea Point - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18378 | ACTIVE | N | N041-00-A/331 | Tea Point - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 17823 | ACTIVE | N | N041-00-A/331 | Tea Point - Station Building - Golders Green Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater | | | | | |
| 8583 | ACTIVE | N | N041-00-A/332 | Mess Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17824 | ACTIVE | N | N041-00-A/332/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Plaster Tiles | | | | YES | |
| 8584 | ACTIVE | N | N041-00-A/333 | Mess Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17825 | ACTIVE | N | N041-00-A/333/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete Supalux Blocks above false ceiling | | | | YES | |



Hazardous Material Asset Register - Summary



N041-00 - Station Building - Golders Green Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 8585 | ACTIVE | N | N041-00-A/334 | Mess Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18379 | ACTIVE | N | N041-00-A/334 | Mess Room - Station Building - Golders Green Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed | | | | | |
| 8586 | ACTIVE | N | N041-00-A/361 | Tea Point - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17826 | ACTIVE | N | N041-00-A/361 | Tea Point - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 18154 | ACTIVE | N | N041-00-A/361/CLG-01 | Ceiling: Suspended - 1 - Tea Point - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal Blocks above false ceiling | | | | YES | |
| 8587 | ACTIVE | N | N041-00-A/371 | Store - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17827 | ACTIVE | N | N041-00-A/371 | Store - Station Building - Golders Green Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 8588 | ACTIVE | N | N041-00-A/411 | Store - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18380 | ACTIVE | N | N041-00-A/411 | Store - Station Building - Golders Green Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Insulation board within 2x Heaters - Non Asbestos | | | | | |
| 17830 | ACTIVE | N | N041-00-A/411 | Store - Station Building - Golders Green Stn | Other Electrical Boxes | Asbestos | Surveyed – Not Detected | | | | Rope in Electrical Box E8 | | | | | |
| 18381 | ACTIVE | N | N041-00-A/411 | Store - Station Building - Golders Green Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Insulation board within 2x Heaters - Non Asbestos | | | | | |
| 17831 | ACTIVE | N | N041-00-A/411 | Store - Station Building - Golders Green Stn | Other Electrical Boxes | Asbestos | Surveyed – Not Detected | | | | Grey Metal Box | | | | | |
| 17832 | ACTIVE | N | N041-00-A/411 | Store - Station Building - Golders Green Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Boarding to Flame Bin Store | | | | | |
| 17829 | ACTIVE | N | N041-00-A/411/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Wooden Strut Beams, Metal Flue above false ceiling | | | | YES | |
| 17828 | ACTIVE | N | N041-00-A/411/FLR-01 | Floor - 1 - Store - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Wooden Base beneath vinyl tiles | | | | | YES |
| 8589 | ACTIVE | N | N041-00-A/412 | SOM Office - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17833 | ACTIVE | N | N041-00-A/412/CLG-01 | Ceiling: Suspended - 1 - SOM Office - Station Building - Golders Green Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |



Hazardous Material Asset Register - Summary



N041-00 - Station Building - Golders Green Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17834 | ACTIVE | N | N041-00-A/412/CLG-01 | Ceiling: Suspended - 1 - SOM Office - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plasterboard; Fibreglass Lagging above false ceiling | | | | YES | |
| 8590 | ACTIVE | N | N041-00-A/414 | Store - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17835 | ACTIVE | N | N041-00-A/414 | Store - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8591 | ACTIVE | N | N041-00-A/416 | Toilet: Unisex - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18382 | ACTIVE | N | N041-00-A/416 | Toilet: Unisex - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8592 | ACTIVE | N | N041-00-A/417 | Toilet: Unisex - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17836 | ACTIVE | N | N041-00-A/417/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal Blocks above false ceiling | | | | YES | |
| 8593 | ACTIVE | N | N041-00-A/418 | Toilet: Female - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17837 | ACTIVE | N | N041-00-A/418 | Toilet: Female - Station Building - Golders Green Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 8594 | ACTIVE | N | N041-00-A/419 | Toilet: Male - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18383 | ACTIVE | N | N041-00-A/419 | Toilet: Male - Station Building - Golders Green Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 8595 | ACTIVE | N | N041-00-A/420 | Toilet: Female - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18155 | ACTIVE | N | N041-00-A/420 | Toilet: Female - Station Building - Golders Green Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 8596 | ACTIVE | N | N041-00-A/437 | Waiting Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17838 | ACTIVE | N | N041-00-A/437 | Waiting Room - Station Building - Golders Green Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 8597 | ACTIVE | N | N041-00-A/531 | Booking On Point - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N041-00 - Station Building - Golders Green Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|-------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 17839 | ACTIVE | N | N041-00-A/531/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal above false ceiling | | | | YES | |
| 8598 | ACTIVE | N | N041-00-A/576 | Stairs: Linear - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19080 | ACTIVE | N | N041-00-A/576 | Stairs: Linear - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8599 | ACTIVE | N | N041-00-A/577 | Stairs: Linear - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8600 | ACTIVE | N | N041-00-A/578 | Stairs: Linear - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17840 | ACTIVE | N | N041-00-A/578 | Stairs: Linear - Station Building - Golders Green Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 8601 | ACTIVE | N | N041-00-A/579 | Stairs: Linear - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18384 | ACTIVE | N | N041-00-A/579 | Stairs: Linear - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8602 | ACTIVE | N | N041-00-A/601 | Stairs: Linear - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8603 | ACTIVE | N | N041-00-A/602 | Stairs: Linear - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17841 | ACTIVE | N | N041-00-A/602 | Stairs: Linear - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8604 | ACTIVE | N | N041-00-A/603 | Stairs: Linear - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17842 | ACTIVE | N | N041-00-A/603 | Stairs: Linear - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8605 | ACTIVE | N | N041-00-A/604 | Stairs: Linear - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17843 | ACTIVE | N | N041-00-A/604 | Stairs: Linear - Station Building - Golders Green Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux - Above Stairs panels | | | | | |
| 8606 | ACTIVE | N | N041-00-A/605 | Stairs: Linear - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N041-00 - Station Building - Golders Green Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18385 | ACTIVE | N | N041-00-A/605 | Stairs: Linear - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8607 | ACTIVE | N | N041-00-A/661 | Switch Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17844 | ACTIVE | N | N041-00-A/661/ WAL-001 80917793 | Wall: Internal - 1 - Switch Room - Station Building - Golders Green Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 18156 | ACTIVE | N | N041-00-A/661/ WAL-002 80917794 | Wall: Internal - 2 - Switch Room - Station Building - Golders Green Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | Electrical Box No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 17845 | ACTIVE | N | N041-00-A/661/ WAL-002 80917794 | Wall: Internal - 2 - Switch Room - Station Building - Golders Green Stn Wall: Internal | Cable Duct: Other | Asbestos | Presumed | | | | Cable Ducts Cable ducts covered by layer of cement on top. Ducts not visible beneath therefore material not scored in 2023 re-inspection. | | | | N | N |
| 8608 | ACTIVE | N | N041-00-A/662 | Switch Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18386 | ACTIVE | N | N041-00-A/662/ FLR-01 80917808 | Floor - 1 - Switch Room - Station Building - Golders Green Stn Floor | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box - between walls 1 & 2 No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 17847 | ACTIVE | N | N041-00-A/662/ WAL-001 80917803 | Wall: Internal - 1 - Switch Room - Station Building - Golders Green Stn Wall: Internal | Cable Duct: Other | Asbestos | Presumed | | | | Cable Ducts Cable ducts are covered by a cement layer on top. Ducts not visible beneath therefore no material score during 2023 re-inspection | | | | N | N |
| 17846 | ACTIVE | N | N041-00-A/662/ WAL-002 80917804 | Wall: Internal - 2 - Switch Room - Station Building - Golders Green Stn Wall: Internal | Isolator Switches | Asbestos | Presumed | | | | Insulation within 1 x Blue Combination Switch 1 x 100 amps No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 8609 | ACTIVE | N | N041-00-A/663 | Switch Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17848 | ACTIVE | N | N041-00-A/663 | Switch Room - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8610 | ACTIVE | N | N041-00-A/664 | Switch Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17849 | ACTIVE | N | N041-00-A/664 | Switch Room - Station Building - Golders Green Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 8611 | ACTIVE | N | N041-00-A/665 | Switch Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N041-00 - Station Building - Golders Green Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18571 | ACTIVE | N | N041-00-A/665 | Switch Room - Station Building - Golders Green Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 8612 | ACTIVE | N | N041-00-A/801 | Office - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18157 | ACTIVE | N | N041-00-A/801 | Office - Station Building - Golders Green Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 8613 | ACTIVE | N | N041-00-A/951 | Disused Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18387 | ACTIVE | N | N041-00-A/951/CLG-01 | Ceiling: Solid - 1 - Disused Room - Station Building - Golders Green Stn | Void | Asbestos | Surveyed – Not Detected | | | | Wooden Strut Beams, Wooden Slatted above Chipboard Ceiling | | | | YES | |
| 8614 | ACTIVE | N | N041-00-A/952 | Disused Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19415 | ACTIVE | N | N041-00-A/952 | Disused Room - Station Building - Golders Green Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed | | | | | |
| 8615 | ACTIVE | N | N041-00-A/953 | Disused Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17850 | ACTIVE | N | N041-00-A/953 | Disused Room - Station Building - Golders Green Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed | | | | | |
| 8616 | ACTIVE | N | N041-00-A/954 | Disused Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20030 | ACTIVE | N | N041-00-A/954 | Disused Room - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8617 | ACTIVE | N | N041-00-A/955 | Locker Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20213 | ACTIVE | N | N041-00-A/955 | Locker Room - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8618 | ACTIVE | N | N041-00-A/956 | Disused Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19291 | ACTIVE | N | N041-00-A/956 | Disused Room - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8619 | ACTIVE | N | N041-00-A/957 | Disused Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20214 | ACTIVE | N | N041-00-A/957 | Disused Room - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N041-00 - Station Building - Golders Green Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|---------------------|-------------|------------|-------------|---------------------|-------------------|
| 8620 | ACTIVE | N | N041-00-A/958 | Disused Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20215 | ACTIVE | N | N041-00-A/958 | Disused Room - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8621 | ACTIVE | N | N041-00-A/959 | Disused Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19292 | ACTIVE | N | N041-00-A/959 | Disused Room - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8622 | ACTIVE | N | N041-00-A/960 | Disused Room - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20216 | ACTIVE | N | N041-00-A/960 | Disused Room - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8623 | ACTIVE | N | N041-00-B/576 | Stairs: Linear - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20217 | ACTIVE | N | N041-00-B/576 | Stairs: Linear - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8624 | ACTIVE | N | N041-00-B/577 | Stairs: Linear - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20218 | ACTIVE | N | N041-00-B/577 | Stairs: Linear - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8625 | ACTIVE | N | N041-00-B/578 | Stairs: Linear - Station Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19293 | ACTIVE | N | N041-00-B/578 | Stairs: Linear - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 20219 | ACTIVE | N | N041-00-B/636 | Overbridge - Station Building - Golders Green Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |

N043-00 - Station Building - Hampstead Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 8652 | ACTIVE | N | N043-00-1/001 | Booking Hall - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17558 | ACTIVE | N | N043-00-1/001/CLG-01 | Ceiling: Solid - 1 - Booking Hall - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Small void above supalux tiles is concrete with metal framework and PVC cables | | | | YES | |



Hazardous Material Asset Register - Summary



N043-00 - Station Building - Hampstead Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 8653 | ACTIVE | N | N043-00-1/011 | Ticket Office - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18072 | ACTIVE | N | N043-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 17560 | ACTIVE | N | N043-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 17559 | ACTIVE | N | N043-00-1/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Hampstead Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | 12 | | | N | N |
| 8654 | ACTIVE | N | N043-00-1/021 | POM - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17561 | ACTIVE | N | N043-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above screwed tiles | | | | YES | |
| 17980 | ACTIVE | N | N043-00-1/021/FLR-01 | Floor - 1 - POM - Station Building - Hampstead Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |
| 8655 | ACTIVE | N | N043-00-1/031 | Mess Room - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17563 | ACTIVE | N | N043-00-1/031 | Mess Room - Station Building - Hampstead Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 17562 | ACTIVE | N | N043-00-1/031 | Mess Room - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | No Access: Presumed | | | | Supalux Boxing on Walls | | | | | |
| 17564 | ACTIVE | N | N043-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 17981 | ACTIVE | N | N043-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above false ceiling | | | | YES | |
| 8656 | ACTIVE | N | N043-00-1/036 | Lobby - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17565 | ACTIVE | N | N043-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above false ceiling | | | | YES | |
| 8657 | ACTIVE | N | N043-00-1/037 | Toilet: Unisex - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19064 | ACTIVE | N | N043-00-1/037/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |



Hazardous Material Asset Register - Summary



N043-00 - Station Building - Hampstead Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17566 | ACTIVE | N | N043-00-1/037/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal Traywork, Frames, PVC Cables, Rock wall Lagging, Solid Concrete Block work above false ceiling | | | | YES | |
| 8658 | ACTIVE | N | N043-00-1/071 | Circulation Area - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17567 | ACTIVE | N | N043-00-1/071/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Small void above supalux tiles is concrete with metal framework and PVC cables | | | | YES | |
| 8659 | ACTIVE | N | N043-00-1/072 | Circulation Area - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17568 | ACTIVE | N | N043-00-1/072/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Small void above supalux tiles is concrete with metal framework and PVC cables | | | | YES | |
| 17982 | ACTIVE | N | N043-00-1/072/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing into Ceiling | | | | | |
| 8660 | ACTIVE | N | N043-00-1/236 | Lobby - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17569 | ACTIVE | N | N043-00-1/236 | Lobby - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | White boarding surrounding door way into machine room Supalux | | | | | |
| 8661 | ACTIVE | N | N043-00-1/237 | Lobby - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17571 | ACTIVE | N | N043-00-1/237 | Lobby - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | No Access: Presumed | | | | Supalux identified to ceiling only | 2 | 0 | | N | N |
| 17572 | ACTIVE | N | N043-00-1/237/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above screwed tiles | | | | YES | |
| 17570 | ACTIVE | N | N043-00-1/237/FLR-01 | Floor - 1 - Lobby - Station Building - Hampstead Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |
| 8662 | ACTIVE | N | N043-00-1/238 | Passage - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17983 | ACTIVE | N | N043-00-1/238 | Passage - Station Building - Hampstead Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Partition Wall - Durasteel - Non Asbestos | | | | | |
| 17573 | ACTIVE | N | N043-00-1/239/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal Traywork, Frames, PVC Cables above open area | | | | YES | |
| 8664 | ACTIVE | N | N043-00-1/412 | Store - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N043-00 - Station Building - Hampstead Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|--------------------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17574 | ACTIVE | N | N043-00-1/412 | Store - Station Building - Hampstead Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Room | | | | | |
| 8665 | ACTIVE | N | N043-00-1/451 | Tenancy - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17575 | ACTIVE | N | N043-00-1/451/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - Hampstead Stn | Void | Asbestos | No Access: Presumed | | | | No access above tiled ceiling | | | | Y | |
| 8666 | ACTIVE | N | N043-00-1/577 | Stairs: Linear - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17576 | ACTIVE | N | N043-00-1/577 | Stairs: Linear - Station Building - Hampstead Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Tenancy | | | | | |
| 8667 | ACTIVE | N | N043-00-1/578 | Stairs: Linear - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17984 | ACTIVE | N | N043-00-1/578 | Stairs: Linear - Station Building - Hampstead Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Tenancy | | | | | |
| 8668 | ACTIVE | N | N043-00-1/601 | Stairs: Linear - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17577 | ACTIVE | N | N043-00-1/601 | Stairs: Linear - Station Building - Hampstead Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8669 | ACTIVE | N | N043-00-1/631 | Stairs: Spiral - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17578 | ACTIVE | N | N043-00-1/631/FLR-01 | Floor - 1 - Spiral Stairs - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux panel bottom of stairs | | | | | |
| 8670 | ACTIVE | N | N043-00-1/661 | Switch Room - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17579 | ACTIVE | N | N043-00-1/661/WAL-001 80902826 | Wall: Internal - 1 - Switch Room - Station Building - Hampstead Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 4 x Switch Boxes 2 x 60 amp, 2 x 200 amp No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 4 | | N | N |
| 17985 | ACTIVE | N | N043-00-1/661/WAL-002 80902827 | Wall: Internal - 2 - Switch Room - Station Building - Hampstead Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | 1 x Transformer Box No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 20360 | ACTIVE | N | N043-00-1/661/WAL-002 80902827 | Wall: Internal - 2 - Switch Room - Station Building - Hampstead Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 2 x 60 amp Switch Boxes No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 2 | | N | N |



Hazardous Material Asset Register - Summary



N043-00 - Station Building - Hampstead Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|--------------------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 20362 | ACTIVE | N | N043-00-1/661/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux at lower level | | | | | |
| 20361 | ACTIVE | N | N043-00-1/661/WAL-003 80902828 | Wall: Internal - 3 - Switch Room - Station Building - Hampstead Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 7 x Switch Boxes - 1 x 30amp, 1 x 60amp, 3 x 100amp, 2 x 200amp | | 7 | | N | N |
| 8671 | ACTIVE | N | N043-00-1/662 | Switch Room - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17580 | ACTIVE | N | N043-00-1/662 | Switch Room - Station Building - Hampstead Stn | | Anthrax | Surveyed – Not Detected | | | | No Anthrax Detected | | | | | |
| 19065 | ACTIVE | N | N043-00-1/662 | Switch Room - Station Building - Hampstead Stn | Cable Duct: Other | Asbestos | Presumed | | | | Cable Ducts Cable ducts are not visible beneath layer of cement on floor surface - therefore material not scored in 2023 re-inspection. | | | | N | N |
| 18073 | ACTIVE | N | N043-00-1/662/CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Boxing - Supalux. | | | | | |
| 18469 | ACTIVE | N | N043-00-1/662/WAL-001 80902833 | Wall: Internal - 1 - Switch Room - Station Building - Hampstead Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | Insulation within 1x Switch Box - 1 x 30 amps No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 17581 | ACTIVE | N | N043-00-1/662/WAL-001 80902833 | Wall: Internal - 1 - Switch Room - Station Building - Hampstead Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | 3 x Transformer Boxes No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 3 | | N | N |
| 25719 | ACTIVE | N | N043-00-1/662/WAL-002 80902834 | Wall: Internal - 2 - Switch Room - Station Building - Hampstead Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | 1x Transformer box No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 8672 | ACTIVE | N | N043-00-1/663 | Switch Cupboard - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17582 | ACTIVE | N | N043-00-1/663/WAL-002 80902845 | Wall: Internal - 2 - Switch Cupboard - Station Building - Hampstead Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | Insulation (arc shutes & flash guards) within 1 x 200 amp Switch Box. Electrical incomer may contain asbestos. No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 8673 | ACTIVE | N | N043-00-1/746 | SCR - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18048 | ACTIVE | N | N043-00-1/746/CLG-01 | Ceiling: Suspended - 1 - SCR - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | 600x600 lay in Supalux Tiles | | | | | |



Hazardous Material Asset Register - Summary



N043-00 - Station Building - Hampstead Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17583 | ACTIVE | N | N043-00-1/746/CLG-01 | Ceiling: Suspended - 1 - SCR - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above supalux tiles | | | | YES | |
| 8674 | ACTIVE | N | N043-00-1/751 | Station Supervisor Office - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 17584 | INACTIVE | N | N043-00-1/751 | Station Supervisor Office - Station Building - Hampstead Stn | | Asbestos | Surveyed – Not Detected | | | | Surveyed - No asbestos Detected | | | | | |
| 69348 | ACTIVE | N | N043-00-1/751/CLG-02 | Ceiling: Suspended - 2 - Office - Station Building - Hampstead Stn | Other Boarding | Asbestos | No Access: Presumed | | | | No access gained into boarding forming boxing to ceiling above false ceiling - Too high to sample (Presumed) | | | R679626 | | |
| 17585 | ACTIVE | N | N043-00-1/791 | Vent Shaft - Station Building - Hampstead Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | No caulking present in tunnel rings; Only sand and loose concrete material – supalux panels on CER in close proximity to vent shaft. New equipment inside. | | | | | |
| 8675 | ACTIVE | N | N043-00-2/236 | Passage - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17586 | ACTIVE | N | N043-00-2/236 | Passage - Station Building - Hampstead Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8676 | ACTIVE | N | N043-00-2/238 | Lobby - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17587 | ACTIVE | N | N043-00-2/238/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18049 | ACTIVE | N | N043-00-2/238/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid & concrete Block work above Supalux Tiles | | | | YES | |
| 8677 | ACTIVE | N | N043-00-2/240 | Lobby - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17588 | ACTIVE | N | N043-00-2/240 | Lobby - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | No Access: Presumed | | | | Supalux Boxing to ceiling. | 6 | | | | |
| 8678 | ACTIVE | N | N043-00-2/281 | Office - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17591 | ACTIVE | N | N043-00-2/281 | Office - Station Building - Hampstead Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - white foam backing | | | | | |
| 17589 | ACTIVE | N | N043-00-2/281 | Office - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | No Access: Presumed | | | | Supalux Boxing vertical to wall 1. | 2 | | | | |
| 17592 | ACTIVE | N | N043-00-2/281 | Office - Station Building - Hampstead Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |



Hazardous Material Asset Register - Summary



N043-00 - Station Building - Hampstead Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17590 | ACTIVE | N | N043-00-2/281/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above supalux tiles | | | | YES | |
| 18074 | ACTIVE | N | N043-00-2/281/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 8679 | ACTIVE | N | N043-00-2/316 | Locker Room - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18050 | ACTIVE | N | N043-00-2/316/CLG-01 | Ceiling: Suspended - 1 - Locker - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 17593 | ACTIVE | N | N043-00-2/316/CLG-01 | Ceiling: Suspended - 1 - Locker - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid & concrete Block work above Supalux Tiles | | | | YES | |
| 8680 | ACTIVE | N | N043-00-2/331 | Locker Room - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18051 | ACTIVE | N | N043-00-2/331 | Locker Room - Station Building - Hampstead Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 19066 | ACTIVE | N | N043-00-2/331 | Locker Room - Station Building - Hampstead Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - foam backing | | | | | |
| 17596 | ACTIVE | N | N043-00-2/331 | Locker Room - Station Building - Hampstead Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Grey & black paint on window frames: EDX analysis indicates in excess of 1%. Now appears to have been painted over in cream. | | 2 | | N | N |
| 17595 | ACTIVE | N | N043-00-2/331/CLG-01 | Ceiling: Suspended - 1 - Locker Room - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid & concrete block work above supalux tiles | | | | YES | |
| 17594 | ACTIVE | N | N043-00-2/331/CLG-01 | Ceiling: Suspended - 1 - Locker Room - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 8681 | ACTIVE | N | N043-00-2/411 | Store - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18052 | ACTIVE | N | N043-00-2/411 | Store - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | No Access: Presumed | | | | Supalux Boxing to ceiling | 6 | | | | |
| 8682 | ACTIVE | N | N043-00-2/412 | Store - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17597 | ACTIVE | N | N043-00-2/412 | Store - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Shelving | | | | | |
| 18053 | ACTIVE | N | N043-00-2/412/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Hampstead Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux panel | 4 | | | YES | |



Hazardous Material Asset Register - Summary



N043-00 - Station Building - Hampstead Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17598 | ACTIVE | N | N043-00-2/412/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux panel | | | | | |
| 17599 | ACTIVE | N | N043-00-2/412/CLG-02 | Ceiling: Suspended - 2 - Store - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux panel | | | | | |
| 17600 | ACTIVE | N | N043-00-2/412/CLG-02 | Ceiling: Suspended - 2 - Store - Station Building - Hampstead Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux panel | 2 | | | YES | |
| 8683 | ACTIVE | N | N043-00-2/416 | Cleaners Store - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17601 | ACTIVE | N | N043-00-2/416/CLG-01 | Ceiling: Solid - 1 - Cleaners Store - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid & concrete block work above plasterboard | | | | YES | |
| 18075 | ACTIVE | N | N043-00-2/416/CLG-01 | Ceiling: Solid - 1 - Cleaners Store - Station Building - Hampstead Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 8684 | ACTIVE | N | N043-00-2/417 | Lobby - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17602 | ACTIVE | N | N043-00-2/417/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Hampstead Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 17603 | ACTIVE | N | N043-00-2/417/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Plasterboard | | | | YES | |
| 8685 | ACTIVE | N | N043-00-2/418 | Toilet - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8686 | ACTIVE | N | N043-00-2/419 | Toilet: Female - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17605 | ACTIVE | N | N043-00-2/419 | Toilet: Female - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | No Access: Presumed | | | | Supalux Boxing to wall 1. | 2 | | | | |
| 17604 | ACTIVE | N | N043-00-2/419/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid & concrete block work above plasterboard | | | | YES | |
| 18054 | ACTIVE | N | N043-00-2/419/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Hampstead Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 8687 | ACTIVE | N | N043-00-2/631 | Stairs: Spiral - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N043-00 - Station Building - Hampstead Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 17606 | ACTIVE | N | N043-00-2/631 | Stairs: Spiral - Station Building - Hampstead Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8688 | ACTIVE | N | N043-00-2/661 | Switch Cupboard - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19067 | ACTIVE | N | N043-00-2/661 | Switch Cupboard - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux panelling around doors | | | | | |
| 17607 | ACTIVE | N | N043-00-2/661/ WAL-002 80903038 | Wall: Internal - 2 - Switch Cupboard - Station Building - Hampstead Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | Insulation within one grey switch fuse 1 x 100 amps No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 8689 | ACTIVE | N | N043-00-2/732 | CER - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18055 | ACTIVE | N | N043-00-2/732/ FLR-01 | Floor - 1 - CER - Station Building - Hampstead Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | N |
| 18221 | ACTIVE | N | N043-00-2/732/ WAL-002 80903046 | Wall: Internal - 2 - CER - Station Building - Hampstead Stn Wall: Internal | Other Boarding | Asbestos | Presumed | | | | 2x Paxoline Boards | | 2 | | N | N |
| 17608 | ACTIVE | N | N043-00-2/732/ WAL-004 80903048 | Wall: Internal - 4 - CER - Station Building - Hampstead Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | Insulation within 2 x 60 amp Grey Switch Fuses No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 2 | | N | N |
| 44004 | INACTIVE | N | N043-00-2/732/ WAL-010 80903054 | Wall: Internal - 10 - CER - Station Building - Hampstead Stn Wall: Internal | Other Boarding | Asbestos | Presumed | | | | Paxoline boarding | | 1 | | N | N |
| 8690 | ACTIVE | N | N043-00-2/776 | Fan Room - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17609 | ACTIVE | N | N043-00-2/776 | Fan Room - Station Building - Hampstead Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8691 | ACTIVE | N | N043-00-2/901 | Passage - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17610 | ACTIVE | N | N043-00-2/901 | Passage - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | No Access: Presumed | | | | Supalux Boxing to ceiling. | 1 | | | | |
| 8692 | ACTIVE | N | N043-00-2/902 | Disused Room - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17611 | ACTIVE | N | N043-00-2/902/ CLG-01 | Ceiling: Solid - 1 - Basement Area - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Roof Area - Concrete Solid above open area | | | | YES | |



Hazardous Material Asset Register - Summary



N043-00 - Station Building - Hampstead Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 8693 | ACTIVE | N | N043-00-3/201 | Passage - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17612 | ACTIVE | N | N043-00-3/201 | Passage - Station Building - Hampstead Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 18056 | ACTIVE | N | N043-00-3/201 | Passage - Station Building - Hampstead Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Black Paint: EDX analysis indicates in excess of 1% - Good condition. Black paint has potentially been overpainted with cream/white paint. Potentially black paint below | | | | N | N |
| 8694 | ACTIVE | N | N043-00-3/202 | Passage - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17613 | ACTIVE | N | N043-00-3/202/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid & concrete blockwork, PVC cables, tiled walls above false ceiling | | | | YES | |
| 8695 | ACTIVE | N | N043-00-3/203 | Passage - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17614 | ACTIVE | N | N043-00-3/203/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid & concrete blockwork, PVC cables, tiled walls above false ceiling | | | | YES | |
| 8696 | ACTIVE | N | N043-00-3/204 | Passage - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17615 | ACTIVE | N | N043-00-3/204/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid & concrete blockwork, PVC cables, tiled walls above false ceiling | | | | YES | |
| 8697 | ACTIVE | N | N043-00-3/205 | Passage - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18076 | ACTIVE | N | N043-00-3/205/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid & concrete blockwork, PVC cables, tiled walls above false ceiling | | | | YES | |
| 8698 | ACTIVE | N | N043-00-3/206 | Passage - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18057 | ACTIVE | N | N043-00-3/206/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid & concrete blockwork, PVC cables, tiled walls above false ceiling | | | | YES | |
| 8699 | ACTIVE | N | N043-00-3/207 | Passage - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17711 | ACTIVE | N | N043-00-3/207/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid & concrete blockwork, PVC cables, tiled walls above false ceiling | | | | YES | |



Hazardous Material Asset Register - Summary



N043-00 - Station Building - Hampstead Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 8700 | ACTIVE | N | N043-00-3/208 | Passage - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17712 | ACTIVE | N | N043-00-3/208/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid & concrete blockwork, PVC cables, tiled walls above false ceiling | | | | YES | |
| 8701 | ACTIVE | N | N043-00-3/209 | Passage - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17713 | ACTIVE | N | N043-00-3/209/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid & concrete blockwork, PVC cables, tiled walls above false ceiling | | | | YES | |
| 17714 | ACTIVE | N | N043-00-3/210 | Plant Room Access - Station Building - Hampstead Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 18144 | ACTIVE | N | N043-00-3/213 | Plant Room Access - Station Building - Hampstead Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Lift 4 Shaft Access - Durasteel panel inside access door - NAD | | | | | |
| 8702 | ACTIVE | N | N043-00-3/214 | Passage - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17715 | ACTIVE | N | N043-00-3/214/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Durasteel side of lifts above metal grid ceiling by lift | | | | YES | |
| 8703 | ACTIVE | N | N043-00-3/215 | Passage - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17716 | ACTIVE | N | N043-00-3/215/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Durasteel side of lifts above metal grid ceiling by lift | | | | YES | |
| 8704 | ACTIVE | N | N043-00-3/216 | Passage - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17717 | ACTIVE | N | N043-00-3/216 | Passage - Station Building - Hampstead Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8705 | ACTIVE | N | N043-00-3/217 | Passage - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17718 | ACTIVE | N | N043-00-3/217/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid & concrete blockwork, PVC cables, tiled walls above false ceiling | | | | YES | |
| 8706 | ACTIVE | N | N043-00-3/411 | Store - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N043-00 - Station Building - Hampstead Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18145 | ACTIVE | N | N043-00-3/411/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 17719 | ACTIVE | N | N043-00-3/411/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid & concrete blockwork, PVC cables, tiled walls above false ceiling | | | | YES | |
| 8707 | ACTIVE | N | N043-00-3/601 | Stairs: Linear - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18224 | ACTIVE | N | N043-00-3/601/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid & concrete blockwork, PVC cables, tiled walls above false ceiling | | | | YES | |
| 8708 | ACTIVE | N | N043-00-3/602 | Stairs: Linear - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17720 | ACTIVE | N | N043-00-3/602/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid & concrete blockwork, PVC cables, tiled walls above false ceiling | | | | YES | |
| 8709 | ACTIVE | N | N043-00-3/661 | Switch Room - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17722 | ACTIVE | N | N043-00-3/661/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid & concrete blockwork, PVC cables, tiled walls above false ceiling | | | | YES | |
| 17721 | ACTIVE | N | N043-00-3/661/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Metal/ Supalux | | | | | |
| 8710 | ACTIVE | N | N043-00-3/662 | Switch Cupboard - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18146 | ACTIVE | N | N043-00-3/662 | Switch Cupboard - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux panels above door | | | | | |
| 8711 | ACTIVE | N | N043-00-3/711 | SER - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17723 | ACTIVE | N | N043-00-3/711 | SER - Station Building - Hampstead Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 17724 | ACTIVE | N | N043-00-3/791 | Vent Shaft - Station Building - Hampstead Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8712 | ACTIVE | N | N043-00-4/201 | Passage - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N043-00 - Station Building - Hampstead Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 8713 | ACTIVE | N | N043-00-4/202 | Passage - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8714 | ACTIVE | N | N043-00-4/261 | Platform 1 - Northbound Local - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70983 | ACTIVE | N | N043-00-4/261 | Platform 1 - Northbound Local - Station Building - Hampstead Stn | Gasket :Pipework | Asbestos | Presumed | | | | Platform Invert - Gaskets - throughout - To flange of metal pipework | | | R731055 | N | Y |
| 70975 | ACTIVE | N | N043-00-4/261 | Platform 1 - Northbound Local - Station Building - Hampstead Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R731055 | | |
| 70979 | ACTIVE | N | N043-00-4/261 | Platform 1 - Northbound Local - Station Building - Hampstead Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 6 no To trackside wall, corner departure end | | 6 | R731055 | N | Y |
| 70985 | ACTIVE | N | N043-00-4/261 | Platform 1 - Northbound Local - Station Building - Hampstead Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Materials within small Westinghouse box - total 1 no - To platform wall, midway | | 1 | R731055 | | |
| 70988 | ACTIVE | N | N043-00-4/261 | Platform 1 - Northbound Local - Station Building - Hampstead Stn | Boarding / Panels | Asbestos | Sampled – Not Detected | | | | Platform Invert - Wooden board/ shuttering - To ceiling | | | R731055 | | |
| 70977 | ACTIVE | N | N043-00-4/261 | Platform 1 - Northbound Local - Station Building - Hampstead Stn | Debris: Other | Asbestos | Sampled – Not Detected | | | | Platform Invert - Plastic and metal pipework - MMMF insulation - Throughout | | | R731055 | N | Y |
| 18147 | ACTIVE | N | N043-00-4/261 | Platform 1 - Northbound Local - Station Building - Hampstead Stn | Cable Ducts: Bitumen | Asbestos | Surveyed – Not Detected | | | | XTX Ducts | | | | | |
| 70976 | ACTIVE | N | N043-00-4/261 | Platform 1 - Northbound Local - Station Building - Hampstead Stn | Debris: Other | Asbestos | Sampled – Not Detected | | | | Platform Invert - Plastic cables, metal conduits and cable management system and firestops and mastics - new - Throughout | | | R731055 | N | Y |
| 25720 | ACTIVE | N | N043-00-4/261 | Platform 1 - Northbound Local - Station Building - Hampstead Stn | Cable: Sheath | Asbestos | Known | | | | JH4 1x Cable (Tailwall by 4/771) | | 1 | | N | N |
| 17725 | ACTIVE | N | N043-00-4/261 | Platform 1 - Northbound Local - Station Building - Hampstead Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | JH4 1 x cable - (Headwall by 4-711) | | 1 | | N | N |
| 70978 | ACTIVE | N | N043-00-4/261 | Platform 1 - Northbound Local - Station Building - Hampstead Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R731055 | | |
| 70981 | ACTIVE | N | N043-00-4/261 | Platform 1 - Northbound Local - Station Building - Hampstead Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - total 2 no throughout - To J Hangers | | 2 | R731055 | | |
| 69341 | ACTIVE | N | N043-00-4/261 | Platform 1 - Northbound Local - Station Building - Hampstead Stn | | Asbestos | Surveyed – Not Detected | | | | No identified ACMs within cable trunking at high level throughout | | | R679626 | | |



Hazardous Material Asset Register - Summary



N043-00 - Station Building - Hampstead Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-------------------------------|---|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 19073 | ACTIVE | N | N043-00-4/261/FLR-01 | Floor: Platform - 1 - Platform 1 - Station Building - Hampstead Stn | Cable Ducts: Bitumen | Asbestos | Surveyed – Not Detected | | | | Cable Sleeves/ Ducts: Non Asbestos: 4no South End - Concrete, 3no North End Head Wall - Bitumen; 3no Pit Side - Metal; 6no Cable Sleeves by Ladder - Metal | | | | | YES |
| 17726 | ACTIVE | N | N043-00-4/261/FLR-01 80903371 | Floor: Platform - 1 - Platform 1 - Station Building - Hampstead Stn Floor | Cable Duct: Other | Asbestos | Strongly Presumed | | | | Platform 1 Invert - Cable Sleeves/ Ducts - Mid. Platform No access into platform inverts during 2023 re-inspection - confined space entry required. | | | | | YES |
| 17727 | ACTIVE | N | N043-00-4/261/FLR-01 80903371 | Floor: Platform - 1 - Platform 1 - Station Building - Hampstead Stn Floor | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 1 Invert - 50mm White Cable to right hand side of cable sleeves, runs along lower J-Hanger, pit side, whole length No access into platform inverts during 2023 re-inspection - confined space entry required. | | | | | YES |
| 8715 | ACTIVE | N | N043-00-4/262 | Platform 2 - Southbound Local - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70963 | ACTIVE | N | N043-00-4/262 | Platform 2 - Southbound Local - Station Building - Hampstead Stn | Debris: Other | Asbestos | Sampled – Not Detected | | | | Platform Invert - Plastic cables, metal conduits and cable management system and firestops and mastics - new - Throughout | | | R731055 | N | Y |
| 69346 | ACTIVE | N | N043-00-4/262 | Platform 2 - Southbound Local - Station Building - Hampstead Stn | | Asbestos | Surveyed – Not Detected | | | | No identified ACMs within cable trunking at high level throughout | | | R679626 | | |
| 70972 | ACTIVE | N | N043-00-4/262 | Platform 2 - Southbound Local - Station Building - Hampstead Stn | Cable Wrap | Asbestos | Sampled – Not Detected | | | | Platform Invert - Wrapping/ cloth - total 1 no x 40m throughout - To pipework by vent shaft entrance | 40 | 1 | R731055 | | |
| 70973 | ACTIVE | N | N043-00-4/262 | Platform 2 - Southbound Local - Station Building - Hampstead Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | Platform Invert - Bitumen cable duct - total 1 no - To trackside wall, departure end - | | 1 | R731055 | N | Y |
| 70974 | ACTIVE | N | N043-00-4/262 | Platform 2 - Southbound Local - Station Building - Hampstead Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable duct- total 1 no - To ceiling, departure end | | 1 | R731055 | N | Y |
| 70965 | ACTIVE | N | N043-00-4/262 | Platform 2 - Southbound Local - Station Building - Hampstead Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R731055 | | |
| 70970 | ACTIVE | N | N043-00-4/262 | Platform 2 - Southbound Local - Station Building - Hampstead Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 3 no - To trackside wall, midway | | 3 | R731055 | N | Y |
| 70971 | ACTIVE | N | N043-00-4/262 | Platform 2 - Southbound Local - Station Building - Hampstead Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Materials within small Westinghouse box - total 1 no - To trackside wall | | 1 | R731055 | | |
| 70964 | ACTIVE | N | N043-00-4/262 | Platform 2 - Southbound Local - Station Building - Hampstead Stn | Debris: Other | Asbestos | Sampled – Not Detected | | | | Platform Invert - Plastic and metal pipework - MMMF insulation - Throughout | | | R731055 | N | Y |
| 70966 | ACTIVE | N | N043-00-4/262 | Platform 2 - Southbound Local - Station Building - Hampstead Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - total 8 no throughout - To J Hangers | | 8 | R731055 | | |



Hazardous Material Asset Register - Summary



N043-00 - Station Building - Hampstead Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 70969 | ACTIVE | N | N043-00-4/262 | Platform 2 - Southbound Local - Station Building - Hampstead Stn | Gasket :Pipework | Asbestos | Presumed | | | | Platform Invert - Gaskets - throughout - To flange of metal pipework | | | R731055 | N | Y |
| 18211 | ACTIVE | N | N043-00-4/262/ FLR-01 80945554 | Floor: Platform - 1 - Platform 2 - Station Building - Hampstead Stn Floor: Platform | Cable: Sheath | Asbestos | Strongly Presumed | | | | Various Cables No access into platform inverts during 2023 re-inspection - confined space entry required. | | | | N | YES |
| 18085 | ACTIVE | N | N043-00-4/262/ FLR-01 80945554 | Floor: Platform - 1 - Platform 2 - Station Building - Hampstead Stn Floor: Platform | Cable Ducts: Cement | Asbestos | Known | | | | To lower lift shaft link tunnel Cement Ducts - Chrysotile; No access into lift shaft link tunnel during 2023 re-inspection - confined space entry via platform inverts required. | | 2 | | | YES |
| 17728 | ACTIVE | N | N043-00-4/262/ FLR-01 | Floor: Platform - 1 - Platform 2 - Station Building - Hampstead Stn | Cable: Wrap | Asbestos | Surveyed – Not Detected | | | | | | | | | YES |
| 18566 | ACTIVE | N | N043-00-4/262/ FLR-01 | Floor: Platform - 1 - Platform 2 - Station Building - Hampstead Stn | Cable Ducts: Bitumen | Asbestos | Surveyed – Not Detected | | | | Bitumen Cable Sleeves | | | | | YES |
| 8716 | ACTIVE | N | N043-00-4/661 | Switch Room - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20364 | ACTIVE | N | N043-00-4/661/ WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Hampstead Stn | Cable: Sheath | Asbestos | Surveyed – Not Detected | | | | Red wrapping around cables non asbestos | | | | | |
| 17729 | ACTIVE | N | N043-00-4/661/ WAL-001 80903380 | Wall: Internal - 1 - Switch Room - Station Building - Hampstead Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | Insulation within 5 x Blue Switch Fuse Boxes 3 x 60 amps, 1 x 100amps, 1 x 200amps No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 5 | | N | N |
| 20366 | ACTIVE | N | N043-00-4/661/ WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Hampstead Stn | Other Boarding | Asbestos | Not Found during Inspection | | | | Paxoline Board | | | | | |
| 17730 | ACTIVE | N | N043-00-4/661/ WAL-002 80903381 | Wall: Internal - 2 - Switch Room - Station Building - Hampstead Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | 2 x Transformer Boxes No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 2 | | N | N |
| 20363 | ACTIVE | N | N043-00-4/661/ WAL-003 80903382 | Wall: Internal - 3 - Switch Room - Station Building - Hampstead Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 x 60 amp Switch Box No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 8717 | ACTIVE | N | N043-00-4/662 | Switch Cupboard - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17731 | ACTIVE | N | N043-00-4/662/ WAL-002 | Wall: Internal - 2 - Switch Cupboard - Station Building - Hampstead Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 2 x Switch Fuse Boxes - Insultation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within | | 2 | | N | N |



Hazardous Material Asset Register - Summary



N043-00 - Station Building - Hampstead Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|--------------------------------|--|-------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|------------------------------|---------------------|-------------------|
| 8718 | ACTIVE | N | N043-00-4/664 | Switch Cupboard - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8719 | ACTIVE | N | N043-00-4/701 | IMR - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 17732 | ACTIVE | N | N043-00-4/701 | IMR - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel on Walls | | | | | |
| 8720 | INACTIVE | N | N043-00-4/711 | Relay Room - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17733 | INACTIVE | N | N043-00-4/711 | Relay Room - Station Building - Hampstead Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 1 x 50mm White Cable, 1x 50mm Green Cable, & 3 x 6mm Cable - removed by DCUK on 14/04/22 as part of TCP | | 5 | | N | N |
| 44068 | INACTIVE | N | N043-00-4/711 | Relay Room - Station Building - Hampstead Stn | Other Boarding | Asbestos | Not Found during Inspection | | | | Paxoline Boarding Walls 1 & 2 | | | Re-Inspection - Alan Hartley | | |
| 18292 | INACTIVE | N | N043-00-4/711 | Relay Room - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Partition | | | | | |
| 44847 | INACTIVE | N | N043-00-4/711 | Relay Room - Station Building - Hampstead Stn | | Asbestos | Strongly Presumed | | | | 600v electrical box - insulating materials within removed by DCUK on 14/04/22 as part of TCP | | | | | |
| 20365 | INACTIVE | N | N043-00-4/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Hampstead Stn | Other Boarding | Asbestos | Strongly Presumed | | | | Paxoline Board - removed by DCUK on 14/04/22 as part of TCP | | 1 | | N | N |
| 44005 | INACTIVE | N | N043-00-4/711/WAL-001 80903410 | Wall: Internal - 1 - Relay Room - Station Building - Hampstead Stn Wall: Internal | PCBs | Polychlorinated biphenyl | Presumed | | | | Blue cylinder, potential PCBS containing | | 1 | | N | N |
| N043 | INACTIVE | N | N043-00-4/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Hampstead Stn | Other Boarding | Asbestos | Not Found during Inspection | | | | Paxoline Board | | | | | |
| 17734 | INACTIVE | N | N043-00-4/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Hampstead Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | 8 x PCB's - located within a roller shutter cabinet. Fair Condition. Serial no. not visible | | 8 | | N | N |
| 8721 | ACTIVE | N | N043-00-4/712 | Relay Room - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18293 | INACTIVE | N | N043-00-4/712 | Relay Room - Station Building - Hampstead Stn | Cable: Sheath | Asbestos | Not Found during Inspection | | | | 1 x 0.5m x 20mm Cables Cable not present during 2020 re-inspection | | 1 | | N | N |
| 17736 | ACTIVE | N | N043-00-4/712 | Relay Room - Station Building - Hampstead Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 4 x 5m x 20mm Cables | | 4 | | N | N |
| 17735 | ACTIVE | N | N043-00-4/712 | Relay Room - Station Building - Hampstead Stn | Cable Duct: Other | Asbestos | Strongly Presumed | | | | Cable Ducts | | | | N | N |



Hazardous Material Asset Register - Summary



N043-00 - Station Building - Hampstead Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------------------------|--|---------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 20368 | ACTIVE | N | N043-00-4/712 80143089 | Relay Room - Station Building - Hampstead Stn Room Assets | Other Boarding | Asbestos | Strongly Presumed | | | | 3x Paxoline Board on various walls | | 3 | | N | N |
| 42325 | INACTIVE | N | N043-00-4/712 | Relay Room - Station Building - Hampstead Stn | PCBs | Polychlorinated biphenyl | Removed | | | | 3 x blue cylinder IPCB's ocated on racks - fair condition Re moved buy others date un known | | 3 | | N | N |
| 8722 | ACTIVE | N | N043-00-4/713 | Relay Room - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17738 | ACTIVE | N | N043-00-4/713 | Relay Room - Station Building - Hampstead Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cable 4x 20mm | | 4 | | N | N |
| 20369 | ACTIVE | N | N043-00-4/713/ WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Hampstead Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | 2 x Westinghouse Boxes No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within | | 2 | | N | N |
| 18294 | INACTIVE | N | N043-00-4/713/ WAL-002 80903427 | Wall: Internal - 2 - Relay Room - Station Building - Hampstead Stn Wall: Internal | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | 3 3x black boxes all potential PCBs.Fair Condition. Serial Nos not visible | | 3 | | N | N |
| 17737 | ACTIVE | N | N043-00-4/713/ WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Hampstead Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Loose Board (1m²) by wall 3 | | 1 | | | |
| 8723 | ACTIVE | N | N043-00-4/771 | Pump Room - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19074 | ACTIVE | N | N043-00-4/771 | Pump Room - Station Building - Hampstead Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8724 | ACTIVE | N | N043-00-4/901 | Store - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17739 | ACTIVE | N | N043-00-4/901 | Store - Station Building - Hampstead Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8725 | ACTIVE | N | N043-00-4/902 | Store - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17740 | ACTIVE | N | N043-00-4/902 | Store - Station Building - Hampstead Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8726 | ACTIVE | N | N043-00-4/903 | Equipment Room - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17741 | ACTIVE | N | N043-00-4/903 | Equipment Room - Station Building - Hampstead Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8727 | ACTIVE | N | N043-00-4/951 | Platform Invert - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N043-00 - Station Building - Hampstead Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|--------------------------------|---|-------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18086 | ACTIVE | N | N043-00-4/951 | Platform Invert - Station Building - Hampstead Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cable 50mm | | 1 | | | |
| 8728 | ACTIVE | N | N043-00-A/131 | LMR - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18295 | INACTIVE | N | N043-00-A/131 | LMR - Station Building - Hampstead Stn | Paper Asbestos | Asbestos | Removed | | | | 4 x Drive Controller - Transformer (Paper Wrap) Upon re-inspection surveyor concluded these items were not present/removed 24-07-2014 | | 4 | | | |
| 18567 | ACTIVE | N | N043-00-A/131/DOR-01 | Door - 1 - LMR - Station Building - Hampstead Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Emergency Exit Door (2m2) - Durasteel | | | | | |
| 43332 | ACTIVE | N | N043-00-A/131/DOR-01 | Door - 1 - LMR - Station Building - Hampstead Stn | | Asbestos | Sampled – Not Detected | | | | Durasteel panel 1m2 located above exit doors to Lift No 2 | | | R557001 | N | N |
| 17742 | ACTIVE | N | N043-00-A/131/WAL-003 80903479 | Wall: Internal - 3 - LMR - Station Building - Hampstead Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | Insulation within 4 x Blue Fuse Switches 2 x 60 amps, 1 x 100 amps, 1 x 200 amps No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 4 | | N | N |
| 20371 | ACTIVE | N | N043-00-A/131/WAL-004 80903480 | Wall: Internal - 4 - LMR - Station Building - Hampstead Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | Insulation within 4 x Blue Fuse Switches 2 x 60 amps, 1 x 100 amps, 1 x 200 amps No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 4 | | N | N |
| 8729 | ACTIVE | N | N043-00-A/236 | Passage - Station Building - Hampstead Stn | Stations: Rooms | Lead Paint/Lead | Room: Not Surveyed – Asbestos Presumed | | | | Lead paint on Wall 3 presumed | | | | | |
| 17743 | ACTIVE | N | N043-00-A/236/WAL-003 | Wall: Internal - 3 - Passage - Station Building - Hampstead Stn | Lead/Leading | Lead Paint/Lead | Presumed | | | | Wall 3 possibly Lead paint | | | | N | N |
| 8730 | ACTIVE | N | N043-00-A/237 | Passage - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17744 | ACTIVE | N | N043-00-A/237 | Passage - Station Building - Hampstead Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Durasteel | | | | | |
| 8731 | INACTIVE | N | N043-00-A/238 | Passage - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17745 | ACTIVE | N | N043-00-A/238/WAL-003 | Wall: Internal - 3 - Passage - Station Building - Hampstead Stn | No Access | Asbestos | No Access: Presumed | | | | Not surveyed - No access | | | | | |
| 8732 | ACTIVE | N | N043-00-A/576 | Ladder - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N043-00 - Station Building - Hampstead Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|--------------------------------|---|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 17747 | ACTIVE | N | N043-00-A/576 | Ladder - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels by Door | | | | | |
| 17746 | ACTIVE | N | N043-00-A/576 | Ladder - Station Building - Hampstead Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Durasteel | | | | | |
| 8733 | ACTIVE | N | N043-00-A/661 | Switch Cupboard - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18087 | ACTIVE | N | N043-00-A/661 | Switch Cupboard - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels above door | | | | | |
| 8734 | ACTIVE | N | N043-00-A/761 | Tank Room - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18296 | ACTIVE | N | N043-00-A/761 | Tank Room - Station Building - Hampstead Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8735 | INACTIVE | N | N043-00-A/801 | Office - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17748 | ACTIVE | N | N043-00-A/801 | Office - Station Building - Hampstead Stn | No Access | Asbestos | No Access: Presumed | | | | Restaurant - No Access from Station | | | | | |
| 8736 | ACTIVE | N | N043-00-B/131 | LMR - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17750 | INACTIVE | N | N043-00-B/131 | LMR - Station Building - Hampstead Stn | Cable: Sheath | Asbestos | Removed | | | | Cables | | | | | |
| 17749 | ACTIVE | N | N043-00-B/131 | LMR - Station Building - Hampstead Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard Panels | | | | | |
| 18297 | ACTIVE | N | N043-00-B/131/CLG-01 | Ceiling: Solid - 1 - Lift Motor Room - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above false ceiling | | | | YES | |
| 20372 | ACTIVE | N | N043-00-B/131/WAL-003 80903578 | Wall: Internal - 3 - Lift Motor Room - Station Building - Hampstead Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | 1 x Transformer Box No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 8737 | ACTIVE | N | N043-00-B/576 | Stairs: Linear - Station Building - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17751 | ACTIVE | N | N043-00-B/576/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Hampstead Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal traywork and PVC cables, solid ceiling above false ceiling | | | | YES | |
| 19075 | ACTIVE | N | N043-00-B/576/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Hampstead Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |



Hazardous Material Asset Register - Summary



N045-00 - Station Building - Belsize Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 8739 | ACTIVE | N | N045-00-1/001 | Booking Hall - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17526 | ACTIVE | N | N045-00-1/001 | Booking Hall - Station Building - Belsize Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8740 | ACTIVE | N | N045-00-1/011 | Ticket Office - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17527 | ACTIVE | N | N045-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Belsize Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete/ Plaster above false ceiling | | | | YES | |
| 42551 | ACTIVE | N | N045-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Belsize Park Stn | Mastic | Asbestos | Surveyed – Not Detected | | | | Mastic/Putty to ducting above false ceiling throughout | | | R511551 | Y | N |
| 17971 | ACTIVE | N | N045-00-1/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Belsize Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal Tray Work and Concrete; Non Asbestos Ducts beneath Computer Flooring | | | | | YES |
| 8741 | ACTIVE | N | N045-00-1/021 | POM - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17529 | ACTIVE | N | N045-00-1/021 | POM - Station Building - Belsize Park Stn | Void | Asbestos | No Access: Presumed | | | | Supalux/ Plasterboard - Boxing to Wall | | | | | |
| 17530 | ACTIVE | N | N045-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Belsize Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete/ Plaster above false ceiling | | | | YES | |
| 17528 | ACTIVE | N | N045-00-1/021/FLR-01 | Floor - 1 - POM - Station Building - Belsize Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal Tray Work and Concrete; Non Asbestos Ducts beneath Computer Flooring | | | | | YES |
| 8742 | ACTIVE | N | N045-00-1/031 | Mess Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17531 | ACTIVE | N | N045-00-1/031 | Mess Room - Station Building - Belsize Park Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 18069 | ACTIVE | N | N045-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Belsize Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete/ Plaster above false ceiling | | | | YES | |
| 17972 | ACTIVE | N | N045-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Belsize Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 8743 | ACTIVE | N | N045-00-1/036 | Lobby - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17534 | ACTIVE | N | N045-00-1/036 | Lobby - Station Building - Belsize Park Stn | Void | Asbestos | No Access: Presumed | | | | Supalux Boxing - No Access within | | | | | |



Hazardous Material Asset Register - Summary



N045-00 - Station Building - Belsize Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|----------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 17533 | ACTIVE | N | N045-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Belsize Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 17532 | ACTIVE | N | N045-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Belsize Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 8744 | ACTIVE | N | N045-00-1/037 | Toilet: Unisex - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17536 | ACTIVE | N | N045-00-1/037 | Toilet: Unisex - Station Building - Belsize Park Stn | Void | Asbestos | No Access: Presumed | | | | Wooden Boxing - No Access within | | | | | |
| 17973 | ACTIVE | N | N045-00-1/037/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Belsize Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 17535 | ACTIVE | N | N045-00-1/037/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Belsize Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 8745 | ACTIVE | N | N045-00-1/071 | Circulation Area - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17537 | ACTIVE | N | N045-00-1/071 | Circulation Area - Station Building - Belsize Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8746 | ACTIVE | N | N045-00-1/072 | Circulation Area - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17538 | ACTIVE | N | N045-00-1/072 | Circulation Area - Station Building - Belsize Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8747 | ACTIVE | N | N045-00-1/081 | Lobby - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17974 | ACTIVE | N | N045-00-1/081/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Belsize Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 17539 | ACTIVE | N | N045-00-1/081/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Belsize Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 8748 | ACTIVE | N | N045-00-1/181 | Forecourt - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20024 | ACTIVE | N | N045-00-1/181 | Forecourt - Station Building - Belsize Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8749 | ACTIVE | N | N045-00-1/182 | Yard - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N045-00 - Station Building - Belsize Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------------------|--|-----------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17540 | ACTIVE | N | N045-00-1/182 | Yard - Station Building - Belsize Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8750 | ACTIVE | N | N045-00-1/183 | Forecourt - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17541 | ACTIVE | N | N045-00-1/183 | Forecourt - Station Building - Belsize Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8751 | ACTIVE | N | N045-00-1/236 | Lobby - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17543 | ACTIVE | N | N045-00-1/236 | Lobby - Station Building - Belsize Park Stn | Void | Asbestos | No Access: Presumed | | | | Metal Boxing - No Access within | | | | | |
| 17542 | ACTIVE | N | N045-00-1/236/CLG-01 80882792 | Ceiling: Suspended - 1 - Lobby - Station Building - Belsize Park Stn Ceiling: Suspended | Void | Asbestos | No Access: Presumed | | | | Above screwed tiles above room 1/662 | | | | Y | N |
| 18070 | ACTIVE | N | N045-00-1/236/FLR-01 | Floor - 1 - Lobby - Station Building - Belsize Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal Tray Work and Concrete; Non Asbestos Ducts beneath Computer Flooring | | | | | YES |
| 8752 | ACTIVE | N | N045-00-1/237 | Passage - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17975 | ACTIVE | N | N045-00-1/237/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Belsize Park Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Durasteel non asbestos | | | | | |
| 17616 | ACTIVE | N | N045-00-1/237/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Belsize Park Stn | Void | Asbestos | No Access: Presumed | | | | Above false ceiling | | | | YES | |
| 8753 | ACTIVE | N | N045-00-1/238 | Lobby - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17617 | ACTIVE | N | N045-00-1/238 | Lobby - Station Building - Belsize Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing (Hollow with PVC cables passing through) | | | | | |
| 8754 | ACTIVE | N | N045-00-1/311 | Mess Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18058 | ACTIVE | N | N045-00-1/311 | Mess Room - Station Building - Belsize Park Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Foam backing | | | | | |
| 8755 | ACTIVE | N | N045-00-1/331 | Mess Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17619 | ACTIVE | N | N045-00-1/331/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Belsize Park Stn | Other Boarding | Asbestos | No Access: Presumed | | | | Above false ceiling | | | | | |



Hazardous Material Asset Register - Summary



N045-00 - Station Building - Belsize Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 17618 | ACTIVE | N | N045-00-1/331/FLR-01 | Floor - 1 - Mess Room - Station Building - Belsize Park Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Rubber Flooring | | | | | YES |
| 8756 | ACTIVE | N | N045-00-1/406 | Bin Store - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17620 | ACTIVE | N | N045-00-1/406 | Bin Store - Station Building - Belsize Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing (Hollow with PVC cables passing through) | | | | | |
| 8757 | ACTIVE | N | N045-00-1/416 | Toilet: Unisex - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8758 | ACTIVE | N | N045-00-1/417 | Toilet: Unisex - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18059 | ACTIVE | N | N045-00-1/417 | Toilet: Unisex - Station Building - Belsize Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 8759 | ACTIVE | N | N045-00-1/426 | Toilet: Female - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17622 | ACTIVE | N | N045-00-1/426/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Belsize Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Fibreglass Lagging above false ceiling | | | | YES | |
| 17621 | ACTIVE | N | N045-00-1/426/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Belsize Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 8760 | ACTIVE | N | N045-00-1/427 | Toilet: Male - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17623 | ACTIVE | N | N045-00-1/427/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Belsize Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Lagging on Pipes above false ceiling | | | | YES | |
| 18077 | ACTIVE | N | N045-00-1/427/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Belsize Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 8761 | ACTIVE | N | N045-00-1/576 | Stairs: Linear - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19068 | ACTIVE | N | N045-00-1/576 | Stairs: Linear - Station Building - Belsize Park Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Steel Tunnel Rings - Non Asbestos | | | | | |
| 18060 | ACTIVE | N | N045-00-1/576 | Stairs: Linear - Station Building - Belsize Park Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | New Durasteel Panels; | | | | | |
| 8762 | ACTIVE | N | N045-00-1/578 | Lobby - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



| N045-00 - Station Building - Belsize Park Stn | | | | | | | | | | | | | | | | |
|---|--------|-------------|---------------------------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
| 17624 | ACTIVE | N | N045-00-1/578 | Lobby - Station Building - Belsize Park Stn | No Access | Asbestos | No Access: Presumed | | | | New Construction. Stairs leading to passage A/237 - 190 Haverstock | | | | | |
| 8763 | ACTIVE | N | N045-00-1/631 | Stairs: Spiral - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17625 | ACTIVE | N | N045-00-1/631 | Stairs: Spiral - Station Building - Belsize Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8764 | ACTIVE | N | N045-00-1/661 | Switch Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44846 | ACTIVE | N | N045-00-1/661 | Switch Room - Station Building - Belsize Park Stn | | Asbestos | Strongly Presumed | | | | Supalux - Panel High Level & Boxing | | | | | |
| 18061 | ACTIVE | N | N045-00-1/661/ WAL-001 80882895 | Wall: Internal - 1 - Switch Room - Station Building - Belsize Park Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | Insulation with Switch Boxes x 5. 1x 200amp, 1 x 60amp, 3 x 100 amps | | 5 | | N | N |
| 25721 | ACTIVE | N | N045-00-1/661/ WAL-002 80882896 | Wall: Internal - 2 - Switch Room - Station Building - Belsize Park Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | 3x Transformer boxes | | 3 | | N | N |
| 17626 | ACTIVE | N | N045-00-1/661/ WAL-002 80882896 | Wall: Internal - 2 - Switch Room - Station Building - Belsize Park Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | Insulation with Switch Boxes 1 x 30amp | | 1 | | N | N |
| 17627 | ACTIVE | N | N045-00-1/661/ WAL-003 80882897 | Wall: Internal - 3 - Switch Room - Station Building - Belsize Park Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | Insulation with Switch Boxes x 4 - 2 x 100amps, 2 x 60amps | | 4 | | N | N |
| 17628 | ACTIVE | N | N045-00-1/661/ WAL-003 80882897 | Wall: Internal - 3 - Switch Room - Station Building - Belsize Park Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | 1 x Transformer Box | | 1 | | N | N |
| 8765 | ACTIVE | N | N045-00-1/662 | Switch Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17630 | ACTIVE | N | N045-00-1/662/ CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Belsize Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Plaster above false ceiling | | | | YES | |
| 17629 | ACTIVE | N | N045-00-1/662/ WAL-002 80882903 | Wall: Internal - 2 - Switch Room - Station Building - Belsize Park Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | Insulation within 9 x Switch Fuse Boxes - 2 x 100amp, 1 x 30amp, 5 x 60amp, 1 x 200amps | | 9 | | N | N |
| 8766 | ACTIVE | N | N045-00-1/711 | Relay Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18078 | ACTIVE | N | N045-00-1/711 | Relay Room - Station Building - Belsize Park Stn | Vinyl tiles | Asbestos | Strongly Presumed | | | | Vinyl tiles on all walls, (substation) some tiles have been removed historically and adhesive remains | | 30 | | | |



Hazardous Material Asset Register - Summary



N045-00 - Station Building - Belsize Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------------------|---|---------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 8767 | ACTIVE | N | N045-00-1/746 | SCR - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18062 | ACTIVE | N | N045-00-1/746/CLG-01 | Ceiling: Suspended - 1 - SCR - Station Building - Belsize Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Supalux Panel above false ceiling | | | | YES | |
| 8768 | ACTIVE | N | N045-00-1/776 | Fan Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18561 | ACTIVE | N | N045-00-1/776 | Fan Room - Station Building - Belsize Park Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | | | | | | |
| 8769 | ACTIVE | N | N045-00-1/781 | Transformer Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17631 | ACTIVE | N | N045-00-1/781/CLG-01 80883573 | Ceiling: Solid - 1 - Transformer Room - Station Building - Belsize Park Stn Ceiling: Solid | Cellactite Sheeting | Asbestos | Strongly Presumed | | | | Corrugated sheeting and skylights (substation) DSC05225 - Corrugated sheets (MMMF) to ceiling 20mx40m DSC05226 - Rope seals to glazing bars of skylights to ceiling throughout | | | | | |
| 8770 | ACTIVE | N | N045-00-1/901 | Void - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17632 | ACTIVE | N | N045-00-1/901 | Void - Station Building - Belsize Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8771 | ACTIVE | N | N045-00-1/951 | Disused Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17633 | ACTIVE | N | N045-00-1/951 | Disused Room - Station Building - Belsize Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8772 | ACTIVE | N | N045-00-2/201 | Passage - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17634 | ACTIVE | N | N045-00-2/201 | Passage - Station Building - Belsize Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8773 | ACTIVE | N | N045-00-2/631 | Stairs: Spiral - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18063 | ACTIVE | N | N045-00-2/631 | Stairs: Spiral - Station Building - Belsize Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8774 | ACTIVE | N | N045-00-2/661 | Switch Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N045-00 - Station Building - Belsize Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|--------------------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 17635 | ACTIVE | N | N045-00-2/661/WAL-001 80883112 | Wall: Internal - 1 - Switch Room - Station Building - Belsize Park Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 4x Switch Boxes Strongly Presumed materials within | | 4 | | | |
| 18222 | INACTIVE | N | N045-00-2/661/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Belsize Park Stn | Isolator Switches | Asbestos | Removed | | | | 4 x Switch Boxes | | 4 | | | |
| 8775 | ACTIVE | N | N045-00-2/662 | Switch Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8776 | ACTIVE | N | N045-00-2/731 | CER - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17636 | ACTIVE | N | N045-00-2/731/FLR-01 | Floor - 1 - CER - Station Building - Belsize Park Stn | Cable Duct: Other | Asbestos | Presumed | | | | Restricted Access - Not possible to sample Duct Material (P); Metal Traywork and PVC Cables observed beneath Computer Flooring Floor void congested and equipment on false floor fixed restrictiing access | | | | N | Y |
| 18064 | ACTIVE | N | N045-00-2/731/WAL-003 80883122 | Wall: Internal - 3 - CER - Station Building - Belsize Park Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 2 x Switch Boxes strongly presumed materials within | | 2 | | N | N |
| 20374 | ACTIVE | N | N045-00-2/731/WAL-004 | Wall: Internal - 4 - CER - Station Building - Belsize Park Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline Board | | | | N | N |
| 17637 | ACTIVE | N | N045-00-2/791 | Vent Shaft - Station Building - Belsize Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8777 | ACTIVE | N | N045-00-2/951 | Disused Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17638 | ACTIVE | N | N045-00-2/951 | Disused Room - Station Building - Belsize Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8778 | ACTIVE | N | N045-00-3/201 | Passage - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19069 | ACTIVE | N | N045-00-3/201 | Passage - Station Building - Belsize Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8779 | ACTIVE | N | N045-00-3/202 | Passage - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18065 | ACTIVE | N | N045-00-3/202 | Passage - Station Building - Belsize Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8780 | ACTIVE | N | N045-00-3/203 | Passage - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N045-00 - Station Building - Belsize Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17639 | ACTIVE | N | N045-00-3/203 | Passage - Station Building - Belsize Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8781 | ACTIVE | N | N045-00-3/411 | Store - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17640 | ACTIVE | N | N045-00-3/411/CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Belsize Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Concrete/ Supalux | | | | | |
| 8782 | ACTIVE | N | N045-00-3/412 | CER - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17641 | ACTIVE | N | N045-00-3/412 | CER - Station Building - Belsize Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8783 | ACTIVE | N | N045-00-3/601 | Stairs: Linear - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18066 | ACTIVE | N | N045-00-3/601 | Stairs: Linear - Station Building - Belsize Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8784 | ACTIVE | N | N045-00-3/602 | Stairs: Linear - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17642 | ACTIVE | N | N045-00-3/602 | Stairs: Linear - Station Building - Belsize Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 17643 | ACTIVE | N | N045-00-3/636 | Overbridge - Station Building - Belsize Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 17644 | ACTIVE | N | N045-00-3/637 | Overbridge - Station Building - Belsize Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8785 | ACTIVE | N | N045-00-4/081 | Store - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8786 | ACTIVE | N | N045-00-4/121 | Platform Invert - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18067 | ACTIVE | N | N045-00-4/121 | Platform Invert - Station Building - Belsize Park Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Rings - Platform Walls | | | | | |
| 19070 | ACTIVE | N | N045-00-4/121 | Platform Invert - Station Building - Belsize Park Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform Invert 1 - 1 x 50mm Cable going to Tunnel Inverts through floor and then back out of invert ceiling No access during 2024 reinspection - Confined space team required to gain access to invert. | | | | | |
| 8787 | ACTIVE | N | N045-00-4/122 | Platform Invert - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N045-00 - Station Building - Belsize Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17645 | ACTIVE | N | N045-00-4/122 | Platform Invert - Station Building - Belsize Park Stn | No Access | Asbestos | No Access: Presumed | | | | Invert only half surveyed | | | | | |
| 17646 | ACTIVE | N | N045-00-4/122 | Platform Invert - Station Building - Belsize Park Stn | Cable: Wrap | Asbestos | Strongly Presumed | | | | Woven insulated cables running in all hangers in platform side cable run and gaskets to metal pipe - runs extra length of Platform 2 invert. No access during 2024 reinspection - Confined space team required to gain access to invert. | | | | | |
| 17647 | ACTIVE | N | N045-00-4/122 | Platform Invert - Station Building - Belsize Park Stn | Cable Duct: Other | Asbestos | Surveyed – Not Detected | | | | Departure end of invert – all Cable Ducts identified as Ceramic | | | | | |
| 8788 | ACTIVE | N | N045-00-4/123 | Switch Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18068 | ACTIVE | N | N045-00-4/123 | Switch Room - Station Building - Belsize Park Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 1 x 50mm Cable going to Tunnel Inverts through floor and then back out of invert ceiling | | | | | |
| 8789 | ACTIVE | N | N045-00-4/201 | Passage - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8790 | ACTIVE | N | N045-00-4/202 | Passage - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8791 | ACTIVE | N | N045-00-4/203 | Passage - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8792 | ACTIVE | N | N045-00-4/261 | Platform 1 - Northbound Local - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70957 | ACTIVE | N | N045-00-4/261 | Platform 1 - Northbound Local - Station Building - Belsize Park Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable duct - total 5 no - To trackside wall arrivals end | | 5 | R731054 | N | Y |
| 70958 | ACTIVE | N | N045-00-4/261 | Platform 1 - Northbound Local - Station Building - Belsize Park Stn | Gasket :Pipework | Asbestos | Known | | | | Platform Invert - Gaskets - throughout - To metal pipework flanges | | | R731054 | N | Y |
| 70959 | ACTIVE | N | N045-00-4/261 | Platform 1 - Northbound Local - Station Building - Belsize Park Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 3 no - To trackside wall midway | | 3 | R731054 | N | Y |
| 70961 | ACTIVE | N | N045-00-4/261 | Platform 1 - Northbound Local - Station Building - Belsize Park Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts debris - total 5no <1m - To floor - midway by trench | 1 | 5 | R731054 | N | Y |
| 70962 | ACTIVE | N | N045-00-4/261 | Platform 1 - Northbound Local - Station Building - Belsize Park Stn | Debris: Other | Asbestos | Sampled – Not Detected | | | | Platform Invert - MMMF insulation - To floor and ducts throughout | | | R731054 | N | Y |
| 17650 | ACTIVE | N | N045-00-4/261 | Platform 1 - Northbound Local - Station Building - Belsize Park Stn | Gasket :Pipework | Asbestos | Surveyed – Not Detected | | | | Gasket (Material witin flange) to water pipe within invert toward arrivals end, Plat 1 N/B | | | | | Y |



Hazardous Material Asset Register - Summary



N045-00 - Station Building - Belsize Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 70955 | ACTIVE | N | N045-00-4/261 | Platform 1 - Northbound Local - Station Building - Belsize Park Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable duct - total 6 no - To platform wall - departure end | | 6 | R731054 | N | Y |
| 70954 | ACTIVE | N | N045-00-4/261 | Platform 1 - Northbound Local - Station Building - Belsize Park Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/wood/lead - To tunnel rings flanges throughout | | | R731054 | | |
| 70956 | ACTIVE | N | N045-00-4/261 | Platform 1 - Northbound Local - Station Building - Belsize Park Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - throughout - To J Hangers throughout | | | R731054 | | |
| 70953 | ACTIVE | N | N045-00-4/261 | Platform 1 - Northbound Local - Station Building - Belsize Park Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R731054 | | |
| 70960 | ACTIVE | N | N045-00-4/261 | Platform 1 - Northbound Local - Station Building - Belsize Park Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 1 no - To dividing wall midway | | 1 | R731054 | N | Y |
| 17649 | ACTIVE | N | N045-00-4/261 | Platform 1 - Northbound Local - Station Building - Belsize Park Stn | Gasket :Pipework | Asbestos | Known | | | | Platform 1 Invert - N/B Arrivals End Gasket (material within flange to water pipe within invert below valve point midway, Invert Plat 1 No access during 2024 reinspection - Confined space team required to gain access to invert. | | | | | Y |
| 17648 | ACTIVE | N | N045-00-4/261 | Platform 1 - Northbound Local - Station Building - Belsize Park Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 1 x 50mm Cable going to Tunnel Inverts 4/121 through floor of 4/123 and then back out of invert ceiling | | | | N | N |
| 8793 | ACTIVE | N | N045-00-4/262 | Platform 2 - Southbound Local - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70945 | ACTIVE | N | N045-00-4/262 | Platform 2 - Southbound Local - Station Building - Belsize Park Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R731054 | | |
| 70946 | ACTIVE | N | N045-00-4/262 | Platform 2 - Southbound Local - Station Building - Belsize Park Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/wood/lead - To tunnel rings flanges throughout | | | R731054 | | |
| 70947 | ACTIVE | N | N045-00-4/262 | Platform 2 - Southbound Local - Station Building - Belsize Park Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 3 no - To ceiling - departure end | | 3 | R731054 | N | Y |
| 70948 | ACTIVE | N | N045-00-4/262 | Platform 2 - Southbound Local - Station Building - Belsize Park Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - Throughout - To J Hangers | | | R731054 | | |
| 70950 | ACTIVE | N | N045-00-4/262 | Platform 2 - Southbound Local - Station Building - Belsize Park Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Materials within large Westinghouse box - total 1 no - To head wall - arrivals end | | 1 | R731054 | | |
| 70951 | ACTIVE | N | N045-00-4/262 | Platform 2 - Southbound Local - Station Building - Belsize Park Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Platform Invert - Supalux panels, firebreak - To ceiling, walls throughout | | | R731054 | N | Y |



Hazardous Material Asset Register - Summary



N045-00 - Station Building - Belsize Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 70949 | ACTIVE | N | N045-00-4/262 | Platform 2 - Southbound Local - Station Building - Belsize Park Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | Platform Invert - Bitumen cable ducts - total 4 no - To platform wall, by mid hatch | | 4 | R731054 | N | Y |
| 70952 | ACTIVE | N | N045-00-4/262 | Platform 2 - Southbound Local - Station Building - Belsize Park Stn | Debris: Other | Asbestos | Sampled – Not Detected | | | | Platform Invert - MMMF insulation debris in cable ducts - Throughout | | | R731054 | N | Y |
| 18079 | ACTIVE | N | N045-00-4/262 | Platform 2 - Southbound Local - Station Building - Belsize Park Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables from 4/711 to tunnel | | 3 | | N | N |
| 69711 | ACTIVE | N | N045-00-4/262 | Platform 2 - Southbound Local - Station Building - Belsize Park Stn | Westing house Boxes | Asbestos | Presumed | | | | Westinghouse box to end of platform adjacent to 4/122 | | 1 | | | |
| 8794 | ACTIVE | N | N045-00-4/661 | Store - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8795 | ACTIVE | N | N045-00-4/662 | Switch Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18128 | ACTIVE | N | N045-00-4/662 | Switch Room - Station Building - Belsize Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux panel above door | | | | | |
| 19413 | ACTIVE | N | N045-00-4/662/ WAL-002 80883281 | Wall: Internal - 2 - Switch Room - Station Building - Belsize Park Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 2 x 60amp, 1 x 100 amp Switch Fuse Boxes | | 3 | | N | N |
| 8796 | ACTIVE | N | N045-00-4/663 | Switch Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17652 | ACTIVE | N | N045-00-4/663 | Switch Room - Station Building - Belsize Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux panel above door | | | | | |
| 17651 | ACTIVE | N | N045-00-4/663/ WAL-002 80883289 | Wall: Internal - 2 - Switch Room - Station Building - Belsize Park Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | Insulation within 5 x Switch Fuse Boxes - 1 x 200am, 2 x 100amp, 2 x 60amp | | 5 | | N | N |
| 20377 | ACTIVE | N | N045-00-4/663/ WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Belsize Park Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Boxes x 3 2 out of 3 boxes remain at present - 1x box removed historically. | | 2 | | N | N |
| 8797 | ACTIVE | N | N045-00-4/664 | Switch Cupboard - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17653 | ACTIVE | N | N045-00-4/664 | Switch Cupboard - Station Building - Belsize Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8798 | ACTIVE | N | N045-00-4/665 | Switch Cupboard - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18129 | ACTIVE | N | N045-00-4/665 | Switch Cupboard - Station Building - Belsize Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N045-00 - Station Building - Belsize Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|--------------------------------|---|---------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 8799 | ACTIVE | N | N045-00-4/711 | Relay Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 53534 | ACTIVE | N | N045-00-4/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Belsize Park Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 1x asbestos cable, next to lead cables entering duct within first roller shutter to wall 1 | | | | | |
| 53539 | ACTIVE | N | N045-00-4/711/WAL-001 80883314 | Wall: Internal - 1 - Relay Room - Station Building - Belsize Park Stn Wall: Internal | Other Boarding | Asbestos | Presumed | | | | small composite boarding top and bottom of transformer booster, within rack 2 (first roller shutter to door) wall 1 | | | | | |
| 53533 | ACTIVE | N | N045-00-4/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Belsize Park Stn | Other Boarding | Asbestos | Presumed | | | | 2x brown composite boarding within the first roller shutter to wall 1 | | | | | |
| 53537 | ACTIVE | N | N045-00-4/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Belsize Park Stn | Cable Ducts: Cement | Asbestos | Presumed | | | | duct to invert - in roller shutter - no access | | | | | |
| 17655 | INACTIVE | N | N045-00-4/711/WAL-001 80883314 | Wall: Internal - 1 - Relay Room - Station Building - Belsize Park Stn Wall: Internal | PCBs | Polychlorinated biphenyl | Removed | | | | 8 x PCB's - very poor condition and showing signs of leakage. Located within a roller shutter cabinet. Serial nos not visible 26/02/2016 still poor condition on re inspection Removed by Edenbeck Feb 2017 | | 8 | | N | N |
| 17654 | ACTIVE | N | N045-00-4/711/WAL-002 80883315 | Wall: Internal - 2 - Relay Room - Station Building - Belsize Park Stn Wall: Internal | Cable: Sheath | Asbestos | Strongly Presumed | | | | Asbestos Cables WALL 3 going into trackside | | | | N | N |
| 53535 | ACTIVE | N | N045-00-4/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Belsize Park Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 2 x 50mm asbestos cables from 600v electrical box to wall 2 into wall 3 (track) | | | | | |
| 53536 | ACTIVE | N | N045-00-4/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Belsize Park Stn | Other Boarding | Asbestos | Strongly Presumed | | | | Composite boarding to large metal electrical box. Wall 2 | | 1 | | | |
| 8800 | ACTIVE | N | N045-00-4/712 | Relay Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18562 | ACTIVE | N | N045-00-4/712 | Relay Room - Station Building - Belsize Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels on wall | | | | | |
| 19542 | ACTIVE | N | N045-00-4/712 | Relay Room - Station Building - Belsize Park Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 1 x 50mm Cable going to Tunnel Inverts - Type 3 states 2 x Cables | | | | N | N |
| 53540 | ACTIVE | N | N045-00-4/712/WAL-001 80883321 | Wall: Internal - 1 - Relay Room - Station Building - Belsize Park Stn Wall: Internal | Cable Ducts: Cement | Asbestos | Presumed | | | | Duct to floor through to invert | | | | | |
| 17656 | INACTIVE | N | N045-00-4/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Belsize Park Stn | PCBs | Polychlorinated biphenyl | Removed | | | | 8 x PCB's located within a roller cabinet - very poor condition with signs of Leakage. Serial nos not visible Removed by Edenbeck 2017 | | 8 | | N | N |
| 20390 | ACTIVE | N | N045-00-4/712/WAL-003 80883323 | Wall: Internal - 3 - Relay Room - Station Building - Belsize Park Stn Wall: Internal | Other Boarding | Asbestos | Presumed | | | | 1x large composite board approx, 1x2m now removed to wall 3 1x small composite now remains. | | 1 | | N | N |



Hazardous Material Asset Register - Summary



N045-00 - Station Building - Belsize Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 53538 | ACTIVE | N | N045-00-4/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Belsize Park Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | smaller composite board to wall 3 (new material) | | | | | |
| 8801 | ACTIVE | N | N045-00-4/771 | Pump Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18130 | ACTIVE | N | N045-00-4/771 | Pump Room - Station Building - Belsize Park Stn | Cable: Sheath | Asbestos | Removed | | | | 20mm Cables going to Invert 1m Cables not present during 2020 reinspection | | | | | |
| 20395 | ACTIVE | N | N045-00-4/771/FLR-01 | Floor - 1 - Pump Room - Station Building - Belsize Park Stn | Gasket :Pipework | Asbestos | Presumed | | | | Gaskets to Flanges - asbestos presumed | | | | | |
| 17657 | ACTIVE | N | N045-00-5/136 | Lift Shaft - Station Building - Belsize Park Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed | | | | | |
| 8802 | ACTIVE | N | N045-00-A/081 | Lobby - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17658 | ACTIVE | N | N045-00-A/081 | Lobby - Station Building - Belsize Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |
| 8803 | ACTIVE | N | N045-00-A/082 | Lobby - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17659 | ACTIVE | N | N045-00-A/082 | Lobby - Station Building - Belsize Park Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | 2 x Trapdoors - Durasteel 1990 Manufactured | | | | | |
| 8804 | ACTIVE | N | N045-00-A/131 | LMR - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18131 | ACTIVE | N | N045-00-A/131 | LMR - Station Building - Belsize Park Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Durasteel Panelling | | | | | |
| 17660 | ACTIVE | N | N045-00-A/131/WAL-003 | Wall: Internal - 3 - LMR - Station Building - Belsize Park Stn | Isolator Switches | Asbestos | Removed | | | | Insulation 5 x Fuse Boxes - 4 x 60amps, 1 x 100 amps Removed not present during 2020 reinspection within room as new lift equipment, upgrade and works being carried out at present. | | 5 | | N | N |
| 8805 | ACTIVE | N | N045-00-A/236 | Passage - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17661 | ACTIVE | N | N045-00-A/236 | Passage - Station Building - Belsize Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | New Construction. Mess Room leading on to passage A/237 - 190 Haverstock | | | | | |
| 8806 | ACTIVE | N | N045-00-A/237 | Passage - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17662 | ACTIVE | N | N045-00-A/237 | Passage - Station Building - Belsize Park Stn | Glazing Rope | Asbestos | Presumed | | | | Possible rope to skylight beading. Mess Room leading on to passage A/236 - 190 Haverstock | | | | | |



Hazardous Material Asset Register - Summary



N045-00 - Station Building - Belsize Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 8807 | ACTIVE | N | N045-00-A/281 | Station Supervisor Office - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18080 | ACTIVE | N | N045-00-A/281 | Station Supervisor Office - Station Building - Belsize Park Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Tiles to Floor and Walls | | | | YES | |
| 17663 | ACTIVE | N | N045-00-A/281 | Station Supervisor Office - Station Building - Belsize Park Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | White Foam Backing | | | | | |
| 17544 | ACTIVE | N | N045-00-A/281/CLG-01 | Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Belsize Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 19002 | ACTIVE | N | N045-00-A/281/CLG-02 | Ceiling: Suspended - 2 - Station Supervisor Office - Station Building - Belsize Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 8808 | ACTIVE | N | N045-00-A/316 | Locker Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17545 | ACTIVE | N | N045-00-A/316 | Locker Room - Station Building - Belsize Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8809 | ACTIVE | N | N045-00-A/317 | Locker Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17546 | ACTIVE | N | N045-00-A/317 | Locker Room - Station Building - Belsize Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | New Construction. Mess Room leading on to passage A/237 - 190 Haverstock | | | | | |
| 8810 | ACTIVE | N | N045-00-A/332 | Mess Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17976 | ACTIVE | N | N045-00-A/332 | Mess Room - Station Building - Belsize Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | New Construction. Mess Room leading on to passage A/236 - 190 Haverstock. | | | | | |
| 8811 | ACTIVE | N | N045-00-A/333 | Mess Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17547 | ACTIVE | N | N045-00-A/333 | Mess Room - Station Building - Belsize Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | New Construction. Mess Room leading on to passage A/236 - 190 Haverstock. | | | | | |
| 8812 | ACTIVE | N | N045-00-A/411 | Store - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18498 | ACTIVE | N | N045-00-A/411 | Store - Station Building - Belsize Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | New Construction. Store in between room A/317 and A/332 - 190 Haverstock | | | | | |
| 8813 | ACTIVE | N | N045-00-A/416 | Toilet: Female - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N045-00 - Station Building - Belsize Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17548 | ACTIVE | N | N045-00-A/416 | Toilet: Female - Station Building - Belsize Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | New Construction Next to Female Toilet - 190 Haverstock | | | | | |
| 8814 | ACTIVE | N | N045-00-A/417 | Toilet: Male - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17549 | ACTIVE | N | N045-00-A/417 | Toilet: Male - Station Building - Belsize Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | New Construction. Next to Male Toilet - 190 Haverstock | | | | | |
| 8815 | ACTIVE | N | N045-00-A/418 | Shower Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17550 | ACTIVE | N | N045-00-A/418 | Shower Room - Station Building - Belsize Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | New Construction. Shower leading out to passage A/237 - 190 Haverstock | | | | | |
| 8816 | ACTIVE | N | N045-00-A/577 | Stairs: Linear - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17551 | ACTIVE | N | N045-00-A/577 | Stairs: Linear - Station Building - Belsize Park Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard Panel on wall | | | | | |
| 8817 | ACTIVE | N | N045-00-A/661 | Switch Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17977 | ACTIVE | N | N045-00-A/661 | Switch Room - Station Building - Belsize Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 17552 | ACTIVE | N | N045-00-A/661 | Switch Room - Station Building - Belsize Park Stn | Void | Asbestos | No Access: Presumed | | | | Within - Supalux Boxing | | | | | |
| 18071 | ACTIVE | N | N045-00-A/661/FLR-01 | Floor - 1 - Switch Room - Station Building - Belsize Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Boxing around Floor - Supalux | | | | | |
| 8818 | ACTIVE | N | N045-00-A/662 | Switch Cupboard - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17553 | ACTIVE | N | N045-00-A/662 | Switch Cupboard - Station Building - Belsize Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Walls & Ceiling Panels | | | | | |
| 8819 | ACTIVE | N | N045-00-A/663 | Switch Cupboard - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17554 | INACTIVE | N | N045-00-A/663 | Switch Cupboard - Station Building - Belsize Park Stn | No Access | Asbestos | No Access: Presumed | | | | New Construction. Switch Room inside passage A/236 - 190 Haverstock | | | | | |
| 8820 | ACTIVE | N | N045-00-A/761 | Equipment Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8821 | ACTIVE | N | N045-00-A/762 | Equipment Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N045-00 - Station Building - Belsize Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------------------|--|---------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17978 | ACTIVE | N | N045-00-A/762 | Equipment Room - Station Building - Belsize Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 8822 | ACTIVE | N | N045-00-A/801 | Training Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17555 | ACTIVE | N | N045-00-A/801 | Training Room - Station Building - Belsize Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | New Construction. Office Next to room A/802 - 190 Haverstock | | | | | |
| 8823 | ACTIVE | N | N045-00-A/802 | Training Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17556 | ACTIVE | N | N045-00-A/802 | Training Room - Station Building - Belsize Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | New Construction Office Next to room A/801 - 190 Haverstock | | | | | |
| 69710 | ACTIVE | N | N045-00-A/802/RSK-01 100169850 | Skylight: Roof - 1 - Training Room - Station Building - Belsize Park Stn Skylight: Roof | Glazing Rope | Asbestos | Presumed | | | | Possible rope to skylight beading | | 1 | | | |
| 8824 | ACTIVE | N | N045-00-A/901 | Disused Room - Station Building - Belsize Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17979 | ACTIVE | N | N045-00-A/901 | Disused Room - Station Building - Belsize Park Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Gallery above 1/781 Substation Isolation switches. No electrician on site during 2024 reinspection to open boxes for inspection - therefore cannot score materials within. Presumed ACM to existing visible and concealed cable ducts within floor and ceiling slab throughout substation. | | 14 | | | |
| 17557 | ACTIVE | N | N045-00-A/901/CLG-01 | Ceiling: Solid - 1 - Disused Room - Station Building - Belsize Park Stn | Cellactite Sheeting | Asbestos | Strongly Presumed | | | | Gallery above 1/781 Substation Corrugated sheeting and skylights 2x different material listed rope and corrugated sheets hence 2 x scores given. Known gaskets to large ductwork / vents (redundant) labelled with ACM. through 2x up-stands on mess level of substation. | | | | | |

N047-00 - Station Building - Chalk Farm Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---------------------|-------------|------------|-------------|---------------------|-------------------|
| 8826 | ACTIVE | N | N047-00-1/001 | Booking Hall - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17485 | ACTIVE | N | N047-00-1/001 | Booking Hall - Station Building - Chalk Farm Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N047-00 - Station Building - Chalk Farm Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-------------------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 8827 | ACTIVE | N | N047-00-1/011 | Ticket Office - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17487 | ACTIVE | N | N047-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 17897 | ACTIVE | N | N047-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Chalk Farm Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 17486 | ACTIVE | N | N047-00-1/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Chalk Farm Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |
| 8828 | ACTIVE | N | N047-00-1/021 | POM - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17488 | INACTIVE | N | N047-00-1/021/FLR-01 80898673 | Floor - 1 - POM - Station Building - Chalk Farm Stn Floor | Void | Asbestos | Surveyed – Not Detected | | | | Beneath Computer Flooring | | | | | YES |
| 8829 | ACTIVE | N | N047-00-1/031 | Mess Room - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17490 | ACTIVE | N | N047-00-1/031 | Mess Room - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 18006 | ACTIVE | N | N047-00-1/031 | Mess Room - Station Building - Chalk Farm Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | White Foam Backing | | | | | |
| 17489 | ACTIVE | N | N047-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18998 | ACTIVE | N | N047-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Chalk Farm Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 8830 | ACTIVE | N | N047-00-1/036 | Toilet: Unisex - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17491 | ACTIVE | N | N047-00-1/036 | Toilet: Unisex - Station Building - Chalk Farm Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8831 | ACTIVE | N | N047-00-1/071 | Circulation Area - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17898 | ACTIVE | N | N047-00-1/071 | Circulation Area - Station Building - Chalk Farm Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Bulkhead to Lift | | | | | |
| 42957 | ACTIVE | N | N047-00-1/136 | Lift Shaft - Station Building - Chalk Farm Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | Durasteel panel, 2m2, to top of shaft above entrance of Lift 2 | | | R521101 | N | N |



Hazardous Material Asset Register - Summary



N047-00 - Station Building - Chalk Farm Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------|--|------------------------|---------------|------------------------|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 17494 | ACTIVE | N | N047-00-1/136 | Lift Shaft - Station Building - Chalk Farm Stn | Cable: Wrap | Asbestos | Known | | | | 9x Woven cables 25m long running from machine chamber to bottom of lift No access into lift shafts during 2023 re-inspection in traffic hours. | | | | | |
| 42962 | ACTIVE | N | N047-00-1/136 | Lift Shaft - Station Building - Chalk Farm Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | Durasteel panel, <2m2, to top of shaft above exit of Lift 1 | | | R521101 | N | N |
| 44916 | ACTIVE | N | N047-00-1/136 | Lift Shaft - Station Building - Chalk Farm Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 7x woven sheath cable running from LMR down shaft connecting to bottom of car in lift shaft 1 No access into lift shafts during 2023 re-inspection in traffic hours. | | 7 | | N | N |
| 17492 | ACTIVE | N | N047-00-1/136 | Lift Shaft - Station Building - Chalk Farm Stn | Caulking | Asbestos | Presumed | | | | Tunnel ring caulking unable to access from lift shaft No access into lift shafts during 2023 re-inspection in traffic hours. | | | | | |
| 42958 | ACTIVE | N | N047-00-1/136 | Lift Shaft - Station Building - Chalk Farm Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | Durasteel panel, 2m2, to top of shaft above exit of Lift 2 | | | R521101 | N | N |
| 42960 | ACTIVE | N | N047-00-1/136 | Lift Shaft - Station Building - Chalk Farm Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | Durasteel panel, 2m2, to bottom of shaft to side of entrance of Lift 2 | | | R521101 | N | N |
| 42961 | ACTIVE | N | N047-00-1/136 | Lift Shaft - Station Building - Chalk Farm Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | Durasteel panel, 2m2, to bottom of shaft to side of exit of Lift 2 | | | R521101 | N | N |
| 42963 | ACTIVE | N | N047-00-1/136 | Lift Shaft - Station Building - Chalk Farm Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | Grout/ hessian, throughout, to caulking within shaft in tunnel ring of Lift 1 | | | R521101 | N | N |
| 42964 | ACTIVE | N | N047-00-1/136 | Lift Shaft - Station Building - Chalk Farm Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | Durasteel panel, 2m2, to top of shaft above entrance of Lift 1 | | | R521101 | N | N |
| 42959 | ACTIVE | N | N047-00-1/136 | Lift Shaft - Station Building - Chalk Farm Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | Durasteel panel, <2m2, to top of shaft to side of exit of Lift 2 | | | R521101 | N | N |
| 44920 | INACTIVE | N | N047-00-1/136 | Lift Shaft - Station Building - Chalk Farm Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Circuit breaker 1 and 2 to wall No access into lift shafts during 2020 re-inspection in traffic hours. | | 2 | | N | N |
| 17493 | ACTIVE | N | N047-00-1/137 | Lift Shaft - Station Building - Chalk Farm Stn | Caulking | Asbestos | Presumed | | | | Tunnel ring caulking unable to access from lift shaft No access into lift shafts during 2023 re-inspection in traffic hours. | | | | | |
| 18999 | ACTIVE | N | N047-00-1/137 | Lift Shaft - Station Building - Chalk Farm Stn | Cable: Wrap | Asbestos | Known | | | | 9x Woven cables 25m long running from machine chamber to bottom of lift No access into lift shafts during 2023 re-inspection in traffic hours. | | | | | |
| 44918 | ACTIVE | N | N047-00-1/137 | Lift Shaft - Station Building - Chalk Farm Stn | | Asbestos | Strongly Presumed | | | | Redundant cable on landing half way down shaft in lift shaft 2 No access into lift shafts during 2023 re-inspection in traffic hours. | | | | N | N |



Hazardous Material Asset Register - Summary



N047-00 - Station Building - Chalk Farm Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 44917 | ACTIVE | N | N047-00-1/137 | Lift Shaft - Station Building - Chalk Farm Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 6x woven sheath cable running from LMR down shaft connecting to bottom of car in lift shaft 2 No access into lift shafts during 2023 re-inspection in traffic hours. | | 6 | | N | N |
| 8832 | ACTIVE | N | N047-00-1/236 | Lobby - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17899 | ACTIVE | N | N047-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Chalk Farm Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 18497 | ACTIVE | N | N047-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux tiles - Screwed in | | | | | |
| 17495 | ACTIVE | N | N047-00-1/236/FLR-01 | Floor - 1 - Lobby - Station Building - Chalk Farm Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |
| 8833 | ACTIVE | N | N047-00-1/237 | Passage - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17496 | ACTIVE | N | N047-00-1/237 | Passage - Station Building - Chalk Farm Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8834 | ACTIVE | N | N047-00-1/238 | Lobby - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17497 | ACTIVE | N | N047-00-1/238 | Lobby - Station Building - Chalk Farm Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8835 | ACTIVE | N | N047-00-1/331 | Mess Room - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17498 | ACTIVE | N | N047-00-1/331 | Mess Room - Station Building - Chalk Farm Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | White Foam Backing | | | | | |
| 17499 | ACTIVE | N | N047-00-1/331 | Mess Room - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Panels & Boxing Supalux | | | | | |
| 17900 | ACTIVE | N | N047-00-1/331/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Chalk Farm Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 8836 | ACTIVE | N | N047-00-1/371 | Store - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17500 | ACTIVE | N | N047-00-1/371 | Store - Station Building - Chalk Farm Stn | No Access | Asbestos | Presumed | | | | Room accessed in 2023. No visible ACMS, however no access behind supalux cladding | | | | | |
| 67616 | ACTIVE | N | N047-00-1/371 | Store - Station Building - Chalk Farm Stn | Lead/Leading | Lead Paint/Lead | Presumed | | | | Presumed lead paint to steel girder. Flaky paint to ceiling | | | | | |



Hazardous Material Asset Register - Summary



N047-00 - Station Building - Chalk Farm Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 8837 | ACTIVE | N | N047-00-1/401 | Bin Store - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17501 | ACTIVE | N | N047-00-1/401 | Bin Store - Station Building - Chalk Farm Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8838 | ACTIVE | N | N047-00-1/411 | Lobby - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17502 | ACTIVE | N | N047-00-1/411/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux tiles | | | | | |
| 17503 | ACTIVE | N | N047-00-1/411/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Chalk Farm Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 8839 | ACTIVE | N | N047-00-1/416 | Toilet - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8840 | ACTIVE | N | N047-00-1/417 | Toilet - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8841 | ACTIVE | N | N047-00-1/426 | Tenancy - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17504 | ACTIVE | N | N047-00-1/426/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - Chalk Farm Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Grills | | | | YES | |
| 8842 | ACTIVE | N | N047-00-1/631 | Stairs: Spiral - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17505 | ACTIVE | N | N047-00-1/631 | Stairs: Spiral - Station Building - Chalk Farm Stn | Pipe Lagging | Asbestos | Not Found during Inspection | | | | Lagging Fibre Glass | | | | | |
| 44352 | ACTIVE | N | N047-00-1/631 | Stairs: Spiral - Station Building - Chalk Farm Stn | Gasket :Pipework | Asbestos | Presumed | | | | Pipe gaskets to ceiling above stairs Presumed gasket - encapsulated medium density | | 1 | | N | N |
| 17901 | ACTIVE | N | N047-00-1/631/FLR-01 | Floor - 1 - Spiral Stairs - Station Building - Chalk Farm Stn | Void | Asbestos | Surveyed – Not Detected | | | | Beneath Stairs - Metal | | | | | YES |
| 8843 | ACTIVE | N | N047-00-1/661 | Switch Room - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17507 | ACTIVE | N | N047-00-1/661/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Chalk Farm Stn | Void | Asbestos | No Access: Presumed | | | | Above False Ceiling | | | | YES | |



Hazardous Material Asset Register - Summary



N047-00 - Station Building - Chalk Farm Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|--------------------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17506 | ACTIVE | N | N047-00-1/661/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux tiles - Screwed in | | | | | |
| 18007 | ACTIVE | N | N047-00-1/661/WAL-002 80898811 | Wall: Internal - 2 - Switch Room - Station Building - Chalk Farm Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 3 x Grey Switch Boxes - Flash Guards & Blocks within. 1 x 100 amp, 2 x 60 amps; Rope Seals Non - Asbestos. Plus three other grey switch boxes - 1x100 amp, 1 x 160 amp, 1x 200 amp No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 6 | | N | N |
| 17508 | ACTIVE | N | N047-00-1/661/WAL-002 80898811 | Wall: Internal - 2 - Switch Room - Station Building - Chalk Farm Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box(es) No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 8844 | ACTIVE | N | N047-00-1/662 | Switch Room - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19000 | ACTIVE | N | N047-00-1/662 | Switch Room - Station Building - Chalk Farm Stn | Cable Duct: Other | Asbestos | Presumed | | | | Cement Cable Ducts | | | | N | |
| 44915 | ACTIVE | N | N047-00-1/662 | Switch Room - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Presumed | | | | Superlux panel to ceiling | | | | N | N |
| 17513 | ACTIVE | N | N047-00-1/662 | Switch Room - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |
| 17509 | ACTIVE | N | N047-00-1/662/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux tiles - Screwed in | | | | | |
| 17510 | ACTIVE | N | N047-00-1/662/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Chalk Farm Stn | Void | Asbestos | No Access: Presumed | | | | Above False Ceiling | | | | YES | |
| 17511 | ACTIVE | N | N047-00-1/662/WAL-001 80898819 | Wall: Internal - 1 - Switch Room - Station Building - Chalk Farm Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | 1 x Transformer Box No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 17512 | ACTIVE | N | N047-00-1/662/WAL-002 80898820 | Wall: Internal - 2 - Switch Room - Station Building - Chalk Farm Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | 1 x Transformer Box No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 17966 | ACTIVE | N | N047-00-1/662/WAL-002 80898820 | Wall: Internal - 2 - Switch Room - Station Building - Chalk Farm Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | W2 6 x Switch Boxes - Flash Guards & Blocks within 5 x 60 amp, 1 x 100 amp. Plus three square grey switch boxes: 1 x 160 amp and 2x100 amp. No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 6 | | N | N |



Hazardous Material Asset Register - Summary



N047-00 - Station Building - Chalk Farm Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|--------------------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17967 | ACTIVE | N | N047-00-1/662/WAL-003 80898821 | Wall: Internal - 3 - Switch Room - Station Building - Chalk Farm Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | 3 x Transformer Boxes No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 25736 | ACTIVE | N | N047-00-1/662/WAL-003 80898821 | Wall: Internal - 3 - Switch Room - Station Building - Chalk Farm Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 1x Switch box No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 8845 | ACTIVE | N | N047-00-1/663 | Switch Cupboard - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17514 | ACTIVE | N | N047-00-1/663/WAL-002 80898827 | Wall: Internal - 2 - Switch Cupboard - Station Building - Chalk Farm Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes - Insulation within 4 x 60 amp, 1 x 100 amps, 1 x 30 amps. Plus two square grey switch boxes: 1x63amp and 1x200amp. No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 8 | | N | N |
| 8846 | ACTIVE | N | N047-00-1/664 | Switch Cupboard - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17515 | ACTIVE | N | N047-00-1/664 | Switch Cupboard - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |
| 8847 | ACTIVE | N | N047-00-1/665 | Switch Cupboard - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17516 | ACTIVE | N | N047-00-1/665 | Switch Cupboard - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |
| 8848 | ACTIVE | N | N047-00-1/746 | SCR - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17968 | ACTIVE | N | N047-00-1/746/CLG-01 | Ceiling: Solid - 1 - SCR - Station Building - Chalk Farm Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 17517 | ACTIVE | N | N047-00-1/746/CLG-01 | Ceiling: Solid - 1 - SCR - Station Building - Chalk Farm Stn | Void | Asbestos | Surveyed – Not Detected | | | | Premises inspection shows ceiling is solid. Possible plasterboard ceiling has been removed | | | | YES | |
| 8849 | ACTIVE | N | N047-00-1/951 | Tenancy - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8850 | ACTIVE | N | N047-00-1/952 | Disused Room - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8851 | ACTIVE | N | N047-00-1/953 | Station Control Room - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17321 | ACTIVE | N | N047-00-1/953 | Station Control Room - Station Building - Chalk Farm Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | White Foam Backing | | | | | |



Hazardous Material Asset Register - Summary



N047-00 - Station Building - Chalk Farm Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-------------------------------|---|------------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18993 | ACTIVE | N | N047-00-1/953/CLG-01 | Ceiling: Suspended - 1 - Station Control Room - Station Building - Chalk Farm Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 17320 | ACTIVE | N | N047-00-1/953/CLG-01 | Ceiling: Suspended - 1 - Station Control Room - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 19030 | ACTIVE | N | N047-00-1/953/FLR-01 | Floor - 1 - Station Control Room - Station Building - Chalk Farm Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Vinyl | | | | | |
| 17319 | ACTIVE | N | N047-00-1/953/FLR-01 80898889 | Floor - 1 - Station Control Room - Station Building - Chalk Farm Stn Floor | Void | Asbestos | No Access: Presumed | | | | Vinyl floor on solid | | | | | YES |
| 8852 | ACTIVE | N | N047-00-1/971 | LMR - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44914 | ACTIVE | N | N047-00-1/971 | LMR - Station Building - Chalk Farm Stn | Other Electrical Boxes | Asbestos | Removed | | | | <1m² Old Circuit breaker unable Not observed this visit No access into LMR during 2020 re-inspection. Permit with L&E required. | | | | N | N |
| 17326 | ACTIVE | N | N047-00-1/971 | LMR - Station Building - Chalk Farm Stn | Cable: Sheath | Asbestos | Removed | | | | Woven Cables 3m long - coming from switch for isolating heating fan in car, and going down to lift shaft No access into LMR during 2020 re-inspection. Permit with L&E required. | | 9 | | | |
| 17327 | ACTIVE | N | N047-00-1/971 | LMR - Station Building - Chalk Farm Stn | Lead/Leading | Lead Paint/Lead | Strongly Presumed | | | | Girder RHS | | | | N | N |
| 19032 | ACTIVE | N | N047-00-1/971/FLR-01 80898914 | Floor - 1 - LMR - Station Building - Chalk Farm Stn Floor | Cable Duct: Other | Asbestos | Surveyed – Not Detected | | | | Surveyed, plastic ducts | | | | | |
| 19031 | ACTIVE | N | N047-00-1/971/WAL-001 | Wall: Internal - 1 - LMR - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux, 10m² Supalux lower level of room on walls 1,2&4 above door NADIS | | | | | |
| 17322 | ACTIVE | N | N047-00-1/971/WAL-002 | Wall: Internal - 2 - LMR - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux, 10m² Supalux lower level of room on walls 1,2&4 above door NADIS | | | | | |
| 17323 | ACTIVE | N | N047-00-1/971/WAL-003 | Wall: Internal - 3 - LMR - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux, 10m² Supalux lower level of room on walls 1,2&4 above door NADIS | | | | | |
| 17324 | ACTIVE | N | N047-00-1/971/WAL-004 | Wall: Internal - 4 - LMR - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux, 10m² Supalux lower level of room on walls 1,2&4 above door NADIS | | | | | |
| 8853 | ACTIVE | N | N047-00-2/201 | Passage - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N047-00 - Station Building - Chalk Farm Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17328 | ACTIVE | N | N047-00-2/201 | Passage - Station Building - Chalk Farm Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Boarding above Lift Doors | | | | | |
| 8854 | ACTIVE | N | N047-00-2/202 | Passage - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17329 | ACTIVE | N | N047-00-2/202 | Passage - Station Building - Chalk Farm Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Boarding above Lift Doors | | | | | |
| 8855 | ACTIVE | N | N047-00-2/411 | Switch Room - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17989 | ACTIVE | N | N047-00-2/411 | Switch Room - Station Building - Chalk Farm Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8856 | ACTIVE | N | N047-00-2/601 | Stairs: Linear - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8857 | ACTIVE | N | N047-00-2/602 | Stairs: Linear - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8858 | ACTIVE | N | N047-00-2/771 | Plant Room - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44353 | ACTIVE | N | N047-00-2/771 | Plant Room - Station Building - Chalk Farm Stn | Caulking | Asbestos | Presumed | | | | Tunnel ring caulking Sealed tunnel ring caulking (sealed with grout) - treated highly friable material. | | | | N | N |
| 25737 | ACTIVE | N | N047-00-2/771/ WAL-003 80899049 | Wall: Internal - 3 - Plant Room - Station Building - Chalk Farm Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | Large Electrical cabinet No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 25645 | ACTIVE | N | N047-00-2/771/ WAL-005 80960986 | Wall: Internal - 5 - Plant Room - Station Building - Chalk Farm Stn Wall: Internal | Other Electrical Boxes | Asbestos | Surveyed – Not Detected | | | | Post 2000 signalling circuits NL Upgrade | | 1 | | N | N |
| 17330 | ACTIVE | N | N047-00-2/771/ WAL-005 80960986 | Wall: Internal - 5 - Plant Room - Station Building - Chalk Farm Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 x 60amp Switch Box - Insulation within No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 25646 | ACTIVE | N | N047-00-2/771/ WAL-006 80960987 | Wall: Internal - 6 - Plant Room - Station Building - Chalk Farm Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | 1 x Transformer Box No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 8859 | ACTIVE | N | N047-00-2/773 | CER - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19033 | ACTIVE | N | N047-00-2/773/ FLR-01 | Floor - 1 - CER - Station Building - Chalk Farm Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete/ Conduits beneath Computer Tiles | | | | | |



Hazardous Material Asset Register - Summary



N047-00 - Station Building - Chalk Farm Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|--------------------------------|--|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 17332 | ACTIVE | N | N047-00-2/773/WAL-001 80899054 | Wall: Internal - 1 - CER - Station Building - Chalk Farm Stn Wall: Internal | Other Boarding | Asbestos | Presumed | | | | Paxoline Board | | | | N | N |
| 17333 | ACTIVE | N | N047-00-2/773/WAL-003 | Wall: Internal - 3 - CER - Station Building - Chalk Farm Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Paxoline Board - Non asbestos. Connect equipment installed post 200 | | 1 | | N | N |
| 17331 | ACTIVE | N | N047-00-2/773/WAL-007 80899060 | Wall: Internal - 7 - CER - Station Building - Chalk Farm Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 2 x 60 amp Switch Boxes No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 2 | | N | N |
| 8860 | ACTIVE | N | N047-00-3/201 | Passage - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17334 | ACTIVE | N | N047-00-3/201 | Passage - Station Building - Chalk Farm Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8861 | ACTIVE | N | N047-00-3/202 | Passage - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17335 | ACTIVE | N | N047-00-3/202 | Passage - Station Building - Chalk Farm Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8862 | ACTIVE | N | N047-00-3/203 | Passage - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17990 | ACTIVE | N | N047-00-3/203 | Passage - Station Building - Chalk Farm Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8863 | ACTIVE | N | N047-00-3/261 | Platform 1 - Northbound Local - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70935 | ACTIVE | N | N047-00-3/261 | Platform 1 - Northbound Local - Station Building - Chalk Farm Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R731053 | | |
| 70941 | ACTIVE | N | N047-00-3/261 | Platform 1 - Northbound Local - Station Building - Chalk Farm Stn | Gasket :Pipework | Asbestos | Presumed | | | | Platform Invert - Gaskets - throughout - To flange of metal pipework | | | R731053 | N | Y |
| 70939 | ACTIVE | N | N047-00-3/261 | Platform 1 - Northbound Local - Station Building - Chalk Farm Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 4 no - To ceiling - arrival end | | 4 | R731053 | N | Y |
| 70934 | ACTIVE | N | N047-00-3/261 | Platform 1 - Northbound Local - Station Building - Chalk Farm Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R731053 | | |
| 70944 | ACTIVE | N | N047-00-3/261 | Platform 1 - Northbound Local - Station Building - Chalk Farm Stn | Debris: Other | Asbestos | Sampled – Not Detected | | | | Platform Invert - MMMF insulation - loose - Throughout | | | R731053 | N | Y |
| 70942 | ACTIVE | N | N047-00-3/261 | Platform 1 - Northbound Local - Station Building - Chalk Farm Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | Platform Invert - Bitumen cable ducts - total 1 no - With loose concrete block to floor - departure end | | 1 | R731053 | N | Y |



Hazardous Material Asset Register - Summary



N047-00 - Station Building - Chalk Farm Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 70940 | ACTIVE | N | N047-00-3/261 | Platform 1 - Northbound Local - Station Building - Chalk Farm Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Small westinghouse - total 1 no - To platform wall - midway | | 1 | R731053 | | |
| 70938 | ACTIVE | N | N047-00-3/261 | Platform 1 - Northbound Local - Station Building - Chalk Farm Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 2 no - To trackside wall - arrival end | | 2 | R731053 | N | Y |
| 70937 | ACTIVE | N | N047-00-3/261 | Platform 1 - Northbound Local - Station Building - Chalk Farm Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 2 no - To trackside wall - arrival end | | 2 | R731053 | N | Y |
| 70936 | ACTIVE | N | N047-00-3/261 | Platform 1 - Northbound Local - Station Building - Chalk Farm Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - throughout (+10)- To J Hanger | | 10 | R731053 | | |
| 17336 | ACTIVE | N | N047-00-3/261 | Platform 1 - Northbound Local - Station Building - Chalk Farm Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Various Cables | | | | | |
| 70943 | ACTIVE | N | N047-00-3/261 | Platform 1 - Northbound Local - Station Building - Chalk Farm Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 4 - To trackside wall departure end | | 4 | R731053 | N | Y |
| 44913 | ACTIVE | N | N047-00-3/261 | Platform 1 - Northbound Local - Station Building - Chalk Farm Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables 1x10mm & 1x30mm: Running full length of invert No access into platform inverts during 2023 re-inspection. Confined space. | | | | N | N |
| 17340 | ACTIVE | N | N047-00-3/261/ FLR-01 | Floor - 1 - Platform 1 - Station Building - Chalk Farm Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 1 Invert - Badly encapsulated Cables by 3/731; Cables exit and enter invert by ladder Platform side by 3/731 No access into platform inverts during 2023 re-inspection. Confined space. | | | | | YES |
| 17337 | ACTIVE | N | N047-00-3/261/ FLR-01 | Floor - 1 - Platform 1 - Station Building - Chalk Farm Stn | Cable: Sheath | Asbestos | Room: Surveyed: Asbestos Strongly Presumed | | | | Platform 1 Invert - Cables 1x10mm & 1x30mm: Running full length of invert | | | | | YES |
| 17338 | ACTIVE | N | N047-00-3/261/ FLR-01 | Floor - 1 - Platform 1 - Station Building - Chalk Farm Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 1 Invert - Cables 3x5mm: Runs across invert from pit wall to back wall, middle of invert No access into platform inverts during 2023 re-inspection. Confined space. | | | | | YES |
| 17664 | ACTIVE | N | N047-00-3/261/ FLR-01 | Floor - 1 - Platform 1 - Station Building - Chalk Farm Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Various Cables running middle of invert No access into platform inverts during 2023 re-inspection. Confined space. | | | | | YES |



Hazardous Material Asset Register - Summary



N047-00 - Station Building - Chalk Farm Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 17665 | ACTIVE | N | N047-00-3/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Chalk Farm Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 1 Invert - 4 x Cables (1 x White Encapsulated, 1 x Green, 2 x Orange (1 Green? - Both Encapsulated) & 2 x Asbestos Cables Encapsulated wrapped around lying on Floor by 3/731. All encapsulated except Green Cable No access into platform inverts during 2023 re-inspection. Confined space. | | | | | YES |
| 19541 | ACTIVE | N | N047-00-3/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Chalk Farm Stn | Cable: Sheath | Asbestos | Not Found during Inspection | | | | White Cable not Encapsulated from other end 3/731 (South End) | | | | | YES |
| 17339 | ACTIVE | N | N047-00-3/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Chalk Farm Stn | Cable Duct: Other | Asbestos | Strongly Presumed | | | | Platform 1 Invert - 4 x Cable Sleeves Far end of Invert No access into platform inverts during 2023 re-inspection. Confined space. | | | | | YES |
| 19034 | ACTIVE | N | N047-00-3/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Chalk Farm Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 1 Invert - Cables 1x20mm: on J-hangers from ceiling wall side No access into platform inverts during 2023 re-inspection. Confined space. | | | | | YES |
| 8864 | ACTIVE | N | N047-00-3/262 | Platform 2 - Southbound Local - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70932 | ACTIVE | N | N047-00-3/262 | Platform 2 - Southbound Local - Station Building - Chalk Farm Stn | Debris: Other | Asbestos | Sampled – Not Detected | | | | Platform Invert - MMMF loose - Throughout | | | R731053 | N | Y |
| 70928 | ACTIVE | N | N047-00-3/262 | Platform 2 - Southbound Local - Station Building - Chalk Farm Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R731053 | | |
| 70930 | ACTIVE | N | N047-00-3/262 | Platform 2 - Southbound Local - Station Building - Chalk Farm Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - throughout - To J Hangers | | | R731053 | | |
| 70931 | ACTIVE | N | N047-00-3/262 | Platform 2 - Southbound Local - Station Building - Chalk Farm Stn | Gasket :Pipework | Asbestos | Presumed | | | | Platform Invert - Gasket - throughout - To flange of pipework - not possible to sample | | | R731053 | N | Y |
| 70933 | ACTIVE | N | N047-00-3/262 | Platform 2 - Southbound Local - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Platform Invert - Supalux panels - throughout - To ceiling | | | R731053 | N | Y |
| 17666 | ACTIVE | N | N047-00-3/262 | Platform 2 - Southbound Local - Station Building - Chalk Farm Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Various Cables - Tail Wall | | | | N | N |
| 70929 | ACTIVE | N | N047-00-3/262 | Platform 2 - Southbound Local - Station Building - Chalk Farm Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R731053 | | |



Hazardous Material Asset Register - Summary



N047-00 - Station Building - Chalk Farm Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|--------------------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 17667 | ACTIVE | N | N047-00-3/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Chalk Farm Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 2 Invert - 3 x Cables 20mm white all run length of invert middle j hangers then cross over from j hanger to entrance to track by ladder No access into platform inverts during 2023 re-inspection. Confined space. | | | | | YES |
| 18132 | ACTIVE | N | N047-00-3/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Chalk Farm Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 2 Invert - 3 x Cables exiting by Track by 2/602 No access into platform inverts during 2023 re-inspection. Confined space. | | | | | YES |
| 17668 | ACTIVE | N | N047-00-3/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Chalk Farm Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 2 Invert - 8 x Cables (3 white, 2 green, 1 brown) & 2 x yellow cables by Entrance/ Exit other end from 2/602 No access into platform inverts during 2023 re-inspection. Confined space. | | | | | YES |
| 8865 | ACTIVE | N | N047-00-3/312 | Switch Room - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8866 | ACTIVE | N | N047-00-3/381 | Switch Cupboard - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17669 | ACTIVE | N | N047-00-3/381 | Switch Cupboard - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 8867 | ACTIVE | N | N047-00-3/661 | Switch Room - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17671 | ACTIVE | N | N047-00-3/661/FLR-01 | Floor - 1 - Switch Room - Station Building - Chalk Farm Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Trap Door | | | | | |
| 18081 | ACTIVE | N | N047-00-3/661/WAL-001 80899086 | Wall: Internal - 1 - Switch Room - Station Building - Chalk Farm Stn Wall: Internal | Other Boarding | Asbestos | Presumed | | | | Transformer Box No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 17670 | ACTIVE | N | N047-00-3/661/WAL-002 80899087 | Wall: Internal - 2 - Switch Room - Station Building - Chalk Farm Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 3 x Switch Boxes - 2 x 100amp, 1 x 100amp. Plus 3x square grey switchboxes: 1x 160amp, 1x 100 amp, 1x 63 amp. No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 3 | | N | N |
| 25647 | ACTIVE | N | N047-00-3/661/WAL-003 80899088 | Wall: Internal - 3 - Switch Room - Station Building - Chalk Farm Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Box 1 x 60amp No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |



Hazardous Material Asset Register - Summary



N047-00 - Station Building - Chalk Farm Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|--------------------------------|--|------------------------|--------------------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 44359 | ACTIVE | N | N047-00-3/661/WAL-003 80899088 | Wall: Internal - 3 - Switch Room - Station Building - Chalk Farm Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer box No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 8868 | ACTIVE | N | N047-00-3/662 | Switch Room - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18563 | ACTIVE | N | N047-00-3/662 | Switch Room - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 67617 | ACTIVE | N | N047-00-3/662 | Switch Room - Station Building - Chalk Farm Stn | Cable Ducts: Bitumen | Asbestos | Presumed | | | | Presumed asbestos ducts, fire stopped - unable to sample | | 3 | | | |
| 18133 | ACTIVE | N | N047-00-3/662/WAL-002 80899094 | Wall: Internal - 2 - Switch Room - Station Building - Chalk Farm Stn Wall: Internal | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | 3 x Electrical Incomer Boxes No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 3 | | N | N |
| 8869 | ACTIVE | N | N047-00-3/663 | Switch Room - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17672 | ACTIVE | N | N047-00-3/663 | Switch Room - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 8870 | ACTIVE | N | N047-00-3/711 | Relay Room - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17674 | ACTIVE | N | N047-00-3/711 | Relay Room - Station Building - Chalk Farm Stn | Cable: Sheath | Asbestos | Removed | | | | 2 x Green Cables 50mm to wall 2 back of room going into 600v box (re-inspected 18.05.22 AW VC) | | 2 | | N | N |
| 17673 | ACTIVE | N | N047-00-3/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 46814 | ACTIVE | N | N047-00-3/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Chalk Farm Stn | Other Boarding | Asbestos | Removed | | | | Paxoline board to equipment in roller shutter 2 - 8x to front 8x underneath support. | | | | | |
| 46813 | ACTIVE | N | N047-00-3/711/WAL-001 80899111 | Wall: Internal - 1 - Relay Room - Station Building - Chalk Farm Stn Wall: Internal | Cable Duct: Other | Asbestos | Presumed | | | | 2 Ducts to floor underneath cable tray - presumed | | | | | |
| 25656 | INACTIVE | N | N047-00-3/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Chalk Farm Stn | PCBs | Asbestos | Strongly Presumed | | | | 8 x PCB's located within roller shutter cabinet. Fair condition - serial numbers not visible. | | 8 | | N | N |
| 42326 | INACTIVE | N | N047-00-3/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Chalk Farm Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | 8 x PCB's - Fair condition, located within roller shutter cabinet In Twice see 25656 | | 8 | | N | N |
| 25657 | ACTIVE | N | N047-00-3/711/WAL-004 | Wall: Internal - 4 - Relay Room - Station Building - Chalk Farm Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Other Boarding | | | | | |



Hazardous Material Asset Register - Summary



N047-00 - Station Building - Chalk Farm Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------------------|---|------------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 25658 | ACTIVE | N | N047-00-3/711/WAL-004 | Wall: Internal - 4 - Relay Room - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Door Frame - Supalux boarding | | | | | |
| 44912 | ACTIVE | N | N047-00-3/712 | Switch Room - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux panels to the walls and to ducts to inverts | | | | N | N |
| 25739 | ACTIVE | N | N047-00-3/712 | Switch Room - Station Building - Chalk Farm Stn | Cable: Sheath | Asbestos | Removed | | | | Approx 4x Braided Cables within Roller shutter Cabinet | | 4 | | N | N |
| 18134 | ACTIVE | N | N047-00-3/712 | Switch Room - Station Building - Chalk Farm Stn | Cable: Sheath | Asbestos | Removed | | | | Cables 50mm going Into Invert | | 2 | | N | N |
| 17676 | ACTIVE | N | N047-00-3/712 80143094 | Switch Room - Station Building - Chalk Farm Stn Room Assets | Cable Duct: Other | Asbestos | Strongly Presumed | | | | Ducts into Invert Ducts not visible beneath filling therefore material not scored in 2023 re-inspection. | | | | N | N |
| 17677 | ACTIVE | N | N047-00-3/712 | Switch Room - Station Building - Chalk Farm Stn | Other Boarding | Asbestos | Removed | | | | Paxoline Board Wall 3 | | 1 | | N | N |
| 17675 | ACTIVE | N | N047-00-3/712 | Switch Room - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux; Supalux Panelling | | | | | |
| 25738 | INACTIVE | N | N047-00-3/712 | Switch Room - Station Building - Chalk Farm Stn | PCBs | Polychlorinated biphenyl | Presumed | | | | Approx 8 x PCB's within Roller shutter cabinet - Wall 2 | | 8 | | N | N |
| 46815 | ACTIVE | N | N047-00-3/712/WAL-001 100007017 | Wall: Internal - 1 - Switch Room - Station Building - Chalk Farm Stn Wall: Internal | Cable Duct: Other | Asbestos | Presumed | | | | 2 x cable ducts to floor. Equipment cabinet and redundant cables removed | | | | | |
| 46816 | ACTIVE | N | N047-00-3/712/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Chalk Farm Stn | Other Boarding | Asbestos | Removed | | | | Paxoline board to equipment in rack x8 to front x8 to underneath | | | | | |
| 8871 | ACTIVE | N | N047-00-3/731 | CER - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17678 | ACTIVE | N | N047-00-3/731 | CER - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panelling | | | | | |
| 44358 | ACTIVE | N | N047-00-3/731/WAL-002 80899129 | Wall: Internal - 2 - CER - Station Building - Chalk Farm Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | 3 x electrical boxes: 1x black box and 2x green cylindrical No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 3 | | N | N |
| 8872 | ACTIVE | N | N047-00-3/762 | Service Riser - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44357 | ACTIVE | N | N047-00-3/762 | Service Riser - Station Building - Chalk Farm Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Electrical box at high level No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 44355 | ACTIVE | N | N047-00-3/762 | Service Riser - Station Building - Chalk Farm Stn | Other Boarding | Asbestos | Presumed | | | | Cement panel | | 1 | | N | N |



Hazardous Material Asset Register - Summary



N047-00 - Station Building - Chalk Farm Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|------------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17679 | ACTIVE | N | N047-00-3/762 | Service Riser - Station Building - Chalk Farm Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables 50mm | | 2 | | N | N |
| 44354 | ACTIVE | N | N047-00-3/762 | Service Riser - Station Building - Chalk Farm Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Westinghouse box No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 44356 | ACTIVE | N | N047-00-3/762 | Service Riser - Station Building - Chalk Farm Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline boarding | | 1 | | N | N |
| 8873 | ACTIVE | N | N047-00-A/047 | Shower Room - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 46444 | ACTIVE | N | N047-00-A/047 | Shower Room - Station Building - Chalk Farm Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | White gloss paint applied to the window, LHS - Thickness: 0.43mm Analysis: 0.15% | | | R674026 | N | N |
| 46442 | ACTIVE | N | N047-00-A/047 | Shower Room - Station Building - Chalk Farm Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | White gloss paint applied to the radiator, LHS - Thickness: 0.3mm Analysis: 0.01% | | | R674026 | N | N |
| 46443 | ACTIVE | N | N047-00-A/047 | Shower Room - Station Building - Chalk Farm Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | White gloss paint applied to the window, RHS - Thickness: 0.71mm Analysis: 0.09% | | | R674026 | N | N |
| 46441 | ACTIVE | N | N047-00-A/047 | Shower Room - Station Building - Chalk Farm Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | White gloss paint applied to the radiator, RHS - Thickness: 0.29mm Analysis: 0.03% | | | R674026 | N | N |
| 18135 | ACTIVE | N | N047-00-A/047/CLG-01 | Ceiling: Suspended - 1 - Shower Room - Station Building - Chalk Farm Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 8874 | ACTIVE | N | N047-00-A/081 | Lobby - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17680 | ACTIVE | N | N047-00-A/081/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Chalk Farm Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 8875 | ACTIVE | N | N047-00-A/131 | LMR - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44087 | ACTIVE | N | N047-00-A/131 | LMR - Station Building - Chalk Farm Stn | | Asbestos | Removed | | | | Paper insulation to door, 0.5m2, within redundant circuit breaker No2 in Lift Motor Room A/131 at Chalk Farm Station. | | | R602326 | N | N |
| 44088 | ACTIVE | N | N047-00-A/131 | LMR - Station Building - Chalk Farm Stn | | Asbestos | Removed | | | | Bakelite panel, 0.5m2, within redundant circuit breaker No2 in Lift Motor Room A/131 at Chalk Farm Station | | | R602326 | N | N |
| 44089 | ACTIVE | N | N047-00-A/131 | LMR - Station Building - Chalk Farm Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | Durasteel panels, 8m2, exit to lift shaft 2 above and to the sides at Ticket Hall level at Chalk Farm Station. | | | R602326 | N | N |
| 44911 | ACTIVE | N | N047-00-A/131 | LMR - Station Building - Chalk Farm Stn | Control Panels | Asbestos | Removed | | | | 1x lift control panel number 1 No access into LMR during 2020 re-inspection. Permit with L&E required. | | 1 | | N | N |



Hazardous Material Asset Register - Summary



N047-00 - Station Building - Chalk Farm Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|------------------------|---------------|------------------------|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 44919 | ACTIVE | N | N047-00-A/131 | LMR - Station Building - Chalk Farm Stn | Control Panels | Asbestos | Presumed | | | | 1x lift control panel number 2 | | 1 | | N | N |
| 44085 | ACTIVE | N | N047-00-A/131 | LMR - Station Building - Chalk Farm Stn | | Asbestos | Removed | | | | Cement panel, 2no 0.25m2, within redundant circuit breaker No2 in Lift Motor Room A/131 at Chalk Farm Station | | | R602326 | N | N |
| 44083 | ACTIVE | N | N047-00-A/131 | LMR - Station Building - Chalk Farm Stn | | Asbestos | Sampled – Not Detected | | | | Woven travelling cable insulation, 16mm diameter, underneath half way box in Lift Motor Room A/131 at Chalk Farm Station (cable runs the full length of the lift shaft). | | | R602326 | N | N |
| 44086 | ACTIVE | N | N047-00-A/131 | LMR - Station Building - Chalk Farm Stn | | Asbestos | Removed | | | | Woven tape to seal, 2m, within redundant circuit breaker No2 in Lift Motor Room A/131 at Chalk Farm Station | | | R602326 | N | N |
| 44084 | ACTIVE | N | N047-00-A/131 | LMR - Station Building - Chalk Farm Stn | | Asbestos | Sampled – Not Detected | | | | Woven travelling cable insulation, 25mm diameter, underneath half way box in Lift Motor Room A/131 at Chalk Farm Station (cable runs the full length of the lift shaft). | | | R602326 | N | N |
| 44082 | ACTIVE | N | N047-00-A/131 | LMR - Station Building - Chalk Farm Stn | | Asbestos | Sampled – Not Detected | | | | Woven travelling cable insulation, 6mm diameter, underneath half way box in Lift Motor Room A/131 at Chalk Farm Station (cable runs the full length of the lift shaft). | | | R602326 | N | N |
| 17325 | ACTIVE | N | N047-00-A/131 | LMR - Station Building - Chalk Farm Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | 1m² Durasteel storage level, upper level | | | | | |
| 17682 | ACTIVE | N | N047-00-A/131 | LMR - Station Building - Chalk Farm Stn | Control Panels | Asbestos | Removed | | | | Lift Control Panels | | | | | |
| 19491 | ACTIVE | N | N047-00-A/131 | LMR - Station Building - Chalk Farm Stn | Isolator Switches | Asbestos | Removed | | | | 2x Old Circuit breakers & other electrical equipment | | 1 | | | |
| 44906 | ACTIVE | N | N047-00-A/131 | LMR - Station Building - Chalk Farm Stn | Cable: Sheath | Asbestos | Removed | | | | 3x woven cable to isolator for light and heating No access into LMR during 2020 re-inspevtion. Permit with L&E required. | | 3 | | N | N |
| 44905 | ACTIVE | N | N047-00-A/131 | LMR - Station Building - Chalk Farm Stn | Cable: Sheath | Asbestos | Removed | | | | 5x woven cable to isolator for light and heating No access into LMR during 2020 re-inspection. Permit with L&E required. | | 5 | | N | N |
| 19071 | ACTIVE | N | N047-00-A/131/WAL-002 | Wall: Internal - 2 - LMR - Station Building - Chalk Farm Stn | Other Electrical Boxes | Asbestos | Removed | | | | Lift Circuit Breakers (Redundant) | | | | | |
| 17681 | ACTIVE | N | N047-00-A/131/WAL-005 | Wall: Internal - 5 - LMR - Station Building - Chalk Farm Stn | Other Electrical Boxes | Asbestos | Removed | | | | Transformer Box(es) No access into LMR during 2020 re-inspection. Permit with L&E required. | | 1 | | N | N |
| 18082 | ACTIVE | N | N047-00-A/131/WAL-005 | Wall: Internal - 5 - LMR - Station Building - Chalk Farm Stn | Isolator Switches | Asbestos | Removed | | | | Switch Boxes 2 x 60 amp No access into platform inverts during 2020 re-inspection. Confined space. | | 2 | | | |



Hazardous Material Asset Register - Summary



N047-00 - Station Building - Chalk Farm Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 44910 | ACTIVE | N | N047-00-A/131/WAL-006 | Wall: Internal - 6 - LMR - Station Building - Chalk Farm Stn | Other Electrical Boxes | Asbestos | Removed | | | | 1x auto control panel No access into platform inverts during 2020 re-inspection. Confined space. | | 1 | | N | N |
| 44909 | ACTIVE | N | N047-00-A/131/WAL-012 | Wall: Internal - 12 - LMR - Station Building - Chalk Farm Stn | Other Electrical Boxes | Asbestos | Removed | | | | 1x transformer No access into platform inverts during 2020 re-inspection. Confined space. | | 1 | | N | N |
| 44907 | ACTIVE | N | N047-00-A/131/WAL-012 | Wall: Internal - 12 - LMR - Station Building - Chalk Farm Stn | Other Electrical Boxes | Asbestos | Removed | | | | 3x combination fuse switch boxes No access into platform inverts during 2020 re-inspection. Confined space. | | 3 | | N | N |
| 44908 | ACTIVE | N | N047-00-A/131/WAL-012 | Wall: Internal - 12 - LMR - Station Building - Chalk Farm Stn | Other Electrical Boxes | Asbestos | Removed | | | | 3x red spot boxes No access into platform inverts during 2020 re-inspection. Confined space. | | 3 | | N | N |
| 8876 | ACTIVE | N | N047-00-A/236 | Passage - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17683 | ACTIVE | N | N047-00-A/236 | Passage - Station Building - Chalk Farm Stn | Isolator Switches | Asbestos | Removed | | | | Combination Fuse Switch - Insulation within | | 1 | | | |
| 8877 | ACTIVE | N | N047-00-A/237 | Passage - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18136 | ACTIVE | N | N047-00-A/237 | Passage - Station Building - Chalk Farm Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8878 | ACTIVE | N | N047-00-A/238 | Lobby - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17684 | ACTIVE | N | N047-00-A/238 | Lobby - Station Building - Chalk Farm Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8879 | ACTIVE | N | N047-00-A/281 | Store - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17685 | ACTIVE | N | N047-00-A/281 | Store - Station Building - Chalk Farm Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8880 | ACTIVE | N | N047-00-A/331 | Mess Room - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17687 | ACTIVE | N | N047-00-A/331 | Mess Room - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Boiler Box Ceiling - Supalux & Plywood | | | | | |
| 18564 | ACTIVE | N | N047-00-A/331/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Chalk Farm Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Tiles | | | | | |



Hazardous Material Asset Register - Summary



N047-00 - Station Building - Chalk Farm Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18137 | ACTIVE | N | N047-00-A/331/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Chalk Farm Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 17686 | ACTIVE | N | N047-00-A/331/FLR-01 | Floor - 1 - Mess Room - Station Building - Chalk Farm Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Lino | | | | | |
| 8881 | ACTIVE | N | N047-00-A/382 | Store - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17518 | ACTIVE | N | N047-00-A/382 | Store - Station Building - Chalk Farm Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 17525 | ACTIVE | N | N047-00-A/382 | Store - Station Building - Chalk Farm Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8882 | ACTIVE | N | N047-00-A/383 | Locker Room - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19001 | ACTIVE | N | N047-00-A/383/CLG-01 | Ceiling: Solid - 1 - Locker Room - Station Building - Chalk Farm Stn | Void | Asbestos | No Access: Presumed | | | | Above false ceiling | | | | YES | |
| 8883 | ACTIVE | N | N047-00-A/384 | Locker Room - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17969 | ACTIVE | N | N047-00-A/384/CLG-01 | Ceiling: Suspended - 1 - Locker Room - Station Building - Chalk Farm Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs Above false ceiling | | | R679624 | YES | |
| 8884 | ACTIVE | N | N047-00-A/416 | Toilet: Male - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17519 | ACTIVE | N | N047-00-A/416/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Chalk Farm Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 8885 | ACTIVE | N | N047-00-A/417 | SER - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17520 | ACTIVE | N | N047-00-A/417/CLG-01 | Ceiling: Suspended - 1 - SER - Station Building - Chalk Farm Stn | Void | Asbestos | No Access: Presumed | | | | Above Soft Board ceiling | | | | YES | |
| 8886 | ACTIVE | N | N047-00-A/418 | Toilet: Female - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17521 | ACTIVE | N | N047-00-A/418/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Chalk Farm Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |



Hazardous Material Asset Register - Summary



N047-00 - Station Building - Chalk Farm Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 8887 | ACTIVE | N | N047-00-A/567 | Stairs: Linear - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17522 | ACTIVE | N | N047-00-A/567 | Stairs: Linear - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Surveyed – Not Detected | | | | Surveyed = No asbestos detected | | | | | |
| 8888 | ACTIVE | N | N047-00-A/576 | Stairs: Linear - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | R679624 | | |
| 8889 | ACTIVE | N | N047-00-A/578 | Stairs: Linear - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17523 | ACTIVE | N | N047-00-A/578 | Stairs: Linear - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 18008 | ACTIVE | N | N047-00-A/578/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Chalk Farm Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Concrete/ Supalux | | | | | |
| 8890 | ACTIVE | N | N047-00-A/761 | Equipment Room - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8891 | ACTIVE | N | N047-00-A/771 | Disused Room - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17970 | ACTIVE | N | N047-00-A/791 | Vent Shaft - Station Building - Chalk Farm Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8892 | ACTIVE | N | N047-00-A/901 | Disused Room - Station Building - Chalk Farm Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17524 | ACTIVE | N | N047-00-A/901 | Disused Room - Station Building - Chalk Farm Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |

N053-00 - Station Building - Mill Hill East Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-------------------------------|--|-----------------|---------------|--|----------|-----------|-----------------|--------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 8893 | ACTIVE | N | N053-00-1/001 | Booking Hall - Station Building - Mill Hill East Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19733 | ACTIVE | N | N053-00-1/001/FLR-01 80907236 | Floor - 1 - Booking Hall - Station Building - Mill Hill East Stn Floor | Void | Asbestos | No Access: Presumed | | | | Cellar under hatch - no access | | | | | YES |
| 8894 | ACTIVE | N | N053-00-1/011 | Ticket Office - Station Building - Mill Hill East Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N053-00 - Station Building - Mill Hill East Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 20098 | ACTIVE | N | N053-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Mill Hill East Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 19223 | ACTIVE | N | N053-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Mill Hill East Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal Ducting & Pipes above Supalux | | | | YES | |
| 19216 | ACTIVE | N | N053-00-1/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Mill Hill East Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Rubber Tiles | | | | | YES |
| 8895 | ACTIVE | N | N053-00-1/021 | POM - Station Building - Mill Hill East Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20099 | ACTIVE | N | N053-00-1/021/CLG-01 80907055 | Ceiling: Solid - 1 - POM - Station Building - Mill Hill East Stn Ceiling: Solid | Void | Asbestos | No Access: Presumed | | | | Beneath Tiles | | | | YES | YES |
| 8896 | ACTIVE | N | N053-00-1/031 | Mess Room - Station Building - Mill Hill East Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 43431 | ACTIVE | N | N053-00-1/031 | Mess Room - Station Building - Mill Hill East Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux panel, 1m, to cooker divider / panel attached to cooker in Mess Room 1/031 at Mill Hill East Station | 1 | | R562801 | N | N |
| 20100 | ACTIVE | N | N053-00-1/031/FLR-01 | Floor - 1 - Mess Room - Station Building - Mill Hill East Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 19736 | ACTIVE | N | N053-00-1/031/FLR-01 | Floor - 1 - Mess Room - Station Building - Mill Hill East Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | | | | | | |
| 8897 | ACTIVE | N | N053-00-1/036 | Toilet: Unisex - Station Building - Mill Hill East Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19810 | ACTIVE | N | N053-00-1/036/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Mill Hill East Stn | Void | Asbestos | Surveyed – Not Detected | | | | Roof Area; Fibreglass Lagging above Wooden Hatch | | | | YES | |
| 8898 | ACTIVE | N | N053-00-1/071 | Circulation Area - Station Building - Mill Hill East Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20101 | ACTIVE | N | N053-00-1/071 | Circulation Area - Station Building - Mill Hill East Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8899 | ACTIVE | N | N053-00-1/081 | Lobby - Station Building - Mill Hill East Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20102 | ACTIVE | N | N053-00-1/081 | Lobby - Station Building - Mill Hill East Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8900 | ACTIVE | N | N053-00-1/406 | Store - Station Building - Mill Hill East Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N053-00 - Station Building - Mill Hill East Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 20103 | ACTIVE | N | N053-00-1/406 | Store - Station Building - Mill Hill East Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8901 | ACTIVE | N | N053-00-1/411 | Store - Station Building - Mill Hill East Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19890 | ACTIVE | N | N053-00-1/411 | Store - Station Building - Mill Hill East Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | | | | | | |
| 8902 | ACTIVE | N | N053-00-1/412 | Store - Station Building - Mill Hill East Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19224 | ACTIVE | N | N053-00-1/412 | Store - Station Building - Mill Hill East Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8903 | ACTIVE | N | N053-00-1/426 | Toilet: Unisex - Station Building - Mill Hill East Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20104 | ACTIVE | N | N053-00-1/426 | Toilet: Unisex - Station Building - Mill Hill East Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8904 | ACTIVE | N | N053-00-1/551 | Yard - Station Building - Mill Hill East Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20105 | ACTIVE | N | N053-00-1/551 | Yard - Station Building - Mill Hill East Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8905 | ACTIVE | N | N053-00-1/552 | Yard - Station Building - Mill Hill East Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20106 | ACTIVE | N | N053-00-1/552 | Yard - Station Building - Mill Hill East Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8906 | ACTIVE | N | N053-00-1/602 | Stairs: Linear - Station Building - Mill Hill East Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19225 | ACTIVE | N | N053-00-1/602 | Stairs: Linear - Station Building - Mill Hill East Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8907 | ACTIVE | N | N053-00-1/661 | Switch Room - Station Building - Mill Hill East Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20107 | ACTIVE | N | N053-00-1/661 | Switch Room - Station Building - Mill Hill East Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box(es) Presumed asbestos insulating materials within. | | 3 | | N | N |
| 44125 | ACTIVE | N | N053-00-1/661/ WAL-002 80907205 | Wall: Internal - 2 - Switch Room - Station Building - Mill Hill East Stn Wall: Internal | Isolator Switches | Asbestos | Presumed | | | | 2x switch boxes on wall 2 (1x30amp and 1x100amp) Presumed asbestos insulating materials within | | 2 | | N | N |
| 19737 | ACTIVE | N | N053-00-1/661/ WAL-004 80907207 | Wall: Internal - 4 - Switch Room - Station Building - Mill Hill East Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | Iron clad Isolators 5x60amps, 2x100amp. Presumed insulating materials within. | | 9 | | N | N |



Hazardous Material Asset Register - Summary



N053-00 - Station Building - Mill Hill East Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|------------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 8908 | ACTIVE | N | N053-00-1/746 | SCR - Station Building - Mill Hill East Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20108 | ACTIVE | N | N053-00-1/746 | SCR - Station Building - Mill Hill East Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8909 | ACTIVE | N | N053-00-A/261 | Platform 1 - Northbound Main - Station Building - Mill Hill East Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20109 | ACTIVE | N | N053-00-A/261 | Platform 1 - Northbound Main - Station Building - Mill Hill East Stn | Cement Cowlings/ Flues | Asbestos | Presumed | | | | Chimney Pot Roof of SCR Room Appears to be ceramic, possible asbestos cement duct/sleeve. Not possible to inspect without high level access equipment. | | 1 | | N | N |
| 43196 | ACTIVE | N | N053-00-A/261 | Platform 1 - Northbound Main - Station Building - Mill Hill East Stn | Mastic | Asbestos | Sampled – Not Detected | | | | Lining, throughout, to undercroft of Platform 1 between columns and beams | | | RR531301 | N | N |
| 43199 | ACTIVE | N | N053-00-A/261 | Platform 1 - Northbound Main - Station Building - Mill Hill East Stn | Bitumen | Asbestos | Sampled – Not Detected | | | | Asphalt/bitumen (old) (0-114m), throughout, to top of timber panels, surface of Platform 1. | | | R531301 | N | N |
| 43197 | ACTIVE | N | N053-00-A/261 | Platform 1 - Northbound Main - Station Building - Mill Hill East Stn | Mastic | Asbestos | Sampled – Not Detected | | | | Mastic (black), throughout, to joints of timber panels to Platform 1 surface | | | R531301 | N | N |
| 43195 | ACTIVE | N | N053-00-A/261 | Platform 1 - Northbound Main - Station Building - Mill Hill East Stn | Mastic | Asbestos | Sampled – Not Detected | | | | Lining, throughout, to undercroft of Platform 1 between beams | | | R531301 | N | N |
| 43198 | ACTIVE | N | N053-00-A/261 | Platform 1 - Northbound Main - Station Building - Mill Hill East Stn | Mastic | Asbestos | Sampled – Not Detected | | | | Mastic (white), throughout, to certain areas of Platform 1 panels at platform edge only | | | R531301 | N | N |
| 19226 | ACTIVE | N | N053-00-A/261 | Platform 1 - Northbound Main - Station Building - Mill Hill East Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Cream Matt Coating - Canopy Beams. Thickness 0.14mm: Analysis 10.68% | | | | N | N |
| 43209 | ACTIVE | N | N053-00-A/261 | Platform 1 - Northbound Main - Station Building - Mill Hill East Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Steel Girders for Light Posts to the Platform Undercroft (Grey) 13.5% | | | R531302 | N | N |
| 43208 | ACTIVE | N | N053-00-A/261 | Platform 1 - Northbound Main - Station Building - Mill Hill East Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Steel Girders for Platform Fence to the Platform Undercroft (Green) 0.2% | | | R531302 | N | N |
| 8910 | ACTIVE | N | N053-00-A/281 | Office - Station Building - Mill Hill East Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20111 | ACTIVE | N | N053-00-A/281 | Office - Station Building - Mill Hill East Stn | Other Electrical Boxes | Asbestos | Surveyed – Not Detected | | | | Electrical Box | | | | | |
| 20110 | ACTIVE | N | N053-00-A/281 | Office - Station Building - Mill Hill East Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | | | | | | |



Hazardous Material Asset Register - Summary



N053-00 - Station Building - Mill Hill East Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|--------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 8911 | ACTIVE | N | N053-00-A/331 | Mess Room - Station Building - Mill Hill East Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20112 | ACTIVE | N | N053-00-A/331 | Mess Room - Station Building - Mill Hill East Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | | | | | | |
| 8912 | ACTIVE | N | N053-00-A/341 | Mess Room - Station Building - Mill Hill East Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8913 | ACTIVE | N | N053-00-A/416 | Toilet: Unisex - Station Building - Mill Hill East Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19227 | ACTIVE | N | N053-00-A/416/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Mill Hill East Stn | Glazing Rope | Asbestos | Strongly Presumed | | | | Glass Ceiling Roof - Rope Seal | | | | N | N |
| 8914 | ACTIVE | N | N053-00-A/436 | Waiting Room - Station Building - Mill Hill East Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20114 | ACTIVE | N | N053-00-A/436 | Waiting Room - Station Building - Mill Hill East Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | | | | | | |
| 8915 | ACTIVE | N | N053-00-A/601 | Stairs: Linear - Station Building - Mill Hill East Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20113 | ACTIVE | N | N053-00-A/601 | Stairs: Linear - Station Building - Mill Hill East Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |

N061-00 - Station Building - High Barnet Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---------------------|-------------|------------|-------------|---------------------|-------------------|
| 8918 | ACTIVE | N | N061-00-1/001 | Booking Hall - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17419 | ACTIVE | N | N061-00-1/001/CLG-01 | Ceiling: Solid - 1 - Booking Hall - Station Building - High Barnet Stn | Void | Asbestos | No Access: Presumed | | | | Above false ceiling | | | | YES | |
| 8919 | ACTIVE | N | N061-00-1/011 | Ticket Office - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17420 | ACTIVE | N | N061-00-1/011 | Ticket Office - Station Building - High Barnet Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8920 | ACTIVE | N | N061-00-1/021 | POM - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N061-00 - Station Building - High Barnet Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|------------------------|-------------|------------|-------------|---------------------|-------------------|
| 19122 | ACTIVE | N | N061-00-1/021/FLR-01 | Floor - 1 - POM - Station Building - High Barnet Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Tiles | | | | | YES |
| 8921 | ACTIVE | N | N061-00-1/031 | Mess Room - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17421 | ACTIVE | N | N061-00-1/031 | Mess Room - Station Building - High Barnet Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8922 | ACTIVE | N | N061-00-1/036 | Toilet: Unisex - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17422 | ACTIVE | N | N061-00-1/036 | Toilet: Unisex - Station Building - High Barnet Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8923 | ACTIVE | N | N061-00-1/081 | Lobby - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17423 | ACTIVE | N | N061-00-1/081/FLR-01 | Floor - 1 - Lobby - Station Building - High Barnet Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Tiles | | | | | YES |
| 8924 | ACTIVE | N | N061-00-1/082 | Lobby - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8925 | ACTIVE | N | N061-00-1/416 | Toilet - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19123 | ACTIVE | N | N061-00-1/416 | Toilet - Station Building - High Barnet Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8926 | ACTIVE | N | N061-00-1/417 | Toilet - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17426 | ACTIVE | N | N061-00-1/417 | Toilet - Station Building - High Barnet Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8927 | ACTIVE | N | N061-00-1/451 | Tenancy - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17999 | ACTIVE | N | N061-00-1/451 | Tenancy - Station Building - High Barnet Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8928 | ACTIVE | N | N061-00-1/452 | Tenancy - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17424 | ACTIVE | N | N061-00-1/452/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - High Barnet Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |



Hazardous Material Asset Register - Summary



N061-00 - Station Building - High Barnet Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17425 | ACTIVE | N | N061-00-1/452/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - High Barnet Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above 1st Floor Attic - slate roof & timber boarding; Roof sealant - Horse Hair, Lime Mortar | | | | YES | |
| 8929 | ACTIVE | N | N061-00-1/453 | Tenancy - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8930 | ACTIVE | N | N061-00-1/454 | Tenancy - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17427 | ACTIVE | N | N061-00-1/454 | Tenancy - Station Building - High Barnet Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8931 | ACTIVE | N | N061-00-1/457 | Toilet - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8932 | ACTIVE | N | N061-00-1/458 | Toilet - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8933 | ACTIVE | N | N061-00-1/459 | Shower Room - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8934 | ACTIVE | N | N061-00-1/576 | Stairs: Linear - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19124 | ACTIVE | N | N061-00-1/576/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - High Barnet Stn | Void | Asbestos | Surveyed – Not Detected | | | | Brick; Wooden Roof above false ceiling | | | | YES | |
| 8935 | ACTIVE | N | N061-00-1/601 | Stairs: Linear - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17428 | ACTIVE | N | N061-00-1/601 | Stairs: Linear - Station Building - High Barnet Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 17429 | ACTIVE | N | N061-00-1/601 | Stairs: Linear - Station Building - High Barnet Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Upstands & Overbridge: Cream Oil Based Paint. Thickness 0.59mm : Analysis 12.02% | | | | N | N |
| 8936 | ACTIVE | N | N061-00-1/602 | Stairs: Linear - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18000 | ACTIVE | N | N061-00-1/602 | Stairs: Linear - Station Building - High Barnet Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 17430 | ACTIVE | N | N061-00-1/602 | Stairs: Linear - Station Building - High Barnet Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Upstands, banisters & Overbridge: Cream Oil Based Paint. Thickness 0.59mm : Analysis 12.02% | | | | N | N |
| 17431 | ACTIVE | N | N061-00-1/636 | Overbridge - Station Building - High Barnet Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



| N061-00 - Station Building - High Barnet Stn | | | | | | | | | | | | | | | | |
|--|----------|-------------|-----------------------------------|---|------------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
| 17432 | ACTIVE | N | N061-00-1/636 | Overbridge - Station Building - High Barnet Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Upstands & Overbridge: Cream Oil Based Paint. Thickness 0.59mm : Analysis 12.02% | | | | N | N |
| 8937 | ACTIVE | N | N061-00-1/661 | Switch Room - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17882 | ACTIVE | N | N061-00-1/661/CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - High Barnet Stn | Void | Asbestos | No Access: Presumed | | | | Above ceiling tiles | | | | YES | |
| 17433 | ACTIVE | N | N061-00-1/661/CLG-02 | Ceiling: Solid - 2 - Switch Room - Station Building - High Barnet Stn | Void | Asbestos | No Access: Presumed | | | | Above ceiling tiles | | | | YES | |
| 42694 | INACTIVE | N | N061-00-1/661/FLR-01 | Floor - 1 - Switch Room - Station Building - High Barnet Stn | | Asbestos | Presumed | | | | | | | | | |
| 17434 | ACTIVE | N | N061-00-1/661/FLR-01 | Floor - 1 - Switch Room - Station Building - High Barnet Stn | Cable Duct: Other | Asbestos | Presumed | | | | Cable ducts by Wall 3 Ducts not visible - Concealed within concrete 17-03-2023 | | 3 | | N | N |
| 18219 | ACTIVE | N | N061-00-1/661/WAL-001 80904720 | Wall: Internal - 1 - Switch Room - Station Building - High Barnet Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch boxes wall 1: 1 x 60 amps. Presumed asbestos insulating materials within Reinspected 17-03-2023 | | 1 | | N | N |
| 44133 | ACTIVE | N | N061-00-1/661/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - High Barnet Stn | Cable Ducts: Cement | Asbestos | Presumed | | | | 6no Ducts to wall 3 Presumed HMT - Check next reinspection. 4-Rail services could not locate ducts but ducts buried in concrete potentially present. (5475) | | 6 | | N | N |
| 17435 | ACTIVE | N | N061-00-1/661/WAL-003 80904722 | Wall: Internal - 3 - Switch Room - Station Building - High Barnet Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box(es) to Wall 3. Presumed asbestos insulating materials within. No electrician on site inspect within 04-04-2023 | | 3 | | | |
| 44124 | ACTIVE | N | N061-00-1/661/WAL-003 80904722 | Wall: Internal - 3 - Switch Room - Station Building - High Barnet Stn Wall: Internal | Isolator Switches | Asbestos | Presumed | | | | 1 x 30 amp switch box. Presumed asbestos insulating materials within Not inspected within during 2023 reinspection as no electrician present. | | 1 | | N | N |
| 8938 | ACTIVE | N | N061-00-2/001 | Booking Hall - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18996 | ACTIVE | N | N061-00-2/001 | Booking Hall - Station Building - High Barnet Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8939 | ACTIVE | N | N061-00-2/011 | Ticket Office - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 17436 | ACTIVE | N | N061-00-2/011 | Ticket Office - Station Building - High Barnet Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Marble tiles to floor, plaster on brick /block to walls, wooden door, window and framework to wall 4, plasterboard to wall 4 above door, supalux to ceiling. 4Rail R726751 | | | | | |



Hazardous Material Asset Register - Summary



N061-00 - Station Building - High Barnet Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 8940 | ACTIVE | N | N061-00-2/021 | POM - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Presumed | | | | | | | | | |
| 17437 | ACTIVE | N | N061-00-2/021 | POM - Station Building - High Barnet Stn | No Access | Asbestos | Presumed | | | | Presumed materials within safe unit to wall 3 Metal/rubber computer tiles to floor, concrete to floor, plaster on brickwork to walls, wooden door and framework to wall 4, supalux to false ceiling, metal to ceiling above false ceiling, modern electrical equipment throughout. 4Rail Report R726751 | | | | | |
| 8941 | ACTIVE | N | N061-00-2/047 | Kitchen - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17883 | ACTIVE | N | N061-00-2/047 | Kitchen - Station Building - High Barnet Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 8942 | ACTIVE | N | N061-00-2/053 | Mess Room - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17438 | ACTIVE | N | N061-00-2/053 | Mess Room - Station Building - High Barnet Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 17439 | ACTIVE | N | N061-00-2/053 | Mess Room - Station Building - High Barnet Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supulux Panels to Outlet Pipes | | | | | |
| 17440 | ACTIVE | N | N061-00-2/053/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - High Barnet Stn | Void | Asbestos | No Access: Presumed | | | | Above false ceiling | | | | YES | |
| 8943 | ACTIVE | N | N061-00-2/054 | Mess Room - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17441 | ACTIVE | N | N061-00-2/054 | Mess Room - Station Building - High Barnet Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 17442 | ACTIVE | N | N061-00-2/054/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - High Barnet Stn | Void | Asbestos | Surveyed – Not Detected | | | | Attic Insulation - Rockwool; Wood - Beams; Walls Brick above false ceiling | | | | YES | |
| 18001 | ACTIVE | N | N061-00-2/054/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - High Barnet Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 17884 | ACTIVE | N | N061-00-2/054/FLR-01 | Floor - 1 - Mess Room - Station Building - High Barnet Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Vinyl Flooring | | | | | |
| 8944 | ACTIVE | N | N061-00-2/055 | Mess Room - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N061-00 - Station Building - High Barnet Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18494 | ACTIVE | N | N061-00-2/055/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - High Barnet Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 17443 | ACTIVE | N | N061-00-2/055/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - High Barnet Stn | Void | Asbestos | No Access: Presumed | | | | Above false ceiling | | | | YES | |
| 8945 | ACTIVE | N | N061-00-2/056 | Mess Room - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17885 | ACTIVE | N | N061-00-2/056/FLR-01 | Floor - 1 - Mess Room - Station Building - High Barnet Stn | Void | Asbestos | Surveyed – Not Detected | | | | Supalux under stairs | | | | | YES |
| 8946 | ACTIVE | N | N061-00-2/057 | Lobby - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17444 | ACTIVE | N | N061-00-2/057 | Lobby - Station Building - High Barnet Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8947 | ACTIVE | N | N061-00-2/058 | Mess Room - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8948 | ACTIVE | N | N061-00-2/081 | Lobby - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17445 | ACTIVE | N | N061-00-2/081 | Lobby - Station Building - High Barnet Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 17446 | ACTIVE | N | N061-00-2/081 | Lobby - Station Building - High Barnet Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Girder: Grey Oil Based Paint. Thickness 0.20mm : Analysis 31.93% | | | | N | N |
| 8949 | ACTIVE | N | N061-00-2/082 | Lobby - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 17447 | ACTIVE | N | N061-00-2/082 | Lobby - Station Building - High Barnet Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Marble tiles to floor, brickwork to walls, ceramic tiles to walls, wooden doors and framework to walls, supalux to false ceiling, metal to false ceiling hatch, metal to ceiling above false ceiling | | | | | |
| 8950 | ACTIVE | N | N061-00-2/201 | Passage - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8951 | ACTIVE | N | N061-00-2/236 | Passage - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17886 | ACTIVE | N | N061-00-2/236 | Passage - Station Building - High Barnet Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N061-00 - Station Building - High Barnet Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|---------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 8952 | ACTIVE | N | N061-00-2/261 | Platform 1 - Northbound Fast - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17449 | INACTIVE | N | N061-00-2/261 | Platform 1 - Northbound Fast - Station Building - High Barnet Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | DUPLICATE OF 17449 Asbestos insulation presumed within Westing House Boxes near the end of Platform 1 Not inspected within during 2023 re inspection as no electrician present | | 2 | | N | N |
| 17887 | ACTIVE | N | N061-00-2/261 | Platform 1 - Northbound Fast - Station Building - High Barnet Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Upstands: Green Oil Based Paint. Thickness 0.42mm : Analysis 11.31% | | | | N | N |
| 17450 | ACTIVE | N | N061-00-2/261 | Platform 1 - Northbound Fast - Station Building - High Barnet Stn | Isolator Switches | Lead Paint/Lead | Known | | | | Switch Boxes: Grey Oil Based Paint. Thickness 0.38mm : Analysis 12.69% (same boxes as ref.17449) | | 2 | | N | N |
| 17448 | ACTIVE | N | N061-00-2/261/CLG-01 | Ceiling: Solid - 1 - Platform 1 - Station Building - High Barnet Stn | Void | Asbestos | Surveyed – Not Detected | | | | External Roof - Tile Cement Non Asbestos above Canopy - Wooden Underneath | | | | YES | |
| 8953 | ACTIVE | N | N061-00-2/262 | Platform 2 - Southbound Fast - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17451 | ACTIVE | N | N061-00-2/262 | Platform 2 - Southbound Fast - Station Building - High Barnet Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 17452 | ACTIVE | N | N061-00-2/262 | Platform 2 - Southbound Fast - Station Building - High Barnet Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Upstands: Green Oil Based Paint. Thickness 0.42mm : Analysis 11.31% | | | | N | N |
| 8954 | ACTIVE | N | N061-00-2/263 | Platform 3 - Southbound Main - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17453 | INACTIVE | N | N061-00-2/263 | Platform 3 - Southbound Main - Station Building - High Barnet Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | Insultation within Westing House Boxes (trackside mid-way by platform 3) presumed to contain asbestos R.A.S - This should be on track and is already covered by Record 33909. Deactivated | | 9 | | N | N |
| 17454 | ACTIVE | N | N061-00-2/263 | Platform 3 - Southbound Main - Station Building - High Barnet Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Upstands: Green Oil Based Paint. Thickness 0.42mm : Analysis 11.31% | | | | N | N |
| 8955 | ACTIVE | N | N061-00-2/281 | Station Supervisor Office - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18997 | ACTIVE | N | N061-00-2/281/CLG-01 | Ceiling: Solid - 1 - Station Supervisor Office - Station Building - High Barnet Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Fibreboard & Plasterboard | | | | | |



Hazardous Material Asset Register - Summary



N061-00 - Station Building - High Barnet Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-----------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 17888 | ACTIVE | N | N061-00-2/281/CLG-01 | Ceiling: Solid - 1 - Station Supervisor Office - Station Building - High Barnet Stn | Void | Asbestos | No Access: Presumed | | | | Above false ceiling | | | | YES | |
| 18002 | ACTIVE | N | N061-00-2/281/WDW-01 | Window - 1 - Station Supervisor Office - Station Building - High Barnet Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard divide above windows | | | | | |
| 18495 | ACTIVE | N | N061-00-2/281/WDW-02 | Window - 2 - Station Supervisor Office - Station Building - High Barnet Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard divide above windows | | | | | |
| 8956 | ACTIVE | N | N061-00-2/291 | Office - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8957 | ACTIVE | N | N061-00-2/316 | Locker Room - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17455 | ACTIVE | N | N061-00-2/316 | Locker Room - Station Building - High Barnet Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8958 | ACTIVE | N | N061-00-2/317 | Locker Room - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17456 | ACTIVE | N | N061-00-2/317 | Locker Room - Station Building - High Barnet Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8959 | ACTIVE | N | N061-00-2/401 | Bin Store - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17457 | ACTIVE | N | N061-00-2/401 | Bin Store - Station Building - High Barnet Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8960 | ACTIVE | N | N061-00-2/411 | Store - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17458 | ACTIVE | N | N061-00-2/411 | Store - Station Building - High Barnet Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 17889 | ACTIVE | N | N061-00-2/411 | Store - Station Building - High Barnet Stn | Lead/Leading | Lead Paint/Lead | Known | | | | 2 x Down Pipes: Green Oil Based Paint. Thickness 0.39mm : Analysis 8.93% | | 2 | | N | N |
| 8961 | ACTIVE | N | N061-00-2/412 | Store - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17459 | ACTIVE | N | N061-00-2/412/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - High Barnet Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above concrete ceiling is - access hatch to loft area in canopy; metal water tank; bitumen roofing felt - Non Asbestos | | | | YES | |
| 17460 | ACTIVE | N | N061-00-2/412/WAL-001 | Wall: Internal - 1 - Store - Station Building - High Barnet Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Partition wall between rooms 2/451 & 2/412 Partition wall is plasterboard with patches of supalux above false ceiling 04-04-2023 | | | | N | N |



Hazardous Material Asset Register - Summary



N061-00 - Station Building - High Barnet Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 44138 | ACTIVE | N | N061-00-2/412/WAL-002 | Wall: Internal - 2 - Store - Station Building - High Barnet Stn | Gasket :Pipework | Asbestos | Presumed | | | | Gaskets to Pipework Presumed (potentially concealed at joints) Reinspected 04-04-2023 | | | | N | N |
| 8962 | ACTIVE | N | N061-00-2/413 | Store - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17462 | ACTIVE | N | N061-00-2/413 | Store - Station Building - High Barnet Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Stairs: White Oil Based Paint. Thickness 0.28mm : Analysis 14.54% | | | | N | N |
| 17461 | ACTIVE | N | N061-00-2/413/FLR-01 | Floor - 1 - Store - Station Building - High Barnet Stn | Void | Asbestos | Surveyed – Not Detected | | | | Wood under stairs | | | | | YES |
| 8963 | ACTIVE | N | N061-00-2/414 | Office - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 17890 | ACTIVE | N | N061-00-2/414 | Office - Station Building - High Barnet Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Carpet to floor, plaster on brick/ block to walls, plasterboard to partition wall 4, wooden door and framework to wall 4, wooden door and framework to wall 4, wooden window and framework to wall 2, rope to wall 2 window pulley - non asbestos, modern electrical equipment throughout, MMMF tiles to false ceiling, plaster to ceiling above false ceiling. (4Rail Report R726751) | | | | | |
| 8964 | ACTIVE | N | N061-00-2/415 | Store - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 18003 | ACTIVE | N | N061-00-2/415 | Store - Station Building - High Barnet Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Carpet tiles on quarry tiles to floor, plaster on brick to solid walls, plasterboard to partition walls, wooden doors and framework to walls, wooden window and framework to wall 2, rope to wall 2 window pulleys - non asbestos, modern boiler and cylinder and pipework to boiler cupboard, wooden boxing, unlagged pipework within to walls, MMMF tiles to ceiling, plaster to ceiling above false ceiling, metal pipework with foam insulation, plastic vent to wall 2, 4Rail Report R726751 | | | | | |
| 8965 | ACTIVE | N | N061-00-2/417 | Toilet: Female - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17463 | ACTIVE | N | N061-00-2/417 | Toilet: Female - Station Building - High Barnet Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Quarry tiles on concrete to floor, ceramic tiles to walls, ceramic toilet and sink, metal cistern, plastic and metal pipework unlagged to walls, electrical heater to wall 1, wooden door and framework to wall 4, meter above door, plasterboard to fixed false ceiling - no access above (4Rail Report R726751) | | | | | |



Hazardous Material Asset Register - Summary



N061-00 - Station Building - High Barnet Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 53948 | ACTIVE | N | N061-00-2/417/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - High Barnet Stn | | Asbestos | Presumed | | | | No access above fixed ceiling | | | | | |
| 8966 | ACTIVE | N | N061-00-2/418 | Toilet: Unisex - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Presumed | | | | No information above wood ceiling | | | | | |
| 17464 | ACTIVE | N | N061-00-2/418 | Toilet: Unisex - Station Building - High Barnet Stn | No Access | Asbestos | No Access: Presumed | | | | No access above wooden ceiling Quarry tiles on concrete to floor, ceramic tiles to lower walls, brickwork to walls, ceramic toilet, cistern and sink, wooden door, window and framework to walls, wood to ceiling, plastic and metal pipework to walls, foam insulation to pipework, plaster on wood panels to upper walls 1&3. 4Rail Report R726751 | | | | YES | |
| 8967 | ACTIVE | N | N061-00-2/419 | Toilet: Unisex - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 17465 | ACTIVE | N | N061-00-2/419 | Toilet: Unisex - Station Building - High Barnet Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Modern lino to floor, plaster on brick to solid walls, plasterboard to partition walls, wooden door and framework to wall 4, wooden window and framework to wall 2, rope to walls 2 window pulley - non asbestos, ceramic toilet, cistern and tiles behind toilet, wooden boxing behind toilet, not inspected within as sealed, modern radiator to wall 1, MMMF tiles to false ceiling, plaster to ceiling above false ceiling. 4Rail Report R726751 | | | | | |
| 8968 | ACTIVE | N | N061-00-2/420 | Shower Room - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 17891 | ACTIVE | N | N061-00-2/420 | Shower Room - Station Building - High Barnet Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Modern lino to floor, ceramic tiles to walls, wooden door and framework to wall 4, wooden windows and framework to wall 2, rope to wall 2 window pulley - non asbestos, ceramic toilet, cistern and sink, wood boxing, unlagged pipework within to wall 4, MMMF tiles to false ceiling, plaster to ceiling above false ceiling. 4Rail Report R726751 | | | | | |
| 8969 | ACTIVE | N | N061-00-2/421 | Toilet: Male - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17466 | ACTIVE | N | N061-00-2/421 | Toilet: Male - Station Building - High Barnet Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8970 | ACTIVE | N | N061-00-2/422 | Toilet: Female - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N061-00 - Station Building - High Barnet Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|------------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 17467 | ACTIVE | N | N061-00-2/422 | Toilet: Female - Station Building - High Barnet Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8971 | ACTIVE | N | N061-00-2/426 | Toilet - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8972 | ACTIVE | N | N061-00-2/427 | Toilet: Unisex - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8973 | ACTIVE | N | N061-00-2/428 | Toilet: Unisex - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17468 | ACTIVE | N | N061-00-2/428 | Toilet: Unisex - Station Building - High Barnet Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8974 | ACTIVE | N | N061-00-2/436 | Waiting Room - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18004 | ACTIVE | N | N061-00-2/436 | Waiting Room - Station Building - High Barnet Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8975 | ACTIVE | N | N061-00-2/437 | Waiting Room - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17469 | ACTIVE | N | N061-00-2/437 | Waiting Room - Station Building - High Barnet Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8976 | ACTIVE | N | N061-00-2/451 | Office - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17892 | ACTIVE | N | N061-00-2/451/ WAL-002 | Wall: Internal - 2 - Office - Station Building - High Barnet Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Partition Wall | | | | | |
| 20023 | ACTIVE | N | N061-00-2/451/ WAL-004 | Wall: Internal - 4 - Office - Station Building - High Barnet Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Partition Wall | | | | | |
| 8977 | ACTIVE | N | N061-00-2/452 | Office - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 17470 | ACTIVE | N | N061-00-2/452/ WAL-002 | Wall: Internal - 2 - Office - Station Building - High Barnet Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Carpet tiles on concrete, plasterboard to partition walls, plaster on brick to solid walls, PVC/ wood windows and framework to walls, rope to window pulleys - non asbestos, wooden doors & framework to walls, modern. electrical equipment throughout. MMMF tiles to false. ceiling, plasterboard to second false ceiling, fixed not inspected above. 4Rail Report R726751. | | | | N | N |



Hazardous Material Asset Register - Summary



N061-00 - Station Building - High Barnet Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 17471 | ACTIVE | N | N061-00-2/452/WAL-004 | Wall: Internal - 4 - Office - Station Building - High Barnet Stn | Other Boarding | Asbestos | No Access: Presumed | | | | No access above fixed false ceiling. 4Rail Report R726751 | | | | N | N |
| 8978 | ACTIVE | N | N061-00-2/453 | Passage - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17472 | ACTIVE | N | N061-00-2/453/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - High Barnet Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Panelling to ceiling | | | | | |
| 18496 | ACTIVE | N | N061-00-2/453/WAL-002 | Wall: Internal - 2 - Passage - Station Building - High Barnet Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Partition Wall | | | | | |
| 17893 | ACTIVE | N | N061-00-2/453/WAL-004 | Wall: Internal - 4 - Passage - Station Building - High Barnet Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Partition Wall | | | | | |
| 8979 | ACTIVE | N | N061-00-2/455 | Passage - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8980 | ACTIVE | N | N061-00-2/661 | Switch Room - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17477 | ACTIVE | N | N061-00-2/661 | Switch Room - Station Building - High Barnet Stn | | Anthrax | Surveyed – Not Detected | | | | No Anthrax Detected | | | | | |
| 17474 | ACTIVE | N | N061-00-2/661 | Switch Room - Station Building - High Barnet Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux panels above door | | | | | |
| 18220 | ACTIVE | N | N061-00-2/661/CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - High Barnet Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 17475 | ACTIVE | N | N061-00-2/661/CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - High Barnet Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 17473 | ACTIVE | N | N061-00-2/661/FLR-01 | Floor - 1 - Switch Room - Station Building - High Barnet Stn | Void | Asbestos | Surveyed – Not Detected | | | | Bituminous Pipe Lining. Floor hatches (no access on re-inspection) | | | | | YES |
| 17894 | ACTIVE | N | N061-00-2/661/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - High Barnet Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Isolation Switches 4 x 100 amp 1 x 300amp. Presumed asbestos insulation within. Not inspected within during 2023 reinspection as no electrician was present | | 5 | | N | N |
| 17476 | ACTIVE | N | N061-00-2/661/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - High Barnet Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Isolation Switches Wall 3: 7 X 60amp 1 x 100 amp 1 x 30amp. Presumed asbestos insulation within. Not Inspected within during 2023 re inspection as no electrician present | | 9 | | N | N |



Hazardous Material Asset Register - Summary



N061-00 - Station Building - High Barnet Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|--------------------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 19492 | ACTIVE | N | N061-00-2/661/WAL-004 80904934 | Wall: Internal - 4 - Switch Room - Station Building - High Barnet Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box(es) to wall 4. Presumed asbestos insulating materials within Not inspected within during 2023 re inspection as no electrician present | | 1 | | N | N |
| 8981 | ACTIVE | N | N061-00-2/662 | Switch Room - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17478 | ACTIVE | N | N061-00-2/662 | Switch Room - Station Building - High Barnet Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 x Isolation Switch box to wall 2. Presumed asbestos insulating materials within Not inspected within during 2023 re inspection as no electrician present. | | 1 | | N | N |
| 17479 | ACTIVE | N | N061-00-2/662/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - High Barnet Stn | Other Boarding | Asbestos | Strongly Presumed | | | | Panels length of Wall 2 and Wall 3 doorway framework Possible non ACM supalux for all panels | | 2 | | N | N |
| 8982 | ACTIVE | N | N061-00-2/746 | SCR - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 17480 | ACTIVE | N | N061-00-2/746 | SCR - Station Building - High Barnet Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Concrete floor & ceiling, plaster on brick to walls, textured coating to walls 1 &3 - Non asbestos, wooden doors and framework, plasterboard to partition wall, modern electrical equipment throughout, modern firestopping, plastic cables, metal conduits and CMS (4Rail Report R726751) | | | | | |
| 8983 | ACTIVE | N | N061-00-2/756 | Station Control Room - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17481 | ACTIVE | N | N061-00-2/756 | Station Control Room - Station Building - High Barnet Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 8984 | ACTIVE | N | N061-00-2/776 | Plant Room - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8985 | ACTIVE | N | N061-00-2/801 | Office - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17483 | ACTIVE | N | N061-00-2/801 | Office - Station Building - High Barnet Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 8986 | ACTIVE | N | N061-00-2/802 | Office - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17896 | ACTIVE | N | N061-00-2/802 | Office - Station Building - High Barnet Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |



Hazardous Material Asset Register - Summary



N061-00 - Station Building - High Barnet Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 8987 | ACTIVE | N | N061-00-2/803 | Office - Station Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N063-00 - Station Building - Totteridge & Whetstone Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 9059 | ACTIVE | N | N063-00-1/001 | Booking Hall - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17387 | ACTIVE | N | N063-00-1/001/CLG-01 | Ceiling: Suspended - 1 - Booking Hall - Station Building - Totteridge & Whetstone Stn | Void | Asbestos | Surveyed – Not Detected | | | | Tiles above false ceiling | | | | YES | |
| 9060 | ACTIVE | N | N063-00-1/011 | Ticket Office - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17388 | ACTIVE | N | N063-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Totteridge & Whetstone Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 17389 | ACTIVE | N | N063-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Totteridge & Whetstone Stn | Void | Asbestos | Surveyed – Not Detected | | | | Timber Rafters; Lagging - Rock Wool above false ceiling | | | | YES | |
| 19112 | ACTIVE | N | N063-00-1/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Totteridge & Whetstone Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |
| 9061 | ACTIVE | N | N063-00-1/021 | POM - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18218 | ACTIVE | N | N063-00-1/021/CLG-01 | Ceiling: Solid - 1 - POM - Station Building - Totteridge & Whetstone Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid and new metal work, PVC cables above false ceiling | | | | YES | |
| 17390 | ACTIVE | N | N063-00-1/021/CLG-01 | Ceiling: Solid - 1 - POM - Station Building - Totteridge & Whetstone Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Fibre Boarding | | | | | |
| 18994 | ACTIVE | N | N063-00-1/021/FLR-01 | Floor - 1 - POM - Station Building - Totteridge & Whetstone Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |
| 9062 | ACTIVE | N | N063-00-1/031 | Mess Room - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17391 | ACTIVE | N | N063-00-1/031 | Mess Room - Station Building - Totteridge & Whetstone Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |



Hazardous Material Asset Register - Summary



N063-00 - Station Building - Totteridge & Whetstone Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 19113 | ACTIVE | N | N063-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Totteridge & Whetstone Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18493 | ACTIVE | N | N063-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Totteridge & Whetstone Stn | Void | Asbestos | Surveyed – Not Detected | | | | Timber Rafters; Lagging - Rock Wool above false ceiling | | | | YES | |
| 9063 | ACTIVE | N | N063-00-1/036 | Toilet: Unisex - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17392 | ACTIVE | N | N063-00-1/036 | Toilet: Unisex - Station Building - Totteridge & Whetstone Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing Panel | | | | | |
| 19114 | ACTIVE | N | N063-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Totteridge & Whetstone Stn | Void | Asbestos | Surveyed – Not Detected | | | | Timber Rafters; Lagging - Rock Wool above false ceiling | | | | YES | |
| 18468 | ACTIVE | N | N063-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Totteridge & Whetstone Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9064 | ACTIVE | N | N063-00-1/071 | Circulation Area - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17393 | ACTIVE | N | N063-00-1/071/CLG-01 | Ceiling: Suspended - 1 - Circulation Area - Station Building - Totteridge & Whetstone Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 17394 | ACTIVE | N | N063-00-1/071/CLG-01 | Ceiling: Suspended - 1 - Circulation Area - Station Building - Totteridge & Whetstone Stn | Void | Asbestos | No Access: Presumed | | | | No access to loft space above false ceiling. Possible ACM's | | | | YES | |
| 18995 | ACTIVE | N | N063-00-1/071/CLG-01 | Ceiling: Suspended - 1 - Circulation Area - Station Building - Totteridge & Whetstone Stn | Void | Asbestos | Surveyed – Not Detected | | | | Tiles - Non Asbestos; Fibre board / plaster board. No access to loft space. Possible ACM's | | | | YES | |
| 9065 | ACTIVE | N | N063-00-1/081 | Lobby - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17395 | ACTIVE | N | N063-00-1/081/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Totteridge & Whetstone Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 17996 | ACTIVE | N | N063-00-1/081/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Totteridge & Whetstone Stn | Void | Asbestos | Surveyed – Not Detected | | | | Timber Rafters; Lagging - Rock Wool above false ceiling | | | | YES | |
| 9066 | ACTIVE | N | N063-00-1/281 | Office - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19115 | ACTIVE | N | N063-00-1/281 | Office - Station Building - Totteridge & Whetstone Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |



Hazardous Material Asset Register - Summary



N063-00 - Station Building - Totteridge & Whetstone Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|--------------------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 19412 | ACTIVE | N | N063-00-1/281 | Office - Station Building - Totteridge & Whetstone Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Tiles | | | | | |
| 17396 | ACTIVE | N | N063-00-1/281/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Totteridge & Whetstone Stn | Void | Asbestos | Surveyed – Not Detected | | | | Tiles above false ceiling | | | | YES | |
| 9067 | ACTIVE | N | N063-00-1/601 | Stairs: Linear - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19116 | ACTIVE | N | N063-00-1/601/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Totteridge & Whetstone Stn | Void | Asbestos | Surveyed – Not Detected | | | | Hardboard panels above metal roofing sheets; Tiles | | | | YES | |
| 9068 | ACTIVE | N | N063-00-1/602 | Stairs: Linear - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17397 | ACTIVE | N | N063-00-1/602/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Totteridge & Whetstone Stn | Void | Asbestos | Surveyed – Not Detected | | | | Tiles; Timber rafters above metal roofing sheets; Tiles | | | | YES | |
| 9069 | ACTIVE | N | N063-00-1/661 | Switch Room - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42699 | ACTIVE | N | N063-00-1/661 | Switch Room - Station Building - Totteridge & Whetstone Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | W3 1 X 30amp. Presumed asbestos insulating materials within.no access internal during re-inspection. Electrical isolations required. | | 1 | | N | N |
| 46167 | ACTIVE | N | N063-00-1/661/CTR-01 81379472 | Contactora: Changeover - 01 - Switch Room - Station Building - Totteridge & Whetstone Stn Contactora: Changeover | Isolator Switches | Asbestos | Strongly Presumed | | | | 1x Switch box. Presumed insulating materials within. No access internal during re-inspection. Electrical isolations required | | 1 | | | |
| 42697 | ACTIVE | N | N063-00-1/661/WAL-001 80887940 | Wall: Internal - 1 - Switch Room - Station Building - Totteridge & Whetstone Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes W1 2 X 60amp, 1 x 100amp, 1 x Bus Bar. Presumed asbestos insulating materials within. no access internal during re-inspection. Electrical isolations required | | 3 | | N | N |
| 42698 | ACTIVE | N | N063-00-1/661/WAL-002 80887941 | Wall: Internal - 2 - Switch Room - Station Building - Totteridge & Whetstone Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | W2 2 X 60amp, 1 X 100amp Switch Boxes. Presumed asbestos insulating materials within. No access internal during re-inspection. Electrical isolations required | | 3 | | N | N |
| 17398 | ACTIVE | N | N063-00-1/661/WAL-003 80887942 | Wall: Internal - 3 - Switch Room - Station Building - Totteridge & Whetstone Stn Wall: Internal | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | 3x Transformer boxes - Presumed asbestos insulating materials within. No access internal during re-inspection. Electrical isolations required | | 3 | | | |
| 9070 | ACTIVE | N | N063-00-1/746 | SCR - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17399 | ACTIVE | N | N063-00-1/746/CLG-01 | Ceiling: Solid - 1 - SCR - Station Building - Totteridge & Whetstone Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Boarding - Non Asbestos | | | | | |



Hazardous Material Asset Register - Summary



N063-00 - Station Building - Totteridge & Whetstone Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17400 | ACTIVE | N | N063-00-1/746/CLG-01 | Ceiling: Solid - 1 - SCR - Station Building - Totteridge & Whetstone Stn | Void | Asbestos | No Access: Presumed | | | | Above false ceiling | | | | YES | |
| 9071 | ACTIVE | N | N063-00-2/081 | Lobby - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19117 | ACTIVE | N | N063-00-2/081 | Lobby - Station Building - Totteridge & Whetstone Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9072 | ACTIVE | N | N063-00-2/082 | Lobby - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17401 | ACTIVE | N | N063-00-2/082 | Lobby - Station Building - Totteridge & Whetstone Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9073 | ACTIVE | N | N063-00-2/261 | Platform 1 - Northbound Fast - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 17402 | ACTIVE | N | N063-00-2/261/CLG-01 | Ceiling: Solid - 1 - Platform 1 - Station Building - Totteridge & Whetstone Stn | Void | Asbestos | Surveyed – Not Detected | | | | Wood with metal roof. Inspection carried out within the canopy void did not identify any suspect materials that may contain asbestos, only dirt and rubbish present. | | | | YES | |
| 9074 | ACTIVE | N | N063-00-2/262 | Platform 2 - Southbound Fast - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19118 | ACTIVE | N | N063-00-2/262/CLG-01 | Ceiling: Solid - 1 - Platform 2 - Station Building - Totteridge & Whetstone Stn | Void | Asbestos | Surveyed – Not Detected | | | | Wood with metal roof. Inspection carried out within the canopy void did not identify any suspect materials that may contain asbestos, only dirt and rubbish present. | | | | YES | |
| 9075 | ACTIVE | N | N063-00-2/406 | Store - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17403 | ACTIVE | N | N063-00-2/406 | Store - Station Building - Totteridge & Whetstone Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9076 | ACTIVE | N | N063-00-2/416 | Toilet: Unisex - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17404 | ACTIVE | N | N063-00-2/416 | Toilet: Unisex - Station Building - Totteridge & Whetstone Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panelling | | | | | |
| 9077 | ACTIVE | N | N063-00-2/417 | Toilet: Female - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17997 | ACTIVE | N | N063-00-2/417 | Toilet: Female - Station Building - Totteridge & Whetstone Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N063-00 - Station Building - Totteridge & Whetstone Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 9078 | ACTIVE | N | N063-00-2/418 | Toilet: Male - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17405 | ACTIVE | N | N063-00-2/418 | Toilet: Male - Station Building - Totteridge & Whetstone Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9079 | ACTIVE | N | N063-00-2/419 | Store - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17406 | ACTIVE | N | N063-00-2/419 | Store - Station Building - Totteridge & Whetstone Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9080 | ACTIVE | N | N063-00-2/426 | Toilet: Unisex - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17407 | ACTIVE | N | N063-00-2/426/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Totteridge & Whetstone Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above hatch in ceiling is rafters for roof | | | | YES | |
| 9081 | ACTIVE | N | N063-00-2/427 | Store - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19119 | ACTIVE | N | N063-00-2/427/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Totteridge & Whetstone Stn | Rope Gaskets | Asbestos | Strongly Presumed | | | | Rope Gasket - SP. Timber Glass Roof | | | | | |
| 9082 | ACTIVE | N | N063-00-2/436 | Waiting Room - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17408 | ACTIVE | N | N063-00-2/436 | Waiting Room - Station Building - Totteridge & Whetstone Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Supalux Panel behind heater | | | | | |
| 9083 | ACTIVE | N | N063-00-2/437 | Waiting Room - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17409 | ACTIVE | N | N063-00-2/437 | Waiting Room - Station Building - Totteridge & Whetstone Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - White Foam backing | | | | | |
| 9084 | ACTIVE | N | N063-00-2/481 | Store - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17410 | ACTIVE | N | N063-00-2/481 | Store - Station Building - Totteridge & Whetstone Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9085 | ACTIVE | N | N063-00-2/551 | Yard - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17998 | ACTIVE | N | N063-00-2/551 | Yard - Station Building - Totteridge & Whetstone Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N063-00 - Station Building - Totteridge & Whetstone Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9086 | ACTIVE | N | N063-00-2/661 | Switch Room - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17411 | ACTIVE | N | N063-00-2/661 | Switch Room - Station Building - Totteridge & Whetstone Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9087 | ACTIVE | N | N063-00-2/662 | Switch Room - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17412 | ACTIVE | N | N063-00-2/662 | Switch Room - Station Building - Totteridge & Whetstone Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - White Foam backing | | | | | |
| 42696 | ACTIVE | N | N063-00-2/662 | Switch Room - Station Building - Totteridge & Whetstone Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes W4, W3 2 X 100 amp, 2 x 60 amp 1 x 200amp Bus Bar. Presumed asbestos insulating materials within | | | | N | N |
| 9088 | ACTIVE | N | N063-00-2/711 | SER - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19120 | ACTIVE | N | N063-00-2/711 | SER - Station Building - Totteridge & Whetstone Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 9089 | ACTIVE | N | N063-00-2/756 | Store - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17414 | ACTIVE | N | N063-00-2/756 | Store - Station Building - Totteridge & Whetstone Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9090 | ACTIVE | N | N063-00-2/951 | Disused Room - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17415 | ACTIVE | N | N063-00-2/951 | Disused Room - Station Building - Totteridge & Whetstone Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - White Foam backing | | | | | |
| 9091 | ACTIVE | N | N063-00-2/952 | Disused Room - Station Building - Totteridge & Whetstone Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17417 | ACTIVE | N | N063-00-2/952 | Disused Room - Station Building - Totteridge & Whetstone Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 17416 | ACTIVE | N | N063-00-2/952 | Disused Room - Station Building - Totteridge & Whetstone Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - White Foam backing | | | | | |
| 19121 | ACTIVE | N | N063-00-2/952/CLG-01 | Ceiling: Solid - 1 - Disused Room - Station Building - Totteridge & Whetstone Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 17418 | ACTIVE | N | N063-00-2/952/CLG-01 | Ceiling: Solid - 1 - Disused Room - Station Building - Totteridge & Whetstone Stn | Void | Asbestos | No Access: Presumed | | | | Above Plasterboard | | | | YES | |



Hazardous Material Asset Register - Summary



N065-00 - Station Building - Woodside Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|-------------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 9095 | ACTIVE | N | N065-00-1/001 | Booking Hall - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17351 | ACTIVE | N | N065-00-1/001 | Booking Hall - Station Building - Woodside Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9096 | ACTIVE | N | N065-00-1/011 | Ticket Office - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17353 | ACTIVE | N | N065-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Woodside Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Steel above false ceiling | | | | YES | |
| 17352 | ACTIVE | N | N065-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Woodside Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 19037 | ACTIVE | N | N065-00-1/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Woodside Park Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Rubber Tiles | | | | | YES |
| 9097 | ACTIVE | N | N065-00-1/021 | POM - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17354 | ACTIVE | N | N065-00-1/021/FLR-01 | Floor - 1 - POM - Station Building - Woodside Park Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Rubber Tiles | | | | | YES |
| 9098 | ACTIVE | N | N065-00-1/031 | Mess Room - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17355 | ACTIVE | N | N065-00-1/031 | Mess Room - Station Building - Woodside Park Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 9099 | ACTIVE | N | N065-00-1/036 | Toilet: Unisex - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19038 | ACTIVE | N | N065-00-1/036 | Toilet: Unisex - Station Building - Woodside Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9100 | ACTIVE | N | N065-00-1/053 | Mess Room - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20022 | ACTIVE | N | N065-00-1/053/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Woodside Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 17356 | ACTIVE | N | N065-00-1/053/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Woodside Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Wood above false ceiling | | | | YES | |
| 17991 | ACTIVE | N | N065-00-1/053/FLR-01 | Floor - 1 - Mess Room - Station Building - Woodside Park Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Lino, Wood | | | | | YES |



Hazardous Material Asset Register - Summary



N065-00 - Station Building - Woodside Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 9101 | ACTIVE | N | N065-00-1/081 | Lobby - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19039 | ACTIVE | N | N065-00-1/081/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Woodside Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18492 | ACTIVE | N | N065-00-1/081/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Woodside Park Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Tiles | | | | YES | |
| 17357 | ACTIVE | N | N065-00-1/081/FLR-01 | Floor - 1 - Lobby - Station Building - Woodside Park Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Tiles | | | | | YES |
| 9102 | ACTIVE | N | N065-00-1/261 | Platform 1 - Northbound Fast - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17358 | ACTIVE | N | N065-00-1/261 | Platform 1 - Northbound Fast - Station Building - Woodside Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9103 | ACTIVE | N | N065-00-1/262 | Platform 2 - Southbound Fast - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17359 | ACTIVE | N | N065-00-1/262 | Platform 2 - Southbound Fast - Station Building - Woodside Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9104 | ACTIVE | N | N065-00-1/281 | Station Supervisor Office - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17361 | ACTIVE | N | N065-00-1/281 | Station Supervisor Office - Station Building - Woodside Park Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - White Foam Insulation | | | | | |
| 68198 | INACTIVE | N | N065-00-1/281 | Station Supervisor Office - Station Building - Woodside Park Stn | LUL Heaters | Asbestos | Presumed | | | | 1/281 check register for lul heater. Wall 6 & wall 7 (partition so not sure of wall numbers | | | | | |
| 17360 | ACTIVE | N | N065-00-1/281 | Station Supervisor Office - Station Building - Woodside Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Fireplace | | | | | |
| 19040 | ACTIVE | N | N065-00-1/281/FLR-01 | Floor - 1 - Station Supervisor Office - Station Building - Woodside Park Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Lino, Wood | | | | | YES |
| 9105 | ACTIVE | N | N065-00-1/282 | CER - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9106 | ACTIVE | N | N065-00-1/311 | Union Office - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N065-00 - Station Building - Woodside Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17992 | ACTIVE | N | N065-00-1/311/CLG-01 | Ceiling: Suspended - 1 - Union Office - Station Building - Woodside Park Stn | Void | Asbestos | No Access: Presumed | | | | Above false Ceiling | | | | YES | |
| 17362 | ACTIVE | N | N065-00-1/311/CLG-01 | Ceiling: Suspended - 1 - Union Office - Station Building - Woodside Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9107 | ACTIVE | N | N065-00-1/411 | Store - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17363 | ACTIVE | N | N065-00-1/411 | Store - Station Building - Woodside Park Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 17364 | ACTIVE | N | N065-00-1/411 | Store - Station Building - Woodside Park Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Walls & Ceilings: Cream Gloss Paint. Thickness 0.35mm : Analysis 4.83% | | | | N | N |
| 9108 | ACTIVE | N | N065-00-1/412 | Store - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17365 | ACTIVE | N | N065-00-1/412 | Store - Station Building - Woodside Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9109 | ACTIVE | N | N065-00-1/416 | Toilet: Male - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17366 | ACTIVE | N | N065-00-1/416 | Toilet: Male - Station Building - Woodside Park Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - White Foam Insulation | | | | | |
| 17367 | ACTIVE | N | N065-00-1/416 | Toilet: Male - Station Building - Woodside Park Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Boxing: Cream Gloss Paint. Thickness 0.40mm : Analysis 4.59% | | | | N | N |
| 19106 | ACTIVE | N | N065-00-1/416/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Woodside Park Stn | Void | Asbestos | No Access: Presumed | | | | Above Wood Ceiling | | | | YES | |
| 9110 | ACTIVE | N | N065-00-1/426 | Toilet: Female - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17368 | ACTIVE | N | N065-00-1/426 | Toilet: Female - Station Building - Woodside Park Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - White Foam Insulation | | | | | |
| 9111 | ACTIVE | N | N065-00-1/427 | Toilet: Female - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17370 | ACTIVE | N | N065-00-1/427 | Toilet: Female - Station Building - Woodside Park Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - White Foam Insulation | | | | | |
| 17369 | ACTIVE | N | N065-00-1/427/FLR-01 | Floor - 1 - Toilet - Station Building - Woodside Park Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Wooden floor | | | | | YES |
| 9112 | ACTIVE | N | N065-00-1/428 | Toilet: Male - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N065-00 - Station Building - Woodside Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|-------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 19107 | ACTIVE | N | N065-00-1/428 | Toilet: Male - Station Building - Woodside Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9113 | ACTIVE | N | N065-00-1/436 | Waiting Room - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17371 | ACTIVE | N | N065-00-1/436 | Waiting Room - Station Building - Woodside Park Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - White Foam Insulation | | | | | |
| 9114 | ACTIVE | N | N065-00-1/437 | Waiting Room - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17372 | ACTIVE | N | N065-00-1/437 | Waiting Room - Station Building - Woodside Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9115 | ACTIVE | N | N065-00-1/438 | Waiting Room - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17373 | ACTIVE | N | N065-00-1/438 | Waiting Room - Station Building - Woodside Park Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - White Foam Insulation | | | | | |
| 19108 | ACTIVE | N | N065-00-1/438/FLR-01 | Floor - 1 - Waiting Room - Station Building - Woodside Park Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Wooden floor | | | | | YES |
| 9116 | ACTIVE | N | N065-00-1/451 | Tenancy - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17993 | ACTIVE | N | N065-00-1/451 | Tenancy - Station Building - Woodside Park Stn | Roofing Tiles | Asbestos | Surveyed – Not Detected | | | | Roofing Felt to Roof of Tenancy | | | | | |
| 17374 | ACTIVE | N | N065-00-1/451 | Tenancy - Station Building - Woodside Park Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Tenancy | | | | | |
| 9117 | ACTIVE | N | N065-00-1/661 | Switch Room - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42687 | INACTIVE | N | N065-00-1/661 | Switch Room - Station Building - Woodside Park Stn | Cable Duct: Other | Asbestos | Presumed | | | | Wall 1 3 x 60 | | | | N | N |
| 17375 | INACTIVE | N | N065-00-1/661 | Switch Room - Station Building - Woodside Park Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Iron Clad Isolators - Insulation Inside Arc chutes have been replaced in box serial no 00185829, leave 8no containing asbestos; | | 8 | | N | N |
| 42689 | INACTIVE | N | N065-00-1/661 | Switch Room - Station Building - Woodside Park Stn | Cable Duct: Other | Asbestos | Presumed | | | | W2 2 X 60 | | | | N | N |
| 17377 | ACTIVE | N | N065-00-1/661 | Switch Room - Station Building - Woodside Park Stn | Cable Duct: Other | Asbestos | Presumed | | | | Cable Ducts | | 5 | | | |
| 17378 | ACTIVE | N | N065-00-1/661 | Switch Room - Station Building - Woodside Park Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Cream Gloss Paint. Thickness 0.36mm : Analysis 5.24% | | | | N | N |



Hazardous Material Asset Register - Summary



N065-00 - Station Building - Woodside Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 19109 | ACTIVE | N | N065-00-1/661/CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - Woodside Park Stn | Void | Asbestos | No Access: Presumed | | | | Above Fibreboard | | | | YES | |
| 17376 | ACTIVE | N | N065-00-1/661/CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - Woodside Park Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Fibreboard | | | | | |
| 42688 | ACTIVE | N | N065-00-1/661/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Woodside Park Stn | Isolator Switches | Asbestos | Presumed | | | | Wall 1 4x Isolators presumed to contain asbestos insulating materials within. (1 x 100amps & 3x 60amps) Arc chutes have been replaced in box serial no 00185829, leaving 8no containing asbestos; Unknown which wall this box is on | | 4 | | N | N |
| 42690 | ACTIVE | N | N065-00-1/661/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Woodside Park Stn | Isolator Switches | Asbestos | Presumed | | | | Wall 2 - 3x Isolators presumed to contain asbestos insulating materials within. (1x 100amps & 2x 60amps) Arc chutes have been replaced in box serial no 00185829, leaving 8no containing asbestos; Unknown which wall this box is on | | 3 | | N | N |
| 42691 | ACTIVE | N | N065-00-1/661/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Woodside Park Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Wall 2 x Transformer box presumed to contain asbestos insulating materials within. | | 1 | | N | N |
| 42693 | ACTIVE | N | N065-00-1/661/WAL-005 | Wall: Internal - 5 - Switch Room - Station Building - Woodside Park Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Wall 5 - 3x Transformer boxes presumed asbestos insulating materials within | | 3 | | N | N |
| 42692 | ACTIVE | N | N065-00-1/661/WAL-005 | Wall: Internal - 5 - Switch Room - Station Building - Woodside Park Stn | Isolator Switches | Asbestos | Presumed | | | | Wall 5 - 1x 30amp Isolator. Presumed asbestos insulating materials within. Arc chutes have been replaced in box serial no 00185829, leaving 8no containing asbestos; Unknown which wall this box is on | | 1 | | N | N |
| 9118 | ACTIVE | N | N065-00-1/732 | CER - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17381 | ACTIVE | N | N065-00-1/732/CLG-01 | Ceiling: Solid - 1 - CER - Station Building - Woodside Park Stn | Void | Asbestos | No Access: Presumed | | | | Above False Ceiling | | | | YES | |
| 17380 | ACTIVE | N | N065-00-1/732/CLG-01 | Ceiling: Solid - 1 - CER - Station Building - Woodside Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 17379 | ACTIVE | N | N065-00-1/732/FLR-01 | Floor - 1 - CER - Station Building - Woodside Park Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Rubber Tiles | | | | | YES |
| 9119 | ACTIVE | N | N065-00-1/746 | SCR - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17994 | ACTIVE | N | N065-00-1/746 | SCR - Station Building - Woodside Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N065-00 - Station Building - Woodside Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 9120 | ACTIVE | N | N065-00-1/901 | Disused Room - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19110 | ACTIVE | N | N065-00-1/901/CLG-01 | Ceiling: Solid - 1 - Disused Room - Station Building - Woodside Park Stn | Void | Asbestos | No Access: Presumed | | | | Above Wood, Corrugated Steel | | | | YES | |
| 9121 | ACTIVE | N | N065-00-1/951 | Disused Room - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17382 | ACTIVE | N | N065-00-1/951/CLG-01 | Ceiling: Solid - 1 - Disused Room - Station Building - Woodside Park Stn | Void | Asbestos | No Access: Presumed | | | | Above Concrete, Fibreboard | | | | YES | |
| 9122 | ACTIVE | N | N065-00-2/951 | Disused Room - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17383 | ACTIVE | N | N065-00-2/951 | Disused Room - Station Building - Woodside Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9123 | ACTIVE | N | N065-00-A/601 | Stairs: Linear - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17384 | ACTIVE | N | N065-00-A/601 | Stairs: Linear - Station Building - Woodside Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9124 | ACTIVE | N | N065-00-A/602 | Stairs: Linear - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17385 | ACTIVE | N | N065-00-A/602 | Stairs: Linear - Station Building - Woodside Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9125 | ACTIVE | N | N065-00-A/603 | Stairs: Linear - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19111 | ACTIVE | N | N065-00-A/603 | Stairs: Linear - Station Building - Woodside Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9126 | ACTIVE | N | N065-00-A/604 | Stairs: Linear - Station Building - Woodside Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17995 | ACTIVE | N | N065-00-A/604 | Stairs: Linear - Station Building - Woodside Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 17386 | ACTIVE | N | N065-00-A/636 | Overbridge - Station Building - Woodside Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N067-00 - Station Building - West Finchley Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|--------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 9127 | ACTIVE | N | N067-00-1/001 | Booking Hall - Station Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20139 | ACTIVE | N | N067-00-1/001 | Booking Hall - Station Building - West Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9128 | ACTIVE | N | N067-00-1/011 | Ticket Office - Station Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20140 | ACTIVE | N | N067-00-1/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - West Finchley Stn | Void | Asbestos | No Access: Presumed | | | | Beneath False Floor | | | | | YES |
| 9129 | ACTIVE | N | N067-00-1/021 | POM - Station Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20141 | ACTIVE | N | N067-00-1/021/FLR-01 | Floor - 1 - POM - Station Building - West Finchley Stn | Void | Asbestos | No Access: Presumed | | | | Beneath False Floor | | | | | YES |
| 9130 | ACTIVE | N | N067-00-1/031 | Mess Room - Station Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19281 | ACTIVE | N | N067-00-1/031 | Mess Room - Station Building - West Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 20142 | ACTIVE | N | N067-00-1/031 | Mess Room - Station Building - West Finchley Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - Insulation Foam Board | | | | | |
| 9131 | ACTIVE | N | N067-00-1/036 | Toilet: Unisex - Station Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20143 | ACTIVE | N | N067-00-1/036 | Toilet: Unisex - Station Building - West Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9132 | ACTIVE | N | N067-00-1/081 | Lobby - Station Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20144 | ACTIVE | N | N067-00-1/081/FLR-01 | Floor - 1 - Lobby - Station Building - West Finchley Stn | Void | Asbestos | No Access: Presumed | | | | Beneath False Floor | | | | | YES |
| 9133 | ACTIVE | N | N067-00-1/261 | Platform 1 - Northbound Fast - Station Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20145 | ACTIVE | N | N067-00-1/261 | Platform 1 - Northbound Fast - Station Building - West Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9134 | ACTIVE | N | N067-00-1/262 | Platform 2 - Southbound Fast - Station Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N067-00 - Station Building - West Finchley Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 19282 | ACTIVE | N | N067-00-1/262 | Platform 2 - Southbound Fast - Station Building - West Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9135 | ACTIVE | N | N067-00-1/281 | Station Supervisor Office - Station Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20147 | ACTIVE | N | N067-00-1/281 | Station Supervisor Office - Station Building - West Finchley Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 20146 | ACTIVE | N | N067-00-1/281 | Station Supervisor Office - Station Building - West Finchley Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - Insulation Foam Board | | | | | |
| 9136 | ACTIVE | N | N067-00-1/401 | Bin Store - Station Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20195 | ACTIVE | N | N067-00-1/401 | Bin Store - Station Building - West Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9137 | ACTIVE | N | N067-00-1/406 | Store - Station Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20196 | ACTIVE | N | N067-00-1/406 | Store - Station Building - West Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9138 | ACTIVE | N | N067-00-1/411 | Store - Station Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20197 | ACTIVE | N | N067-00-1/411 | Store - Station Building - West Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9139 | ACTIVE | N | N067-00-1/412 | Store - Station Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20198 | ACTIVE | N | N067-00-1/412 | Store - Station Building - West Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9140 | ACTIVE | N | N067-00-1/416 | Toilet: Male - Station Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20199 | ACTIVE | N | N067-00-1/416 | Toilet: Male - Station Building - West Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9141 | ACTIVE | N | N067-00-1/426 | Toilet: Female - Station Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20200 | ACTIVE | N | N067-00-1/426 | Toilet: Female - Station Building - West Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N067-00 - Station Building - West Finchley Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9142 | ACTIVE | N | N067-00-1/427 | Toilet: Male - Station Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20201 | ACTIVE | N | N067-00-1/427 | Toilet: Male - Station Building - West Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9143 | ACTIVE | N | N067-00-1/436 | Waiting Room - Station Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20202 | ACTIVE | N | N067-00-1/436 | Waiting Room - Station Building - West Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9144 | ACTIVE | N | N067-00-1/437 | Waiting Room - Station Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20203 | ACTIVE | N | N067-00-1/437 | Waiting Room - Station Building - West Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9145 | ACTIVE | N | N067-00-1/551 | Yard - Station Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20204 | ACTIVE | N | N067-00-1/551 | Yard - Station Building - West Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9146 | ACTIVE | N | N067-00-1/552 | Yard - Station Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20205 | ACTIVE | N | N067-00-1/552 | Yard - Station Building - West Finchley Stn | Cement Troughing | Asbestos | Removed | | | | Outside Station 800mm long Cable Troughing. This area was re-inspected in 2020 and the troughing could not be found. It is believed to have been removed by the asbestos surveyor | | | | | |
| 9147 | ACTIVE | N | N067-00-1/661 | Switch Room - Station Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20206 | ACTIVE | N | N067-00-1/661 | Switch Room - Station Building - West Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9148 | ACTIVE | N | N067-00-1/731 | CER - Station Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20208 | ACTIVE | N | N067-00-1/731 | CER - Station Building - West Finchley Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 20207 | ACTIVE | N | N067-00-1/731/FLR-01 | Floor - 1 - CER - Station Building - West Finchley Stn | Void | Asbestos | No Access: Presumed | | | | Beneath False Floor | | | | | YES |
| 9149 | ACTIVE | N | N067-00-1/746 | SCR - Station Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N067-00 - Station Building - West Finchley Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|---------------------|-------------|------------|-------------|---------------------|-------------------|
| 20209 | ACTIVE | N | N067-00-1/746 | SCR - Station Building - West Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9150 | ACTIVE | N | N067-00-1/776 | Plant Room - Station Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20210 | ACTIVE | N | N067-00-1/776 | Plant Room - Station Building - West Finchley Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed | | | | | |
| 9151 | ACTIVE | N | N067-00-A/601 | Stairs: Linear - Station Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19290 | ACTIVE | N | N067-00-A/601 | Stairs: Linear - Station Building - West Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9152 | ACTIVE | N | N067-00-A/602 | Stairs: Linear - Station Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20211 | ACTIVE | N | N067-00-A/602 | Stairs: Linear - Station Building - West Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 20212 | ACTIVE | N | N067-00-A/636 | Overbridge - Station Building - West Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |

N068-02 - Depot Building - West Finchley To Finchley Central

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 9168 | ACTIVE | N | N068-02-1/417 | Workshop - Depot Building - West Finchley To Finchley Central | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N071-00 - Station Building - Finchley Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|---------------------------|-------------|------------|-------------|---------------------|-------------------|
| 9169 | ACTIVE | N | N071-00-1/001 | Booking Hall - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24313 | ACTIVE | N | N071-00-1/001/CLG-01 | Ceiling: Solid - 1 - Booking Hall - Station Building - Finchley Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Wood above false ceiling | | | | Yes | |
| 24769 | ACTIVE | N | N071-00-1/001/CLG-02 | Ceiling: Solid - 2 - Booking Hall - Station Building - Finchley Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Wood above false ceiling | | | | Yes | |
| 24317 | ACTIVE | N | N071-00-1/001/FLR-01 | Floor - 1 - Booking Hall - Station Building - Finchley Central Stn | Void | Asbestos | No Access: Presumed | | | | Beneath computer flooring | | | | | Yes |



Hazardous Material Asset Register - Summary



N071-00 - Station Building - Finchley Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 24848 | ACTIVE | N | N071-00-1/001/FLR-02 | Floor - 2 - Booking Hall - Station Building - Finchley Central Stn | Void | Asbestos | No Access: Presumed | | | | Beneath computer flooring | | | | | Yes |
| 9170 | ACTIVE | N | N071-00-1/011 | Ticket Office - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24850 | ACTIVE | N | N071-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Finchley Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Brick, plastic; timber rafters, felt; supalux boarding W2 | | | | Yes | |
| 24849 | ACTIVE | N | N071-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Finchley Central Stn | | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9171 | ACTIVE | N | N071-00-1/021 | POM - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24852 | ACTIVE | N | N071-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Finchley Central Stn | | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 24853 | ACTIVE | N | N071-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Finchley Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Timber Rafters above false ceiling | | | | Yes | |
| 24851 | ACTIVE | N | N071-00-1/021/FLR-01 | Floor - 1 - POM - Station Building - Finchley Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | PVC Cable, Metal Cable Tray beneath Tiles, Computer Flooring | | | | | Yes |
| 9172 | ACTIVE | N | N071-00-1/031 | Mess Room - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24855 | ACTIVE | N | N071-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Finchley Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Timber Rafters, Conduit, Felt, Supalux Board above false ceiling | | | | Yes | |
| 24854 | ACTIVE | N | N071-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Finchley Central Stn | | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9173 | ACTIVE | N | N071-00-1/036 | Toilet: Unisex - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24857 | ACTIVE | N | N071-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Finchley Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Timber Rafters, Brick, Block, Rock Wool Pipe Lagging, Copper Pipe above false ceiling | | | | Yes | |
| 24856 | ACTIVE | N | N071-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Finchley Central Stn | | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9174 | ACTIVE | N | N071-00-1/081 | Lobby - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N071-00 - Station Building - Finchley Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 24858 | ACTIVE | N | N071-00-1/081/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Finchley Central Stn | Void | Asbestos | No Access: Presumed | | | | Walls, Brick, Plaster above false ceiling | | | | Yes | |
| 9175 | ACTIVE | N | N071-00-1/082 | Lobby - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24859 | ACTIVE | N | N071-00-1/082 | Lobby - Station Building - Finchley Central Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Lift Shaft - Not Surveyed - New | | | | | |
| 24860 | ACTIVE | N | N071-00-1/136 | Lift Shaft - Station Building - Finchley Central Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Lift Shaft - Not Surveyed - New | | | | | |
| 24861 | ACTIVE | N | N071-00-1/137 | Lift Shaft - Station Building - Finchley Central Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Lift Shaft - Not Surveyed - New | | | | | |
| 9176 | ACTIVE | N | N071-00-1/236 | Passage - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24863 | ACTIVE | N | N071-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Finchley Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Timber rafters above false ceiling | | | | Yes | |
| 24862 | ACTIVE | N | N071-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Finchley Central Stn | | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 25473 | ACTIVE | N | N071-00-1/236/FLR-01 | Floor - 1 - Passage - Station Building - Finchley Central Stn | Void | Asbestos | No Access: Presumed | | | | Beneath computer flooring | | | | | Yes |
| 9177 | ACTIVE | N | N071-00-1/291 | Office - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24864 | ACTIVE | N | N071-00-1/291 | Office - Station Building - Finchley Central Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - white foam insulation | | 1 | | | |
| 24865 | ACTIVE | N | N071-00-1/291/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Finchley Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plasterboard, Walls Brick, Plaster; Air Con, PVC Cables, Conduit above false ceiling | | | | Yes | |
| 9178 | ACTIVE | N | N071-00-1/301 | GSM Office - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 25474 | ACTIVE | N | N071-00-1/301/CLG-01 | Ceiling: Solid - 1 - GSM Office - Station Building - Finchley Central Stn | Void | Asbestos | No Access: Presumed | | | | Above Plasterboard | | | | Yes | |
| 24866 | ACTIVE | N | N071-00-1/301/CLG-01 | Ceiling: Solid - 1 - GSM Office - Station Building - Finchley Central Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 9179 | ACTIVE | N | N071-00-1/351 | Mess Room - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N071-00 - Station Building - Finchley Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 24868 | ACTIVE | N | N071-00-1/351 | Mess Room - Station Building - Finchley Central Stn | Bitumen | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel under Sink | | 1 | | | |
| 24867 | ACTIVE | N | N071-00-1/351/FLR-01 | Floor - 1 - Mess Room - Station Building - Finchley Central Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Vinyl Flooring | | | | | |
| 9180 | ACTIVE | N | N071-00-1/411 | Store - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24417 | ACTIVE | N | N071-00-1/411/CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Finchley Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Timber joints above false ceiling | | | | Yes | |
| 24869 | ACTIVE | N | N071-00-1/411/CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Finchley Central Stn | | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9181 | ACTIVE | N | N071-00-1/412 | Store - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 25475 | ACTIVE | N | N071-00-1/412/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Finchley Central Stn | Void | Asbestos | No Access: Presumed | | | | Above false ceiling | | | | Yes | |
| 24870 | ACTIVE | N | N071-00-1/412/FLR-01 | Floor - 1 - Store - Station Building - Finchley Central Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Vinyl Flooring | | | | | |
| 9182 | ACTIVE | N | N071-00-1/416 | Toilet: Unisex - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24871 | ACTIVE | N | N071-00-1/416/FLR-01 | Floor - 1 - Toilet - Station Building - Finchley Central Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Vinyl Flooring | | | | | |
| 9183 | ACTIVE | N | N071-00-1/601 | Stairs: Linear - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24872 | ACTIVE | N | N071-00-1/601/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Finchley Central Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Roof Sheets, Metal Boxing | | | | Yes | |
| 9184 | ACTIVE | N | N071-00-1/602 | Stairs: Linear - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24873 | ACTIVE | N | N071-00-1/602/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Finchley Central Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Roof Sheets | | | | Yes | |
| 24419 | ACTIVE | N | N071-00-1/636 | Overbridge - Station Building - Finchley Central Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Cream Oil Based Paint - Support Struts. Thickness 1.04mm: Analysis 7.5% | | | | N | N |
| 24320 | ACTIVE | N | N071-00-1/636 | Overbridge - Station Building - Finchley Central Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Walls - Green Oil Based Paint. Thickness 1.24mm: Analysis 8.4% | | | | N | N |



Hazardous Material Asset Register - Summary



N071-00 - Station Building - Finchley Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|--------------------------------|--|-------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 24955 | ACTIVE | N | N071-00-1/636 | Overbridge - Station Building - Finchley Central Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Blue/Grey Oil Based Paint - Side Exterior Steel Work. Thickness 1.75mm: Analysis 11.1% | | | | N | N |
| 24954 | ACTIVE | N | N071-00-1/636/CLG-01 | Ceiling: Solid - 1 - Overbridge - Station Building - Finchley Central Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Roof Sheets | | | | Yes | |
| 24874 | ACTIVE | N | N071-00-1/636/FLR-01 | Floor - 1 - Overbridge - Station Building - Finchley Central Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Timber Decking | | | | | Yes |
| 9185 | ACTIVE | N | N071-00-1/661 | Switch Cupboard - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24956 | ACTIVE | N | N071-00-1/661 | Switch Cupboard - Station Building - Finchley Central Stn | Isolator Switches | Asbestos | Presumed | | | | 3x Switch Box 100,200amps. Presumed asbestos asbestos materials within. | | 3 | | | |
| 69843 | ACTIVE | N | N071-00-1/661/FLR-01 80915595 | Floor - 1 - Switch Cupboard - Station Building - Finchley Central Stn Floor | Other Boarding | Asbestos | Strongly Presumed | | | | Bitumen Cable Duct to Floor | | 1 | | | |
| 44896 | ACTIVE | N | N071-00-1/667 | Switch - Station Building - Finchley Central Stn | Cable Duct: Other | Asbestos | Presumed | | | | Cable ducting 1m below ground running from 1/667 switch room to cable pit within hard standing in front of gas locker 1/636 | | | | N | N |
| 69844 | ACTIVE | N | N071-00-1/667/WAL-003 80915600 | Wall: Internal - 3 - Switch - Station Building - Finchley Central Stn Wall: Internal | Isolator Switches | Asbestos | Presumed | | | | 1x Switch Box 300amps. Presumed asbestos insulating materials within. | | 1 | | | |
| 9186 | ACTIVE | N | N071-00-2/081 | Lobby - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24959 | ACTIVE | N | N071-00-2/081/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Finchley Central Stn | | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 24960 | ACTIVE | N | N071-00-2/081/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Finchley Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Brickwork Arch above false ceiling | | | | Yes | |
| 9187 | ACTIVE | N | N071-00-2/082 | Lobby - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9188 | ACTIVE | N | N071-00-2/083 | Lobby - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24961 | ACTIVE | N | N071-00-2/083 | Lobby - Station Building - Finchley Central Stn | | Asbestos | Surveyed – Not Detected | | | | Supalux Cupboard | | | | | |
| 9189 | ACTIVE | N | N071-00-2/084 | Lobby - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24962 | ACTIVE | N | N071-00-2/084 | Lobby - Station Building - Finchley Central Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed | | | | | |



Hazardous Material Asset Register - Summary



N071-00 - Station Building - Finchley Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|------------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 9190 | ACTIVE | N | N071-00-2/131 | LMR - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24963 | ACTIVE | N | N071-00-2/131 | LMR - Station Building - Finchley Central Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New | | | | | |
| 9191 | ACTIVE | N | N071-00-2/132 | LMR - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24964 | ACTIVE | N | N071-00-2/132 | LMR - Station Building - Finchley Central Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New | | | | | |
| 9192 | ACTIVE | N | N071-00-2/261 | Platform 1 - Northbound Main - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24966 | ACTIVE | N | N071-00-2/261 | Platform 1 - Northbound Main - Station Building - Finchley Central Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Southbound end - Main Distribution Framework - Insulation within | | | | N | N |
| 24968 | ACTIVE | N | N071-00-2/261 | Platform 1 - Northbound Main - Station Building - Finchley Central Stn | Lead/Leading | Lead Paint/Lead | Known | | | | 4 x Support Struts to Stairs. Thickness 0.62mm: Analysis 7.9% | | | | N | N |
| 24967 | ACTIVE | N | N071-00-2/261 | Platform 1 - Northbound Main - Station Building - Finchley Central Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Main Support to Overbridge Cream Oil Based Paint. Thickness 0.30mm: Analysis 4.6% | | | | N | N |
| 24965 | ACTIVE | N | N071-00-2/261/CLG-01 | Ceiling: Solid - 1 - Platform 1 - Station Building - Finchley Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above Wood Tongue & Groove | | | | Yes | |
| 9193 | ACTIVE | N | N071-00-2/262 | Platform 2 - Northbound Fast - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24970 | ACTIVE | N | N071-00-2/262 | Platform 2 - Northbound Fast - Station Building - Finchley Central Stn | Lead/Leading | Lead Paint/Lead | Known | | | | 4 x Support Struts to Stairs Cream Oil Based Paint. Thickness 0.62mm: Analysis 7.9% | | | | N | N |
| 25484 | ACTIVE | N | N071-00-2/262 | Platform 2 - Northbound Fast - Station Building - Finchley Central Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Main Support to Overbridge Cream Oil Based Paint. Thickness 0.30mm: Analysis 4.6% | | | | N | N |
| 24969 | ACTIVE | N | N071-00-2/262/CLG-01 | Ceiling: Solid - 1 - Platform 2 - Station Building - Finchley Central Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Roofing Sheets | | | | Yes | |
| 9194 | ACTIVE | N | N071-00-2/263 | Platform 3 - Southbound Fast - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24973 | ACTIVE | N | N071-00-2/263 | Platform 3 - Southbound Fast - Station Building - Finchley Central Stn | Debris: Cement | Asbestos | Removed | | | | Embankment behind Platform 3 - Chrysotile Cement debris (1-2m²) The troughing above was removed by the LARC Pectel. This area was re-inspected and there was no visible surface troughing present. | | | | | |



Hazardous Material Asset Register - Summary



N071-00 - Station Building - Finchley Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 24971 | ACTIVE | N | N071-00-2/263/CLG-01 | Ceiling: Solid - 1 - Platform 3 - Station Building - Finchley Central Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Roofing Sheets | | | | Yes | |
| 9195 | ACTIVE | N | N071-00-2/281 | Mess Room - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24974 | ACTIVE | N | N071-00-2/281/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Finchley Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plasterboard, Walls Brick, Concrete, PVC All Cables, Rock Wool Pipe Lagging above false ceiling | | | | Yes | |
| 25485 | ACTIVE | N | N071-00-2/281/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Finchley Central Stn | | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9196 | ACTIVE | N | N071-00-2/316 | Locker Room - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24975 | ACTIVE | N | N071-00-2/316/CLG-01 | Ceiling: Suspended - 1 - Locker Room - Station Building - Finchley Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Brickwork Arches, Conduit, PVC Cables above false ceiling | | | | Yes | |
| 9197 | ACTIVE | N | N071-00-2/317 | Locker Room - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24977 | ACTIVE | N | N071-00-2/317/CLG-01 | Ceiling: Solid - 1 - Locker Room - Station Building - Finchley Central Stn | Void | Asbestos | No Access: Presumed | | | | Above false ceiling | | | | Yes | |
| 24976 | ACTIVE | N | N071-00-2/317/FLR-01 | Floor - 1 - Locker Room - Station Building - Finchley Central Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Lino, Concrete Brick | | | | | |
| 9198 | ACTIVE | N | N071-00-2/341 | Mess Room - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 25486 | ACTIVE | N | N071-00-2/341/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Finchley Central Stn | | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 24978 | ACTIVE | N | N071-00-2/341/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Finchley Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plasterboard, Walls Brick, Concrete, PVC All Cables, Rock Wool Pipe Lagging above false ceiling | | | | Yes | |
| 9199 | ACTIVE | N | N071-00-2/411 | Store - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24979 | ACTIVE | N | N071-00-2/411 | Store - Station Building - Finchley Central Stn | | Asbestos | Surveyed – Not Detected | | | | Wall - Supalux Panel by Window | | | | | |
| 9200 | ACTIVE | N | N071-00-2/412 | Store - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N071-00 - Station Building - Finchley Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9201 | ACTIVE | N | N071-00-2/413 | Store - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 46440 | ACTIVE | N | N071-00-2/413 | Store - Station Building - Finchley Central Stn | Plaster | Asbestos | Sampled – Not Detected | | | | Plaster to walls around windows, Platform Level | | | R670351 | N | N |
| 46439 | ACTIVE | N | N071-00-2/413 | Store - Station Building - Finchley Central Stn | Mastic | Asbestos | Sampled – Not Detected | | | | Mastic to frame (small window), Platform Level | | | R670351 | N | N |
| 46438 | ACTIVE | N | N071-00-2/413 | Store - Station Building - Finchley Central Stn | Mastic | Asbestos | Sampled – Not Detected | | | | Mastic between sill and frame (small window), Platform Level | | | R670351 | N | N |
| 46436 | ACTIVE | N | N071-00-2/413 | Store - Station Building - Finchley Central Stn | Mastic | Asbestos | Sampled – Not Detected | | | | Putty/mastic to (large) window frame (nearest window), Platform Level | | | R670351 | N | N |
| 46437 | ACTIVE | N | N071-00-2/413 | Store - Station Building - Finchley Central Stn | Mastic | Asbestos | Sampled – Not Detected | | | | Putty/mastic to (large) window frame and glass, Platform Level | | | R670351 | N | N |
| 46435 | ACTIVE | N | N071-00-2/413 | Store - Station Building - Finchley Central Stn | Mastic | Asbestos | Sampled – Not Detected | | | | Putty/mastic to (large) window frame, Platform Level | | | R670351 | N | N |
| 9202 | ACTIVE | N | N071-00-2/414 | Store - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9203 | ACTIVE | N | N071-00-2/416 | Toilet: Female - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24980 | ACTIVE | N | N071-00-2/416 | Toilet: Female - Station Building - Finchley Central Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - white foam backing | | 1 | | | |
| 9204 | ACTIVE | N | N071-00-2/417 | Toilet: Male - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24981 | ACTIVE | N | N071-00-2/417 | Toilet: Male - Station Building - Finchley Central Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - white foam backing | | 1 | | | |
| 9205 | ACTIVE | N | N071-00-2/426 | Toilet: Unisex - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9206 | ACTIVE | N | N071-00-2/427 | Toilet: Unisex - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 24982 | ACTIVE | N | N071-00-2/427/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Finchley Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Pipe lagging above plaster; hatch - wooden rafters | | | | Yes | |
| 9207 | ACTIVE | N | N071-00-2/436 | Waiting Room - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 25061 | ACTIVE | N | N071-00-2/436 | Waiting Room - Station Building - Finchley Central Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - white foam backing | | 1 | | | |



Hazardous Material Asset Register - Summary



N071-00 - Station Building - Finchley Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 25060 | ACTIVE | N | N071-00-2/436/FLR-01 | Floor - 1 - Waiting Room - Station Building - Finchley Central Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Vinyl flooring | | | | | |
| 9208 | ACTIVE | N | N071-00-2/437 | Waiting Room - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 25062 | ACTIVE | N | N071-00-2/437/FLR-01 | Floor - 1 - Waiting Room - Station Building - Finchley Central Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Vinyl flooring | | | | | |
| 9209 | ACTIVE | N | N071-00-2/438 | Waiting Room - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 25063 | ACTIVE | N | N071-00-2/438 | Waiting Room - Station Building - Finchley Central Stn | LUL Heaters | Asbestos | Removed | | | | Old Heater by Door | | 1 | | N | N |
| 9210 | ACTIVE | N | N071-00-2/661 | Switch Room - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 25064 | ACTIVE | N | N071-00-2/661 | Switch Room - Station Building - Finchley Central Stn | | Asbestos | Surveyed – Not Detected | | | | Supalux Cladding | | | | | |
| 25066 | ACTIVE | N | N071-00-2/661/CLG-01 80915829 | Ceiling: Solid - 1 - Switch Room - Station Building - Finchley Central Stn Ceiling: Solid | Void | Asbestos | No Access: Presumed | | | | Above false ceiling | | | | Yes | |
| 25065 | ACTIVE | N | N071-00-2/661/CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - Finchley Central Stn | | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding | | | | | |
| 25067 | ACTIVE | N | N071-00-2/661/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Finchley Central Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch box x 1 - 30 amp, W1. Presumed asbestos insulating materials within. | | 1 | | N | N |
| 42700 | ACTIVE | N | N071-00-2/661/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Finchley Central Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Wall 2 - 1 x Transformer Box presumed to contain asbestos insulating materials within | | 1 | | N | N |
| 46184 | ACTIVE | N | N071-00-2/661/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Finchley Central Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 3x Transformer boxes. Presumed asbestos insulation materials within. | | 3 | | | |
| 25068 | ACTIVE | N | N071-00-2/661/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Finchley Central Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch boxes x 8 - 5 x 60amp, 2 x 100 amp, 1 x 200amp. Presumed insulating materials within. | | 8 | | N | N |
| 9211 | ACTIVE | N | N071-00-2/662 | Switch Room - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 25069 | ACTIVE | N | N071-00-2/662 | Switch Room - Station Building - Finchley Central Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - white foam backing | | 1 | | | |



Hazardous Material Asset Register - Summary



N071-00 - Station Building - Finchley Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 25070 | ACTIVE | N | N071-00-2/662/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Finchley Central Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1x Transformer boxes - presumed asbestos within (1x modern transformer is adjacent to old transformer. | | 2 | | N | N |
| 42701 | ACTIVE | N | N071-00-2/662/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Finchley Central Stn | LUL Heaters | Asbestos | Strongly Presumed | | | | HEATER ON w2 Presumed asbestos panel behind heater. | | 1 | | | |
| 24323 | ACTIVE | N | N071-00-2/662/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Finchley Central Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 5x Switch boxes 1 x 30 amps, 3 x 60 amps, 1 x 100 amps. Presumed asbestos insulating materials within | | 5 | | N | N |
| 9212 | ACTIVE | N | N071-00-2/666 | Switch Cupboard - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 25071 | ACTIVE | N | N071-00-2/666 | Switch Cupboard - Station Building - Finchley Central Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 1x Switch Box 60amps. Presumed asbestos insulating materials within. | | 1 | | N | N |
| 9213 | ACTIVE | N | N071-00-2/667 | Switch Cupboard - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 25072 | ACTIVE | N | N071-00-2/667 | Switch Cupboard - Station Building - Finchley Central Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New | | | | | |
| 9214 | ACTIVE | N | N071-00-2/731 | CER - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9215 | ACTIVE | N | N071-00-2/746 | SCR - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9216 | ACTIVE | N | N071-00-2/776 | Store - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 25574 | ACTIVE | N | N071-00-2/776 | Store - Station Building - Finchley Central Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | LTB Heater - No Asbestos Detected (Foam) | | 1 | | | |
| 25075 | ACTIVE | N | N071-00-2/776/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Finchley Central Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 25076 | ACTIVE | N | N071-00-2/776/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Finchley Central Stn | Void | Asbestos | No Access: Presumed | | | | Above false ceiling | | | | Yes | |
| 9217 | ACTIVE | N | N071-00-2/801 | Meeting Room - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 69845 | ACTIVE | N | N071-00-2/801 | Meeting Room - Station Building - Finchley Central Stn | Other Boarding | Asbestos | Strongly Presumed | | | | Bitumen Acoustic Sink and Drainer Pads | | 2 | | | |
| 25077 | ACTIVE | N | N071-00-2/801/CLG-01 | Ceiling: Solid - 1 - Meeting Room - Station Building - Finchley Central Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |



Hazardous Material Asset Register - Summary



N071-00 - Station Building - Finchley Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 25575 | ACTIVE | N | N071-00-2/801/CLG-01 | Ceiling: Solid - 1 - Meeting Room - Station Building - Finchley Central Stn | Void | Asbestos | No Access: Presumed | | | | Above false ceiling | | | | Yes | |
| 9218 | ACTIVE | N | N071-00-2/901 | Store - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 25078 | ACTIVE | N | N071-00-2/901/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Finchley Central Stn | Cement Cowlings/ Flues | Asbestos | Strongly Presumed | | | | Flue coming from 2/417 toilet out of wall | | 1 | | N | N |
| 44897 | ACTIVE | N | N071-00-2/901/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Finchley Central Stn | Cement Cowlings/ Flues | Asbestos | Strongly Presumed | | | | Flue coming from 2/417 toilet wall and onto Roof | | 1 | | Y | N |
| 9219 | ACTIVE | N | N071-00-2/902 | Store - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 25079 | ACTIVE | N | N071-00-2/902 | Store - Station Building - Finchley Central Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New | | | | | |
| 9220 | ACTIVE | N | N071-00-2/903 | Store - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 25080 | ACTIVE | N | N071-00-2/903 | Store - Station Building - Finchley Central Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New | | | | | |
| 9221 | ACTIVE | N | N071-00-2/951 | Office - Station Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 25082 | ACTIVE | N | N071-00-2/951 | Office - Station Building - Finchley Central Stn | Bitumen | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel under Sink | | 1 | | | |
| 46214 | ACTIVE | N | N071-00-2/951 | Office - Station Building - Finchley Central Stn | Cement Cowlings/ Flues | Asbestos | Presumed | | | | Cement Cowls on top of roof 2/951. No access to sample | | 4 | | | |
| 25576 | ACTIVE | N | N071-00-2/951/CLG-01 | Ceiling: Solid - 1 - Office - Station Building - Finchley Central Stn | Void | Asbestos | No Access: Presumed | | | | Above false ceiling | | | | Yes | |
| 25081 | ACTIVE | N | N071-00-2/951/FLR-01 | Floor - 1 - Office - Station Building - Finchley Central Stn | Void | Asbestos | Surveyed – Not Detected | | | | Quarry Tiles beneath Carpet Tiles | | | | | Yes |

N072-01 - Signals Building - Finchley Central To East Finchley

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 9225 | ACTIVE | N | N072-01-2/732 | CER - Signals Building - Finchley Central To East Finchley | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N073-00 - Station Building - East Finchley Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------------|--|---------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 9235 | ACTIVE | N | N073-00-1/001 | Booking Hall - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17915 | ACTIVE | N | N073-00-1/001 | Booking Hall - Station Building - East Finchley Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Horizontal Supalux Board above Tenancy & Boswick Gates Housing (Entrance A) | | | | | |
| 20256 | ACTIVE | N | N073-00-1/001/ BAT-001 | Battery: Mimic Control Panel - Booking Hall - Station Building - East Finchley Stn | Cement Cowlings/ Flues | Asbestos | Known | | | | Cement Cowlings on Roof - Staff Offices - South Corner of Building | | | | N | N |
| 9236 | ACTIVE | N | N073-00-1/011 | Ticket Office - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18873 | ACTIVE | N | N073-00-1/011/ CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - East Finchley Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 17190 | ACTIVE | N | N073-00-1/011/ CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - East Finchley Stn | Void | Asbestos | Surveyed – Not Detected | | | | Fibre glass lagged pipes plastic cable; Concrete ceiling galvanised tray works above false ceiling | | | | YES | |
| 17189 | ACTIVE | N | N073-00-1/011/ FLR-01 | Floor - 1 - Ticket Office - Station Building - East Finchley Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Plastic Cables; Metal ducts beneath Computer flooring | | | | | YES |
| 9237 | ACTIVE | N | N073-00-1/021 | POM - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17191 | ACTIVE | N | N073-00-1/021/ FLR-01 | Floor - 1 - POM - Station Building - East Finchley Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Plastic cables, Supalux firebreak to ticket machines, galvanised duct; No access beyond Supalux firebreak under ticket machine beneath Computer flooring | | | | | YES |
| 9238 | ACTIVE | N | N073-00-1/081 | Lobby - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17194 | ACTIVE | N | N073-00-1/081/ CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - East Finchley Stn | Void | Asbestos | Surveyed – Not Detected | | | | Cast iron soil pipe, fibreglass pipe insulation plastic cables, metal vent ducts above false ceiling | | | | YES | |
| 18874 | ACTIVE | N | N073-00-1/081/ CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - East Finchley Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 17192 | ACTIVE | N | N073-00-1/081/ FLR-01 | Floor - 1 - Lobby - Station Building - East Finchley Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal duct work beneath Solid tiled to Rear; Computer tiles to front; Concrete, plastic cable | | | | | YES |
| 17193 | ACTIVE | N | N073-00-1/081/ FLR-02 | Floor - 2 - Lobby - Station Building - East Finchley Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal duct work beneath Solid tiled to Rear; Computer tiles to front; Concrete, plastic cable | | | | | YES |
| 9239 | ACTIVE | N | N073-00-1/201 | Passage - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N073-00 - Station Building - East Finchley Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 17916 | ACTIVE | N | N073-00-1/201 | Passage - Station Building - East Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9240 | ACTIVE | N | N073-00-1/202 | Passage - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17195 | ACTIVE | N | N073-00-1/202 | Passage - Station Building - East Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 18985 | ACTIVE | N | N073-00-1/202 | Passage - Station Building - East Finchley Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Bostwick Gate - Brown Matt Paint. Thickness 0.16mm: Analysis 1.96% | | | | N | N |
| 9241 | ACTIVE | N | N073-00-1/236 | Passage - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17196 | ACTIVE | N | N073-00-1/236 | Passage - Station Building - East Finchley Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Superlux Panels above Electrical Equipment High Level | | | | | |
| 9242 | ACTIVE | N | N073-00-1/237 | Passage - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17197 | ACTIVE | N | N073-00-1/237/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - East Finchley Stn | Void | Asbestos | Surveyed – Not Detected | | | | Cast iron soil pipes, fibre glass insulation on pipes, steel conduit, plastic cables; walls brick; concrete above false ceiling | | | | YES | |
| 18875 | ACTIVE | N | N073-00-1/237/FLR-01 | Floor - 1 - Passage - Station Building - East Finchley Stn | Void | Asbestos | Surveyed – Not Detected | | | | Cable pits, plastic/lead cables, Terracotta ducts beneath false floor | | | | | YES |
| 9243 | ACTIVE | N | N073-00-1/281 | Station Control Room - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17198 | ACTIVE | N | N073-00-1/281 | Station Control Room - Station Building - East Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 70902 | ACTIVE | N | N073-00-1/281 | Station Control Room - Station Building - East Finchley Stn | Lead/Leading | Asbestos | Sampled – Not Detected | | | | Beige matt paint to walls - <0.01% lead content | | | R754601 | | |
| 70904 | ACTIVE | N | N073-00-1/281 | Station Control Room - Station Building - East Finchley Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | White matt paint to ceiling - <0.01% Does not constitute a lead hazard | | | R754601 | | |
| 70899 | ACTIVE | N | N073-00-1/281 | Station Control Room - Station Building - East Finchley Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Beige matt paint to walls - 0.03% Does not constitute a lead hazard | | | R754601 | | |
| 70897 | ACTIVE | N | N073-00-1/281 | Station Control Room - Station Building - East Finchley Stn | Lead/Leading | Lead Paint/Lead | Known | | | | White gloss paint applied to window frames. 1.87% lead content 0.61mm paint thickness | | | R754601 | | |
| 70905 | ACTIVE | N | N073-00-1/281 | Station Control Room - Station Building - East Finchley Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | White matt paint to ceiling - <0.01% Does not constitute a lead hazard | | | R754601 | | |
| 70906 | ACTIVE | N | N073-00-1/281 | Station Control Room - Station Building - East Finchley Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | White gloss paint to horizontal bars to windows <0.01% Does not constitute lead hazard | | | R754601 | | |
| 70907 | ACTIVE | N | N073-00-1/281 | Station Control Room - Station Building - East Finchley Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | White gloss paint to metal conduits - 0.06% Does not constitute a lead hazard | | | R754601 | | |



Hazardous Material Asset Register - Summary



N073-00 - Station Building - East Finchley Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|-------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 70903 | ACTIVE | N | N073-00-1/281 | Station Control Room - Station Building - East Finchley Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Beige matt paint to door and framework - 0.08% Does not constitute a lead hazard | | | R754601 | | |
| 9244 | ACTIVE | N | N073-00-1/311 | Mess Room - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17199 | ACTIVE | N | N073-00-1/311/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - East Finchley Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Ceiling Tiles | | | | | |
| 9245 | ACTIVE | N | N073-00-1/316 | Locker Room - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19410 | ACTIVE | N | N073-00-1/316 | Locker Room - Station Building - East Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9246 | ACTIVE | N | N073-00-1/317 | Locker Room - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17200 | INACTIVE | N | N073-00-1/317/CLG-01 | Ceiling: Solid - 1 - Locker Room - Station Building - East Finchley Stn | No Access | Asbestos | No Access: Presumed | | | | No Asbestos Visible | | | | | |
| 9247 | ACTIVE | N | N073-00-1/332 | Mess Room - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17201 | ACTIVE | N | N073-00-1/332/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - East Finchley Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Ceiling Tiles | | | | | |
| 17202 | ACTIVE | N | N073-00-1/332/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - East Finchley Stn | Void | Asbestos | Surveyed – Not Detected | | | | Fibreboard Residue No Asbestos Detected; Concrete above false ceiling | | | | YES | |
| 18876 | ACTIVE | N | N073-00-1/332/DOR-01 | Door - 1 - Mess Room - Station Building - East Finchley Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel on Door | | | | | |
| 9248 | ACTIVE | N | N073-00-1/333 | Office - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18986 | ACTIVE | N | N073-00-1/333/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - East Finchley Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid above false ceiling | | | | YES | |
| 17203 | ACTIVE | N | N073-00-1/333/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - East Finchley Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Fibreboard | | | | | |
| 9249 | ACTIVE | N | N073-00-1/416 | Toilet: Unisex - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17204 | ACTIVE | N | N073-00-1/416 | Toilet: Unisex - Station Building - East Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N073-00 - Station Building - East Finchley Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 9250 | ACTIVE | N | N073-00-1/417 | Toilet: Unisex - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18877 | ACTIVE | N | N073-00-1/417/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - East Finchley Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 17205 | ACTIVE | N | N073-00-1/417/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - East Finchley Stn | Void | Asbestos | Surveyed – Not Detected | | | | Fibre glass lagged pipe plastic cables metal CMS; Plaster on Solid above false ceiling | | | | YES | |
| 9251 | ACTIVE | N | N073-00-1/451 | Tenancy - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17206 | ACTIVE | N | N073-00-1/451 | Tenancy - Station Building - East Finchley Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - Tenancy | | | | | |
| 9252 | ACTIVE | N | N073-00-1/452 | Tenancy - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17207 | ACTIVE | N | N073-00-1/452 | Tenancy - Station Building - East Finchley Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - Tenancy | | | | | |
| 9253 | ACTIVE | N | N073-00-1/453 | Locker Room - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17917 | ACTIVE | N | N073-00-1/453/CLG-01 | Ceiling: Suspended - 1 - Locker Room - Station Building - East Finchley Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false friends | | | | YES | |
| 9254 | ACTIVE | N | N073-00-1/455 | Tenancy - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17208 | ACTIVE | N | N073-00-1/455/WAL-001 | Wall: Internal - 1 - Tenancy - Station Building - East Finchley Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Isolators. Presumed asbestos insulating materials within | | 2 | | N | N |
| 9255 | ACTIVE | N | N073-00-1/661 | Switch Cupboard - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18488 | ACTIVE | N | N073-00-1/661 | Switch Cupboard - Station Building - East Finchley Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch boxes (4 x 60 amps, 2 x 200 amps) Presumed asbestos insulating materials within | | 6 | | N | N |
| 9256 | ACTIVE | N | N073-00-1/662 | Switch Room - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17209 | ACTIVE | N | N073-00-1/662 | Switch Room - Station Building - East Finchley Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch boxes (7 x 100 amps, 1 x 30 amps, 5 x 60 amps, 1 x 200 amps, 1 x 30 amps) Presumed asbestos insulating materials within, isolations required to inspect internally. | | 14 | | N | N |



Hazardous Material Asset Register - Summary



N073-00 - Station Building - East Finchley Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18940 | ACTIVE | N | N073-00-1/662 | Switch Room - Station Building - East Finchley Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Transformer Box(es) Presumed asbestos insulating materials within, isolations required to inspect internally. | | 4 | | N | N |
| 9257 | ACTIVE | N | N073-00-1/663 | Switch Cupboard - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17210 | ACTIVE | N | N073-00-1/663 | Switch Cupboard - Station Building - East Finchley Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes (3 x 100 amps, 1 x 300 amps, 1 x 200 amps) Presumed asbestos insulating materials within. isolations required to inspect internally. | | 5 | | N | N |
| 9258 | ACTIVE | N | N073-00-1/746 | SCR - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17211 | ACTIVE | N | N073-00-1/746 | SCR - Station Building - East Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9259 | ACTIVE | N | N073-00-1/786 | Service Riser - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18941 | ACTIVE | N | N073-00-1/786 | Service Riser - Station Building - East Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9260 | ACTIVE | N | N073-00-1/801 | Office - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17213 | ACTIVE | N | N073-00-1/801/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - East Finchley Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Fibreboard | | | | | |
| 17214 | ACTIVE | N | N073-00-1/801/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - East Finchley Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid plaster ceiling; Fibre glass lagged pipe above Fibreboard Tile | | 1 | | YES | |
| 17212 | ACTIVE | N | N073-00-1/801/WAL-001 | Wall: Internal - 1 - Office - Station Building - East Finchley Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Doorway blocked off with plasterboard | | 1 | | | |
| 9261 | ACTIVE | N | N073-00-A/236 | Passage - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18942 | ACTIVE | N | N073-00-A/236/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - East Finchley Stn | Void | Asbestos | Surveyed – Not Detected | | | | Brick Walls; Concrete; Much Cardboard Debris and Boxes above Render on Mesh | | 1 | | YES | |
| 9262 | ACTIVE | N | N073-00-A/261 | Platform 1 - Northbound Fast - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18215 | INACTIVE | N | N073-00-A/261 | Platform 1 - Northbound Fast - Station Building - East Finchley Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | By 17B points - Westinghouse Boxes x 10 | | 10 | | N | N |



Hazardous Material Asset Register - Summary



N073-00 - Station Building - East Finchley Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-----------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 17219 | ACTIVE | N | N073-00-A/261 | Platform 1 - Northbound Fast - Station Building - East Finchley Stn | Lead/Leading | Lead Paint/Lead | Known | | | | HL Window Frames furthest from building - Light Green Paint Analysis 10.20% | | | | | |
| 17218 | ACTIVE | N | N073-00-A/261 | Platform 1 - Northbound Fast - Station Building - East Finchley Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Seating Area Window Frames - White Matt Paint. Thickness 0.36mm: Analysis 5.03% | | | | N | N |
| 17220 | ACTIVE | N | N073-00-A/261 | Platform 1 - Northbound Fast - Station Building - East Finchley Stn | Lead/Leading | Lead Paint/Lead | Known | | | | HL Window Frames closest to building - Light Green Paint Analysis 13.00% | | | | N | N |
| 9263 | ACTIVE | N | N073-00-A/262 | Platform 2 - Northbound Local - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 54088 | ACTIVE | N | N073-00-A/262 | Platform 2 - Northbound Local - Station Building - East Finchley Stn | | Asbestos | Strongly Presumed | | | | Cement pipe behind barrier gate | | 1 | | | |
| 18943 | ACTIVE | N | N073-00-A/262 | Platform 2 - Northbound Local - Station Building - East Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 17221 | ACTIVE | N | N073-00-A/262 | Platform 2 - Northbound Local - Station Building - East Finchley Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Seating Area Window Frames - White Matt Paint. Thickness 0.36mm: Analysis 5.03% | | | | N | N |
| 17222 | ACTIVE | N | N073-00-A/262 | Platform 2 - Northbound Local - Station Building - East Finchley Stn | Lead/Leading | Lead Paint/Lead | Known | | | | HL Window Frames closest to building - Light Green Paint Analysis 13.00% | | | | N | N |
| 18987 | ACTIVE | N | N073-00-A/262 | Platform 2 - Northbound Local - Station Building - East Finchley Stn | Lead/Leading | Lead Paint/Lead | Known | | | | HL Window Frames furthest from Building - Light Green Paint. Analysis 10.20% | | | | N | N |
| 9264 | ACTIVE | N | N073-00-A/263 | Platform 3 - Southbound Local - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17224 | ACTIVE | N | N073-00-A/263 | Platform 3 - Southbound Local - Station Building - East Finchley Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Seating Area Window Frames - White Matt Paint. Thickness 0.36mm: Analysis 5.03% | | | | N | N |
| 17223 | ACTIVE | N | N073-00-A/263 | Platform 3 - Southbound Local - Station Building - East Finchley Stn | Lead/Leading | Lead Paint/Lead | Known | | | | HL Window Frames closest to building - Light Green Paint Analysis 21% | | | | N | N |
| 18944 | ACTIVE | N | N073-00-A/263/ FLR-01 | Floor - 1 - Platform 3 - Station Building - East Finchley Stn | Void | Asbestos | Surveyed – Not Detected | | | | Hatch in Floor no asbestos detected beneath false floor | | | | | YES |
| 9265 | ACTIVE | N | N073-00-A/264 | Platform 4 - Southbound Fast - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17918 | ACTIVE | N | N073-00-A/264 | Platform 4 - Southbound Fast - Station Building - East Finchley Stn | Lead/Leading | Lead Paint/Lead | Known | | | | HL Window Frames closest to building - Light Green Paint Analysis 21% | | | | N | N |



Hazardous Material Asset Register - Summary



N073-00 - Station Building - East Finchley Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-----------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 17226 | ACTIVE | N | N073-00-A/264 | Platform 4 - Southbound Fast - Station Building - East Finchley Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Seating Area Window Frames - White Matt Paint. Thickness 0.36mm: Analysis 5.03% | | | | N | N |
| 17225 | ACTIVE | N | N073-00-A/264/FLR-01 | Floor - 1 - Platform 4 - Station Building - East Finchley Stn | Void | Asbestos | Surveyed – Not Detected | | | | Hatch in Floor no asbestos detected beneath false floor | | | | | YES |
| 9266 | ACTIVE | N | N073-00-A/306 | Train Ops Manager Office - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17227 | ACTIVE | N | N073-00-A/306 | Train Ops Manager Office - Station Building - East Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9267 | ACTIVE | N | N073-00-A/311 | General Office - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18945 | ACTIVE | N | N073-00-A/311/CLG-01 | Ceiling: Solid - 1 - General Office - Station Building - East Finchley Stn | Void | Asbestos | Surveyed – Not Detected | | | | Temptex covering Concrete; Disused GALV Steel Tank; Plasterboard above ceiling | | | | YES | |
| 17228 | ACTIVE | N | N073-00-A/311/CLG-02 | Ceiling: Solid - 2 - General Office - Station Building - East Finchley Stn | Void | Asbestos | Surveyed – Not Detected | | | | Temptex covering Concrete; Disused GALV Steel Tank; Plasterboard above ceiling | | | | YES | |
| 9268 | ACTIVE | N | N073-00-A/351 | Mess Room - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17229 | ACTIVE | N | N073-00-A/351/WAL-003 | Wall: Internal - 3 - Mess Room - Station Building - East Finchley Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 9269 | ACTIVE | N | N073-00-A/411 | Store - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17230 | ACTIVE | N | N073-00-A/411 | Store - Station Building - East Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 17231 | ACTIVE | N | N073-00-A/411 | Store - Station Building - East Finchley Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Interior Walls - Cream Matt Paint. Thickness 0.22mm: Analysis 1.15% | | | | N | N |
| 17232 | ACTIVE | N | N073-00-A/411 | Store - Station Building - East Finchley Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Exterior Surround - White Matt Paint. Thickness 0.29mm: Analysis 5.28% | | | | N | N |
| 9270 | ACTIVE | N | N073-00-A/416 | Toilet: Unisex - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18946 | ACTIVE | N | N073-00-A/416/WAL-003 | Wall: Internal - 3 - Toilet - Station Building - East Finchley Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 9271 | ACTIVE | N | N073-00-A/436 | Waiting Room - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N073-00 - Station Building - East Finchley Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 17233 | ACTIVE | N | N073-00-A/436 | Waiting Room - Station Building - East Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9272 | ACTIVE | N | N073-00-A/437 | Waiting Room - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17234 | ACTIVE | N | N073-00-A/437 | Waiting Room - Station Building - East Finchley Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Superlux Panels High Level; Wooden Backing for Underground Posters | | | | | |
| 9273 | ACTIVE | N | N073-00-A/438 | Waiting Room - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17919 | ACTIVE | N | N073-00-A/438 | Waiting Room - Station Building - East Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9274 | ACTIVE | N | N073-00-A/439 | Waiting Room - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17235 | ACTIVE | N | N073-00-A/439 | Waiting Room - Station Building - East Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9275 | ACTIVE | N | N073-00-A/451 | Tenancy - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17237 | ACTIVE | N | N073-00-A/451 | Tenancy - Station Building - East Finchley Stn | Other Boarding | Asbestos | Strongly Presumed | | | | Fuse Board behind Fuse | | | | N | N |
| 17236 | ACTIVE | N | N073-00-A/451/FLR-01 | Floor - 1 - Tenancy - Station Building - East Finchley Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Wood block floor | | | | | YES |
| 18947 | ACTIVE | N | N073-00-A/451/WAL-003 | Wall: Internal - 3 - Tenancy - Station Building - East Finchley Stn | Rope Seals | Asbestos | Known | | | | 2 Fuse Boxes Rope Seal - Chrysotile | | | | N | N |
| 9276 | ACTIVE | N | N073-00-A/481 | CER - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17238 | ACTIVE | N | N073-00-A/481/FLR-01 | Floor - 1 - CER - Station Building - East Finchley Stn | Cable Duct: Other | Asbestos | Presumed | | | | 150mm cores (ducts) to H/L trackside beneath false floor/ concealed within floor slab | | | | N | YES |
| 9277 | ACTIVE | N | N073-00-A/576 | Stairs: Linear - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17239 | ACTIVE | N | N073-00-A/576 | Stairs: Linear - Station Building - East Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9278 | ACTIVE | N | N073-00-A/601 | Stairs: Linear - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17920 | ACTIVE | N | N073-00-A/601 | Stairs: Linear - Station Building - East Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N073-00 - Station Building - East Finchley Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---------------------|-------------|------------|-------------|---------------------|-------------------|
| 9279 | ACTIVE | N | N073-00-A/602 | Stairs: Linear - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17240 | ACTIVE | N | N073-00-A/602 | Stairs: Linear - Station Building - East Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9280 | ACTIVE | N | N073-00-A/801 | Office - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18988 | ACTIVE | N | N073-00-A/801 | Office - Station Building - East Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9281 | ACTIVE | N | N073-00-A/802 | Office - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17241 | ACTIVE | N | N073-00-A/802 | Office - Station Building - East Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9282 | ACTIVE | N | N073-00-B/041 | Mess Room - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17242 | ACTIVE | N | N073-00-B/041 | Mess Room - Station Building - East Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9283 | ACTIVE | N | N073-00-B/047 | Kitchen - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18948 | ACTIVE | N | N073-00-B/047 | Kitchen - Station Building - East Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9284 | ACTIVE | N | N073-00-B/050 | Store - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17243 | ACTIVE | N | N073-00-B/050 | Store - Station Building - East Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9285 | ACTIVE | N | N073-00-B/081 | Passage - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17244 | ACTIVE | N | N073-00-B/081/FLR-01 | Floor - 1 - Passage - Station Building - East Finchley Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Solid, Lino | | | | | |
| 9286 | ACTIVE | N | N073-00-B/236 | Passage - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18949 | ACTIVE | N | N073-00-B/236 | Passage - Station Building - East Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9287 | ACTIVE | N | N073-00-B/291 | Office - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N073-00 - Station Building - East Finchley Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-----------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 17921 | ACTIVE | N | N073-00-B/291/WAL-003 | Wall: Internal - 3 - Office - Station Building - East Finchley Stn | Void | Asbestos | No Access: Presumed | | | | Movement Panel - No Access Behind | | | | | |
| 9288 | ACTIVE | N | N073-00-B/331 | Mess Room - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17245 | ACTIVE | N | N073-00-B/331/FLR-01 | Floor - 1 - Mess Room - Station Building - East Finchley Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Solid, Lino | | | | | |
| 9289 | ACTIVE | N | N073-00-B/416 | Toilet: Male - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17341 | ACTIVE | N | N073-00-B/416/FLR-01 | Floor - 1 - Toilet - Station Building - East Finchley Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Solid, Lino | | | | | |
| 9290 | ACTIVE | N | N073-00-B/417 | Toilet: Female - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19035 | ACTIVE | N | N073-00-B/417/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - East Finchley Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid above false ceiling | | | | YES | |
| 9291 | ACTIVE | N | N073-00-B/418 | Shower Room - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17342 | ACTIVE | N | N073-00-B/418/FLR-01 | Floor - 1 - Shower Room - Station Building - East Finchley Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Solid, Lino | | | | | |
| 9292 | ACTIVE | N | N073-00-B/531 | Booking On Point - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17343 | ACTIVE | N | N073-00-B/531/FLR-01 | Floor - 1 - Office - Station Building - East Finchley Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Solid, Lino | | | | | |
| 9293 | ACTIVE | N | N073-00-B/576 | Stairs: Linear - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17344 | ACTIVE | N | N073-00-B/576/FLR-01 | Floor - 1 - Linear Stairs - Station Building - East Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | Bitumen Cover | | | | | |
| 17345 | ACTIVE | N | N073-00-B/576/WAL-004 | Wall: Internal - 4 - Linear Stairs - Station Building - East Finchley Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 9294 | ACTIVE | N | N073-00-B/577 | Stairs: Linear - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19036 | ACTIVE | N | N073-00-B/577/FLR-01 | Floor - 1 - Linear Stairs - Station Building - East Finchley Stn | | Asbestos | Surveyed – Not Detected | | | | Bitumen Cover | | | | | |



Hazardous Material Asset Register - Summary



N073-00 - Station Building - East Finchley Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18217 | ACTIVE | N | N073-00-B/577/WAL-004 | Wall: Internal - 4 - Linear Stairs - Station Building - East Finchley Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 9295 | ACTIVE | N | N073-00-B/951 | Disused Room - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 42245 | ACTIVE | N | N073-00-B/951 | Disused Room - Station Building - East Finchley Stn | Lagging | Asbestos | Surveyed – Not Detected | | | | Concrete, Hessian Lagged Pipes - no visible asbestos | | | | N | N |
| 9296 | ACTIVE | N | N073-00-B/952 | Office - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42246 | ACTIVE | N | N073-00-B/952 | Office - Station Building - East Finchley Stn | Lagging | Asbestos | Surveyed – Not Detected | | | | Concrete, Hessian Lagged Pipes | | | | N | N |
| 9297 | ACTIVE | N | N073-00-C/761 | Equipment Room - Station Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17348 | ACTIVE | N | N073-00-C/761 | Equipment Room - Station Building - East Finchley Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing around Pipes | | | | | |

N073-02 - Signals Building - East Finchley Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|--------------|-------------|------------|-------------|---------------------|-------------------|
| 9299 | ACTIVE | N | N073-02-0/731 | CER - Signals Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17349 | ACTIVE | N | N073-02-0/731 | CER - Signals Building - East Finchley Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed | | | | | |

N075-00 - Station Building - Highgate Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 9300 | ACTIVE | N | N075-00-1/101 | Circulation Area - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18866 | ACTIVE | N | N075-00-1/101 | Circulation Area - Station Building - Highgate Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9301 | ACTIVE | N | N075-00-1/151 | UMC - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17912 | ACTIVE | N | N075-00-1/151/FLR-01 | Floor - 1 - UMC - Station Building - Highgate Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Flammable Store (Durasteel) - Non Asbestos | | | | | |



Hazardous Material Asset Register - Summary



N075-00 - Station Building - Highgate Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 19364 | ACTIVE | N | N075-00-1/172 | Escalator Incline - Station Building - Highgate Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access | | | | | |
| 17155 | ACTIVE | N | N075-00-1/172 | Escalator Incline - Station Building - Highgate Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed | | | | | |
| 9302 | ACTIVE | N | N075-00-1/201 | Passage - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17156 | ACTIVE | N | N075-00-1/201 | Passage - Station Building - Highgate Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9303 | ACTIVE | N | N075-00-1/401 | Bin Store - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17159 | ACTIVE | N | N075-00-1/401 | Bin Store - Station Building - Highgate Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access | | | | | |
| 9304 | ACTIVE | N | N075-00-1/411 | Store - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18867 | ACTIVE | N | N075-00-1/411 | Store - Station Building - Highgate Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9305 | ACTIVE | N | N075-00-1/426 | Toilet: Male - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17160 | ACTIVE | N | N075-00-1/426 | Toilet: Male - Station Building - Highgate Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | LU Heater - White Foam Backing | | | | | |
| 18868 | ACTIVE | N | N075-00-1/426/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Highgate Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above False Ceiling | | | | YES | |
| 17161 | ACTIVE | N | N075-00-1/426/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Highgate Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | False Ceiling | | | | | |
| 9306 | ACTIVE | N | N075-00-1/427 | Switch Room - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18983 | ACTIVE | N | N075-00-1/427 | Switch Room - Station Building - Highgate Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9307 | ACTIVE | N | N075-00-1/451 | Tenancy - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17162 | ACTIVE | N | N075-00-1/451 | Tenancy - Station Building - Highgate Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9308 | ACTIVE | N | N075-00-1/576 | Stairs: Linear - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N075-00 - Station Building - Highgate Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17913 | ACTIVE | N | N075-00-1/576 | Stairs: Linear - Station Building - Highgate Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed | | | | | |
| 9309 | ACTIVE | N | N075-00-1/577 | Stairs: Linear - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17163 | ACTIVE | N | N075-00-1/577 | Stairs: Linear - Station Building - Highgate Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed | | | | | |
| 9310 | ACTIVE | N | N075-00-1/601 | Stairs: Linear - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17164 | ACTIVE | N | N075-00-1/601 | Stairs: Linear - Station Building - Highgate Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9311 | ACTIVE | N | N075-00-1/602 | Stairs: Linear - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17165 | ACTIVE | N | N075-00-1/602/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Highgate Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 17166 | ACTIVE | N | N075-00-1/602/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Highgate Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Metal Work above False Ceiling | | | | YES | |
| 9312 | ACTIVE | N | N075-00-1/761 | SVC - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18869 | ACTIVE | N | N075-00-1/761/CLG-01 | Ceiling: Suspended - 1 - SVC - Station Building - Highgate Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 17167 | ACTIVE | N | N075-00-1/761/CLG-01 | Ceiling: Suspended - 1 - SVC - Station Building - Highgate Stn | Void | Asbestos | No Access: Presumed | | | | Above False eiling | | | | YES | |
| 9313 | ACTIVE | N | N075-00-2/001 | Booking Hall - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17173 | ACTIVE | N | N075-00-2/001/CLG-01 | Ceiling: Solid - 1 - Booking Hall - Station Building - Highgate Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Glass Rock Panelling to Beam above False Ceiling | | | | YES | |
| 9314 | ACTIVE | N | N075-00-2/011 | Ticket Office - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17246 | ACTIVE | N | N075-00-2/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Highgate Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |
| 9315 | ACTIVE | N | N075-00-2/021 | POM - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17247 | ACTIVE | N | N075-00-2/021/FLR-01 | Floor - 1 - POM - Station Building - Highgate Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |



Hazardous Material Asset Register - Summary



N075-00 - Station Building - Highgate Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9316 | ACTIVE | N | N075-00-2/031 | Mess Room - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17248 | ACTIVE | N | N075-00-2/031 | Mess Room - Station Building - Highgate Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 18489 | ACTIVE | N | N075-00-2/031 | Mess Room - Station Building - Highgate Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | LU Heater - White Foam Backing | | | | | |
| 9317 | ACTIVE | N | N075-00-2/036 | Toilet: Unisex - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17249 | ACTIVE | N | N075-00-2/036 | Toilet: Unisex - Station Building - Highgate Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |
| 9318 | ACTIVE | N | N075-00-2/071 | Circulation Area - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17250 | ACTIVE | N | N075-00-2/071/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Highgate Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Glass Rock Panelling to Beam; Metal Work above False Ceiling | | | | YES | |
| 18950 | ACTIVE | N | N075-00-2/071/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Highgate Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9319 | ACTIVE | N | N075-00-2/081 | Lobby - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17251 | ACTIVE | N | N075-00-2/081 | Lobby - Station Building - Highgate Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels | | | | | |
| 17252 | ACTIVE | N | N075-00-2/081/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Highgate Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |
| 9320 | ACTIVE | N | N075-00-2/091 | Circulation Area - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17253 | ACTIVE | N | N075-00-2/091 | Circulation Area - Station Building - Highgate Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Rings - Caulking No access above FC during 2020 re-inspection | | | | | N |
| 17254 | ACTIVE | N | N075-00-2/091/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Highgate Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid Concrete, Metal Work, RSJ Beams above False Ceiling | | | | YES | |
| 18951 | ACTIVE | N | N075-00-2/091/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Highgate Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9321 | ACTIVE | N | N075-00-2/151 | UMC - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N075-00 - Station Building - Highgate Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17255 | ACTIVE | N | N075-00-2/151/FLR-01 | Floor - 1 - UMC - Station Building - Highgate Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Flammable Store (Durasteel) - Non Asbestos | | | | | |
| 9322 | ACTIVE | N | N075-00-2/161 | LMC - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18216 | ACTIVE | N | N075-00-2/161 | LMC - Station Building - Highgate Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 17256 | ACTIVE | N | N075-00-2/171 | Escalator Incline - Station Building - Highgate Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access | | | | | |
| 9323 | ACTIVE | N | N075-00-2/201 | Passage - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17257 | ACTIVE | N | N075-00-2/201 | Passage - Station Building - Highgate Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Rings - Caulking No access above FC during 2020 re-inspection | | | | | N |
| 18952 | ACTIVE | N | N075-00-2/201/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Highgate Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid Concrete, Metal Work, RSJ Beams above False Ceiling | | | | YES | |
| 17258 | ACTIVE | N | N075-00-2/201/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Highgate Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9324 | ACTIVE | N | N075-00-2/202 | Passage - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17259 | ACTIVE | N | N075-00-2/202 | Passage - Station Building - Highgate Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9325 | ACTIVE | N | N075-00-2/203 | Passage - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17260 | ACTIVE | N | N075-00-2/203 | Passage - Station Building - Highgate Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9326 | ACTIVE | N | N075-00-2/236 | Lobby - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17261 | ACTIVE | N | N075-00-2/236/FLR-01 | Floor - 1 - Lobby - Station Building - Highgate Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring No access in floor void during 2020 re-inspection | | | | | YES |
| 9327 | ACTIVE | N | N075-00-2/311 | Office - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17922 | ACTIVE | N | N075-00-2/311 | Office - Station Building - Highgate Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | LU Heater - White Foam Backing | | | | | |
| 9328 | ACTIVE | N | N075-00-2/331 | Mess Room - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N075-00 - Station Building - Highgate Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|--------------------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17263 | ACTIVE | N | N075-00-2/331 | Mess Room - Station Building - Highgate Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | LU Heater - White Foam Backing | | | | | |
| 17262 | ACTIVE | N | N075-00-2/331 | Mess Room - Station Building - Highgate Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 9329 | ACTIVE | N | N075-00-2/401 | Station Control Room - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17264 | ACTIVE | N | N075-00-2/401 | Station Control Room - Station Building - Highgate Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 18953 | ACTIVE | N | N075-00-2/401/FLR-01 | Floor - 1 - Station Control Room - Station Building - Highgate Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Vinyl | | | | | |
| 9330 | ACTIVE | N | N075-00-2/406 | Disused Room - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17265 | ACTIVE | N | N075-00-2/406 | Disused Room - Station Building - Highgate Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |
| 9331 | ACTIVE | N | N075-00-2/411 | Store - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17266 | ACTIVE | N | N075-00-2/411 | Store - Station Building - Highgate Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9332 | ACTIVE | N | N075-00-2/451 | Tenancy - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17267 | ACTIVE | N | N075-00-2/451 | Tenancy - Station Building - Highgate Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Tenancy | | | | | |
| 9333 | ACTIVE | N | N075-00-2/452 | Tenancy - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17923 | ACTIVE | N | N075-00-2/452 | Tenancy - Station Building - Highgate Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Tenancy | | | | | |
| 9334 | ACTIVE | N | N075-00-2/661 | Switch Room - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18989 | ACTIVE | N | N075-00-2/661/WAL-001 80916227 | Wall: Internal - 1 - Switch Room - Station Building - Highgate Stn Wall: Internal | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Transformer Box(es) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 3 | | N | N |



Hazardous Material Asset Register - Summary



N075-00 - Station Building - Highgate Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|---------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18954 | ACTIVE | N | N075-00-2/661/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Highgate Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Box Insulation within (1X 30 Amps) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | N | N |
| 18467 | ACTIVE | N | N075-00-2/661/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Highgate Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes - Insulation within (1x100 Amps/8 x 60Amps) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 9 | | N | N |
| 9335 | ACTIVE | N | N075-00-2/662 | Switch Room - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44139 | ACTIVE | N | N075-00-2/662 | Switch Room - Station Building - Highgate Stn | Cable Ducts: Cement | Asbestos | Presumed | | | | Cable ducts - P - Cement & Bitumen | | | | N | N |
| 19411 | ACTIVE | N | N075-00-2/662/FLR-01 | Floor - 1 - Switch Room - Station Building - Highgate Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Hatch | | | | | YES |
| 17268 | ACTIVE | N | N075-00-2/662/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Highgate Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes - Insulation within 3 x 30 Amps/4 x 60 Amps and 1 x 100Amps No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 8 | | N | N |
| 17269 | ACTIVE | N | N075-00-2/662/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Highgate Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Box - Insulation within (1 x 100 Amps) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | N | N |
| 9336 | ACTIVE | N | N075-00-2/663 | Switch Room - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17270 | ACTIVE | N | N075-00-2/663 | Switch Room - Station Building - Highgate Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9337 | ACTIVE | N | N075-00-2/664 | Switch Cupboard - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18990 | ACTIVE | N | N075-00-2/664/CLG-01 | Ceiling: Suspended - 1 - Switch Cupboard - Station Building - Highgate Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 9338 | ACTIVE | N | N075-00-2/731 | CER - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18490 | ACTIVE | N | N075-00-2/731/FLR-01 | Floor - 1 - CER - Station Building - Highgate Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |



Hazardous Material Asset Register - Summary



N075-00 - Station Building - Highgate Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 17271 | ACTIVE | N | N075-00-2/731/WAL-001 | Wall: Internal - 1 - CER - Station Building - Highgate Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes - 2 x 60 amps - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 2 | | N | N |
| 19489 | ACTIVE | N | N075-00-2/731/WAL-002 | Wall: Internal - 2 - CER - Station Building - Highgate Stn | Other Boarding | Asbestos | Strongly Presumed | | | | Paxoline Board | | 1 | | N | N |
| 9339 | ACTIVE | N | N075-00-2/746 | SCR - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18955 | ACTIVE | N | N075-00-2/746 | SCR - Station Building - Highgate Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9340 | ACTIVE | N | N075-00-2/771 | Pump Room - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17272 | ACTIVE | N | N075-00-2/771/CLG-01 | Ceiling: Solid - 1 - Pump Room - Station Building - Highgate Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |
| 9341 | ACTIVE | N | N075-00-2/901 | Void - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17273 | ACTIVE | N | N075-00-2/901 | Void - Station Building - Highgate Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed | | | | | |
| 9342 | ACTIVE | N | N075-00-2/951 | UMC - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9343 | ACTIVE | N | N075-00-2/TA1 | Tenancy - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9344 | ACTIVE | N | N075-00-3/081 | Circulation Area - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17274 | ACTIVE | N | N075-00-3/081 | Circulation Area - Station Building - Highgate Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Rings - Caulking No access in FC during 2020 re-inspection | | | | N | N |
| 17275 | ACTIVE | N | N075-00-3/081/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Highgate Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid Concrete, Metal Work, RSJ Beams | | | | YES | |
| 18956 | ACTIVE | N | N075-00-3/081/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Highgate Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9345 | ACTIVE | N | N075-00-3/161 | LMC - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N075-00 - Station Building - Highgate Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-------------------------------|--|-------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 17276 | ACTIVE | N | N075-00-3/161 | LMC - Station Building - Highgate Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |
| 17277 | ACTIVE | N | N075-00-3/161 | LMC - Station Building - Highgate Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Black Oil Based Paint - Girders. Thickness .09mm; Est Quantity 6sqm; Analysis 1.5% - Fair Conditioning | | | | N | N |
| 9346 | ACTIVE | N | N075-00-3/201 | Passage - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17278 | ACTIVE | N | N075-00-3/201 | Passage - Station Building - Highgate Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 18957 | INACTIVE | N | N075-00-3/201/CLG-01 80916557 | Ceiling: Solid - 1 - Passage - Station Building - Highgate Stn Ceiling: Solid | Lead/Leading | Lead Paint/Lead | Known | | | | Cream Emulsion Paint. Thickness .43mm; Est Quantity 30sqm; Analysis 2.0% - Poor Condition, flaking paint over walkway | | | | N | N |
| 17924 | INACTIVE | N | N075-00-3/201/CLG-02 | Ceiling: Solid - 2 - Passage - Station Building - Highgate Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Cream Emulsion Paint. Thickness .43mm; Est Quantity 30sqm; Analysis 2.0% - Ok Fair | | | | N | N |
| 17279 | INACTIVE | N | N075-00-3/201/CLG-03 | Ceiling: Solid - 3 - Passage - Station Building - Highgate Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Cream Emulsion Paint. Thickness .43mm; Est Quantity 30sqm; Analysis 2.0% - Fair | | | | N | N |
| 9347 | ACTIVE | N | N075-00-3/202 | Passage - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17280 | ACTIVE | N | N075-00-3/202 | Passage - Station Building - Highgate Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9348 | ACTIVE | N | N075-00-3/203 | Passage - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17281 | ACTIVE | N | N075-00-3/203 | Passage - Station Building - Highgate Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9349 | ACTIVE | N | N075-00-3/204 | Passage - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17282 | ACTIVE | N | N075-00-3/204 | Passage - Station Building - Highgate Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9350 | ACTIVE | N | N075-00-3/205 | Passage - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17283 | ACTIVE | N | N075-00-3/205 | Passage - Station Building - Highgate Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9351 | ACTIVE | N | N075-00-3/206 | Passage - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17284 | ACTIVE | N | N075-00-3/206 | Passage - Station Building - Highgate Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N075-00 - Station Building - Highgate Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9352 | ACTIVE | N | N075-00-3/236 | Passage - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18958 | ACTIVE | N | N075-00-3/236/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Highgate Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |
| 9353 | ACTIVE | N | N075-00-3/261 | Platform 1 - Northbound Fast - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44129 | ACTIVE | N | N075-00-3/261 | Platform 1 - Northbound Fast - Station Building - Highgate Stn | Lead/Leading | Lead Paint/Lead | Presumed | | | | Red lead paint at platform end, outside room 3/713 | | | | N | N |
| 17285 | ACTIVE | N | N075-00-3/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Highgate Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 2 x Cables on top J-Hanger All All other cables - within Invert not visible on Platform No access as invert - Confined space team required. | | | | N | YES |
| 17286 | ACTIVE | N | N075-00-3/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Highgate Stn | Cable Duct: Other | Asbestos | Surveyed – Not Detected | | | | All Cable Ducts - Non Asbestos | | | | | YES |
| 9354 | ACTIVE | N | N075-00-3/262 | Platform 2 - Southbound Fast - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17288 | ACTIVE | N | N075-00-3/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Highgate Stn | Cable Duct: Other | Asbestos | Surveyed – Not Detected | | | | All Cable Ducts - Non Asbestos | | | | | YES |
| 17287 | ACTIVE | N | N075-00-3/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Highgate Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 2 x Cables All other cables - In Invert - not visible on platform No access as invert - Confined space team required. | | | | N | YES |
| 9355 | ACTIVE | N | N075-00-3/281 | CER - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17290 | ACTIVE | N | N075-00-3/281/CLG-01 | Ceiling: Solid - 1 - CER - Station Building - Highgate Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |
| 17289 | ACTIVE | N | N075-00-3/281/DOR-01 | Door - 1 - CER - Station Building - Highgate Stn | Durasteel | Asbestos | Strongly Presumed | | | | Durasteel Panel above door | | 1 | | N | N |
| 19022 | ACTIVE | N | N075-00-3/281/FLR-01 | Floor - 1 - CER - Station Building - Highgate Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |
| 9356 | ACTIVE | N | N075-00-3/381 | Switch Room - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17986 | ACTIVE | N | N075-00-3/381 | Switch Room - Station Building - Highgate Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |
| 9357 | ACTIVE | N | N075-00-3/382 | Store - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N075-00 - Station Building - Highgate Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|--------------------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18991 | ACTIVE | N | N075-00-3/382 | Store - Station Building - Highgate Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | LU Heater White Foam Backing | | | | | |
| 17291 | ACTIVE | N | N075-00-3/382 | Store - Station Building - Highgate Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |
| 9358 | ACTIVE | N | N075-00-3/383 | SER - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17292 | ACTIVE | N | N075-00-3/383 | SER - Station Building - Highgate Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | LU Heater White Foam Backing | | | | | |
| 17293 | ACTIVE | N | N075-00-3/383 | SER - Station Building - Highgate Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 9359 | ACTIVE | N | N075-00-3/406 | Store - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19023 | ACTIVE | N | N075-00-3/406 | Store - Station Building - Highgate Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panelling around ducting | | | | | |
| 9360 | ACTIVE | N | N075-00-3/411 | Disused Room - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17294 | ACTIVE | N | N075-00-3/411 | Disused Room - Station Building - Highgate Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | 2 | | | |
| 9361 | ACTIVE | N | N075-00-3/661 | Switch Room - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17295 | INACTIVE | N | N075-00-3/661/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Highgate Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes Insulation within (1 x 60 Amps) - Located on wall 2 | | 1 | | N | N |
| 44132 | ACTIVE | N | N075-00-3/661/WAL-001 80916459 | Wall: Internal - 1 - Switch Room - Station Building - Highgate Stn Wall: Internal | Isolator Switches | Asbestos | Presumed | | | | 60 amp switch box No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | N | N |
| 19488 | ACTIVE | N | N075-00-3/661/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Highgate Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 8 X Switch Boxes Insulation within (5 x 100 Amps/3 x 200 Amps) wall 2 No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 8 | | N | N |
| 17174 | INACTIVE | N | N075-00-3/661/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Highgate Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes Insulation within - Located on Wall 2 as advised by Alan Hartley | | 5 | | | |
| 9362 | ACTIVE | N | N075-00-3/662 | Switch Cupboard - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N075-00 - Station Building - Highgate Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|--------------------------------|---|------------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9363 | ACTIVE | N | N075-00-3/663 | Switch Room - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18870 | ACTIVE | N | N075-00-3/663/CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - Highgate Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |
| 9364 | ACTIVE | N | N075-00-3/706 | Passage - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9365 | ACTIVE | N | N075-00-3/711 | Relay Room - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Strongly Presumed | | | | | | | | | |
| 42544 | ACTIVE | N | N075-00-3/711 | Relay Room - Station Building - Highgate Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Various Cables 4m each from rack on wall 2 and onto wall 3 | | | | N | N |
| 17176 | INACTIVE | N | N075-00-3/711 | Relay Room - Station Building - Highgate Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 3 x 15mm Cables - 2 x going into Invert | | 3 | | N | N |
| 18984 | INACTIVE | N | N075-00-3/711 | Relay Room - Station Building - Highgate Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | 4 x PCB's - Fair Condition. Serial nos not visible | | 4 | | N | N |
| 17175 | ACTIVE | N | N075-00-3/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Highgate Stn | Westing house Boxes | Asbestos | Presumed | | | | Two Westinghouse Boxes one big, one small on wall 2 | | 2 | | N | N |
| 44127 | ACTIVE | N | N075-00-3/711/WAL-002 80916568 | Wall: Internal - 2 - Relay Room - Station Building - Highgate Stn Wall: Internal | Other Boarding | Asbestos | Presumed | | | | Brown composite panel to capacitor on rack - wall 2 | | 4 | | N | N |
| 46857 | ACTIVE | N | N075-00-3/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Highgate Stn | Other Boarding | Asbestos | Presumed | | | | Black composite panel to rack on wall 2 | | | | | |
| 46858 | ACTIVE | N | N075-00-3/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Highgate Stn | Other Boarding | Asbestos | Presumed | | | | Black Composite panel to underneath top shelf on rack of wall 2 | | | | | |
| 44134 | INACTIVE | N | N075-00-3/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Highgate Stn | Cable Ducts: Cement | Asbestos | Presumed | | | | No access to cable ducts - Presumed Asbestos No Access during 2020 re-inspection | | | | N | N |
| 44126 | ACTIVE | N | N075-00-3/711/WAL-003 80916569 | Wall: Internal - 3 - Relay Room - Station Building - Highgate Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | 3no x electrical boxes on wall 3 No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 3 | | N | N |
| 9366 | ACTIVE | N | N075-00-3/712 | Relay Room - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17179 | INACTIVE | N | N075-00-3/712 | Relay Room - Station Building - Highgate Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | 3 x PCB's - Fair Condition. Serial Nos Not Visible - Fair | | 3 | | N | N |
| 17178 | ACTIVE | N | N075-00-3/712/WAL-001 80916577 | Wall: Internal - 1 - Relay Room - Station Building - Highgate Stn Wall: Internal | Cable: Sheath | Asbestos | Presumed | | | | 15mm 1 x wrap and 1 x woven Cables going into Invert | | 2 | | N | N |



Hazardous Material Asset Register - Summary



N075-00 - Station Building - Highgate Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|--------------------------------|---|------------------------|--------------------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17177 | ACTIVE | N | N075-00-3/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Highgate Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | 3no electrical boxes wall 1 No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 2 | | N | N |
| 44136 | INACTIVE | N | N075-00-3/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Highgate Stn | Cable Ducts: Cement | Asbestos | Presumed | | | | Cable duct wall 1 - No access - P No access during 2020 re-inspection | | | | N | N |
| 44131 | ACTIVE | N | N075-00-3/712/WAL-002 80916578 | Wall: Internal - 2 - Relay Room - Station Building - Highgate Stn Wall: Internal | Other Boarding | Asbestos | Presumed | | | | Black /brown composite board to capacitors on rack of wall 2 | | 3 | | N | N |
| 46861 | ACTIVE | N | N075-00-3/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Highgate Stn | Cable: Sheath | Asbestos | Presumed | | | | braided cable to rack on wall 2 | | | | | |
| 46860 | ACTIVE | N | N075-00-3/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Highgate Stn | Other Boarding | Asbestos | Presumed | | | | Black composite board to rack wall 2 | | | | | |
| 18871 | INACTIVE | N | N075-00-3/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Highgate Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline Board | | | | N | N |
| 46859 | ACTIVE | N | N075-00-3/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Highgate Stn | Other Boarding | Asbestos | Presumed | | | | Black composite board to rack x1 on wall 2 | | | | | |
| 42545 | INACTIVE | N | N075-00-3/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Highgate Stn | Other Boarding | Asbestos | Strongly Presumed | | | | Paxoline Board | | | | N | N |
| 9367 | ACTIVE | N | N075-00-3/713 | Relay Room - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18487 | ACTIVE | N | N075-00-3/713/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Highgate Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | 4no Electrical Boxes - Insulation within - wall 1 No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 4 | | N | N |
| 17180 | ACTIVE | N | N075-00-3/713/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Highgate Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 10mm Cables - 2 x going into Invert | | 10 | | N | N |
| 44128 | ACTIVE | N | N075-00-3/713/WAL-002 80916488 | Wall: Internal - 2 - Relay Room - Station Building - Highgate Stn Wall: Internal | Other Boarding | Asbestos | Presumed | | | | Paxoline boarding | | 2 | | N | N |
| 17181 | INACTIVE | N | N075-00-3/713/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Highgate Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | 2 x PCB's - Fair Condition. Serial nos not visible | | 2 | | N | N |
| 9368 | ACTIVE | N | N075-00-3/714 | Relay Room - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18872 | INACTIVE | N | N075-00-3/714 | Relay Room - Station Building - Highgate Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | 5 x PCB's - Fair condition. Serial Nos Not Visible - Fair Condition | | 5 | | N | N |
| 44137 | ACTIVE | N | N075-00-3/714/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Highgate Stn | Cable Ducts: Cement | Asbestos | Presumed | | | | Cable ducts - wall 1 - No access P No access during 2020 re-inspection | | | | N | N |
| 44130 | ACTIVE | N | N075-00-3/714/WAL-002 80916500 | Wall: Internal - 2 - Relay Room - Station Building - Highgate Stn Wall: Internal | Other Boarding | Asbestos | Presumed | | | | Paxoline boarding | | 6 | | N | N |



Hazardous Material Asset Register - Summary



N075-00 - Station Building - Highgate Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17182 | ACTIVE | N | N075-00-3/714/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Highgate Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | 3no Electrical Boxes - Insulation within wall 3 No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 3 | | N | N |
| 17183 | ACTIVE | N | N075-00-3/714/WAL-004 | Wall: Internal - 4 - Relay Room - Station Building - Highgate Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 15mm Cables going into Invert | | 2 | | N | N |
| 9369 | ACTIVE | N | N075-00-3/901 | Disused Room - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17184 | ACTIVE | N | N075-00-3/901 | Disused Room - Station Building - Highgate Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9370 | ACTIVE | N | N075-00-3/991 | Equipment Room - Station Building - Highgate Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17185 | ACTIVE | N | N075-00-3/991/CLG-01 | Ceiling: Solid - 1 - Equipment Room - Station Building - Highgate Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |

N081-00 - Station Building - Archway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 9377 | ACTIVE | N | N081-00-1/001 | Booking Hall - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17106 | ACTIVE | N | N081-00-1/001/CLG-01 | Ceiling: Suspended - 1 - Booking Hall - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 17107 | ACTIVE | N | N081-00-1/001/CLG-01 | Ceiling: Suspended - 1 - Booking Hall - Station Building - Archway Stn | Void | Asbestos | Surveyed – Not Detected | | | | From 1/021 Concrete; Brick Walls; Metal duct for cable and vent boarding; On duct by end wall is supalux | | | | YES | |
| 9378 | ACTIVE | N | N081-00-1/011 | Ticket Office - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18789 | ACTIVE | N | N081-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 17910 | ACTIVE | N | N081-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Archway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Brick, Metal Ducting above Supalux Tiles | | | | YES | |
| 17108 | ACTIVE | N | N081-00-1/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Archway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid, Concrete; Plastic Cables beneath Computer Flooring | | | | | YES |



Hazardous Material Asset Register - Summary



N081-00 - Station Building - Archway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|--------------------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 9379 | ACTIVE | N | N081-00-1/021 | POM - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17110 | ACTIVE | N | N081-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 17111 | ACTIVE | N | N081-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | Concrete; Brick Walls; Metal ducting for cables and vent; Fibre-glass wadding on ceiling; Plastic Cables above False Ceiling | | | | YES | |
| 17109 | ACTIVE | N | N081-00-1/021/FLR-01 | Floor - 1 - POM - Station Building - Archway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid, Concrete; Plastic Cables beneath Computer Flooring | | | | | YES |
| 9380 | ACTIVE | N | N081-00-1/031 | Mess Room - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17113 | ACTIVE | N | N081-00-1/031 | Mess Room - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 17112 | ACTIVE | N | N081-00-1/031 | Mess Room - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board | | | | | |
| 17115 | ACTIVE | N | N081-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | Concrete; Brick Walls; Metal ducting for cables and vent; Fibre-glass wadding on ceiling; Plastic Cables above False Ceiling | | | | YES | |
| 17114 | ACTIVE | N | N081-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18790 | ACTIVE | N | N081-00-1/031/WAL-004 80889392 | Wall: Internal - 4 - Mess Room - Station Building - Archway Stn Wall: Internal | LUL Heaters | Asbestos | Removed | | | | LU Heater - Insulation Board - Chrysotile Removed | | | | N | N |
| 9381 | ACTIVE | N | N081-00-1/036 | Toilet: Unisex - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17117 | ACTIVE | N | N081-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Archway Stn | Void | Asbestos | Surveyed – Not Detected | | | | All walls brick/ breeze block, ceiling concrete; Metal Duct - Air Conditioning; Plastic Cables above False Ceiling | | | | YES | |
| 17116 | ACTIVE | N | N081-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9382 | ACTIVE | N | N081-00-1/047 | Locker Room - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17118 | ACTIVE | N | N081-00-1/047/CLG-01 | Ceiling: Suspended - 1 - Locker Room - Station Building - Archway Stn | Void | Asbestos | Surveyed – Not Detected | | | | All walls brick/ breeze block, ceiling concrete; Metal Duct - Air Conditioning; Plastic Cables above False Ceiling | | | | YES | |
| 18791 | ACTIVE | N | N081-00-1/047/CLG-01 | Ceiling: Suspended - 1 - Locker Room - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |



Hazardous Material Asset Register - Summary



N081-00 - Station Building - Archway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 9383 | ACTIVE | N | N081-00-1/071 | Circulation Area - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17119 | ACTIVE | N | N081-00-1/071/CLG-01 | Ceiling: Suspended - 1 - Circulation Area - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 17120 | ACTIVE | N | N081-00-1/071/CLG-02 | Ceiling: Solid - 2 - Circulation Area - Station Building - Archway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; PVC Cables above Supalux Tiles | | | | YES | |
| 9384 | ACTIVE | N | N081-00-1/201 | Passage - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17911 | ACTIVE | N | N081-00-1/201 | Passage - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles - Above Entrance | | | | | |
| 17121 | ACTIVE | N | N081-00-1/201/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Archway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 20017 | ACTIVE | N | N081-00-1/201/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9385 | ACTIVE | N | N081-00-1/202 | Passage - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17122 | ACTIVE | N | N081-00-1/202/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Archway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 18792 | ACTIVE | N | N081-00-1/202/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9386 | ACTIVE | N | N081-00-1/236 | Lobby - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17125 | ACTIVE | N | N081-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18857 | ACTIVE | N | N081-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Archway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Plastic Cable; Metal Duct - Air Conditioning; Brick above False Ceiling | | | | YES | |
| 17126 | ACTIVE | N | N081-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Archway Stn | Void | Asbestos | Surveyed – Not Detected | | | | All walls brick/ breeze block, ceiling concrete. Metal ducting (Supalux board on duct) above False Ceiling | | | | YES | |
| 17124 | ACTIVE | N | N081-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 17123 | ACTIVE | N | N081-00-1/236/FLR-01 | Floor - 1 - Lobby - Station Building - Archway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plastic Cables; Solid, Concrete beneath Computer Flooring | | | | | YES |
| 9387 | ACTIVE | N | N081-00-1/237 | Lobby - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N081-00 - Station Building - Archway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 9388 | ACTIVE | N | N081-00-1/238 | Lobby - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17128 | ACTIVE | N | N081-00-1/238/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Archway Stn | Void | Asbestos | Surveyed – Not Detected | | | | All walls brick/block, ceiling concrete; All pipe and duct metal (void above 1/406); Plastic Cables above False Ceiling | | | | YES | |
| 17127 | ACTIVE | N | N081-00-1/238/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9389 | ACTIVE | N | N081-00-1/311 | Office - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17129 | ACTIVE | N | N081-00-1/311/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18981 | ACTIVE | N | N081-00-1/311/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Archway Stn | Void | Asbestos | Surveyed – Not Detected | | | | All walls brick, ceiling concrete metal ducting, Supalux Panel, Plastic Cables above Supalux Tiles | | | | YES | |
| 9390 | ACTIVE | N | N081-00-1/331 | Station Supervisor Office - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17130 | ACTIVE | N | N081-00-1/331/CLG-01 | Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Archway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Ceiling concrete. All walls brick. Duct Metal with Fibre-Glass insulation PVC Cable above False Ceiling | | | | YES | |
| 18858 | ACTIVE | N | N081-00-1/331/CLG-01 | Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9391 | ACTIVE | N | N081-00-1/401 | Bin Store - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9392 | ACTIVE | N | N081-00-1/406 | Store - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17131 | ACTIVE | N | N081-00-1/406/CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 17132 | ACTIVE | N | N081-00-1/406/CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Archway Stn | Void | Asbestos | Surveyed – Not Detected | | | | All walls brick/block, ceiling concrete. Metal ducting with fibre-glass insulation; Plastic Cables above Supalux Ceiling | | | | YES | |
| 9393 | ACTIVE | N | N081-00-1/411 | Store - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18859 | ACTIVE | N | N081-00-1/411/CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Archway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 17133 | ACTIVE | N | N081-00-1/411/CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |



Hazardous Material Asset Register - Summary



N081-00 - Station Building - Archway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9394 | ACTIVE | N | N081-00-1/416 | Toilet: Female - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17134 | ACTIVE | N | N081-00-1/416 | Toilet: Female - Station Building - Archway Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater Foam Backing | | | | | |
| 17135 | ACTIVE | N | N081-00-1/416/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 17136 | ACTIVE | N | N081-00-1/416/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Archway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Ceiling is concrete. All walls brick metal ducting spacer in wall is wood, pipe lagging - Rock Wool; Plastic cable; (roof space split in two) - above False Ceiling | | | | YES | |
| 9395 | ACTIVE | N | N081-00-1/417 | Toilet: Male - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18485 | ACTIVE | N | N081-00-1/417 | Toilet: Male - Station Building - Archway Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater Foam Backing | | | | | |
| 19416 | ACTIVE | N | N081-00-1/417 | Toilet: Male - Station Building - Archway Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | LTB Fire Door | | | | | |
| 17138 | ACTIVE | N | N081-00-1/417/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Archway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Ceiling Concrete. All walls brick; Metal ducting, fibre-glass insulated pipes; Plastic Cables - above False Ceiling | | | | YES | |
| 17137 | ACTIVE | N | N081-00-1/417/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9396 | ACTIVE | N | N081-00-1/451 | Tenancy - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18860 | ACTIVE | N | N081-00-1/451 | Tenancy - Station Building - Archway Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Tenancy | | | | | |
| 9397 | ACTIVE | N | N081-00-1/631 | Stairs: Spiral - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17139 | ACTIVE | N | N081-00-1/631 | Stairs: Spiral - Station Building - Archway Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring Caulking | | | | | |
| 17140 | ACTIVE | N | N081-00-1/631/CLG-01 | Ceiling: Solid - 1 - Spiral Stairs - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles. Bulkhead - Supalux Tiles | | | | | |
| 17141 | ACTIVE | N | N081-00-1/631/CLG-01 | Ceiling: Solid - 1 - Spiral Stairs - Station Building - Archway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Brick above False Ceiling | | | | YES | |
| 9398 | ACTIVE | N | N081-00-1/661 | Switch Room - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N081-00 - Station Building - Archway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|--------------------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18861 | ACTIVE | N | N081-00-1/661 | Switch Room - Station Building - Archway Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Various Electrical Equipment - Insulation within HMT Re-Inspection ok - No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score materials within. | | | | N | N |
| 17142 | ACTIVE | N | N081-00-1/661/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Archway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete | | | | YES | |
| 18214 | ACTIVE | N | N081-00-1/661/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 17143 | ACTIVE | N | N081-00-1/661/WAL-002 80889557 | Wall: Internal - 2 - Switch Room - Station Building - Archway Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | 3 x Transformer Box(es) HMT Re-Inspection - No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score materials within. | | 3 | | N | N |
| 42538 | ACTIVE | N | N081-00-1/661/WAL-004 80889559 | Wall: Internal - 4 - Switch Room - Station Building - Archway Stn Wall: Internal | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | 1 X Red Spot Box No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score materials within. | | 1 | | N | N |
| 42539 | ACTIVE | N | N081-00-1/661/WAL-004 80889559 | Wall: Internal - 4 - Switch Room - Station Building - Archway Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 X Switch Box No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score materials within. | | 1 | | N | N |
| 9399 | ACTIVE | N | N081-00-1/746 | SCR - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17144 | ACTIVE | N | N081-00-1/746/CLG-01 | Ceiling: Suspended - 1 - SCR - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 17145 | ACTIVE | N | N081-00-1/746/CLG-01 | Ceiling: Suspended - 1 - SCR - Station Building - Archway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 9400 | ACTIVE | N | N081-00-1/776 | Fan Room - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18862 | ACTIVE | N | N081-00-1/776 | Fan Room - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 18618 | ACTIVE | N | N081-00-1/791/CLG-01 | Ceiling: Solid - 1 - Vent Shaft - Station Building - Archway Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Rings - Sealed over with Concrete - No Caulking present | | | | | |
| 9401 | ACTIVE | N | N081-00-1/901 | SVC - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18466 | ACTIVE | N | N081-00-1/901 | SVC - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 9402 | ACTIVE | N | N081-00-1/951 | Mess Room - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N081-00 - Station Building - Archway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 69755 | ACTIVE | N | N081-00-1/951 | Mess Room - Station Building - Archway Stn | LUL Heaters | Asbestos | Presumed | | | | LUL Heater - Presumed asbestos backing board | | 1 | | | |
| 16951 | ACTIVE | N | N081-00-1/951 | Mess Room - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 16952 | ACTIVE | N | N081-00-1/951/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 16953 | ACTIVE | N | N081-00-1/951/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Archway Stn | Void | Asbestos | Surveyed – Not Detected | | | | All walls brick/block, ceiling concrete; Metal duct with fibre-glass lagging also on pipe work boxing is Supalux - above false ceiling | | | | YES | |
| 9403 | ACTIVE | N | N081-00-2/081 | Circulation Area - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19140 | ACTIVE | N | N081-00-2/081 | Circulation Area - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9404 | ACTIVE | N | N081-00-2/082 | Lobby - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16954 | ACTIVE | N | N081-00-2/082 | Lobby - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9405 | ACTIVE | N | N081-00-2/151 | UMC - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18619 | ACTIVE | N | N081-00-2/151 | UMC - Station Building - Archway Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Incline from 2/151 to 2/161 - Tunnel Rings - Covered with concrete - No caulking present behind | | | | | |
| 44123 | ACTIVE | N | N081-00-2/151 | UMC - Station Building - Archway Stn | | Asbestos | Known | | | | Gasket, 2 no, to A/C metal ductwork in 2/151 UMC 1 & 2 at Archway Station | | | R605851 | N | N |
| 44122 | ACTIVE | N | N081-00-2/151 | UMC - Station Building - Archway Stn | | Asbestos | Known | | | | Gasket, 2 no, to A/C metal ductwork in 2/151 UMC 1 & 2 at Archway Station | | | R605851 | N | N |
| 44121 | ACTIVE | N | N081-00-2/151 | UMC - Station Building - Archway Stn | | Asbestos | Known | | | | Gasket, 2 no, to A/C metal ductwork in 2/151 UMC 1 & 2 at Archway Station | | | R605851 | N | N |
| 16956 | ACTIVE | N | N081-00-2/151 | UMC - Station Building - Archway Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Flammable Store (Durasteel) - Non Asbestos | | | | | |
| 16955 | ACTIVE | N | N081-00-2/151 | UMC - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel; | | | | | |
| 9406 | ACTIVE | N | N081-00-2/161 | LMC - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16959 | ACTIVE | N | N081-00-2/161 | LMC - Station Building - Archway Stn | Cable Duct: Other | Asbestos | Presumed | | | | Cable Sleeve - No Access to sample | | 1 | | | |



Hazardous Material Asset Register - Summary



N081-00 - Station Building - Archway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|----------------------|---------------|--|----------|-----------|-----------------|--------------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 16958 | ACTIVE | N | N081-00-2/161 | LMC - Station Building - Archway Stn | Cable Ducts: Bitumen | Asbestos | Surveyed – Not Detected | | | | Bitumen Ducts - Non Asbestos | | | | | |
| 16957 | ACTIVE | N | N081-00-2/161/FLR-01 | Floor - 1 - LMC - Station Building - Archway Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Hatch on floor | | | | | YES |
| 9407 | ACTIVE | N | N081-00-2/201 | Passage - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19141 | ACTIVE | N | N081-00-2/201 | Passage - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9408 | ACTIVE | N | N081-00-2/202 | Passage - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16960 | ACTIVE | N | N081-00-2/202 | Passage - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9409 | ACTIVE | N | N081-00-2/236 | Lobby - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16961 | ACTIVE | N | N081-00-2/236 | Lobby - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9410 | ACTIVE | N | N081-00-2/237 | Lobby - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18620 | ACTIVE | N | N081-00-2/237 | Lobby - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9411 | ACTIVE | N | N081-00-2/238 | Lobby - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16962 | ACTIVE | N | N081-00-2/238 | Lobby - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9412 | ACTIVE | N | N081-00-2/406 | Store - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16963 | ACTIVE | N | N081-00-2/406 | Store - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9413 | ACTIVE | N | N081-00-2/411 | Disused Room - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16964 | ACTIVE | N | N081-00-2/411 | Disused Room - Station Building - Archway Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring: Caulking - Non Asbestos | | | | | |
| 18621 | ACTIVE | N | N081-00-2/411 | Disused Room - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding | | | | | |



Hazardous Material Asset Register - Summary



N081-00 - Station Building - Archway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9414 | ACTIVE | N | N081-00-2/601 | Stairs: Linear - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19142 | ACTIVE | N | N081-00-2/601 | Stairs: Linear - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9415 | ACTIVE | N | N081-00-2/602 | Stairs: Linear - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16965 | ACTIVE | N | N081-00-2/602 | Stairs: Linear - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9416 | ACTIVE | N | N081-00-2/603 | Stairs: Linear - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16966 | ACTIVE | N | N081-00-2/603 | Stairs: Linear - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 16967 | ACTIVE | N | N081-00-2/636 | Overbridge - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 16968 | ACTIVE | N | N081-00-2/637 | Overbridge - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9417 | ACTIVE | N | N081-00-2/661 | Switch Room - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18622 | ACTIVE | N | N081-00-2/661 | Switch Room - Station Building - Archway Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 9418 | ACTIVE | N | N081-00-2/662 | Switch Room - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16969 | ACTIVE | N | N081-00-2/662 | Switch Room - Station Building - Archway Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 9419 | ACTIVE | N | N081-00-2/711 | SER - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18914 | ACTIVE | N | N081-00-2/711 | SER - Station Building - Archway Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 9420 | ACTIVE | N | N081-00-2/731 | CER - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16970 | ACTIVE | N | N081-00-2/731/CLG-01 | Ceiling: Solid - 1 - CER - Station Building - Archway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Roof - Corrugated Metal Sheet - above Breeze Blocks, Concrete | | | | YES | |
| 19143 | ACTIVE | N | N081-00-2/731/FLR-01 | Floor - 1 - CER - Station Building - Archway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid, new metal work, PVC Cables beneath Wooden floor | | | | | YES |



Hazardous Material Asset Register - Summary



N081-00 - Station Building - Archway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 16971 | ACTIVE | N | N081-00-2/731/ WAL-004 80889987 | Wall: Internal - 4 - CER - Station Building - Archway Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 2 x Grey Switch Boxes - Insultaion within (60amps) No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score materials within. | | 2 | | N | N |
| 9421 | ACTIVE | N | N081-00-2/761 | Computer Equipment Cupboard - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18623 | ACTIVE | N | N081-00-2/761 | Computer Equipment Cupboard - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9422 | ACTIVE | N | N081-00-2/762 | Computer Equipment Cupboard - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16972 | ACTIVE | N | N081-00-2/762 | Computer Equipment Cupboard - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9423 | ACTIVE | N | N081-00-2/763 | Computer Equipment Cupboard - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16973 | ACTIVE | N | N081-00-2/763 | Computer Equipment Cupboard - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9424 | ACTIVE | N | N081-00-2/764 | Computer Equipment Cupboard - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18687 | ACTIVE | N | N081-00-2/764 | Computer Equipment Cupboard - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9425 | ACTIVE | N | N081-00-2/765 | Computer Equipment Cupboard - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16974 | ACTIVE | N | N081-00-2/765 | Computer Equipment Cupboard - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9426 | ACTIVE | N | N081-00-2/766 | Computer Equipment Cupboard - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16975 | ACTIVE | N | N081-00-2/766 | Computer Equipment Cupboard - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9427 | ACTIVE | N | N081-00-2/786 | Service Riser - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16976 | ACTIVE | N | N081-00-2/786 | Service Riser - Station Building - Archway Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Rings; Caulking | | | | | |



Hazardous Material Asset Register - Summary



N081-00 - Station Building - Archway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 17298 | ACTIVE | N | N081-00-2/786 | Service Riser - Station Building - Archway Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 1x Combination fuse switch on wall next to service shaft 2/786. Presumed asbestos insulating materials within. | | 1 | | | |
| 69767 | ACTIVE | N | N081-00-2/786 | Service Riser - Station Building - Archway Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Fan Vent Equipment - Presumed asbestos insulating within | | 2 | | | |
| 69762 | ACTIVE | N | N081-00-2/786 | Service Riser - Station Building - Archway Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1x Red Spot Distribution Box. Presumed asbestos insulating materials within. | | 1 | | | |
| 69761 | ACTIVE | N | N081-00-2/786 | Service Riser - Station Building - Archway Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1x Transformer Box to wall. Presumed asbestos insulating materials within | | 1 | | | |
| 69760 | ACTIVE | N | N081-00-2/786 | Service Riser - Station Building - Archway Stn | | Asbestos | Strongly Presumed | | | | Asbestos containing materials strongly presumed within Fan equipment and metal duct work. Asbestos mastic to duct work joints, Asbestos gaskets and rope seals to Fan/Housing | | | | | |
| 69759 | ACTIVE | N | N081-00-2/786 | Service Riser - Station Building - Archway Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Electrical equipment & trunking to wall by service shaft. Presumed asbestos insulating materials within | | 2 | | | |
| 69758 | ACTIVE | N | N081-00-2/786 | Service Riser - Station Building - Archway Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1x Transformer box to wall by service shaft. Presumed asbestos insulating materials within | | 1 | | | |
| 18688 | ACTIVE | N | N081-00-2/791/CLG-01 | Ceiling: Solid - 1 - Vent Shaft - Station Building - Archway Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Rings - Sealed over with Concrete - No Caulking present | | | | | |
| 9428 | ACTIVE | N | N081-00-2/951 | Switch Room - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16977 | ACTIVE | N | N081-00-2/951/CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |
| 18478 | ACTIVE | N | N081-00-2/951/DOR-01 | Door - 1 - Switch Room - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel above Door | | | | | |
| 16978 | ACTIVE | N | N081-00-2/973/CLG-01 | Ceiling: Solid - 1 - Vent Shaft - Station Building - Archway Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Rings Caulking | | | | | |
| 19024 | ACTIVE | N | N081-00-2/973/WAL-001 | Wall: Internal - 1 - Vent Shaft - Station Building - Archway Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Rings Caulking | | | | | |
| 17296 | ACTIVE | N | N081-00-2/986 | Vent Shaft - Station Building - Archway Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Rings; Caulking - Non Asbestos below Concrete floor | | | | | |
| 17297 | ACTIVE | N | N081-00-2/986/WAL-001 | Wall: Internal - 1 - Vent Shaft - Station Building - Archway Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Rings - Caulking. | | | | N | N |
| 9429 | ACTIVE | N | N081-00-3/121 | Platform Invert - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17299 | ACTIVE | N | N081-00-3/121 | Platform Invert - Station Building - Archway Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access | | | | | |



Hazardous Material Asset Register - Summary



N081-00 - Station Building - Archway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9430 | ACTIVE | N | N081-00-3/201 | Passage - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17300 | ACTIVE | N | N081-00-3/201 | Passage - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9431 | ACTIVE | N | N081-00-3/202 | Passage - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19025 | ACTIVE | N | N081-00-3/202 | Passage - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9432 | ACTIVE | N | N081-00-3/203 | Passage - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17301 | ACTIVE | N | N081-00-3/203 | Passage - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9433 | ACTIVE | N | N081-00-3/204 | Passage - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17302 | ACTIVE | N | N081-00-3/204 | Passage - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9434 | ACTIVE | N | N081-00-3/205 | Passage - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17303 | ACTIVE | N | N081-00-3/205 | Passage - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9435 | ACTIVE | N | N081-00-3/261 | Platform 1 - Southbound Fast - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70026 | ACTIVE | N | N081-00-3/261 | Platform 1 - Southbound Fast - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | Platform Invert - Metal tunnel rings to walls, floor throughout - concrete infill, Plastic cables, meta conduits and CMS, New firestops and mastics, plastic and metal pipework, wood splinters, fibres (shuttering, panels, cut offs) grout/ wood/lead to tunnel ring flanges throughout, MMMF insulation loose, concrete slab to ceiling, walls throughout, RSJ to ceiling throughout | | | | | |
| 70023 | ACTIVE | N | N081-00-3/261 | Platform 1 - Southbound Fast - Station Building - Archway Stn | Gasket :Pipework | Asbestos | Sampled – Not Detected | | | | Platform Invert - Gaskets to metal pipework flange throughout | | | R731061 | | Y |
| 70022 | ACTIVE | N | N081-00-3/261 | Platform 1 - Southbound Fast - Station Building - Archway Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - 4x Bitumen Cable ducts to trackside wall, departure end. | | 4 | R731061 | | Y |
| 70020 | ACTIVE | N | N081-00-3/261 | Platform 1 - Southbound Fast - Station Building - Archway Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - 2x Cement cable ducts to trackside wall, arrivals end | | 2 | R731061 | | Y |



Hazardous Material Asset Register - Summary



N081-00 - Station Building - Archway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|----------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 70017 | ACTIVE | N | N081-00-3/261 | Platform 1 - Southbound Fast - Station Building - Archway Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - 2x Cement cable ducts to steps to middle manhole | | 2 | R731061 | | Y |
| 70025 | ACTIVE | N | N081-00-3/261 | Platform 1 - Southbound Fast - Station Building - Archway Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - 2x Bitumen Cable ducts to platform wall, arrival end. | | 2 | R731061 | | Y |
| 70018 | ACTIVE | N | N081-00-3/261 | Platform 1 - Southbound Fast - Station Building - Archway Stn | Cable: Sheath | Asbestos | Known | | | | Platform Invert - Braided cables to J-Hanger throughout | | | R731061 | | Y |
| 70024 | ACTIVE | N | N081-00-3/261 | Platform 1 - Southbound Fast - Station Building - Archway Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - 10x Bitumen cable ducts to platform wall, midway | | 10 | R731061 | | Y |
| 70014 | ACTIVE | N | N081-00-3/261 | Platform 1 - Southbound Fast - Station Building - Archway Stn | Westing house Boxes | Asbestos | Presumed | | | | Platform Invert - 1x Small Westinghouse Box to departure wall | | 1 | R731061 | | Y |
| 19026 | INACTIVE | N | N081-00-3/261/ FLR-01 | Floor - 1 - Platform 1 - Station Building - Archway Stn | Cable Ducts: Cement | Asbestos | Strongly Presumed | | | | Platform Invert - Cable Duct No access within invert 2020 re-inspection as confined space team required. | | 1 | | N | YES |
| 19490 | INACTIVE | N | N081-00-3/261/ FLR-01 | Floor - 1 - Platform 1 - Station Building - Archway Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform Invert - Various Cables No access within invert 2020 re-inspection as confined space team required. | | | | N | YES |
| 18992 | ACTIVE | N | N081-00-3/261/ FLR-01 | Floor - 1 - Platform 1 - Station Building - Archway Stn | Lead/Leading | Lead Paint/Lead | Strongly Presumed | | | | Red Grit Bin - Fair | | | | N | N |
| 9436 | ACTIVE | N | N081-00-3/262 | Platform 2 - Northbound Fast - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70032 | ACTIVE | N | N081-00-3/262 | Platform 2 - Northbound Fast - Station Building - Archway Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - 4x Bitumen cable ducts to platform wall midway | | 4 | R731058 | | Y |
| 70028 | ACTIVE | N | N081-00-3/262 | Platform 2 - Northbound Fast - Station Building - Archway Stn | Cable: Sheath | Asbestos | Known | | | | Platform Invert - 10x Braided cables to J-Hangers | | 10 | R731058 | | Y |
| 70031 | ACTIVE | N | N081-00-3/262 | Platform 2 - Northbound Fast - Station Building - Archway Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - 4x Bitumen cable ducts to platform wall/ceiling departure end | | 4 | R731058 | | Y |
| 70033 | ACTIVE | N | N081-00-3/262 | Platform 2 - Northbound Fast - Station Building - Archway Stn | Cable Ducts: Bitumen | Asbestos | Surveyed – Not Detected | | | | Platform Invert - 6x Bitumen cable ducts to trackside wall/ceiling | | 6 | R731058 | | Y |
| 70034 | ACTIVE | N | N081-00-3/262 | Platform 2 - Northbound Fast - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | Platform Invert - Metal tunnel rings to walls, floor throughout - concrete infll, concrete slab to ceiling, walls throughout, RSJ to ceiling, plastic cables, metal conduits and CMS, New firestops and mastics throughout, plastic and metal pipework, wood splinters, fibres (shuttering, panels, cut offs) new electrical equipment, boxes, units, metal access hatches and ladders/steps, grout/wood/ lead to tunnel ring flanges throughout, supalux cut offs to ceiling, MMMF insulation loose. | | | R731058 | | Y |



Hazardous Material Asset Register - Summary



N081-00 - Station Building - Archway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------------------|---|------------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 70030 | ACTIVE | N | N081-00-3/262 | Platform 2 - Northbound Fast - Station Building - Archway Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - 4x Bitumen ducts to trackside wall departure end | | 4 | R731058 | | Y |
| 17305 | ACTIVE | N | N081-00-3/262 | Platform 2 - Northbound Fast - Station Building - Archway Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Trackside - Black Paint at bottom contains lead - Fair | | | | N | N |
| 17306 | INACTIVE | N | N081-00-3/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Archway Stn | Cable Ducts: Bitumen | Asbestos | Surveyed – Not Detected | | | | Platform 2 Invert - Bitumen Cable Ducts below 3/731 | | | | | YES |
| 17987 | INACTIVE | N | N081-00-3/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Archway Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 2 Invert - Various Cables No access within invert 2020 re-inspection as confined space team required. | | | | N | YES |
| 17304 | ACTIVE | N | N081-00-3/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Archway Stn | Lead/Leading | Lead Paint/Lead | Strongly Presumed | | | | Red Grit Bin - Fair | | | | N | N |
| 9437 | ACTIVE | N | N081-00-3/661 | Switch Room - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18491 | ACTIVE | N | N081-00-3/661/FLR-01 | Floor - 1 - Switch Room - Station Building - Archway Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Hatch on floor | | | | | YES |
| 17307 | ACTIVE | N | N081-00-3/661/WAL-001 80889724 | Wall: Internal - 1 - Switch Room - Station Building - Archway Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | Tunnel Lighting Box - ACM within to wall 1 No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score materials within. | | 1 | | | |
| 42542 | ACTIVE | N | N081-00-3/661/WAL-003 80889726 | Wall: Internal - 3 - Switch Room - Station Building - Archway Stn Wall: Internal | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | 1 x Tunnel Lighting Box No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score materials within. | | 1 | | N | N |
| 9438 | ACTIVE | N | N081-00-3/662 | Switch Room - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44951 | ACTIVE | N | N081-00-3/662 | Switch Room - Station Building - Archway Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1no Low Level Transformer Box - Insulation within | | 1 | | N | N |
| 44950 | ACTIVE | N | N081-00-3/662 | Switch Room - Station Building - Archway Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1 x Busbar | | 1 | | N | N |
| 19027 | ACTIVE | N | N081-00-3/662/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Archway Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes - 2 x 60 amps Insulation within. 1x Switch box removed No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score materials within. | | 2 | | N | N |
| 42540 | ACTIVE | N | N081-00-3/662/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Archway Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | 1 X Train Describer No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score materials within. | | 1 | | N | N |



Hazardous Material Asset Register - Summary



N081-00 - Station Building - Archway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|--------------------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 9439 | ACTIVE | N | N081-00-3/663 | Switch Room - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17308 | INACTIVE | N | N081-00-3/663/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Archway Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes - Insulation within - HMU Re Inspection 20/08/15 - Switch boxes should have been recorded against 3/662 and not 3/663 | | 2 | | | |
| 17309 | ACTIVE | N | N081-00-3/663/WAL-002 80889757 | Wall: Internal - 2 - Switch Room - Station Building - Archway Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | MCB Distribution - Insulation within No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score materials within. | | 1 | | | |
| 17311 | INACTIVE | N | N081-00-3/663/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Archway Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Low Level Transformer Box - Insulation within - HMU Re Inspection 20/08/15 - This item should have been recorded against 3/662 and not 3/663 | | 1 | | | |
| 17310 | INACTIVE | N | N081-00-3/663/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Archway Stn | Train Describers | Asbestos | Presumed | | | | Train Describer Box - HMU Re Inspection 20/08/15 - This item should have been recorded against 3/662 and not 3/663 | | 1 | | | |
| 9440 | ACTIVE | N | N081-00-3/664 | Switch Room - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44947 | ACTIVE | N | N081-00-3/664/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Archway Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | High Level Equipment - Built 21/05/1999; W2 1 x 60amp Switch Box | | | | N | N |
| 17312 | ACTIVE | N | N081-00-3/664/WAL-002 80889770 | Wall: Internal - 2 - Switch Room - Station Building - Archway Stn Wall: Internal | Isolator Switches | Asbestos | Presumed | | | | Red Spot Fuse Box - Insulation within Presume 1x Combination Fuse Switch to wall -Presume 1x electrical box to wall - No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score materials within. | | 1 | | | |
| 9441 | ACTIVE | N | N081-00-3/706 | IMR - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17313 | ACTIVE | N | N081-00-3/706 | IMR - Station Building - Archway Stn | Other Boarding | Asbestos | Strongly Presumed | | | | Paxoline Board | | | | N | N |
| 19028 | ACTIVE | N | N081-00-3/706 | IMR - Station Building - Archway Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 15mm Cables going into Invert | | 2 | | N | N |
| 9442 | ACTIVE | N | N081-00-3/712 | Relay Room - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17988 | ACTIVE | N | N081-00-3/712 80143115 | Relay Room - Station Building - Archway Stn Room Assets | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Transformer Box on floor wall 2 and wall 3 No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score materials within. | | 1 | | N | N |
| 19029 | ACTIVE | N | N081-00-3/712 | Relay Room - Station Building - Archway Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 50mm Cables going into Invert | | 1 | | N | N |



Hazardous Material Asset Register - Summary



N081-00 - Station Building - Archway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------------------------|--|---------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 17314 | ACTIVE | N | N081-00-3/712 | Relay Room - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board | | | | | |
| 42327 | INACTIVE | N | N081-00-3/712 | Relay Room - Station Building - Archway Stn | PCBs | Polychlorinated biphenyl | Presumed | | | | 2 x small silver cylinder PCB's - wall mounted 6 x medium siver cylinder - wall mounted | | 8 | | N | N |
| 17315 | ACTIVE | N | N081-00-3/712/ WAL-002 80889796 | Wall: Internal - 2 - Relay Room - Station Building - Archway Stn Wall: Internal | Westing house Boxes | Asbestos | Strongly Presumed | | | | Westinghouse Boxes - Insulation within No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score materials within. | | 2 | | N | N |
| 9443 | ACTIVE | N | N081-00-3/713 | Relay Room - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17316 | ACTIVE | N | N081-00-3/713 | Relay Room - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels | | | | | |
| 17318 | INACTIVE | N | N081-00-3/713 | Relay Room - Station Building - Archway Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | 6 x PCB's - serial no.s not visible - showing signs of leakage. - Leaking as Reported Still Leaking - 16-03-2016 | | 6 | | N | N |
| 17317 | ACTIVE | N | N081-00-3/713/ WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Archway Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Electrical box removed - cables cut back to trunking behind cabinet and encapsulated 2 x green 50mm Cables going to Track | | 2 | | N | N |
| 53555 | INACTIVE | N | N081-00-3/713/ WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Archway Stn | Other Boarding | Asbestos | Presumed | | | | 6x brown panels to equipment in cabinet wall 3 | | | | | |
| 9444 | INACTIVE | N | N081-00-3/714 | Relay Room - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17146 | ACTIVE | N | N081-00-3/714 | Relay Room - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board | | | | | |
| 41914 | INACTIVE | N | N081-00-3/714/ FLR-01 | Floor - 1 - Relay Room - Station Building - Archway Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | 4 x PCB's on floor by wall 1 - serial numbers and condition not visible - no access | | 4 | | N | N |
| 17149 | INACTIVE | N | N081-00-3/714/ WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Archway Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | 6 x PCB's - Fair condition (1 x upper shelf, 5 x lower shelf) | | 6 | | | |
| 17147 | ACTIVE | N | N081-00-3/714/ WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Archway Stn | Cable: Sheath | Asbestos | Presumed | | | | Green Cable Cables (green) most likely to be nylon material | | | | N | N |
| 18863 | ACTIVE | N | N081-00-3/714/ WAL-003 80889811 | Wall: Internal - 3 - Relay Room - Station Building - Archway Stn Wall: Internal | Westing house Boxes | Asbestos | Strongly Presumed | | | | Westing House Box - Insulation within 1 x Small Blue Cylinder mounted on rack - Wall 3 - 16-03-2016 1 x Small Blue Cylinder mounted on rack high level wall 3 - 16/03/2016 No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score materials within. | | 1 | | N | N |



Hazardous Material Asset Register - Summary



N081-00 - Station Building - Archway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|---------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 42657 | INACTIVE | N | N081-00-3/714/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Archway Stn | PCBs | Polychlorinated biphenyl | Presumed | | | | 1 x small blue Cylinder mounted on rack away from wall 3 hard to see Plus Another 1 x small blue Cylinder on rack high Level | | 1 | | N | N |
| 17148 | ACTIVE | N | N081-00-3/714/WAL-004 | Wall: Internal - 4 - Relay Room - Station Building - Archway Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline Board Presume black composite panels throughout to wall 3 - Photo DSC05274 Presume materials with rectifier box to wall 3 - Photo DSC05275 Presume black composite panels throughout to wall 1 - Photo DSC05276 | | | | N | N |
| 9445 | ACTIVE | N | N081-00-3/715 | Relay Room - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18864 | INACTIVE | N | N081-00-3/715 | Relay Room - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 17150 | ACTIVE | N | N081-00-3/715 | Relay Room - Station Building - Archway Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Brown Paint contains lead | | | | | |
| 53556 | ACTIVE | N | N081-00-3/715/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Archway Stn | Other Boarding | Asbestos | Sampled – Not Detected | | | | x 4 packing board to rack on wall 2 - ID non asbestos - NO. 4RS- JP-221113-R717876 | | | | | |
| 46862 | ACTIVE | N | N081-00-3/715/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Archway Stn | Other Boarding | Asbestos | Known | | | | Composite brown paxoline board to wall 2 - (Note new brown panel within box/ cabinet, throughout rest of room) | | | | | |
| 9446 | ACTIVE | N | N081-00-3/716 | Relay Room - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17153 | ACTIVE | N | N081-00-3/716 | Relay Room - Station Building - Archway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |
| 18486 | INACTIVE | N | N081-00-3/716 | Relay Room - Station Building - Archway Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | 4 x PCB's - Fair Condition. Serial no.s not visible - Fair | | 4 | | N | N |
| 17154 | ACTIVE | N | N081-00-3/716/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Archway Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | Westing House Box Presume x4 Brown composite panels to wall 1 racking - Photo DSC05253 No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score materials within. | | 1 | | N | N |
| 9447 | ACTIVE | N | N081-00-3/731 | Lobby - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18982 | ACTIVE | N | N081-00-3/731 | Lobby - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N081-00 - Station Building - Archway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 9448 | ACTIVE | N | N081-00-3/732 | CER - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17151 | ACTIVE | N | N081-00-3/732 | CER - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9449 | ACTIVE | N | N081-00-3/761 | Equipment Room - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17152 | ACTIVE | N | N081-00-3/761 | Equipment Room - Station Building - Archway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9450 | ACTIVE | N | N081-00-A/711 | Plant Room - Station Building - Archway Stn | Stations: Rooms | Asbestos | Room: Surveyed – Asbestos Known | | | | | | | | | |
| 44955 | INACTIVE | N | N081-00-A/711 | Plant Room - Station Building - Archway Stn | Control Panels | Asbestos | Presumed | | | | Material Within 1no Fan Panel to Floor by Door | | | | N | N |
| 44956 | ACTIVE | N | N081-00-A/711 | Plant Room - Station Building - Archway Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Materials Within Transformer By Wall 1 | | | | N | N |
| 44957 | ACTIVE | N | N081-00-A/711 | Plant Room - Station Building - Archway Stn | Control Panels | Asbestos | Presumed | | | | Materials Within Control Panel By Wall 1 | | | | N | N |
| 44958 | ACTIVE | N | N081-00-A/711 | Plant Room - Station Building - Archway Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Materials Within Fuse/Switch Box to Micronic Filter Unit | | 1 | R592401 | N | N |
| 18865 | INACTIVE | N | N081-00-A/711 | Plant Room - Station Building - Archway Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed | | | | | |
| 44952 | ACTIVE | N | N081-00-A/711 | Plant Room - Station Building - Archway Stn | Mastic | Asbestos | Known | | | | Putty to Joint at Fan Exhaust | | | | N | N |
| 44953 | ACTIVE | N | N081-00-A/711 | Plant Room - Station Building - Archway Stn | Mastic | Asbestos | Known | | | | Mastic to A/C Metal Ductwork Flanges | | | | N | N |
| 44954 | ACTIVE | N | N081-00-A/711/WAL-001 | Wall: Internal - 1 - Plant Room - Station Building - Archway Stn | Rope Gaskets | Asbestos | Known | | | | Gasket 1no to Seal of AHU Flange | | | R592401 | N | N |

N083-00 - Station Building - Tufnell Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-------------------------------|---|-------------------|---------------|------------------------------------|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 9451 | ACTIVE | N | N083-00-1/001 | Booking Hall - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 42312 | ACTIVE | N | N083-00-1/001 | Booking Hall - Station Building - Tufnell Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux boxing - cables, cable management system within - Above entrance | | | R501951 | N | N |
| 17023 | ACTIVE | N | N083-00-1/001/CLG-01 80914114 | Ceiling: Solid - 1 - Booking Hall - Station Building - Tufnell Park Stn Ceiling: Solid | No Access | Asbestos | Surveyed – Not Detected | | | | Plaster on concrete slab | | | R501951 | YES | N |



Hazardous Material Asset Register - Summary



N083-00 - Station Building - Tufnell Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-------------------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 42313 | ACTIVE | N | N083-00-1/001/FLR-01 | Floor - 1 - Booking Hall - Station Building - Tufnell Park Stn | | Asbestos | Surveyed – Not Detected | | | | Ceramic tiles on concrete slab | | | R501951 | N | N |
| 9452 | ACTIVE | N | N083-00-1/011 | Ticket Office - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 42236 | ACTIVE | N | N083-00-1/011 | Ticket Office - Station Building - Tufnell Park Stn | | Asbestos | Surveyed – Not Detected | | | | Above false ceiling - Plaster on concrete slab, plaster coving to main ceiling, A/C metal ductwork - new MMMF and Supalux, Supalux panels, RSJ | | | R501951 | Y | N |
| 42306 | ACTIVE | N | N083-00-1/011 | Ticket Office - Station Building - Tufnell Park Stn | Other Electrical Boxes | Asbestos | Surveyed – Not Detected | | | | New electrical boxes throughout | | | R501951 | N | N |
| 17024 | ACTIVE | N | N083-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Tufnell Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 17027 | INACTIVE | N | N083-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Tufnell Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plaster, Solid above False Ceiling | | | | YES | |
| 17025 | INACTIVE | N | N083-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Tufnell Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Block Work, Trunking above False Ceiling | | | | YES | |
| 42305 | ACTIVE | N | N083-00-1/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Tufnell Park Stn | | Asbestos | Surveyed – Not Detected | | | | Screed on concrete slab beneath false floor | | | R501951 | N | Y |
| 18703 | ACTIVE | N | N083-00-1/011/FLR-01 80914132 | Floor - 1 - Ticket Office - Station Building - Tufnell Park Stn Floor | No Access | Asbestos | No Access: Presumed | | | | Lino (new) on metal / wooden computer tiles. No access | | | R501951 | N | N |
| 9453 | ACTIVE | N | N083-00-1/021 | POM - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19148 | ACTIVE | N | N083-00-1/021/CCO-01 | Cash Counter - NC500 - POM - Station Building - Tufnell Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 42310 | ACTIVE | N | N083-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Tufnell Park Stn | | Asbestos | Surveyed – Not Detected | | | | MMMF ceiling tiles on metal framework. Supalux panels. | | | R501951 | N | N |
| 42311 | ACTIVE | N | N083-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Tufnell Park Stn | | Asbestos | Surveyed – Not Detected | | | | Concrete slab, A/C metal ducts - new (MMMD & supalux) gaitor new, RSJ above false ceiling | | | R501951 | Y | N |
| 17026 | INACTIVE | N | N083-00-1/021/FLR-01 | Floor - 1 - POM - Station Building - Tufnell Park Stn | No Access | Asbestos | No Access: Presumed | | | | Concrete slab below computer tiles | | | R501951 | N | Y |
| 42240 | ACTIVE | N | N083-00-1/021/FLR-01 | Floor - 1 - POM - Station Building - Tufnell Park Stn | | Asbestos | Surveyed – Not Detected | | | | Lino (new) on metal / wooden computer tiles - computer tiles on concrete slab beneath false floor | | | R501951 | Y | N |
| 9454 | ACTIVE | N | N083-00-1/031 | Mess Room - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N083-00 - Station Building - Tufnell Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18704 | ACTIVE | N | N083-00-1/031 | Mess Room - Station Building - Tufnell Park Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | LU Heater (Foam) | | | | | |
| 17028 | ACTIVE | N | N083-00-1/031 | Mess Room - Station Building - Tufnell Park Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 17029 | ACTIVE | N | N083-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Tufnell Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 17030 | ACTIVE | N | N083-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Tufnell Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Block Work, Supalux Boxing, Pipe Work, Fibre Glass | | | | YES | |
| 9455 | ACTIVE | N | N083-00-1/036 | Lobby - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 42307 | ACTIVE | N | N083-00-1/036 | Lobby - Station Building - Tufnell Park Stn | | Asbestos | Surveyed – Not Detected | | | | Above false ceiling - A/C metal ductwork - new (MMMF and Supalux) forming and within the false ceiling, plastic and metal - foam/mmmf insulation throughout | | | R501951 | Y | N |
| 42237 | ACTIVE | N | N083-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Tufnell Park Stn | | Asbestos | Surveyed – Not Detected | | | | MMMF ceiling tiles on metal framework to suspended ceiling, plaster on concrete slab above false ceiling, Supalux panels | | | R501951 | N | N |
| 17032 | ACTIVE | N | N083-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Tufnell Park Stn | | Asbestos | Surveyed – Not Detected | | | | Block Work, Trunking | | | | YES | |
| 17031 | ACTIVE | N | N083-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Tufnell Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 18705 | INACTIVE | N | N083-00-1/036/FLR-01 | Floor - 1 - Lobby - Station Building - Tufnell Park Stn | No Access | Asbestos | No Access: Presumed | | | | Ceramic tiles on concrete slab - base floor – no false floor | | | R501951 | N | N |
| 9456 | ACTIVE | N | N083-00-1/037 | Toilet: Unisex - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17033 | ACTIVE | N | N083-00-1/037/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Tufnell Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Breeze Block, Glass Window - Wooden Frame; Metal Pipes above False Ceiling | | | | YES | |
| 19363 | ACTIVE | N | N083-00-1/037/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Tufnell Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 9457 | ACTIVE | N | N083-00-1/071 | Circulation Area - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Surveyed – Asbestos Known | | | | Durasteel Panels around all lift doors are a mixture of Asbestos and Non Asbestos types. Please contact the HMU if your work will disturb these panels | | | | | |
| 17034 | ACTIVE | N | N083-00-1/071 | Circulation Area - Station Building - Tufnell Park Stn | Durasteel | Asbestos | No Access: Presumed | | | | Durasteel Panels around all lift doors are a mixture of Asbestos and Non Asbestos types. No access | | | | | |



Hazardous Material Asset Register - Summary



N083-00 - Station Building - Tufnell Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 42439 | ACTIVE | N | N083-00-1/071 | Circulation Area - Station Building - Tufnell Park Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | Durasteel panel, <2m2, left hand side of upper landing entry side of lift, to left hand side of lift 1 | | | R504176 | N | N |
| 42314 | ACTIVE | N | N083-00-1/071 | Circulation Area - Station Building - Tufnell Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Above entrance door - Supalux boxing - cables, cable management systems within | | | R501951 | N | N |
| 45358 | ACTIVE | N | N083-00-1/071 | Circulation Area - Station Building - Tufnell Park Stn | Durasteel | Asbestos | Presumed | | | | Durasteel Panels around all lift doors are a mixture of Asbestos and non asbestos types. No access | | | | N | N |
| 18706 | ACTIVE | N | N083-00-1/071/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Tufnell Park Stn | Void | Asbestos | Not Found during Inspection | | | | Plaster on concrete slab, wooden panels Not Found on last inspection still presume Not located in 2020 re-inspection. | | | R501951 | N | N |
| 9458 | ACTIVE | N | N083-00-1/081 | Lobby - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9459 | ACTIVE | N | N083-00-1/236 | Passage - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17036 | ACTIVE | N | N083-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Tufnell Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Fibreglass Lagging; Block Work; Metal Ducts above False Ceiling | | | | YES | |
| 17035 | ACTIVE | N | N083-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Tufnell Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 9460 | ACTIVE | N | N083-00-1/237 | Lobby - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42238 | ACTIVE | N | N083-00-1/237 | Lobby - Station Building - Tufnell Park Stn | | Asbestos | Surveyed – Not Detected | | | | Lino (new) on metal / wooden computer tiles | | | R501951 | N | N |
| 42308 | ACTIVE | N | N083-00-1/237 | Lobby - Station Building - Tufnell Park Stn | Other Electrical Boxes | Asbestos | Surveyed – Not Detected | | | | New Electrical Boxes throughout | | | R501951 | N | N |
| 17038 | ACTIVE | N | N083-00-1/237/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Tufnell Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plaster on concrete, plastic and metal pipework, foam, above false ceiling | | | R501951 | YES | N |
| 17037 | INACTIVE | N | N083-00-1/237/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Tufnell Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 42239 | ACTIVE | N | N083-00-1/237/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Tufnell Park Stn | | Asbestos | Surveyed – Not Detected | | | | A/C metal ductwork - new (MMMMF and Supalux, MMF ceiling tiles on metal framework, plaster on concrete, Plastic and metal pipework - foam forming and within suspended ceiling | | | R501951 | N | N |
| 17902 | ACTIVE | N | N083-00-1/237/FLR-01 80914254 | Floor - 1 - Lobby - Station Building - Tufnell Park Stn Floor | Void | Asbestos | No Access: Presumed | | | | Computer tiles on concrete slab beneath false floor | | | R501951 | N | Y |



Hazardous Material Asset Register - Summary



N083-00 - Station Building - Tufnell Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 9461 | ACTIVE | N | N083-00-1/281 | Locker Room - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18707 | ACTIVE | N | N083-00-1/281 | Locker Room - Station Building - Tufnell Park Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | LU Heater - Foam Board | | | | | |
| 17040 | ACTIVE | N | N083-00-1/281/CLG-01 | Ceiling: Suspended - 1 - Locker Room - Station Building - Tufnell Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Fibreglass Lagging Pipes; Plasterboard; Ducting above False Ceiling | | | | YES | |
| 17039 | ACTIVE | N | N083-00-1/281/CLG-01 | Ceiling: Suspended - 1 - Locker Room - Station Building - Tufnell Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 20289 | ACTIVE | N | N083-00-1/281/DORS | Doors - Locker Room - Station Building - Tufnell Park Stn | | Lead Paint/Lead | Surveyed – Not Detected | | | | Lead Paint Content. Door to Corridor | | | | | |
| 20288 | ACTIVE | N | N083-00-1/281/WLS | Walls: Internal - Locker Room - Station Building - Tufnell Park Stn | | Lead Paint/Lead | Surveyed – Not Detected | | | | Lead Paint content not detected in Cream Gloss on all walls | | | | | |
| 9462 | ACTIVE | N | N083-00-1/331 | Station Control Room - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17041 | ACTIVE | N | N083-00-1/331 | Station Control Room - Station Building - Tufnell Park Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | LU Heaters - Foam | | 2 | | | |
| 20273 | ACTIVE | N | N083-00-1/331 | Station Control Room - Station Building - Tufnell Park Stn | | Lead Paint/Lead | Surveyed – Not Detected | | | | Handrail / Ladder Lead Content - Report R410510 02/06/2014 | | | | | |
| 17043 | ACTIVE | N | N083-00-1/331/CLG-01 | Ceiling: Suspended - 1 - Station Control Room - Station Building - Tufnell Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Tank Pipe Lagging - Fibreglass; Plasterboard; Concrete Ceiling above False Ceiling | | | | YES | |
| 17042 | ACTIVE | N | N083-00-1/331/CLG-01 | Ceiling: Suspended - 1 - Station Control Room - Station Building - Tufnell Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 20287 | ACTIVE | N | N083-00-1/331/DORS | Doors - Station Control Room - Station Building - Tufnell Park Stn | | Lead Paint/Lead | Surveyed – Not Detected | | | | Door to Corridor - Brown Varnish | | | | | |
| 20281 | ACTIVE | N | N083-00-1/331/DORS | Doors - Station Control Room - Station Building - Tufnell Park Stn | | Lead Paint/Lead | Surveyed – Not Detected | | | | Door to yard - Lead Paint Content | | | | | |
| 18917 | ACTIVE | N | N083-00-1/331/WAL-001 | Wall: Internal - 1 - Station Control Room - Station Building - Tufnell Park Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 18481 | ACTIVE | N | N083-00-1/331/WAL-002 | Wall: Internal - 2 - Station Control Room - Station Building - Tufnell Park Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 18773 | ACTIVE | N | N083-00-1/331/WAL-003 | Wall: Internal - 3 - Station Control Room - Station Building - Tufnell Park Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |



Hazardous Material Asset Register - Summary



N083-00 - Station Building - Tufnell Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 20283 | ACTIVE | N | N083-00-1/331/WDW-01 | Window - 1 - Station Control Room - Station Building - Tufnell Park Stn | | Lead Paint/Lead | Surveyed – Not Detected | | | | Window Frame - Lead Paint | | | | | |
| 20276 | ACTIVE | N | N083-00-1/331/WDW-01 | Window - 1 - Station Control Room - Station Building - Tufnell Park Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Bars to window - lead content in paint | | | | | |
| 20277 | ACTIVE | N | N083-00-1/331/WDW-02 | Window - 2 - Station Control Room - Station Building - Tufnell Park Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Bars to Window Lead Paint Content | | | | | |
| 20284 | ACTIVE | N | N083-00-1/331/WDW-02 | Window - 2 - Station Control Room - Station Building - Tufnell Park Stn | | Lead Paint/Lead | Surveyed – Not Detected | | | | Window Frame Lead Paint Content | | | | | |
| 20279 | ACTIVE | N | N083-00-1/331/WDW-03 | Window - 3 - Station Control Room - Station Building - Tufnell Park Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Lead Paint Content in Bars to Window | | | | | |
| 20285 | ACTIVE | N | N083-00-1/331/WDW-03 | Window - 3 - Station Control Room - Station Building - Tufnell Park Stn | | Lead Paint/Lead | Surveyed – Not Detected | | | | Window frame - Lead Paint Content | | | | | |
| 20286 | ACTIVE | N | N083-00-1/331/WLS | Walls: Internal - Station Control Room - Station Building - Tufnell Park Stn | | Lead Paint/Lead | Surveyed – Not Detected | | | | All Walls - Cream Gloss | | | | | |
| 9463 | ACTIVE | N | N083-00-1/401 | Bin Store - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17903 | ACTIVE | N | N083-00-1/401 | Bin Store - Station Building - Tufnell Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Cupboard - Supalux Panels | | | | | |
| 17044 | ACTIVE | N | N083-00-1/401/CLG-01 | Ceiling: Solid - 1 - Bin Store - Station Building - Tufnell Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels | | | | | |
| 18774 | ACTIVE | N | N083-00-1/401/CLG-01 | Ceiling: Solid - 1 - Bin Store - Station Building - Tufnell Park Stn | Void | Asbestos | No Access: Presumed | | | | Above False Ceiling | | | | YES | |
| 9464 | ACTIVE | N | N083-00-1/416 | Toilet: Male - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17045 | ACTIVE | N | N083-00-1/416 | Toilet: Male - Station Building - Tufnell Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9465 | ACTIVE | N | N083-00-1/417 | Toilet: Female - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17046 | ACTIVE | N | N083-00-1/417 | Toilet: Female - Station Building - Tufnell Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



| N083-00 - Station Building - Tufnell Park Stn | | | | | | | | | | | | | | | | |
|---|--------|-------------|----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
| 9466 | ACTIVE | N | N083-00-1/631 | Stairs: Spiral - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17048 | ACTIVE | N | N083-00-1/631 | Stairs: Spiral - Station Building - Tufnell Park Stn | Pipe Lagging | Asbestos | Surveyed – Not Detected | | | | Non Asbestos | | | | | |
| 17047 | ACTIVE | N | N083-00-1/631/CLG-01 | Ceiling: Suspended - 1 - Spiral Stairs - Station Building - Tufnell Park Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Caulking - Non Asbestos | | | | | |
| 9467 | ACTIVE | N | N083-00-1/661 | Switch Room - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18775 | ACTIVE | N | N083-00-1/661 | Switch Room - Station Building - Tufnell Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels | | | | | |
| 17050 | ACTIVE | N | N083-00-1/661 | Switch Room - Station Building - Tufnell Park Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box(es) - asbestos materials within | | 3 | | | |
| 17049 | ACTIVE | N | N083-00-1/661 | Switch Room - Station Building - Tufnell Park Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes - asbestos materials within 1 x 30 amps, 6 x 60 amps, 2 x 100 amps. Wall 7 | | 9 | | | |
| 9468 | ACTIVE | N | N083-00-1/663 | Switch Room - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9469 | ACTIVE | N | N083-00-1/664 | Switch Cupboard - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17051 | ACTIVE | N | N083-00-1/664 | Switch Cupboard - Station Building - Tufnell Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9470 | ACTIVE | N | N083-00-1/665 | Switch Room - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17904 | ACTIVE | N | N083-00-1/665 | Switch Room - Station Building - Tufnell Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 9471 | ACTIVE | N | N083-00-1/746 | SCR - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17052 | ACTIVE | N | N083-00-1/746 | SCR - Station Building - Tufnell Park Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 17053 | ACTIVE | N | N083-00-1/746/CLG-01 | Ceiling: Solid - 1 - SCR - Station Building - Tufnell Park Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 17054 | ACTIVE | N | N083-00-1/791 | Vent Shaft - Station Building - Tufnell Park Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Caulking - Non Asbestos | | | | | |
| 17055 | ACTIVE | N | N083-00-1/901 | Vent Shaft - Station Building - Tufnell Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | No Access High Level | | | | | |



Hazardous Material Asset Register - Summary



N083-00 - Station Building - Tufnell Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18776 | ACTIVE | N | N083-00-1/901 | Vent Shaft - Station Building - Tufnell Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Sealed Door into Vent Shaft | | | | | |
| 9472 | ACTIVE | N | N083-00-1/951 | Pump Room - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17056 | ACTIVE | N | N083-00-1/951 | Pump Room - Station Building - Tufnell Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | surveyed in original type 2 management survey R19038 | | | | | |
| 9473 | ACTIVE | N | N083-00-1/952 | Disused Room - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17058 | ACTIVE | N | N083-00-1/952/CLG-01 | Ceiling: Solid - 1 - Disused Room - Station Building - Tufnell Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plaster on Solid Walls & Ceiling; Wooden Match Board above window - above False Ceiling | | | | YES | |
| 18777 | ACTIVE | N | N083-00-1/952/CLG-01 | Ceiling: Solid - 1 - Disused Room - Station Building - Tufnell Park Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 17057 | ACTIVE | N | N083-00-1/952/FLR-01 | Floor - 1 - Disused Room - Station Building - Tufnell Park Stn | Void | Asbestos | Surveyed – Not Detected | | | | Wooden Battens; Loose Clinker Concrete beneath Quarry Tiles; Wooden Floor Boards, Wooden Skirting | | | | | YES |
| 17059 | ACTIVE | N | N083-00-1/952/WAL-001 | Wall: Internal - 1 - Disused Room - Station Building - Tufnell Park Stn | | Anthrax | Surveyed – Not Detected | | | | No Anthrax Detected | | | | | |
| 9474 | ACTIVE | N | N083-00-2/131 | LMR - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9475 | ACTIVE | N | N083-00-2/201 | Passage - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17060 | ACTIVE | N | N083-00-2/201 | Passage - Station Building - Tufnell Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed | | | | | |
| 9476 | ACTIVE | N | N083-00-2/202 | Passage - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20016 | ACTIVE | N | N083-00-2/202 | Passage - Station Building - Tufnell Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Lift lobby | | | | | |
| 9477 | ACTIVE | N | N083-00-2/203 | Passage - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17061 | ACTIVE | N | N083-00-2/203 | Passage - Station Building - Tufnell Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Entering to lift lobby | | | | | |
| 9478 | ACTIVE | N | N083-00-2/204 | Passage - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N083-00 - Station Building - Tufnell Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-------------------------------|--|------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18778 | ACTIVE | N | N083-00-2/204 | Passage - Station Building - Tufnell Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Lift lobby | | | | | |
| 9479 | ACTIVE | N | N083-00-2/205 | Passage - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Surveyed – Asbestos Known | | | | | | | | | |
| 17062 | ACTIVE | N | N083-00-2/205 | Passage - Station Building - Tufnell Park Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring Caulking - Non Asbestos | | | | | |
| 42067 | ACTIVE | N | N083-00-2/205 | Passage - Station Building - Tufnell Park Stn | Durasteel | Asbestos | Known | | | | Durasteel Panels around all lift doors are a mixture of Asbestos and Non Asbestos types. Unable to locate within area. | | | | | |
| 9480 | ACTIVE | N | N083-00-2/206 | Passage - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Surveyed – Asbestos Known | | | | | | | | | |
| 17063 | ACTIVE | N | N083-00-2/206 | Passage - Station Building - Tufnell Park Stn | Durasteel | Asbestos | No Access: Presumed | | | | Durasteel Panels around all lift doors are a mixture of Asbestos and Non Asbestos types. Unable to locate within area. | | | | | |
| 9481 | ACTIVE | N | N083-00-2/207 | Passage - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17905 | ACTIVE | N | N083-00-2/207 | Passage - Station Building - Tufnell Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Passage way | | | | | |
| 9482 | ACTIVE | N | N083-00-2/208 | Passage - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17064 | ACTIVE | N | N083-00-2/208 | Passage - Station Building - Tufnell Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Passageway | | | | | |
| 9483 | ACTIVE | N | N083-00-2/209 | Passage - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18779 | ACTIVE | N | N083-00-2/209 | Passage - Station Building - Tufnell Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Passageway to stairs | | | | | |
| 9484 | ACTIVE | N | N083-00-2/261 | Platform 1 - Northbound Fast - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17065 | ACTIVE | N | N083-00-2/261 | Platform 1 - Northbound Fast - Station Building - Tufnell Park Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring Caulking - Non Asbestos | | | | | |
| 18780 | ACTIVE | N | N083-00-2/261/FLR-01 80914475 | Floor - 1 - Platform 1 - Station Building - Tufnell Park Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 1 Invert - Various Cables | | | | | YES |
| 17066 | ACTIVE | N | N083-00-2/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Tufnell Park Stn | Gasket :Pipework | Asbestos | Strongly Presumed | | | | Platform 1 Invert - 3 x Gaskets - 20m along from 2/731 platform side | | | | | YES |



Hazardous Material Asset Register - Summary



N083-00 - Station Building - Tufnell Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-------------------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9485 | ACTIVE | N | N083-00-2/401 | Store - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17906 | ACTIVE | N | N083-00-2/401/CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Tufnell Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 17069 | ACTIVE | N | N083-00-2/401/CLG-01 80914480 | Ceiling: Suspended - 1 - Store - Station Building - Tufnell Park Stn Ceiling: Suspended | Void | Asbestos | No Access: Presumed | | | | Above Supalux Ceiling Panels to Underside of Steps | | | | YES | |
| 17068 | ACTIVE | N | N083-00-2/401/FLR-01 | Floor - 1 - Store - Station Building - Tufnell Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel under Stairs | | | | | |
| 9486 | ACTIVE | N | N083-00-2/601 | Stairs: Linear - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17070 | ACTIVE | N | N083-00-2/601 | Stairs: Linear - Station Building - Tufnell Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Stairs | | | | | |
| 9487 | ACTIVE | N | N083-00-2/602 | Stairs: Linear - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17071 | ACTIVE | N | N083-00-2/602 | Stairs: Linear - Station Building - Tufnell Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Stairs | | | | | |
| 9488 | ACTIVE | N | N083-00-2/603 | Stairs: Linear - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18482 | ACTIVE | N | N083-00-2/603 | Stairs: Linear - Station Building - Tufnell Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Lobby to stairs | | | | | |
| 9489 | ACTIVE | N | N083-00-2/604 | Stairs: Linear - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17072 | ACTIVE | N | N083-00-2/604 | Stairs: Linear - Station Building - Tufnell Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Stairs | | | | | |
| 18781 | ACTIVE | N | N083-00-2/636 | Overbridge - Station Building - Tufnell Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | | | | | | |
| 17073 | ACTIVE | N | N083-00-2/637 | Overbridge - Station Building - Tufnell Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Over ridge | | | | | |
| 9490 | ACTIVE | N | N083-00-2/661 | Switch Room - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18918 | ACTIVE | N | N083-00-2/661 | Switch Room - Station Building - Tufnell Park Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Partition Wall | | | | | |
| 17074 | ACTIVE | N | N083-00-2/661 | Switch Room - Station Building - Tufnell Park Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes - Insulation Within - 3 x 100 amps, 1 x 200 amps, 3 x 60 amps. Walls 1&3 | | 7 | | | |



Hazardous Material Asset Register - Summary



N083-00 - Station Building - Tufnell Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------------------|--|------------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 69756 | ACTIVE | N | N083-00-2/661/WAL-003 80914513 | Wall: Internal - 3 - Switch Room - Station Building - Tufnell Park Stn Wall: Internal | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Transformer Box - asbestos materials within | | 1 | | | |
| 9491 | ACTIVE | N | N083-00-2/711 | Relay Room - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42902 | ACTIVE | N | N083-00-2/711 80143119 | Relay Room - Station Building - Tufnell Park Stn Room Assets | Other Electrical Boxes | Asbestos | Presumed | | | | 600v electrical box - Presumed asbestos insulation within | | 1 | | | |
| 42903 | INACTIVE | N | N083-00-2/711 | Relay Room - Station Building - Tufnell Park Stn | PCBs | Polychlorinated biphenyl | Presumed | | | | Presumed PCB's within Roller Shutter Cabinet | | | | | |
| 53594 | ACTIVE | N | N083-00-2/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Tufnell Park Stn | Cable: Sheath | Asbestos | Presumed | | | | presumed asbestos cables to bunch - within cabinet wall 1 | | | | | |
| 17075 | INACTIVE | N | N083-00-2/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Tufnell Park Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Electrical Boxes - insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | | |
| 53595 | ACTIVE | N | N083-00-2/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Tufnell Park Stn | Cable Ducts: Cement | Asbestos | Presumed | | | | filled in duct to cabinet going into invert | | | | | |
| 53592 | ACTIVE | N | N083-00-2/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Tufnell Park Stn | Other Boarding | Asbestos | Presumed | | | | rack 2 inside roller shutter to wall 1 - 6x composite brown boarding to equipment | | | | | |
| 18213 | ACTIVE | N | N083-00-2/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Tufnell Park Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 2x Green Cables 600 volts going into Inverts | | 2 | | | |
| 53593 | ACTIVE | N | N083-00-2/711/WAL-002 80914519 | Wall: Internal - 2 - Relay Room - Station Building - Tufnell Park Stn Wall: Internal | Other Boarding | Asbestos | Presumed | | | | Brown composite board to box. Wall 2 | | 1 | | | |
| 9492 | ACTIVE | N | N083-00-2/731 | CER - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18782 | ACTIVE | N | N083-00-2/731/WAL-002 | Wall: Internal - 2 - CER - Station Building - Tufnell Park Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Green Cables going into Inverts | | 2 | | | |
| 17076 | ACTIVE | N | N083-00-2/731/WAL-002 | Wall: Internal - 2 - CER - Station Building - Tufnell Park Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | White Cables going into Inverts | | 1 | | | |
| 9493 | ACTIVE | N | N083-00-2/732 | CER - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18783 | ACTIVE | N | N083-00-2/732 | CER - Station Building - Tufnell Park Stn | Other Boarding | Asbestos | Strongly Presumed | | | | Paxoline Board | | 1 | | | |
| 17077 | ACTIVE | N | N083-00-2/732/FLR-01 | Floor - 1 - CER - Station Building - Tufnell Park Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |



Hazardous Material Asset Register - Summary



N083-00 - Station Building - Tufnell Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|--------------------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17078 | ACTIVE | N | N083-00-2/732/WAL-002 80914533 | Wall: Internal - 2 - CER - Station Building - Tufnell Park Stn Wall: Internal | Isolator Switches | Asbestos | No Access: Presumed | | | | Switch Boxes - asbestos materials within - 2 x 60 amps. Wall 4 | | 2 | | | |
| 9494 | ACTIVE | N | N083-00-2/733 | CER - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17079 | ACTIVE | N | N083-00-2/733 | CER - Station Building - Tufnell Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9495 | ACTIVE | N | N083-00-2/761 | Computer Equipment Cupboard - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17080 | ACTIVE | N | N083-00-2/761 | Computer Equipment Cupboard - Station Building - Tufnell Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | New Electrical Cabinets | | | | | |
| 9496 | ACTIVE | N | N083-00-2/762 | Computer Equipment Cupboard - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17081 | ACTIVE | N | N083-00-2/762 | Computer Equipment Cupboard - Station Building - Tufnell Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | New Electrical Cabinets | | | | | |
| 9497 | ACTIVE | N | N083-00-2/763 | Computer Equipment Cupboard - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18784 | ACTIVE | N | N083-00-2/763 | Computer Equipment Cupboard - Station Building - Tufnell Park Stn | No Access | Asbestos | Surveyed – Not Detected | | | | New Electrical Cabinets | | | | | |
| 17082 | ACTIVE | N | N083-00-2/791 | Vent Shaft - Station Building - Tufnell Park Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Rings - Caulking | | | | | |
| 9498 | ACTIVE | N | N083-00-3/081 | Lobby - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17083 | ACTIVE | N | N083-00-3/081 | Lobby - Station Building - Tufnell Park Stn | Other Electrical Boxes | Asbestos | Not Found during Inspection | | | | No asbestos containing materials within 3/081 See 3/711 (Rooms connected) | | | | | |
| 9499 | ACTIVE | N | N083-00-3/121 | Platform Invert - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18785 | ACTIVE | N | N083-00-3/121 | Platform Invert - Station Building - Tufnell Park Stn | | Asbestos | Surveyed – Not Detected | | | | Bitumen Cable Ducts & Insulation to Ceiling | | | | | |
| 17084 | ACTIVE | N | N083-00-3/121 | Platform Invert - Station Building - Tufnell Park Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 2 Invert - Various Cables. Encapsulation of up to 10 x Cables | | | | | |
| 17907 | ACTIVE | N | N083-00-3/121 | Platform Invert - Station Building - Tufnell Park Stn | Cable Ducts: Cement | Asbestos | Strongly Presumed | | | | Cement Cable Ducts | | | | | |



Hazardous Material Asset Register - Summary



N083-00 - Station Building - Tufnell Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------------------------|--|------------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9500 | ACTIVE | N | N083-00-3/262 | Platform 2 - Southbound Fast - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17085 | ACTIVE | N | N083-00-3/262 | Platform 2 - Southbound Fast - Station Building - Tufnell Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9501 | ACTIVE | N | N083-00-3/662 | Switch Room - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17087 | ACTIVE | N | N083-00-3/662 | Switch Room - Station Building - Tufnell Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |
| 69757 | ACTIVE | N | N083-00-3/662 | Switch Room - Station Building - Tufnell Park Stn | Other Boarding | Asbestos | Presumed | | | | Various Composite Panels and Brackets to walls and equipment | | | | | |
| 17088 | ACTIVE | N | N083-00-3/662/ WAL-003 80914607 | Wall: Internal - 3 - Switch Room - Station Building - Tufnell Park Stn Wall: Internal | Cable: Sheath | Asbestos | Strongly Presumed | | | | Green Cables going into Inverts | | 2 | | | |
| 18919 | ACTIVE | N | N083-00-3/662/ WAL-003 80914607 | Wall: Internal - 3 - Switch Room - Station Building - Tufnell Park Stn Wall: Internal | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Westinghouse Box - asbestos materials within | | 1 | | | |
| 9502 | ACTIVE | N | N083-00-3/663 | Switch Cupboard - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18786 | ACTIVE | N | N083-00-3/663 | Switch Cupboard - Station Building - Tufnell Park Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Transformer Box(es) - asbestos materials within | | 1 | | | |
| 9503 | ACTIVE | N | N083-00-3/664 | Switch Cupboard - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17089 | ACTIVE | N | N083-00-3/664 | Switch Cupboard - Station Building - Tufnell Park Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9504 | ACTIVE | N | N083-00-3/711 | Relay Room - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42900 | ACTIVE | N | N083-00-3/711 80143121 | Relay Room - Station Building - Tufnell Park Stn Room Assets | Other Electrical Boxes | Asbestos | Removed | | | | 600v electrical box - Presumed asbestos insulating materials within Now Removed | | 1 | | | |
| 42901 | INACTIVE | N | N083-00-3/711 | Relay Room - Station Building - Tufnell Park Stn | PCBs | Polychlorinated biphenyl | Presumed | | | | Presumed PCB's within Roller Shutter cabinet | | | | | |
| 53588 | ACTIVE | N | N083-00-3/711/ WAL-001 80914628 | Wall: Internal - 1 - Relay Room - Station Building - Tufnell Park Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | Old style CTB boxes. Wall 1 | | 2 | | | |
| 53587 | ACTIVE | N | N083-00-3/711/ WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Tufnell Park Stn | Other Boarding | Asbestos | Removed | | | | brown composite materials to box on wall 2 | | | | | |



Hazardous Material Asset Register - Summary



N083-00 - Station Building - Tufnell Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|--------------------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17908 | ACTIVE | N | N083-00-3/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Tufnell Park Stn | Cable: Sheath | Asbestos | Removed | | | | 2x 50cm Green Cables going into Inverts | | 2 | | | |
| 53590 | ACTIVE | N | N083-00-3/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Tufnell Park Stn | Cable: Sheath | Asbestos | Removed | | | | asbestos cables to duct in roller cabinet 2 wall 3 | | | | | |
| 17090 | ACTIVE | N | N083-00-3/711/WAL-003 80914630 | Wall: Internal - 3 - Relay Room - Station Building - Tufnell Park Stn Wall: Internal | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Westinghouse Box - asbestos materials within. Wall 3 | | 1 | | | |
| 53591 | ACTIVE | N | N083-00-3/711/WAL-003 80914630 | Wall: Internal - 3 - Relay Room - Station Building - Tufnell Park Stn Wall: Internal | Cable Ducts: Cement | Asbestos | Presumed | | | | filled in duct to floor wall 3 | | 1 | | | |
| 53589 | ACTIVE | N | N083-00-3/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Tufnell Park Stn | Other Boarding | Asbestos | Removed | | | | within roller shutter 1 8 x paxoline board to equipment on rack | | | | | |
| 9505 | ACTIVE | N | N083-00-3/731 | Switch Room - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17091 | ACTIVE | N | N083-00-3/731/CLG-01 80914639 | Ceiling: Solid - 1 - Switch Room - Station Building - Tufnell Park Stn Ceiling: Solid | Void | Asbestos | Surveyed – Not Detected | | | | Above False Ceiling. No void identified, ceiling is solid | | | | YES | |
| 18483 | ACTIVE | N | N083-00-3/731/FLR-01 | Floor - 1 - Switch Room - Station Building - Tufnell Park Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Hatch to flooded Invert | | | | | YES |
| 42196 | ACTIVE | N | N083-00-A/131 | LMR - Station Building - Tufnell Park Stn | Durasteel | Asbestos | Room: Surveyed – Asbestos Known | | | | Lift Shaft 1 -30m² Durasteel Panels to shaft (PLEASE BE AWARE THAT SOME PANELS HAVE BEEN IDENTIFIED AS CONTAINING ASBESTOS PLEASE CONTACT THIS UNIT IF YOUR WORK WILL DISTURB THESE PANELS) | | | | N | N |
| 45357 | ACTIVE | N | N083-00-A/131 | LMR - Station Building - Tufnell Park Stn | Durasteel | Asbestos | Not Found during Inspection | | | | Lift Shaft 2 - Durasteel panels to lift shaft (See report R488651) | | | | N | N |
| 42217 | ACTIVE | N | N083-00-A/131 | LMR - Station Building - Tufnell Park Stn | | Asbestos | Sampled – Not Detected | | | | Lift Controller 2 - 6 x Brown Composite Panels throughout Lift Motor Room to Lift Controller 2 | | | | | |
| 42215 | ACTIVE | N | N083-00-A/131 | LMR - Station Building - Tufnell Park Stn | Other Boarding | Asbestos | Sampled – Not Detected | | | | 6 x Brown Composite Panels throughout Lift Motor Room - to Lift Controller 1 | | 6 | | N | N |
| 42201 | ACTIVE | N | N083-00-A/131 | LMR - Station Building - Tufnell Park Stn | Durasteel | Asbestos | Room: Surveyed – Asbestos Known | | | | Lift Shaft 2 -30m² Durasteel Panels to shaft (PLEASE BE AWARE THAT SOME PANELS HAVE BEEN IDENTIFIED AS CONTAINING ASBESTOS PLEASE CONTACT THIS UNIT IF YOUR WORK WILL DISTURB THESE PANELS) | | | | N | N |
| 42200 | ACTIVE | N | N083-00-A/131 | LMR - Station Building - Tufnell Park Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Lift Shaft 2 - Tunnel Caulking | | | | N | N |



Hazardous Material Asset Register - Summary



N083-00 - Station Building - Tufnell Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|--------------------------------------|--|------------------------|-----------------|---------------------------------|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 42206 | ACTIVE | N | N083-00-A/131 | LMR - Station Building - Tufnell Park Stn | Durasteel | Asbestos | Room: Surveyed – Asbestos Known | | | | LIFT SHAFT 1 & 2 PLEASE BE AWARE THAT SOME PANELS HAVE BEEN IDENTIFIED AS CONTAINING ASBESTOS PLEASE CONTACT THE HAZARDOUS MATERIALS UNIT IF YOUR WORK WILL DISTURB THESE PANELS | | | | N | N |
| 45356 | ACTIVE | N | N083-00-A/131 | LMR - Station Building - Tufnell Park Stn | Durasteel | Asbestos | Not Found during Inspection | | | | Lift Shaft 1 - Durasteel panels to lift shaft (See report R488651) | | | | N | N |
| 42195 | ACTIVE | N | N083-00-A/131 | LMR - Station Building - Tufnell Park Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Lift Shaft 1 - Tunnel Caulking | | | | N | N |
| 42187 | ACTIVE | N | N083-00-A/131 | LMR - Station Building - Tufnell Park Stn | Other Boarding | Asbestos | Known | | | | Materials within Vent Shaft | | | | N | N |
| 42186 | ACTIVE | N | N083-00-A/131 | LMR - Station Building - Tufnell Park Stn | Other Electrical Boxes | Asbestos | Removed | | | | 2 x Circuit Breakers & Busbar Removed by projects | | 2 | | N | N |
| 42191 | ACTIVE | N | N083-00-A/131 | LMR - Station Building - Tufnell Park Stn | Rope Gaskets | Asbestos | Strongly Presumed | | | | Rope Material behind joints in the vent chamber | | | | N | N |
| 42199 | ACTIVE | N | N083-00-A/131 | LMR - Station Building - Tufnell Park Stn | Cable: Sheath | Asbestos | No Access: Presumed | | | | Lift Shaft 1 - 3x 25mm Woven Shealth Cables Possible left in shaft by Projects | | 1 | | N | N |
| 42202 | ACTIVE | N | N083-00-A/131 | LMR - Station Building - Tufnell Park Stn | Cable: Sheath | Asbestos | Sampled – Not Detected | | | | Lift Shaft 2 - 3 x 25mm Woven Shealth Cables 4-RAIL sampled Cable sheath, 7m, to cables NADIS No access into lift shaft during 2020 re-inspection. Permit required with L&E | | 2 | | N | N |
| 42214 | ACTIVE | N | N083-00-A/131 | LMR - Station Building - Tufnell Park Stn | Other Boarding | Asbestos | Removed | | | | Lift Controller 1 - 2m² Black composite panel within Lift Motor Room Removed by asbestos removal contractors (appointed by HMU) on behalf of the Lift Refurbishment Project ES2953c & ES2953d, Edenbeck, date of removal 18/07/15 | 2 | | | N | N |
| 42216 | ACTIVE | N | N083-00-A/131 | LMR - Station Building - Tufnell Park Stn | Other Boarding | Asbestos | Removed | | | | Lift Controller 2 - 2m² Black Composite Panel within Lift Controller 2 Removed by asbestos removal contractors (appointed by HMU) on behalf of the Lift Refurbishment Project ES2953c & ES2953d, Edenbeck, date of removal 18/07/15 | 2 | | | N | N |
| 42194 | ACTIVE | N | N083-00-A/131 | LMR - Station Building - Tufnell Park Stn | Lead/Leading | Lead Paint/Lead | Removed | | | | Yellow Steps - lead paint strongly persumed 16/03/2016 steps have been removed | | | | N | N |
| 42193 | ACTIVE | N | N083-00-A/131 | LMR - Station Building - Tufnell Park Stn | Lead/Leading | Lead Paint/Lead | Strongly Presumed | | | | Red Paint on Beams (now painted black) | | | | N | N |
| 42184 | ACTIVE | N | N083-00-A/131/ CLG-01 80914653 | Ceiling: Solid - 1 - LMR - Station Building - Tufnell Park Stn Ceiling: Solid | No Access | Asbestos | Surveyed – Not Detected | | | | No void identified, ceiling is solid | | | | | |



Hazardous Material Asset Register - Summary



N083-00 - Station Building - Tufnell Park Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|------------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 42189 | ACTIVE | N | N083-00-A/131/WAL-001 | Wall: Internal - 1 - LMR - Station Building - Tufnell Park Stn | Other Electrical Boxes | Asbestos | Removed | | | | 0.5m² Controller box 1&2 - Sulluminite within boxes Removed by Projects | | | | N | N |
| 42192 | ACTIVE | N | N083-00-A/131/WAL-002 | Wall: Internal - 2 - LMR - Station Building - Tufnell Park Stn | Other Electrical Boxes | Asbestos | Removed | | | | 0.5m² Distribution board - Sulluminite within boxes Removed by Projects | | | | N | N |
| 42188 | ACTIVE | N | N083-00-A/131/WAL-004 | Wall: Internal - 4 - LMR - Station Building - Tufnell Park Stn | Other Electrical Boxes | Asbestos | Removed | | | | 1x Transformer box Removed by Projects | | 1 | | N | N |
| 42164 | ACTIVE | N | N083-00-A/131/WAL-004 | Wall: Internal - 4 - LMR - Station Building - Tufnell Park Stn | Isolator Switches | Asbestos | Removed | | | | 3 x Switch Boxes - Insulation within Removed by projects | | 3 | | N | N |
| 42190 | ACTIVE | N | N083-00-A/131/WAL-004 | Wall: Internal - 4 - LMR - Station Building - Tufnell Park Stn | Isolator Switches | Asbestos | Removed | | | | 1x Switch box Removed by projects | | 1 | | N | N |
| 9506 | ACTIVE | N | N083-00-A/576 | Ladder - Station Building - Tufnell Park Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18484 | ACTIVE | N | N083-00-A/576 | Ladder - Station Building - Tufnell Park Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Flammable Store (Durasteel) - Non Asbestos | | | | | |
| 18788 | ACTIVE | N | N083-00-A/576 | Ladder - Station Building - Tufnell Park Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | 30m² Boarding to lift access - Non Asbestos | | | | | |
| 42666 | ACTIVE | N | N083-00-A/576 | Ladder - Station Building - Tufnell Park Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Red gloss paint to beam in Lift Motor Room A/576 0.69 | | | R488652 | N | N |
| 42665 | ACTIVE | N | N083-00-A/576 | Ladder - Station Building - Tufnell Park Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Red gloss paint to beam in Lift Motor Room A/576 0.52% | | | R488652 | N | N |
| 42664 | ACTIVE | N | N083-00-A/576 | Ladder - Station Building - Tufnell Park Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Red gloss paint to beam in Lift Motor Room A/576 0.58% | | | R488652 | N | N |
| 42667 | ACTIVE | N | N083-00-A/576 | Ladder - Station Building - Tufnell Park Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Black matt paint to beam in Lift Motor Room A/576 0.11% | | | R488652 | N | N |
| 17104 | ACTIVE | N | N083-00-A/576/WAL-001 | Wall: Internal - 1 - Ladder - Station Building - Tufnell Park Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |
| 17105 | ACTIVE | N | N083-00-A/576/WAL-001 | Wall: Internal - 1 - Ladder - Station Building - Tufnell Park Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Durasteel Panel | | | | | |

N085-00 - Station Building - Kentish Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 9507 | ACTIVE | N | N085-00-1/001 | Booking Hall - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N085-00 - Station Building - Kentish Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18530 | ACTIVE | N | N085-00-1/001/CLG-01 | Ceiling: Solid - 1 - Booking Hall - Station Building - Kentish Town Stn | | Anthrax | Surveyed – Not Detected | | | | No Anthrax Detected | | | | YES | |
| 16853 | ACTIVE | N | N085-00-1/001/CLG-01 | Ceiling: Solid - 1 - Booking Hall - Station Building - Kentish Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, plaster, render and metal work. All cables PVC above Concrete Ceiling | | | | YES | |
| 9508 | ACTIVE | N | N085-00-1/011 | Ticket Office - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70627 | ACTIVE | N | N085-00-1/011 | Ticket Office - Station Building - Kentish Town Stn | | Asbestos | Sampled – Not Detected | | | | Bitumen cable duct in floor void to base of wall - non asbestos | | | R736326 | | |
| 9509 | ACTIVE | N | N085-00-1/021 | POM - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16855 | ACTIVE | N | N085-00-1/021/FLR-01 | Floor - 1 - POM - Station Building - Kentish Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Beneath Computer Flooring | | | | | YES |
| 9510 | ACTIVE | N | N085-00-1/031 | Mess Room - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16857 | ACTIVE | N | N085-00-1/031 | Mess Room - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 16856 | ACTIVE | N | N085-00-1/031 | Mess Room - Station Building - Kentish Town Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | LUL Heater - Foam | | | | | |
| 16858 | ACTIVE | N | N085-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Kentish Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Plaster above False Ceiling | | | | YES | |
| 9511 | ACTIVE | N | N085-00-1/036 | Toilet: Unisex - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16859 | ACTIVE | N | N085-00-1/036 | Toilet: Unisex - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9512 | ACTIVE | N | N085-00-1/071 | Circulation Area - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18531 | ACTIVE | N | N085-00-1/071/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Kentish Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above False Ceiling - No Anthrax Detected; Above Bulk Heads by escalators Concrete, plaster, render and metal work. All cables PVC. | | | | YES | |
| 9513 | ACTIVE | N | N085-00-1/081 | Lobby - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16860 | ACTIVE | N | N085-00-1/081/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Kentish Town Stn | Void | Asbestos | No Access: Presumed | | | | Above False Ceiling | | | | YES | |



Hazardous Material Asset Register - Summary



N085-00 - Station Building - Kentish Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 9514 | ACTIVE | N | N085-00-1/201 | Passage - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16861 | ACTIVE | N | N085-00-1/201/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Kentish Town Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 9515 | ACTIVE | N | N085-00-1/236 | Lobby - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16862 | ACTIVE | N | N085-00-1/236/CLG-01 80906416 | Ceiling: Suspended - 1 - Lobby - Station Building - Kentish Town Stn Ceiling: Suspended | Void | Asbestos | Removed | | | | Above Supalux. | | | | YES | |
| 19132 | ACTIVE | N | N085-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Kentish Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 9516 | ACTIVE | N | N085-00-1/237 | Passage - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16863 | ACTIVE | N | N085-00-1/237 | Passage - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9517 | ACTIVE | N | N085-00-1/281 | Station Control Room - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16864 | ACTIVE | N | N085-00-1/281/CLG-01 | Ceiling: Suspended - 1 - Station Control Room - Station Building - Kentish Town Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Skirting Board Plaster | | | | | |
| 18908 | ACTIVE | N | N085-00-1/281/CLG-01 | Ceiling: Suspended - 1 - Station Control Room - Station Building - Kentish Town Stn | Void | Asbestos | No Access: Presumed | | | | Above Soft Board; Skirting Board Plaster False ceiling | | | | YES | |
| 9518 | ACTIVE | N | N085-00-1/406 | SVC - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16865 | ACTIVE | N | N085-00-1/406 | SVC - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9519 | ACTIVE | N | N085-00-1/411 | Locker Room - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16867 | ACTIVE | N | N085-00-1/411/CLG-01 | Ceiling: Suspended - 1 - Locker Room - Station Building - Kentish Town Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux | | | | YES | |
| 16866 | ACTIVE | N | N085-00-1/411/CLG-01 | Ceiling: Suspended - 1 - Locker Room - Station Building - Kentish Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |



Hazardous Material Asset Register - Summary



N085-00 - Station Building - Kentish Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|--------------------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18532 | ACTIVE | N | N085-00-1/411/FLR-01 | Floor - 1 - Locker Room - Station Building - Kentish Town Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Skirting Board Plaster | | | | | |
| 9520 | ACTIVE | N | N085-00-1/631 | Stairs: Spiral - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16868 | ACTIVE | N | N085-00-1/631 | Stairs: Spiral - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9521 | ACTIVE | N | N085-00-1/661 | Switch Room - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18533 | ACTIVE | N | N085-00-1/661/WAL-001 80906466 | Wall: Internal - 1 - Switch Room - Station Building - Kentish Town Stn Wall: Internal | Isolator Switches | Asbestos | Known | | | | Switch box 1 x 30 amps. Wall 1 - Switch Boxes confirmed to contain Flash guards, Arc Chutes & Cementious Blocks - All containing Asbestos have been labelled | | 1 | | N | N |
| 9522 | ACTIVE | N | N085-00-1/662 | Switch Cupboard - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16869 | ACTIVE | N | N085-00-1/662 | Switch Cupboard - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9523 | ACTIVE | N | N085-00-1/663 | Switch Cupboard - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19133 | ACTIVE | N | N085-00-1/663/CLG-01 | Ceiling: Suspended - 1 - Switch Cupboard - Station Building - Kentish Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 16870 | ACTIVE | N | N085-00-1/663/CLG-01 | Ceiling: Suspended - 1 - Switch Cupboard - Station Building - Kentish Town Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux | | | | YES | |
| 9524 | ACTIVE | N | N085-00-1/746 | SCR - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16871 | ACTIVE | N | N085-00-1/746 | SCR - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9525 | ACTIVE | N | N085-00-1/991 | Lobby - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16872 | ACTIVE | N | N085-00-1/991 | Lobby - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9526 | ACTIVE | N | N085-00-1/992 | Locker Room - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16873 | ACTIVE | N | N085-00-1/992 | Locker Room - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N085-00 - Station Building - Kentish Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------|---|---------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 9527 | ACTIVE | N | N085-00-1/993 | Store - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16874 | ACTIVE | N | N085-00-1/993 | Store - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9528 | ACTIVE | N | N085-00-1/994 | Store - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16875 | ACTIVE | N | N085-00-1/994 | Store - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9529 | ACTIVE | N | N085-00-2/151 | UMC - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18414 | ACTIVE | N | N085-00-2/151 | UMC - Station Building - Kentish Town Stn | Cable Ducts: Cement | Asbestos | Surveyed – Not Detected | | | | Cable Duct & Debris | | | | | |
| 43249 | ACTIVE | N | N085-00-2/151 | UMC - Station Building - Kentish Town Stn | | Asbestos | Room: Surveyed – No Known Asbestos | | | | MMMF gaitor 2no to A/C ductwork | | | R554126 | N | N |
| 43250 | ACTIVE | N | N085-00-2/151 | UMC - Station Building - Kentish Town Stn | Isolator Switches | Asbestos | Removed | | | | Materials within fire switch box 1no to column by entrance door | | | R554126 | N | N |
| 43246 | ACTIVE | N | N085-00-2/151 | UMC - Station Building - Kentish Town Stn | | Asbestos | Room: Surveyed – No Known Asbestos | | | | New durasteel panel 2m2 to storage bunker by escalator 2 | | | R554126 | N | N |
| 43266 | ACTIVE | N | N085-00-2/151 | UMC - Station Building - Kentish Town Stn | | Asbestos | Sampled – Not Detected | | | | Render on concrete has been sampled in several areas throughout this room. Walls and ceiling No asbestos detected. Please see survey report R554128 (27/09/2016) | | | R554128 | N | N |
| 43243 | ACTIVE | N | N085-00-2/151 | UMC - Station Building - Kentish Town Stn | | Asbestos | Sampled – Not Detected | | | | Plastic cables, metal conduits and cable management system and firestop and mastic - new throughout | | | R554126 | N | N |
| 43248 | ACTIVE | N | N085-00-2/151 | UMC - Station Building - Kentish Town Stn | Isolator Switches | Asbestos | Removed | | | | Materials within large combination fuse switch 1no to wall by switchboard 1 and 2 | | | R554126 | N | N |
| 43247 | ACTIVE | N | N085-00-2/151 | UMC - Station Building - Kentish Town Stn | Bitumen | Asbestos | Sampled – Not Detected | | | | Bitumen cable duct 1no to under stairs wall adjacent to escalator 2 machine | | | R554126 | N | N |
| 43242 | ACTIVE | N | N085-00-2/151 | UMC - Station Building - Kentish Town Stn | | Asbestos | Sampled – Not Detected | | | | Brickwork to walls columns and pillars | | | R554126 | N | N |
| 43241 | ACTIVE | N | N085-00-2/151 | UMC - Station Building - Kentish Town Stn | | Asbestos | Sampled – Not Detected | | | | Concrete slab to floor, ceiling, pillars and columns | | | R554126 | N | N |
| 43245 | INACTIVE | N | N085-00-2/151 | UMC - Station Building - Kentish Town Stn | Isolator Switches | Asbestos | Presumed | | | | Materials within combination fuse switches 5no to wall by 2/953 | | | R554126 | N | N |



Hazardous Material Asset Register - Summary



N085-00 - Station Building - Kentish Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 16876 | ACTIVE | N | N085-00-2/151 | UMC - Station Building - Kentish Town Stn | Isolator Switches | Asbestos | Known | | | | 5x Switch Boxes near to wall by 2/953 - Switch Boxes confirmed to contain Flash guards, Arc Chutes & Cementious Blocks - All containing Asbestos have been labelled. 3 x 100 amps, 1 x 60 amps, 1 x 200 amps | | 5 | | N | N |
| 43279 | ACTIVE | N | N085-00-2/151 | UMC - Station Building - Kentish Town Stn | Lead/Leading | Lead Paint/Lead | Known | | | | UMC 2/151 Yellow(Orange) Matt Beams and handrails 750 2.62% | | | R554127 | N | N |
| 43280 | ACTIVE | N | N085-00-2/151 | UMC - Station Building - Kentish Town Stn | Lead/Leading | Lead Paint/Lead | Known | | | | UMC 2/151 Grey Matt RSJ, Ceiling 530 9.96% | | | R554127 | N | N |
| 43278 | ACTIVE | N | N085-00-2/151 | UMC - Station Building - Kentish Town Stn | Lead/Leading | Lead Paint/Lead | Known | | | | UMC 2/151 White Gloss Walls at low level 1250 0.27% | | | R554127 | N | N |
| 43277 | ACTIVE | N | N085-00-2/151 | UMC - Station Building - Kentish Town Stn | Lead/Leading | Lead Paint/Lead | Known | | | | UMC 2/151 Yellow Gloss Walls at high level 460 0.16% | | | R554127 | N | N |
| 18534 | ACTIVE | N | N085-00-2/151/FLR-01 | Floor - 1 - UMC - Station Building - Kentish Town Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Flammable Store (Durasteel) - Non Asbestos | | | | | |
| 9530 | ACTIVE | N | N085-00-2/201 | Passage - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16877 | ACTIVE | N | N085-00-2/201/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Kentish Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux panels - To false ceiling by stairs (1/631) RSJ (In False ceiling) Vermiculate to ceiling void - Non asbestos | | | | Y | |
| 9531 | ACTIVE | N | N085-00-2/236 | Lobby - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16878 | ACTIVE | N | N085-00-2/236 | Lobby - Station Building - Kentish Town Stn | Cable: Sheath | Asbestos | Presumed | | | | Presumed asbestos cables still present, historically identified but could not be located during 2020 & 2024 re-inspections. There is no photo of the original ACM on record. There is also no recorded ACM removals for this room, although a series of removals have taken place over the years at this station. | | | | | |
| 9532 | ACTIVE | N | N085-00-2/237 | Lobby - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9533 | ACTIVE | N | N085-00-2/331 | Mess Room - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20077 | ACTIVE | N | N085-00-2/331 | Mess Room - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 70001 | ACTIVE | N | N085-00-2/331 | Mess Room - Station Building - Kentish Town Stn | | Asbestos | Sampled – Not Detected | | | | False ceiling tiles - Non asbestos, old false ceiling tiles above new - Non asbestos | | | R671001 | Y | |



Hazardous Material Asset Register - Summary



N085-00 - Station Building - Kentish Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-------------------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18689 | ACTIVE | N | N085-00-2/331/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Kentish Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plaster, Concrete above MMF false ceiling | | | | YES | |
| 9534 | ACTIVE | N | N085-00-2/416 | Toilet: Female - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16979 | ACTIVE | N | N085-00-2/416 | Toilet: Female - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9535 | ACTIVE | N | N085-00-2/417 | Toilet: Male - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16980 | ACTIVE | N | N085-00-2/417 | Toilet: Male - Station Building - Kentish Town Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - Foam | | | | | |
| 16982 | ACTIVE | N | N085-00-2/417/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Kentish Town Stn | Void | Asbestos | No Access: Presumed | | | | No Access above False Ceiling | | | | YES | |
| 16981 | ACTIVE | N | N085-00-2/417/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Kentish Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9536 | ACTIVE | N | N085-00-2/631 | Stairs: Spiral - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18690 | ACTIVE | N | N085-00-2/631 | Stairs: Spiral - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 16983 | ACTIVE | N | N085-00-2/641 | Gantry - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 16984 | ACTIVE | N | N085-00-2/641 | Gantry - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9537 | ACTIVE | N | N085-00-2/731 | CER - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18479 | ACTIVE | N | N085-00-2/731 | CER - Station Building - Kentish Town Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Grey Switch Boxes - Insulation within. Switch Boxes confirmed to contain Flash guards, Arc Chutes & Cementious Blocks - All containing Asbestos have been labelled | | 2 | | N | N |
| 16985 | ACTIVE | N | N085-00-2/731 | CER - Station Building - Kentish Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 19144 | ACTIVE | N | N085-00-2/731/FLR-01 80906641 | Floor - 1 - CER - Station Building - Kentish Town Stn Floor | Void | Asbestos | No Access: Presumed | | | | Beneath Wooden Raised Floor | | | | | YES |
| 9538 | ACTIVE | N | N085-00-2/733 | SER - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N085-00 - Station Building - Kentish Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18691 | ACTIVE | N | N085-00-2/733/FLR-01 | Floor - 1 - SER - Station Building - Kentish Town Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Wooden Floor | | | | | YES |
| 16986 | ACTIVE | N | N085-00-2/791 | Vent Shaft - Station Building - Kentish Town Stn | Cable: Wrap | Asbestos | Known | | | | Lagging (9m) at bottom of vent shaft | 9 | | | N | N |
| 16987 | ACTIVE | N | N085-00-2/792 | Vent Shaft - Station Building - Kentish Town Stn | Debris: Other | Asbestos | Surveyed – Not Detected | | | | Steel Rings; Debris on Rings - Non Asbestos | | | | | |
| 9539 | ACTIVE | N | N085-00-2/901 | Void - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16988 | ACTIVE | N | N085-00-2/901 | Void - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9540 | ACTIVE | N | N085-00-2/951 | Disused Room - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70002 | ACTIVE | N | N085-00-2/951 | Disused Room - Station Building - Kentish Town Stn | Other Boarding | Asbestos | Sampled – Not Detected | | | | Vermiculate to ceiling void - Non asbestos | | | R671001 | | |
| 16989 | ACTIVE | N | N085-00-2/951 | Disused Room - Station Building - Kentish Town Stn | Pipe Lagging | Asbestos | Surveyed – Not Detected | | | | | | | | | |
| 9541 | ACTIVE | N | N085-00-2/952 | Store - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16990 | ACTIVE | N | N085-00-2/952 | Store - Station Building - Kentish Town Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cable | | 1 | | N | N |
| 9542 | ACTIVE | N | N085-00-2/953 | Disused Room - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 43264 | ACTIVE | N | N085-00-2/953 | Disused Room - Station Building - Kentish Town Stn | | Asbestos | Sampled – Not Detected | | | | Render on concrete has been sampled in several areas throughout this room. Walls and ceiling No asbestos detected. Please see survey report R554128 (27/09/2016) | | | R554128 | N | N |
| 18692 | ACTIVE | N | N085-00-2/953 | Disused Room - Station Building - Kentish Town Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 x Switch Box - Insulation within; 100 amps | | 1 | | | |
| 43236 | ACTIVE | N | N085-00-2/953 | Disused Room - Station Building - Kentish Town Stn | | Asbestos | Sampled – Not Detected | | | | Loose MMMF insulation to floor | | | R554126 | N | N |
| 43235 | ACTIVE | N | N085-00-2/953 | Disused Room - Station Building - Kentish Town Stn | | Asbestos | Sampled – Not Detected | | | | Plastic and metal pipework - some within MMMF insulation throughout | | | R554126 | N | N |
| 43234 | ACTIVE | N | N085-00-2/953 | Disused Room - Station Building - Kentish Town Stn | | Asbestos | Sampled – Not Detected | | | | Ceramic tiles partial on plaster on brickwork | | | R554126 | N | N |
| 43233 | ACTIVE | N | N085-00-2/953 | Disused Room - Station Building - Kentish Town Stn | Mastic | Asbestos | Sampled – Not Detected | | | | Plastic cables metal conduits and cable management system and firestop and mastic - new throughout | | | R554126 | N | N |



Hazardous Material Asset Register - Summary



N085-00 - Station Building - Kentish Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------|--|------------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 43232 | INACTIVE | N | N085-00-2/953 | Disused Room - Station Building - Kentish Town Stn | Isolator Switches | Asbestos | Presumed | | | | Materials within combination fuse switch 1no to wall by stairs | | | R554126 | N | N |
| 43231 | ACTIVE | N | N085-00-2/953 | Disused Room - Station Building - Kentish Town Stn | | Asbestos | Sampled – Not Detected | | | | Plaster on Brickwork to walls and ceiling | | | R554126 | | |
| 43230 | ACTIVE | N | N085-00-2/953 | Disused Room - Station Building - Kentish Town Stn | | Asbestos | Sampled – Not Detected | | | | Concrete Slab to floor and some ceiling | | | R554126 | | |
| 43267 | ACTIVE | N | N085-00-2/953 | Disused Room - Station Building - Kentish Town Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Disused Room 2/953 Pink Matt Walls 250 3.66% | | | R554127 | N | N |
| 43273 | ACTIVE | N | N085-00-2/953 | Disused Room - Station Building - Kentish Town Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Disused Room 2/953 - No Paint pavement area outside of the station | | | R554127 | N | N |
| 43272 | ACTIVE | N | N085-00-2/953 | Disused Room - Station Building - Kentish Town Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Disused Room 2/953 Black Gloss Metal framework of skylight 580 0.09% | | | R554127 | N | N |
| 43268 | ACTIVE | N | N085-00-2/953 | Disused Room - Station Building - Kentish Town Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Disused Room 2/953 Cream Matt Walls above and below stairs 190 4.08% | | | R554127 | N | N |
| 43269 | ACTIVE | N | N085-00-2/953 | Disused Room - Station Building - Kentish Town Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Disused Room 2/953 Black Gloss RSJ and metal pipework 410 2.68% | | | R554127 | N | N |
| 43271 | ACTIVE | N | N085-00-2/953 | Disused Room - Station Building - Kentish Town Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Disused Room 2/953 Green Matt Parts of walls 490 0.18% | | | R554127 | N | N |
| 9543 | ACTIVE | N | N085-00-2/954 | Disused Room - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 43237 | ACTIVE | N | N085-00-2/954 | Disused Room - Station Building - Kentish Town Stn | | Asbestos | Sampled – Not Detected | | | | Concrete slab to floor, ceiling and walls | | | R554126 | | |
| 43240 | ACTIVE | N | N085-00-2/954 | Disused Room - Station Building - Kentish Town Stn | | Asbestos | Sampled – Not Detected | | | | Plastic cables and metal conduits and firestop and mastic - new throughout | | | R554126 | N | N |
| 43244 | ACTIVE | N | N085-00-2/954 | Disused Room - Station Building - Kentish Town Stn | | Asbestos | Room: Surveyed – No Known Asbestos | | | | A/C metal ductwork - new throughout | | | R554126 | N | N |
| 18915 | ACTIVE | N | N085-00-2/954 | Disused Room - Station Building - Kentish Town Stn | Pipe Lagging | Asbestos | Surveyed – Not Detected | | | | Pipe Cladding & Debris | | | | | |
| 43265 | ACTIVE | N | N085-00-2/954 | Disused Room - Station Building - Kentish Town Stn | | Asbestos | Sampled – Not Detected | | | | Render on concrete has been sampled in several areas throughout this room. Walls and ceiling No asbestos detected. Please see survey report R554128 (27/09/2016) | | | R554128 | N | N |
| 43238 | ACTIVE | N | N085-00-2/954 | Disused Room - Station Building - Kentish Town Stn | | Asbestos | Sampled – Not Detected | | | | Brickwork to walls and columns | | | R554126 | N | N |
| 43239 | ACTIVE | N | N085-00-2/954 | Disused Room - Station Building - Kentish Town Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Materials within SPBC electrical box 1 x to wall 1 presumed to contain asbestos | | 1 | R554126 | N | N |
| 43276 | ACTIVE | N | N085-00-2/954 | Disused Room - Station Building - Kentish Town Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Disused Room 2/954 Grey Gloss Metal framework of skylight 740 12.9% | | | R554127 | N | N |



Hazardous Material Asset Register - Summary



N085-00 - Station Building - Kentish Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|----------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 43275 | ACTIVE | N | N085-00-2/954 | Disused Room - Station Building - Kentish Town Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Disused Room 2/954 Black Gloss RSJ and metal pipework 230 20.7% | | | R554127 | N | N |
| 43274 | ACTIVE | N | N085-00-2/954 | Disused Room - Station Building - Kentish Town Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Disused Room 2/954 Grey Matt Down pipe 310 27.5% | | | R554127 | N | N |
| 9544 | ACTIVE | N | N085-00-3/081 | Circulation Area - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16991 | ACTIVE | N | N085-00-3/081 | Circulation Area - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9545 | ACTIVE | N | N085-00-3/121 | Platform Invert - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19145 | ACTIVE | N | N085-00-3/121 | Platform Invert - Station Building - Kentish Town Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed | | | | | |
| 9546 | ACTIVE | N | N085-00-3/161 | LMC - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16992 | ACTIVE | N | N085-00-3/161 | LMC - Station Building - Kentish Town Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | within Tunnel Rings | | | | | |
| 9547 | ACTIVE | N | N085-00-3/162 | LMC - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9548 | ACTIVE | N | N085-00-3/201 | Passage - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16993 | ACTIVE | N | N085-00-3/201 | Passage - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9549 | ACTIVE | N | N085-00-3/261 | Platform 1 - Northbound Fast - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 71009 | ACTIVE | N | N085-00-3/261 | Platform 1 - Northbound Fast - Station Building - Kentish Town Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - total >10 no - To J hangers throughout arrivals end | | 10 | R731056 | | |
| 71008 | ACTIVE | N | N085-00-3/261 | Platform 1 - Northbound Fast - Station Building - Kentish Town Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 4 no - To ceiling arrivals end | | 4 | R731056 | N | Y |
| 71007 | ACTIVE | N | N085-00-3/261 | Platform 1 - Northbound Fast - Station Building - Kentish Town Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R731056 | | |
| 71006 | ACTIVE | N | N085-00-3/261 | Platform 1 - Northbound Fast - Station Building - Kentish Town Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R731056 | | |



Hazardous Material Asset Register - Summary



N085-00 - Station Building - Kentish Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 44936 | ACTIVE | N | N085-00-3/261 | Platform 1 - Northbound Fast - Station Building - Kentish Town Stn | | Asbestos | Removed | | | | Leaking Hydrant, 2nd & bottom gasket, tap gland - Removed by Econ under request ES2578a/b/c | | | | N | N |
| 42534 | ACTIVE | N | N085-00-3/261 | Platform 1 - Northbound Fast - Station Building - Kentish Town Stn | Cable: Sheath | Asbestos | Removed | | | | Cable wrap (10m) - Removed by Econ under request ES2578b | 10 | | R287952 | N | N |
| 18693 | ACTIVE | N | N085-00-3/261 | Platform 1 - Northbound Fast - Station Building - Kentish Town Stn | Gasket :Pipework | Asbestos | Removed | | | | Gaskets to Joints on Hydrant Pipework - Removed by Econ under request ES2578a/b/c | | | | N | N |
| 44937 | ACTIVE | N | N085-00-3/261 | Platform 1 - Northbound Fast - Station Building - Kentish Town Stn | | Asbestos | Known | | | | Platform 1 Invert - Cables by hydrant | | | | N | N |
| 16994 | ACTIVE | N | N085-00-3/261/CLG-01 | Ceiling: Solid - 1 - Platform 1 - Station Building - Kentish Town Stn | Cable: Sheath | Asbestos | Presumed | | | | 2 x Braided Cables | | 2 | | N | N |
| 16996 | ACTIVE | N | N085-00-3/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Kentish Town Stn | Cable Duct: Other | Asbestos | Presumed | | | | Platform 1 Invert - Cable Ducts - Presumed Chrysotile | | | | N | YES |
| 16995 | ACTIVE | N | N085-00-3/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Kentish Town Stn | Cable: Sheath | Asbestos | Known | | | | Platform 1 Invert - Various Cables / Woven insulated cables throughout length of invert. | | | | N | YES |
| 16997 | INACTIVE | N | N085-00-3/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Kentish Town Stn | Cable: Wrap | Asbestos | Known | | | | Platform 1 Invert - known Chrysotile - woven insulated cables throughout length of platform 1 invert | | | | | YES |
| 9550 | ACTIVE | N | N085-00-3/411 | Disused Room - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20080 | ACTIVE | N | N085-00-3/411/CLG-01 | Ceiling: Suspended - 1 - Disused Room - Station Building - Kentish Town Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | YES | |
| 9551 | ACTIVE | N | N085-00-3/576 | Ladder - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18694 | ACTIVE | N | N085-00-3/576 | Ladder - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9552 | ACTIVE | N | N085-00-3/601 | Stairs: Linear - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16998 | ACTIVE | N | N085-00-3/601 | Stairs: Linear - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9553 | ACTIVE | N | N085-00-3/602 | Stairs: Linear - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16999 | ACTIVE | N | N085-00-3/602 | Stairs: Linear - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N085-00 - Station Building - Kentish Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|--------------------------------|---|------------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9554 | ACTIVE | N | N085-00-3/603 | Stairs: Linear - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17000 | ACTIVE | N | N085-00-3/603 | Stairs: Linear - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9555 | ACTIVE | N | N085-00-3/604 | Disused Room - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18695 | ACTIVE | N | N085-00-3/604/FLR-01 | Floor - 1 - Stairs - Station Building - Kentish Town Stn | Cable Duct: Other | Asbestos | Known | | | | Cable Sleeves - Chrysotile | | 3 | | N | N |
| 9556 | ACTIVE | N | N085-00-3/661 | Relay Room - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17002 | ACTIVE | N | N085-00-3/661/WAL-001 80906802 | Wall: Internal - 1 - Relay Room - Station Building - Kentish Town Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | Wall 1 - Main Switch Boxes - Possible Asbestos Materials within | | 2 | | | |
| 43226 | ACTIVE | N | N085-00-3/661/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Kentish Town Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Wall 2 - 5 Switch boxes strongly presumed to contain asbestos insulating materials within - 2 x 60amps, 2 x 100amps, 1 x 200amps. | | 5 | | N | N |
| 43227 | ACTIVE | N | N085-00-3/661/WAL-003 80906804 | Wall: Internal - 3 - Relay Room - Station Building - Kentish Town Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | Wall 3 - Switch boxes strongly presumed to contain asbestos materials within - 4 x 60amps 1 x 100amps 1 x 200amps. Additional 2 x Green UNION electrical boxes. | | 8 | | N | N |
| 17001 | ACTIVE | N | N085-00-3/661/WAL-004 | Wall: Internal - 4 - Relay Room - Station Building - Kentish Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels | | | | | |
| 9557 | ACTIVE | N | N085-00-3/711 | Relay Room - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 53660 | ACTIVE | N | N085-00-3/711 | Relay Room - Station Building - Kentish Town Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Green box with presumed composite boarding inside | | 1 | | | |
| 17004 | ACTIVE | N | N085-00-3/711 | Relay Room - Station Building - Kentish Town Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Electrical Box on Wall presumed to contain asbestos insulating materials within | | 1 | | N | N |
| 42046 | INACTIVE | N | N085-00-3/711 | Relay Room - Station Building - Kentish Town Stn | PCBs | Polychlorinated biphenyl | Removed | | | | 7 x PCB's - Fair Condition Re Moved by Edenbeck Feb 2017 Under ES7773a | | 7 | | N | N |
| 53616 | ACTIVE | N | N085-00-3/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Kentish Town Stn | Cable Duct: Other | Asbestos | Presumed | | | | ducts to floor inside cabinet | | | | | |
| 9558 | ACTIVE | N | N085-00-3/732 | CER - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18696 | ACTIVE | N | N085-00-3/732 | CER - Station Building - Kentish Town Stn | Isolator Switches | Asbestos | Removed | | | | Switch Boxes strongly presumed to contain asbestos insulating materials within were not present in 2020 re-inspection. | | 2 | | N | N |



Hazardous Material Asset Register - Summary



N085-00 - Station Building - Kentish Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9559 | ACTIVE | N | N085-00-3/761 | Relay Room - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18697 | ACTIVE | N | N085-00-3/761 | Relay Room - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 17005 | ACTIVE | N | N085-00-3/791 | Vent Shaft - Station Building - Kentish Town Stn | Cable: Wrap | Asbestos | Surveyed – Not Detected | | | | LHS to Door | | | | | |
| 17006 | ACTIVE | N | N085-00-3/791 | Vent Shaft - Station Building - Kentish Town Stn | Cable: Wrap | Asbestos | Known | | | | Lagging (7m) at bottom of vent shaft | 7 | | | N | N |
| 9560 | ACTIVE | N | N085-00-3/951 | Disused Room - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17007 | ACTIVE | N | N085-00-3/951 | Disused Room - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9561 | ACTIVE | N | N085-00-3/952 | Void - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18698 | ACTIVE | N | N085-00-3/952 | Void - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 17008 | ACTIVE | N | N085-00-3/971 | Vent Shaft - Station Building - Kentish Town Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | within Tunnel Rings | | | | | |
| 9562 | ACTIVE | N | N085-00-3/981 | Stairs: Linear - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17009 | ACTIVE | N | N085-00-3/981 | Stairs: Linear - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9563 | ACTIVE | N | N085-00-4/201 | Passage - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17010 | ACTIVE | N | N085-00-4/201 | Passage - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9564 | ACTIVE | N | N085-00-4/202 | Passage - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18699 | ACTIVE | N | N085-00-4/202 | Passage - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9565 | ACTIVE | N | N085-00-4/262 | Platform 2 - Southbound Fast - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17011 | INACTIVE | N | N085-00-4/262 | Platform 2 - Southbound Fast - Station Building - Kentish Town Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 1 x 20mm, 1 x 50mm & 1 x 10mm Cables going into Track | | | | N | N |



Hazardous Material Asset Register - Summary



N085-00 - Station Building - Kentish Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|--------------------------------|--|------------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 17012 | ACTIVE | N | N085-00-4/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Kentish Town Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 2 Invert - Various Cables | | | | N | YES |
| 9566 | ACTIVE | N | N085-00-4/381 | Store - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18700 | ACTIVE | N | N085-00-4/381 | Store - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9567 | ACTIVE | N | N085-00-4/382 | Store - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17013 | ACTIVE | N | N085-00-4/382 | Store - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9568 | ACTIVE | N | N085-00-4/661 | Switch Room - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17014 | ACTIVE | N | N085-00-4/661 | Switch Room - Station Building - Kentish Town Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables going to Track and 1 x going to Invert - 2 x Green 1 x White | | 3 | | N | N |
| 42047 | INACTIVE | N | N085-00-4/661 | Switch Room - Station Building - Kentish Town Stn | PCBs | Polychlorinated biphenyl | Removed | | | | 8 x PCB's - 6 x Fair Condition, 2 x possibly leaking - currently being investigated by HMU Re Moved by Edenbeck Feb 2017 Under ES7773a | | 8 | | N | N |
| 17003 | ACTIVE | N | N085-00-4/661/WAL-001 80906827 | Wall: Internal - 1 - Switch Room - Station Building - Kentish Town Stn Wall: Internal | Cable: Sheath | Asbestos | Strongly Presumed | | | | 2x Green 50mm Cables | | 2 | | N | N |
| 53614 | ACTIVE | N | N085-00-4/661/WAL-001 80906827 | Wall: Internal - 1 - Switch Room - Station Building - Kentish Town Stn Wall: Internal | Other Boarding | Asbestos | Presumed | | | | Board to 600v box | | 1 | | | |
| 9569 | ACTIVE | N | N085-00-4/662 | Switch Room - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18701 | ACTIVE | N | N085-00-4/662 | Switch Room - Station Building - Kentish Town Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Blue Switch Boxes - Asbestos insulation presumed within 3 x 60 amps, 1 x 100 amps | | 4 | | N | N |
| 18916 | ACTIVE | N | N085-00-4/662 | Switch Room - Station Building - Kentish Town Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Transformer Box(es) presumed asbestos insulation within | | 1 | | N | N |
| 17015 | ACTIVE | N | N085-00-4/662/WAL-004 | Wall: Internal - 4 - Switch Room - Station Building - Kentish Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux boarding above Entrance | | | | | |
| 9570 | ACTIVE | N | N085-00-4/663 | Switch Room - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17016 | ACTIVE | N | N085-00-4/663 | Switch Room - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N085-00 - Station Building - Kentish Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|--------------------------------|---|------------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9571 | ACTIVE | N | N085-00-4/711 | Relay Room - Station Building - Kentish Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19362 | ACTIVE | N | N085-00-4/711 | Relay Room - Station Building - Kentish Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 17019 | INACTIVE | N | N085-00-4/711 | Relay Room - Station Building - Kentish Town Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 10 mm Cables going into Invert | | 1 | | | |
| 17017 | ACTIVE | N | N085-00-4/711 | Relay Room - Station Building - Kentish Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Wall & Ceiling Tiles Supalux | | | | | |
| 18702 | ACTIVE | N | N085-00-4/711/CLG-01 | Ceiling: Solid - 1 - Relay Room - Station Building - Kentish Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 17018 | INACTIVE | N | N085-00-4/711/CLG-01 | Ceiling: Solid - 1 - Relay Room - Station Building - Kentish Town Stn | Vinyl tiles | Asbestos | Presumed | | | | Wall & Ceiling Tiles (Duplicate) with 17017 | | | | | |
| 17021 | ACTIVE | N | N085-00-4/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Kentish Town Stn | Other Boarding | Asbestos | Strongly Presumed | | | | 1 x Paxoline Board (high to wall 1) | | 1 | | N | N |
| 17067 | ACTIVE | N | N085-00-4/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Kentish Town Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 2x 50 mm green Cables going into Invert | | 2 | | N | N |
| 19147 | ACTIVE | N | N085-00-4/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Kentish Town Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | 1 x Westinghouse Box strongly presumed to asbestos insulating materials within. | | 1 | | N | N |
| 53612 | ACTIVE | N | N085-00-4/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Kentish Town Stn | Other Boarding | Asbestos | Presumed | | | | 2 x circuit boxes to wall 2 - black composite panels | | 2 | | | |
| 53611 | ACTIVE | N | N085-00-4/711/WAL-002 80906931 | Wall: Internal - 2 - Relay Room - Station Building - Kentish Town Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | Large free standing electrical equipment - presumed asbestos materials within | | 1 | | | |
| 53613 | ACTIVE | N | N085-00-4/711/WAL-003 80906932 | Wall: Internal - 3 - Relay Room - Station Building - Kentish Town Stn Wall: Internal | Other Boarding | Asbestos | Presumed | | | | Brown composite panel to front of rectifier | | 1 | | | |
| 17020 | ACTIVE | N | N085-00-4/711/WAL-004 | Wall: Internal - 4 - Relay Room - Station Building - Kentish Town Stn | Lead/Leading | Lead Paint/Lead | Strongly Presumed | | | | Electrical Box Presumed to be Lead Paint | | | | N | N |
| 19146 | ACTIVE | N | N085-00-4/971 | Vent Shaft - Station Building - Kentish Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 9572 | ACTIVE | N | N091-00-1/001 | Booking Hall - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42909 | ACTIVE | N | N091-00-1/001 | Booking Hall - Station Building - Camden Town Stn | Boarding: AIB | Asbestos | Presumed | | | | Boarding and associated debris above false ceiling. Asbestos assumed in this location due to its' KNOWN presence confirmed at N091-00-1/071. | | | | Y | N |
| 16594 | ACTIVE | N | N091-00-1/001/CLG-01 | Ceiling: Solid - 1 - Booking Hall - Station Building - Camden Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above Ceiling - Gates - Brick, Concrete | | | | YES | |
| 9573 | ACTIVE | N | N091-00-1/011 | Ticket Office - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16595 | ACTIVE | N | N091-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Camden Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Rendered Plaster, Breeze Block above Supalux Tiles | | | | YES | |
| 18280 | ACTIVE | N | N091-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9574 | ACTIVE | N | N091-00-1/021 | POM - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16597 | ACTIVE | N | N091-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels | | | | | |
| 16598 | ACTIVE | N | N091-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Camden Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Rendered Plaster above false ceiling | | | | YES | |
| 18281 | INACTIVE | N | N091-00-1/021/FLR-01 | Floor - 1 - POM - Station Building - Camden Town Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Rubber Flooring | | | | | YES |
| 16596 | ACTIVE | N | N091-00-1/021/FLR-01 | Floor - 1 - POM - Station Building - Camden Town Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |
| 9575 | ACTIVE | N | N091-00-1/031 | Mess Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16599 | ACTIVE | N | N091-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels | | | | | |
| 18833 | ACTIVE | N | N091-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Camden Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above Supalux Panels - ref report R679623 - NAD throughout false ceiling | | | | YES | |
| 9576 | ACTIVE | N | N091-00-1/036 | Toilet: Unisex - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 44788 | ACTIVE | N | N091-00-1/036 | Toilet: Unisex - Station Building - Camden Town Stn | | Lead Paint/Lead | Sampled – Not Detected | | | | Cream matt paint on walls - Analysis Results <0.01% Not lead hazard White powder coated paint on false ceiling - N/A Not lead hazard | | | | | |
| 16600 | ACTIVE | N | N091-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels | | | | | |
| 18403 | ACTIVE | N | N091-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Camden Town Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Panels | | | | YES | |
| 9577 | ACTIVE | N | N091-00-1/071 | Circulation Area - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16601 | ACTIVE | N | N091-00-1/071 | Circulation Area - Station Building - Camden Town Stn | Boarding: AIB | Asbestos | Known | | | | Boarding and associated debris above false ceiling. Tiles directly above landing area of Escalators 1 & 2 found to contains amosite asbestos. Linked to 42908. | | | | YES | N |
| 19046 | ACTIVE | N | N091-00-1/071 | Circulation Area - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Middle boards - Supalux; Outer boards - Plaster; | | | | | |
| 42908 | ACTIVE | N | N091-00-1/071/CLG-04 | Ceiling: Suspended - 4 - Circulation Area - Station Building - Camden Town Stn | Boarding: AIB | Asbestos | Known | | | | Boarding and associated debris above false ceiling. Tiles directly above landing area of Escalators 1 & 2 found to contains amosite asbestos. Linked to HMI 16601. | | | R181476 | Y | N |
| 9578 | ACTIVE | N | N091-00-1/236 | Lobby - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16603 | ACTIVE | N | N091-00-1/236/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Camden Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Rendered Plaster, Concrete, Brick above false ceiling | | | | YES | |
| 18282 | ACTIVE | N | N091-00-1/236/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels | | | | | |
| 16602 | ACTIVE | N | N091-00-1/236/FLR-01 | Floor - 1 - Lobby - Station Building - Camden Town Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |
| 9579 | ACTIVE | N | N091-00-1/311 | Office - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16605 | ACTIVE | N | N091-00-1/311/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels | | | | | |
| 16606 | ACTIVE | N | N091-00-1/311/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Camden Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Rendered Plaster, Breeze Blocks above Supalux Panels | | | | YES | |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 16604 | ACTIVE | N | N091-00-1/311/FLR-01 | Floor - 1 - Office - Station Building - Camden Town Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring; Rubber Floor Covering | | | | | YES |
| 9580 | ACTIVE | N | N091-00-1/331 | Mess Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16607 | ACTIVE | N | N091-00-1/331 | Mess Room - Station Building - Camden Town Stn | Bitumen | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 44787 | ACTIVE | N | N091-00-1/331 | Mess Room - Station Building - Camden Town Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Cream matt paint on Walls & ceiling - Analysis Results <0.01% & 0.13% Not lead hazard / White power coated paint on false ceiling - N/A Not lead hazard | | | | | |
| 16928 | ACTIVE | N | N091-00-1/331/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles; Inside Fascia around Canopy - Solid | | | | | |
| 16929 | ACTIVE | N | N091-00-1/331/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Camden Town Stn | Glazing Rope | Asbestos | Strongly Presumed | | | | Glass Skylight - Rope Seal | | | | N | N |
| 18612 | ACTIVE | N | N091-00-1/331/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Camden Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs above False Ceiling | | | R679623 | YES | |
| 18283 | ACTIVE | N | N091-00-1/331/FLR-01 | Floor - 1 - Mess Room - Station Building - Camden Town Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Linoleum, Rubber | | | | | YES |
| 9581 | ACTIVE | N | N091-00-1/401 | Bin Store - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16930 | ACTIVE | N | N091-00-1/401 | Bin Store - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9582 | ACTIVE | N | N091-00-1/406 | SVC - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16932 | ACTIVE | N | N091-00-1/406 | SVC - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels | | | | | |
| 16933 | ACTIVE | N | N091-00-1/406/CLG-01 | Ceiling: Solid - 1 - SVC - Station Building - Camden Town Stn | No Access | Asbestos | No Access: Presumed | | | | Above false ceiling | | | | YES | |
| 16931 | ACTIVE | N | N091-00-1/406/FLR-01 | Floor - 1 - SVC - Station Building - Camden Town Stn | Debris: Cement | Asbestos | Surveyed – Not Detected | | | | Cement Debris - Non Asbestos | | | | | |
| 9583 | ACTIVE | N | N091-00-1/411 | SVC - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18613 | ACTIVE | N | N091-00-1/411 | SVC - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|------------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9584 | ACTIVE | N | N091-00-1/412 | SCR - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16935 | ACTIVE | N | N091-00-1/412 | SCR - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding Surround; Inside 4no Metal Doors Supalux Boarding | | | | | |
| 16936 | ACTIVE | N | N091-00-1/412/CLG-01 | Ceiling: Solid - 1 - SCR - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Frame & Surround | | | | | |
| 19139 | ACTIVE | N | N091-00-1/412/CLG-01 | Ceiling: Solid - 1 - SCR - Station Building - Camden Town Stn | Void | Asbestos | No Access: Presumed | | | | Above False Ceiling | | | | YES | |
| 16934 | ACTIVE | N | N091-00-1/412/FLR-01 | Floor - 1 - SCR - Station Building - Camden Town Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Linoleum, Rubber | | | | | YES |
| 9585 | ACTIVE | N | N091-00-1/551 | Yard - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18614 | ACTIVE | N | N091-00-1/551 | Yard - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9586 | ACTIVE | N | N091-00-1/631 | Stairs: Spiral - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16937 | ACTIVE | N | N091-00-1/631/CLG-01 | Ceiling: Solid - 1 - Spiral Stairs - Station Building - Camden Town Stn | Void | Asbestos | No Access: Presumed | | | | Above False Ceiling | | | | YES | |
| 9587 | ACTIVE | N | N091-00-1/661 | Switch Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16938 | ACTIVE | N | N091-00-1/661/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Camden Town Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 5no Grey Switch Boxes - Insulation within | | 5 | | N | N |
| 9588 | ACTIVE | N | N091-00-1/662 | Switch Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18913 | ACTIVE | N | N091-00-1/662 | Switch Room - Station Building - Camden Town Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Cream Emulsion Paint - Ceiling and Walls. Thickness .20mm; Est Quantity 30sqm; Analysis 1.8% - Poor Condition | | | | N | N |
| 18615 | ACTIVE | N | N091-00-1/662/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Camden Town Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 x 30 amp Switch Box | | 1 | | N | N |
| 16940 | ACTIVE | N | N091-00-1/662/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Camden Town Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 3no Transformer Boxes | | 3 | | N | N |
| 16939 | ACTIVE | N | N091-00-1/662/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Camden Town Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 2 x 60amp, 2 x 100amp Switch Boxes - Insulation within | | 4 | | N | N |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|------------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 16941 | ACTIVE | N | N091-00-1/662/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Camden Town Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Blue Oil Based Paint Switch Boxes and Busbar Thickness .09mm; Est Quantity 2sqm; Analysis 1.2% | | | | N | N |
| 18417 | ACTIVE | N | N091-00-1/662/WAL-004 | Wall: Internal - 4 - Switch Room - Station Building - Camden Town Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 4 x 60amp Switch Boxes - Insulation within | | 4 | | N | N |
| 9589 | ACTIVE | N | N091-00-1/746 | Station Control Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18616 | ACTIVE | N | N091-00-1/746/CLG-01 | Ceiling: Suspended - 1 - Station Control Room - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 20079 | ACTIVE | N | N091-00-1/746/CLG-01 | Ceiling: Suspended - 1 - Station Control Room - Station Building - Camden Town Stn | Glazing Rope | Asbestos | Strongly Presumed | | | | Above Ceiling: Glass Canopy - Rope Seal | | | | Y | N |
| 16943 | ACTIVE | N | N091-00-1/746/CLG-01 | Ceiling: Suspended - 1 - Station Control Room - Station Building - Camden Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal Ducting, Fibreglass Lagging, Metal Pipes, Rendered Plaster above False Ceiling | | | | YES | |
| 16942 | ACTIVE | N | N091-00-1/746/FLR-01 | Floor - 1 - Station Control Room - Station Building - Camden Town Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Linoleum, Rubber | | | | | YES |
| 9590 | ACTIVE | N | N091-00-2/151 | UMC - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44151 | ACTIVE | N | N091-00-2/151 | UMC - Station Building - Camden Town Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer box | | 1 | | N | N |
| 16945 | ACTIVE | N | N091-00-2/151 | UMC - Station Building - Camden Town Stn | Pipe Lagging | Asbestos | Surveyed – Not Detected | | | | String around Pipe | | | | | |
| 16947 | ACTIVE | N | N091-00-2/151 | UMC - Station Building - Camden Town Stn | Cable Duct: Other | Asbestos | Sampled – Not Detected | | | | Cable sleeve in vault next to switch boxes - NADIS | | | | | |
| 16946 | ACTIVE | N | N091-00-2/151 | UMC - Station Building - Camden Town Stn | Isolator Switches | Asbestos | Removed | | | | 4 x Blue, 1no Grey, 1no Red Switch Boxes - Insulation within | | 6 | | | |
| 16944 | ACTIVE | N | N091-00-2/151 | UMC - Station Building - Camden Town Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Flammable Store (Durasteel) - Non Asbestos | | | | | |
| 9591 | ACTIVE | N | N091-00-2/210 | Lobby - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18617 | ACTIVE | N | N091-00-2/210/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Camden Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Vermiculite Pipe Lagging; Fibreglass Pipe Lagging above ceiling | | | | YES | |
| 9592 | ACTIVE | N | N091-00-2/236 | Lobby - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 16950 | ACTIVE | N | N091-00-2/236/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Camden Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plaster above False Ceiling | | | | YES | |
| 16949 | ACTIVE | N | N091-00-2/236/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9593 | ACTIVE | N | N091-00-2/237 | Lobby - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16781 | ACTIVE | N | N091-00-2/237/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Camden Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plaster above False Ceiling | | | | YES | |
| 16782 | ACTIVE | N | N091-00-2/237/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 16783 | ACTIVE | N | N091-00-2/237/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Camden Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plaster above False Ceiling | | | | YES | |
| 18450 | ACTIVE | N | N091-00-2/237/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9594 | ACTIVE | N | N091-00-2/238 | Lobby - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 46450 | ACTIVE | N | N091-00-2/238 | Lobby - Station Building - Camden Town Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | White matt paint to walls - Thickness: 0.28mm Analysis: <0.02% | | | R686776 | N | N |
| 9595 | ACTIVE | N | N091-00-2/239 | Lobby - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16784 | ACTIVE | N | N091-00-2/239 | Lobby - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 9596 | ACTIVE | N | N091-00-2/241 | Lobby - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16785 | ACTIVE | N | N091-00-2/241 | Lobby - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9597 | ACTIVE | N | N091-00-2/316 | Locker Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18451 | ACTIVE | N | N091-00-2/316 | Locker Room - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 46448 | ACTIVE | N | N091-00-2/316 | Locker Room - Station Building - Camden Town Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | White matt paint to walls - Thickness: 0.48mm Analysis: <0.02% | | | R686776 | N | N |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9598 | ACTIVE | N | N091-00-2/371 | CER - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18410 | ACTIVE | N | N091-00-2/371 | CER - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding; Vermiculite Pipe Lagging | | | | | |
| 19125 | ACTIVE | N | N091-00-2/371/FLR-01 | Floor - 1 - CER - Station Building - Camden Town Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |
| 16786 | INACTIVE | N | N091-00-2/371/FLR-02 | Floor - 2 - CER - Station Building - Camden Town Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |
| 9599 | ACTIVE | N | N091-00-2/406 | Shower Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16787 | ACTIVE | N | N091-00-2/406/CLG-01 | Ceiling: Suspended - 1 - Shower Room - Station Building - Camden Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Grid | | | | YES | |
| 9600 | ACTIVE | N | N091-00-2/407 | Lobby - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18452 | ACTIVE | N | N091-00-2/407/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Camden Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Grid | | | | YES | |
| 9601 | ACTIVE | N | N091-00-2/412 | Disused Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9602 | ACTIVE | N | N091-00-2/416 | Toilet: Female - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16788 | ACTIVE | N | N091-00-2/416 | Toilet: Female - Station Building - Camden Town Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | LU Heater Foam Insulation Board | | | | | |
| 9603 | ACTIVE | N | N091-00-2/417 | Disused Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19358 | ACTIVE | N | N091-00-2/417/CLG-01 | Ceiling: Solid - 1 - Disused Room - Station Building - Camden Town Stn | Void | Asbestos | No Access: Presumed | | | | No Access within Asbestos Boarding | | | | YES | |
| 42071 | ACTIVE | N | N091-00-2/417/CLG-01 80897361 | Ceiling: Solid - 1 - Disused Room - Station Building - Camden Town Stn Ceiling: Solid | Mastic | Asbestos | Presumed | | | | Mastic to joints within ventilation ducting | | | | | N |
| 16789 | ACTIVE | N | N091-00-2/417/CLG-01 | Ceiling: Solid - 1 - Disused Room - Station Building - Camden Town Stn | Boarding: AIB | Asbestos | Known | | | | Asbestos Boarding - Chrysotile & Amphibole | | | | | N |
| 9604 | ACTIVE | N | N091-00-2/418 | Toilet: Male - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|--------------------------------|---|---------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 70316 | ACTIVE | N | N091-00-2/418 | Toilet: Male - Station Building - Camden Town Stn | LUL Heaters | Asbestos | Presumed | | | | LU Heater - Asbestos Panel Within - Presumed NB Not previously noted on asbestos survey | | 1 | | | |
| 70314 | INACTIVE | N | N091-00-2/418 | Toilet: Male - Station Building - Camden Town Stn | LUL Heaters | Asbestos | Presumed | | | | LU Heater - Asbestos Panel within - Presumed NB - Not previously noted on asbestos survey | | 1 | | | |
| 46451 | ACTIVE | N | N091-00-2/418 | Toilet: Male - Station Building - Camden Town Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | White matt paint to walls - Thickness: 0.48mm Analysis: <0.02% | | | R686776 | N | N |
| 16790 | ACTIVE | N | N091-00-2/418/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Camden Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Grid | | | | YES | |
| 9605 | ACTIVE | N | N091-00-2/571 | Store - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18453 | ACTIVE | N | N091-00-2/571 | Store - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding and Boxing | | | | | |
| 9606 | ACTIVE | N | N091-00-2/664 | Switch Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16791 | ACTIVE | N | N091-00-2/664 | Switch Room - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9607 | ACTIVE | N | N091-00-2/731 | CER - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18904 | ACTIVE | N | N091-00-2/731 | CER - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding above Door | | | | | |
| 19126 | ACTIVE | N | N091-00-2/731/CLG-01 | Ceiling: Solid - 1 - CER - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Plaster; Supalux Boxing | | | | | |
| 16792 | ACTIVE | N | N091-00-2/731/FLR-01 | Floor - 1 - CER - Station Building - Camden Town Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |
| 16793 | ACTIVE | N | N091-00-2/731/WAL-001 80897396 | Wall: Internal - 1 - CER - Station Building - Camden Town Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 2 x 60amp Grey Fuse Switches | | 2 | | N | N |
| 9608 | ACTIVE | N | N091-00-2/732 | Switch Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44309 | ACTIVE | N | N091-00-2/732 | Switch Room - Station Building - Camden Town Stn | Cable Ducts: Cement | Asbestos | Presumed | | | | Ductwork 8no to floor by wall 3 | | | | | |
| 16794 | ACTIVE | N | N091-00-2/732/CLG-01 | Ceiling: Solid - 1 - MDF - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|--------------------------------|---|-------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18454 | ACTIVE | N | N091-00-2/732/FLR-01 | Floor - 1 - Switch Room - Station Building - Camden Town Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |
| 43786 | ACTIVE | N | N091-00-2/732/WAL-003 80897411 | Wall: Internal - 3 - MDF - Station Building - Camden Town Stn Wall: Internal | Cable Duct: Other | Asbestos | Known | | | | Ductwork, 8no, to floor by wall 3 in CER | | 8 | R589530 | N | N |
| 9609 | ACTIVE | N | N091-00-2/761 | Equipment Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16795 | ACTIVE | N | N091-00-2/761 | Equipment Room - Station Building - Camden Town Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 46449 | ACTIVE | N | N091-00-2/761 | Equipment Room - Station Building - Camden Town Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | White matt paint to walls - Thickness: 0.27mm Analysis: <0.02% | | | R686776 | N | N |
| 9610 | ACTIVE | N | N091-00-2/771 | Pump Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9611 | ACTIVE | N | N091-00-2/776 | Fan Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16797 | ACTIVE | N | N091-00-2/776/WAL-004 | Wall: Internal - 4 - Fan Room - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding - also above Door to 2/151 | | | | | |
| 16796 | ACTIVE | N | N091-00-2/776/WAL-006 | Wall: Internal - 6 - Fan Room - Station Building - Camden Town Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 x 30amp Switch Box - Insulation within | | 1 | | N | N |
| 9612 | ACTIVE | N | N091-00-2/993 | Disused Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18455 | ACTIVE | N | N091-00-2/993 | Disused Room - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 16798 | ACTIVE | N | N091-00-2/993 | Disused Room - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux White Boarding - Storage | | | | | |
| 16799 | ACTIVE | N | N091-00-2/993 | Disused Room - Station Building - Camden Town Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Green/ Yellow Oil Based Paint - Girder. Thickness .27mm; Est Quantity 4lm; Analysis 3.9% (LEAD PAINT LIKELY TO HAVE BEEN PAINTED OVER WITH BLACK PAINT) | | | | N | N |
| 9613 | ACTIVE | N | N091-00-2/994 | Disused Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16800 | ACTIVE | N | N091-00-2/994 | Disused Room - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|----------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 16801 | INACTIVE | N | N091-00-2/994 | Disused Room - Station Building - Camden Town Stn | Lead/Leading | Lead Paint/Lead | Removed | | | | Cream Oil Based Paint - Girder. Thickness .35mm; Est Quantity 21m; Analysis 4.2% Removed as part of SMEP (PH) | | | | | |
| 18456 | ACTIVE | N | N091-00-2/994/CLG-01 | Ceiling: Solid - 1 - Disused Room - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding low level | | | | | |
| 9614 | ACTIVE | N | N091-00-2/995 | Equipment Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19127 | ACTIVE | N | N091-00-2/995 | Equipment Room - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding | | | | | |
| 9615 | ACTIVE | N | N091-00-3/081 | Circulation Area - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16802 | ACTIVE | N | N091-00-3/081 | Circulation Area - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9616 | ACTIVE | N | N091-00-3/121 | Platform Invert - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18464 | ACTIVE | N | N091-00-3/121/WAL-002 | Wall: Internal - 2 - Platform Invert - Station Building - Camden Town Stn | Cable: Sheath | Asbestos | Known | | | | Braided Cable | | | | | |
| 25665 | ACTIVE | N | N091-00-3/121/WAL-003 | Wall: Internal - 3 - Platform Invert - Station Building - Camden Town Stn | Other Boarding | Asbestos | Strongly Presumed | | | | Boarding | | 1 | | | |
| 9617 | ACTIVE | N | N091-00-3/161 | LMC - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 46329 | ACTIVE | N | N091-00-3/161 | LMC - Station Building - Camden Town Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Bitumen Cable Ducts Wall 1 x 3no Wall 3 x 6no | | 9 | R679623 | | |
| 16803 | ACTIVE | N | N091-00-3/161 | LMC - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible (REF R679623) NAD to CMS | | | | | |
| 9618 | ACTIVE | N | N091-00-3/202 | Passage - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16804 | ACTIVE | N | N091-00-3/202 | Passage - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9619 | ACTIVE | N | N091-00-3/203 | Passage - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16805 | ACTIVE | N | N091-00-3/203 | Passage - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------|--|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9620 | ACTIVE | N | N091-00-3/204 | Passage - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16879 | ACTIVE | N | N091-00-3/204 | Passage - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9621 | ACTIVE | N | N091-00-3/205 | Passage - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16880 | ACTIVE | N | N091-00-3/205 | Passage - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9622 | ACTIVE | N | N091-00-3/261 | Platform 1 - Northbound Local - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 46328 | ACTIVE | N | N091-00-3/261 | Platform 1 - Northbound Local - Station Building - Camden Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Platform 1 - Cable Management System - Surveyed no asbestos detected - refer to report R679623 | | | R629623 | | |
| 16881 | ACTIVE | N | N091-00-3/261 | Platform 1 - Northbound Local - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels by Relay Room - Non Asbestos | | | | | |
| 70888 | ACTIVE | N | N091-00-3/261 | Platform 1 - Northbound Local - Station Building - Camden Town Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - total >20no - To J Hanger throughout | | 20 | R731051 | | |
| 70887 | ACTIVE | N | N091-00-3/261 | Platform 1 - Northbound Local - Station Building - Camden Town Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 2 no - To trackside wall departure end | | 2 | R731051 | N | Y |
| 46863 | INACTIVE | N | N091-00-3/261 | Platform 1 - Northbound Local - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | to cable trunking at high level - NAD | | | | | |
| 18535 | ACTIVE | N | N091-00-3/261 | Platform 1 - Northbound Local - Station Building - Camden Town Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 1x 50mm diameter, 2m long Cable - At the end of the platform in j-hanger running into into tunnel | 2 | | | N | N |
| 70886 | ACTIVE | N | N091-00-3/261 | Platform 1 - Northbound Local - Station Building - Camden Town Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R731051 | | |
| 70900 | ACTIVE | N | N091-00-3/261 | Platform 1 - Northbound Local - Station Building - Camden Town Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 8 no - To trackside wall arrivals end | | 8 | R731051 | N | Y |
| 70896 | ACTIVE | N | N091-00-3/261 | Platform 1 - Northbound Local - Station Building - Camden Town Stn | Debris: Other | Asbestos | Sampled – Not Detected | | | | Platform Invert - Plasterboard with MMMF insulation matrix -total <1m - To ceiling arrivals end | 1 | | R731051 | N | Y |
| 70894 | ACTIVE | N | N091-00-3/261 | Platform 1 - Northbound Local - Station Building - Camden Town Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 2 no - Trackside wall midway | | 2 | R731051 | N | Y |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 70892 | ACTIVE | N | N091-00-3/261 | Platform 1 - Northbound Local - Station Building - Camden Town Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 3 no - To platform side wall | | 3 | R731051 | N | Y |
| 70891 | ACTIVE | N | N091-00-3/261 | Platform 1 - Northbound Local - Station Building - Camden Town Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 2 no - To trackside wall departure end | | 2 | R731051 | N | Y |
| 70885 | ACTIVE | N | N091-00-3/261 | Platform 1 - Northbound Local - Station Building - Camden Town Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R731051 | | |
| 70898 | ACTIVE | N | N091-00-3/261 | Platform 1 - Northbound Local - Station Building - Camden Town Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 10 no - To ceiling arrivals end | | 10 | R731051 | N | Y |
| 70895 | ACTIVE | N | N091-00-3/261 | Platform 1 - Northbound Local - Station Building - Camden Town Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 10 no - Platform side wall midway | | 10 | R731051 | N | Y |
| 70890 | ACTIVE | N | N091-00-3/261 | Platform 1 - Northbound Local - Station Building - Camden Town Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Materials within link box - total 1 no - To trackside wall departure end | | 1 | R731051 | | |
| 16883 | ACTIVE | N | N091-00-3/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Camden Town Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Various Cables - within invert | | | | N | YES |
| 43121 | ACTIVE | N | N091-00-3/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Camden Town Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Tunnel ring caulking, throughout to bolts sprayed in yellow at Camden 20ab point bolt 1 | | | R512086 | N | N |
| 43122 | ACTIVE | N | N091-00-3/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Camden Town Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Tunnel ring caulking, throughout to bolts sprayed in yellow at Camden 20ab point bolt 2. | | | R512086 | N | N |
| 43123 | ACTIVE | N | N091-00-3/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Camden Town Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Tunnel ring caulking, throughout to bolts sprayed in yellow at Camden 20ab point bolt 3. | | | R512086 | N | N |
| 43126 | ACTIVE | N | N091-00-3/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Camden Town Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Tunnel ring caulking, throughout to bolts sprayed in yellow at Camden 20ab point bolt 6. | | | R512086 | N | N |
| 16882 | ACTIVE | N | N091-00-3/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Camden Town Stn | Cable Ducts: Bitumen | Asbestos | Surveyed – Not Detected | | | | Platform 1 Invert - Bitumen Ducts to Cross Passage - Middle of Invert - Non Asbestos | | | | | YES |
| 43124 | ACTIVE | N | N091-00-3/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Camden Town Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Tunnel ring caulking, throughout to bolts sprayed in yellow at Camden 20ab point bolt 4. | | | R512086 | N | N |
| 43125 | ACTIVE | N | N091-00-3/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Camden Town Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Tunnel ring caulking, throughout to bolts sprayed in yellow at Camden 20ab point bolt 5. | | | R512086 | N | N |
| 43127 | ACTIVE | N | N091-00-3/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Camden Town Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Tunnel ring caulking, throughout to bolts sprayed in yellow at Camden 20ab point bolt 7. | | | R512086 | N | N |
| 43128 | ACTIVE | N | N091-00-3/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Camden Town Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Tunnel ring caulking, throughout to bolts sprayed in yellow at Camden 20ab point bolt 8. | | | R512086 | N | N |
| 9623 | ACTIVE | N | N091-00-3/263 | Platform 3 - Northbound Fast - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|----------------------|---------------|-----------------------------|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18465 | ACTIVE | N | N091-00-3/263 | Platform 3 - Northbound Fast - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Walls - Supalux | | | | | |
| 70925 | ACTIVE | N | N091-00-3/263 | Platform 3 - Northbound Fast - Station Building - Camden Town Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - total >16 no - Throughout to J Hanger | | 16 | R731052 | | |
| 16885 | ACTIVE | N | N091-00-3/263 | Platform 3 - Northbound Fast - Station Building - Camden Town Stn | Cable: Sheath | Asbestos | Not Found during Inspection | | | | Various Cables - within invert | | | | N | |
| 16884 | ACTIVE | N | N091-00-3/263 | Platform 3 - Northbound Fast - Station Building - Camden Town Stn | Cable Ducts: Bitumen | Asbestos | Surveyed – Not Detected | | | | Bitumen duct (2 x), head wall, platform side, Bitumen duct (2 x), head wall, track side NADIS | | | | | |
| 70922 | ACTIVE | N | N091-00-3/263 | Platform 3 - Northbound Fast - Station Building - Camden Town Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Materials within Link box - total 1 no - Trackside wall departure end | | 1 | R731052 | | |
| 70920 | ACTIVE | N | N091-00-3/263 | Platform 3 - Northbound Fast - Station Building - Camden Town Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R731052 | | |
| 70921 | ACTIVE | N | N091-00-3/263 | Platform 3 - Northbound Fast - Station Building - Camden Town Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 2 no - Platform wall departure end | | 2 | R731052 | N | Y |
| 70919 | ACTIVE | N | N091-00-3/263 | Platform 3 - Northbound Fast - Station Building - Camden Town Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R731052 | | |
| 70927 | ACTIVE | N | N091-00-3/263 | Platform 3 - Northbound Fast - Station Building - Camden Town Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 2 no - Trackside wall arrivals end | | 2 | R731052 | N | Y |
| 70926 | ACTIVE | N | N091-00-3/263 | Platform 3 - Northbound Fast - Station Building - Camden Town Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 2 no - Trackside wall midway | | 2 | R731052 | N | Y |
| 18536 | ACTIVE | N | N091-00-3/263 | Platform 3 - Northbound Fast - Station Building - Camden Town Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Woven cable (2 x 15 m), at high level into invert. Head wall, platform side, | | | | N | N |
| 70924 | ACTIVE | N | N091-00-3/263 | Platform 3 - Northbound Fast - Station Building - Camden Town Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Materials within small Westinghouse box - total 1 no - By shaft to floor departure end | | 1 | R731052 | | |
| 42628 | ACTIVE | N | N091-00-3/263/ FLR-01 | Floor - 1 - Platform 3 - Station Building - Camden Town Stn | Cable Duct: Other | Asbestos | Sampled – Not Detected | | | | Dust, throughout, to LHS cable run on Northbound Platform 3 invert at Camden Town Station | | | R515301 | N | N |
| 42625 | ACTIVE | N | N091-00-3/263/ FLR-01 | Floor - 1 - Platform 3 - Station Building - Camden Town Stn | Cable Duct: Other | Asbestos | Sampled – Not Detected | | | | Dust, throughout, to invert floor on Northbound Platform 3 invert at Camden Town Station | | | R515301 | N | N |
| 16886 | ACTIVE | N | N091-00-3/263/ FLR-01 | Floor - 1 - Platform 3 - Station Building - Camden Town Stn | Cable Ducts: Bitumen | Asbestos | Surveyed – Not Detected | | | | Platform 3 Invert - Bitumen Ducts to 4/953, under 3/715 & to track - Non Asbestos | | | | | YES |
| 16887 | ACTIVE | N | N091-00-3/263/ FLR-01 | Floor - 1 - Platform 3 - Station Building - Camden Town Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 3 Invert - Various Cables | | | | | YES |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 16888 | ACTIVE | N | N091-00-3/263/FLR-01 | Floor - 1 - Platform 3 - Station Building - Camden Town Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Platform 3 Invert - 1 x Switch Box - Insulation within - Under 3/714 RHS | | 1 | | N | YES |
| 42629 | ACTIVE | N | N091-00-3/263/FLR-01 | Floor - 1 - Platform 3 - Station Building - Camden Town Stn | Cable Duct: Other | Asbestos | Sampled – Not Detected | | | | Dust, throughout, to invert floor on Northbound Platform 3 invert at Camden Town Station | | | R515301 | N | N |
| 42626 | ACTIVE | N | N091-00-3/263/FLR-01 | Floor - 1 - Platform 3 - Station Building - Camden Town Stn | Cable Duct: Other | Asbestos | Sampled – Not Detected | | | | Dust, throughout, within broken concrete to invert floor on Northbound Platform 3 invert at Camden Town Station | | | R515301 | N | N |
| 42627 | ACTIVE | N | N091-00-3/263/FLR-01 | Floor - 1 - Platform 3 - Station Building - Camden Town Stn | Cable Duct: Other | Asbestos | Sampled – Not Detected | | | | Dust, throughout, to RHS cable run on Northbound Platform 3 invert at Camden Town Station | | | R515301 | N | N |
| 9624 | ACTIVE | N | N091-00-3/603 | Stairs: Linear - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18537 | ACTIVE | N | N091-00-3/603 | Stairs: Linear - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9625 | ACTIVE | N | N091-00-3/604 | Stairs: Linear - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16889 | ACTIVE | N | N091-00-3/604 | Stairs: Linear - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9626 | ACTIVE | N | N091-00-3/605 | Stairs: Linear - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19134 | ACTIVE | N | N091-00-3/605 | Stairs: Linear - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9627 | ACTIVE | N | N091-00-3/606 | Stairs: Linear - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18909 | ACTIVE | N | N091-00-3/606 | Stairs: Linear - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 16890 | ACTIVE | N | N091-00-3/636 | Overbridge - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 19360 | ACTIVE | N | N091-00-3/637 | Overbridge - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9628 | ACTIVE | N | N091-00-3/661 | Switch Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18602 | ACTIVE | N | N091-00-3/661 | Switch Room - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel above door- Non Asbestos | | | | | |
| 42073 | ACTIVE | N | N091-00-3/661 | Switch Room - Station Building - Camden Town Stn | Lead/Leading | Lead Paint/Lead | Presumed | | | | Presumed Cream based Lead paint - to walls and ceiling | | | | N | N |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|------------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 42072 | ACTIVE | N | N091-00-3/661/FLR-01 | Floor - 1 - Switch Room - Station Building - Camden Town Stn | Cable Ducts: Cement | Asbestos | Presumed | | | | Ducts filled in. Presumed asbestos | | | | N | |
| 16891 | ACTIVE | N | N091-00-3/661/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Camden Town Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 3 x 60amp, 5 x 100amp, 1 x 200amp Switch Boxes - Insulation within | | 9 | | N | N |
| 25659 | ACTIVE | N | N091-00-3/661/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Camden Town Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box | | 1 | | N | N |
| 25660 | ACTIVE | N | N091-00-3/661/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Camden Town Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 x 100 amp, 4 x 60amp Switch Boxes | | 5 | | N | N |
| 9629 | ACTIVE | N | N091-00-3/664 | Switch Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16892 | ACTIVE | N | N091-00-3/664/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Camden Town Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 x 60amp, 3 x 60amp Switch Boxes - Insulation within | | 4 | | N | N |
| 9630 | ACTIVE | N | N091-00-3/671 | Switch Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19135 | ACTIVE | N | N091-00-3/671 | Switch Room - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 9631 | ACTIVE | N | N091-00-3/706 | IMR - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42075 | ACTIVE | N | N091-00-3/706 | IMR - Station Building - Camden Town Stn | Other Boarding | Asbestos | Removed | | | | Paxoline Boards to back of room - wall 2 | | | | N | N |
| 42076 | ACTIVE | N | N091-00-3/706 80143126 | IMR - Station Building - Camden Town Stn Room Assets | Other Electrical Boxes | Asbestos | Presumed | | | | Electrical equipment presumed to contain asbestos within | | 2 | | N | N |
| 46829 | ACTIVE | N | N091-00-3/706 | IMR - Station Building - Camden Town Stn | Other Boarding | Asbestos | Removed | | | | Brown paxoline board to wall 1 to 4x boxes | | | | | |
| 18603 | ACTIVE | N | N091-00-3/706 | IMR - Station Building - Camden Town Stn | Cable: Sheath | Asbestos | Removed | | | | 500m long Cable going into Invert | | | | N | |
| 46830 | ACTIVE | N | N091-00-3/706 | IMR - Station Building - Camden Town Stn | Other Boarding | Asbestos | Removed | | | | brown paxoline board to 2boxes wall 3 | | | | | |
| 46840 | ACTIVE | N | N091-00-3/706/CLG-03 | Ceiling: Solid - 3 - IMR - Station Building - Camden Town Stn | Other Boarding | Asbestos | Removed | | | | board to rack - small box shape wall 3 | | | | | |
| 16893 | ACTIVE | N | N091-00-3/706/FLR-01 | Floor - 1 - IMR - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux on floors - Non Asbestos | | | | | |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------------------|---|---------------------|--------------------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 9632 | ACTIVE | N | N091-00-3/713 | Relay Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Strongly Presumed | | | | | | | | | |
| 25675 | ACTIVE | N | N091-00-3/713 | Relay Room - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding | | | | | |
| 69983 | ACTIVE | N | N091-00-3/713 80143127 | Relay Room - Station Building - Camden Town Stn Room Assets | Cable: Sheath | Asbestos | Strongly Presumed | | | | Braided Cables Throughout. Woven Sheathing over wiring to terminals | 10 | | | | |
| 46831 | ACTIVE | N | N091-00-3/713 80143127 | Relay Room - Station Building - Camden Town Stn Room Assets | Other Boarding | Asbestos | Presumed | | | | Paxoline Board to Rectifiers - wall 3 &4 in first room | | | | | |
| 46832 | ACTIVE | N | N091-00-3/713 | Relay Room - Station Building - Camden Town Stn | Other Boarding | Asbestos | Presumed | | | | paxoline board to wall 3 & 4 first room | | | | | |
| 25673 | ACTIVE | N | N091-00-3/713 | Relay Room - Station Building - Camden Town Stn | Cable Ducts: Cement | Asbestos | Presumed | | | | Cement Ducts - in two areas of the room | | | | N | |
| 46833 | ACTIVE | N | N091-00-3/713 | Relay Room - Station Building - Camden Town Stn | Other Boarding | Asbestos | Presumed | | | | Board paxoline to wall 3 & 4 | | | | | |
| 16895 | ACTIVE | N | N091-00-3/713/ CLG-01 | Ceiling: Solid - 1 - Relay Room - Station Building - Camden Town Stn | No Access | Asbestos | No Access: Presumed | | | | No Info on Ceiling | | | | | |
| 25669 | ACTIVE | N | N091-00-3/713/ WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Camden Town Stn | PCBs | Asbestos | Strongly Presumed | | | | 6 x PCB's - fair condition | | 6 | | N | N |
| 16894 | ACTIVE | N | N091-00-3/713/ WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Camden Town Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | on Walls (Previously sampled NAD) | | | | | |
| 42328 | INACTIVE | N | N091-00-3/713/ WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Camden Town Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | 6 x Silver Cylinder PCB's on Paxo Board | | 6 | | N | N |
| 25676 | ACTIVE | N | N091-00-3/713/ WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Camden Town Stn | Boarding: Cement | Asbestos | Presumed | | | | Approx 40 Arc Chutes | | 40 | | N | N |
| 44145 | ACTIVE | N | N091-00-3/713/ WAL-002 80897650 | Wall: Internal - 2 - Relay Room - Station Building - Camden Town Stn Wall: Internal | Other Boarding | Asbestos | Presumed | | | | Paxoline boarding behind PCB cylinders | | 1 | | N | N |
| 25672 | ACTIVE | N | N091-00-3/713/ WAL-004 | Wall: Internal - 4 - Relay Room - Station Building - Camden Town Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline Board | | 1 | | N | N |
| 25674 | ACTIVE | N | N091-00-3/713/ WAL-004 80897652 | Wall: Internal - 4 - Relay Room - Station Building - Camden Town Stn Wall: Internal | Cable: Sheath | Asbestos | Sampled – Not Detected | | | | Braided Cables - R713551 - non asbestos - ID confirmed | | | | N | N |
| 42057 | INACTIVE | N | N091-00-3/713/ WAL-004 80897652 | Wall: Internal - 4 - Relay Room - Station Building - Camden Town Stn Wall: Internal | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | 12 x Silver Cylinder PCB's - Fair condition (above the door & high level); 5 x separate locations on same wall | | 12 | | N | N |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------------------------|---|------------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 25670 | ACTIVE | N | N091-00-3/713/ WAL-009 80963018 | Wall: Internal - 9 - Relay Room - Station Building - Camden Town Stn Wall: Internal | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | 2 x Rectifier Boxes - Asbestos materials within | | 2 | | N | N |
| 25671 | ACTIVE | N | N091-00-3/713/ WAL-009 80963018 | Wall: Internal - 9 - Relay Room - Station Building - Camden Town Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | 1 x Electrical Box - Asbestos materials within | | 1 | | N | N |
| 25667 | ACTIVE | N | N091-00-3/713/ WAL-010 80963019 | Wall: Internal - 10 - Relay Room - Station Building - Camden Town Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 2 x Fuse Switches - Asbestos rope seal and materials within this older type box | | 2 | | N | N |
| 25668 | ACTIVE | N | N091-00-3/713/ WAL-010 80963019 | Wall: Internal - 10 - Relay Room - Station Building - Camden Town Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | 1 x Transformer - Asbestos materials within | | 1 | | N | N |
| 9633 | ACTIVE | N | N091-00-3/714 | Relay Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 53684 | ACTIVE | N | N091-00-3/714 | Relay Room - Station Building - Camden Town Stn | Other Boarding | Asbestos | Removed | | | | composite boarding to wall | | | | | |
| 46834 | ACTIVE | N | N091-00-3/714 | Relay Room - Station Building - Camden Town Stn | Other Boarding | Asbestos | Presumed | | | | paxoline board to wall switch | | | | | |
| 18604 | ACTIVE | N | N091-00-3/714 | Relay Room - Station Building - Camden Town Stn | Cable: Sheath | Asbestos | Removed | | | | Various Cables | | | | N | N |
| 16896 | ACTIVE | N | N091-00-3/714 | Relay Room - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing - Non Asbestos | | | | | |
| 46839 | ACTIVE | N | N091-00-3/714/ WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Camden Town Stn | Other Boarding | Asbestos | Removed | | | | 2 x brown paxoline board to boxes wall 3 | | | | | |
| 9634 | ACTIVE | N | N091-00-3/715 | Relay Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Presumed | | | | | | | | | |
| 46838 | INACTIVE | N | N091-00-3/715 | Relay Room - Station Building - Camden Town Stn | Cable: Sheath | Asbestos | Presumed | | | | 2x 50mm green cables into box | | | | | |
| 16897 | ACTIVE | N | N091-00-3/715 | Relay Room - Station Building - Camden Town Stn | Cable: Sheath | Asbestos | Removed | | | | 2x Green Cables feeding electrical box wall 2(back of room) | | 2 | | | |
| 53682 | INACTIVE | N | N091-00-3/715 | Relay Room - Station Building - Camden Town Stn | Other Boarding | Asbestos | Presumed | | | | brown paxoline board within cupboard | | | | | |
| 53683 | ACTIVE | N | N091-00-3/715 | Relay Room - Station Building - Camden Town Stn | Cable Ducts: Cement | Asbestos | Removed | | | | ducts within roller shutter presumed | | | | | |
| 42079 | ACTIVE | N | N091-00-3/715 | Relay Room - Station Building - Camden Town Stn | Cable: Sheath | Asbestos | Removed | | | | Asbestos braided cables presumed within roller shutter cabinet. | | | | | |
| 19136 | INACTIVE | N | N091-00-3/715 | Relay Room - Station Building - Camden Town Stn | PCBs | Polychlorinated biphenyl | Removed | | | | 5 x PCB's (located within roller shutter cabinet) - Poor Condition. Serial Nos not visible - HMU to investigate Removed by Edenbeck Feb 2017 | | 5 | | N | N |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|--------------------------------|--|---------------------|--------------------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 42080 | INACTIVE | N | N091-00-3/715/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Camden Town Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 1x Braided cable feeding electrical box | | | | | |
| 9635 | ACTIVE | N | N091-00-3/716 | Relay Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18415 | ACTIVE | N | N091-00-3/716 | Relay Room - Station Building - Camden Town Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 2m long Cable | | 1 | | N | N |
| 42082 | ACTIVE | N | N091-00-3/716 | Relay Room - Station Building - Camden Town Stn | Cable Ducts: Cement | Asbestos | Presumed | | | | Cable ducts - No access presumed asbestos sleeves within | | | | N | |
| 42081 | ACTIVE | N | N091-00-3/716 | Relay Room - Station Building - Camden Town Stn | Cable: Sheath | Asbestos | Presumed | | | | Braided cables within roller shutter cabinet | | | | N | N |
| 16898 | ACTIVE | N | N091-00-3/716 | Relay Room - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels - Non Asbestos | | | | | |
| 16899 | INACTIVE | N | N091-00-3/716 | Relay Room - Station Building - Camden Town Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | 3 x PCB's (located within roller shutter cabinet) - Fair Condition. Serial Nos not visible | | 3 | | N | N |
| 18910 | INACTIVE | N | N091-00-3/791 | Vent Shaft - Station Building - Camden Town Stn | Cable: Wrap | Asbestos | Removed | | | | Cable Wrap - Chrysotile Removed by Forest ES5052 15/07/2014 | | | | | |
| 16900 | ACTIVE | N | N091-00-3/791 | Vent Shaft - Station Building - Camden Town Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | within Tunnel Rings | | | | | |
| 18605 | ACTIVE | N | N091-00-3/792 | Vent Shaft - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9636 | ACTIVE | N | N091-00-3/972 | Disused Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16902 | ACTIVE | N | N091-00-3/972 | Disused Room - Station Building - Camden Town Stn | Cable: Wrap | Asbestos | Surveyed – Not Detected | | | | | | | | | |
| 16901 | ACTIVE | N | N091-00-3/972 | Disused Room - Station Building - Camden Town Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 2m long Cable | | 1 | | N | N |
| 69982 | ACTIVE | N | N091-00-3/972/WAL-001 80897677 | Wall: Internal - 1 - Disused Room - Station Building - Camden Town Stn Wall: Internal | Westing house Boxes | Asbestos | Strongly Presumed | | | | Westinghouse Box adjacent to access door via Platform 1 | | | | | |
| 9637 | ACTIVE | N | N091-00-4/087 | Lobby - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16903 | ACTIVE | N | N091-00-4/087/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18911 | ACTIVE | N | N091-00-4/087/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Camden Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Rendered Plaster, Metal Matrix; Sheeting - Non Asbestos | | | | YES | |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 9638 | ACTIVE | N | N091-00-4/204 | Passage - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16904 | ACTIVE | N | N091-00-4/204 | Passage - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9639 | ACTIVE | N | N091-00-4/205 | Passage - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16905 | ACTIVE | N | N091-00-4/205 | Passage - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9640 | ACTIVE | N | N091-00-4/206 | Passage - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16906 | ACTIVE | N | N091-00-4/206 | Passage - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9641 | ACTIVE | N | N091-00-4/601 | Stairs: Linear - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18606 | ACTIVE | N | N091-00-4/601 | Stairs: Linear - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9642 | ACTIVE | N | N091-00-4/602 | Stairs: Linear - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16907 | ACTIVE | N | N091-00-4/602 | Stairs: Linear - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9643 | ACTIVE | N | N091-00-4/714 | Relay Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16908 | ACTIVE | N | N091-00-4/714 | Relay Room - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel above 4/786 | | | | | |
| 9644 | ACTIVE | N | N091-00-4/715 | Relay Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9645 | ACTIVE | N | N091-00-4/731 | CER - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 53617 | ACTIVE | N | N091-00-4/731 | CER - Station Building - Camden Town Stn | Other Boarding | Asbestos | Sampled – Not Detected | | | | brown composite boarding to wall 2 & 3 - confirmed NAD 4RS-JP-221111-R717826 | | | | | |
| 9646 | ACTIVE | N | N091-00-4/751 | Office - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-------------------------------|--|-------------------|---------------|--|----------|-----------|-----------------|------------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 16909 | ACTIVE | N | N091-00-4/751/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18607 | ACTIVE | N | N091-00-4/751/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Camden Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Sheeting above False Ceiling | | | | YES | |
| 9647 | ACTIVE | N | N091-00-4/771 | Fan Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9648 | ACTIVE | N | N091-00-4/776 | Fan Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18416 | ACTIVE | N | N091-00-4/776 | Fan Room - Station Building - Camden Town Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Box - Insulation within | | 1 | | N | N |
| 16910 | ACTIVE | N | N091-00-4/776 | Fan Room - Station Building - Camden Town Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Cementitious Boarding back of Door | | 1 | | | |
| 9649 | ACTIVE | N | N091-00-4/777 | Fan Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19361 | ACTIVE | N | N091-00-4/777 | Fan Room - Station Building - Camden Town Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | within Tunnel Rings | | | | | |
| 9650 | ACTIVE | N | N091-00-4/778 | Fan Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16911 | ACTIVE | N | N091-00-4/778/DOR-01 | Door - 1 - Fan Room - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Door Panel - Non Asbestos | | | | | |
| 9651 | ACTIVE | N | N091-00-4/786 | Service Riser - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19137 | ACTIVE | N | N091-00-4/786 | Service Riser - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9652 | ACTIVE | N | N091-00-4/952 | Disused Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16912 | ACTIVE | N | N091-00-4/952/CLG-01 80897858 | Ceiling: Solid - 1 - Disused Room - Station Building - Camden Town Stn Ceiling: Solid | Void | Asbestos | Surveyed – Not Detected | | | | Above Metal Ceiling | | | | YES | |
| 9653 | ACTIVE | N | N091-00-4/953 | Disused Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18608 | ACTIVE | N | N091-00-4/953 | Disused Room - Station Building - Camden Town Stn | Cable: Wrap | Asbestos | Surveyed – Not Detected | | | | | | | | | |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 16913 | ACTIVE | N | N091-00-4/953 | Disused Room - Station Building - Camden Town Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Brown Oil Based Paint - Beam above 4/778. Thickness .24mm; Est Quantity 16sqm; Analysis 6.47% | | | | N | N |
| 9654 | ACTIVE | N | N091-00-4/954 | Disused Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16914 | ACTIVE | N | N091-00-4/954 | Disused Room - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9655 | ACTIVE | N | N091-00-5/121 | Platform Invert - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16915 | ACTIVE | N | N091-00-5/121 | Platform Invert - Station Building - Camden Town Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Platform Invert - No Access | | | | | |
| 9656 | ACTIVE | N | N091-00-5/122 | Platform Invert - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18609 | ACTIVE | N | N091-00-5/122 | Platform Invert - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel - Non Asbestos | | | | | |
| 9657 | ACTIVE | N | N091-00-5/201 | Passage - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16916 | ACTIVE | N | N091-00-5/201 | Passage - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9658 | ACTIVE | N | N091-00-5/202 | Passage - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20078 | ACTIVE | N | N091-00-5/202 | Passage - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9659 | ACTIVE | N | N091-00-5/203 | Passage - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16917 | ACTIVE | N | N091-00-5/203 | Passage - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9660 | ACTIVE | N | N091-00-5/262 | Platform 2 - Southbound Local - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70884 | ACTIVE | N | N091-00-5/262 | Platform 2 - Southbound Local - Station Building - Camden Town Stn | Cement Troughing | Asbestos | Known | | | | Platform Invert - Cement shuttering - total <1m - To ceiling by departure end | 1 | | R731051 | N | Y |
| 16919 | ACTIVE | N | N091-00-5/262 | Platform 2 - Southbound Local - Station Building - Camden Town Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Woven cable at high level into invert. Southbound head wall | | | | | |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|----------------------|---------------|-------------------------|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 16920 | ACTIVE | N | N091-00-5/262 | Platform 2 - Southbound Local - Station Building - Camden Town Stn | Cable Ducts: Cement | Asbestos | Known | | | | Cement ducts x 4 southbound Head Wall | | | | N | |
| 16921 | ACTIVE | N | N091-00-5/262 | Platform 2 - Southbound Local - Station Building - Camden Town Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Approx. 7 x Cables going to Track, 6 x Cables nr 5/121 | | | | | |
| 70873 | ACTIVE | N | N091-00-5/262 | Platform 2 - Southbound Local - Station Building - Camden Town Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R731051 | | |
| 70876 | ACTIVE | N | N091-00-5/262 | Platform 2 - Southbound Local - Station Building - Camden Town Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - total >20no throughout - To J Hanger | | 20 | R731051 | | |
| 70877 | ACTIVE | N | N091-00-5/262 | Platform 2 - Southbound Local - Station Building - Camden Town Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Materials within link box - total 1 no - To trackside wall arrivals end | | 1 | R731051 | | |
| 70879 | ACTIVE | N | N091-00-5/262 | Platform 2 - Southbound Local - Station Building - Camden Town Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 2 no - To ceiling arrivals end | | 2 | R731051 | N | Y |
| 70883 | ACTIVE | N | N091-00-5/262 | Platform 2 - Southbound Local - Station Building - Camden Town Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 6 no - To trackside wall departure end | | 6 | R731051 | N | Y |
| 16918 | ACTIVE | N | N091-00-5/262 | Platform 2 - Southbound Local - Station Building - Camden Town Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Bitumen duct (2 x) head wall, platform side - NADIS, Bitumen duct (2 x), head wall, below nosing - NADIS Dust, middle of platform 2 in pit - NADIS | | | | | |
| 70882 | ACTIVE | N | N091-00-5/262 | Platform 2 - Southbound Local - Station Building - Camden Town Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 8 no - To platform wall | | 8 | R731051 | N | Y |
| 70880 | ACTIVE | N | N091-00-5/262 | Platform 2 - Southbound Local - Station Building - Camden Town Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 2 no - To trackside wall - midway | | 2 | R731051 | N | Y |
| 70878 | ACTIVE | N | N091-00-5/262 | Platform 2 - Southbound Local - Station Building - Camden Town Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable duct - total 1 no - To trackside wall arrivals end | | 1 | R731051 | N | Y |
| 19138 | ACTIVE | N | N091-00-5/262 | Platform 2 - Southbound Local - Station Building - Camden Town Stn | Cable Ducts: Cement | Asbestos | Known | | | | 2 x Cable Sleeves - Chrysotile near 5/121 invert access | | | | | |
| 46864 | ACTIVE | N | N091-00-5/262 | Platform 2 - Southbound Local - Station Building - Camden Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | To metal cable trunking CMS | | | | | |
| 70872 | ACTIVE | N | N091-00-5/262 | Platform 2 - Southbound Local - Station Building - Camden Town Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R731051 | | |
| 16923 | ACTIVE | N | N091-00-5/262/ FLR-01 | Floor - 1 - Platform 2 - Station Building - Camden Town Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform 2 Invert - Cable Duct | | | | | YES |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18610 | ACTIVE | N | N091-00-5/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Camden Town Stn | Cable Ducts: Cement | Asbestos | Known | | | | Cable Sleeve in Floor - Chrysotile Nr 5/706: Cement Around Cable Sleeve - Non Asbestos | | | | N | |
| 16922 | ACTIVE | N | N091-00-5/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Camden Town Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform 2 Invert - 13 x Cables | | | | | YES |
| 9661 | ACTIVE | N | N091-00-5/264 | Platform 4 - Southbound Fast - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70908 | ACTIVE | N | N091-00-5/264 | Platform 4 - Southbound Fast - Station Building - Camden Town Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R731052 | | |
| 70910 | ACTIVE | N | N091-00-5/264 | Platform 4 - Southbound Fast - Station Building - Camden Town Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 no - To trackside wall, arrivals end | | 2 | R731052 | N | Y |
| 70911 | ACTIVE | N | N091-00-5/264 | Platform 4 - Southbound Fast - Station Building - Camden Town Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Materials within core box - total 1 no - To trackside wall | | 1 | R731052 | | |
| 70912 | ACTIVE | N | N091-00-5/264 | Platform 4 - Southbound Fast - Station Building - Camden Town Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable duct - total 1 no - To trackside wall | | 1 | R731052 | N | Y |
| 70913 | ACTIVE | N | N091-00-5/264 | Platform 4 - Southbound Fast - Station Building - Camden Town Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - total >10 no - Throughout to J Hanger | | 10 | R731052 | | |
| 70914 | ACTIVE | N | N091-00-5/264 | Platform 4 - Southbound Fast - Station Building - Camden Town Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Materials within materials within small Westinghouse box - total 1 no - To trackside wall | | 1 | R731052 | | |
| 18611 | ACTIVE | N | N091-00-5/264 | Platform 4 - Southbound Fast - Station Building - Camden Town Stn | Cable: Wrap | Asbestos | Known | | | | 1 Lm Wrapping Chrysotile at head wall end of platform | | | | N | N |
| 44147 | ACTIVE | N | N091-00-5/264 | Platform 4 - Southbound Fast - Station Building - Camden Town Stn | Westing house Boxes | Asbestos | Presumed | | | | Westinghouse box located near head wall | | 1 | | N | N |
| 70915 | ACTIVE | N | N091-00-5/264 | Platform 4 - Southbound Fast - Station Building - Camden Town Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Materials within materials within small Westinghouse box - total 1 no - To trackside wall | | 1 | R731052 | | |
| 70916 | ACTIVE | N | N091-00-5/264 | Platform 4 - Southbound Fast - Station Building - Camden Town Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 2 no - To trackside wall, midway | | 2 | R731052 | N | Y |
| 70909 | ACTIVE | N | N091-00-5/264 | Platform 4 - Southbound Fast - Station Building - Camden Town Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R731052 | | |
| 44146 | ACTIVE | N | N091-00-5/264 | Platform 4 - Southbound Fast - Station Building - Camden Town Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Electrical box located at tail wall, platform 4 | | 1 | | N | N |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|----------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 70917 | ACTIVE | N | N091-00-5/264 | Platform 4 - Southbound Fast - Station Building - Camden Town Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 12 no - Platform side wall midway | | 12 | R731052 | N | Y |
| 70918 | ACTIVE | N | N091-00-5/264 | Platform 4 - Southbound Fast - Station Building - Camden Town Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total >10 no - Trackside wall departure end | | 10 | R731052 | N | Y |
| 44148 | ACTIVE | N | N091-00-5/264 | Platform 4 - Southbound Fast - Station Building - Camden Town Stn | Lead/Leading | Lead Paint/Lead | Presumed | | | | Blue lead paint paint to Westinghouse box and cream lead paint to pipe work | | | | N | N |
| 16924 | ACTIVE | N | N091-00-5/264/CLG-01 | Ceiling: Solid - 1 - Platform 4 - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels above Relay Room - Non Asbestos | | | | | |
| 18912 | ACTIVE | N | N091-00-5/264/FLR-01 | Floor - 1 - Platform 4 - Station Building - Camden Town Stn | Cable Ducts: Cement | Asbestos | No Access: Presumed | | | | 2 x Cable Sleeves - Chrysotile - within invert | | | | | YES |
| 16925 | ACTIVE | N | N091-00-5/264/FLR-01 | Floor - 1 - Platform 4 - Station Building - Camden Town Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 4 Invert - 6 x Cables | | | | | YES |
| 9662 | ACTIVE | N | N091-00-5/406 | Store - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18411 | ACTIVE | N | N091-00-5/406 | Store - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 16927 | ACTIVE | N | N091-00-5/406 | Store - Station Building - Camden Town Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Sink Cabinet & Table - Laminated - Non Asbestos | | | | | |
| 16926 | ACTIVE | N | N091-00-5/406 | Store - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 16806 | ACTIVE | N | N091-00-5/406/CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18457 | ACTIVE | N | N091-00-5/406/CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Camden Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal Roof Beams | | | | YES | |
| 16807 | ACTIVE | N | N091-00-5/406/WAL-001 | Wall: Internal - 1 - Store - Station Building - Camden Town Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 x 30amp Grey Switch Box - Insulation within | | 1 | | N | N |
| 9663 | ACTIVE | N | N091-00-5/591 | Disused Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9664 | ACTIVE | N | N091-00-5/663 | Switch Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16809 | ACTIVE | N | N091-00-5/663 | Switch Room - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel above entrance | | | | | |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|--------------------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 42084 | ACTIVE | N | N091-00-5/663/FLR-01 | Floor - 1 - Switch Room - Station Building - Camden Town Stn | Cable Ducts: Cement | Asbestos | Presumed | | | | Potential cable sleeve/sleeves filled in - No access | | | | N | N |
| 16808 | ACTIVE | N | N091-00-5/663/FLR-01 80897936 | Floor - 1 - Switch Room - Station Building - Camden Town Stn Floor | Cable Duct: Other | Asbestos | Presumed | | | | Cable Ducts x 3 | | 3 | | N | |
| 42083 | ACTIVE | N | N091-00-5/663/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Camden Town Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 1x 100 amps Switch box Wall 1 | | 1 | | N | N |
| 16810 | ACTIVE | N | N091-00-5/663/WAL-002 80897932 | Wall: Internal - 2 - Switch Room - Station Building - Camden Town Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 3 x 60amp, 1 x 100amp Fuse Switches | | 4 | | N | N |
| 25661 | ACTIVE | N | N091-00-5/663/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Camden Town Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 x 30amp Switch Box | | 1 | | N | N |
| 9665 | ACTIVE | N | N091-00-5/665 | Switch Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19486 | ACTIVE | N | N091-00-5/665 | Switch Room - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding above entrance | | | | | |
| 18519 | ACTIVE | N | N091-00-5/665/FLR-01 | Floor - 1 - Switch Room - Station Building - Camden Town Stn | Cable Duct: Other | Asbestos | Presumed | | | | Sealed Cable Ducts | | 3 | | N | |
| 16811 | ACTIVE | N | N091-00-5/665/WAL-002 80897941 | Wall: Internal - 2 - Switch Room - Station Building - Camden Town Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 4 x 60amp Fuse Switches | | 4 | | N | N |
| 9666 | ACTIVE | N | N091-00-5/670 | Switch Cupboard - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16814 | ACTIVE | N | N091-00-5/670 | Switch Cupboard - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9667 | ACTIVE | N | N091-00-5/706 | IMR - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 46835 | INACTIVE | N | N091-00-5/706 | IMR - Station Building - Camden Town Stn | Other Boarding | Asbestos | Presumed | | | | paxoline board to rack middle | | | | | |
| 46841 | ACTIVE | N | N091-00-5/706 | IMR - Station Building - Camden Town Stn | Other Boarding | Asbestos | Presumed | | | | paxoline board to air off sign to wall 2 back | | | | | |
| 42085 | ACTIVE | N | N091-00-5/706 | IMR - Station Building - Camden Town Stn | Other Electrical Boxes | Asbestos | Removed | | | | 1x Switch box presumed to contain asbestos insulation within | | 1 | | N | N |
| 46837 | ACTIVE | N | N091-00-5/706 | IMR - Station Building - Camden Town Stn | Other Boarding | Asbestos | Removed | | | | paxoline board (walls 1 & 3) | | | | | |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------------|--|------------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 46836 | ACTIVE | N | N091-00-5/706 | IMR - Station Building - Camden Town Stn | Other Boarding | Asbestos | Removed | | | | paxoline board to bay sign wall 1 | | | | | |
| 16813 | ACTIVE | N | N091-00-5/706 | IMR - Station Building - Camden Town Stn | Cable: Sheath | Asbestos | Removed | | | | Cable going to Track 1x 30mm diameter white cable | | 1 | | N | N |
| 16812 | ACTIVE | N | N091-00-5/706 | IMR - Station Building - Camden Town Stn | Cable: Sheath | Asbestos | Removed | | | | Cables going to Invert 2x 25mm diameter yellow cables 4x 15mm diameter white cables | | 6 | | N | N |
| 44149 | ACTIVE | N | N091-00-5/706 SC10003171 | IMR - Station Building - Camden Town Stn Room Assets | Other Boarding | Asbestos | Removed | | | | Paxoline boarding to wall 1 x 3 boxes | | | | N | N |
| 9668 | ACTIVE | N | N091-00-5/711 | Relay Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18520 | ACTIVE | N | N091-00-5/711 | Relay Room - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9669 | ACTIVE | N | N091-00-5/712 | Relay Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42088 | INACTIVE | N | N091-00-5/712 SC10003172 | Relay Room - Station Building - Camden Town Stn Room Assets | Cable Ducts: Cement | Asbestos | Presumed | | | | Cable sleeves within roller shutter cabinet filled in - No access | | | | N | |
| 44150 | ACTIVE | N | N091-00-5/712 SC10003172 | Relay Room - Station Building - Camden Town Stn Room Assets | Other Boarding | Asbestos | Presumed | | | | Paxoline boarding in roller shutter cabinets | | | | N | N |
| 16816 | ACTIVE | N | N091-00-5/712/ CLG-01 | Ceiling: Solid - 1 - Relay Room - Station Building - Camden Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above false Ceiling | | | | YES | |
| 16815 | ACTIVE | N | N091-00-5/712/ CLG-01 | Ceiling: Solid - 1 - Relay Room - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board | | | | | |
| 42087 | ACTIVE | N | N091-00-5/712/ WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Camden Town Stn | Cable Ducts: Cement | Asbestos | Presumed | | | | Cable sleeves within roller shutter cabinet | | | | N | N |
| 25666 | ACTIVE | N | N091-00-5/712/ WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Camden Town Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Braided Cables within roller shutter cabinet | | | | N | N |
| 18521 | INACTIVE | N | N091-00-5/712/ WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Camden Town Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | 5 x PCB's - Good Condition. Serial Nos None Visible | | 5 | | N | N |
| 9670 | ACTIVE | N | N091-00-5/713 | Relay Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42089 | INACTIVE | N | N091-00-5/713 | Relay Room - Station Building - Camden Town Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Asbestos flashguards/insulation presumed within this electrical box - box cover removed | | 1 | | N | N |
| 19128 | ACTIVE | N | N091-00-5/713 | Relay Room - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Wall by Door, Fuse Box & Light Switch - Supalux | | | | | |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|-----------------|--------------------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 16817 | INACTIVE | N | N091-00-5/713 | Relay Room - Station Building - Camden Town Stn | PCBs | Polychlorinated biphenyl | Removed | | | | 5 x PCB's - 4 x Fair Condition, 1 x Possibly leaking - under investigation by the HMU. Serial Nos None Visible. Removed by Edenbeck Feb 2017 ES7773a | | 5 | | | |
| 46842 | ACTIVE | N | N091-00-5/713/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Camden Town Stn | Cable: Sheath | Asbestos | Removed | | | | 2 x 50mm green woven cables to electrical box - within first cabinet and boarding to back of electrical box | | | | | |
| 25663 | ACTIVE | N | N091-00-5/713/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Camden Town Stn | Cable: Sheath | Asbestos | Removed | | | | Braided Cables within roller shutter - may be hidden from view within bunched lead cables | | | | N | N |
| 46843 | ACTIVE | N | N091-00-5/713/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Camden Town Stn | Cable: Sheath | Asbestos | Removed | | | | white woven cable within 2nd roller shutter cabinet | | | | | |
| 9671 | ACTIVE | N | N091-00-5/951 | Disused Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16818 | ACTIVE | N | N091-00-5/951 | Disused Room - Station Building - Camden Town Stn | No Access | Asbestos | Surveyed – Not Detected | | | | NAD | | | | | |
| 9672 | ACTIVE | N | N091-00-A/041 | Mess Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18905 | ACTIVE | N | N091-00-A/041/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Camden Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Fibreglass Lagging | | | | YES | |
| 9673 | ACTIVE | N | N091-00-A/047 | Mess Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16822 | ACTIVE | N | N091-00-A/047/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Camden Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Rock Wool lagging, conduit, all walls plaster | | | | YES | |
| 16819 | ACTIVE | N | N091-00-A/047/WAL-002 | Wall: Internal - 2 - Mess Room - Station Building - Camden Town Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel under Sink | | | | | |
| 18412 | ACTIVE | N | N091-00-A/047/WAL-003 | Wall: Internal - 3 - Mess Room - Station Building - Camden Town Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 16820 | ACTIVE | N | N091-00-A/047/WAL-004 | Wall: Internal - 4 - Mess Room - Station Building - Camden Town Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 18522 | ACTIVE | N | N091-00-A/047/WAL-005 | Wall: Internal - 5 - Mess Room - Station Building - Camden Town Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 16821 | ACTIVE | N | N091-00-A/047/WAL-006 | Wall: Internal - 6 - Mess Room - Station Building - Camden Town Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-------------------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 9674 | ACTIVE | N | N091-00-A/048 | Locker Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19129 | ACTIVE | N | N091-00-A/048 | Locker Room - Station Building - Camden Town Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 9675 | ACTIVE | N | N091-00-A/050 | Office - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16823 | ACTIVE | N | N091-00-A/050/FLR-01 | Floor - 1 - Office - Station Building - Camden Town Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Rubber Flooring | | | | | YES |
| 9676 | ACTIVE | N | N091-00-A/053 | Locker Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16824 | ACTIVE | N | N091-00-A/053 | Locker Room - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9677 | ACTIVE | N | N091-00-A/081 | Lobby - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18523 | ACTIVE | N | N091-00-A/081 | Lobby - Station Building - Camden Town Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 9678 | ACTIVE | N | N091-00-A/235 | Disused Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16825 | ACTIVE | N | N091-00-A/235 | Disused Room - Station Building - Camden Town Stn | Glazing Rope | Asbestos | Presumed | | | | Rope Seal to Skylight | | | | | |
| 16831 | ACTIVE | N | N091-00-A/235/CLG-01 80953853 | Ceiling: Solid - 1 - Disused Room - Station Building - Camden Town Stn Ceiling: Solid | Rope Seals | Asbestos | Strongly Presumed | | | | Glass Canopy - Rope Seal | | | | | N |
| 9679 | ACTIVE | N | N091-00-A/236 | Passage - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16826 | ACTIVE | N | N091-00-A/236 | Passage - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9680 | ACTIVE | N | N091-00-A/316 | Locker Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9681 | ACTIVE | N | N091-00-A/331 | Kitchen - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16827 | ACTIVE | N | N091-00-A/331/FLR-01 | Floor - 1 - Kitchen - Station Building - Camden Town Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Rubber Flooring | | | | | YES |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|--------------------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 9682 | ACTIVE | N | N091-00-A/416 | Toilet: Unisex - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18524 | ACTIVE | N | N091-00-A/416 | Toilet: Unisex - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9683 | ACTIVE | N | N091-00-A/418 | Toilet: Unisex - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16829 | ACTIVE | N | N091-00-A/418/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Camden Town Stn | Void | Asbestos | No Access: Presumed | | | | Hatch Not Surveyed above False Ceiling | | | | YES | |
| 16828 | ACTIVE | N | N091-00-A/418/FLR-01 | Floor - 1 - Toilet - Station Building - Camden Town Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Rubber Flooring | | | | | YES |
| 9684 | ACTIVE | N | N091-00-A/419 | Shower Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16830 | ACTIVE | N | N091-00-A/419 | Shower Room - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9685 | ACTIVE | N | N091-00-A/578 | Stairs: Linear - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9686 | ACTIVE | N | N091-00-A/633 | Stairs: Spiral - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16832 | ACTIVE | N | N091-00-A/633 | Stairs: Spiral - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 16833 | ACTIVE | N | N091-00-A/646 | Gantry - Station Building - Camden Town Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed | | | | | |
| 9687 | ACTIVE | N | N091-00-A/651 | Plant Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9688 | ACTIVE | N | N091-00-A/661 | Switch Room - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18525 | ACTIVE | N | N091-00-A/661/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Camden Town Stn | Rope Gaskets | Asbestos | Sampled – Not Detected | | | | Rope gasket (2 x 2(L)m), within red spot door to wall 2. NADIS | | | | | |
| 16834 | ACTIVE | N | N091-00-A/661/WAL-002 80898299 | Wall: Internal - 2 - Switch Room - Station Building - Camden Town Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 2 x 100amp , 1 x 60amp Fuse Switches | | 3 | | N | N |
| 9689 | ACTIVE | N | N091-00-A/731 | CER - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|---------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 18906 | ACTIVE | N | N091-00-A/731 | CER - Station Building - Camden Town Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 9690 | ACTIVE | N | N091-00-A/801 | Lobby - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20076 | INACTIVE | N | N091-00-A/801/FLR-01 | Floor - 1 - Lobby - Station Building - Camden Town Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Rubber Flooring | | | | | YES |
| 16836 | ACTIVE | N | N091-00-A/801/FLR-01 | Floor - 1 - Lobby - Station Building - Camden Town Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Rubber Flooring | | | | | YES |
| 9691 | ACTIVE | N | N091-00-A/803 | Passage - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16835 | ACTIVE | N | N091-00-A/803 | Passage - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9692 | ACTIVE | N | N091-00-A/804 | Office - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 46502 | ACTIVE | N | N091-00-A/804/FLR-01 | Floor - 1 - Office - Station Building - Camden Town Stn | No Access | Asbestos | No Access: Presumed | | | | No Access beneath Flooring | | | | | |
| 9693 | ACTIVE | N | N091-00-B/236 | Passage - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9694 | ACTIVE | N | N091-00-B/316 | Store - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16837 | ACTIVE | N | N091-00-B/316 | Store - Station Building - Camden Town Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 9695 | ACTIVE | N | N091-00-B/411 | Store - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16838 | ACTIVE | N | N091-00-B/411 | Store - Station Building - Camden Town Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9696 | ACTIVE | N | N091-00-B/412 | Store - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9697 | ACTIVE | N | N091-00-B/413 | Store - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16839 | ACTIVE | N | N091-00-B/413 | Store - Station Building - Camden Town Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 9698 | ACTIVE | N | N091-00-B/415 | Kitchen - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18526 | ACTIVE | N | N091-00-B/415/FLR-01 | Floor - 1 - Kitchen - Station Building - Camden Town Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Rubber Flooring | | | | | YES |
| 9699 | ACTIVE | N | N091-00-B/416 | Toilet: Female - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16840 | ACTIVE | N | N091-00-B/416/FLR-01 | Floor - 1 - Toilet - Station Building - Camden Town Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Rubber Flooring | | | | | YES |
| 9700 | ACTIVE | N | N091-00-B/417 | Shower - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16841 | ACTIVE | N | N091-00-B/417/FLR-01 | Floor - 1 - Shower - Station Building - Camden Town Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Rubber Flooring | | | | | YES |
| 9701 | ACTIVE | N | N091-00-B/418 | Toilet: Male - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16842 | ACTIVE | N | N091-00-B/418 | Toilet: Male - Station Building - Camden Town Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 9702 | ACTIVE | N | N091-00-B/576 | Stairs: Linear - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18413 | ACTIVE | N | N091-00-B/576 | Stairs: Linear - Station Building - Camden Town Stn | Other Electrical Boxes | Asbestos | No Access: Presumed | | | | Gasket to Lift Motor | | | | | |
| 18527 | ACTIVE | N | N091-00-B/576 | Stairs: Linear - Station Building - Camden Town Stn | Rope Gaskets | Asbestos | Surveyed – Not Detected | | | | Rope to pulley of sash window , top of stairs - NAD | | | | | |
| 16843 | ACTIVE | N | N091-00-B/576 | Stairs: Linear - Station Building - Camden Town Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Service Lift Shaft Insulating Board - Non Asbestos | | | | | |
| 70064 | ACTIVE | N | N091-00-B/576 | Stairs: Linear - Station Building - Camden Town Stn | No Access | Asbestos | No Access: Presumed | | | | No access above false ceiling | | | | Y | |
| 9703 | ACTIVE | N | N091-00-B/631 | Stairs: Spiral - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19130 | ACTIVE | N | N091-00-B/631 | Stairs: Spiral - Station Building - Camden Town Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed | | | | | |
| 9704 | ACTIVE | N | N091-00-B/801 | SER - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16844 | ACTIVE | N | N091-00-B/801/CLG-01 | Ceiling: Solid - 1 - SER - Station Building - Camden Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above false Ceiling - Plastic Cable, CMS; Concrete; Artex to Ceiling | | | | YES | |
| 9705 | ACTIVE | N | N091-00-B/802 | Office - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 16845 | ACTIVE | N | N091-00-B/802 | Office - Station Building - Camden Town Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 16846 | ACTIVE | N | N091-00-B/802/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |
| 16847 | ACTIVE | N | N091-00-B/802/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Camden Town Stn | Void | Asbestos | No Access: Presumed | | | | Above False Ceiling | | | | YES | |
| 9706 | ACTIVE | N | N091-00-B/803 | Store - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18907 | ACTIVE | N | N091-00-B/803/CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Camden Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above Fibre Tiles - Plastic Cables, Armour Flex Lagging; CMS Cable Troughing; Concrete, Metal Mesh; Artex to Ceiling - Non Asbestos - Badly Damaged; | | | | YES | |
| 18528 | ACTIVE | N | N091-00-B/803/FLR-01 | Floor - 1 - Store - Station Building - Camden Town Stn | Void | Asbestos | No Access: Presumed | | | | Concrete, Wood beneath Carpet Tiles, Hard Board and Wood | | | | | YES |
| 16848 | ACTIVE | N | N091-00-B/803/WAL-002 | Wall: Internal - 2 - Store - Station Building - Camden Town Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 19359 | ACTIVE | N | N091-00-B/803/WAL-003 | Wall: Internal - 3 - Store - Station Building - Camden Town Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 19131 | ACTIVE | N | N091-00-B/803/WAL-004 | Wall: Internal - 4 - Store - Station Building - Camden Town Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 9707 | ACTIVE | N | N091-00-B/804 | Store - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9708 | ACTIVE | N | N091-00-B/991 | Office - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16849 | ACTIVE | N | N091-00-B/991 | Office - Station Building - Camden Town Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 16850 | ACTIVE | N | N091-00-B/991/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Camden Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plaster Walls; Wood Panels above Fibreboard Ceiling | | | | YES | |
| 9709 | ACTIVE | N | N091-00-B/992 | Store - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9710 | ACTIVE | N | N091-00-B/993 | Office - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N091-00 - Station Building - Camden Town Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--------------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 18529 | ACTIVE | N | N091-00-B/993 | Office - Station Building - Camden Town Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 16852 | ACTIVE | N | N091-00-B/993/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Camden Town Stn | Void | Asbestos | Surveyed – Not Detected | | | | Rendered Plaster above Supalux Panel | | | | YES | |
| 16851 | ACTIVE | N | N091-00-B/993/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Camden Town Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |
| 9711 | ACTIVE | N | N091-00-B/994 | Office - Station Building - Camden Town Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N093-00 - Station Building - Mornington Crescent Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9713 | ACTIVE | N | N093-00-1/001 | Booking Hall - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19340 | ACTIVE | N | N093-00-1/001/FLR-01 | Floor - 1 - Booking Hall - Station Building - Mornington Crescent Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Vinyl Tiles | | | | | |
| 9714 | ACTIVE | N | N093-00-1/011 | Ticket Office - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19342 | ACTIVE | N | N093-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Mornington Crescent Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 19343 | ACTIVE | N | N093-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Mornington Crescent Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal, Fibreglass Lagging above Supalux Tiles | | | | YES | |
| 19341 | ACTIVE | N | N093-00-1/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Mornington Crescent Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Wooden False Floor | | | | | YES |
| 9715 | ACTIVE | N | N093-00-1/021 | POM - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19747 | ACTIVE | N | N093-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Mornington Crescent Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 19385 | ACTIVE | N | N093-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Mornington Crescent Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal, Fibreglass Lagging above Supalux Tiles | | | | YES | |



Hazardous Material Asset Register - Summary



N093-00 - Station Building - Mornington Crescent Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 20154 | ACTIVE | N | N093-00-1/021/FLR-01 | Floor - 1 - POM - Station Building - Mornington Crescent Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Wooden False Floor | | | | | YES |
| 9716 | ACTIVE | N | N093-00-1/071 | Circulation Area - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20153 | ACTIVE | N | N093-00-1/071 | Circulation Area - Station Building - Mornington Crescent Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Railing & Surround on Staircase: Blue Gloss contains lead levels greater then 1% | | | | N | N |
| 9717 | ACTIVE | N | N093-00-1/081 | Lobby - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19386 | ACTIVE | N | N093-00-1/081/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Mornington Crescent Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 20155 | ACTIVE | N | N093-00-1/081/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Mornington Crescent Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above Plasterboard | | | | YES | |
| 9718 | ACTIVE | N | N093-00-1/082 | Lobby - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9719 | ACTIVE | N | N093-00-1/083 | Lobby - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19816 | ACTIVE | N | N093-00-1/083 | Lobby - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 19387 | ACTIVE | N | N093-00-1/083/FLR-01 | Floor - 1 - Lobby - Station Building - Mornington Crescent Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Lino | | | | | YES |
| 9720 | ACTIVE | N | N093-00-1/084 | Lobby - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19388 | ACTIVE | N | N093-00-1/084 | Lobby - Station Building - Mornington Crescent Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Note. doors to area outside Main entrance isn't accessible. Requires access via lift. | | | | | |
| 9721 | ACTIVE | N | N093-00-1/131 | LMR - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19389 | ACTIVE | N | N093-00-1/131 | LMR - Station Building - Mornington Crescent Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard & Superlux Boxing | | | | | |
| 19603 | ACTIVE | N | N093-00-1/136 | Lift Shaft - Station Building - Mornington Crescent Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access unable to locate via lift lobby on ground and basement level, also checked lift motor room | | | | | |



Hazardous Material Asset Register - Summary



N093-00 - Station Building - Mornington Crescent Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9722 | ACTIVE | N | N093-00-1/236 | Lobby - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19391 | ACTIVE | N | N093-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Mornington Crescent Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal, Fibreglass Lagging above Supalux Tiles | | | | YES | |
| 20156 | ACTIVE | N | N093-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Mornington Crescent Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 19390 | ACTIVE | N | N093-00-1/236/FLR-01 | Floor - 1 - Lobby - Station Building - Mornington Crescent Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Wooden False Floor | | | | | YES |
| 9723 | ACTIVE | N | N093-00-1/341 | Mess Room - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9724 | ACTIVE | N | N093-00-1/401 | Bin Store - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19393 | ACTIVE | N | N093-00-1/401/CLG-01 | Ceiling: Solid - 1 - Bin Store - Station Building - Mornington Crescent Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above Plasterboard | | | | YES | |
| 19392 | ACTIVE | N | N093-00-1/401/CLG-01 | Ceiling: Solid - 1 - Bin Store - Station Building - Mornington Crescent Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 9725 | ACTIVE | N | N093-00-1/406 | Store - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20157 | ACTIVE | N | N093-00-1/406 | Store - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9726 | ACTIVE | N | N093-00-1/451 | Tenancy - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19394 | ACTIVE | N | N093-00-1/451 | Tenancy - Station Building - Mornington Crescent Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Tenancy | | | | | |
| 19395 | ACTIVE | N | N093-00-1/451/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - Mornington Crescent Stn | Void | Asbestos | Surveyed – Not Detected | | | | Roof: Bitumen - Non Asbestos | | | | YES | |
| 9727 | ACTIVE | N | N093-00-1/551 | Yard - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19604 | ACTIVE | N | N093-00-1/551 | Yard - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 46455 | ACTIVE | N | N093-00-1/551 | Yard - Station Building - Mornington Crescent Stn | | Asbestos | Sampled – Not Detected | | | | Composite roofing felt to top of roof in External area adjacent to Stairs S/576 and Forecourt 1/551 | | | R634001 | N | N |



Hazardous Material Asset Register - Summary



N093-00 - Station Building - Mornington Crescent Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 46456 | ACTIVE | N | N093-00-1/551 | Yard - Station Building - Mornington Crescent Stn | | Asbestos | Sampled – Not Detected | | | | Guttering to fascia timber board in External area adjacent to Stairs S/ 576 and Forecourt 1/551 | 6 | | R634001 | N | N |
| 46458 | ACTIVE | N | N093-00-1/551 | Yard - Station Building - Mornington Crescent Stn | | Asbestos | Sampled – Not Detected | | | | Composite strip above guttering and under roof in External area adjacent to Stairs S/576 and Forecourt 1/551 | 6 | | R634001 | N | N |
| 46457 | ACTIVE | N | N093-00-1/551 | Yard - Station Building - Mornington Crescent Stn | | Asbestos | Sampled – Not Detected | | | | Mastic/sealant to joints of guttering in External area adjacent to Stairs S/576 and Forecourt 1/551 | 6 | | R634001 | N | N |
| 9728 | ACTIVE | N | N093-00-1/576 | Stairs: Linear - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19396 | ACTIVE | N | N093-00-1/576 | Stairs: Linear - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9729 | ACTIVE | N | N093-00-1/631 | Stairs: Spiral - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20158 | ACTIVE | N | N093-00-1/631 | Stairs: Spiral - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9730 | ACTIVE | N | N093-00-1/746 | Stairs: Linear - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19397 | ACTIVE | N | N093-00-1/746 | Stairs: Linear - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9731 | ACTIVE | N | N093-00-1/751 | Station Control Room - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20159 | ACTIVE | N | N093-00-1/751/ CLG-01 | Ceiling: Suspended - 1 - Station Control Room - Station Building - Mornington Crescent Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 19817 | ACTIVE | N | N093-00-1/751/ CLG-01 | Ceiling: Suspended - 1 - Station Control Room - Station Building - Mornington Crescent Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal, Fibreglass Lagging above Supalux Tiles | | | | YES | |
| 19398 | ACTIVE | N | N093-00-1/751/ FLR-01 | Floor - 1 - Station Control Room - Station Building - Mornington Crescent Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |
| 9732 | ACTIVE | N | N093-00-2/053 | Locker Room - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19399 | ACTIVE | N | N093-00-2/053 | Locker Room - Station Building - Mornington Crescent Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater Insulation Board Foam | | | | | |
| 19605 | ACTIVE | N | N093-00-2/053/ CLG-01 | Ceiling: Suspended - 1 - Locker Room - Station Building - Mornington Crescent Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |



Hazardous Material Asset Register - Summary



N093-00 - Station Building - Mornington Crescent Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 19400 | ACTIVE | N | N093-00-2/053/CLG-01 | Ceiling: Suspended - 1 - Locker Room - Station Building - Mornington Crescent Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Metal above Supalux Tiles | | | | YES | |
| 9733 | ACTIVE | N | N093-00-2/081 | Lobby - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19401 | ACTIVE | N | N093-00-2/081 | Lobby - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9734 | ACTIVE | N | N093-00-2/201 | Passage - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19402 | ACTIVE | N | N093-00-2/201 | Passage - Station Building - Mornington Crescent Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard Panel, Supalux Boxing | | | | | |
| 9735 | ACTIVE | N | N093-00-2/236 | Passage - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20160 | ACTIVE | N | N093-00-2/236 | Passage - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9736 | ACTIVE | N | N093-00-2/281 | Locker Room - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19403 | ACTIVE | N | N093-00-2/281 | Locker Room - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9737 | ACTIVE | N | N093-00-2/406 | Store - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19404 | ACTIVE | N | N093-00-2/406 | Store - Station Building - Mornington Crescent Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 9738 | ACTIVE | N | N093-00-2/411 | Store - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19405 | ACTIVE | N | N093-00-2/411 | Store - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9739 | ACTIVE | N | N093-00-2/412 | Fan Room - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20161 | ACTIVE | N | N093-00-2/412 | Fan Room - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9740 | ACTIVE | N | N093-00-2/416 | Toilet: Unisex - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N093-00 - Station Building - Mornington Crescent Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 19406 | ACTIVE | N | N093-00-2/416/FLR-01 | Floor - 1 - Toilet - Station Building - Mornington Crescent Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Lino | | | | | |
| 19407 | ACTIVE | N | N093-00-2/416/FLR-01 | Floor - 1 - Toilet - Station Building - Mornington Crescent Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 20162 | ACTIVE | N | N093-00-2/416/FLR-01 | Floor - 1 - Toilet - Station Building - Mornington Crescent Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal above Supalux Tiles | | | | | YES |
| 9741 | ACTIVE | N | N093-00-2/631 | Stairs: Spiral - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19408 | ACTIVE | N | N093-00-2/631 | Stairs: Spiral - Station Building - Mornington Crescent Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel ring caulking throughout - Non asbestos | | | | | |
| 9742 | ACTIVE | N | N093-00-2/632 | Stairs: Spiral - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19451 | ACTIVE | N | N093-00-2/632 | Stairs: Spiral - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | Roof - no asbestos detected | | | | | |
| 19409 | ACTIVE | N | N093-00-2/632 | Stairs: Spiral - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | Roof - no asbestos detected | | | | | |
| 9743 | ACTIVE | N | N093-00-2/661 | Switch Room - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19452 | ACTIVE | N | N093-00-2/661 | Switch Room - Station Building - Mornington Crescent Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 1 x 20mm Cable to Intake Electric Board - poor condition | | 1 | | N | N |
| 20163 | ACTIVE | N | N093-00-2/661 | Switch Room - Station Building - Mornington Crescent Stn | Lead/Leading | Lead Paint/Lead | Strongly Presumed | | | | White & Black Lead Paint to Girder above Door - white painted over with black | | | | N | N |
| 9744 | ACTIVE | N | N093-00-2/662 | Switch Room - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19453 | ACTIVE | N | N093-00-2/662 | Switch Room - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9745 | ACTIVE | N | N093-00-2/663 | Switch Room - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19454 | ACTIVE | N | N093-00-2/663 | Switch Room - Station Building - Mornington Crescent Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 9746 | ACTIVE | N | N093-00-2/731 | Switch Room - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N093-00 - Station Building - Mornington Crescent Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 19455 | ACTIVE | N | N093-00-2/731/FLR-01 | Floor - 1 - Switch Room - Station Building - Mornington Crescent Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Wooden False Floor | | | | | YES |
| 9747 | ACTIVE | N | N093-00-2/746 | SCR - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20164 | ACTIVE | N | N093-00-2/746 | SCR - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9748 | ACTIVE | N | N093-00-2/786 | Service Riser - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19419 | ACTIVE | N | N093-00-2/786 | Service Riser - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9749 | ACTIVE | N | N093-00-2/801 | Disused - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20165 | ACTIVE | N | N093-00-2/801 | Disused - Station Building - Mornington Crescent Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 19456 | ACTIVE | N | N093-00-2/801/CLG-01 | Ceiling: Solid - 1 - Office - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | Artex - Non Asbestos | | | | | |
| 9750 | ACTIVE | N | N093-00-2/802 | Disused - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19457 | ACTIVE | N | N093-00-2/802 | Disused - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9751 | ACTIVE | N | N093-00-2/991 | Store - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19458 | ACTIVE | N | N093-00-2/991 | Store - Station Building - Mornington Crescent Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 9752 | ACTIVE | N | N093-00-2/992 | Lobby - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19459 | ACTIVE | N | N093-00-2/992 | Lobby - Station Building - Mornington Crescent Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | New Vermiculite Boxing/Cladding and Supalux Boarding | | | | | |
| 9753 | ACTIVE | N | N093-00-2/993 | Store - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20166 | ACTIVE | N | N093-00-2/993 | Store - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N093-00 - Station Building - Mornington Crescent Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9754 | ACTIVE | N | N093-00-3/081 | Lobby - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19606 | ACTIVE | N | N093-00-3/081 | Lobby - Station Building - Mornington Crescent Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Boarding around door | | | | | |
| 9755 | ACTIVE | N | N093-00-3/731 | CER - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19461 | ACTIVE | N | N093-00-3/731 | CER - Station Building - Mornington Crescent Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 19460 | ACTIVE | N | N093-00-3/731/FLR-01 | Floor - 1 - CER - Station Building - Mornington Crescent Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Wooden False Floor | | | | | YES |
| 9756 | ACTIVE | N | N093-00-3/786 | Service Riser - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19380 | ACTIVE | N | N093-00-3/786 | Service Riser - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9757 | ACTIVE | N | N093-00-4/081 | Lobby - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20167 | ACTIVE | N | N093-00-4/081/FLR-01 | Floor - 1 - Lobby - Station Building - Mornington Crescent Stn | Void | Asbestos | Surveyed – Not Detected | | | | 3 x Clay Ducts, PVC Cables beneath Wooden False Floor | | | | | YES |
| 9758 | ACTIVE | N | N093-00-4/201 | Passage - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19462 | ACTIVE | N | N093-00-4/201 | Passage - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9759 | ACTIVE | N | N093-00-4/202 | Passage - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19463 | ACTIVE | N | N093-00-4/202/FLR-01 | Floor - 1 - Passage - Station Building - Mornington Crescent Stn | Void | Asbestos | Surveyed – Not Detected | | | | Clay Ducts beneath Tiles | | | | | YES |
| 9760 | ACTIVE | N | N093-00-4/203 | Passage - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19464 | ACTIVE | N | N093-00-4/203 | Passage - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9761 | ACTIVE | N | N093-00-4/204 | Passage - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N093-00 - Station Building - Mornington Crescent Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 19465 | ACTIVE | N | N093-00-4/204/FLR-01 | Floor - 1 - Passage - Station Building - Mornington Crescent Stn | Void | Asbestos | Surveyed – Not Detected | | | | Clay Ducts beneath Tiles | | | | | YES |
| 9762 | ACTIVE | N | N093-00-4/205 | Passage - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19607 | ACTIVE | N | N093-00-4/205 | Passage - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9763 | ACTIVE | N | N093-00-4/206 | Passage - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19466 | ACTIVE | N | N093-00-4/206/FLR-01 | Floor - 1 - Passage - Station Building - Mornington Crescent Stn | Void | Asbestos | Surveyed – Not Detected | | | | Clay Ducts beneath Tiles | | | | | YES |
| 9764 | ACTIVE | N | N093-00-4/207 | Passage - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19467 | ACTIVE | N | N093-00-4/207 | Passage - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 20168 | ACTIVE | N | N093-00-4/207 | Passage - Station Building - Mornington Crescent Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Overbridge Panels: Cream Gloss Paint contains lead levels greater than 1% | | | | N | N |
| 9765 | ACTIVE | N | N093-00-4/601 | Stairs: Linear - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19468 | ACTIVE | N | N093-00-4/601 | Stairs: Linear - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9766 | ACTIVE | N | N093-00-4/602 | Stairs: Linear - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19469 | ACTIVE | N | N093-00-4/602/FLR-01 | Floor - 1 - Station Building - Mornington Crescent Stn | Void | Asbestos | Surveyed – Not Detected | | | | Cement & Bitumen Ducts - Non Asbestos | | | | | YES |
| 9767 | ACTIVE | N | N093-00-4/661 | CER - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20169 | ACTIVE | N | N093-00-4/661 | CER - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9768 | ACTIVE | N | N093-00-4/731 | CER - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19470 | ACTIVE | N | N093-00-4/731 | CER - Station Building - Mornington Crescent Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard Boxing | | | | | |
| 19239 | ACTIVE | N | N093-00-4/787 | Vent Shaft - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N093-00 - Station Building - Mornington Crescent Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 9769 | ACTIVE | N | N093-00-4/791 | Air Plenum - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19472 | ACTIVE | N | N093-00-4/791 | Air Plenum - Station Building - Mornington Crescent Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access area sealed off | | | | | |
| 19473 | ACTIVE | N | N093-00-4/901 | Vent Shaft - Station Building - Mornington Crescent Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Cord Beams | | | | | |
| 19818 | ACTIVE | N | N093-00-4/901 | Vent Shaft - Station Building - Mornington Crescent Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board Boxing | | | | | |
| 19169 | ACTIVE | N | N093-00-4/901/FLR-01 | Floor - 1 - Vent Shaft - Station Building - Mornington Crescent Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal; Solid, Concrete | | | | | YES |
| 9770 | ACTIVE | N | N093-00-5/201 | Passage - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19474 | ACTIVE | N | N093-00-5/201 | Passage - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9771 | ACTIVE | N | N093-00-5/202 | Passage - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19475 | ACTIVE | N | N093-00-5/202 | Passage - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9772 | ACTIVE | N | N093-00-5/203 | Passage - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19476 | ACTIVE | N | N093-00-5/203 | Passage - Station Building - Mornington Crescent Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard Boxing | | | | | |
| 19608 | ACTIVE | N | N093-00-5/203/FLR-01 | Floor - 1 - Passage - Station Building - Mornington Crescent Stn | Void | Asbestos | Surveyed – Not Detected | | | | Clay Ducts beneath Tiles | | | | | YES |
| 9773 | ACTIVE | N | N093-00-5/204 | Passage - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19321 | ACTIVE | N | N093-00-5/204 | Passage - Station Building - Mornington Crescent Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard Boxing | | | | | |
| 9774 | ACTIVE | N | N093-00-5/261 | Platform 1 - Northbound Local - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19477 | ACTIVE | N | N093-00-5/261 | Platform 1 - Northbound Local - Station Building - Mornington Crescent Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel inside Auto Phone & Tunnel Phone Panel | | | | | |



Hazardous Material Asset Register - Summary



N093-00 - Station Building - Mornington Crescent Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|--------------------------------------|--|----------------------|---------------|------------------------|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 70863 | ACTIVE | N | N093-00-5/261 | Platform 1 - Northbound Local - Station Building - Mornington Crescent Stn | Debris: Other | Asbestos | Sampled – Not Detected | | | | Platform Invert - MMMF insulation loose - Throughout | | | R728775 | N | Y |
| 70860 | ACTIVE | N | N093-00-5/261 | Platform 1 - Northbound Local - Station Building - Mornington Crescent Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 3 no - Platform wall | | 3 | R728775 | N | Y |
| 70861 | ACTIVE | N | N093-00-5/261 | Platform 1 - Northbound Local - Station Building - Mornington Crescent Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - Throughout - To J Hanger | | | R728775 | | |
| 70857 | ACTIVE | N | N093-00-5/261 | Platform 1 - Northbound Local - Station Building - Mornington Crescent Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728775 | | |
| 70858 | ACTIVE | N | N093-00-5/261 | Platform 1 - Northbound Local - Station Building - Mornington Crescent Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728775 | | |
| 70859 | ACTIVE | N | N093-00-5/261 | Platform 1 - Northbound Local - Station Building - Mornington Crescent Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts -total 3 no - To trackside wall, departure end | | 3 | R728775 | N | Y |
| 70864 | ACTIVE | N | N093-00-5/261 | Platform 1 - Northbound Local - Station Building - Mornington Crescent Stn | Debris: Other | Asbestos | Sampled – Not Detected | | | | Platform Invert - MMMF cable wrapping - To cables throughout | | | R728775 | N | Y |
| 70865 | ACTIVE | N | N093-00-5/261 | Platform 1 - Northbound Local - Station Building - Mornington Crescent Stn | Gasket :Pipework | Asbestos | Presumed | | | | Platform Invert - Gaskets - Throughout - To metal pipework flanges | | | R728775 | N | Y |
| 70866 | ACTIVE | N | N093-00-5/261 | Platform 1 - Northbound Local - Station Building - Mornington Crescent Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 2 no - To trackside wall, arrivals end | | 2 | R728775 | N | Y |
| 70867 | ACTIVE | N | N093-00-5/261 | Platform 1 - Northbound Local - Station Building - Mornington Crescent Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 no - To trackside wall, arrivals end | | 2 | R728775 | N | Y |
| 70868 | ACTIVE | N | N093-00-5/261 | Platform 1 - Northbound Local - Station Building - Mornington Crescent Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 4 no - To ceiling, arrivals end | | 4 | R728775 | N | Y |
| 70869 | ACTIVE | N | N093-00-5/261 | Platform 1 - Northbound Local - Station Building - Mornington Crescent Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts- total 2 no - To ceiling, arrivals end | | 2 | R728775 | N | Y |
| 70862 | ACTIVE | N | N093-00-5/261 | Platform 1 - Northbound Local - Station Building - Mornington Crescent Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Materials within medium Westinghouse box - total 1 no - | | 1 | R728775 | | |
| 19819 | ACTIVE | N | N093-00-5/261/ FLR-01 80907629 | Floor - 1 - Platform 1 - Station Building - Mornington Crescent Stn Floor | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 1 Invert - Cables No access within invert 2024 re-inspection as confined space team required. | | 6 | | | YES |
| 19515 | ACTIVE | N | N093-00-5/261/ FLR-01 80907629 | Floor - 1 - Platform 1 - Station Building - Mornington Crescent Stn Floor | Cable Ducts: Cement | Asbestos | Known | | | | Platform 1 Invert - Cable Sleeves - Chrysotile No access within invert 2024 re-inspection as confined space team required. | | 4 | | | YES |



Hazardous Material Asset Register - Summary



N093-00 - Station Building - Mornington Crescent Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|--------------------------------|--|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9775 | ACTIVE | N | N093-00-5/262 | Platform 2 - Southbound Local - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19516 | ACTIVE | N | N093-00-5/262 | Platform 2 - Southbound Local - Station Building - Mornington Crescent Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel inside Auto Phone & Tunnel Phone Panel | | | | | |
| 70855 | ACTIVE | N | N093-00-5/262 | Platform 2 - Southbound Local - Station Building - Mornington Crescent Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - Throughout - To J Hanger | | | R728775 | | |
| 70851 | ACTIVE | N | N093-00-5/262 | Platform 2 - Southbound Local - Station Building - Mornington Crescent Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728775 | | |
| 70852 | ACTIVE | N | N093-00-5/262 | Platform 2 - Southbound Local - Station Building - Mornington Crescent Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable duct - total 1 no - To trackside wall, arrivals end | | 1 | R728775 | N | Y |
| 70856 | ACTIVE | N | N093-00-5/262 | Platform 2 - Southbound Local - Station Building - Mornington Crescent Stn | Gasket :Pipework | Asbestos | Presumed | | | | Platform Invert - Gaskets - Throughout - To metal pipework flanges | | | R728775 | N | Y |
| 70849 | ACTIVE | N | N093-00-5/262 | Platform 2 - Southbound Local - Station Building - Mornington Crescent Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Materials within link boxes - total 2 no - To trackside wall | | 2 | R728775 | | |
| 70850 | ACTIVE | N | N093-00-5/262 | Platform 2 - Southbound Local - Station Building - Mornington Crescent Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728775 | | |
| 70848 | ACTIVE | N | N093-00-5/262 | Platform 2 - Southbound Local - Station Building - Mornington Crescent Stn | Debris: Other | Asbestos | Sampled – Not Detected | | | | Platform Invert - MMMF loose - Throughout | | | R728775 | N | Y |
| 19517 | ACTIVE | N | N093-00-5/262/ FLR-01 80907644 | Floor - 1 - Platform 2 - Station Building - Mornington Crescent Stn Floor | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 2 Invert - 1 x Brown Cable No access within invert 2024 re-inspection as confined space team required. | | | | N | YES |
| 9776 | ACTIVE | N | N093-00-5/661 | Switch Room - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19518 | ACTIVE | N | N093-00-5/661 | Switch Room - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9777 | ACTIVE | N | N093-00-5/662 | Switch Room - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19170 | ACTIVE | N | N093-00-5/662 | Switch Room - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9778 | ACTIVE | N | N093-00-5/711 | IMR - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N093-00 - Station Building - Mornington Crescent Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------------------------|---|------------------------|--------------------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 19519 | ACTIVE | N | N093-00-5/711 80143136 | IMR - Station Building - Mornington Crescent Stn Room Assets | Cable: Sheath | Asbestos | Known | | | | 20mm woven sheath to pipework - confirmed ACM - R710926 | | 1 | | N | N |
| 44167 | ACTIVE | N | N093-00-5/711 | IMR - Station Building - Mornington Crescent Stn | Other Boarding | Asbestos | Sampled – Not Detected | | | | 4 x Paxoline boarding to wall 3 - ID confirmed non asbestos 4RS- JP-211347-R710926 | | | | | |
| 42330 | INACTIVE | N | N093-00-5/711 80143136 | IMR - Station Building - Mornington Crescent Stn Room Assets | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | 1 x 1 x medium silver cylinder PCB wall 3 up high | | 1 | | N | N |
| 53625 | ACTIVE | N | N093-00-5/711/ WAL-003 80907606 | Wall: Internal - 3 - IMR - Station Building - Mornington Crescent Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | Materials within transformers x2 to wall 3 | | | | | |
| 53624 | ACTIVE | N | N093-00-5/711/ WAL-003 80907606 | Wall: Internal - 3 - IMR - Station Building - Mornington Crescent Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | Materials within rectifiers x2 to wall 3 - x1 now removed | | 1 | | | |
| 9779 | ACTIVE | N | N093-00-5/712 | Relay Room - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42153 | ACTIVE | N | N093-00-5/712 | Relay Room - Station Building - Mornington Crescent Stn | Cable Ducts: Cement | Asbestos | Presumed | | | | Concrete ducts filled in - No access. Presumed asbestos ducts below | | | | N | |
| 19609 | ACTIVE | N | N093-00-5/712 | Relay Room - Station Building - Mornington Crescent Stn | Cable Duct: Other | Asbestos | Presumed | | | | Ducts behind Shutters | | | | N | N |
| 19520 | ACTIVE | N | N093-00-5/712 | Relay Room - Station Building - Mornington Crescent Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 50mm Cable | | 2 | | | |
| 44166 | ACTIVE | N | N093-00-5/712 | Relay Room - Station Building - Mornington Crescent Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline various behind roller shutter | | | | N | N |
| 42329 | INACTIVE | N | N093-00-5/712 | Relay Room - Station Building - Mornington Crescent Stn | PCBs | Polychlorinated biphenyl | Presumed | | | | 1 x medium silver cylinder PCB | | 1 | | N | N |
| 25693 | INACTIVE | N | N093-00-5/712/ WAL-001 80908298 | Wall: Internal - 1 - Relay Room - Station Building - Mornington Crescent Stn Wall: Internal | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | Approx 5 x PCB's - fair condition black boxes | | 5 | | N | N |
| 9780 | ACTIVE | N | N093-00-5/771 | Pump Room - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19521 | ACTIVE | N | N093-00-5/771 | Pump Room - Station Building - Mornington Crescent Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 9781 | ACTIVE | N | N093-00-A/082 | Lobby - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19171 | ACTIVE | N | N093-00-A/082 | Lobby - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9782 | ACTIVE | N | N093-00-A/131 | LMR - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N093-00 - Station Building - Mornington Crescent Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------------------------|---|------------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 19523 | ACTIVE | N | N093-00-A/131 | LMR - Station Building - Mornington Crescent Stn | Lead/Leading | Lead Paint/Lead | Strongly Presumed | | | | Lead paint to Girders | | | | | |
| 19522 | ACTIVE | N | N093-00-A/131/ WAL-001 80907658 | Wall: Internal - 1 - LMR - Station Building - Mornington Crescent Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 300amp Switch Box - Strongly presumed materials within | | 1 | | N | N |
| 25694 | ACTIVE | N | N093-00-A/131/ WAL-001 80907658 | Wall: Internal - 1 - LMR - Station Building - Mornington Crescent Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | 1 x Transformer Box - Presumed materials within | | 1 | | | |
| 9783 | ACTIVE | N | N093-00-A/351 | Mess Room - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19524 | ACTIVE | N | N093-00-A/351 | Mess Room - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 19172 | ACTIVE | N | N093-00-A/351 | Mess Room - Station Building - Mornington Crescent Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 9784 | ACTIVE | N | N093-00-A/416 | Toilet: Unisex - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19525 | ACTIVE | N | N093-00-A/416 | Toilet: Unisex - Station Building - Mornington Crescent Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 9785 | ACTIVE | N | N093-00-A/576 | Stairs: Linear - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 9786 | ACTIVE | N | N093-00-A/577 | Stairs: Linear - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9787 | ACTIVE | N | N093-00-A/781 | Transformer Room - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19526 | ACTIVE | N | N093-00-A/781 | Transformer Room - Station Building - Mornington Crescent Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access Note this room is Alamed | | | | | |
| 9788 | ACTIVE | N | N093-00-A/801 | Disused - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19240 | ACTIVE | N | N093-00-A/801 | Disused - Station Building - Mornington Crescent Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 19173 | ACTIVE | N | N093-00-A/801/ FLR-01 | Floor - 1 - Office - Station Building - Mornington Crescent Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Lino | | | | | |
| 9789 | ACTIVE | N | N093-00-A/803 | Office - Station Building - Mornington Crescent Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N093-00 - Station Building - Mornington Crescent Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|----------------|---------------|-------------------------|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 19527 | ACTIVE | N | N093-00-A/803 | Office - Station Building - Mornington Crescent Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 19338 | ACTIVE | N | N093-00/ROF-01 | Structure: Roof - 1 - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No glazing panels or rope seal; Roof felt - All New | | | | | |
| 19339 | ACTIVE | N | N093-00/ROF-02 | Structure: Roof - 2 - Station Building - Mornington Crescent Stn | | Asbestos | Surveyed – Not Detected | | | | No glazing panels or rope seal; Roof felt - All New | | | | | |

N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9790 | ACTIVE | N | N095-00-2/001 | Booking Hall - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 69690 | ACTIVE | N | N095-00-2/001 | Booking Hall - Station Building - Euston Stn | | Asbestos | Sampled – Not Detected | | | | Insulation board to the back of some ceiling tiles (tiles containing round lights and speakers) | | | R700888Rev3 | | |
| 69687 | ACTIVE | N | N095-00-2/001 | Booking Hall - Station Building - Euston Stn | Other Boarding | Asbestos | Sampled – Not Detected | | | | Insulation board throughout to false ceiling perimeter & to fire stop intake ceiling void by entrance to ticket hall. | 12 | | R700888Rev3 | | |
| 69686 | ACTIVE | N | N095-00-2/001 | Booking Hall - Station Building - Euston Stn | Bitumen | Asbestos | Sampled – Not Detected | | | | Bitumen paint throughout to metal beams and girders >100 | 100 | | R700888Rev3 | | |
| 15257 | ACTIVE | N | N095-00-2/001/CLG-01 | Ceiling: Suspended - 1 - Booking Hall - Station Building - Euston Stn | Void | Asbestos | Surveyed – Not Detected | | | | Insulated Plastic Cables; Fire Break Panel; Concrete | | | | YES | |
| 9791 | ACTIVE | N | N095-00-2/011 | Ticket Office - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18016 | ACTIVE | N | N095-00-2/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Euston Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Fibreglass Lagging above Acoustic Panel | | | | YES | |
| 15258 | ACTIVE | N | N095-00-2/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Beneath False Wooden Floor No access beneath fixed raised floor during 2020 re-inspection. | | | | | YES |
| 9792 | ACTIVE | N | N095-00-2/021 | POM - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15260 | ACTIVE | N | N095-00-2/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Euston Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Metal Vent Ducts above Acoustic Panel | | | | YES | |
| 15259 | ACTIVE | N | N095-00-2/021/FLR-01 | Floor - 1 - POM - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | No Access below Computer Flooring Tiles. | | | | | YES |



Hazardous Material Asset Register - Summary



| N095-00 - Station Building - Euston Stn | | | | | | | | | | | | | | | | |
|---|----------|-------------|----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
| 9793 | ACTIVE | N | N095-00-2/031 | Mess Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15261 | ACTIVE | N | N095-00-2/031 | Mess Room - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 15262 | ACTIVE | N | N095-00-2/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Euston Stn | Void | Asbestos | Surveyed – Not Detected | | | | Fibreglass Lagging above Acoustic Panel | | | | YES | |
| 9794 | ACTIVE | N | N095-00-2/036 | Toilet: Unisex - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15263 | ACTIVE | N | N095-00-2/036/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Acoustic Panel No access above acoustic panel during 2020 re-inspection. | | | | | |
| 9795 | ACTIVE | N | N095-00-2/037 | Lobby - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18017 | ACTIVE | N | N095-00-2/037/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Acoustic Panel No access above acoustic panel during 2020 re-inspection. | | | | | |
| 9796 | ACTIVE | N | N095-00-2/071 | Circulation Area - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15264 | ACTIVE | N | N095-00-2/071/CLG-01 | Ceiling: Suspended - 1 - Circulation Area - Station Building - Euston Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above Metal Ceiling - Insulated Plastic Cables; Fire Break Panel - Non Asbestos | | | | YES | |
| 9797 | ACTIVE | N | N095-00-2/151 | UMC - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15268 | ACTIVE | N | N095-00-2/151 | UMC - Station Building - Euston Stn | Cable Duct: Other | Asbestos | Known | | | | Mastic to Flanges within AC Duct in UMC Active - ductwork with mastic to joints is present in 2020 re-inspection | | | | | |
| 15269 | ACTIVE | N | N095-00-2/151 | UMC - Station Building - Euston Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Various Electrical Boxes | | | | | |
| 45001 | INACTIVE | N | N095-00-2/151 | UMC - Station Building - Euston Stn | Rope Gaskets | Asbestos | Strongly Presumed | | | | Gasket to Ventilation Fan | | | | N | N |
| 15270 | ACTIVE | N | N095-00-2/151 | UMC - Station Building - Euston Stn | Westing house Boxes | Asbestos | Removed | | | | Insulation within - 3no Westinghouse Boxes by Access B Removed by others - confirmed 26/06/2014 | | 3 | | | |
| 18559 | ACTIVE | N | N095-00-2/151 | UMC - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Various Cables - SP | | | | | |



Hazardous Material Asset Register - Summary



| N095-00 - Station Building - Euston Stn | | | | | | | | | | | | | | | | |
|---|----------|-------------|----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
| 15265 | ACTIVE | N | N095-00-2/151 | UMC - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Known Asbestos - Caulking in Tunnel Ring Joints and Flanges throughout inclines No access into inclines during 2020 re-inspection - permit required with L&E. | | | | | |
| 20264 | ACTIVE | N | N095-00-2/151 | UMC - Station Building - Euston Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Various Pump Controllers - Other Electrical Equipment | | | | | |
| 15267 | ACTIVE | N | N095-00-2/151 | UMC - Station Building - Euston Stn | Rope Gaskets | Asbestos | Known | | | | Rope Gaskets to Joints to Ventilation Equipment | | | | | |
| 44360 | ACTIVE | N | N095-00-2/151 | UMC - Station Building - Euston Stn | Gasket :Pipework | Asbestos | Presumed | | | | Gaskets to Bolted Joints on pipe work | | | | | |
| 18018 | ACTIVE | N | N095-00-2/151 | UMC - Station Building - Euston Stn | Mastic | Asbestos | Strongly Presumed | | | | Chrysotile Mastic to Flange to AC Duct in UMC | | | | | |
| 25858 | ACTIVE | N | N095-00-2/151 | UMC - Station Building - Euston Stn | Rope Seals | Asbestos | Surveyed – Not Detected | | | | New Gaiters to Fan Equipment - Non Asbestos | | | | | |
| 15266 | ACTIVE | N | N095-00-2/151/FLR-01 | Floor - 1 - UMC - Station Building - Euston Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes - Insulation within 2no 60amps on freestanding frame | | 2 | | | |
| 9798 | ACTIVE | N | N095-00-2/201 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | Room Surveyed - No asbestos Detected | | | | | |
| 15271 | INACTIVE | N | N095-00-2/201 | Passage - Station Building - Euston Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - No Access | | | | | |
| 9799 | ACTIVE | N | N095-00-2/202 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19295 | ACTIVE | N | N095-00-2/202/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Fire Break | | | | | |
| 9800 | ACTIVE | N | N095-00-2/203 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18560 | ACTIVE | N | N095-00-2/203 | Passage - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9801 | ACTIVE | N | N095-00-2/237 | Lobby - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15272 | ACTIVE | N | N095-00-2/237/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Acoustic Panel No access above acoustic panel during 2020 re-inspection | | | | | |
| 18019 | ACTIVE | N | N095-00-2/237/FLR-01 | Floor - 1 - Lobby - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Beneath - Computer Tiles No access beneath tiles fixed to floor during 2020 re-inspection | | | | | YES |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 9802 | ACTIVE | N | N095-00-2/238 | Lobby - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 15274 | ACTIVE | N | N095-00-2/238/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Euston Stn | Void | Asbestos | Surveyed – Not Detected | | | | Brick Wall; Fibreglass Lagging; Supalux Boxing; Concrete above Supalux Tiles | | | | YES | |
| 15273 | ACTIVE | N | N095-00-2/238/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9803 | ACTIVE | N | N095-00-2/239 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18581 | ACTIVE | N | N095-00-2/239 | Passage - Station Building - Euston Stn | No Access | Asbestos | Surveyed – Not Detected | | | | New Construction | | | | | |
| 9804 | ACTIVE | N | N095-00-2/301 | Tenancy - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15275 | ACTIVE | N | N095-00-2/301 | Tenancy - Station Building - Euston Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - Foam Insulation Board | | | | | |
| 18020 | ACTIVE | N | N095-00-2/301/CLG-01 | Ceiling: Suspended - 1 - Tenancy - Station Building - Euston Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Brick Walls; Supalux Fire Break above Plasterboard | | | | YES | |
| 15276 | ACTIVE | N | N095-00-2/301/CLG-01 | Ceiling: Suspended - 1 - Tenancy - Station Building - Euston Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 9805 | ACTIVE | N | N095-00-2/306 | Station Supervisor Office - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15277 | ACTIVE | N | N095-00-2/306/CLG-01 | Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Euston Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Supalux Fire Break above Acoustic Panel | | | | YES | |
| 9806 | ACTIVE | N | N095-00-2/311 | Office - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15278 | ACTIVE | N | N095-00-2/311/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Acoustic Panel No access above acoustic panel during 2020 re-inspection | | | | | |
| 9807 | ACTIVE | N | N095-00-2/331 | Mess Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15279 | ACTIVE | N | N095-00-2/331 | Mess Room - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 15280 | ACTIVE | N | N095-00-2/331 | Mess Room - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18624 | ACTIVE | N | N095-00-2/331/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Euston Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Fibreglass Supalux above Supalux Tiles | | | | YES | |
| 15281 | ACTIVE | N | N095-00-2/331/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9808 | ACTIVE | N | N095-00-2/366 | Mess Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18021 | ACTIVE | N | N095-00-2/366 | Mess Room - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 15282 | ACTIVE | N | N095-00-2/366 | Mess Room - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 15283 | ACTIVE | N | N095-00-2/366/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | | | | | | |
| 15284 | ACTIVE | N | N095-00-2/366/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Boarding No access above supalux ceiling during 2020 re-inspection | | | | | |
| 9809 | ACTIVE | N | N095-00-2/371 | Switch Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18022 | ACTIVE | N | N095-00-2/371 | Switch Room - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | | | | | | |
| 9810 | ACTIVE | N | N095-00-2/406 | Locker Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15285 | ACTIVE | N | N095-00-2/406 | Locker Room - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 9811 | ACTIVE | N | N095-00-2/411 | Locker Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18169 | ACTIVE | N | N095-00-2/411 | Locker Room - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 15286 | ACTIVE | N | N095-00-2/411/CLG-01 | Ceiling: Suspended - 1 - Locker Room - Station Building - Euston Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Brick Walls above False Ceiling | | | | YES | |
| 9812 | ACTIVE | N | N095-00-2/416 | Toilet: Male - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15287 | ACTIVE | N | N095-00-2/416/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18476 | ACTIVE | N | N095-00-2/416/CLG-02 | Ceiling: Suspended - 2 - Toilet - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Tiles No access above fixed supalux tiles during 2020 re-inspection. | | | | | |
| 9813 | ACTIVE | N | N095-00-2/417 | Toilet: Female - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15288 | ACTIVE | N | N095-00-2/417/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Euston Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above Supalux Tiles - Concrete; Brick Wall; Fibreglass Lagging; Metal Vent Ducts | | | | YES | |
| 18023 | ACTIVE | N | N095-00-2/417/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9814 | ACTIVE | N | N095-00-2/418 | Lobby - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15289 | ACTIVE | N | N095-00-2/418/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18625 | ACTIVE | N | N095-00-2/418/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Tiles No access above fixed supalux tiles during 2020 re-inspection. | | | | | |
| 9815 | ACTIVE | N | N095-00-2/419 | Lobby - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15291 | ACTIVE | N | N095-00-2/419/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Euston Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above Supalux Tiles - Concrete; Brick Wall; Fibreglass Lagging; Metal Vent Ducts | | | | YES | |
| 15290 | ACTIVE | N | N095-00-2/419/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9816 | ACTIVE | N | N095-00-2/451 | Station Control Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18024 | ACTIVE | N | N095-00-2/451 | Station Control Room - Station Building - Euston Stn | No Access | Asbestos | Surveyed – Not Detected | | | | No Access - New Construction | | | | | |
| 9817 | ACTIVE | N | N095-00-2/452 | Lobby - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15292 | ACTIVE | N | N095-00-2/452 | Lobby - Station Building - Euston Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access No access during 2020 re-inspection - private property keys with station office. | | | | | |
| 9818 | ACTIVE | N | N095-00-2/453 | ATM - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15293 | ACTIVE | N | N095-00-2/453 | ATM - Station Building - Euston Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access ATM - Tenancy - Generally No Access | | | | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|--------------------------------|--|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9819 | ACTIVE | N | N095-00-2/454 | ATM - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15294 | ACTIVE | N | N095-00-2/454 | ATM - Station Building - Euston Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access ATM - Tenancy - Generally No Access | | | | | |
| 9820 | ACTIVE | N | N095-00-2/665 | Switch Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Surveyed – Asbestos Known | | | | | | | | | |
| 44364 | ACTIVE | N | N095-00-2/665 | Switch Room - Station Building - Euston Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline packing between electrical boxes | | | | | |
| 25857 | ACTIVE | N | N095-00-2/665 | Switch Room - Station Building - Euston Stn | Mastic | Asbestos | Presumed | | | | Mastic Material to Joint in AC Ventilation | | | | | |
| 18025 | ACTIVE | N | N095-00-2/665/FLR-01 | Floor - 1 - Switch Room - Station Building - Euston Stn | Vinyl tiles | Asbestos | Presumed | | | | Vinyl Tiles 2020 re-inspection - bitumen adhesive beneath tiles also presumed to contain chrysotile | | | | | |
| 25859 | ACTIVE | N | N095-00-2/665/FLR-01 | Floor - 1 - Switch Room - Station Building - Euston Stn | Cable Duct: Other | Asbestos | Presumed | | | | Various Cable Ducts - Sealed over; On Floor by Walls 1,2,4 ducts not visible beneath filling therefore materials not scored during 2020 re-inspection. | | | | | |
| 44363 | ACTIVE | N | N095-00-2/665/FLR-01 80900513 | Floor - 1 - Switch Room - Station Building - Euston Stn Floor | Cable: Sheath | Asbestos | Strongly Presumed | | | | 2no 50mm cables from UMC? to electrical boxes | | | | | |
| 15295 | ACTIVE | N | N095-00-2/665/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Euston Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes - Insulation within 3x 30amp, 1x 100amp, 1x 200amp | | 5 | | | |
| 15297 | ACTIVE | N | N095-00-2/665/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Euston Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box(es) - Insulation within | | 1 | | | |
| 15298 | INACTIVE | N | N095-00-2/665/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Euston Stn | Other Boarding | Asbestos | Removed | | | | Paxoline Board to Meter Not found on re-inspection 26/06/2014 - Removed by others? | | | | | |
| 44362 | INACTIVE | N | N095-00-2/665/WAL-001 80900508 | Wall: Internal - 1 - Switch Room - Station Building - Euston Stn Wall: Internal | Isolator Switches | Asbestos | Presumed | | | | 5no 3x 30amp, 1x 100 1x 200 | | | | | |
| 20260 | ACTIVE | N | N095-00-2/665/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Euston Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes - Insulation within 2x 100amp | | 2 | | | |
| 20263 | ACTIVE | N | N095-00-2/665/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Euston Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box(es) - Insulation within | | 1 | | | |
| 20262 | ACTIVE | N | N095-00-2/665/WAL-004 80900511 | Wall: Internal - 4 - Switch Room - Station Building - Euston Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box(es) - Insulation within | | 2 | | | |
| 15296 | ACTIVE | N | N095-00-2/665/WAL-004 | Wall: Internal - 4 - Switch Room - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing to Ventilation/Fan Equipment by Door | | | | | |
| 20261 | ACTIVE | N | N095-00-2/665/WAL-004 80900511 | Wall: Internal - 4 - Switch Room - Station Building - Euston Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes - Insulation within; 2no 100amps, 1no 30amps, 1no 200amps | | 4 | | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9821 | ACTIVE | N | N095-00-2/666 | Switch Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18626 | ACTIVE | N | N095-00-2/666 | Switch Room - Station Building - Euston Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes - Insulation within W4 3x60, 1x200; W2 2x 30amp; W3 5x60 2x200 | | 13 | | | |
| 25860 | ACTIVE | N | N095-00-2/666 | Switch Room - Station Building - Euston Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Boxes | | 6 | | | |
| 18170 | ACTIVE | N | N095-00-2/666 | Switch Room - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 9822 | ACTIVE | N | N095-00-2/667 | Switch Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15299 | ACTIVE | N | N095-00-2/667/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | | | | | | |
| 18026 | ACTIVE | N | N095-00-2/667/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Ceiling No access above supalux fixed ceiling during 2020 re-inspection. | | | | | |
| 9823 | ACTIVE | N | N095-00-2/668 | Switch Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15300 | ACTIVE | N | N095-00-2/668 | Switch Room - Station Building - Euston Stn | No Access | Asbestos | Surveyed – Not Detected | | | | New Construction | | | | | |
| 9824 | ACTIVE | N | N095-00-2/711 | Pump Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9825 | ACTIVE | N | N095-00-2/731 | CER - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15302 | ACTIVE | N | N095-00-2/731 | CER - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 9826 | ACTIVE | N | N095-00-2/746 | SCR - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15303 | ACTIVE | N | N095-00-2/746 | SCR - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 9827 | ACTIVE | N | N095-00-2/751 | Station Control Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18027 | ACTIVE | N | N095-00-2/751/CLG-01 | Ceiling: Suspended - 1 - Station Control Room - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Tiles No access above fixed supalux ceiling tiles during 2020 re-inspection. | | | | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18231 | ACTIVE | N | N095-00-2/751/CLG-01 | Ceiling: Suspended - 1 - Station Control Room - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 15304 | ACTIVE | N | N095-00-2/751/FLR-01 | Floor - 1 - Station Control Room - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Beneath False Wooden Floor No access below fixed raised floor during 2020 re-inspection. | | | | | YES |
| 9828 | ACTIVE | N | N095-00-2/761 | SVC - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15308 | ACTIVE | N | N095-00-2/761 | SVC - Station Building - Euston Stn | Cable: Wrap | Asbestos | Surveyed – Not Detected | | | | Bonzo Tape on Pipes Non Asbestos | | | | | |
| 15307 | ACTIVE | N | N095-00-2/761 | SVC - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing and Boarding on Wall. Bonzo Tape on Pipes Non Asbestos | | | | | |
| 15305 | ACTIVE | N | N095-00-2/761/FLR-01 | Floor - 1 - SVC - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Beneath False Wooden / Supalux Floor No access beneath raised floor during 2020 re-inspection. | | | | | YES |
| 15306 | ACTIVE | N | N095-00-2/761/FLR-01 | Floor - 1 - SVC - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | | | | | | |
| 9829 | ACTIVE | N | N095-00-2/762 | Disused Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18028 | ACTIVE | N | N095-00-2/762/CLG-01 | Ceiling: Solid - 1 - Disused Room - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels, Metal Beam | | | | | |
| 9830 | ACTIVE | N | N095-00-2/771 | Pump Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15309 | ACTIVE | N | N095-00-2/771 | Pump Room - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9831 | ACTIVE | N | N095-00-2/781 | Transformer Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15310 | ACTIVE | N | N095-00-2/781 | Transformer Room - Station Building - Euston Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access UK Power Network Asset | | | | | |
| 15311 | ACTIVE | N | N095-00-2/791 | Vent Shaft - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9832 | ACTIVE | N | N095-00-2/901 | Disused Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18627 | ACTIVE | N | N095-00-2/901 | Disused Room - Station Building - Euston Stn | No Access | Asbestos | Surveyed – Not Detected | | | | No Asbestos Detected, but no access to High Level Areas; | | | | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|---------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9833 | ACTIVE | N | N095-00-2/951 | Void - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15312 | ACTIVE | N | N095-00-2/951 | Void - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9834 | ACTIVE | N | N095-00-3/091 | Circulation Area - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18089 | ACTIVE | N | N095-00-3/091/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling No access above fixed metal false ceiling during 20202 re-inspection. | | | | | |
| 15313 | ACTIVE | N | N095-00-3/091/FLR-01 | Floor - 1 - Circulation Area - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Cable Sleeves - Chrysotile (Beneath circulating area facing opposite 3/202) No access into floor duct during 2020 re-inspection. Lifting equipment required. | | 4 | | | |
| 9835 | ACTIVE | N | N095-00-3/092 | Circulation Area - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15315 | ACTIVE | N | N095-00-3/092 | Circulation Area - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Tunnel Ring Caulking - Amphibole No access above fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 15314 | ACTIVE | N | N095-00-3/092/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling No access above fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 9836 | ACTIVE | N | N095-00-3/093 | Circulation Area - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15316 | ACTIVE | N | N095-00-3/093 | Circulation Area - Station Building - Euston Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking No access above fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 18582 | ACTIVE | N | N095-00-3/093/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling No access above fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 9837 | ACTIVE | N | N095-00-3/094 | Circulation Area - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 45002 | ACTIVE | N | N095-00-3/094 | Circulation Area - Station Building - Euston Stn | Caulking | Asbestos | Presumed | | | | Tunnel ring caulking presumed as no access was possible to sample tunnel rings | | | | N | N |
| 15317 | ACTIVE | N | N095-00-3/094/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling - Caulking / Cellactite SP Above | | | | | |
| 9838 | ACTIVE | N | N095-00-3/121 | Service Riser - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



| N095-00 - Station Building - Euston Stn | | | | | | | | | | | | | | | | |
|---|--------|-------------|----------------------|---|---------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
| 18628 | ACTIVE | N | N095-00-3/121 | Service Riser - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables No access into service riser during 2020 re-inspection. Confined space. | | 6 | | | |
| 9839 | ACTIVE | N | N095-00-3/122 | Service Riser - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15318 | ACTIVE | N | N095-00-3/122 | Service Riser - Station Building - Euston Stn | Mastic | Asbestos | Presumed | | | | Trunking to Ventilation Equipment - Mastic to Joints | | | | | |
| 18090 | ACTIVE | N | N095-00-3/122 | Service Riser - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables | | 3 | | | |
| 9840 | ACTIVE | N | N095-00-3/123 | Service Riser - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15319 | ACTIVE | N | N095-00-3/123 | Service Riser - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9841 | ACTIVE | N | N095-00-3/124 | Service Riser - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15320 | ACTIVE | N | N095-00-3/124 | Service Riser - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables | | 2 | | | |
| 18091 | ACTIVE | N | N095-00-3/124/FLR-01 | Floor - 1 - Service Riser - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Cable Sleeves - Chrysotile No access into service during 2020 re-inspection. Confined space. | | 22 | | | |
| 9842 | ACTIVE | N | N095-00-3/125 | Service Riser - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15321 | ACTIVE | N | N095-00-3/125 | Service Riser - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables No access into service riser during 2020 re-inspection. Confined space. | | 4 | | | |
| 19427 | ACTIVE | N | N095-00-3/125/FLR-01 | Floor - 1 - Service Riser - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Cable Sleeves - Chrysotile No access into service riser during 2020 re-inspection. Confined space. | | 10 | | | |
| 9843 | ACTIVE | N | N095-00-3/126 | Service Riser - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18629 | ACTIVE | N | N095-00-3/126 | Service Riser - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables | | 7 | | | |
| 15322 | ACTIVE | N | N095-00-3/126/FLR-01 | Floor - 1 - Service Riser - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Various Cable Sleeves - Chrysotile | | | | | |
| 9844 | ACTIVE | N | N095-00-3/151 | UMC - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



| N095-00 - Station Building - Euston Stn | | | | | | | | | | | | | | | | |
|---|----------|-------------|---------------------|-------------------------------------|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
| 18092 | ACTIVE | N | N095-00-3/151 | UMC - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Cable Sleeve - in Wall - Chrysotile | | | | | |
| 15323 | ACTIVE | N | N095-00-3/151 | UMC - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding | | | | | |
| 15325 | ACTIVE | N | N095-00-3/151 | UMC - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Various Asbestos Sheathed Cables | | 5 | | | |
| 25867 | ACTIVE | N | N095-00-3/151 | UMC - Station Building - Euston Stn | Mastic | Asbestos | Presumed | | | | Mastic to Ventilation Ducting | | | | | |
| 45003 | INACTIVE | N | N095-00-3/151 | UMC - Station Building - Euston Stn | | Asbestos | Strongly Presumed | | | | 5no Cables | | 5 | | N | N |
| 15324 | ACTIVE | N | N095-00-3/151 | UMC - Station Building - Euston Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking - UMC Access | | | | | |
| 9845 | ACTIVE | N | N095-00-3/152 | UMC - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15326 | ACTIVE | N | N095-00-3/152 | UMC - Station Building - Euston Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking | | | | | |
| 18232 | ACTIVE | N | N095-00-3/152 | UMC - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Various Cables (7no) | | 7 | | | |
| 25868 | ACTIVE | N | N095-00-3/152 | UMC - Station Building - Euston Stn | Mastic | Asbestos | Presumed | | | | Mastic to Joints in Ventilation Ducting | | | | | |
| 25869 | ACTIVE | N | N095-00-3/152 | UMC - Station Building - Euston Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box | | | | | |
| 9846 | ACTIVE | N | N095-00-3/161 | LMC - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15327 | ACTIVE | N | N095-00-3/161 | LMC - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Escalator incline surveyed. Suspect material was a board, tested and found to be Supalux | | | | | |
| 15329 | ACTIVE | N | N095-00-3/161 | LMC - Station Building - Euston Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Insulation within Small Electrical Box | | 1 | | | |
| 18093 | ACTIVE | N | N095-00-3/161 | LMC - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 50mm Cables | | 2 | | | |
| 15328 | ACTIVE | N | N095-00-3/161 | LMC - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Tunnel Ring Caulking. Access Areas Encapsulated | | | | | |
| 9847 | ACTIVE | N | N095-00-3/162 | LMC - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15330 | ACTIVE | N | N095-00-3/162 | LMC - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding | | | | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 44361 | ACTIVE | N | N095-00-3/162 | LMC - Station Building - Euston Stn | Gasket :Pipework | Asbestos | Not Found during Inspection | | | | Gaskets to pipework on pipework to pump equipment Pipework and gaskets not present in 2020 re-inspection. Possibly removed. | | 5 | | | |
| 18233 | ACTIVE | N | N095-00-3/162 | LMC - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Tunnel Ring Caulking | | | | | |
| 15331 | ACTIVE | N | N095-00-3/162 | LMC - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Various Cables - SP | | 7 | | | |
| 9848 | ACTIVE | N | N095-00-3/201 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 69680 | ACTIVE | N | N095-00-3/201 | Passage - Station Building - Euston Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | 20x Bitumen ducts within cable pit 2 | 20 | 20 | R700888Rev3 | | Y |
| 69678 | ACTIVE | N | N095-00-3/201 | Passage - Station Building - Euston Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | 20x Bitumen ducts within cable pit 1 | 20 | 20 | R700888Rev3 | | Y |
| 15332 | ACTIVE | N | N095-00-3/201/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal False Ceiling No access above fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 9849 | ACTIVE | N | N095-00-3/202 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15333 | ACTIVE | N | N095-00-3/202/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal False Ceiling No access above fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 9850 | ACTIVE | N | N095-00-3/203 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18094 | ACTIVE | N | N095-00-3/203/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal False Ceiling No access above fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 9851 | ACTIVE | N | N095-00-3/204 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15334 | ACTIVE | N | N095-00-3/204/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal False Ceiling No access above fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 15335 | ACTIVE | N | N095-00-3/204/FLR-01 | Floor - 1 - Passage - Station Building - Euston Stn | Cable Duct: Other | Asbestos | Known | | | | Cable Ducts - Chrysotile No access into floor ducts during 2020 re-inspection. | | 12 | | | |
| 9852 | ACTIVE | N | N095-00-3/205 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|---------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 15336 | ACTIVE | N | N095-00-3/205/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Tiles No access above fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 9853 | ACTIVE | N | N095-00-3/206 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15337 | ACTIVE | N | N095-00-3/206/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Tiles No access above fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 9854 | ACTIVE | N | N095-00-3/207 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18095 | ACTIVE | N | N095-00-3/207/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Tiles No access above fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 9855 | ACTIVE | N | N095-00-3/208 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15338 | ACTIVE | N | N095-00-3/208/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Tiles No access above fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 9856 | ACTIVE | N | N095-00-3/236 | Lobby - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18477 | ACTIVE | N | N095-00-3/236/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | YES | |
| 15339 | ACTIVE | N | N095-00-3/236/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Euston Stn | Void | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | YES | |
| 9857 | ACTIVE | N | N095-00-3/281 | Office - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Presumed | | | | Room is now part of 3/236 along with 3/341; | | | | | |
| 15340 | ACTIVE | N | N095-00-3/281/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | | | | | | |
| 18583 | ACTIVE | N | N095-00-3/281/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Euston Stn | Cellactite Sheeting | Asbestos | Known | | | | Corrugated Sheet - Chrysotile above False Ceiling No access above false ceiling during 2020 re-inspection. | | | | YES | |
| 9858 | ACTIVE | N | N095-00-3/341 | Mess Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15341 | ACTIVE | N | N095-00-3/341 | Mess Room - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18096 | ACTIVE | N | N095-00-3/341/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Euston Stn | Cellactite Sheeting | Asbestos | Known | | | | Corrugated Sheet - Chrysotile above False Ceiling No access above false ceiling during 2020 re-inspection. | | | | YES | |
| 9859 | ACTIVE | N | N095-00-3/406 | Locker Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15342 | ACTIVE | N | N095-00-3/406/CLG-01 | Ceiling: Suspended - 1 - Locker Room - Station Building - Euston Stn | Cellactite Sheeting | Asbestos | Known | | | | Corrugated Sheet - Chrysotile above Supalux Tiles No access above fixed supalux tiles during 2020 re-inspection. | | | | YES | |
| 19296 | ACTIVE | N | N095-00-3/406/CLG-01 | Ceiling: Suspended - 1 - Locker Room - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | | | | | | |
| 9860 | ACTIVE | N | N095-00-3/407 | Bin Store - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15343 | ACTIVE | N | N095-00-3/407/CLG-01 | Ceiling: Solid - 1 - Bin Store - Station Building - Euston Stn | Cellactite Sheeting | Asbestos | Known | | | | Cellactite Corrugated Sheet - Chrysotile | 30 | | | | |
| 9861 | ACTIVE | N | N095-00-3/601 | Stairs: Linear - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15344 | ACTIVE | N | N095-00-3/601/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal False Ceiling No access above fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 9862 | ACTIVE | N | N095-00-3/602 | Stairs: Linear - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15345 | ACTIVE | N | N095-00-3/602/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal False Ceiling No access above fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 9863 | ACTIVE | N | N095-00-3/603 | Stairs: Linear - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 69677 | ACTIVE | N | N095-00-3/603 | Stairs: Linear - Station Building - Euston Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | 20x Bitumen cable ducts within cable pit. | 20 | 20 | R700888Rev3 | | |
| 18097 | ACTIVE | N | N095-00-3/603/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal False Ceiling No access above fixed false ceiling during 2020 re-inspection. | | | | | |
| 9864 | ACTIVE | N | N095-00-3/631 | Stairs: Spiral - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18630 | ACTIVE | N | N095-00-3/631 | Stairs: Spiral - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



| N095-00 - Station Building - Euston Stn | | | | | | | | | | | | | | | | |
|---|----------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
| 18234 | ACTIVE | N | N095-00-3/791 | LMC Access - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Tunnel Ring - Caulkng - Amphipole Encapsualted 04/09/2007 | | | | | |
| 15346 | INACTIVE | N | N095-00-3/791/CLG-01 | Ceiling: Solid - 1 - LMC Access - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Tunnel Ring - Caulkng - Amphipole Encapsualted 04/09/2007 | | | | | |
| 15347 | ACTIVE | N | N095-00-3/792 | LMC Access - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Tunnel Ring - Caulkng - Amphipole Encapsualted 04/09/2007 | | | | | |
| 15348 | INACTIVE | N | N095-00-3/792/CLG-01 | Ceiling: Solid - 1 - LMC Access - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Tunnel Ring - Caulkng - Amphipole Encapsualted 04/09/2007 | | | | | |
| 15349 | ACTIVE | N | N095-00-3/793 | UMC Access - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Tunnel Ring - Caulkng - Amphipole Encapsualted 04/09/2007 | | | | | |
| 15350 | INACTIVE | N | N095-00-3/793/CLG-01 | Ceiling: Solid - 1 - UMC Access - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Tunnel Ring - Caulkng - Amphipole Encapsualted 04/09/2007 | | | | | |
| 15351 | ACTIVE | N | N095-00-3/794 | UMC Access - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Tunnel Ring - Caulkng - Chrysotile Encapsualted 04/09/2007 | | | | | |
| 15352 | INACTIVE | N | N095-00-3/794/CLG-01 | Ceiling: Solid - 1 - UMC Access - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Tunnel Ring - Caulkng - Chrysotile Encapsualted 04/09/2007 | | | | | |
| 9865 | ACTIVE | N | N095-00-4/201 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18098 | ACTIVE | N | N095-00-4/201/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling No access above fixed false ceiling during 2020 re-inspection. | | | | | |
| 9866 | ACTIVE | N | N095-00-4/202 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15353 | ACTIVE | N | N095-00-4/202/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling No access above fixed false ceiling during 2020 re-inspection. | | | | | |
| 9867 | ACTIVE | N | N095-00-4/203 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 69696 | ACTIVE | N | N095-00-4/203 | Passage - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux panel throughout to rear of metal panels (walls/ceiling) | | | R700888Rev3 | | |
| 15354 | ACTIVE | N | N095-00-4/203/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling No access above fixed metal false ceiling during 020 re-inspection. | | | | | |
| 9868 | ACTIVE | N | N095-00-4/236 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15355 | ACTIVE | N | N095-00-4/236 | Passage - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 2no x 20mm Cables | | 2 | | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9869 | ACTIVE | N | N095-00-4/261 | Platform 1 - Northbound Local - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70744 | ACTIVE | N | N095-00-4/261 | Platform 1 - Northbound Local - Station Building - Euston Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | Platform Invert - Bitumen cable ducts - total 10 no - To platform wall midway | | 10 | R728769 | N | Y |
| 69553 | ACTIVE | N | N095-00-4/261 | Platform 1 - Northbound Local - Station Building - Euston Stn | Westing house Boxes | Asbestos | Presumed | | | | Platform Invert - Small Westinghouse box - to trackside wall midway | | 1 | R728769 | | |
| 69555 | ACTIVE | N | N095-00-4/261 | Platform 1 - Northbound Local - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable duct to trackside / headwall arrivals end | | 1 | R728769 | | |
| 69558 | ACTIVE | N | N095-00-4/261 | Platform 1 - Northbound Local - Station Building - Euston Stn | Westing house Boxes | Asbestos | Presumed | | | | Platform Invert - Small Westinghouse box to platform wall midway | | 1 | R728769 | | |
| 69560 | ACTIVE | N | N095-00-4/261 | Platform 1 - Northbound Local - Station Building - Euston Stn | Cable: Wrap | Asbestos | Known | | | | Platform Invert - Cable wrapping to cables departure end (2x 1m) | 1 | 2 | R728769 | | |
| 70745 | ACTIVE | N | N095-00-4/261 | Platform 1 - Northbound Local - Station Building - Euston Stn | Cable Wrap | Asbestos | Known | | | | Platform Invert - Cable wrapping - cloth - total 2no x 1m - To cables departure end | 1 | 2 | R728769 | | |
| 70747 | ACTIVE | N | N095-00-4/261 | Platform 1 - Northbound Local - Station Building - Euston Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 2 no - To trackside wall departure end | | 2 | R728769 | N | Y |
| 69562 | ACTIVE | N | N095-00-4/261 | Platform 1 - Northbound Local - Station Building - Euston Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | Platform Invert - 8x Bitumen cable ducts to floor and wall departure end | | 8 | R728769 | | |
| 69566 | ACTIVE | N | N095-00-4/261 | Platform 1 - Northbound Local - Station Building - Euston Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - 8x Bitumen cable ducts to track wall/head wall arrivals end | | 8 | R728769 | | |
| 70743 | ACTIVE | N | N095-00-4/261 | Platform 1 - Northbound Local - Station Building - Euston Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Small Westinghouse box - total 1 no - To platform wall midway | | 1 | R728769 | | |
| 69689 | ACTIVE | N | N095-00-4/261 | Platform 1 - Northbound Local - Station Building - Euston Stn | | Asbestos | Sampled – Not Detected | | | | Filler /packing between tunnel ring joints | | | R700888Rev3 | | |
| 69688 | ACTIVE | N | N095-00-4/261 | Platform 1 - Northbound Local - Station Building - Euston Stn | Other Boarding | Asbestos | Sampled – Not Detected | | | | Insulation board - Backing on metal panel | 2 | | R700888Rev3 | | |
| 70737 | ACTIVE | N | N095-00-4/261 | Platform 1 - Northbound Local - Station Building - Euston Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout, wood, lead - To tunnel rings flanges throughout | | | R728769 | | |
| 69572 | ACTIVE | N | N095-00-4/261 | Platform 1 - Northbound Local - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | Platform Invert - Metal tunnel rings, concrete infill to walls, floor throughout, wood splinters, fibres (shuttering panels, cut offs) to concrete ceiling and walls throughout, grout, wood, lead to tunnel ring flanges throughout, metal access hatches in ladders.steps, supalux panel throughout on ceiling and walls, new electrical boxes, | | | | | |
| 70736 | ACTIVE | N | N095-00-4/261 | Platform 1 - Northbound Local - Station Building - Euston Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings, concrete infill - To walls, floor throughout | | | R728769 | | |
| 70746 | ACTIVE | N | N095-00-4/261 | Platform 1 - Northbound Local - Station Building - Euston Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | Platform Invert - Bitumen cable ducts - total 8 no - To platform floor and wall departure end | | 8 | R728769 | N | Y |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 69559 | ACTIVE | N | N095-00-4/261 | Platform 1 - Northbound Local - Station Building - Euston Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | Platform Invert - 10x Bitumen cable ducts to platform wall midway | | 10 | R728769 | | |
| 69557 | ACTIVE | N | N095-00-4/261 | Platform 1 - Northbound Local - Station Building - Euston Stn | Cable: Sheath | Asbestos | Known | | | | Platform Invert - Braided cable to J-Hanger | | 1 | R728769 | | |
| 70740 | ACTIVE | N | N095-00-4/261 | Platform 1 - Northbound Local - Station Building - Euston Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Small Westinghouse box - total 1 no- To trackside wall midway | | 1 | R728769 | | |
| 70739 | ACTIVE | N | N095-00-4/261 | Platform 1 - Northbound Local - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Platform Invert - Supalux panel - Throughout - To ceiling and wall | | | R728769 | N | Y |
| 70738 | ACTIVE | N | N095-00-4/261 | Platform 1 - Northbound Local - Station Building - Euston Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 8 no- To track wall/ head wall arrivals end | | 8 | R728769 | N | Y |
| 70742 | ACTIVE | N | N095-00-4/261 | Platform 1 - Northbound Local - Station Building - Euston Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cable - total 1 no - To J Hangers | | 1 | R728769 | | |
| 70741 | ACTIVE | N | N095-00-4/261 | Platform 1 - Northbound Local - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable duct - total 1 no - To trackside / head wall arrivals end | | 1 | R728769 | N | Y |
| 69570 | ACTIVE | N | N095-00-4/261 | Platform 1 - Northbound Local - Station Building - Euston Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - 2x Bitumen cable ducts to trackside wall departure end | | 2 | R728769 | | |
| 15356 | ACTIVE | N | N095-00-4/261/ CLG-01 | Ceiling: Solid - 1 - Platform 1 - Station Building - Euston Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above False Ceiling - No presumed asbestos | | | | | |
| 18099 | ACTIVE | N | N095-00-4/261/ FLR-01 | Floor - 1 - Platform 1 - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform 1 Invert Various Cable Sleeves - Chrysotile | | | | | YES |
| 15358 | ACTIVE | N | N095-00-4/261/ FLR-01 | Floor - 1 - Platform 1 - Station Building - Euston Stn | Cable: Wrap | Asbestos | Known | | | | Platform 1 Invert Chrysotile Asbestos Material Wrap. Previously Encapsulated. Strongly presumed No access into platform inverts during 2020 re-inspection. Confined space. | | | | | YES |
| 15357 | ACTIVE | N | N095-00-4/261/ FLR-01 | Floor - 1 - Platform 1 - Station Building - Euston Stn | Cable: Sheath | Asbestos | Known | | | | Platform 1 Invert 3 no. Cables | | 3 | | | YES |
| 9870 | ACTIVE | N | N095-00-4/262 | Platform 2 - Southbound Local - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70730 | ACTIVE | N | N095-00-4/262 | Platform 2 - Southbound Local - Station Building - Euston Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Small Westinghouse box - total 1 no - To platform wall midway | | 1 | R728769 | | |
| 70733 | ACTIVE | N | N095-00-4/262 | Platform 2 - Southbound Local - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 6 no - To trackside wall | | 6 | R728769 | N | Y |
| 70734 | ACTIVE | N | N095-00-4/262 | Platform 2 - Southbound Local - Station Building - Euston Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - 10 core box - total 1 no - To wall at departure end | | 1 | R728769 | | |
| 69542 | ACTIVE | N | N095-00-4/262 | Platform 2 - Southbound Local - Station Building - Euston Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | Platform Invert - 20x Bitumen cable ducts to arrivals walls 1 & 2 | | 20 | R728769 | | |



Hazardous Material Asset Register - Summary



| N095-00 - Station Building - Euston Stn | | | | | | | | | | | | | | | | |
|---|----------|-------------|---------------------|---|------------------------|---------------|-------------------------|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
| 69548 | ACTIVE | N | N095-00-4/262 | Platform 2 - Southbound Local - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - 6x Cable ducts to trackside wall | | 6 | R728769 | | |
| 69551 | ACTIVE | N | N095-00-4/262 | Platform 2 - Southbound Local - Station Building - Euston Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Platform Invert - 10 Core Box to wall at departure end | | 1 | R728769 | | |
| 15360 | ACTIVE | N | N095-00-4/262 | Platform 2 - Southbound Local - Station Building - Euston Stn | Cable: Sheath | Asbestos | Known | | | | Various Cables going to the Tunnel | | | | | |
| 45004 | INACTIVE | N | N095-00-4/262 | Platform 2 - Southbound Local - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 2 Invert - 2 No braided cable | | 2 | | | Y |
| 69545 | ACTIVE | N | N095-00-4/262 | Platform 2 - Southbound Local - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable duct to platform wall midway in invert | | 1 | R728769 | | |
| 69571 | ACTIVE | N | N095-00-4/262 | Platform 2 - Southbound Local - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | Platform Invert - Metal tunnel rings, concrete infill to walls, floor throughout, concrete slab to ceiling, walls throughout, RSJ to ceiling throughout, brickwork to walls throughout, plastic cables, metal conduits, cable management system, firestop and new mastics, plastic and metal pipework throughout, wood splinters, fibres (shuttering panels, cut offs to concrete ceiling and walls throughout) grout, wood, lead to tunnel ring flanges throughout, metal access hatches in ladders/ steps, | | | R728769 | | |
| 70729 | ACTIVE | N | N095-00-4/262 | Platform 2 - Southbound Local - Station Building - Euston Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - Throughout - To J Hangers | | | R728769 | | |
| 69564 | ACTIVE | N | N095-00-4/262 | Platform 2 - Southbound Local - Station Building - Euston Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - 4x Bitumen cable ducts to platform wall departure end | | 4 | R728769 | | |
| 69543 | ACTIVE | N | N095-00-4/262 | Platform 2 - Southbound Local - Station Building - Euston Stn | Cable: Sheath | Asbestos | Known | | | | Platform Invert - Asbestos braided cables to J-Hangers throughout | | | R728769 | | |
| 70726 | ACTIVE | N | N095-00-4/262 | Platform 2 - Southbound Local - Station Building - Euston Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings, concrete infill - To walls, floor throughout | | | R728769 | | |
| 18631 | INACTIVE | N | N095-00-4/262 | Platform 2 - Southbound Local - Station Building - Euston Stn | Cable: Sheath | Asbestos | No Access: Presumed | | | | 25mm Cable near Stairs 3/603; Various Cables going to the Tunnel | | 1 | | | |
| 69544 | ACTIVE | N | N095-00-4/262 | Platform 2 - Southbound Local - Station Building - Euston Stn | Westing house Boxes | Asbestos | Presumed | | | | Platform Invert - Small Westinghouse box to platform wall midway within invert | | 1 | R728769 | | |
| 70735 | ACTIVE | N | N095-00-4/262 | Platform 2 - Southbound Local - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Platform Invert - Supalux shuttering - To ceiling throughout | | | R728769 | N | Y |
| 70732 | ACTIVE | N | N095-00-4/262 | Platform 2 - Southbound Local - Station Building - Euston Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 4 no - To platform wall departure end | | 4 | R728769 | N | Y |
| 70731 | ACTIVE | N | N095-00-4/262 | Platform 2 - Southbound Local - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable duct - total 1 no - To platform wall midway | | 1 | R728769 | N | Y |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 70728 | ACTIVE | N | N095-00-4/262 | Platform 2 - Southbound Local - Station Building - Euston Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | Platform Invert - Bitumen cable ducts - total 20 no - To arrivals walls 1 and 2 | | 20 | R728769 | N | Y |
| 70727 | ACTIVE | N | N095-00-4/262 | Platform 2 - Southbound Local - Station Building - Euston Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout, wood, lead - To tunnel rings flanges throughout | | | R728769 | | |
| 15359 | ACTIVE | N | N095-00-4/262/CLG-01 | Ceiling: Solid - 1 - Platform 2 - Station Building - Euston Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above Concrete, Metal False Ceiling | | | | | |
| 15361 | INACTIVE | N | N095-00-4/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Euston Stn | Cable: Sheath | Asbestos | Known | | | | Platform 2 Invert Various Cables | | | | | YES |
| 18100 | INACTIVE | N | N095-00-4/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform 2 Invert 1x Cement Duct under 4/732 - Chrysotile | | 1 | | | YES |
| 15363 | INACTIVE | N | N095-00-4/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 2 Invert - under 3/603 Braided Cables | | 3 | | | YES |
| 18647 | INACTIVE | N | N095-00-4/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Euston Stn | Cable Ducts: Bitumen | Asbestos | Strongly Presumed | | | | Platform 2 Invert 2 x Bitumen Ducts H/L under 4/668 | | 2 | | | YES |
| 15362 | ACTIVE | N | N095-00-4/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Under 4/732 Ducts Cement - Asbestos identified. | | | | | YES |
| 9871 | ACTIVE | N | N095-00-4/381 | Switch Cupboard - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18235 | ACTIVE | N | N095-00-4/381/CLG-01 | Ceiling: Solid - 1 - Switch Cupboard - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | | | | | | |
| 15364 | ACTIVE | N | N095-00-4/381/CLG-01 | Ceiling: Solid - 1 - Switch Cupboard - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux No access above fixed supalux tiles during 2020 re-inspection. | | | | | |
| 9872 | ACTIVE | N | N095-00-4/661 | Switch Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15365 | ACTIVE | N | N095-00-4/661 | Switch Room - Station Building - Euston Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes - Insulation within 3x60 amp, 1x 30amp & 100amp | | 5 | | | |
| 9873 | ACTIVE | N | N095-00-4/668 | Switch Cupboard - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15366 | ACTIVE | N | N095-00-4/668 | Switch Cupboard - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9874 | ACTIVE | N | N095-00-4/711 | Lobby - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18101 | ACTIVE | N | N095-00-4/711 | Lobby - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|------------------------|---|-----------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9875 | ACTIVE | N | N095-00-4/712 | Relay Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18632 | ACTIVE | N | N095-00-4/712 | Relay Room - Station Building - Euston Stn | Cable: Sheath | Asbestos | Removed | | | | 2x Green 50mm Cables to wall 3 - removed as part of TCP project Oct 2022 | | 2 | | | |
| 19297 | ACTIVE | N | N095-00-4/712 | Relay Room - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 20mm Cables | | 1 | | N | N |
| 46820 | ACTIVE | N | N095-00-4/712 | Relay Room - Station Building - Euston Stn | Vinyl tiles | Asbestos | Known | | | | Marley tiles - (R713576) throughout the room to walls mostly removed on wall 3 . Still remaining on wall 1,2 and ceiling. | | | | | |
| 46821 | ACTIVE | N | N095-00-4/712 | Relay Room - Station Building - Euston Stn | Bitumen | Asbestos | Known | | | | Bitumen Glue to Marley Tiles on walls | | | R713576 | | |
| 15367 | ACTIVE | N | N095-00-4/712 | Relay Room - Station Building - Euston Stn | PCBs | Polychlorinated biphenyl | Removed | | | | PCB's - Fair Condition Serial Nos 39519; 19287; 197505; 39232; 40824; 43947 23/02/2017 Inspection still Fair Condition | | 6 | | | |
| 46822 | ACTIVE | N | N095-00-4/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Euston Stn | Other Boarding | Asbestos | Removed | | | | Paxoline board to within equipment rack to wall 3. - removed as part of TCP project - Oct 2022 | | | | | |
| 46824 | ACTIVE | N | N095-00-4/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Euston Stn | Other Boarding | Asbestos | Removed | | | | Brown paxoline board to wall 3 base of transformer - removed as part of TCP project - Oct 2022 | | | | | |
| 46825 | ACTIVE | N | N095-00-4/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Euston Stn | Other Boarding | Asbestos | Removed | | | | Brown paxoline board wall 3 to front side of frame - removed as part of TCP project - Oct 2022 | | | | | |
| 46823 | ACTIVE | N | N095-00-4/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Euston Stn | Other Boarding | Asbestos | Removed | | | | Paxoline board to wall plug - black - wall 3 low level - - removed as part of TCP project - Oct 2022 | | | | | |
| 9876 | ACTIVE | N | N095-00-4/713 | Relay Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44366 | ACTIVE | N | N095-00-4/713 80143139 | Relay Room - Station Building - Euston Stn Room Assets | Cable: Sheath | Asbestos | Presumed | | | | 2no yellow cables within roller shutters | | | | | |
| 44365 | ACTIVE | N | N095-00-4/713 80143139 | Relay Room - Station Building - Euston Stn Room Assets | Other Boarding | Asbestos | Presumed | | | | Paxoline panelling throughout room | | | | | |
| 15371 | ACTIVE | N | N095-00-4/713 | Relay Room - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 20mm Cables | | 1 | | | |
| 15370 | ACTIVE | N | N095-00-4/713 | Relay Room - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 2no x 50mm Cables | | 2 | | | |
| 15369 | INACTIVE | N | N095-00-4/713 | Relay Room - Station Building - Euston Stn | PCBs | Polychlorinated biphenyl | Removed | | | | 8 x PCB's - Fair Condition - located in roller shutter cabinet 23/02/2017 inspection signs of leaking | | 8 | | N | N |
| 18102 | ACTIVE | N | N095-00-4/713/CLG-01 | Ceiling: Suspended - 1 - Relay Room - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Boarding No access above fixed supalux panels during 2020 re-inspection. | | | | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 15368 | ACTIVE | N | N095-00-4/713/CLG-01 | Ceiling: Suspended - 1 - Relay Room - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Ceiling | | | | | |
| 9877 | ACTIVE | N | N095-00-4/731 | CER - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9878 | ACTIVE | N | N095-00-4/732 | CER - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9879 | ACTIVE | N | N095-00-4/771 | Pump Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18633 | ACTIVE | N | N095-00-4/771 | Pump Room - Station Building - Euston Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 60amp Switch Box - Insulation within | | 1 | | | |
| 15372 | ACTIVE | N | N095-00-4/771 | Pump Room - Station Building - Euston Stn | Gasket :Pipework | Asbestos | Presumed | | | | Gaskets to Flanged Bolted Joints to Pump Equipment | | | | | |
| 9880 | ACTIVE | N | N095-00-4/781 | Fan Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17933 | ACTIVE | N | N095-00-4/781 | Fan Room - Station Building - Euston Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No access | | | | | |
| 9881 | ACTIVE | N | N095-00-4/786 | Service Riser - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15183 | ACTIVE | N | N095-00-4/786 | Service Riser - Station Building - Euston Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring - Caulking | | | | | |
| 15184 | ACTIVE | N | N095-00-4/786/CLG-01 | Ceiling: Solid - 1 - Service Shaft - Station Building - Euston Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring - Caulking | | | | | |
| 17934 | ACTIVE | N | N095-00-4/786/CLG-01 | Ceiling: Solid - 1 - Service Shaft - Station Building - Euston Stn | Caulking | Asbestos | No Access: Presumed | | | | Rendered Tunnel Rings - No access to Sample Caulking Tunnel rings not visible behind render during 2020 re-inspection. | | | | | |
| 15185 | ACTIVE | N | N095-00-4/791 | Vent Shaft - Station Building - Euston Stn | Caulking | Asbestos | No Access: Presumed | | | | Rendered Tunnel Rings - No access to Sample Caulking Tunnel rings not visible behind render during 2020 re-inspection. | | | | | |
| 15186 | ACTIVE | N | N095-00-4/792 | Vent Shaft - Station Building - Euston Stn | Caulking | Asbestos | No Access: Presumed | | | | Rendered Tunnel Rings - No access to Sample Caulking Tunnel rings not visible behind render during 2020 re-inspection. | | | | | |
| 15187 | ACTIVE | N | N095-00-4/792/CLG-01 | Ceiling: Solid - 1 - Vent Shaft - Station Building - Euston Stn | No Access | Asbestos | No Access: Presumed | | | | Ceiling and above not surveyed - too high High level not accessed during 2020 re-inspection. | | | | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9882 | ACTIVE | N | N095-00-4/971 | Disused Room Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15188 | ACTIVE | N | N095-00-4/971 | Disused Room Room - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 45006 | ACTIVE | N | N095-00-4/972 | Vent Shaft - Station Building - Euston Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Materials within ten core box presumed to contain asbestos insulating materials within | | | | N | N |
| 15189 | ACTIVE | N | N095-00-4/972 | Vent Shaft - Station Building - Euston Stn | Caulking | Asbestos | No Access: Presumed | | | | Rendered Tunnel Rings - No access to Sample Caulking Tunnel rings not visible behind render during 2020 re-inspection. | | | | | |
| 45007 | ACTIVE | N | N095-00-4/972 | Vent Shaft - Station Building - Euston Stn | Cable: Sheath | Asbestos | Known | | | | Braided cable coming out of box | | | | N | N |
| 45005 | ACTIVE | N | N095-00-4/972 | Vent Shaft - Station Building - Euston Stn | Cable: Sheath | Asbestos | Known | | | | 1x Asbestos braided cable to cable run on wall | | | | N | N |
| 69667 | ACTIVE | N | N095-00-4/972 | Vent Shaft - Station Building - Euston Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | Bitumen duct to brick wall | | 1 | R700888Rev3 | | |
| 69669 | ACTIVE | N | N095-00-4/972 | Vent Shaft - Station Building - Euston Stn | Cable: Sheath | Asbestos | Known | | | | Vent Shaft area - 2x cables on cable racking on wall opposite door to room 4/731 (>20m2) | 20 | 2 | R700888Rev3 | | |
| 18472 | INACTIVE | N | N095-00-4/972/CLG-01 | Ceiling: Solid - 1 - Vent Shaft - Station Building - Euston Stn | Caulking | Asbestos | No Access: Presumed | | | | Rendered Tunnel Rings - No access to Sample Caulking | | | | | |
| 69698 | ACTIVE | N | N095-00-4/973 | Vent Shaft - Station Building - Euston Stn | Bitumen | Asbestos | Sampled – Not Detected | | | | Bitumen to walls/ceiling & floor of passage/vent tunnel throughout | | | R700888Rev3 | | |
| 15190 | ACTIVE | N | N095-00-4/973 | Vent Shaft - Station Building - Euston Stn | Caulking | Asbestos | No Access: Presumed | | | | Rendered Tunnel Rings - No access to Sample Caulking Tunnel rings not visible behind render during 2020 re-inspection. | | | | | |
| 17935 | INACTIVE | N | N095-00-4/973/CLG-01 | Ceiling: Solid - 1 - Vent Shaft - Station Building - Euston Stn | Caulking | Asbestos | No Access: Presumed | | | | Rendered Tunnel Rings - No access to Sample Caulking | | | | | |
| 15191 | ACTIVE | N | N095-00-4/974 | Vent Shaft - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 69685 | ACTIVE | N | N095-00-4/974 | Vent Shaft - Station Building - Euston Stn | Cable: Wrap | Asbestos | Sampled – Not Detected | | | | Cable wrapping to cable run and loose to wall | 20 | 2 | R700888Rev3 | | |
| 15192 | ACTIVE | N | N095-00-4/975 | Vent Shaft - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 15193 | ACTIVE | N | N095-00-4/976 | Vent Shaft - Station Building - Euston Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring Caulking | | | | | |
| 15194 | ACTIVE | N | N095-00-4/976/CLG-01 | Ceiling: Solid - 1 - Vent Shaft - Station Building - Euston Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring Caulking | | | | | |
| 45010 | ACTIVE | N | N095-00-4/981 | Vent Shaft - Station Building - Euston Stn | Cable: Sheath | Asbestos | Known | | | | Braided cable coming out of box | | 1 | | N | N |



Hazardous Material Asset Register - Summary



| N095-00 - Station Building - Euston Stn | | | | | | | | | | | | | | | | |
|---|--------|-------------|----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
| 45009 | ACTIVE | N | N095-00-4/981 | Vent Shaft - Station Building - Euston Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Materials within ten core box presumed to contain asbestos insulating materials within | | | | N | N |
| 45008 | ACTIVE | N | N095-00-4/981 | Vent Shaft - Station Building - Euston Stn | Cable: Sheath | Asbestos | Known | | | | 1x Asbestos braided cable to cable run on wall | | 1 | | N | N |
| 18577 | ACTIVE | N | N095-00-4/981 | Vent Shaft - Station Building - Euston Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring Caulking | | | | | |
| 9883 | ACTIVE | N | N095-00-4/982 | Disused Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15195 | ACTIVE | N | N095-00-4/982 | Disused Room - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables to Vent Tunnel Slight damage identified during 2020 re-inspection. | | 3 | | | |
| 9884 | ACTIVE | N | N095-00-4/986 | Disused Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 45011 | ACTIVE | N | N095-00-4/986 | Disused Room - Station Building - Euston Stn | Gasket :Pipework | Asbestos | Presumed | | | | 6x gaskets to flanges of metal pipework centre of shaft | | 6 | | N | N |
| 15196 | ACTIVE | N | N095-00-4/986/CLG-01 | Ceiling: Solid - 1 - Disused Room - Station Building - Euston Stn | No Access | Asbestos | No Access: Presumed | | | | Ceiling and above not surveyed - too high High level not accessed during 2020 re-inspection. | | | | | |
| 9885 | ACTIVE | N | N095-00-5/201 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18166 | ACTIVE | N | N095-00-5/201/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Tunnel Rings behind metal panels - Asbestos Caulking Opposite the bottom of staircase 3/601 in corridor 5/201. Refer to Report R700888Rev3 | | | | | |
| 9886 | ACTIVE | N | N095-00-5/411 | Disused Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17936 | ACTIVE | N | N095-00-5/411 | Disused Room - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Tunnel Ring - Caulking - Amphibole | | | | | |
| 15197 | ACTIVE | N | N095-00-5/411 | Disused Room - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel above door, Tunnel Rings, Bricks | | | | | |
| 15198 | ACTIVE | N | N095-00-5/411/CLG-01 | Ceiling: Solid - 1 - Disused Room - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling No access above fixed metal ceiling during 2020 re-inspection. | | | | | |
| 9887 | ACTIVE | N | N095-00-5/601 | Stairs: Linear - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18552 | ACTIVE | N | N095-00-5/601/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Caulking, throughout, to tunnel rings above false ceiling (between rings) | | | R674051 | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|---------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 45012 | INACTIVE | N | N095-00-5/601/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Caulking to metal tunnel ring flanges in false ceiling Item sampled again on 04/03/2020 - R674051 Caulking, throughout, to tunnel rings above false ceiling (between rings) | | | | Y | N |
| 9888 | ACTIVE | N | N095-00-5/602 | Stairs: Linear - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15199 | ACTIVE | N | N095-00-5/602/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Euston Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above Metal Ceiling | | | | | |
| 15200 | ACTIVE | N | N095-00-5/602/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board | | | | | |
| 17937 | ACTIVE | N | N095-00-5/602/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Tunnel Ring - Caulking - Chrysotile & Amosite Item sampled again on 04/03/2020 - R674051 Caulking, throughout, to tunnel rings above false ceiling (between rings) | | | | | |
| 15201 | ACTIVE | N | N095-00-5/791 | Vent Shaft - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Tunnel Rings to Walls LHS & RHS, Ceiling and below False Floor - Caulking - Chrysotile | | | | | |
| 9889 | ACTIVE | N | N095-00-6/081 | Circulation Area - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15202 | ACTIVE | N | N095-00-6/081/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling - Tunnel Ring Caulking Strongly Presumed to be present. No access above fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 9890 | ACTIVE | N | N095-00-6/082 | Circulation Area - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17938 | ACTIVE | N | N095-00-6/082 | Circulation Area - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Caulking - Amphibole No access above fixed false ceiling during 2020 re-inspection. | | | | Y | |
| 15203 | ACTIVE | N | N095-00-6/082/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling No access above fixed false ceiling during 2020 re-inspection. | | | | | |
| 9891 | ACTIVE | N | N095-00-6/121 | Service Riser - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15204 | ACTIVE | N | N095-00-6/121 | Service Riser - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 50mm Cables - SP | | 1 | | | |
| 45015 | INACTIVE | N | N095-00-6/121 | Service Riser - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | 10no Cable Sleeves | | 10 | | N | N |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|---------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 45014 | INACTIVE | N | N095-00-6/121 | Service Riser - Station Building - Euston Stn | | Asbestos | Known | | | | 1no Asbestos Cable | | | | N | N |
| 15205 | ACTIVE | N | N095-00-6/121/WAL-001 | Wall: Internal - 1 - Service Riser - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Cable Sleeves - Underneath 6/211 - Chrysotile No access into service riser during 2020 re-inspection. Confined space. | | | | | |
| 9892 | ACTIVE | N | N095-00-6/122 | Service Riser - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17939 | ACTIVE | N | N095-00-6/122 | Service Riser - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Cable Sleeves - Chrysotile No access into service riser during 2020 re-inspection. Confined space. | | | | | |
| 15206 | ACTIVE | N | N095-00-6/122 | Service Riser - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables | | 8 | | | |
| 45017 | INACTIVE | N | N095-00-6/122 | Service Riser - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | 10no Cable Sleeves (Below Passage) | | 10 | | N | N |
| 45016 | INACTIVE | N | N095-00-6/122 | Service Riser - Station Building - Euston Stn | | Asbestos | Known | | | | Asbestos Cables (Below Passage) | | | | N | N |
| 9893 | ACTIVE | N | N095-00-6/123 | Service Riser - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15207 | ACTIVE | N | N095-00-6/123 | Service Riser - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Cable Sleeves under 6/203 - Chrysotile No access into service riser during 2020 re-inspection. Confined space. | | 10 | | | |
| 9894 | ACTIVE | N | N095-00-6/124 | Service Riser - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18263 | ACTIVE | N | N095-00-6/124 | Service Riser - Station Building - Euston Stn | Cable Duct: Other | Asbestos | Strongly Presumed | | | | Cable Sleeves - Chrysotile | | 10 | | | |
| 18553 | ACTIVE | N | N095-00-6/124 | Service Riser - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables | | 4 | | | |
| 9895 | ACTIVE | N | N095-00-6/161 | LMC - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15522 | ACTIVE | N | N095-00-6/161 | LMC - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 9 x Cables going into Invert | | 9 | | | |
| 69703 | ACTIVE | N | N095-00-6/161 | LMC - Station Building - Euston Stn | Other Boarding | Asbestos | Sampled – Not Detected | | | | Insulation board to floor near the end of the service duct/cableway | | | R700888Rev3 | | |
| 15521 | ACTIVE | N | N095-00-6/161 | LMC - Station Building - Euston Stn | Cable Duct: Other | Asbestos | Strongly Presumed | | | | 2 x Cable Sleeves / Ducts | | 2 | | | |
| 15519 | ACTIVE | N | N095-00-6/161 | LMC - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Tunnel Ring - Caulkng - Amphipole - Encapsulated | | | | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|---------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 15520 | INACTIVE | N | N095-00-6/161/CLG-01 | Ceiling: Solid - 1 - LMC - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Tunnel Ring - Caulkng - Amphipole - Encapsulated | | | | | |
| 9896 | ACTIVE | N | N095-00-6/162 | LMC - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15524 | ACTIVE | N | N095-00-6/162 | LMC - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Cement cable duct within LMC 3&4 | | | | | |
| 18264 | ACTIVE | N | N095-00-6/162 | LMC - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Encapsulated - Tunnel Ring - Caulkng - Chrysotile | | | | | |
| 15525 | ACTIVE | N | N095-00-6/162 | LMC - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 4no Cables | | 4 | | | |
| 15523 | INACTIVE | N | N095-00-6/162/CLG-01 | Ceiling: Solid - 1 - LMC - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Encapsulated - Tunnel Ring - Caulkng - Chrysotile | | | | | |
| 9897 | ACTIVE | N | N095-00-6/201 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15526 | ACTIVE | N | N095-00-6/201 | Passage - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Asbestos tunnel ring caulking behind metal panels (R700888Rev3) | 10 | | | | |
| 69692 | ACTIVE | N | N095-00-6/201 | Passage - Station Building - Euston Stn | | Asbestos | Sampled – Not Detected | | | | Packer around bolts to tunnel rings | 1 | | R700888Rev3 | | |
| 9898 | ACTIVE | N | N095-00-6/202 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18646 | ACTIVE | N | N095-00-6/202 | Passage - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables No access into floor ducts during 2020 re-inspection. Lifting equipment required. | | 2 | | | |
| 18656 | ACTIVE | N | N095-00-6/202 | Passage - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Various Cable Sleeves - Chrysotile No access into floor ducts during 2020 re-inspection. Lifting equipment required. | | | | | |
| 18265 | ACTIVE | N | N095-00-6/202/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling No access above fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 9899 | ACTIVE | N | N095-00-6/203 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15527 | ACTIVE | N | N095-00-6/203/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling No access above fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 9900 | ACTIVE | N | N095-00-6/204 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|---------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 15529 | ACTIVE | N | N095-00-6/204 | Passage - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Various Cable Sleeves - Chrysotile No access into floor ducts during 2020 re-inspection. | | | | | |
| 15528 | ACTIVE | N | N095-00-6/204/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling No access above fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 9901 | ACTIVE | N | N095-00-6/205 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18242 | ACTIVE | N | N095-00-6/205/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling No access above fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 9902 | ACTIVE | N | N095-00-6/206 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15531 | ACTIVE | N | N095-00-6/206 | Passage - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Cable Sleeves - Chrysotile No access into floor ducts during 2020 re-inspection. Lifting equipment required. | | 1 | | | |
| 15530 | ACTIVE | N | N095-00-6/206/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling No access into fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 9903 | ACTIVE | N | N095-00-6/207 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18708 | ACTIVE | N | N095-00-6/207 | Passage - Station Building - Euston Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking No access above fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 18266 | ACTIVE | N | N095-00-6/207/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling No access above fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 9904 | ACTIVE | N | N095-00-6/208 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15532 | ACTIVE | N | N095-00-6/208/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling No access above fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 15533 | INACTIVE | N | N095-00-6/208/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | | |
| 9905 | ACTIVE | N | N095-00-6/209 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9906 | ACTIVE | N | N095-00-6/210 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|---------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 69672 | ACTIVE | N | N095-00-6/210 | Passage - Station Building - Euston Stn | Cellactite Sheeting | Asbestos | Known | | | | Cellactite behind brick wall | 3 | | R700888Rev3 | | |
| 15534 | ACTIVE | N | N095-00-6/210/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Caulking to metal tunnel rings above false ceiling - Known | | | R662226 | | |
| 45013 | INACTIVE | N | N095-00-6/210/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Caulking to metal tunnel ring flanges in false ceiling | | | | N | N |
| 9907 | ACTIVE | N | N095-00-6/211 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15535 | ACTIVE | N | N095-00-6/211/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling No access above fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 9908 | ACTIVE | N | N095-00-6/212 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15537 | ACTIVE | N | N095-00-6/212/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling No access above fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 9909 | ACTIVE | N | N095-00-6/213 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18268 | ACTIVE | N | N095-00-6/213/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling No access above fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 9910 | ACTIVE | N | N095-00-6/214 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15539 | ACTIVE | N | N095-00-6/214/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling No access above fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 9911 | ACTIVE | N | N095-00-6/215 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15540 | ACTIVE | N | N095-00-6/215/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Fire Break above Metal Ceiling | | | | YES | |
| 9912 | ACTIVE | N | N095-00-6/216 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15541 | ACTIVE | N | N095-00-6/216/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete | | | | | |
| 9913 | ACTIVE | N | N095-00-6/217 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|---------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 15542 | ACTIVE | N | N095-00-6/217/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling No access above fixed metal false ceiling during 2020 re-inspection. | | | | | |
| 9914 | ACTIVE | N | N095-00-6/237 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 69700 | ACTIVE | N | N095-00-6/237 | Passage - Station Building - Euston Stn | Other Boarding | Asbestos | Sampled – Not Detected | | | | Medium density ceiling tiles throughout | | | R700888Rev3 | | |
| 19428 | ACTIVE | N | N095-00-6/237 | Passage - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Tunnel rings (not visible) possibly containing caulking material in flanges and joints are present behind corrugated metal sheeting forming structure of all platform tunnels at the station– Known Asbestos. No access above false ceiling during 2020 re-inspection. | | | | | |
| 69702 | ACTIVE | N | N095-00-6/237 | Passage - Station Building - Euston Stn | Other Boarding | Asbestos | Sampled – Not Detected | | | | Medium density board ceiling tiles loose to floor | | | R700888Rev3 | | |
| 15373 | ACTIVE | N | N095-00-6/237/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Ceiling Tiles | | | | | |
| 15374 | INACTIVE | N | N095-00-6/237/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Euston Stn | Cellactite Sheeting | Asbestos | Known | | | | Cellactite Corrugated Sheet - Chrysotile above False Ceiling | | | | Y | N |
| 18269 | ACTIVE | N | N095-00-6/237/DOR-01 | Door - 1 - Passage - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux panel on door | | | | | |
| 9915 | ACTIVE | N | N095-00-6/238 | Lobby - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18103 | ACTIVE | N | N095-00-6/238 | Lobby - Station Building - Euston Stn | No Access | Asbestos | Room: Surveyed – No Known Asbestos | | | | Not Surveyed Management survey completed during 2020 re-inspection. No asbestos containing materials present. | | | | | |
| 9916 | ACTIVE | N | N095-00-6/239 | Lobby - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15375 | ACTIVE | N | N095-00-6/239 | Lobby - Station Building - Euston Stn | No Access | Asbestos | Room: Surveyed – No Known Asbestos | | | | Not Surveyed Management survey completed during 2020 re-inspection. No asbestos containing materials present. | | | | | |
| 9917 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18709 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Cable Sleeves - Chrysotile (Below Passage 6/212) | | 10 | | | Y |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|----------------------|---------------|------------------------|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 69574 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Cable: Sheath | Asbestos | Known | | | | Platform Invert - 2x Braided cables to J Hangers throughout | | 2 | R728770 | | |
| 69577 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Cable: Sheath | Asbestos | Known | | | | Platform Invert - Braided cable - cut to concrete cores | | 1 | R728770 | | |
| 69579 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - 10x Cement cable ducts to dividing wall (2x banks of 5x) | | 10 | R728769 | | |
| 69582 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts to dividing wall (2x banks of 5) | | 10 | R728770 | | |
| 69584 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - 6x Cement cable ducts to trackside wall, arrivals end | | 6 | R728770 | | |
| 69585 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable duct to trackside wall, arrival end | | 1 | R728770 | | |
| 70749 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728770 | | |
| 70750 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - total 2 no throughout - To J Hangers | | 2 | R728770 | | |
| 70751 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable duct - total 1 no - To trackside wall , departure end | | 1 | R728770 | N | Y |
| 70753 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 x 5no - To dividing wall | | 10 | R728770 | N | Y |
| 70754 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 x 5no - To dividing wall | | 10 | R728770 | N | Y |
| 70758 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 6 no - To trackside wall, arrivals end | | 6 | R728770 | N | Y |
| 70759 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable duct - total 1 no - To trackside wall, arrivals end | | 1 | R728770 | N | Y |
| 69691 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux to firebreak above high level arched ceiling panels | 4 | | R700888Rev3 | | |
| 69581 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - 10x Cement cable ducts to dividing wall (2x banks of 5) | | 10 | R728770 | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|----------------------|---------------|-------------------------|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 69583 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Westing house Boxes | Asbestos | Presumed | | | | Platform Invert - Small Westinghouse box to trackside wall, arrivals end. Presumed asbestos insulating materials within | | 1 | R728770 | | |
| 69586 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - 6x Cement cable duct to trackside wall departure end | | 6 | R728770 | | |
| 70748 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728770 | | |
| 70752 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cable - cut - total 1 no - To concrete cores | | 1 | R728770 | | |
| 70755 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 x 5no - To dividing wall | | 10 | R728770 | N | Y |
| 70756 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 x 5no - To dividing wall | | 10 | R728770 | N | Y |
| 70757 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Materials within small Westinghouse box - total 1 no - To trackside wall, arrivals end | | 1 | R728770 | | |
| 70760 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 6 no - To trackside wall, departure end | | 6 | R728770 | N | Y |
| 69640 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill to walls, floor throughout, plastic cables, metal conduits and cable management system and new firestop and mastics, plastic and metal pipework, grout, wood, lead to tunnel ring flanges throughout, wood splinters, fibres (shuttering panels, cut offs to concrete ceiling and walls, | | | | | |
| 15376 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Void | Asbestos | Surveyed – Not Detected | | | | Tiles; Metal behind cable running panels & Panel below Euston Sign | | | | | |
| 15538 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Asbestos Cables (Below Passage 6/212) | | | | | Y |
| 69575 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable duct to trackside wall departure end. | | 1 | R728770 | | |
| 69580 | ACTIVE | N | N095-00-6/263 | Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - 10x Cement cable ducts to dividing wall (2x banks of 5) | | 10 | R728770 | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|---------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 15377 | ACTIVE | N | N095-00-6/263/CLG-01 | Ceiling: Solid - 1 - Platform 3 - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Localised Encapsulation - Asbestos Caulking behind panelling the length of platform - above Metal Ceiling | | | | YES | |
| 15378 | INACTIVE | N | N095-00-6/263/FLR-01 | Floor - 1 - Platform 3 - Station Building - Euston Stn | Cable: Sheath | Asbestos | Known | | | | Platform 3 Invert - Various Cable Sleeves - Chrysotile | | | | | YES |
| 18104 | INACTIVE | N | N095-00-6/263/FLR-01 | Floor - 1 - Platform 3 - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 3 Invert - 2no Cables nr 6/717 | | 2 | | | YES |
| 9918 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18267 | INACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cable within invert by 6/211 | | 1 | | | |
| 69636 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - 4x Cement cable ducts to trackside wall | | 4 | R728770 | | |
| 69635 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Westing house Boxes | Asbestos | Presumed | | | | Platform Invert - Small Westinghouse box to trackside wall. Presumed asbestos insulating materials within | | 1 | R728770 | | |
| 69633 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - 10x Cement cable ducts to dividing wall (2 banks of 5) | | 10 | R728770 | | |
| 70765 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 no - To trackside wall | | 2 | R728770 | N | Y |
| 70772 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Materials within small Westinghouse box - total 1 no - To trackside wall | | 1 | R728770 | | |
| 69590 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - 10x Cable ducts to diving walls (2x banks of 5x) | | 10 | R728770 | | |
| 70769 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 x 5no - To dividing walls | | 10 | R728770 | N | Y |
| 70770 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 4 no - To platform wall | | 4 | R728770 | N | Y |
| 70771 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 x 5no - To dividing wall | | 10 | R728770 | N | Y |
| 70773 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 4 no - To trackside wall | | 4 | R728770 | N | Y |



Hazardous Material Asset Register - Summary



| N095-00 - Station Building - Euston Stn | | | | | | | | | | | | | | | | |
|---|--------|-------------|---------------------|---|----------------------|---------------|-------------------------|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
| 70774 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 no - To trackside wall | | 2 | R728770 | N | Y |
| 69587 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - 4x Cement cable ducts to trackside wall, arrivals end | | 4 | R728770 | | |
| 69588 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable: Sheath | Asbestos | Known | | | | Platform Invert - >10x Braided cables on J Hangers throughout invert | | 10 | R728770 | | |
| 69589 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - 2x Cement cable ducts to trackside wall | | 2 | R728770 | | |
| 70761 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728770 | | |
| 70763 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 4 no - To trackside wall, arrivals end | | 4 | R728770 | N | Y |
| 70766 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 x 5no - To dividing walls | | 10 | R728770 | N | Y |
| 70767 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 x 5no - To dividing walls | | 10 | R728770 | N | Y |
| 69631 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - 10x Cement cable ducts to dividing wall (2 banks of 5) | | 10 | R728770 | | |
| 69632 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - 4x Cement cable ducts to platform wall | | 4 | R728770 | | |
| 69639 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - 2x Cement cable ducts to trackside wall | | 2 | R728770 | | |
| 69641 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill to walls, floor throughout, grout, wood, lead to tunnel ring flanges throughout, plastic and metal pipework, wood splinters, fibres (shuttering panels, cut-offs) to concrete ceiling and walls throughout, metal access hatches and ladders/steps, plastic cables, metal conduits and cable management systems and new fire stopping and mastics | | | | | |
| 15380 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Presumed | | | | Platform 4 tail wall trackside - Cable Ducts | | 2 | | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 15536 | INACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Cable Sleeves - Chrysotile within invert by 6/211 | | 10 | | | |
| 69591 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - 10x Cement Cement cable ducts to dividing walls (2x banks of 5) | | 10 | R728770 | | |
| 69540 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cellactite Sheeting | Asbestos | Known | | | | Corrugated cellactite sheeting behind platform fascias and above relay rooms at departure and arrival ends of platform | | | 0600082 | | |
| 70762 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728770 | | |
| 70764 | ACTIVE | N | N095-00-6/264 | Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - total >10 no throughout - To J Hangers throughout | | 10 | R728770 | | |
| 15379 | ACTIVE | N | N095-00-6/264/CLG-01 | Ceiling: Solid - 1 - Platform 4 - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Above Metal Ceiling - Asbestos Caulking behind panelling the length of platform | | | | YES | |
| 15382 | ACTIVE | N | N095-00-6/264/FLR-01 | Floor - 1 - Platform 4 - Station Building - Euston Stn | Caulking | Asbestos | Strongly Presumed | | | | Platform 4 Invert -Tunnel Rings - Caulking by 6/715 | | | | | YES |
| 15381 | INACTIVE | N | N095-00-6/264/FLR-01 | Floor - 1 - Platform 4 - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform 4 Invert - Various Cable Sleeves - Chrysotile | | | | | YES |
| 15383 | INACTIVE | N | N095-00-6/264/FLR-01 | Floor - 1 - Platform 4 - Station Building - Euston Stn | Cable Duct: Other | Asbestos | Known | | | | Various Cable Ducts within Invert | | 6 | | | YES |
| 18105 | INACTIVE | N | N095-00-6/264/FLR-01 | Floor - 1 - Platform 4 - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 4 Invert - Various Cables | | | | | YES |
| 9919 | ACTIVE | N | N095-00-6/265 | Platform 5 - Northbound Local - Victoria Line - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70798 | ACTIVE | N | N095-00-6/265 | Platform 5 - Northbound Local - Victoria Line - Station Building - Euston Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Materials within small Westinghouse box - total 1 no - To trackside wall, departure end | | 1 | R728770 | | |
| 70801 | ACTIVE | N | N095-00-6/265 | Platform 5 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 x 5no - To dividing wall | | 10 | R728770 | N | Y |
| 70802 | ACTIVE | N | N095-00-6/265 | Platform 5 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 x 5no - To platform wall | | 10 | R728770 | N | Y |
| 69646 | ACTIVE | N | N095-00-6/265 | Platform 5 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - 2x Cement cable ducts to trackside wall departure end | | 2 | R728771 | | |
| 69653 | ACTIVE | N | N095-00-6/265 | Platform 5 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable: Sheath | Asbestos | Known | | | | Platform Invert - >10x Braided cables to J Hangers throughout | | 10 | R728771 | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|----------------------|---------------|------------------------|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 69656 | ACTIVE | N | N095-00-6/265 | Platform 5 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - 10x Cement cable ducts to dividing wall (2 banks of 5) | | 10 | R728771 | | |
| 69661 | ACTIVE | N | N095-00-6/265 | Platform 5 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - 10x Cement cable ducts to trackside wall arrival end (2x banks of 5) | | 10 | R728771 | | |
| 70793 | ACTIVE | N | N095-00-6/265 | Platform 5 - Northbound Local - Victoria Line - Station Building - Euston Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728770 | | |
| 70794 | ACTIVE | N | N095-00-6/265 | Platform 5 - Northbound Local - Victoria Line - Station Building - Euston Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728770 | | |
| 70797 | ACTIVE | N | N095-00-6/265 | Platform 5 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - >10no throughout - To J Hangers throughout | | 10 | R728770 | | |
| 70799 | ACTIVE | N | N095-00-6/265 | Platform 5 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 x 5no - To dividing wall | | 10 | R728770 | N | Y |
| 70800 | ACTIVE | N | N095-00-6/265 | Platform 5 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 x 5no - To dividing wall | | 10 | R728770 | N | Y |
| 70803 | ACTIVE | N | N095-00-6/265 | Platform 5 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert- Cement cable ducts - total 2 x 5no - To trackside wall, arrivals end | | 10 | R728770 | N | Y |
| 70804 | ACTIVE | N | N095-00-6/265 | Platform 5 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 x 5no - To trackside wall, arrivals end | | 10 | R728770 | N | Y |
| 69541 | ACTIVE | N | N095-00-6/265 | Platform 5 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cellactite Sheeting | Asbestos | Known | | | | Corrugated Cellactite sheeting behind platform fascias and above relay rooms at departure and arrival ends of platform | | | 0600082 | | |
| 69648 | ACTIVE | N | N095-00-6/265 | Platform 5 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - 4x Cement cable ducts to trackside wall departure end. | | 4 | R728771 | | |
| 69654 | ACTIVE | N | N095-00-6/265 | Platform 5 - Northbound Local - Victoria Line - Station Building - Euston Stn | Westing house Boxes | Asbestos | Presumed | | | | Platform Invert - Small Westinghouse Box. Presumed asbestos insulating materials within | | 1 | R728771 | | |
| 69655 | ACTIVE | N | N095-00-6/265 | Platform 5 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - 10x Cement cable ducts to dividing wall (2 banks of 5) | | 10 | R728771 | | |
| 69657 | ACTIVE | N | N095-00-6/265 | Platform 5 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - 10x Cement cable ducts to dividing wall (2 banks of 5) | | 10 | R728771 | | |
| 69658 | ACTIVE | N | N095-00-6/265 | Platform 5 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - 10x Cement cable ducts to platform wall (2 banks of 5) | | 10 | R728771 | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 69660 | ACTIVE | N | N095-00-6/265 | Platform 5 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - 10x Cement cable ducts to trackside wall arrivals end (2x banks 5) | | 10 | R728771 | | |
| 69665 | ACTIVE | N | N095-00-6/265 | Platform 5 - Northbound Local - Victoria Line - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill to walls, floor throughout, grout/wood/lead to tunnel ring flanges, RSJ to ceiling, brickwork to walls, plastic cables, metal conduits and cable management system and new firestopping and mastics, wood splinters, fibres (shuttering, panels, cut-offs) | | | | | |
| 70795 | ACTIVE | N | N095-00-6/265 | Platform 5 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 no - To trackside wall, departure end | | 2 | R728770 | N | Y |
| 70796 | ACTIVE | N | N095-00-6/265 | Platform 5 - Northbound Local - Victoria Line - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 4 no - To trackside wall, departure end | | 4 | R728770 | N | Y |
| 15384 | ACTIVE | N | N095-00-6/265/CLG-01 | Ceiling: Solid - 1 - Platform 5 - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Localised Encapsulation - Asbestos Caulking behind panelling the length of platform | | | | | |
| 18634 | INACTIVE | N | N095-00-6/265/FLR-01 | Floor - 1 - Platform 5 - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform 5 Invert - Various Cable Sleeves - Chrysotile | | | | | YES |
| 15385 | INACTIVE | N | N095-00-6/265/FLR-01 | Floor - 1 - Platform 5 - Station Building - Euston Stn | Westing house Boxes | Asbestos | Surveyed – Not Detected | | | | Platform 5 Invert | | 1 | | | YES |
| 15386 | INACTIVE | N | N095-00-6/265/FLR-01 | Floor - 1 - Platform 5 - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 5 Invert - Various Cables | | | | | YES |
| 15387 | INACTIVE | N | N095-00-6/265/FLR-01 | Floor - 1 - Platform 5 - Station Building - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | Cement Cable Ducts at Middle of SB Platform within Wall to LMC in Invert - Chrysotile | | | | | YES |
| 9920 | ACTIVE | N | N095-00-6/266 | Platform 6 - Southbound Fast - Northern Line - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70808 | ACTIVE | N | N095-00-6/266 | Platform 6 - Southbound Fast - Northern Line - Station Building - Euston Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728770 | | |
| 69663 | ACTIVE | N | N095-00-6/266 | Platform 6 - Southbound Fast - Northern Line - Station Building - Euston Stn | Cable: Sheath | Asbestos | Presumed | | | | Platform Invert - Braided cable - North end right hand side of cable run to J Hanger 9 | | 1 | | | |
| 69664 | ACTIVE | N | N095-00-6/266 | Platform 6 - Southbound Fast - Northern Line - Station Building - Euston Stn | No Access | Asbestos | No Access: Presumed | | | | Platform Invert was flooded and could not be surveyed in 2024 | | | | | |
| 70806 | ACTIVE | N | N095-00-6/266 | Platform 6 - Southbound Fast - Northern Line - Station Building - Euston Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728770 | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 69328 | ACTIVE | N | N095-00-6/266 | Platform 6 - Southbound Fast - Northern Line - Station Building - Euston Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs behind VE/ frieze panels throughout | | | R747651 | | |
| 69662 | ACTIVE | N | N095-00-6/266 | Platform 6 - Southbound Fast - Northern Line - Station Building - Euston Stn | Cable: Sheath | Asbestos | Known | | | | Platform Invert - 2x Braided cables adj hatch below switch room | | 2 | | | |
| 69666 | ACTIVE | N | N095-00-6/266 | Platform 6 - Southbound Fast - Northern Line - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill to walls, floor throughout, grout/wood/lead to tunnel ring flanges throughout, RSJ to ceiling, brickwork to walls, concrete slab to ceiling, walls, plastic cables, metal conduits and cable management system with new fire stopping and mastics, wood splinters, fibres (shuttering, panels, cut offs to concrete ceiling and walls, new electrical equipment boxes,metal access hatches & ladders. Limited access to fully inspect invert due to flooding | | | | | |
| 18106 | ACTIVE | N | N095-00-6/266/ FLR-01 | Floor - 1 - Platform 6 - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 6 Invert - Various Cables | | | | | YES |
| 9921 | ACTIVE | N | N095-00-6/381 | Passage - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15389 | ACTIVE | N | N095-00-6/381 | Passage - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 15388 | ACTIVE | N | N095-00-6/381 | Passage - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9922 | ACTIVE | N | N095-00-6/382 | Store - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9923 | ACTIVE | N | N095-00-6/383 | Store - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15390 | ACTIVE | N | N095-00-6/383 | Store - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 15391 | ACTIVE | N | N095-00-6/383 | Store - Station Building - Euston Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Boarding in storage - Non Asbestos | | | | | |
| 15393 | ACTIVE | N | N095-00-6/383 | Store - Station Building - Euston Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | 2 x Heaters - Chrysotile Insulation Boards - REMOVED | | | | | |
| 18236 | ACTIVE | N | N095-00-6/383/ CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 15392 | ACTIVE | N | N095-00-6/383/ CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Euston Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|---------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18648 | ACTIVE | N | N095-00-6/383/DOR-01 | Door - 1 - Store - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels on doors | | | | | |
| 9924 | ACTIVE | N | N095-00-6/384 | Store - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18107 | ACTIVE | N | N095-00-6/384 | Store - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9925 | ACTIVE | N | N095-00-6/385 | Store - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15473 | ACTIVE | N | N095-00-6/385 | Store - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Tunnel rings (not visible) possibly containing caulking material in flanges and joints are present behind corrugated metal sheeting forming structure of all platform tunnels at the station– Known Asbestos. No access above fixed supalux false ceiling during 2020 re-inspection. | | | | | |
| 15471 | ACTIVE | N | N095-00-6/385/CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Euston Stn | Cellactite Sheeting | Asbestos | Known | | | | Above False Ceiling - Corrugated Sheet - Chrysotile No access above fixed supalux false ceiling during 2020 re-inspection. | | | | YES | |
| 15394 | ACTIVE | N | N095-00-6/385/CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 15472 | ACTIVE | N | N095-00-6/385/CLG-02 | Ceiling: Solid - 2 - Store - Station Building - Euston Stn | Cellactite Sheeting | Asbestos | Known | | | | Above False Ceiling - Corrugated Sheet - Chrysotile No access above fixed supalux false ceiling during 2020 re-inspection. | | | | YES | |
| 19893 | ACTIVE | N | N095-00-6/385/CLG-02 | Ceiling: Solid - 2 - Store - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18252 | INACTIVE | N | N095-00-6/385/WAL-001 | Wall: Internal - 1 - Store - Station Building - Euston Stn | Vinyl tiles | Asbestos | Removed | | | | Marley Tiles on All Walls | | | | | |
| 9926 | ACTIVE | N | N095-00-6/386 | Store - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9927 | ACTIVE | N | N095-00-6/406 | Store - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15474 | ACTIVE | N | N095-00-6/406/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 15475 | ACTIVE | N | N095-00-6/406/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Euston Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | | |
| 18228 | ACTIVE | N | N095-00-6/406/CLG-02 | Ceiling: Suspended - 2 - Store - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 15476 | ACTIVE | N | N095-00-6/406/CLG-02 | Ceiling: Suspended - 2 - Store - Station Building - Euston Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | | |
| 9928 | ACTIVE | N | N095-00-6/411 | Store - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15477 | ACTIVE | N | N095-00-6/411 | Store - Station Building - Euston Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring Caulking - Non Asbestos | | | | | |
| 15478 | ACTIVE | N | N095-00-6/411/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Euston Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring Caulking - Non Asbestos | | | | | |
| 9929 | ACTIVE | N | N095-00-6/661 | Switch Cupboard - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18254 | ACTIVE | N | N095-00-6/661 | Switch Cupboard - Station Building - Euston Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box by Door - Insulation within | | 1 | | | |
| 18253 | ACTIVE | N | N095-00-6/661 | Switch Cupboard - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel above Door | | | | | |
| 15481 | ACTIVE | N | N095-00-6/661 | Switch Cupboard - Station Building - Euston Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Electrical Boxes - Insulation within | | 2 | | N | N |
| 15480 | ACTIVE | N | N095-00-6/661/CLG-01 | Ceiling: Suspended - 1 - Switch Cupboard - Station Building - Euston Stn | Cellactite Sheeting | Asbestos | Known | | | | Chrysotile Corrugated Sheet above Supalux Tiles No access above fixed supalux tiles during 2020 re-inspection. | | | | YES | |
| 15479 | ACTIVE | N | N095-00-6/661/CLG-01 | Ceiling: Suspended - 1 - Switch Cupboard - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9930 | ACTIVE | N | N095-00-6/663 | Switch Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 69683 | ACTIVE | N | N095-00-6/663 | Switch Room - Station Building - Euston Stn | Bitumen | Asbestos | Known | | | | Asbestos bitumen adhesive to floor | 12 | | R700888Rev3 | | |
| 15482 | ACTIVE | N | N095-00-6/663 | Switch Room - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel above Door | | | | | |
| 15484 | ACTIVE | N | N095-00-6/663/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Euston Stn | Cellactite Sheeting | Asbestos | Known | | | | Chrysotile Corrugated Sheet above Supalux Tiles; No access to reinspect above screwed down ceiling; No access above fixed supalux tiles during 2020 re-inspection. | | | | | |
| 15483 | ACTIVE | N | N095-00-6/663/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18642 | ACTIVE | N | N095-00-6/663/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Euston Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box by Door - Insulation within | | 1 | | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|--------------------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 9931 | ACTIVE | N | N095-00-6/664 | Switch Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18255 | ACTIVE | N | N095-00-6/664 | Switch Room - Station Building - Euston Stn | Vinyl tiles | Asbestos | No Access: Presumed | | | | Grey Vinyl Tiles on Walls - Tiles have been removed however there may be some remaining behind equipment to walls - P | | | | | |
| 25817 | ACTIVE | N | N095-00-6/664/FLR-01 | Floor - 1 - Switch Room - Station Building - Euston Stn | Vinyl tiles | Asbestos | Known | | | | Red & Grey Vinyl Tiles to Floor Sampled negative in report R19047 23/01/2002, but resampled in 2006 in report 060082 and trace amounts of asbestos were identified. | | | | | |
| 18654 | ACTIVE | N | N095-00-6/664/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Euston Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 3 x 60amp Switch Boxes - Insulation within | | | | | |
| 19478 | ACTIVE | N | N095-00-6/664/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Euston Stn | Other Boarding | Asbestos | Presumed | | | | Transformer Box by Door - Insulation within | | 1 | | | |
| 25818 | ACTIVE | N | N095-00-6/664/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Euston Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Small Controller Box W2 | | 1 | | | |
| 25819 | ACTIVE | N | N095-00-6/664/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Euston Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Large Controller W3 | | 1 | | | |
| 9932 | ACTIVE | N | N095-00-6/665 | SER - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15485 | ACTIVE | N | N095-00-6/665 | SER - Station Building - Euston Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access | | | | | |
| 9933 | ACTIVE | N | N095-00-6/666 | Switch Cupboard - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15486 | ACTIVE | N | N095-00-6/666 | Switch Cupboard - Station Building - Euston Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - new construction | | | | | |
| 9934 | ACTIVE | N | N095-00-6/711 | IMR - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15487 | ACTIVE | N | N095-00-6/711 | IMR - Station Building - Euston Stn | Vinyl tiles | Asbestos | Known | | | | Grey Marley Tiles (150m²) No access to IMR during 2020 re-inspection in traffic hours. Access is trackside off platform 6. | | | | N | N |
| 44367 | ACTIVE | N | N095-00-6/711/WAL-004 80901379 | Wall: Internal - 4 - IMR - Station Building - Euston Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | Old switch box | | 1 | | N | N |
| 9935 | ACTIVE | N | N095-00-6/712 | Relay Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15488 | ACTIVE | N | N095-00-6/712 | Relay Room - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables going into Invert - Some have been Cut Back and all have been encapsulated | | 25 | | N | N |



Hazardous Material Asset Register - Summary



| N095-00 - Station Building - Euston Stn | | | | | | | | | | | | | | | | |
|---|----------|-------------|---------------------------------------|---|------------------------|--------------------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
| 18256 | ACTIVE | N | N095-00-6/712 | Relay Room - Station Building - Euston Stn | Other Boarding | Asbestos | Strongly Presumed | | | | Paxoline Packing throughout Room | | | | N | N |
| 9936 | ACTIVE | N | N095-00-6/713 | Relay Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15489 | ACTIVE | N | N095-00-6/713 | Relay Room - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables going into Invert - Majority of cables have been removed remainder have been encapsulated; | | 25 | | | |
| 25820 | ACTIVE | N | N095-00-6/713 | Relay Room - Station Building - Euston Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline Packing Material | | | | | |
| 9937 | ACTIVE | N | N095-00-6/714 | Relay Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15490 | ACTIVE | N | N095-00-6/714 | Relay Room - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Various Cables - Some cut as they enter room, other remain live - All Encapsulated (Room Redundant - 26/06/2014) Moderate damage identified during 2020 re-inspection. Terminated cables have been encapsulated on edges. | | | | | |
| 18643 | ACTIVE | N | N095-00-6/714 | Relay Room - Station Building - Euston Stn | Other Boarding | Asbestos | Strongly Presumed | | | | Paxoline Packing throughout Room - Small amounts remain; (Room redundant - 26/06/2014) | | | | | |
| 9938 | ACTIVE | N | N095-00-6/715 | Relay Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18257 | ACTIVE | N | N095-00-6/715 | Relay Room - Station Building - Euston Stn | Other Boarding | Asbestos | Strongly Presumed | | | | Paxoline Packing throughout Room | | | | N | N |
| 15491 | ACTIVE | N | N095-00-6/715 | Relay Room - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Various Cables Moderate damage identified during 2020 re-inspection. Some cables terminated/cut with edges encapsulated. | | | | N | N |
| 9939 | ACTIVE | N | N095-00-6/716 | Relay Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18239 | ACTIVE | N | N095-00-6/716 | Relay Room - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 3no x 10mm Cables - 1no White & 2no Brown | | 3 | | N | N |
| 15492 | INACTIVE | N | N095-00-6/716 | Relay Room - Station Building - Euston Stn | PCBs | Polychlorinated biphenyl | Removed | | | | 2 x PCB's - Fair Condition Serial Nos M14160; M14185 23/02/2017 inspection Fair Condition | | 2 | | N | |
| 20334 | ACTIVE | N | N095-00-6/716/ FLR-01 | Floor - 1 - Relay Room - Station Building - Euston Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Drum type train describer - On floor centre of room | | 1 | | N | N |
| 44368 | ACTIVE | N | N095-00-6/716/ WAL-001 80901764 | Wall: Internal - 1 - Relay Room - Station Building - Euston Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | Westinghouse box | | 1 | | N | N |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|--------------------------------|---|------------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 44369 | ACTIVE | N | N095-00-6/716/WAL-001 80901764 | Wall: Internal - 1 - Relay Room - Station Building - Euston Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer box | | 1 | | N | N |
| 9940 | ACTIVE | N | N095-00-6/717 | Relay Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 53980 | ACTIVE | N | N095-00-6/717 | Relay Room - Station Building - Euston Stn | Other Boarding | Asbestos | Sampled – Not Detected | | | | square brown paxoline board | | | R729651RevC | | |
| 15493 | ACTIVE | N | N095-00-6/717 | Relay Room - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 10mm Cables | | 3 | | N | N |
| 15494 | INACTIVE | N | N095-00-6/717 | Relay Room - Station Building - Euston Stn | PCBs | Polychlorinated biphenyl | Removed | | | | 5 x PCB's - Fair Condition Serial Nos - none visible 23/02/2017 inspection Fair Condition | | 5 | | | |
| 46826 | INACTIVE | N | N095-00-6/717/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Euston Stn | Other Boarding | Asbestos | Removed | | | | Paxoline board to rack at back of room | | | | | |
| 46828 | ACTIVE | N | N095-00-6/717/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Euston Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline Board to wall 3 | | | | | |
| 46827 | ACTIVE | N | N095-00-6/717/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Euston Stn | Other Electrical Boxes | Asbestos | Presumed | | | | switch box to wall 3 at low level | | | | | |
| 9941 | ACTIVE | N | N095-00-6/718 | SER - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15495 | ACTIVE | N | N095-00-6/718 | SER - Station Building - Euston Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access | | | | | |
| 9942 | ACTIVE | N | N095-00-6/719 | SER - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15496 | ACTIVE | N | N095-00-6/719 | SER - Station Building - Euston Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - new construction | | | | | |
| 9943 | ACTIVE | N | N095-00-6/731 | CER - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15497 | ACTIVE | N | N095-00-6/731 | CER - Station Building - Euston Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline Box & Board | | | | N | N |
| 15498 | ACTIVE | N | N095-00-6/731 | CER - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 10mm Cables | | 2 | | N | N |
| 18258 | ACTIVE | N | N095-00-6/731 | CER - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Caulking to Tunnel Rings No access above false ceiling during 2020 re-inspection. | | | | Y | |
| 18240 | ACTIVE | N | N095-00-6/731/FLR-01 | Floor - 1 - CER - Station Building - Euston Stn | Vinyl tiles | Asbestos | Presumed | | | | Green Vinyl Floor Tiles | | | | N | N |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|---------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9944 | ACTIVE | N | N095-00-6/732 | CER - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15501 | ACTIVE | N | N095-00-6/732 | CER - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Tunnel rings (not visible) possibly containing caulking material in flanges and joints are present behind corrugated metal sheeting forming structure of all platform tunnels at the station– Known Asbestos. No access above fixed supalux tiles during 2020 re-inspection. | | | | Y | N |
| 19946 | ACTIVE | N | N095-00-6/732/CLG-01 | Ceiling: Suspended - 1 - CER - Station Building - Euston Stn | Cellactite Sheeting | Asbestos | Known | | | | Cellactite Corrugated Sheet above Supalux Tiles No access above fixed supalux tiles during 2020 re-inspection. | | | | Y | N |
| 15499 | ACTIVE | N | N095-00-6/732/CLG-01 | Ceiling: Suspended - 1 - CER - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 15500 | ACTIVE | N | N095-00-6/732/WAL-002 | Wall: Internal - 2 - CER - Station Building - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Asbestos cables going into floor | | 6 | | N | N |
| 9945 | ACTIVE | N | N095-00-6/733 | Switch Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15502 | ACTIVE | N | N095-00-6/733 | Switch Room - Station Building - Euston Stn | Cable: Sheath | Asbestos | Not Found during Inspection | | | | Tunnel ring j hangers contain 2 x 30mm Asbestos cables | | 2 | | | |
| 15503 | ACTIVE | N | N095-00-6/733 | Switch Room - Station Building - Euston Stn | Isolator Switches | Asbestos | Not Found during Inspection | | | | Fuse Switch | | 1 | | | |
| 18259 | ACTIVE | N | N095-00-6/733/FLR-01 | Floor - 1 - Switch Room - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Beneath - False Wooden floor No access beneath false raised floor during 2020 re-inspection. | | | | | |
| 9946 | ACTIVE | N | N095-00-6/734 | CER - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15505 | ACTIVE | N | N095-00-6/734 | CER - Station Building - Euston Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes - Insulation within | | 2 | | | |
| 15504 | ACTIVE | N | N095-00-6/734/FLR-01 | Floor - 1 - CER - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Beneath - False Wooden floor No access beneath false raised floor during 2020 re-inspection. | | | | | |
| 9947 | ACTIVE | N | N095-00-6/735 | Mess Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



| N095-00 - Station Building - Euston Stn | | | | | | | | | | | | | | | | |
|---|--------|-------------|----------------------|--|---------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
| 15508 | ACTIVE | N | N095-00-6/735 | Mess Room - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Tunnel rings (not visible) possibly containing caulking material in flanges and joints are present behind corrugated metal sheeting forming structure of all platform tunnels at the station– Known Asbestos. No access above fixed supalux ceiling during 2020 re-inspection. | | | | Y | N |
| 15506 | ACTIVE | N | N095-00-6/735 | Mess Room - Station Building - Euston Stn | Bitumen | Asbestos | Sampled – Not Detected | | | | Acoustic Panel below sink Sampled by 4-Rail Services ID Report ref R721201 - 14/11/22. Panel removed subsequently when sink replaced. | | 1 | | N | N |
| 69701 | ACTIVE | N | N095-00-6/735 | Mess Room - Station Building - Euston Stn | Other Boarding | Asbestos | Sampled – Not Detected | | | | Medium density board ceiling tiles throughout | | | R700888Rev3 | | |
| 18260 | ACTIVE | N | N095-00-6/735/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles - Screwed down | | | | | |
| 15507 | ACTIVE | N | N095-00-6/735/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Euston Stn | Cellactite Sheeting | Asbestos | Known | | | | Cellactite Corrugated Sheet above Supalux Tiles No access above fixed supalux ceiling during 2020 re-inspection. | | | | Y | N |
| 9948 | ACTIVE | N | N095-00-6/736 | CER - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15509 | ACTIVE | N | N095-00-6/736/FLR-01 | Floor - 1 - CER - Station Building - Euston Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Tiles No computer tiles are present to floor during 2020 re-inspection, only solid concrete floor. | | | | | YES |
| 9949 | ACTIVE | N | N095-00-6/737 | CER - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18644 | ACTIVE | N | N095-00-6/737 | CER - Station Building - Euston Stn | No Access | Asbestos | Room: Surveyed – No Known Asbestos | | | | Not Surveyed Management survey carried out during 2020 re-inspection. No samples taken. | | | | | |
| 9950 | ACTIVE | N | N095-00-6/738 | CER - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 69705 | ACTIVE | N | N095-00-6/738 | CER - Station Building - Euston Stn | | Asbestos | No Access: Presumed | | | | Room not previously surveyed | | | | | |
| 9951 | ACTIVE | N | N095-00-6/761 | Equipment Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15511 | ACTIVE | N | N095-00-6/761 | Equipment Room - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Caulking to Tunnel Rings No access above fixed false ceiling during 2020 re-inspection. | | | | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 19300 | ACTIVE | N | N095-00-6/761 | Equipment Room - Station Building - Euston Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Vinyl Tiles - Walls | | | | | |
| 15510 | ACTIVE | N | N095-00-6/761/CLG-01 | Ceiling: Suspended - 1 - Equipment Room - Station Building - Euston Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18261 | ACTIVE | N | N095-00-6/761/FLR-01 | Floor - 1 - Equipment Room - Station Building - Euston Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Vinyl Tiles | | | | | |
| 9952 | ACTIVE | N | N095-00-6/762 | Computer Equipment Cupboard - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9953 | ACTIVE | N | N095-00-6/763 | Computer Equipment Cupboard - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9954 | ACTIVE | N | N095-00-6/764 | Computer Equipment Cupboard - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9955 | ACTIVE | N | N095-00-6/765 | Computer Equipment Cupboard - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9956 | ACTIVE | N | N095-00-6/766 | Computer Equipment Cupboard - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9957 | ACTIVE | N | N095-00-6/767 | Computer Equipment Cupboard - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9958 | ACTIVE | N | N095-00-6/768 | Computer Equipment Cupboard - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9959 | ACTIVE | N | N095-00-6/769 | Computer Equipment Cupboard - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 69704 | ACTIVE | N | N095-00-6/791 | Vent Shaft - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | Concrete floor, bitumen ducts in manhole - Non asbestos, tiled walls, concrete ceiling | | | | | |
| 15513 | ACTIVE | N | N095-00-6/792 | Vent Shaft - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Encapsulated - Walls -Tunnel Ring - Caulking - Chrysotile | | | | | |
| 15512 | INACTIVE | N | N095-00-6/792/CLG-01 | Ceiling: Solid - 1 - Vent Shaft - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Encapsulated - Tunnel Ring - Caulking - Chrysotile | | | | | |
| 15514 | ACTIVE | N | N095-00-6/793 | Vent Shaft - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 18262 | ACTIVE | N | N095-00-6/794 | Vent Shaft - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Encapsulated - Tunnel Ring - Caulking - Amphipole | | | | | |
| 18655 | INACTIVE | N | N095-00-6/794/CLG-01 | Ceiling: Solid - 1 - Vent Shaft - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Encapsulated - Tunnel Ring - Caulking - Amphipole | | | | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18645 | ACTIVE | N | N095-00-6/795 | Vent Shaft - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 69537 | ACTIVE | N | N095-00-6/796 | Vent Shaft - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | 8x Metal ducts to ceiling at end of tunnel | | | R636526 | | |
| 15515 | ACTIVE | N | N095-00-6/796 | Vent Shaft - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | VP78A - Vent Tunnel: An Asbestos management survey was carried out within this location. Refer to 4-Rail Services Report R636526. Concrete slab to floor, to entry wall and ceiling, metal grill to door, cast iron tunnel rings to vent tunnel (wood and grout caulking throughout to TR joints, metal pipe and PVC cable at entrance passage, concrete render to tunnel ring pan, metal pipe, bracket and pvc cables to tunnel ring pan. metal ducts | | | | | |
| 69535 | ACTIVE | N | N095-00-6/796 | Vent Shaft - Station Building - Euston Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | 1x Bitumen duct under floor/steps and entrance | | | R636526 | | |
| 69536 | ACTIVE | N | N095-00-6/796 | Vent Shaft - Station Building - Euston Stn | | Asbestos | Sampled – Not Detected | | | | Wood and grout caulking to tunnel ring joints throughout | | | R636526 | | |
| 69538 | ACTIVE | N | N095-00-6/796 | Vent Shaft - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | VP78A - Vent tunnel - Level 1: An asbestos management survey was carried out on the vent tunnel. Refer to 4-Rail Services Report R636526. Concrete render on tunnel ring to vent tunnel slope, concrete and tile to chimney to shaft, metal hand rail, concrete slab, concrete render and tiles to vent tunnel, paving slab to floor level 1, metal grill to platform exit, high level ceiling, brickwork to wals in tunnel , concrete floor. | | | R636526 | | |
| 15517 | ACTIVE | N | N095-00-6/797 | Vent Shaft - Station Building - Euston Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring Caulking - Non Asbestos | | | | | |
| 18241 | ACTIVE | N | N095-00-6/798/CLG-01 | Ceiling: Solid - 1 - Vent Shaft - Station Building - Euston Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Too High No access to high level ceiling during 2020 re-inspection. | | | | | |
| 15518 | ACTIVE | N | N095-00-6/799 | Vent Shaft - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 18649 | ACTIVE | N | N095-00-6/800 | Vent Shaft - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Wall - Tunnel Ring - Caulking - Chrysotile Slight damage identified during 2020 re-inspection. | | | | | |
| 18171 | INACTIVE | N | N095-00-6/800/CLG-01 | Ceiling: Solid - 1 - Vent Shaft - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Tunnel Ring - Caulking - Chrysotile | | | | | |
| 9960 | ACTIVE | N | N095-00-6/951 | Kitchen - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|---------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18237 | ACTIVE | N | N095-00-6/951 | Kitchen - Station Building - Euston Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring - Caulking | | | | | |
| 15396 | ACTIVE | N | N095-00-6/951 | Kitchen - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 9961 | ACTIVE | N | N095-00-6/952 | Mess Room - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15397 | ACTIVE | N | N095-00-6/952 | Mess Room - Station Building - Euston Stn | Caulking | Asbestos | Known | | | | Tunnel Ring - Caulking No access above fixed false ceiling during 2020 re-inspection. | | | | | |
| 69539 | ACTIVE | N | N095-00-6/981 | Vent Shaft - Station Building - Euston Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Wood and grout caulking to tunnel ring joints throughout | | | R636526 | | |
| 15395 | ACTIVE | N | N095-00-6/981 | Vent Shaft - Station Building - Euston Stn | | Asbestos | Surveyed – Not Detected | | | | Concrete slab to entrance walls and ceiling, wooden door and breezeblock construction to room 6/411, metal pipe and PVC cables throughout, cast iron tunnel rings, wood and grout caulking to ring joints throughout, concrete steps to access level 1 of 6/796, concrete ceiling, to access stairs. | | | | | |
| 69697 | ACTIVE | N | N095-00-6/981 | Vent Shaft - Station Building - Euston Stn | Bitumen | Asbestos | Sampled – Not Detected | | | | Bitumen adhesive <50m | | | R700888Rev3 | | |
| 9962 | ACTIVE | N | N095-00-B/901 | Vent Shaft - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9963 | ACTIVE | N | N095-00-B/902 | Vent Shaft - Station Building - Euston Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 46686 | ACTIVE | N | N095/00/CS278 | Shaft: Cable - SH/CS278 - NOR Line - Euston Stn | Caulking | Asbestos | Known | | | | CS278B - 22Kv Cable Shaft Encapsulated Tunnel rings throughout shaft and tunnels at bottom of shaft | | | R705151 | | |
| 46689 | ACTIVE | N | N095/00/CS278 | Shaft: Cable - SH/CS278 - NOR Line - Euston Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | CS278B - 22Kv Cable Shaft Asbestos components within Switch Box - Bottom of Shaft | | 1 | R705151 | | |
| 46690 | ACTIVE | N | N095/00/CS278 | Shaft: Cable - SH/CS278 - NOR Line - Euston Stn | Cable Ducts: Cement | Asbestos | Known | | | | CS278B - 22Kv Cable Shaft 2no Cement Ducts to Bottom of Shaft | | 2 | R705151 | | |
| 46692 | ACTIVE | N | N095/00/CS278 | Shaft: Cable - SH/CS278 - NOR Line - Euston Stn | Other Boarding | Asbestos | Sampled – Not Detected | | | | CS278B - 22Kv Cable Shaft Insulating Blocks to floor where cables penetrate into shaft (2x 2m²) - Top of Shaft | | 2 | R705151 | | |
| 46693 | ACTIVE | N | N095/00/CS278 | Shaft: Cable - SH/CS278 - NOR Line - Euston Stn | No Access | Asbestos | Presumed | | | | CS278B - 22Kv Cable Shaft Note on Access Tunnel area at bottom of shaft accessed as far as reasonably practicable. Access eventually blocked by narrow cable runs and vicinity to live track. | | | R705151 | | |



Hazardous Material Asset Register - Summary



N095-00 - Station Building - Euston Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|----------------------|---------------|------------------------|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 46687 | ACTIVE | N | N095/00/CS278 | Shaft: Cable - SH/CS278 - NOR Line - Euston Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | CS278B - 22Kv Cable Shaft Various Braided (+8) Asbestos Sheathed Cables in vertical cable Run down shaft | | 8 | R705151 | | |
| 46688 | ACTIVE | N | N095/00/CS278 | Shaft: Cable - SH/CS278 - NOR Line - Euston Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | CS278B - 22kv Cable Shaft Bitumen Ducts (18no) within chamber area beneath durasteel doors | | 18 | R705151 | | |
| 46691 | ACTIVE | N | N095/00/CS278 | Shaft: Cable - SH/CS278 - NOR Line - Euston Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | CS278B - 22Kv Cable Shaft Durasteel to 3m ² to Floor and Doors (2x 1m ²) to shaft entrances to floor - top of shaft | | | R705151 | | |

N101-00 - Station Building - Warren Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|---------------------|---------------|-------------------------|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 68134 | ACTIVE | N | N101-00-1/071/CLG-02 | Ceiling: Suspended - 1 - Circulation Area - Station Building - Warren Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs above false ceiling | | | R648026 | Y | |
| 68133 | ACTIVE | N | N101-00-1/238/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Warren Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs above false ceiling | | | R648026 | Y | |
| 68135 | ACTIVE | N | N101-00-1/751/CLG-01 | Ceiling: Suspended - 1 - Station Control Room - Station Building - Warren Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs above false ceiling | | | R648026 | Y | |
| 68153 | ACTIVE | N | N101-00-2/331 | Mess/Locker - Station Building - Warren Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs above false ceiling | | | R679606 | Y | |
| 68154 | ACTIVE | N | N101-00-2/416 | Toilet - Station Building - Warren Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs above false ceiling | | | R679606 | Y | |
| 68165 | ACTIVE | N | N101-00-3/081 | Circulation Area - Station Building - Warren Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs behind the VE/ frieze panels | | | R679606 | | |
| 68164 | ACTIVE | N | N101-00-3/092 | Circulation Area - Station Building - Warren Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs behind the VE/ frieze panels | | | R679606 | | |
| 68150 | ACTIVE | N | N101-00-3/093 | Circulation Area - Station Building - Warren Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs behind VE/ frieze panels | | | R679606 | | |
| 68166 | ACTIVE | N | N101-00-3/093 | Circulation Area - Station Building - Warren Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs behind the VE/ frieze panels | | | R679606 | | |
| 68138 | ACTIVE | N | N101-00-3/202 | Passage - Station Building - Warren Street Stn | Cellactite Sheeting | Asbestos | Known | | | | Cellactite to ceiling above false ceiling behind head wall to 3/093 | 2 | | R679606 | Y | |
| 68136 | ACTIVE | N | N101-00-3/202 | Passage - Station Building - Warren Street Stn | Caulking | Asbestos | Known | | | | Caulking throughout to tunnel ring joints behind VE/frieze panels | 50 | | R679606 | | |
| 68137 | ACTIVE | N | N101-00-3/202 | Passage - Station Building - Warren Street Stn | Cellactite Sheeting | Asbestos | Known | | | | Cellactite up to top of wall behind VE/frieze panels | 1 | | R679606 | | |



Hazardous Material Asset Register - Summary



N101-00 - Station Building - Warren Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|---------------------|---------------|-------------------------|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 68152 | ACTIVE | N | N101-00-3/203 | Passage - Station Building - Warren Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs behind VE/ frieze panels | | | R679606 | | |
| 68151 | ACTIVE | N | N101-00-3/204 | Passage - Station Building - Warren Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs behind VE/ frieze panels | | | R679606 | | |
| 68139 | ACTIVE | N | N101-00-3/751 | Office - Station Building - Warren Street Stn | Cellactite Sheeting | Asbestos | Known | | | | Cellactite throughout to ceiling above false ceiling | 25 | | R679606 | Y | |
| 68162 | ACTIVE | N | N101-00-4/081 | Circulation Area - Station Building - Warren Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs behind the VE/ frieze panels | | | R679606 | | |
| 68169 | ACTIVE | N | N101-00-4/201 | Circulation Area - Station Building - Warren Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs above false ceiling | | | R679606 | | |
| 68167 | ACTIVE | N | N101-00-4/202 | Circulation Area - Station Building - Warren Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs above false ceiling | | | R679606 | Y | |
| 68168 | ACTIVE | N | N101-00-4/203 | Passage - Station Building - Warren Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs behind VE/ frieze panels | | | R679606 | | |
| 68155 | ACTIVE | N | N101-00-4/204 | Passage - Station Building - Warren Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs behind VE/ frieze panels | | | R679606 | | |
| 68158 | ACTIVE | N | N101-00-4/601 | Stairs: Linear - Station Building - Warren Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs behind VE/ frieze panels | | | R679606 | | |
| 68171 | ACTIVE | N | N101-00-4/603 | Stairs: Linear - Station Building - Warren Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs above false ceiling | | | R679606 | | |
| 68170 | ACTIVE | N | N101-00-4/604 | Stairs: Linear - Station Building - Warren Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs behind VE/ frieze panels | | | R679606 | | |
| 68161 | ACTIVE | N | N101-00-4/636 | Overbridge - Station Building - Warren Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs behind the VE/ frieze panels | | | R679606 | | |
| 68157 | ACTIVE | N | N101-00-4/637 | Overbridge - Station Building - Warren Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs behind VE/ frieze panels | | | R679606 | | |
| 68147 | ACTIVE | N | N101-00-5/261 | Platform 1 - Station Building - Warren Street Stn | Caulking | Asbestos | Strongly Presumed | | | | Strongly presumed caulking - Visible in a few cavities in the wall behind the VE/frieze panels | 3 | | R679606 | | |
| 68148 | ACTIVE | N | N101-00-5/262 | Platform 2 - Station Building - Warren Street Stn | Caulking | Asbestos | Strongly Presumed | | | | Strongly presumed caulking - Visible in a few cavities in the wall behind the VE/frieze panels | 3 | | R679606 | | |
| 68160 | ACTIVE | N | N101-00-6/081 | Circulation Area - Station Building - Warren Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs behind the VE/ frieze panels | | | R679606 | | |
| 68140 | ACTIVE | N | N101-00-6/202 | Circulation Area - Station Building - Warren Street Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Strongly presumed asbestos braided cable to cable bundle to wall above 6/301 above false ceiling | | 1 | R679606 | Y | |
| 68142 | ACTIVE | N | N101-00-6/202 | Circulation Area - Station Building - Warren Street Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Strongly presumed asbestos braided cables throughout behind VE/frieze panels | | 3 | R679606 | | |
| 68141 | ACTIVE | N | N101-00-6/202 | Circulation Area - Station Building - Warren Street Stn | Cellactite Sheeting | Asbestos | Known | | | | Cellactite throughout at low level behind VE/frieze panels | 1 | | R679606 | | |



Hazardous Material Asset Register - Summary



N101-00 - Station Building - Warren Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|----------------------|---------------|-------------------------|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 68144 | ACTIVE | N | N101-00-6/202 | Circulation Area - Station Building - Warren Street Stn | Caulking | Asbestos | Strongly Presumed | | | | Strongly presumed caulking to exposed tunnel ring joint at high level in ceiling void to 6/204 | 5 | | R679606 | Y | |
| 68143 | ACTIVE | N | N101-00-6/202 | Circulation Area - Station Building - Warren Street Stn | Caulking | Asbestos | Strongly Presumed | | | | Strongly presumed caulking to exposed tunnel ring joint behind last VE/frieze panel to 6/081 | 1 | | R679606 | | |
| 68145 | ACTIVE | N | N101-00-6/204 | Passage - Station Building - Warren Street Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Strongly presumed asbestos braided cables to ceiling void to cable bundles | | 4 | R679606 | Y | |
| 68146 | ACTIVE | N | N101-00-6/209 | Passage - Station Building - Warren Street Stn | Caulking | Asbestos | Known | | | | Caulking throughout to tunnel ring joints above high level panels in the middle of passage (Caulking is encapsulated) | 50 | | R679606 | | |
| 68159 | ACTIVE | N | N101-00-6/261 | Platform 3 - Station Building - Warren Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs behind VE/ frieze panels | | | R679606 | | |
| 70121 | ACTIVE | N | N101-00-6/261 | Platform 3 - Station Building - Warren Street Stn | Cable Sheath | Asbestos | Known | | | | Invert - Braided cables - total 22 no - To J Hanger throughout over track crossing | | 22 | R718701 | | |
| 70120 | ACTIVE | N | N101-00-6/261 | Platform 3 - Station Building - Warren Street Stn | Cable Ducts: Cement | Asbestos | Known | | | | Invert - Cement cable ducts - total 8 no - To trackside wall and head wall | | 8 | R718701 | | Y |
| 70124 | ACTIVE | N | N101-00-6/261 | Platform 3 - Station Building - Warren Street Stn | Cable Ducts: Cement | Asbestos | Known | | | | Invert - Cement cable ducts - total 2 x 5 no - To dividing wall | | 10 | R718701 | | Y |
| 70123 | ACTIVE | N | N101-00-6/261 | Platform 3 - Station Building - Warren Street Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Invert - Materials within small Westinghouse box - total 1 no - To trackside wall and head wall | | 1 | R718701 | | |
| 70122 | ACTIVE | N | N101-00-6/261 | Platform 3 - Station Building - Warren Street Stn | Cable Ducts: Cement | Asbestos | Known | | | | Invert - Cement cable ducts - total 2 no - To middle wall | | 2 | R718701 | | Y |
| 70119 | ACTIVE | N | N101-00-6/261 | Platform 3 - Station Building - Warren Street Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R718701 | | |
| 70118 | ACTIVE | N | N101-00-6/261 | Platform 3 - Station Building - Warren Street Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Invert - Metal tunnel rings - concrete infill - To walls, floor | | | R718701 | | |
| 70125 | ACTIVE | N | N101-00-6/261 | Platform 3 - Station Building - Warren Street Stn | Cable Ducts: Cement | Asbestos | Known | | | | Invert - Cement cable ducts - total 2 x 8 no - To dividing wall | | 16 | R718701 | | Y |
| 70126 | ACTIVE | N | N101-00-6/261 | Platform 3 - Station Building - Warren Street Stn | Cable Ducts: Cement | Asbestos | Known | | | | Invert - Cement cable ducts - total 8 no - To trackside wall and tail wall | | 8 | R718701 | | Y |
| 70114 | ACTIVE | N | N101-00-6/262 | Platform 4 - Station Building - Warren Street Stn | Cable Ducts: Cement | Asbestos | Known | | | | Invert - Cement cable ducts - total 2 x 5 no - To dividing wall | | 10 | R718701 | | Y |
| 70115 | ACTIVE | N | N101-00-6/262 | Platform 4 - Station Building - Warren Street Stn | Cable Ducts: Cement | Asbestos | Known | | | | Invert - Cement cable ducts - total 2 x 5 no - To dividing wall | | 10 | R718701 | | Y |
| 70111 | ACTIVE | N | N101-00-6/262 | Platform 4 - Station Building - Warren Street Stn | Cable Sheath | Asbestos | Known | | | | Invert - Braided cables - total 22 no - To J Hangers throughout both sides | | 22 | R718701 | | |
| 70110 | ACTIVE | N | N101-00-6/262 | Platform 4 - Station Building - Warren Street Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R718701 | | |
| 70113 | ACTIVE | N | N101-00-6/262 | Platform 4 - Station Building - Warren Street Stn | Cable Ducts: Cement | Asbestos | Known | | | | Invert - Cement cable ducts - total 2 no - To dividing wall | | 2 | R718701 | | Y |



Hazardous Material Asset Register - Summary



N101-00 - Station Building - Warren Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|----------------------|---------------|------------------------|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 70112 | ACTIVE | N | N101-00-6/262 | Platform 4 - Station Building - Warren Street Stn | Cable Ducts: Cement | Asbestos | Known | | | | Invert - Cement cable ducts - total 8 no - To trackside wall and head wall | | 8 | R718701 | | Y |
| 68149 | ACTIVE | N | N101-00-6/262 | Platform 4 - Station Building - Warren Street Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Strongly presumed asbestos braided cables throughout to low level cable bundle behind VE/frieze panels | | 1 | R679606 | | |
| 70117 | ACTIVE | N | N101-00-6/262 | Platform 4 - Station Building - Warren Street Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Invert - Materials within small Westinghouse box - total 1 no - Trackside throughout | | 1 | R718701 | | |
| 70116 | ACTIVE | N | N101-00-6/262 | Platform 4 - Station Building - Warren Street Stn | Cable Ducts: Cement | Asbestos | Known | | | | Invert - Cement cable ducts - total 8 no - To trackside and head wall | | 8 | R718701 | | Y |
| 70109 | ACTIVE | N | N101-00-6/262 | Platform 4 - Station Building - Warren Street Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Invert - Metal tunnel rings - concrete infill - To walls, floor | | | R718701 | | |

N103-00 - Station Building - Goodge Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 9966 | ACTIVE | N | N103-00-1/001 | Booking Hall - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19444 | ACTIVE | N | N103-00-1/001/CLG-01 | Ceiling: Solid - 1 - Booking Hall - Station Building - Goodge Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 19425 | ACTIVE | N | N103-00-1/001/CLG-01 | Ceiling: Solid - 1 - Booking Hall - Station Building - Goodge Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9967 | ACTIVE | N | N103-00-1/011 | Ticket Office - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19319 | ACTIVE | N | N103-00-1/011/CLG-01 | Ceiling: Solid - 1 - Ticket Office - Station Building - Goodge Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 20115 | ACTIVE | N | N103-00-1/011/CLG-01 | Ceiling: Solid - 1 - Ticket Office - Station Building - Goodge Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 20116 | ACTIVE | N | N103-00-1/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Goodge Street Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |
| 9968 | ACTIVE | N | N103-00-1/021 | POM - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19228 | ACTIVE | N | N103-00-1/021/FLR-01 | Floor - 1 - POM - Station Building - Goodge Street Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |
| 9969 | ACTIVE | N | N103-00-1/071 | Circulation Area - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N103-00 - Station Building - Goodge Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 20117 | ACTIVE | N | N103-00-1/071 | Circulation Area - Station Building - Goodge Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels by Lift | | | | | |
| 42448 | ACTIVE | N | N103-00-1/136 | Lift Shaft - Station Building - Goodge Street Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | Lift Shaft 3&4 - 8m ² Durasteel panels behind control panel and above doors to top and bottom of lift shaft | 8 | | R504226 | N | N |
| 44155 | ACTIVE | N | N103-00-1/136 | Lift Shaft - Station Building - Goodge Street Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | Durasteel panel, 3m ² , behind lift control panel sandwiched between tiles and metal frame in Lift 1&2 1/136 at Goodge Street Station | | | R607276 | N | N |
| 43111 | ACTIVE | N | N103-00-1/136 | Lift Shaft - Station Building - Goodge Street Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | Durasteel panel No. 2, 1.5m ² , to middle of access door – street level, Lift Shaft 3&4, | | | R511077 | N | N |
| 42449 | ACTIVE | N | N103-00-1/136 | Lift Shaft - Station Building - Goodge Street Stn | Cable: Sheath | Asbestos | Sampled – Not Detected | | | | Lift Shaft 3&4 - 2 x 4 no. braided cables (tracking) between lift cars 3 and 4 | | 8 | R504226 | N | N |
| 43112 | ACTIVE | N | N103-00-1/136 | Lift Shaft - Station Building - Goodge Street Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | Durasteel panel No. 1, 1.5m ² , to middle of access door – low level, Lift Shaft 3&4, | | | R511077 | N | N |
| 43110 | ACTIVE | N | N103-00-1/136 | Lift Shaft - Station Building - Goodge Street Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | Durasteel panel No. 1, 1.5m ² , to middle of access door – street level, Lift Shaft 3&4, | | | R511077 | N | N |
| 20118 | ACTIVE | N | N103-00-1/136 | Lift Shaft - Station Building - Goodge Street Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access | | | | | |
| 42450 | ACTIVE | N | N103-00-1/137 | Lift Shaft - Station Building - Goodge Street Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | Lift Shaft 1&2 - 8m ² Durasteel panels behind control panel and above doors to top and bottom of lift shaft - NAD as per report R504226. | 8 | | R504226 | N | N |
| 20119 | ACTIVE | N | N103-00-1/137 | Lift Shaft - Station Building - Goodge Street Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access | | | | | |
| 43106 | ACTIVE | N | N103-00-1/137 | Lift Shaft - Station Building - Goodge Street Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | Durasteel partel No. 2, 1.5m ² , to middle of access door – street level, Lift Shaft 1&2, | | | R511077 | N | N |
| 43108 | ACTIVE | N | N103-00-1/137 | Lift Shaft - Station Building - Goodge Street Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | Durasteel panel No. 2, 1.5m ² , surrounded of exit door, Lift Shaft 1&2 | | | R511077 | N | N |
| 42451 | ACTIVE | N | N103-00-1/137 | Lift Shaft - Station Building - Goodge Street Stn | Cable: Sheath | Asbestos | Sampled – Not Detected | | | | Lift Shaft 1&2 - 2 x 4no. braided cables (tracking) between lift cars 1 and 2 - NAD as per report R504226. | | 8 | R504226 | N | N |
| 43107 | ACTIVE | N | N103-00-1/137 | Lift Shaft - Station Building - Goodge Street Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | Durasteel partel No. 1, 1.5m ² , to middle access panel, access door – low level, Lift Shaft 1&2, | | | R511077 | N | N |
| 43109 | ACTIVE | N | N103-00-1/137 | Lift Shaft - Station Building - Goodge Street Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Caulking, throughout, Lift Shaft 1&2, | | | R511077 | N | N |
| 43105 | ACTIVE | N | N103-00-1/137 | Lift Shaft - Station Building - Goodge Street Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | Durasteel panel No. 1, 1.5m ² , to middle of access door – street level, Lift Shaft 1&2, | | | R511077 | N | N |
| 9970 | ACTIVE | N | N103-00-1/201 | Passage - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20120 | ACTIVE | N | N103-00-1/201 | Passage - Station Building - Goodge Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Access Hatches | | | | | |



Hazardous Material Asset Register - Summary



N103-00 - Station Building - Goodge Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 9971 | ACTIVE | N | N103-00-1/236 | Lobby - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20122 | ACTIVE | N | N103-00-1/236/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Goodge Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Fibreglass Lagging to Pipes above Supalux Tiles | | | | YES | |
| 20121 | ACTIVE | N | N103-00-1/236/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Goodge Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 19229 | ACTIVE | N | N103-00-1/236/FLR-01 | Floor - 1 - Lobby - Station Building - Goodge Street Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |
| 9972 | ACTIVE | N | N103-00-1/237 | Passage - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20123 | ACTIVE | N | N103-00-1/237 | Passage - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9973 | ACTIVE | N | N103-00-1/401 | Bin Store - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20124 | ACTIVE | N | N103-00-1/401 | Bin Store - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9974 | ACTIVE | N | N103-00-1/416 | Toilet: Unisex - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20170 | ACTIVE | N | N103-00-1/416 | Toilet: Unisex - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9975 | ACTIVE | N | N103-00-1/451 | CER - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Ne Access 08 Oct 2014 | | | | | |
| 70563 | ACTIVE | N | N103-00-1/451 | CER - Station Building - Goodge Street Stn | Textured Coating | Asbestos | Sampled – Not Detected | | | | Textured coating to walls throughout | 20 | | R727478 | | |
| 70564 | ACTIVE | N | N103-00-1/451 | CER - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | Ceramic tiles to floor, plaster on brick/block to walls, wooden doors and framework to wall 4, plaster on solid to ceiling, modern electrical equipment. | | | R727478 | | |
| 20171 | ACTIVE | N | N103-00-1/451 | CER - Station Building - Goodge Street Stn | No Access | Asbestos | No Access: Presumed | | | | No access to high level ceiling, access blocked by services throughout room, No access to inspect high level boxing | | | | | |
| 9976 | ACTIVE | N | N103-00-1/452 | Tenancy - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19283 | ACTIVE | N | N103-00-1/452 | Tenancy - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



| N103-00 - Station Building - Goodge Street Stn | | | | | | | | | | | | | | | | |
|--|--------|-------------|---------------------------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
| 9977 | ACTIVE | N | N103-00-1/631 | Stairs: Spiral - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19741 | ACTIVE | N | N103-00-1/631 | Stairs: Spiral - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9978 | ACTIVE | N | N103-00-1/661 | Switch Room - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44189 | ACTIVE | N | N103-00-1/661/ WAL-001 80895486 | Wall: Internal - 1 - Switch Room - Station Building - Goodge Street Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 x switch box No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 20173 | ACTIVE | N | N103-00-1/661/ WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Goodge Street Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | 4 x Transformer Boxes No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 4 | | N | N |
| 19284 | ACTIVE | N | N103-00-1/661/ WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Goodge Street Stn | Other Electrical Boxes | Asbestos | Removed | | | | 1 x Transformer Box - removed by others | | 1 | | | |
| 20172 | ACTIVE | N | N103-00-1/661/ WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Goodge Street Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Blue Switch Boxes - Insulation within 6 x 60, 1 x 100 1x 200 amps No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 8 | | N | N |
| 9979 | ACTIVE | N | N103-00-1/761 | SVC - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20174 | ACTIVE | N | N103-00-1/761 | SVC - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9980 | ACTIVE | N | N103-00-1/902 | Void - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20175 | ACTIVE | N | N103-00-1/902 | Void - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9981 | ACTIVE | N | N103-00-1/903 | Void - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20176 | ACTIVE | N | N103-00-1/903 | Void - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9982 | ACTIVE | N | N103-00-1/904 | Void - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N103-00 - Station Building - Goodge Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 20177 | ACTIVE | N | N103-00-1/904 | Void - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9983 | ACTIVE | N | N103-00-1/905 | Void - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19742 | ACTIVE | N | N103-00-1/905 | Void - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9984 | ACTIVE | N | N103-00-1/906 | Void - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20178 | ACTIVE | N | N103-00-1/906 | Void - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9985 | ACTIVE | N | N103-00-2/053 | Mess Room - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20181 | ACTIVE | N | N103-00-2/053 | Mess Room - Station Building - Goodge Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Internal panel to wall cavity - plasterboard | | | | | |
| 20179 | ACTIVE | N | N103-00-2/053 | Mess Room - Station Building - Goodge Street Stn | LUL Heaters | Asbestos | No Access: Presumed | | | | LU Heater Foam Backing | | | | | |
| 20180 | ACTIVE | N | N103-00-2/053/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Goodge Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 19285 | ACTIVE | N | N103-00-2/053/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Goodge Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9986 | ACTIVE | N | N103-00-2/081 | Lobby - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20183 | ACTIVE | N | N103-00-2/081/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Goodge Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 20182 | ACTIVE | N | N103-00-2/081/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Goodge Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9987 | ACTIVE | N | N103-00-2/082 | Lobby - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20184 | ACTIVE | N | N103-00-2/082 | Lobby - Station Building - Goodge Street Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater White Foam Backing | | | | | |
| 19743 | ACTIVE | N | N103-00-2/082/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Goodge Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |



Hazardous Material Asset Register - Summary



N103-00 - Station Building - Goodge Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|-------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 19286 | ACTIVE | N | N103-00-2/082/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Goodge Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9988 | ACTIVE | N | N103-00-2/236 | Lobby - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19892 | INACTIVE | N | N103-00-2/236 | Lobby - Station Building - Goodge Street Stn | Lead/Leading | Lead Paint/Lead | Known | | | | White Oil Based Paint - Girder. Thickness .26mm; Est Quantity 3lm; Analysis 9.29%. Not found upon re inspection 08/10/2014 | | | | | |
| 20185 | ACTIVE | N | N103-00-2/236/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Goodge Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 20187 | ACTIVE | N | N103-00-2/236/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Goodge Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Fibreboard Tiles | | | | YES | |
| 20186 | ACTIVE | N | N103-00-2/236/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Goodge Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 9989 | ACTIVE | N | N103-00-2/237 | Passage - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19287 | ACTIVE | N | N103-00-2/237 | Passage - Station Building - Goodge Street Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux Insulation Board | | | | | |
| 20188 | ACTIVE | N | N103-00-2/237 | Passage - Station Building - Goodge Street Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Black Oil Based Paint - Pipework. Thickness .27mm; Est Quantity 3lm; Analysis 2.38% | | | | N | N |
| 9990 | ACTIVE | N | N103-00-2/291 | Station Supervisor Office - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 25824 | ACTIVE | N | N103-00-2/291 | Station Supervisor Office - Station Building - Goodge Street Stn | Lead/Leading | Lead Paint/Lead | Presumed | | | | Upon re inspection 08/10/14 it was noted that a white oil based painted Girder is present. | | | | N | N |
| 20189 | ACTIVE | N | N103-00-2/291/CLG-01 | Ceiling: Solid - 1 - Station Supervisor Office - Station Building - Goodge Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 19812 | ACTIVE | N | N103-00-2/291/CLG-01 | Ceiling: Solid - 1 - Station Supervisor Office - Station Building - Goodge Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Fibreboard Tiles | | | | YES | |
| 9991 | ACTIVE | N | N103-00-2/292 | Switch Room - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20190 | ACTIVE | N | N103-00-2/292/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Goodge Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |



Hazardous Material Asset Register - Summary



N103-00 - Station Building - Goodge Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 19288 | ACTIVE | N | N103-00-2/292/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Goodge Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 9992 | ACTIVE | N | N103-00-2/351 | Locker Room - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19320 | ACTIVE | N | N103-00-2/351/CLG-01 | Ceiling: Solid - 1 - Locker Room - Station Building - Goodge Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 20191 | ACTIVE | N | N103-00-2/351/CLG-01 | Ceiling: Solid - 1 - Locker Room - Station Building - Goodge Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9993 | ACTIVE | N | N103-00-2/406 | Store - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20192 | ACTIVE | N | N103-00-2/406 | Store - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9994 | ACTIVE | N | N103-00-2/411 | Store - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20193 | ACTIVE | N | N103-00-2/411 | Store - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9995 | ACTIVE | N | N103-00-2/416 | Toilet: Male - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20194 | ACTIVE | N | N103-00-2/416/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Goodge Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 19289 | ACTIVE | N | N103-00-2/416/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Goodge Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 9996 | ACTIVE | N | N103-00-2/417 | Toilet: Female - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20081 | ACTIVE | N | N103-00-2/417/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Goodge Street Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Tiles | | | | YES | |
| 19190 | ACTIVE | N | N103-00-2/417/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Goodge Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 9997 | ACTIVE | N | N103-00-2/631 | Stairs: Spiral - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N103-00 - Station Building - Goodge Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 19191 | ACTIVE | N | N103-00-2/631 | Stairs: Spiral - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 9998 | ACTIVE | N | N103-00-2/666 | Switch Room - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19192 | ACTIVE | N | N103-00-2/666/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Goodge Street Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 4 x 60, 2 x 100 amp Switch Boxes - Insulation within No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 6 | | N | N |
| 25825 | ACTIVE | N | N103-00-2/666/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Goodge Street Stn | Other Electrical Boxes | Asbestos | Presumed | | | | W3 - 1 x Transformer Box No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 9999 | ACTIVE | N | N103-00-2/667 | Switch Room - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19193 | ACTIVE | N | N103-00-2/667/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Goodge Street Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 4 x 60, 1 x 200, 1 x 100amp Switch Boxes - Insulation within No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 6 | | N | N |
| 25826 | ACTIVE | N | N103-00-2/667/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Goodge Street Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | W2 - 1 x 30amp Red Switch Box No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 10000 | ACTIVE | N | N103-00-2/668 | Switch Cupboard - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19194 | ACTIVE | N | N103-00-2/668/WAL-001 | Wall: Internal - 1 - Switch Cupboard - Station Building - Goodge Street Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 x 300amp Grey Switch Boxes - Insulation within No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 10001 | ACTIVE | N | N103-00-2/669 | Switch Room - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20082 | ACTIVE | N | N103-00-2/669 | Switch Room - Station Building - Goodge Street Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 10002 | ACTIVE | N | N103-00-2/731 | CER - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N103-00 - Station Building - Goodge Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 20083 | ACTIVE | N | N103-00-2/731/CLG-01 | Ceiling: Solid - 1 - CER - Station Building - Goodge Street Stn | Other Boarding | Asbestos | Presumed | | | | Boxing to Beams Re-inspected by 4-Rail 22-03-2023 (possible supalux, no access to inspect closely) | | | | N | N |
| 19195 | ACTIVE | N | N103-00-2/731/CLG-01 | Ceiling: Solid - 1 - CER - Station Building - Goodge Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Supalux panel above door | | | | | |
| 19596 | ACTIVE | N | N103-00-2/731/FLR-01 | Floor - 1 - CER - Station Building - Goodge Street Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |
| 19197 | ACTIVE | N | N103-00-2/731/WAL-002 | Wall: Internal - 2 - CER - Station Building - Goodge Street Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline Boarding Re-inspected by 4-Rail 22-03-2023 | | 1 | | N | N |
| 19196 | ACTIVE | N | N103-00-2/731/WAL-005 | Wall: Internal - 5 - CER - Station Building - Goodge Street Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 2 x 60amp Grey Switch Boxes - Insulation within No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 2 | | N | N |
| 10003 | ACTIVE | N | N103-00-2/732 | Switch Room - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19199 | INACTIVE | N | N103-00-2/732 | Switch Room - Station Building - Goodge Street Stn | Isolator Switches | Asbestos | Removed | | | | 2 x Grey Switch Boxes - Insulation within Not found upon re inspection 08/10/2014 - Removed | | 2 | | | |
| 19198 | ACTIVE | N | N103-00-2/732/FLR-01 | Floor - 1 - Switch Room - Station Building - Goodge Street Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | |
| 19200 | ACTIVE | N | N103-00-2/732/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Goodge Street Stn | Other Boarding | Asbestos | Presumed | | | | Panels High Level Re-inspected by 4-Rail Services, possible supalux but limited access to check 22-03-2023 | | | | N | N |
| 10004 | ACTIVE | N | N103-00-2/746 | SCR - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20084 | ACTIVE | N | N103-00-2/746/CLG-01 | Ceiling: Solid - 1 - SCR - Station Building - Goodge Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 19201 | ACTIVE | N | N103-00-2/746/CLG-01 | Ceiling: Solid - 1 - SCR - Station Building - Goodge Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 19418 | ACTIVE | N | N103-00-2/746/CLG-02 | Ceiling: Suspended - 2 - SCR - Station Building - Goodge Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 19202 | ACTIVE | N | N103-00-2/746/CLG-02 | Ceiling: Suspended - 2 - SCR - Station Building - Goodge Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 10005 | ACTIVE | N | N103-00-2/776 | Fan Room - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N103-00 - Station Building - Goodge Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|------------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 67618 | ACTIVE | N | N103-00-2/776 | Fan Room - Station Building - Goodge Street Stn | No Access | Asbestos | No Access: Presumed | | | | No access behind supalux boarding to vent equipment. panel was sampled and confirmed to be non asbestos, however a void behind with more boarding was visible looking through hole in board. Unable to sample to confirm non asbestos or inspect closely. Reference Maximo ID 20085 and report R739751 | | | | | |
| 44188 | ACTIVE | N | N103-00-2/776 | Fan Room - Station Building - Goodge Street Stn | Lead/Leading | Lead Paint/Lead | Presumed | | | | Presumed lead paint - black and cream gloss | | | | N | N |
| 19203 | ACTIVE | N | N103-00-2/776/WAL-002 | Wall: Internal - 2 - Fan Room - Station Building - Goodge Street Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1 x Transformer Box No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 20085 | ACTIVE | N | N103-00-2/776/WAL-006 | Wall: Internal - 6 - Fan Room - Station Building - Goodge Street Stn | Other Boarding | Asbestos | Sampled – Not Detected | | | | Panel behind Vent Equipment - Sampled and confirmed to be non asbestos. Refer to ID report R739751 2023 | | 1 | | N | N |
| 25827 | ACTIVE | N | N103-00-2/776/WAL-006 | Wall: Internal - 6 - Fan Room - Station Building - Goodge Street Stn | Rope Seals | Asbestos | Presumed | | | | Possible asbestos rope between flanges Re-inspected by 4-Rail Services 22-03-2023 | | | | N | N |
| 19597 | ACTIVE | N | N103-00-2/776/WAL-007 | Wall: Internal - 7 - Fan Room - Station Building - Goodge Street Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 60amp Grey Switch Box - Insulation within No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 10006 | ACTIVE | N | N103-00-2/901 | Disused Room - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19204 | ACTIVE | N | N103-00-2/901 | Disused Room - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10007 | ACTIVE | N | N103-00-2/951 | Disused Room - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19205 | ACTIVE | N | N103-00-2/951 | Disused Room - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10008 | ACTIVE | N | N103-00-2/952 | Store - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19206 | ACTIVE | N | N103-00-2/952 | Store - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10009 | ACTIVE | N | N103-00-2/953 | Locker Room - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N103-00 - Station Building - Goodge Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|---------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 20086 | ACTIVE | N | N103-00-2/953 | Locker Room - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10010 | ACTIVE | N | N103-00-2/954 | Passage - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19207 | ACTIVE | N | N103-00-2/954 | Passage - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10011 | ACTIVE | N | N103-00-2/955 | Service Riser - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19208 | ACTIVE | N | N103-00-2/955/CLG-01 | Ceiling: Solid - 1 - Service Riser - Station Building - Goodge Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Small Supalux Panels / Concrete | | | | | |
| 10012 | ACTIVE | N | N103-00-2/956 | Disused Room - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19209 | ACTIVE | N | N103-00-2/956 | Disused Room - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 20087 | ACTIVE | N | N103-00-3/131 | Lift Shaft - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 19813 | ACTIVE | N | N103-00-3/132 | Lift Shaft - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10013 | ACTIVE | N | N103-00-3/201 | Passage - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19598 | ACTIVE | N | N103-00-3/201 | Passage - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10014 | ACTIVE | N | N103-00-3/202 | Passage - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19210 | ACTIVE | N | N103-00-3/202 | Passage - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10015 | ACTIVE | N | N103-00-3/203 | Passage - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19211 | ACTIVE | N | N103-00-3/203 | Passage - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10016 | ACTIVE | N | N103-00-3/601 | Stairs: Linear - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19212 | ACTIVE | N | N103-00-3/601 | Stairs: Linear - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



| N103-00 - Station Building - Goodge Street Stn | | | | | | | | | | | | | | | | |
|--|--------|-------------|-----------------------|---|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
| 10017 | ACTIVE | N | N103-00-3/602 | Stairs: Linear - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20088 | ACTIVE | N | N103-00-3/602 | Stairs: Linear - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 19213 | ACTIVE | N | N103-00-3/636 | Overbridge - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 19214 | ACTIVE | N | N103-00-3/637 | Overbridge - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10018 | ACTIVE | N | N103-00-3/665 | Switch Cupboard - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19744 | ACTIVE | N | N103-00-3/665/FLR-01 | Floor - 1 - Switch Cupboard - Station Building - Goodge Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels to Stairs | | | | | |
| 19599 | ACTIVE | N | N103-00-3/665/WAL-005 | Wall: Internal - 5 - Switch Cupboard - Station Building - Goodge Street Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Grey Switch Boxes - Insulation within - 3 x 60, 1 x 100 amps No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 4 | | N | N |
| 10019 | ACTIVE | N | N103-00-3/951 | Disused Room - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19254 | ACTIVE | N | N103-00-3/951 | Disused Room - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10020 | ACTIVE | N | N103-00-4/121 | Platform Invert - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19257 | ACTIVE | N | N103-00-4/121 | Platform Invert - Station Building - Goodge Street Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 1 Invert - J hangers along entire length of invert - 2 x braided cables | | 2 | | | |
| 19255 | ACTIVE | N | N103-00-4/121 | Platform Invert - Station Building - Goodge Street Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform 1 invert under 4/712 & 4/713 Ducts - Bitumen - NADIS | | | | | |
| 19256 | ACTIVE | N | N103-00-4/121 | Platform Invert - Station Building - Goodge Street Stn | Cable Duct: Other | Asbestos | Strongly Presumed | | | | Platform 1 Invert - Cable Ducts South & North End | | | | | |
| 20089 | ACTIVE | N | N103-00-4/121 | Platform Invert - Station Building - Goodge Street Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 1 Invert - 3 Braided Cables | | | | | |
| 10021 | ACTIVE | N | N103-00-4/122 | Platform Invert - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19271 | ACTIVE | N | N103-00-4/122 | Platform Invert - Station Building - Goodge Street Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | J hangers along entire length of Platform 2 invert - braided cable Access to invert via 4/792 | | 1 | | | |



Hazardous Material Asset Register - Summary



N103-00 - Station Building - Goodge Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|----------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 19544 | ACTIVE | N | N103-00-4/122 | Platform Invert - Station Building - Goodge Street Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform 2 Invert - Cable Duct under 4/711 - Chrysotile Access to invert via 4/792 | | | | | |
| 19814 | ACTIVE | N | N103-00-4/122 | Platform Invert - Station Building - Goodge Street Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 2 Invert - 1 x Braided Cable Access to invert via 4/792 | | 1 | | | |
| 10022 | ACTIVE | N | N103-00-4/201 | Passage - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19258 | ACTIVE | N | N103-00-4/201 | Passage - Station Building - Goodge Street Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel ring caulking, near cross passage within Goodge street Deep level shelter | | | | | |
| 20090 | ACTIVE | N | N103-00-4/201 | Passage - Station Building - Goodge Street Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Dark green coloured paint applied to the floodgate. Analysis 1.56% | | | | | |
| 10023 | ACTIVE | N | N103-00-4/202 | Passage - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19259 | ACTIVE | N | N103-00-4/202 | Passage - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10024 | ACTIVE | N | N103-00-4/261 | Platform 1 - Northbound Local - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70840 | ACTIVE | N | N103-00-4/261 | Platform 1 - Northbound Local - Station Building - Goodge Street Stn | Gasket :Pipework | Asbestos | Presumed | | | | Platform Invert - Gaskets - Throughout - To metal pipework | | | R728774 | N | Y |
| 70839 | ACTIVE | N | N103-00-4/261 | Platform 1 - Northbound Local - Station Building - Goodge Street Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable duct - total 1 no - To trackside wall, midway | | 1 | R728774 | N | Y |
| 19260 | ACTIVE | N | N103-00-4/261 | Platform 1 - Northbound Local - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 70835 | ACTIVE | N | N103-00-4/261 | Platform 1 - Northbound Local - Station Building - Goodge Street Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - Throughout >6no - To J Hangers throughout arrivals end | | 6 | R728774 | | |
| 70833 | ACTIVE | N | N103-00-4/261 | Platform 1 - Northbound Local - Station Building - Goodge Street Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 4 no - To trackside wall, arrivals end | | 4 | R728774 | N | Y |
| 70831 | ACTIVE | N | N103-00-4/261 | Platform 1 - Northbound Local - Station Building - Goodge Street Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728774 | | |
| 70845 | ACTIVE | N | N103-00-4/261 | Platform 1 - Northbound Local - Station Building - Goodge Street Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 4 no - To ceiling, departure end | | 4 | R728774 | N | Y |
| 70842 | ACTIVE | N | N103-00-4/261 | Platform 1 - Northbound Local - Station Building - Goodge Street Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert -Materials within 10 core box - total 1 no - To trackside wall, departure end | | 1 | R728774 | | |



Hazardous Material Asset Register - Summary



N103-00 - Station Building - Goodge Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 70837 | ACTIVE | N | N103-00-4/261 | Platform 1 - Northbound Local - Station Building - Goodge Street Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable duct - total 1 no - To trackside wall, arrivals end | | 1 | R728774 | N | Y |
| 70843 | ACTIVE | N | N103-00-4/261 | Platform 1 - Northbound Local - Station Building - Goodge Street Stn | Cable Ducts: Cement | Asbestos | Sampled – Not Detected | | | | Platform Invert - Cement cable ducts - total 6 no - To trackside wall, departure end | | 6 | R728774 | N | Y |
| 70834 | ACTIVE | N | N103-00-4/261 | Platform 1 - Northbound Local - Station Building - Goodge Street Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable duct - total 1 no - To trackside wall, arrivals end | | 1 | R728774 | N | Y |
| 70830 | ACTIVE | N | N103-00-4/261 | Platform 1 - Northbound Local - Station Building - Goodge Street Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728774 | | |
| 10025 | ACTIVE | N | N103-00-4/262 | Platform 2 - Southbound Local - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70820 | ACTIVE | N | N103-00-4/262 | Platform 2 - Southbound Local - Station Building - Goodge Street Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable duct- total 1 no - To trackside wall, arrivals end | | 1 | R728774 | N | Y |
| 70823 | ACTIVE | N | N103-00-4/262 | Platform 2 - Southbound Local - Station Building - Goodge Street Stn | Gasket :Pipework | Asbestos | Presumed | | | | Platform Invert - Gaskets - Throughout - To metal pipework, not possible to sample | | | R728774 | N | Y |
| 70824 | ACTIVE | N | N103-00-4/262 | Platform 2 - Southbound Local - Station Building - Goodge Street Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 4 no - To platform wall, midway | | 4 | R728774 | N | Y |
| 44932 | ACTIVE | N | N103-00-4/262 | Platform 2 - Southbound Local - Station Building - Goodge Street Stn | Cable: Sheath | Asbestos | Known | | | | Braided cable on cable run at departure end, going into platform invert Limited access to re-inspect during traffic hour re-inspection 4-Rail 22-03-2023 | | | | N | N |
| 44933 | ACTIVE | N | N103-00-4/262 | Platform 2 - Southbound Local - Station Building - Goodge Street Stn | Cable: Sheath | Asbestos | Known | | | | Braided cable on cable run at arrival end, going into platform invert No access for close inspection during traffic hours re-inspection. 4-Rail 22-03-2023 | | | | N | N |
| 19261 | ACTIVE | N | N103-00-4/262 | Platform 2 - Southbound Local - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 70827 | ACTIVE | N | N103-00-4/262 | Platform 2 - Southbound Local - Station Building - Goodge Street Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 4 no - To ceiling at departure end | | 4 | R728774 | N | Y |
| 70829 | ACTIVE | N | N103-00-4/262 | Platform 2 - Southbound Local - Station Building - Goodge Street Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 no - To trackside wall, departure end | | 2 | R728774 | N | Y |
| 70816 | ACTIVE | N | N103-00-4/262 | Platform 2 - Southbound Local - Station Building - Goodge Street Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728774 | | |



Hazardous Material Asset Register - Summary



N103-00 - Station Building - Goodge Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|------------------------|---|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 70817 | ACTIVE | N | N103-00-4/262 | Platform 2 - Southbound Local - Station Building - Goodge Street Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728774 | | |
| 70819 | ACTIVE | N | N103-00-4/262 | Platform 2 - Southbound Local - Station Building - Goodge Street Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - total 6 no - To J Hangers | | 6 | R728774 | | |
| 70822 | ACTIVE | N | N103-00-4/262 | Platform 2 - Southbound Local - Station Building - Goodge Street Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 4 no - To ceiling - arrivals end | | 4 | R728774 | N | Y |
| 10026 | ACTIVE | N | N103-00-4/661 | Switch Cupboard - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20091 | ACTIVE | N | N103-00-4/661 | Switch Cupboard - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10027 | ACTIVE | N | N103-00-4/662 | Switch Cupboard - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19263 | ACTIVE | N | N103-00-4/662/ FLR-01 | Floor - 1 - Switch Cupboard - Station Building - Goodge Street Stn | Cable Duct: Other | Asbestos | Presumed | | | | 3 x Ducts - Sealed - 1 located by Wall 1 and 2 located by Wall 2 Ducts not visible beneath covering - therefore not scored in 2023 re-inspection. | | 3 | | N | N |
| 19262 | ACTIVE | N | N103-00-4/662/ WAL-003 | Wall: Internal - 3 - Switch Cupboard - Station Building - Goodge Street Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 x 60amp Grey Switch Boxes - Insulation within No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 10028 | ACTIVE | N | N103-00-4/663 | Switch Cupboard - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19600 | ACTIVE | N | N103-00-4/663/ FLR-01 | Floor - 1 - Switch Cupboard - Station Building - Goodge Street Stn | Cable Duct: Other | Asbestos | Presumed | | | | Ducts - Sealed by Wall 2 Re-inspection by 4-Rail 22-03-2023 | | 4 | | N | N |
| 25828 | ACTIVE | N | N103-00-4/663/ WAL-001 | Wall: Internal - 1 - Switch Cupboard - Station Building - Goodge Street Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 x 100amp Switch Box No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 19264 | ACTIVE | N | N103-00-4/663/ WAL-002 | Wall: Internal - 2 - Switch Cupboard - Station Building - Goodge Street Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 2 x 60, 1 x 100, 1 x 200 amp Switch Boxes - Insulation within No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 4 | | N | N |
| 10029 | ACTIVE | N | N103-00-4/664 | Switch Cupboard - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N103-00 - Station Building - Goodge Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 20092 | ACTIVE | N | N103-00-4/664 | Switch Cupboard - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10030 | ACTIVE | N | N103-00-4/711 | Relay Room - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44193 | ACTIVE | N | N103-00-4/711/ WAL-001 80896130 | Wall: Internal - 1 - Relay Room - Station Building - Goodge Street Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | 3 x electrical boxes No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 3 | | N | N |
| 19745 | ACTIVE | N | N103-00-4/711/ WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Goodge Street Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | 1 x Westinghouse Box - Insulation within No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 44194 | ACTIVE | N | N103-00-4/711/ WAL-003 80896132 | Wall: Internal - 3 - Relay Room - Station Building - Goodge Street Stn Wall: Internal | Other Boarding | Asbestos | Presumed | | | | Various pieces of Paxoline board Re-inspected by 4-Rail 22-03-2023 | | | | N | N |
| 10031 | ACTIVE | N | N103-00-4/712 | Relay Room - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44192 | ACTIVE | N | N103-00-4/712 80143147 | Relay Room - Station Building - Goodge Street Stn Room Assets | Cable Ducts: Cement | Asbestos | Sampled – Not Detected | | | | Presumed asbestos cable ducts - assumed same material as ducts tested that run to the invert under room 4/712 which were sampled to be NADIS as per report P011738-001 | | 1 | P011738-001 | N | N |
| 20093 | ACTIVE | N | N103-00-4/712 | Relay Room - Station Building - Goodge Street Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 2x 50mm Green Cable going into Invert Re-inspected by 4-Rail Services 22-03-2023 | | 2 | | N | N |
| 42495 | ACTIVE | N | N103-00-4/712 | Relay Room - Station Building - Goodge Street Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Asbestos insulating materials within 600v electrical box No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 44336 | ACTIVE | N | N103-00-4/712 | Relay Room - Station Building - Goodge Street Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Grey Tencore Box No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 19267 | INACTIVE | N | N103-00-4/712 | Relay Room - Station Building - Goodge Street Stn | Other Electrical Boxes | Asbestos | Removed | | | | 1 x Transformer Box - Removed - noted upon HMU reinspection 08/10/2014 | | 1 | | | |
| 19266 | ACTIVE | N | N103-00-4/712 | Relay Room - Station Building - Goodge Street Stn | Cable Ducts: Bitumen | Asbestos | Surveyed – Not Detected | | | | Ducts - Bitumen | | | | | |



Hazardous Material Asset Register - Summary



N103-00 - Station Building - Goodge Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|--------------------------------|--|------------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 42497 | ACTIVE | N | N103-00-4/712 | Relay Room - Station Building - Goodge Street Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1x Rectifier box - Asbestos insulating materials within No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 19265 | ACTIVE | N | N103-00-4/712/FLR-01 | Floor - 1 - Relay Room - Station Building - Goodge Street Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Durasteel Floor | | | | | |
| 44191 | ACTIVE | N | N103-00-4/712/WAL-001 80896137 | Wall: Internal - 1 - Relay Room - Station Building - Goodge Street Stn Wall: Internal | Cable: Sheath | Asbestos | Presumed | | | | 5mm cable in corner of room Re-inspected by 4-Rail Services 22-03-2023 | | 1 | | N | N |
| 10032 | ACTIVE | N | N103-00-4/713 | Relay Room - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19269 | ACTIVE | N | N103-00-4/713 | Relay Room - Station Building - Goodge Street Stn | Cable Ducts: Bitumen | Asbestos | Surveyed – Not Detected | | | | Ducts - Bitumen | | | | | |
| 42498 | ACTIVE | N | N103-00-4/713 | Relay Room - Station Building - Goodge Street Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | 1x 600v Electrical box - Asbestos insulating materials within No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 42064 | INACTIVE | N | N103-00-4/713 | Relay Room - Station Building - Goodge Street Stn | PCBs | Polychlorinated biphenyl | Removed | | | | 5 x PCB's - located within roller shutter cabinet - 4 x fair condition, 1 possibly leaking Removed by Edenbeck Feb 2017 under ES7773a | | 5 | | N | N |
| 19268 | ACTIVE | N | N103-00-4/713/FLR-01 | Floor - 1 - Relay Room - Station Building - Goodge Street Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Durasteel Floor | | | | | |
| 44934 | ACTIVE | N | N103-00-4/713/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Goodge Street Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | J hangers - braided cable 2no Only 1no Cable noted on Re-Inspection | | | | N | N |
| 20094 | ACTIVE | N | N103-00-4/713/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Goodge Street Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 2x 50mm Green Cable going into invert Re-inspected by 4-Rail Services 22-03-2023 | | 2 | | N | N |
| 19270 | ACTIVE | N | N103-00-4/713/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Goodge Street Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 10mm Cables behind within roller Shutter cabinet Re-inspected by 4-Rail Services 22-03-2023 | | 2 | | N | N |
| 10033 | ACTIVE | N | N103-00-4/714 | SER - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19272 | ACTIVE | N | N103-00-4/714 | SER - Station Building - Goodge Street Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 10034 | ACTIVE | N | N103-00-4/731 | CER - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N103-00 - Station Building - Goodge Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------------------------|---|------------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 42500 | ACTIVE | N | N103-00-4/731 | CER - Station Building - Goodge Street Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 3x Braided cables (2x green / 1x yellow) to right hand duct in roller shutter cabinet & Asbestos woven cable to bunch of cables from left hand duct to roller cabinet Re-inspected by 4-Rail Services 22-03-2023 | | 3 | | N | N |
| 42499 | ACTIVE | N | N103-00-4/731 | CER - Station Building - Goodge Street Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | 1x 600v Electrical box - Insulated materials within. Within roller shutter cabinet No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 53947 | ACTIVE | N | N103-00-4/731 | CER - Station Building - Goodge Street Stn | Other Boarding | Asbestos | Presumed | | | | brown packing material to frame behind clear plastic covered electrical box | | | | | |
| 19237 | ACTIVE | N | N103-00-4/731 | CER - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 53946 | ACTIVE | N | N103-00-4/731 | CER - Station Building - Goodge Street Stn | Cable: Sheath | Asbestos | Presumed | | | | 1 thin cable to equipment above 600v box. -right-hand side cable coming up from equipment (Left side able is non asbestos aramid cables) | | | | | |
| 42065 | INACTIVE | N | N103-00-4/731 | CER - Station Building - Goodge Street Stn | PCBs | Polychlorinated biphenyl | Removed | | | | 6 x PCB's - Fair Condition - located within roller shutter cabinet Removed by Edenbeck Feb 2017 under ES7773a | | 6 | | N | N |
| 53945 | ACTIVE | N | N103-00-4/731/ FLR-01 | Floor - 1 - CER - Station Building - Goodge Street Stn | | Asbestos | No Access: Presumed | | | | No access to manholes trunking | | | | | Y |
| 44190 | ACTIVE | N | N103-00-4/731/ WAL-001 80896151 | Wall: Internal - 1 - CER - Station Building - Goodge Street Stn Wall: Internal | Cable: Sheath | Asbestos | Presumed | | | | 2 x sheathed cables 50mm each (coming from electrical box within roller shutter cabinet) Re-inspected by 4-Rail Services 22-03-2023 | | 2 | | N | N |
| 10035 | ACTIVE | N | N103-00-4/732 | CER - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19273 | ACTIVE | N | N103-00-4/732 | CER - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10036 | ACTIVE | N | N103-00-4/786 | Service Area - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Presumed | | | | | | | | | |
| 70562 | ACTIVE | N | N103-00-4/786 | Service Area - Station Building - Goodge Street Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Grout to tunnel ring joints | 20 | | R727478 | | |
| 70561 | ACTIVE | N | N103-00-4/786 | Service Area - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | General information - Metal to shaft walls, metal door and framework to shaft walls, metal cat ladder, plastic cables, metal conduits and CMS, metal pipework, metal tunnel rings to condenser area, modern condenser units | | | R727478 | | |



Hazardous Material Asset Register - Summary



N103-00 - Station Building - Goodge Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------------------------|--|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 19274 | ACTIVE | N | N103-00-4/786 | Service Area - Station Building - Goodge Street Stn | Gasket :Pipework | Asbestos | Presumed | | | | 3x Gaskets to flange joints of pipework - concealed | | 3 | | | |
| 70560 | ACTIVE | N | N103-00-4/786 | Service Area - Station Building - Goodge Street Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | 2x Bitumen ducts to wall behind top of ladder. | | 2 | R727478 | | |
| 19379 | ACTIVE | N | N103-00-4/791 | Vent Shaft - Station Building - Goodge Street Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 2 x 20mm Green Cable going into invert Re-inspected by 4-Rail Services 22-03-2023 | | 2 | R19046 | | |
| 44195 | ACTIVE | N | N103-00-4/791/ WAL-001 80896166 | Wall: Internal - 1 - Vent Shaft - Station Building - Goodge Street Stn Wall: Internal | Cable Ducts: Cement | Asbestos | Presumed | | | | 3 x cable ducts on wall 1 Re-inspected by 4-Rail Services 22-03-2023 | | 3 | | N | N |
| 10037 | ACTIVE | N | N103-00-4/792 | CER - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42502 | ACTIVE | N | N103-00-4/792 | CER - Station Building - Goodge Street Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 1x 600v electrical box with asbestos insulating materials within No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 20095 | ACTIVE | N | N103-00-4/792 | CER - Station Building - Goodge Street Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 2 x 50mm Green Cable going into invert Re-inspection by 4-Rail Services 22-03-2023 | | 2 | | N | N |
| 19275 | ACTIVE | N | N103-00-4/792/ WAL-001 | Wall: Internal - 1 - CER - Station Building - Goodge Street Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1 x Rectifier box high level No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 19276 | ACTIVE | N | N103-00-4/792/ WAL-003 | Wall: Internal - 3 - CER - Station Building - Goodge Street Stn | Other Boarding | Asbestos | Presumed | | | | Small Paxoline Board on Frame Re-inspected by 4-Rail Services 22-03-2023 | | 2 | | N | N |
| 19601 | ACTIVE | N | N103-00-4/793 | Vent Shaft - Station Building - Goodge Street Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 20mm Cable going into invert Re-inspected by 4-Rail Services 22-03-2023 | | | | | |
| 10038 | ACTIVE | N | N103-00-4/951 | Switch Room - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19277 | ACTIVE | N | N103-00-4/951 | Switch Room - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10039 | ACTIVE | N | N103-00-4/952 | Switch Room - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19278 | ACTIVE | N | N103-00-4/952 | Switch Room - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10040 | ACTIVE | N | N103-00-A/031 | Mess Room - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N103-00 - Station Building - Goodge Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 19279 | ACTIVE | N | N103-00-A/031 | Mess Room - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 20096 | ACTIVE | N | N103-00-A/031 | Mess Room - Station Building - Goodge Street Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | LH Heater Foam Backing | | | | | |
| 20097 | ACTIVE | N | N103-00-A/031/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Goodge Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 19322 | ACTIVE | N | N103-00-A/031/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Goodge Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 10041 | ACTIVE | N | N103-00-A/047 | Kitchen - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19325 | ACTIVE | N | N103-00-A/047 | Kitchen - Station Building - Goodge Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Fibreboard Partition | | | | | |
| 19324 | ACTIVE | N | N103-00-A/047/CLG-01 | Ceiling: Solid - 1 - Kitchen - Station Building - Goodge Street Stn | Void | Asbestos | No Access: Presumed | | | | Above Fibreboard Tiles | | | | YES | |
| 19323 | ACTIVE | N | N103-00-A/047/CLG-01 | Ceiling: Solid - 1 - Kitchen - Station Building - Goodge Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Fibreboard Tiles | | | | | |
| 10042 | ACTIVE | N | N103-00-A/131 | LMR - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20148 | INACTIVE | N | N103-00-A/131 | LMR - Station Building - Goodge Street Stn | Isolator Switches | Asbestos | Surveyed – Not Detected | | | | Blue Switch Boxes - New Survey - No Asbestos Found in Isolators & Bus Bar Chamber | | 8 | | | |
| 44935 | INACTIVE | N | N103-00-A/131 | LMR - Station Building - Goodge Street Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Flash guards, 8no x 1m, to combination fuse switch box to Switch Gear | | | | N | N |
| 42441 | INACTIVE | N | N103-00-A/131 | LMR - Station Building - Goodge Street Stn | Boarding: AIB | Asbestos | Presumed | | | | 2 x 4 no. break pads to fly wheel of 4 lift motors | | 2 | R504226 | N | N |
| 44280 | ACTIVE | N | N103-00-A/131 | LMR - Station Building - Goodge Street Stn | | Asbestos | Not Found during Inspection | | | | Machine board, 2m2, inside dismantled lift machinery in the lift machinery room at Goodge Street Station Item not present in 2020 re-inspection. Possibly removed since last inspection. | | | R611326 | N | N |
| 42445 | ACTIVE | N | N103-00-A/131/WAL-002 | Wall: Internal - 2 - LMR - Station Building - Goodge Street Stn | Control Panels | Asbestos | Not Found during Inspection | | | | 4 x materials within control panels to wall 2 Item not present in 2020 re-inspection. Possibly removed since last inspection. | | 4 | R504226 | N | N |



Hazardous Material Asset Register - Summary



N103-00 - Station Building - Goodge Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 42444 | ACTIVE | N | N103-00-A/131/WAL-002 | Wall: Internal - 2 - LMR - Station Building - Goodge Street Stn | Isolator Switches | Asbestos | Not Found during Inspection | | | | Materials within combination fuse switch to wall 2 (LEB supply) Item not present in 2020 re-inspection. Possibly removed since last inspection. | | 1 | R504226 | N | N |
| 42442 | ACTIVE | N | N103-00-A/131/WAL-002 | Wall: Internal - 2 - LMR - Station Building - Goodge Street Stn | Control Panels | Asbestos | Not Found during Inspection | | | | Materials within 4 x circuit breakers and controller panel 1-4 Item not present in 2020 re-inspection. Possibly removed since last inspection. | | 4 | R504226 | N | N |
| 42443 | ACTIVE | N | N103-00-A/131/WAL-002 | Wall: Internal - 2 - LMR - Station Building - Goodge Street Stn | Control Panels | Asbestos | Not Found during Inspection | | | | 4 x Materials within controllers 1-4 by wall 2 Item not present in 2020 re-inspection. Possibly removed since last inspection. | | 4 | R504226 | N | N |
| 42447 | ACTIVE | N | N103-00-A/131/WAL-005 | Wall: Internal - 5 - LMR - Station Building - Goodge Street Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Bus Bar No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within. Note - layout of equipment changed since previous inspection. | | 1 | R504226 | N | N |
| 42446 | ACTIVE | N | N103-00-A/131/WAL-005 | Wall: Internal - 5 - LMR - Station Building - Goodge Street Stn | Isolator Switches | Asbestos | Presumed | | | | Materials within 2 x combination fuse switch No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within. Layout changed since previous inspection. Now only 2no. switch boxes are present. | | 2 | R504226 | N | N |
| 10043 | ACTIVE | N | N103-00-A/236 | Passage - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19326 | ACTIVE | N | N103-00-A/236/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Goodge Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Fibreboard Tiles | | | | | |
| 19746 | ACTIVE | N | N103-00-A/236/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Goodge Street Stn | Void | Asbestos | No Access: Presumed | | | | Above Fibreboard Tiles | | | | YES | |
| 10044 | ACTIVE | N | N103-00-A/301 | Mess Room - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19815 | ACTIVE | N | N103-00-A/301/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Goodge Street Stn | Void | Asbestos | No Access: Presumed | | | | Above Fibreboard Tiles | | | | YES | |
| 19327 | ACTIVE | N | N103-00-A/301/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Goodge Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Fibreboard Tiles | | | | | |



Hazardous Material Asset Register - Summary



N103-00 - Station Building - Goodge Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 10045 | ACTIVE | N | N103-00-A/416 | Toilet: Unisex - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19602 | ACTIVE | N | N103-00-A/416/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Goodge Street Stn | Void | Asbestos | No Access: Presumed | | | | Above Fibreboard Tiles | | | | YES | |
| 19328 | ACTIVE | N | N103-00-A/416/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Goodge Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Fibreboard Tiles | | | | | |
| 10046 | ACTIVE | N | N103-00-A/417 | Lobby - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19329 | ACTIVE | N | N103-00-A/417/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Goodge Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 20149 | ACTIVE | N | N103-00-A/417/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Goodge Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 10047 | ACTIVE | N | N103-00-A/418 | Toilet: Male - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19330 | ACTIVE | N | N103-00-A/418/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Goodge Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Fibreboard Tiles | | | | | |
| 19331 | ACTIVE | N | N103-00-A/418/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Goodge Street Stn | Void | Asbestos | No Access: Presumed | | | | Above Fibreboard Tiles | | | | YES | |
| 10048 | ACTIVE | N | N103-00-A/419 | Toilet: Unisex - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19333 | ACTIVE | N | N103-00-A/419/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Goodge Street Stn | Void | Asbestos | No Access: Presumed | | | | Above Fibreboard Tiles | | | | YES | |
| 19332 | ACTIVE | N | N103-00-A/419/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Goodge Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Fibreboard Tiles | | | | | |
| 10049 | ACTIVE | N | N103-00-A/576 | Stairs: Linear - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20150 | ACTIVE | N | N103-00-A/576 | Stairs: Linear - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10050 | ACTIVE | N | N103-00-A/578 | Stairs: Linear - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N103-00 - Station Building - Goodge Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 19334 | ACTIVE | N | N103-00-A/578/CLG-01 | Ceiling: Suspended - 1 - Linear Stairs - Station Building - Goodge Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board | | | | | |
| 19335 | ACTIVE | N | N103-00-A/578/CLG-01 | Ceiling: Suspended - 1 - Linear Stairs - Station Building - Goodge Street Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Board | | | | YES | |
| 10051 | ACTIVE | N | N103-00-A/631 | Stairs: Spiral - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20151 | ACTIVE | N | N103-00-A/631 | Stairs: Spiral - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 54001 | ACTIVE | N | N103-00-A/631 | Stairs: Spiral - Station Building - Goodge Street Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Black Gloss Paint to External Emergency Staircase - throughout - highest level 1.81% | | | R728401 | | |
| 10052 | ACTIVE | N | N103-00-A/786 | Service Riser - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19336 | ACTIVE | N | N103-00-A/786/CLG-01 | Ceiling: Solid - 1 - Service Riser - Station Building - Goodge Street Stn | Void | Asbestos | No Access: Presumed | | | | Above Vermiculite | | | | YES | |
| 10053 | ACTIVE | N | N103-00-B/301 | Office - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19238 | ACTIVE | N | N103-00-B/301/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Goodge Street Stn | Void | Asbestos | No Access: Presumed | | | | Above Fibreboard Tiles | | | | YES | |
| 19337 | ACTIVE | N | N103-00-B/301/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Goodge Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Fibreboard Tiles | | | | | |
| 70565 | ACTIVE | N | N103-00-B/302 | Office - Station Building - Goodge Street Stn | No Access | Asbestos | No Access: Presumed | | | | Carpet on wood floor, no access within floor void | | | R727478 | | Y |
| 70567 | ACTIVE | N | N103-00-B/302 | Office - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | MMMF ceiling tiles, plasterboard to ceiling above false ceiling | | | R727478 | Y | |
| 10054 | ACTIVE | N | N103-00-B/303 | Office - Station Building - Goodge Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20152 | ACTIVE | N | N103-00-B/303 | Office - Station Building - Goodge Street Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access | | | | | |
| 70568 | ACTIVE | N | N103-00-B/303 | Office - Station Building - Goodge Street Stn | | Asbestos | Surveyed – Not Detected | | | | MMMF ceiling tiles, plasterboard to ceiling above false ceiling | | | R727478 | Y | |
| 70566 | ACTIVE | N | N103-00-B/303 | Office - Station Building - Goodge Street Stn | No Access | Asbestos | No Access: Presumed | | | | Carpet on wood floor, no access within floor void | | | R727478 | | Y |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------------|--|-----------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 10055 | INACTIVE | N | N105-00-1/031 | Mess Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished - TWBN/Cross Rail project | | | | | |
| 10056 | INACTIVE | N | N105-00-1/201 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished - TWBN / Cross Rail project | | | | | |
| 19529 | INACTIVE | N | N105-00-1/201 | Passage - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | Demolished - TWBN / Cross Rail project No Asbestos Visible | | | | | |
| 19528 | INACTIVE | N | N105-00-1/201/ WAL-001 | Wall: Internal - 1 - Passage - Station Building - Tottenham Court Road Stn | | Anthrax | Surveyed – Not Detected | | | | Demolished - TWBN / Cross Rail project No Anthrax Detected | | | | | |
| 10057 | INACTIVE | N | N105-00-1/202 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished - TWBN / Cross Rail project | | | | | |
| 19174 | INACTIVE | N | N105-00-1/202 | Passage - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | Demolished - TWBN / Cross Rail project No Asbestos Visible | | | | | |
| 10058 | INACTIVE | N | N105-00-1/203 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished - TWBN / Cross Rail project | | | | | |
| 19530 | INACTIVE | N | N105-00-1/203 | Passage - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | Demolished - TWBN / Cross Rail project No Asbestos Visible | | | | | |
| 10059 | INACTIVE | N | N105-00-1/236 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished - TWBN / Cross Rail project | | | | | |
| 19531 | INACTIVE | N | N105-00-1/236 | Passage - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | Demolished - TWBN / Cross Rail project No Asbestos Visible | | | | | |
| 10060 | INACTIVE | N | N105-00-1/237 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished - TWBN / Cross Rail project | | | | | |
| 19532 | INACTIVE | N | N105-00-1/237 | Passage - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | Demolished - TWBN / Cross Rail project No Asbestos Visible | | | | | |
| 10061 | ACTIVE | N | N105-00-1/238 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | New Construction - TWBN / Cross Rail project Passage Formerly 1/412, 1/781, 1/782 N105-04s Iss 17 2008/9 SID number has been re used in a new location | | | | | |
| 19175 | ACTIVE | N | N105-00-1/238 | Passage - Station Building - Tottenham Court Road Stn | No Access | Asbestos | Surveyed – Not Detected | | | | New Construction - TWBN / Cross Rail project Passage Formerly 1/412, 1/781, 1/782 N105-04s Iss 17 2008/9 SID number has been re used in a new location | | | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 10062 | ACTIVE | N | N105-00-1/401 | Store - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished - TWBN/CrossRail project | | | | | |
| 10063 | ACTIVE | N | N105-00-1/411 | Store - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished TWBN/CrossRail project | | | | | |
| 19610 | INACTIVE | N | N105-00-1/411 | Store - Station Building - Tottenham Court Road Stn | | Asbestos | Area Demolished | | | | Demolished TWBN/CrossRail project No Asbestos Visible | | | | | |
| 10064 | INACTIVE | N | N105-00-1/412 | Store - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished - TWBN/Cross Rail project | | | | | |
| 19535 | INACTIVE | N | N105-00-1/412 | Store - Station Building - Tottenham Court Road Stn | Durasteel | Asbestos | Area Demolished | | | | Demolished - TWBN / Cross Rail project Access door 10m² Durasteel access door and panel to right | | | | | |
| 19176 | INACTIVE | N | N105-00-1/412 | Store - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Area Demolished | | | | Demolished - TWBN / Cross Rail project Air con motor with supalux boxing | | | | | |
| 19534 | INACTIVE | N | N105-00-1/412/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Tottenham Court Road Stn | Void | Asbestos | Area Demolished | | | | Demolished - TWBN / Cross Rail project Above false ceiling | | | | YES | |
| 19533 | INACTIVE | N | N105-00-1/412/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Area Demolished | | | | Demolished - TWBN / Cross Rail project Supalux / Concrete | | | | | |
| 10065 | INACTIVE | N | N105-00-1/426 | SVC - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished - TWBN / Cross Rail project | | | | | |
| 19536 | INACTIVE | N | N105-00-1/426 | SVC - Station Building - Tottenham Court Road Stn | | Asbestos | Area Demolished | | | | Demolished - TWBN / Cross Rail project No Asbestos Visible | | | | | |
| 10066 | INACTIVE | N | N105-00-1/428 | Toilet - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished - TWBN / Cross Rail project | | | | | |
| 19537 | INACTIVE | N | N105-00-1/428 | Toilet - Station Building - Tottenham Court Road Stn | | Asbestos | Area Demolished | | | | Demolished - TWBN / Cross Rail project | | | | | |
| 10067 | ACTIVE | N | N105-00-1/451 | Tenancy - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished - TWBN / Cross Rail project | | | | | |
| 19611 | INACTIVE | N | N105-00-1/451/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Demolished - TWBN / Cross Rail project Plastic cables & metal conduits, metal pipework, concrete above false ceiling (Responsibility of LU Group Properties) | | 4 | | YES | |
| 19538 | INACTIVE | N | N105-00-1/451/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Area Demolished | | | | Demolished - TWBN / Cross Rail project Supalux panels Wooden Panels | | 2 | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 10068 | INACTIVE | N | N105-00-1/452 | Tenancy - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished - TWBN / Cross Rail project | | | | | |
| 19381 | INACTIVE | N | N105-00-1/452/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Demolished - TWBN / Cross Rail project Plastic cables & metal conduits, concrete above false ceiling (responsibility of LU Group Properties) | | 3 | | YES | |
| 19177 | INACTIVE | N | N105-00-1/452/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Demolished - TWBN / Cross Rail project Supalux panels to false ceiling RSJ beam to ceiling Wooden Panels | | 3 | | YES | |
| 10069 | INACTIVE | N | N105-00-1/601 | Stairs: Linear - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished - TWBN / Cross Rail project | | | | | |
| 19539 | INACTIVE | N | N105-00-1/601 | Stairs: Linear - Station Building - Tottenham Court Road Stn | | Asbestos | Area Demolished | | | | Demolished - TWBN / Cross Rail project No Asbestos Visible | | | | | |
| 10070 | INACTIVE | N | N105-00-1/602 | Stairs: Linear - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished - TWBN / Cross Rail project | | | | | |
| 19540 | INACTIVE | N | N105-00-1/602 | Stairs: Linear - Station Building - Tottenham Court Road Stn | | Asbestos | Area Demolished | | | | Demolished - TWBN / Cross Rail project No Asbestos Visible | | | | | |
| 10071 | INACTIVE | N | N105-00-1/603 | Stairs: Linear - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished - TWBN / Cross Rail project | | | | | |
| 19574 | INACTIVE | N | N105-00-1/603 | Stairs: Linear - Station Building - Tottenham Court Road Stn | | Asbestos | Area Demolished | | | | Demolished - TWBN / Cross Rail project No Asbestos Visible | | | | | |
| 10072 | INACTIVE | N | N105-00-1/604 | Stairs: Linear - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished - TWBN / Cross Rail project | | | | | |
| 19575 | INACTIVE | N | N105-00-1/604 | Stairs: Linear - Station Building - Tottenham Court Road Stn | | Asbestos | Area Demolished | | | | Demolished - TWBN / Cross Rail project No Asbestos Visible | | | | | |
| 10073 | INACTIVE | N | N105-00-1/605 | Stairs: Linear - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished - TWBN / Cross Rail project | | | | | |
| 19576 | INACTIVE | N | N105-00-1/605 | Stairs: Linear - Station Building - Tottenham Court Road Stn | | Asbestos | Area Demolished | | | | Demolished - TWBN / Cross Rail project No Asbestos Visible | | | | | |
| 10074 | INACTIVE | N | N105-00-1/606 | Stairs: Linear - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished - TWBN / Cross Rail project | | | | | |
| 19821 | INACTIVE | N | N105-00-1/606 | Stairs: Linear - Station Building - Tottenham Court Road Stn | | Asbestos | Area Demolished | | | | Demolished - TWBN / Cross Rail project No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 10075 | INACTIVE | N | N105-00-1/607 | Stairs: Linear - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished - TWBN / Cross Rail project | | | | | |
| 19187 | INACTIVE | N | N105-00-1/607 | Stairs: Linear - Station Building - Tottenham Court Road Stn | | Asbestos | Area Demolished | | | | Demolished - TWBN / Cross Rail project No Asbestos Visible | | | | | |
| 10076 | INACTIVE | N | N105-00-1/608 | Stairs: Linear - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | As part of the TWBN / Cross Rail project the SID number has been changed to 2/610. 1/608 is no longer in use on the station layouts | | | | | |
| 19577 | INACTIVE | N | N105-00-1/608 | Stairs: Linear - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | SID number changed to 2/610 as part of the TWBN / Cross Rail project No Asbestos Visible | | | | | |
| 10077 | INACTIVE | N | N105-00-1/609 | Stairs: Linear - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | SID number changed to 2/609 as part of the TWBN / Cross Rail project No Asbestos Visible | | | | | |
| 19578 | INACTIVE | N | N105-00-1/609 | Stairs: Linear - Station Building - Tottenham Court Road Stn | | Asbestos | Area Demolished | | | | SID number changed to 2/609 as part of the TWBN / Cross Rail project No Asbestos Visible | | | | | |
| 10078 | INACTIVE | N | N105-00-1/610 | Switch Room - Station Building - Tottenham Court Road Stn (Crossrail) | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished as part of the TWBN/ Cross Rail project | | | | | |
| 19579 | INACTIVE | N | N105-00-1/610/ CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Tottenham Court Road Stn (Crossrail) | Void | Asbestos | Area Demolished | | | | Demolished as part of the TWBN/ Cross Rail project Concrete, piro cables, plastic cable above false ceiling | | | | YES | |
| 19188 | INACTIVE | N | N105-00-1/610/ CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Tottenham Court Road Stn (Crossrail) | Boarding: Supalux | Asbestos | Area Demolished | | | | Demolished as part of the TWBN/ Cross Rail project Supalux Tiles | | | | | |
| 10079 | INACTIVE | N | N105-00-1/781 | Switch Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | 1/781 has been merged into 1/238 as part of the TWBN / Cross Rail project. Transformer room has been relocated - station layout N105-19s | | | | | |
| 19581 | INACTIVE | N | N105-00-1/781 | Switch Room - Station Building - Tottenham Court Road Stn | No Access | Asbestos | Area Demolished | | | | 1/781 has been merged into 1/238 as part of the TWBN / Cross Rail project. Transformer room has been relocated - station layout N105-19s. | | | | | |
| 10080 | INACTIVE | N | N105-00-1/782 | TXR - Falconberg Court - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | 1/782 has been merged into 1/238 as part of the TWBN / Cross Rail project. Transformer room has been relocated - station layout N105-19s Responsibility of UK Power networks (old record) | | | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|---------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 19749 | INACTIVE | N | N105-00-1/782 | TXR - Falconberg Court - Station Building - Tottenham Court Road Stn | No Access | Asbestos | Area Demolished | | | | Not Surveyed - Responsibility of UK Power networks (old record) 1/782 has been merged into 1/238 as part of the TWBN / Cross Rail project. Transformer room has been relocated - station layout N105-19s. SID No. re used and remains the same | | | | | |
| 10081 | ACTIVE | N | N105-00-1/901 | Disused Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished SID No. has been re-used for Mezzanine Deck | | | | | |
| 10082 | INACTIVE | N | N105-00-2/001 | Booking Hall - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | As part of the TWBN / Cross Rail project this area has been merged with 2/071 | | | | | |
| 19583 | INACTIVE | N | N105-00-2/001/CLG-01 | Ceiling: Suspended - 1 - Booking Hall - Station Building - Tottenham Court Road Stn | Mastic | Asbestos | Removed | | | | As part of the TWBN / Cross Rail project this area has been merged with 2/071 Mastic to ductwork - Removed 2014 | | | | YES | |
| 19584 | INACTIVE | N | N105-00-2/001/CLG-01 | Ceiling: Suspended - 1 - Booking Hall - Station Building - Tottenham Court Road Stn | Cellactite Sheeting | Asbestos | Removed | | | | As part of the TWBN / Cross Rail project this area has been merged with 2/071 12m² Cellactite above false ceiling - Removed December 2014 | | 1 | | YES | |
| 19189 | INACTIVE | N | N105-00-2/001/CLG-01 | Ceiling: Suspended - 1 - Booking Hall - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | As part of the TWBN / Cross Rail project this area has been merged with 2/071 Supalux board above column number 1, 10lm Ducting | | 1 | | | |
| 19582 | INACTIVE | N | N105-00-2/001/CLG-01 | Ceiling: Suspended - 1 - Booking Hall - Station Building - Tottenham Court Road Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | As part of the TWBN / Cross Rail project this area has been merged with 2/071 Master board | | | | YES | |
| 10083 | INACTIVE | N | N105-00-2/011 | Ticket Office - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished as part of the TWBN / Cross Rail project | | | | | |
| 19586 | INACTIVE | N | N105-00-2/011/CLG-01 | Ceiling: Solid - 1 - Ticket Office - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Area Demolished | | | | Demolished as part of the TWBN / Cross Rail project Supalux Tiles | | | | | |
| 19234 | INACTIVE | N | N105-00-2/011/CLG-01 | Ceiling: Solid - 1 - Ticket Office - Station Building - Tottenham Court Road Stn | Void | Asbestos | Area Demolished | | | | Demolished as part of the TWBN / Cross Rail project Breeze block, concrete, plastic cable, air con, vermiculite lagging to pipes above false ceiling | | | | YES | |
| 19585 | INACTIVE | N | N105-00-2/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Tottenham Court Road Stn | Void | Asbestos | Area Demolished | | | | Demolished as part of the TWBN / Cross Rail project Concrete, plastic cables beneath computer flooring | | | | | YES |
| 19587 | INACTIVE | N | N105-00-2/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Tottenham Court Road Stn | Void | Asbestos | Area Demolished | | | | Demolished as part of the TWBN / Cross Rail project Concrete, plastic cable, trunking beneath computer tile (nylon) | | | | | YES |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|---------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 10084 | INACTIVE | N | N105-00-2/021 | POM - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished as part of the TWBN / Cross Rail project | | | | | |
| 19614 | INACTIVE | N | N105-00-2/021/CLG-01 | Ceiling: Solid - 1 - POM - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Area Demolished | | | | Demolished as part of the TWBN / Cross Rail project Supalux Tiles | | | | | |
| 19872 | INACTIVE | N | N105-00-2/021/CLG-01 | Ceiling: Solid - 1 - POM - Station Building - Tottenham Court Road Stn | Cellactite Sheeting | Asbestos | Area Demolished | | | | Demolished as part of the TWBN / Cross Rail project 20m² Cellactite water management - Removed by Rhodar Dec 2014 | | 1 | | YES | |
| 19588 | INACTIVE | N | N105-00-2/021/CLG-01 | Ceiling: Solid - 1 - POM - Station Building - Tottenham Court Road Stn | Void | Asbestos | Area Demolished | | | | Demolished as part of the TWBN / Cross Rail project Breeze block, concrete, plaster, plastic cable, rock wool above false ceiling | | | | YES | |
| 25874 | INACTIVE | N | N105-00-2/021/WAL-003 | Wall: Internal - 3 - POM - Station Building - Tottenham Court Road Stn | Boarding: AIB | Asbestos | Area Demolished | | | | Demolished as part of the TWBN / Cross Rail project Meduim density board >5m to trunking at high level wall 3 - Removed Dec 2014 | 5 | | | N | N |
| 10085 | INACTIVE | N | N105-00-2/031 | Mess Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished as part of the TWBN / Cross Rail project | | | | | |
| 19235 | INACTIVE | N | N105-00-2/031/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Tottenham Court Road Stn | Cellactite Sheeting | Asbestos | Area Demolished | | | | Demolished as part of the TWBN / Cross Rail project Cellactite, 4m² AFC - Removed Dec 2014 | | 1 | | | |
| 19591 | INACTIVE | N | N105-00-2/031/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Tottenham Court Road Stn | Void | Asbestos | Area Demolished | | | | Demolished as part of the TWBN / Cross Rail project Rock wool, concrete, plaster, plastic cable, air con unit above false ceiling | | | | YES | |
| 19590 | INACTIVE | N | N105-00-2/031/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Area Demolished | | | | Demolished as part of the TWBN / Cross Rail project Supalux Tiles | | | | | |
| 19589 | INACTIVE | N | N105-00-2/031/WAL-003 | Wall: Internal - 3 - Mess Room - Station Building - Tottenham Court Road Stn | LUL Heaters | Asbestos | Area Demolished | | | | Demolished as part of the TWBN / Cross Rail project LTB fire heater pad 12x10 | | 12 | | | |
| 10086 | INACTIVE | N | N105-00-2/036 | Toilet - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished as part of the TWBN / Cross Rail project | | | | | |
| 19644 | INACTIVE | N | N105-00-2/036/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Tottenham Court Road Stn | Void | Asbestos | Area Demolished | | | | Demolished as part of the TWBN / Cross Rail project Toilet Cubicle - Air con, plaster, concrete, rock wool, plastic cables above false ceiling | | | | YES | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 19645 | INACTIVE | N | N105-00-2/036/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Tottenham Court Road Stn | Cellactite Sheeting | Asbestos | Area Demolished | | | | Demolished as part of the TWBN / Cross Rail project Toilet Cubicle - 10m² Cellactite above false ceiling - Removed Dec 2014 | | 1 | | YES | |
| 19595 | INACTIVE | N | N105-00-2/036/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Area Demolished | | | | Demolished as part of the TWBN / Cross Rail project Toilet Cubicle - Supalux Tiles | | 1 | | | |
| 19594 | INACTIVE | N | N105-00-2/036/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Tottenham Court Road Stn | Cellactite Sheeting | Asbestos | Area Demolished | | | | Demolished as part of the TWBN / Cross Rail project 3m² Cellactite above false ceiling - Removed Dec 2014 | | 1 | | YES | |
| 19593 | INACTIVE | N | N105-00-2/036/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Tottenham Court Road Stn | Void | Asbestos | Area Demolished | | | | Demolished as part of the TWBN / Cross Rail project Air con, plastic cables, rock wool, concrete, plaster above false ceiling | | | | YES | |
| 19592 | INACTIVE | N | N105-00-2/036/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Area Demolished | | | | Demolished as part of the TWBN / Cross Rail project Supalux Tiles | | | | | |
| 19236 | INACTIVE | N | N105-00-2/036/WAL-004 | Wall: Internal - 4 - Toilet - Station Building - Tottenham Court Road Stn | Cellactite Sheeting | Asbestos | Area Demolished | | | | Demolished as part of the TWBN / Cross Rail project 1m² Cellactite above wall 4 - Removed Dec 2014 | | 1 | | | |
| 10087 | ACTIVE | N | N105-00-2/071 | Circulation Area - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Formerly 2/001 - Booking Hall - changes made as part of the TWBN / Cross Rail project. | | | | | |
| 42501 | INACTIVE | N | N105-00-2/071 | Circulation Area - Station Building - Tottenham Court Road Stn | Cable Ducts: Bitumen | Asbestos | Removed | | | | Bitumen cable ducts (1 no.), within pit to floor (Record transferred across from 2/001. 2/001 and 2/071 have been merged into 2/071) | | | R478051 | N | |
| 19647 | ACTIVE | N | N105-00-2/071 | Circulation Area - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Esc 5 (Arch 1 from top landing) - supalux debris, debris within arch - NADIS. 2/071 has been merged with 2/001 and is now the Booking Hall - changes made as part of the TWBN / Cross Rail project. | | | | | |
| 19250 | ACTIVE | N | N105-00-2/071/CLG-01 | Ceiling: Suspended - 1 - Circulation Area - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles. Metal mesh to false ceiling, metal pipework to false ceiling, steel sheet to high level ceiling, aluminium vent duct 2/071 has been merged with 2/001 and is now the Booking Hall - changes made as part of the TWBN / Cross Rail project. | | | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|---------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 19646 | ACTIVE | N | N105-00-2/071/CLG-01 | Ceiling: Suspended - 1 - Circulation Area - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, plastic cables, master board, steel cable tray in false ceiling, plasterboard to beam in false ceiling above false ceiling 2/071 has been merged with 2/001 and is now the Booking Hall - changes made as part of the TWBN / Cross Rail project. | | | | YES | |
| 10088 | INACTIVE | N | N105-00-2/201 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished as part of the TWBN/ CrossRail project | | | | | |
| 19648 | INACTIVE | N | N105-00-2/201 | Passage - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | Demolished as part of the TWBN/ CrossRail project No Asbestos Visible | | | | | |
| 41909 | INACTIVE | N | N105-00-2/201/FLR-01 | Floor - 1 - Passage - Station Building - Tottenham Court Road Stn | | Asbestos | Sampled – Not Detected | | | | Demolished as part of the TWBN/ CrossRail project Pipe insulation (1 no.) to pipe within pit to floor slab | | 1 | | | |
| 10089 | INACTIVE | N | N105-00-2/236 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished - TWBN/CrossRail project | | | | | |
| 19365 | INACTIVE | N | N105-00-2/236/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Tottenham Court Road Stn | Void | Asbestos | Area Demolished | | | | Demolished - TWBN/CrossRail project Breeze block, concrete, plastic cable, rock wool. Vermiculite lagging to pipes above false ceiling | | | | YES | |
| 19251 | INACTIVE | N | N105-00-2/236/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Tottenham Court Road Stn | Cellactite Sheeting | Asbestos | Area Demolished | | | | Demolished - TWBN/CrossRail project 3m² Cellactite water management above false ceiling - Removed Dec 2014 | | 1 | | YES | |
| 19650 | INACTIVE | N | N105-00-2/236/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Area Demolished | | | | Demolished - TWBN/CrossRail project Supalux Tiles | | | | | |
| 19649 | INACTIVE | N | N105-00-2/236/FLR-01 | Floor - 1 - Passage - Station Building - Tottenham Court Road Stn | Void | Asbestos | Area Demolished | | | | Demolished - TWBN/CrossRail project Concrete, plastic cables, trunking, fibre glass beneath computer tile (nylon) | | | | | YES |
| 10090 | INACTIVE | N | N105-00-2/311 | Office - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished - TWBN/CrossRail project | | | | | |
| 19654 | INACTIVE | N | N105-00-2/311/CLG-01 | Ceiling: Solid - 1 - Office - Station Building - Tottenham Court Road Stn | Cellactite Sheeting | Asbestos | Area Demolished | | | | Demolished - TWBN/CrossRail project 14m² Cellactite - Removed by Rhodar Dec 2014 | | 1 | | | |
| 19617 | INACTIVE | N | N105-00-2/311/CLG-01 | Ceiling: Solid - 1 - Office - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Area Demolished | | | | Demolished TWBN/CrossRail project Supalux Tiles | | | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 19653 | INACTIVE | N | N105-00-2/311/CLG-01 | Ceiling: Solid - 1 - Office - Station Building - Tottenham Court Road Stn | Void | Asbestos | Area Demolished | | | | Demolished - TWBN/CrossRail project Air con, rock wool, plastic cables, concrete, breeze block. Packing between pipes. Vermiculite boxing high level | | | | YES | |
| 19651 | INACTIVE | N | N105-00-2/311/DOR-01 | Door - 1 - Office - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Area Demolished | | | | Demolished TWBN/CrossRail project Supalux panel low level on access door | | | | | |
| 19652 | INACTIVE | N | N105-00-2/311/WAL-001 | Wall: Internal - 1 - Office - Station Building - Tottenham Court Road Stn | LUL Heaters | Asbestos | Area Demolished | | | | Demolished - TWBN/CrossRail project LTB fire - Heater pad within 10"x12" | | | | | |
| 10091 | INACTIVE | N | N105-00-2/396 | Disused Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished - TWBN / CrossRail project | | | | | |
| 19655 | INACTIVE | N | N105-00-2/396 | Disused Room - Station Building - Tottenham Court Road Stn | | Asbestos | Area Demolished | | | | Demolished - TWBN / CrossRail project No Asbestos Visible | | | | | |
| 10092 | INACTIVE | N | N105-00-2/631 | Stairs: Spiral - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished - TWBN / Cross Rail project | | | | | |
| 19252 | INACTIVE | N | N105-00-2/631 | Stairs: Spiral - Station Building - Tottenham Court Road Stn | | Asbestos | Area Demolished | | | | Demolished - TWBN / Cross Rail project No Asbestos Visible | | | | | |
| 10093 | INACTIVE | N | N105-00-2/746 | SCR - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished - TWBN / CrossRail project | | | | | |
| 19656 | INACTIVE | N | N105-00-2/746 | SCR - Station Building - Tottenham Court Road Stn | | Asbestos | Area Demolished | | | | Demolished - TWBN / Cross Rail project No Asbestos Visible | | | | | |
| 10094 | INACTIVE | N | N105-00-2/776 | Plant Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Demolished - TWBN / Cross Rail project | | | | | |
| 19875 | INACTIVE | N | N105-00-2/776/CLG-01 | Ceiling: Solid - 1 - Plant Room - Station Building - Tottenham Court Road Stn | Mastic | Asbestos | Area Demolished | | | | Demolished - TWBN / Cross Rail project Mastic to ductwork - Removed Dec 2014 | | | | | |
| 19657 | INACTIVE | N | N105-00-2/776/WAL-001 | Wall: Internal - 1 - Plant Room - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Area Demolished | | | | Demolished - TWBN / Cross Rail project Tunnel ring caulking throughout - Non asbestos | | | | | |
| 10095 | INACTIVE | N | N105-00-2/786 | Service Riser - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | As part of the TWBN / Cross Rail project this area has been merged with 2/071 | | | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 19253 | INACTIVE | N | N105-00-2/786 | Service Riser - Station Building - Tottenham Court Road Stn | | Asbestos | Area Demolished | | | | No Asbestos Visible As part of the TWBN / Cross Rail project this area has been merged with 2/071 | | | | | |
| 10096 | ACTIVE | N | N105-00-3/151 | UMC - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19660 | ACTIVE | N | N105-00-3/151 | UMC - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Disused Tunnel off UMC - Caulking throughout - NAD | | | | | |
| 42338 | ACTIVE | N | N105-00-3/151 | UMC - Station Building - Tottenham Court Road Stn | | Asbestos | Sampled – Not Detected | | | | Vermiculite cladding to 1 x sprinkler pipework | | | R506751 | N | N |
| 19658 | ACTIVE | N | N105-00-3/151/CLG-01 | Ceiling: Solid - 1 - UMC - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | High level LHS of access door- Supalux panel | | | | | |
| 19659 | ACTIVE | N | N105-00-3/151/CLG-01 | Ceiling: Solid - 1 - UMC - Station Building - Tottenham Court Road Stn | Void | Asbestos | No Access: Presumed | | | | Above false ceiling | | | | YES | |
| 19301 | ACTIVE | N | N105-00-3/151/FLR-01 | Floor - 1 - UMC - Station Building - Tottenham Court Road Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Lid to Storage Bin | | | | | |
| 10097 | ACTIVE | N | N105-00-3/201 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19661 | ACTIVE | N | N105-00-3/201/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Non asbestos pipework & cables. Concrete above false ceiling - concrete, cables, metal & plastic, ducting to ceiling - no asbestos visible, metal mesh | | | | YES | |
| 10098 | ACTIVE | N | N105-00-3/396 | SVC - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19618 | ACTIVE | N | N105-00-3/396 | SVC - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux (Walls) | | | | | |
| 19662 | ACTIVE | N | N105-00-3/396/CLG-01 | Ceiling: Solid - 1 - SVC - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 19663 | ACTIVE | N | N105-00-3/396/CLG-01 | Ceiling: Solid - 1 - SVC - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal Grill forms Floor to 2/776 above false ceiling | | 1 | | YES | |
| 10099 | ACTIVE | N | N105-00-3/411 | Disused Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19302 | ACTIVE | N | N105-00-3/411 | Disused Room - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel ring caulking | | | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 10100 | ACTIVE | N | N105-00-3/631 | Stairs: Spiral - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19664 | ACTIVE | N | N105-00-3/631 | Stairs: Spiral - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Tunnel Rings - Solid Caulking - sampled | | 1 | | | |
| 19711 | ACTIVE | N | N105-00-3/631/CLG-01 | Ceiling: Suspended - 1 - Spiral Stairs - Station Building - Tottenham Court Road Stn | Void | Asbestos | No Access: Presumed | | | | Above metal ceiling | | | | YES | |
| 10101 | ACTIVE | N | N105-00-3/665 | Switch Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19713 | ACTIVE | N | N105-00-3/665 | Switch Room - Station Building - Tottenham Court Road Stn | Isolator Switches | Asbestos | Surveyed – Not Detected | | | | All asbestos insulation materials removed | | 14 | | | |
| 19712 | ACTIVE | N | N105-00-3/665/CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |
| 10102 | ACTIVE | N | N105-00-3/666 | Switch Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19313 | ACTIVE | N | N105-00-3/666 | Switch Room - Station Building - Tottenham Court Road Stn | Isolator Switches | Asbestos | Surveyed – Not Detected | | | | All asbestos insulation materials removed | | 12 | | | |
| 10103 | ACTIVE | N | N105-00-3/776 | Plant Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10104 | ACTIVE | N | N105-00-4/081 | Circulation Area - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19714 | ACTIVE | N | N105-00-4/081/CLG-01 | Ceiling: Suspended - 1 - Circulation Area - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Stainless steel water management & concrete above VE Panel | | | | YES | |
| 10105 | ACTIVE | N | N105-00-4/082 | Circulation Area - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19715 | ACTIVE | N | N105-00-4/082/CLG-01 | Ceiling: Suspended - 1 - Circulation Area - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Stainless steel water management & concrete above VE Panel | | | | YES | |
| 10106 | ACTIVE | N | N105-00-4/083 | Lobby - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19314 | ACTIVE | N | N105-00-4/083/WAL-004 | Wall: Internal - 4 - Lobby - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux panel above door | | | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 10107 | ACTIVE | N | N105-00-4/091 | Circulation Area - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Surveyed – Asbestos Known | | | | | | | | | |
| 42507 | ACTIVE | N | N105-00-4/091 | Circulation Area - Station Building - Tottenham Court Road Stn | Cable Ducts: Cement | Asbestos | Known | | | | Cement ducting, 7m, running under steps to 4/604 - 4/091 | 7 | | R491226 | N | |
| 41922 | ACTIVE | N | N105-00-4/091 | Circulation Area - Station Building - Tottenham Court Road Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | 11 x Bitumen cable ducts within the cable pit to floor and towards stairs 4/604 within the Circulation Area | | 11 | | | |
| 41923 | ACTIVE | N | N105-00-4/091 | Circulation Area - Station Building - Tottenham Court Road Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | 8 x Bitumen Cable Ducts within cable pit to floor towards the Circulation Area within lower intermediate level | | 8 | | | |
| 19716 | ACTIVE | N | N105-00-4/091/CLG-01 | Ceiling: Suspended - 1 - Circulation Area - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | New Corrugated Metal Sheetting / Water Management System. Metal Tunnel Rings - Concrete Fill above false ceiling | | | | YES | |
| 10108 | ACTIVE | N | N105-00-4/151 | UMC Access - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19315 | ACTIVE | N | N105-00-4/151 | UMC Access - Station Building - Tottenham Court Road Stn | Isolator Switches | Asbestos | Surveyed – Not Detected | | | | All asbestos insulation materials removed | | 1 | | | |
| 19718 | ACTIVE | N | N105-00-4/151/CLG-01 | Ceiling: Solid - 1 - UMC - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring - Caulking - Solid; Lagging - Non Asbestos | | | | | |
| 19717 | ACTIVE | N | N105-00-4/151/CLG-01 | Ceiling: Solid - 1 - UMC - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux panel at start of incline | | | | | |
| 19719 | ACTIVE | N | N105-00-4/151/CLG-01 | Ceiling: Solid - 1 - UMC - Station Building - Tottenham Court Road Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux panel | | | | YES | |
| 19668 | ACTIVE | N | N105-00-4/151/FLR-01 | Floor - 1 - UMC - Station Building - Tottenham Court Road Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Lid to Storage Bin | | | | | |
| 10109 | ACTIVE | N | N105-00-4/152 | UMC - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19721 | ACTIVE | N | N105-00-4/152 | UMC - Station Building - Tottenham Court Road Stn | Isolator Switches | Asbestos | Surveyed – Not Detected | | | | All asbestos insulation materials removed | | 1 | | | |
| 19720 | ACTIVE | N | N105-00-4/152/FLR-01 | Floor - 1 - UMC Access - Station Building - Tottenham Court Road Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Lid to Storage Bin | | | | | |
| 10110 | ACTIVE | N | N105-00-4/161 | LMC - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 19722 | ACTIVE | N | N105-00-4/161 | LMC - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10111 | ACTIVE | N | N105-00-4/162 | LMC - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19316 | ACTIVE | N | N105-00-4/162 | LMC - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Known | | | | 30m Cable - Encapsulated No access 2024 re-inspection. | | 1 | | | |
| 19723 | ACTIVE | N | N105-00-4/162 | LMC - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Known | | | | 10mm Cable - Encapsulated No access 2024 re-inspection. | | 1 | | | |
| 10112 | ACTIVE | N | N105-00-4/201 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19801 | ACTIVE | N | N105-00-4/201/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring Caulking | | | | YES | |
| 19422 | ACTIVE | N | N105-00-4/201/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | The Rotunda area was survyed - No asbestos detected. Dust to tunnel ring throughoutabove metal ceiling. | | | | YES | |
| 10113 | ACTIVE | N | N105-00-4/202 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19724 | ACTIVE | N | N105-00-4/202/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plastic cables. Metal brackets . Concrete slab to horizontal beam. Dust. Cement on mesh above false ceiling | | | | YES | |
| 10114 | ACTIVE | N | N105-00-4/203 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19317 | ACTIVE | N | N105-00-4/203 | Passage - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10115 | ACTIVE | N | N105-00-4/204 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19877 | ACTIVE | N | N105-00-4/204/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Tottenham Court Road Stn | Void | Asbestos | Sampled – Not Detected | | | | Concrete from void NADIS - above false ceiling | | | | YES | |
| 19725 | ACTIVE | N | N105-00-4/204/FLR-01 | Floor - 1 - Passage - Station Building - Tottenham Court Road Stn | Void | Asbestos | No Access: Presumed | | | | Beneath false floor - manhole jammed /sealed shut | | | | | YES |
| 19727 | ACTIVE | N | N105-00-4/205 | Overbridge - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | No Access: Presumed | | | | Overbridge - Bitumen to tunnel ring, deep level - presumed above ceiling panels | | | | | |
| 19669 | ACTIVE | N | N105-00-4/205/CLG-01 | Ceiling: Suspended - 1 - Overbridge - Station building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete screed throughout. Plaster screed above false ceiling | | | | YES | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|---------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 19726 | ACTIVE | N | N105-00-4/205/CLG-02 | Ceiling: Solid - 2 - Overbridge - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete screed throughout. Plaster screed above false ceiling | | | | YES | |
| 19318 | ACTIVE | N | N105-00-4/205/CLG-03 | Ceiling: Solid - 3 - Overbridge - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete screed throughout. Plaster screed above false ceiling | | | | YES | |
| 19779 | ACTIVE | N | N105-00-4/206 | Overbridge - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | No Access: Presumed | | | | Overbridge - Bitumen to tunnel ring, deep level - presumed above ceiling panels | | | | | |
| 19728 | ACTIVE | N | N105-00-4/206/CLG-01 | Ceiling: Suspended - 1 - Overbridge - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete screed throughout. Plaster screed above false ceiling | | | | YES | |
| 19729 | ACTIVE | N | N105-00-4/206/CLG-02 | Ceiling: Solid - 2 - Overbridge - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete screed throughout. Plaster screed above false ceiling | | | | YES | |
| 19730 | ACTIVE | N | N105-00-4/206/CLG-03 | Ceiling: Solid - 3 - Overbridge - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete screed throughout. Plaster screed above false ceiling | | | | YES | |
| 10116 | ACTIVE | N | N105-00-4/207 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19781 | ACTIVE | N | N105-00-4/207 | Passage - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | Bitumen Ducts | | 11 | | | |
| 19780 | ACTIVE | N | N105-00-4/207 | Passage - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux boarding RHS replacing frieze panel | | | | | |
| 19803 | ACTIVE | N | N105-00-4/207/FLR-01 | Floor - 1 - Passage - Station Building - Tottenham Court Road Stn | Cable Ducts: Cement | Asbestos | Known | | | | Cement Cable ducts manhole nearest to stairs 4/604 (base of stairs) beneath floor | | 3 | | | Y |
| 10117 | ACTIVE | N | N105-00-4/209 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10118 | ACTIVE | N | N105-00-4/211 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19782 | ACTIVE | N | N105-00-4/211 | Passage - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux paneling Above doors 4/083 in passage 4/211, Wooden surround - Above doors 4/772 in passage 4/211, | | | | | |
| 19783 | ACTIVE | N | N105-00-4/211 | Passage - Station Building - Tottenham Court Road Stn | Mastic | Asbestos | Surveyed – Not Detected | | | | Mastic to ductwork flanges to ceiling throughout Corridor and Lobby in station entrance, 4/211 & 4/772 | | | | | |
| 19373 | ACTIVE | N | N105-00-4/211/FLR-01 | Floor - 1 - Passage - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Manhole - Bitumen cable ducts - Non asbestos near 4/083 (plastic cables within) | | 39 | | | YES |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-------------------------------|--|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 10119 | ACTIVE | N | N105-00-4/212 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42336 | ACTIVE | N | N105-00-4/212/FLR-01 | Floor - 1 - Passage - Station Building - Tottenham Court Road Stn | Cable Ducts: Cement | Asbestos | Known | | | | Cement cable ducts (2x3Lm) to floor (within concrete slab) | | 2 | R506751 | N | N |
| 19785 | ACTIVE | N | N105-00-4/212/FLR-01 | Floor - 1 - Passage - Station Building - Tottenham Court Road Stn | Cable: Wrap | Asbestos | Strongly Presumed | | | | Braided cables in cable hatch manhole | | | | | |
| 19784 | ACTIVE | N | N105-00-4/212/FLR-01 | Floor - 1 - Passage - Station Building - Tottenham Court Road Stn | Cable Ducts: Cement | Asbestos | Known | | | | Cement Duct (Below floor hatch no 8) | | | | | |
| 42337 | ACTIVE | N | N105-00-4/212/FLR-01 | Floor - 1 - Passage - Station Building - Tottenham Court Road Stn | Cable Ducts: Cement | Asbestos | Known | | | | Cement cable ducts (2x4Lm) to floor (within concrete slab) | | 2 | R506751 | N | N |
| 10120 | ACTIVE | N | N105-00-4/213 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19374 | ACTIVE | N | N105-00-4/213/FLR-01 | Floor - 1 - Passage - Station Building - Tottenham Court Road Stn | Void | Asbestos | No Access: Presumed | | | | No access to floor hatches - Corridor bricked up at both ends | | | | | YES |
| 19786 | ACTIVE | N | N105-00-4/213/FLR-01 | Floor - 1 - Passage - Station Building - Tottenham Court Road Stn | Cable Ducts: Bitumen | Asbestos | Surveyed – Not Detected | | | | Bitumen Ducts below floor hatch | | 18 | | | |
| 10121 | ACTIVE | N | N105-00-4/214 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19423 | ACTIVE | N | N105-00-4/214/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Tunnel Rings beneath Metal Panels | | | | YES | |
| 19788 | ACTIVE | N | N105-00-4/214/FLR-01 | Floor - 1 - Passage - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | Manhole 5 - 4x Bitumen cable ducts - Manhole in corner (outer side) near escalator 6 - Non asbestos | | | | | |
| 19879 | ACTIVE | N | N105-00-4/214/FLR-01 80913066 | Floor - 1 - Passage - Station Building - Tottenham Court Road Stn Floor | Cable Duct: Other | Asbestos | No Access: Presumed | | | | Manhole 1 - other ducts may be present behind concrete / cement panels | | | | | |
| 19787 | ACTIVE | N | N105-00-4/214/FLR-01 | Floor - 1 - Passage - Station Building - Tottenham Court Road Stn | Cable Ducts: Bitumen | Asbestos | Surveyed – Not Detected | | | | Manhole 1 - 12+ Bitumen Cable Ducts - to Manhole by door 4/751. 4x Bitumen cable ducts - manhole in corner (inner side) near station supervisor's office, - Non asbestos (plastic cables within) | | | | | |
| 10122 | ACTIVE | N | N105-00-4/215 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 19789 | ACTIVE | N | N105-00-4/215/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above Cable Trays | | | | YES | |
| 10123 | ACTIVE | N | N105-00-4/236 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19791 | ACTIVE | N | N105-00-4/236 | Passage - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Walls - Durasteel non asbestos | | | | | |
| 19790 | ACTIVE | N | N105-00-4/236 | Passage - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Presumed | | | | Walls - Concrete - Caulking behind presumed | | | | | |
| 19792 | ACTIVE | N | N105-00-4/236/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Strongly Presumed | | | | Caulking above Concrete ceiling | | | | YES | |
| 19793 | ACTIVE | N | N105-00-4/236/CLG-02 | Ceiling: Solid - 2 - Passage - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Strongly Presumed | | | | Caulking above Concrete ceiling | | | | YES | |
| 19375 | ACTIVE | N | N105-00-4/236/FLR-01 | Floor - 1 - Passage - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Strongly Presumed | | | | Caulking beneath Concrete floor | | | | | YES |
| 19303 | ACTIVE | N | N105-00-4/236/FLR-02 | Floor - 2 - Passage - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Strongly Presumed | | | | Caulking beneath Concrete floor | | | | | YES |
| 10124 | ACTIVE | N | N105-00-4/237 | Lobby - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19376 | ACTIVE | N | N105-00-4/237 | Lobby - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10125 | ACTIVE | N | N105-00-4/238 | Lobby - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19794 | ACTIVE | N | N105-00-4/238 | Lobby - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10126 | ACTIVE | N | N105-00-4/239 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19796 | ACTIVE | N | N105-00-4/239 | Passage - Station Building - Tottenham Court Road Stn | Mastic | Asbestos | Surveyed – Not Detected | | | | Mastic to Ductwork NAD | | | | | |
| 19795 | ACTIVE | N | N105-00-4/239 | Passage - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux panel to cap off duct (Fibreglass Duct Lagging to main passage) | | | | | |
| 10127 | ACTIVE | N | N105-00-4/240 | Lobby - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 19377 | ACTIVE | N | N105-00-4/240 | Lobby - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10128 | ACTIVE | N | N105-00-4/241 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19797 | ACTIVE | N | N105-00-4/241 | Passage - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10129 | ACTIVE | N | N105-00-4/316 | Locker Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19798 | ACTIVE | N | N105-00-4/316 | Locker Room - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10130 | ACTIVE | N | N105-00-4/317 | Locker Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19378 | ACTIVE | N | N105-00-4/317 | Locker Room - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10131 | ACTIVE | N | N105-00-4/331 | Mess Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19848 | ACTIVE | N | N105-00-4/331 | Mess Room - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux paneling above door 4/751 | | | | | |
| 19434 | ACTIVE | N | N105-00-4/331/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, plastic cable, air con above metal tiles | | | | YES | |
| 19799 | ACTIVE | N | N105-00-4/331/FLR-01 | Floor - 1 - Mess Room - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, plastic cables, CMS, fire alarm beneath computer tiles - nylon | | | | | YES |
| 19800 | ACTIVE | N | N105-00-4/331/WAL-001 | Wall: Internal - 1 - Mess Room - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux boxing, horizontal: low level | | | | | |
| 19847 | ACTIVE | N | N105-00-4/331/WAL-002 | Wall: Internal - 2 - Mess Room - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Up to stairs - Supalux boxing, horizontal: low level | | | | | |
| 10132 | ACTIVE | N | N105-00-4/332 | Office - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19849 | ACTIVE | N | N105-00-4/332/WAL-002 | Wall: Internal - 2 - Locker Room - Station Building - Tottenham Court Road Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - Insulation Board Foam | | | | | |
| 19850 | ACTIVE | N | N105-00-4/332/WAL-002 | Wall: Internal - 2 - Locker Room - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | High Level Supalux panel | | | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 10133 | ACTIVE | N | N105-00-4/401 | Disused Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19851 | ACTIVE | N | N105-00-4/401 | Disused Room - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10134 | ACTIVE | N | N105-00-4/406 | SVC - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19852 | ACTIVE | N | N105-00-4/406 | SVC - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10135 | ACTIVE | N | N105-00-4/407 | Store - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19435 | ACTIVE | N | N105-00-4/407 | Store - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10136 | ACTIVE | N | N105-00-4/408 | Store - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19853 | ACTIVE | N | N105-00-4/408 | Store - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10137 | ACTIVE | N | N105-00-4/409 | Mess Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19854 | ACTIVE | N | N105-00-4/409 | Mess Room - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10138 | ACTIVE | N | N105-00-4/411 | Store - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19677 | ACTIVE | N | N105-00-4/411 | Store - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux boxing to air con motor | | | | | |
| 10139 | ACTIVE | N | N105-00-4/412 | Switch Cupboard - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19855 | ACTIVE | N | N105-00-4/412 | Switch Cupboard - Station Building - Tottenham Court Road Stn | Isolator Switches | Asbestos | Known | | | | 1no Blue CFS Switch Box | | 1 | | | |
| 19436 | ACTIVE | N | N105-00-4/412 | Switch Cupboard - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel above door | | | | | |
| 19881 | ACTIVE | N | N105-00-4/412 | Switch Cupboard - Station Building - Tottenham Court Road Stn | Isolator Switches | Asbestos | Surveyed – Not Detected | | | | All asbestos insulation materials removed | | 5 | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 10140 | ACTIVE | N | N105-00-4/416 | Toilet: Male - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19856 | ACTIVE | N | N105-00-4/416 | Toilet: Male - Station Building - Tottenham Court Road Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - Insulation Board Foam | | | | | |
| 10141 | ACTIVE | N | N105-00-4/417 | Toilet: Female - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19857 | ACTIVE | N | N105-00-4/417 | Toilet: Female - Station Building - Tottenham Court Road Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - Insulation Board Foam | | | | | |
| 10142 | ACTIVE | N | N105-00-4/418 | Shower Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19437 | ACTIVE | N | N105-00-4/418 | Shower Room - Station Building - Tottenham Court Road Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - Insulation Board Foam | | | | | |
| 10143 | ACTIVE | N | N105-00-4/419 | Store - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19858 | ACTIVE | N | N105-00-4/419/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 19859 | ACTIVE | N | N105-00-4/419/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | YES | |
| 10144 | ACTIVE | N | N105-00-4/576 | Stairs: Linear - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19860 | ACTIVE | N | N105-00-4/576 | Stairs: Linear - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels | | | | | |
| 10145 | ACTIVE | N | N105-00-4/601 | Stairs: Linear - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19678 | ACTIVE | N | N105-00-4/601 | Stairs: Linear - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10146 | ACTIVE | N | N105-00-4/602 | Stairs: Linear - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19438 | ACTIVE | N | N105-00-4/602 | Stairs: Linear - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10147 | ACTIVE | N | N105-00-4/603 | Stairs: Linear - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 19861 | ACTIVE | N | N105-00-4/603 | Stairs: Linear - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10148 | ACTIVE | N | N105-00-4/604 | Stairs: Linear - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Surveyed – Asbestos Known | | | | | | | | | |
| 19862 | ACTIVE | N | N105-00-4/604 | Stairs: Linear - Station Building - Tottenham Court Road Stn | Cable Ducts: Cement | Asbestos | Surveyed – Not Detected | | | | Cement ducting, 7m, running under steps to 4/604 - 4/091 | 7 | | | N | |
| 10149 | ACTIVE | N | N105-00-4/605 | Stairs: Linear - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19439 | ACTIVE | N | N105-00-4/605 | Stairs: Linear - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10150 | ACTIVE | N | N105-00-4/606 | Stairs: Linear - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19863 | ACTIVE | N | N105-00-4/606 | Stairs: Linear - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10151 | ACTIVE | N | N105-00-4/607 | Stairs: Linear - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42492 | ACTIVE | N | N105-00-4/607 | Stairs: Linear - Station Building - Tottenham Court Road Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Bitumen cable ducts, within concrete slab to bottom of stairs Note - these appear to run from Northbound Platform 3 Northern Line (from invert) into stairs area and upstairs. | | | R505876 | N | N |
| 19864 | ACTIVE | N | N105-00-4/607 | Stairs: Linear - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10152 | ACTIVE | N | N105-00-4/608 | Stairs: Linear - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19865 | ACTIVE | N | N105-00-4/608 | Stairs: Linear - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10153 | ACTIVE | N | N105-00-4/609 | Stairs: Linear - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19304 | ACTIVE | N | N105-00-4/609 | Stairs: Linear - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10154 | ACTIVE | N | N105-00-4/661 | Switch Cupboard - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19440 | ACTIVE | N | N105-00-4/661 | Switch Cupboard - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux boarding above door | | | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 10155 | ACTIVE | N | N105-00-4/662 | Switch Cupboard - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19866 | ACTIVE | N | N105-00-4/662 | Switch Cupboard - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux boarding | | | | | |
| 10156 | ACTIVE | N | N105-00-4/663 | Switch Cupboard - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19867 | ACTIVE | N | N105-00-4/663 | Switch Cupboard - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux boarding | | | | | |
| 10157 | ACTIVE | N | N105-00-4/664 | Communications Equipment Cupboard - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19868 | ACTIVE | N | N105-00-4/664 | Communications Equipment Cupboard - Station Building - Tottenham Court Road Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 10158 | ACTIVE | N | N105-00-4/665 | Communications Equipment Cupboard - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19805 | ACTIVE | N | N105-00-4/665 | Communications Equipment Cupboard - Station Building - Tottenham Court Road Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 10159 | ACTIVE | N | N105-00-4/666 | Switch Cupboard - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19441 | ACTIVE | N | N105-00-4/666 | Switch Cupboard - Station Building - Tottenham Court Road Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 10160 | ACTIVE | N | N105-00-4/667 | Communications Equipment Cupboard - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19869 | ACTIVE | N | N105-00-4/667 | Communications Equipment Cupboard - Station Building - Tottenham Court Road Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 10161 | ACTIVE | N | N105-00-4/711 | Relay Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19442 | ACTIVE | N | N105-00-4/711 | Relay Room - Station Building - Tottenham Court Road Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1no Electrical Box W4, 3no Electrical Boxes W2 - Presumed asbestos materials within | | 4 | | | |
| 19871 | ACTIVE | N | N105-00-4/711 | Relay Room - Station Building - Tottenham Court Road Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline Boarding - Various Areas | | | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|--------------------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 19882 | ACTIVE | N | N105-00-4/711 | Relay Room - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Presumed | | | | Walls - Concrete - Caulking behind presumed | | | | | |
| 19870 | ACTIVE | N | N105-00-4/711/CLG-01 | Ceiling: Solid - 1 - Relay Room - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Strongly Presumed | | | | Caulking above Concrete ceiling | | | | YES | |
| 19679 | INACTIVE | N | N105-00-4/711/FLR-01 | Floor - 1 - Relay Room - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Strongly Presumed | | | | Caulking above Concrete ceiling | | | | YES | |
| 19807 | ACTIVE | N | N105-00-4/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Tottenham Court Road Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline Boarding - Various Areas | | 3 | | | |
| 19546 | ACTIVE | N | N105-00-4/711/WAL-002 80913583 | Wall: Internal - 2 - Relay Room - Station Building - Tottenham Court Road Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | Rectifier boxes - Presumed asbestos materials within | | 2 | | | |
| 19496 | ACTIVE | N | N105-00-4/711/WAL-003 80913584 | Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box(es) - Presumed asbestos materials within | | 2 | | | |
| 10162 | ACTIVE | N | N105-00-4/731 | CER - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19922 | ACTIVE | N | N105-00-4/731/FLR-01 | Floor - 1 - CER - Station Building - Tottenham Court Road Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Marley tiles on solid floor 15m² | | | | | |
| 10163 | ACTIVE | N | N105-00-4/732 | CER - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19923 | ACTIVE | N | N105-00-4/732/FLR-01 | Floor - 1 - CER - Station Building - Tottenham Court Road Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Marley tiles on solid floor 20m | | | | | |
| 10164 | ACTIVE | N | N105-00-4/733 | CER - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19943 | ACTIVE | N | N105-00-4/733 | CER - Station Building - Tottenham Court Road Stn | Isolator Switches | Asbestos | Surveyed – Not Detected | | | | All asbestos insulation materials removed | | 4 | | | |
| 19925 | ACTIVE | N | N105-00-4/733 | CER - Station Building - Tottenham Court Road Stn | Isolator Switches | Asbestos | Surveyed – Not Detected | | | | All asbestos insulation materials removed | | 4 | | | |
| 19924 | ACTIVE | N | N105-00-4/733/FLR-01 | Floor - 1 - CER - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | No asbestos visible beneath computer flooring | | | | | YES |
| 10165 | ACTIVE | N | N105-00-4/746 | SCR - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10166 | ACTIVE | N | N105-00-4/751 | Station Control Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 41945 | ACTIVE | N | N105-00-4/751 | Station Control Room - Station Building - Tottenham Court Road Stn | Debris: Other | Asbestos | Sampled – Not Detected | | | | <1m² Debris to riser 2 | | | | N | N |
| 41944 | ACTIVE | N | N105-00-4/751 | Station Control Room - Station Building - Tottenham Court Road Stn | Cable Duct: Other | Asbestos | Sampled – Not Detected | | | | Approx 4 x Cable Ducts to riser 1 | | 4 | | N | N |
| 41946 | ACTIVE | N | N105-00-4/751 | Station Control Room - Station Building - Tottenham Court Road Stn | Gasket :Pipework | Asbestos | Sampled – Not Detected | | | | 1 x Gasket to flange of A/C duct | | 1 | | N | N |
| 19927 | ACTIVE | N | N105-00-4/751/CLG-01 | Ceiling: Solid - 1 - Station Control Room - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Concrete, plastic cable, air con, above false ceiling (limited access due to equipment and space) above metal tile | | | | YES | |
| 19885 | ACTIVE | N | N105-00-4/751/FLR-01 | Floor - 1 - Station Control Room - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, plastic cable, CMS beneath computer tiles (nylon) | | | | | YES |
| 19926 | ACTIVE | N | N105-00-4/751/WAL-003 | Wall: Internal - 3 - Station Control Room - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding | | | | | |
| 19497 | ACTIVE | N | N105-00-4/751/WAL-004 | Wall: Internal - 4 - Station Control Room - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Boxing - supalux & wood | | | | | |
| 10167 | ACTIVE | N | N105-00-4/756 | Stairs: Linear - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10168 | ACTIVE | N | N105-00-4/771 | Pump Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19928 | ACTIVE | N | N105-00-4/771 | Pump Room - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring Caulking | | | | | |
| 10169 | ACTIVE | N | N105-00-4/772 | Lobby - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19930 | ACTIVE | N | N105-00-4/772/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Area accessed - no visible asbestos | | | | YES | |
| 19929 | ACTIVE | N | N105-00-4/772/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux 6m², to suspended ceiling | | | | | |
| 10170 | ACTIVE | N | N105-00-4/773 | Equipment Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42656 | INACTIVE | N | N105-00-4/773 | Equipment Room - Station Building - Tottenham Court Road Stn | Isolator Switches | Asbestos | Removed | | | | Materials within red, x2, to wall 4 by door to track, equipment room 4/773 (floodgate). - REMOVED by Econ 22/11/2012 | | | R515576 | N | N |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|--------------------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 42655 | INACTIVE | N | N105-00-4/773 | Equipment Room - Station Building - Tottenham Court Road Stn | Isolator Switches | Asbestos | Room: Surveyed – Asbestos Known | | | | Composite panel, 2 x ½m2, 2 x to either side of 30amp switch boxes to wall 4, equipment room 4/773 (floodgate) | | | R515576 | N | N |
| 42654 | ACTIVE | N | N105-00-4/773 | Equipment Room - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Sampled – Not Detected | | | | Braided cables – white, 4 units x 2 cables, within 4x30amp switch boxes to wall 4, equipment room 4/773 (floodgate) | | | R515576 | N | N |
| 19933 | ACTIVE | N | N105-00-4/773 | Equipment Room - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Known | | | | Sheathed Wiring. Encapsulated where accessible by Econ ES3071 | | | | | |
| 42653 | ACTIVE | N | N105-00-4/773 | Equipment Room - Station Building - Tottenham Court Road Stn | Rope Gaskets | Asbestos | Sampled – Not Detected | | | | Rope-gasket, 4 x 11lim units, to rear of 4x30amp switch boxes throughout – to wall 4, equipment room 4/773 (floodgate). | | | R515576 | N | N |
| 19931 | ACTIVE | N | N105-00-4/773/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Known | | | | All walls - Tunnel Rings Caulking Amphibole. Encapsulated where accessible by Econ ES3071 | | | | | |
| 46501 | ACTIVE | N | N105-00-4/773/WAL-001 80913619 | Wall: Internal - 1 - Lobby - Station Building - Tottenham Court Road Stn Wall: Internal | Isolator Switches | Asbestos | Presumed | | | | 6x Combination Fuse Switches to Wall 1. Presumed asbestos materials within. | | 6 | | | |
| 19498 | ACTIVE | N | N105-00-4/773/WAL-001 | Wall: Internal - 1 - Lobby - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Known | | | | All walls - Tunnel Rings Caulking Amphibole. Encapsulated where accessible by Econ ES3071 | | | | | |
| 19932 | ACTIVE | N | N105-00-4/773/WAL-001 | Wall: Internal - 1 - Lobby - Station Building - Tottenham Court Road Stn | Boarding: Cement | Asbestos | Known | | | | Composite boarding to wall 1, between 4th & 6th isolators & between 2nd and 3rd isolator Boarding - Chrysotile | | | | | |
| 10171 | ACTIVE | N | N105-00-4/774 | Fan Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19499 | ACTIVE | N | N105-00-4/774/CLG-01 | Ceiling: Solid - 1 - Fan Room - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Strongly Presumed | | | | Above concrete ceiling | | | | | |
| 19683 | ACTIVE | N | N105-00-4/774/FLR-01 | Floor - 1 - Fan Room - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking beneath floor | | | | | YES |
| 19934 | ACTIVE | N | N105-00-4/774/WAL-001 | Wall: Internal - 1 - Fan Room - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Presumed | | | | Tunnel Ring Caulking behind Concrete and Supalux Panel | | | | | |
| 10172 | ACTIVE | N | N105-00-4/775 | Pump Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19935 | INACTIVE | N | N105-00-4/775 | Pump Room - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 19990 | ACTIVE | N | N105-00-4/775 | Pump Room - Station Building - Tottenham Court Road Stn | Isolator Switches | Asbestos | Known | | | | CFS Switch boxes - Asbestos materials within. | | 5 | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 43432 | ACTIVE | N | N105-00-4/775 | Pump Room - Station Building - Tottenham Court Road Stn | Gasket :Pipework | Asbestos | Known | | | | Gaskets to flanges on pump equipment situated on floor | | | | N | N |
| 10173 | ACTIVE | N | N105-00-4/776 | Fan Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19937 | ACTIVE | N | N105-00-4/776 | Fan Room - Station Building - Tottenham Court Road Stn | Rope Gaskets | Asbestos | Known | | | | Rope Gasket throughout to fan unit flanges | | | | | |
| 19936 | ACTIVE | N | N105-00-4/776 | Fan Room - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux boxing throughout to small air conditioner duct works by stairs/ ladder - | | | | | |
| 10174 | ACTIVE | N | N105-00-4/786 | Service Riser - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19938 | ACTIVE | N | N105-00-4/786 | Service Riser - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 19939 | ACTIVE | N | N105-00-4/791 | Vent Shaft - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 19500 | ACTIVE | N | N105-00-4/792 | Vent Shaft - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 19940 | ACTIVE | N | N105-00-4/793 | Vent Shaft - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Concrete. Supalux panel above switch room 4/663 | | | | | |
| 19941 | ACTIVE | N | N105-00-4/793 | Vent Shaft - Station Building - Tottenham Court Road Stn | Mastic | Asbestos | Known | | | | Mastic to ductwork | | | | | |
| 19501 | ACTIVE | N | N105-00-4/795 | Vent Shaft - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 19942 | ACTIVE | N | N105-00-4/796 | Vent Shaft - Station Building - Tottenham Court Road Stn | Rope Gaskets | Asbestos | Known | | | | Gasket to ventilation machinery | | | | | |
| 25901 | ACTIVE | N | N105-00-4/796 | Vent Shaft - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux debris (<1m2) to top of ventilation control panel by stairs and to floor. | | | | N | N |
| 19944 | ACTIVE | N | N105-00-4/796 | Vent Shaft - Station Building - Tottenham Court Road Stn | Isolator Switches | Asbestos | Known | | | | 5no. CFS Switch Boxes - Asbestos materials within | | 5 | | | |
| 19502 | ACTIVE | N | N105-00-4/797 | Vent Shaft - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10175 | ACTIVE | N | N105-00-4/901 | Disused Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19509 | ACTIVE | N | N105-00-4/901 | Disused Room - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Known | | | | Tunnel Rings - Caulking - Amphibole. Encapsulated by Econ ES3071 | | | | | |
| 19989 | ACTIVE | N | N105-00-4/901/CLG-01 | Ceiling: Solid - 1 - Disused Room - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Known | | | | Tunnel Rings - Caulking - Amphibole. Encapsulated by Econ ES3071 | | | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 10176 | ACTIVE | N | N105-00-4/902 | Pump Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10177 | ACTIVE | N | N105-00-4/903 | Switch Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19991 | ACTIVE | N | N105-00-4/903 | Switch Room - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10178 | ACTIVE | N | N105-00-4/904 | Switch Cupboard - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19510 | ACTIVE | N | N105-00-4/904 | Switch Cupboard - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10179 | ACTIVE | N | N105-00-4/951 | Mess Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19424 | ACTIVE | N | N105-00-4/951 | Mess Room - Station Building - Tottenham Court Road Stn | Mastic | Asbestos | Known | | | | Mastic to ductwork | | | | | |
| 19992 | INACTIVE | N | N105-00-4/951 | Mess Room - Station Building - Tottenham Court Road Stn | LUL Heaters | Asbestos | No Access: Presumed | | | | Heater - Insulation Foam Board | | | | | |
| 10180 | ACTIVE | N | N105-00-4/953 | CER - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19993 | ACTIVE | N | N105-00-4/953 | CER - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Strongly Presumed | | | | Caulking beneath Tiles, Concrete - Walls | | | | | YES |
| 19545 | ACTIVE | N | N105-00-4/953/CLG-01 | Ceiling: Solid - 1 - CER - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Strongly Presumed | | | | Caulking above Tiles, Concrete - Walls | | | | | YES |
| 19886 | ACTIVE | N | N105-00-4/953/FLR-01 | Floor - 1 - CER - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Known | | | | Caulking beneath Tiles | | | | | YES |
| 10181 | ACTIVE | N | N105-00-4/971 | CER - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19994 | ACTIVE | N | N105-00-4/971 | CER - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10182 | ACTIVE | N | N105-00-5/201 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19511 | ACTIVE | N | N105-00-5/201 | Passage - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|---------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 10183 | ACTIVE | N | N105-00-5/202 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19995 | ACTIVE | N | N105-00-5/202/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Tottenham Court Road Stn | Void | Asbestos | No Access: Presumed | | | | Above false ceiling | | | | YES | |
| 10184 | ACTIVE | N | N105-00-5/203 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19512 | ACTIVE | N | N105-00-5/203/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Tottenham Court Road Stn | Void | Asbestos | No Access: Presumed | | | | Above false ceiling | | | | YES | |
| 10185 | ACTIVE | N | N105-00-5/204 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19809 | ACTIVE | N | N105-00-5/204 | Passage - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux panel high level, above bottom of stairs | | | | | |
| 19996 | ACTIVE | N | N105-00-5/204/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Tottenham Court Road Stn | Void | Asbestos | No Access: Presumed | | | | Above false ceiling | | | | YES | |
| 10186 | ACTIVE | N | N105-00-5/205 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42155 | ACTIVE | N | N105-00-5/205 | Passage - Station Building - Tottenham Court Road Stn | Cable Duct: Other | Asbestos | Removed | | | | Asbestos Duct removal from stairs - breakout of area 12m x 2m x 100mm deep in area | | | | | |
| 10187 | ACTIVE | N | N105-00-5/261 | Platform 1 - Westbound Local - Central Line - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19998 | ACTIVE | N | N105-00-5/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | Platform 1 Invert - All bitumen cable ducts have been sampled | | | | | YES |
| 19997 | ACTIVE | N | N105-00-5/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | Bitumen cable ducts track side wall | | | | | |
| 10188 | ACTIVE | N | N105-00-5/262 | Platform 2 - Eastbound Local - Central Line - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19513 | ACTIVE | N | N105-00-5/262 | Platform 2 - Eastbound Local - Central Line - Station Building - Tottenham Court Road Stn | Cable Ducts: Cement | Asbestos | Known | | | | 4 x cement cable ducts - to top of bank of cable ducts nearest to tunnel | | 4 | | | |
| 19999 | ACTIVE | N | N105-00-5/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | 6x Bitumen cable ducts - Trackside wall (concrete block furthrese from tunnel) | | | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-------------------------------|--|---------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 20000 | ACTIVE | N | N105-00-5/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | Platform 2 Invert - 10x Bitumen Ducts at Departure End of Invert | | | | | YES |
| 20001 | ACTIVE | N | N105-00-5/262/FLR-01 80913314 | Floor - 1 - Platform 2 - Station Building - Tottenham Court Road Stn Floor | Cable Ducts: Cement | Asbestos | Strongly Presumed | | | | Platform 2 Invert - Asbestos duct below 5/661 No access within invert 2024 re-inspection - confined space team required. | | | | | YES |
| 10189 | ACTIVE | N | N105-00-5/396 | SVC - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20002 | ACTIVE | N | N105-00-5/396 | SVC - Station Building - Tottenham Court Road Stn | Gasket :Pipework | Asbestos | Presumed | | | | Platform 2 Invert - No Gastets visible to Pipework to Fire Hydrants No access within invert 2024 re-inspection - confined space team required. | | | | | |
| 10190 | ACTIVE | N | N105-00-5/661 | Switch Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20005 | ACTIVE | N | N105-00-5/661 | Switch Room - Station Building - Tottenham Court Road Stn | Cable Duct: Other | Asbestos | Known | | | | Cable sleeve to floor | | 2 | | | |
| 20003 | ACTIVE | N | N105-00-5/661/CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above false ceiling | | | | YES | |
| 19514 | ACTIVE | N | N105-00-5/661/CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux, Concrete | | | | | |
| 19731 | ACTIVE | N | N105-00-5/661/CLG-02 | Ceiling: Suspended - 2 - Switch Room - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux, Concrete | | | | | |
| 20004 | ACTIVE | N | N105-00-5/661/CLG-02 | Ceiling: Suspended - 2 - Switch Room - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above false ceiling | | | | YES | |
| 10191 | ACTIVE | N | N105-00-5/662 | Switch Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20006 | ACTIVE | N | N105-00-5/662/DOR-01 | Door - 1 - Switch Room - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux panels around edges of door | | | | | |
| 10192 | ACTIVE | N | N105-00-5/663 | Switch Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20007 | ACTIVE | N | N105-00-5/663 | Switch Room - Station Building - Tottenham Court Road Stn | Isolator Switches | Asbestos | Surveyed – Not Detected | | | | All asbestos insulation materials removed | | 4 | | | |
| 20221 | ACTIVE | N | N105-00-5/663/DOR-01 | Door - 1 - Switch Room - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux panels above door (firebreak) | | | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|----------------------|---------------|--|----------|-----------|-----------------|---------------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 10193 | ACTIVE | N | N105-00-5/664 | Switch Cupboard - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10194 | ACTIVE | N | N105-00-5/670 | Switch Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20008 | ACTIVE | N | N105-00-5/670/DOR-01 | Door - 1 - Switch Room - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding around edges of door | | | | | |
| 10195 | ACTIVE | N | N105-00-5/711 | Relay Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20010 | ACTIVE | N | N105-00-5/711 | Relay Room - Station Building - Tottenham Court Road Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Durasteel Boarding | | | | | |
| 20009 | ACTIVE | N | N105-00-5/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boards | | | | | |
| 10196 | ACTIVE | N | N105-00-5/712 | Relay Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20054 | ACTIVE | N | N105-00-5/712/WAL-004 | Wall: Internal - 4 - Relay Room - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel to RHS W4 Door | | | | | |
| 10197 | ACTIVE | N | N105-00-5/761 | Service Riser - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20055 | ACTIVE | N | N105-00-5/761/DOR-01 | Door - 1 - Equipment Room - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux panels above doors | | | | | |
| 20056 | ACTIVE | N | N105-00-5/761/DOR-02 | Door - 2 - Equipment Room - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux panels above doors | | | | | |
| 10198 | ACTIVE | N | N105-00-5/901 | Disused Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19217 | ACTIVE | N | N105-00-5/901 | Disused Room - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10199 | ACTIVE | N | N105-00-6/161 | LMC - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20058 | ACTIVE | N | N105-00-6/161 | LMC - Station Building - Tottenham Court Road Stn | Cable Ducts: Bitumen | Asbestos | Presumed | | | | Bitumen Ducts - RHS to upper wall | | 2 | | | |
| 20057 | ACTIVE | N | N105-00-6/161 | LMC - Station Building - Tottenham Court Road Stn | Bitumen | Asbestos | Presumed | | | | Bitumen Ducts - LHS to upper wall | | 3 | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 10200 | ACTIVE | N | N105-00-6/201 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20059 | ACTIVE | N | N105-00-6/201 | Passage - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10201 | ACTIVE | N | N105-00-6/202 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19888 | ACTIVE | N | N105-00-6/202 | Passage - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10202 | ACTIVE | N | N105-00-6/203 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19218 | ACTIVE | N | N105-00-6/203/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid above VE Panels | | | | YES | |
| 10203 | ACTIVE | N | N105-00-6/204 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20060 | ACTIVE | N | N105-00-6/204 | Passage - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux fire breaks adjacent to both platforms | | | | | |
| 20061 | ACTIVE | N | N105-00-6/204/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid above VE Panels | | | | YES | |
| 10204 | ACTIVE | N | N105-00-6/205 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20062 | ACTIVE | N | N105-00-6/205 | Passage - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux fire breaks adjacent to both platforms | | | | | |
| 10205 | ACTIVE | N | N105-00-6/206 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20063 | ACTIVE | N | N105-00-6/206/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Tottenham Court Road Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Fibrous Board nr 6/396 & 6/761 above metal ceiling | | | | YES | |
| 10206 | ACTIVE | N | N105-00-6/207 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19219 | ACTIVE | N | N105-00-6/207 | Passage - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux fire breaks adjacent to both platforms | | | | | |
| 20064 | ACTIVE | N | N105-00-6/207/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above metal ceiling | | | | YES | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------|---|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 10207 | ACTIVE | N | N105-00-6/208 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20065 | ACTIVE | N | N105-00-6/208 | Passage - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10208 | ACTIVE | N | N105-00-6/209 | Passage - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20066 | ACTIVE | N | N105-00-6/209 | Passage - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10209 | ACTIVE | N | N105-00-6/263 | Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 25758 | ACTIVE | N | N105-00-6/263 | Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn | Westing house Boxes | Asbestos | Presumed | | | | Platform Invert - materials within Westinghouse box to platform wall No access within invert 2024 re-inspection - confined space team required. | | | | | |
| 25759 | ACTIVE | N | N105-00-6/263 | Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn | | Asbestos | Sampled – Not Detected | | | | Platform Invert - Ducts to wall at end of invert. Gasket to platform wall of invert. Cable duct to trackside wall. Cable duct to platform wall. Caulking to tunnel ring flanges to invert. Cable Ducts throughout to trackside - Asbestos not detected in samples | | | | | |
| 20067 | ACTIVE | N | N105-00-6/263 | Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Presumed | | | | Braided Cable - used to tie up other cables throughout invert No access within invert 2024 re-inspection - confined space team required. | | | | | |
| 25751 | ACTIVE | N | N105-00-6/263 | Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Known | | | | Platform Invert - Large green encapsulated braided cable along trackside No access within invert 2024 re-inspection - confined space team required. | | | | | |
| 20068 | INACTIVE | N | N105-00-6/263 | Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn | Cable Duct: Other | Asbestos | Presumed | | | | Ducts entering invert - arrivals end. If ducts are to be utilised, HMU to advise | | | | | |
| 41952 | ACTIVE | N | N105-00-6/263 | Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn | Cable Ducts: Cement | Asbestos | Known | | | | 2 x Cement Cable Ducts - RHS to headwall at arrival end | | 2 | | N | N |
| 41951 | ACTIVE | N | N105-00-6/263 | Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | 3 x Bitumen Cable Ducts - RHS to headwall of arrival end | | 3 | | N | N |
| 25757 | ACTIVE | N | N105-00-6/263 | Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Known | | | | Yellow braided cable to head wall | | | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 25756 | ACTIVE | N | N105-00-6/263 | Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Known | | | | Platform Invert - White small braided cable along trackside to Westinghouse electrical box No access within invert 2024 re-inspection - confined space team required. | | | | | |
| 25755 | ACTIVE | N | N105-00-6/263 | Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn | Cable Duct: Other | Asbestos | Presumed | | | | Platform 3 Invert - 4 x visible ducts No access within invert 2024 re-inspection - confined space team required. | | 4 | | | |
| 41953 | ACTIVE | N | N105-00-6/263 | Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | 2 x Bitumen cable ducts - LHS to trackside wall of arrival end | | 2 | | N | N |
| 41954 | ACTIVE | N | N105-00-6/263 | Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn | Cable Ducts: Bitumen | Asbestos | Surveyed – Not Detected | | | | 2 x Bitumen Cable Ducts - LHS to trackside wall at arrival end | | 2 | | N | N |
| 25753 | ACTIVE | N | N105-00-6/263 | Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn | Cable Duct: Other | Asbestos | Strongly Presumed | | | | Platform 3 Invert - 16 x Ducts No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score material within. | | 16 | | | |
| 19221 | ACTIVE | N | N105-00-6/263/ FLR-01 | Floor - 1 - Platform 3 - Station Building - Tottenham Court Road Stn | Gasket :Pipework | Asbestos | Strongly Presumed | | | | Platform 3 Invert - access to the pipe gaskets was not possible and they must be strongly presumed to contain Chrysotile asbestos. No access within invert 2024 re-inspection - confined space team required. | | | | | YES |
| 20069 | ACTIVE | N | N105-00-6/263/ FLR-01 | Floor - 1 - Platform 3 - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Known | | | | Platform 3 Invert - Various braided cables either end of the invert. Encapsulated by Econ ES3071 No access within invert 2024 re-inspection - confined space team required. | | | | | YES |
| 10210 | ACTIVE | N | N105-00-6/264 | Platform 4 - Southbound Local - Northern Line - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20070 | ACTIVE | N | N105-00-6/264 | Platform 4 - Southbound Local - Northern Line - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 50mm cables nr 6/208 | | 1 | | | |
| 25786 | ACTIVE | N | N105-00-6/264 | Platform 4 - Southbound Local - Northern Line - Station Building - Tottenham Court Road Stn | Cable Duct: Other | Asbestos | Sampled – Not Detected | | | | Platform 4 Invert - Cable ducts (>10 no.) to walls and ceiling. | | | | | |
| 25787 | ACTIVE | N | N105-00-6/264 | Platform 4 - Southbound Local - Northern Line - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Known | | | | Platform 4 Southbound Invert - Braided cables (>10 no.) to cable run, coming in and going out of invert into Relay Room and Track. No access within invert 2024 re-inspection - confined space team required. | | 10 | | | |
| 19734 | ACTIVE | N | N105-00-6/264 | Platform 4 - Southbound Local - Northern Line - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 10mm cables nr 6/208 | | 1 | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-------------------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 20071 | ACTIVE | N | N105-00-6/264 | Platform 4 - Southbound Local - Northern Line - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Presumed | | | | 50mm cable nr 6/712 going to track - Note 6/712 does not exist. Unable to locate ACM, Presumed still present | | 1 | | | |
| 41949 | ACTIVE | N | N105-00-6/264 | Platform 4 - Southbound Local - Northern Line - Station Building - Tottenham Court Road Stn | Cable Duct: Other | Asbestos | Presumed | | | | 1 x Cable Duct behind panel to headwall - limited access. | | 1 | | N | N |
| 41947 | ACTIVE | N | N105-00-6/264 | Platform 4 - Southbound Local - Northern Line - Station Building - Tottenham Court Road Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | 3 x Bitumen Cable Ducts - RHS to headwall of departure end | | 3 | | N | N |
| 25742 | ACTIVE | N | N105-00-6/264 | Platform 4 - Southbound Local - Northern Line - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Presumed | | | | Platform 4 Invert - 1x 10 Core box with 2 braided cabels within box No access within invert 2024 re-inspection - confined space team required. | | 1 | | | |
| 25792 | ACTIVE | N | N105-00-6/264 | Platform 4 - Southbound Local - Northern Line - Station Building - Tottenham Court Road Stn | Cable Duct: Other | Asbestos | Presumed | | | | Platform 4 Southbound Invert - 10-core box (1 no.), to wall with 2 no. braided cables within box. No access within invert 2024 re-inspection - confined space team required. | | 2 | | | |
| 25789 | ACTIVE | N | N105-00-6/264 | Platform 4 - Southbound Local - Northern Line - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Presumed | | | | Platform 4 Southbound Invert - 1 x 10-core box to wall with 2 no. braided cables within box. No access within invert 2024 re-inspection - confined space team required. | | | | | |
| 25791 | ACTIVE | N | N105-00-6/264 | Platform 4 - Southbound Local - Northern Line - Station Building - Tottenham Court Road Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Platform 4 Southbound Invert - 1 x 10-core box to wall with 2 no. braided cables within box. No access within invert 2024 re-inspection - confined space team required. | | | | | |
| 20072 | ACTIVE | N | N105-00-6/264/FLR-01 | Floor - 1 - Platform 4 - Station Building - Tottenham Court Road Stn | Cable Duct: Other | Asbestos | Surveyed – Not Detected | | | | Platform 4 Invert - Cable ducts (>10 no.), to walls and ceiling. | | | | | YES |
| 19889 | INACTIVE | N | N105-00-6/264/FLR-01 | Floor - 1 - Platform 4 - Station Building - Tottenham Court Road Stn | Cable Duct: Other | Asbestos | Surveyed – Not Detected | | | | Platform 4 Invert - 1x Cable ducts - Invert depature end. If ducts are to be utilised, HMU to advise | | | | | YES |
| 20073 | ACTIVE | N | N105-00-6/264/FLR-01 80913967 | Floor - 1 - Platform 4 - Station Building - Tottenham Court Road Stn Floor | Cable: Sheath | Asbestos | Known | | | | Various braided Cables near to route at arrivals and departure. Encapsulated by Econ ES3071 11 hangers. From floor up the first 5 do not have asbestos cables laying within. From 5 up there is a mismatch of asbestos cables. 2 x green and 1 x yellow. 30m into the invert small bore asbestos cabling has also been used as cable ties. | | | | | YES |
| 10211 | ACTIVE | N | N105-00-6/371 | CER - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20074 | INACTIVE | N | N105-00-6/371/FLR-01 | Floor - 1 - CER - Station Building - Tottenham Court Road Stn | Void | Asbestos | No Access: Presumed | | | | Ducts into floor - Wall 2 and 3 no access due to heavy use of fire stop. | | | | | YES |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 20075 | INACTIVE | N | N105-00-6/371/WAL-001 | Wall: Internal - 1 - CER - Station Building - Tottenham Court Road Stn | Void | Asbestos | No Access: Presumed | | | | Electrical box - No access, front shutter down | | | | | |
| 19222 | ACTIVE | N | N105-00-6/371/WAL-002 | Wall: Internal - 2 - CER - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Not Found during Inspection | | | | 40mm Woven cables sleeve 1LM Room not present 2020 re-inspection - station upgrade / crossrail | | 2 | | | |
| 19735 | ACTIVE | N | N105-00-6/371/WAL-002 | Wall: Internal - 2 - CER - Station Building - Tottenham Court Road Stn | Other Electrical Boxes | Asbestos | Not Found during Inspection | | | | Electrical box, suliminite within Room not present 2020 re-inspection - station upgrade / crossrail | | 1 | | | |
| 19230 | ACTIVE | N | N105-00-6/371/WAL-003 | Wall: Internal - 3 - CER - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Not Found during Inspection | | | | 40mm woven cable exit room into track Room not present 2020 re-inspection - station upgrade / crossrail | | | | | |
| 19547 | ACTIVE | N | N105-00-6/371/WAL-004 | Wall: Internal - 4 - CER - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Not Found during Inspection | | | | 5mm Electric cables woven shealth - high level Room not present 2020 re-inspection - station upgrade / crossrail | | | | | |
| 10212 | ACTIVE | N | N105-00-6/381 | Equipment Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20125 | ACTIVE | N | N105-00-6/381 | Equipment Room - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding & Panel above door | | | | | |
| 10213 | ACTIVE | N | N105-00-6/396 | Disused Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20126 | ACTIVE | N | N105-00-6/396 | Disused Room - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10214 | ACTIVE | N | N105-00-6/401 | Store - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20127 | ACTIVE | N | N105-00-6/401 | Store - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board | | | | | |
| 19231 | ACTIVE | N | N105-00-6/401/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board | | | | | |
| 20128 | ACTIVE | N | N105-00-6/401/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Tottenham Court Road Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Board | | | | YES | |
| 10215 | ACTIVE | N | N105-00-6/481 | Stretcher Cupboard - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------|--|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 20129 | ACTIVE | N | N105-00-6/481 | Stretcher Cupboard - Station Building - Tottenham Court Road Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10216 | ACTIVE | N | N105-00-6/663 | Switch Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20131 | INACTIVE | N | N105-00-6/663 | Switch Room - Station Building - Tottenham Court Road Stn | Isolator Switches | Asbestos | Removed | | | | W3 - 1 x Switch Box - insulation within - Removed | | 1 | | | |
| 20130 | ACTIVE | N | N105-00-6/663 | Switch Room - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding & Panels by Door | | | | | |
| 10217 | ACTIVE | N | N105-00-6/672 | Switch Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19232 | ACTIVE | N | N105-00-6/672 | Switch Room - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux boarding around edges of door | | | | | |
| 10218 | ACTIVE | N | N105-00-6/673 | Switch Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19738 | ACTIVE | N | N105-00-6/673 | Switch Room - Station Building - Tottenham Court Road Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux boarding around edges of door | | | | | |
| 10219 | ACTIVE | N | N105-00-6/711 | Relay Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 25883 | INACTIVE | N | N105-00-6/711 | Relay Room - Station Building - Tottenham Court Road Stn | Other Electrical Boxes | Asbestos | Removed | | | | 10 Core Boxes | | 1 | | N | N |
| 25879 | INACTIVE | N | N105-00-6/711 | Relay Room - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Removed | | | | 10 + Braided Cables from fuses | | 10 | | N | N |
| 25878 | INACTIVE | N | N105-00-6/711 | Relay Room - Station Building - Tottenham Court Road Stn | | Asbestos | Removed | | | | 10 + Fuses | | 10 | | N | N |
| 25780 | ACTIVE | N | N105-00-6/711 | Relay Room - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Removed | | | | Braided cable within cabinet/box LHS away from door Date identified 08/09/2014 | | | | | |
| 25779 | INACTIVE | N | N105-00-6/711 | Relay Room - Station Building - Tottenham Court Road Stn | Other Boarding | Asbestos | Removed | | | | Melamine board, within cabinet/box LHS away from door. | | | | | |
| 41942 | ACTIVE | N | N105-00-6/711 | Relay Room - Station Building - Tottenham Court Road Stn | Cable Duct: Other | Asbestos | Sampled – Not Detected | | | | 4 x 1m Cable Troughing / Ducting | 1 | 4 | | N | |
| 25884 | INACTIVE | N | N105-00-6/711 | Relay Room - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Removed | | | | 7 x Braided cables from fuse box | | 7 | | N | N |
| 25885 | INACTIVE | N | N105-00-6/711 | Relay Room - Station Building - Tottenham Court Road Stn | Other Boarding | Asbestos | Removed | | | | Fuses to Braided cables | | 10 | | N | N |
| 25876 | INACTIVE | N | N105-00-6/711 | Relay Room - Station Building - Tottenham Court Road Stn | Other Electrical Boxes | Asbestos | Removed | | | | 1 x Capacitor Unit | | 1 | | N | N |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|------------------------|--------------------------|-----------------------------|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 25781 | ACTIVE | N | N105-00-6/711 | Relay Room - Station Building - Tottenham Court Road Stn | Cable Duct: Other | Asbestos | Not Found during Inspection | | | | Ducts within cabinet/box LHS away from door. Room not present 2020 re-inspection - station upgrade / crossrail | | | | | |
| 25882 | ACTIVE | N | N105-00-6/711 | Relay Room - Station Building - Tottenham Court Road Stn | Westing house Boxes | Asbestos | Removed | | | | 2 x Large Westinghouse Boxes - left hand wall | | 2 | | N | N |
| 25877 | INACTIVE | N | N105-00-6/711 | Relay Room - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Removed | | | | Braided cables from Capacitor unit | | 2 | | N | N |
| 19811 | ACTIVE | N | N105-00-6/711/FLR-01 | Floor - 1 - Relay Room - Station Building - Tottenham Court Road Stn | Cable Ducts: Cement | Asbestos | Not Found during Inspection | | | | Cable Ducts to Corner of Room W2&3; No Access Sealed; Room not present 2020 re-inspection - station upgrade / crossrail | | | | | |
| 20314 | ACTIVE | N | N105-00-6/711/FLR-01 | Floor - 1 - Relay Room - Station Building - Tottenham Court Road Stn | Cable Duct: Other | Asbestos | Not Found during Inspection | | | | Large Cable Ducts by Wall 1 within Racking Room not present 2020 re-inspection - station upgrade / crossrail | | 2 | | | |
| 42491 | ACTIVE | N | N105-00-6/711/FLR-01 | Floor - 1 - Relay Room - Station Building - Tottenham Court Road Stn | Cable Duct: Other | Asbestos | Not Found during Inspection | | | | 5 x cable ducts to floor descending into invert below Platform 3 northbound Room not present 2020 re-inspection - station upgrade / crossrail | | | R481901 | N | N |
| 20318 | INACTIVE | N | N105-00-6/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Removed | | | | Small Woven Cables running between Fuse Box from W1 accross W2 to Fuse Boxes on W3; Potentially only Cotton; | | | | | |
| 20312 | INACTIVE | N | N105-00-6/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Tottenham Court Road Stn | Westing house Boxes | Asbestos | Removed | | | | Westinghouse Box | | 1 | | | |
| 20313 | INACTIVE | N | N105-00-6/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Tottenham Court Road Stn | Other Electrical Boxes | Asbestos | Removed | | | | Other Electrical Box - Insulation within | | 1 | | | |
| 20315 | INACTIVE | N | N105-00-6/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Tottenham Court Road Stn | Other Boarding | Asbestos | Removed | | | | Arc Chutes to Fuses within Racking | | 53 | | | |
| 20309 | ACTIVE | N | N105-00-6/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Not Found during Inspection | | | | Caulking within Tunnel Rings behind Render Room not present 2020 re-inspection - station upgrade / crossrail | | | | | |
| 20317 | INACTIVE | N | N105-00-6/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Removed | | | | Woven Sheathed Cables within Racking; Approx 3no | | 3 | | | |
| 20316 | INACTIVE | N | N105-00-6/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Tottenham Court Road Stn | PCBs | Polychlorinated biphenyl | Removed | | | | Relay Boxes - PCBs within; Within Racking | | 6 | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 20319 | INACTIVE | N | N105-00-6/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Tottenham Court Road Stn | Other Electrical Boxes | Asbestos | Removed | | | | 600V Box (+2no Power Feed Cables see 19233) | | 1 | | | |
| 25777 | ACTIVE | N | N105-00-6/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Tottenham Court Road Stn | Cable Duct: Other | Asbestos | Not Found during Inspection | | | | Duct - corner of Wall 2 & 3. Date Identified 08/09/2014 Room not present 2020 re-inspection - station upgrade / crossrail | | | | | |
| 20134 | INACTIVE | N | N105-00-6/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Tottenham Court Road Stn | Other Electrical Boxes | Asbestos | Removed | | | | Electrical box H/L - Paxoline Boxing within - Removed | | 1 | | | |
| 25776 | ACTIVE | N | N105-00-6/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Removed | | | | Braided cable to wall 2 going into floor duct. | | | | | |
| 19233 | INACTIVE | N | N105-00-6/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Removed | | | | 2no 40mm woven cables from 600V Box (see 20319) - Encapsulated. 1no exits to Invert via Floor; 1no exits to Track W3; | | 2 | | | |
| 20308 | INACTIVE | N | N105-00-6/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Removed | | | | Small Woven Cables running between Perspex Faced Electrical Fuse Boxes - Potentially only cotton; | | | | | |
| 20132 | INACTIVE | N | N105-00-6/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Removed | | | | 5no Sheathed Cables. Encapsulated by Econ ES3071 | | 5 | | | |
| 20133 | INACTIVE | N | N105-00-6/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Removed | | | | 40mm Cable exits room into track - Removed | | | | | |
| 20310 | INACTIVE | N | N105-00-6/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn | Other Electrical Boxes | Asbestos | Removed | | | | Rectifier Box - Insulation materials within | | | | | |
| 25778 | INACTIVE | N | N105-00-6/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn | Other Boarding | Asbestos | Removed | | | | Melamine board to high level box | | | | | |
| 20311 | INACTIVE | N | N105-00-6/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn | Other Electrical Boxes | Asbestos | Removed | | | | Tencore Box | | 1 | | | |
| 10220 | ACTIVE | N | N105-00-6/712 | Relay Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 25772 | ACTIVE | N | N105-00-6/712 | Relay Room - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Removed | | | | Braided cable within box/cabinet next to the door. | | | | | |
| 25773 | INACTIVE | N | N105-00-6/712 | Relay Room - Station Building - Tottenham Court Road Stn | Other Boarding | Asbestos | Removed | | | | Melamine board, within box/ cabinet RHS next to door. | | | | | |
| 19739 | INACTIVE | N | N105-00-6/712 | Relay Room - Station Building - Tottenham Court Road Stn | Other Electrical Boxes | Asbestos | Removed | | | | Electric box - Paxoline within box | | 1 | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|------------------------|---------------|-----------------------------|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 19891 | ACTIVE | N | N105-00-6/712 | Relay Room - Station Building - Tottenham Court Road Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Durasteel panel above door | | | | | |
| 25891 | INACTIVE | N | N105-00-6/712 | Relay Room - Station Building - Tottenham Court Road Stn | Other Boarding | Asbestos | Removed | | | | 4 x Fuses and braided cables (left hand wall) | | 4 | | N | N |
| 25887 | INACTIVE | N | N105-00-6/712 | Relay Room - Station Building - Tottenham Court Road Stn | Other Electrical Boxes | Asbestos | Removed | | | | 1 x Capacitor Unit | | 1 | | N | N |
| 25889 | ACTIVE | N | N105-00-6/712 | Relay Room - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Removed | | | | 3 x Braided Cables to Capacitor Unit and Cable Duct Braided Cables and Capacitor removed | | 3 | | N | N |
| 25890 | INACTIVE | N | N105-00-6/712 | Relay Room - Station Building - Tottenham Court Road Stn | Other Electrical Boxes | Asbestos | Removed | | | | 1 x FG D/B 17 box | | 1 | | N | N |
| 25896 | ACTIVE | N | N105-00-6/712 | Relay Room - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Removed | | | | 3 x Braided cables | | 3 | | N | N |
| 25898 | INACTIVE | N | N105-00-6/712 | Relay Room - Station Building - Tottenham Court Road Stn | Other Boarding | Asbestos | Removed | | | | 4 x Fuses | | 4 | | N | N |
| 25771 | INACTIVE | N | N105-00-6/712 | Relay Room - Station Building - Tottenham Court Road Stn | Other Boarding | Asbestos | Removed | | | | Melamine board, to box no. TT12913 | | | | | |
| 25774 | ACTIVE | N | N105-00-6/712 | Relay Room - Station Building - Tottenham Court Road Stn | Cable Duct: Other | Asbestos | Not Found during Inspection | | | | Ducts within cabinet/box next to door in relay room. Date Identified 08/09/2014 Room not present 2020 re-inspection - station upgrade / crossrail | | | | | |
| 41751 | ACTIVE | N | N105-00-6/712 | Relay Room - Station Building - Tottenham Court Road Stn | Cable Duct: Other | Asbestos | Not Found during Inspection | | | | Large Ducts within Racking Room not present 2020 re-inspection - station upgrade / crossrail | | | | N | N |
| 25892 | ACTIVE | N | N105-00-6/712 | Relay Room - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Removed | | | | 3 x Braided cables going to fuses | | 3 | | N | N |
| 25888 | INACTIVE | N | N105-00-6/712 | Relay Room - Station Building - Tottenham Court Road Stn | Other Boarding | Asbestos | Removed | | | | 10 + Fuses next to Capacitor unit | | 10 | | N | N |
| 25894 | INACTIVE | N | N105-00-6/712 | Relay Room - Station Building - Tottenham Court Road Stn | Other Electrical Boxes | Asbestos | Removed | | | | 1 x Capacitor Unit | | 1 | | N | N |
| 25895 | INACTIVE | N | N105-00-6/712 | Relay Room - Station Building - Tottenham Court Road Stn | Other Boarding | Asbestos | Removed | | | | 10 + Fuses next to Capacitor unit | | 10 | | N | N |
| 25897 | INACTIVE | N | N105-00-6/712 | Relay Room - Station Building - Tottenham Court Road Stn | Other Electrical Boxes | Asbestos | Removed | | | | 1 x FG D/B 17 box | | 1 | | N | N |
| 25899 | ACTIVE | N | N105-00-6/712 | Relay Room - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Removed | | | | 3 x Braided cables to LHS wall going to fuses | | 3 | | N | N |
| 20332 | INACTIVE | N | N105-00-6/712/FLR-01 | Floor - 1 - Relay Room - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Removed | | | | 1no 10mm Cable Brown - Attached to Equipment on Racking by W3 | | 1 | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|------------------------|---------------|-----------------------------|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 20327 | ACTIVE | N | N105-00-6/712/FLR-01 | Floor - 1 - Relay Room - Station Building - Tottenham Court Road Stn | Cable Duct: Other | Asbestos | Not Found during Inspection | | | | Cable Ducts to Invert in Corner of Floor by Walls 1&2 - Sealed Room not present 2020 re-inspection - station upgrade / crossrail | | | | | |
| 20138 | INACTIVE | N | N105-00-6/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Removed | | | | 5mm woven sleeve cables - from high level perspex fronted fuse box, exits to floor. | | 2 | | | |
| 20322 | INACTIVE | N | N105-00-6/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Tottenham Court Road Stn | Other Electrical Boxes | Asbestos | Removed | | | | Rectifier Box H/L; Insulation materials within; | | 1 | | | |
| 25770 | INACTIVE | N | N105-00-6/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Removed | | | | Braided Cable to wall 2 going to floor. Date Identified 08/09/2014 | | | | | |
| 20324 | INACTIVE | N | N105-00-6/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Tottenham Court Road Stn | Other Electrical Boxes | Asbestos | Removed | | | | Distribution Box - Insulation Materials within | | 1 | | | |
| 20323 | INACTIVE | N | N105-00-6/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Tottenham Court Road Stn | Other Electrical Boxes | Asbestos | Removed | | | | 600V Box (+2no Power Feed Cables see 19280) | | 1 | | | |
| 19280 | INACTIVE | N | N105-00-6/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Removed | | | | 2no 40mm - from 600v Box exits to floor. Encapsulated. | | 2 | | | |
| 20320 | INACTIVE | N | N105-00-6/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Removed | | | | Cable Runs from Electrical Box W2 (19739) accross to Racking on W3 | | 1 | | | |
| 20321 | ACTIVE | N | N105-00-6/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn | Caulking | Asbestos | Not Found during Inspection | | | | Tunnel Ring Caulking behind Plaster Room not present 2020 re-inspection - station upgrade / crossrail | | | | | |
| 20331 | ACTIVE | N | N105-00-6/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn | Cable Duct: Other | Asbestos | Not Found during Inspection | | | | Large Cable Ducts by Wall 3 within Racking Room not present 2020 re-inspection - station upgrade / crossrail | | 2 | | | |
| 20137 | INACTIVE | N | N105-00-6/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn | Other Boarding | Asbestos | Removed | | | | Relay panels - Paxoline in various areas on panel - within Racking adjacent to Relay Boxes | | 7 | | | |
| 20325 | INACTIVE | N | N105-00-6/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn | Other Electrical Boxes | Asbestos | Removed | | | | Electrical Box - Insulation Materials within | | 1 | | | |
| 20328 | INACTIVE | N | N105-00-6/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn | Other Boarding | Asbestos | Removed | | | | Arc Chutes to Fuses within Racking | | | | | |



Hazardous Material Asset Register - Summary



N105-00 - Station Building - Tottenham Court Road Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|-----------------|--------------------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 20136 | INACTIVE | N | N105-00-6/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn | Cable: Sheath | Asbestos | Removed | | | | 2no 15mm woven cable - 1no Yellow 1no Green from Equipment into Large Ducts within Racking Cables removed | | 2 | | | |
| 20330 | INACTIVE | N | N105-00-6/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn | PCBs | Polychlorinated biphenyl | Removed | | | | Relay Boxes - PCBs within; Within Racking | | 6 | | | |
| 10221 | ACTIVE | N | N105-00-6/713 | Relay Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10222 | ACTIVE | N | N105-00-6/761 | Disused Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10223 | ACTIVE | N | N105-00-6/771 | Equipment Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10224 | ACTIVE | N | N105-00-6/901 | Disused Room - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10225 | ACTIVE | N | N105-00-A/081 | Lobby - Station Building - Tottenham Court Road Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20135 | ACTIVE | N | N105-00-A/081 | Lobby - Station Building - Tottenham Court Road Stn | No Access | Asbestos | Surveyed – Not Detected | | | | | | | | | |

N125-00 - Station Building - Angel Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 10843 | ACTIVE | N | N125-00-1/001 | Booking Hall - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18358 | ACTIVE | N | N125-00-1/001/CLG-01 | Ceiling: Solid - 1 - Booking Hall - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | YES | |
| 20026 | ACTIVE | N | N125-00-1/001/FLR-01 | Floor - 1 - Booking Hall - Station Building - Angel Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 16657 | ACTIVE | N | N125-00-1/001/FLR-01 | Floor - 1 - Booking Hall - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Rubber Tiles | | | | | YES |
| 16658 | ACTIVE | N | N125-00-1/001/FLR-01 | Floor - 1 - Booking Hall - Station Building - Angel Stn | Void | Asbestos | Surveyed – Not Detected | | | | Breeze Block Walls; Fibreglass Lagged Pipes above Supalux | | | | | YES |
| 10844 | ACTIVE | N | N125-00-1/011 | Ticket Office - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N125-00 - Station Building - Angel Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 10845 | ACTIVE | N | N125-00-1/021 | POM - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16660 | ACTIVE | N | N125-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Angel Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 16661 | ACTIVE | N | N125-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Angel Stn | Void | Asbestos | Surveyed – Not Detected | | | | Breeze Block Walls; Fibreglass Lagged Pipes above Supalux | | | | YES | |
| 16659 | ACTIVE | N | N125-00-1/021/FLR-01 | Floor - 1 - POM - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Rubber Tiles | | | | | YES |
| 10846 | ACTIVE | N | N125-00-1/031 | Mess Room - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18359 | ACTIVE | N | N125-00-1/031 | Mess Room - Station Building - Angel Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | 2 x Heaters - Foam Insulation Board | | | | | |
| 16662 | ACTIVE | N | N125-00-1/031 | Mess Room - Station Building - Angel Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 16664 | ACTIVE | N | N125-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Angel Stn | Void | Asbestos | Surveyed – Not Detected | | | | Solid Concrete Roof; Breeze Block Walls; Fibreglass Lagged Pipes above Supalux Ceiling | | | | YES | |
| 16663 | ACTIVE | N | N125-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Angel Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 10847 | ACTIVE | N | N125-00-1/036 | Lobby - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18360 | ACTIVE | N | N125-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 16665 | ACTIVE | N | N125-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 10848 | ACTIVE | N | N125-00-1/037 | Toilet: Unisex - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19051 | ACTIVE | N | N125-00-1/037/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Angel Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 16666 | ACTIVE | N | N125-00-1/037/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Angel Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 10849 | ACTIVE | N | N125-00-1/071 | Circulation Area - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16667 | ACTIVE | N | N125-00-1/071/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Angel Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above Metal Ceiling | | | | YES | |



Hazardous Material Asset Register - Summary



N125-00 - Station Building - Angel Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 10850 | ACTIVE | N | N125-00-1/236 | Lobby - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18361 | ACTIVE | N | N125-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 16670 | ACTIVE | N | N125-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn | Void | Asbestos | Surveyed – Not Detected | | | | Breeze Blocks above Supalux Ceiling | | | | YES | |
| 16669 | ACTIVE | N | N125-00-1/236/FLR-01 | Floor - 1 - Lobby - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Rubber Tiles | | | | | YES |
| 10851 | ACTIVE | N | N125-00-1/237 | Lobby - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16672 | ACTIVE | N | N125-00-1/237/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete Roof; Breeze Block Walls | | | | YES | |
| 16671 | ACTIVE | N | N125-00-1/237/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 10852 | ACTIVE | N | N125-00-1/238 | Lobby - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18362 | ACTIVE | N | N125-00-1/238/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Metal Duct above Supalux Tiles | | | | YES | |
| 16673 | ACTIVE | N | N125-00-1/238/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 10853 | ACTIVE | N | N125-00-1/239 | Lobby - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19963 | ACTIVE | N | N125-00-1/239/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 16674 | ACTIVE | N | N125-00-1/239/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Tiles | | | | YES | |
| 10854 | ACTIVE | N | N125-00-1/331 | Mess Room - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16676 | ACTIVE | N | N125-00-1/331 | Mess Room - Station Building - Angel Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - Foam Insulation Board | | | | | |
| 18363 | ACTIVE | N | N125-00-1/331 | Mess Room - Station Building - Angel Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 16677 | ACTIVE | N | N125-00-1/331/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Angel Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |



Hazardous Material Asset Register - Summary



N125-00 - Station Building - Angel Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 18836 | ACTIVE | N | N125-00-1/331/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Angel Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 10855 | ACTIVE | N | N125-00-1/341 | Station Supervisor Office - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19052 | ACTIVE | N | N125-00-1/341 | Station Supervisor Office - Station Building - Angel Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - Foam Insulation Board | | | | | |
| 16678 | ACTIVE | N | N125-00-1/341 | Station Supervisor Office - Station Building - Angel Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 18364 | ACTIVE | N | N125-00-1/341/CLG-01 | Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Angel Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 16679 | ACTIVE | N | N125-00-1/341/CLG-01 | Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Angel Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 10856 | ACTIVE | N | N125-00-1/416 | Toilet: Female - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16684 | ACTIVE | N | N125-00-1/416/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Angel Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 16683 | ACTIVE | N | N125-00-1/416/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Angel Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 10857 | ACTIVE | N | N125-00-1/417 | Toilet - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18365 | ACTIVE | N | N125-00-1/417/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 19053 | ACTIVE | N | N125-00-1/417/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 10858 | ACTIVE | N | N125-00-1/418 | Toilet: Male - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16685 | ACTIVE | N | N125-00-1/418/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Angel Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 16686 | ACTIVE | N | N125-00-1/418/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Angel Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 10859 | ACTIVE | N | N125-00-1/632 | Stairs: Spiral - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16689 | ACTIVE | N | N125-00-1/632 | Stairs: Spiral - Station Building - Angel Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Durasteel Boxing | | | | | |



Hazardous Material Asset Register - Summary



N125-00 - Station Building - Angel Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|------------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 10860 | ACTIVE | N | N125-00-1/661 | Switch Room - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44282 | ACTIVE | N | N125-00-1/661 | Switch Room - Station Building - Angel Stn | Cable Duct: Other | Asbestos | Presumed | | | | Ducts to floor - Presumed Cable ducts are not visible beneath cement layer on top to floor- therefore material not scored in 2020 re-inspection. | | | | N | N |
| 16690 | ACTIVE | N | N125-00-1/661/ WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Angel Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 x 30 amp Switch Box - Insulation within - No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | | |
| 18366 | ACTIVE | N | N125-00-1/661/ WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Angel Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 4 x Transformer Boxes No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within | | 4 | | | |
| 10861 | ACTIVE | N | N125-00-1/731 | CER - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16693 | ACTIVE | N | N125-00-1/731/ FLR-01 | Floor - 1 - CER - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |
| 19054 | ACTIVE | N | N125-00-1/731/ WAL-003 | Wall: Internal - 3 - CER - Station Building - Angel Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 2 x 60 amp Switch Boxes - Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within | | 2 | | | |
| 10862 | ACTIVE | N | N125-00-1/746 | SCR - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16696 | ACTIVE | N | N125-00-1/746/ CLG-01 | Ceiling: Suspended - 1 - SCR - Station Building - Angel Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 16695 | ACTIVE | N | N125-00-1/746/ CLG-01 | Ceiling: Suspended - 1 - SCR - Station Building - Angel Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 16694 | ACTIVE | N | N125-00-1/746/ DOR-01 | Door - 1 - SCR - Station Building - Angel Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Door - Supalux Trim around Glass | | | | | |
| 10863 | ACTIVE | N | N125-00-1/751 | Station Control Room - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16698 | ACTIVE | N | N125-00-1/751 | Station Control Room - Station Building - Angel Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Box - Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within | | 2 | | | |



Hazardous Material Asset Register - Summary



N125-00 - Station Building - Angel Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 16697 | ACTIVE | N | N125-00-1/751/CLG-01 | Ceiling: Suspended - 1 - Station Control Room - Station Building - Angel Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Metal Duct, Fibreglass Duct Lagging above false ceiling | | | | YES | |
| 18367 | ACTIVE | N | N125-00-1/751/FLR-01 | Floor - 1 - Station Control Room - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Wooden False Floor | | | | | YES |
| 10864 | ACTIVE | N | N125-00-1/761 | SVC - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18899 | ACTIVE | N | N125-00-1/761 | SVC - Station Building - Angel Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10865 | ACTIVE | N | N125-00-1/776 | Plant Room - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16699 | ACTIVE | N | N125-00-1/776 | Plant Room - Station Building - Angel Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10866 | ACTIVE | N | N125-00-1/777 | Plant Room - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16700 | ACTIVE | N | N125-00-1/777 | Plant Room - Station Building - Angel Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10867 | ACTIVE | N | N125-00-1/778 | Fan Room - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18368 | ACTIVE | N | N125-00-1/778 | Fan Room - Station Building - Angel Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | No Caulking Identified | | | | | |
| 10868 | ACTIVE | N | N125-00-2/151 | UMC - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16706 | ACTIVE | N | N125-00-2/151 | UMC - Station Building - Angel Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | Durasteel Panels, on incline | | | | | |
| 16707 | ACTIVE | N | N125-00-2/171 | Escalator Incline - Station Building - Angel Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10869 | ACTIVE | N | N125-00-2/236 | Lobby - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18370 | ACTIVE | N | N125-00-2/236 | Lobby - Station Building - Angel Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Board High level behind ventilation equipment - access gained by cat ladder - Non asbestos | | | | | |
| 10870 | ACTIVE | N | N125-00-2/237 | Passage - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16708 | ACTIVE | N | N125-00-2/237 | Passage - Station Building - Angel Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux on Fire Exit | | | | | |



Hazardous Material Asset Register - Summary



N125-00 - Station Building - Angel Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 10871 | ACTIVE | N | N125-00-2/240 | Lobby - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18900 | ACTIVE | N | N125-00-2/240/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Steel Duct above Supalux ceiling | | | | YES | |
| 16710 | ACTIVE | N | N125-00-2/240/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 10872 | ACTIVE | N | N125-00-2/341 | Lobby - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16713 | ACTIVE | N | N125-00-2/341/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Concrete; Steel Duct above Supalux Tiles | | | | | |
| 16712 | ACTIVE | N | N125-00-2/341/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 10873 | ACTIVE | N | N125-00-2/631 | Stairs: Spiral - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | | | | | | |
| 18407 | ACTIVE | N | N125-00-2/631 | Stairs: Spiral - Station Building - Angel Stn | No Access | Asbestos | Surveyed – Not Detected | | | | No known asbestos. Concrete slab to floor and stairs. Brickwork to walls, plastic cables, metal conduits, firestops, cable management system, new mastic, Durasteel panel - Non asbestos. Refer to report R725001 | | | | | |
| 10874 | ACTIVE | N | N125-00-2/661 | Switch Room - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16721 | ACTIVE | N | N125-00-2/661/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Angel Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 x 60amp Switch Box - Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | | |
| 25698 | ACTIVE | N | N125-00-2/661/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Angel Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 2 x 60amp, 1 x 30amp switch boxes - insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within | | 3 | | | |
| 16722 | ACTIVE | N | N125-00-2/661/WAL-004 | Wall: Internal - 4 - Switch Room - Station Building - Angel Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | | |
| 10875 | ACTIVE | N | N125-00-2/662 | Switch Room - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18373 | ACTIVE | N | N125-00-2/662 | Switch Room - Station Building - Angel Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N125-00 - Station Building - Angel Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 10876 | ACTIVE | N | N125-00-2/781 | Switch Room - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | No Access Room has Alarm (EDF) Aug 2014 | | | | | |
| 16723 | ACTIVE | N | N125-00-2/781 | Switch Room - Station Building - Angel Stn | Isolator Switches | Asbestos | Presumed | | | | Materials within 2x combination fuse switches. Presumed asbestos (R725001) | | | | | |
| 10877 | ACTIVE | N | N125-00-2/956 | Disused Room - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | | | | | | |
| 16729 | ACTIVE | N | N125-00-2/956 | Disused Room - Station Building - Angel Stn | No Access | Asbestos | Surveyed – Not Detected | | | | No known asbestos - Concrete slab to floor, ceiling, columns and beams, brickwork to walls, plastic cables, metal conduits, firestops, cable management system, new mastic, new heater units, new modern sink area, AC ductwork, AC pant units. Refer to report R725001 | | | | | |
| 10878 | ACTIVE | N | N125-00-3/071 | Circulation Area - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 46398 | ACTIVE | N | N125-00-3/071 | Circulation Area - Station Building - Angel Stn | | Asbestos | Sampled – Not Detected | | | | Plasterboard, MMMF within matrix behind cable management system metal panels to walls | | | R679620 | N | N |
| 16731 | ACTIVE | N | N125-00-3/071/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Angel Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above metal ceiling | | | R679620 | YES | |
| 10879 | ACTIVE | N | N125-00-3/072 | Circulation Area - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 46397 | ACTIVE | N | N125-00-3/072 | Circulation Area - Station Building - Angel Stn | Boarding: AIB | Asbestos | Sampled – Not Detected | | | | Insulation board throughout to the rack of vertical metal panels above 3/201 | 5 | | R679620 | N | N |
| 44105 | ACTIVE | N | N125-00-3/072/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Angel Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Mastic, 4m, to plasterboard panel/ metal frame to 3/072 Corridor to Escalators 1,2&3. | | | R604726 | N | N |
| 44104 | ACTIVE | N | N125-00-3/072/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Angel Stn | Caulking | Asbestos | Sampled – Not Detected | | | | New plasterboard panel (plus debris on floor), 1 no, to metal frame behind advertising panel to 3/072 Corridor to Escalators 1,2&3. | | | R604726 | N | N |
| 44103 | ACTIVE | N | N125-00-3/072/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Angel Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Clay cable ducts, 4 no, to concrete floor (PVC cables coming out) to 3/072 Corridor to Escalators 1,2&3. | | | R604726 | N | N |
| 44102 | ACTIVE | N | N125-00-3/072/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Angel Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Tunnel caulking, throughout, to tunnel rings at end of 3/072 Corridor to Escalators 1,2&3. | | | R604726 | N | N |
| 16732 | ACTIVE | N | N125-00-3/072/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Angel Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above metal ceiling | | | | YES | |
| 44101 | ACTIVE | N | N125-00-3/072/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Angel Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Tunnel caulking, throughout, to tunnel rings at middle of 3/072 Corridor to Escalators 1,2&3. | | | R604726 | N | N |



Hazardous Material Asset Register - Summary



N125-00 - Station Building - Angel Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 44100 | ACTIVE | N | N125-00-3/072/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Angel Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Tunnel caulking, throughout, to tunnel rings at start of 3/072 Corridor to Escalators 1,2&3. | | | R604726 | N | N |
| 10880 | ACTIVE | N | N125-00-3/151 | UMC - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18463 | ACTIVE | N | N125-00-3/151 | UMC - Station Building - Angel Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Durasteel Panels - Non Asbestos | | | | | |
| 19058 | ACTIVE | N | N125-00-3/151/CLG-01 | Ceiling: Suspended - 1 - UMC - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal, Supalux Ceiling | | | | YES | |
| 16734 | ACTIVE | N | N125-00-3/151/CLG-01 | Ceiling: Suspended - 1 - UMC - Station Building - Angel Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Ceilings - Metal, Supalux | | | | | |
| 10881 | ACTIVE | N | N125-00-3/161 | LMC - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16736 | ACTIVE | N | N125-00-3/161/CLG-01 | Ceiling: Solid - 1 - LMC - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | YES | |
| 16735 | ACTIVE | N | N125-00-3/161/FLR-02 | Floor - 2 - LMC - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Metal Floor | | | | | YES |
| 19357 | ACTIVE | N | N125-00-3/171 | Escalator Incline - Station Building - Angel Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Concrete to floor, metal tunnel rings to walls & ceiling, plastic cables, metal conduits, firestops, cable management system, new mastic, plastic and metal pipework. New escalator equipment, durasteel to incline walls both sides - Non asbestos, metal cable ducts, RSJs. Refer to Report R725001 | | | | | |
| 10882 | ACTIVE | N | N125-00-3/201 | Passage - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18441 | ACTIVE | N | N125-00-3/201/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Angel Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Rings - Cement Grout | | | | | |
| 16737 | ACTIVE | N | N125-00-3/201/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | YES | |
| 10883 | ACTIVE | N | N125-00-4/071 | Circulation Area - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 46399 | ACTIVE | N | N125-00-4/071 | Circulation Area - Station Building - Angel Stn | Boarding: AIB | Asbestos | Sampled – Not Detected | | | | Insulation board to the bacm of metal panels | 30 | | R679620 | N | N |
| 16745 | ACTIVE | N | N125-00-4/071/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Angel Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above Metal Ceiling | | | R679620 | YES | |



Hazardous Material Asset Register - Summary



N125-00 - Station Building - Angel Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 10884 | ACTIVE | N | N125-00-4/072 | Circulation Area - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 46400 | ACTIVE | N | N125-00-4/072 | Circulation Area - Station Building - Angel Stn | Boarding: AIB | Asbestos | Sampled – Not Detected | | | | Insulation board to the back of metal panels | 15 | | R679620 | N | N |
| 16746 | ACTIVE | N | N125-00-4/072/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | YES | |
| 10885 | ACTIVE | N | N125-00-4/081 | Lobby - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16747 | ACTIVE | N | N125-00-4/081/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | YES | |
| 10886 | ACTIVE | N | N125-00-4/161 | LMC - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18442 | ACTIVE | N | N125-00-4/161 | LMC - Station Building - Angel Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Concrete Caulking (Walls) | | | | | |
| 16748 | ACTIVE | N | N125-00-4/161/CLG-01 | Ceiling: Suspended - 1 - LMC - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | YES | |
| 10887 | ACTIVE | N | N125-00-4/201 | Passage - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19060 | ACTIVE | N | N125-00-4/201/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | YES | |
| 10888 | ACTIVE | N | N125-00-4/202 | Passage - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16749 | ACTIVE | N | N125-00-4/202/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | YES | |
| 10889 | ACTIVE | N | N125-00-4/203 | Passage - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16750 | ACTIVE | N | N125-00-4/203/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | YES | |
| 10890 | ACTIVE | N | N125-00-4/204 | Passage - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18443 | ACTIVE | N | N125-00-4/204/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | YES | |
| 10891 | ACTIVE | N | N125-00-4/205 | Passage - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



| N125-00 - Station Building - Angel Stn | | | | | | | | | | | | | | | | |
|--|--------|-------------|----------------------|--|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
| 16751 | ACTIVE | N | N125-00-4/205/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | YES | |
| 10892 | ACTIVE | N | N125-00-4/206 | Passage - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16752 | ACTIVE | N | N125-00-4/206/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | YES | |
| 10893 | ACTIVE | N | N125-00-4/207 | Passage - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16753 | ACTIVE | N | N125-00-4/207/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | YES | |
| 10894 | ACTIVE | N | N125-00-4/208 | Passage - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16754 | ACTIVE | N | N125-00-4/208/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | YES | |
| 10895 | ACTIVE | N | N125-00-4/236 | Service Area - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16756 | ACTIVE | N | N125-00-4/236 | Service Area - Station Building - Angel Stn | Cement Troughing | Asbestos | Known | | | | Cable Troughing - Chrysotile | | | | | |
| 18408 | ACTIVE | N | N125-00-4/236 | Service Area - Station Building - Angel Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Rings - Caulking - Non Asbestos (Walls) | | | | | |
| 16755 | ACTIVE | N | N125-00-4/236/CLG-01 | Ceiling: Solid - 1 - Service Area - Station Building - Angel Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Rings - Caulking - Non Asbestos | | | | | |
| 10896 | ACTIVE | N | N125-00-4/261 | Platform 1 - Northbound Fast - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70724 | ACTIVE | N | N125-00-4/261 | Platform 1 - Northbound Fast - Station Building - Angel Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728768 | | |
| 70722 | ACTIVE | N | N125-00-4/261 | Platform 1 - Northbound Fast - Station Building - Angel Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728768 | | |
| 16757 | ACTIVE | N | N125-00-4/261 | Platform 1 - Northbound Fast - Station Building - Angel Stn | Cement Troughing | Asbestos | Known | | | | Cable Troughing - Chrysotile No access to underside of platform during traffic hours in 2020 re-inspection. | | | | | |
| 68240 | ACTIVE | N | N125-00-4/261 | Platform 1 - Northbound Fast - Station Building - Angel Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs behind frieze panels throughout | | | R679620 | | |
| 18902 | ACTIVE | N | N125-00-4/261/CLG-01 | Ceiling: Solid - 1 - Platform 1 - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | YES | |



Hazardous Material Asset Register - Summary



N125-00 - Station Building - Angel Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18444 | ACTIVE | N | N125-00-4/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Angel Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 1 Invert 12mm Cable - Invert Main Wall No photo in report R56252. No access into platform invert during 2020 re-inspection - confined space entry required. | | 1 | R56252 | | YES |
| 10897 | ACTIVE | N | N125-00-4/262 | Platform 2 - Southbound Fast - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70718 | ACTIVE | N | N125-00-4/262 | Platform 2 - Southbound Fast - Station Building - Angel Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728768 | | |
| 70721 | ACTIVE | N | N125-00-4/262 | Platform 2 - Southbound Fast - Station Building - Angel Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | Platform Invert - Durasteel panels - total 2 no x <1m2 - To each end of invert trackside | 1 | 2 | R728768 | | |
| 68241 | ACTIVE | N | N125-00-4/262 | Platform 2 - Southbound Fast - Station Building - Angel Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs behind frieze panels throughout | | | R679620 | | |
| 70720 | ACTIVE | N | N125-00-4/262 | Platform 2 - Southbound Fast - Station Building - Angel Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728768 | | |
| 16758 | ACTIVE | N | N125-00-4/262/CLG-01 | Ceiling: Solid - 1 - Platform 2 - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | YES | |
| 16760 | ACTIVE | N | N125-00-4/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Angel Stn | Void | Asbestos | Surveyed – Not Detected | | | | New Build, All Cables PVC, J Hangers, All New Structure, Ceramic Ducts to 4/207 & 4/702 - NAD, invert to track via 4/711 & track adjacent to 4/662, J Hangers & PVC Cables - NAD | | | | | YES |
| 16759 | ACTIVE | N | N125-00-4/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Angel Stn | Durasteel | Asbestos | Strongly Presumed | | | | Headwall <0.5m Durasteel panel under nosing of platform No access to underside of platform during traffic in 2020 re-inspection | | 1 | | | |
| 10898 | ACTIVE | N | N125-00-4/406 | Store - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16761 | ACTIVE | N | N125-00-4/406 | Store - Station Building - Angel Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10899 | ACTIVE | N | N125-00-4/411 | SER - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16762 | ACTIVE | N | N125-00-4/411 | SER - Station Building - Angel Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10900 | ACTIVE | N | N125-00-4/631 | Stairs: Spiral - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16763 | ACTIVE | N | N125-00-4/631 | Stairs: Spiral - Station Building - Angel Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Durasteel Panel - Non Asbestos | | | | | |



Hazardous Material Asset Register - Summary



N125-00 - Station Building - Angel Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|------------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18445 | ACTIVE | N | N125-00-4/631/CLG-01 | Ceiling: Solid - 1 - Spiral Stairs - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | YES | |
| 10901 | ACTIVE | N | N125-00-4/632 | Lobby - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16764 | ACTIVE | N | N125-00-4/632 | Lobby - Station Building - Angel Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 44946 | ACTIVE | N | N125-00-4/632 | Lobby - Station Building - Angel Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Disused Staircase - Bottom of Shaft - Single Width Stairs Grey Gloss | | | | N | N |
| 44944 | ACTIVE | N | N125-00-4/632 | Lobby - Station Building - Angel Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Disused Staircase - Bottom of Shaft - Support steel Grey Gloss | | | | N | N |
| 44945 | ACTIVE | N | N125-00-4/632 | Lobby - Station Building - Angel Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Disused Staircase - Bottom of Shaft - Hand Rail Grey Gloss | | | | N | N |
| 10902 | ACTIVE | N | N125-00-4/661 | Switch Room - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16765 | ACTIVE | N | N125-00-4/661/CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | YES | |
| 20028 | ACTIVE | N | N125-00-4/661/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Angel Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 3 x 100amp, 2 x 200amp, 2 x 60amp Switch Boxes - Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within | | 7 | | | |
| 16766 | ACTIVE | N | N125-00-4/661/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Angel Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1 x Transformer Box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | | |
| 10903 | ACTIVE | N | N125-00-4/662 | Switch Room - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16767 | ACTIVE | N | N125-00-4/662/CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | YES | |
| 43257 | ACTIVE | N | N125-00-4/662/FLR-01 | Floor - 1 - Switch Room - Station Building - Angel Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within | | | | N | N |
| 16768 | ACTIVE | N | N125-00-4/662/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Angel Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 2 x 60 amp, 1 x 200 amp, 3 x 100 amp Switch Boxes - Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within | | 6 | | | |



Hazardous Material Asset Register - Summary



N125-00 - Station Building - Angel Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 10904 | ACTIVE | N | N125-00-4/663 | Switch Cupboard - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | No Access Need Track Side Protection Aug 2014 | | | | | |
| 18446 | ACTIVE | N | N125-00-4/663 | Switch Cupboard - Station Building - Angel Stn | No Access | Asbestos | Surveyed – Not Detected | | | | No known asbestos. New electrical equipment, boxes, plastic cables, metal conduits, firestops, cable management system, new mastic. Durasteel to door and ceiling - Non asbestos. Refer to report R725001 | | | | | |
| 10905 | ACTIVE | N | N125-00-4/711 | Relay Room - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16769 | ACTIVE | N | N125-00-4/711 | Relay Room - Station Building - Angel Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10906 | ACTIVE | N | N125-00-4/712 | Passage - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18409 | ACTIVE | N | N125-00-4/712 | Passage - Station Building - Angel Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Walls | | | | | |
| 16770 | ACTIVE | N | N125-00-4/712 | Passage - Station Building - Angel Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board on Wall | | | | | |
| 16771 | ACTIVE | N | N125-00-4/712/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Angel Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | | | | | | |
| 10907 | ACTIVE | N | N125-00-4/713 | Lobby - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44938 | ACTIVE | N | N125-00-4/713 | Lobby - Station Building - Angel Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline Packing behind metal struts | | | | N | N |
| 19061 | ACTIVE | N | N125-00-4/713 | Lobby - Station Building - Angel Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10908 | ACTIVE | N | N125-00-4/731 | CER - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18447 | ACTIVE | N | N125-00-4/731/FLR-01 | Floor - 1 - CER - Station Building - Angel Stn | Void | Asbestos | Surveyed – Not Detected | | | | PVC Cables, Metal, Trunking beneath Computer Flooring | | | | | YES |
| 16772 | ACTIVE | N | N125-00-4/731/WAL-005 | Wall: Internal - 5 - CER - Station Building - Angel Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 2 x 60 amp Switch Boxes - Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within | | 2 | | | |
| 10909 | ACTIVE | N | N125-00-4/761 | CER - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N125-00 - Station Building - Angel Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|---------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 16773 | ACTIVE | N | N125-00-4/791 | Vent Shaft - Station Building - Angel Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access | | | | | |
| 16774 | ACTIVE | N | N125-00-4/792 | Vent Shaft - Station Building - Angel Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access No keys available. Refer to report R725001 | | | | | |
| 46391 | ACTIVE | N | N125-00-4/793 | Vent Shaft - Station Building - Angel Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Caulking/bitumen throughout to concrete block joints to vent shaft walls Survey of 4/793, 4/794 & 4/795 combined. | 100 | | R683051 | N | N |
| 46393 | ACTIVE | N | N125-00-4/793 | Vent Shaft - Station Building - Angel Stn | Mastic | Asbestos | Sampled – Not Detected | | | | Mastic throughout to floor joints Survey of 4/793, 4/794 & 4/795 combined. | 100 | | R683051 | N | N |
| 46395 | ACTIVE | N | N125-00-4/793 | Vent Shaft - Station Building - Angel Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | Durasteel doors to entrance to vent shaft from staircase Survey of 4/793, 4/794 & 4/795 combined. | 4 | 2 | R683051 | N | N |
| 46390 | ACTIVE | N | N125-00-4/793 | Vent Shaft - Station Building - Angel Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | Durasteel enclosure to stairs to middle of vent Survey of 4/793, 4/794 & 4/795 combined | 100 | | R683051 | N | N |
| 46394 | ACTIVE | N | N125-00-4/793 | Vent Shaft - Station Building - Angel Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Caulking throughout to metal tunnel ring joints Survey of 4/793, 4/794 & 4/795 combined. | 100 | | R683051 | N | N |
| 46392 | ACTIVE | N | N125-00-4/793 | Vent Shaft - Station Building - Angel Stn | Mastic | Asbestos | Sampled – Not Detected | | | | Sealant around the screws to concrete blocks to vent shaft wall Survey of 4/793, 4/794 & 4/795 combined. | 1 | | R683051 | N | N |
| 16776 | ACTIVE | N | N125-00-4/794 | Vent Shaft - Station Building - Angel Stn | No Access | Asbestos | Surveyed – Not Detected | | | | No known asbestos. Metal panels to ceiling, concrete slab to floor, ceiling and walls, Concrete precast tunnel rings throughout, plastic cables, metal conduits, firestops, cable management system, new mastic, Durasteel to door 4/631 walls and stairs 600m2 non asbestos. New AC duct, terracotta ducts to either side of doors 4/631 and walls. Refer to report R725001 | | | | | |
| 19062 | ACTIVE | N | N125-00-4/795 | Vent Shaft - Station Building - Angel Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10910 | ACTIVE | N | N125-00-4/951 | Disused Room - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18448 | ACTIVE | N | N125-00-4/951 | Disused Room - Station Building - Angel Stn | Cable Duct: Other | Asbestos | Surveyed – Not Detected | | | | Cable Sleeve | | | | | |
| 64513 | ACTIVE | N | N125-00-4/951 | Disused Room - Station Building - Angel Stn | Cable Ducts: Cement | Asbestos | Sampled – Not Detected | | | | Ducts- Non Asbestos - R736276 Report | | | R736276 | | |



Hazardous Material Asset Register - Summary



| N125-00 - Station Building - Angel Stn | | | | | | | | | | | | | | | | |
|--|----------|-------------|-----------------------|--|---------------------|--------------------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
| 16777 | ACTIVE | N | N125-00-4/951 | Disused Room - Station Building - Angel Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring - Caulking Solid | | | | | |
| 16778 | ACTIVE | N | N125-00-4/951/CLG-01 | Ceiling: Solid - 1 - Disused Room - Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Tunnel Ring | | | | YES | |
| 18903 | ACTIVE | N | N125-00-4/951/CLG-01 | Ceiling: Solid - 1 - Disused Room - Station Building - Angel Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring - No Caulking Identified | | | | | |
| 10911 | ACTIVE | N | N125-00-4/952 | Disused Room - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16779 | ACTIVE | N | N125-00-4/952 | Disused Room - Station Building - Angel Stn | Cement Troughing | Asbestos | Strongly Presumed | | | | Cable Troughing - Chrysotile | | | | | |
| 10912 | ACTIVE | N | N125-00-4/953 | Relay Room - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19063 | ACTIVE | N | N125-00-4/953 | Relay Room - Station Building - Angel Stn | Westing house Boxes | Asbestos | Presumed | | | | Westinghouse Box | | 1 | | | |
| 18449 | ACTIVE | N | N125-00-4/953 | Relay Room - Station Building - Angel Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline Board | | | | | |
| 18402 | ACTIVE | N | N125-00-4/953 | Relay Room - Station Building - Angel Stn | Other Boarding | Asbestos | Presumed | | | | Asbestos Board Top Rack | | | | | |
| 16780 | ACTIVE | N | N125-00-4/953 | Relay Room - Station Building - Angel Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables | | 3 | | | |
| 42039 | INACTIVE | N | N125-00-4/953/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Angel Stn | PCBs | Polychlorinated biphenyl | Known | | | | 1 x PCB - Fair Condition | | 1 | | N | N |
| 42331 | INACTIVE | N | N125-00-4/953/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Angel Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | 3 x box style PCB's - Fair Condition 01 March 2017 inspection Fair Condition | | 3 | | N | N |
| 10913 | ACTIVE | N | N125-00-5/422 | Platform Invert - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16585 | ACTIVE | N | N125-00-5/422 | Platform Invert - Station Building - Angel Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access | | | | | |
| 10914 | ACTIVE | N | N125-00-5/771 | Pump Room - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16586 | ACTIVE | N | N125-00-5/771 | Pump Room - Station Building - Angel Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access : Note A Do not enter notice applied to this room | | | | | |
| 16587 | ACTIVE | N | N125-00-5/791 | Vent Shaft - Station Building - Angel Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access | | | | | |



Hazardous Material Asset Register - Summary



N125-00 - Station Building - Angel Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 10915 | ACTIVE | N | N125-00-A/776 | Fan Room - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16592 | ACTIVE | N | N125-00-A/776 | Fan Room - Station Building - Angel Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Rings - Inspected & No Caulking Identified | | | | | |
| 10916 | ACTIVE | N | N125-00-A/778 | Fan Room - Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16593 | ACTIVE | N | N125-00-A/778 | Fan Room - Station Building - Angel Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Rings - Inspected & No Caulking Identified | | | | | |

N127-00 - Station Building - Old Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 16550 | ACTIVE | N | N127-00-1/171 | Escalator Incline - Station Building - Old Street Stn | No Access | Asbestos | No Access: Presumed | | | | Dust 1m2 to back of advertising | | | | N | N |
| 44308 | ACTIVE | N | N127-00-1/171 | Escalator Incline - Station Building - Old Street Stn | | Asbestos | Sampled – Not Detected | | | | Corrugated sheeting >30m To back of metal panels on escalator wall running throughout | | | R612151 | N | N |
| 19355 | ACTIVE | N | N127-00-1/172/CLG-01 | Ceiling: Solid - 1 - Escalator Incline - Station Building - Old Street Stn | Caulking | Asbestos | Known | | | | Escalator 3 Incline - Caulking to tunnel ring within incline No access 2020 re-inspection no lift escalator ticket | | | | | |
| 18208 | ACTIVE | N | N127-00-1/172/WAL-001 | Wall: Internal - 1 - Escalator Incline - Station Building - Old Street Stn | Caulking | Asbestos | Known | | | | Escalator 3 Incline - Caulking to tunnel ring within incline No access 2020 re-inspection no lift escalator ticket | | | | | |
| 16551 | ACTIVE | N | N127-00-1/172/WAL-002 | Wall: Internal - 2 - Escalator Incline - Station Building - Old Street Stn | Caulking | Asbestos | Known | | | | Escalator 3 Incline - Caulking to tunnel ring within incline No access 2020 re-inspection no lift escalator ticket | | | | | |
| 10968 | ACTIVE | N | N127-00-2/001 | Booking Hall - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16552 | ACTIVE | N | N127-00-2/001 | Booking Hall - Station Building - Old Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10969 | ACTIVE | N | N127-00-2/011 | Ticket Office - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16553 | ACTIVE | N | N127-00-2/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 18209 | ACTIVE | N | N127-00-2/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Walls Breeze Block; Metal Pipe Work above Supalux Ceiling | | | | | YES |



Hazardous Material Asset Register - Summary



N127-00 - Station Building - Old Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 10970 | ACTIVE | N | N127-00-2/021 | POM - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18831 | ACTIVE | N | N127-00-2/021 | POM - Station Building - Old Street Stn | LUL Heaters | Asbestos | Known | | | | LU Heater - Insulation Board - Chrysotile | | | | | |
| 16554 | ACTIVE | N | N127-00-2/021 | POM - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panelling - High Level Back Wall; Supalux Panelling Base of Safe LHS | | | | | |
| 16555 | ACTIVE | N | N127-00-2/021/CLG-01 | Ceiling: Solid - 1 - POM - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 10971 | ACTIVE | N | N127-00-2/031 | Mess Room - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16556 | ACTIVE | N | N127-00-2/031/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Walls - Brick Work; Metal Duct Work | | | | YES | |
| 44959 | ACTIVE | N | N127-00-2/031/WAL-001 | Wall: Internal - 1 - Mess Room - Station Building - Old Street Stn | LUL Heaters | Asbestos | Presumed | | | | Heater | | | | N | N |
| 10972 | ACTIVE | N | N127-00-2/036 | Lobby - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16558 | ACTIVE | N | N127-00-2/036/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Walls Breeze Block above Supalux Tiles | | | | YES | |
| 19043 | ACTIVE | N | N127-00-2/036/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 16557 | ACTIVE | N | N127-00-2/036/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 10973 | ACTIVE | N | N127-00-2/037 | Toilet: Unisex - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18210 | ACTIVE | N | N127-00-2/037/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Walls Breeze Block above Supalux Tiles | | | | YES | |
| 10974 | ACTIVE | N | N127-00-2/047 | Kitchen - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16559 | ACTIVE | N | N127-00-2/047/CLG-01 | Ceiling: Solid - 1 - Kitchen - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 16560 | ACTIVE | N | N127-00-2/047/CLG-01 | Ceiling: Solid - 1 - Kitchen - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | PVC Cable; Concrete; Lagging Fibre glass; Conduits above False Ceiling | | | | YES | |
| 46347 | ACTIVE | N | N127-00-2/047/CLG-01 | Ceiling: Solid - 1 - Kitchen - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux panels to ceiling | | | R672526 | N | N |
| 46348 | ACTIVE | N | N127-00-2/047/FLR-01 | Floor - 1 - Kitchen - Station Building - Old Street Stn | Vinyl tiles | Asbestos | Sampled – Not Detected | | | | Lino flooring on solid concrete floor | | | R672526 | N | N |



Hazardous Material Asset Register - Summary



N127-00 - Station Building - Old Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 10975 | ACTIVE | N | N127-00-2/071 | Circulation Area - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16561 | ACTIVE | N | N127-00-2/071/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Loose Rock Wool above False Ceiling | | | | YES | |
| 10976 | ACTIVE | N | N127-00-2/081 | Lobby - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16562 | ACTIVE | N | N127-00-2/081 | Lobby - Station Building - Old Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10977 | ACTIVE | N | N127-00-2/151 | UMC - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16451 | ACTIVE | N | N127-00-2/151 | UMC - Station Building - Old Street Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Black & Cream Oil Based Paint - Girder. Thickness .23mm; Est Quantity 4lm; Analysis 14.9% | | | | | |
| 18118 | ACTIVE | N | N127-00-2/151 | UMC - Station Building - Old Street Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Grey Oil Based Paint - Girder. Thickness .44mm; Est Quantity 15lm; Analysis 18.9% | | | | | |
| 16452 | ACTIVE | N | N127-00-2/151/WAL-001 | Wall: Internal - 1 - UMC - Station Building - Old Street Stn | | Asbestos | Surveyed – Not Detected | | | | Bitumen Ducts | | | | | |
| 16449 | ACTIVE | N | N127-00-2/151/WAL-001 | Wall: Internal - 1 - UMC - Station Building - Old Street Stn | Cable Duct: Other | Asbestos | Known | | | | Ducts Above Switch Board No 2 - Chrysotile No access 2020 re-inspection no lift escalator ticket | | 8 | | | |
| 16450 | ACTIVE | N | N127-00-2/151/WAL-002 | Wall: Internal - 2 - UMC - Station Building - Old Street Stn | Cable Duct: Other | Asbestos | Known | | | | Ducts to RHS of Escalator Sprinkler System - Chrysotile No access 2020 re-inspection no lift escalator ticket | | 6 | | | |
| 10978 | ACTIVE | N | N127-00-2/152 | UMC - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16454 | ACTIVE | N | N127-00-2/152 | UMC - Station Building - Old Street Stn | Gasket :Pipework | Asbestos | Presumed | | | | Gasket to Escalator Motor No access 2020 re-inspection no lift escalator ticket | | | | | |
| 16453 | ACTIVE | N | N127-00-2/152 | UMC - Station Building - Old Street Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | Durasteel (2m2), to storage bin cover. | | 1 | | | |
| 16455 | ACTIVE | N | N127-00-2/152 | UMC - Station Building - Old Street Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Cream Gloss - Steel Column & Beam 13.03% | | | | | |
| 25709 | ACTIVE | N | N127-00-2/152 | UMC - Station Building - Old Street Stn | | Lead Paint/Lead | Sampled – Not Detected | | | | Cream Gloss Wall 0.0004% | | | | | |
| 25708 | ACTIVE | N | N127-00-2/152 | UMC - Station Building - Old Street Stn | | Lead Paint/Lead | Sampled – Not Detected | | | | Blue Gloss Wall 0.07% | | | | | |



Hazardous Material Asset Register - Summary



N127-00 - Station Building - Old Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------------|--|------------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18119 | ACTIVE | N | N127-00-2/152 | UMC - Station Building - Old Street Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Black Gloss - Steel Column 20.13% | | | | | |
| 20020 | ACTIVE | N | N127-00-2/152/ WAL-002 | Wall: Internal - 2 - UMC - Station Building - Old Street Stn | Cable Duct: Other | Asbestos | Known | | | | 10 x Ducts No access 2020 re-inspection no lift escalator ticket | | 10 | | | |
| 10979 | ACTIVE | N | N127-00-2/201 | Passage - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16456 | ACTIVE | N | N127-00-2/201/ CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Metal Ducts above False Ceiling | | | | YES | |
| 10980 | ACTIVE | N | N127-00-2/202 | Passage - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18120 | ACTIVE | N | N127-00-2/202 | Passage - Station Building - Old Street Stn | Other Electrical Boxes | Asbestos | Known | | | | AFC Lining to Electrical Box - Chrysotile | | | | | |
| 16457 | ACTIVE | N | N127-00-2/202/ CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | PVC Cables, Brick, Concrete, Trunking above False Ceiling Boarding to Bulkhead - Sampled and confirmed non asbestos report R713626 - At top of escalator/ door 2/151 | | | | YES | |
| 10981 | ACTIVE | N | N127-00-2/203 | Passage - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16458 | ACTIVE | N | N127-00-2/203/ CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Bricks; PVC Cables; Trunking above False Ceiling | | | | YES | |
| 10982 | ACTIVE | N | N127-00-2/236 | Passage - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16460 | ACTIVE | N | N127-00-2/236/ CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18121 | ACTIVE | N | N127-00-2/236/ CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Supalux Sheeting, Concrete above Supalux Tiles | | | | YES | |
| 16459 | ACTIVE | N | N127-00-2/236/ DOR-01 | Door - 1 - Passage - Station Building - Old Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Door Panels | | | | | |
| 46338 | ACTIVE | N | N127-00-2/236/ FLR-01 | Floor - 1 - Passage - Station Building - Old Street Stn | Vinyl tiles | Asbestos | Sampled – Not Detected | | | | Lino flooring on solid concrete floor | | | R672526 | N | N |
| 10983 | ACTIVE | N | N127-00-2/237 | Lobby - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N127-00 - Station Building - Old Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 16461 | ACTIVE | N | N127-00-2/237/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 16462 | ACTIVE | N | N127-00-2/237/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Walls Breeze Block; Fibre glass Lagged Pipe Work above Supalux Tiles | | | | YES | |
| 10984 | ACTIVE | N | N127-00-2/238 | Lobby - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18826 | ACTIVE | N | N127-00-2/238/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels | | | | | |
| 16464 | ACTIVE | N | N127-00-2/238/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Walls Breeze Block above Supalux Panels | | | | YES | |
| 16463 | ACTIVE | N | N127-00-2/238/FLR-01 | Floor - 1 - Lobby - Station Building - Old Street Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Lino PVC | | | | | YES |
| 10985 | ACTIVE | N | N127-00-2/281 | Locker Room - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18973 | ACTIVE | N | N127-00-2/281 | Locker Room - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 46343 | ACTIVE | N | N127-00-2/281/DORS | Doors - Locker Room - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux panels to low level of timber door | 1 | | R672526 | N | N |
| 46342 | ACTIVE | N | N127-00-2/281/FLR-01 | Floor - 1 - Locker Room - Station Building - Old Street Stn | Vinyl tiles | Asbestos | Sampled – Not Detected | | | | Lino flooring on solid concrete floor | | | R672526 | N | N |
| 10986 | ACTIVE | N | N127-00-2/291 | Station Supervisor Office - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18122 | ACTIVE | N | N127-00-2/291/CLG-01 | Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | PVC Cable; Concrete; Lagging Fibre glass; Conduits above False Ceiling | | | | YES | |
| 46341 | ACTIVE | N | N127-00-2/291/CLG-01 | Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux panels to ceiling | | | R672526 | N | N |
| 18397 | ACTIVE | N | N127-00-2/291/CLG-01 | Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 46340 | ACTIVE | N | N127-00-2/291/FLR-01 | Floor - 1 - Station Supervisor Office - Station Building - Old Street Stn | Vinyl tiles | Asbestos | Sampled – Not Detected | | | | Lino flooring on solid concrete floor | | | R672526 | N | N |
| 16465 | ACTIVE | N | N127-00-2/291/WAL-001 | Wall: Internal - 1 - Station Supervisor Office - Station Building - Old Street Stn | LUL Heaters | Asbestos | Sampled – Not Detected | | | | Heater - Lining within LTB heater was sampled and no asbestos was detected. Refer to 4-Rail ID report R691926 | | | | | |
| 10987 | ACTIVE | N | N127-00-2/311 | Office - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N127-00 - Station Building - Old Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 16468 | ACTIVE | N | N127-00-2/311 | Office - Station Building - Old Street Stn | LUL Heaters | Asbestos | Strongly Presumed | | | | LU Heater - Insulation Board | | | | | |
| 16467 | ACTIVE | N | N127-00-2/311/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Walls Breeze Block; Fibre glass Lagged Pipe Work above False Ceiling | | | | YES | |
| 16466 | ACTIVE | N | N127-00-2/311/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 10988 | ACTIVE | N | N127-00-2/331 | Mess Room - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18974 | ACTIVE | N | N127-00-2/331/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels | | | | | |
| 46345 | ACTIVE | N | N127-00-2/331/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux panels to ceiling | | | R672526 | N | N |
| 18123 | ACTIVE | N | N127-00-2/331/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Fibre glass Lagged Pipe Work above False Ceiling | | | | YES | |
| 46346 | ACTIVE | N | N127-00-2/331/DOR-01 | Door: Cubicle - 1 - Mess Room - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux panels to low level of timber door | 1 | | R672526 | N | N |
| 46344 | ACTIVE | N | N127-00-2/331/FLR-01 | Floor - 1 - Mess Room - Station Building - Old Street Stn | Vinyl tiles | Asbestos | Sampled – Not Detected | | | | Lino flooring on solid concrete floor | | | R672526 | N | N |
| 16469 | ACTIVE | N | N127-00-2/331/WAL-003 | Wall: Internal - 3 - Mess Room - Station Building - Old Street Stn | LUL Heaters | Asbestos | Strongly Presumed | | | | Heater | | | | | |
| 10989 | ACTIVE | N | N127-00-2/396 | SVC - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16470 | ACTIVE | N | N127-00-2/396 | SVC - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels | | | | | |
| 10990 | ACTIVE | N | N127-00-2/397 | SVC - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18124 | ACTIVE | N | N127-00-2/397/DOR-01 | Door - 1 - SVC - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel above Door | | | | | |
| 10991 | ACTIVE | N | N127-00-2/411 | Store - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16471 | ACTIVE | N | N127-00-2/411 | Store - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel - back Ceiling | | | | | |
| 10992 | ACTIVE | N | N127-00-2/412 | Store - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N127-00 - Station Building - Old Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 16472 | ACTIVE | N | N127-00-2/412 | Store - Station Building - Old Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 10993 | ACTIVE | N | N127-00-2/416 | Toilet: Male - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16473 | ACTIVE | N | N127-00-2/416/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 16474 | ACTIVE | N | N127-00-2/416/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Fibre glass Lagged Pipe Work above False Ceiling | | | | YES | |
| 10994 | ACTIVE | N | N127-00-2/417 | Lobby - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18125 | ACTIVE | N | N127-00-2/417/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 16475 | ACTIVE | N | N127-00-2/417/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Fibre glass Lagged Pipe Work above False Ceiling | | | | YES | |
| 16476 | ACTIVE | N | N127-00-2/417/CLG-02 | Ceiling: Suspended - 2 - Lobby - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 16477 | ACTIVE | N | N127-00-2/417/CLG-02 | Ceiling: Suspended - 2 - Lobby - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Fibre glass Lagged Pipe Work above False Ceiling | | | | YES | |
| 10995 | ACTIVE | N | N127-00-2/418 | Toilet: Female - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18126 | ACTIVE | N | N127-00-2/418/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Fibre glass Lagged Pipe Work above False Ceiling | | | | YES | |
| 16478 | ACTIVE | N | N127-00-2/418/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 10996 | ACTIVE | N | N127-00-2/455 | Tenancy - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | No Access Tenant in place Aug 2014 | | | | | |
| 16479 | ACTIVE | N | N127-00-2/455 | Tenancy - Station Building - Old Street Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access | | | | | |
| 10997 | ACTIVE | N | N127-00-2/601 | Stairs: Linear - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18827 | ACTIVE | N | N127-00-2/601/CLG-01 | Ceiling: Solid - 1 - Spiral Stairs - Station Building - Old Street Stn | No Access | Asbestos | Surveyed – Not Detected | | | | This location was surveyed on behalf of Morgan Sindall. Please refer to report R655702 | | | | | |
| 10998 | ACTIVE | N | N127-00-2/602 | Stairs: Linear - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |



Hazardous Material Asset Register - Summary



N127-00 - Station Building - Old Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 46461 | ACTIVE | N | N127-00-2/602 | Stairs: Linear - Station Building - Old Street Stn | | Asbestos | No Access: Presumed | | | | No access under metal nosing plate on steps | | | | | |
| 18975 | ACTIVE | N | N127-00-2/602/CLG-01 | Ceiling: Solid - 1 - Spiral Stairs - Station Building - Old Street Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Surveyed on behalf of Morgan Sindall. Refer to 4-Rail report R655702Rev1. | | | | | |
| 10999 | ACTIVE | N | N127-00-2/631 | Stairs: Spiral - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16481 | ACTIVE | N | N127-00-2/631 | Stairs: Spiral - Station Building - Old Street Stn | Caulking | Asbestos | Known | | | | Asbestos caulking in tunnel ring joints and flanges has been identified at the station. Therefore, all ring joints must be suspected of containing asbestos. Rings forming staircase structure are sealed. | | | | | |
| 16480 | ACTIVE | N | N127-00-2/631 | Stairs: Spiral - Station Building - Old Street Stn | Cable Duct: Other | Asbestos | Strongly Presumed | | | | Ducts | | 10 | | | |
| 11000 | ACTIVE | N | N127-00-2/661 | Switch Room - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16483 | ACTIVE | N | N127-00-2/661 | Switch Room - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing - High Level | | | | | |
| 18127 | ACTIVE | N | N127-00-2/661 | Switch Room - Station Building - Old Street Stn | Gasket :Pipework | Asbestos | Strongly Presumed | | | | Gasket missing - presume 1x combination fuse switch box to wall - photo DSC05624 | | | | | |
| 16482 | ACTIVE | N | N127-00-2/661/FLR-01 | Floor - 1 - Switch Room - Station Building - Old Street Stn | Vinyl tiles | Asbestos | Known | | | | Grey Marley Tiles - Chrysotile | | | | | |
| 44960 | ACTIVE | N | N127-00-2/661/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Old Street Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | 1 x 60amp Switch Box - Insulation within | | 1 | | N | N |
| 11001 | ACTIVE | N | N127-00-2/662 | Switch Room - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18976 | ACTIVE | N | N127-00-2/662 | Switch Room - Station Building - Old Street Stn | Other Electrical Boxes | Asbestos | Presumed | | | | EDF in Take Feed - Asbestos components within | | 1 | | | |
| 42160 | ACTIVE | N | N127-00-2/662/FLR-01 | Floor - 1 - Switch Room - Station Building - Old Street Stn | Cable Ducts: Cement | Asbestos | Known | | | | Cement Cable Ducts - by wall 3 - 2no | | 2 | R713626 | | |
| 25705 | ACTIVE | N | N127-00-2/662/FLR-01 | Floor - 1 - Switch Room - Station Building - Old Street Stn | Void | Asbestos | Presumed | | | | No access to Floor Hatches | | 2 | | | |
| 16485 | ACTIVE | N | N127-00-2/662/FLR-01 | Floor - 1 - Switch Room - Station Building - Old Street Stn | Vinyl tiles | Asbestos | Known | | | | Red & Grey Marley Vinyl Tiles 21/11/2022 - 32no Loose floor tiles were removed by Econ for Morgan Sindall / Old St Roundabout Project - Bitumen underneath these tiles was left in-situ. | 6 | | | | |



Hazardous Material Asset Register - Summary



N127-00 - Station Building - Old Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 16486 | ACTIVE | N | N127-00-2/662/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Old Street Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Box 1 x 30 amp - Asbestos Insulation within | | 1 | | | |
| 18191 | ACTIVE | N | N127-00-2/662/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Old Street Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 3 x Transformer Boxes | | 3 | | | |
| 11002 | ACTIVE | N | N127-00-2/666 | Switch Room - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18398 | ACTIVE | N | N127-00-2/666 | Switch Room - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Walls Supalux Panels | | | | | |
| 16489 | ACTIVE | N | N127-00-2/666/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel, Concrete, Brick; PVC Cable above False Ceiling | | | | YES | |
| 16487 | ACTIVE | N | N127-00-2/666/FLR-01 | Floor - 1 - Switch Room - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 16488 | ACTIVE | N | N127-00-2/666/FLR-01 | Floor - 1 - Switch Room - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete beneath Supalux Floor | | | | | YES |
| 18192 | ACTIVE | N | N127-00-2/666/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Old Street Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 x 30amp Switch Box - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 25706 | ACTIVE | N | N127-00-2/666/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Old Street Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Boxes x 3 No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 3 | | | |
| 25704 | ACTIVE | N | N127-00-2/666/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Old Street Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 x 60amp Switch Box No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 25707 | ACTIVE | N | N127-00-2/666/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Old Street Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 9 x 60amp, 1 x 200amp Switch Boxes No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 10 | | | |
| 11003 | ACTIVE | N | N127-00-2/746 | SCR - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16490 | ACTIVE | N | N127-00-2/746 | SCR - Station Building - Old Street Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No access | | | | | |



Hazardous Material Asset Register - Summary



N127-00 - Station Building - Old Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 11004 | ACTIVE | N | N127-00-2/776 | Plant Room - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 25714 | ACTIVE | N | N127-00-2/776 | Plant Room - Station Building - Old Street Stn | Mastic | Asbestos | Surveyed – Not Detected | | | | Gaskets to vent systems - possible mastic between flanges Report R713626 (23/06/2022) - states New Mastic & Gaiters. | | | | | |
| 16491 | ACTIVE | N | N127-00-2/776/WAL-001 | Wall: Internal - 1 - Plant Room - Station Building - Old Street Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 x 100amp Switch Box - Insulation within | | 1 | | | |
| 18977 | ACTIVE | N | N127-00-2/777/CLG-01 | Ceiling: Suspended - 1 - Vent Shaft - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; PVC Cable; Conduit above False Ceiling | | | | YES | |
| 16492 | ACTIVE | N | N127-00-2/777/CLG-01 | Ceiling: Suspended - 1 - Vent Shaft - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 16493 | ACTIVE | N | N127-00-2/791 | Vent Shaft - Station Building - Old Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 18193 | ACTIVE | N | N127-00-2/792 | Vent Shaft - Station Building - Old Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11005 | ACTIVE | N | N127-00-2/951 | Store - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19961 | ACTIVE | N | N127-00-2/951/WAL-003 | Wall: Internal - 3 - Store - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 11006 | ACTIVE | N | N127-00-2/952 | Disused Room - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16494 | ACTIVE | N | N127-00-2/952 | Disused Room - Station Building - Old Street Stn | | Asbestos | Surveyed – Not Detected | | | | Bitumen Ducts | | | | | |
| 11007 | ACTIVE | N | N127-00-3/207 | Passage - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16495 | ACTIVE | N | N127-00-3/207 | Passage - Station Building - Old Street Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Network Rail Area | | | | | |
| 11008 | ACTIVE | N | N127-00-3/208 | Passage - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16496 | ACTIVE | N | N127-00-3/208 | Passage - Station Building - Old Street Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Network Rail Area | | | | | |
| 11009 | ACTIVE | N | N127-00-3/209 | Passage - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N127-00 - Station Building - Old Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|----------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 16497 | ACTIVE | N | N127-00-3/209 | Passage - Station Building - Old Street Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Network Rail Area | | | | | |
| 11010 | ACTIVE | N | N127-00-3/281 | Office - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16498 | ACTIVE | N | N127-00-3/281 | Office - Station Building - Old Street Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Network Rail Area | | | | | |
| 11011 | ACTIVE | N | N127-00-3/605 | Stairs: Linear - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16499 | ACTIVE | N | N127-00-3/605 | Stairs: Linear - Station Building - Old Street Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Network Rail Area | | | | | |
| 11012 | ACTIVE | N | N127-00-3/606 | Stairs: Linear - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18194 | ACTIVE | N | N127-00-3/606 | Stairs: Linear - Station Building - Old Street Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Network Rail Area | | | | | |
| 11013 | ACTIVE | N | N127-00-3/661 | Switch Cupboard - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16500 | ACTIVE | N | N127-00-3/661 | Switch Cupboard - Station Building - Old Street Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Network Rail Area | | | | | |
| 11014 | ACTIVE | N | N127-00-3/662 | Switch Room - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16501 | ACTIVE | N | N127-00-3/662 | Switch Room - Station Building - Old Street Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Network Rail Area | | | | | |
| 11015 | ACTIVE | N | N127-00-3/663 | Switch Room - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20021 | ACTIVE | N | N127-00-3/663 | Switch Room - Station Building - Old Street Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Network Rail Area | | | | | |
| 11016 | ACTIVE | N | N127-00-3/711 | Relay Room - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16502 | ACTIVE | N | N127-00-3/711 | Relay Room - Station Building - Old Street Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Network Rail Area | | | | | |
| 11017 | ACTIVE | N | N127-00-3/712 | Relay Room - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18195 | ACTIVE | N | N127-00-3/712 | Relay Room - Station Building - Old Street Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Network Rail Area | | | | | |



Hazardous Material Asset Register - Summary



N127-00 - Station Building - Old Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|---------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 11018 | ACTIVE | N | N127-00-4/081 | Circulation Area - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16504 | ACTIVE | N | N127-00-4/081 | Circulation Area - Station Building - Old Street Stn | Caulking | Asbestos | Strongly Presumed | | | | Asbestos caulking in tunnel ring joints and flanges has been identified at the station. Therefore, all ring joints must be suspected of containing asbestos. Rings forming staircase structure are sealed. | | | | | |
| 16503 | ACTIVE | N | N127-00-4/081/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Old Street Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Panels | | | | YES | |
| 11019 | ACTIVE | N | N127-00-4/161 | LMC - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18196 | ACTIVE | N | N127-00-4/161/CLG-01 | Ceiling: Suspended - 1 - LMC - Station Building - Old Street Stn | Caulking | Asbestos | Known | | | | Tunnel Ring Caulking - Chrysotile & Amphibole No access 2020 re-inspection no lift escalator ticket | | | | | |
| 16505 | ACTIVE | N | N127-00-4/161/CLG-01 | Ceiling: Suspended - 1 - LMC - Station Building - Old Street Stn | Cellactite Sheeting | Asbestos | Known | | | | Ceiling above escalator 1 & 2 incline and rooms - Cellactite No access 2020 re-inspection no lift escalator ticket | | | | | |
| 11020 | ACTIVE | N | N127-00-4/162 | LMC - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44961 | ACTIVE | N | N127-00-4/162 | LMC - Station Building - Old Street Stn | Cellactite Sheeting | Asbestos | Known | | | | Bitumen corrugated sheet to wall in front of door and ceiling | | | | N | N |
| 44962 | ACTIVE | N | N127-00-4/162 | LMC - Station Building - Old Street Stn | Mastic | Asbestos | Known | | | | Putty to Joint | | | | N | N |
| 25760 | ACTIVE | N | N127-00-4/162 | LMC - Station Building - Old Street Stn | Cellactite Sheeting | Asbestos | Known | | | | Cellactite sheet No access 2020 re-inspection no lift escalator ticket | | | | | |
| 25711 | ACTIVE | N | N127-00-4/162 | LMC - Station Building - Old Street Stn | Lead/Leading | Lead Paint/Lead | Strongly Presumed | | | | Cream gloss steel column and beam presumed to be 13.03% | | | | | |
| 25710 | ACTIVE | N | N127-00-4/162 | LMC - Station Building - Old Street Stn | Lead/Leading | Lead Paint/Lead | Strongly Presumed | | | | Black gloss steel column lead content presumed to be 20.13% | | | | | |
| 18197 | ACTIVE | N | N127-00-4/162/CLG-01 | Ceiling: Solid - 1 - LMC - Station Building - Old Street Stn | Caulking | Asbestos | Known | | | | Caulking behind Cellactite No access 2020 re-inspection no lift escalator ticket | | | | | |
| 16509 | ACTIVE | N | N127-00-4/162/CLG-01 | Ceiling: Solid - 1 - LMC - Station Building - Old Street Stn | Cellactite Sheeting | Asbestos | Known | | | | Ceiling above escalator 1 & 2 incline and rooms - Cellactite No access 2020 re-inspection no lift escalator ticket | | | | | |
| 18978 | ACTIVE | N | N127-00-4/162/WAL-001 | Wall: Internal - 1 - LMC - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels | | | | | |



Hazardous Material Asset Register - Summary



N127-00 - Station Building - Old Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 16506 | ACTIVE | N | N127-00-4/162/WAL-001 | Wall: Internal - 1 - LMC - Station Building - Old Street Stn | Cable Duct: Other | Asbestos | Known | | | | 6 x Cable Ducts to Walls 1&2 No access 2020 re-inspection no lift escalator ticket | | 6 | | | |
| 16508 | ACTIVE | N | N127-00-4/162/WAL-002 | Wall: Internal - 2 - LMC - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels to ceiling at corner of walls 2 & 3 | | | | | |
| 16507 | ACTIVE | N | N127-00-4/162/WAL-002 | Wall: Internal - 2 - LMC - Station Building - Old Street Stn | Cable Duct: Other | Asbestos | Known | | | | Cable Ducts to Walls 1&2 No access 2020 re-inspection no lift escalator ticket | | 6 | | | |
| 11021 | ACTIVE | N | N127-00-4/201 | Passage - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16510 | ACTIVE | N | N127-00-4/201/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Tiles above false ceiling | | | | YES | |
| 11022 | ACTIVE | N | N127-00-4/202 | Passage - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16511 | ACTIVE | N | N127-00-4/202 | Passage - Station Building - Old Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11023 | ACTIVE | N | N127-00-4/203 | Passage - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16512 | ACTIVE | N | N127-00-4/203 | Passage - Station Building - Old Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11024 | ACTIVE | N | N127-00-4/204 | Passage - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16513 | ACTIVE | N | N127-00-4/204 | Passage - Station Building - Old Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 44292 | ACTIVE | N | N127-00-4/204 | Passage - Station Building - Old Street Stn | | Asbestos | Sampled – Not Detected | | | | Supalux panel, 1m, to ceiling in Passage 4/204 at Old Street Station | | | R610526 | N | N |
| 11025 | ACTIVE | N | N127-00-4/205 | Passage - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16514 | ACTIVE | N | N127-00-4/205 | Passage - Station Building - Old Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11026 | ACTIVE | N | N127-00-4/206 | Passage - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18198 | ACTIVE | N | N127-00-4/206 | Passage - Station Building - Old Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11027 | ACTIVE | N | N127-00-4/207 | Passage - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N127-00 - Station Building - Old Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|---------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 16515 | ACTIVE | N | N127-00-4/207/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Melamine Panels - Non Asbestos | | | | | |
| 18828 | ACTIVE | N | N127-00-4/207/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn | Caulking | Asbestos | Strongly Presumed | | | | By 4/209 Caulking in tunnel in joints (not visible) behind metal and cellactite sheeting - SP - above False Ceiling | | | | | |
| 11028 | ACTIVE | N | N127-00-4/208 | Passage - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18979 | ACTIVE | N | N127-00-4/208/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn | Cellactite Sheeting | Asbestos | Strongly Presumed | | | | Cellactite sheeting above False Ceiling | | | | | |
| 16516 | ACTIVE | N | N127-00-4/208/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Melamine Panels - Non Asbestos | | | | | |
| 16517 | ACTIVE | N | N127-00-4/208/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn | Caulking | Asbestos | Strongly Presumed | | | | Caulking within tunnel ring joints not visible behind -SP. Concrete by 4/211 - above False Ceiling | | | | YES | |
| 11029 | ACTIVE | N | N127-00-4/209 | Passage - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18199 | ACTIVE | N | N127-00-4/209/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Melamine Panels - Non Asbestos | | | | | |
| 16609 | ACTIVE | N | N127-00-4/209/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn | Caulking | Asbestos | Strongly Presumed | | | | Caulking within tunnel ring joints not visible behind - SP - above False Ceiling | | | | | |
| 16608 | ACTIVE | N | N127-00-4/209/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn | Cellactite Sheeting | Asbestos | Strongly Presumed | | | | Cellactite sheeting above False Ceiling | | | | | |
| 11030 | ACTIVE | N | N127-00-4/210 | Passage - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16611 | ACTIVE | N | N127-00-4/210 | Passage - Station Building - Old Street Stn | Caulking | Asbestos | Strongly Presumed | | | | Behind metal arch panels Bottom of escalator 3 metal corrugated sheeting – caulking within tunnel rings not visible but suspected behind rock wool lagging - SP | | | | | |
| 18284 | ACTIVE | N | N127-00-4/210/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Melamine Panels - Non Asbestos | | | | | |
| 16610 | ACTIVE | N | N127-00-4/210/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn | Cellactite Sheeting | Asbestos | Strongly Presumed | | | | Cellactite Panels above False Ceiling | | | | YES | |
| 11031 | ACTIVE | N | N127-00-4/211 | Passage - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16612 | ACTIVE | N | N127-00-4/211/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn | Cellactite Sheeting | Asbestos | Strongly Presumed | | | | Cellactite Panels above Metal Ceiling | | | | YES | |
| 11032 | ACTIVE | N | N127-00-4/236 | Passage - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N127-00 - Station Building - Old Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 16613 | ACTIVE | N | N127-00-4/236 | Passage - Station Building - Old Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11033 | ACTIVE | N | N127-00-4/237 | Lobby - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16614 | ACTIVE | N | N127-00-4/237 | Lobby - Station Building - Old Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11034 | ACTIVE | N | N127-00-4/601 | Stairs: Linear - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19962 | ACTIVE | N | N127-00-4/601 | Stairs: Linear - Station Building - Old Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11035 | ACTIVE | N | N127-00-4/602 | Stairs: Spiral - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16615 | ACTIVE | N | N127-00-4/602/CLG-01 | Ceiling: Solid - 1 - Spiral Stairs - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above Metal Ceiling - Corrugated Metal; PVC Cables; Cable Tray; Rock Wool; Fire break, Solid Concrete behind | | | | YES | |
| 18285 | ACTIVE | N | N127-00-4/602/CLG-01 | Ceiling: Solid - 1 - Spiral Stairs - Station Building - Old Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Melamine Panels | | | | | |
| 11036 | ACTIVE | N | N127-00-4/603 | Stairs: Linear - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18404 | ACTIVE | N | N127-00-4/603/CLG-01 | Ceiling: Solid - 1 - Spiral Stairs - Station Building - Old Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Melamine Panels | | | | | |
| 16616 | ACTIVE | N | N127-00-4/603/CLG-01 | Ceiling: Solid - 1 - Spiral Stairs - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above False Ceiling - Corrugated Metal; PVC Cables; Cable Tray; Rock Wool; Fire break, Solid concrete behind | | | | YES | |
| 11037 | ACTIVE | N | N127-00-4/604 | Stairs: Linear - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16617 | ACTIVE | N | N127-00-4/604/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Old Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Melamine Panels | | | | | |
| 16618 | ACTIVE | N | N127-00-4/604/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above False Ceiling - Corrugated Metal; PVC Cables; Cable Tray; Rock Wool; Fire break, Solid Concrete behind | | | | YES | |
| 11038 | ACTIVE | N | N127-00-4/731 | CER - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18286 | ACTIVE | N | N127-00-4/731 | CER - Station Building - Old Street Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No access | | | | | |



Hazardous Material Asset Register - Summary



N127-00 - Station Building - Old Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 11039 | ACTIVE | N | N127-00-4/732 | CER - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19047 | ACTIVE | N | N127-00-4/732 | CER - Station Building - Old Street Stn | Other Boarding | Asbestos | Presumed | | | | Distribution Board - Paxoline Backing Board - P | | | | | |
| 16619 | ACTIVE | N | N127-00-4/732/FLR-01 | Floor - 1 - CER - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Beneath Computer Flooring Concrete slab to floor within floor void. New Lino on metal/ wood raised computer tiles to raised floor. Plastic cables, metal conduits, cable management system and firestop and mastic - new throughout. MMMF insulation and debris loose fill within floor void. new electrical boxes throughout. non asbestos containing materials. general rubbish within floor void. | | | | | YES |
| 16484 | ACTIVE | N | N127-00-4/732/WAL-004 | Wall: Internal - 4 - CER - Station Building - Old Street Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 2no x 60amp Switch Boxes- SP - Asbestos Components within | | 2 | | | |
| 11040 | ACTIVE | N | N127-00-4/761 | Computer Equipment Cupboard - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16621 | ACTIVE | N | N127-00-4/761 | Computer Equipment Cupboard - Station Building - Old Street Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11041 | ACTIVE | N | N127-00-4/762 | Computer Equipment Cupboard - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18287 | ACTIVE | N | N127-00-4/762 | Computer Equipment Cupboard - Station Building - Old Street Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11042 | ACTIVE | N | N127-00-4/763 | Computer Equipment Cupboard - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16622 | ACTIVE | N | N127-00-4/763 | Computer Equipment Cupboard - Station Building - Old Street Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11043 | ACTIVE | N | N127-00-4/764 | Computer Equipment Cupboard - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16623 | ACTIVE | N | N127-00-4/764 | Computer Equipment Cupboard - Station Building - Old Street Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11044 | ACTIVE | N | N127-00-4/765 | Computer Equipment Cupboard - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N127-00 - Station Building - Old Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 16624 | ACTIVE | N | N127-00-4/765 | Computer Equipment Cupboard - Station Building - Old Street Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11045 | ACTIVE | N | N127-00-4/766 | Computer Equipment Cupboard - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18288 | ACTIVE | N | N127-00-4/766 | Computer Equipment Cupboard - Station Building - Old Street Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11046 | ACTIVE | N | N127-00-4/791 | Passage - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16625 | ACTIVE | N | N127-00-4/792 | Vent Shaft - Station Building - Old Street Stn | Caulking | Asbestos | Strongly Presumed | | | | Asbestos caulking in tunnel ring joints and flanges has been identified at the station. Therefore, all ring joints must be suspected of containing asbestos. Rings are sealed. | | | | | |
| 18834 | ACTIVE | N | N127-00-4/792 | Vent Shaft - Station Building - Old Street Stn | Gasket :Pipework | Asbestos | Strongly Presumed | | | | Gaskets & Rope - Vent System & Extractor Fan Motor | | | | | |
| 16620 | ACTIVE | N | N127-00-4/792 | Vent Shaft - Station Building - Old Street Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 2 | | | |
| 11047 | ACTIVE | N | N127-00-4/793 | Switch Cupboard - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16626 | ACTIVE | N | N127-00-4/793 | Switch Cupboard - Station Building - Old Street Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access | | | | | |
| 11048 | ACTIVE | N | N127-00-4/794 | SER - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19048 | ACTIVE | N | N127-00-4/794 | SER - Station Building - Old Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard Panel (Walls) | | | | | |
| 16628 | ACTIVE | N | N127-00-4/794 | SER - Station Building - Old Street Stn | Caulking | Asbestos | Strongly Presumed | | | | Asbestos caulking in tunnel ring joints and flanges has been identified at the station. Therefore, all ring joints must be suspected of containing asbestos. Rings are sealed. 2 samples were taken and found not to contain asbestos. Refer to Report R333201. | | | | | |
| 16627 | ACTIVE | N | N127-00-4/794/CLG-01 | Ceiling: Solid - 1 - SER - Station Building - Old Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard Panel | | | | | |
| 18289 | ACTIVE | N | N127-00-4/794/CLG-01 | Ceiling: Solid - 1 - SER - Station Building - Old Street Stn | Other Boarding | Asbestos | No Access: Presumed | | | | Above Plasterboard Panel | | | | | |



Hazardous Material Asset Register - Summary



| N127-00 - Station Building - Old Street Stn | | | | | | | | | | | | | | | | |
|---|--------|-------------|----------------------|--|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
| 11049 | ACTIVE | N | N127-00-5/201 | Passage - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16629 | ACTIVE | N | N127-00-5/201 | Passage - Station Building - Old Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11050 | ACTIVE | N | N127-00-5/202 | Passage - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18290 | ACTIVE | N | N127-00-5/202/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Rock Wool above Tiled Ceiling | | | | YES | |
| 11051 | ACTIVE | N | N127-00-5/203 | Passage - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16630 | ACTIVE | N | N127-00-5/203/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | New Corrugated Metal, Concrete; PVC Cables above Tiled Ceiling | | | | YES | |
| 11052 | ACTIVE | N | N127-00-5/204 | Passage - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16631 | ACTIVE | N | N127-00-5/204/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access to high Aug 2014 | | | | | |
| 11053 | ACTIVE | N | N127-00-5/205 | Passage - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16632 | ACTIVE | N | N127-00-5/205/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above False Ceiling - Metal Corrugated Sheets and Rock Wool Lagging, Plastic Cables. Solid Concrete behind | | | | YES | |
| 11054 | ACTIVE | N | N127-00-5/206 | Passage - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16633 | ACTIVE | N | N127-00-5/206/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Old Street Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above Melamine Panels - Metal Corrugated Sheets and Rock Wool Lagging, Plastic Cables. Solid Concrete behind | | | | YES | |
| 11055 | ACTIVE | N | N127-00-5/261 | Platform 1 - Northbound Fast - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70700 | ACTIVE | N | N127-00-5/261 | Platform 1 - Northbound Fast - Station Building - Old Street Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 no - To trackside wall | | 2 | R728767 | N | Y |
| 70707 | ACTIVE | N | N127-00-5/261 | Platform 1 - Northbound Fast - Station Building - Old Street Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 6 no - To platform wall | | 6 | R728767 | N | Y |
| 70699 | ACTIVE | N | N127-00-5/261 | Platform 1 - Northbound Fast - Station Building - Old Street Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/wood/lead - To tunnel rings throughout | | | R728767 | | |



Hazardous Material Asset Register - Summary



N127-00 - Station Building - Old Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 70702 | ACTIVE | N | N127-00-5/261 | Platform 1 - Northbound Fast - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Platform Invert - Supalux panels/ shuttering - To platform wall/ ceiling throughout | | | R728767 | N | Y |
| 70703 | ACTIVE | N | N127-00-5/261 | Platform 1 - Northbound Fast - Station Building - Old Street Stn | Cable Sheath | Asbestos | Known | | | | Platform invert - Braided cables - total 5 no - To trackside wall and J hangers throughout | | 5 | R728767 | | |
| 70704 | ACTIVE | N | N127-00-5/261 | Platform 1 - Northbound Fast - Station Building - Old Street Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 6 no - To platform wall | | 6 | R728767 | N | Y |
| 70701 | ACTIVE | N | N127-00-5/261 | Platform 1 - Northbound Fast - Station Building - Old Street Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable duct - total 1 no - To trackside wall | | 1 | R728767 | N | Y |
| 70698 | ACTIVE | N | N127-00-5/261 | Platform 1 - Northbound Fast - Station Building - Old Street Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728767 | | |
| 16634 | ACTIVE | N | N127-00-5/261/ CLG-01 | Ceiling: Solid - 1 - Platform 1 - Station Building - Old Street Stn | Caulking | Asbestos | Strongly Presumed | | | | Caulking within tunnel rings strongly presumed to be present but not visible | | | | | |
| 18291 | ACTIVE | N | N127-00-5/261/ CLG-01 | Ceiling: Solid - 1 - Platform 1 - Station Building - Old Street Stn | Cellactite Sheeting | Asbestos | Strongly Presumed | | | | Additional inspection behind large corrugated metal covers over platform and track Cellactite sheeting | | | | | |
| 16635 | ACTIVE | N | N127-00-5/261/ FLR-01 | Floor - 1 - Platform 1 - Station Building - Old Street Stn | | Asbestos | Surveyed – Not Detected | | | | Platform 1 Invert - New Bitumen Ducts. | | | | | YES |
| 16638 | ACTIVE | N | N127-00-5/261/ FLR-01 | Floor - 1 - Platform 1 - Station Building - Old Street Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 1 Invert - Woven cable insulation (sheath?) on J Hanger 2 No Access 2020 Re-inspection - confined space team required | | | | | YES |
| 16637 | ACTIVE | N | N127-00-5/261/ FLR-01 | Floor - 1 - Platform 1 - Station Building - Old Street Stn | Cable: Wrap | Asbestos | Strongly Presumed | | | | Platform 1 Invert - Woven cable wrapping at both ends of Invert No Access 2020 Re-inspection - confined space team required | | | | | YES |
| 16636 | ACTIVE | N | N127-00-5/261/ FLR-01 | Floor - 1 - Platform 1 - Station Building - Old Street Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 1 Invert - 4 x Cables 2x10mm / 2x8mm / length of invert on JH3 No Access 2020 Re-inspection- confined space team required | | | | | YES |
| 11056 | ACTIVE | N | N127-00-5/262 | Platform 2 - Southbound Fast - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70714 | ACTIVE | N | N127-00-5/262 | Platform 2 - Southbound Fast - Station Building - Old Street Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total2 no - To trackside wall | | 2 | R728767 | N | Y |
| 70711 | ACTIVE | N | N127-00-5/262 | Platform 2 - Southbound Fast - Station Building - Old Street Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 no - To trackside wall | | 2 | R728767 | N | Y |
| 70713 | ACTIVE | N | N127-00-5/262 | Platform 2 - Southbound Fast - Station Building - Old Street Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 6 no - To platform side wall | | 6 | R728767 | N | Y |
| 70708 | ACTIVE | N | N127-00-5/262 | Platform 2 - Southbound Fast - Station Building - Old Street Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728767 | | |



Hazardous Material Asset Register - Summary



N127-00 - Station Building - Old Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 70710 | ACTIVE | N | N127-00-5/262 | Platform 2 - Southbound Fast - Station Building - Old Street Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 8 no - To trackside wall | | 8 | R728767 | N | Y |
| 70709 | ACTIVE | N | N127-00-5/262 | Platform 2 - Southbound Fast - Station Building - Old Street Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/wood/lead - To tunnel rings throughout | | | R728767 | | |
| 16639 | ACTIVE | N | N127-00-5/262 | Platform 2 - Southbound Fast - Station Building - Old Street Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Tail Wall: Switch Box - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | | | | |
| 70712 | ACTIVE | N | N127-00-5/262 | Platform 2 - Southbound Fast - Station Building - Old Street Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - total 4 no - To J hangers - trackside wall | | 4 | R728767 | | |
| 18354 | ACTIVE | N | N127-00-5/262/CLG-01 | Ceiling: Solid - 1 - Platform 2 - Station Building - Old Street Stn | Cellactite Sheeting | Asbestos | Strongly Presumed | | | | Additional inspection behind large corrugated metal covers over platform and track Cellactite sheeting | | | | | |
| 16640 | ACTIVE | N | N127-00-5/262/CLG-01 | Ceiling: Solid - 1 - Platform 2 - Station Building - Old Street Stn | Caulking | Asbestos | Strongly Presumed | | | | Caulking within tunnel rings strongly presumed to be present but not visible | | | | | |
| 16641 | ACTIVE | N | N127-00-5/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Old Street Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables Note limited information of exact location of cable (need further details) | | 2 | | | YES |
| 11057 | ACTIVE | N | N127-00-5/263 | Platform 3 - Network Rail - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16642 | ACTIVE | N | N127-00-5/263 | Platform 3 - Network Rail - Station Building - Old Street Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - Network Rail Area | | | | | |
| 11058 | ACTIVE | N | N127-00-5/264 | Platform 4 - Network Rail - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16643 | ACTIVE | N | N127-00-5/264 | Platform 4 - Network Rail - Station Building - Old Street Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - Network Rail Area | | | | | |
| 11059 | ACTIVE | N | N127-00-5/411 | Disused Room - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19049 | ACTIVE | N | N127-00-5/411 | Disused Room - Station Building - Old Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11060 | ACTIVE | N | N127-00-5/412 | Disused Room - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16644 | ACTIVE | N | N127-00-5/412 | Disused Room - Station Building - Old Street Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11061 | ACTIVE | N | N127-00-5/661 | Switch Cupboard - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | | | | | | |



Hazardous Material Asset Register - Summary



N127-00 - Station Building - Old Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18355 | ACTIVE | N | N127-00-5/661/CLG-01 | Ceiling: Solid - 1 - Switch Cupboard - Station Building - Old Street Stn | Void | Asbestos | No Access: Presumed | | | | Not possible to inspect above supalux panels at time of survey due to electricians working on equipment | | | | YES | |
| 16645 | ACTIVE | N | N127-00-5/661/CLG-01 | Ceiling: Solid - 1 - Switch Cupboard - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11062 | ACTIVE | N | N127-00-5/662 | Switch Cupboard - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | | | | | | |
| 16646 | ACTIVE | N | N127-00-5/662/CLG-01 | Ceiling: Solid - 1 - Switch Cupboard - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18405 | ACTIVE | N | N127-00-5/662/CLG-01 | Ceiling: Solid - 1 - Switch Cupboard - Station Building - Old Street Stn | Void | Asbestos | No Access: Presumed | | | | Not possible to inspect above supalux panels at time of survey due to electricians working on equipment | | | | YES | |
| 11063 | ACTIVE | N | N127-00-5/663 | Switch Cupboard - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16648 | ACTIVE | N | N127-00-5/663/CLG-01 | Ceiling: Solid - 1 - Switch Cupboard - Station Building - Old Street Stn | Void | Asbestos | No Access: Presumed | | | | Not possible to inspect above supalux panels at time of survey due to electricians working on equipment | | | | YES | |
| 16647 | ACTIVE | N | N127-00-5/663/CLG-01 | Ceiling: Solid - 1 - Switch Cupboard - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11064 | ACTIVE | N | N127-00-5/664 | Switch Cupboard - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16649 | ACTIVE | N | N127-00-5/664/CLG-01 | Ceiling: Solid - 1 - Switch Cupboard - Station Building - Old Street Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Panels | | | | YES | |
| 19050 | ACTIVE | N | N127-00-5/664/CLG-01 | Ceiling: Solid - 1 - Switch Cupboard - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels | | | | | |
| 11065 | ACTIVE | N | N127-00-5/665 | Switch Cupboard - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18356 | ACTIVE | N | N127-00-5/665/CLG-01 | Ceiling: Solid - 1 - Switch Cupboard - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels | | | | | |
| 16651 | ACTIVE | N | N127-00-5/665/CLG-01 | Ceiling: Solid - 1 - Switch Cupboard - Station Building - Old Street Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Panels | | | | YES | |



Hazardous Material Asset Register - Summary



N127-00 - Station Building - Old Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 16650 | ACTIVE | N | N127-00-5/665/WAL-001 | Wall: Internal - 1 - Switch Cupboard - Station Building - Old Street Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 1x Switch box Wall 1 Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 42161 | ACTIVE | N | N127-00-5/665/WAL-002 | Wall: Internal - 2 - Switch Cupboard - Station Building - Old Street Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 4x Switch boxes Wall 2 Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 4 | | | |
| 11066 | ACTIVE | N | N127-00-5/761 | CER - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42162 | ACTIVE | N | N127-00-5/761 | CER - Station Building - Old Street Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline board | | | | | |
| 16652 | ACTIVE | N | N127-00-5/761 | CER - Station Building - Old Street Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access | | | | | |
| 42163 | ACTIVE | N | N127-00-5/761/FLR-01 | Floor - 1 - CER - Station Building - Old Street Stn | Cable Duct: Other | Asbestos | Presumed | | | | Cable ducts - No access presumed | | | | | |
| 11067 | ACTIVE | N | N127-00-5/763 | Disused Room - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18406 | ACTIVE | N | N127-00-5/763/CLG-01 | Ceiling: Solid - 1 - Disused Room - Station Building - Old Street Stn | Boarding: AIB | Asbestos | Known | | | | Amosite - AIB Likely to have AIB damage in the false ceiling from previous cutting of board. | | | | | |
| 18835 | ACTIVE | N | N127-00-5/763/WAL-001 | Wall: Internal - 1 - Disused Room - Station Building - Old Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Boarding | | | | | |
| 16653 | ACTIVE | N | N127-00-5/763/WAL-003 | Wall: Internal - 3 - Disused Room - Station Building - Old Street Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Boarding | | | | | |
| 11068 | ACTIVE | N | N127-00-5/771 | Pump Room - Station Building - Old Street Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18357 | ACTIVE | N | N127-00-5/771 | Pump Room - Station Building - Old Street Stn | Gasket :Pipework | Asbestos | Presumed | | | | Pumps - Old Gaskets | | | | | |
| 16655 | ACTIVE | N | N127-00-5/771/CLG-01 | Ceiling: Solid - 1 - Pump Room - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux; Rock Wool; PVC Cables above Supalux Tiles | | | | | |
| 16654 | ACTIVE | N | N127-00-5/771/CLG-01 | Ceiling: Solid - 1 - Pump Room - Station Building - Old Street Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |



Hazardous Material Asset Register - Summary



N127-00 - Station Building - Old Street Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-------------------|---------------|---------------------|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 25712 | ACTIVE | N | N127-00-5/771/WAL-003 | Wall: Internal - 3 - Pump Room - Station Building - Old Street Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 x switch box No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 16656 | ACTIVE | N | N127-00-5/791 | Vent Shaft - Station Building - Old Street Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No access | | | | | |

N135-00 - Station Building - London Bridge Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 11309 | ACTIVE | N | N135-00-5/713 | SER - Station Building - London Bridge Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N137-00 - Station Building - Borough Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 44851 | ACTIVE | N | N137-00-0/000/CPY-01 | Canopy: Station Entrance - 1 - Station Entrance - Station Building - Borough Stn | Glazing Rope | Asbestos | No Access: Presumed | | | | No Access to Glazing Bars/Rope Seals - SP | | | | N | N |
| 11380 | ACTIVE | N | N137-00-1/001 | Booking Hall - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16571 | ACTIVE | N | N137-00-1/001/CLG-01 | Ceiling: Suspended - 1 - Booking Hall - Station Building - Borough Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels | | | | | |
| 16572 | ACTIVE | N | N137-00-1/001/CLG-01 | Ceiling: Suspended - 1 - Booking Hall - Station Building - Borough Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above False Ceiling - W4 2 x Supalux Panels; | | | | YES | |
| 16573 | ACTIVE | N | N137-00-1/001/CLG-01 | Ceiling: Suspended - 1 - Booking Hall - Station Building - Borough Stn | Debris: Other | Asbestos | Surveyed – Not Detected | | | | Metal Beams - Sprayed Coating | | | | YES | |
| 16570 | ACTIVE | N | N137-00-1/001/WAL-001 | Wall: Internal - 1 - Booking Hall - Station Building - Borough Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Metal Poster Boards on Plasterboard | | 3 | | | |
| 18274 | ACTIVE | N | N137-00-1/001/WAL-004 | Wall: Internal - 4 - Booking Hall - Station Building - Borough Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels | | 2 | | | |
| 11381 | ACTIVE | N | N137-00-1/011 | Ticket Office - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19044 | ACTIVE | N | N137-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Borough Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |



Hazardous Material Asset Register - Summary



N137-00 - Station Building - Borough Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 16574 | ACTIVE | N | N137-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Borough Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Brick, Breeze Block; Fibreglass Lagging above False Ceiling | | | | YES | |
| 18275 | ACTIVE | N | N137-00-1/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Borough Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Rubbish beneath Computer Flooring | | | | | YES |
| 11382 | ACTIVE | N | N137-00-1/021 | POM - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 16575 | ACTIVE | N | N137-00-1/021/FLR-01 | Floor - 1 - POM - Station Building - Borough Stn | Void | Asbestos | Surveyed – Not Detected | | | | Beneath Computer Flooring | | | | | YES |
| 11383 | ACTIVE | N | N137-00-1/031 | Mess Room - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 16577 | ACTIVE | N | N137-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Borough Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18401 | ACTIVE | N | N137-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Borough Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Plaster; Brick Walls; Metal Ducting & Conduits; Fibreglass Lagging above False Ceiling | | | | YES | |
| 16576 | ACTIVE | N | N137-00-1/031/FLR-01 | Floor - 1 - Mess Room - Station Building - Borough Stn | Void | Asbestos | Surveyed – Not Detected | | | | concrete below raise floor | | | | | YES |
| 18276 | ACTIVE | N | N137-00-1/031/WAL-003 | Wall: Internal - 3 - Mess Room - Station Building - Borough Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 11384 | ACTIVE | N | N137-00-1/036 | Toilet: Unisex - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16578 | ACTIVE | N | N137-00-1/036 | Toilet: Unisex - Station Building - Borough Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11385 | ACTIVE | N | N137-00-1/071 | Circulation Area - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19045 | ACTIVE | N | N137-00-1/071/CLG-01 | Ceiling: Suspended - 1 - Circulation Area - Station Building - Borough Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above Panels of False Ceiling | | | R672576 | YES | |
| 18277 | ACTIVE | N | N137-00-1/071/CLG-01 | Ceiling: Suspended - 1 - Circulation Area - Station Building - Borough Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Concrete; Supalux Panels; Plasterboard; Metal Sprayed Coating | | | | | |
| 16579 | ACTIVE | N | N137-00-1/071/FLR-01 | Floor - 1 - Circulation Area - Station Building - Borough Stn | Void | Asbestos | No Access: Presumed | | | | No Access - Hatches - Hatch nr 1/631 - Rubber Cables & Concrete beneath tiles | | | | | YES |
| 19356 | ACTIVE | N | N137-00-1/071/WAL-001 | Wall: Internal - 1 - Circulation Area - Station Building - Borough Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |



Hazardous Material Asset Register - Summary



N137-00 - Station Building - Borough Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 16580 | ACTIVE | N | N137-00-1/071/WAL-003 | Wall: Internal - 3 - Circulation Area - Station Building - Borough Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Durasteel Panel above Lift in Shaft | | | | | |
| 16568 | ACTIVE | N | N137-00-1/136 | Lift Shaft - Station Building - Borough Stn | | Asbestos | Surveyed – Not Detected | | | | Lift Cars: Small electrical boxes on top of lift cars | | | | | |
| 44852 | ACTIVE | N | N137-00-1/136 | Lift Shaft - Station Building - Borough Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Small electrical boxes on top of lift cars - Presumed ACM inside (No access on re-inspection - Access to lift shaft required 03-03-2023) | | | | N | N |
| 16569 | ACTIVE | N | N137-00-1/136 | Lift Shaft - Station Building - Borough Stn | No Access | Asbestos | No Access: Presumed | | | | Lift Shaft: Durasteel Panelling Forming internal structure throughout shafts & Woven cable insulation length of shafts | | | | | |
| 11386 | ACTIVE | N | N137-00-1/236 | Lobby - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18832 | ACTIVE | N | N137-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Borough Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 16582 | ACTIVE | N | N137-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Borough Stn | Void | Asbestos | Surveyed – Not Detected | | | | Painted Concrete; Brick Walls, Breeze Blocks above Supalux Tiles | | | | YES | |
| 16581 | ACTIVE | N | N137-00-1/236/FLR-01 | Floor - 1 - Lobby - Station Building - Borough Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete beneath Computer Flooring | | | | | YES |
| 11387 | ACTIVE | N | N137-00-1/237 | Lobby - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16583 | ACTIVE | N | N137-00-1/237/FLR-01 | Floor - 1 - Lobby - Station Building - Borough Stn | Void | Asbestos | No Access: Presumed | | | | To Hatch - Metal Drain | | | | | YES |
| 11388 | ACTIVE | N | N137-00-1/281 | Station Control Room - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16425 | ACTIVE | N | N137-00-1/281/CLG-01 | Ceiling: Suspended - 1 - Station Control Room - Station Building - Borough Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above False Ceiling - Metal Roof - Spray Coating (Also on Pipework & Beams), Concrete; Brick Walls; Metal Trunking & Conduits; Fibreglass Lagging; | | | | YES | |
| 18111 | ACTIVE | N | N137-00-1/281/CLG-01 | Ceiling: Suspended - 1 - Station Control Room - Station Building - Borough Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plaster & Fibreboard; Boarding | | | | | |
| 16584 | ACTIVE | N | N137-00-1/281/WAL-002 | Wall: Internal - 2 - Station Control Room - Station Building - Borough Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 11389 | ACTIVE | N | N137-00-1/401 | Switch Cupboard - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16426 | ACTIVE | N | N137-00-1/401/WAL-002 | Wall: Internal - 2 - Switch Cupboard - Station Building - Borough Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux & Fibreboard Boxing - Pipes behind; Supalux Panels behind Switch Boxes | | | | | |



Hazardous Material Asset Register - Summary



N137-00 - Station Building - Borough Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18396 | ACTIVE | N | N137-00-1/401/WAL-002 | Wall: Internal - 2 - Switch Cupboard - Station Building - Borough Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Grey Switch Box 300amp - Insulation within No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 16427 | ACTIVE | N | N137-00-1/401/WAL-003 | Wall: Internal - 3 - Switch Cupboard - Station Building - Borough Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux & Fibreboard Boxing - Pipes behind, Supalux Panels | | | | | |
| 11390 | ACTIVE | N | N137-00-1/418 | Toilet: Unisex - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16428 | ACTIVE | N | N137-00-1/418 | Toilet: Unisex - Station Building - Borough Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11391 | ACTIVE | N | N137-00-1/631 | Stairs: Spiral - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18112 | ACTIVE | N | N137-00-1/631 | Stairs: Spiral - Station Building - Borough Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Rings (No Access Behind) - Solid Caulking | | | | | |
| 16429 | ACTIVE | N | N137-00-1/631 | Stairs: Spiral - Station Building - Borough Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Bottom of Stairs nr 2/733 Supalux Panel | | | | | |
| 11392 | ACTIVE | N | N137-00-1/662 | Store - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16430 | ACTIVE | N | N137-00-1/662/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Borough Stn | Debris: Other | Asbestos | Surveyed – Not Detected | | | | Sprayed Coating - Ceiling Level and Beams to Ceiling | | | | | |
| 11393 | ACTIVE | N | N137-00-2/201 | Passage - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 18971 | ACTIVE | N | N137-00-2/201/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Borough Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above Ceiling without damage to Tiles | | | | YES | |
| 11394 | ACTIVE | N | N137-00-2/202 | Passage - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 16431 | ACTIVE | N | N137-00-2/202 | Passage - Station Building - Borough Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11395 | ACTIVE | N | N137-00-2/203 | Passage - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 68242 | ACTIVE | N | N137-00-2/203 | Passage - Station Building - Borough Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs above false ceiling | | | R672576 | | |
| 18113 | ACTIVE | N | N137-00-2/203/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Borough Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Strip, Plaster | | | | YES | |



Hazardous Material Asset Register - Summary



N137-00 - Station Building - Borough Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 16432 | ACTIVE | N | N137-00-2/203/FLR-01 | Floor - 1 - Passage - Station Building - Borough Stn | Void | Asbestos | No Access: Presumed | | | | 7 x Hatches - No Access through Hatches - without causing damage | | | | | YES |
| 11396 | ACTIVE | N | N137-00-2/236 | Lobby - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18825 | ACTIVE | N | N137-00-2/236/WAL-003 | Wall: Internal - 3 - Lobby - Station Building - Borough Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |
| 11397 | ACTIVE | N | N137-00-2/261 | Platform 1 - Northbound Fast - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70677 | ACTIVE | N | N137-00-2/261 | Platform 1 - Northbound Fast - Station Building - Borough Stn | | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 2 x 8 no - Within cable pit by cross passage | | 16 | R728766 | N | Y |
| 70676 | ACTIVE | N | N137-00-2/261 | Platform 1 - Northbound Fast - Station Building - Borough Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 4 no - Within cable pit departure end | | 4 | R728766 | N | Y |
| 70674 | ACTIVE | N | N137-00-2/261 | Platform 1 - Northbound Fast - Station Building - Borough Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728766 | | |
| 43222 | INACTIVE | N | N137-00-2/261 | Platform 1 - Northbound Fast - Station Building - Borough Stn | Westing house Boxes | Asbestos | Presumed | | | | DUPLICATE OF 16435 03-03-23 White Westing house box No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | N | N |
| 68245 | ACTIVE | N | N137-00-2/261 | Platform 1 - Northbound Fast - Station Building - Borough Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs above VE panel trunking | | | R672576 | | |
| 70678 | ACTIVE | N | N137-00-2/261 | Platform 1 - Northbound Fast - Station Building - Borough Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 8 no - Within invert midway wall | | 8 | R728766 | N | Y |
| 16435 | ACTIVE | N | N137-00-2/261 | Platform 1 - Northbound Fast - Station Building - Borough Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | Westinghouse Box nr 2/711 No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 16434 | ACTIVE | N | N137-00-2/261 | Platform 1 - Northbound Fast - Station Building - Borough Stn | Cable: Sheath | Asbestos | Known | | | | 2x10mm Cable going into Track nr 2/711 Reinspected 03-03-2023 | | | | | |
| 16433 | ACTIVE | N | N137-00-2/261 | Platform 1 - Northbound Fast - Station Building - Borough Stn | Other Boarding | Asbestos | Known | | | | 3 sides Horizontal Boxing - Chrysotile nr 2/711 Photo as below as shows other end of platform Re-inspected 03-03-23 | | | | | |
| 70675 | ACTIVE | N | N137-00-2/261 | Platform 1 - Northbound Fast - Station Building - Borough Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728766 | | |



Hazardous Material Asset Register - Summary



N137-00 - Station Building - Borough Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 16436 | ACTIVE | N | N137-00-2/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Borough Stn | Cable Duct: Other | Asbestos | Strongly Presumed | | | | Platform 1 Invert Cable Sleeves. Survey 23/03/05 Tested Ducts by Dividing wall - NAD - Bitumen No access during 2023 Re-inspection as confined space team required | | | | | YES |
| 11398 | ACTIVE | N | N137-00-2/601 | Stairs: Linear - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16437 | ACTIVE | N | N137-00-2/601 | Stairs: Linear - Station Building - Borough Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 68243 | ACTIVE | N | N137-00-2/601 | Stairs: Linear - Station Building - Borough Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs above metal trunking | | | R672576 | | |
| 11399 | ACTIVE | N | N137-00-2/602 | Stairs: Linear - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18114 | ACTIVE | N | N137-00-2/602 | Stairs: Linear - Station Building - Borough Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 68244 | ACTIVE | N | N137-00-2/602 | Stairs: Linear - Station Building - Borough Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs above metal trunking | | | R672576 | | |
| 11400 | ACTIVE | N | N137-00-2/603 | Stairs: Linear - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16438 | ACTIVE | N | N137-00-2/603 | Stairs: Linear - Station Building - Borough Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11401 | ACTIVE | N | N137-00-2/604 | Stairs: Linear - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16439 | ACTIVE | N | N137-00-2/604 | Stairs: Linear - Station Building - Borough Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 16440 | ACTIVE | N | N137-00-2/636 | Overbridge - Station Building - Borough Stn | Lead/Leading | Lead Paint/Lead | Known | | | | RSJ Cream Gloss Analysis 1.56% | | | | | |
| 18972 | ACTIVE | N | N137-00-2/636/FLR-01 | Floor - 1 - Overbridge - Station Building - Borough Stn | Void | Asbestos | No Access: Presumed | | | | Hatches - No Access through Hatches - without causing damage | | 7 | | | YES |
| 11402 | ACTIVE | N | N137-00-2/661 | Switch Room - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18115 | ACTIVE | N | N137-00-2/661/FLR-01 | Floor - 1 - Switch Room - Station Building - Borough Stn | Void | Asbestos | No Access: Presumed | | | | No Access beneath metal check plate | | | | | YES |
| 16441 | ACTIVE | N | N137-00-2/661/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Borough Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux & 2 Suplaux Panels on top of Board | | | | | |



Hazardous Material Asset Register - Summary



N137-00 - Station Building - Borough Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 11403 | ACTIVE | N | N137-00-2/662 | Switch Room - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44855 | ACTIVE | N | N137-00-2/662 | Switch Room - Station Building - Borough Stn | Other Electrical Boxes | Asbestos | Removed | | | | 3no Blue & 1no Grey Switch Boxes on Metal Frame - Insulation within Not present during 2023 reinspection | | | | N | N |
| 16442 | ACTIVE | N | N137-00-2/662 | Switch Room - Station Building - Borough Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 44854 | ACTIVE | N | N137-00-2/662 | Switch Room - Station Building - Borough Stn | Other Electrical Boxes | Asbestos | Removed | | | | Blue Trunking & Electrical Equipment - Insulation within Not present during 2023 reinspection | | | | N | N |
| 11404 | ACTIVE | N | N137-00-2/663 | Switch Cupboard - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44856 | ACTIVE | N | N137-00-2/663 | Switch Cupboard - Station Building - Borough Stn | Other Electrical Boxes | Asbestos | Removed | | | | Grey Trunking - Insulation within Not present in 2023 reinspection | | | | N | N |
| 44857 | ACTIVE | N | N137-00-2/663/WAL-002 | Wall: Internal - 2 - Switch Cupboard - Station Building - Borough Stn | Other Electrical Boxes | Asbestos | Removed | | | | 3no Grey Switch Boxes - Insulation within Not present in 2023 reinspection | | 3 | | N | N |
| 16443 | ACTIVE | N | N137-00-2/663/WAL-004 | Wall: Internal - 4 - Switch Cupboard - Station Building - Borough Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel above Door | | | | | |
| 11405 | ACTIVE | N | N137-00-2/665 | Switch Cupboard - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16444 | ACTIVE | N | N137-00-2/665/WAL-003 | Wall: Internal - 3 - Switch Cupboard - Station Building - Borough Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux & 2 Supalux Panels on top of Board | | | | | |
| 11406 | ACTIVE | N | N137-00-2/666 | Switch Cupboard - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18116 | ACTIVE | N | N137-00-2/666 | Switch Cupboard - Station Building - Borough Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11407 | ACTIVE | N | N137-00-2/667 | Switch Cupboard - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16445 | ACTIVE | N | N137-00-2/667 | Switch Cupboard - Station Building - Borough Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11408 | ACTIVE | N | N137-00-2/668 | Switch Cupboard - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16446 | ACTIVE | N | N137-00-2/668 | Switch Cupboard - Station Building - Borough Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |



Hazardous Material Asset Register - Summary



N137-00 - Station Building - Borough Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------------|--|------------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 11409 | ACTIVE | N | N137-00-2/711 | Relay Room - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16447 | ACTIVE | N | N137-00-2/711 | Relay Room - Station Building - Borough Stn | Vinyl tiles | Asbestos | Known | | | | Green/ Light Grey Vinyl Tiles Some tiles removed Reinspected in 2023 | | | | | |
| 44323 | ACTIVE | N | N137-00-2/711 | Relay Room - Station Building - Borough Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline boarding wall 1 & 3 Reinspected 03-03-23 | | | | | |
| 16519 | ACTIVE | N | N137-00-2/711 | Relay Room - Station Building - Borough Stn | Cable: Sheath | Asbestos | Known | | | | 10mm Cable going into Track from relay room via platform Reinspected 03-03-2023 | | 2 | | | |
| 43219 | ACTIVE | N | N137-00-2/711/ WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Borough Stn | Cable: Sheath | Asbestos | Presumed | | | | known asbestos braided cable x2 running along rack to wall 1 Reinspected 03-03-2023 | | | | N | N |
| 16520 | INACTIVE | N | N137-00-2/711/ WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Borough Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | PCB's -Fair Condition. Serial Nos. 186493; 186491; 186474; 186510 | | 4 | | | |
| 18117 | ACTIVE | N | N137-00-2/711/ WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Borough Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | 600v WB & SC Ltd westernhouse box- Insulation within - wall2 No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 18200 | ACTIVE | N | N137-00-2/711/ WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Borough Stn | Boarding: Cement | Asbestos | Strongly Presumed | | | | Boarding to Racking Under PCB's Reinspection 2023 | | | | | |
| 16518 | ACTIVE | N | N137-00-2/711/ WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Borough Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box(es) No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 16448 | ACTIVE | N | N137-00-2/711/ WAL-004 | Wall: Internal - 4 - Relay Room - Station Building - Borough Stn | Other Boarding | Asbestos | Removed | | | | Brown composite board to wall 4 Not present during 2023 reinspection | | 1 | | | |
| 11410 | ACTIVE | N | N137-00-2/731 | CER - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16521 | ACTIVE | N | N137-00-2/731/ FLR-01 | Floor - 1 - CER - Station Building - Borough Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete beneath Computer Flooring | | | | | YES |
| 16522 | ACTIVE | N | N137-00-2/731/ WAL-004 | Wall: Internal - 4 - CER - Station Building - Borough Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Grey Switch Boxes 60amps - Insulation within No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within. | | 2 | | | |
| 11411 | ACTIVE | N | N137-00-2/732 | Switch Cupboard - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18201 | ACTIVE | N | N137-00-2/732 | Switch Cupboard - Station Building - Borough Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N137-00 - Station Building - Borough Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 11412 | ACTIVE | N | N137-00-2/733 | Switch Room - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18202 | ACTIVE | N | N137-00-2/733 | Switch Room - Station Building - Borough Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Caulking within Tunnel Rings | | | | | |
| 16523 | ACTIVE | N | N137-00-2/733/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Borough Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels | | | | | |
| 16524 | ACTIVE | N | N137-00-2/733/WAL-004 | Wall: Internal - 4 - Switch Room - Station Building - Borough Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 11413 | ACTIVE | N | N137-00-2/734 | Computer Equipment Cupboard - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16525 | ACTIVE | N | N137-00-2/734 | Computer Equipment Cupboard - Station Building - Borough Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11414 | ACTIVE | N | N137-00-2/901 | Disused Room - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19354 | ACTIVE | N | N137-00-2/901 | Disused Room - Station Building - Borough Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11415 | ACTIVE | N | N137-00-3/081 | Pump Room - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16526 | ACTIVE | N | N137-00-3/081 | Pump Room - Station Building - Borough Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11416 | ACTIVE | N | N137-00-3/262 | Platform 2 - Southbound Fast - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16527 | ACTIVE | N | N137-00-3/262 | Platform 2 - Southbound Fast - Station Building - Borough Stn | Cable: Sheath | Asbestos | Known | | | | 10mm Cable going into Cable Run Reinspection 2023 | | 1 | | | |
| 16528 | INACTIVE | N | N137-00-3/262 | Platform 2 - Southbound Fast - Station Building - Borough Stn | Cable: Sheath | Asbestos | Known | | | | DUPLICATE TO 16527 10mm Cable going into Track nr 3/711 | | 1 | | | |
| 18203 | ACTIVE | N | N137-00-3/262 | Platform 2 - Southbound Fast - Station Building - Borough Stn | Other Boarding | Asbestos | Known | | | | Chrysotile Boarding - nr 3/711 Reinspectws 2023 | | | | | |
| 68246 | ACTIVE | N | N137-00-3/262 | Platform 2 - Southbound Fast - Station Building - Borough Stn | Void | Asbestos | Surveyed – Not Detected | | | | No identified ACMs above VE panel trunking | | | R672576 | | |
| 70683 | ACTIVE | N | N137-00-3/262 | Platform 2 - Southbound Fast - Station Building - Borough Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728766 | | |
| 70679 | ACTIVE | N | N137-00-3/262 | Platform 2 - Southbound Fast - Station Building - Borough Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728766 | | |



Hazardous Material Asset Register - Summary



N137-00 - Station Building - Borough Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|------------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 70687 | ACTIVE | N | N137-00-3/262 | Platform 2 - Southbound Fast - Station Building - Borough Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 8 no - To invert brick wall - midway | | 8 | R728766 | N | Y |
| 70686 | ACTIVE | N | N137-00-3/262 | Platform 2 - Southbound Fast - Station Building - Borough Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 8 no - To invert brick wall - midway | | 8 | R728766 | N | Y |
| 18399 | ACTIVE | N | N137-00-3/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Borough Stn | Cable Duct: Other | Asbestos | Strongly Presumed | | | | Platform 2 Invert. Cable Sleeves No access during 2023 re-inspection as confined space team required | | | | | YES |
| 11417 | ACTIVE | N | N137-00-3/406 | Store - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18829 | ACTIVE | N | N137-00-3/406 | Store - Station Building - Borough Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11418 | ACTIVE | N | N137-00-3/711 | Relay Room - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18980 | ACTIVE | N | N137-00-3/711 | Relay Room - Station Building - Borough Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | vinyl tiles all walls Reinspected 2023 | | 1 | | | |
| 16529 | ACTIVE | N | N137-00-3/711 | Relay Room - Station Building - Borough Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 10mm Cable going into Track Reinspected 2023 | | 1 | | | |
| 44853 | ACTIVE | N | N137-00-3/711 | Relay Room - Station Building - Borough Stn | Cable: Wrap | Asbestos | Strongly Presumed | | | | 1x10mm Cable Reinspected 2023 | | 1 | | N | N |
| 43224 | ACTIVE | N | N137-00-3/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Borough Stn | Boarding: Cement | Asbestos | Presumed | | | | Board under PCB's Reinspected 2023 | | | | N | N |
| 43225 | ACTIVE | N | N137-00-3/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Borough Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 600 V box silver No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within. | | | | N | N |
| 16530 | INACTIVE | N | N137-00-3/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Borough Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | PCB's - Good Condition. Serial Nos. 186464; 186476; 186499; 168198; 186516; 392280, 186198, 188516 | | 6 | | | |
| 11419 | ACTIVE | N | N137-00-3/733 | CER - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16533 | ACTIVE | N | N137-00-3/733/CLG-01 | Ceiling: Solid - 1 - CER - Station Building - Borough Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 16534 | ACTIVE | N | N137-00-3/733/CLG-01 | Ceiling: Solid - 1 - CER - Station Building - Borough Stn | Void | Asbestos | No Access: Presumed | | | | Beneath False Ceiling | | | | YES | |
| 18204 | ACTIVE | N | N137-00-3/733/WAL-001 | Wall: Internal - 1 - CER - Station Building - Borough Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Partition Wall - Supalux | | | | | |
| 16531 | ACTIVE | N | N137-00-3/733/WAL-002 | Wall: Internal - 2 - CER - Station Building - Borough Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Partition Wall - Supalux | | | | | |



Hazardous Material Asset Register - Summary



N137-00 - Station Building - Borough Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18205 | ACTIVE | N | N137-00-3/733/WAL-003 | Wall: Internal - 3 - CER - Station Building - Borough Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Grey Switch Box 60amp - Insulation within No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 16532 | ACTIVE | N | N137-00-3/733/WAL-004 | Wall: Internal - 4 - CER - Station Building - Borough Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Partition Wall - Supalux | | | | | |
| 11420 | ACTIVE | N | N137-00-A/131 | LMR - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19041 | ACTIVE | N | N137-00-A/131 | LMR - Station Building - Borough Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Lift Motor, Gearbox and Brake Assembly - Gaskets & Rope Seal. Not possible to reinspect as isolations/engineer required to inspect within. 2023 | | | | | |
| 16536 | ACTIVE | N | N137-00-A/131 | LMR - Station Building - Borough Stn | Isolator Switches | Asbestos | Removed | | | | Facing Borough High Street - 3 Grey Switch Boxes - Insulation within | | 3 | | | |
| 16541 | ACTIVE | N | N137-00-A/131/FLR-01 | Floor - 1 - LMR - Station Building - Borough Stn | Durasteel | Asbestos | Presumed | | | | Lid to Storage Bin Reinspected 2023 | | 1 | | | |
| 16535 | ACTIVE | N | N137-00-A/131/FLR-01 | Floor - 1 - LMR - Station Building - Borough Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Facing Borough High Street - Supalux Panel | | | | | |
| 16537 | ACTIVE | N | N137-00-A/131/WAL-001 | Wall: Internal - 1 - LMR - Station Building - Borough Stn | Other Electrical Boxes | Asbestos | Surveyed – Not Detected | | | | Busbar Chamber. Type 3 States Non Asbestos | | 2 | | | |
| 16539 | ACTIVE | N | N137-00-A/131/WAL-004 | Wall: Internal - 4 - LMR - Station Building - Borough Stn | Other Electrical Boxes | Asbestos | Surveyed – Not Detected | | | | H/way Box No 2&1 - Auto Control 1 & 2 - Insulation within - Type 3 States Non Asbestos | | | | | |
| 16540 | ACTIVE | N | N137-00-A/131/WAL-004 | Wall: Internal - 4 - LMR - Station Building - Borough Stn | Other Electrical Boxes | Asbestos | Surveyed – Not Detected | | | | Controllers - Insulation within - Type 3 States Non Asbestos | | 2 | | | |
| 16538 | ACTIVE | N | N137-00-A/131/WAL-004 | Wall: Internal - 4 - LMR - Station Building - Borough Stn | Other Electrical Boxes | Asbestos | Surveyed – Not Detected | | | | Fuse Box - Insulation within - Type 3 States Non Asbestos | | 1 | | | |
| 18206 | ACTIVE | N | N137-00-A/131/WAL-050 | Wall: Internal - 50 - LMR - Station Building - Borough Stn | Other Electrical Boxes | Asbestos | Removed | | | | Not present in 2023 reinspected Transformer Box (Redundant) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 11421 | ACTIVE | N | N137-00-A/236 | Passage - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18830 | ACTIVE | N | N137-00-A/236 | Passage - Station Building - Borough Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11422 | ACTIVE | N | N137-00-A/316 | Lobby - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N137-00 - Station Building - Borough Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 16543 | ACTIVE | N | N137-00-A/316/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Borough Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux & Plasterboard Boxing | | | | | |
| 16544 | ACTIVE | N | N137-00-A/316/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Borough Stn | Void | Asbestos | No Access: Presumed | | | | Above False Ceiling | | | | YES | |
| 16542 | ACTIVE | N | N137-00-A/316/FLR-01 | Floor - 1 - Lobby - Station Building - Borough Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Quarry Tiles; Wooden False Floor | | | | | YES |
| 11423 | ACTIVE | N | N137-00-A/317 | Locker Room - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16545 | ACTIVE | N | N137-00-A/317 | Locker Room - Station Building - Borough Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11424 | ACTIVE | N | N137-00-A/331 | Mess Room - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16546 | ACTIVE | N | N137-00-A/331 | Mess Room - Station Building - Borough Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11425 | ACTIVE | N | N137-00-A/576 | Stairs: Linear - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16547 | ACTIVE | N | N137-00-A/576/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Borough Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above Entrance - Metal Beam - Sprayed Coating above Metal Ceiling | | | | YES | |
| 18207 | ACTIVE | N | N137-00-A/576/WAL-003 | Wall: Internal - 3 - Linear Stairs - Station Building - Borough Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Board Panels | | | | | |
| 11426 | ACTIVE | N | N137-00-A/663 | Switch Room - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11427 | ACTIVE | N | N137-00-A/664 | Switch Room - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16548 | ACTIVE | N | N137-00-A/664 | Switch Room - Station Building - Borough Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11428 | ACTIVE | N | N137-00-A/665 | Switch Room - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16549 | ACTIVE | N | N137-00-A/665 | Switch Room - Station Building - Borough Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11429 | ACTIVE | N | N137-00-A/731 | CER - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18400 | ACTIVE | N | N137-00-A/731 | CER - Station Building - Borough Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |



Hazardous Material Asset Register - Summary



N137-00 - Station Building - Borough Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|--------------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 11430 | ACTIVE | N | N137-00-A/746 | SCR - Station Building - Borough Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19042 | ACTIVE | N | N137-00-A/746/CLG-01 | Ceiling: Solid - 1 - SCR - Station Building - Borough Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | YES | |
| 16567 | ACTIVE | N | N137-00/CPY-01 | Canopy - 1 - Station Building - Borough Stn | Glazing Rope | Asbestos | No Access: Presumed | | | | No Access to Glazing Bars/Rope Seals | | | | | |

N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 45089 | ACTIVE | N | N143-00-0/001/CPY-02 | Canopy: Station Entrance - 1 - Station Entrance - Station Building - Kennington Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Blue Gloss Coating | | | | N | N |
| 11441 | ACTIVE | N | N143-00-1/001 | Booking Hall - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18030 | ACTIVE | N | N143-00-1/001 | Booking Hall - Station Building - Kennington Stn | Glazing Rope | Asbestos | Known | | | | Rope Seal behind glazing bars Skylight within booking hall/ circulating area | | | | | |
| 18821 | ACTIVE | N | N143-00-1/001/CLG-01 | Ceiling: Suspended - 1 - Booking Hall - Station Building - Kennington Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Panel underneath Glass Ceiling - management survey R641126 - checked confirmed NAD | | | | | |
| 11442 | ACTIVE | N | N143-00-1/011 | Ticket Office - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42587 | ACTIVE | N | N143-00-1/011 | Ticket Office - Station Building - Kennington Stn | | Asbestos | Sampled – Not Detected | | | | Mastic/putty, throughout, to flu pipe and ducting joints above ticket office window in Ticket Office | | | R512676 | N | N |
| 16343 | ACTIVE | N | N143-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Kennington Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles; Wooden Soffit Boards | | | | | |
| 18965 | ACTIVE | N | N143-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Kennington Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Plaster, Solid above False Ceiling | | | | YES | |
| 42586 | ACTIVE | N | N143-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Kennington Stn | Mastic | Asbestos | Sampled – Not Detected | | | | Mastic/putty, throughout, to flu pipe and ducting joints within false ceiling in Ticket Office | | | R512676 | Y | N |
| 18330 | ACTIVE | N | N143-00-1/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Kennington Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Wooden False Floor, Computer Flooring | | | | YES | |
| 11443 | ACTIVE | N | N143-00-1/021 | POM - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17965 | ACTIVE | N | N143-00-1/021/FLR-01 | Floor - 1 - POM - Station Building - Kennington Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |



Hazardous Material Asset Register - Summary



N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 11444 | ACTIVE | N | N143-00-1/031 | Mess Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16345 | ACTIVE | N | N143-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Kennington Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 18029 | ACTIVE | N | N143-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Kennington Stn | Void | Asbestos | No Access: Presumed | | | | Above False Ceiling | | | | YES | |
| 16346 | ACTIVE | N | N143-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Kennington Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 16344 | ACTIVE | N | N143-00-1/031/WAL-002 | Wall: Internal - 2 - Mess Room - Station Building - Kennington Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - Foam Insulation Board | | | | | |
| 11445 | ACTIVE | N | N143-00-1/036 | Lobby - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16348 | ACTIVE | N | N143-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Kennington Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Plaster, Solid above false ceiling | | | | YES | |
| 16347 | ACTIVE | N | N143-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Kennington Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding | | | | | |
| 11446 | ACTIVE | N | N143-00-1/037 | Toilet: Unisex - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16351 | ACTIVE | N | N143-00-1/037/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Kennington Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Plaster, Solid above false ceiling | | | | YES | |
| 16350 | ACTIVE | N | N143-00-1/037/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Kennington Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding | | | | | |
| 16349 | ACTIVE | N | N143-00-1/037/FLR-01 | Floor - 1 - Toilet - Station Building - Kennington Stn | Void | Asbestos | No Access: Presumed | | | | To Manholes beneath Quarry Tiles | | | | | |
| 11447 | ACTIVE | N | N143-00-1/071 | Circulation Area - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16342 | ACTIVE | N | N143-00-1/071 | Circulation Area - Station Building - Kennington Stn | Glazing Rope | Asbestos | Known | | | | Rope seal inside glazing bars - Chrysotile | | | | | |
| 11448 | ACTIVE | N | N143-00-1/082 | Lobby - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 16352 | ACTIVE | N | N143-00-1/082 | Lobby - Station Building - Kennington Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction (see 1/632) | | | | | |
| 11449 | ACTIVE | N | N143-00-1/132 | LMR - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 45090 | INACTIVE | N | N143-00-1/132 | LMR - Station Building - Kennington Stn | Rope Gaskets | Asbestos | Strongly Presumed | | | | Lift Motor, Gearbox and Brake Assembly - Gaskets & Rope Seal | | | | N | N |
| 16353 | ACTIVE | N | N143-00-1/136 | Lift Shaft - Station Building - Kennington Stn | No Access | Asbestos | No Access: Presumed | | | | Shaft not surveyed - Identical from Borough | | | | | |
| 20018 | ACTIVE | N | N143-00-1/136/CLG-01 | Ceiling: Solid - 1 - Lift Shaft - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | Lift Cars | | | | | |
| 11450 | ACTIVE | N | N143-00-1/237 | Lobby - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16355 | ACTIVE | N | N143-00-1/237/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Kennington Stn | Void | Asbestos | Surveyed – Not Detected | | | | Supalux above Supalux Board | | | | YES | |
| 16354 | ACTIVE | N | N143-00-1/237/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Kennington Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding | | | | | |
| 11451 | ACTIVE | N | N143-00-1/238 | Passage - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19353 | ACTIVE | N | N143-00-1/238 | Passage - Station Building - Kennington Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction (see 1/632) | | | | | |
| 11452 | ACTIVE | N | N143-00-1/317 | Locker Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18031 | ACTIVE | N | N143-00-1/317 | Locker Room - Station Building - Kennington Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11453 | ACTIVE | N | N143-00-1/318 | Locker Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16356 | ACTIVE | N | N143-00-1/318 | Locker Room - Station Building - Kennington Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11454 | ACTIVE | N | N143-00-1/333 | Mess Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16357 | ACTIVE | N | N143-00-1/333 | Mess Room - Station Building - Kennington Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |



Hazardous Material Asset Register - Summary



N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 11455 | ACTIVE | N | N143-00-1/412 | Store - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16359 | ACTIVE | N | N143-00-1/412/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Kennington Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Ceiling No supalux ceiling visible from premises inspection photos. Investigate | | | | YES | |
| 16358 | ACTIVE | N | N143-00-1/412/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Kennington Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 11456 | ACTIVE | N | N143-00-1/417 | Toilet: Male - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16360 | ACTIVE | N | N143-00-1/417/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Kennington Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 16361 | ACTIVE | N | N143-00-1/417/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Kennington Stn | Void | Asbestos | Surveyed – Not Detected | | | | Wooden Boarding; Fibreglass Lagging above Supalux Tiles | | | | YES | |
| 18032 | ACTIVE | N | N143-00-1/417/FLR-01 | Floor - 1 - Toilet - Station Building - Kennington Stn | Void | Asbestos | No Access: Presumed | | | | To Manholes beneath Quarry Tiles | | | | | YES |
| 11457 | ACTIVE | N | N143-00-1/418 | Toilet: Female - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16363 | ACTIVE | N | N143-00-1/418/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Kennington Stn | Void | Asbestos | Surveyed – Not Detected | | | | Wooden Boarding; Fibreglass Lagging above Supalux Tiles | | | | YES | |
| 16362 | ACTIVE | N | N143-00-1/418/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Kennington Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11458 | ACTIVE | N | N143-00-1/576 | Ladder - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18461 | ACTIVE | N | N143-00-1/576 | Ladder - Station Building - Kennington Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11459 | ACTIVE | N | N143-00-1/601 | Train Maintainers Office - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18966 | ACTIVE | N | N143-00-1/601 | Train Maintainers Office - Station Building - Kennington Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11460 | ACTIVE | N | N143-00-1/602 | Office - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------------|---|------------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18033 | ACTIVE | N | N143-00-1/602 | Office - Station Building - Kennington Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11461 | ACTIVE | N | N143-00-1/631 | Stairs: Spiral - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42178 | ACTIVE | N | N143-00-1/631 | Stairs: Spiral - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | Central Core of Spiral Stairs - None visible ES7879 Confirms no asbestos | | | | N | N |
| 16364 | ACTIVE | N | N143-00-1/631 | Stairs: Spiral - Station Building - Kennington Stn | Lead/Leading | Lead Paint/Lead | Known | | | | | | | | | |
| 16365 | ACTIVE | N | N143-00-1/631 | Stairs: Spiral - Station Building - Kennington Stn | Lead/Leading | Lead Paint/Lead | Known | | | | White Gloss Top and Bottom of Stairs. Thickness 6.10mm: Analysis 1.81%; Thickness 9.10mm: Analysis 26.7% | | | | | |
| 11462 | ACTIVE | N | N143-00-1/633 | Passage - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16366 | ACTIVE | N | N143-00-1/633/ FLR-01 | Floor - 1 - Passage - Station Building - Kennington Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Manholes | | | | | YES |
| 18034 | ACTIVE | N | N143-00-1/633/ WAL-004 | Wall: Internal - 4 - Passage - Station Building - Kennington Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board; Supalux Boarding above door to 1/632 | | | | | |
| 11463 | ACTIVE | N | N143-00-1/661 | Station Control Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70108 | ACTIVE | N | N143-00-1/661 | Station Control Room - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Electrical equipment. Check manufacturer date. Equipment installed pre 1999 presumed to contain asbestos components within. | | | | | |
| 16367 | ACTIVE | N | N143-00-1/661/ CLG-01 | Ceiling: Suspended - 1 - Station Control Room - Station Building - Kennington Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |
| 45091 | ACTIVE | N | N143-00-1/661/ WAL-003 | Wall: Internal - 3 - Station Control Room - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | 7no Dark Blue Switch Box - Insulation within Could not be seen during re-inspection. Electrical equipment potentially behind metal panel. | | 7 | | N | N |
| 11464 | ACTIVE | N | N143-00-1/666 | Service Riser - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16368 | ACTIVE | N | N143-00-1/666/ CLG-01 | Ceiling: Solid - 1 - Service Riser - Station Building - Kennington Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |
| 45092 | ACTIVE | N | N143-00-1/666/ WAL-003 | Wall: Internal - 3 - Service Riser - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Removed | | | | 1no Red, 1no Grey & 5no Blue Switch Boxes - Insulation within. Not present during 2023 re-inspection. | | 7 | | N | N |



Hazardous Material Asset Register - Summary



N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 11465 | ACTIVE | N | N143-00-1/667 | Switch Cupboard - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16369 | ACTIVE | N | N143-00-1/667/WAL-001 | Wall: Internal - 1 - Switch Cupboard - Station Building - Kennington Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding | | | | | |
| 16370 | ACTIVE | N | N143-00-1/667/WAL-002 | Wall: Internal - 2 - Switch Cupboard - Station Building - Kennington Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding behind Electrical Box | | 2 | | | |
| 18035 | ACTIVE | N | N143-00-1/667/WAL-002 | Wall: Internal - 2 - Switch Cupboard - Station Building - Kennington Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Grey Switch Box - Insulation within 300amp Not inspected internally during 2023 reinspection as no electrician present to isolate. | | 1 | | | |
| 18967 | ACTIVE | N | N143-00-1/667/WAL-004 | Wall: Internal - 4 - Switch Cupboard - Station Building - Kennington Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding | | | | | |
| 11466 | ACTIVE | N | N143-00-1/668 | Switch Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16371 | ACTIVE | N | N143-00-1/668 | Switch Room - Station Building - Kennington Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11467 | ACTIVE | N | N143-00-1/669 | Switch Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16372 | ACTIVE | N | N143-00-1/669 | Switch Room - Station Building - Kennington Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11468 | ACTIVE | N | N143-00-1/731 | CER - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16373 | ACTIVE | N | N143-00-1/731 | CER - Station Building - Kennington Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11469 | ACTIVE | N | N143-00-1/747 | SCR - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16374 | ACTIVE | N | N143-00-1/747 | SCR - Station Building - Kennington Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access | | | | | |
| 11470 | ACTIVE | N | N143-00-2/137 | Fan Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16376 | ACTIVE | N | N143-00-2/137 | Fan Room - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Known | | | | Braided cable to Wall Fan. Braided cable to wall fan cut back to wall and Encapsulated. No safe access down ladder to survey during 2023 re-inspection | | 1 | | | |



Hazardous Material Asset Register - Summary



N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 42181 | ACTIVE | N | N143-00-2/137 | Fan Room - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | Fan room beneath lift path - no known asbestos | | | | | |
| 11471 | ACTIVE | N | N143-00-2/201 | Passage - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42180 | ACTIVE | N | N143-00-2/201 | Passage - Station Building - Kennington Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Concrete services shaft runs beneath public passageway | | | | | |
| 16377 | ACTIVE | N | N143-00-2/201/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Kennington Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard; Supalux Panel | | | | | |
| 11472 | ACTIVE | N | N143-00-2/202 | Passage - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18036 | ACTIVE | N | N143-00-2/202/FLR-01 | Floor - 1 - Passage - Station Building - Kennington Stn | Void | Asbestos | No Access: Presumed | | | | No Access through Manhole | | | | | YES |
| 11473 | ACTIVE | N | N143-00-2/203 | Passage - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16378 | ACTIVE | N | N143-00-2/203 | Passage - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11474 | ACTIVE | N | N143-00-2/204 | Passage - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16379 | ACTIVE | N | N143-00-2/204/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Kennington Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 11475 | ACTIVE | N | N143-00-2/601 | Stairs: Linear - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16380 | ACTIVE | N | N143-00-2/601 | Stairs: Linear - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11476 | ACTIVE | N | N143-00-2/602 | Stairs: Linear - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18968 | ACTIVE | N | N143-00-2/602 | Stairs: Linear - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11477 | ACTIVE | N | N143-00-2/603 | Stairs: Linear - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16381 | ACTIVE | N | N143-00-2/603 | Stairs: Linear - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 11478 | ACTIVE | N | N143-00-2/604 | Stairs: Linear - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18822 | ACTIVE | N | N143-00-2/604 | Stairs: Linear - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11479 | ACTIVE | N | N143-00-2/661 | Switch Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18332 | ACTIVE | N | N143-00-2/661/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Kennington Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Ceiling | | | | YES | |
| 18037 | ACTIVE | N | N143-00-2/661/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Kennington Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 18331 | ACTIVE | N | N143-00-2/661/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Kennington Stn | Caulking | Asbestos | Known | | | | Tunnel Rings - Paint on Tunnel Rings Chrysotile | | | | | |
| 11480 | ACTIVE | N | N143-00-2/776 | Fan Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18038 | ACTIVE | N | N143-00-2/776 | Fan Room - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 1m Cable Unencapsulated No safe access down ladder during 2023 re-inspection | | 1 | | | |
| 45093 | ACTIVE | N | N143-00-2/776 | Fan Room - Station Building - Kennington Stn | Gasket :Pipework | Asbestos | Strongly Presumed | | | | Gaskets to flanges of metal pipework throughout | | 4 | | N | N |
| 11481 | ACTIVE | N | N143-00-3/081 | Lobby - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 45095 | ACTIVE | N | N143-00-3/081 | Lobby - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1x fuse switch box to tunnel rings Not inspected within 2023 re-inspection as no electrician present to electrical isolate. | | 1 | | N | N |
| 45096 | ACTIVE | N | N143-00-3/081 | Lobby - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1x fire isolation equipment Not inspected internally during 2023 re-inspection as no electrician to isolate | | 1 | | N | N |
| 45094 | ACTIVE | N | N143-00-3/081 | Lobby - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1x transformer unit to wall | | 1 | | N | N |
| 16383 | ACTIVE | N | N143-00-3/081/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Kennington Stn | Caulking | Asbestos | Known | | | | Tunnel Ring - Caulking - Chrysotile/ Amphibole ENCAPSULATED | | | | | |
| 16382 | ACTIVE | N | N143-00-3/081/WAL-001 | Wall: Internal - 1 - Lobby - Station Building - Kennington Stn | Caulking | Asbestos | Known | | | | Tunnel Ring - Caulking - Chrysotile/ Amphibole ENCAPSULATED | | | | | |
| 18823 | INACTIVE | N | N143-00-3/081/WAL-007 | Wall: Internal - 7 - Lobby - Station Building - Kennington Stn | Caulking | Asbestos | Known | | | | Switch box 60 amp | | | | | |



Hazardous Material Asset Register - Summary



N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 11482 | ACTIVE | N | N143-00-3/201 | Passage - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16384 | ACTIVE | N | N143-00-3/201 | Passage - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11483 | ACTIVE | N | N143-00-3/202 | Passage - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16385 | ACTIVE | N | N143-00-3/202 | Passage - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11484 | ACTIVE | N | N143-00-3/203 | Passage - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18039 | ACTIVE | N | N143-00-3/203 | Passage - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11485 | ACTIVE | N | N143-00-3/204 | Passage - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16386 | ACTIVE | N | N143-00-3/204 | Passage - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Ducts with 16mm woven Cables Not visible during 2023 re-inspection. Possibly within CMS | | 5 | | | |
| 11486 | ACTIVE | N | N143-00-3/236 | Passage - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16388 | ACTIVE | N | N143-00-3/236 | Passage - Station Building - Kennington Stn | Boarding: Cement | Asbestos | Known | | | | White boarding behind Electrical Equipment - Chrysotile | | | | | |
| 16387 | ACTIVE | N | N143-00-3/236 | Passage - Station Building - Kennington Stn | Caulking | Asbestos | Known | | | | Wall - Tunnel Ring - Caulking - Chrysotile - ENCAPSULATED | | | | | |
| 45114 | ACTIVE | N | N143-00-3/236 | Passage - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 2x pump supply fuse switches to wall Not inspected internally during 2023 re-inspection as no electrician present. | | 2 | | N | N |
| 45112 | ACTIVE | N | N143-00-3/236 | Passage - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1x pump no.1 box to wall LHS by door Not inspected internally during 2023 re-inspection as no electrician | | | | N | N |
| 45118 | ACTIVE | N | N143-00-3/236 | Passage - Station Building - Kennington Stn | Other Boarding | Asbestos | Presumed | | | | 6x distribution boards and combination fuse switch boxes to wall. Not inspected internally during 2023 re-inspection as no electrician present. | | 6 | | N | N |
| 45117 | ACTIVE | N | N143-00-3/236 | Passage - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 2x pump supply fuse boxes to wall Not inspected internally during 2023 re-inspection as no electrician present | | 2 | | N | N |
| 45116 | ACTIVE | N | N143-00-3/236 | Passage - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1x trans rec unit to wall Not inspected internally during 2023 reinspection as no electrician present. | | 1 | | N | N |



Hazardous Material Asset Register - Summary



N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 45115 | ACTIVE | N | N143-00-3/236 | Passage - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1x terminal box to floor | | 1 | | N | N |
| 45113 | ACTIVE | N | N143-00-3/236 | Passage - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 2x orange fuse switch boxes to wall Not inspected internally during 2023 re-inspection as no electrician present | | 2 | | N | N |
| 45111 | ACTIVE | N | N143-00-3/236 | Passage - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1x combination fuse switch box to wall LHS by door Not inspected internally during 2023 reinspection as no electrician present. | | 1 | | N | N |
| 45108 | ACTIVE | N | N143-00-3/236 | Passage - Station Building - Kennington Stn | Other Boarding | Asbestos | Known | | | | Board to pump supply fuse boxes | | | | N | N |
| 45106 | ACTIVE | N | N143-00-3/236 | Passage - Station Building - Kennington Stn | Other Boarding | Asbestos | Known | | | | Board to pump supplle fuse switches | | | | N | N |
| 45107 | ACTIVE | N | N143-00-3/236 | Passage - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Known | | | | 2x braided cables to cable run going into room 3/715 | | 2 | | N | N |
| 18040 | ACTIVE | N | N143-00-3/236/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Kennington Stn | Caulking | Asbestos | Known | | | | Wall - Tunnel Ring - Caulking - Chrysotile - ENCAPSULATED | | | | | |
| 20019 | ACTIVE | N | N143-00-3/236/FLR-01 | Floor - 1 - Passage - Station Building - Kennington Stn | Gasket :Pipework | Asbestos | Presumed | | | | Possible asbestos gaskets to pipework within manhole. Not possible to fully inspect. Other ACMs maybe present. | | | | | |
| 16389 | ACTIVE | N | N143-00-3/236/WAL-001 | Wall: Internal - 1 - Passage - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 10mmØ Cables | | 1 | | | |
| 16390 | ACTIVE | N | N143-00-3/236/WAL-009 | Wall: Internal - 9 - Passage - Station Building - Kennington Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 2 x Grey Switch Box & 2 x Red Fuse Boxes - Insulation within | | 4 | | | |
| 11487 | ACTIVE | N | N143-00-3/261 | Platform 1 - Northbound Local - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16392 | ACTIVE | N | N143-00-3/261 | Platform 1 - Northbound Local - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform Southend 10mmØ Cables Not visible during 2023 re-inspection, possibly within invert or trackside. | | 1 | | | |
| 42459 | ACTIVE | N | N143-00-3/261 | Platform 1 - Northbound Local - Station Building - Kennington Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Invert - Wood & Grout throughout within flanges to metal tunnel rings - NADIS | | | R414078 | N | N |
| 42461 | ACTIVE | N | N143-00-3/261 | Platform 1 - Northbound Local - Station Building - Kennington Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Invert - Suplalux Panels to some walls and ceiling as firebreaks | | | R414078 | N | N |
| 42463 | INACTIVE | N | N143-00-3/261 | Platform 1 - Northbound Local - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Presumed | | | | Invert - Braided cables (green & white) throughout within j-hanger to platform and trackside walls and ceiling | | | R414078 | N | N |



Hazardous Material Asset Register - Summary



N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 42460 | INACTIVE | N | N143-00-3/261 | Platform 1 - Northbound Local - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Presumed | | | | Platform Invert - Braided cables (green & white) throughout within j-hanger to platform and trackside walls and ceiling | | | R414078 | N | N |
| 42462 | ACTIVE | N | N143-00-3/261 | Platform 1 - Northbound Local - Station Building - Kennington Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Invert - Caulking - Wood & Grout throughout within flanges to metal tunnel rings - NADIS | | | R414078 | N | N |
| 70208 | ACTIVE | N | N143-00-3/261 | Platform 1 - Northbound Local - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Known | | | | Platform 1 Invert - 4x Braided cables to J-Hangers throughout | | 4 | R728764 | N | Y |
| 70209 | ACTIVE | N | N143-00-3/261 | Platform 1 - Northbound Local - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Platform 1 Invert - 10 Core Box to J-Hangers | | 1 | R7287464 | N | Y |
| 70213 | ACTIVE | N | N143-00-3/261 | Platform 1 - Northbound Local - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | Platform 1 Invert - Metal tunnel rings to walls, floor throughout - concrete infill, grout, wood, lead to tunnel ring flanges throughout, plastic cables, metal conduits and CMS, new fire stop and mastics, new electrical boxes, wood splinters, fibres (shuttering, panels, cut offs) to concrete ceiling and walls throughout, supalux debris and boarding, plastic and metal and terracotta cable ducts | | | | | |
| 70207 | ACTIVE | N | N143-00-3/261 | Platform 1 - Northbound Local - Station Building - Kennington Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform 1 Invert - 3x Cement cable ducts to platform wall, departure end by hatch. | | 3 | R728764 | N | Y |
| 70211 | ACTIVE | N | N143-00-3/261 | Platform 1 - Northbound Local - Station Building - Kennington Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform 1 Invert - 4x Bitumen cable ducts to track wall, departure end | | 4 | R728764 | N | Y |
| 45097 | INACTIVE | N | N143-00-3/261 | Platform 1 - Northbound Local - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 1 Invert - Cable wrap on pipe by ladder into invert track wall 0.25m | 0 | | | N | N |
| 18041 | INACTIVE | N | N143-00-3/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 1 Invert - Various Cables | | | | | YES |
| 16391 | ACTIVE | N | N143-00-3/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Kennington Stn | No Access | Asbestos | No Access: Presumed | | | | No Access through Manhole | | | | | |
| 42464 | ACTIVE | N | N143-00-3/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Kennington Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Invert - Supalux panels | | | R414078 | N | N |
| 11488 | ACTIVE | N | N143-00-3/263 | Platform 3 - Northbound Fast - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 45098 | INACTIVE | N | N143-00-3/263 | Platform 3 - Northbound Fast - Station Building - Kennington Stn | Other Boarding | Asbestos | Presumed | | | | Boarding/lining to electrical boxes x2, sides & bottom - 100m from North end of Platform 3, left hand side | | | | N | N |



Hazardous Material Asset Register - Summary



N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 70221 | ACTIVE | N | N143-00-3/263 | Platform 3 - Northbound Fast - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | Platform 3 Invert - Metal tunnel rings to walls, floor throughout - concrete infill, grout, wood, lead to tunnel rings flanges throughout, plastic cables, metal conduits and CMS, new firestop and mastics, plastic and metal pipework, wood splinters, fibres (shuttering, panels, cut-offs), plastic, terracotta and metal cable ducts | | | R728765 | N | Y |
| 70220 | ACTIVE | N | N143-00-3/263 | Platform 3 - Northbound Fast - Station Building - Kennington Stn | | Asbestos | No Access: Presumed | | | | Platform 3 Invert - No access to each end as 2x man holes shut/ jammed | | | R728765 | N | Y |
| 42465 | ACTIVE | N | N143-00-3/263 | Platform 3 - Northbound Fast - Station Building - Kennington Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Invert - Caulking - Wood & Grout throughout within flanges to metal tunnel rings | | | R414078 | N | N |
| 42466 | INACTIVE | N | N143-00-3/263 | Platform 3 - Northbound Fast - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Presumed | | | | Invert - Braided Cables (green & white) throughout within j-hanger to platform and trackside walls and ceiling | | | R414078 | N | N |
| 43374 | ACTIVE | N | N143-00-3/263 | Platform 3 - Northbound Fast - Station Building - Kennington Stn | | Asbestos | Sampled – Not Detected | | | | Cement cable ducting through invert wall, Platform 3 Invert | | | R558376 | N | N |
| 16393 | ACTIVE | N | N143-00-3/263 | Platform 3 - Northbound Fast - Station Building - Kennington Stn | Cable Duct: Other | Asbestos | Strongly Presumed | | | | Redundant Cable Tray 5m from end of Platform Not visible during 2023 re-inspection. Possibly trackside | | | | | |
| 70216 | ACTIVE | N | N143-00-3/263 | Platform 3 - Northbound Fast - Station Building - Kennington Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform 3 Invert -20x Bitumen cable ducts to mid cable pit access | | 20 | R728765 | N | Y |
| 42467 | ACTIVE | N | N143-00-3/263 | Platform 3 - Northbound Fast - Station Building - Kennington Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux panels | | | R414078 | N | N |
| 42468 | ACTIVE | N | N143-00-3/263 | Platform 3 - Northbound Fast - Station Building - Kennington Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Caulking - Wood & Grout throughout within flanges to metal tunnel rings | | | R414078 | N | N |
| 16394 | ACTIVE | N | N143-00-3/263/ FLR-01 | Floor - 1 - Platform 3 - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Presumed | | | | Previously identified asbestos braided cables within this invert were not identified as part of the new management survey R728765 2024. Possible removed as part of the NL extension works at this station. It is noted that no access to each end could be gained as a result of the manholes being jammed. There is a possibility that some asbestos cables maybe still present within these area. Any suspect cables should not be disturbed and reported to the HMT. Further investigation required. | | | | | YES |
| 11489 | ACTIVE | N | N143-00-3/381 | Disused Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 16395 | ACTIVE | N | N143-00-3/381/CLG-01 | Ceiling: Solid - 1 - Disused Room - Station Building - Kennington Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Rings - Caulking Mastic Metal | | | | | |
| 11490 | ACTIVE | N | N143-00-3/382 | Switch Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16397 | ACTIVE | N | N143-00-3/382/CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - Kennington Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Tiles, Plaster, Solid - above False Ceiling | | | | YES | |
| 16396 | ACTIVE | N | N143-00-3/382/CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - Kennington Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 18969 | ACTIVE | N | N143-00-3/382/FLR-01 | Floor - 1 - Switch Room - Station Building - Kennington Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Grey Vinyl Tiles | | | | | YES |
| 11491 | ACTIVE | N | N143-00-3/411 | Store - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18042 | ACTIVE | N | N143-00-3/411 | Store - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 45099 | ACTIVE | N | N143-00-3/411/WAL-002 | Wall: Internal - 2 - Store - Station Building - Kennington Stn | Caulking | Asbestos | Known | | | | Tunnel ring caulking to flanges to rear of metal panel | | | | N | N |
| 11492 | ACTIVE | N | N143-00-3/661 | Lobby - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16398 | ACTIVE | N | N143-00-3/661 | Lobby - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11493 | ACTIVE | N | N143-00-3/662 | Service Riser - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16399 | ACTIVE | N | N143-00-3/662/WAL-002 | Wall: Internal - 2 - Service Riser - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 10mmØ Cables | | 2 | | | |
| 18043 | ACTIVE | N | N143-00-3/662/WAL-003 | Wall: Internal - 3 - Service Riser - Station Building - Kennington Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | | | | | | |
| 11494 | ACTIVE | N | N143-00-3/663 | Switch Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16400 | ACTIVE | N | N143-00-3/663 | Switch Room - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 45100 | ACTIVE | N | N143-00-3/663/WAL-004 | Wall: Internal - 4 - Switch Room - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1no Grey Switch Box - Insulation within. Note: Switch Box not present during re-inspection. Check electrical equipment during next re-inspection for any other possible ACMs. | | 1 | | N | N |
| 11495 | ACTIVE | N | N143-00-3/664 | Switch Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16401 | ACTIVE | N | N143-00-3/664 | Switch Room - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11496 | ACTIVE | N | N143-00-3/706 | IMR - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 45109 | ACTIVE | N | N143-00-3/706 | IMR - Station Building - Kennington Stn | Vinyl tiles | Asbestos | Presumed | | | | Green marley tiles (partial) on render, brickwork and metal tunnel rings have been removed. Possible asbestos adhesive residue present. Check with HMT prior to intrusive works. | | | | N | N |
| 45110 | ACTIVE | N | N143-00-3/706 | IMR - Station Building - Kennington Stn | Vinyl tiles | Asbestos | Known | | | | Grey marley tiles (partial) to upper walls and ceiling some loose have been removed. Possible asbestos adhesive residue present. Check with HMT prior to intrusive works. | | | | N | N |
| 18044 | ACTIVE | N | N143-00-3/706/WAL-001 | Wall: Internal - 1 - IMR - Station Building - Kennington Stn | Vinyl tiles | Asbestos | Removed | | | | All Walls - 20sqm Tiles behind Equipment Room being stripped out by NL Signals Recovery Team - Tiles removed by Edenbeck 23/10/2015 | | | | | |
| 16402 | ACTIVE | N | N143-00-3/706/WAL-007 | Wall: Internal - 7 - IMR - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Removed | | | | 10mmØ Cables Removed by others based on re-inspection October 2016 | | 3 | | | |
| 16403 | ACTIVE | N | N143-00-3/706/WAL-008 | Wall: Internal - 8 - IMR - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Removed | | | | Green Cable Removed by others based on re-inspection October 2016 | | 1 | | | |
| 11497 | ACTIVE | N | N143-00-3/711 | Relay Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18045 | ACTIVE | N | N143-00-3/711 | Relay Room - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Removed | | | | 50mmØ Cables - to Platform 1 Not visible during 2023 re-inspection | | 2 | | | |
| 44322 | ACTIVE | N | N143-00-3/711 | Relay Room - Station Building - Kennington Stn | Cable Ducts: Cement | Asbestos | Presumed | | | | Filled in cement duct - no access presumed | | | | | |
| 18046 | ACTIVE | N | N143-00-3/711 | Relay Room - Station Building - Kennington Stn | Boarding: Cement | Asbestos | Strongly Presumed | | | | Boarding High Level to Racking | | | | | |
| 45119 | ACTIVE | N | N143-00-3/711 | Relay Room - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Removed | | | | 5x braided cables in cable run to wall 3 and 4 into floor inverts. Not visible during 2023 re-inspection. | | 5 | | N | N |
| 16406 | ACTIVE | N | N143-00-3/711 | Relay Room - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Middle of Room 8no 1.5ml Tape within Electrical Equipment - Chrysotile | | 8 | | | |



Hazardous Material Asset Register - Summary



N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------------|---|------------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 16405 | ACTIVE | N | N143-00-3/711 | Relay Room - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Presumed | | | | 10mmØ Cables - to Platform 1 Not visible during 2023 re-inspection. Historic photo added. Check and remove on next survey | | 2 | | | |
| 16404 | ACTIVE | N | N143-00-3/711/ FLR-01 | Floor - 1 - Relay Room - Station Building - Kennington Stn | Vinyl tiles | Asbestos | Removed | | | | Tiles Need to check if this item has been removed to confirm. No ACM tiles visible during 2023 re-inspection. Only Quarry tiles | | | | | |
| 16407 | ACTIVE | N | N143-00-3/711/ WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Kennington Stn | Other Boarding | Asbestos | Removed | | | | Paxoline Board Need to check if this item has been removed to confirm Not present in 2023 reinspection | | | | | |
| 42060 | INACTIVE | N | N143-00-3/711/ WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Kennington Stn | PCBs | Polychlorinated biphenyl | Removed | | | | 2 x PCB's - Fair Condition Need to check if this item has been removed to confirm Removed by NLE date not Known | | 2 | | N | N |
| 16408 | ACTIVE | N | N143-00-3/711/ WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Removed | | | | Transformer Box(es) Need to check if this item has been removed to confirm. Not present during 2023 re-inspection | | 1 | | | |
| 45120 | ACTIVE | N | N143-00-3/711/ WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn | Other Boarding | Asbestos | Known | | | | 1x brown composite panel | | 1 | | N | N |
| 45121 | ACTIVE | N | N143-00-3/711/ WAL-004 | Wall: Internal - 4 - Relay Room - Station Building - Kennington Stn | Other Boarding | Asbestos | Strongly Presumed | | | | Panel boarding to high level | | | | N | N |
| 11498 | ACTIVE | N | N143-00-3/712 | Relay Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16409 | ACTIVE | N | N143-00-3/712 | Relay Room - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box (Redundant) Not inspected internally during 2023 re-inspection as no electrician present. | | 1 | | | |
| 45123 | ACTIVE | N | N143-00-3/712 | Relay Room - Station Building - Kennington Stn | Other Boarding | Asbestos | Known | | | | Brown composite panel to base of equipment | | | | N | N |
| 18824 | ACTIVE | N | N143-00-3/712 | Relay Room - Station Building - Kennington Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline Board (All Walls) | | | | | |
| 16410 | ACTIVE | N | N143-00-3/712/ WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Rectifier Box Not inspected internally during 2023 re-inspection as no electrician present. | | 1 | | | |
| 45122 | ACTIVE | N | N143-00-3/712/ WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Kennington Stn | Other Boarding | Asbestos | Known | | | | Brown composite panels on equipment | | | | N | N |
| 43287 | INACTIVE | N | N143-00-3/712/ WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Kennington Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | Wall 1 PCB's Medium Silver Cylinder Wall Mounted Fair Condition 2016 No Access - 11/01/2017 | | | | N | N |
| 45124 | ACTIVE | N | N143-00-3/712/ WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Kennington Stn | Boarding: Cement | Asbestos | Known | | | | 1x cement panel by 12 fuses | | | | N | N |



Hazardous Material Asset Register - Summary



N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 45127 | ACTIVE | N | N143-00-3/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Presumed | | | | 1no 10mmØ Cable Not visible during 2023 re-inspection. Historic photo added. Check next visit and then remove | | 1 | | N | N |
| 45126 | ACTIVE | N | N143-00-3/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Materials within transformers and electrical boxes Not inspected internally during 2023 re-inspection as no electrician present | | | | N | N |
| 45125 | INACTIVE | N | N143-00-3/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Known | | | | 1x braided cable running into invert | | 1 | | N | N |
| 18970 | ACTIVE | N | N143-00-3/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 50mmØ Cable | | 1 | | | |
| 18462 | ACTIVE | N | N143-00-3/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Removed | | | | Black Circuit Breaker Box Not visible in 2023 reinspection | | 1 | | | |
| 18047 | ACTIVE | N | N143-00-3/712/WAL-004 | Wall: Internal - 4 - Relay Room - Station Building - Kennington Stn | Boarding: Cement | Asbestos | Strongly Presumed | | | | Boarding with Electrical Fuse Equipment attached | | 1 | | | |
| 11499 | ACTIVE | N | N143-00-3/713 | Relay Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 45102 | ACTIVE | N | N143-00-3/713 | Relay Room - Station Building - Kennington Stn | Boarding: Cement | Asbestos | Known | | | | Cement panel to racking where relay box sits | | | | N | N |
| 43210 | ACTIVE | N | N143-00-3/713/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Black Rectifier Box Not inspected internally during 2023 re-inspection as no electrician present. | | | | | |
| 43211 | ACTIVE | N | N143-00-3/713/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Kennington Stn | Isolator Switches | Asbestos | Removed | | | | Switch Box 1 x 60 amp Not present within relay room. Error in records. | | | | | |
| 16411 | ACTIVE | N | N143-00-3/713/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Kennington Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | Westinghouse Brake Box - Insulation within Not inspected internally during 2023 re-inspection as no electrician present. | | 1 | | | |
| 11500 | ACTIVE | N | N143-00-3/714 | Relay Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 45128 | ACTIVE | N | N143-00-3/714 | Relay Room - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1x Rectifier Not inspected internally during 2023 re-inspection as no electrician present. | | 1 | | N | N |
| 45130 | ACTIVE | N | N143-00-3/714 | Relay Room - Station Building - Kennington Stn | Other Boarding | Asbestos | Presumed | | | | Brown composite panels to wall | | | | N | N |
| 45129 | ACTIVE | N | N143-00-3/714 | Relay Room - Station Building - Kennington Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | 2x westinghouse brake boxes to wall | | 2 | | N | N |



Hazardous Material Asset Register - Summary



N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 16412 | INACTIVE | N | N143-00-3/714/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | Westinghouse Brake Box - Insulation within | | 1 | | | |
| 11501 | ACTIVE | N | N143-00-3/715 | Relay Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 45134 | ACTIVE | N | N143-00-3/715 | Relay Room - Station Building - Kennington Stn | Westing house Boxes | Asbestos | Presumed | | | | 4x westinghouse boxes to walls Not inspected internally during 2023 re-inspection as no electrician present. | | 4 | | N | N |
| 45131 | ACTIVE | N | N143-00-3/715 | Relay Room - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Known | | | | 2x braided cables to wall | | 2 | | N | N |
| 45132 | ACTIVE | N | N143-00-3/715 | Relay Room - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Known | | | | 2x braided cables to cable run coming in through concrete duct | | 2 | | N | N |
| 45135 | ACTIVE | N | N143-00-3/715 | Relay Room - Station Building - Kennington Stn | Other Boarding | Asbestos | Sampled – Not Detected | | | | 4x brown composite panels to walls 1&3 - ID confirmed Non asbestos 4RS-JP-221112-R717851 | | 4 | | N | N |
| 53620 | INACTIVE | N | N143-00-3/715/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Kennington Stn | Westing house Boxes | Asbestos | Presumed | | | | Westinghouse Brake Box - Insulation within - Wall 1 | | | | | |
| 19485 | INACTIVE | N | N143-00-3/715/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 10mmØ Cable | | 1 | | | |
| 16413 | INACTIVE | N | N143-00-3/715/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Kennington Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | Westinghouse Brake Box - Insulation within - wall 1 to back corner of room | | 4 | | | |
| 53622 | ACTIVE | N | N143-00-3/715/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Kennington Stn | Boarding: Cement | Asbestos | Presumed | | | | Cement Panel to below capacitor back of room wall 1 (3802r) | | | | | |
| 45133 | ACTIVE | N | N143-00-3/715/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1x rectifier equipment box (black) to wall 1 Not inspected internally during 2023 as no electrician present | | 2 | | N | N |
| 53621 | ACTIVE | N | N143-00-3/715/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1x rectifier (black) and equipment box to wall 3 Not inspected internally during 2023 re-inspection as no electrician present | | | | | |
| 53623 | ACTIVE | N | N143-00-3/715/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn | Boarding: Cement | Asbestos | Surveyed – Not Detected | | | | Cement Panel to below capacitor back of room wall 3 (back of room) - confirmed on visual inspection as wood | | | | | |
| 53619 | INACTIVE | N | N143-00-3/715/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn | Westing house Boxes | Asbestos | Presumed | | | | Westinghouse Brake Box - Insulation within - Wall 3 to back | | | | | |
| 16414 | INACTIVE | N | N143-00-3/715/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | Westinghouse Brake Box - Insulation within - Wall 3 to front | | 4 | | | |



Hazardous Material Asset Register - Summary



N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 11502 | ACTIVE | N | N143-00-3/716 | Lobby - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 45137 | ACTIVE | N | N143-00-3/716 | Lobby - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1x terminal box to wall Not inspected internally during 2023 re-inspection as no electrician present. | | 1 | | N | N |
| 45138 | ACTIVE | N | N143-00-3/716 | Lobby - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1x transformer unit to wall Not visible during 2023 re-inspection. Historic photo added. Check on next site visit and remove | | 1 | | N | N |
| 45136 | ACTIVE | N | N143-00-3/716 | Lobby - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 2x orange switch boxes to wall Not inspected internally during 2023 re-inspection as no electrician present | | 2 | | N | N |
| 18108 | ACTIVE | N | N143-00-3/716 | Lobby - Station Building - Kennington Stn | Caulking | Asbestos | Known | | | | Walls - Tunnel Ring - Caulking - Chrysotile -ENCAPSUALTED | | | | | |
| 16415 | ACTIVE | N | N143-00-3/716/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Kennington Stn | Caulking | Asbestos | Known | | | | Tunnel Ring - Caulking - Chrysotile - ENCAPSUALTED | | | | | |
| 11503 | ACTIVE | N | N143-00-3/731 | CER - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16416 | ACTIVE | N | N143-00-3/731/FLR-01 | Floor - 1 - CER - Station Building - Kennington Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |
| 16417 | ACTIVE | N | N143-00-3/731/WAL-002 | Wall: Internal - 2 - CER - Station Building - Kennington Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard Panel above Door - 6x 0.05m² | | | | | |
| 11504 | ACTIVE | N | N143-00-3/791 | Passage - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18109 | ACTIVE | N | N143-00-3/791 | Passage - Station Building - Kennington Stn | Caulking | Asbestos | Known | | | | Wall - Tunnel Ring - Caulking - Chrysotile/ Amphibole ENCAPSULATED | | | | | |
| 16418 | ACTIVE | N | N143-00-3/791/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Kennington Stn | Caulking | Asbestos | Known | | | | Tunnel Ring - Caulking - Chrysotile/ Amphibole ENCAPSULATED | | | | | |
| 16419 | ACTIVE | N | N143-00-3/791/FLR-01 | Floor - 1 - Passage - Station Building - Kennington Stn | Cable Duct: Other | Asbestos | Known | | | | Floor - Cables Sleeves | | 3 | | | |
| 11505 | ACTIVE | N | N143-00-3/792 | Passage - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19417 | ACTIVE | N | N143-00-3/792 | Passage - Station Building - Kennington Stn | Caulking | Asbestos | Known | | | | Wall - Tunnel Ring - Caulking - Chrysotile/ Amphibole ENCAPSULATED | | | | | |
| 45101 | ACTIVE | N | N143-00-3/792 | Passage - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1x combination fuse switch to wall (Possible duplication) Not inspected internally during 2023 as no electrician present. | | 1 | | N | N |



Hazardous Material Asset Register - Summary



N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 16420 | ACTIVE | N | N143-00-3/792/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Kennington Stn | Caulking | Asbestos | Known | | | | Tunnel Ring - Caulking - Chrysotile/ Amphibole ENCAPSULATED | | | | | |
| 18110 | ACTIVE | N | N143-00-3/792/WAL-001 | Wall: Internal - 1 - Passage - Station Building - Kennington Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Grey Switch Box - Insulation within Not inspected internally during 2023 re-inspection as no electrician present. | | 1 | | | |
| 11506 | ACTIVE | N | N143-00-3/793 | Passage - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16421 | ACTIVE | N | N143-00-3/793 | Passage - Station Building - Kennington Stn | Caulking | Asbestos | Known | | | | Wall - Tunnel Ring - Caulking - Chrysotile/ Amphibole ENCAPSULATED | | | | | |
| 16235 | ACTIVE | N | N143-00-3/793/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Kennington Stn | Caulking | Asbestos | Known | | | | Tunnel Ring - Caulking - Chrysotile/ Amphibole ENCAPSULATED | | | | | |
| 16422 | INACTIVE | N | N143-00-3/793/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Kennington Stn | Caulking | Asbestos | Known | | | | Tunnel Ring - Caulking - Chrysotile/ Amphibole ENCAPSULATED | | | | | |
| 16423 | ACTIVE | N | N143-00-3/794 | Vent Shaft - Station Building - Kennington Stn | Caulking | Asbestos | Known | | | | Cast Iron rings at higher level. Asbestos caulking present - ENCAPSULATED | | | | | |
| 43525 | ACTIVE | N | N143-00-3/794 | Vent Shaft - Station Building - Kennington Stn | Bitumen | Asbestos | Sampled – Not Detected | | | | Vent Shaft – Bitumen Roof - Weather Proof Covering | | | R566601 | N | N |
| 11507 | ACTIVE | N | N143-00-3/796 | Passage - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16424 | ACTIVE | N | N143-00-3/796 | Passage - Station Building - Kennington Stn | Caulking | Asbestos | Known | | | | Walls and Ceiling - Tunnel Ring - Caulking - Chrysotile/ Amphibole ENCAPSULATED | | | | | |
| 11508 | ACTIVE | N | N143-00-4/201 | Passage - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19098 | ACTIVE | N | N143-00-4/201 | Passage - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11509 | ACTIVE | N | N143-00-4/202 | Passage - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16236 | ACTIVE | N | N143-00-4/202 | Passage - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11510 | ACTIVE | N | N143-00-4/203 | Passage - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16237 | ACTIVE | N | N143-00-4/203 | Passage - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 11511 | ACTIVE | N | N143-00-4/236 | Passage - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19099 | ACTIVE | N | N143-00-4/236/FLR-01 | Floor - 1 - Passage - Station Building - Kennington Stn | Cable Ducts: Bitumen | Asbestos | Presumed | | | | Bitumen Ducts - Known ducts running under floor (invert?) but no direct access from 4/236. | | 2 | | | YES |
| 43213 | ACTIVE | N | N143-00-4/236/WAL-003 | Wall: Internal - 3 - Passage - Station Building - Kennington Stn | Westing house Boxes | Asbestos | Removed | | | | Small green Westinghouse box Not present during 2023 re-inspection. | | | | | |
| 11512 | ACTIVE | N | N143-00-4/262 | Platform 2 - Southbound Local - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70212 | ACTIVE | N | N143-00-4/262 | Platform 2 - Southbound Local - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | Platform 2 Invert - Metal tunnel rings to walls, floor throughout - concrete infill, grout/wood/lead to tunnel ring flanges throughout, plastic cables, metal conduits and CMS, new firestops and mastics, new electrical equipment, terracotta, metal and plastic cable ducts, wood splinters, fibres (shuttering, panels, cut-offs) to concrete ceiling and walls throughout, | | | | | |
| 42473 | ACTIVE | N | N143-00-4/262 | Platform 2 - Southbound Local - Station Building - Kennington Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Invert - Caulking - Wood & Grout throughout within flanges to metal tunnel rings | | | R414078 | N | N |
| 42476 | ACTIVE | N | N143-00-4/262 | Platform 2 - Southbound Local - Station Building - Kennington Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Departure end (tunnel mouth) Caulking - Wood & Grout throughout within flanges to metal tunnel rings | | | R414078 | N | N |
| 42470 | INACTIVE | N | N143-00-4/262 | Platform 2 - Southbound Local - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Presumed | | | | Invert - Braided cables (green & white) throughout within j-hanger to platform and trackside walls and ceiling | | | R414078 | N | N |
| 42177 | ACTIVE | N | N143-00-4/262 | Platform 2 - Southbound Local - Station Building - Kennington Stn | Caulking | Asbestos | Known | | | | Platform Invert - Tunnel Ring Caulking - impact zone 2 While new management survey R728764 did not identify asbestos caulking, this instance previously identified must be taken into consideration for intrusive works within the invert. Consult with the HMT. | | | | N | N |
| 43375 | ACTIVE | N | N143-00-4/262 | Platform 2 - Southbound Local - Station Building - Kennington Stn | | Asbestos | Sampled – Not Detected | | | | Cable wrapping to cable in cable run (damaged), Platform 2 Invert, Kennington Station | | | R558376 | N | N |
| 70210 | ACTIVE | N | N143-00-4/262 | Platform 2 - Southbound Local - Station Building - Kennington Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform 2 Invert - 4x Bitumen cable ducts to platform wall, midway | | 4 | R728764 | N | Y |
| 45139 | ACTIVE | N | N143-00-4/262 | Platform 2 - Southbound Local - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1x tunnel telephone box to wall Historic photo added, check on next site visit if box is still present. | | 1 | | N | N |



Hazardous Material Asset Register - Summary



N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 42474 | INACTIVE | N | N143-00-4/262 | Platform 2 - Southbound Local - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Presumed | | | | Invert - Braided cables (green & white) throughout Within j-hanger to platform and trackside walls and ceiling | | | R414078 | N | N |
| 42475 | ACTIVE | N | N143-00-4/262 | Platform 2 - Southbound Local - Station Building - Kennington Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Arrivals end (tunnel mouth) - Caulking - Wood & Grout throughout within flanges to metal tunnel rings | | | R414078 | N | N |
| 42469 | INACTIVE | N | N143-00-4/262 | Platform 2 - Southbound Local - Station Building - Kennington Stn | Caulking | Asbestos | Known | | | | Invert - Caulking - Wood & Grout throughout - NOTE this is believed to be contamination from adjacent woven cable insulation - further samples to be taken | | | R414078 | N | N |
| 16240 | ACTIVE | N | N143-00-4/262 | Platform 2 - Southbound Local - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Various Cables Nr 4/711 Not visible during 2023 re-inspection. Historic photo added. Check next site visit and then remove | | | | | |
| 16241 | ACTIVE | N | N143-00-4/262 | Platform 2 - Southbound Local - Station Building - Kennington Stn | Caulking | Asbestos | Presumed | | | | Tunnel ring caulking to tunnel rings10m, 13m & 16m from head wall. No access to track | | | | | |
| 45140 | ACTIVE | N | N143-00-4/262 | Platform 2 - Southbound Local - Station Building - Kennington Stn | Westing house Boxes | Asbestos | Presumed | | | | 1x small westinghouse box to wall Historic photo added, check next site visit to see if assets still remains | | 1 | | N | N |
| 16239 | ACTIVE | N | N143-00-4/262 | Platform 2 - Southbound Local - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform Southend 10mmØ Cable - Nr 4/951 Not visible during 2023 re-inspection. Historic photo added. Check on next site visit and then remove. | | 1 | | | |
| 70206 | ACTIVE | N | N143-00-4/262 | Platform 2 - Southbound Local - Station Building - Kennington Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | Platform 2 Invert - 4x Bitumen cable ducts to arrivals end | | 4 | R728764 | N | Y |
| 16238 | INACTIVE | N | N143-00-4/262/ FLR-01 | Floor - 1 - Platform 2 - Station Building - Kennington Stn | Void | Asbestos | No Access: Presumed | | | | No Access through Manhole | | | | | |
| 18815 | INACTIVE | N | N143-00-4/262/ FLR-01 | Floor - 1 - Platform 2 - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 2 Invert 10mmØ Cable | | 1 | | | YES |
| 11513 | ACTIVE | N | N143-00-4/264 | Platform 4 - Southbound Fast - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42166 | INACTIVE | N | N143-00-4/264 | Platform 4 - Southbound Fast - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Known | | | | Invert - south end of platform no. 4 2 x Braided cables within cable ducts, to platform side-wall | | 2 | | N | N |
| 70218 | ACTIVE | N | N143-00-4/264 | Platform 4 - Southbound Fast - Station Building - Kennington Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform 4 Invert - 10x Bitumen cable ducts to cable pit - arrivals end | | 10 | R728765 | N | Y |
| 70219 | ACTIVE | N | N143-00-4/264 | Platform 4 - Southbound Fast - Station Building - Kennington Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform 4 Invert - 2x Bitumen cable ducts to cable pit - arrivals end | | 2 | R728765 | N | Y |



Hazardous Material Asset Register - Summary



N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------|--|----------------------|---------------|-------------------------|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 43377 | ACTIVE | N | N143-00-4/264 | Platform 4 - Southbound Fast - Station Building - Kennington Stn | Bitumen | Asbestos | Sampled – Not Detected | | | | Bitumen lining material to floor, Platform 4 Invert, Kennington Station | | | R558376 | N | N |
| 43376 | ACTIVE | N | N143-00-4/264 | Platform 4 - Southbound Fast - Station Building - Kennington Stn | Debris: Other | Asbestos | Sampled – Not Detected | | | | Supalux boarding debris to floor, Platform 4 Invert, Kennington Station | | | R558376 | N | N |
| 70222 | ACTIVE | N | N143-00-4/264 | Platform 4 - Southbound Fast - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | Platform 4 Invert - Metal tunnel rings to walls, floor throughout - concrete infill, grout, wood, lead to tunnel ring flanges throughout, plastic cables, metal conduits and CMS, new firestop and mastic throughout, plastic and metal pipework, wood splinters, fibres (shuttering, panels, cut-offs) to concrete ceiling and walls throughout, plastic, terracotta and metal cable ducts | | | R728765 | N | Y |
| 42454 | ACTIVE | N | N143-00-4/264 | Platform 4 - Southbound Fast - Station Building - Kennington Stn | Cable Duct: Other | Asbestos | Sampled – Not Detected | | | | Platform Invert - Cable Ducts platform side wall | | | R414081 | N | N |
| 45141 | INACTIVE | N | N143-00-4/264 | Platform 4 - Southbound Fast - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Known | | | | South end of platform no. 4 - invert (impact zone 3) Asbestos - K - 2 x braided cables within cable ducts to platform side-wall | | 2 | | N | N |
| 42457 | ACTIVE | N | N143-00-4/264 | Platform 4 - Southbound Fast - Station Building - Kennington Stn | Cable Duct: Other | Asbestos | Sampled – Not Detected | | | | Invert - Cable ducts platform side within Pit 1. | | | R414081 | N | N |
| 42456 | ACTIVE | N | N143-00-4/264 | Platform 4 - Southbound Fast - Station Building - Kennington Stn | Pipe Lagging | Asbestos | Sampled – Not Detected | | | | Invert – Loose pipe insulation, to old pipe platform side by steps | | | R414081 | N | N |
| 42455 | ACTIVE | N | N143-00-4/264 | Platform 4 - Southbound Fast - Station Building - Kennington Stn | Other Boarding | Asbestos | Sampled – Not Detected | | | | Invert – Board / Panel to Ceiling - platform side by steps | | | R414081 | N | N |
| 42452 | ACTIVE | N | N143-00-4/264 | Platform 4 - Southbound Fast - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Sampled – Not Detected | | | | Invert – Loose cable wrapping | | | R414081 | N | N |
| 70217 | ACTIVE | N | N143-00-4/264 | Platform 4 - Southbound Fast - Station Building - Kennington Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform 4 Invert - 20x Bitumen cable ducts to cable pit midway | | 20 | R728765 | N | Y |
| 42168 | ACTIVE | N | N143-00-4/264 | Platform 4 - Southbound Fast - Station Building - Kennington Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Invert - south end of platform no. 4 - Caulking throughout - within flanges to metal rings to wall and floor | | | | N | N |
| 42169 | ACTIVE | N | N143-00-4/264 | Platform 4 - Southbound Fast - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Sampled – Not Detected | | | | Invert - south end of platform no. 4 >20 Lm Loose wrapping to cable to wall - track side | 20 | | | N | N |



Hazardous Material Asset Register - Summary



N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 42453 | INACTIVE | N | N143-00-4/264 | Platform 4 - Southbound Fast - Station Building - Kennington Stn | Cable Duct: Other | Asbestos | Known | | | | Invert - Cable Ducts platform side wall. NB:Woven sheathed cables also within ducts | | | R414081 | N | N |
| 45142 | ACTIVE | N | N143-00-4/264 | Platform 4 - Southbound Fast - Station Building - Kennington Stn | Cable Duct: Other | Asbestos | Known | | | | South end of platform no. 4 - invert (impact zone 3) Asbestos - K - 2 x cable ducts to wall next to terracotta cable ducts | | 2 | | N | N |
| 42176 | ACTIVE | N | N143-00-4/264 | Platform 4 - Southbound Fast - Station Building - Kennington Stn | Lagging | Asbestos | Sampled – Not Detected | | | | Invert - south end of platform 4 <1 Lm Loose pipe insulation from old pipe of platform side wall, by stairs to invert | | 1 | | N | N |
| 42172 | ACTIVE | N | N143-00-4/264 | Platform 4 - Southbound Fast - Station Building - Kennington Stn | Cable Duct: Other | Asbestos | Sampled – Not Detected | | | | Invert - south end of platform 4. 2 x Cable Ducts to wall - braided cables side of the platform | | 2 | | N | N |
| 42165 | INACTIVE | N | N143-00-4/264 | Platform 4 - Southbound Fast - Station Building - Kennington Stn | Cable Duct: Other | Asbestos | Known | | | | Invert south end of platform no. 4 2 x Cable Ducts to wall - next to terracotta cable ducts | | 2 | | N | N |
| 42167 | ACTIVE | N | N143-00-4/264 | Platform 4 - Southbound Fast - Station Building - Kennington Stn | Cable Duct: Other | Asbestos | Sampled – Not Detected | | | | Cable pits north-end of platform no. 4 2 x Cable Ducts to platform side wall within pit no.1 | | 2 | | N | N |
| 42170 | INACTIVE | N | N143-00-4/264 | Platform 4 - Southbound Fast - Station Building - Kennington Stn | Cable Duct: Other | Asbestos | Known | | | | Invert - south end of platform 4. 2 x Cable Ducts to wall, next to terracotta cable ducts. - Inactivated - duplicate record | | 2 | | N | N |
| 42174 | ACTIVE | N | N143-00-4/264 | Platform 4 - Southbound Fast - Station Building - Kennington Stn | Other Boarding | Asbestos | Sampled – Not Detected | | | | Invert - south end of platform 4. 0.5m² Board/Panel to ceiling, by the stairs to the invert platform side | | | | N | N |
| 43378 | ACTIVE | N | N143-00-4/264 | Platform 4 - Southbound Fast - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Sampled – Not Detected | | | | Cable wrapping to cable in cable run (damaged) Platform 4 Invert, Kennington Station | | | R558376 | N | N |
| 70214 | ACTIVE | N | N143-00-4/264 | Platform 4 - Southbound Fast - Station Building - Kennington Stn | Cable: Wrap | Asbestos | Known | | | | Platform 4 Invert - Cable wrapping and woven debris to arch at departure end (1no <6M) | 6 | 1 | R728765 | N | Y |
| 70215 | ACTIVE | N | N143-00-4/264 | Platform 4 - Southbound Fast - Station Building - Kennington Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | Platform 4 Invert - Bitumen cable ducts to ceiling by access hatch at departure end | | 1 | R728765 | N | Y |
| 19100 | ACTIVE | N | N143-00-4/264/FLR-01 | Floor - 1 - Platform 4 - Station Building - Kennington Stn | Cable Ducts: Bitumen | Asbestos | Surveyed – Not Detected | | | | Bitumen Ducts; Plastic & Ceramic Ducts | | | | | YES |
| 16242 | INACTIVE | N | N143-00-4/264/FLR-01 | Floor - 1 - Platform 4 - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 4 Invert - Various Cables | | | | | YES |
| 11514 | ACTIVE | N | N143-00-4/281 | CER - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16243 | ACTIVE | N | N143-00-4/281/CLG-01 | Ceiling: Suspended - 1 - CER - Station Building - Kennington Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |



Hazardous Material Asset Register - Summary



N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 16244 | ACTIVE | N | N143-00-4/281/CLG-01 | Ceiling: Suspended - 1 - CER - Station Building - Kennington Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal above Supalux Tiles | | | | YES | |
| 45143 | ACTIVE | N | N143-00-4/281/FLR-01 | Floor - 1 - CER - Station Building - Kennington Stn | Vinyl tiles | Asbestos | Known | | | | Beige floor tiles on concrete slab to floor | | | | N | N |
| 45144 | ACTIVE | N | N143-00-4/281/FLR-01 | Floor - 1 - CER - Station Building - Kennington Stn | Bitumen | Asbestos | Known | | | | Bitumen backing and adhesive to rear of tile to floor | | | | N | N |
| 11515 | ACTIVE | N | N143-00-4/376 | Switch Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16245 | ACTIVE | N | N143-00-4/376 | Switch Room - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11516 | ACTIVE | N | N143-00-4/411 | Store - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18895 | ACTIVE | N | N143-00-4/411 | Store - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11517 | ACTIVE | N | N143-00-4/416 | Toilet: Female - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16246 | ACTIVE | N | N143-00-4/416 | Toilet: Female - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11518 | ACTIVE | N | N143-00-4/417 | Toilet: Male - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16247 | ACTIVE | N | N143-00-4/417/FLR-01 | Floor - 1 - Toilet - Station Building - Kennington Stn | Void | Asbestos | No Access: Presumed | | | | No Access through Manhole | | | | | YES |
| 11519 | ACTIVE | N | N143-00-4/661 | Pump Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19101 | ACTIVE | N | N143-00-4/661/CLG-01 | Ceiling: Solid - 1 - Pump Room - Station Building - Kennington Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding | | | | | |
| 16248 | ACTIVE | N | N143-00-4/661/CLG-01 | Ceiling: Solid - 1 - Pump Room - Station Building - Kennington Stn | Void | Asbestos | Surveyed – Not Detected | | | | Wood above false ceiling | | | | YES | |
| 11520 | ACTIVE | N | N143-00-4/662 | Switch Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 45145 | ACTIVE | N | N143-00-4/662 | Switch Room - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Removed | | | | 3no Grey Switch Boxes - Insulation within Not visible during 2023 re-inspection | | 3 | | N | N |



Hazardous Material Asset Register - Summary



N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 45146 | ACTIVE | N | N143-00-4/662/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Materials within electrical unit | | 1 | | N | N |
| 16249 | INACTIVE | N | N143-00-4/662/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Large Electrical Box | | 1 | | | |
| 19351 | ACTIVE | N | N143-00-4/662/WAL-004 | Wall: Internal - 4 - Switch Room - Station Building - Kennington Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding | | | | | |
| 11521 | ACTIVE | N | N143-00-4/663 | Switch Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19102 | ACTIVE | N | N143-00-4/663 | Switch Room - Station Building - Kennington Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux above door | | | | | |
| 11522 | ACTIVE | N | N143-00-4/664 | Switch Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42140 | ACTIVE | N | N143-00-4/664 | Switch Room - Station Building - Kennington Stn | Other Boarding | Asbestos | Removed | | | | Bakelite Panel Removed by others based on re-inspection October 2016 | | | | N | N |
| 42142 | ACTIVE | N | N143-00-4/664 | Switch Room - Station Building - Kennington Stn | Other Boarding | Asbestos | Removed | | | | Bakerlite Panel within Connector boxes Removed by others based on re-inspection October 2016 | | | | N | N |
| 42139 | ACTIVE | N | N143-00-4/664 | Switch Room - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Removed | | | | Various electrical equipment boxes Removed by others based on re-inspection October 2016 | | | | N | N |
| 20014 | ACTIVE | N | N143-00-4/664 | Switch Room - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 42141 | ACTIVE | N | N143-00-4/664 | Switch Room - Station Building - Kennington Stn | LUL Heaters | Asbestos | Removed | | | | Heater (Bakelite panel within) Removed by others based on re-inspection October 2016 | | 1 | | N | N |
| 11523 | ACTIVE | N | N143-00-4/665 | Switch Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16250 | ACTIVE | N | N143-00-4/665 | Switch Room - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11524 | ACTIVE | N | N143-00-4/666 | Switch Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16251 | ACTIVE | N | N143-00-4/666 | Switch Room - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11525 | ACTIVE | N | N143-00-4/711 | Relay Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Surveyed – Asbestos Known | | | | | | | | | |
| 18326 | ACTIVE | N | N143-00-4/711 | Relay Room - Station Building - Kennington Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Durasteel Panel | | | | | |



Hazardous Material Asset Register - Summary



N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|------------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 42077 | INACTIVE | N | N143-00-4/711 | Relay Room - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Removed | | | | 600v Box - Removed by Signals supported by Econ 19/07/2015 | | | | | |
| 42078 | ACTIVE | N | N143-00-4/711 | Relay Room - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Removed | | | | Feed Cables to 600v Box (42077 - Removed by Signals 19/07/2015) 1no Asbestos Sheathed & 1no Lead Sheathed All items Removed under Northern Line Extension Based on Re-inspection October 2016 | | | | | |
| 16253 | ACTIVE | N | N143-00-4/711 | Relay Room - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Removed | | | | Various Cables Nr Platform 2 All items Removed under Northern Line Extension Based on Re-inspection October 2016 | | | | | |
| 42440 | ACTIVE | N | N143-00-4/711 | Relay Room - Station Building - Kennington Stn | Caulking | Asbestos | Sampled – Not Detected | | | | <1m2 Caulking and Packing to tunnel rings on Platform 2 | | | R501401 | N | N |
| 42132 | ACTIVE | N | N143-00-4/711 | Relay Room - Station Building - Kennington Stn | Other Boarding | Asbestos | Sampled – Not Detected | | | | Washers to bolts throughout | | | | N | N |
| 42133 | ACTIVE | N | N143-00-4/711 | Relay Room - Station Building - Kennington Stn | Mastic | Asbestos | Sampled – Not Detected | | | | Mastic throughout - to the joints of the metal cladding | | | | N | N |
| 42136 | ACTIVE | N | N143-00-4/711 | Relay Room - Station Building - Kennington Stn | Cable: Sheath | Asbestos | Removed | | | | Woven sheath cables in various locations Removed by NLE under ES8225 | | | | N | N |
| 42137 | ACTIVE | N | N143-00-4/711 | Relay Room - Station Building - Kennington Stn | Cellactite Sheeting | Asbestos | Removed | | | | Cellactite sheeting, 50m² to the back of Wall 1 Re moved by NLE under ES8225 | 50 | | | N | N |
| 42138 | ACTIVE | N | N143-00-4/711 | Relay Room - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Removed | | | | Various electrical equipment boxes All items Removed under Northern Line Extension Based on Re-inspection October 2016 | | | | N | N |
| 16252 | ACTIVE | N | N143-00-4/711/CLG-01 | Ceiling: Solid - 1 - Relay Room - Station Building - Kennington Stn | Void | Asbestos | Removed | | | | Above false ceiling All items Removed under Northern Line Extension Based on Re-inspection October 2016 | | | | YES | |
| 42134 | ACTIVE | N | N143-00-4/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | Durasteel door - 500x 500 | | | | N | N |
| 18896 | ACTIVE | N | N143-00-4/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Removed | | | | Green Electrical Box All items Removed under Northern Line Extension Based on Re-inspection October 2016 | | 1 | | | |
| 19103 | INACTIVE | N | N143-00-4/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn | PCBs | Polychlorinated biphenyl | Removed | | | | 6 x PCB's - Fair Condition All items Removed under Northern Line Extension Based on Re-inspection October 2016 | | 6 | | N | N |
| 11526 | ACTIVE | N | N143-00-4/712 | Pump Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Strongly Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------------|--|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 45148 | ACTIVE | N | N143-00-4/712 | Pump Room - Station Building - Kennington Stn | Other Boarding | Asbestos | Presumed | | | | 1x distributon board to wall Not inspected internally during 2023 re-inspection as no electrician present. | | 1 | | N | N |
| 45149 | ACTIVE | N | N143-00-4/712 | Pump Room - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1x combination fuse switch box to wall Not inspected internally during 2023 re-inspection as no electrician present. | | 1 | | N | N |
| 45150 | ACTIVE | N | N143-00-4/712 | Pump Room - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1x transformer to wall Not inspected internally during 2023 re-inspection as no electrician present. | | 1 | | N | N |
| 45151 | ACTIVE | N | N143-00-4/712 | Pump Room - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1x pump supplies box to wall Not inspected internally during 2023 re-inspection as no electrician present. | | 1 | | N | N |
| 45147 | ACTIVE | N | N143-00-4/712 | Pump Room - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1x track loop pump box to wall by door Not inspected internally during 2023 re-inspection as no electrician present. | | 1 | | N | N |
| 16255 | ACTIVE | N | N143-00-4/712/ WAL-003 | Wall: Internal - 3 - Pump Room - Station Building - Kennington Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Grey Fuse Box - Insulation within Not inspected internally during 2023 re-inspection as no electrician present. | | 1 | | | |
| 16254 | ACTIVE | N | N143-00-4/712/ WAL-004 | Wall: Internal - 4 - Pump Room - Station Building - Kennington Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 11527 | ACTIVE | N | N143-00-4/731 | Switch Cupboard - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16256 | ACTIVE | N | N143-00-4/731 | Switch Cupboard - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 45105 | ACTIVE | N | N143-00-4/731/ WAL-002 | Wall: Internal - 2 - Switch Cupboard - Station Building - Kennington Stn | Other Electrical Boxes | Asbestos | Removed | | | | 1no Grey Fuse Box - Insulation within Not visible during 2023 re-inspection | | 1 | | N | N |
| 11528 | ACTIVE | N | N143-00-4/776 | Fan Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19104 | ACTIVE | N | N143-00-4/776 | Fan Room - Station Building - Kennington Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11529 | ACTIVE | N | N143-00-A/132 | Pump Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16258 | ACTIVE | N | N143-00-A/132 | Pump Room - Station Building - Kennington Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Durasteel 35m ² - Non Asbestos | | | | | |
| 45104 | ACTIVE | N | N143-00-A/132 | Pump Room - Station Building - Kennington Stn | Gasket :Pipework | Asbestos | Strongly Presumed | | | | Lift Motor, Gearbox and Brake Assembly - Gaskets & Rope Seal | | | | N | N |



Hazardous Material Asset Register - Summary



N143-00 - Station Building - Kennington Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|-------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 16257 | ACTIVE | N | N143-00-A/132/FLR-01 | Floor - 1 - Pump Room - Station Building - Kennington Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Durasteel 8m | | | | | |
| 11530 | ACTIVE | N | N143-00-A/133 | Pump Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16564 | ACTIVE | N | N143-00-A/133/CLG-01 | Ceiling: Suspended - 1 - Pump Room - Station Building - Kennington Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Above Supalux Ceiling | | | | | |
| 16563 | ACTIVE | N | N143-00-A/133/FLR-01 | Floor - 1 - Pump Room - Station Building - Kennington Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Metal Flooring | | | | | YES |
| 11531 | ACTIVE | N | N143-00-A/786 | Service Area - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11532 | ACTIVE | N | N143-00-B/134 | Pump Room - Station Building - Kennington Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44247 | ACTIVE | N | N143-00-B/134 | Pump Room - Station Building - Kennington Stn | Other Boarding | Asbestos | Known | | | | Fibrous panel 1x3linm fixed to wooden horizontal beams to wall by the fire exit sign and floor hatch adjacent to controller 1 within the lift motor room B/134 at Kennington Station | | | R610227 | N | N |
| 45103 | ACTIVE | N | N143-00-B/134 | Pump Room - Station Building - Kennington Stn | Rope Gaskets | Asbestos | Strongly Presumed | | | | Lift Motor, Gearbox and Brake Assembly - Gaskets & Rope Seal | | | | N | N |
| 44248 | INACTIVE | N | N143-00-B/134 | Pump Room - Station Building - Kennington Stn | Other Boarding | Asbestos | Known | | | | Fibrous panel 1x3linm fixed to wooden horizontal beams to wall by the fire exit sign and floor hatch adjacent to controller 1 within the lift motor room B/134 at Kennington Station. | | | R610227 | N | N |
| 18273 | ACTIVE | N | N143-00-B/134 | Pump Room - Station Building - Kennington Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Durasteel 35m² | | | | | |
| 16566 | ACTIVE | N | N143-00-B/134/FLR-01 | Floor - 1 - Pump Room - Station Building - Kennington Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Durasteel 8m | | | | | |
| 16341 | ACTIVE | N | N143-00/CPY-01 | Canopy - 1 - Station Building - Kennington Stn | Lead/Leading | Lead Paint/Lead | Strongly Presumed | | | | Blue Gloss Coating | | | | | |

N145-00 - Station Building - Oval Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---------------------|-------------|------------|-------------|---------------------|-------------------|
| 11533 | ACTIVE | N | N145-00-1/001 | Booking Hall - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16272 | ACTIVE | N | N145-00-1/001 | Booking Hall - Station Building - Oval Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N145-00 - Station Building - Oval Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 11534 | ACTIVE | N | N145-00-1/011 | Ticket Office - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16274 | ACTIVE | N | N145-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Oval Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18898 | ACTIVE | N | N145-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Oval Stn | Void | Asbestos | Surveyed – Not Detected | | | | W: Rendered Plaster on Brick; C: Plaster on Mesh & Concrete | | | | YES | |
| 16273 | ACTIVE | N | N145-00-1/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Oval Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete beneath wooden floor | | | | | YES |
| 11535 | ACTIVE | N | N145-00-1/021 | POM - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17948 | ACTIVE | N | N145-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Oval Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 16275 | ACTIVE | N | N145-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Oval Stn | Void | Asbestos | Surveyed – Not Detected | | | | W: Rendered Plaster on Brick; C: Concrete | | | | YES | |
| 11536 | ACTIVE | N | N145-00-1/031 | Mess Room - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16277 | ACTIVE | N | N145-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Oval Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 16276 | ACTIVE | N | N145-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Oval Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11537 | ACTIVE | N | N145-00-1/036 | Toilet: Unisex - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16278 | ACTIVE | N | N145-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Oval Stn | Void | Asbestos | Surveyed – Not Detected | | | | Breeze Block; Plaster above false ceiling | | | | YES | |
| 18816 | ACTIVE | N | N145-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Oval Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11538 | ACTIVE | N | N145-00-1/071 | Circulation Area - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17949 | ACTIVE | N | N145-00-1/071 | Circulation Area - Station Building - Oval Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | YES | |
| 11539 | ACTIVE | N | N145-00-1/081 | Lobby - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N145-00 - Station Building - Oval Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|------------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 16279 | ACTIVE | N | N145-00-1/081 | Lobby - Station Building - Oval Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | YES | |
| 11540 | ACTIVE | N | N145-00-1/083 | Lobby - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16280 | ACTIVE | N | N145-00-1/083/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Oval Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 18327 | ACTIVE | N | N145-00-1/083/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Oval Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Fibreglass Lagging above false ceiling | | | | YES | |
| 16283 | ACTIVE | N | N145-00-1/151 | UMC - Station Building - Oval Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Lid to Storage Bin | | | | YES | |
| 17951 | ACTIVE | N | N145-00-1/151 | UMC - Station Building - Oval Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Boarding above Escalators 1&2 | | | | YES | |
| 16281 | ACTIVE | N | N145-00-1/151 | UMC - Station Building - Oval Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Transformer Box(es) presumed asbestos insulating materials within | | 1 | | | |
| 16282 | ACTIVE | N | N145-00-1/151 | UMC - Station Building - Oval Stn | Lead/Leading | Lead Paint/Lead | Known | | | | UMC - Red Oil Based Paint - 2 x Girder to Housing Units. Thickness .36mm; Est Quantity 6 lm; Analysis 29.39% (not in Maximo) | | | | | |
| 17950 | ACTIVE | N | N145-00-1/151 | UMC - Station Building - Oval Stn | Lead/Leading | Lead Paint/Lead | Known | | | | UMC - Red Oil Based Paint - Pipework. Thickness .31mm; Est Quantity 20lm; Analysis 3.85% (not in Maximo) | | | | | |
| 11541 | ACTIVE | N | N145-00-1/236 | Lobby - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16284 | ACTIVE | N | N145-00-1/236/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Oval Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels | | | | | |
| 11542 | ACTIVE | N | N145-00-1/237 | Lobby - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16285 | ACTIVE | N | N145-00-1/237/FLR-01 | Floor - 1 - Lobby - Station Building - Oval Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 16286 | ACTIVE | N | N145-00-1/237/FLR-01 | Floor - 1 - Lobby - Station Building - Oval Stn | Void | Asbestos | Surveyed – Not Detected | | | | W: Rendered Plaster on Brick; C: Concrete | | | | | YES |
| 11543 | ACTIVE | N | N145-00-1/316 | Locker Room - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11544 | ACTIVE | N | N145-00-1/332 | Mess Room - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16287 | ACTIVE | N | N145-00-1/332/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Oval Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |



Hazardous Material Asset Register - Summary



N145-00 - Station Building - Oval Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 17952 | ACTIVE | N | N145-00-1/332/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Oval Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Fibreglass Lagging; Supalux Boards; No Rope Seals present in Glazing Bars above false ceiling | | | | YES | |
| 11545 | ACTIVE | N | N145-00-1/396 | SVC - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16288 | ACTIVE | N | N145-00-1/396 | SVC - Station Building - Oval Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | YES | |
| 11546 | ACTIVE | N | N145-00-1/397 | Disused Room - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16289 | ACTIVE | N | N145-00-1/397 | Disused Room - Station Building - Oval Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | YES | |
| 11547 | ACTIVE | N | N145-00-1/406 | Bin Store - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16290 | ACTIVE | N | N145-00-1/406 | Bin Store - Station Building - Oval Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | YES | |
| 11548 | ACTIVE | N | N145-00-1/407 | Store - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11549 | ACTIVE | N | N145-00-1/411 | Store - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11550 | ACTIVE | N | N145-00-1/416 | Lobby - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16291 | ACTIVE | N | N145-00-1/416/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Oval Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |
| 11551 | ACTIVE | N | N145-00-1/417 | Switch Room - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18817 | ACTIVE | N | N145-00-1/417 | Switch Room - Station Building - Oval Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | YES | |
| 11552 | ACTIVE | N | N145-00-1/419 | Shower Room - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16292 | ACTIVE | N | N145-00-1/419 | Shower Room - Station Building - Oval Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | YES | |
| 11553 | ACTIVE | N | N145-00-1/420 | Toilet: Male - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



| N145-00 - Station Building - Oval Stn | | | | | | | | | | | | | | | | |
|---------------------------------------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|-------------------------------------|-------------|------------|-------------|---------------------|-------------------|
| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
| 20015 | ACTIVE | N | N145-00-1/420 | Toilet: Male - Station Building - Oval Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | YES | |
| 11554 | ACTIVE | N | N145-00-1/421 | Toilet: Unisex - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16293 | ACTIVE | N | N145-00-1/421 | Toilet: Unisex - Station Building - Oval Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | YES | |
| 11555 | ACTIVE | N | N145-00-1/451 | Tenancy - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16294 | ACTIVE | N | N145-00-1/451 | Tenancy - Station Building - Oval Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 17953 | ACTIVE | N | N145-00-1/451/CLG-01 | Ceiling: Suspended - 1 - Tenancy - Station Building - Oval Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Tiles | | | | YES | |
| 11556 | ACTIVE | N | N145-00-1/452 | Tenancy - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16295 | ACTIVE | N | N145-00-1/452 | Tenancy - Station Building - Oval Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels | | | | | |
| 18328 | ACTIVE | N | N145-00-1/452/CLG-01 | Ceiling: Suspended - 1 - Tenancy - Station Building - Oval Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 16296 | ACTIVE | N | N145-00-1/452/CLG-01 | Ceiling: Suspended - 1 - Tenancy - Station Building - Oval Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal, Concrete above Supalux Tiles | | | | YES | |
| 11557 | ACTIVE | N | N145-00-1/551 | Yard - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16297 | ACTIVE | N | N145-00-1/551 | Yard - Station Building - Oval Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | YES | |
| 11558 | ACTIVE | N | N145-00-1/577 | Stairs: Linear - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11559 | ACTIVE | N | N145-00-1/631 | Stairs: Spiral - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16298 | ACTIVE | N | N145-00-1/631/CLG-02 | Ceiling: Solid - 2 - Spiral Stairs - Station Building - Oval Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel nr 1/791 | | | | | |
| 11560 | ACTIVE | N | N145-00-1/663 | Store - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N145-00 - Station Building - Oval Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 19352 | ACTIVE | N | N145-00-1/663/CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Oval Stn | Void | Asbestos | Surveyed – Not Detected | | | | Wood Bations & Concrete above Supalux Ceiling | | | | YES | |
| 17954 | ACTIVE | N | N145-00-1/663/CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Oval Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 11561 | ACTIVE | N | N145-00-1/665 | Switch Room - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16299 | ACTIVE | N | N145-00-1/665/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Oval Stn | Isolator Switches | Asbestos | Surveyed – Not Detected | | | | Iron Clad Isolator - Insulation within - No removal required - Non Asbestos | | 1 | | | |
| 11562 | ACTIVE | N | N145-00-1/751 | Station Control Room - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16301 | ACTIVE | N | N145-00-1/751/CLG-01 | Ceiling: Solid - 1 - Station Control Room - Station Building - Oval Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Strip | | | | YES | |
| 16300 | ACTIVE | N | N145-00-1/751/FLR-01 | Floor - 1 - Station Control Room - Station Building - Oval Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Wooden Floor | | | | | YES |
| 11563 | ACTIVE | N | N145-00-1/781 | TXR - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17955 | ACTIVE | N | N145-00-1/781 | TXR - Station Building - Oval Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed | | | | | |
| 11564 | ACTIVE | N | N145-00-1/782 | TXR - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18960 | ACTIVE | N | N145-00-1/782 | TXR - Station Building - Oval Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed | | | | | |
| 18818 | ACTIVE | N | N145-00-1/791 | Vent Shaft - Station Building - Oval Stn | Cable Ducts: Bitumen | Asbestos | Surveyed – Not Detected | | | | Bitumen Cable Sleeves | | | | | |
| 16302 | ACTIVE | N | N145-00-1/791 | Vent Shaft - Station Building - Oval Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Solid Caulking | | | | | |
| 20267 | ACTIVE | N | N145-00-1/791 | Vent Shaft - Station Building - Oval Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Report R87573 14/06/2014 - Tunnel Ring Caulking - Middle Level - NADIS | | | | N | |
| 20297 | ACTIVE | N | N145-00-1/791 | Vent Shaft - Station Building - Oval Stn | Cable Ducts: Cement | Asbestos | Sampled – Not Detected | | | | Report R87573 14/05/2014 -High level - Cement Sleeve NADIS High level - Dust/Debris to Gantry Arm NADIS | | | | N | |
| 11565 | ACTIVE | N | N145-00-1/901 | Disused Room - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16303 | ACTIVE | N | N145-00-1/901 | Disused Room - Station Building - Oval Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N145-00 - Station Building - Oval Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|----------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 11566 | ACTIVE | N | N145-00-1/TA1 | Tenancy - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16304 | ACTIVE | N | N145-00-1/TA1 | Tenancy - Station Building - Oval Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Tenancy | | | | | |
| 11567 | ACTIVE | N | N145-00-2/081 | Circulation Area - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11568 | ACTIVE | N | N145-00-2/082 | Switch Room - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16305 | ACTIVE | N | N145-00-2/161 | LMC - Station Building - Oval Stn | Caulking | Asbestos | No Access: Presumed | | | | Caulking to Ceiling - Not Surveyed | | | | | |
| 17956 | ACTIVE | N | N145-00-2/161 | LMC - Station Building - Oval Stn | Isolator Switches | Asbestos | Surveyed – Not Detected | | | | Iron Clad Isolator - No removal required - Non Asbestos | | 1 | | | |
| 16306 | ACTIVE | N | N145-00-2/161 | LMC - Station Building - Oval Stn | Lead/Leading | Lead Paint/Lead | Known | | | | LMC - Black Oil Based Paint - Girder. Thickness .48mm; Est Quantity 3lm; Analysis 1.32%. (3/161 in Maximo reported as an error) | | | | | |
| 11569 | ACTIVE | N | N145-00-2/201 | Passage - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16307 | ACTIVE | N | N145-00-2/201 | Passage - Station Building - Oval Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11570 | ACTIVE | N | N145-00-2/203 | Passage - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18961 | ACTIVE | N | N145-00-2/203 | Passage - Station Building - Oval Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11571 | ACTIVE | N | N145-00-2/236 | Lobby - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16308 | ACTIVE | N | N145-00-2/236 | Lobby - Station Building - Oval Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Walls - Supalux Panels | | | | | |
| 11572 | ACTIVE | N | N145-00-2/261 | Platform 1 - Northbound Local - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70673 | ACTIVE | N | N145-00-2/261 | Platform 1 - Northbound Local - Station Building - Oval Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | Platform Invert - Bitumen cable ducts - total 10 no - To midway wall | | 10 | R728763 | N | Y |
| 70672 | ACTIVE | N | N145-00-2/261 | Platform 1 - Northbound Local - Station Building - Oval Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | Platform Invert - Bitumen cable ducts - total 4 no - To wall, arrivals end | | 4 | R728763 | N | Y |
| 70671 | ACTIVE | N | N145-00-2/261 | Platform 1 - Northbound Local - Station Building - Oval Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | Platform Invert - Bitumen cable ducts - total 2 no - To wall, departure end | | 2 | R728763 | N | Y |



Hazardous Material Asset Register - Summary



N145-00 - Station Building - Oval Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 70669 | ACTIVE | N | N145-00-2/261 | Platform 1 - Northbound Local - Station Building - Oval Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728763 | | |
| 46459 | ACTIVE | N | N145-00-2/261 | Platform 1 - Northbound Local - Station Building - Oval Stn | Debris: Other | Asbestos | Sampled – Not Detected | | | | Dust to cables and floor (small debris pieces too) at Departure end - Throughout | | | R633826 | N | N |
| 46460 | ACTIVE | N | N145-00-2/261 | Platform 1 - Northbound Local - Station Building - Oval Stn | Debris: Other | Asbestos | Sampled – Not Detected | | | | Dust to cables and floor (small debris pieces too) at Arrival end - Throughout | | | R633826 | N | N |
| 16309 | ACTIVE | N | N145-00-2/261 | Platform 1 - Northbound Local - Station Building - Oval Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables going into Track | | 2 | | | |
| 70670 | ACTIVE | N | N145-00-2/261 | Platform 1 - Northbound Local - Station Building - Oval Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728763 | | |
| 16310 | ACTIVE | N | N145-00-2/261/ FLR-01 | Floor - 1 - Platform 1 - Station Building - Oval Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 1 Invert - 20mm Cables - Head Wall | | 2 | | | YES |
| 16311 | ACTIVE | N | N145-00-2/261/ FLR-01 | Floor - 1 - Platform 1 - Station Building - Oval Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Culking to Invert | | | | | YES |
| 11573 | ACTIVE | N | N145-00-2/291 | Store - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17957 | ACTIVE | N | N145-00-2/291 | Store - Station Building - Oval Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board (Walls) | | | | | |
| 16312 | ACTIVE | N | N145-00-2/291/ CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Oval Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board | | | | | |
| 11574 | ACTIVE | N | N145-00-2/411 | Disused Room - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18819 | ACTIVE | N | N145-00-2/411/ CLG-01 | Ceiling: Suspended - 1 - Disused Room - Station Building - Oval Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Ceiling - Non Asbestos | | | | | |
| 11575 | ACTIVE | N | N145-00-2/416 | Toilet - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11576 | ACTIVE | N | N145-00-2/601 | Stairs: Linear - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16313 | ACTIVE | N | N145-00-2/601 | Stairs: Linear - Station Building - Oval Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11577 | ACTIVE | N | N145-00-2/602 | Stairs: Linear - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16314 | ACTIVE | N | N145-00-2/602 | Stairs: Linear - Station Building - Oval Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N145-00 - Station Building - Oval Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 11578 | ACTIVE | N | N145-00-2/661 | Switch Room - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17958 | ACTIVE | N | N145-00-2/661 | Switch Room - Station Building - Oval Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11579 | ACTIVE | N | N145-00-2/662 | Switch Room - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16315 | ACTIVE | N | N145-00-2/662 | Switch Room - Station Building - Oval Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Walls - Supalux Boxing | | | | | |
| 11580 | ACTIVE | N | N145-00-2/664 | Switch Cupboard - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18329 | ACTIVE | N | N145-00-2/664/CLG-01 | Ceiling: Suspended - 1 - Switch Cupboard - Station Building - Oval Stn | Void | Asbestos | No Access: Presumed | | | | Above False Ceiling | | | | YES | |
| 18962 | ACTIVE | N | N145-00-2/664/CLG-01 | Ceiling: Suspended - 1 - Switch Cupboard - Station Building - Oval Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 11581 | ACTIVE | N | N145-00-2/665 | Switch Cupboard - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16316 | ACTIVE | N | N145-00-2/665 | Switch Cupboard - Station Building - Oval Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11582 | ACTIVE | N | N145-00-2/666 | Switch Room - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16317 | ACTIVE | N | N145-00-2/666 | Switch Room - Station Building - Oval Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11583 | ACTIVE | N | N145-00-2/711 | Relay Room - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 46286 | ACTIVE | N | N145-00-2/711 | Relay Room - Station Building - Oval Stn | Other Boarding | Asbestos | Presumed | | | | 1x Brown composite panel to racking presumed to contain asbestos | | | | | |
| 16320 | ACTIVE | N | N145-00-2/711 | Relay Room - Station Building - Oval Stn | Boarding: Cement | Asbestos | Removed | | | | Panels under PCB's. Tested and Confirmed Asbestos - Removed/ not present 2020 re-inspection. | | 4 | | | |
| 16319 | ACTIVE | N | N145-00-2/711 | Relay Room - Station Building - Oval Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables going into Inverts | | 3 | | | |
| 16321 | INACTIVE | N | N145-00-2/711 | Relay Room - Station Building - Oval Stn | Westing house Boxes | Asbestos | Removed | | | | Westinghouse Box - Removed by Signals supported by Econ 15/07/2015 | | 1 | | | |
| 19484 | INACTIVE | N | N145-00-2/711 | Relay Room - Station Building - Oval Stn | Other Electrical Boxes | Asbestos | Removed | | | | Transformer Box(es) Has been removed | | 1 | | | |



Hazardous Material Asset Register - Summary



N145-00 - Station Building - Oval Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|-------------------|--------------------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17959 | ACTIVE | N | N145-00-2/711 | Relay Room - Station Building - Oval Stn | Vinyl tiles | Asbestos | Strongly Presumed | | | | Tiles under signalling equipment - All others have been removed - Chrysotile; Concrete. Vast majority of tile removed, only those under signalling equipment remain, these can only be removed when signalling equipment is replaced | | | | | |
| 16318 | ACTIVE | N | N145-00-2/711/CLG-01 | Ceiling: Solid - 1 - Relay Room - Station Building - Oval Stn | Void | Asbestos | No Access: Presumed | | | | Above partly tiles false ceiling | | | | YES | |
| 16322 | INACTIVE | N | N145-00-2/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Oval Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | PCB's - Fair Condition Serial Nos. 186616; 186590; 178950; 186634; 186601; 186647; 186527;186333 Re inspected 14/04/2015 | | 9 | | | |
| 11584 | ACTIVE | N | N145-00-2/761 | CER - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18963 | ACTIVE | N | N145-00-2/761 | CER - Station Building - Oval Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11585 | ACTIVE | N | N145-00-2/786 | Service Riser - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16323 | ACTIVE | N | N145-00-2/786 | Service Riser - Station Building - Oval Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel above Door | | | | | |
| 11586 | ACTIVE | N | N145-00-2/787 | Service Riser - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16324 | ACTIVE | N | N145-00-2/787 | Service Riser - Station Building - Oval Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel above Door | | | | | |
| 17960 | ACTIVE | N | N145-00-2/791 | Vent Shaft - Station Building - Oval Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Top Level - Tunnel Rings - Solid Caulking; | | | | | |
| 20266 | ACTIVE | N | N145-00-2/791 | Vent Shaft - Station Building - Oval Stn | Caulking | Asbestos | Sampled – Not Detected | | | | R87573 14/05/2014 - Middle Level Tunnel Ring Caulking NADIS | | | | N | |
| 20298 | ACTIVE | N | N145-00-2/791 | Vent Shaft - Station Building - Oval Stn | Debris: Other | Asbestos | Sampled – Not Detected | | | | R87573 14/05/2014 - Middle level - Tunnel Ring Bolt Flanges NADIS. Middle level - Debris to Tunnel Rings NADIS | | | | N | N |
| 11587 | ACTIVE | N | N145-00-2/992 | Pump Room - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16325 | ACTIVE | N | N145-00-2/992 | Pump Room - Station Building - Oval Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel above Door | | | | | |
| 16326 | ACTIVE | N | N145-00-2/992/CLG-01 | Ceiling: Suspended - 1 - Plant Room - Station Building - Oval Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | False Ceiling | | | | | |



Hazardous Material Asset Register - Summary



| N145-00 - Station Building - Oval Stn | | | | | | | | | | | | | | | | |
|---------------------------------------|--------|-------------|----------------------|---|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
| 16327 | ACTIVE | N | N145-00-2/992/CLG-01 | Ceiling: Suspended - 1 - Plant Room - Station Building - Oval Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Ceiling | | | | YES | |
| 11588 | ACTIVE | N | N145-00-3/151 | UMC - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11589 | ACTIVE | N | N145-00-3/161 | LMC - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11590 | ACTIVE | N | N145-00-3/201 | Passage - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17961 | ACTIVE | N | N145-00-3/201/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Oval Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel | | | | | |
| 11591 | ACTIVE | N | N145-00-3/202 | Passage - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18964 | ACTIVE | N | N145-00-3/202/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Oval Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | YES | |
| 11592 | ACTIVE | N | N145-00-3/262 | Platform 2 - Southbound Local - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16329 | ACTIVE | N | N145-00-3/262 | Platform 2 - Southbound Local - Station Building - Oval Stn | Cable Ducts: Bitumen | Asbestos | Surveyed – Not Detected | | | | Cable Ducts | | 6 | | | |
| 70668 | ACTIVE | N | N145-00-3/262 | Platform 2 - Southbound Local - Station Building - Oval Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 20 no - To cable pit walls - departure end | | 20 | R728763 | N | Y |
| 70664 | ACTIVE | N | N145-00-3/262 | Platform 2 - Southbound Local - Station Building - Oval Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728763 | | |
| 16328 | ACTIVE | N | N145-00-3/262 | Platform 2 - Southbound Local - Station Building - Oval Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables going into Track | | 1 | | | |
| 70667 | ACTIVE | N | N145-00-3/262 | Platform 2 - Southbound Local - Station Building - Oval Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 20 no - To cable pit walls - midway | | 20 | R728763 | N | Y |
| 70665 | ACTIVE | N | N145-00-3/262 | Platform 2 - Southbound Local - Station Building - Oval Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728763 | | |
| 70666 | ACTIVE | N | N145-00-3/262 | Platform 2 - Southbound Local - Station Building - Oval Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 10 no - To mid wall | | 10 | R728763 | N | Y |
| 16330 | ACTIVE | N | N145-00-3/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Oval Stn | Cable Ducts: Bitumen | Asbestos | Surveyed – Not Detected | | | | Bitumen Ducts to concrete Plinth | | | | | YES |
| 11593 | ACTIVE | N | N145-00-3/406 | Pump Room - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N145-00 - Station Building - Oval Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|------------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 16331 | ACTIVE | N | N145-00-3/406 | Pump Room - Station Building - Oval Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Walls - Supalux | | | | | |
| 16332 | ACTIVE | N | N145-00-3/406/CLG-01 | Ceiling: Solid - 1 - Plant Room - Station Building - Oval Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board | | | | | |
| 11594 | ACTIVE | N | N145-00-3/412 | Store - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17962 | ACTIVE | N | N145-00-3/412 | Store - Station Building - Oval Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11595 | ACTIVE | N | N145-00-3/712 | Relay Room - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16333 | ACTIVE | N | N145-00-3/712 | Relay Room - Station Building - Oval Stn | Vinyl tiles | Asbestos | Strongly Presumed | | | | Tiles under signalling equipment - All others have been removed. Vast majority of tile removed only those under signalling equipment remain these can only be removed when signalling equipment is replaced | | | | | |
| 16334 | ACTIVE | N | N145-00-3/712 | Relay Room - Station Building - Oval Stn | Boarding: Cement | Asbestos | Presumed | | | | Panels under PCB's (not to be confused with the vinyl tiles that are present under/behind racking containing signalling equipment. | | | | | |
| 16335 | INACTIVE | N | N145-00-3/712 | Relay Room - Station Building - Oval Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Westinghouse boxes In twice see 17963 | | 1 | | | |
| 17963 | INACTIVE | N | N145-00-3/712 | Relay Room - Station Building - Oval Stn | Westing house Boxes | Asbestos | Removed | | | | Westinghouse Box - removed by signals supported by Econ; | | 1 | | | |
| 18820 | ACTIVE | N | N145-00-3/712 | Relay Room - Station Building - Oval Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | cables | | 3 | | | |
| 46287 | ACTIVE | N | N145-00-3/712 | Relay Room - Station Building - Oval Stn | Other Boarding | Asbestos | Presumed | | | | 7x Brown composite panels to racking. Presumed to contain asbestos | | 7 | | | |
| 16336 | INACTIVE | N | N145-00-3/712 | Relay Room - Station Building - Oval Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | 6 x PCB's - Fair Condition. Serial Nos. 186460; 186622; 186545; 186495; 186500; 186502 Re inspected 14/04/2015 | | 6 | | | |
| 11596 | ACTIVE | N | N145-00-A/331 | Mess Room - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16337 | ACTIVE | N | N145-00-A/331 | Mess Room - Station Building - Oval Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 11597 | ACTIVE | N | N145-00-A/416 | Toilet - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11598 | ACTIVE | N | N145-00-A/576 | Stairs: Linear - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N145-00 - Station Building - Oval Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|---------------------------|-------------|------------|-------------|---------------------|-------------------|
| 16338 | ACTIVE | N | N145-00-A/576 | Stairs: Linear - Station Building - Oval Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11599 | ACTIVE | N | N145-00-A/661 | Switch Cupboard - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16339 | ACTIVE | N | N145-00-A/661 | Switch Cupboard - Station Building - Oval Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Ceiling | | | | | |
| 11600 | ACTIVE | N | N145-00-A/746 | SCR - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17964 | ACTIVE | N | N145-00-A/746/FLR-01 | Floor - 1 - SCR - Station Building - Oval Stn | Void | Asbestos | Removed | | | | Beneath Computer Flooring | | | | | YES |
| 11601 | ACTIVE | N | N145-00-A/783 | CER - Station Building - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16340 | ACTIVE | N | N145-00-A/783/FLR-01 | Floor - 1 - CER - Station Building - Oval Stn | Void | Asbestos | Sampled – Not Detected | | | | Beneath Computer Flooring | | | | | |

N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 11617 | ACTIVE | N | N147-00-1/001 | Booking Hall - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18855 | ACTIVE | N | N147-00-1/001/CLG-01 | Ceiling: Suspended - 1 - Booking Hall - Station Building - Stockwell Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Above Supalux Tiles - Concrete; Fireboard around Steels; Vermiculite boxing above 1/240; Fibreglass lagging, solid below. | | | | YES | |
| 16043 | ACTIVE | N | N147-00-1/001/CLG-01 | Ceiling: Suspended - 1 - Booking Hall - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18878 | ACTIVE | N | N147-00-1/001/FLR-01 | Floor - 1 - Booking Hall - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete beneath Computer Flooring | | | | | |
| 16042 | ACTIVE | N | N147-00-1/001/FLR-01 | Floor - 1 - Booking Hall - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | 3x Floor Hatches | | 3 | | | YES |
| 11618 | ACTIVE | N | N147-00-1/011 | Ticket Office - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 16044 | ACTIVE | N | N147-00-1/011 | Ticket Office - Station Building - Stockwell Stn | LUL Heaters | Asbestos | Sampled – Not Detected | | | | Foam Insulation - Non Asbestos | | | | | |
| 16045 | ACTIVE | N | N147-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|---------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 16046 | ACTIVE | N | N147-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above Supalux Tiles - Concrete, Solid; Metal Ducting, Vermiculite Boxing over beams | | | | YES | |
| 45018 | ACTIVE | N | N147-00-1/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Stockwell Stn | Cable Ducts: Cement | Asbestos | Known | | | | Cement cable ducts within concrete floor to rear of wall 2 | | | | N | N |
| 41933 | ACTIVE | N | N147-00-1/011/WAL-003 | Wall: Internal - 3 - Ticket Office - Station Building - Stockwell Stn | | Asbestos | Sampled – Not Detected | | | | Metal and wood, 4 x to window frames | | 4 | | N | N |
| 41934 | ACTIVE | N | N147-00-1/011/WAL-003 | Wall: Internal - 3 - Ticket Office - Station Building - Stockwell Stn | | Asbestos | Sampled – Not Detected | | | | Plaster / Brickwork throughout NADIS | | | | N | N |
| 11619 | ACTIVE | N | N147-00-1/021 | POM - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16047 | ACTIVE | N | N147-00-1/021/FLR-01 | Floor - 1 - POM - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete beneath Computer Flooring | | | | | YES |
| 11620 | ACTIVE | N | N147-00-1/031 | Mess Room - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18319 | ACTIVE | N | N147-00-1/031 | Mess Room - Station Building - Stockwell Stn | LUL Heaters | Asbestos | Sampled – Not Detected | | | | Foam Insulation - Non Asbestos | | | | | |
| 16049 | ACTIVE | N | N147-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Solid; Metal Pipes & Ducts above Supalux Tiles | | | | YES | |
| 16048 | ACTIVE | N | N147-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11621 | ACTIVE | N | N147-00-1/036 | Lobby - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16050 | ACTIVE | N | N147-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Solid; Metal Vent Ducting; Solid Walls above Supalux Tiles | | | | YES | |
| 18856 | ACTIVE | N | N147-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11622 | ACTIVE | N | N147-00-1/037 | Toilet: Unisex - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11623 | ACTIVE | N | N147-00-1/047 | Kitchen - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18921 | ACTIVE | N | N147-00-1/047/CLG-01 | Ceiling: Suspended - 1 - Kitchen - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 16053 | ACTIVE | N | N147-00-1/047/CLG-01 | Ceiling: Suspended - 1 - Kitchen - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 16052 | ACTIVE | N | N147-00-1/047/CLG-01 | Ceiling: Suspended - 1 - Kitchen - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Solid Walls; Ceiling Vent Ducting above Supalux Tiles | | | | YES | |
| 16051 | ACTIVE | N | N147-00-1/047/CLG-01 | Ceiling: Suspended - 1 - Kitchen - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11624 | ACTIVE | N | N147-00-1/071 | Circulation Area - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16055 | ACTIVE | N | N147-00-1/071/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Fire board covering Steel; Vermiculite boxing; Solid walls above False Ceiling | | | | YES | |
| 16054 | ACTIVE | N | N147-00-1/071/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18879 | ACTIVE | N | N147-00-1/071/FLR-01 | Floor - 1 - Circulation Area - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | No access to Floor Hatches | | | | | YES |
| 11625 | ACTIVE | N | N147-00-1/151 | UMC - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 69910 | ACTIVE | N | N147-00-1/151 | UMC - Station Building - Stockwell Stn | Boarding: Cement | Asbestos | Known | | | | Cement shuttering to ceiling within floor vents ducts | | | R488351 | | |
| 18745 | ACTIVE | N | N147-00-1/151 | UMC - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables | | 2 | | | |
| 45019 | ACTIVE | N | N147-00-1/151 | UMC - Station Building - Stockwell Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Insulation inside busbar unit | | | R26676 | N | N |
| 18320 | ACTIVE | N | N147-00-1/151 | UMC - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cut above Flam Store 1no Redundant Cable j-hanger x 1, along Escalator 4 Incline | | 1 | | | |
| 69909 | ACTIVE | N | N147-00-1/151 | UMC - Station Building - Stockwell Stn | Boarding: Cement | Asbestos | Known | | | | Cement shuttering within floor vent duct work | | | R488351 | | |
| 42182 | ACTIVE | N | N147-00-1/151 | UMC - Station Building - Stockwell Stn | Boarding: Cement | Asbestos | Known | | | | Cement shuttering throughout to ceiling within floor vent ducts | | | R488351 | | |
| 16060 | ACTIVE | N | N147-00-1/151 | UMC - Station Building - Stockwell Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box(es) | | 1 | | | |
| 18922 | ACTIVE | N | N147-00-1/151/CLG-01 | Ceiling: Solid - 1 - UMC - Station Building - Stockwell Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | W4 Durasteel Ceiling Panel | | | | | |
| 16056 | ACTIVE | N | N147-00-1/151/FLR-01 | Floor - 1 - UMC - Station Building - Stockwell Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Lid to Storage Bin | | | | | |
| 45020 | ACTIVE | N | N147-00-1/151/WAL-001 | Wall: Internal - 1 - UMC - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Presumed | | | | Green braided cable - Within cable run by storage bunker, running perimeter wall into incline | | | | N | N |
| 45022 | ACTIVE | N | N147-00-1/151/WAL-001 | Wall: Internal - 1 - UMC - Station Building - Stockwell Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Materials within 10 core box by escalator 4 | | 10 | | N | N |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 45021 | INACTIVE | N | N147-00-1/151/WAL-004 | Wall: Internal - 4 - UMC - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Presumed | | | | Green braided cable - Within cable run by storage bunker, running perimeter wall into incline | | | | N | N |
| 16057 | ACTIVE | N | N147-00-1/151/WAL-004 | Wall: Internal - 4 - UMC - Station Building - Stockwell Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | Westinghouse Boxes - Insulation within May no longer be present | | 3 | | | |
| 18923 | ACTIVE | N | N147-00-1/151/WAL-005 | Wall: Internal - 5 - UMC - Station Building - Stockwell Stn | Gasket :Pipework | Asbestos | Strongly Presumed | | | | Gasket within ventilation shaft | | 6 | | | |
| 16058 | ACTIVE | N | N147-00-1/151/WAL-005 | Wall: Internal - 5 - UMC - Station Building - Stockwell Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | EAC Control Panel - insulation within | | 1 | | | |
| 16059 | ACTIVE | N | N147-00-1/151/WAL-006 | Wall: Internal - 6 - UMC - Station Building - Stockwell Stn | Gasket :Pipework | Asbestos | Strongly Presumed | | | | Gasket within ventilation ductwork/shaft | | 6 | | | |
| 11626 | ACTIVE | N | N147-00-1/152 | UMC - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18924 | ACTIVE | N | N147-00-1/152 | UMC - Station Building - Stockwell Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box(es) | | 1 | | | |
| 45023 | ACTIVE | N | N147-00-1/152 | UMC - Station Building - Stockwell Stn | Cable Ducts: Cement | Asbestos | Known | | | | 4no cement cable ducts to corner of walls 3 and 4 | | | | N | N |
| 16061 | ACTIVE | N | N147-00-1/152/CLG-01 | Ceiling: Solid - 1 - UMC - Station Building - Stockwell Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | W3 Durasteel Ceiling Panel - Non Asbestos | | | | | |
| 16064 | ACTIVE | N | N147-00-1/152/CLG-01 | Ceiling: Solid - 1 - UMC - Station Building - Stockwell Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | W3 Durasteel Ceiling Panel - Non Asbestos | | | | | |
| 16065 | ACTIVE | N | N147-00-1/152/CLG-01 | Ceiling: Solid - 1 - UMC - Station Building - Stockwell Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | W5 Durasteel Ceiling Panel - Non Asbestos | | | | | |
| 16062 | ACTIVE | N | N147-00-1/152/WAL-005 | Wall: Internal - 5 - UMC - Station Building - Stockwell Stn | Cable Duct: Other | Asbestos | Strongly Presumed | | | | Cable Sleeves | | 6 | | | |
| 16063 | ACTIVE | N | N147-00-1/152/WAL-006 | Wall: Internal - 6 - UMC - Station Building - Stockwell Stn | Cable Duct: Other | Asbestos | Surveyed – Not Detected | | | | Cable Sleeves | | 4 | | | |
| 16066 | ACTIVE | N | N147-00-1/171 | Escalator Incline - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 1x Redundant Cable j-hanger no 1, along Escalator 4 Incline | | | | | |
| 45025 | ACTIVE | N | N147-00-1/171 | Escalator Incline - Station Building - Stockwell Stn | Cellactite Sheeting | Asbestos | Known | | | | Cellactite - corrugated Throughout 40m visible -To walls and ceiling of incline- | | | | N | N |
| 45024 | ACTIVE | N | N147-00-1/171 | Escalator Incline - Station Building - Stockwell Stn | Caulking | Asbestos | Known | | | | Caulking - To Flanges of tunnel rings to walls - throughout | | | | N | N |
| 11627 | ACTIVE | N | N147-00-1/236 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16068 | ACTIVE | N | N147-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete / Metal Ducting / Conduits; Fibreglass lagging above Supalux Tiles | | | | YES | |
| 18925 | ACTIVE | N | N147-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 11628 | ACTIVE | N | N147-00-1/237 | Lobby - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16071 | ACTIVE | N | N147-00-1/237/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 18880 | ACTIVE | N | N147-00-1/237/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Vermiculite Panels; Fibreglass Lagging above False Ceiling | | | | YES | |
| 16069 | ACTIVE | N | N147-00-1/237/WAL-002 | Wall: Internal - 2 - Lobby - Station Building - Stockwell Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 16070 | ACTIVE | N | N147-00-1/237/WAL-003 | Wall: Internal - 3 - Lobby - Station Building - Stockwell Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 11629 | ACTIVE | N | N147-00-1/238 | Lobby - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11630 | ACTIVE | N | N147-00-1/239 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11631 | ACTIVE | N | N147-00-1/240 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16073 | ACTIVE | N | N147-00-1/240 | Passage - Station Building - Stockwell Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | YES | |
| 45026 | ACTIVE | N | N147-00-1/240 | Passage - Station Building - Stockwell Stn | LUL Heaters | Asbestos | Presumed | | | | Heater - Materials within LTB box | | | | N | N |
| 11632 | ACTIVE | N | N147-00-1/241 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18927 | ACTIVE | N | N147-00-1/241/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 16074 | ACTIVE | N | N147-00-1/241/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | Vermiculite on beams; Solid Ceiling above False Ceiling | | | | YES | |
| 11633 | ACTIVE | N | N147-00-1/242 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16075 | ACTIVE | N | N147-00-1/242/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 18746 | ACTIVE | N | N147-00-1/242/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11634 | ACTIVE | N | N147-00-1/243 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|---------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 16076 | ACTIVE | N | N147-00-1/243/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 16077 | ACTIVE | N | N147-00-1/243/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Solid. Vermiculite Boxing on Beams above False Ceiling | | | | YES | |
| 11635 | ACTIVE | N | N147-00-1/244 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 45027 | ACTIVE | N | N147-00-1/244 | Passage - Station Building - Stockwell Stn | Cable Ducts: Cement | Asbestos | Known | | | | 4no cement cable ducts - cables within - to wall 2 by steps | | 4 | | N | N |
| 16078 | ACTIVE | N | N147-00-1/244 | Passage - Station Building - Stockwell Stn | Pipe Lagging | Asbestos | Surveyed – Not Detected | | | | | | | | | |
| 16079 | ACTIVE | N | N147-00-1/244 | Passage - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 4m x 15mm Cable. 2no Cables bottom j-hanger both sides | | 2 | | | |
| 18321 | ACTIVE | N | N147-00-1/244/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Steel Clad Boarding | | | | | |
| 18928 | ACTIVE | N | N147-00-1/244/FLR-01 | Floor - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Floor Hatch x 2 | | | | | YES |
| 11636 | ACTIVE | N | N147-00-1/291 | DMT Office - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18685 | ACTIVE | N | N147-00-1/291/CLG-01 | Ceiling: Suspended - 1 - DMT Office - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Metal Pipe with Rubber; Vermiculite Boxing above Supalux Board | | | | YES | |
| 15894 | ACTIVE | N | N147-00-1/291/CLG-01 | Ceiling: Suspended - 1 - DMT Office - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board | | | | | |
| 15893 | ACTIVE | N | N147-00-1/291/FLR-01 | Floor - 1 - DMT Office - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | No Access to Floor Hatches beneath Concrete, Rubber Tiles | | | | | |
| 11637 | ACTIVE | N | N147-00-1/301 | Station Supervisor Office - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15897 | ACTIVE | N | N147-00-1/301/CLG-01 | Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Ducts; Vermiculite Boxing above Supalux Tiles | | | | YES | |
| 15896 | ACTIVE | N | N147-00-1/301/CLG-01 | Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 15895 | ACTIVE | N | N147-00-1/301/FLR-01 | Floor - 1 - Station Supervisor Office - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Floor Hatch | | | | | YES |
| 11638 | ACTIVE | N | N147-00-1/311 | Office - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 15902 | ACTIVE | N | N147-00-1/311/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal trunking; Pipework; Ducts above Supalux Tiles | | | | YES | |
| 15901 | ACTIVE | N | N147-00-1/311/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 15899 | ACTIVE | N | N147-00-1/311/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Ducting; Cable - Plastic above Supalux Tiles | | | | YES | |
| 15898 | ACTIVE | N | N147-00-1/311/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11639 | ACTIVE | N | N147-00-1/331 | Mess Room - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15900 | ACTIVE | N | N147-00-1/331/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Metal Trays; Vermiculite Lagging | | | | YES | |
| 18686 | ACTIVE | N | N147-00-1/331/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11640 | ACTIVE | N | N147-00-1/361 | Kitchen - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11641 | ACTIVE | N | N147-00-1/366 | Kitchen - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18735 | ACTIVE | N | N147-00-1/366/CLG-01 | Ceiling: Suspended - 1 - Kitchen - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Vermiculite Boxing over Beams and Fibreglass Lagging above False ceiling | | | | YES | |
| 15903 | ACTIVE | N | N147-00-1/366/CLG-01 | Ceiling: Suspended - 1 - Kitchen - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 11642 | ACTIVE | N | N147-00-1/396 | SVC - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 45028 | ACTIVE | N | N147-00-1/396 | SVC - Station Building - Stockwell Stn | Gasket :Pipework | Asbestos | Known | | | | Gasket to 4no flanges of pipework | | 4 | | N | N |
| 18801 | ACTIVE | N | N147-00-1/396/CLG-01 | Ceiling: Suspended - 1 - SVC - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board | | | | | |
| 11643 | ACTIVE | N | N147-00-1/406 | Store - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18314 | ACTIVE | N | N147-00-1/406/CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 15904 | ACTIVE | N | N147-00-1/406/CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Solid Walls; Fibreglass Debris above False Ceiling | | | | YES | |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18753 | ACTIVE | N | N147-00-1/406/FLR-01 | Floor - 1 - Store - Station Building - Stockwell Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Green Vinyl Tiles (non asbestos) | | | | | |
| 11644 | ACTIVE | N | N147-00-1/407 | Bin Store - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15906 | ACTIVE | N | N147-00-1/407 | Bin Store - Station Building - Stockwell Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Durasteel panels side of Escalator | | | | | |
| 15905 | ACTIVE | N | N147-00-1/407/CLG-01 | Ceiling: Solid - 1 - Bin Store - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels x2; Vermiculite Boxing over beams | | | | | |
| 11645 | ACTIVE | N | N147-00-1/408 | Switch Room - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18754 | ACTIVE | N | N147-00-1/408/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux | | | | YES | |
| 15907 | ACTIVE | N | N147-00-1/408/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 11646 | ACTIVE | N | N147-00-1/409 | Cleaners Room - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15908 | ACTIVE | N | N147-00-1/409 | Cleaners Room - Station Building - Stockwell Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 15909 | ACTIVE | N | N147-00-1/409/CLG-01 | Ceiling: Solid - 1 - Cleaners Room - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete Walls & Ceiling above Supalux Tiles | | | | YES | |
| 19345 | ACTIVE | N | N147-00-1/409/CLG-01 | Ceiling: Solid - 1 - Cleaners Room - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11647 | ACTIVE | N | N147-00-1/411 | Store - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18802 | ACTIVE | N | N147-00-1/411/CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 18755 | ACTIVE | N | N147-00-1/411/CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above False Ceiling - Concrete; Vermiculite Boxing; Fibreglass Lagging | | | | YES | |
| 15910 | ACTIVE | N | N147-00-1/411/FLR-01 | Floor - 1 - Store - Station Building - Stockwell Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Vinyl Tiles (non asbestos) | | | | | YES |
| 11648 | ACTIVE | N | N147-00-1/416 | Toilet: Female - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15911 | ACTIVE | N | N147-00-1/416 | Toilet: Female - Station Building - Stockwell Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Foam Insulation Board | | | | | |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 15913 | ACTIVE | N | N147-00-1/416/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Ducting above False Ceiling | | | | YES | |
| 15912 | ACTIVE | N | N147-00-1/416/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11649 | ACTIVE | N | N147-00-1/417 | Toilet: Male - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16214 | ACTIVE | N | N147-00-1/417/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Fire Board on Steels; Vermiculite over Beams beneath Supalux Tiles | | | | YES | |
| 16213 | ACTIVE | N | N147-00-1/417/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 15914 | ACTIVE | N | N147-00-1/417/FLR-01 | Floor - 1 - Toilet - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Floor Hatches - Drains Below | | | | | YES |
| 19092 | ACTIVE | N | N147-00-1/417/WAL-004 | Wall: Internal - 4 - Toilet - Station Building - Stockwell Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | LU Heater x 2 Foam Insulation Panel | | 2 | | | |
| 11650 | ACTIVE | N | N147-00-1/451 | Tenancy - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16216 | ACTIVE | N | N147-00-1/451/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Tiles | | | | YES | |
| 16215 | ACTIVE | N | N147-00-1/451/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11651 | ACTIVE | N | N147-00-1/452 | Tenancy - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16218 | ACTIVE | N | N147-00-1/452/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 16219 | ACTIVE | N | N147-00-1/452/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Fire Board on Steels; Solid Plaster Walls, Breeze Block, Metal Vent Ducts above Supalux Tiles | | | | YES | |
| 19093 | ACTIVE | N | N147-00-1/452/FLR-01 | Floor - 1 - Tenancy - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete beneath Computer Flooring | | | | | YES |
| 16217 | ACTIVE | N | N147-00-1/452/WAL-001 | Wall: Internal - 1 - Tenancy - Station Building - Stockwell Stn | Other Electrical Boxes | Asbestos | Surveyed – Not Detected | | | | Electrical Equipment | | | | YES | |
| 11652 | ACTIVE | N | N147-00-1/453 | Tenancy - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19094 | ACTIVE | N | N147-00-1/453/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Tiles | | | | YES | |
| 16220 | ACTIVE | N | N147-00-1/453/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 11653 | ACTIVE | N | N147-00-1/511 | BTP Office - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16221 | ACTIVE | N | N147-00-1/511 | BTP Office - Station Building - Stockwell Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11654 | ACTIVE | N | N147-00-1/512 | BTP Store - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16222 | ACTIVE | N | N147-00-1/512/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 16223 | ACTIVE | N | N147-00-1/512/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Tiles | | | | YES | |
| 11655 | ACTIVE | N | N147-00-1/513 | BTP Office - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18752 | ACTIVE | N | N147-00-1/513 | BTP Office - Station Building - Stockwell Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11656 | ACTIVE | N | N147-00-1/576 | Stairs: Linear - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18893 | ACTIVE | N | N147-00-1/576/WAL-004 | Wall: Internal - 4 - Linear Stairs - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels above Entrance Door | | | | | |
| 11657 | ACTIVE | N | N147-00-1/661 | Switch Room - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 45029 | ACTIVE | N | N147-00-1/661/FLR-01 | Floor - 1 - Switch Room - Station Building - Stockwell Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer to floor by wall 2 | | | | N | N |
| 16224 | ACTIVE | N | N147-00-1/661/FLR-01 | Floor - 1 - Switch Room - Station Building - Stockwell Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Red & Grey Vinyl Floor Tiles (non asbestos) | | | | | |
| 11658 | ACTIVE | N | N147-00-1/663 | Switch Room - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19095 | ACTIVE | N | N147-00-1/663/FLR-01 | Floor - 1 - Switch Room - Station Building - Stockwell Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Red & Grey Vinyl Floor Tiles (non asbestos) | | | | | |
| 16225 | ACTIVE | N | N147-00-1/663/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Stockwell Stn | Other Electrical Boxes | Asbestos | Surveyed – Not Detected | | | | Electrical Equipment | | | | YES | |
| 16226 | ACTIVE | N | N147-00-1/667 | Vent Shaft - Station Building - Stockwell Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11659 | ACTIVE | N | N147-00-1/668 | Switch Room - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18325 | ACTIVE | N | N147-00-1/668 | Switch Room - Station Building - Stockwell Stn | Cable Duct: Other | Asbestos | Strongly Presumed | | | | Cable Ducts | | | | | |
| 43252 | ACTIVE | N | N147-00-1/668/FLR-01 | Floor - 1 - Switch Room - Station Building - Stockwell Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 3 x Transformer boxes | | | | N | N |
| 19096 | ACTIVE | N | N147-00-1/668/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Stockwell Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes - Insulation within | | 6 | | | |
| 16229 | ACTIVE | N | N147-00-1/668/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Stockwell Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Trunking Insulation within | | 1 | | | |
| 16228 | ACTIVE | N | N147-00-1/668/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 11660 | ACTIVE | N | N147-00-1/669 | Switch Cupboard - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16227 | ACTIVE | N | N147-00-1/669/DOR-01 | Door - 1 - Switch Cupboard - Station Building - Stockwell Stn | Durasteel | Asbestos | Sampled – Not Detected | | | | Door for Electric Cupboard to 1/669 - Durasteel | | | | | |
| 11661 | ACTIVE | N | N147-00-1/700 | SER - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11662 | ACTIVE | N | N147-00-1/731 | CER - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16230 | ACTIVE | N | N147-00-1/731 | CER - Station Building - Stockwell Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 45030 | ACTIVE | N | N147-00-1/731 | CER - Station Building - Stockwell Stn | Other Boarding | Asbestos | Known | | | | Brown Compostie Boarding Panel | | | | N | N |
| 11663 | ACTIVE | N | N147-00-1/746 | Telephone Exchange Room - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16231 | ACTIVE | N | N147-00-1/746/CLG-01 | Ceiling: Suspended - 1 - Telephone Exchange Room - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 16232 | ACTIVE | N | N147-00-1/746/CLG-01 | Ceiling: Suspended - 1 - Telephone Exchange Room - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | Above False Ceiling | | | | YES | |
| 11664 | ACTIVE | N | N147-00-1/747 | SCR - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 45037 | ACTIVE | N | N147-00-1/747 | SCR - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Known | | | | Red braided cable - Running from electrical equipment to wall 1 and into wall 4 | | | | N | N |
| 45034 | ACTIVE | N | N147-00-1/747 | SCR - Station Building - Stockwell Stn | Other Boarding | Asbestos | Known | | | | Kitchen (On Station Layout as SCR) - Brown composite panels - To electrical equipment to wall 1 (within) | | | | N | N |



Hazardous Material Asset Register - Summary



| N147-00 - Station Building - Stockwell Stn | | | | | | | | | | | | | | | | |
|--|--------|-------------|-----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
| 45035 | ACTIVE | N | N147-00-1/747 | SCR - Station Building - Stockwell Stn | | Asbestos | Known | | | | Kitchen (On Station Layout as SCR) - Brown composite panels/washers - To metal racking throughout - some are new | | | | N | N |
| 45033 | ACTIVE | N | N147-00-1/747 | SCR - Station Building - Stockwell Stn | Bitumen | Asbestos | Known | | | | Kitchen (On Station Layout as SCR) - Bitumen adhesive/backing on concrete slab - To rear of red and grey floor tiles to floor | | | | N | N |
| 16233 | ACTIVE | N | N147-00-1/747/CLG-01 | Ceiling: Solid - 1 - SCR - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 19097 | ACTIVE | N | N147-00-1/747/CLG-01 | Ceiling: Solid - 1 - SCR - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Vermiculite Panelling; Concrete above Supalux Ceiling | | | | YES | |
| 45032 | ACTIVE | N | N147-00-1/747/FLR-01 | Floor - 1 - SCR - Station Building - Stockwell Stn | Vinyl tiles | Asbestos | Known | | | | Kitchen (On Station Layout as SCR) - Red & Grey floor tiles on concrete slab | | | | N | N |
| 18894 | ACTIVE | N | N147-00-1/747/FLR-01 | Floor - 1 - SCR - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | Floor Hatch - Drains beneath | | | | | YES |
| 45036 | ACTIVE | N | N147-00-1/747/WAL-001 | Wall: Internal - 1 - SCR - Station Building - Stockwell Stn | Other Electrical Boxes | Asbestos | Known | | | | Materials within distribution rectifier and retard boxes | | | | N | N |
| 11665 | ACTIVE | N | N147-00-1/751 | Station Control Room - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16080 | ACTIVE | N | N147-00-1/751/CLG-01 | Ceiling: Suspended - 1 - Station Control Room - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Rubber & Plastic Cables above Supalux Tiles | | | | YES | |
| 18929 | ACTIVE | N | N147-00-1/751/CLG-01 | Ceiling: Suspended - 1 - Station Control Room - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 16234 | ACTIVE | N | N147-00-1/751/FLR-01 | Floor - 1 - Station Control Room - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete beneath Computer Flooring | | | | | YES |
| 11666 | ACTIVE | N | N147-00-1/761 | Equipment Room - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16081 | ACTIVE | N | N147-00-1/761 | Equipment Room - Station Building - Stockwell Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 16082 | ACTIVE | N | N147-00-1/791 | Vent Shaft - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Low Level at Base: Tunnel Ring Caulking Seals | | | | | |
| 16083 | ACTIVE | N | N147-00-1/792 | Vent Shaft - Station Building - Stockwell Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 16271 | ACTIVE | N | N147-00-1/792 | Vent Shaft - Station Building - Stockwell Stn | Caulking | Asbestos | Known | | | | Tunnel Ring Caulking (VP68) | | | | | |
| 11667 | ACTIVE | N | N147-00-2/091 | Circulation Area - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|-------------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 18930 | ACTIVE | N | N147-00-2/091/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking - Encapsulated | | | | YES | |
| 11668 | ACTIVE | N | N147-00-2/161 | LMC - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16085 | ACTIVE | N | N147-00-2/161/CLG-01 | Ceiling: Solid - 1 - LMC - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel W2 | | | | | |
| 19955 | ACTIVE | N | N147-00-2/161/FLR-01 | Floor - 1 - LMC - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | No Access Floor Hatch x 2 | | | | | YES |
| 16086 | ACTIVE | N | N147-00-2/161/WAL-001 | Wall: Internal - 1 - LMC - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking - Encapsulated | | | | | |
| 16084 | ACTIVE | N | N147-00-2/161/WAL-002 | Wall: Internal - 2 - LMC - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 1 x Cable | | | | | |
| 11669 | ACTIVE | N | N147-00-2/201 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19349 | ACTIVE | N | N147-00-2/201 | Passage - Station Building - Stockwell Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11670 | ACTIVE | N | N147-00-2/202 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16087 | ACTIVE | N | N147-00-2/202/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking - Encapsulated | | | | YES | |
| 11671 | ACTIVE | N | N147-00-2/203 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16088 | ACTIVE | N | N147-00-2/203/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking - Encapsulated | | | | YES | |
| 18931 | ACTIVE | N | N147-00-2/203/FLR-01 | Floor - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | No Access Floor Hatch x 2 | | | | | YES |
| 11672 | ACTIVE | N | N147-00-2/204 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16089 | ACTIVE | N | N147-00-2/204/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking - Encapsulated | | | | YES | |
| 11673 | ACTIVE | N | N147-00-2/236 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16090 | ACTIVE | N | N147-00-2/236 | Passage - Station Building - Stockwell Stn | Boarding: Cement | Asbestos | Known | | | | Bricks; Join 0.01m2 - Chrysotile | | | | | |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 16091 | ACTIVE | N | N147-00-2/236/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | YES | |
| 11674 | ACTIVE | N | N147-00-2/237 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18881 | ACTIVE | N | N147-00-2/237 | Passage - Station Building - Stockwell Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11675 | ACTIVE | N | N147-00-2/577 | Stairs: Linear - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18932 | ACTIVE | N | N147-00-2/577 | Stairs: Linear - Station Building - Stockwell Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11676 | ACTIVE | N | N147-00-2/579 | Stairs: Linear - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16092 | ACTIVE | N | N147-00-2/579 | Stairs: Linear - Station Building - Stockwell Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11677 | ACTIVE | N | N147-00-2/601 | Stairs: Linear - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16094 | ACTIVE | N | N147-00-2/601/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal Corrugated Sheet | | | | YES | |
| 16093 | ACTIVE | N | N147-00-2/601/FLR-01 | Floor - 1 - Linear Stairs - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | No Access Floor Hatch x 2 | | | | | YES |
| 11678 | ACTIVE | N | N147-00-2/602 | Stairs: Linear - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18933 | ACTIVE | N | N147-00-2/602/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Part Supalux, metal corrugated sheet - no access above, metal sheets | | | | YES | |
| 11679 | ACTIVE | N | N147-00-2/603 | Stairs: Linear - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16095 | ACTIVE | N | N147-00-2/603 | Stairs: Linear - Station Building - Stockwell Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 16096 | ACTIVE | N | N147-00-2/646 | Gantry - Station Building - Stockwell Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access - leads to trackside | | | | | |
| 11680 | ACTIVE | N | N147-00-2/661 | Switch Room - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18882 | ACTIVE | N | N147-00-2/661 | Switch Room - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding | | | | | |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 11681 | ACTIVE | N | N147-00-2/662 | Switch Room - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16097 | ACTIVE | N | N147-00-2/662 | Switch Room - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding above door | | | | | |
| 11682 | ACTIVE | N | N147-00-2/711 | CER - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 45038 | ACTIVE | N | N147-00-2/711 | CER - Station Building - Stockwell Stn | Other Electrical Boxes | Asbestos | Known | | | | Transformer Box Insulation within | | | | N | N |
| 16098 | ACTIVE | N | N147-00-2/711 | CER - Station Building - Stockwell Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 45039 | ACTIVE | N | N147-00-2/711 | CER - Station Building - Stockwell Stn | Other Boarding | Asbestos | Known | | | | Brown Composite Panel | | | | N | N |
| 11683 | ACTIVE | N | N147-00-2/761 | Equipment Room - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 45031 | ACTIVE | N | N147-00-2/761 | Equipment Room - Station Building - Stockwell Stn | Caulking | Asbestos | Known | | | | Tunnel Ring Caulking to Tunnel Ring Joints | | | | N | N |
| 16099 | ACTIVE | N | N147-00-2/761 | Equipment Room - Station Building - Stockwell Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 16100 | ACTIVE | N | N147-00-2/791 | Vent Shaft - Station Building - Stockwell Stn | Gasket :Pipework | Asbestos | Sampled – Not Detected | | | | Gasket between pipe sections to fire hydrant pipework beside catwalk | | | | | |
| 45041 | ACTIVE | N | N147-00-2/791 | Vent Shaft - Station Building - Stockwell Stn | Caulking | Asbestos | Known | | | | To tunnel ring joints (no access) | | | | N | N |
| 45040 | ACTIVE | N | N147-00-2/791 | Vent Shaft - Station Building - Stockwell Stn | | Asbestos | Known | | | | Cable - To tunnel ring right hand side | | | | N | N |
| 18934 | ACTIVE | N | N147-00-2/791 | Vent Shaft - Station Building - Stockwell Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Fibrous Caulking laid into tunnel ring flange / Cement within uncapped tunnel ring flange | | | | | |
| 11684 | ACTIVE | N | N147-00-3/081 | Circulation Area - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 45042 | ACTIVE | N | N147-00-3/081 | Circulation Area - Station Building - Stockwell Stn | Cellactite Sheeting | Asbestos | Strongly Presumed | | | | Cellactite - SP - Behind metal panels to wall - limited access | | | | N | N |
| 20011 | ACTIVE | N | N147-00-3/081/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | Above False Ceiling - Metal Sheeting - No Access Above; Metal Trim | | | | YES | |
| 16101 | ACTIVE | N | N147-00-3/081/FLR-01 | Floor - 1 - Circulation Area - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Floor Hatches: Cable Shaft & Escalator Chamber beneath false floor | | | | | YES |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|---------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 16102 | ACTIVE | N | N147-00-3/081/WAL-002 | Wall: Internal - 2 - Circulation Area - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | | | | | | |
| 11685 | ACTIVE | N | N147-00-3/082 | Circulation Area - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 45043 | ACTIVE | N | N147-00-3/082 | Circulation Area - Station Building - Stockwell Stn | Cellactite Sheeting | Asbestos | Strongly Presumed | | | | Cellactite - SP - Behind metal panels to wall - limited access | | | | N | N |
| 16170 | ACTIVE | N | N147-00-3/082/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | Metal Corrugated sheets - No access above; Trunking - above Metal Sheeting False Ceiling | | | | YES | |
| 16103 | ACTIVE | N | N147-00-3/082/FLR-01 | Floor - 1 - Circulation Area - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | No Access Floor Hatch | | | | | YES |
| 11686 | ACTIVE | N | N147-00-3/161 | LMC - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16175 | ACTIVE | N | N147-00-3/161 | LMC - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 40m x 15mm Green Cable present | | 1 | | | |
| 42183 | ACTIVE | N | N147-00-3/161 | LMC - Station Building - Stockwell Stn | Boarding: Cement | Asbestos | Known | | | | Cement shuttering throughout to ceiling within vent ducts | | | R488351 | N | N |
| 16173 | ACTIVE | N | N147-00-3/161 | LMC - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boards | | | | | |
| 16174 | ACTIVE | N | N147-00-3/161 | LMC - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Lobby: Caulking in between steel tunnel rings - Encapsulated | | | | | |
| 45044 | ACTIVE | N | N147-00-3/161 | LMC - Station Building - Stockwell Stn | Caulking | Asbestos | Known | | | | Caulking to flanges of metal tunnel walls | | | | N | N |
| 16171 | ACTIVE | N | N147-00-3/161/FLR-01 | Floor - 1 - LMC - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | Floor Hatch beneath Concrete Floor | | | | | YES |
| 19016 | ACTIVE | N | N147-00-3/161/WAL-002 | Wall: Internal - 2 - LMC - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking | | | | | |
| 16172 | ACTIVE | N | N147-00-3/161/WAL-004 | Wall: Internal - 4 - LMC - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking | | | | | |
| 11687 | ACTIVE | N | N147-00-3/201 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19017 | INACTIVE | N | N147-00-3/201/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Boards | | | | YES | |
| 16176 | ACTIVE | N | N147-00-3/201/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | No Access: Presumed | | | | Supalux Boards | | | | | |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 11688 | ACTIVE | N | N147-00-3/202 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16178 | ACTIVE | N | N147-00-3/202/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Boards | | | | YES | |
| 16177 | ACTIVE | N | N147-00-3/202/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boards | | | | | |
| 11689 | ACTIVE | N | N147-00-3/203 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16179 | ACTIVE | N | N147-00-3/203/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Boards | | | | YES | |
| 18890 | ACTIVE | N | N147-00-3/203/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boards | | | | | |
| 11690 | ACTIVE | N | N147-00-3/204 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16180 | ACTIVE | N | N147-00-3/204/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boards | | | | | |
| 16181 | ACTIVE | N | N147-00-3/204/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking Encapsulated - above Supalux Board | | | | YES | |
| 19018 | ACTIVE | N | N147-00-3/204/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boards | | | | | |
| 19350 | ACTIVE | N | N147-00-3/204/FLR-01 | Floor - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | No Access Floor Hatch | | | | | YES |
| 11691 | ACTIVE | N | N147-00-3/205 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11692 | ACTIVE | N | N147-00-3/206 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16183 | ACTIVE | N | N147-00-3/206/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal Trunking / Concrete needs removing from the whole ceiling to see all of area | | | | YES | |
| 16182 | ACTIVE | N | N147-00-3/206/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boards | | | | | |
| 11693 | ACTIVE | N | N147-00-3/207 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19019 | ACTIVE | N | N147-00-3/207/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Board | | | | YES | |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18751 | ACTIVE | N | N147-00-3/207/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boards | | | | | |
| 11694 | ACTIVE | N | N147-00-3/208 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18891 | ACTIVE | N | N147-00-3/208/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal Trunking / Concrete needs removing from the whole ceiling to see all of area | | | | YES | |
| 16184 | ACTIVE | N | N147-00-3/208/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boards | | | | | |
| 11695 | ACTIVE | N | N147-00-3/209 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16185 | ACTIVE | N | N147-00-3/209 | Passage - Station Building - Stockwell Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11696 | ACTIVE | N | N147-00-3/210 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16186 | ACTIVE | N | N147-00-3/210/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 16187 | ACTIVE | N | N147-00-3/210/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 11697 | ACTIVE | N | N147-00-3/211 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19020 | ACTIVE | N | N147-00-3/211/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | YES | |
| 11698 | ACTIVE | N | N147-00-3/212 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16189 | ACTIVE | N | N147-00-3/212/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 16188 | ACTIVE | N | N147-00-3/212/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11699 | ACTIVE | N | N147-00-3/213 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16190 | ACTIVE | N | N147-00-3/213/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 16191 | ACTIVE | N | N147-00-3/213/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 11700 | ACTIVE | N | N147-00-3/214 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16192 | ACTIVE | N | N147-00-3/214/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 19021 | ACTIVE | N | N147-00-3/214/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 11701 | ACTIVE | N | N147-00-3/215 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16195 | ACTIVE | N | N147-00-3/215/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | Metal Corrugated sheet above False Ceiling - No Access above | | | | YES | |
| 16194 | ACTIVE | N | N147-00-3/215/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 16193 | ACTIVE | N | N147-00-3/215/FLR-01 | Floor - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | No Access beneath Floor Hatch | | | | | YES |
| 11702 | ACTIVE | N | N147-00-3/216 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19087 | ACTIVE | N | N147-00-3/216/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 16197 | ACTIVE | N | N147-00-3/216/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | Metal Corrugated sheet above Supalux Tiles - No Access above | | | | YES | |
| 16196 | ACTIVE | N | N147-00-3/216/FLR-01 | Floor - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | No Access beneath Floor Hatch | | | | | YES |
| 11703 | ACTIVE | N | N147-00-3/217 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16199 | ACTIVE | N | N147-00-3/217/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 16200 | ACTIVE | N | N147-00-3/217/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | Metal Corrugated sheet above Supalux Tiles - No Access above | | | | YES | |
| 16198 | ACTIVE | N | N147-00-3/217/FLR-01 | Floor - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | No Access beneath Floor Hatch | | | | | YES |
| 11704 | ACTIVE | N | N147-00-3/218 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20013 | ACTIVE | N | N147-00-3/218/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 19088 | ACTIVE | N | N147-00-3/218/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 11705 | ACTIVE | N | N147-00-3/219 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16202 | ACTIVE | N | N147-00-3/219/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 16201 | ACTIVE | N | N147-00-3/219/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11706 | ACTIVE | N | N147-00-3/236 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16203 | ACTIVE | N | N147-00-3/236/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking - Encapsulated | | | | | |
| 18324 | ACTIVE | N | N147-00-3/236/WAL-001 | Wall: Internal - 1 - Passage - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | All Walls - Tunnel Ring Caulking - Encapsulated | | | | | |
| 11707 | ACTIVE | N | N147-00-3/237 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19956 | ACTIVE | N | N147-00-3/237 | Passage - Station Building - Stockwell Stn | Cable Duct: Other | Asbestos | Strongly Presumed | | | | Cable Ducts | | | | | |
| 16205 | ACTIVE | N | N147-00-3/237 | Passage - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking Halfway to 3/236 Partly Encapsulated | | | | | |
| 45045 | ACTIVE | N | N147-00-3/237 | Passage - Station Building - Stockwell Stn | Caulking | Asbestos | Known | | | | Tunnel Ring Caulking To Tunnel Ring Joints Throughout | | | | N | N |
| 16206 | ACTIVE | N | N147-00-3/237 | Passage - Station Building - Stockwell Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Dark brown coloured paint applied to the floodgate. Analysis 13.5% | | | | | |
| 19089 | ACTIVE | N | N147-00-3/237/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking - Encapsulated | | | | | |
| 16204 | ACTIVE | N | N147-00-3/237/WAL-001 | Wall: Internal - 1 - Passage - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | All Walls - Tunnel Ring Caulking - Encapsulated | | | | | |
| 11708 | ACTIVE | N | N147-00-3/238 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16208 | ACTIVE | N | N147-00-3/238/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking - Chrysotile & Amphibole | | | | | |
| 16207 | ACTIVE | N | N147-00-3/238/WAL-001 | Wall: Internal - 1 - Passage - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking - Chrysotile & Amphibole | | | | | |
| 18892 | ACTIVE | N | N147-00-3/238/WAL-002 | Wall: Internal - 2 - Passage - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking - Chrysotile & Amphibole | | | | | |
| 11709 | ACTIVE | N | N147-00-3/239 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 16209 | ACTIVE | N | N147-00-3/239 | Passage - Station Building - Stockwell Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes - Insulation within | | 2 | | | |
| 19090 | ACTIVE | N | N147-00-3/239 | Passage - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cut Cables on top of Switch Boxes | | | | | |
| 16210 | ACTIVE | N | N147-00-3/239 | Passage - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables | | | | | |
| 11710 | ACTIVE | N | N147-00-3/240 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18747 | ACTIVE | N | N147-00-3/240 | Passage - Station Building - Stockwell Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes - Insulation within | | 2 | | | |
| 16106 | ACTIVE | N | N147-00-3/240 | Passage - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables | | | | | |
| 16105 | ACTIVE | N | N147-00-3/240 | Passage - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cut Cables on top of Switch Boxes | | | | | |
| 16104 | ACTIVE | N | N147-00-3/240/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking - Type 3 Confirmed as Non Asbestos | | | | | |
| 16211 | ACTIVE | N | N147-00-3/240/WAL-001 | Wall: Internal - 1 - Passage - Station Building - Stockwell Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Tunnel Ring Caulking - Type 3 Confirmed as Non Asbestos | | | | | |
| 16212 | ACTIVE | N | N147-00-3/240/WAL-002 | Wall: Internal - 2 - Passage - Station Building - Stockwell Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Tunnel Ring Caulking - Type 3 Confirmed as Non Asbestos | | | | | |
| 19091 | ACTIVE | N | N147-00-3/240/WAL-003 | Wall: Internal - 3 - Passage - Station Building - Stockwell Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Tunnel Ring Caulking - Type 3 Confirmed as Non Asbestos | | | | | |
| 11711 | ACTIVE | N | N147-00-3/241 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16109 | ACTIVE | N | N147-00-3/241/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking - Encapsulated above False Ceiling | | | | YES | |
| 16108 | ACTIVE | N | N147-00-3/241/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 16107 | ACTIVE | N | N147-00-3/241/FLR-01 | Floor - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | No Access Floor Hatch below false floor | | | | | |
| 18935 | ACTIVE | N | N147-00-3/241/WAL-004 | Wall: Internal - 4 - Passage - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board above door | | | | | |
| 11712 | ACTIVE | N | N147-00-3/242 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18936 | ACTIVE | N | N147-00-3/242/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 16112 | ACTIVE | N | N147-00-3/242/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Tunnel Ring Caulking - Type 3 Confirmed as Non Asbestos | | | | YES | |
| 16110 | ACTIVE | N | N147-00-3/242/FLR-01 | Floor - 1 - Passage - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Floor Hatch - Metal to Cable Shaft beneath Concrete floor | | | | | |
| 16111 | ACTIVE | N | N147-00-3/242/WAL-004 | Wall: Internal - 4 - Passage - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel to door | | | | | |
| 11713 | ACTIVE | N | N147-00-3/243 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16114 | ACTIVE | N | N147-00-3/243/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn | Caulking | Asbestos | Known | | | | Tunnel Ring Caulking - Chrysotile & Amphibole - Encapsulated | | | | | |
| 16113 | ACTIVE | N | N147-00-3/243/WAL-001 | Wall: Internal - 1 - Passage - Station Building - Stockwell Stn | Caulking | Asbestos | Known | | | | All Walls - Tunnel Ring Caulking - Chrysotile & Amphibole - Encapsulated | | | | | |
| 11714 | ACTIVE | N | N147-00-3/261 | Platform 1 - Northbound Local - Victoria Line - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 45046 | ACTIVE | N | N147-00-3/261 | Platform 1 - Northbound Local - Victoria Line - Station Building - Stockwell Stn | Cellactite Sheeting | Asbestos | Known | | | | Cellactite at high level throughout NOTE limited access to metal panels, no access to cellactite at high level | | | | N | N |
| 70609 | ACTIVE | N | N147-00-3/261 | Platform 1 - Northbound Local - Victoria Line - Station Building - Stockwell Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 6 no - To trackside wall arrivals end | | 6 | R728761 | N | Y |
| 18937 | ACTIVE | N | N147-00-3/261 | Platform 1 - Northbound Local - Victoria Line - Station Building - Stockwell Stn | Cellactite Sheeting | Asbestos | Known | | | | Asbestos ID - Confirmed as Asbestos - Chrysotile - near 3/712 | | | | | |
| 70607 | ACTIVE | N | N147-00-3/261 | Platform 1 - Northbound Local - Victoria Line - Station Building - Stockwell Stn | | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728761 | N | Y |
| 70610 | ACTIVE | N | N147-00-3/261 | Platform 1 - Northbound Local - Victoria Line - Station Building - Stockwell Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - 18 no throughout - To J Hangers | | 18 | R728761 | | |
| 70612 | ACTIVE | N | N147-00-3/261 | Platform 1 - Northbound Local - Victoria Line - Station Building - Stockwell Stn | Tunnel Ring Caulking | Asbestos | Known | | | | Platform Invert - Caulking - Throughout - To tunnel rings flanges throughout | | | R728761 | | |
| 70614 | ACTIVE | N | N147-00-3/261 | Platform 1 - Northbound Local - Victoria Line - Station Building - Stockwell Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 10 no - To dividing wall | | 10 | R728761 | N | Y |
| 70619 | ACTIVE | N | N147-00-3/261 | Platform 1 - Northbound Local - Victoria Line - Station Building - Stockwell Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 x 10 no - | | 20 | R728761 | N | Y |
| 70620 | ACTIVE | N | N147-00-3/261 | Platform 1 - Northbound Local - Victoria Line - Station Building - Stockwell Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 x 10 no | | 20 | R728761 | N | Y |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 70605 | ACTIVE | N | N147-00-3/261 | Platform 1 - Northbound Local - Victoria Line - Station Building - Stockwell Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728761 | | |
| 16115 | ACTIVE | N | N147-00-3/261/CLG-01 | Ceiling: Solid - 1 - Platform 1 - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Sealed Tunnel Rings above Metal Sheeting | | | | YES | |
| 16117 | ACTIVE | N | N147-00-3/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Known | | | | Platform 1 Invert - 23 x various Cables | | | | | YES |
| 16116 | ACTIVE | N | N147-00-3/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Stockwell Stn | Cable Duct: Other | Asbestos | Known | | | | Platform 1 Invert - 39 x various Cable Sleeves - Chrysotile & Amphibole | | | | | YES |
| 11715 | ACTIVE | N | N147-00-3/262 | Platform 2 - Northbound Local - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 45047 | ACTIVE | N | N147-00-3/262 | Platform 2 - Northbound Local - Station Building - Stockwell Stn | Cellactite Sheeting | Asbestos | Strongly Presumed | | | | Cellactite at high level throughout | | | | N | N |
| 16119 | ACTIVE | N | N147-00-3/262 | Platform 2 - Northbound Local - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 2cm Cable - Tailwall | | 1 | | | |
| 70622 | ACTIVE | N | N147-00-3/262 | Platform 2 - Northbound Local - Station Building - Stockwell Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728761 | | |
| 70630 | ACTIVE | N | N147-00-3/262 | Platform 2 - Northbound Local - Station Building - Stockwell Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 x 10 no - To platform wall, midway | | 20 | R728761 | N | Y |
| 70629 | ACTIVE | N | N147-00-3/262 | Platform 2 - Northbound Local - Station Building - Stockwell Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 10 no - To platform wall, midway | | 10 | R728761 | N | Y |
| 70628 | ACTIVE | N | N147-00-3/262 | Platform 2 - Northbound Local - Station Building - Stockwell Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Materials within 10 core box - total 1 no - To trackside wall | | 1 | R728761 | | |
| 18883 | ACTIVE | N | N147-00-3/262 | Platform 2 - Northbound Local - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 30mm Diameter Cable - near 3/713 | | 1 | | | |
| 18938 | ACTIVE | N | N147-00-3/262 | Platform 2 - Northbound Local - Station Building - Stockwell Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Box - Tailwall | | 1 | | | |
| 45049 | ACTIVE | N | N147-00-3/262 | Platform 2 - Northbound Local - Station Building - Stockwell Stn | Cable Ducts: Cement | Asbestos | Strongly Presumed | | | | Platform 2 Invert - 10no cable sleeves near 2/601 | | 10 | | N | N |
| 45048 | ACTIVE | N | N147-00-3/262 | Platform 2 - Northbound Local - Station Building - Stockwell Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform 2 Invert - 18no cable sleeves - Platform 2 Northbound invert 8m and 20m on from 2/601 | | 18 | | N | N |
| 16120 | INACTIVE | N | N147-00-3/262 | Platform 2 - Northbound Local - Station Building - Stockwell Stn | Westing house Boxes | Asbestos | Presumed | | | | Insulation within Westinghouse Box (trackside) | | 1 | | | |
| 19483 | ACTIVE | N | N147-00-3/262 | Platform 2 - Northbound Local - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 15mm Diameter Cable - near 3/713 | | 1 | | | |
| 16121 | ACTIVE | N | N147-00-3/262 | Platform 2 - Northbound Local - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 15mm Cables | | 4 | | | |
| 70621 | ACTIVE | N | N147-00-3/262 | Platform 2 - Northbound Local - Station Building - Stockwell Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728761 | | |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 70624 | ACTIVE | N | N147-00-3/262 | Platform 2 - Northbound Local - Station Building - Stockwell Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 4 no - To trackside wall arrivals end | | 4 | R728761 | N | Y |
| 70625 | ACTIVE | N | N147-00-3/262 | Platform 2 - Northbound Local - Station Building - Stockwell Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - total 12 no throughout - To j Hangers throughout | | 12 | R728761 | | |
| 70631 | ACTIVE | N | N147-00-3/262 | Platform 2 - Northbound Local - Station Building - Stockwell Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 5 no - To trackside wall departure end | | 5 | R728761 | N | Y |
| 70626 | ACTIVE | N | N147-00-3/262 | Platform 2 - Northbound Local - Station Building - Stockwell Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 no - To trackside wall in arch arrivals end | | 2 | R728761 | N | Y |
| 16118 | ACTIVE | N | N147-00-3/262/CLG-01 | Ceiling: Solid - 1 - Platform 2 - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Sealed Tunnel Rings above Metal Sheeting | | | | YES | |
| 18748 | ACTIVE | N | N147-00-3/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 2 Invert - Various Cables | | | | | YES |
| 11716 | ACTIVE | N | N147-00-3/263 | Platform 3 - Southbound Local - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70644 | ACTIVE | N | N147-00-3/263 | Platform 3 - Southbound Local - Station Building - Stockwell Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 3 no - To trackside wall departure end | | 3 | R728762 | N | Y |
| 70646 | ACTIVE | N | N147-00-3/263 | Platform 3 - Southbound Local - Station Building - Stockwell Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - total >4 no Throughout - To J Hangers throughout | | 4 | R728762 | | |
| 70649 | ACTIVE | N | N147-00-3/263 | Platform 3 - Southbound Local - Station Building - Stockwell Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | Platform Invert - Bitumen cable ducts - total 16 no - To trackside head wall arrivals end | | 16 | R728762 | N | Y |
| 45050 | ACTIVE | N | N147-00-3/263 | Platform 3 - Southbound Local - Station Building - Stockwell Stn | Other Boarding | Asbestos | Strongly Presumed | | | | Cellactite behind panels to wall | | | | N | N |
| 70645 | ACTIVE | N | N147-00-3/263 | Platform 3 - Southbound Local - Station Building - Stockwell Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 x 10 no - To platform side wall - midway | | 20 | R728762 | N | Y |
| 16122 | ACTIVE | N | N147-00-3/263 | Platform 3 - Southbound Local - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables Trackside | | 6 | | | |
| 70642 | ACTIVE | N | N147-00-3/263 | Platform 3 - Southbound Local - Station Building - Stockwell Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728762 | | |
| 70640 | ACTIVE | N | N147-00-3/263 | Platform 3 - Southbound Local - Station Building - Stockwell Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728762 | | |
| 70647 | ACTIVE | N | N147-00-3/263 | Platform 3 - Southbound Local - Station Building - Stockwell Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 4 no -To platform side wall - midway | | 4 | R728762 | N | Y |
| 16123 | ACTIVE | N | N147-00-3/263 | Platform 3 - Southbound Local - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cable - Trackside Tail Wall Tunnel mouth | | 1 | | | |
| 18939 | ACTIVE | N | N147-00-3/263/CLG-01 | Ceiling: Solid - 1 - Platform 3 - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Sealed Tunnel Rings above Metal Sheeting | | | | | |
| 18884 | ACTIVE | N | N147-00-3/263/FLR-01 | Floor - 1 - Platform 3 - Station Building - Stockwell Stn | Cable Duct: Other | Asbestos | Strongly Presumed | | | | Platform 3 Invert - Cable Sleeves, 23no No Access | | 27 | | | YES |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 16124 | ACTIVE | N | N147-00-3/263/FLR-01 | Floor - 1 - Platform 3 - Station Building - Stockwell Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform 3 Invert - Cable Sleeves - Chrysotile | | 24 | | | YES |
| 16125 | ACTIVE | N | N147-00-3/263/FLR-01 | Floor - 1 - Platform 3 - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 3 Invert - Various Cables | | 6 | | | YES |
| 11717 | ACTIVE | N | N147-00-3/264 | Platform 4 - Southbound Local - Victoria Line - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70656 | ACTIVE | N | N147-00-3/264 | Platform 4 - Southbound Local - Victoria Line - Station Building - Stockwell Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 12 no - To dividing wall midway | | 12 | R728762 | N | Y |
| 45052 | ACTIVE | N | N147-00-3/264 | Platform 4 - Southbound Local - Victoria Line - Station Building - Stockwell Stn | Other Boarding | Asbestos | Strongly Presumed | | | | Boarding in Tunnel near 3/714 - No Access | | | | N | N |
| 16126 | ACTIVE | N | N147-00-3/264 | Platform 4 - Southbound Local - Victoria Line - Station Building - Stockwell Stn | Other Boarding | Asbestos | No Access: Presumed | | | | Boarding in Tunnel near 3/714 | | | | | |
| 70661 | ACTIVE | N | N147-00-3/264 | Platform 4 - Southbound Local - Victoria Line - Station Building - Stockwell Stn | Tunnel Ring Caulking | Asbestos | Known | | | | Platform Invert - Caulking - Throughout - To tunnel rings flanges throughout | | | R728762 | | |
| 70658 | ACTIVE | N | N147-00-3/264 | Platform 4 - Southbound Local - Victoria Line - Station Building - Stockwell Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Materials within small Westinghouse box - total 1 no - To trackside wall departure end | | 1 | R728762 | | |
| 45051 | ACTIVE | N | N147-00-3/264 | Platform 4 - Southbound Local - Victoria Line - Station Building - Stockwell Stn | Cellactite Sheeting | Asbestos | Strongly Presumed | | | | Cellactite behind panels to wall | | | | N | N |
| 70650 | ACTIVE | N | N147-00-3/264 | Platform 4 - Southbound Local - Victoria Line - Station Building - Stockwell Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728762 | | |
| 70651 | ACTIVE | N | N147-00-3/264 | Platform 4 - Southbound Local - Victoria Line - Station Building - Stockwell Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728762 | | |
| 70652 | ACTIVE | N | N147-00-3/264 | Platform 4 - Southbound Local - Victoria Line - Station Building - Stockwell Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 4 no - To trackside wall arrivals end | | 4 | R728762 | N | Y |
| 70654 | ACTIVE | N | N147-00-3/264 | Platform 4 - Southbound Local - Victoria Line - Station Building - Stockwell Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - total 18 no throughout - To J Hangers throughout | | 18 | R728762 | | |
| 70655 | ACTIVE | N | N147-00-3/264 | Platform 4 - Southbound Local - Victoria Line - Station Building - Stockwell Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 x 12 no - To dividing wall | | 24 | R728762 | N | Y |
| 70657 | ACTIVE | N | N147-00-3/264 | Platform 4 - Southbound Local - Victoria Line - Station Building - Stockwell Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 6 no - To trackside wall departure end | | 6 | R728762 | N | Y |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|---------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 19003 | ACTIVE | N | N147-00-3/264/CLG-01 | Ceiling: Solid - 1 - Platform 4 - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Sealed Tunnel Rings above Metal Sheeting | | | | YES | |
| 16128 | ACTIVE | N | N147-00-3/264/FLR-01 | Floor - 1 - Platform 4 - Station Building - Stockwell Stn | Cable Duct: Other | Asbestos | Strongly Presumed | | | | Platform 4 Invert - Various Cable Sleeves x 42. 10 x Filled in - No Access | | 42 | | YES | |
| 16127 | ACTIVE | N | N147-00-3/264/FLR-01 | Floor - 1 - Platform 4 - Station Building - Stockwell Stn | Cable Duct: Other | Asbestos | Known | | | | Platform 4 Invert - Various Cable Sleeves - 20 x Chrysotile | | 20 | | YES | |
| 18322 | ACTIVE | N | N147-00-3/264/FLR-01 | Floor - 1 - Platform 4 - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 4 Invert - Various Cables | | 33 | | YES | |
| 11718 | ACTIVE | N | N147-00-3/381 | Store - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16129 | ACTIVE | N | N147-00-3/381/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Stockwell Stn | Cellactite Sheeting | Asbestos | Strongly Presumed | | | | Bituminous Corrugated Sheeting | | | | | |
| 11719 | ACTIVE | N | N147-00-3/382 | Store - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16130 | ACTIVE | N | N147-00-3/382/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 18885 | ACTIVE | N | N147-00-3/382/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking | | | | YES | |
| 18749 | ACTIVE | N | N147-00-3/382/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Stockwell Stn | Cellactite Sheeting | Asbestos | Known | | | | Bituminous Corrugated Sheeting in Ceiling - Chrysotile | | | | | |
| 11720 | ACTIVE | N | N147-00-3/407 | Plant Room - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16131 | ACTIVE | N | N147-00-3/407/CLG-01 | Ceiling: Suspended - 1 - Cleaners Room - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board | | | | | |
| 16132 | ACTIVE | N | N147-00-3/407/CLG-01 | Ceiling: Suspended - 1 - Cleaners Room - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking | | | | YES | |
| 19004 | ACTIVE | N | N147-00-3/407/FLR-01 | Floor - 1 - Cleaners Room - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Floor Hatch - Drain Gully beneath Quarry Tiles | | | | | |
| 11721 | ACTIVE | N | N147-00-3/408 | Mess Room - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16133 | ACTIVE | N | N147-00-3/408/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board | | | | | |
| 16134 | ACTIVE | N | N147-00-3/408/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking Encapsulated | | | | YES | |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 11722 | ACTIVE | N | N147-00-3/409 | Disused Room - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 45053 | ACTIVE | N | N147-00-3/409 | Disused Room - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel ring caulking to tunnel ring above false ceiling | | | | N | N |
| 19005 | ACTIVE | N | N147-00-3/409/CLG-01 | Ceiling: Suspended - 1 - Disused Room - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 16135 | ACTIVE | N | N147-00-3/409/CLG-01 | Ceiling: Suspended - 1 - Disused Room - Station Building - Stockwell Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring Caulking - Type 3 Confirmed as Non Asbestos | | | | YES | |
| 11723 | ACTIVE | N | N147-00-3/410 | Cleaners Room - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 45054 | ACTIVE | N | N147-00-3/410 | Cleaners Room - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel caulking above false ceiling | | | | N | N |
| 16136 | ACTIVE | N | N147-00-3/410/CLG-01 | Ceiling: Suspended - 1 - Cleaners Room - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 16137 | ACTIVE | N | N147-00-3/410/CLG-01 | Ceiling: Suspended - 1 - Cleaners Room - Station Building - Stockwell Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring Caulking - Type 3 Confirmed as Non Asbestos | | | | YES | |
| 11724 | ACTIVE | N | N147-00-3/411 | LMC - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16138 | ACTIVE | N | N147-00-3/411 | LMC - Station Building - Stockwell Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11725 | ACTIVE | N | N147-00-3/581 | Stairs: Linear - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19006 | ACTIVE | N | N147-00-3/581 | Stairs: Linear - Station Building - Stockwell Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11726 | ACTIVE | N | N147-00-3/662 | Switch Room - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 45055 | ACTIVE | N | N147-00-3/662 | Switch Room - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel ring caulking throughout | | | | N | N |
| 18886 | ACTIVE | N | N147-00-3/662/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 16139 | ACTIVE | N | N147-00-3/662/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Ceiling | | | | YES | |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 11727 | ACTIVE | N | N147-00-3/663 | Switch Room - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16145 | ACTIVE | N | N147-00-3/663 | Switch Room - Station Building - Stockwell Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box(es) | | 3 | | | |
| 45056 | ACTIVE | N | N147-00-3/663 | Switch Room - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | | | | | N | N |
| 16143 | ACTIVE | N | N147-00-3/663/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Board | | | | YES | |
| 16141 | ACTIVE | N | N147-00-3/663/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board | | | | | |
| 16140 | ACTIVE | N | N147-00-3/663/FLR-01 | Floor - 1 - Switch Room - Station Building - Stockwell Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Red Vinyl - Non Asbestos | | | | | |
| 19008 | ACTIVE | N | N147-00-3/663/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables | | 2 | | | |
| 16142 | ACTIVE | N | N147-00-3/663/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Stockwell Stn | Other Electrical Boxes | Asbestos | Surveyed – Not Detected | | | | Electrical Equipment | | | | | |
| 16144 | ACTIVE | N | N147-00-3/663/WAL-005 | Wall: Internal - 5 - Switch Room - Station Building - Stockwell Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Box Insulation within | | 1 | | | |
| 19007 | ACTIVE | N | N147-00-3/663/WAL-006 | Wall: Internal - 6 - Switch Room - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel above entrance | | | | | |
| 11728 | ACTIVE | N | N147-00-3/664 | Switch Cupboard - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19009 | ACTIVE | N | N147-00-3/664 | Switch Cupboard - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | New Build Formerly part of 3/238 - therefore Tunnel Ring Caulking - Encapsulated | | | | | |
| 45057 | ACTIVE | N | N147-00-3/664 | Switch Cupboard - Station Building - Stockwell Stn | Caulking | Asbestos | Known | | | | Tunnel ring caulking to tunnel ring joints on walls and ceiling | | | | N | N |
| 11729 | ACTIVE | N | N147-00-3/711 | Relay Room - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16147 | ACTIVE | N | N147-00-3/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables | | 2 | | | |
| 16148 | ACTIVE | N | N147-00-3/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables | | 31 | | | |
| 16146 | ACTIVE | N | N147-00-3/711/WAL-004 | Wall: Internal - 4 - Relay Room - Station Building - Stockwell Stn | Other Boarding | Asbestos | Strongly Presumed | | | | Packing between Electrical Equipment | | | | | |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------------|--|-------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 11730 | ACTIVE | N | N147-00-3/712 | Relay Room - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19010 | ACTIVE | N | N147-00-3/712 | Relay Room - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Various Cables 2 cables from invert near wall 1 going to wall 2 duct Approx 12 cut cables from duct wall 1 Approx 7 cables to wall 2 cut | | 10 | | | |
| 53778 | ACTIVE | N | N147-00-3/712 | Relay Room - Station Building - Stockwell Stn | Other Boarding | Asbestos | Sampled – Not Detected | | | | packing board throughout frame | | | | | |
| 42321 | INACTIVE | N | N147-00-3/712 | Relay Room - Station Building - Stockwell Stn | PCBs | Polychlorinated biphenyl | Presumed | | | | 3 x Blue Cyclinder PCB'S - wall mounted Fair Condition | | 3 | | N | N |
| 53777 | ACTIVE | N | N147-00-3/712/ WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Stockwell Stn | Other Boarding | Asbestos | Presumed | | | | Wall 2 1x Brown composite board long | | | | | |
| 11731 | ACTIVE | N | N147-00-3/713 | Relay Room - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16149 | ACTIVE | N | N147-00-3/713 | Relay Room - Station Building - Stockwell Stn | Vinyl tiles | Asbestos | Known | | | | Marley tiles to walls - Known asbestos | | | | | |
| 45059 | INACTIVE | N | N147-00-3/713 | Relay Room - Station Building - Stockwell Stn | Vinyl tiles | Asbestos | Known | | | | Grey marley tiles to walls | | | | N | N |
| 16151 | ACTIVE | N | N147-00-3/713/ CLG-01 | Ceiling: Suspended - 1 - Relay Room - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | Above False Ceiling | | | | YES | |
| 18887 | ACTIVE | N | N147-00-3/713/ CLG-01 | Ceiling: Suspended - 1 - Relay Room - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 16150 | ACTIVE | N | N147-00-3/713/ FLR-01 | Floor - 1 - Relay Room - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel by W2 | | | | | |
| 45058 | ACTIVE | N | N147-00-3/713/ WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Stockwell Stn | Other Boarding | Asbestos | Known | | | | 2x brown composite panel to racking | | | | N | N |
| 11732 | ACTIVE | N | N147-00-3/714 | Relay Room - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 45060 | ACTIVE | N | N147-00-3/714 | Relay Room - Station Building - Stockwell Stn | Other Boarding | Asbestos | Known | | | | 16x brown composite panels to rear of racking to walls | | | | N | N |
| 16152 | ACTIVE | N | N147-00-3/714 | Relay Room - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables | | 18 | | | |
| 19011 | ACTIVE | N | N147-00-3/714/ WAL-004 | Wall: Internal - 4 - Relay Room - Station Building - Stockwell Stn | Other Boarding | Asbestos | Strongly Presumed | | | | Packing between Electrical Equipment | | | | | |
| 11733 | ACTIVE | N | N147-00-3/715 | Relay Room - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 16153 | ACTIVE | N | N147-00-3/715 | Relay Room - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables various, many cut and encapsulated presumed duct to wall - x16 cables cut approx. x4 cables running length from wall 2 duct to wall 3 invert | | 18 | | | |
| 53779 | ACTIVE | N | N147-00-3/715 | Relay Room - Station Building - Stockwell Stn | Other Boarding | Asbestos | Sampled – Not Detected | | | | packing board to frame throughout (as 3/712) | | | | | |
| 11734 | ACTIVE | N | N147-00-3/716 | SER - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16154 | ACTIVE | N | N147-00-3/716 | SER - Station Building - Stockwell Stn | Vinyl tiles | Asbestos | Strongly Presumed | | | | Tunnel rings encapsulated | | | | | |
| 11735 | ACTIVE | N | N147-00-3/731 | CER - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18750 | ACTIVE | N | N147-00-3/731 | CER - Station Building - Stockwell Stn | Other Electrical Boxes | Asbestos | Surveyed – Not Detected | | | | Electrical Equipment | | | | | |
| 16156 | ACTIVE | N | N147-00-3/731/CLG-01 | Ceiling: Suspended - 1 - CER - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking | | | | YES | |
| 16155 | ACTIVE | N | N147-00-3/731/CLG-01 | Ceiling: Suspended - 1 - CER - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11736 | ACTIVE | N | N147-00-3/732 | CER - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18888 | ACTIVE | N | N147-00-3/732 | CER - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables | | 5 | | | |
| 16157 | ACTIVE | N | N147-00-3/732/CLG-01 | Ceiling: Suspended - 1 - CER - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board | | | | | |
| 19012 | ACTIVE | N | N147-00-3/732/CLG-01 | Ceiling: Suspended - 1 - CER - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking | | | | YES | |
| 11737 | ACTIVE | N | N147-00-3/733 | CER - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18459 | ACTIVE | N | N147-00-3/733/FLR-01 | Floor - 1 - CER - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete beneath Computer Flooring | | | | | YES |
| 16158 | ACTIVE | N | N147-00-3/733/WAL-003 | Wall: Internal - 3 - CER - Station Building - Stockwell Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes 60amp - Insulation within | | 2 | | | |
| 11738 | ACTIVE | N | N147-00-3/734 | Lobby - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16160 | ACTIVE | N | N147-00-3/734/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Corrugated Sheeting, Wooden Slats | | | | YES | |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 16159 | ACTIVE | N | N147-00-3/734/FLR-01 | Floor - 1 - Lobby - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete beneath Computer Flooring | | | | | YES |
| 11739 | ACTIVE | N | N147-00-3/761 | Equipment Room - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16162 | ACTIVE | N | N147-00-3/761 | Equipment Room - Station Building - Stockwell Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Walls - Grey Vinyl - Non Asbestos | | | | | |
| 19013 | ACTIVE | N | N147-00-3/761/CLG-01 80910969 | Ceiling: Suspended - 1 - Equipment Room - Station Building - Stockwell Stn Ceiling: Suspended | Caulking | Asbestos | Known | | | | Tunnel Ring Caulking. Type 3 - Confirmed as Asbestos 17/09/03 | | | | YES | |
| 16161 | ACTIVE | N | N147-00-3/761/CLG-01 | Ceiling: Suspended - 1 - Equipment Room - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 43251 | ACTIVE | N | N147-00-3/761/WAL-001 | Wall: Internal - 1 - Equipment Room - Station Building - Stockwell Stn | Vinyl tiles | Asbestos | Presumed | | | | Vinyl Tiles on all walls | | | | N | N |
| 11740 | ACTIVE | N | N147-00-3/762 | Computer Equipment Cupboard - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16163 | ACTIVE | N | N147-00-3/762 | Computer Equipment Cupboard - Station Building - Stockwell Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11741 | ACTIVE | N | N147-00-3/763 | Computer Equipment Cupboard - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20012 | ACTIVE | N | N147-00-3/763 | Computer Equipment Cupboard - Station Building - Stockwell Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11742 | ACTIVE | N | N147-00-3/764 | Computer Equipment Cupboard - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16164 | ACTIVE | N | N147-00-3/764 | Computer Equipment Cupboard - Station Building - Stockwell Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11743 | ACTIVE | N | N147-00-3/765 | Computer Equipment Cupboard - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16165 | ACTIVE | N | N147-00-3/765 | Computer Equipment Cupboard - Station Building - Stockwell Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11744 | ACTIVE | N | N147-00-3/766 | Computer Equipment Cupboard - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|---------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 16166 | ACTIVE | N | N147-00-3/766 | Computer Equipment Cupboard - Station Building - Stockwell Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11745 | ACTIVE | N | N147-00-3/767 | Computer Equipment Cupboard - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19014 | ACTIVE | N | N147-00-3/767 | Computer Equipment Cupboard - Station Building - Stockwell Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11746 | ACTIVE | N | N147-00-3/768 | Computer Equipment Cupboard - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16167 | ACTIVE | N | N147-00-3/768 | Computer Equipment Cupboard - Station Building - Stockwell Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11747 | ACTIVE | N | N147-00-3/769 | Computer Equipment Cupboard - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16168 | ACTIVE | N | N147-00-3/769 | Computer Equipment Cupboard - Station Building - Stockwell Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11748 | ACTIVE | N | N147-00-3/770 | Computer Equipment Cupboard - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19015 | ACTIVE | N | N147-00-3/770 | Computer Equipment Cupboard - Station Building - Stockwell Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 45074 | ACTIVE | N | N147-00-3/901 | Vent Shaft - Station Building - Stockwell Stn | Cable Duct: Other | Asbestos | Presumed | | | | 10no Cable ducts - cables within to walls | | 10 | | N | N |
| 45072 | ACTIVE | N | N147-00-3/901 | Vent Shaft - Station Building - Stockwell Stn | Cable Duct: Other | Asbestos | Presumed | | | | 10no Cable ducts - cables within - to walls , not able to sample | | 10 | | N | N |
| 16169 | ACTIVE | N | N147-00-3/901 | Vent Shaft - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cable LHS J-Hanger No1 | | 1 | | | |
| 45071 | ACTIVE | N | N147-00-3/901 | Vent Shaft - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Presumed | | | | 1no White braided cable | | | | N | N |
| 45075 | ACTIVE | N | N147-00-3/901 | Vent Shaft - Station Building - Stockwell Stn | Cable Duct: Other | Asbestos | Strongly Presumed | | | | 32no Cable ducts | | 32 | | N | N |
| 45062 | ACTIVE | N | N147-00-3/901 | Vent Shaft - Station Building - Stockwell Stn | Cable Ducts: Cement | Asbestos | Known | | | | 10no Cement Cable Ducts - To wall right hand side | | | | N | N |
| 11749 | ACTIVE | N | N147-00-4/236 | Yard - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18889 | ACTIVE | N | N147-00-4/236 | Yard - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Westinghouse boxes | | | | | |
| 45076 | ACTIVE | N | N147-00-4/236 | Yard - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Known | | | | Braided cables 2 and 4 J hanger on cable run | | | | N | N |
| 16259 | ACTIVE | N | N147-00-4/236 | Yard - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking to all Walls and Ceiling | | | | | |
| 16260 | ACTIVE | N | N147-00-4/236/CLG-01 | Ceiling: Solid - 1 - Yard - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above false ceiling | | | | YES | |
| 11750 | ACTIVE | N | N147-00-4/237 | Passage - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 41720 | ACTIVE | N | N147-00-4/237 | Passage - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Known | | | | 1 x Braided cable to middle cable run on side of control panel | | 1 | | N | N |
| 41714 | ACTIVE | N | N147-00-4/237 | Passage - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Known | | | | Braided cable, 1x65m, on cable run between existing control panel and main sump | | 1 | | N | N |
| 41715 | ACTIVE | N | N147-00-4/237 | Passage - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Known | | | | Braided cable, 1x60m, coming from floor and running along cable run located at bottom of the main stairs up to the existing control panel | | 1 | | N | N |
| 41718 | ACTIVE | N | N147-00-4/237 | Passage - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Known | | | | 4 x Braided cable coming from control panel to track level and 2 x coming in from main sump area and bottom of stairs | | 4 | | N | N |
| 41721 | ACTIVE | N | N147-00-4/237 | Passage - Station Building - Stockwell Stn | Caulking | Asbestos | Known | | | | Caulking within tunnel ring flanges | | | | N | N |
| 16262 | ACTIVE | N | N147-00-4/237 | Passage - Station Building - Stockwell Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Material within electrical box. (CS268B) | | 1 | | | |
| 19105 | ACTIVE | N | N147-00-4/237 | Passage - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Presumed | | | | Cables around pump in shaft. (CS268B) | | | | | |
| 18460 | ACTIVE | N | N147-00-4/237 | Passage - Station Building - Stockwell Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Ceiling - Type 3 confirmed as Non Asbestos. (CS268B) | | | | | |
| 41717 | ACTIVE | N | N147-00-4/237 | Passage - Station Building - Stockwell Stn | Other Boarding | Asbestos | Known | | | | 2 x switch boxes | | 2 | | N | N |
| 41719 | ACTIVE | N | N147-00-4/237 | Passage - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Known | | | | 9 x Braided cable to high level cable run on other side of control panel | | 9 | | N | N |
| 45079 | ACTIVE | N | N147-00-4/237 | Passage - Station Building - Stockwell Stn | Cellactite Sheeting | Asbestos | Known | | | | Cellactite Boarding / Bitumen corrugated sheet to ceiling | 250 | | | N | N |
| 45078 | ACTIVE | N | N147-00-4/237 | Passage - Station Building - Stockwell Stn | Westing house Boxes | Asbestos | Known | | | | 2no Westinghouse boxes - To wall, left wall 1 past cable run | | 2 | | N | N |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|------------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 45077 | ACTIVE | N | N147-00-4/237 | Passage - Station Building - Stockwell Stn | Other Electrical Boxes | Asbestos | Known | | | | 1no Transformer - To far end wall by IMR | | 1 | | N | N |
| 45081 | ACTIVE | N | N147-00-4/237 | Passage - Station Building - Stockwell Stn | Other Boarding | Asbestos | Known | | | | 2 x Melamine board, to pump 5 & 6 control box located at existing control panel | | | | N | N |
| 45080 | ACTIVE | N | N147-00-4/237 | Passage - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Known | | | | 4no Braided Cables 100m On cable run 6 & 7 J Hanger from top middle passage | | 4 | | N | N |
| 16261 | ACTIVE | N | N147-00-4/237 | Passage - Station Building - Stockwell Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Walls - Type 3 confirmed as Non Asbestos (CS268B) | | | | | |
| 16263 | ACTIVE | N | N147-00-4/237 | Passage - Station Building - Stockwell Stn | Cellactite Sheeting | Asbestos | Known | | | | Cellactite Boarding on ceiling - 10m2. Type 3 States 20m2. (CS268B) | | | | | |
| 11751 | ACTIVE | N | N147-00-4/706 | IMR - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16264 | ACTIVE | N | N147-00-4/706/CLG-01 | Ceiling: Solid - 1 - IMR - Station Building - Stockwell Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | YES | |
| 45082 | ACTIVE | N | N147-00-4/706/WAL-001 | Wall: Internal - 1 - IMR - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Known | | | | Green Braided cables - To wall 1 above A/C unit far end- numerous | | | | N | N |
| 17946 | ACTIVE | N | N147-00-4/706/WAL-001 | Wall: Internal - 1 - IMR - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables and wall mounted PCB's Silver wall mounted | | 6 | | | |
| 45083 | ACTIVE | N | N147-00-4/706/WAL-003 | Wall: Internal - 3 - IMR - Station Building - Stockwell Stn | Other Boarding | Asbestos | Known | | | | Brown composite panels - throughout to wall 3 | | | | N | N |
| 43253 | INACTIVE | N | N147-00-4/706/WAL-003 | Wall: Internal - 3 - IMR - Station Building - Stockwell Stn | PCBs | Polychlorinated biphenyl | Presumed | | | | 8 x green cylinders mounted high on wall Fair Condition | | | | N | N |
| 11752 | ACTIVE | N | N147-00-4/707 | IMR - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16266 | ACTIVE | N | N147-00-4/707 | IMR - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables | | 8 | | | |
| 16265 | ACTIVE | N | N147-00-4/707 | IMR - Station Building - Stockwell Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Caulking | | | | | |
| 45084 | ACTIVE | N | N147-00-4/707 | IMR - Station Building - Stockwell Stn | Cable: Sheath | Asbestos | Known | | | | Green woven cables - Numerous - Throughout to wall and ceiling | | | | N | N |
| 18897 | ACTIVE | N | N147-00-4/707 | IMR - Station Building - Stockwell Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Grey Switch Boxes - Insulation within | | 2 | | | |
| 42322 | INACTIVE | N | N147-00-4/707 | IMR - Station Building - Stockwell Stn | PCBs | Polychlorinated biphenyl | Presumed | | | | 8 x Silver Cyclinder PCB's - wall mounted Fair Condition | | 8 | | N | N |
| 45088 | INACTIVE | N | N147-00-4/707 | IMR - Station Building - Stockwell Stn | PCBs | Polychlorinated biphenyl | Known | | | | 8 x Green Cyclinder Wall Mounted PCB | | 8 | | N | N |
| 16267 | ACTIVE | N | N147-00-4/707/CLG-01 | Ceiling: Solid - 1 - IMR - Station Building - Stockwell Stn | Cellactite Sheeting | Asbestos | Known | | | | Cellactite Boarding on ceiling - 10m2 | | | | | |



Hazardous Material Asset Register - Summary



N147-00 - Station Building - Stockwell Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 45085 | ACTIVE | N | N147-00-4/707/FLR-01 | Floor - 1 - IMR - Station Building - Stockwell Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 2no circuit breaker boxes To middle of room frame | | 2 | | N | N |
| 45086 | ACTIVE | N | N147-00-4/707/WAL-001 | Wall: Internal - 1 - IMR - Station Building - Stockwell Stn | Other Boarding | Asbestos | Presumed | | | | Brown composite panel - Throughout | | | | N | N |
| 45087 | ACTIVE | N | N147-00-4/707/WAL-003 | Wall: Internal - 3 - IMR - Station Building - Stockwell Stn | Other Boarding | Asbestos | Presumed | | | | Brown composite panel - Throughout | | | | N | N |
| 11753 | ACTIVE | N | N147-00-4/771 | Pump Room - Station Building - Stockwell Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16269 | ACTIVE | N | N147-00-4/771/CLG-01 | Ceiling: Solid - 1 - Pump Room - Station Building - Stockwell Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board | | | | | |
| 16270 | ACTIVE | N | N147-00-4/771/CLG-01 | Ceiling: Solid - 1 - Pump Room - Station Building - Stockwell Stn | Cellactite Sheeting | Asbestos | Known | | | | Cellactite Roof 15m2 | | | | YES | |
| 16268 | ACTIVE | N | N147-00-4/771/FLR-01 | Floor - 1 - Pump Room - Station Building - Stockwell Stn | Void | Asbestos | Surveyed – Not Detected | | | | Floor Hatch - Sumps beneath Metal Floor | | | | | YES |
| 17947 | ACTIVE | N | N147-00-4/771/WAL-003 | Wall: Internal - 3 - Pump Room - Station Building - Stockwell Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring Caulking | | | | | |

N153-00 - Station Building - Clapham North Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 11754 | ACTIVE | N | N153-00-1/001 | Booking Hall - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18771 | ACTIVE | N | N153-00-1/001 | Booking Hall - Station Building - Clapham North Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11755 | ACTIVE | N | N153-00-1/011 | Ticket Office - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 42487 | ACTIVE | N | N153-00-1/011 | Ticket Office - Station Building - Clapham North Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above False Ceiling - Plastic Cables, Trunking and Conduits | | | R506551 | Y | N |
| 42488 | ACTIVE | N | N153-00-1/011 | Ticket Office - Station Building - Clapham North Stn | Void | Asbestos | Surveyed – Not Detected | | | | Beneath False Floor - Concrete, Plastic Cables, Trunking Conduits beneath Computer flooring tiles | | | R506551 | N | Y |
| 42477 | ACTIVE | N | N153-00-1/011 | Ticket Office - Station Building - Clapham North Stn | Mastic | Asbestos | Sampled – Not Detected | | | | Putty throughout joints of Air Conditioning unit | | | R506551 | N | N |
| 42483 | ACTIVE | N | N153-00-1/011 | Ticket Office - Station Building - Clapham North Stn | Debris: Other | Asbestos | Surveyed – Not Detected | | | | Above False Ceiling - Fibreglass Debris above | | | R506551 | N | Y |
| 42481 | ACTIVE | N | N153-00-1/011 | Ticket Office - Station Building - Clapham North Stn | Cable Duct: Other | Asbestos | Surveyed – Not Detected | | | | Beneath False Floor - Concrete beneath computer tiles | | | R506551 | N | Y |



Hazardous Material Asset Register - Summary



N153-00 - Station Building - Clapham North Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 15974 | ACTIVE | N | N153-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Clapham North Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 15975 | ACTIVE | N | N153-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Clapham North Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above False Ceiling | | | | YES | |
| 11756 | ACTIVE | N | N153-00-1/021 | POM - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 42490 | ACTIVE | N | N153-00-1/021 | POM - Station Building - Clapham North Stn | Debris: Other | Asbestos | Surveyed – Not Detected | | | | Below False Floor - Supalux Debris | | | R506551 | N | Y |
| 42478 | ACTIVE | N | N153-00-1/021 | POM - Station Building - Clapham North Stn | Debris: Other | Asbestos | Sampled – Not Detected | | | | Above False Ceiling - Dust sample throughout - Note wall 3 seems to be encapsulated - no residue seen. | | | R506551 | Y | N |
| 42479 | ACTIVE | N | N153-00-1/021 | POM - Station Building - Clapham North Stn | Mastic | Asbestos | Sampled – Not Detected | | | | Putty throughout joints of Air Conditioning unit | | | R506551 | N | N |
| 42484 | ACTIVE | N | N153-00-1/021 | POM - Station Building - Clapham North Stn | Void | Asbestos | Surveyed – Not Detected | | | | Breeze Block, Brick and Concrete above false ceiling | | | R506551 | Y | N |
| 42489 | ACTIVE | N | N153-00-1/021 | POM - Station Building - Clapham North Stn | Void | Asbestos | Surveyed – Not Detected | | | | Beneath False Floor - Concrete, plastic cables, trunking and conduits beneath computer floor tiles | | | R506551 | N | Y |
| 42485 | ACTIVE | N | N153-00-1/021 | POM - Station Building - Clapham North Stn | Lagging | Asbestos | Surveyed – Not Detected | | | | Above False Ceiling - A/C Trunking, Fibreglass Lagging, Fibreglass Debris | | | R506551 | Y | N |
| 18772 | ACTIVE | N | N153-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Clapham North Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 15976 | ACTIVE | N | N153-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Clapham North Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above False Ceiling - Concrete, Breeze Block and Brick | | | R506551 | YES | N |
| 11757 | ACTIVE | N | N153-00-1/031 | Mess Room - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | Below false floor | | | | | |
| 15977 | ACTIVE | N | N153-00-1/031 | Mess Room - Station Building - Clapham North Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - Insulation Foam Board | | | | | |
| 11758 | ACTIVE | N | N153-00-1/036 | Toilet: Unisex - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15978 | ACTIVE | N | N153-00-1/036 | Toilet: Unisex - Station Building - Clapham North Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Cover to void under sink - Tiles on a Supalux Panel - Supalux Debris in void | | | | | |
| 19959 | ACTIVE | N | N153-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Clapham North Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Fibreglass Lagging above Supalux Tiles | | | | YES | |



Hazardous Material Asset Register - Summary



N153-00 - Station Building - Clapham North Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-------------------------------|--|------------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 15979 | ACTIVE | N | N153-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Clapham North Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11759 | ACTIVE | N | N153-00-1/041 | Locker Room - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11760 | ACTIVE | N | N153-00-1/071 | Circulation Area - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18837 | ACTIVE | N | N153-00-1/071 | Circulation Area - Station Building - Clapham North Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11761 | ACTIVE | N | N153-00-1/151 | UMC - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42662 | ACTIVE | N | N153-00-1/151 | UMC - Station Building - Clapham North Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Beige Gloss on Stairs 0.28% | | | R504501 | N | N |
| 42660 | ACTIVE | N | N153-00-1/151 | UMC - Station Building - Clapham North Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Red Gloss on Floor, Analysis Results 0.09% | | | R504501 | N | N |
| 44972 | ACTIVE | N | N153-00-1/151 | UMC - Station Building - Clapham North Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Red Oil Based Paint | | | | N | N |
| 42663 | ACTIVE | N | N153-00-1/151 | UMC - Station Building - Clapham North Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Cream Matt on Walls at entry level 0.31% | | | R504501 | N | N |
| 42661 | ACTIVE | N | N153-00-1/151 | UMC - Station Building - Clapham North Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Cream Matt Walls 0.04% | | | R504501 | N | N |
| 15981 | ACTIVE | N | N153-00-1/151 | UMC - Station Building - Clapham North Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Pipework - Red Oil Based Paint. Thickness .08mm; Est Quantity 30 lm; Analysis 3.08% | | | | | |
| 18740 | ACTIVE | N | N153-00-1/151/FLR-01 | Floor - 1 - UMC - Station Building - Clapham North Stn | Debris: Cement | Asbestos | Surveyed – Not Detected | | | | Dust / Debris in Duct below Floor | | | | | YES |
| 41902 | ACTIVE | N | N153-00-1/151/FLR-01 80892901 | Floor - 1 - UMC - Station Building - Clapham North Stn Floor | Other Electrical Boxes | Asbestos | Presumed | | | | 1 x Trasformer Box. Presumed asbestos insulating materials within. No access to inspect internally. Electrical isolations required | | 1 | | N | N |
| 15980 | ACTIVE | N | N153-00-1/151/FLR-01 | Floor - 1 - UMC - Station Building - Clapham North Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Lid to Storage Bin | | | | | |
| 15982 | ACTIVE | N | N153-00-1/171 | Escalator Incline - Station Building - Clapham North Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access | | | | | |
| 11762 | ACTIVE | N | N153-00-1/236 | Lobby - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18838 | ACTIVE | N | N153-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Clapham North Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |



Hazardous Material Asset Register - Summary



N153-00 - Station Building - Clapham North Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-------------------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 15983 | ACTIVE | N | N153-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Clapham North Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 11763 | ACTIVE | N | N153-00-1/237 | Passage - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15984 | ACTIVE | N | N153-00-1/237 | Passage - Station Building - Clapham North Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11764 | ACTIVE | N | N153-00-1/331 | Locker Room - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19348 | ACTIVE | N | N153-00-1/331 | Locker Room - Station Building - Clapham North Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - Insulation Foam Board | | | | | |
| 15985 | ACTIVE | N | N153-00-1/331/CLG-01 | Ceiling: Suspended - 1 - Locker Room - Station Building - Clapham North Stn | Void | Asbestos | No Access: Presumed | | | | No Access above false ceiling - too high | | | | YES | |
| 18839 | ACTIVE | N | N153-00-1/331/CLG-01 | Ceiling: Suspended - 1 - Locker Room - Station Building - Clapham North Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11765 | ACTIVE | N | N153-00-1/401 | Locker Room - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15987 | ACTIVE | N | N153-00-1/401/CLG-01 80964082 | Ceiling: Solid - 1 - Locker Room - Station Building - Clapham North Stn Ceiling: Solid | Void | Asbestos | Surveyed – Not Detected | | | | No Access under False Ceiling Metal Panel | | | | YES | |
| 15986 | ACTIVE | N | N153-00-1/401/CLG-01 | Ceiling: Solid - 1 - Locker Room - Station Building - Clapham North Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux, Plaster; Metal Panel | | | | | |
| 11766 | ACTIVE | N | N153-00-1/411 | Store - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15988 | ACTIVE | N | N153-00-1/411 | Store - Station Building - Clapham North Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11767 | ACTIVE | N | N153-00-1/412 | SVC - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15989 | ACTIVE | N | N153-00-1/412/CLG-01 | Ceiling: Suspended - 1 - SVC - Station Building - Clapham North Stn | Void | Asbestos | No Access: Presumed | | | | No Access above false ceiling - too high | | | | YES | |
| 18840 | ACTIVE | N | N153-00-1/412/CLG-01 | Ceiling: Suspended - 1 - SVC - Station Building - Clapham North Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |



Hazardous Material Asset Register - Summary



N153-00 - Station Building - Clapham North Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 11768 | ACTIVE | N | N153-00-1/416 | Lobby - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15991 | ACTIVE | N | N153-00-1/416/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Clapham North Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Fibreglass above Supalux Tiles | | | | YES | |
| 15990 | ACTIVE | N | N153-00-1/416/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Clapham North Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11769 | ACTIVE | N | N153-00-1/417 | Toilet: Male - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18809 | ACTIVE | N | N153-00-1/417/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Clapham North Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 15992 | ACTIVE | N | N153-00-1/417/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Clapham North Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11770 | ACTIVE | N | N153-00-1/418 | Toilet: Female - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15993 | ACTIVE | N | N153-00-1/418/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Clapham North Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 18841 | ACTIVE | N | N153-00-1/418/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Clapham North Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11771 | ACTIVE | N | N153-00-1/601 | Stairs: Linear - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11772 | ACTIVE | N | N153-00-1/602 | Stairs: Linear - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11773 | ACTIVE | N | N153-00-1/603 | Stairs: Linear - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11774 | ACTIVE | N | N153-00-1/604 | Stairs: Linear - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11775 | ACTIVE | N | N153-00-1/605 | Stairs: Linear - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11776 | ACTIVE | N | N153-00-1/631 | Stairs: Spiral - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N153-00 - Station Building - Clapham North Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|--------------------------------|---|------------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 15994 | ACTIVE | N | N153-00-1/631 | Stairs: Spiral - Station Building - Clapham North Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - Insulation Foam Board | | | | | |
| 15995 | ACTIVE | N | N153-00-1/631 | Stairs: Spiral - Station Building - Clapham North Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Durasteel Panel | | | | | |
| 15996 | ACTIVE | N | N153-00-1/631 | Stairs: Spiral - Station Building - Clapham North Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Girder - Cream Oil Based Paint. Thickness .34mm; Est Quantity 50 lm; Analysis 1.32% | | | | | |
| 11777 | ACTIVE | N | N153-00-1/661 | Switch Room - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Presumed | | | | | | | | | |
| 18741 | INACTIVE | N | N153-00-1/661/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Clapham North Stn | Isolator Switches | Asbestos | Removed | | | | 5 x Isolator Isolator Switch Boxes - Asbestos free stickers attached. Flash Guards replaced for SMEP works by EMS Group September 2009 | | 5 | | N | N |
| 41903 | ACTIVE | N | N153-00-1/661/WAL-001 80893023 | Wall: Internal - 1 - Switch Room - Station Building - Clapham North Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | 1 x Transformer Box. Presumed asbestos insulating materials within. No access to inspect internally, electrical isolations required | | 1 | | N | N |
| 11778 | ACTIVE | N | N153-00-1/662 | Switch Room - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18842 | ACTIVE | N | N153-00-1/662 | Switch Room - Station Building - Clapham North Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 42040 | INACTIVE | N | N153-00-1/662/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Clapham North Stn | Isolator Switches | Asbestos | Room: Asbestos Free | | | | 3 x Isolator Switch Boxes - Flash Guards was replaced by EMS Group in September 2009 | | 3 | | N | N |
| 11779 | ACTIVE | N | N153-00-1/663 | Switch Room - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42041 | INACTIVE | N | N153-00-1/663 | Switch Room - Station Building - Clapham North Stn | Isolator Switches | Asbestos | Removed | | | | 9 x Isolator Switch Boxes - Flash Guards replaced by EMS Group September 2009 | | 9 | | N | N |
| 18317 | ACTIVE | N | N153-00-1/663/WAL-001 80893047 | Wall: Internal - 1 - Switch Room - Station Building - Clapham North Stn Wall: Internal | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | 3 x Transformer Boxes. Presumed asbestos insulating materials within. No access to inspect internally. Electrical isolations required | | 3 | | | |
| 41904 | ACTIVE | N | N153-00-1/663/WAL-002 80893048 | Wall: Internal - 2 - Switch Room - Station Building - Clapham North Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | 1 x Tranformer Box. Presumed asbestos insulation within. No access to inspect internally. Electrical isolations required | | 1 | | N | N |
| 11780 | ACTIVE | N | N153-00-1/664 | Switch Room - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42043 | INACTIVE | N | N153-00-1/664 | Switch Room - Station Building - Clapham North Stn | Isolator Switches | Asbestos | Removed | | | | 5 x Isolator Switch Boxes - Flash Guards replaced by EMS Group September 2009 | | 5 | | N | N |



Hazardous Material Asset Register - Summary



N153-00 - Station Building - Clapham North Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 15997 | ACTIVE | N | N153-00-1/664/DOR-01 | Door - 1 - Switch Room - Station Building - Clapham North Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Durasteel & Door - Non Asbestos | | | | | |
| 11781 | ACTIVE | N | N153-00-1/746 | SCR - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15998 | ACTIVE | N | N153-00-1/746 | SCR - Station Building - Clapham North Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11782 | ACTIVE | N | N153-00-1/751 | Station Control Room - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15999 | ACTIVE | N | N153-00-1/751/CLG-01 | Ceiling: Solid - 1 - Station Control Room - Station Building - Clapham North Stn | Void | Asbestos | No Access: Presumed | | | | Above False Ceiling | | | | YES | |
| 18843 | ACTIVE | N | N153-00-1/751/FLR-01 | Floor - 1 - Station Control Room - Station Building - Clapham North Stn | Void | Asbestos | No Access: Presumed | | | | Wooden False Floor and Lino | | | | | YES |
| 11783 | ACTIVE | N | N153-00-2/001 | Booking Hall - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11784 | ACTIVE | N | N153-00-2/011 | Ticket Office - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11785 | ACTIVE | N | N153-00-2/021 | POM - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11786 | ACTIVE | N | N153-00-2/031 | Mess Room - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11787 | ACTIVE | N | N153-00-2/071 | Circulation Area - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11788 | ACTIVE | N | N153-00-2/081 | Circulation Area - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18810 | ACTIVE | N | N153-00-2/081 | Circulation Area - Station Building - Clapham North Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11789 | ACTIVE | N | N153-00-2/161 | LMC - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16000 | ACTIVE | N | N153-00-2/161 | LMC - Station Building - Clapham North Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 16001 | ACTIVE | N | N153-00-2/161 | LMC - Station Building - Clapham North Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Girder - Cream Oil Based Paint. Thickness .22mm; Est Quantity 6 lm; Analysis 1.38% | | | | | |



Hazardous Material Asset Register - Summary



N153-00 - Station Building - Clapham North Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---------------------|-------------|------------|-------------|---------------------|-------------------|
| 11790 | ACTIVE | N | N153-00-2/201 | Passage - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16002 | ACTIVE | N | N153-00-2/201 | Passage - Station Building - Clapham North Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11791 | ACTIVE | N | N153-00-2/202 | Passage - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16003 | ACTIVE | N | N153-00-2/202 | Passage - Station Building - Clapham North Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11792 | ACTIVE | N | N153-00-2/203 | Passage - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18844 | ACTIVE | N | N153-00-2/203 | Passage - Station Building - Clapham North Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11793 | ACTIVE | N | N153-00-2/204 | Passage - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16004 | ACTIVE | N | N153-00-2/204 | Passage - Station Building - Clapham North Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11794 | ACTIVE | N | N153-00-2/236 | Passage - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11795 | ACTIVE | N | N153-00-2/401 | Switch Room - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11796 | ACTIVE | N | N153-00-2/406 | Switch Cupboard - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16005 | ACTIVE | N | N153-00-2/406 | Switch Cupboard - Station Building - Clapham North Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11797 | ACTIVE | N | N153-00-2/416 | Mess Room - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11798 | ACTIVE | N | N153-00-2/418 | Cleaners Room - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11799 | ACTIVE | N | N153-00-2/451 | Tenancy - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11800 | ACTIVE | N | N153-00-2/601 | Stairs: Linear - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N153-00 - Station Building - Clapham North Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18811 | ACTIVE | N | N153-00-2/601 | Stairs: Linear - Station Building - Clapham North Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11801 | ACTIVE | N | N153-00-2/661 | Equipment Room - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11802 | ACTIVE | N | N153-00-2/662 | Switch Room - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16006 | ACTIVE | N | N153-00-2/662 | Switch Room - Station Building - Clapham North Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11803 | ACTIVE | N | N153-00-2/663 | Switch Cupboard - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18845 | ACTIVE | N | N153-00-2/663 | Switch Cupboard - Station Building - Clapham North Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11804 | ACTIVE | N | N153-00-2/664 | Switch Cupboard - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16007 | ACTIVE | N | N153-00-2/664 | Switch Cupboard - Station Building - Clapham North Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11805 | ACTIVE | N | N153-00-2/666 | Switch Cupboard - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16008 | ACTIVE | N | N153-00-2/666 | Switch Cupboard - Station Building - Clapham North Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - No Access | | | | | |
| 11806 | ACTIVE | N | N153-00-2/731 | Passage - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16009 | ACTIVE | N | N153-00-2/731 | Passage - Station Building - Clapham North Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11807 | ACTIVE | N | N153-00-2/732 | CER - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18846 | ACTIVE | N | N153-00-2/732/FLR-01 | Floor - 1 - CER - Station Building - Clapham North Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |
| 42044 | INACTIVE | N | N153-00-2/732/WAL-002 | Wall: Internal - 2 - CER - Station Building - Clapham North Stn | Isolator Switches | Asbestos | Removed | | | | 2 x Isolator Switch Boxes - Flash Guards was replaced for SMEP works by EMS Group September 2009 | | 2 | | N | N |
| 11808 | ACTIVE | N | N153-00-2/746 | SCR - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N153-00 - Station Building - Clapham North Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 11809 | ACTIVE | N | N153-00-2/751 | Station Control Room - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11810 | ACTIVE | N | N153-00-2/762 | SVC - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11811 | ACTIVE | N | N153-00-2/901 | Disused Room - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11812 | ACTIVE | N | N153-00-2/952 | CER - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16010 | ACTIVE | N | N153-00-2/952 | CER - Station Building - Clapham North Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11813 | ACTIVE | N | N153-00-2/953 | Switch Room - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18812 | ACTIVE | N | N153-00-2/953 | Switch Room - Station Building - Clapham North Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11814 | ACTIVE | N | N153-00-2/955 | CER - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16012 | ACTIVE | N | N153-00-2/955/CLG-01 | Ceiling: Suspended - 1 - CER - Station Building - Clapham North Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Tiles | | | | YES | |
| 18742 | ACTIVE | N | N153-00-2/955/CLG-01 | Ceiling: Suspended - 1 - CER - Station Building - Clapham North Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 16011 | ACTIVE | N | N153-00-2/955/FLR-01 | Floor - 1 - CER - Station Building - Clapham North Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |
| 16013 | ACTIVE | N | N153-00-2/986/WAL-001 | Wall: Internal - 1 - Vent Shaft - Station Building - Clapham North Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring - Concrete Caulking | | | | | |
| 18847 | ACTIVE | N | N153-00-2/986/WAL-002 | Wall: Internal - 2 - Vent Shaft - Station Building - Clapham North Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring - Concrete Caulking | | | | | |
| 18318 | ACTIVE | N | N153-00-2/986/WAL-003 | Wall: Internal - 3 - Vent Shaft - Station Building - Clapham North Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring - Concrete Caulking | | | | | |
| 16014 | ACTIVE | N | N153-00-2/986/WAL-004 | Wall: Internal - 4 - Vent Shaft - Station Building - Clapham North Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring - Concrete Caulking | | | | | |



Hazardous Material Asset Register - Summary



N153-00 - Station Building - Clapham North Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---------------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 11815 | ACTIVE | N | N153-00-3/261 | Platform 1 - Northbound Local - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16015 | ACTIVE | N | N153-00-3/261 | Platform 1 - Northbound Local - Station Building - Clapham North Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 10mm Cable | | 1 | | | |
| 11816 | ACTIVE | N | N153-00-3/262 | Platform 2 - Southbound Local - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16016 | ACTIVE | N | N153-00-3/262 | Platform 2 - Southbound Local - Station Building - Clapham North Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables | | 2 | | | |
| 44973 | ACTIVE | N | N153-00-3/262 | Platform 2 - Southbound Local - Station Building - Clapham North Stn | Cable: Sheath | Asbestos | Known | | | | Braided cable 1no to wall at entrance | | | | N | N |
| 11817 | ACTIVE | N | N153-00-3/661 | Switch Room - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16017 | ACTIVE | N | N153-00-3/661 | Switch Room - Station Building - Clapham North Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels to outside | | | | | |
| 16018 | ACTIVE | N | N153-00-3/661/CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - Clapham North Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux | | | | YES | |
| 18848 | ACTIVE | N | N153-00-3/661/CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - Clapham North Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 11818 | ACTIVE | N | N153-00-3/711 | SER - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16019 | ACTIVE | N | N153-00-3/711 | SER - Station Building - Clapham North Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11819 | ACTIVE | N | N153-00-3/731 | CER - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16020 | ACTIVE | N | N153-00-3/731 | CER - Station Building - Clapham North Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11820 | ACTIVE | N | N153-00-3/771 | Pump Room - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16021 | ACTIVE | N | N153-00-3/771/WAL-001 | Wall: Internal - 1 - Pump Room - Station Building - Clapham North Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring - Concrete Caulking | | | | | |



Hazardous Material Asset Register - Summary



N153-00 - Station Building - Clapham North Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18813 | ACTIVE | N | N153-00-3/771/WAL-002 | Wall: Internal - 2 - Pump Room - Station Building - Clapham North Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring - Concrete Caulking | | | | | |
| 18849 | ACTIVE | N | N153-00-3/771/WAL-003 | Wall: Internal - 3 - Pump Room - Station Building - Clapham North Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring - Concrete Caulking | | | | | |
| 16022 | ACTIVE | N | N153-00-3/771/WAL-004 | Wall: Internal - 4 - Pump Room - Station Building - Clapham North Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Ring - Concrete Caulking | | | | | |
| 11821 | ACTIVE | N | N153-00-3/781 | Equipment Room - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16023 | ACTIVE | N | N153-00-3/781 | Equipment Room - Station Building - Clapham North Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - No Access | | | | | |
| 11822 | ACTIVE | N | N153-00-3/782 | TXR - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16024 | ACTIVE | N | N153-00-3/782 | TXR - Station Building - Clapham North Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - No Access | | | | | |
| 11823 | ACTIVE | N | N153-00-3/783 | Switch Room - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44975 | ACTIVE | N | N153-00-3/783 | Switch Room - Station Building - Clapham North Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | 1no Remote Control Box to Wall | | | | N | N |
| 44974 | ACTIVE | N | N153-00-3/783 | Switch Room - Station Building - Clapham North Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | 1no Auxiliary Transformer to Floor | | | | N | N |
| 44977 | ACTIVE | N | N153-00-3/783 | Switch Room - Station Building - Clapham North Stn | Cable: Sheath | Asbestos | Known | | | | External - Braided cables >4no Going Into Room | | | | N | N |
| 16025 | ACTIVE | N | N153-00-3/783 | Switch Room - Station Building - Clapham North Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - No Access | | | | | |
| 44976 | ACTIVE | N | N153-00-3/783 | Switch Room - Station Building - Clapham North Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | 1no Marshall Cabinet to Wall | | | | N | N |
| 11824 | ACTIVE | N | N153-00-3/786 | Platform Invert - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70551 | ACTIVE | N | N153-00-3/786 | Platform Invert - Station Building - Clapham North Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - total 2 no - To J Hangers RHS | | 2 | R728759 | | |
| 16027 | ACTIVE | N | N153-00-3/786 | Platform Invert - Station Building - Clapham North Stn | Cable Duct: Other | Asbestos | Presumed | | | | Invert. 6 + Ducts at high level (cannot be sampled from out or inside as no safe access via ladder) | | 6 | | | |
| 16028 | ACTIVE | N | N153-00-3/786 | Platform Invert - Station Building - Clapham North Stn | Cable Duct: Other | Asbestos | Presumed | | | | Invert. 3+ Ducts at high level (cannot be sampled safely) | | 3 | | | |



Hazardous Material Asset Register - Summary



N153-00 - Station Building - Clapham North Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 16029 | ACTIVE | N | N153-00-3/786 | Platform Invert - Station Building - Clapham North Stn | Cable: Sheath | Asbestos | Presumed | | | | Invert. 1 x white braided cable - from track to 3rd J hanger from bottom | | 1 | | | |
| 16031 | ACTIVE | N | N153-00-3/786 | Platform Invert - Station Building - Clapham North Stn | Other Electrical Boxes | Asbestos | Presumed | | | | ACMs within electrical equipment between rooms 3/661 & 3/783. | | | | | |
| 18850 | ACTIVE | N | N153-00-3/786 | Platform Invert - Station Building - Clapham North Stn | Caulking | Asbestos | Sampled – Not Detected | | | | Caulking full length of invert inbetween exposed tunnel rings | | | | | |
| 70537 | ACTIVE | N | N153-00-3/786 | Platform Invert - Station Building - Clapham North Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728759 | | |
| 18851 | ACTIVE | N | N153-00-3/786 | Platform Invert - Station Building - Clapham North Stn | Cable: Sheath | Asbestos | Presumed | | | | Invert. - 1 x Green Braided Cable - from track to 9th J hanger from top | | 1 | | | |
| 70540 | ACTIVE | N | N153-00-3/786 | Platform Invert - Station Building - Clapham North Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout, wood, lead - To tunnel rings flanges throughout | | | R728759 | | |
| 70552 | ACTIVE | N | N153-00-3/786 | Platform Invert - Station Building - Clapham North Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Platform Invert - Materials within transformer - total 1 no - To arch RHS by steps | | 1 | R728759 | | |
| 70553 | ACTIVE | N | N153-00-3/786 | Platform Invert - Station Building - Clapham North Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Platform Invert - Materials within disused train stop - total 1 no - To arch RHS by steps | | 1 | R728759 | | |
| 70554 | ACTIVE | N | N153-00-3/786 | Platform Invert - Station Building - Clapham North Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable duct - total 3 no - To high level wall by steps RHS | | 3 | R728759 | N | Y |
| 70555 | ACTIVE | N | N153-00-3/786 | Platform Invert - Station Building - Clapham North Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable duct - total 1 no - To high level wall by steps LHS | | 1 | R728759 | N | Y |
| 16026 | ACTIVE | N | N153-00-3/786 | Platform Invert - Station Building - Clapham North Stn | Cable: Wrap | Asbestos | Surveyed – Not Detected | | | | Tape on Cable & Rope around Cable the length of Cable Run | | | | | |
| 16030 | ACTIVE | N | N153-00-3/786 | Platform Invert - Station Building - Clapham North Stn | Cable: Sheath | Asbestos | Presumed | | | | Invert. - 1 x Green Braided Cable - from track to bottom J hanger | | 1 | | | |
| 11825 | ACTIVE | N | N153-00-3/787 | Platform Invert - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18744 | ACTIVE | N | N153-00-3/787 | Platform Invert - Station Building - Clapham North Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cable Run - Cables SP | | | | | |
| 70549 | ACTIVE | N | N153-00-3/787 | Platform Invert - Station Building - Clapham North Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Materials within link boxes - total 4 no - To cable run RHS | | 4 | R728759 | | |
| 70536 | ACTIVE | N | N153-00-3/787 | Platform Invert - Station Building - Clapham North Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728759 | | |
| 70550 | ACTIVE | N | N153-00-3/787 | Platform Invert - Station Building - Clapham North Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - total 4 no - To J Hangers | | 4 | R728759 | | |
| 70539 | ACTIVE | N | N153-00-3/787 | Platform Invert - Station Building - Clapham North Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout, wood, lead - To tunnel rings flanges throughout | | | R728759 | | |
| 11826 | ACTIVE | N | N153-00-3/788 | Platform Invert - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N153-00 - Station Building - Clapham North Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|----------------------|---------------|-------------------------|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 70547 | ACTIVE | N | N153-00-3/788 | Platform Invert - Station Building - Clapham North Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Platform Invert - Supalux panels and debris - Throughout - To walls and loose to floor by doors to 3/787 | | | R728759 | N | Y |
| 70545 | ACTIVE | N | N153-00-3/788 | Platform Invert - Station Building - Clapham North Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 4 no - To ceiling by ladder RHS | | 4 | R728759 | N | Y |
| 70544 | ACTIVE | N | N153-00-3/788 | Platform Invert - Station Building - Clapham North Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 10 no - To trackside wall / ceiling RHS | | 10 | R728759 | N | Y |
| 67680 | ACTIVE | N | N153-00-3/788 | Platform Invert - Station Building - Clapham North Stn | | Asbestos | Sampled – Not Detected | | | | Tunnel ring joints - Concrete throughout 4-Rail Services sampled 24/11/2023 - ID Report R740851 | | | | | |
| 19960 | ACTIVE | N | N153-00-3/788 | Platform Invert - Station Building - Clapham North Stn | Cable Duct: Other | Asbestos | Surveyed – Not Detected | | | | Cable Sleeves | | | | | |
| 70541 | ACTIVE | N | N153-00-3/788 | Platform Invert - Station Building - Clapham North Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 1 no - To trackside wall LHS | | 1 | R728759 | N | Y |
| 70542 | ACTIVE | N | N153-00-3/788 | Platform Invert - Station Building - Clapham North Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 8 no - To trackside wall LHS | | 8 | R728759 | N | Y |
| 42045 | INACTIVE | N | N153-00-3/788 | Platform Invert - Station Building - Clapham North Stn | Isolator Switches | Asbestos | Removed | | | | 2 x Isolator Switch Boxes - Flash Guards was replaced by EMS Group September 2009 | | 2 | | N | N |
| 18852 | ACTIVE | N | N153-00-3/788 | Platform Invert - Station Building - Clapham North Stn | Cable Duct: Other | Asbestos | Surveyed – Not Detected | | | | 6+ Ducts at high level (no safe way to sample) | | 6 | | | |
| 70548 | ACTIVE | N | N153-00-3/788 | Platform Invert - Station Building - Clapham North Stn | Debris: Other | Asbestos | Sampled – Not Detected | | | | Platform Invert - MMMF insulation loose - Throughout - To ducts, floor | | | R728759 | N | Y |
| 70546 | ACTIVE | N | N153-00-3/788 | Platform Invert - Station Building - Clapham North Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | Platform Invert - Bitumen cable ducts - total 2 x 2no - Within concrete cable trays to floor RHS | | 4 | R728759 | N | Y |
| 70538 | ACTIVE | N | N153-00-3/788 | Platform Invert - Station Building - Clapham North Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout, wood, lead - To tunnel rings flanges throughout | | | R728759 | | |
| 70535 | ACTIVE | N | N153-00-3/788 | Platform Invert - Station Building - Clapham North Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728759 | | |
| 16032 | ACTIVE | N | N153-00-3/788 | Platform Invert - Station Building - Clapham North Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Bitumen based, at ground level in front of door Sampled by 4-Rail Services 24/11/2023 - ID Report R740851 | | 4 | | | |
| 70543 | ACTIVE | N | N153-00-3/788 | Platform Invert - Station Building - Clapham North Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - total 4 no - With J Hangers throughout | | 4 | R728759 | | |
| 16033 | ACTIVE | N | N153-00-3/788 | Platform Invert - Station Building - Clapham North Stn | Isolator Switches | Asbestos | Removed | | | | Presumed rope seal within combination fuse switches flash guards replaced by new electrical boxes | | 2 | | | |
| 16039 | ACTIVE | N | N153-00-3/791 | Vent Shaft - Station Building - Clapham North Stn | Cable Duct: Other | Asbestos | Surveyed – Not Detected | | | | Cable Sleeves | | | | | |
| 16038 | ACTIVE | N | N153-00-3/791/CLG-01 | Ceiling: Solid - 1 - Vent Shaft - Station Building - Clapham North Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Concrete Caulking | | | | | |



Hazardous Material Asset Register - Summary



N153-00 - Station Building - Clapham North Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---------------------|-------------|------------|-------------|---------------------|-------------------|
| 16034 | ACTIVE | N | N153-00-3/791/WAL-001 | Wall: Internal - 1 - Vent Shaft - Station Building - Clapham North Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Concrete Caulking | | | | | |
| 16035 | ACTIVE | N | N153-00-3/791/WAL-002 | Wall: Internal - 2 - Vent Shaft - Station Building - Clapham North Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Concrete Caulking | | | | | |
| 16036 | ACTIVE | N | N153-00-3/791/WAL-003 | Wall: Internal - 3 - Vent Shaft - Station Building - Clapham North Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Concrete Caulking | | | | | |
| 18853 | ACTIVE | N | N153-00-3/791/WAL-004 | Wall: Internal - 4 - Vent Shaft - Station Building - Clapham North Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Concrete Caulking | | | | | |
| 16037 | ACTIVE | N | N153-00-3/791/WAL-005 | Wall: Internal - 5 - Vent Shaft - Station Building - Clapham North Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Concrete Caulking | | | | | |
| 11827 | ACTIVE | N | N153-00-A/081 | Lobby - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18814 | ACTIVE | N | N153-00-A/081 | Lobby - Station Building - Clapham North Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11828 | ACTIVE | N | N153-00-B/081 | Lobby - Station Building - Clapham North Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16040 | ACTIVE | N | N153-00-B/081 | Lobby - Station Building - Clapham North Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |

N155-00 - Station Building - Clapham Common Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---------------------|-------------|------------|-------------|---------------------|-------------------|
| 11829 | ACTIVE | N | N155-00-1/601 | Stairs: Linear - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15920 | ACTIVE | N | N155-00-1/601 | Stairs: Linear - Station Building - Clapham Common Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11830 | ACTIVE | N | N155-00-1/602 | Stairs: Linear - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15921 | ACTIVE | N | N155-00-1/602 | Stairs: Linear - Station Building - Clapham Common Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11831 | ACTIVE | N | N155-00-1/603 | Stairs: Linear - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N155-00 - Station Building - Clapham Common Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 15922 | ACTIVE | N | N155-00-1/603 | Stairs: Linear - Station Building - Clapham Common Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11832 | ACTIVE | N | N155-00-1/604 | Stairs: Linear - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15923 | ACTIVE | N | N155-00-1/604/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Clapham Common Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal above Metal Ceiling | | | | YES | |
| 11833 | ACTIVE | N | N155-00-1/605 | Stairs: Linear - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18803 | ACTIVE | N | N155-00-1/605 | Stairs: Linear - Station Building - Clapham Common Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11834 | ACTIVE | N | N155-00-2/001 | Booking Hall - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15924 | ACTIVE | N | N155-00-2/001/CLG-01 | Ceiling: Solid - 1 - Booking Hall - Station Building - Clapham Common Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above Metal Ceiling Tiles | | | R679638 | YES | |
| 18757 | ACTIVE | N | N155-00-2/001/FLR-01 | Floor - 1 - Booking Hall - Station Building - Clapham Common Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | 1x Bitumen duct under lifting cover - beneath false floor. Manhole keys and heavy lifting tools required to access. | | | | | YES |
| 11835 | ACTIVE | N | N155-00-2/011 | Ticket Office - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15926 | ACTIVE | N | N155-00-2/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Clapham Common Stn | Void | Asbestos | Surveyed – Not Detected | | | | Walls - Brick & Concrete above Fibreboard Ceiling | | | | YES | |
| 15925 | ACTIVE | N | N155-00-2/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Clapham Common Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete and Concrete Ducts beneath Computer Tiles | | | | | YES |
| 11836 | ACTIVE | N | N155-00-2/021 | POM - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15927 | ACTIVE | N | N155-00-2/021/FLR-01 | Floor - 1 - POM - Station Building - Clapham Common Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete beneath Computer Tiles | | | | | YES |
| 11837 | ACTIVE | N | N155-00-2/031 | Mess Room - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18758 | ACTIVE | N | N155-00-2/031 | Mess Room - Station Building - Clapham Common Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | | | | | | |
| 15929 | ACTIVE | N | N155-00-2/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Clapham Common Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above False Ceiling - Concrete, Plaster; Fibreglass Lagging; Breeze Block Walls | | | | YES | |



Hazardous Material Asset Register - Summary



N155-00 - Station Building - Clapham Common Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 15928 | ACTIVE | N | N155-00-2/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Clapham Common Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11838 | ACTIVE | N | N155-00-2/036 | Toilet: Unisex - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18759 | ACTIVE | N | N155-00-2/036/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Clapham Common Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Metal Ducting; Fibreglass Lagging - above Supalux Tiles | | | | YES | |
| 18804 | ACTIVE | N | N155-00-2/036/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Clapham Common Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11839 | ACTIVE | N | N155-00-2/071 | Circulation Area - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15930 | ACTIVE | N | N155-00-2/071/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Clapham Common Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above Metal Ceiling | | | R679638 | YES | |
| 11840 | ACTIVE | N | N155-00-2/081 | Lobby - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70706 | ACTIVE | N | N155-00-2/081 | Lobby - Station Building - Clapham Common Stn | | Lead Paint/Lead | Sampled – Not Detected | | | | Cream gloss to walls and conduits 0.24mm paint thickness <0.01% lead content Ceiling - Powder coated metal panels Door & door frame - factory varnish Skirting - ceramic tiles | | | | | |
| 15931 | ACTIVE | N | N155-00-2/081/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Clapham Common Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 15932 | ACTIVE | N | N155-00-2/081/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Clapham Common Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Fibreglass Lagging above Supalux Tiles | | | | YES | |
| 11841 | ACTIVE | N | N155-00-2/151 | UMC - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18760 | ACTIVE | N | N155-00-2/151 | UMC - Station Building - Clapham Common Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux & Supalux Boarding | | | | | |
| 15935 | ACTIVE | N | N155-00-2/151 | UMC - Station Building - Clapham Common Stn | Pipe Lagging | Asbestos | Surveyed – Not Detected | | | | Lagging & Cover to Thermometer | | | | | |
| 42050 | ACTIVE | N | N155-00-2/151 | UMC - Station Building - Clapham Common Stn | Isolator Switches | Asbestos | Sampled – Not Detected | | | | Rope (1m) to door of switch boxes x 2 NADIS | | 2 | | N | N |
| 42049 | ACTIVE | N | N155-00-2/151 | UMC - Station Building - Clapham Common Stn | Other Boarding | Asbestos | Presumed | | | | Siluminite component blocks within 6-way boxes (all boxes) - presumed asbestos materials within | | 4 | | N | N |



Hazardous Material Asset Register - Summary



N155-00 - Station Building - Clapham Common Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|------------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 42052 | ACTIVE | N | N155-00-2/151 | UMC - Station Building - Clapham Common Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer box - Presumed asbestos materials within | | 1 | | N | N |
| 42051 | ACTIVE | N | N155-00-2/151 | UMC - Station Building - Clapham Common Stn | Other Boarding | Asbestos | Presumed | | | | Siluminite component blocks within coil to 2KvA TX box. Presumed asbestos materials within. | | 1 | | N | N |
| 15933 | ACTIVE | N | N155-00-2/151 | UMC - Station Building - Clapham Common Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Red Oil Based Paint - 2no Girder to Housing Units. Thickness .13mm; Est Quantity 6 lm; Analysis 3.07% | | | | | |
| 15934 | ACTIVE | N | N155-00-2/151/FLR-01 | Floor - 1 - UMC - Station Building - Clapham Common Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Lid to Storage Bin | | | | | |
| 15936 | ACTIVE | N | N155-00-2/171 | Escalator Incline - Station Building - Clapham Common Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Adj Esc 3: Walls above hangers on incline - Supalux boxing | | | | | |
| 11842 | ACTIVE | N | N155-00-2/201 | Passage - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18761 | ACTIVE | N | N155-00-2/201 | Passage - Station Building - Clapham Common Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11843 | ACTIVE | N | N155-00-2/236 | Passage - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19958 | ACTIVE | N | N155-00-2/236/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Clapham Common Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete & Breeze Block above Fibreboard Ceiling | | | | YES | |
| 15937 | ACTIVE | N | N155-00-2/236/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Clapham Common Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Fibreboard Ceiling | | | | | |
| 18737 | ACTIVE | N | N155-00-2/236/FLR-01 | Floor - 1 - Passage - Station Building - Clapham Common Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete & Metal Trunking beneath Computer Tiles flooring | | | | | YES |
| 11844 | ACTIVE | N | N155-00-2/401 | Switch Room - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19346 | ACTIVE | N | N155-00-2/401 | Switch Room - Station Building - Clapham Common Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11845 | ACTIVE | N | N155-00-2/416 | Mess Room - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15938 | ACTIVE | N | N155-00-2/416/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Clapham Common Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Fibreglass Lagging above Supalux Tiles | | | | YES | |
| 18762 | ACTIVE | N | N155-00-2/416/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Clapham Common Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |



Hazardous Material Asset Register - Summary



N155-00 - Station Building - Clapham Common Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 11846 | ACTIVE | N | N155-00-2/417 | Toilet: Unisex - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15940 | ACTIVE | N | N155-00-2/417/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Clapham Common Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Fibreglass Lagging above Supalux Tiles | | | | YES | |
| 15939 | ACTIVE | N | N155-00-2/417/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Clapham Common Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11847 | ACTIVE | N | N155-00-2/418 | Cleaners Room - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15941 | ACTIVE | N | N155-00-2/418/CLG-01 | Ceiling: Suspended - 1 - Cleaners Room - Station Building - Clapham Common Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Fibreglass Lagging above Supalux Tiles | | | | YES | |
| 18763 | ACTIVE | N | N155-00-2/418/CLG-01 | Ceiling: Suspended - 1 - Cleaners Room - Station Building - Clapham Common Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11848 | ACTIVE | N | N155-00-2/451 | Tenancy - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15942 | ACTIVE | N | N155-00-2/451 | Tenancy - Station Building - Clapham Common Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Tenancy | | | | | |
| 11849 | ACTIVE | N | N155-00-2/661 | Equipment Room - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15943 | ACTIVE | N | N155-00-2/661 | Equipment Room - Station Building - Clapham Common Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11850 | ACTIVE | N | N155-00-2/662 | Switch Room - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42054 | ACTIVE | N | N155-00-2/662 | Switch Room - Station Building - Clapham Common Stn | Isolator Switches | Asbestos | Known | | | | Combination Fuse Switches - asbestos flash pad materials within | | 8 | | N | N |
| 15944 | ACTIVE | N | N155-00-2/662 | Switch Room - Station Building - Clapham Common Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Supalux Panels | | | | | |
| 42055 | ACTIVE | N | N155-00-2/662 | Switch Room - Station Building - Clapham Common Stn | Other Boarding | Asbestos | Presumed | | | | Siluminite component blocks within combination fuse switch - CFS to wall 1 | | 1 | | N | N |
| 42053 | ACTIVE | N | N155-00-2/662 | Switch Room - Station Building - Clapham Common Stn | Rope Seals | Asbestos | Sampled – Not Detected | | | | Rope (1m) to door of switch box | | | | N | N |
| 11851 | ACTIVE | N | N155-00-2/746 | SCR - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N155-00 - Station Building - Clapham Common Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|----------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 15945 | ACTIVE | N | N155-00-2/746 | SCR - Station Building - Clapham Common Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11852 | ACTIVE | N | N155-00-2/751 | Station Control Room - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70705 | ACTIVE | N | N155-00-2/751 | Station Control Room - Station Building - Clapham Common Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | White gloss paint on walls and conduits 0.37mm paint thickness < 0.01% lead content Ceiling - Powder coated metal panels Door & door frame - factory varnish Window frames - unpainted metal | | | R753401 | | |
| 18764 | ACTIVE | N | N155-00-2/751/CLG-01 | Ceiling: Solid - 1 - Station Control Room - Station Building - Clapham Common Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, PVC Cables & Metal Pipes above Metal Ceiling | | | | YES | |
| 19347 | ACTIVE | N | N155-00-2/751/FLR-01 | Floor - 1 - Station Control Room - Station Building - Clapham Common Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete & Metal Trunking - beneath Computer Tiles | | | | | YES |
| 11853 | ACTIVE | N | N155-00-2/762 | SVC - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15946 | ACTIVE | N | N155-00-2/762 | SVC - Station Building - Clapham Common Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11854 | ACTIVE | N | N155-00-2/901 | Disused Room - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18738 | ACTIVE | N | N155-00-2/901 | Disused Room - Station Building - Clapham Common Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding; Concrete | | | | | |
| 11855 | ACTIVE | N | N155-00-3/081 | Circulation Area - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15947 | ACTIVE | N | N155-00-3/081 | Circulation Area - Station Building - Clapham Common Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11856 | ACTIVE | N | N155-00-3/161 | LMC - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15948 | ACTIVE | N | N155-00-3/161 | LMC - Station Building - Clapham Common Stn | Cable Ducts: Bitumen | Asbestos | Surveyed – Not Detected | | | | Bitumen Cable Sleeves | | | | | |
| 20271 | ACTIVE | N | N155-00-3/161 | LMC - Station Building - Clapham Common Stn | | Asbestos | Sampled – Not Detected | | | | Boarding (0.25m2), high level, adjacent to Escalator no. 3 | | | | | |
| 20326 | ACTIVE | N | N155-00-3/161 | LMC - Station Building - Clapham Common Stn | Other Boarding | Asbestos | Sampled – Not Detected | | | | Boarding (est. 0.25m²), adjacent to Escalator no.3 at high level to concrete wall | | | | | |
| 18805 | ACTIVE | N | N155-00-3/161 | LMC - Station Building - Clapham Common Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Girder - Blue Oil Based Paint. Thickness .28mm; Est Quantity 4 lm; Analysis 3.47% | | | | | |



Hazardous Material Asset Register - Summary



N155-00 - Station Building - Clapham Common Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|----------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 15949 | ACTIVE | N | N155-00-3/161 | LMC - Station Building - Clapham Common Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Girder - Beige Oil Based Paint. Thickness .33mm; Est Quantity 10 lm; Analysis 21.87% | | | | | |
| 11857 | ACTIVE | N | N155-00-3/201 | Passage - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18765 | ACTIVE | N | N155-00-3/201 | Passage - Station Building - Clapham Common Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11858 | ACTIVE | N | N155-00-3/202 | Passage - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15950 | ACTIVE | N | N155-00-3/202/ FLR-01 | Floor - 1 - Passage - Station Building - Clapham Common Stn | Cable Ducts: Bitumen | Asbestos | Surveyed – Not Detected | | | | Bitumen Cable Sleeves beneath Tiled False Floor | | | | | YES |
| 15951 | ACTIVE | N | N155-00-3/202/ FLR-01 | Floor - 1 - Passage - Station Building - Clapham Common Stn | Cable Ducts: Bitumen | Asbestos | Surveyed – Not Detected | | | | Bitumen Cable Sleeves | | | | | YES |
| 11859 | ACTIVE | N | N155-00-3/237 | Passage - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11860 | ACTIVE | N | N155-00-3/238 | Passage - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18766 | ACTIVE | N | N155-00-3/238 | Passage - Station Building - Clapham Common Stn | Cable Ducts: Bitumen | Asbestos | Surveyed – Not Detected | | | | Bitumen Cable Sleeves | | | | | |
| 11861 | ACTIVE | N | N155-00-3/261 | Platform 1 - Northbound Local - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 46325 | ACTIVE | N | N155-00-3/261 | Platform 1 - Northbound Local - Station Building - Clapham Common Stn | Westing house Boxes | Asbestos | Presumed | | | | Electrical boxes at the end of island platform near metal stair case - Presumed to contain asbestos materials within | | 4 | | | |
| 46326 | ACTIVE | N | N155-00-3/261 | Platform 1 - Northbound Local - Station Building - Clapham Common Stn | Westing house Boxes | Asbestos | Presumed | | | | Small Westinghouse box to wall within invert | | 1 | | | |
| 18315 | ACTIVE | N | N155-00-3/261 | Platform 1 - Northbound Local - Station Building - Clapham Common Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 20mm Cables - Encapsulated | | 3 | | | |
| 15953 | ACTIVE | N | N155-00-3/261 | Platform 1 - Northbound Local - Station Building - Clapham Common Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 10mm Cables - Encapsulated | | 2 | | | |
| 15952 | ACTIVE | N | N155-00-3/261 | Platform 1 - Northbound Local - Station Building - Clapham Common Stn | Cable Ducts: Bitumen | Asbestos | Surveyed – Not Detected | | | | Bitumen Cable Sleeves | | | | | |
| 15954 | ACTIVE | N | N155-00-3/261/ FLR-01 | Floor - 1 - Platform 1 - Station Building - Clapham Common Stn | Isolator Switches | Asbestos | Presumed | | | | Invert Tail Wall - 1x Flash Guard left hand side wall Switch Box | | 1 | | | YES |



Hazardous Material Asset Register - Summary



N155-00 - Station Building - Clapham Common Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-------------------------------|--|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 15955 | ACTIVE | N | N155-00-3/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Clapham Common Stn | Cable: Sheath | Asbestos | Presumed | | | | Invert adjacent to markers 110. 4x Textile cable in wood box Encapsulated. This is the same as record 15962. Two entries to cover Platform 1&2 | | | | | YES |
| 18806 | ACTIVE | N | N155-00-3/261/FLR-01 80900137 | Floor - 1 - Platform 1 - Station Building - Clapham Common Stn Floor | Cable Ducts: Cement | Asbestos | Known | | | | Invert 4x Cable ducts - under stairs 3/576. This is the same as record 15961. Two entries to cover Platform 1&2 | | | | | YES |
| 18767 | ACTIVE | N | N155-00-3/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Clapham Common Stn | Cement Troughing | Asbestos | Known | | | | Invert under stairs 3/576. 24Lm Cable troughing - floor, under stairs running towards tail wall left hand side wall & head wall right hand side wall | | | | | YES |
| 11862 | ACTIVE | N | N155-00-3/262 | Platform 2 - Southbound Local - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15956 | ACTIVE | N | N155-00-3/262 | Platform 2 - Southbound Local - Station Building - Clapham Common Stn | Cable Ducts: Bitumen | Asbestos | Surveyed – Not Detected | | | | Bitumen Cable Sleeves | | | | | |
| 15957 | ACTIVE | N | N155-00-3/262 | Platform 2 - Southbound Local - Station Building - Clapham Common Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 20mm Cables - Encapsulated | | 3 | | | |
| 15958 | ACTIVE | N | N155-00-3/262 | Platform 2 - Southbound Local - Station Building - Clapham Common Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 10mm Cables - Encapsulated | | 2 | | | |
| 15961 | ACTIVE | N | N155-00-3/262/FLR-01 80900147 | Floor - 1 - Platform 2 - Station Building - Clapham Common Stn Floor | Cable Ducts: Cement | Asbestos | Known | | | | Invert 4x Cable ducts - under stairs 3/576. This is the same as record 18806. Two entries to cover Platform 1&2 | | | | | YES |
| 15959 | ACTIVE | N | N155-00-3/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Clapham Common Stn | Cement Troughing | Asbestos | Known | | | | Invert under stairs 3/576. 24Lm Cable troughing - floor, under stairs running towards tail wall left hand side wall & head wall right hand side wall. (Island platform - reference is also under Platform 1 - 18767) | | | | | YES |
| 15960 | ACTIVE | N | N155-00-3/262/FLR-01 80900147 | Floor - 1 - Platform 2 - Station Building - Clapham Common Stn Floor | Isolator Switches | Asbestos | Presumed | | | | Electrical boxes at end of island platform - Presumed asbestos materials within. | | 4 | | | YES |
| 15962 | ACTIVE | N | N155-00-3/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Clapham Common Stn | Cable: Sheath | Asbestos | Presumed | | | | Invert adjacent to markers 110. 4x Textile cable in wood box Encapsulated. This is the same as record 15955. Two entries to cover Platform 1&2 | | | | | YES |
| 11863 | ACTIVE | N | N155-00-3/281 | Switch Room - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11864 | ACTIVE | N | N155-00-3/331 | Locker Room - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18768 | ACTIVE | N | N155-00-3/331/CLG-01 | Ceiling: Solid - 1 - Locker Room - Station Building - Clapham Common Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above Plaster Ceiling | | | | YES | |



Hazardous Material Asset Register - Summary



N155-00 - Station Building - Clapham Common Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|------------------------|---|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 11865 | ACTIVE | N | N155-00-3/406 | Store - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11866 | ACTIVE | N | N155-00-3/576 | Stairs: Linear - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11867 | ACTIVE | N | N155-00-3/601 | Stairs: Linear - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11868 | ACTIVE | N | N155-00-3/661 | Disused Room - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15963 | ACTIVE | N | N155-00-3/661/CLG-01 | Ceiling: Solid - 1 - Disused Room - Station Building - Clapham Common Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above Tiles | | | | YES | |
| 11869 | ACTIVE | N | N155-00-3/711 | Relay Room - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18769 | ACTIVE | N | N155-00-3/711 80143198 | Relay Room - Station Building - Clapham Common Stn Room Assets | Westing house Boxes | Asbestos | Strongly Presumed | | | | 2 x Westinghouse Boxes to Metal caged area Externally - asbestos materials within | | 2 | | | |
| 18316 | ACTIVE | N | N155-00-3/711 80143198 | Relay Room - Station Building - Clapham Common Stn Room Assets | Other Electrical Boxes | Asbestos | Presumed | | | | Tranformer Boxes to Metal caged area Externally - asbestos materials within | | 2 | | | |
| 54034 | ACTIVE | N | N155-00-3/711 | Relay Room - Station Building - Clapham Common Stn | Other Boarding | Asbestos | Removed | | | | Paxoline boarding x1 - sampled R732251 confirmed asbestos Brown board next to rack 7 | | | R732251 | | |
| 44320 | ACTIVE | N | N155-00-3/711 | Relay Room - Station Building - Clapham Common Stn | Cable: Wrap | Asbestos | Removed | | | | Cable Wrap | | | | | |
| 15965 | ACTIVE | N | N155-00-3/711 | Relay Room - Station Building - Clapham Common Stn | Cable: Sheath | Asbestos | Removed | | | | 20mm Cables - Encapsulated | | 3 | | | |
| 54037 | ACTIVE | N | N155-00-3/711 | Relay Room - Station Building - Clapham Common Stn | Other Boarding | Asbestos | Removed | | | | Paxoline boarding x1 - sampled R732251 confirmed asbestos Brown board to wall 4 in front of main door | | | R732251 | | |
| 15966 | ACTIVE | N | N155-00-3/711 | Relay Room - Station Building - Clapham Common Stn | Cable: Sheath | Asbestos | Removed | | | | 10mm Cables - Encapsulated | | 2 | | | |
| 54036 | ACTIVE | N | N155-00-3/711 | Relay Room - Station Building - Clapham Common Stn | Other Boarding | Asbestos | Removed | | | | Paxoline boarding x1 - sampled R732251 confirmed asbestos Brown board on the rack on the floor | | | R732251 | | |
| 54038 | ACTIVE | N | N155-00-3/711 | Relay Room - Station Building - Clapham Common Stn | Bitumen | Asbestos | Sampled – Not Detected | | | | glue to walls | | | R732251 | | |
| 44321 | ACTIVE | N | N155-00-3/711 | Relay Room - Station Building - Clapham Common Stn | Other Boarding | Asbestos | Removed | | | | Paxoline boarding x1 - sampled R732251 confirmed asbestos Brown Board to rack 1 on wall 3 | | | | | |
| 15964 | ACTIVE | N | N155-00-3/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Clapham Common Stn | Vinyl tiles | Asbestos | Known | | | | Green Vinyl Tiles - All Walls - Chrysotile - Some have been removed | | | | | |



Hazardous Material Asset Register - Summary



N155-00 - Station Building - Clapham Common Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 11870 | ACTIVE | N | N155-00-3/731 | CER - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15967 | ACTIVE | N | N155-00-3/731/ FLR-01 | Floor - 1 - CER - Station Building - Clapham Common Stn | Void | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | YES |
| 11871 | ACTIVE | N | N155-00-4/121 | Platform Invert - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70596 | ACTIVE | N | N155-00-4/121 | Platform Invert - Station Building - Clapham Common Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 1 no - To floor right hand side where passage falls | | 1 | R728760 | N | Y |
| 18807 | ACTIVE | N | N155-00-4/121 | Platform Invert - Station Building - Clapham Common Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 70587 | ACTIVE | N | N155-00-4/121 | Platform Invert - Station Building - Clapham Common Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Link box - total 1 no - To wall to both trackside walls (north end) | | 1 | R728760 | | |
| 70585 | ACTIVE | N | N155-00-4/121 | Platform Invert - Station Building - Clapham Common Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 2 no 6m - To both trackside walls (north end) | 6 | 2 | R728760 | N | Y |
| 70580 | ACTIVE | N | N155-00-4/121 | Platform Invert - Station Building - Clapham Common Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728760 | | |
| 70594 | ACTIVE | N | N155-00-4/121 | Platform Invert - Station Building - Clapham Common Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Link box - total 1 no - By cable run left hand side near 4/662 | | 1 | R728760 | | |
| 70593 | ACTIVE | N | N155-00-4/121 | Platform Invert - Station Building - Clapham Common Stn | Boarding / Panels | Asbestos | Sampled – Not Detected | | | | Platform Invert - Woodite (cement/ wood) panels - total 3 no 2m2 - To walls 4/122 and south rows above door | 2 | 3 | R728760 | N | Y |
| 70592 | ACTIVE | N | N155-00-4/121 | Platform Invert - Station Building - Clapham Common Stn | Boarding / Panels | Asbestos | Presumed | | | | Platform Invert - Black composite panel - total 1 no - Within wooden electrical box - live no possible to sample | | 1 | R728760 | | |
| 70591 | ACTIVE | N | N155-00-4/121 | Platform Invert - Station Building - Clapham Common Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts loose debris - total 1 no <1m - To floor in first arch right hand side | 1 | 1 | R728760 | N | Y |
| 70589 | ACTIVE | N | N155-00-4/121 | Platform Invert - Station Building - Clapham Common Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 4 no - Within concrete cable slab by access steps | | 4 | R728760 | N | Y |
| 70584 | ACTIVE | N | N155-00-4/121 | Platform Invert - Station Building - Clapham Common Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728760 | | |
| 70586 | ACTIVE | N | N155-00-4/121 | Platform Invert - Station Building - Clapham Common Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement cable ducts - total 2 no 4m - To ceiling to both trackside walls (north end) | 4 | 2 | R728760 | N | Y |
| 11872 | ACTIVE | N | N155-00-4/122 | Platform Invert - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15968 | ACTIVE | N | N155-00-4/122 | Platform Invert - Station Building - Clapham Common Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N155-00 - Station Building - Clapham Common Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 11873 | ACTIVE | N | N155-00-4/123 | Platform Invert - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70598 | ACTIVE | N | N155-00-4/123 | Platform Invert - Station Building - Clapham Common Stn | Gasket :Pipework | Asbestos | Known | | | | Platform Invert - Compressed asbestos fibre gasket (red - total 1 no throughout - To end flange of pipework | | 1 | R728760 | N | Y |
| 18739 | ACTIVE | N | N155-00-4/123 | Platform Invert - Station Building - Clapham Common Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 70597 | ACTIVE | N | N155-00-4/123 | Platform Invert - Station Building - Clapham Common Stn | Isolator Switches | Asbestos | Presumed | | | | Platform Invert - Combination fuse switch - total 1 no - To cable run right hand side by 4/781 | | 1 | R728760 | N | Y |
| 70602 | ACTIVE | N | N155-00-4/123 | Platform Invert - Station Building - Clapham Common Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable duct - total 6 no - To ceiling by CAT ladder | | 6 | R728760 | N | Y |
| 70604 | ACTIVE | N | N155-00-4/123 | Platform Invert - Station Building - Clapham Common Stn | Boarding / Panels | Asbestos | Sampled – Not Detected | | | | Platform Invert - Woodite (cement/ wood) panels - total 2m2 - To wall by 4/781 | 2 | | R728760 | N | Y |
| 70583 | ACTIVE | N | N155-00-4/123 | Platform Invert - Station Building - Clapham Common Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728760 | | |
| 70579 | ACTIVE | N | N155-00-4/123 | Platform Invert - Station Building - Clapham Common Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728760 | | |
| 70599 | ACTIVE | N | N155-00-4/123 | Platform Invert - Station Building - Clapham Common Stn | Isolator Switches | Asbestos | Presumed | | | | Platform Invert - Combination fuse switch - total 1 no - To floor right hand side by 4/781 | | 1 | R728760 | N | Y |
| 70601 | ACTIVE | N | N155-00-4/123 | Platform Invert - Station Building - Clapham Common Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable duct - total 2 no 9m - To both trackside walls by CAT ladder | 9 | 2 | R728760 | N | Y |
| 11874 | ACTIVE | N | N155-00-4/661 | Switch Cupboard - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15969 | ACTIVE | N | N155-00-4/661 | Switch Cupboard - Station Building - Clapham Common Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11875 | ACTIVE | N | N155-00-4/662 | Switch Room - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15970 | ACTIVE | N | N155-00-4/662 | Switch Room - Station Building - Clapham Common Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11876 | ACTIVE | N | N155-00-4/663 | Switch Room - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18770 | ACTIVE | N | N155-00-4/663 | Switch Room - Station Building - Clapham Common Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11877 | ACTIVE | N | N155-00-4/664 | Switch Cupboard - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N155-00 - Station Building - Clapham Common Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 15971 | ACTIVE | N | N155-00-4/664 | Switch Cupboard - Station Building - Clapham Common Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11878 | ACTIVE | N | N155-00-4/771 | Plant Room - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15972 | ACTIVE | N | N155-00-4/771 | Plant Room - Station Building - Clapham Common Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11879 | ACTIVE | N | N155-00-4/781 | Transformer Room - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18808 | ACTIVE | N | N155-00-4/781 | Transformer Room - Station Building - Clapham Common Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access via invert | | | | | |
| 11880 | ACTIVE | N | N155-00-4/782 | Transformer Room - Station Building - Clapham Common Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15973 | ACTIVE | N | N155-00-4/782 | Transformer Room - Station Building - Clapham Common Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access via invert | | | | | |

N163-00 - Station Building - Clapham South Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 11881 | ACTIVE | N | N163-00-1/001 | Booking Hall - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15861 | ACTIVE | N | N163-00-1/001 | Booking Hall - Station Building - Clapham South Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11882 | ACTIVE | N | N163-00-1/011 | Ticket Office - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15863 | ACTIVE | N | N163-00-1/011/CLG-01 | Ceiling: Solid - 1 - Ticket Office - Station Building - Clapham South Stn | Void | Asbestos | Surveyed – Not Detected | | | | Wood, Fibreglass Lagging above Supalux ceiling | | | | YES | |
| 15862 | ACTIVE | N | N163-00-1/011/CLG-01 | Ceiling: Solid - 1 - Ticket Office - Station Building - Clapham South Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Ceiling | | | | | |
| 18676 | ACTIVE | N | N163-00-1/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Clapham South Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Wooden false floor | | | | | YES |
| 11883 | ACTIVE | N | N163-00-1/021 | POM - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15864 | ACTIVE | N | N163-00-1/021/FLR-01 | Floor - 1 - POM - Station Building - Clapham South Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Wooden false floor | | | | | YES |



Hazardous Material Asset Register - Summary



N163-00 - Station Building - Clapham South Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 11884 | ACTIVE | N | N163-00-1/031 | Mess Room - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15865 | ACTIVE | N | N163-00-1/031 | Mess Room - Station Building - Clapham South Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater Insulation Board Foam | | | | | |
| 15866 | ACTIVE | N | N163-00-1/031/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Clapham South Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Tiles | | | | YES | |
| 18677 | ACTIVE | N | N163-00-1/031/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Clapham South Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles Ceiling | | | | | |
| 11885 | ACTIVE | N | N163-00-1/036 | Lobby - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15867 | ACTIVE | N | N163-00-1/036 | Lobby - Station Building - Clapham South Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11886 | ACTIVE | N | N163-00-1/037 | Toilet: Unisex - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15868 | ACTIVE | N | N163-00-1/037 | Toilet: Unisex - Station Building - Clapham South Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding | | | | | |
| 11887 | ACTIVE | N | N163-00-1/071 | Circulation Area - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15869 | ACTIVE | N | N163-00-1/071/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Clapham South Stn | Glazing Rope | Asbestos | Strongly Presumed | | | | Rope Seal on Glass Ceiling x2 to ceiling Re-inspected 03-03-2023 | | | | | |
| 11888 | ACTIVE | N | N163-00-1/151 | UMC - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15761 | ACTIVE | N | N163-00-1/151 | UMC - Station Building - Clapham South Stn | Durasteel | Asbestos | Presumed | | | | Durasteel Panel above door to 2/733 Re-inspected 03-03-2023 | | | | | |
| 18249 | ACTIVE | N | N163-00-1/151 | UMC - Station Building - Clapham South Stn | Gasket :Pipework | Asbestos | Presumed | | | | Gaskets to Fan Equipment - None Visible - P No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within. | | | | | |
| 15762 | ACTIVE | N | N163-00-1/151 | UMC - Station Building - Clapham South Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Red Oil Based Paint - Pipework. Thickness .11mm; Est Quantity 60lm; Analysis 4.04% | | | | | |
| 15764 | ACTIVE | N | N163-00-1/151 | UMC - Station Building - Clapham South Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Red Oil Based Paint - 2no Girder to Housing Unit. Thickness .41mm; Est Quantity 4lm; Analysis 12.52% | | | | | |
| 15763 | ACTIVE | N | N163-00-1/151 | UMC - Station Building - Clapham South Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Yellow Oil Based Paint - Stairs. Thickness .38mm; Est Quantity 4sqm; Analysis 1.68% | | | | | |



Hazardous Material Asset Register - Summary



N163-00 - Station Building - Clapham South Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------------------|---|------------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18516 | ACTIVE | N | N163-00-1/151 | UMC - Station Building - Clapham South Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Grey Oil Based Paint - Girder. Thickness .21mm; Est Quantity 5lm; Analysis 1.29% Overpainted with yellow up to head high | | | | | |
| 18667 | ACTIVE | N | N163-00-1/151/CLG-01 | Ceiling: Solid - 1 - UMC - Station Building - Clapham South Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Concrete, Supalux | | | | | |
| 18678 | ACTIVE | N | N163-00-1/151/FLR-01 | Floor - 1 - UMC - Station Building - Clapham South Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Lid to Storage Bin | | | | | |
| 15759 | ACTIVE | N | N163-00-1/151/WAL-001 | Wall: Internal - 1 - UMC - Station Building - Clapham South Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box(es) No electrician present during 2023 reinspection to open electrical equipment. | | 1 | | | |
| 15758 | ACTIVE | N | N163-00-1/151/WAL-002 | Wall: Internal - 2 - UMC - Station Building - Clapham South Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 2 x 60amp, 1 x 30amp & 1 x 100amp Switch Boxes - Insulation within No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within. | | 4 | | | |
| 15760 | INACTIVE | N | N163-00-1/151/WAL-003 80891831 | Wall: Internal - 3 - UMC - Station Building - Clapham South Stn Wall: Internal | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box(es) in twice 10/3/2016 with 15759 | | 1 | | | |
| 15765 | ACTIVE | N | N163-00-1/171 | Escalator Incline - Station Building - Clapham South Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access | | | | | |
| 11889 | ACTIVE | N | N163-00-1/236 | Passage - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15766 | ACTIVE | N | N163-00-1/236/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Clapham South Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 18728 | ACTIVE | N | N163-00-1/236/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Clapham South Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11890 | ACTIVE | N | N163-00-1/237 | Lobby - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18517 | ACTIVE | N | N163-00-1/237 | Lobby - Station Building - Clapham South Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11891 | ACTIVE | N | N163-00-1/238 | Lobby - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15768 | ACTIVE | N | N163-00-1/238/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Clapham South Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 15767 | ACTIVE | N | N163-00-1/238/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Clapham South Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |



Hazardous Material Asset Register - Summary



N163-00 - Station Building - Clapham South Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 11892 | ACTIVE | N | N163-00-1/239 | Lobby - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18518 | ACTIVE | N | N163-00-1/239/FLR-01 | Floor - 1 - Lobby - Station Building - Clapham South Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Wooden false floor | | | | | YES |
| 11893 | ACTIVE | N | N163-00-1/301 | Locker Room - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15769 | ACTIVE | N | N163-00-1/301 | Locker Room - Station Building - Clapham South Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding | | | | | |
| 11894 | ACTIVE | N | N163-00-1/331 | Mess Room - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15770 | ACTIVE | N | N163-00-1/331/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Clapham South Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 15771 | ACTIVE | N | N163-00-1/331/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Clapham South Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 11895 | ACTIVE | N | N163-00-1/416 | Toilet: Female - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15772 | ACTIVE | N | N163-00-1/416/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Clapham South Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18584 | ACTIVE | N | N163-00-1/416/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Clapham South Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 11896 | ACTIVE | N | N163-00-1/417 | Toilet: Male - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15774 | ACTIVE | N | N163-00-1/417/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Clapham South Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 15773 | ACTIVE | N | N163-00-1/417/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Clapham South Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11897 | ACTIVE | N | N163-00-1/451 | Tenancy - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19954 | ACTIVE | N | N163-00-1/451/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - Clapham South Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |



Hazardous Material Asset Register - Summary



N163-00 - Station Building - Clapham South Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 15775 | ACTIVE | N | N163-00-1/451/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - Clapham South Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Tiles | | | | YES | |
| 11898 | ACTIVE | N | N163-00-1/452 | Tenancy - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15776 | ACTIVE | N | N163-00-1/452 | Tenancy - Station Building - Clapham South Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11899 | ACTIVE | N | N163-00-1/453 | Tenancy - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18585 | ACTIVE | N | N163-00-1/453 | Tenancy - Station Building - Clapham South Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11900 | ACTIVE | N | N163-00-1/661 | Switch Room - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15778 | ACTIVE | N | N163-00-1/661/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Clapham South Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18586 | ACTIVE | N | N163-00-1/661/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Clapham South Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Tiles | | | | YES | |
| 15777 | ACTIVE | N | N163-00-1/661/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Clapham South Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes 4 x Grey 60amp & 3 x Blue 100amp & 2 x 60amp - Insulation within No electrician present during 2023 reinspection to open. | | 9 | | | |
| 15779 | ACTIVE | N | N163-00-1/661/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Clapham South Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Transformer Box(es) No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 11901 | ACTIVE | N | N163-00-1/662 | Switch Room - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15780 | ACTIVE | N | N163-00-1/662/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Clapham South Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Tiles | | | | YES | |
| 18587 | ACTIVE | N | N163-00-1/662/CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Clapham South Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 15781 | ACTIVE | N | N163-00-1/662/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Clapham South Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Transformer Box(es) No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |



Hazardous Material Asset Register - Summary



N163-00 - Station Building - Clapham South Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 19950 | ACTIVE | N | N163-00-1/662/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Clapham South Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes 4 x Grey 60amp & 3 x Blue 100amp & 2 x 60amp - Insulation within No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within. | | 9 | | | |
| 19481 | ACTIVE | N | N163-00-1/662/WAL-004 | Wall: Internal - 4 - Switch Room - Station Building - Clapham South Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Transformer Box(es), 1x combination fuse switch to wall 4 - photo DSC05499 No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within. | | 3 | | | |
| 11902 | ACTIVE | N | N163-00-1/746 | SCR - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18730 | ACTIVE | N | N163-00-1/746 | SCR - Station Building - Clapham South Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11903 | ACTIVE | N | N163-00-1/751 | Station Control Room - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18588 | ACTIVE | N | N163-00-1/751/CLG-01 | Ceiling: Solid - 1 - Station Control Room - Station Building - Clapham South Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Strip; Supalux Boarding | | | | YES | |
| 15782 | ACTIVE | N | N163-00-1/751/FLR-01 | Floor - 1 - Station Control Room - Station Building - Clapham South Stn | Void | Asbestos | No Access: Presumed | | | | Beneath false Wooden Floor | | | | | YES |
| 11904 | ACTIVE | N | N163-00-1/761 | SVC - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15783 | ACTIVE | N | N163-00-1/761 | SVC - Station Building - Clapham South Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11905 | ACTIVE | N | N163-00-1/776 | Plant Room - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15784 | ACTIVE | N | N163-00-1/776/FLR-01 | Floor - 1 - Plant Room - Station Building - Clapham South Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Wooden Floor | | | | | YES |
| 11906 | ACTIVE | N | N163-00-1/901 | Yard - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15785 | ACTIVE | N | N163-00-1/901 | Yard - Station Building - Clapham South Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11907 | ACTIVE | N | N163-00-1/951 | Void - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N163-00 - Station Building - Clapham South Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 15786 | ACTIVE | N | N163-00-1/951 | Void - Station Building - Clapham South Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | | | | | | |
| 11908 | ACTIVE | N | N163-00-1/952 | Bin Store - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15787 | ACTIVE | N | N163-00-1/952 | Bin Store - Station Building - Clapham South Stn | Gasket :Pipework | Asbestos | Presumed | | | | Gaskets to Pipework | | | | | |
| 18589 | ACTIVE | N | N163-00-1/952 | Bin Store - Station Building - Clapham South Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Red Oil Based Paint - Stand. Thickness .05mm; Est Quantity 1 lm; Analysis 2.72% | | | | | |
| 11909 | ACTIVE | N | N163-00-2/081 | Circulation Area - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15788 | ACTIVE | N | N163-00-2/081 | Circulation Area - Station Building - Clapham South Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11910 | ACTIVE | N | N163-00-2/161 | LMC - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15789 | ACTIVE | N | N163-00-2/161 | LMC - Station Building - Clapham South Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11911 | ACTIVE | N | N163-00-2/201 | Passage - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15790 | ACTIVE | N | N163-00-2/201 | Passage - Station Building - Clapham South Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11912 | ACTIVE | N | N163-00-2/202 | Passage - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15791 | ACTIVE | N | N163-00-2/202 | Passage - Station Building - Clapham South Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11913 | ACTIVE | N | N163-00-2/203 | Passage - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18590 | ACTIVE | N | N163-00-2/203 | Passage - Station Building - Clapham South Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11914 | ACTIVE | N | N163-00-2/204 | Passage - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15792 | ACTIVE | N | N163-00-2/204 | Passage - Station Building - Clapham South Stn | | Asbestos | Surveyed – Not Detected | | | | | | | | | |
| 11915 | ACTIVE | N | N163-00-2/261 | Platform 1 - Northbound Local - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N163-00 - Station Building - Clapham South Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 70522 | ACTIVE | N | N163-00-2/261 | Platform 1 - Northbound Local - Station Building - Clapham South Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 4 no - To platform wall | | 4 | R728758 | N | Y |
| 70519 | ACTIVE | N | N163-00-2/261 | Platform 1 - Northbound Local - Station Building - Clapham South Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728758 | | |
| 70521 | ACTIVE | N | N163-00-2/261 | Platform 1 - Northbound Local - Station Building - Clapham South Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - total 4 no - To J Hangers throughout | | 4 | R728758 | | |
| 70518 | ACTIVE | N | N163-00-2/261 | Platform 1 - Northbound Local - Station Building - Clapham South Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728758 | | |
| 70520 | ACTIVE | N | N163-00-2/261 | Platform 1 - Northbound Local - Station Building - Clapham South Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 2 no - To trackside wall - arrivals end | | 2 | R728758 | N | Y |
| 70525 | ACTIVE | N | N163-00-2/261 | Platform 1 - Northbound Local - Station Building - Clapham South Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 8 no - To trackside wall - departures end | | 8 | R728758 | N | Y |
| 70524 | ACTIVE | N | N163-00-2/261 | Platform 1 - Northbound Local - Station Building - Clapham South Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Materials within small Westinghouse box - total 1 no - To platform wall, midway | | 1 | R728758 | | |
| 70523 | ACTIVE | N | N163-00-2/261 | Platform 1 - Northbound Local - Station Building - Clapham South Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts-total 4 no - To platform wall | | 4 | R728758 | N | Y |
| 15793 | ACTIVE | N | N163-00-2/261/ FLR-01 | Floor - 1 - Platform 1 - Station Building - Clapham South Stn | Cable: Sheath | Asbestos | No Access: Presumed | | | | Braided Cable 100m long | | | | | YES |
| 18729 | ACTIVE | N | N163-00-2/261/ FLR-01 | Floor - 1 - Platform 1 - Station Building - Clapham South Stn | Debris: Cement | Asbestos | Strongly Presumed | | | | Platform 1 Invert - Asbestos Cement Debris | | | | | YES |
| 11916 | ACTIVE | N | N163-00-2/262 | Platform 2 - Southbound Local - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70526 | ACTIVE | N | N163-00-2/262 | Platform 2 - Southbound Local - Station Building - Clapham South Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728758 | | |
| 70532 | ACTIVE | N | N163-00-2/262 | Platform 2 - Southbound Local - Station Building - Clapham South Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Materials within small Westinghouse box - total 1 no - To trackside wall, midway | | 1 | R728758 | | |
| 70531 | ACTIVE | N | N163-00-2/262 | Platform 2 - Southbound Local - Station Building - Clapham South Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 8 no - To platform wall near departure end | | 8 | R728758 | N | Y |
| 70530 | ACTIVE | N | N163-00-2/262 | Platform 2 - Southbound Local - Station Building - Clapham South Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 8 no - To platform wall near departure end | | 8 | R728758 | N | Y |



Hazardous Material Asset Register - Summary



N163-00 - Station Building - Clapham South Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18731 | ACTIVE | N | N163-00-2/262 | Platform 2 - Southbound Local - Station Building - Clapham South Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels inside Fire Point | | | | | |
| 70533 | ACTIVE | N | N163-00-2/262 | Platform 2 - Southbound Local - Station Building - Clapham South Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Materials within small Westinghouse box - total 1 no - To platform wall, midway | | 1 | R728758 | | |
| 70534 | ACTIVE | N | N163-00-2/262 | Platform 2 - Southbound Local - Station Building - Clapham South Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 8 no - To trackside wall arrivals end | | 8 | R728758 | N | Y |
| 70527 | ACTIVE | N | N163-00-2/262 | Platform 2 - Southbound Local - Station Building - Clapham South Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728758 | | |
| 70529 | ACTIVE | N | N163-00-2/262 | Platform 2 - Southbound Local - Station Building - Clapham South Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - total 8 no - To J Hangers throughout | | 8 | R728758 | | |
| 70528 | ACTIVE | N | N163-00-2/262 | Platform 2 - Southbound Local - Station Building - Clapham South Stn | Cable Wrap | Asbestos | Known | | | | Platform Invert - Cable wrapping - total 1 no <1m - To cable trackside wall at departure end | 1 | 1 | R728758 | | |
| 18591 | ACTIVE | N | N163-00-2/262/ FLR-01 | Floor - 1 - Platform 2 - Station Building - Clapham South Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 2 Invert - Braided Cable 10m long | | | | | YES |
| 11917 | ACTIVE | N | N163-00-2/406 | Switch Room - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15794 | ACTIVE | N | N163-00-2/406 | Switch Room - Station Building - Clapham South Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11918 | ACTIVE | N | N163-00-2/661 | Switch Room - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15795 | ACTIVE | N | N163-00-2/661 | Switch Room - Station Building - Clapham South Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11919 | ACTIVE | N | N163-00-2/663 | Switch Room - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15796 | ACTIVE | N | N163-00-2/663/ CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Clapham South Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | | | | | | |
| 15797 | ACTIVE | N | N163-00-2/663/ CLG-01 | Ceiling: Suspended - 1 - Switch Room - Station Building - Clapham South Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Ceiling | | | | YES | |
| 11920 | ACTIVE | N | N163-00-2/664 | Switch Room - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15798 | ACTIVE | N | N163-00-2/664 | Switch Room - Station Building - Clapham South Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard Panel above Entrance | | | | | |



Hazardous Material Asset Register - Summary



| N163-00 - Station Building - Clapham South Stn | | | | | | | | | | | | | | | | |
|--|--------|-------------|-----------------------|--|---------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
| 11921 | ACTIVE | N | N163-00-2/665 | Switch Room - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18592 | ACTIVE | N | N163-00-2/665 | Switch Room - Station Building - Clapham South Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard Panel above Entrance | | | | | |
| 11922 | ACTIVE | N | N163-00-2/666 | Switch Cupboard - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15799 | ACTIVE | N | N163-00-2/666 | Switch Cupboard - Station Building - Clapham South Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11923 | ACTIVE | N | N163-00-2/667 | Switch Cupboard - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15800 | ACTIVE | N | N163-00-2/667 | Switch Cupboard - Station Building - Clapham South Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11924 | ACTIVE | N | N163-00-2/711 | Relay Room - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18594 | ACTIVE | N | N163-00-2/711 | Relay Room - Station Building - Clapham South Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 10mm / 20mm Cables on lower cable run, to wall 1. 1x cable running to invert (wall 2) and 2x cables running to track (wall 3) Re-inspected 03-03-2023 | | 2 | | | |
| 53549 | ACTIVE | N | N163-00-2/711 | Relay Room - Station Building - Clapham South Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | brown board to new rely on top of dot matrix - NEW - wall 3 | | | | | |
| 15801 | ACTIVE | N | N163-00-2/711 | Relay Room - Station Building - Clapham South Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux board, 2no x 0.1m2, to firestop on top of duct to floor by walls 2 and 3 in IMR 2/711. Note no access to duct due to live cables and Supalux firestop on top | | | | | |
| 15804 | ACTIVE | N | N163-00-2/711/CLG-01 | Ceiling: Solid - 1 - Relay Room - Station Building - Clapham South Stn | Vinyl tiles | Asbestos | Known | | | | Vinyl Tiles. Most tiles removed , still in place behind racking and equipment Re-inspected 03-03-2023 | | | | | |
| 15808 | ACTIVE | N | N163-00-2/711/FLR-01 | Floor - 1 - Relay Room - Station Building - Clapham South Stn | Cable Ducts: Cement | Asbestos | Surveyed – Not Detected | | | | Ducts (porcelain VC) non asbestos - with supalux panel to front | | | | | |
| 18595 | ACTIVE | N | N163-00-2/711/FLR-01 | Floor - 1 - Relay Room - Station Building - Clapham South Stn | Boarding: Cement | Asbestos | Sampled – Not Detected | | | | Floor (right hand side) damaged Cement Board over Ducts board is supalux ref report : R616801 | | | | | |
| 53547 | ACTIVE | N | N163-00-2/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Clapham South Stn | Other Boarding | Asbestos | Presumed | | | | composite boarding x6 to equipment bottom shelf of rack wall 1 Re-inspection 03-03-2023 | | | | | |
| 15809 | ACTIVE | N | N163-00-2/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Clapham South Stn | Boarding: Cement | Asbestos | Presumed | | | | Cement panel under equipment to top shelf of rack on wall 1 Re-inspected 03-03-2023 | | | | | |



Hazardous Material Asset Register - Summary



N163-00 - Station Building - Clapham South Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|------------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 44318 | ACTIVE | N | N163-00-2/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Clapham South Stn | Other Boarding | Asbestos | Presumed | | | | brown composite boarding to rack equipment top shelf wall 1 x5 Re-inspected 03-03-2023 | | | | | |
| 18593 | ACTIVE | N | N163-00-2/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Clapham South Stn | Vinyl tiles | Asbestos | Known | | | | Vinyl Tiles. most tiles removed still in place behind racks and equipment Re-inspected 03-03-2023 | | | | | |
| 19482 | INACTIVE | N | N163-00-2/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Clapham South Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | Westinghouse Box In twice see 15807 | | 1 | | | |
| 44903 | INACTIVE | N | N163-00-2/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Clapham South Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box | | 1 | | N | N |
| 15807 | ACTIVE | N | N163-00-2/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Clapham South Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Westinghouse box to wall 1 No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 15810 | INACTIVE | N | N163-00-2/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Clapham South Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | 5 x PCB's - Fair Condition Serial Nos. 197459; 197469; 197474; 197454; 197493 Re inspected 14/04/2015 Fair Condition | | 5 | | | |
| 15806 | ACTIVE | N | N163-00-2/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Clapham South Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 5mm Cable thin cable going from equipment box wall 2 and down wall behind pipes Re-inspected 03-03-2023 | | 1 | | | |
| 15805 | ACTIVE | N | N163-00-2/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Clapham South Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 20mm Cable going to the Invert - Moderate Damage Re-inspected 03-03-2023 | | 1 | | | |
| 15802 | ACTIVE | N | N163-00-2/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Clapham South Stn | Vinyl tiles | Asbestos | Known | | | | Vinyl Tiles. most tiles removed still in place behind racks and equipment Re-inspected 03-03-2023 | | | | | |
| 53548 | ACTIVE | N | N163-00-2/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Clapham South Stn | Other Boarding | Asbestos | Presumed | | | | Brown composite board to box wall 2 Re-inspection 03-03-2023 | | | | | |
| 15803 | ACTIVE | N | N163-00-2/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Clapham South Stn | Vinyl tiles | Asbestos | Known | | | | Vinyl Tiles. most tiles removed still in place behind racks and equipment Re-inspected 03-03-2023 | | | | | |
| 18793 | ACTIVE | N | N163-00-2/711/WAL-004 | Wall: Internal - 4 - Relay Room - Station Building - Clapham South Stn | Vinyl tiles | Asbestos | Known | | | | Vinyl Tiles. most tiles removed still in place behind racks and equipment Re-inspected 03-03-2023 | | | | | |
| 11925 | ACTIVE | N | N163-00-2/712 | Relay Room - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N163-00 - Station Building - Clapham South Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|------------------------|--------------------------|-------------------------|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 44603 | ACTIVE | N | N163-00-2/712 | Relay Room - Station Building - Clapham South Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux board, 1no x 0.1m2, to firestop on top of duct to floor by wall 2 in IMR 2/712. Note, no access to duct as covered under supalux and live cables | | | R616801 | | |
| 15815 | ACTIVE | N | N163-00-2/712/CLG-01 | Ceiling: Solid - 1 - Relay Room - Station Building - Clapham South Stn | Vinyl tiles | Asbestos | Strongly Presumed | | | | Vinyl Tiles most tiles to wall and ceiling removed some still in place behind racks and equipment Re-inspected 03-03-2023 Re-inspected 03-03-2023 | | | | | |
| 18795 | ACTIVE | N | N163-00-2/712/FLR-01 | Floor - 1 - Relay Room - Station Building - Clapham South Stn | Cable Ducts: Cement | Asbestos | Surveyed – Not Detected | | | | Ducts under Panel - supalux boarding to front - duct porcelain VC/AW site visit | | | | | |
| 18598 | ACTIVE | N | N163-00-2/712/FLR-01 | Floor - 1 - Relay Room - Station Building - Clapham South Stn | Boarding: Cement | Asbestos | Surveyed – Not Detected | | | | Floor RHS ducts porcelain non asbestos (VC site visit) panel is supalux | | | | | |
| 53550 | ACTIVE | N | N163-00-2/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Clapham South Stn | Boarding: Cement | Asbestos | Presumed | | | | cement panel - to top shelf of racking on wall 1 Re-inspected 03-03-2023 | | | | | |
| 15811 | ACTIVE | N | N163-00-2/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Clapham South Stn | Vinyl tiles | Asbestos | Strongly Presumed | | | | All Walls Vinyl Tiles Some removal along W1 Re-inspected 03-03-2023 most tiles removed some still in place behind racks and equipment | | | | | |
| 15820 | ACTIVE | N | N163-00-2/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Clapham South Stn | Boarding: Cement | Asbestos | Removed | | | | Panel under PCB's Not identified during re-inspection 2023 | | 2 | | | |
| 15821 | INACTIVE | N | N163-00-2/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Clapham South Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | PCB's - Fair Condition Serial Nos. 197491; 197480; 197475; 38131; 197470; 197483 Re inspected 14/04/2015 | | 6 | | | |
| 15818 | ACTIVE | N | N163-00-2/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Clapham South Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 5mm thin Cable entering electrical box wall4, running down wall behind pipework Re-inspected 03-03-2023 | | 2 | | | |
| 18794 | ACTIVE | N | N163-00-2/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Clapham South Stn | Vinyl tiles | Asbestos | Strongly Presumed | | | | All Walls Vinyl Tiles most tiles removed some still in place behind racks and equipment Re-inspected 03-03-2023 | | | | | |
| 18250 | ACTIVE | N | N163-00-2/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Clapham South Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Westinghouse Box No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 44904 | ACTIVE | N | N163-00-2/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Clapham South Stn | Other Electrical Boxes | Asbestos | Surveyed – Not Detected | | | | Transformer Box - LTE box new (survey AW VC) | | 1 | | N | N |



Hazardous Material Asset Register - Summary



N163-00 - Station Building - Clapham South Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|---------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18597 | ACTIVE | N | N163-00-2/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Clapham South Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 20mm Cables going to the Track Re-inspected 03-03-2023 | | 1 | | | |
| 15816 | ACTIVE | N | N163-00-2/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Clapham South Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 10mm Cables in cable run going to the Track from wall 3 to wall 5 Re-inspected 03-03-2023 | | 1 | | | |
| 15817 | ACTIVE | N | N163-00-2/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Clapham South Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 20mm Cables in cable run from wall 3 going to track wall 5 Re-inspected 03-03-2023 | | 1 | | | |
| 53552 | ACTIVE | N | N163-00-2/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Clapham South Stn | Other Boarding | Asbestos | Presumed | | | | Brown composite panels x6 to rack at bottom on wall 3 Re-inspected 03-03-2023 | | | | | |
| 53551 | ACTIVE | N | N163-00-2/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Clapham South Stn | Other Boarding | Asbestos | Presumed | | | | brown composite panels x6 top shelf to rack to wall 3 Re-inspected 03-03-2023 | | | | | |
| 18596 | ACTIVE | N | N163-00-2/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Clapham South Stn | Vinyl tiles | Asbestos | Strongly Presumed | | | | All Walls Vinyl Tiles Some tiles removed Re-inspected 03-03-2023 | | | | | |
| 15819 | INACTIVE | N | N163-00-2/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Clapham South Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | Westinghouse Box In Twice see 18250 | | 1 | | | |
| 15812 | ACTIVE | N | N163-00-2/712/WAL-004 | Wall: Internal - 4 - Relay Room - Station Building - Clapham South Stn | Vinyl tiles | Asbestos | Strongly Presumed | | | | All Walls Vinyl Tiles most tiles removed some still in place behind racks and equipment Re-inspected 03-03-2023 | | | | | |
| 44319 | ACTIVE | N | N163-00-2/712/WAL-004 | Wall: Internal - 4 - Relay Room - Station Building - Clapham South Stn | Other Boarding | Asbestos | Presumed | | | | brown composite boarding to box on wall 4 Re-inspected 03-03-2023 | | | | | |
| 15813 | ACTIVE | N | N163-00-2/712/WAL-005 | Wall: Internal - 5 - Relay Room - Station Building - Clapham South Stn | Vinyl tiles | Asbestos | Strongly Presumed | | | | All Walls Vinyl Tiles Some removal along W5 most tiles removed some still in place behind racks and equipment Re-inspected 03-03-2023 | | | | | |
| 15814 | ACTIVE | N | N163-00-2/712/WAL-006 | Wall: Internal - 6 - Relay Room - Station Building - Clapham South Stn | Vinyl tiles | Asbestos | Strongly Presumed | | | | All Walls Vinyl Tiles Some removal along W6 Most tiles removed some still in place behind racks and equipment Re-inspected 03-03-2023 | | | | | |
| 11926 | ACTIVE | N | N163-00-2/731 | Passage - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15822 | ACTIVE | N | N163-00-2/731/WAL-004 | Wall: Internal - 4 - Passage - Station Building - Clapham South Stn | Isolator Switches | Asbestos | Removed | | | | 30amp Switch Boxes - Insulation within Not present during re-inspection 2023 | | 2 | | | |



Hazardous Material Asset Register - Summary



N163-00 - Station Building - Clapham South Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 11927 | ACTIVE | N | N163-00-2/732 | Lobby - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15915 | ACTIVE | N | N163-00-2/732/FLR-01 | Floor - 1 - Lobby - Station Building - Clapham South Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | YES |
| 11928 | ACTIVE | N | N163-00-2/733 | CER - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18736 | ACTIVE | N | N163-00-2/733/FLR-01 | Floor - 1 - CER - Station Building - Clapham South Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | |
| 15916 | ACTIVE | N | N163-00-2/733/WAL-002 | Wall: Internal - 2 - CER - Station Building - Clapham South Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes 60amp - Insulation within No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within. | | 2 | | | |
| 11929 | ACTIVE | N | N163-00-2/761 | Store - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11930 | ACTIVE | N | N163-00-2/781 | TXR - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15917 | ACTIVE | N | N163-00-2/781 | TXR - Station Building - Clapham South Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access | | | | | |
| 11931 | ACTIVE | N | N163-00-2/951 | Disused Room - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18756 | ACTIVE | N | N163-00-2/951/FLR-01 | Floor - 1 - Disused Room - Station Building - Clapham South Stn | Other Boarding | Asbestos | No Access: Presumed | | | | No Access beneath Non Asbestos Boarding | | | | | |
| 11932 | ACTIVE | N | N163-00-2/952 | SER - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15918 | ACTIVE | N | N163-00-2/952 | SER - Station Building - Clapham South Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11933 | ACTIVE | N | N163-00-3/161 | LMC - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11934 | ACTIVE | N | N163-00-A/761 | Equipment Room - Station Building - Clapham South Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15919 | ACTIVE | N | N163-00-A/761 | Equipment Room - Station Building - Clapham South Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access | | | | | |



Hazardous Material Asset Register - Summary



N165-00 - Station Building - Balham Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 11935 | ACTIVE | N | N165-00-1/081 | Lobby - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15872 | ACTIVE | N | N165-00-1/081 | Lobby - Station Building - Balham Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 11936 | ACTIVE | N | N165-00-1/181 | Station Entrance - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15873 | ACTIVE | N | N165-00-1/181 | Station Entrance - Station Building - Balham Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11937 | ACTIVE | N | N165-00-1/203 | Passage - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15874 | ACTIVE | N | N165-00-1/203 | Passage - Station Building - Balham Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11938 | ACTIVE | N | N165-00-1/401 | Store - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15878 | ACTIVE | N | N165-00-1/401/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Above False Ceiling - Plasterboard on Metal Ceiling, Ceiling, Durasteel same in room, Plasterboard, Rock Wool, | | | | YES | |
| 15877 | ACTIVE | N | N165-00-1/401/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Balham Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Durasteel Diamond Holes - No asbestos detected | | | | | |
| 15875 | ACTIVE | N | N165-00-1/401/WAL-001 | Wall: Internal - 1 - Store - Station Building - Balham Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Durasteel Diamond Holes - No asbestos detected | | | | | |
| 18680 | ACTIVE | N | N165-00-1/401/WAL-002 | Wall: Internal - 2 - Store - Station Building - Balham Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Durasteel Diamond Holes - No asbestos detected | | | | | |
| 15876 | ACTIVE | N | N165-00-1/401/WAL-004 | Wall: Internal - 4 - Store - Station Building - Balham Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Durasteel Diamond Holes - No asbestos detected | | | | | |
| 11939 | ACTIVE | N | N165-00-1/402 | Bin Store - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18799 | ACTIVE | N | N165-00-1/402/CLG-01 | Ceiling: Suspended - 1 - Bin Store - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plasterboard above Supalux Tiles | | | | YES | |
| 15879 | ACTIVE | N | N165-00-1/402/CLG-01 | Ceiling: Suspended - 1 - Bin Store - Station Building - Balham Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11940 | ACTIVE | N | N165-00-1/406 | SVC - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18681 | ACTIVE | N | N165-00-1/406 | SVC - Station Building - Balham Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N165-00 - Station Building - Balham Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 11941 | ACTIVE | N | N165-00-1/451 | Store - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15881 | ACTIVE | N | N165-00-1/451/CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 15880 | ACTIVE | N | N165-00-1/451/CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Balham Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11942 | ACTIVE | N | N165-00-1/452 | Store - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15882 | ACTIVE | N | N165-00-1/452/CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Balham Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18682 | ACTIVE | N | N165-00-1/452/CLG-01 | Ceiling: Suspended - 1 - Store - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Supalux Tiles | | | | YES | |
| 11943 | ACTIVE | N | N165-00-1/453 | SER - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15883 | ACTIVE | N | N165-00-1/453/FLR-01 | Floor - 1 - SER - Station Building - Balham Stn | Void | Asbestos | No Access: Presumed | | | | Limited access beneath concrete/ metal false floor | | | | | |
| 11944 | ACTIVE | N | N165-00-1/454 | Tenancy - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15884 | ACTIVE | N | N165-00-1/454/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Fibreboard Ceiling | | | | YES | |
| 11945 | ACTIVE | N | N165-00-1/455 | Tenancy - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15885 | ACTIVE | N | N165-00-1/455/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Fibreboard Ceiling | | | | YES | |
| 11946 | ACTIVE | N | N165-00-1/601 | Stairs: Linear - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18313 | ACTIVE | N | N165-00-1/601/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete and Corrugated Metal above false ceiling - Metal Panels | | | | YES | |
| 11947 | ACTIVE | N | N165-00-1/602 | Stairs: Linear - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15886 | ACTIVE | N | N165-00-1/602 | Stairs: Linear - Station Building - Balham Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11948 | ACTIVE | N | N165-00-1/603 | Stairs: Linear - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N165-00 - Station Building - Balham Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18734 | ACTIVE | N | N165-00-1/603 | Stairs: Linear - Station Building - Balham Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11949 | ACTIVE | N | N165-00-1/604 | Stairs: Linear - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18683 | ACTIVE | N | N165-00-1/604/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Metal Strip False Ceiling | | | | YES | |
| 11950 | ACTIVE | N | N165-00-1/761 | Switch Room - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15887 | ACTIVE | N | N165-00-1/761/CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - Balham Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | | | | | | |
| 18800 | ACTIVE | N | N165-00-1/761/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Balham Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 100amp Switch Box - Insulation within No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 15889 | ACTIVE | N | N165-00-1/791 | Vent Shaft - Station Building - Balham Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Black Oil Based Paint - Pipework Thickness .51mm; Est Quantity 8 lm; Analysis 18.02% | | | | | |
| 15754 | ACTIVE | N | N165-00-1/791/FLR-01 | Floor - 1 - Vent Shaft - Station Building - Balham Stn | Lagging | Asbestos | Surveyed – Not Detected | | | | On Floor | | | | | |
| 15888 | ACTIVE | N | N165-00-1/791/FLR-01 | Floor - 1 - Vent Shaft - Station Building - Balham Stn | Lagging | Asbestos | Surveyed – Not Detected | | | | On Floor | | | | | |
| 11951 | ACTIVE | N | N165-00-1/952 | Disused Room - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18684 | ACTIVE | N | N165-00-1/952/CLG-01 | Ceiling: Solid - 1 - Disused Room - Station Building - Balham Stn | Void | Asbestos | No Access: Presumed | | | | Above Wood Slates Damage to Ceiling would occur if to access above Supalux | | | | YES | |
| 15890 | ACTIVE | N | N165-00-1/952/FLR-01 | Floor - 1 - Disused Room - Station Building - Balham Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Wooden False Floor | | | | | YES |
| 11952 | ACTIVE | N | N165-00-2/001 | Booking Hall - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15891 | ACTIVE | N | N165-00-2/001/CLG-01 | Ceiling: Solid - 1 - Booking Hall - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal above Metal Strip - False Ceiling | | | | YES | |
| 11953 | ACTIVE | N | N165-00-2/011 | Ticket Office - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15734 | ACTIVE | N | N165-00-2/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal Corrugated Ceiling, PVC Cables and Metal Trunking above Fibreboard Ceiling | | | | YES | |



Hazardous Material Asset Register - Summary



N165-00 - Station Building - Balham Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 15892 | ACTIVE | N | N165-00-2/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete beneath Computer Tiles | | | | | YES |
| 11954 | ACTIVE | N | N165-00-2/021 | POM - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15736 | ACTIVE | N | N165-00-2/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal Corrugated Ceiling, PVC Cables and Metal Trunking above Fibreboard Ceiling | | | | YES | |
| 15735 | ACTIVE | N | N165-00-2/021/FLR-01 | Floor - 1 - POM - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete beneath Computer Tiles | | | | | YES |
| 11955 | ACTIVE | N | N165-00-2/031 | Mess Room - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 46576 | ACTIVE | N | N165-00-2/031 | Mess Room - Station Building - Balham Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Mess Room & Cupboard. Yellow gloss paint on RSJ & metal ceiling (18.9%) | | 19 | R704502 | | |
| 15737 | ACTIVE | N | N165-00-2/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal above Supalux Tiles | | | | YES | |
| 18511 | ACTIVE | N | N165-00-2/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Balham Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 11956 | ACTIVE | N | N165-00-2/036 | Lobby - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15738 | ACTIVE | N | N165-00-2/036/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal; Fibreglass Lagging above Supalux Tiles | | | | YES | |
| 18665 | ACTIVE | N | N165-00-2/036/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | YES | |
| 11957 | ACTIVE | N | N165-00-2/037 | Toilet: Unisex - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15741 | ACTIVE | N | N165-00-2/037 | Toilet: Unisex - Station Building - Balham Stn | | Asbestos | Surveyed – Not Detected | | | | Toilet Cistern - Bakelite | | | | YES | |
| 15739 | ACTIVE | N | N165-00-2/037/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Balham Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 15740 | ACTIVE | N | N165-00-2/037/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal above Supalux Tiles | | | | YES | |
| 11958 | ACTIVE | N | N165-00-2/071 | Circulation Area - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18512 | ACTIVE | N | N165-00-2/071/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal above Metal Strip false ceiling | | | | YES | |



Hazardous Material Asset Register - Summary



N165-00 - Station Building - Balham Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 11959 | ACTIVE | N | N165-00-2/151 | UMC - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18248 | ACTIVE | N | N165-00-2/151 | UMC - Station Building - Balham Stn | Gasket :Pipework | Asbestos | Sampled – Not Detected | | | | Fire Hydrant Gaskets | | | | | |
| 15743 | ACTIVE | N | N165-00-2/151 | UMC - Station Building - Balham Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Board above door to 1/792 | | | | | |
| 18513 | ACTIVE | N | N165-00-2/151 | UMC - Station Building - Balham Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Grey Oil Based Paint - Stairs. Thickness .27mm; Est Quantity 5 sqm; Analysis 2.44% Now painted yellow. Unclear if paintwork has been stripped or overpainted. Presumed lead hazard under yellow paintwork. | | | | | |
| 15745 | ACTIVE | N | N165-00-2/151 | UMC - Station Building - Balham Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Red Oil Based Paint - 2no Girder to Housing Unit. Thickness .27mm; Est Quantity 25 lm; Analysis 40.23% Now painted white. It is not known if paintwork was stripped or overpainted. Presumed lead hazard below white paint. | | | | | |
| 15746 | ACTIVE | N | N165-00-2/151 | UMC - Station Building - Balham Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Green/ Grey Oil Based Paint - Girder. Thickness .33mm; Est Quantity 6 lm; Analysis 11.24% | | | | | |
| 44931 | ACTIVE | N | N165-00-2/151 | UMC - Station Building - Balham Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Handrail - Grey Gloss. Now painted yellow. Unclear if paintwork has been stripped or overpainted. Check next site visit | | | | N | N |
| 44930 | ACTIVE | N | N165-00-2/151 | UMC - Station Building - Balham Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Escalator No.3 Metal support - Orange Gloss | | | | N | N |
| 44929 | ACTIVE | N | N165-00-2/151 | UMC - Station Building - Balham Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Escalator No.1 Metal Housing - Dark Red Gloss | | | | N | N |
| 15744 | ACTIVE | N | N165-00-2/151 | UMC - Station Building - Balham Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Black & White Oil Based Paint - Girder. Thickness .34mm; Est Quantity 10 lm; Analysis 5.55% Now painted yellow and white | | | | | |
| 18726 | ACTIVE | N | N165-00-2/151 | UMC - Station Building - Balham Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Red Oil Based Paint - Pipework Thickness .21mm; Est Quantity 60 lm; Analysis 4.15% | | | | | |
| 15742 | ACTIVE | N | N165-00-2/151/ FLR-01 | Floor - 1 - UMC - Station Building - Balham Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Lid to Storage Bin | | | | | |
| 15747 | ACTIVE | N | N165-00-2/171 | Escalator Incline - Station Building - Balham Stn | | Asbestos | Surveyed – Not Detected | | | | Wooden Caulking | | | | | |
| 11960 | ACTIVE | N | N165-00-2/201 | Passage - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15748 | ACTIVE | N | N165-00-2/201/ CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Metal Strip false ceiling | | | | YES | |



Hazardous Material Asset Register - Summary



N165-00 - Station Building - Balham Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 11961 | ACTIVE | N | N165-00-2/202 | Passage - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15749 | ACTIVE | N | N165-00-2/202/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Metal Strip false ceiling | | | | YES | |
| 11962 | ACTIVE | N | N165-00-2/236 | Passage - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18514 | ACTIVE | N | N165-00-2/236/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal Corrugated Ceiling, PVC Cables and Metal Trunking above Fibreboard Ceiling | | | | YES | |
| 15750 | ACTIVE | N | N165-00-2/236/FLR-01 | Floor - 1 - Passage - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete beneath Computer Tiles | | | | | YES |
| 11963 | ACTIVE | N | N165-00-2/237 | Passage - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15752 | ACTIVE | N | N165-00-2/237/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal above Supalux Tiles | | | | YES | |
| 15751 | ACTIVE | N | N165-00-2/237/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Balham Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 11964 | ACTIVE | N | N165-00-2/238 | Lobby - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18727 | ACTIVE | N | N165-00-2/238/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Balham Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 15753 | ACTIVE | N | N165-00-2/238/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal above Supalux Tiles | | | | YES | |
| 11965 | ACTIVE | N | N165-00-2/311 | Switch Room - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11966 | ACTIVE | N | N165-00-2/331 | Mess Room - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 46578 | ACTIVE | N | N165-00-2/331 | Mess Room - Station Building - Balham Stn | Lead/Leading | Lead Paint/Lead | Strongly Presumed | | | | Ticket office, mess room & cupboard 2/331. Yellow gloss paint on pipework (0.81%) It is possible that layers containing lead at a percentage higher than 1% exist below | | | R704502 | | |
| 46574 | ACTIVE | N | N165-00-2/331 | Mess Room - Station Building - Balham Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Mess room & cupboard RSJ & Metal Grills in false ceiling - Yellow gloss (23.4%) | | | R704502 | | |
| 15755 | ACTIVE | N | N165-00-2/331/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Balham Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |



Hazardous Material Asset Register - Summary



| N165-00 - Station Building - Balham Stn | | | | | | | | | | | | | | | | |
|---|--------|-------------|-----------------------|---|------------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
| 18515 | ACTIVE | N | N165-00-2/331/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal above Supalux Tiles | | | | YES | |
| 11967 | ACTIVE | N | N165-00-2/411 | Disused Room - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15756 | ACTIVE | N | N165-00-2/411 | Disused Room - Station Building - Balham Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 46577 | ACTIVE | N | N165-00-2/411 | Disused Room - Station Building - Balham Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Mess Room & Cupboard. Yellow gloss paint on RSJ and metal ceiling. (18.9%) | | | R704502 | | |
| 11968 | ACTIVE | N | N165-00-2/416 | Toilet: Unisex - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18666 | ACTIVE | N | N165-00-2/416/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Balham Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 15757 | ACTIVE | N | N165-00-2/416/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal above Supalux Tiles | | | | YES | |
| 11969 | ACTIVE | N | N165-00-2/661 | Station Control Room - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18599 | ACTIVE | N | N165-00-2/661/CLG-01 | Ceiling: Solid - 1 - Station Control Room - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal above False Ceiling | | | | YES | |
| 11970 | ACTIVE | N | N165-00-2/662 | Switch Room - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15824 | ACTIVE | N | N165-00-2/662/CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - Balham Stn | Void | Asbestos | Surveyed – Not Detected | | | | Steel Ceiling, Fire Alarm System Brick wall to rear, Solid Plaster above Supalux Ceiling | | | | YES | |
| 15825 | ACTIVE | N | N165-00-2/662/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Balham Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box(es) No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score material within. | | 3 | | | |
| 15823 | ACTIVE | N | N165-00-2/662/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Balham Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Box 30amp- Insulation within No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 11971 | ACTIVE | N | N165-00-2/663 | Switch Room - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18796 | ACTIVE | N | N165-00-2/663/CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - Balham Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | YES | |



Hazardous Material Asset Register - Summary



N165-00 - Station Building - Balham Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|--------------------------------|--|-------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18600 | ACTIVE | N | N165-00-2/663/WAL-002 80890595 | Wall: Internal - 2 - Switch Room - Station Building - Balham Stn Wall: Internal | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes: 2 x 30amp 2x 60amp 1 x 100amp W2; Red Fuse Box W3 No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score material within. | | 6 | | | |
| 11972 | ACTIVE | N | N165-00-2/731 | CER - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15826 | ACTIVE | N | N165-00-2/731/WAL-006 | Wall: Internal - 6 - CER - Station Building - Balham Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes 60amp - Insulation within No access 2024 re-inspection as CER in within the UMC and no Lift & Escalator ticket to gain access. | | 2 | | | |
| 11973 | ACTIVE | N | N165-00-2/732 | Switch Room - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15827 | ACTIVE | N | N165-00-2/732 | Switch Room - Station Building - Balham Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11974 | ACTIVE | N | N165-00-2/746 | SCR - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15828 | ACTIVE | N | N165-00-2/746/CLG-01 | Ceiling: Solid - 1 - SCR - Station Building - Balham Stn | Void | Asbestos | No Access: Presumed | | | | Above Corrugated Metal | | | | YES | |
| 11975 | ACTIVE | N | N165-00-2/951 | Void - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 46575 | ACTIVE | N | N165-00-2/951 | Void - Station Building - Balham Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Mess Room & Cupboard. Yellow gloss paint on RSJ and metal grills in false ceiling. (23.4%) | | | R704502 | | |
| 46579 | ACTIVE | N | N165-00-2/951 | Void - Station Building - Balham Stn | Lead/Leading | Lead Paint/Lead | Strongly Presumed | | | | Ticket office, mess room & cupboard. Yellow gloss paint on pipework. (0.81%) It is assumed layers containing lead at a percentage higher than 1% maybe present. | | | R704502 | | |
| 15829 | ACTIVE | N | N165-00-2/951/CLG-01 | Ceiling: Solid - 1 - Void - Station Building - Balham Stn | Void | Asbestos | No Access: Presumed | | | | Above Corrugated Metal | | | | YES | |
| 11976 | ACTIVE | N | N165-00-2/991 | UMC - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18458 | ACTIVE | N | N165-00-2/991/CLG-01 | Ceiling: Solid - 1 - UMC - Station Building - Balham Stn | Void | Asbestos | No Access: Presumed | | | | No access above Supalux Ceiling. Damage to ceiling would occur if accessed above Supalux | | | | YES | |
| 11977 | ACTIVE | N | N165-00-2/992 | UMC - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15830 | ACTIVE | N | N165-00-2/992/CLG-01 | Ceiling: Solid - 1 - UMC - Station Building - Balham Stn | Void | Asbestos | No Access: Presumed | | | | No access above Supalux Ceiling. Damage to ceiling would occur if accessed above Supalux | | | | YES | |



Hazardous Material Asset Register - Summary



N165-00 - Station Building - Balham Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 11978 | ACTIVE | N | N165-00-3/081 | Circulation Area - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15831 | ACTIVE | N | N165-00-3/081 | Circulation Area - Station Building - Balham Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11979 | ACTIVE | N | N165-00-3/161 | LMC - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15832 | ACTIVE | N | N165-00-3/161 | LMC - Station Building - Balham Stn | Cable Duct: Other | Asbestos | Surveyed – Not Detected | | | | Cables Sleeves | | | | | |
| 18797 | ACTIVE | N | N165-00-3/161 | LMC - Station Building - Balham Stn | Gasket :Pipework | Asbestos | Strongly Presumed | | | | Gaskets on Pump Equipment joints | | | | | |
| 15833 | ACTIVE | N | N165-00-3/161 | LMC - Station Building - Balham Stn | Cable: Sheath | Asbestos | Removed | | | | Encapsulated - 10mm Asbestos cable next to Earth Terminal Box - SP (on Floor) No asbestos cable visible during 2023 re-inspection | | 1 | | | |
| 18601 | ACTIVE | N | N165-00-3/161 | LMC - Station Building - Balham Stn | Cable: Sheath | Asbestos | Removed | | | | 15mm Cables - Encapsulated Not visible during 2023 re-inspection | | 3 | | | |
| 15834 | ACTIVE | N | N165-00-3/161 | LMC - Station Building - Balham Stn | Cable: Sheath | Asbestos | Removed | | | | Encapsulated - 1 x Cable J-Hanger No 3 Not visible during 2023 re-inspection | | 1 | | | |
| 44927 | ACTIVE | N | N165-00-3/161 | LMC - Station Building - Balham Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Column - Grey Gloss | | | | N | N |
| 70161 | ACTIVE | N | N165-00-3/161 | LMC - Station Building - Balham Stn | Lead/Leading | Lead Paint/Lead | Presumed | | | | Yellow gloss to pipework 0.96% The content of lead was found to be just below 1% and is very likely that some of the layers in the paint coating contain lead at a level higher than 1% | | | R442201 | | |
| 11980 | ACTIVE | N | N165-00-3/201 | Passage - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18668 | ACTIVE | N | N165-00-3/201 | Passage - Station Building - Balham Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11981 | ACTIVE | N | N165-00-3/202 | Passage - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15837 | ACTIVE | N | N165-00-3/202 | Passage - Station Building - Balham Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11982 | ACTIVE | N | N165-00-3/203 | Passage - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N165-00 - Station Building - Balham Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 15838 | ACTIVE | N | N165-00-3/203 | Passage - Station Building - Balham Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11983 | ACTIVE | N | N165-00-3/204 | Passage - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18732 | ACTIVE | N | N165-00-3/204 | Passage - Station Building - Balham Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11984 | ACTIVE | N | N165-00-3/205 | Passage - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15839 | ACTIVE | N | N165-00-3/205 | Passage - Station Building - Balham Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11985 | ACTIVE | N | N165-00-3/261 | Platform 1 - Northbound Local - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15835 | ACTIVE | N | N165-00-3/261 | Platform 1 - Northbound Local - Station Building - Balham Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Boarding near 3/664 | | | | | |
| 70163 | ACTIVE | N | N165-00-3/261 | Platform 1 - Northbound Local - Station Building - Balham Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | Platform 1 Invert - 1x Bitumen Cable ducts to trackside wall | | 1 | R728757 | N | Y |
| 70177 | ACTIVE | N | N165-00-3/261 | Platform 1 - Northbound Local - Station Building - Balham Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform 1 Invert - 5x Bitumen cable ducts platform wall. | | 5 | R728757 | N | Y |
| 70167 | ACTIVE | N | N165-00-3/261 | Platform 1 - Northbound Local - Station Building - Balham Stn | Westing house Boxes | Asbestos | Presumed | | | | Platform 1 Invert - 1x Small Westinghouse box. Presumed asbestos insulating materials within | | 1 | R728757 | N | Y |
| 70188 | ACTIVE | N | N165-00-3/261 | Platform 1 - Northbound Local - Station Building - Balham Stn | | Asbestos | Surveyed – Not Detected | | | | Platform 1 Invert - Metal tunnel rings to walls, floor throughout - concrete infill, grout/wood/lead to tunnel ring flanges throughout, concrete slab to ceiling and walls throughout, brickwork to walls throughout, plastic cables, metal conduits and CMS, new firestops and mastics, plastic & metal pipework, wood splinters, fibres (shuttering, panels, cut-offs), new electrical boxes, units, metal, plastic and terracotta cable ducts | | | R728757 | N | Y |
| 70178 | ACTIVE | N | N165-00-3/261 | Platform 1 - Northbound Local - Station Building - Balham Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform 1 Invert - 5x Bitumen cable ducts to platform wall. | | 5 | R728757 | N | Y |
| 70166 | ACTIVE | N | N165-00-3/261 | Platform 1 - Northbound Local - Station Building - Balham Stn | Westing house Boxes | Asbestos | Presumed | | | | Platform 1 Invert - 1x Small Westinghouse box. Presumed asbestos insulating materials within | | 1 | R728757 | N | Y |
| 70165 | ACTIVE | N | N165-00-3/261 | Platform 1 - Northbound Local - Station Building - Balham Stn | Westing house Boxes | Asbestos | Presumed | | | | Platform 1 - 1x Small Westinghouse box platform wall midway. Presumed asbestos insulating materials within | | 1 | R728757 | N | Y |
| 70162 | ACTIVE | N | N165-00-3/261 | Platform 1 - Northbound Local - Station Building - Balham Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | Platform 1 Invert - 8x Bitumen cable ducts to tail wall trackside | | 8 | R728757 | N | Y |



Hazardous Material Asset Register - Summary



N165-00 - Station Building - Balham Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|----------------------|---------------|---------------------------------|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 70180 | ACTIVE | N | N165-00-3/261 | Platform 1 - Northbound Local - Station Building - Balham Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform 1 Invert - 4x Bitumen cable ducts | | 4 | R728757 | N | Y |
| 70164 | ACTIVE | N | N165-00-3/261 | Platform 1 - Northbound Local - Station Building - Balham Stn | Cable: Sheath | Asbestos | Known | | | | Platform 1 Invert - 4x Braided cables to J-Hangers throughout | | 4 | R728757 | N | Y |
| 15836 | INACTIVE | N | N165-00-3/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Balham Stn | Cable: Sheath | Asbestos | Presumed | | | | Platform 1 Invert - 10mm Asbestos Cable on 10th J hanger no access 2020 reinspection as confined space team required | | 1 | | | YES |
| 11986 | ACTIVE | N | N165-00-3/262 | Platform 2 - Southbound Local - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Surveyed – Asbestos Known | | | | | | | | | |
| 70187 | ACTIVE | N | N165-00-3/262 | Platform 2 - Southbound Local - Station Building - Balham Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform 2 Invert - Bitumen cable duct trackside wall - headwall | | 1 | R728757 | N | Y |
| 70184 | ACTIVE | N | N165-00-3/262 | Platform 2 - Southbound Local - Station Building - Balham Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform 2 Invert - 2x Bitumen cable ducts to platform wall. | | 2 | R728757 | N | Y |
| 70169 | ACTIVE | N | N165-00-3/262 | Platform 2 - Southbound Local - Station Building - Balham Stn | Westing house Boxes | Asbestos | Presumed | | | | Platform 2 Invert - 1x Small Westinghouse box to trackside wall tail end. Presumed asbestos insulating materials within | | 1 | R728757 | N | Y |
| 18669 | ACTIVE | N | N165-00-3/262 | Platform 2 - Southbound Local - Station Building - Balham Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Boarding near 3/661 | | | | | |
| 70181 | ACTIVE | N | N165-00-3/262 | Platform 2 - Southbound Local - Station Building - Balham Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform 2 Invert - 1x Bitumen cable duct to trackside wall tail wall | | 1 | R728757 | N | Y |
| 70175 | ACTIVE | N | N165-00-3/262 | Platform 2 - Southbound Local - Station Building - Balham Stn | Westing house Boxes | Asbestos | Presumed | | | | Platform 2 Invert - 1x Small Westinghouse box to platform wall. Presumed asbestos insulating materials within. | | 1 | R728757 | N | Y |
| 70168 | ACTIVE | N | N165-00-3/262 | Platform 2 - Southbound Local - Station Building - Balham Stn | Cable: Sheath | Asbestos | Known | | | | Platform 2 Invert - 6x Braided cables to J-Hangers throughout | | 6 | R728757 | N | Y |
| 15840 | ACTIVE | N | N165-00-3/262 | Platform 2 - Southbound Local - Station Building - Balham Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 70182 | ACTIVE | N | N165-00-3/262 | Platform 2 - Southbound Local - Station Building - Balham Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform 2 Invert - 4x Bitumen cable ducts to platform wall - midway. | | 4 | R728757 | N | Y |
| 70185 | ACTIVE | N | N165-00-3/262 | Platform 2 - Southbound Local - Station Building - Balham Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform 2 Invert - 6x Bitumen cable ducts trackside wall - head wall | | 6 | R728757 | N | Y |



Hazardous Material Asset Register - Summary



N165-00 - Station Building - Balham Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 70190 | ACTIVE | N | N165-00-3/262 | Platform 2 - Southbound Local - Station Building - Balham Stn | | Asbestos | Surveyed – Not Detected | | | | Platform 2 Invert - Metal tunnel rings to walls and floor throughout - concrete infill, grout/wood/lead to tunnel ring flanges throughout, Concrete slab to ceiling, walls throughout, RSJ to ceiling throughout, brickwork to walls throughout, plastic cables, metal conduits and CMS, new firestop and mastics throughout, wood splinter, fibres (shuttering, panels, cut offs) to concrete ceiling and walls throughout, new electrical equipment boxes to concrete ceiling and walls throughout | | | | | |
| 18798 | INACTIVE | N | N165-00-3/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Balham Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 2 Invert - 1 x Braided Cable no access 2020 reinspection as confined space team required | | 1 | | | YES |
| 15841 | ACTIVE | N | N165-00-3/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Balham Stn | Cable Ducts: Bitumen | Asbestos | Surveyed – Not Detected | | | | Bitumen Cable Sleeves | | | | | YES |
| 11987 | ACTIVE | N | N165-00-3/661 | Switch Cupboard - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15842 | ACTIVE | N | N165-00-3/661 | Switch Cupboard - Station Building - Balham Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding above door | | | | | |
| 11988 | ACTIVE | N | N165-00-3/662 | Switch Cupboard - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18670 | ACTIVE | N | N165-00-3/662 | Switch Cupboard - Station Building - Balham Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11989 | ACTIVE | N | N165-00-3/663 | Switch Room - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15843 | ACTIVE | N | N165-00-3/663 | Switch Room - Station Building - Balham Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11990 | ACTIVE | N | N165-00-3/664 | Switch Cupboard - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15844 | ACTIVE | N | N165-00-3/664 | Switch Cupboard - Station Building - Balham Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11991 | ACTIVE | N | N165-00-3/665 | Switch Room - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15845 | ACTIVE | N | N165-00-3/665 | Switch Room - Station Building - Balham Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11992 | ACTIVE | N | N165-00-3/666 | Switch Room - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N165-00 - Station Building - Balham Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|---------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18671 | ACTIVE | N | N165-00-3/666 | Switch Room - Station Building - Balham Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11993 | ACTIVE | N | N165-00-3/711 | Relay Room - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18673 | ACTIVE | N | N165-00-3/711/CLG-01 | Ceiling: Solid - 1 - Relay Room - Station Building - Balham Stn | Vinyl tiles | Asbestos | Known | | | | Vinyl Tiles some tiles removed | | | | | |
| 18672 | ACTIVE | N | N165-00-3/711/FLR-01 | Floor - 1 - Relay Room - Station Building - Balham Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Green & White Tiles | | | | | |
| 69872 | ACTIVE | N | N165-00-3/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Balham Stn | Boarding: Cement | Asbestos | Presumed | | | | Cement board below relay equipment | | 1 | | | |
| 15849 | ACTIVE | N | N165-00-3/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Balham Stn | Vinyl tiles | Asbestos | Known | | | | Grey & Green Vinyl Tiles - Some removed some tiles removed of both grey and green | | | | | |
| 15853 | INACTIVE | N | N165-00-3/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Balham Stn | Boarding: Cement | Asbestos | Removed | | | | Cement beneath Relay Capacitors - Panel under PCB's | | | | | |
| 69874 | ACTIVE | N | N165-00-3/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Balham Stn | Other Boarding | Asbestos | Presumed | | | | 1x brown board to back on room box 17 -wall 1 | | 1 | | | |
| 69873 | ACTIVE | N | N165-00-3/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Balham Stn | Other Boarding | Asbestos | Presumed | | | | 3 x long brown board bottom of rack to wall 1 | | 3 | | | |
| 44311 | ACTIVE | N | N165-00-3/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Balham Stn | Other Boarding | Asbestos | Presumed | | | | Black board x6 to top of rack wall 1 | | 6 | | | |
| 15854 | INACTIVE | N | N165-00-3/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Balham Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | 6 x PCB's - Fair Condition. Serial Nos. 197449; 197466; 197451; 197450; 197455; 197458 Re inspected 14/04/2015 | | 6 | | | |
| 18674 | ACTIVE | N | N165-00-3/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Balham Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | Westinghouse Box - Insulation within No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 15852 | ACTIVE | N | N165-00-3/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Balham Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 5mm Cable | | 2 | | | |
| 15851 | ACTIVE | N | N165-00-3/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Balham Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 20mm Cable going to track | | 1 | | | |
| 15850 | ACTIVE | N | N165-00-3/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Balham Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 10mm Cable going to track | | 1 | | | |
| 18251 | ACTIVE | N | N165-00-3/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Balham Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 10mm Cable going into Invert | | 1 | | | |
| 53541 | ACTIVE | N | N165-00-3/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Balham Stn | Other Boarding | Asbestos | Removed | | | | brown composite packing material to framework on wall 3 Not found in 2024 re-inspection. | | | | | |



Hazardous Material Asset Register - Summary



N165-00 - Station Building - Balham Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|---------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 44312 | ACTIVE | N | N165-00-3/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Balham Stn | Other Boarding | Asbestos | Removed | | | | 1 x brown composite boarding wall 3 behind plastic casing to high voltage box. Not found in 2024 re-inspection | | | | | |
| 11994 | ACTIVE | N | N165-00-3/712 | Relay Room - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44313 | INACTIVE | N | N165-00-3/712 | Relay Room - Station Building - Balham Stn | Cable Ducts: Cement | Asbestos | Presumed | | | | Filled in ductwork | | | | | |
| 15855 | ACTIVE | N | N165-00-3/712/CLG-01 | Ceiling: Solid - 1 - Relay Room - Station Building - Balham Stn | Vinyl tiles | Asbestos | Known | | | | Green & Grey Vinyl Tiles - to ALL walls and ceiling majority removed to walls both green & grey but still present behind equipment and racking to walls | | | | | |
| 18733 | INACTIVE | N | N165-00-3/712/FLR-01 | Floor - 1 - Relay Room - Station Building - Balham Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Green & White Tiles | | | | | |
| 15856 | INACTIVE | N | N165-00-3/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Balham Stn | Vinyl tiles | Asbestos | Known | | | | Grey & Green Vinyl Tiles - Majority Removed majority removed to walls both green & grey. | | | | | |
| 15859 | ACTIVE | N | N165-00-3/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Balham Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | 1 x Westinghouse Box - Insulation within No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 53544 | ACTIVE | N | N165-00-3/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Balham Stn | Other Boarding | Asbestos | Removed | | | | brown composite board x6 to bottom equipment on rack wall 1. Not found in 2024 re-inspecton | | | | | |
| 53543 | ACTIVE | N | N165-00-3/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Balham Stn | Other Boarding | Asbestos | Removed | | | | brown composite board x6 to equipment top rack of shelving wall 1. Not found in 2024 reinspection | | | | | |
| 19957 | ACTIVE | N | N165-00-3/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Balham Stn | Boarding: Cement | Asbestos | Removed | | | | Cement beneath Relay Capacitors to top shelf of rack on wall 1. Not found during 2024 re-inspection | | | | | |
| 15860 | INACTIVE | N | N165-00-3/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Balham Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | 6no PCB's - Fair Condition. Serial Nos. 197457; 197486; 186506; 197452; 197484; 197471 Re inspected 14/04/2015 | | 6 | | | |
| 18675 | INACTIVE | N | N165-00-3/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Balham Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 20mm Cable going to track | | 1 | | | |
| 53542 | ACTIVE | N | N165-00-3/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Balham Stn | Other Boarding | Asbestos | Removed | | | | Composite panel box to wall 2 back of room Not found in 2024 re-inspection | | | | | |
| 15858 | ACTIVE | N | N165-00-3/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Balham Stn | Cable: Sheath | Asbestos | Removed | | | | thin cable exiting box to wall 2 and running down wall behind pipe. Not found in 2024 reinspection | | 1 | | | |
| 15857 | ACTIVE | N | N165-00-3/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Balham Stn | Cable: Sheath | Asbestos | Removed | | | | 10mm 20mm Cables to cable run around room from wall 1 to wall 3 exit to track - Encapsulated good condition. Not visible in 2024 reinspection | | 1 | | | |



Hazardous Material Asset Register - Summary



N165-00 - Station Building - Balham Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 53545 | ACTIVE | N | N165-00-3/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Balham Stn | Other Boarding | Asbestos | Presumed | | | | brown composite packing board to rack wall 3 | | | | | |
| 53546 | ACTIVE | N | N165-00-3/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Balham Stn | Other Boarding | Asbestos | Presumed | | | | brown panel to box on rack wall 3 | | | | | |
| 11995 | ACTIVE | N | N165-00-3/731 | CER - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15846 | ACTIVE | N | N165-00-3/731 | CER - Station Building - Balham Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11996 | ACTIVE | N | N165-00-3/761 | Store - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15847 | ACTIVE | N | N165-00-3/761 | Store - Station Building - Balham Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 11997 | ACTIVE | N | N165-00-3/951 | Void - Station Building - Balham Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15848 | ACTIVE | N | N165-00-3/951 | Void - Station Building - Balham Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |

N167-00 - Station Building - Tooting Bec Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---------------------|-------------|------------|-------------|---------------------|-------------------|
| 12011 | ACTIVE | N | N167-00-1/081 | Lobby - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15684 | ACTIVE | N | N167-00-1/081 | Lobby - Station Building - Tooting Bec Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Wall | | | | | |
| 12012 | ACTIVE | N | N167-00-1/201 | Passage - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18434 | ACTIVE | N | N167-00-1/201 | Passage - Station Building - Tooting Bec Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12013 | ACTIVE | N | N167-00-1/202 | Passage - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15685 | ACTIVE | N | N167-00-1/202 | Passage - Station Building - Tooting Bec Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12014 | ACTIVE | N | N167-00-1/451 | Tenancy - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N167-00 - Station Building - Tooting Bec Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 15686 | ACTIVE | N | N167-00-1/451 | Tenancy - Station Building - Tooting Bec Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Tenancy | | | | | |
| 12015 | ACTIVE | N | N167-00-1/601 | Stairs: Linear - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15687 | ACTIVE | N | N167-00-1/601 | Stairs: Linear - Station Building - Tooting Bec Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12016 | ACTIVE | N | N167-00-1/602 | Stairs: Linear - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18435 | ACTIVE | N | N167-00-1/602/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Tooting Bec Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Strip | | | | | |
| 12017 | ACTIVE | N | N167-00-1/603 | Stairs: Linear - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15688 | ACTIVE | N | N167-00-1/603/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Tooting Bec Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Strip | | | | | |
| 12018 | ACTIVE | N | N167-00-1/604 | Stairs: Linear - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15689 | ACTIVE | N | N167-00-1/604/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Tooting Bec Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Strip | | | | | |
| 12019 | ACTIVE | N | N167-00-1/781 | TXR - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18436 | ACTIVE | N | N167-00-1/781 | TXR - Station Building - Tooting Bec Stn | Cable Duct: Other | Asbestos | Strongly Presumed | | | | Cable Ducts - In Draw Pit | | 8 | | | |
| 15690 | ACTIVE | N | N167-00-1/781 | TXR - Station Building - Tooting Bec Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Box - Arc Chutes and Flash Guards presumed inside switches. May also be present in other equipment inside room No electrician on site during 2024 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | | |
| 69708 | ACTIVE | N | N167-00-1/781 | TXR - Station Building - Tooting Bec Stn | | Asbestos | Sampled – Not Detected | | | | Concrete render and MMMF insulation <1m2 to pipe cable sleeve on wall. | 1 | | R667226 | | |
| 12020 | ACTIVE | N | N167-00-2/001 | Booking Hall - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15691 | ACTIVE | N | N167-00-2/001/CLG-01 | Ceiling: Solid - 1 - Booking Hall - Station Building - Tooting Bec Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal above Metal Strip false ceiling | | | | YES | |



Hazardous Material Asset Register - Summary



N167-00 - Station Building - Tooting Bec Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 12021 | ACTIVE | N | N167-00-2/011 | Ticket Office - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18437 | ACTIVE | N | N167-00-2/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Tooting Bec Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal above Plasterboard False Ceiling | | | | YES | |
| 15692 | ACTIVE | N | N167-00-2/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Tooting Bec Stn | Void | Asbestos | No Access: Presumed | | | | Beneath false floor | | | | | YES |
| 12022 | ACTIVE | N | N167-00-2/021 | POM - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15694 | ACTIVE | N | N167-00-2/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Tooting Bec Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal above Plasterboard False Ceiling | | | | YES | |
| 15693 | ACTIVE | N | N167-00-2/021/FLR-01 | Floor - 1 - POM - Station Building - Tooting Bec Stn | Void | Asbestos | No Access: Presumed | | | | Beneath false floor | | | | | |
| 12023 | ACTIVE | N | N167-00-2/031 | Mess Room - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15695 | ACTIVE | N | N167-00-2/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Tooting Bec Stn | Void | Asbestos | Surveyed – Not Detected | | | | Supalux Board and Metal above Plasterboard False Ceiling | | | | YES | |
| 12024 | ACTIVE | N | N167-00-2/036 | Store - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15696 | ACTIVE | N | N167-00-2/036 | Store - Station Building - Tooting Bec Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding | | | | | |
| 12025 | ACTIVE | N | N167-00-2/037 | Toilet: Unisex - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15697 | ACTIVE | N | N167-00-2/037 | Toilet: Unisex - Station Building - Tooting Bec Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12026 | ACTIVE | N | N167-00-2/071 | Circulation Area - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18499 | ACTIVE | N | N167-00-2/071/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Tooting Bec Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal above Metal Strip false ceiling | | | | YES | |
| 12027 | ACTIVE | N | N167-00-2/082 | Lobby - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15698 | ACTIVE | N | N167-00-2/082 | Lobby - Station Building - Tooting Bec Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N167-00 - Station Building - Tooting Bec Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 12028 | ACTIVE | N | N167-00-2/083 | Lobby - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18722 | ACTIVE | N | N167-00-2/083/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Tooting Bec Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Plasterboard False Ceiling | | | | YES | |
| 12029 | ACTIVE | N | N167-00-2/151 | UMC - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15700 | ACTIVE | N | N167-00-2/151 | UMC - Station Building - Tooting Bec Stn | Rope Gaskets | Asbestos | Surveyed – Not Detected | | | | Cloth Webbing | | | | | |
| 18500 | ACTIVE | N | N167-00-2/151 | UMC - Station Building - Tooting Bec Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Red Oil Based Paint - 2no Girders to housing units Thickness .08mm; Est Quantity 6 lm; Analysis 32.24% | | | | | |
| 19949 | ACTIVE | N | N167-00-2/151 | UMC - Station Building - Tooting Bec Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Black & White Oil Based Paint - Girders Thickness .19mm; Est Quantity 18 lm; Analysis 4.87% | | | | | |
| 15704 | ACTIVE | N | N167-00-2/151 | UMC - Station Building - Tooting Bec Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Yellow Oil Based Paint - Stairs Thickness .25mm; Est Quantity 6 lm; Analysis 2.84% | | | | | |
| 15701 | ACTIVE | N | N167-00-2/151 | UMC - Station Building - Tooting Bec Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Grey Oil Based Paint - Pipework Thickness .33mm; Est Quantity 15 lm; Analysis 21.45% | | | | | |
| 15703 | ACTIVE | N | N167-00-2/151 | UMC - Station Building - Tooting Bec Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Green/ Grey Oil Based Paint - Girder Thickness .31mm; Est Quantity 15 lm; Analysis 2.85% | | | | | |
| 15702 | ACTIVE | N | N167-00-2/151 | UMC - Station Building - Tooting Bec Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Red Oil Based Paint - Pipework Thickness .07mm; Est Quantity 30 lm; Analysis 2.75% | | | | | |
| 15699 | ACTIVE | N | N167-00-2/151/FLR-01 | Floor - 1 - UMC - Station Building - Tooting Bec Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Lid to Storage Bin | | | | | |
| 18230 | ACTIVE | N | N167-00-2/171 | Escalator Incline - Station Building - Tooting Bec Stn | Caulking | Asbestos | Strongly Presumed | | | | Tunnel Ring Joints along incline - Rings sealed but may be present behind No access into esclator incline during 2024 re-inspection. Permit required with L&E | | | | | |
| 12030 | ACTIVE | N | N167-00-2/201 | Passage - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15706 | ACTIVE | N | N167-00-2/201/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Tooting Bec Stn | Void | Asbestos | No Access: Presumed | | | | Above - Metal Strip | | | | | |
| 15705 | ACTIVE | N | N167-00-2/201/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Tooting Bec Stn | Void | Asbestos | Sampled – Not Detected | | | | Cladding to steel within ceiling/ void - NADIS - above metal strip | | | | | |



Hazardous Material Asset Register - Summary



N167-00 - Station Building - Tooting Bec Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18501 | ACTIVE | N | N167-00-2/201/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Tooting Bec Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal above Plasterboard False Ceiling | | | | YES | |
| 12031 | ACTIVE | N | N167-00-2/202 | Passage - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12032 | ACTIVE | N | N167-00-2/236 | Passage - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12033 | ACTIVE | N | N167-00-2/237 | Lobby - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18723 | ACTIVE | N | N167-00-2/237/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Tooting Bec Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal above Plasterboard False Ceiling | | | | YES | |
| 15707 | ACTIVE | N | N167-00-2/237/FLR-01 | Floor - 1 - Lobby - Station Building - Tooting Bec Stn | Void | Asbestos | No Access: Presumed | | | | Beneath false floor | | | | | |
| 12034 | ACTIVE | N | N167-00-2/331 | Mess Room - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 69868 | ACTIVE | N | N167-00-2/331 | Mess Room - Station Building - Tooting Bec Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Cream matt paint to walls throughout room <0.02%, paint thickness 310um | | | R750476 | | |
| 69869 | ACTIVE | N | N167-00-2/331 | Mess Room - Station Building - Tooting Bec Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Cream matt paint to ceiling <0.02%, paint thickness 210um | | | R750476 | | |
| 15708 | ACTIVE | N | N167-00-2/331/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Tooting Bec Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal above Plasterboard False Ceiling | | | | YES | |
| 15709 | ACTIVE | N | N167-00-2/331/CLG-02 | Ceiling: Suspended - 2 - Mess Room - Station Building - Tooting Bec Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal above Plasterboard False Ceiling | | | | YES | |
| 12035 | ACTIVE | N | N167-00-2/401 | Bin Store - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15710 | ACTIVE | N | N167-00-2/401 | Bin Store - Station Building - Tooting Bec Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 18502 | ACTIVE | N | N167-00-2/401/CLG-01 | Ceiling: Solid - 1 - Bin Store - Station Building - Tooting Bec Stn | Lead/Leading | Lead Paint/Lead | Known | | | | White Oil Based Paint - Girder in Ceiling. Thickness .04mm; Est Quantity 4 sqm; Analysis 5.92% | | | | | |
| 12036 | ACTIVE | N | N167-00-2/406 | Store - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18503 | ACTIVE | N | N167-00-2/406/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Tooting Bec Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal above Plasterboard False Ceiling | | | | YES | |



Hazardous Material Asset Register - Summary



N167-00 - Station Building - Tooting Bec Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 12037 | ACTIVE | N | N167-00-2/411 | SVC - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15711 | ACTIVE | N | N167-00-2/411 | SVC - Station Building - Tooting Bec Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12038 | ACTIVE | N | N167-00-2/416 | Toilet: Female - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15712 | ACTIVE | N | N167-00-2/416/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Tooting Bec Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Plasterboard False Ceiling | | | | YES | |
| 12039 | ACTIVE | N | N167-00-2/417 | Toilet: Male - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15713 | ACTIVE | N | N167-00-2/417/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Tooting Bec Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Plasterboard False Ceiling | | | | YES | |
| 12040 | ACTIVE | N | N167-00-2/661 | Switch Room - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15714 | ACTIVE | N | N167-00-2/661 | Switch Room - Station Building - Tooting Bec Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12041 | ACTIVE | N | N167-00-2/662 | Switch Room - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18504 | ACTIVE | N | N167-00-2/662 | Switch Room - Station Building - Tooting Bec Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12042 | ACTIVE | N | N167-00-2/746 | SCR - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15715 | ACTIVE | N | N167-00-2/746/CLG-01 | Ceiling: Suspended - 1 -SCR - Station Building - Tooting Bec Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal, Fibreglass Lagging above Plasterboard Ceiling | | | | YES | |
| 15716 | ACTIVE | N | N167-00-2/746/FLR-01 | Floor - 1 - SCR - Station Building - Tooting Bec Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | |
| 12043 | ACTIVE | N | N167-00-2/751 | Station Control Room - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 69866 | ACTIVE | N | N167-00-2/751 | Station Control Room - Station Building - Tooting Bec Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Cream matt paint to walls throughout room <0.02%, paint thickness 230um | | | R750476 | | |
| 69867 | ACTIVE | N | N167-00-2/751 | Station Control Room - Station Building - Tooting Bec Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | White gloss concrete beam on ceiling <0.02%, paint thickness 750um | | | R750476 | | |



Hazardous Material Asset Register - Summary



N167-00 - Station Building - Tooting Bec Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---------------------------|-------------|------------|-------------|---------------------|-------------------|
| 18505 | ACTIVE | N | N167-00-2/751/FLR-01 | Floor - 1 - Station Control Room - Station Building - Tooting Bec Stn | Void | Asbestos | No Access: Presumed | | | | Above Meal Strip | | | | | |
| 15717 | ACTIVE | N | N167-00-2/751/FLR-01 | Floor - 1 - Station Control Room - Station Building - Tooting Bec Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | |
| 12044 | ACTIVE | N | N167-00-2/761 | Plant Room - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15720 | ACTIVE | N | N167-00-2/761 | Plant Room - Station Building - Tooting Bec Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing; | | | | | |
| 15719 | ACTIVE | N | N167-00-2/761/CLG-01 | Ceiling: Solid - 1 - Plant Room - Station Building - Tooting Bec Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Ceiling | | | | YES | |
| 15718 | ACTIVE | N | N167-00-2/761/FLR-01 | Floor - 1 - Plant Room - Station Building - Tooting Bec Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | |
| 12045 | ACTIVE | N | N167-00-2/771 | Pump Room - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15721 | ACTIVE | N | N167-00-2/771 | Pump Room - Station Building - Tooting Bec Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12046 | ACTIVE | N | N167-00-2/776 | Fan Room - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18506 | ACTIVE | N | N167-00-2/776 | Fan Room - Station Building - Tooting Bec Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | New Type | | | | | |
| 12047 | ACTIVE | N | N167-00-2/786 | Service Riser - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15722 | ACTIVE | N | N167-00-2/786 | Service Riser - Station Building - Tooting Bec Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 18664 | ACTIVE | N | N167-00-2/901 | Vent Shaft - Station Building - Tooting Bec Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 15723 | ACTIVE | N | N167-00-2/902 | Vent Shaft - Station Building - Tooting Bec Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12048 | ACTIVE | N | N167-00-3/081 | Circulation Area - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15724 | ACTIVE | N | N167-00-3/081 | Circulation Area - Station Building - Tooting Bec Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12049 | ACTIVE | N | N167-00-3/082 | Lobby - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N167-00 - Station Building - Tooting Bec Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|----------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18507 | ACTIVE | N | N167-00-3/082 | Lobby - Station Building - Tooting Bec Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12050 | ACTIVE | N | N167-00-3/161 | LMC - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15726 | ACTIVE | N | N167-00-3/161 | LMC - Station Building - Tooting Bec Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux by Entrance - Non Asbestos; | | | | | |
| 18724 | ACTIVE | N | N167-00-3/161 | LMC - Station Building - Tooting Bec Stn | Cable: Sheath | Asbestos | Surveyed – Not Detected | | | | Cables - Non Asbestos; | | | | | |
| 15725 | ACTIVE | N | N167-00-3/161 | LMC - Station Building - Tooting Bec Stn | Cable Ducts: Cement | Asbestos | Strongly Presumed | | | | Cement Cable Ducts (from Plat from 1 Invert?) Encapsulated | | | | | |
| 18247 | ACTIVE | N | N167-00-3/161 | LMC - Station Building - Tooting Bec Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Black Oil Based Paint - 2 no Escalators. Thickness .44mm; Est Quantity 4 sqm; Analysis 39.79% | | | | | |
| 15727 | ACTIVE | N | N167-00-3/161 | LMC - Station Building - Tooting Bec Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Blue Oil Based Paint - 2 no Girders. Thickness .20mm; Est Quantity 4 lm; Analysis 8.37% | | | | | |
| 12051 | ACTIVE | N | N167-00-3/201 | Passage - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18508 | ACTIVE | N | N167-00-3/201 | Passage - Station Building - Tooting Bec Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12052 | ACTIVE | N | N167-00-3/202 | Passage - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15728 | ACTIVE | N | N167-00-3/202/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Tooting Bec Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Panels | | | | YES | |
| 12053 | ACTIVE | N | N167-00-3/203 | Passage - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15729 | ACTIVE | N | N167-00-3/203/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Tooting Bec Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal Panels | | | | YES | |
| 12054 | ACTIVE | N | N167-00-3/204 | Passage - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18509 | ACTIVE | N | N167-00-3/204 | Passage - Station Building - Tooting Bec Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12055 | ACTIVE | N | N167-00-3/261 | Platform 1 - Northbound Local - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70495 | ACTIVE | N | N167-00-3/261 | Platform 1 - Northbound Local - Station Building - Tooting Bec Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable duct - total 1 no - To trackside wall, midway | | 1 | R728756 | N | Y |



Hazardous Material Asset Register - Summary



N167-00 - Station Building - Tooting Bec Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 70496 | ACTIVE | N | N167-00-3/261 | Platform 1 - Northbound Local - Station Building - Tooting Bec Stn | Cable Wrap | Asbestos | Known | | | | Platform Invert - Cable wrapping - total 2 x 1m - To HV cable , midway and arrivals end | 1 | 2 | R728756 | | |
| 70492 | ACTIVE | N | N167-00-3/261 | Platform 1 - Northbound Local - Station Building - Tooting Bec Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cable - total 1 no throughout - To J Hangers | | 1 | R728756 | | |
| 70490 | ACTIVE | N | N167-00-3/261 | Platform 1 - Northbound Local - Station Building - Tooting Bec Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728756 | | |
| 44924 | ACTIVE | N | N167-00-3/261 | Platform 1 - Northbound Local - Station Building - Tooting Bec Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | NB Tunnel - Left hand side of tail end of tunnel, 2nd cable shelf from top - 2x10mm Cables | | 2 | | N | N |
| 70497 | ACTIVE | N | N167-00-3/261 | Platform 1 - Northbound Local - Station Building - Tooting Bec Stn | Ducts | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal cable ducts - total 12 no - To platform wall, midway by access hatch | | 12 | R728756 | | |
| 70498 | ACTIVE | N | N167-00-3/261 | Platform 1 - Northbound Local - Station Building - Tooting Bec Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable duct - total 1 no - To trackside wall | | 1 | R728756 | N | Y |
| 70493 | ACTIVE | N | N167-00-3/261 | Platform 1 - Northbound Local - Station Building - Tooting Bec Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement panels - total sporadic, throughout - To access hatch/vent above arches to trackside wall | | | R728756 | N | Y |
| 70489 | ACTIVE | N | N167-00-3/261 | Platform 1 - Northbound Local - Station Building - Tooting Bec Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728756 | | |
| 70491 | ACTIVE | N | N167-00-3/261 | Platform 1 - Northbound Local - Station Building - Tooting Bec Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 8 no - To arrivals track wall | | 8 | R728756 | N | Y |
| 15731 | ACTIVE | N | N167-00-3/261/ FLR-01 | Floor - 1 - Platform 1 - Station Building - Tooting Bec Stn | Cable Duct: Other | Asbestos | Strongly Presumed | | | | Encapsulated - TLL Connect 6 x Cables Ducts - Leading from platform inverts through to concourse inverts/cable ways No access into platform inverts during 2020 re-inspection. Confined space entry required. | | | | | YES |
| 15730 | ACTIVE | N | N167-00-3/261/ FLR-01 | Floor - 1 - Platform 1 - Station Building - Tooting Bec Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 2 x Cables - 2nd J Hanger down on Pit side wall No access into platform inverts during 2020 re-inspection. Confined space entry required. | | 2 | | | YES |
| 12056 | ACTIVE | N | N167-00-3/262 | Platform 2 - Southbound Local - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44925 | ACTIVE | N | N167-00-3/262 | Platform 2 - Southbound Local - Station Building - Tooting Bec Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | SB Tunnel - Head of Tunnel - 3no Cables | | 3 | | N | N |



Hazardous Material Asset Register - Summary



N167-00 - Station Building - Tooting Bec Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|----------------------|---------------|-------------------------|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 70507 | ACTIVE | N | N167-00-3/262 | Platform 2 - Southbound Local - Station Building - Tooting Bec Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable duct - total 1 no - To trackside wall, departure end | | 1 | R728756 | N | Y |
| 44926 | ACTIVE | N | N167-00-3/262 | Platform 2 - Southbound Local - Station Building - Tooting Bec Stn | Cement Troughing | Asbestos | Presumed | | | | SB Tunnel - 2m into Tunnel - Troughing | | | | N | N |
| 70500 | ACTIVE | N | N167-00-3/262 | Platform 2 - Southbound Local - Station Building - Tooting Bec Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728756 | | |
| 70501 | ACTIVE | N | N167-00-3/262 | Platform 2 - Southbound Local - Station Building - Tooting Bec Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable duct - total 1 no - Trackside wall arrivals end | | 1 | R728756 | N | Y |
| 70505 | ACTIVE | N | N167-00-3/262 | Platform 2 - Southbound Local - Station Building - Tooting Bec Stn | Cable Wrap | Asbestos | Known | | | | Platform Invert - Cable wrapping - total 2 no - To HV cables, trackside wall midway and departure end | | 2 | R728756 | | |
| 70506 | ACTIVE | N | N167-00-3/262 | Platform 2 - Southbound Local - Station Building - Tooting Bec Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 2no x 8 - To platform wall, midway | | 16 | R728756 | N | Y |
| 70509 | ACTIVE | N | N167-00-3/262 | Platform 2 - Southbound Local - Station Building - Tooting Bec Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 6 no - To trackside wall, departure end | | 6 | R728756 | N | Y |
| 18725 | ACTIVE | N | N167-00-3/262 | Platform 2 - Southbound Local - Station Building - Tooting Bec Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 15mm Cable No access into platform inverts during 2020 re-inspection. Confined space entry required. | | 1 | | | |
| 70499 | ACTIVE | N | N167-00-3/262 | Platform 2 - Southbound Local - Station Building - Tooting Bec Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728756 | | |
| 70502 | ACTIVE | N | N167-00-3/262 | Platform 2 - Southbound Local - Station Building - Tooting Bec Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cable - total 1 no throughout - To J Hangers | | 1 | R728756 | | |
| 70503 | ACTIVE | N | N167-00-3/262 | Platform 2 - Southbound Local - Station Building - Tooting Bec Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 2no x 8 - To platform wall | | 16 | R728756 | N | Y |
| 70504 | ACTIVE | N | N167-00-3/262 | Platform 2 - Southbound Local - Station Building - Tooting Bec Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | Platform Invert - Bitumen cable duct - total 1 no - To trackside wall, midway | | 1 | R728756 | N | Y |
| 15733 | ACTIVE | N | N167-00-3/262/ FLR-01 | Floor - 1 - Platform 2 - Station Building - Tooting Bec Stn | Cable Ducts: Bitumen | Asbestos | Surveyed – Not Detected | | | | Plat 2 Invert- LHS Bitumem Ducts Cable Way- Non Asbestos | | | | | YES |
| 18510 | ACTIVE | N | N167-00-3/262/ FLR-01 | Floor - 1 - Platform 2 - Station Building - Tooting Bec Stn | Cable Duct: Other | Asbestos | Strongly Presumed | | | | Plat 2 Invert - 6 x Cables Ducts - Leading from platform inverts through to concourse inverts/cable ways No access into platform inverts during 2020 re-inspection. Confined space entry required. | | 6 | | | YES |



Hazardous Material Asset Register - Summary



N167-00 - Station Building - Tooting Bec Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 15543 | ACTIVE | N | N167-00-3/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Tooting Bec Stn | Cable: Wrap | Asbestos | Strongly Presumed | | | | Plat 2 Invert - 1st J Hanger at ends of platform at trackside penetration - Cable Wrapping No access into platform inverts during 2020 re-inspection. Confined space entry required. | | | | | YES |
| 15732 | ACTIVE | N | N167-00-3/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Tooting Bec Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 2 Invert - Located on 2nd J Hanger running length of invert - 2x10mm Cables No access into platform inverts during 2020 re-inspection. Confined space entry required. | | 2 | | | YES |
| 12057 | ACTIVE | N | N167-00-3/406 | CER - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15544 | ACTIVE | N | N167-00-3/406/FLR-01 | Floor - 1 - CER - Station Building - Tooting Bec Stn | Void | Asbestos | Surveyed – Not Detected | | | | Beneath Computer Flooring | | | | | YES |
| 12058 | ACTIVE | N | N167-00-3/661 | Switch Room - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18270 | ACTIVE | N | N167-00-3/661 | Switch Room - Station Building - Tooting Bec Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12059 | ACTIVE | N | N167-00-3/664 | Switch Room - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15545 | ACTIVE | N | N167-00-3/664 | Switch Room - Station Building - Tooting Bec Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12060 | ACTIVE | N | N167-00-3/665 | Service Riser - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15546 | ACTIVE | N | N167-00-3/665 | Service Riser - Station Building - Tooting Bec Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 15mm Cable | | 1 | | | |
| 12061 | ACTIVE | N | N167-00-3/667 | Switch Room - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18271 | ACTIVE | N | N167-00-3/667/FLR-01 | Floor - 1 - Switch Room - Station Building - Tooting Bec Stn | Debris: Other | Asbestos | Surveyed – Not Detected | | | | Supalux Debris on Floor | | | | | |
| 12062 | ACTIVE | N | N167-00-3/668 | Switch Room - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15547 | ACTIVE | N | N167-00-3/668 | Switch Room - Station Building - Tooting Bec Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12063 | ACTIVE | N | N167-00-3/669 | Switch Cupboard - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N167-00 - Station Building - Tooting Bec Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|---------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18657 | ACTIVE | N | N167-00-3/669 | Switch Cupboard - Station Building - Tooting Bec Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding above Window | | | | | |
| 12064 | ACTIVE | N | N167-00-3/711 | CER - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15549 | ACTIVE | N | N167-00-3/711 | CER - Station Building - Tooting Bec Stn | Vinyl tiles | Asbestos | Known | | | | Green & White Tiles - Chrysotile - some removed | | | | | |
| 19479 | INACTIVE | N | N167-00-3/711 | CER - Station Building - Tooting Bec Stn | Boarding: Cement | Asbestos | No Access: Presumed | | | | Boarding - Cement Made inactive duplication with 18710 | | | | | |
| 18243 | ACTIVE | N | N167-00-3/711/CLG-01 | Ceiling: Solid - 1 - CER - Station Building - Tooting Bec Stn | Vinyl tiles | Asbestos | Known | | | | Green & White Tiles - Chrysotile Note - Most of the tiles have been removed. Remaining tiles are in good condition. | | | | | |
| 15548 | ACTIVE | N | N167-00-3/711/FLR-01 | Floor - 1 - CER - Station Building - Tooting Bec Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Vinyl Tiles | | | | | |
| 18710 | ACTIVE | N | N167-00-3/711/WAL-001 | Wall: Internal - 1 - CER - Station Building - Tooting Bec Stn | Boarding: Cement | Asbestos | Strongly Presumed | | | | Cement Panels under capacitors top shelf wall 3 | | 1 | | | |
| 15552 | INACTIVE | N | N167-00-3/711/WAL-001 | Wall: Internal - 1 - CER - Station Building - Tooting Bec Stn | PCBs | Polychlorinated biphenyl | Removed | | | | 6 x PCB's - Fair Condition Serial Nos. 186420, 186422, 186481, 186468, 186566, 197489 Re inspected 14/04/2015 Re inspection 2023 - removed | | 6 | | | |
| 53678 | ACTIVE | N | N167-00-3/711/WAL-002 | Wall: Internal - 2 - CER - Station Building - Tooting Bec Stn | Other Boarding | Asbestos | Presumed | | | | brown panel to 600v box to wall 2 | | | | | |
| 15550 | ACTIVE | N | N167-00-3/711/WAL-002 | Wall: Internal - 2 - CER - Station Building - Tooting Bec Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | SP Cables - 3 cables running throughout 2 top hanger going to trackside wall 5 1 running to invert in second hanger | | 5 | | | |
| 53679 | ACTIVE | N | N167-00-3/711/WAL-002 | Wall: Internal - 2 - CER - Station Building - Tooting Bec Stn | Cable: Sheath | Asbestos | Presumed | | | | thin cable to 600v box on wall 2 | | | | | |
| 67609 | ACTIVE | N | N167-00-3/711/WAL-003 | Wall: Internal - 3 - CER - Station Building - Tooting Bec Stn | Other Boarding | Asbestos | Presumed | | | | 2x brown board to third row of frame on wall 3 | | | | | |
| 53677 | ACTIVE | N | N167-00-3/711/WAL-003 | Wall: Internal - 3 - CER - Station Building - Tooting Bec Stn | Other Boarding | Asbestos | Presumed | | | | 6 x brown composite board bottom shelf to rack wall 3 | | | | | |
| 18272 | INACTIVE | N | N167-00-3/711/WAL-003 | Wall: Internal - 3 - CER - Station Building - Tooting Bec Stn | Westing house Boxes | Asbestos | Removed | | | | Westinghouse Box - Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within 2023 reinspection confirmed removed. | | 1 | | | |



Hazardous Material Asset Register - Summary



N167-00 - Station Building - Tooting Bec Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|------------------------|--------------------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 53676 | ACTIVE | N | N167-00-3/711/WAL-003 | Wall: Internal - 3 - CER - Station Building - Tooting Bec Stn | Other Boarding | Asbestos | Presumed | | | | 2 x brown composite board wall 3 To top shelf of rack | | | | | |
| 15551 | ACTIVE | N | N167-00-3/711/WAL-005 | Wall: Internal - 5 - CER - Station Building - Tooting Bec Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Paxolin Board - onsite inspection confirmed new relay and board | | | | | |
| 12065 | ACTIVE | N | N167-00-3/712 | Relay Room - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 67615 | ACTIVE | N | N167-00-3/712 | Relay Room - Station Building - Tooting Bec Stn | Boarding: Cement | Asbestos | Presumed | | | | asbestos presumed cement panels x2 to framework | | 2 | | | |
| 18334 | ACTIVE | N | N167-00-3/712 | Relay Room - Station Building - Tooting Bec Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables x 4 running from middle fuse bay wall 1 1 on top j hanger to trackside exit wall 2 and 3 cables bottom hanger entering invert to floor wall 1 | | 6 | | | |
| 44317 | ACTIVE | N | N167-00-3/712 | Relay Room - Station Building - Tooting Bec Stn | Cable Ducts: Cement | Asbestos | Presumed | | | | filled in cement ductwork Cement ductwork not visible beneath filling on top - therefore not scored during 2020 re-inspection. | | | | | |
| 15560 | ACTIVE | N | N167-00-3/712 | Relay Room - Station Building - Tooting Bec Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Small Transformer - Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | | |
| 18335 | INACTIVE | N | N167-00-3/712 | Relay Room - Station Building - Tooting Bec Stn | PCBs | Polychlorinated biphenyl | Removed | | | | PCB's - Fair Condition Serial Nos. 197473; 197485; 197477; 197479; 197481; 197460; 197478 Inspected 14/04/2015 Reinspection 2023 confirmed removed | | 7 | | | |
| 15558 | INACTIVE | N | N167-00-3/712/CLG-01 | Ceiling: Solid - 1 - Relay Room - Station Building - Tooting Bec Stn | Void | Asbestos | No Access: Presumed | | | | Above False Ceiling | | | | YES | |
| 15557 | ACTIVE | N | N167-00-3/712/CLG-01 | Ceiling: Solid - 1 - Relay Room - Station Building - Tooting Bec Stn | Vinyl tiles | Asbestos | Known | | | | Marley Tiles to Wall - known - Chrysotile - some removed | | | | | |
| 15553 | ACTIVE | N | N167-00-3/712/FLR-01 | Floor - 1 - Relay Room - Station Building - Tooting Bec Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Vinyl Tiles - NAD | | | | | |
| 53672 | ACTIVE | N | N167-00-3/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Tooting Bec Stn | Other Boarding | Asbestos | Presumed | | | | 1 x long brown panel above cement panel to 3rd shelf on rack wall 1 | | | | | |
| 15554 | ACTIVE | N | N167-00-3/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Tooting Bec Stn | Vinyl tiles | Asbestos | Known | | | | Marley Tiles to Wall - known - Chrysotile - some removed | | | | | |



Hazardous Material Asset Register - Summary



N167-00 - Station Building - Tooting Bec Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|----------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 15559 | INACTIVE | N | N167-00-3/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Tooting Bec Stn | Westing house Boxes | Asbestos | Removed | | | | Westinghouse Box Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within 2023 re inspection removed | | 1 | | | |
| 53674 | ACTIVE | N | N167-00-3/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Tooting Bec Stn | Other Boarding | Asbestos | Presumed | | | | 3 long brown composite panels to bottom shelf of rack to wall 1 above presumed cement panel | | | | | |
| 15561 | ACTIVE | N | N167-00-3/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Tooting Bec Stn | Boarding: Cement | Asbestos | Strongly Presumed | | | | Rack to wall 1 1 x long brown panel with cement panel base to 3 rd shelf 1 x cracked cement panel to bottom of rack | | 2 | | | |
| 53671 | ACTIVE | N | N167-00-3/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Tooting Bec Stn | Other Boarding | Asbestos | Presumed | | | | 8 x Black Composite panel to rack - Top of rack to capacitors 693T wall 1 | | | | | |
| 18333 | ACTIVE | N | N167-00-3/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Tooting Bec Stn | Vinyl tiles | Asbestos | Known | | | | Marley Tiles to Wall - known - Chrysotile - some removed | | | | | |
| 53673 | ACTIVE | N | N167-00-3/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Tooting Bec Stn | Cable: Sheath | Asbestos | Presumed | | | | thin white cable to 600v box wall 2 | | | | | |
| 53670 | ACTIVE | N | N167-00-3/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Tooting Bec Stn | Other Boarding | Asbestos | Presumed | | | | 600v Box with brown composite panel within | | | | | |
| 15555 | ACTIVE | N | N167-00-3/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Tooting Bec Stn | Vinyl tiles | Asbestos | Known | | | | Marley Tiles to Wall - known - Chrysotile - some removed | | | | | |
| 15556 | ACTIVE | N | N167-00-3/712/WAL-004 | Wall: Internal - 4 - Relay Room - Station Building - Tooting Bec Stn | Vinyl tiles | Asbestos | Known | | | | Marley Tiles to Wall - known - Chrysotile - some removed | | | | | |
| 12066 | ACTIVE | N | N167-00-3/731 | Switch Cupboard - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18711 | ACTIVE | N | N167-00-3/731 | Switch Cupboard - Station Building - Tooting Bec Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12067 | ACTIVE | N | N167-00-3/732 | CER - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15564 | ACTIVE | N | N167-00-3/732 | CER - Station Building - Tooting Bec Stn | Cable Ducts: Bitumen | Asbestos | Surveyed – Not Detected | | | | Bitumem Ducts to Inverts - Non Asbestos | | | | | |
| 15563 | ACTIVE | N | N167-00-3/732/FLR-01 | Floor - 1 - CER - Station Building - Tooting Bec Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | | | | | | |



Hazardous Material Asset Register - Summary



N167-00 - Station Building - Tooting Bec Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 12068 | ACTIVE | N | N167-00-3/733 | CER - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15870 | ACTIVE | N | N167-00-3/733 | CER - Station Building - Tooting Bec Stn | Other Boarding | Asbestos | Sampled – Not Detected | | | | Boarding between the distribution board and CMS; also between the Changeover contactor and the CMS | | | | | |
| 18679 | ACTIVE | N | N167-00-3/733/FLR-01 | Floor - 1 - CER - Station Building - Tooting Bec Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Flooring | | | | | |
| 15871 | ACTIVE | N | N167-00-3/733/WAL-001 | Wall: Internal - 1 - CER - Station Building - Tooting Bec Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Grey Switch Boxes 60amp - Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within | | 2 | | | |
| 12069 | ACTIVE | N | N167-00-A/781 | TXR - Station Building - Tooting Bec Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18658 | ACTIVE | N | N167-00-A/781 | TXR - Station Building - Tooting Bec Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access | | | | | |
| 15562 | ACTIVE | N | N167-00-B/781 | Roof Access - Station Building - Tooting Bec Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |

N169-00 - Station Building - Tooting Broadway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 12070 | ACTIVE | N | N169-00-1/001 | Booking Hall - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12071 | ACTIVE | N | N169-00-1/011 | Ticket Office - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18716 | ACTIVE | N | N169-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Tooting Broadway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Fibreglass Pipe Lagging above Plasterboard Ceiling | | | | YES | |
| 15602 | ACTIVE | N | N169-00-1/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Tooting Broadway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Metal Tray & PVC Cables beneath False Wooden Floor | | | | | YES |
| 12072 | ACTIVE | N | N169-00-1/021 | POM - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15603 | ACTIVE | N | N169-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Tooting Broadway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Fibreglass Pipe Lagging above Plasterboard Ceiling | | | | | |
| 18347 | ACTIVE | N | N169-00-1/021/FLR-01 | Floor - 1 - POM - Station Building - Tooting Broadway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Metal Tray & PVC Cables beneath False Wooden Floor | | | | | YES |



Hazardous Material Asset Register - Summary



N169-00 - Station Building - Tooting Broadway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 12073 | ACTIVE | N | N169-00-1/031 | Mess Room - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15604 | ACTIVE | N | N169-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Tooting Broadway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Supalux Boarding above Plasterboard Ceiling | | | | YES | |
| 12074 | ACTIVE | N | N169-00-1/036 | Toilet: Unisex - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18229 | ACTIVE | N | N169-00-1/036 | Toilet: Unisex - Station Building - Tooting Broadway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding | | | | | |
| 15605 | ACTIVE | N | N169-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Tooting Broadway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Plasterboard Ceiling | | | | YES | |
| 12075 | ACTIVE | N | N169-00-1/071 | Circulation Area - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15606 | ACTIVE | N | N169-00-1/071/CLG-01 | Ceiling: Solid - 1 - Circulation Area - Station Building - Tooting Broadway Stn | Glazing Rope | Asbestos | Sampled – Not Detected | | | | Rope Seal on Glass Ceilings. Glazing appears NAD in latest Type 2/3 | | | | | |
| 12076 | ACTIVE | N | N169-00-1/081 | Lobby - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12077 | ACTIVE | N | N169-00-1/082 | Lobby - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12078 | ACTIVE | N | N169-00-1/236 | Passage - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15608 | ACTIVE | N | N169-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Tooting Broadway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Plasterboard Ceiling | | | | YES | |
| 12079 | ACTIVE | N | N169-00-1/237 | Passage - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18661 | ACTIVE | N | N169-00-1/237/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Tooting Broadway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Plasterboard Ceiling | | | | YES | |
| 18349 | ACTIVE | N | N169-00-1/237/FLR-01 | Floor - 1 - Passage - Station Building - Tooting Broadway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Metal Tray & PVC Cables beneath False Wooden Floor | | | | | YES |
| 12080 | ACTIVE | N | N169-00-1/281 | Station Control Room - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N169-00 - Station Building - Tooting Broadway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|-------------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 15609 | ACTIVE | N | N169-00-1/281/FLR-01 | Floor - 1 - Station Control Room - Station Building - Tooting Broadway Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Wooden Floor | | | | | YES |
| 12081 | ACTIVE | N | N169-00-1/316 | Locker Room - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15610 | ACTIVE | N | N169-00-1/316 | Locker Room - Station Building - Tooting Broadway Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Supalux; Foam Insulation Board | | | | | |
| 15611 | ACTIVE | N | N169-00-1/316/WAL-001 | Wall: Internal - 1 - Locker Room - Station Building - Tooting Broadway Stn | | Anthrax | Surveyed – Not Detected | | | | No Anthrax Detected | | | | | |
| 12082 | ACTIVE | N | N169-00-1/331 | Mess Room - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19951 | ACTIVE | N | N169-00-1/331 | Mess Room - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 15612 | ACTIVE | N | N169-00-1/331/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Tooting Broadway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Plasterboard Ceiling | | | | YES | |
| 12083 | ACTIVE | N | N169-00-1/396 | SVC - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12084 | ACTIVE | N | N169-00-1/401 | Bin Store - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12085 | ACTIVE | N | N169-00-1/412 | Store - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18350 | ACTIVE | N | N169-00-1/412 | Store - Station Building - Tooting Broadway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 12086 | ACTIVE | N | N169-00-1/416 | Toilet: Unisex - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12087 | ACTIVE | N | N169-00-1/417 | Toilet: Unisex - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18351 | ACTIVE | N | N169-00-1/417/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Tooting Broadway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Plasterboard Ceiling | | | | YES | |
| 12088 | ACTIVE | N | N169-00-1/451 | ATM - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N169-00 - Station Building - Tooting Broadway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|------------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 12089 | ACTIVE | N | N169-00-1/576 | Fan Room - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15618 | ACTIVE | N | N169-00-1/576 | Fan Room - Station Building - Tooting Broadway Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Grey Oil Based Paint - Fan Thickness .08mm; Est Quantity 4sqm; Analysis 1.22% | | | | | |
| 25678 | ACTIVE | N | N169-00-1/576/CLG-01 | Ceiling: Solid - 1 - Fan Room - Station Building - Tooting Broadway Stn | Void | Asbestos | Sampled – Not Detected | | | | Concrete above Plasterboard Ceiling. The filler between the concrete slab - NADIS | | | | | |
| 25677 | ACTIVE | N | N169-00-1/576/CLG-01 | Ceiling: Solid - 1 - Fan Room - Station Building - Tooting Broadway Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plaster Board | | | | | |
| 15620 | ACTIVE | N | N169-00-1/577 | UMC Access - Station Building - Tooting Broadway Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Black Oil Based Paint - Stairs Thickness .12mm; Est Quantity 6 lm; Analysis 28.08% | | | | | |
| 12090 | ACTIVE | N | N169-00-1/661 | Switch Room - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18352 | ACTIVE | N | N169-00-1/661/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Tooting Broadway Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box(es) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 2 | | | |
| 25851 | ACTIVE | N | N169-00-1/661/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Tooting Broadway Stn | Rope Gaskets | Asbestos | Sampled – Not Detected | | | | 1 x Hessian Rope Gasket to floor of access cover. Red CFS - Asset no. 00136572 | | 1 | | N | N |
| 15621 | ACTIVE | N | N169-00-1/661/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Tooting Broadway Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Red Switch Box 30amp - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 12091 | ACTIVE | N | N169-00-1/761 | Service Riser - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12092 | ACTIVE | N | N169-00-2/081 | Passage - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12093 | ACTIVE | N | N169-00-2/151 | UMC - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18353 | ACTIVE | N | N169-00-2/151 | UMC - Station Building - Tooting Broadway Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Red Oil Based Paint - Pipework Thickness .09mm; Est Quantity 20 lm; Analysis 4.21% | | | | | |
| 15628 | ACTIVE | N | N169-00-2/151 | UMC - Station Building - Tooting Broadway Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Red Oil Based Paint - 2no Girder Housing Units Thickness .10mm; Est Quantity 6 lm; Analysis 46.55% | | 2 | | | |



Hazardous Material Asset Register - Summary



N169-00 - Station Building - Tooting Broadway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 15626 | ACTIVE | N | N169-00-2/151/CLG-01 | Ceiling: Suspended - 1 - UMC - Station Building - Tooting Broadway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | To Ceiling | | | | | |
| 15625 | ACTIVE | N | N169-00-2/151/DOR-01 | Door - 1 - UMC - Station Building - Tooting Broadway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding around Door | | | | | |
| 15624 | ACTIVE | N | N169-00-2/151/FLR-01 | Floor - 1 - UMC - Station Building - Tooting Broadway Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Lid to Storage Bin | | | | | |
| 25854 | ACTIVE | N | N169-00-2/151/WAL-004 | Wall: Internal - 4 - UMC - Station Building - Tooting Broadway Stn | Rope Gaskets | Asbestos | Sampled – Not Detected | | | | 1 x Hessian Rope Gasket to rear of access cover. Red Spot Fuse Board (new), Asset no.00136615, to wall 4 of UMC 1,2 & 3 | | | | N | N |
| 15627 | ACTIVE | N | N169-00-2/151/WAL-004 | Wall: Internal - 4 - UMC - Station Building - Tooting Broadway Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box(es) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 18717 | ACTIVE | N | N169-00-2/171 | Escalator Incline - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12094 | ACTIVE | N | N169-00-2/236 | Lobby - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15629 | ACTIVE | N | N169-00-2/236 | Lobby - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12095 | ACTIVE | N | N169-00-2/237 | Passage - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15630 | ACTIVE | N | N169-00-2/237 | Passage - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12096 | ACTIVE | N | N169-00-2/411 | Store - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15631 | ACTIVE | N | N169-00-2/411 | Store - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12097 | ACTIVE | N | N169-00-2/551 | Yard - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15632 | ACTIVE | N | N169-00-2/551 | Yard - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12098 | ACTIVE | N | N169-00-2/552 | Yard - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12099 | ACTIVE | N | N169-00-2/661 | Switch Room - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N169-00 - Station Building - Tooting Broadway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18418 | ACTIVE | N | N169-00-2/661/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Tooting Broadway Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box(es) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 3 | | | |
| 15633 | ACTIVE | N | N169-00-2/661/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Tooting Broadway Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Grey Switch Box 30amp - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 12100 | ACTIVE | N | N169-00-2/662 | Service Riser - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15634 | ACTIVE | N | N169-00-2/662 | Service Riser - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12101 | ACTIVE | N | N169-00-2/663 | Switch Cupboard - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18718 | ACTIVE | N | N169-00-2/663 | Switch Cupboard - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12102 | ACTIVE | N | N169-00-2/731 | CER - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18244 | ACTIVE | N | N169-00-2/731/FLR-01 | Floor - 1 - CER - Station Building - Tooting Broadway Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete & Metal Tray beneath Computer Flooring | | | | | YES |
| 15635 | ACTIVE | N | N169-00-2/731/WAL-004 | Wall: Internal - 4 - CER - Station Building - Tooting Broadway Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 2x Switch boxes 60amp No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | | | | |
| 25853 | ACTIVE | N | N169-00-2/731/WAL-004 | Wall: Internal - 4 - CER - Station Building - Tooting Broadway Stn | Rope Gaskets | Asbestos | Sampled – Not Detected | | | | 1 x Hessian Rope Gasket to rear of access cover. Red CFS Asset no. 00136628. NOTE – flash guards within are fibreglass, non-ACM. | | | | N | N |
| 25852 | ACTIVE | N | N169-00-2/731/WAL-004 | Wall: Internal - 4 - CER - Station Building - Tooting Broadway Stn | Rope Gaskets | Asbestos | Sampled – Not Detected | | | | 1 x Hessian Rope Gasket to rear of access cover. Red CFS, Asset no. 00136627. NOTE – flash guards within are fibreglass non-ACM | | | | N | N |
| 12103 | ACTIVE | N | N169-00-2/746 | SCR - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19948 | ACTIVE | N | N169-00-2/746 | SCR - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12104 | ACTIVE | N | N169-00-2/761 | Computer Equipment Cupboard - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N169-00 - Station Building - Tooting Broadway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|--------------------------|-------------|------------|-------------|---------------------|-------------------|
| 15636 | ACTIVE | N | N169-00-2/761 | Computer Equipment Cupboard - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12105 | ACTIVE | N | N169-00-2/762 | Computer Equipment Cupboard - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18419 | ACTIVE | N | N169-00-2/762 | Computer Equipment Cupboard - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12106 | ACTIVE | N | N169-00-2/763 | Computer Equipment Cupboard - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19344 | ACTIVE | N | N169-00-2/763 | Computer Equipment Cupboard - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12107 | ACTIVE | N | N169-00-2/764 | Computer Equipment Cupboard - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15637 | ACTIVE | N | N169-00-2/764 | Computer Equipment Cupboard - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12108 | ACTIVE | N | N169-00-2/765 | Computer Equipment Cupboard - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19952 | ACTIVE | N | N169-00-2/765 | Computer Equipment Cupboard - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12109 | ACTIVE | N | N169-00-2/766 | Computer Equipment Cupboard - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18420 | ACTIVE | N | N169-00-2/766 | Computer Equipment Cupboard - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12110 | ACTIVE | N | N169-00-2/776 | Fan Room - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15638 | ACTIVE | N | N169-00-2/776 | Fan Room - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12111 | ACTIVE | N | N169-00-2/781 | TXR - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15639 | ACTIVE | N | N169-00-2/781 | TXR - Station Building - Tooting Broadway Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access | | | | | |



Hazardous Material Asset Register - Summary



N169-00 - Station Building - Tooting Broadway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 12112 | ACTIVE | N | N169-00-2/782 | TXR - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18421 | ACTIVE | N | N169-00-2/782 | TXR - Station Building - Tooting Broadway Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access | | | | | |
| 15640 | ACTIVE | N | N169-00-2/791 | Vent Shaft - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12113 | ACTIVE | N | N169-00-2/901 | SER - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15641 | ACTIVE | N | N169-00-2/901 | SER - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12114 | ACTIVE | N | N169-00-3/071 | Circulation Area - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15642 | ACTIVE | N | N169-00-3/071 | Circulation Area - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12115 | ACTIVE | N | N169-00-3/161 | LMC - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18719 | ACTIVE | N | N169-00-3/161 | LMC - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 18422 | ACTIVE | N | N169-00-3/161 | LMC - Station Building - Tooting Broadway Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Grey Oil Based Paint - Girder Thickness .31mm; Est Quantity 4 lm; Analysis 21.13% | | | | | |
| 12116 | ACTIVE | N | N169-00-3/201 | Passage - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15643 | ACTIVE | N | N169-00-3/201 | Passage - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12117 | ACTIVE | N | N169-00-3/202 | Passage - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15644 | ACTIVE | N | N169-00-3/202 | Passage - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12118 | ACTIVE | N | N169-00-3/203 | Passage - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15645 | ACTIVE | N | N169-00-3/203 | Passage - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12119 | ACTIVE | N | N169-00-3/204 | Passage - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N169-00 - Station Building - Tooting Broadway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 15646 | ACTIVE | N | N169-00-3/204 | Passage - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12120 | ACTIVE | N | N169-00-3/205 | Passage - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18423 | ACTIVE | N | N169-00-3/205 | Passage - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12121 | ACTIVE | N | N169-00-3/206 | Passage - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15647 | ACTIVE | N | N169-00-3/206 | Passage - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12122 | ACTIVE | N | N169-00-3/207 | Passage - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15648 | ACTIVE | N | N169-00-3/207 | Passage - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12123 | ACTIVE | N | N169-00-3/261 | Platform 1 - Northbound Local - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70474 | ACTIVE | N | N169-00-3/261 | Platform 1 - Northbound Local - Station Building - Tooting Broadway Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Small Westinghouse box - total 1 no - Trackside wall - departure end | | 1 | R728755 | | |
| 70470 | ACTIVE | N | N169-00-3/261 | Platform 1 - Northbound Local - Station Building - Tooting Broadway Stn | Cable Wrap | Asbestos | Known | | | | Platform Invert - Woven cloth - total 1 no - To pipe, trackside wall - midway | | 1 | R728755 | | |
| 70466 | ACTIVE | N | N169-00-3/261 | Platform 1 - Northbound Local - Station Building - Tooting Broadway Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 2 x 4no - To arrivals end - trackside wall | | 8 | R728755 | N | Y |
| 70464 | ACTIVE | N | N169-00-3/261 | Platform 1 - Northbound Local - Station Building - Tooting Broadway Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728755 | | |
| 70475 | ACTIVE | N | N169-00-3/261 | Platform 1 - Northbound Local - Station Building - Tooting Broadway Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable duct - total 2 no - Trackside wall - departure end | | 2 | R728755 | N | Y |
| 70473 | ACTIVE | N | N169-00-3/261 | Platform 1 - Northbound Local - Station Building - Tooting Broadway Stn | Cable Wrap | Asbestos | Known | | | | Platform Invert - Wrapping cloth - total 1 no - To platform wall - departure end | | 1 | R728755 | | |
| 70472 | ACTIVE | N | N169-00-3/261 | Platform 1 - Northbound Local - Station Building - Tooting Broadway Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 6 no - To platform wall - midway | | 6 | R728755 | N | Y |
| 70469 | ACTIVE | N | N169-00-3/261 | Platform 1 - Northbound Local - Station Building - Tooting Broadway Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable duct - total 6 no - To platform wall - midway | | 6 | R728755 | N | Y |



Hazardous Material Asset Register - Summary



N169-00 - Station Building - Tooting Broadway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 70467 | ACTIVE | N | N169-00-3/261 | Platform 1 - Northbound Local - Station Building - Tooting Broadway Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - total 6 no - To J Hangers throughout | | 6 | R728755 | | |
| 70465 | ACTIVE | N | N169-00-3/261 | Platform 1 - Northbound Local - Station Building - Tooting Broadway Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728755 | | |
| 70471 | ACTIVE | N | N169-00-3/261 | Platform 1 - Northbound Local - Station Building - Tooting Broadway Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable duct - total 1 no - Trackside wall - midway | | 1 | R728755 | N | Y |
| 15649 | ACTIVE | N | N169-00-3/261/ FLR-01 | Floor - 1 - Platform 1 - Station Building - Tooting Broadway Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 1 Invert - Various Cables No access 2020 re-inspection as confined space team required | | | | | YES |
| 12124 | ACTIVE | N | N169-00-3/262 | Platform 2 - Southbound Local - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70483 | ACTIVE | N | N169-00-3/262 | Platform 2 - Southbound Local - Station Building - Tooting Broadway Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 4 no - To platform wall - midway | | 4 | R728755 | N | Y |
| 70477 | ACTIVE | N | N169-00-3/262 | Platform 2 - Southbound Local - Station Building - Tooting Broadway Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728755 | | |
| 70480 | ACTIVE | N | N169-00-3/262 | Platform 2 - Southbound Local - Station Building - Tooting Broadway Stn | Cable Wrap | Asbestos | Known | | | | Platform Invert -Wrapping cloth - total 1 no - To trackside wall - arrival end | | 1 | R728755 | | |
| 70481 | ACTIVE | N | N169-00-3/262 | Platform 2 - Southbound Local - Station Building - Tooting Broadway Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - total 6 no - To J Hangers | | 6 | R728755 | | |
| 70484 | ACTIVE | N | N169-00-3/262 | Platform 2 - Southbound Local - Station Building - Tooting Broadway Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 4 no - To trackside wall - departure end | | 4 | R728755 | N | Y |
| 70485 | ACTIVE | N | N169-00-3/262 | Platform 2 - Southbound Local - Station Building - Tooting Broadway Stn | Cable Wrap | Asbestos | Known | | | | Platform Invert - Wrapping cloth - total 1 no - To trackside wall - departure end | | 1 | R728755 | | |
| 70482 | ACTIVE | N | N169-00-3/262 | Platform 2 - Southbound Local - Station Building - Tooting Broadway Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 2 no - To platform wall - midway | | 2 | R728755 | N | Y |
| 18424 | ACTIVE | N | N169-00-3/262 | Platform 2 - Southbound Local - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 70478 | ACTIVE | N | N169-00-3/262 | Platform 2 - Southbound Local - Station Building - Tooting Broadway Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728755 | | |
| 70479 | ACTIVE | N | N169-00-3/262 | Platform 2 - Southbound Local - Station Building - Tooting Broadway Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable duct - total 1 no - To trackside wall - arrival end | | 1 | R728755 | N | Y |



Hazardous Material Asset Register - Summary



N169-00 - Station Building - Tooting Broadway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 12125 | ACTIVE | N | N169-00-3/661 | Service Riser - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15650 | ACTIVE | N | N169-00-3/661 | Service Riser - Station Building - Tooting Broadway Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 1x15mm going to invert 3/661 | | | | | |
| 12126 | ACTIVE | N | N169-00-3/662 | Store - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15651 | ACTIVE | N | N169-00-3/662 | Store - Station Building - Tooting Broadway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board around door | | | | | |
| 12127 | ACTIVE | N | N169-00-3/663 | Switch Room - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18425 | ACTIVE | N | N169-00-3/663 | Switch Room - Station Building - Tooting Broadway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board around door | | | | | |
| 12128 | ACTIVE | N | N169-00-3/664 | Switch Room - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15652 | ACTIVE | N | N169-00-3/664 | Switch Room - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12129 | ACTIVE | N | N169-00-3/665 | Switch Room - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15653 | ACTIVE | N | N169-00-3/665 | Switch Room - Station Building - Tooting Broadway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux & Plasterboard boarding | | | | | |
| 12130 | ACTIVE | N | N169-00-3/666 | Switch Room - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15654 | ACTIVE | N | N169-00-3/666 | Switch Room - Station Building - Tooting Broadway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux & Plasterboard boarding | | | | | |
| 12131 | ACTIVE | N | N169-00-3/667 | Switch Cupboard - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18426 | ACTIVE | N | N169-00-3/667 | Switch Cupboard - Station Building - Tooting Broadway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux & Plasterboard boarding | | | | | |
| 12132 | ACTIVE | N | N169-00-3/668 | Switch Cupboard - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18662 | ACTIVE | N | N169-00-3/668 | Switch Cupboard - Station Building - Tooting Broadway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux & Plasterboard boarding | | | | | |
| 12133 | ACTIVE | N | N169-00-3/669 | Switch Cupboard - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N169-00 - Station Building - Tooting Broadway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18720 | ACTIVE | N | N169-00-3/669 | Switch Cupboard - Station Building - Tooting Broadway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux & Plasterboard boarding | | | | | |
| 12134 | ACTIVE | N | N169-00-3/706 | Lobby - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15655 | ACTIVE | N | N169-00-3/706 | Lobby - Station Building - Tooting Broadway Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding under Sink | | | | | |
| 12135 | ACTIVE | N | N169-00-3/707 | IMR - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15656 | ACTIVE | N | N169-00-3/707/WAL-002 | Wall: Internal - 2 - IMR - Station Building - Tooting Broadway Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline Boarding above door | | | | | |
| 12136 | ACTIVE | N | N169-00-3/708 | IMR - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Surveyed – Asbestos Known | | | | | | | | | |
| 15660 | ACTIVE | N | N169-00-3/708 | IMR - Station Building - Tooting Broadway Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 15mm Cables from 3/708 to 3/710-various 2x white asbestos cables 2m approx from wall 1-3 Bay number 3-2 (1x cable running onto wall 2) (1x cable running in j hanger) | | 2 | | | |
| 15662 | ACTIVE | N | N169-00-3/708 | IMR - Station Building - Tooting Broadway Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Paxoline Boarding x 2 to wall 1 to equipment - new board | | | | | |
| 53657 | ACTIVE | N | N169-00-3/708 | IMR - Station Building - Tooting Broadway Stn | Other Boarding | Asbestos | Presumed | | | | Rack to middle of room 5 x composite brown board to first rack | | | | | |
| 53658 | ACTIVE | N | N169-00-3/708 | IMR - Station Building - Tooting Broadway Stn | Bakerlite | Asbestos | Presumed | | | | presumed Bakerlite telephone to middle of room | | | | | |
| 53659 | ACTIVE | N | N169-00-3/708 | IMR - Station Building - Tooting Broadway Stn | Other Boarding | Asbestos | Presumed | | | | Middle of room 3x composite board to Rack next to point control middle of room 1 x board to rack 4 in middle of room | | | | | |
| 18245 | ACTIVE | N | N169-00-3/708/CLG-01 | Ceiling: Solid - 1 - IMR - Station Building - Tooting Broadway Stn | Vinyl tiles | Asbestos | Known | | | | Marley Tiles - Chrysotile Some tiles loose to wall & on floor | | | | | |
| 15661 | ACTIVE | N | N169-00-3/708/WAL-001 | Wall: Internal - 1 - IMR - Station Building - Tooting Broadway Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box(es) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 53656 | ACTIVE | N | N169-00-3/708/WAL-001 | Wall: Internal - 1 - IMR - Station Building - Tooting Broadway Stn | Other Boarding | Asbestos | Presumed | | | | 9 x brown board to bay 12 wall 1 | | | | | |
| 15657 | ACTIVE | N | N169-00-3/708/WAL-001 | Wall: Internal - 1 - IMR - Station Building - Tooting Broadway Stn | Vinyl tiles | Asbestos | Known | | | | Marley Tiles - Chrysotile Some tiles loose to wall n floor | | | | | |



Hazardous Material Asset Register - Summary



N169-00 - Station Building - Tooting Broadway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|------------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18721 | INACTIVE | N | N169-00-3/708/WAL-001 | Wall: Internal - 1 - IMR - Station Building - Tooting Broadway Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | PCB - Good Condition - Cylindrical, Blue - mounted on Paxoline board Re Inspected 14/04/2015 | | 4 | | | |
| 18427 | ACTIVE | N | N169-00-3/708/WAL-002 | Wall: Internal - 2 - IMR - Station Building - Tooting Broadway Stn | Vinyl tiles | Asbestos | Known | | | | Tiles - Chrysotile Tiles loose to wall and floor | | | | | |
| 15658 | ACTIVE | N | N169-00-3/708/WAL-003 | Wall: Internal - 3 - IMR - Station Building - Tooting Broadway Stn | Vinyl tiles | Asbestos | Known | | | | Tiles - Chrysotile Tiles loose to wall and floor | | | | | |
| 15663 | ACTIVE | N | N169-00-3/708/WAL-003 | Wall: Internal - 3 - IMR - Station Building - Tooting Broadway Stn | Other Boarding | Asbestos | Presumed | | | | 2 x paxoline board 1x large Board 1x small board to rack wall 3 | | | | | |
| 15659 | ACTIVE | N | N169-00-3/708/WAL-004 | Wall: Internal - 4 - IMR - Station Building - Tooting Broadway Stn | Vinyl tiles | Asbestos | Known | | | | Tiles - Chrysotile Some tiles loose to wall and floor | | | | | |
| 18428 | INACTIVE | N | N169-00-3/708/WAL-004 | Wall: Internal - 4 - IMR - Station Building - Tooting Broadway Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | PCB - Good Condition - Cylindrical, Blue - wall mounted on Paxoline board still present on 2022 reinspection | | 2 | | | |
| 12137 | ACTIVE | N | N169-00-3/709 | IMR - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42323 | INACTIVE | N | N169-00-3/709 | IMR - Station Building - Tooting Broadway Stn | PCBs | Polychlorinated biphenyl | Presumed | | | | 2 x small cylindrical PCB's wall mounted on paxoline board Fair Condition | | 2 | | N | N |
| 15664 | ACTIVE | N | N169-00-3/709/WAL-001 | Wall: Internal - 1 - IMR - Station Building - Tooting Broadway Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline Boarding throughout Missing 1x presumed composite panel photo DSC05758 | | | | | |
| 18429 | ACTIVE | N | N169-00-3/709/WAL-001 | Wall: Internal - 1 - IMR - Station Building - Tooting Broadway Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Grey Switch Box 100amp - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 15666 | ACTIVE | N | N169-00-3/709/WAL-001 | Wall: Internal - 1 - IMR - Station Building - Tooting Broadway Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 15mm Cables from 3/708 to 3/710 | | 2 | | | |
| 15665 | ACTIVE | N | N169-00-3/709/WAL-002 | Wall: Internal - 2 - IMR - Station Building - Tooting Broadway Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline Boarding throughout | | | | | |
| 15668 | ACTIVE | N | N169-00-3/709/WAL-002 | Wall: Internal - 2 - IMR - Station Building - Tooting Broadway Stn | Other Electrical Boxes | Asbestos | Presumed | | | | AC Fuse Box 100amps No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 15669 | INACTIVE | N | N169-00-3/709/WAL-002 | Wall: Internal - 2 - IMR - Station Building - Tooting Broadway Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | 6 x blue cylindrical PCB's Re inspected 14/04/2015 Fair Condition | | 6 | | | |
| 15667 | ACTIVE | N | N169-00-3/709/WAL-004 | Wall: Internal - 4 - IMR - Station Building - Tooting Broadway Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box(es) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 3 | | | |



Hazardous Material Asset Register - Summary



N169-00 - Station Building - Tooting Broadway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|------------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 12138 | ACTIVE | N | N169-00-3/710 | IMR - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44316 | ACTIVE | N | N169-00-3/710 | IMR - Station Building - Tooting Broadway Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline board boxes | | | | | |
| 15670 | ACTIVE | N | N169-00-3/710 | IMR - Station Building - Tooting Broadway Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Electrical Equipment - Insulation within throughout Room No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | | | | |
| 18430 | ACTIVE | N | N169-00-3/710 | IMR - Station Building - Tooting Broadway Stn | Caulking | Asbestos | Presumed | | | | Caulking Solid | | | | | |
| 15671 | ACTIVE | N | N169-00-3/710/WAL-001 | Wall: Internal - 1 - IMR - Station Building - Tooting Broadway Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Transformer Box(es) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 18431 | ACTIVE | N | N169-00-3/710/WAL-001 | Wall: Internal - 1 - IMR - Station Building - Tooting Broadway Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | Westinghouse Box No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 2 | | | |
| 15673 | ACTIVE | N | N169-00-3/710/WAL-002 | Wall: Internal - 2 - IMR - Station Building - Tooting Broadway Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 5mm Cables | | 2 | | | |
| 15674 | INACTIVE | N | N169-00-3/710/WAL-003 | Wall: Internal - 3 - IMR - Station Building - Tooting Broadway Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | 3 x PCB Cylindrical, blue,mounted on metal panel Re inspected 14/04/2015 Fair Condition | | 3 | | | |
| 15672 | ACTIVE | N | N169-00-3/710/WAL-004 | Wall: Internal - 4 - IMR - Station Building - Tooting Broadway Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 15mm Cables from 3/708 to 3/710 | | 2 | | | |
| 12139 | ACTIVE | N | N169-00-3/711 | Relay Room - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44315 | ACTIVE | N | N169-00-3/711 | Relay Room - Station Building - Tooting Broadway Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline boarding wall 2 behind glass box | | | | | |
| 15680 | ACTIVE | N | N169-00-3/711/CLG-01 | Ceiling: Solid - 1 - Relay Room - Station Building - Tooting Broadway Stn | Vinyl tiles | Asbestos | Known | | | | Tiles - Chrysotile White Tiles on Ceiling remain Some tiles loose | | | | | |
| 19953 | ACTIVE | N | N169-00-3/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Tooting Broadway Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | W1 Westinghouse Box - Insulation within. Asbestos Cable going into box No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |



Hazardous Material Asset Register - Summary



N169-00 - Station Building - Tooting Broadway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|------------------------|--------------------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18433 | INACTIVE | N | N169-00-3/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Tooting Broadway Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Small Transformer Box - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 15682 | ACTIVE | N | N169-00-3/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Tooting Broadway Stn | Boarding: Cement | Asbestos | Strongly Presumed | | | | Cement panel to racking on wall 1 x2 top and bottom rack | | 3 | | | |
| 18246 | ACTIVE | N | N169-00-3/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Tooting Broadway Stn | Vinyl tiles | Asbestos | Known | | | | Tiles - Chrysotile - Green behind Equipment most removed some remain to wall 1 | | | | | |
| 53653 | ACTIVE | N | N169-00-3/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Tooting Broadway Stn | Other Boarding | Asbestos | Presumed | | | | 6 x black composite board to top shelf of rack on wall 1 | | | | | |
| 53654 | ACTIVE | N | N169-00-3/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Tooting Broadway Stn | Other Boarding | Asbestos | Presumed | | | | 1 x brown board to top shelf of rack to wall 1 | | | | | |
| 15681 | ACTIVE | N | N169-00-3/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Tooting Broadway Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Asbestos cable Wall 1 coming out of duct and running to trackside wall 2 | | 1 | | | |
| 15683 | INACTIVE | N | N169-00-3/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Tooting Broadway Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | PCB's - Fair Condition Serial Nos. 197476; 197490; 197461; 197492; 197472; 197477, 197487; 197488. Re inspected 14/04/2015 Fair Condition | | 7 | | | |
| 53655 | ACTIVE | N | N169-00-3/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Tooting Broadway Stn | Cable: Sheath | Asbestos | Presumed | | | | thin white cable from 600v electrical box wall 2 | | | | | |
| 18432 | INACTIVE | N | N169-00-3/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Tooting Broadway Stn | Vinyl tiles | Asbestos | Known | | | | Tiles - Chrysotile - Green behind Equipment remain Duplicate entry | | | | | |
| 15677 | INACTIVE | N | N169-00-3/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Tooting Broadway Stn | Vinyl tiles | Asbestos | Known | | | | Tiles - Chrysotile - Green behind Equipment remain Duplicate entry | | | | | |
| 15679 | ACTIVE | N | N169-00-3/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Tooting Broadway Stn | Vinyl tiles | Asbestos | Known | | | | Marley Tiles - Chrysotile - Green - most removed some remain behind Equipment to wall 2-3 | | | | | |
| 15678 | INACTIVE | N | N169-00-3/711/WAL-004 | Wall: Internal - 4 - Relay Room - Station Building - Tooting Broadway Stn | Vinyl tiles | Asbestos | Known | | | | Tiles - Chrysotile - Green behind Equipment remain Duplicate entry | | | | | |
| 12140 | ACTIVE | N | N169-00-3/956 | Disused Room - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15675 | ACTIVE | N | N169-00-3/956 | Disused Room - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N169-00 - Station Building - Tooting Broadway Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---------------------|-------------|------------|-------------|---------------------|-------------------|
| 12141 | ACTIVE | N | N169-00-A/481 | Equipment Room - Station Building - Tooting Broadway Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15676 | ACTIVE | N | N169-00-A/481 | Equipment Room - Station Building - Tooting Broadway Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |

N173-00 - Station Building - Colliers Wood Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 12142 | ACTIVE | N | N173-00-1/001 | Booking Hall - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15453 | ACTIVE | N | N173-00-1/001 | Booking Hall - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12143 | ACTIVE | N | N173-00-1/011 | Ticket Office - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15454 | ACTIVE | N | N173-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Colliers Wood Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18186 | ACTIVE | N | N173-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Colliers Wood Stn | Void | Asbestos | No Access: Presumed | | | | AboveSupalux Tiles | | | | | |
| 42243 | ACTIVE | N | N173-00-1/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Colliers Wood Stn | Debris: Other | Asbestos | Sampled – Not Detected | | | | Dust - 1m² under false floor, Floor tiles, under false floor, Dust & debris under false | 1 | | | N | Y |
| 18639 | ACTIVE | N | N173-00-1/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Colliers Wood Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Tiles | | | | | YES |
| 42242 | ACTIVE | N | N173-00-1/011/WAL-002 | Wall: Internal - 2 - Ticket Office - Station Building - Colliers Wood Stn | Other Boarding | Asbestos | Sampled – Not Detected | | | | Insulation panel, 1m to loose panel in timber cupboard to bottom of wall 2. Insulation panel 1m, to timber box no 3 to wall 2 | 1 | | | N | N |
| 12144 | ACTIVE | N | N173-00-1/021 | POM - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15457 | ACTIVE | N | N173-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Colliers Wood Stn | Void | Asbestos | No Access: Presumed | | | | AboveSupalux Tiles | | | | | |
| 15456 | ACTIVE | N | N173-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Colliers Wood Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 15455 | ACTIVE | N | N173-00-1/021/FLR-01 | Floor - 1 - POM - Station Building - Colliers Wood Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Computer Tiles | | | | | YES |



Hazardous Material Asset Register - Summary



N173-00 - Station Building - Colliers Wood Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 12145 | ACTIVE | N | N173-00-1/031 | Mess Room - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18187 | ACTIVE | N | N173-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Colliers Wood Stn | Void | Asbestos | No Access: Presumed | | | | AboveSupalux Tiles | | | | | |
| 15458 | ACTIVE | N | N173-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Colliers Wood Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 12146 | ACTIVE | N | N173-00-1/036 | Toilet: Unisex - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15460 | ACTIVE | N | N173-00-1/036/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Colliers Wood Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Tiles | | | | | |
| 15459 | ACTIVE | N | N173-00-1/036/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Colliers Wood Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 12147 | ACTIVE | N | N173-00-1/071 | Circulation Area - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15461 | ACTIVE | N | N173-00-1/071 | Circulation Area - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12148 | ACTIVE | N | N173-00-1/081 | Lobby - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15462 | ACTIVE | N | N173-00-1/081/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Colliers Wood Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18640 | ACTIVE | N | N173-00-1/081/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Colliers Wood Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Tiles | | | | | |
| 12149 | ACTIVE | N | N173-00-1/151 | UMC - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44979 | ACTIVE | N | N173-00-1/151 | UMC - Station Building - Colliers Wood Stn | Caulking | Asbestos | Presumed | | | | Tunnel ring caulking to tunnel ring joints | | | | N | N |
| 18188 | ACTIVE | N | N173-00-1/151 | UMC - Station Building - Colliers Wood Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Lid to Storage Bin | | | | | |
| 15463 | ACTIVE | N | N173-00-1/151 | UMC - Station Building - Colliers Wood Stn | Lead/Leading | Lead Paint/Lead | Known | | | | White Gloss - Column Thickness: 0.24mm. Analysis 1.1% | | | | | |
| 15464 | ACTIVE | N | N173-00-1/151 | UMC - Station Building - Colliers Wood Stn | Lead/Leading | Lead Paint/Lead | Known | | | | White Gloss - Column Thickness: 0.26mm. Analysis 3% | | | | | |



Hazardous Material Asset Register - Summary



N173-00 - Station Building - Colliers Wood Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|------------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 15465 | ACTIVE | N | N173-00-1/151 | UMC - Station Building - Colliers Wood Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Blue Gloss - Column Thickness: 0.29mm. Analysis 8.9% | | | | | |
| 44980 | ACTIVE | N | N173-00-1/151/WAL-004 | Wall: Internal - 4 - UMC - Station Building - Colliers Wood Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 3x combination fuse switches | | 3 | | N | N |
| 12150 | ACTIVE | N | N173-00-1/236 | Lobby - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18189 | ACTIVE | N | N173-00-1/236 | Lobby - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12151 | ACTIVE | N | N173-00-1/237 | Lobby - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15466 | ACTIVE | N | N173-00-1/237 | Lobby - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12152 | ACTIVE | N | N173-00-1/239 | Lobby - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15467 | ACTIVE | N | N173-00-1/239 | Lobby - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12153 | ACTIVE | N | N173-00-1/281 | Lobby - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18190 | ACTIVE | N | N173-00-1/281/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Colliers Wood Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Tiles | | | | | |
| 15468 | ACTIVE | N | N173-00-1/281/CLG-01 | Ceiling: Suspended - 1 - Lobby - Station Building - Colliers Wood Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 12154 | ACTIVE | N | N173-00-1/316 | Locker Room - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15469 | ACTIVE | N | N173-00-1/316 | Locker Room - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12155 | ACTIVE | N | N173-00-1/396 | SVC - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18653 | ACTIVE | N | N173-00-1/396 | SVC - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12156 | ACTIVE | N | N173-00-1/406 | Store - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N173-00 - Station Building - Colliers Wood Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 15470 | ACTIVE | N | N173-00-1/406 | Store - Station Building - Colliers Wood Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 12157 | ACTIVE | N | N173-00-1/411 | Store - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19299 | ACTIVE | N | N173-00-1/411/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Colliers Wood Stn | Void | Asbestos | Surveyed – Not Detected | | | | Corrugated Material - Non Asbestos above Plasterboard Ceiling | | | | YES | |
| 12158 | ACTIVE | N | N173-00-1/417 | Toilet: Unisex - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18641 | ACTIVE | N | N173-00-1/417/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Colliers Wood Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 18336 | ACTIVE | N | N173-00-1/417/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Colliers Wood Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Tiles | | | | | |
| 12159 | ACTIVE | N | N173-00-1/551 | Yard - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15565 | ACTIVE | N | N173-00-1/551 | Yard - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12160 | ACTIVE | N | N173-00-1/666 | Switch Cupboard - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15566 | ACTIVE | N | N173-00-1/666 | Switch Cupboard - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12161 | ACTIVE | N | N173-00-1/667 | Switch Room - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15567 | ACTIVE | N | N173-00-1/667 | Switch Room - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12162 | ACTIVE | N | N173-00-1/714 | Station Control Room - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12163 | ACTIVE | N | N173-00-1/731 | Store - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15568 | ACTIVE | N | N173-00-1/731 | Store - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12164 | ACTIVE | N | N173-00-1/732 | Equipment Room - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N173-00 - Station Building - Colliers Wood Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 15569 | ACTIVE | N | N173-00-1/732 | Equipment Room - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 19947 | ACTIVE | N | N173-00-1/751 | Station Control Room - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12165 | ACTIVE | N | N173-00-1/761 | Void - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18337 | ACTIVE | N | N173-00-1/761 | Void - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12166 | ACTIVE | N | N173-00-2/081 | Circulation Area - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15570 | ACTIVE | N | N173-00-2/081 | Circulation Area - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12167 | ACTIVE | N | N173-00-2/161 | LMC - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18338 | ACTIVE | N | N173-00-2/161 | LMC - Station Building - Colliers Wood Stn | Cable: Sheath | Asbestos | Surveyed – Not Detected | | | | Braided Cables 50cmI x 0.5cm diameter from redundant equipment | | 2 | | | |
| 15571 | ACTIVE | N | N173-00-2/161 | LMC - Station Building - Colliers Wood Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables - Chrysotile | | 3 | | | |
| 12168 | ACTIVE | N | N173-00-2/201 | Passage - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15572 | ACTIVE | N | N173-00-2/201 | Passage - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12169 | ACTIVE | N | N173-00-2/202 | Passage - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15573 | ACTIVE | N | N173-00-2/202 | Passage - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12170 | ACTIVE | N | N173-00-2/203 | Passage - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18712 | ACTIVE | N | N173-00-2/203 | Passage - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12171 | ACTIVE | N | N173-00-2/204 | Passage - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15574 | ACTIVE | N | N173-00-2/204 | Passage - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N173-00 - Station Building - Colliers Wood Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------------|--------|-------------|---------------------|--|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 12172 | ACTIVE | N | N173-00-2/205 | Passage - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15575 | ACTIVE | N | N173-00-2/205 | Passage - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12173 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70383 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Cable Wrap | Asbestos | Known | | | | Invert - Cable wrapping - total 1no x 1m - To HV cable at departure end | 1 | 1 | R710426 | | |
| 70385 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Cable Sheath | Asbestos | Known | | | | Invert - Braided cables - total 1 no - To J Hanger at departure end | | 1 | R710426 | | |
| 70423 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728754 | | |
| 70425 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Cable Wrap | Asbestos | Known | | | | Platform Invert - Wrapping cloth - total 1 no - To cable trackside wall arrivals end | | 1 | R728754 | | |
| 70426 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 8 no - To trackside wall arrivals end | | 8 | R728754 | N | Y |
| 70427 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - green / white - total 8 no - To J Hangers | | 8 | R728754 | | |
| 02/06/2023 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Cable Wrap | Asbestos | Known | | | | Platform Invert - Wrapping cloth - total 1 no - To trackside wall | | 1 | R728754 | | |
| 70434 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Cable Wrap | Asbestos | Known | | | | Platform Invert - Wrapping cloth - total 1 no - To cable trackside wall departures end | | 1 | R728754 | | |
| 18339 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables from Invert out of Vent Duct | | 4 | | | |
| 15576 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Other Boarding | Asbestos | Strongly Presumed | | | | Material behind sign outside 2/711 | | | | | |
| 70371 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Invert - Bitumen cable ducts - total 8 no - To platform wall arrival end | | 8 | R710426 | | Y |
| 70373 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Cable Wrap | Asbestos | Known | | | | Invert - Cable wrapping - total 1 no x 16m - To HV cable | 16 | 1 | R710426 | | |



Hazardous Material Asset Register - Summary



N173-00 - Station Building - Colliers Wood Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|----------------------|---------------|------------------------|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 70374 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Cable Sheath | Asbestos | Known | | | | Invert - Braided cables - total 4 no - To ceiling at arrival end | | 4 | R710426 | | |
| 70375 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Invert - Bitumen cable ducts - total 1 no - Mid way trackside wall | | 1 | R710426 | | Y |
| 70379 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Cable Sheath | Asbestos | Known | | | | Invert - Braided cables - total 3 no - To J Hangers over track crossing from platform wall to track wall (OTX) | | 3 | R710426 | | |
| 70387 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Invert - Metal tunnel rings - To walls | | | R710426 | | |
| 70388 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Invert - Bitumen cable ducts - total 8 no - To platform wall midway | | 8 | R710426 | | Y |
| 70424 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728754 | | |
| 70428 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable duct - total 1 no - To trackside wall midway | | 1 | R728754 | N | Y |
| 70429 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Cable Wrap | Asbestos | Known | | | | Platform Invert - Wrapping cloth - total 1 no - To trackside wall midway | | 1 | R728754 | | |
| 70430 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 2 x 4 no - To platform wall | | 8 | R728754 | N | Y |
| 70431 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 2 x 4 no - To platform wall | | 8 | R728754 | N | Y |
| 70432 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable duct - total 1 no - To trackside wall | | 1 | R728754 | N | Y |
| 70435 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 2 no - Trackside wall departures end | | 2 | R728754 | N | Y |
| 70372 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Cable Sheath | Asbestos | Known | | | | Invert - Braided cables - total 1 no - To J Hangers to trackside wall | | 1 | R710426 | | |
| 70376 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Cable Wrap | Asbestos | Known | | | | Invert - Cable wrapping - total 1 no x 16m - To HV cable, midway | 16 | 1 | R710426 | | |
| 70377 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Invert - Bitumen cable ducts - total 3 no | | 3 | R710426 | | Y |



Hazardous Material Asset Register - Summary



N173-00 - Station Building - Colliers Wood Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 70380 | ACTIVE | N | N173-00-2/261 | Platform 1 - Northbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Invert - Bitumen cable ducts - total 2 no - To trackside wall at departure end | | 2 | R710426 | | Y |
| 15577 | ACTIVE | N | N173-00-2/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - Colliers Wood Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform Invert - 1m of cable wrap slight damage To cable at arrival side & 1m To cable at departure end - Chrysotile Asbestos | | 3 | | | YES |
| 12174 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70457 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Cable Wrap | Asbestos | Known | | | | Platform Invert - Wrapping cloth - total 1 no - To trackside wall departure end | | 1 | R728754 | | |
| 70453 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement panel - total 1 no - To trackside wall departure end | | 1 | R728754 | N | Y |
| 70448 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement panel - total 1 no - To trackside wall - midway | | 1 | R728754 | N | Y |
| 70444 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement panel - total 1 no - To trackside wall, hole (recess) - midway | | 1 | R728754 | N | Y |
| 70443 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 7 no - To platform wall - midway | | 7 | R728754 | N | Y |
| 70442 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | Platform Invert - Bitumen cable duct - total 1 no - To trackside wall - midway | | 1 | R728754 | N | Y |
| 70440 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement panel - total <1m2 - To trackside wall - hole (recess) | 1 | | R728754 | N | Y |
| 70437 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728754 | | |
| 15578 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board behind termination point box | | | | | |
| 70399 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Cable Sheath | Asbestos | Known | | | | Invert - Braided cables - total 4 no - Trackside wall | | 4 | R710426 | | |
| 70459 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | Platform Invert - Bitumen cable ducts - total 8 no - To trackside wall departure end | | 8 | R728754 | N | Y |
| 70455 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement panel - total 1 no - To trackside wall departure end | | 1 | R728754 | N | Y |



Hazardous Material Asset Register - Summary



N173-00 - Station Building - Colliers Wood Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|----------------------|---------------|------------------------|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 70451 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Bitumen | Asbestos | Known | | | | Platform Invert - Bitumen cable duct - total 1 no - To trackside wall - midway | | 1 | R728754 | N | Y |
| 70449 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Cement | Asbestos | Known | | | | Platform Invert - Cement panel- total 1 no - To trackside wall - midway | | 1 | R728754 | N | Y |
| 70447 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert -Small Westinghouse box - total 1 no - To platform wall | | 1 | R728754 | | |
| 70446 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable duct - total 1 no - To trackside wall - midway | | 1 | R728754 | N | Y |
| 70445 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Cable Wrap | Asbestos | Known | | | | Platform Invert - Wrapping cloth - total 1 no - To trackside wall - midway | | 1 | R728754 | | |
| 70441 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 7 no - To platform wall - midway | | 7 | R728754 | N | Y |
| 70439 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - total 8 no - To J Hangers throughout | | 8 | R728754 | | |
| 70438 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Cable Wrap | Asbestos | Known | | | | Platform Invert - Wrapping cloth - total 2 no - To cable trackside arrivals end | | 2 | R728754 | | |
| 70436 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728754 | | |
| 70400 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Invert - Metal tunnel rings - To walls | | | R710426 | | |
| 70398 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Invert - Bitumen cable ducts - total 6 no - Trackside wall, departure end | | 6 | R710426 | | Y |
| 70396 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Cement | Asbestos | Known | | | | Invert - Cement panel - total 1 no x <1m2 - Trackside wall | 1 | 1 | R710426 | | Y |
| 70395 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Invert - Bitumen cable ducts - total 2 no - Platform wall, midway | | 2 | R710426 | | Y |
| 70394 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Cable Sheath | Asbestos | Known | | | | Invert - Braided cables - total 4 no - Platform wall over track crossing to track wall, midway | | 4 | R710426 | | |
| 70393 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Invert - Bitumen cable ducts - total 6 no - Platform wall, midway | | 6 | R710426 | | Y |



Hazardous Material Asset Register - Summary



N173-00 - Station Building - Colliers Wood Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|---------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 70392 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Cement | Asbestos | Known | | | | Invert - Cement panel - total 1 no <1m - Trackside wall in alcove, midway | 1 | 1 | R710426 | | Y |
| 70389 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Cable Wrap | Asbestos | Known | | | | Invert - Cable wrapping - total 2no x 1m - To trackside wall at arrival end | 1 | 2 | R710426 | | |
| 70390 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Cable Sheath | Asbestos | Known | | | | Invert - Braided cables - total 3 no - To trackside wall over track crossing | | 3 | R710426 | | |
| 70391 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Cement | Asbestos | Known | | | | Invert - Cement panel - total 1 no x <1m2 - Trackside wall in alcove | 1 | 1 | R710426 | | Y |
| 70397 | ACTIVE | N | N173-00-2/262 | Platform 2 - Southbound Local - Station Building - Colliers Wood Stn | Cable Ducts: Cement | Asbestos | Known | | | | Invert - Cement panel - total 1 no x <1m - Trackside wall | 1 | 1 | R710426 | | Y |
| 15579 | ACTIVE | N | N173-00-2/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Colliers Wood Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 2 Invert - Braided Cable | | | | | YES |
| 18713 | ACTIVE | N | N173-00-2/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - Colliers Wood Stn | Cable Duct: Other | Asbestos | Strongly Presumed | | | | Platform 2 Invert - Braided Cable Sleeves | | | | | YES |
| 12175 | ACTIVE | N | N173-00-2/661 | Lobby - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18340 | ACTIVE | N | N173-00-2/661 | Lobby - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12176 | ACTIVE | N | N173-00-2/662 | Toilet - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12177 | ACTIVE | N | N173-00-2/663 | Disused Room - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15580 | ACTIVE | N | N173-00-2/663 | Disused Room - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12178 | ACTIVE | N | N173-00-2/664 | Switch Room - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15581 | ACTIVE | N | N173-00-2/664 | Switch Room - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12179 | ACTIVE | N | N173-00-2/665 | Switch Cupboard - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18659 | ACTIVE | N | N173-00-2/665 | Switch Cupboard - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N173-00 - Station Building - Colliers Wood Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 12180 | ACTIVE | N | N173-00-2/666 | Switch Cupboard - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15582 | ACTIVE | N | N173-00-2/666 | Switch Cupboard - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12181 | ACTIVE | N | N173-00-2/667 | Switch Cupboard - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18341 | ACTIVE | N | N173-00-2/667 | Switch Cupboard - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12182 | ACTIVE | N | N173-00-2/668 | Switch Cupboard - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15583 | ACTIVE | N | N173-00-2/668 | Switch Cupboard - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12183 | ACTIVE | N | N173-00-2/711 | Relay Room - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15585 | ACTIVE | N | N173-00-2/711 | Relay Room - Station Building - Colliers Wood Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 3x cable braided from fuse bay (2 exiting trackside by wall 5, 1 entering invert) 1m each length 1x Green cable from wall 5 to platform invert 2m length | | 4 | | | |
| 18342 | INACTIVE | N | N173-00-2/711/CLG-01 | Ceiling: Solid - 1 - Relay Room - Station Building - Colliers Wood Stn | Vinyl tiles | Asbestos | Strongly Presumed | | | | Grey & Green Vinyl Tiles Duplicate with 15584 | | | | | |
| 15584 | ACTIVE | N | N173-00-2/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Colliers Wood Stn | Vinyl tiles | Asbestos | Strongly Presumed | | | | Grey & Green Vinyl Tiles on all walls and ceiling | | | | | |
| 15586 | ACTIVE | N | N173-00-2/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Colliers Wood Stn | Boarding: Cement | Asbestos | Strongly Presumed | | | | cement panel to bottom shelf of rack | | | | | |
| 15587 | INACTIVE | N | N173-00-2/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Colliers Wood Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | 6 x PCB's - Fair Condition Serial Nos. 186453; 186425; 186458; 186434; 186513; 197465 Inspected 14/04/2015 | | 6 | | | |
| 64657 | ACTIVE | N | N173-00-2/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Colliers Wood Stn | Other Boarding | Asbestos | Presumed | | | | x6 black composite board to equipment. Top shelf of rack by wall 3 | | | | | |
| 64656 | ACTIVE | N | N173-00-2/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Colliers Wood Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | supalux panel to wall 3 - NAD | | | | | |
| 64658 | ACTIVE | N | N173-00-2/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Colliers Wood Stn | Boarding: Cement | Asbestos | Strongly Presumed | | | | cement panel to second shelf of rack underneath electrical equipment | | | | | |



Hazardous Material Asset Register - Summary



N173-00 - Station Building - Colliers Wood Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|------------------------|--------------------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 19480 | ACTIVE | N | N173-00-2/711/WAL-004 | Wall: Internal - 4 - Relay Room - Station Building - Colliers Wood Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | Insulation within 1x Westinghouse Box | | | | | |
| 64659 | ACTIVE | N | N173-00-2/711/WAL-005 | Wall: Internal - 5 - Relay Room - Station Building - Colliers Wood Stn | Cable: Sheath | Asbestos | Presumed | | | | 1x earthing cable from electrical box on wall 5 connecting to cable run 3m length | | | | | |
| 64660 | ACTIVE | N | N173-00-2/711/WAL-005 | Wall: Internal - 5 - Relay Room - Station Building - Colliers Wood Stn | Other Boarding | Asbestos | Presumed | | | | Brown composite board on dot matrix sign bay on wall 5 | | | | | |
| 12184 | ACTIVE | N | N173-00-2/712 | Relay Room - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15588 | ACTIVE | N | N173-00-2/712 | Relay Room - Station Building - Colliers Wood Stn | Vinyl tiles | Asbestos | Strongly Presumed | | | | Grey & Green Marley Tiles to walls and ceiling | | | | | |
| 67597 | ACTIVE | N | N173-00-2/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Colliers Wood Stn | Cable: Sheath | Asbestos | Known | | | | 4x Asbestos braided cables running from fuse bay wall 1 to invert (3x 5metres) and trackside via wall 3 duct (1x 7metres) | 22 | 4 | | | |
| 67596 | ACTIVE | N | N173-00-2/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Colliers Wood Stn | Boarding: Cement | Asbestos | Known | | | | 3x Asbestos cement panels - top, 3rd and bottom shelf to equipment rack at wall 1 | | 3 | | | |
| 18714 | INACTIVE | N | N173-00-2/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Colliers Wood Stn | Vinyl tiles | Asbestos | Strongly Presumed | | | | Grey & Brown Vinyl Tiles | | | | | |
| 15592 | ACTIVE | N | N173-00-2/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Colliers Wood Stn | Other Boarding | Asbestos | Presumed | | | | 6x Brown panels to electrical equipment on shelves within rack at wall 1 | | 6 | | | |
| 18344 | INACTIVE | N | N173-00-2/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Colliers Wood Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Transformer Box(es) | | 1 | | | |
| 15591 | ACTIVE | N | N173-00-2/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Colliers Wood Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | Insulation within Westinghouse Box to wall 1 | | 1 | | | |
| 15600 | INACTIVE | N | N173-00-2/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - Colliers Wood Stn | PCBs | Polychlorinated biphenyl | Removed | | | | 7 x PCB's - Fair Condition Serial Nos. 186434, 186435; 186610; 186452; 186484; 186432; 186503, 186494 Inspected 14/04/2015 | | 7 | | | |
| 67598 | ACTIVE | N | N173-00-2/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Colliers Wood Stn | Other Boarding | Asbestos | Presumed | | | | Brown panel casing to electrical item on wall 2 | | 1 | | | |
| 15589 | ACTIVE | N | N173-00-2/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Colliers Wood Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Small Supalux Board to High Level Wall 3 | | | | | |
| 18343 | ACTIVE | N | N173-00-2/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Colliers Wood Stn | Cable: Sheath | Asbestos | Known | | | | Multiple asbestos cables 1x green braided asbestos cable running from wall 2 duct to invert - 2 metres | | 5 | | | |



Hazardous Material Asset Register - Summary



N173-00 - Station Building - Colliers Wood Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 67599 | ACTIVE | N | N173-00-2/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - Colliers Wood Stn | Cable: Sheath | Asbestos | Known | | | | 1x Asbestos braided earthing cable running from electrical asset on wall 2 to j hanger - 2 metres | 2 | 1 | | | |
| 15590 | INACTIVE | N | N173-00-2/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - Colliers Wood Stn | Other Boarding | Asbestos | Presumed | | | | Small Boarding High Level | | | | | |
| 12185 | ACTIVE | N | N173-00-2/731 | SER - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15593 | ACTIVE | N | N173-00-2/731 | SER - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12186 | ACTIVE | N | N173-00-2/901 | Disused Room - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15594 | ACTIVE | N | N173-00-2/901 | Disused Room - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12187 | ACTIVE | N | N173-00-2/951 | Disused Room - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15595 | ACTIVE | N | N173-00-2/951 | Disused Room - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12188 | ACTIVE | N | N173-00-A/236 | Passage - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15596 | ACTIVE | N | N173-00-A/236 | Passage - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12189 | ACTIVE | N | N173-00-A/576 | Stairs: Linear - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18660 | ACTIVE | N | N173-00-A/576 | Stairs: Linear - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12190 | ACTIVE | N | N173-00-A/731 | CER - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18345 | ACTIVE | N | N173-00-A/731 | CER - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12191 | ACTIVE | N | N173-00-A/732 | CER - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18715 | ACTIVE | N | N173-00-A/732 | CER - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N173-00 - Station Building - Colliers Wood Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|------------------------|---------------|--|----------|-----------|-----------------|---------------------|-------------|------------|-------------|---------------------|-------------------|
| 12192 | ACTIVE | N | N173-00-A/761 | Void - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15597 | ACTIVE | N | N173-00-A/761 | Void - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12193 | ACTIVE | N | N173-00-B/576 | Stairs: Linear - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15598 | ACTIVE | N | N173-00-B/576 | Stairs: Linear - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12194 | ACTIVE | N | N173-00-B/661 | Void - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15599 | ACTIVE | N | N173-00-B/661 | Void - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12195 | ACTIVE | N | N173-00-B/746 | SCR - Station Building - Colliers Wood Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18346 | ACTIVE | N | N173-00-B/746 | SCR - Station Building - Colliers Wood Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 15452 | ACTIVE | N | N173-00/ROF-01 | Structure: Roof - 1 - Station Building - Colliers Wood Stn | Cement Cowlings/ Flues | Asbestos | No Access: Presumed | | | | Cement Flue | | | | | |

N175-00 - Station Building - South Wimbledon Stn - Repair

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 12196 | ACTIVE | N | N175-00-1/001 | Booking Hall - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Presumed | | | | | | | | | |
| 44981 | ACTIVE | N | N175-00-1/001 | Booking Hall - Station Building - South Wimbledon Stn | Glazing Rope | Asbestos | Presumed | | | | Glazing rope to high level entrance throughout | | | | N | N |
| 19298 | INACTIVE | N | N175-00-1/001 | Booking Hall - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible - Relates to 3-5 Morden Road | | | | | |
| 12197 | ACTIVE | N | N175-00-1/011 | Ticket Office - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15398 | ACTIVE | N | N175-00-1/011 | Ticket Office - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12198 | ACTIVE | N | N175-00-1/021 | POM - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N175-00 - Station Building - South Wimbledon Stn - Repair

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|------------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 15399 | ACTIVE | N | N175-00-1/021 | POM - Station Building - South Wimbledon Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Foam Backing Non-Asbestos | | | | | |
| 12199 | ACTIVE | N | N175-00-1/036 | Toilet: Unisex - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15400 | ACTIVE | N | N175-00-1/036 | Toilet: Unisex - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12200 | ACTIVE | N | N175-00-1/071 | Circulation Area - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44982 | ACTIVE | N | N175-00-1/071 | Circulation Area - Station Building - South Wimbledon Stn | Glazing Rope | Asbestos | Presumed | | | | Glazing rope to skylight | | | | N | N |
| 18635 | ACTIVE | N | N175-00-1/071 | Circulation Area - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12201 | ACTIVE | N | N175-00-1/151 | UMC - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18173 | ACTIVE | N | N175-00-1/151 | UMC - Station Building - South Wimbledon Stn | Gasket :Pipework | Asbestos | Strongly Presumed | | | | Gaskets on Fire Main and Ventilation Equipment | | | | | |
| 15404 | ACTIVE | N | N175-00-1/151 | UMC - Station Building - South Wimbledon Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer far LHS corner | | 1 | | | |
| 15402 | ACTIVE | N | N175-00-1/151 | UMC - Station Building - South Wimbledon Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Vermiculite Cladding to Girders | | | | | |
| 44985 | ACTIVE | N | N175-00-1/151 | UMC - Station Building - South Wimbledon Stn | Cable Duct: Other | Asbestos | Strongly Presumed | | | | Ducts with cement infill | | | | N | N |
| 44984 | ACTIVE | N | N175-00-1/151 | UMC - Station Building - South Wimbledon Stn | | Asbestos | Presumed | | | | 1x Flash guard - transformer far LHS corner | | 1 | | N | N |
| 18636 | ACTIVE | N | N175-00-1/151 | UMC - Station Building - South Wimbledon Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Black Gloss on Column. Thickness: 0.26mm Analysis 1.2% | | | | | |
| 41805 | INACTIVE | N | N175-00-1/151 | UMC - Station Building - South Wimbledon Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Cream Walls Lead by weight 0.08% | | | | N | N |
| 15405 | ACTIVE | N | N175-00-1/151 | UMC - Station Building - South Wimbledon Stn | Lead/Leading | Lead Paint/Lead | No Access: Presumed | | | | Green Gloss on Columns under Escalator. Thickness: 0.19mm Analysis 6.1% | | | | | |
| 18172 | ACTIVE | N | N175-00-1/151/CLG-01 | Ceiling: Solid - 1 - UMC - Station Building - South Wimbledon Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux near Stairs | | | | | |
| 15401 | ACTIVE | N | N175-00-1/151/FLR-01 | Floor - 1 - UMC - Station Building - South Wimbledon Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Lid to Storage Bin | | | | | |
| 15403 | ACTIVE | N | N175-00-1/151/WAL-004 | Wall: Internal - 4 - UMC - Station Building - South Wimbledon Stn | Isolator Switches | Asbestos | Known | | | | 9 x Switch Boxes - Insulation within | | | | | |



Hazardous Material Asset Register - Summary



N175-00 - Station Building - South Wimbledon Stn - Repair

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------------|---|-------------------|---------------|--|----------|-----------|-----------------|-----------------------------|-------------|------------|-------------|---------------------|-------------------|
| 12202 | ACTIVE | N | N175-00-1/236 | Lobby - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15406 | ACTIVE | N | N175-00-1/236 | Lobby - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12203 | ACTIVE | N | N175-00-1/237 | Passage - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15407 | ACTIVE | N | N175-00-1/237 | Passage - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12204 | ACTIVE | N | N175-00-1/311 | Locker Room - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15408 | ACTIVE | N | N175-00-1/311/ WAL-005 | Wall: Internal - 5 - Locker Room - Station Building - South Wimbledon Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Foam backing - Non asbestos | | | | | |
| 12205 | ACTIVE | N | N175-00-1/316 | SCR - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18174 | ACTIVE | N | N175-00-1/316 | SCR - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12206 | ACTIVE | N | N175-00-1/331 | Locker Room - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15409 | ACTIVE | N | N175-00-1/331 | Locker Room - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12207 | ACTIVE | N | N175-00-1/396 | SVC - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15410 | ACTIVE | N | N175-00-1/396 | SVC - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12208 | ACTIVE | N | N175-00-1/406 | Switch Room - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44983 | ACTIVE | N | N175-00-1/406/ CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - South Wimbledon Stn | Other Boarding | Asbestos | Presumed | | | | Ceiling panel slight damage | | | | N | N |
| 18650 | ACTIVE | N | N175-00-1/406/ CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - South Wimbledon Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels | | | | | |
| 18175 | ACTIVE | N | N175-00-1/406/ CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - South Wimbledon Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Panels | | | | | |



Hazardous Material Asset Register - Summary



N175-00 - Station Building - South Wimbledon Stn - Repair

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|--------------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 15411 | ACTIVE | N | N175-00-1/406/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - South Wimbledon Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Box 30amp - Insulation within | | 1 | | | |
| 18637 | ACTIVE | N | N175-00-1/406/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - South Wimbledon Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Transformer Box(es) | | 3 | | | |
| 12209 | ACTIVE | N | N175-00-1/411 | Store - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15412 | ACTIVE | N | N175-00-1/411 | Store - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12210 | ACTIVE | N | N175-00-1/416 | Toilet: Female - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15413 | ACTIVE | N | N175-00-1/416 | Toilet: Female - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12211 | ACTIVE | N | N175-00-1/417 | Toilet: Male - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12212 | ACTIVE | N | N175-00-1/451 | Tenancy - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15414 | ACTIVE | N | N175-00-1/451/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - South Wimbledon Stn | No Access | Asbestos | No Access: Presumed | | | | No Access above false ceiling | | | | YES | |
| 12213 | ACTIVE | N | N175-00-1/452 | Tenancy - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18176 | ACTIVE | N | N175-00-1/452/CLG-01 | Ceiling: Solid - 1 - Tenancy - Station Building - South Wimbledon Stn | No Access | Asbestos | No Access: Presumed | | | | No Access above false ceiling | | | | YES | |
| 12214 | ACTIVE | N | N175-00-1/453 | Tenancy - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15415 | ACTIVE | N | N175-00-1/453 | Tenancy - Station Building - South Wimbledon Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - Tenancy | | | | | |
| 12215 | ACTIVE | N | N175-00-1/576 | Stairs: Linear - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15416 | ACTIVE | N | N175-00-1/576 | Stairs: Linear - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12216 | ACTIVE | N | N175-00-1/661 | Switch Room - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N175-00 - Station Building - South Wimbledon Stn - Repair

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 15417 | ACTIVE | N | N175-00-1/661 | Switch Room - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12217 | ACTIVE | N | N175-00-1/664 | Locker Room - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15418 | ACTIVE | N | N175-00-1/664 | Locker Room - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12218 | ACTIVE | N | N175-00-1/666 | Switch Cupboard - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15419 | ACTIVE | N | N175-00-1/666 | Switch Cupboard - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12219 | ACTIVE | N | N175-00-1/751 | Station Control Room - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18177 | ACTIVE | N | N175-00-1/751 | Station Control Room - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12220 | ACTIVE | N | N175-00-2/081 | Circulation Area - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44986 | ACTIVE | N | N175-00-2/081 | Circulation Area - Station Building - South Wimbledon Stn | Caulking | Asbestos | Presumed | | | | Escalator Incline (Non Public Side) - Tunnel Ring Caulking To Tunnel Joints - No Access | | | | N | N |
| 15420 | ACTIVE | N | N175-00-2/081 | Circulation Area - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12221 | ACTIVE | N | N175-00-2/161 | LMC - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15423 | ACTIVE | N | N175-00-2/161 | LMC - Station Building - South Wimbledon Stn | Cable: Sheath | Asbestos | Known | | | | Green Braided Cables | | 4 | | | |
| 15421 | ACTIVE | N | N175-00-2/161 | LMC - Station Building - South Wimbledon Stn | Cable Duct: Other | Asbestos | Surveyed – Not Detected | | | | New Cable Ducts | | 6 | | | |
| 15422 | ACTIVE | N | N175-00-2/161 | LMC - Station Building - South Wimbledon Stn | Cable Duct: Other | Asbestos | Surveyed – Not Detected | | | | Cable Ducts into Inverts | | 4 | | | |
| 12222 | ACTIVE | N | N175-00-2/201 | Passage - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15424 | ACTIVE | N | N175-00-2/201 | Passage - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12223 | ACTIVE | N | N175-00-2/202 | Passage - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N175-00 - Station Building - South Wimbledon Stn - Repair

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 15425 | ACTIVE | N | N175-00-2/202 | Passage - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12224 | ACTIVE | N | N175-00-2/203 | Passage - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15426 | ACTIVE | N | N175-00-2/203 | Passage - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12225 | ACTIVE | N | N175-00-2/204 | Passage - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18178 | ACTIVE | N | N175-00-2/204 | Passage - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12226 | ACTIVE | N | N175-00-2/205 | Passage - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15427 | ACTIVE | N | N175-00-2/205 | Passage - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12227 | ACTIVE | N | N175-00-2/261 | Platform 1 - Northbound Local - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70405 | ACTIVE | N | N175-00-2/261 | Platform 1 - Northbound Local - Station Building - South Wimbledon Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 6 no - To platform wall, midway | | 6 | R728753 | N | Y |
| 15428 | ACTIVE | N | N175-00-2/261 | Platform 1 - Northbound Local - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 44987 | ACTIVE | N | N175-00-2/261 | Platform 1 - Northbound Local - Station Building - South Wimbledon Stn | Cable: Sheath | Asbestos | Known | | | | 4no cables to tail end of platform on cable run | | | | N | N |
| 44988 | ACTIVE | N | N175-00-2/261 | Platform 1 - Northbound Local - Station Building - South Wimbledon Stn | Westing house Boxes | Asbestos | Presumed | | | | Platform 1 Invert - Small Westinghouse Box to wall trackside | | | | N | N |
| 70402 | ACTIVE | N | N175-00-2/261 | Platform 1 - Northbound Local - Station Building - South Wimbledon Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728753 | | |
| 70401 | ACTIVE | N | N175-00-2/261 | Platform 1 - Northbound Local - Station Building - South Wimbledon Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Invert -Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728753 | | |
| 70407 | ACTIVE | N | N175-00-2/261 | Platform 1 - Northbound Local - Station Building - South Wimbledon Stn | Ducts | Asbestos | Sampled – Not Detected | | | | Platform Invert - Terracotta cable ducts - total 3 no | | 3 | R728753 | | |
| 70406 | ACTIVE | N | N175-00-2/261 | Platform 1 - Northbound Local - Station Building - South Wimbledon Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Platform Invert - Small Westinghouse box - total 1 no - To platform wall, midway | | 1 | R728753 | | |



Hazardous Material Asset Register - Summary



N175-00 - Station Building - South Wimbledon Stn - Repair

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|----------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 70404 | ACTIVE | N | N175-00-2/261 | Platform 1 - Northbound Local - Station Building - South Wimbledon Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - total 3 no - To trackside wall, tail end | | 3 | R728753 | | |
| 18179 | ACTIVE | N | N175-00-2/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - South Wimbledon Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Platform 1 Invert - White Cable 40ml x 100mm diameter | | | | | YES |
| 15430 | ACTIVE | N | N175-00-2/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - South Wimbledon Stn | Cable: Sheath | Asbestos | No Access: Presumed | | | | Cables near 2/711 | | 4 | | | YES |
| 15429 | ACTIVE | N | N175-00-2/261/FLR-01 | Floor - 1 - Platform 1 - Station Building - South Wimbledon Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables entire length of Invert | | 2 | | | YES |
| 12228 | ACTIVE | N | N175-00-2/262 | Platform 2 - Southbound Local - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70414 | ACTIVE | N | N175-00-2/262 | Platform 2 - Southbound Local - Station Building - South Wimbledon Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 4 no - To ceiling, head wall | | 4 | R728753 | N | Y |
| 15431 | ACTIVE | N | N175-00-2/262 | Platform 2 - Southbound Local - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 44991 | ACTIVE | N | N175-00-2/262 | Platform 2 - Southbound Local - Station Building - South Wimbledon Stn | Cable: Sheath | Asbestos | Known | | | | Platform 2 Invert - 5no to cable run running throughout & going out of invert | | | | N | N |
| 44990 | ACTIVE | N | N175-00-2/262 | Platform 2 - Southbound Local - Station Building - South Wimbledon Stn | Westing house Boxes | Asbestos | Presumed | | | | Platform 2 Invert - Small Westinghouse Box to wall trackside | | | | N | N |
| 44989 | ACTIVE | N | N175-00-2/262 | Platform 2 - Southbound Local - Station Building - South Wimbledon Stn | Cable: Sheath | Asbestos | Known | | | | 4no cables to head end on cable run | | | | N | N |
| 70413 | ACTIVE | N | N175-00-2/262 | Platform 2 - Southbound Local - Station Building - South Wimbledon Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 6 no - To platform wall | | 6 | R728753 | N | Y |
| 70412 | ACTIVE | N | N175-00-2/262 | Platform 2 - Southbound Local - Station Building - South Wimbledon Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 6 no - To platform wall, midway | | 6 | R728753 | N | Y |
| 70408 | ACTIVE | N | N175-00-2/262 | Platform 2 - Southbound Local - Station Building - South Wimbledon Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Metal tunnel rings - concrete infill - To walls, floor throughout | | | R728753 | | |
| 70409 | ACTIVE | N | N175-00-2/262 | Platform 2 - Southbound Local - Station Building - South Wimbledon Stn | Tunnel Ring Caulking | Asbestos | Sampled – Not Detected | | | | Platform Invert - Grout/ wood/ lead - To tunnel rings flanges throughout | | | R728753 | | |
| 70411 | ACTIVE | N | N175-00-2/262 | Platform 2 - Southbound Local - Station Building - South Wimbledon Stn | Cable Ducts: Bitumen | Asbestos | Sampled – Not Detected | | | | Platform Invert - Bitumen cable ducts - total 4 no - To ceiling - arrivals end/ tail end | | 4 | R728753 | N | Y |



Hazardous Material Asset Register - Summary



N175-00 - Station Building - South Wimbledon Stn - Repair

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 70410 | ACTIVE | N | N175-00-2/262 | Platform 2 - Southbound Local - Station Building - South Wimbledon Stn | Cable Sheath | Asbestos | Known | | | | Platform Invert - Braided cables - total 3 no - To trackside wall | | 3 | R728753 | | |
| 18638 | ACTIVE | N | N175-00-2/262/FLR-01 | Floor - 1 - Platform 2 - Station Building - South Wimbledon Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Green Cable 40ml x 20mm diameter | | 1 | | | YES |
| 12229 | ACTIVE | N | N175-00-2/661 | Disused Room - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12230 | ACTIVE | N | N175-00-2/662 | Lobby - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15432 | ACTIVE | N | N175-00-2/662 | Lobby - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12231 | ACTIVE | N | N175-00-2/663 | Disused Room - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12232 | ACTIVE | N | N175-00-2/664 | Switch Cupboard - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15433 | ACTIVE | N | N175-00-2/664 | Switch Cupboard - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 44992 | ACTIVE | N | N175-00-2/664/FLR-01 | Floor - 1 - Switch Cupboard - Station Building - South Wimbledon Stn | Cable Duct: Other | Asbestos | Presumed | | | | Cable ducts to floor - no access for sampling | | | | N | N |
| 12233 | ACTIVE | N | N175-00-2/665 | Switch Room - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18180 | ACTIVE | N | N175-00-2/665 | Switch Room - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12234 | ACTIVE | N | N175-00-2/666 | Switch Room - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15434 | ACTIVE | N | N175-00-2/666 | Switch Room - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 44993 | ACTIVE | N | N175-00-2/666/FLR-01 | Floor - 1 - Switch Room - Station Building - South Wimbledon Stn | Cable Duct: Other | Asbestos | Presumed | | | | Cable ducts to floor - no access for sampling | | | | N | N |
| 12235 | ACTIVE | N | N175-00-2/667 | Switch Cupboard - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15435 | ACTIVE | N | N175-00-2/667 | Switch Cupboard - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N175-00 - Station Building - South Wimbledon Stn - Repair

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 12236 | ACTIVE | N | N175-00-2/711 | Relay Room - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44994 | INACTIVE | N | N175-00-2/711 | Relay Room - Station Building - South Wimbledon Stn | Vinyl tiles | Asbestos | Known | | | | Grey Vinyl tiles to high level walls and ceiling | 50 | | | N | N |
| 67912 | ACTIVE | N | N175-00-2/711 | Relay Room - Station Building - South Wimbledon Stn | Other Boarding | Asbestos | Presumed | | | | round packing board to frame throughout | | | | | |
| 67911 | ACTIVE | N | N175-00-2/711 | Relay Room - Station Building - South Wimbledon Stn | Other Boarding | Asbestos | Known | | | | brown square packing board throughout | | | R737376 | | |
| 44995 | INACTIVE | N | N175-00-2/711 | Relay Room - Station Building - South Wimbledon Stn | Cable: Sheath | Asbestos | Known | | | | Green braided cables To ducts and wall 3, first and last J Hangers 2no x 3m | 3 | 2 | | N | N |
| 15438 | ACTIVE | N | N175-00-2/711/CLG-01 | Ceiling: Solid - 1 - Relay Room - Station Building - South Wimbledon Stn | Vinyl tiles | Asbestos | Known | | | | Asbestos - K 50sqm Grey Vinyl tiles to high level walls and ceiling | | | | | |
| 44998 | ACTIVE | N | N175-00-2/711/FLR-01 | Floor - 1 - Relay Room - Station Building - South Wimbledon Stn | Cable Duct: Other | Asbestos | Presumed | | | | 3no ducts to floor by wall 2 - no access for sampling | | 3 | | N | N |
| 67904 | ACTIVE | N | N175-00-2/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - South Wimbledon Stn | Other Boarding | Asbestos | Presumed | | | | 10 brown board to equipment to top rack | | | | | |
| 44997 | ACTIVE | N | N175-00-2/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - South Wimbledon Stn | Boarding: Cement | Asbestos | Known | | | | Cement Panel to top shelf on rack of wall 1 | 1 | 1 | | N | N |
| 44996 | ACTIVE | N | N175-00-2/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - South Wimbledon Stn | Other Boarding | Asbestos | Presumed | | | | Brown composite panel To wall 1 by CR(N) circuit | | | | N | N |
| 19945 | ACTIVE | N | N175-00-2/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - South Wimbledon Stn | Boarding: Cement | Asbestos | Presumed | | | | Cement Panel to the bottom of rack | | | | | |
| 15439 | ACTIVE | N | N175-00-2/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - South Wimbledon Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Westinghouse Box to back of wall 1 | | 1 | | | |
| 67905 | ACTIVE | N | N175-00-2/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - South Wimbledon Stn | Cable: Wrap | Asbestos | Surveyed – Not Detected | | | | green aramid cables non asbestos to rack at front of wall 1 | | | | | |
| 18181 | ACTIVE | N | N175-00-2/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - South Wimbledon Stn | Vinyl tiles | Asbestos | Known | | | | 40sqm Green & White Vinyl tiles | | | | | |
| 18182 | ACTIVE | N | N175-00-2/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - South Wimbledon Stn | Cable: Sheath | Asbestos | Presumed | | | | Cables within J-hangers - 4 white asbestos cables: 2 top row 6m exiting trackside wall 3 2 middle row of trunking 5m exiting invert through duct wall 2 | | | | | |



Hazardous Material Asset Register - Summary



N175-00 - Station Building - South Wimbledon Stn - Repair

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|------------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 15440 | INACTIVE | N | N175-00-2/711/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - South Wimbledon Stn | PCBs | Polychlorinated biphenyl | Removed | | | | 6 x PCB's - Fair Condition Serial Nos.186508, 186441, 186563, 186565, 186438, 186144, 186566 Re Inspected 14/04/2015 | | 5 | | | |
| 18238 | INACTIVE | N | N175-00-2/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - South Wimbledon Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | | | 1 | | | |
| 19429 | ACTIVE | N | N175-00-2/711/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - South Wimbledon Stn | Vinyl tiles | Asbestos | Known | | | | 40sqm Green & White Vinyl tiles | | | | | |
| 15436 | ACTIVE | N | N175-00-2/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - South Wimbledon Stn | Vinyl tiles | Asbestos | Known | | | | 40sqm Green & White Vinyl tiles | | | | | |
| 18651 | ACTIVE | N | N175-00-2/711/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - South Wimbledon Stn | Cable: Sheath | Asbestos | Presumed | | | | Green asbestos cable x1 exiting trackside going into invert wall 2 | | 1 | | | |
| 15437 | ACTIVE | N | N175-00-2/711/WAL-004 | Wall: Internal - 4 - Relay Room - Station Building - South Wimbledon Stn | Vinyl tiles | Asbestos | Known | | | | 40sqm Green & White Vinyl tiles | | | | | |
| 12237 | ACTIVE | N | N175-00-2/712 | Relay Room - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15444 | ACTIVE | N | N175-00-2/712 | Relay Room - Station Building - South Wimbledon Stn | Boarding: Cement | Asbestos | Known | | | | Cement Panels to top and bottom shelving at wall 3 - 2no x 1m - slight damage | | | | | |
| 44999 | INACTIVE | N | N175-00-2/712 | Relay Room - Station Building - South Wimbledon Stn | Boarding: Cement | Asbestos | Known | | | | Cement Panels to top and bottom shelving at wall 3 - 2no x 1m - slight damage | 1 | 2 | | N | N |
| 18184 | INACTIVE | N | N175-00-2/712 | Relay Room - Station Building - South Wimbledon Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | 6 x PCB's - Fair Condition Serial Nos. 186492; 186488; 186411; 186505; 186522; 186424, 186566, 186563, 186438, 186508 Re inspected 14/04/2015 | | 6 | | | |
| 45000 | ACTIVE | N | N175-00-2/712/FLR-01 | Floor - 1 - Relay Room - Station Building - South Wimbledon Stn | Cable Duct: Other | Asbestos | Presumed | | | | 4no ducts to floor by wall 2 - no access for sampling | | | | N | N |
| 15441 | ACTIVE | N | N175-00-2/712/WAL-001 | Wall: Internal - 1 - Relay Room - Station Building - South Wimbledon Stn | Vinyl tiles | Asbestos | Known | | | | Red Vinyl Wall Tiles - poor condition | | | | | |
| 15446 | ACTIVE | N | N175-00-2/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - South Wimbledon Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Electrical Boxes x2 | | 1 | | | |
| 18652 | ACTIVE | N | N175-00-2/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - South Wimbledon Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | wall 2-3 Asbestos Cables: 3 cables - 2 white , 1 green 2 white cable approx.2m length going into fuse board wall 3 1 green cable exiting at wall 3 trackside approx.1.5 m length | | | | | |
| 15442 | ACTIVE | N | N175-00-2/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - South Wimbledon Stn | Vinyl tiles | Asbestos | Known | | | | Red Vinyl Wall Tiles - poor condition | | | | | |



Hazardous Material Asset Register - Summary



N175-00 - Station Building - South Wimbledon Stn - Repair

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 15445 | ACTIVE | N | N175-00-2/712/WAL-002 | Wall: Internal - 2 - Relay Room - Station Building - South Wimbledon Stn | Westinghouse Boxes | Asbestos | Presumed | | | | Westinghouse box to wall 2 | | 1 | | | |
| 53663 | ACTIVE | N | N175-00-2/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - South Wimbledon Stn | Other Boarding | Asbestos | Presumed | | | | 3x light brown board to rack on wall 3 | | | | | |
| 53652 | ACTIVE | N | N175-00-2/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - South Wimbledon Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 1 white cable running from fuse board exiting trackside length 1m | | | | | |
| 53661 | ACTIVE | N | N175-00-2/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - South Wimbledon Stn | Other Boarding | Asbestos | Presumed | | | | Black composite to top shelf of rack on capacitor x2 black - wall 3 | | | | | |
| 18183 | ACTIVE | N | N175-00-2/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - South Wimbledon Stn | Vinyl tiles | Asbestos | Known | | | | Red Vinyl Wall Tiles | | | | | |
| 53662 | ACTIVE | N | N175-00-2/712/WAL-003 | Wall: Internal - 3 - Relay Room - Station Building - South Wimbledon Stn | Other Boarding | Asbestos | Presumed | | | | 3x dark brown board to capacitor rack top wall 3 | | | | | |
| 15443 | ACTIVE | N | N175-00-2/712/WAL-004 | Wall: Internal - 4 - Relay Room - Station Building - South Wimbledon Stn | Vinyl tiles | Asbestos | Known | | | | Red Vinyl Wall Tiles - poor condition | | | | | |
| 12238 | ACTIVE | N | N175-00-2/761 | Cleaners Store - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15447 | ACTIVE | N | N175-00-2/761 | Cleaners Store - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12239 | ACTIVE | N | N175-00-2/951 | SER - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15448 | ACTIVE | N | N175-00-2/951 | SER - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12240 | ACTIVE | N | N175-00-2/963 | Store - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15449 | ACTIVE | N | N175-00-2/963 | Store - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12241 | ACTIVE | N | N175-00-A/661 | CER - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15450 | ACTIVE | N | N175-00-A/661/FLR-01 | Floor - 1 - CER - Station Building - South Wimbledon Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Existing Containment beneath Computer Tiles | | | | | YES |
| 45411 | ACTIVE | N | N175-00-A/661/WAL-003 | Wall: Internal - 3 - CER - Station Building - South Wimbledon Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 2no Combination fuse switches | | 2 | | N | N |



Hazardous Material Asset Register - Summary



N175-00 - Station Building - South Wimbledon Stn - Repair

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|--------------------------|-------------|------------|-------------|---------------------|-------------------|
| 12242 | ACTIVE | N | N175-00-A/731 | Switch Room - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12243 | ACTIVE | N | N175-00-A/732 | Switch Room - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15451 | ACTIVE | N | N175-00-A/732 | Switch Room - Station Building - South Wimbledon Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12244 | ACTIVE | N | N175-00-A/901 | Disused Room - Station Building - South Wimbledon Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18185 | ACTIVE | N | N175-00-A/901 | Disused Room - Station Building - South Wimbledon Stn | No Access | Asbestos | No Access: Presumed | | | | No Access - Not Surveyed | | | | | |

N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 12248 | ACTIVE | N | N177-00-1/001 | Booking Hall - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42585 | ACTIVE | N | N177-00-1/001 | Booking Hall - Station Building - Morden Stn | Other Boarding | Asbestos | Room: Surveyed – Asbestos Known | | | | Board, 2m2, on left hand side front of Morden Station | 2 | 2 | R508576 | N | N |
| 15138 | ACTIVE | N | N177-00-1/001 | Booking Hall - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 15139 | ACTIVE | N | N177-00-1/001/CLG-01 | Ceiling: Solid - 1 - Booking Hall - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Painted beams supporting the ticket hall | | | | | |
| 12249 | ACTIVE | N | N177-00-1/011 | Ticket Office - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70069 | ACTIVE | N | N177-00-1/011 | Ticket Office - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | The boxing within 1/011 was inspected as part of project works to strip this room. No asbestos containing materials were identified. Metal and plastic pipework present, foam insulation. supalux vertical boxing on wooden frame. | | | R752026 | | |
| 69317 | ACTIVE | N | N177-00-1/011 | Ticket Office - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | White gloss paint to wall - <0.02% | | | R747501 | | |
| 69316 | ACTIVE | N | N177-00-1/011 | Ticket Office - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Cream gloss paint to wall - <0.02% | | | R747501 | | |
| 15141 | ACTIVE | N | N177-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Morden Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Ceiling | | | | | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18471 | ACTIVE | N | N177-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Metal Ducts; Fibreglass Lagging; | | | | YES | |
| 15142 | ACTIVE | N | N177-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Morden Stn | Cable: Wrap | Asbestos | Surveyed – Not Detected | | | | Tape | | | | YES | |
| 43104 | ACTIVE | N | N177-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Wooden windows to North wall (White Gloss) 1.30% | | | R519077 | N | N |
| 19166 | ACTIVE | N | N177-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Wooden Skylight | | | | | |
| 43103 | ACTIVE | N | N177-00-1/011/CLG-01 | Ceiling: Suspended - 1 - Ticket Office - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Brown Gloss Original ceiling within the false ceiling (Brown Gloss) 1.77% | | | R519077 | Y | N |
| 15140 | ACTIVE | N | N177-00-1/011/FLR-01 | Floor - 1 - Ticket Office - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath wooden false floor | | | | | Yes |
| 12250 | ACTIVE | N | N177-00-1/021 | POM - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15144 | ACTIVE | N | N177-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Metal Ducts above Supalux Tiles | | | | YES | |
| 42966 | ACTIVE | N | N177-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Morden Stn | Boarding: Supalux | Asbestos | Sampled – Not Detected | | | | Supalux 8m (l), within panel to floor slab under machine, within POM room | | | R519706 | N | N |
| 19167 | ACTIVE | N | N177-00-1/021/CLG-01 | Ceiling: Suspended - 1 - POM - Station Building - Morden Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 15143 | ACTIVE | N | N177-00-1/021/FLR-01 | Floor - 1 - POM - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath wooden false floor | | | | | YES |
| 12251 | ACTIVE | N | N177-00-1/031 | Mess Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15145 | ACTIVE | N | N177-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Morden Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board | | | | | |
| 15146 | ACTIVE | N | N177-00-1/031/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Metal Ducts above Supalux Board | | | | YES | |
| 12252 | ACTIVE | N | N177-00-1/036 | Toilet: Unisex - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 69318 | ACTIVE | N | N177-00-1/036 | Toilet: Unisex - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Cream gloss paint to wall - 0.19% | | | R747501 | | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|-------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 69319 | ACTIVE | N | N177-00-1/036 | Toilet: Unisex - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Cream gloss paint to pipework - <0.02% | | | R747501 | | |
| 19168 | ACTIVE | N | N177-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Metal Ducts above Supalux Tiles | | | | YES | |
| 15147 | ACTIVE | N | N177-00-1/036/CLG-01 | Ceiling: Suspended - 1 - Toilet - Station Building - Morden Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 12253 | ACTIVE | N | N177-00-1/041 | Mess Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15148 | ACTIVE | N | N177-00-1/041/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Morden Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Non Asbestos Boarding | | | | | |
| 18576 | ACTIVE | N | N177-00-1/041/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Wood above false ceiling | | | | YES | |
| 12254 | ACTIVE | N | N177-00-1/042 | Mess Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15150 | INACTIVE | N | N177-00-1/042/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plasterboard above Polystyrene false ceiling / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | YES | |
| 15149 | INACTIVE | N | N177-00-1/042/FLR-01 | Floor - 1 - Mess Room - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | YES |
| 12255 | ACTIVE | N | N177-00-1/047 | Kitchen - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15151 | ACTIVE | N | N177-00-1/047/CLG-01 | Ceiling: Solid - 1 - Kitchen - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Wood above Supalux Tiles | | | | YES | |
| 18547 | ACTIVE | N | N177-00-1/047/CLG-01 | Ceiling: Solid - 1 - Kitchen - Station Building - Morden Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 12256 | ACTIVE | N | N177-00-1/048 | Kitchen - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 18164 | INACTIVE | N | N177-00-1/048/CLG-01 | Ceiling: Solid - 1 - Kitchen - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Board / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17925 | INACTIVE | N | N177-00-1/048/CLG-01 | Ceiling: Solid - 1 - Kitchen - Station Building - Morden Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 12257 | ACTIVE | N | N177-00-1/053 | Mess Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15152 | ACTIVE | N | N177-00-1/053/DOR-01 | Door - 1 - Mess Room - Station Building - Morden Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board | | | | | |
| 15153 | ACTIVE | N | N177-00-1/053/DOR-01 | Door - 1 - Mess Room - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Board | | | | | |
| 12258 | ACTIVE | N | N177-00-1/054 | Switch Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15155 | ACTIVE | N | N177-00-1/054/CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Boxing | | | | | |
| 15154 | ACTIVE | N | N177-00-1/054/CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - Morden Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 12259 | ACTIVE | N | N177-00-1/056 | Toilet: Unisex - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15156 | ACTIVE | N | N177-00-1/056/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Board | | | | | |
| 17926 | ACTIVE | N | N177-00-1/056/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Morden Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board | | | | | |
| 12260 | ACTIVE | N | N177-00-1/071 | Circulation Area - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15157 | ACTIVE | N | N177-00-1/071 | Circulation Area - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | YES | |
| 12261 | ACTIVE | N | N177-00-1/081 | Lobby - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15158 | ACTIVE | N | N177-00-1/081/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Wood above Plaster/Tiles false ceiling | | | | YES | |
| 12263 | ACTIVE | N | N177-00-1/083 | Lobby - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15160 | ACTIVE | N | N177-00-1/083/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Above Wood Ceiling | | | | | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 12264 | ACTIVE | N | N177-00-1/084 | Lobby - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15161 | ACTIVE | N | N177-00-1/084 | Lobby - Station Building - Morden Stn | No Access | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 12265 | ACTIVE | N | N177-00-1/086 | Lobby - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18548 | ACTIVE | N | N177-00-1/086 | Lobby - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12266 | ACTIVE | N | N177-00-1/087 | Lobby - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15162 | ACTIVE | N | N177-00-1/087 | Lobby - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12267 | ACTIVE | N | N177-00-1/092 | Lobby - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12268 | ACTIVE | N | N177-00-1/131 | LMR - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15163 | ACTIVE | N | N177-00-1/131 | LMR - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12269 | ACTIVE | N | N177-00-1/132 | LMR - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15164 | ACTIVE | N | N177-00-1/132 | LMR - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 17928 | ACTIVE | N | N177-00-1/136 | Lift Shaft - Station Building - Morden Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 15165 | ACTIVE | N | N177-00-1/137 | Lift Shaft - Station Building - Morden Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 12270 | ACTIVE | N | N177-00-1/201 | Passage - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15166 | ACTIVE | N | N177-00-1/201 | Passage - Station Building - Morden Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board nr White Door | | | | | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 12271 | ACTIVE | N | N177-00-1/202 | Passage - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15167 | ACTIVE | N | N177-00-1/202/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Above Wood Ceiling | | | | | |
| 12272 | ACTIVE | N | N177-00-1/203 | Passage - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18549 | ACTIVE | N | N177-00-1/203 | Passage - Station Building - Morden Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 12273 | ACTIVE | N | N177-00-1/236 | Passage - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15168 | ACTIVE | N | N177-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Morden Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux - Acoustic Panel, Fibreboard | | | | | |
| 17929 | ACTIVE | N | N177-00-1/236/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Fibreboard; Wooden Roof above false ceiling | | | | YES | |
| 12274 | ACTIVE | N | N177-00-1/237 | Passage - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 43637 | ACTIVE | N | N177-00-1/237 | Passage - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | White paint to ceiling over head of access door thickness 240 0.01% | | | R588826 | N | N |
| 12275 | ACTIVE | N | N177-00-1/238 | Lobby - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15169 | ACTIVE | N | N177-00-1/238/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Glass, Supalux | | | | | |
| 15170 | ACTIVE | N | N177-00-1/238/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Above - Glass, Supalux false ceiling | | | | | |
| 43530 | ACTIVE | N | N177-00-1/238/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Yellow Gloss Handrail thickness 190 0.05% | | | R564777 | N | N |
| 43526 | ACTIVE | N | N177-00-1/238/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Cream Matt Wall 4 thickness 390 0.08% | | | R564777 | N | N |
| 43527 | ACTIVE | N | N177-00-1/238/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Cream Matt Pipe to wall thickness 290 0.42% | | | R564777 | N | N |
| 43528 | ACTIVE | N | N177-00-1/238/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Cream Matt Wall 3 thickness 380 1.34% | | | R564777 | N | N |
| 43529 | ACTIVE | N | N177-00-1/238/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | White Matt Wooden door frame entrance thickness 720 3.42% | | | R564777 | N | N |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|-------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 12276 | ACTIVE | N | N177-00-1/239 | Passage - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 69320 | ACTIVE | N | N177-00-1/239 | Passage - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Sampled – Not Detected | | | | Cream gloss paint to walls - <0.02% | | | R747501 | | |
| 17930 | ACTIVE | N | N177-00-1/239/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Metal Ducts above Supalux Board | | | | YES | |
| 15172 | ACTIVE | N | N177-00-1/239/CLG-01 | Ceiling: Suspended - 1 - Passage - Station Building - Morden Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board | | | | | |
| 15171 | ACTIVE | N | N177-00-1/239/FLR-01 | Floor - 1 - Passage - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath the Wooden False Floor | | | | | YES |
| 12277 | ACTIVE | N | N177-00-1/240 | Passage - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15173 | ACTIVE | N | N177-00-1/240/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Hardboard above Acoustic Panels | | | | YES | |
| 12278 | ACTIVE | N | N177-00-1/241 | Passage - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15174 | INACTIVE | N | N177-00-1/241/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plasterboard above Polystyrene False Ceiling / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | YES | |
| 18550 | INACTIVE | N | N177-00-1/241/FLR-01 | Floor - 1 - Passage - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | YES |
| 12279 | ACTIVE | N | N177-00-1/242 | Passage - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15175 | INACTIVE | N | N177-00-1/242/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal False Ceiling / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 18475 | INACTIVE | N | N177-00-1/242/FLR-01 | Floor - 1 - Passage - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | YES |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 12280 | ACTIVE | N | N177-00-1/243 | Passage - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15176 | ACTIVE | N | N177-00-1/243 | Passage - Station Building - Morden Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 12281 | ACTIVE | N | N177-00-1/281 | Office - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15177 | ACTIVE | N | N177-00-1/281/CLG-01 | Ceiling: Solid - 1 - Office - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Wood, Fibreglass Lagging above Tiled Ceiling | | | | YES | |
| 12282 | ACTIVE | N | N177-00-1/284 | Station Supervisor Office - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17931 | ACTIVE | N | N177-00-1/284 | Station Supervisor Office - Station Building - Morden Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 12283 | ACTIVE | N | N177-00-1/291 | Office - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15178 | INACTIVE | N | N177-00-1/291 | Office - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 12284 | ACTIVE | N | N177-00-1/301 | Passage - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15179 | ACTIVE | N | N177-00-1/301/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Wood, above Panels, Glass | | | | YES | |
| 12285 | ACTIVE | N | N177-00-1/302 | Mess Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18165 | ACTIVE | N | N177-00-1/302/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Morden Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Tiles | | | | | |
| 15180 | ACTIVE | N | N177-00-1/302/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Tiles | | | | | |
| 12286 | ACTIVE | N | N177-00-1/306 | Office - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|-------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18551 | INACTIVE | N | N177-00-1/306/CLG-01 | Ceiling: Solid - 1 - Office - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Board / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 17932 | INACTIVE | N | N177-00-1/306/CLG-01 | Ceiling: Solid - 1 - Office - Station Building - Morden Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 12287 | ACTIVE | N | N177-00-1/311 | Office - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15181 | ACTIVE | N | N177-00-1/311 | Office - Station Building - Morden Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - Foam Insulation Board | | | | | |
| 15182 | ACTIVE | N | N177-00-1/311/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Morden Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board | | | | | |
| 18161 | ACTIVE | N | N177-00-1/311/CLG-01 | Ceiling: Suspended - 1 - Office - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete; Metal Ducts above Supalux Board | | | | YES | |
| 12288 | ACTIVE | N | N177-00-1/316 | SER - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19082 | ACTIVE | N | N177-00-1/316 | SER - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | YES | |
| 12289 | ACTIVE | N | N177-00-1/317 | Quiet Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18538 | ACTIVE | N | N177-00-1/317 | Quiet Room - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12291 | ACTIVE | N | N177-00-1/331 | Mess Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19083 | ACTIVE | N | N177-00-1/331/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete, Wood - Above Tiles | | | | YES | |
| 43634 | ACTIVE | N | N177-00-1/331/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Pink flaking paint to walls thickness 330 0.01% | | | R588826 | N | N |
| 12293 | ACTIVE | N | N177-00-1/342 | Mess Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15058 | ACTIVE | N | N177-00-1/342 | Mess Room - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 15057 | ACTIVE | N | N177-00-1/342/WAL-001 | Wall: Internal - 1 - Mess Room - Station Building - Morden Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Board | | | | | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 15059 | ACTIVE | N | N177-00-1/342/WAL-002 | Wall: Internal - 2 - Mess Room - Station Building - Morden Stn | LUL Heaters | Asbestos | Removed | | | | Insulation within CEH Heater | | | | | |
| 12294 | ACTIVE | N | N177-00-1/401 | Store - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18539 | ACTIVE | N | N177-00-1/401/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Morden Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel, Concrete | | | | | |
| 12295 | ACTIVE | N | N177-00-1/402 | Store - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15060 | ACTIVE | N | N177-00-1/402 | Store - Station Building - Morden Stn | | Asbestos | Room: Asbestos Free | | | | No Asbestos Visible / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | YES | |
| 12296 | ACTIVE | N | N177-00-1/406 | Store - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18572 | ACTIVE | N | N177-00-1/406/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Morden Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel, Concrete | | | | | |
| 12297 | ACTIVE | N | N177-00-1/407 | Store - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 19084 | INACTIVE | N | N177-00-1/407/FLR-01 | Floor - 1 - Store - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Rubber Flooring / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | YES |
| 12298 | ACTIVE | N | N177-00-1/411 | Store - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15061 | ACTIVE | N | N177-00-1/411 | Store - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12299 | ACTIVE | N | N177-00-1/413 | Switch Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15062 | ACTIVE | N | N177-00-1/413 | Switch Room - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12300 | ACTIVE | N | N177-00-1/414 | Locker Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 15064 | ACTIVE | N | N177-00-1/414/CLG-01 | Ceiling: Solid - 1 - Locker Room - Station Building - Morden Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panels | | | | | |
| 19085 | ACTIVE | N | N177-00-1/414/CLG-01 | Ceiling: Solid - 1 - Locker Room - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Panels | | | | | |
| 15063 | ACTIVE | N | N177-00-1/414/FLR-01 | Floor - 1 - Locker Room - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Rubber Flooring | | | | | YES |
| 12302 | ACTIVE | N | N177-00-1/416 | Toilet: Female - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15066 | ACTIVE | N | N177-00-1/416 | Toilet: Female - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 43533 | ACTIVE | N | N177-00-1/416/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Room: Surveyed – Asbestos Known | | | | White Matt Door frame 810 3.37% | | | R564777 | N | N |
| 43636 | ACTIVE | N | N177-00-1/416/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | White paint to ceiling thickness 110 0.02% | | | R588826 | N | N |
| 43534 | ACTIVE | N | N177-00-1/416/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Room: Surveyed – Asbestos Known | | | | White Matt Door 110 0.05% | | | R564777 | N | N |
| 43635 | ACTIVE | N | N177-00-1/416/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Cream paint to walls. thickness 160 0.02% | | | R588826 | N | N |
| 44966 | ACTIVE | N | N177-00-1/416/DOR-01 | Door - 1 - Toilet - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | White Matt Door | | | | N | N |
| 44965 | ACTIVE | N | N177-00-1/416/DOR-01 | Door - 1 - Toilet - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | White Matt Door Frame | | | | N | N |
| 12303 | ACTIVE | N | N177-00-1/417 | Lobby - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15067 | ACTIVE | N | N177-00-1/417/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Boxing | | | | | |
| 43532 | ACTIVE | N | N177-00-1/417/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Room: Surveyed – Asbestos Known | | | | White Matt Door 110 0.05% | | | R564777 | N | N |
| 43531 | ACTIVE | N | N177-00-1/417/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Room: Surveyed – Asbestos Known | | | | White Matt Door frame 680 2.11% | | | R564777 | N | N |
| 44967 | ACTIVE | N | N177-00-1/417/DOR-01 | Door - 1 - Lobby - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | White Matt Door Frame | | | | N | N |
| 44968 | ACTIVE | N | N177-00-1/417/DOR-01 | Door - 1 - Lobby - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | White Matt Door | | | | N | N |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 12304 | ACTIVE | N | N177-00-1/418 | Toilet: Male - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15068 | ACTIVE | N | N177-00-1/418 | Toilet: Male - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | Water Tank - Non Asbestos | | | | | |
| 18540 | ACTIVE | N | N177-00-1/418 | Toilet: Male - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 12305 | ACTIVE | N | N177-00-1/419 | Mess Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15069 | ACTIVE | N | N177-00-1/419 | Mess Room - Station Building - Morden Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Supalux Panel above Heater | | | | | |
| 43638 | ACTIVE | N | N177-00-1/419 | Mess Room - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | White paint around the ceiling roof light thickness 470 0.02% | | | R588826 | N | N |
| 12306 | ACTIVE | N | N177-00-1/420 | Mess Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19086 | ACTIVE | N | N177-00-1/420 | Mess Room - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 43632 | ACTIVE | N | N177-00-1/420 | Mess Room - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Cream flaking paint to walls thickness110 0.02% | | | R588826 | N | N |
| 43633 | ACTIVE | N | N177-00-1/420 | Mess Room - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | White flaking paint to ceiling thickness 750 2.26% | | | R588826 | N | N |
| 12307 | ACTIVE | N | N177-00-1/421 | Toilet: Female - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15070 | ACTIVE | N | N177-00-1/421 | Toilet: Female - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12308 | ACTIVE | N | N177-00-1/422 | Toilet: Male - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15071 | ACTIVE | N | N177-00-1/422/ FLR-01 | Floor - 1 - Toilet - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Plasterboard Floor | | | | | YES |
| 12311 | ACTIVE | N | N177-00-1/425 | Shower Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18541 | ACTIVE | N | N177-00-1/425 | Shower Room - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12312 | ACTIVE | N | N177-00-1/426 | Toilet: Female - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 15074 | ACTIVE | N | N177-00-1/426 | Toilet: Female - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12313 | ACTIVE | N | N177-00-1/427 | Toilet: Male - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15076 | INACTIVE | N | N177-00-1/427/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plasterboard Tiles above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | YES | |
| 15075 | INACTIVE | N | N177-00-1/427/FLR-01 | Floor - 1 - Toilet - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Metal False Floor /T his room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | YES |
| 12314 | ACTIVE | N | N177-00-1/428 | Toilet - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 19150 | INACTIVE | N | N177-00-1/428/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plasterboard Tiles above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | YES | |
| 15077 | INACTIVE | N | N177-00-1/428/FLR-01 | Floor - 1 - Toilet - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | YES |
| 12315 | ACTIVE | N | N177-00-1/429 | Toilet - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15078 | ACTIVE | N | N177-00-1/429 | Toilet - Station Building - Morden Stn | No Access | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 12316 | ACTIVE | N | N177-00-1/451 | Tenancy - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15108 | ACTIVE | N | N177-00-1/451/CLG-01 | Ceiling: Suspended - 1 - Tenancy - Station Building - Morden Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access | | | | YES | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 12317 | ACTIVE | N | N177-00-1/576 | Stairs: Linear - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15109 | ACTIVE | N | N177-00-1/576 | Stairs: Linear - Station Building - Morden Stn | | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 12318 | ACTIVE | N | N177-00-1/577 | Stairs: Linear - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 19158 | ACTIVE | N | N177-00-1/577 | Stairs: Linear - Station Building - Morden Stn | | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 12319 | ACTIVE | N | N177-00-1/601 | Stairs: Linear - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15110 | ACTIVE | N | N177-00-1/601 | Stairs: Linear - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12320 | ACTIVE | N | N177-00-1/602 | Stairs: Linear - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15111 | ACTIVE | N | N177-00-1/602 | Stairs: Linear - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12321 | ACTIVE | N | N177-00-1/603 | Stairs: Linear - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15112 | ACTIVE | N | N177-00-1/603 | Stairs: Linear - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12322 | ACTIVE | N | N177-00-1/604 | Stairs: Linear - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19159 | ACTIVE | N | N177-00-1/604 | Stairs: Linear - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12323 | ACTIVE | N | N177-00-1/607 | Stairs: Linear - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15113 | ACTIVE | N | N177-00-1/607 | Stairs: Linear - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|-------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 15114 | ACTIVE | N | N177-00-1/607 | Stairs: Linear - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Support Steel and Hand Rail to Staircase | | | | | |
| 12324 | ACTIVE | N | N177-00-1/609 | Stairs: Linear - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18470 | ACTIVE | N | N177-00-1/609 | Stairs: Linear - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12325 | ACTIVE | N | N177-00-1/610 | Stairs: Linear - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15115 | INACTIVE | N | N177-00-1/610/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Above Metal, Glass / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 12326 | ACTIVE | N | N177-00-1/611 | Stairs: Linear - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19160 | ACTIVE | N | N177-00-1/611 | Stairs: Linear - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12327 | ACTIVE | N | N177-00-1/612 | Stairs: Linear - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15116 | ACTIVE | N | N177-00-1/612 | Stairs: Linear - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 15117 | ACTIVE | N | N177-00-1/636 | Overbridge - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 15118 | ACTIVE | N | N177-00-1/637 | Overbridge - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12328 | ACTIVE | N | N177-00-1/661 | Switch Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19161 | ACTIVE | N | N177-00-1/661/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Morden Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Insulation within Switch Boxes; 3 x 60 amps, & 1 x 100 amps No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 4 | | | |
| 15119 | ACTIVE | N | N177-00-1/661/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Morden Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Insulation within Switch Boxes; 1x 30 amps, & 1 x 60 amps No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 2 | | | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 12330 | ACTIVE | N | N177-00-1/663 | Switch Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15121 | ACTIVE | N | N177-00-1/663/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Morden Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Insulation within Switch Boxes; 2no 60amp 1no 100amp No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 3 | | | |
| 12332 | ACTIVE | N | N177-00-1/665 | Switch Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15123 | ACTIVE | N | N177-00-1/665/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Morden Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Insulation within Switch Boxes; 1no 60 & 200amp; 3no 100amp No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 5 | | | |
| 12333 | ACTIVE | N | N177-00-1/666 | Switch Cupboard - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 19162 | INACTIVE | N | N177-00-1/666/CLG-01 | Ceiling: Solid - 1 - Switch Cupboard - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Above Plasterboard / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 18575 | INACTIVE | N | N177-00-1/666/FLR-01 | Floor - 1 - Switch Cupboard - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | YES |
| 12334 | ACTIVE | N | N177-00-1/711 | Power Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15124 | ACTIVE | N | N177-00-1/711 | Power Room - Station Building - Morden Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 12335 | ACTIVE | N | N177-00-1/746 | Staff IT Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15125 | ACTIVE | N | N177-00-1/746 | Staff IT Room - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12336 | ACTIVE | N | N177-00-1/761 | Equipment Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 15126 | ACTIVE | N | N177-00-1/761/WAL-003 | Wall: Internal - 3 - Equipment Room - Station Building - Morden Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Insulation within Switch Boxes; 1no 60amp No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 12337 | ACTIVE | N | N177-00-1/801 | Office - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15127 | ACTIVE | N | N177-00-1/801/CLG-01 | Ceiling: Solid - 1 - Office - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Hardboard; Fibreglass Lagging above Acoustic Panels | | | | YES | |
| 12338 | ACTIVE | N | N177-00-1/802 | Office - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18545 | ACTIVE | N | N177-00-1/802/CLG-01 | Ceiling: Solid - 1 - Office - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Hardboard; Fibreglass Lagging - above Acoustic Panels | | | | YES | |
| 12339 | ACTIVE | N | N177-00-1/804 | Office - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15128 | ACTIVE | N | N177-00-1/804/CLG-01 | Ceiling: Solid - 1 - Office - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Hardboard; Fibreglass Lagging above Acoustic Panels | | | | YES | |
| 12340 | ACTIVE | N | N177-00-1/805 | Office - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19163 | ACTIVE | N | N177-00-1/805/CLG-01 | Ceiling: Solid - 1 - Office - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Hardboard; Fibreglass Lagging above Acoustic Panels | | | | YES | |
| 12344 | ACTIVE | N | N177-00-1/809 | Office - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15133 | ACTIVE | N | N177-00-1/809/CLG-01 | Ceiling: Solid - 1 - Office - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Concrete above Non Asbestos Ceiling Tiles | | | | | |
| 12345 | ACTIVE | N | N177-00-1/810 | Office - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15080 | INACTIVE | N | N177-00-1/810/CLG-01 | Ceiling: Solid - 1 - Office - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plasterboard above Polystyrene False Ceiling / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | YES | |
| 19164 | INACTIVE | N | N177-00-1/810/FLR-01 | Floor - 1 - Office - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | YES |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 12346 | ACTIVE | N | N177-00-1/811 | Office - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15081 | INACTIVE | N | N177-00-1/811/CLG-01 | Ceiling: Solid - 1 - Office - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plasterboard above Polystyrene False Ceiling / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | YES | |
| 19151 | ACTIVE | N | N177-00-1/811/FLR-01 | Floor - 1 - Office - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Metal False Floor | | | | | YES |
| 12347 | ACTIVE | N | N177-00-1/812 | Office - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15082 | INACTIVE | N | N177-00-1/812/CLG-01 | Ceiling: Solid - 1 - Office - Station Building - Morden Stn | Boarding: Supalux | Asbestos | Room: Asbestos Free | | | | Supalux Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15083 | INACTIVE | N | N177-00-1/812/CLG-01 | Ceiling: Solid - 1 - Office - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 12348 | ACTIVE | N | N177-00-1/813 | Office - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15084 | ACTIVE | N | N177-00-1/813 | Office - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12349 | ACTIVE | N | N177-00-1/814 | Playback Suite - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19152 | ACTIVE | N | N177-00-1/814/CLG-01 | Ceiling: Solid - 1 - Office - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | No Access through Hatch in ceiling | | | | YES | |
| 12350 | ACTIVE | N | N177-00-1/815 | Training Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15085 | ACTIVE | N | N177-00-1/815 | Training Room - Station Building - Morden Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 12351 | ACTIVE | N | N177-00-1/816 | Technical Support Office - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 15086 | ACTIVE | N | N177-00-1/816 | Technical Support Office - Station Building - Morden Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 12352 | ACTIVE | N | N177-00-1/861 | Equipment Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12353 | ACTIVE | N | N177-00-1/901 | Store - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15087 | ACTIVE | N | N177-00-1/901 | Store - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12354 | ACTIVE | N | N177-00-1/903 | Office - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15088 | ACTIVE | N | N177-00-1/903/CLG-01 | Ceiling: Solid - 1 - Office - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Hardboard above Acoustic Panels | | | | YES | |
| 12355 | ACTIVE | N | N177-00-1/904 | Kitchen - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15089 | ACTIVE | N | N177-00-1/904/CLG-01 | Ceiling: Solid - 1 - Kitchen - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Above Plasterboard | | | | | |
| 12356 | ACTIVE | N | N177-00-1/905 | Store - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19153 | ACTIVE | N | N177-00-1/905 | Store - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12357 | ACTIVE | N | N177-00-1/906 | Store - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15090 | ACTIVE | N | N177-00-1/906 | Store - Station Building - Morden Stn | No Access | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 12358 | ACTIVE | N | N177-00-1/907 | Store - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 12359 | ACTIVE | N | N177-00-1/908 | Store - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18542 | ACTIVE | N | N177-00-1/908/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Morden Stn | No Access | Asbestos | No Access: Presumed | | | | No Access above Plasterboard Ceiling | | | | YES | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 15091 | ACTIVE | N | N177-00-1/909 | Gantry - Station Building - Morden Stn | No Access | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 12360 | ACTIVE | N | N177-00-1/910 | Store - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15092 | ACTIVE | N | N177-00-1/910 | Store - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12361 | ACTIVE | N | N177-00-2/047 | Mess Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15094 | ACTIVE | N | N177-00-2/047 | Mess Room - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 15093 | ACTIVE | N | N177-00-2/047/FLR-01 | Floor - 1 - Mess Room - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | No Access beneath Lino, Wooden Floor; | | | | | YES |
| 19154 | ACTIVE | N | N177-00-2/047/FLR-01 | Floor - 1 - Mess Room - Station Building - Morden Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Tiles under Sink | | | | | |
| 12362 | ACTIVE | N | N177-00-2/081 | Lobby - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15095 | ACTIVE | N | N177-00-2/081/FLR-01 | Floor - 1 - Lobby - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | No Access beneath Lino, Wooden Floor | | | | | YES |
| 12363 | ACTIVE | N | N177-00-2/261 | Platform 1 - Southbound Local - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15096 | ACTIVE | N | N177-00-2/261 | Platform 1 - Southbound Local - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12364 | ACTIVE | N | N177-00-2/262 | Platform 2 - Southbound Local - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70415 | ACTIVE | N | N177-00-2/262 | Platform 2 - Southbound Local - Station Building - Morden Stn | Ducts | Asbestos | Sampled – Not Detected | | | | Platform Invert /Pit - Plastic/ concrete cable ducts - Throughout | | | R728751 | | |
| 15097 | ACTIVE | N | N177-00-2/262 | Platform 2 - Southbound Local - Station Building - Morden Stn | Pipe Lagging | Asbestos | Surveyed – Not Detected | | | | nr 2/662 & 2/731 | | | | | |
| 19155 | ACTIVE | N | N177-00-2/262 | Platform 2 - Southbound Local - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Girders below Stairs | | | | | |
| 12365 | ACTIVE | N | N177-00-2/263 | Platform 3 - Northbound Main - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70416 | ACTIVE | N | N177-00-2/263 | Platform 3 - Northbound Main - Station Building - Morden Stn | Ducts | Asbestos | Sampled – Not Detected | | | | Platform Invert / Pit - Plastic/ concrete cable ducts - Throughout | | | R728751 | | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|-----------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 18162 | ACTIVE | N | N177-00-2/263 | Platform 3 - Northbound Main - Station Building - Morden Stn | Pipe Lagging | Asbestos | Surveyed – Not Detected | | | | nr 2/662 | | | | | |
| 15098 | ACTIVE | N | N177-00-2/263 | Platform 3 - Northbound Main - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Girders below Stairs | | | | | |
| 12366 | ACTIVE | N | N177-00-2/264 | Platform 4 - Northbound Main - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15099 | ACTIVE | N | N177-00-2/264 | Platform 4 - Northbound Main - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 70417 | ACTIVE | N | N177-00-2/264 | Platform 4 - Northbound Main - Station Building - Morden Stn | Ducts | Asbestos | Sampled – Not Detected | | | | Platform Invert/Pit - Plastic/ concrete cable ducts - Throughout | | | R728752 | | |
| 15100 | ACTIVE | N | N177-00-2/264 | Platform 4 - Northbound Main - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Girders below Stairs | | | | | |
| 12367 | ACTIVE | N | N177-00-2/265 | Platform 5 - Northbound Local - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70418 | ACTIVE | N | N177-00-2/265 | Platform 5 - Northbound Local - Station Building - Morden Stn | Ducts | Asbestos | Sampled – Not Detected | | | | Platform Invert/Pit - Plastic/ concrete cable ducts - Throughout | | | R728752 | | |
| 18543 | ACTIVE | N | N177-00-2/265 | Platform 5 - Northbound Local - Station Building - Morden Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 50mm Cable on OTX from 2/666 to Trackside in cess 2x cables partially encapsulated Missing entry on overbridge presume materials within 1x Small westinghouse to wall of 1/636 by door to lobby 1/237 - Photo DSC5447 | | 2 | | | |
| 18574 | ACTIVE | N | N177-00-2/265 | Platform 5 - Northbound Local - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Girders below Stairs | | | | | |
| 12368 | ACTIVE | N | N177-00-2/331 | Mess Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15102 | ACTIVE | N | N177-00-2/331 | Mess Room - Station Building - Morden Stn | LUL Heaters | Asbestos | Surveyed – Not Detected | | | | Heater - Foam Insulation Board | | | | | |
| 15101 | ACTIVE | N | N177-00-2/331 | Mess Room - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 19156 | ACTIVE | N | N177-00-2/331/ FLR-01 | Floor - 1 - Mess Room - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Wooden False Floor | | | | | YES |
| 12369 | ACTIVE | N | N177-00-2/371 | Disused Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15103 | ACTIVE | N | N177-00-2/371 | Disused Room - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible; Recently Refurbished 2013/14; | | | | | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------------|--|---------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 44970 | ACTIVE | N | N177-00-2/371 | Disused Room - Station Building - Morden Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | External - 1x Westinghouse box (to wall by door 2/731) | | | | N | N |
| 44969 | ACTIVE | N | N177-00-2/371 | Disused Room - Station Building - Morden Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | External - 1x Small Westinghouse box (wall adjacent to track) | | | | N | N |
| 12370 | ACTIVE | N | N177-00-2/372 | Disused Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15104 | ACTIVE | N | N177-00-2/372 | Disused Room - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible; Recently Refurbished 2013/14; | | | | | |
| 15105 | ACTIVE | N | N177-00-2/372 | Disused Room - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | East Wall matt brown paint - encapsulated. Project have skimmed wall with plaster | | | | | |
| 12371 | ACTIVE | N | N177-00-2/373 | Mess Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19157 | ACTIVE | N | N177-00-2/373/ WAL-003 | Wall: Internal - 3 - Mess Room - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink | | | | | |
| 12372 | ACTIVE | N | N177-00-2/381 | Store - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15106 | ACTIVE | N | N177-00-2/381 | Store - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12373 | ACTIVE | N | N177-00-2/382 | Store - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15107 | ACTIVE | N | N177-00-2/382 | Store - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12374 | ACTIVE | N | N177-00-2/406 | Store - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18544 | ACTIVE | N | N177-00-2/406 | Store - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12375 | ACTIVE | N | N177-00-2/411 | Toilet: Unisex - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15208 | ACTIVE | N | N177-00-2/411/ FLR-01 | Floor - 1 - Toilet - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Lino, False Wooden Floor | | | | | YES |
| 12376 | ACTIVE | N | N177-00-2/412 | Store - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15209 | ACTIVE | N | N177-00-2/412 | Store - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 12377 | ACTIVE | N | N177-00-2/413 | Store - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15210 | ACTIVE | N | N177-00-2/413 | Store - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12378 | ACTIVE | N | N177-00-2/414 | Store - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15211 | ACTIVE | N | N177-00-2/414 | Store - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12379 | ACTIVE | N | N177-00-2/416 | Lobby - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17940 | ACTIVE | N | N177-00-2/416 | Lobby - Station Building - Morden Stn | Cable: Sheath | Asbestos | Presumed | | | | White Cables outside on walkway bridge / otx in cable run | | 2 | | | |
| 12380 | ACTIVE | N | N177-00-2/417 | Toilet: Unisex - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15213 | ACTIVE | N | N177-00-2/417/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Boarding/Plasterboard | | | | | |
| 15212 | ACTIVE | N | N177-00-2/417/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Morden Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | | | | | | |
| 12381 | ACTIVE | N | N177-00-2/418 | Toilet: Unisex - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15214 | ACTIVE | N | N177-00-2/418 | Toilet: Unisex - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12382 | ACTIVE | N | N177-00-2/451 | Switch Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17941 | ACTIVE | N | N177-00-2/451 | Switch Room - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12383 | ACTIVE | N | N177-00-2/661 | Switch Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15215 | ACTIVE | N | N177-00-2/661/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Morden Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|------------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 18554 | ACTIVE | N | N177-00-2/661/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Morden Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box(es) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 3 | | | |
| 12384 | ACTIVE | N | N177-00-2/662 | Switch Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15216 | ACTIVE | N | N177-00-2/662 | Switch Room - Station Building - Morden Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 3 | | | |
| 17942 | ACTIVE | N | N177-00-2/662 | Switch Room - Station Building - Morden Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer Box(es) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 15217 | ACTIVE | N | N177-00-2/662/CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Above Plasterboard Ceiling | | | | | |
| 12386 | ACTIVE | N | N177-00-2/666 | Switch Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18227 | ACTIVE | N | N177-00-2/666/CLG-01 | Ceiling: Solid - 1 - Switch Room - Station Building - Morden Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | White 50mmØ Cable to wall 1 and on ceiling above door through duct onto OTX then to Track | | | | | |
| 15223 | ACTIVE | N | N177-00-2/666/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Morden Stn | Cable Duct: Other | Asbestos | Strongly Presumed | | | | Cable Ducts 6no W1 & W3 | | 6 | | | |
| 15222 | ACTIVE | N | N177-00-2/666/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Morden Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes - Insulation within; 3 x 100 amps, 4 x 60 amps, 2 x 200 amps No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 9 | | | |
| 15224 | ACTIVE | N | N177-00-2/666/WAL-003 | Wall: Internal - 3 - Switch Room - Station Building - Morden Stn | Cable Duct: Other | Asbestos | Strongly Presumed | | | | Cable Ducts 6no W1 & W3 | | 6 | | | |
| 12387 | ACTIVE | N | N177-00-2/667 | Switch Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18555 | ACTIVE | N | N177-00-2/667 | Switch Room - Station Building - Morden Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |
| 12388 | ACTIVE | N | N177-00-2/706 | IMR - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|---------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 17944 | ACTIVE | N | N177-00-2/706 | IMR - Station Building - Morden Stn | Cable: Sheath | Asbestos | Presumed | | | | White Cables Presume 4x brown composite panels to rear of light reels to walls throughout - photo DSC05418 | | 4 | | | |
| 18578 | ACTIVE | N | N177-00-2/706/WAL-001 | Wall: Internal - 1 - IMR - Station Building - Morden Stn | Vinyl tiles | Asbestos | Presumed | | | | Grey Tiles - Above Head Height to walls throughout - some loose | | | | | |
| 19294 | ACTIVE | N | N177-00-2/706/WAL-001 | Wall: Internal - 1 - IMR - Station Building - Morden Stn | Vinyl tiles | Asbestos | Known | | | | Red Tiles to lower walls throughout some loose - Chrysotile | | | | | |
| 15226 | ACTIVE | N | N177-00-2/706/WAL-002 | Wall: Internal - 2 - IMR - Station Building - Morden Stn | Vinyl tiles | Asbestos | Presumed | | | | Grey Tiles - Above Head Height to upper wall - some loose | | | | | |
| 15225 | ACTIVE | N | N177-00-2/706/WAL-002 | Wall: Internal - 2 - IMR - Station Building - Morden Stn | Vinyl tiles | Asbestos | Known | | | | Red Tiles to lower wall throughout some loose - Chrysotile | | | | | |
| 12389 | ACTIVE | N | N177-00-2/731 | CER - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17945 | ACTIVE | N | N177-00-2/731/FLR-01 | Floor - 1 - CER - Station Building - Morden Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Floor Tiles | | | | | |
| 12390 | ACTIVE | N | N177-00-2/732 | CER - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15227 | ACTIVE | N | N177-00-2/732 | CER - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12391 | ACTIVE | N | N177-00-2/746 | SCR - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15228 | ACTIVE | N | N177-00-2/746 | SCR - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12392 | ACTIVE | N | N177-00-2/762 | Equipment Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15229 | ACTIVE | N | N177-00-2/762 | Equipment Room - Station Building - Morden Stn | Westing house Boxes | Asbestos | Strongly Presumed | | | | Small Westinhouse Box to external/rear of 2/762 (Trackside) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 18556 | ACTIVE | N | N177-00-2/762 | Equipment Room - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible; Recently Refurbished 2013/14; | | | | | |
| 44964 | ACTIVE | N | N177-00-2/771 | Pump Room - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Green & cream paint to walls | | | | N | N |
| 44963 | ACTIVE | N | N177-00-2/771/CLG-01 | Ceiling: Solid - 1 - Pump - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Cream paint to ceiling | | | | N | N |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|-----------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 12393 | ACTIVE | N | N177-00-2/951 | Disused Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15230 | ACTIVE | N | N177-00-2/951 | Disused Room - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible; Recently Refurbished 2013/14; | | | | | |
| 15231 | ACTIVE | N | N177-00-2/951 | Disused Room - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | East wall matt brown paint - encapsulated. Project have skimmed wall with plaster | | | | | |
| 12394 | ACTIVE | N | N177-00-A/081 | Lobby - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 18009 | INACTIVE | N | N177-00-A/081/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plasterboard Tiles above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | YES | |
| 15232 | INACTIVE | N | N177-00-A/081/FLR-01 | Floor - 1 - Lobby - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | YES |
| 12395 | ACTIVE | N | N177-00-A/082 | Lobby - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15234 | INACTIVE | N | N177-00-A/082/CLG-01 | Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plasterboard Tiles above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | YES | |
| 15233 | INACTIVE | N | N177-00-A/082/FLR-01 | Floor - 1 - Lobby - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | YES |
| 12396 | ACTIVE | N | N177-00-A/083 | Lobby - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12397 | ACTIVE | N | N177-00-A/084 | Lobby - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12398 | ACTIVE | N | N177-00-A/085 | Lobby - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 12399 | ACTIVE | N | N177-00-A/086 | Lobby - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12400 | ACTIVE | N | N177-00-A/087 | Lobby - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12401 | ACTIVE | N | N177-00-A/236 | Passage - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15236 | INACTIVE | N | N177-00-A/236/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plasterboard Tiles above Polystyrene Tiles /This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | YES | |
| 15235 | INACTIVE | N | N177-00-A/236/FLR-01 | Floor - 1 - Passage - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | YES |
| 12402 | ACTIVE | N | N177-00-A/237 | Passage - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15237 | INACTIVE | N | N177-00-A/237/CLG-01 | Ceiling: Solid - 1 - Passage - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 12403 | ACTIVE | N | N177-00-A/316 | Locker Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15238 | INACTIVE | N | N177-00-A/316/CLG-01 | Ceiling: Solid - 1 - Locker Room - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plasterboard Tiles above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | YES | |
| 18010 | INACTIVE | N | N177-00-A/316/FLR-01 | Floor - 1 - Locker Room - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | YES |
| 12404 | ACTIVE | N | N177-00-A/317 | Locker Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 12405 | ACTIVE | N | N177-00-A/318 | Locker Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12406 | ACTIVE | N | N177-00-A/319 | Locker Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12407 | ACTIVE | N | N177-00-A/331 | Mess Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15240 | INACTIVE | N | N177-00-A/331/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plasterboard above Plasterboard False Ceiling / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | YES | |
| 15239 | INACTIVE | N | N177-00-A/331/FLR-01 | Floor - 1 - Mess Room - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | YES |
| 12408 | ACTIVE | N | N177-00-A/332 | Mess Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 18011 | INACTIVE | N | N177-00-A/332 | Mess Room - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | Acoustic Panel below sink / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15242 | INACTIVE | N | N177-00-A/332/CLG-01 | Ceiling: Solid - 1 - Mess Room - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plasterboard above Plasterboard False Ceiling / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | YES | |
| 15241 | INACTIVE | N | N177-00-A/332/FLR-01 | Floor - 1 - Mess Room - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | YES |
| 12409 | ACTIVE | N | N177-00-A/406 | Store - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|-----------------|---------------|-------------------------|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 15243 | INACTIVE | N | N177-00-A/406/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Above Fibreboard Ceiling / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 18473 | INACTIVE | N | N177-00-A/406/FLR-01 | Floor - 1 - Store - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Rubber Flooring / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | YES |
| 12410 | ACTIVE | N | N177-00-A/411 | Store - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 18012 | INACTIVE | N | N177-00-A/411/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Above Fibreboard Ceiling / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15244 | INACTIVE | N | N177-00-A/411/FLR-01 | Floor - 1 - Store - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Rubber Flooring / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | YES |
| 12411 | ACTIVE | N | N177-00-A/412 | Store - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15245 | INACTIVE | N | N177-00-A/412/CLG-01 | Ceiling: Solid - 1 - Store - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 12412 | ACTIVE | N | N177-00-A/416 | Toilet: Female - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 18167 | INACTIVE | N | N177-00-A/416/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plasterboard Tiles above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | YES | |
| 18579 | INACTIVE | N | N177-00-A/416/FLR-01 | Floor - 1 - Toilet - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | YES |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 12413 | ACTIVE | N | N177-00-A/417 | Shower Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15247 | INACTIVE | N | N177-00-A/417/CLG-01 | Ceiling: Solid - 1 - Shower Room - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plasterboard Tiles above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | YES | |
| 15246 | INACTIVE | N | N177-00-A/417/FLR-01 | Floor - 1 - Shower Room - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | YES |
| 12414 | ACTIVE | N | N177-00-A/418 | Toilet: Male - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 18013 | INACTIVE | N | N177-00-A/418/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plasterboard Tiles above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | YES | |
| 15248 | INACTIVE | N | N177-00-A/418/FLR-01 | Floor - 1 - Toilet - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | YES |
| 12415 | ACTIVE | N | N177-00-A/419 | Toilet: Female - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15249 | INACTIVE | N | N177-00-A/419/CLG-01 | Ceiling: Solid - 1 - Toilet - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plasterboard Tiles above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | YES | |
| 18557 | INACTIVE | N | N177-00-A/419/FLR-01 | Floor - 1 - Toilet - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | YES |
| 12416 | ACTIVE | N | N177-00-A/420 | Toilet: Male - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 12417 | ACTIVE | N | N177-00-A/421 | Shower Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12418 | ACTIVE | N | N177-00-A/422 | Shower Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12419 | ACTIVE | N | N177-00-A/423 | Shower Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12420 | ACTIVE | N | N177-00-A/424 | Shower Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12421 | ACTIVE | N | N177-00-A/425 | Shower Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12422 | ACTIVE | N | N177-00-A/576 | Stairs: Linear - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15251 | INACTIVE | N | N177-00-A/576/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Above Fibreboard Ceiling / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 18014 | INACTIVE | N | N177-00-A/576/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Above Fibreboard Ceiling / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15250 | INACTIVE | N | N177-00-A/576/FLR-01 | Floor - 1 - Linear Stairs - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Rubber Flooring / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | YES |
| 12423 | ACTIVE | N | N177-00-A/661 | Switch Cupboard - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15252 | INACTIVE | N | N177-00-A/661/FLR-01 | Floor - 1 - Switch Cupboard - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Rubber Flooring / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | YES |
| 12424 | ACTIVE | N | N177-00-A/761 | Equipment Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 15253 | INACTIVE | N | N177-00-A/761/CLG-01 | Ceiling: Solid - 1 - Equipment Room - Station Building - Morden Stn | Boarding: Supalux | Asbestos | Surveyed – Not Detected | | | | Ceiling Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15254 | INACTIVE | N | N177-00-A/761/CLG-01 | Ceiling: Solid - 1 - Equipment Room - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 12425 | ACTIVE | N | N177-00-A/801 | Office - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 18168 | INACTIVE | N | N177-00-A/801/CLG-01 | Ceiling: Solid - 1 - Office - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 12426 | ACTIVE | N | N177-00-A/802 | Office - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 18015 | INACTIVE | N | N177-00-A/802/CLG-01 | Ceiling: Solid - 1 - Office - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plasterboard Tiles above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | YES | |
| 18580 | INACTIVE | N | N177-00-A/802/FLR-01 | Floor - 1 - Office - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | YES |
| 12427 | ACTIVE | N | N177-00-A/803 | Office - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15255 | INACTIVE | N | N177-00-A/803/CLG-01 | Ceiling: Solid - 1 - Office - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plasterboard Tiles above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | YES | |
| 12428 | ACTIVE | N | N177-00-A/901 | Store - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|--|-----------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 12429 | ACTIVE | N | N177-00-A/902 | Store - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12430 | ACTIVE | N | N177-00-A/903 | Store - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12431 | ACTIVE | N | N177-00-A/904 | Store - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12432 | ACTIVE | N | N177-00-A/905 | Shower Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12433 | ACTIVE | N | N177-00-B/576 | Stairs: Linear - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | |
| 15256 | INACTIVE | N | N177-00-B/576/CLG-01 | Ceiling: Solid - 1 - Linear Stairs - Station Building - Morden Stn | Void | Asbestos | Surveyed – Not Detected | | | | Plasterboard Tiles above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | YES | |
| 18558 | INACTIVE | N | N177-00-B/576/FLR-01 | Floor - 1 - Linear Stairs - Station Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free | | | | | YES |
| 12434 | ACTIVE | N | N177-00-B/776 | Plant Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 43402 | ACTIVE | N | N177-00/ROF-01 | Structure: Roof - 1 - Station Building - Morden Stn | | Asbestos | Sampled – Not Detected | | | | Asphalt on concrete slab 60m2 to roof | | | R559476 | | |
| 43405 | ACTIVE | N | N177-00/ROF-01 | Structure: Roof - 1 - Station Building - Morden Stn | | Asbestos | Sampled – Not Detected | | | | Plastic cables, metal conduits and cable management system and fire stop and mastic - new throughout | | | 559476 | | |
| 43403 | ACTIVE | N | N177-00/ROF-01 | Structure: Roof - 1 - Station Building - Morden Stn | | Asbestos | Sampled – Not Detected | | | | Fibre glass water tank - with MMMF to roof | | | R559476 | | |
| 43404 | ACTIVE | N | N177-00/ROF-01 | Structure: Roof - 1 - Station Building - Morden Stn | | Asbestos | Sampled – Not Detected | | | | Roof 1 - Brickwork to walls | | | R559476 | | |
| 15134 | ACTIVE | N | N177-00/ROF-01 | Structure: Roof - 1 - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Painted structural beams supporting the roof | | | | | |
| 43406 | ACTIVE | N | N177-00/ROF-02 | Structure: Roof - 2 - Station Building - Morden Stn | Bitumen | Asbestos | Sampled – Not Detected | | | | Bitumen on concrete 30m2 to sides and under paving slab to roof | 30 | | R559476 | | |
| 43409 | ACTIVE | N | N177-00/ROF-02 | Structure: Roof - 2 - Station Building - Morden Stn | Ducts | Asbestos | Sampled – Not Detected | | | | A/C Ductwork - new with MMMF insulation throughout | | | R559476 | | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|------------------|-----------------|------------------------|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 43411 | ACTIVE | N | N177-00/ROF-02 | Structure: Roof - 2 - Station Building - Morden Stn | | Asbestos | Sampled – Not Detected | | | | Plastic and metal pipework - MMMF /foam insulation throughout | | | R559476 | | |
| 43407 | ACTIVE | N | N177-00/ROF-02 | Structure: Roof - 2 - Station Building - Morden Stn | | Asbestos | Sampled – Not Detected | | | | Roof 2 - Brickwork to walls | | | R559476 | | |
| 43410 | ACTIVE | N | N177-00/ROF-02 | Structure: Roof - 2 - Station Building - Morden Stn | Mastic | Asbestos | Sampled – Not Detected | | | | Plastic cables, metal conduits and cable management system and firestop and mastic - new throughout | | | R559476 | | |
| 43408 | ACTIVE | N | N177-00/ROF-02 | Structure: Roof - 2 - Station Building - Morden Stn | Bitumen | Asbestos | Sampled – Not Detected | | | | Stone slab on foam on bitumen on concrete to floor | | | R559476 | | |
| 15135 | ACTIVE | N | N177-00/ROF-02 | Structure: Roof - 2 - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Painted structural beams supporting the roof | | | | | |
| 43412 | ACTIVE | N | N177-00/ROF-03 | Structure: Roof - 3 - Station Building - Morden Stn | | Asbestos | Sampled – Not Detected | | | | Asphalt on concrete 20m2 to floor | | | R559476 | | |
| 43413 | ACTIVE | N | N177-00/ROF-03 | Structure: Roof - 3 - Station Building - Morden Stn | | Asbestos | Sampled – Not Detected | | | | Brickwork to walls | | | R559476 | | |
| 43416 | ACTIVE | N | N177-00/ROF-03 | Structure: Roof - 3 - Station Building - Morden Stn | | Asbestos | Sampled – Not Detected | | | | Plastic cables, metal conduits and cable management system and firestop and mastic - new throughout | | | R559476 | | |
| 43414 | ACTIVE | N | N177-00/ROF-03 | Structure: Roof - 3 - Station Building - Morden Stn | | Asbestos | Sampled – Not Detected | | | | Wood door and framework to walls | | | R559476 | | |
| 43415 | ACTIVE | N | N177-00/ROF-03 | Structure: Roof - 3 - Station Building - Morden Stn | | Asbestos | Sampled – Not Detected | | | | Wooden fascia board to edge of roof 1 side | | | R559476 | | |
| 18546 | ACTIVE | N | N177-00/ROF-03 | Structure: Roof - 3 - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Painted structural beams supporting the roof | | | | | |
| 18226 | ACTIVE | N | N177-00/ROF-04 | Structure: Roof - 4 - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Painted structural beams supporting the roof | | | | | |
| 43399 | ACTIVE | N | N177-00/ROF-05 | Structure: Roof - 5 - Station Building - Morden Stn | | Asbestos | Sampled – Not Detected | | | | New skylight - plastic to roof | | | R559476 | | |
| 43400 | ACTIVE | N | N177-00/ROF-05 | Structure: Roof - 5 - Station Building - Morden Stn | | Asbestos | Sampled – Not Detected | | | | Brickwork to walls | | | R559476 | | |
| 43401 | ACTIVE | N | N177-00/ROF-05 | Structure: Roof - 5 - Station Building - Morden Stn | Mastic | Asbestos | Sampled – Not Detected | | | | Plastic cables, metal conduits and cable management system and fire stop and mastic - new throughout | | | R559476 | | |
| 15136 | ACTIVE | N | N177-00/ROF-05 | Structure: Roof - 5 - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Painted structural beams supporting the roof | | | | | |
| 43421 | ACTIVE | N | N177-00/ROF-06 | Structure: Roof - 6 - Station Building - Morden Stn | Boarding: Cement | Asbestos | Presumed | | | | Roof 6 - Cement Panel fascia boards to side of roof Undercloaking to sides of roof not panels to skylghts as per previous report. | | | R559476 | | |
| 43565 | ACTIVE | N | N177-00/ROF-06 | Structure: Roof - 6 - Station Building - Morden Stn | | Asbestos | Sampled – Not Detected | | | | Cement pipe/duct to roof 6 location 9 on photo | | | R564776 | N | N |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------|---|------------------|-----------------|-------------------------|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 43391 | ACTIVE | N | N177-00/ROF-06 | Structure: Roof - 6 - Station Building - Morden Stn | | Asbestos | Sampled – Not Detected | | | | Asphalt on wood 140m2 to roof - south side | 140 | | R559476 | | |
| 43387 | ACTIVE | N | N177-00/ROF-06 | Structure: Roof - 6 - Station Building - Morden Stn | Bitumen | Asbestos | Sampled – Not Detected | | | | White Roof tile 10no on top of bitumen roof felt where edge protection guards area | | | R559476 | | |
| 43390 | ACTIVE | N | N177-00/ROF-06 | Structure: Roof - 6 - Station Building - Morden Stn | | Asbestos | Sampled – Not Detected | | | | Fibre glass water tanks - with MMMF insulation 3no to roof | | | R559476 | | |
| 43388 | ACTIVE | N | N177-00/ROF-06 | Structure: Roof - 6 - Station Building - Morden Stn | Boarding: Cement | Asbestos | Removed | | | | Cement panel 2 no2m to either sides of skylight (above entrance lobby) Replaced with new supalux material recently | 2 | | R559476 | Y | N |
| 43386 | ACTIVE | N | N177-00/ROF-06 | Structure: Roof - 6 - Station Building - Morden Stn | Glazing Rope | Asbestos | Presumed | | | | Rope 3 bars Within glazing bar to skylight. No access to sample without risking smashing glass. To be inspected when glazing removed | | | R559476 | | |
| Y | INACTIVE | N | N177-00/ROF-06 | Structure: Roof - 6 - Station Building - Morden Stn | Cement Troughing | Asbestos | Known | | | | Cement Panel 2 no 2m to either sides of Skylight (above entrance lobby) | 2 | | R559476 | Y | N |
| 43389 | ACTIVE | N | N177-00/ROF-06 | Structure: Roof - 6 - Station Building - Morden Stn | Pipe Lagging | Asbestos | Sampled – Not Detected | | | | Plastic and metal pipework - some with MMMF/ foam insulation throughout | | | R559476 | Y | N |
| 19165 | ACTIVE | N | N177-00/ROF-06 | Structure: Roof - 6 - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Painted structural beams supporting the roof | | | | | |
| 43639 | ACTIVE | N | N177-00/ROF-07 | Structure: Roof - 7 - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | Slate roof tiles throughout to roof 7 | | | R564776 | N | N |
| 43564 | ACTIVE | N | N177-00/ROF-07 | Structure: Roof - 7 - Station Building - Morden Stn | Roofing Tiles | Asbestos | Sampled – Not Detected | | | | Slate roof tiles, throughout to roof 7, location 1 to 8 on photo | | | R564776 | N | N |
| 43396 | ACTIVE | N | N177-00/ROF-07 | Structure: Roof - 7 - Station Building - Morden Stn | | Asbestos | Sampled – Not Detected | | | | Asphalt on brickwork 40m to side of roof (east) | 40 | | R559476 | | |
| 43393 | ACTIVE | N | N177-00/ROF-07 | Structure: Roof - 7 - Station Building - Morden Stn | Roofing Tiles | Asbestos | Known | | | | Ridge tiles on top of rubber 40m to centre of pitched roof | | | R559476 | | |
| 43398 | ACTIVE | N | N177-00/ROF-07 | Structure: Roof - 7 - Station Building - Morden Stn | | Asbestos | Sampled – Not Detected | | | | Brickwork to sides | | | R559476 | | |
| 43397 | ACTIVE | N | N177-00/ROF-07 | Structure: Roof - 7 - Station Building - Morden Stn | Roofing Tiles | Asbestos | Sampled – Not Detected | | | | Roof tiles on wood 180m2 under roof tiles | 180 | | R559476 | | |
| 43395 | ACTIVE | N | N177-00/ROF-07 | Structure: Roof - 7 - Station Building - Morden Stn | Boarding: Cement | Asbestos | Known | | | | Cement panels on top of wood 1 no 4m2 to lighting post to top of roof Damaged to bottom panel missing corner section | | | R559476 | | |
| 43394 | ACTIVE | N | N177-00/ROF-07 | Structure: Roof - 7 - Station Building - Morden Stn | Roofing Tiles | Asbestos | Sampled – Not Detected | | | | Cement under cloaking 12m to edge under roof tile | | | R559476 | | |
| 43392 | ACTIVE | N | N177-00/ROF-07 | Structure: Roof - 7 - Station Building - Morden Stn | Roofing Tiles | Asbestos | Sampled – Not Detected | | | | Roof tile 180m2 to pitched roof | 180 | | R559476 | | |



Hazardous Material Asset Register - Summary



N177-00 - Station Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-------------------------------|---|------------------------|--------------------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 15137 | ACTIVE | N | N177-00/ROF-07 | Structure: Roof - 7 - Station Building - Morden Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Painted structural beams supporting the roof | | | | | |
| 12385 | ACTIVE | N | N177-03-2/664 | Switch Room - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17943 | ACTIVE | N | N177-03-2/664/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Morden Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes - Insulation within 100amp No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 1 | | | |
| 15218 | ACTIVE | N | N177-03-2/664/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Morden Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline Boarding various locations | | | | | |
| 15221 | INACTIVE | N | N177-03-2/664/WAL-001 | Wall: Internal - 1 - Switch Room - Station Building - Morden Stn | PCBs | Polychlorinated biphenyl | Strongly Presumed | | | | 10 x PCB's - fair Condition - serial numbers197448, 197441, 186348, 186597, 38555, 168264, 197409, 36908, 186603, 186551.165254, 30905 1 x black cyclinder, 1 x medium silver cyclinder, 2 x small silver cyclinder, 3 x blue cyclinder PCB's - wall mounted | | 17 | | N | N |
| 15219 | ACTIVE | N | N177-03-2/664/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Morden Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline Boarding various locations | | | | | |
| 15220 | ACTIVE | N | N177-03-2/664/WAL-002 | Wall: Internal - 2 - Switch Room - Station Building - Morden Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Westinghouse Boxes - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within. | | 3 | | | |
| 15079 | ACTIVE | N | N177-05-1/447 | Bicycle Shed - Signals Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 12329 | ACTIVE | N | N177-07-1/662 | Switch Cupboard - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19543 | ACTIVE | N | N177-07-1/662/FLR-01 80886386 | Floor - 1 - Switch Cupboard - Station Building - Morden Stn Floor | Cable Ducts: Cement | Asbestos | Presumed | | | | Cable Ducts Cement | | | | | |
| 15120 | ACTIVE | N | N177-07-1/662/FLR-01 | Floor - 1 - Switch Cupboard - Station Building - Morden Stn | Cable: Sheath | Asbestos | Presumed | | | | Mains Cable | | 1 | | | |
| 12331 | ACTIVE | N | N177-07-1/664 | Switch Cupboard - Station Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15122 | ACTIVE | N | N177-07-1/664 | Switch Cupboard - Station Building - Morden Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



X132-01 - ERU - Camden Town

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---------------------------------|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 14865 | ACTIVE | N | X132-01-1/317 | Workshop - ERU - Camden Town | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14866 | ACTIVE | N | X132-01-1/661 | Switch Room - ERU - Camden Town | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14867 | ACTIVE | N | X132-01-1/801 | Office - ERU - Camden Town | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14868 | ACTIVE | N | X132-01-A/047 | Mess Room - ERU - Camden Town | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14869 | ACTIVE | N | X132-01-A/331 | Mess Room - ERU - Camden Town | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N021-01 - Signal Cabin - Edgware Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------|---|-----------------|---------------|------------------------------------|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 8322 | ACTIVE | N | N021-01-0/576 | Stairs: Linear - Signal Cabin - Edgware Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | | | | | | |
| 8323 | ACTIVE | N | N021-01-0/577 | Stairs: Linear - Signal Cabin - Edgware Stn | Stations: Rooms | Asbestos | Room: Asbestos Free | | | | | | | | | |
| 8324 | ACTIVE | N | N021-01-0/706 | IMR - Signal Cabin - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Presumed | | | | | | | | | |
| 25841 | ACTIVE | N | N021-01-0/706 | IMR - Signal Cabin - Edgware Stn | Other Boarding | Asbestos | Presumed | | | | Paxoline board | | | | | |
| 25839 | ACTIVE | N | N021-01-0/706 | IMR - Signal Cabin - Edgware Stn | Vinyl tiles | Asbestos | Presumed | | | | Green / Grey Vinyl tiles on Walls & Ceilings | | | | | |
| 8325 | ACTIVE | N | N021-01-0/707 | IMR - Signal Cabin - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Presumed | | | | | | | | | |
| 8326 | ACTIVE | N | N021-01-0/951 | Disused Room - Signal Cabin - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Presumed | | | | | | | | | |
| 25840 | ACTIVE | N | N021-01-0/951 | Disused Room - Signal Cabin - Edgware Stn | Vinyl tiles | Asbestos | Presumed | | | | Green / Grey Vinyl tiles on Walls & Ceilings | | | | | |
| 8240 | ACTIVE | N | N021-01-1/083 | Lobby - Signal Cabin - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19840 | INACTIVE | N | N021-01-1/083 | Lobby - Signal Cabin - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N021-01 - Signal Cabin - Edgware Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|------------------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 44859 | ACTIVE | N | N021-01-1/083/WAL-001 | Wall: Internal - 1 - Lobby - Signal Cabin - Edgware Stn | Cable: Sheath | Asbestos | Presumed | | | | Black Braided Cable to window wall 1, 1st window | 2 | 1 | | N | N |
| 19676 | ACTIVE | N | N021-01-1/083/WDW-01 | Window - 1 - Lobby - Signal Cabin - Edgware Stn | Lead/Leading | Lead Paint/Lead | Strongly Presumed | | | | Lead Paint on Crittle Windows | | | | | |
| 19432 | ACTIVE | N | N021-01-1/083/WDW-02 | Window - 2 - Lobby - Signal Cabin - Edgware Stn | Lead/Leading | Lead Paint/Lead | Strongly Presumed | | | | Lead Paint on Crittle Windows | | | | | |
| 8255 | ACTIVE | N | N021-01-1/366 | Mess Room - Signal Cabin - Edgware Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19904 | INACTIVE | N | N021-01-1/366 | Mess Room - Signal Cabin - Edgware Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Room | | | | | |
| 19913 | ACTIVE | N | N021-01-1/366/WAL-002 | Wall: Internal - 2 - Mess Room - Signal Cabin - Edgware Stn | Bitumen | Asbestos | Sampled – Not Detected | | | | Acoustic Panel below sink - Sampled as part of management survey R643426 - 2019 | | 1 | | | |
| 8268 | ACTIVE | N | N021-01-1/419 | Toilet: Unisex - Signal Cabin - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Presumed | | | | | | | | | |
| 19449 | ACTIVE | N | N021-01-1/419 | Toilet: Unisex - Signal Cabin - Edgware Stn | Cement Cowlings/ Flues | Asbestos | Removed | | | | Flues - to disused cooker hoods | | | | | |
| 19912 | ACTIVE | N | N021-01-1/419 | Toilet: Unisex - Signal Cabin - Edgware Stn | Lead/Leading | Lead Paint/Lead | Strongly Presumed | | | | Lead Paint on Crittle Windows | | | | | |
| 8277 | ACTIVE | N | N021-01-1/708 | IMR - Signal Cabin - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Presumed | | | | | | | | | |
| 25842 | ACTIVE | N | N021-01-1/708 | IMR - Signal Cabin - Edgware Stn | Other Electrical Boxes | Asbestos | Presumed | | | | Transformer box - Insulation within | | 1 | | | |
| 25843 | ACTIVE | N | N021-01-1/708 | IMR - Signal Cabin - Edgware Stn | Vinyl tiles | Asbestos | Presumed | | | | Green / Grey Vinyl tiles on Walls & Ceilings | | | | | |
| 44869 | ACTIVE | N | N021-01-1/708 | IMR - Signal Cabin - Edgware Stn | Bitumen | Asbestos | Strongly Presumed | | | | Adhesive to Green & Grey tiles on Walls | | | | N | N |
| 19920 | INACTIVE | N | N021-01-1/708 | IMR - Signal Cabin - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |
| 44874 | ACTIVE | N | N021-01-1/708 | IMR - Signal Cabin - Edgware Stn | Cable Wrap | Asbestos | Presumed | | | | Green Braided Cable throughout to wall high level and framework | | | | | |
| 44872 | ACTIVE | N | N021-01-1/708/WAL-001 | Wall: Internal - 1 - IMR - Signal Cabin - Edgware Stn | Rope Gaskets | Asbestos | Strongly Presumed | | | | 2x Gaskets to metal tube electric heater | | 2 | | N | N |
| 44870 | ACTIVE | N | N021-01-1/708/WAL-001 | Wall: Internal - 1 - IMR - Signal Cabin - Edgware Stn | | Asbestos | Strongly Presumed | | | | Brown Composite Panel and Packing | | | | N | N |
| 44871 | ACTIVE | N | N021-01-1/708/WAL-003 | Wall: Internal - 3 - IMR - Signal Cabin - Edgware Stn | | Asbestos | Strongly Presumed | | | | Brown Composite Panel and Packing | | | | N | N |
| 44873 | ACTIVE | N | N021-01-1/708/WAL-006 | Wall: Internal - 6 - IMR - Signal Cabin - Edgware Stn | Rope Gaskets | Asbestos | Strongly Presumed | | | | 2x Gaskets to metal tube electric heater | | 2 | | N | N |



Hazardous Material Asset Register - Summary



N021-01 - Signal Cabin - Edgware Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 8286 | ACTIVE | N | N021-01-2/047 | Kitchen - Signal Cabin - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19969 | ACTIVE | N | N021-01-2/047/CLG-01 | Ceiling: Suspended - 1 - Kitchen - Signal Cabin - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 19970 | ACTIVE | N | N021-01-2/047/CLG-01 | Ceiling: Suspended - 1 - Kitchen - Signal Cabin - Edgware Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux | | | | YES | |
| 44875 | ACTIVE | N | N021-01-2/047/FLR-01 | Floor - 1 - Kitchen - Station Building - Edgware Stn | Vinyl tiles | Asbestos | Known | | | | Vinyl Tiles to floor | | | | N | N |
| 44876 | ACTIVE | N | N021-01-2/047/FLR-01 | Floor - 1 - Kitchen - Station Building - Edgware Stn | Bitumen | Asbestos | Known | | | | Adhesive to floor under tile | | | | N | N |
| 8298 | ACTIVE | N | N021-01-2/332 | Store - Signal Cabin - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Strongly Presumed | | | | | | | | | |
| 19982 | ACTIVE | N | N021-01-2/332/DOR-01 | Door - 1 - Store - Signal Cabin - Edgware Stn | Boarding: Cement | Asbestos | Removed | | | | Cement Panel above disused doorway under stairs 2/576 leading to 2/333. Removed by the Licensed Asbestos Removal Contractor EMS | | | | | |
| 8299 | ACTIVE | N | N021-01-2/333 | Mess Room - Signal Cabin - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Presumed | | | | | | | | | |
| 19981 | ACTIVE | N | N021-01-2/333/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Signal Cabin - Edgware Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Supalux | | | | | |
| 19507 | ACTIVE | N | N021-01-2/333/CLG-01 | Ceiling: Suspended - 1 - Mess Room - Signal Cabin - Edgware Stn | Void | Asbestos | No Access: Presumed | | | | Above Supalux | | | | YES | |
| 44868 | ACTIVE | N | N021-01-2/333/FLR-01 | Floor - 1 - Mess Room - Signal Cabin - Edgware Stn | Bitumen | Asbestos | Known | | | | Adhesive to floor under tile | | | | N | N |
| 44867 | ACTIVE | N | N021-01-2/333/FLR-01 | Floor - 1 - Mess Room - Signal Cabin - Edgware Stn | Vinyl tiles | Asbestos | Known | | | | Vinyl Tiles to floor | | | | N | N |
| 8306 | ACTIVE | N | N021-01-2/576 | Stairs: Linear - Signal Cabin - Edgware Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 19988 | INACTIVE | N | N021-01-2/576 | Stairs: Linear - Signal Cabin - Edgware Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |



Hazardous Material Asset Register - Summary



N022-01 - Disused Room - Disused Building - Edgware To Burnt Oak

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---------------------|-------------|------------|-------------|---------------------|-------------------|
| 8327 | ACTIVE | N | N022-01-0/952 | Disused Room - Disused Building - Edgware To Burnt Oak | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20052 | ACTIVE | N | N022-01-0/952 | Disused Room - Disused Building - Edgware To Burnt Oak | | Asbestos | Surveyed – Not Detected | | | | No Asbestos Visible | | | | | |

N022-02 - Signals Building - Edgware To Burnt Oak

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 8328 | ACTIVE | N | N022-02-0/661 | Switch Room - Signals Building - Edgware To Burnt Oak | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8329 | ACTIVE | N | N022-02-0/711 | SER - Signals Building - Edgware To Burnt Oak | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20051 | ACTIVE | N | N022-02-0/711 | SER - Signals Building - Edgware To Burnt Oak | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - deemed to be Asbestos free | | | | | |

N022-03 - P Way Accommodation - Edgware To Burnt Oak

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 8330 | ACTIVE | N | N022-03-0/081 | Lobby - P Way Accommodation - Edgware To Burnt Oak | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8331 | ACTIVE | N | N022-03-0/416 | Toilet: Unisex - P Way Accommodation - Edgware To Burnt Oak | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8332 | ACTIVE | N | N022-03-0/701 | Equipment Room - P Way Accommodation - Edgware To Burnt Oak | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N022-05 - Traction Control Cabin - Edgware To Burnt Oak

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 8334 | ACTIVE | N | N022-05-0/661 | Equipment Room - Traction Control Cabin - Edgware To Burnt Oak | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N023-01 - Signals Building - Burnt Oak Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 8367 | ACTIVE | N | N023-01-0/711 | SER - Signals Building - Burnt Oak Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N025-01 - Signals Building - Colindale Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 8400 | ACTIVE | N | N025-01-1/731 | CER - Signals Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N025-02 - Signals Building - Colindale Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 8401 | ACTIVE | N | N025-02-1/711 | SER - Signals Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N025-03 - Signals Building - Colindale Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 8402 | ACTIVE | N | N025-03-2/706 | IMR - Signals Building - Colindale Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19709 | ACTIVE | N | N025-03-2/706 | IMR - Signals Building - Colindale Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | 4x 35mm Cables within J hanger to wall 3 leading outside to Track | | 4 | | | |
| 19708 | ACTIVE | N | N025-03-2/706 | IMR - Signals Building - Colindale Stn | Cable: Sheath | Asbestos | Strongly Presumed | | | | Cables - External to IMR - Encapsulated | | 2 | | | |

N031-01 - Signals Building - Hendon Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------------------------|-------------|------------|-------------|---------------------|-------------------|
| 8473 | ACTIVE | N | N031-01-0/711 | SER - Signals Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19615 | ACTIVE | N | N031-01-0/711 | SER - Signals Building - Hendon Central Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Room | | | | | |



Hazardous Material Asset Register - Summary



N031-02 - Signals Building - Hendon Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 8474 | ACTIVE | N | N031-02-2/706 | IMR - Signals Building - Hendon Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N032-01 - Store - Hendon Central To Brent Cross

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 8476 | ACTIVE | N | N032-01-0/411 | Store Room - Store - Hendon Central To Brent Cross | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N033-01 - Signals Building - Brent Cross Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 8509 | ACTIVE | N | N033-01-1/711 | SER - Signals Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N033-02 - Signals Building - Brent Cross Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 8510 | ACTIVE | N | N033-02-0/732 | CER - Signals Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N033-03 - Signals Building - Brent Cross Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|------------------------------------|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 8511 | ACTIVE | N | N033-03-0/731 | CER - Signals Building - Brent Cross Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 17880 | ACTIVE | N | N033-03-0/731 | CER - Signals Building - Brent Cross Stn | No Access | Asbestos | Surveyed – Not Detected | | | | CER near the platforms was constructed Post 2000 and considered asbestos free | | | | | |

N041-01 - Signals Building - Golders Green Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 8626 | ACTIVE | N | N041-01-0/711 | SER - Signals Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N041-01 - Signals Building - Golders Green Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|------|---------------|-------------------|----------|-----------|-----------------|---------------------|-------------|------------|-------------|---------------------|-------------------|
| 46274 | ACTIVE | N | N041-01-0/711 | SER - Signals Building - Golders Green Stn | | Asbestos | Strongly Presumed | | | | see Premises Survey | | | | N | N |

N041-02 - Signals Building - Golders Green Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|------------------------|---------------|-----------------------------------|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 8627 | ACTIVE | N | N041-02-1/662 | Switch Room - Signals Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Surveyed: Asbestos Presumed | | | | | | | | | |
| 41911 | ACTIVE | N | N041-02-1/662/WAL-001 | Wall: Internal - 1 - Switch Room - Signals Building - Golders Green Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | 1 x Switch Box - insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |
| 41912 | ACTIVE | N | N041-02-1/662/WAL-001 | Wall: Internal - 1 - Switch Room - Signals Building - Golders Green Stn | Other Electrical Boxes | Asbestos | Presumed | | | | 1 x Transformer Box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within | | 1 | | N | N |

N041-03 - Locker Block - Golders Green Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 8628 | ACTIVE | N | N041-03-1/316 | Locker Room - Locker Block - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8629 | ACTIVE | N | N041-03-1/416 | Shower Room - Locker Block - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8630 | ACTIVE | N | N041-03-1/417 | Shower Room - Locker Block - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8631 | ACTIVE | N | N041-03-1/418 | Toilet: Unisex - Locker Block - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8632 | ACTIVE | N | N041-03-A/316 | Locker Room - Locker Block - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8633 | ACTIVE | N | N041-03-A/416 | Shower Room - Locker Block - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8634 | ACTIVE | N | N041-03-A/417 | Shower Room - Locker Block - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N041-03 - Locker Block - Golders Green Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 8635 | ACTIVE | N | N041-03-A/418 | Toilet: Unisex - Locker Block - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8636 | ACTIVE | N | N041-03-A/576 | Stairs: Linear - Locker Block - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N041-04 - Signals Building - Golders Green Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 8637 | ACTIVE | N | N041-04-1/732 | CER - Signals Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N041-05 - Signals Building - Golders Green Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|------|---------------|-------------------|----------|-----------|-----------------|---------------------|-------------|------------|-------------|---------------------|-------------------|
| 46273 | ACTIVE | N | N041-05-0/706 | IMR - Signals Building - Golders Green Stn | | Asbestos | Strongly Presumed | | | | see Premises Survey | | | | N | N |

N042-02 - Store - Golders Green To Hampstead

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 8638 | ACTIVE | N | N042-02-0/571 | Store Room - Store - Golders Green To Hampstead | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N042-03 - Office Building - Golders Green To Hampstead

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 8639 | ACTIVE | N | N042-03-A/683 | Office - Office Building - Golders Green To Hampstead | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N042-04 - Signals Building - Golders Green To Hampstead

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 8640 | ACTIVE | N | N042-04-1/706 | IMR - Signals Building - Golders Green To Hampstead | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N042-04 - Signals Building - Golders Green To Hampstead

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 8641 | ACTIVE | N | N042-04-1/731 | IMR - Signals Building - Golders Green To Hampstead | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N042-05 - Signal Cabin - Golders Green To Hampstead

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 8642 | ACTIVE | N | N042-05-1/661 | Switch Room - Signal Cabin - Golders Green To Hampstead | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8643 | ACTIVE | N | N042-05-1/662 | Switch Room - Signal Cabin - Golders Green To Hampstead | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8644 | ACTIVE | N | N042-05-A/047 | Kitchen - Signal Cabin - Golders Green To Hampstead | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8645 | ACTIVE | N | N042-05-A/081 | Lobby - Signal Cabin - Golders Green To Hampstead | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8646 | ACTIVE | N | N042-05-A/416 | Toilet: Unisex - Signal Cabin - Golders Green To Hampstead | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8647 | ACTIVE | N | N042-05-A/801 | Signals Office - Signal Depot - Golders Green To Hampstead | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N042-06 - Union Office - Golders Green To Hampstead

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 8648 | ACTIVE | N | N042-06-A/047 | Kitchen - Union Office - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8649 | ACTIVE | N | N042-06-A/081 | Lobby - Union Office - Golders Green To Hampstead | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8650 | ACTIVE | N | N042-06-A/416 | Toilet: Unisex - Union Office - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8651 | ACTIVE | N | N042-06-A/801 | Union Office - Office Building - Golders Green Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N043-01 - Substation - Hampstead Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 8738 | ACTIVE | N | N043-01-1/781 | Transformer Room - Substation - Hampstead Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N053-01 - Signals Building - Mill Hill East Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 8916 | ACTIVE | N | N053-01-0/731 | CER - Signals Building - Mill Hill East Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N054-01 - Signals Building - Mill Hill East To Finchley Central

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 8917 | ACTIVE | N | N054-01-0/711 | SER - Signals Building - Mill Hill East To Finchley Central | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N061-01 - Signals Building - High Barnet Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 8988 | ACTIVE | N | N061-01-2/731 | CER - Signals Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17895 | ACTIVE | N | N061-01-2/731 | CER - Signals Building - High Barnet Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |

N061-02 - Signals Building - High Barnet Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 8989 | ACTIVE | N | N061-02-2/711 | SER - Signals Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8990 | ACTIVE | N | N061-02-2/731 | SER - Signals Building - High Barnet Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N062-02 - Signals Building - High Barnet To Totteridge & Whetstone

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|---------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 8991 | ACTIVE | N | N062-02-1/731 | CER - Signals Building - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8992 | ACTIVE | N | N062-02-A/706 | IMR - Signals Building - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42244 | ACTIVE | N | N062-02-A/706 | IMR - Signals Building - High Barnet To Totteridge & Whetstone | Cable Ducts: Cement | Asbestos | Surveyed – Not Detected | | | | Packing to concrete ducts within IMR / Relay room A - none detected | | | | N | N |

N062-03 - Abrams House - High Barnet To Totteridge & Whetstone

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 8993 | ACTIVE | N | N062-03-1/047 | Kitchen - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8994 | ACTIVE | N | N062-03-1/053 | Mess Room - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8995 | ACTIVE | N | N062-03-1/081 | Lobby - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8996 | ACTIVE | N | N062-03-1/082 | Lobby - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8997 | ACTIVE | N | N062-03-1/083 | Lobby - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8998 | ACTIVE | N | N062-03-1/084 | Lobby - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8999 | ACTIVE | N | N062-03-1/316 | Locker Room - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9000 | ACTIVE | N | N062-03-1/317 | Locker Room - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9001 | ACTIVE | N | N062-03-1/318 | Locker Room - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9002 | ACTIVE | N | N062-03-1/319 | Locker Room - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N062-03 - Abrams House - High Barnet To Totteridge & Whetstone

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 9003 | ACTIVE | N | N062-03-1/401 | Store - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9004 | ACTIVE | N | N062-03-1/406 | Store - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9005 | ACTIVE | N | N062-03-1/416 | Shower Room - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9006 | ACTIVE | N | N062-03-1/417 | Shower Room - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9007 | ACTIVE | N | N062-03-1/418 | Toilet: Male - Train Crew Accommodation - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9008 | ACTIVE | N | N062-03-1/419 | Toilet: Female - Train Crew Accommodation - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9009 | ACTIVE | N | N062-03-1/420 | Toilet: Unisex - Train Crew Accommodation - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9010 | ACTIVE | N | N062-03-1/421 | Toilet: Unisex - Train Crew Accommodation - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9011 | ACTIVE | N | N062-03-1/422 | Toilet - Abrams House - High Barnet to Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9012 | ACTIVE | N | N062-03-1/423 | Toilet: Unisex - Train Crew Accommodation - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9013 | ACTIVE | N | N062-03-1/481 | Locker Room - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9014 | ACTIVE | N | N062-03-1/482 | Locker Room - Abrams House - High Barnet to Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9015 | ACTIVE | N | N062-03-1/576 | Stairs: Linear - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9016 | ACTIVE | N | N062-03-1/577 | Stairs: Linear - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9017 | ACTIVE | N | N062-03-1/661 | Switch Room - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N062-03 - Abrams House - High Barnet To Totteridge & Whetstone

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 9018 | ACTIVE | N | N062-03-1/767 | Service Riser - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9019 | ACTIVE | N | N062-03-A/041 | Mess Room - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9020 | ACTIVE | N | N062-03-A/047 | Kitchen - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9021 | ACTIVE | N | N062-03-A/081 | Lobby - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9022 | ACTIVE | N | N062-03-A/082 | Lobby - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9023 | ACTIVE | N | N062-03-A/083 | Lobby - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9024 | ACTIVE | N | N062-03-A/084 | Lobby - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9025 | ACTIVE | N | N062-03-A/086 | Lobby - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9026 | ACTIVE | N | N062-03-A/316 | Locker Room - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9027 | ACTIVE | N | N062-03-A/406 | Store - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9028 | ACTIVE | N | N062-03-A/411 | Store - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9029 | ACTIVE | N | N062-03-A/412 | Store - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9030 | ACTIVE | N | N062-03-A/416 | Toilet: Female - Train Crew Accommodation - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9031 | ACTIVE | N | N062-03-A/417 | Toilet: Unisex - Train Crew Accommodation - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9032 | ACTIVE | N | N062-03-A/418 | Toilet: Male - Train Crew Accommodation - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N062-03 - Abrams House - High Barnet To Totteridge & Whetstone

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 9033 | ACTIVE | N | N062-03-A/419 | Toilet - Abrams House - High Barnet to Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9034 | ACTIVE | N | N062-03-A/420 | Toilet: Unisex - Train Crew Accommodation - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9035 | ACTIVE | N | N062-03-A/421 | Shower Room - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9036 | ACTIVE | N | N062-03-A/531 | DMT Office - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9037 | ACTIVE | N | N062-03-A/787 | Service Riser - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9038 | ACTIVE | N | N062-03-A/801 | Interview Room - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9039 | ACTIVE | N | N062-03-A/802 | Office - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9040 | ACTIVE | N | N062-03-B/044 | Mess Room - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9041 | ACTIVE | N | N062-03-B/081 | Lobby - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9042 | ACTIVE | N | N062-03-B/082 | Lobby - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9043 | ACTIVE | N | N062-03-B/236 | Passage - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9044 | ACTIVE | N | N062-03-B/306 | Office - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9045 | ACTIVE | N | N062-03-B/311 | Union Office - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9046 | ACTIVE | N | N062-03-B/411 | Store - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9047 | ACTIVE | N | N062-03-B/412 | Meeting Room - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N062-03 - Abrams House - High Barnet To Totteridge & Whetstone

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 9048 | ACTIVE | N | N062-03-B/416 | Toilet: Female - Train Crew Accommodation - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9049 | ACTIVE | N | N062-03-B/417 | Toilet: Male - Train Crew Accommodation - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9050 | ACTIVE | N | N062-03-B/731 | SCR - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9051 | ACTIVE | N | N062-03-B/790 | Service Riser - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9052 | ACTIVE | N | N062-03-B/801 | Train Ops Manager Office - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9053 | ACTIVE | N | N062-03-B/802 | Train Ops Support Manager Office - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9054 | ACTIVE | N | N062-03-B/803 | Training Room - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9055 | ACTIVE | N | N062-03-B/804 | Training Room - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9056 | ACTIVE | N | N062-03-B/805 | Meeting Room - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9057 | ACTIVE | N | N062-03-C/776 | Plant Room - Abrams House - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N062-05 - Signals Building - High Barnet To Totteridge & Whetstone

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 9058 | ACTIVE | N | N062-05-2/731 | CER - Signals Building - High Barnet To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N064-01 - Signals Building - Totteridge & Whetstone To Woodside Park

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 9092 | ACTIVE | N | N064-01-2/731 | Relay Room - Signals Building - Woodside Park To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N064-02 - Signals Building - Totteridge & Whetstone To Woodside Park

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 9093 | ACTIVE | N | N064-02-2/711 | SER - Signals Building - Woodside Park To Totteridge & Whetstone | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N064-03 - Signals Building - Totteridge & Whetstone To Woodside Park

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9094 | ACTIVE | N | N064-03-0/711 | SER - Signals Building - Totteridge & Whetstone to Woodside Park | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 46282 | ACTIVE | N | N064-03-0/711 | SER - Signals Building - Totteridge & Whetstone to Woodside Park | Westinghouse Boxes | Asbestos | Presumed | | | | 1x Westinghouse box to rear of building | | 1 | | | |
| 46277 | ACTIVE | N | N064-03-0/711/WAL-002 | Wall: Internal - 2 - SER - Signals Building - Totteridge & Whetstone To Woodside Park | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | 3x Electrical Equipment | | 3 | | N | N |
| 46279 | ACTIVE | N | N064-03-0/711/WAL-003 | Wall: Internal - 3 - SER - Signals Building - Totteridge & Whetstone To Woodside Park | Cable Duct: Other | Asbestos | Strongly Presumed | | | | 1x Cable duct | | 1 | | N | N |
| 46278 | ACTIVE | N | N064-03-0/711/WAL-003 | Wall: Internal - 3 - SER - Signals Building - Totteridge & Whetstone To Woodside Park | Westinghouse Boxes | Asbestos | Strongly Presumed | | | | 1x Small Westinghouse box | | 1 | | | |
| 46281 | ACTIVE | N | N064-03-0/711/WAL-004 | Wall: Internal - 4 - SER - Signals Building - Totteridge & Whetstone To Woodside Park | Other Boarding | Asbestos | Strongly Presumed | | | | 4x Composite Board fuse blocks | | 4 | | N | N |
| 46280 | ACTIVE | N | N064-03-0/711/WAL-004 | Wall: Internal - 4 - SER - Signals Building - Totteridge & Whetstone To Woodside Park | Westinghouse Boxes | Asbestos | Strongly Presumed | | | | 1x Small Westinghouse box | | 1 | | | |

N067-01 - Signals Building - West Finchley Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 9153 | ACTIVE | N | N067-01-0/661 | Switch Room - Signals Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N067-01 - Signals Building - West Finchley Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 9154 | ACTIVE | N | N067-01-0/711 | SER - Signals Building - West Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N071-01 - Signals Building - Finchley Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 9222 | ACTIVE | N | N071-01-0/711 | SER - Signals Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N071-02 - Signals Building - Finchley Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 9223 | ACTIVE | N | N071-02-2/732 | CER - Signals Building - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N071-03 - Pump House - Finchley Central Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9224 | ACTIVE | N | N071-03-2/771 | Pump Room - Pump House - Finchley Central Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 25074 | ACTIVE | N | N071-03-2/771 | Pump Room - Pump House - Finchley Central Stn | Isolator Switches | Asbestos | Presumed | | | | 1x Switch box Presumed asbestos insulation within | | 1 | | N | N |

N072-02 - Communications Building - Finchley Central To East Finchley

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 9226 | ACTIVE | N | N072-02-0/741 | Telephone Exchange - Communications Building - Finchley Central To East Finchley | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N072-04 - Signal Cabin - Finchley Central To East Finchley

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 9227 | ACTIVE | N | N072-04-1/081 | Lobby - Signal Cabin - Finchley Central To East Finchley | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N072-04 - Signal Cabin - Finchley Central To East Finchley

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 9228 | ACTIVE | N | N072-04-1/576 | Stairs: Linear - Signal Cabin - Finchley Central To East Finchley | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9229 | ACTIVE | N | N072-04-1/706 | IMR - Signal Cabin - Finchley Central To East Finchley | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9230 | ACTIVE | N | N072-04-1/711 | IMR - Signal Cabin - Finchley Central To East Finchley | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9231 | ACTIVE | N | N072-04-1/731 | CER - Signal Cabin - Finchley Central To East Finchley | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9232 | ACTIVE | N | N072-04-A/706 | IMR - Signal Cabin - Finchley Central To East Finchley | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9233 | ACTIVE | N | N072-04-A/731 | CER - Signal Cabin - Finchley Central To East Finchley | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9234 | ACTIVE | N | N072-04-A/771 | Store - Signal Cabin - Finchley Central To East Finchley | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N073-01 - Signals Building - East Finchley Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---------------------------------|-------------|------------|-------------|---------------------|-------------------|
| 9298 | ACTIVE | N | N073-01-0/711 | SER - Signals Building - East Finchley Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 17350 | ACTIVE | N | N073-01-0/711 | SER - Signals Building - East Finchley Stn | No Access | Asbestos | Surveyed – Not Detected | | | | Not Surveyed - New Construction | | | | | |

N075-01 - Station Building - Highgate Disused Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------|--|------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9371 | INACTIVE | N | N075-01-1/261 | Disused Room - Station Building - Highgate Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44892 | INACTIVE | N | N075-01-1/261 | Disused Room - Station Building - Highgate Disused Stn | Other Boarding | Asbestos | Presumed | | | | Advertising Boards along platform | | | | N | N |
| 44169 | ACTIVE | N | N075-01-1/261 | Disused Room - Station Building - Highgate Disused Stn | Boarding: Cement | Asbestos | Presumed | | | | Advertising boards located along the platform | | | | N | N |



Hazardous Material Asset Register - Summary



N075-01 - Station Building - Highgate Disused Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|-----------------------|---|------------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 9372 | INACTIVE | N | N075-01-1/262 | Disused Room - Station Building - Highgate Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44893 | INACTIVE | N | N075-01-1/262 | Disused Room - Station Building - Highgate Disused Stn | Other Boarding | Asbestos | Presumed | | | | Advertising Boards along platform | | | | N | N |
| 44170 | ACTIVE | N | N075-01-1/262 | Disused Room - Station Building - Highgate Disused Stn | Boarding: Cement | Asbestos | Presumed | | | | Advertising boards located along the platform | | | | N | N |
| 9373 | INACTIVE | N | N075-01-1/776 | Plant Room - Station Building - Highgate Disused Stn | Stations: Rooms | Asbestos | Room: Surveyed – Asbestos Known | | | | | | | | | |
| 17168 | ACTIVE | N | N075-01-1/776 | Plant Room - Station Building - Highgate Disused Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Transformer Box - Asbestos materials within to wall 2 | | 1 | | N | N |
| 44894 | INACTIVE | N | N075-01-1/776 | Plant Room - Station Building - Highgate Disused Stn | Mastic | Asbestos | Strongly Presumed | | | | Flanges / Mastic within Ductwork | | | | N | N |
| 42543 | ACTIVE | N | N075-01-1/776 | Plant Room - Station Building - Highgate Disused Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Combination fuse switch - Asbestos materials within 1 x 60 amp Switch Box to wall 1 | | 1 | | N | N |
| 44895 | INACTIVE | N | N075-01-1/776 | Plant Room - Station Building - Highgate Disused Stn | Other Electrical Boxes | Asbestos | Strongly Presumed | | | | Transformer Box & 1 x 60 amp Switch Box | | | | N | N |
| 44168 | ACTIVE | N | N075-01-1/776/WAL-003 | Wall: Internal - 3 - Disused Room - Disused Station Building - Highgate Stn | Mastic | Asbestos | Strongly Presumed | | | | Flanges / Mastic within Ductwork | | | | N | N |
| 9374 | INACTIVE | N | N075-01-1/951 | Disused Room - Station Building - Highgate Disused Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | None Visible | | | | | |
| 70384 | ACTIVE | N | N075-01-1/951 | Disused Room - Station Building - Highgate Disused Stn | | Asbestos | Surveyed – Not Detected | | | | Surveyed no asbestos detected | | | | | |
| 9375 | INACTIVE | N | N075-01-1/952 | Disused Room - Station Building - Highgate Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 70381 | ACTIVE | N | N075-01-1/952 | Disused Room - Station Building - Highgate Disused Stn | | Asbestos | No Access: Presumed | | | | Access sealed over | | | | | |
| 9376 | INACTIVE | N | N075-01-1/953 | CER - Station Building - Highgate Disused Stn | Stations: Rooms | Asbestos | Room: Surveyed – No Known Asbestos | | | | | | | | | |
| 42247 | ACTIVE | N | N075-01-1/953 | CER - Station Building - Highgate Disused Stn | | Asbestos | Surveyed – Not Detected | | | | No Asbestos visible | | | | | |



Hazardous Material Asset Register - Summary



N096-01 - Melton Street Vent Shaft - Camden Town To Euston

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 9964 | ACTIVE | N | N096-01-1/781 | Tunnel Telephone Room - Melton Street Vent Shaft - Camden Town To Euston | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 9965 | ACTIVE | N | N096-01-4/781 | Plant Room - Melton Street Vent Shaft - Camden Town To Euston | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N124-02 - Substation - Kings Cross To Angel

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 10842 | ACTIVE | N | N124-02-1/781 | Substation Room - Substation - Kings Cross To Angel | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N125-01 - Station Building - Angel Disused Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|----------------------------|-------------|------------|-------------|---------------------|-------------------|
| 10917 | ACTIVE | N | N125-01-1/081 | Lobby - Disused Station Building - Angel Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10918 | ACTIVE | N | N125-01-1/083 | Lobby - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10919 | ACTIVE | N | N125-01-1/240 | Passage - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10920 | ACTIVE | N | N125-01-1/401 | Store - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10921 | ACTIVE | N | N125-01-1/411 | Store - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10922 | ACTIVE | N | N125-01-1/412 | Transformer Room - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16682 | ACTIVE | N | N125-01-1/412/FLR-01 | Floor - 1 - Equipment Room - Disused Station Building - Angel Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Vinyl Tiles - Non Asbestos | | | | | |
| 10923 | ACTIVE | N | N125-01-1/576 | Stairs: Linear - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10924 | ACTIVE | N | N125-01-1/631 | Stairs: Spiral - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N125-01 - Station Building - Angel Disused Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|-----------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 43968 | ACTIVE | N | N125-01-1/631 | Stairs: Spiral - Station Building - Angel Disused Stn | | Asbestos | Sampled – Not Detected | | | | Bitumen stair treads, disused shaft | | | R407101 | N | N |
| 43969 | ACTIVE | N | N125-01-1/631 | Stairs: Spiral - Station Building - Angel Disused Stn | | Asbestos | Sampled – Not Detected | | | | Caulking, passage at bottom of disused shaft | | | R407101 | N | N |
| 44940 | ACTIVE | N | N125-01-1/631 | Stairs: Spiral - Station Building - Angel Disused Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Disused Staircase - Top of Stairs - Support Steel - Grey Gloss | | | | N | N |
| 44943 | ACTIVE | N | N125-01-1/631 | Stairs: Spiral - Station Building - Angel Disused Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Disused Staircase - Bottom of Shaft - Single Width Stairs Grey Gloss | | | | N | N |
| 44942 | ACTIVE | N | N125-01-1/631 | Stairs: Spiral - Station Building - Angel Disused Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Disused Staircase - Bottom of Shaft - Hand Rail Grey Gloss | | | | N | N |
| 44941 | ACTIVE | N | N125-01-1/631 | Stairs: Spiral - Station Building - Angel Disused Stn | Lead/Leading | Lead Paint/Lead | Known | | | | Disused Staircase - Bottom of Shaft - Support steel Grey Gloss | | | | N | N |
| 10925 | ACTIVE | N | N125-01-1/662 | Switch Room - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10926 | ACTIVE | N | N125-01-1/663 | Switch Room - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10927 | ACTIVE | N | N125-01-1/801 | Office - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20027 | ACTIVE | N | N125-01-1/801/CLG-01 | Ceiling: Solid - 1 - Office - Disused Station Building - Angel Stn | Glazing Rope | Asbestos | Strongly Presumed | | | | Roof Light - Glazing Bars No access to disused ticket hall area during 2020 re-inspection. Keys not available with station supervisor and alternative route via disused lower concourse deemed unsafe. | | | | | |
| 10928 | ACTIVE | N | N125-01-1/951 | Disused Room - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10929 | ACTIVE | N | N125-01-1/952 | Disused Room - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10930 | ACTIVE | N | N125-01-1/953 | Disused Room - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10931 | ACTIVE | N | N125-01-1/954 | Disused Room - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10932 | ACTIVE | N | N125-01-1/986 | Disused Room - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N125-01 - Station Building - Angel Disused Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|-----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 10933 | ACTIVE | N | N125-01-1/987 | Disused Room - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10934 | ACTIVE | N | N125-01-2/238 | Disused Room - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16709 | ACTIVE | N | N125-01-2/238/WAL-003 | Wall: Internal - 3 - Disused Room - Disused Station Building - Angel Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Hardboard Panel | | | | | |
| 10935 | ACTIVE | N | N125-01-2/239 | Passage - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19055 | ACTIVE | N | N125-01-2/239/CLG-01 | Ceiling: Solid - 1 - Passage - Disused Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Plasterboard ceiling | | | | YES | |
| 10936 | ACTIVE | N | N125-01-2/331 | Mess Room - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16711 | ACTIVE | N | N125-01-2/331/CLG-01 | Ceiling: Solid - 1 - Mess room - Disused Station Building - Angel Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 18371 | ACTIVE | N | N125-01-2/331/CLG-01 | Ceiling: Solid - 1 - Mess room - Disused Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Plasterboard ceiling | | | | YES | |
| 10937 | ACTIVE | N | N125-01-2/371 | Store - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10938 | ACTIVE | N | N125-01-2/411 | Store - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16715 | ACTIVE | N | N125-01-2/411 | Store - Station Building - Angel Disused Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed -No Access : Note A Do not Enter notice is applied to the Room | | | | | |
| 10939 | ACTIVE | N | N125-01-2/412 | Store - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16716 | ACTIVE | N | N125-01-2/412 | Store - Station Building - Angel Disused Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed -No Access : Note A Do not Enter notice is applied to the Room | | | | | |
| 10940 | ACTIVE | N | N125-01-2/413 | Store - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16717 | ACTIVE | N | N125-01-2/413 | Store - Station Building - Angel Disused Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed -No Access : Note A Do not Enter notice is applied to the Room | | | | | |



Hazardous Material Asset Register - Summary



N125-01 - Station Building - Angel Disused Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-----------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 10941 | ACTIVE | N | N125-01-2/416 | Disused Room - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16718 | ACTIVE | N | N125-01-2/416/CLG-01 | Ceiling: Solid - 1 - Disused Room - Disused Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Plasterboard ceiling | | | | YES | |
| 16719 | ACTIVE | N | N125-01-2/416/CLG-01 | Ceiling: Solid - 1 - Disused Room - Disused Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Plasterboard ceiling | | | | YES | |
| 18372 | ACTIVE | N | N125-01-2/416/CLG-01 | Ceiling: Solid - 1 - Disused Room - Disused Station Building - Angel Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 10942 | ACTIVE | N | N125-01-2/417 | Shower Room - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19056 | ACTIVE | N | N125-01-2/417/CLG-01 | Ceiling: Solid - 1 - Shower Room - Disused Station Building - Angel Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 10943 | ACTIVE | N | N125-01-2/418 | Shower Room - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10944 | ACTIVE | N | N125-01-2/901 | Service Riser - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | No Access, Notice Do Not Enter Aug 2014 | | | | | |
| 16724 | ACTIVE | N | N125-01-2/901 | Service Riser - Station Building - Angel Disused Stn | No Access | Asbestos | No Access: Presumed | | | | Not Surveyed - No Access : Note A do not Enter notice applied to this room | | | | | |
| 10945 | ACTIVE | N | N125-01-2/951 | Disused Room - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10946 | ACTIVE | N | N125-01-2/953 | Disused Room - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18438 | ACTIVE | N | N125-01-2/953/CLG-01 | Ceiling: Solid - 1 - Disused Room - Disused Station Building - Angel Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |
| 16726 | ACTIVE | N | N125-01-2/953/CLG-01 | Ceiling: Solid - 1 - Disused Room - Disused Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Plasterboard ceiling | | | | YES | |
| 10947 | ACTIVE | N | N125-01-2/954 | Office - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 19057 | ACTIVE | N | N125-01-2/954/CLG-01 | Ceiling: Solid - 1 - Office - Disused Station Building - Angel Stn | Other Boarding | Asbestos | Surveyed – Not Detected | | | | Plasterboard | | | | | |



Hazardous Material Asset Register - Summary



N125-01 - Station Building - Angel Disused Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-------------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 16727 | ACTIVE | N | N125-01-2/954/CLG-01 | Ceiling: Solid - 1 - Office - Disused Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above Plasterboard ceiling | | | | YES | |
| 10948 | ACTIVE | N | N125-01-2/955 | Disused Room - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10949 | ACTIVE | N | N125-01-2/988 | Disused Room - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10950 | ACTIVE | N | N125-01-2/989 | Disused Room - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10951 | ACTIVE | N | N125-01-3/081 | Lobby - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10952 | ACTIVE | N | N125-01-3/082 | Circulation Area - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44739 | ACTIVE | N | N125-01-3/082 | Circulation Area - Station Building - Angel Disused Stn | | Lead Paint/Lead | Known | | | | High level walls / ceilings - Cream gloss - Lead Content Analysis - 0.63% | | | | | |
| 44738 | ACTIVE | N | N125-01-3/082 | Circulation Area - Station Building - Angel Disused Stn | | Lead Paint/Lead | Known | | | | Columns & Beams - Green gloss paint - Lead Content Analysis 1.91% | | | | | |
| 44750 | ACTIVE | N | N125-01-3/082 | Circulation Area - Station Building - Angel Disused Stn | | Lead Paint/Lead | Sampled – Not Detected | | | | Skirting and low level walls - Black matt paint - Lead Analysis - 0.13% - Not considered a lead hazard | | | | | |
| 18440 | ACTIVE | N | N125-01-3/082/FLR-01 | Floor - 1 - Circulation Area - Disused Station Building - Angel Stn | Isolator Switches | Asbestos | Not Found during Inspection | | | | Flash Guards - Chrysotile Flash guards not present in 2020 re-inspection - possibly removed | | 4 | | | |
| 10953 | ACTIVE | N | N125-01-3/202 | Lobby - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42250 | ACTIVE | N | N125-01-3/202 | Lobby - Station Building - Angel Disused Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Walls - Durasteel | | | | N | N |
| 44939 | ACTIVE | N | N125-01-3/202 | Lobby - Station Building - Angel Disused Stn | Lead/Leading | Lead Paint/Lead | Known | | | | High level walls / ceiling - Green Gloss | | | | N | N |
| 10954 | ACTIVE | N | N125-01-3/203 | Passage - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44745 | ACTIVE | N | N125-01-3/203 | Passage - Station Building - Angel Disused Stn | | Lead Paint/Lead | Known | | | | Columns & Beams - Green gloss paint - Lead Content Analysis 1.91% | | | | | |
| 44747 | ACTIVE | N | N125-01-3/203 | Passage - Station Building - Angel Disused Stn | | Lead Paint/Lead | Sampled – Not Detected | | | | Skirting and low level walls - Black Matt - Lead Paint Analysis 0.14% | | | | | |
| 44744 | ACTIVE | N | N125-01-3/203 | Passage - Station Building - Angel Disused Stn | | Lead Paint/Lead | Known | | | | Low level wall - Blue gloss - Lead Content Analysis 8.64% | | | | | |



Hazardous Material Asset Register - Summary



N125-01 - Station Building - Angel Disused Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|-----------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 44746 | ACTIVE | N | N125-01-3/203 | Passage - Station Building - Angel Disused Stn | | Lead Paint/Lead | Sampled – Not Detected | | | | High level walls / ceiling - Cream Gloss - Lead Paint Analysis 0.18% | | | | | |
| 10955 | ACTIVE | N | N125-01-3/204 | Passage - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44743 | ACTIVE | N | N125-01-3/204 | Passage - Station Building - Angel Disused Stn | | Lead Paint/Lead | Sampled – Not Detected | | | | Skirting and low level walls - Black matt paint - Lead Analysis - 0.16% - Not considered a lead hazard | | | | | |
| 44742 | ACTIVE | N | N125-01-3/204 | Passage - Station Building - Angel Disused Stn | | Lead Paint/Lead | Known | | | | High level walls / ceiling - Cream Gloss - Lead Paint Analysis 0.54% | | | | | |
| 44741 | ACTIVE | N | N125-01-3/204 | Passage - Station Building - Angel Disused Stn | | Lead Paint/Lead | Known | | | | Columns & Beams - Green gloss paint - Lead Content Analysis 2.54% | | | | | |
| 10956 | ACTIVE | N | N125-01-3/205 | Passage - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10957 | ACTIVE | N | N125-01-3/206 | Lobby - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 44749 | ACTIVE | N | N125-01-3/206 | Lobby - Station Building - Angel Disused Stn | | Lead Paint/Lead | Sampled – Not Detected | | | | Skirting and low level walls - Black Matt - Lead Paint Analysis 0.14% | | | | | |
| 44748 | ACTIVE | N | N125-01-3/206 | Lobby - Station Building - Angel Disused Stn | | Lead Paint/Lead | Sampled – Not Detected | | | | High level walls / ceiling - Cream Gloss - Lead Paint Analysis 0.18% | | | | | |
| 10958 | ACTIVE | N | N125-01-3/632 | Lobby - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 10959 | ACTIVE | N | N125-01-3/661 | Switch Cupboard - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | No Access - Presumed to contain Switch Boxes - Insulation within | | | | | |
| 10960 | ACTIVE | N | N125-01-3/763 | Switch Cupboard - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42251 | ACTIVE | N | N125-01-3/763 | Switch Cupboard - Station Building - Angel Disused Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Supalux Boarding | | | | N | N |
| 10961 | ACTIVE | N | N125-01-3/986 | Disused Room - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42254 | ACTIVE | N | N125-01-3/986 | Disused Room - Station Building - Angel Disused Stn | | Asbestos | Surveyed – Not Detected | | | | Tunnel Rings Caulking - Further investigations required | | | | | |
| 10962 | ACTIVE | N | N125-01-3/987 | Disused Room - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 42255 | ACTIVE | N | N125-01-3/987 | Disused Room - Station Building - Angel Disused Stn | Caulking | Asbestos | Surveyed – Not Detected | | | | Tunnel Rings Caulking - further investigation required | | | | N | N |



Hazardous Material Asset Register - Summary



N125-01 - Station Building - Angel Disused Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|--|-------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 10963 | ACTIVE | N | N125-01-A/131 | Disused Room - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16589 | ACTIVE | N | N125-01-A/131 | Disused Room - Station Building - Angel Disused Stn | Isolator Switches | Asbestos | Strongly Presumed | | | | Switch Boxes - Insulation within Area not accessed during 2020 re-inspection. Access via disused ticket hall. | | 3 | | | |
| 16588 | ACTIVE | N | N125-01-A/131/CLG-01 | Ceiling: Solid - 1 - Disused Room - Disused Station Building - Angel Stn | Void | Asbestos | No Access: Presumed | | | | Above - Non Asbestos Boards | | | | YES | |
| 18279 | ACTIVE | N | N125-01-A/131/FLR-01 | Floor - 1 - Stairs - Disused Station Building - Angel Stn | Durasteel | Asbestos | Surveyed – Not Detected | | | | Lid to Storage Bin | | | | | |
| 10964 | ACTIVE | N | N125-01-A/132 | Disused Room - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16590 | ACTIVE | N | N125-01-A/132/FLR-01 | Floor - 1 - Stairs - Disused Station Building - Angel Stn | Debris: Other | Asbestos | Known | | | | Machine Debris - Chrysotile Area not accessed during 2020 re-inspection. Access via disused ticket hall. | | | | | |
| 10965 | ACTIVE | N | N125-01-A/291 | Disused Room - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 16591 | ACTIVE | N | N125-01-A/291/FLR-01 | Floor - 1 - Disused Room - Disused Station Building - Angel Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Lino, Vinyl Tiles - Non Asbestos | | | | | |
| 10966 | ACTIVE | N | N125-01-A/411 | Disused Room - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 20025 | ACTIVE | N | N125-01-A/411/FLR-01 | Floor - 1 - Disused Room - Disused Station Building - Angel Stn | Vinyl tiles | Asbestos | Surveyed – Not Detected | | | | Lino, Vinyl Tiles - Non Asbestos | | | | | |
| 10967 | ACTIVE | N | N125-01-A/578 | Stairs: Linear - Station Building - Angel Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N142-01 - Signals Building - Elephant & Castle To Kennington

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 11431 | ACTIVE | N | N142-01-0/081 | Lobby - Signals Building - Elephant & Castle To Kennington | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11432 | ACTIVE | N | N142-01-0/661 | Switch Cupboard - Signals Building - Elephant & Castle To Kennington | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N142-01 - Signals Building - Elephant & Castle To Kennington

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 11433 | ACTIVE | N | N142-01-0/711 | SER - Signals Building - Elephant & Castle To Kennington | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11434 | ACTIVE | N | N142-01-A/081 | Lobby - Signals Building - Elephant & Castle To Kennington | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11435 | ACTIVE | N | N142-01-A/082 | Lobby - Signals Building - Elephant & Castle To Kennington | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11436 | ACTIVE | N | N142-01-A/316 | Locker Room - Signals Building - Elephant & Castle To Kennington | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11437 | ACTIVE | N | N142-01-A/416 | Shower Room - Signals Building - Elephant & Castle To Kennington | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11438 | ACTIVE | N | N142-01-A/417 | Toilet: Unisex - Signals Building - Elephant & Castle To Kennington | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11439 | ACTIVE | N | N142-01-A/481 | Signals Office - Signals Office Building - Elephant & Castle To Kennington | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11440 | ACTIVE | N | N142-01-A/661 | Switch Room - Signals Building - Elephant & Castle To Kennington | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N166-01 - Balham Vent Shaft - Balham To Tooting Bec

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 11998 | ACTIVE | N | N166-01-1/081 | Lobby - Balham Vent Shaft - Balham To Tooting Bec | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 11999 | ACTIVE | N | N166-01-1/411 | Store - Balham Vent Shaft - Balham To Tooting Bec | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12000 | ACTIVE | N | N166-01-1/576 | Stairs: Linear - Balham Vent Shaft - Balham To Tooting Bec | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12001 | ACTIVE | N | N166-01-1/776 | Fan Room - Balham Vent Shaft - Balham To Tooting Bec | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12002 | ACTIVE | N | N166-01-1/801 | Office - Balham Vent Shaft - Balham To Tooting Bec | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N166-01 - Balham Vent Shaft - Balham To Tooting Bec

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 12003 | ACTIVE | N | N166-01-A/081 | Lobby - Balham Vent Shaft - Balham To Tooting Bec | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12004 | ACTIVE | N | N166-01-A/416 | Disused Room - Balham Vent Shaft - Balham To Tooting Bec | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12005 | ACTIVE | N | N166-01-A/776 | Fan Room - Balham Vent Shaft - Balham To Tooting Bec | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12006 | ACTIVE | N | N166-01-B/081 | Lobby - Balham Vent Shaft - Balham To Tooting Bec | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12007 | ACTIVE | N | N166-01-B/402 | Void - Balham Vent Shaft - Balham To Tooting Bec | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12008 | ACTIVE | N | N166-01-B/411 | Store - Balham Vent Shaft - Balham To Tooting Bec | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12009 | ACTIVE | N | N166-01-B/801 | Office - Balham Vent Shaft - Balham To Tooting Bec | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12010 | ACTIVE | N | N166-01-B/901 | Void - Balham Vent Shaft - Balham To Tooting Bec | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N176-01 - Dorset Road Pump House - South Wimbledon To Morden

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 12247 | ACTIVE | N | N176-01-1/771 | Pump Room - Dorset Road Pump House - South Wimbledon To Morden | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N177-02 - Kenley Road Pump House - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 12435 | ACTIVE | N | N177-02-1/771 | Pump Room - Kenley Road Pump House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N177-03 - Signals Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|-------------------------------------|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 12436 | ACTIVE | N | N177-03-2/706 | IMR - Signals Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N177-04 - Signals Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|-------------------------------------|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 12437 | ACTIVE | N | N177-04-1/711 | SER - Signals Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

N177-05 - Bicycle Shed - Signals Building - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|----------------------|---|-----------------|---------------|--|----------|-----------|-----------------|----------------------------|-------------|------------|-------------|---------------------|-------------------|
| 12438 | ACTIVE | N | N177-05-1/731 | CER - Signals Building - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 18163 | ACTIVE | N | N177-05-1/731/FLR-01 | Floor - 1 - CER - Signals Building - Morden Stn | Void | Asbestos | No Access: Presumed | | | | Beneath False Wooden Floor | | | | | YES |

N177-06 - Garth House - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 12439 | ACTIVE | N | N177-06-1/041 | Mess Room - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12440 | ACTIVE | N | N177-06-1/042 | Mess Room - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12441 | ACTIVE | N | N177-06-1/047 | Kitchen - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12442 | ACTIVE | N | N177-06-1/048 | Kitchen - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12443 | ACTIVE | N | N177-06-1/053 | Mess Room - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12444 | ACTIVE | N | N177-06-1/054 | Switch Room - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N177-06 - Garth House - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 12445 | ACTIVE | N | N177-06-1/056 | Toilet: Unisex - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12446 | ACTIVE | N | N177-06-1/081 | Lobby - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12447 | ACTIVE | N | N177-06-1/083 | Lobby - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12448 | ACTIVE | N | N177-06-1/084 | Lobby - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12449 | ACTIVE | N | N177-06-1/092 | Lobby - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12450 | ACTIVE | N | N177-06-1/237 | Passage - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12451 | ACTIVE | N | N177-06-1/238 | Lobby - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12452 | ACTIVE | N | N177-06-1/240 | Passage - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12453 | ACTIVE | N | N177-06-1/241 | Passage - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12454 | ACTIVE | N | N177-06-1/242 | Passage - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12455 | ACTIVE | N | N177-06-1/281 | Office - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12456 | ACTIVE | N | N177-06-1/291 | Office - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12457 | ACTIVE | N | N177-06-1/301 | Passage - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12458 | ACTIVE | N | N177-06-1/302 | Mess Room - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12459 | ACTIVE | N | N177-06-1/306 | Office - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N177-06 - Garth House - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 12460 | ACTIVE | N | N177-06-1/317 | Office - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12461 | ACTIVE | N | N177-06-1/331 | Mess Room - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12462 | ACTIVE | N | N177-06-1/401 | Store - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12463 | ACTIVE | N | N177-06-1/402 | Store - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12464 | ACTIVE | N | N177-06-1/406 | Store - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12465 | ACTIVE | N | N177-06-1/407 | Store - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12466 | ACTIVE | N | N177-06-1/411 | Store - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12467 | ACTIVE | N | N177-06-1/414 | Locker Room - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12468 | ACTIVE | N | N177-06-1/416 | Toilet: Male - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12469 | ACTIVE | N | N177-06-1/417 | Lobby - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12470 | ACTIVE | N | N177-06-1/418 | Toilet: Female - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12471 | ACTIVE | N | N177-06-1/421 | Toilet: Female - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12472 | ACTIVE | N | N177-06-1/422 | Toilet: Male - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12473 | ACTIVE | N | N177-06-1/425 | Shower Room - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12474 | ACTIVE | N | N177-06-1/426 | Shower Room - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N177-06 - Garth House - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 12475 | ACTIVE | N | N177-06-1/427 | Toilet: Male - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12476 | ACTIVE | N | N177-06-1/610 | Stairs: Linear - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12477 | ACTIVE | N | N177-06-1/661 | Switch Room - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12478 | ACTIVE | N | N177-06-1/662 | Switch Cupboard - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12479 | ACTIVE | N | N177-06-1/664 | Switch Cupboard - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12480 | ACTIVE | N | N177-06-1/666 | Switch Cupboard - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12481 | ACTIVE | N | N177-06-1/761 | Equipment Room - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12482 | ACTIVE | N | N177-06-1/801 | Office - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12483 | ACTIVE | N | N177-06-1/802 | Office - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12484 | ACTIVE | N | N177-06-1/804 | Office - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12485 | ACTIVE | N | N177-06-1/805 | Office - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12486 | ACTIVE | N | N177-06-1/809 | Office - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12487 | ACTIVE | N | N177-06-1/810 | Office - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12488 | ACTIVE | N | N177-06-1/811 | Office - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12489 | ACTIVE | N | N177-06-1/812 | Office - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N177-06 - Garth House - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 12490 | ACTIVE | N | N177-06-1/813 | Office - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12491 | ACTIVE | N | N177-06-1/901 | Store - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12492 | ACTIVE | N | N177-06-1/903 | Office - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12493 | ACTIVE | N | N177-06-1/904 | Kitchen - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12494 | ACTIVE | N | N177-06-1/906 | Store - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12495 | ACTIVE | N | N177-06-1/907 | Store - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12496 | ACTIVE | N | N177-06-1/908 | Store - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12497 | ACTIVE | N | N177-06-A/082 | Lobby - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12498 | ACTIVE | N | N177-06-A/236 | Passage - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12499 | ACTIVE | N | N177-06-A/237 | Passage - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12500 | ACTIVE | N | N177-06-A/316 | Locker Room - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12501 | ACTIVE | N | N177-06-A/331 | Mess Room - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12502 | ACTIVE | N | N177-06-A/332 | Mess Room - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12503 | ACTIVE | N | N177-06-A/406 | Store - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12504 | ACTIVE | N | N177-06-A/411 | Store - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



N177-06 - Garth House - Morden Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 12505 | ACTIVE | N | N177-06-A/412 | Store - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12506 | ACTIVE | N | N177-06-A/417 | Shower Room - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12507 | ACTIVE | N | N177-06-A/576 | Stairs: Linear - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12508 | ACTIVE | N | N177-06-A/661 | Switch Cupboard - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12509 | ACTIVE | N | N177-06-A/761 | Equipment Room - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12510 | ACTIVE | N | N177-06-A/801 | Office - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12511 | ACTIVE | N | N177-06-A/802 | Office - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12512 | ACTIVE | N | N177-06-A/803 | Office - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12513 | ACTIVE | N | N177-06-B/576 | Stairs: Linear - Garth House - Morden Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

ND021-02 - Signals Building - Edgware Depot

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 12535 | ACTIVE | N | ND021-02-0/661 | Switch Room - Signals Building - Edgware Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

ND074-02 - Office Building - Highgate Depot

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 12552 | ACTIVE | N | ND074-02-1/081 | Lobby - Office Building - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12553 | ACTIVE | N | ND074-02-1/082 | Lobby - Office Building - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



ND074-02 - Office Building - Highgate Depot

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 12554 | ACTIVE | N | ND074-02-1/236 | Passage - Office Building - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12555 | ACTIVE | N | ND074-02-1/316 | Locker Room - Office Building - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12556 | ACTIVE | N | ND074-02-1/331 | Mess Room - Office Building - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12557 | ACTIVE | N | ND074-02-1/416 | Toilet: Female - Office Building - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12558 | ACTIVE | N | ND074-02-1/417 | Toilet: Male - Office Building - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12559 | ACTIVE | N | ND074-02-1/661 | Switch Room - Office Building - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12560 | ACTIVE | N | ND074-02-1/801 | Office - Office Building - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12561 | ACTIVE | N | ND074-02-1/802 | Office - Office Building - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12562 | ACTIVE | N | ND074-02-1/803 | Office - Office Building - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12563 | ACTIVE | N | ND074-02-1/901 | Cleaners Room - Office Building - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

ND074-03 - Highgate Service Control Centre - Highgate Depot

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 12564 | ACTIVE | N | ND074-03-1/081 | Lobby - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12565 | ACTIVE | N | ND074-03-1/082 | Lobby - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12566 | ACTIVE | N | ND074-03-1/083 | Lobby - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



ND074-03 - Highgate Service Control Centre - Highgate Depot

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 12567 | ACTIVE | N | ND074-03-1/236 | Passage - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12568 | ACTIVE | N | ND074-03-1/237 | Passage - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12569 | ACTIVE | N | ND074-03-1/238 | Passage - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12570 | ACTIVE | N | ND074-03-1/239 | Passage - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12571 | ACTIVE | N | ND074-03-1/240 | Passage - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12572 | ACTIVE | N | ND074-03-1/241 | Passage - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12573 | ACTIVE | N | ND074-03-1/242 | Passage - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12574 | ACTIVE | N | ND074-03-1/316 | Locker Room - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12575 | ACTIVE | N | ND074-03-1/331 | Mess Room - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12576 | ACTIVE | N | ND074-03-1/332 | Mess Room - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12577 | ACTIVE | N | ND074-03-1/401 | Cleaners Room - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12578 | ACTIVE | N | ND074-03-1/411 | Store - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12579 | ACTIVE | N | ND074-03-1/412 | Store - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12580 | ACTIVE | N | ND074-03-1/413 | Store - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12581 | ACTIVE | N | ND074-03-1/416 | Shower Room - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



ND074-03 - Highgate Service Control Centre - Highgate Depot

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 12582 | ACTIVE | N | ND074-03-1/417 | Toilet: Unisex - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12583 | ACTIVE | N | ND074-03-1/419 | Toilet: Female - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12584 | ACTIVE | N | ND074-03-1/420 | Toilet: Male - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12585 | ACTIVE | N | ND074-03-1/421 | Shower Room - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12586 | ACTIVE | N | ND074-03-1/576 | Stairs: Linear - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12587 | ACTIVE | N | ND074-03-1/661 | Switch Room - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12588 | ACTIVE | N | ND074-03-1/662 | Switch Room - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12589 | ACTIVE | N | ND074-03-1/663 | Switch Cupboard - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12590 | ACTIVE | N | ND074-03-1/664 | Switch Cupboard - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12591 | ACTIVE | N | ND074-03-1/665 | UPS Room - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12592 | ACTIVE | N | ND074-03-1/751 | Control Room - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12593 | ACTIVE | N | ND074-03-1/761 | Equipment Room - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12594 | ACTIVE | N | ND074-03-1/776 | Plant Room - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12595 | ACTIVE | N | ND074-03-1/781 | Transformer Room - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12596 | ACTIVE | N | ND074-03-1/782 | Transformer Room - Highgate Service Control Centre - Highgate Depot | | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



ND074-03 - Highgate Service Control Centre - Highgate Depot

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 12597 | ACTIVE | N | ND074-03-1/783 | Plant Room - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12598 | ACTIVE | N | ND074-03-1/791 | Service Area - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12599 | ACTIVE | N | ND074-03-1/792 | Service Area - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12600 | ACTIVE | N | ND074-03-1/793 | Service Area - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12601 | ACTIVE | N | ND074-03-1/801 | Training Room - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12602 | ACTIVE | N | ND074-03-1/802 | Incident Office - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12603 | ACTIVE | N | ND074-03-1/803 | Technical Support Office - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12604 | ACTIVE | N | ND074-03-1/804 | Server Room - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12605 | ACTIVE | N | ND074-03-1/805 | LUL Office - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12606 | ACTIVE | N | ND074-03-1/806 | LUL Office - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12607 | ACTIVE | N | ND074-03-1/807 | LUL Office - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12608 | ACTIVE | N | ND074-03-1/808 | Reception Office - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12609 | ACTIVE | N | ND074-03-1/810 | Union Office - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12610 | ACTIVE | N | ND074-03-1/901 | Technical Support Office - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12611 | ACTIVE | N | ND074-03-1/902 | Office - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



ND074-03 - Highgate Service Control Centre - Highgate Depot

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 12612 | ACTIVE | N | ND074-03-1/903 | Quiet Room - Highgate Service Control Centre - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

ND074-05 - Signals Building - Highgate Depot

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 12620 | ACTIVE | N | ND074-05-0/661 | Switch Room - Signals Building - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12621 | ACTIVE | N | ND074-05-0/711 | Relay Room - Signals Building - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

W001-01 - Station Building - North End Bull & Bush Disused Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 14536 | ACTIVE | N | W001-01-1/131 | LMR - Station Building - North End Bull & Bush Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14537 | ACTIVE | N | W001-01-1/236 | Lobby - Station Building - North End Bull & Bush Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14538 | ACTIVE | N | W001-01-1/261 | Platform 1 - Northern Line - Station Building - North End Bull & Bush Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14539 | ACTIVE | N | W001-01-1/781 | Substation Room - Station Building - North End Bull & Bush Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14540 | ACTIVE | N | W001-01-2/236 | Lobby - Station Building - North End Bull & Bush Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14541 | ACTIVE | N | W001-01-2/237 | Lobby - Station Building - North End Bull & Bush Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14542 | ACTIVE | N | W001-01-2/238 | Lobby - Station Building - North End Bull & Bush Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14543 | ACTIVE | N | W001-01-2/576 | Stairs: Linear - Station Building - North End Bull & Bush Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14544 | ACTIVE | N | W001-01-2/577 | Stairs: Linear - Station Building - North End Bull & Bush Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



W001-01 - Station Building - North End Bull & Bush Disused Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 14545 | ACTIVE | N | W001-01-2/661 | Switch Room - Station Building - North End Bull & Bush Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14546 | ACTIVE | N | W001-01-2/751 | Depot Control Room - Station Building - North End Bull & Bush Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14547 | ACTIVE | N | W001-01-3/711 | Relay Room - Station Building - North End Bull & Bush Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

W002-01 - Station Building - South Kentish Town Disused Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 14548 | ACTIVE | N | W002-01-1/236 | Passage - Station Building - South Kentish Town Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14549 | ACTIVE | N | W002-01-1/576 | Stairs: Spiral - Station Building - South Kentish Town Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14550 | ACTIVE | N | W002-01-2/081 | Lobby - Station Building - South Kentish Town Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14551 | ACTIVE | N | W002-01-2/661 | Switch Room - Station Building - South Kentish Town Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14552 | ACTIVE | N | W002-01-2/776 | Plant Room - Station Building - South Kentish Town Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

W003-01 - Station Building - City Road Disused Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 14553 | ACTIVE | N | W003-01-1/576 | Stairs: Linear - Station Building - City Road Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14554 | ACTIVE | N | W003-01-1/577 | Stairs: Linear - Station Building - City Road Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14555 | ACTIVE | N | W003-01-2/236 | Passage - Station Building - City Road Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14556 | ACTIVE | N | W003-01-3/236 | Passage - Station Building - City Road Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



W003-01 - Station Building - City Road Disused Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 14557 | ACTIVE | N | W003-01-3/237 | Passage - Station Building - City Road Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14558 | ACTIVE | N | W003-01-3/261 | Platform 1 - Northbound Fast - Northern Line - Station Building - City Road Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14559 | ACTIVE | N | W003-01-3/262 | Platform 2 - Southbound Fast - Northern Line - Station Building - City Road Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14560 | ACTIVE | N | W003-01-3/576 | Stairs: Linear - Station Building - City Road Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14561 | ACTIVE | N | W003-01-3/577 | Stairs: Linear - Station Building - City Road Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14562 | ACTIVE | N | W003-01-3/791 | Fan Room - Station Building - City Road Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

W006-01 - Station Building - Melton Street Disused Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 14579 | ACTIVE | N | W006-01-1/081 | Disused - Station Building - Melton Street Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14580 | ACTIVE | N | W006-01-1/236 | Lobby - Station Building - Melton Street Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14581 | ACTIVE | N | W006-01-1/576 | Stairs: Linear - Station Building - Melton Street Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14582 | ACTIVE | N | W006-01-1/577 | Stairs: Linear - Station Building - Melton Street Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14583 | ACTIVE | N | W006-01-2/901 | Disused - Station Building - Melton Street Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14584 | ACTIVE | N | W006-01-2/902 | Disused Room - Station Building - Melton Street Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14585 | ACTIVE | N | W006-01-2/903 | Disused Room - Station Building - Melton Street Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



W006-01 - Station Building - Melton Street Disused Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 14586 | ACTIVE | N | W006-01-A/236 | Passage - Station Building - Melton Street Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14587 | ACTIVE | N | W006-01-A/416 | Toilet: Unisex - Station Building - Melton Street Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14588 | ACTIVE | N | W006-01-A/417 | Toilet: Unisex - Station Building - Melton Street Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14589 | ACTIVE | N | W006-01-A/801 | Disused - Station Building - Melton Street Disused Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

X113-01 - Control Centre - Cobourg Street

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 14791 | ACTIVE | N | X113-01-1/081 | Lobby - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14792 | ACTIVE | N | X113-01-1/082 | Lobby - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14793 | ACTIVE | N | X113-01-1/236 | Passage - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14794 | ACTIVE | N | X113-01-1/238 | Passage - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14795 | ACTIVE | N | X113-01-1/331 | Office - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14796 | ACTIVE | N | X113-01-1/401 | Store - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14797 | ACTIVE | N | X113-01-1/411 | Store - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14798 | ACTIVE | N | X113-01-1/412 | Store - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14799 | ACTIVE | N | X113-01-1/551 | Yard - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



X113-01 - Control Centre - Cobourg Street

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 14800 | ACTIVE | N | X113-01-1/552 | Yard - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14801 | ACTIVE | N | X113-01-1/576 | Stairs: Linear - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14802 | ACTIVE | N | X113-01-1/577 | Stairs: Linear - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14803 | ACTIVE | N | X113-01-1/578 | Stairs: Linear - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14804 | ACTIVE | N | X113-01-1/661 | Switch Room - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14805 | ACTIVE | N | X113-01-1/711 | SER - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14806 | ACTIVE | N | X113-01-1/761 | Equipment Room - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14807 | ACTIVE | N | X113-01-1/762 | Equipment Room - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14808 | ACTIVE | N | X113-01-1/763 | Equipment Room - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14809 | ACTIVE | N | X113-01-1/781 | Transformer Room - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 41706 | INACTIVE | N | X113-01-1/781 | Transformer Room - Control Centre - Cobourg Street | Rope Gaskets | Asbestos | Known | | | | Fan Head House - Rope Gasket to ventilation ducting | | | | N | N |
| 14810 | ACTIVE | N | X113-01-1/782 | Transformer Room - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14811 | ACTIVE | N | X113-01-1/783 | Transformer Room - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14812 | ACTIVE | N | X113-01-1/784 | Transformer Room - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14813 | ACTIVE | N | X113-01-1/801 | Office - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



X113-01 - Control Centre - Cobourg Street

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 14814 | ACTIVE | N | X113-01-1/802 | Office - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14815 | ACTIVE | N | X113-01-2/236 | Passage - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14816 | ACTIVE | N | X113-01-2/406 | Store - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14817 | ACTIVE | N | X113-01-2/711 | SER - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14818 | ACTIVE | N | X113-01-2/712 | SER - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14819 | ACTIVE | N | X113-01-2/731 | CER - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14820 | ACTIVE | N | X113-01-2/761 | Equipment Room - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14821 | ACTIVE | N | X113-01-2/781 | Transformer Room - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14822 | ACTIVE | N | X113-01-2/782 | Transformer Room - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14823 | ACTIVE | N | X113-01-A/081 | Lobby - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14824 | ACTIVE | N | X113-01-A/082 | Lobby - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14825 | ACTIVE | N | X113-01-A/083 | Lobby - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14826 | ACTIVE | N | X113-01-A/236 | Passage - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14827 | ACTIVE | N | X113-01-A/316 | Locker Room - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14828 | ACTIVE | N | X113-01-A/411 | Office - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



X113-01 - Control Centre - Cobourg Street

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 14829 | ACTIVE | N | X113-01-A/416 | Toilet: Female - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14830 | ACTIVE | N | X113-01-A/551 | Passage - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14831 | ACTIVE | N | X113-01-A/761 | Equipment Room - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14832 | ACTIVE | N | X113-01-A/786 | Service Riser - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14833 | ACTIVE | N | X113-01-A/801 | Office - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14834 | ACTIVE | N | X113-01-A/802 | Office - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14835 | ACTIVE | N | X113-01-A/803 | Office - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14836 | ACTIVE | N | X113-01-A/804 | Office - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14837 | ACTIVE | N | X113-01-A/805 | Office - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14838 | ACTIVE | N | X113-01-B/047 | Kitchen - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14839 | ACTIVE | N | X113-01-B/081 | Office - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14840 | ACTIVE | N | X113-01-B/236 | Passage - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14841 | ACTIVE | N | X113-01-B/237 | Passage - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14842 | ACTIVE | N | X113-01-B/411 | Store - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14843 | ACTIVE | N | X113-01-B/416 | Passage - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



X113-01 - Control Centre - Cobourg Street

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|---------------------|---------------|--|----------|-----------|-----------------|--|-------------|------------|-------------|---------------------|-------------------|
| 14844 | ACTIVE | N | X113-01-B/417 | Toilet: Male - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14845 | ACTIVE | N | X113-01-B/418 | Toilet: Unisex - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14846 | ACTIVE | N | X113-01-B/576 | Stairs: Linear - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14847 | ACTIVE | N | X113-01-B/577 | Stairs: Linear - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14848 | ACTIVE | N | X113-01-B/578 | Stairs: Linear - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14849 | ACTIVE | N | X113-01-B/579 | Stairs: Linear - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14850 | ACTIVE | N | X113-01-B/581 | Stairs: Linear - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14851 | ACTIVE | N | X113-01-B/582 | Stairs: Linear - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14852 | ACTIVE | N | X113-01-B/589 | Stairs: Linear - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14853 | ACTIVE | N | X113-01-B/661 | Switch Cupboard - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14854 | ACTIVE | N | X113-01-B/756 | Station Control Room - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14855 | ACTIVE | N | X113-01-B/761 | Equipment Room - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 41705 | INACTIVE | N | X113-01-B/761 | Equipment Room - Control Centre - Cobourg Street | Cable Ducts: Cement | Asbestos | Known | | | | Cement Cable Ducts to outer ring wall | | | | N | N |
| 41709 | INACTIVE | N | X113-01-B/761 | Equipment Room - Control Centre - Cobourg Street | Boarding: AIB | Asbestos | Known | | | | Outer Ring - AIB boarding above ducts through outer wall | | | | N | N |
| 41704 | INACTIVE | N | X113-01-B/761/CLG-01 | Ceiling: Solid - 1 - Equipment Room - Control Centre - Cobourg Street | Boarding: AIB | Asbestos | Known | | | | AIB panels to false ceiling - no access above | | | | N | N |



Hazardous Material Asset Register - Summary



X113-01 - Control Centre - Cobourg Street

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|----------|-------------|----------------------|---|---------------------|---------------|--|----------|-----------|-----------------|---|-------------|------------|-------------|---------------------|-------------------|
| 14856 | ACTIVE | N | X113-01-B/762 | Equipment Room - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 41703 | INACTIVE | N | X113-01-B/762 | Equipment Room - Control Centre - Cobourg Street | Cable Ducts: Cement | Asbestos | Known | | | | Cement Cable Ducts to outer ring wall | | | | N | N |
| 41702 | INACTIVE | N | X113-01-B/762 | Equipment Room - Control Centre - Cobourg Street | Isolator Switches | Asbestos | Strongly Presumed | | | | Materials within fuse/switch boxes to outer wall | | | | N | N |
| 41710 | INACTIVE | N | X113-01-B/762 | Equipment Room - Control Centre - Cobourg Street | Boarding: AIB | Asbestos | Known | | | | Outer Ring - AIB Boarding above ducts through outer wall | | | | N | N |
| 41701 | INACTIVE | N | X113-01-B/762/CLG-01 | Ceiling: Solid - 1 - Equipment Room - Control Centre - Cobourg Street | Boarding: AIB | Asbestos | Known | | | | AIB panel to false ceiling | | | | N | N |
| 14857 | ACTIVE | N | X113-01-B/776 | Plant Room - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 41711 | INACTIVE | N | X113-01-B/776 | Plant Room - Control Centre - Cobourg Street | Other Boarding | Asbestos | Presumed | | | | Exterior to Control room walls, composite Roof and possible asbestos within | | | | N | N |
| 41708 | INACTIVE | N | X113-01-B/776/CLG-01 | Ceiling: Solid - 1 - Plant Room - Control Centre - Cobourg Street | Boarding: AIB | Asbestos | Known | | | | AIB board - Vertical boarding above false ceiling to perimeter of room. Partially covered with Supalux boarding | | | | Y | Y |
| 41707 | INACTIVE | N | X113-01-B/776/CLG-01 | Ceiling: Solid - 1 - Plant Room - Control Centre - Cobourg Street | Boarding: AIB | Asbestos | Known | | | | AIB board - horizontal boarding above false ceiling to perimeter of room | | | | Y | Y |
| 14858 | ACTIVE | N | X113-01-B/777 | Plant Room - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14859 | ACTIVE | N | X113-01-B/801 | Office - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14860 | ACTIVE | N | X113-01-B/802 | Office - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14861 | ACTIVE | N | X113-01-B/803 | Office - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14862 | ACTIVE | N | X113-01-B/804 | Office - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14863 | ACTIVE | N | X113-01-B/805 | Office - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14864 | ACTIVE | N | X113-01-B/806 | Office - Control Centre - Cobourg Street | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



X143-01 - Archer House - Oval Stn

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 14870 | ACTIVE | N | X143-01-1/081 | Lobby - Archer House - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14871 | ACTIVE | N | X143-01-1/291 | Office - Archer House - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14872 | ACTIVE | N | X143-01-1/416 | Toilet: Unisex - Office Building - Archer House | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14873 | ACTIVE | N | X143-01-1/576 | Stairs: Linear - Archer House - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14874 | ACTIVE | N | X143-01-1/661 | Switch Cupboard - Archer House - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14875 | ACTIVE | N | X143-01-1/801 | Office - Archer House - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14876 | ACTIVE | N | X143-01-A/047 | Kitchen - Archer House - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14877 | ACTIVE | N | X143-01-A/081 | Passage - Archer House - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14878 | ACTIVE | N | X143-01-A/082 | Lobby - Archer House - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14879 | ACTIVE | N | X143-01-A/291 | Office - Archer House - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14880 | ACTIVE | N | X143-01-A/311 | Office - Archer House - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14881 | ACTIVE | N | X143-01-A/411 | Store - Archer House - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14882 | ACTIVE | N | X143-01-A/412 | Store - Archer House - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14883 | ACTIVE | N | X143-01-A/416 | Toilet: Unisex - Office Building - Archer House | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 14884 | ACTIVE | N | X143-01-A/801 | Office - Archer House - Oval Stn | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



X164-01 - Office Building - Battersea ERU

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 15031 | ACTIVE | N | X164-01-1/081 | Lobby - Office Building - Battersea ERU | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15032 | ACTIVE | N | X164-01-1/236 | Passage - Office Building - Battersea ERU | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15033 | ACTIVE | N | X164-01-1/331 | Cupboard - Office Building - Battersea ERU | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15034 | ACTIVE | N | X164-01-1/332 | Gym Room - Office Building - Battersea ERU | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15035 | ACTIVE | N | X164-01-1/406 | Store - Office Building - Battersea ERU | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15036 | ACTIVE | N | X164-01-1/416 | Toilet: Unisex - Office Building - Battersea ERU | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15037 | ACTIVE | N | X164-01-1/417 | Shower Room - Office Building - Battersea ERU | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15038 | ACTIVE | N | X164-01-1/418 | Shower Room - Office Building - Battersea ERU | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15039 | ACTIVE | N | X164-01-1/576 | Stairs: Linear - Office Building - Battersea ERU | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15040 | ACTIVE | N | X164-01-1/577 | Stairs: Linear - Office Building - Battersea ERU | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15041 | ACTIVE | N | X164-01-1/761 | Equipment Room - Office Building - Battersea ERU | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15042 | ACTIVE | N | X164-01-1/901 | Workshop - Office Building - Battersea ERU | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15043 | ACTIVE | N | X164-01-A/047 | Kitchen - Office Building - Battersea ERU | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15044 | ACTIVE | N | X164-01-A/416 | Toilet: Female - Office Building - Battersea ERU | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15045 | ACTIVE | N | X164-01-A/417 | Toilet: Male - Office Building - Battersea ERU | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



X164-01 - Office Building - Battersea ERU

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 15046 | ACTIVE | N | X164-01-A/801 | DMT Office - DMT Office Building - Battersea ERU | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15047 | ACTIVE | N | X164-01-A/802 | Office - Office Building - Battersea ERU | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 15048 | ACTIVE | N | X164-01-A/803 | Office - Office Building - Battersea ERU | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

X656-01 - Electrical Building - Hendon Central To Brent Cross

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 8477 | ACTIVE | N | N032-02-0/711 | Relay Room - Electrical Building - Hendon Central To Brent Cross | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 8478 | ACTIVE | N | X656-01-0/781 | Substation Room - Electrical Building - Hendon Central To Brent Cross | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

ND021-01 - Depot Building - Edgware Depot

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 12514 | ACTIVE | N | ND021-01-1/081 | Lobby - Depot Building - Edgware Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12515 | ACTIVE | N | ND021-01-1/332 | Mess Room - Depot Building - Edgware Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12516 | ACTIVE | N | ND021-01-1/420 | Toilet: Unisex - Depot Building - Edgware Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12517 | ACTIVE | N | ND021-01-1/561 | Workshop - Depot Building - Edgware Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12518 | ACTIVE | N | ND021-01-1/573 | Equipment Room - Depot Building - Edgware Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12519 | ACTIVE | N | ND021-01-1/661 | Switch Room - Depot Building - Edgware Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



ND021-01 - Depot Building - Edgware Depot

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|---|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 12520 | ACTIVE | N | ND021-01-1/662 | Switch Room - Depot Building - Edgware Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12521 | ACTIVE | N | ND021-01-1/663 | Switch Room - Depot Building - Edgware Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12522 | ACTIVE | N | ND021-01-1/804 | ISS Office- Depot Building - Edgware Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12523 | ACTIVE | N | ND021-01-2/081 | Lobby - Train Crew Accommodation - Depot Building - Edgware Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12524 | ACTIVE | N | ND021-01-2/083 | Lobby - Train Crew Accommodation - Depot Building - Edgware Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12525 | ACTIVE | N | ND021-01-2/316 | Locker Room - Train Crew Accommodation - Depot Building - Edgware Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12526 | ACTIVE | N | ND021-01-2/317 | Locker Room - Train Crew Accommodation - Depot Building - Edgware Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12527 | ACTIVE | N | ND021-01-2/731 | CER - Train Crew Accommodation - Depot Building - Edgware Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12528 | ACTIVE | N | ND021-01-2/786 | Switch Room - Train Crew Accommodation - Depot Building - Edgware Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12529 | ACTIVE | N | ND021-01-2/787 | Switch Room - Train Crew Accommodation - Depot Building - Edgware Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12530 | ACTIVE | N | ND021-01-2/801 | Training Room - Train Crew Accommodation - Depot Building - Edgware Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12531 | ACTIVE | N | ND021-01-2/802 | SCR - Train Crew Accommodation - Depot Building - Edgware Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12532 | ACTIVE | N | ND021-01-2/803 | Training Room - Train Crew Accommodation - Depot Building - Edgware Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12533 | ACTIVE | N | ND021-01-2/804 | SCR - Train Crew Accommodation - Depot Building - Edgware Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12534 | ACTIVE | N | ND021-01-2/805 | Store - Train Crew Accommodation - Depot Building - Edgware Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |



Hazardous Material Asset Register - Summary



ND074-01 - Depot Building - Highgate Depot

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 12551 | ACTIVE | N | ND074-01-1/561 | Workshop - Depot Building - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |

ND074-04 - Gate House - Highgate Depot

| Ref. | Status | Maint. Line | Location/Asset Code | Location/Asset Description | Area | Material Type | Material Status | Start(m) | Finish(m) | Linear Position | Notes | Qty. Metres | Qty. Units | Report Ref. | Above False Ceiling | Below False Floor |
|-------|--------|-------------|---------------------|--|-----------------|---------------|--|----------|-----------|-----------------|-------|-------------|------------|-------------|---------------------|-------------------|
| 12613 | ACTIVE | N | ND074-04-0/081 | Lobby - Gate House - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12614 | ACTIVE | N | ND074-04-0/416 | Toilet: Unisex - Gate House - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12615 | ACTIVE | N | ND074-04-0/481 | Store - Gate House - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12616 | ACTIVE | N | ND074-04-0/482 | Store - Gate House - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12617 | ACTIVE | N | ND074-04-0/661 | Switch Cupboard - Gate House - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12618 | ACTIVE | N | ND074-04-0/751 | Station Control Room - Gate House - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |
| 12619 | ACTIVE | N | ND074-04-0/786 | Service Area - Gate House - Highgate Depot | Stations: Rooms | Asbestos | Room: Not Surveyed – Asbestos Presumed | | | | | | | | | |