



Hazardous Material Asset Register - Summary



Run date: 19/08/2024

Line: Piccadilly

Risk Assessment Status: Active, Inactive
Hazardous Material Status: All
Hazardous Material Type: All

D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4974	ACTIVE	P	D205-00-1/001	Booking Hall - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23256	ACTIVE	P	D205-00-1/001	Booking Hall - Station Building - Acton Town Stn	Lead/Leading	Lead Paint/Lead	Known				Above shutters - green/grey gloss 2m x 0.2m - entrance to main station. Thickness : 0.12mm Analysis : 5.24%					
4975	ACTIVE	P	D205-00-1/011	Ticket Office - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4976	ACTIVE	P	D205-00-1/012	Ticket Office - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23854	ACTIVE	P	D205-00-1/012	Ticket Office - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
4977	ACTIVE	P	D205-00-1/021	POM - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4978	ACTIVE	P	D205-00-1/022	POM - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23257	ACTIVE	P	D205-00-1/022	POM - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
4979	ACTIVE	P	D205-00-1/031	Mess Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4980	ACTIVE	P	D205-00-1/032	Mess Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos				New Construction					
23258	INACTIVE	P	D205-00-1/032	Mess Room - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
4981	ACTIVE	P	D205-00-1/036	Toilet - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4982	ACTIVE	P	D205-00-1/041	Mess Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46805	ACTIVE	p	D205-00-1/041	Mess Room - Station Building - Acton Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				Undercroft Area to TCA Cables - SP Debris to Spoil - P No access at time of re-inspection 2024					
4983	ACTIVE	p	D205-00-1/047	Kitchen - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42211	ACTIVE	p	D205-00-1/047	Kitchen - Station Building - Acton Town Stn	Lagging	Asbestos	Sampled – Not Detected				Lagging - 10m² to AC ducting within kitchen area	10			N	N
42210	ACTIVE	p	D205-00-1/047	Kitchen - Station Building - Acton Town Stn	Lead/Leading	Lead Paint/Lead	Sampled – Not Detected				Paint - 15Lm to lintel within kitchen area	15			N	N
4984	ACTIVE	p	D205-00-1/049	Kitchen - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23262	ACTIVE	p	D205-00-1/049/ WAL-002	Wall: Internal - 2 - Kitchen - Station Building - Acton Town Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heaters - foam insulation		1			
23263	ACTIVE	p	D205-00-1/049/ WAL-003	Wall: Internal - 3 - Kitchen - Station Building - Acton Town Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heaters - foam insulation		1			
4985	ACTIVE	p	D205-00-1/050	Store - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4986	ACTIVE	p	D205-00-1/056	Toilet: Unisex - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4987	ACTIVE	p	D205-00-1/071	Circulation Area - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4988	ACTIVE	p	D205-00-1/081	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4989	ACTIVE	p	D205-00-1/083	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4990	ACTIVE	p	D205-00-1/084	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4991	ACTIVE	p	D205-00-1/085	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4992	ACTIVE	p	D205-00-1/086	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
45323	ACTIVE	P	D205-00-1/086	Lobby - Station Building - Acton Town Stn	Cement Cowlings/ Flues	Asbestos	Not Found during Inspection				Roof Above - 0.4m² Cement flue cap & flue on top of chimney Not Found on Re-Inspection				N	N
4993	ACTIVE	P	D205-00-1/087	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4994	ACTIVE	P	D205-00-1/088	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4995	ACTIVE	P	D205-00-1/089	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23269	ACTIVE	P	D205-00-1/089/ FLR-01	Floor - 1 - Lobby - Station Building - Acton Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Old vinyl type surface on solid					
23271	ACTIVE	P	D205-00-1/089/ WAL-002	Wall: Internal - 2 - Lobby - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Solid above false ceiling				Yes	
23270	ACTIVE	P	D205-00-1/089/ WAL-002	Wall: Internal - 2 - Lobby - Station Building - Acton Town Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
4996	ACTIVE	P	D205-00-1/090	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46804	ACTIVE	P	D205-00-1/090	Lobby - Station Building - Acton Town Stn	Control Panels	Asbestos	Presumed				Control Panel - Presumed asbestos components witihin		1			
23273	INACTIVE	P	D205-00-1/090/ CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Above false ceiling					
42257	ACTIVE	P	D205-00-1/090/ CLG-02 80942754	Ceiling: Solid - 2 - Lobby - Station Building - Acton Town Stn Ceiling: Solid	Mastic	Asbestos	Presumed				Mastic to Ducting This area been refurbished					
23272	ACTIVE	P	D205-00-1/090/ WAL-001 80856053	Wall: Internal - 1 - Lobby - Station Building - Acton Town Stn Wall: Internal	Void	Asbestos	No Access: Presumed				Riser - Wooden Panel - No Access					
24027	ACTIVE	P	D205-00-1/090/ WAL-001 80856053	Wall: Internal - 1 - Lobby - Station Building - Acton Town Stn Wall: Internal	Other Boarding	Asbestos	Presumed				High level boxing					
4997	ACTIVE	P	D205-00-1/091	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4998	ACTIVE	P	D205-00-1/092	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23275	ACTIVE	P	D205-00-1/092/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, copper pipes, armour flex lagging, plastic cables, wood above false ceiling				Yes	
23274	ACTIVE	P	D205-00-1/092/FLR-01	Floor - 1 - Lobby - Station Building - Acton Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				2m Marley tiles on solid					
4999	ACTIVE	P	D205-00-1/093	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23276	ACTIVE	P	D205-00-1/093	Lobby - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
5000	ACTIVE	P	D205-00-1/094	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23277	ACTIVE	P	D205-00-1/094	Lobby - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
5001	ACTIVE	P	D205-00-1/095	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23278	ACTIVE	P	D205-00-1/095	Lobby - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
5002	ACTIVE	P	D205-00-1/096	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23856	ACTIVE	P	D205-00-1/096	Lobby - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
23279	ACTIVE	P	D205-00-1/136	Lift Shaft - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
23280	ACTIVE	P	D205-00-1/137	Lift Shaft - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
5003	ACTIVE	P	D205-00-1/201	Passage - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5004	ACTIVE	P	D205-00-1/202	Passage - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5005	ACTIVE	P	D205-00-1/203	Passage - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5006	ACTIVE	P	D205-00-1/236	Passage - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5007	ACTIVE	P	D205-00-1/237	Passage - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23284	ACTIVE	P	D205-00-1/237	Passage - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Cupboard					
23282	ACTIVE	P	D205-00-1/237/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Acton Town Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
23283	ACTIVE	P	D205-00-1/237/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Above false ceiling					
23281	ACTIVE	P	D205-00-1/237/FLR-01	Floor - 1 - Passage - Station Building - Acton Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
23857	ACTIVE	P	D205-00-1/237/FLR-01 80854987	Floor - 1 - Passage - Station Building - Acton Town Stn Floor	Void	Asbestos	Surveyed – Not Detected				Beneath lino - solid under Lino					
5008	ACTIVE	P	D205-00-1/238	Passage - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5009	ACTIVE	P	D205-00-1/239	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5010	ACTIVE	P	D205-00-1/247	Kitchen - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5011	ACTIVE	P	D205-00-1/281	Mess Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23286	ACTIVE	P	D205-00-1/281/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Acton Town Stn	Glazing Rope	Asbestos	Strongly Presumed				Glass ceiling - rope seals					
23858	ACTIVE	P	D205-00-1/281/FLR-01	Floor - 1 - Office - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Beneath Lino					
23285	ACTIVE	P	D205-00-1/281/FLR-01	Floor - 1 - Office - Station Building - Acton Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
5012	ACTIVE	P	D205-00-1/291	Office - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23289	ACTIVE	P	D205-00-1/291	Office - Station Building - Acton Town Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater x 2 - Foam insulation		2			
23288	ACTIVE	P	D205-00-1/291/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Acton Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux. Boarding access to skylight - plasterboard					



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23859	ACTIVE	P	D205-00-1/291/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
23287	ACTIVE	P	D205-00-1/291/FLR-01	Floor - 1 - Office - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Beneath carpet					
5013	ACTIVE	P	D205-00-1/311	Interview Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23290	ACTIVE	P	D205-00-1/311	Interview Room - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
5014	ACTIVE	P	D205-00-1/316	Locker Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23293	ACTIVE	P	D205-00-1/316	Locker Room - Station Building - Acton Town Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - foam insulation		1			
23291	ACTIVE	P	D205-00-1/316/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Acton Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
23292	ACTIVE	P	D205-00-1/316/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
5015	ACTIVE	P	D205-00-1/317	Locker Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24028	ACTIVE	P	D205-00-1/317	Locker Room - Station Building - Acton Town Stn	Lead/Leading	Lead Paint/Lead	Removed				Locker - dark green matt - 2m ² . Thickness : Dust Analysis : 4.03% Removed by others					
23296	ACTIVE	P	D205-00-1/317	Locker Room - Station Building - Acton Town Stn	Lead/Leading	Lead Paint/Lead	Known				Locker - dark green matt - 2m ² . Thickness : Dust Analysis : 4.03%					
5016	ACTIVE	P	D205-00-1/318	Locker Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23297	ACTIVE	P	D205-00-1/318/CLG-01	Ceiling: Solid - 1 - Locker Room - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Solid above polystyrene ceiling				Yes	
5017	ACTIVE	P	D205-00-1/319	Locker Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5018	ACTIVE	P	D205-00-1/320	Locker Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23298	ACTIVE	P	D205-00-1/320	Locker Room - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5019	ACTIVE	P	D205-00-1/331	Mess Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23301	ACTIVE	P	D205-00-1/331	Mess Room - Station Building - Acton Town Stn	Bitumen	Asbestos	Surveyed – Not Detected				Sink - Acoustic panel		1			
23300	ACTIVE	P	D205-00-1/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above acoustic tiles				Yes	
5020	ACTIVE	P	D205-00-1/332	Office - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5021	ACTIVE	P	D205-00-1/333	Mess Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23305	ACTIVE	P	D205-00-1/333/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Above plasterboard					
23304	ACTIVE	P	D205-00-1/333/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Acton Town Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
23302	ACTIVE	P	D205-00-1/333/FLR-01	Floor - 1 - Mess Room - Station Building - Acton Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino on solid					
23303	ACTIVE	P	D205-00-1/333/WAL-003	Wall: Internal - 3 - Mess Room - Station Building - Acton Town Stn	Bitumen	Asbestos	Surveyed – Not Detected				Sink - Acoustic panel		1			
5022	ACTIVE	P	D205-00-1/334	Mess Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23308	ACTIVE	P	D205-00-1/334	Mess Room - Station Building - Acton Town Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - Foam insulation		1			
23307	ACTIVE	P	D205-00-1/334/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux				Yes	
23306	ACTIVE	P	D205-00-1/334/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Acton Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
5023	ACTIVE	P	D205-00-1/335	Mess Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46802	ACTIVE	P	D205-00-1/335	Mess Room - Station Building - Acton Town Stn	Void	Asbestos	Presumed				No Access - Above False Ceiling - Presumed					
5024	ACTIVE	P	D205-00-1/341	Mess Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23312	ACTIVE	P	D205-00-1/341	Mess Room - Station Building - Acton Town Stn	Bitumen	Asbestos	Surveyed – Not Detected				Sink - Acoustic panel		1			
23311	ACTIVE	P	D205-00-1/341/FLR-01 80855072	Floor - 1 - Mess Room - Station Building - Acton Town Stn Floor	Void	Asbestos	Surveyed – Not Detected				Beneath vinyl tiles - Solid					
23310	ACTIVE	P	D205-00-1/341/FLR-01	Floor - 1 - Mess Room - Station Building - Acton Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected									
5025	ACTIVE	P	D205-00-1/342	Locker Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23314	ACTIVE	P	D205-00-1/342/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Above false ceiling					
23862	ACTIVE	P	D205-00-1/342/DOR-01	Door - 1 - Locker Room - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Concrete and steel above tiles, carpet and fibreboard					
23316	ACTIVE	P	D205-00-1/342/FLR-01 80855079	Floor - 1 - Locker Room - Station Building - Acton Town Stn Floor	Void	Asbestos	No Access: Presumed				Beneath panel below doormat					
23861	ACTIVE	P	D205-00-1/342/FLR-01	Floor - 1 - Locker Room - Station Building - Acton Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				10m Marley tiles					
23313	INACTIVE	P	D205-00-1/342/FLR-01	Floor - 1 - Locker Room - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Beneath Marley tiles					
23315	ACTIVE	P	D205-00-1/342/FLR-01	Floor - 1 - Locker Room - Station Building - Acton Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected									
42263	ACTIVE	P	D205-00-1/342/WAL-002 80855075	Wall: Internal - 2 - Locker Room - Station Building - Acton Town Stn Wall: Internal	Void	Asbestos	No Access: Presumed				Wooden riser to corner of walls 2/3 - no access					
5026	ACTIVE	P	D205-00-1/343	Mess Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23317	ACTIVE	P	D205-00-1/343/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Acton Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				10m Marley tiles					
23318	INACTIVE	P	D205-00-1/343/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Beneath Marley tiles					
5027	ACTIVE	P	D205-00-1/406	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos				New Construction					
23319	INACTIVE	P	D205-00-1/406	Lobby - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5028	ACTIVE	P	D205-00-1/411	Store - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23320	ACTIVE	P	D205-00-1/411/FLR-01	Floor - 1 - Store - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Beneath fixed lino covering					
5029	ACTIVE	P	D205-00-1/412	Store - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23153	ACTIVE	P	D205-00-1/412/FLR-01	Floor - 1 - Store - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Solid beneath carpet					Yes
5030	ACTIVE	P	D205-00-1/414	Office - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45324	ACTIVE	P	D205-00-1/414/WAL-001	Wall: Internal - 1 - Office - Station Building - Acton Town Stn	Cable Duct: Other	Asbestos	Presumed				Cable Duct				N	N
5031	ACTIVE	P	D205-00-1/417	Toilet: Female - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23158	ACTIVE	P	D205-00-1/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above acoustic tiles, plasterboard (access to skylight)				Yes	
24001	ACTIVE	P	D205-00-1/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Acton Town Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Acoustic tiles					
5032	ACTIVE	P	D205-00-1/418	Toilet: Male - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46803	ACTIVE	P	D205-00-1/418	Toilet: Male - Station Building - Acton Town Stn	Void	Asbestos	Presumed				No Access to Floor Hatches - Presumed					
5033	ACTIVE	P	D205-00-1/419	Shower Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23166	ACTIVE	P	D205-00-1/419/CLG-01	Ceiling: Solid - 1 - Shower Room - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Above false ceiling					
23163	ACTIVE	P	D205-00-1/419/FLR-01	Floor - 1 - Shower Room - Station Building - Acton Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
23164	ACTIVE	P	D205-00-1/419/FLR-01	Floor - 1 - Shower Room - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Parquet flooring beneath Lino					Yes



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23165	ACTIVE	P	D205-00-1/419/WAL-001	Wall: Internal - 1 - Shower Room - Station Building - Acton Town Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
5034	ACTIVE	P	D205-00-1/420	Toilet: Unisex - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5035	ACTIVE	P	D205-00-1/421	Toilet: Male - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5036	ACTIVE	P	D205-00-1/422	Toilet: Female - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23171	ACTIVE	P	D205-00-1/422/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, breeze block, plastic cables, lagged water pipe (rock wool), conduit above false ceiling				Yes	
23170	ACTIVE	P	D205-00-1/422/FLR-01	Floor - 1 - Toilet - Station Building - Acton Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				3.5m Marley tiles					
5037	ACTIVE	P	D205-00-1/423	Toilet: Unisex - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos				New Construction					
23844	INACTIVE	P	D205-00-1/423	Toilet: Unisex - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
5038	ACTIVE	P	D205-00-1/424	Toilet: Unisex - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23172	ACTIVE	P	D205-00-1/424	Toilet: Unisex - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
5039	ACTIVE	P	D205-00-1/426	Toilet: Male - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45325	ACTIVE	P	D205-00-1/426/WAL-003	Wall: Internal - 3 - Toilet - Station Building - Acton Town Stn		Asbestos	Known				Lining to LTB Heating	1			N	N
23610	ACTIVE	P	D205-00-1/426/WAL-003	Wall: Internal - 3 - Toilet - Station Building - Acton Town Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - Foam insulation		1			
5040	ACTIVE	P	D205-00-1/427	Toilet: Male - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23174	ACTIVE	P	D205-00-1/427/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Concrete / Roof Light above false ceiling				Yes	



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23173	ACTIVE	P	D205-00-1/427/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Acton Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Part Supalux					
46801	ACTIVE	P	D205-00-1/427/FLR-01	Floor - 1 - Toilet - Station Building - Acton Town Stn	Void	Asbestos	Presumed				No Access - Below drainage hatch					
23845	ACTIVE	P	D205-00-1/427/WAL-001	Wall: Internal - 1 - Toilet - Station Building - Acton Town Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - Foam insulation		1			
5041	ACTIVE	P	D205-00-1/428	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5042	ACTIVE	P	D205-00-1/429	Toilet: Unisex - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos				New Construction					
23846	INACTIVE	P	D205-00-1/429	Toilet: Unisex - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
5043	ACTIVE	P	D205-00-1/451	Tenancy - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				No Access 21 Oct 2014					
23178	ACTIVE	P	D205-00-1/451	Tenancy - Station Building - Acton Town Stn	No Access	Asbestos	No Access: Presumed				No Access Not Surveyed Keys not provided by CSS at time of Re-inspection 2024					
5044	ACTIVE	P	D205-00-1/452	Tenancy - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
23179	ACTIVE	P	D205-00-1/452/FLR-01	Floor - 1 - Tenancy - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Beneath floor boards					
5045	ACTIVE	P	D205-00-1/453	Tenancy - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23180	ACTIVE	P	D205-00-1/453/FLR-01	Floor - 1 - Tenancy - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath parquet flooring					Yes
5046	ACTIVE	P	D205-00-1/454	Tenancy - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23181	ACTIVE	P	D205-00-1/454/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Acton Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux foam tiles					
23182	ACTIVE	P	D205-00-1/454/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Above Supalux foam tiles					
23183	ACTIVE	P	D205-00-1/454/FLR-01	Floor - 1 - Tenancy - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Beneath parquet flooring					



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5047	ACTIVE	P	D205-00-1/455	Tenancy - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45326	ACTIVE	P	D205-00-1/455	Tenancy - Station Building - Acton Town Stn		Asbestos	Not Found during Inspection				Walls 1, 2, 3 - Partitions, no access No Access on Re-Inspection - Tenancy Occupied				N	N
23188	ACTIVE	P	D205-00-1/455	Tenancy - Station Building - Acton Town Stn	Bitumen	Asbestos	Surveyed – Not Detected				Sinks acoustic panels		1			
23184	ACTIVE	P	D205-00-1/455/FLR-01	Floor - 1 - Tenancy - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Beneath parquet flooring					
23185	ACTIVE	P	D205-00-1/455/WAL-001	Wall: Internal - 1 - Tenancy - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Behind partitions					
23186	ACTIVE	P	D205-00-1/455/WAL-002	Wall: Internal - 2 - Tenancy - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Behind partitions					
23187	ACTIVE	P	D205-00-1/455/WAL-003	Wall: Internal - 3 - Tenancy - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Behind partitions					
5048	ACTIVE	P	D205-00-1/456	Tenancy - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23200	ACTIVE	P	D205-00-1/456/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Tenancy Control Room - solid & wooden skirting above false ceiling				Yes	
23199	ACTIVE	P	D205-00-1/456/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Acton Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Tenancy Control Room - Supalux, wooden boarding					
23198	ACTIVE	P	D205-00-1/456/FLR-01	Floor - 1 - Tenancy - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Tenancy Control Room - Beneath parquet flooring Keys not provided by CSS at time of Re-inspection 2024					Yes
23192	ACTIVE	P	D205-00-1/456/FLR-01	Floor - 1 - Tenancy - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Tenancy Office Room - Beneath wooden floor Keys not provided by CSS at time of Re-inspection 2024					Yes
23197	ACTIVE	P	D205-00-1/456/FLR-01	Floor - 1 - Tenancy - Station Building - Acton Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Tenancy Control Room - Parquet with Lino above. Wooden boxing near fuse box by wall 1					
23189	ACTIVE	P	D205-00-1/456/FLR-01	Floor - 1 - Tenancy - Station Building - Acton Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
24002	ACTIVE	P	D205-00-1/456/FLR-01	Floor - 1 - Tenancy - Station Building - Acton Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Tenancy Office Room - Lino on wood					
23195	ACTIVE	P	D205-00-1/456/FLR-01	Floor - 1 - Tenancy - Station Building - Acton Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Tenancy Kitchen Area - Lino on wood boards					



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23196	ACTIVE	P	D205-00-1/456/FLR-01	Floor - 1 - Tenancy - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Tenancy Kitchen Area - Beneath wooden floor Keys not provided by CSS at time of Re-inspection 2024					Yes
23847	ACTIVE	P	D205-00-1/456/WAL-001	Wall: Internal - 1 - Tenancy - Station Building - Acton Town Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Tenancy Kitchen Area - Plasterboard partition no access behind					
23193	ACTIVE	P	D205-00-1/456/WAL-001	Wall: Internal - 1 - Tenancy - Station Building - Acton Town Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Tenancy Office Room - Plasterboard Partitions					
23190	ACTIVE	P	D205-00-1/456/WAL-002	Wall: Internal - 2 - Tenancy - Station Building - Acton Town Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard Partitions					
23191	ACTIVE	P	D205-00-1/456/WAL-003	Wall: Internal - 3 - Tenancy - Station Building - Acton Town Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard Partitions					
23194	ACTIVE	P	D205-00-1/456/WAL-004	Wall: Internal - 4 - Tenancy - Station Building - Acton Town Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Tenancy Office Room - Plasterboard Partitions					
5049	ACTIVE	P	D205-00-1/457	Tenancy - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23202	ACTIVE	P	D205-00-1/457	Tenancy - Station Building - Acton Town Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No access above ceiling into void					
5050	ACTIVE	P	D205-00-1/458	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5051	ACTIVE	P	D205-00-1/459	Tenancy - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5052	ACTIVE	P	D205-00-1/460	Tenancy - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5053	ACTIVE	P	D205-00-1/461	SER - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5054	ACTIVE	P	D205-00-1/462	Tenancy - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
23204	ACTIVE	P	D205-00-1/462/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Acton Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
23849	ACTIVE	P	D205-00-1/462/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Y	



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23203	ACTIVE	P	D205-00-1/462/FLR-01	Floor - 1 - Tenancy - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Carpet on solid					Yes
5055	ACTIVE	P	D205-00-1/463	Tenancy - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
23205	ACTIVE	P	D205-00-1/463/FLR-01	Floor - 1 - Tenancy - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Beneath wooden floor					Y
23206	ACTIVE	P	D205-00-1/463/WAL-001	Wall: Internal - 1 - Tenancy - Station Building - Acton Town Stn	Other Electrical Boxes	Asbestos	No Access: Presumed				Fuse box Asbestos Components – Strongly Presumed within		1			
5056	ACTIVE	P	D205-00-1/464	ATM - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23479	INACTIVE	P	D205-00-1/464	ATM - Station Building - Acton Town Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No access					
23201	ACTIVE	P	D205-00-1/464	ATM - Station Building - Acton Town Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed Keys not provided by CSS at time of Re-inspection 2024					
5057	ACTIVE	P	D205-00-1/531	Office - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5058	ACTIVE	P	D205-00-1/532	DMT Office - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23480	ACTIVE	P	D205-00-1/532	DMT Office - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
5059	ACTIVE	P	D205-00-1/576	Stairs: Linear - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46283	INACTIVE	P	D205-00-1/576	Stairs: Linear - Station Building - Acton Town Stn	Westing house Boxes	Asbestos	Presumed				1x westinghouse box to wall by metal floor gate		1		N	N
42276	ACTIVE	P	D205-00-1/576	Stairs: Linear - Station Building - Acton Town Stn	Cable Ducts: Bitumen	Asbestos	Strongly Presumed				Bitumen Cable Ducts end of Platform 5 to Substation UK Power Asset		13			
42275	ACTIVE	P	D205-00-1/576	Stairs: Linear - Station Building - Acton Town Stn	Isolator Switches	Asbestos	Strongly Presumed				1no Switch Box - Under Metal Grate on Platform 5 Disused Platform Area bottom of Stairs 1/576 Asbestos Components – Strongly Presumed within		1			



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42278	ACTIVE	P	D205-00-1/576	Stairs: Linear - Station Building - Acton Town Stn	Boarding: AIB	Asbestos	Presumed				Potential Asbestos Contamination - AIB Debris West End removed by Econ 11/11/2011, East End removed by UKPN/Forest 2012? Invert to Disused Platform 5 Disused Platform Area bottom of Stairs 1/576 No access at time of re-inspection 2024			R20476		Y
42273	ACTIVE	P	D205-00-1/576	Stairs: Linear - Station Building - Acton Town Stn	Cable: Sheath	Asbestos	Known				Woven cable sheath - J-Hanger 7 - 1x40mm, 1x20 Cable runs from ramp end to accommodation blocks Disused Platform Area bottom of Stairs1/576 Not located on re-inspection 2024		2			
5060	ACTIVE	P	D205-00-1/577	Stairs: Linear - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23482	ACTIVE	P	D205-00-1/577/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Acton Town Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
23483	ACTIVE	P	D205-00-1/577/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Above plasterboard					
23481	ACTIVE	P	D205-00-1/577/FLR-01	Floor - 1 - Station Building - Acton Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino, marble tiles					
5061	ACTIVE	P	D205-00-1/578	Stairs: Linear - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5062	ACTIVE	P	D205-00-1/579	Stairs: Linear - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5063	ACTIVE	P	D205-00-1/601	Stairs: Linear - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5064	ACTIVE	P	D205-00-1/602	Stairs: Linear - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5065	ACTIVE	P	D205-00-1/603	Stairs: Linear - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23484	ACTIVE	P	D205-00-1/603/WDW-01	Window - 1 - Linear Stairs - Station Building - Acton Town Stn	Lead/Leading	Lead Paint/Lead	Known				Window frames - white gloss. Thickness : 0.46mm Analysis : 15%. Upon HMU re inspection Oct 2014 - it was noted that it has been painted blue. See also HM42279;					



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5066	ACTIVE	P	D205-00-1/604	Stairs: Linear - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5067	ACTIVE	P	D205-00-1/661	Switch Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5068	ACTIVE	P	D205-00-1/662	Switch Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5069	ACTIVE	P	D205-00-1/663	Switch Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23485	ACTIVE	P	D205-00-1/663	Switch Room - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
5070	ACTIVE	P	D205-00-1/664	Switch Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23486	ACTIVE	P	D205-00-1/664	Switch Room - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
5071	ACTIVE	P	D205-00-1/746	SCR - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5072	ACTIVE	P	D205-00-1/776	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5073	INACTIVE	P	D205-00-1/801	Office - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5074	ACTIVE	P	D205-00-1/802	Office - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5075	ACTIVE	P	D205-00-1/803	RCI Office - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5076	ACTIVE	P	D205-00-1/804	Locker Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5077	ACTIVE	P	D205-00-1/806	Office - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23494	ACTIVE	P	D205-00-1/806/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Conduit, concrete ceiling, plastic cables above false ceiling				Yes	



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23492	ACTIVE	P	D205-00-1/806/FLR-01	Floor - 1 - Office - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Screed, latex beneath carpet tiles					Yes
23493	ACTIVE	P	D205-00-1/806/WAL-003	Wall: Internal - 3 - Office - Station Building - Acton Town Stn		Asbestos	Surveyed – Not Detected				Superlux (high level boarding 8"x6")					
5078	ACTIVE	P	D205-00-1/901	Equipment Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5079	ACTIVE	P	D205-00-1/902	Switch Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5080	ACTIVE	P	D205-00-1/903	Cupboard - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23497	ACTIVE	P	D205-00-1/903	Cupboard - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
5081	ACTIVE	P	D205-00-1/904	Office - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5082	ACTIVE	P	D205-00-1/905	Locker Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5083	ACTIVE	P	D205-00-1/906	Locker Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5084	ACTIVE	P	D205-00-1/907	Kitchen - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos				New Construction					
23498	INACTIVE	P	D205-00-1/907	Kitchen - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
5085	ACTIVE	P	D205-00-2/081	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5086	ACTIVE	P	D205-00-2/082	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5087	ACTIVE	P	D205-00-2/083	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5088	ACTIVE	P	D205-00-2/084	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23881	ACTIVE	P	D205-00-2/084/WAL-001	Wall: Internal - 1 - Lobby - Station Building - Acton Town Stn		Asbestos	Surveyed – Not Detected				Supalux Board					
23503	ACTIVE	P	D205-00-2/084/WAL-001	Wall: Internal - 1 - Lobby - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
23505	ACTIVE	P	D205-00-2/084/WAL-002	Wall: Internal - 2 - Lobby - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
23504	ACTIVE	P	D205-00-2/084/WAL-002	Wall: Internal - 2 - Lobby - Station Building - Acton Town Stn		Asbestos	Surveyed – Not Detected				Supalux Board					
5089	ACTIVE	P	D205-00-2/085	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23506	ACTIVE	P	D205-00-2/085	Lobby - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
5090	ACTIVE	P	D205-00-2/086	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23882	ACTIVE	P	D205-00-2/086	Lobby - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
5091	ACTIVE	P	D205-00-2/087	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23507	ACTIVE	P	D205-00-2/087	Lobby - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
5092	ACTIVE	P	D205-00-2/236	Passage - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5093	ACTIVE	P	D205-00-2/237	Passage - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5094	ACTIVE	P	D205-00-2/238	Lobby - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5095	ACTIVE	P	D205-00-2/261	Platform 1 - Eastbound Local - District Line - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45329	ACTIVE	P	D205-00-2/261	Platform 1 - Eastbound Local - District Line - Station Building - Acton Town Stn	Other Electrical Boxes	Asbestos	Presumed				Asbestos components within Signal Boxes / Lamp to Columns & Canopy throughout Asbestos Components – Presumed within				N	N



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23512	ACTIVE	P	D205-00-2/261	Platform 1 - Eastbound Local - District Line - Station Building - Acton Town Stn	Glazing Rope	Asbestos	Known				70LM Glazing bars, rope seals					
23513	ACTIVE	P	D205-00-2/261	Platform 1 - Eastbound Local - District Line - Station Building - Acton Town Stn	Lead/Leading	Lead Paint/Lead	Known				RSJ End of platform 1 station end - Green, grey gloss - 10m². Thickness : 0.91mm Analysis : 13.8%					
23511	ACTIVE	P	D205-00-2/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Below various manhole covers					
5096	ACTIVE	P	D205-00-2/262	Platform 2 - Eastbound Fast - Piccadilly Line - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23514	ACTIVE	P	D205-00-2/262	Platform 2 - Eastbound Fast - Piccadilly Line - Station Building - Acton Town Stn	Glazing Rope	Asbestos	Known				70LM Glazing bars, rope seals					
45330	ACTIVE	P	D205-00-2/262	Platform 2 - Eastbound Fast - Piccadilly Line - Station Building - Acton Town Stn	Other Electrical Boxes	Asbestos	Presumed				Asbestos components within Signal Boxes / Lamp to Columns & Canopy throughout Asbestos Components – Presumed within				N	N
23516	ACTIVE	P	D205-00-2/262	Platform 2 - Eastbound Fast - Piccadilly Line - Station Building - Acton Town Stn	Cable: Sheath	Asbestos	Known				Various braided cables on cable bridge that runs above Platform 1-5. Cables come from Switch Room 2/664 No Access at time of re-inspection 2024					
23515	ACTIVE	P	D205-00-2/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Below various manhole covers					
5097	ACTIVE	P	D205-00-2/263	Platform 3 - Wesbound Fast - Piccadilly Line - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23518	ACTIVE	P	D205-00-2/263	Platform 3 - Wesbound Fast - Piccadilly Line - Station Building - Acton Town Stn	Glazing Rope	Asbestos	Known				70LM Glazing bars, rope seals				N	N
45331	ACTIVE	P	D205-00-2/263	Platform 3 - Wesbound Fast - Piccadilly Line - Station Building - Acton Town Stn	Other Electrical Boxes	Asbestos	Presumed				Asbestos components within Signal Boxes / Lamp to Columns & Canopy throughout Asbestos Components – Presumed within				N	N
23519	ACTIVE	P	D205-00-2/263	Platform 3 - Wesbound Fast - Piccadilly Line - Station Building - Acton Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				Various braided cables on cable bridge that runs above Platform 1-5. Cable come from Switch Room 2/664 No Access at time of re-inspection 2024					
23517	ACTIVE	P	D205-00-2/263/FLR-01	Floor - 1 - Platform 3 - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Below various manhole covers					



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5098	ACTIVE	p	D205-00-2/264	Platform 4 - Wesbound Local - District Line - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45332	ACTIVE	p	D205-00-2/264	Platform 4 - Wesbound Local - District Line - Station Building - Acton Town Stn	Other Electrical Boxes	Asbestos	Presumed				Asbestos components within Signal Boxes / Lamp to Columns & Canopy throughout Asbestos Components – Presumed within				N	N
23521	ACTIVE	p	D205-00-2/264	Platform 4 - Wesbound Local - District Line - Station Building - Acton Town Stn	Glazing Rope	Asbestos	Known				70LM Glazing bars, rope seals				N	N
23520	ACTIVE	p	D205-00-2/264/FLR-01	Floor - 1 - Platform 4 - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Below various manhole covers					
45338	ACTIVE	p	D205-00-2/265	Platform - Station Building - Acton Town Stn	Cable Ducts: Bitumen	Asbestos	Strongly Presumed				Platform 5 - Bitumen Cable Ducts end of Platform 5 to Substation/ Accommodation building				N	N
45337	INACTIVE	p	D205-00-2/265	Platform - Station Building - Acton Town Stn	Cement Troughing	Asbestos	Removed				Platform 5 - Underneath platform 5 invert - Approx: 20m² Cement troughing - along whole stretch of invert area - down from 1/576 Removed under ES3489.	20			N	N
45334	ACTIVE	p	D205-00-2/265	Platform - Station Building - Acton Town Stn	Westing house Boxes	Asbestos	Presumed				Platform 5 - Between Disused Platform & Walk Way to track access block EAST - Materials With Small Westinghouse to Wall at South End of Disused Platform Asbestos Components – Presumed within		1		N	N
45335	ACTIVE	p	D205-00-2/265	Platform - Station Building - Acton Town Stn	Other Electrical Boxes	Asbestos	Presumed				Platform 5 - Disused Platform - Materials Within Link Boxes to Trackside Wall by Ramp at North End Asbestos Components – Presumed within				N	N
45336	ACTIVE	p	D205-00-2/265	Platform - Station Building - Acton Town Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Platform 5 - Towards station - Redundant Iron clad isolator adjacent accommodation building behind barrier to track Asbestos Components – Presumed within				N	N
45333	ACTIVE	p	D205-00-2/265	Platform - Station Building - Acton Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 5 - Disused Platform - Jhanger 7 - 1x40mm, 1x20 cable run from ramp end to accommodation blocks located at bottom of stairs 1/576 Not found - No access to track at time of re-inspection 2020 & 2024		2		N	N
5099	ACTIVE	p	D205-00-2/316	Locker Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23848	ACTIVE	P	D205-00-2/316	Locker Room - Station Building - Acton Town Stn	No Access	Asbestos	Removed				Not Surveyed - Demolished					
5100	ACTIVE	P	D205-00-2/331	Tea Point - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos				New Construction					
23527	INACTIVE	P	D205-00-2/331	Tea Point - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
5101	ACTIVE	P	D205-00-2/371	Store - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5102	ACTIVE	P	D205-00-2/406	Store - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23528	ACTIVE	P	D205-00-2/406	Store - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
5103	ACTIVE	P	D205-00-2/411	Store - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5104	ACTIVE	P	D205-00-2/412	Store - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5105	ACTIVE	P	D205-00-2/413	Store - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5106	ACTIVE	P	D205-00-2/416	Toilet - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23325	ACTIVE	P	D205-00-2/416/FLR-01	Floor - 1 - Toilet - Station Building - Acton Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
23326	ACTIVE	P	D205-00-2/416/FLR-01	Floor - 1 - Toilet - Station Building - Acton Town Stn	Void	Asbestos	Removed				Beneath Lino - Room demolished by SMEP					
5107	ACTIVE	P	D205-00-2/417	Toilet: Unisex - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5108	ACTIVE	P	D205-00-2/418	Shower Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5109	ACTIVE	P	D205-00-2/426	Toilet: Unisex - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos				New Construction					
23531	INACTIVE	P	D205-00-2/426	Toilet: Unisex - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5110	ACTIVE	P	D205-00-2/436	Waiting Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23532	ACTIVE	P	D205-00-2/436/CLG-01	Ceiling: Suspended - 1 - Waiting Room - Station Building - Acton Town Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
23884	ACTIVE	P	D205-00-2/436/CLG-01	Ceiling: Suspended - 1 - Waiting Room - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Wood plastic cables, rock wool above false ceiling				Yes	
5111	ACTIVE	P	D205-00-2/437	Waiting Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23533	ACTIVE	P	D205-00-2/437/CLG-01	Ceiling: Suspended - 1 - Waiting Room - Station Building - Acton Town Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
23534	ACTIVE	P	D205-00-2/437/CLG-01	Ceiling: Suspended - 1 - Waiting Room - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Wood plastic cables, rock wool above false ceiling				Yes	
5112	ACTIVE	P	D205-00-2/451	Tenancy - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
24036	ACTIVE	P	D205-00-2/451/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Y	
23536	ACTIVE	P	D205-00-2/451/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Acton Town Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
23535	ACTIVE	P	D205-00-2/451/FLR-01	Floor - 1 - Tenancy - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Beneath floor boards					Y
5113	ACTIVE	P	D205-00-2/452	Information Centre - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23322	ACTIVE	P	D205-00-2/452/CLG-01	Ceiling: Suspended - 1 - Information Centre - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Above false ceiling					
23321	ACTIVE	P	D205-00-2/452/CLG-01	Ceiling: Suspended - 1 - Information Centre - Station Building - Acton Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
23885	ACTIVE	P	D205-00-2/452/FLR-01	Floor - 1 - Information Centre - Station Building - Acton Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Blue vinyl tiles					
5114	ACTIVE	P	D205-00-2/481	Store - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5115	ACTIVE	P	D205-00-2/484	Store - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23324	ACTIVE	P	D205-00-2/484/DOR-01	Door - 1 - Store - Station Building - Acton Town Stn	Lead/Leading	Lead Paint/Lead	Removed				Door - red gloss - 1.5m ² x 0.5m ² . Thickness : 0.44mm Analysis : 10.1% Has since been replaced with a wooden door as noted upon HMU re inspection 21/10/2014					
23323	ACTIVE	P	D205-00-2/484/FLR-01	Floor - 1 - Store - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Beneath Inspection cover. Observed filled over at time of re-inspection 2024					
5116	ACTIVE	P	D205-00-2/485	Tea Point - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5117	ACTIVE	P	D205-00-2/576	Stairs: Linear - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23327	ACTIVE	P	D205-00-2/576	Stairs: Linear - Station Building - Acton Town Stn		Asbestos	Surveyed – Not Detected				Non-Woven, except HV cable, which has Hessian bituminous insulation					
23329	ACTIVE	P	D205-00-2/576	Stairs: Linear - Station Building - Acton Town Stn	Lead/Leading	Lead Paint/Lead	Known				By 2/901 rails on external stairs - grey matt - 7m ² . Thickness : 0.46mm Analysis : 13.9%;					
23328	ACTIVE	P	D205-00-2/576/DOR-01	Door - 1 - Linear Stairs - Station Building - Acton Town Stn	Lead/Leading	Lead Paint/Lead	Removed				Door - grey gloss - 2m ² . Thickness : 0.10mm Analysis : 7.65% The door has since been replaced as noted upon HMU re inspection 21/10/2014					
5118	ACTIVE	P	D205-00-2/577	Stairs: Linear - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5119	ACTIVE	P	D205-00-2/578	Stairs: Linear - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5120	ACTIVE	P	D205-00-2/579	Stairs: Linear - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5121	ACTIVE	P	D205-00-2/580	Stairs: Linear - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5122	ACTIVE	P	D205-00-2/661	Switch Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
45327	ACTIVE	P	D205-00-2/661	Switch Room - Station Building - Acton Town Stn	Other Electrical Boxes	Asbestos	Presumed				Materials Within Combination Fuse Switches to Wall 3 Asbestos Components – Presumed within		4		N	N
5123	ACTIVE	P	D205-00-2/662	Switch Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Room in very poor condition - as noted upon HMU re inspection 21/10/2014					



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23334	ACTIVE	P	D205-00-2/662	Switch Room - Station Building - Acton Town Stn	Other Electrical Boxes	Asbestos	Removed				rectifier box Not present 2020 re-inspection removed		1			
45328	ACTIVE	P	D205-00-2/662	Switch Room - Station Building - Acton Town Stn	Other Electrical Boxes	Asbestos	Removed				Transformer Box Not present 2020 re-inspection removed				N	N
23702	ACTIVE	P	D205-00-2/662	Switch Room - Station Building - Acton Town Stn	Cable: Wrap	Asbestos	Removed				1/3 Im Cable Wrapping within Transformer. NB - could not be sampled because of isolation Not present 2020 re-inspection removed					
5124	ACTIVE	P	D205-00-2/663	Switch Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23335	ACTIVE	P	D205-00-2/663/DOR-01	Door - 1 - Switch Room - Station Building - Acton Town Stn		Asbestos	Surveyed – Not Detected				Supalux boarding on door					
23336	ACTIVE	P	D205-00-2/663/DOR-02	Door - 2 - Switch Room - Station Building - Acton Town Stn		Asbestos	Surveyed – Not Detected				Supalux boarding on door					
42262	ACTIVE	P	D205-00-2/663/FLR-01 80855661	Floor - 1 - Switch Room - Station Building - Acton Town Stn Floor	Void	Asbestos	No Access: Presumed				No Access to Manhole Covers					
23863	ACTIVE	P	D205-00-2/663/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Acton Town Stn	Other Electrical Boxes	Asbestos	Removed				Transformer Box - Removed by others		1			
23337	ACTIVE	P	D205-00-2/663/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Acton Town Stn	Isolator Switches	Asbestos	Strongly Presumed				Iron Clad Isolators 1x60, 2x100, 1x200amps Asbestos Components – Strongly Presumed within		4		N	N
5125	ACTIVE	P	D205-00-2/664	Switch Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
45344	ACTIVE	P	D205-00-2/664	Switch Room - Station Building - Acton Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				Outside Door of switch room (Cable Bridge) - 1x 6cm ø continuing from station & cable continuing along route No access at time of re-inspection 2024 - Excessive bird droppings - RPE & PPE required	6	1		N	N
45345	ACTIVE	P	D205-00-2/664	Switch Room - Station Building - Acton Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				Outside Door of switch room (Cable Bridge) - 2x Cables from box No access at time of re-inspection 2024 - Excessive bird droppings - RPE & PPE required		2		N	N
45346	ACTIVE	P	D205-00-2/664	Switch Room - Station Building - Acton Town Stn		Asbestos	Not Found during Inspection				Outside Door of switch room (Cable Bridge) - 6x Cable sleeves - High level before cable run		6		N	N



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
45343	ACTIVE	P	D205-00-2/664	Switch Room - Station Building - Acton Town Stn	Westing house Boxes	Asbestos	Not Found during Inspection				Outside Door of switch room (Cable Bridge) - Westlinghouse box				N	N
45339	ACTIVE	P	D205-00-2/664	Switch Room - Station Building - Acton Town Stn	Other Electrical Boxes	Asbestos	Removed				Wall 2 - 6 x Switch Boxes - Removed		6		N	N
45340	ACTIVE	P	D205-00-2/664	Switch Room - Station Building - Acton Town Stn	Other Electrical Boxes	Asbestos	Presumed				2x Electrical boxes - Wall 3 H/ L(10"x6") Asbestos Components – Presumed within		2		N	N
45341	ACTIVE	P	D205-00-2/664	Switch Room - Station Building - Acton Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				Outside Door of switch room (Cable Bridge) - 1x 2cm ø Cable looping to ceiling along cable route No access at time of re-inspection 2024 - Excessive bird droppings - RPE & PPE required	2	1		N	N
45348	ACTIVE	P	D205-00-2/664	Switch Room - Station Building - Acton Town Stn		Asbestos	Presumed				Outside Door of switch room (Cable Bridge) - Materials Within Link Box to Cable Run of Concrete Cable Overbridge No access at time of re-inspection 2024 - Excessive bird droppings - RPE & PPE required				N	N
45347	ACTIVE	P	D205-00-2/664	Switch Room - Station Building - Acton Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				Outside Door of switch room (Cable Bridge) - 5m length Cable wrap - on right hand side of cable route No access at time of re-inspection 2024 - Excessive bird droppings - RPE & PPE required	5			N	N
45342	ACTIVE	P	D205-00-2/664	Switch Room - Station Building - Acton Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				Outside Door of switch room (Cable Bridge) - 2x 5cm ø Cable remains on right hand side No access at time of re-inspection 2024 - Excessive bird droppings - RPE & PPE required	5	2		N	N
5126	ACTIVE	P	D205-00-2/751	CER - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45322	ACTIVE	P	D205-00-2/751	CER - Station Building - Acton Town Stn	Other Electrical Boxes	Asbestos	Presumed				Materials Within Transformers to Wall 4 Westinghouse Box – Asbestos Components – Strongly Presumed within				N	N
5127	ACTIVE	P	D205-00-2/761	Equipment Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5128	ACTIVE	P	D205-00-2/763	Equipment Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46800	ACTIVE	P	D205-00-2/763	Equipment Room - Station Building - Acton Town Stn	Debris: Other	Asbestos	Presumed				Asbestos debris (Pipe Insulation) within painted surfaces to walls W4, W5, W6			R55202 & R712976		



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
53554	ACTIVE	p	D205-00-2/763	Equipment Room - Station Building - Acton Town Stn	Debris: Other	Asbestos	Known				Asbestos Debris (Pipe Insulation) to Grey Floor Paint			R712976		
23349	ACTIVE	p	D205-00-2/763	Equipment Room - Station Building - Acton Town Stn	Lead/Leading	Lead Paint/Lead	Removed				Door - green matt - 2m². Thickness : Dust Analysis : 2.53% Not found upon HMU Re inspection 21/10/2014					
53553	ACTIVE	p	D205-00-2/763	Equipment Room - Station Building - Acton Town Stn	Lead/Leading	Lead Paint/Lead	Known				Black Gloss Paint to Plinths on Floor 0.90% Lead - 610um Paint Thickness			R712977		
5129	ACTIVE	p	D205-00-2/771	Pump Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23350	ACTIVE	p	D205-00-2/771	Pump Room - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
45321	ACTIVE	p	D205-00-2/771	Pump Room - Station Building - Acton Town Stn	Other Electrical Boxes	Asbestos	No Access: Presumed				Materials Within Transformer by Wall 1 No access 2020 & 2024 re-inspection (pwteh) required as room off platform on track level				N	N
5130	ACTIVE	p	D205-00-2/772	Pump Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23351	ACTIVE	p	D205-00-2/772	Pump Room - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
5131	ACTIVE	p	D205-00-2/801	CER - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23352	INACTIVE	p	D205-00-2/801	CER - Station Building - Acton Town Stn	Other Boarding	Asbestos	Removed				Supalux partition, board behind wall 3 LTB heater removed as part of conversion to CER					
23703	INACTIVE	p	D205-00-2/801	CER - Station Building - Acton Town Stn	Other Boarding	Asbestos	Removed				Supalux partition, board behind wall 4 LTB heater removed as part of conversion to CER					
5132	ACTIVE	p	D205-00-2/802	Office - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5133	ACTIVE	p	D205-00-2/803	Office - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5134	ACTIVE	p	D205-00-2/804	Train Technician Office - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5135	ACTIVE	p	D205-00-2/805	Mobile Train Technician Office - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5136	ACTIVE	P	D205-00-2/901	Disused Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5137	ACTIVE	P	D205-00-2/902	Locker Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5138	ACTIVE	P	D205-00-2/903	Office - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5139	ACTIVE	P	D205-00-2/904	Locker Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5140	ACTIVE	P	D205-00-2/906	Locker Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5141	ACTIVE	P	D205-00-2/951	Locker Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23156	ACTIVE	P	D205-00-2/951/ WAL-010 80855903	Wall: Internal - 1 - Locker Room - Station Building - Acton Town Stn Wall: Internal	Cable Duct: Other	Asbestos	Presumed				Cables Duct Wasn't visible during 2020 or 2024 Re-Inspection		1			
5142	ACTIVE	P	D205-00-2/952	Store - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23365	ACTIVE	P	D205-00-2/952	Store - Station Building - Acton Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				White boarding in storage - Supalux					
5143	ACTIVE	P	D205-00-2/953	Disused Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5144	ACTIVE	P	D205-00-2/954	Disused Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23366	ACTIVE	P	D205-00-2/954	Disused Room - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
5145	ACTIVE	P	D205-00-2/955	Disused Room - Station Building - Acton Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23866	ACTIVE	P	D205-00-2/955	Disused Room - Station Building - Acton Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
42256	ACTIVE	P	D205-00/ROF-01 80955382	Structure: Roof - 1 - Station Building - Acton Town Stn Structure: Roof	Cement Cowlings/ Flues	Asbestos	Presumed				Cement Flue Cowling on roof above 1/461		1			



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23260	ACTIVE	P	D205-01-1/041/CLG-01	Ceiling: Suspended - 1 - Mess Room - Train Crew Accommodation - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Concrete 225m² above false ceiling	225			Yes	
23259	ACTIVE	P	D205-01-1/041/FLR-01 80855988	Floor - 1 - Mess Room - Station Building - Acton Town Stn Floor	Void	Asbestos	No Access: Presumed				Beneath wooden panel under door mat. Area is refurbished and modern Lino coverings are now present throughout.					
23855	ACTIVE	P	D205-01-1/041/FLR-01	Floor - 1 - Mess Room - Station Building - Acton Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
42213	ACTIVE	P	D205-01-1/041/WAL-013	Wall: Internal - 13 - Mess Room - Train Crew Accommodation - Acton Town Stn		Asbestos	Sampled – Not Detected				Residue - 3Lm to metal water pipe				N	N
23612	ACTIVE	P	D205-01-1/047/CLG-01	Ceiling: Suspended - 1 - Kitchen - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Solid, plasterboard panels above door - above false ceiling				Yes	
42208	ACTIVE	P	D205-01-1/047/CLG-02	Ceiling: Solid - 2 - Kitchen - Station Building - Acton Town Stn	Other Boarding	Asbestos	Sampled – Not Detected				Render/plaster 30m² above false ceiling	30			Y	
42209	ACTIVE	P	D205-01-1/047/CLG-02	Ceiling: Solid - 2 - Kitchen - Station Building - Acton Town Stn	Lead/Leading	Asbestos	Sampled – Not Detected				Paint - 30m² to main ceiling		30		N	N
23261	ACTIVE	P	D205-01-1/047/FLR-01	Floor - 1 - Kitchen - Station Building - Acton Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl on solid					
23267	ACTIVE	P	D205-01-1/056/FLR-01	Floor - 1 - Station Building - Acton Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino on solid					
23268	ACTIVE	P	D205-01-1/056/FLR-01	Floor - 1 - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Polystyrene on solid					
23294	ACTIVE	P	D205-01-1/317/FLR-01	Floor - 1 - Locker Room - Station Building - Acton Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl on solid floor					
23295	ACTIVE	P	D205-01-1/317/WAL-006	Wall: Internal - 6 - Locker Room - Station Building - Acton Town Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
23613	ACTIVE	P	D205-01-1/317/WAL-007	Wall: Internal - 7 - Locker Room - Station Building - Acton Town Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
23309	INACTIVE	P	D205-01-1/335/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Above Aluminium tiles					
23860	ACTIVE	P	D205-01-1/335/FLR-01	Floor - 1 - Mess Room - Station Building - Acton Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino on concrete					
23161	ACTIVE	P	D205-01-1/418/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Acton Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Compressed supalux tiles					



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23162	ACTIVE	P	D205-01-1/418/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Solid; fibreglass, aluminium ducts above false ceiling				Yes	
23160	INACTIVE	P	D205-01-1/418/FLR-01	Floor - 1 - Toilet - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Beneath 3 x manhole covers					
23159	ACTIVE	P	D205-01-1/418/FLR-01	Floor - 1 - Toilet - Station Building - Acton Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino on solid					
23487	INACTIVE	P	D205-01-1/801/FLR-01	Floor - 1 - Office - Station Building - Acton Town Stn	Void	Asbestos	Removed				Beneath carpet - Room now part of 1/906;					
23496	ACTIVE	P	D205-01-1/902/WAL-002 80855966	Wall: Internal - 2 - Switch Room - Station Building - Acton Town Stn Wall: Internal	Other Electrical Boxes	Asbestos	Strongly Presumed				Insulation inside trunking No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1		N	N
23495	ACTIVE	P	D205-01-1/902/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Acton Town Stn	Isolator Switches	Asbestos	Strongly Presumed				3 x Blue Iron Clad Isolators 2x60amps, 1x100amps No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		3		N	N
23880	ACTIVE	P	D205-01-2/081/FLR-01	Floor - 1 - Lobby - Station Building - Acton Town Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding x 3		3			
23499	ACTIVE	P	D205-01-2/081/FLR-01	Floor - 1 - Lobby - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Beneath supalux boarding					
23508	ACTIVE	P	D205-01-2/236/WAL-005	Wall: Internal - 5 - Passage - Station Building - Acton Town Stn	Isolator Switches	Asbestos	Strongly Presumed				Iron Clad Isolator x 30 amp No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
23348	ACTIVE	P	D205-01-2/763/WAL-001	Wall: Internal - 1 - Equipment Room - Station Building - Acton Town Stn	Debris: Other	Asbestos	Presumed				Brick painted - possible asbestos debris in paint - ALL WALLS					
23361	ACTIVE	P	D205-01-2/901/DOR-01	Door - 1 - Disused Room - Station Building - Acton Town Stn	Lead/Leading	Lead Paint/Lead	Removed				4 doors - grey / green gloss - 2m ² . Thickness : Dust Analysis : 18.7% May have been removed - as noted during HMU re-inspection 21/10/2014					
23364	ACTIVE	P	D205-01-2/951/DOR-01	Door - 1 - Locker Room - Station Building - Acton Town Stn	Lead/Leading	Lead Paint/Lead	Removed				Door - green gloss - 2m ² Thickness : Dust Analysis : 19.5% May have been removed. Not found upon HMU re inspection 21/10/2014					
24035	ACTIVE	P	D205-01-2/951/WAL-002	Wall: Internal - 2 - Locker Room - Station Building - Acton Town Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LTB heater foam panels		1			
23155	ACTIVE	P	D205-02-1/414/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Above tiles					



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23154	ACTIVE	P	D205-02-1/414/FLR-01	Floor - 1 - Office - Station Building - Acton Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino Tiles					
23157	ACTIVE	P	D205-02-1/414/WAL-002	Wall: Internal - 2 - Office - Station Building - Acton Town Stn	LUL Heaters	Asbestos	Strongly Presumed				LTB Heater		1		N	N
23167	ACTIVE	P	D205-02-1/420/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
23843	ACTIVE	P	D205-02-1/420/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Acton Town Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
23168	ACTIVE	P	D205-02-1/421/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Acton Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux tiles					
23169	ACTIVE	P	D205-02-1/421/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux tiles				Yes	
23177	ACTIVE	P	D205-02-1/428/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above supalux				Yes	
23176	ACTIVE	P	D205-02-1/428/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Acton Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
23175	ACTIVE	P	D205-02-1/428/WAL-001	Wall: Internal - 1 - Lobby - Station Building - Acton Town Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - 2 x foam panels in LTB heater		2			
23488	ACTIVE	P	D205-02-1/803/FLR-01	Floor - 1 - RCI Office - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Beneath Lino					
23489	ACTIVE	P	D205-02-1/803/WAL-001	Wall: Internal - 1 - RCI Office - Station Building - Acton Town Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LTB heater 2x foam panels		2			
23490	ACTIVE	P	D205-02-1/804/FLR-01	Floor - 1 - Locker Room - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Beneath Lino					
23491	ACTIVE	P	D205-02-1/804/WAL-007	Wall: Internal - 7 - Locker Room - Station Building - Acton Town Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LTB heater foam panels		1			
23501	ACTIVE	P	D205-02-2/083/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Acton Town Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
23502	ACTIVE	P	D205-02-2/083/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23500	ACTIVE	P	D205-02-2/083/FLR-01	Floor - 1 - Lobby - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Beneath carpet					
23510	ACTIVE	P	D205-02-2/237/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Breeze block, plaster cables above false ceiling				Yes	
23509	ACTIVE	P	D205-02-2/237/FLR-01	Floor - 1 - Passage - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Carpet on solid					Yes
23883	ACTIVE	P	D205-02-2/413/FLR-01	Floor - 1 - Store - Station Building - Acton Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl					
23529	ACTIVE	P	D205-02-2/413/FLR-01	Floor - 1 - Store - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Solid beneath vinyl					Yes
23530	ACTIVE	P	D205-02-2/417/WAL-001 80855813	Wall: Internal - 1 - Toilet - Station Building - Acton Town Stn Wall: Internal	LUL Heaters	Asbestos	Presumed				Heater		1		N	N
23340	ACTIVE	P	D205-02-2/664/DOR-01	Door - 1 - Switch Room - Station Building - Acton Town Stn	Lead/Leading	Lead Paint/Lead	Removed				Door - blue gloss - 2m². Thickness : 0.07mm Analysis : 2.27% The door has since been replaced with a wooden one - as reported upon HMU Re -inspection 21/10/2014					
23339	ACTIVE	P	D205-02-2/664/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Acton Town Stn	Other Electrical Boxes	Asbestos	Presumed				1 x 60amp Switch box No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1		N	N
23338	ACTIVE	P	D205-02-2/664/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Acton Town Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Box No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
41728	ACTIVE	P	D205-02-2/664/WAL-003 80855838	Wall: Internal - 3 - Switch Room - Station Building - Acton Town Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box and associated box at high level No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		2		N	N
23354	ACTIVE	P	D205-02-2/802/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, plaster, plastic cables above false ceiling				Yes	
23353	ACTIVE	P	D205-02-2/802/FLR-01	Floor - 1 - Office - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Solid beneath carpet					Yes
23356	ACTIVE	P	D205-02-2/803/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, plaster, plastic cables above false ceiling				Yes	
23355	ACTIVE	P	D205-02-2/803/FLR-01	Floor - 1 - Office - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Solid beneath carpet					Yes



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23358	ACTIVE	P	D205-02-2/804/CLG-01	Ceiling: Suspended - 1 - Train Technician Office - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, plaster, plastic cables above false ceiling				Yes	
23357	ACTIVE	P	D205-02-2/804/FLR-01	Floor - 1 - Train Technician Office - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Solid beneath carpet tiles					Yes
23359	ACTIVE	P	D205-02-2/805/CLG-01	Ceiling: Suspended - 1 - Mobile Train Technician Office - Station Building - Acton Town Stn		Asbestos	Surveyed – Not Detected				Supalux foam tiles					
23360	ACTIVE	P	D205-02-2/805/CLG-01	Ceiling: Suspended - 1 - Mobile Train Technician Office - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, plaster, plastic cables above false ceiling				Yes	
24030	ACTIVE	P	D205-02-2/805/FLR-01	Floor - 1 - Mobile Train Technician Office - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Solid beneath carpet					Yes
23363	ACTIVE	P	D205-02-2/903/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Acton Town Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
23865	ACTIVE	P	D205-02-2/903/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Acton Town Stn		Asbestos	Surveyed – Not Detected				Supalux					
23362	ACTIVE	P	D205-02-2/903/FLR-01	Floor - 1 - Office - Station Building - Acton Town Stn	Vinyl tiles	Asbestos	No Access: Presumed				Beneath carpet					
24029	ACTIVE	P	D205-04-2/662/FLR-01	Floor - 1 - Switch Room - Station Building - Acton Town Stn	Void	Asbestos	No Access: Presumed				Beneath Duct cover					
23330	ACTIVE	P	D205-04-2/662/WAL-001 80855829	Wall: Internal - 1 - Switch Room - Station Building - Acton Town Stn Wall: Internal	Isolator Switches	Asbestos	Presumed				Switch Box 60amp, labelled as redundant No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1		N	N
23333	ACTIVE	P	D205-04-2/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Acton Town Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Trunking No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1		N	N
23331	ACTIVE	P	D205-04-2/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Acton Town Stn	Isolator Switches	Asbestos	Presumed				Iron Clad Isolators - 3x60, 2x100, 1x200, 1x300amps No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		7		N	N



Hazardous Material Asset Register - Summary



D205-00 - Station Building - Acton Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42260	ACTIVE	P	D205/P/BGE-05	Bridge: Cable and Pipe - D62C - Acton Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				Small remnants of asbestos sheathed cable remains in J-Hangers; Encapsulated by Econ 16/12/2016 - where it was not possible to remove fully; Access outside door of Switch Room 2/664 Cable Bridge D62C		1			
23345	ACTIVE	P	D205/P/BGE-05	Bridge: Cable and Pipe - D62C - Acton Town Stn	Cable: Wrap	Asbestos	Removed				Cable Wrap RHS of Cable Bridge D62C - Poor Condition Cable Wrap Removed by Econ 16/12/2016 Access outside door of Switch Room 2/664		1			
23346	ACTIVE	P	D205/P/BGE-05	Bridge: Cable and Pipe - D62C - Acton Town Stn	Cable Duct: Other	Asbestos	Presumed				6no Cable sleeves - High level before cable run - Outside Door of switch room 2/664; Cable Bridge D62C;		6			
23347	ACTIVE	P	D205/P/BGE-05	Bridge: Cable and Pipe - D62C - Acton Town Stn	Cable: Sheath	Asbestos	Removed				Cable along cable route into Westinghouse box - Centre cable run; Removed by Econ 16/12/2016 Access outside door of Switch Room 2/664 Cable Bridge D62C		1			
23343	ACTIVE	P	D205/P/BGE-05	Bridge: Cable and Pipe - D62C - Acton Town Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westlinghouse Boxes - Cable Bridge D62C Access outside door of Switch Room 2/664		2			
42272	ACTIVE	P	D205/P/BGE-05	Bridge: Cable and Pipe - D62C - Acton Town Stn	Other Electrical Boxes	Asbestos	Presumed				2no Tencore Boxes on RHS of Cable Bridge D62C Access outside door of Switch Room 2/664		2			
23344	ACTIVE	P	D205/P/BGE-05	Bridge: Cable and Pipe - D62C - Acton Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				1x 6cm ø continuing from station & cable continuing along route. Cable Encapsulated by Econ 16/12/2016. Access outside door of Switch Room 2/664 Cable Bridge D62C		1			
23341	ACTIVE	P	D205/P/BGE-05	Bridge: Cable and Pipe - D62C - Acton Town Stn	Void	Asbestos	No Access: Presumed				No Access to Pit outside of door to Switch Room 2/664 - Metal Grate - No access to Debris within - Presumed Cable Bridge D62C					
23342	ACTIVE	P	D205/P/BGE-05	Bridge: Cable and Pipe - D62C - Acton Town Stn	Cable: Sheath	Asbestos	Sampled – Not Detected				Outside Door of switch room 2/664 (Cable Bridge) - 2x 5cm ø Cable remains on right hand side - NON ASBESTOS		2			
23864	ACTIVE	P	D205/P/BGE-05	Bridge: Cable and Pipe - D62C - Acton Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				1no x 2cm ø Cable looping to ceiling along cable route on RHS Wall adj 2/664 Cable Bridge D62C Access outside door of Switch Room 2/664 Previously Encapsulated by Forest ES329 - 12/05/2004 Re-encapsulated by Econ 16/06/2016	10	1			



Hazardous Material Asset Register - Summary



D213-00 - Station Building - South Ealing Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5146	ACTIVE	P	D213-00-1/001	Booking Hall - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23367	ACTIVE	P	D213-00-1/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - South Ealing Stn	Glazing Rope	Asbestos	Strongly Presumed				Ceiling glazing bars					
23368	ACTIVE	P	D213-00-1/001/CLG-02	Ceiling: Solid - 2 - Skylight - Booking Hall - Station Building - South Ealing Stn	Glazing Rope	Asbestos	Strongly Presumed				Ceiling glazing bars					
5147	ACTIVE	P	D213-00-1/011	Ticket Office - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23370	ACTIVE	P	D213-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - South Ealing Stn	Void	Asbestos	Surveyed – Not Detected				Metal above Supalux ceiling				Yes	
23867	ACTIVE	P	D213-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - South Ealing Stn		Asbestos	Surveyed – Not Detected				Supalux					
23369	ACTIVE	P	D213-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - South Ealing Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer flooring					Yes
5148	ACTIVE	P	D213-00-1/021	POM - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23371	ACTIVE	P	D213-00-1/021/FLR-01	Floor - 1 - POM - Station Building - South Ealing Stn	Void	Asbestos	No Access: Presumed				Beneath computer flooring					Yes
5149	ACTIVE	P	D213-00-1/031	Mess Room - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23425	ACTIVE	P	D213-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - South Ealing Stn		Asbestos	Surveyed – Not Detected				Supalux					
23426	ACTIVE	P	D213-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - South Ealing Stn	Void	Asbestos	Surveyed – Not Detected				Metal above Supalux ceiling				Yes	
5150	ACTIVE	P	D213-00-1/036	Toilet: Unisex - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23428	ACTIVE	P	D213-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - South Ealing Stn	Void	Asbestos	Surveyed – Not Detected				Metal above Supalux ceiling				Yes	
23427	ACTIVE	P	D213-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - South Ealing Stn		Asbestos	Surveyed – Not Detected				Supalux					



Hazardous Material Asset Register - Summary



D213-00 - Station Building - South Ealing Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5151	ACTIVE	P	D213-00-1/081	Lobby - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23431	ACTIVE	P	D213-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - South Ealing Stn	Void	Asbestos	Surveyed – Not Detected				Metal above Supalux ceiling				Yes	
23430	ACTIVE	P	D213-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - South Ealing Stn		Asbestos	Surveyed – Not Detected				Supalux					
23429	ACTIVE	P	D213-00-1/081/FLR-01	Floor - 1 - Lobby - Station Building - South Ealing Stn	Void	Asbestos	No Access: Presumed				Beneath computer flooring					Yes
5152	ACTIVE	P	D213-00-1/082	Lobby - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23432	ACTIVE	P	D213-00-1/082/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - South Ealing Stn		Asbestos	Surveyed – Not Detected				Supalux				Yes	
23433	ACTIVE	P	D213-00-1/082/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - South Ealing Stn	Void	Asbestos	Surveyed – Not Detected				Metal above Supalux ceiling				Yes	
5153	ACTIVE	P	D213-00-1/236	Passage - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5154	ACTIVE	P	D213-00-1/281	Station Supervisor Office - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23435	ACTIVE	P	D213-00-1/281/CLG-01	Ceiling: Solid - 1 - Station Supervisor Office - Station Building - South Ealing Stn	Other Boarding	Asbestos	No Access: Presumed				Above plasterboard					
23434	ACTIVE	P	D213-00-1/281/WAL-003	Wall: Internal - 3 - Station Supervisor Office - Station Building - South Ealing Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - Foam		1			
5155	ACTIVE	P	D213-00-1/401	Lobby - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24033	ACTIVE	P	D213-00-1/401/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - South Ealing Stn	Void	Asbestos	No Access: Presumed				Above Supalux ceiling				Yes	
23436	ACTIVE	P	D213-00-1/401/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - South Ealing Stn		Asbestos	Surveyed – Not Detected				Supalux					
5156	ACTIVE	P	D213-00-1/406	Store - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D213-00 - Station Building - South Ealing Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23437	ACTIVE	P	D213-00-1/406/CLG-01	Ceiling: Solid - 1 - Store - Station Building - South Ealing Stn	Other Boarding	Asbestos	No Access: Presumed				Above plasterboard					
5157	ACTIVE	P	D213-00-1/411	Store - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23438	ACTIVE	P	D213-00-1/411/CLG-01	Ceiling: Solid - 1 - Store - Station Building - South Ealing Stn	Other Boarding	Asbestos	No Access: Presumed				Above plasterboard					
5158	ACTIVE	P	D213-00-1/416	Toilet: Unisex - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23439	ACTIVE	P	D213-00-1/416/WAL-003	Wall: Internal - 3 - Toilet - Station Building - South Ealing Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - Foam		1			
5159	ACTIVE	P	D213-00-1/451	Store - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23705	ACTIVE	P	D213-00-1/451/CLG-01	Ceiling: Solid - 1 - Store - Station Building - South Ealing Stn	Other Boarding	Asbestos	No Access: Presumed				Above plasterboard					
5160	ACTIVE	P	D213-00-1/452	Tenancy - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23874	ACTIVE	P	D213-00-1/452	Tenancy - Station Building - South Ealing Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
5161	ACTIVE	P	D213-00-1/453	Tenancy - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5162	ACTIVE	P	D213-00-1/551	Yard - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23440	ACTIVE	P	D213-00-1/551	Yard - Station Building - South Ealing Stn	Other Boarding	Asbestos	Presumed				Soffit Boarding to outside of Station Building					
5163	ACTIVE	P	D213-00-1/601	Stairs: Linear - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23441	ACTIVE	P	D213-00-1/601/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - South Ealing Stn	Void	Asbestos	No Access: Presumed				Metal Cladding - potentially single skim roof, but if not potential for insulation materials between inner and outer cladding				Yes	
5164	ACTIVE	P	D213-00-1/602	Stairs: Linear - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D213-00 - Station Building - South Ealing Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23442	ACTIVE	P	D213-00-1/602/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - South Ealing Stn	Void	Asbestos	No Access: Presumed				Metal Cladding - potentially single skim roof, but if not potential for insulation materials between inner and outer cladding.				Yes	
23875	ACTIVE	P	D213-00-1/636/CLG-01	Ceiling: Suspended - 1 - Overbridge - Station Building - South Ealing Stn	Void	Asbestos	No Access: Presumed				Above metal cladding				Yes	
5165	ACTIVE	P	D213-00-1/661	Switch Room - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23443	ACTIVE	P	D213-00-1/661/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - South Ealing Stn	Void	Asbestos	No Access: Presumed				Above plasterboard				Yes	
23446	ACTIVE	P	D213-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - South Ealing Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
23444	ACTIVE	P	D213-00-1/661/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - South Ealing Stn	Isolator Switches	Asbestos	Strongly Presumed				6 Switch Boxes - 5 x 60amp 1 x 200amp No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		6			
23445	ACTIVE	P	D213-00-1/661/WAL-007	Wall: Internal - 7 - Switch Room - Station Building - South Ealing Stn	Isolator Switches	Asbestos	Strongly Presumed				1 Switch Box - 1x30amp No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
23876	ACTIVE	P	D213-00-1/661/WAL-007	Wall: Internal - 7 - Switch Room - Station Building - South Ealing Stn	Other Electrical Boxes	Asbestos	Presumed				3 x Transformer Box insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		3			
5166	ACTIVE	P	D213-00-1/731	CER - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5167	ACTIVE	P	D213-00-1/746	SCR - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5168	ACTIVE	P	D213-00-1/776	Plant Room - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23448	ACTIVE	P	D213-00-1/776/CLG-01	Ceiling: Solid - 1 - Plant Room - Station Building - South Ealing Stn	Void	Asbestos	No Access: Presumed				Above Supalux				Yes	



Hazardous Material Asset Register - Summary



D213-00 - Station Building - South Ealing Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23447	ACTIVE	P	D213-00-1/776/CLG-01	Ceiling: Solid - 1 - Plant Room - Station Building - South Ealing Stn		Asbestos	Surveyed – Not Detected				Supalux					
5169	ACTIVE	P	D213-00-2/261	Platform 1 - Eastbound Local - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23451	ACTIVE	P	D213-00-2/261	Platform 1 - Eastbound Local - Station Building - South Ealing Stn		Asbestos	Surveyed – Not Detected				Supalux boarding behind signs					
42151	ACTIVE	P	D213-00-2/261	Platform 1 - Eastbound Local - Station Building - South Ealing Stn	Lead/Leading	Lead Paint/Lead	Presumed				Potential green lead paint on platform upstands					
23453	ACTIVE	P	D213-00-2/261	Platform 1 - Eastbound Local - Station Building - South Ealing Stn	Lead/Leading	Lead Paint/Lead	Known				Waiting areas - side panels - green gloss. Thickness : 0.02mm Analysis : 1.3%					
23454	ACTIVE	P	D213-00-2/261	Platform 1 - Eastbound Local - Station Building - South Ealing Stn	Lead/Leading	Lead Paint/Lead	Known				Waiting areas - Lower panel - green gloss. Thickness : 0.09mm Analysis : 1.1%					
23452	ACTIVE	P	D213-00-2/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - South Ealing Stn	Glazing Rope	Asbestos	Strongly Presumed				Glazing bars - part of canopy					
23450	ACTIVE	P	D213-00-2/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - South Ealing Stn		Asbestos	Surveyed – Not Detected				Canopy - Supalux					
23449	ACTIVE	P	D213-00-2/261/FLR-01	Floor - 1 - Platform 1 - Station Building - South Ealing Stn	Void	Asbestos	No Access: Presumed				Beneath Inspection covers					Yes
23455	ACTIVE	P	D213-00-2/261/WDW-01	Window - 1 - Platform 1 - Station Building - South Ealing Stn	Lead/Leading	Lead Paint/Lead	Known				Waiting areas - window frames - white gloss. Thickness : 0.35mm Analysis : 2.8%					
23456	ACTIVE	P	D213-00-2/261/WDW-02	Window - 2 - Platform 1 - Station Building - South Ealing Stn	Lead/Leading	Lead Paint/Lead	Known				Waiting areas - window frames - white gloss. Thickness : 0.35mm Analysis : 2.8%					
5170	ACTIVE	P	D213-00-2/262	Platform 2 - Eastbound Fast - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45250	ACTIVE	P	D213-00-2/262	Platform 2 - Eastbound Fast - Station Building - South Ealing Stn	Glazing Rope	Asbestos	Strongly Presumed				Glazing bars - Part of Canopy				N	N
23459	ACTIVE	P	D213-00-2/262	Platform 2 - Eastbound Fast - Station Building - South Ealing Stn		Asbestos	Surveyed – Not Detected				Supalux boarding behind signs					
23460	ACTIVE	P	D213-00-2/262	Platform 2 - Eastbound Fast - Station Building - South Ealing Stn	Lead/Leading	Lead Paint/Lead	Known				Waiting areas - side panels - green gloss. Thickness : 0.02mm Analysis : 1.3%					



Hazardous Material Asset Register - Summary



D213-00 - Station Building - South Ealing Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23461	ACTIVE	P	D213-00-2/262	Platform 2 - Eastbound Fast - Station Building - South Ealing Stn	Lead/Leading	Lead Paint/Lead	Known				Waiting areas - Lower panel - green gloss. Thickness : 0.09mm Analysis : 1.1%					
42152	ACTIVE	P	D213-00-2/262	Platform 2 - Eastbound Fast - Station Building - South Ealing Stn	Lead/Leading	Lead Paint/Lead	Presumed				Potential green lead paint on platform upstands					
23458	ACTIVE	P	D213-00-2/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - South Ealing Stn		Asbestos	Surveyed – Not Detected				Canopy - Supalux					
23457	ACTIVE	P	D213-00-2/262/FLR-01	Floor - 1 - Platform 2 - Station Building - South Ealing Stn	Void	Asbestos	No Access: Presumed				Beneath Inspection Covers					Yes
23462	ACTIVE	P	D213-00-2/262/WDW-01	Window - 1 - Platform 1 - Station Building - South Ealing Stn	Lead/Leading	Lead Paint/Lead	Known				Waiting areas - window frames - white gloss. Thickness : 0.35mm Analysis : 2.8%					
23463	ACTIVE	P	D213-00-2/262/WDW-02	Window - 2 - Platform 1 - Station Building - South Ealing Stn	Lead/Leading	Lead Paint/Lead	Known				Waiting areas - window frames - white gloss. Thickness : 0.35mm Analysis : 2.8%					
5171	ACTIVE	P	D213-00-2/263	Platform 3 - Westbound Fast - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23467	ACTIVE	P	D213-00-2/263	Platform 3 - Westbound Fast - Station Building - South Ealing Stn	Lead/Leading	Lead Paint/Lead	Removed				Waiting areas - Lower panel - green gloss. Thickness : 0.09mm Analysis : 1.1% Waiting rooms have been removed and re-placed with new (NAD) HMU Re-Inspection - 19/05/2016					
23877	ACTIVE	P	D213-00-2/263	Platform 3 - Westbound Fast - Station Building - South Ealing Stn	Lead/Leading	Lead Paint/Lead	Removed				Waiting areas - window frames - white gloss. Thickness : 0.35mm Analysis : 2.8%					
24034	ACTIVE	P	D213-00-2/263	Platform 3 - Westbound Fast - Station Building - South Ealing Stn	Lead/Leading	Lead Paint/Lead	Removed				Waiting areas - window frames - white gloss. Thickness : 0.35mm Analysis : 2.8%					
23466	ACTIVE	P	D213-00-2/263	Platform 3 - Westbound Fast - Station Building - South Ealing Stn	Lead/Leading	Lead Paint/Lead	Removed				Waiting areas - side panels - green gloss. Thickness : 0.02mm Analysis : 1.3% Waiting rooms have been removed and re-placed with new (NAD) HMU Re-Inspection - 19/05/2016					
23465	ACTIVE	P	D213-00-2/263/CLG-01	Ceiling: Solid - 1 - Platform 3 - Station Building - South Ealing Stn	Void	Asbestos	No Access: Presumed				Above Supalux				Yes	
23464	ACTIVE	P	D213-00-2/263/CLG-01	Ceiling: Solid - 1 - Platform 3 - Station Building - South Ealing Stn		Asbestos	Surveyed – Not Detected				Supalux					
5172	ACTIVE	P	D213-00-2/264	Platform 4 - Westbound Local - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D213-00 - Station Building - South Ealing Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23468	ACTIVE	P	D213-00-2/264	Platform 4 - Westbound Local - Station Building - South Ealing Stn		Asbestos	Surveyed – Not Detected				Ceiling - Supalux					
23469	ACTIVE	P	D213-00-2/264	Platform 4 - Westbound Local - Station Building - South Ealing Stn	Void	Asbestos	No Access: Presumed				Above Supalux ceiling					
23471	ACTIVE	P	D213-00-2/264	Platform 4 - Westbound Local - Station Building - South Ealing Stn	Lead/Leading	Lead Paint/Lead	Removed				Waiting areas - Lower panel - green gloss. Thickness : 0.09mm Analysis : 1.1% Waiting rooms have been removed and re-placed with new (NAD) HMU Re-Inspection - 19/05/2016					
23472	ACTIVE	P	D213-00-2/264	Platform 4 - Westbound Local - Station Building - South Ealing Stn	Lead/Leading	Lead Paint/Lead	Removed				Waiting areas - window frames - white gloss. Thickness : 0.35mm Analysis : 2.8% Waiting rooms have been removed and re-placed with new (NAD) HMU Re-Inspection - 19/05/2016					
23878	ACTIVE	P	D213-00-2/264	Platform 4 - Westbound Local - Station Building - South Ealing Stn	Lead/Leading	Lead Paint/Lead	Removed				Waiting areas - window frames - white gloss. Thickness : 0.35mm Analysis : 2.8%					
23470	ACTIVE	P	D213-00-2/264	Platform 4 - Westbound Local - Station Building - South Ealing Stn	Lead/Leading	Lead Paint/Lead	Removed				Waiting areas - side panels - green gloss. Thickness : 0.02mm Analysis : 1.3% Waiting rooms have been removed and re-placed with new (NAD) HMU Re-Inspection - 19/05/2016					
5173	ACTIVE	P	D213-00-2/411	Store - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5174	ACTIVE	P	D213-00-2/436	Waiting Room - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23473	ACTIVE	P	D213-00-2/436/CLG-01	Ceiling: Solid - 1 - Waiting Room - Station Building - South Ealing Stn		Asbestos	Surveyed – Not Detected				Supalux					
23474	ACTIVE	P	D213-00-2/436/CLG-01	Ceiling: Solid - 1 - Waiting Room - Station Building - South Ealing Stn	Void	Asbestos	No Access: Presumed				Above Supalux				Yes	
5175	ACTIVE	P	D213-00-2/662	Switch Room - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23879	ACTIVE	P	D213-00-2/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - South Ealing Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes - 4 x 60amp No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		4			



Hazardous Material Asset Register - Summary



D213-00 - Station Building - South Ealing Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23475	ACTIVE	P	D213-00-2/662/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - South Ealing Stn	Other Electrical Boxes	Asbestos	Presumed				Wall 5 (not in Maximo) 1 x Transformer Box insulation withing No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
5176	ACTIVE	P	D213-00-2/731	CER - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46383	ACTIVE	P	D213-00-2/731	CER - Station Building - South Ealing Stn	Mastic	Asbestos	Sampled – Not Detected				Brown mastic to external door frame			R670801	N	N
46382	ACTIVE	P	D213-00-2/731/CLG-01	Ceiling: Solid - 1 - CER - Station Building - South Ealing Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux residue - panel remnant to ceiling by wall 2 by purple cables	1		R670801	N	N
23477	ACTIVE	P	D213-00-2/731/CLG-01	Ceiling: Solid - 1 - CER - Station Building - South Ealing Stn	Cable Duct: Other	Asbestos	Presumed				Sealed Cable sleeves in ceiling - No Access - Presumed					
46380	ACTIVE	P	D213-00-2/731/WAL-001	Wall: Internal - 1 - CER - Station Building - South Ealing Stn		Asbestos	Sampled – Not Detected				Bitumen damp proof course to base of wall 1	2		R670801	N	N
23476	INACTIVE	P	D213-00-2/731/WAL-002	Wall: Internal - 2 - CER - Station Building - South Ealing Stn	Other Boarding	Asbestos	Removed				Paxoline boarding					
46384	INACTIVE	P	D213-00-2/731/WAL-002	Wall: Internal - 2 - CER - Station Building - South Ealing Stn	Other Boarding	Asbestos	Known				Brown composite board to wall 2 at high level	1	1	R670801	N	N
46381	ACTIVE	P	D213-00-2/731/WAL-004	Wall: Internal - 4 - CER - Station Building - South Ealing Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux panel to wall 4 above door	1	1	R670801	N	N
5177	ACTIVE	P	D213-00-2/761	Equipment Room - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5178	ACTIVE	P	D213-00-A/761	Equipment Room - Station Building - South Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23372	ACTIVE	P	D213-00-A/761/CLG-01	Ceiling: Solid - 1 - Equipment Room - Station Building - South Ealing Stn	Void	Asbestos	No Access: Presumed				Above foam ceiling				Yes	
23478	ACTIVE	P	D213-00-A/761/FLR-01	Floor - 1 - Equipment Room - Station Building - South Ealing Stn	Void	Asbestos	No Access: Presumed				Beneath wooden floor					Yes

D215-00 - Station Building - Northfields Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5180	ACTIVE	P	D215-00-1/001	Booking Hall - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D215-00 - Station Building - Northfields Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5181	ACTIVE	P	D215-00-1/011	Ticket Office - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23376	ACTIVE	P	D215-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Northfields Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
23377	ACTIVE	P	D215-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Northfields Stn	Void	Asbestos	Surveyed – Not Detected				Concrete & glass lights above Supalux Tiles				Yes	
23375	ACTIVE	P	D215-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Northfields Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer flooring					Yes
5182	ACTIVE	P	D215-00-1/021	POM - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23378	ACTIVE	P	D215-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Northfields Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer flooring					Yes
5183	ACTIVE	P	D215-00-1/031	Mess Room - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23379	ACTIVE	P	D215-00-1/031	Mess Room - Station Building - Northfields Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Foam backing behind LUL heater		1			
23380	ACTIVE	P	D215-00-1/031/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Northfields Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard above extractor fan					
5184	ACTIVE	P	D215-00-1/036	Toilet: Unisex - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5185	ACTIVE	P	D215-00-1/082	Lobby - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42357	ACTIVE	P	D215-00-1/082/DORS	Doors - Lobby - Station Building - Northfields Stn	Lead/Leading	Lead Paint/Lead	Presumed				Red Gloss Door - Lead paint presumed		1		N	N
23381	ACTIVE	P	D215-00-1/082/WAL-005	Wall: Internal - 5 - Lobby - Station Building - Northfields Stn	LUL Heaters	Asbestos	Strongly Presumed				2 x White backing boards LUL Heater		2			
5186	ACTIVE	P	D215-00-1/083	Lobby - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23382	ACTIVE	P	D215-00-1/083/FLR-01	Floor - 1 - Lobby - Station Building - Northfields Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl flooring					
5187	ACTIVE	P	D215-00-1/085	Lobby - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D215-00 - Station Building - Northfields Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5188	ACTIVE	P	D215-00-1/196	Footpath - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5189	ACTIVE	P	D215-00-1/197	Footpath - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23383	ACTIVE	P	D215-00-1/197	Footpath - Station Building - Northfields Stn	Glazing Rope	Asbestos	Presumed				110m Rope Gasket in glazing bars on walkway					
5190	ACTIVE	P	D215-00-1/236	Passage - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23384	ACTIVE	P	D215-00-1/236/FLR-01	Floor - 1 - Passage - Station Building - Northfields Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer flooring/tiles					Yes
5191	ACTIVE	P	D215-00-1/237	Passage - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5192	ACTIVE	P	D215-00-1/281	Office - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23386	ACTIVE	P	D215-00-1/281/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Northfields Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
23387	ACTIVE	P	D215-00-1/281/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Northfields Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above plasterboard				Yes	
23385	ACTIVE	P	D215-00-1/281/FLR-01	Floor - 1 - Office - Station Building - Northfields Stn	Void	Asbestos	Surveyed – Not Detected				Vinyl beneath carpet tiles					Yes
5193	ACTIVE	P	D215-00-1/291	Locker Room - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23388	ACTIVE	P	D215-00-1/291/WAL-001	Wall: Internal - 1 - Locker Room - Station Building - Northfields Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard no access behind					
42317	ACTIVE	P	D215-00-1/292	Office - Station Building - Northfields Stn	Cable: Sheath	Asbestos	Strongly Presumed				Encapsulated cables in corner of walls 2 & 3 in room 1/292		4			
5194	ACTIVE	P	D215-00-1/295	Office - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23391	ACTIVE	P	D215-00-1/295/FLR-01	Floor - 1 - Office - Station Building - Northfields Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath carpet					Yes
5195	ACTIVE	P	D215-00-1/301	BTP Office - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D215-00 - Station Building - Northfields Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23392	ACTIVE	P	D215-00-1/301/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Northfields Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above fibreboard tiles				Yes	
5196	ACTIVE	P	D215-00-1/311	Office - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23868	ACTIVE	P	D215-00-1/311	Office - Station Building - Northfields Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				White foam backing		1			
5197	ACTIVE	P	D215-00-1/331	Store - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5198	ACTIVE	P	D215-00-1/351	Office - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23395	ACTIVE	P	D215-00-1/351/FLR-01	Floor - 1 - Office - Station Building - Northfields Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl flooring					
5199	ACTIVE	P	D215-00-1/352	Mess Room - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23869	ACTIVE	P	D215-00-1/352	Mess Room - Station Building - Northfields Stn	Bitumen	Asbestos	Surveyed – Not Detected				Acoustic panel under sink		1			
5200	ACTIVE	P	D215-00-1/406	Store - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5201	ACTIVE	P	D215-00-1/407	Store - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5202	ACTIVE	P	D215-00-1/411	Store - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23396	ACTIVE	P	D215-00-1/411/FLR-01	Floor - 1 - Store - Station Building - Northfields Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl flooring					
5203	ACTIVE	P	D215-00-1/412	Store - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23397	ACTIVE	P	D215-00-1/412/FLR-01	Floor - 1 - Store - Station Building - Northfields Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl flooring					
5204	ACTIVE	P	D215-00-1/414	Store - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5205	ACTIVE	P	D215-00-1/416	Toilet: Female - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D215-00 - Station Building - Northfields Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5206	ACTIVE	P	D215-00-1/417	Toilet: Male - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5207	ACTIVE	P	D215-00-1/426	Toilet: Female - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5208	ACTIVE	P	D215-00-1/427	Toilet: Male - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5209	ACTIVE	P	D215-00-1/451	Tenancy - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5210	ACTIVE	P	D215-00-1/551	Yard - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23398	ACTIVE	P	D215-00-1/576	Stairs - Station Building - Northfields Stn	Lead/Leading	Lead Paint/Lead	Known				(Not on Maximo) Stairs - All walls in office & stair case - 90m² Green emulsion. Thickness : 0.49mm Analysis : 4.6%					
5211	ACTIVE	P	D215-00-1/577	Stairs: Linear - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23870	ACTIVE	P	D215-00-1/577	Stairs: Linear - Station Building - Northfields Stn	Glazing Rope	Asbestos	Presumed				110m Rope Gasket - In glazing bars on walkway					
5212	ACTIVE	P	D215-00-1/601	Stairs: Linear - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5213	ACTIVE	P	D215-00-1/602	Stairs: Linear - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5214	ACTIVE	P	D215-00-1/661	Switch Room - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23399	ACTIVE	P	D215-00-1/661/ DOR-01	Door - 1 - Switch Room - Station Building - Northfields Stn		Asbestos	Surveyed – Not Detected				Supalux panel on door					
42318	ACTIVE	P	D215-00-1/661/ WAL-001 80874883	Wall: Internal - 1 - Switch Room - Station Building - Northfields Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				Transformer box at high level		1			
42353	ACTIVE	P	D215-00-1/661/ WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Northfields Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Trunking running along walls 1 & 2				N	N
23403	ACTIVE	P	D215-00-1/661/ WAL-002 80874884	Wall: Internal - 2 - Switch Room - Station Building - Northfields Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				Trunking along walls 1 & 2					



Hazardous Material Asset Register - Summary



D215-00 - Station Building - Northfields Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23402	ACTIVE	P	D215-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Northfields Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x Switch Boxes 1 x 100amp		1			
23400	ACTIVE	P	D215-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Northfields Stn	Isolator Switches	Asbestos	Strongly Presumed				6 x Switch Boxes 2 x 60, 2 x 100, & 2 x 200 amps		6			
23401	ACTIVE	P	D215-00-1/661/WAL-003 80874885	Wall: Internal - 3 - Switch Room - Station Building - Northfields Stn Wall: Internal	Other Electrical Boxes	Asbestos	Strongly Presumed				Trunking and busbar					
5215	ACTIVE	P	D215-00-1/662	Switch Room - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23704	ACTIVE	P	D215-00-1/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Northfields Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Box - 1x 200amp		1			
5216	ACTIVE	P	D215-00-1/664	Switch Room - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23407	ACTIVE	P	D215-00-1/664/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Northfields Stn	Other Electrical Boxes	Asbestos	Presumed				Trunking					
23404	ACTIVE	P	D215-00-1/664/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Northfields Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes x 6 - 5 x 60amp 1 x100amp		6			
23405	ACTIVE	P	D215-00-1/664/WAL-001 80874897	Wall: Internal - 1 - Switch Room - Station Building - Northfields Stn Wall: Internal	Other Electrical Boxes	Asbestos	Strongly Presumed				Trunking / busbar		1			
23406	ACTIVE	P	D215-00-1/664/WAL-003 80874899	Wall: Internal - 3 - Switch Room - Station Building - Northfields Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes 1 x 30 amp		1			
23408	ACTIVE	P	D215-00-1/664/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Northfields Stn	Other Electrical Boxes	Asbestos	Presumed				3 x Transformer Box		3			
23409	ACTIVE	P	D215-00-1/664/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Northfields Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box		1			
5217	ACTIVE	P	D215-00-1/746	SCR - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5218	ACTIVE	P	D215-00-1/801	Tenancy - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23411	ACTIVE	P	D215-00-1/801/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Northfields Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	



Hazardous Material Asset Register - Summary



D215-00 - Station Building - Northfields Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23410	ACTIVE	P	D215-00-1/801/FLR-01	Floor - 1 - Tenancy - Station Building - Northfields Stn	Void	Asbestos	Surveyed – Not Detected				Underlay/concrete beneath carpet tiles					Yes
5219	ACTIVE	P	D215-00-1/901	Plant Room - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5220	ACTIVE	P	D215-00-1/902	Plant Room - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42316	ACTIVE	P	D215-00-1/902/WAL-001 80874937	Wall: Internal - 1 - Plant Room - Station Building - Northfields Stn Wall: Internal	Control Panels	Asbestos	Presumed				Plant equipment located on floor by wall one, potential asbestos components within		1			
23413	ACTIVE	P	D215-00-1/902/WAL-002	Wall: Internal - 2 - Plant Room - Station Building - Northfields Stn	Gasket :Pipework	Asbestos	Strongly Presumed				Gaskets to Pump Equipment		2			
23412	ACTIVE	P	D215-00-1/902/WAL-004 80874940	Wall: Internal - 4 - Plant Room - Station Building - Northfields Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				1 x 30amp Switch Box		1			
5221	ACTIVE	P	D215-00-1/903	Lobby - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24032	ACTIVE	P	D215-00-1/903/FLR-01	Floor - 1 - Lobby - Station Building - Northfields Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl					
5222	ACTIVE	P	D215-00-1/904	Store - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23414	ACTIVE	P	D215-00-1/904/FLR-01	Floor - 1 - Store - Station Building - Northfields Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl					
5223	ACTIVE	P	D215-00-1/905	Locker Room - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23871	ACTIVE	P	D215-00-1/905/FLR-01	Floor - 1 - Locker Room - Station Building - Northfields Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl					
5224	ACTIVE	P	D215-00-1/906	Lobby - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23417	ACTIVE	P	D215-00-1/906/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Northfields Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, glass rock panel above false ceiling				Yes	
23416	ACTIVE	P	D215-00-1/906/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Northfields Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
23415	ACTIVE	P	D215-00-1/906/FLR-01	Floor - 1 - Lobby - Station Building - Northfields Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl					



Hazardous Material Asset Register - Summary



D215-00 - Station Building - Northfields Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5225	ACTIVE	P	D215-00-1/907	Locker Room - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5226	ACTIVE	P	D215-00-1/908	Mess Room - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23419	ACTIVE	P	D215-00-1/908/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Northfields Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
23872	ACTIVE	P	D215-00-1/908/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Northfields Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
23418	ACTIVE	P	D215-00-1/908/FLR-01	Floor - 1 - Mess Room - Station Building - Northfields Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl					
5227	ACTIVE	P	D215-00-2/081	Lobby - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5228	ACTIVE	P	D215-00-2/261	Platform 1 - Westbound Local - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43254	ACTIVE	P	D215-00-2/261	Platform 1 - Westbound Local - Station Building - Northfields Stn	Cable: Sheath	Asbestos	Presumed				Platform Indicator Box suspected asbestos cables within Example Photo				N	N
42355	ACTIVE	P	D215-00-2/261	Platform 1 - Westbound Local - Station Building - Northfields Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Train indicator board asbestos presumed		1		N	N
23424	ACTIVE	P	D215-00-2/261	Platform 1 - Westbound Local - Station Building - Northfields Stn	No Access	Asbestos	No Access: Presumed				Platform 1 Invert - Not surveyed - Cables strongly presumed					
23423	ACTIVE	P	D215-00-2/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Northfields Stn	Glazing Rope	Asbestos	Strongly Presumed				Rope gaskets to glass roof lights - some of the gaskets have been removed and some still remain					
23873	ACTIVE	P	D215-00-2/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Northfields Stn	Void	Asbestos	Surveyed – Not Detected				Beneath manhole cover/cable pits throughout platform					Yes
5229	ACTIVE	P	D215-00-2/262	Platform 2 - Westbound Fast - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24772	ACTIVE	P	D215-00-2/262	Platform 2 - Westbound Fast - Station Building - Northfields Stn	No Access	Asbestos	No Access: Presumed				Platform 2 Invert - Not surveyed - Cables strongly presumed					
42356	ACTIVE	P	D215-00-2/262	Platform 2 - Westbound Fast - Station Building - Northfields Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Train indicator board asbestos presumed		1		N	N



Hazardous Material Asset Register - Summary



D215-00 - Station Building - Northfields Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24771	ACTIVE	P	D215-00-2/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - Northfields Stn	Glazing Rope	Asbestos	Strongly Presumed				Rope gaskets to glass roof lights - some of the gaskets have been removed and some still remain					
24770	ACTIVE	P	D215-00-2/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Northfields Stn	Void	Asbestos	Surveyed – Not Detected				Beneath manhole cover/cable pits throughout platform 2					Yes
5230	ACTIVE	P	D215-00-2/263	Platform 3 - Eastbound Fast - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
24775	ACTIVE	P	D215-00-2/263	Platform 3 - Eastbound Fast - Station Building - Northfields Stn	No Access	Asbestos	No Access: Presumed				Platform 3 Invert - Not surveyed - Cables strongly presumed					
42354	ACTIVE	P	D215-00-2/263	Platform 3 - Eastbound Fast - Station Building - Northfields Stn	Other Electrical Boxes	Asbestos	Presumed				Train indicator board asbestos presumed		1		N	N
24774	ACTIVE	P	D215-00-2/263/CLG-01	Ceiling: Solid - 1 - Platform 3 - Station Building - Northfields Stn	Glazing Rope	Asbestos	Strongly Presumed				Rope gaskets to glass roof lights - some of the gaskets have been removed and some still remain					
24773	ACTIVE	P	D215-00-2/263/FLR-01	Floor - 1 - Platform 3 - Station Building - Northfields Stn	Void	Asbestos	No Access: Presumed				Beneath manhole cover					Yes
5231	ACTIVE	P	D215-00-2/264	Platform 4 - Eastbound Local - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42320	ACTIVE	P	D215-00-2/264	Platform 4 - Eastbound Local - Station Building - Northfields Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Train indicator board asbestos presumed - asset number 00271050		1			
24778	ACTIVE	P	D215-00-2/264	Platform 4 - Eastbound Local - Station Building - Northfields Stn	No Access	Asbestos	No Access: Presumed				Platform 4 Invert - Not surveyed - Cables strongly presumed					
24777	ACTIVE	P	D215-00-2/264/CLG-01	Ceiling: Solid - 1 - Platform 4 - Station Building - Northfields Stn	Glazing Rope	Asbestos	Strongly Presumed				Rope gaskets to glass roof lights - some of the gaskets have been removed and some still remain					
24776	ACTIVE	P	D215-00-2/264/FLR-01	Floor - 1 - Platform 4 - Station Building - Northfields Stn	Void	Asbestos	No Access: Presumed				Beneath manhole cover					Yes
68604	ACTIVE	P	D215-00-2/331	Mess Room - Station Building - Northfields Stn		Asbestos	Surveyed – Not Detected				New Building - Constructed Circa 2013					
5232	ACTIVE	P	D215-00-2/411	Store - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5233	ACTIVE	P	D215-00-2/412	Store - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24779	ACTIVE	P	D215-00-2/413	Office - Station Building - Northfields Stn	Lead/Leading	Lead Paint/Lead	Known				All walls to store room - 60m ² Brown emulsion. Thickness : 0.23mm Analysis : 8.1%					



Hazardous Material Asset Register - Summary



D215-00 - Station Building - Northfields Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5234	ACTIVE	P	D215-00-2/436	Waiting Room - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5235	ACTIVE	P	D215-00-2/437	Waiting Room - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5236	ACTIVE	P	D215-00-2/481	Disused Room - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5237	ACTIVE	P	D215-00-2/661	Switch Room - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24784	ACTIVE	P	D215-00-2/661/FLR-01	Floor - 1 - Switch Room - Station Building - Northfields Stn	Boarding: Cement	Asbestos	Known				Hatch Room behind 2/661 - 2x Cement panels (0.5m²)		2			
24780	ACTIVE	P	D215-00-2/661/FLR-01	Floor - 1 - Switch Room - Station Building - Northfields Stn	Void	Asbestos	Surveyed – Not Detected				Beneath metal hatch					Yes
24783	ACTIVE	P	D215-00-2/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Northfields Stn	Other Electrical Boxes	Asbestos	Presumed				2 x Transformer Boxes		2			
24781	ACTIVE	P	D215-00-2/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Northfields Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes 3 x 60amp 1x100amp		4			
24782	ACTIVE	P	D215-00-2/661/WAL-002 80875115	Wall: Internal - 2 - Switch Room - Station Building - Northfields Stn Wall: Internal	Other Electrical Boxes	Asbestos	Strongly Presumed				Trunking & busbar					
5238	ACTIVE	P	D215-00-2/761	CER - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5239	ACTIVE	P	D215-00-2/901	Disused Room - Station Building - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20302	ACTIVE	P	D215-00-2/901/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Northfields Stn	Lead/Leading	Lead Paint/Lead	Sampled – Not Detected				Cream Matt Paint					
24789	INACTIVE	P	D215-00-2/901/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Northfields Stn	Lead/Leading	Lead Paint/Lead	Sampled – Not Detected				Cream Matt Thickness: 280µm, Analysis: <0.01					
20299	ACTIVE	P	D215-00-2/901/DOR-01	Door - 1 - Disused Room - Station Building - Northfields Stn	Lead/Leading	Lead Paint/Lead	Sampled – Not Detected				R411726 14/07/2014 - Lead Paint Content					
24786	INACTIVE	P	D215-00-2/901/DOR-01	Door - 1 - Disused Room - Station Building - Northfields Stn	Lead/Leading	Lead Paint/Lead	Sampled – Not Detected				Red Gloss Thickness:190µm, Analysis: <0.01					



Hazardous Material Asset Register - Summary



D215-00 - Station Building - Northfields Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24787	INACTIVE	P	D215-00-2/901/DOR-01	Door - 1 - Disused Room - Station Building - Northfields Stn	Lead/Leading	Lead Paint/Lead	Sampled – Not Detected				Door Frame - White Gloss Thickness: 340μ, Analysis: 0.05					
24785	ACTIVE	P	D215-00-2/901/FLR-01	Floor - 1 - Disused Room - Station Building - Northfields Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl on wood					
25389	ACTIVE	P	D215-00-2/901/FLR-01	Floor - 1 - Disused Room - Station Building - Northfields Stn	Void	Asbestos	No Access: Presumed				Beneath wooden floor					Yes
20304	ACTIVE	P	D215-00-2/901/WAL-001	Wall: Internal - 1 - Disused Room - Station Building - Northfields Stn	Lead/Leading	Lead Paint/Lead	Sampled – Not Detected				Cream Matt Paint					
24790	INACTIVE	P	D215-00-2/901/WAL-001	Wall: Internal - 1 - Disused Room - Station Building - Northfields Stn	Lead/Leading	Lead Paint/Lead	Sampled – Not Detected				Walls - Cream Matt Thickness: 360μm, Analysis: <0.01					
20305	ACTIVE	P	D215-00-2/901/WAL-002	Wall: Internal - 2 - Disused Room - Station Building - Northfields Stn	Lead/Leading	Lead Paint/Lead	Sampled – Not Detected				Cream matt Paint					
20306	ACTIVE	P	D215-00-2/901/WAL-003	Wall: Internal - 3 - Disused Room - Station Building - Northfields Stn	Lead/Leading	Lead Paint/Lead	Sampled – Not Detected				Cream Matt Paint					
20307	ACTIVE	P	D215-00-2/901/WAL-004	Wall: Internal - 4 - Disused Room - Station Building - Northfields Stn	Lead/Leading	Lead Paint/Lead	Sampled – Not Detected				Cream Matt Paint					
20301	ACTIVE	P	D215-00-2/901/WDW-01	Window - 1 - Disused Room - Station Building - Northfields Stn	Lead/Leading	Lead Paint/Lead	Sampled – Not Detected				White Gloss Paint					
24788	INACTIVE	P	D215-00-2/901/WDW-01	Window - 1 - Disused Room - Station Building - Northfields Stn	Lead/Leading	Lead Paint/Lead	Sampled – Not Detected				White Gloss Thickness:190μm, Analysis: <0.01					
42319	ACTIVE	P	D215-00/CPY-01 80955394	Canopy - 1 - Station Building - Northfields Stn Structure: Canopy	Other Electrical Boxes	Asbestos	Presumed				Platform indicator box suspected asbestos cables within Example Photo		1			
43256	ACTIVE	P	D215-00/CPY-02	Canopy - 2 - Station Building - Northfields Stn	Cable: Sheath	Asbestos	Presumed				Platform Indicator box suspected asbestos cable within Example Photo				N	N

D217-00 - Station Building - Boston Manor Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5256	ACTIVE	P	D217-00-1/001	Booking Hall - Station Building - Boston Manor Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D217-00 - Station Building - Boston Manor Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24791	ACTIVE	P	D217-00-1/001/WAL-001	Wall: Internal - 1 - Booking Hall - Station Building - Boston Manor Stn	Lead/Leading	Lead Paint/Lead	Removed				Around photo booth - blue on green gloss - 2m². Thickness : 0.51mm Analysis : 5.0%					
24314	ACTIVE	P	D217-00-1/001/WAL-006	Wall: Internal - 6 - Booking Hall - Station Building - Boston Manor Stn	Lead/Leading	Lead Paint/Lead	Known				Around poster boards - blue on green gloss - 2m². Thickness : 0.51mm Analysis : 5.0%					
5257	ACTIVE	P	D217-00-1/011	Ticket Office - Station Building - Boston Manor Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24793	ACTIVE	P	D217-00-1/011	Ticket Office - Station Building - Boston Manor Stn		Asbestos	Surveyed – Not Detected				Supalux					
24792	ACTIVE	P	D217-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Boston Manor Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
5258	ACTIVE	P	D217-00-1/021	POM - Station Building - Boston Manor Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24794	ACTIVE	P	D217-00-1/021	POM - Station Building - Boston Manor Stn		Asbestos	Surveyed – Not Detected				Supalux Boxing panel for vent unit					
25391	ACTIVE	P	D217-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Boston Manor Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
5259	ACTIVE	P	D217-00-1/031	Mess Room - Station Building - Boston Manor Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24878	ACTIVE	P	D217-00-1/031	Mess Room - Station Building - Boston Manor Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				2x LTB heater - foam panels		2			
24875	ACTIVE	P	D217-00-1/031/FLR-01	Floor - 1 - Mess Room - Station Building - Boston Manor Stn	Void	Asbestos	No Access: Presumed				Beneath Lino - No reference to floor structure - Potential False Floor?					Yes
24876	ACTIVE	P	D217-00-1/031/WAL-006	Wall: Internal - 6 - Mess Room - Station Building - Boston Manor Stn	Bitumen	Asbestos	Surveyed – Not Detected				0.06m² Sink acoustic panel		1			
24877	ACTIVE	P	D217-00-1/031/WAL-011	Wall: Internal - 11 - Mess Room - Station Building - Boston Manor Stn		Asbestos	Surveyed – Not Detected				Supalux - 2 sides of partition wall					
5260	ACTIVE	P	D217-00-1/036	Toilet: Unisex - Station Building - Boston Manor Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5261	ACTIVE	P	D217-00-1/081	Lobby - Station Building - Boston Manor Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24879	ACTIVE	P	D217-00-1/081/FLR-01	Floor - 1 - Lobby - Station Building - Boston Manor Stn	Void	Asbestos	No Access: Presumed				Beneath Lino - No reference to floor structure - Potential False Floor?					Yes



Hazardous Material Asset Register - Summary



D217-00 - Station Building - Boston Manor Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5262	ACTIVE	P	D217-00-1/426	Toilet: Male - Station Building - Boston Manor Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24881	ACTIVE	P	D217-00-1/426/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Boston Manor Stn	Void	Asbestos	No Access: Presumed				Above ceiling hatch				Yes	
24880	ACTIVE	P	D217-00-1/426/FLR-01	Floor - 1 - Toilet - Station Building - Boston Manor Stn	Void	Asbestos	Surveyed – Not Detected				Drain below hatch					Yes
5263	ACTIVE	P	D217-00-1/427	Toilet: Female - Station Building - Boston Manor Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24882	ACTIVE	P	D217-00-1/427/FLR-01	Floor - 1 - Toilet - Station Building - Boston Manor Stn	Void	Asbestos	Surveyed – Not Detected				Stairs below hatch					Yes
5264	ACTIVE	P	D217-00-1/451	Tenancy - Station Building - Boston Manor Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24885	ACTIVE	P	D217-00-1/451/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Boston Manor Stn	Void	Asbestos	No Access: Presumed				Above Wood Panel on ceiling above wall 4				Yes	
24884	ACTIVE	P	D217-00-1/451/FLR-01	Floor - 1 - Tenancy - Station Building - Boston Manor Stn	Void	Asbestos	Surveyed – Not Detected				Wooden solid floor beneath Lino					Yes
24889	ACTIVE	P	D217-00-1/451/FLR-01	Floor - 1 - Tenancy - Station Building - Boston Manor Stn	Void	Asbestos	No Access: Presumed				Tenancy Main Office - beneath wooden slats					
24888	ACTIVE	P	D217-00-1/451/FLR-01	Floor - 1 - Tenancy - Station Building - Boston Manor Stn	Void	Asbestos	Surveyed – Not Detected				Solid beneath Lino					Yes
24883	ACTIVE	P	D217-00-1/451/FLR-01	Floor - 1 - Tenancy - Station Building - Boston Manor Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
24887	ACTIVE	P	D217-00-1/451/FLR-01	Floor - 1 - Tenancy - Station Building - Boston Manor Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Tennancy Lobby - Lino					
24886	ACTIVE	P	D217-00-1/451/WAL-003	Wall: Internal - 3 - Tenancy - Station Building - Boston Manor Stn	Bitumen	Asbestos	Surveyed – Not Detected				Sink acoustic panel		1			
5265	ACTIVE	P	D217-00-1/601	Stairs: Linear - Station Building - Boston Manor Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24318	ACTIVE	P	D217-00-1/601	Stairs: Linear - Station Building - Boston Manor Stn	Glazing Rope	Asbestos	Strongly Presumed				Canopy - glass & metal glazing bars					
45180	ACTIVE	P	D217-00-1/601	Stairs: Linear - Station Building - Boston Manor Stn	Lead/Leading	Lead Paint/Lead	Known				Railings - Green gloss - 8m²	8			N	N
45179	ACTIVE	P	D217-00-1/601	Stairs: Linear - Station Building - Boston Manor Stn	Lead/Leading	Lead Paint/Lead	Known				Skirting board - Red gloss - 5m²	5			N	N



Hazardous Material Asset Register - Summary



D217-00 - Station Building - Boston Manor Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24890	ACTIVE	P	D217-00-1/601/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Boston Manor Stn	Void	Asbestos	No Access: Presumed				Above wooden beams & roofing				Yes	
5266	ACTIVE	P	D217-00-1/602	Stairs: Linear - Station Building - Boston Manor Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24892	ACTIVE	P	D217-00-1/602	Stairs: Linear - Station Building - Boston Manor Stn	Glazing Rope	Asbestos	Strongly Presumed				Canopy - glass & metal glazing bars					
24893	ACTIVE	P	D217-00-1/602	Stairs: Linear - Station Building - Boston Manor Stn	Lead/Leading	Lead Paint/Lead	Known				Skirting board - Red gloss - 5m². Thickness : 0.96mm Analysis : 3.8%					
25476	ACTIVE	P	D217-00-1/602	Stairs: Linear - Station Building - Boston Manor Stn	Lead/Leading	Lead Paint/Lead	Known				Railings - Green gloss - 8m². Thickness : 0.50mm Analysis : 5.8%					
24891	ACTIVE	P	D217-00-1/602/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Boston Manor Stn	Void	Asbestos	No Access: Presumed				Above wooden beams & roofing				Yes	
5267	ACTIVE	P	D217-00-2/081	Lobby - Station Building - Boston Manor Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25477	ACTIVE	P	D217-00-2/081	Lobby - Station Building - Boston Manor Stn	Void	Asbestos	Surveyed – Not Detected				(Not on Maximo) Lobby Above false ceiling -solid walls, ceiling & ducting					Yes
24897	ACTIVE	P	D217-00-2/081	Lobby - Station Building - Boston Manor Stn	Other Boarding	Asbestos	Surveyed – Not Detected				(Not on Maximo) Lobby Ceiling - Plasterboard					
5268	ACTIVE	P	D217-00-2/261	Platform 1 - Westbound Local - Station Building - Boston Manor Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24900	ACTIVE	P	D217-00-2/261	Platform 1 - Westbound Local - Station Building - Boston Manor Stn	Rope Seals	Asbestos	Strongly Presumed				11x glass canopy with metal glazing bars - no access to rope seals		11			
24901	ACTIVE	P	D217-00-2/261	Platform 1 - Westbound Local - Station Building - Boston Manor Stn	Lead/Leading	Lead Paint/Lead	Known				5x 5m² Poster board surrounds - Green gloss. Thickness : 0.5mm Analysis : 5.8%					
24418	ACTIVE	P	D217-00-2/261	Platform 1 - Westbound Local - Station Building - Boston Manor Stn	Lead/Leading	Lead Paint/Lead	Known				Canopy window frames - black on white gloss 2-4m². Thickness : 0.06mm Analysis : 2.5%					
25478	ACTIVE	P	D217-00-2/261	Platform 1 - Westbound Local - Station Building - Boston Manor Stn	Lead/Leading	Lead Paint/Lead	Known				Canopy window frames - White gloss - 2x 4m². Thickness : 0.09mm Analysis 2.6%					
24902	ACTIVE	P	D217-00-2/261	Platform 1 - Westbound Local - Station Building - Boston Manor Stn	Lead/Leading	Lead Paint/Lead	Removed				Bin by platform - Green gloss - 2m². Thickness : 0.5mm Analysis : 5.8%					
24898	ACTIVE	P	D217-00-2/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Boston Manor Stn	Void	Asbestos	No Access: Presumed				Beneath 3x Drain covers					Yes



Hazardous Material Asset Register - Summary



D217-00 - Station Building - Boston Manor Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24899	ACTIVE	P	D217-00-2/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Boston Manor Stn	Void	Asbestos	Surveyed – Not Detected				Cables beneath Electrical covers					Yes
5269	ACTIVE	P	D217-00-2/262	Platform 2 - Eastbound Local - Station Building - Boston Manor Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24985	ACTIVE	P	D217-00-2/262	Platform 2 - Eastbound Local - Station Building - Boston Manor Stn	Rope Seals	Asbestos	Strongly Presumed				11x glass canopy with metal glazing bars - no access to rope seals		11			
24989	ACTIVE	P	D217-00-2/262	Platform 2 - Eastbound Local - Station Building - Boston Manor Stn	Lead/Leading	Lead Paint/Lead	Known				5x 5m ² Poster board surrounds - Green gloss. Thickness : 0.5mm Analysis : 5.8%					
24987	ACTIVE	P	D217-00-2/262	Platform 2 - Eastbound Local - Station Building - Boston Manor Stn	Lead/Leading	Lead Paint/Lead	Known				Canopy window frames - Black on white gloss - 2x 4m ² . Thickness : 0.06mm Analysis : 2.5%					
24988	ACTIVE	P	D217-00-2/262	Platform 2 - Eastbound Local - Station Building - Boston Manor Stn	Lead/Leading	Lead Paint/Lead	Known				Canopy window frames - White gloss - 2x 4m ² . Thickness : 0.09mm Analysis 2.6%					
24986	ACTIVE	P	D217-00-2/262	Platform 2 - Eastbound Local - Station Building - Boston Manor Stn	Lead/Leading	Lead Paint/Lead	Removed				Grit bins - Red/brown gloss - 2m ² . Thickness : 0.15mm Analysis : 1.9%					
24983	ACTIVE	P	D217-00-2/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Boston Manor Stn	Void	Asbestos	No Access: Presumed				Beneath Wood slats at bottom stairs					Yes
24984	ACTIVE	P	D217-00-2/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Boston Manor Stn	Void	Asbestos	No Access: Presumed				Beneath 3 x metal drains					Yes
24321	ACTIVE	P	D217-00-2/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Boston Manor Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Rubber lighting cables beneath 8x Electrical covers					
5270	ACTIVE	P	D217-00-2/281	Station Supervisor Office - Station Building - Boston Manor Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24990	ACTIVE	P	D217-00-2/281/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Boston Manor Stn	Void	Asbestos	Surveyed – Not Detected				Solid ceiling, solid walls, ducting, vent pipes & cable tray, fibreglass lagged pipes above metal tiles				Yes	
5271	ACTIVE	P	D217-00-2/331	Mess Room - Station Building - Boston Manor Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24991	ACTIVE	P	D217-00-2/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Boston Manor Stn	Void	Asbestos	Surveyed – Not Detected				Solid walls & ceiling, cable trays above metal tiles				Yes	
24992	ACTIVE	P	D217-00-2/331/WAL-003	Wall: Internal - 3 - Mess Room - Station Building - Boston Manor Stn	Bitumen	Asbestos	Surveyed – Not Detected				Sink acoustic panel		1			
5272	ACTIVE	P	D217-00-2/401	Bin Store - Station Building - Boston Manor Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D217-00 - Station Building - Boston Manor Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24993	ACTIVE	P	D217-00-2/401	Bin Store - Station Building - Boston Manor Stn	Lead/Leading	Lead Paint/Lead	Known				Drain pipe - white on black gloss - 3m ² . Thickness : 0.07mm Analysis : 2.1%					
5273	ACTIVE	P	D217-00-2/661	Switch Room - Station Building - Boston Manor Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24995	ACTIVE	P	D217-00-2/661	Switch Room - Station Building - Boston Manor Stn	Other Boarding	Asbestos	Presumed				Paxoline Board High Level					
24994	ACTIVE	P	D217-00-2/661/ WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Boston Manor Stn	Isolator Switches	Asbestos	Removed				Switch Box 1x 100amp		1			
5274	ACTIVE	P	D217-00-2/662	Switch Room - Station Building - Boston Manor Stn	Stations: Rooms	Asbestos	Room: Surveyed – Asbestos Known									
24997	ACTIVE	P	D217-00-2/662/ CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Boston Manor Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
24996	ACTIVE	P	D217-00-2/662/ FLR-01	Floor - 1 - Switch Room - Station Building - Boston Manor Stn	Void	Asbestos	Surveyed – Not Detected				Rubber cables, 3x cable sleeves beneath hatches					Yes
25487	ACTIVE	P	D217-00-2/662/ WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Boston Manor Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box		1			
24420	ACTIVE	P	D217-00-2/662/ WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Boston Manor Stn	Isolator Switches	Asbestos	Strongly Presumed				Swich Boxes - 7 x 60amp & 1 x 100amp		7			
24999	ACTIVE	P	D217-00-2/662/ WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Boston Manor Stn	Other Electrical Boxes	Asbestos	Presumed				3 x Transformer Box		3			
24998	ACTIVE	P	D217-00-2/662/ WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Boston Manor Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes 1 x 30amp		1			
5275	ACTIVE	P	D217-00-2/731	CER - Station Building - Boston Manor Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
25001	ACTIVE	P	D217-00-2/731/ CLG-01	Ceiling: Suspended - 1 - CER - Station Building - Boston Manor Stn	Void	Asbestos	No Access: Presumed				No Access above cladding to underside of Stairs				Yes	
25000	ACTIVE	P	D217-00-2/731/ WAL-001	Wall: Internal - 1 - CER - Station Building - Boston Manor Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Partition wall Supalux board					
5276	ACTIVE	P	D217-00-2/746	SCR - Station Building - Boston Manor Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D217-00 - Station Building - Boston Manor Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25003	ACTIVE	P	D217-00-2/746/CLG-01	Ceiling: Suspended - 1 - SCR - Station Building - Boston Manor Stn	Void	Asbestos	Surveyed – Not Detected				Solid walls, ceiling & ducts above false ceiling				Yes	
25002	ACTIVE	P	D217-00-2/746/CLG-01	Ceiling: Suspended - 1 - SCR - Station Building - Boston Manor Stn	Other Boarding	Asbestos	Presumed				Plasterboard					
5277	ACTIVE	P	D217-00-2/901	Store - Station Building - Boston Manor Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25488	ACTIVE	P	D217-00-2/901	Store - Station Building - Boston Manor Stn	Lead/Leading	Lead Paint/Lead	Known				Drain pipe - white on black gloss - 3m² . Thickness : 0.07mm Analysis : 2.1%					

D219-00 - Station Building - Osterley Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5283	ACTIVE	P	D219-00-1/001	Booking Hall - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25092	ACTIVE	P	D219-00-1/001	Booking Hall - Station Building - Osterley Stn	Lead/Leading	Lead Paint/Lead	Known				Around toilet entrance - Dark blue gloss - 3m². Thickness : 0.37mm Analysis : 2.1% has been over painted brown					
25091	ACTIVE	P	D219-00-1/001	Booking Hall - Station Building - Osterley Stn	Lead/Leading	Lead Paint/Lead	Known				Tenancy shutter 1/452 - Blue gloss - 3m². Thickness : 0.44mm Analysis : 1.2%					
25008	ACTIVE	P	D219-00-1/001/GTE-01	Gate: Collapsible - 1 - Booking Hall - Station Building - Osterley Stn	Lead/Leading	Lead Paint/Lead	Removed				Gates - Cream gloss - 15m². Thickness : 0.45mm Analysis : 2.4%					
25090	ACTIVE	P	D219-00-1/001/GTE-02	Gate: J Door Entry - 1 - Booking Hall - Station Building - Osterley Stn	Lead/Leading	Lead Paint/Lead	Removed				Gates - Cream gloss - 15m². Thickness : 0.45mm Analysis : 2.4%					
25007	ACTIVE	P	D219-00-1/001/WAL-003	Wall: Internal - 3 - Booking Hall - Station Building - Osterley Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding					
5284	ACTIVE	P	D219-00-1/011	Ticket Office - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25096	ACTIVE	P	D219-00-1/011	Ticket Office - Station Building - Osterley Stn	Debris: Cement	Asbestos	Known				Basement area below ticket office - Cement debris in spoil heap (surface debris cement)					
25094	ACTIVE	P	D219-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Osterley Stn		Asbestos	Surveyed – Not Detected				Supalux tiles, fibreglass lagging					
25095	ACTIVE	P	D219-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Osterley Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, brick, plastic cables, aircon, wood above false ceiling				Yes	



Hazardous Material Asset Register - Summary



D219-00 - Station Building - Osterley Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25093	ACTIVE	P	D219-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Osterley Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer flooring					Yes
5285	ACTIVE	P	D219-00-1/021	POM - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24324	ACTIVE	P	D219-00-1/021/CLG-01	Ceiling: Solid - 1 - POM - Station Building - Osterley Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
25099	ACTIVE	P	D219-00-1/021/CLG-01	Ceiling: Solid - 1 - POM - Station Building - Osterley Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard, Solid					
25097	ACTIVE	P	D219-00-1/021/WAL-001	Wall: Internal - 1 - POM - Station Building - Osterley Stn		Asbestos	Surveyed – Not Detected				Supalux panel					
25098	ACTIVE	P	D219-00-1/021/WAL-003	Wall: Internal - 3 - POM - Station Building - Osterley Stn		Asbestos	Surveyed – Not Detected				Supalux panel					
5286	ACTIVE	P	D219-00-1/061	Car Park - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5287	ACTIVE	P	D219-00-1/081	Lobby - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25102	ACTIVE	P	D219-00-1/081/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Osterley Stn		Asbestos	Surveyed – Not Detected				Part supalux, metal ducting, plaster, solid above false ceiling				Yes	
25100	ACTIVE	P	D219-00-1/081/WAL-001	Wall: Internal - 1 - Lobby - Station Building - Osterley Stn		Asbestos	Surveyed – Not Detected				Supalux panel					
25101	ACTIVE	P	D219-00-1/081/WAL-002	Wall: Internal - 2 - Lobby - Station Building - Osterley Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding					
5288	ACTIVE	P	D219-00-1/426	Toilet: Male - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25103	ACTIVE	P	D219-00-1/426/FLR-01	Floor - 1 - Toilet - Station Building - Osterley Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
5289	ACTIVE	P	D219-00-1/427	Toilet: Female - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5290	ACTIVE	P	D219-00-1/446	Bicycle Shed - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5291	ACTIVE	P	D219-00-1/451	Tenancy - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5292	ACTIVE	P	D219-00-1/452	Tenancy - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D219-00 - Station Building - Osterley Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25104	ACTIVE	P	D219-00-1/452	Tenancy - Station Building - Osterley Stn	Void	Asbestos	No Access: Presumed				(Not on Maximo) Tenancy - above plastic ceiling					
5293	ACTIVE	P	D219-00-1/453	Tenancy - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25105	ACTIVE	P	D219-00-1/453	Tenancy - Station Building - Osterley Stn	Void	Asbestos	No Access: Presumed				(Not on Maximo) Wall 4 - Plasterboard					
5294	ACTIVE	P	D219-00-1/576	Stairs: Linear - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25577	ACTIVE	P	D219-00-1/576/CLG-01	Ceiling: Suspended - 1 - Linear Stairs - Station Building - Osterley Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
25106	ACTIVE	P	D219-00-1/576/CLG-01	Ceiling: Suspended - 1 - Linear Stairs - Station Building - Osterley Stn	Void	Asbestos	No Access: Presumed				Concrete above false ceiling				Yes	
5295	ACTIVE	P	D219-00-1/601	Stairs: Linear - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5296	ACTIVE	P	D219-00-1/602	Stairs: Linear - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5297	ACTIVE	P	D219-00-1/603	Stairs: Linear - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25107	ACTIVE	P	D219-00-1/636	Overbridge - Station Building - Osterley Stn	Lead/Leading	Lead Paint/Lead	Removed				Gates - Cream gloss - 5m². Thickness : 0.45mm Analysis : 2.4%					
5298	ACTIVE	P	D219-00-1/661	Switch Room - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Surveyed – Asbestos Known									
25108	ACTIVE	P	D219-00-1/661/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Osterley Stn	Void	Asbestos	No Access: Presumed				Above Chipboard ceiling				Yes	
25578	ACTIVE	P	D219-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Osterley Stn	Other Electrical Boxes	Asbestos	Surveyed – Not Detected				Wall 1 - 1 x Transformer Box		1		N	N
42068	ACTIVE	P	D219-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Osterley Stn	Rope Gaskets	Asbestos	Sampled – Not Detected				Wall 2 - Rope Gaskets to the lids of the Switch Boxes - NADIS		4		N	N
25109	ACTIVE	P	D219-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Osterley Stn	Isolator Switches	Asbestos	Known				Wall 2 - 4 x 60amp Switch Boxes - Flash Guards within		4		N	N
5299	ACTIVE	P	D219-00-2/081	Lobby - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D219-00 - Station Building - Osterley Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5300	ACTIVE	P	D219-00-2/236	Passage - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5301	ACTIVE	P	D219-00-2/237	Passage - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25111	ACTIVE	P	D219-00-2/237/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Osterley Stn	Void	Asbestos	Surveyed – Not Detected				Supalux tiles, Air con, plastic cables, concrete above false ceiling fire break above false ceiling				Yes	
25110	ACTIVE	P	D219-00-2/237/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Osterley Stn		Asbestos	Surveyed – Not Detected				Supalux Boxing					
5302	ACTIVE	P	D219-00-2/261	Platform 1 - Westbound Local - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25112	ACTIVE	P	D219-00-2/261	Platform 1 - Westbound Local - Station Building - Osterley Stn		Asbestos	Sampled – Not Detected				Bitumen ducts along platform 1					
25113	ACTIVE	P	D219-00-2/261	Platform 1 - Westbound Local - Station Building - Osterley Stn	Void	Asbestos	No Access: Presumed				Beneath inspection cover					
5303	ACTIVE	P	D219-00-2/262	Platform 2 - Eastbound Local - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25114	ACTIVE	P	D219-00-2/262	Platform 2 - Eastbound Local - Station Building - Osterley Stn		Asbestos	Sampled – Not Detected				Bitumen Ducts					
45216	ACTIVE	P	D219-00-2/262	Platform 2 - Eastbound Local - Station Building - Osterley Stn	Westing house Boxes	Asbestos	Presumed				Materials within small Westinghouse Box to Wall 2/406 by Cable Run				N	N
25579	ACTIVE	P	D219-00-2/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Osterley Stn	Void	Asbestos	No Access: Presumed				Beneath inspection covers					Yes
25115	ACTIVE	P	D219-00-2/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Osterley Stn	Other Boarding	Asbestos	Presumed				0.1m² Boarding on floor (debris) West End		1			
5304	ACTIVE	P	D219-00-2/281	Station Supervisor Office - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25116	ACTIVE	P	D219-00-2/281/CLG-01	Ceiling: Solid - 1 - Station Supervisor Office - Station Building - Osterley Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Fibreboard					
25117	ACTIVE	P	D219-00-2/281/CLG-01	Ceiling: Solid - 1 - Station Supervisor Office - Station Building - Osterley Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
5305	ACTIVE	P	D219-00-2/331	Mess Room - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25195	ACTIVE	P	D219-00-2/331	Mess Room - Station Building - Osterley Stn	Bitumen	Asbestos	Surveyed – Not Detected				0.06m² Acoustic panel under sink		1			



Hazardous Material Asset Register - Summary



D219-00 - Station Building - Osterley Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25194	ACTIVE	P	D219-00-2/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Osterley Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Supalux boarding, ducting & conduits above false ceiling				Yes	
25193	ACTIVE	P	D219-00-2/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Osterley Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
25192	ACTIVE	P	D219-00-2/331/WAL-001	Wall: Internal - 1 - Mess Room - Station Building - Osterley Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LTB heater - foam insulation		1			
5306	ACTIVE	P	D219-00-2/406	Store - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25196	ACTIVE	P	D219-00-2/406/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Osterley Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Fibreboard					
25197	ACTIVE	P	D219-00-2/406/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Osterley Stn	Void	Asbestos	Surveyed – Not Detected				Wood, concrete above false ceiling				Yes	
5307	ACTIVE	P	D219-00-2/407	CER - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25198	ACTIVE	P	D219-00-2/407/WAL-002	Wall: Internal - 2 - CER - Station Building - Osterley Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - foam panels		1			
5308	ACTIVE	P	D219-00-2/411	Passage - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5309	ACTIVE	P	D219-00-2/416	Toilet: Unisex - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25199	ACTIVE	P	D219-00-2/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Osterley Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles & Boxing					
25200	ACTIVE	P	D219-00-2/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Osterley Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
5310	ACTIVE	P	D219-00-2/436	Waiting Room - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25201	ACTIVE	P	D219-00-2/447/FLR-01	Floor - 1 - Bicycle Shed - Station Building - Osterley Stn	Void	Asbestos	Surveyed – Not Detected				Throughout bike shed as per Report R747951					Yes
5311	ACTIVE	P	D219-00-2/451	Store - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46725	ACTIVE	P	D219-00-2/451/WAL-002	Wall: Internal - 2 - Store - Station Building - Osterley Stn	Cable Ducts: Bitumen	Asbestos	Known				Cable Ducts to Wall 2 behind metal boxing		6	R707651		
5312	ACTIVE	P	D219-00-2/452	Tenancy - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D219-00 - Station Building - Osterley Stn																
Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5313	ACTIVE	P	D219-00-2/661	Switch Room - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Surveyed – Asbestos Known									
24682	ACTIVE	P	D219-00-2/661	Switch Room - Station Building - Osterley Stn	Cable Duct: Other	Asbestos	Known				Cable sleeves x 2 filled in - chrysotile		2			
24325	ACTIVE	P	D219-00-2/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Osterley Stn	Other Electrical Boxes	Asbestos	Surveyed – Not Detected				2 x Transformer Boxes - non ACM - as reported by 4-RAIL		2		N	N
42070	ACTIVE	P	D219-00-2/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Osterley Stn	Other Electrical Boxes	Asbestos	Sampled – Not Detected				1 x Red Spot Distribution Box - NAD Gasket to Lid - NADIS		1		N	N
25202	ACTIVE	P	D219-00-2/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Osterley Stn	Isolator Switches	Asbestos	Strongly Presumed				Flash Guards with 4 x Switch boxes - 3 x 60amp 1 x 100amp. Gaskets to lids - NADIS		4		N	N
5314	ACTIVE	P	D219-00-2/662	Switch Room - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Surveyed – Asbestos Known									
42069	ACTIVE	P	D219-00-2/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Osterley Stn	Isolator Switches	Asbestos	Surveyed – Not Detected				Nylon Flash Guards within Switch boxes - 2 x 100amp (LHS), 1 x 60amp (RHS) - low level - wall 2 Gaskets to lid (high level to CFS) NADIS		3		N	N
25205	ACTIVE	P	D219-00-2/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Osterley Stn	Isolator Switches	Asbestos	Known				Flash Guards with 3 x 60amp Switch Boxes (high level)		3		N	N
25203	ACTIVE	P	D219-00-2/662/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Osterley Stn	Other Electrical Boxes	Asbestos	Surveyed – Not Detected				3 x Transformers - no ACM's present		3		N	N
25204	ACTIVE	P	D219-00-2/662/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Osterley Stn	Isolator Switches	Asbestos	Surveyed – Not Detected				1 x 30amp Switch box - Nylon Flashguard within - NAD Gasket to Lid - sampled - no asbestos detected		1		N	N
5315	ACTIVE	P	D219-00-2/746	SCR - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5316	ACTIVE	P	D219-00-2/761	Equipment Room - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25586	ACTIVE	P	D219-00-2/761/CLG-01	Ceiling: Solid - 1 - Equipment Room - Station Building - Osterley Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
25206	ACTIVE	P	D219-00-2/761/CLG-01	Ceiling: Solid - 1 - Equipment Room - Station Building - Osterley Stn	Void	Asbestos	No Access: Presumed				Above plasterboard				Yes	
5317	ACTIVE	P	D219-00-2/771	Pump Room - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25207	ACTIVE	P	D219-00-2/771/FLR-01	Floor - 1 - Pump Room - Station Building - Osterley Stn		Asbestos	Surveyed – Not Detected				Suplalux boarding					



Hazardous Material Asset Register - Summary



D219-00 - Station Building - Osterley Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25208	ACTIVE	P	D219-00-2/771/FLR-01	Floor - 1 - Pump Room - Station Building - Osterley Stn	Void	Asbestos	No Access: Presumed				Beneath hatch on floor					Yes
5318	ACTIVE	P	D219-00-2/776	Plant Room - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5319	ACTIVE	P	D219-00-2/801	Store - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25587	ACTIVE	P	D219-00-2/801/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Osterley Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, metal ducting & conduits, supalux debris above false ceiling				Yes	
25209	ACTIVE	P	D219-00-2/801/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Osterley Stn		Asbestos	Surveyed – Not Detected				Suplalux Tiles					
5320	ACTIVE	P	D219-00-2/901	CER - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5321	ACTIVE	P	D219-00-2/951	Disused Room - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5322	ACTIVE	P	D219-00-2/952	Switch Room - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5323	ACTIVE	P	D219-00-2/953	Disused Room - Station Building - Osterley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

D223-00 - Station Building - Hounslow East Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5325	ACTIVE	P	D223-00-1/002	Booking Hall - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5326	ACTIVE	P	D223-00-1/012	Ticket Office - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5327	ACTIVE	P	D223-00-1/022	POM - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5328	ACTIVE	P	D223-00-1/037	Toilet: Unisex - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5329	ACTIVE	P	D223-00-1/071	Circulation Area - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D223-00 - Station Building - Hounslow East Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5330	ACTIVE	p	D223-00-1/083	Lobby - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5331	ACTIVE	p	D223-00-1/084	Lobby - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5332	ACTIVE	p	D223-00-1/131	LMR - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5333	ACTIVE	p	D223-00-1/132	LMR - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5334	ACTIVE	p	D223-00-1/201	Passage - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5335	ACTIVE	p	D223-00-1/236	Passage - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5336	ACTIVE	p	D223-00-1/281	Station Supervisor Office - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5337	ACTIVE	p	D223-00-1/311	Office - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5338	ACTIVE	p	D223-00-1/331	Mess Room - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5339	ACTIVE	p	D223-00-1/402	Bin Store - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5340	ACTIVE	p	D223-00-1/406	Store - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5341	ACTIVE	p	D223-00-1/416	Toilet: Unisex - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5342	ACTIVE	p	D223-00-1/428	Toilet: Unisex - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5343	ACTIVE	p	D223-00-1/451	ATM - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5344	ACTIVE	p	D223-00-1/661	Switch Cupboard - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D223-00 - Station Building - Hounslow East Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5345	ACTIVE	p	D223-00-1/731	CER - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5346	ACTIVE	p	D223-00-1/746	SCR - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5347	ACTIVE	p	D223-00-1/786	Service Area - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5348	ACTIVE	p	D223-00-1/901	Void - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5349	ACTIVE	p	D223-00-1/902	Service Area - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5350	ACTIVE	p	D223-00-1/903	Service Area - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5351	ACTIVE	p	D223-00-1/904	Service Area - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5352	ACTIVE	p	D223-00-1/905	Service Area - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5353	ACTIVE	p	D223-00-1/906	Service Area - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5354	ACTIVE	p	D223-00-A/236	Passage - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5355	ACTIVE	p	D223-00-A/261	Platform 1 - Westbound Local - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5356	ACTIVE	p	D223-00-A/262	Platform 2 - Eastbound Local - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5357	ACTIVE	p	D223-00-A/436	Waiting Room - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5358	ACTIVE	p	D223-00-A/437	Waiting Room - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5359	ACTIVE	p	D223-00-A/576	Stairs: Linear - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D223-00 - Station Building - Hounslow East Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5360	ACTIVE	p	D223-00-A/604	Stairs: Linear - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5361	ACTIVE	p	D223-00-A/605	Stairs: Linear - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5362	ACTIVE	p	D223-00-A/661	Switch Room - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5363	ACTIVE	p	D223-00-A/662	Switch Room - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5364	ACTIVE	p	D223-00-A/731	CER - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5365	ACTIVE	p	D223-00-A/776	Plant Room - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5366	ACTIVE	p	D223-00-A/777	Plant Room - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5367	ACTIVE	p	D223-00-A/786	UPS Room - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5368	ACTIVE	p	D223-00-B/576	Stairs: Linear - Station Building - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

D225-00 - Station Building - Hounslow Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5371	ACTIVE	p	D225-00-1/001	Booking Hall - Station Building - Hounslow Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25211	ACTIVE	p	D225-00-1/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Hounslow Central Stn	Void	Asbestos	No Access: Presumed				Above ceiling hatch				Yes	
25210	ACTIVE	p	D225-00-1/001/FLR-01	Floor - 1 - Booking Hall - Station Building - Hounslow Central Stn	Void	Asbestos	No Access: Presumed				Beneath floor hatch near 1/083					Yes
5372	ACTIVE	p	D225-00-1/011	Ticket Office - Station Building - Hounslow Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D225-00 - Station Building - Hounslow Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25213	ACTIVE	P	D225-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Hounslow Central Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
25214	ACTIVE	P	D225-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Hounslow Central Stn	Void	Asbestos	Surveyed – Not Detected				Wood ducting & conduits. Roof - Wooden base above false ceiling				Yes	
25212	ACTIVE	P	D225-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Hounslow Central Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
5373	ACTIVE	P	D225-00-1/021	POM - Station Building - Hounslow Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25216	ACTIVE	P	D225-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Hounslow Central Stn	Void	Asbestos	Surveyed – Not Detected				Wooden frame above false ceiling				Yes	
25215	ACTIVE	P	D225-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Hounslow Central Stn		Asbestos	Surveyed – Not Detected				Supalux					
25588	ACTIVE	P	D225-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Hounslow Central Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
5374	ACTIVE	P	D225-00-1/031	Mess Room - Station Building - Hounslow Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25295	ACTIVE	P	D225-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Hounslow Central Stn		Asbestos	Surveyed – Not Detected				Supalux panels					
25296	ACTIVE	P	D225-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Hounslow Central Stn	Void	Asbestos	No Access: Presumed				Plasterboard - no clear access above. All walls solid, metal ducting & conduits above false ceiling				Yes	
25217	ACTIVE	P	D225-00-1/031/FLR-01	Floor - 1 - Mess Room - Station Building - Hounslow Central Stn	Void	Asbestos	No Access: Presumed				Beneath floor hatch					Yes
25294	ACTIVE	P	D225-00-1/031/WAL-003	Wall: Internal - 3 - Mess Room - Station Building - Hounslow Central Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LUL heater - 2 x foam panels		2			
25297	ACTIVE	P	D225-00-1/031/WDW-01	Window - 1 - Mess Room - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Over bars, windows & frames - 5m² cream gloss. Thickness : 1.14mm Analysis : 11.0%				N	N
5375	ACTIVE	P	D225-00-1/036	Toilet: Unisex - Station Building - Hounslow Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24425	ACTIVE	P	D225-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Hounslow Central Stn	Void	Asbestos	Surveyed – Not Detected				Wood, fibreglass pipe lagging by wall 3, wooden panel above window by wall 2, metal pipe going through false ceiling wall 2 above false ceiling				Yes	



Hazardous Material Asset Register - Summary



D225-00 - Station Building - Hounslow Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25298	ACTIVE	P	D225-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Hounslow Central Stn		Asbestos	Surveyed – Not Detected				Supalux panels					
25299	ACTIVE	P	D225-00-1/036/WDW-01	Window - 1 - Toilet - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Over bars & window frame - 2m ² white gloss. Thickness : 0.63mm Analysis : 14.0%				N	N
5376	ACTIVE	P	D225-00-1/081	Lobby - Station Building - Hounslow Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25301	ACTIVE	P	D225-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Hounslow Central Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
25302	ACTIVE	P	D225-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Hounslow Central Stn	Void	Asbestos	Surveyed – Not Detected				Wood ducting & conduits above false ceiling				Yes	
25300	ACTIVE	P	D225-00-1/081/FLR-01	Floor - 1 - Lobby - Station Building - Hounslow Central Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
5377	ACTIVE	P	D225-00-1/082	Lobby - Station Building - Hounslow Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25303	ACTIVE	P	D225-00-1/082/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Hounslow Central Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
25304	ACTIVE	P	D225-00-1/082/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Hounslow Central Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard above supalux tiles				Yes	
5378	ACTIVE	P	D225-00-1/083	Lobby - Station Building - Hounslow Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25305	ACTIVE	P	D225-00-1/083/FLR-01	Floor - 1 - Lobby - Station Building - Hounslow Central Stn	Void	Asbestos	No Access: Presumed				Beneath 2 x floor hatch					Yes
5379	ACTIVE	P	D225-00-1/201	Passage - Station Building - Hounslow Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25306	ACTIVE	P	D225-00-1/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Hounslow Central Stn	Void	Asbestos	No Access: Presumed				Above metal hatch by A601				Yes	
25307	ACTIVE	P	D225-00-1/281	Office - Station Building - Hounslow Central Stn	Void	Asbestos	No Access: Presumed				(Not on Maximo) Office - Supalux ceiling - concrete, ducting & conduits above false ceiling				Yes	
25308	ACTIVE	P	D225-00-1/281	Office - Station Building - Hounslow Central Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				(Not on Maximo) Office - 2x foam panels within		2			
25309	ACTIVE	P	D225-00-1/281	Office - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				(Not on Maximo) Office - Windows - 2m ² White gloss. Thickness : 1.14mm Analysis : 11.0%					



Hazardous Material Asset Register - Summary



D225-00 - Station Building - Hounslow Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5380	ACTIVE	P	D225-00-1/406	Store - Station Building - Hounslow Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25310	ACTIVE	P	D225-00-1/406/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Hounslow Central Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
5381	ACTIVE	P	D225-00-1/411	Passage - Station Building - Hounslow Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25312	ACTIVE	P	D225-00-1/411/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Hounslow Central Stn	Void	Asbestos	No Access: Presumed				Above wood and metal frame				Yes	
24106	ACTIVE	P	D225-00-1/411/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Ceiling - 15m² white gloss. Thickness : 0.91mm Analysis : 5.0%				N	N
25311	ACTIVE	P	D225-00-1/411/FLR-01	Floor - 1 - Passage - Station Building - Hounslow Central Stn	Void	Asbestos	Surveyed – Not Detected				Drains beneath floor hatch					Yes
5382	ACTIVE	P	D225-00-1/426	Toilet: Male - Station Building - Hounslow Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25313	ACTIVE	P	D225-00-1/426/WDW-01	Window - 1 - Toilet - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Windows wall 3 - 1m² white gloss. Thickness : 0.63mm Analysis : 14.0%				N	N
5383	ACTIVE	P	D225-00-1/427	Toilet: Female - Station Building - Hounslow Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25315	ACTIVE	P	D225-00-1/427/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Hounslow Central Stn	Void	Asbestos	No Access: Presumed				Above 3x wood panel by skylight				Yes	
25314	ACTIVE	P	D225-00-1/427/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Hounslow Central Stn	Void	Asbestos	No Access: Presumed				Toilet Lobby - above plasterboard ceiling				Yes	
25316	ACTIVE	P	D225-00-1/427/WDW-01	Window - 1 - Toilet - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Windows wall 3 - 1m² white gloss. Thickness : 0.63mm Analysis : 14.0%				N	N
25317	ACTIVE	P	D225-00-1/427/WDW-02	Window - 2 - Toilet - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Windows wall 3 - 1m² white gloss. Thickness : 0.63mm Analysis : 14.0%					
5384	ACTIVE	P	D225-00-1/551	Yard - Station Building - Hounslow Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5385	ACTIVE	P	D225-00-1/552	Yard - Station Building - Hounslow Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24107	ACTIVE	P	D225-00-1/552	Yard - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Yard - Ladder & wood coiling - 3m² black gloss. Thickness : 0.25mm Analysis : 12.0%				N	N



Hazardous Material Asset Register - Summary



D225-00 - Station Building - Hounslow Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25318	ACTIVE	P	D225-00-1/552	Yard - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Yard - Drain pipe - 3m² black gloss. Thickness : 0.52mm Analysis : 15.0%				N	N
5386	ACTIVE	P	D225-00-1/661	Switch Room - Station Building - Hounslow Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25395	ACTIVE	P	D225-00-1/661/FLR-01	Floor - 1 - Switch Room - Station Building - Hounslow Central Stn	Vinyl tiles	Asbestos	Known				Switch Room 2nd Section - 3m² Grey vinyl floor tiles / 3m² Red vinyl floor tiles	6			N	N
25397	ACTIVE	P	D225-00-1/661/FLR-01	Floor - 1 - Switch Room - Station Building - Hounslow Central Stn	Cable Ducts: Bitumen	Asbestos	Strongly Presumed				Switch Room 2nd Section - Bitumen Duct Floor by wall 3		1		N	N
25396	ACTIVE	P	D225-00-1/661/FLR-01	Floor - 1 - Switch Room - Station Building - Hounslow Central Stn	Bitumen	Asbestos	Surveyed – Not Detected				Switch Room 2nd Section - Tile backing - Bitumen - non asbestos					
25399	ACTIVE	P	D225-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Hounslow Central Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Switch Room 2nd Section - Trunking Asbestos Components – Strongly Presumed within		1		N	N
25398	ACTIVE	P	D225-00-1/661/WAL-001 80868745	Wall: Internal - 1 - Switch Room - Station Building - Hounslow Central Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Switch Room 2nd Section - 6x Iron clad isolators - 4 x 60amp, 1 x blue 100amp,1x grey 60amp		6		N	N
25400	ACTIVE	P	D225-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Removed				All walls - Skirting boards on all walls - 4m² Black matt. Thickness : 0.65mm Analysis : 8.2%				N	N
25393	ACTIVE	P	D225-00-1/661/WAL-003 80868747	Wall: Internal - 3 - Switch Room - Station Building - Hounslow Central Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Switch Room 1st Section - 1x 30amp Iron clad isolators		1		N	N
25394	ACTIVE	P	D225-00-1/661/WAL-003 80868747	Wall: Internal - 3 - Switch Room - Station Building - Hounslow Central Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				Switch Room 1st Section - 4 x Transformer Boxes Asbestos Components – Strongly Presumed within		4		N	N
5387	ACTIVE	P	D225-00-1/731	CER - Station Building - Hounslow Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5388	ACTIVE	P	D225-00-1/746	SCR - Station Building - Hounslow Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25402	ACTIVE	P	D225-00-1/746/CLG-01	Ceiling: Solid - 1 - SCR - Station Building - Hounslow Central Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Hollow Plasterboard		1			
25401	ACTIVE	P	D225-00-1/746/CLG-01	Ceiling: Solid - 1 - SCR - Station Building - Hounslow Central Stn		Asbestos	Surveyed – Not Detected				Supalux panel wall 2					
25403	ACTIVE	P	D225-00-1/746/CLG-01	Ceiling: Solid - 1 - SCR - Station Building - Hounslow Central Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	



Hazardous Material Asset Register - Summary



D225-00 - Station Building - Hounslow Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5389	ACTIVE	p	D225-00-2/281	Station Supervisor Office - Station Building - Hounslow Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5390	ACTIVE	p	D225-00-A/261	Platform 1 - Westbound Local - Station Building - Hounslow Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25408	ACTIVE	p	D225-00-A/261	Platform 1 - Westbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Column - Lower Section of Canopy support - White gloss. Lead : 8.37% Note: Testing carried out of paintwork on these Columns in 2006 had a range of results. 13.9% 11.2% 9.5%, 8.2%. 26.1%, 7.7%, 3.4%, 30.3%. Possible change as a result of paint stripping works in 2006. Only one column in one location was sampled in 2023.				N	N
25409	ACTIVE	p	D225-00-A/261	Platform 1 - Westbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Platform 1&2 Steelwork by PA system, dark blue gloss paint. 1.44% R717001				N	N
25412	ACTIVE	p	D225-00-A/261	Platform 1 - Westbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Arch supports - Light blue gloss - Throughout high level. Lead 0.73% Note: Testing carried out of paintwork on these arch supports in 2006 had a range of results. 12.7% 11% 12.2%. Possible change because of paint stripping works in 2006. It is reasonable to assume that while result is less than 1%, some of the layers contain lead at a percentage higher than 1% and others do not contain lead at all. For this reason the paint coating(s) should be treated as a lead hazard.				N	N
25414	ACTIVE	p	D225-00-A/261	Platform 1 - Westbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Wood middle support - Light blue gloss throughout high level - Upper. Lead : 17.0%				N	N
25411	ACTIVE	p	D225-00-A/261	Platform 1 - Westbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Support - Dark blue gloss throughout high level (upper wooden). Lead : 8.4% Note: The dark blue paint was tested in 2023 in several locations and there has been a reduction in the lead content in these areas, which is likely from the paint stripping works in 2006.				N	N
25410	ACTIVE	p	D225-00-A/261	Platform 1 - Westbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Platform 1&2 Steelwork adjacent to CCTV cameras and PA speakers. Dark blue gloss paint. Lead : 1.01% (R717001)				N	N
25407	ACTIVE	p	D225-00-A/261	Platform 1 - Westbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				7x Canopy frame - 4m² white gloss. Thickness : 0.35mm Analysis : 2.6%				N	N



Hazardous Material Asset Register - Summary



D225-00 - Station Building - Hounslow Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
69863	ACTIVE	p	D225-00-A/261	Platform 1 - Westbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Platform 1&2 Top of stairs steelwork 2m away from CCTV, dark blue gloss paint 0.76% R717001. Note: The dark blue paint was tested in 2006 and had a result of 8.4%. Possible change because of paint stripping works in 2006. It is reasonable to assume that while result is less than 1%, some of the layers contain lead at a percentage higher than 1% and others do not contain lead at all. For this reason the paint coating(s) should be treated as a lead hazard.			R717001		
69861	ACTIVE	p	D225-00-A/261	Platform 1 - Westbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Platform 1&2 Steelwork 2m away from CCTV system, dark blue gloss paint 0.74% R717001 Note: The dark blue paint was tested in 2006 and had a result of 8.4%. Possible change because of paint stripping works in 2006. It is reasonable to assume that while result is less than 1%, some of the layers contain lead at a percentage higher than 1% and others do not contain lead at all. For this reason the paint coating(s) should be treated as a lead hazard.			R717001		
69859	ACTIVE	p	D225-00-A/261	Platform 1 - Westbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Platform 1&2 Steelwork by CCTV system, dark blue gloss paint 0.78% R717001 Note: The dark blue paint was tested in 2006 and had a result of 8.4%. Possible change because of paint stripping works in 2006. It is reasonable to assume that while result is less than 1%, some of the layers contain lead at a percentage higher than 1% and others do not contain lead at all. For this reason the paint coating(s) should be treated as a lead hazard.			R717001		
69857	ACTIVE	p	D225-00-A/261	Platform 1 - Westbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Platform 1&2 Steelwork by CCTV system, dark blue gloss paint, 0.84% R717001 Note: The dark blue paint was tested in 2006 and had a result of 8.4%. Possible change because of paint stripping works in 2006. It is reasonable to assume that while result is less than 1%, some of the layers contain lead at a percentage higher than 1% and others do not contain lead at all. For this reason the paint coating(s) should be treated as a lead hazard.			R717001		
69850	ACTIVE	p	D225-00-A/261	Platform 1 - Westbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Platform 1&2 Steelwork next to CCTV, dark blue gloss paint. 2.30% R717001			R717001		



Hazardous Material Asset Register - Summary



D225-00 - Station Building - Hounslow Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25413	ACTIVE	p	D225-00-A/261	Platform 1 - Westbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Platform 1 &2 Steelwork by CCTV system. Light blue gloss paint. 4.25% R717001				N	N
69855	ACTIVE	p	D225-00-A/261	Platform 1 - Westbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Platform 1&2, steelwork by CCTV system, dark blue gloss paint 0.57% R717001. Note: The dark blue paint was tested in 2006 and had a result of 8.4%. Possible change because of paint stripping works in 2006. It is reasonable to assume that while result is less than 1%, some of the layers contain lead at a percentage higher than 1% and others do not contain lead at all. For this reason the paint coating(s) should be treated as a lead hazard.			R717001		
69852	ACTIVE	p	D225-00-A/261	Platform 1 - Westbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Platform 1&2 by steelwork next to CCTV, dark blue gloss paint 4.57% R717001			R717001		
24114	ACTIVE	p	D225-00-A/261	Platform 1 - Westbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Wood supports- light blue gloss throughout high level central areas - Upper. Lead : 26.4%				N	N
24113	ACTIVE	p	D225-00-A/261	Platform 1 - Westbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Fascia Panels - East end of platform - White gloss. Lead : 11.2%.				N	N
25406	ACTIVE	p	D225-00-A/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Hounslow Central Stn	Cellactite Sheeting	Asbestos	Known				Corrugated roof strips					
25405	ACTIVE	p	D225-00-A/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Hounslow Central Stn	Glazing Rope	Asbestos	Known				Metal glazing bars to skylight					
45185	INACTIVE	p	D225-00-A/261/CPY-02	Canopy: Platform - 1 - Platform 1 - Westbound Local - Station Building - Hounslow Central Stn	Glazing Rope	Lead Paint/Lead	Known				Rope Seal to platform canopy				N	N
25404	ACTIVE	p	D225-00-A/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Hounslow Central Stn	Void	Asbestos	Surveyed – Not Detected				Beneath 7 x floor hatches non asbestos as per report R745551					Yes
5391	ACTIVE	p	D225-00-A/262	Platform 2 - Eastbound Local - Station Building - Hounslow Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46498	ACTIVE	p	D225-00-A/262	Platform 2 - Eastbound Local - Station Building - Hounslow Central Stn		Asbestos	Sampled – Not Detected				Auto Kiosk - on island platform between A/261 & A/262 and adjacent to A/661;					
25498	ACTIVE	p	D225-00-A/262	Platform 2 - Eastbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Wood supports- light blue gloss throughout high level central areas - Upper. Lead : 26.4%				N	N
25499	ACTIVE	p	D225-00-A/262	Platform 2 - Eastbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Wood middle support - Light blue gloss throughout high level - Upper. Lead : 17.0%				N	N



Hazardous Material Asset Register - Summary



D225-00 - Station Building - Hounslow Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25492	ACTIVE	p	D225-00-A/262	Platform 2 - Eastbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Fascia Panels - East end of platform - White gloss. Lead : 11.2%.				N	N
25491	ACTIVE	p	D225-00-A/262	Platform 2 - Eastbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Column - Lower Section of Canopy support - White gloss. Lead : 8.37% Note: Testing carried out of paintwork on these Columns in 2006 had a range of results. 13.9% 11.2% 9.5%, 8.2%. 26.1%, 7.7%, 3.4%, 30.3%. Possible change as a result of paint stripping works in 2006. Only one column in one location was sampled in 2023.				N	N
69854	ACTIVE	p	D225-00-A/262	Platform 2 - Eastbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Platform 1&2 by steelwork next to CCTV, dark blue gloss paint 4.57% R717001			R717001		
69858	ACTIVE	p	D225-00-A/262	Platform 2 - Eastbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Platform 1&2 Steelwork by CCTV system, dark blue gloss paint, 0.84% R717001 Note: The dark blue paint was tested in 2006 and had a result of 8.4%. Possible change because of paint stripping works in 2006. It is reasonable to assume that while result is less than 1%, some of the layers contain lead at a percentage higher than 1% and others do not contain lead at all. For this reason the paint coating(s) should be treated as a lead hazard.			R717001		
69864	ACTIVE	p	D225-00-A/262	Platform 2 - Eastbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Platform 1&2 Top of stairs steelwork 2m away from CCTV, dark blue gloss paint 0.76% R717001. Note: The dark blue paint was tested in 2006 and had a result of 8.4%. Possible change because of paint stripping works in 2006. It is reasonable to assume that while result is less than 1%, some of the layers contain lead at a percentage higher than 1% and others do not contain lead at all. For this reason the paint coating(s) should be treated as a lead hazard.			R717001		
69851	ACTIVE	p	D225-00-A/262	Platform 2 - Eastbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Platform 1&2 Steelwork next to CCTV, dark blue gloss paint. 2.30% R717001			R717001		



Hazardous Material Asset Register - Summary



D225-00 - Station Building - Hounslow Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
69856	ACTIVE	p	D225-00-A/262	Platform 2 - Eastbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Platform 1&2, steelwork by CCTV system, dark blue gloss paint 0.57% R717001. Note: The dark blue paint was tested in 2006 and had a result of 8.4%.Possible change because of paint stripping works in 2006. It is reasonable to assume that while result is less than 1%, some of the layers contain lead at a percentage higher than 1% and others do not contain lead at all. For this reason the paint coating(s) should be treated as a lead hazard.			R717001		
69860	ACTIVE	p	D225-00-A/262	Platform 2 - Eastbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Platform 1&2 Steelwork by CCTV system, dark blue gloss paint 0.78% R717001 Note: The dark blue paint was tested in 2006 and had a result of 8.4%. Possible change because of paint stripping works in 2006. It is reasonable to assume that while result is less than 1%, some of the layers contain lead at a percentage higher than 1% and others do not contain lead at all. For this reason the paint coating(s) should be treated as a lead hazard.			R717001		
25495	ACTIVE	p	D225-00-A/262	Platform 2 - Eastbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Support - Dark blue gloss throughout high level (upper wooden). Lead : 8.4% Note: The dark blue paint was tested in 2023 in several locations and there has been a reduction in the lead content in these areas, which is likely from the paint stripping works in 2006.				N	N
25493	ACTIVE	p	D225-00-A/262	Platform 2 - Eastbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Platform 1&2 Steelwork by PA system, dark blue gloss paint. 1.44% R717001				N	N
25417	ACTIVE	p	D225-00-A/262	Platform 2 - Eastbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				7x Canopy frame - 4m² white gloss. Thickness : 0.35mm Analysis : 2.6%.				N	N
25497	ACTIVE	p	D225-00-A/262	Platform 2 - Eastbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Platform 1 &2 Steelwork by CCTV system. Light blue gloss paint. 4.25% R717001				N	N



Hazardous Material Asset Register - Summary



D225-00 - Station Building - Hounslow Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25496	ACTIVE	P	D225-00-A/262	Platform 2 - Eastbound Local - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Arch supports - Light blue gloss - Throughout high level. Lead 0.73% Note: Testing carried out of paintwork on these arch supports in 2006 had a range of results. 12.7% 11% 12.2%. Possible change because of paint stripping works in 2006. It is reasonable to assume that while result is less than 1%, some of the layers contain lead at a percentage higher than 1% and others do not contain lead at all. For this reason the paint coating(s) should be treated as a lead hazard.				N	N
24409	ACTIVE	P	D225-00-A/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - Hounslow Central Stn	Glazing Rope	Asbestos	Known				Metal glazing bars to skylight					
25416	ACTIVE	P	D225-00-A/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - Hounslow Central Stn	Void	Asbestos	No Access: Presumed				Above wooden slats				Yes	
24115	ACTIVE	P	D225-00-A/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - Hounslow Central Stn	Cellactite Sheeting	Asbestos	Known				Corrugated roof strips					
45186	INACTIVE	P	D225-00-A/262/CPY-02	Canopy: Platform - 1 - Platform 2 - Eastbound Local - Station Building - Hounslow Central Stn	Glazing Rope	Asbestos	Presumed				Rope Seal to platform canopy				N	N
25415	ACTIVE	P	D225-00-A/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Hounslow Central Stn	Void	Asbestos	Surveyed – Not Detected				Beneath 7 x floor hatches non asbestos as per report R745551					Yes
5392	ACTIVE	P	D225-00-A/601	Stairs: Linear - Station Building - Hounslow Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25500	ACTIVE	P	D225-00-A/601	Stairs: Linear - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Top pillar & surround - 4m² white gloss. Analysis : 2.6%				N	N
24411	ACTIVE	P	D225-00-A/601	Stairs: Linear - Station Building - Hounslow Central Stn	Lead/Leading	Lead Paint/Lead	Known				Outside entrance - On three drain pipes & window & inner side of station signal 8m² white gloss. Thickness : 0.09mm Analysis : 3.3%				N	N
5393	ACTIVE	P	D225-00-A/661	Switch Room - Station Building - Hounslow Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25502	ACTIVE	P	D225-00-A/661/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Hounslow Central Stn		Asbestos	Surveyed – Not Detected				Supalux					
25503	ACTIVE	P	D225-00-A/661/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Hounslow Central Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
25505	ACTIVE	P	D225-00-A/661/FLR-01	Floor - 1 - Switch Room - Station Building - Hounslow Central Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box by Wall 1 Asbestos Components – Strongly Presumed within		1		N	N



Hazardous Material Asset Register - Summary



D225-00 - Station Building - Hounslow Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25506	ACTIVE	P	D225-00-A/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Hounslow Central Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 60amp Iron clad isolator No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score material within.		1		N	N
25504	ACTIVE	P	D225-00-A/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Hounslow Central Stn	Other Boarding	Asbestos	Presumed				1 x paxoline board		1		N	N
25501	ACTIVE	P	D225-00-A/661/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Hounslow Central Stn		Asbestos	Surveyed – Not Detected				Supalux panel boxing above door					
5394	ACTIVE	P	D225-00-A/662	Tunnel Telephone Room - Station Building - Hounslow Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

D227-00 - Station Building - Hounslow West Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5398	ACTIVE	P	D227-00-1/001	Booking Hall - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25507	ACTIVE	P	D227-00-1/001	Booking Hall - Station Building - Hounslow West Stn	Cable Ducts: Bitumen	Asbestos	Presumed				3x Bitumus Ducts - Chrysotile - (cable passes through service duct in existing ducts) No access into floor pit as manhole keys required.		3			
5399	ACTIVE	P	D227-00-1/011	Ticket Office - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25511	ACTIVE	P	D227-00-1/011	Ticket Office - Station Building - Hounslow West Stn		Asbestos	Surveyed – Not Detected				Roof - Supalux Board					
25510	ACTIVE	P	D227-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Hounslow West Stn	Void	Asbestos	Surveyed – Not Detected				Supalux above false ceiling				Yes	
25509	ACTIVE	P	D227-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Hounslow West Stn		Asbestos	Surveyed – Not Detected				Supalux					
24120	ACTIVE	P	D227-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Hounslow West Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles				Yes	
25508	ACTIVE	P	D227-00-1/011/WAL-002	Wall: Internal - 2 - Ticket Office - Station Building - Hounslow West Stn		Asbestos	Surveyed – Not Detected				Supalux boxing walls 2 & 3					
5400	ACTIVE	P	D227-00-1/021	POM - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D227-00 - Station Building - Hounslow West Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25512	ACTIVE	P	D227-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				Beneath Computer tiles					
5401	ACTIVE	P	D227-00-1/031	Mess Room - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24121	ACTIVE	P	D227-00-1/031/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				Above false ceiling					
25514	ACTIVE	P	D227-00-1/031/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Hounslow West Stn		Asbestos	Surveyed – Not Detected				Supalux boxing between walls 2 & 4					
25513	ACTIVE	P	D227-00-1/031/WAL-003	Wall: Internal - 3 - Mess Room - Station Building - Hounslow West Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater		1			
25515	ACTIVE	P	D227-00-1/031/WDW-01	Window - 1 - Mess Room - Station Building - Hounslow West Stn	Lead/Leading	Lead Paint/Lead	Known				Metal window - 2m² White gloss. Thickness : 0.50mm Analysis : 13.0%					
5402	ACTIVE	P	D227-00-1/036	Lobby - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5403	ACTIVE	P	D227-00-1/037	Toilet: Unisex - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5404	ACTIVE	P	D227-00-1/201	Passage - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5405	ACTIVE	P	D227-00-1/202	Passage - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25594	ACTIVE	P	D227-00-1/202	Passage - Station Building - Hounslow West Stn	Cable Duct: Other	Asbestos	Known				Garden Area - Cable duct (22m visible), 12 Ducts on left of beam & 10 ducts on right of beam - far left, underneath walk way - Not readily accessible. Sampled in 4 Rail Report R100626		22			
25516	ACTIVE	P	D227-00-1/202/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Hounslow West Stn	Void	Asbestos	Surveyed – Not Detected				Aluminium ceiling, metal slats plastic cable brick CMS, wood, conduits above false ceiling				Yes	
25517	ACTIVE	P	D227-00-1/202/CLG-02	Ceiling: Suspended - 2 - Passage - Station Building - Hounslow West Stn	Void	Asbestos	Surveyed – Not Detected				Aluminium ceiling, metal slats plastic cable brick CMS, wood, conduits above false ceiling				Yes	
25593	ACTIVE	P	D227-00-1/202/WDW-01	Window - 1 - Passage - Station Building - Hounslow West Stn	Lead/Leading	Lead Paint/Lead	Known				Window frame - 6m² - White gloss. Thickness : 0.50mm Analysis : 13.0%					
5406	ACTIVE	P	D227-00-1/236	Lobby - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D227-00 - Station Building - Hounslow West Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5407	ACTIVE	P	D227-00-1/237	Lobby - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25597	ACTIVE	P	D227-00-1/237/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				No access above false ceiling. Double strip light attached to ceiling, not safe to dismantle or drill into for endoscopic inspection internally					
25596	ACTIVE	P	D227-00-1/237/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Hounslow West Stn		Asbestos	Surveyed – Not Detected				2 x Supalux panels by wall 5					
25595	ACTIVE	P	D227-00-1/237/FLR-01	Floor - 1 - Lobby - Station Building - Hounslow West Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
5408	ACTIVE	P	D227-00-1/238	Lobby - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25598	ACTIVE	P	D227-00-1/238/CLG-01 80868011	Ceiling: Suspended - 1 - Lobby - Station Building - Hounslow West Stn Ceiling: Suspended	Glazing Rope	Asbestos	Strongly Presumed				Glass canopy, rope seal under metal glazing bars - Throughout ceiling void					
5409	ACTIVE	P	D227-00-1/301	Station Supervisor Office - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25599	ACTIVE	P	D227-00-1/301	Station Supervisor Office - Station Building - Hounslow West Stn	LUL Heaters	Asbestos	Sampled – Not Detected				Back board to LTB heater 24"x36" opposite entrance door		1			
25602	ACTIVE	P	D227-00-1/301	Station Supervisor Office - Station Building - Hounslow West Stn	Other Boarding	Asbestos	Sampled – Not Detected				4m² Boarding to wall ticket area					
25601	ACTIVE	P	D227-00-1/301/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				Above false ceiling					
25600	ACTIVE	P	D227-00-1/301/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Hounslow West Stn		Asbestos	Surveyed – Not Detected				Supalux					
25603	ACTIVE	P	D227-00-1/301/WDW-01	Window - 1 - Station Supervisor Office - Station Building - Hounslow West Stn	Lead/Leading	Lead Paint/Lead	Known				Metal window - 2m² White gloss. Thickness : 0.50mm Analysis : 13.0%					
5410	ACTIVE	P	D227-00-1/311	Office - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25605	ACTIVE	P	D227-00-1/311/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Hounslow West Stn	Void	Asbestos	Surveyed – Not Detected				Supalux boarding debris - solid walls & ceiling, plastic cables - above solid ceiling				Yes	
25604	ACTIVE	P	D227-00-1/311/WAL-002	Wall: Internal - 2 - Office - Station Building - Hounslow West Stn	LUL Heaters	Asbestos	Sampled – Not Detected				LTB heater - 2x foam panels		2			



Hazardous Material Asset Register - Summary



D227-00 - Station Building - Hounslow West Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5411	ACTIVE	P	D227-00-1/416	Toilet: Unisex - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25606	ACTIVE	P	D227-00-1/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Hounslow West Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
25607	ACTIVE	P	D227-00-1/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Hounslow West Stn	Void	Asbestos	Surveyed – Not Detected				Concrete by wall 2, 2x supalux panels, metal - above false ceiling				Yes	
24427	ACTIVE	P	D227-00-1/416/WAL-003	Wall: Internal - 3 - Toilet - Station Building - Hounslow West Stn	LUL Heaters	Asbestos	Surveyed – Not Detected									
5412	ACTIVE	P	D227-00-1/451	Tenancy - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5413	ACTIVE	P	D227-00-1/452	Tenancy - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24209	ACTIVE	P	D227-00-1/452/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				Above wooden ceiling					
25608	ACTIVE	P	D227-00-1/452/FLR-01	Floor - 1 - Tenancy - Station Building - Hounslow West Stn	Void	Asbestos	Surveyed – Not Detected				Wood beneath Lino and ceramic tiles beneath wood					Yes
5414	ACTIVE	P	D227-00-1/453	Tenancy - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24134	ACTIVE	P	D227-00-1/453	Tenancy - Station Building - Hounslow West Stn	Cement Cowlings/Flues	Asbestos	No Access: Presumed				Ground behind 1/453 - 0.4m² Flue pipe - amosite & chrysotile No access 2024 re-inspection as no keys with Station supervisor as tenancy		1			
24129	ACTIVE	P	D227-00-1/453	Tenancy - Station Building - Hounslow West Stn	Lead/Leading	Lead Paint/Lead	Known				Kitchen - Metal window - 2m² White gloss. Thickness : 0.50mm Analysis : 13.0%					
24135	ACTIVE	P	D227-00-1/453	Tenancy - Station Building - Hounslow West Stn	Lead/Leading	Lead Paint/Lead	Known				Ground behind 1/453 - On windows x6 - 5m² - white gloss. Thickness : 0.50mm Analysis : 13.0%					
24132	ACTIVE	P	D227-00-1/453	Tenancy - Station Building - Hounslow West Stn	Lead/Leading	Lead Paint/Lead	Known				Gents Toilet - Metal window - 1m² White gloss. Thickness : 0.50mm Analysis : 13.0%					
24128	ACTIVE	P	D227-00-1/453	Tenancy - Station Building - Hounslow West Stn	Lead/Leading	Lead Paint/Lead	Known				Ladies Toilet - Metal window - 1m² White gloss. Thickness : 0.50mm Analysis : 13.0%					
24210	ACTIVE	P	D227-00-1/453/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				Left room of Tenancy - above false ceiling					
25610	ACTIVE	P	D227-00-1/453/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				Above false ceiling					



Hazardous Material Asset Register - Summary



D227-00 - Station Building - Hounslow West Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25612	ACTIVE	P	D227-00-1/453/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Hounslow West Stn		Asbestos	Surveyed – Not Detected				Left room of Tenancy - Supalux tiles					
24130	ACTIVE	P	D227-00-1/453/CLG-01 80868075	Ceiling: Suspended - 1 - Tenancy - Station Building - Hounslow West Stn Ceiling: Suspended	Cement Cowlings/Flues	Asbestos	No Access: Presumed				Store - 0.08m² Cement flue No access 2024 re-inspection as no keys with Station supervisor as tenancy		1			
25609	ACTIVE	P	D227-00-1/453/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Hounslow West Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
25617	ACTIVE	P	D227-00-1/453/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				Back office - above false ceiling					
24211	ACTIVE	P	D227-00-1/453/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Hounslow West Stn		Asbestos	Surveyed – Not Detected				Back office - Supalux					
25613	ACTIVE	P	D227-00-1/453/FLR-01	Floor - 1 - Tenancy - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				Back office - beneath carpet					
25611	ACTIVE	P	D227-00-1/453/FLR-01	Floor - 1 - Tenancy - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				Left room of Tenancy - beneath carpet					
24126	ACTIVE	P	D227-00-1/453/FLR-01	Floor - 1 - Tenancy - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				Lobby - beneath Lino floor					
24131	ACTIVE	P	D227-00-1/453/FLR-01	Floor - 1 - Tenancy - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				Lobby Gents - beneath Lino					
25614	ACTIVE	P	D227-00-1/453/WAL-002	Wall: Internal - 2 - Tenancy - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				Back office - behind Plasterboard partition					
24133	ACTIVE	P	D227-00-1/453/WAL-002 80868084	Wall: Internal - 2 - Tenancy - Station Building - Hounslow West Stn Wall: Internal	Isolator Switches	Asbestos	No Access: Presumed				Room by entrance - Fuse Switch - wall 2 No access 2024 re-inspection as no keys with Station supervisor as tenancy		1			
25615	ACTIVE	P	D227-00-1/453/WAL-003 80868085	Wall: Internal - 3 - Tenancy - Station Building - Hounslow West Stn Wall: Internal	Void	Asbestos	No Access: Presumed				Back office - behind Plasterboard partition No access 2024 re-inspection as no keys with Station supervisor as tenancy					
25616	ACTIVE	P	D227-00-1/453/WAL-004 80868086	Wall: Internal - 4 - Tenancy - Station Building - Hounslow West Stn Wall: Internal	Void	Asbestos	No Access: Presumed				Back office - behind Plasterboard partition No access 2024 re-inspection as no keys with Station supervisor as tenancy					
24127	ACTIVE	P	D227-00-1/453/WDW-01	Window - 1 - Tenancy - Station Building - Hounslow West Stn	Lead/Leading	Lead Paint/Lead	Known				Lobby - Metal window - 2m² White gloss. Thickness : 0.50mm Analysis : 13.0%					
5415	ACTIVE	P	D227-00-1/454	Tenancy - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D227-00 - Station Building - Hounslow West Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24144	ACTIVE	P	D227-00-1/454	Tenancy - Station Building - Hounslow West Stn	Cable Duct: Other	Asbestos	No Access: Presumed				Behind 1/454 - 2x Cable Sleeves - Amosite & Chrysotile) bottom of stairs in ground, left & right side of wall No access 2024 re-inspection as no keys with Station supervisor as tenancy		2			
24139	ACTIVE	P	D227-00-1/454/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Hounslow West Stn		Asbestos	Surveyed – Not Detected				Supalux					
24140	ACTIVE	P	D227-00-1/454/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				Above false ceiling					
24143	ACTIVE	P	D227-00-1/454/FLR-01	Floor - 1 - Tenancy - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				Kitchen - beneath Lino					
24136	ACTIVE	P	D227-00-1/454/WAL-001 80868096	Wall: Internal - 1 - Tenancy - Station Building - Hounslow West Stn Wall: Internal	Other Boarding	Asbestos	No Access: Presumed				Partition wall 1,2&3 No access 2024 re-inspection as no keys with Station supervisor as tenancy					
24137	ACTIVE	P	D227-00-1/454/WAL-002 80868107	Wall: Internal - 2 - Tenancy - Station Building - Hounslow West Stn Wall: Internal	Other Boarding	Asbestos	No Access: Presumed				Partition wall 1,2&3 No access 2024 re-inspection as no keys with Station supervisor as tenancy					
24138	ACTIVE	P	D227-00-1/454/WAL-003 80868108	Wall: Internal - 3 - Tenancy - Station Building - Hounslow West Stn Wall: Internal	Other Boarding	Asbestos	No Access: Presumed				Partition wall 1,2&3 No access 2024 re-inspection as no keys with Station supervisor as tenancy					
24141	ACTIVE	P	D227-00-1/454/WDW-01	Window - 1 - Tenancy - Station Building - Hounslow West Stn	Lead/Leading	Lead Paint/Lead	Known				Metal window - 5m² - White gloss. Thickness : 0.50mm Analysis : 13.0%					
24142	ACTIVE	P	D227-00-1/454/WDW-02	Window - 2 - Tenancy - Station Building - Hounslow West Stn	Lead/Leading	Lead Paint/Lead	Known				Metal window - 5m² - White gloss. Thickness : 0.50mm Analysis : 13.0%					
5416	ACTIVE	P	D227-00-1/601	Stairs: Linear - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25171	ACTIVE	P	D227-00-1/601/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Hounslow West Stn	Void	Asbestos	Surveyed – Not Detected				Aluminium ceiling, metal slats plastic cable brick CMS, wood, conduits above false ceiling				Yes	
24145	ACTIVE	P	D227-00-1/601/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Hounslow West Stn		Asbestos	Surveyed – Not Detected				Supalux					
5417	ACTIVE	P	D227-00-1/602	Stairs: Linear - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24147	ACTIVE	P	D227-00-1/602/CLG-01	Ceiling: Suspended - 1 - Linear Stairs - Station Building - Hounslow West Stn	Void	Asbestos	Surveyed – Not Detected				Aluminium ceiling, metal slats plastic cable brick CMS, wood, conduits above false ceiling				Yes	
24146	ACTIVE	P	D227-00-1/602/CLG-01	Ceiling: Suspended - 1 - Linear Stairs - Station Building - Hounslow West Stn		Asbestos	Surveyed – Not Detected				Supalux					



Hazardous Material Asset Register - Summary



D227-00 - Station Building - Hounslow West Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5418	ACTIVE	P	D227-00-1/603	Stairs: Linear - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24218	ACTIVE	P	D227-00-1/603	Stairs: Linear - Station Building - Hounslow West Stn	Lead/Leading	Lead Paint/Lead	Known				On railing - 5m² - Red gloss. Thickness : 0.15mm Analysis : 11.9%					
24150	ACTIVE	P	D227-00-1/603	Stairs: Linear - Station Building - Hounslow West Stn	Lead/Leading	Lead Paint/Lead	Known				On gates - 1m² - Yellow gloss. Thickness : 0.21mm Analysis : 7.32%,white gloss on beams					
24148	ACTIVE	P	D227-00-1/603/CLG-01 80868129	Ceiling: Solid - 1 - Linear Stairs - Station Building - Hounslow West Stn Ceiling: Solid	Void	Asbestos	Surveyed – Not Detected				Above metal and wood frame					
24149	INACTIVE	P	D227-00-1/603/CLG-02	Ceiling: Suspended - 2 - Linear Stairs - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				Above metal and wood frame					
5419	ACTIVE	P	D227-00-1/661	Switch Room - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25172	ACTIVE	P	D227-00-1/661/WAL-001 80868140	Wall: Internal - 1 - Switch Room - Station Building - Hounslow West Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box - P - Asbestos Components within		1			
24231	ACTIVE	P	D227-00-1/661/WAL-002 80868141	Wall: Internal - 2 - Switch Room - Station Building - Hounslow West Stn Wall: Internal	Cable Duct: Other	Asbestos	Strongly Presumed				4 x cable sleeves - filled over to floor		4			
24151	ACTIVE	P	D227-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Hounslow West Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box - P- Asbestos Components within		1			
24230	ACTIVE	P	D227-00-1/661/WAL-003 80868142	Wall: Internal - 3 - Switch Room - Station Building - Hounslow West Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				8x Iron Clad Isolators - 1 x 30amp Red, 6 x 60amp, 1 x 100amp - Asbestos Components within		8			
24229	ACTIVE	P	D227-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Hounslow West Stn	Other Electrical Boxes	Lead Paint/Lead	Strongly Presumed				Trunking - SP - Asbestos Components within					
5420	ACTIVE	P	D227-00-1/665	Switch Cupboard - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24232	ACTIVE	P	D227-00-1/665/FLR-01	Floor - 1 - Switch Cupboard - Station Building - Hounslow West Stn	Cable Duct: Other	Asbestos	Presumed				6 x Cable Sleeves beneath concrete & Wooden Slates (these have been replaced with yellow covers)		6			
5421	ACTIVE	P	D227-00-1/746	SCR - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24234	ACTIVE	P	D227-00-1/746/CLG-01	Ceiling: Suspended - 1 - SCR - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				Above false ceiling					



Hazardous Material Asset Register - Summary



D227-00 - Station Building - Hounslow West Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24233	ACTIVE	P	D227-00-1/746/CLG-01	Ceiling: Suspended - 1 - SCR - Station Building - Hounslow West Stn		Asbestos	Surveyed – Not Detected				Supalux					
24235	ACTIVE	P	D227-00-1/791/CLG-01	Ceiling: Solid - 1 - Vent Shaft - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				Above metal ceiling					
24237	ACTIVE	P	D227-00-1/792/CLG-01	Ceiling: Solid - 1 - Vent Shaft - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				Above metal ceiling					
24236	INACTIVE	P	D227-00-1/792/FLR-01	Floor - 1 - Vent Shaft - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				Beneath wooden panel					
5422	ACTIVE	P	D227-00-2/201	Passage - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24238	ACTIVE	P	D227-00-2/201/FLR-01 80947627	Floor - 1 - Passage - Station Building - Hounslow West Stn Floor	Void	Asbestos	No Access: Presumed				Beneath 4 x floor hatches 1 x now visible					
24239	ACTIVE	P	D227-00-2/201/WAL-001	Wall: Internal - 1 - Passage - Station Building - Hounslow West Stn		Asbestos	Surveyed – Not Detected				1x Supalux partition around garden					
5423	ACTIVE	P	D227-00-2/406	Locker Room - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24241	ACTIVE	P	D227-00-2/406/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Hounslow West Stn		Asbestos	Surveyed – Not Detected				Supalux					
24242	ACTIVE	P	D227-00-2/406/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Hounslow West Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Terracotta Tiles above false ceiling				Yes	
24240	ACTIVE	P	D227-00-2/406/FLR-01	Floor - 1 - Locker Room - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				Beneath Lino					
5424	ACTIVE	P	D227-00-2/411	Store - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5425	ACTIVE	P	D227-00-2/412	Store - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24243	ACTIVE	P	D227-00-2/412/WDW-01	Window - 1 - Store - Station Building - Hounslow West Stn	Lead/Leading	Lead Paint/Lead	Known				On window x 2 - White gloss - 2m². Thickness : 0.50mm Analysis : 13.0%					
5426	ACTIVE	P	D227-00-2/413	Store - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24244	ACTIVE	P	D227-00-2/413/FLR-01 80868239	Floor - 1 - Store - Station Building - Hounslow West Stn Floor	Void	Asbestos	No Access: Presumed				Beneath 2x floor hatches presumably beneath lock boxes					



Hazardous Material Asset Register - Summary



D227-00 - Station Building - Hounslow West Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5427	ACTIVE	P	D227-00-2/416	Disused Room - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25180	ACTIVE	P	D227-00-2/416/WDW-01	Window - 1 - Disused Room - Station Building - Hounslow West Stn	Lead/Leading	Lead Paint/Lead	Known				5m² - white gloss. Thickness : 0.50mm Analysis : 13.0%					
24245	ACTIVE	P	D227-00-2/416/WDW-02	Window - 2 - Disused Room - Station Building - Hounslow West Stn	Lead/Leading	Lead Paint/Lead	Known				5m² - white gloss. Thickness : 0.50mm Analysis : 13.0%					
24246	ACTIVE	P	D227-00-2/416/WDW-03	Window - 3 - Disused Room - Station Building - Hounslow West Stn	Lead/Leading	Lead Paint/Lead	Known				5m² - white gloss. Thickness : 0.50mm Analysis : 13.0%					
24247	ACTIVE	P	D227-00-2/416/WDW-04	Window - 4 - Disused Room - Station Building - Hounslow West Stn	Lead/Leading	Lead Paint/Lead	Known				5m² - white gloss. Thickness : 0.50mm Analysis : 13.0%					
5428	ACTIVE	P	D227-00-2/661	Switch Room - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24249	ACTIVE	P	D227-00-2/661/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Hounslow West Stn		Asbestos	Surveyed – Not Detected				Supalux panels by wall 2					
25181	ACTIVE	P	D227-00-2/661/CLG-01 80868589	Ceiling: Solid - 1 - Switch Room - Station Building - Hounslow West Stn Ceiling: Solid	Void	Asbestos	Surveyed – Not Detected				No false ceilings or void to ceiling					
24248	ACTIVE	P	D227-00-2/661/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Hounslow West Stn		Asbestos	Surveyed – Not Detected				2x Supalux panel					
24250	ACTIVE	P	D227-00-2/661/WAL-005 80868276	Wall: Internal - 5 - Switch Room - Station Building - Hounslow West Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				1x 30amp Iron clad isolator - Asbestos Components Within		1			
24220	ACTIVE	P	D227-00-2/661/WAL-005 80868276	Wall: Internal - 5 - Switch Room - Station Building - Hounslow West Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				3 x Transformer Boxes - Asbestos Components Within		3			
5429	ACTIVE	P	D227-00-2/662	Switch Room - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25182	ACTIVE	P	D227-00-2/662	Switch Room - Station Building - Hounslow West Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1 x Trunking - Asbestos Components Within		1			
24252	ACTIVE	P	D227-00-2/662	Switch Room - Station Building - Hounslow West Stn	Isolator Switches	Asbestos	Strongly Presumed				4x Iron clad isolators - 1 x 60amp, 1 x 100amp, 2 x 200amp - Asbestos Components Within		4			
24251	ACTIVE	P	D227-00-2/662/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Hounslow West Stn		Asbestos	Surveyed – Not Detected				Supalux panel by wall 13					



Hazardous Material Asset Register - Summary



D227-00 - Station Building - Hounslow West Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5430	ACTIVE	P	D227-00-2/663	Switch Room - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5431	ACTIVE	P	D227-00-2/731	CER - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24253	ACTIVE	P	D227-00-2/731/FLR-01	Floor - 1 - CER - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				Beneath manholes					Yes
24328	ACTIVE	P	D227-00-2/731/WAL-002 80868315	Wall: Internal - 2 - CER - Station Building - Hounslow West Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				2 x 60amp Iron clad isolators - Asbestos Components Within		2			
5432	ACTIVE	P	D227-00-2/732	Lobby - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5433	ACTIVE	P	D227-00-2/901	Store - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24331	ACTIVE	P	D227-00-2/901	Store - Station Building - Hounslow West Stn	Lead/Leading	Lead Paint/Lead	Known				Front window - 1m² - white gloss. Thickness : 0.50mm Analysis : 13.0%					
24329	ACTIVE	P	D227-00-2/901/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Hounslow West Stn		Asbestos	Surveyed – Not Detected				Supalux panel by wall 13					
24330	ACTIVE	P	D227-00-2/901/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				Above supalux panel				Yes	
5434	ACTIVE	P	D227-00-2/902	Disused Room - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5435	ACTIVE	P	D227-00-3/236	Lobby - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24334	ACTIVE	P	D227-00-3/236	Lobby - Station Building - Hounslow West Stn	Cable: Sheath	Asbestos	Known				Cable, invert in room		1			
24332	ACTIVE	P	D227-00-3/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Hounslow West Stn		Asbestos	Surveyed – Not Detected				Supalux					
24333	ACTIVE	P	D227-00-3/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Hounslow West Stn	Void	Asbestos	Surveyed – Not Detected				Concrete , solid walls above false ceiling				Yes	
5436	ACTIVE	P	D227-00-3/261	Platform 1 - Westbound Local - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D227-00 - Station Building - Hounslow West Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24337	ACTIVE	p	D227-00-3/261	Platform 1 - Westbound Local - Station Building - Hounslow West Stn	Other Boarding	Asbestos	Known				Canopy soffit - Amosite (Brown) along the platform Minor repairs & localised encapsulation was completed by DCUK - 05/07/2021 - HM00416					
45184	ACTIVE	p	D227-00-3/261	Platform 1 - Westbound Local - Station Building - Hounslow West Stn	Cable: Sheath	Asbestos	Known				Westbound Invert nr 3/711 - 3x Braided Cable		3	E775-935	N	N
24335	ACTIVE	p	D227-00-3/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Hounslow West Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, conduits rubber cables above false ceiling				Yes	
24336	ACTIVE	p	D227-00-3/261/CLG-02	Ceiling: Solid - 2 - Platform 1 - Station Building - Hounslow West Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, conduits rubber cables above false ceiling				Yes	
5437	ACTIVE	p	D227-00-3/262	Platform 2 - Eastbound Local - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24429	INACTIVE	p	D227-00-3/262	Platform 2 - Eastbound Local - Station Building - Hounslow West Stn	Cable: Sheath	Asbestos	Strongly Presumed				Eastbound Invert nr 3/711 - 1x 12cmØ Cable - from outer pit side		1			
24338	ACTIVE	p	D227-00-3/262	Platform 2 - Eastbound Local - Station Building - Hounslow West Stn	Cable: Sheath	Asbestos	Known				Eastbound Invert nr 3/711 - 3x Braided cable		3			
24345	ACTIVE	p	D227-00-3/262	Platform 2 - Eastbound Local - Station Building - Hounslow West Stn	Cable: Sheath	Asbestos	Strongly Presumed				Eastbound Invert nr 3/712 - 2 x 12cmØ & 3x 2cmØ cable in east bound and middle invert by 3/712		2			
24342	ACTIVE	p	D227-00-3/262	Platform 2 - Eastbound Local - Station Building - Hounslow West Stn	Cable: Sheath	Asbestos	Strongly Presumed				Eastbound Invert nr 3/711 - Pit side - 1 x 12cmØ Cable, white, frayed in places, water damage		1			
25189	ACTIVE	p	D227-00-3/262	Platform 2 - Eastbound Local - Station Building - Hounslow West Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Eastbound Invert nr 3/711 - cable sleeves - In drain, gully trench track full of water					
24344	ACTIVE	p	D227-00-3/262	Platform 2 - Eastbound Local - Station Building - Hounslow West Stn	Cable: Sheath	Asbestos	Strongly Presumed				Eastbound Invert nr 3/712 - 1x 12cmØ Cable from outer pit side		1			
24340	ACTIVE	p	D227-00-3/262	Platform 2 - Eastbound Local - Station Building - Hounslow West Stn	Other Boarding	Asbestos	Known				60m² Boarding at high level Canopy soffit & boarding along the platform Amosite (Brown) Minor repairs & localised encapsulation was completed by DCUK - 05/07/2021 - HM00416					
24343	ACTIVE	p	D227-00-3/262	Platform 2 - Eastbound Local - Station Building - Hounslow West Stn	Cable: Sheath	Asbestos	Strongly Presumed				Eastbound Invert nr 3/711 - 3 x 2cmØ cables, white - pit side		3			
24346	ACTIVE	p	D227-00-3/262	Platform 2 - Eastbound Local - Station Building - Hounslow West Stn	Cable: Sheath	Asbestos	Strongly Presumed				Eastbound Invert nr 3/712 - 1 x 30cmØ & 3x 2cmØ cables going to west end of platform					



Hazardous Material Asset Register - Summary



D227-00 - Station Building - Hounslow West Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24341	ACTIVE	P	D227-00-3/262	Platform 2 - Eastbound Local - Station Building - Hounslow West Stn	Lead/Leading	Lead Paint/Lead	Removed				Stretcher cupboard - 2m² Green gloss. Thickness : 0.28mm Analysis : 12.8%					
24339	ACTIVE	P	D227-00-3/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - Hounslow West Stn	Void	Asbestos	Surveyed – Not Detected				Above false ceiling				Yes	
24223	ACTIVE	P	D227-00-3/262/CLG-02	Ceiling: Solid - 2 - Platform 2 - Station Building - Hounslow West Stn	Void	Asbestos	Surveyed – Not Detected				Above false ceiling				Yes	
5438	ACTIVE	P	D227-00-3/281	Mess Room - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24347	ACTIVE	P	D227-00-3/281/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Hounslow West Stn		Asbestos	Surveyed – Not Detected				Supalux					
24348	ACTIVE	P	D227-00-3/281/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Hounslow West Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, solid walls above false ceiling				Yes	
25190	ACTIVE	P	D227-00-3/281/FLR-01	Floor - 1 - Mess Room - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				Beneath floor hatch					Yes
5439	ACTIVE	P	D227-00-3/411	Store - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24349	ACTIVE	P	D227-00-3/411/FLR-01	Floor - 1 - Store - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				Beneath floor hatch- sealed shut					Yes
24350	ACTIVE	P	D227-00-3/411/WAL-003	Wall: Internal - 3 - Store - Station Building - Hounslow West Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LTB Heater 2 x foam panels		2			
5440	ACTIVE	P	D227-00-3/412	Disused Room - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25191	ACTIVE	P	D227-00-3/412/FLR-01	Floor - 1 - Disused Room - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				Beneath rubber tiles					Yes
5441	ACTIVE	P	D227-00-3/661	Switch Room - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24431	ACTIVE	P	D227-00-3/661	Switch Room - Station Building - Hounslow West Stn	Other Electrical Boxes	Asbestos	Presumed				2 x Transformer Boxes Wall 1 & Wall 2		2			
24352	ACTIVE	P	D227-00-3/661	Switch Room - Station Building - Hounslow West Stn	Other Boarding	Asbestos	Strongly Presumed				Walls - Various paxoline panels on electrical equipment	2				
24354	ACTIVE	P	D227-00-3/661/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Hounslow West Stn	Void	Asbestos	Surveyed – Not Detected				Brick, concrete, plastic cables, high level boxing supalux on wall 4 above false ceiling				Yes	



Hazardous Material Asset Register - Summary



D227-00 - Station Building - Hounslow West Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24353	ACTIVE	P	D227-00-3/661/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Hounslow West Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
5442	ACTIVE	P	D227-00-3/711	Relay Room - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24433	ACTIVE	P	D227-00-3/711	Relay Room - Station Building - Hounslow West Stn	Lead/Leading	Lead Paint/Lead	Removed				Fire point box nr 3/711 - 1m² - Red gloss. Thickness : 0.15mm Analysis : 5.94% Not found assumed box has been removed					
24432	ACTIVE	P	D227-00-3/711/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				Above metal ceiling				Yes	
42921	ACTIVE	P	D227-00-3/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Hounslow West Stn	PCBs	Asbestos	Removed				PCB Large Silver					
42920	ACTIVE	P	D227-00-3/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Hounslow West Stn	PCBs	Asbestos	Presumed				PCB Rack Mounted					
42922	ACTIVE	P	D227-00-3/711/WAL-001 80868527	Wall: Internal - 1 - Relay Room - Station Building - Hounslow West Stn Wall: Internal	Other Boarding	Asbestos	Presumed				Paxoline Boards - various forms throughout all walls	2				
42919	ACTIVE	P	D227-00-3/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Hounslow West Stn	PCBs	Asbestos	Removed				PCB Blue Cylinder					
5443	ACTIVE	P	D227-00-3/712	Relay Room - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5444	ACTIVE	P	D227-00-3/731	CER - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24436	ACTIVE	P	D227-00-3/731/CLG-01	Ceiling: Suspended - 1 - CER - Station Building - Hounslow West Stn	Void	Asbestos	Surveyed – Not Detected				Brick, concrete & plastic cables above false ceiling				Yes	
24435	ACTIVE	P	D227-00-3/731/CLG-01	Ceiling: Suspended - 1 - CER - Station Building - Hounslow West Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
24434	ACTIVE	P	D227-00-3/731/WAL-001	Wall: Internal - 1 - CER - Station Building - Hounslow West Stn	Void	Asbestos	No Access: Presumed				No access behind as fire rating would be compromised - high level boarding non asbestos with new mastic on outer edges					
5445	ACTIVE	P	D227-00-3/761	Traction Control Room - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24437	ACTIVE	P	D227-00-3/761	Traction Control Room - Station Building - Hounslow West Stn	No Access	Asbestos	No Access: Presumed				Not surveyed					



Hazardous Material Asset Register - Summary



D227-00 - Station Building - Hounslow West Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5446	ACTIVE	P	D227-00-3/901	Disused Room - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5447	ACTIVE	P	D227-00-3/951	Mess Room - Station Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24438	ACTIVE	P	D227-00-3/951/FLR-01	Floor - 1 - Mess Room - Station Building - Hounslow West Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath rubber tiles					Yes
24440	ACTIVE	P	D227-00-3/951/WAL-004	Wall: Internal - 4 - Mess Room - Station Building - Hounslow West Stn	Void	Asbestos	Surveyed – Not Detected				Concrete & Solid walls above false ceiling				Yes	
24439	ACTIVE	P	D227-00-3/951/WAL-004	Wall: Internal - 4 - Mess Room - Station Building - Hounslow West Stn		Asbestos	Surveyed – Not Detected				Supalux					

D229-00 - Station Building - Hatton Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5451	ACTIVE	P	D229-00-1/001	Booking Hall - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45281	ACTIVE	P	D229-00-1/001	Booking Hall - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Known				Cable pit by waiting area adjacent to shop 1/451 - 2x white braided cables (within 3 no walls?)		2		N	N
24445	ACTIVE	P	D229-00-1/001/CLG-01	Ceiling: Suspended - 1 - Booking Hall - Station Building - Hatton Cross Stn	Void	Asbestos	No Access: Presumed				Void above false ceiling				Yes	
24444	ACTIVE	P	D229-00-1/001/FLR-01	Floor - 1 - Booking Hall - Station Building - Hatton Cross Stn	Void	Asbestos	No Access: Presumed				No Access beneath Inspection Chambers to Floor For Cable Pit adjacent to 1/451 see 45281					Yes
42647	ACTIVE	P	D229-00-1/001/FLR-01	Floor - 1 - Booking Hall - Station Building - Hatton Cross Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Bitumen cable ducts 19 no within 3 no walls within cable pit	19		R513651	N	N
42648	ACTIVE	P	D229-00-1/001/FLR-01	Floor - 1 - Booking Hall - Station Building - Hatton Cross Stn	Cable Duct: Other	Asbestos	Room: Surveyed – Asbestos Known				White braided cables 2 no within 3 no walls within cable pit	2		R513651	N	N
42646	ACTIVE	P	D229-00-1/001/FLR-01	Floor - 1 - Booking Hall - Station Building - Hatton Cross Stn	Cable Duct: Other	Asbestos	Room: Surveyed – Asbestos Known				White braided cables 2 no within 2no walls within cable pit	2		R513651	N	N
42645	ACTIVE	P	D229-00-1/001/FLR-01	Floor - 1 - Booking Hall - Station Building - Hatton Cross Stn	Cable Ducts: Bitumen	Asbestos	Room: Surveyed – Asbestos Known				Bitumen cable ducts 16 no within 2 no walls within cable pit	16		R513651	N	N
5452	ACTIVE	P	D229-00-1/011	Ticket Office - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D229-00 - Station Building - Hatton Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24447	ACTIVE	P	D229-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, metal trunking, plastic cables, brick above manmade mineral fibre tiles				Yes	
42566	ACTIVE	P	D229-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Hatton Cross Stn	Debris: Other	Asbestos	Sampled – Not Detected				Dust / debris throughout within floor void			R498476	N	N
24446	ACTIVE	P	D229-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; plastic cables, metal ducting beneath computer tiles					Yes
5453	ACTIVE	P	D229-00-1/021	POM - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24225	ACTIVE	P	D229-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, metal trunking, plastic cables, brick above manmade mineral fibre tiles				Yes	
24448	ACTIVE	P	D229-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, cable steel ducts beneath computer tiles					Yes
5454	ACTIVE	P	D229-00-1/031	Mess Room - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24450	ACTIVE	P	D229-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, metal trunking, plastic cables, brick above manmade mineral fibre tiles				Yes	
24449	ACTIVE	P	D229-00-1/031/FLR-01	Floor - 1 - Mess Room - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Rubber raised tiles on Solid					Yes
5455	ACTIVE	P	D229-00-1/036	Toilet: Unisex - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25277	ACTIVE	P	D229-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Hatton Cross Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
24451	ACTIVE	P	D229-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Bricks, Concrete above false ceiling				Yes	
5456	ACTIVE	P	D229-00-1/071	Circulation Area - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24452	ACTIVE	P	D229-00-1/071/CLG-01	Ceiling: Suspended - 1 - Circulation Area - Station Building - Hatton Cross Stn	Void	Asbestos	Sampled – Not Detected				NB canopy above ticket window sampled NAD - above false ceiling				Yes	
5457	ACTIVE	P	D229-00-1/081	Lobby - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D229-00 - Station Building - Hatton Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24453	ACTIVE	P	D229-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, metal trunking, plastic cables, brick above manmade mineral fibre tiles				Yes	
5458	ACTIVE	P	D229-00-1/201	Circulation Area - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25278	ACTIVE	P	D229-00-1/201/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Hatton Cross Stn	Void	Asbestos	No Access: Presumed				No Access above Plasterboard Ceiling				Yes	
24454	ACTIVE	P	D229-00-1/201/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Hatton Cross Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
5459	ACTIVE	P	D229-00-1/236	Lobby - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24455	ACTIVE	P	D229-00-1/236/DOR-01	Door - 1 - Lobby - Station Building - Hatton Cross Stn		Asbestos	Surveyed – Not Detected				Supalux Panel on fthe ront and back of the door					
5460	ACTIVE	P	D229-00-1/237	Lobby - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24515	ACTIVE	P	D229-00-1/237/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Mmmf boarding - Boxing to trunking above false ceiling, concrete, metal trunking, plastic cables, brick above manmade mineral fibre tiles				Yes	
24456	ACTIVE	P	D229-00-1/237/FLR-01	Floor - 1 - Lobby - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
5461	ACTIVE	P	D229-00-1/311	Office - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24518	ACTIVE	P	D229-00-1/311/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, plastic cables, trunking, brick, above manmade mineral fibre tiles				Yes	
24516	ACTIVE	P	D229-00-1/311/FLR-01	Floor - 1 - Office - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Rubber raised tiles on solid					Yes
24517	ACTIVE	P	D229-00-1/311/WAL-003	Wall: Internal - 3 - Office - Station Building - Hatton Cross Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LTB LUL Heater		1			
5462	ACTIVE	P	D229-00-1/401	Bin Store - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5463	ACTIVE	P	D229-00-1/451	Tenancy - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D229-00 - Station Building - Hatton Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24520	ACTIVE	P	D229-00-1/451/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Hatton Cross Stn	Void	Asbestos	No Access: Presumed				No Access above false ceiling NB Tenancy Managed by TFL Commercial Properties				Yes	
24519	ACTIVE	P	D229-00-1/451/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Hatton Cross Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
5464	ACTIVE	P	D229-00-1/601	Stairs: Linear - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24521	ACTIVE	P	D229-00-1/601	Stairs: Linear - Station Building - Hatton Cross Stn	Other Electrical Boxes	Asbestos	Removed				Train indication sign		1			
5465	ACTIVE	P	D229-00-1/602	Stairs: Linear - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24523	ACTIVE	P	D229-00-1/602/CLG-01	Ceiling: Suspended - 1 - Linear Stairs - Station Building - Hatton Cross Stn	Void	Asbestos	No Access: Presumed				No Access above Plasterboard Ceiling				Yes	
24522	ACTIVE	P	D229-00-1/602/CLG-01	Ceiling: Suspended - 1 - Linear Stairs - Station Building - Hatton Cross Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard, Artex					
5466	ACTIVE	P	D229-00-1/603	Stairs: Linear - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24525	ACTIVE	P	D229-00-1/603/CLG-01	Ceiling: Suspended - 1 - Linear Stairs - Station Building - Hatton Cross Stn	Void	Asbestos	No Access: Presumed				No access above Plasterboard ceiling				Yes	
24524	ACTIVE	P	D229-00-1/603/CLG-01	Ceiling: Suspended - 1 - Linear Stairs - Station Building - Hatton Cross Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard, Artex					
5467	ACTIVE	P	D229-00-1/604	Stairs: Linear - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46356	ACTIVE	P	D229-00-1/604	Stairs: Linear - Station Building - Hatton Cross Stn	Debris: Other	Asbestos	Sampled – Not Detected				White debris on top of false ceiling panels	1		R679608	N	N
24526	ACTIVE	P	D229-00-1/604	Stairs: Linear - Station Building - Hatton Cross Stn	Other Electrical Boxes	Asbestos	Removed				Train indication sign		1			
46357	ACTIVE	P	D229-00-1/604/CLG-01	Ceiling: Suspended - 1 - Linear Stairs - Station Building - Hatton Cross Stn	Debris: Other	Asbestos	Sampled – Not Detected				White debris on top of false ceiling panels	1		R679608	N	N
46358	ACTIVE	P	D229-00-1/604/CLG-01	Ceiling: Suspended - 1 - Linear Stairs - Station Building - Hatton Cross Stn	Mastic	Asbestos	Sampled – Not Detected				White mastic throughout to false ceiling panels	10		R679608	N	N



Hazardous Material Asset Register - Summary



D229-00 - Station Building - Hatton Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5468	ACTIVE	P	D229-00-1/661	Switch Room - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45283	ACTIVE	P	D229-00-1/661	Switch Room - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Known				Cable Pit - 2x White braided cables running from external wall (bus stop side) along walls (loose to floor) and into electrical main sector box		2		N	N
45282	ACTIVE	P	D229-00-1/661	Switch Room - Station Building - Hatton Cross Stn	Cable Ducts: Bitumen	Asbestos	Known				Cable Pit - 8x cable ducts to external wall(bus stop side) in cable pit		8		N	N
42652	ACTIVE	P	D229-00-1/661	Switch Room - Station Building - Hatton Cross Stn	Cable Duct: Other	Asbestos	Room: Surveyed – Asbestos Known				White braided cables 2 no x 70m Within wall (shop side), labelled and encapsulated with Incorez	70	2	R513651	N	N
42651	ACTIVE	P	D229-00-1/661	Switch Room - Station Building - Hatton Cross Stn	Cable Ducts: Bitumen	Asbestos	Room: Surveyed – Asbestos Known				Bitumen cable ducts 10 no within wall (shop side)	10		R513651	N	N
24529	ACTIVE	P	D229-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Hatton Cross Stn	Isolator Switches	Asbestos	Presumed				1x 60amp Combination switch box		1			
25286	ACTIVE	P	D229-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Hatton Cross Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Boxes No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
24228	ACTIVE	P	D229-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Hatton Cross Stn	Isolator Switches	Asbestos	Presumed				1x 30amp Combination switch box		1			
42642	ACTIVE	P	D229-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Hatton Cross Stn	Cable Duct: Other	Asbestos	Room: Surveyed – Asbestos Known				White braided cables 2 no Running from external wall (bus stop side) along walls (loose to floor) and into electrical main sector box	2		R513651	N	N
24530	ACTIVE	P	D229-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Hatton Cross Stn	Other Electrical Boxes	Asbestos	Presumed				3 x Transformer Boxes		3			
42649	ACTIVE	P	D229-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Hatton Cross Stn	Cable Ducts: Bitumen	Asbestos	Room: Surveyed – Asbestos Known				Bitumen cable ducts 8 no to external wall (bus stop side) in cable pit	8		R513651	N	N
42641	ACTIVE	P	D229-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Hatton Cross Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Bitumen cable ducts 8 no to external wall (bus stop side) in cable pit	8		R513651	N	N
24527	ACTIVE	P	D229-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Hatton Cross Stn	Cable Ducts: Cement	Asbestos	Known				2 x 6"x6" cement pads below electric meter		2			
24528	ACTIVE	P	D229-00-1/661/WAL-003 80864385	Wall: Internal - 3 - Switch Room - Station Building - Hatton Cross Stn Wall: Internal	Cable: Sheath	Asbestos	Known				60mm x 2 woven sheath cables - Exit: main switch board, right hand side of door		2			



Hazardous Material Asset Register - Summary



D229-00 - Station Building - Hatton Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5469	ACTIVE	P	D229-00-1/662	Switch Room - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24531	ACTIVE	P	D229-00-1/662	Switch Room - Station Building - Hatton Cross Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - new build					
5470	ACTIVE	P	D229-00-1/663	Switch Cupboard - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5471	ACTIVE	P	D229-00-1/731	CER - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24532	ACTIVE	P	D229-00-1/731	CER - Station Building - Hatton Cross Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - new build					
5472	ACTIVE	P	D229-00-1/746	SCR - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24535	ACTIVE	P	D229-00-1/746/CLG-01	Ceiling: Suspended - 1 - SCR - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Previous Supalux Ceiling Removed				Yes	
24534	ACTIVE	P	D229-00-1/746/CLG-01	Ceiling: Suspended - 1 - SCR - Station Building - Hatton Cross Stn		Asbestos	Surveyed – Not Detected				Supalux; Supalux Panel					
24533	ACTIVE	P	D229-00-1/746/FLR-01	Floor - 1 - SCR - Station Building - Hatton Cross Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected									
5473	ACTIVE	P	D229-00-1/751	Station Control Room - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25287	ACTIVE	P	D229-00-1/751	Station Control Room - Station Building - Hatton Cross Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - new build					
5474	ACTIVE	P	D229-00-1/761	Plant Room - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44284	ACTIVE	P	D229-00-1/761	Plant Room - Station Building - Hatton Cross Stn		Asbestos	Sampled – Not Detected				Mastic throughout to vent ducts joints			R609401	N	N
24537	INACTIVE	P	D229-00-1/761/CLG-01	Ceiling: Solid - 1 - Plant Room - Station Building - Hatton Cross Stn	Void	Asbestos	Removed				No False Ceiling				Yes	
24536	ACTIVE	P	D229-00-1/761/CLG-01	Ceiling: Solid - 1 - Plant Room - Station Building - Hatton Cross Stn		Asbestos	Surveyed – Not Detected				Supalux Boxing					
24538	ACTIVE	P	D229-00-1/761/WAL-002	Wall: Internal - 2 - Plant Room - Station Building - Hatton Cross Stn		Asbestos	Surveyed – Not Detected				Supalux surround vent ducts					



Hazardous Material Asset Register - Summary



D229-00 - Station Building - Hatton Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44283	ACTIVE	P	D229-00-1/761/WAL-004	Wall: Internal - 4 - Plant Room - Station Building - Hatton Cross Stn	Control Panels	Asbestos	Presumed				Control panel 1 no to wall 4			R609401	N	N
5475	ACTIVE	P	D229-00-1/762	Computer Equipment Cupboard - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25288	ACTIVE	P	D229-00-1/762	Computer Equipment Cupboard - Station Building - Hatton Cross Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - new build					
5476	ACTIVE	P	D229-00-1/763	Computer Equipment Cupboard - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24539	ACTIVE	P	D229-00-1/763	Computer Equipment Cupboard - Station Building - Hatton Cross Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - new build					
5477	ACTIVE	P	D229-00-1/764	Computer Equipment Cupboard - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24540	ACTIVE	P	D229-00-1/764	Computer Equipment Cupboard - Station Building - Hatton Cross Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - new build					
5478	ACTIVE	P	D229-00-1/765	Computer Equipment Cupboard - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24541	ACTIVE	P	D229-00-1/765	Computer Equipment Cupboard - Station Building - Hatton Cross Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - new build					
5479	ACTIVE	P	D229-00-1/766	Computer Equipment Cupboard - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25289	ACTIVE	P	D229-00-1/766	Computer Equipment Cupboard - Station Building - Hatton Cross Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - new build					
5480	ACTIVE	P	D229-00-1/767	Computer Equipment Cupboard - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24542	ACTIVE	P	D229-00-1/767	Computer Equipment Cupboard - Station Building - Hatton Cross Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - new build					
5481	ACTIVE	P	D229-00-1/776	Fan Room - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5482	ACTIVE	P	D229-00-1/781	Substation Room - Substation - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D229-00 - Station Building - Hatton Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24600	INACTIVE	P	D229-00-1/781	Substation Room - Substation - Hatton Cross Stn	No Access	Asbestos	No Access: Presumed				Property Managed by LU Power & Electrical					
42644	ACTIVE	P	D229-00-1/781	Substation Room - Substation - Hatton Cross Stn	Cable Duct: Other	Asbestos	Room: Surveyed – Asbestos Known				White braided cables 2 no X 70m Within wall (shop side), labelled and encapsulated with Incorez	70	2	R513651	N	N
42643	ACTIVE	P	D229-00-1/781	Substation Room - Substation - Hatton Cross Stn	Cable Ducts: Bitumen	Asbestos	Room: Surveyed – Asbestos Known				Bitumen cable ducts 10 no within wall (shop side)	10		R513651	N	N
44291	ACTIVE	P	D229-00-1/781	Substation Room - Substation - Hatton Cross Stn		Asbestos	Sampled – Not Detected				Supalux panel 2 x 2m to the substation wall facing transitional area			R609401	N	N
45285	ACTIVE	P	D229-00-1/781	Substation Room - Substation - Hatton Cross Stn	Cable Ducts: Bitumen	Asbestos	Known				Property managed by LU Power & Electrical - 10x Bitumen cable ducts within wall (shop side)		10		N	N
45284	ACTIVE	P	D229-00-1/781	Substation Room - Substation - Hatton Cross Stn	Cable: Sheath	Asbestos	Known				Property managed by LU Power & Electrical - 2x 70m white braided cables within wall (shop side) labelled and encapsulated within incorez. (cables only encapsulated substation side and not in any cable pit	70	2		N	N
5483	ACTIVE	P	D229-00-1/791	CER - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5484	ACTIVE	P	D229-00-1/901	Office - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24415	ACTIVE	P	D229-00-1/901/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, plastic cables, metal trunking, brick above manmade mineral fibre tiles false ceiling				Yes	
24601	ACTIVE	P	D229-00-1/901/FLR-01	Floor - 1 - Office - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Rubber raised tiles on solid					Yes
5485	ACTIVE	P	D229-00-1/902	Office - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24602	ACTIVE	P	D229-00-1/902/WAL-004	Wall: Internal - 4 - Office - Station Building - Hatton Cross Stn	Isolator Switches	Asbestos	Presumed				1x 30amp Switch Box - Insulation within		1			
5486	ACTIVE	P	D229-00-2/053	Mess Room - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24604	ACTIVE	P	D229-00-2/053/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; supalux partition above false ceiling				Yes	
24603	ACTIVE	P	D229-00-2/053/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Hatton Cross Stn		Asbestos	Surveyed – Not Detected				Supalux; Concrete Panel					



Hazardous Material Asset Register - Summary



D229-00 - Station Building - Hatton Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5487	ACTIVE	P	D229-00-2/081	Lobby - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24608	ACTIVE	P	D229-00-2/081	Lobby - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Known				2x15mm Cable		2			
24611	ACTIVE	P	D229-00-2/081	Lobby - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Known				8x15mm cable - entry from invert, exit - LHS of relay room into relay room, j hanger no. 1		8			
24612	ACTIVE	P	D229-00-2/081	Lobby - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Known				4x30mm cable, entry from invert - exit: LHS of relay room into relay room, j hanger no. 2		4			
24613	ACTIVE	P	D229-00-2/081	Lobby - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Known				2x15mm cable - entry from invert, exit LHS of relay room into relay room, j hanger no. 3		2			
24614	ACTIVE	P	D229-00-2/081	Lobby - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Known				1x 30mm cable entry from invert, exit LHS of relay room into relay room, j hanger no. 3		1			
24615	ACTIVE	P	D229-00-2/081	Lobby - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Known				3x15mm cable entry from invert, exit LHS of relay room into relay room, j hanger no. 4		3			
24618	ACTIVE	P	D229-00-2/081	Lobby - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Known				10 x 15mm cable entry via invert runs along RHS relay room - j hanger no. 1		10			
24621	ACTIVE	P	D229-00-2/081	Lobby - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Known				1 x 15mm cable entry via invert runs along RHS relay room - j hanger no. 4		1			
24620	ACTIVE	P	D229-00-2/081	Lobby - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Known				1 x 20mm cable entry via invert runs along RHS relay room - j hanger no. 3`		1			
24619	ACTIVE	P	D229-00-2/081	Lobby - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Known				3x15mm cable entry via invert runs along RHS relay room - j hanger no. 3		3			
24605	ACTIVE	P	D229-00-2/081/WAL-001	Wall: Internal - 1 - Lobby - Station Building - Hatton Cross Stn	Westing house Boxes	Asbestos	Presumed				1 x Westinghouse Box - Insulation within		1			
24610	ACTIVE	P	D229-00-2/081/WAL-002	Wall: Internal - 2 - Lobby - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Known				1 x15mm cable - enters room via platform signal box wall 2 - drops into invert		1			
24609	ACTIVE	P	D229-00-2/081/WAL-003	Wall: Internal - 3 - Lobby - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Known				1x20mm cable enters room via invert to high level, exits through concrete ducts to wall 3 to trackside		1			
24617	ACTIVE	P	D229-00-2/081/WAL-005	Wall: Internal - 5 - Lobby - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Known				1x20mm cable entry through invert to high level, exit through concrete duct wall 5 to trackside		1			
25373	ACTIVE	P	D229-00-2/081/WAL-005	Wall: Internal - 5 - Lobby - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Known				4x15mm cable entry through invert to high level, exit through concrete duct wall 5 to trackside		4			
24616	ACTIVE	P	D229-00-2/081/WAL-006	Wall: Internal - 6 - Lobby - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Known				4x15mm Cable entry through invert up wall 6 - cable cut redundant		4			



Hazardous Material Asset Register - Summary



D229-00 - Station Building - Hatton Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24606	ACTIVE	P	D229-00-2/081/WAL-007	Wall: Internal - 7 - Lobby - Station Building - Hatton Cross Stn	Westing house Boxes	Asbestos	Presumed				2 x Westinghouse Box - Insulation within		2			
24607	ACTIVE	P	D229-00-2/081/WAL-007	Wall: Internal - 7 - Lobby - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Known				10mm cable -from westinghouse boxes into invert		1			
5488	ACTIVE	P	D229-00-2/236	Lobby - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25374	ACTIVE	P	D229-00-2/236/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
24623	ACTIVE	P	D229-00-2/236/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Hatton Cross Stn		Asbestos	Surveyed – Not Detected				Supalux					
24622	ACTIVE	P	D229-00-2/236/FLR-01	Floor - 1 - Lobby - Station Building - Hatton Cross Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Solid, Vinyl					
5489	ACTIVE	P	D229-00-2/261	Platform 1 - Westbound Local - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24688	ACTIVE	P	D229-00-2/261	Platform 1 - Westbound Local - Station Building - Hatton Cross Stn	Gasket :Pipework	Asbestos	Strongly Presumed				Concourse Invert (hatch near 2/081) - 7 x gaskets - 7m from entrance					
24689	ACTIVE	P	D229-00-2/261	Platform 1 - Westbound Local - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Known				Platform 1 Invert - 30 x cable sleeves - Chrysotile (including 6 x cable ducts departure end head wall - R202651)		30			
24687	ACTIVE	P	D229-00-2/261	Platform 1 - Westbound Local - Station Building - Hatton Cross Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Concourse Invert (hatch near 2/081) - 1 x cable sleeve filled in - 6m from entrance		1			
24695	ACTIVE	P	D229-00-2/261	Platform 1 - Westbound Local - Station Building - Hatton Cross Stn	Other Electrical Boxes	Asbestos	Presumed				Platform 1 Invert - possible ACM inside 2 electrical boxes on the track wall		2			
24690	ACTIVE	P	D229-00-2/261	Platform 1 - Westbound Local - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - 28 x braided cables - throughout invert		28			
24694	ACTIVE	P	D229-00-2/261	Platform 1 - Westbound Local - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - 5x Braided cables on platform side wall - green and white cables		5			
24693	ACTIVE	P	D229-00-2/261	Platform 1 - Westbound Local - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - 1x Braided cable - trackside wall on 3rd from top j hanger		1			
24692	ACTIVE	P	D229-00-2/261	Platform 1 - Westbound Local - Station Building - Hatton Cross Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Platform 1 Invert - 6 x cable ducts departure end head wall		6			



Hazardous Material Asset Register - Summary



D229-00 - Station Building - Hatton Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24691	ACTIVE	P	D229-00-2/261	Platform 1 - Westbound Local - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Known				Platform 1 Invert - 2 x cut braided cables		2			
24624	ACTIVE	P	D229-00-2/261/CLG-01	Ceiling: Suspended - 1 - Platform 1 - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Above canopy - plastic cables, concrete, soil pipes, brick				Yes	
24625	ACTIVE	P	D229-00-2/261/CLG-01	Ceiling: Suspended - 1 - Platform 1 - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Strongly Presumed				2 x braided cables in access hatch		2			
5490	ACTIVE	P	D229-00-2/262	Platform 2 - Eastbound Local - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24698	ACTIVE	P	D229-00-2/262	Platform 2 - Eastbound Local - Station Building - Hatton Cross Stn	Other Electrical Boxes	Asbestos	Presumed				Platform 2 - Concourse Invert (hatch near 2/081) - 3 x Fuse Boxes - Insulation within - 10m from Hatch		3			
24416	ACTIVE	P	D229-00-2/262	Platform 2 - Eastbound Local - Station Building - Hatton Cross Stn	Westing house Boxes	Asbestos	Presumed				Components within 2 x Small Westinghouse boxes		2			
24700	ACTIVE	P	D229-00-2/262	Platform 2 - Eastbound Local - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - 16 x braided cables throughout invert		16			
24699	ACTIVE	P	D229-00-2/262	Platform 2 - Eastbound Local - Station Building - Hatton Cross Stn	Cable Duct: Other	Asbestos	Known				Platform 2 - Invert 6 x cable sleeves - Head wall - Chrysotile		6			
24702	ACTIVE	P	D229-00-2/262	Platform 2 - Eastbound Local - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Strongly Presumed				4 x braided cables - crossing invert		4			
24697	ACTIVE	P	D229-00-2/262	Platform 2 - Eastbound Local - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Platform 2 - concourse Invert (hatch near 2/081) - above canopy - plastic cables, concrete, soil pipes, brick above metal grills				Yes	
24701	ACTIVE	P	D229-00-2/262	Platform 2 - Eastbound Local - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Presumed				Platform 2 Invert - Cut Cables 3 x 14m, 15m & 25m from entrance		3			
24696	ACTIVE	P	D229-00-2/262/CLG-01	Ceiling: Suspended - 1 - Platform 2 - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Above canopy - plastic cables, concrete, soil pipes, brick				Yes	
5491	ACTIVE	P	D229-00-2/291	Office - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24704	ACTIVE	P	D229-00-2/291/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Hatton Cross Stn		Asbestos	Surveyed – Not Detected				Supalux					
24705	ACTIVE	P	D229-00-2/291/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	



Hazardous Material Asset Register - Summary



D229-00 - Station Building - Hatton Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24703	ACTIVE	P	D229-00-2/291/WAL-003	Wall: Internal - 3 - Office - Station Building - Hatton Cross Stn	Other Boarding	Asbestos	Surveyed – Not Detected				LTB heater - 18"x12" board to back of heater					
5492	ACTIVE	P	D229-00-2/331	Mess Room - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44288	ACTIVE	P	D229-00-2/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Hatton Cross Stn	Control Panels	Asbestos	Presumed				Control panel 1no to wall 2 behind locker					
44285	ACTIVE	P	D229-00-2/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Hatton Cross Stn		Asbestos	Sampled – Not Detected				Supalux panel 10 x 0.5m to wall 2 behind locker			R609401	N	N
24706	ACTIVE	P	D229-00-2/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
44287	ACTIVE	P	D229-00-2/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Hatton Cross Stn		Asbestos	Sampled – Not Detected				Supalux panel 10m2 to ceiling			R609401	N	N
44286	ACTIVE	P	D229-00-2/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Hatton Cross Stn		Asbestos	Sampled – Not Detected				Supalux panel 1 x 0.2m to end of exhaust system at wall 2			R609401	N	N
25380	ACTIVE	P	D229-00-2/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Hatton Cross Stn		Asbestos	Surveyed – Not Detected				Supalux					
24707	ACTIVE	P	D229-00-2/331/WAL-001	Wall: Internal - 1 - Mess Room - Station Building - Hatton Cross Stn	Other Boarding	Asbestos	Surveyed – Not Detected				LTB heater - 18"x12" board to back of heater					
5493	ACTIVE	P	D229-00-2/381	Store - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24709	ACTIVE	P	D229-00-2/381/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, rendered walls above false ceiling				Yes	
24708	ACTIVE	P	D229-00-2/381/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Hatton Cross Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
5494	ACTIVE	P	D229-00-2/413	CER - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25381	ACTIVE	P	D229-00-2/413/WAL-001	Wall: Internal - 1 - CER - Station Building - Hatton Cross Stn		Asbestos	Surveyed – Not Detected				Cable Sleeve - Bituminous paper					
5495	ACTIVE	P	D229-00-2/414	Yard - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D229-00 - Station Building - Hatton Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24796	ACTIVE	P	D229-00-2/414	Yard - Station Building - Hatton Cross Stn	Rope Seals	Asbestos	Strongly Presumed				Trackside Wall WB - 4 x Westinghouse Boxes		4			
24713	ACTIVE	P	D229-00-2/414	Yard - Station Building - Hatton Cross Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Wall to Invert WB side - 6 x cable sleeves in each - Encapsulated - no access		6			
24712	ACTIVE	P	D229-00-2/414	Yard - Station Building - Hatton Cross Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Wall to Invert EB side - 6 x cable sleeves in each - Encapsulated - no access		6			
24710	ACTIVE	P	D229-00-2/414	Yard - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Strongly Presumed				3m Visible x 20mmØ white braided cable from box on mezzanine gate		1			
24795	ACTIVE	P	D229-00-2/414	Yard - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Strongly Presumed				Trackside Wall WB - 2 x braided cables		2			
25382	ACTIVE	P	D229-00-2/414	Yard - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cable Run WB - 7 x braided cables		7			
24711	ACTIVE	P	D229-00-2/414	Yard - Station Building - Hatton Cross Stn	Westing house Boxes	Asbestos	Strongly Presumed				Wall by Invert EB side - Westinghouse Box & 2 x Green 40mmØ Cables		2			
44290	ACTIVE	P	D229-00-2/414	Yard - Station Building - Hatton Cross Stn	Control Panels	Asbestos	Presumed				Fan Control panel 1 no to low wall in front of metal platform			R609401	N	N
24714	ACTIVE	P	D229-00-2/414	Yard - Station Building - Hatton Cross Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cable Run EB - 14 x cables		14			
5496	ACTIVE	P	D229-00-2/416	Lobby - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5497	ACTIVE	P	D229-00-2/417	Lobby - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24798	ACTIVE	P	D229-00-2/417/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
24797	ACTIVE	P	D229-00-2/417/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Hatton Cross Stn		Asbestos	Surveyed – Not Detected				Supalux					
5498	ACTIVE	P	D229-00-2/418	Toilet: Female - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24799	ACTIVE	P	D229-00-2/418/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Hatton Cross Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
24800	ACTIVE	P	D229-00-2/418/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
5499	ACTIVE	P	D229-00-2/419	Toilet: Male - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D229-00 - Station Building - Hatton Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24803	ACTIVE	P	D229-00-2/419/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
24802	ACTIVE	P	D229-00-2/419/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Hatton Cross Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
24801	ACTIVE	P	D229-00-2/419/FLR-01	Floor - 1 - Toilet - Station Building - Hatton Cross Stn	Void	Asbestos	No Access: Presumed				Beneath Inspection Chamber					Yes
5500	ACTIVE	P	D229-00-2/661	Switch Room - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24807	ACTIVE	P	D229-00-2/661	Switch Room - Station Building - Hatton Cross Stn	Cable Duct: Other	Asbestos	Presumed				10 x Sealed Cable Ducts		10			
45287	INACTIVE	P	D229-00-2/661	Switch Room - Station Building - Hatton Cross Stn	Cable Duct: Other	Asbestos	Strongly Presumed				10no Sealed Cable Ducts - No Access		10		N	N
24679	ACTIVE	P	D229-00-2/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Hatton Cross Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch boxes Insulation within 4 x 60amp, 2 x30amp		4			
24315	ACTIVE	P	D229-00-2/661/WAL-002 80864619	Wall: Internal - 2 - Switch Room - Station Building - Hatton Cross Stn Wall: Internal	Other Boarding	Asbestos	Surveyed – Not Detected				2 x Suluminite panels		2			
45286	ACTIVE	P	D229-00-2/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Hatton Cross Stn	Other Boarding	Asbestos	Not Found during Inspection				2 x Suluminite panel		2		N	N
24806	INACTIVE	P	D229-00-2/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Hatton Cross Stn	Other Electrical Boxes	Asbestos	Known				Tunnel light electric box x 2		2			
24805	INACTIVE	P	D229-00-2/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Hatton Cross Stn	Other Electrical Boxes	Asbestos	Presumed				Automatic change over box		1			
24804	ACTIVE	P	D229-00-2/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Hatton Cross Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boxing					
24808	ACTIVE	P	D229-00-2/661/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Hatton Cross Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch boxes Insulation within - 2x 60amp		2			
5501	ACTIVE	P	D229-00-2/662	Switch Room - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24809	INACTIVE	P	D229-00-2/662/FLR-01	Floor - 1 - Switch Room - Station Building - Hatton Cross Stn	Other Electrical Boxes	Asbestos	Presumed				1x 8KVA transformer on the floor wall 1 and 2		1			



Hazardous Material Asset Register - Summary



D229-00 - Station Building - Hatton Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24810	ACTIVE	P	D229-00-2/662/WAL-001 80864631	Wall: Internal - 1 - Switch Room - Station Building - Hatton Cross Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box on floor		1			
25392	ACTIVE	P	D229-00-2/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Hatton Cross Stn	Other Electrical Boxes	Asbestos	Presumed				1x 8KVA transformer on the floor wall 2 and 3		1			
5502	ACTIVE	P	D229-00-2/663	Switch Room - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44289	ACTIVE	P	D229-00-2/663	Switch Room - Station Building - Hatton Cross Stn	Cable Duct: Other	Asbestos	Presumed				Floor ducts 3 no to floor under MCB box B			R609401	N	N
5503	ACTIVE	P	D229-00-2/664	Switch Room - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24812	ACTIVE	P	D229-00-2/664/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, rock wool, supalux boarding above false ceiling				Yes	
24811	ACTIVE	P	D229-00-2/664/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Hatton Cross Stn		Asbestos	Surveyed – Not Detected				(Part) Supalux Tiles					
5504	ACTIVE	P	D229-00-2/711	IMR - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46482	ACTIVE	P	D229-00-2/711	IMR - Station Building - Hatton Cross Stn	No Access	Asbestos	Strongly Presumed				Room requires full survey - the following is a note from 4Rails 2020 Re-Inspection of the adjoining room 2/712 Note 2/711 not surveyed and no info at all in this current PDF 2020 re-inspection. Lots of ACMs i.e tiles, composite boards, cables etc..within this room next to 2/712. (adjacent room).					
24813	ACTIVE	P	D229-00-2/711/CLG-01	Ceiling: Solid - 1 - IMR - Station Building - Hatton Cross Stn	Void	Asbestos	No Access: Presumed				No Access behind Metal Cladding				Yes	
5505	ACTIVE	P	D229-00-2/712	Relay Room - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24817	ACTIVE	P	D229-00-2/712	Relay Room - Station Building - Hatton Cross Stn	Other Electrical Boxes	Asbestos	Presumed				2 x Circuit Breakers		2			
24816	ACTIVE	P	D229-00-2/712	Relay Room - Station Building - Hatton Cross Stn	Other Boarding	Asbestos	Presumed				Various Paxoline Boards throughout room					
24818	ACTIVE	P	D229-00-2/712	Relay Room - Station Building - Hatton Cross Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Flashguards					



Hazardous Material Asset Register - Summary



D229-00 - Station Building - Hatton Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24814	ACTIVE	P	D229-00-2/712/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - Hatton Cross Stn	Void	Asbestos	No Access: Presumed				No access behind Metal Cladding				Yes	
24815	ACTIVE	P	D229-00-2/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Hatton Cross Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse Joint Boxes		1			
25469	ACTIVE	P	D229-00-2/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Hatton Cross Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse Joint Boxes		1			
5506	ACTIVE	P	D229-00-2/731	CER - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24903	ACTIVE	P	D229-00-2/731/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Hatton Cross Stn	Void	Asbestos	No Access: Presumed				No Access behind Metal Cladding				Yes	
24819	ACTIVE	P	D229-00-2/731/WAL-002	Wall: Internal - 2 - CER - Station Building - Hatton Cross Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding					
24904	ACTIVE	P	D229-00-2/731/WAL-003	Wall: Internal - 3 - CER - Station Building - Hatton Cross Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes - Insulation within 2 x 60amp		2			
24820	ACTIVE	P	D229-00-2/731/WAL-003	Wall: Internal - 3 - CER - Station Building - Hatton Cross Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding					
5507	ACTIVE	P	D229-00-2/732	Disused Room - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24905	ACTIVE	P	D229-00-2/732/CLG-01	Ceiling: Suspended - 1 - Disused Room - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
5508	ACTIVE	P	D229-00-2/761	Mess Room - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24908	ACTIVE	P	D229-00-2/761/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Hatton Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete vent ducts above false ceiling				Yes	
24907	ACTIVE	P	D229-00-2/761/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Hatton Cross Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
24906	ACTIVE	P	D229-00-2/761/FLR-01	Floor - 1 - Mess Room - Station Building - Hatton Cross Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Grey vinyl tiles					
5509	ACTIVE	P	D229-00-2/771	Pump Room - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24909	ACTIVE	P	D229-00-2/771/DOR-01	Door - 1 - Pump Room - Station Building - Hatton Cross Stn		Asbestos	Surveyed – Not Detected				Supalux Panel on bottom of Door front & back					



Hazardous Material Asset Register - Summary



D229-00 - Station Building - Hatton Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24681	ACTIVE	P	D229-00-2/771/WAL-004	Wall: Internal - 4 - Pump Room - Station Building - Hatton Cross Stn	Other Electrical Boxes	Asbestos	Presumed				1x Tencore box		1			
5510	ACTIVE	P	D229-00-2/772	Pump Room - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5511	ACTIVE	P	D229-00-A/411	Store - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46500	ACTIVE	P	D229-00-A/4111	Roof - Station Building - Hatton Cross Stn	Cement Cowlings/ Flues	Asbestos	Sampled – Not Detected				Concrete Cows to Roof 40+ - All same construction with terracotta flues within		40	R699501		
5512	ACTIVE	P	D229-00-A/576	Stairs: Linear - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5513	ACTIVE	P	D229-00-A/776	Fan Room - Station Building - Hatton Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42563	ACTIVE	P	D229-00-A/776	Fan Room - Station Building - Hatton Cross Stn	Rope Gaskets	Asbestos	Sampled – Not Detected				Rope gasket throughout to metal A/ C ducts – Direct impact to planned works – removal required			R498476	N	N
42565	ACTIVE	P	D229-00-A/776	Fan Room - Station Building - Hatton Cross Stn	Debris: Other	Asbestos	Sampled – Not Detected				Dust / debris throughout to floor on metal tiles			R498476	N	N
24912	ACTIVE	P	D229-00-A/776	Fan Room - Station Building - Hatton Cross Stn	Rope Gaskets	Asbestos	Known				Gaskets to Vent Equipment - Chrysotile					
42564	ACTIVE	P	D229-00-A/776	Fan Room - Station Building - Hatton Cross Stn		Asbestos	Room: Surveyed – No Known Asbestos				Metal ceiling tiles on metal framework (MMMMF to rear) to floor			R498476	N	N
42562	ACTIVE	P	D229-00-A/776	Fan Room - Station Building - Hatton Cross Stn	Gasket :Pipework	Asbestos	Sampled – Not Detected				Gaitors throughout to A/C metal			R498476	N	N

D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5514	ACTIVE	P	D233-00-1/071	Circulation Area - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24913	INACTIVE	P	D233-00-1/136/WAL-003	Wall: Internal - 3 - Lift Shaft - Station Building - Heathrow Terminals 123 Stn	Other Electrical Boxes	Asbestos	Removed				Within electrical componments of lift motor equipment - has since been removed.					
5515	ACTIVE	P	D233-00-1/151	UMC - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24914	ACTIVE	P	D233-00-1/151	UMC - Station Building - Heathrow Terminals 123 Stn	Lead/Leading	Lead Paint/Lead	Known				Vertical Pipe next to Door 1/151 (Top of Stairs 1/631, Corridor 2/236) - Red Gloss Paint. Lead Analysis: 3.04%					
5516	ACTIVE	P	D233-00-1/236	Passage - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42233	ACTIVE	P	D233-00-1/236	Passage - Station Building - Heathrow Terminals 123 Stn	Lead/Leading	Lead Paint/Lead	Known				Vertical piipe next to door 1/151 (top of stairs 1/631, corridor 2/236) Red gloss					
5517	ACTIVE	P	D233-00-1/237	Passage - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24915	ACTIVE	P	D233-00-1/237/FLR-01	Floor - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
24916	ACTIVE	P	D233-00-1/237/FLR-01	Floor - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Beneath Lino					Yes
5518	ACTIVE	P	D233-00-1/238	Passage - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5519	ACTIVE	P	D233-00-1/239	Disused Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5520	ACTIVE	P	D233-00-1/240	Passage - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5521	ACTIVE	P	D233-00-1/241	Lobby - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5522	ACTIVE	P	D233-00-1/242	Lobby - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24917	ACTIVE	P	D233-00-1/242	Lobby - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux white boarding high level					
24918	ACTIVE	P	D233-00-1/242/WAL-001	Wall: Internal - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Wall 1 & 2 high level Supalux panels					
5523	ACTIVE	P	D233-00-1/243	Passage - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5524	ACTIVE	P	D233-00-1/401	Tea Point - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25479	ACTIVE	P	D233-00-1/401/DOR-01	Door - 1 - Store - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Melamine with supalux boarding around door					
5525	ACTIVE	P	D233-00-1/631	Stairs: Linear - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24920	ACTIVE	P	D233-00-1/631	Stairs: Linear - Station Building - Heathrow Terminals 123 Stn	Lead/Leading	Lead Paint/Lead	Known				Horizontal pipe under stairs - Red Gloss Paint. Lead Analysis: 1.83%					
24919	ACTIVE	P	D233-00-1/631	Stairs: Linear - Station Building - Heathrow Terminals 123 Stn	Lead/Leading	Lead Paint/Lead	Known				Horizontal Pipe with Pressure Gauge top of stairs - Red Gloss Paint. Lead Analysis: 0.429%					
5526	ACTIVE	P	D233-00-1/661	Switch Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24923	ACTIVE	P	D233-00-1/661/FLR-01	Floor - 1 - Switch Room - Station Building - Heathrow Terminals 123 Stn	Other Electrical Boxes	Asbestos	Presumed				1 x 6KVA - Wall 3 floor No asbestos within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within		1			
24922	ACTIVE	P	D233-00-1/661/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Heathrow Terminals 123 Stn	Isolator Switches	Asbestos	Removed				1 x red spot fuse board No asbestos within		1			
24921	ACTIVE	P	D233-00-1/661/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Heathrow Terminals 123 Stn	Isolator Switches	Asbestos	Presumed				1x 30amp Iron clad isolator Removed by Econ ES1524o 2020 re-inspection claims items still present No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
5527	ACTIVE	P	D233-00-1/761	SVC - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5528	ACTIVE	P	D233-00-2/001	Booking Hall - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25480	ACTIVE	P	D233-00-2/001	Booking Hall - Station Building - Heathrow Terminals 123 Stn	Other Boarding	Asbestos	Presumed				Metal surround on escalator walls (walls of melamine back onto wood then brick behind) - Board behind - needs to remove metal to sample					
24924	ACTIVE	P	D233-00-2/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard, plastic cables, metal trunking above false ceiling				Yes	
5529	ACTIVE	P	D233-00-2/011	Ticket Office - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24927	ACTIVE	P	D233-00-2/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, marine ply - brick, plaster, plastic cable, air con above false ceiling				Yes	
24926	ACTIVE	P	D233-00-2/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
24925	ACTIVE	P	D233-00-2/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, plastic cable, supalux board and debris beneath computer flooring					Yes
25481	ACTIVE	P	D233-00-2/011/WAL-002	Wall: Internal - 2 - Ticket Office - Station Building - Heathrow Terminals 123 Stn		Asbestos	Sampled – Not Detected				Supalux Boxing - Ticket Hall side					
25009	ACTIVE	P	D233-00-2/011/WAL-003	Wall: Internal - 3 - Ticket Office - Station Building - Heathrow Terminals 123 Stn		Asbestos	Sampled – Not Detected				Supalux Boxing - Ticket Hall side					
5530	ACTIVE	P	D233-00-2/012	Ticket Office - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25010	ACTIVE	P	D233-00-2/012	Ticket Office - Station Building - Heathrow Terminals 123 Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - new build					
5531	ACTIVE	P	D233-00-2/021	POM - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25013	ACTIVE	P	D233-00-2/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, plastic cable, trunking, supalux debris, above false ceiling				Yes	
25011	ACTIVE	P	D233-00-2/021/FLR-01	Floor - 1 - POM - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, plastic cable, trunking, supalux debris beneath computer flooring					Yes
25012	ACTIVE	P	D233-00-2/021/WAL-001	Wall: Internal - 1 - POM - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding					
5532	ACTIVE	P	D233-00-2/022	POM - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25017	ACTIVE	P	D233-00-2/022/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, plastic cable, air con, supalux pads above aircon wall 4 above false ceiling				Yes	
24322	ACTIVE	P	D233-00-2/022/FLR-01	Floor - 1 - POM - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, plastic cable beneath computer flooring					Yes
25014	ACTIVE	P	D233-00-2/022/WAL-002	Wall: Internal - 2 - POM - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux - high level boarding at top					



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25016	ACTIVE	P	D233-00-2/022/WAL-003	Wall: Internal - 3 - POM - Station Building - Heathrow Terminals 123 Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard panel					
25015	ACTIVE	P	D233-00-2/022/WAL-004	Wall: Internal - 4 - POM - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				High level boarding at top, Supalux panel					
5533	ACTIVE	P	D233-00-2/031	Mess Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Surveyed – Asbestos Known									
25021	ACTIVE	P	D233-00-2/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Brick, concrete, air con, plastic cables, rock wool lagging above metal grille tiles				Yes	
25022	ACTIVE	P	D233-00-2/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Heathrow Terminals 123 Stn	Boarding: AIB	Asbestos	Known				4m² AIB Panel - On top of metal sheeting in ceiling (kitchen area)					
25716	ACTIVE	P	D233-00-2/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				No access above false ceiling					
25018	ACTIVE	P	D233-00-2/031/FLR-01	Floor - 1 - Mess Room - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, conduits, plastic cable beneath computer flooring					Yes
25019	ACTIVE	P	D233-00-2/031/WAL-007	Wall: Internal - 7 - Mess Room - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux boarding					
25020	ACTIVE	P	D233-00-2/031/WAL-008	Wall: Internal - 8 - Mess Room - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux board and debris					
5534	ACTIVE	P	D233-00-2/036	Toilet: Unisex - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25489	ACTIVE	P	D233-00-2/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
25023	ACTIVE	P	D233-00-2/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Brick, breeze block, air con, rock wool lagging, plastic cable above false ceiling				Yes	
25024	ACTIVE	P	D233-00-2/036/UNL-01	Urinal - 1 - Toilet - Station Building - Heathrow Terminals 123 Stn	Lead/Leading	Lead Paint/Lead	Known				Toilet - green gloss - 2m long. Thickness : 0.16m Analysis : 9.31%					
69354	ACTIVE	P	D233-00-2/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				No identified ACMs above false ceiling			R679633		
5535	ACTIVE	P	D233-00-2/091	Circulation Area - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25490	INACTIVE	P	D233-00-2/091/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Bus Station Side (within bulkhead/ void area only) - above Concrete slab, MMMF Insulation, plasterboard, plastic cables				Yes	
25025	ACTIVE	P	D233-00-2/091/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Above metal ceiling				Yes	
25026	INACTIVE	P	D233-00-2/091/FLR-01	Floor - 1 - Circulation Area - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Bus Station Side (within bulkhead/ void area only) - beneath MMMF Insulation, plastic cables					Yes
5536	ACTIVE	P	D233-00-2/092	Circulation Area - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24117	ACTIVE	P	D233-00-2/092	Circulation Area - Station Building - Heathrow Terminals 123 Stn	Mastic	Asbestos	Known				Asbestos mastic / gaskets to flanged ventilation ducting - Red Jointed Areas - Encapsulated					
25028	ACTIVE	P	D233-00-2/092	Circulation Area - Station Building - Heathrow Terminals 123 Stn	Mastic	Asbestos	Known				Encapsulated 12/11/2011 - Asbestos gaskets to flanged high level ventilation ducting - Chrysotile. Duplicate of 24117????					
45288	INACTIVE	P	D233-00-2/092	Circulation Area - Station Building - Heathrow Terminals 123 Stn	Mastic	Asbestos	Known				Mastic to flanges - Encapsulated				N	N
25027	ACTIVE	P	D233-00-2/092/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Above metal ceiling Area surveyed as part of SMEP?				Yes	
5537	ACTIVE	P	D233-00-2/093	Circulation Area - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25029	ACTIVE	P	D233-00-2/093/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Fibreglass, metal trunking, concrete, plastic cables above metal ceiling				Yes	
5538	ACTIVE	P	D233-00-2/111	Circulation Area - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25032	ACTIVE	P	D233-00-2/111	Circulation Area - Station Building - Heathrow Terminals 123 Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel boarding behind heater					
25031	INACTIVE	P	D233-00-2/111/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Above acoustic tiles				Yes	
69353	ACTIVE	P	D233-00-2/111/CLG-02	Ceiling: Suspended - 1 - Circulation Area - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				No identified ACMs above false ceiling			R679633		



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25030	ACTIVE	P	D233-00-2/111/FLR-01	Floor - 1 - Circulation Area - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Beneath carpet					Yes
25118	INACTIVE	P	D233-00-2/111/WAL-001	Wall: Internal - 1 - Circulation Area - Station Building - Heathrow Terminals 123 Stn	LUL Heaters	Asbestos	Removed				1 x LTB Heater - Removed ny EMS Group 10/06/2010					
25033	INACTIVE	P	D233-00-2/111/WAL-004	Wall: Internal - 4 - Circulation Area - Station Building - Heathrow Terminals 123 Stn	LUL Heaters	Asbestos	Removed				2 x LTB Heater- Removed					
5539	ACTIVE	P	D233-00-2/112	Store - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25121	INACTIVE	P	D233-00-2/112/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Above metal ceiling				Yes	
69357	ACTIVE	P	D233-00-2/112/CLG-02	Ceiling: Suspended - 1 - Store - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				No identified ACMs above false ceiling			R679633		
25119	ACTIVE	P	D233-00-2/112/FLR-01	Floor - 1 - Store - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
25120	ACTIVE	P	D233-00-2/112/FLR-01	Floor - 1 - Store - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Beneath Lino					Yes
5540	ACTIVE	P	D233-00-2/113	Office - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25123	ACTIVE	P	D233-00-2/113/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Acoustic panels				Yes	
25124	ACTIVE	P	D233-00-2/113/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete & fibreglass lagging above acoustic panels				Yes	
25122	ACTIVE	P	D233-00-2/113/FLR-01	Floor - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Beneath carpet					Yes
5541	ACTIVE	P	D233-00-2/117	Mess Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25128	ACTIVE	P	D233-00-2/117	Mess Room - Station Building - Heathrow Terminals 123 Stn	Boarding: AIB	Asbestos	Known				6m² AIB panel on top of metal sheeting (to ceiling kitchen area)					
25127	INACTIVE	P	D233-00-2/117/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Above metal ceiling				Yes	



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
69358	ACTIVE	P	D233-00-2/117/CLG-02	Ceiling: Suspended - 1 - Mess Room - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				No identified ACMs above false ceiling			R679633		
25126	ACTIVE	P	D233-00-2/117/FLR-01	Floor - 1 - Mess Room - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Beneath Lino					Yes
25125	ACTIVE	P	D233-00-2/117/FLR-01	Floor - 1 - Mess Room - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino, Tiles					
25864	ACTIVE	P	D233-00-2/136	Lift Shaft - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				New Room					
25863	ACTIVE	P	D233-00-2/136	Lift Shaft - Station Building - Heathrow Terminals 123 Stn		Asbestos	Room: Surveyed – No Known Asbestos				New Construction					
25865	ACTIVE	P	D233-00-2/137	Lift Shaft - Station Building - Heathrow Terminals 123 Stn		Asbestos	Room: Surveyed – No Known Asbestos				Not Surveyed - New Asset					
25866	ACTIVE	P	D233-00-2/137	Lift Shaft - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Not surveyed - New Assets					
5542	ACTIVE	P	D233-00-2/236	Passage - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25131	ACTIVE	P	D233-00-2/236	Passage - Station Building - Heathrow Terminals 123 Stn	Lead/Leading	Lead Paint/Lead	Known				Pipe - red gloss - 7m². Thickness : 0.15mm Analysis : 2.48%					
25129	ACTIVE	P	D233-00-2/236/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux Boxing					
25130	ACTIVE	P	D233-00-2/236/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
5543	ACTIVE	P	D233-00-2/237	Passage - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25133	ACTIVE	P	D233-00-2/237/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Above Supalux				Yes	
25132	ACTIVE	P	D233-00-2/237/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux & concrete					
5544	ACTIVE	P	D233-00-2/239	Passage - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25135	ACTIVE	P	D233-00-2/239	Passage - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux panel above door					



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25580	ACTIVE	P	D233-00-2/239/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, conduit, metal cables above metal ceiling				Yes	
25134	ACTIVE	P	D233-00-2/239/FLR-01	Floor - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				25LM Marley tiles (green)					
5545	ACTIVE	P	D233-00-2/240	Passage - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5546	ACTIVE	P	D233-00-2/241	Passage - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25138	ACTIVE	P	D233-00-2/241	Passage - Station Building - Heathrow Terminals 123 Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Foam panel in heater					
24422	ACTIVE	P	D233-00-2/241/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
25137	ACTIVE	P	D233-00-2/241/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Brick copper pipes, galvanised ductwork, plastic cables, fibreglass packing to feed through on walls - above supalux ceiling				Yes	
25136	ACTIVE	P	D233-00-2/241/WAL-003	Wall: Internal - 3 - Passage - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux boarding					
5547	ACTIVE	P	D233-00-2/242	Passage - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25581	ACTIVE	P	D233-00-2/242/FLR-01	Floor - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				24m² Vinyl floor					
25139	ACTIVE	P	D233-00-2/242/WAL-003	Wall: Internal - 3 - Passage - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding					
25140	ACTIVE	P	D233-00-2/242/WAL-003	Wall: Internal - 3 - Passage - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, metal air con unit, fibre glass lagging with aluminium foil, plastic cables above metal ceiling				Yes	
5548	ACTIVE	P	D233-00-2/243	Lobby - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25142	ACTIVE	P	D233-00-2/243/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Metal sill jamming panels in concrete, fibreglass in plastic bags, metal pipes & trunking above metal ceiling				Yes	
25141	ACTIVE	P	D233-00-2/243/FLR-01	Floor - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				12m² Vinyl floor					



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5549	ACTIVE	P	D233-00-2/244	Passage - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25143	ACTIVE	P	D233-00-2/244/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Above metal ceiling				Yes	
5550	ACTIVE	P	D233-00-2/245	Stairs: Linear - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25218	ACTIVE	P	D233-00-2/245/CLG-01	Ceiling: Suspended - 1 - Linear Stairs - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Downstairs - Supalux, Supalux Boxing					
25582	ACTIVE	P	D233-00-2/245/CLG-01	Ceiling: Suspended - 1 - Linear Stairs - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above metal ceiling				Yes	
25219	ACTIVE	P	D233-00-2/245/CLG-01	Ceiling: Suspended - 1 - Linear Stairs - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Above false ceiling				Yes	
5551	ACTIVE	P	D233-00-2/246	Lobby - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25221	ACTIVE	P	D233-00-2/246/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, fibreglass in plastic bags, metal ductwork, plastic cables above metal ceiling				Yes	
25220	ACTIVE	P	D233-00-2/246/FLR-01	Floor - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				12m² Vinyl floor					
5552	ACTIVE	P	D233-00-2/247	Lobby - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25223	ACTIVE	P	D233-00-2/247/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
25224	ACTIVE	P	D233-00-2/247/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, plastic cable, conduits above false ceiling				Yes	
25222	ACTIVE	P	D233-00-2/247/FLR-01	Floor - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				8m Marley tile (brown/grey)					
5553	ACTIVE	P	D233-00-2/248	Toilet: Unisex - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25225	ACTIVE	P	D233-00-2/248	Toilet: Unisex - Station Building - Heathrow Terminals 123 Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5554	ACTIVE	P	D233-00-2/249	Passage - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24424	ACTIVE	P	D233-00-2/249/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Plastic cables, brickwork, metal pipework above metal ceiling				Yes	
25228	ACTIVE	P	D233-00-2/249/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Cable Duct: Other	Asbestos	Presumed				Ducts above false ceiling					
25226	ACTIVE	P	D233-00-2/249/FLR-01	Floor - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				6m² Vinyl					
25227	ACTIVE	P	D233-00-2/249/WAL-001	Wall: Internal - 1 - Passage - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux panel					
5555	ACTIVE	P	D233-00-2/252	Passage - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25231	ACTIVE	P	D233-00-2/252/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Above metal strips				Yes	
25229	ACTIVE	P	D233-00-2/252/FLR-01	Floor - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Beneath Computer flooring					Yes
25230	ACTIVE	P	D233-00-2/252/WAL-004	Wall: Internal - 4 - Passage - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux boarding					
5556	ACTIVE	P	D233-00-2/311	Office - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25233	ACTIVE	P	D233-00-2/311/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Above metal ceiling				Yes	
25232	ACTIVE	P	D233-00-2/311/FLR-01	Floor - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Beneath Computer flooring					Yes
5557	ACTIVE	P	D233-00-2/316	Locker Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25237	ACTIVE	P	D233-00-2/316/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Heathrow Terminals 123 Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Hose reel cupboard behind 2/316 -					
25235	ACTIVE	P	D233-00-2/316/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25238	ACTIVE	P	D233-00-2/316/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Above plasterboard				Yes	
25236	ACTIVE	P	D233-00-2/316/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
25589	ACTIVE	P	D233-00-2/316/FLR-01	Floor - 1 - Locker Room - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Beneath Lino					Yes
25234	ACTIVE	P	D233-00-2/316/FLR-01	Floor - 1 - Locker Room - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
5558	ACTIVE	P	D233-00-2/341	Mess Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25591	ACTIVE	P	D233-00-2/341	Mess Room - Station Building - Heathrow Terminals 123 Stn	Boarding: AIB	Asbestos	Known				2m² AIB panel on top of metal sheeting to ceiling (in kitchen area)					
25242	ACTIVE	P	D233-00-2/341	Mess Room - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux boarding above door, Melamine panel on wood					
25240	ACTIVE	P	D233-00-2/341/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
25241	ACTIVE	P	D233-00-2/341/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, galvanised ductwork, fibreglass lagging, plastic cables above false ceiling				Yes	
25590	ACTIVE	P	D233-00-2/341/FLR-01	Floor - 1 - Mess Room - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				4m² vinyl floor tile					
25239	ACTIVE	P	D233-00-2/341/FLR-02	Floor - 2 - Mess Room - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				4m² vinyl floor tile					
5559	ACTIVE	P	D233-00-2/349	Stairs: Linear - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25243	ACTIVE	P	D233-00-2/349/CLG-01	Ceiling: Suspended - 1 - Linear Stairs - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
25319	ACTIVE	P	D233-00-2/349/CLG-01	Ceiling: Suspended - 1 - Linear Stairs - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux				Yes	
5560	ACTIVE	P	D233-00-2/406	Plant Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25320	ACTIVE	P	D233-00-2/406	Plant Room - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux white boarding in small passage,					
5561	ACTIVE	P	D233-00-2/411	Store - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25322	INACTIVE	P	D233-00-2/411/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Above metal ceiling				Yes	
69352	ACTIVE	P	D233-00-2/411/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				No identified ACMs above false ceiling			R679633		
25321	ACTIVE	P	D233-00-2/411/FLR-01	Floor - 1 - Store - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Beneath Computer flooring					Yes
5562	ACTIVE	P	D233-00-2/412	Store - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25324	ACTIVE	P	D233-00-2/412/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, plastic cables trunking above metal ceiling				Yes	
25323	ACTIVE	P	D233-00-2/412/FLR-01	Floor - 1 - Store - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, plastic cables trunking beneath computer flooring					Yes
5563	ACTIVE	P	D233-00-2/413	Store - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25325	ACTIVE	P	D233-00-2/413/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above metal ceiling				Yes	
5564	ACTIVE	P	D233-00-2/416	Toilet: Female - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25326	ACTIVE	P	D233-00-2/416	Toilet: Female - Station Building - Heathrow Terminals 123 Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
5565	ACTIVE	P	D233-00-2/417	Lobby - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25328	ACTIVE	P	D233-00-2/417/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Brick, cast iron pipe, metal trunking, plastic cables above supalux ceiling				Yes	
25327	ACTIVE	P	D233-00-2/417/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5566	ACTIVE	P	D233-00-2/418	Lobby - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25330	ACTIVE	P	D233-00-2/418/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above supalux ceiling				Yes	
25329	ACTIVE	P	D233-00-2/418/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
5567	ACTIVE	P	D233-00-2/419	Toilet: Male - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25331	ACTIVE	P	D233-00-2/419/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, copper pipes, plastic cable above metal ceiling				Yes	
5568	ACTIVE	P	D233-00-2/420	Toilet: Female - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25332	ACTIVE	P	D233-00-2/420/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, copper pipes, plastic cable above metal ceiling				Yes	
5569	ACTIVE	P	D233-00-2/421	Toilet: Male - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25333	ACTIVE	P	D233-00-2/421/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
25334	ACTIVE	P	D233-00-2/421/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above supalux ceiling				Yes	
24426	ACTIVE	P	D233-00-2/421/WAL-004	Wall: Internal - 4 - Toilet - Station Building - Heathrow Terminals 123 Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LUL heater - foam					
5570	ACTIVE	P	D233-00-2/422	Toilet: Unisex - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25336	ACTIVE	P	D233-00-2/422/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Metal duct & concrete above supalux ceiling				Yes	
24108	ACTIVE	P	D233-00-2/422/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Heathrow Terminals 123 Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LUL heater - foam					
25335	ACTIVE	P	D233-00-2/422/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5571	ACTIVE	P	D233-00-2/451	Tenancy - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5572	ACTIVE	P	D233-00-2/452	Office - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25340	ACTIVE	P	D233-00-2/452	Office - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux boarding under counter					
25339	ACTIVE	P	D233-00-2/452/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
24109	ACTIVE	P	D233-00-2/452/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux above grid					
25337	ACTIVE	P	D233-00-2/452/FLR-01	Floor - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
25338	ACTIVE	P	D233-00-2/452/FLR-01	Floor - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Beneath Lino					Yes
25342	ACTIVE	P	D233-00-2/452/WAL-002	Wall: Internal - 2 - Office - Station Building - Heathrow Terminals 123 Stn	Cable Duct: Other	Asbestos	No Access: Presumed				Cable ducts on wall 2 & 4, buried in floor No access below floor					
25341	ACTIVE	P	D233-00-2/452/WAL-002	Wall: Internal - 2 - Office - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux boarding					
5573	ACTIVE	P	D233-00-2/454	Tenancy - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5574	ACTIVE	P	D233-00-2/455	Tenancy - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5575	ACTIVE	P	D233-00-2/456	Tenancy - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5576	ACTIVE	P	D233-00-2/661	Service Riser - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5577	ACTIVE	P	D233-00-2/663	Switch Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25418	ACTIVE	P	D233-00-2/663/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Heathrow Terminals 123 Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 30 amp combination fuse switch + 3no Transformer Boxes No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
25344	ACTIVE	P	D233-00-2/663/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Heathrow Terminals 123 Stn	Isolator Switches	Asbestos	Strongly Presumed				8 x combination fuse switches - 5 x 60amp, 1 x 100amp, 2 x 30amp No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		8			
25343	ACTIVE	P	D233-00-2/663/WAL-004 80866006	Wall: Internal - 4 - Switch Room - Station Building - Heathrow Terminals 123 Stn Wall: Internal	Other Electrical Boxes	Asbestos	Strongly Presumed				3x 6KVA transformer plus switch box 1x30 No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		3			
24110	ACTIVE	P	D233-00-2/663/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Heathrow Terminals 123 Stn	Cable Duct: Other	Asbestos	Presumed				Cable ducts on wall 2 & 4, buried in floor					
5578	ACTIVE	P	D233-00-2/664	Switch Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25420	ACTIVE	P	D233-00-2/664/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Above false ceiling				Yes	
25419	ACTIVE	P	D233-00-2/664/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux boarding					
25421	ACTIVE	P	D233-00-2/664/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminals 123 Stn	Isolator Switches	Asbestos	Presumed				1x Iron clad isolator No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
5579	ACTIVE	P	D233-00-2/665	Switch Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25422	ACTIVE	P	D233-00-2/665/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminals 123 Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 100amp Switch Box No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
5580	INACTIVE	P	D233-00-2/666	Disused Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos				Re-Inspection 04/09/2014					
25423	ACTIVE	P	D233-00-2/666	Disused Room - Station Building - Heathrow Terminals 123 Stn	No Access	Asbestos	Room: Surveyed – No Known Asbestos				Re-Inspection 04 Sept 2014					



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5581	ACTIVE	P	D233-00-2/667	Switch Cupboard - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25424	INACTIVE	P	D233-00-2/667	Switch Cupboard - Station Building - Heathrow Terminals 123 Stn	No Access	Asbestos	Surveyed – Not Detected				Not surveyed					
5582	ACTIVE	P	D233-00-2/668	Switch Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5583	ACTIVE	P	D233-00-2/669	Cupboard - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5584	ACTIVE	P	D233-00-2/751	Station Control Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25429	ACTIVE	P	D233-00-2/751/CLG-01	Ceiling: Suspended - 1 - Station Control Room - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
25431	ACTIVE	P	D233-00-2/751/CLG-01	Ceiling: Suspended - 1 - Station Control Room - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Brick wall, concrete ceiling, plastic cables, conduit metal, galvanised, ductwork, brickwork above false ceiling				Yes	
25430	ACTIVE	P	D233-00-2/751/CLG-02	Ceiling: Suspended - 2 - Station Control Room - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
25432	ACTIVE	P	D233-00-2/751/CLG-02	Ceiling: Suspended - 2 - Station Control Room - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Brick wall, concrete ceiling, plastic cables, conduit metal, galvanised, ductwork, brickwork above false ceiling				Yes	
25427	ACTIVE	P	D233-00-2/751/FLR-01	Floor - 1 - Station Control Room - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Beneath Lino					Yes
25425	ACTIVE	P	D233-00-2/751/FLR-01	Floor - 1 - Station Control Room - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
25426	ACTIVE	P	D233-00-2/751/FLR-02	Floor - 2 - Station Control Room - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
25428	ACTIVE	P	D233-00-2/751/FLR-02	Floor - 2 - Station Control Room - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Beneath Lino					Yes
5585	ACTIVE	P	D233-00-2/776	Store - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5586	ACTIVE	P	D233-00-2/781	Mess Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25435	ACTIVE	P	D233-00-2/781/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
25434	ACTIVE	P	D233-00-2/781/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
25433	ACTIVE	P	D233-00-2/781/FLR-01	Floor - 1 - Mess Room - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Presumed				Marley Tiles Not within scope as this is the substation mess room - no access 2020 re-inspection					
45289	ACTIVE	P	D233-00-2/782	Substation Room - Station Building - Heathrow Terminals 123 Stn	Other Electrical Boxes	Asbestos	No Access: Presumed				All electrical switchs strongly presumed to contain asbestos				N	N
5587	ACTIVE	P	D233-00-2/783	Service Riser - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5588	ACTIVE	P	D233-00-2/784	Service Riser - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25437	ACTIVE	P	D233-00-2/784	Service Riser - Station Building - Heathrow Terminals 123 Stn	Other Boarding	Asbestos	Surveyed – Not Detected				White boarding vent, beneath duct - plasterboard					
25436	ACTIVE	P	D233-00-2/784	Service Riser - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				White boxing - Supalux					
24116	ACTIVE	P	D233-00-2/784/FLR-01	Floor - 1 - Service Riser - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux Debris					
5589	ACTIVE	P	D233-00-2/786	Service Riser - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25438	ACTIVE	P	D233-00-2/791/FLR-01	Floor - 1 - Vent Shaft - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Beneath floor					Yes
25439	ACTIVE	P	D233-00-2/792	Vent Shaft - Station Building - Heathrow Terminals 123 Stn	No Access	Asbestos	Room: Surveyed – No Known Asbestos				Re Inspection 04 Sept 2014					
24410	ACTIVE	P	D233-00-2/793	Vent Shaft - Station Building - Heathrow Terminals 123 Stn	No Access	Asbestos	No Access: Presumed				Not surveyed					
69356	ACTIVE	P	D233-00-2/801	Office - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Surveyed – Not Detected				No identified ACMs			R679633		
5590	INACTIVE	P	D233-00-2/801	Office - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5591	ACTIVE	P	D233-00-2/802	Office - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
69355	ACTIVE	P	D233-00-2/802/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				No identified ACMs above false ceiling			R679633		
5592	ACTIVE	P	D233-00-2/901	Plant Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5593	ACTIVE	P	D233-00-2/902	Tenancy - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5594	ACTIVE	P	D233-00-2/903	Equipment Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5595	ACTIVE	P	D233-00-2/904	Disused Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25441	ACTIVE	P	D233-00-2/904/CLG-01	Ceiling: Suspended - 1 - Disused Room - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Above false ceiling				Yes	
25440	ACTIVE	P	D233-00-2/904/CLG-01	Ceiling: Suspended - 1 - Disused Room - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
5596	ACTIVE	P	D233-00-2/905	Tenancy - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5597	ACTIVE	P	D233-00-2/954	Tenancy - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5598	ACTIVE	P	D233-00-3/053	Office - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25443	ACTIVE	P	D233-00-3/053	Office - Station Building - Heathrow Terminals 123 Stn	Boarding: AIB	Asbestos	Known				8m² AIB Panel on top of metal sheeting (above false ceiling in kitchen area)				Y	
24118	ACTIVE	P	D233-00-3/053/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Above false ceiling				Yes	
25442	ACTIVE	P	D233-00-3/053/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
5599	ACTIVE	P	D233-00-3/081	Lobby - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5600	ACTIVE	P	D233-00-3/113	Office - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25519	ACTIVE	P	D233-00-3/113/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
25518	ACTIVE	P	D233-00-3/113/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
25444	ACTIVE	P	D233-00-3/113/FLR-01	Floor - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				40m Marley tile (green) on solid					
5601	ACTIVE	P	D233-00-3/114	Office - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25521	ACTIVE	P	D233-00-3/114/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
25522	ACTIVE	P	D233-00-3/114/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, AC trunking, rope, copper pipes, drip tray, plastic cable above false ceiling				Yes	
25520	ACTIVE	P	D233-00-3/114/FLR-01	Floor - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				16m Green marley tiles					
5602	ACTIVE	P	D233-00-3/115	Store - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25526	ACTIVE	P	D233-00-3/115/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
25525	ACTIVE	P	D233-00-3/115/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
25523	ACTIVE	P	D233-00-3/115/FLR-01	Floor - 1 - Store - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				16m Marley tile (green) on solid					
25524	ACTIVE	P	D233-00-3/115/WAL-002	Wall: Internal - 2 - Store - Station Building - Heathrow Terminals 123 Stn	LUL Heaters	Asbestos	Surveyed – Not Detected						1			
5603	ACTIVE	P	D233-00-3/116	Office - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25529	ACTIVE	P	D233-00-3/116/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Concrete, plastic cables, Conduit, all putty/mastic to slip joint ventilation ducting above false ceiling				Yes	



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25528	ACTIVE	P	D233-00-3/116/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
25527	ACTIVE	P	D233-00-3/116/FLR-01	Floor - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				16m Marley tile (green)					
5604	ACTIVE	P	D233-00-3/131	LMR - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25531	ACTIVE	P	D233-00-3/131	LMR - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Surround around door supalux boarding , supalux panel above door					
25534	INACTIVE	P	D233-00-3/131/WAL-001	Wall: Internal - 1 - LMR - Station Building - Heathrow Terminals 123 Stn	Other Electrical Boxes	Asbestos	Removed				1 x Change over unit Removed by Econ ES5328 (25/07/2013)		1			
24412	INACTIVE	P	D233-00-3/131/WAL-001	Wall: Internal - 1 - LMR - Station Building - Heathrow Terminals 123 Stn	Isolator Switches	Asbestos	Removed				4 x Switch fuse boxes Removed by Econ ES5328 (25/07/2013)		4			
25533	INACTIVE	P	D233-00-3/131/WAL-001	Wall: Internal - 1 - LMR - Station Building - Heathrow Terminals 123 Stn	Isolator Switches	Asbestos	Removed				2 x red spot fuse board Removed by Econ ES5328 (25/07/2013)		2			
25535	INACTIVE	P	D233-00-3/131/WAL-003	Wall: Internal - 3 - LMR - Station Building - Heathrow Terminals 123 Stn	Other Electrical Boxes	Asbestos	Removed				1x Ring master box (motor equipment) Removed by Econ ES5328 (25/07/2013)		1			
25532	INACTIVE	P	D233-00-3/131/WAL-003	Wall: Internal - 3 - LMR - Station Building - Heathrow Terminals 123 Stn		Asbestos	Removed				Within woven cable insulation low level Removed by Econ ES5328 (25/07/2013)					
25530	ACTIVE	P	D233-00-3/131/WAL-003	Wall: Internal - 3 - LMR - Station Building - Heathrow Terminals 123 Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel boarding					
25536	INACTIVE	P	D233-00-3/131/WAL-004	Wall: Internal - 4 - LMR - Station Building - Heathrow Terminals 123 Stn	Other Electrical Boxes	Asbestos	Removed				1x Red spot fuse board Removed by Econ ES5328 (25/07/2013)		1			
24122	INACTIVE	P	D233-00-3/131/WAL-004	Wall: Internal - 4 - LMR - Station Building - Heathrow Terminals 123 Stn	Isolator Switches	Asbestos	Removed				1x Combination switch box Removed by Econ ES5328 (25/07/2013)		1			
5605	ACTIVE	P	D233-00-3/132	LMR - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5606	ACTIVE	P	D233-00-3/151	UMC - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25250	ACTIVE	P	D233-00-3/151	UMC - Station Building - Heathrow Terminals 123 Stn	Lead/Leading	Lead Paint/Lead	Known				Escalator machine chamber - red gloss - 3m². Thickness : 0.20mm Analysis : 1.55%					



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25537	ACTIVE	P	D233-00-3/151	UMC - Station Building - Heathrow Terminals 123 Stn	Lead/Leading	Lead Paint/Lead	Presumed				Metal Steps to right hand side & metal handrail - Red Gloss. Lead Analysis: 1.324%					
5607	ACTIVE	P	D233-00-3/152	UMC - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25251	ACTIVE	P	D233-00-3/152	UMC - Station Building - Heathrow Terminals 123 Stn	Lead/Leading	Lead Paint/Lead	Known				Escalator machine chamber - red gloss - 3m². Thickness : 0.20mm Analysis : 1.55%					
25540	ACTIVE	P	D233-00-3/152	UMC - Station Building - Heathrow Terminals 123 Stn	Lead/Leading	Lead Paint/Lead	Known				Red Gloss					
25538	ACTIVE	P	D233-00-3/152/ WAL-001	Wall: Internal - 1 - UMC - Station Building - Heathrow Terminals 123 Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
25539	ACTIVE	P	D233-00-3/152/ WAL-003	Wall: Internal - 3 - UMC - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Upstairs - Supalux boarding					
5608	ACTIVE	P	D233-00-3/161	LMC - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5609	ACTIVE	P	D233-00-3/236	Passage - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25542	ACTIVE	P	D233-00-3/236/ CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
25543	ACTIVE	P	D233-00-3/236/ CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
24123	ACTIVE	P	D233-00-3/236/ FLR-01	Floor - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				2m² Tiles Lino (by 3/244)					
25541	ACTIVE	P	D233-00-3/236/ WAL-001	Wall: Internal - 1 - Passage - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux Boxing					
5610	ACTIVE	P	D233-00-3/237	Passage - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5611	ACTIVE	P	D233-00-3/238	Passage - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25618	ACTIVE	P	D233-00-3/238/ CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux tiles, Supalux boxing					



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn																
Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25619	ACTIVE	P	D233-00-3/238/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	No Access	Asbestos	No Access: Presumed				Above false ceiling					
25620	ACTIVE	P	D233-00-3/238/CLG-02	Ceiling: Solid - 2 - Passage - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux tiles, Supalux boxing					
25621	ACTIVE	P	D233-00-3/238/CLG-02	Ceiling: Solid - 2 - Passage - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Above false ceiling					
5612	ACTIVE	P	D233-00-3/239	Passage - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25623	ACTIVE	P	D233-00-3/239/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
25622	ACTIVE	P	D233-00-3/239/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux boxing					
5613	ACTIVE	P	D233-00-3/240	Passage - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25626	ACTIVE	P	D233-00-3/240/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, plastic cables, pipe, conduits above false ceiling				Yes	
25625	ACTIVE	P	D233-00-3/240/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
25624	ACTIVE	P	D233-00-3/240/FLR-01	Floor - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				12m Marley tiles (brown/grey)					
5614	ACTIVE	P	D233-00-3/243	Passage - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25629	ACTIVE	P	D233-00-3/243	Passage - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux boarding all along 12x Cable sleeves - left hand side, end, Supalux boarding around vent duct,					
25630	ACTIVE	P	D233-00-3/243/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Cable Duct: Other	Asbestos	No Access: Presumed				Cable sleeves on ceiling					
5615	ACTIVE	P	D233-00-3/244	Passage - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25633	ACTIVE	P	D233-00-3/244	Passage - Station Building - Heathrow Terminals 123 Stn	Mastic	Asbestos	Known				Encapsulated - Asbestos gaskets to flanged ventilation ducting					



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25631	ACTIVE	P	D233-00-3/244/FLR-01	Floor - 1 - Passage - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Loose supalux boarding, concrete					
25632	ACTIVE	P	D233-00-3/244/WAL-003	Wall: Internal - 3 - Passage - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				10 x Supalux boards (3x Access panels)					
5616	ACTIVE	P	D233-00-3/246	Passage - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25634	ACTIVE	P	D233-00-3/246	Passage - Station Building - Heathrow Terminals 123 Stn	Mastic	Asbestos	Known				Encapsulated - Asbestos gaskets to flanged ventilation ducting					
24212	ACTIVE	P	D233-00-3/246	Passage - Station Building - Heathrow Terminals 123 Stn	Mastic	Asbestos	Known				Encapsulated - Asbestos gaskets to flanged ventilation ducting					
24213	ACTIVE	P	D233-00-3/246	Passage - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux panel above door - good condition					
25635	ACTIVE	P	D233-00-3/246/FLR-01	Floor - 1 - Passage - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux boarding					
25636	ACTIVE	P	D233-00-3/246/FLR-01	Floor - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Beneath Supalux boarding					Yes
25637	ACTIVE	P	D233-00-3/246/WAL-007	Wall: Internal - 7 - Passage - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				2 x Supalux board					
5617	ACTIVE	P	D233-00-3/247	Lobby - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25639	ACTIVE	P	D233-00-3/247/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
25638	ACTIVE	P	D233-00-3/247/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
5618	ACTIVE	P	D233-00-3/248	Passage - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25642	ACTIVE	P	D233-00-3/248	Passage - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux boarding above doors 3/733 & 3/131,					
25641	ACTIVE	P	D233-00-3/248/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, plastic cables, conduits above false ceiling				Yes	
24214	ACTIVE	P	D233-00-3/248/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25640	ACTIVE	P	D233-00-3/248/FLR-01	Floor - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				42m Marley tile (brown/grey)					
5619	ACTIVE	P	D233-00-3/249	Lobby - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24215	ACTIVE	P	D233-00-3/249/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, plastic cables, conduits above false ceiling				Yes	
25644	ACTIVE	P	D233-00-3/249/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
24050	ACTIVE	P	D233-00-3/249/FLR-01	Floor - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				5m² Marley tile (brown/grey)					
25643	ACTIVE	P	D233-00-3/249/FLR-01	Floor - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				20m Marley tile (brown/grey)					
5620	ACTIVE	P	D233-00-3/250	Passage - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24051	ACTIVE	P	D233-00-3/250/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
24216	ACTIVE	P	D233-00-3/250/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, conduit, plastic cables; All slip joint ventilation ducting has non-asbestos mastic/putty above false ceiling				Yes	
5621	ACTIVE	P	D233-00-3/251	Lobby - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24053	ACTIVE	P	D233-00-3/251/FLR-01	Floor - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				36m Marley tile (grey/brown)					
24052	ACTIVE	P	D233-00-3/251/FLR-01	Floor - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				2m² Marley tile (grey/brown)					
5622	ACTIVE	P	D233-00-3/252	Office - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24055	ACTIVE	P	D233-00-3/252/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, plastic cable, brick conduits above false ceiling				Yes	
24054	ACTIVE	P	D233-00-3/252/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5623	ACTIVE	P	D233-00-3/301	Office - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24059	ACTIVE	P	D233-00-3/301	Office - Station Building - Heathrow Terminals 123 Stn	Boarding: AIB	Asbestos	Known				6m² AIB panel on top of metal sheeting (to ceiling kitchen area)					
24057	ACTIVE	P	D233-00-3/301/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
24056	ACTIVE	P	D233-00-3/301/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
24058	INACTIVE	P	D233-00-3/301/WAL-004	Wall: Internal - 4 - Office - Station Building - Heathrow Terminals 123 Stn	LUL Heaters	Asbestos	Removed				LUL heater foam insulation - Has since been removed		1			
5624	ACTIVE	P	D233-00-3/302	Office - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25086	ACTIVE	P	D233-00-3/302	Office - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux boarding above door					
24063	ACTIVE	P	D233-00-3/302/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
24064	ACTIVE	P	D233-00-3/302/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
25087	ACTIVE	P	D233-00-3/302/FLR-01	Floor - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
24061	ACTIVE	P	D233-00-3/302/FLR-01	Floor - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Beneath Lino					Yes
24060	ACTIVE	P	D233-00-3/302/FLR-01	Floor - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
24068	ACTIVE	P	D233-00-3/302/FLR-01	Floor - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Beneath Lino					Yes
24062	ACTIVE	P	D233-00-3/302/WAL-001	Wall: Internal - 1 - Office - Station Building - Heathrow Terminals 123 Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				2x LTB heater		2			
5625	ACTIVE	P	D233-00-3/331	Mess Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24067	ACTIVE	P	D233-00-3/331	Mess Room - Station Building - Heathrow Terminals 123 Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				1x LUL heater with foam insulation		1			
24065	ACTIVE	P	D233-00-3/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
24066	ACTIVE	P	D233-00-3/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
5626	ACTIVE	P	D233-00-3/333	Office - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24069	ACTIVE	P	D233-00-3/333/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete slab, steel a/c ductwork above false ceiling				Yes	
5627	ACTIVE	P	D233-00-3/361	Mess Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24076	ACTIVE	P	D233-00-3/361	Mess Room - Station Building - Heathrow Terminals 123 Stn	Boarding: AIB	Asbestos	Known				6m² AIB panel on top of metal sheeting above (to ceiling kitchen area)					
24073	ACTIVE	P	D233-00-3/361/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
24072	ACTIVE	P	D233-00-3/361/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
24074	ACTIVE	P	D233-00-3/361/CLG-02	Ceiling: Solid - 2 - Mess Room - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
24075	ACTIVE	P	D233-00-3/361/CLG-02	Ceiling: Solid - 2 - Mess Room - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
24070	ACTIVE	P	D233-00-3/361/FLR-01	Floor - 1 - Mess Room - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
24071	ACTIVE	P	D233-00-3/361/FLR-01	Floor - 1 - Mess Room - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Beneath Lino					Yes
25088	ACTIVE	P	D233-00-3/361/WAL-003	Wall: Internal - 3 - Mess Room - Station Building - Heathrow Terminals 123 Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LUL heater foam insulation		1			
5628	ACTIVE	P	D233-00-3/371	Mess Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24933	ACTIVE	P	D233-00-3/371	Mess Room - Station Building - Heathrow Terminals 123 Stn	Boarding: AIB	Asbestos	Known				4m² AIB Panel - On top of metal sheeting above ceiling (kitchen area)					
24930	ACTIVE	P	D233-00-3/371/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
24932	ACTIVE	P	D233-00-3/371/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, plastic cables, conduits above false ceiling				Yes	
24931	ACTIVE	P	D233-00-3/371/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
24928	ACTIVE	P	D233-00-3/371/FLR-01	Floor - 1 - Mess Room - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				25m² Marley tile (grey/brown)					
24929	ACTIVE	P	D233-00-3/371/WAL-004	Wall: Internal - 4 - Mess Room - Station Building - Heathrow Terminals 123 Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - foam insulation		1			
5629	ACTIVE	P	D233-00-3/391	SCR - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5630	ACTIVE	P	D233-00-3/406	Store - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24936	ACTIVE	P	D233-00-3/406	Store - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux boarding above door					
24934	ACTIVE	P	D233-00-3/406/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
24935	ACTIVE	P	D233-00-3/406/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
5631	ACTIVE	P	D233-00-3/412	Store - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5632	ACTIVE	P	D233-00-3/413	Disused Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5633	ACTIVE	P	D233-00-3/414	CER - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24938	ACTIVE	P	D233-00-3/414/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, concrete, plastic cables, conduits, pipes above false ceiling				Yes	



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24937	ACTIVE	P	D233-00-3/414/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
5634	ACTIVE	P	D233-00-3/415	Store - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5635	ACTIVE	P	D233-00-3/416	Lobby - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24939	ACTIVE	P	D233-00-3/416/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
24319	ACTIVE	P	D233-00-3/416/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, concrete, plastic cable and brick; 300mm x 300mm slip joint ducting				Yes	
5636	ACTIVE	P	D233-00-3/417	Lobby - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24941	ACTIVE	P	D233-00-3/417/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
24940	ACTIVE	P	D233-00-3/417/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
5637	ACTIVE	P	D233-00-3/418	Toilet - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24942	ACTIVE	P	D233-00-3/418/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete slab above false ceiling				Yes	
5638	ACTIVE	P	D233-00-3/419	Office - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24943	ACTIVE	P	D233-00-3/419/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete slab above false ceiling				Yes	
5639	ACTIVE	P	D233-00-3/420	Toilet - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24944	ACTIVE	P	D233-00-3/420/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete slabs, steel a/c ductwork, supalux packing to a/c ductwork at high level above false ceiling				Yes	
5640	ACTIVE	P	D233-00-3/421	Toilet: Unisex - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24946	ACTIVE	P	D233-00-3/421/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				All putty/mastic to slip joint ducting above false ceiling				Yes	
25482	ACTIVE	P	D233-00-3/421/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
24947	ACTIVE	P	D233-00-3/421/WAL-004	Wall: Internal - 4 - Toilet - Station Building - Heathrow Terminals 123 Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Foam insulation in Heater		1			
24948	ACTIVE	P	D233-00-3/421/WAL-004	Wall: Internal - 4 - Toilet - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
24945	ACTIVE	P	D233-00-3/421/WAL-004	Wall: Internal - 4 - Toilet - Station Building - Heathrow Terminals 123 Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LTB heater		1			
24949	ACTIVE	P	D233-00-3/421/WAL-004	Wall: Internal - 4 - Toilet - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, copper pipe, plastic cable, metal trunking. All slip joint ducting, putty/mastic between joints above false ceiling				Yes	
5641	ACTIVE	P	D233-00-3/422	Toilet: Unisex - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5642	ACTIVE	P	D233-00-3/481	Store - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5643	ACTIVE	P	D233-00-3/482	Store - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24951	ACTIVE	P	D233-00-3/482/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux tiles				Yes	
24950	ACTIVE	P	D233-00-3/482/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
25483	ACTIVE	P	D233-00-3/482/FLR-01	Floor - 1 - Store - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				20m² Marley tile (grey)					
24952	INACTIVE	P	D233-00-3/482/WAL-004	Wall: Internal - 4 - Store - Station Building - Heathrow Terminals 123 Stn	LUL Heaters	Asbestos	Removed				REMOVED - 8"12" LTB heater (pad inside heater)		1			
5644	ACTIVE	P	D233-00-3/483	Store - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24953	ACTIVE	P	D233-00-3/483/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25034	ACTIVE	P	D233-00-3/483/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, metal ducting above false ceiling				Yes	
5645	ACTIVE	P	D233-00-3/484	Void - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5646	ACTIVE	P	D233-00-3/485	Office - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25036	ACTIVE	P	D233-00-3/485/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete slab, steel a/c ductwork above false ceiling				Yes	
25035	ACTIVE	P	D233-00-3/485/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
5647	ACTIVE	P	D233-00-3/486	Store - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25037	ACTIVE	P	D233-00-3/486	Store - Station Building - Heathrow Terminals 123 Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
5648	ACTIVE	P	D233-00-3/487	CER - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25038	ACTIVE	P	D233-00-3/487/CLG-01	Ceiling: Suspended - 1 - CER - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Above supalux tiles				Yes	
24421	ACTIVE	P	D233-00-3/487/FLR-01	Floor - 1 - CER - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				2m² Beige tiles					
5649	ACTIVE	P	D233-00-3/488	Store - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5650	ACTIVE	P	D233-00-3/489	Disused Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5651	ACTIVE	P	D233-00-3/501	Office - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25042	ACTIVE	P	D233-00-3/501/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete slab, metal a/c ductwork above false ceiling				Yes	
25041	ACTIVE	P	D233-00-3/501/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25039	ACTIVE	P	D233-00-3/501/FLR-01	Floor - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino on concrete slab					Yes
25040	ACTIVE	P	D233-00-3/501/WAL-001	Wall: Internal - 1 - Office - Station Building - Heathrow Terminals 123 Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Foam insulation in LTB heater		1			
5652	ACTIVE	P	D233-00-3/502	Office - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25045	ACTIVE	P	D233-00-3/502	Office - Station Building - Heathrow Terminals 123 Stn	Other Boarding	Asbestos	Presumed				Materials within lining to safe No access as no key due to CSM suite during 2020 re-inspection					
25044	ACTIVE	P	D233-00-3/502/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete slab, steel a/c ductwork, PVC cables above false ceiling				Yes	
25043	ACTIVE	P	D233-00-3/502/FLR-01	Floor - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino on concrete slab					Yes
5653	ACTIVE	P	D233-00-3/503	Office - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25047	ACTIVE	P	D233-00-3/503/FLR-01	Floor - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete slab, steel a/c ductwork, PVC cables above false ceiling					Yes
25046	ACTIVE	P	D233-00-3/503/FLR-01	Floor - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino on concrete slab					Yes
5654	ACTIVE	P	D233-00-3/504	Office - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25571	ACTIVE	P	D233-00-3/504/FLR-01	Floor - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete slab, steel a/c ductwork, PVC cables above false ceiling					Yes
25048	ACTIVE	P	D233-00-3/504/FLR-01	Floor - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino on concrete slab					
5655	ACTIVE	P	D233-00-3/505	Office - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25050	ACTIVE	P	D233-00-3/505/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete slab, steel a/c ductwork, PVC cables above false ceiling				Yes	
25049	ACTIVE	P	D233-00-3/505/FLR-01	Floor - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino on concrete slab					Yes



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5656	ACTIVE	P	D233-00-3/506	Locker Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25052	ACTIVE	P	D233-00-3/506/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Steel a/c ductwork, supalux & plasterboard cladding to a/c unit above false ceiling				Yes	
25051	ACTIVE	P	D233-00-3/506/FLR-01	Floor - 1 - Locker Room - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino on concrete slab					
5657	ACTIVE	P	D233-00-3/511	Passage - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25572	ACTIVE	P	D233-00-3/511/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete slab, steel a/c ductwork, PVC cables green/grey mastic - non asbestos to a/c ductwork above false ceiling				Yes	
25053	ACTIVE	P	D233-00-3/511/FLR-01	Floor - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino on concrete slab					
5658	ACTIVE	P	D233-00-3/512	Cell - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25054	ACTIVE	P	D233-00-3/512/CLG-01	Ceiling: Suspended - 1 - Cell - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
25055	ACTIVE	P	D233-00-3/512/CLG-01	Ceiling: Suspended - 1 - Cell - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, steel a/c ductwork, PVC cables above false ceiling				Yes	
5659	ACTIVE	P	D233-00-3/513	Office - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25059	ACTIVE	P	D233-00-3/513/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Above false ceiling				Yes	
25058	ACTIVE	P	D233-00-3/513/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
25056	ACTIVE	P	D233-00-3/513/FLR-01	Floor - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
25057	ACTIVE	P	D233-00-3/513/FLR-01	Floor - 1 - Office - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Beneath Lino					Yes
5660	ACTIVE	P	D233-00-3/514	Lobby - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25573	ACTIVE	P	D233-00-3/514/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete slab above false ceiling				Yes	
5661	ACTIVE	P	D233-00-3/515	Tenancy - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25145	ACTIVE	P	D233-00-3/515/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
25146	ACTIVE	P	D233-00-3/515/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, steel a/c ductwork above false ceiling				Yes	
25144	ACTIVE	P	D233-00-3/515/FLR-01	Floor - 1 - Tenancy - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino on concrete slab					Yes
5662	ACTIVE	P	D233-00-3/516	Mess Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25149	ACTIVE	P	D233-00-3/516/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				PVC cables above false ceiling				Yes	
25148	ACTIVE	P	D233-00-3/516/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
25147	ACTIVE	P	D233-00-3/516/WAL-001	Wall: Internal - 1 - Mess Room - Station Building - Heathrow Terminals 123 Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				(Rest Room on summary sheet and station layout) Foam insulation in LTB heater		1			
5663	ACTIVE	P	D233-00-3/521	Cell - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5664	ACTIVE	P	D233-00-3/522	Cell - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5665	ACTIVE	P	D233-00-3/576	Stairs: Linear - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25151	ACTIVE	P	D233-00-3/576/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Above false ceiling				Yes	
25150	ACTIVE	P	D233-00-3/576/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
5666	ACTIVE	P	D233-00-3/661	Switch Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25152	ACTIVE	P	D233-00-3/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminals 123 Stn	Isolator Switches	Asbestos	Strongly Presumed				1x 60 amp Fuse switch No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
5667	ACTIVE	P	D233-00-3/662	Switch Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25153	ACTIVE	P	D233-00-3/662/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Heathrow Terminals 123 Stn	Isolator Switches	Asbestos	Presumed				5 x 30amp, 1 x 100 amp Combination switch box No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		6			
25155	ACTIVE	P	D233-00-3/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminals 123 Stn	Isolator Switches	Asbestos	Strongly Presumed				3 x 60amp, 4 x 100amp, 1 x 200amp Combination switch boxes No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		8			
25156	ACTIVE	P	D233-00-3/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminals 123 Stn	Isolator Switches	Asbestos	Surveyed – Not Detected				1 x Red spot fuse board Deemed to be asbestos free (PFH)		1			
25154	ACTIVE	P	D233-00-3/662/WAL-003 80867283	Wall: Internal - 3 - Switch Room - Station Building - Heathrow Terminals 123 Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				Trunking					
5668	ACTIVE	P	D233-00-3/663	Switch Cupboard - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25157	ACTIVE	P	D233-00-3/663/CLG-01	Ceiling: Suspended - 1 - Switch Cupboard - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
25158	ACTIVE	P	D233-00-3/663/CLG-01	Ceiling: Suspended - 1 - Switch Cupboard - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Above supalux panels				Yes	
5669	ACTIVE	P	D233-00-3/664	Switch Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5670	ACTIVE	P	D233-00-3/731	Switch Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25159	ACTIVE	P	D233-00-3/731/FLR-01	Floor - 1 - Switch Room - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Beneath computer flooring					Yes
5671	ACTIVE	P	D233-00-3/732	CER - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24423	ACTIVE	p	D233-00-3/732	CER - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding behind Electrical Equipment					
25160	ACTIVE	p	D233-00-3/732/FLR-01	Floor - 1 - CER - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, plastic cable, trunking beneath computer flooring					Yes
25583	ACTIVE	p	D233-00-3/732/WAL-004	Wall: Internal - 4 - CER - Station Building - Heathrow Terminals 123 Stn	Isolator Switches	Asbestos	Presumed				2 x Fuse switches		2			
5672	ACTIVE	p	D233-00-3/733	CER - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5673	ACTIVE	p	D233-00-3/761	Equipment Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25161	ACTIVE	p	D233-00-3/761	Equipment Room - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Known				Walls - 70m Marley tiles(brown) on solid Some loose					
25162	ACTIVE	p	D233-00-3/761	Equipment Room - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Known				20m Marley tiles (brown) on solid above false ceiling Some loose					
25163	INACTIVE	p	D233-00-3/761	Equipment Room - Station Building - Heathrow Terminals 123 Stn	PCBs	Polychlorinated biphenyl	Known				4 x tested PCB's found leaking		4			
5674	ACTIVE	p	D233-00-3/762	Equipment Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25164	INACTIVE	p	D233-00-3/762/WAL-004	Wall: Internal - 4 - Equipment Room - Station Building - Heathrow Terminals 123 Stn	Isolator Switches	Asbestos	Removed				REMOVED - 1x Fuse switch		1			
5675	ACTIVE	p	D233-00-3/776	Fan Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5676	ACTIVE	p	D233-00-3/777	Fan Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25166	ACTIVE	p	D233-00-3/777	Fan Room - Station Building - Heathrow Terminals 123 Stn	Gasket :Pipework	Asbestos	Known				Asbestos gaskets to flanged ventilation ducting throughout fan room All remaining ducting containing asbestos gaskets have been encapsulated throughout this area					
25165	ACTIVE	p	D233-00-3/777	Fan Room - Station Building - Heathrow Terminals 123 Stn	Rope Seals	Asbestos	Known				Rope on duct - Encapsulated					
5677	ACTIVE	p	D233-00-3/778	Fan Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5678	ACTIVE	P	D233-00-3/782	Station Control Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25584	ACTIVE	P	D233-00-3/782	Station Control Room - Station Building - Heathrow Terminals 123 Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
5679	ACTIVE	P	D233-00-3/783	Substation Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25167	ACTIVE	P	D233-00-3/783	Substation Room - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Strongly Presumed				Basement - 4 x asbestos braided cables run in existing high level CMS Not within scope of 2020 reinspection		4			
45290	ACTIVE	P	D233-00-3/783	Substation Room - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Presumed				4 no. asbestos braided cables run in CMS high level through sub basement		4		N	N
5680	ACTIVE	P	D233-00-3/786	Service Area - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5681	ACTIVE	P	D233-00-3/787	Service Riser - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5682	ACTIVE	P	D233-00-3/788	Service Riser - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5683	ACTIVE	P	D233-00-3/901	Disused Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25168	ACTIVE	P	D233-00-3/902	Vent Shaft - Station Building - Heathrow Terminals 123 Stn	No Access	Asbestos	No Access: Presumed				Area accessed but unable to fully survey as a fixed scaffold is required. No ACM's are suspected.					
5684	ACTIVE	P	D233-00-3/903	Disused Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5685	ACTIVE	P	D233-00-3/904	Store - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5686	ACTIVE	P	D233-00-4/053	Equipment Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25244	ACTIVE	P	D233-00-4/053/CLG-01	Ceiling: Solid - 1 - Equipment Room - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
25585	ACTIVE	P	D233-00-4/053/CLG-01	Ceiling: Solid - 1 - Equipment Room - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24326	INACTIVE	P	D233-00-4/053/WAL-002	Wall: Internal - 2 - Equipment Room - Station Building - Heathrow Terminals 123 Stn	LUL Heaters	Asbestos	Removed				REMOVED - 0.02m² Heater		1			
25169	ACTIVE	P	D233-00-4/053/WAL-004	Wall: Internal - 4 - Equipment Room - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				3 x loose supalux boards					
5687	ACTIVE	P	D233-00-4/161	LMC - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25249	ACTIVE	P	D233-00-4/161	LMC - Station Building - Heathrow Terminals 123 Stn	Isolator Switches	Asbestos	Not Found during Inspection				5 x Fuse Switches & Trunking Removed not present		5			
45291	ACTIVE	P	D233-00-4/161	LMC - Station Building - Heathrow Terminals 123 Stn	Lead/Leading	Lead Paint/Lead	Presumed				Lead paint presumed				N	N
25245	ACTIVE	P	D233-00-4/161/FLR-01	Floor - 1 - LMC - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Beneath hatch					Yes
25248	ACTIVE	P	D233-00-4/161/WAL-001	Wall: Internal - 1 - LMC - Station Building - Heathrow Terminals 123 Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Upstairs by wall 1 Plasterboard					
25247	ACTIVE	P	D233-00-4/161/WAL-003	Wall: Internal - 3 - LMC - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Upstairs by wall 3 Supalux boxing					
25246	ACTIVE	P	D233-00-4/161/WAL-003	Wall: Internal - 3 - LMC - Station Building - Heathrow Terminals 123 Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel boarding					
5688	ACTIVE	P	D233-00-4/162	LMC - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45292	ACTIVE	P	D233-00-4/162	LMC - Station Building - Heathrow Terminals 123 Stn	Lead/Leading	Lead Paint/Lead	Presumed				Lead paint presumed				N	N
5689	ACTIVE	P	D233-00-4/201	Passage - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25253	ACTIVE	P	D233-00-4/201/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Other Boarding	Asbestos	Removed				Melamine Removed new tiles installed					
25252	ACTIVE	P	D233-00-4/201/FLR-01	Floor - 1 - Passage - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Beneath hatch					Yes
5690	ACTIVE	P	D233-00-4/236	Lobby - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25255	ACTIVE	P	D233-00-4/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
25256	ACTIVE	P	D233-00-4/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, plastic cable above false ceiling				Yes	
25254	ACTIVE	P	D233-00-4/236/FLR-01	Floor - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				25m Marley tiles					
5691	ACTIVE	P	D233-00-4/237	Lobby - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25592	ACTIVE	P	D233-00-4/237/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
25258	ACTIVE	P	D233-00-4/237/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, plastic cable above false ceiling				Yes	
25257	ACTIVE	P	D233-00-4/237/FLR-01	Floor - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				10m Marley tile (grey/brown)					
5692	ACTIVE	P	D233-00-4/238	Lobby - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25260	ACTIVE	P	D233-00-4/238/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
25259	ACTIVE	P	D233-00-4/238/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Heathrow Terminals 123 Stn		Asbestos	Surveyed – Not Detected				Supalux					
5693	ACTIVE	P	D233-00-4/261	Platform 1 - Westbound Local - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25270	ACTIVE	P	D233-00-4/261	Platform 1 - Westbound Local - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - 4x Cables (2x 60mm - track wall 4m from head wall, 2x 10mm)		4			
24683	ACTIVE	P	D233-00-4/261	Platform 1 - Westbound Local - Station Building - Heathrow Terminals 123 Stn	Cellactite Sheeting	Asbestos	Strongly Presumed				Corrugated sheet behind blue cover - West End					
25262	ACTIVE	P	D233-00-4/261	Platform 1 - Westbound Local - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Strongly Presumed				Woven cable sheath 20mm Above false ceiling (AFC)					
25263	ACTIVE	P	D233-00-4/261	Platform 1 - Westbound Local - Station Building - Heathrow Terminals 123 Stn	Cable Ducts: Bitumen	Asbestos	Known				Third bottom duct - bitumen - nr 4/661 switch room end Manhole keys required					



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25345	ACTIVE	p	D233-00-4/261	Platform 1 - Westbound Local - Station Building - Heathrow Terminals 123 Stn	Cellactite Sheeting	Asbestos	Known				Platform 1 (Departure End) - Cellactite (60m2) to Ceiling - Above False Ceiling					
25268	ACTIVE	p	D233-00-4/261	Platform 1 - Westbound Local - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - 2x Cables 15m from headwall (1x60mm, 1x10mm)		2			
24105	ACTIVE	p	D233-00-4/261	Platform 1 - Westbound Local - Station Building - Heathrow Terminals 123 Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Platform 1 Invert - 4x Cables sleeves by 4/712 - Filled In - No Access to sample		4			
25267	ACTIVE	p	D233-00-4/261	Platform 1 - Westbound Local - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - 1x 10mm Cable 30m from head wall		1			
25264	ACTIVE	p	D233-00-4/261	Platform 1 - Westbound Local - Station Building - Heathrow Terminals 123 Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Platform 1 Invert - 3x Cables 18m from 4/406 nr head wall		3			
25266	ACTIVE	p	D233-00-4/261	Platform 1 - Westbound Local - Station Building - Heathrow Terminals 123 Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Platform 1 Invert - 4x Cable sleeves - 10m past central invert nr head wall		4			
25265	ACTIVE	p	D233-00-4/261	Platform 1 - Westbound Local - Station Building - Heathrow Terminals 123 Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Platform 1 Invert - 6x Cable sleeves - 18m from 4/406		6			
25269	ACTIVE	p	D233-00-4/261	Platform 1 - Westbound Local - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - 2 x 10mm Cables 8m from head wall		2			
24104	ACTIVE	p	D233-00-4/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, metal struts, plastic cables above false ceiling				Yes	
25261	ACTIVE	p	D233-00-4/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Heathrow Terminals 123 Stn	Other Boarding	Asbestos	Known				Melamine New false ceiling installed therefore possibly removed					
5694	ACTIVE	p	D233-00-4/262	Platform 2 - Eastbound Local - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25350	ACTIVE	p	D233-00-4/262	Platform 2 - Eastbound Local - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - 2x 10mm Cables 15m from head wall - nr 4/706		2			
25351	ACTIVE	p	D233-00-4/262	Platform 2 - Eastbound Local - Station Building - Heathrow Terminals 123 Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Platform 2 Invert - 1x Cable sleeve 25m from head wall nr 4/706		1			
25352	ACTIVE	p	D233-00-4/262	Platform 2 - Eastbound Local - Station Building - Heathrow Terminals 123 Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Platform 2 Invert - 18x Cable sleeves around centre of invert nr 4/706		18			
25346	ACTIVE	p	D233-00-4/262	Platform 2 - Eastbound Local - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cable coming from first top duct into barrier above - nr 4/661					



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24327	ACTIVE	p	D233-00-4/262	Platform 2 - Eastbound Local - Station Building - Heathrow Terminals 123 Stn	Cellactite Sheeting	Asbestos	Known				Platform 2 Arrival End - Behind platform wall exposed cellactite sheeting encapsulated					
25353	ACTIVE	p	D233-00-4/262	Platform 2 - Eastbound Local - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - 2x Cables 5m from head wall nr 4/711		2			
25355	ACTIVE	p	D233-00-4/262	Platform 2 - Eastbound Local - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - 2x Cables (1x20m, 1x 60m) - by headwall br 4/706		2			
25356	ACTIVE	p	D233-00-4/262	Platform 2 - Eastbound Local - Station Building - Heathrow Terminals 123 Stn	Cellactite Sheeting	Asbestos	Known				Platform 2 Arrival End - Cellactite (60m2) to Ceiling - Chrysotile					
25347	ACTIVE	p	D233-00-4/262	Platform 2 - Eastbound Local - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Known				Two 15mm asbestos braided cables running from centre of EB platforms to headwall - Encapsulated No access below platform		2			
25348	ACTIVE	p	D233-00-4/262	Platform 2 - Eastbound Local - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - 9x assorted coloured cables & sizes - 2m from head wall nr 4/706		9			
45293	ACTIVE	p	D233-00-4/262	Platform 2 - Eastbound Local - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cable coming from bottom fifth duct going back to first top duct & into invert nr 4/661				N	N
24684	ACTIVE	p	D233-00-4/262	Platform 2 - Eastbound Local - Station Building - Heathrow Terminals 123 Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Platform 2 Invert - 3x Cable sleeves - 2m from back wall nr 4/711		3			
25349	ACTIVE	p	D233-00-4/262	Platform 2 - Eastbound Local - Station Building - Heathrow Terminals 123 Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Platform 2 Invert - 5 x Cable sleeves approx 15m from head wall nr 4/706		5			
25354	ACTIVE	p	D233-00-4/262	Platform 2 - Eastbound Local - Station Building - Heathrow Terminals 123 Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Platform 2 Invert - 4x Cable sleeves 2m from pit wall		4			
69359	ACTIVE	p	D233-00-4/262/CLG-02	Ceiling: Suspended - 2 - Platform 2 - Station Building - Heathrow Terminals 123 Stn	Void	Asbestos	Surveyed – Not Detected				No ACMs above false ceiling or behind VE panels			R679633		
45294	ACTIVE	p	D233-00-4/262/CLG-02	Ceiling: Suspended - 2 - Platform 2 - Station Building - Heathrow Terminals 123 Stn	Other Boarding	Asbestos	Removed				Melamine New false ceiling installed therefore possibly removed				N	N
5695	ACTIVE	p	D233-00-4/331	Kitchen - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5696	ACTIVE	p	D233-00-4/376	Store - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5697	ACTIVE	p	D233-00-4/396	Disused Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25357	INACTIVE	P	D233-00-4/396/WAL-002	Wall: Internal - 2 - Disused Room - Station Building - Heathrow Terminals 123 Stn	LUL Heaters	Asbestos	Removed				0.02m² Pad within Heater - Heater has been removed and replaced.		1			
5698	ACTIVE	P	D233-00-4/406	Lobby - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5699	ACTIVE	P	D233-00-4/407	Store - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5700	ACTIVE	P	D233-00-4/411	Disused Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5701	ACTIVE	P	D233-00-4/416	Shower Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5702	ACTIVE	P	D233-00-4/417	Lobby - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5703	ACTIVE	P	D233-00-4/418	Toilet: Unisex - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5704	ACTIVE	P	D233-00-4/419	Toilet: Unisex - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5705	ACTIVE	P	D233-00-4/481	Service Riser - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25358	ACTIVE	P	D233-00-4/481	Service Riser - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	No Access: Presumed				Various cables In Cable Shaft No Access below panel on floor					
5706	ACTIVE	P	D233-00-4/482	Equipment Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5707	ACTIVE	P	D233-00-4/483	Equipment Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5708	ACTIVE	P	D233-00-4/661	Switch Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42205	ACTIVE	P	D233-00-4/661	Switch Room - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Strongly Presumed				Asbestos - SP 2x Green cables (<10 (L)m) within manhole 1x Cable coming from first top duct platform 2 side into barrier above 1x Cable coming from bottom fifth duct going back to first top duct and into invert Lifting tools required for manhole no access 2020 reinspection		2			
42204	ACTIVE	P	D233-00-4/661	Switch Room - Station Building - Heathrow Terminals 123 Stn	Cable Ducts: Bitumen	Asbestos	Known				Third bottom duct within Manhole Lifting tools required for manhole no access 2020 reinspection					
25359	INACTIVE	P	D233-00-4/661/FLR-01	Floor - 1 - Switch Room - Station Building - Heathrow Terminals 123 Stn		Asbestos	Strongly Presumed				2x Green cables (<10 (L)m) below false floor Duplicate record see 42205		2			
25360	INACTIVE	P	D233-00-4/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Heathrow Terminals 123 Stn	Isolator Switches	Asbestos	Removed				1x Red spot fuse board Non asbestos - PFH		1			
24111	ACTIVE	P	D233-00-4/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Heathrow Terminals 123 Stn	Other Electrical Boxes	Asbestos	Presumed				1x 6KVA transformer on floor - Wall 1 & 2		1			
25361	ACTIVE	P	D233-00-4/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminals 123 Stn	Other Electrical Boxes	Asbestos	Presumed				2x Tunnel fan switch		2			
25362	INACTIVE	P	D233-00-4/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminals 123 Stn	Train Describers	Asbestos	Removed				1x Train describer transformer		1			
5709	ACTIVE	P	D233-00-4/662	Switch Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25365	ACTIVE	P	D233-00-4/662	Switch Room - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Strongly Presumed				1x 40mm Cable		1			
25364	ACTIVE	P	D233-00-4/662/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Heathrow Terminals 123 Stn	Other Electrical Boxes	Asbestos	Presumed				2x Signal box No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		2			
25363	ACTIVE	P	D233-00-4/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminals 123 Stn	Isolator Switches	Asbestos	Presumed				2x Switch box - access through 4/706 No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		2			
5710	ACTIVE	P	D233-00-4/663	Switch Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24112	ACTIVE	P	D233-00-4/663/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminals 123 Stn	Other Electrical Boxes	Asbestos	No Access: Presumed				1x Fuse box		1			
5711	ACTIVE	P	D233-00-4/664	Switch Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5712	ACTIVE	P	D233-00-4/665	Switch Cupboard - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5713	ACTIVE	P	D233-00-4/706	IMR - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25458	ACTIVE	P	D233-00-4/706	IMR - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Known				4x 35mm Cables on top J hangers at end of platform 2		4			
45295	ACTIVE	P	D233-00-4/706	IMR - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Known				1x 30mm Cable in bottom cable duct	30	1		N	N
25446	ACTIVE	P	D233-00-4/706	IMR - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Known				1x 25mm Cables in 2nd from bottom cable duct in corner on wall 3&4		1			
25370	ACTIVE	P	D233-00-4/706	IMR - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Known				7x 25mm Cables in top cable duct		7			
25445	ACTIVE	P	D233-00-4/706	IMR - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Known				3x 35mm Cables		3			
25369	ACTIVE	P	D233-00-4/706	IMR - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Known				5x 25mm Cables in 2nd from top cable duct		5			
25457	ACTIVE	P	D233-00-4/706	IMR - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Known				5x 25mm Cables from top duct into invert 2 - platform 2 side		5			
25456	ACTIVE	P	D233-00-4/706	IMR - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Known				15x 25mm Cables on all J hangers running to RWY 1100 L2 points, LHS of track heading towards Hatton cross		15			
25455	ACTIVE	P	D233-00-4/706	IMR - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Known				Outside IMR - 4x 25mm Cables running to RWY 1100 L2 points, RHS of track heading towards Hatton Cross PWT-EH required to gain access to track for photo however cables present within room		4			
42230	ACTIVE	P	D233-00-4/706	IMR - Station Building - Heathrow Terminals 123 Stn	Other Boarding	Asbestos	Presumed				Numerous Paxoline boarding throughout room (difficult to quantify)					
42225	INACTIVE	P	D233-00-4/706	IMR - Station Building - Heathrow Terminals 123 Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				Approx 10 PCB's		10			
42227	INACTIVE	P	D233-00-4/706	IMR - Station Building - Heathrow Terminals 123 Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				Approx 21 PCB's (9 in RACK 8, 12 in RACK 9)		21			



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42226	INACTIVE	P	D233-00-4/706	IMR - Station Building - Heathrow Terminals 123 Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				Approx 11 PCB's in Rack 5		11			
25366	ACTIVE	P	D233-00-4/706/WAL-001	Wall: Internal - 1 - IMR - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables - approx 18x10mm, 1x20mm, 3x30mm		22			
25367	ACTIVE	P	D233-00-4/706/WAL-003	Wall: Internal - 3 - IMR - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables - approx 5x30mm, 2x 25mm, 15x 10mm		22			
25368	ACTIVE	P	D233-00-4/706/WAL-003	Wall: Internal - 3 - IMR - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Known				Cables run from platform 2 invert at end of platform 2 into duct into IMR, along H hangers on wall 3 to fuse board					
25452	ACTIVE	P	D233-00-4/706/WAL-004	Wall: Internal - 4 - IMR - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Known				Cables run from platform 1 invert at end of platform 1, into IMR, along J hangers on wall 5 to fuse board					
25453	ACTIVE	P	D233-00-4/706/WAL-004	Wall: Internal - 4 - IMR - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Known				4x 25mm Cables in 2nd from top cable duct,		4			
25454	INACTIVE	P	D233-00-4/706/WAL-004	Wall: Internal - 4 - IMR - Station Building - Heathrow Terminals 123 Stn		Asbestos	Known				4x 25mm Cables in bottom cable duct		4			
24685	ACTIVE	P	D233-00-4/706/WAL-004	Wall: Internal - 4 - IMR - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Known				Cables coming from cable run at end of platform 1 running in each cable duct into IMR along J hangers on wall 4&5 to fuse board					
25450	ACTIVE	P	D233-00-4/706/WAL-004	Wall: Internal - 4 - IMR - Station Building - Heathrow Terminals 123 Stn	Cable Duct: Other	Asbestos	Known				8x25mm in 2nd from bottom cable duct		8			
25447	ACTIVE	P	D233-00-4/706/WAL-004	Wall: Internal - 4 - IMR - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Known				7x 25mm cable in top cable duct		7			
25448	ACTIVE	P	D233-00-4/706/WAL-004	Wall: Internal - 4 - IMR - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Known				2x35mm Cable		2			
25449	ACTIVE	P	D233-00-4/706/WAL-004	Wall: Internal - 4 - IMR - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Known				1x 25mm cable in 2nd from top cable duct		1			
25451	ACTIVE	P	D233-00-4/706/WAL-004	Wall: Internal - 4 - IMR - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Known				3x 25mm cable in bottom cable duct					
5714	ACTIVE	P	D233-00-4/711	Relay Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25462	ACTIVE	P	D233-00-4/711	Relay Room - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Known				Outside 4/711 - 10x 25mm Cables that exit relay room through top 4 ducts run on top 4 J hangers up to BRS 160m where some cable enter passageway between tracks (3x Cables running on top 4 J hangers enter passage way in between tracks, Cables are cut near rooms at end of passageway between tracks PWT-EH required to access track for photo however cables present in Room 4/711					
25460	ACTIVE	P	D233-00-4/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Known				2x 40mm Cables run from 4th platform 2 invert duct around wall 2&3 & terminate at 600 volt signal box		2			
25459	ACTIVE	P	D233-00-4/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Known				10x 25mm Cables run from 1st 4 platform 2 invert ducts along wall 3 & exit through top 4 ducts to track		10			
25461	INACTIVE	P	D233-00-4/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Heathrow Terminals 123 Stn		Asbestos	Removed				8x 10mm, 2x 40mm Cables Duplicate record - Please see 25460		10			
5715	ACTIVE	P	D233-00-4/712	Relay Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25465	INACTIVE	P	D233-00-4/712	Relay Room - Station Building - Heathrow Terminals 123 Stn		Asbestos	Known				Outside 4/712 Platform 1 side loop end - 1x25mm runs on top J hanger for at least 100m on loop from relay room 4/712		1			
25467	ACTIVE	P	D233-00-4/712	Relay Room - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Known				Outside 4/712 Platform 1 side loop end - 3x 25mm in 2nd Cable duct in floor to invert by wall 1 PWT-EH required to gain to track for photo however cables present in 4/712		3			
25466	ACTIVE	P	D233-00-4/712	Relay Room - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Known				Outside 4/712 Platform 1 side loop end - 2x 25mm Cables on 2nd from top J hanger run for at least 100m on loop from relay room 4/712 PWT-EH required to gain access to track for photo however cables present in Room 4/712		2			
24119	ACTIVE	P	D233-00-4/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Known				2x 40mm Cables in 4th cable duct in floor to invert 1 by wall 1(green woven cables run from invert Duct around wall 1&2 & terminals at 600 volt single box)		2			
25463	INACTIVE	P	D233-00-4/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Heathrow Terminals 123 Stn		Asbestos	Removed				Cables - 2x 40mm Duplicate record		2			
25464	ACTIVE	P	D233-00-4/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables - 10x 3mm		10			



Hazardous Material Asset Register - Summary



D233-00 - Station Building - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5716	ACTIVE	p	D233-00-4/771	Pump Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25468	ACTIVE	p	D233-00-4/771	Pump Room - Station Building - Heathrow Terminals 123 Stn	Gasket :Pipework	Asbestos	No Access: Presumed				Gaskets on Pump					
5717	ACTIVE	p	D233-00-4/786	Service Riser - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25545	ACTIVE	p	D233-00-4/786	Service Riser - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Known				Cables going from floor to ceiling 2x 10mm		2			
25544	ACTIVE	p	D233-00-4/786	Service Riser - Station Building - Heathrow Terminals 123 Stn	Cable: Sheath	Asbestos	Known				Cables going from floor to ceiling - 2x 40mm		2			
5718	ACTIVE	p	D233-00-4/901	Disused Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5719	ACTIVE	p	D233-00-4/902	Equipment Room - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5720	ACTIVE	p	D233-00-A/131	LMR - Station Building - Heathrow Terminals 123 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24413	ACTIVE	p	D233-00-A/131	LMR - Station Building - Heathrow Terminals 123 Stn	Other Electrical Boxes	Asbestos	Presumed				Components presumed inside electrical equipment box and pulley system No access unable to locate within station also station supervisor not sure either. No access 2020 re-inspection.					

D235-00 - Station Building - Heathrow Terminal 4 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5724	ACTIVE	p	D235-00-1/396	SVC - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5725	ACTIVE	p	D235-00-1/631	Stairs: Spiral - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25546	ACTIVE	p	D235-00-1/631	Stairs: Spiral - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supaluc panel around door					
5726	ACTIVE	p	D235-00-1/632	Stairs: Spiral - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D235-00 - Station Building - Heathrow Terminal 4 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5727	ACTIVE	P	D235-00-1/776	Plant Room - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25547	ACTIVE	P	D235-00-1/776	Plant Room - Station Building - Heathrow Terminal 4 Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed					
24276	ACTIVE	P	D235-00-1/776	Plant Room - Station Building - Heathrow Terminal 4 Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
5728	ACTIVE	P	D235-00-2/031	Mess Room - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25550	ACTIVE	P	D235-00-2/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Heathrow Terminal 4 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Concrete, metal trays & conduits above false ceiling				Yes	
25549	ACTIVE	P	D235-00-2/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux foam tiles					
25548	ACTIVE	P	D235-00-2/031/FLR-01	Floor - 1 - Mess Room - Station Building - Heathrow Terminal 4 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				10m² Vinyl floor tiles					
5729	ACTIVE	P	D235-00-2/081	Lobby - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5730	ACTIVE	P	D235-00-2/082	Lobby - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5731	ACTIVE	P	D235-00-2/083	Lobby - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5732	ACTIVE	P	D235-00-2/084	Lobby - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25552	ACTIVE	P	D235-00-2/084/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				No access above 2 x metal vent hatches					
5733	ACTIVE	P	D235-00-2/236	Passage - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25553	ACTIVE	P	D235-00-2/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Fibreglass lagging above false ceiling				Yes	
5734	ACTIVE	P	D235-00-2/237	Lobby - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D235-00 - Station Building - Heathrow Terminal 4 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25554	ACTIVE	P	D235-00-2/237/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux foam tiles					
25555	ACTIVE	P	D235-00-2/237/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	Surveyed – Not Detected				Metal trays & concrete above false ceiling				Yes	
5735	ACTIVE	P	D235-00-2/238	Passage - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25556	ACTIVE	P	D235-00-2/238/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux foam tiles					
25557	ACTIVE	P	D235-00-2/238/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
5736	ACTIVE	P	D235-00-2/239	Passage - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5737	ACTIVE	P	D235-00-2/240	Passage - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25559	ACTIVE	P	D235-00-2/240/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	Surveyed – Not Detected				Conduits, metal beams above false ceiling				Yes	
25558	ACTIVE	P	D235-00-2/240/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux foam tiles					
5738	ACTIVE	P	D235-00-2/241	Passage - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5739	ACTIVE	P	D235-00-2/243	Passage - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25561	ACTIVE	P	D235-00-2/243/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	Surveyed – Not Detected				5x Concrete, fibreglass lagged pipes above false ceiling				Yes	
25560	ACTIVE	P	D235-00-2/243/WAL-001	Wall: Internal - 1 - Passage - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux panel					
24125	ACTIVE	P	D235-00-2/244/FLR-01	Floor - 1 - Gantry - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				No access behind Metal Cable Tray					Yes
5740	ACTIVE	P	D235-00-2/311	Store - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D235-00 - Station Building - Heathrow Terminal 4 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25562	ACTIVE	P	D235-00-2/311/FLR-01	Floor - 1 - Store - Station Building - Heathrow Terminal 4 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				10m² Vinyl floor tiles					
5741	ACTIVE	P	D235-00-2/316	Disused Room - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25564	ACTIVE	P	D235-00-2/316/CLG-01	Ceiling: Suspended - 1 - Disused Room - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete vent duct tubes above false ceiling				Yes	
25563	ACTIVE	P	D235-00-2/316/WAL-004	Wall: Internal - 4 - Disused Room - Station Building - Heathrow Terminal 4 Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
5742	ACTIVE	P	D235-00-2/331	Mess Room - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24208	ACTIVE	P	D235-00-2/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				No access above supalux ceiling tiles					
25565	ACTIVE	P	D235-00-2/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
5743	ACTIVE	P	D235-00-2/332	Mess Room - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25567	ACTIVE	P	D235-00-2/332/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux panel					
25566	ACTIVE	P	D235-00-2/332/WAL-001	Wall: Internal - 1 - Mess Room - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux panel					
5744	ACTIVE	P	D235-00-2/381	Disused Room - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25568	ACTIVE	P	D235-00-2/381	Disused Room - Station Building - Heathrow Terminal 4 Stn	No Access	Asbestos	No Access: Presumed				(Disused on station layout) Not Surveyed					
5745	ACTIVE	P	D235-00-2/382	Office - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25569	ACTIVE	P	D235-00-2/382	Office - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	Surveyed – Not Detected				False wall - fibreglass lagging on pipes & supalux boarding behind					
24077	ACTIVE	P	D235-00-2/382/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	



Hazardous Material Asset Register - Summary



D235-00 - Station Building - Heathrow Terminal 4 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25570	ACTIVE	P	D235-00-2/382/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux					
5746	ACTIVE	P	D235-00-2/383	Disused Room - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5747	ACTIVE	P	D235-00-2/411	Store - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24078	ACTIVE	P	D235-00-2/411/FLR-01	Floor - 1 - Store - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux boxing at base of ducting by wall 1					
5748	ACTIVE	P	D235-00-2/412	Store - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24079	ACTIVE	P	D235-00-2/412/FLR-01	Floor - 1 - Store - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux boxing by wall 5					
24080	ACTIVE	P	D235-00-2/412/WAL-001	Wall: Internal - 1 - Store - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux panel					
24081	ACTIVE	P	D235-00-2/412/WAL-006	Wall: Internal - 6 - Store - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux panel above the door panel					
24082	ACTIVE	P	D235-00-2/412/WAL-006	Wall: Internal - 6 - Store - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, vent units, fibreglass lagged above false ceiling				Yes	
5749	ACTIVE	P	D235-00-2/416	Toilet: Male - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24217	ACTIVE	P	D235-00-2/416/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				No access above 2 x metal Vent hatches					
5750	ACTIVE	P	D235-00-2/417	Toilet: Female - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24083	ACTIVE	P	D235-00-2/417/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux foam tile (second toilet)					
24084	ACTIVE	P	D235-00-2/417/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				No access above false ceiling					
24085	ACTIVE	P	D235-00-2/417/WAL-004	Wall: Internal - 4 - Toilet - Station Building - Heathrow Terminal 4 Stn	Bakerlite	Asbestos	Not Found during Inspection				2x 0.3m² Toilet Cistern - 1st & 2nd toilet Removed cisterns now ceramic				N	N



Hazardous Material Asset Register - Summary



D235-00 - Station Building - Heathrow Terminal 4 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5751	ACTIVE	P	D235-00-2/418	Shower Room - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5752	ACTIVE	P	D235-00-2/419	Toilet: Male - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5753	ACTIVE	P	D235-00-2/420	Toilet: Female - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5754	ACTIVE	P	D235-00-2/421	Toilet: Male - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5755	ACTIVE	P	D235-00-2/576	Stairs: Linear - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24087	ACTIVE	P	D235-00-2/576/CLG-01	Ceiling: Suspended - 1 - Linear Stairs - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
24086	ACTIVE	P	D235-00-2/576/CLG-01	Ceiling: Suspended - 1 - Linear Stairs - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux foam tiles					
5756	ACTIVE	P	D235-00-2/577	Ladder Lobby - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5757	ACTIVE	P	D235-00-2/578	Ladder Lobby - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5758	ACTIVE	P	D235-00-2/579	Stairs: Linear - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5759	ACTIVE	P	D235-00-2/631	Stairs: Spiral - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24088	ACTIVE	P	D235-00-2/631	Stairs: Spiral - Station Building - Heathrow Terminal 4 Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
70513	ACTIVE	P	D235-00-2/646	Gantry - Station Building - Heathrow Terminal 4 Stn	Gasket :Pipework	Asbestos	Known				Asbestos to flange of pipework/ valves - some are rubber gaskets by cat ladder 2/579				N	N
5760	ACTIVE	P	D235-00-2/761	CER - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24089	ACTIVE	P	D235-00-2/761/FLR-01	Floor - 1 - CER - Station Building - Heathrow Terminal 4 Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Red vinyl tiles					



Hazardous Material Asset Register - Summary



D235-00 - Station Building - Heathrow Terminal 4 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24090	ACTIVE	P	D235-00-2/761/WAL-004	Wall: Internal - 4 - CER - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux Boxing on wall					
5761	ACTIVE	P	D235-00-2/763	Plant Room - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5762	ACTIVE	P	D235-00-2/764	Service Riser - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24091	ACTIVE	P	D235-00-2/764/CLG-01	Ceiling: Solid - 1 - Service Riser - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux boxing by wall 3					
5763	ACTIVE	P	D235-00-2/801	Disused Room - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24093	ACTIVE	P	D235-00-2/801/WAL-004	Wall: Internal - 4 - Disused Room - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux panel					
5764	ACTIVE	P	D235-00-2/901	Plant Room - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5765	ACTIVE	P	D235-00-2/907	Service Riser - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24094	ACTIVE	P	D235-00-2/907/WAL-001	Wall: Internal - 1 - Service Riser - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux boxing & panels around vent equipment					
5766	ACTIVE	P	D235-00-3/001	Booking Hall - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42288	ACTIVE	P	D235-00-3/001	Booking Hall - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	Sampled – Not Detected				Insulation throughout to mesh throughtout within the ceiling void.				Y	N
25089	ACTIVE	P	D235-00-3/001/FLR-01	Floor - 1 - Booking Hall - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				No access to Inspection Chambers					Yes
5767	ACTIVE	P	D235-00-3/011	Ticket Office - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42287	ACTIVE	P	D235-00-3/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Heathrow Terminal 4 Stn	Mastic	Asbestos	Sampled – Not Detected				Mastic throughout to the joints of the metal ductwork above the false ceiling rear of the ticket office by third ventilation air supply				Y	N
24097	ACTIVE	P	D235-00-3/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete sprayed beams, metal cable trays above false ceiling				Yes	



Hazardous Material Asset Register - Summary



D235-00 - Station Building - Heathrow Terminal 4 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42286	ACTIVE	P	D235-00-3/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Heathrow Terminal 4 Stn	Mastic	Asbestos	Sampled – Not Detected				Mastic throughout to the joints of the metal ductwork above the false ceiling midway to ticket office by second ventilation air supply				Y	N
42285	ACTIVE	P	D235-00-3/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Heathrow Terminal 4 Stn	Mastic	Asbestos	Sampled – Not Detected				Mastic throughout to the joints of the metal ductwork above the false ceiling by the entrance to ticket office by first ventilation air supply				Y	N
24096	ACTIVE	P	D235-00-3/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux foam tiles					
24095	ACTIVE	P	D235-00-3/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
5768	ACTIVE	P	D235-00-3/021	POM - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24098	ACTIVE	P	D235-00-3/021/FLR-01	Floor - 1 - POM - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
5769	ACTIVE	P	D235-00-3/036	Toilet: Unisex - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5770	ACTIVE	P	D235-00-3/071	Circulation Area - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25551	ACTIVE	P	D235-00-3/071	Circulation Area - Station Building - Heathrow Terminal 4 Stn	Cable Duct: Other	Asbestos	Known				Cement cable duct - Exact location to be confirmed		1			
24100	ACTIVE	P	D235-00-3/071	Circulation Area - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				No access to Fire Cupboard					
24099	ACTIVE	P	D235-00-3/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				No access to access hatches within ceiling x4				Yes	
25170	ACTIVE	P	D235-00-3/071/FLR-01	Floor - 1 - Circulation Area - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				No access to below 13 x hatches to floor					Yes
5771	ACTIVE	P	D235-00-3/081	Lobby - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5772	ACTIVE	P	D235-00-3/201	Passage - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24101	ACTIVE	P	D235-00-3/201/FLR-01	Floor - 1 - Passage - Station Building - Heathrow Terminal 4 Stn	No Access	Asbestos	No Access: Presumed				Beneath 1 x hatch					Yes



Hazardous Material Asset Register - Summary



D235-00 - Station Building - Heathrow Terminal 4 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5773	ACTIVE	P	D235-00-3/236	Passage - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24102	ACTIVE	P	D235-00-3/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux foam tile					
24103	ACTIVE	P	D235-00-3/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
5774	ACTIVE	P	D235-00-3/237	Passage - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5775	ACTIVE	P	D235-00-3/238	Passage - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24154	ACTIVE	P	D235-00-3/238/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	Surveyed – Not Detected				Metal ducting, solid above false ceiling				Yes	
24153	ACTIVE	P	D235-00-3/238/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux foam tiles					
24152	ACTIVE	P	D235-00-3/238/WAL-002	Wall: Internal - 2 - Passage - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux boxing, no access behind, supalux panels around door frames					
5776	ACTIVE	P	D235-00-3/239	Passage - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24156	ACTIVE	P	D235-00-3/239/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
24155	ACTIVE	P	D235-00-3/239/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux foam tiles					
5777	ACTIVE	P	D235-00-3/240	Lobby - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24161	ACTIVE	P	D235-00-3/240/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
24160	ACTIVE	P	D235-00-3/240/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux foam tiles					
24157	ACTIVE	P	D235-00-3/240/WAL-001	Wall: Internal - 1 - Lobby - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux boxing between walls 1&2, 2&3					



Hazardous Material Asset Register - Summary



D235-00 - Station Building - Heathrow Terminal 4 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24158	ACTIVE	P	D235-00-3/240/WAL-003	Wall: Internal - 3 - Lobby - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux boxing between walls, 2&3, 1&2					
24159	ACTIVE	P	D235-00-3/240/WAL-004	Wall: Internal - 4 - Lobby - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux panels around door frame					
5778	ACTIVE	P	D235-00-3/241	Lobby - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24163	ACTIVE	P	D235-00-3/241/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
24162	ACTIVE	P	D235-00-3/241/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux foam tiles					
5779	ACTIVE	P	D235-00-3/242	Lobby - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5780	ACTIVE	P	D235-00-3/243	Lobby - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24686	ACTIVE	P	D235-00-3/243/WAL-001 80864923	Wall: Internal - 1 - Lobby - Station Building - Heathrow Terminal 4 Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Iron clad isolator - Asbestos Components within		1		N	N
24164	INACTIVE	P	D235-00-3/243/WAL-001	Wall: Internal - 1 - Lobby - Station Building - Heathrow Terminal 4 Stn	Isolator Switches	Asbestos	Strongly Presumed				1x Combination Fuse switches - 1x30amps No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
5781	ACTIVE	P	D235-00-3/244	Passage - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5782	ACTIVE	P	D235-00-3/261	Platform 1 - Single Line Local - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5783	ACTIVE	P	D235-00-3/281	Station Supervisor Office - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24165	ACTIVE	P	D235-00-3/281/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux foam tiles					
24166	ACTIVE	P	D235-00-3/281/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	



Hazardous Material Asset Register - Summary



D235-00 - Station Building - Heathrow Terminal 4 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5784	ACTIVE	P	D235-00-3/331	Tea Point - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24167	ACTIVE	P	D235-00-3/331	Tea Point - Station Building - Heathrow Terminal 4 Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - Non visible					
5785	ACTIVE	P	D235-00-3/401	Bin Store - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5786	ACTIVE	P	D235-00-3/406	Store - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24171	ACTIVE	P	D235-00-3/406/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Above supalux panel					
24170	ACTIVE	P	D235-00-3/406/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux panel by walls 1 & 2					
24168	ACTIVE	P	D235-00-3/406/WAL-002	Wall: Internal - 2 - Store - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux Boxing					
24169	ACTIVE	P	D235-00-3/406/WAL-004	Wall: Internal - 4 - Store - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux Boxing					
5787	ACTIVE	P	D235-00-3/411	Store - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5788	ACTIVE	P	D235-00-3/412	Store - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24173	ACTIVE	P	D235-00-3/412/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	Surveyed – Not Detected				Solid concrete sprayed beams above false ceiling				Yes	
24172	ACTIVE	P	D235-00-3/412/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux panelling above wall 4					
25173	ACTIVE	P	D235-00-3/412/FLR-01	Floor - 1 - Store - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				Beneath 1 x hatch					Yes
5789	ACTIVE	P	D235-00-3/413	Store - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5790	ACTIVE	P	D235-00-3/414	Lobby - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D235-00 - Station Building - Heathrow Terminal 4 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24174	ACTIVE	P	D235-00-3/414/WAL-004	Wall: Internal - 4 - Lobby - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux panel					
5791	ACTIVE	P	D235-00-3/415	Store - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24175	ACTIVE	P	D235-00-3/415/FLR-01	Floor - 1 - Store - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				Beneath hatch					Yes
5792	ACTIVE	P	D235-00-3/416	Toilet: Female - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24176	ACTIVE	P	D235-00-3/416	Toilet: Female - Station Building - Heathrow Terminal 4 Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - Non visible					
5793	ACTIVE	P	D235-00-3/417	Toilet: Male - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25174	ACTIVE	P	D235-00-3/417	Toilet: Male - Station Building - Heathrow Terminal 4 Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - Non visible					
5794	ACTIVE	P	D235-00-3/451	Tenancy - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24178	ACTIVE	P	D235-00-3/451	Tenancy - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				Supalux boxing back part of Tenancy - No access behind NB this property is managed by TFL Commercial Property					
24177	ACTIVE	P	D235-00-3/451/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
5795	ACTIVE	P	D235-00-3/452	Tenancy - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5796	ACTIVE	P	D235-00-3/661	Switch Room - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25175	ACTIVE	P	D235-00-3/661/FLR-01	Floor - 1 - Switch Room - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				Beneath hatch					Yes
43217	ACTIVE	P	D235-00-3/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Heathrow Terminal 4 Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Cable Ducts Wall 1				N	N
43216	ACTIVE	P	D235-00-3/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Heathrow Terminal 4 Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Transformer Box Asbestos Components – Strongly Presumed within		1		N	N



Hazardous Material Asset Register - Summary



D235-00 - Station Building - Heathrow Terminal 4 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24254	ACTIVE	P	D235-00-3/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminal 4 Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Electrical equipment Asbestos Components – Strongly Presumed within				N	N
5797	ACTIVE	P	D235-00-3/662	Switch Room - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24255	ACTIVE	P	D235-00-3/662/FLR-01	Floor - 1 - Switch Room - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				Beneath hatch					Yes
24256	ACTIVE	P	D235-00-3/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminal 4 Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Electrical equipment Asbestos Components – Strongly Presumed within				N	N
5798	ACTIVE	P	D235-00-3/663	Switch Room - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24257	ACTIVE	P	D235-00-3/663/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminal 4 Stn	Isolator Switches	Asbestos	Not Found during Inspection				6x Iron clad isolators Removed not present 2020 Re-inspection.		6		N	N
24258	ACTIVE	P	D235-00-3/663/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminal 4 Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Trunking Asbestos Components – Strongly Presumed within				N	N
43218	ACTIVE	P	D235-00-3/663/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminal 4 Stn	Isolator Switches	Asbestos	Strongly Presumed				Wall 2, 6 Switch Box 4 x 60amps, 2 x 30amps		6		N	N
5799	ACTIVE	P	D235-00-3/664	Switch Room - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5800	ACTIVE	P	D235-00-3/665	Switch Room - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24428	ACTIVE	P	D235-00-3/665/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminal 4 Stn	Isolator Switches	Asbestos	Strongly Presumed				1x Iron clad isolators 1 x 30amps		1		N	N
43223	ACTIVE	P	D235-00-3/665/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminal 4 Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				3 Transformer Boxes Asbestos Components – Strongly Presumed within		3		N	N
5801	ACTIVE	P	D235-00-3/666	Switch Room - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24259	ACTIVE	P	D235-00-3/666/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				2x Supalux panels by wall 3					
5802	INACTIVE	P	D235-00-3/711	Relay Room - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Polychlorinated biphenyl	Strongly Presumed									



Hazardous Material Asset Register - Summary



D235-00 - Station Building - Heathrow Terminal 4 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42114	INACTIVE	P	D235-00-3/711	Relay Room - Station Building - Heathrow Terminal 4 Stn	PCBs	Polychlorinated biphenyl	Known				6 x PCB's - Fair Condition		6		N	N
43221	INACTIVE	P	D235-00-3/711/ WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Heathrow Terminal 4 Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				8 x PCB's, Wall 1				N	N
5803	ACTIVE	P	D235-00-3/712	Disused Room - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5804	ACTIVE	P	D235-00-3/731	CER - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24260	ACTIVE	P	D235-00-3/731/ WAL-002	Wall: Internal - 2 - CER - Station Building - Heathrow Terminal 4 Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x Iron clad isolators 2 x 60amps		2		N	N
5805	ACTIVE	P	D235-00-3/746	SCR - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45205	ACTIVE	P	D235-00-3/762	Vent Shaft - Station Building - Heathrow Terminal 4 Stn	Rope Gaskets	Asbestos	Strongly Presumed				Top level - Vent equipment				N	N
24266	ACTIVE	P	D235-00-3/762	Vent Shaft - Station Building - Heathrow Terminal 4 Stn	Rope Gaskets	Asbestos	Strongly Presumed				Fan & ventilation equipment - no access to gaskets				N	N
24265	ACTIVE	P	D235-00-3/762	Vent Shaft - Station Building - Heathrow Terminal 4 Stn	Cable Duct: Other	Asbestos	Strongly Presumed				4x cable ducts		4		N	N
24262	ACTIVE	P	D235-00-3/762/ FLR-01	Floor - 1 - Vent Shaft - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				Beneath hatch by wall 2					Yes
24264	ACTIVE	P	D235-00-3/762/ WAL-002 80865108	Wall: Internal - 2 - Vent Shaft - Station Building - Heathrow Terminal 4 Stn Wall: Internal	LUL Heaters	Asbestos	Strongly Presumed				1 x Wall heater.		1		N	N
24263	ACTIVE	P	D235-00-3/762/ WAL-003	Wall: Internal - 3 - Vent Shaft - Station Building - Heathrow Terminal 4 Stn	Isolator Switches	Asbestos	Strongly Presumed				3x Iron clad isolators - 2x 200amps & 1x 100 amps		3		N	N
5806	ACTIVE	P	D235-00-3/771	Pump Room - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24267	ACTIVE	P	D235-00-3/771/ FLR-01	Floor - 1 - Pump Room - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				Beneath hatch					Yes
24268	ACTIVE	P	D235-00-3/771/ WAL-004	Wall: Internal - 4 - Pump Room - Station Building - Heathrow Terminal 4 Stn	Isolator Switches	Asbestos	Strongly Presumed				5x Iron clad isolators - 4x30amps, 1x 60amps		5		N	N
24269	ACTIVE	P	D235-00-3/771/ WAL-004	Wall: Internal - 4 - Pump Room - Station Building - Heathrow Terminal 4 Stn	Gasket :Pipework	Asbestos	No Access: Presumed				Gaskets in pumps equipment					



Hazardous Material Asset Register - Summary



D235-00 - Station Building - Heathrow Terminal 4 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25183	ACTIVE	P	D235-00-3/771/WAL-004	Wall: Internal - 4 - Pump Room - Station Building - Heathrow Terminal 4 Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Trunking Asbestos Components – Strongly Presumed within				N	N
70570	ACTIVE	P	D235-00-3/786	Service Area - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
5807	INACTIVE	P	D235-00-3/786	Service Area - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24270	INACTIVE	P	D235-00-3/786	Service Area - Station Building - Heathrow Terminal 4 Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
5808	ACTIVE	P	D235-00-3/787	Service Riser - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24271	ACTIVE	P	D235-00-3/787	Service Riser - Station Building - Heathrow Terminal 4 Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - Non visible					
5809	ACTIVE	P	D235-00-3/788	Service Area - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24272	ACTIVE	P	D235-00-3/788	Service Area - Station Building - Heathrow Terminal 4 Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - Non visible					
5810	ACTIVE	P	D235-00-3/801	CER - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24273	ACTIVE	P	D235-00-3/801/WAL-003	Wall: Internal - 3 - CER - Station Building - Heathrow Terminal 4 Stn		Asbestos	Surveyed – Not Detected				Supalux boxing around vents					
5811	ACTIVE	P	D235-00-3/901	Tenancy - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25184	ACTIVE	P	D235-00-3/901/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				Above false ceiling NB Property managed by TFL Commercial Property				Yes	
5812	ACTIVE	P	D235-00-3/902	Store - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24274	ACTIVE	P	D235-00-3/902/FLR-01	Floor - 1 - Store - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				Beneath computer tiles					Yes
5813	ACTIVE	P	D235-00-3/903	Disused Room - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D235-00 - Station Building - Heathrow Terminal 4 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5814	ACTIVE	p	D235-00-3/951	Disused Room - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24275	ACTIVE	p	D235-00-3/951	Disused Room - Station Building - Heathrow Terminal 4 Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - Non visible					
5815	ACTIVE	p	D235-00-A/776	Plant Room - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24277	ACTIVE	p	D235-00-A/776	Plant Room - Station Building - Heathrow Terminal 4 Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed NB Managed by LU Power & Electrical					
5816	ACTIVE	p	D235-00-A/777	Plant Room - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5817	ACTIVE	p	D235-00-B/776	Plant Room - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24278	ACTIVE	p	D235-00-B/776	Plant Room - Station Building - Heathrow Terminal 4 Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed NB Managed by LU Power & Electrical					
5818	ACTIVE	p	D235-00-C/776	Plant Room - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25185	ACTIVE	p	D235-00-C/776	Plant Room - Station Building - Heathrow Terminal 4 Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed NB Managed by LU Power & Electrical					
5819	ACTIVE	p	D235-00-C/777	Plant Room - Station Building - Heathrow Terminal 4 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

D237-00 - Station Building - Heathrow Terminal 5 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5820	ACTIVE	p	D237-00-3/711	SER - Station Building - Heathrow Terminal 5 Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

D243-00 - Station Building - Ealing Common Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5821	ACTIVE	p	D243-00-1/001	Booking Hall - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D243-00 - Station Building - Ealing Common Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5822	ACTIVE	P	D243-00-1/011	Ticket Office - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24356	ACTIVE	P	D243-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Ealing Common Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
24355	ACTIVE	P	D243-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Ealing Common Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
24280	ACTIVE	P	D243-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Ealing Common Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
5823	ACTIVE	P	D243-00-1/021	POM - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24357	ACTIVE	P	D243-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Ealing Common Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
5824	ACTIVE	P	D243-00-1/031	Mess Room - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24414	ACTIVE	P	D243-00-1/031	Mess Room - Station Building - Ealing Common Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				2x Gas heaters		2			
5825	ACTIVE	P	D243-00-1/036	Toilet: Unisex - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5826	ACTIVE	P	D243-00-1/081	Lobby - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5827	ACTIVE	P	D243-00-1/451	Tenancy - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24358	ACTIVE	P	D243-00-1/451/FLR-01	Floor - 1 - Tenancy - Station Building - Ealing Common Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl on wood flooring					
24359	ACTIVE	P	D243-00-1/451/FLR-01	Floor - 1 - Tenancy - Station Building - Ealing Common Stn	Void	Asbestos	No Access: Presumed				Beneath wooden floor					Yes
5828	ACTIVE	P	D243-00-1/452	Tenancy - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24360	ACTIVE	P	D243-00-1/452	Tenancy - Station Building - Ealing Common Stn	No Access	Asbestos	No Access: Presumed				Tenancy - Not Surveyed					
5829	ACTIVE	P	D243-00-1/453	Tenancy - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				21 Oct 2014 No Access					



Hazardous Material Asset Register - Summary



D243-00 - Station Building - Ealing Common Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24361	ACTIVE	p	D243-00-1/453	Tenancy - Station Building - Ealing Common Stn	No Access	Asbestos	No Access: Presumed				No Access 21 Oct 2014 Tenancy - Not Surveyed					
5830	ACTIVE	p	D243-00-1/601	Stairs: Linear - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24362	ACTIVE	p	D243-00-1/601	Stairs: Linear - Station Building - Ealing Common Stn	Lead/Leading	Lead Paint/Lead	Known				On hand rails supports & spindles of stairs - blue gloss. Thickness : 0.44mm Analysis : 7.5%					
24363	ACTIVE	p	D243-00-1/601	Stairs: Linear - Station Building - Ealing Common Stn	Lead/Leading	Lead Paint/Lead	Known				Band of colour to stair wells light brown gloss - 40m². Thickness : 0.53mm Analysis : 2.7% (Potentially painted over with white paint)					
24364	ACTIVE	p	D243-00-1/601	Stairs: Linear - Station Building - Ealing Common Stn	Lead/Leading	Lead Paint/Lead	Known				Around windows on platform canopy - light brown gloss - 40m² - has since been painted blue - noted during HMU Re Inspection					
5831	ACTIVE	p	D243-00-1/602	Stairs: Linear - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24366	ACTIVE	p	D243-00-1/602	Stairs: Linear - Station Building - Ealing Common Stn	Lead/Leading	Lead Paint/Lead	Known				Band of colour to stair wells light brown gloss - 40m². Thickness : 0.53mm Analysis : 2.7% (Potentially painted over with white paint)					
24365	ACTIVE	p	D243-00-1/602	Stairs: Linear - Station Building - Ealing Common Stn	Lead/Leading	Lead Paint/Lead	Known				On hand rails supports & spindles of stairs - blue gloss. Thickness : 0.44mm Analysis : 7.5%					
24367	ACTIVE	p	D243-00-1/602	Stairs: Linear - Station Building - Ealing Common Stn	Lead/Leading	Lead Paint/Lead	Known				Around windows on platform canopy - light brown gloss - 40m² - has since been painted blue - noted upon HMU re inspection					
24368	ACTIVE	p	D243-00-1/636	Overbridge - Station Building - Ealing Common Stn	Lead/Leading	Lead Paint/Lead	Known				On hand rails supports & spindles of stairs - blue gloss. Thickness : 0.44mm Analysis : 7.5%					
5832	ACTIVE	p	D243-00-1/661	Switch Room - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24371	ACTIVE	p	D243-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Ealing Common Stn	Other Boarding	Asbestos	Presumed				Paxoline Board					
24370	ACTIVE	p	D243-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Ealing Common Stn	Cable Duct: Other	Asbestos	Presumed				2 x cable ducts - 1 x sealed		2			
24369	ACTIVE	p	D243-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Ealing Common Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes 2x60amp, 1x100amp Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		3			
5833	ACTIVE	p	D243-00-1/662	Switch Room - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D243-00 - Station Building - Ealing Common Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24372	ACTIVE	P	D243-00-1/662/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Ealing Common Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes 3 x 2x60amp 1x100amp No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		3			
24374	ACTIVE	P	D243-00-1/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Ealing Common Stn	Cable Duct: Other	Asbestos	Presumed				Cable ducts					
24373	ACTIVE	P	D243-00-1/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Ealing Common Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes 1 x 30amp No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
24375	ACTIVE	P	D243-00-1/662/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Ealing Common Stn	Other Electrical Boxes	Asbestos	Presumed				3 x Transformer Boxes - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		3			
25271	ACTIVE	P	D243-00-1/662/WDW-01	Window - 1 - Switch Room - Station Building - Ealing Common Stn		Asbestos	Surveyed – Not Detected				Supalux panel in window low level. Plywood panel in window high level					
5834	ACTIVE	P	D243-00-1/761	Equipment Room - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5835	ACTIVE	P	D243-00-2/081	Computer Equipment Cupboard - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24376	ACTIVE	P	D243-00-2/081/WAL-002	Wall: Internal - 2 - Computer Equipment Cupboard - Station Building - Ealing Common Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard panels above door					
5836	ACTIVE	P	D243-00-2/082	Lobby - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5837	ACTIVE	P	D243-00-2/261	Platform 1 - Westbound Main - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24378	ACTIVE	P	D243-00-2/261	Platform 1 - Westbound Main - Station Building - Ealing Common Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse Box - Insulation within - WB End No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
24377	ACTIVE	P	D243-00-2/261	Platform 1 - Westbound Main - Station Building - Ealing Common Stn	Cable: Sheath	Asbestos	Strongly Presumed				3x Cables within hangers of old post route - Ramp end		3			



Hazardous Material Asset Register - Summary



D243-00 - Station Building - Ealing Common Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42146	ACTIVE	p	D243-00-2/261	Platform 1 - Westbound Main - Station Building - Ealing Common Stn	Lead/Leading	Lead Paint/Lead	Presumed				Potentially red lead paint on grit bin platform 1 near 2/406					
42144	ACTIVE	p	D243-00-2/261	Platform 1 - Westbound Main - Station Building - Ealing Common Stn	Lead/Leading	Lead Paint/Lead	Presumed				Potentially lead paint on Stretcher cupboard on platform 1 by 2/762					
24380	ACTIVE	p	D243-00-2/261	Platform 1 - Westbound Main - Station Building - Ealing Common Stn	Lead/Leading	Lead Paint/Lead	Known				Band of colour around windows on platform canopy - light brown gloss - 40m². Thickness : 0.53mm Analysis : 2.7%. - Not found upon HMU Re Inspection Oct 2014					
24379	ACTIVE	p	D243-00-2/261	Platform 1 - Westbound Main - Station Building - Ealing Common Stn	Lead/Leading	Lead Paint/Lead	Known				Band of colour to stair wells light brown gloss - 40m². Thickness : 0.53mm Analysis : 2.7%. Not found upon HMU Re Inspection Oct 2014					
25272	ACTIVE	P	D243-00-2/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Ealing Common Stn	Void	Asbestos	Surveyed – Not Detected				Manholes - all manholes are electrical or rainwater Bitumen ducts from cable pit mid platform to next cable pit near end of platform - NON ASBESTOS (R705286)					Yes
5838	ACTIVE	p	D243-00-2/262	Platform 2 - Eastbound Main - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42116	ACTIVE	p	D243-00-2/262	Platform 2 - Eastbound Main - Station Building - Ealing Common Stn	Cable: Sheath	Asbestos	Presumed				Braided cables within J-Hanger					
24457	ACTIVE	p	D243-00-2/262	Platform 2 - Eastbound Main - Station Building - Ealing Common Stn	Westing house Boxes	Asbestos	Strongly Presumed				Various Westinghouse Boxes - Insulation within - EB End No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.					
25273	ACTIVE	p	D243-00-2/262	Platform 2 - Eastbound Main - Station Building - Ealing Common Stn	Lead/Leading	Lead Paint/Lead	Known				Band of colour around windows on platform canopy - light brown gloss - 40m². Thickness : 0.53mm Analysis : 2.7% - Not found upon HMU Re Inspection Oct 2014					
24381	ACTIVE	p	D243-00-2/262	Platform 2 - Eastbound Main - Station Building - Ealing Common Stn	Lead/Leading	Lead Paint/Lead	Known				Band of colour to stair wells light brown gloss - 40m². Thickness : 0.53mm Analysis : 2.7% - Not found upon Re Inspection (HMU) Oct 2014					
42145	ACTIVE	p	D243-00-2/262	Platform 2 - Eastbound Main - Station Building - Ealing Common Stn	Lead/Leading	Lead Paint/Lead	Presumed				Potentially red lead paint on Grit bins platform 2 by 2/401					
5839	ACTIVE	p	D243-00-2/281	Station Supervisor Office - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24460	ACTIVE	p	D243-00-2/281	Station Supervisor Office - Station Building - Ealing Common Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				2x LUL heaters with white foam backing		2			



Hazardous Material Asset Register - Summary



D243-00 - Station Building - Ealing Common Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24461	ACTIVE	P	D243-00-2/281	Station Supervisor Office - Station Building - Ealing Common Stn		Asbestos	Surveyed – Not Detected				Supalux boxing around columns					
24459	ACTIVE	P	D243-00-2/281/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Ealing Common Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
24458	ACTIVE	P	D243-00-2/281/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Ealing Common Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
5840	ACTIVE	P	D243-00-2/331	Mess Room - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24464	ACTIVE	P	D243-00-2/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Ealing Common Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
24465	ACTIVE	P	D243-00-2/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Ealing Common Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
24463	ACTIVE	P	D243-00-2/331/FLR-01	Floor - 1 - Mess Room - Station Building - Ealing Common Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl flooring					
5841	ACTIVE	P	D243-00-2/401	Bin Store - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5842	ACTIVE	P	D243-00-2/406	Store - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5843	ACTIVE	P	D243-00-2/411	Store - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24471	ACTIVE	P	D243-00-2/411/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Ealing Common Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
24470	ACTIVE	P	D243-00-2/411/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Ealing Common Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
24468	ACTIVE	P	D243-00-2/411/WAL-001	Wall: Internal - 1 - Store - Station Building - Ealing Common Stn		Asbestos	Surveyed – Not Detected				Supalux Boxing					
24466	ACTIVE	P	D243-00-2/411/WAL-002	Wall: Internal - 2 - Store - Station Building - Ealing Common Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
24467	ACTIVE	P	D243-00-2/411/WAL-003	Wall: Internal - 3 - Store - Station Building - Ealing Common Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					



Hazardous Material Asset Register - Summary



D243-00 - Station Building - Ealing Common Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24469	ACTIVE	P	D243-00-2/411/WAL-003	Wall: Internal - 3 - Store - Station Building - Ealing Common Stn		Asbestos	Surveyed – Not Detected				Supalux Boxing					
5844	ACTIVE	P	D243-00-2/412	CER - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5845	ACTIVE	P	D243-00-2/416	Toilet: Male - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24473	ACTIVE	P	D243-00-2/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Ealing Common Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
24472	ACTIVE	P	D243-00-2/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Ealing Common Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
5846	ACTIVE	P	D243-00-2/417	Toilet: Female - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25279	ACTIVE	P	D243-00-2/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Ealing Common Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
24474	ACTIVE	P	D243-00-2/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Ealing Common Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
5847	ACTIVE	P	D243-00-2/436	Waiting Room - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5848	ACTIVE	P	D243-00-2/437	Waiting Room - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5849	ACTIVE	P	D243-00-2/451	Store - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24475	ACTIVE	P	D243-00-2/451	Store - Station Building - Ealing Common Stn	No Access	Asbestos	Surveyed – Not Detected				Room converted in to CER see HM00116					
5850	ACTIVE	P	D243-00-2/452	Tenancy - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5851	ACTIVE	P	D243-00-2/661	Switch Room - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24476	ACTIVE	P	D243-00-2/661	Switch Room - Station Building - Ealing Common Stn		Asbestos	Surveyed – Not Detected				Supalux panels above door at high level					



Hazardous Material Asset Register - Summary



D243-00 - Station Building - Ealing Common Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5852	ACTIVE	P	D243-00-2/706	IMR - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42143	ACTIVE	P	D243-00-2/706	IMR - Station Building - Ealing Common Stn	Other Electrical Boxes	Asbestos	Presumed				3x Rectifier boxes and electrical equipment - Insulation within presumed to contain asbestos Missing entire Room 2/761 on Platform, 1 brown panels , electrical boxes, CFS, transformers - requires full management survey at later date, not part of 2020 re-inspection No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.					
24477	ACTIVE	P	D243-00-2/706	IMR - Station Building - Ealing Common Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Bakelite panels on back of control panels					
42147	ACTIVE	P	D243-00-2/706	IMR - Station Building - Ealing Common Stn	Other Boarding	Asbestos	Presumed				Paxoline board behind electrical equipment Missing known blue and grey marley tiles to walls throughout 120m2 approx Composite slight damage and some loose .					
5853	ACTIVE	P	D243-00-2/746	SCR - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5854	ACTIVE	P	D243-00-2/762	Disused Room - Station Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25280	ACTIVE	P	D243-00-2/762/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Ealing Common Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Tentest Board					

DD216-19 - Charles Holden House - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6092	ACTIVE	P	DD216-19-1/041	Canteen - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6093	ACTIVE	P	DD216-19-1/047	Kitchen - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6094	ACTIVE	P	DD216-19-1/081	Lobby - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



DD216-19 - Charles Holden House - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6095	ACTIVE	p	DD216-19-1/236	Passage - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6096	ACTIVE	p	DD216-19-1/237	Passage - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6097	ACTIVE	p	DD216-19-1/291	Office - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6098	ACTIVE	p	DD216-19-1/331	Mess Room - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6099	ACTIVE	p	DD216-19-1/332	Mess Room - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6100	ACTIVE	p	DD216-19-1/406	Store - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6101	ACTIVE	p	DD216-19-1/416	Toilet: Disabled - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6102	ACTIVE	p	DD216-19-1/417	Toilet: Female - Train Crew Accommodation - Northfields Depot Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6103	ACTIVE	p	DD216-19-1/418	Toilet: Male - Train Crew Accommodation - Northfields Depot Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6104	ACTIVE	p	DD216-19-1/531	Depot Control Room - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6105	ACTIVE	p	DD216-19-1/532	Booking On Point - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6106	ACTIVE	p	DD216-19-1/576	Stairs: Linear - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6107	ACTIVE	p	DD216-19-1/661	Switch Room - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6108	ACTIVE	p	DD216-19-1/801	Office - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6109	ACTIVE	p	DD216-19-1/802	Office - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



DD216-19 - Charles Holden House - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6110	ACTIVE	p	DD216-19-1/803	Office - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6111	ACTIVE	p	DD216-19-1/804	Office - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6112	ACTIVE	p	DD216-19-1/805	Office - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6113	ACTIVE	p	DD216-19-A/236	Passage - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6114	ACTIVE	p	DD216-19-A/237	Passage - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6115	ACTIVE	p	DD216-19-A/331	Mess Room - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46695	ACTIVE	p	DD216-19-A/331	Mess Room - Charles Holden House - Northfields Depot	Bitumen	Asbestos	Sampled – Not Detected				Acoustic panel under sink - 0.05m²					
6116	ACTIVE	p	DD216-19-A/332	Locker Room - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6117	ACTIVE	p	DD216-19-A/333	Locker Room - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6118	ACTIVE	p	DD216-19-A/334	Locker Room - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6119	ACTIVE	p	DD216-19-A/335	Locker Room - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6120	ACTIVE	p	DD216-19-A/406	Store - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6121	ACTIVE	p	DD216-19-A/416	Toilet: Female - Charles Holden House - Northfields Depot Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6122	ACTIVE	p	DD216-19-A/417	Toilet: Male - Charles Holden House - Northfields Depot Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6123	ACTIVE	p	DD216-19-A/571	Store - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



DD216-19 - Charles Holden House - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6124	ACTIVE	P	DD216-19-A/661	Switch Room - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6125	ACTIVE	P	DD216-19-A/662	Switch Cupboard - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6126	ACTIVE	P	DD216-19-A/664	Switch Cupboard - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6127	ACTIVE	P	DD216-19-A/665	Switch Cupboard - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6128	ACTIVE	P	DD216-19-A/776	Plant Room - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6129	ACTIVE	P	DD216-19-A/801	Office - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6130	ACTIVE	P	DD216-19-A/802	Union Office - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6131	ACTIVE	P	DD216-19-A/803	Training Room - Charles Holden House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10226	ACTIVE	P	N107-00-1/047	Kitchen - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
22004	ACTIVE	P	N107-00-1/047/CLG-01	Ceiling: Solid - 1 - Kitchen - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Above false ceiling - CONCRETE (Report - R167826)					
22003	ACTIVE	P	N107-00-1/047/CLG-01	Ceiling: Solid - 1 - Kitchen - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux panel					
22005	ACTIVE	P	N107-00-1/047/CLG-01	Ceiling: Solid - 1 - Kitchen - Station Building - Leicester Square Stn	Lead/Leading	Lead Paint/Lead	Known				Sprinkler: Red Gloss. Thickness 0.11mm: Analysis 4.67%					
22002	ACTIVE	P	N107-00-1/047/SNK-01	Sink - 1 - Kitchen - Station Building - Leicester Square Stn	Bitumen	Asbestos	Surveyed – Not Detected				Bituminous Acoustic Panel under Sink					



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10227	ACTIVE	P	N107-00-1/201	Circulation Area - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22006	ACTIVE	P	N107-00-1/201/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Above false ceiling					
10228	ACTIVE	P	N107-00-1/202	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22007	ACTIVE	P	N107-00-1/202/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux panel					
10229	ACTIVE	P	N107-00-1/203	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22009	ACTIVE	P	N107-00-1/203	Passage - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Wall 3 - Supalux (wall 3 not in maximo)					
22008	ACTIVE	P	N107-00-1/203/WAL-001	Wall: Internal - 1 - Passage - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Fibreboard, Supalux					
10230	ACTIVE	P	N107-00-1/236	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23572	ACTIVE	P	N107-00-1/236/WAL-004	Wall: Internal - 4 - Passage - Station Building - Leicester Square Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard Partition					
10231	ACTIVE	P	N107-00-1/237	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22011	ACTIVE	P	N107-00-1/237	Passage - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux vent by entrance					
22012	ACTIVE	P	N107-00-1/237	Passage - Station Building - Leicester Square Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LTB Heater		1			
23723	ACTIVE	P	N107-00-1/237/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, brick walls and ceiling with plastic sheathed cables and metal CMS - above false ceiling				Yes	
22013	ACTIVE	P	N107-00-1/237/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux					
22010	ACTIVE	P	N107-00-1/237/FLR-01	Floor - 1 - Passage - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Beneath rubber floor					Yes
10232	ACTIVE	P	N107-00-1/238	Lobby - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22014	ACTIVE	P	N107-00-1/238/WAL-001	Wall: Internal - 1 - Lobby - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux cladding to vent duct					
22015	ACTIVE	P	N107-00-1/238/WAL-002	Wall: Internal - 2 - Lobby - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux cladding to vent duct					
22016	ACTIVE	P	N107-00-1/238/WAL-003	Wall: Internal - 3 - Lobby - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux cladding to vent duct					
22017	ACTIVE	P	N107-00-1/238/WAL-004	Wall: Internal - 4 - Lobby - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux cladding to vent duct					
10233	ACTIVE	P	N107-00-1/239	Lobby - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
23724	ACTIVE	P	N107-00-1/239/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Air con ducting, Plastic cables, New CMS & brick walls near 1/411, Breeze block above false ceiling				Yes	
22018	ACTIVE	P	N107-00-1/239/WAL-004	Wall: Internal - 4 - Lobby - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Panel by Entrance					
10234	ACTIVE	P	N107-00-1/301	Office - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22020	ACTIVE	P	N107-00-1/301/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Brick, Vent Duct above false ceiling				Yes	
25821	ACTIVE	P	N107-00-1/301/FLR-01	Floor - 1 - Office - Station Building - Leicester Square Stn	Vinyl tiles	Asbestos	Presumed				Marley Tiles potentially under carpet tiles Not possible to access beneath well fixed ceramic tiles without causing extensive damage to floor.					
22019	INACTIVE	P	N107-00-1/301/FLR-01	Floor - 1 - Office - Station Building - Leicester Square Stn	Vinyl tiles	Asbestos	Presumed				Potential Marley tiles under carpet					Yes
10235	ACTIVE	P	N107-00-1/316	Locker Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22292	ACTIVE	P	N107-00-1/316/CLG-01	Ceiling: Solid - 1 - Locker Room - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Brick Vent Duct above false ceiling				Yes	
22291	ACTIVE	P	N107-00-1/316/FLR-01	Floor - 1 - Locker Room - Station Building - Leicester Square Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Brown Marley Tiles - non asbestos					
22290	ACTIVE	P	N107-00-1/316/WAL-002	Wall: Internal - 2 - Locker Room - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux boxing below vent duct& Fibreglass lagged duct near ceiling					



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10236	ACTIVE	P	N107-00-1/317	Locker Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
22294	ACTIVE	P	N107-00-1/317/CLG-01	Ceiling: Solid - 1 - Locker Room - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
22293	ACTIVE	P	N107-00-1/317/FLR-01	Floor - 1 - Locker Room - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Beneath rubber matting					Yes
10237	ACTIVE	P	N107-00-1/331	Locker Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
23663	ACTIVE	P	N107-00-1/331	Locker Room - Station Building - Leicester Square Stn	Other Boarding	Asbestos	Presumed				Board to void by wall to 1/317					
22297	ACTIVE	P	N107-00-1/331/CLG-01	Ceiling: Solid - 1 - Locker Room - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete with plastic sheathed cables and metal CMS above false ceiling				Yes	
22295	ACTIVE	P	N107-00-1/331/WAL-004	Wall: Internal - 4 - Locker Room - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Large Supalux Panel					
22296	ACTIVE	P	N107-00-1/331/WAL-006	Wall: Internal - 6 - Locker Room - Station Building - Leicester Square Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LUL Heater - Foam Backing		1			
10238	ACTIVE	P	N107-00-1/396	Disused Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
10239	ACTIVE	P	N107-00-1/406	Bin Store - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
44459	ACTIVE	P	N107-00-1/406	Bin Store - Station Building - Leicester Square Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Supalux boarding to walls 3 and 4					
10240	ACTIVE	P	N107-00-1/411	Toilet - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
22298	ACTIVE	P	N107-00-1/411/WAL-002	Wall: Internal - 2 - Store - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Boxing, Supalux Panelling					
22300	ACTIVE	P	N107-00-1/411/WAL-003	Wall: Internal - 3 - Store - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Panelling					
22299	ACTIVE	P	N107-00-1/411/WAL-007	Wall: Internal - 7 - Store - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Boxing					



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10241	ACTIVE	P	N107-00-1/416	Toilet: Male - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
22302	ACTIVE	P	N107-00-1/416	Toilet: Male - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux & Glass Rock Band decorating panel around top					
22303	ACTIVE	P	N107-00-1/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				Asbestos cables in conduit above door - false ceiling				Yes	
22301	ACTIVE	P	N107-00-1/416/FLR-01	Floor - 1 - Toilet - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				To manholes					Yes
10242	ACTIVE	P	N107-00-1/417	Toilet: Female - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
22304	ACTIVE	P	N107-00-1/417/FLR-01	Floor - 1 - Toilet - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				To manholes					Yes
46499	ACTIVE	P	N107-00-1/418	Toilet - Station Building - Leicester Square Stn		Asbestos	No Access: Presumed				Room Not Surveyed					
10243	ACTIVE	P	N107-00-1/601	Stairs: Linear - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
22306	ACTIVE	P	N107-00-1/601/CLG-01 80858488	Ceiling: Solid - 1 - Linear Stairs - Station Building - Leicester Square Stn Ceiling: Solid	Void	Asbestos	Surveyed – Not Detected				Above false ceiling					
10244	ACTIVE	P	N107-00-1/602	Stairs: Linear - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
22307	ACTIVE	P	N107-00-1/602/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Panels; render on mesh; wooden panels					
23756	ACTIVE	P	N107-00-1/602/CLG-01 80858492	Ceiling: Solid - 1 - Linear Stairs - Station Building - Leicester Square Stn Ceiling: Solid	Void	Asbestos	Surveyed – Not Detected				Above false ceiling					
10245	ACTIVE	P	N107-00-1/603	Stairs: Linear - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
22308	ACTIVE	P	N107-00-1/603/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Aircon ducting, plastic cables, concrete ceiling, concrete/brick above bulkhead above false ceiling				Yes	
10246	ACTIVE	P	N107-00-1/604	Stairs: Linear - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10247	ACTIVE	P	N107-00-1/605	Stairs: Linear - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
10248	ACTIVE	P	N107-00-1/606	Stairs: Linear - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
10249	ACTIVE	P	N107-00-1/607	Stairs: Linear - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
10250	ACTIVE	P	N107-00-1/661	Switch Cupboard - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
22309	ACTIVE	P	N107-00-1/661	Switch Cupboard - Station Building - Leicester Square Stn	Isolator Switches	Asbestos	Strongly Presumed				Wall 1 - 1 x Switch Box - Insulation within (1x100amps) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
10251	ACTIVE	P	N107-00-1/761	SVC - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22313	ACTIVE	P	N107-00-1/761	SVC - Station Building - Leicester Square Stn	Gasket :Pipework	Asbestos	Strongly Presumed				Wall 1 - 2 x possible water mains - gaskets		2			
22314	ACTIVE	P	N107-00-1/761	SVC - Station Building - Leicester Square Stn	Lead/Leading	Lead Paint/Lead	Known				Pump: Red Gloss. Thickness 0.67mm: Analysis 5.74%					
23757	ACTIVE	P	N107-00-1/761/CLG-01	Ceiling: Solid - 1 - SVC - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Panel					
22312	ACTIVE	P	N107-00-1/761/CLG-01 80858506	Ceiling: Solid - 1 - SVC - Station Building - Leicester Square Stn Ceiling: Solid	Void	Asbestos	Surveyed – Not Detected				Above false ceiling					
22310	ACTIVE	P	N107-00-1/761/FLR-01	Floor - 1 - SVC - Station Building - Leicester Square Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Marley Tiles - non asbestos					
22311	ACTIVE	P	N107-00-1/761/WAL-002	Wall: Internal - 2 - SVC - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Panels					
10252	ACTIVE	P	N107-00-1/786	Service Riser - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22315	ACTIVE	P	N107-00-1/786/WAL-003	Wall: Internal - 3 - Service Riser - Station Building - Leicester Square Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Track Disconnection Box - Potential Siluminite No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.					
22316	ACTIVE	P	N107-00-1/791	Vent Shaft - Station Building - Leicester Square Stn	Caulking	Asbestos	No Access: Presumed				No access to sample caulking between tunnel rings					



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23758	ACTIVE	P	N107-00-1/791/DOR-01	Door - 1 - Vent Shaft - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux around Door Frames					
10253	ACTIVE	P	N107-00-1/901	Disused Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10254	ACTIVE	P	N107-00-1/952	Video Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22318	ACTIVE	P	N107-00-1/952	Video Room - Station Building - Leicester Square Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LTB heater - foam backing		1			
22319	ACTIVE	P	N107-00-1/952/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
22317	ACTIVE	P	N107-00-1/952/FLR-01	Floor - 1 - Office - Station Building - Leicester Square Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Linoleum					
10255	ACTIVE	P	N107-00-1/953	SVC - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10256	ACTIVE	P	N107-00-2/001	Booking Hall - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10257	ACTIVE	P	N107-00-2/011	Ticket Office - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22321	ACTIVE	P	N107-00-2/011/CLG-01	Ceiling: Solid - 1 - Ticket Office - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
22322	ACTIVE	P	N107-00-2/011/CLG-01	Ceiling: Solid - 1 - Ticket Office - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete to ceiling, concrete/ breeze blocks to walls, water pipes/ lagging / armour flex / rockwool . All cables plastic / aircon ducting above false ceiling				Yes	
22320	ACTIVE	P	N107-00-2/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Beneath rubber tiles					Yes
10258	ACTIVE	P	N107-00-2/012	Ticket Office - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22324	ACTIVE	P	N107-00-2/012/CLG-01	Ceiling: Solid - 1 - Ticket Office - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
22325	ACTIVE	P	N107-00-2/012/CLG-01	Ceiling: Solid - 1 - Ticket Office - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete to ceiling, concrete /brick to walls, all cables plastic, CMS, conduits					
22323	ACTIVE	P	N107-00-2/012/FLR-01	Floor - 1 - Ticket Office - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Steel Cable Ducts beneath Computer Tiles					Yes



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10259	ACTIVE	P	N107-00-2/021	POM - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22328	ACTIVE	P	N107-00-2/021/CLG-01	Ceiling: Solid - 1 - POM - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete to ceiling & walls, all cables plastic, air con, rockwool, ducting,supalux boarding debris, CMS, conduits above false ceiling				Yes	
22327	ACTIVE	P	N107-00-2/021/CLG-01	Ceiling: Solid - 1 - POM - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
22326	ACTIVE	P	N107-00-2/021/FLR-01	Floor - 1 - POM - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Steel Cable Ducts beneath Computer Tiles					Yes
10260	ACTIVE	P	N107-00-2/022	POM - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22332	ACTIVE	P	N107-00-2/022/CLG-01	Ceiling: Solid - 1 - POM - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete to ceiling, CMS / water pipes with rockwool canvas lagging, supalux boarding debris above false ceiling				Yes	
22331	ACTIVE	P	N107-00-2/022/CLG-01	Ceiling: Solid - 1 - POM - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
22330	ACTIVE	P	N107-00-2/022/FLR-01	Floor - 1 - POM - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Steel Cable Ducts, Fibreglass beneath false floor					Yes
22329	ACTIVE	P	N107-00-2/022/FLR-01	Floor - 1 - POM - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
10261	ACTIVE	P	N107-00-2/031	Mess Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22334	ACTIVE	P	N107-00-2/031/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
22335	ACTIVE	P	N107-00-2/031/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete to ceiling, all cables plastic, air con ducting, conduits, water pipes, rockwool lagging above false ceiling				Yes	
22333	ACTIVE	P	N107-00-2/031/FLR-01	Floor - 1 - Mess Room - Station Building - Leicester Square Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Linoleum Tiles					
10262	ACTIVE	P	N107-00-2/036	Toilet: Unisex - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23759	ACTIVE	P	N107-00-2/036/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete,all cables plastic, conduits, CMS above metal ceiling				Yes	
10263	ACTIVE	P	N107-00-2/071	Circulation Area - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22336	ACTIVE	P	N107-00-2/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Above hatches					
10264	ACTIVE	P	N107-00-2/072	Circulation Area - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22337	ACTIVE	P	N107-00-2/072	Circulation Area - Station Building - Leicester Square Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed					
10265	ACTIVE	P	N107-00-2/081	Lobby - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23954	ACTIVE	P	N107-00-2/081	Lobby - Station Building - Leicester Square Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
10266	ACTIVE	P	N107-00-2/151	UMC - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
25808	ACTIVE	P	N107-00-2/151	UMC - Station Building - Leicester Square Stn	Other Electrical Boxes	Asbestos	Presumed				1x Transformer box - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.					
22139	INACTIVE	P	N107-00-2/151	UMC - Station Building - Leicester Square Stn	Isolator Switches	Asbestos	Removed				UMC Escalator 4,5&6 - 485V Supply box - 3 x Switch Boxes - Insulation within		3			
22138	ACTIVE	P	N107-00-2/151	UMC - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				UMC Escalator 4,5&6 - Above Ceiling - Plaster on mesh, all cables plastic, concrete,debris: hessian cloth, supalux boarding, wood, plaster. No asbestos was identified in the surveyed area. However, access to fully survey was heavily restricted by extensive cable trunking and cable throughout ceiling void					
25809	ACTIVE	P	N107-00-2/151	UMC - Station Building - Leicester Square Stn	Gasket :Pipework	Asbestos	Presumed				Gaskets on old pipework					
22136	ACTIVE	P	N107-00-2/151	UMC - Station Building - Leicester Square Stn	Lead/Leading	Lead Paint/Lead	Known				UMC Access Area - RSJ: Yellow Gloss. Thickness 0.64mm: Analysis 6.41% Possibly painted over					
22137	ACTIVE	P	N107-00-2/151	UMC - Station Building - Leicester Square Stn	Lead/Leading	Lead Paint/Lead	Known				UMC Access Area - RSJ: Grey Gloss. Thickness 0.53mm: Analysis 1.43%					
22341	ACTIVE	P	N107-00-2/151/CLG-01	Ceiling: Solid - 1 - UMC - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Above chequered plate					
22135	ACTIVE	P	N107-00-2/151/CLG-02	Ceiling: Solid - 2 - UMC - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Above chequered plate					



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22338	ACTIVE	P	N107-00-2/151/WAL-001	Wall: Internal - 1 - UMC - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				High Level Supalux Panels by wall 2					
22339	ACTIVE	P	N107-00-2/151/WAL-002	Wall: Internal - 2 - UMC - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				High Level Supalux & Glass Panels					
23760	ACTIVE	P	N107-00-2/151/WAL-003	Wall: Internal - 3 - UMC - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				High Level Supalux & Glass Panels					
22340	ACTIVE	P	N107-00-2/151/WAL-004	Wall: Internal - 4 - UMC - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux panels above high level					
10267	ACTIVE	P	N107-00-2/152	UMC - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
22150	ACTIVE	P	N107-00-2/152	UMC - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	Presumed				UMC 12 & 3 - above Controller 2 - 2 x Concrete Cable Sleeve					
25810	ACTIVE	P	N107-00-2/152	UMC - Station Building - Leicester Square Stn	Gasket :Pipework	Asbestos	Presumed				Gaskets on old pipework					
22151	ACTIVE	P	N107-00-2/152	UMC - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	Presumed				UMC 12 & 3 - above Isolator 3 - 1 x Concrete Cable Sleeve (No access) Cables removed but duct present within ceiling slab					
22153	ACTIVE	P	N107-00-2/152	UMC - Station Building - Leicester Square Stn	Lead/Leading	Lead Paint/Lead	Known				Pipe: Red Gloss. Thickness to thin to measure: Analysis 5.25%					
22140	ACTIVE	P	N107-00-2/152/WAL-001	Wall: Internal - 1 - UMC - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				UMC Access Lobby - Supalux - high level					
22142	INACTIVE	P	N107-00-2/152/WAL-001	Wall: Internal - 1 - UMC - Station Building - Leicester Square Stn	Isolator Switches	Asbestos	Removed				UMC 12 & 3 - 2 x Switch Boxes - Insulation within		2			
22143	ACTIVE	P	N107-00-2/152/WAL-002	Wall: Internal - 2 - UMC - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	Presumed				UMC 12 & 3 - 9 x Concrete Cable Sleeve (No access)		9			
22144	ACTIVE	P	N107-00-2/152/WAL-002	Wall: Internal - 2 - UMC - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	Presumed				UMC 12 & 3 - 2m above ground 2 x Cable Sleeves - next to Fire Door (No access)		2			
22141	ACTIVE	P	N107-00-2/152/WAL-002	Wall: Internal - 2 - UMC - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				UMC Access Lobby - Supalux Boarding					
23741	INACTIVE	P	N107-00-2/152/WAL-003	Wall: Internal - 3 - UMC - Station Building - Leicester Square Stn	Isolator Switches	Asbestos	Removed				UMC 12 & 3 - 4 x Switch Boxes - Insulation within		4			



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23660	INACTIVE	P	N107-00-2/152/WAL-003	Wall: Internal - 3 - UMC - Station Building - Leicester Square Stn	Isolator Switches	Asbestos	Removed				UMC 12 & 3 - 2 x Switch Boxes - Insulation within		2			
22152	INACTIVE	P	N107-00-2/152/WAL-004	Wall: Internal - 4 - UMC - Station Building - Leicester Square Stn	Isolator Switches	Asbestos	Removed				UMC 12 & 3 - 4 x Switch Boxes - Insulation within		4			
22145	ACTIVE	P	N107-00-2/152/WAL-008	Wall: Internal - 8 - UMC - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	Presumed				UMC 12 & 3 - 5 x Concrete Cable Sleeve (No access) Above door 2/631		5			
22146	ACTIVE	P	N107-00-2/152/WAL-011	Wall: Internal - 11 - UMC - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	Presumed				UMC 12 & 3 - above 2/777 8 x Concrete Cable Sleeves (No access)		8			
22147	ACTIVE	P	N107-00-2/152/WAL-011	Wall: Internal - 11 - UMC - Station Building - Leicester Square Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				UMC 12 & 3 - Distribution Board Right of 2/777 2x to wall					
22148	ACTIVE	P	N107-00-2/152/WAL-011	Wall: Internal - 11 - UMC - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	Presumed				UMC 12 & 3 - 2 x Concrete Cable Sleeve (No access)		2			
22149	ACTIVE	P	N107-00-2/152/WAL-012	Wall: Internal - 12 - UMC - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	Presumed				UMC 12 & 3 - Ceiling by wall 2 - 2 x Concrete Cable Sleeve (No access) Render coming away no visible caulking		2			
43999	ACTIVE	P	N107-00-2/171	Escalator Incline - Station Building - Leicester Square Stn		Asbestos	Sampled – Not Detected				Dust/debris, throughout, to wall of central escalator incline (2/171) at Leicester Square Station			R597201	N	N
43998	ACTIVE	P	N107-00-2/171	Escalator Incline - Station Building - Leicester Square Stn		Asbestos	Sampled – Not Detected				Mastic debris, <1m, to wall of central escalator incline (2/171) at Leicester Square Station			R597201	N	N
22154	ACTIVE	P	N107-00-2/171	Escalator Incline - Station Building - Leicester Square Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
22155	ACTIVE	P	N107-00-2/172	Escalator Incline - Station Building - Leicester Square Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
44006	ACTIVE	P	N107-00-2/172	Escalator Incline - Station Building - Leicester Square Stn		Asbestos	Sampled – Not Detected				Dust/debris throughout to floor of central escalator incline			R597201	N	N
10268	ACTIVE	P	N107-00-2/236	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23742	ACTIVE	P	N107-00-2/236/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete to walls, all cables plastic, water pipes, CMS, Rockwool debris, Supalux Boarding debris - above false ceiling				Yes	
22157	ACTIVE	P	N107-00-2/236/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
22160	ACTIVE	P	N107-00-2/236/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Insulation Board panels above false ceiling				Yes	



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22159	ACTIVE	P	N107-00-2/236/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
22158	ACTIVE	P	N107-00-2/236/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Supalux Panel; all cables plastic, Fibreglass Lagged pipes & tank above false ceiling				Yes	
22156	ACTIVE	P	N107-00-2/236/FLR-01	Floor - 1 - Passage - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Beneath Computer and Linoleum Tiles					Yes
10269	ACTIVE	P	N107-00-2/237	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10270	ACTIVE	P	N107-00-2/238	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10271	ACTIVE	P	N107-00-2/239	Lobby - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22162	ACTIVE	P	N107-00-2/239/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
22163	ACTIVE	P	N107-00-2/239/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Above false ceiling					
22164	ACTIVE	P	N107-00-2/239/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Insulation Board panels above false ceiling				Yes	
22161	ACTIVE	P	N107-00-2/239/FLR-01	Floor - 1 - Lobby - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Steel Cable Ducts beneath Computer Tiles					Yes
10272	ACTIVE	P	N107-00-2/240	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10273	ACTIVE	P	N107-00-2/241	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22166	ACTIVE	P	N107-00-2/241/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete to ceiling, concrete to walls, all cables plastic, water pipes, rockwool lagging, supalux boarding debris, CMS Mastic to all concrete joints NADIS (Mastic found throughout all ceiling areas) above false ceiling				Yes	
22165	ACTIVE	P	N107-00-2/241/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
10274	ACTIVE	P	N107-00-2/242	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22167	ACTIVE	P	N107-00-2/242	Passage - Station Building - Leicester Square Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Rings - Caulking Sealed					
22168	ACTIVE	P	N107-00-2/242	Passage - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Known				4 x Cable Sleeves in Lift Chamber - Chrysotile					
10275	ACTIVE	P	N107-00-2/311	Office - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22170	ACTIVE	P	N107-00-2/311/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
22171	ACTIVE	P	N107-00-2/311/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete to ceiling, concrete / brick / breeze block to walls. All cables plastic, supalux boarding to concrete ceiling, water pipes, rockwool lagging, supalux boarding debris, conduits above false ceiling				Yes	
22169	ACTIVE	P	N107-00-2/311/FLR-01	Floor - 1 - Office - Station Building - Leicester Square Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Linoleum Tiles					
10276	ACTIVE	P	N107-00-2/401	Store - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10277	ACTIVE	P	N107-00-2/411	Store - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22173	ACTIVE	P	N107-00-2/411/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
23575	ACTIVE	P	N107-00-2/411/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete to ceiling & walls, all cables plastic, aircon ducting, rockwool lagging, master board to aircon motor above false ceiling				Yes	
22172	ACTIVE	P	N107-00-2/411/FLR-01	Floor - 1 - Store - Station Building - Leicester Square Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Linoleum Tiles					
10278	ACTIVE	P	N107-00-2/412	Store - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22177	ACTIVE	P	N107-00-2/412	Store - Station Building - Leicester Square Stn	Lead/Leading	Lead Paint/Lead	Known				Top Half of Wall: Cream Gloss. Thickness 0.30mm: Analysis 1.16%					
22176	ACTIVE	P	N107-00-2/412	Store - Station Building - Leicester Square Stn	Lead/Leading	Lead Paint/Lead	Known				Bottom half of wall: Green Gloss. Thickness 0.32mm: Analysis 2.09%. Over painted cream					
22175	ACTIVE	P	N107-00-2/412/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Panels					
23743	ACTIVE	P	N107-00-2/412/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Above false ceiling					



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22174	ACTIVE	P	N107-00-2/412/WAL-005	Wall: Internal - 5 - Store - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding					
10279	ACTIVE	P	N107-00-2/416	Shower Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22180	ACTIVE	P	N107-00-2/416/CLG-01	Ceiling: Suspended - 1 - Shower Room - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete ceiling, metal ductwork, plastic cables, breeze block, concrete walls, rockwool lagging to pipes, supalux debris to top of tiles, chipboard to walls above metal ceiling				Yes	
23744	ACTIVE	P	N107-00-2/416/CLG-02	Ceiling: Solid - 2 - Shower Room - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete ceiling, metal ductwork, plastic cables, breeze block, concrete walls, rockwool lagging to pipes, supalux debris to top of tiles, chipboard to walls above metal ceiling				Yes	
22178	ACTIVE	P	N107-00-2/416/FLR-01	Floor - 1 - Shower Room - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Beneath Hatch					Yes
22179	ACTIVE	P	N107-00-2/416/FLR-02	Floor - 2 - Shower Room - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Beneath Hatch					Yes
10280	ACTIVE	P	N107-00-2/417	Shower Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22183	ACTIVE	P	N107-00-2/417/CLG-01	Ceiling: Suspended - 1 - Shower Room - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above metal sheets				Yes	
22181	ACTIVE	P	N107-00-2/417/FLR-01	Floor - 1 - Shower Room - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Beneath Manholes					Yes
22182	ACTIVE	P	N107-00-2/417/FLR-02	Floor - 2 - Shower Room - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Beneath Manholes					Yes
10281	ACTIVE	P	N107-00-2/418	Toilet: Unisex - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22238	ACTIVE	P	N107-00-2/418	Toilet: Unisex - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Male Toilet - concrete to ceiling and walls, all cables plastic, conduits, CMS above Metal tiles				Yes	
10282	ACTIVE	P	N107-00-2/451	Office - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22241	ACTIVE	P	N107-00-2/451/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				Yes	



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22240	ACTIVE	P	N107-00-2/451/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
22239	ACTIVE	P	N107-00-2/451/WAL-004	Wall: Internal - 4 - Office - Station Building - Leicester Square Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard partition					
10283	ACTIVE	P	N107-00-2/452	Tenancy - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22242	ACTIVE	P	N107-00-2/452/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Vermiculite cladding (throughout). Metal pipework by wall 2 in false ceiling.				Yes	
10284	ACTIVE	P	N107-00-2/453	Tenancy - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22243	ACTIVE	P	N107-00-2/453/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Above metal tiles					
22244	INACTIVE	P	N107-00-2/453/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Above metal tiles					
10285	ACTIVE	P	N107-00-2/454	Tenancy - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22245	ACTIVE	P	N107-00-2/454	Tenancy - Station Building - Leicester Square Stn	Other Boarding	Asbestos	No Access: Presumed				Panels on the outside of cupboard in the corner of shop No access within 2020 re-inspection no key with SSO					
22246	ACTIVE	P	N107-00-2/454	Tenancy - Station Building - Leicester Square Stn	Other Boarding	Asbestos	Strongly Presumed				Material surrounding the front of entrance					
10286	ACTIVE	P	N107-00-2/455	Tenancy - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22248	ACTIVE	P	N107-00-2/455/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Leicester Square Stn	Other Boarding	Asbestos	Strongly Presumed				Tenancy - material surrounding the front of entrance					
22247	ACTIVE	P	N107-00-2/455/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Tenancy - Ceiling - no access above metal tiles					
10287	ACTIVE	P	N107-00-2/456	Station Control Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23952	ACTIVE	P	N107-00-2/456/CLG-01	Ceiling: Suspended - 1 - Station Control Room - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Restricted survey due to false ceiling being very close to concrete ceiling - all cables plastic, conduits, water pipes, CMS, above metal tiles				Yes	



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22249	ACTIVE	P	N107-00-2/456/FLR-01	Floor - 1 - Station Control Room - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
10288	ACTIVE	P	N107-00-2/457	ATM - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10289	ACTIVE	P	N107-00-2/458	Tenancy - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22250	ACTIVE	P	N107-00-2/458	Tenancy - Station Building - Leicester Square Stn	Other Boarding	Asbestos	Strongly Presumed				Boarding material & void behind to shop signage					
22251	ACTIVE	P	N107-00-2/458/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Above white grill					
10290	ACTIVE	P	N107-00-2/631	Stairs: Spiral - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22255	ACTIVE	P	N107-00-2/631	Stairs: Spiral - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				2x 5cmØ Cables right of stairs go through to 4/732		2			
22256	ACTIVE	P	N107-00-2/631	Stairs: Spiral - Station Building - Leicester Square Stn	Other Boarding	Asbestos	No Access: Presumed				Board Panel - Surrounding Pipes					
23751	ACTIVE	P	N107-00-2/631	Stairs: Spiral - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	Strongly Presumed				5 x Cable Sleeves (4x sleeves by 2/242, 1x sleeve in floor)		5			
22254	ACTIVE	P	N107-00-2/631	Stairs: Spiral - Station Building - Leicester Square Stn	Isolator Switches	Asbestos	Not Found during Inspection				1 x Switch Box - Insulation within Not able to find during 2020 re-inspection - assume removed		1			
23752	ACTIVE	P	N107-00-2/631	Stairs: Spiral - Station Building - Leicester Square Stn	Other Boarding	Asbestos	Known				2x0.5 High level panel boarding near CER		2			
22252	ACTIVE	P	N107-00-2/631/CLG-01	Ceiling: Suspended - 1 - Spiral Stairs - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Solid, Concrete, Steel; Chipboard/ Hardboard above false ceiling				Yes	
22253	ACTIVE	P	N107-00-2/631/CLG-01	Ceiling: Suspended - 1 - Spiral Stairs - Station Building - Leicester Square Stn	Void	Asbestos	Sampled – Not Detected				1x 0.5 High level panel boarding near CER NADIS - above false ceiling				Yes	
10291	ACTIVE	P	N107-00-2/632	Stairs: Spiral - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22257	ACTIVE	P	N107-00-2/632/FLR-01	Floor - 1 - Spiral Stairs - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Board - Foot of Stairs					
22258	ACTIVE	P	N107-00-2/632/FLR-01	Floor - 1 - Spiral Stairs - Station Building - Leicester Square Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Beneath false floor					



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10292	ACTIVE	P	N107-00-2/661	Equipment Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10293	ACTIVE	P	N107-00-2/662	Switch Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25743	ACTIVE	P	N107-00-2/662/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Leicester Square Stn	Isolator Switches	Asbestos	Strongly Presumed				1x Switchbox - Insulation within strongly presumed No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
23753	ACTIVE	P	N107-00-2/662/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Leicester Square Stn	Isolator Switches	Asbestos	Strongly Presumed				7 x Switch Boxes - Insulation within (5x60amps, 2x100amps, 2x30amps)		7			
22259	ACTIVE	P	N107-00-2/662/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Panels, Centre of Room Supalux Column					
25744	ACTIVE	P	N107-00-2/662/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Leicester Square Stn	Isolator Switches	Asbestos	Strongly Presumed				1x Switchbox - Insulation within strongly presumed No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
10294	ACTIVE	P	N107-00-2/663	Switch Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22260	ACTIVE	P	N107-00-2/663/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Leicester Square Stn	Isolator Switches	Asbestos	Strongly Presumed				8 x Switch Boxes - Insulation within (4x 60amps, 3x 100amps, 1x 200amps) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		8			
25745	ACTIVE	P	N107-00-2/663/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Leicester Square Stn	Isolator Switches	Asbestos	Strongly Presumed				1x Switch box - Insulation within (1x 100amps) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
25746	ACTIVE	P	N107-00-2/663/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Leicester Square Stn	Isolator Switches	Asbestos	Strongly Presumed				1x Switchbox - Insulation within (1x 60amps) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
10295	ACTIVE	P	N107-00-2/664	Equipment Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10296	ACTIVE	P	N107-00-2/665	Switch Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25747	ACTIVE	P	N107-00-2/665/FLR-01	Floor - 1 - Switch Room - Station Building - Leicester Square Stn	Other Electrical Boxes	Asbestos	Presumed				2x Transformer boxes on floor by Wall 1&2 No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		2			
22261	ACTIVE	P	N107-00-2/665/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Leicester Square Stn	Isolator Switches	Asbestos	Strongly Presumed				8 x Switch Boxes - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		8			
10297	ACTIVE	P	N107-00-2/666	Switch Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22263	ACTIVE	P	N107-00-2/666/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Leicester Square Stn	Isolator Switches	Asbestos	Strongly Presumed				Wall 2 - 1 x Switch Box - Insulation within (1x30amps) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
22262	ACTIVE	P	N107-00-2/666/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Panel					
25748	ACTIVE	P	N107-00-2/666/WAL-002 80858236	Wall: Internal - 2 - Switch Room - Station Building - Leicester Square Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				3x Transformer box - Insulation within presumed middle box has been replaced No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		3			
25749	ACTIVE	P	N107-00-2/666/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Leicester Square Stn	Other Electrical Boxes	Asbestos	Presumed				Wall 3 - 3x Transformer boxes No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		3			
22264	ACTIVE	P	N107-00-2/666/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Leicester Square Stn	Isolator Switches	Asbestos	Strongly Presumed				Wall 3 - 1 x Switch Boxes - Insulation within (1x30amps) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
10298	ACTIVE	P	N107-00-2/667	Switch Cupboard - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22265	ACTIVE	P	N107-00-2/667	Switch Cupboard - Station Building - Leicester Square Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x Switch Boxes - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		2			
10299	ACTIVE	P	N107-00-2/746	SCR - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22266	ACTIVE	P	N107-00-2/746/FLR-01	Floor - 1 - SCR - Station Building - Leicester Square Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Marley White Tiles					
10300	ACTIVE	P	N107-00-2/761	Transformer Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10301	ACTIVE	P	N107-00-2/771	Pump Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22267	ACTIVE	P	N107-00-2/771/FLR-01	Floor - 1 - Pump Room - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Beneath Manholes					Yes
10302	ACTIVE	P	N107-00-2/776	Fan Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10303	ACTIVE	P	N107-00-2/777	Fan Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22269	ACTIVE	P	N107-00-2/777	Fan Room - Station Building - Leicester Square Stn	Isolator Switches	Asbestos	Not Found during Inspection				1 x Switch Box - Insulation within Not present 2020 re-inspection unable to locate - presumed removed.		1			
22268	ACTIVE	P	N107-00-2/777/FLR-01	Floor - 1 - Fan Room - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Hatch - Concrete, Tunnel Rings beneath hatch					Yes
10304	ACTIVE	P	N107-00-2/952	Disused Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10305	ACTIVE	P	N107-00-2/954	CER - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22270	ACTIVE	P	N107-00-2/954	CER - Station Building - Leicester Square Stn	Isolator Switches	Asbestos	Strongly Presumed				Back of Room 1no Switch Boxes - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
10306	ACTIVE	P	N107-00-2/955	Disused Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10307	ACTIVE	P	N107-00-2/981	Disused Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22271	ACTIVE	P	N107-00-2/981/WAL-003	Wall: Internal - 3 - Disused Room - Station Building - Leicester Square Stn	Isolator Switches	Asbestos	No Access: Presumed				1 x Switch Box behind metal grating - Insulation within No access as part of sub station transformer room. no part of 2020 re-inspection No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
45222	ACTIVE	P	N107-00-2/981/WAL-004	Wall: Internal - 4 - Disused Room - Station Building - Leicester Square Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				6x Flashguards within Combination Fuse Switch		6		N	N
10308	ACTIVE	P	N107-00-3/081	Circulation Area - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10309	ACTIVE	P	N107-00-3/161	LMC - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22273	ACTIVE	P	N107-00-3/161/WAL-003	Wall: Internal - 3 - LMC - Station Building - Leicester Square Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Cable Ducts 2x3					
22272	ACTIVE	P	N107-00-3/161/WAL-003	Wall: Internal - 3 - LMC - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Bituminous Cable duct next to Esc 6 by Ceiling		1			
10310	ACTIVE	P	N107-00-3/201	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22274	ACTIVE	P	N107-00-3/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Non asbestos firebreaks with rock wool at ends of passageway above false ceiling				Yes	
10311	ACTIVE	P	N107-00-3/411	Disused Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22275	ACTIVE	P	N107-00-3/411/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Non asbestos firebreaks with rock wool at ends of passageway above false ceiling				Yes	
10312	ACTIVE	P	N107-00-3/601	Stairs: Linear - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23953	ACTIVE	P	N107-00-3/601/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Above metal sheets				Yes	



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10313	ACTIVE	P	N107-00-3/602	Stairs: Linear - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22276	ACTIVE	P	N107-00-3/602/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Above metal sheets				Yes	
22277	ACTIVE	P	N107-00-3/602/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Plaster on plastic mesh, concrete above false ceiling				Yes	
10314	ACTIVE	P	N107-00-3/603	Stairs: Linear - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10315	ACTIVE	P	N107-00-3/633	Stairs: Spiral - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45223	ACTIVE	P	N107-00-3/633	Stairs: Spiral - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables present between 3/633 & 5/239				N	N
10316	ACTIVE	P	N107-00-3/731	CER - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22281	ACTIVE	P	N107-00-3/731/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Board					
22278	ACTIVE	P	N107-00-3/731/WAL-001	Wall: Internal - 1 - CER - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding outside rear of fire exit door, Supalux panels blocking doorway					
22280	ACTIVE	P	N107-00-3/731/WAL-002	Wall: Internal - 2 - CER - Station Building - Leicester Square Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x Grey Switch Boxes behind metal grating - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		2			
22279	ACTIVE	P	N107-00-3/731/WAL-002	Wall: Internal - 2 - CER - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding outside rear of fire exit door, Supalux panels blocking doorway					
10317	ACTIVE	P	N107-00-3/732	Switch Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22282	ACTIVE	P	N107-00-3/732	Switch Room - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Panels					
22283	ACTIVE	P	N107-00-3/732/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux panels to side of stair					
22284	ACTIVE	P	N107-00-3/732/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Above Supalux panels				Yes	



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23754	ACTIVE	P	N107-00-3/732/FLR-01	Floor - 1 - Switch Room - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
10318	ACTIVE	P	N107-00-3/901	Disused Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10319	ACTIVE	P	N107-00-3/902	Disused Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10320	ACTIVE	P	N107-00-3/903	Disused Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10321	ACTIVE	P	N107-00-4/201	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10322	ACTIVE	P	N107-00-4/202	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10323	ACTIVE	P	N107-00-4/203	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10324	ACTIVE	P	N107-00-4/204	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
69712	ACTIVE	P	N107-00-4/204	Passage - Station Building - Leicester Square Stn	Other Boarding	Asbestos	Sampled – Not Detected				Insulation board (2 x 1sqm) behind frieze panels to Platform 3	2		R679602		
22285	ACTIVE	P	N107-00-4/204/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Leicester Square Stn	Other Boarding	Asbestos	Strongly Presumed				Board inside, the under side of the hatch, not sampled contractors in area No access 2020 re-inspection into False ceiling as large ve panles and fixed.					
23755	ACTIVE	P	N107-00-4/204/CLG-01 80858925	Ceiling: Solid - 1 - Passage - Station Building - Leicester Square Stn Ceiling: Solid	Void	Asbestos	Surveyed – Not Detected				Solid, concrete above false ceiling				Yes	
10325	ACTIVE	P	N107-00-4/205	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10326	ACTIVE	P	N107-00-4/263	Platform 3 - Southbound Local - Northern Line - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45224	ACTIVE	P	N107-00-4/263	Platform 3 - Southbound Local - Northern Line - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				Arrivals End - Braided Cables in J Hanger, North End				N	N



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22289	INACTIVE	p	N107-00-4/263	Platform 3 - Southbound Local - Northern Line - Station Building - Leicester Square Stn		Asbestos	Removed				Arrivals End - 2x jumper cables southbound BRS 26 trackside		2			
22287	ACTIVE	p	N107-00-4/263	Platform 3 - Southbound Local - Northern Line - Station Building - Leicester Square Stn		Asbestos	Removed				Mid Point - There are asbestos ducts present under track crossing					
22187	ACTIVE	p	N107-00-4/263	Platform 3 - Southbound Local - Northern Line - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Presumed				Platform 3 Invert - 2x Braided cables - up to 4/771 via concrete ducts No access during 2020 re-inspection as confined space team required		2			
22186	ACTIVE	p	N107-00-4/263	Platform 3 - Southbound Local - Northern Line - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Presumed				Platform 3 Invert - 2x Braided Cable Pit Wall under 5/604 No access during 2020 re-inspection as confined space team required		2			
22184	ACTIVE	p	N107-00-4/263	Platform 3 - Southbound Local - Northern Line - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Presumed				Arrivals End - 1x Braided cable Head Wall trackside - j hanger 2		1			
25741	ACTIVE	p	N107-00-4/263	Platform 3 - Southbound Local - Northern Line - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	Presumed				Mid Point - There are asbestos ducts present UTX No access during 2020 re-inspection as confined space team required					
25740	ACTIVE	p	N107-00-4/263	Platform 3 - Southbound Local - Northern Line - Station Building - Leicester Square Stn	Void	Asbestos	Removed				Mid Point - Asbestos possible where cables disappear behind poster				N	N
22286	INACTIVE	p	N107-00-4/263	Platform 3 - Southbound Local - Northern Line - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	Removed				Mid Point - Possible where cables disappear behind poster. Asbestos Ducts present UTX					
22189	ACTIVE	p	N107-00-4/263	Platform 3 - Southbound Local - Northern Line - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Presumed				Platform 3 Invert - 2 x braided cables - 2 cables pitwall up to 4/711 and 1 out of 4/711 up to 4/712 No access during 2020 re-inspection as confined space team required		2			
22288	ACTIVE	p	N107-00-4/263	Platform 3 - Southbound Local - Northern Line - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Arrivals End - Supalux fire breaks at end behind panels					
22188	ACTIVE	p	N107-00-4/263	Platform 3 - Southbound Local - Northern Line - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Presumed				Platform 3 Invert - 2x Braided Cable - wall down stairs to passage between inverts under 5/604 No access during 2020 re-inspection as confined space team required		2			
22185	ACTIVE	p	N107-00-4/263	Platform 3 - Southbound Local - Northern Line - Station Building - Leicester Square Stn	Lead/Leading	Lead Paint/Lead	Known				Grit Box: Black Gloss. Thickness 1.18mm: Analysis 3.48%					



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44385	ACTIVE	p	N107-00-4/263	Platform 3 - Southbound Local - Northern Line - Station Building - Leicester Square Stn	Lead/Leading	Lead Paint/Lead	Known				Lead Cable – throughout section trackside - Please note that lead sheathed cabling has been identified throughout this section. If planning to remove these cables then a suitable and sufficient risk assessment must be undertaken to mitigate from the risk of exposure					
10327	ACTIVE	p	N107-00-4/264	Platform 4 - Northbound Local - Northern Line - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22191	INACTIVE	p	N107-00-4/264	Platform 4 - Northbound Local - Northern Line - Station Building - Leicester Square Stn		Asbestos	Removed				1x Braided cable - J hanger 3 trackside southend		1			
23576	INACTIVE	p	N107-00-4/264	Platform 4 - Northbound Local - Northern Line - Station Building - Leicester Square Stn		Asbestos	Removed				4x Braided Cables - J hangers 2&4 - trackside		4			
45227	ACTIVE	p	N107-00-4/264	Platform 4 - Northbound Local - Northern Line - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				Arrivals End SB - Asbestos - SP - 3x Braided Cables in J Hanger		3		N	N
45226	ACTIVE	p	N107-00-4/264	Platform 4 - Northbound Local - Northern Line - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				Departure End NB - 3x Braided Cables in J Hanger		3		N	N
22194	ACTIVE	p	N107-00-4/264	Platform 4 - Northbound Local - Northern Line - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Presumed				Platform 4 Invert - Approx. 11 x Cables No access during 2020 re-inspection as confined space team required		11			
22193	ACTIVE	p	N107-00-4/264	Platform 4 - Northbound Local - Northern Line - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	Presumed				Platform 4 Invert - 11 x Cable Sleeves - Chrysotile No access during 2020 re-inspection as confined space team required		11			
22190	ACTIVE	p	N107-00-4/264	Platform 4 - Northbound Local - Northern Line - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Departure End NB - 2m2 Boarding - Supalux – broken in 4 pieces					
22192	INACTIVE	p	N107-00-4/264	Platform 4 - Northbound Local - Northern Line - Station Building - Leicester Square Stn	Cement Troughing	Asbestos	Removed				Cement troughing (3m length) at south end - Chrysotile					
45225	ACTIVE	p	N107-00-4/264	Platform 4 - Northbound Local - Northern Line - Station Building - Leicester Square Stn	Lead/Leading	Lead Paint/Lead	Known				Lead Cable – throughout section trackside - Please note that lead sheathed cabling has been identified throughout this section. If planning to remove these cables then a suitable and sufficient risk assessment must be undertaken to mitigate from the risk of exposure				N	N
10328	ACTIVE	p	N107-00-4/401	Disused Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10329	ACTIVE	P	N107-00-4/411	Store - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10330	ACTIVE	P	N107-00-4/412	Store - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10331	ACTIVE	P	N107-00-4/601	Stairs: Linear - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10332	ACTIVE	P	N107-00-4/602	Stairs: Linear - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22196	ACTIVE	P	N107-00-4/602/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Above ceiling - at entrance concrete, quarry tiles & rubber cables				Yes	
22195	ACTIVE	P	N107-00-4/602/FLR-01	Floor - 1 - Linear Stairs - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Beneath Hatch					Yes
10333	ACTIVE	P	N107-00-4/603	Stairs: Linear - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22197	ACTIVE	P	N107-00-4/603/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Above ceiling - top entrance - concrete, quarry tiles; rubber & metal pipes				Yes	
10334	ACTIVE	P	N107-00-4/661	Switch Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22198	ACTIVE	P	N107-00-4/661/FLR-01 80858792	Floor - 1 - Switch Room - Station Building - Leicester Square Stn Floor	Void	Asbestos	No Access: Presumed				Cable ducts in middle of the floor					Yes
10335	ACTIVE	P	N107-00-4/663	Switch Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10336	ACTIVE	P	N107-00-4/664	Switch Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
22203	ACTIVE	P	N107-00-4/664	Switch Room - Station Building - Leicester Square Stn	Lead/Leading	Lead Paint/Lead	Known				Bottom of Walls: Brown Gloss. Thickness 0.95mm: Analysis 3.67%					
22201	ACTIVE	P	N107-00-4/664/FLR-01	Floor - 1 - Switch Room - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	Sampled – Not Detected				6 x Cable Sleeves on Floor - 3 x Ceramic and 3 filled in. Using ACE Invert Report that sampled the ducts from below PFH established filled in ducts are non asbestos		6			



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25750	ACTIVE	P	N107-00-4/664/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Leicester Square Stn	Other Electrical Boxes	Asbestos	Presumed				Wall 1 - 1x Transformer Box - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
22202	ACTIVE	P	N107-00-4/664/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				Green Cables 5cm to 600v		2			
22199	ACTIVE	P	N107-00-4/664/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Leicester Square Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Distribution Board - insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.					
22200	ACTIVE	P	N107-00-4/664/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Leicester Square Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Wall 3 - Insulation within Electrical equipment No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.					
23745	ACTIVE	P	N107-00-4/664/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Leicester Square Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Trunking - Insulation within Missing presume 4x CFS to wall No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.					
10337	ACTIVE	P	N107-00-4/711	Lobby - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10338	ACTIVE	P	N107-00-4/712	Relay Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23661	ACTIVE	P	N107-00-4/712/FLR-01	Floor - 1 - Relay Room - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	Sampled – Not Detected				8 x Cable Sleeves - no access - filled in by Wall 3 &4 Using ACE Invert Report that sampled the ducts from below PFH established filled in ducts are non asbestos		8			
22205	ACTIVE	P	N107-00-4/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Leicester Square Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Wall 1 - 1x Rectifier box high level - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
22206	INACTIVE	P	N107-00-4/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Leicester Square Stn		Asbestos	Removed				3 x cables		3			



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22204	ACTIVE	P	N107-00-4/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				2x 50mm diameter green cables from 600v Box and 2x 5mm diameter cables to Wall 4 (Cables start on Wall 4 and lead onto Wall 3 and run down into the invert via filled in ducts on the floor		4			
23746	ACTIVE	P	N107-00-4/712/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				2x 50mm diameter green cables from 600v Box and 2x 5mm diameter cables to Wall 4 (Cables start on Wall 4 and lead onto Wall 3 and run down into the invert via filled in ducts on the floor					
10339	ACTIVE	P	N107-00-4/714	Relay Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22207	ACTIVE	P	N107-00-4/714	Relay Room - Station Building - Leicester Square Stn	Lead/Leading	Lead Paint/Lead	Known				Bottom of Walls: Brown Gloss. Thickness 0.95mm: Analysis 3.67%					
25761	ACTIVE	P	N107-00-4/714/FLR-01	Floor - 1 - Relay Room - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	Presumed				Floor on Wall 1 within roller shutter cabinet - Cable sleeves (Braided cables feed into cable sleeve)					
25762	ACTIVE	P	N107-00-4/714/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				Wall 1 - Braided cables bunched with PVC cables within roller shutter cabinet. At least two visible which run into cement ducts within floor					
25754	INACTIVE	P	N107-00-4/714/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Leicester Square Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				Approx 18x PCB's within roller shutter cupboard					
25767	ACTIVE	P	N107-00-4/714/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Leicester Square Stn	Other Electrical Boxes	Asbestos	Presumed				Wall 2 - 1x Electrical box - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.					
25763	ACTIVE	P	N107-00-4/714/WAL-002 80858830	Wall: Internal - 2 - Relay Room - Station Building - Leicester Square Stn Wall: Internal	Cable: Sheath	Asbestos	Strongly Presumed				Wall 2 - 2x Braided cables from 600v electrical box which run down into invert & wall 3 x2					
25766	ACTIVE	P	N107-00-4/714/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Leicester Square Stn	Other Electrical Boxes	Asbestos	Presumed				Wall 2 - 1x Electrical box - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.					
25765	ACTIVE	P	N107-00-4/714/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				Wall 3 - Braided cable bunched with PVC cables within roller shutter cabinet					
25768	ACTIVE	P	N107-00-4/714/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	Presumed				Wall 3 - Cable ducts within roller shutter cabinet					
25764	INACTIVE	P	N107-00-4/714/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Leicester Square Stn	PCBs	Polychlorinated biphenyl	Presumed				Wall 3 - Approx 8x PCB's within roller shutter cabinet					



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10340	ACTIVE	P	N107-00-4/731	Disused Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23747	ACTIVE	P	N107-00-4/731/WAL-001	Wall: Internal - 1 - Disused Room - Station Building - Leicester Square Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse Box - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
10341	ACTIVE	P	N107-00-4/732	CER - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22211	ACTIVE	P	N107-00-4/732	CER - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				2 x cables from stair wall to room		2			
22208	ACTIVE	P	N107-00-4/732/FLR-01	Floor - 1 - CER - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Concrete Floor Below Computer Floor Tiles No Known Asbestos, however not all areas may have accessed during the asbestos survey.					Yes
22209	ACTIVE	P	N107-00-4/732/WAL-002	Wall: Internal - 2 - CER - Station Building - Leicester Square Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x Switch Box - Insulation within (1x60amps) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
22210	ACTIVE	P	N107-00-4/732/WAL-002	Wall: Internal - 2 - CER - Station Building - Leicester Square Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Distribution Board - insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.					
10342	ACTIVE	P	N107-00-5/081	Circulation Area - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22212	ACTIVE	P	N107-00-5/081/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Plaster above steel panels				Yes	
10343	ACTIVE	P	N107-00-5/161	LMC - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22215	ACTIVE	P	N107-00-5/161	LMC - Station Building - Leicester Square Stn	Cable Duct: Other	Asbestos	Presumed				12 x Cable Sleeves (No access)		12			
22216	ACTIVE	P	N107-00-5/161	LMC - Station Building - Leicester Square Stn	Gasket :Pipework	Asbestos	Presumed				Vent Sprinkler System 5 x Gaskets (No access)		5			
22214	ACTIVE	P	N107-00-5/161/CLG-01	Ceiling: Solid - 1 - LMC - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Above metal girders				Yes	
22213	ACTIVE	P	N107-00-5/161/FLR-01	Floor - 1 - LMC - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Beneath Manholes					Yes



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10344	ACTIVE	P	N107-00-5/201	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22217	ACTIVE	P	N107-00-5/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above steel panels				Yes	
10345	ACTIVE	P	N107-00-5/202	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22218	ACTIVE	P	N107-00-5/202/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Plaster above steel				Yes	
10346	ACTIVE	P	N107-00-5/203	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10347	ACTIVE	P	N107-00-5/204	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23951	ACTIVE	P	N107-00-5/204/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above steel panels				Yes	
10348	ACTIVE	P	N107-00-5/205	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22219	ACTIVE	P	N107-00-5/205/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Plaster, solid above steel panels				Yes	
10349	ACTIVE	P	N107-00-5/206	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22220	ACTIVE	P	N107-00-5/206/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Plaster, concrete above steel panels				Yes	
10350	ACTIVE	P	N107-00-5/207	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22221	ACTIVE	P	N107-00-5/207/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Plaster, concrete above steel panels				Yes	
10351	ACTIVE	P	N107-00-5/208	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22222	ACTIVE	P	N107-00-5/208/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Plaster, Solid, PVC cables above steel panels				Yes	



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10352	ACTIVE	P	N107-00-5/209	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10353	ACTIVE	P	N107-00-5/236	Lobby - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10354	ACTIVE	P	N107-00-5/237	Lobby - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22226	ACTIVE	P	N107-00-5/237	Lobby - Station Building - Leicester Square Stn	Lead/Leading	Lead Paint/Lead	Known				RJS: Black Matt. Thickness 0.23mm: Analysis 5.29%					
22224	ACTIVE	P	N107-00-5/237/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
22223	ACTIVE	P	N107-00-5/237/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Leicester Square Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
22225	ACTIVE	P	N107-00-5/237/DOR-01	Door - 1 - Lobby - Station Building - Leicester Square Stn	Lead/Leading	Lead Paint/Lead	Known				Door Handle: Black Gloss. Thickness Dust: Analysis 8.77%					
10355	ACTIVE	P	N107-00-5/238	Lobby - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23748	ACTIVE	P	N107-00-5/238/FLR-01	Floor - 1 - Lobby - Station Building - Leicester Square Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Marley Tiles					
22227	ACTIVE	P	N107-00-5/238/WAL-004	Wall: Internal - 4 - Lobby - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux/Wood Panel					
10356	ACTIVE	P	N107-00-5/239	Lobby - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22229	ACTIVE	P	N107-00-5/239	Lobby - Station Building - Leicester Square Stn	Boarding: Cement	Asbestos	Strongly Presumed				Cement Panel through Ducts - Panel is 10m above head from stairs High level unable to gain full access during 2020 re-inspection					
22228	ACTIVE	P	N107-00-5/239	Lobby - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				2 x Braided Cables		2			
23662	ACTIVE	P	N107-00-5/239/WAL-001	Wall: Internal - 1 - Lobby - Station Building - Leicester Square Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x Grey Switch Box - Insulation within (1x60amps) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
10357	ACTIVE	P	N107-00-5/316	Locker Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22230	ACTIVE	P	N107-00-5/316/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Above false ceiling				Yes	
23749	ACTIVE	P	N107-00-5/316/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux					
10358	ACTIVE	P	N107-00-5/376	Equipment Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22231	ACTIVE	P	N107-00-5/376/WAL-003	Wall: Internal - 3 - Equipment Room - Station Building - Leicester Square Stn	Bitumen	Asbestos	Surveyed – Not Detected				Acoustic Panel under Sink		1			
10359	ACTIVE	P	N107-00-5/381	SER - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22232	ACTIVE	P	N107-00-5/381/CLG-01	Ceiling: Solid - 1 - SER - Station Building - Leicester Square Stn	Void	Asbestos	Removed				Above false ceiling				Yes	
10360	ACTIVE	P	N107-00-5/382	Locker Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22233	ACTIVE	P	N107-00-5/382	Locker Room - Station Building - Leicester Square Stn	Bitumen	Asbestos	Surveyed – Not Detected				Acoustic Panel under Sink		1			
10361	ACTIVE	P	N107-00-5/383	Disused Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23750	ACTIVE	P	N107-00-5/383/FLR-01	Floor - 1 - Disused Room - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Beneath manhole					Yes
10362	ACTIVE	P	N107-00-5/406	Store - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22234	ACTIVE	P	N107-00-5/406/WAL-002	Wall: Internal - 2 - Store - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Panels around Cables					
22235	ACTIVE	P	N107-00-5/406/WAL-003	Wall: Internal - 3 - Store - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Cupboard Supalux Lined					
10363	ACTIVE	P	N107-00-5/407	Store - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22345	ACTIVE	P	N107-00-5/407/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Leicester Square Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22346	ACTIVE	P	N107-00-5/407/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard				Yes	
22236	ACTIVE	P	N107-00-5/407/FLR-01	Floor - 1 - Store - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	No Access: Presumed				7 x Cable Sleeves (No access)		7			
22343	ACTIVE	P	N107-00-5/407/WAL-001	Wall: Internal - 1 - Store - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	No Access: Presumed				3 x Cable Sleeves (No access)		3			
22237	ACTIVE	P	N107-00-5/407/WAL-003	Wall: Internal - 3 - Store - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux					
22344	ACTIVE	P	N107-00-5/407/WAL-003	Wall: Internal - 3 - Store - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	No Access: Presumed				7 x Cable Sleeves (No access)		7			
22342	ACTIVE	P	N107-00-5/407/WAL-007	Wall: Internal - 7 - Store - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux, Chipboard, Breeze Block					
10364	ACTIVE	P	N107-00-5/601	Stairs: Linear - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22347	ACTIVE	P	N107-00-5/601/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above steel panels				Yes	
10365	ACTIVE	P	N107-00-5/602	Stairs: Linear - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22348	ACTIVE	P	N107-00-5/602/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above steel panels				Yes	
10366	ACTIVE	P	N107-00-5/603	Stairs: Linear - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22350	ACTIVE	P	N107-00-5/603/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Plaster, Concrete above steel panels				Yes	
22349	ACTIVE	P	N107-00-5/603/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above steel panels				Yes	
10367	ACTIVE	P	N107-00-5/604	Stairs: Linear - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10368	ACTIVE	P	N107-00-5/605	Stairs: Linear - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22351	ACTIVE	P	N107-00-5/605	Stairs: Linear - Station Building - Leicester Square Stn	Lead/Leading	Lead Paint/Lead	Known				Gates: Grey Gloss. Thickness 0.15mm: Analysis 3.44%					
23577	ACTIVE	P	N107-00-5/605/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Above Ducting, Rubber Cables				Yes	
22352	ACTIVE	P	N107-00-5/636/CLG-01	Ceiling: Solid - 1 - Overbridge - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above steel panels				Yes	
22353	ACTIVE	P	N107-00-5/637/CLG-01	Ceiling: Solid - 1 - Overbridge - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Brick above steel panels				Yes	
22354	ACTIVE	P	N107-00-5/638/CLG-01	Ceiling: Solid - 1 - Overbridge - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above steel panels				Yes	
10369	ACTIVE	P	N107-00-5/661	Switch Cupboard - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10370	ACTIVE	P	N107-00-5/662	Switch Cupboard - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10371	ACTIVE	P	N107-00-5/663	Switch Cupboard - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10372	ACTIVE	P	N107-00-5/751	Mess Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22355	ACTIVE	P	N107-00-5/751/FLR-01	Floor - 1 - Mess Room - Station Building - Leicester Square Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Marley Tiles - non asbestos					
22356	ACTIVE	P	N107-00-5/751/WAL-002	Wall: Internal - 2 - Mess Room - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Boards					
10373	ACTIVE	P	N107-00-5/761	Equipment Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23761	ACTIVE	P	N107-00-5/761	Equipment Room - Station Building - Leicester Square Stn	Lead/Leading	Lead Paint/Lead	Known				All Walls: Yellow Gloss. Thickness 0.67mm: Analysis 3.00% over painted in white					
22357	ACTIVE	P	N107-00-5/761/FLR-01	Floor - 1 - Equipment Room - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Plastic Cables, Concrete beneath manhole					Yes
22358	ACTIVE	P	N107-00-5/761/WAL-001	Wall: Internal - 1 - Equipment Room - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux panel					



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22359	ACTIVE	P	N107-00-5/761/WAL-003	Wall: Internal - 3 - Equipment Room - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux panel					
10374	ACTIVE	P	N107-00-5/762	Equipment Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22360	ACTIVE	P	N107-00-5/762	Equipment Room - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Panel above door to 5/786					
10375	ACTIVE	P	N107-00-5/771	Pump Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22361	ACTIVE	P	N107-00-5/771/DOR-01	Door - 1 - Pump Room - Station Building - Leicester Square Stn	Lead/Leading	Lead Paint/Lead	Removed				Door Frame: Green Matt. Thickness 0.22mm: Analysis 1.55%					
10376	ACTIVE	P	N107-00-5/776	Fan Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22364	ACTIVE	P	N107-00-5/776	Fan Room - Station Building - Leicester Square Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x Switch Box - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
22363	ACTIVE	P	N107-00-5/776	Fan Room - Station Building - Leicester Square Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Caulking - Encapsulated Iron Fillings					
23762	ACTIVE	P	N107-00-5/776	Fan Room - Station Building - Leicester Square Stn	Rope Gaskets	Asbestos	Surveyed – Not Detected				Vent Exhaust Shaft - Inspection Hatch Gasket - Non Asbestos					
22362	ACTIVE	P	N107-00-5/776/FLR-01	Floor - 1 - Fan Room - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Flooded beneath manholes					Yes
10377	ACTIVE	P	N107-00-5/786	Service Riser - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22365	ACTIVE	P	N107-00-5/786	Service Riser - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Board Panel					
10378	ACTIVE	P	N107-00-5/951	Disused Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10379	ACTIVE	P	N107-00-5/952	Disused Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22366	INACTIVE	P	N107-00-5/952/FLR-01	Floor - 1 - Disused Room - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Flooded beneath false floor					Yes
10380	ACTIVE	P	N107-00-5/953	Office - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22367	ACTIVE	P	N107-00-5/953	Office - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Panels to Doors to 5/786					
22368	ACTIVE	P	N107-00-5/953	Office - Station Building - Leicester Square Stn	Isolator Switches	Asbestos	No Access: Presumed				1 x Switch Box - Insulation within - labelled 'clock' has Siluminite backing panel inside. Equipment live so no sample possible		1			
23763	ACTIVE	P	N107-00-5/953/ WAL-001	Wall: Internal - 1 - Office - Station Building - Leicester Square Stn	Other Boarding	Asbestos	Not Found during Inspection				Shelf (Headway Lock Relay Shelf) Removed not present 2020 re-inspection					
10381	ACTIVE	P	N107-00-5/986	Disused Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23981	ACTIVE	P	N107-00-5/986/ CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Leicester Square Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel Ring Caulking - Throughout to joints behind wood packing					
10382	ACTIVE	P	N107-00-6/201	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22421	ACTIVE	P	N107-00-6/201/ CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above steel panels				Yes	
10383	ACTIVE	P	N107-00-6/202	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22422	ACTIVE	P	N107-00-6/202/ CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above steel panels				Yes	
10384	ACTIVE	P	N107-00-6/203	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22423	ACTIVE	P	N107-00-6/203	Passage - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux behind metal side panel					
22424	ACTIVE	P	N107-00-6/203/ CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Steel Panel				Yes	
10385	ACTIVE	P	N107-00-6/204	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22426	ACTIVE	P	N107-00-6/204/ CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Leicester Square Stn	Void	Asbestos	No Access: Presumed				Above Supalux panels				Yes	
22425	ACTIVE	P	N107-00-6/204/ CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Panel by Platform 2					



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10386	ACTIVE	p	N107-00-6/205	Passage - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10387	ACTIVE	p	N107-00-6/261	Platform 1 - Westbound Local - Piccadilly Line - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22438	ACTIVE	p	N107-00-6/261	Platform 1 - Westbound Local - Piccadilly Line - Station Building - Leicester Square Stn		Asbestos	Sampled – Not Detected				Platform 1 Invert - Bitumen cable duct to head wall - NADIS					
22436	ACTIVE	p	N107-00-6/261	Platform 1 - Westbound Local - Piccadilly Line - Station Building - Leicester Square Stn		Asbestos	Sampled – Not Detected				Platform 1 Invert - 7x Bitumen cable ducts to tail wall end and under track - NADIS		7			
22435	ACTIVE	p	N107-00-6/261	Platform 1 - Westbound Local - Piccadilly Line - Station Building - Leicester Square Stn	Westing house Boxes	Asbestos	Strongly Presumed				Platform 1 Invert - 4 x Westinghouse Boxing - Insulation within		4			
22433	ACTIVE	p	N107-00-6/261	Platform 1 - Westbound Local - Piccadilly Line - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - 14 x Cables		14			
22431	ACTIVE	p	N107-00-6/261	Platform 1 - Westbound Local - Piccadilly Line - Station Building - Leicester Square Stn	Caulking	Asbestos	Strongly Presumed				Head Wall & Tail End Wall - Tunnel Ring Caulking (No access to tunnel rings during re-inspection 08/10/2014)					
22437	ACTIVE	p	N107-00-6/261	Platform 1 - Westbound Local - Piccadilly Line - Station Building - Leicester Square Stn		Asbestos	Sampled – Not Detected				Platform 1 Invert - Red cable wrapping to large cable - NADIS					
69713	ACTIVE	p	N107-00-6/261	Platform 1 - Westbound Local - Piccadilly Line - Station Building - Leicester Square Stn	Other Boarding	Asbestos	Sampled – Not Detected				Insulation board to the back of blue frieze panels above passages			R679602		
22428	ACTIVE	p	N107-00-6/261	Platform 1 - Westbound Local - Piccadilly Line - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Arrivals End - Supalux boarding					
69383	ACTIVE	p	N107-00-6/261	Platform 1 - Westbound Local - Piccadilly Line - Station Building - Leicester Square Stn		Asbestos	Sampled – Not Detected				Non asbestos fibre glass Behind VE panels above door 6/712			R679602		
22432	ACTIVE	p	N107-00-6/261	Platform 1 - Westbound Local - Piccadilly Line - Station Building - Leicester Square Stn	Caulking	Asbestos	Surveyed – Not Detected				Platform 1 Invert - Floor Caulking between Tunnel Rings					
23665	ACTIVE	p	N107-00-6/261	Platform 1 - Westbound Local - Piccadilly Line - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	Known				Platform 1 Invert - 45 x Cable Sleeves - Chrysotile		45			
45228	ACTIVE	p	N107-00-6/261	Platform 1 - Westbound Local - Piccadilly Line - Station Building - Leicester Square Stn		Asbestos	Strongly Presumed				Arrivals End - 12no Cables		12		N	N
22427	ACTIVE	p	N107-00-6/261	Platform 1 - Westbound Local - Piccadilly Line - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Departure End - Suplaux boarding behind metal panels					



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22429	INACTIVE	p	N107-00-6/261	Platform 1 - Westbound Local - Piccadilly Line - Station Building - Leicester Square Stn	Westing house Boxes	Asbestos	Removed				Arrivals End - 1 x Westinghouse Boxing - Insulation within		1			
22434	ACTIVE	p	N107-00-6/261	Platform 1 - Westbound Local - Piccadilly Line - Station Building - Leicester Square Stn	Westing house Boxes	Asbestos	Presumed				Platform 1 Invert - Large Westinghouse box platform wall near tail end		1			
10388	ACTIVE	p	N107-00-6/262	Platform 2 - Eastbound Local - Piccadilly Line - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22441	ACTIVE	p	N107-00-6/262	Platform 2 - Eastbound Local - Piccadilly Line - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Arrivals End - Supalux boarding					
23770	ACTIVE	p	N107-00-6/262	Platform 2 - Eastbound Local - Piccadilly Line - Station Building - Leicester Square Stn	Caulking	Asbestos	Surveyed – Not Detected				Platform 2 Invert - Tunnel Ring - Caulking down Hatch 6/205 - Non Asbestos					
69714	ACTIVE	p	N107-00-6/262	Platform 2 - Eastbound Local - Piccadilly Line - Station Building - Leicester Square Stn	Other Boarding	Asbestos	Sampled – Not Detected				Insulation board to back of blue frieze panels above passages	15		R679602		
22444	ACTIVE	p	N107-00-6/262	Platform 2 - Eastbound Local - Piccadilly Line - Station Building - Leicester Square Stn	Caulking	Asbestos	Strongly Presumed				Platform 2 Invert - Tunnel Ring Caulking nr 6/711. Tunnel Ring - Caulking down Hatch 6/205 - Non Asbestos					
22443	ACTIVE	p	N107-00-6/262	Platform 2 - Eastbound Local - Piccadilly Line - Station Building - Leicester Square Stn	Cable Duct: Other	Asbestos	Known				Platform 2 Invert - 43 x Cable Sleeves - Chrysotile		43			
22442	ACTIVE	p	N107-00-6/262	Platform 2 - Eastbound Local - Piccadilly Line - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - Approx 30 x cables. Controlled encapsulation and/ or fettling of multiple lengths of asbestos sheathed cables in j hangers & on floor on invert.		30			
22430	ACTIVE	p	N107-00-6/262	Platform 2 - Eastbound Local - Piccadilly Line - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				Arrivals End - 12 x Cables Trackside off tunnel Track access required		12			
22440	ACTIVE	p	N107-00-6/262	Platform 2 - Eastbound Local - Piccadilly Line - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Departure End - Supalux boarding, no cables behind metal					
25804	ACTIVE	p	N107-00-6/262	Platform 2 - Eastbound Local - Piccadilly Line - Station Building - Leicester Square Stn	Caulking	Asbestos	Strongly Presumed				Tunnel ring caulking Head & Tail Wall					
22439	ACTIVE	p	N107-00-6/262	Platform 2 - Eastbound Local - Piccadilly Line - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 EB - 13 x Cables from top of platform down tunnel at west head wall		13			
23769	ACTIVE	p	N107-00-6/262	Platform 2 - Eastbound Local - Piccadilly Line - Station Building - Leicester Square Stn	Lead/Leading	Lead Paint/Lead	Known				Platform 2 EB - Platform Cupboard: Blue Gloss. Thickness to thin to measure: Analysis 2.01%					
10389	ACTIVE	p	N107-00-6/381	Store - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22445	ACTIVE	P	N107-00-6/381/WAL-004	Wall: Internal - 4 - Store - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Boxing to Vent from Invert					
10390	ACTIVE	P	N107-00-6/661	Switch Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22446	ACTIVE	P	N107-00-6/661/FLR-01	Floor - 1 - Switch Room - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	Strongly Presumed				Cable ducts in floor, three sealed with concrete		3			
22447	ACTIVE	P	N107-00-6/661/FLR-01	Floor - 1 - Switch Room - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				Plastic Cables, Concrete, Ceramic Ducts to invert beneath manhole					Yes
22449	ACTIVE	P	N107-00-6/661/FLR-01	Floor - 1 - Switch Room - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	Known				10cm & 6cmØ Ducts - Chrysotile - Floor by wall 1		2			
22448	ACTIVE	P	N107-00-6/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Leicester Square Stn	Isolator Switches	Asbestos	Surveyed – Not Detected				Wall 2 - 4 x Switch Boxes & trunking - Insulation within (3x60amps, 1x100amps)		4			
25803	ACTIVE	P	N107-00-6/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Leicester Square Stn	Other Electrical Boxes	Asbestos	Presumed				1x Transformer box Wall 3 - Insulation within Missing - presume 4x CFS to wall No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.					
10391	ACTIVE	P	N107-00-6/663	Switch Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
22450	ACTIVE	P	N107-00-6/663/FLR-01	Floor - 1 - Switch Room - Station Building - Leicester Square Stn	Cable Ducts: Bitumen	Asbestos	Surveyed – Not Detected				6 x Bituminous Paper Ducts		6			
10392	ACTIVE	P	N107-00-6/664	Switch Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22451	ACTIVE	P	N107-00-6/664/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Panel at Top					
10393	ACTIVE	P	N107-00-6/701	Disused Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22452	ACTIVE	P	N107-00-6/701/WAL-002 80859414	Wall: Internal - 2 - Disused Room - Station Building - Leicester Square Stn Wall: Internal	Other Electrical Boxes	Asbestos	Strongly Presumed				3x Lrg Transformer Boxes & Bus Bar - Antennary No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.					



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10394	ACTIVE	P	N107-00-6/711	Relay Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
22453	ACTIVE	P	N107-00-6/711	Relay Room - Station Building - Leicester Square Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel Panels					
22458	ACTIVE	P	N107-00-6/711	Relay Room - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	Strongly Presumed				Backroom: 11no Cable Ducts		11			
22457	ACTIVE	P	N107-00-6/711	Relay Room - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				Approx - 13 x Cables From Platform side to Invert (Backroom)		13			
22455	ACTIVE	P	N107-00-6/711/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - Leicester Square Stn	Void	Asbestos	Surveyed – Not Detected				No identified ACMs above false ceiling			R679602	Yes	
22454	ACTIVE	P	N107-00-6/711/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux, Concrete					
22459	ACTIVE	P	N107-00-6/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Wall 1/2 6 x Cable Ducts - Bituminous Paper - non asbestos		6			
25798	ACTIVE	P	N107-00-6/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				Wall 2 - Approx 15-20 Cables within Roller shutter cabinet in Front room		15			
25801	ACTIVE	P	N107-00-6/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Leicester Square Stn	Other Boarding	Asbestos	Presumed				Wall 2 - 1x Paxoline Board (Front Room)		1			
25797	INACTIVE	P	N107-00-6/711/WAL-002 80859429	Wall: Internal - 2 - Relay Room - Station Building - Leicester Square Stn Wall: Internal	PCBs	Polychlorinated biphenyl	Presumed				Wall 2 - Approx 6 x PCBs within Rollershutter Cabinet in Front Room		12			
22460	ACTIVE	P	N107-00-6/711/WAL-005	Wall: Internal - 5 - Relay Room - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				Approx 2 Cables (Backroom)		2			
22456	ACTIVE	P	N107-00-6/711/WAL-005	Wall: Internal - 5 - Relay Room - Station Building - Leicester Square Stn	Westing house Boxes	Asbestos	Strongly Presumed				1x Westinghouse box - Insulation within (Backroom) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
25796	ACTIVE	P	N107-00-6/711/WAL-008	Wall: Internal - 8 - Relay Room - Station Building - Leicester Square Stn	Other Boarding	Asbestos	Presumed				1x Paxoline board above electrical equipment (Backroom)		1			
25795	ACTIVE	P	N107-00-6/711/WAL-008	Wall: Internal - 8 - Relay Room - Station Building - Leicester Square Stn	Other Electrical Boxes	Asbestos	Presumed				1x Rectifier - Insulation within (Backroom) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10395	ACTIVE	P	N107-00-6/712	Relay Room - Station Building - Leicester Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45230	ACTIVE	P	N107-00-6/712	Relay Room - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				2x 2cmØ 1x1cmØ Green cables back wall to invert		3		N	N
23666	ACTIVE	P	N107-00-6/712	Relay Room - Station Building - Leicester Square Stn	Durasteel	Asbestos	No Access: Presumed				Wall 6 - Durasteel not sampled as near main 600v Switch					
45229	INACTIVE	P	N107-00-6/712	Relay Room - Station Building - Leicester Square Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				600V Fuse Box - Insulation within		1		N	N
25833	ACTIVE	P	N107-00-6/712/FLR-01	Floor - 1 - Relay Room - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	Strongly Presumed				4x Cable ducts at foot of Wall 3		4			
25832	ACTIVE	P	N107-00-6/712/FLR-01	Floor - 1 - Relay Room - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	Strongly Presumed				4x Cable ducts by foot of wall 2		4			
25831	ACTIVE	P	N107-00-6/712/FLR-01	Floor - 1 - Relay Room - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	Strongly Presumed				1x Duct in floor by wall 4 near door		1			
25834	ACTIVE	P	N107-00-6/712/FLR-01	Floor - 1 - Relay Room - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	Strongly Presumed				1x Cable duct at corner of walls 3&4		1			
22461	ACTIVE	P	N107-00-6/712/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Leicester Square Stn		Asbestos	Surveyed – Not Detected				Supalux Box					
25783	ACTIVE	P	N107-00-6/712/WAL-005	Wall: Internal - 5 - Relay Room - Station Building - Leicester Square Stn	Other Boarding	Asbestos	Presumed				Wall 5 - 1x Paxoline Board		1			
23771	ACTIVE	P	N107-00-6/712/WAL-005	Wall: Internal - 5 - Relay Room - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	Presumed				Approx 10 x Cable Sleeves - No Access - Filled In On wall and on floor		10			
25784	ACTIVE	P	N107-00-6/712/WAL-005	Wall: Internal - 5 - Relay Room - Station Building - Leicester Square Stn	Other Electrical Boxes	Asbestos	Presumed				Wall 5 - 1x Rectifier - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
22465	ACTIVE	P	N107-00-6/712/WAL-005	Wall: Internal - 5 - Relay Room - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				Wall 5 - 3x Cables		3			
22462	ACTIVE	P	N107-00-6/712/WAL-006	Wall: Internal - 6 - Relay Room - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	Presumed				2x Cable ducts concreted in corner of Wall 1&2		2			
22464	ACTIVE	P	N107-00-6/712/WAL-006	Wall: Internal - 6 - Relay Room - Station Building - Leicester Square Stn	Westing house Boxes	Asbestos	Strongly Presumed				Wall 6 - 1x Westinghouse Box - Signal Box - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			



Hazardous Material Asset Register - Summary



N107-00 - Station Building - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23982	ACTIVE	P	N107-00-6/712/WAL-006	Wall: Internal - 6 - Relay Room - Station Building - Leicester Square Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Wall 6 - 1x 600v Main Link Box & Supply - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
22463	ACTIVE	P	N107-00-6/712/WAL-006	Wall: Internal - 6 - Relay Room - Station Building - Leicester Square Stn	Other Electrical Boxes	Asbestos	Presumed				Wall 6 - 1x LTE Transformer box- Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
25794	ACTIVE	P	N107-00-6/712/WAL-008	Wall: Internal - 8 - Relay Room - Station Building - Leicester Square Stn	Cable Ducts: Cement	Asbestos	Presumed				Wall 8 - Approx 2 Cable ducts within Roller shutter cabinet - No access presumed		2			
25793	ACTIVE	P	N107-00-6/712/WAL-008	Wall: Internal - 8 - Relay Room - Station Building - Leicester Square Stn	Other Boarding	Asbestos	Presumed				Wall 8 - 1x Paxoline board		1			
25790	ACTIVE	P	N107-00-6/712/WAL-008	Wall: Internal - 8 - Relay Room - Station Building - Leicester Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				Wall 8 - Approx 5 cables within Rollershutter cabinet (3x green, 1x yellow , 1x white)		5			
25782	INACTIVE	P	N107-00-6/712/WAL-008 80859447	Wall: Internal - 8 - Relay Room - Station Building - Leicester Square Stn Wall: Internal	PCBs	Polychlorinated biphenyl	Presumed				Wall 8 - Approx 4 x PCBs within roller shutter cabinet		9			

P011-00 - Station Building - Cockfosters Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12622	ACTIVE	P	P011-00-1/436	Waiting Room - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20418	INACTIVE	P	P011-00-1/436/CLG-01	Ceiling: Solid - 1 - Waiting Room - Station Building - Cockfosters Stn	Void	Asbestos	No Access: Presumed				Above Wood/Glass Panels				Yes	
20419	ACTIVE	P	P011-00-1/436/CLG-01	Ceiling: Solid - 1 - Waiting Room - Station Building - Cockfosters Stn	Void	Asbestos	No Access: Presumed				Above Wood/Glass Panels				Yes	
12623	ACTIVE	P	P011-00-1/437	Waiting Room - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				No access above false ceiling					
20396	ACTIVE	P	P011-00-1/437/CLG-01	Ceiling: Solid - 1 - Waiting Room - Station Building - Cockfosters Stn	Void	Asbestos	No Access: Presumed				Above wood & glass ceiling				Yes	
12624	ACTIVE	P	P011-00-1/601	Stairs: Linear - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									



Hazardous Material Asset Register - Summary



P011-00 - Station Building - Cockfosters Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12625	ACTIVE	P	P011-00-1/602	Stairs: Linear - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12626	ACTIVE	P	P011-00-1/603	Stairs: Linear - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12627	ACTIVE	P	P011-00-1/604	Stairs: Linear - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12628	ACTIVE	P	P011-00-1/605	Stairs: Linear - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
20420	ACTIVE	P	P011-00-1/605	Stairs: Linear - Station Building - Cockfosters Stn	Glazing Rope	Asbestos	Presumed				Rope seals behind glazing bars glass skylight Location on original Type 2 report as 2/451				N	N
12629	ACTIVE	P	P011-00-1/606	Stairs: Linear - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12630	ACTIVE	P	P011-00-1/761	Equipment Room - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12631	ACTIVE	P	P011-00-1/951	Disused Room - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12632	ACTIVE	P	P011-00-2/001	Booking Hall - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
20398	ACTIVE	P	P011-00-2/001	Booking Hall - Station Building - Cockfosters Stn	Cable: Sheath	Asbestos	Presumed				Platform Indicator Board No Access to see Cables - Presumed within No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score material within.				N	N
12633	ACTIVE	P	P011-00-2/011	Ticket Office - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20401	ACTIVE	P	P011-00-2/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Cockfosters Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				Yes	
20400	ACTIVE	P	P011-00-2/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Cockfosters Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
20399	ACTIVE	P	P011-00-2/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Cockfosters Stn	Void	Asbestos	Surveyed – Not Detected				Concrete & PVC Cables beneath Computer Flooring					Yes



Hazardous Material Asset Register - Summary



P011-00 - Station Building - Cockfosters Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12634	ACTIVE	P	P011-00-2/012	Ticket Office - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20403	ACTIVE	P	P011-00-2/012/CLG-01	Ceiling: Solid - 1 - Ticket Office - Station Building - Cockfosters Stn	Void	Asbestos	No Access: Presumed				Above Timber Ceiling				Yes	
20402	ACTIVE	P	P011-00-2/012/FLR-01	Floor - 1 - Ticket Office - Station Building - Cockfosters Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl					
12635	ACTIVE	P	P011-00-2/021	POM - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20404	ACTIVE	P	P011-00-2/021/FLR-01	Floor - 1 - POM - Station Building - Cockfosters Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath Computer Flooring					Yes
12636	ACTIVE	P	P011-00-2/031	Mess Room - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12637	ACTIVE	P	P011-00-2/036	Toilet: Unisex - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12638	ACTIVE	P	P011-00-2/047	Mess Room - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20405	ACTIVE	P	P011-00-2/047/FLR-01	Floor - 1 - Mess Room - Station Building - Cockfosters Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
20406	ACTIVE	P	P011-00-2/047/FLR-01	Floor - 1 - Mess Room - Station Building - Cockfosters Stn	Void	Asbestos	No Access: Presumed				Beneath Lino					Yes
12639	ACTIVE	P	P011-00-2/201	Passage - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12640	ACTIVE	P	P011-00-2/202	Passage - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12641	ACTIVE	P	P011-00-2/236	Passage - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20409	ACTIVE	P	P011-00-2/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Cockfosters Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				Yes	
20408	ACTIVE	P	P011-00-2/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Cockfosters Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
20407	ACTIVE	P	P011-00-2/236/FLR-01	Floor - 1 - Passage - Station Building - Cockfosters Stn	Void	Asbestos	Surveyed – Not Detected				Concrete/ PVC Cables beneath Computer Flooring					Yes



Hazardous Material Asset Register - Summary



P011-00 - Station Building - Cockfosters Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12642	ACTIVE	P	P011-00-2/237	Passage - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20411	ACTIVE	P	P011-00-2/237	Passage - Station Building - Cockfosters Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Insulation board in LUL heater - Type 3 shows non asbestos		1			
23911	ACTIVE	P	P011-00-2/237/FLR-01	Floor - 1 - Passage - Station Building - Cockfosters Stn	Void	Asbestos	No Access: Presumed				Beneath Lino					Yes
20410	ACTIVE	P	P011-00-2/237/FLR-01	Floor - 1 - Passage - Station Building - Cockfosters Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
12643	ACTIVE	P	P011-00-2/261	Platform 1 - Eastbound Local - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
20412	ACTIVE	P	P011-00-2/261	Platform 1 - Eastbound Local - Station Building - Cockfosters Stn	Cable: Sheath	Asbestos	Strongly Presumed				2no Braided cable running along platform in cable run in hanger 4. No access to track at time of re-inspection 2024		2		N	N
42282	ACTIVE	P	P011-00-2/261	Platform 1 - Eastbound Local - Station Building - Cockfosters Stn	Debris: Other	Asbestos	Presumed				Debris/cement sheets/ AIB sheets found in soil and in debris in the cess - embankment adjacent to Platform 1 Asbestos Debris was picked and removed during the construction of new TCA Walkway, further debris may become evident if further excavations are undertaken.	20	3		N	N
42281	INACTIVE	P	P011-00-2/261	Platform 1 - Eastbound Local - Station Building - Cockfosters Stn	Debris: Cement	Asbestos	Known				3 x 20m debris/ cement sheets buried within soil and in debris in the cess - emabankment adjacent to Platform 1	20	3		N	N
12644	ACTIVE	P	P011-00-2/262	Platform 2 - Single Line Local - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12645	ACTIVE	P	P011-00-2/263	Platform 3 - Single Line Local - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12646	ACTIVE	P	P011-00-2/264	Platform 4 - Westbound Local - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
20413	ACTIVE	P	P011-00-2/264	Platform 4 - Westbound Local - Station Building - Cockfosters Stn	Cable: Sheath	Asbestos	Strongly Presumed				from behind 2/047 Green asbestos cable running along platform. No access to track at time of re-inspection 2024		1			
12647	ACTIVE	P	P011-00-2/281	Station Supervisor Office - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12648	ACTIVE	P	P011-00-2/331	Mess Room - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									



Hazardous Material Asset Register - Summary



P011-00 - Station Building - Cockfosters Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12649	ACTIVE	P	P011-00-2/332	Tea Point - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12650	ACTIVE	P	P011-00-2/401	Bin Store - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12651	ACTIVE	P	P011-00-2/406	Store - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20414	ACTIVE	P	P011-00-2/406/FLR-01	Floor - 1 - Store - Station Building - Cockfosters Stn	Void	Asbestos	No Access: Presumed				To Hatch on floor					Yes
12652	ACTIVE	P	P011-00-2/407	Store - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12653	ACTIVE	P	P011-00-2/411	Store - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
23912	INACTIVE	P	P011-00-2/411/DOR-01	Door - 1 - Store - Station Building - Cockfosters Stn	Lead/Leading	Lead Paint/Lead	Known				Door outside - Green gloss - 7m². Thickness : 0.31mm Analysis : 4.6%					
20415	ACTIVE	P	P011-00-2/411/DOR-02	Door - 2 - Store - Station Building - Cockfosters Stn	Lead/Leading	Lead Paint/Lead	Known				Door outside - Green gloss - 7m². Thickness : 0.31mm Analysis : 4.6%				N	N
12654	ACTIVE	P	P011-00-2/412	Store - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12655	ACTIVE	P	P011-00-2/413	Store - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12656	ACTIVE	P	P011-00-2/414	Store - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20416	ACTIVE	P	P011-00-2/414/FLR-01	Floor - 1 - Store - Station Building - Cockfosters Stn	Void	Asbestos	No Access: Presumed				No access to 2 x manhole covers					Yes
12657	ACTIVE	P	P011-00-2/415	Store - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12658	ACTIVE	P	P011-00-2/416	Toilet: Male - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12659	ACTIVE	P	P011-00-2/417	Toilet: Female - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12660	ACTIVE	P	P011-00-2/426	Toilet: Male - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									



Hazardous Material Asset Register - Summary



P011-00 - Station Building - Cockfosters Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20417	ACTIVE	P	P011-00-2/426/WAL-001	Wall: Internal - 1 - Toilet - Station Building - Cockfosters Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing					
12661	ACTIVE	P	P011-00-2/427	Toilet: Female - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12662	ACTIVE	P	P011-00-2/436	Waiting Room - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12663	ACTIVE	P	P011-00-2/437	Waiting Room - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12664	ACTIVE	P	P011-00-2/446	CER - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12665	ACTIVE	P	P011-00-2/451	Tenancy - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
23886	INACTIVE	P	P011-00-2/451/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Cockfosters Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling				Yes	
23913	ACTIVE	P	P011-00-2/451/FLR-01	Floor - 1 - Tenancy - Station Building - Cockfosters Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath Carpet					Yes
12666	ACTIVE	P	P011-00-2/452	Tenancy - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
23914	ACTIVE	P	P011-00-2/452	Tenancy - Station Building - Cockfosters Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard partition walls					
20478	ACTIVE	P	P011-00-2/452/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Cockfosters Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				Yes	
20477	ACTIVE	P	P011-00-2/452/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Cockfosters Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux tiles					
20422	ACTIVE	P	P011-00-2/452/FLR-01	Floor - 1 - Tenancy - Station Building - Cockfosters Stn	Void	Asbestos	No Access: Presumed				Beneath wooden floor					Yes
12667	ACTIVE	P	P011-00-2/453	Tenancy - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20479	ACTIVE	P	P011-00-2/453	Tenancy - Station Building - Cockfosters Stn		Asbestos	Surveyed – Not Detected				Surveyed for TFL Group Properties - No Asbestos Detected					



Hazardous Material Asset Register - Summary



P011-00 - Station Building - Cockfosters Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12668	ACTIVE	P	P011-00-2/661	Switch Room - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
20482	ACTIVE	P	P011-00-2/661	Switch Room - Station Building - Cockfosters Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box Asbestos Components – Presumed within		1		N	N
20483	ACTIVE	P	P011-00-2/661	Switch Room - Station Building - Cockfosters Stn	Lead/Leading	Lead Paint/Lead	Known				Metal Panel - Red Gloss - Thickness: 0.14mm Analysis: 9.25% . Now partially hidden by recently installed equipment				N	N
20480	ACTIVE	P	P011-00-2/661/ WAL-001 80862130	Wall: Internal - 1 - Switch Room - Station Building - Cockfosters Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				4 x Iron clad isolators 2 x 60 amps, 2 x 100 amps No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score material within.		4		N	N
20481	ACTIVE	P	P011-00-2/661/ WAL-002 80862131	Wall: Internal - 2 - Switch Room - Station Building - Cockfosters Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				3x Iron clad isolators 2 x 60 amps, 1 x 100 amps No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score material within.		3		N	N
25829	INACTIVE	P	P011-00-2/661/ WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Cockfosters Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box		1			
25805	INACTIVE	P	P011-00-2/661/ WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Cockfosters Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box		1			
12669	ACTIVE	P	P011-00-2/662	Switch Room - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
44826	INACTIVE	P	P011-00-2/662/ FLR-01	Floor - 1 - Switch Room - Station Building - Cockfosters Stn	Cable Duct: Other	Asbestos	Removed				Asbestos		2			
20484	ACTIVE	P	P011-00-2/662/ WAL-001 80862137	Wall: Internal - 1 - Switch Room - Station Building - Cockfosters Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				4x Iron clad isolators - 3 x 60 amps, 1 x 100 amps No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score material within.		4		N	N
20487	ACTIVE	P	P011-00-2/662/ WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Cockfosters Stn	Cable Duct: Other	Asbestos	Known				Cable Ducts W1 1no Low Level & 1no High Level - Chrysotile		2			
20486	ACTIVE	P	P011-00-2/662/ WAL-002 80862138	Wall: Internal - 2 - Switch Room - Station Building - Cockfosters Stn Wall: Internal	Cable Duct: Other	Asbestos	Presumed				2 x Cable Sleeves - Sealed - Located Low level		2		N	N
20485	ACTIVE	P	P011-00-2/662/ WAL-003 80862139	Wall: Internal - 3 - Switch Room - Station Building - Cockfosters Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				6x Iron clad isolators - 1 x 60 amps, 3 x 100 amps, 2 x 200 amps No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score material within.		6		N	N



Hazardous Material Asset Register - Summary



P011-00 - Station Building - Cockfosters Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12670	ACTIVE	P	P011-00-2/663	Switch Room - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
20488	ACTIVE	P	P011-00-2/663/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Cockfosters Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				2 x Superlux panel					
20489	ACTIVE	P	P011-00-2/663/CLG-01 80862152	Ceiling: Suspended - 1 - Switch Room - Station Building - Cockfosters Stn Ceiling: Suspended	Void	Asbestos	No Access: Presumed				Above 2x Supalux Ceiling Panels within void				Yes	
20490	ACTIVE	P	P011-00-2/663/WAL-002 80862149	Wall: Internal - 2 - Switch Room - Station Building - Cockfosters Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				3 x Transformer Boxes Asbestos Components – Presumed within		3		N	N
20491	ACTIVE	P	P011-00-2/663/WAL-002 80862149	Wall: Internal - 2 - Switch Room - Station Building - Cockfosters Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				1 x 30amp Iron clad isolator. No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score material within.		1		N	N
12671	ACTIVE	P	P011-00-2/746	SCR - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12672	ACTIVE	P	P011-00-2/761	Equipment Room - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
20492	INACTIVE	P	P011-00-2/761	Equipment Room - Station Building - Cockfosters Stn	Cable: Sheath	Asbestos	Strongly Presumed				1x 30mm - Outside along track from behind 2/047 and along Platform 4					
25806	ACTIVE	P	P011-00-2/761/WAL-004	Wall: Internal - 4 - Equipment Room - Station Building - Cockfosters Stn	Other Boarding	Asbestos	Strongly Presumed				Paxoline Board	1	1		N	N
12673	ACTIVE	P	P011-00-2/776	Plant Room - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12674	ACTIVE	P	P011-00-2/801	Training Room - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
23921	ACTIVE	P	P011-00-2/801/FLR-01	Floor - 1 - Office - Station Building - Cockfosters Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
20493	ACTIVE	P	P011-00-2/801/FLR-01	Floor - 1 - Office - Station Building - Cockfosters Stn	Void	Asbestos	No Access: Presumed				Beneath Lino					Yes
12675	ACTIVE	P	P011-00-2/951	Switch Room - Station Building - Cockfosters Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									



Hazardous Material Asset Register - Summary



P011-00 - Station Building - Cockfosters Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20421	ACTIVE	P	P011-00/ROF-01	Roof - 1 - External - Station Building - Cockfosters Stn	Cement Cowlings/ Flues	Asbestos	Strongly Presumed				2 x cementitous flues to booking hall / station roof near Tenancy 2/451 1x cowl remains as new lift works taking place and the 2nd flue may have been removed. However possible flue pipe residue / debris may remain within concrete roof slab		1			N
43993	ACTIVE	P	P011-00/ROF-01 80955472	Roof - 1 - External - Station Building - Cockfosters Stn Structure: Roof	Cable: Sheath	Asbestos	Presumed				2no Small Asbestos Woven Cables on Roof in CRMS near Car Park / Stairs 1/605. Not located previously when referred to old photos. Not identified at time of re-inspection 2024, presumed to remain		2			N

P013-00 - Station Building - Oakwood Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12686	ACTIVE	P	P013-00-1/001	Booking Hall - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20494	ACTIVE	P	P013-00-1/001	Booking Hall - Station Building - Oakwood Stn	Lead/Leading	Lead Paint/Lead	Known				Door Frames & Windows throughout area and into 1/072 - White gloss - 10m ² Thickness : 0.19mm Analysis : 2.3%		4		N	N
20495	ACTIVE	P	P013-00-1/001	Booking Hall - Station Building - Oakwood Stn	Lead/Leading	Lead Paint/Lead	Known				2x Poster board surrounds - White gloss - 4m ² Thickness : 0.23mm Analysis : 1.1%		2		Y	N
44512	ACTIVE	P	P013-00-1/001	Booking Hall - Station Building - Oakwood Stn	Lead/Leading	Lead Paint/Lead	Presumed				Black gloss shutters				N	N
12687	ACTIVE	P	P013-00-1/011	Ticket Office - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20498	ACTIVE	P	P013-00-1/011/ CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Oakwood Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Vertical Supalux boarding to sky light					
23922	ACTIVE	P	P013-00-1/011/ CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Oakwood Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux tiles					
20497	ACTIVE	P	P013-00-1/011/ CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Oakwood Stn	Void	Asbestos	Surveyed – Not Detected				Plaster / Solid above Supalux Tiles				Yes	
20496	ACTIVE	P	P013-00-1/011/ FLR-01	Floor - 1 - Ticket Office - Station Building - Oakwood Stn	Void	Asbestos	Surveyed – Not Detected				Brick, Trunking, PVC Cable beneath Concrete Floor, Wood					Yes
12688	ACTIVE	P	P013-00-1/021	POM - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									



Hazardous Material Asset Register - Summary



P013-00 - Station Building - Oakwood Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23888	ACTIVE	P	P013-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Oakwood Stn	Void	Asbestos	Surveyed – Not Detected				Superlux, PVC Cable, Trunking beneath Computer Tiles					Yes
12689	ACTIVE	P	P013-00-1/031	Mess Room - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12690	ACTIVE	P	P013-00-1/036	Toilet: Unisex - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12691	ACTIVE	P	P013-00-1/071	Circulation Area - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
44511	ACTIVE	P	P013-00-1/071	Circulation Area - Station Building - Oakwood Stn	Lead/Leading	Lead Paint/Lead	Presumed				3x brown gloss paint to poster surround		3		N	N
12692	ACTIVE	P	P013-00-1/072	Circulation Area - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
20499	ACTIVE	P	P013-00-1/072	Circulation Area - Station Building - Oakwood Stn	Void	Asbestos	No Access: Presumed				No access behind metal stretcher cupboard					
12693	ACTIVE	P	P013-00-1/081	Lobby - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12694	ACTIVE	P	P013-00-1/082	Lobby - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12695	ACTIVE	P	P013-00-1/083	Lobby - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12696	ACTIVE	P	P013-00-1/131	Lift Pump Room - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Asbestos Free									
23923	ACTIVE	P	P013-00-1/131	Lift Pump Room - Station Building - Oakwood Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
12697	ACTIVE	P	P013-00-1/236	Passage - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20501	ACTIVE	P	P013-00-1/236	Passage - Station Building - Oakwood Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boarding above front door					
20500	ACTIVE	P	P013-00-1/236/FLR-01	Floor - 1 - Passage - Station Building - Oakwood Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
12698	ACTIVE	P	P013-00-1/237	Passage - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – Asbestos Known									
23924	ACTIVE	P	P013-00-1/237/FLR-01	Floor - 1 - Passage - Station Building - Oakwood Stn	Void	Asbestos	No Access: Presumed				No access to hatch on floor (Potentially relates to 20502 - 4no Cable Ducts within)					Y



Hazardous Material Asset Register - Summary



P013-00 - Station Building - Oakwood Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20502	ACTIVE	P	P013-00-1/237/WAL-001	Wall: Internal - 1 - Passage - Station Building - Oakwood Stn	Cable Duct: Other	Asbestos	No Access: Presumed				4x Ducts - Void wall 1 (Potentially relates to 23924 Void previously non accessed) Floor duct not accessed during 2020 re-inspection. Manhole cover lifting equipment required. Presume ducts within are still present.		4			
12699	ACTIVE	P	P013-00-1/281	Station Supervisors Office - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20503	ACTIVE	P	P013-00-1/281/FLR-01	Floor - 1 - Office - Station Building - Oakwood Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
12700	ACTIVE	P	P013-00-1/311	Office - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12701	ACTIVE	P	P013-00-1/316	Locker Room - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20504	ACTIVE	P	P013-00-1/316/WAL-001	Wall: Internal - 1 - Locker Room - Station Building - Oakwood Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard boxing					
12702	ACTIVE	P	P013-00-1/318	Locker Room - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12703	ACTIVE	P	P013-00-1/331	Mess Room - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
20505	ACTIVE	P	P013-00-1/331	Mess Room - Station Building - Oakwood Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boarding on escape door					
20508	ACTIVE	P	P013-00-1/331	Mess Room - Station Building - Oakwood Stn	Bitumen	Asbestos	Surveyed – Not Detected				2x Sink units - Non asbestos		2			
20506	ACTIVE	P	P013-00-1/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Oakwood Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boarding					
20507	ACTIVE	P	P013-00-1/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Oakwood Stn	Void	Asbestos	No Access: Presumed				No Access behind Supalux Boarding				Yes	
12704	ACTIVE	P	P013-00-1/332	Mess Room - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12705	ACTIVE	P	P013-00-1/341	Mess Room - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20510	ACTIVE	P	P013-00-1/341/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Oakwood Stn	Bitumen	Asbestos	Surveyed – Not Detected				Acoustic Panel					



Hazardous Material Asset Register - Summary



P013-00 - Station Building - Oakwood Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20511	ACTIVE	P	P013-00-1/341/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Oakwood Stn	Void	Asbestos	Surveyed – Not Detected				Plaster / Solid above false ceiling				Yes	
20509	ACTIVE	P	P013-00-1/341/FLR-01	Floor - 1 - Mess Room - Station Building - Oakwood Stn	Void	Asbestos	No Access: Presumed				No access to hatch on floor					Yes
12706	ACTIVE	P	P013-00-1/406	Store - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12707	ACTIVE	P	P013-00-1/411	Store - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20512	ACTIVE	P	P013-00-1/411/FLR-01	Floor - 1 - Store - Station Building - Oakwood Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
12708	ACTIVE	P	P013-00-1/412	Store - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20513	ACTIVE	P	P013-00-1/412/FLR-01	Floor - 1 - Store - Station Building - Oakwood Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
12709	ACTIVE	P	P013-00-1/413	Store - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20514	ACTIVE	P	P013-00-1/413/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Oakwood Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling				Yes	
12710	ACTIVE	P	P013-00-1/414	Tenancy - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20515	ACTIVE	P	P013-00-1/414	Tenancy - Station Building - Oakwood Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
12711	ACTIVE	P	P013-00-1/415	Store - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				NEW					
20516	ACTIVE	P	P013-00-1/415	Store - Station Building - Oakwood Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
12712	ACTIVE	P	P013-00-1/416	Toilet: Male - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20519	ACTIVE	P	P013-00-1/416	Toilet: Male - Station Building - Oakwood Stn	Lead/Leading	Lead Paint/Lead	Known				Door Frame - White Gloss - 1m². Thickness : 0.19mm Analysis : 2.3%				N	N
20518	ACTIVE	P	P013-00-1/416/FLR-01	Floor - 1 - Toilet - Station Building - Oakwood Stn	Void	Asbestos	Surveyed – Not Detected				2x Inspection covers. Manhole - clay sewerage pipes					Yes
20517	ACTIVE	P	P013-00-1/416/FLR-01	Floor - 1 - Toilet - Station Building - Oakwood Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Tiles / Supalux					



Hazardous Material Asset Register - Summary



P013-00 - Station Building - Oakwood Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12713	ACTIVE	P	P013-00-1/417	Toilet: Female - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20520	ACTIVE	P	P013-00-1/417/FLR-01	Floor - 1 - Toilet - Station Building - Oakwood Stn	Void	Asbestos	Surveyed – Not Detected				Inspection cover, Sewerage - Ceramic beneath Quarry Tiles					Yes
23925	ACTIVE	P	P013-00-1/417/WAL-001	Wall: Internal - 1 - Toilet - Station Building - Oakwood Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing					
12714	ACTIVE	P	P013-00-1/418	Toilet: Male - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12715	ACTIVE	P	P013-00-1/419	Toilet: Female - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12716	ACTIVE	P	P013-00-1/426	Toilet: Male - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12717	ACTIVE	P	P013-00-1/427	Toilet: Female - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12718	ACTIVE	P	P013-00-1/451	Tenancy - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23926	ACTIVE	P	P013-00-1/451	Tenancy - Station Building - Oakwood Stn	Lead/Leading	Lead Paint/Lead	Known				Window frame surround - Red gloss - 4m ² - Thickness : 0.16mm Analysis : 4.1% Projects may have removed				N	N
20524	ACTIVE	P	P013-00-1/451	Tenancy - Station Building - Oakwood Stn	Lead/Leading	Lead Paint/Lead	Known				Door - white gloss - 4m ² - Thickness : 0.19mm Analysis : 2.3%. Projects may have removed. 30/09/2014 - Door is now Red				N	N
20522	ACTIVE	P	P013-00-1/451/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Oakwood Stn	Bitumen	Asbestos	Surveyed – Not Detected				Acoustic panel					
20523	ACTIVE	P	P013-00-1/451/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Oakwood Stn	Void	Asbestos	Surveyed – Not Detected				Polystyrene tiles on solid above false ceiling				Yes	
20521	ACTIVE	P	P013-00-1/451/WAL-002	Wall: Internal - 2 - Tenancy - Station Building - Oakwood Stn	Other Boarding	Asbestos	No Access: Presumed				Wall 2 - Wooden boxing - no access					
12719	ACTIVE	P	P013-00-1/452	Store - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20526	ACTIVE	P	P013-00-1/452/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Oakwood Stn	Void	Asbestos	No Access: Presumed				Above Wood Ceiling				Yes	
20525	ACTIVE	P	P013-00-1/452/FLR-01	Floor - 1 - Store - Station Building - Oakwood Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Linoleum					



Hazardous Material Asset Register - Summary



P013-00 - Station Building - Oakwood Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12720	ACTIVE	P	P013-00-1/453	Tenancy - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20528	ACTIVE	P	P013-00-1/453	Tenancy - Station Building - Oakwood Stn	Lead/Leading	Lead Paint/Lead	Known				Inside surround & walls- Light blue/ violet gloss - 8m². Thickness : No access Analysis : 1.5% Projects may have removed				N	N
20527	ACTIVE	P	P013-00-1/453/ WAL-001	Wall: Internal - 1 - Tenancy - Station Building - Oakwood Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Wooden violet boarding					
12721	ACTIVE	P	P013-00-1/454	Tenancy - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23927	ACTIVE	P	P013-00-1/454/ CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Oakwood Stn	Void	Asbestos	No Access: Presumed				Above Metal slats				Yes	
12722	ACTIVE	P	P013-00-1/455	Tenancy - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23889	ACTIVE	P	P013-00-1/455	Tenancy - Station Building - Oakwood Stn	Other Boarding	Asbestos	No Access: Presumed				Blue wooden boxing on all walls					
20529	ACTIVE	P	P013-00-1/455	Tenancy - Station Building - Oakwood Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
20530	ACTIVE	P	P013-00-1/455/ CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Oakwood Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Acoustic panels					
20531	ACTIVE	P	P013-00-1/455/ CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Oakwood Stn	Void	Asbestos	Surveyed – Not Detected				Polystyrene tiles on concrete above acoustic panels				Yes	
12723	ACTIVE	P	P013-00-1/456	Tenancy - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12724	ACTIVE	P	P013-00-1/457	Tenancy - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20423	ACTIVE	P	P013-00-1/457	Tenancy - Station Building - Oakwood Stn	Bitumen	Asbestos	Surveyed – Not Detected				0.02m² non asbestos acoustic panel on sink		1			
20428	ACTIVE	P	P013-00-1/457/ FLR-01	Floor - 1 - Tenancy - Station Building - Oakwood Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
20532	ACTIVE	P	P013-00-1/457/ FLR-01	Floor - 1 - Tenancy - Station Building - Oakwood Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino - Toilet					
20424	ACTIVE	P	P013-00-1/457/ WAL-001	Wall: Internal - 1 - Tenancy - Station Building - Oakwood Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Tenancy Toilet - Plasterboard					
20425	ACTIVE	P	P013-00-1/457/ WAL-002	Wall: Internal - 2 - Tenancy - Station Building - Oakwood Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Tenancy Toilet - Plasterboard					



Hazardous Material Asset Register - Summary



P013-00 - Station Building - Oakwood Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20426	ACTIVE	P	P013-00-1/457/WAL-003	Wall: Internal - 3 - Tenancy - Station Building - Oakwood Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Tenancy Toilet - Plasterboard					
23928	ACTIVE	P	P013-00-1/457/WAL-003	Wall: Internal - 3 - Tenancy - Station Building - Oakwood Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
20427	ACTIVE	P	P013-00-1/457/WAL-004	Wall: Internal - 4 - Tenancy - Station Building - Oakwood Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Tenancy Toilet - Plasterboard					
12725	ACTIVE	P	P013-00-1/551	Yard - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20429	ACTIVE	P	P013-00-1/551/FLR-01	Floor - 1 - Yard - Station Building - Oakwood Stn	Void	Asbestos	Surveyed – Not Detected				Floor hatch x3. Sewerage ceramic pipes beneath Concrete floor					Yes
12726	ACTIVE	P	P013-00-1/601	Stairs: Linear - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12727	ACTIVE	P	P013-00-1/602	Stairs: Linear - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Not on station layout???					
20430	ACTIVE	P	P013-00-1/636	Overbridge - Station Building - Oakwood Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
12728	ACTIVE	P	P013-00-1/661	Switch Room - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
23887	ACTIVE	P	P013-00-1/661	Switch Room - Station Building - Oakwood Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boarding on door					
20431	ACTIVE	P	P013-00-1/661/FLR-01	Floor - 1 - Switch Room - Station Building - Oakwood Stn	Cable Duct: Other	Asbestos	Strongly Presumed				4 x Cable sleeves filled in Cable sleeves not visible beneath filling therefore material not scored in 2020 re-inspection		4		N	N
20432	ACTIVE	P	P013-00-1/661/FLR-01	Floor - 1 - Switch Room - Station Building - Oakwood Stn	Void	Asbestos	No Access: Presumed				No access to Hatch					Yes
20433	ACTIVE	P	P013-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Oakwood Stn	Other Electrical Boxes	Asbestos	Presumed				Insulation within 1 x Transformer Box 7no. combination fuse switches to wall 3 and 2no. combination fuse switches to wall 2 are present. All but 2 CFS to wall 3 have stickers stating interiors of boxes have been cleaned.		1		N	N
44513	INACTIVE	P	P013-00-1/661/WAL-002 80885010	Wall: Internal - 2 - Switch Room - Station Building - Oakwood Stn Wall: Internal	Isolator Switches	Asbestos	Removed				2x 60 amp switch boxes REMOVED by PECTEL 06/01/2007		2		N	N
44514	INACTIVE	P	P013-00-1/661/WAL-003 80885011	Wall: Internal - 3 - Switch Room - Station Building - Oakwood Stn Wall: Internal	Other Electrical Boxes	Asbestos	Removed				7x switch boxes (1x200 amp, 4x60 amp, 2x100 amp) - Removed by Pectel 06/01/2007		7		N	N



Hazardous Material Asset Register - Summary



P013-00 - Station Building - Oakwood Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12729	ACTIVE	P	P013-00-1/662	Switch Room - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
24037	ACTIVE	P	P013-00-1/662/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Oakwood Stn	Isolator Switches	Asbestos	Strongly Presumed				1x 30amp Iron clad isolator and trunking wall		1		N	N
20434	ACTIVE	P	P013-00-1/662/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Oakwood Stn	Other Electrical Boxes	Asbestos	Presumed				Insulation within 3 x Transformer Box		3		N	N
12730	ACTIVE	P	P013-00-1/746	SCR - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12731	ACTIVE	P	P013-00-1/776	Plant Room - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
20435	ACTIVE	P	P013-00-1/776/WAL-001	Wall: Internal - 1 - Plant Room - Station Building - Oakwood Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 30amp grey iron clad isolator		1		N	N
20436	ACTIVE	P	P013-00-1/776/WAL-002	Wall: Internal - 2 - Plant Room - Station Building - Oakwood Stn	Gasket :Pipework	Asbestos	Strongly Presumed				Gaskets on pump equipment walls 2 and 3 - no access to take sample				N	N
12732	ACTIVE	P	P013-00-1/801	Office - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12733	ACTIVE	P	P013-00-1/901	Store - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12734	ACTIVE	P	P013-00-1/902	Store - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44472	INACTIVE	P	P013-00-1/902	Store - Station Building - Oakwood Stn	Void	Asbestos	No Access: Presumed				Void beneath floor				N	Y
20437	ACTIVE	P	P013-00-1/902/FLR-01	Floor - 1 - Store - Station Building - Oakwood Stn	Void	Asbestos	No Access: Presumed				No access beneath Hatch on floor - ceramic sewerage					Yes
12735	ACTIVE	P	P013-00-1/951	Office - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20438	ACTIVE	P	P013-00-2/136	Lift Shaft - Station Building - Oakwood Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
12736	ACTIVE	P	P013-00-2/261	Platform 1 - Westbound Local - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – Asbestos Known									
23915	ACTIVE	P	P013-00-2/261	Platform 1 - Westbound Local - Station Building - Oakwood Stn	Other Electrical Boxes	Asbestos	Known				Insulation within Various Westinghouse Boxes - Trackside				N	N



Hazardous Material Asset Register - Summary



P013-00 - Station Building - Oakwood Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20439	ACTIVE	P	P013-00-2/261	Platform 1 - Westbound Local - Station Building - Oakwood Stn	Cable: Sheath	Asbestos	Known				Cables on cable run (no 4 J hanger) No access onto track during 2020 re-inspection during traffic hours. Item not accessed. Viewed from platform only.				N	N
20440	ACTIVE	P	P013-00-2/261	Platform 1 - Westbound Local - Station Building - Oakwood Stn	Cement Troughing	Asbestos	Known				Cable troughing debris - Chrysotile				N	N
12737	ACTIVE	P	P013-00-2/262	Platform 2 - Eastbound Local - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
20443	ACTIVE	P	P013-00-2/262	Platform 2 - Eastbound Local - Station Building - Oakwood Stn	Cement Troughing	Asbestos	Known				Cable troughing debris - Chrysotile				N	N
20442	ACTIVE	P	P013-00-2/262	Platform 2 - Eastbound Local - Station Building - Oakwood Stn	Cable: Sheath	Asbestos	Known				Cables on cable run				N	N
20441	ACTIVE	P	P013-00-2/262	Platform 2 - Eastbound Local - Station Building - Oakwood Stn	Westing house Boxes	Asbestos	Strongly Presumed				Insulation within Various Westinghouse Boxes - Trackside		10		N	N
12738	ACTIVE	P	P013-00-2/371	Store - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
23916	ACTIVE	P	P013-00-2/371	Store - Station Building - Oakwood Stn	Westing house Boxes	Asbestos	No Access: Presumed				10x Westinghouse boxes outside 2/371 No access onto track during 2020 re-inspection during traffic hours. Item not accessed.		10		N	N
20444	ACTIVE	P	P013-00-2/371	Store - Station Building - Oakwood Stn	Cable: Sheath	Asbestos	Strongly Presumed				Woven sheathed cable 2 no to cable run from caged Westinghouse boxes (outside 2/371) over track crossing to far side of Piccadilly Line, Eastbound & Westbound Roads on the underside of Bridge G324				N	N
44803	ACTIVE	P	P013-00-2/371	Store - Station Building - Oakwood Stn	Lead/Leading	Lead Paint/Lead	Known				Light Blue Matt Support Columns thickness 930 11.5% Caged area outside 2/371 - Bridge G324			R596702		
12739	ACTIVE	P	P013-00-2/372	Store - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12740	ACTIVE	P	P013-00-2/411	Store - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20446	INACTIVE	P	P013-00-2/411/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Oakwood Stn	Void	Asbestos	No Access: Presumed				Above Corrugated metal sheeting				Yes	
20445	ACTIVE	P	P013-00-2/411/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Oakwood Stn	Cellactite Sheeting	Asbestos	Surveyed – Not Detected				Corrugated metal sheeting					



Hazardous Material Asset Register - Summary



P013-00 - Station Building - Oakwood Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12741	ACTIVE	P	P013-00-2/412	Store - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12742	ACTIVE	P	P013-00-2/415	Store - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Not on station layout???					
12743	ACTIVE	P	P013-00-2/436	Waiting Room - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
23917	ACTIVE	P	P013-00-2/436/WAL-003	Wall: Internal - 3 - Waiting Room - Station Building - Oakwood Stn	LUL Heaters	Asbestos	Strongly Presumed				Insulation Board within 1 x LUL Heater		1		N	N
12744	ACTIVE	P	P013-00-2/661	Switch Room - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
20448	ACTIVE	P	P013-00-2/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Oakwood Stn	Isolator Switches	Asbestos	Strongly Presumed				3 x Iron clad isolators & trunking - 1 x 100, 2 x 60 amps		3		N	N
20449	ACTIVE	P	P013-00-2/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Oakwood Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 60amp Iron clad isolators & trunking		1		N	N
20447	ACTIVE	P	P013-00-2/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Oakwood Stn	Other Electrical Boxes	Asbestos	Presumed				Insulation within 1 x Transformer Box		1		N	N
12745	ACTIVE	P	P013-00-2/662	Switch Room - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
12746	ACTIVE	P	P013-00-2/731	CER - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20450	ACTIVE	P	P013-00-2/731/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Oakwood Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard/Solid					
20451	ACTIVE	P	P013-00-2/731/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Oakwood Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling				Yes	
12747	ACTIVE	P	P013-00-2/761	Equipment Room - Station Building - Oakwood Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									

P015-00 - Station Building - Southgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44805	ACTIVE	P	P015-00-0/000	Station Entrance - Station Building - Southgate Stn	Lead/Leading	Lead Paint/Lead	Known				4x 2m² Outside poster boards - Blue on black- External to Station by Entrances			R20727		



Hazardous Material Asset Register - Summary



P015-00 - Station Building - Southgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12749	ACTIVE	P	P015-00-1/001	Booking Hall - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20454	ACTIVE	P	P015-00-1/001	Booking Hall - Station Building - Southgate Stn	Lead/Leading	Lead Paint/Lead	Known				Frieze - Dark blue matt - 20m². Thickness : 0.18mm Analysis : 12.7%				N	N
20453	ACTIVE	P	P015-00-1/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Above false ceiling					
12750	ACTIVE	P	P015-00-1/011	Ticket Office - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20457	ACTIVE	P	P015-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Southgate Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
20458	ACTIVE	P	P015-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Southgate Stn	Void	Asbestos	Surveyed – Not Detected				Supalux Boarding around vent above false ceiling				Yes	
20459	ACTIVE	P	P015-00-1/011/CLG-02	Ceiling: Suspended - 2 - Ticket Office - Station Building - Southgate Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
20460	ACTIVE	P	P015-00-1/011/CLG-02	Ceiling: Suspended - 2 - Ticket Office - Station Building - Southgate Stn	Void	Asbestos	Surveyed – Not Detected				Supalux Boarding around vent above false ceiling				Yes	
20455	ACTIVE	P	P015-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Southgate Stn	Void	Asbestos	Surveyed – Not Detected				Concrete and metal trunking beneath computer tiles					Yes
20456	ACTIVE	P	P015-00-1/011/WAL-001	Wall: Internal - 1 - Ticket Office - Station Building - Southgate Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boxing around ceiling lighting					
12751	ACTIVE	P	P015-00-1/021	POM - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20463	ACTIVE	P	P015-00-1/021/CLG-01	Ceiling: Solid - 1 - POM - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Above metal hatches in ceiling					
20461	ACTIVE	P	P015-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Southgate Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
20462	ACTIVE	P	P015-00-1/021/WAL-001	Wall: Internal - 1 - POM - Station Building - Southgate Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux and metal panelling					
12752	ACTIVE	P	P015-00-1/031	Mess Room - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20464	ACTIVE	P	P015-00-1/031/WAL-002	Wall: Internal - 2 - Mess Room - Station Building - Southgate Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LTB heater with foam insulation		1			



Hazardous Material Asset Register - Summary



P015-00 - Station Building - Southgate Stn																
Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12753	ACTIVE	P	P015-00-1/036	Toilet: Unisex - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12754	ACTIVE	P	P015-00-1/071	Circulation Area - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12755	ACTIVE	P	P015-00-1/151	UMC - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44064	ACTIVE	P	P015-00-1/151	UMC - Station Building - Southgate Stn	Other Electrical Boxes	Asbestos	Presumed				1 x transformer box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
46420	ACTIVE	P	P015-00-1/151	UMC - Station Building - Southgate Stn	Other Electrical Boxes	Asbestos	Presumed				Emergency battery supply to wall		1	R689101	N	N
46413	ACTIVE	P	P015-00-1/151	UMC - Station Building - Southgate Stn	Gasket :Pipework	Asbestos	Sampled – Not Detected				Gasket to pipework	1		R689101	N	N
46421	ACTIVE	P	P015-00-1/151	UMC - Station Building - Southgate Stn	Other Electrical Boxes	Asbestos	Presumed				6 Way E4 box to wall		1	R689101	N	N
46419	ACTIVE	P	P015-00-1/151	UMC - Station Building - Southgate Stn	Other Electrical Boxes	Asbestos	Presumed				6 Way E6 Box to wall		1	R689101	N	N
46412	ACTIVE	P	P015-00-1/151	UMC - Station Building - Southgate Stn	Pipe Lagging	Asbestos	Sampled – Not Detected				Pipe insulation to ceiling/wall			R689101	N	N
46414	ACTIVE	P	P015-00-1/151	UMC - Station Building - Southgate Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux boxing to wall/pipework	1		R689101	N	N
46415	ACTIVE	P	P015-00-1/151	UMC - Station Building - Southgate Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux panel to wall (Sampled twice)	1		R689101	N	N
46416	ACTIVE	P	P015-00-1/151	UMC - Station Building - Southgate Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel panel forming lid to flammable bin	1		R689101	N	N
46417	ACTIVE	P	P015-00-1/151	UMC - Station Building - Southgate Stn	Gasket :Pipework	Asbestos	Sampled – Not Detected				Gasket to Motor No. 1 to concrete slab	1		R689101	N	N
46418	ACTIVE	P	P015-00-1/151	UMC - Station Building - Southgate Stn	Gasket :Pipework	Asbestos	Sampled – Not Detected				Gasket to Motor No. 3 to concrete slab	1		R689101	N	N
20469	ACTIVE	P	P015-00-1/151	UMC - Station Building - Southgate Stn	Lead/Leading	Lead Paint/Lead	Known				Beams - 8m² Black gloss - thickness : 0.23mm Analysis : 22.8%				N	N
20465	ACTIVE	P	P015-00-1/151/CLG-01	Ceiling: Solid - 1 - UMC - Station Building - Southgate Stn	Cable: Sheath	Asbestos	Strongly Presumed				Wall 1 Cable sleeves in ceiling by 240v lamp control - Situated behind right hand side of escalator equipment, tucked into the corner of ceiling. 3 & 3 , 6no total Presumed bitumen sleeves				N	N



Hazardous Material Asset Register - Summary



P015-00 - Station Building - Southgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20466	ACTIVE	P	P015-00-1/151/WAL-003	Wall: Internal - 3 - UMC - Station Building - Southgate Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels above 1/668					
20468	ACTIVE	P	P015-00-1/151/WAL-003	Wall: Internal - 3 - UMC - Station Building - Southgate Stn	Cable Duct: Other	Asbestos	Strongly Presumed				11 x cable sleeves at high level, approx. 10m along right-hand side wall as you walk in the room Some terracotta - others no access		11		N	N
20467	ACTIVE	P	P015-00-1/151/WAL-004	Wall: Internal - 4 - UMC - Station Building - Southgate Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				3 x supply boxes No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		3		N	N
12756	ACTIVE	P	P015-00-1/236	Passage - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12757	ACTIVE	P	P015-00-1/237	Lobby - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23918	ACTIVE	P	P015-00-1/237/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Above false ceiling					
12758	ACTIVE	P	P015-00-1/238	Passage - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24038	ACTIVE	P	P015-00-1/238/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Suspended Supalux					
20471	ACTIVE	P	P015-00-1/238/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Southgate Stn	Void	Asbestos	Surveyed – Not Detected				Supalux boxing around vent above false ceiling				Yes	
20470	ACTIVE	P	P015-00-1/238/FLR-01 80879209	Floor - 1 - Passage - Station Building - Southgate Stn Floor	Void	Asbestos	No Access: Presumed				Wooden Boxing on floor by walls 3 and 4 - no access beneath No access into passage during 2020 re-inspection. Problem with door lock.				N	Y
20472	ACTIVE	P	P015-00-1/238/FLR-01	Floor - 1 - Passage - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Beneath Rubber Tiles					Yes
12759	ACTIVE	P	P015-00-1/239	Passage - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23919	INACTIVE	P	P015-00-1/239/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Above metal trunking and cable tray					
12760	ACTIVE	P	P015-00-1/281	Station Supervisor Office - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20475	ACTIVE	P	P015-00-1/281/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Southgate Stn	Void	Asbestos	Surveyed – Not Detected				Wooden panels. Supalux panels by fire equipment above false ceiling				Yes	



Hazardous Material Asset Register - Summary



P015-00 - Station Building - Southgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20474	ACTIVE	P	P015-00-1/281/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Southgate Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel/Solid					
20473	ACTIVE	P	P015-00-1/281/FLR-01	Floor - 1 - Station Supervisor Office - Station Building - Southgate Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath Computer Tiles part solid					Yes
12761	ACTIVE	P	P015-00-1/311	Office - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20476	ACTIVE	P	P015-00-1/311/FLR-01	Floor - 1 - Office - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Beneath Rubber Tiles					Yes
23920	ACTIVE	P	P015-00-1/311/WAL-004	Wall: Internal - 4 - Office - Station Building - Southgate Stn	Void	Asbestos	Surveyed – Not Detected				Supalux Boxing					
12762	ACTIVE	P	P015-00-1/331	Mess Room - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20695	ACTIVE	P	P015-00-1/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Above false ceiling					
20694	ACTIVE	P	P015-00-1/331/WAL-004	Wall: Internal - 4 - Mess Room - Station Building - Southgate Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LUL heater insulation, 2 foam panels		2			
12763	ACTIVE	P	P015-00-1/401	Bin Store - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12764	ACTIVE	P	P015-00-1/411	Toilet: Male - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20696	ACTIVE	P	P015-00-1/411/FLR-01	Floor - 1 - Toilet - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Beneath wooden flooring					Yes
12765	ACTIVE	P	P015-00-1/416	Toilet: Male - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20699	ACTIVE	P	P015-00-1/416/WAL-001	Wall: Internal - 1 - Toilet - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux Boxing around vent system					
20697	ACTIVE	P	P015-00-1/416/WAL-001	Wall: Internal - 1 - Toilet - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux panel					
20698	ACTIVE	P	P015-00-1/416/WAL-001	Wall: Internal - 1 - Toilet - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Behind Supalux panel					
20700	ACTIVE	P	P015-00-1/416/WAL-004	Wall: Internal - 4 - Toilet - Station Building - Southgate Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LUL heater - 2 foam panels		2			
12766	ACTIVE	P	P015-00-1/417	Toilet: Female - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P015-00 - Station Building - Southgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12767	ACTIVE	P	P015-00-1/451	Tenancy - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20705	ACTIVE	P	P015-00-1/451/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
20706	ACTIVE	P	P015-00-1/451/CLG-02	Ceiling: Suspended - 2 - Tenancy - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
20707	ACTIVE	P	P015-00-1/451/CLG-03	Ceiling: Suspended - 3 - Tenancy - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
20708	ACTIVE	P	P015-00-1/451/CLG-03	Ceiling: Suspended - 3 - Tenancy - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling - Ceilings 1-3				Yes	
23895	ACTIVE	P	P015-00-1/451/FLR-01	Floor - 1 - Tenancy - Station Building - Southgate Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino slats					
20701	ACTIVE	P	P015-00-1/451/WAL-001	Wall: Internal - 1 - Tenancy - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux					
20704	ACTIVE	P	P015-00-1/451/WAL-002	Wall: Internal - 2 - Tenancy - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux Panel, Metal and glass					
20702	ACTIVE	P	P015-00-1/451/WAL-003	Wall: Internal - 3 - Tenancy - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux					
20703	ACTIVE	P	P015-00-1/451/WAL-004	Wall: Internal - 4 - Tenancy - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux					
12768	ACTIVE	P	P015-00-1/452	Tenancy - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20709	ACTIVE	P	P015-00-1/452/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
20710	ACTIVE	P	P015-00-1/452/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles				Yes	
23971	ACTIVE	P	P015-00-1/452/FLR-01	Floor - 1 - Tenancy - Station Building - Southgate Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Floor - Vinyl tiles, 2m² cream & 7m² grey/brown					
20711	ACTIVE	P	P015-00-1/452/WAL-003	Wall: Internal - 3 - Tenancy - Station Building - Southgate Stn	Isolator Switches	Asbestos	No Access: Presumed				Fuse box, insulation inside -Inside wood panel wall 3 No access into tenancy during 2020 re-inspection. Closed.		1		N	N
12769	ACTIVE	P	P015-00-1/453	Tenancy - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P015-00 - Station Building - Southgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20718	ACTIVE	P	P015-00-1/453/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
20719	ACTIVE	P	P015-00-1/453/CLG-02	Ceiling: Suspended - 2 - Tenancy - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
20720	ACTIVE	P	P015-00-1/453/CLG-03	Ceiling: Suspended - 3 - Tenancy - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
20721	ACTIVE	P	P015-00-1/453/DOR-01	Door - 1 - Tenancy - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling - Ceilings 1-3					
20712	ACTIVE	P	P015-00-1/453/FLR-01	Floor - 1 - Tenancy - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
23972	ACTIVE	P	P015-00-1/453/FLR-02	Floor - 2 - Tenancy - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
20714	ACTIVE	P	P015-00-1/453/FLR-03	Floor - 3 - Tenancy - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Beneath Supalux Tiles - floors 1-3					Yes
20713	ACTIVE	P	P015-00-1/453/FLR-03	Floor - 3 - Tenancy - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
20715	ACTIVE	P	P015-00-1/453/WAL-001	Wall: Internal - 1 - Tenancy - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
23973	ACTIVE	P	P015-00-1/453/WAL-002	Wall: Internal - 2 - Tenancy - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
20716	ACTIVE	P	P015-00-1/453/WAL-002	Wall: Internal - 2 - Tenancy - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
20717	ACTIVE	P	P015-00-1/453/WAL-003	Wall: Internal - 3 - Tenancy - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Behind Supalux Tiles - Walls 1-3					
12770	ACTIVE	P	P015-00-1/454	Tenancy - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20726	ACTIVE	P	P015-00-1/454/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Above false ceilings				Yes	
23896	ACTIVE	P	P015-00-1/454/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
20722	ACTIVE	P	P015-00-1/454/FLR-01	Floor - 1 - Tenancy - Station Building - Southgate Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
20723	ACTIVE	P	P015-00-1/454/WAL-001	Wall: Internal - 1 - Tenancy - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					



Hazardous Material Asset Register - Summary



P015-00 - Station Building - Southgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20724	ACTIVE	P	P015-00-1/454/WAL-003	Wall: Internal - 3 - Tenancy - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
20725	ACTIVE	P	P015-00-1/454/WAL-004	Wall: Internal - 4 - Tenancy - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
12771	ACTIVE	P	P015-00-1/455	Tenancy - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20732	ACTIVE	P	P015-00-1/455	Tenancy - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Tenancy Back Office - above Supalux Tiles					
20730	ACTIVE	P	P015-00-1/455	Tenancy - Station Building - Southgate Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Tenancy Back Office - Walls - Plasterboard Partition					
20731	ACTIVE	P	P015-00-1/455	Tenancy - Station Building - Southgate Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Tenancy Back Office - Ceiling - Supalux Tiles					
20728	ACTIVE	P	P015-00-1/455/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Hatch Cupboard				Yes	
20729	ACTIVE	P	P015-00-1/455/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Above false ceiling and hatch cupboard				Yes	
20727	ACTIVE	P	P015-00-1/455/WAL-001	Wall: Internal - 1 - Tenancy - Station Building - Southgate Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
12772	ACTIVE	P	P015-00-1/456	Tenancy - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20735	ACTIVE	P	P015-00-1/456/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed									
24041	ACTIVE	P	P015-00-1/456/FLR-01	Floor - 1 - Tenancy - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden Slats					Yes
20733	ACTIVE	P	P015-00-1/456/FLR-02	Floor - 2 - Tenancy - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden Slats					Yes
20734	ACTIVE	P	P015-00-1/456/WAL-001	Wall: Internal - 1 - Tenancy - Station Building - Southgate Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Inner Wall - Plasterboard Partition					
23974	ACTIVE	P	P015-00-1/456/WAL-003	Wall: Internal - 3 - Tenancy - Station Building - Southgate Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Inner Wall - Plasterboard Partition					
12773	ACTIVE	P	P015-00-1/457	Tenancy - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20740	ACTIVE	P	P015-00-1/457/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles				Yes	



Hazardous Material Asset Register - Summary



P015-00 - Station Building - Southgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23975	ACTIVE	P	P015-00-1/457/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Southgate Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Supalux Tiles					
20736	ACTIVE	P	P015-00-1/457/WAL-001	Wall: Internal - 1 - Tenancy - Station Building - Southgate Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
20737	ACTIVE	P	P015-00-1/457/WAL-002	Wall: Internal - 2 - Tenancy - Station Building - Southgate Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
20738	ACTIVE	P	P015-00-1/457/WAL-003	Wall: Internal - 3 - Tenancy - Station Building - Southgate Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
20739	ACTIVE	P	P015-00-1/457/WAL-004	Wall: Internal - 4 - Tenancy - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Behind Hatch					
12774	ACTIVE	P	P015-00-1/458	Tenancy - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20745	ACTIVE	P	P015-00-1/458/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Southgate Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Supalux Tiles					
20746	ACTIVE	P	P015-00-1/458/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles				Yes	
20741	ACTIVE	P	P015-00-1/458/FLR-01	Floor - 1 - Tenancy - Station Building - Southgate Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
20742	ACTIVE	P	P015-00-1/458/WAL-001	Wall: Internal - 1 - Tenancy - Station Building - Southgate Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
23976	ACTIVE	P	P015-00-1/458/WAL-002	Wall: Internal - 2 - Tenancy - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux around window					
20743	ACTIVE	P	P015-00-1/458/WAL-003	Wall: Internal - 3 - Tenancy - Station Building - Southgate Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
20747	ACTIVE	P	P015-00-1/458/WAL-004	Wall: Internal - 4 - Tenancy - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Partition wall 4 not accessible to sample					
20744	ACTIVE	P	P015-00-1/458/WAL-004	Wall: Internal - 4 - Tenancy - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Hatch - no access behind lock broken					
12775	ACTIVE	P	P015-00-1/576	UMC - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46410	ACTIVE	P	P015-00-1/576	UMC - Station Building - Southgate Stn	Pipe Lagging	Asbestos	Sampled – Not Detected				Pipe insulation to pipework	3		R689101	N	N
46411	ACTIVE	P	P015-00-1/576	UMC - Station Building - Southgate Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux boxing to pipe insulation on wall	1		R689101	N	N



Hazardous Material Asset Register - Summary



P015-00 - Station Building - Southgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12776	ACTIVE	P	P015-00-1/664	Switch Room - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44180	INACTIVE	P	P015-00-1/664	Switch Room - Station Building - Southgate Stn		Asbestos	Strongly Presumed				Cable Sleeves - No access					
20537	ACTIVE	P	P015-00-1/664	Switch Room - Station Building - Southgate Stn	Cable Ducts: Cement	Asbestos	No Access: Presumed				Cable sleeves - concrete sealed surrounds					
20533	ACTIVE	P	P015-00-1/664/FLR-01	Floor - 1 - Switch Room - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				3 x Hatches in floor - No access below					Yes
20534	ACTIVE	P	P015-00-1/664/FLR-01	Floor - 1 - Switch Room - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux Boxing on floor by walls 1 and 2 x 2					
44058	ACTIVE	P	P015-00-1/664/WAL-002 80879464	Wall: Internal - 2 - Switch Room - Station Building - Southgate Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				3x transformer boxes No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		3		N	N
20536	ACTIVE	P	P015-00-1/664/WAL-003 80879465	Wall: Internal - 3 - Switch Room - Station Building - Southgate Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				1x - Iron clad isolator 30amps No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
44059	ACTIVE	P	P015-00-1/664/WAL-003 80879465	Wall: Internal - 3 - Switch Room - Station Building - Southgate Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				1 x transformer box wall 3 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
20535	ACTIVE	P	P015-00-1/664/WAL-004 80879466	Wall: Internal - 4 - Switch Room - Station Building - Southgate Stn Wall: Internal	Other Electrical Boxes	Asbestos	Strongly Presumed				Delta electrical system No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
12777	ACTIVE	P	P015-00-1/666	Switch Room - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20538	ACTIVE	P	P015-00-1/666/FLR-01	Floor - 1 - Switch Room - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux panel on floor by wall 2					
20539	ACTIVE	P	P015-00-1/666/FLR-01	Floor - 1 - Switch Room - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Beneath 2 x metal checker plates on floor					Yes
20541	ACTIVE	P	P015-00-1/666/WAL-002 80879473	Wall: Internal - 2 - Switch Room - Station Building - Southgate Stn Wall: Internal	Other Electrical Boxes	Asbestos	Strongly Presumed				Trunking at high and low level No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within				N	N



Hazardous Material Asset Register - Summary



P015-00 - Station Building - Southgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23890	ACTIVE	P	P015-00-1/666/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Southgate Stn	Isolator Switches	Asbestos	Strongly Presumed				7 x iron clad isolators No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		7		N	N
20540	ACTIVE	P	P015-00-1/666/WAL-003 80879474	Wall: Internal - 3 - Switch Room - Station Building - Southgate Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				1 x iron clad isolators, 30 amp		1		N	N
12778	ACTIVE	P	P015-00-1/667	Switch Cupboard - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20542	ACTIVE	P	P015-00-1/667	Switch Cupboard - Station Building - Southgate Stn	Cable Duct: Other	Asbestos	No Access: Presumed				Cable sleeves - filled in no access					
12779	ACTIVE	P	P015-00-1/668	Switch Cupboard - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20543	ACTIVE	P	P015-00-1/668/WAL-001	Wall: Internal - 1 - Switch Cupboard - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux Paneling					
20544	ACTIVE	P	P015-00-1/668/WAL-003	Wall: Internal - 3 - Switch Cupboard - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux Paneling					
20545	ACTIVE	P	P015-00-1/668/WAL-004	Wall: Internal - 4 - Switch Cupboard - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux Paneling					
12780	ACTIVE	P	P015-00-1/669	Switch Room - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20546	ACTIVE	P	P015-00-1/669	Switch Room - Station Building - Southgate Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
12781	ACTIVE	P	P015-00-1/746	SCR - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12782	ACTIVE	P	P015-00-1/761	Equipment Room - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20547	ACTIVE	P	P015-00-1/761/FLR-01	Floor - 1 - Equipment Room - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Beneath metal hatch check plate					Yes
12783	ACTIVE	P	P015-00-1/762	Computer Equipment Cupboard - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20548	ACTIVE	P	P015-00-1/762	Computer Equipment Cupboard - Station Building - Southgate Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					



Hazardous Material Asset Register - Summary



P015-00 - Station Building - Southgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12784	ACTIVE	P	P015-00-1/763	Computer Equipment Cupboard - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20549	ACTIVE	P	P015-00-1/763	Computer Equipment Cupboard - Station Building - Southgate Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
12785	ACTIVE	P	P015-00-1/764	Computer Equipment Cupboard - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23929	ACTIVE	P	P015-00-1/764	Computer Equipment Cupboard - Station Building - Southgate Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
12786	ACTIVE	P	P015-00-1/765	Computer Equipment Cupboard - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20550	ACTIVE	P	P015-00-1/765	Computer Equipment Cupboard - Station Building - Southgate Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
12787	ACTIVE	P	P015-00-1/766	Computer Equipment Cupboard - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20551	ACTIVE	P	P015-00-1/766	Computer Equipment Cupboard - Station Building - Southgate Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
20552	ACTIVE	P	P015-00-1/791	Vent Shaft - Station Building - Southgate Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Sealed access hatch in 1/416					
12788	ACTIVE	P	P015-00-1/901	GLAP - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20553	ACTIVE	P	P015-00-1/901/CLG-01	Ceiling: Solid - 1 - GLAP - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Metal, Supalux, solid on top of canopy. Ceiling canopy underside wood					
23930	ACTIVE	P	P015-00-1/901/FLR-01	Floor - 1 - GLAP - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Tiles					Yes
12789	ACTIVE	P	P015-00-2/081	Circulation Area - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20555	ACTIVE	P	P015-00-2/081	Circulation Area - Station Building - Southgate Stn	Lead/Leading	Lead Paint/Lead	Known				Window frames outside 2/236 - 1m² White gloss. Thickness : 0.36mm Analysis : 1.33%				N	N
20554	ACTIVE	P	P015-00-2/081/FLR-01	Floor - 1 - Circulation Area - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Beneath Hatches					Yes
12790	ACTIVE	P	P015-00-2/161	LMC - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P015-00 - Station Building - Southgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46425	ACTIVE	P	P015-00-2/161	LMC - Station Building - Southgate Stn	Other Electrical Boxes	Asbestos	Presumed				Control gear boxes to wall - 3no.		3	R689101	N	N
46429	ACTIVE	P	P015-00-2/161	LMC - Station Building - Southgate Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel caulking to tunnel walls LHS - Throughout			R689101	N	N
46430	ACTIVE	P	P015-00-2/161	LMC - Station Building - Southgate Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel caulking to tunnel walls RHS - Throughout			R689101	N	N
46428	ACTIVE	P	P015-00-2/161	LMC - Station Building - Southgate Stn	Other Electrical Boxes	Asbestos	Presumed				Pump No. 1 supply to wall - 1no.		1	R689101	N	N
46427	ACTIVE	P	P015-00-2/161	LMC - Station Building - Southgate Stn	Other Electrical Boxes	Asbestos	Presumed				Control gear boxes to wall - 3no.		3	R689101	N	N
46422	ACTIVE	P	P015-00-2/161	LMC - Station Building - Southgate Stn	Gasket :Pipework	Asbestos	Sampled – Not Detected				Metal pipework gasket (Sampled twice)	1		R689101	N	N
46423	ACTIVE	P	P015-00-2/161	LMC - Station Building - Southgate Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel caulking to tunnel walls on LHS			R689101	N	N
46424	ACTIVE	P	P015-00-2/161	LMC - Station Building - Southgate Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel caulking to tunnel walls on RHS			R689101	N	N
46426	ACTIVE	P	P015-00-2/161	LMC - Station Building - Southgate Stn	Westing house Boxes	Asbestos	Presumed				Small westinghouse boxes to wall - 2no.		2	R689101	N	N
20556	ACTIVE	P	P015-00-2/161/FLR-01	Floor - 1 - LMC - Station Building - Southgate Stn	Void	Asbestos	Surveyed – Not Detected				Sumps below false floor					Yes
23931	ACTIVE	P	P015-00-2/161/WAL-001	Wall: Internal - 1 - LMC - Station Building - Southgate Stn	Caulking	Asbestos	Strongly Presumed				Tunnel rings sealed with concrete No access into LMC during 2020 re-inspection in traffic hours. Access via manhole required.				N	N
20557	ACTIVE	P	P015-00-2/161/WAL-001	Wall: Internal - 1 - LMC - Station Building - Southgate Stn	Cable: Sheath	Asbestos	No Access: Presumed				8x Cable sleeves, filled in - Walls 1 and 3 No access into LMC during 2020 re-inspection in traffic hours. Access via manhole required.		8		N	N
20559	ACTIVE	P	P015-00-2/161/WAL-001	Wall: Internal - 1 - LMC - Station Building - Southgate Stn	Westing house Boxes	Asbestos	No Access: Presumed				3 Westinghouse boxes - Walls 1 & 3 No access into LMC during 2020 re-inspection in traffic hours. Access via manhole required.		3		N	N
20560	ACTIVE	P	P015-00-2/161/WAL-003	Wall: Internal - 3 - LMC - Station Building - Southgate Stn	Westing house Boxes	Asbestos	Strongly Presumed				3 Westinghouse boxes - Walls 1 & 3 No access into LMC during 2020 re-inspection in traffic hours. Access via manhole required.		3		N	N
20558	ACTIVE	P	P015-00-2/161/WAL-003	Wall: Internal - 3 - LMC - Station Building - Southgate Stn	Cable: Sheath	Asbestos	No Access: Presumed				8x Cable sleeves, filled in - Walls 1 and 3 No access into LMC during 2020 re-inspection in traffic hours. Access via manhole required.		8		N	N



Hazardous Material Asset Register - Summary



P015-00 - Station Building - Southgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23614	ACTIVE	P	P015-00-2/161/WAL-003	Wall: Internal - 3 - LMC - Station Building - Southgate Stn	Caulking	Asbestos	Strongly Presumed				Tunnel rings sealed with concrete No access into LMC during 2020 re-inspection in traffic hours. Access via manhole required.				N	N
12791	ACTIVE	P	P015-00-2/201	Passage - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12792	ACTIVE	P	P015-00-2/202	Passage - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12793	ACTIVE	P	P015-00-2/203	Passage - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12794	ACTIVE	P	P015-00-2/204	Passage - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12795	ACTIVE	P	P015-00-2/205	Passage - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12796	ACTIVE	P	P015-00-2/236	Passage - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20563	ACTIVE	P	P015-00-2/236	Passage - Station Building - Southgate Stn	Lead/Leading	Lead Paint/Lead	Known				Stretcher ceiling board - 2m ² green gloss. Thickness : 0.36mm Analysis : 1.33%				N	N
20561	ACTIVE	P	P015-00-2/236/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				No info on ceiling construction				Yes	
20562	ACTIVE	P	P015-00-2/236/WAL-006	Wall: Internal - 6 - Passage - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Behind Supalux Boxing and Wooden Panels					
12797	ACTIVE	P	P015-00-2/261	Platform 1 - Eastbound Local - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20569	ACTIVE	P	P015-00-2/261	Platform 1 - Eastbound Local - Station Building - Southgate Stn	Caulking	Asbestos	Strongly Presumed				Tail wall - Tunnel ring caulking No access onto track during 2020 re-inspection in traffic hours. Item not accessed.				N	N
20570	ACTIVE	P	P015-00-2/261	Platform 1 - Eastbound Local - Station Building - Southgate Stn	Cable: Sheath	Asbestos	Known				Tail Wall - J Hanger 2 - 3 x Cables running to Duct 2 Viewed from platform only therefore not scored during 2020 re-inspection		3		N	N
20564	ACTIVE	P	P015-00-2/261	Platform 1 - Eastbound Local - Station Building - Southgate Stn	No Access	Asbestos	No Access: Presumed				Metal fronted cupboard by 2/711 - no access					



Hazardous Material Asset Register - Summary



P015-00 - Station Building - Southgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20566	ACTIVE	P	P015-00-2/261	Platform 1 - Eastbound Local - Station Building - Southgate Stn	Cable: Sheath	Asbestos	Known				Head Wall - J Hanger 3 - 3 x Cables to duct 2 No access onto track during 2020 re-inspection during traffic hours. Item not accessed.		3		N	N
20568	ACTIVE	P	P015-00-2/261	Platform 1 - Eastbound Local - Station Building - Southgate Stn	Caulking	Asbestos	Strongly Presumed				Headwall - Tunnel ring caulking No access onto track during 2020 re-inspection during traffic hours. Item not accessed.				N	N
46465	ACTIVE	P	P015-00-2/261	Platform 1 - Eastbound Local - Station Building - Southgate Stn	Cable Duct: Other	Asbestos	Sampled – Not Detected				9no. Cable ducts to track wall at arrival end		9	R685826	N	N
46464	ACTIVE	P	P015-00-2/261	Platform 1 - Eastbound Local - Station Building - Southgate Stn	Cable Duct: Other	Asbestos	Sampled – Not Detected				9no. Cable ducts to track wall at departure end		9	R685826	N	N
46385	ACTIVE	P	P015-00-2/261	Platform 1 - Eastbound Local - Station Building - Southgate Stn	Cable Duct: Other	Asbestos	Sampled – Not Detected				Cable Ducts 9no Arrival and Tail End Walls			R685826		
23615	ACTIVE	P	P015-00-2/261	Platform 1 - Eastbound Local - Station Building - Southgate Stn	Cable: Sheath	Asbestos	Strongly Presumed				Eastbound Invert - Hatch near 2/711 5x Cables from ceiling near head wall No access into platform inverts during 2020 re-inspection. Confined space.		5		N	Y
20574	ACTIVE	P	P015-00-2/261	Platform 1 - Eastbound Local - Station Building - Southgate Stn	Cable: Sheath	Asbestos	Strongly Presumed				Eastbound Invert - 1x Cable from pit side ceiling to ceiling No access into platform inverts during 2020 re-inspection. Confined space.		1		N	N
20575	ACTIVE	P	P015-00-2/261	Platform 1 - Eastbound Local - Station Building - Southgate Stn	Westing house Boxes	Asbestos	Strongly Presumed				Eastbound Invert - Halfway - Westinghouse box insulation No access into platform inverts during 2020 re-inspection. Confined space.		1		N	N
20572	ACTIVE	P	P015-00-2/261	Platform 1 - Eastbound Local - Station Building - Southgate Stn	Cable: Sheath	Asbestos	Known				Tail Wall - J hanger 4 - 1 x Cable runs to 4th Duct into 2/711 No access onto track during 2020 re-inspection in traffic hours. Item not accessed.		1		N	N
20567	ACTIVE	P	P015-00-2/261	Platform 1 - Eastbound Local - Station Building - Southgate Stn	Cable: Sheath	Asbestos	Known				Head Wall - J hanger 4 - 1x 60mm Cable leading to duct 3 & 4 No access onto track during 2020 re-inspection during traffic hours. Item not accessed.		1		N	N
20573	ACTIVE	P	P015-00-2/261	Platform 1 - Eastbound Local - Station Building - Southgate Stn	Cable: Sheath	Asbestos	Strongly Presumed				Eastbound Invert - 1x Cable from ceiling along pit wall No access into platform inverts during 2020 re-inspection. Confined space.		1		N	N



Hazardous Material Asset Register - Summary



P015-00 - Station Building - Southgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20571	ACTIVE	P	P015-00-2/261	Platform 1 - Eastbound Local - Station Building - Southgate Stn	Cable: Sheath	Asbestos	Known				Tail Wall - J Hanger 3 - 2 x Cables runs to 3rd Duct into 2/711 No access onto track during 2020 re-inspection in traffic hours. Item not accessed.		2		N	N
20576	ACTIVE	P	P015-00-2/261	Platform 1 - Eastbound Local - Station Building - Southgate Stn	Cable: Sheath	Asbestos	Strongly Presumed				Eastbound Invert - Below 2/713 - All cables from other end through ceiling near 2/713 No access into platform inverts during 2020 re-inspection. Confined space.				N	N
20565	ACTIVE	P	P015-00-2/261	Platform 1 - Eastbound Local - Station Building - Southgate Stn	Lead/Leading	Lead Paint/Lead	Known				Grit bin - 2m ² Red Gloss. Thickness : 0.36mm Analysis : 1.33%				N	N
12798	ACTIVE	P	P015-00-2/262	Platform 2 - Westbound Local - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20581	ACTIVE	P	P015-00-2/262	Platform 2 - Westbound Local - Station Building - Southgate Stn	Cable: Sheath	Asbestos	Strongly Presumed				Westbound Invert - Down Hatch near 2/712 - 3x Cables from 2/712 end pit side near hatch No access into platform inverts during 2020 re-inspection. Confined space.		3		N	N
20580	ACTIVE	P	P015-00-2/262	Platform 2 - Westbound Local - Station Building - Southgate Stn	Cable: Sheath	Asbestos	Strongly Presumed				Westbound Invert - Down Hatch near 2/714 - 2x Cables from platform side near head wall, along pit side No access into platform inverts during 2020 re-inspection. Confined space.		2		N	N
46386	ACTIVE	P	P015-00-2/262	Platform 2 - Westbound Local - Station Building - Southgate Stn	Cable Duct: Other	Asbestos	Sampled – Not Detected				Cable Ducts 9no Arrival and Tail End Walls			R685826		
20579	ACTIVE	P	P015-00-2/262	Platform 2 - Westbound Local - Station Building - Southgate Stn	Cable: Sheath	Asbestos	Strongly Presumed				Westbound Invert - Down Hatch near 2/714 - 2x Cables from ceiling head wall, 1 going from ceiling to ceiling No access into platform inverts during 2020 re-inspection. Confined space.		2		N	N
46466	ACTIVE	P	P015-00-2/262	Platform 2 - Westbound Local - Station Building - Southgate Stn	Cable Duct: Other	Asbestos	Sampled – Not Detected				9no. Cable ducts to track wall at departure end		9	R685826	N	N
46467	ACTIVE	P	P015-00-2/262	Platform 2 - Westbound Local - Station Building - Southgate Stn	Cable Duct: Other	Asbestos	Sampled – Not Detected				9no. Cable ducts to track wall at arrival end		9	R685826	N	N
20578	ACTIVE	P	P015-00-2/262	Platform 2 - Westbound Local - Station Building - Southgate Stn	Lead/Leading	Lead Paint/Lead	Known				Grit bin - 2m ² Red gloss - Nr 2/712 - Thickness : 0.18mm Analysis : 11% Grit bin surround - 1m ² Dark red Nr 2/712 - Thickness : 0.39mm Analysis : 10.3%		1		N	N
20577	ACTIVE	P	P015-00-2/262/ WAL-001	Wall: Internal - 1 - Platform 2 - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Trunking walls 1 and 3					



Hazardous Material Asset Register - Summary



P015-00 - Station Building - Southgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23932	ACTIVE	P	P015-00-2/262/WAL-003	Wall: Internal - 3 - Platform 2 - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Trunking walls 1 and 3					
12799	ACTIVE	P	P015-00-2/281	Store - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20582	ACTIVE	P	P015-00-2/281/WAL-001	Wall: Internal - 1 - Store - Station Building - Southgate Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LTB heater insulation 2 x foam panels		2			
23933	ACTIVE	P	P015-00-2/281/WAL-003	Wall: Internal - 3 - Store - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux panel and frame behind window					
12800	ACTIVE	P	P015-00-2/371	Store - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12801	ACTIVE	P	P015-00-2/661	Switch Room - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20583	ACTIVE	P	P015-00-2/661	Switch Room - Station Building - Southgate Stn	Other Electrical Boxes	Asbestos	Surveyed – Not Detected				Electrical equipment - NEW		1		N	N
20584	ACTIVE	P	P015-00-2/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Southgate Stn	Cable Duct: Other	Asbestos	Presumed				Cable Sleeves filled in - E2 Wall 1				N	N
12802	ACTIVE	P	P015-00-2/663	Switch Room - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20585	ACTIVE	P	P015-00-2/663/FLR-01	Floor - 1 - Switch Room - Station Building - Southgate Stn	Cable: Sheath	Asbestos	No Access: Presumed				No Access to Cable Sleeve - Presumed					Yes
23957	ACTIVE	P	P015-00-2/663/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Southgate Stn	Other Electrical Boxes	Asbestos	Presumed				1x Tranformer Box Wall 1 Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
20586	INACTIVE	P	P015-00-2/663/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Southgate Stn	Cable Duct: Other	Asbestos	No Access: Presumed				Concrete finished cable sleeve - no access below					
20642	ACTIVE	P	P015-00-2/663/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Southgate Stn	Isolator Switches	Asbestos	Strongly Presumed				6 x Iron clad isolators insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		6		N	N
20643	ACTIVE	P	P015-00-2/663/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Southgate Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x Iron clad isolators insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N



Hazardous Material Asset Register - Summary



P015-00 - Station Building - Southgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20645	ACTIVE	P	P015-00-2/663/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Southgate Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Trunking - insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within				N	N
20644	ACTIVE	P	P015-00-2/663/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Southgate Stn	Isolator Switches	Asbestos	Strongly Presumed				5 x Iron clad isolators insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		5		N	N
12803	ACTIVE	P	P015-00-2/711	Relay Room - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20648	ACTIVE	P	P015-00-2/711	Relay Room - Station Building - Southgate Stn	Cable: Sheath	Asbestos	Strongly Presumed				5x cable sleeves - Head wall back of room - no access filled in Cable sleeve not visible behind filling therefore not scored in 2020 reinspection.		5		N	N
42112	INACTIVE	P	P015-00-2/711	Relay Room - Station Building - Southgate Stn	PCBs	Polychlorinated biphenyl	Known				6 x PCB's - Fair Condition. Located within roller shutter cabinet		6		N	N
20647	ACTIVE	P	P015-00-2/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Southgate Stn	Cable: Sheath	Asbestos	Strongly Presumed				7x cables - walls 2 and 3		7		N	N
44060	ACTIVE	P	P015-00-2/711/WAL-002 80879619	Wall: Internal - 2 - Relay Room - Station Building - Southgate Stn Wall: Internal	Other Boarding	Asbestos	Presumed				Paxoline boarding within roller shutter cabinet				N	N
20646	ACTIVE	P	P015-00-2/711/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Southgate Stn	Cable: Sheath	Asbestos	Strongly Presumed				2 x 5cm cables from 600v supply box		2		N	N
12804	ACTIVE	P	P015-00-2/712	Relay Room - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44197	INACTIVE	P	P015-00-2/712	Relay Room - Station Building - Southgate Stn		Polychlorinated biphenyl	Presumed				6 oblong black box PCB terminals behind roller shutter					
20649	ACTIVE	P	P015-00-2/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Southgate Stn	Cable: Sheath	Asbestos	Strongly Presumed				3 x Cables		3		N	N
44061	ACTIVE	P	P015-00-2/712/WAL-003 80879627	Wall: Internal - 3 - Relay Room - Station Building - Southgate Stn Wall: Internal	Other Boarding	Asbestos	Presumed				Paxoline boarding behind equipment box and glass panel		1		N	N
12805	ACTIVE	P	P015-00-2/713	Relay Room - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20651	ACTIVE	P	P015-00-2/713/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Southgate Stn	Cable: Sheath	Asbestos	Strongly Presumed				6 x Cables - wall 1 - wall 2 - From invert to head wall		6		N	N
20650	ACTIVE	P	P015-00-2/713/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Southgate Stn	Cable: Sheath	Asbestos	Strongly Presumed				2 x cables - wall 4 to wall 2 - cable from signal light to head wall		2		N	N



Hazardous Material Asset Register - Summary



P015-00 - Station Building - Southgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12806	ACTIVE	P	P015-00-2/714	Relay Room - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20652	ACTIVE	P	P015-00-2/714	Relay Room - Station Building - Southgate Stn	Cable: Sheath	Asbestos	Strongly Presumed				2 x Cables from 600v Supply Box - Wall 2		2		N	N
42113	INACTIVE	P	P015-00-2/714	Relay Room - Station Building - Southgate Stn	PCBs	Polychlorinated biphenyl	Known				7 x PCB's - Fair Condition - located within roller shutter cabinet		7		N	N
44062	INACTIVE	P	P015-00-2/714/ WAL-002 80879642	Wall: Internal - 2 - Relay Room - Station Building - Southgate Stn Wall: Internal	Cable: Sheath	Asbestos	Presumed				5 x woven cable sheath coming from roller shutter cabinet		5		N	N
20653	ACTIVE	P	P015-00-2/714/ WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Southgate Stn	Cable: Sheath	Asbestos	Strongly Presumed				9 x cables - Wall 2 - from headwall going into roller shutter cabinet		9		N	N
44063	ACTIVE	P	P015-00-2/714/ WAL-002 80879642	Wall: Internal - 2 - Relay Room - Station Building - Southgate Stn Wall: Internal	Other Boarding	Asbestos	Presumed				Paxoline boarding in roller shutter cabinet				N	N
20654	ACTIVE	P	P015-00-2/714/ WAL-003 80879643	Wall: Internal - 3 - Relay Room - Station Building - Southgate Stn Wall: Internal	Cable Duct: Other	Asbestos	Strongly Presumed				5x Cable Sleeves - Head Wall- filled in Cable sleeves not visible beneath filling therefore not scored in 2020 reinspection.		5		N	N
12807	ACTIVE	P	P015-00-2/731	CER - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20656	ACTIVE	P	P015-00-2/731/ WAL-001 80879648	Wall: Internal - 1 - CER - Station Building - Southgate Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				2 x Combination fuse switches 2x60amps No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2		N	N
20655	ACTIVE	P	P015-00-2/731/ WAL-005 80879652	Wall: Internal - 5 - CER - Station Building - Southgate Stn Wall: Internal	Other Boarding	Asbestos	Presumed				Paxoline Board		1		N	N
12808	ACTIVE	P	P015-00-2/761	Equipment Room - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20657	ACTIVE	P	P015-00-2/761/ WAL-001	Wall: Internal - 1 - Equipment Room - Station Building - Southgate Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Supalux panel on frame					
12809	ACTIVE	P	P015-00-2/762	Computer Equipment Cupboard - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12810	ACTIVE	P	P015-00-2/763	Computer Equipment Cupboard - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12811	ACTIVE	P	P015-00-2/764	Computer Equipment Cupboard - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P015-00 - Station Building - Southgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12812	ACTIVE	P	P015-00-2/765	Computer Equipment Cupboard - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12813	ACTIVE	P	P015-00-2/766	Computer Equipment Cupboard - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12814	ACTIVE	P	P015-00-2/786	Service Riser - Station Building - Southgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20660	ACTIVE	P	P015-00-2/786/CLG-01	Ceiling: Solid - 1 - Service Riser - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Opposite side - 14 Supalux panels					
23965	INACTIVE	P	P015-00-2/786/CLG-01	Ceiling: Solid - 1 - Service Riser - Station Building - Southgate Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
23964	ACTIVE	P	P015-00-2/786/FLR-01	Floor - 1 - Service Riser - Station Building - Southgate Stn		Asbestos	Surveyed – Not Detected				Supalux debris on floor					
20658	ACTIVE	P	P015-00-2/786/WAL-001	Wall: Internal - 1 - Service Riser - Station Building - Southgate Stn	Caulking	Asbestos	No Access: Presumed				Entrance Side - Tunnel rings sealed, caulking No access into service riser during 2020 re-inspection. Confined space.				N	N
20659	ACTIVE	P	P015-00-2/786/WAL-001	Wall: Internal - 1 - Service Riser - Station Building - Southgate Stn	Cable Duct: Other	Asbestos	No Access: Presumed				Entrance Side - Six cable sleeves No access into service riser during 2020 re-inspection. Confined space.		6		N	N
23616	ACTIVE	P	P015-00-2/786/WAL-003	Wall: Internal - 3 - Service Riser - Station Building - Southgate Stn	Westing house Boxes	Asbestos	No Access: Presumed				Entrance Side - Westinghouse boxes No access into service riser during 2020 re-inspection. Confined space.				N	N

P021-00 - Station Building - Arnos Grove Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12815	ACTIVE	P	P021-00-1/001	Booking Hall - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20661	ACTIVE	P	P021-00-1/001	Booking Hall - Station Building - Arnos Grove Stn	Void	Asbestos	No Access: Presumed				Behind Black boarding - Wood (To Tenancies?)					YES
44548	ACTIVE	P	P021-00-1/001	Booking Hall - Station Building - Arnos Grove Stn	Lead/Leading	Lead Paint/Lead	Presumed				Blue lead paint on shutters at top of stairs				N	N
12816	ACTIVE	P	P021-00-1/011	Ticket Office - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23893	ACTIVE	P	P021-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Arnos Grove Stn	Void	Asbestos	Surveyed – Not Detected				Plaster/solid above false ceiling				Yes	



Hazardous Material Asset Register - Summary



P021-00 - Station Building - Arnos Grove Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20663	ACTIVE	P	P021-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Arnos Grove Stn		Asbestos	Surveyed – Not Detected				Supalux					
20662	ACTIVE	P	P021-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Arnos Grove Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
12817	ACTIVE	P	P021-00-1/021	POM - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20664	ACTIVE	P	P021-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Arnos Grove Stn		Asbestos	Surveyed – Not Detected				Supalux					
20665	ACTIVE	P	P021-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Arnos Grove Stn	Void	Asbestos	No Access: Presumed				Above Supalux				Yes	
23966	ACTIVE	P	P021-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Arnos Grove Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
12818	ACTIVE	P	P021-00-1/031	Mess Room - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20667	ACTIVE	P	P021-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Arnos Grove Stn	Void	Asbestos	Surveyed – Not Detected				Plaster/solid above false ceiling				Yes	
20666	ACTIVE	P	P021-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Arnos Grove Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
12819	ACTIVE	P	P021-00-1/036	Toilet: Unisex - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20669	ACTIVE	P	P021-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Arnos Grove Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux				Yes	
20668	ACTIVE	P	P021-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Arnos Grove Stn		Asbestos	Surveyed – Not Detected				Supalux					
12820	ACTIVE	P	P021-00-1/047	Mess Room - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20670	ACTIVE	P	P021-00-1/047/WAL-002	Wall: Internal - 2 - Mess Room - Station Building - Arnos Grove Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - Foam insulation		1			
12821	ACTIVE	P	P021-00-1/201	Passage - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P021-00 - Station Building - Arnos Grove Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44547	ACTIVE	P	P021-00-1/201	Passage - Station Building - Arnos Grove Stn	Lead/Leading	Lead Paint/Lead	Presumed				Blue lead paint on shutters				N	N
20671	INACTIVE	P	P021-00-1/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Arnos Grove Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
20672	ACTIVE	P	P021-00-1/201/CLG-02	Ceiling: Solid - 2 - Passage - Station Building - Arnos Grove Stn	Void	Asbestos	No Access: Presumed				Black boarding - Wood - Ceiling No Access				Yes	
12822	ACTIVE	P	P021-00-1/202	Passage - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20674	ACTIVE	P	P021-00-1/202	Passage - Station Building - Arnos Grove Stn	Lead/Leading	Lead Paint/Lead	Known				Gates - 3m² Blue Gloss. Thickness : 0.41mm Analysis : 1.5%				N	N
20673	ACTIVE	P	P021-00-1/202/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Arnos Grove Stn	Void	Asbestos	No Access: Presumed				Black boarding - Wood - Ceiling No Access				Yes	
12823	ACTIVE	P	P021-00-1/236	Lobby - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20675	ACTIVE	P	P021-00-1/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Arnos Grove Stn		Asbestos	Surveyed – Not Detected				Supalux					
20678	INACTIVE	P	P021-00-1/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Arnos Grove Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
20676	ACTIVE	P	P021-00-1/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Arnos Grove Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux				Yes	
20679	INACTIVE	P	P021-00-1/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Arnos Grove Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				Yes	
20677	ACTIVE	P	P021-00-1/236/WAL-002 80860392	Wall: Internal - 2 - Lobby - Station Building - Arnos Grove Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				1 x 60amp Isolator Switch (Blue) - Asbestos Components within - SP		1		N	N
12824	ACTIVE	P	P021-00-1/237	Lobby - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12825	ACTIVE	P	P021-00-1/238	Lobby - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23894	ACTIVE	P	P021-00-1/238	Lobby - Station Building - Arnos Grove Stn	Lead/Leading	Lead Paint/Lead	Known				5m² Light green gloss. Thickness : 0.79mm Analysis : 8.0% Over Painted in Cream Lower layers lead					N



Hazardous Material Asset Register - Summary



P021-00 - Station Building - Arnos Grove Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12826	ACTIVE	P	P021-00-1/239	Toilet: Female - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20680	ACTIVE	P	P021-00-1/239/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Arnos Grove Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
12827	ACTIVE	P	P021-00-1/281	Station Supervisor Office - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23967	ACTIVE	P	P021-00-1/281	Station Supervisor Office - Station Building - Arnos Grove Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				2 x Heaters - Foam Insulation		2			
20681	ACTIVE	P	P021-00-1/281	Station Supervisor Office - Station Building - Arnos Grove Stn	Cement Cowlings/ Flues	Asbestos	Strongly Presumed				Cement flue through the window on the roof. Re-Inspection confirms on roof of Office 1/281		1		N	N
12828	ACTIVE	P	P021-00-1/291	Office - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12829	ACTIVE	P	P021-00-1/301	Office - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20682	ACTIVE	P	P021-00-1/301/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Arnos Grove Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
20683	ACTIVE	P	P021-00-1/301/CLG-02	Ceiling: Solid - 2 - Office - Station Building - Arnos Grove Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
12830	ACTIVE	P	P021-00-1/331	Mess Room - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20684	ACTIVE	P	P021-00-1/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Arnos Grove Stn		Asbestos	Surveyed – Not Detected				Supalux					
20685	ACTIVE	P	P021-00-1/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Arnos Grove Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Suplalux				Yes	
23968	ACTIVE	P	P021-00-1/331/FLR-01	Floor - 1 - Mess Room - Station Building - Arnos Grove Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				2x Heaters - Foam Insulation		2			
12831	ACTIVE	P	P021-00-1/332	Mess Room - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12832	ACTIVE	P	P021-00-1/401	Store - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P021-00 - Station Building - Arnos Grove Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20687	ACTIVE	P	P021-00-1/401/DOR-01	Door - 1 - Store - Station Building - Arnos Grove Stn	Lead/Leading	Lead Paint/Lead	Known				Door - 2m² Blue gloss. Thickness : 0.34mm Analysis : 7.4%				N	N
20686	ACTIVE	P	P021-00-1/401/WAL-001	Wall: Internal - 1 - Store - Station Building - Arnos Grove Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding					
12833	ACTIVE	P	P021-00-1/416	Toilet: Male - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20688	ACTIVE	P	P021-00-1/416	Toilet: Male - Station Building - Arnos Grove Stn	Lead/Leading	Lead Paint/Lead	Known				7m² Light green gloss - thickness : 0.79mm Analysis : 8.0% Upon re inspection 30/09/2014 new painted was noted Upon Re-Inspection 20/04/2016 Over Painted in Cream				N	N
23969	ACTIVE	P	P021-00-1/416/WAL-002	Wall: Internal - 2 - Toilet - Station Building - Arnos Grove Stn		Asbestos	Surveyed – Not Detected				Boarding by heater - Supalux					
12834	ACTIVE	P	P021-00-1/417	Toilet: Female - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20689	ACTIVE	P	P021-00-1/417	Toilet: Female - Station Building - Arnos Grove Stn	No Access	Asbestos	Surveyed – Not Detected				NAD during 2024 re-inspection					
12835	ACTIVE	P	P021-00-1/451	Tenancy - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20690	ACTIVE	P	P021-00-1/451	Tenancy - Station Building - Arnos Grove Stn	Void	Asbestos	No Access: Presumed				Behind wooden board					
20692	ACTIVE	P	P021-00-1/451/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Arnos Grove Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux				Yes	
20691	ACTIVE	P	P021-00-1/451/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Arnos Grove Stn		Asbestos	Surveyed – Not Detected				Supalux					
12836	ACTIVE	P	P021-00-1/452	Office - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23970	ACTIVE	P	P021-00-1/452	Office - Station Building - Arnos Grove Stn	No Access	Asbestos	Surveyed – Not Detected				NAD at time of 2024 re-inspection					
12837	ACTIVE	P	P021-00-1/453	Tenancy - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20588	ACTIVE	P	P021-00-1/453/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Arnos Grove Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard				Yes	



Hazardous Material Asset Register - Summary



P021-00 - Station Building - Arnos Grove Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20587	ACTIVE	P	P021-00-1/453/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Arnos Grove Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
20589	ACTIVE	P	P021-00-1/453/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Arnos Grove Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
24040	ACTIVE	P	P021-00-1/453/FLR-01	Floor - 1 - Tenancy - Station Building - Arnos Grove Stn	Void	Asbestos	No Access: Presumed				Beneath Parquet					YES
12838	ACTIVE	P	P021-00-1/454	Tenancy - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20693	ACTIVE	P	P021-00-1/454	Tenancy - Station Building - Arnos Grove Stn	No Access	Asbestos	Surveyed – Not Detected				Surveyed by Frankham's for Group Properties - No Asbestos Detected					
12839	ACTIVE	P	P021-00-1/576	Stairs: Linear - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20590	ACTIVE	P	P021-00-1/576	Stairs: Linear - Station Building - Arnos Grove Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
12840	ACTIVE	P	P021-00-1/577	Stairs: Linear - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20591	ACTIVE	P	P021-00-1/577	Stairs: Linear - Station Building - Arnos Grove Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
12841	ACTIVE	P	P021-00-1/578	Stairs: Linear - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20592	ACTIVE	P	P021-00-1/578	Stairs: Linear - Station Building - Arnos Grove Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
12842	ACTIVE	P	P021-00-1/601	Stairs: Linear - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12843	ACTIVE	P	P021-00-1/602	Stairs: Linear - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12844	ACTIVE	P	P021-00-1/603	Stairs: Linear - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12845	ACTIVE	P	P021-00-1/604	Stairs: Linear - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12846	ACTIVE	P	P021-00-1/605	Stairs: Linear - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P021-00 - Station Building - Arnos Grove Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46497	ACTIVE	P	P021-00-1/605	Stairs: Linear - Station Building - Arnos Grove Stn	Void	Asbestos	Sampled – Not Detected				Cable Croft to underside of stairs 1/605 on Embankment and associated cable chamber					
20594	ACTIVE	P	P021-00-1/636	Overbridge - Station Building - Arnos Grove Stn	Lead/Leading	Lead Paint/Lead	Removed				Overbridge - First aid stretcher - 1.5m² Blue gloss - thickness : 0.40mm Analysis : 16.0%					
20593	ACTIVE	P	P021-00-1/636	Overbridge - Station Building - Arnos Grove Stn	Lead/Leading	Lead Paint/Lead	Known				Overbridge - Information sign - 1m² Blue gloss - thickness : 0.40mm Analysis : 16.0%		1		N	N
20595	ACTIVE	P	P021-00-1/636	Overbridge - Station Building - Arnos Grove Stn	Lead/Leading	Lead Paint/Lead	Known				Overbridge - Jump Leads box - 2m² Blue gloss - thickness : 0.40mm Analysis : 16.0%		1		N	N
20596	ACTIVE	P	P021-00-1/637	Overbridge - Station Building - Arnos Grove Stn	No Access	Asbestos	Surveyed – Not Detected				New					
12847	ACTIVE	P	P021-00-1/661	Switch Room - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20602	ACTIVE	P	P021-00-1/661	Switch Room - Station Building - Arnos Grove Stn	Lead/Leading	Lead Paint/Lead	Known				Wall - 15m² Light green gloss - thickness : 0.58mm Analysis : 7.5% Upon re inspection 30/11/14 it was noted that it has been re painted Upon re-inspection 20/04/2016 over painted in White				N	N
20597	ACTIVE	P	P021-00-1/661/ FLR-01	Floor - 1 - Switch Room - Station Building - Arnos Grove Stn	Void	Asbestos	Surveyed – Not Detected				Concrete - 1x Cable sleeve beneath fuse switch					YES
25813	ACTIVE	P	P021-00-1/661/ WAL-002 80860637	Wall: Internal - 2 - Switch Room - Station Building - Arnos Grove Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Isolator Switches - Insulation within - 2x 60, 1 x 100amp, 1 x 200amp Bus Bar W6, Bus Bar, W3 - Asbestos Components within - SP		4		N	N
20598	ACTIVE	P	P021-00-1/661/ WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Arnos Grove Stn		Asbestos	Surveyed – Not Detected				White boarding - Supalux Cream boarding - Supalux					
25811	ACTIVE	P	P021-00-1/661/ WAL-005 80860640	Wall: Internal - 5 - Switch Room - Station Building - Arnos Grove Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Isolator Switches - Insulation within 1 x 60amp - Asbestos components within - SP		1		N	N
25812	INACTIVE	P	P021-00-1/661/ WAL-005	Wall: Internal - 5 - Switch Room - Station Building - Arnos Grove Stn	Isolator Switches	Asbestos	Strongly Presumed				Isolator Switches - Insulation within 1 x 60amp		1			
20599	ACTIVE	P	P021-00-1/661/ WAL-006 80860641	Wall: Internal - 6 - Switch Room - Station Building - Arnos Grove Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Isolator Switches - Insulation within - 4 x 60 amps, 1 x 200 amps - Asbestos Components within - SP		5		N	N
25815	ACTIVE	P	P021-00-1/661/ WAL-008 80860643	Wall: Internal - 8 - Switch Room - Station Building - Arnos Grove Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Isolator Switches - Insulation within 1 x 100 amp - Asbestos Components within - SP		1		N	N
20600	ACTIVE	P	P021-00-1/661/ WAL-009 80860644	Wall: Internal - 9 - Switch Room - Station Building - Arnos Grove Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				3x Transformer Boxes - Insulation within - Asbestos Components within - P		3		N	N



Hazardous Material Asset Register - Summary



P021-00 - Station Building - Arnos Grove Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25814	ACTIVE	P	P021-00-1/661/WAL-009 80860644	Wall: Internal - 9 - Switch Room - Station Building - Arnos Grove Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Isolator Switches - Insulation within 1 x 30amp - Asbestos Components within - SP		1		N	N
20601	ACTIVE	P	P021-00-1/661/WAL-010 80860645	Wall: Internal - 10 - Switch Room - Station Building - Arnos Grove Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Boxes - Insulation within - Asbestos Components within - P		1		N	N
23891	ACTIVE	P	P021-00-1/661/WAL-011 80860646	Wall: Internal - 11 - Switch Room - Station Building - Arnos Grove Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Boxes - Insulation within - Asbestos Components within - P		1		N	N
12848	ACTIVE	P	P021-00-1/746	SCR - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12849	ACTIVE	P	P021-00-2/261	Platform 1 - Eastbound Local - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23958	ACTIVE	P	P021-00-2/261	Platform 1 - Eastbound Local - Station Building - Arnos Grove Stn	Westing house Boxes	Asbestos	Strongly Presumed				Navy blue Westinghouse Boxes between Platforms 1 & 2 - Asbestos Components Within - SP		1		N	N
20605	ACTIVE	P	P021-00-2/261	Platform 1 - Eastbound Local - Station Building - Arnos Grove Stn	Cable: Sheath	Asbestos	Strongly Presumed				Potential asbestos cable within cable run - Trackside		1		N	N
20604	ACTIVE	P	P021-00-2/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Arnos Grove Stn	Glazing Rope	Asbestos	Removed				Glazing bars on ceiling - removed and replaced with non-asbestos material, see ID report R611951			R611951		N
20603	ACTIVE	P	P021-00-2/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Arnos Grove Stn	Void	Asbestos	No Access: Presumed				Beneath Inspection Covers					YES
12850	ACTIVE	P	P021-00-2/262	Platform 2 - Single Line Local - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23959	INACTIVE	P	P021-00-2/262	Platform 2 - Single Line Local - Station Building - Arnos Grove Stn	Westing house Boxes	Asbestos	Strongly Presumed				Black Westinghouse Boxes between Platforms 1 & 2					
20607	ACTIVE	P	P021-00-2/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - Arnos Grove Stn	Glazing Rope	Asbestos	Removed				Glazing bars on ceiling - removed and replaced with non-asbestos material, see ID report R611951			R611951		N
20606	ACTIVE	P	P021-00-2/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Arnos Grove Stn	Void	Asbestos	No Access: Presumed				Beneath Inspection Covers					YES
12851	ACTIVE	P	P021-00-2/263	Platform 3 - Single Line Local - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20609	INACTIVE	P	P021-00-2/263/CLG-01	Ceiling: Solid - 1 - Platform 3 - Station Building - Arnos Grove Stn	Glazing Rope	Asbestos	Removed				Glazing bars on ceiling - removed and replaced with non-asbestos material, see ID report R611951			R611951	N	N



Hazardous Material Asset Register - Summary



P021-00 - Station Building - Arnos Grove Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20608	ACTIVE	P	P021-00-2/263/FLR-01	Floor - 1 - Platform 3 - Station Building - Arnos Grove Stn	Void	Asbestos	Surveyed – Not Detected				Beneath Inspection Covers					YES
12852	ACTIVE	P	P021-00-2/264	Platform 4 - Westbound Local - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20612	ACTIVE	P	P021-00-2/264	Platform 4 - Westbound Local - Station Building - Arnos Grove Stn	Westing house Boxes	Asbestos	Strongly Presumed				4x Westinghouse Boxes - Trackside - Asbestos Components Within - SP		5		N	N
23960	ACTIVE	P	P021-00-2/264	Platform 4 - Westbound Local - Station Building - Arnos Grove Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables on cable run - Trackside				N	N
20611	ACTIVE	P	P021-00-2/264/CLG-01	Ceiling: Solid - 1 - Platform 4 - Station Building - Arnos Grove Stn	Glazing Rope	Asbestos	Removed				Glazing bars on ceiling - removed and replaced with non-asbestos material, see ID report R611951			R611951	N	N
20610	ACTIVE	P	P021-00-2/264/FLR-01	Floor - 1 - Platform 4 - Station Building - Arnos Grove Stn	Void	Asbestos	No Access: Presumed				Beneath Inspection Covers					YES
12853	ACTIVE	P	P021-00-2/331	Tea Point - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20614	ACTIVE	P	P021-00-2/331/CLG-01 80860731	Ceiling: Solid - 1 - Mess Room - Station Building - Arnos Grove Stn Ceiling: Solid	Void	Asbestos	Surveyed – Not Detected				NAD at time of 2024 re-inspection				Yes	
20613	ACTIVE	P	P021-00-2/331/FLR-01	Floor - 1 - Mess Room - Station Building - Arnos Grove Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
12854	ACTIVE	P	P021-00-2/411	Store - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12855	ACTIVE	P	P021-00-2/412	Store - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12856	ACTIVE	P	P021-00-2/436	Waiting Room - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12857	ACTIVE	P	P021-00-2/437	Waiting Room - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12858	ACTIVE	P	P021-00-2/661	Switch Room - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43911	INACTIVE	P	P021-00-2/661	Switch Room - Station Building - Arnos Grove Stn		Asbestos	Known				Flash Guards, 4no to fuse switch boses			R510626	N	N
43912	ACTIVE	P	P021-00-2/661	Switch Room - Station Building - Arnos Grove Stn		Asbestos	Sampled – Not Detected				Plastic arc chutes, 3 no, to fuse switch boxes			R510626	N	N



Hazardous Material Asset Register - Summary



P021-00 - Station Building - Arnos Grove Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20617	ACTIVE	P	P021-00-2/661/WAL-001 80860766	Wall: Internal - 1 - Switch Room - Station Building - Arnos Grove Stn Wall: Internal	Other Boarding	Asbestos	Removed				Paxoline Board - Removed		1		N	N
20616	ACTIVE	P	P021-00-2/661/WAL-002 80860767	Wall: Internal - 2 - Switch Room - Station Building - Arnos Grove Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box - Insulation within - Asbestos Components within - P		1		N	N
42537	ACTIVE	P	P021-00-2/661/WAL-002 80860767	Wall: Internal - 2 - Switch Room - Station Building - Arnos Grove Stn Wall: Internal	Other Boarding	Asbestos	Presumed				Presumed asbestos within siluminate panels 2m2 to busbar - Asbestos Components Within - P		1	R510626	N	N
20615	ACTIVE	P	P021-00-2/661/WAL-002 80860767	Wall: Internal - 2 - Switch Room - Station Building - Arnos Grove Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Iron Clad Isolators - 4 x 60, 1 x 200 1 x 300amp - Asbestos Components within - SP		6		N	N
25816	ACTIVE	P	P021-00-2/661/WAL-003 80860768	Wall: Internal - 3 - Switch Room - Station Building - Arnos Grove Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Iron Clad Isolators - 2 x 60, 1 x 100amps - Asbestos Components within - SP		3		N	N
44065	ACTIVE	P	P021-00-2/661/WAL-003 80860768	Wall: Internal - 3 - Switch Room - Station Building - Arnos Grove Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				Bus bar to wall 3 with trunking - Asbestos Components Within - P		1		N	N
12859	ACTIVE	P	P021-00-2/731	CER - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12860	ACTIVE	P	P021-00-2/761	Equipment Room - Station Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

P023-00 - Station Building - Bounds Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12896	ACTIVE	P	P023-00-1/001	Booking Hall - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45181	ACTIVE	P	P023-00-1/001	Booking Hall - Station Building - Bounds Green Stn	Glazing Rope	Asbestos	Strongly Presumed				Outside front station - Rope seal behind metal glazing bars on canopy Not Observed on this Visit				N	N
20618	ACTIVE	P	P023-00-1/001	Booking Hall - Station Building - Bounds Green Stn	Lead/Leading	Lead Paint/Lead	Known				Around door to tenancy - Red Matt - thickness : 0.03mm Analysis : 1.9% HMU Re-inspection ok 10-03-2015				N	N
12897	ACTIVE	P	P023-00-1/011	Ticket Office - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24039	ACTIVE	P	P023-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Bounds Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete walls, breeze block, ventilation equipment above false ceiling				Yes	



Hazardous Material Asset Register - Summary



P023-00 - Station Building - Bounds Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20620	ACTIVE	P	P023-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Supalux					
20622	ACTIVE	P	P023-00-1/011/CLG-02	Ceiling: Suspended - 2 - Ticket Office - Station Building - Bounds Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete walls, breeze block, ventilation equipment above false ceiling				Yes	
20621	ACTIVE	P	P023-00-1/011/CLG-02	Ceiling: Suspended - 2 - Ticket Office - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Supalux					
20619	ACTIVE	P	P023-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Bounds Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath Computer Tiles					Yes
12898	ACTIVE	P	P023-00-1/021	POM - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20623	ACTIVE	P	P023-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Bounds Green Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Tiles					Yes
12899	ACTIVE	P	P023-00-1/031	Mess Room - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20625	ACTIVE	P	P023-00-1/031/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Bounds Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
20624	ACTIVE	P	P023-00-1/031/WAL-003	Wall: Internal - 3 - Mess Room - Station Building - Bounds Green Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LTB heater x 2 - foam panels		2			
12900	ACTIVE	P	P023-00-1/053	Mess Room - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20627	ACTIVE	P	P023-00-1/053	Mess Room - Station Building - Bounds Green Stn	Other Boarding	Asbestos	Not Found during Inspection				Yard (outside 1/053) - 20m2 Shed Panels HMU Re-inspection still the same				N	N
20629	ACTIVE	P	P023-00-1/053	Mess Room - Station Building - Bounds Green Stn	Cement Cowlings/ Flues	Asbestos	Not Found during Inspection				Yard (outside 1/053) - Pipe in metal cladding HMU Re-Inspection still the same				N	N
20628	ACTIVE	P	P023-00-1/053	Mess Room - Station Building - Bounds Green Stn	Other Boarding	Asbestos	Not Found during Inspection				Yard (outside 1/053) - 8m2 Water Tank boxing on roof HMU Re-Inspection not found still the same				N	N
20626	ACTIVE	P	P023-00-1/053/WAL-003	Wall: Internal - 3 - Mess Room - Station Building - Bounds Green Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - Foam insulation		1			
12901	ACTIVE	P	P023-00-1/071	Circulation Area - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20630	ACTIVE	P	P023-00-1/071/FLR-01	Floor - 1 - Circulation Area - Station Building - Bounds Green Stn	Void	Asbestos	No Access: Presumed				Beneath Hatches					Yes



Hazardous Material Asset Register - Summary



P023-00 - Station Building - Bounds Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12902	ACTIVE	P	P023-00-1/081	Lobby - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12903	ACTIVE	P	P023-00-1/151	UMC - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20632	ACTIVE	P	P023-00-1/151	UMC - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Entrance above door - Supalux					
45182	ACTIVE	P	P023-00-1/151	UMC - Station Building - Bounds Green Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				2x Controllers		2		N	N
46365	ACTIVE	P	P023-00-1/151	UMC - Station Building - Bounds Green Stn	Other Electrical Boxes	Asbestos	Presumed				BD1E3 box - emergency battery to wall		1	R689076	N	N
46364	ACTIVE	P	P023-00-1/151	UMC - Station Building - Bounds Green Stn	Gasket :Pipework	Asbestos	Sampled – Not Detected				Gasket to motor joints - Throughout (Sampled twice)			R689076	N	N
46362	ACTIVE	P	P023-00-1/151	UMC - Station Building - Bounds Green Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel panel to storage bunker	2		R689076	N	N
46369	ACTIVE	P	P023-00-1/151	UMC - Station Building - Bounds Green Stn	Other Electrical Boxes	Asbestos	Presumed				BD1E4 box - battery box to wall		1	R689076	N	N
46368	ACTIVE	P	P023-00-1/151	UMC - Station Building - Bounds Green Stn	Other Electrical Boxes	Asbestos	Presumed				12 way to wall		1	R689076	N	N
43716	ACTIVE	P	P023-00-1/151	UMC - Station Building - Bounds Green Stn		Asbestos	Sampled – Not Detected				Gasket 6" x 6" adjacent to RHS wall in UMC			R591226	N	N
46367	ACTIVE	P	P023-00-1/151	UMC - Station Building - Bounds Green Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer and fan boxes to wall		5	R689076	N	N
46366	ACTIVE	P	P023-00-1/151	UMC - Station Building - Bounds Green Stn	Other Electrical Boxes	Asbestos	Presumed				6 way fuse board box to wall		1	R689076	N	N
23963	ACTIVE	P	P023-00-1/151	UMC - Station Building - Bounds Green Stn	Other Electrical Boxes	Asbestos	Removed				Main Area - Fan Controllers				N	N
20631	ACTIVE	P	P023-00-1/151	UMC - Station Building - Bounds Green Stn	Gasket :Pipework	Asbestos	Known				Fire Hydrant Gasket to LHS of Valve (Chrysotile)				N	N
43717	ACTIVE	P	P023-00-1/151	UMC - Station Building - Bounds Green Stn		Asbestos	Sampled – Not Detected				Gasket 6" X 6" on main gate valve			R591226	N	N
43718	ACTIVE	P	P023-00-1/151	UMC - Station Building - Bounds Green Stn	Gasket :Pipework	Asbestos	Known				Gasket 6" x 6" LHS old wheel to gate valve		6	R591226	N	N
46363	ACTIVE	P	P023-00-1/151	UMC - Station Building - Bounds Green Stn	Gasket :Pipework	Asbestos	Sampled – Not Detected				Fire hydrant pipework/gaskets to joints			R689076	N	N
20639	ACTIVE	P	P023-00-1/151	UMC - Station Building - Bounds Green Stn	Lead/Leading	Lead Paint/Lead	Known				Girders - Blue, Green Matt - 6x4m ² - Thickness : 0.42mm Analysis : 21.0% HMPS inspection top over painted green bottom over painted in yellow				N	N



Hazardous Material Asset Register - Summary



P023-00 - Station Building - Bounds Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20638	ACTIVE	P	P023-00-1/151	UMC - Station Building - Bounds Green Stn	Lead/Leading	Lead Paint/Lead	Known				Sprinkler system - Red Matt - Thickness : 0.03m Analysis : 1.9%				N	N
20636	ACTIVE	P	P023-00-1/151/WAL-001	Wall: Internal - 1 - UMC - Station Building - Bounds Green Stn	Rope Gaskets	Asbestos	Strongly Presumed				Main Area - Ventilation system (gaskets)				N	N
20637	ACTIVE	P	P023-00-1/151/WAL-002	Wall: Internal - 2 - UMC - Station Building - Bounds Green Stn	Gasket :Pipework	Asbestos	Strongly Presumed				Main Area - Pump Gaskets				N	N
20633	ACTIVE	P	P023-00-1/151/WAL-003	Wall: Internal - 3 - UMC - Station Building - Bounds Green Stn	Isolator Switches	Asbestos	Removed				Entrance Area - Combination fuse box		1		N	N
20634	ACTIVE	P	P023-00-1/151/WAL-004	Wall: Internal - 4 - UMC - Station Building - Bounds Green Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Main Area - 1x Trunking No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
23962	ACTIVE	P	P023-00-1/151/WAL-004	Wall: Internal - 4 - UMC - Station Building - Bounds Green Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Main Area - 2 x Fan switches HMU Re-Inspection ok - 10-03-2015 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2		N	N
20635	ACTIVE	P	P023-00-1/151/WAL-004 80863155	Wall: Internal - 4 - UMC - Station Building - Bounds Green Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Main Area - 1x Switches HMPS reinspection 1 box removed No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
46370	ACTIVE	P	P023-00-1/171/WLS	Walls: Internal - Escalator Incline - Station Building - Bounds Green Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel caulking to low level of LHS wall			R689076	N	N
46371	ACTIVE	P	P023-00-1/171/WLS	Walls: Internal - Escalator Incline - Station Building - Bounds Green Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel caulking to low level of RHS wall			R689076	N	N
12904	ACTIVE	P	P023-00-1/236	Lobby - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20640	ACTIVE	P	P023-00-1/236/WAL-001	Wall: Internal - 1 - Lobby - Station Building - Bounds Green Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard Boxing					
12905	ACTIVE	P	P023-00-1/237	Lobby - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20641	ACTIVE	P	P023-00-1/237	Lobby - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Supalux boarding above door					



Hazardous Material Asset Register - Summary



P023-00 - Station Building - Bounds Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12906	ACTIVE	P	P023-00-1/238	Lobby - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20750	ACTIVE	P	P023-00-1/238/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
20751	ACTIVE	P	P023-00-1/238/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Bounds Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete. Air con - Breeze Block PVC Cables above false ceiling				Yes	
20753	ACTIVE	P	P023-00-1/238/CLG-02	Ceiling: Suspended - 2 - Lobby - Station Building - Bounds Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete. Air con - Breeze Block PVC Cables above false ceiling				Yes	
20752	ACTIVE	P	P023-00-1/238/CLG-02	Ceiling: Suspended - 2 - Lobby - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
20748	ACTIVE	P	P023-00-1/238/FLR-01	Floor - 1 - Lobby - Station Building - Bounds Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, PVC Cables and Cable Trunking beneath Computer Tiles					Yes
20749	ACTIVE	P	P023-00-1/238/WAL-001	Wall: Internal - 1 - Lobby - Station Building - Bounds Green Stn	Other Electrical Boxes	Asbestos	Surveyed – Not Detected				Electrical equipment					
12907	ACTIVE	P	P023-00-1/281	Station Supervisors Office - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20754	ACTIVE	P	P023-00-1/281/FLR-01	Floor - 1 - Office - Station Building - Bounds Green Stn	Void	Asbestos	No Access: Presumed				Beneath Rubber Tiles					Yes
20756	ACTIVE	P	P023-00-1/281/WAL-003	Wall: Internal - 3 - Office - Station Building - Bounds Green Stn	Void	Asbestos	No Access: Presumed				Behind Supalux Boxing					
20755	ACTIVE	P	P023-00-1/281/WAL-003	Wall: Internal - 3 - Office - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Supalux Boxing					
20757	ACTIVE	P	P023-00-1/281/WAL-004	Wall: Internal - 4 - Office - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Supalux Boxing					
20758	ACTIVE	P	P023-00-1/281/WAL-004	Wall: Internal - 4 - Office - Station Building - Bounds Green Stn	Void	Asbestos	No Access: Presumed				Behind Supalux Boxing					
20760	ACTIVE	P	P023-00-1/281/WAL-005	Wall: Internal - 5 - Office - Station Building - Bounds Green Stn	Void	Asbestos	No Access: Presumed				Behind Supalux Boxing					
20759	ACTIVE	P	P023-00-1/281/WAL-005	Wall: Internal - 5 - Office - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Supalux Boxing					



Hazardous Material Asset Register - Summary



P023-00 - Station Building - Bounds Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12908	ACTIVE	P	P023-00-1/396	SVC - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20763	ACTIVE	P	P023-00-1/396	SVC - Station Building - Bounds Green Stn	Gasket :Pipework	Asbestos	Known				Gaskets on Pumps- Chrysotile HMU Re-Inspection Looks like all New Pipes - 10-03-2015				N	N
20761	ACTIVE	P	P023-00-1/396/CLG-01	Ceiling: Solid - 1 - SVC - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding					
20762	ACTIVE	P	P023-00-1/396/CLG-01	Ceiling: Solid - 1 - SVC - Station Building - Bounds Green Stn	Void	Asbestos	No Access: Presumed				Above Supalux Boarding				Yes	
12909	ACTIVE	P	P023-00-1/401	Lobby - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12910	ACTIVE	P	P023-00-1/406	Store - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12911	ACTIVE	P	P023-00-1/416	Lobby - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20764	ACTIVE	P	P023-00-1/416/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Supalux					
23977	ACTIVE	P	P023-00-1/416/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Bounds Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux				Yes	
12912	ACTIVE	P	P023-00-1/417	Toilet: Male - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20765	ACTIVE	P	P023-00-1/417/WAL-001	Wall: Internal - 1 - Toilet - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding behind Heater					
20766	ACTIVE	P	P023-00-1/417/WAL-002	Wall: Internal - 2 - Toilet - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Supalux Boxing					
12913	ACTIVE	P	P023-00-1/418	Toilet: Female - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20768	ACTIVE	P	P023-00-1/418/WAL-001	Wall: Internal - 1 - Toilet - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Supalux Boxing					
20767	ACTIVE	P	P023-00-1/418/WAL-001	Wall: Internal - 1 - Toilet - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding behind Heater					



Hazardous Material Asset Register - Summary



P023-00 - Station Building - Bounds Green Stn																
Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23978	ACTIVE	P	P023-00-1/418/WAL-002	Wall: Internal - 2 - Toilet - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Supalux Boxing					
12914	ACTIVE	P	P023-00-1/419	Toilet: Unisex - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20771	ACTIVE	P	P023-00-1/419	Toilet: Unisex - Station Building - Bounds Green Stn	Lead/Leading	Lead Paint/Lead	Known				On metal window frame & metal bars - white gloss - 3m ² - Thickness : 0.18mm Analysis : 4.5% HMU Re-Inspection ok - 10-03-2015				N	N
20769	ACTIVE	P	P023-00-1/419/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Supalux					
20770	ACTIVE	P	P023-00-1/419/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Bounds Green Stn	Void	Asbestos	Surveyed – Not Detected				Solid above Supalux				Yes	
12915	ACTIVE	P	P023-00-1/451	Tenancy - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23979	ACTIVE	P	P023-00-1/451	Tenancy - Station Building - Bounds Green Stn	Lead/Leading	Lead Paint/Lead	Known				Sprinkler system - red matt - 5m ² - Thickness : 0.03mm Analysis : 1.9% HMU Re-Inspection ok - 10-03-2015. New false ceiling covering most of pipe work				N	N
20772	ACTIVE	P	P023-00-1/451/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Bounds Green Stn	Void	Asbestos	Surveyed – Not Detected				Solid. Metal Sprinkler system above Metal false ceiling				Yes	
23897	ACTIVE	P	P023-00-1/451/FLR-01	Floor - 1 - Tenancy - Station Building - Bounds Green Stn	Void	Asbestos	No Access: Presumed				Beneath Wood Flooring					Yes
12916	ACTIVE	P	P023-00-1/452	Tenancy - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20773	ACTIVE	P	P023-00-1/452	Tenancy - Station Building - Bounds Green Stn	Lead/Leading	Lead Paint/Lead	Known				Sprinkler system - White matt - 5m ² - Thickness : 0.03mm Analysis : 1.9% HMU Re-Inspection Over Painted White - 10-03-2015				N	N
12917	ACTIVE	P	P023-00-1/664	Switch Room - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20774	ACTIVE	P	P023-00-1/664/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Bounds Green Stn	Isolator Switches	Asbestos	Strongly Presumed				7x Fuse switches 1 x 30 amp, 3 x 60 amp, 1 x 100 amp, 1 x 200 amp, 1 x 300amps. HMU Re-inspection All on W1 - one of Wall is Red Spot - 1 Transformer W1 10-03-2015 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		7		N	N



Hazardous Material Asset Register - Summary



P023-00 - Station Building - Bounds Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12918	ACTIVE	P	P023-00-1/665	Switch Room - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20828	ACTIVE	P	P023-00-1/665	Switch Room - Station Building - Bounds Green Stn	Isolator Switches	Asbestos	Strongly Presumed				6 switch boxes 1x 200 amp , 3x100, 3x60 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		7		N	N
20827	ACTIVE	P	P023-00-1/665	Switch Room - Station Building - Bounds Green Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Transformer Box x3 , 1 switch box 30 amp wall 3 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		4			
44515	ACTIVE	P	P023-00-1/665/ WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Bounds Green Stn	Other Electrical Boxes	Asbestos	Presumed				1 x transformer box wall. 6 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within				N	N
12919	ACTIVE	P	P023-00-1/666	Switch Cupboard - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20831	ACTIVE	P	P023-00-1/666	Switch Cupboard - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Supalux above door from outside					
20829	ACTIVE	P	P023-00-1/666/ CLG-01	Ceiling: Solid - 1 - Switch Cupboard - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Supalux					
20830	ACTIVE	P	P023-00-1/666/ CLG-01	Ceiling: Solid - 1 - Switch Cupboard - Station Building - Bounds Green Stn	Void	Asbestos	No Access: Presumed				Above Supalux				Yes	
12920	ACTIVE	P	P023-00-1/731	SCR - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20832	ACTIVE	P	P023-00-1/791	Vent Shaft - Station Building - Bounds Green Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access - Leads to lower shaft 1/792					
20833	ACTIVE	P	P023-00-1/792/ CLG-01	Ceiling: Solid - 1 - Vent Shaft - Station Building - Bounds Green Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Rings - Non Asbestos Caulking					
20834	ACTIVE	P	P023-00-1/901	Vent Shaft - Station Building - Bounds Green Stn	Lead/Leading	Lead Paint/Lead	Known				Door to escalators - black gloss - 7m ² - Thickness : 0.49mm Analysis : 9.8% HMPS re-inspection over painted with blue				N	N
12921	ACTIVE	P	P023-00-2/081	Circulation Area - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P023-00 - Station Building - Bounds Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20835	ACTIVE	P	P023-00-2/081/FLR-01	Floor - 1 - Circulation Area - Station Building - Bounds Green Stn	Void	Asbestos	No Access: Presumed				No access to manhole in floor					Yes
12922	ACTIVE	P	P023-00-2/161	LMC - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46360	ACTIVE	P	P023-00-2/161	LMC - Station Building - Bounds Green Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel caulking to low level of RHS wall			R689076	N	N
46359	ACTIVE	P	P023-00-2/161	LMC - Station Building - Bounds Green Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel caulking to low level of LHS wall			R689076	N	N
46361	ACTIVE	P	P023-00-2/161	LMC - Station Building - Bounds Green Stn	Other Electrical Boxes	Asbestos	Presumed				Pump control panel (pump gear) and earth terminal box		1	R689076	N	N
23899	ACTIVE	P	P023-00-2/161	LMC - Station Building - Bounds Green Stn	Lead/Leading	Lead Paint/Lead	Known				Girders - Blue / Green Matt - 14m ² - Thickness : 0.42mm Analysis : 21.0% HMU R-e-Inspection No Access - 10-03-2015				N	N
20838	ACTIVE	P	P023-00-2/161/CLG-01	Ceiling: Solid - 1 - LMC - Station Building - Bounds Green Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
20836	ACTIVE	P	P023-00-2/161/WAL-001	Wall: Internal - 1 - LMC - Station Building - Bounds Green Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel ring, caulking					
20839	ACTIVE	P	P023-00-2/161/WAL-001 80863202	Wall: Internal - 1 - LMC - Station Building - Bounds Green Stn Wall: Internal	Cable Duct: Other	Asbestos	Strongly Presumed				4x Cable sleeves - filled in on right wall , 2 x on left wall Cable sleeves not visible behind cement layer covering. therefore not scored during 2020 re-inspection.		4		N	N
20837	ACTIVE	P	P023-00-2/161/WAL-002	Wall: Internal - 2 - LMC - Station Building - Bounds Green Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel ring, caulking					
20840	ACTIVE	P	P023-00-2/161/WAL-003	Wall: Internal - 3 - LMC - Station Building - Bounds Green Stn	Cable Duct: Other	Asbestos	Strongly Presumed				4x Cable sleeves - filled in Cable sleeves not visible behind cement layer covering. therefore not scored during 2020 re-inspection.		4		N	N
12923	ACTIVE	P	P023-00-2/201	Passage - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12924	ACTIVE	P	P023-00-2/202	Passage - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12925	ACTIVE	P	P023-00-2/203	Passage - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P023-00 - Station Building - Bounds Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12926	ACTIVE	P	P023-00-2/204	Passage - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12927	ACTIVE	P	P023-00-2/205	Passage - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12928	ACTIVE	P	P023-00-2/236	Passage - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20841	ACTIVE	P	P023-00-2/236/WAL-001	Wall: Internal - 1 - Passage - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding					
20842	ACTIVE	P	P023-00-2/236/WAL-003	Wall: Internal - 3 - Passage - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding					
20843	ACTIVE	P	P023-00-2/236/WAL-004	Wall: Internal - 4 - Passage - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding					
12929	ACTIVE	P	P023-00-2/261	Platform 1 - Eastbound Local - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24009	ACTIVE	P	P023-00-2/261	Platform 1 - Eastbound Local - Station Building - Bounds Green Stn	Cable: Sheath	Asbestos	Known				Tail End into Relay room 2/712 - 2x 50mm Cables - J hanger 3 - Cables drop down to go through duct 6 Inspection from platform end only during 2020 re-inspection during traffic hours.		2		N	N
46387	ACTIVE	P	P023-00-2/261	Platform 1 - Eastbound Local - Station Building - Bounds Green Stn	Cable Duct: Other	Asbestos	Sampled – Not Detected				Cable Ducts 10no Arrival and Tail End Walls			R685826		
20848	ACTIVE	P	P023-00-2/261	Platform 1 - Eastbound Local - Station Building - Bounds Green Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 invert nr 2/712 - 7x Cables nr 2/712 (1x 5cm dia, 5x 2cm dia, 1x 8cm dia)		7			
20846	ACTIVE	P	P023-00-2/261	Platform 1 - Eastbound Local - Station Building - Bounds Green Stn	Cable: Sheath	Asbestos	Known				Tail End into Relay room 2/712 - 1x 60mm Cable - j hanger 4 - cable enters duct 2 & runs into relay rm 2/712 Inspection from platform end only during 2020 re-inspection during traffic hours.		1		N	N
20845	ACTIVE	P	P023-00-2/261	Platform 1 - Eastbound Local - Station Building - Bounds Green Stn	Cable: Sheath	Asbestos	Known				Tail End into Relay room 2/712 - 2x 25mm Cables - J hanger 2 - cables drop down & enter duct 5 Inspection from platform end only during 2020 re-inspection during traffic hours.		2			
20847	ACTIVE	P	P023-00-2/261	Platform 1 - Eastbound Local - Station Building - Bounds Green Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 InvertBy Pit side by wall - 7x Cables (5x 2cm dia 2m from hatch, 1x 5cm dia, 1x 8cm dia)		7		N	N



Hazardous Material Asset Register - Summary



P023-00 - Station Building - Bounds Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23618	ACTIVE	p	P023-00-2/261	Platform 1 - Eastbound Local - Station Building - Bounds Green Stn	Cable Duct: Other	Asbestos	Known				Platform 1 Invert by Hatch - 0.5m2 Cable sleeve high level - Chrysotile		1		N	N
46469	ACTIVE	p	P023-00-2/261	Platform 1 - Eastbound Local - Station Building - Bounds Green Stn	Cable Duct: Other	Asbestos	Sampled – Not Detected				10no. Cable ducts to track wall at arrival end		10	R685826	N	N
46468	ACTIVE	p	P023-00-2/261	Platform 1 - Eastbound Local - Station Building - Bounds Green Stn	Cable Duct: Other	Asbestos	Sampled – Not Detected				10no. Cable ducts to track wall at departure end		10	R685826	N	N
44521	ACTIVE	p	P023-00-2/261	Platform 1 - Eastbound Local - Station Building - Bounds Green Stn	Lead/Leading	Lead Paint/Lead	Presumed				Grit bin presumed red and cream paint				N	N
20844	ACTIVE	p	P023-00-2/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Bounds Green Stn	Cable Duct: Other	Asbestos	Known				1x cable sleeve in floor, filled in Cable sleeve not visible beneath filling therefore not scored during 2020 reinspection.		1		N	N
12930	ACTIVE	p	P023-00-2/262	Platform 2 - Westbound Local - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46470	ACTIVE	p	P023-00-2/262	Platform 2 - Westbound Local - Station Building - Bounds Green Stn	Cable Duct: Other	Asbestos	Sampled – Not Detected				9no. Cable ducts to track wall at departure end		9	R685826	N	N
46388	ACTIVE	p	P023-00-2/262	Platform 2 - Westbound Local - Station Building - Bounds Green Stn	Cable Duct: Other	Asbestos	Sampled – Not Detected				Cable Ducts 9no Arrival and Tail End Walls			R685826		
46471	ACTIVE	p	P023-00-2/262	Platform 2 - Westbound Local - Station Building - Bounds Green Stn	Cable Duct: Other	Asbestos	Sampled – Not Detected				9no. Cable ducts to track wall at arrival end		9	R685826	N	N
20880	ACTIVE	p	P023-00-2/262	Platform 2 - Westbound Local - Station Building - Bounds Green Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - 1x 20mm dia cable Pitwall 10m No access into platform inverts during 2020 re-inspection. Confined space.		1		N	N
20849	ACTIVE	p	P023-00-2/262	Platform 2 - Westbound Local - Station Building - Bounds Green Stn	Westing house Boxes	Asbestos	Known				Platform 2 Invert - Westinghouse box		1		N	N
24010	ACTIVE	p	P023-00-2/262	Platform 2 - Westbound Local - Station Building - Bounds Green Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - 7x Green cables pitwall nr 2/762 (1x 60mm, 2x 30mm, 4x 20mm) No access into platform inverts during 2020 re-inspection. Confined space.		7		N	N
12931	ACTIVE	p	P023-00-2/381	Store - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20850	ACTIVE	p	P023-00-2/381	Store - Station Building - Bounds Green Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel Rings - Caulking sampled non-asbestos					



Hazardous Material Asset Register - Summary



P023-00 - Station Building - Bounds Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20851	ACTIVE	P	P023-00-2/381/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Bounds Green Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Rings					
12932	ACTIVE	P	P023-00-2/406	CER - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24011	ACTIVE	P	P023-00-2/406	CER - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Above Door					
20853	ACTIVE	P	P023-00-2/406	CER - Station Building - Bounds Green Stn	Lead/Leading	Lead Paint/Lead	Removed				Thickness : 0.01mm Analysis : 1.5% HMU Re-Inspection Noted has been painted				N	N
20852	ACTIVE	P	P023-00-2/406/WAL-001	Wall: Internal - 1 - CER - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding					
12933	ACTIVE	P	P023-00-2/411	Store - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44516	ACTIVE	P	P023-00-2/411	Store - Station Building - Bounds Green Stn	LUL Heaters	Asbestos	Strongly Presumed				Heater on wall 2 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within					
20856	ACTIVE	P	P023-00-2/411	Store - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Above Door					
44517	ACTIVE	P	P023-00-2/411	Store - Station Building - Bounds Green Stn	Lead/Leading	Lead Paint/Lead	Presumed				First aid stretcher box green paint wall 1				N	N
20854	ACTIVE	P	P023-00-2/411/WAL-001	Wall: Internal - 1 - Store - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding					
20855	ACTIVE	P	P023-00-2/411/WAL-002	Wall: Internal - 2 - Store - Station Building - Bounds Green Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - foam insulation		1			
12934	ACTIVE	P	P023-00-2/661	Switch Room - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20858	ACTIVE	P	P023-00-2/661	Switch Room - Station Building - Bounds Green Stn	Lead/Leading	Lead Paint/Lead	Known				Cream matt wall - 15m². Thickness : 0.32mm Analysis : 1.8% HMU Re Inspection ok - 10-03-2015				N	N
20857	ACTIVE	P	P023-00-2/661/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Bounds Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				3x Supalux boarding					
12935	ACTIVE	P	P023-00-2/663	Switch Room - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P023-00 - Station Building - Bounds Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20860	ACTIVE	P	P023-00-2/663	Switch Room - Station Building - Bounds Green Stn	Isolator Switches	Asbestos	Strongly Presumed				12x Iron clad isolators 6 x 60 amps, 4 x 100 amps, 2 x 200 amps, HMU Re-Inspection W1 4 X 60 amps 1 x 100amps W2 1 Trans Form W3 3 X 100amps 2 X 200amps 2 X 60amps - 10-03-2015 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		12		N	N
20859	ACTIVE	P	P023-00-2/663	Switch Room - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Supalux boarding above door					
24043	ACTIVE	P	P023-00-2/663/FLR-01	Floor - 1 - Switch Room - Station Building - Bounds Green Stn	Cable Duct: Other	Asbestos	Strongly Presumed				W1 2 Cable Sleeves , 1 Cable Sleeve 3 - 10-03-2015 Cable sleeves not visible beneath covering layer on top therefore not scored during 2020 re-inspection.		3		N	N
12936	ACTIVE	P	P023-00-2/664	Disused Room - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Asbestos Free									
20861	ACTIVE	P	P023-00-2/664	Disused Room - Station Building - Bounds Green Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
12937	ACTIVE	P	P023-00-2/711	Relay Room - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44526	ACTIVE	P	P023-00-2/711 80143224	Relay Room - Station Building - Bounds Green Stn Room Assets	Other Electrical Boxes	Asbestos	Presumed				Green electrical box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within				N	N
20862	ACTIVE	P	P023-00-2/711	Relay Room - Station Building - Bounds Green Stn	Cable: Sheath	Asbestos	Strongly Presumed				5x Cables (2x 40mm dia, 3x 10mm dia)		5		N	N
44527	ACTIVE	P	P023-00-2/711 80143224	Relay Room - Station Building - Bounds Green Stn Room Assets	Other Boarding	Asbestos	Presumed				Boarding inside roller shutters				N	N
44528	ACTIVE	P	P023-00-2/711 80143224	Relay Room - Station Building - Bounds Green Stn Room Assets	Other Boarding	Asbestos	Presumed				Paxoline boarding				N	N
20864	ACTIVE	P	P023-00-2/711	Relay Room - Station Building - Bounds Green Stn	Lead/Leading	Lead Paint/Lead	Known				Fuse box - green gloss - 1m ² - thickness : 0.01mm Analysis : 7.8% HMU Re Inspection Poor Condition - 10-03-2015				N	N
44529	ACTIVE	P	P023-00-2/711 80143224	Relay Room - Station Building - Bounds Green Stn Room Assets	Lead/Leading	Lead Paint/Lead	Presumed				Yellow paint to walls - poor condition				N	N
43156	INACTIVE	P	P023-00-2/711	Relay Room - Station Building - Bounds Green Stn	PCBs	Polychlorinated biphenyl	Presumed				8 X PCB's Fair Condition		8		N	N
20865	ACTIVE	P	P023-00-2/711/DOR-01	Door - 1 - Relay Room - Station Building - Bounds Green Stn	Lead/Leading	Lead Paint/Lead	Known				Door - brown gloss - 2m ² - thickness : 0.01mm Analysis : 25.0% HMU Re-Inspection Poor Condition - 10-03-2015				N	N



Hazardous Material Asset Register - Summary



P023-00 - Station Building - Bounds Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20863	ACTIVE	P	P023-00-2/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Bounds Green Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Cable sleeves - filled in HMU Re-Inspection ok - 04-08-15				N	N
12938	ACTIVE	P	P023-00-2/712	Relay Room - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20867	ACTIVE	P	P023-00-2/712	Relay Room - Station Building - Bounds Green Stn	Cable: Sheath	Asbestos	Strongly Presumed				2x 40mm dia Cables		2		N	N
44520	ACTIVE	P	P023-00-2/712 80143225	Relay Room - Station Building - Bounds Green Stn Room Assets	Cable Ducts: Cement	Asbestos	Presumed				5 ducts to floor				N	N
44519	ACTIVE	P	P023-00-2/712 80143225	Relay Room - Station Building - Bounds Green Stn Room Assets	Other Boarding	Asbestos	Presumed				Brown paxoline box					
44525	INACTIVE	P	P023-00-2/712 80143225	Relay Room - Station Building - Bounds Green Stn Room Assets	Cable Ducts: Cement	Asbestos	Presumed				Cable ducts to floor				N	N
44518	ACTIVE	P	P023-00-2/712 80143225	Relay Room - Station Building - Bounds Green Stn Room Assets	Other Electrical Boxes	Asbestos	Presumed				Green electrical box presumed No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within					
20869	ACTIVE	P	P023-00-2/712	Relay Room - Station Building - Bounds Green Stn	Lead/Leading	Lead Paint/Lead	Known				Fuse box - green gloss - 1m² - thickness : 0.01mm Analysis : 25.0% HMU Re-Inspection Poor Condition - 10-03-2015				N	N
20868	ACTIVE	P	P023-00-2/712	Relay Room - Station Building - Bounds Green Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Cream matt wall - 12m² - thickness : 0.27mm Analysis : 7.6% HMU Re-Inspection Poor Condition - 10-03-2015				N	N
44434	INACTIVE	P	P023-00-2/712	Relay Room - Station Building - Bounds Green Stn	PCBs	Polychlorinated biphenyl	Presumed				HMU Re-Inspection 8 PCB's Fair - 10-03-2015		8		N	N
20866	ACTIVE	P	P023-00-2/712/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - Bounds Green Stn	No Access	Asbestos	No Access: Presumed				No Information					
12939	ACTIVE	P	P023-00-2/731	CER - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24012	ACTIVE	P	P023-00-2/731	CER - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding					
20872	ACTIVE	P	P023-00-2/731	CER - Station Building - Bounds Green Stn	Lead/Leading	Lead Paint/Lead	Known				Equipment surround - green matt - 7m² - thickness : 0.04mm Analysis : 1.2% HMPSRe-inspection confirmed overpainted				N	N
20870	ACTIVE	P	P023-00-2/731/FLR-01	Floor - 1 - CER - Station Building - Bounds Green Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Boarding on floor					
20871	ACTIVE	P	P023-00-2/731/WAL-003	Wall: Internal - 3 - CER - Station Building - Bounds Green Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding					



Hazardous Material Asset Register - Summary



P023-00 - Station Building - Bounds Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12940	ACTIVE	P	P023-00-2/732	CER - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20873	ACTIVE	P	P023-00-2/732/FLR-01	Floor - 1 - CER - Station Building - Bounds Green Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					Yes
20875	ACTIVE	P	P023-00-2/732/WAL-001	Wall: Internal - 1 - CER - Station Building - Bounds Green Stn	Isolator Switches	Asbestos	Strongly Presumed				W1 2x Iron clad isolators, 2 x 60 Amps, HMU Re-Inspection - 10-03-2015 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2		N	N
20874	ACTIVE	P	P023-00-2/732/WAL-001 80863081	Wall: Internal - 1 - CER - Station Building - Bounds Green Stn Wall: Internal	Other Boarding	Asbestos	Strongly Presumed				Paxoline Board to wall 4 and wall 1				N	N
24013	INACTIVE	P	P023-00-2/732/WAL-002	Wall: Internal - 2 - CER - Station Building - Bounds Green Stn	Other Boarding	Asbestos	Strongly Presumed				Paxoline Board HMU Re-Inspection ok - 10-03-2015				N	N
12941	ACTIVE	P	P023-00-2/733	Switch Room - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20876	ACTIVE	P	P023-00-2/733/FLR-01	Floor - 1 - MDF - Station Building - Bounds Green Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					Yes
12942	ACTIVE	P	P023-00-2/761	Relay Room - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44523	ACTIVE	P	P023-00-2/761	Relay Room - Station Building - Bounds Green Stn	Other Electrical Boxes	Asbestos	Presumed				Green electrical box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within				N	N
44522	ACTIVE	P	P023-00-2/761 80143226	Relay Room - Station Building - Bounds Green Stn Room Assets	Other Boarding	Asbestos	Presumed				Paxoline Board 1 W2 All Alone - 10-03-2015				N	N
44524	ACTIVE	P	P023-00-2/761 80143226	Relay Room - Station Building - Bounds Green Stn Room Assets	Lead/Leading	Lead Paint/Lead	Presumed				Green paint on electrical box				N	N
20878	ACTIVE	P	P023-00-2/761 80143226	Relay Room - Station Building - Bounds Green Stn Room Assets	Lead/Leading	Lead Paint/Lead	Known				Cream matt wall - 8m² - thickness : 0.27mm Analysis : 7.8% HMPS Re-Inspection Poor Condition -				N	N
20877	ACTIVE	P	P023-00-2/761/WAL-002 80863103	Wall: Internal - 2 - Relay Room - Station Building - Bounds Green Stn Wall: Internal	Cable: Sheath	Asbestos	Strongly Presumed				7 x Cables - 1x40mm dia, 5x 20mm dia HMU Re-Inspection Papoline Board 1 W2 All Alone - 10-03-2015		6		N	N
12943	ACTIVE	P	P023-00-2/762	Relay Room - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44533	ACTIVE	P	P023-00-2/762	Relay Room - Station Building - Bounds Green Stn	Cable Ducts: Cement	Asbestos	Presumed				5 cable ducts to floor				N	N



Hazardous Material Asset Register - Summary



P023-00 - Station Building - Bounds Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20879	ACTIVE	p	P023-00-2/762	Relay Room - Station Building - Bounds Green Stn	Cable: Sheath	Asbestos	Strongly Presumed				6x Cables 3 x 20mm dia, 2 x 30mm dia, 1x 40mm dia HMU Re-Inspection ok - 10-03-2015		6		N	N
44530	ACTIVE	p	P023-00-2/762	Relay Room - Station Building - Bounds Green Stn	Other Boarding	Asbestos	Presumed				Brown paxoline boarding throughout room				N	N
44531	ACTIVE	p	P023-00-2/762	Relay Room - Station Building - Bounds Green Stn	Other Electrical Boxes	Asbestos	Presumed				Green electrical box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within				N	N
44532	ACTIVE	p	P023-00-2/762	Relay Room - Station Building - Bounds Green Stn	Lead/Leading	Lead Paint/Lead	Presumed				Green paint on electrical box				N	N
24014	ACTIVE	p	P023-00-2/762	Relay Room - Station Building - Bounds Green Stn	Lead/Leading	Lead Paint/Lead	Known				Cream matt wall - 8m ² - thickness : 0.27mm Analysis : 7.8% HMU Re-Inspection Fair Condition - 10-03-2015				N	N
12944	ACTIVE	p	P023-00-2/786	Service Riser - Station Building - Bounds Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24015	ACTIVE	p	P023-00-2/786	Service Riser - Station Building - Bounds Green Stn	Other Electrical Boxes	Asbestos	No Access: Presumed				2nd Passage - Ventilation Equipment HMU Re-Inspection No Access 10-03-2015 No access during 2020 re-inspection. confined space.				N	N
20882	ACTIVE	p	P023-00-2/786	Service Riser - Station Building - Bounds Green Stn	Other Electrical Boxes	Asbestos	No Access: Presumed				Ventilation Equipment HMU Re-Inspection No Access 10-03-2015 No access during 2020 re-inspection. Confined space.				N	N
20881	ACTIVE	p	P023-00-2/786	Service Riser - Station Building - Bounds Green Stn	Westing house Boxes	Asbestos	Surveyed – Not Detected				2 Westinghouse boxes		2			
20883	ACTIVE	p	P023-00-2/786	Service Riser - Station Building - Bounds Green Stn	Lead/Leading	Lead Paint/Lead	Known				2nd Passage - down stairs to LMC - blue /green - 7m ² - thickness : 0.49mm Analysis : 9.8% HMU Re-Inspection ok - 10-03-2015				N	N
20884	ACTIVE	p	P023-00-2/791/CLG-01	Ceiling: Solid - 1 - Vent Shaft - Station Building - Bounds Green Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Rings - Caulking sampled non-asbestos					

P025-00 - Station Building - Wood Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12946	ACTIVE	p	P025-00-1/001	Booking Hall - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20885	ACTIVE	p	P025-00-1/001	Booking Hall - Station Building - Wood Green Stn		Asbestos	Surveyed – Not Detected				Above passage entrances - Supalux					



Hazardous Material Asset Register - Summary



P025-00 - Station Building - Wood Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12947	ACTIVE	P	P025-00-1/011	Ticket Office - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20889	ACTIVE	P	P025-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Wood Green Stn	Void	Asbestos	Surveyed – Not Detected				Supalux panels, metal trunking & CMS tray work, wood sections, very low void for installation of new CMS, plastic sheathed cables above false ceiling				Yes	
20888	ACTIVE	P	P025-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Wood Green Stn		Asbestos	Surveyed – Not Detected				Supalux panels					
20890	ACTIVE	P	P025-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Wood Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete screed base floor with plastic sheathed cables & metal trunking & tray work. Some rock wool insulation BENEATH - Wood floor tiles with non asbestos vinyl covering & metal trims					Yes
20886	ACTIVE	P	P025-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Wood Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete screed base floor with plastic sheathed cables & metal trunking & tray work. Some rock wool insulation BENEATH - Wood floor tiles with non asbestos vinyl covering & metal trims					Yes
20887	ACTIVE	P	P025-00-1/011/WAL-001	Wall: Internal - 1 - Ticket Office - Station Building - Wood Green Stn		Asbestos	Surveyed – Not Detected				Suplax boxing					
12948	ACTIVE	P	P025-00-1/021	POM - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12949	ACTIVE	P	P025-00-1/031	Mess Room - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20892	ACTIVE	P	P025-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Wood Green Stn	Void	Asbestos	No Access: Presumed				Concrete ceiling, metal trunking & CMS tray work, wood sections, plastic sheathed cables. No safe access to enter loft space level				Yes	
20891	ACTIVE	P	P025-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Wood Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels					
12950	ACTIVE	P	P025-00-1/036	Toilet: Unisex - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20893	ACTIVE	P	P025-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Wood Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels					
20894	ACTIVE	P	P025-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Wood Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete & plaster, solid ceiling , plastic sheathed cables & metal trunking & tray work above false ceiling				Yes	



Hazardous Material Asset Register - Summary



P025-00 - Station Building - Wood Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12951	ACTIVE	P	P025-00-1/071	Circulation Area - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20895	ACTIVE	P	P025-00-1/071/FLR-01	Floor - 1 - Circulation Area - Station Building - Wood Green Stn	Void	Asbestos	No Access: Presumed				Beneath Ceramic tiles, metal floor plates. Ceramic tiles, metal floor plates					Yes
20896	ACTIVE	P	P025-00-1/071/WAL-002	Wall: Internal - 2 - Circulation Area - Station Building - Wood Green Stn	No Access	Asbestos	No Access: Presumed				Canopy level, supalux / metal banisters					
12952	ACTIVE	P	P025-00-1/081	Lobby - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12953	ACTIVE	P	P025-00-1/151	UMC - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44551	ACTIVE	P	P025-00-1/151	UMC - Station Building - Wood Green Stn	Lead/Leading	Lead Paint/Lead	Presumed				Red paint to pipework throughout				N	N
44302	ACTIVE	P	P025-00-1/151	UMC - Station Building - Wood Green Stn	Lead/Leading	Lead Paint/Lead	Known				Grey Gloss Landing trusses Thickness 140mm Analysis 1.01%			R609051	N	N
44300	ACTIVE	P	P025-00-1/151	UMC - Station Building - Wood Green Stn	Lead/Leading	Lead Paint/Lead	Known				Yellow Gloss Trusses/support column Thickness 130mm Analysis 29.8%			R609051	N	N
44299	ACTIVE	P	P025-00-1/151	UMC - Station Building - Wood Green Stn	Lead/Leading	Lead Paint/Lead	Known				Yellow Gloss Trusses/support column Thickness 130mm Analysis 6.63%			R609051	N	N
44297	ACTIVE	P	P025-00-1/151	UMC - Station Building - Wood Green Stn	Lead/Leading	Lead Paint/Lead	Known				Grey Gloss Landing trusses Thickness 140mm Analysis 4.23%			R609051	N	N
20906	ACTIVE	P	P025-00-1/151	UMC - Station Building - Wood Green Stn	Lead/Leading	Lead Paint/Lead	Known				Air conditioning unit - Blue gloss - 15m ² - Thickness : 0.40mm Analysis : 10.4% UMC has been overpainted					N
44296	ACTIVE	P	P025-00-1/151	UMC - Station Building - Wood Green Stn	Lead/Leading	Lead Paint/Lead	Sampled – Not Detected				Blue Gloss Trusses/support column Thickness 110mm Analysis 0.5%			R609051	N	N
23900	ACTIVE	P	P025-00-1/151	UMC - Station Building - Wood Green Stn	Lead/Leading	Lead Paint/Lead	Known				Metal beams - Blue gloss - 30m ² - Thickness : 0.30mm Analysis : 14.2% UMC has been overpainted				N	N
20907	ACTIVE	P	P025-00-1/151	UMC - Station Building - Wood Green Stn	Lead/Leading	Lead Paint/Lead	Known				UMC middle of stairs - Metal beam & stair barriers & pipe bottom of stairs - 2m ² - Metal/gloss - Thickness : 0.26mm Analysis : 1.64%					
24044	ACTIVE	P	P025-00-1/151	UMC - Station Building - Wood Green Stn	Lead/Leading	Lead Paint/Lead	Known				UMC middle of stairs - Pipes from ceiling middle of stairs to floor to ceiling bolt stairs - Thickness : 0.06mm Analysis : 3.1%					N
44298	ACTIVE	P	P025-00-1/151	UMC - Station Building - Wood Green Stn	Lead/Leading	Lead Paint/Lead	Sampled – Not Detected				Grey Gloss Incline trusses Thickness 130mm Analysis 0.4%			R609051	N	N
44301	ACTIVE	P	P025-00-1/151	UMC - Station Building - Wood Green Stn	Lead/Leading	Lead Paint/Lead	Known				Blue Gloss Trusses/support column Thickness 120mm Analysis 5.57%			R609051	N	N



Hazardous Material Asset Register - Summary



P025-00 - Station Building - Wood Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44303	ACTIVE	P	P025-00-1/151	UMC - Station Building - Wood Green Stn	Lead/Leading	Lead Paint/Lead	Sampled – Not Detected				Grey Gloss Incline trusses Thickness 140mm Analysis 0.48%			R609051	N	N
44295	ACTIVE	P	P025-00-1/151	UMC - Station Building - Wood Green Stn	Lead/Leading	Lead Paint/Lead	Known				Yellow Gloss Trusses/support column Thickness 120mm Analysis 5.04%			R609051	N	N
43715	ACTIVE	P	P025-00-1/151/WAL-001	Wall: Internal - 1 - UMC - Station Building - Wood Green Stn		Asbestos	Sampled – Not Detected				Gasket 6" x 6" bottom valve in UMC			R591226	N	N
20899	ACTIVE	P	P025-00-1/151/WAL-001 80882580	Wall: Internal - 1 - UMC - Station Building - Wood Green Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Iron clad isolator, same wall as stairs (1 x 300 amps) Asbestos Components - Strongly Presumed Within		1		N	N
20902	ACTIVE	P	P025-00-1/151/WAL-001 80882580	Wall: Internal - 1 - UMC - Station Building - Wood Green Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				300 amp Switch and trunking				N	N
23619	ACTIVE	P	P025-00-1/151/WAL-001 80882580	Wall: Internal - 1 - UMC - Station Building - Wood Green Stn Wall: Internal	Cable Duct: Other	Asbestos	Strongly Presumed				Cable sleeve - high level		3		N	N
43714	ACTIVE	P	P025-00-1/151/WAL-001	Wall: Internal - 1 - UMC - Station Building - Wood Green Stn		Asbestos	Sampled – Not Detected				Gasket 6" x 6" top flange in UMC			R591226	N	N
43713	ACTIVE	P	P025-00-1/151/WAL-001	Wall: Internal - 1 - UMC - Station Building - Wood Green Stn		Asbestos	Sampled – Not Detected				Gasket 6" x 6" to gate valve in UMC			R591226	N	N
44550	ACTIVE	P	P025-00-1/151/WAL-001 80882580	Wall: Internal - 1 - UMC - Station Building - Wood Green Stn Wall: Internal	Gasket :Pipework	Asbestos	Presumed				Gaskets to pipework by stairs		8		N	N
20904	ACTIVE	P	P025-00-1/151/WAL-002	Wall: Internal - 2 - UMC - Station Building - Wood Green Stn	Rope Gaskets	Asbestos	Strongly Presumed				Gaskets within wall 2 vent system					N
20898	ACTIVE	P	P025-00-1/151/WAL-002	Wall: Internal - 2 - UMC - Station Building - Wood Green Stn	Void	Asbestos	No Access: Presumed				Behind Supalux and wood panel					
20897	INACTIVE	P	P025-00-1/151/WAL-002	Wall: Internal - 2 - UMC - Station Building - Wood Green Stn	Boarding: Supalux	Asbestos	No Access: Presumed				No Access behind Supalux Panel(s)					
20905	ACTIVE	P	P025-00-1/151/WAL-002	Wall: Internal - 2 - UMC - Station Building - Wood Green Stn	Lead/Leading	Lead Paint/Lead	Known				Door, wall 2 - White gloss - 1.5m ² - Thickness : 0.45mm Analysis : 9.71% UMC has been overpainted				N	N
44552	ACTIVE	P	P025-00-1/151/WAL-003 80882582	Wall: Internal - 3 - UMC - Station Building - Wood Green Stn Wall: Internal	Gasket :Pipework	Asbestos	Presumed				Gaskets to pipework - 6 no. Including down-pipe		6		N	N
20900	ACTIVE	P	P025-00-1/151/WAL-003 80882582	Wall: Internal - 3 - UMC - Station Building - Wood Green Stn Wall: Internal	Cable Duct: Other	Asbestos	Strongly Presumed				Cable sleeve - ceiling level		1			N



Hazardous Material Asset Register - Summary



P025-00 - Station Building - Wood Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20903	ACTIVE	P	P025-00-1/151/WAL-003	Wall: Internal - 3 - UMC - Station Building - Wood Green Stn	Isolator Switches	Asbestos	Not Found during Inspection				Switch and trunking					
24017	ACTIVE	P	P025-00-1/151/WAL-003	Wall: Internal - 3 - UMC - Station Building - Wood Green Stn	Rope Gaskets	Asbestos	Strongly Presumed				Gaskets within walls 3 vent system				N	N
24016	ACTIVE	P	P025-00-1/151/WAL-004 80882583	Wall: Internal - 4 - UMC - Station Building - Wood Green Stn Wall: Internal	Cable Duct: Other	Asbestos	Strongly Presumed				Cable sleeve - ceiling level		1			N
44553	ACTIVE	P	P025-00-1/151/WAL-004 80882583	Wall: Internal - 4 - UMC - Station Building - Wood Green Stn Wall: Internal	Lead/Leading	Lead Paint/Lead	Presumed				Blue gloss paint to pipework				N	N
44549	ACTIVE	P	P025-00-1/151/WAL-005 80882584	Wall: Internal - 5 - UMC - Station Building - Wood Green Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				Transformer box with 2 x switch boxes attached		3		N	N
20901	ACTIVE	P	P025-00-1/151/WAL-006 80882585	Wall: Internal - 6 - UMC - Station Building - Wood Green Stn Wall: Internal	Cable Duct: Other	Asbestos	Strongly Presumed				Cable sleeve - ceiling level		3			N
12954	ACTIVE	P	P025-00-1/201	Passage - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20909	ACTIVE	P	P025-00-1/201	Passage - Station Building - Wood Green Stn	Lead/Leading	Lead Paint/Lead	Known				6x Poster boards - Black gloss - 6x2m ² - Thickness : 0.10mm Analysis : 1.4%				N	N
20908	ACTIVE	P	P025-00-1/201/FLR-01	Floor - 1 - Passage - Station Building - Wood Green Stn	Void	Asbestos	No Access: Presumed				Beneath false floor of metal/rubber grating					Yes
12955	ACTIVE	P	P025-00-1/202	Passage - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20911	ACTIVE	P	P025-00-1/202	Passage - Station Building - Wood Green Stn	Lead/Leading	Lead Paint/Lead	Known				6x Poster boards - Black gloss - 6x2m ² - Thickness : 0.10mm Analysis : 1.4%				N	N
20912	ACTIVE	P	P025-00-1/202/FLR-01	Floor - 1 - Passage - Station Building - Wood Green Stn	Void	Asbestos	No Access: Presumed				Beneath false floor - metal/rubber grating					Yes
20910	INACTIVE	P	P025-00-1/202/FLR-01	Floor - 1 - Passage - Station Building - Wood Green Stn	Void	Asbestos	No Access: Presumed				Beneath false floor of metal/rubber grating					Yes
12956	ACTIVE	P	P025-00-1/203	Passage - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20913	ACTIVE	P	P025-00-1/203	Passage - Station Building - Wood Green Stn	Lead/Leading	Lead Paint/Lead	Known				6x Poster boards - Black gloss - 6x2m ² - Thickness : 0.10mm Analysis : 1.4%				N	N
12957	ACTIVE	P	P025-00-1/236	Lobby - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P025-00 - Station Building - Wood Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12958	ACTIVE	P	P025-00-1/237	Lobby - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12959	ACTIVE	P	P025-00-1/238	Lobby - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20916	ACTIVE	P	P025-00-1/238/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Wood Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete & plaster, solid ceiling , plastic sheathed cables & metal trunking & tray work above false ceiling				Yes	
20915	ACTIVE	P	P025-00-1/238/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Wood Green Stn		Asbestos	Surveyed – Not Detected				Supalux panels					
20914	ACTIVE	P	P025-00-1/238/FLR-01	Floor - 1 - Lobby - Station Building - Wood Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete screed base floor with plastic sheathed cables & metal trunking & tray work. Some rock wool insulation beneath computer flooring					Yes
12960	ACTIVE	P	P025-00-1/281	Office - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12961	ACTIVE	P	P025-00-1/311	Office - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12962	ACTIVE	P	P025-00-1/316	Store - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20917	ACTIVE	P	P025-00-1/316/FLR-01	Floor - 1 - Store - Station Building - Wood Green Stn	Void	Asbestos	Surveyed – Not Detected				Carpet on Concrete					Yes
12963	ACTIVE	P	P025-00-1/331	Locker Room - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45256	ACTIVE	P	P025-00-1/331/CLG-01	Ceiling: Solid - 1 - Locker Room - Station Building - Wood Green Stn	Glazing Rope	Asbestos	No Access: Presumed				Rope seal under metal glazing bars of skylight				N	N
20918	ACTIVE	P	P025-00-1/331/FLR-01	Floor - 1 - Locker Room - Station Building - Wood Green Stn	Void	Asbestos	No Access: Presumed				Beneath Hatch					Yes
20919	ACTIVE	P	P025-00-1/331/WAL-003 80882001	Wall: Internal - 3 - Locker Room - Station Building - Wood Green Stn Wall: Internal	Rope Gaskets	Asbestos	Removed				Boiler and Metal Flue - Removed				N	N
12964	ACTIVE	P	P025-00-1/332	Mess Room - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20920	ACTIVE	P	P025-00-1/332/FLR-01	Floor - 1 - Mess Room - Station Building - Wood Green Stn	Void	Asbestos	Surveyed – Not Detected				Carpet on Concrete					Yes



Hazardous Material Asset Register - Summary



P025-00 - Station Building - Wood Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20921	ACTIVE	P	P025-00-1/332/WAL-003	Wall: Internal - 3 - Mess Room - Station Building - Wood Green Stn	Bitumen	Asbestos	Surveyed – Not Detected				Sink - acoustic panel		1			
12965	ACTIVE	P	P025-00-1/396	SVC - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20922	ACTIVE	P	P025-00-1/396/WAL-002	Wall: Internal - 2 - SVC - Station Building - Wood Green Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Old metal heater		1			
12966	ACTIVE	P	P025-00-1/407	Store - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12967	ACTIVE	P	P025-00-1/411	Store - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12968	ACTIVE	P	P025-00-1/412	Disused Room - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20924	ACTIVE	P	P025-00-1/412	Disused Room - Station Building - Wood Green Stn	Bitumen	Asbestos	Surveyed – Not Detected				2x 0.25m ² - Acoustic Panel		2			
20923	ACTIVE	P	P025-00-1/412/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Wood Green Stn	Void	Asbestos	Surveyed – Not Detected				Metal tray work CMS above non asbestos foam ceiling tiles				Yes	
24018	ACTIVE	P	P025-00-1/412/FLR-01	Floor - 1 - Disused Room - Station Building - Wood Green Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl floor covering					
12969	ACTIVE	P	P025-00-1/413	Disused Room - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20927	ACTIVE	P	P025-00-1/413/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Wood Green Stn	Void	Asbestos	No Access: Presumed				Above Wood Board				Yes	
20925	ACTIVE	P	P025-00-1/413/FLR-01	Floor - 1 - Disused Room - Station Building - Wood Green Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl floor covering on solid concrete					
20926	ACTIVE	P	P025-00-1/413/WAL-004	Wall: Internal - 4 - Disused Room - Station Building - Wood Green Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino on concrete back at door					
12970	ACTIVE	P	P025-00-1/416	Toilet: Female - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44554	ACTIVE	P	P025-00-1/416	Toilet: Female - Station Building - Wood Green Stn	LUL Heaters	Asbestos	Presumed				Heater		1		N	N



Hazardous Material Asset Register - Summary



P025-00 - Station Building - Wood Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24019	ACTIVE	P	P025-00-1/416/CLG-01 80882071	Ceiling: Solid - 1 - Toilet - Station Building - Wood Green Stn Ceiling: Solid	Void	Asbestos	No Access: Presumed				Above ceiling				Yes	
12971	ACTIVE	P	P025-00-1/417	Toilet: Male - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45257	ACTIVE	P	P025-00-1/417/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Wood Green Stn	Glazing Rope	Asbestos	No Access: Presumed				Rope seal under metal glazing bars of skylight				N	N
20928	ACTIVE	P	P025-00-1/417/FLR-01	Floor - 1 - Toilet - Station Building - Wood Green Stn	Void	Asbestos	No Access: Presumed				Beneath Floor Hatch					Yes
20929	ACTIVE	P	P025-00-1/417/WAL-003	Wall: Internal - 3 - Toilet - Station Building - Wood Green Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Wooden Boxing					
12972	ACTIVE	P	P025-00-1/418	Disused Room - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20775	ACTIVE	P	P025-00-1/418/CLG-01	Ceiling: Suspended - 1 - Disused Room - Station Building - Wood Green Stn	Void	Asbestos	Surveyed – Not Detected				(Toilet) Concrete ceiling, plastic roof glazing, fibre glass lagged pipes, plastic sheathed cables , fibre glass water tank above Supalux panels				Yes	
20931	ACTIVE	P	P025-00-1/418/FLR-01	Floor - 1 - Disused Room - Station Building - Wood Green Stn	Void	Asbestos	No Access: Presumed				(Toilet) Hatch beneath floor					Yes
20930	ACTIVE	P	P025-00-1/418/WAL-001	Wall: Internal - 1 - Disused Room - Station Building - Wood Green Stn	Other Electrical Boxes	Asbestos	Surveyed – Not Detected				Electrical cupboard					
12973	ACTIVE	P	P025-00-1/419	Disused Room - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20776	ACTIVE	P	P025-00-1/419/FLR-01	Floor - 1 - Disused Room - Station Building - Wood Green Stn	Void	Asbestos	Surveyed – Not Detected				Office - Concrete beneath Lino					Yes
20777	ACTIVE	P	P025-00-1/419/WAL-004	Wall: Internal - 4 - Disused Room - Station Building - Wood Green Stn		Asbestos	Surveyed – Not Detected				Suplax panel above door					
12974	ACTIVE	P	P025-00-1/551	Yard - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12975	ACTIVE	P	P025-00-1/552	Yard - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20778	ACTIVE	P	P025-00-1/552/FLR-01	Floor - 1 - Exterior - Station Building - Wood Green Stn	Void	Asbestos	No Access: Presumed				Beneath 3 x Floor Hatches					Yes



Hazardous Material Asset Register - Summary



P025-00 - Station Building - Wood Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12976	ACTIVE	P	P025-00-1/664	Switch Room - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20781	ACTIVE	P	P025-00-1/664	Switch Room - Station Building - Wood Green Stn		Asbestos	Surveyed – Not Detected				Panel behind sweet shop meter - Supalux					
20782	ACTIVE	P	P025-00-1/664/ WAL-001 80882128	Wall: Internal - 1 - Switch Room - Station Building - Wood Green Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				8x Iron clad isolators - 5 x 60 amps, 1 x 100 amps, 1 x 200 amps, 1 x 30 amps - Asbestos Components - Strongly Presumed Within		8		N	N
20783	ACTIVE	P	P025-00-1/664/ WAL-001 80882128	Wall: Internal - 1 - Switch Room - Station Building - Wood Green Stn Wall: Internal	Other Electrical Boxes	Asbestos	Strongly Presumed				Trunking - Asbestos Components - Strongly Presumed Within				N	N
20779	ACTIVE	P	P025-00-1/664/ WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Wood Green Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cable sleeves filled in		2		N	N
20784	ACTIVE	P	P025-00-1/664/ WAL-002 80882129	Wall: Internal - 2 - Switch Room - Station Building - Wood Green Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				1x Iron clad isolator 1 x 30 amps - Asbestos Components - Strongly Presumed Within		1		N	N
20780	ACTIVE	P	P025-00-1/664/ WAL-003 80882130	Wall: Internal - 3 - Switch Room - Station Building - Wood Green Stn Wall: Internal	Cable: Sheath	Asbestos	Strongly Presumed				Cable sleeves to floor - quantity unknown due to filled over				N	N
24042	ACTIVE	P	P025-00-1/664/ WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Wood Green Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Wood panel behind motor					
12977	ACTIVE	P	P025-00-1/665	Switch Room - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20785	ACTIVE	P	P025-00-1/665/ CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Wood Green Stn		Asbestos	Surveyed – Not Detected				Supalux Panels					
20786	ACTIVE	P	P025-00-1/665/ CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Wood Green Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
20788	ACTIVE	P	P025-00-1/665/ WAL-002 80882136	Wall: Internal - 2 - Switch Room - Station Building - Wood Green Stn Wall: Internal	Other Electrical Boxes	Asbestos	Strongly Presumed				Trunking - Asbestos Components - Strongly Presumed Within				N	N
20787	ACTIVE	P	P025-00-1/665/ WAL-002 80882136	Wall: Internal - 2 - Switch Room - Station Building - Wood Green Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				9x Iron clad isolators 2 x 100 amps, 2 x 300 amps, 2 x 30 amps, 3 x 60 amps - Asbestos Components - Strongly Presumed Within		9		N	N
12978	ACTIVE	P	P025-00-1/667	Switch Cupboard - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20789	ACTIVE	P	P025-00-1/667	Switch Cupboard - Station Building - Wood Green Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					



Hazardous Material Asset Register - Summary



P025-00 - Station Building - Wood Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12979	ACTIVE	P	P025-00-1/731	CER - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44555	ACTIVE	P	P025-00-1/731	CER - Station Building - Wood Green Stn	Other Boarding	Asbestos	Presumed				Various paxoline boards		3		N	N
23980	ACTIVE	P	P025-00-1/731/FLR-01	Floor - 1 - CER - Station Building - Wood Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath Computer Tiles					Yes
20790	ACTIVE	P	P025-00-1/731/WAL-001 80882142	Wall: Internal - 1 - CER - Station Building - Wood Green Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				2 x - Iron clad isolator - 2 x 60 amps - Asbestos Components - Strongly Presumed Within		2		N	N
12980	ACTIVE	P	P025-00-1/746	SCR - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12981	ACTIVE	P	P025-00-1/747	SCR - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12982	ACTIVE	P	P025-00-1/751	Station Control Room - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12983	ACTIVE	P	P025-00-1/761	Equipment Room - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12984	ACTIVE	P	P025-00-1/762	Equipment Room - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20791	ACTIVE	P	P025-00-1/762/FLR-01 80882185	Floor - 1 - Equipment Room - Station Building - Wood Green Stn Floor	Void	Asbestos	No Access: Presumed				Beneath Wood panels on ledge to wall 1					Yes
20792	ACTIVE	P	P025-00-1/791/WAL-003	Wall: Internal - 3 - Vent Shaft - Station Building - Wood Green Stn	Caulking	Asbestos	Strongly Presumed				Tunnel ring caulking					
12985	ACTIVE	P	P025-00-1/801	Disused Room - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20794	ACTIVE	P	P025-00-1/801/CLG-01	Ceiling: Suspended - 1 - Disused Room - Station Building - Wood Green Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
20795	ACTIVE	P	P025-00-1/801/CLG-01	Ceiling: Suspended - 1 - Disused Room - Station Building - Wood Green Stn	Void	Asbestos	Surveyed – Not Detected				Hatch to loft - vent equipment and supalux				Yes	
20793	ACTIVE	P	P025-00-1/801/WAL-002	Wall: Internal - 2 - Disused Room - Station Building - Wood Green Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard partition walls					



Hazardous Material Asset Register - Summary



P025-00 - Station Building - Wood Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24004	ACTIVE	P	P025-00-1/801/WAL-003	Wall: Internal - 3 - Disused Room - Station Building - Wood Green Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard partition walls					
12986	ACTIVE	P	P025-00-1/901	Disused Room - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20796	ACTIVE	P	P025-00-1/901	Disused Room - Station Building - Wood Green Stn		Asbestos	Surveyed – Not Detected				Suplax panel above door					
20797	ACTIVE	P	P025-00-1/901/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Wood Green Stn	Void	Asbestos	Surveyed – Not Detected				Metal tray work CMS above false ceiling				Yes	
20798	ACTIVE	P	P025-00-1/901/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Wood Green Stn	Void	Asbestos	No Access: Presumed				Lower ceiling - No Access, live electrics				Yes	
20799	ACTIVE	P	P025-00-1/901/WAL-001 80882198	Wall: Internal - 1 - Disused Room - Station Building - Wood Green Stn Wall: Internal	Other Electrical Boxes	Asbestos	Strongly Presumed				Redundant electrical equipment to wall - Asbestos Components - Strongly Presumed Within		3		N	N
24005	ACTIVE	P	P025-00-1/901/WAL-002 80882199	Wall: Internal - 2 - Disused Room - Station Building - Wood Green Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Iron clad isolator 30 amp - Asbestos Components - Strongly Presumed Within		1		N	N
45258	INACTIVE	P	P025-00-1/901/WAL-004	Wall: Internal - 4 - Disused Room - Station Building - Wood Green Stn	Other Boarding	Asbestos	Strongly Presumed				Electrical and wood board behind				N	N
12987	ACTIVE	P	P025-00-1/902	Disused Room - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20800	ACTIVE	P	P025-00-1/902/WAL-003	Wall: Internal - 3 - Disused Room - Station Building - Wood Green Stn	Bitumen	Asbestos	Surveyed – Not Detected				Sink - acoustic panel		1			
20801	ACTIVE	P	P025-00-1/902/WAL-003	Wall: Internal - 3 - Disused Room - Station Building - Wood Green Stn	Void	Asbestos	Surveyed – Not Detected				Ceramic tiles on plasterboard					
12988	ACTIVE	P	P025-00-1/903	Void - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12989	ACTIVE	P	P025-00-2/036	Lobby - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12990	ACTIVE	P	P025-00-2/037	Toilet: Unisex - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12991	ACTIVE	P	P025-00-2/047	Kitchen - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P025-00 - Station Building - Wood Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12992	ACTIVE	P	P025-00-2/081	Circulation Area - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12993	ACTIVE	P	P025-00-2/161	LMC - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20806	ACTIVE	P	P025-00-2/161	LMC - Station Building - Wood Green Stn	Lead/Leading	Lead Paint/Lead	Known				Metal beams & door to 2/788 - Blue gloss - 6m² - Thickness : 0.30mm Analysis : 14.2%					
20802	ACTIVE	P	P025-00-2/161/FLR-01	Floor - 1 - LMC - Station Building - Wood Green Stn	Void	Asbestos	Surveyed – Not Detected				Sumps beneath floor hatches					Yes
20803	ACTIVE	P	P025-00-2/161/WAL-001 80882618	Wall: Internal - 1 - LMC - Station Building - Wood Green Stn Wall: Internal	Cable Duct: Other	Asbestos	Strongly Presumed				Cable sleeves below ceiling - quantity unknown due to filled over					
20805	ACTIVE	P	P025-00-2/161/WAL-002 80882619	Wall: Internal - 2 - LMC - Station Building - Wood Green Stn Wall: Internal	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse Box by Door to 2/786 - Asbestos Components - Strongly Presumed Within		1			
20804	ACTIVE	P	P025-00-2/161/WAL-002 80882619	Wall: Internal - 2 - LMC - Station Building - Wood Green Stn Wall: Internal	Cable Duct: Other	Asbestos	Strongly Presumed				8 x cable sleeves filled in		8			
12994	ACTIVE	P	P025-00-2/201	Passage - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12995	ACTIVE	P	P025-00-2/202	Passage - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12996	ACTIVE	P	P025-00-2/203	Passage - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12997	ACTIVE	P	P025-00-2/204	Passage - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12998	ACTIVE	P	P025-00-2/237	Passage - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20807	ACTIVE	P	P025-00-2/237/FLR-01	Floor - 1 - Passage - Station Building - Wood Green Stn	Void	Asbestos	No Access: Presumed				Beneath hatches					Yes
20808	ACTIVE	P	P025-00-2/237/WAL-001 80882298	Wall: Internal - 1 - Passage - Station Building - Wood Green Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Iron clad isolator 60 amp - Asbestos Components - Strongly Presumed Within		1		N	N
12999	ACTIVE	P	P025-00-2/238	Passage - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20809	ACTIVE	P	P025-00-2/238/FLR-01	Floor - 1 - Passage - Station Building - Wood Green Stn	Void	Asbestos	No Access: Presumed				Beneath floor hatch					Yes



Hazardous Material Asset Register - Summary



P025-00 - Station Building - Wood Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13000	ACTIVE	p	P025-00-2/239	Passage - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13001	ACTIVE	p	P025-00-2/240	Passage - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13002	ACTIVE	p	P025-00-2/241	Lobby - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13003	ACTIVE	p	P025-00-2/261	Platform 1 - Eastbound Local - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20815	ACTIVE	p	P025-00-2/261	Platform 1 - Eastbound Local - Station Building - Wood Green Stn	Westing house Boxes	Asbestos	Strongly Presumed				Platform 1 Invert - 1x Westinghouse box & 2x Tencore along invert		3			Y
20810	ACTIVE	p	P025-00-2/261	Platform 1 - Eastbound Local - Station Building - Wood Green Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Various Metal Equipment Boxes along Platform		3		N	N
20811	ACTIVE	p	P025-00-2/261	Platform 1 - Eastbound Local - Station Building - Wood Green Stn	Cable: Sheath	Asbestos	Known				Platform 1 Invert - Approx 24 x cables along invert platform side & pit side (some cut)		24			Y
20812	ACTIVE	p	P025-00-2/261	Platform 1 - Eastbound Local - Station Building - Wood Green Stn	Cable: Sheath	Asbestos	Known				Platform 1 Invert - 5 x cable sleeves - halfway along in arches leading to pit - Chrysotile		5			Y
20813	ACTIVE	p	P025-00-2/261	Platform 1 - Eastbound Local - Station Building - Wood Green Stn	Cable Duct: Other	Asbestos	Sampled – Not Detected				Various Cable Ducts sampled in Type 2 please check the attachment					Y
20814	ACTIVE	p	P025-00-2/261	Platform 1 - Eastbound Local - Station Building - Wood Green Stn	Cable: Sheath	Asbestos	Known				Platform 1 Invert - 5x Cable sleeves - Pit side near ladder		5			Y
13004	ACTIVE	p	P025-00-2/262	Platform 2 - Westbound Local - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20816	ACTIVE	p	P025-00-2/262	Platform 2 - Westbound Local - Station Building - Wood Green Stn	Cable: Sheath	Asbestos	Known				Platform 2 Invert - Approx 24 x cables along invert platform side & pit side (some cut)		24			Y
20818	ACTIVE	p	P025-00-2/262	Platform 2 - Westbound Local - Station Building - Wood Green Stn	Cable Duct: Other	Asbestos	Strongly Presumed				5x Cable sleeves - along invert (like drainage channels)		5			Y
24006	ACTIVE	p	P025-00-2/262	Platform 2 - Westbound Local - Station Building - Wood Green Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Platform 2 Invert - Small Westinghouse Box Components with					Y
20817	ACTIVE	p	P025-00-2/262	Platform 2 - Westbound Local - Station Building - Wood Green Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Platform 2 Invert - All cable ducts					Y



Hazardous Material Asset Register - Summary



P025-00 - Station Building - Wood Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13005	ACTIVE	P	P025-00-2/281	Office - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20819	ACTIVE	P	P025-00-2/281	Office - Station Building - Wood Green Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Partition wall plasterboard					
20820	ACTIVE	P	P025-00-2/281/ WAL-001	Wall: Internal - 1 - Office - Station Building - Wood Green Stn		Asbestos	Surveyed – Not Detected				Suplax boxing					
13006	ACTIVE	P	P025-00-2/331	Cleaners Room - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20821	ACTIVE	P	P025-00-2/331/ WAL-003	Wall: Internal - 3 - Cleaners Room - Station Building - Wood Green Stn		Asbestos	Surveyed – Not Detected				Supalux Boxing around vent system					
24007	ACTIVE	P	P025-00-2/331/ WAL-006	Wall: Internal - 6 - Cleaners Room - Station Building - Wood Green Stn		Asbestos	Surveyed – Not Detected				Metal / Supalux Panel of vent unit					
13007	ACTIVE	P	P025-00-2/381	Disused Room - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20822	ACTIVE	P	P025-00-2/381/ WAL-004	Wall: Internal - 4 - Disused Room - Station Building - Wood Green Stn		Asbestos	Surveyed – Not Detected				Suplax Boxing / Wood Coat panel					
13008	ACTIVE	P	P025-00-2/382	Office - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20823	ACTIVE	P	P025-00-2/382/ WAL-002	Wall: Internal - 2 - Office - Station Building - Wood Green Stn		Asbestos	Surveyed – Not Detected				Suplax panel					
13009	ACTIVE	P	P025-00-2/383	Store - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20825	ACTIVE	P	P025-00-2/383	Store - Station Building - Wood Green Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel Rings: Wood and grout caulking to tunnel ring to ceiling - samples taken from within 2/384 which shares the same tunnel bore.			R714576	N	
20824	ACTIVE	P	P025-00-2/383/ CLG-01	Ceiling: Solid - 1 - Store - Station Building - Wood Green Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel Rings: Wood and grout caulking to tunnel ring to ceiling - samples taken from within 2/384 which shares the same tunnel bore.			R714576	N	N
13010	ACTIVE	P	P025-00-2/384	Store - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23617	ACTIVE	P	P025-00-2/384/ CLG-01	Ceiling: Solid - 1 - Store - Station Building - Wood Green Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel Rings: Wood and grout caulking to tunnel ring to ceiling			R714576	N	N



Hazardous Material Asset Register - Summary



P025-00 - Station Building - Wood Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24008	ACTIVE	P	P025-00-2/384/WAL-002	Wall: Internal - 2 - Store - Station Building - Wood Green Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel rings: Wood and grout caulking to tunnel ring to ceiling			R714576	N	N
13011	ACTIVE	P	P025-00-2/401	Store - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13012	ACTIVE	P	P025-00-2/416	Tea Point - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20826	ACTIVE	P	P025-00-2/416/FLR-01	Floor - 1 - Mess Room - Station Building - Wood Green Stn	Void	Asbestos	No Access: Presumed				Beneath Hatch					Yes
13013	ACTIVE	P	P025-00-2/417	Toilet: Female - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21092	ACTIVE	P	P025-00-2/417/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Wood Green Stn		Asbestos	Surveyed – Not Detected				Suplax panels					
21093	ACTIVE	P	P025-00-2/417/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Wood Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete Ceiling, Metal Trunking & CMS Tray work, Wood sections, Plastic Sheathed Cables above false ceiling				Yes	
23898	ACTIVE	P	P025-00-2/417/FLR-01	Floor - 1 - Toilet - Station Building - Wood Green Stn	Void	Asbestos	No Access: Presumed				Beneath Hatch					Yes
13014	ACTIVE	P	P025-00-2/418	Toilet: Male - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21095	ACTIVE	P	P025-00-2/418/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Wood Green Stn		Asbestos	Surveyed – Not Detected				Suplax Tiles					
21096	ACTIVE	P	P025-00-2/418/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Wood Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete Ceiling, Metal Trunking & CMS Tray work, Wood sections, Plastic Sheathed Cables above false ceiling				Yes	
21094	ACTIVE	P	P025-00-2/418/FLR-01 80882447	Floor - 1 - Toilet - Station Building - Wood Green Stn Floor	Void	Asbestos	No Access: Presumed				Beneath Hatch					
13015	ACTIVE	P	P025-00-2/661	Switch Room - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45259	INACTIVE	P	P025-00-2/661	Switch Room - Station Building - Wood Green Stn	Cable Duct: Other	Asbestos	Strongly Presumed				15x Cables sleeves		15		N	N
21099	ACTIVE	P	P025-00-2/661/FLR-01	Floor - 1 - Switch Room - Station Building - Wood Green Stn	Cable Duct: Other	Asbestos	Strongly Presumed				4no Blocks of cable ducts to floor (approx. 15no ducts in total)		4		N	N



Hazardous Material Asset Register - Summary



P025-00 - Station Building - Wood Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21097	ACTIVE	P	P025-00-2/661/WAL-002 80882452	Wall: Internal - 2 - Switch Room - Station Building - Wood Green Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Iron clad isolator x 9 - 3 x 300 amps, 1 x 200 amps, 3 x 100 amps, 1 x 60 amps, 1 x 30 amps - Asbestos Components - Strongly Presumed Within		9		N	N
21098	ACTIVE	P	P025-00-2/661/WAL-002 80882452	Wall: Internal - 2 - Switch Room - Station Building - Wood Green Stn Wall: Internal	Other Electrical Boxes	Asbestos	Strongly Presumed				2 x Trunking - Asbestos Components - Strongly Presumed Within				N	N
13016	ACTIVE	P	P025-00-2/663	Switch Room - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21102	ACTIVE	P	P025-00-2/663	Switch Room - Station Building - Wood Green Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Cable sleeves - filled in				N	N
21101	ACTIVE	P	P025-00-2/663/WAL-001 80882460	Wall: Internal - 1 - Switch Room - Station Building - Wood Green Stn Wall: Internal	Other Electrical Boxes	Asbestos	Strongly Presumed				Trunking - Asbestos Components - Strongly Presumed Within				N	N
23621	ACTIVE	P	P025-00-2/663/WAL-001 80882460	Wall: Internal - 1 - Switch Room - Station Building - Wood Green Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				3x Iron clad isolator - 2 x 60 amps, 1 x 30 amps - Asbestos Components - Strongly Presumed Within		3		N	N
21100	ACTIVE	P	P025-00-2/663/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Wood Green Stn	Void	Asbestos	No Access: Presumed				Above wood panels - wall 4				Yes	
13017	ACTIVE	P	P025-00-2/666	Switch Room - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21103	ACTIVE	P	P025-00-2/666/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Wood Green Stn		Asbestos	Surveyed – Not Detected				2 x Supalux panels					
21104	ACTIVE	P	P025-00-2/666/WAL-003 80882470	Wall: Internal - 3 - Switch Room - Station Building - Wood Green Stn Wall: Internal	Boarding: Supalux	Asbestos	No Access: Presumed				Suplax boxing - wall 1 & 3					
13018	ACTIVE	P	P025-00-2/706	IMR - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44557	ACTIVE	P	P025-00-2/706 80143227	IMR - Station Building - Wood Green Stn Room Assets	Other Boarding	Asbestos	Presumed				Paxoline boarding		10		N	N
44463	ACTIVE	P	P025-00-2/706 80143227	IMR - Station Building - Wood Green Stn Room Assets	Cable: Sheath	Asbestos	Strongly Presumed				Multiple Strongly presumed Asbestos Cables within 2/706				N	N
44560	ACTIVE	P	P025-00-2/706 80143227	IMR - Station Building - Wood Green Stn Room Assets	Cable Ducts: Bitumen	Asbestos	Presumed				Cable ducts				N	N
44558	INACTIVE	P	P025-00-2/706 80143227	IMR - Station Building - Wood Green Stn Room Assets	PCBs	Polychlorinated biphenyl	Presumed				Presumed blue cylinder PCBs mounted at high level		9		N	N
44559	INACTIVE	P	P025-00-2/706 80143227	IMR - Station Building - Wood Green Stn Room Assets	PCBs	Polychlorinated biphenyl	Presumed				Presumed black box PCBs		10		N	N



Hazardous Material Asset Register - Summary



P025-00 - Station Building - Wood Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21105	ACTIVE	P	P025-00-2/706/CLG-01	Ceiling: Suspended - 1 - IMR - Station Building - Wood Green Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				Yes	
13019	ACTIVE	P	P025-00-2/711	Relay Room - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44563	ACTIVE	P	P025-00-2/711 80143228	Relay Room - Station Building - Wood Green Stn Room Assets	Other Electrical Boxes	Asbestos	Presumed				Green electrical box behind steelwork - Asbestos Components - Presumed Within		1		N	N
44561	ACTIVE	P	P025-00-2/711 80143228	Relay Room - Station Building - Wood Green Stn Room Assets	Other Boarding	Asbestos	Presumed				Paxoline boarding wall 1 & 2		4		N	N
44562	ACTIVE	P	P025-00-2/711 80143228	Relay Room - Station Building - Wood Green Stn Room Assets	Westing house Boxes	Asbestos	Presumed				Westinghouse box - Asbestos Components - Presumed Within		1		N	N
43382	INACTIVE	P	P025-00-2/711	Relay Room - Station Building - Wood Green Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				PCB's Blue Cylinder on Racks High Mounted		7		N	N
21106	ACTIVE	P	P025-00-2/711/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - Wood Green Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
21107	ACTIVE	P	P025-00-2/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Wood Green Stn	Cable: Sheath	Asbestos	Strongly Presumed				27 x Cables		27		N	N
13020	ACTIVE	P	P025-00-2/712	Pump Room - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44564	ACTIVE	P	P025-00-2/712	Pump Room - Station Building - Wood Green Stn	Other Electrical Boxes	Asbestos	Presumed				Presumed green electrical box - Asbestos Components - Presumed Within		1		N	N
44565	ACTIVE	P	P025-00-2/712	Pump Room - Station Building - Wood Green Stn	Cable: Sheath	Asbestos	Presumed				Cable ducts and sleeves				N	N
21108	ACTIVE	P	P025-00-2/712/FLR-01	Floor - 1 - Pump Room - Station Building - Wood Green Stn	Void	Asbestos	Surveyed – Not Detected				Sumps beneath hatches					Yes
21109	ACTIVE	P	P025-00-2/712/WAL-003	Wall: Internal - 3 - Pump Room - Station Building - Wood Green Stn	Cable: Sheath	Asbestos	Strongly Presumed				12 x Cables		12		N	N
13021	ACTIVE	P	P025-00-2/713	Relay Room - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21113	ACTIVE	P	P025-00-2/713 80143229	Relay Room - Station Building - Wood Green Stn Room Assets	Cable: Sheath	Asbestos	Strongly Presumed				Numerous Green cables from invert to head wall				N	N
43383	INACTIVE	P	P025-00-2/713	Relay Room - Station Building - Wood Green Stn	PCBs	Polychlorinated biphenyl	Known				PCB's Blue Cylinder on Racks High Mounted				N	N
23547	ACTIVE	P	P025-00-2/713/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - Wood Green Stn	Void	Asbestos	Surveyed – Not Detected				Solid above false ceiling				Yes	



Hazardous Material Asset Register - Summary



P025-00 - Station Building - Wood Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23548	ACTIVE	P	P025-00-2/713/WAL-001 80882513	Wall: Internal - 1 - Relay Room - Station Building - Wood Green Stn Wall: Internal	Other Boarding	Asbestos	Presumed				Paxoline Boards		1		N	N
44556	ACTIVE	P	P025-00-2/713/WAL-001 80882513	Wall: Internal - 1 - Relay Room - Station Building - Wood Green Stn Wall: Internal	Westing house Boxes	Asbestos	Presumed				Westinghouse box - Asbestos Components - Presumed Within		1		N	N
21110	ACTIVE	P	P025-00-2/713/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Wood Green Stn	Cable: Sheath	Asbestos	Not Found during Inspection				Green cables to signals				N	N
21111	ACTIVE	P	P025-00-2/713/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Wood Green Stn	Cable: Sheath	Asbestos	Strongly Presumed				Green cables to signals		2		N	N
21112	ACTIVE	P	P025-00-2/713/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Wood Green Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Green cable to phone and signal light		2		N	N
13022	ACTIVE	P	P025-00-2/731	CER - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21114	ACTIVE	P	P025-00-2/731/WAL-001	Wall: Internal - 1 - CER - Station Building - Wood Green Stn		Asbestos	Surveyed – Not Detected				Suplax Panel					
13023	ACTIVE	P	P025-00-2/732	Equipment Room - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21115	ACTIVE	P	P025-00-2/732/WAL-003	Wall: Internal - 3 - Equipment Room - Station Building - Wood Green Stn		Asbestos	Surveyed – Not Detected				Supalux panel and frame around window					
13024	ACTIVE	P	P025-00-2/786	Service Riser - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21119	ACTIVE	P	P025-00-2/786	Service Riser - Station Building - Wood Green Stn	Cable Duct: Other	Asbestos	Strongly Presumed				9 x cable sleeves - some filled in		9			
21117	ACTIVE	P	P025-00-2/786/CLG-01	Ceiling: Solid - 1 - Service Riser - Station Building - Wood Green Stn		Asbestos	Surveyed – Not Detected				Suplax panels					
21118	INACTIVE	P	P025-00-2/786/CLG-01	Ceiling: Solid - 1 - Service Riser - Station Building - Wood Green Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
21116	ACTIVE	P	P025-00-2/786/FLR-01	Floor - 1 - Service Riser - Station Building - Wood Green Stn		Asbestos	Surveyed – Not Detected				Supalux debris					
23549	ACTIVE	P	P025-00-2/786/WAL-004	Wall: Internal - 4 - Service Riser - Station Building - Wood Green Stn		Asbestos	Surveyed – Not Detected				Suplax panel along door					
21120	ACTIVE	P	P025-00-2/791	Vent Shaft - Station Building - Wood Green Stn	Caulking	Asbestos	Strongly Presumed				Tunnel rings - sealed				N	N



Hazardous Material Asset Register - Summary



P025-00 - Station Building - Wood Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13025	ACTIVE	P	P025-00-2/901	Store - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13026	ACTIVE	P	P025-00-A/041	Mess Room - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13027	ACTIVE	P	P025-00-A/047	Store - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13028	ACTIVE	P	P025-00-A/056	Toilet: Unisex - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13029	ACTIVE	P	P025-00-A/236	Lobby - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13030	ACTIVE	P	P025-00-A/411	Store - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13031	ACTIVE	P	P025-00-A/412	Store - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13032	ACTIVE	P	P025-00-A/576	Stairs: Linear - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13033	ACTIVE	P	P025-00-A/801	Office - Station Building - Wood Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

P027-00 - Station Building - Turnpike Lane Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13034	ACTIVE	P	P027-00-1/396	SVC - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21122	ACTIVE	P	P027-00-1/396/CLG-01	Ceiling: Solid - 1 - SVC - Station Building - Turnpike Lane Stn	Void	Asbestos	No Access: Presumed				Above Wood ceiling				N	N
21121	ACTIVE	P	P027-00-1/396/WAL-002	Wall: Internal - 2 - SVC - Station Building - Turnpike Lane Stn		Asbestos	Surveyed – Not Detected				Suplax panel					
13035	ACTIVE	P	P027-00-1/601	Stairs: Linear - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13036	ACTIVE	P	P027-00-1/602	Stairs: Linear - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P027-00 - Station Building - Turnpike Lane Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13037	ACTIVE	P	P027-00-1/603	Stairs: Linear - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13038	ACTIVE	P	P027-00-1/604	Stairs: Linear - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13039	ACTIVE	P	P027-00-2/001	Booking Hall - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21123	ACTIVE	P	P027-00-2/001/FLR-01	Floor - 1 - Booking Hall - Station Building - Turnpike Lane Stn	Void	Asbestos	No Access: Presumed				Beneath manhole				N	Yes
13040	ACTIVE	P	P027-00-2/011	Ticket Office - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21125	ACTIVE	P	P027-00-2/011/CLG-01	Ceiling: Solid - 1 - Ticket Office - Station Building - Turnpike Lane Stn		Asbestos	Surveyed – Not Detected				Ceiling & boxing Supalux					
21126	ACTIVE	P	P027-00-2/011/CLG-01	Ceiling: Solid - 1 - Ticket Office - Station Building - Turnpike Lane Stn	Void	Asbestos	Surveyed – Not Detected				Concrete & plasterboard above false ceiling				Yes	
21124	ACTIVE	P	P027-00-2/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Turnpike Lane Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer flooring					Yes
13041	ACTIVE	P	P027-00-2/021	POM - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21129	ACTIVE	P	P027-00-2/021/CLG-01	Ceiling: Solid - 1 - POM - Station Building - Turnpike Lane Stn	Void	Asbestos	Surveyed – Not Detected				Plaster on concrete above supalux ceiling				Yes	
21128	ACTIVE	P	P027-00-2/021/CLG-01	Ceiling: Solid - 1 - POM - Station Building - Turnpike Lane Stn		Asbestos	Surveyed – Not Detected				Supalux					
21127	ACTIVE	P	P027-00-2/021/FLR-01	Floor - 1 - POM - Station Building - Turnpike Lane Stn	Void	Asbestos	Surveyed – Not Detected				Concrete base, supalux panel, fibreglass debris (plastic cable) beneath computer flooring					Yes
13042	ACTIVE	P	P027-00-2/031	Mess Room - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21130	ACTIVE	P	P027-00-2/031/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Turnpike Lane Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				N	N
24048	ACTIVE	P	P027-00-2/031/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Turnpike Lane Stn		Asbestos	Surveyed – Not Detected				Ceiling & boxing Supalux					
13043	ACTIVE	P	P027-00-2/032	Kitchen - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P027-00 - Station Building - Turnpike Lane Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23550	ACTIVE	P	P027-00-2/032/CLG-01	Ceiling: Solid - 1 - Kitchen - Station Building - Turnpike Lane Stn		Asbestos	Surveyed – Not Detected				Supalux					
21131	ACTIVE	P	P027-00-2/032/CLG-01	Ceiling: Solid - 1 - Kitchen - Station Building - Turnpike Lane Stn	Void	Asbestos	Surveyed – Not Detected				Plaster on solid above false ceiling				Yes	
13044	ACTIVE	P	P027-00-2/036	Toilet: Unisex - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21132	ACTIVE	P	P027-00-2/036/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Turnpike Lane Stn		Asbestos	Surveyed – Not Detected				Supalux					
21133	ACTIVE	P	P027-00-2/036/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Turnpike Lane Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				N	N
13045	ACTIVE	P	P027-00-2/091	Circulation Area - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13046	ACTIVE	P	P027-00-2/151	UMC - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43720	ACTIVE	P	P027-00-2/151	UMC - Station Building - Turnpike Lane Stn		Asbestos	Sampled – Not Detected				Gasket 6" x 6" top flange in UMC			R591226	N	N
21134	ACTIVE	P	P027-00-2/151	UMC - Station Building - Turnpike Lane Stn	Rope Gaskets	Asbestos	No Access: Presumed				Gaskets to door and Extraction Fan Unit Gaskets HMT Re-inspection					
43722	ACTIVE	P	P027-00-2/151	UMC - Station Building - Turnpike Lane Stn		Asbestos	Sampled – Not Detected				Gasket 6" x 6" bottom valve in UMC			R591226	N	N
23551	ACTIVE	P	P027-00-2/151	UMC - Station Building - Turnpike Lane Stn	Gasket :Pipework	Asbestos	No Access: Presumed				Gaskets on Down Pipe work and possible lead paint HMT Re-inspection					
43719	ACTIVE	P	P027-00-2/151	UMC - Station Building - Turnpike Lane Stn		Asbestos	Sampled – Not Detected				Gasket 6" x 6" to gate valve in UMC			R591226	N	N
21136	ACTIVE	P	P027-00-2/151	UMC - Station Building - Turnpike Lane Stn	Lead/Leading	Lead Paint/Lead	Known				Equipment surround - Red gloss - 18m ² - Thickness : 0.08mm Analysis : 3.75%		1			
21135	ACTIVE	P	P027-00-2/151/FLR-01	Floor - 1 - UMC - Station Building - Turnpike Lane Stn	Lead/Leading	Lead Paint/Lead	Known				Flooring - Red gloss - 20m ² - Thickness : 0.39mm Analysis : 14.0%		1			
13047	ACTIVE	P	P027-00-2/201	Passage - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13048	ACTIVE	P	P027-00-2/202	Passage - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P027-00 - Station Building - Turnpike Lane Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13049	ACTIVE	P	P027-00-2/203	Passage - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21137	ACTIVE	P	P027-00-2/203	Passage - Station Building - Turnpike Lane Stn	Void	Asbestos	No Access: Presumed				Walls - Tiles, partly hollow wall behind - no access				N	N
23552	ACTIVE	P	P027-00-2/203/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Turnpike Lane Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				N	N
21138	INACTIVE	P	P027-00-2/203/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Turnpike Lane Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
13050	ACTIVE	P	P027-00-2/204	Passage - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21139	ACTIVE	P	P027-00-2/204/FLR-01	Floor - 1 - Passage - Station Building - Turnpike Lane Stn	Void	Asbestos	No Access: Presumed				Beneath manhole				N	Yes
13051	ACTIVE	P	P027-00-2/236	Lobby - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21142	ACTIVE	P	P027-00-2/236/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Turnpike Lane Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	N
21141	ACTIVE	P	P027-00-2/236/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Turnpike Lane Stn		Asbestos	Surveyed – Not Detected				Supalux, metal duct above					
21140	ACTIVE	P	P027-00-2/236/FLR-01	Floor - 1 - Lobby - Station Building - Turnpike Lane Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring				N	Yes
13052	ACTIVE	P	P027-00-2/237	Lobby - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21143	ACTIVE	P	P027-00-2/237/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Turnpike Lane Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	N
23553	ACTIVE	P	P027-00-2/237/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Turnpike Lane Stn		Asbestos	Surveyed – Not Detected				Vermiculite Pipe with Suplax boxing surround Supalux panels					
13053	ACTIVE	P	P027-00-2/238	Lobby - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20932	ACTIVE	P	P027-00-2/238/WAL-004	Wall: Internal - 4 - Lobby - Station Building - Turnpike Lane Stn		Asbestos	Surveyed – Not Detected				Supalux panels					



Hazardous Material Asset Register - Summary



P027-00 - Station Building - Turnpike Lane Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13054	ACTIVE	P	P027-00-2/301	Station Control Room - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20937	ACTIVE	P	P027-00-2/301/CLG-01	Ceiling: Solid - 1 - Station Control Room - Station Building - Turnpike Lane Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
20936	ACTIVE	P	P027-00-2/301/CLG-01	Ceiling: Solid - 1 - Station Control Room - Station Building - Turnpike Lane Stn		Asbestos	Surveyed – Not Detected				Supalux					
20935	ACTIVE	P	P027-00-2/301/CLG-01	Ceiling: Solid - 1 - Station Control Room - Station Building - Turnpike Lane Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
20934	ACTIVE	P	P027-00-2/301/CLG-01	Ceiling: Solid - 1 - Station Control Room - Station Building - Turnpike Lane Stn		Asbestos	Surveyed – Not Detected				Supalux					
20933	ACTIVE	P	P027-00-2/301/FLR-01	Floor - 1 - Station Control Room - Station Building - Turnpike Lane Stn	Void	Asbestos	No Access: Presumed				Beneath Lino & Computer flooring				N	Yes
13055	ACTIVE	P	P027-00-2/311	Office - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13056	ACTIVE	P	P027-00-2/331	Mess Room - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20940	ACTIVE	P	P027-00-2/331	Mess Room - Station Building - Turnpike Lane Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LUL heater - foam backing		1			
20939	ACTIVE	P	P027-00-2/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Turnpike Lane Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	N
20938	ACTIVE	P	P027-00-2/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Turnpike Lane Stn		Asbestos	Surveyed – Not Detected				Supalux					
13057	ACTIVE	P	P027-00-2/416	Toilet: Male - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20942	ACTIVE	P	P027-00-2/416/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Turnpike Lane Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
20943	ACTIVE	P	P027-00-2/416/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Turnpike Lane Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard				Yes	N
20941	ACTIVE	P	P027-00-2/416/FLR-01	Floor - 1 - Toilet - Station Building - Turnpike Lane Stn	Void	Asbestos	No Access: Presumed				Beneath manhole				N	Yes



Hazardous Material Asset Register - Summary



P027-00 - Station Building - Turnpike Lane Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13058	ACTIVE	P	P027-00-2/417	Toilet: Female - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20945	ACTIVE	P	P027-00-2/417/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Turnpike Lane Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard				Yes	N
20944	ACTIVE	P	P027-00-2/417/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Turnpike Lane Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
13059	ACTIVE	P	P027-00-2/451	Store - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13060	ACTIVE	P	P027-00-2/452	Tenancy - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20946	ACTIVE	P	P027-00-2/452	Tenancy - Station Building - Turnpike Lane Stn	No Access	Asbestos	Room: Surveyed – No Known Asbestos				No visible suspect materials at time of HMT Re-inspection				N	N
13061	ACTIVE	P	P027-00-2/601	Stairs: Linear - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20947	ACTIVE	P	P027-00-2/601	Stairs: Linear - Station Building - Turnpike Lane Stn	No Access	Asbestos	Room: Surveyed – No Known Asbestos				No visible suspect materials at time of HMT Re-inspection				N	N
13062	ACTIVE	P	P027-00-2/661	Switch Room - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20949	ACTIVE	P	P027-00-2/661	Switch Room - Station Building - Turnpike Lane Stn	Isolator Switches	Asbestos	Strongly Presumed				2x Switches (Grey) 2 x 60 amps HMT Re-inspection		2			
24020	ACTIVE	P	P027-00-2/661	Switch Room - Station Building - Turnpike Lane Stn	Lead/Leading	Lead Paint/Lead	Known				Cream gloss - 10m² - Thickness : 0.23mm Analysis ; 7.7%					
20948	ACTIVE	P	P027-00-2/661/FLR-01	Floor - 1 - Switch Room - Station Building - Turnpike Lane Stn	Void	Asbestos	No Access: Presumed				Below manhole - concrete & supalux panels, only plastic cable visible - Full access not possible				N	Yes
13063	ACTIVE	P	P027-00-2/662	Switch Room - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20951	ACTIVE	P	P027-00-2/662	Switch Room - Station Building - Turnpike Lane Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding above door					
42702	ACTIVE	P	P027-00-2/662	Switch Room - Station Building - Turnpike Lane Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box Wall 1 Asbestos Components – Presumed within	1			N	N
42705	ACTIVE	P	P027-00-2/662	Switch Room - Station Building - Turnpike Lane Stn	PCBs	Asbestos	Presumed				PCB Fair Condition Wall 3 HMT Re-inspection				N	N



Hazardous Material Asset Register - Summary



P027-00 - Station Building - Turnpike Lane Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42704	ACTIVE	P	P027-00-2/662	Switch Room - Station Building - Turnpike Lane Stn	PCBs	Asbestos	Presumed				Blue PCB up High Wall 1 HMT Re-inspection				N	N
42703	ACTIVE	P	P027-00-2/662	Switch Room - Station Building - Turnpike Lane Stn	Other Electrical Boxes	Asbestos	Presumed				Trunking on Wall 3 Asbestos Components – Presumed within				N	N
20952	ACTIVE	P	P027-00-2/662	Switch Room - Station Building - Turnpike Lane Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				3 x Transformer Boxes Wall 3 Asbestos Components – Strongly Presumed within		3			
24021	ACTIVE	P	P027-00-2/662	Switch Room - Station Building - Turnpike Lane Stn	Isolator Switches	Asbestos	Strongly Presumed				Wall 3 one Switch Box HMT Re-inspection		1		N	N
20950	ACTIVE	P	P027-00-2/662/ FLR-01	Floor - 1 - Switch Room - Station Building - Turnpike Lane Stn	Void	Asbestos	No Access: Presumed				To manholes				N	Yes
13064	ACTIVE	P	P027-00-2/746	SCR - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20953	ACTIVE	P	P027-00-2/746/ FLR-01	Floor - 1 - SCR - Station Building - Turnpike Lane Stn	Void	Asbestos	Surveyed – Not Detected				Inspection cover - wooden slats below					Yes
13065	ACTIVE	P	P027-00-2/771	Pump Room - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20954	ACTIVE	P	P027-00-2/771/ FLR-01	Floor - 1 - Pump Room - Station Building - Turnpike Lane Stn	Void	Asbestos	No Access: Presumed				No access to inspection cover and beneath				N	Yes
13066	ACTIVE	P	P027-00-2/772	Tank Room - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13067	ACTIVE	P	P027-00-2/951	Disused Room - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20957	ACTIVE	P	P027-00-2/951	Disused Room - Station Building - Turnpike Lane Stn		Asbestos	Surveyed – Not Detected				Fire Reel cupboard - supalux panels					
20956	ACTIVE	P	P027-00-2/951	Disused Room - Station Building - Turnpike Lane Stn	Void	Asbestos	No Access: Presumed				Fire Reel cupboard - No access beneath steel floor				N	N
24022	ACTIVE	P	P027-00-2/951/ CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Turnpike Lane Stn	Void	Asbestos	No Access: Presumed				Above Metal Duct				Yes	N
20955	ACTIVE	P	P027-00-2/951/ FLR-01	Floor - 1 - Disused Room - Station Building - Turnpike Lane Stn	Void	Asbestos	No Access: Presumed				Beneath Steel Floor				N	Yes
13068	ACTIVE	P	P027-00-3/081	Circulation Area - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P027-00 - Station Building - Turnpike Lane Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13069	ACTIVE	P	P027-00-3/082	Switch Room - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23901	ACTIVE	P	P027-00-3/082/FLR-01	Floor - 1 - Switch Room - Station Building - Turnpike Lane Stn	Void	Asbestos	No Access: Presumed				Beneath computer flooring				N	Yes
13070	ACTIVE	P	P027-00-3/161	LMC - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20958	ACTIVE	P	P027-00-3/161/FLR-01	Floor - 1 - LMC - Station Building - Turnpike Lane Stn	Void	Asbestos	No Access: Presumed				Beneath Manholes				N	Yes
13071	ACTIVE	P	P027-00-3/201	Passage - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13072	ACTIVE	P	P027-00-3/202	Passage - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13073	ACTIVE	P	P027-00-3/203	Passage - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13074	ACTIVE	P	P027-00-3/204	Passage - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13075	ACTIVE	P	P027-00-3/207	Passage - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13076	ACTIVE	P	P027-00-3/236	Passage - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24023	ACTIVE	P	P027-00-3/236	Passage - Station Building - Turnpike Lane Stn	Lead/Leading	Lead Paint/Lead	Known				Stretcher - Green gloss - 1.5m². Thickness : 0.30mm Analysis : 9.9%		1			
20959	ACTIVE	P	P027-00-3/236/WAL-001	Wall: Internal - 1 - Passage - Station Building - Turnpike Lane Stn	Lead/Leading	Lead Paint/Lead	Known				Cream gloss - 15m². Thickness : 0.32mm Analysis : 6.7%		1			
13077	ACTIVE	P	P027-00-3/261	Platform 1 - Eastbound Local - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20963	ACTIVE	P	P027-00-3/261	Platform 1 - Eastbound Local - Station Building - Turnpike Lane Stn	Cable: Sheath	Asbestos	Surveyed – Not Detected				Tail End - Cables in front of Hanger				N	N
21042	ACTIVE	P	P027-00-3/261	Platform 1 - Eastbound Local - Station Building - Turnpike Lane Stn	Cable: Sheath	Asbestos	Strongly Presumed				Nr 3/714 Eastbound Invert - 7x Cables pit side & trackside along invert ceiling & walls No access to inspect material due to trackside, HMT Re-inspection		7		N	Y



Hazardous Material Asset Register - Summary



P027-00 - Station Building - Turnpike Lane Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
45253	ACTIVE	p	P027-00-3/261	Platform 1 - Eastbound Local - Station Building - Turnpike Lane Stn	Cable: Sheath	Asbestos	Known				Tail End - J Hanger 1 - 1x 60mm Cable to duct 1 No access to inspect material due to trackside, HMT Re-inspection	60	1		N	N
45252	ACTIVE	p	P027-00-3/261	Platform 1 - Eastbound Local - Station Building - Turnpike Lane Stn	Cable: Sheath	Asbestos	Known				J Hangers 2 & 4 - Tail End - Cables in front of Hanger No access to inspect material due to trackside, HMT Re-inspection				N	N
45254	ACTIVE	p	P027-00-3/261	Platform 1 - Eastbound Local - Station Building - Turnpike Lane Stn	Cable: Sheath	Asbestos	Removed				Tail End - J Hanger 2 - Cables in front of Hanger Duplication of 45252				N	N
20961	ACTIVE	p	P027-00-3/261	Platform 1 - Eastbound Local - Station Building - Turnpike Lane Stn	Cable: Sheath	Asbestos	Known				Head Wall - J hanger 2-3 - 3x 25mm Cables, run into duct 1, 2x 25mm Cables run into duct 2- Head wall No access to inspect material due to trackside, HMT Re-inspection		5		N	N
20965	ACTIVE	p	P027-00-3/261	Platform 1 - Eastbound Local - Station Building - Turnpike Lane Stn	Cable: Sheath	Asbestos	Surveyed – Not Detected				Tail End - Cables in front of Hanger				N	N
20964	ACTIVE	p	P027-00-3/261	Platform 1 - Eastbound Local - Station Building - Turnpike Lane Stn	Cable: Sheath	Asbestos	Surveyed – Not Detected				Tail End - J Hanger 1 - 1x 60mm Cable to duct 1		1		N	N
20962	ACTIVE	p	P027-00-3/261	Platform 1 - Eastbound Local - Station Building - Turnpike Lane Stn	Cable: Sheath	Asbestos	Known				Head Wall - 1x 60mm Cable runs behind Hanger - Head wall No access to inspect material due to trackside, HMT Re-inspection		1		N	N
20966	ACTIVE	p	P027-00-3/261	Platform 1 - Eastbound Local - Station Building - Turnpike Lane Stn	Cable: Sheath	Asbestos	Known				Tail End - J hanger 3 - 1x 25mm Cable to duct 3 No access to inspect material due to trackside, HMT Re-inspection		1		N	N
20960	ACTIVE	p	P027-00-3/261	Platform 1 - Eastbound Local - Station Building - Turnpike Lane Stn	Caulking	Asbestos	Strongly Presumed				Platform 1 - Tunnel Ring Caulking (caulking is sealed) Headwall & Tail Ends No access to inspect material due to trackside, HMT Re-inspection				N	N
21043	ACTIVE	p	P027-00-3/261	Platform 1 - Eastbound Local - Station Building - Turnpike Lane Stn	Cable: Sheath	Asbestos	Strongly Presumed				Nr 3/714 Eastbound Invert - 6x Cables - From pit wall to electrical circuits No access to inspect material due to trackside, HMT Re-inspection		6		N	Y
21044	ACTIVE	p	P027-00-3/261	Platform 1 - Eastbound Local - Station Building - Turnpike Lane Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Nr 3/714 Eastbound Invert - 1x Cable sleeves - No access cables in way, 5x Cable sleeves - Filled in, no access No access to inspect material due to trackside, HMT Re-inspection		1		N	Y
23902	ACTIVE	p	P027-00-3/261	Platform 1 - Eastbound Local - Station Building - Turnpike Lane Stn	Lead/Leading	Lead Paint/Lead	Known				Sand Cupboard -White gloss - 1m². Thickness : 0.52mm Analysis : 10.0%		1			



Hazardous Material Asset Register - Summary



P027-00 - Station Building - Turnpike Lane Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13078	ACTIVE	P	P027-00-3/262	Platform 2 - Westbound Local - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20967	ACTIVE	P	P027-00-3/262	Platform 2 - Westbound Local - Station Building - Turnpike Lane Stn	Cable: Sheath	Asbestos	Strongly Presumed				2 x 70m Cables to Signal halfway along platform (white) HMT Re-inspection		2			
23904	ACTIVE	P	P027-00-3/262	Platform 2 - Westbound Local - Station Building - Turnpike Lane Stn	Cable: Sheath	Asbestos	Presumed				Westbound Invert down hatch - 7x cables pit side from ceiling going down pit wall No access to inspect material due to trackside, HMT Re-inspection		7			Y
21040	ACTIVE	P	P027-00-3/262	Platform 2 - Westbound Local - Station Building - Turnpike Lane Stn	Cable: Sheath	Asbestos	Strongly Presumed				Westbound Invert - All Cables nr 3/712 No access to inspect material due to trackside, HMT Re-inspection				N	Y
13079	ACTIVE	P	P027-00-3/281	CER - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20969	ACTIVE	P	P027-00-3/281	CER - Station Building - Turnpike Lane Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x Iron Clad Isolators, 2 x 60 amps HMT Re-inspection		2			
20968	ACTIVE	P	P027-00-3/281	CER - Station Building - Turnpike Lane Stn	Other Boarding	Asbestos	Strongly Presumed				Paxoline Board HMT Re-inspection					
13080	ACTIVE	P	P027-00-3/376	Switch Room - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20970	ACTIVE	P	P027-00-3/376	Switch Room - Station Building - Turnpike Lane Stn		Asbestos	Surveyed – Not Detected				Supalux panel to rear wall right hand side of room - Supalux door					
13081	ACTIVE	P	P027-00-3/381	Store - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20972	ACTIVE	P	P027-00-3/381	Store - Station Building - Turnpike Lane Stn	Void	Asbestos	No Access: Presumed				Walls - Tunnel rings, no access to caulking - Encapsulated HMT Re-inspection				N	N
20971	ACTIVE	P	P027-00-3/381/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Turnpike Lane Stn	Caulking	Asbestos	No Access: Presumed				Tunnel rings, no access to caulking - Encapsulated HMT Re-inspection				N	N
13082	ACTIVE	P	P027-00-3/411	Store - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20974	ACTIVE	P	P027-00-3/411	Store - Station Building - Turnpike Lane Stn		Asbestos	Surveyed – Not Detected				Panel above door - Supalux					
20973	ACTIVE	P	P027-00-3/411/FLR-01	Floor - 1 - Store - Station Building - Turnpike Lane Stn	Void	Asbestos	No Access: Presumed				Beneath Manhole to Cable Ducts					Yes



Hazardous Material Asset Register - Summary



P027-00 - Station Building - Turnpike Lane Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24024	ACTIVE	P	P027-00-3/411/WAL-003	Wall: Internal - 3 - Store - Station Building - Turnpike Lane Stn	Lead/Leading	Lead Paint/Lead	Known				Cream gloss - 7m² - Thickness : 1.70mm Analysis : 5.2% Walls have been over painted		1			
20975	ACTIVE	P	P027-00-3/411/WAL-003	Wall: Internal - 3 - Store - Station Building - Turnpike Lane Stn	Lead/Leading	Lead Paint/Lead	Known				Blue gloss - 2m² - Thickness : 0.17mm Analysis : 10%. Walls have been over painted		1			
13083	ACTIVE	P	P027-00-3/661	Switch Room - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24045	ACTIVE	P	P027-00-3/661	Switch Room - Station Building - Turnpike Lane Stn	Isolator Switches	Asbestos	Strongly Presumed				4x Iron clad isolators 3 x 60 amps, 1 x 100 amps Asbestos components within HMT Re-inspection		4			
20976	ACTIVE	P	P027-00-3/661	Switch Room - Station Building - Turnpike Lane Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Panel above door - Supalux		1			
13084	ACTIVE	P	P027-00-3/662	Switch Room - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20978	ACTIVE	P	P027-00-3/662	Switch Room - Station Building - Turnpike Lane Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box Asbestos Components – Presumed within		1			
20979	ACTIVE	P	P027-00-3/662	Switch Room - Station Building - Turnpike Lane Stn	Isolator Switches	Asbestos	Strongly Presumed				6 x Iron clad isolators 3 x 100 amps, 3 x 60 amps HMT Re-inspection		6			
20980	ACTIVE	P	P027-00-3/662	Switch Room - Station Building - Turnpike Lane Stn	Lead/Leading	Lead Paint/Lead	Known				Cream gloss - 10m². Thickness : 0.32mm Analysis : 6.7%		1			
20977	ACTIVE	P	P027-00-3/662/FLR-01	Floor - 1 - Switch Room - Station Building - Turnpike Lane Stn		Asbestos	Surveyed – Not Detected				Panel above door - Supalux					
13085	ACTIVE	P	P027-00-3/663	Switch Room - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13086	ACTIVE	P	P027-00-3/711	Relay Room - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20983	ACTIVE	P	P027-00-3/711	Relay Room - Station Building - Turnpike Lane Stn	Cable: Sheath	Asbestos	Strongly Presumed				2x4m yellow Cables, 3x 1.5m Green Cables HMT Re-inspection		2			
20984	ACTIVE	P	P027-00-3/711	Relay Room - Station Building - Turnpike Lane Stn	Lead/Leading	Lead Paint/Lead	Known				All walls - Cream gloss - 15m² - Thickness : 1.70mm Analysis : 5.2%					
20981	ACTIVE	P	P027-00-3/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Turnpike Lane Stn	Other Boarding	Asbestos	Strongly Presumed				Paxoline Board HMT Re-inspection		1			



Hazardous Material Asset Register - Summary



P027-00 - Station Building - Turnpike Lane Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42918	ACTIVE	P	P027-00-3/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Turnpike Lane Stn	PCBs	Asbestos	Not Found during Inspection				Blue PCB up High Wall 1 - Fair Condition Item not found during 2020 re-inspection. Possibly removed.					
20982	ACTIVE	P	P027-00-3/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Turnpike Lane Stn	Other Boarding	Asbestos	Strongly Presumed				Paxoline Board HMT Re-inspection		1			
24025	ACTIVE	P	P027-00-3/711/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Turnpike Lane Stn	No Access	Asbestos	No Access: Presumed				Behind Metal sheet		1		N	N
13087	ACTIVE	P	P027-00-3/712	Relay Room - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20986	ACTIVE	P	P027-00-3/712	Relay Room - Station Building - Turnpike Lane Stn	Cable: Sheath	Asbestos	Strongly Presumed				5x Cables - (1x 6cmØ Green Cable -600v1x 1cm Ø White Cable & 1x 3cm Ø Green Cable 2x 1.5m Cables -1 Green 1 Yellow) HMT Re-inspection		5			
24026	ACTIVE	P	P027-00-3/712	Relay Room - Station Building - Turnpike Lane Stn	Cable Duct: Other	Asbestos	No Access: Presumed				Cable ducts in walls HMT Re-inspection		1			
20987	ACTIVE	P	P027-00-3/712	Relay Room - Station Building - Turnpike Lane Stn	Lead/Leading	Lead Paint/Lead	Known				All walls - Cream gloss - 15m² - Thickness : 1.70mm Analysis : 5.2%		1			
20985	ACTIVE	P	P027-00-3/712/FLR-01	Floor - 1 - Relay Room - Station Building - Turnpike Lane Stn	Cable Duct: Other	Asbestos	No Access: Presumed				Floor cable ducts HMT Re-inspection		1			
13088	ACTIVE	P	P027-00-3/713	Relay Room - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21038	ACTIVE	P	P027-00-3/713	Relay Room - Station Building - Turnpike Lane Stn	Cable: Sheath	Asbestos	Strongly Presumed				14x Cables (2x 3m Cables from box to platform signal, 2x 1.5m Cables from box to wall signal, 1x 4m Cable to tunnel telephone box to wall, 2x 3m Cables, 7x 1.5m Cables to invert/headwall) HMT Re-inspection		14			
21041	ACTIVE	P	P027-00-3/713	Relay Room - Station Building - Turnpike Lane Stn	Caulking	Asbestos	Surveyed – Not Detected				Westbound Invert down hatch - caulking platform side - Non asbestos		1			
21039	ACTIVE	P	P027-00-3/713	Relay Room - Station Building - Turnpike Lane Stn	Caulking	Asbestos	Surveyed – Not Detected				Caulking platform side nr 3/712 - Non asbestos					
20988	ACTIVE	P	P027-00-3/713/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Turnpike Lane Stn	Other Boarding	Asbestos	Strongly Presumed				Paxoline Board HMT Re-inspection		1			
21037	ACTIVE	P	P027-00-3/713/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Turnpike Lane Stn	Other Boarding	Asbestos	Strongly Presumed				Paxoline Board HMT Re-inspection		1			



Hazardous Material Asset Register - Summary



P027-00 - Station Building - Turnpike Lane Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13089	ACTIVE	P	P027-00-3/714	Relay Room - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21046	ACTIVE	P	P027-00-3/714	Relay Room - Station Building - Turnpike Lane Stn	Cable: Sheath	Asbestos	Strongly Presumed				2x 0.5m Green Cables 600v HMT Re-inspection		2			
21048	ACTIVE	P	P027-00-3/714	Relay Room - Station Building - Turnpike Lane Stn	Cable: Sheath	Asbestos	Strongly Presumed				3x 1.5m Green cables HMT Re-inspection		3			
21047	ACTIVE	P	P027-00-3/714	Relay Room - Station Building - Turnpike Lane Stn	Cable: Sheath	Asbestos	Strongly Presumed				2x 2m Cables -1 green, 1yellow HMT Re-inspection		2			
42917	ACTIVE	P	P027-00-3/714/ WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Turnpike Lane Stn	PCBs	Asbestos	Strongly Presumed				PCB Fair Condition wall 3 HMT Re-inspection					
21049	ACTIVE	P	P027-00-3/714/ WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Turnpike Lane Stn	Lead/Leading	Lead Paint/Lead	Known				Cream gloss - 10m ² - 1.7mm Analysis : 5.2%		1			
21045	ACTIVE	P	P027-00-3/714/ WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Turnpike Lane Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Solid plaster above metal		1			
13090	ACTIVE	P	P027-00-3/731	CER - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21050	ACTIVE	P	P027-00-3/731	CER - Station Building - Turnpike Lane Stn		Asbestos	Surveyed – Not Detected				Panel to blocked off window - Supalux		1			
21051	ACTIVE	P	P027-00-3/731	CER - Station Building - Turnpike Lane Stn	Lead/Leading	Lead Paint/Lead	Known				Green gloss - 8m ² - Thickness : 0.32mm Analysis : 9.9%		1			
21052	ACTIVE	P	P027-00-3/731	CER - Station Building - Turnpike Lane Stn	Lead/Leading	Lead Paint/Lead	Known				Blue gloss - 8m ² - Thickness : 0.30mm Analysis : 10%		1			
13091	ACTIVE	P	P027-00-3/732	CER - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21053	ACTIVE	P	P027-00-3/732	CER - Station Building - Turnpike Lane Stn	Isolator Switches	Asbestos	Strongly Presumed				Iron Clad Isolators 2 x 60 amps HMT Re-inspection		2		N	N
23542	ACTIVE	P	P027-00-3/732/ FLR-01	Floor - 1 - CER - Station Building - Turnpike Lane Stn	Void	Asbestos	Surveyed – Not Detected				Computer Flooring beneath concrete, steel ducts, plastic cables		1			Yes
13092	ACTIVE	P	P027-00-3/761	Computer Equipment Cupboard - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21054	ACTIVE	P	P027-00-3/761	Computer Equipment Cupboard - Station Building - Turnpike Lane Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed. Non Visible - New Electrical Cabinets					
13093	ACTIVE	P	P027-00-3/762	Computer Equipment Cupboard - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P027-00 - Station Building - Turnpike Lane Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21055	ACTIVE	p	P027-00-3/762	Computer Equipment Cupboard - Station Building - Turnpike Lane Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed. Non Visible - New Electrical Cabinets					
13094	ACTIVE	p	P027-00-3/763	Computer Equipment Cupboard - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21056	ACTIVE	p	P027-00-3/763	Computer Equipment Cupboard - Station Building - Turnpike Lane Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed. Non Visible - New Electrical Cabinets					
13095	ACTIVE	p	P027-00-3/764	Computer Equipment Cupboard - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24047	ACTIVE	p	P027-00-3/764	Computer Equipment Cupboard - Station Building - Turnpike Lane Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed. Non Visible - New Electrical Cabinets					
13096	ACTIVE	p	P027-00-3/765	Computer Equipment Cupboard - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23543	ACTIVE	p	P027-00-3/765	Computer Equipment Cupboard - Station Building - Turnpike Lane Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed. Non Visible - New Electrical Cabinets					
13097	ACTIVE	p	P027-00-3/766	Computer Equipment Cupboard - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21057	ACTIVE	p	P027-00-3/766	Computer Equipment Cupboard - Station Building - Turnpike Lane Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed. Non Visible - New Electrical Cabinets					
13098	ACTIVE	p	P027-00-3/786	Service Riser - Station Building - Turnpike Lane Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21058	ACTIVE	p	P027-00-3/791	Vent Shaft - Station Building - Turnpike Lane Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel ring caulking encapsulated		1			

P029-00 - Station Building - Manor House Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13101	ACTIVE	p	P029-00-1/401	Bin Store - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13102	ACTIVE	p	P029-00-1/601	Stairs: Linear - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23544	ACTIVE	p	P029-00-1/601	Stairs: Linear - Station Building - Manor House Stn	Lead/Leading	Lead Paint/Lead	Known				Top railing - Light blue on green, grey - 2x1m ² Thickness : 0.67mm Analysis : 4.5% - Poor Condition					



Hazardous Material Asset Register - Summary



P029-00 - Station Building - Manor House Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21060	ACTIVE	P	P029-00-1/601/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Manor House Stn	Void	Asbestos	No Access: Presumed				Above Metal sheets - bottom of stairs on ceiling		1			
13103	ACTIVE	P	P029-00-1/602	Stairs: Linear - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21061	ACTIVE	P	P029-00-1/602	Stairs: Linear - Station Building - Manor House Stn	Lead/Leading	Lead Paint/Lead	Known				Top railing - Light blue on green, grey - 2x1m ² Thickness : 0.67mm Analysis : 4.5% - Poor Condition					
13104	ACTIVE	P	P029-00-1/603	Stairs: Linear - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21062	ACTIVE	P	P029-00-1/603	Stairs: Linear - Station Building - Manor House Stn	Lead/Leading	Lead Paint/Lead	Known				Top railing - Light blue on green, grey - 2x1m ² Thickness : 0.67mm Analysis : 4.5% - Poor Condition					
13105	ACTIVE	P	P029-00-1/604	Stairs: Linear - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21063	ACTIVE	P	P029-00-1/604	Stairs: Linear - Station Building - Manor House Stn	Lead/Leading	Lead Paint/Lead	Known				Top railing - Light blue on green, grey - 2x1m ² Thickness : 0.67mm Analysis : 4.5% - Poor Condition					
21065	ACTIVE	P	P029-00-1/604/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Manor House Stn	Void	Asbestos	No Access: Presumed				Above Supalux panels					
21064	ACTIVE	P	P029-00-1/604/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Manor House Stn		Asbestos	Surveyed – Not Detected				Supalux panels		1			
13106	ACTIVE	P	P029-00-1/605	Stairs: Linear - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21066	ACTIVE	P	P029-00-1/605	Stairs: Linear - Station Building - Manor House Stn	Lead/Leading	Lead Paint/Lead	Known				Top railing - Light blue on green, grey - 2x1m ² Thickness : 0.67mm Analysis : 4.5% - Poor Condition					
13107	ACTIVE	P	P029-00-1/606	Stairs: Linear - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21067	ACTIVE	P	P029-00-1/606	Stairs: Linear - Station Building - Manor House Stn	Lead/Leading	Lead Paint/Lead	Known				Top railing - Light blue on green, grey - 2x1m ² Thickness : 0.67mm Analysis : 4.5% - Poor Condition					
13108	ACTIVE	P	P029-00-1/607	Stairs: Linear - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13109	ACTIVE	P	P029-00-2/001	Booking Hall - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
69735	ACTIVE	P	P029-00-2/001	Booking Hall - Station Building - Manor House Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux to wall going into panels	1		R679617		



Hazardous Material Asset Register - Summary



P029-00 - Station Building - Manor House Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
69734	ACTIVE	P	P029-00-2/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Manor House Stn	Void	Asbestos	Surveyed – Not Detected				No identified ACMs above false ceiling			R679617	Y	
21069	ACTIVE	P	P029-00-2/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Manor House Stn	Void	Asbestos	No Access: Presumed				Above Fibreglass / Plaster					
21068	ACTIVE	P	P029-00-2/001/FLR-01	Floor - 1 - Booking Hall - Station Building - Manor House Stn	Void	Asbestos	No Access: Presumed				Beneath hatches					
13110	ACTIVE	P	P029-00-2/011	Ticket Office - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21072	ACTIVE	P	P029-00-2/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Manor House Stn	Void	Asbestos	Surveyed – Not Detected				Metal conduits, plastic & rubber cables, concrete above Supalux tiles		3		Yes	
21071	ACTIVE	P	P029-00-2/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Manor House Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles		1			
21070	ACTIVE	P	P029-00-2/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Manor House Stn	Void	Asbestos	Surveyed – Not Detected				Concrete & debris beneath computer tiles		2			Yes
13111	ACTIVE	P	P029-00-2/021	POM - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42861	ACTIVE	P	P029-00-2/021	POM - Station Building - Manor House Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux panels/boards, 6m (1), under machine within floor void in POM Room 2/021	6	1	R519101	N	N
13112	ACTIVE	P	P029-00-2/031	Mess Room - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21074	ACTIVE	P	P029-00-2/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Manor House Stn	Void	Asbestos	Surveyed – Not Detected				Solid, breeze block walls, ducting & conduits above Supalux tiles		3		Yes	
21073	ACTIVE	P	P029-00-2/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Manor House Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles		1			
13113	ACTIVE	P	P029-00-2/036	Lobby - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46798	ACTIVE	P	P029-00-2/036/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Manor House Stn	Void	Asbestos	No Access: Presumed				No Access above Supalux Ceiling Tiles					
13114	ACTIVE	P	P029-00-2/037	Toilet: Unisex - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P029-00 - Station Building - Manor House Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21076	ACTIVE	P	P029-00-2/037/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Manor House Stn	Void	Asbestos	Surveyed – Not Detected				Concrete ceiling above Supalux tiles		1		Yes	
21075	ACTIVE	P	P029-00-2/037/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Manor House Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles		1			
13115	ACTIVE	P	P029-00-2/047	Kitchen - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21078	ACTIVE	P	P029-00-2/047/CLG-01	Ceiling: Suspended - 1 - Kitchen - Station Building - Manor House Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles		1			
21079	ACTIVE	P	P029-00-2/047/CLG-01	Ceiling: Suspended - 1 - Kitchen - Station Building - Manor House Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, metal above supalux tiles				Yes	
21077	ACTIVE	P	P029-00-2/047/FLR-01	Floor - 1 - Kitchen - Station Building - Manor House Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles		1			Yes
13116	ACTIVE	P	P029-00-2/071	Circulation Area - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21081	ACTIVE	P	P029-00-2/071	Circulation Area - Station Building - Manor House Stn	Void	Asbestos	No Access: Presumed				Pillars - Wooden clad - no access					
69733	ACTIVE	P	P029-00-2/071	Circulation Area - Station Building - Manor House Stn	Other Boarding	Asbestos	Sampled – Not Detected				Panel and strip running throughout under metal panel to wall	10		R679617		
21080	ACTIVE	P	P029-00-2/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Manor House Stn	Void	Asbestos	No Access: Presumed				Above Fibreglass / Plaster					
69732	ACTIVE	P	P029-00-2/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Manor House Stn	Void	Asbestos	Surveyed – Not Detected				No identified ACMs above false ceiling			R679617	Y	
13117	ACTIVE	P	P029-00-2/081	Lobby - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13118	ACTIVE	P	P029-00-2/151	UMC - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23546	ACTIVE	P	P029-00-2/151	UMC - Station Building - Manor House Stn	Lead/Leading	Lead Paint/Lead	Known				Beams x 8 - floor to ceiling also on beam vents on ceiling - grey matt - 40m². Thickness : 0.22mm Analysis : 4.7%. All beams have been over painted in yellow		8			
21091	ACTIVE	P	P029-00-2/151	UMC - Station Building - Manor House Stn	Lead/Leading	Lead Paint/Lead	Known				Hand rails for LMC - Grey matt. Thickness : 0.22mm Analysis : 4.7%					



Hazardous Material Asset Register - Summary



P029-00 - Station Building - Manor House Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21090	ACTIVE	P	P029-00-2/151	UMC - Station Building - Manor House Stn	Lead/Leading	Lead Paint/Lead	Known				Motor of escalator 1,2&3 - Red matt - 20m ² . Thickness : 0.63mm Analysis : 3.3%. All beams have been over painted in yellow					
21089	ACTIVE	P	P029-00-2/151	UMC - Station Building - Manor House Stn	Lead/Leading	Lead Paint/Lead	Known				Along all walls pipe metal - red matt - 80m long. Thickness : too thin Analysis : 3.9%. All beams have been over painted in yellow					
21082	ACTIVE	P	P029-00-2/151	UMC - Station Building - Manor House Stn	Lead/Leading	Lead Paint/Lead	Known				Metal pipe - 6m long. Thickness : too thin Analysis : 3.9%		1			
23905	ACTIVE	P	P029-00-2/151	UMC - Station Building - Manor House Stn	Lead/Leading	Lead Paint/Lead	Known				Escalator 3 white surround, lower beams - white matt - 3m ² . Thickness : 0.18mm Analysis : 2.5%. All beams have been over painted in yellow					
21087	ACTIVE	P	P029-00-2/151/CLG-01	Ceiling: Solid - 1 - UMC - Station Building - Manor House Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Downstairs UMC - 2x Cable sleeves filled in on ceiling		2			
21086	ACTIVE	P	P029-00-2/151/WAL-001	Wall: Internal - 1 - UMC - Station Building - Manor House Stn	Isolator Switches	Asbestos	Removed				Downstairs UMC - Red 1x Fuse switch Removed as Per ES7311, not found at last inspection		1			
21088	ACTIVE	P	P029-00-2/151/WAL-007	Wall: Internal - 7 - UMC - Station Building - Manor House Stn	Rope Gaskets	Asbestos	Strongly Presumed				Gaskets on vent system					
23545	ACTIVE	P	P029-00-2/151/WAL-011	Wall: Internal - 11 - UMC - Station Building - Manor House Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel panel on storage bin		1			
21085	ACTIVE	P	P029-00-2/151/WAL-011	Wall: Internal - 11 - UMC - Station Building - Manor House Stn		Asbestos	Surveyed – Not Detected				Downstairs UMC - Supalux panel by wall 11 - no access behind					
53828	ACTIVE	P	P029-00-2/171	Escalator Incline - Station Building - Manor House Stn		Asbestos	No Access: Presumed				The area behind the cladding on the passenger side and the incline on the non passenger side has not been surveyed.					
13119	ACTIVE	P	P029-00-2/201	Passage - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20990	ACTIVE	P	P029-00-2/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Manor House Stn	Void	Asbestos	No Access: Presumed				Above Fibreglass/plaster ceiling					
20989	ACTIVE	P	P029-00-2/201/FLR-01	Floor - 1 - Passage - Station Building - Manor House Stn	No Access	Asbestos	No Access: Presumed				No information available					
13120	ACTIVE	P	P029-00-2/202	Passage - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
69729	ACTIVE	P	P029-00-2/202/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Manor House Stn	Void	Asbestos	Surveyed – Not Detected				No identified ACMs above false ceiling			R679617	Y	



Hazardous Material Asset Register - Summary



P029-00 - Station Building - Manor House Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20992	INACTIVE	P	P029-00-2/202/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Manor House Stn	Void	Asbestos	No Access: Presumed				Above Fibreglass hatch cover					
20991	ACTIVE	P	P029-00-2/202/FLR-01	Floor - 1 - Passage - Station Building - Manor House Stn	Void	Asbestos	No Access: Presumed				No access to hatch					
13121	ACTIVE	P	P029-00-2/203	Passage - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
69728	ACTIVE	P	P029-00-2/203/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Manor House Stn	Void	Asbestos	Surveyed – Not Detected				No identified ACMs above false ceiling			R679617	Y	
13122	ACTIVE	P	P029-00-2/204	Passage - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
69727	ACTIVE	P	P029-00-2/204/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Manor House Stn	Void	Asbestos	Surveyed – Not Detected				No identified ACMs above false ceiling			R679617	Y	
20994	INACTIVE	P	P029-00-2/204/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Manor House Stn	Void	Asbestos	No Access: Presumed				Above Fibreglass / Plaster		1		Yes	
20993	ACTIVE	P	P029-00-2/204/FLR-01	Floor - 1 - Passage - Station Building - Manor House Stn	Void	Asbestos	No Access: Presumed				No access to hatch					Yes
13123	ACTIVE	P	P029-00-2/205	Passage - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20995	ACTIVE	P	P029-00-2/205/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Manor House Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles		1			
20996	INACTIVE	P	P029-00-2/205/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Manor House Stn	Void	Asbestos	No Access: Presumed				Above Supalux tiles		1		Yes	
69726	ACTIVE	P	P029-00-2/205/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Manor House Stn	Void	Asbestos	Surveyed – Not Detected				No identified ACMs above false ceiling			R679617	Y	
13124	ACTIVE	P	P029-00-2/206	Passage - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20998	ACTIVE	P	P029-00-2/206	Passage - Station Building - Manor House Stn	No Access	Asbestos	No Access: Presumed				Hatch near stairs 1/307 - No access below					
20997	INACTIVE	P	P029-00-2/206/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Manor House Stn	Void	Asbestos	No Access: Presumed				Above corrugated plastic				Yes	



Hazardous Material Asset Register - Summary



P029-00 - Station Building - Manor House Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
69725	ACTIVE	P	P029-00-2/206/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Manor House Stn	Void	Asbestos	Surveyed – Not Detected				No identified ACMs above false ceiling			R679617	Y	
13125	ACTIVE	P	P029-00-2/207	Passage - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21000	ACTIVE	P	P029-00-2/207/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Manor House Stn	Void	Asbestos	No Access: Presumed				Above Fibreglass / Plaster				Yes	
69731	ACTIVE	P	P029-00-2/207/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Manor House Stn	Void	Asbestos	Surveyed – Not Detected				No identified ACMs above false ceiling			R679617	Y	
20999	ACTIVE	P	P029-00-2/207/FLR-01	Floor - 1 - Passage - Station Building - Manor House Stn	Void	Asbestos	No Access: Presumed				No access to hatch					Yes
13126	ACTIVE	P	P029-00-2/236	Lobby - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21001	ACTIVE	P	P029-00-2/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Manor House Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
21002	ACTIVE	P	P029-00-2/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Manor House Stn	Void	Asbestos	Surveyed – Not Detected				Solid, breeze block walls, venting above Supalux tiles				Yes	
24046	ACTIVE	P	P029-00-2/236/FLR-01	Floor - 1 - Lobby - Station Building - Manor House Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
13127	ACTIVE	P	P029-00-2/237	Lobby - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21004	ACTIVE	P	P029-00-2/237/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Manor House Stn	Void	Asbestos	Surveyed – Not Detected				Ducts, conduits & metal beams above Supalux tiles				Yes	
21003	ACTIVE	P	P029-00-2/237/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Manor House Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
13128	ACTIVE	P	P029-00-2/301	Station Control Room - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
69730	ACTIVE	P	P029-00-2/301/CLG-01	Ceiling: Suspended - 1 - Station Control Room - Station Building - Manor House Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux panels to ceiling			R679617	N	
13129	ACTIVE	P	P029-00-2/331	Mess Room - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P029-00 - Station Building - Manor House Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21007	ACTIVE	P	P029-00-2/331	Mess Room - Station Building - Manor House Stn		Asbestos	Surveyed – Not Detected				Supalux panel above wooden door frame					
21006	ACTIVE	P	P029-00-2/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Manor House Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, wall 4 - vermiculite lagging, vents & ducts, metal beam structure above false ceiling				Yes	
23537	ACTIVE	P	P029-00-2/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Manor House Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
21008	ACTIVE	P	P029-00-2/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Manor House Stn	Lead/Leading	Lead Paint/Lead	Known				Ceiling beams above false ceiling - Grey / brown matt - 15m². Thickness : 0.32mm Analysis : 59%					
21005	ACTIVE	P	P029-00-2/331/FLR-01	Floor - 1 - Mess Room - Station Building - Manor House Stn	Void	Asbestos	No Access: Presumed				Beneath hatches					Yes
13130	ACTIVE	P	P029-00-2/406	Store - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13131	ACTIVE	P	P029-00-2/411	Store - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21009	ACTIVE	P	P029-00-2/411/FLR-01	Floor - 1 - Store - Station Building - Manor House Stn	Void	Asbestos	No Access: Presumed				No access beneath vinyl tiles on wood					Yes
23538	ACTIVE	P	P029-00-2/411/WAL-002	Wall: Internal - 2 - Store - Station Building - Manor House Stn		Asbestos	Surveyed – Not Detected				No access behind 2 x supalux panels					
13132	ACTIVE	P	P029-00-2/412	Store - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21010	ACTIVE	P	P029-00-2/412/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Manor House Stn	Void	Asbestos	No Access: Presumed				Above concrete, metal, plasterboard ceiling				Yes	
21011	ACTIVE	P	P029-00-2/412/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Manor House Stn	Lead/Leading	Lead Paint/Lead	Known				Ceiling beams - Grey / brown matt - 2m². Thickness : 0.32mm Analysis : 59%					
13133	ACTIVE	P	P029-00-2/416	Lobby - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21014	ACTIVE	P	P029-00-2/416/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Manor House Stn	Void	Asbestos	Surveyed – Not Detected				Ducting, conduits , vermiculite lagging above supalux tiles				Yes	
21013	ACTIVE	P	P029-00-2/416/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Manor House Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
21012	ACTIVE	P	P029-00-2/416/FLR-01	Floor - 1 - Lobby - Station Building - Manor House Stn	Void	Asbestos	No Access: Presumed				No access to Hatch					Yes



Hazardous Material Asset Register - Summary



P029-00 - Station Building - Manor House Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13134	ACTIVE	P	P029-00-2/417	Toilet: Female - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13135	ACTIVE	P	P029-00-2/418	Toilet: Male - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21015	ACTIVE	P	P029-00-2/418/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Manor House Stn	Void	Asbestos	Surveyed – Not Detected				Ducting, conduits , vermiculite lagging above supalux tiles				Yes	
23539	ACTIVE	P	P029-00-2/418/FLR-01	Floor - 1 - Toilet - Station Building - Manor House Stn	Void	Asbestos	No Access: Presumed				No access to Hatch					Yes
13136	ACTIVE	P	P029-00-2/451	Tenancy - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13137	ACTIVE	P	P029-00-2/661	Switch Room - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21016	ACTIVE	P	P029-00-2/661	Switch Room - Station Building - Manor House Stn	Isolator Switches	Asbestos	Strongly Presumed				8x Iron Clad isolators - Walls 4&5. 1 x 100 amps, 6 x 100 amps, 1 x 30 amps. Type 2 report ES11-199 has sampled SOME of the rope gaskets within the switch/fuses and N.A.D.I.S however flashguards contained Chrysotile No access into UMC during 2024 re-inspection. permit with L&E required.		8			
21017	ACTIVE	P	P029-00-2/661/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Manor House Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Trunking - SP Asbestos Components within Asbestos Components – Strongly Presumed within					
13138	ACTIVE	P	P029-00-2/662	Switch Room - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42724	ACTIVE	P	P029-00-2/662	Switch Room - Station Building - Manor House Stn	Other Electrical Boxes	Asbestos	Presumed				3x transformer boxes W4 Asbestos Components – Presumed within		3			
21024	ACTIVE	P	P029-00-2/662/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Manor House Stn	Lead/Leading	Lead Paint/Lead	Known				Metal work on ceiling - red matt - 4m². Thickness : 0.63mm Analysis : 3.3%					
21023	ACTIVE	P	P029-00-2/662/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Manor House Stn	Lead/Leading	Lead Paint/Lead	Known				Ceiling beams - Grey matt - 2.5m long. Thickness : 0.32mm Analysis : 59%					



Hazardous Material Asset Register - Summary



P029-00 - Station Building - Manor House Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21019	ACTIVE	P	P029-00-2/662/WAL-002 80872011	Wall: Internal - 2 - Switch Room - Station Building - Manor House Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				8 x Iron Clad Isolators. Type 2 report ES11-199 has sampled SOME of the rope gaskets within the switch/fuses and no asbestos detected in samples. However flashguards contained Chrysotile w3 5x60amp 1x200 amp 1x100amp No access into UMC during 2024 re-inspection. permit with L&E required.		8			
21021	ACTIVE	P	P029-00-2/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Manor House Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				2 x Trunking - SP Asbestos Components within Asbestos Components – Strongly Presumed within		2			
21018	ACTIVE	P	P029-00-2/662/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Manor House Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				High level - Supalux panel with rubber cables					
21022	ACTIVE	P	P029-00-2/662/WAL-003 80872012	Wall: Internal - 3 - Switch Room - Station Building - Manor House Stn Wall: Internal	Cable Duct: Other	Asbestos	Strongly Presumed				3x Cable sleeves on floor by wall 3 no access filled in Cable sleeves not visible beneath filling therefore not scored during 2024 reinspection.		3			
21020	ACTIVE	P	P029-00-2/662/WAL-004 80872013	Wall: Internal - 4 - Switch Room - Station Building - Manor House Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				1 x Iron Clad Isolators. Type 2 report ES11-199 has sampled SOME of the rope gaskets within the switch/fuses and no asbestos detected in samples. However flashguards contained Chrysotile update record 1x30amp switch boxes No access into UMC during 2024 re-inspection. permit with L&E required.		1			
13139	ACTIVE	P	P029-00-2/663	Switch Cupboard - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13140	ACTIVE	P	P029-00-2/731	CER - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23903	ACTIVE	P	P029-00-2/731	CER - Station Building - Manor House Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x Iron Clad isolators W2 2x 60 amp No electrician on site during 2024 reinspection to open boxes for inspection - therefore cannot score material within		2			
21026	ACTIVE	P	P029-00-2/731/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Manor House Stn	Void	Asbestos	No Access: Presumed				Above corrugated metal				Yes	
21025	ACTIVE	P	P029-00-2/731/FLR-01	Floor - 1 - CER - Station Building - Manor House Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath Computer flooring					Yes
13141	ACTIVE	P	P029-00-2/746	SCR - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P029-00 - Station Building - Manor House Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13142	ACTIVE	P	P029-00-2/761	Equipment Room - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21028	ACTIVE	P	P029-00-2/761	Equipment Room - Station Building - Manor House Stn	Lead/Leading	Lead Paint/Lead	Known				Valve handle - black matt - 4m². Thickness : 0.17mm Analysis : 3.1%					
21027	ACTIVE	P	P029-00-2/761/DOR-01	Door - 1 - Equipment Room - Station Building - Manor House Stn	Boarding: Cement	Asbestos	Known				3 x Cement boarding on back of door Moderate damage to upper panel. Other panels have slight damage. No changes observed during 2024 reinspection		3			
13143	ACTIVE	P	P029-00-2/901	SVC - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21031	ACTIVE	P	P029-00-2/901/CLG-01	Ceiling: Suspended - 1 - SVC - Station Building - Manor House Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
23540	ACTIVE	P	P029-00-2/901/CLG-01	Ceiling: Suspended - 1 - SVC - Station Building - Manor House Stn		Asbestos	Surveyed – Not Detected				Supalux Suplax boxing					
21029	ACTIVE	P	P029-00-2/901/FLR-01	Floor - 1 - SVC - Station Building - Manor House Stn	Void	Asbestos	No Access: Presumed				Beneath Hatch					Yes
21030	ACTIVE	P	P029-00-2/901/WAL-002	Wall: Internal - 2 - SVC - Station Building - Manor House Stn		Asbestos	Surveyed – Not Detected				Supalux panel no access behind					
13144	ACTIVE	P	P029-00-2/902	Station Control Room - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13145	ACTIVE	P	P029-00-2/951	Disused Room - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21032	ACTIVE	P	P029-00-2/951	Disused Room - Station Building - Manor House Stn	Boarding: Cement	Asbestos	Presumed				Cement Board forming boxing. Identified during 2024 HMT Re-inspection.	4				
13146	ACTIVE	P	P029-00-3/081	Circulation Area - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21033	ACTIVE	P	P029-00-3/081/FLR-01	Floor - 1 - Circulation Area - Station Building - Manor House Stn	Void	Asbestos	No Access: Presumed				Beneath - Hatch by wall 1 - to LMC Floor plates at bottom escalator - Metal visible from LMC					Yes
21034	ACTIVE	P	P029-00-3/081/WAL-002	Wall: Internal - 2 - Circulation Area - Station Building - Manor House Stn		Asbestos	Surveyed – Not Detected				Top level above 3/236 - supalux panel behind A/C unit					
13147	ACTIVE	P	P029-00-3/161	LMC - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P029-00 - Station Building - Manor House Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21144	INACTIVE	P	P029-00-3/161	LMC - Station Building - Manor House Stn		Asbestos	Removed				Gaskets, pump equipment by wall 2					
23620	ACTIVE	P	P029-00-3/161/WAL-001	Wall: Internal - 1 - LMC - Station Building - Manor House Stn	Cable Duct: Other	Asbestos	Strongly Presumed				5 x Cable sleeves Type 2 report R40403 shows that Asbestos Type is Amosite (Node point 49&50)		5			
23541	ACTIVE	P	P029-00-3/161/WAL-002	Wall: Internal - 2 - LMC - Station Building - Manor House Stn		Asbestos	Surveyed – Not Detected				2 x Supalux panels					
21035	ACTIVE	P	P029-00-3/161/WAL-002	Wall: Internal - 2 - LMC - Station Building - Manor House Stn	Cable Duct: Other	Asbestos	Strongly Presumed				9 x Cable sleeves Type 2 report R40403 shows that Asbestos Type is Amosite (Node point 49&50)		9			
21036	ACTIVE	P	P029-00-3/161/WAL-003	Wall: Internal - 3 - LMC - Station Building - Manor House Stn	Cable Duct: Other	Asbestos	Strongly Presumed				7 x Cable sleeves Type 2 report R40403 shows that Asbestos Type is Amosite (Node point 49&50).		7			
13148	ACTIVE	P	P029-00-3/201	Passage - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13149	ACTIVE	P	P029-00-3/202	Passage - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13150	ACTIVE	P	P029-00-3/203	Passage - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13151	ACTIVE	P	P029-00-3/204	Passage - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13152	ACTIVE	P	P029-00-3/205	Passage - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13153	ACTIVE	P	P029-00-3/236	Lobby - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21145	ACTIVE	P	P029-00-3/236	Lobby - Station Building - Manor House Stn	Lead/Leading	Lead Paint/Lead	Known				Metal stretcher cupboard - grey matt - 3m². Thickness : 0.08mm Analysis : 6.6%					
13154	ACTIVE	P	P029-00-3/261	Platform 1 - Eastbound Local - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21147	ACTIVE	P	P029-00-3/261	Platform 1 - Eastbound Local - Station Building - Manor House Stn	Caulking	Asbestos	Strongly Presumed				EB Headwall - Tunnel ring caulking No access onto track during 2024 re-inspection in traffic hours.					



Hazardous Material Asset Register - Summary



P029-00 - Station Building - Manor House Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21153	ACTIVE	p	P029-00-3/261	Platform 1 - Eastbound Local - Station Building - Manor House Stn	Westing house Boxes	Asbestos	Strongly Presumed				Platform 1 Invert - 3x Westinghouse box (1no large & 2no Small) - nr 3/712 No access onto track during 2024 re-inspection in traffic hours.		3			
23622	ACTIVE	p	P029-00-3/261	Platform 1 - Eastbound Local - Station Building - Manor House Stn	Cable Ducts: Bitumen	Asbestos	Strongly Presumed				Cables ducts throughout Inverts No access onto track during 2024 re-inspection in traffic hours.		8			
21148	ACTIVE	p	P029-00-3/261	Platform 1 - Eastbound Local - Station Building - Manor House Stn	Cable: Sheath	Asbestos	Known				EB Headwall - J hanger 1b - 2x 10mm Cables J hanger 2a - 2x 20mm Cables No access onto track during 2024 re-inspection in traffic hours.		2			
21146	ACTIVE	p	P029-00-3/261	Platform 1 - Eastbound Local - Station Building - Manor House Stn	Cable Duct: Other	Asbestos	Strongly Presumed				West End of Eastbound platform - 6 x bitumus ducts, cables comes from 3/661 invert & out of existing duct heads to Finsbury park. No access onto track during 2024 re-inspection in traffic hours.		6			
21149	ACTIVE	p	P029-00-3/261	Platform 1 - Eastbound Local - Station Building - Manor House Stn	Cable: Sheath	Asbestos	Known				EB Tail End - 5x Cables - woven cables run in j hangers 2a & 2b into ducts 1 (top) & 2. J hangers 1a & 1b are free of woven cables No access onto track during 2024 re-inspection in traffic hours.		5			
21152	ACTIVE	p	P029-00-3/261	Platform 1 - Eastbound Local - Station Building - Manor House Stn	Caulking	Asbestos	Strongly Presumed				Platform 1 Invert - Caulking all along invert - sealed No access onto track during 2024 re-inspection in traffic hours.					
69736	ACTIVE	p	P029-00-3/261	Platform 1 - Eastbound Local - Station Building - Manor House Stn		Asbestos	Surveyed – Not Detected				No identified ACMs within metal trunking			R679617		
21151	ACTIVE	p	P029-00-3/261	Platform 1 - Eastbound Local - Station Building - Manor House Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - Cables platform side & pit side along length of invert and at Head/tail walls Appox - 10x cables (1x 1cm dia 1x 2cm dia from ceiling head wall, 2x 8cm dia - pit side into junction, 1x 1cm dia - yellow cable along invert, 2x12cm dia, 1x 2cm dia No access onto track during 2024 re-inspection in traffic hours.		10			
21150	ACTIVE	p	P029-00-3/261/ FLR-01	Floor - 1 - Platform 1 - Station Building - Manor House Stn	Lead/Leading	Lead Paint/Lead	Removed				Grit bin by 3/712 - red matt - 4m². Thickness : 0.06mm Analysis : 1.9%		2			
13155	ACTIVE	p	P029-00-3/262	Platform 2 - Westbound Local - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44464	ACTIVE	p	P029-00-3/262	Platform 2 - Westbound Local - Station Building - Manor House Stn		Asbestos	Strongly Presumed				Asbestos SP - 8x filled cable sleeves - INVERT No access onto track during 2024 re-inspection in traffic hours.					



Hazardous Material Asset Register - Summary



P029-00 - Station Building - Manor House Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
69737	ACTIVE	p	P029-00-3/262	Platform 2 - Westbound Local - Station Building - Manor House Stn	Cable Sheath	Asbestos	Known				Braided cables in metal trunking		2	R679617		
44465	ACTIVE	p	P029-00-3/262	Platform 2 - Westbound Local - Station Building - Manor House Stn	Cable Ducts: Cement	Asbestos	Strongly Presumed				8x filled cable sleeves half way along platform invert. No access onto track during 2024 re-inspection in traffic hours.					
54023	ACTIVE	p	P029-00-3/262	Platform 2 - Westbound Local - Station Building - Manor House Stn	Cable Duct: Other	Asbestos	Strongly Presumed				8 No Cable Sleeves - Sealed - Halfway along invert No access onto track during 2024 re-inspection in traffic hours.		8	R20883		Y
46331	ACTIVE	p	P029-00-3/262	Platform 2 - Westbound Local - Station Building - Manor House Stn	Cable: Sheath	Asbestos	Known				Known asbestos cable - Inside metal trunking, however one running throughout platform					
21157	ACTIVE	p	P029-00-3/262	Platform 2 - Westbound Local - Station Building - Manor House Stn	Cable: Sheath	Asbestos	Presumed				Cross Passage to Sub Station - 1x cable travels via UTX into cross passage & then up into sub station No access within trunking therefore not scored during 2024 re-inspection.		1			
21158	ACTIVE	p	P029-00-3/262	Platform 2 - Westbound Local - Station Building - Manor House Stn	Cable: Sheath	Asbestos	Presumed				Southbound track adjacent to cross passage shaft - 12 x Cables travel over OTX and into cable passage & heads up shaft into sub-station No access within trunking therefore not scored during 2024 reinspection.		12			
21156	ACTIVE	p	P029-00-3/262	Platform 2 - Westbound Local - Station Building - Manor House Stn	Westing house Boxes	Asbestos	Strongly Presumed				Platform 2 Invert - Westinghouse Box - by headwall other end 3/714 Asbestos components within Asbestos feeder cables go into box No access onto track during 2024 re-inspection in traffic hours.		1			
21154	ACTIVE	p	P029-00-3/262	Platform 2 - Westbound Local - Station Building - Manor House Stn	Cable: Sheath	Asbestos	Presumed				16x Cable going from signal box to signal box - cable running down track on existing j hangers to sub station No access onto track during 2024 re-inspection in traffic hours.		16			
21161	ACTIVE	p	P029-00-3/262	Platform 2 - Westbound Local - Station Building - Manor House Stn	Cable: Sheath	Asbestos	Presumed				West bound track - 6 x Cables No access onto track during 2024 re-inspection in traffic hours.		6			
21160	ACTIVE	p	P029-00-3/262	Platform 2 - Westbound Local - Station Building - Manor House Stn	Cable: Sheath	Asbestos	Presumed				Eastbound track 15m from Finsbury Park - 3 x Cables comes along tunnel & through ducts No access onto track during 2024 re-inspection in traffic hours.		3			



Hazardous Material Asset Register - Summary



P029-00 - Station Building - Manor House Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21155	ACTIVE	P	P029-00-3/262	Platform 2 - Westbound Local - Station Building - Manor House Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - approx 23 x cables platform side & pit side along length of invert & at Head/ tail walls. 2x 8cm dia - from ceiling 1.5m from headwall, one going out ceiling pit side headwall, one going down to invert 2 / 1x8cm dia going along down inverts No access onto track during 2024 re-inspection in traffic hours.		23			
21159	ACTIVE	P	P029-00-3/262/ FLR-01	Floor - 1 - Platform 2 - Station Building - Manor House Stn	Cement Troughing	Asbestos	Strongly Presumed				Southbound track adjacent to cross passage shaft - UTX cement troughing from west bound relay gap (4 lm) No access onto track during 2024 re-inspection in traffic hours.					
13156	ACTIVE	P	P029-00-3/281	Switch Room - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13157	ACTIVE	P	P029-00-3/331	Mess Room - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21162	ACTIVE	P	P029-00-3/331/ WAL-003	Wall: Internal - 3 - Mess Room - Station Building - Manor House Stn	Isolator Switches	Asbestos	Strongly Presumed				1x Iron clad isolator 1 x 30 amp No electrician on site during 2024 reinspection to open boxes for inspection - therefore cannot score material within		1			
13158	ACTIVE	P	P029-00-3/381	Store - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13159	ACTIVE	P	P029-00-3/382	Store - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21163	ACTIVE	P	P029-00-3/382/ CLG-01	Ceiling: Solid - 1 - Store - Station Building - Manor House Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Rings sealed in Concrete Caulking not visible behind concrete therefore not scored in 2024 reinspection.					
23554	ACTIVE	P	P029-00-3/382/ WAL-001	Wall: Internal - 1 - Store - Station Building - Manor House Stn	Caulking	Asbestos	Strongly Presumed				All Walls - Tunnel Rings sealed in Concrete Caulking not visible behind concrete therefore not scored in 2024 reinspection.					
13160	ACTIVE	P	P029-00-3/384	CER - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21167	ACTIVE	P	P029-00-3/384/ CLG-01	Ceiling: Solid - 1 - CER - Station Building - Manor House Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Rings sealed in concrete - Walls 2 & 4 & Ceiling No tunnel rings visible - behind wall					



Hazardous Material Asset Register - Summary



P029-00 - Station Building - Manor House Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21164	ACTIVE	P	P029-00-3/384/WAL-001 80872185	Wall: Internal - 1 - CER - Station Building - Manor House Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				2 x Iron clad isolators 2x60 amps No electrician on site during 2024 reinspection to open boxes for inspection - therefore cannot score material within		2			
21165	ACTIVE	P	P029-00-3/384/WAL-002	Wall: Internal - 2 - CER - Station Building - Manor House Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Rings sealed in concrete - Walls 2 & 4 & Ceiling					
21166	ACTIVE	P	P029-00-3/384/WAL-004	Wall: Internal - 4 - CER - Station Building - Manor House Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Rings sealed in concrete - Walls 2 & 4 & Ceiling					
13161	ACTIVE	P	P029-00-3/411	Store - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42584	ACTIVE	P	P029-00-3/411	Store - Station Building - Manor House Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel caulking, throughout, to tunnel rings in Store Room 3/411			R510126	N	N
13162	ACTIVE	P	P029-00-3/661	Switch Room - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23555	ACTIVE	P	P029-00-3/661/FLR-01	Floor - 1 - Switch Room - Station Building - Manor House Stn	Cable Duct: Other	Asbestos	Known				Cables sleeves on the floor near wall 3 (1x wood - below iron clad isolator)					
21226	ACTIVE	P	P029-00-3/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Manor House Stn	Other Electrical Boxes	Asbestos	Known				Trunking Asbestos Components within		1			
23647	ACTIVE	P	P029-00-3/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Manor House Stn	Isolator Switches	Asbestos	Strongly Presumed				6 x Iron Clad Isolator. Later Type 2 report ES11-199 has sampled some of the rope gaskets and no asbestos detected in sample - however some flash guards contain Chrysotile. Type 2 report ES11-199 has sampled some of the rope gaskets and N.A.D.I.S however some flash guards contain Chrysotile		6			
21225	ACTIVE	P	P029-00-3/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Manor House Stn	Other Electrical Boxes	Asbestos	Known				Transformer Box Asbestos Components within		1			
21227	ACTIVE	P	P029-00-3/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Manor House Stn	Other Electrical Boxes	Asbestos	Known				Trunking Asbestos Components within		1			
21228	ACTIVE	P	P029-00-3/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Manor House Stn	Isolator Switches	Asbestos	Strongly Presumed				Iron clad isolators Type 2 report ES11-199 has sampled some of the rope gaskets and no asbestos detected in sample - however flash guards contain Chrysotile					
13163	ACTIVE	P	P029-00-3/662	Switch Room - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P029-00 - Station Building - Manor House Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21229	ACTIVE	P	P029-00-3/662/FLR-01	Floor - 1 - Switch Room - Station Building - Manor House Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Electrical equipment - centre of floor Asbestos Components – Strongly Presumed within					
13164	ACTIVE	P	P029-00-3/663	Switch Room - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21230	ACTIVE	P	P029-00-3/663/FLR-01	Floor - 1 - Switch Room - Station Building - Manor House Stn	Cable Duct: Other	Asbestos	Known				2x Cables sleeves on floor by wall 3 (1x ceramic)		2			
13165	ACTIVE	P	P029-00-3/664	Switch Room - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13166	ACTIVE	P	P029-00-3/711	Relay Room - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21231	ACTIVE	P	P029-00-3/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Manor House Stn	Cable Duct: Other	Asbestos	Known				5x Cable sleeves by floor (cables sleeves 1&2 have asbestos cables)		5			
21232	ACTIVE	P	P029-00-3/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Manor House Stn	Cable Duct: Other	Asbestos	Known				5x Cable sleeves - Node point 42-44		5			
13167	ACTIVE	P	P029-00-3/712	Relay Room - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21233	ACTIVE	P	P029-00-3/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Manor House Stn	Cable: Sheath	Asbestos	Strongly Presumed				5 x Cables by floor - J hanger from top 1&2 asbestos cables, rest are free, concrete & cable sleeves		5			
42941	ACTIVE	P	P029-00-3/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Manor House Stn	Other Boarding	Asbestos	No Access: Presumed				Paxoline Board up High Level on W2					
42942	ACTIVE	P	P029-00-3/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Manor House Stn	Other Boarding	Asbestos	No Access: Presumed				Paxoline Board up High Level on W3					
13168	ACTIVE	P	P029-00-3/713	Relay Room - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21236	ACTIVE	P	P029-00-3/713	Relay Room - Station Building - Manor House Stn	Lead/Leading	Lead Paint/Lead	Known				All room - Yellow gloss - 10m ² . Thickness : 0.33mm Analysis : 8.2%		9			
42944	ACTIVE	P	P029-00-3/713/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Manor House Stn	PCBs	Asbestos	Strongly Presumed				6 PCB W1					
43283	ACTIVE	P	P029-00-3/713/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Manor House Stn	Lead/Leading	Lead Paint/Lead	Presumed				Lead Paint on Walls very poor condition				N	N



Hazardous Material Asset Register - Summary



P029-00 - Station Building - Manor House Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21235	ACTIVE	P	P029-00-3/713/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Manor House Stn	Cable: Sheath	Asbestos	Strongly Presumed				3x Cable (1x 8cm invert to green, 1x 8cm head wall yellow, 1x 2cm green electrical equipment) Wall 2		3			
21234	ACTIVE	P	P029-00-3/713/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Manor House Stn	Cable: Sheath	Asbestos	Strongly Presumed				2x 8cm dia Cable - from 600v supply into invert through concrete sleeves - wall 4		2			
13169	ACTIVE	P	P029-00-3/714	Relay Room - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Wall 2 Westinghouse box					
21237	ACTIVE	P	P029-00-3/714	Relay Room - Station Building - Manor House Stn	Cable: Sheath	Asbestos	Strongly Presumed				2 x 1cm Cable from platform to signal lights		2			
21239	ACTIVE	P	P029-00-3/714	Relay Room - Station Building - Manor House Stn	Cable: Sheath	Asbestos	Strongly Presumed				7x 1cm - from invert to head wall		7			
21240	ACTIVE	P	P029-00-3/714	Relay Room - Station Building - Manor House Stn	Cable: Sheath	Asbestos	Strongly Presumed				3x Cables (1x 2cm, 1x5cm, 1x8cm) from inv		3			
21238	ACTIVE	P	P029-00-3/714/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Manor House Stn	Cable: Sheath	Asbestos	Strongly Presumed				4x 1cm Cables - signal lights cables wall 1 - two from platform across trunking two from signal lights to invert		4			
23584	ACTIVE	P	P029-00-3/714/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Manor House Stn	Cable Duct: Other	Asbestos	Strongly Presumed				5x Cable sleeves - filled in Cable sleeves not visible beneath filling therefore not scored during 2024 reinspection.		5		N	N
43418	ACTIVE	P	P029-00-3/714/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Manor House Stn	Westing house Boxes	Asbestos	Presumed				Westinghouse box Asbestos Components – Presumed within		1			
13170	ACTIVE	P	P029-00-3/786	Service Riser - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21243	ACTIVE	P	P029-00-3/786	Service Riser - Station Building - Manor House Stn		Asbestos	Surveyed – Not Detected				Supalux panels 1m up					
21244	ACTIVE	P	P029-00-3/786/CLG-01	Ceiling: Solid - 1 - Service Shaft - Station Building - Manor House Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Cable sleeve halfway on ceiling					
21242	ACTIVE	P	P029-00-3/786/CLG-01	Ceiling: Solid - 1 - Service Shaft - Station Building - Manor House Stn		Asbestos	Surveyed – Not Detected				Supalux by wall 2					
23585	ACTIVE	P	P029-00-3/786/CLG-01	Ceiling: Solid - 1 - Service Shaft - Station Building - Manor House Stn		Asbestos	Surveyed – Not Detected				2nd Shaft Access from end wall 3 - Supalux panel Fibreglass lagging halfway along					
21241	ACTIVE	P	P029-00-3/786/WAL-001	Wall: Internal - 1 - Service Shaft - Station Building - Manor House Stn	Caulking	Asbestos	Surveyed – Not Detected				Caulking platform side nr 3/712 - Non asbestos					



Hazardous Material Asset Register - Summary



P029-00 - Station Building - Manor House Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21245	ACTIVE	P	P029-00-3/786/WAL-001	Wall: Internal - 1 - Service Shaft - Station Building - Manor House Stn	Cable Duct: Other	Asbestos	Strongly Presumed				6x Cable sleeves		6			
21246	ACTIVE	P	P029-00-3/791	Vent Shaft - Station Building - Manor House Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No access onto track during 2024 re-inspection in traffic hours.					
13171	ACTIVE	P	P029-00-3/901	CER - Station Building - Manor House Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45220	ACTIVE	P	P029-00-3/901	CER - Station Building - Manor House Stn	Cable: Sheath	Asbestos	Strongly Presumed				Node point 8&8, 37&38 - Vent Shaft - 2x 60mm Green Cables coming into vent & crossing chamber No access onto track during 2024 re-inspection in traffic hours.	60	2		N	N
45219	ACTIVE	P	P029-00-3/901	CER - Station Building - Manor House Stn	Cable Duct: Other	Asbestos	Known				Not on CMS - Vent Shaft - 18x Cable sleeves No access onto track during 2024 re-inspection in traffic hours.		18		N	N
21247	ACTIVE	P	P029-00-3/901/FLR-01	Floor - 1 - CER - Station Building - Manor House Stn	Cable Duct: Other	Asbestos	Strongly Presumed				2x Cable sleeves on floor by wall 3 - filled in no access Cable sleeves not visible beneath filling therefore not scored during 2024 re-inspection.		2			

P043-00 - Station Building - Arsenal Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13297	ACTIVE	P	P043-00-1/001	Booking Hall - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43194	ACTIVE	P	P043-00-1/001	Booking Hall - Station Building - Arsenal Stn		Asbestos	Sampled – Not Detected				Putty/ mastic, <1m, to firebreak where ceiling and wall meet in Ticket Hall at Arsenal Station			R513801	N	N
43189	ACTIVE	P	P043-00-1/001	Booking Hall - Station Building - Arsenal Stn		Asbestos	Sampled – Not Detected				Packing, throughout, within exposed damaged ceiling beam in Ticket Hall at Arsenal Station			R513801	N	N
43188	ACTIVE	P	P043-00-1/001	Booking Hall - Station Building - Arsenal Stn		Asbestos	Sampled – Not Detected				Render/ plaster, throughout, within broken ceiling beam in Ticket Hall at Arsenal Station			R513801	N	N
43186	ACTIVE	P	P043-00-1/001	Booking Hall - Station Building - Arsenal Stn		Asbestos	Sampled – Not Detected				Limestone render, throughout, to small section of sand and cement not yet rendered in Ticket Hall at Arsenal Station			R513801	N	N
43193	ACTIVE	P	P043-00-1/001	Booking Hall - Station Building - Arsenal Stn		Asbestos	Sampled – Not Detected				Supalux, <1m2, to firebreak where ceiling and wall meet in Ticket Hall at Arsenal Station			R513801	N	N
43185	ACTIVE	P	P043-00-1/001	Booking Hall - Station Building - Arsenal Stn		Asbestos	Sampled – Not Detected				Render/ plaster, throughout, to small section of sand and cement not yet rendered in Ticket Hall at Arsenal Station			R513801	N	N



Hazardous Material Asset Register - Summary



P043-00 - Station Building - Arsenal Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43187	ACTIVE	P	P043-00-1/001	Booking Hall - Station Building - Arsenal Stn		Asbestos	Sampled – Not Detected				Render, throughout, recently applied within last week in Ticket Hall at Arsenal Station.			R513801	N	N
43190	ACTIVE	P	P043-00-1/001	Booking Hall - Station Building - Arsenal Stn		Asbestos	Sampled – Not Detected				Render/ plaster, throughout, from ceiling and wall where damp in Ticket Hall at Arsenal Station			R513801	N	N
43192	ACTIVE	P	P043-00-1/001	Booking Hall - Station Building - Arsenal Stn		Asbestos	Sampled – Not Detected				Paint/ emulsion, throughout, to ceiling by support beam in Ticket Hall at Arsenal Station			R513801	N	N
23599	ACTIVE	P	P043-00-1/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Arsenal Stn	Glazing Rope	Asbestos	Strongly Presumed				Rope seals behind metal glazing bars					
21395	ACTIVE	P	P043-00-1/001/FLR-01	Floor - 1 - Booking Hall - Station Building - Arsenal Stn	Void	Asbestos	No Access: Presumed				To hatches on floor				N	Yes
21394	ACTIVE	P	P043-00-1/001/FLR-01	Floor - 1 - Booking Hall - Station Building - Arsenal Stn		Asbestos	Surveyed – Not Detected				Supalux Boxing					
13298	ACTIVE	P	P043-00-1/011	Ticket Office - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21400	ACTIVE	P	P043-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Arsenal Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Wall: brick, breeze block and metal vent units, cable trays above false ceiling				Yes	
21399	ACTIVE	P	P043-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Arsenal Stn		Asbestos	Surveyed – Not Detected				Supalux					
21396	ACTIVE	P	P043-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Arsenal Stn	Void	Asbestos	Surveyed – Not Detected				Cables and Conduits beneath Computer tiles					Yes
21398	ACTIVE	P	P043-00-1/011/WAL-001	Wall: Internal - 1 - Ticket Office - Station Building - Arsenal Stn	Void	Asbestos	Surveyed – Not Detected				Wooden box hatches x 3, cabling behind					
21397	ACTIVE	P	P043-00-1/011/WAL-001	Wall: Internal - 1 - Ticket Office - Station Building - Arsenal Stn	Void	Asbestos	Surveyed – Not Detected				Hatches lower level x 2 - Electrical equipment behind,					
13299	ACTIVE	P	P043-00-1/012	CER - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23934	ACTIVE	P	P043-00-1/012/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Arsenal Stn	Void	Asbestos	Surveyed – Not Detected				Solid ceiling and venting above false ceiling				Yes	
21401	ACTIVE	P	P043-00-1/012/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Arsenal Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
23600	ACTIVE	P	P043-00-1/012/FLR-01	Floor - 1 - CER - Station Building - Arsenal Stn	Void	Asbestos	Surveyed – Not Detected				Cement ducting, rubber cables & debris beneath computer tiles					Yes
13300	ACTIVE	P	P043-00-1/021	POM - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21403	ACTIVE	P	P043-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Arsenal Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					



Hazardous Material Asset Register - Summary



P043-00 - Station Building - Arsenal Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21404	ACTIVE	P	P043-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Arsenal Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, wall: brick, breeze block and metal vent units above false ceiling				Yes	
21402	ACTIVE	P	P043-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Arsenal Stn	Void	Asbestos	Surveyed – Not Detected				Cement ducting, rubber cables & debris, metal trunking beneath computer tiles					Yes
13301	ACTIVE	P	P043-00-1/031	Mess Room - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21406	ACTIVE	P	P043-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Arsenal Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, wall: brick, breeze block and metal vent units above false ceiling				Yes	
21405	ACTIVE	P	P043-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Arsenal Stn		Asbestos	Surveyed – Not Detected				Supalux					
23601	ACTIVE	P	P043-00-1/031/WAL-003	Wall: Internal - 3 - Mess Room - Station Building - Arsenal Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LTB heater x 2 - foam panel		2			
13302	ACTIVE	P	P043-00-1/036	Toilet: Unisex - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21409	ACTIVE	P	P043-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Arsenal Stn		Asbestos	Surveyed – Not Detected				Supalux					
21410	ACTIVE	P	P043-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Arsenal Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, wall: breeze block Metal trunking & PVC cables Conduit, metal flue above false ceiling				Yes	
21407	ACTIVE	P	P043-00-1/036/FLR-01	Floor - 1 - Toilet - Station Building - Arsenal Stn	Void	Asbestos	No Access: Presumed				No access beneath drain				N	Yes
21408	ACTIVE	P	P043-00-1/036/WAL-004	Wall: Internal - 4 - Toilet - Station Building - Arsenal Stn	Void	Asbestos	No Access: Presumed				Behind wooden hatch				N	N
13303	ACTIVE	P	P043-00-1/047	Kitchen - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21411	ACTIVE	P	P043-00-1/047/CLG-01	Ceiling: Suspended - 1 - Kitchen - Station Building - Arsenal Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
21412	ACTIVE	P	P043-00-1/047/CLG-01	Ceiling: Suspended - 1 - Kitchen - Station Building - Arsenal Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, walls: solid, metal trim and fibreglass pipe lagging above false ceiling				Yes	
13304	ACTIVE	P	P043-00-1/071	Circulation Area - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21415	INACTIVE	P	P043-00-1/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Arsenal Stn	Void	Asbestos	No Access: Presumed				Above metal hatch				N	N
21413	ACTIVE	P	P043-00-1/071/FLR-01	Floor - 1 - Circulation Area - Station Building - Arsenal Stn	Void	Asbestos	Surveyed – Not Detected				Ceramic ducts beneath hatch 6					Yes



Hazardous Material Asset Register - Summary



P043-00 - Station Building - Arsenal Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21414	ACTIVE	P	P043-00-1/071/WAL-002	Wall: Internal - 2 - Circulation Area - Station Building - Arsenal Stn		Asbestos	Surveyed – Not Detected				Supalux panel					
13305	ACTIVE	P	P043-00-1/081	Lobby - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21416	ACTIVE	P	P043-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Arsenal Stn		Asbestos	Surveyed – Not Detected				Supalux					
21417	ACTIVE	P	P043-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Arsenal Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, wall: brick, breeze block and metal cable tray above false ceiling				Yes	
13306	ACTIVE	P	P043-00-1/082	Lobby - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21419	ACTIVE	P	P043-00-1/082/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Arsenal Stn	Void	Asbestos	Surveyed – Not Detected				Solid walls & metal trim, concrete above false ceiling				Yes	
21418	ACTIVE	P	P043-00-1/082/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Arsenal Stn		Asbestos	Surveyed – Not Detected				Supalux					
13307	ACTIVE	P	P043-00-1/201	Passage - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21422	ACTIVE	P	P043-00-1/201	Passage - Station Building - Arsenal Stn		Asbestos	Surveyed – Not Detected				Supalux boxing above entrance of passage					
21421	ACTIVE	P	P043-00-1/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Arsenal Stn		Asbestos	Surveyed – Not Detected				Supalux board on ceiling in the division between ticket hall & passage no 1/201					
23562	ACTIVE	P	P043-00-1/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Arsenal Stn	Void	Asbestos	Surveyed – Not Detected				Above false ceiling				Yes	
21420	ACTIVE	P	P043-00-1/201/FLR-01	Floor - 1 - Passage - Station Building - Arsenal Stn	Void	Asbestos	Surveyed – Not Detected				Water, concrete beneath 4 x floor hatches					Yes
13308	ACTIVE	P	P043-00-1/202	Passage - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23602	ACTIVE	P	P043-00-1/202/FLR-01	Floor - 1 - Passage- Station Building - Arsenal Stn	Void	Asbestos	No Access: Presumed				To 2 x floor hatches				N	Yes
13309	ACTIVE	P	P043-00-1/203	Passage - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21423	ACTIVE	P	P043-00-1/203/FLR-01	Floor - 1 - Passage - Station Building - Arsenal Stn	Void	Asbestos	No Access: Presumed				2x Inspection hatch - centre floor				N	Yes
21424	ACTIVE	P	P043-00-1/203/WAL-001	Wall: Internal - 1 - Passage - Station Building - Arsenal Stn	Void	Asbestos	Surveyed – Not Detected				Water below metal drainage covers					Yes



Hazardous Material Asset Register - Summary



P043-00 - Station Building - Arsenal Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21425	ACTIVE	P	P043-00-1/203/WAL-003	Wall: Internal - 3 - Passage - Station Building - Arsenal Stn	Void	Asbestos	Surveyed – Not Detected				Water below metal drainage covers					Yes
13310	ACTIVE	P	P043-00-1/237	Lobby - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21427	ACTIVE	P	P043-00-1/237/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Arsenal Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, walls: breeze block above false ceiling				Yes	
23623	ACTIVE	P	P043-00-1/237/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Arsenal Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
21426	ACTIVE	P	P043-00-1/237/FLR-01	Floor - 1 - Lobby - Station Building - Arsenal Stn	Void	Asbestos	Surveyed – Not Detected				Concrete below computer tiles					Yes
13311	ACTIVE	P	P043-00-1/401	Bin Store - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13312	ACTIVE	P	P043-00-1/416	Toilet: Unisex - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21428	ACTIVE	P	P043-00-1/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Arsenal Stn		Asbestos	Surveyed – Not Detected				Supalux					
21429	ACTIVE	P	P043-00-1/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Arsenal Stn	Void	Asbestos	Surveyed – Not Detected				Solid walls & metal trim, concrete ceiling & fibreglass pipe lagging above false ceiling				Yes	
13313	ACTIVE	P	P043-00-1/601	Stairs: Linear - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13314	ACTIVE	P	P043-00-1/602	Stairs: Linear - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13315	ACTIVE	P	P043-00-1/603	Stairs: Linear - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13316	ACTIVE	P	P043-00-1/661	Switch Room - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21431	ACTIVE	P	P043-00-1/661/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Arsenal Stn		Asbestos	Surveyed – Not Detected				3x Supalux panel by wall 3					
23624	ACTIVE	P	P043-00-1/661/FLR-01	Floor - 1 - Switch Room - Station Building - Arsenal Stn	Void	Asbestos	No Access: Presumed				Hatches x 2				N	Yes
21430	ACTIVE	P	P043-00-1/661/FLR-01	Floor - 1 - Switch Room - Station Building - Arsenal Stn		Asbestos	Surveyed – Not Detected				Supalux by wall 1 and between walls 3 and 4					
21543	ACTIVE	P	P043-00-1/661/WAL-001 80861503	Wall: Internal - 1 - Switch Room - Station Building - Arsenal Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				6 x Iron clad isolators No electrician on site during 2024 reinspection to open boxes for inspection - therefore cannot score material within		6			



Hazardous Material Asset Register - Summary



P043-00 - Station Building - Arsenal Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23651	ACTIVE	P	P043-00-1/661/WAL-002 80861504	Wall: Internal - 2 - Switch Room - Station Building - Arsenal Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				Transformer Boxes Asbestos Components – Presumed within		1			
21545	ACTIVE	P	P043-00-1/661/WAL-002 80861504	Wall: Internal - 2 - Switch Room - Station Building - Arsenal Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				1 x Iron clad isolators No electrician on site during 2024 reinspection to open boxes for inspection - therefore cannot score material within		1			
21542	ACTIVE	P	P043-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Arsenal Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Boxes Asbestos Components – Presumed within		3			
21544	ACTIVE	P	P043-00-1/661/WAL-003 80861505	Wall: Internal - 3 - Switch Room - Station Building - Arsenal Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				1 x Iron clad isolators No electrician on site during 2024 reinspection to open boxes for inspection - therefore cannot score material within		1			
13317	ACTIVE	p	P043-00-1/662	Switch Room - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21549	ACTIVE	P	P043-00-1/662/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Arsenal Stn	Void	Asbestos	Surveyed – Not Detected				Steel girder, plaster, wood above false ceiling				Yes	
21548	ACTIVE	P	P043-00-1/662/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Arsenal Stn		Asbestos	Surveyed – Not Detected				Supalux Panels					
21546	ACTIVE	P	P043-00-1/662/FLR-01	Floor - 1 - Switch Room - Station Building - Arsenal Stn		Asbestos	Surveyed – Not Detected				Supalux Boxing by wall 1 & 3					
21550	INACTIVE	P	P043-00-1/662/FLR-01	Floor - 1 - Switch Room - Station Building - Arsenal Stn	Cable Duct: Other	Asbestos	Known				0.06m2 Cable sleeve - wall 2 under metal hatch cover Cable sleeves not visible beneath cement therefore not scored in 2020 reinspection.		1			
21547	INACTIVE	P	P043-00-1/662/FLR-01	Floor - 1 - Switch Room - Station Building - Arsenal Stn	Void	Asbestos	No Access: Presumed				Beneath false floor				N	Yes
21551	ACTIVE	P	P043-00-1/662/FLR-01 80861501	Floor - 1 - Switch Room - Station Building - Arsenal Stn Floor	Cable: Sheath	Asbestos	Strongly Presumed				3x Covered cable sleeves - adjacent wall 2 floor hatch beneath matting Cable sleeves not visible therefore not scored in 2024 re-inspection.		3			
21552	ACTIVE	P	P043-00-1/662/WAL-001 80861496	Wall: Internal - 1 - Switch Room - Station Building - Arsenal Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				3 x Iron clad isolators No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score material within		3			
21553	ACTIVE	P	P043-00-1/662/WAL-002 80861497	Wall: Internal - 2 - Switch Room - Station Building - Arsenal Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				4 x Iron clad isolators No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score material within		4			
13318	ACTIVE	p	P043-00-1/746	SCR - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P043-00 - Station Building - Arsenal Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21554	ACTIVE	P	P043-00-1/746/CLG-01	Ceiling: Solid - 1 - SCR - Station Building - Arsenal Stn		Asbestos	Surveyed – Not Detected				6x Supalux panels					
21555	ACTIVE	P	P043-00-1/746/CLG-01	Ceiling: Solid - 1 - SCR - Station Building - Arsenal Stn	Void	Asbestos	No Access: Presumed				Above Supalux panels				Yes	N
13319	ACTIVE	P	P043-00-1/751	Station Control Room - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23637	ACTIVE	P	P043-00-1/751/CLG-01	Ceiling: Suspended - 1 - Station Control Room - Station Building - Arsenal Stn		Asbestos	Surveyed – Not Detected				Supalux					
21557	ACTIVE	P	P043-00-1/751/CLG-01	Ceiling: Suspended - 1 - Station Control Room - Station Building - Arsenal Stn	Void	Asbestos	Surveyed – Not Detected				Venting, metal cable trays and rubber cables. Walls & ceiling - Solid above false ceiling				Yes	
21556	ACTIVE	P	P043-00-1/751/FLR-01	Floor - 1 - Station Control Room - Station Building - Arsenal Stn	Void	Asbestos	No Access: Presumed				To hatch				N	Yes
21558	ACTIVE	P	P043-00-1/751/FLR-02	Floor - 2 - Station Control Room - Station Building - Arsenal Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
13320	ACTIVE	P	P043-00-2/081	Lobby - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21559	ACTIVE	P	P043-00-2/081/WAL-002	Wall: Internal - 2 - Lobby - Station Building - Arsenal Stn		Asbestos	Surveyed – Not Detected				Supalux					
21560	INACTIVE	P	P043-00-2/081/WAL-002	Wall: Internal - 2 - Lobby - Station Building - Arsenal Stn	Void	Asbestos	No Access: Presumed				Above Supalux					
23638	ACTIVE	P	P043-00-2/081/WAL-002	Wall: Internal - 2 - Lobby - Station Building - Arsenal Stn	Lead/Leading	Lead Paint/Lead	Known				Lobby door outside - red gloss - 2m². Thickness : 0.51mm Analysis : 1.8%					
13321	ACTIVE	P	P043-00-2/201	Passage - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13322	ACTIVE	P	P043-00-2/202	Passage - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13323	ACTIVE	P	P043-00-2/203	Passage - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13324	ACTIVE	P	P043-00-2/261	Platform 1 - Eastbound Local - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21625	ACTIVE	P	P043-00-2/261	Platform 1 - Eastbound Local - Station Building - Arsenal Stn		Asbestos	Surveyed – Not Detected				Eastbound Platform 1 Invert - approx 19 Gaskets - On pumps equipment pipes - Non asbestos					
21630	ACTIVE	P	P043-00-2/261	Platform 1 - Eastbound Local - Station Building - Arsenal Stn	Cable: Sheath	Asbestos	Strongly Presumed				Eastbound Platform 1 Invert - 2x Cables under Voltage Stabilizing unit (VSU)		2		N	N



Hazardous Material Asset Register - Summary



P043-00 - Station Building - Arsenal Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21624	ACTIVE	P	P043-00-2/261	Platform 1 - Eastbound Local - Station Building - Arsenal Stn	Caulking	Asbestos	Surveyed – Not Detected				Eastbound Platform 1 Invert - Caulking halfway along in tunnel rings					
21565	ACTIVE	P	P043-00-2/261	Platform 1 - Eastbound Local - Station Building - Arsenal Stn	Cable: Sheath	Asbestos	Strongly Presumed				Eastbound platform under 2/081, under P-way cabin -2x Cables from switch gear onto pit wall along invert low level then up to level		2		N	N
21627	ACTIVE	P	P043-00-2/261	Platform 1 - Eastbound Local - Station Building - Arsenal Stn	Cable: Sheath	Asbestos	Strongly Presumed				Eastbound Platform 1 Invert - Approx 12 Cables platform side/ trackside along length of invert as well as at Head walls		12		N	N
21628	ACTIVE	P	P043-00-2/261	Platform 1 - Eastbound Local - Station Building - Arsenal Stn	Caulking	Asbestos	Presumed				Tunnel Ring Caulking - Sealed platform side down hatch nr 2/281				N	N
21626	ACTIVE	P	P043-00-2/261	Platform 1 - Eastbound Local - Station Building - Arsenal Stn	Cable: Sheath	Asbestos	Strongly Presumed				Eastbound platform under 2/081, under P-way cabin - 2x Cables coming from switch room 2/661 & heading out to track		2		N	N
21561	ACTIVE	P	P043-00-2/261	Platform 1 - Eastbound Local - Station Building - Arsenal Stn	Lead/Leading	Lead Paint/Lead	Removed				Grit bin by 2/711 - Red gloss - 2m². Thickness : 0.51mm Analysis : 1.8%					
21562	INACTIVE	P	P043-00-2/261	Platform 1 - Eastbound Local - Station Building - Arsenal Stn	Lead/Leading	Lead Paint/Lead	Removed				Removed Stretcher cupboard - red gloss - 2m². Thickness : 0.51mm Analysis : 1.8%					
21563	ACTIVE	P	P043-00-2/261	Platform 1 - Eastbound Local - Station Building - Arsenal Stn	Lead/Leading	Lead Paint/Lead	Known				Tunnel ring surround end of track - green gloss - 22m². Thickness : 0.41mm Analysis : 1.3%					
21564	ACTIVE	P	P043-00-2/261	Platform 1 - Eastbound Local - Station Building - Arsenal Stn	Lead/Leading	Lead Paint/Lead	Known				Electrical cable covers, trackside - green gloss - 20m². Thickness : 0.41mm Analysis : 1.3%					
23639	INACTIVE	P	P043-00-2/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Arsenal Stn	Void	Asbestos	No Access: Presumed				Eastbound Platform 1 Invert - above false ceiling				Yes	N
21566	ACTIVE	P	P043-00-2/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Arsenal Stn	Void	Asbestos	Surveyed – Not Detected				Eastbound Platform 1 Invert - Fibreglass lagging down hatch near 2/281					Yes
13325	ACTIVE	P	P043-00-2/262	Platform 2 - Westbound Local - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46433	ACTIVE	P	P043-00-2/262	Platform 2 - Westbound Local - Station Building - Arsenal Stn		Asbestos	Sampled – Not Detected				Render to trackside wall - Throughout			R651551	N	N
21633	ACTIVE	P	P043-00-2/262	Platform 2 - Westbound Local - Station Building - Arsenal Stn	Cable: Wrap	Asbestos	Strongly Presumed				Tail Wall Braded Cable wrap, near 2/712					
46432	ACTIVE	P	P043-00-2/262	Platform 2 - Westbound Local - Station Building - Arsenal Stn	Debris: Other	Asbestos	Sampled – Not Detected				Dust/debris behind panel to walls - Throughout			R651551	N	N
23653	INACTIVE	P	P043-00-2/262	Platform 2 - Westbound Local - Station Building - Arsenal Stn	Cable: Sheath	Asbestos	Strongly Presumed				Tail Wall Braded Cable near 2/712 Duplicate of 21633					
21635	ACTIVE	P	P043-00-2/262	Platform 2 - Westbound Local - Station Building - Arsenal Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - Under 2/662 Westbound platform 2 - Approx 6 x cables platform side / trackside along length of invert and at Head walls				N	N



Hazardous Material Asset Register - Summary



P043-00 - Station Building - Arsenal Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21634	ACTIVE	P	P043-00-2/262	Platform 2 - Westbound Local - Station Building - Arsenal Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - Under 2/662 Westbound platform 2 - 3x cables from switch room through new core hole onto new J hanger low level on pit wall heading to voltage stabilization unit				N	N
21631	ACTIVE	P	P043-00-2/262	Platform 2 - Westbound Local - Station Building - Arsenal Stn	Lead/Leading	Lead Paint/Lead	Known				Tunnel ring surrounds end of track - green gloss - 22m². Thickness : 0.41mm Analysis : 1.3%					
45177	INACTIVE	P	P043-00-2/262	Platform 2 - Westbound Local - Station Building - Arsenal Stn	Lead/Leading	Lead Paint/Lead	Removed				Grit bin - red gloss - 2m² N.B. Not found on inspection	2			N	N
21632	ACTIVE	P	P043-00-2/262	Platform 2 - Westbound Local - Station Building - Arsenal Stn	Lead/Leading	Lead Paint/Lead	Known				Electrical cable covers trackside - green gloss - 20m². Thickness : 0.41mm Analysis : 1.3%					
21629	ACTIVE	P	P043-00-2/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - Arsenal Stn	Void	Asbestos	No Access: Presumed				Metal vent hatch nr 2/731 - No Access Above				Yes	N
13326	ACTIVE	P	P043-00-2/281	CER - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21636	ACTIVE	P	P043-00-2/281/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Arsenal Stn	Boarding: Supalux	Asbestos	No Access: Presumed				To Supalux hatch				N	N
21637	ACTIVE	P	P043-00-2/281/WAL-005	Wall: Internal - 5 - CER - Station Building - Arsenal Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x Iron clad isolators Suspect asbestos containing materials Strongly Presumed within		2			
13327	ACTIVE	P	P043-00-2/381	Lobby - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23938	ACTIVE	P	P043-00-2/381	Lobby - Station Building - Arsenal Stn	Isolator Switches	Asbestos	Removed				3x 0.02m2 Arc chute inside iron clad isolator		1			
21638	ACTIVE	P	P043-00-2/381/FLR-01	Floor - 1 - Lobby - Station Building - Arsenal Stn	Isolator Switches	Asbestos	Removed				1x Iron clad isolator on floor between walls 4 & 5		1			
13328	ACTIVE	P	P043-00-2/661	Switch Room - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21639	ACTIVE	P	P043-00-2/661/FLR-01	Floor - 1 - Switch Room - Station Building - Arsenal Stn	Void	Asbestos	Surveyed – Not Detected				3x Ceramic cable sleeves, 4x Block sleeves, 1x Wooden panel above ceiling					Yes
21640	ACTIVE	P	P043-00-2/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Arsenal Stn	Isolator Switches	Asbestos	Strongly Presumed				5x Iron clad isolators - 1 x 300 amps, 2 x 200 amps, 2 x 60 amps Strongly Presumed asbestos containing materials within.		5			
23668	ACTIVE	P	P043-00-2/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Arsenal Stn	Isolator Switches	Asbestos	Strongly Presumed				2x Iron Clad switch boxes Strongly Presumed Asbestos Containing materials within		2			
21641	ACTIVE	P	P043-00-2/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Arsenal Stn	Gasket :Pipework	Asbestos	Strongly Presumed				Pump equipment (no access to gaskets)					
13329	ACTIVE	P	P043-00-2/662	Switch Room - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P043-00 - Station Building - Arsenal Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21643	INACTIVE	P	P043-00-2/662/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Arsenal Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	N
23669	ACTIVE	P	P043-00-2/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Arsenal Stn	Isolator Switches	Asbestos	Strongly Presumed				Iron clad isolator - 1 x 100 amps Strongly Presumed Asbestos containing materials within		1			
21645	ACTIVE	P	P043-00-2/662/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Arsenal Stn	Isolator Switches	Asbestos	Strongly Presumed				Iron clad isolator - 3 x 100 amps Strongly presumed asbestos containing materials within		3			
21644	ACTIVE	P	P043-00-2/662/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Arsenal Stn	Other Electrical Boxes	Asbestos	Presumed				Trunking Asbestos Components – Presumed within					
21642	ACTIVE	P	P043-00-2/662/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Arsenal Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux - ceiling level					
13330	ACTIVE	P	P043-00-2/663	Switch Room - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
13331	ACTIVE	P	P043-00-2/664	Switch Room - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13332	ACTIVE	P	P043-00-2/666	Switch Room - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13333	ACTIVE	P	P043-00-2/711	Relay Room - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21647	ACTIVE	P	P043-00-2/711/FLR-01	Floor - 1 - Relay Room - Station Building - Arsenal Stn	Void	Asbestos	No Access: Presumed				Beneath false floor				N	Yes
21646	ACTIVE	P	P043-00-2/711/FLR-01	Floor - 1 - Relay Room - Station Building - Arsenal Stn		Asbestos	Surveyed – Not Detected				3x Supalux panels by walls 2 & 3					
21648	ACTIVE	P	P043-00-2/711/WAL-002 80861321	Wall: Internal - 2 - Relay Room - Station Building - Arsenal Stn Wall: Internal	Westing house Boxes	Asbestos	Strongly Presumed				Westlinghouse Box Asbestos Components – Strongly Presumed within		1		N	N
21649	ACTIVE	P	P043-00-2/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Arsenal Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Door man switch electrical box Asbestos Components – Strongly Presumed within				N	N
13334	ACTIVE	P	P043-00-2/712	Relay Room - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21651	ACTIVE	P	P043-00-2/712/FLR-01	Floor - 1 - Relay Room - Station Building - Arsenal Stn	Void	Asbestos	No Access: Presumed				Beneath Supalux boxing				N	Yes
21650	ACTIVE	P	P043-00-2/712/FLR-01	Floor - 1 - Relay Room - Station Building - Arsenal Stn		Asbestos	Surveyed – Not Detected				Supalux boxing around cables near walls 2 and 3					
21654	ACTIVE	P	P043-00-2/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Arsenal Stn	Cable: Sheath	Asbestos	Strongly Presumed				1x cables from invert to wall 3		1		N	N



Hazardous Material Asset Register - Summary



P043-00 - Station Building - Arsenal Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21653	ACTIVE	P	P043-00-2/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Arsenal Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables x 2 from 600v supply, one goes to invert and one goes out of wall 3		2		N	N
21652	ACTIVE	P	P043-00-2/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Arsenal Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard Panel					
13335	ACTIVE	P	P043-00-2/731	CER - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21656	ACTIVE	P	P043-00-2/731 80143244	CER - Station Building - Arsenal Stn Room Assets	Other Electrical Boxes	Asbestos	Strongly Presumed				Transformer Box Asbestos Components – Strongly Presumed within		1			
21655	ACTIVE	P	P043-00-2/731/FLR-01	Floor - 1 - CER - Station Building - Arsenal Stn		Asbestos	Surveyed – Not Detected				Supalux Boxing on floor by wall 2 - PVC cables behind					
21657	ACTIVE	P	P043-00-2/731/WAL-001	Wall: Internal - 1 - CER - Station Building - Arsenal Stn	Cable: Sheath	Asbestos	Strongly Presumed				1x 2cm dia cable		1			
21658	ACTIVE	P	P043-00-2/731/WAL-002 80861306	Wall: Internal - 2 - CER - Station Building - Arsenal Stn Wall: Internal	Westing house Boxes	Asbestos	Strongly Presumed				Westlinghouse box Asbestos Components – Strongly Presumed within		1			
13336	ACTIVE	P	P043-00-2/732	CER - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21659	ACTIVE	P	P043-00-2/732/FLR-01	Floor - 1 - CER - Station Building - Arsenal Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panel - floor, wall 1					
42706	ACTIVE	P	P043-00-2/732/WAL-002	Wall: Internal - 2 - CER - Station Building - Arsenal Stn	Other Boarding	Asbestos	Removed				Paxoline Board on Wall 2				N	N
21660	ACTIVE	P	P043-00-2/732/WAL-002	Wall: Internal - 2 - CER - Station Building - Arsenal Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse box Asbestos Components – Strongly Presumed within		1			
21661	ACTIVE	P	P043-00-2/732/WAL-003	Wall: Internal - 3 - CER - Station Building - Arsenal Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer box Asbestos Components – Presumed within		1		N	N
21662	ACTIVE	P	P043-00-2/791/WAL-001 80861299	Wall: Internal - 1 - Vent Shaft - Station Building - Arsenal Stn Wall: Internal	Caulking	Asbestos	No Access: Presumed				Tunnel ring caulking No access to vent shaft during 2024 re-inspection in traffic hours. Access via track.				N	N
13337	ACTIVE	P	P043-00-A/731	CER - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21664	ACTIVE	P	P043-00-A/731/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Arsenal Stn	Void	Asbestos	Room: Surveyed – No Known Asbestos				Above metal ceiling				Yes	
21663	ACTIVE	P	P043-00-A/731/FLR-01	Floor - 1 - CER - Station Building - Arsenal Stn	Void	Asbestos	Surveyed – Not Detected				Rubber cables beneath metal floor					Yes



Hazardous Material Asset Register - Summary



P043-00 - Station Building - Arsenal Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21665	ACTIVE	P	P043-00-A/731/WAL-003	Wall: Internal - 3 - CER - Station Building - Arsenal Stn	Isolator Switches	Asbestos	Room: Surveyed – No Known Asbestos				2x Iron clad isolators Note on Re-Inspection found to be NAD		2			
13338	ACTIVE	P	P043-00-A/732	CER - Station Building - Arsenal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23670	INACTIVE	P	P043-00-A/732/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Arsenal Stn	Void	Asbestos	No Access: Presumed				Beneath metal floor				Yes	N

P045-00 - Station Building - Holloway Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46374	INACTIVE	P	P045-00-0/004	Station Entrance - Station Building - Holloway Road Stn		Asbestos	Sampled – Not Detected				Dirt/dust between gaskets to glazing to 6no. Panels	1		R685476	N	N
13339	ACTIVE	P	P045-00-1/001	Booking Hall - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21667	ACTIVE	P	P045-00-1/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Y	N
21666	ACTIVE	P	P045-00-1/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
13340	ACTIVE	P	P045-00-1/011	Ticket Office - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21669	ACTIVE	P	P045-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
23671	ACTIVE	P	P045-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Holloway Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
21668	ACTIVE	P	P045-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Holloway Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete & electrical wiring beneath computer flooring					Yes
13341	ACTIVE	P	P045-00-1/021	POM - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43664	ACTIVE	P	P045-00-1/021	POM - Station Building - Holloway Road Stn		Asbestos	Sampled – Not Detected				Supalux panel Under machine within floor void			R521301	N	N
43666	ACTIVE	P	P045-00-1/021	POM - Station Building - Holloway Road Stn		Asbestos	Sampled – Not Detected				A/c metal ductwork - supalux boxing, MMMF			R521301	N	N



Hazardous Material Asset Register - Summary



P045-00 - Station Building - Holloway Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21671	ACTIVE	P	P045-00-1/021	POM - Station Building - Holloway Road Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard boarding above ticket machines & under stairs					
43665	ACTIVE	P	P045-00-1/021	POM - Station Building - Holloway Road Stn		Asbestos	Sampled – Not Detected				Concrete Slab to floor and floor void			R521301	N	N
21670	ACTIVE	P	P045-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Holloway Road Stn	Void	Asbestos	Surveyed – Not Detected				Lino on raised metal/wood tiles. 4-Rail survey below floor 12/05/2016 Concrete slab below.				N	Yes
13342	ACTIVE	P	P045-00-1/031	Mess Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21674	ACTIVE	P	P045-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Holloway Road Stn	Void	Asbestos	Surveyed – Not Detected				Plaster, solid above false ceiling				Yes	
21672	ACTIVE	P	P045-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
21673	ACTIVE	P	P045-00-1/031/CLG-02	Ceiling: Suspended - 2 - Mess Room - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
23672	ACTIVE	P	P045-00-1/031/CLG-02	Ceiling: Suspended - 2 - Mess Room - Station Building - Holloway Road Stn	Void	Asbestos	Surveyed – Not Detected				Plaster, solid above false ceiling				Yes	
13343	ACTIVE	P	P045-00-1/036	Lobby - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13344	ACTIVE	P	P045-00-1/037	Toilet: Unisex - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13345	ACTIVE	P	P045-00-1/071	Circulation Area - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23939	ACTIVE	P	P045-00-1/071/FLR-01	Floor - 1 - Circulation Area - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Beneath hatch				N	Yes
13346	ACTIVE	P	P045-00-1/236	Lobby - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21679	ACTIVE	P	P045-00-1/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Holloway Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Supalux boxing above false ceiling				Yes	
21678	ACTIVE	P	P045-00-1/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					



Hazardous Material Asset Register - Summary



P045-00 - Station Building - Holloway Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21675	ACTIVE	P	P045-00-1/236/FLR-01	Floor - 1 - Lobby - Station Building - Holloway Road Stn	Void	Asbestos	Surveyed – Not Detected				Lino on raised metal/wood tiles. 4-Rail survey below floor 12/05/2016. Concrete slab				N	Yes
21676	ACTIVE	P	P045-00-1/236/WAL-002	Wall: Internal - 2 - Lobby - Station Building - Holloway Road Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
21677	ACTIVE	P	P045-00-1/236/WAL-004	Wall: Internal - 4 - Lobby - Station Building - Holloway Road Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
13347	ACTIVE	P	P045-00-1/237	Lobby - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13348	ACTIVE	P	P045-00-1/238	Lobby - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21681	ACTIVE	P	P045-00-1/238/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Part suplax tiles, Supalux vertical boarding					
21682	ACTIVE	P	P045-00-1/238/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Holloway Road Stn	Durasteel	Asbestos	Strongly Presumed				Durasteel - half of ceiling					N
21683	ACTIVE	P	P045-00-1/238/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				N	N
21680	ACTIVE	P	P045-00-1/238/WAL-004	Wall: Internal - 4 - Lobby - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux Beam					
13349	ACTIVE	P	P045-00-1/239	Passage - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13350	ACTIVE	P	P045-00-1/281	Station Control Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21687	ACTIVE	P	P045-00-1/281/CLG-01	Ceiling: Suspended - 1 - Station Control Room - Station Building - Holloway Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete & fibreglass lagging above false ceiling				Yes	
21686	ACTIVE	P	P045-00-1/281/CLG-01	Ceiling: Suspended - 1 - Station Control Room - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
21684	ACTIVE	P	P045-00-1/281/FLR-01	Floor - 1 - Station Control Room - Station Building - Holloway Road Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
21685	ACTIVE	P	P045-00-1/281/FLR-01	Floor - 1 - Station Control Room - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Beneath Lino				N	Yes



Hazardous Material Asset Register - Summary



P045-00 - Station Building - Holloway Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13351	ACTIVE	P	P045-00-1/282	Mess Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21688	ACTIVE	P	P045-00-1/282/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
21689	ACTIVE	P	P045-00-1/282/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Holloway Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
13352	ACTIVE	P	P045-00-1/331	Mess Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13353	ACTIVE	P	P045-00-1/401	Bin Store - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23673	ACTIVE	P	P045-00-1/401	Bin Store - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux boarding around air duct					
21692	ACTIVE	P	P045-00-1/401/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Holloway Road Stn	Void	Asbestos	Surveyed – Not Detected				Above supalux ceiling					
21691	ACTIVE	P	P045-00-1/401/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux					
21690	ACTIVE	P	P045-00-1/401/WAL-001	Wall: Internal - 1 - Store - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux boarding					
13354	ACTIVE	P	P045-00-1/406	Store - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21694	ACTIVE	P	P045-00-1/406	Store - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux Panel above door					
21693	ACTIVE	P	P045-00-1/406/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux boxing					
23940	ACTIVE	P	P045-00-1/406/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Above Supalux Boxing				N	N
13355	ACTIVE	P	P045-00-1/411	Switch Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23674	ACTIVE	P	P045-00-1/411/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux boxing no access					



Hazardous Material Asset Register - Summary



P045-00 - Station Building - Holloway Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21695	ACTIVE	P	P045-00-1/411/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux boarding					
13356	ACTIVE	P	P045-00-1/412	Store - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21696	ACTIVE	P	P045-00-1/412/WAL-001	Wall: Internal - 1 - Store - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux boarding					
13357	ACTIVE	P	P045-00-1/416	Toilet: Female - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13358	ACTIVE	P	P045-00-1/417	Toilet: Male - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21698	ACTIVE	P	P045-00-1/417/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Holloway Road Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
23675	ACTIVE	P	P045-00-1/417/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard				N	N
21697	ACTIVE	P	P045-00-1/417/FLR-01	Floor - 1 - Toilet - Station Building - Holloway Road Stn	Void	Asbestos	Surveyed – Not Detected				Supalux board					Yes
13359	ACTIVE	P	P045-00-1/418	Toilet - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21701	ACTIVE	P	P045-00-1/418/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				N	N
21700	ACTIVE	P	P045-00-1/418/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux boarding, Plasterboard					
21699	ACTIVE	P	P045-00-1/418/DOR-04	Door - 4 - Toilet - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Beneath inspection cover				N	N
13360	ACTIVE	P	P045-00-1/451	Tenancy - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21702	ACTIVE	P	P045-00-1/451/FLR-01	Floor - 1 - Tenancy - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Beneath wood floor				N	Yes
13361	ACTIVE	P	P045-00-1/631	Stairs: Spiral - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P045-00 - Station Building - Holloway Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13362	ACTIVE	P	P045-00-1/661	Switch Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21705	ACTIVE	P	P045-00-1/661	Switch Room - Station Building - Holloway Road Stn	Isolator Switches	Asbestos	Strongly Presumed				20x Fuse switch 3 x 200 amps, 13 x 60 apms, 2 x 30 amps, 2 x 100 amps No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		20		N	N
44401	ACTIVE	P	P045-00-1/661	Switch Room - Station Building - Holloway Road Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer boxes x 4 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		4		N	N
44402	ACTIVE	P	P045-00-1/661	Switch Room - Station Building - Holloway Road Stn	Other Electrical Boxes	Asbestos	Presumed				2 x switch boxes (Bill) walls 2&5 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2		N	N
21704	ACTIVE	P	P045-00-1/661/FLR-01	Floor - 1 - Switch Room - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Beneath Supalux Boarding				N	Yes
21703	ACTIVE	P	P045-00-1/661/FLR-01	Floor - 1 - Switch Room - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				3x Suplaux boarding					
13363	ACTIVE	P	P045-00-1/746	SCR - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13364	ACTIVE	P	P045-00-1/761	SVC - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23941	ACTIVE	P	P045-00-1/761	SVC - Station Building - Holloway Road Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LTB heater with foam panels inside		1			
21709	ACTIVE	P	P045-00-1/761	SVC - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Suplaux boarding high level					
21706	ACTIVE	P	P045-00-1/761/FLR-01	Floor - 1 - SVC - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				To inspection covers				N	Yes
21707	ACTIVE	P	P045-00-1/761/WAL-001	Wall: Internal - 1 - SVC - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux boarding					
21708	ACTIVE	P	P045-00-1/761/WAL-002	Wall: Internal - 2 - SVC - Station Building - Holloway Road Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
13366	ACTIVE	P	P045-00-1/901	Store - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21712	ACTIVE	P	P045-00-1/901	Store - Station Building - Holloway Road Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LTB heater with foam insulation inside		1			



Hazardous Material Asset Register - Summary



P045-00 - Station Building - Holloway Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21713	ACTIVE	P	P045-00-1/901	Store - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Suplax air vent boarding					
21710	ACTIVE	P	P045-00-1/901/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux boarding, Plasterboard					
21711	ACTIVE	P	P045-00-1/901/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	N
13367	ACTIVE	P	P045-00-1/981	Stairs: Linear - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21714	ACTIVE	P	P045-00-1/981/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Holloway Road Stn	Other Boarding	Asbestos	Surveyed – Not Detected				17x white boarding in loft - Plasterboard					
13368	ACTIVE	P	P045-00-2/201	Passage - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13369	ACTIVE	P	P045-00-2/202	Passage - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13370	ACTIVE	P	P045-00-2/203	Passage - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13371	ACTIVE	P	P045-00-2/204	Passage - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21716	ACTIVE	P	P045-00-2/204/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Suplax					
21717	ACTIVE	P	P045-00-2/204/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Above Supalux ceiling				Yes	
21715	ACTIVE	P	P045-00-2/204/WAL-001	Wall: Internal - 1 - Passage - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				No access to hatch on wall				N	N
13372	ACTIVE	P	P045-00-2/205	Passage - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23676	ACTIVE	P	P045-00-2/205/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Suplax panels					
21718	ACTIVE	P	P045-00-2/205/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Holloway Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux panels				Yes	



Hazardous Material Asset Register - Summary



P045-00 - Station Building - Holloway Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13373	ACTIVE	P	P045-00-2/601	Stairs: Linear - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13374	ACTIVE	P	P045-00-2/631	Stairs: Spiral - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13375	ACTIVE	P	P045-00-2/761	Computer Equipment Cupboard - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13376	ACTIVE	P	P045-00-2/762	Computer Equipment Cupboard - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13377	ACTIVE	P	P045-00-2/763	Computer Equipment Cupboard - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13378	ACTIVE	P	P045-00-2/764	Computer Equipment Cupboard - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13379	ACTIVE	P	P045-00-2/765	Computer Equipment Cupboard - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13380	ACTIVE	P	P045-00-2/766	Computer Equipment Cupboard - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13381	ACTIVE	P	P045-00-2/771	Pump Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13382	ACTIVE	P	P045-00-2/971	Disused Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13383	ACTIVE	P	P045-00-2/972	Disused Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21719	ACTIVE	P	P045-00-2/972/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	N
13384	ACTIVE	P	P045-00-2/981	Disused Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13385	ACTIVE	P	P045-00-2/982	Disused Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13386	ACTIVE	P	P045-00-2/991	Disused Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P045-00 - Station Building - Holloway Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13387	ACTIVE	P	P045-00-3/201	Passage - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13388	ACTIVE	P	P045-00-3/202	Passage - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21720	ACTIVE	P	P045-00-3/202	Passage - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				One supalux & one plasterboard boarding above grid 3/289					
13389	ACTIVE	P	P045-00-3/236	Lobby - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23566	ACTIVE	P	P045-00-3/236/DOR-01	Door - 1 - Lobby - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Wood/supalux door frame					
13390	ACTIVE	P	P045-00-3/261	Platform 1 - Westbound Local - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42755	ACTIVE	P	P045-00-3/261	Platform 1 - Westbound Local - Station Building - Holloway Road Stn	Void	Asbestos	Presumed				Green Trunking to Trackside Potential for asbestos containing materials within				N	N
21724	ACTIVE	P	P045-00-3/261	Platform 1 - Westbound Local - Station Building - Holloway Road Stn	Cable: Sheath	Asbestos	Strongly Presumed				4x Cables - 1x 40mm, 1x 20mm, 1x 30mm 1x10mm		4		N	N
21723	ACTIVE	P	P045-00-3/261	Platform 1 - Westbound Local - Station Building - Holloway Road Stn	Westing house Boxes	Asbestos	Strongly Presumed				3x Westlinghouse brake box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		3		N	N
21722	ACTIVE	P	P045-00-3/261	Platform 1 - Westbound Local - Station Building - Holloway Road Stn	Cable: Sheath	Asbestos	Strongly Presumed				2x Cables - 1x 25mm - J hanger 2 - 1x 30mm		2		N	N
21726	ACTIVE	P	P045-00-3/261	Platform 1 - Westbound Local - Station Building - Holloway Road Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - 14 Cables 1x 30mm, 1x 25mm, 1x 100mm 1x5mm - Outer wall by manhole nr 3/714 1x 30mm, 1x20mm, 2x10mm, 1x15mm from ceiling, 1x 30mm, 1x25mm, 3x10mm by manhole nr 3/712		14			
21721	ACTIVE	P	P045-00-3/261	Platform 1 - Westbound Local - Station Building - Holloway Road Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard by disused sealed passage					
69840	ACTIVE	P	P045-00-3/261	Platform 1 - Westbound Local - Station Building - Holloway Road Stn		Asbestos	Sampled – Not Detected				Concrete to outer wall trackside near 3/381			R749801		
23678	ACTIVE	P	P045-00-3/261	Platform 1 - Westbound Local - Station Building - Holloway Road Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - cables platform side & pit side along length of invert and at Head/tail walls				N	N



Hazardous Material Asset Register - Summary



P045-00 - Station Building - Holloway Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21725	ACTIVE	p	P045-00-3/261	Platform 1 - Westbound Local - Station Building - Holloway Road Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Platform 1 Invert - Head wall red door assumed to be lead paint				N	N
23677	INACTIVE	p	P045-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				To manholes				N	Yes
42753	ACTIVE	p	P045-00-3/261/WAL-001	Wall: Internal - 1 - Platform 1 - Station Building - Holloway Road Stn	Lead/Leading	Lead Paint/Lead	Presumed				Green lead Paint to Tail wall				N	N
13391	ACTIVE	p	P045-00-3/262	Platform 2 - Eastbound Local - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21569	ACTIVE	p	P045-00-3/262	Platform 2 - Eastbound Local - Station Building - Holloway Road Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - Cables platform side & pit side along length of invert and at Head/tail walls				N	N
21568	ACTIVE	p	P045-00-3/262	Platform 2 - Eastbound Local - Station Building - Holloway Road Stn	Cable: Sheath	Asbestos	Strongly Presumed				At least 1x 30mm & 1x 40mm Cable - West end of platform		2		N	N
21572	ACTIVE	p	P045-00-3/262	Platform 2 - Eastbound Local - Station Building - Holloway Road Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Platform 2 Invert - 9x Cable sleeves -(3x 3m from hatch, 6x 5m from hatch)		9		N	N
21571	ACTIVE	p	P045-00-3/262	Platform 2 - Eastbound Local - Station Building - Holloway Road Stn	Westing house Boxes	Asbestos	Strongly Presumed				Platform 2 Invert - Westinghouse signal box - Rear wall near 3/383		1		N	N
21567	ACTIVE	p	P045-00-3/262	Platform 2 - Eastbound Local - Station Building - Holloway Road Stn	Caulking	Asbestos	Strongly Presumed				Tunnel rings caulking - EB Headwall End No access onto track during 2020 re-inspection therefore material not scored.				N	N
44407	ACTIVE	p	P045-00-3/262	Platform 2 - Eastbound Local - Station Building - Holloway Road Stn	Other Boarding	Asbestos	Not Found during Inspection				Paxoline within telephone kiosk, head wall end of platform Item not found in 2020 re-inspection. Possibly removed.		1		N	N
42757	ACTIVE	p	P045-00-3/262	Platform 2 - Eastbound Local - Station Building - Holloway Road Stn	Cable Duct: Other	Asbestos	Presumed				Green Trunking to Tracksides Potential for asbestos containing materials within				N	N
21570	ACTIVE	p	P045-00-3/262	Platform 2 - Eastbound Local - Station Building - Holloway Road Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - 10 Cables - (2x25mm, 1x10mm outer wall, 1x10mm, 2x25mm manhole nr 3/711 coming down the ceiling,		10		N	N
21729	ACTIVE	p	P045-00-3/262	Platform 2 - Eastbound Local - Station Building - Holloway Road Stn	Cable: Sheath	Asbestos	Strongly Presumed				5x Cables, 3x 25mm - J hanger 2 1x 30mm - J hanger 4, 1x 35mm - J hanger 3 - EB Headwall End		5		N	N
21728	ACTIVE	p	P045-00-3/262	Platform 2 - Eastbound Local - Station Building - Holloway Road Stn	Westing house Boxes	Asbestos	Strongly Presumed				2x Westinghouse switch end of platform No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2		N	N



Hazardous Material Asset Register - Summary



P045-00 - Station Building - Holloway Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
69841	ACTIVE	P	P045-00-3/262	Platform 2 - Eastbound Local - Station Building - Holloway Road Stn		Asbestos	Sampled – Not Detected				Concrete to outer wall trackside near 3/384			R749801		
21727	INACTIVE	P	P045-00-3/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				To manhole				N	Yes
13392	ACTIVE	P	P045-00-3/381	Store - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21573	ACTIVE	P	P045-00-3/381	Store - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux boarding above door					
69870	ACTIVE	P	P045-00-3/381	Store - Station Building - Holloway Road Stn	Void	Asbestos	Surveyed – Not Detected				Breezeblocks to wall (outer wall), concrete to inner wall. Cavity visually checked as far as reasonably practicable. Limited access to inspect behind			R749801		
13393	ACTIVE	P	P045-00-3/382	Store - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21574	ACTIVE	P	P045-00-3/382/WAL-002	Wall: Internal - 2 - Store - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux boarding					
13394	ACTIVE	P	P045-00-3/383	Disused Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21575	ACTIVE	P	P045-00-3/383	Disused Room - Station Building - Holloway Road Stn	Westing house Boxes	Asbestos	No Access: Presumed				1x Westinghouse box and cable No access onto track during 2020 re-inspection during traffic hours		1		N	N
13395	ACTIVE	P	P045-00-3/384	Store - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
69871	ACTIVE	P	P045-00-3/384	Store - Station Building - Holloway Road Stn	Void	Asbestos	Surveyed – Not Detected				Breezeblocks to wall (outer wall), metal tunnel rings to inner wall. Cavity visually checked as far as reasonably practicable. Limited access to inspect behind			R749801		
13396	ACTIVE	P	P045-00-3/411	Disused Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21576	ACTIVE	P	P045-00-3/411	Disused Room - Station Building - Holloway Road Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - no access small Door on platform Wall				N	N
13397	ACTIVE	P	P045-00-3/661	Switch Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21578	ACTIVE	P	P045-00-3/661	Switch Room - Station Building - Holloway Road Stn	Cable Duct: Other	Asbestos	Known				1x Cable sleeve in middle of room Cable sleeves beneath loose panel		1			



Hazardous Material Asset Register - Summary



P045-00 - Station Building - Holloway Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21577	ACTIVE	P	P045-00-3/661/FLR-01	Floor - 1 - Switch Room - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				To hatch on floor				N	Yes
44404	ACTIVE	P	P045-00-3/661/WAL-002 80872966	Wall: Internal - 2 - Switch Room - Station Building - Holloway Road Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				Electrical boxes No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2		N	N
13398	ACTIVE	P	P045-00-3/662	Switch Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23565	ACTIVE	P	P045-00-3/662/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux boarding					
13399	ACTIVE	P	P045-00-3/663	Switch Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21580	ACTIVE	P	P045-00-3/663	Switch Room - Station Building - Holloway Road Stn	Isolator Switches	Asbestos	Strongly Presumed				2x Fuse switches 1 x 60 amps, 1 x 100 amps No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2		N	N
42743	ACTIVE	P	P045-00-3/663/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Holloway Road Stn	Other Electrical Boxes	Asbestos	Presumed				Trunking No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
21579	ACTIVE	P	P045-00-3/663/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux					
13400	ACTIVE	P	P045-00-3/664	Switch Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44408	ACTIVE	P	P045-00-3/664	Switch Room - Station Building - Holloway Road Stn	Other Electrical Boxes	Asbestos	Presumed				3 x electrical boxes No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		3		N	N
21582	ACTIVE	P	P045-00-3/664	Switch Room - Station Building - Holloway Road Stn	Isolator Switches	Asbestos	Strongly Presumed				4x Iron clad fuse switches No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		4		N	N
42747	ACTIVE	P	P045-00-3/664/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Holloway Road Stn	Other Electrical Boxes	Asbestos	Presumed				Trunking No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N



Hazardous Material Asset Register - Summary



P045-00 - Station Building - Holloway Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21581	ACTIVE	P	P045-00-3/664/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux					
13401	ACTIVE	P	P045-00-3/665	Switch Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21583	ACTIVE	P	P045-00-3/665	Switch Room - Station Building - Holloway Road Stn	Westing house Boxes	Asbestos	No Access: Presumed				5x Westlinghouse brake box No access onto track during 2020 re-inspection during traffic hours		5		N	N
13402	ACTIVE	P	P045-00-3/711	Relay Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44409	ACTIVE	P	P045-00-3/711 80143245	Relay Room - Station Building - Holloway Road Stn Room Assets	Cable: Sheath	Asbestos	Presumed				3 x cables within roller shutter cabinet		3		N	N
21585	ACTIVE	P	P045-00-3/711	Relay Room - Station Building - Holloway Road Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westlinghouse brake box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
21584	ACTIVE	P	P045-00-3/711	Relay Room - Station Building - Holloway Road Stn	Cable: Sheath	Asbestos	Strongly Presumed				1x 20mm Cable		1		N	N
44411	ACTIVE	P	P045-00-3/711 80143245	Relay Room - Station Building - Holloway Road Stn Room Assets	Other Boarding	Asbestos	Presumed				Paxoline boarding - multiple				N	N
44410	INACTIVE	P	P045-00-3/711 80143245	Relay Room - Station Building - Holloway Road Stn Room Assets	PCBs	Polychlorinated biphenyl	Presumed				7 x black boxes		7		N	N
23640	ACTIVE	P	P045-00-3/711/DOR-01	Door - 1 - Relay Room - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux door frame					
21586	ACTIVE	P	P045-00-3/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Holloway Road Stn	Cable: Sheath	Asbestos	Strongly Presumed				2x 10mm Cables		2		N	N
13403	ACTIVE	P	P045-00-3/712	Relay Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23641	ACTIVE	P	P045-00-3/712	Relay Room - Station Building - Holloway Road Stn	Westing house Boxes	Asbestos	Strongly Presumed				1 x Westlinghouse brake box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
21587	ACTIVE	P	P045-00-3/712/DOR-01	Door - 1 - Relay Room - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux door frame					
44403	ACTIVE	P	P045-00-3/712/WAL-001 80873019	Wall: Internal - 1 - Relay Room - Station Building - Holloway Road Stn Wall: Internal	Other Boarding	Asbestos	Presumed				Paxoline board		1		N	N



Hazardous Material Asset Register - Summary



P045-00 - Station Building - Holloway Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13404	ACTIVE	P	P045-00-3/713	Relay Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21588	ACTIVE	P	P045-00-3/713	Relay Room - Station Building - Holloway Road Stn	Westing house Boxes	Asbestos	Strongly Presumed				1 x Westlinghouse brake box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
42751	ACTIVE	P	P045-00-3/713/ WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Holloway Road Stn	Other Boarding	Asbestos	Presumed				Paxoline Board High Level x 2				N	N
13405	ACTIVE	P	P045-00-3/714	Relay Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42754	ACTIVE	P	P045-00-3/714	Relay Room - Station Building - Holloway Road Stn	Lead/Leading	Asbestos	Removed				Green Stretcher Box Lead Paint				N	N
21591	ACTIVE	P	P045-00-3/714	Relay Room - Station Building - Holloway Road Stn	Cable: Sheath	Asbestos	Strongly Presumed				4x Cables (2x 40mm, 1x30mm, 1x15mm)		4		N	N
44406	INACTIVE	P	P045-00-3/714 80143248	Relay Room - Station Building - Holloway Road Stn Room Assets	PCBs	Polychlorinated biphenyl	Presumed				Presumed PCBs within roller shutter cabinet				N	N
21589	ACTIVE	P	P045-00-3/714/ FLR-01	Floor - 1 - Relay Room - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				2x 0.02m2 Supalux boards					
21590	ACTIVE	P	P045-00-3/714/ FLR-01	Floor - 1 - Relay Room - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Beneath Supalux boards				N	Yes
44405	ACTIVE	P	P045-00-3/714/ WAL-002 80873034	Wall: Internal - 2 - Relay Room - Station Building - Holloway Road Stn Wall: Internal	Other Boarding	Asbestos	Presumed				Paxoline boxing				N	N
13406	ACTIVE	P	P045-00-A/082	Lobby - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23642	ACTIVE	P	P045-00-A/082	Lobby - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux partition walls, no access behind					
13407	ACTIVE	P	P045-00-A/131	LMR - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21594	ACTIVE	P	P045-00-A/131	LMR - Station Building - Holloway Road Stn	Durasteel	Asbestos	Surveyed – Not Detected				2m2 Durasteel panel on flammable store		1			
21595	ACTIVE	P	P045-00-A/131	LMR - Station Building - Holloway Road Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				2x Circuit breakers No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2		N	N
21596	ACTIVE	P	P045-00-A/131	LMR - Station Building - Holloway Road Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				2x Controller		2		N	N



Hazardous Material Asset Register - Summary



P045-00 - Station Building - Holloway Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44413	ACTIVE	P	P045-00-A/131	LMR - Station Building - Holloway Road Stn	Other Boarding	Asbestos	Presumed				Soffits to roof recess Presumed asbestos cement.				N	N
23643	ACTIVE	P	P045-00-A/131	LMR - Station Building - Holloway Road Stn	Isolator Switches	Asbestos	Strongly Presumed				13x Fuse switch - 3 x 30 amp, 1 x 300 amps, 5 x 60 amps, 1 x 200 amps, 1 x 100 amps, 2 x 200 amps 2020 re-inspection states 11no. No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		13		N	N
44412	ACTIVE	P	P045-00-A/131	LMR - Station Building - Holloway Road Stn	Other Electrical Boxes	Asbestos	Presumed				1 x electrical box (Bill) No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
42759	ACTIVE	P	P045-00-A/131	LMR - Station Building - Holloway Road Stn	Cable Duct: Other	Asbestos	Presumed				Trunking (Same Wall as Switch Boxes) No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within				N	N
21598	ACTIVE	P	P045-00-A/131	LMR - Station Building - Holloway Road Stn	Lead/Leading	Lead Paint/Lead	Known				Girder - Green gloss - 6m². Thickness : 0.17mm Analysis : 19.0%				N	N
21597	ACTIVE	P	P045-00-A/131	LMR - Station Building - Holloway Road Stn	Lead/Leading	Lead Paint/Lead	Known				Equipment surround - yellow gloss - 2m². Thickness : 0.19mm Analysis : 2.0%				N	N
21593	ACTIVE	P	P045-00-A/131/CLG-01	Ceiling: Solid - 1 - LMR - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding					
21592	ACTIVE	P	P045-00-A/131/FLR-01	Floor - 1 - LMR - Station Building - Holloway Road Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel Panel		1			
42761	ACTIVE	P	P045-00-A/131/WAL-003	Wall: Internal - 3 - LMR - Station Building - Holloway Road Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box 2no.		2		N	N
13408	ACTIVE	P	P045-00-A/236	Lobby - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21599	ACTIVE	P	P045-00-A/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
21600	ACTIVE	P	P045-00-A/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles				Yes	N
13409	ACTIVE	P	P045-00-A/237	Lobby - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21601	ACTIVE	P	P045-00-A/237/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux					



Hazardous Material Asset Register - Summary



P045-00 - Station Building - Holloway Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21602	ACTIVE	P	P045-00-A/237/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Above Supalux				Yes	N
13410	ACTIVE	P	P045-00-A/238	Lobby - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13411	ACTIVE	P	P045-00-A/311	Locker Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23937	ACTIVE	P	P045-00-A/311/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Above Supalux				Yes	N
21606	ACTIVE	P	P045-00-A/311/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux					
42762	ACTIVE	P	P045-00-A/311/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Holloway Road Stn	Lead/Leading	Lead Paint/Lead	Presumed				Red Paint on Pipe				N	N
21603	ACTIVE	P	P045-00-A/311/FLR-01	Floor - 1 - Locker Room - Station Building - Holloway Road Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
21604	ACTIVE	P	P045-00-A/311/FLR-01	Floor - 1 - Locker Room - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Beneath Lino				N	Yes
21605	ACTIVE	P	P045-00-A/311/WAL-001	Wall: Internal - 1 - Locker Room - Station Building - Holloway Road Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
13412	ACTIVE	P	P045-00-A/316	Mess Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21609	ACTIVE	P	P045-00-A/316	Mess Room - Station Building - Holloway Road Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Vertical boarding beneath stairs - Plasterboard					
21610	ACTIVE	P	P045-00-A/316	Mess Room - Station Building - Holloway Road Stn	Lead/Leading	Lead Paint/Lead	Known				Pipe - Red gloss - 3m². Thickness : N/A Analysis : 6.16%				N	N
21607	ACTIVE	P	P045-00-A/316/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Half ceiling - Supalux Half ceiling - Plasterboard					
21608	ACTIVE	P	P045-00-A/316/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	N
13413	ACTIVE	P	P045-00-A/331	Mess Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P045-00 - Station Building - Holloway Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23644	ACTIVE	P	P045-00-A/331	Mess Room - Station Building - Holloway Road Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard - wall right hand side of window, plasterboard boarding beneath window					
21613	ACTIVE	P	P045-00-A/331	Mess Room - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux boxing by window,					
21611	ACTIVE	P	P045-00-A/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux. Concrete & Metal RSJ's					
21612	ACTIVE	P	P045-00-A/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	N
13414	ACTIVE	P	P045-00-A/417	Toilet: Male - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21614	ACTIVE	P	P045-00-A/417	Toilet: Male - Station Building - Holloway Road Stn	No Access	Asbestos	Surveyed – Not Detected				Not surveyed - none visible					
13415	ACTIVE	P	P045-00-A/418	Toilet: Female - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21615	ACTIVE	P	P045-00-A/418	Toilet: Female - Station Building - Holloway Road Stn	No Access	Asbestos	Surveyed – Not Detected				Not surveyed - none visible					
13416	ACTIVE	P	P045-00-A/576	Stairs: Linear - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21616	ACTIVE	P	P045-00-A/576/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Holloway Road Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
21617	ACTIVE	P	P045-00-A/576/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard				Yes	N
21618	ACTIVE	P	P045-00-A/576/CLG-02	Ceiling: Solid - 2 - Linear Stairs - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard				Yes	N
23645	ACTIVE	P	P045-00-A/576/CLG-02	Ceiling: Solid - 2 - Linear Stairs - Station Building - Holloway Road Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
13417	ACTIVE	P	P045-00-A/578	Stairs: Linear - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13418	ACTIVE	P	P045-00-A/579	Stairs: Linear - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13419	ACTIVE	P	P045-00-A/661	Switch Cupboard - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P045-00 - Station Building - Holloway Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21621	ACTIVE	P	P045-00-A/661	Switch Cupboard - Station Building - Holloway Road Stn	Isolator Switches	Asbestos	Strongly Presumed				Fuse switch 1 x 100 amps No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
21619	ACTIVE	P	P045-00-A/661/WAL-003	Wall: Internal - 3 - Switch Cupboard - Station Building - Holloway Road Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
21620	ACTIVE	P	P045-00-A/661/WAL-004	Wall: Internal - 4 - Switch Cupboard - Station Building - Holloway Road Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
13420	ACTIVE	P	P045-00-A/731	CER - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23652	ACTIVE	P	P045-00-A/731	CER - Station Building - Holloway Road Stn	Isolator Switches	Asbestos	Strongly Presumed				2x Fuse switch 2 x 60 amps No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2			
23667	ACTIVE	P	P045-00-A/731/FLR-01	Floor - 1 - CER - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Beneath computer flooring				N	Yes
21622	ACTIVE	P	P045-00-A/731/WAL-004	Wall: Internal - 4 - CER - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux & Bakerlite boarding					
13421	ACTIVE	P	P045-00-A/732	Switch Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21623	ACTIVE	P	P045-00-A/732/FLR-01	Floor - 1 - Switch Room - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Beneath computer flooring				N	Yes
13422	ACTIVE	P	P045-00-A/761	Equipment Room - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21891	ACTIVE	P	P045-00-A/761/CLG-01	Ceiling: Solid - 1 - Equipment Room - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Above Supalux				Yes	N
21890	ACTIVE	P	P045-00-A/761/CLG-01	Ceiling: Solid - 1 - Equipment Room - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Supalux					
21885	ACTIVE	P	P045-00-A/761/FLR-01	Floor - 1 - Equipment Room - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Beneath false floor				N	Yes
21886	ACTIVE	P	P045-00-A/761/WAL-001	Wall: Internal - 1 - Equipment Room - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Wood & Supalux					



Hazardous Material Asset Register - Summary



P045-00 - Station Building - Holloway Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21887	ACTIVE	P	P045-00-A/761/WAL-002	Wall: Internal - 2 - Equipment Room - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Wood & Supalux					
21888	ACTIVE	P	P045-00-A/761/WAL-003	Wall: Internal - 3 - Equipment Room - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Wood & Supalux					
21889	ACTIVE	P	P045-00-A/761/WAL-004	Wall: Internal - 4 - Equipment Room - Station Building - Holloway Road Stn		Asbestos	Surveyed – Not Detected				Wood & Supalux					
13423	ACTIVE	P	P045-00-A/801	Office - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46496	ACTIVE	P	P045-00-A/801/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Holloway Road Stn	Paper Asbestos	Asbestos	Sampled – Not Detected				Materials to ceiling					
21892	ACTIVE	P	P045-00-A/801/FLR-01	Floor - 1 - Office - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Beneath carpet & wood				N	Yes
13424	ACTIVE	P	P045-00-A/802	Office - Station Building - Holloway Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21893	ACTIVE	P	P045-00-A/802/FLR-01	Floor - 1 - Office - Station Building - Holloway Road Stn	Void	Asbestos	No Access: Presumed				Beneath carpet & wood				N	Yes
21894	ACTIVE	P	P045-00-A/802/WAL-004	Wall: Internal - 4 - Office - Station Building - Holloway Road Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
46389	ACTIVE	P	P045-00/SEC-01	Canopy: Station Entrance - 1 - External - Station Building - Holloway Road Stn	Glazing Rope	Asbestos	Surveyed – Not Detected				Station Canopy Entrance - No Asbestos Rope to Glazing Visually Inspected by 4R ES12563 - Noted on AFM Certificates					

P047-00 - Station Building - Caledonian Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13425	ACTIVE	P	P047-00-1/001	Booking Hall - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21897	ACTIVE	P	P047-00-1/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Caledonian Road Stn	Void	Asbestos	Surveyed – Not Detected				Above Hatch Wall 1 - Brick, Metal Beam. Above ceiling - solid, concrete; 2 x metal, wood hatches; W3 Wooden Struts & Cables - Fibreglass Lagged Pipes; Metal Beam				Yes	
21896	ACTIVE	P	P047-00-1/001/WAL-001	Wall: Internal - 1 - Booking Hall - Station Building - Caledonian Road Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel Panels going up Lift Shaft					



Hazardous Material Asset Register - Summary



P047-00 - Station Building - Caledonian Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13426	ACTIVE	P	P047-00-1/011	Ticket Office - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21900	ACTIVE	P	P047-00-1/011	Ticket Office - Station Building - Caledonian Road Stn	Lead/Leading	Lead Paint/Lead	Known				On Sprinkler System Outside Door: Red Gloss. Thickness Variable: Analysis 3.90%				Y	N
21899	ACTIVE	P	P047-00-1/011/CLG-01	Ceiling: Solid - 1 - Ticket Office - Station Building - Caledonian Road Stn	Void	Asbestos	Surveyed – Not Detected				Solid, breeze block walls; ducts & vent units above false ceiling				Yes	
23570	ACTIVE	P	P047-00-1/011/CLG-01	Ceiling: Solid - 1 - Ticket Office - Station Building - Caledonian Road Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
21898	ACTIVE	P	P047-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Caledonian Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
13427	ACTIVE	P	P047-00-1/021	POM - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21902	ACTIVE	P	P047-00-1/021/CLG-01	Ceiling: Solid - 1 - POM - Station Building - Caledonian Road Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
23711	ACTIVE	P	P047-00-1/021/CLG-01	Ceiling: Solid - 1 - POM - Station Building - Caledonian Road Stn	Void	Asbestos	Surveyed – Not Detected				Solid; Vent Ducting above false ceiling				Yes	
21901	ACTIVE	P	P047-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Caledonian Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
13428	ACTIVE	P	P047-00-1/031	Mess Room - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21906	ACTIVE	P	P047-00-1/031	Mess Room - Station Building - Caledonian Road Stn	Lead/Leading	Lead Paint/Lead	Known				On Sprinkler System AFC: Red Gloss. Thickness Variable: Analysis 3.90%				Y	N
21904	ACTIVE	P	P047-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Caledonian Road Stn		Asbestos	Surveyed – Not Detected				Supalux					
21905	ACTIVE	P	P047-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Caledonian Road Stn	Void	Asbestos	Surveyed – Not Detected				Solid, fibreglass lagged pipes above false ceiling				Yes	
21903	ACTIVE	P	P047-00-1/031/FLR-01	Floor - 1 - Mess Room - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Beneath rubber tiles					Yes
13429	ACTIVE	P	P047-00-1/036	Toilet: Unisex - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23712	ACTIVE	P	P047-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Caledonian Road Stn	Void	Asbestos	Surveyed – Not Detected				Solid, wooden panel above Plaster, Hatch				Yes	



Hazardous Material Asset Register - Summary



P047-00 - Station Building - Caledonian Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13430	ACTIVE	P	P047-00-1/071	Circulation Area - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21907	ACTIVE	P	P047-00-1/071	Circulation Area - Station Building - Caledonian Road Stn	No Access	Asbestos	No Access: Presumed				To Lift Shaft					
21908	ACTIVE	P	P047-00-1/071	Circulation Area - Station Building - Caledonian Road Stn	Pipe Lagging	Asbestos	Surveyed – Not Detected				Circulating Area Roof - Fibreglass Pipe Lagging					
42553	ACTIVE	P	P047-00-1/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Caledonian Road Stn	Glazing Rope	Asbestos	Strongly Presumed				Rope within glazing bars to skylight to ceiling		1	R498601	N	N
43644	ACTIVE	P	P047-00-1/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Caledonian Road Stn		Asbestos	Sampled – Not Detected				Plaster on concrete slab to ceiling			R498601	N	N
21909	ACTIVE	P	P047-00-1/081	Lobby - Station Building - Caledonian Road Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
13431	ACTIVE	P	P047-00-1/082	Lobby - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21910	ACTIVE	P	P047-00-1/082	Lobby - Station Building - Caledonian Road Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
13432	ACTIVE	P	P047-00-1/236	Lobby - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21911	ACTIVE	P	P047-00-1/236/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Caledonian Road Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel 2m² to hatch in ceiling-tower needed	2			N	N
23713	ACTIVE	P	P047-00-1/236/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Above false ceiling					
13433	ACTIVE	P	P047-00-1/237	Mess Room - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13434	ACTIVE	P	P047-00-1/238	Lobby - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21913	ACTIVE	P	P047-00-1/238/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Caledonian Road Stn	Cable Duct: Other	Asbestos	No Access: Presumed				2 x cable sleeves on ceiling		2			
21912	ACTIVE	P	P047-00-1/238/WAL-004	Wall: Internal - 4 - Lobby - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Behind Vermiculite lagged pipes					
13435	ACTIVE	P	P047-00-1/239	Toilet: Unisex - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P047-00 - Station Building - Caledonian Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23571	ACTIVE	P	P047-00-1/239/FLR-01	Floor - 1 - Toilet - Station Building - Caledonian Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
21914	ACTIVE	P	P047-00-1/239/FLR-02	Floor - 2 - Lobby - Station Building - Caledonian Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
13436	ACTIVE	P	P047-00-1/240	Lobby - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21915	ACTIVE	P	P047-00-1/240/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Caledonian Road Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
21916	ACTIVE	P	P047-00-1/240/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
13437	ACTIVE	P	P047-00-1/281	Station Control Room - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21918	ACTIVE	P	P047-00-1/281	Station Control Room - Station Building - Caledonian Road Stn		Asbestos	Surveyed – Not Detected				Wall - Supalux Tiles					
21917	ACTIVE	P	P047-00-1/281/FLR-01	Floor - 1 - Station Control Room - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Beneath rubber tiles					Yes
21919	ACTIVE	P	P047-00-1/281/WAL-001	Wall: Internal - 1 - Station Control Room - Station Building - Caledonian Road Stn	Lead/Leading	Lead Paint/Lead	Known				On Sprinkler System AFC & Boxing Red Gloss. Thickness Variable: Analysis 3.90%				Y	N
21920	ACTIVE	P	P047-00-1/281/WAL-002	Wall: Internal - 2 - Station Control Room - Station Building - Caledonian Road Stn	Lead/Leading	Lead Paint/Lead	Known				On Sprinkler System AFC & Boxing Red Gloss. Thickness Variable: Analysis 3.90%				Y	N
13438	ACTIVE	P	P047-00-1/361	Mess Room - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21921	ACTIVE	P	P047-00-1/361/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Caledonian Road Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
21922	ACTIVE	P	P047-00-1/361/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Caledonian Road Stn	Void	Asbestos	Surveyed – Not Detected				Brick, Plaster, Concrete Walls, Vent & Sprinkler System above false ceiling				Yes	
21923	ACTIVE	P	P047-00-1/361/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Caledonian Road Stn	Lead/Leading	Lead Paint/Lead	Known				On Sprinkler System: Red Gloss. Thickness Variable: Analysis 3.90%				Y	N
13439	ACTIVE	P	P047-00-1/401	Bin Store - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P047-00 - Station Building - Caledonian Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21925	ACTIVE	P	P047-00-1/401/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Caledonian Road Stn	Void	Asbestos	Surveyed – Not Detected				Brick Walls, Plaster, Solid above false ceiling				Yes	
21924	ACTIVE	P	P047-00-1/401/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Caledonian Road Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
23714	ACTIVE	P	P047-00-1/401/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Caledonian Road Stn	Lead/Leading	Lead Paint/Lead	Known				On Sprinkler System: Red Gloss. Thickness Variable: Analysis 3.90%				Y	N
13440	ACTIVE	P	P047-00-1/411	CER - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21927	ACTIVE	P	P047-00-1/411/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Caledonian Road Stn		Asbestos	Surveyed – Not Detected				Solid; 3 x Supalux Panels					
21928	ACTIVE	P	P047-00-1/411/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
21926	ACTIVE	P	P047-00-1/411/FLR-01	Floor - 1 - CER - Station Building - Caledonian Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
13441	ACTIVE	P	P047-00-1/416	Toilet: Male - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21930	ACTIVE	P	P047-00-1/416	Toilet: Male - Station Building - Caledonian Road Stn	Lead/Leading	Lead Paint/Lead	Known				On Window Frame & Sills: White Gloss. Thickness 0.66mm: Analysis 4.40%				N	N
21929	ACTIVE	P	P047-00-1/416/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Caledonian Road Stn	Void	Asbestos	Surveyed – Not Detected				Solid, brick walls above metal tiles				Yes	
13442	ACTIVE	P	P047-00-1/417	Toilet: Female - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21931	ACTIVE	P	P047-00-1/417/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Caledonian Road Stn	Void	Asbestos	Surveyed – Not Detected				Solid, brick walls above metal tiles				Yes	
23715	ACTIVE	P	P047-00-1/417/WDW-01	Window - 1 - Toilet - Station Building - Caledonian Road Stn	Lead/Leading	Lead Paint/Lead	Known				Window Frame & Sills: White Gloss. Thickness 0.66mm: Analysis 4.40%				N	N
21932	ACTIVE	P	P047-00-1/417/WDW-02	Window - 2 - Toilet - Station Building - Caledonian Road Stn	Lead/Leading	Lead Paint/Lead	Known				Window Frame & Sills: White Gloss. Thickness 0.66mm: Analysis 4.40%				N	N
13443	ACTIVE	P	P047-00-1/418	Toilet: Unisex - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21933	ACTIVE	P	P047-00-1/418	Toilet: Unisex - Station Building - Caledonian Road Stn	No Access	Asbestos	No Access: Presumed				No information available					



Hazardous Material Asset Register - Summary



P047-00 - Station Building - Caledonian Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13444	ACTIVE	P	P047-00-1/451	Store - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos				R&D Survey completed 27/04/2022 R221013 - No Asbestos Detected					
21936	ACTIVE	P	P047-00-1/451/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Caledonian Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Foam Tiles					
23716	ACTIVE	P	P047-00-1/451/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Caledonian Road Stn	Void	Asbestos	Surveyed – Not Detected				Above false ceiling - Plaster on concrete, wooden covings, timber joists, plastic cables.				Yes	
21934	ACTIVE	P	P047-00-1/451/FLR-01	Floor - 1 - Store - Station Building - Caledonian Road Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				White, Cream & Red Vinyl Tiles					
21935	ACTIVE	P	P047-00-1/451/FLR-01	Floor - 1 - Store - Station Building - Caledonian Road Stn	Void	Asbestos	Surveyed – Not Detected				Wood beneath false floor - Concrete below. Red tile debris - Non asbestos					Yes
13445	ACTIVE	P	P047-00-1/452	Tenancy - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21937	ACTIVE	P	P047-00-1/452	Tenancy - Station Building - Caledonian Road Stn	Lead/Leading	Lead Paint/Lead	Known				Inside of Door: White Gloss. Thickness 0.36mm: Analysis 2.80%				N	N
21730	ACTIVE	P	P047-00-1/452/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Tenancy - 2nd Floor Landing - No access through Hatch which leads to flat roof				Yes	
13446	ACTIVE	P	P047-00-1/453	Tenancy - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21731	ACTIVE	P	P047-00-1/453/FLR-01	Floor - 1 - Tenancy - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Wood beneath carpet - no access beneath wood					Yes
21732	ACTIVE	P	P047-00-1/453/WAL-002	Wall: Internal - 2 - Tenancy - Station Building - Caledonian Road Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
13447	ACTIVE	P	P047-00-1/551	Yard - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43642	ACTIVE	P	P047-00-1/551	Yard - Station Building - Caledonian Road Stn		Asbestos	Sampled – Not Detected				Concrete Slab			R498601	N	N
21734	ACTIVE	P	P047-00-1/551	Yard - Station Building - Caledonian Road Stn	Debris: Cement	Asbestos	Not Found during Inspection				By Stairs to Basement: Floor Concrete; Cement Panel Debris - Chrysotile Not found during 2020 re-inspection. Possibly removed				N	N
43643	ACTIVE	P	P047-00-1/551	Yard - Station Building - Caledonian Road Stn		Asbestos	Sampled – Not Detected				MMMF ceramic tiles on concrete slab to floor (walkway)			R498601	N	N
13448	ACTIVE	P	P047-00-1/576	Stairs: Linear - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P047-00 - Station Building - Caledonian Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42556	ACTIVE	P	P047-00-1/576	Stairs: Linear - Station Building - Caledonian Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panel to underside of stairs			R498601	N	N
21735	ACTIVE	P	P047-00-1/576	Stairs: Linear - Station Building - Caledonian Road Stn		Asbestos	Surveyed – Not Detected				Supalux Panel High Level					
23567	ACTIVE	P	P047-00-1/576/ WAL-002	Wall: Internal - 2 - Linear Stairs - Station Building - Caledonian Road Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Box - Insulation within by wall 3 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
13449	ACTIVE	P	P047-00-1/577	Stairs: Linear - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13450	ACTIVE	P	P047-00-1/631	Stairs: Spiral - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21736	ACTIVE	P	P047-00-1/631	Stairs: Spiral - Station Building - Caledonian Road Stn		Asbestos	Surveyed – Not Detected				Fire Hydrant Cupboard: Door - Wood with Supalux Panel					
13451	ACTIVE	P	P047-00-1/661	Switch Room - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21739	ACTIVE	P	P047-00-1/661/ CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
21738	ACTIVE	P	P047-00-1/661/ CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Caledonian Road Stn		Asbestos	Surveyed – Not Detected				Supalux Panels					
21737	ACTIVE	P	P047-00-1/661/ FLR-01	Floor - 1 - Switch Room - Station Building - Caledonian Road Stn	Cable Duct: Other	Asbestos	Strongly Presumed				9 x Cable Sleeves Cable sleeves not visible beneath filling therefore not scored during 2020 reinspection.		9		N	N
21740	ACTIVE	P	P047-00-1/661/ WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Caledonian Road Stn	Isolator Switches	Asbestos	Strongly Presumed				Wall 1 Switch Box 1 x 100 amp No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		8		N	N
42707	ACTIVE	P	P047-00-1/661/ WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Caledonian Road Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Wall 1 Electrical Boxes No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within				N	N
42709	ACTIVE	P	P047-00-1/661/ WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Caledonian Road Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Wall 4 Electrical Box x 1 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within				N	N



Hazardous Material Asset Register - Summary



P047-00 - Station Building - Caledonian Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21741	ACTIVE	P	P047-00-1/661/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Caledonian Road Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Wall 4 Switch Box 5 x 60 amp No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		5		N	N
42708	ACTIVE	P	P047-00-1/661/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Caledonian Road Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Wall 4 Cable Sleeves Cable sleeves not visible beneath filling therefore not scored during 2020 re-inspection.				N	N
42710	ACTIVE	P	P047-00-1/661/WAL-005	Wall: Internal - 5 - Switch Room - Station Building - Caledonian Road Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Wall 5 - 2no. Electrical box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2		N	N
42711	ACTIVE	P	P047-00-1/661/WAL-006	Wall: Internal - 6 - Switch Room - Station Building - Caledonian Road Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Wall 6 Transformer Box 2 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2		N	N
21742	ACTIVE	P	P047-00-1/661/WAL-007	Wall: Internal - 7 - Switch Room - Station Building - Caledonian Road Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				3 x Transformer Boxes 1 X 30 amp, 1 x 100amp, 3 x 60 Switch Boxes No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		5		N	N
13452	ACTIVE	P	P047-00-1/665	Switch Cupboard - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21744	ACTIVE	P	P047-00-1/665	Switch Cupboard - Station Building - Caledonian Road Stn		Asbestos	Surveyed – Not Detected				Outside 1/665 - Supalux Panelling on all walls					
23679	ACTIVE	P	P047-00-1/665/CLG-01	Ceiling: Suspended - 1 - Switch Cupboard - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
21743	ACTIVE	P	P047-00-1/665/CLG-01	Ceiling: Suspended - 1 - Switch Cupboard - Station Building - Caledonian Road Stn		Asbestos	Surveyed – Not Detected				Supalux					
13453	ACTIVE	P	P047-00-1/731	CER - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21746	ACTIVE	P	P047-00-1/731	CER - Station Building - Caledonian Road Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x Switch Boxes Insulation within 2 x 60 amps No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2		N	N
21747	ACTIVE	P	P047-00-1/731	CER - Station Building - Caledonian Road Stn	Other Boarding	Asbestos	Strongly Presumed				Plaxoline Board				N	N



Hazardous Material Asset Register - Summary



P047-00 - Station Building - Caledonian Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21745	ACTIVE	P	P047-00-1/731/FLR-01	Floor - 1 - CER - Station Building - Caledonian Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Fibreglass Lagging beneath computer floor					Yes
13454	ACTIVE	P	P047-00-1/746	SCR - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23680	INACTIVE	P	P047-00-1/746/FLR-01	Floor - 1 - SCR - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Beneath false floor					Yes
21748	ACTIVE	P	P047-00-1/746/FLR-01	Floor - 1 - SCR - Station Building - Caledonian Road Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Grey Vinyl Tiles					
13455	ACTIVE	P	P047-00-1/761	SVC - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21752	ACTIVE	P	P047-00-1/761	SVC - Station Building - Caledonian Road Stn	Lead/Leading	Lead Paint/Lead	Known				On Pump Valves: Red Gloss. Thickness Variable: Analysis 3.90%				N	N
21751	ACTIVE	P	P047-00-1/761/CLG-01	Ceiling: Solid - 1 - SVC - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
21750	ACTIVE	P	P047-00-1/761/CLG-01	Ceiling: Solid - 1 - SVC - Station Building - Caledonian Road Stn		Asbestos	Surveyed – Not Detected				By W1 Supalux Panel; By W2 Supalux Boxing					
21749	ACTIVE	P	P047-00-1/761/WAL-002	Wall: Internal - 2 - SVC - Station Building - Caledonian Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels, boxing - cables and pipework and some ceiling				N	N
43655	ACTIVE	P	P047-00-1/791	Vent Shaft - Station Building - Caledonian Road Stn		Asbestos	Sampled – Not Detected				Concrete Slab to floor and some of top			R498426	N	N
21733	ACTIVE	P	P047-00-1/791	Vent Shaft - Station Building - Caledonian Road Stn	No Access	Asbestos	No Access: Presumed				To Ventilation Shaft					
43654	ACTIVE	P	P047-00-1/791	Vent Shaft - Station Building - Caledonian Road Stn		Asbestos	Sampled – Not Detected				Plastic and metal pipework - some MMMF insulation throughout			R498426	N	N
43652	ACTIVE	P	P047-00-1/791	Vent Shaft - Station Building - Caledonian Road Stn		Asbestos	Sampled – Not Detected				Metal tunnel ring, grout through caulking to wall			R498426	N	N
43653	ACTIVE	P	P047-00-1/791	Vent Shaft - Station Building - Caledonian Road Stn		Asbestos	Sampled – Not Detected				Brickwork to wall (top of shaft)			R498426	N	N
23681	ACTIVE	P	P047-00-1/791	Vent Shaft - Station Building - Caledonian Road Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
13456	ACTIVE	P	P047-00-1/901	Disused Room - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13457	ACTIVE	P	P047-00-1/902	Disused Room - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13458	ACTIVE	P	P047-00-1/903	Disused Room - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P047-00 - Station Building - Caledonian Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13459	ACTIVE	P	P047-00-1/904	Store - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21753	ACTIVE	P	P047-00-1/904/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Caledonian Road Stn		Asbestos	Surveyed – Not Detected				Supalux					
21754	ACTIVE	P	P047-00-1/904/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Caledonian Road Stn	Void	Asbestos	Surveyed – Not Detected				Solid, Brick Walls above false ceiling				Yes	
13460	ACTIVE	P	P047-00-2/081	Lobby - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21756	ACTIVE	P	P047-00-2/081	Lobby - Station Building - Caledonian Road Stn	Lead/Leading	Lead Paint/Lead	Known				Banisters & lift Shaft: Black Gloss. Thickness Too Thin To Measure: Analysis 4.61%				N	N
21755	ACTIVE	P	P047-00-2/081/FLR-01	Floor - 1 - Lobby - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Under Stairs - no access - too many boxes					Yes
23682	ACTIVE	P	P047-00-2/081/WAL-003	Wall: Internal - 3 - Lobby - Station Building - Caledonian Road Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
13461	ACTIVE	P	P047-00-2/201	Passage - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13462	ACTIVE	P	P047-00-2/236	Lobby - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13463	ACTIVE	P	P047-00-2/237	Locker Room - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45200	ACTIVE	P	P047-00-2/237	Locker Room - Station Building - Caledonian Road Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Box - Insulation within by wall 3 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
13464	ACTIVE	P	P047-00-2/238	Passage - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21758	ACTIVE	P	P047-00-2/238/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Caledonian Road Stn		Asbestos	Surveyed – Not Detected				Supalux Panels. W6-10 Fibreglass Lagging around Pipes, Foam					
21759	ACTIVE	P	P047-00-2/238/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
21757	ACTIVE	P	P047-00-2/238/WAL-006	Wall: Internal - 6 - Passage - Station Building - Caledonian Road Stn		Asbestos	Surveyed – Not Detected				Supalux Panel Boxing onto Beam					



Hazardous Material Asset Register - Summary



P047-00 - Station Building - Caledonian Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13465	ACTIVE	P	P047-00-2/316	Locker Room - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21760	ACTIVE	P	P047-00-2/316/CLG-01	Ceiling: Solid - 1 - Locker Room - Station Building - Caledonian Road Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles; Supalux Panel					
21761	ACTIVE	P	P047-00-2/316/CLG-01	Ceiling: Solid - 1 - Locker Room - Station Building - Caledonian Road Stn	Void	Asbestos	Surveyed – Not Detected				Solid above false ceiling				Yes	
13466	ACTIVE	P	P047-00-2/317	Locker Room - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21763	ACTIVE	P	P047-00-2/317/CLG-01	Ceiling: Solid - 1 - Locker Room - Station Building - Caledonian Road Stn	Void	Asbestos	Surveyed – Not Detected				Solid above false ceiling				Yes	
21762	ACTIVE	P	P047-00-2/317/CLG-01	Ceiling: Solid - 1 - Locker Room - Station Building - Caledonian Road Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
13467	ACTIVE	P	P047-00-2/331	Mess Room - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21764	ACTIVE	P	P047-00-2/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Caledonian Road Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
21765	ACTIVE	P	P047-00-2/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Caledonian Road Stn	Void	Asbestos	Surveyed – Not Detected				Solid above false ceiling				Yes	
13468	ACTIVE	P	P047-00-2/332	Mess Room - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21766	ACTIVE	P	P047-00-2/332/FLR-01	Floor - 1 - Mess - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				No access underneath Hatches					Yes
23654	ACTIVE	P	P047-00-2/332/WAL-004	Wall: Internal - 4 - Mess Room - Station Building - Caledonian Road Stn	Bitumen	Asbestos	Strongly Presumed				Acoustic Panel under Sink - Chrysotile		1		N	N
13469	ACTIVE	P	P047-00-2/406	Store - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13470	ACTIVE	P	P047-00-2/407	Store - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13471	ACTIVE	P	P047-00-2/411	Store - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P047-00 - Station Building - Caledonian Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13472	ACTIVE	P	P047-00-2/416	Toilet: Male - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21767	ACTIVE	P	P047-00-2/416/FLR-01	Floor - 1 - Toilet - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				No access underneath Hatches					Yes
13473	ACTIVE	P	P047-00-2/452	Disused Room - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21768	ACTIVE	P	P047-00-2/452	Disused Room - Station Building - Caledonian Road Stn	Cable: Sheath	Asbestos	No Access: Presumed				Tenancy (On Survey Area B) Wall 18 - 1x 2cm diameter Cable going into Electrical Box. Basement in very poor condition No access to disused area during 2020 re-inspection. area is currently a construction site.		1		N	N
21771	ACTIVE	P	P047-00-2/452	Disused Room - Station Building - Caledonian Road Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Tenancy - Lobby (On Survey Area C). Wall 1, Wall 3, Wall 13 - Plasterboard. Basement in very poor condition					
21775	ACTIVE	P	P047-00-2/452	Disused Room - Station Building - Caledonian Road Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Tenancy (On Survey Area E) - W1,3,4 Plasterboard. Basement in very poor condition					
21839	ACTIVE	P	P047-00-2/452	Disused Room - Station Building - Caledonian Road Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Tenancy (On Survey Area O) - Lino Top, Vinyl Floor, Green Tiles underneath.					
21840	ACTIVE	P	P047-00-2/452	Disused Room - Station Building - Caledonian Road Stn	Bakerlite	Asbestos	No Access: Presumed				Tenancy (On Survey Area O) - Wall 4 & 8 Toilet Cistern - Amphibole. No access to disused area during 2020 re-inspection. area is currently a construction site.				N	N
45202	ACTIVE	P	P047-00-2/452	Disused Room - Station Building - Caledonian Road Stn		Asbestos	Presumed				Disused Basement (Very Poor Condition) - Fire Door from Basement to Area C				N	N
21770	ACTIVE	P	P047-00-2/452	Disused Room - Station Building - Caledonian Road Stn		Asbestos	Surveyed – Not Detected				Tenancy (On Survey Area B). Wall 18 & 26 Supalux Panels. Basement in very poor condition					
21772	ACTIVE	P	P047-00-2/452	Disused Room - Station Building - Caledonian Road Stn	Cable: Sheath	Asbestos	No Access: Presumed				Tenancy - Lobby (On Survey Area C). Cable. Basement in very poor condition No access to disused area during 2020 re-inspection. area is currently a construction site. Photo of entrance DSC05175		1		N	N
21773	ACTIVE	P	P047-00-2/452	Disused Room - Station Building - Caledonian Road Stn	Cable: Sheath	Asbestos	No Access: Presumed				W14 &15 - 1x5cm Cable goes into switch in Tenancy (Area E). Basement in very poor condition No access to disused area during 2020 re-inspection. area is currently a construction site.		1		N	N



Hazardous Material Asset Register - Summary



P047-00 - Station Building - Caledonian Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23683	ACTIVE	P	P047-00-2/452	Disused Room - Station Building - Caledonian Road Stn	Cable: Sheath	Asbestos	No Access: Presumed				Tenancy (On Survey Area E) - Walls 1,2 & Floor - 1x5cm Cable. Basement in very poor condition No access to disused area during 2020 re-inspection. area is currently a construction site.		1		N	N
21780	ACTIVE	P	P047-00-2/452	Disused Room - Station Building - Caledonian Road Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Tenancy (On Survey Area G) - Wall 5 by Wall 6 Plasterboard - no access to cavity. Wall 6 Plasterboard Partition - no access behind. Basement in very poor condition					
21778	ACTIVE	P	P047-00-2/452	Disused Room - Station Building - Caledonian Road Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Tenancy (On Survey Area F) - W2 Plasterboard, Centre Partition Plasterboard. Basement in very poor condition					
21842	ACTIVE	P	P047-00-2/452	Disused Room - Station Building - Caledonian Road Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Tenancy (On Survey Area P) - Wall 3 Plasterboard Poster - No access to cavity; Wall 5 & 6 Plasterboard Partition;					
21845	ACTIVE	P	P047-00-2/452	Disused Room - Station Building - Caledonian Road Stn	Bakerlite	Asbestos	No Access: Presumed				Tenancy (On Survey Area R) - Wall 3 & 7 Toilet Cistern - Amphibole. No access to disused area during 2020 re-inspection. area is currently a construction site.				N	N
21777	ACTIVE	P	P047-00-2/452	Disused Room - Station Building - Caledonian Road Stn	Lead/Leading	Lead Paint/Lead	Known				Tenancy (On Survey Area F) - Around Pipes on Ceiling: White Gloss. Thickness 0.49mm: Analysis 1.90%. Basement in very poor condition				N	N
21781	ACTIVE	P	P047-00-2/452	Disused Room - Station Building - Caledonian Road Stn	Lead/Leading	Lead Paint/Lead	Known				Tenancy - Second Floor (On Survey Area I) - Around Window Areas: White Gloss. Thickness 0.49mm: Analysis 1.90%. Basement in very poor condition				N	N
21769	ACTIVE	P	P047-00-2/452	Disused Room - Station Building - Caledonian Road Stn	Lead/Leading	Lead Paint/Lead	Known				Tenancy (On Survey Area B) Beams by walls 13-17. Black Gloss. Thickness 1.37mm: Analysis 12.10% Basement in very poor condition				N	N
21774	ACTIVE	P	P047-00-2/452	Disused Room - Station Building - Caledonian Road Stn	Lead/Leading	Lead Paint/Lead	Known				Tenancy - Lobby (On Survey Area C) - Beams 1-4: Red Matt. Thickness 0.89mm: Analysis 5.9%. Basement in very poor condition				N	N
21779	ACTIVE	P	P047-00-2/452	Disused Room - Station Building - Caledonian Road Stn	Lead/Leading	Lead Paint/Lead	Known				Tenancy (On Survey Area F) - Around Pipes on Ceiling: White Gloss. Thickness 0.49mm: Analysis 1.90%. Basement in very poor condition				N	N
21836	ACTIVE	P	P047-00-2/452/FLR-01	Floor - 1 - Disused Room - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Tenancy (On Survey Area K) - no access beneath carpet.					Yes
21847	ACTIVE	P	P047-00-2/452/FLR-01	Floor - 1 - Disused Room - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Tenancy (On Survey Area T) - no access beneath floorboards.					Yes



Hazardous Material Asset Register - Summary



P047-00 - Station Building - Caledonian Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21838	ACTIVE	P	P047-00-2/452/FLR-01	Floor - 1 - Disused Room - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Tenancy (On Survey Area N) - no access beneath floorboards.					Yes
21841	ACTIVE	P	P047-00-2/452/FLR-01	Floor - 1 - Disused Room - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Tenancy (On Survey Area P) - no access beneath floor boards.					Yes
21844	ACTIVE	P	P047-00-2/452/FLR-01	Floor - 1 - Disused Room - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Tenancy (On Survey Area R) - no access beneath lino, floorboards.					Yes
21846	ACTIVE	P	P047-00-2/452/FLR-01	Floor - 1 - Disused Room - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Tenancy (On Survey Area S) - no access beneath floorboards. .					Yes
21843	ACTIVE	P	P047-00-2/452/FLR-01	Floor - 1 - Disused Room - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Tenancy (On Survey Area Q) - no access beneath floor boards.					Yes
23684	ACTIVE	P	P047-00-2/452/FLR-01	Floor - 1 - Disused Room - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Tenancy (On Survey Area J) no access beneath carpet, wood floor.					Yes
21837	ACTIVE	P	P047-00-2/452/FLR-01	Floor - 1 - Disused Room - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Tenancy (On Survey Area L) - no access beneath floor boards.					Yes
13474	ACTIVE	P	P047-00-2/631	Stairs: Spiral - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21848	ACTIVE	P	P047-00-2/631/FLR-01	Floor - 1 - Spiral Stairs - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Concrete Vent Shaft - Metal - No Access Inside					Yes
13475	ACTIVE	P	P047-00-2/661	Switch Room - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
42558	ACTIVE	P	P047-00-2/661	Switch Room - Station Building - Caledonian Road Stn	Pipe Lagging	Asbestos	Surveyed – Not Detected				Metal pipe - hessian wrapping and MMMF insulation to walls and ceiling			R498601	N	N
21849	ACTIVE	P	P047-00-2/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Caledonian Road Stn		Asbestos	Surveyed – Not Detected				Wall 1 to 8 Supalux Boxing					
42557	INACTIVE	P	P047-00-2/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Caledonian Road Stn	Isolator Switches	Asbestos	Strongly Presumed				Materials within combination fuse switch boxes 4 no To wall 3		4	R498601	N	N
42713	ACTIVE	P	P047-00-2/661/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Caledonian Road Stn	Isolator Switches	Asbestos	Strongly Presumed				Wall 4 Switch Boxes 1 x 30, 2 x 60, 2 x 100 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		5		N	N



Hazardous Material Asset Register - Summary



P047-00 - Station Building - Caledonian Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43650	ACTIVE	P	P047-00-2/661/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Caledonian Road Stn		Asbestos	Sampled – Not Detected				Supalux boxing panels to wall 1 and 4			R498601	N	N
21850	ACTIVE	P	P047-00-2/661/WAL-006	Wall: Internal - 6 - Switch Room - Station Building - Caledonian Road Stn	Cable: Sheath	Asbestos	Not Found during Inspection				Wall 6 to 7 - 2m Length Cable Not found in 2020 re-inspection. Possibly removed.		1			
21851	INACTIVE	P	P047-00-2/661/WAL-007	Wall: Internal - 7 - Switch Room - Station Building - Caledonian Road Stn	Cable: Sheath	Asbestos	Strongly Presumed				Wall 6 to 7 - 2m Length Cable		1			
21852	INACTIVE	P	P047-00-2/661/WAL-007	Wall: Internal - 7 - Switch Room - Station Building - Caledonian Road Stn	Isolator Switches	Asbestos	Strongly Presumed				5 x Switch Boxes - Insulation within - 2 x 100amp, 2 x 60 amps 1 x 30 amps		5			
23707	ACTIVE	P	P047-00-2/661/WAL-007	Wall: Internal - 7 - Switch Room - Station Building - Caledonian Road Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				2 x Trunking - Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2			
13476	ACTIVE	P	P047-00-2/731	CER - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21854	ACTIVE	P	P047-00-2/731	CER - Station Building - Caledonian Road Stn	Lead/Leading	Lead Paint/Lead	Known				Window: White Gloss. Thickness 0.66mm: Analysis 4.40%				N	N
21853	ACTIVE	P	P047-00-2/731/WAL-001	Wall: Internal - 1 - CER - Station Building - Caledonian Road Stn		Asbestos	Surveyed – Not Detected				Walls 1 to 3 Supalux Boxing - no access behind					
13477	ACTIVE	P	P047-00-2/761	Equipment Room - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21856	ACTIVE	P	P047-00-2/761	Equipment Room - Station Building - Caledonian Road Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x Switch Box - Insulation within 1 X 30 amp No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
21855	ACTIVE	P	P047-00-2/761/WAL-006	Wall: Internal - 6 - Equipment Room - Station Building - Caledonian Road Stn		Asbestos	Surveyed – Not Detected				Supalux Box - Above Door					
13478	ACTIVE	P	P047-00-3/121	Platform Invert - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23943	ACTIVE	P	P047-00-3/121/DOR-01	Door - 1 - Platform Invert - Station Building - Caledonian Road Stn	Lead/Leading	Lead Paint/Lead	Known				Both Sides of Door: Red Gloss. Thickness 0.39mm: Analysis 6.10%				N	N
13479	ACTIVE	P	P047-00-3/122	Platform Invert - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P047-00 - Station Building - Caledonian Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21857	ACTIVE	P	P047-00-3/122/DOR-01	Door - 1 - Platform Invert - Station Building - Caledonian Road Stn	Lead/Leading	Lead Paint/Lead	Known				Both Sides of Door: Red Gloss. Thickness 0.39mm: Analysis 6.10%				N	N
13480	ACTIVE	P	P047-00-3/201	Passage - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13481	ACTIVE	P	P047-00-3/202	Passage - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43649	ACTIVE	P	P047-00-3/202	Passage - Station Building - Caledonian Road Stn		Asbestos	Sampled – Not Detected				Ceramic tiles on concrete slab to floor			R498601	N	N
13482	ACTIVE	P	P047-00-3/203	Passage - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43648	ACTIVE	P	P047-00-3/203	Passage - Station Building - Caledonian Road Stn		Asbestos	Sampled – Not Detected				Ceramic tiles (partial) on plaster on concrete slab			R498601	N	N
13483	ACTIVE	P	P047-00-3/204	Passage - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13484	ACTIVE	P	P047-00-3/261	Platform 1 - Eastbound Local - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21859	ACTIVE	P	P047-00-3/261	Platform 1 - Eastbound Local - Station Building - Caledonian Road Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - 13 x cables present		13		N	N
21858	ACTIVE	P	P047-00-3/261	Platform 1 - Eastbound Local - Station Building - Caledonian Road Stn		Asbestos	Surveyed – Not Detected				Platform 1 Invert - Supalux panel					
23708	ACTIVE	P	P047-00-3/261/WAL-003	Wall: Internal - 3 - Platform 1 - Station Building - Caledonian Road Stn	Void	Asbestos	Presumed				Red Metal Trackside Trunking - P - Materials within (Previously painted green)				N	N
13485	ACTIVE	P	P047-00-3/262	Platform 2 - Westbound Local - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21861	ACTIVE	P	P047-00-3/262	Platform 2 - Westbound Local - Station Building - Caledonian Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Platform 2 Invert - Supalux Board					
69829	ACTIVE	P	P047-00-3/262	Platform 2 - Westbound Local - Station Building - Caledonian Road Stn	Caulking	Asbestos	Sampled – Not Detected				Wood/grout to metal tunnel ring flange to rear of room 3/382			R749776		
21862	ACTIVE	P	P047-00-3/262	Platform 2 - Westbound Local - Station Building - Caledonian Road Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - 18 x Cables present		18		N	N



Hazardous Material Asset Register - Summary



P047-00 - Station Building - Caledonian Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21860	ACTIVE	P	P047-00-3/262/WAL-003	Wall: Internal - 3 - Platform 2 - Station Building - Caledonian Road Stn	Void	Asbestos	Presumed				Red Metal Trackside Trunking - P - Materials within (Previously painted green)				N	N
13486	ACTIVE	P	P047-00-3/381	Lobby - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23944	ACTIVE	P	P047-00-3/381	Lobby - Station Building - Caledonian Road Stn	Lead/Leading	Lead Paint/Lead	Known				Surround over Tunnel Ring: Green Gloss. Thickness 0.45mm: Analysis 3.60% (over painted with cream)				N	N
21863	ACTIVE	P	P047-00-3/381/DOR-01	Door - 1 - Lobby - Station Building - Caledonian Road Stn	Lead/Leading	Lead Paint/Lead	Known				Both Sides of Door: Red Gloss. Thickness 0.39mm: Analysis 6.10%				N	N
13487	ACTIVE	P	P047-00-3/382	Store - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
69785	ACTIVE	P	P047-00-3/382	Store - Station Building - Caledonian Road Stn	Void	Asbestos	Sampled – Not Detected				Clay to cavity / void area behind block work wall			R749776		
13488	ACTIVE	P	P047-00-3/661	Switch Room - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21864	ACTIVE	P	P047-00-3/661/FLR-01	Floor - 1 - Switch Room - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Beneath Hatch					Yes
21866	ACTIVE	P	P047-00-3/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Caledonian Road Stn	Isolator Switches	Asbestos	Strongly Presumed				3 x Switch Boxes - Insulation within 1 X 100 amp, 1 x 30amp, 1 x 60amp No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		3		N	N
21869	ACTIVE	P	P047-00-3/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Caledonian Road Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Trunking - Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within					
21867	ACTIVE	P	P047-00-3/661/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Caledonian Road Stn	Isolator Switches	Asbestos	Strongly Presumed				5 x Switch Boxes - Insulation within 2 X 60 amp, 2 x 200, 1 x 100amp No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		5		N	N
21868	ACTIVE	P	P047-00-3/661/WAL-005	Wall: Internal - 5 - Switch Room - Station Building - Caledonian Road Stn	Isolator Switches	Asbestos	Strongly Presumed				No Box on this wall 1no. box to wall 5 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		3		N	N
21870	ACTIVE	P	P047-00-3/661/WAL-005	Wall: Internal - 5 - Switch Room - Station Building - Caledonian Road Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Trunking - Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within				N	N



Hazardous Material Asset Register - Summary



P047-00 - Station Building - Caledonian Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21865	ACTIVE	P	P047-00-3/661/WAL-008	Wall: Internal - 8 - Switch Room - Station Building - Caledonian Road Stn		Asbestos	Surveyed – Not Detected				Supalux Boxing - no access behind					
21871	ACTIVE	P	P047-00-3/661/WAL-008	Wall: Internal - 8 - Switch Room - Station Building - Caledonian Road Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Transformer Box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
13489	ACTIVE	P	P047-00-3/662	Switch Room - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21872	ACTIVE	P	P047-00-3/662/FLR-01	Floor - 1 - Switch Room - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Beneath 3 x Hatches					Yes
21874	ACTIVE	P	P047-00-3/662/WAL-005	Wall: Internal - 5 - Switch Room - Station Building - Caledonian Road Stn	Other Electrical Boxes	Asbestos	Presumed				Electrical Equipment - Insulation within				N	N
21873	ACTIVE	P	P047-00-3/662/WAL-008	Wall: Internal - 8 - Switch Room - Station Building - Caledonian Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels above door					
13490	ACTIVE	P	P047-00-3/663	Disused Room - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21875	ACTIVE	P	P047-00-3/663/WAL-004	Wall: Internal - 4 - Disused Room - Station Building - Caledonian Road Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Junction Box - Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within				N	N
13491	ACTIVE	P	P047-00-3/711	Relay Room - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21877	ACTIVE	P	P047-00-3/711	Relay Room - Station Building - Caledonian Road Stn	Cable: Sheath	Asbestos	Strongly Presumed				7 x cables		7		N	N
67613	ACTIVE	P	P047-00-3/711	Relay Room - Station Building - Caledonian Road Stn	Other Electrical Boxes	Asbestos	Presumed				Green electrical box		1			
23709	ACTIVE	P	P047-00-3/711/FLR-01	Floor - 1 - Relay Room - Station Building - Caledonian Road Stn	Cable: Sheath	Asbestos	No Access: Presumed				10 x Cable Sleeves - No Access Filled In		10			
21876	ACTIVE	P	P047-00-3/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Behind Supalux panel					
13492	ACTIVE	P	P047-00-3/712	Relay Room - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21878	ACTIVE	P	P047-00-3/712/FLR-01	Floor - 1 - Relay Room - Station Building - Caledonian Road Stn	Cable Duct: Other	Asbestos	No Access: Presumed				4 x Cable Sleeves		4			



Hazardous Material Asset Register - Summary



P047-00 - Station Building - Caledonian Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42717	ACTIVE	P	P047-00-3/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Caledonian Road Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Wall 1 Electrical Box x 2 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2		N	N
42716	ACTIVE	P	P047-00-3/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Caledonian Road Stn	Other Boarding	Asbestos	Strongly Presumed				Wall 1 Paxoline Board (High Level)				N	N
42714	ACTIVE	P	P047-00-3/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Caledonian Road Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Electrical Box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within				N	N
21879	ACTIVE	P	P047-00-3/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Caledonian Road Stn		Asbestos	Surveyed – Not Detected				Supalux Panel					
21880	ACTIVE	P	P047-00-3/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Caledonian Road Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Electrical Box on Floor - Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within					
23710	ACTIVE	P	P047-00-3/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Caledonian Road Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x Switch Boxes - Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2			
42721	ACTIVE	P	P047-00-3/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Caledonian Road Stn	Other Boarding	Asbestos	Strongly Presumed				Wall 3 Paxoline Board High Level				N	N
42720	INACTIVE	P	P047-00-3/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Caledonian Road Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				Wall 3 - 2 x Small Blue Cylinder PCB's on Rack		2		N	N
13493	ACTIVE	P	P047-00-3/713	Relay Room - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21881	ACTIVE	P	P047-00-3/713/FLR-01	Floor - 1 - Relay Room - Station Building - Caledonian Road Stn	Cable Duct: Other	Asbestos	No Access: Presumed				4 x Cable Sleeves		4			
42719	ACTIVE	P	P047-00-3/713/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Caledonian Road Stn	Cable: Sheath	Asbestos	Strongly Presumed				Wall 1 Asbestos Cables in PCB's Rack				N	N
45203	ACTIVE	P	P047-00-3/713/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Caledonian Road Stn	Cable: Sheath	Asbestos	Strongly Presumed				Asbestos Cables within PCB Rack				N	N



Hazardous Material Asset Register - Summary



P047-00 - Station Building - Caledonian Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21882	ACTIVE	P	P047-00-3/713/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Caledonian Road Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse Boxes - Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
45204	ACTIVE	P	P047-00-3/713/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Caledonian Road Stn	Other Boarding	Asbestos	Strongly Presumed				Paxoline Board High Level				N	N
13494	ACTIVE	P	P047-00-3/731	CER - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21883	ACTIVE	P	P047-00-3/731/FLR-01	Floor - 1 - CER - Station Building - Caledonian Road Stn	Cable Duct: Other	Asbestos	No Access: Presumed				4 x Cable Sleeves		4			
21884	ACTIVE	P	P047-00-3/731/WAL-002	Wall: Internal - 2 - CER - Station Building - Caledonian Road Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse - Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1			
13495	ACTIVE	P	P047-00-3/761	Disused Room - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23569	ACTIVE	P	P047-00-3/761/FLR-01	Floor - 1 - Disused Room - Station Building - Caledonian Road Stn	Void	Asbestos	Surveyed – Not Detected				Rubber & Plastic Cables, Metal Sleeves beneath Drain cover					Yes
21782	ACTIVE	P	P047-00-3/761/WAL-003	Wall: Internal - 3 - Disused Room - Station Building - Caledonian Road Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x Switch Boxes - Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2		N	N
43658	ACTIVE	P	P047-00-3/791	Vent Shaft - Station Building - Caledonian Road Stn		Asbestos	Sampled – Not Detected				Concrete Slab to floor and some of top			R498426	N	N
21785	ACTIVE	P	P047-00-3/791	Vent Shaft - Station Building - Caledonian Road Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Top of Draft Relief Shaft - Circuit Box - Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within				N	N
43657	ACTIVE	P	P047-00-3/791	Vent Shaft - Station Building - Caledonian Road Stn		Asbestos	Sampled – Not Detected				Plastic and metal pipework - some MMMF insulation throughout			R498426	N	N
43656	ACTIVE	P	P047-00-3/791	Vent Shaft - Station Building - Caledonian Road Stn		Asbestos	Sampled – Not Detected				Brickwork to wall (top of shaft)			R498426	N	N
21783	ACTIVE	P	P047-00-3/791	Vent Shaft - Station Building - Caledonian Road Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking				N	N
21786	ACTIVE	P	P047-00-3/791	Vent Shaft - Station Building - Caledonian Road Stn	Lead/Leading	Lead Paint/Lead	Known				Top of Draft Relief Shaft - Gates: Green Gloss. Thickness 0.45mm: Analysis 3.60%				N	N



Hazardous Material Asset Register - Summary



P047-00 - Station Building - Caledonian Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21784	ACTIVE	P	P047-00-3/791/FLR-01	Floor - 1 - Vent Shaft - Station Building - Caledonian Road Stn	Void	Asbestos	Surveyed – Not Detected				Top of Draft Relief Shaft - Metal Beams beneath Metal Floor					Yes
13496	ACTIVE	P	P047-00-A/131	LMR - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
21792	ACTIVE	P	P047-00-A/131	LMR - Station Building - Caledonian Road Stn	Cable: Sheath	Asbestos	Sampled – Not Detected				Lift Motor Room, No. 3 & 4 Halfway Box & full length of lift shaft from halfway box - Braided Cables 3x30m Cables sampled report R519401 25/04/2016		3		N	N
21788	ACTIVE	P	P047-00-A/131	LMR - Station Building - Caledonian Road Stn	Cable: Sheath	Asbestos	Sampled – Not Detected				3 x Cables into Halfway Box Centre of Room Cables sampled report R519401 25/04/2016		3		N	N
42554	ACTIVE	P	P047-00-A/131/FLR-01	Floor - 1 - LMR - Station Building - Caledonian Road Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel panels 1 x 2m² to storage bunker to floor	2	1	R498601	N	N
43164	ACTIVE	P	P047-00-A/131/FLR-01	Floor - 1 - LMR - Station Building - Caledonian Road Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel, 1.25m2, above exit door lower level of Lift No 3 at Caledonian Road Station.			R530501	N	N
43163	ACTIVE	P	P047-00-A/131/FLR-01	Floor - 1 - LMR - Station Building - Caledonian Road Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel, 1.25m2, above exit door top landing of Lift No 3 at Caledonian Road Station			R530501	N	N
21787	ACTIVE	P	P047-00-A/131/FLR-01	Floor - 1 - LMR - Station Building - Caledonian Road Stn	Void	Asbestos	No Access: Presumed				Beneath false floor					Yes
43646	ACTIVE	P	P047-00-A/131/FLR-01	Floor - 1 - LMR - Station Building - Caledonian Road Stn		Asbestos	Sampled – Not Detected				Concrete slab to floor and ceiling			R498601	N	N
43165	ACTIVE	P	P047-00-A/131/FLR-01	Floor - 1 - LMR - Station Building - Caledonian Road Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel, 1.25m2, above access door lower level of Lift No 3 at Caledonian Road Station			R530501	N	N
42970	ACTIVE	P	P047-00-A/131/FLR-01	Floor - 1 - LMR - Station Building - Caledonian Road Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel panel, 2m2, LHS of access door, Lift Shaft No3 (ground level).			R519401	N	N
42555	ACTIVE	P	P047-00-A/131/FLR-01	Floor - 1 - LMR - Station Building - Caledonian Road Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel panel 2m² to floor hatches	2		R498601	N	N
43647	ACTIVE	P	P047-00-A/131/FLR-01	Floor - 1 - LMR - Station Building - Caledonian Road Stn		Asbestos	Sampled – Not Detected				Brickwork to walls			R498601	N	N
21790	ACTIVE	P	P047-00-A/131/FLR-01	Floor - 1 - LMR - Station Building - Caledonian Road Stn	Other Electrical Boxes	Asbestos	Not Found during Inspection				Floor by Wall 1- Wall 4 Electrical Control Panel - Insulation within Not found in 2020 re-inspection. Possibly removed.				N	N
42969	ACTIVE	P	P047-00-A/131/FLR-01	Floor - 1 - LMR - Station Building - Caledonian Road Stn	Cable: Sheath	Asbestos	Sampled – Not Detected				Cable wrap, throughout, to woven sheath cables x3 (to junction box), LMR			R519401	N	N
42971	ACTIVE	P	P047-00-A/131/FLR-01	Floor - 1 - LMR - Station Building - Caledonian Road Stn	Cable: Sheath	Asbestos	Sampled – Not Detected				Grout/concrete, throughout, to tunnel ring flanges throughout the shaft (no access behind concrete, client informed), lift shaft No3			R519401	N	N



Hazardous Material Asset Register - Summary



P047-00 - Station Building - Caledonian Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23568	ACTIVE	P	P047-00-A/131/WAL-001	Wall: Internal - 1 - LMR - Station Building - Caledonian Road Stn	Cable Duct: Other	Asbestos	No Access: Presumed				Cable Sleeves - No Access Filled in					
21789	ACTIVE	P	P047-00-A/131/WAL-001	Wall: Internal - 1 - LMR - Station Building - Caledonian Road Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x Switch Box & Trunking - Insulation within 2 x 100 amps Only 2no. present in 2020 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2		N	N
21791	ACTIVE	P	P047-00-A/131/WAL-004	Wall: Internal - 4 - LMR - Station Building - Caledonian Road Stn	Other Electrical Boxes	Asbestos	Not Found during Inspection				Isolator 600v - Insulation within Not found in 2020 re-inspection. Possibly removed.				N	N
13497	ACTIVE	P	P047-00-A/576	Stairs: Linear - Station Building - Caledonian Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43645	ACTIVE	P	P047-00-A/576	Stairs: Linear - Station Building - Caledonian Road Stn		Asbestos	Sampled – Not Detected				Plaster to brickwork to walls			R498601	N	N

P048-01 - Office Complex - 174 York Way-Caledonian Road To Kings Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13498	ACTIVE	P	P048-01-1/047	Kitchen - Office Complex - 174 York Way-Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13499	ACTIVE	P	P048-01-1/236	Lobby - Office Complex - 174 York Way-Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13500	ACTIVE	P	P048-01-1/237	Lobby - Office Complex - 174 York Way-Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13501	ACTIVE	P	P048-01-1/238	Lobby - Office Complex -174 York Way-Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13502	ACTIVE	P	P048-01-1/240	Passage - Office Complex - 174 York Way-Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13503	ACTIVE	P	P048-01-1/411	Store - Office Complex -174 York Way-Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13504	ACTIVE	P	P048-01-1/416	Toilet: Unisex - Office Complex - 174 York Way-Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13505	ACTIVE	P	P048-01-1/417	Toilet: Unisex - Office Complex - Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P048-01 - Office Complex - 174 York Way-Caledonian Road To Kings Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13506	ACTIVE	P	P048-01-1/418	Toilet: Male - Office Complex - Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13507	ACTIVE	P	P048-01-1/451	Tenancy - Office Complex - Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13508	ACTIVE	P	P048-01-1/452	Tenancy - Office Complex - Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13509	ACTIVE	P	P048-01-1/453	Tenancy - Office Complex - Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13510	ACTIVE	P	P048-01-1/454	Tenancy - Office Complex - Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13511	ACTIVE	P	P048-01-1/455	Tenancy - Office Complex - Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13512	ACTIVE	P	P048-01-1/456	Tenancy - Office Complex - Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13513	ACTIVE	P	P048-01-1/457	Tenancy - Office Complex - Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13514	ACTIVE	P	P048-01-1/458	Tenancy - Office Complex - Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13515	ACTIVE	P	P048-01-1/576	Stairs: Linear - Office Complex - Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13516	ACTIVE	P	P048-01-1/731	CER - Office Complex - Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13517	ACTIVE	P	P048-01-1/981	Stairs: Linear - Office Complex - Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13518	ACTIVE	P	P048-01-A/053	Kitchen - Office Complex - Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13519	ACTIVE	P	P048-01-A/236	Lobby - Office Complex - Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13520	ACTIVE	P	P048-01-A/416	Toilet: Female - Office Complex - Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P048-01 - Office Complex - 174 York Way-Caledonian Road To Kings Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13521	ACTIVE	P	P048-01-A/417	Toilet: Male - Office Complex - Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13522	ACTIVE	P	P048-01-A/576	Stairs: Linear - Office Complex - Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13523	ACTIVE	P	P048-01-A/801	Disused - Disused Complex - Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13524	ACTIVE	P	P048-01-A/802	Disused - Disused Complex - Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13525	ACTIVE	P	P048-01-A/803	Disused - Disused Complex - Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13526	ACTIVE	P	P048-01-A/804	Disused - Disused Complex - Caledonian Road To Kings Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

P053-00 - Station Building - Russell Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13527	ACTIVE	P	P053-00-1/001	Booking Hall - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21793	ACTIVE	P	P053-00-1/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Russell Square Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
13528	ACTIVE	P	P053-00-1/011	Ticket Office - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13529	ACTIVE	P	P053-00-1/021	POM - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13530	ACTIVE	P	P053-00-1/031	Office - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13531	ACTIVE	P	P053-00-1/036	Toilet: Unisex - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13532	ACTIVE	P	P053-00-1/053	Station Control Room - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P053-00 - Station Building - Russell Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21796	ACTIVE	P	P053-00-1/053/CLG-01	Ceiling: Solid - 1 - Station Control Room - Station Building - Russell Square Stn	Void	Asbestos	Surveyed – Not Detected				Ducting Conduits; Fibreglass Lagged Pipes above false ceiling				Yes	
21795	ACTIVE	P	P053-00-1/053/CLG-01	Ceiling: Solid - 1 - Station Control Room - Station Building - Russell Square Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
21794	ACTIVE	P	P053-00-1/053/FLR-01	Floor - 1 - Station Control Room - Station Building - Russell Square Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Tiles					Yes
13533	ACTIVE	P	P053-00-1/071	Circulation Area - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21797	ACTIVE	P	P053-00-1/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Russell Square Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
13534	ACTIVE	P	P053-00-1/139	Void - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13535	ACTIVE	P	P053-00-1/236	Passage - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21798	ACTIVE	P	P053-00-1/236/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Russell Square Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
13536	ACTIVE	P	P053-00-1/237	Passage - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13537	ACTIVE	P	P053-00-1/406	Store - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23685	ACTIVE	P	P053-00-1/406/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Russell Square Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
13538	ACTIVE	P	P053-00-1/411	Void - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13539	ACTIVE	P	P053-00-1/416	Toilet: Unisex - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21799	ACTIVE	P	P053-00-1/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Russell Square Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
13540	ACTIVE	P	P053-00-1/417	Toilet: Female - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P053-00 - Station Building - Russell Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21800	ACTIVE	P	P053-00-1/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Russell Square Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
13541	ACTIVE	P	P053-00-1/418	Toilet: Male - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21801	ACTIVE	P	P053-00-1/418/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Russell Square Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
13542	ACTIVE	P	P053-00-1/576	Stairs: Linear - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21802	ACTIVE	P	P053-00-1/576/DOR-01	Door - 1 - Linear Stairs - Station Building - Russell Square Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux around door					
13543	ACTIVE	P	P053-00-1/631	Stairs: Spiral - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23686	ACTIVE	P	P053-00-1/631	Stairs: Spiral - Station Building - Russell Square Stn	Lagging	Asbestos	Presumed				Trunking lagging -may be asbestos lagging, too high to reach Viewed from spiral stairs only. No high level access.					N
13544	ACTIVE	P	P053-00-1/663	Switch Room - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21803	ACTIVE	P	P053-00-1/663/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Russell Square Stn	Cable Duct: Other	Asbestos	Presumed				4 x Sealed ducts Cable sleeves not visible beneath filling therefore not scored during 2020 re-inspection.		4		N	N
41905	ACTIVE	P	P053-00-1/663/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Russell Square Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 60amp Switch boxes (Paxoline boarding located within box, but no asbestos arc chutes / flash guards as confirmed by opening box - see photo) No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
21804	ACTIVE	P	P053-00-1/663/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Russell Square Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1x Transformer Box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
21805	ACTIVE	P	P053-00-1/663/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Russell Square Stn	Isolator Switches	Asbestos	Strongly Presumed				4 x Switch boxes - 2 x 60, 1 x 200, 1 x 100amps No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		4		N	N



Hazardous Material Asset Register - Summary



P053-00 - Station Building - Russell Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13545	ACTIVE	P	P053-00-1/664	Switch Room - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21806	ACTIVE	P	P053-00-1/664/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Russell Square Stn	Isolator Switches	Asbestos	Strongly Presumed				1x Switch box 1x30amps No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
23687	ACTIVE	P	P053-00-1/664/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Russell Square Stn	Isolator Switches	Asbestos	Strongly Presumed				5x Switch box - 3x60, 1x30, 1x100 amps No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		5		N	N
13546	ACTIVE	P	P053-00-1/786	Service Riser - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45231	ACTIVE	P	P053-00-2/136	Lift Shaft - Station Building - Russell Square Stn	Cable: Sheath	Asbestos	Presumed				12 x Trailing Cables (4 woven cables per lift shaft)		12		N	N
13547	ACTIVE	P	P053-00-2/236	Passage - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21807	ACTIVE	P	P053-00-2/236/DOR-01	Door - 1 - Passage - Station Building - Russell Square Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux door surround					
13548	ACTIVE	P	P053-00-2/401	Bin Store - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21808	ACTIVE	P	P053-00-2/401/FLR-01	Floor - 1 - Store - Station Building - Russell Square Stn	Void	Asbestos	No Access: Presumed				Beneath floor hatch					Yes
13549	ACTIVE	P	P053-00-2/406	Store - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13550	ACTIVE	P	P053-00-2/411	Store - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13551	ACTIVE	P	P053-00-2/416	Shower - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21809	ACTIVE	P	P053-00-2/416/CLG-01	Ceiling: Solid - 1 - Shower - Station Building - Russell Square Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
13552	ACTIVE	P	P053-00-2/665	Switch Room - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P053-00 - Station Building - Russell Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21813	ACTIVE	P	P053-00-2/665	Switch Room - Station Building - Russell Square Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Bus Bar No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
21812	ACTIVE	P	P053-00-2/665	Switch Room - Station Building - Russell Square Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Cable ducts Cable duct not visible beneath filling therefore not scored during 2020 reinspection		1		N	N
21810	ACTIVE	P	P053-00-2/665/FLR-01	Floor - 1 - Switch Room - Station Building - Russell Square Stn	Void	Asbestos	No Access: Presumed				Beneath floor hatch					Yes
41906	ACTIVE	P	P053-00-2/665/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Russell Square Stn	Other Electrical Boxes	Asbestos	Presumed				1 x RSE (electrical) Box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
23942	ACTIVE	P	P053-00-2/665/WAL-006	Wall: Internal - 6 - Switch Room - Station Building - Russell Square Stn	Isolator Switches	Asbestos	Strongly Presumed				6x Switch Boxes 3 x 60amps, 1 x 200, 2 x100 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		6		N	N
21811	ACTIVE	P	P053-00-2/665/WAL-008	Wall: Internal - 8 - Switch Room - Station Building - Russell Square Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				2 x Transformers No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2		N	N
13553	ACTIVE	P	P053-00-2/666	Switch Room - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23655	ACTIVE	P	P053-00-2/666/WAL-004 80877844	Wall: Internal - 4 - Switch Room - Station Building - Russell Square Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				1x Switch box 1x30amps No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
21814	ACTIVE	P	P053-00-2/666/WAL-004 80877844	Wall: Internal - 4 - Switch Room - Station Building - Russell Square Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				3 x Transformer Boxes No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		3		N	N
13554	ACTIVE	P	P053-00-2/667	Switch Cupboard - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13555	ACTIVE	P	P053-00-2/668	Switch Room - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13556	ACTIVE	P	P053-00-2/669	Switch Cupboard - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P053-00 - Station Building - Russell Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21816	ACTIVE	P	P053-00-2/669	Switch Cupboard - Station Building - Russell Square Stn	Other Boarding	Asbestos	Removed				Paxoline Board Removed - as noted upon re inspection During inspection found to have been removed by others					
21815	ACTIVE	P	P053-00-2/669	Switch Cupboard - Station Building - Russell Square Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux above Door					
21817	ACTIVE	P	P053-00-2/669	Switch Cupboard - Station Building - Russell Square Stn	Other Electrical Boxes	Asbestos	Removed				Electrical Equipment During inspection found to be all new electrical equipment, replaced by others.		1			
13557	ACTIVE	P	P053-00-2/731	CER - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21819	ACTIVE	P	P053-00-2/731/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Russell Square Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Boxing over beams - Supalux					
21818	ACTIVE	P	P053-00-2/731/FLR-01	Floor - 1 - CER - Station Building - Russell Square Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Tiles					Yes
21821	ACTIVE	P	P053-00-2/731/WAL-001	Wall: Internal - 1 - CER - Station Building - Russell Square Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x Switch boxes 2X60amps No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2		N	N
21820	ACTIVE	P	P053-00-2/731/WAL-002	Wall: Internal - 2 - CER - Station Building - Russell Square Stn	Other Boarding	Asbestos	Presumed				Paxoline Board		1		N	N
13558	ACTIVE	P	P053-00-2/746	SCR - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
21822	ACTIVE	P	P053-00-2/746	SCR - Station Building - Russell Square Stn	No Access	Asbestos	Surveyed – Not Detected									
13559	ACTIVE	P	P053-00-2/776	Fan Room - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23688	ACTIVE	P	P053-00-2/776	Fan Room - Station Building - Russell Square Stn	Rope Gaskets	Asbestos	Strongly Presumed				Gaskets to fan equipment				N	N
21825	ACTIVE	P	P053-00-2/776/DOR-01	Door - 1 - Fan Room - Station Building - Russell Square Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux door surround					
21823	ACTIVE	P	P053-00-2/776/FLR-01	Floor - 1 - Fan Room - Station Building - Russell Square Stn	Void	Asbestos	No Access: Presumed				Beneath floor hatch					Yes
21824	ACTIVE	P	P053-00-2/776/FLR-02	Floor - 2 - Fan Room - Station Building - Russell Square Stn	Void	Asbestos	No Access: Presumed				Beneath floor hatch					Yes
13560	ACTIVE	P	P053-00-2/781	Mess Room - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P053-00 - Station Building - Russell Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13561	ACTIVE	P	P053-00-2/801	CER - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21826	ACTIVE	P	P053-00-2/801/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Russell Square Stn	Void	Asbestos	No Access: Presumed				Above wooden boxing				Yes	
13562	ACTIVE	P	P053-00-2/901	Passage - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21827	ACTIVE	P	P053-00-2/901/DOR-01	Door - 1 - Passage - Station Building - Russell Square Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux door surround					
13563	ACTIVE	P	P053-00-2/902	Store - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13564	ACTIVE	P	P053-00-2/905	Store - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13565	ACTIVE	P	P053-00-2/906	Store - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44279	ACTIVE	P	P053-00-2/906	Store - Station Building - Russell Square Stn	Mastic	Asbestos	Presumed				Mastic to Air Handling Unit (AHU) - identified during inspection 01/12/2017				N	N
23689	ACTIVE	P	P053-00-2/906	Store - Station Building - Russell Square Stn	Gasket :Pipework	Asbestos	Presumed				Gaskets to pipe work				N	N
21828	ACTIVE	P	P053-00-2/906/FLR-01 80877997	Floor - 1 - Store - Station Building - Russell Square Stn Floor	Void	Asbestos	No Access: Presumed				4 x Hatch					Yes
45232	ACTIVE	P	P053-00-3/136	Lift Shaft - Station Building - Russell Square Stn	Cable: Sheath	Asbestos	Presumed				12 x Trailing Cables (4 woven cables per lift shaft)		12		N	N
13566	ACTIVE	P	P053-00-3/201	Passage - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13567	ACTIVE	P	P053-00-3/202	Passage - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21829	ACTIVE	P	P053-00-3/202/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Russell Square Stn	Void	Asbestos	Surveyed – Not Detected				Vent above				Yes	
13568	ACTIVE	P	P053-00-3/236	Passage - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21830	ACTIVE	P	P053-00-3/236/FLR-01	Floor - 1 - Passage - Station Building - Russell Square Stn	Void	Asbestos	No Access: Presumed				Beneath Manhole					Yes



Hazardous Material Asset Register - Summary



P053-00 - Station Building - Russell Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13569	ACTIVE	P	P053-00-3/411	Disused Room - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13570	ACTIVE	P	P053-00-3/601	Stairs: Linear - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13571	ACTIVE	P	P053-00-3/602	Stairs: Linear - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21831	ACTIVE	P	P053-00-3/602/FLR-01	Floor - 1 - Linear Stairs - Station Building - Russell Square Stn	Void	Asbestos	No Access: Presumed				Beneath Hatch					Yes
13572	ACTIVE	P	P053-00-3/603	Stairs: Linear - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13573	ACTIVE	P	P053-00-3/604	Stairs: Linear - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13574	ACTIVE	P	P053-00-3/632	Stairs: Spiral - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13575	ACTIVE	P	P053-00-3/633	Stairs: Spiral - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13576	ACTIVE	P	P053-00-3/711	Relay Room - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21834	ACTIVE	P	P053-00-3/711	Relay Room - Station Building - Russell Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				Various Braided cables				N	N
21833	ACTIVE	P	P053-00-3/711	Relay Room - Station Building - Russell Square Stn	Other Boarding	Asbestos	Presumed				1x Paxoline Board	30	1		N	N
21832	ACTIVE	P	P053-00-3/711	Relay Room - Station Building - Russell Square Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Flood gate switch equipment No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within				N	N
23706	ACTIVE	P	P053-00-3/711/FLR-01	Floor - 1 - Relay Room - Station Building - Russell Square Stn	Void	Asbestos	No Access: Presumed				Beneath Hatch					Yes
13577	ACTIVE	P	P053-00-3/901	Equipment Room - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21942	ACTIVE	P	P053-00-3/901	Equipment Room - Station Building - Russell Square Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Various Floodgate Equipment No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within				N	N



Hazardous Material Asset Register - Summary



P053-00 - Station Building - Russell Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44278	ACTIVE	P	P053-00-3/901	Equipment Room - Station Building - Russell Square Stn	Caulking	Asbestos	Presumed				Sealed caulking throughout					
45221	ACTIVE	P	P053-00-3/901	Equipment Room - Station Building - Russell Square Stn	Cable Duct: Other	Asbestos	Known				Node point 34 to 36 - Vent Shaft - 1x Cable duct		1		N	N
21939	ACTIVE	P	P053-00-3/901	Equipment Room - Station Building - Russell Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				Braided cables going into 3/711				N	N
21940	ACTIVE	P	P053-00-3/901	Equipment Room - Station Building - Russell Square Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x Westinghouse box on the outside 3/711 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
21835	ACTIVE	P	P053-00-3/901/ FLR-01	Floor - 1 - Equipment Room - Station Building - Russell Square Stn	Void	Asbestos	No Access: Presumed				Beneath Hatches					Yes
21938	ACTIVE	P	P053-00-3/901/ WAL-001	Wall: Internal - 1 - Equipment Room - Station Building - Russell Square Stn	Cable Ducts: Bitumen	Asbestos	Presumed				2 x Bitumen ducts		2		N	N
21941	ACTIVE	P	P053-00-3/901/ WAL-001 80878129	Wall: Internal - 1 - Equipment Room - Station Building - Russell Square Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				2 x 30 amp Switch Boxes No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2		N	N
21943	ACTIVE	P	P053-00-3/902	Vent Shaft - Station Building - Russell Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				7 x braided cables to lift shaft		7		N	N
44277	ACTIVE	P	P053-00-3/902	Vent Shaft - Station Building - Russell Square Stn	Caulking	Asbestos	Presumed				Sealed caulking throughout					
13578	ACTIVE	P	P053-00-3/903	Substation Room - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13579	ACTIVE	P	P053-00-3/951	Disused Room - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21946	ACTIVE	P	P053-00-3/999	Vent Shaft - Station Building - Russell Square Stn	Caulking	Asbestos	Strongly Presumed				Tunnel rings - Passage down ladder hole to track				N	N
21944	ACTIVE	P	P053-00-3/999	Vent Shaft - Station Building - Russell Square Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x Fuse boxes - Insulation inside No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2		N	N
21945	ACTIVE	P	P053-00-3/999	Vent Shaft - Station Building - Russell Square Stn	Boarding: AIB	Asbestos	Known				0.5m² Cement panel at back of fuse boxes Cement - bonded material rather than medium density.		1		N	N
45233	ACTIVE	P	P053-00-4/136	Lift Shaft - Station Building - Russell Square Stn	Cable: Sheath	Asbestos	Presumed				12 x Trailing Cables (4 woven cables per lift shaft)		12		N	N



Hazardous Material Asset Register - Summary



P053-00 - Station Building - Russell Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13580	ACTIVE	p	P053-00-4/261	Platform 1 - Eastbound Local - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23656	ACTIVE	p	P053-00-4/261	Platform 1 - Eastbound Local - Station Building - Russell Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				Braided cables from invert within Riser Cupboard - Tail wall on platform No access within riser cupboard during traffic hours in 2020 re-inspection.					
21947	ACTIVE	p	P053-00-4/261	Platform 1 - Eastbound Local - Station Building - Russell Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				Braided cables Head wall on platform				N	N
21948	ACTIVE	p	P053-00-4/261	Platform 1 - Eastbound Local - Station Building - Russell Square Stn	Cable: Sheath	Asbestos	Known				Eastbound Invert - cable sleeves - platform side by headwall					
21952	ACTIVE	p	P053-00-4/261	Platform 1 - Eastbound Local - Station Building - Russell Square Stn	Westing house Boxes	Asbestos	Strongly Presumed				Eastbound Invert - Westlinghouse boxes x 3 - Pit Wall 15m up		3			
21951	ACTIVE	p	P053-00-4/261	Platform 1 - Eastbound Local - Station Building - Russell Square Stn	Caulking	Asbestos	Presumed				Eastbound Invert - Caulking sealed with concrete					
21949	ACTIVE	p	P053-00-4/261	Platform 1 - Eastbound Local - Station Building - Russell Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				Eastbound Invert - various cables					
21950	ACTIVE	p	P053-00-4/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Russell Square Stn	Cable: Sheath	Asbestos	Known				Eastbound Invert - Cable Sleeves in ceiling under 4/664 - Chrysotile					Y
13581	ACTIVE	p	P053-00-4/262	Platform 2 - Westbound Local - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21957	ACTIVE	p	P053-00-4/262	Platform 2 - Westbound Local - Station Building - Russell Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				Westbound Invert - various cables					
21956	ACTIVE	p	P053-00-4/262	Platform 2 - Westbound Local - Station Building - Russell Square Stn	Cable: Sheath	Asbestos	Known				Westbound Invert - 8 x Cables Sleeve near 4/711 - Chrysotile		8			
21955	ACTIVE	p	P053-00-4/262	Platform 2 - Westbound Local - Station Building - Russell Square Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westbound Invert - Westlinghouse box (2 cables) 20m on from 4/711					
21954	ACTIVE	p	P053-00-4/262	Platform 2 - Westbound Local - Station Building - Russell Square Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westbound Invert - Westlinghouse box (2 cables) Passage between invert					
21953	ACTIVE	p	P053-00-4/262	Platform 2 - Westbound Local - Station Building - Russell Square Stn	Cable: Sheath	Asbestos	Known				Eastbound Invert - Braided cables - Tail wall on platform				N	N



Hazardous Material Asset Register - Summary



P053-00 - Station Building - Russell Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44187	ACTIVE	P	P053-00-4/262	Platform 2 - Westbound Local - Station Building - Russell Square Stn	Cable Ducts: Cement	Asbestos	Presumed				Cement cable ducts going into invert at tail wall of platform		2		N	N
23717	ACTIVE	P	P053-00-4/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - Russell Square Stn	Cable: Sheath	Asbestos	Known				Westbound Invert - 3 x Cable Sleeves in Ceiling under 4/712 - Chrysotile		3			
13582	ACTIVE	P	P053-00-4/661	Relay Room - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21961	ACTIVE	P	P053-00-4/661/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - Russell Square Stn	Void	Asbestos	No Access: Presumed				Beneath Supalux panel				Yes	
21960	ACTIVE	P	P053-00-4/661/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - Russell Square Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel					
21958	ACTIVE	P	P053-00-4/661/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Russell Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				8 x Braided cables 1x 30 black, 3x 50m green, 2x15m, 2x5m black Walls 2 & 3		8		N	N
45234	ACTIVE	P	P053-00-4/661/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Russell Square Stn		Asbestos	Strongly Presumed				Racking signalling equipment - Wall 3				N	N
21959	ACTIVE	P	P053-00-4/661/WAL-003 80878174	Wall: Internal - 3 - Relay Room - Station Building - Russell Square Stn Wall: Internal	Cable: Sheath	Asbestos	Strongly Presumed				Wall 3 - 2 x Braided cables (50mm green)		2		N	N
44185	ACTIVE	P	P053-00-4/661/WAL-004 80878175	Wall: Internal - 4 - Relay Room - Station Building - Russell Square Stn Wall: Internal	Other Boarding	Asbestos	Presumed				Paxoline boarding within roller shutter cabinets x 11		11		N	N
44186	INACTIVE	P	P053-00-4/661/WAL-004 80878175	Wall: Internal - 4 - Relay Room - Station Building - Russell Square Stn Wall: Internal	PCBs	Polychlorinated biphenyl	Presumed				8 x black boxes PCBs		8		N	N
13583	ACTIVE	P	P053-00-4/662	Switch Room - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21962	ACTIVE	P	P053-00-4/662	Switch Room - Station Building - Russell Square Stn	Isolator Switches	Asbestos	Strongly Presumed				3 x Switch boxes 2x60, 1x100 amps No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		3		N	N
21963	ACTIVE	P	P053-00-4/662	Switch Room - Station Building - Russell Square Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
23718	ACTIVE	P	P053-00-4/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Russell Square Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel					



Hazardous Material Asset Register - Summary



P053-00 - Station Building - Russell Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13584	ACTIVE	P	P053-00-4/663	Switch Room - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
42881	ACTIVE	P	P053-00-4/664	Relay Room - Station Building - Russell Square Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Electrical box - WALL 2 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
21965	ACTIVE	P	P053-00-4/664	Relay Room - Station Building - Russell Square Stn	Other Electrical Boxes	Asbestos	Presumed				P- rectifier box		1		N	N
21964	ACTIVE	P	P053-00-4/664	Relay Room - Station Building - Russell Square Stn	Cable: Sheath	Asbestos	Not Found during Inspection				Braided cable into a small siemens box					
53984	ACTIVE	P	P053-00-4/664	Relay Room - Station Building - Russell Square Stn	Other Boarding	Asbestos	Surveyed – Not Detected				brown board to back of frame NAD - board appearance new					
53983	ACTIVE	P	P053-00-4/664	Relay Room - Station Building - Russell Square Stn	Other Boarding	Asbestos	Sampled – Not Detected				packing to the frame - small square - report R736151 - asbestos ID confirmed non asbestos			R736151		
53985	ACTIVE	P	P053-00-4/664	Relay Room - Station Building - Russell Square Stn	Other Electrical Boxes	Asbestos	Presumed				rectified board on front wall 2					
13585	ACTIVE	P	P053-00-4/664	Relay Room - Station Building - Russell Square Stn	Westing house Boxes	Asbestos	Presumed				Switch box wall 2		1		N	N
23945	ACTIVE	P	P053-00-4/664/ WAL-002 80878201	Wall: Internal - 2 - Relay Room - Station Building - Russell Square Stn Wall: Internal	Other Boarding	Asbestos	Strongly Presumed				Paxoline board bottom of bracket to clock relay		1		N	N
13586	ACTIVE	P	P053-00-4/665	Switch Room - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23719	ACTIVE	P	P053-00-4/665	Switch Room - Station Building - Russell Square Stn	Cable Duct: Other	Asbestos	Presumed				6 x Cement cable ducts		6		N	N
22022	ACTIVE	P	P053-00-4/665/ WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Russell Square Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1 x Bus Bar No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
22021	ACTIVE	P	P053-00-4/665/ WAL-001 80878213	Wall: Internal - 1 - Switch Room - Station Building - Russell Square Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				5x Switch Boxes 2x60, 2x100, 1x200 amp No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		5		N	N
22023	ACTIVE	P	P053-00-4/665/ WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Russell Square Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N



Hazardous Material Asset Register - Summary



P053-00 - Station Building - Russell Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13587	ACTIVE	P	P053-00-4/669	Switch Room - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22025	ACTIVE	P	P053-00-4/669	Switch Room - Station Building - Russell Square Stn	Isolator Switches	Asbestos	Strongly Presumed				3 x Switch Boxes 1x30, 2x60 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		3		N	N
22024	ACTIVE	P	P053-00-4/669	Switch Room - Station Building - Russell Square Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1 x Transformer box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
13588	ACTIVE	P	P053-00-4/670	Switch Room - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13589	ACTIVE	P	P053-00-4/671	Switch Cupboard - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22026	ACTIVE	P	P053-00-4/671	Switch Cupboard - Station Building - Russell Square Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Switch Cupboard Floor - Supalux around cable ducts					
22027	ACTIVE	P	P053-00-4/671	Switch Cupboard - Station Building - Russell Square Stn	Durasteel	Asbestos	Surveyed – Not Detected				Switch Cupboard Wall 1 - Durasteel (New)					
22028	ACTIVE	P	P053-00-4/671	Switch Cupboard - Station Building - Russell Square Stn	Isolator Switches	Asbestos	No Access: Presumed				Switch Cupboard - 4x Switch boxes 2x60, 2x30amps 4/671 not found - not on station plans. Possible typo?		4		N	N
13590	ACTIVE	P	P053-00-4/711	Relay Room - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22029	ACTIVE	P	P053-00-4/711	Relay Room - Station Building - Russell Square Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1x Transformer Box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
22030	ACTIVE	P	P053-00-4/711	Relay Room - Station Building - Russell Square Stn	Other Boarding	Asbestos	Presumed				Paxoline Board				N	N
44176	ACTIVE	P	P053-00-4/711/ WAL-001 80878238	Wall: Internal - 1 - Relay Room - Station Building - Russell Square Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				2 x transformer boxes No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2		N	N
42883	INACTIVE	P	P053-00-4/711/ WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Russell Square Stn	PCBs	Polychlorinated biphenyl	Presumed				4 X Blue Cylinder PCB's wall mounted		4		N	N



Hazardous Material Asset Register - Summary



P053-00 - Station Building - Russell Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13591	ACTIVE	P	P053-00-4/712	Relay Room - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44172	ACTIVE	P	P053-00-4/712 80143256	Relay Room - Station Building - Russell Square Stn Room Assets	Other Electrical Boxes	Asbestos	Presumed				Green electrical box to wall 3 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
44174	ACTIVE	P	P053-00-4/712 80143256	Relay Room - Station Building - Russell Square Stn Room Assets	Other Boarding	Asbestos	Presumed				11 x Paxoline boarding in roller shutter 2 - wall 3		11		N	N
22031	ACTIVE	P	P053-00-4/712	Relay Room - Station Building - Russell Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				2 x 50m braided cables entering 600v box -wall 1- into floor duct		2		N	N
22032	ACTIVE	P	P053-00-4/712	Relay Room - Station Building - Russell Square Stn	Cable: Sheath	Asbestos	Strongly Presumed				2 x 20m braided cables from Track wall 1 to 2		2		N	N
44173	ACTIVE	P	P053-00-4/712 80143256	Relay Room - Station Building - Russell Square Stn Room Assets	Cable: Sheath	Asbestos	Presumed				asbestos cables to bunch from invert going into equipment within roller shutter cabinet 2				N	N
53986	ACTIVE	P	P053-00-4/712	Relay Room - Station Building - Russell Square Stn	Cable: Sheath	Asbestos	Presumed				1x black earth cable at high level exiting from electrical box (running parallel to 2 green NAD cables) into 1st shutter cabinet on wall 3					
44175	INACTIVE	P	P053-00-4/712 80143256	Relay Room - Station Building - Russell Square Stn Room Assets	PCBs	Polychlorinated biphenyl	Presumed				8 x black boxes with suspected PCBs		8		N	N
22033	ACTIVE	P	P053-00-4/712/ WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Russell Square Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Paxoline Board - new board				N	N
45235	INACTIVE	P	P053-00-4/712/ WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Russell Square Stn		Asbestos	Strongly Presumed				Racking signalling equipment - Wall 4				N	N
64606	INACTIVE	P	P053-00-4/712/ WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Russell Square Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1 to wall fgjkhsdroujgsoi					
13592	ACTIVE	P	P053-00-A/048	Kitchen - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13593	ACTIVE	P	P053-00-A/131	LMR - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
22034	ACTIVE	P	P053-00-A/131	LMR - Station Building - Russell Square Stn	Other Electrical Boxes	Asbestos	Removed				3 x Control boxes, 3 fuse & electrical boards (3m²) During inspection found to have been removed by lift refurbishment project		3		N	N



Hazardous Material Asset Register - Summary



P053-00 - Station Building - Russell Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41752	ACTIVE	P	P053-00-A/131	LMR - Station Building - Russell Square Stn	Isolator Switches	Asbestos	Presumed				Walls - 3 x Combination Fuse Boxes No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within Photos taken from safest possible vantage point from equipment due to live lift machinery in the way.		3		N	N
41754	ACTIVE	P	P053-00-A/131	LMR - Station Building - Russell Square Stn	Durasteel	Asbestos	Sampled – Not Detected				4 x Durasteel panels to floor and storage box				N	N
41753	ACTIVE	P	P053-00-A/131/ BAS-001 81271836	Base: Detector - LMR - Station Building - Russell Square Stn Base: Detector	Other Electrical Boxes	Asbestos	Presumed				1x transformer box and 1x fuse box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within Limited access within live machinery. Photo from closest safe area		2		N	N
13594	ACTIVE	P	P053-00-A/236	Passage - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				No Access above false ceiling and below false floor, No Need to Re-Inspect					
23947	ACTIVE	P	P053-00-A/236	Passage - Station Building - Russell Square Stn	Void	Asbestos	No Access: Presumed				No Access above false ceiling and below false floor, No Need to Re-Inspect				Y	Y
44263	ACTIVE	P	P053-00-A/236	Passage - Station Building - Russell Square Stn	Other Boarding	Asbestos	Presumed				2no. LUL Heater - presumed asbestos backing panel No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
13595	ACTIVE	P	P053-00-A/237	Passage - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				No Access above false ceiling and below false floor, No Need to Re-Inspect					
22035	ACTIVE	P	P053-00-A/237	Passage - Station Building - Russell Square Stn	No Access	Asbestos	No Access: Presumed				No Access above false ceiling and below false floor, No Need to Re-Inspect					
13596	ACTIVE	P	P053-00-A/291	GSM Office - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				No Access above false ceiling and below false floor, No Need to Re-Inspect					
23725	ACTIVE	P	P053-00-A/291	GSM Office - Station Building - Russell Square Stn	No Access	Asbestos	No Access: Presumed				No Access above false ceiling and below false floor, No Need to Re-Inspect				Y	Y
13597	ACTIVE	P	P053-00-A/292	Store - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				No Access above false ceiling and below false floor, No Need to Re-Inspect					
22036	ACTIVE	P	P053-00-A/292	Store - Station Building - Russell Square Stn	No Access	Asbestos	No Access: Presumed				No Access above false ceiling and below false floor, No Need to Re-Inspect				Y	Y
13598	ACTIVE	P	P053-00-A/301	Office - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				No Access above false ceiling and below false floor, No Need to Re-Inspect					



Hazardous Material Asset Register - Summary



P053-00 - Station Building - Russell Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22037	ACTIVE	p	P053-00-A/301	Office - Station Building - Russell Square Stn	No Access	Asbestos	No Access: Presumed				No Access above false ceiling and below false floor, No Need to Re-Inspect				Y	Y
13599	ACTIVE	p	P053-00-A/316	Locker Room - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				No Access above false ceiling and below false floor, No Need to Re-Inspect					
23726	ACTIVE	p	P053-00-A/316	Locker Room - Station Building - Russell Square Stn	No Access	Asbestos	No Access: Presumed				No Access above false ceiling and below false floor, No Need to Re-Inspect				Y	Y
13600	ACTIVE	p	P053-00-A/417	Mess Room - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				No Access above false ceiling and below false floor, No Need to Re-Inspect					
23573	ACTIVE	p	P053-00-A/417	Mess Room - Station Building - Russell Square Stn	No Access	Asbestos	No Access: Presumed				No Access above false ceiling and below false floor, No Need to Re-Inspect				Y	Y
13601	ACTIVE	p	P053-00-A/418	Toilet: Female - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				No Access above false ceiling and below false floor, No Need to Re-Inspect					
22038	ACTIVE	p	P053-00-A/418	Toilet: Female - Station Building - Russell Square Stn	No Access	Asbestos	No Access: Presumed				No Access above false ceiling and below false floor, No Need to Re-Inspect				Y	Y
13602	ACTIVE	p	P053-00-A/419	Toilet: Male - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				No Access above false ceiling and below false floor, No Need to Re-Inspect					
22039	ACTIVE	p	P053-00-A/419	Toilet: Male - Station Building - Russell Square Stn	No Access	Asbestos	No Access: Presumed				No Access above false ceiling and below false floor, No Need to Re-Inspect				Y	Y
13603	ACTIVE	p	P053-00-A/568	Stairs: Linear - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				No Access above false ceiling and below false floor, No Need to Re-Inspect					
23727	ACTIVE	p	P053-00-A/568	Stairs: Linear - Station Building - Russell Square Stn	No Access	Asbestos	No Access: Presumed				No Access above false ceiling and below false floor, No Need to Re-Inspect				Y	Y
13604	ACTIVE	p	P053-00-A/576	Stairs: Linear - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				No Access above false ceiling and below false floor, No Need to Re-Inspect					
22040	ACTIVE	p	P053-00-A/576	Stairs: Linear - Station Building - Russell Square Stn	No Access	Asbestos	No Access: Presumed				No Access above false ceiling and below false floor, No Need to Re-Inspect				Y	Y
13605	ACTIVE	p	P053-00-A/661	Switch Cupboard - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				No Access above false ceiling and below false floor, No Need to Re-Inspect					
22041	ACTIVE	p	P053-00-A/661	Switch Cupboard - Station Building - Russell Square Stn	No Access	Asbestos	No Access: Presumed				No Access above false ceiling and below false floor, No Need to Re-Inspect				Y	Y
13606	ACTIVE	p	P053-00-A/776	Plant Room - Station Building - Russell Square Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				No Access Power Plant Room					
22042	ACTIVE	p	P053-00-A/776	Plant Room - Station Building - Russell Square Stn	No Access	Asbestos	No Access: Presumed				No Access Power Plant Room					



Hazardous Material Asset Register - Summary



P057-00 - Station Building - Covent Garden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13609	ACTIVE	P	P057-00-1/001	Booking Hall - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42129	ACTIVE	P	P057-00-1/001	Booking Hall - Station Building - Covent Garden Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel Panel, 1m² loose to wall of boarding within ticket hall	1			N	N
13610	ACTIVE	P	P057-00-1/011	Ticket Office - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22044	ACTIVE	P	P057-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles					
22043	ACTIVE	P	P057-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Covent Garden Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
22045	ACTIVE	P	P057-00-1/011/DOR-01	Door - 1 - Ticket Office - Station Building - Covent Garden Stn		Asbestos	Surveyed – Not Detected				Boarding on door - Supalux					
23728	ACTIVE	P	P057-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Floor Tiles					Yes
13611	ACTIVE	P	P057-00-1/021	POM - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23729	ACTIVE	P	P057-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Covent Garden Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				Yes	
22047	ACTIVE	P	P057-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Covent Garden Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
22046	ACTIVE	P	P057-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Tiles					Yes
13612	ACTIVE	P	P057-00-1/071	Circulation Area - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22050	ACTIVE	P	P057-00-1/071	Circulation Area - Station Building - Covent Garden Stn		Asbestos	Surveyed – Not Detected				Supalux panels above door to 1/396					
46372	ACTIVE	P	P057-00-1/071	Circulation Area - Station Building - Covent Garden Stn	Other Boarding	Asbestos	Sampled – Not Detected				Composite panels to ceiling	10		R679631	N	N
68264	ACTIVE	P	P057-00-1/071	Circulation Area - Station Building - Covent Garden Stn	Void	Asbestos	Surveyed – Not Detected				Above false ceiling			R679631	Y	
22051	ACTIVE	P	P057-00-1/071	Circulation Area - Station Building - Covent Garden Stn	Durasteel	Asbestos	Strongly Presumed				LIFTS 1, 2, 3, 4 - Panel above doors - Durasteel				N	N
22048	ACTIVE	P	P057-00-1/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Covent Garden Stn	Durasteel	Asbestos	Known				Durasteel panelling above false ceiling				Yes	N



Hazardous Material Asset Register - Summary



P057-00 - Station Building - Covent Garden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22049	ACTIVE	P	P057-00-1/071/CLG-02	Ceiling: Solid - 2 - Circulation Area - Station Building - Covent Garden Stn	Durasteel	Asbestos	Known				Durasteel panelling above false ceiling				Yes	N
13613	ACTIVE	P	P057-00-1/072	Circulation Area - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46373	ACTIVE	P	P057-00-1/072	Circulation Area - Station Building - Covent Garden Stn	Other Boarding	Asbestos	Sampled – Not Detected				Composite panels to ceiling	10		R679631	N	N
22056	ACTIVE	P	P057-00-1/072	Circulation Area - Station Building - Covent Garden Stn	Durasteel	Asbestos	Strongly Presumed				LIFTS 1, 2, 3, 4 - Panel above doors - Durasteel				N	N
22053	ACTIVE	P	P057-00-1/072/CLG-01	Ceiling: Suspended - 1 - Circulation Area - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
22052	ACTIVE	P	P057-00-1/072/CLG-01	Ceiling: Suspended - 1 - Circulation Area - Station Building - Covent Garden Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard panels					
22054	ACTIVE	P	P057-00-1/072/CLG-02	Ceiling: Solid - 2 - Circulation Area - Station Building - Covent Garden Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard panels					
22055	ACTIVE	P	P057-00-1/072/CLG-02	Ceiling: Solid - 2 - Circulation Area - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
23659	ACTIVE	P	P057-00-1/136	Lift Shaft - Station Building - Covent Garden Stn	Durasteel	Asbestos	Known				Durasteel panelling surrounding top of lift shaft				N	N
42125	ACTIVE	P	P057-00-1/137	Lift Shaft - Station Building - Covent Garden Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel panel, 1m², above access doors to LHS of Lift Shaft 4	1			N	N
42126	ACTIVE	P	P057-00-1/137	Lift Shaft - Station Building - Covent Garden Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel panel, 1m² above access doors to RHS of Lift Shaft 4	1			N	N
22057	ACTIVE	P	P057-00-1/137	Lift Shaft - Station Building - Covent Garden Stn	Durasteel	Asbestos	Known				Durasteel panelling surrounding top of lift shaft 3 - 4 Partially removed by Edenbeck ES5107a 06/05/2015					
42124	ACTIVE	P	P057-00-1/137	Lift Shaft - Station Building - Covent Garden Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel panel, 2.5m2 , to bottom of Shaft 4-3	2			N	N
42127	ACTIVE	P	P057-00-1/137	Lift Shaft - Station Building - Covent Garden Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel panel, 1m² above access doors to LHS of Lift Shaft 3	1			N	N
42128	ACTIVE	P	P057-00-1/137	Lift Shaft - Station Building - Covent Garden Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel panel, 1m² above access doors to RHS of Lift Shaft 3	1			N	N
13614	ACTIVE	P	P057-00-1/201	Passage - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22059	ACTIVE	P	P057-00-1/201	Passage - Station Building - Covent Garden Stn	Durasteel	Asbestos	Known				Durasteel panelling behind tiled walls				N	N



Hazardous Material Asset Register - Summary



P057-00 - Station Building - Covent Garden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22058	ACTIVE	P	P057-00-1/201/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Covent Garden Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
13615	ACTIVE	P	P057-00-1/237	Lobby - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22062	ACTIVE	P	P057-00-1/237	Lobby - Station Building - Covent Garden Stn	Durasteel	Asbestos	Known				Durasteel - Chrysotile				N	N
22060	ACTIVE	P	P057-00-1/237/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Covent Garden Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
22061	ACTIVE	P	P057-00-1/237/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Covent Garden Stn	Void	Asbestos	Surveyed – Not Detected				Supalux Boarding above metal grid				Yes	
23948	ACTIVE	P	P057-00-1/237/FLR-01	Floor - 1 - Lobby - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Tiles					Yes
13616	ACTIVE	P	P057-00-1/281	Station Supervisor Office - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22063	ACTIVE	P	P057-00-1/281	Station Supervisor Office - Station Building - Covent Garden Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
13617	ACTIVE	P	P057-00-1/396	SVC - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22067	ACTIVE	P	P057-00-1/396	SVC - Station Building - Covent Garden Stn	Lead/Leading	Lead Paint/Lead	Known				Pipe - Red gloss - 2m². Thickness : 0.03m² Analysis : 7.1%				N	N
22064	ACTIVE	P	P057-00-1/396/WAL-001	Wall: Internal - 1 - SVC - Station Building - Covent Garden Stn		Asbestos	Surveyed – Not Detected				Supalux boarding					
22065	ACTIVE	P	P057-00-1/396/WAL-003	Wall: Internal - 3 - SVC - Station Building - Covent Garden Stn		Asbestos	Surveyed – Not Detected				Supalux boarding					
22066	ACTIVE	P	P057-00-1/396/WAL-004	Wall: Internal - 4 - SVC - Station Building - Covent Garden Stn		Asbestos	Surveyed – Not Detected				Supalux boarding					
13618	ACTIVE	P	P057-00-1/402	Bin Store - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22068	ACTIVE	P	P057-00-1/402/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				No access to hatch				Yes	
13619	ACTIVE	P	P057-00-1/452	Tenancy - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P057-00 - Station Building - Covent Garden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22069	ACTIVE	P	P057-00-1/452/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Above metal ceiling				Yes	
23730	ACTIVE	P	P057-00-1/452/FLR-01	Floor - 1 - Tenancy - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Beneath metal floor					Yes
13620	ACTIVE	P	P057-00-1/631	Stairs: Spiral - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13621	ACTIVE	P	P057-00-1/633	Stairs: Spiral - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22070	ACTIVE	P	P057-00-1/633	Stairs: Spiral - Station Building - Covent Garden Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Boarding around vent unit - plasterboard / Fibreglass lagging					
13622	ACTIVE	P	P057-00-1/634	Stairs: Spiral - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23731	ACTIVE	P	P057-00-1/634/CLG-01	Ceiling: Solid - 1 - Spiral Stairs - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
22071	ACTIVE	P	P057-00-1/634/FLR-01	Floor - 1 - Spiral Stairs - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Beneath metal floor					Yes
22072	ACTIVE	P	P057-00-1/634/FLR-02	Floor - 2 - Spiral Stairs - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Beneath metal floor					Yes
13623	ACTIVE	P	P057-00-1/667	Switch Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22073	ACTIVE	P	P057-00-1/667/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				No access to hatch				Yes	
13624	ACTIVE	P	P057-00-1/761	Disused Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22074	ACTIVE	P	P057-00-1/761/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Covent Garden Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
22075	ACTIVE	P	P057-00-1/761/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles				Yes	
13625	ACTIVE	P	P057-00-1/786	Service Riser - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22076	ACTIVE	P	P057-00-1/786	Service Riser - Station Building - Covent Garden Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Vent unit boarding above door - plasterboard					



Hazardous Material Asset Register - Summary



P057-00 - Station Building - Covent Garden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13626	ACTIVE	P	P057-00-1/791	Service Riser - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23732	ACTIVE	P	P057-00-1/791	Service Riser - Station Building - Covent Garden Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
13627	ACTIVE	P	P057-00-1/901	Disused Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22077	ACTIVE	P	P057-00-1/901/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Above metal panelling				Yes	
13628	ACTIVE	P	P057-00-1/902	Disused Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22078	ACTIVE	P	P057-00-1/902/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Above metal panelling				Yes	
13629	ACTIVE	P	P057-00-1/903	Disused Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22079	ACTIVE	P	P057-00-1/903/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Above metal panelling				Yes	
13630	ACTIVE	P	P057-00-1/904	Disused Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13631	ACTIVE	P	P057-00-2/031	Mess Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22083	ACTIVE	P	P057-00-2/031	Mess Room - Station Building - Covent Garden Stn	Bitumen	Asbestos	Surveyed – Not Detected				Sink - acoustic panel		1			
22080	ACTIVE	P	P057-00-2/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Covent Garden Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
22081	ACTIVE	P	P057-00-2/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Covent Garden Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
22082	ACTIVE	P	P057-00-2/031/WAL-001	Wall: Internal - 1 - Mess Room - Station Building - Covent Garden Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LUL Heater - Foam insulation		1			
13632	ACTIVE	P	P057-00-2/082	Lobby - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P057-00 - Station Building - Covent Garden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22085	ACTIVE	P	P057-00-2/082	Lobby - Station Building - Covent Garden Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Supalux/Plasterboard & Textured Coating. Plasterboard to Riser by Cat Ladder					
22084	ACTIVE	P	P057-00-2/082	Lobby - Station Building - Covent Garden Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Supalux/Plasterboard & Textured Coating.					
13633	ACTIVE	P	P057-00-2/083	Lobby - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22086	ACTIVE	P	P057-00-2/083	Lobby - Station Building - Covent Garden Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
13634	ACTIVE	P	P057-00-2/201	Passage - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13635	ACTIVE	P	P057-00-2/236	Passage - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22088	ACTIVE	P	P057-00-2/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Covent Garden Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
22089	ACTIVE	P	P057-00-2/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Covent Garden Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
22087	ACTIVE	P	P057-00-2/236/FLR-01	Floor - 1 - Passage - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Beneath manhole covers					Yes
13636	ACTIVE	P	P057-00-2/238	Passage - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22090	ACTIVE	P	P057-00-2/238	Passage - Station Building - Covent Garden Stn		Asbestos	Surveyed – Not Detected				Plasterboard, Supalux by vents (<1m²)					
22092	ACTIVE	P	P057-00-2/238	Passage - Station Building - Covent Garden Stn		Asbestos	Surveyed – Not Detected				Plaster / supalux panels throughout					
23949	ACTIVE	P	P057-00-2/238/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
22091	ACTIVE	P	P057-00-2/238/CLG-02	Ceiling: Solid - 2 - Passage - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
13637	ACTIVE	P	P057-00-2/239	Passage - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22093	ACTIVE	P	P057-00-2/239/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Covent Garden Stn	Void	Asbestos	Surveyed – Not Detected				Above false ceiling			R679631	Yes	



Hazardous Material Asset Register - Summary



P057-00 - Station Building - Covent Garden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13638	ACTIVE	P	P057-00-2/318	Locker Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22094	ACTIVE	P	P057-00-2/318/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
13639	ACTIVE	P	P057-00-2/319	Toilet: Unisex - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22095	ACTIVE	P	P057-00-2/319/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
13640	ACTIVE	P	P057-00-2/320	Locker Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23733	ACTIVE	P	P057-00-2/320	Locker Room - Station Building - Covent Garden Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
13641	ACTIVE	P	P057-00-2/331	Mess Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22096	ACTIVE	P	P057-00-2/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Covent Garden Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
22097	ACTIVE	P	P057-00-2/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Covent Garden Stn	Void	Asbestos	Surveyed – Not Detected				Concrete. Metal tray work & plastic sheathed cables / Fibre glass lagged hot water pipes . No evidence of a bad strip beneath fibreglass - above false ceiling				Yes	
13642	ACTIVE	P	P057-00-2/407	Store - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22098	ACTIVE	P	P057-00-2/407/FLR-01	Floor - 1 - Store - Station Building - Covent Garden Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath Lino tiles					Yes
23734	ACTIVE	P	P057-00-2/407/FLR-01	Floor - 1 - Store - Station Building - Covent Garden Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino Tiles					
22101	ACTIVE	P	P057-00-2/407/WAL-002	Wall: Internal - 2 - Store - Station Building - Covent Garden Stn		Asbestos	Surveyed – Not Detected				Loose boarding - Supalux,					
22099	ACTIVE	P	P057-00-2/407/WAL-002	Wall: Internal - 2 - Store - Station Building - Covent Garden Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
22100	ACTIVE	P	P057-00-2/407/WAL-003	Wall: Internal - 3 - Store - Station Building - Covent Garden Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					



Hazardous Material Asset Register - Summary



P057-00 - Station Building - Covent Garden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13643	ACTIVE	P	P057-00-2/413	Store - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23735	ACTIVE	P	P057-00-2/413	Store - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				To hatch on wall					
13644	ACTIVE	P	P057-00-2/414	Store - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22102	ACTIVE	P	P057-00-2/414	Store - Station Building - Covent Garden Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
13645	ACTIVE	P	P057-00-2/416	Toilet: Male - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22103	ACTIVE	P	P057-00-2/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Above Metal Tiles				Yes	
13646	ACTIVE	P	P057-00-2/417	Toilet: Female - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22104	ACTIVE	P	P057-00-2/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Above Metal Tiles				Yes	
13647	ACTIVE	P	P057-00-2/418	Toilet: Unisex - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23736	ACTIVE	P	P057-00-2/418	Toilet: Unisex - Station Building - Covent Garden Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
13648	ACTIVE	P	P057-00-2/631	Stairs: Spiral - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13649	ACTIVE	P	P057-00-2/662	Switch Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22108	ACTIVE	P	P057-00-2/662	Switch Room - Station Building - Covent Garden Stn	Isolator Switches	Asbestos	Strongly Presumed				7 x Iron clad isolators W1 2 x 30 Amp, 1 x 30 Amp, 3 x 60 Amp, 1 x 100 Amp including Busbars walls 1 & 3 Isolators removed from 1no Switch Box 00277337/42		7		N	N
22106	ACTIVE	P	P057-00-2/662/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Covent Garden Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding					
22107	ACTIVE	P	P057-00-2/662/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Above Supalux Boarding				Yes	



Hazardous Material Asset Register - Summary



P057-00 - Station Building - Covent Garden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22105	ACTIVE	P	P057-00-2/662/FLR-01	Floor - 1 - Switch Room - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Beneath false floor					Yes
13650	ACTIVE	P	P057-00-2/664	Switch Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23950	ACTIVE	P	P057-00-2/664	Switch Room - Station Building - Covent Garden Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Vent unit - plasterboard, fibreglass lagging					
22109	ACTIVE	P	P057-00-2/664	Switch Room - Station Building - Covent Garden Stn	Isolator Switches	Asbestos	Strongly Presumed				Iron Clad Isolator 1 x 30 amp W2		1		N	N
44386	ACTIVE	P	P057-00-2/664/FLR-01 80863790	Floor - 1 - Switch Room - Station Building - Covent Garden Stn Floor	Other Electrical Boxes	Asbestos	Known				3no Transformer Boxes		3		N	N
13651	ACTIVE	P	P057-00-2/667	Switch Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22113	ACTIVE	P	P057-00-2/667/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
22112	ACTIVE	P	P057-00-2/667/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Covent Garden Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
22111	ACTIVE	P	P057-00-2/667/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Covent Garden Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard boarding					
22110	ACTIVE	P	P057-00-2/667/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Covent Garden Stn		Asbestos	Surveyed – Not Detected				Supalux					
13652	ACTIVE	P	P057-00-2/668	Switch Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13653	ACTIVE	P	P057-00-2/669	Switch Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13654	ACTIVE	P	P057-00-2/670	Switch Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13655	ACTIVE	P	P057-00-2/746	SCR - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22114	ACTIVE	P	P057-00-2/746/DOR-01	Door - 1 - SCR - Station Building - Covent Garden Stn		Asbestos	Surveyed – Not Detected				Supalux boarding around door					



Hazardous Material Asset Register - Summary



P057-00 - Station Building - Covent Garden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13656	ACTIVE	P	P057-00-2/748	SCR - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13657	ACTIVE	P	P057-00-2/761	SVC - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22117	ACTIVE	P	P057-00-2/761	SVC - Station Building - Covent Garden Stn	Gasket :Pipework	Asbestos	Presumed				10x Gasket between pipe flanges - Chrysotile ES7156 - refers to the removal of the gaskets to pipework and on re-inspection 09/05/2018 it is evident the pipework as been replaced but there is no record of how / when this work was carried out and if all gaskets were removed!				N	N
22118	ACTIVE	P	P057-00-2/761	SVC - Station Building - Covent Garden Stn	Lead/Leading	Lead Paint/Lead	Known				Pipe - Red gloss - 2m. Thickness : 0.03mm Analysis : 2.4% NB Condition issues to capped pipe Strongly Presumed to contain Lead paint.				N	N
22116	ACTIVE	P	P057-00-2/761/CLG-01	Ceiling: Solid - 1 - SVC - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Supalux panels to concrete slab, but is there a void above supalux panels? None evident during check to ceiling caused by water ingress see report R703951 (attached)				Yes	
22115	ACTIVE	P	P057-00-2/761/CLG-01	Ceiling: Solid - 1 - SVC - Station Building - Covent Garden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels, Plasterboard					
13658	ACTIVE	P	P057-00-2/776	Fan Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22123	ACTIVE	P	P057-00-2/776	Fan Room - Station Building - Covent Garden Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x Iron clad isolators		2		N	N
23737	ACTIVE	P	P057-00-2/776	Fan Room - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				To hatch on wall					
22122	ACTIVE	P	P057-00-2/776/CLG-01	Ceiling: Solid - 1 - Fan Room - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
22121	ACTIVE	P	P057-00-2/776/CLG-01	Ceiling: Solid - 1 - Fan Room - Station Building - Covent Garden Stn		Asbestos	Surveyed – Not Detected				Supalux boarding					
22119	ACTIVE	P	P057-00-2/776/WAL-003	Wall: Internal - 3 - Fan Room - Station Building - Covent Garden Stn		Asbestos	Surveyed – Not Detected				Supalux boarding					
22120	ACTIVE	P	P057-00-2/776/WAL-004	Wall: Internal - 4 - Fan Room - Station Building - Covent Garden Stn		Asbestos	Surveyed – Not Detected				Supalux boarding					



Hazardous Material Asset Register - Summary



P057-00 - Station Building - Covent Garden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13659	ACTIVE	P	P057-00-2/777	Plant Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13660	ACTIVE	P	P057-00-2/951	Lobby - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23738	ACTIVE	P	P057-00-2/951	Lobby - Station Building - Covent Garden Stn	Lead/Leading	Lead Paint/Lead	Known				Pipe - Red gloss - 5m². Thickness : 0.03m² Analysis : 2.7%				N	N
13661	ACTIVE	P	P057-00-2/952	Disused Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13662	ACTIVE	P	P057-00-3/201	Passage - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23574	ACTIVE	P	P057-00-3/201	Passage - Station Building - Covent Garden Stn	Durasteel	Asbestos	Strongly Presumed				LIFTS 1, 2, 3, 4 - Panel above doors - Durasteel				N	N
13663	ACTIVE	P	P057-00-3/202	Passage - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22124	ACTIVE	P	P057-00-3/202	Passage - Station Building - Covent Garden Stn	Durasteel	Asbestos	Strongly Presumed				LIFTS 1, 2, 3, 4 - Panel above doors - Durasteel				N	N
13664	ACTIVE	P	P057-00-3/203	Passage - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13665	ACTIVE	P	P057-00-3/303	Passage - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13666	ACTIVE	P	P057-00-3/411	CER - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13667	ACTIVE	P	P057-00-3/601	Stairs: Linear - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13668	ACTIVE	P	P057-00-3/602	Stairs: Linear - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13669	ACTIVE	P	P057-00-4/201	Passage - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13670	ACTIVE	P	P057-00-4/202	Passage - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P057-00 - Station Building - Covent Garden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13671	ACTIVE	p	P057-00-4/203	Passage - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13672	ACTIVE	p	P057-00-4/261	Platform 1 - Westbound Local - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23740	ACTIVE	p	P057-00-4/261	Platform 1 - Westbound Local - Station Building - Covent Garden Stn	Cable: Sheath	Asbestos	Strongly Presumed				Invert 1 WB - Cables - 11x10mm		11		N	N
22127	ACTIVE	p	P057-00-4/261	Platform 1 - Westbound Local - Station Building - Covent Garden Stn	Cable: Sheath	Asbestos	Strongly Presumed				Invert 1 WB - Cables -3x 30mm		3		N	N
22128	ACTIVE	p	P057-00-4/261	Platform 1 - Westbound Local - Station Building - Covent Garden Stn	Other Boarding	Asbestos	Known				Invert 1 WB - Boarding on floor - Pit Side - Chrysotile				N	N
22129	ACTIVE	p	P057-00-4/261	Platform 1 - Westbound Local - Station Building - Covent Garden Stn	Gasket :Pipework	Asbestos	Strongly Presumed				Invert 1 WB - Gasket material between metal pipe flanges				N	N
22131	ACTIVE	p	P057-00-4/261	Platform 1 - Westbound Local - Station Building - Covent Garden Stn	Cable: Sheath	Asbestos	Strongly Presumed				Invert 1 WB - Cables running Pit side & platform side of invert				N	N
45176	ACTIVE	p	P057-00-4/261	Platform 1 - Westbound Local - Station Building - Covent Garden Stn	Pit Blocks	Asbestos	Presumed				Asbestos - P - Pitblocks					
44387	ACTIVE	p	P057-00-4/261	Platform 1 - Westbound Local - Station Building - Covent Garden Stn	Cable: Sheath	Asbestos	Strongly Presumed				1x 50mm Cable to Westinghouse Box down into invert - head wall		1		N	N
22125	ACTIVE	p	P057-00-4/261	Platform 1 - Westbound Local - Station Building - Covent Garden Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse box		1		N	N
22130	ACTIVE	p	P057-00-4/261	Platform 1 - Westbound Local - Station Building - Covent Garden Stn	Cable: Sheath	Asbestos	Strongly Presumed				Invert 1 WB - Cables -4x 20mm		4		N	N
23739	ACTIVE	p	P057-00-4/261	Platform 1 - Westbound Local - Station Building - Covent Garden Stn	Cable: Sheath	Asbestos	Strongly Presumed				Invert 1 WB - 5x 20mm Cables - run from invert entrance all of the way along invert		5		N	N
22126	ACTIVE	p	P057-00-4/261	Platform 1 - Westbound Local - Station Building - Covent Garden Stn	Cable: Sheath	Asbestos	Strongly Presumed				Invert 1 WB - 2x 30mm - run from invert entrance all of the way along invert		2		N	N
13673	ACTIVE	p	P057-00-4/262	Platform 2 - Eastbound Local - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21967	ACTIVE	p	P057-00-4/262	Platform 2 - Eastbound Local - Station Building - Covent Garden Stn	Cable: Sheath	Asbestos	Strongly Presumed				Invert 2 EB - 1x 50mm - Cables run for 30m from invert entrance all along invert to 100m from entrance		1		N	N



Hazardous Material Asset Register - Summary



P057-00 - Station Building - Covent Garden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21968	ACTIVE	P	P057-00-4/262	Platform 2 - Eastbound Local - Station Building - Covent Garden Stn	Cable: Sheath	Asbestos	Strongly Presumed				Invert 2 EB - 4x 30mm - Cables run for 30m from invert entrance all along invert to 100m from entrance		4		N	N
21966	ACTIVE	P	P057-00-4/262	Platform 2 - Eastbound Local - Station Building - Covent Garden Stn	Cable: Sheath	Asbestos	Strongly Presumed				Invert 2 EB - 12x 10mm - Cables run for 30m from invert entrance all along invert to 100m from entrance		12		N	N
22132	ACTIVE	P	P057-00-4/262	Platform 2 - Eastbound Local - Station Building - Covent Garden Stn	No Access	Asbestos	No Access: Presumed				To metal trunking					
22133	ACTIVE	P	P057-00-4/262	Platform 2 - Eastbound Local - Station Building - Covent Garden Stn	Cable: Sheath	Asbestos	Known				Invert EB - 22no 20mm dia. Green Cables crossing invert by 4/712		1		N	Y
21969	ACTIVE	P	P057-00-4/262	Platform 2 - Eastbound Local - Station Building - Covent Garden Stn	Cable: Sheath	Asbestos	Strongly Presumed				Invert 2 EB - Cables at end wall of invert				N	N
22134	ACTIVE	P	P057-00-4/262	Platform 2 - Eastbound Local - Station Building - Covent Garden Stn	Lead/Leading	Lead Paint/Lead	Removed				Store box - Cream gloss - 0.7m². Thickness : 0.65mm Analysis : 1.4%				N	N
13674	ACTIVE	P	P057-00-4/381	Store - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13675	ACTIVE	P	P057-00-4/661	Switch Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21970	ACTIVE	P	P057-00-4/661/FLR-01	Floor - 1 - Switch Room - Station Building - Covent Garden Stn		Asbestos	Surveyed – Not Detected				Suplax boarding by wall 2					
21972	ACTIVE	P	P057-00-4/661/WAL-001 80864132	Wall: Internal - 1 - Switch Room - Station Building - Covent Garden Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				6x Iron clad isolators 3 x 200 amps, 3 x 60 amps including Busbars walls 1&3		6		N	N
21971	ACTIVE	P	P057-00-4/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Covent Garden Stn		Asbestos	Surveyed – Not Detected				Supalux boxing					
13676	ACTIVE	P	P057-00-4/666	Switch Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23657	ACTIVE	P	P057-00-4/666	Switch Room - Station Building - Covent Garden Stn	Isolator Switches	Asbestos	Strongly Presumed				1x Iron clad isolator 1 x 60 amps		1		N	N
21975	ACTIVE	P	P057-00-4/666	Switch Room - Station Building - Covent Garden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Corners of walls - Supalux Slats					
21977	ACTIVE	P	P057-00-4/666	Switch Room - Station Building - Covent Garden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Boarding by vent unit Supalux					



Hazardous Material Asset Register - Summary



P057-00 - Station Building - Covent Garden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21976	ACTIVE	P	P057-00-4/666/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Above false ceiling - photo on premises looks like a solid ceiling.				Yes	
21973	ACTIVE	P	P057-00-4/666/FLR-01	Floor - 1 - Switch Room - Station Building - Covent Garden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Boarding on floor Supalux					
21974	ACTIVE	P	P057-00-4/666/FLR-01	Floor - 1 - Switch Room - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				To hatch and beneath supalux					Yes
13677	ACTIVE	P	P057-00-4/668	Switch Cupboard - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21978	ACTIVE	P	P057-00-4/668	Switch Cupboard - Station Building - Covent Garden Stn	Cable: Wrap	Asbestos	Strongly Presumed				Electrical Equipment - 4 x 10mm - Wrapped Cables (SP) into Electrical box (P)		6			
13678	ACTIVE	P	P057-00-4/711	Relay Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44391	ACTIVE	P	P057-00-4/711 80143263	Relay Room - Station Building - Covent Garden Stn Room Assets	Other Boarding	Asbestos	Strongly Presumed				Paxoline boards to signal equipment and shelf		9		N	N
21982	ACTIVE	P	P057-00-4/711	Relay Room - Station Building - Covent Garden Stn	Lead/Leading	Lead Paint/Lead	Known				Box - Green gloss - 0.3m². Thickness : 0.53mm Analysis : 1.3%				N	N
21979	ACTIVE	P	P057-00-4/711/FLR-01	Floor - 1 - Relay Room - Station Building - Covent Garden Stn		Asbestos	Surveyed – Not Detected				Supalux boarding					
44390	ACTIVE	P	P057-00-4/711/WAL-001 80864157	Wall: Internal - 1 - Relay Room - Station Building - Covent Garden Stn Wall: Internal	Cable Duct: Other	Asbestos	Presumed				Cable ducts - sealed - within roller shutter cabinet - to invert				N	N
21981	ACTIVE	P	P057-00-4/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Covent Garden Stn	Cable: Sheath	Asbestos	Strongly Presumed				1 x Cable		1		N	N
44388	ACTIVE	P	P057-00-4/711/WAL-001 80864157	Wall: Internal - 1 - Relay Room - Station Building - Covent Garden Stn Wall: Internal	Cable: Sheath	Asbestos	Strongly Presumed				Multiple cables within roller shutter into invert		9		N	N
44389	INACTIVE	P	P057-00-4/711/WAL-001 80864157	Wall: Internal - 1 - Relay Room - Station Building - Covent Garden Stn Wall: Internal	PCBs	Polychlorinated biphenyl	Presumed				6no Black Boxes within roller shutter cabinet		6		N	N
21980	ACTIVE	P	P057-00-4/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Covent Garden Stn	Cable: Sheath	Asbestos	Strongly Presumed				9 x Cables - Slight damage		9		N	N
13679	ACTIVE	P	P057-00-4/712	Relay Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21983	ACTIVE	P	P057-00-4/712	Relay Room - Station Building - Covent Garden Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse box		1		N	N



Hazardous Material Asset Register - Summary



P057-00 - Station Building - Covent Garden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44398	ACTIVE	P	P057-00-4/712 80143264	Relay Room - Station Building - Covent Garden Stn Room Assets	Other Boarding	Asbestos	Presumed				Paxoline boarding to wrack wall 3 by entrance				N	N
44396	ACTIVE	P	P057-00-4/712 80143264	Relay Room - Station Building - Covent Garden Stn Room Assets	Other Boarding	Asbestos	Presumed				Paxoline to numerous cable boxes with roller shutter cabinet				N	N
44395	ACTIVE	P	P057-00-4/712 80143264	Relay Room - Station Building - Covent Garden Stn Room Assets	Cable: Sheath	Asbestos	Strongly Presumed				Numerous sheathed green cables within roller shutter cabinet				N	N
21986	ACTIVE	P	P057-00-4/712 80143264	Relay Room - Station Building - Covent Garden Stn Room Assets	Lead/Leading	Lead Paint/Lead	Known				Walls - Cream gloss - 4m². Thickness : 0.18mm Analysis : 9.44% poor condition paint heavily flaked				N	N
44397	INACTIVE	P	P057-00-4/712 80143264	Relay Room - Station Building - Covent Garden Stn Room Assets	PCBs	Polychlorinated biphenyl	Presumed				5 x black boxes with roller shutter cabinet		5		N	N
23720	ACTIVE	P	P057-00-4/712/ FLR-01	Floor - 1 - Relay Room - Station Building - Covent Garden Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding					
21985	ACTIVE	P	P057-00-4/712/ WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Covent Garden Stn	Cable: Sheath	Asbestos	Strongly Presumed				2x Cables		2		N	N
21984	ACTIVE	P	P057-00-4/712/ WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Covent Garden Stn	Cable: Sheath	Asbestos	Strongly Presumed				1x 30mm Cable going into Wall 3		1		N	N
13680	ACTIVE	P	P057-00-4/713	Relay Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23946	ACTIVE	P	P057-00-4/713	Relay Room - Station Building - Covent Garden Stn	Westing house Boxes	Asbestos	Strongly Presumed				2 x Westinghouse box		2		N	N
44394	ACTIVE	P	P057-00-4/713/ WAL-001 80864176	Wall: Internal - 1 - Relay Room - Station Building - Covent Garden Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				Transformer box		1		N	N
44393	ACTIVE	P	P057-00-4/713/ WAL-001 80864176	Wall: Internal - 1 - Relay Room - Station Building - Covent Garden Stn Wall: Internal	Other Boarding	Asbestos	Presumed				Paxoline boarding x3		3		N	N
23721	ACTIVE	P	P057-00-4/713/ WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Covent Garden Stn		Asbestos	Surveyed – Not Detected				Supalux panel					
13681	ACTIVE	P	P057-00-4/731	Switch Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21987	ACTIVE	P	P057-00-4/731/ FLR-01	Floor - 1 - Switch Room - Station Building - Covent Garden Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, ceramic cable sleeves beneath computer tiles					Yes
13682	ACTIVE	P	P057-00-4/732	CER - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P057-00 - Station Building - Covent Garden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
21988	ACTIVE	P	P057-00-4/732/FLR-01	Floor - 1 - CER - Station Building - Covent Garden Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
13683	ACTIVE	P	P057-00-4/733	CER - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21990	ACTIVE	P	P057-00-4/733	CER - Station Building - Covent Garden Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x Iron clad isolators 2 x 60 amps		2		N	N
21989	ACTIVE	P	P057-00-4/733/FLR-01	Floor - 1 - CER - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Beneath computer tiles					Yes
23722	ACTIVE	P	P057-00-4/733/WAL-002	Wall: Internal - 2 - CER - Station Building - Covent Garden Stn	Cable: Sheath	Asbestos	Strongly Presumed				5 x Cables		5		N	N
44392	ACTIVE	P	P057-00-4/733/WAL-002 80864198	Wall: Internal - 2 - CER - Station Building - Covent Garden Stn Wall: Internal	Other Boarding	Asbestos	Presumed				Paxoline board x2		2		N	N
13684	ACTIVE	P	P057-00-4/761	Computer Equipment Cupboard - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21991	ACTIVE	P	P057-00-4/761	Computer Equipment Cupboard - Station Building - Covent Garden Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
13685	ACTIVE	P	P057-00-4/762	Computer Equipment Cupboard - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21992	ACTIVE	P	P057-00-4/762	Computer Equipment Cupboard - Station Building - Covent Garden Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
13686	ACTIVE	P	P057-00-4/763	Computer Equipment Cupboard - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21993	ACTIVE	P	P057-00-4/763	Computer Equipment Cupboard - Station Building - Covent Garden Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
13687	ACTIVE	P	P057-00-4/951	Plant Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13688	ACTIVE	P	P057-00-A/131	LMR - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21995	ACTIVE	P	P057-00-A/131	LMR - Station Building - Covent Garden Stn	Gasket :Pipework	Asbestos	No Access: Presumed				4x gaskets very old motor for all lifts 1 to 4 - Full Access NOT POSSIBLE					
21996	ACTIVE	P	P057-00-A/131	LMR - Station Building - Covent Garden Stn	Other Electrical Boxes	Asbestos	No Access: Presumed				4 x Power & Relay controller of lift 1 to 4 - Full Access NOT POSSIBLE		4			
21994	ACTIVE	P	P057-00-A/131	LMR - Station Building - Covent Garden Stn	Lead/Leading	Lead Paint/Lead	Known				Steps - Yellow gloss - 0.8m². Thickness : 0.10mm Analysis : 2.7%				N	N



Hazardous Material Asset Register - Summary



P057-00 - Station Building - Covent Garden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13689	ACTIVE	P	P057-00-A/132	Switch Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
21998	ACTIVE	P	P057-00-A/132/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Above Metal Boarding				Yes	
21997	ACTIVE	P	P057-00-A/132/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Covent Garden Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Boarding - Plasterboard					
13690	ACTIVE	P	P057-00-A/133	Switch Room - Station Building - Covent Garden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44400	ACTIVE	P	P057-00-A/133	Switch Room - Station Building - Covent Garden Stn	Mastic	Asbestos	Presumed				Mastic to flange on fan ducting on ceiling		1		N	N
22001	ACTIVE	P	P057-00-A/133	Switch Room - Station Building - Covent Garden Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x Iron Clad Isolators		2		N	N
22000	ACTIVE	P	P057-00-A/133/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Above Metal Cladding				Yes	
21999	ACTIVE	P	P057-00-A/133/FLR-01	Floor - 1 - Switch Room - Station Building - Covent Garden Stn	Void	Asbestos	No Access: Presumed				Beneath false floor					Yes
44399	ACTIVE	P	P057-00-A/133/WAL-003 80864269	Wall: Internal - 3 - Switch Room - Station Building - Covent Garden Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				1x transformer box W3		1		N	N

P067-00 - Station Building - Hyde Park Corner Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13940	ACTIVE	P	P067-00-1/601	Stairs: Linear - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13941	ACTIVE	P	P067-00-1/602	Stairs: Linear - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13942	ACTIVE	P	P067-00-1/603	Stairs: Linear - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13943	ACTIVE	P	P067-00-1/631	Stairs: Spiral - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22816	ACTIVE	P	P067-00-1/631/FLR-01	Floor - 1 - Spiral Stairs - Station Building - Hyde Park Corner Stn	Void	Asbestos	No Access: Presumed				Beneath floor hatch					Yes



Hazardous Material Asset Register - Summary



P067-00 - Station Building - Hyde Park Corner Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13944	ACTIVE	P	P067-00-2/001	Booking Hall - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22818	ACTIVE	P	P067-00-2/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Hyde Park Corner Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
23076	ACTIVE	P	P067-00-2/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				Above false ceiling on beams - white gloss - 70m². Thickness : 0.59mm Analysis : 1.79%				Yes	
22817	ACTIVE	P	P067-00-2/001/FLR-01	Floor - 1 - Booking Hall - Station Building - Hyde Park Corner Stn	Void	Asbestos	No Access: Presumed				Beneath floor hatch					Yes
13945	ACTIVE	P	P067-00-2/011	Ticket Office - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23079	ACTIVE	P	P067-00-2/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Hyde Park Corner Stn	Void	Asbestos	Surveyed – Not Detected				Concrete metal beams & fibreglass lagging above supalux tiles				Yes	
23078	ACTIVE	P	P067-00-2/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
23080	ACTIVE	P	P067-00-2/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				Above false ceiling, metal coated beam - red gloss - 8m². Thickness : too thin analysis : 27.0%					
23077	ACTIVE	P	P067-00-2/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Hyde Park Corner Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
13946	ACTIVE	P	P067-00-2/021	POM - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23082	ACTIVE	P	P067-00-2/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				On all pipes & ceiling on sprinkler system - red gloss - 7m². Thickness : 0.09mm Analysis : 2.5%					
23081	ACTIVE	P	P067-00-2/021/FLR-01	Floor - 1 - POM - Station Building - Hyde Park Corner Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
23083	ACTIVE	P	P067-00-2/021/WAL-003	Wall: Internal - 3 - POM - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Supalux boxing around ventilation systems & metal cable sleeves					
13947	ACTIVE	P	P067-00-2/031	Mess Room - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23085	ACTIVE	P	P067-00-2/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Hyde Park Corner Stn	Void	Asbestos	Surveyed – Not Detected				Supalux Tiles above false ceiling				Yes	N



Hazardous Material Asset Register - Summary



P067-00 - Station Building - Hyde Park Corner Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23084	ACTIVE	P	P067-00-2/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
23086	ACTIVE	P	P067-00-2/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				Above false ceiling, metal coated beam - red gloss - 12m2. Thickness : too thin analysis : 27.0%				Yes	N
23087	ACTIVE	P	P067-00-2/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				Sprinkler system wall 2 - red gloss - 2m2. Thickness : 0.09mm Analysis : 2.5%					
23609	ACTIVE	P	P067-00-2/031/FLR-01	Floor - 1 - Mess Room - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Supalux panel by wall 3					
23088	ACTIVE	P	P067-00-2/031/FLR-01	Floor - 1 - Mess Room - Station Building - Hyde Park Corner Stn	Void	Asbestos	No Access: Presumed				Beneath supalux panel				N	Yes
23089	ACTIVE	P	P067-00-2/031/WAL-001	Wall: Internal - 1 - Mess Room - Station Building - Hyde Park Corner Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				2 x LTB heaters, foam panels within		2		N	N
23090	ACTIVE	P	P067-00-2/031/WAL-002	Wall: Internal - 2 - Mess Room - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Supalux ceiling tiles by floor					
23091	ACTIVE	P	P067-00-2/031/WAL-004	Wall: Internal - 4 - Mess Room - Station Building - Hyde Park Corner Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				2 x LTB heaters, foam panels within		2		N	N
13948	ACTIVE	P	P067-00-2/036	Toilet: Unisex - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23835	ACTIVE	P	P067-00-2/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Hyde Park Corner Stn	Void	Asbestos	Surveyed – Not Detected				Metal vent ducts, metal beams above Supalux tiles				Yes	
23093	ACTIVE	P	P067-00-2/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
23092	ACTIVE	P	P067-00-2/036/WAL-002	Wall: Internal - 2 - Toilet - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Supalux panel					
13949	ACTIVE	P	P067-00-2/053	Mess Room - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23094	ACTIVE	P	P067-00-2/053/WAL-001	Wall: Internal - 1 - Mess Room - Station Building - Hyde Park Corner Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				2 x LTB heaters, foam panels		2		N	N
13950	ACTIVE	P	P067-00-2/054	Lobby - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P067-00 - Station Building - Hyde Park Corner Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23095	ACTIVE	P	P067-00-2/054/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				Ceiling & metal pipes - Black gloss - 5m². Thickness : 0.10mm Analysis : 12.4%					
13951	ACTIVE	P	P067-00-2/071	Circulation Area - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23097	ACTIVE	P	P067-00-2/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Hyde Park Corner Stn	Void	Asbestos	Sampled – Not Detected				Above metal ceiling - Debris on/ under RSJ/ on ceiling tile & seal debris to girder in ceiling void above escalator 1&3 - NADIS. Seal debris to old fire break in ceiling void in same area as above entry - NADIS. Above Escalator 1 - seal debris in old fire break LHS of girder & debris on ceiling tiles - NADIS				Yes	
23096	ACTIVE	P	P067-00-2/071/FLR-01	Floor - 1 - Circulation Area - Station Building - Hyde Park Corner Stn	Void	Asbestos	No Access: Presumed				Beneath 3x hatches in front of barriers and floor plates by escalators				N	Yes
13952	ACTIVE	P	P067-00-2/081	Lobby - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23099	ACTIVE	P	P067-00-2/081	Lobby - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				Metal beam - red gloss - 2m². Thickness : Too thin Analysis : 2.1%					
23098	ACTIVE	P	P067-00-2/081/WAL-001	Wall: Internal - 1 - Lobby - Station Building - Hyde Park Corner Stn	Void	Asbestos	No Access: Presumed				Above Supalux boxing					
23836	ACTIVE	P	P067-00-2/081/WAL-001	Wall: Internal - 1 - Lobby - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Supalux boxing by walls 1 & 2					
13953	ACTIVE	P	P067-00-2/151	UMC - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23100	ACTIVE	P	P067-00-2/151	UMC - Station Building - Hyde Park Corner Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel storage box - NADIS,		1			
23106	ACTIVE	P	P067-00-2/151	UMC - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				Floor & banisters - grey gloss - 13x 9m2. Thickness : 0.20mm Analysis : 6.19% floor has been over painted					
23104	ACTIVE	P	P067-00-2/151	UMC - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				Sprinkler - red gloss - 20m2. Thickness : 0.09mm Analysis : 2.5%					
23109	ACTIVE	P	P067-00-2/151	UMC - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				RSJ's - green gloss. Thickness : 0.54mm Analysis : 8.2%					
23108	ACTIVE	P	P067-00-2/151	UMC - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				Metal lagging - red gloss - 20m 2. Thickness : 0.54mm Analysis : 8.2%					
23107	ACTIVE	P	P067-00-2/151	UMC - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				Beams metal - grey gloss - 20m2. Thickness : 0.20mm Analysis : 6.19%					



Hazardous Material Asset Register - Summary



P067-00 - Station Building - Hyde Park Corner Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23105	ACTIVE	P	P067-00-2/151	UMC - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				Sprinkler - red gloss - 20m2. Thickness : 0.09mm Analysis : 2.5%					
23101	ACTIVE	P	P067-00-2/151/CLG-01	Ceiling: Solid - 1 - UMC - Station Building - Hyde Park Corner Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Approx 12 x cable sleeves - ceiling by wall 2		12			
23102	ACTIVE	P	P067-00-2/151/WAL-002	Wall: Internal - 2 - UMC - Station Building - Hyde Park Corner Stn	Cable Duct: Other	Asbestos	Strongly Presumed				3 x Cable sleeves - wall 2 Sample identified in Maximo Reference 23101.		3			
23103	ACTIVE	P	P067-00-2/151/WAL-003	Wall: Internal - 3 - UMC - Station Building - Hyde Park Corner Stn	Isolator Switches	Asbestos	Strongly Presumed				Fuse switches		1		N	N
13954	ACTIVE	P	P067-00-2/201	Passage - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23110	ACTIVE	P	P067-00-2/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Hyde Park Corner Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above metal tiles				Yes	N
13955	ACTIVE	P	P067-00-2/202	Passage - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23111	ACTIVE	P	P067-00-2/202/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Hyde Park Corner Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above metal tiles				Yes	N
13956	ACTIVE	P	P067-00-2/236	Passage - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23114	ACTIVE	P	P067-00-2/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				Above false ceiling on sprinkler system - red gloss - 5m². Thickness : 0.09mm Analysis : 2.5%				Yes	
23115	ACTIVE	P	P067-00-2/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				On beams & walls above false ceiling - cream gloss - 6m². Thickness : Too thin Analysis : 2.1%				Yes	
23112	ACTIVE	P	P067-00-2/236/FLR-01	Floor - 1 - Passage - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
23113	ACTIVE	P	P067-00-2/236/FLR-01	Floor - 1 - Passage - Station Building - Hyde Park Corner Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
13957	ACTIVE	P	P067-00-2/237	Passage - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23117	ACTIVE	P	P067-00-2/237/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Hyde Park Corner Stn	Void	Asbestos	Surveyed – Not Detected				Metal pipes and trunking, supalux boxing above fibreboard ceiling				Yes	
23837	ACTIVE	P	P067-00-2/237/FLR-01	Floor - 1 - Passage - Station Building - Hyde Park Corner Stn	Void	Asbestos	No Access: Presumed				Beneath 2 x hatches					Yes



Hazardous Material Asset Register - Summary



P067-00 - Station Building - Hyde Park Corner Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23116	ACTIVE	P	P067-00-2/237/WAL-003	Wall: Internal - 3 - Passage - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Supalux boxing & fibreboard					
13958	ACTIVE	P	P067-00-2/238	Lobby - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23120	ACTIVE	P	P067-00-2/238	Lobby - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				Sprinkler system on wall & ceiling - red gloss - 2m². Thickness : 0.09mm Analysis : 2.5%					
23119	INACTIVE	P	P067-00-2/238/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				Sprinkler system on wall & ceiling - red gloss - 2m². Thickness : 0.09mm Analysis : 2.5%					
23118	ACTIVE	P	P067-00-2/238/WAL-003	Wall: Internal - 3 - Lobby - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				1x Supalux panel					
13959	ACTIVE	P	P067-00-2/239	Passage - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23838	ACTIVE	P	P067-00-2/239/WAL-005	Wall: Internal - 5 - Passage - Station Building - Hyde Park Corner Stn	Void	Asbestos	No Access: Presumed				Behind 2 x metal hatch covers					
13960	ACTIVE	P	P067-00-2/240	Passage - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23121	ACTIVE	P	P067-00-2/240	Passage - Station Building - Hyde Park Corner Stn	Void	Asbestos	No Access: Presumed				Wall 5 - Behind 2 x metal hatch covers					
13961	ACTIVE	P	P067-00-2/241	Passage - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13962	ACTIVE	P	P067-00-2/281	Station Supervisor Office - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23125	ACTIVE	P	P067-00-2/281	Station Supervisor Office - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Surveyed – Not Detected				Sprinkler - red gloss - 4m². Thickness : 0.09mm Analysis : 2.5% Not found in this room, room clear based on re-Inspection 2016					
23123	ACTIVE	P	P067-00-2/281/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Hyde Park Corner Stn	Void	Asbestos	Surveyed – Not Detected				Concrete conduits above false ceiling				Yes	
23122	ACTIVE	P	P067-00-2/281/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Supalux / Fibreboard					
23124	ACTIVE	P	P067-00-2/281/WAL-007	Wall: Internal - 7 - Station Supervisor Office - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Supalux boxing					



Hazardous Material Asset Register - Summary



P067-00 - Station Building - Hyde Park Corner Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13963	ACTIVE	P	P067-00-2/411	Locker Room - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23999	ACTIVE	P	P067-00-2/411	Locker Room - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				Sprinkler - red gloss - 3m². Thickness : 0.09mm Analysis : 2.5%					
23839	ACTIVE	P	P067-00-2/411/ WAL-001	Wall: Internal - 1 - Locker Room - Station Building - Hyde Park Corner Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - 2 fx oam panels within		2			
13964	ACTIVE	P	P067-00-2/412	Store - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22924	ACTIVE	P	P067-00-2/412/ CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Supalux panels					
22925	ACTIVE	P	P067-00-2/412/ CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Hyde Park Corner Stn	Void	Asbestos	No Access: Presumed				Above Supalux panels				Yes	
22926	ACTIVE	P	P067-00-2/412/ WAL-002	Wall: Internal - 2 - Store - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				Sprinkler wall 2 - red gloss - 3m². Thickness : 0.09mm Analysis : 2.5%					
13965	ACTIVE	P	P067-00-2/413	Disused Room - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13966	ACTIVE	P	P067-00-2/414	Store - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13967	ACTIVE	P	P067-00-2/417	Toilet: Unisex - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22928	ACTIVE	P	P067-00-2/417/ CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Supalux boxing & supalux tiles					
22929	ACTIVE	P	P067-00-2/417/ CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Hyde Park Corner Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
22927	ACTIVE	P	P067-00-2/417/ FLR-01	Floor - 1 - Toilet - Station Building - Hyde Park Corner Stn	Void	Asbestos	No Access: Presumed				Beneath Lino					Yes
13968	ACTIVE	P	P067-00-2/418	Toilet: Unisex - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22931	ACTIVE	P	P067-00-2/418/ CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				Ceiling & metal pipes - Black gloss - 5m². Thickness : 0.10mm Analysis : 12.4%					



Hazardous Material Asset Register - Summary



P067-00 - Station Building - Hyde Park Corner Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22930	ACTIVE	P	P067-00-2/418/FLR-01	Floor - 1 - Toilet - Station Building - Hyde Park Corner Stn	Void	Asbestos	Surveyed – Not Detected				Metal pipes below manhole					Yes
13969	ACTIVE	P	P067-00-2/451	Tenancy - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22932	ACTIVE	P	P067-00-2/451/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Hyde Park Corner Stn	Void	Asbestos	No Access: Presumed				Above metal tiles				Yes	
13970	ACTIVE	P	P067-00-2/453	ATM - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22933	INACTIVE	P	P067-00-2/453/CLG-01	Ceiling: Suspended - 1 - ATM - Station Building - Hyde Park Corner Stn	Void	Asbestos	No Access: Presumed				Above Metal girders. High level boxing vermiculite - no asbestos detected.				Yes	
13971	ACTIVE	P	P067-00-2/631	Stairs: Spiral - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22935	ACTIVE	P	P067-00-2/631	Stairs: Spiral - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				Pillar - white gloss - 40m². Thickness : 0.38mm Analysis : 6.23%					
22934	ACTIVE	P	P067-00-2/631	Stairs: Spiral - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				Banister - white gloss - 40m². Thickness : 0.38mm Analysis : 6.23%					
23995	INACTIVE	P	P067-00-2/631/FLR-01	Floor - 1 - Spiral Stairs - Station Building - Hyde Park Corner Stn	Void	Asbestos	No Access: Presumed				Beneath metal floor					Yes
13972	ACTIVE	P	P067-00-2/661	Switch Room - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13973	ACTIVE	P	P067-00-2/664	Switch Cupboard - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22938	ACTIVE	P	P067-00-2/664	Switch Cupboard - Station Building - Hyde Park Corner Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Switch Cupboard - Trunking					
22937	ACTIVE	P	P067-00-2/664	Switch Cupboard - Station Building - Hyde Park Corner Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Cupboard - Wall 2 8x Iron clad isolators - 3 x 200 amps, 1 x 60 amps, 3 x 100 amps, 1 x 30 amps (not in maximo)		8			
22936	ACTIVE	P	P067-00-2/664	Switch Cupboard - Station Building - Hyde Park Corner Stn	Durasteel	Asbestos	Surveyed – Not Detected				Switch Cupboard - Wall 1 & 4 Durasteel					
13974	ACTIVE	P	P067-00-2/666	Switch Room - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22939	INACTIVE	P	P067-00-2/666/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Hyde Park Corner Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	



Hazardous Material Asset Register - Summary



P067-00 - Station Building - Hyde Park Corner Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43129	ACTIVE	P	P067-00-2/666/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Hyde Park Corner Stn	Other Electrical Boxes	Asbestos	Presumed				3 Transformer boxes W1 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within				N	N
22942	ACTIVE	P	P067-00-2/666/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Hyde Park Corner Stn	Isolator Switches	Asbestos	Strongly Presumed				1x Iron clad isolators		1			
22940	ACTIVE	P	P067-00-2/666/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Supalux boxing					
22941	ACTIVE	P	P067-00-2/666/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Hyde Park Corner Stn	Isolator Switches	Asbestos	Strongly Presumed				6 x Iron clad isolators - 1 x 100 amps, 5 x 60 amps, 1 x 30 amp		6			
22943	ACTIVE	P	P067-00-2/666/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Hyde Park Corner Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Trunking		1			
13975	ACTIVE	P	P067-00-2/667	Switch Room - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23821	ACTIVE	P	P067-00-2/667/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Hyde Park Corner Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Trunking		1			
22944	ACTIVE	P	P067-00-2/667/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Hyde Park Corner Stn	Isolator Switches	Asbestos	Strongly Presumed				5x Iron clad isolators - 3 x 60 amps, 1 x 200 amps, 1 x 30 amps		5			
13976	ACTIVE	P	P067-00-2/731	CER - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22945	ACTIVE	P	P067-00-2/731/WAL-002	Wall: Internal - 2 - CER - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				2 x supalux panels					
22946	ACTIVE	P	P067-00-2/731/WAL-003	Wall: Internal - 3 - CER - Station Building - Hyde Park Corner Stn	Westing house Boxes	Asbestos	Surveyed – Not Detected									
13977	ACTIVE	P	P067-00-2/746	SCR - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22949	ACTIVE	P	P067-00-2/746/CLG-01	Ceiling: Suspended - 1 - SCR - Station Building - Hyde Park Corner Stn	Void	Asbestos	Surveyed – Not Detected				Metal beams & ducting, electrical ducting above Fibreboard ceiling				Yes	
22950	ACTIVE	P	P067-00-2/746/DOR-01	Door - 1 - SCR - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Entrance - Supalux panel both sides					
22948	ACTIVE	P	P067-00-2/746/FLR-01	Floor - 1 - SCR - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Supalux boxing					



Hazardous Material Asset Register - Summary



P067-00 - Station Building - Hyde Park Corner Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22947	ACTIVE	P	P067-00-2/746/FLR-01	Floor - 1 - SCR - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Supalux boxing to walls					
13978	ACTIVE	P	P067-00-2/761	SVC - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22953	ACTIVE	P	P067-00-2/761	SVC - Station Building - Hyde Park Corner Stn	Gasket :Pipework	Asbestos	Presumed				Gakets of pipeworks					
22952	ACTIVE	P	P067-00-2/761	SVC - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				2x Sprinkler - red gloss - 10m². Thickness : 0.09mm Analysis : 2.5%					
22951	ACTIVE	P	P067-00-2/761/WAL-001	Wall: Internal - 1 - SVC - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Supalux boxing					
13979	ACTIVE	P	P067-00-2/771	Pump Room - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22954	INACTIVE	P	P067-00-2/771/CLG-01	Ceiling: Solid - 1 - Pump Room - Station Building - Hyde Park Corner Stn	Void	Asbestos	No Access: Presumed				Above metal ceiling				Yes	
13980	ACTIVE	P	P067-00-2/776	Fan Room - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22957	ACTIVE	P	P067-00-2/776	Fan Room - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				2 x Sprinkler - red gloss. Thickness : 0.09mm Analysis : 2.5%					
22955	ACTIVE	P	P067-00-2/776/WAL-001	Wall: Internal - 1 - Fan Room - Station Building - Hyde Park Corner Stn	Gasket :Pipework	Asbestos	Strongly Presumed				Gaskets					
22956	ACTIVE	P	P067-00-2/776/WAL-002	Wall: Internal - 2 - Fan Room - Station Building - Hyde Park Corner Stn	Gasket :Pipework	Asbestos	Strongly Presumed				Gaskets					
22958	ACTIVE	P	P067-00-2/776/WAL-004	Wall: Internal - 4 - Fan Room - Station Building - Hyde Park Corner Stn	Isolator Switches	Asbestos	Strongly Presumed				1x Iron clad isolators - 1 x 200 amps		1			
13981	ACTIVE	P	P067-00-2/777	Fan Room - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22962	ACTIVE	P	P067-00-2/777/CLG-01 80873797	Ceiling: Solid - 1 - Fan Room - Station Building - Hyde Park Corner Stn Ceiling: Solid	Rope Gaskets	Asbestos	Not Found during Inspection				Gaskets on fan unit - centre of floor to wall 1 & ceiling 27/07/2016 to dark for photos During 2020 re-inspection - No fan unit visible in 2/777. Photo taken shows view inside room.					
22963	ACTIVE	P	P067-00-2/777/CLG-01 80873797	Ceiling: Solid - 1 - Fan Room - Station Building - Hyde Park Corner Stn Ceiling: Solid	Lead/Leading	Lead Paint/Lead	Known				Ceiling beams - cream gloss - 7m². Thickness : 0.23mm Analysis : 16% to dark for photo					



Hazardous Material Asset Register - Summary



P067-00 - Station Building - Hyde Park Corner Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22959	ACTIVE	P	P067-00-2/777/DOR-01	Door - 1 - Fan Room - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Supalux front door & panel					
22961	ACTIVE	P	P067-00-2/777/FLR-01 80873798	Floor - 1 - Fan Room - Station Building - Hyde Park Corner Stn Floor	Rope Gaskets	Asbestos	Not Found during Inspection				Gaskets on fan unit - centre of floor to wall 1 & ceiling to dark for photos During 2020 re-inspection - No fan unit visible in 2/777. Photo taken shows view inside room.					
23699	ACTIVE	P	P067-00-2/777/WAL-001	Wall: Internal - 1 - Fan Room - Station Building - Hyde Park Corner Stn	Rope Gaskets	Asbestos	Not Found during Inspection				Gaskets on fan unit - centre of floor to wall 1 & ceiling During 2020 re-inspection - No fan unit visible in 2/777. Photo taken shows view inside room.					
23996	ACTIVE	P	P067-00-2/777/WAL-003	Wall: Internal - 3 - Fan Room - Station Building - Hyde Park Corner Stn	Westing house Boxes	Asbestos	Sampled – Not Detected				1 x Westlinghouse box		1			
22960	ACTIVE	P	P067-00-2/777/WAL-004 80873796	Wall: Internal - 4 - Fan Room - Station Building - Hyde Park Corner Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Iron clad isolators to dark to take photos small door to entrance					
13982	ACTIVE	P	P067-00-2/778	Fan Room - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13983	ACTIVE	P	P067-00-2/901	Fan Room - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22966	ACTIVE	P	P067-00-2/901	Fan Room - Station Building - Hyde Park Corner Stn	Gasket :Pipework	Asbestos	Strongly Presumed				Gaskets on Fire equipment					
22967	ACTIVE	P	P067-00-2/901	Fan Room - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				Sprinkler - red gloss - 2m ² . Thickness : 0.09mm Analysis : 2.5%					
23822	INACTIVE	P	P067-00-2/901/CLG-01	Ceiling: Solid - 1 - Fan Room - Station Building - Hyde Park Corner Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
22964	ACTIVE	P	P067-00-2/901/WAL-001	Wall: Internal - 1 - Fan Room - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Supalux panels					
22965	ACTIVE	P	P067-00-2/901/WAL-002	Wall: Internal - 2 - Fan Room - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Supalux panels					
13984	ACTIVE	P	P067-00-2/951	Bin Store - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22969	ACTIVE	P	P067-00-2/951	Bin Store - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				Sprinkler - red gloss - 3m ² . Thickness : 0.09mm Analysis : 2.5%					
22970	ACTIVE	P	P067-00-2/951/CLG-01 80873500	Ceiling: Suspended - 1 - Store - Station Building - Hyde Park Corner Stn Ceiling: Suspended	Lead/Leading	Lead Paint/Lead	Known				Beam on ceiling - red gloss - 6m ² . Thickness : Too thin Analysis : 27% overpaint in cream					



Hazardous Material Asset Register - Summary



P067-00 - Station Building - Hyde Park Corner Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22968	ACTIVE	P	P067-00-2/951/FLR-01	Floor - 1 - Store - Station Building - Hyde Park Corner Stn	Void	Asbestos	No Access: Presumed				Beneath 2 x metal hatches					Yes
13985	ACTIVE	P	P067-00-3/236	Lobby - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13986	ACTIVE	P	P067-00-3/316	Office - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
41757	ACTIVE	P	P067-00-3/316/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Hyde Park Corner Stn-	Other Boarding	Asbestos	Sampled – Not Detected				Fibreboard Ceiling Tiles 5m² to ceiling				N	N
13987	ACTIVE	P	P067-00-3/357	Stairs: Linear - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13988	ACTIVE	P	P067-00-3/567	Stairs: Linear - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13989	ACTIVE	P	P067-00-3/568	Stairs: Linear - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13990	ACTIVE	P	P067-00-3/781	Substation Room - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
41770	ACTIVE	P	P067-00-3/781/FLR-01	Floor - 1 - Substation Room - Station Building - Hyde Park Corner Stn	Other Electrical Boxes	Asbestos	Presumed				Materials within auxiliary transformer by wall 4		1		N	N
41769	ACTIVE	P	P067-00-3/781/FLR-01	Floor - 1 - Substation Room - Station Building - Hyde Park Corner Stn	Cable Ducts: Bitumen	Asbestos	Known				8 x Bitumen Cable Ducts below combination fuse switch boxes		8		N	N
41759	ACTIVE	P	P067-00-3/781/WAL-001	Wall: Internal - 1 - Substation Room - Station Building - Hyde Park Corner Stn	Other Electrical Boxes	Asbestos	Presumed				Materials within busbar to wall 1					
41758	INACTIVE	P	P067-00-3/781/WAL-001	Wall: Internal - 1 - Substation Room - Station Building - Hyde Park Corner Stn	Isolator Switches	Asbestos	Presumed				Wall 1 - 5 x materials within combination fuse switch box		5		N	N
41764	ACTIVE	P	P067-00-3/781/WAL-001	Wall: Internal - 1 - Substation Room - Station Building - Hyde Park Corner Stn	Other Electrical Boxes	Asbestos	Presumed				Materials within 7 x HV breaker		7		N	N
41761	INACTIVE	P	P067-00-3/781/WAL-001	Wall: Internal - 1 - Substation Room - Station Building - Hyde Park Corner Stn	Other Electrical Boxes	Asbestos	Presumed				Materials within 1 x Busbar		1		N	N
41760	ACTIVE	P	P067-00-3/781/WAL-001	Wall: Internal - 1 - Substation Room - Station Building - Hyde Park Corner Stn	Isolator Switches	Asbestos	Presumed				Materials within 5 x combination fuse switch box					



Hazardous Material Asset Register - Summary



P067-00 - Station Building - Hyde Park Corner Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41765	ACTIVE	P	P067-00-3/781/WAL-002	Wall: Internal - 2 - Substation Room - Station Building - Hyde Park Corner Stn	Other Electrical Boxes	Asbestos	Presumed				Materials within 7 x relays		7		N	N
41766	ACTIVE	P	P067-00-3/781/WAL-002	Wall: Internal - 2 - Substation Room - Station Building - Hyde Park Corner Stn	Other Electrical Boxes	Asbestos	Presumed				Materials within 3 x fuse boards		3		N	N
41767	ACTIVE	P	P067-00-3/781/WAL-002	Wall: Internal - 2 - Substation Room - Station Building - Hyde Park Corner Stn	Other Electrical Boxes	Asbestos	Presumed				Materials within 4 x Busbar 2020 re-inspection - 3x busbar covers are loose to floor with encapsulated rope gasket visible		4		N	N
41768	ACTIVE	P	P067-00-3/781/WAL-002	Wall: Internal - 2 - Substation Room - Station Building - Hyde Park Corner Stn	Isolator Switches	Asbestos	Presumed				Materials within 14 x combination fuse switch box		14		N	N
41762	ACTIVE	P	P067-00-3/781/WAL-003	Wall: Internal - 3 - Substation Room - Station Building - Hyde Park Corner Stn	Isolator Switches	Asbestos	Presumed				Materials within 2 x combination fuse switch box		2		N	N
41763	ACTIVE	P	P067-00-3/781/WAL-004	Wall: Internal - 4 - Substation Room - Station Building - Hyde Park Corner Stn	Isolator Switches	Asbestos	Not Found during Inspection				Materials within 1 x combination fuse switch box Not found during 2020 re-inspection		1		N	N
13991	ACTIVE	P	P067-00-4/053	Disused Room - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13992	ACTIVE	P	P067-00-4/236	Passage - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23823	ACTIVE	P	P067-00-4/236	Passage - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				Metal arches - cream gloss - 8m². Thickness : 0.23mm Analysis : 16%					
22971	ACTIVE	P	P067-00-4/236/WAL-001	Wall: Internal - 1 - Passage Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				Cream gloss - 8m². Thickness : 0.23mm Analysis : 16%					
22972	ACTIVE	P	P067-00-4/236/WAL-003	Wall: Internal - 3 - Passage Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				Cream gloss - 8m². Thickness : 0.23mm Analysis : 16%					
13993	ACTIVE	P	P067-00-4/238	Passage - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
69847	ACTIVE	P	P067-00-4/238	Passage - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Concrete floor, Ceramic tiles on solid walls, solid ceiling with metal trunking					
13994	ACTIVE	P	P067-00-4/239	Passage - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23029	ACTIVE	P	P067-00-4/239	Passage - Station Building - Hyde Park Corner Stn	Caulking	Asbestos	Strongly Presumed				Solid & ceramic tiles, no access to tunnel rings behind Slight damage. Sealed caulking - treated highly friable material.					



Hazardous Material Asset Register - Summary



P067-00 - Station Building - Hyde Park Corner Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23028	ACTIVE	P	P067-00-4/239	Passage - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				Metal beams, double doors - White gloss - 40m². Thickness : 0.40m Analysis : 4.23%					
22973	ACTIVE	P	P067-00-4/239	Passage - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				Central pillar - cream gloss - 15m². Thickness : 0.76mm Analysis : 1.37%					
13995	ACTIVE	P	P067-00-4/567	Stairs: Linear - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23030	ACTIVE	P	P067-00-4/567/ WAL-001	Wall: Internal - 1 - Linear Stairs - Station Building - Hyde Park Corner Stn	Cable: Sheath	Asbestos	Strongly Presumed				1 x 2cm dia 5m length Encapsulated		1			
13996	ACTIVE	P	P067-00-4/568	Stairs: Linear - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13997	ACTIVE	P	P067-00-4/661	Switch Room - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45207	ACTIVE	P	P067-00-4/661/ WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Hyde Park Corner Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1 x 30amps, 1 x 200. 3 x 60amps 1 x 100amps		5		N	N
23032	ACTIVE	P	P067-00-4/661/ WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Hyde Park Corner Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1x Trunking		1			
23031	ACTIVE	P	P067-00-4/661/ WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Hyde Park Corner Stn	Isolator Switches	Asbestos	Strongly Presumed				3x Iron clad isolators - 2 x 60 amps, 1 x100 amps		3			
13998	ACTIVE	P	P067-00-4/662	Switch Room - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13999	ACTIVE	P	P067-00-4/731	CER - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23033	ACTIVE	P	P067-00-4/731/ FLR-01	Floor - 1 - CER - Station Building - Hyde Park Corner Stn	Void	Asbestos	Surveyed – Not Detected				Concrete & metal trunking beneath computer tiles					Yes
23034	ACTIVE	P	P067-00-4/731/ WAL-001	Wall: Internal - 1 - CER - Station Building - Hyde Park Corner Stn	Isolator Switches	Asbestos	Strongly Presumed				2x Iron clad isolators		2			
14000	ACTIVE	P	P067-00-4/732	Switch Room - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23035	ACTIVE	P	P067-00-4/732/ CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Hyde Park Corner Stn	Cable Duct: Other	Asbestos	Not Found during Inspection				8 x cables sleeves by wall 4 4/732 not found during 2020 re-inspection - not on station layout plans.		8			



Hazardous Material Asset Register - Summary



P067-00 - Station Building - Hyde Park Corner Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14001	ACTIVE	P	P067-00-4/761	Computer Equipment Cupboard - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14002	ACTIVE	P	P067-00-4/762	Computer Equipment Cupboard - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14003	ACTIVE	P	P067-00-4/763	Computer Equipment Cupboard - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14004	ACTIVE	P	P067-00-4/781	Substation Room - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
41772	ACTIVE	P	P067-00-4/781	Substation Room - Station Building - Hyde Park Corner Stn	Other Boarding	Asbestos	Sampled – Not Detected				Brown composite panels throughout to spare DC breaker				N	N
41771	ACTIVE	P	P067-00-4/781	Substation Room - Station Building - Hyde Park Corner Stn	Boarding: Cement	Asbestos	Not Found during Inspection				5 x Cement boxing and panels to spare DC breaker Cement boxing present on spate DC breaker is green and labelled "non asbestos". Possibly replaced former asbestos cement boxing.		5		N	N
41773	ACTIVE	P	P067-00-4/781/FLR-01	Floor - 1 - Substation Room - Station Building - Hyde Park Corner Stn	Other Electrical Boxes	Asbestos	Presumed				Materials within Rectifier no. 1 to floor by wall 2		1		N	N
41775	ACTIVE	P	P067-00-4/781/FLR-01	Floor - 1 - Substation Room - Station Building - Hyde Park Corner Stn	Other Electrical Boxes	Asbestos	Presumed				Materials within Rectifier no. 3 to floor by wall 2					
41776	ACTIVE	P	P067-00-4/781/FLR-01	Floor - 1 - Substation Room - Station Building - Hyde Park Corner Stn	Other Electrical Boxes	Asbestos	Presumed				Materials within DC breakers to floor by wall 4		18		N	N
41780	ACTIVE	P	P067-00-4/781/FLR-01	Floor - 1 - Substation Room - Station Building - Hyde Park Corner Stn	Cable Ducts: Bitumen	Asbestos	Known				3 x Bitumen Cable Ducts by wall 4		3		N	N
41781	ACTIVE	P	P067-00-4/781/FLR-01	Floor - 1 - Substation Room - Station Building - Hyde Park Corner Stn	Cable Ducts: Bitumen	Asbestos	Known				3 x Bitumen Cable Ducts by wall 1		3		N	N
41778	ACTIVE	P	P067-00-4/781/FLR-01	Floor - 1 - Substation Room - Station Building - Hyde Park Corner Stn	Cable Duct: Other	Asbestos	Presumed				8 x Cable ducts to underside of mezzanine floor		8			
41779	ACTIVE	P	P067-00-4/781/FLR-01	Floor - 1 - Substation Room - Station Building - Hyde Park Corner Stn	Cable Ducts: Bitumen	Asbestos	Known				6 x Bitumen Cable Ducts to floor		6		N	N
41774	ACTIVE	P	P067-00-4/781/FLR-01	Floor - 1 - Substation Room - Station Building - Hyde Park Corner Stn	Other Electrical Boxes	Asbestos	Presumed				Materials within Rectifier no. 2 to floor by wall 2		1		N	N



Hazardous Material Asset Register - Summary



P067-00 - Station Building - Hyde Park Corner Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41777	ACTIVE	P	P067-00-4/781/WAL-004	Wall: Internal - 4 - Substation Room - Station Building - Hyde Park Corner Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux17m² to corner of vent room 4/792 and wall 4				N	N
23037	ACTIVE	P	P067-00-4/793	Vent Shaft - Station Building - Hyde Park Corner Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels by entrance door & wall above					
23038	ACTIVE	P	P067-00-4/793	Vent Shaft - Station Building - Hyde Park Corner Stn	Boarding: Cement	Asbestos	Known				2sqm Cement panel above door		1			
23036	ACTIVE	P	P067-00-4/793/CLG-01	Ceiling: Solid - 1 - Vent Shaft - Station Building - Hyde Park Corner Stn	Void	Asbestos	No Access: Presumed				Beneath hatches				Yes	N
23700	ACTIVE	P	P067-00-4/793/FLR-01	Floor - 1 - Vent Shaft - Station Building - Hyde Park Corner Stn	Rope Gaskets	Asbestos	Strongly Presumed				Gaskets on Fan vents in centre of room/ high level of fan unit					
23039	ACTIVE	P	P067-00-4/793/WAL-003	Wall: Internal - 3 - Vent Shaft - Station Building - Hyde Park Corner Stn	Isolator Switches	Asbestos	Strongly Presumed				Iron clad isolators - Asbestos components within					
14005	ACTIVE	P	P067-00-4/952	Disused Room - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14006	ACTIVE	P	P067-00-4/985	Disused Room - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23040	ACTIVE	P	P067-00-4/985/FLR-01	Floor - 1 - Disused Room - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Metal, rubber, debris & plaster beneath manholes					Yes
14007	ACTIVE	P	P067-00-5/081	Passage - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14008	ACTIVE	P	P067-00-5/161	LMC - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23046	ACTIVE	P	P067-00-5/161	LMC - Station Building - Hyde Park Corner Stn	Lead/Leading	Lead Paint/Lead	Known				Entrance to LMC Red Lead Paint on Pipe work.					
23043	ACTIVE	P	P067-00-5/161/CLG-01	Ceiling: Solid - 1 - LMC - Station Building - Hyde Park Corner Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Cable sleeves - filled in concrete					
23830	ACTIVE	P	P067-00-5/161/CLG-02	Ceiling: Solid - 2 - LMC - Station Building - Hyde Park Corner Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Cable sleeves - filled in concrete					
23041	ACTIVE	P	P067-00-5/161/FLR-01	Floor - 1 - LMC - Station Building - Hyde Park Corner Stn	Void	Asbestos	Surveyed – Not Detected				Sumps beneath hatches				N	Yes
23044	ACTIVE	P	P067-00-5/161/WAL-001	Wall: Internal - 1 - LMC - Station Building - Hyde Park Corner Stn	Caulking	Asbestos	Strongly Presumed				Caulking Sealed caulking - treated highly friable material.					



Hazardous Material Asset Register - Summary



P067-00 - Station Building - Hyde Park Corner Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23045	ACTIVE	P	P067-00-5/161/WAL-003	Wall: Internal - 3 - LMC - Station Building - Hyde Park Corner Stn	Caulking	Asbestos	Strongly Presumed				Caulking Sealed caulking - treated highly friable material					
23042	ACTIVE	P	P067-00-5/161/WAL-003	Wall: Internal - 3 - LMC - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Supalux panel					
14009	ACTIVE	P	P067-00-5/201	Passage - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23831	ACTIVE	P	P067-00-5/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Hyde Park Corner Stn	No Access	Asbestos	No Access: Presumed				To trunking				Yes	
23047	ACTIVE	P	P067-00-5/201/FLR-01	Floor - 1 - Passage - Station Building - Hyde Park Corner Stn	Void	Asbestos	No Access: Presumed				Beneath 7x Hatches					Yes
23048	ACTIVE	P	P067-00-5/201/WAL-001	Wall: Internal - 1 - Passage - Station Building - Hyde Park Corner Stn	Cable: Sheath	Asbestos	Strongly Presumed				1x 2cm dia cable - coming from platform 2 into station radio system		1			
14010	ACTIVE	P	P067-00-5/202	Passage - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14011	ACTIVE	P	P067-00-5/203	Passage - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14012	ACTIVE	P	P067-00-5/204	Passage - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14013	ACTIVE	P	P067-00-5/205	Passage - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14014	ACTIVE	P	P067-00-5/206	Passage - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23049	ACTIVE	P	P067-00-5/206/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Hyde Park Corner Stn	Void	Asbestos	Surveyed – Not Detected				Concrete & metal ducting above false ceiling				Yes	
23050	ACTIVE	P	P067-00-5/206/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Hyde Park Corner Stn	Void	Asbestos	Surveyed – Not Detected				Concrete & metal ducting above false ceiling				Yes	
14015	ACTIVE	P	P067-00-5/207	Passage - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14016	ACTIVE	P	P067-00-5/208	Passage - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P067-00 - Station Building - Hyde Park Corner Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23051	ACTIVE	p	P067-00-5/237	Platform Invert - Station Building - Hyde Park Corner Stn	Westing house Boxes	Asbestos	Known				Platform Invert - Wall 2 - 2 x Westinghouse boxes		2			
14017	ACTIVE	p	P067-00-5/238	Passage - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23998	ACTIVE	p	P067-00-5/238	Passage - Station Building - Hyde Park Corner Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
14018	ACTIVE	p	P067-00-5/261	Platform 1 - Eastbound Local - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
69848	ACTIVE	p	P067-00-5/261	Platform 1 - Eastbound Local - Station Building - Hyde Park Corner Stn	Cable Ducts: Cement	Asbestos	Known				Platform Invert - Cement cable ducting debris <1m2 (identified on fault 963552)	2	2	R642926		
23054	ACTIVE	p	P067-00-5/261	Platform 1 - Eastbound Local - Station Building - Hyde Park Corner Stn	Cable: Sheath	Asbestos	Strongly Presumed				Eastbound Invert - Cables - platform side & pit side along length of invert and at Head/tail walls. Approx 14 x nr 5/207, 4x 1cm dia, 2x 5cm dia, 1x 15cm dia - from ceiling to pit side nr 5/711. 4x 1cm dia, 2x 5cm dia, 1x 8cm dia - from the other end to ceiling		14			
23052	ACTIVE	p	P067-00-5/261	Platform 1 - Eastbound Local - Station Building - Hyde Park Corner Stn	Westing house Boxes	Asbestos	Presumed				Eastbound Invert - 2 x Westinghouse box nr passage 5/207 + 1no Tencore Box		3			
23053	ACTIVE	p	P067-00-5/261	Platform 1 - Eastbound Local - Station Building - Hyde Park Corner Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Eastbound Invert - cable sleeves nr 5/711 - 6x 30m from hatch		6			
45209	ACTIVE	p	P067-00-5/261	Platform 1 - Eastbound Local - Station Building - Hyde Park Corner Stn	Cable: Sheath	Asbestos	Known				Link to Invert 1 & 2 - Braided cables throughout to J hangers within link cable passage of platform invert 1 and 2				N	N
45208	ACTIVE	p	P067-00-5/261	Platform 1 - Eastbound Local - Station Building - Hyde Park Corner Stn	Cable: Sheath	Asbestos	Known				Eastbound Invert - Braided cables throughout, within J hangers to trackside wall within invert				N	N
23832	ACTIVE	p	P067-00-5/261	Platform 1 - Eastbound Local - Station Building - Hyde Park Corner Stn	Cable: Sheath	Asbestos	Strongly Presumed				2 x Cables (1x 8cm dia, 1x5cm dia) Running behind metal casing possibly more behind		2			
43118	ACTIVE	p	P067-00-5/261	Platform 1 - Eastbound Local - Station Building - Hyde Park Corner Stn	Cable Ducts: Bitumen	Asbestos	Known				Bitumen ducts, 11 no., to east end of invert under Platform 1 and on track side, approximately 10 m		11	R525801	N	N
14019	ACTIVE	p	P067-00-5/262	Platform 2 - Westbound Local - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23056	INACTIVE	p	P067-00-5/262	Platform 2 - Westbound Local - Station Building - Hyde Park Corner Stn	No Access	Asbestos	No Access: Presumed				Within trunking trackside					



Hazardous Material Asset Register - Summary



P067-00 - Station Building - Hyde Park Corner Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23060	ACTIVE	P	P067-00-5/262	Platform 2 - Westbound Local - Station Building - Hyde Park Corner Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Westbound Invert - 23x cable sleeves from hatch 5/662 - 4 x by headwall, 6 x platform side, 5 x nr passage 5/208		23			
45211	ACTIVE	P	P067-00-5/262	Platform 2 - Westbound Local - Station Building - Hyde Park Corner Stn	Cable: Sheath	Asbestos	Known				Link to Invert 1 & 2 - Braided cables throughout to J hangers within link cable passage of platform invert 1 and 2				N	N
23057	ACTIVE	P	P067-00-5/262	Platform 2 - Westbound Local - Station Building - Hyde Park Corner Stn	Cable: Sheath	Asbestos	Strongly Presumed				Approx 8x Cables behind metal boxing - head wall from track		8			
23059	ACTIVE	P	P067-00-5/262	Platform 2 - Westbound Local - Station Building - Hyde Park Corner Stn	Westing house Boxes	Asbestos	Presumed				Westbound Invert - 1x Westinghouse box - Pit side - Asbestos components presumed within		1			
23055	ACTIVE	P	P067-00-5/262	Platform 2 - Westbound Local - Station Building - Hyde Park Corner Stn	Cable: Sheath	Asbestos	Strongly Presumed				2x 2cm dia Cables from Westinghouse box - Wall & head wall 5/208		2			
23058	ACTIVE	P	P067-00-5/262	Platform 2 - Westbound Local - Station Building - Hyde Park Corner Stn	Cable: Sheath	Asbestos	Strongly Presumed				Westbound Invert - Cables platform side & pit side length of invert and at head / tails walls. Approx 37 x nr 5/208 (19 x 1cm dia & 8 x 2cm dia down from hatch. 2 x 4cm dia, 1x 8cm dia green & brown cables, 1 x coming from ceiling out of pit wall filled in, 1x 1cm dia		37			
43119	ACTIVE	P	P067-00-5/262	Platform 2 - Westbound Local - Station Building - Hyde Park Corner Stn	Bitumen	Asbestos	Sampled – Not Detected				4 x Bitumen cable ducts within concrete slab at departure end on track site wall - NADIS Bitumen ducts 2no to west end of invert under Platform 2 - NADIS		6	R525801	N	N
45210	ACTIVE	P	P067-00-5/262	Platform 2 - Westbound Local - Station Building - Hyde Park Corner Stn	Cable: Sheath	Asbestos	Presumed				Westbound Invert - Braided cables throughout, within J hangers to trackside wall within invert				N	N
43120	ACTIVE	P	P067-00-5/262	Platform 2 - Westbound Local - Station Building - Hyde Park Corner Stn	Cable: Sheath	Asbestos	Known				Braided cables, 4 x 50 mm, 5 m long, entering invert from west end and entering to Room 5/761, under Platform 2, Cables viewed from platform only during traffic hours therefore material not score in re-inspection.			R525801	N	N
14020	ACTIVE	P	P067-00-5/406	Store - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23062	ACTIVE	P	P067-00-5/406/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Hyde Park Corner Stn	No Access	Asbestos	No Access: Presumed				Above false ceiling					
23061	ACTIVE	P	P067-00-5/406/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Supalux					
14021	ACTIVE	P	P067-00-5/661	Switch Room - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P067-00 - Station Building - Hyde Park Corner Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23063	ACTIVE	P	P067-00-5/661/WAL-003 80873982	Wall: Internal - 3 - Switch Room - Station Building - Hyde Park Corner Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				6x Isolators & Trunking 1x30, 1x200, 3x 60, 1x100		6			
23064	ACTIVE	P	P067-00-5/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Hyde Park Corner Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1 xTransformer Box		1			
14022	ACTIVE	P	P067-00-5/662	Switch Room - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23065	ACTIVE	P	P067-00-5/662/FLR-01	Floor - 1 - Switch Room Station Building - Hyde Park Corner Stn	Void	Asbestos	No Access: Presumed				Beneath 4x hatches					Yes
23068	ACTIVE	P	P067-00-5/662/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Hyde Park Corner Stn	Other Boarding	Asbestos	Strongly Presumed				Paxoline Board					
23067	ACTIVE	P	P067-00-5/662/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Hyde Park Corner Stn	Other Electrical Boxes	Asbestos	Presumed				2 x Electrical Equipment - Presumed Asbestos components within - Dark Blue equipment case is new and therefore non-asbestos.		2			
23069	INACTIVE	P	P067-00-5/662/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Hyde Park Corner Stn	Other Electrical Boxes	Asbestos	Removed				Trunking		1			
23066	ACTIVE	P	P067-00-5/662/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Supalux boxing around electrical transformer					
23701	INACTIVE	P	P067-00-5/662/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Hyde Park Corner Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1x Electrical Equipment		1			
14023	ACTIVE	P	P067-00-5/711	Relay Room - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22975	INACTIVE	P	P067-00-5/711	Relay Room - Station Building - Hyde Park Corner Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				8 x PCB's		8			
23070	ACTIVE	P	P067-00-5/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				3x Supalux panels- no access behind					
23075	ACTIVE	P	P067-00-5/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Hyde Park Corner Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse Box		1			
43131	ACTIVE	P	P067-00-5/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Hyde Park Corner Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box W1				N	N
22974	ACTIVE	P	P067-00-5/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Hyde Park Corner Stn	Cable: Sheath	Asbestos	Strongly Presumed				Approx 5x 1cm dia Cables from invert		5			



Hazardous Material Asset Register - Summary



P067-00 - Station Building - Hyde Park Corner Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23834	ACTIVE	P	P067-00-5/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Hyde Park Corner Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables going down to invert - 1x 2cm dia, 1x 5cm dia		2			
43130	INACTIVE	P	P067-00-5/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Hyde Park Corner Stn	PCBs	Polychlorinated biphenyl	Presumed				2 Blue Cylinder PCB's on Paxoline W3				N	N
23071	ACTIVE	P	P067-00-5/711/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				3x Supalux panels- no access behind					
23073	ACTIVE	P	P067-00-5/711/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Hyde Park Corner Stn	Cable: Sheath	Asbestos	Strongly Presumed				11x Cables - Wall 4&6 (Looping from wall 1 to electrical equipment wall 2) & Paxoline Board		11			
23833	ACTIVE	P	P067-00-5/711/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Supalux panel by wall 4					
23072	ACTIVE	P	P067-00-5/711/WAL-005	Wall: Internal - 5 - Relay Room - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Supalux panels, boxing					
23074	ACTIVE	P	P067-00-5/711/WAL-006	Wall: Internal - 6 - Relay Room - Station Building - Hyde Park Corner Stn	Cable: Sheath	Asbestos	Strongly Presumed				1 Cables From wooden box going into invert wall 4		11			
14024	ACTIVE	P	P067-00-5/731	Switch Cupboard - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22977	ACTIVE	P	P067-00-5/731/DOR-02	Door - 2 - Switch Cupboard - Station Building - Hyde Park Corner Stn	Cable Duct: Other	Asbestos	Strongly Presumed				4x Cables sleeves on floor by wall 2		4			
22978	ACTIVE	P	P067-00-5/731/WAL-001	Wall: Internal - 1 - Switch Cupboard - Station Building - Hyde Park Corner Stn	Isolator Switches	Asbestos	Strongly Presumed				3x Iron clad isolators - 1 x 100 amps, 1 x 200 amps, 1 x 60 amps		3			
22976	ACTIVE	P	P067-00-5/731/WAL-001	Wall: Internal - 1 - Switch Cupboard - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				Part supalux, part solid					
22979	ACTIVE	P	P067-00-5/731/WAL-001	Wall: Internal - 1 - Switch Cupboard - Station Building - Hyde Park Corner Stn	Other Electrical Boxes	Asbestos	No Access: Presumed				Trunking					
14025	ACTIVE	P	P067-00-5/732	Computer Equipment Cupboard - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22980	ACTIVE	P	P067-00-5/732/WAL-003	Wall: Internal - 3 - Computer Equipment Cupboard - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				2x supalux panels, 1x batterns					
14026	ACTIVE	P	P067-00-5/761	Equipment Room - Station Building - Hyde Park Corner Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P067-00 - Station Building - Hyde Park Corner Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
22982	ACTIVE	P	P067-00-5/761/FLR-01	Floor - 1 - Equipment Room - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				6x Supalux					
23607	ACTIVE	P	P067-00-5/761/WAL-001	Wall: Internal - 1 - Equipment Room - Station Building - Hyde Park Corner Stn	Cable: Sheath	Asbestos	Strongly Presumed				2x Cables - 600v East & westbound board		2			
22981	ACTIVE	P	P067-00-5/761/WAL-003	Wall: Internal - 3 - Equipment Room - Station Building - Hyde Park Corner Stn	Cable: Sheath	Asbestos	Strongly Presumed				6x Cables - from 600v		6			
45213	ACTIVE	P	P067-00-5/791	Vent Shaft - Station Building - Hyde Park Corner Stn	Cable: Sheath	Asbestos	Known				Vent Tunnel - 3 x 8Linm to HV cables to J hangers on each side of tunnel by step ladder to invert & link invert cable way passage	8	3		N	N
45212	ACTIVE	P	P067-00-5/791	Vent Shaft - Station Building - Hyde Park Corner Stn	Westing house Boxes	Asbestos	Known				Vent Tunnel - 2 x small westinghouse box (materials within) to wall by ladder within invert		2		N	N
22984	ACTIVE	P	P067-00-5/791/CLG-01	Ceiling: Solid - 1 - Vent Shaft - Station Building - Hyde Park Corner Stn		Asbestos	Surveyed – Not Detected				1x supalux panel					
22985	ACTIVE	P	P067-00-5/791/CLG-01	Ceiling: Solid - 1 - Vent Shaft - Station Building - Hyde Park Corner Stn	Void	Asbestos	No Access: Presumed				Above supalux panel				Yes	
22983	ACTIVE	P	P067-00-5/791/FLR-01	Floor - 1 - Vent Shaft - Station Building - Hyde Park Corner Stn	Void	Asbestos	No Access: Presumed				Beneath metal floor top of stairs				N	Yes

P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14027	ACTIVE	P	P069-00-1/201	Passage - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
68059	INACTIVE	P	P069-00-1/201/CPT-002	Call Point: Wired - Passage - Station Building - Knightsbridge Stn	Caulking	Asbestos	Removed				TEST - REMoved by gneineilng 23/1/24					
22986	ACTIVE	P	P069-00-1/201/FLR-01	Floor - 1 - Passage - Station Building - Knightsbridge Stn	Void	Asbestos	No Access: Presumed				Beneath floor hatch					Yes
68058	INACTIVE	P	P069-00-1/201/WAL-004	Wall: Internal - 4 - Passage - Station Building - Knightsbridge Stn		Asbestos	Known				TEST					
14028	ACTIVE	P	P069-00-1/202	Passage - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14029	ACTIVE	P	P069-00-1/402	Bin Store - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14030	ACTIVE	P	P069-00-1/601	Stairs: Linear - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14031	ACTIVE	P	P069-00-1/602	Stairs: Linear - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
22987	ACTIVE	P	P069-00-1/602/FLR-01	Floor - 1 - Linear Stairs - Station Building - Knightsbridge Stn	Void	Asbestos	No Access: Presumed				Beneath floor hatch					Yes
14032	ACTIVE	P	P069-00-1/603	Stairs: Linear - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14033	ACTIVE	P	P069-00-1/605	Stairs: Linear - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14034	ACTIVE	P	P069-00-1/607	Stairs: Linear - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43440	ACTIVE	P	P069-00-1/607/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				High Level Ceiling - NAD Plaster = NADIS R&D Survey R589551 22/03/2017			R562251	Y	
43685	ACTIVE	P	P069-00-1/607/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Plaster on wire mesh on concrete slab 3m2 Above metal boxing of gate line to ceiling to stair entrance 1/607			R589551	N	N
43686	ACTIVE	P	P069-00-1/607/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Plaster on concrete slab to ceiling			R589551	N	N
43441	ACTIVE	P	P069-00-1/607/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				Metal Paneling - No Access High Level - NAD Plaster = NADIS R&D Survey R589551 22/03/2017					
43687	ACTIVE	P	P069-00-1/607/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Concrete slab within metal nosing to floor			R589551	N	N
14035	ACTIVE	P	P069-00-1/608	Stairs: Linear - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43443	ACTIVE	P	P069-00-1/608/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				High Level Ceiling - NAD Plaster = NADIS R&D Survey R589551 22/03/2017			R562251	Y	
43442	ACTIVE	P	P069-00-1/608/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				Metal Paneling - No Access High Level - NAD Plaster = NADIS R&D Survey R589551 22/03/2017			R562251		
43688	ACTIVE	P	P069-00-1/608/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Plaster on wire mesh on concrete slab 3m2 Above metal boxing of gate line to ceiling to stair entrance 1/608			R589551	N	N



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14036	ACTIVE	P	P069-00-1/609	Stairs: Linear - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44328	ACTIVE	P	P069-00-1/609/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Concrete core penetration – Part 1 Through entire concrete slab to confirm if any asbetos containign materials are preent (drilled with semi-controlled conditions). No shuttering present			R616551		
43689	ACTIVE	P	P069-00-1/609/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Plaster on wire mesh on concrete slab 3m2 Above metal boxing of gate line to ceiling to stair entrance 1/608			R589551	N	N
44329	ACTIVE	P	P069-00-1/609/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Concrete drill penetration – dust Into floor by access manhole			R616551		
43444	ACTIVE	P	P069-00-1/609/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				High Level Ceiling - NAD Plaster = NADIS R&D Survey R589551 22/03/2017			R562251	Y	
43445	ACTIVE	P	P069-00-1/609/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Knightsbridge Stn	Void	Asbestos	Sampled – Not Detected				Metal Paneling - No Access High Level - Intrusive Survey Required			R562251		
44335	ACTIVE	P	P069-00-1/609/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Concrete core penetration – Part 2 Through entire concrete slab to confirm if any asbestos containing materials are present (drilled with semi-controlled conditions). No shuttering present			R616551		
44334	ACTIVE	P	P069-00-1/609/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Concrete drill penetration – dust Into LHS wall, midway through vent duct			R616551		
44333	ACTIVE	P	P069-00-1/609/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Concrete drill penetration – dust Into LHS wall			R616551		
44332	ACTIVE	P	P069-00-1/609/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Concrete drill penetration – dust Into RHS wall			R616551		
44331	ACTIVE	P	P069-00-1/609/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Concrete drill penetration – dust Into RHS wall, adjacent to sample 173294/250218/01			R616551		
44330	ACTIVE	P	P069-00-1/609/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Concrete drill penetration – dust Into floor of duct			R616551		
14037	ACTIVE	P	P069-00-1/610	Stairs: Linear - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14038	ACTIVE	P	P069-00-1/611	Stairs: Linear - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14039	ACTIVE	P	P069-00-1/612	Stairs: Linear - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14040	ACTIVE	P	P069-00-1/901	Store - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14041	ACTIVE	P	P069-00-1/902	Store - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14042	ACTIVE	P	P069-00-1/903	Void - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14043	ACTIVE	P	P069-00-2/001	Booking Hall - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
48005	ACTIVE	P	P069-00-2/001	Booking Hall - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Lead Paint to central ceiling to Booking Hall 2no Samples - 3.62% & 5.16%			R712251		
43700	ACTIVE	P	P069-00-2/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Knightsbridge Stn	Void	Asbestos	Sampled – Not Detected				Ceramic tiles on brickwork/ concrete slab to walls			R589551	N	N
43697	ACTIVE	P	P069-00-2/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Knightsbridge Stn	Other Boarding	Asbestos	Sampled – Not Detected				Woodite panels 60m2 to rear of some VE panels			R589591	N	N
43698	ACTIVE	P	P069-00-2/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Knightsbridge Stn	Void	Asbestos	Sampled – Not Detected				Plaster on concrete slab to ceiling and in false ceiling			R589551	Y	N
23824	ACTIVE	P	P069-00-2/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				Above Supalux boxing - NAD R&D Survey R589551 22/03/2017					
22988	ACTIVE	P	P069-00-2/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Knightsbridge Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Suplax boxing by stairs 1/602					
43699	ACTIVE	P	P069-00-2/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Knightsbridge Stn	Void	Asbestos	Sampled – Not Detected				Plastic and metal pipework - foam and MMMF insulation throughout in false ceiling			R589551		
14044	ACTIVE	P	P069-00-2/002	Booking Hall - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
69378	ACTIVE	P	P069-00-2/002/CLG-02	Ceiling: Suspended - 1 - Booking Hall - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				No ACMs above false ceiling			R679615	Y	
14045	ACTIVE	P	P069-00-2/011	Ticket Office - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43446	ACTIVE	P	P069-00-2/011	Ticket Office - Station Building - Knightsbridge Stn	Lagging	Asbestos	Sampled – Not Detected				Fire Stopping - Throughout - Non Asbestos			R562251		
43447	ACTIVE	P	P069-00-2/011	Ticket Office - Station Building - Knightsbridge Stn	Plaster	Asbestos	Sampled – Not Detected				Plaster Sampled on Solid			R562251		
22991	ACTIVE	P	P069-00-2/011/CLG-01	Ceiling: Solid - 1 - Ticket Office - Station Building - Knightsbridge Stn		Asbestos	Surveyed – Not Detected				Supalux - To A/C ductwork within false ceiling				Y	
22992	ACTIVE	P	P069-00-2/011/CLG-01	Ceiling: Solid - 1 - Ticket Office - Station Building - Knightsbridge Stn		Asbestos	Surveyed – Not Detected				Plaster, solid above false ceiling				Yes	
43448	ACTIVE	P	P069-00-2/011/CLG-01	Ceiling: Solid - 1 - Ticket Office - Station Building - Knightsbridge Stn	Mastic	Asbestos	Surveyed – Not Detected				Air Condition Ducting - Above False Ceiling - Gaskets not accessed / not possible until duct sections split to give access – but visually appear new style; Confirmed non asbestos in report R596201 (07/06/2017)			R562251	Y	
22989	ACTIVE	P	P069-00-2/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				Beneath Computer Flooring - Concrete Slab (R596201)					Y
43449	ACTIVE	P	P069-00-2/011/WAL-001	Wall: Internal - 1 - Ticket Office - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard Lined Boxing on Metal Stands Framework - High Level W3 R596201			R562251		
22990	ACTIVE	P	P069-00-2/011/WAL-001	Wall: Internal - 1 - Ticket Office - Station Building - Knightsbridge Stn		Asbestos	Surveyed – Not Detected				Supalux boarding					
43541	INACTIVE	P	P069-00-2/011/WAL-001	Wall: Internal - 1 - Ticket Office - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Matt Walls thickness 230 0.01%			R562252	N	N
43550	INACTIVE	P	P069-00-2/011/WAL-001	Wall: Internal - 1 - Ticket Office - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Black Matt Ceiling above False Ceiling thickness 160 0.01%			R562252	Y	N
43542	INACTIVE	P	P069-00-2/011/WAL-001	Wall: Internal - 1 - Ticket Office - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Powder Coated False Ceiling - Metal Tiles			R562252	Y	N
43996	ACTIVE	P	P069-00-2/011/WAL-003	Wall: Internal - 3 - Ticket Office - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Textured Coating to top of Wall 3 by Plasterboard			R596201		
14046	ACTIVE	P	P069-00-2/013	Ticket Office - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
69374	ACTIVE	P	P069-00-2/013/CLG-02	Ceiling: Suspended - 1 - Ticket Office - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				No ACMs above false ceiling			R679615	Y	
14047	ACTIVE	P	P069-00-2/021	POM - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42844	ACTIVE	P	P069-00-2/021	POM - Station Building - Knightsbridge Stn	Other Boarding	Asbestos	Sampled – Not Detected				Boarding 1m² below false floor within POM room	1	2	R518926	N	Y
22994	ACTIVE	P	P069-00-2/021/CLG-01	Ceiling: Solid - 1 - POM - Station Building - Knightsbridge Stn		Asbestos	Surveyed – Not Detected				Supalux					
22995	ACTIVE	P	P069-00-2/021/CLG-01	Ceiling: Solid - 1 - POM - Station Building - Knightsbridge Stn		Asbestos	Surveyed – Not Detected				Plaster, solid above false ceiling				Yes	
43546	INACTIVE	P	P069-00-2/021/CLG-01	Ceiling: Solid - 1 - POM - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Powder Coated False Ceiling - Metal Tiles			R562252	Y	N
43549	INACTIVE	P	P069-00-2/021/CLG-01	Ceiling: Solid - 1 - POM - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Black Matt Ceiling above False Ceiling thickness 160 0.01%			R562252	Y	N
43545	INACTIVE	P	P069-00-2/021/CLG-01	Ceiling: Solid - 1 - POM - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Matt Walls thickness 240 0.01%			R562252	N	N
23825	ACTIVE	P	P069-00-2/021/FLR-01	Floor - 1 - POM - Station Building - Knightsbridge Stn	Void	Asbestos	No Access: Presumed				Beneath computer flooring					Yes
22993	ACTIVE	P	P069-00-2/021/WAL-003	Wall: Internal - 3 - POM - Station Building - Knightsbridge Stn		Asbestos	Surveyed – Not Detected				Supalux boarding					
14048	ACTIVE	P	P069-00-2/023	POM - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14049	ACTIVE	P	P069-00-2/031	Mess Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
43450	ACTIVE	P	P069-00-2/031	Mess Room - Station Building - Knightsbridge Stn	Plaster	Asbestos	Sampled – Not Detected				Plaster Sampled on Solid Walls			R562251		
23826	INACTIVE	P	P069-00-2/031	Mess Room - Station Building - Knightsbridge Stn	Bitumen	Asbestos	Removed				0.02m² Sink acoustic panel New report (10/01/2017): States all 4no Acoustic Pads to be Non-Asbestos		1			
43547	INACTIVE	P	P069-00-2/031	Mess Room - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Black Matt Ceiling above False Ceiling thickness 160 0.01%			R562252	Y	N
43539	INACTIVE	P	P069-00-2/031	Mess Room - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Matt Walls thickness 230 0.01%			R562252	N	N
43540	INACTIVE	P	P069-00-2/031	Mess Room - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Powder Coated False Ceiling - Metal Tiles			R562252	Y	N
22996	ACTIVE	P	P069-00-2/031/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Knightsbridge Stn		Asbestos	Surveyed – Not Detected				Supalux Boxing - To A/C ductwork within false ceiling				Y	



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43451	ACTIVE	P	P069-00-2/031/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Knightsbridge Stn	Mastic	Asbestos	Surveyed – Not Detected				Air Condition Ducting - Above False Ceiling - Gaskets not accessed / not possible until duct sections split to give access – but visually appear new style; Confirmed non asbestos in report R596201 07/06/2017			R562251	Y	
14050	ACTIVE	P	P069-00-2/033	Mess Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
69376	ACTIVE	P	P069-00-2/033	Mess Room - Station Building - Knightsbridge Stn	Bitumen	Asbestos	Sampled – Not Detected				Bitumen sink pads		3	R679615		
69377	ACTIVE	P	P069-00-2/033/CLG-02	Ceiling: Suspended - 1 - Mess Room - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				No ACMs above false ceiling			R679615	Y	
14051	ACTIVE	P	P069-00-2/036	Toilet: Unisex - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14052	ACTIVE	P	P069-00-2/053	Mess Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
22998	ACTIVE	P	P069-00-2/053	Mess Room - Station Building - Knightsbridge Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Foam insulation, metal duct above work surface		1			
43455	ACTIVE	P	P069-00-2/053	Mess Room - Station Building - Knightsbridge Stn	Mastic	Asbestos	Sampled – Not Detected				General Penetrations: Mastic to cable management system/ pipework penetrations to high level walls throughout			R562251		
43457	ACTIVE	P	P069-00-2/053	Mess Room - Station Building - Knightsbridge Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux Panel to Ducts			R562251		
43453	ACTIVE	P	P069-00-2/053	Mess Room - Station Building - Knightsbridge Stn	Plaster	Asbestos	Sampled – Not Detected				Plaster Sampled to High Level Walls			R562251		
43456	ACTIVE	P	P069-00-2/053	Mess Room - Station Building - Knightsbridge Stn	Mastic	Asbestos	Sampled – Not Detected				Mastic to Duct Joints			R562251		
43557	INACTIVE	P	P069-00-2/053	Mess Room - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Matt Lower Part of Walls - Tiles			R562252	N	N
43556	INACTIVE	P	P069-00-2/053	Mess Room - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Matt Upper Part of Walls and Ceiling thickness 200 0.01%			R562252	N	N
43454	ACTIVE	P	P069-00-2/053/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Knightsbridge Stn	Mastic	Asbestos	No Access: Presumed				Air Condition Ducting - Gaskets not accessed / not possible until duct sections split to give access – but visually appear new style;			R562251		
43452	ACTIVE	P	P069-00-2/053/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Knightsbridge Stn	Plaster	Asbestos	Sampled – Not Detected				Plaster Sampled to Ceiling			R562251		
22997	ACTIVE	P	P069-00-2/053/FLR-01	Floor - 1 - Mess Room - Station Building - Knightsbridge Stn	Void	Asbestos	No Access: Presumed				Inspection Chamber - No Access Below - Intrusive Survey Required					Yes



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14053	ACTIVE	P	P069-00-2/071	Circulation Area - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43696	ACTIVE	P	P069-00-2/071	Circulation Area - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Ceramic tiles on brickwork/ concrete slab to walls			R589551	N	N
43694	ACTIVE	P	P069-00-2/071	Circulation Area - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Woodite panels 60m2 to rear of some VE panels			R589551	N	N
43695	ACTIVE	P	P069-00-2/071	Circulation Area - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Plastic and metal pipework - foam and MMMF insulation throughout in false ceiling			R589551	N	N
14054	ACTIVE	P	P069-00-2/072	Circulation Area - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
69382	ACTIVE	P	P069-00-2/072	Circulation Area - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				No ACMs behind VE panels			R679615		
14055	ACTIVE	P	P069-00-2/073	Circulation Area - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
69381	ACTIVE	P	P069-00-2/073/ CLG-02	Ceiling: Suspended - 1 - Circulation Area - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				No ACMs above false ceiling			R679615	Y	
14056	ACTIVE	P	P069-00-2/082	Lobby - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14057	ACTIVE	P	P069-00-2/083	Lobby - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
69373	ACTIVE	P	P069-00-2/083/ CLG-02	Ceiling: Suspended - 1 - Lobby - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				No ACMs above false ceiling			R679615	Y	
14058	ACTIVE	P	P069-00-2/084	Lobby - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
69372	ACTIVE	P	P069-00-2/084/ CLG-02	Ceiling: Suspended - 1 - Lobby - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				No ACMs above false ceiling			R679615	Y	
14059	ACTIVE	P	P069-00-2/085	Lobby - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
69375	ACTIVE	P	P069-00-2/085/ CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				No ACMs above false ceiling			R679615		
14060	ACTIVE	P	P069-00-2/093	GLAP - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14061	ACTIVE	P	P069-00-2/151	UMC - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23004	INACTIVE	P	P069-00-2/151	UMC - Station Building - Knightsbridge Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x Switch boxes		2			
23001	ACTIVE	P	P069-00-2/151	UMC - Station Building - Knightsbridge Stn		Asbestos	Surveyed – Not Detected				Supalux panel above motor 6					
23002	ACTIVE	P	P069-00-2/151	UMC - Station Building - Knightsbridge Stn	Rope Gaskets	Asbestos	Presumed				Gaskets on extractor fan					
23000	ACTIVE	P	P069-00-2/151	UMC - Station Building - Knightsbridge Stn		Asbestos	Surveyed – Not Detected				Supalux panels around door. Supalux boxing by entrance					
23005	ACTIVE	P	P069-00-2/151/CLG-01	Ceiling: Solid - 1 - UMC - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Red lead paint on pipe work					
42503	ACTIVE	P	P069-00-2/151/FLR-01 80875284	Floor - 1 - UMC - Station Building - Knightsbridge Stn Floor	Other Electrical Boxes	Asbestos	Presumed				Old Wippen bourne vent equipment - Asbestos components within - Presumed					
23003	ACTIVE	P	P069-00-2/151/WAL-012	Wall: Internal - 12 - UMC - Station Building - Knightsbridge Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x grey combination fuse switches - 1 x 200 amps, 1 x 60 amps - Asbestos components within - SP		2			
14062	ACTIVE	P	P069-00-2/152	UMC - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23006	INACTIVE	P	P069-00-2/152	UMC - Station Building - Knightsbridge Stn	Other Electrical Boxes	Asbestos	Removed				3x Escalator Circuit Breakers - removed during Escalator refurbishment		3			
23007	ACTIVE	P	P069-00-2/152	UMC - Station Building - Knightsbridge Stn	Isolator Switches	Asbestos	Strongly Presumed				2x Iron clad isolators 1 x 300 amps, 1 x 60 amps - Asbestos components within		2			
42505	ACTIVE	P	P069-00-2/152	UMC - Station Building - Knightsbridge Stn	Other Electrical Boxes	Asbestos	Presumed				1 transformer box - Asbestos components within - Presumed					
23008	ACTIVE	P	P069-00-2/152/CLG-01	Ceiling: Solid - 1 - UMC - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Red lead paint on pipe work					
14063	ACTIVE	P	P069-00-2/153	UMC - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23009	ACTIVE	P	P069-00-2/153/FLR-01	Floor - 1 - UMC - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				Beneath metal floor					Yes
14064	ACTIVE	P	P069-00-2/201	Passage - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23997	ACTIVE	P	P069-00-2/201	Passage - Station Building - Knightsbridge Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard boarding by 2/456 -		1			
46856	ACTIVE	P	P069-00-2/201	Passage - Station Building - Knightsbridge Stn	Cable Ducts: Cement	Asbestos	Presumed				duct and debris throughout to the floor below passage floor					



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23010	ACTIVE	P	P069-00-2/201/WAL-001	Wall: Internal - 1 - Passage - Station Building - Knightsbridge Stn		Asbestos	Surveyed – Not Detected				Supalux boxing near phones boxes with supalux boarding above					
14065	ACTIVE	P	P069-00-2/237	Lobby - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
43459	ACTIVE	P	P069-00-2/237	Lobby - Station Building - Knightsbridge Stn	Plaster	Asbestos	Sampled – Not Detected				Plaster Sampled on Walls & Ceiling			R562251		
43994	ACTIVE	P	P069-00-2/237	Lobby - Station Building - Knightsbridge Stn	Mastic	Asbestos	Surveyed – Not Detected				Mastic to A/C Metal Ductwork - Non Asbestos			R596201		
43535	INACTIVE	P	P069-00-2/237	Lobby - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Matt Walls thickness 210 0.01%			R562252	N	N
43536	INACTIVE	P	P069-00-2/237	Lobby - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Matt False Ceiling - Supalux - Not Painted			R562252	Y	N
23012	ACTIVE	P	P069-00-2/237/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				Plaster, solid above false ceiling				Yes	
43461	ACTIVE	P	P069-00-2/237/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Knightsbridge Stn		Asbestos	Surveyed – Not Detected				Firestopping - Throughout to wall penetrations, within false ceiling			R562251	Y	
23011	ACTIVE	P	P069-00-2/237/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Knightsbridge Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
14066	ACTIVE	P	P069-00-2/238	Lobby - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23014	ACTIVE	P	P069-00-2/238/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				Plaster, solid above false ceiling				Yes	
23013	ACTIVE	P	P069-00-2/238/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Knightsbridge Stn		Asbestos	Surveyed – Not Detected				Supalux					
43551	INACTIVE	P	P069-00-2/238/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Black Matt Ceiling above False Ceiling thickness 160 0.01%			R562252	Y	N
43544	INACTIVE	P	P069-00-2/238/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Powder Coated False Ceiling - Metal Tiles			R562252	Y	N
43543	INACTIVE	P	P069-00-2/238/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Matt Walls thickness 210 0.01%			R562252	N	N
14067	ACTIVE	P	P069-00-2/239	Lobby (Brompton Road) - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43463	ACTIVE	P	P069-00-2/239	Lobby (Brompton Road) - Station Building - Knightsbridge Stn	Mastic	Asbestos	Sampled – Not Detected				General Penetrations: Mastic to cable management system/ pipework penetrations to high level walls throughout			R562251		
43462	ACTIVE	P	P069-00-2/239	Lobby (Brompton Road) - Station Building - Knightsbridge Stn	Plaster	Asbestos	Sampled – Not Detected				Plaster Sampled on both High Level Walls & Ceiling			R562251		
23015	ACTIVE	P	P069-00-2/239/ FLR-01	Floor - 1 - Lobby - Station Building - Knightsbridge Stn	Void	Asbestos	No Access: Presumed				Inspection Chamber - No Access Below - Intrusive Survey Required					Yes
14068	ACTIVE	P	P069-00-2/240	Store - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23017	ACTIVE	P	P069-00-2/240/ CLG-01	Ceiling: Solid - 1 - Store - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
23016	ACTIVE	P	P069-00-2/240/ CLG-01	Ceiling: Solid - 1 - Store - Station Building - Knightsbridge Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding to either side of entrance door to 2/902 to wall 1					
44090	ACTIVE	P	P069-00-2/240/ CLG-01	Ceiling: Solid - 1 - Store - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Black braided cable 1 no. x 3m, to ceiling	3		R602501	N	N
45236	ACTIVE	P	P069-00-2/240/ CLG-01	Ceiling: Solid - 1 - Store - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Matt Ceiling - Concrete Not Painted				N	N
43464	ACTIVE	P	P069-00-2/240/ FLR-01	Floor - 1 - Store - Station Building - Knightsbridge Stn	Void	Asbestos	No Access: Presumed				Sealed Service Duct to Floor - No Access - Intrusive Survey Required			R562251		Y
43466	ACTIVE	P	P069-00-2/240/ WAL-002	Wall: Internal - 2 - Store - Station Building - Knightsbridge Stn	Mastic	Asbestos	Sampled – Not Detected				Mastic to galvanized duct joints			R562251		
43465	ACTIVE	P	P069-00-2/240/ WAL-002	Wall: Internal - 2 - Store - Station Building - Knightsbridge Stn	Mastic	Asbestos	Sampled – Not Detected				Old Grey Mastic High Level A/C Ductwork			R562251		
43561	INACTIVE	P	P069-00-2/240/ WAL-002	Wall: Internal - 2 - Store - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Matt Walls thickness 200 0.01% Ceiling Concrete Not Painted			R562252		
44091	ACTIVE	P	P069-00-2/240/ WAL-004	Wall: Internal - 4 - Store - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Pink fire stopping material < 1m2 , to wall 4 above door			R602501	N	N
14069	ACTIVE	P	P069-00-2/241	Lobby - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43467	ACTIVE	P	P069-00-2/241	Lobby - Station Building - Knightsbridge Stn	Mastic	Asbestos	Sampled – Not Detected				Mastic to A/C ducting & wall penetrations throughout			R562251		
43468	ACTIVE	P	P069-00-2/241	Lobby - Station Building - Knightsbridge Stn	Plaster	Asbestos	Sampled – Not Detected				Plaster sampled to wall & ceiling (partial encapsulation)			R562251		



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23018	ACTIVE	P	P069-00-2/241/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				Plaster, solid above false ceiling				Yes	
43559	INACTIVE	P	P069-00-2/241/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Matt Walls thickness 200 0.02%			R562252	N	N
45237	ACTIVE	P	P069-00-2/241/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Matt Walls and Ceiling 200 0.01%				N	N
43499	ACTIVE	P	P069-00-2/241/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Green-Olive Gloss Paint to Ceiling Thickness 280um / Percentage 4.01			R562252		
23827	ACTIVE	P	P069-00-2/241/WAL-004	Wall: Internal - 4 - Lobby - Station Building - Knightsbridge Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding to wall 4 cable management system					
14070	ACTIVE	P	P069-00-2/242	Passage - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23020	ACTIVE	P	P069-00-2/242/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Knightsbridge Stn	Void	Asbestos	No Access: Presumed				Above supalux boxing					
23019	ACTIVE	P	P069-00-2/242/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Knightsbridge Stn		Asbestos	Surveyed – Not Detected				Supalux boxing					
69380	ACTIVE	P	P069-00-2/242/FLR-01	Floor - 1 - Passage - Station Building - Knightsbridge Stn	Pipe Lagging	Asbestos	Sampled – Not Detected				MMMF insulation to pipework below hatches	1		R679615		Y
14071	ACTIVE	P	P069-00-2/316	Locker Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
44012	ACTIVE	P	P069-00-2/316	Locker Room - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				A/C metal ductwork - new MMMF and supalux insulation to ceiling and walls			R596201	N	N
44011	ACTIVE	P	P069-00-2/316	Locker Room - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Plaster on brickwork and concrete slab to walls			R596201	N	N
44010	ACTIVE	P	P069-00-2/316	Locker Room - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Ceramic tiles on concrete slab to floor			R596201	N	N
44013	ACTIVE	P	P069-00-2/316	Locker Room - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Supalux boxing, RSJ, cables and pipework within, to walls 4, 5 and ceiling			R596201	N	N
14072	ACTIVE	P	P069-00-2/331	Mess Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14073	ACTIVE	P	P069-00-2/332	Mess Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14074	ACTIVE	P	P069-00-2/396	SVC - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23023	ACTIVE	P	P069-00-2/396	SVC - Station Building - Knightsbridge Stn	Gasket :Pipework	Asbestos	Known				2x 0.05M pipe gasket 1 x blue, 1 x red		2			
23022	ACTIVE	P	P069-00-2/396	SVC - Station Building - Knightsbridge Stn	Gasket :Pipework	Asbestos	Known				2x 0.05m² pipe gasket - 1x blue, 1 x red		2			
23024	ACTIVE	P	P069-00-2/396	SVC - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Lead paint on pipe work red and blue					
23828	ACTIVE	P	P069-00-2/396/CLG-01	Ceiling: Solid - 1 - SVC - Station Building - Knightsbridge Stn	Void	Asbestos	No Access: Presumed				Above supalux boxing				N	N
23021	ACTIVE	P	P069-00-2/396/CLG-01	Ceiling: Solid - 1 - SVC - Station Building - Knightsbridge Stn		Asbestos	Surveyed – Not Detected				Supalux boxing					
14075	ACTIVE	P	P069-00-2/397	SVC - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23025	ACTIVE	P	P069-00-2/397/FLR-01	Floor - 1 - SVC - Station Building - Knightsbridge Stn		Asbestos	Surveyed – Not Detected				Loose board- supalux					
23829	ACTIVE	P	P069-00-2/397/FLR-01	Floor - 1 - SVC - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				Loose Supalux Panel to Floor					Yes
23026	ACTIVE	P	P069-00-2/397/WAL-002	Wall: Internal - 2 - SVC - Station Building - Knightsbridge Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard		1			
14076	ACTIVE	P	P069-00-2/398	SVC - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14077	ACTIVE	P	P069-00-2/406	Shower Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14078	ACTIVE	P	P069-00-2/411	Store - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23127	ACTIVE	P	P069-00-2/411/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Knightsbridge Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Ducting - Ceiling adjacent Wall 2					
43703	ACTIVE	P	P069-00-2/411/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				New A/C metal ductwork within supalux boxing to wall 3			R589551	N	N
23128	INACTIVE	P	P069-00-2/411/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Knightsbridge Stn		Asbestos	Surveyed – Not Detected				Above Supalux boxing					
23126	ACTIVE	P	P069-00-2/411/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				Supalux Boxing - No Access within - A/C Ductwork within R&D Survey 589551					



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43702	ACTIVE	P	P069-00-2/411/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Supalux boxing 8m2 to wall 3			R589551	N	N
43701	ACTIVE	P	P069-00-2/411/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Mastic throughout (2x2m) to A/C metal ductwork in boxing to wall 3			R589551	N	N
23608	ACTIVE	P	P069-00-2/411/FLR-01	Floor - 1 - Store - Station Building - Knightsbridge Stn	Void	Asbestos	No Access: Presumed				Inspection Chamber - No Access Below - Lifting Gear Required for Drain Covers - Intrusive Survey Required					Yes
23027	ACTIVE	P	P069-00-2/411/WAL-002	Wall: Internal - 2 - Store - Station Building - Knightsbridge Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing with A/C ductwork within, new slip joint.					
14079	ACTIVE	P	P069-00-2/412	Store - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14080	ACTIVE	P	P069-00-2/413	Store - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
14081	ACTIVE	P	P069-00-2/416	Toilet: Unisex - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
43458	ACTIVE	P	P069-00-2/416	Toilet: Unisex - Station Building - Knightsbridge Stn	Plaster	Asbestos	Sampled – Not Detected				Plaster Sampled on Walls & Ceiling			R562251		
43995	ACTIVE	P	P069-00-2/416	Toilet: Unisex - Station Building - Knightsbridge Stn	Mastic	Asbestos	Sampled – Not Detected				Mastic to A/C ductwork - Non Asbestos			R596201		
43538	INACTIVE	P	P069-00-2/416	Toilet: Unisex - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Matt False Ceiling Sulalux - Not Painted			R562252	Y	N
43537	INACTIVE	P	P069-00-2/416	Toilet: Unisex - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Matt Walls thickness 230 0.01%			R562252	N	N
43460	ACTIVE	P	P069-00-2/416/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Knightsbridge Stn		Asbestos	Surveyed – Not Detected				Firestopping - Throughout to wall penetrations, within false ceiling			R562251	Y	
23129	ACTIVE	P	P069-00-2/416/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Knightsbridge Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
23130	ACTIVE	P	P069-00-2/416/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				Plaster, solid & vermiculite pipe above false ceiling				Yes	
14082	ACTIVE	P	P069-00-2/417	Toilet: Female - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43471	ACTIVE	P	P069-00-2/417	Toilet: Female - Station Building - Knightsbridge Stn	Plaster	Asbestos	Sampled – Not Detected				Plaster sampled on Walls & Ceilings			R562251		



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43472	ACTIVE	P	P069-00-2/417	Toilet: Female - Station Building - Knightsbridge Stn	Mastic	Asbestos	No Access: Presumed				Mastic to A/C Units to be investigated - Intrusive Survey Required			R562251		
43552	INACTIVE	P	P069-00-2/417	Toilet: Female - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Matt Upper Part of Walls and Ceiling 210 0.01%			R562252	N	N
43553	INACTIVE	P	P069-00-2/417	Toilet: Female - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Matt Lower Part of Walls - Tiles			R562252	N	N
23131	ACTIVE	P	P069-00-2/417/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				Above false ceiling					
14083	ACTIVE	P	P069-00-2/418	Toilet: Male - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43477	ACTIVE	P	P069-00-2/418	Toilet: Male - Station Building - Knightsbridge Stn	Mastic	Asbestos	Sampled – Not Detected				Mastic to Duct Joints			R562251		
43474	ACTIVE	P	P069-00-2/418	Toilet: Male - Station Building - Knightsbridge Stn	Plaster	Asbestos	Sampled – Not Detected				Plaster sampled to Walls & Ceiling			R562251		
43473	ACTIVE	P	P069-00-2/418	Toilet: Male - Station Building - Knightsbridge Stn	Mastic	Asbestos	Sampled – Not Detected				Mastic to A/C, supalux boarding and to wall penetrations - throughout			R562251		
23133	ACTIVE	P	P069-00-2/418	Toilet: Male - Station Building - Knightsbridge Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boarding around air duct					
43475	ACTIVE	P	P069-00-2/418	Toilet: Male - Station Building - Knightsbridge Stn	Mastic	Asbestos	Sampled – Not Detected				General Penetrations - Mastic to cable management system/ pipework penetrations to high level walls throughout			R562251		
43476	ACTIVE	P	P069-00-2/418	Toilet: Male - Station Building - Knightsbridge Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux Boarding to Duct Cover			R562251		
23132	ACTIVE	P	P069-00-2/418/FLR-01	Floor - 1 - Toilet - Station Building - Knightsbridge Stn	Void	Asbestos	No Access: Presumed				Inspection Chamber - No Access Below - Intrusive Survey Required					Yes
14084	ACTIVE	P	P069-00-2/420	Toilet: Unisex - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14085	ACTIVE	P	P069-00-2/451	Tenancy - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23134	ACTIVE	P	P069-00-2/451/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Knightsbridge Stn	Void	Asbestos	No Access: Presumed				Above false ceiling					
14086	ACTIVE	P	P069-00-2/459	ATM - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14087	ACTIVE	P	P069-00-2/460	ATM - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14088	ACTIVE	P	P069-00-2/661	Switch Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43483	ACTIVE	P	P069-00-2/661	Switch Room - Station Building - Knightsbridge Stn	Cable Duct: Other	Asbestos	Sampled – Not Detected				Cable ducts - within Concrete Structure - NADIS R&D Survey R589551			R562251		
43480	ACTIVE	P	P069-00-2/661	Switch Room - Station Building - Knightsbridge Stn	Void	Asbestos	Sampled – Not Detected				Hatch Sealed - No Access - NAD R&D Survey R589551			R562251		
43481	ACTIVE	P	P069-00-2/661	Switch Room - Station Building - Knightsbridge Stn	Cable Duct: Other	Asbestos	Surveyed – Not Detected				No ducts visible where cables enter walls - Confirmed no Ducts on site visit 10/02/2017 by APB			R562251		
43478	ACTIVE	P	P069-00-2/661	Switch Room - Station Building - Knightsbridge Stn	Plaster	Asbestos	Sampled – Not Detected				Plaster sampled on walls			R562251		
43712	ACTIVE	P	P069-00-2/661	Switch Room - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Brickwork/ concrete slab to sides and top, floor			R589551	N	N
43710	ACTIVE	P	P069-00-2/661	Switch Room - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				MMMF insulation - loose 1m2 to cable duct			R589551	N	N
43707	ACTIVE	P	P069-00-2/661	Switch Room - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Plaster on wire mesh on concrete slab to ceiling in false ceiling			R589551	N	N
43705	ACTIVE	P	P069-00-2/661	Switch Room - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Concrete slab to ceiling in false ceiling			R589551		
43484	ACTIVE	P	P069-00-2/661	Switch Room - Station Building - Knightsbridge Stn	Other Boarding	Asbestos	Sampled – Not Detected				Vermiculite to Pipework			R562251		
43482	ACTIVE	P	P069-00-2/661	Switch Room - Station Building - Knightsbridge Stn	Other Boarding	Asbestos	Sampled – Not Detected				Backing Boards to below bottom LHS of Switch Boxes			R562251		
43711	ACTIVE	P	P069-00-2/661	Switch Room - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Pink Firestop 1m2 to cable duct			R589551	N	N
43709	ACTIVE	P	P069-00-2/661	Switch Room - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Mastic 1m to cable duct			R589551	N	N
43708	ACTIVE	P	P069-00-2/661	Switch Room - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Hessian cable wrapping to HV cable in false ceiling			R589551	N	N
43706	ACTIVE	P	P069-00-2/661	Switch Room - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Plastic/ metal cable duct - cables within to ceiling in false ceiling			R589551	N	N
43704	ACTIVE	P	P069-00-2/661	Switch Room - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Supalux boxing 4m2 to ceiling by door			R589551	N	N
43497	ACTIVE	P	P069-00-2/661	Switch Room - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Emulsion Paint to Walls and Ceiling Thickness 300um / Percentage 1.35%			R562252		
43479	ACTIVE	P	P069-00-2/661/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Knightsbridge Stn	Plaster	Asbestos	Sampled – Not Detected				Plaster sampled on ceiling			R562251		



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23135	ACTIVE	P	P069-00-2/661/FLR-01	Floor - 1 - Switch Room - Station Building - Knightsbridge Stn		Asbestos	Surveyed – Not Detected				2x Supalux boarding					
23136	ACTIVE	P	P069-00-2/661/FLR-01 80875456	Floor - 1 - Switch Room - Station Building - Knightsbridge Stn Floor	Cable Duct: Other	Asbestos	No Access: Presumed				Cable ducts - Beneath Supalux boarding - floor to walls 3 & 4; No access to sample Cable Ducts - Intrusive Survey Required.					Yes
23138	ACTIVE	P	P069-00-2/661/WAL-003 80875449	Wall: Internal - 3 - Switch Room - Station Building - Knightsbridge Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				3 x Transformer Box plus 1x wall 7 Insulation material within - No Access - Due to boxes being live; Only 3no. transformer boxes present in 2020 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		3			
23139	INACTIVE	P	P069-00-2/661/WAL-003 80875449	Wall: Internal - 3 - Switch Room - Station Building - Knightsbridge Stn Wall: Internal	Isolator Switches	Asbestos	Removed				1x Switch box 30 amp Insulation material within - No Access - Due to boxes being live; All boxes were checked and either the arc chutes confirmed non asbestos or the asbestos arc chutes removed on the 13/07/2017		1			
23137	INACTIVE	P	P069-00-2/661/WAL-007	Wall: Internal - 7 - Switch Room - Station Building - Knightsbridge Stn	Isolator Switches	Asbestos	Removed				10x Switch boxes - 3 x 30 amps, 1 x 100 amps, 6 x 60 amps and Busbar All boxes were checked and either the arc chutes confirmed non asbestos or the asbestos arc chutes removed on the 13/07/2017		10			
14089	ACTIVE	P	P069-00-2/662	Switch Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43486	ACTIVE	P	P069-00-2/662	Switch Room - Station Building - Knightsbridge Stn	Other Boarding	Asbestos	Sampled – Not Detected				Vermiculite to Pipework			R562251		
43487	ACTIVE	P	P069-00-2/662	Switch Room - Station Building - Knightsbridge Stn	Cable Duct: Other	Asbestos	No Access: Presumed				Cable Ducts - No Access due to Firestops - Intrusive Survey Required Walls 1 & 2 Floor & Wall 1			R562251		
43485	ACTIVE	P	P069-00-2/662	Switch Room - Station Building - Knightsbridge Stn	Mastic	Asbestos	Sampled – Not Detected				Mastic to H/L A/C Ducting			R562251		
43498	ACTIVE	P	P069-00-2/662	Switch Room - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Emulsion Paint to Walls and Ceiling Thickness 300um / Percentage 1.35%			R562252		
23840	ACTIVE	P	P069-00-2/662/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Knightsbridge Stn	Isolator Switches	Asbestos	Strongly Presumed				6x Switch boxes - 1 x 200 amps, 5 x 200 amps Including Busbar Insulation material within - No Access - Due to boxes being live; No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		6			



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23140	ACTIVE	P	P069-00-2/662/WAL-003 80875460	Wall: Internal - 3 - Switch Room - Station Building - Knightsbridge Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box + 1 x Transformer Box REMOVED (confirmed 04/02/2016) Insulation material within - No Access - Due to boxes being live; No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2			
14090	ACTIVE	P	P069-00-2/669	Switch Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23141	ACTIVE	P	P069-00-2/669/WAL-005	Wall: Internal - 5 - Switch Room - Station Building - Knightsbridge Stn		Asbestos	Surveyed – Not Detected				Supalux boarding					
14091	ACTIVE	P	P069-00-2/670	Switch Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23142	ACTIVE	P	P069-00-2/670/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Knightsbridge Stn	Isolator Switches	Asbestos	Strongly Presumed				1x Isolators - 1 x 30 amps No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1			
14092	ACTIVE	P	P069-00-2/671	Switch Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14093	ACTIVE	P	P069-00-2/672	Switch Cupboard - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23143	ACTIVE	P	P069-00-2/672/CLG-01	Ceiling: Solid - 1 - Switch Cupboard - Station Building - Knightsbridge Stn	Void	Asbestos	No Access: Presumed				Above metal ceiling (high)					
23144	ACTIVE	P	P069-00-2/672/WAL-001	Wall: Internal - 1 - Switch Cupboard - Station Building - Knightsbridge Stn	Isolator Switches	Asbestos	No Access: Presumed				1x Isolators 60 amps Room not accessed during 2020 re-inspection. Key not available with station supervisor at the time.		1			
14094	ACTIVE	P	P069-00-2/673	Switch Cupboard - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23145	INACTIVE	P	P069-00-2/673	Switch Cupboard - Station Building - Knightsbridge Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Duplicate of 22999					
22999	ACTIVE	P	P069-00-2/673	Switch Cupboard - Station Building - Knightsbridge Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Room not on current station layout					
14095	ACTIVE	P	P069-00-2/747	SCR - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14096	ACTIVE	P	P069-00-2/751	Store - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43488	ACTIVE	P	P069-00-2/751	Store - Station Building - Knightsbridge Stn	Plaster	Asbestos	Sampled – Not Detected				Plaster sampled to Walls & Ceiling			R562251		
23841	ACTIVE	P	P069-00-2/751/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				Plaster, solid above false ceiling				Yes	
23146	ACTIVE	P	P069-00-2/751/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Knightsbridge Stn		Asbestos	Surveyed – Not Detected				Office - Supalux					
43560	INACTIVE	P	P069-00-2/751/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Blue Matt Walls thickness 110 0.01%			R562252	N	N
43500	ACTIVE	P	P069-00-2/751/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				White Matt Paint to Ceiling Thickness 190 / Percentage 0.55% (<1% - Borderline)			R562252		
14097	ACTIVE	P	P069-00-2/752	Station Control Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23147	ACTIVE	P	P069-00-2/752	Station Control Room - Station Building - Knightsbridge Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New build					
14098	ACTIVE	P	P069-00-2/771	Pump Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
69363	ACTIVE	P	P069-00-2/771	Pump Room - Station Building - Knightsbridge Stn	Void	Asbestos	No Access: Presumed				No access to floor ducts - heavy and jammed shut			R679615		
14099	ACTIVE	P	P069-00-2/776	Plant Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46854	ACTIVE	P	P069-00-2/776	Plant Room - Station Building - Knightsbridge Stn	Cable Ducts: Cement	Asbestos	No Access: Presumed				possible cable ducts to floor - no access					
46853	ACTIVE	P	P069-00-2/776/WAL-004	Wall: Internal - 4 - Plant Room - Station Building - Knightsbridge Stn	Other Electrical Boxes	Asbestos	Presumed				materials within combination fuse switch to wall 4					
14100	ACTIVE	P	P069-00-2/777	Fan Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
69367	ACTIVE	P	P069-00-2/777	Fan Room - Station Building - Knightsbridge Stn	Other Boarding	Asbestos	Sampled – Not Detected				Woodite strip to door frames to wall 4	3		R679615		
14102	ACTIVE	P	P069-00-2/787	Service Riser - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14103	ACTIVE	P	P069-00-2/901	Tenancy - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43690	ACTIVE	P	P069-00-2/901	Tenancy - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Supalux boxing 2m2 Above kiosk window to walll			R589551	N	N
43691	ACTIVE	P	P069-00-2/901	Tenancy - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Fibreboard boxing 3m2 to wall 4			R589551	N	N
43692	ACTIVE	P	P069-00-2/901	Tenancy - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Supalux boxing 3m2 to wall 2			R589551	N	N
43490	ACTIVE	P	P069-00-2/901	Tenancy - Station Building - Knightsbridge Stn		Asbestos	Removed				Safe - No Access Within - Intrusive Survey Required Removed by others			R562251		
43555	INACTIVE	P	P069-00-2/901	Tenancy - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Black Matt Lower Part of Walls thickness 160 0.02%			R562252	N	N
43554	INACTIVE	P	P069-00-2/901	Tenancy - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Matt Walls and Ceiling thickness 290 0.01%			R562252	N	N
23149	ACTIVE	P	P069-00-2/901/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				Plastic cables, metal conduits with metal cable management system Above false ceiling					
43489	ACTIVE	P	P069-00-2/901/WAL-004	Wall: Internal - 4 - Tenancy - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				Boxing to Wall 4 - No Access - NAD R&D Survey R589551			R562251		
14104	ACTIVE	P	P069-00-2/902	Disused Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43491	ACTIVE	P	P069-00-2/902	Disused Room - Station Building - Knightsbridge Stn	Rope Gaskets	Asbestos	No Access: Presumed				Gaskets to A/C ductwork			R562251		
43470	ACTIVE	P	P069-00-2/902	Disused Room - Station Building - Knightsbridge Stn	Mastic	Asbestos	Sampled – Not Detected				Mastic to galvanized duct on wall - RHS Mastic to supalux boarding surrounding A/C ducting			R562251		
43469	ACTIVE	P	P069-00-2/902/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Knightsbridge Stn	Other Boarding	Asbestos	Sampled – Not Detected				Vermiculite to pipes to ceiling			R562251		
23150	ACTIVE	P	P069-00-2/902/FLR-01	Floor - 1 - Disused Room - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				Inspection Chamber - Concrete to manhole structure to floor, wall & ceiling					Yes
43562	INACTIVE	P	P069-00-2/902/FLR-01	Floor - 1 - Disused Room - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Gloss Walls and Ceiling thickness 230 0.11%			R562252	N	N
43563	INACTIVE	P	P069-00-2/902/FLR-01	Floor - 1 - Disused Room - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Gloss Steel Beam thickness 200 0.28%			R562252	N	N



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23842	INACTIVE	P	P069-00-2/902/WAL-002	Wall: Internal - 2 - Disused Room - Station Building - Knightsbridge Stn	Isolator Switches	Asbestos	Strongly Presumed				2x Switches - 1blue, 1 grey - 1 x 200 amps, 1 x 100 amps. Walls 2&6		2			
23151	INACTIVE	P	P069-00-2/902/WAL-006	Wall: Internal - 6 - Disused Room - Station Building - Knightsbridge Stn	Isolator Switches	Asbestos	Removed				2x Switches - 1blue, 1 grey - 1 x 200 amps, 1 x 100 amps. Walls 2&6 Insulation material within - No Access - Due to boxes being live;		2			
14105	ACTIVE	P	P069-00-2/903	Disused Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14106	ACTIVE	P	P069-00-2/904	Disused Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43492	ACTIVE	P	P069-00-2/904	Disused Room - Station Building - Knightsbridge Stn	Plaster	Asbestos	Sampled – Not Detected				Plaster sampled on walls & ceiling AFC			R562251		
43493	ACTIVE	P	P069-00-2/904/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Knightsbridge Stn	Other Electrical Boxes	Asbestos	Surveyed – Not Detected				Metal electrical junction box - AFC Photo confirms box is new and not liable to contain asbestos - APB			R562251	Y	
43496	ACTIVE	P	P069-00-2/904/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Green-Olive Gloss Paint to Ceiling above False Ceiling Thickness 270um / Percentage 0.55% (<1% - Borderline)			R562252	Y	
43558	INACTIVE	P	P069-00-2/904/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Matt Walls Thickness 210 - 0.01%			R562252	N	N
14107	ACTIVE	P	P069-00-3/091	Circulation Area - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23152	ACTIVE	P	P069-00-3/091/FLR-01	Floor - 1 - Circulation Area - Station Building - Knightsbridge Stn	Void	Asbestos	No Access: Presumed				Beneath inspection cover - (access into machine chamber?)					Yes
14108	ACTIVE	P	P069-00-3/236	Disused Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43584	ACTIVE	P	P069-00-3/236	Disused Room - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Concrete troughing, Terracotta ducts to floor and raised concrete slab - corner of wall 1/2			R567376	N	N
43585	ACTIVE	P	P069-00-3/236	Disused Room - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Plastic cables / metal conduits with metal cable management system throughout, Breezeblocks to wall 4			R567376	N	N
43582	ACTIVE	P	P069-00-3/236	Disused Room - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Partial ceramic tiles throughout to walls			R567376	N	N
43587	ACTIVE	P	P069-00-3/236	Disused Room - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Modern fire stopping and mastic to new breezeblock wall area and within terracotta ducts, metal pipework entering wall 4, high level			R567376	N	N
43583	ACTIVE	P	P069-00-3/236	Disused Room - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Render / plaster throughout to walls, to decorative columes/alcove			R567376	N	N



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43581	ACTIVE	p	P069-00-3/236	Disused Room - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Concrete slabs with partial concrete panels throughout to floor			R567376	N	N
43509	ACTIVE	p	P069-00-3/236	Disused Room - Station Building - Knightsbridge Stn	Plaster	Asbestos	Sampled – Not Detected				Plaster sampled to: throughout to walls to decorative columns to decorative alcove			R567376		
43612	ACTIVE	p	P069-00-3/236	Disused Room - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Disused Store Room – walls and ceiling to the LHS of the room - Cream Gloss Paint : Thickness 720um / 15.5%			R567377		
43613	ACTIVE	p	P069-00-3/236	Disused Room - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Disused Store Room – walls and ceiling to the RHS of the room - Cream Matt Paint : Thickness 320um / 7.78%			R567377		
45238	INACTIVE	p	P069-00-3/236/ FLR-01	Floor - 1 - Disused Room - Station Building - Knightsbridge Stn	Debris: Cement	Asbestos	Removed				Cement flat sheet debris within floor rubble - debris was found during SFA works - Edenbeck attended site and removed debris - ES9547h - 10/02/2019. NB Additional debris may become evident if further breakout is required.				N	N
43510	ACTIVE	p	P069-00-3/236/ FLR-01	Floor - 1 - Disused Room - Station Building - Knightsbridge Stn	Void	Asbestos	Sampled – Not Detected				Concrete Troughing - No Access within Investigated 07/09/2017 - NADIS R602502			R567376		
14109	ACTIVE	p	P069-00-3/237	Passage - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43594	ACTIVE	p	P069-00-3/237	Passage - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Brown composite backing board 1m2 to high level, by access stairs			R567376	N	N
43595	ACTIVE	p	P069-00-3/237	Passage - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Grout and render throughout to walls throughout behind ceramic tiles			R567376	N	N
44002	ACTIVE	p	P069-00-3/237	Passage - Station Building - Knightsbridge Stn	Other Boarding	Asbestos	Sampled – Not Detected				Asbestos Board - Strongly Presumed; Within lower CRMS along passage opposite door to 3/733; Investigated 23/06/2017 - Plasterboard with MMMF within - NADIS R559251			R559251		
44025	ACTIVE	p	P069-00-3/237	Passage - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Plasterboard with MMMF within matrix, <1m2, within cable management system to wall opposite Passage 3/733 within Passage 3/237			R559251	N	N
43506	ACTIVE	p	P069-00-3/237	Passage - Station Building - Knightsbridge Stn	Plaster	Asbestos	Sampled – Not Detected				Plaster sampled to: throughout to walls and behind ceramic tiles to decorative columns to decorative alcoving at High Level			R567376		
43597	ACTIVE	p	P069-00-3/237	Passage - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Fire stopping / mastic throughoutTo external wall penetrations by 3/732 (breezeblock wall)			R567376		



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
45239	INACTIVE	p	P069-00-3/237	Passage - Station Building - Knightsbridge Stn	Other Boarding	Asbestos	Presumed				Brown composite backing Board 1m² to high level, by access Stairs	1			N	N
43598	ACTIVE	p	P069-00-3/237	Passage - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Concrete throughout to Over Bridge metal arches to 3/639			R567376	N	N
43596	ACTIVE	p	P069-00-3/237	Passage - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				MMMF insulation to entrance area 4/203 at platform level			R567376		
43617	ACTIVE	p	P069-00-3/237	Passage - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Passage – Decorative columns (throughout) - White Matt Paint : Thickness 330um / 6.92%			R567377		
43631	INACTIVE	p	P069-00-3/237	Passage - Station Building - Knightsbridge Stn		Lead Paint/Lead	Known				Black Matt Partial mid level wall 730 thickness 0.10% Patch			R567377	N	N
14110	ACTIVE	p	P069-00-3/238	Passage - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43601	ACTIVE	p	P069-00-3/238	Passage - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Concrete throughout to Over Bridge metal arches to 3/639			R567376	N	N
43600	ACTIVE	p	P069-00-3/238	Passage - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				MMMF insulation to entrance area 4/203 at platform level			R567376	N	N
43507	ACTIVE	p	P069-00-3/238	Passage - Station Building - Knightsbridge Stn	Plaster	Asbestos	Sampled – Not Detected				Plaster sampled to: throughout to walls and behind ceramic tiles to decorative columns to decorative alcoving at High Level			R567376		
43599	ACTIVE	p	P069-00-3/238	Passage - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Brown composite backing board 1m2 to high level, by access stairs			R567376	N	N
45240	INACTIVE	p	P069-00-3/238	Passage - Station Building - Knightsbridge Stn	Other Boarding	Asbestos	Presumed				Brown composite backing Board 1m² to high level, by access Stairs	1			N	N
43610	ACTIVE	p	P069-00-3/238	Passage - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Matt Paint to High level walls and ceiling : Thickness 560um / 1.68%			R567377		
43614	ACTIVE	p	P069-00-3/238	Passage - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Passage – decorative arches of the entrance to 3/986 Vent Shaft - Dark Green Matt Paint: Thickness 380um / 9.13%			R567377		
14111	ACTIVE	p	P069-00-3/239	Service Riser - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14112	ACTIVE	p	P069-00-3/576	Stairs: Linear - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43503	ACTIVE	p	P069-00-3/576	Stairs: Linear - Station Building - Knightsbridge Stn	Plaster	Asbestos	Sampled – Not Detected				Plaster sampled to: throughout to walls and behind ceramic tiles to decorative columns to decorative alcoving at High Level			R567376		
43580	ACTIVE	p	P069-00-3/576	Stairs: Linear - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Fire stopping / mastic throughout to external wall penetrations by 3/732 (breezeblock wall			R567376	N	N



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43566	ACTIVE	P	P069-00-3/576	Stairs: Linear - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Concrete Slab to floor throughout			R567376	N	N
43568	ACTIVE	P	P069-00-3/576	Stairs: Linear - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Render / plaster 2.5m2 to decorative columns			R567376	N	N
43577	ACTIVE	P	P069-00-3/576	Stairs: Linear - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				New A/C unit to walls			R567376	N	N
43567	ACTIVE	P	P069-00-3/576	Stairs: Linear - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Render / plaster Throughout to walls and behind ceramic tiles			R567376	N	N
43569	ACTIVE	P	P069-00-3/576	Stairs: Linear - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Render / plaster 3m2 to decorative alcoving at high level			R567376	N	N
43575	ACTIVE	P	P069-00-3/576	Stairs: Linear - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Plaster Throughout to decorative columns and above by shaft 3/986			R567376	N	N
43573	ACTIVE	P	P069-00-3/576	Stairs: Linear - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Fibreglass boarding debris above entrance to bottom of stairs 3/576			R567376		
45241	INACTIVE	P	P069-00-3/576	Stairs: Linear - Station Building - Knightsbridge Stn	Other Boarding	Asbestos	Removed				Brown composite backing Board 1m² to high level, by access Stairs - Removed by Edenbeck ES9547j 30/07/2021	1			N	N
43579	ACTIVE	P	P069-00-3/576	Stairs: Linear - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Partial breezeblock by 3/731 to walls, modern fire stopping and mastics to breezeblock wall			R567376	N	N
43578	ACTIVE	P	P069-00-3/576	Stairs: Linear - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Metal pipework - some with foam insulation throughout			R567376	N	N
43576	ACTIVE	P	P069-00-3/576	Stairs: Linear - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Render / plaster Throughout to walls and ceiling throughout along passage			R567376	N	N
43574	ACTIVE	P	P069-00-3/576	Stairs: Linear - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				MMMF insulation to entrance area 4/203 at platform level			R567376	N	N
43572	ACTIVE	P	P069-00-3/576	Stairs: Linear - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Grout and render throughout to walls throughout behind ceramic tiles			R567376	N	N
43570	ACTIVE	P	P069-00-3/576	Stairs: Linear - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Plastic cables / metal conduits with metal cable management system throughout			R567376	N	N
43571	ACTIVE	P	P069-00-3/576	Stairs: Linear - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Brown composite backing board 1m2 to high level, by access stairs			R567376	N	N
14113	ACTIVE	P	P069-00-3/601	Stairs: Linear - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14114	ACTIVE	P	P069-00-3/602	Stairs: Linear - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24000	ACTIVE	P	P069-00-3/636/CLG-01	Ceiling: Solid - 1 - Overbridge - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above plaster, solid ceiling				Yes	



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23207	ACTIVE	P	P069-00-3/637/CLG-01	Ceiling: Solid - 1 - Overbridge - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above plaster, solid ceiling				Yes	
46463	ACTIVE	P	P069-00-3/638	Overbridge - Station Building - Knightsbridge Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel ring caulking behind render	1		R634902	N	N
43505	ACTIVE	P	P069-00-3/638	Overbridge - Station Building - Knightsbridge Stn	Plaster	Asbestos	Sampled – Not Detected				Plaster sampled to: throughout to walls and behind ceramic tiles to decorative columns to decorative alcoving at High Level			R567376		
45242	INACTIVE	P	P069-00-3/638	Overbridge - Station Building - Knightsbridge Stn	Other Boarding	Asbestos	Removed				Brown composite backing Board 1m² to high level, by access Stairs Removed by Edenbeck under ES9547j - 28/07/2021	1			N	N
44092	ACTIVE	P	P069-00-3/638	Overbridge - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Brown composite panel 1 x < 1 m2 to wall at top of stairs			R602501	N	N
43618	ACTIVE	P	P069-00-3/638	Overbridge - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Overbridge – Decorative columns and alcoves at the top of the stairs - Dark Cream Matt Paint: Thickness 480um / 15.5%			R567377		
43625	INACTIVE	P	P069-00-3/638	Overbridge - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Dark Green Matt Arches 320 thickness 0.87% 4 No, Throughout			R567377	N	N
43630	INACTIVE	P	P069-00-3/638	Overbridge - Station Building - Knightsbridge Stn		Lead Paint/Lead	Known				Turquoise Gloss Ceramic tiles to the low level wall 640 thickness 0.31% Throughout			R567377	N	N
43622	ACTIVE	P	P069-00-3/638	Overbridge - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Overbridge - Arches - Dark Green Matt Paint - 4no Throughout Hoopers Court Thickness 320um / 0.87% (Borderline)			R567377		
43588	ACTIVE	P	P069-00-3/638/WAL-001	Wall: Internal - 1 - Overbridge - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Grout and render throughout to walls throughout behind ceramic tiles			R567376	N	N
43589	ACTIVE	P	P069-00-3/638/WAL-001	Wall: Internal - 1 - Overbridge - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Fibreglass boarding debris above entrance to bottom of stairs 3/576			R567376		
43591	ACTIVE	P	P069-00-3/638/WAL-001	Wall: Internal - 1 - Overbridge - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Metal pipework - some with foam insulation throughout			R567376	N	N
43593	ACTIVE	P	P069-00-3/638/WAL-001	Wall: Internal - 1 - Overbridge - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Concrete throughout to Over Bridge metal arches to 3/639			R567376	N	N
43590	ACTIVE	P	P069-00-3/638/WAL-001	Wall: Internal - 1 - Overbridge - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				MMMF insulation to entrance area 4/203 at platform level			R567376		
43592	ACTIVE	P	P069-00-3/638/WAL-001	Wall: Internal - 1 - Overbridge - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Partial breezeblock by 3/731 to walls, modern fire stopping and mastics to breezeblock wall			R567376	N	N



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43523	ACTIVE	P	P069-00-3/638/WAL-001	Wall: Internal - 1 - Overbridge - Station Building - Knightsbridge Stn	Other Boarding	Asbestos	Sampled – Not Detected				Brown composite backing board - Electrical Equipment in-situ; To high level, by access stairs 3/576, to wall 1 Investigated 17/08/2017 - NADIS - R602501		1	R567376		
43607	ACTIVE	P	P069-00-3/639	Overbridge - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Metal pipework - some with foam insulation throughout			R567376	N	N
43604	ACTIVE	P	P069-00-3/639	Overbridge - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				MMMF insulation to entrance area 4/203 at platform level			R567376	N	N
43602	ACTIVE	P	P069-00-3/639	Overbridge - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Brown composite backing board 1m2 to high level, by access stairs			R567376	N	N
43606	ACTIVE	P	P069-00-3/639	Overbridge - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Grout and render throughout to walls throughout behind ceramic tiles			R567376	N	N
43603	ACTIVE	P	P069-00-3/639	Overbridge - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Concrete slab to floor throughout			R567376	N	N
43605	ACTIVE	P	P069-00-3/639	Overbridge - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Plastic cables / metal conduits with metal cable management system throughout			R567376	N	N
43508	ACTIVE	P	P069-00-3/639	Overbridge - Station Building - Knightsbridge Stn	Plaster	Asbestos	Sampled – Not Detected				Plaster sampled to: throughout to walls and behind ceramic tiles to decorative columns to decorative alcoving at High Level			R567376		
43611	ACTIVE	P	P069-00-3/639	Overbridge - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Dark Cream Matt Paint to Entrance Archway to Overbridge: Thickness 740um / 21.5%			R567377		
14115	ACTIVE	P	P069-00-3/671	Switch Cupboard - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14116	ACTIVE	P	P069-00-3/672	Switch Cupboard - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43511	ACTIVE	P	P069-00-3/672/CLG-01	Ceiling: Solid - 1 - Switch Cupboard - Station Building - Knightsbridge Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux Panels to False Ceilings & External Fascias			R567376		
14117	ACTIVE	P	P069-00-3/731	CER - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23208	ACTIVE	P	P069-00-3/731/FLR-01	Floor - 1 - CER - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				Beneath computer flooring - No Asbestos Detected Site Visit 21/06/2017					Yes
23209	ACTIVE	P	P069-00-3/731/WAL-003	Wall: Internal - 3 - CER - Station Building - Knightsbridge Stn	Isolator Switches	Asbestos	Presumed				2 x Iron Clad Isolators / Fuse Switches Flash Guards - Non Asbestos Type Materials Brown Composite Boards - Presumed No access during 2020 re-inspection. Area under Skanska construction works.		2			



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14118	ACTIVE	P	P069-00-3/732	Switch Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23210	ACTIVE	P	P069-00-3/732/FLR-01	Floor - 1 - Switch Room - Station Building - Knightsbridge Stn	Void	Asbestos	No Access: Presumed				Beneath computer flooring Visually checked as far as practicable on site visit 21/06/2017 and no asbestos containing materials were evident, however not all areas were accessible;					Yes
14119	ACTIVE	P	P069-00-3/733	CER - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14120	ACTIVE	P	P069-00-3/771	Pump Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23211	ACTIVE	P	P069-00-3/771	Pump Room - Station Building - Knightsbridge Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
14121	ACTIVE	P	P069-00-3/772	Pump Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23213	ACTIVE	P	P069-00-3/772/CLG-01	Ceiling: Solid - 1 - Pump Room - Station Building - Knightsbridge Stn	Void	Asbestos	No Access: Presumed				Above Supalux panel				Yes	
23212	ACTIVE	P	P069-00-3/772/CLG-01	Ceiling: Solid - 1 - Pump Room - Station Building - Knightsbridge Stn		Asbestos	Surveyed – Not Detected				Supalux panel					
14122	ACTIVE	P	P069-00-3/981	Stairs - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44338	ACTIVE	P	P069-00-3/981	Stairs - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Concrete slab to floor, end walls and ceiling			R614926		
44339	ACTIVE	P	P069-00-3/981	Stairs - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Hessian rope throughout to metal tunnel ring flanges			R614926		
43501	ACTIVE	P	P069-00-3/981	Stairs - Station Building - Knightsbridge Stn	Caulking	Asbestos	Sampled – Not Detected				Caulking to Horizontal Tunnel Rings			R567376		
44337	ACTIVE	P	P069-00-3/981	Stairs - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Braided cables - cut 3 x 30m to left hand side of tunnel and loose in ceiling			R614926		
43522	ACTIVE	P	P069-00-3/981	Stairs - Station Building - Knightsbridge Stn	No Access	Asbestos	No Access: Presumed				No Access to High Level Areas			R567376		
43521	ACTIVE	P	P069-00-3/981	Stairs - Station Building - Knightsbridge Stn	Caulking	Asbestos	Sampled – Not Detected				Caulking to Tunnel Rings throughout Ground Floor Level			R567376		
44093	ACTIVE	P	P069-00-3/981	Stairs - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Caulking throughout to metal tunnel rings			R602501	N	N



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43629	INACTIVE	P	P069-00-3/981	Stairs - Station Building - Knightsbridge Stn		Lead Paint/Lead	Known				Green/Yellow Gloss Disused pipework 530 thickness 0.30% Throughout			R567377	N	N
45248	ACTIVE	P	P069-00-3/981	Stairs - Station Building - Knightsbridge Stn		Lead Paint/Lead	Known				White Matt Brickwork Walls				N	N
43626	INACTIVE	P	P069-00-3/981	Stairs - Station Building - Knightsbridge Stn		Lead Paint/Lead	Known				Green/Yellow Gloss Cat ladders and brackets 120 thickness 0.83 Throughout			R567377	N	N
43627	INACTIVE	P	P069-00-3/981	Stairs - Station Building - Knightsbridge Stn		Lead Paint/Lead	Known				Green/Yellow Gloss RSJ at high level 440 thickness 0.47% Throughout			R567377	N	N
43628	INACTIVE	P	P069-00-3/981	Stairs - Station Building - Knightsbridge Stn		Lead Paint/Lead	Known				White Matt Brickwork walls 840 thickness 0.01% Throughout			R567377	N	N
43615	ACTIVE	P	P069-00-3/981	Stairs - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Disused Vent Shaft – Walls - White Matt Paint: Thickness 510um / 16.3%			R567377		
14123	ACTIVE	P	P069-00-3/986	Disused Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43518	ACTIVE	P	P069-00-3/986	Disused Room - Station Building - Knightsbridge Stn	Lagging	Asbestos	Sampled – Not Detected				Sprayed Coating to Metal Corrugated Sheeting to additional shaft area			R567376		
43515	INACTIVE	P	P069-00-3/986	Disused Room - Station Building - Knightsbridge Stn	Rope Gaskets	Asbestos	Removed				Rope Gasket to top of ventilation shaft - street level No access during 2020 re-inspection. Area under Skanska construction works. This material(s) is liable to have been removed by the developer, as part of the major development of this area to introduce SFA at Knightsbridge Station; Knightsbridge Tube station will have step-free access by summer 2022, reached by a new entrance at Hooper's Court.	8		R567376		
43514	ACTIVE	P	P069-00-3/986	Disused Room - Station Building - Knightsbridge Stn	Plaster	Asbestos	Sampled – Not Detected				Decorative Plaster / Render within top shaft area; Below the adjacent metal corrugated area			R567376		
43512	ACTIVE	P	P069-00-3/986	Disused Room - Station Building - Knightsbridge Stn	Caulking	Asbestos	Sampled – Not Detected				Caulking throughout to Tunnel Ring Flanges: Samples taken from Ground Floor, First Floor, Second Floor			R567376		
43516	INACTIVE	P	P069-00-3/986	Disused Room - Station Building - Knightsbridge Stn	Cable Ducts: Cement	Asbestos	Removed				Cement Duct / Pipe - to side of Vent Shaft to High Level Removed by Edenbeck 10/08/2017	3		R567376		



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43517	INACTIVE	P	P069-00-3/986	Disused Room - Station Building - Knightsbridge Stn	Other Electrical Boxes	Asbestos	Removed				Electrical Box at top of Ventilation Shaft - No Access - Presumed No access during 2020 re-inspection. Area under Skanska construction works. This material(s) is liable to have been removed by the developer, as part of the major development of this area to introduce SFA at Knightsbridge Station; Knightsbridge Tube station will have step-free access by summer 2022, reached by a new entrance at Hooper's Court.		1	R567376		
43519	INACTIVE	P	P069-00-3/986	Disused Room - Station Building - Knightsbridge Stn	No Access	Asbestos	Removed				No Access to High Level Top of Shaft - over the access steps / cat ladder This material(s) is liable to have been removed by the developer, as part of the major development of this area to introduce SFA at Knightsbridge Station; Knightsbridge Tube station will have step-free access by summer 2022, reached by a new entrance at Hooper's Court.			R567376		
43520	INACTIVE	P	P069-00-3/986	Disused Room - Station Building - Knightsbridge Stn	No Access	Asbestos	Removed				No Access to Locked Fire Door to top of shaft area This material(s) is liable to have been removed by the developer, as part of the major development of this area to introduce SFA at Knightsbridge Station; Knightsbridge Tube station will have step-free access by summer 2022, reached by a new entrance at Hooper's Court.			R567376		
43513	ACTIVE	P	P069-00-3/986	Disused Room - Station Building - Knightsbridge Stn	Cable: Sheath	Asbestos	Sampled – Not Detected				Braided Cables to floor by access stairs to RHS of additional top area		2	R567376		
43502	ACTIVE	P	P069-00-3/986	Disused Room - Station Building - Knightsbridge Stn	Caulking	Asbestos	Sampled – Not Detected				Caulking to Horizontal & Vertical Tunnel Rings			R567376		
43621	ACTIVE	P	P069-00-3/986	Disused Room - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Top of Shaft 3/986 - Guard Rail - Black / Orange Gloss Paint Thickness 250um / 28.5%			R567377		
43620	ACTIVE	P	P069-00-3/986	Disused Room - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Top area of 3/986 Vent Shaft – Timber batons - White Matt Paint Thickness 200um / 56.1%			R567377		
43609	ACTIVE	P	P069-00-3/986	Disused Room - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Disused Vent Shaft – High level walls and ceiling in the entrance to the shaft: Thickness 500um / 1.55%			R567377		
45246	INACTIVE	P	P069-00-3/986	Disused Room - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Silver Gloss Walls				N	N



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43623	ACTIVE	P	P069-00-3/986	Disused Room - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Top area of 3/986 Vent Shaft – Cat ladders and brackets Green / Yellow Gloss Paint - Thickness 120um / 0.83 (Borderline)			R567377		
45249	ACTIVE	P	P069-00-3/986	Disused Room - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Green/Yellow Gloss Disused pipework				N	N
45247	INACTIVE	P	P069-00-3/986	Disused Room - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Green/Yellow Gloss RSJ at high level				N	N
43619	ACTIVE	P	P069-00-3/986	Disused Room - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Top area of 3/986 Vent Shaft – Decorative columns and alcoves - white/cream gloss paint: Thickness 630um / 22.3%			R567377		
14124	ACTIVE	P	P069-00-3/987	Disused Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43616	ACTIVE	P	P069-00-3/987	Disused Room - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Outer shaft cladding at high level - by entrance to CER 3/733 - White Matt Paint: Thickness 750um / 15.8%			R567377		
14125	ACTIVE	P	P069-00-4/081	Circulation Area - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23214	ACTIVE	P	P069-00-4/081/FLR-01	Floor - 1 - Circulation Area - Station Building - Knightsbridge Stn	No Access	Asbestos	Surveyed – Not Detected				Manhole access to 4/162					Yes
14126	ACTIVE	P	P069-00-4/161	LMC - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23217	INACTIVE	P	P069-00-4/161	LMC - Station Building - Knightsbridge Stn	Cable: Sheath	Asbestos	Presumed				1x 100m cable by supalux panel		1			
23216	ACTIVE	P	P069-00-4/161/CLG-01	Ceiling: Solid - 1 - LMC - Station Building - Knightsbridge Stn	Void	Asbestos	Presumed				1 x100 cable by Supalux panel Presumed cement cable duct				Yes	
23215	ACTIVE	P	P069-00-4/161/CLG-01	Ceiling: Solid - 1 - LMC - Station Building - Knightsbridge Stn		Asbestos	Surveyed – Not Detected				Supalux Panels on ceiling					
14127	ACTIVE	P	P069-00-4/162	LMC - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23218	ACTIVE	P	P069-00-4/162	LMC - Station Building - Knightsbridge Stn	Gasket :Pipework	Asbestos	Strongly Presumed				12 x Gaskets on all pumps		12			
14128	ACTIVE	P	P069-00-4/201	Passage - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14129	ACTIVE	P	P069-00-4/202	Passage - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14130	ACTIVE	P	P069-00-4/203	Service Riser - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45244	ACTIVE	P	P069-00-4/203	Service Riser - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Matt high level walls and ceiling				N	N
14131	ACTIVE	P	P069-00-4/204	Passage - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14132	ACTIVE	P	P069-00-4/205	Passage - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14133	ACTIVE	P	P069-00-4/206	Passage - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14134	ACTIVE	P	P069-00-4/236	Lobby - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14135	ACTIVE	P	P069-00-4/237	Lobby - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14136	ACTIVE	P	P069-00-4/261	Platform 1 - Eastbound Local - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23852	ACTIVE	P	P069-00-4/261	Platform 1 - Eastbound Local - Station Building - Knightsbridge Stn	Cable Duct: Other	Asbestos	Known				Eastbound Invert - 2 x Cable sleeves - platform side near head wall down hatch 4/664		2			Y
69379	ACTIVE	P	P069-00-4/261	Platform 1 - Eastbound Local - Station Building - Knightsbridge Stn	Cable: Sheath	Asbestos	Strongly Presumed				Strongly presumed asbestos braided cables within cable management system boxing at departure end of platform and within 4/712		5	R679615		
42884	INACTIVE	P	P069-00-4/261	Platform 1 - Eastbound Local - Station Building - Knightsbridge Stn	Cable: Sheath	Asbestos	Presumed				Asbestos SP 2 x 10 mm 4m cable after 4/202					
23221	ACTIVE	P	P069-00-4/261	Platform 1 - Eastbound Local - Station Building - Knightsbridge Stn	Cable: Sheath	Asbestos	Strongly Presumed				At least 6x Cable by 4/712		6			
23222	ACTIVE	P	P069-00-4/261	Platform 1 - Eastbound Local - Station Building - Knightsbridge Stn	Westing house Boxes	Asbestos	Strongly Presumed				Small Westinghouse brake box by 4/712 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1			
42786	ACTIVE	P	P069-00-4/261	Platform 1 - Eastbound Local - Station Building - Knightsbridge Stn	Westing house Boxes	Asbestos	Presumed				Small Westing House box by 4/712		1			



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23220	ACTIVE	p	P069-00-4/261	Platform 1 - Eastbound Local - Station Building - Knightsbridge Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Walls - white boarding - supalux					
23233	ACTIVE	p	P069-00-4/261	Platform 1 - Eastbound Local - Station Building - Knightsbridge Stn	Debris: Other	Asbestos	Known				Eastbound Invert - Debris on floor near platform side head wall down hatch 4/664					Y
23234	ACTIVE	p	P069-00-4/261	Platform 1 - Eastbound Local - Station Building - Knightsbridge Stn	Cable: Sheath	Asbestos	Strongly Presumed				Eastbound Invert - Cables platform side & pit side along length of Invert hatch					Y
23223	INACTIVE	p	P069-00-4/261	Platform 1 - Eastbound Local - Station Building - Knightsbridge Stn	Cable: Sheath	Asbestos	Removed				2x 10mm 4m Cables after 4/202 Cables were pulled back into the invert by Edenbeck HM00061 and removed;		2			
23224	ACTIVE	p	P069-00-4/261	Platform 1 - Eastbound Local - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Platform 1&2 - 40m² Trackside trunking, no access to sample - 40m² black gloss					
23219	ACTIVE	p	P069-00-4/261/ FLR-01	Floor - 1 - Platform 1 - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				Manholes - Access to inverts					Yes
14137	ACTIVE	p	P069-00-4/262	Platform 2 - Westbound Local - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46332	INACTIVE	p	P069-00-4/262	Platform 2 - Westbound Local - Station Building - Knightsbridge Stn	Cable: Sheath	Asbestos	Known				Asbestos Cable - Behind metal fascias panels, midway by signals box and runs within frieze panels towards direction of departure end into room					
46333	ACTIVE	p	P069-00-4/262	Platform 2 - Westbound Local - Station Building - Knightsbridge Stn	Other Electrical Boxes	Asbestos	Presumed				Materials within signal box to wall midway					
42787	ACTIVE	p	P069-00-4/262	Platform 2 - Westbound Local - Station Building - Knightsbridge Stn	Westing house Boxes	Asbestos	Not Found during Inspection				Small Westing House box (Location by Relay Room?) Westinghouse box not found in 2020 re-inspection. Possibly removed.					
23851	ACTIVE	p	P069-00-4/262	Platform 2 - Westbound Local - Station Building - Knightsbridge Stn	Cable: Sheath	Asbestos	Known				Braided cables - From trackside into invert at departure end wall					Y
23230	ACTIVE	p	P069-00-4/262	Platform 2 - Westbound Local - Station Building - Knightsbridge Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Westbound Invert - 6x Cable sleeves near 4/208 & 2x Cable sleeves platform side ceiling level down hatch by 4/281		6			Y
46376	ACTIVE	p	P069-00-4/262	Platform 2 - Westbound Local - Station Building - Knightsbridge Stn	Cable: Sheath	Asbestos	Sampled – Not Detected				Cable wrapping to thick cable to entrance to vent shaft trackside	1		R687276	N	N
46855	ACTIVE	p	P069-00-4/262	Platform 2 - Westbound Local - Station Building - Knightsbridge Stn	Cable: Sheath	Asbestos	Known				within cable management system boxing at arrivals end wall - and pass in 4/711 and platform invert - asbestos braided cables					



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44415	INACTIVE	p	P069-00-4/262	Platform 2 - Westbound Local - Station Building - Knightsbridge Stn	Cement Troughing	Asbestos	Removed				Troughing, <0.1m, to wall platform side in Platform 2 Invert Piccadilly Line Westbound, coming from room 4/791 and platform 1 invert.			R622676		Y
46375	ACTIVE	p	P069-00-4/262	Platform 2 - Westbound Local - Station Building - Knightsbridge Stn	Cable: Sheath	Asbestos	Sampled – Not Detected				Cable wrapping to thin cable to entrance to vent shaft trackside	1		R687276	N	N
46377	ACTIVE	p	P069-00-4/262	Platform 2 - Westbound Local - Station Building - Knightsbridge Stn	Debris: Cement	Asbestos	Sampled – Not Detected				Cement debris loose between trackwall and panels Sampled twice		10	R686301	N	N
44414	INACTIVE	p	P069-00-4/262	Platform 2 - Westbound Local - Station Building - Knightsbridge Stn	Cement Troughing	Asbestos	Removed				Troughing and debris, >0.1m, to wall platform side (PVC cables inside) NB troughing going into room 4/761 and in to platform invert Westbound platform 2.			R622676		Y
23226	ACTIVE	p	P069-00-4/262	Platform 2 - Westbound Local - Station Building - Knightsbridge Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				6x 0.03m2 Supalux panels - under over bridge front side					
23227	ACTIVE	p	P069-00-4/262	Platform 2 - Westbound Local - Station Building - Knightsbridge Stn	Other Boarding	Asbestos	Surveyed – Not Detected				3x 2m2 Plasterboard - Under over bridge beneath 10m White boarding above tiles		3			
23231	ACTIVE	p	P069-00-4/262	Platform 2 - Westbound Local - Station Building - Knightsbridge Stn	Boarding: Cement	Asbestos	Known				Westbound Invert - 0.5m² Cement panel - halfway, 70m up near middle ladder		1			Y
23611	ACTIVE	p	P069-00-4/262	Platform 2 - Westbound Local - Station Building - Knightsbridge Stn	Cable: Sheath	Asbestos	Known				Asbestos - K - Behind metal fascias panels, midway by signals box and runs within frieze panels towards direction of departure end into room		4			
23229	ACTIVE	p	P069-00-4/262	Platform 2 - Westbound Local - Station Building - Knightsbridge Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westbound Invert - 2x Westlinghouse box - towards 4/208		2			Y
23228	INACTIVE	p	P069-00-4/262	Platform 2 - Westbound Local - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Removed				On stretcher cupboard - 2m² grey gloss - near 4/381. Thickness : 0.04mm Analysis : 2.64%					
23225	ACTIVE	p	P069-00-4/262	Platform 2 - Westbound Local - Station Building - Knightsbridge Stn	Lead/Leading	Lead Paint/Lead	Known				Platform 1&2 - 40m² Trackside trunking, no access to sample - 40m² black gloss					
23232	ACTIVE	p	P069-00-4/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Knightsbridge Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Eastbound Invert - 2m up - fibreglass lagging & supalux					
23850	ACTIVE	p	P069-00-4/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Knightsbridge Stn	Void	Asbestos	Surveyed – Not Detected				Manhole access to invert					Yes
14138	ACTIVE	p	P069-00-4/381	Store - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14139	ACTIVE	P	P069-00-4/406	Store - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23238	ACTIVE	P	P069-00-4/406/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Knightsbridge Stn	Void	Asbestos	No Access: Presumed				Above Supalux boarding				Yes	
23237	ACTIVE	P	P069-00-4/406/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Knightsbridge Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				3x Supalux boarding					
44096	ACTIVE	P	P069-00-4/406/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Knightsbridge Stn	Bitumen	Asbestos	Sampled – Not Detected				Bitumen cable ducts 6 no., to upper metal check plate within concrete slabs			R602501	N	N
23236	ACTIVE	P	P069-00-4/406/FLR-01	Floor - 1 - Store - Station Building - Knightsbridge Stn	Void	Asbestos	No Access: Presumed				Beneath Supalux and Inspection cover					Yes
23235	ACTIVE	P	P069-00-4/406/FLR-01	Floor - 1 - Store - Station Building - Knightsbridge Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boarding by wall 2&4					
46378	ACTIVE	P	P069-00-4/406/FLR-01	Floor - 1 - Store - Station Building - Knightsbridge Stn	Cable Ducts: Cement	Asbestos	Known				Cable duct concealed on concrete cable slab to floor by door to Platform 1; Duct confirmed during works by Delatim who broke it out and raised it as 55613683 attached - Report R703551 attached Edenbeck to carryout encapsulation under HM00760 in November 2021			R685001	N	N
14140	ACTIVE	P	P069-00-4/662	Switch Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14141	ACTIVE	P	P069-00-4/664	Switch Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
14142	ACTIVE	P	P069-00-4/666	Relay Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
46379	INACTIVE	P	P069-00-4/666	Relay Room - Station Building - Knightsbridge Stn	Cable: Sheath	Asbestos	Known				5no. braided cables in cable runs to walls 1 and 3 and floor slab		5	R685001	N	N
53745	ACTIVE	P	P069-00-4/666	Relay Room - Station Building - Knightsbridge Stn	Other Electrical Boxes	Asbestos	Presumed				Electrical box 600 v board at back 2x (on wall 1&3)					
53746	ACTIVE	P	P069-00-4/666	Relay Room - Station Building - Knightsbridge Stn	Other Electrical Boxes	Asbestos	Presumed				transformer box to wall1 - (door entry from WB platform)					
23239	ACTIVE	P	P069-00-4/666/FLR-01	Floor - 1 - Relay Room - Station Building - Knightsbridge Stn		Asbestos	Surveyed – Not Detected				2 x supalux boarding					



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
53747	ACTIVE	P	P069-00-4/666/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Knightsbridge Stn	Other Boarding	Asbestos	Presumed				3 x board on rack to wall 1					
23240	ACTIVE	P	P069-00-4/666/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Knightsbridge Stn	Cable: Sheath	Asbestos	Known				4x Cables - 2 cables going into electrical 600v box (Note this 2 way entry into room - entry was from WB platform		4			
23241	ACTIVE	P	P069-00-4/666/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Knightsbridge Stn	Cable: Sheath	Asbestos	Known				3 x asbestos total - 2x Cables going into 600velectrical box (Note this 2 way entry into room - entry was from WB platform)		3			
53748	ACTIVE	P	P069-00-4/666/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Knightsbridge Stn	Other Boarding	Asbestos	Presumed				Composite boarding 2 x backing plate to wall large size presumed asbestos 4 x base plates new board appear new					
14143	ACTIVE	P	P069-00-4/668	Switch Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23242	ACTIVE	P	P069-00-4/668/FLR-01	Floor - 1 - Switch Room - Station Building - Knightsbridge Stn	Void	Asbestos	No Access: Presumed				Beneath manholes					Yes
24003	ACTIVE	P	P069-00-4/668/WAL-003 80876192	Wall: Internal - 3 - Switch Room - Station Building - Knightsbridge Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				10 switch boxes (9x Blue, 1x Grey) and busbar		10			
14144	ACTIVE	P	P069-00-4/711	Relay Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23246	INACTIVE	P	P069-00-4/711	Relay Room - Station Building - Knightsbridge Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				7x PCB's		7			
23243	ACTIVE	P	P069-00-4/711/FLR-01	Floor - 1 - Relay Room - Station Building - Knightsbridge Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				2 x Supalux Boards		2			
23244	ACTIVE	P	P069-00-4/711/FLR-01	Floor - 1 - Relay Room - Station Building - Knightsbridge Stn	Void	Asbestos	No Access: Presumed				Beneath 2no Supalux Boards					Yes
23245	ACTIVE	P	P069-00-4/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Knightsbridge Stn	Cable: Sheath	Asbestos	Strongly Presumed				Approx 11x Cables		11			
14145	ACTIVE	P	P069-00-4/712	Relay Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23250	INACTIVE	P	P069-00-4/712 80143276	Relay Room - Station Building - Knightsbridge Stn Room Assets	PCBs	Polychlorinated biphenyl	Strongly Presumed				6 x PCB's		7			
23247	ACTIVE	P	P069-00-4/712/FLR-01	Floor - 1 - Relay Room - Station Building - Knightsbridge Stn		Asbestos	Surveyed – Not Detected				2 x Supalux Boards					
23248	ACTIVE	P	P069-00-4/712/FLR-01	Floor - 1 - Relay Room - Station Building - Knightsbridge Stn	Void	Asbestos	No Access: Presumed				Beneath 2no Supalux Boards					Yes



Hazardous Material Asset Register - Summary



P069-00 - Station Building - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
23249	ACTIVE	P	P069-00-4/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Knightsbridge Stn	Cable: Sheath	Asbestos	Strongly Presumed				Approx 10 or more cables		10			
14146	ACTIVE	P	P069-00-4/761	Equipment Room - Station Building - Knightsbridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23255	INACTIVE	P	P069-00-4/761	Equipment Room - Station Building - Knightsbridge Stn	Isolator Switches	Asbestos	No Access: Presumed				1 x Grey fuse switch		1			
44095	ACTIVE	P	P069-00-4/761	Equipment Room - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Grout caulking 1m to metal tunnel rings			R602501	N	N
44094	ACTIVE	P	P069-00-4/761	Equipment Room - Station Building - Knightsbridge Stn		Asbestos	Sampled – Not Detected				Rope, throughout within flanges to metal tunnel rings			R602501	N	N
23254	ACTIVE	P	P069-00-4/761/CLG-01	Ceiling: Solid - 1 - Equipment Room - Station Building - Knightsbridge Stn	Caulking	Asbestos	No Access: Presumed				Tunnel Ring caulking as been sampled and was non-asbestos, however if disturbing rings more intrusive sampling may be required					
23253	ACTIVE	P	P069-00-4/761/FLR-01	Floor - 1 - Equipment Room - Station Building - Knightsbridge Stn	Cement Troughing	Asbestos	No Access: Presumed				5m cable troughing & lid on floor - (Lids removed) No access into equipment room during 2020 re-inspection. Sealed shut.					
23853	ACTIVE	P	P069-00-4/761/FLR-01	Floor - 1 - Equipment Room - Station Building - Knightsbridge Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boards					
23251	ACTIVE	P	P069-00-4/761/FLR-01	Floor - 1 - Equipment Room - Station Building - Knightsbridge Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding					
23252	ACTIVE	P	P069-00-4/761/WAL-002	Wall: Internal - 2 - Equipment Room - Station Building - Knightsbridge Stn		Asbestos	Surveyed – Not Detected				White boarding - Supalux					
43494	ACTIVE	P	P069-00/EN	Entrances - Knightsbridge Stn	Bitumen	Asbestos	No Access: Presumed				Bitumen/ asphalt weather proof covering on concrete slab - To roof of canopy to Entrance D No access to high level during 2020 re-inspection.			R562251		

P083-00 - Station Building - North Ealing Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14148	ACTIVE	P	P083-00-1/001	Booking Hall - Station Building - North Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14149	ACTIVE	P	P083-00-1/011	Ticket Office - Station Building - North Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P083-00 - Station Building - North Ealing Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24483	ACTIVE	P	P083-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - North Ealing Stn		Asbestos	Surveyed – Not Detected				Supalux					
24484	ACTIVE	P	P083-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - North Ealing Stn	Void	Asbestos	Surveyed – Not Detected				Plaster, solid above false ceiling				Yes	
25281	ACTIVE	P	P083-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - North Ealing Stn	Void	Asbestos	Surveyed – Not Detected				Cable trunking, conduit, concrete, PVC cables, rock wool beneath computer flooring					Yes
14150	ACTIVE	P	P083-00-1/021	POM - Station Building - North Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24485	ACTIVE	P	P083-00-1/021/FLR-01	Floor - 1 - POM - Station Building - North Ealing Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, superlux panel, rock wool, PVC cables, cable trunking beneath computer flooring					Yes
14151	ACTIVE	P	P083-00-1/031	Mess Room - Station Building - North Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24545	ACTIVE	P	P083-00-1/031	Mess Room - Station Building - North Ealing Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LTB heater - Foam		1			
24543	ACTIVE	P	P083-00-1/031/WAL-001	Wall: Internal - 1 - Mess Room - Station Building - North Ealing Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
24544	ACTIVE	P	P083-00-1/031/WAL-004	Wall: Internal - 4 - Mess Room - Station Building - North Ealing Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
14152	ACTIVE	P	P083-00-1/036	Toilet: Unisex - Station Building - North Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24551	ACTIVE	P	P083-00-1/036/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - North Ealing Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
24550	ACTIVE	P	P083-00-1/036/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - North Ealing Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
24546	ACTIVE	P	P083-00-1/036/WAL-001	Wall: Internal - 1 - Toilet - Station Building - North Ealing Stn		Asbestos	Surveyed – Not Detected				Plasterboard - no access					
24547	ACTIVE	P	P083-00-1/036/WAL-004	Wall: Internal - 4 - Toilet - Station Building - North Ealing Stn		Asbestos	Surveyed – Not Detected				Plasterboard - no access					
24548	ACTIVE	P	P083-00-1/036/WAL-005	Wall: Internal - 5 - Toilet - Station Building - North Ealing Stn		Asbestos	Surveyed – Not Detected				Plasterboard - no access					



Hazardous Material Asset Register - Summary



P083-00 - Station Building - North Ealing Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24549	ACTIVE	P	P083-00-1/036/WAL-006	Wall: Internal - 6 - Toilet - Station Building - North Ealing Stn		Asbestos	Surveyed – Not Detected				Plasterboard - no access					
14153	ACTIVE	P	P083-00-1/061	Car Park - Station Building - North Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14154	ACTIVE	P	P083-00-1/081	Lobby - Station Building - North Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24555	ACTIVE	P	P083-00-1/081	Lobby - Station Building - North Ealing Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Walls - Plasterboard					
24553	ACTIVE	P	P083-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - North Ealing Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard & boarding (plaster) above false ceiling				Yes	
24552	ACTIVE	P	P083-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - North Ealing Stn		Asbestos	Surveyed – Not Detected				Supalux					
24554	ACTIVE	P	P083-00-1/081/FLR-01	Floor - 1 - Lobby - Station Building - North Ealing Stn	Void	Asbestos	Surveyed – Not Detected				Floor void - Concrete, rock wool, wood, PVC cables, cable trunking beneath computer flooring					Yes
14155	ACTIVE	P	P083-00-1/082	Lobby - Station Building - North Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24556	ACTIVE	P	P083-00-1/082	Lobby - Station Building - North Ealing Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Walls - Plasterboard					
24557	ACTIVE	P	P083-00-1/082/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - North Ealing Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
24307	ACTIVE	P	P083-00-1/082/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - North Ealing Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
14156	ACTIVE	P	P083-00-1/083	Lobby - Station Building - North Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24559	ACTIVE	P	P083-00-1/083/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - North Ealing Stn	Void	Asbestos	Surveyed – Not Detected				Wood above plaster				Yes	
24558	ACTIVE	P	P083-00-1/083/WAL-002	Wall: Internal - 2 - Lobby - Station Building - North Ealing Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
14157	ACTIVE	P	P083-00-1/201	Passage - Station Building - North Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P083-00 - Station Building - North Ealing Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25290	ACTIVE	P	P083-00-1/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - North Ealing Stn	Void	Asbestos	No Access: Presumed				Above Canopy - wooden slats				Yes	
14158	ACTIVE	P	P083-00-1/331	Mess Room - Station Building - North Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24561	ACTIVE	P	P083-00-1/331	Mess Room - Station Building - North Ealing Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard Partition walls					
24563	ACTIVE	P	P083-00-1/331	Mess Room - Station Building - North Ealing Stn		Asbestos	Surveyed – Not Detected				Supalux boarding on door					
24562	ACTIVE	P	P083-00-1/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - North Ealing Stn	Void	Asbestos	Surveyed – Not Detected				Wood above false ceiling				Yes	
24560	ACTIVE	P	P083-00-1/331/FLR-01	Floor - 1 - Mess Room - Station Building - North Ealing Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl on solid					
14159	ACTIVE	P	P083-00-1/411	Store - Station Building - North Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24565	ACTIVE	P	P083-00-1/411/CLG-01	Ceiling: Solid - 1 - Store - Station Building - North Ealing Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
24566	ACTIVE	P	P083-00-1/411/CLG-01	Ceiling: Solid - 1 - Store - Station Building - North Ealing Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
24564	ACTIVE	P	P083-00-1/411/WAL-001	Wall: Internal - 1 - Store - Station Building - North Ealing Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
25291	ACTIVE	P	P083-00-1/411/WAL-002	Wall: Internal - 2 - Store - Station Building - North Ealing Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
14160	ACTIVE	P	P083-00-1/426	Toilet: Male - Station Building - North Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14161	ACTIVE	P	P083-00-1/427	Toilet: Female - Station Building - North Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24568	ACTIVE	P	P083-00-1/427	Toilet: Female - Station Building - North Ealing Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard Partition					
24569	ACTIVE	P	P083-00-1/427/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - North Ealing Stn	Void	Asbestos	Surveyed – Not Detected				Wood above false ceiling				Yes	
24567	ACTIVE	P	P083-00-1/427/FLR-01	Floor - 1 - Toilet - Station Building - North Ealing Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino floor					



Hazardous Material Asset Register - Summary



P083-00 - Station Building - North Ealing Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14162	ACTIVE	P	P083-00-1/601	Stairs: Linear - Station Building - North Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25292	ACTIVE	P	P083-00-1/601/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - North Ealing Stn	Void	Asbestos	No Access: Presumed				Above wooden slats				Yes	
14163	ACTIVE	P	P083-00-1/602	Stairs: Linear - Station Building - North Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24570	ACTIVE	P	P083-00-1/602/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - North Ealing Stn	Void	Asbestos	No Access: Presumed				Above Metal cladding				Yes	
24571	ACTIVE	P	P083-00-1/636/CLG-01	Ceiling: Solid - 1 - Overbridge - Station Building - North Ealing Stn	Void	Asbestos	No Access: Presumed				Above Metal cladding				Yes	
24626	ACTIVE	P	P083-00-1/636/FLR-01	Floor - 1 - Overbridge - Station Building - North Ealing Stn	Void	Asbestos	No Access: Presumed				Beneath Metal floor					Yes
14164	ACTIVE	P	P083-00-1/661	Switch Room - Station Building - North Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24627	ACTIVE	P	P083-00-1/661/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - North Ealing Stn	No Access	Asbestos	No Access: Presumed				Above false ceiling				Yes	
24631	ACTIVE	P	P083-00-1/661/FLR-01	Floor - 1 - Switch Room - Station Building - North Ealing Stn	Cable Duct: Other	Asbestos	Strongly Presumed				3 x cable sleeves by wall 1 (corner wall 4) - filled in		3			
24630	ACTIVE	P	P083-00-1/661/FLR-01	Floor - 1 - Switch Room - Station Building - North Ealing Stn		Asbestos	Sampled – Not Detected				2 x cable sleeves on floor by wall 1 - 1 filled in		2			
25830	ACTIVE	P	P083-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - North Ealing Stn	Other Electrical Boxes	Asbestos	Presumed				3 x Transformer Boxes Asbestos Components – Presumed within		3		N	N
24629	ACTIVE	P	P083-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - North Ealing Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 100 amp Switch Box No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
24628	ACTIVE	P	P083-00-1/661/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - North Ealing Stn	Isolator Switches	Asbestos	Strongly Presumed				4 x Switch Boxes wall No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score material within.		5			
14165	ACTIVE	P	P083-00-1/746	SCR - Station Building - North Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P083-00 - Station Building - North Ealing Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24632	ACTIVE	P	P083-00-1/746/CLG-01	Ceiling: Solid - 1 - SCR - Station Building - North Ealing Stn	Void	Asbestos	Surveyed – Not Detected				Wood above false ceiling				Yes	
14166	ACTIVE	P	P083-00-2/261	Platform 1 - Westbound Main - Station Building - North Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24634	ACTIVE	P	P083-00-2/261	Platform 1 - Westbound Main - Station Building - North Ealing Stn	Cellactite Sheeting	Asbestos	Surveyed – Not Detected				Ceiling - Corrugated metal					
69218	ACTIVE	P	P083-00-2/261	Platform 1 - Westbound Main - Station Building - North Ealing Stn	Glazing Rope	Asbestos	Removed				Known asbestos rope to platform glazing panels removed by Licensed Asbestos Removal Contractor Pectel in 2007					
24633	ACTIVE	P	P083-00-2/261/FLR-01	Floor - 1 - Platform 1 - Station Building - North Ealing Stn	Void	Asbestos	Surveyed – Not Detected				Beneath Inspection covers and Manhole covers Cable pits and manhole covers were inspected by 4-Rail Services and HMT on 03/12/2023. 4-Rail Services ID report R740926. All ducts were non-asbestos.					Yes
14167	ACTIVE	P	P083-00-2/262	Platform 2 - Eastbound Main - Station Building - North Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
69219	ACTIVE	P	P083-00-2/262	Platform 2 - Eastbound Main - Station Building - North Ealing Stn	Glazing Rope	Asbestos	Surveyed – Not Detected				No suspect asbestos rope to platform glazing panels					
24635	ACTIVE	P	P083-00-2/262/FLR-01	Floor - 1 - Platform 2 - Station Building - North Ealing Stn	Void	Asbestos	Surveyed – Not Detected				Beneath Inspection covers and Manhole covers Cable pits and manhole covers were inspected by 4-Rail Services and HMT on 03/12/2023. 4-Rail Services ID report R740926. All ducts were non-asbestos.					Yes
14168	ACTIVE	P	P083-00-2/436	Waiting Room - Station Building - North Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24636	ACTIVE	P	P083-00-2/436/CLG-01	Ceiling: Solid - 1 - Waiting Room - Station Building - North Ealing Stn	Void	Asbestos	No Access: Presumed				Above wooden slats				Yes	
14169	ACTIVE	P	P083-00-2/761	Equipment Room - Station Building - North Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24309	ACTIVE	P	P083-00-2/761/CLG-01	Ceiling: Solid - 1 - Equipment Room - Station Building - North Ealing Stn	Void	Asbestos	No Access: Presumed				Above wooden ceiling				Yes	
24637	ACTIVE	P	P083-00-2/761/FLR-01	Floor - 1 - Equipment Room - Station Building - North Ealing Stn	Void	Asbestos	No Access: Presumed				Beneath wooden floor					Yes



Hazardous Material Asset Register - Summary



P085-00 - Station Building - Park Royal Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14172	ACTIVE	P	P085-00-1/001	Booking Hall - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24639	INACTIVE	P	P085-00-1/001	Booking Hall - Station Building - Park Royal Stn	Lead/Leading	Lead Paint/Lead	Removed				First Aid Cabinet - Green gloss - 2m². Thickness : 0.16mm Analysis : 14% My have been removed as part of SMEP works - not found upon HMU re inspection					
24638	ACTIVE	P	P085-00-1/001	Booking Hall - Station Building - Park Royal Stn	Lead/Leading	Lead Paint/Lead	Known				Columns - All columns 9m Long - Blue Emulsion. Thickness : 0.12mm Analysis : 1.7% This may have been painted over or removed as part of SMEP works - noted HMU re inspection 28/10/14					
14173	ACTIVE	P	P085-00-1/011	Ticket Office - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24641	ACTIVE	P	P085-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Park Royal Stn		Asbestos	Surveyed – Not Detected				Supalux tiles					
24642	ACTIVE	P	P085-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Park Royal Stn	Void	Asbestos	Surveyed – Not Detected				Concrete & plaster above false ceiling				Yes	
24640	ACTIVE	P	P085-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Park Royal Stn	Void	Asbestos	Surveyed – Not Detected				Concrete & fibreglass lagging beneath computer tiles					Yes
14174	ACTIVE	P	P085-00-1/021	POM - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24643	ACTIVE	P	P085-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Park Royal Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
14175	ACTIVE	P	P085-00-1/031	Mess Room - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25375	ACTIVE	P	P085-00-1/031/WDW-01	Window - 1 - Mess Room - Station Building - Park Royal Stn	Lead/Leading	Lead Paint/Lead	Known				Window frames - White gloss - 2m². Thickness : 0.05mm Analysis : 2.1%					
14176	ACTIVE	P	P085-00-1/036	Toilet: Unisex - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14177	ACTIVE	P	P085-00-1/071	Circulation Area - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45409	ACTIVE	P	P085-00-1/071	Circulation Area - Station Building - Park Royal Stn	Lead/Leading	Lead Paint/Lead	Known				Columns - All columns 9m Long - Blue Emulsion. Thickness : 0.12mm Analysis : 1.7% This may have been painted over or removed as part of SMEP works - noted HMU re inspection 28/10/14				N	N



Hazardous Material Asset Register - Summary



P085-00 - Station Building - Park Royal Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
45410	INACTIVE	P	P085-00-1/071	Circulation Area - Station Building - Park Royal Stn	Lead/Leading	Lead Paint/Lead	Known				First Aid Cabinet - Green gloss - 2m²				N	N
14178	ACTIVE	P	P085-00-1/081	Lobby - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14179	ACTIVE	P	P085-00-1/082	Lobby - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24645	ACTIVE	P	P085-00-1/082/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Park Royal Stn	Void	Asbestos	Surveyed – Not Detected				Concrete & ducting above false ceiling				Yes	
24644	ACTIVE	P	P085-00-1/082/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Park Royal Stn		Asbestos	Surveyed – Not Detected				Supalux foam tiles					
14180	ACTIVE	P	P085-00-1/083	Lobby - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24647	ACTIVE	P	P085-00-1/083/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Park Royal Stn	Void	Asbestos	No Access: Presumed				Above 2 x loft hatches				Yes	
24646	ACTIVE	P	P085-00-1/083/FLR-01	Floor - 1 - Lobby - Station Building - Park Royal Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Grey vinyl					
14181	ACTIVE	P	P085-00-1/084	Lobby - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24649	ACTIVE	P	P085-00-1/084	Lobby - Station Building - Park Royal Stn	Lead/Leading	Lead Paint/Lead	Known				2 x pipes 4m long - cream gloss. Thickness : 0.20mm Analysis : 3.1% * May have been insulated with silver cladding. Room originally 1/411 - but converted to Lobby and SID changed to 1/084					
14182	ACTIVE	P	P085-00-1/201	Passage - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14183	ACTIVE	P	P085-00-1/281	Station Supervisor Office - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24648	ACTIVE	P	P085-00-1/281/FLR-01	Floor - 1 - Station Supervisor Office - Station Building - Park Royal Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				New vinyl floor tiles					
14184	ACTIVE	P	P085-00-1/311	Office - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25376	ACTIVE	P	P085-00-1/311/WDW-01	Window - 1 - Office - Station Building - Park Royal Stn	Lead/Leading	Lead Paint/Lead	Known				Window frames - White gloss - 2m². Thickness : 0.05mm Analysis : 2.1%.					



Hazardous Material Asset Register - Summary



P085-00 - Station Building - Park Royal Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14185	ACTIVE	P	P085-00-1/406	Store - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14186	ACTIVE	P	P085-00-1/411	Toilet - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14187	ACTIVE	P	P085-00-1/416	Toilet: Female - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14188	ACTIVE	P	P085-00-1/417	Toilet: Unisex - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14189	ACTIVE	P	P085-00-1/418	Toilet: Male - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14190	ACTIVE	P	P085-00-1/451	Tenancy - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24650	ACTIVE	P	P085-00-1/451/FLR-01	Floor - 1 - Tenancy - Station Building - Park Royal Stn	Void	Asbestos	No Access: Presumed				Beneath floor boards - Managed by TFL Commercial Properties					Yes
14191	ACTIVE	P	P085-00-1/452	CER - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24652	INACTIVE	P	P085-00-1/452/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Park Royal Stn	Void	Asbestos	No Access: Presumed				Above false ceiling - Removed during conversion into CER				Yes	
24651	ACTIVE	P	P085-00-1/452/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Park Royal Stn		Asbestos	Surveyed – Not Detected				Supalux foam					
14192	ACTIVE	P	P085-00-1/453	Tenancy - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24719	ACTIVE	P	P085-00-1/453	Tenancy - Station Building - Park Royal Stn	Void	Asbestos	Surveyed – Not Detected				Tenancy Office Area Floor - Concrete beneath carpet					Yes
24722	ACTIVE	P	P085-00-1/453	Tenancy - Station Building - Park Royal Stn	Other Electrical Boxes	Asbestos	No Access: Presumed				Tenancy Main Area - Wall 3 Electrical Box *Area has been re vamped - noted upon visual inspection Area managed by TFL Commercial Property		1			
24720	ACTIVE	P	P085-00-1/453	Tenancy - Station Building - Park Royal Stn	Void	Asbestos	No Access: Presumed				Tenancy Office Area - No access above hatch on ceiling Area managed by TFL Commercial Properties					



Hazardous Material Asset Register - Summary



P085-00 - Station Building - Park Royal Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24723	ACTIVE	P	P085-00-1/453	Tenancy - Station Building - Park Royal Stn	Cable: Sheath	Asbestos	No Access: Presumed				6 x cables - coming from electrical box * Area has been re vamped - noted upon HMU visual inspection Tenancy Managed by TFL Commercial Property		6			
24721	ACTIVE	P	P085-00-1/453	Tenancy - Station Building - Park Royal Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Tenancy Office Area - Window, door - Black gloss - 8m². Not sampled - no access *Area has been re vamped - noted upon visual inspection					
24718	ACTIVE	P	P085-00-1/453	Tenancy - Station Building - Park Royal Stn	Lead/Leading	Lead Paint/Lead	Known				Tenancy Toilet - Window Frames - White gloss - 1m². Thickness : 0.05mm Analysis : 2.1% * Over painted in green -noted during HMU visual inspection					
24716	ACTIVE	P	P085-00-1/453/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Park Royal Stn	Void	Asbestos	No Access: Presumed				Above wooden ceiling at entrance Area managed by TFL Commercial Property				Yes	
24717	ACTIVE	P	P085-00-1/453/FLR-01	Floor - 1 - Tenancy - Station Building - Park Royal Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Tenancy Toilet Floor - Lino					
24715	INACTIVE	P	P085-00-1/453/FLR-01	Floor - 1 - Tenancy - Station Building - Park Royal Stn	Void	Asbestos	No Access: Presumed				Concrete noted - Beneath carpet tiles					Yes
14193	ACTIVE	P	P085-00-1/551	Yard - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24724	ACTIVE	P	P085-00-1/551	Yard - Station Building - Park Royal Stn	Cement Cowlings/ Flues	Asbestos	Known				Cement flue cap - roof above 1/418 Access via CAT ladder to roof from the yard near SSO		1			
14194	ACTIVE	P	P085-00-1/576	Stairs: Linear - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14195	ACTIVE	P	P085-00-1/601	Stairs: Linear - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24725	ACTIVE	P	P085-00-1/601	Stairs: Linear - Station Building - Park Royal Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Outside - Grey gloss 10m² - not sampled					
14196	ACTIVE	P	P085-00-1/602	Stairs: Linear - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24737	ACTIVE	P	P085-00-1/602	Stairs: Linear - Station Building - Park Royal Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Outside - Grey gloss 10m² - not sampled					
14197	ACTIVE	P	P085-00-1/663	Switch Room - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24727	ACTIVE	P	P085-00-1/663/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Park Royal Stn	Other Electrical Boxes	Asbestos	Presumed				Electrical Equipment - P - Asbestos components withihn		1			



Hazardous Material Asset Register - Summary



P085-00 - Station Building - Park Royal Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24728	ACTIVE	P	P085-00-1/663/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Park Royal Stn	Other Electrical Boxes	Asbestos	Presumed				3 x Transformer Boxes - P - Asbestos Components within		3			
24726	ACTIVE	P	P085-00-1/663/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Park Royal Stn	Isolator Switches	Asbestos	Strongly Presumed				1x Switch Box 30amp - SP Asbestos components within		1			
24729	ACTIVE	P	P085-00-1/663/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Park Royal Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Boxes - P - Asbestos components within		1			
24730	ACTIVE	P	P085-00-1/663/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Park Royal Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1 x Junction Box Insulation within - SP - Asbestos components within		1			
14198	ACTIVE	P	P085-00-1/746	SCR - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24731	ACTIVE	P	P085-00-1/746/WDW-01	Window - 1 - SCR - Station Building - Park Royal Stn	Lead/Leading	Lead Paint/Lead	Known				Window frames - White gloss - 2m². Thickness : 0.05mm Analysis : 2.1%					
14199	ACTIVE	P	P085-00-1/951	Disused Room - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24732	ACTIVE	P	P085-00-1/951/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Park Royal Stn	Void	Asbestos	Surveyed – Not Detected				Laminated plywood above false ceiling				Yes	
25383	ACTIVE	P	P085-00-1/951/FLR-01	Floor - 1 - Disused Room - Station Building - Park Royal Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
14200	ACTIVE	P	P085-00-2/261	Platform 1 - Westbound Main - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24734	ACTIVE	P	P085-00-2/261	Platform 1 - Westbound Main - Station Building - Park Royal Stn	Cement Cowlings/ Flues	Asbestos	Presumed				1x 0.07m² Cement Flue behind border fence between boundaries - may move within boundaries Not found at last re-inspection Not able to locate as limited info plus nothing present as per location so either removed or present in different location		1			
24735	ACTIVE	P	P085-00-2/261	Platform 1 - Westbound Main - Station Building - Park Royal Stn	Other Boarding	Asbestos	Not Found during Inspection				0.02m² Board located between the two waiting rooms Not able to locate as limited info plus nothing present as per location so either removed or present in different location . also only one waiting room on each platforms not two.		1			



Hazardous Material Asset Register - Summary



P085-00 - Station Building - Park Royal Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25384	ACTIVE	P	P085-00-2/261	Platform 1 - Westbound Main - Station Building - Park Royal Stn	Other Boarding	Asbestos	Not Found during Inspection				0.5m ² Panel cement Platform 1 embankment between border fence to private area, possible removed Keep at presumed Not able to find 2020 re-inspection however may have been removed or within dense vegetation on embankment		1			
42894	ACTIVE	P	P085-00-2/261	Platform 1 - Westbound Main - Station Building - Park Royal Stn	Lead/Leading	Lead Paint/Lead	Presumed				Grit bin at end of platform, red paint		1			
24733	ACTIVE	P	P085-00-2/261/ FLR-01 80877311	Floor - 1 - Platform 1 - Station Building - Park Royal Stn Floor	Void	Asbestos	No Access: Presumed				Beneath multiple electrical covers and drains					Yes
14201	ACTIVE	P	P085-00-2/262	Platform 2 - Eastbound Main - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24736	ACTIVE	P	P085-00-2/262	Platform 2 - Eastbound Main - Station Building - Park Royal Stn	Bitumen	Asbestos	Presumed				0.5m ² Bitumen felt Ridge At the top section of the embankment after kiosk 2/761		1			
14202	ACTIVE	P	P085-00-2/436	Waiting Room - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14203	ACTIVE	P	P085-00-2/437	Waiting Room - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14204	ACTIVE	P	P085-00-2/438	Waiting Room - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24740	ACTIVE	P	P085-00-2/438	Waiting Room - Station Building - Park Royal Stn	Bitumen	Asbestos	Surveyed – Not Detected				0.04m ² Bitumen panel		1			
24741	ACTIVE	P	P085-00-2/438	Waiting Room - Station Building - Park Royal Stn	Lead/Leading	Lead Paint/Lead	Known				Seats & lower walls - Grey gloss -10m ² . Thickness : 0.85mm Analysis : 2.1%. Possible overpaint in grey.					
24739	ACTIVE	P	P085-00-2/438/ CLG-01	Ceiling: Solid - 1 - Waiting Room - Station Building - Park Royal Stn		Asbestos	Surveyed – Not Detected				Felt on roof above wooden ceiling					
14205	ACTIVE	P	P085-00-2/439	Waiting Room - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14206	ACTIVE	P	P085-00-2/481	Disused - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24738	ACTIVE	P	P085-00-2/481	Disused - Station Building - Park Royal Stn	Debris: Other	Asbestos	Known				Asbestos Debris - Some visible on surface of Spoil. Further debris within Spoil SP					



Hazardous Material Asset Register - Summary



P085-00 - Station Building - Park Royal Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14207	ACTIVE	P	P085-00-2/661	Switch Room - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25385	ACTIVE	P	P085-00-2/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Park Royal Stn	Isolator Switches	Asbestos	Strongly Presumed				1x Switch Box 60amp - SP - Asbestos components within		1			
14208	ACTIVE	P	P085-00-2/731	CER - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14209	ACTIVE	P	P085-00-2/761	Equipment Room - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14210	ACTIVE	P	P085-00-2/762	Equipment Room - Station Building - Park Royal Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

P087-00 - Station Building - Alperton Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14211	ACTIVE	P	P087-00-1/001	Booking Hall - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24821	ACTIVE	P	P087-00-1/001	Booking Hall - Station Building - Alperton Stn		Asbestos	Surveyed – Not Detected				Supalux boarding above ticket machine					
24742	ACTIVE	P	P087-00-1/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Alperton Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
25386	ACTIVE	P	P087-00-1/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Alperton Stn	Void	Asbestos	No Access: Presumed				High level Ceiling - No Access to inspect fully.				Yes	
24311	ACTIVE	P	P087-00-1/001/FLR-01	Floor - 1 - Booking Hall - Station Building - Alperton Stn	Void	Asbestos	Surveyed – Not Detected				Ceramic Tiles					
14212	ACTIVE	P	P087-00-1/011	Ticket Office - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24823	ACTIVE	P	P087-00-1/011/CLG-01	Ceiling: Solid - 1 - Ticket Office - Station Building - Alperton Stn		Asbestos	Surveyed – Not Detected				Supalux					
24824	ACTIVE	P	P087-00-1/011/CLG-01	Ceiling: Solid - 1 - Ticket Office - Station Building - Alperton Stn	Void	Asbestos	Surveyed – Not Detected				Fibre glass lagging above false ceiling				Yes	
24822	ACTIVE	P	P087-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Alperton Stn	Void	Asbestos	No Access: Presumed				Beneath computer flooring					
24825	ACTIVE	P	P087-00-1/011/WAL-003	Wall: Internal - 3 - Ticket Office - Station Building - Alperton Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LUL heaters on walls foam insulation		1			



Hazardous Material Asset Register - Summary



P087-00 - Station Building - Alperton Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24826	ACTIVE	P	P087-00-1/011/WAL-004	Wall: Internal - 4 - Ticket Office - Station Building - Alperton Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LUL heaters on walls foam insulation		1			
14213	ACTIVE	P	P087-00-1/021	POM - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
46700	ACTIVE	P	P087-00-1/021/CLG-01	Ceiling: Solid - 1 - POM - Station Building - Alperton Stn	Void	Asbestos	No Access: Presumed				No access above False Ceiling					
46698	ACTIVE	P	P087-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Alperton Stn	Void	Asbestos	No Access: Presumed				No Access under Computer Flooring					
14214	ACTIVE	P	P087-00-1/031	Mess Room - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24827	ACTIVE	P	P087-00-1/031/FLR-01	Floor - 1 - Mess Room - Station Building - Alperton Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
14215	ACTIVE	P	P087-00-1/036	Toilet: Unisex - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14216	ACTIVE	P	P087-00-1/071	Circulation Area - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
14217	ACTIVE	P	P087-00-1/081	Lobby - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24831	ACTIVE	P	P087-00-1/081/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Alperton Stn	Void	Asbestos	Surveyed – Not Detected				Fibre glass lagging above false ceiling				Yes	
24830	ACTIVE	P	P087-00-1/081/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Alperton Stn		Asbestos	Surveyed – Not Detected				Supalux					
24828	ACTIVE	P	P087-00-1/081/FLR-01	Floor - 1 - Lobby - Station Building - Alperton Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
24829	ACTIVE	P	P087-00-1/081/FLR-01	Floor - 1 - Lobby - Station Building - Alperton Stn	Void	Asbestos	No Access: Presumed				Beneath boxing / wood					
14218	ACTIVE	P	P087-00-1/082	Lobby - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
14219	ACTIVE	P	P087-00-1/083	Lobby - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
14220	ACTIVE	P	P087-00-1/151	UMC - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24832	ACTIVE	P	P087-00-1/151	UMC - Station Building - Alperton Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Circuit breaker - Asbestos Components within		1		N	N



Hazardous Material Asset Register - Summary



P087-00 - Station Building - Alperton Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24834	ACTIVE	P	P087-00-1/151	UMC - Station Building - Alperton Stn	Other Electrical Boxes	Asbestos	Presumed				Escalator Equipment - Asbestos Components within - P				N	N
24833	ACTIVE	P	P087-00-1/151	UMC - Station Building - Alperton Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Controller Box - Asbestos Components within		1		N	N
14221	ACTIVE	P	P087-00-1/161	LMC - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24835	ACTIVE	P	P087-00-1/161/FLR-01	Floor - 1 - LMC - Station Building - Alperton Stn	Void	Asbestos	No Access: Presumed				Beneath hatch on floor					
14222	ACTIVE	P	P087-00-1/281	Station Supervisor Office - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24836	ACTIVE	P	P087-00-1/281/FLR-01	Floor - 1 - Station Supervisor Office - Station Building - Alperton Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
24316	ACTIVE	P	P087-00-1/281/WAL-004	Wall: Internal - 4 - Station Supervisor Office - Station Building - Alperton Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LUL heater - foam insulation		1			
14223	ACTIVE	P	P087-00-1/411	Store - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24837	ACTIVE	P	P087-00-1/411/FLR-01	Floor - 1 - Store - Station Building - Alperton Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
14224	ACTIVE	P	P087-00-1/426	Toilet: Female - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24839	ACTIVE	P	P087-00-1/426	Toilet: Female - Station Building - Alperton Stn	Lead/Leading	Lead Paint/Lead	Known				Entrance door - Red gloss - 2m². Thickness : 0.22mm Analysis : 17.2%				N	N
24838	ACTIVE	P	P087-00-1/426/DOR-01	Door - 1 - Toilet - Station Building - Alperton Stn	Lead/Leading	Lead Paint/Lead	Known				Lobby Door may still be present; Cubicle doors have been replaced during SMEP; Original description: All Toilet doors - Blue gloss - 12m². Thickness : 0.35mm Analysis : 9.32%				N	N
25470	ACTIVE	P	P087-00-1/426/WDW-01	Window - 1 - Toilet - Station Building - Alperton Stn	Lead/Leading	Lead Paint/Lead	Known				Window frame - Cream gloss - 0.5m². Thickness : 0.14mm Analysis : 5.26%				N	N
14225	ACTIVE	P	P087-00-1/427	Toilet: Male - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
24840	ACTIVE	P	P087-00-1/427	Toilet: Male - Station Building - Alperton Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LUL heater - foam insulation		1			



Hazardous Material Asset Register - Summary



P087-00 - Station Building - Alperton Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14228	ACTIVE	P	P087-00-1/451	Tenancy - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24842	ACTIVE	P	P087-00-1/451	Tenancy - Station Building - Alperton Stn	Other Boarding	Asbestos	Strongly Presumed				Fascia Boards to external frontage of Tenancy (within 1/001)				N	N
24841	ACTIVE	P	P087-00-1/451/FLR-01	Floor - 1 - Tenancy - Station Building - Alperton Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden floor. Floor is now tiled over					
14229	ACTIVE	P	P087-00-1/601	Stairs: Linear - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
46697	ACTIVE	P	P087-00-1/636/FLR-01	Floor - 1 - Overbridge - Station Building - Alperton Stn	Void	Asbestos	No Access: Presumed				No Access below Hatches to Floor		2			
14230	ACTIVE	P	P087-00-1/661	Switch Room - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25471	ACTIVE	P	P087-00-1/661	Switch Room - Station Building - Alperton Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Bakelite boarding above four switches					
24843	ACTIVE	P	P087-00-1/661/FLR-01	Floor - 1 - Switch Room - Station Building - Alperton Stn	Cable Duct: Other	Asbestos	Presumed				Sealed Cable Ducts by walls 1 & 2				N	N
24845	ACTIVE	P	P087-00-1/661/FLR-01	Floor - 1 - Switch Room - Station Building - Alperton Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Boxes - wall 1 Asbestos Components within - P		4		N	N
24680	ACTIVE	P	P087-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Alperton Stn	Isolator Switches	Asbestos	Strongly Presumed				Wall 1 1 x 30amp Switch Box - Asbestos Components within - SP		7		N	N
24844	ACTIVE	P	P087-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Alperton Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch boxes 1 x 300, 3 x 60, 1 x 30, 1x 400 amp Asbestos Components within - SP		6		N	N
14231	ACTIVE	P	P087-00-1/662	Switch Room - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24847	ACTIVE	P	P087-00-1/662/FLR-01	Floor - 1 - Switch Room - Station Building - Alperton Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Boxes - wall 1 Asbestos Components within - P		1		N	N
25472	ACTIVE	P	P087-00-1/662/FLR-01	Floor - 1 - Switch Room - Station Building - Alperton Stn	Void	Asbestos	No Access: Presumed				Beneath Manholes beneath rubber matting					
24846	ACTIVE	P	P087-00-1/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Alperton Stn	Isolator Switches	Asbestos	Strongly Presumed				Wall 2 3x Switch boxes 2x Blue, 1 x Grey - 2 x 100, 1x60amp Asbestos Components within - SP		3		N	N
14232	ACTIVE	P	P087-00-1/663	Disused Room - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24179	INACTIVE	P	P087-00-1/663	Disused Room - Station Building - Alperton Stn	Other Electrical Boxes	Asbestos	Removed				1 x Fuse switch - REMOVED confirmed removed by premises photo attached		1		N	N



Hazardous Material Asset Register - Summary



P087-00 - Station Building - Alperton Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14233	ACTIVE	P	P087-00-1/746	SCR - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
14234	ACTIVE	P	P087-00-1/901	Store - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
14235	ACTIVE	P	P087-00-A/261	Platform 1 - Westbound Main - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24180	ACTIVE	P	P087-00-A/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Alperton Stn	Void	Asbestos	No Access: Presumed				Beneath Manholes					
14236	ACTIVE	P	P087-00-A/262	Platform 2 - Eastbound Main - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24182	ACTIVE	P	P087-00-A/262	Platform 2 - Eastbound Main - Station Building - Alperton Stn	Cement Troughing	Asbestos	Strongly Presumed				Troughing West End				N	N
24181	ACTIVE	P	P087-00-A/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Alperton Stn	Void	Asbestos	No Access: Presumed				Beneath Manholes					
14226	ACTIVE	P	P087-00-A/436	Waiting Room - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
14227	ACTIVE	P	P087-00-A/437	Waiting Room - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
14237	ACTIVE	P	P087-00-A/576	Stairs: Linear - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
14238	ACTIVE	P	P087-00-A/601	Stairs: Linear - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
14239	ACTIVE	P	P087-00-A/602	Stairs: Linear - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
14240	ACTIVE	P	P087-00-A/731	CER - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24185	ACTIVE	P	P087-00-A/731	CER - Station Building - Alperton Stn	No Access	Asbestos	Surveyed – Not Detected				No Asbestos Evident from Photos supplied by Premises - please see attached					
14241	ACTIVE	P	P087-00-A/761	Equipment Room - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14242	ACTIVE	P	P087-00-A/981	Disused Room - Station Building - Alperton Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P089-00 - Station Building - Sudbury Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14243	ACTIVE	P	P089-00-1/001	Booking Hall - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24186	ACTIVE	P	P089-00-1/001	Booking Hall - Station Building - Sudbury Town Stn	Lead/Leading	Lead Paint/Lead	Known				Hand Rail - Blue gloss. Thickness : 0.01mm Analysis : 1.5%				N	N
14244	ACTIVE	P	P089-00-1/011	Ticket Office - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24189	ACTIVE	P	P089-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Sudbury Town Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
24190	ACTIVE	P	P089-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Sudbury Town Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				Yes	
24188	ACTIVE	P	P089-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Sudbury Town Stn	Void	Asbestos	No Access: Presumed				Beneath computer flooring					Yes
14245	ACTIVE	P	P089-00-1/021	POM - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24193	INACTIVE	P	P089-00-1/021	POM - Station Building - Sudbury Town Stn	Lead/Leading	Lead Paint/Lead	Removed				Safe - Grey gloss. Thickness : 0.04mm Analysis : 4.3% Looks like Safe has been removed.				N	N
24192	ACTIVE	P	P089-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Sudbury Town Stn	Void	Asbestos	No Access: Presumed				Beneath computer flooring					Yes
24191	ACTIVE	P	P089-00-1/021/WAL-002	Wall: Internal - 2 - POM - Station Building - Sudbury Town Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - foam insulation		1			
14246	ACTIVE	P	P089-00-1/031	Mess Room - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24194	ACTIVE	P	P089-00-1/031/WAL-003	Wall: Internal - 3 - Mess Room - Station Building - Sudbury Town Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - foam insulation		1			
14247	ACTIVE	P	P089-00-1/036	Toilet: Unisex - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14248	ACTIVE	P	P089-00-1/081	Lobby - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25176	ACTIVE	P	P089-00-1/081/FLR-01	Floor - 1 - Lobby - Station Building - Sudbury Town Stn	Void	Asbestos	No Access: Presumed				Beneath computer flooring					Yes
14249	ACTIVE	P	P089-00-1/261	Platform 1 - Westbound Main - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P089-00 - Station Building - Sudbury Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24195	ACTIVE	P	P089-00-1/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Sudbury Town Stn	Void	Asbestos	No Access: Presumed				No Access Below Inspection Covers					Yes
14250	ACTIVE	P	P089-00-1/262	Platform 2 - Eastbound Main - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24196	ACTIVE	P	P089-00-1/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Sudbury Town Stn	Void	Asbestos	No Access: Presumed				Beneath inspection covers					Yes
14251	ACTIVE	P	P089-00-1/281	CER - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14252	ACTIVE	P	P089-00-1/311	Office - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24197	ACTIVE	P	P089-00-1/311/WAL-003	Wall: Internal - 3 - Office - Station Building - Sudbury Town Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - foam insulation		1			
14253	ACTIVE	P	P089-00-1/316	Locker Room - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24199	ACTIVE	P	P089-00-1/316	Locker Room - Station Building - Sudbury Town Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LUL Heater - foam insulation		1			
25177	INACTIVE	P	P089-00-1/316/CLG-01	Ceiling: Solid - 1 - Locker Room - Station Building - Sudbury Town Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
24198	ACTIVE	P	P089-00-1/316/FLR-01	Floor - 1 - Locker Room - Station Building - Sudbury Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
14254	ACTIVE	P	P089-00-1/401	Lobby - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14255	ACTIVE	P	P089-00-1/426	Toilet: Female - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24200	ACTIVE	P	P089-00-1/426	Toilet: Female - Station Building - Sudbury Town Stn	Lead/Leading	Lead Paint/Lead	Known				Door & frame - Blue gloss. Thickness : 0.19mm Analysis : 2.4%				N	N
14256	ACTIVE	P	P089-00-1/427	Toilet: Male - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24201	ACTIVE	P	P089-00-1/427	Toilet: Male - Station Building - Sudbury Town Stn	Lead/Leading	Lead Paint/Lead	Known				Door & frame - Blue gloss. Thickness : 0.16mm Analysis : 5.2%				N	N
14257	ACTIVE	P	P089-00-1/436	Waiting Room - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P089-00 - Station Building - Sudbury Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24187	ACTIVE	P	P089-00-1/436	Waiting Room - Station Building - Sudbury Town Stn	Lead/Leading	Lead Paint/Lead	Known				Window frame - White gloss. Thickness : 0.16mm Analysis : 12.0% On 4 Rail Report as 1/001 but relates to 1/436				N	N
14258	ACTIVE	P	P089-00-1/437	Waiting Room - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14259	ACTIVE	P	P089-00-1/451	Disused Room - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24203	ACTIVE	P	P089-00-1/451/CLG-01	Ceiling: Suspended - 1 - Disused Room - Station Building - Sudbury Town Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
25178	ACTIVE	P	P089-00-1/451/CLG-01	Ceiling: Suspended - 1 - Disused Room - Station Building - Sudbury Town Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
24202	ACTIVE	P	P089-00-1/451/FLR-01	Floor - 1 - Disused Room - Station Building - Sudbury Town Stn	Void	Asbestos	Surveyed – Not Detected				Solid beneath carpet					Yes
14260	ACTIVE	P	P089-00-1/452	Toilet: Unisex - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24204	ACTIVE	P	P089-00-1/452/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Sudbury Town Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
24219	ACTIVE	P	P089-00-1/452/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Sudbury Town Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
14261	ACTIVE	P	P089-00-1/453	Disused Room - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Surveyed – Asbestos Known									
46503	ACTIVE	P	P089-00-1/453	Disused Room - Station Building - Sudbury Town Stn	Bitumen	Asbestos	Sampled – Not Detected				Bitumen Damp Proof - Walls 2 & 3 Sampled R701351 - No Asbestos Detected			R701351		
46504	ACTIVE	P	P089-00-1/453	Disused Room - Station Building - Sudbury Town Stn	Mastic	Asbestos	Sampled – Not Detected				Putty to Windows Sampled on report R701351			R701351		
46508	ACTIVE	P	P089-00-1/453	Disused Room - Station Building - Sudbury Town Stn	Lead/Leading	Lead Paint/Lead	Known				Lead Paint to Green gloss paint to upper walls – advertising panels - above roller shutters 200µm Thickness - 1.09%			R701352		
46506	ACTIVE	P	P089-00-1/453	Disused Room - Station Building - Sudbury Town Stn	Lead/Leading	Lead Paint/Lead	Known				Lead Paint to Black gloss paint applied to lower walls 150µm Thickness - 1.94%			R701352		



Hazardous Material Asset Register - Summary



P089-00 - Station Building - Sudbury Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46505	ACTIVE	P	P089-00-1/453	Disused Room - Station Building - Sudbury Town Stn	Lead/Leading	Lead Paint/Lead	Known				Lead Paint to Blue gloss paint applied to walls, doors, windows and shutter; 250µm Thickness - 1.10%			R701352		
46507	ACTIVE	P	P089-00-1/453	Disused Room - Station Building - Sudbury Town Stn	Lead/Leading	Lead Paint/Lead	Known				Lead Paint to Green gloss paint to upper walls – advertising panels 180µm Thickness - 2.34%			R701352		
24206	ACTIVE	P	P089-00-1/453/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Sudbury Town Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above wooden slats See Report R701351				Yes	
24205	ACTIVE	P	P089-00-1/453/FLR-01	Floor - 1 - Disused Room - Station Building - Sudbury Town Stn	Void	Asbestos	Surveyed – Not Detected				Beneath wooden floor - Concrete / Stone Slab See Report R701351					Yes
25179	ACTIVE	P	P089-00-1/453/WAL-001	Wall: Internal - 1 - Disused Room - Station Building - Sudbury Town Stn	Other Boarding	Asbestos	Known				Asbestos Board behind heater Wall 1 Under Bench	1	1		N	N
14262	ACTIVE	P	P089-00-1/661	Switch Room - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45251	INACTIVE	P	P089-00-1/661	Switch Room - Station Building - Sudbury Town Stn	Isolator Switches	Asbestos	Strongly Presumed				8x Fuse switches (7blue, 1grey)				N	N
24285	ACTIVE	P	P089-00-1/661	Switch Room - Station Building - Sudbury Town Stn	Cable Duct: Other	Asbestos	Presumed				Various Sealed Ducts				N	N
24207	ACTIVE	P	P089-00-1/661/FLR-01	Floor - 1 - Switch Room - Station Building - Sudbury Town Stn	Void	Asbestos	No Access: Presumed				Beneath hatch on floor					Yes
24281	ACTIVE	P	P089-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Sudbury Town Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 30 Fuse switch No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score material within.		1		N	N
24284	ACTIVE	P	P089-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Sudbury Town Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Boxes x 3 Asbestos Components – Presumed within		3		N	N
24282	ACTIVE	P	P089-00-1/661/WAL-005	Wall: Internal - 5 - Switch Room - Station Building - Sudbury Town Stn	Isolator Switches	Asbestos	Strongly Presumed				Fuse switches - 6 x 60amps, 1x100amps Missing presumed 1x CFS to wall No electrician on site during 2024 re-inspection to open boxes for inspection - therefore cannot score material within.		7		N	N
24283	ACTIVE	P	P089-00-1/661/WAL-006	Wall: Internal - 6 - Switch Room - Station Building - Sudbury Town Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Boxes x 1 Asbestos Components – Presumed within		1		N	N
14263	ACTIVE	P	P089-00-1/662	CER - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P089-00 - Station Building - Sudbury Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14264	ACTIVE	P	P089-00-1/663	Disused Room - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24286	INACTIVE	P	P089-00-1/663/DOR-01	Door - 1 - Disused Room - Station Building - Sudbury Town Stn	Lead/Leading	Lead Paint/Lead	Removed				Door - 2m ² - Red gloss. Thickness : 0.19mm Analysis : 5.3% Door has been replaced				N	N
14265	ACTIVE	P	P089-00-1/746	SCR - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24288	ACTIVE	P	P089-00-1/901/CLG-01	Ceiling: Solid - 1 - GLAP - Station Building - Sudbury Town Stn	Void	Asbestos	No Access: Presumed				Above wooden slats				Yes	
24287	ACTIVE	P	P089-00-1/901/FLR-01	Floor - 1 - GLAP - Station Building - Sudbury Town Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
14266	ACTIVE	P	P089-00-1/951	Disused Room - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14267	ACTIVE	P	P089-00-1/952	Disused Room - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24289	ACTIVE	P	P089-00-1/952/FLR-01	Floor - 1 - Disused Room - Station Building - Sudbury Town Stn	Void	Asbestos	No Access: Presumed				Beneath wooden floor					Yes
14268	ACTIVE	P	P089-00-1/953	Disused Room - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14269	ACTIVE	P	P089-00-1/954	Disused Room - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24292	ACTIVE	P	P089-00-1/954/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Sudbury Town Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
24291	ACTIVE	P	P089-00-1/954/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Sudbury Town Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
24290	ACTIVE	P	P089-00-1/954/FLR-01	Floor - 1 - Disused Room - Station Building - Sudbury Town Stn	Void	Asbestos	Surveyed – Not Detected				Solid beneath carpet flooring					Yes
14270	ACTIVE	P	P089-00-A/601	Stairs: Linear - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14271	ACTIVE	P	P089-00-A/602	Stairs: Linear - Station Building - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P093-00 - Station Building - Sudbury Hill Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14274	ACTIVE	P	P093-00-1/001	Booking Hall - Station Building - Sudbury Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24297	ACTIVE	P	P093-00-1/001	Booking Hall - Station Building - Sudbury Hill Stn	Lead/Leading	Lead Paint/Lead	Known				Telephone Kiosk surround - Blue gloss - 3m². Thickness : 0.11mm Analysis : 1.5%					
24298	ACTIVE	P	P093-00-1/001	Booking Hall - Station Building - Sudbury Hill Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Booking hall ceiling - 400ft above ground - no access to sample					
14275	ACTIVE	P	P093-00-1/011	Ticket Office - Station Building - Sudbury Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25187	ACTIVE	P	P093-00-1/011/CLG-01	Ceiling: Solid - 1 - Ticket Office - Station Building - Sudbury Hill Stn	Void	Asbestos	No Access: Presumed				Wooden board & joists above false ceiling - no access above				Yes	
24300	ACTIVE	P	P093-00-1/011/CLG-01	Ceiling: Solid - 1 - Ticket Office - Station Building - Sudbury Hill Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
24299	ACTIVE	P	P093-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Sudbury Hill Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
14276	ACTIVE	P	P093-00-1/021	POM - Station Building - Sudbury Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24301	ACTIVE	P	P093-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Sudbury Hill Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
14277	ACTIVE	P	P093-00-1/031	Mess Room - Station Building - Sudbury Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24302	ACTIVE	P	P093-00-1/031/WAL-002	Wall: Internal - 2 - Mess Room - Station Building - Sudbury Hill Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Old LUL heater 2x foam panels within		2			
24303	ACTIVE	P	P093-00-1/031/WAL-002	Wall: Internal - 2 - Mess Room - Station Building - Sudbury Hill Stn	Void	Asbestos	No Access: Presumed				Above metal hatch					
14278	ACTIVE	P	P093-00-1/036	Switch Room - Station Building - Sudbury Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14279	ACTIVE	P	P093-00-1/053	Station Supervisors Office - Station Building - Sudbury Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24306	ACTIVE	P	P093-00-1/053	Station Supervisors Office - Station Building - Sudbury Hill Stn	Lead/Leading	Lead Paint/Lead	Known				2 x Windows frames - White gloss - 0.5m². Thickness : 0.20mm Analysis : 6.0%					
45349	ACTIVE	P	P093-00-1/053	Station Supervisors Office - Station Building - Sudbury Hill Stn	Lead/Leading	Lead Paint/Lead	Known				2x Windows frames - White gloss Thickness : 0.20mm Analysis : 6.0%				N	N



Hazardous Material Asset Register - Summary



P093-00 - Station Building - Sudbury Hill Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24222	ACTIVE	P	P093-00-1/053/DOR-01	Door - 1 - Station Supervisors Office - Station Building - Sudbury Hill Stn	Lead/Leading	Lead Paint/Lead	Known				Inside of door - Blue gloss - 2m². Thickness : 0.28mm Analysis : 3.0%					
25188	ACTIVE	P	P093-00-1/053/DOR-01	Door - 1 - Station Supervisors Office - Station Building - Sudbury Hill Stn	Lead/Leading	Lead Paint/Lead	Known				Outside of door - Blue gloss - 2m². Thickness : 1.05mm Analysis : 3.0%					
24304	ACTIVE	P	P093-00-1/053/FLR-01	Floor - 1 - Station Supervisors Office - Station Building - Sudbury Hill Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl floor tiles					
24305	INACTIVE	P	P093-00-1/053/WAL-002	Wall: Internal - 2 - Station Supervisors Office - Station Building - Sudbury Hill Stn	LUL Heaters	Asbestos	Surveyed – Not Detected									
14280	ACTIVE	P	P093-00-1/071	Circulation Area - Station Building - Sudbury Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14281	ACTIVE	P	P093-00-1/081	Lobby - Station Building - Sudbury Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24383	ACTIVE	P	P093-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Sudbury Hill Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
24382	ACTIVE	P	P093-00-1/081/FLR-01	Floor - 1 - Lobby - Station Building - Sudbury Hill Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath computer tiles					Yes
14282	ACTIVE	P	P093-00-1/246	Toilet - Station Building - Sudbury Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14283	ACTIVE	P	P093-00-1/291	Mess Room - Station Building - Sudbury Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24385	ACTIVE	P	P093-00-1/291	Mess Room - Station Building - Sudbury Hill Stn	Lead/Leading	Lead Paint/Lead	Known				Window frame outside - Grey gloss - 0.3m². Thickness : 0.46mm Analysis : 3.2%					
24386	ACTIVE	P	P093-00-1/291	Mess Room - Station Building - Sudbury Hill Stn	Lead/Leading	Lead Paint/Lead	Known				Outside of door - Blue gloss - 2m². Thickness : 0.45mm Analysis : 3.4%					
24387	ACTIVE	P	P093-00-1/291/DOR-01	Door - 1 - Mess Room - Station Building - Sudbury Hill Stn	Lead/Leading	Lead Paint/Lead	Removed				Door - Pink gloss - 2m². Thickness : 0.14m Analysis : 1.9%					
24384	ACTIVE	P	P093-00-1/291/WAL-004	Wall: Internal - 4 - Mess Room - Station Building - Sudbury Hill Stn		Asbestos	Surveyed – Not Detected				Supalux panel above door					
14284	ACTIVE	P	P093-00-1/426	Toilet: Female - Station Building - Sudbury Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24388	ACTIVE	P	P093-00-1/426/WAL-006	Wall: Internal - 6 - Toilet - Station Building - Sudbury Hill Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LUL heater 2x foam panels inside		2			



Hazardous Material Asset Register - Summary



P093-00 - Station Building - Sudbury Hill Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24224	ACTIVE	P	P093-00-1/426/WDW-01	Window - 1 - Toilet - Station Building - Sudbury Hill Stn	Lead/Leading	Lead Paint/Lead	Known				Toilet windows - white gloss - 0.5m² - Woman's W/C. Thickness : 0.33mm Analysis : 5.5%					
24389	ACTIVE	P	P093-00-1/426/WDW-02	Window - 2 - Toilet - Station Building - Sudbury Hill Stn	Lead/Leading	Lead Paint/Lead	Known				Toilet windows - white gloss - 0.5m² - Woman's W/C. Thickness : 0.33mm Analysis : 5.5%				N	N
24390	ACTIVE	P	P093-00-1/426/WDW-03	Window - 3 - Toilet - Station Building - Sudbury Hill Stn	Lead/Leading	Lead Paint/Lead	Known				Toilet windows - white gloss - 0.5m² - Woman's W/C. Thickness : 0.33mm Analysis : 5.5%				N	N
14285	ACTIVE	P	P093-00-1/427	Toilet: Male - Station Building - Sudbury Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24395	ACTIVE	P	P093-00-1/427	Toilet: Male - Station Building - Sudbury Hill Stn	Lead/Leading	Lead Paint/Lead	Known				2 Window Frames - White gloss - 0.5m². Thickness : 0.33mm Thickness : 5.5%					
24394	ACTIVE	P	P093-00-1/427	Toilet: Male - Station Building - Sudbury Hill Stn	Lead/Leading	Lead Paint/Lead	Known				Cubicle doors - Blue gloss - 8m². Thickness : 0.44mm Analysis : 5.2%					
24392	ACTIVE	P	P093-00-1/427	Toilet: Male - Station Building - Sudbury Hill Stn	Lead/Leading	Lead Paint/Lead	Known				Outside of door - Blue gloss - 2m². Thickness : 0.52mm Analysis : 1.7%					
24393	ACTIVE	P	P093-00-1/427	Toilet: Male - Station Building - Sudbury Hill Stn	Lead/Leading	Lead Paint/Lead	Known				Inside of door - Blue gloss - 2m². Thickness : 0.44mm Analysis : 5.2%					
24391	ACTIVE	P	P093-00-1/427/WAL-003	Wall: Internal - 3 - Toilet - Station Building - Sudbury Hill Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LUL heater 2 x foam panels inside		2			
14286	ACTIVE	P	P093-00-1/451	Tenancy - Station Building - Sudbury Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24396	ACTIVE	P	P093-00-1/451/FLR-01	Floor - 1 - Tenancy - Station Building - Sudbury Hill Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				New vinyl floor tiles					
14287	ACTIVE	P	P093-00-1/452	Tenancy - Station Building - Sudbury Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14288	ACTIVE	P	P093-00-1/601	Stairs: Linear - Station Building - Sudbury Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14289	ACTIVE	P	P093-00-1/602	Stairs: Linear - Station Building - Sudbury Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25274	ACTIVE	P	P093-00-1/636/WAL-001	Wall: Internal - 1 - Overbridge - Station Building - Sudbury Hill Stn	Void	Asbestos	No Access: Presumed				Behind hatch					
14290	ACTIVE	P	P093-00-1/661	Switch Room - Station Building - Sudbury Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24397	ACTIVE	P	P093-00-1/661/FLR-01 80879964	Floor - 1 - Switch Room - Station Building - Sudbury Hill Stn Floor	Void	Asbestos	No Access: Presumed				Void 20m², rubble, mud, metal pipes beneath hatch					Yes



Hazardous Material Asset Register - Summary



P093-00 - Station Building - Sudbury Hill Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43169	ACTIVE	P	P093-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Sudbury Hill Stn	Cable Duct: Other	Asbestos	Presumed				Wall 1 Sealed Cable Ducts				N	N
42924	ACTIVE	P	P093-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Sudbury Hill Stn	Isolator Switches	Asbestos	Presumed				Switch Box 1 x 30amp - Fair Condition No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.				N	N
42923	ACTIVE	P	P093-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Sudbury Hill Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box x3 - Fair Condition No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.				N	N
42925	ACTIVE	P	P093-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Sudbury Hill Stn	Other Electrical Boxes	Asbestos	Presumed				Electrical Box x1 - Fair Condition No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.				N	N
42926	ACTIVE	P	P093-00-1/661/WAL-005	Wall: Internal - 5 - Switch Room - Station Building - Sudbury Hill Stn	Isolator Switches	Asbestos	Presumed				Switch Box 1 x 60amp - Fair Condition No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.				N	N
43170	ACTIVE	P	P093-00-1/661/WAL-007	Wall: Internal - 7 - Switch Room - Station Building - Sudbury Hill Stn	Other Electrical Boxes	Asbestos	Presumed				Wall 7 Trunking x2 No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		2		N	N
42927	ACTIVE	P	P093-00-1/661/WAL-007	Wall: Internal - 7 - Switch Room - Station Building - Sudbury Hill Stn	Isolator Switches	Asbestos	Presumed				Switch Box x4 , 3 x 60amp , 1 x 100amp - Fair Condition No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.				N	N
14291	ACTIVE	P	P093-00-1/746	SCR - Station Building - Sudbury Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42934	ACTIVE	P	P093-00-1/746	SCR - Station Building - Sudbury Hill Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Outside of Door - Blue Gloss 3m ² HMU Re-Inspection - OK					
42937	ACTIVE	P	P093-00-1/746	SCR - Station Building - Sudbury Hill Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Window Frame - White Gloss - 0.5m ² HMU Re-Inspection - ok					
42936	ACTIVE	P	P093-00-1/746	SCR - Station Building - Sudbury Hill Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Window frame outside - Grey Gloss - 0.3m ² HMU Re-Inspection - OK					
42935	ACTIVE	P	P093-00-1/746	SCR - Station Building - Sudbury Hill Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Inside of Door - Blue Gloss - 2m ² HMU Re-inspection - OK					



Hazardous Material Asset Register - Summary



P093-00 - Station Building - Sudbury Hill Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14292	ACTIVE	P	P093-00-2/053	Store - Station Building - Sudbury Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14293	ACTIVE	P	P093-00-2/261	Platform 1 - Westbound Main - Station Building - Sudbury Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45350	ACTIVE	P	P093-00-2/261	Platform 1 - Westbound Main - Station Building - Sudbury Hill Stn		Asbestos	Not Found during Inspection				Cable Sleeves - West part cable pit - No access covers jammed				N	N
14294	ACTIVE	P	P093-00-2/262	Platform 2 - Eastbound Main - Station Building - Sudbury Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45351	ACTIVE	P	P093-00-2/262	Platform 2 - Eastbound Main - Station Building - Sudbury Hill Stn		Asbestos	Not Found during Inspection				12x Cable Sleeves - East part cable pit				N	N
14295	ACTIVE	P	P093-00-2/406	CER - Station Building - Sudbury Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14296	ACTIVE	P	P093-00-2/661	Switch Room - Station Building - Sudbury Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45354	ACTIVE	P	P093-00-2/661	Switch Room - Station Building - Sudbury Hill Stn		Asbestos	Strongly Presumed				2x - Cable sleeves - No access		2		N	N
42928	ACTIVE	P	P093-00-2/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Sudbury Hill Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Trunking - Fair Condition No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.					
42929	ACTIVE	P	P093-00-2/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Sudbury Hill Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Box x2 2 x 60amp - Fair Condition No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.				N	N
45353	ACTIVE	P	P093-00-2/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Sudbury Hill Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1no Transformer Boxes Insulation within		1		N	N
45352	ACTIVE	P	P093-00-2/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Sudbury Hill Stn		Asbestos	Strongly Presumed				2x Trunking				N	N
42930	ACTIVE	P	P093-00-2/661/WAL-006	Wall: Internal - 6 - Switch Room - Station Building - Sudbury Hill Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Box x4, 2 x 60amp, 1 x 100amp, 1 x 200amp - Fair Condition No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.				N	N



Hazardous Material Asset Register - Summary



P093-00 - Station Building - Sudbury Hill Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42931	ACTIVE	P	P093-00-2/661/WAL-006	Wall: Internal - 6 - Switch Room - Station Building - Sudbury Hill Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Transformer Box x2 - Fair Condition No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.					
42932	ACTIVE	P	P093-00-2/661/WAL-006	Wall: Internal - 6 - Switch Room - Station Building - Sudbury Hill Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Trunking - Fair Condition - Fair Condition No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.					

P095-00 - Station Building - South Harrow Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14302	ACTIVE	P	P095-00-1/001	Booking Hall - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14303	ACTIVE	P	P095-00-1/011	Ticket Office - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25275	ACTIVE	P	P095-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - South Harrow Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
24401	ACTIVE	P	P095-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - South Harrow Stn		Asbestos	Surveyed – Not Detected				Supalux					
24400	ACTIVE	P	P095-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - South Harrow Stn	Void	Asbestos	No Access: Presumed				Beneath computer flooring					Yes
14304	ACTIVE	P	P095-00-1/021	POM - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24402	ACTIVE	P	P095-00-1/021/FLR-01	Floor - 1 - POM - Station Building - South Harrow Stn	Void	Asbestos	No Access: Presumed				Beneath computer flooring					Yes
24403	ACTIVE	P	P095-00-1/021/WAL-002	Wall: Internal - 2 - POM - Station Building - South Harrow Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - Foam insulation		1			
14305	ACTIVE	P	P095-00-1/031	Mess Room - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24404	ACTIVE	P	P095-00-1/031/WAL-004	Wall: Internal - 4 - Mess Room - Station Building - South Harrow Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LTB heater - foam insulation		1			
14306	ACTIVE	P	P095-00-1/036	Toilet: Unisex - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P095-00 - Station Building - South Harrow Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24405	ACTIVE	P	P095-00-1/036/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - South Harrow Stn	Glazing Rope	Asbestos	No Access: Presumed				No Glass ceiling, No Glazing Bars					
14307	ACTIVE	P	P095-00-1/071	Circulation Area - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14308	ACTIVE	P	P095-00-1/081	Lobby - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24406	ACTIVE	P	P095-00-1/081/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - South Harrow Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
25276	ACTIVE	P	P095-00-1/081/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
14309	ACTIVE	P	P095-00-1/082	Lobby - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14310	ACTIVE	P	P095-00-1/083	Lobby - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14311	ACTIVE	P	P095-00-1/236	Passage - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24407	ACTIVE	P	P095-00-1/236/FLR-01	Floor - 1 - Passage - Station Building - South Harrow Stn	Void	Asbestos	No Access: Presumed				Beneath computer flooring					Yes
14312	ACTIVE	P	P095-00-1/237	Passage - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24408	ACTIVE	P	P095-00-1/237/FLR-01	Floor - 1 - Passage - Station Building - South Harrow Stn	Void	Asbestos	No Access: Presumed				Beneath 2 x hatches					Yes
14313	ACTIVE	P	P095-00-1/238	Passage - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24487	ACTIVE	P	P095-00-1/238	Passage - Station Building - South Harrow Stn	Lead/Leading	Lead Paint/Lead	Removed				Sliding Gate - 4m2 Pink gloss. Thickness : 0.69mm Analysis : 5.1% No Gate Found Removed					
24488	ACTIVE	P	P095-00-1/238	Passage - Station Building - South Harrow Stn	Lead/Leading	Lead Paint/Lead	Removed				Metal pipe - 4m2 - Pink gloss. Thickness : 0.61mm Analysis : 4.4% Pipe not found during re inspection					
24486	ACTIVE	P	P095-00-1/238/FLR-01	Floor - 1 - Passage - Station Building - South Harrow Stn	Void	Asbestos	No Access: Presumed				Beneath Inspection cover					Yes
14314	ACTIVE	P	P095-00-1/247	Toilet - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P095-00 - Station Building - South Harrow Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14315	ACTIVE	P	P095-00-1/281	Station Supervisor Office - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24493	ACTIVE	P	P095-00-1/281	Station Supervisor Office - Station Building - South Harrow Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				2 x Heaters - Foam insulation		2			
24492	ACTIVE	P	P095-00-1/281/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - South Harrow Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				Yes	
24490	ACTIVE	P	P095-00-1/281/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - South Harrow Stn		Asbestos	Surveyed – Not Detected				Supalux					
24491	ACTIVE	P	P095-00-1/281/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - South Harrow Stn	Bitumen	Asbestos	Surveyed – Not Detected				1x acoustic tile in middle of ceiling					
24489	ACTIVE	P	P095-00-1/281/FLR-01	Floor - 1 - Station Supervisor Office - Station Building - South Harrow Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Linoleum					
14316	ACTIVE	P	P095-00-1/331	CER - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24494	ACTIVE	P	P095-00-1/331/WAL-002	Wall: Internal - 2 - CER - Station Building - South Harrow Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - Foam insulation		1			
14317	ACTIVE	P	P095-00-1/401	Bin Store - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14318	ACTIVE	P	P095-00-1/406	Store - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24499	ACTIVE	P	P095-00-1/406/CLG-01	Ceiling: Solid - 1 - Store - Station Building - South Harrow Stn	Void	Asbestos	No Access: Presumed				Above wooden ceiling				Yes	
14319	ACTIVE	P	P095-00-1/411	Store - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24500	ACTIVE	P	P095-00-1/411/CLG-01	Ceiling: Solid - 1 - Store - Station Building - South Harrow Stn	Void	Asbestos	No Access: Presumed				Above wooden panelling				Yes	
14320	ACTIVE	P	P095-00-1/412	Store - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14321	ACTIVE	P	P095-00-1/414	Store - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P095-00 - Station Building - South Harrow Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14322	ACTIVE	P	P095-00-1/416	Toilet: Unisex - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14323	ACTIVE	P	P095-00-1/426	Toilet: Female - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24502	ACTIVE	P	P095-00-1/426	Toilet: Female - Station Building - South Harrow Stn	LUL Heaters	Asbestos	Removed				No access to heater No Heater in this room - HMU Re-Inspection - 19/05/2016 Removed		1			
24503	ACTIVE	P	P095-00-1/426/ CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - South Harrow Stn	Glazing Rope	Asbestos	Strongly Presumed				Ceiling glazing bars					
24501	ACTIVE	P	P095-00-1/426/ FLR-01 80878717	Floor - 1 - Toilet - Station Building - South Harrow Stn Floor	Void	Asbestos	No Access: Presumed				Beneath hatch					Yes
14324	ACTIVE	P	P095-00-1/428	Toilet: Male - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24504	ACTIVE	P	P095-00-1/428/ CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - South Harrow Stn	Glazing Rope	Asbestos	Strongly Presumed				Ceiling glazing bars					
25282	ACTIVE	P	P095-00-1/428/ WAL-004	Wall: Internal - 4 - Toilet - Station Building - South Harrow Stn	LUL Heaters	Asbestos	Removed				No Heater in this room		1			
14325	ACTIVE	P	P095-00-1/429	Toilet: Unisex - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24506	ACTIVE	P	P095-00-1/429/ CLG-01 80878747	Ceiling: Solid - 1 - Toilet - Station Building - South Harrow Stn Ceiling: Solid	Glazing Rope	Asbestos	No Access: Presumed				Ceiling glazing bars					
24505	ACTIVE	P	P095-00-1/429/ FLR-01 80878748	Floor - 1 - Toilet - Station Building - South Harrow Stn Floor	Void	Asbestos	No Access: Presumed				Beneath hatch					Yes
14326	ACTIVE	P	P095-00-1/451	Tenancy - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24507	ACTIVE	P	P095-00-1/451	Tenancy - Station Building - South Harrow Stn	No Access	Asbestos	Surveyed – Not Detected				Tenancy Non Visible					
14327	ACTIVE	P	P095-00-1/452	Tenancy - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25283	ACTIVE	P	P095-00-1/452	Tenancy - Station Building - South Harrow Stn	No Access	Asbestos	Surveyed – Not Detected				Tenancy Non Visible					



Hazardous Material Asset Register - Summary



P095-00 - Station Building - South Harrow Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24595	ACTIVE	P	P095-00-1/452	Tenancy - Station Building - South Harrow Stn	Debris: Other	Asbestos	No Access: Presumed				Side Gate adjacent to 1/452 - 2x 0.04m ² Debris - 30cm from main gate No access - no key with Station supervisor		2			
14328	ACTIVE	P	P095-00-1/453	Computer Equipment Cupboard - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25284	ACTIVE	P	P095-00-1/453/CLG-01	Ceiling: Suspended - 1 - Computer Equipment Cupboard - Station Building - South Harrow Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above acoustic panels				Yes	
24510	ACTIVE	P	P095-00-1/453/CLG-01	Ceiling: Suspended - 1 - Computer Equipment Cupboard - Station Building - South Harrow Stn	Bitumen	Asbestos	Surveyed – Not Detected				Acoustic panels					
24508	ACTIVE	P	P095-00-1/453/FLR-01	Floor - 1 - Computer Equipment Cupboard - Station Building - South Harrow Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath carpet					Yes
24509	ACTIVE	P	P095-00-1/453/WAL-003	Wall: Internal - 3 - Computer Equipment Cupboard - Station Building - South Harrow Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				2 x Heater - Foam insulation		2			
14329	ACTIVE	P	P095-00-1/454	ATM - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14330	ACTIVE	P	P095-00-1/455	Tenancy - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14331	ACTIVE	P	P095-00-1/661	Switch Room - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24511	ACTIVE	P	P095-00-1/661/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - South Harrow Stn	Void	Asbestos	No Access: Presumed				Above chipboard ceiling				Yes	
24512	ACTIVE	P	P095-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - South Harrow Stn	Other Electrical Boxes	Asbestos	Presumed				3 x Transformer Boxes No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within		3			
24227	ACTIVE	P	P095-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - South Harrow Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x Switch Box 30amp (Grey) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
24513	ACTIVE	P	P095-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - South Harrow Stn	Cable Duct: Other	Asbestos	Presumed				3 x Sealed Ducts		3			



Hazardous Material Asset Register - Summary



P095-00 - Station Building - South Harrow Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14332	ACTIVE	P	P095-00-1/662	Switch Room - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25907	ACTIVE	P	P095-00-1/662/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - South Harrow Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1 x Transformer Box No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1		N	N
24572	ACTIVE	P	P095-00-1/662/WAL-002 80878796	Wall: Internal - 2 - Switch Room - Station Building - South Harrow Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				3 x Switch Boxes - 1 x 200amp & 2 x 60amp No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		3			
25906	ACTIVE	P	P095-00-1/662/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - South Harrow Stn	Isolator Switches	Asbestos	Strongly Presumed				4 x Switch Boxes - 3 x 60amp & 1 x 100amps No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		4		N	N
25285	ACTIVE	P	P095-00-1/662/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - South Harrow Stn		Asbestos	Surveyed – Not Detected				Supalux boarding					
14333	ACTIVE	P	P095-00-1/746	SCR - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24577	ACTIVE	P	P095-00-1/746/CLG-01 80878806	Ceiling: Solid - 1 - SCR - Station Building - South Harrow Stn Ceiling: Solid	Void	Asbestos	No Access: Presumed				Above chipboard				Yes	
14334	ACTIVE	P	P095-00-A/261	Platform 1 - Westbound Main - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24583	ACTIVE	P	P095-00-A/261	Platform 1 - Westbound Main - Station Building - South Harrow Stn	Other Electrical Boxes	Asbestos	Presumed				Current Relay Boxes west end of platform No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		2			
24584	ACTIVE	P	P095-00-A/261	Platform 1 - Westbound Main - Station Building - South Harrow Stn	Lead/Leading	Lead Paint/Lead	Removed				Outside Building on Platform 1 - On down pipe - 3m long - black gloss. Analysis : 9.1% Black Down Pipe Removed					
24587	ACTIVE	P	P095-00-A/261	Platform 1 - Westbound Main - Station Building - South Harrow Stn	Lead/Leading	Lead Paint/Lead	Known				Outside Building on Platform 1 - Auto phone - 0.2m² - Yellow gloss. Analysis : 1.0% Auto Phone has been changed		1			
24585	ACTIVE	P	P095-00-A/261	Platform 1 - Westbound Main - Station Building - South Harrow Stn	Lead/Leading	Lead Paint/Lead	Known				Outside Building on Platform 1 - Box on platform - 3m² - Red gloss. Analysis : 1.2%		1			
14335	ACTIVE	P	P095-00-A/262	Platform 2 - Eastbound Main - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P095-00 - Station Building - South Harrow Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24589	ACTIVE	p	P095-00-A/262	Platform 2 - Eastbound Main - Station Building - South Harrow Stn	Westing house Boxes	Asbestos	Strongly Presumed				5x Westing house brake box towards sidings No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		5			
24588	ACTIVE	p	P095-00-A/262	Platform 2 - Eastbound Main - Station Building - South Harrow Stn	Cable: Sheath	Asbestos	Removed				1x 25mm Cable - west end Cable not found - Removed, HMU Re-Inspection - 19/05/2016		1			
24590	ACTIVE	p	P095-00-A/262	Platform 2 - Eastbound Main - Station Building - South Harrow Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Signalling Equipment towards sidings No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
25293	ACTIVE	p	P095-00-A/262	Platform 2 - Eastbound Main - Station Building - South Harrow Stn	Other Electrical Boxes	Asbestos	Presumed				Current Relay Boxes at west end of platform 2 No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		2			
24586	ACTIVE	p	P095-00-A/262	Platform 2 - Eastbound Main - Station Building - South Harrow Stn	Lead/Leading	Lead Paint/Lead	Known				On door A/904 - 2m ² - Red gloss. Thickness : 0.12mm Analysis : 1.4%. Paint flaking off at bottom of door, poor condition.		1			
42893	ACTIVE	p	P095-00-A/262	Platform 2 - Eastbound Main - Station Building - South Harrow Stn	Lead/Leading	Lead Paint/Lead	Presumed				Red grit bin at end of platform 2. Lead paint flaking off, poor condition.		1		N	N
14336	ACTIVE	p	P095-00-A/347	Waiting Room - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14337	ACTIVE	p	P095-00-A/406	Store - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24596	ACTIVE	p	P095-00-A/406/FLR-01	Floor - 1 - Store - Station Building - South Harrow Stn	Cable Duct: Other	Asbestos	Known				1x Cable sleeve on floor by wall 1		1			
14338	ACTIVE	p	P095-00-A/411	Store - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24597	ACTIVE	p	P095-00-A/411/FLR-01	Floor - 1 - Store - Station Building - South Harrow Stn	Void	Asbestos	No Access: Presumed				Beneath wooden floor					Yes
42940	ACTIVE	p	P095-00-A/411/WAL-002	Wall: Internal - 2 - Store - Station Building - South Harrow Stn	Other Boarding	Asbestos	No Access: Presumed				W2 - Paxoline Board High Level					
42939	ACTIVE	p	P095-00-A/411/WAL-002	Wall: Internal - 2 - Store - Station Building - South Harrow Stn	Cable Duct: Other	Asbestos	No Access: Presumed				W2 Cable Ducts					



Hazardous Material Asset Register - Summary



P095-00 - Station Building - South Harrow Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42938	ACTIVE	P	P095-00-A/411/WAL-002	Wall: Internal - 2 - Store - Station Building - South Harrow Stn	Other Electrical Boxes	Asbestos	No Access: Presumed				Wall 2 Transformer Box					
14339	ACTIVE	P	P095-00-A/436	Waiting Room - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14340	ACTIVE	P	P095-00-A/437	Waiting Room - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14341	ACTIVE	P	P095-00-A/601	Stairs: Linear - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14342	ACTIVE	P	P095-00-A/602	Stairs: Linear - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24655	ACTIVE	P	P095-00-A/602	Stairs: Linear - Station Building - South Harrow Stn	Cable Duct: Other	Asbestos	Presumed				Beneath Stairs 2nd Room - 2x Cable sleeves (Cementitious)		2			
24656	ACTIVE	P	P095-00-A/602/WAL-002	Wall: Internal - 2 - Linear Stairs - Station Building - South Harrow Stn	Westing house Boxes	Asbestos	Presumed				Beneath Stairs 2nd Room - Westling house brake box Not found at last inspection, Re - Inspect to confirm No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
14343	ACTIVE	P	P095-00-A/661	Switch Room - Station Building - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24514	ACTIVE	P	P095-00-A/661	Switch Room - Station Building - South Harrow Stn	Cable Duct: Other	Asbestos	Presumed				Various Sealed Ducts on wall 2 / floor		7			
24657	ACTIVE	P	P095-00-A/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - South Harrow Stn		Asbestos	Surveyed – Not Detected				Supalux panel above door					
24660	ACTIVE	P	P095-00-A/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - South Harrow Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x 100amp & 4 x 60amp Switch Boxes No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		6			
43651	ACTIVE	P	P095-00-A/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - South Harrow Stn	Rope Gaskets	Asbestos	Sampled – Not Detected				Hessian rope gasket,Electrical equipment serial number 00282821 Switch Room A/661			R520451	N	N
24659	ACTIVE	P	P095-00-A/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - South Harrow Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			



Hazardous Material Asset Register - Summary



P095-00 - Station Building - South Harrow Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24658	ACTIVE	P	P095-00-A/661/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - South Harrow Stn		Asbestos	Surveyed – Not Detected				Supalux panel above door					

D214-01 - Signals Building - South Ealing To Northfields

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5179	ACTIVE	P	D214-01-0/731	CER - Signals Building - South Ealing To Northfields	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

D215-01 - Signal Cabin - Northfields Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5240	ACTIVE	P	D215-01-0/701	Mess Room - Signal Cabin - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

D215-02 - Signal Cabin - Northfields Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5241	ACTIVE	P	D215-02-1/081	Lobby - Signal Cabin - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5242	ACTIVE	P	D215-02-1/084	Lobby - Signal Cabin - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5243	ACTIVE	P	D215-02-1/292	Office - Signal Cabin - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24031	ACTIVE	P	D215-02-1/292	Office - Signal Cabin - Northfields Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				(Not on Maximo) Vinyl flooring - In corner of room between walls 2/3					
23389	ACTIVE	P	D215-02-1/292	Office - Signal Cabin - Northfields Stn	Cable: Sheath	Asbestos	Known				4x 4m long encapsulated cables into CMS - runs to 2/236 corner of walls 2 & 3		4			
23390	ACTIVE	P	D215-02-1/292	Office - Signal Cabin - Northfields Stn	Lead/Leading	Lead Paint/Lead	Known				All walls in office & stair case - 90m² Green emulsion. Thickness : 0.49mm Analysis : 4.6%					
5244	ACTIVE	P	D215-02-1/293	Office - Signal Cabin - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5245	ACTIVE	P	D215-02-1/294	Office - Signal Cabin - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D215-02 - Signal Cabin - Northfields Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5246	ACTIVE	P	D215-02-1/332	Mess Room - Signal Cabin - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23393	ACTIVE	P	D215-02-1/332	Mess Room - Signal Cabin - Northfields Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Mess Room Floor - Vinyl					
23394	ACTIVE	P	D215-02-1/332/WAL-001	Wall: Internal - 1 - Mess Room - Signal Cabin - Northfields Stn	Gasket :Pipework	Asbestos	Presumed				Mess Room - wall 1 & 4 - Gaskets to flanged joints on pipework		1		N	N
42358	ACTIVE	P	D215-02-1/332/WAL-004	Wall: Internal - 4 - Mess Room - Signal Cabin - Northfields Stn	Gasket :Pipework	Asbestos	Presumed				Mess Room - wall 1 & 4 - Gaskets to flanged joints on pipework		1		N	N
5247	ACTIVE	P	D215-02-1/418	Toilet: Unisex - Signal Cabin - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5248	ACTIVE	P	D215-02-1/576	Stairs: Linear - Signal Cabin - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5249	ACTIVE	P	D215-02-2/236	Passage - Signal Cabin - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23421	ACTIVE	P	D215-02-2/236	Passage - Signal Cabin - Northfields Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Trunking					
23420	ACTIVE	P	D215-02-2/236	Passage - Signal Cabin - Northfields Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 60amp Switch Box high level		1			
23422	ACTIVE	P	D215-02-2/236	Passage - Signal Cabin - Northfields Stn	Cable: Sheath	Asbestos	Strongly Presumed				4x Cables 4m long - 3 x grey, 1 x yellow from office 1/292		4			
5250	ACTIVE	P	D215-02-2/291	CER - Signal Cabin - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5251	ACTIVE	P	D215-02-2/413	Mess Room - Signal Cabin - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5252	ACTIVE	P	D215-02-2/731	CER - Signal Cabin - Northfields Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

D216-01 - Substation - Northfields To Boston Manor

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5253	ACTIVE	P	D216-01-0/081	Lobby - Substation - Northfields To Boston Manor	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5254	ACTIVE	P	D216-01-0/707	Power Room - Substation - Northfields To Boston Manor	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D216-01 - Substation - Northfields To Boston Manor

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5255	ACTIVE	p	D216-01-0/781	IMR - Substation - Northfields To Boston Manor	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

D217-01 - Signals Building - Boston Manor Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5278	ACTIVE	p	D217-01-1/951	Disused Room - Signals Building - Boston Manor Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24896	ACTIVE	p	D217-01-1/951	Disused Room - Signals Building - Boston Manor Stn	Roofing Tiles	Asbestos	Strongly Presumed				Roofing Tiles					
24895	ACTIVE	p	D217-01-1/951	Disused Room - Signals Building - Boston Manor Stn	Debris: Other	Asbestos	Known				Debris around the ground and platform of Signal Cabin					
24894	ACTIVE	p	D217-01-1/951	Disused Room - Signals Building - Boston Manor Stn	Void	Asbestos	No Access: Presumed				(Not on Maximo) Disused - above wood ceiling					
5279	ACTIVE	p	D217-01-2/951	Disused Room - Signals Building - Boston Manor Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25005	ACTIVE	p	D217-01-2/951	Disused Room - Signals Building - Boston Manor Stn	Lead/Leading	Lead Paint/Lead	Known				Front of building - Dark green gloss - 8m². Thickness : 0.18mm Analysis : 2.1%					
25004	ACTIVE	p	D217-01-2/951/CLG-01	Ceiling: Solid - 1 - Disused Room - Signals Building - Boston Manor Stn	Void	Asbestos	No Access: Presumed				Above wood ceiling				Yes	

D217-02 - Signals Building - Boston Manor Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5280	ACTIVE	p	D217-02-2/732	CER - Signals Building - Boston Manor Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									

D218-01 - Signals Building - Boston Manor To Osterley

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5281	ACTIVE	p	D218-01-0/706	IMR - Signals Building - Boston Manor To Osterley	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5282	ACTIVE	p	D218-01-0/707	Power Room - Signals Building - Boston Manor To Osterley	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D223-01 - Store - Hounslow East Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5369	ACTIVE	p	D223-01-A/901	Store Room - Store - Hounslow East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

D224-01 - Signals Building - Hounslow East To Hounslow Central

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5370	ACTIVE	p	D224-01-0/706	IMR - Signals Building - Hounslow East To Hounslow Central	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

D226-01 - Signals Building - Hounslow Central To Hounslow West

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5395	ACTIVE	p	D226-01-3/571	CER - Signals Building - Hounslow Central To Hounslow West	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5396	ACTIVE	p	D226-01-3/662	Switch Cupboard - Signals Building - Hounslow Central To Hounslow West	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5397	ACTIVE	p	D226-01-3/952	Disused Room - Signals Building - Hounslow Central To Hounslow West	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

D227-01 - Signals Building - Hounslow West Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5448	ACTIVE	p	D227-01-3/761	Equipment Room - Signals Building - Hounslow West Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

D228-02 - Perimeter Road Pump House - Hounslow West To Hatton Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5449	ACTIVE	p	D228-02-0/711	Pump Room - Perimeter Road Pump House - Hounslow West To Hatton Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
41696	ACTIVE	p	D228-02-0/711	Pump Room - Perimeter Road Pump House - Hounslow West To Hatton Cross	Cable Ducts: Bitumen	Asbestos	Known				10 x Bitumen cable ducts to floor below distribution boxes to wall 3		10		N	N



Hazardous Material Asset Register - Summary



D228-02 - Perimeter Road Pump House - Hounslow West To Hatton Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41700	ACTIVE	p	D228-02-0/711	Pump Room - Perimeter Road Pump House - Hounslow West To Hatton Cross	Cable Ducts: Bitumen	Asbestos	Presumed				Pump House and Vent Shaft - 1 x Switch box (fan) to wall 3 / corner of walls 2 and 3		1		N	N
41698	ACTIVE	p	D228-02-0/711	Pump Room - Perimeter Road Pump House - Hounslow West To Hatton Cross	Cable Sheath	Asbestos	Presumed				1 x Braided cable within bitumen cable ducts to floor below distribution box to wall 3		1			
41699	ACTIVE	p	D228-02-0/711	Pump Room - Perimeter Road Pump House - Hounslow West To Hatton Cross	Cable Ducts: Bitumen	Asbestos	Known				Pump House and Vent Shaft - 6 x Bitumen cable ducts within wall - wall 3		6		N	N

D228-03 - Parkway Road Pump House - Hounslow West To Hatton Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5450	ACTIVE	p	D228-03-0/711	Pump Room - Parkway Road Pump House - Hounslow West To Hatton Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

D234-02 - Wessex Road Vent Shaft - Heathrow Terminals 123 To Heathrow Terminal 4

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5721	ACTIVE	p	D234-02-1/661	Switch Room - Wessex Road Vent Shaft - Heathrow Airport To Heathrow Terminal 4	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5722	ACTIVE	p	D234-02-1/662	Switch Room - Wessex Road Vent Shaft - Heathrow Airport To Heathrow Terminal 4	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5723	ACTIVE	p	D234-02-1/776	Pump Room - Wessex Road Vent Shaft - Heathrow Airport To Heathrow Terminal 4	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

D243-01 - Store - Ealing Common Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5855	ACTIVE	p	D243-01-2/413	Store Room - Store - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D243-02 - Signal Cabin - Ealing Common Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5856	ACTIVE	P	D243-02-2/418	Toilet: Unisex - Signal Cabin - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24226	ACTIVE	P	D243-02-2/418/FLR-01	Floor - 1 - Toilet - Signal Cabin - Ealing Common Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl flooring					
5857	ACTIVE	P	D243-02-2/951	Disused Room - Signal Cabin - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24480	ACTIVE	P	D243-02-2/951	Disused Room - Signal Cabin - Ealing Common Stn	Westing house Boxes	Asbestos	Strongly Presumed				Various Westinghouse Boxes - Insulation within - EB End No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.					
24478	ACTIVE	P	D243-02-2/951/FLR-01	Floor - 1 - Disused Room - Signal Cabin - Ealing Common Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl flooring					
24479	ACTIVE	P	D243-02-2/951/FLR-02	Floor - 2 - Disused Room - Signal Cabin - Ealing Common Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl flooring					
5858	ACTIVE	P	D243-02-2/952	Mess Room - Signal Cabin - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
24481	ACTIVE	P	D243-02-2/952/CLG-01	Ceiling: Solid - 1 - Mess Room - Signal Cabin - Ealing Common Stn	Void	Asbestos	Surveyed – Not Detected				Floor boards above Timber joints				Yes	
42148	ACTIVE	P	D243-02-2/952/WAL-001	Wall: Internal - 1 - Mess Room - Signal Cabin - Ealing Common Stn	Other Electrical Boxes	Asbestos	Presumed				Electrical box on Wall 1 - asbestos insulation presumed within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
42149	ACTIVE	P	D243-02-2/952/WAL-002	Wall: Internal - 2 - Mess Room - Signal Cabin - Ealing Common Stn	Other Electrical Boxes	Asbestos	Presumed				Electrical box - presumed asbestos insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			

D243-03 - Signals Building - Ealing Common Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5859	ACTIVE	P	D243-03-2/706	IMR - Signals Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D243-03 - Signals Building - Ealing Common Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5860	ACTIVE	p	D243-03-2/761	Equipment Room - Signals Building - Ealing Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

P012-01 - Traction Control Cabin - Cockfosters To Oakwood

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12676	ACTIVE	p	P012-01-0/701	Equipment Room - Traction Control Cabin - Cockfosters To Oakwood	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

P012-03 - Signal Cabin - Cockfosters To Oakwood

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12677	ACTIVE	p	P012-03-1/701	IMR - Signal Cabin - Cockfosters To Oakwood	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12678	ACTIVE	p	P012-03-1/702	IMR - Signal Cabin - Cockfosters To Oakwood	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12679	ACTIVE	p	P012-03-1/706	IMR - Signal Cabin - Cockfosters To Oakwood	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12680	ACTIVE	p	P012-03-1/707	IMR - Signal Cabin - Cockfosters To Oakwood	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12681	ACTIVE	p	P012-03-A/236	Passage - Signal Cabin - Cockfosters To Oakwood	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12682	ACTIVE	p	P012-03-A/731	CER - Signal Cabin - Cockfosters To Oakwood	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12683	ACTIVE	p	P012-03-A/732	SER - Signal Cabin - Cockfosters To Oakwood	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12684	ACTIVE	p	P012-03-A/951	Switch Room - Signal Cabin - Cockfosters To Oakwood	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12685	ACTIVE	p	P012-03-A/952	Switch Room - Signal Cabin - Cockfosters To Oakwood	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P021-01 - Signals Building - Arnos Grove Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12861	ACTIVE	p	P021-01-1/731	CER - Signals Building - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

P021-02 - Store - Arnos Grove Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12862	ACTIVE	p	P021-02-0/571	Store Room - Store - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

P021-03 - P Way Store - Arnos Grove Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12863	ACTIVE	p	P021-03-1/047	Kitchen - P Way Store - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12864	ACTIVE	p	P021-03-1/571	Mess Room - P Way Store - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12865	ACTIVE	p	P021-03-A/801	Office - P Way Store - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

P021-04 - Train Crew Accommodation - Arnos Grove Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12866	ACTIVE	p	P021-04-2/332	Mess Room - Train Crew Accommodation - Arnos Grove Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
23961	ACTIVE	p	P021-04-2/332	Mess Room - Train Crew Accommodation - Arnos Grove Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					

P022-01 - P Way Accommodation - Arnos Grove To Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12867	ACTIVE	p	P022-01-0/741	Tunnel Telephone Room - P Way Cabin - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P022-01 - P Way Accommodation - Arnos Grove To Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12868	ACTIVE	P	P022-01-1/047	Kitchen - P Way Cabin - Bounds Green To Arnos Grove	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12869	ACTIVE	P	P022-01-1/081	Lobby - P Way Cabin - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12870	ACTIVE	P	P022-01-1/331	Mess Room - P Way Cabin - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12871	ACTIVE	P	P022-01-1/571	Store - P Way Cabin - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12872	ACTIVE	P	P022-01-A/706	IMR - P Way Cabin - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12873	ACTIVE	P	P022-01-A/801	Office - P Way Cabin - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

P022-04 - Points Care Team Accommodation - Arnos Grove To Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12875	ACTIVE	P	P022-04-1/411	Store - P Way Accommodation - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12876	ACTIVE	P	P022-04-1/412	Store - P Way Accommodation - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12877	ACTIVE	P	P022-04-1/413	Store - P Way Accommodation - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12878	ACTIVE	P	P022-04-1/571	Store - P Way Accommodation - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12879	ACTIVE	P	P022-04-1/576	Stairs: Linear - P Way Accommodation - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12880	ACTIVE	P	P022-04-1/801	P Way Office - P Way Accommodation - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12881	ACTIVE	P	P022-04-1/951	Disused Room - P Way Accommodation - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P022-04 - Points Care Team Accommodation - Arnos Grove To Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12882	ACTIVE	p	P022-04-A/081	Lobby - P Way Accommodation - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12883	ACTIVE	p	P022-04-A/316	Locker Room - P Way Accommodation - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12884	ACTIVE	p	P022-04-A/317	Locker Room - P Way Accommodation - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12885	ACTIVE	p	P022-04-A/761	CER - P Way Accommodation - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12886	ACTIVE	p	P022-04-A/801	Office - P Way Accommodation - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12887	ACTIVE	p	P022-04-B/047	Kitchen - P Way Accommodation - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12888	ACTIVE	p	P022-04-B/236	Passage - P Way Accommodation - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12889	ACTIVE	p	P022-04-B/416	Shower Room - P Way Accommodation - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12890	ACTIVE	p	P022-04-B/417	Toilet: Unisex - P Way Accommodation - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12891	ACTIVE	p	P022-04-B/661	Switch Room - P Way Accommodation - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12892	ACTIVE	p	P022-04-B/776	Plant Room - P Way Accommodation - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12893	ACTIVE	p	P022-04-B/801	Office - P Way Accommodation - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12894	ACTIVE	p	P022-04-B/802	Office - P Way Accommodation - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12895	ACTIVE	p	P022-04-B/803	Office - P Way Accommodation - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P024-02 - Substation - Bounds Green To Wood Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12945	ACTIVE	P	P024-02-1/781	Electrical Room - Substation - Bounds Green To Wood Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

P064-01 - Station Building - Dover Street Disused Station - Piccadilly Circus To Green Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13693	ACTIVE	P	P064-01-5/411	Disused Room - Dover Street Disused Station - Piccadilly Circus To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13694	ACTIVE	P	P064-01-5/731	CER - Dover Street Disused Station - Piccadilly Circus To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13695	ACTIVE	P	P064-01-5/761	Switch Room - Dover Street Disused Station - Piccadilly Circus To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13696	ACTIVE	P	P064-01-5/762	Computer Equipment Cupboard - Dover Street Disused Station - Piccadilly Circus To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13697	ACTIVE	P	P064-01-5/763	Computer Equipment Cupboard - Dover Street Disused Station - Piccadilly Circus To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13698	ACTIVE	P	P064-01-5/764	Computer Equipment Cupboard - Dover Street Disused Station - Piccadilly Circus To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13699	ACTIVE	P	P064-01-5/765	Computer Equipment Cupboard - Dover Street Disused Station - Piccadilly Circus To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13700	ACTIVE	P	P064-01-5/766	Computer Equipment Cupboard - Dover Street Disused Station - Piccadilly Circus To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13701	ACTIVE	P	P064-01-5/767	Computer Equipment Cupboard - Dover Street Disused Station - Piccadilly Circus To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13702	ACTIVE	P	P064-01-5/768	Computer Equipment Cupboard - Dover Street Disused Station - Piccadilly Circus To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P064-01 - Station Building - Dover Street Disused Station - Piccadilly Circus To Green Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
13703	ACTIVE	p	P064-01-5/769	Computer Equipment Cupboard - Dover Street Disused Station - Piccadilly Circus To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13704	ACTIVE	p	P064-01-5/770	Computer Equipment Cupboard - Dover Street Disused Station - Piccadilly Circus To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13705	ACTIVE	p	P064-01-5/791	Disused Room - Dover Street Disused Station - Piccadilly Circus To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13706	ACTIVE	p	P064-01-5/901	Computer Equipment Cupboard - Dover Street Disused Station - Piccadilly Circus To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13707	ACTIVE	p	P064-01-5/902	Computer Equipment Cupboard - Dover Street Disused Station - Piccadilly Circus To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13708	ACTIVE	p	P064-01-5/903	Computer Equipment Cupboard - Dover Street Disused Station - Piccadilly Circus To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
13709	ACTIVE	p	P064-01-5/971	Disused Room - Dover Street Disused Station - Piccadilly Circus To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

P083-01 - Substation - North Ealing Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14170	ACTIVE	p	P083-01-1/781	Transformer Room - Substation - North Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

P083-02 - Signals Building - North Ealing Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14171	ACTIVE	p	P083-02-1/731	CER - Signals Building - North Ealing Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P089-01 - Store - Sudbury Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14272	ACTIVE	p	P089-01-1/371	Store Room - Store - Sudbury Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

P093-01 - Substation - Sudbury Hill Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14297	ACTIVE	p	P093-01-1/781	Substation Room - Substation - Sudbury Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

P094-01 - P Way Accommodation - Sudbury Hill To South Harrow

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14298	ACTIVE	p	P094-01-1/371	Mess Room - P Way Accommodation - Sudbury Hill To South Harrow	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

P094-02 - P Way Accommodation - Sudbury Hill To South Harrow

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14299	ACTIVE	p	P094-02-1/372	Mess Room - P Way Accommodation - Sudbury Hill To South Harrow	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

P094-03 - Store - Sudbury Hill To South Harrow

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14300	ACTIVE	p	P094-03-1/411	Store Room - Store - Sudbury Hill To South Harrow	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

P094-04 - Signals Building - Sudbury Hill To South Harrow

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14301	ACTIVE	p	P094-04-1/706	IMR - Signals Building - Sudbury Hill To South Harrow	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P095-05 - Train Crew Accommodation - South Harrow Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14344	ACTIVE	P	P095-05-A/081	Lobby - Train Crew Accommodation - South Harrow Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed				Room surveyed on report R724701					
53853	ACTIVE	P	P095-05-A/081	Lobby - Train Crew Accommodation - South Harrow Stn	Lead/Leading	Lead Paint/Lead	Known				White Matt Paint to Window Frames 4.92%			R724702		
24308	ACTIVE	P	P095-05-A/081/CLG-01	Ceiling: Solid - 1 - Lobby - Train Crew Accommodation - South Harrow Stn	Void	Asbestos	Surveyed – Not Detected				Above false ceiling - surveyed on R724701				Yes	
24580	ACTIVE	P	P095-05-A/081/CLG-01	Ceiling: Solid - 1 - Lobby - Train Crew Accommodation - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
24579	ACTIVE	P	P095-05-A/081/FLR-01	Floor - 1 - Lobby - Train Crew Accommodation - South Harrow Stn	Void	Asbestos	No Access: Presumed				Beneath floor hatch					Yes
24578	ACTIVE	P	P095-05-A/081/FLR-01	Floor - 1 - Lobby - Train Crew Accommodation - South Harrow Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Linoleum					
14345	ACTIVE	P	P095-05-A/236	Lobby - Train Crew Accommodation - South Harrow Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
53854	ACTIVE	P	P095-05-A/236	Lobby - Train Crew Accommodation - South Harrow Stn	Lead/Leading	Lead Paint/Lead	Known				White Matt Paint to Window Frames 4.92%			R724702		
24582	ACTIVE	P	P095-05-A/236/CLG-01	Ceiling: Solid - 1 - Lobby - Train Crew Accommodation - South Harrow Stn	Void	Asbestos	No Access: Presumed				Above wooden slats				Yes	
24581	ACTIVE	P	P095-05-A/236/FLR-01	Floor - 1 - Lobby - Train Crew Accommodation - South Harrow Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Linoleum					
14346	ACTIVE	P	P095-05-A/331	Mess Room - Train Crew Accommodation - South Harrow Stn	Stations: Rooms	Asbestos	Room: Surveyed – Asbestos Known				See report R724701 for more info					
53855	ACTIVE	P	P095-05-A/331	Mess Room - Train Crew Accommodation - South Harrow Stn	Lead/Leading	Lead Paint/Lead	Known				White Matt Paint to Window Frames 4.92%			R724702		
24592	ACTIVE	P	P095-05-A/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Train Crew Accommodation - South Harrow Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
24591	ACTIVE	P	P095-05-A/331/FLR-01	Floor - 1 - Mess Room - Train Crew Accommodation - South Harrow Stn	Vinyl tiles	Asbestos	Sampled – Not Detected				Linoleum					
53845	ACTIVE	P	P095-05-A/331/WAL-002	Wall: Internal - 2 - Mess Room - Train Crew Accommodation - South Harrow Stn	Bitumen	Asbestos	Known				Bitumen Sink Pads - 2no - Wall 2		2	R724701		



Hazardous Material Asset Register - Summary



P095-05 - Train Crew Accommodation - South Harrow Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14347	ACTIVE	P	P095-05-A/332	Disused Room - Train Crew Accommodation - South Harrow Stn	Stations: Rooms	Asbestos	Room: Surveyed – Asbestos Known				See Survey R724701					
53847	ACTIVE	P	P095-05-A/332	Disused Room - Train Crew Accommodation - South Harrow Stn	Lead/Leading	Lead Paint/Lead	Known				White Gloss to Door & Window Frames 5.51%			R724702		
24594	ACTIVE	P	P095-05-A/332/CLG-01	Ceiling: Solid - 1 - Disused Room - Train Crew Accommodation - South Harrow Stn	Void	Asbestos	Surveyed – Not Detected				Above false ceiling - No Asbestos Detected see report R724701				Yes	
25371	ACTIVE	P	P095-05-A/332/CLG-01	Ceiling: Solid - 1 - Disused Room - Train Crew Accommodation - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
24593	ACTIVE	P	P095-05-A/332/FLR-01	Floor - 1 - Disused Room - Train Crew Accommodation - South Harrow Stn	Vinyl tiles	Asbestos	Sampled – Not Detected				Linoleum - Sampled on report R724701					
53844	ACTIVE	P	P095-05-A/332/WAL-002	Wall: Internal - 2 - Disused Room - Train Crew Accommodation - South Harrow Stn	Bitumen	Asbestos	Known				Bitumen Sink Pads 2no - Wall 2		2	R724701		
14348	ACTIVE	P	P095-05-A/412	Store - Train Crew Accommodation - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14349	ACTIVE	P	P095-05-A/413	Store - Train Crew Accommodation - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14350	ACTIVE	P	P095-05-A/416	Toilet: Female - Train Crew Accommodation - South Harrow Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
53851	ACTIVE	P	P095-05-A/416	Toilet: Female - Train Crew Accommodation - South Harrow Stn	Lead/Leading	Lead Paint/Lead	Known				White Matt Gloss to Window Frames 4.92%			R724702		
24599	ACTIVE	P	P095-05-A/416/CLG-01	Ceiling: Solid - 1 - Toilet - Train Crew Accommodation - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
24653	ACTIVE	P	P095-05-A/416/CLG-01	Ceiling: Solid - 1 - Toilet - Train Crew Accommodation - South Harrow Stn	Void	Asbestos	Surveyed – Not Detected				Above false ceiling - area checked please see survey R724701 for more details				Yes	
14351	ACTIVE	P	P095-05-A/417	Toilet: Male - Train Crew Accommodation - South Harrow Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos				Room surveyed on report R724701					
53852	ACTIVE	P	P095-05-A/417	Toilet: Male - Train Crew Accommodation - South Harrow Stn	Lead/Leading	Lead Paint/Lead	Known				White Matt Paint to Window Frames 4.92%			R724702		



Hazardous Material Asset Register - Summary



P095-05 - Train Crew Accommodation - South Harrow Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14352	ACTIVE	P	P095-05-A/662	Switch Room - Train Crew Accommodation - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44067	ACTIVE	P	P095-05-A/662	Switch Room - Train Crew Accommodation - South Harrow Stn		Asbestos	Removed				1no Switch Box Asbestos Flash Guards Removed 20/12/2016		1			
24661	ACTIVE	P	P095-05-A/662/FLR-01	Floor - 1 - Switch Room - Train Crew Accommodation - South Harrow Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Linoleum					
24664	ACTIVE	P	P095-05-A/662/WAL-001	Wall: Internal - 1 - Switch Room - Train Crew Accommodation - South Harrow Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Box No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
24662	ACTIVE	P	P095-05-A/662/WAL-003	Wall: Internal - 3 - Switch Room - Train Crew Accommodation - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
24663	ACTIVE	P	P095-05-A/662/WAL-004	Wall: Internal - 4 - Switch Room - Train Crew Accommodation - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
14353	ACTIVE	P	P095-05-A/776	Plant Room - Train Crew Accommodation - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24310	ACTIVE	P	P095-05-A/776/CLG-01	Ceiling: Solid - 1 - Plant Room - Train Crew Accommodation - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
24666	ACTIVE	P	P095-05-A/776/CLG-01	Ceiling: Solid - 1 - Plant Room - Train Crew Accommodation - South Harrow Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
24665	ACTIVE	P	P095-05-A/776/FLR-01	Floor - 1 - Plant Room - Train Crew Accommodation - South Harrow Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Linoleum					
14354	ACTIVE	P	P095-05-A/901	Disused Room - Train Crew Accommodation - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24669	ACTIVE	P	P095-05-A/901/CLG-01	Ceiling: Solid - 1 - Disused Room - Train Crew Accommodation - South Harrow Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
24668	ACTIVE	P	P095-05-A/901/CLG-01	Ceiling: Solid - 1 - Disused Room - Train Crew Accommodation - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
25377	ACTIVE	P	P095-05-A/901/FLR-01	Floor - 1 - Disused Room - Train Crew Accommodation - South Harrow Stn	Void	Asbestos	No Access: Presumed				Beneath floor hatches					Yes



Hazardous Material Asset Register - Summary



P095-05 - Train Crew Accommodation - South Harrow Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24667	ACTIVE	P	P095-05-A/901/FLR-01	Floor - 1 - Disused Room - Train Crew Accommodation - South Harrow Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Linoleum					
14355	ACTIVE	P	P095-05-A/902	Store - Train Crew Accommodation - South Harrow Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
53849	ACTIVE	P	P095-05-A/902	Store - Train Crew Accommodation - South Harrow Stn	Lead/Leading	Lead Paint/Lead	Known				White Matt to Window Frames 5.9%			R724702		
53848	ACTIVE	P	P095-05-A/902	Store - Train Crew Accommodation - South Harrow Stn	Lead/Leading	Lead Paint/Lead	Known				White Gloss Paint to Door & Window Frames 5.51%			R724702		
24670	ACTIVE	P	P095-05-A/902/FLR-01	Floor - 1 - Store - Train Crew Accommodation - South Harrow Stn	Vinyl tiles	Asbestos	Sampled – Not Detected				Linoleum - sampled in report R724701					
24671	ACTIVE	P	P095-05-A/902/WAL-005	Wall: Internal - 5 - Store - Train Crew Accommodation - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
24672	ACTIVE	P	P095-05-A/902/WAL-006	Wall: Internal - 6 - Store - Train Crew Accommodation - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
14356	ACTIVE	P	P095-05-A/903	Disused Room - Train Crew Accommodation - South Harrow Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed				see report for R724701					
53856	ACTIVE	P	P095-05-A/903	Disused Room - Train Crew Accommodation - South Harrow Stn	Lead/Leading	Lead Paint/Lead	Known				White Matt Paint to Window Frames 4.92%			R724702		
24675	ACTIVE	P	P095-05-A/903/CLG-01	Ceiling: Solid - 1 - Disused Room - Train Crew Accommodation - South Harrow Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
24674	ACTIVE	P	P095-05-A/903/CLG-01	Ceiling: Solid - 1 - Disused Room - Train Crew Accommodation - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
25378	ACTIVE	P	P095-05-A/903/FLR-01	Floor - 1 - Disused Room - Train Crew Accommodation - South Harrow Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Linoleum					
24673	ACTIVE	P	P095-05-A/903/WAL-001	Wall: Internal - 1 - Disused Room - Train Crew Accommodation - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
53846	ACTIVE	P	P095-05-A/903/WAL-004	Wall: Internal - 4 - Disused Room - Train Crew Accommodation - South Harrow Stn	Bitumen	Asbestos	Sampled – Not Detected				Bitumen Sink Pads - 2no - Wall 4		2	R724701		



Hazardous Material Asset Register - Summary



P095-05 - Train Crew Accommodation - South Harrow Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14357	ACTIVE	P	P095-05-A/904	Training Room - Train Crew Accommodation - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25379	ACTIVE	P	P095-05-A/904/CLG-01	Ceiling: Solid - 1 - Office - Train Crew Accommodation - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
24677	ACTIVE	P	P095-05-A/904/CLG-01	Ceiling: Solid - 1 - Office - Train Crew Accommodation - South Harrow Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
24676	ACTIVE	P	P095-05-A/904/FLR-01	Floor - 1 - Office - Train Crew Accommodation - South Harrow Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath carpet					Yes
14358	ACTIVE	P	P095-05-A/905	Store - Train Crew Accommodation - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24678	ACTIVE	P	P095-05-A/905	Store - Train Crew Accommodation - South Harrow Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
14359	ACTIVE	P	P095-05-B/236	Lobby - Train Crew Accommodation - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24744	ACTIVE	P	P095-05-B/236/CLG-01	Ceiling: Solid - 1 - Lobby - Train Crew Accommodation - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
24745	ACTIVE	P	P095-05-B/236/CLG-01	Ceiling: Solid - 1 - Lobby - Train Crew Accommodation - South Harrow Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
24312	ACTIVE	P	P095-05-B/236/WAL-001	Wall: Internal - 1 - Lobby - Train Crew Accommodation - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
24743	ACTIVE	P	P095-05-B/236/WAL-005	Wall: Internal - 5 - Lobby - Train Crew Accommodation - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
14360	ACTIVE	P	P095-05-B/331	Mess Room - Train Crew Accommodation - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24748	ACTIVE	P	P095-05-B/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Train Crew Accommodation - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
24749	ACTIVE	P	P095-05-B/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Train Crew Accommodation - South Harrow Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
24746	ACTIVE	P	P095-05-B/331/FLR-01	Floor - 1 - Mess Room - Train Crew Accommodation - South Harrow Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Linoleum					



Hazardous Material Asset Register - Summary



P095-05 - Train Crew Accommodation - South Harrow Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24747	ACTIVE	P	P095-05-B/331/WAL-004	Wall: Internal - 4 - Mess Room - Train Crew Accommodation - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
14361	ACTIVE	P	P095-05-B/411	Store - Train Crew Accommodation - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24750	ACTIVE	P	P095-05-B/411	Store - Train Crew Accommodation - South Harrow Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
14362	ACTIVE	P	P095-05-B/416	Toilet: Female - Train Crew Accommodation - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24756	ACTIVE	P	P095-05-B/416/CLG-01	Ceiling: Solid - 1 - Toilet - Train Crew Accommodation - South Harrow Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
24755	ACTIVE	P	P095-05-B/416/CLG-01	Ceiling: Solid - 1 - Toilet - Train Crew Accommodation - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
24751	ACTIVE	P	P095-05-B/416/FLR-01	Floor - 1 - Toilet - Train Crew Accommodation - South Harrow Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Linoleum					
24752	ACTIVE	P	P095-05-B/416/WAL-001	Wall: Internal - 1 - Toilet - Train Crew Accommodation - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
24753	ACTIVE	P	P095-05-B/416/WAL-003	Wall: Internal - 3 - Toilet - Train Crew Accommodation - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
24754	ACTIVE	P	P095-05-B/416/WAL-004	Wall: Internal - 4 - Toilet - Train Crew Accommodation - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
14363	ACTIVE	P	P095-05-B/417	Toilet: Male - Train Crew Accommodation - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25387	ACTIVE	P	P095-05-B/417/CLG-01	Ceiling: Solid - 1 - Toilet - Train Crew Accommodation - South Harrow Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
24760	ACTIVE	P	P095-05-B/417/CLG-01	Ceiling: Solid - 1 - Toilet - Train Crew Accommodation - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
24757	ACTIVE	P	P095-05-B/417/FLR-01	Floor - 1 - Toilet - Train Crew Accommodation - South Harrow Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Linoleum					
24758	ACTIVE	P	P095-05-B/417/WAL-001	Wall: Internal - 1 - Toilet - Train Crew Accommodation - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					



Hazardous Material Asset Register - Summary



P095-05 - Train Crew Accommodation - South Harrow Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24759	ACTIVE	P	P095-05-B/417/WAL-004	Wall: Internal - 4 - Toilet - Train Crew Accommodation - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
14364	ACTIVE	P	P095-05-B/576	Stairs: Linear - Train Crew Accommodation - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14365	ACTIVE	P	P095-05-B/801	Library/Study - Train Crew Accommodation - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24761	ACTIVE	P	P095-05-B/801/FLR-01	Floor - 1 - Office - Train Crew Accommodation - South Harrow Stn	Void	Asbestos	No Access: Presumed				Beneath wooden floor (carpet on wood)					Yes
24762	ACTIVE	P	P095-05-B/801/WAL-004	Wall: Internal - 4 - Office - Train Crew Accommodation - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
14366	ACTIVE	P	P095-05-B/802	Meditation Room - Train Crew Accommodation - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24763	ACTIVE	P	P095-05-B/802	Meditation Room - Train Crew Accommodation - South Harrow Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
14367	ACTIVE	P	P095-05-B/803	Train Technician Office - Train Crew Accommodation - South Harrow Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24766	ACTIVE	P	P095-05-B/803/CLG-01	Ceiling: Solid - 1 - Train Technician Office - Train Crew Accommodation - South Harrow Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
25388	ACTIVE	P	P095-05-B/803/CLG-01	Ceiling: Solid - 1 - Train Technician Office - Train Crew Accommodation - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
24764	ACTIVE	P	P095-05-B/803/FLR-01	Floor - 1 - Train Technician Office - Train Crew Accommodation - South Harrow Stn	Void	Asbestos	No Access: Presumed				Beneath wooden floor (carpet on wood)					Yes
24765	ACTIVE	P	P095-05-B/803/WAL-004	Wall: Internal - 4 - Train Technician Office - Train Crew Accommodation - South Harrow Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Half plasterboard, half plaster on solid					



Hazardous Material Asset Register - Summary



P123-01 - Station Building - Aldwych Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14368	ACTIVE	P	P123-01-1/001	Booking Hall - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42268	ACTIVE	P	P123-01-1/001	Booking Hall - Station Building - Aldwych Disused Stn	Gasket :Pipework	Asbestos	Presumed				Remnants of Gasket to disused pipe work in disused fire cupboard					
44493	ACTIVE	P	P123-01-1/001	Booking Hall - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				Black gloss to noticeboards in Booking Hall, Circulating Area and Stairs / Passage 2.2%			R609826		
44491	ACTIVE	P	P123-01-1/001	Booking Hall - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				Cream gloss to walls of Booking Hall, Circulating Area and Stairs and Passage 6.93%			R609826		
14369	ACTIVE	P	P123-01-1/011	Disused Room - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20379	ACTIVE	P	P123-01-1/011/FLR-01	Floor - 1 - Disused Room - Station Building - Aldwych Disused Stn	Void	Asbestos	No Access: Presumed				No Access - Below Computer Flooring					Y
20378	ACTIVE	P	P123-01-1/011/WAL-002	Wall: Internal - 2 - Disused Room - Station Building - Aldwych Disused Stn	LUL Heaters	Asbestos	Strongly Presumed				LTB Heater - Internal Board		1			
14370	ACTIVE	P	P123-01-1/021	POM - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42266	ACTIVE	P	P123-01-1/021/CLG-01 80925870	Ceiling: Solid - 1 - POM - Station Building - Aldwych Disused Stn Ceiling: Solid	Mastic	Asbestos	Presumed				Mastic to Air Handling Units					
20380	ACTIVE	P	P123-01-1/021/FLR-01	Floor - 1 - POM - Station Building - Aldwych Disused Stn	Void	Asbestos	No Access: Presumed				No Access below Computer Flooring					Y
14371	ACTIVE	P	P123-01-1/036	Disused Room - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14372	ACTIVE	P	P123-01-1/071	Circulation Area - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44492	ACTIVE	P	P123-01-1/071	Circulation Area - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				Cream gloss to walls of Booking Hall, Circulating Area and Stairs and Passage 6.93%			R609826		
44494	ACTIVE	P	P123-01-1/071	Circulation Area - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				Black gloss to noticeboards in Booking Hall, Circulating Area and Stairs / Passage 2.2%			R609826		
14373	ACTIVE	P	P123-01-1/186	Station Entrance - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20381	ACTIVE	P	P123-01-1/186	Station Entrance - Station Building - Aldwych Disused Stn	Void	Asbestos	No Access: Presumed				No Access - to wooden boxing around door					
14374	ACTIVE	P	P123-01-1/187	Station Entrance - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P123-01 - Station Building - Aldwych Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20382	ACTIVE	p	P123-01-1/187	Station Entrance - Station Building - Aldwych Disused Stn	Void	Asbestos	No Access: Presumed				No access to boxing around entrance					
14375	ACTIVE	p	P123-01-1/188	Station Entrance - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20383	ACTIVE	p	P123-01-1/188	Station Entrance - Station Building - Aldwych Disused Stn	Void	Asbestos	No Access: Presumed				No access to wooden boxing above door					
14376	ACTIVE	p	P123-01-1/201	Passage - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20384	ACTIVE	p	P123-01-1/201	Passage - Station Building - Aldwych Disused Stn	Boarding: Cement	Asbestos	Surveyed – Not Detected				Telephone Boxes - No Asbestos Detected					
44499	ACTIVE	p	P123-01-1/201	Passage - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				Black gloss to noticeboards 7.96% by Entrance 1/186			R609826		
44495	ACTIVE	p	P123-01-1/201	Passage - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				White emulsion to ceiling 4.13% by Entrance 1/186			R609826		
44503	ACTIVE	p	P123-01-1/201	Passage - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				Black Gloss to lower section of the concrete columns 3.8% by Stairs 1/601			R609826		
14377	ACTIVE	p	P123-01-1/202	Passage - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44496	ACTIVE	p	P123-01-1/202	Passage - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				White emulsion to ceiling 4.13%			R609826		
44504	ACTIVE	p	P123-01-1/202	Passage - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				Black Gloss to lower section of the concrete columns 3.8% by 1/601			R609826		
44500	ACTIVE	p	P123-01-1/202	Passage - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				Black gloss to noticeboards 7.96%			R609826		
14378	ACTIVE	p	P123-01-1/203	Passage - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44539	ACTIVE	p	P123-01-1/203	Passage - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				White emulsion to the ceiling 1.46% by Entrance 1/187			R609826		
14379	ACTIVE	p	P123-01-1/236	Lobby - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44534	ACTIVE	p	P123-01-1/236	Lobby - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				While emulsion to ceiling 18.5%			R609826		
44510	ACTIVE	p	P123-01-1/236	Lobby - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				Cream emulsion to walls 8.55%			R609826		



Hazardous Material Asset Register - Summary



P123-01 - Station Building - Aldwych Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14380	ACTIVE	P	P123-01-1/237	Lobby - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20385	ACTIVE	P	P123-01-1/237	Lobby - Station Building - Aldwych Disused Stn	Void	Asbestos	No Access: Presumed				Computer Flooring - No Access Below					Y
14381	ACTIVE	P	P123-01-1/406	Disused Room - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14382	ACTIVE	P	P123-01-1/426	Toilet: Unisex - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42267	ACTIVE	P	P123-01-1/426	Toilet: Unisex - Station Building - Aldwych Disused Stn	Bakerlite	Asbestos	Presumed				Toilet system 2nd cubical from main door; Cistern Labeled asbestos, however this was sampled and confirmed non asbestos in report R19873?		1	R19873		
44509	ACTIVE	P	P123-01-1/426	Toilet: Unisex - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				Cream gloss to window frames 21.2%			R609826		
44507	ACTIVE	P	P123-01-1/426	Toilet: Unisex - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				Green gloss to doors and door frames 3.23%			R609826		
44508	ACTIVE	P	P123-01-1/426	Toilet: Unisex - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				White emulsion to ceiling 2.89%			R609826		
14383	ACTIVE	P	P123-01-1/427	Toilet: Unisex - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44536	ACTIVE	P	P123-01-1/427	Toilet: Unisex - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				White emulsion to ceiling 1.48% (on report as 1/417)			R609826		
14384	ACTIVE	P	P123-01-1/451	Disused - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20386	ACTIVE	P	P123-01-1/451	Disused - Station Building - Aldwych Disused Stn	Bitumen	Asbestos	Surveyed – Not Detected				Acoustic Panel under Sink					
14385	ACTIVE	P	P123-01-1/601	Stairs: Linear - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44497	ACTIVE	P	P123-01-1/601	Stairs: Linear - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				White emulsion to ceiling 4.13%			R609826		
44505	ACTIVE	P	P123-01-1/601	Stairs: Linear - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				Black Gloss to lower section of the concrete columns 3.8%			R609826		
44501	ACTIVE	P	P123-01-1/601	Stairs: Linear - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				Black gloss to noticeboards 7.96% - duplicate of 1/201?			R609826		
14386	ACTIVE	P	P123-01-1/602	Stairs: Linear - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P123-01 - Station Building - Aldwych Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44506	INACTIVE	P	P123-01-1/602	Stairs: Linear - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Removed				Black Gloss to lower section of the concrete columns 3.8% - No columns to stairs 1/602 - No evidence of columns to stairs 1/602			R609826		
44498	ACTIVE	P	P123-01-1/602	Stairs: Linear - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				White emulsion to ceiling 4.13%			R609826		
44502	INACTIVE	P	P123-01-1/602	Stairs: Linear - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Removed				Black gloss to noticeboards 7.96%			R609826		
14387	ACTIVE	P	P123-01-1/603	Lobby - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14388	ACTIVE	P	P123-01-1/631	Stairs: Spiral - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44478	ACTIVE	P	P123-01-1/631	Stairs: Spiral - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Gloss to Walls 1.37%			R609826		
14389	ACTIVE	P	P123-01-1/661	Switch Room - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20388	ACTIVE	P	P123-01-1/661/FLR-01	Floor - 1 - Switch Room - Station Building - Aldwych Disused Stn	Other Electrical Boxes	Asbestos	Presumed				1no Transformer Box - Asbestos materials within		1			
20387	ACTIVE	P	P123-01-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Aldwych Disused Stn	Isolator Switches	Asbestos	Strongly Presumed				3x60amp 1x100amp Switch Boxes - Asbestos materials within		4			
25717	ACTIVE	P	P123-01-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Aldwych Disused Stn	Other Boarding	Asbestos	Presumed				Paxoline Board on Busbar					
14390	ACTIVE	P	P123-01-1/746	SCR - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14391	ACTIVE	P	P123-01-2/053	Store - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44486	ACTIVE	P	P123-01-2/053	Store - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				White gloss to walls 1.25%			R609826		
14392	ACTIVE	P	P123-01-2/202	Passage - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44483	ACTIVE	P	P123-01-2/202	Passage - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				White emulsion to ceiling beams 8.05%			R609826		
44479	ACTIVE	P	P123-01-2/202	Passage - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Gloss to Walls 5.56%			R609826		



Hazardous Material Asset Register - Summary



P123-01 - Station Building - Aldwych Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44481	ACTIVE	p	P123-01-2/202	Passage - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				White emulsion to ceilings 1.11%			R609826		
14393	ACTIVE	p	P123-01-2/203	Passage - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44482	ACTIVE	p	P123-01-2/203	Passage - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				White emulsion to ceiling 1.11%			R609826		
44484	ACTIVE	p	P123-01-2/203	Passage - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				White emulsion to ceiling beam 8.05%			R609826		
44480	ACTIVE	p	P123-01-2/203	Passage - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Gloss to Walls 5.56%			R609826		
14394	ACTIVE	p	P123-01-2/236	Passage - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14395	ACTIVE	p	P123-01-2/281	Station Control Room - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44489	ACTIVE	p	P123-01-2/281	Station Control Room - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				White gloss to the ceiling beam 3.16%			R609826		
44488	ACTIVE	p	P123-01-2/281	Station Control Room - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				White emulsion to ceiling 5.16%			R609826		
44490	ACTIVE	p	P123-01-2/281	Station Control Room - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				White gloss to window frames 1.28%			R609826		
14396	ACTIVE	p	P123-01-2/407	Store - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14397	ACTIVE	p	P123-01-2/416	Toilet: Unisex - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14398	ACTIVE	p	P123-01-2/417	Toilet: Unisex - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14399	ACTIVE	p	P123-01-2/631	Stairs: Spiral - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14400	ACTIVE	p	P123-01-2/661	Store - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20389	ACTIVE	p	P123-01-2/661	Store - Station Building - Aldwych Disused Stn	Isolator Switches	Asbestos	Strongly Presumed				3no 60amp Switch Boxes - Asbestos materials within		3			
44485	ACTIVE	p	P123-01-2/661	Store - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				White emulsion to beam 1%			R609826		



Hazardous Material Asset Register - Summary



P123-01 - Station Building - Aldwych Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14401	ACTIVE	P	P123-01-2/801	Store - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20391	ACTIVE	P	P123-01-2/801/FLR-01	Floor - 1 - Store - Station Building - Aldwych Disused Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl Flooring					
14402	ACTIVE	P	P123-01-2/991	Disused Room - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25718	ACTIVE	P	P123-01-2/991	Disused Room - Station Building - Aldwych Disused Stn	Boarding: AIB	Asbestos	Strongly Presumed				Partition Wall between 2/991 & 2/661; SID Plate situated on; has been painted over boarding 11/11/2015. AIB fillet in-between Supalux boarding.					
20392	ACTIVE	P	P123-01-2/991	Disused Room - Station Building - Aldwych Disused Stn	Gasket :Pipework	Asbestos	Presumed				Gaskets on Flanged Pipework - Possible rubber NAD material on re-inspection		1			
14403	ACTIVE	P	P123-01-2/992	Disused Room - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20393	ACTIVE	P	P123-01-2/992	Disused Room - Station Building - Aldwych Disused Stn	Cable: Sheath	Asbestos	Strongly Presumed				2no 15mm dia x 300mm Cables High Level	0	2			
20394	ACTIVE	P	P123-01-2/992	Disused Room - Station Building - Aldwych Disused Stn	Cable: Sheath	Asbestos	Strongly Presumed				1no Cable within Pipework Low Level		1			
44487	ACTIVE	P	P123-01-2/992	Disused Room - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				White emulsion to ceiling 8.82%			R609826		
25682	ACTIVE	P	P123-01-3/136	Lift Shaft - Station Building - Aldwych Disused Stn	Caulking	Asbestos	Surveyed – Not Detected				Caulking to Tunnel Ring FLanges					
25683	ACTIVE	P	P123-01-3/136	Lift Shaft - Station Building - Aldwych Disused Stn	Cable: Wrap	Asbestos	Surveyed – Not Detected				Cable wrap 0.5lm to bottom of shaft to wall by wooden access panel boarded up in old gate way	1				
44538	ACTIVE	P	P123-01-3/136	Lift Shaft - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				Black gloss to skirting on Lift Cars 1 & 2; 10.8%			R609826		
44537	ACTIVE	P	P123-01-3/136	Lift Shaft - Station Building - Aldwych Disused Stn	Lead/Leading	Lead Paint/Lead	Known				Green Gloss to Walls of Lift Cars 1& 2; 20.9%			R609826		
14404	ACTIVE	P	P123-01-3/201	Passage - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42269	ACTIVE	P	P123-01-3/201	Passage - Station Building - Aldwych Disused Stn	Gasket :Pipework	Asbestos	Presumed				Gasket to pipe work adjacent to vent equipment in spiral					
14405	ACTIVE	P	P123-01-3/202	Passage - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14406	ACTIVE	P	P123-01-3/203	Passage - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P123-01 - Station Building - Aldwych Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14407	ACTIVE	P	P123-01-3/261	Platform 2 - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25728	ACTIVE	P	P123-01-3/261	Platform 2 - Station Building - Aldwych Disused Stn	Westing house Boxes	Asbestos	Presumed				Redundant Westinghouse Box; in Disused Tunnel of Disused Platform 3/261		1			
25684	ACTIVE	P	P123-01-3/261	Platform 2 - Station Building - Aldwych Disused Stn	Caulking	Asbestos	Surveyed – Not Detected				Caulking between Tunnel Rings					
44107	ACTIVE	P	P123-01-3/261/FLR-01	Floor - 1 - Platform 2 - Station Building - Aldwych Disused Stn	Void	Asbestos	No Access: Presumed				No Access to Invert					Y
14408	ACTIVE	P	P123-01-3/601	Stairs: Linear - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14409	ACTIVE	P	P123-01-3/602	Stairs: Linear - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25685	ACTIVE	P	P123-01-3/636	Overbridge - Station Building - Aldwych Disused Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel doors on entrance to Overbridge					
14410	ACTIVE	P	P123-01-3/661	Switch Room - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25686	ACTIVE	P	P123-01-3/661	Switch Room - Station Building - Aldwych Disused Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Large Fuse Equipment - Asbestos Materials within		1			
14411	ACTIVE	P	P123-01-3/731	CER - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25688	ACTIVE	P	P123-01-3/731	CER - Station Building - Aldwych Disused Stn	Caulking	Asbestos	Surveyed – Not Detected				Caulking to Tunnel Flanges					
25687	ACTIVE	P	P123-01-3/731/FLR-01	Floor - 1 - CER - Station Building - Aldwych Disused Stn	Void	Asbestos	No Access: Presumed				Computer Flooring - No access beneath					Y
25690	ACTIVE	P	P123-01-3/731/WAL-001	Wall: Internal - 1 - CER - Station Building - Aldwych Disused Stn	Isolator Switches	Asbestos	Strongly Presumed				2no 60amp Switch Boxes - Asbestos materials within		2			
25689	ACTIVE	P	P123-01-3/731/WAL-001	Wall: Internal - 1 - CER - Station Building - Aldwych Disused Stn	Other Boarding	Asbestos	Presumed				Paxoline Board behind Electrical Equipment		1			
14412	ACTIVE	P	P123-01-3/732	Switch Room - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25691	ACTIVE	P	P123-01-3/732/FLR-01	Floor - 1 - Switch Room - Station Building - Aldwych Disused Stn	Void	Asbestos	No Access: Presumed				Computer Flooring - No Access Below					Y
14413	ACTIVE	P	P123-01-3/776	Fan Room - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



P123-01 - Station Building - Aldwych Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25732	ACTIVE	p	P123-01-3/792	Vent Shaft - Station Building - Aldwych Disused Stn		Asbestos	Surveyed – Not Detected				Caulking to Tunnel Rings					
25733	ACTIVE	p	P123-01-3/792/FLR-01	Floor - 1 - Vent Shaft - Station Building - Aldwych Disused Stn		Asbestos	Surveyed – Not Detected				0.5Lm Durasteel panel to bottom of shaft on floor opposite stairs/ ladder - NADIS, Durasteel debris <1m2 to bottom of shaft by rubbish pile - presume to be debris within rubbish and floor - Non asbestos;					
14414	ACTIVE	p	P123-01-3/982	Lobby - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14415	ACTIVE	p	P123-01-3/983	Passage - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14416	ACTIVE	p	P123-01-3/986	Disused Room - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25731	ACTIVE	p	P123-01-3/986	Disused Room - Station Building - Aldwych Disused Stn	Debris: Other	Asbestos	Known				Crocidolite Asbestos Residue below Painted areas to Area of Tunnel Rings up to 20metres from End Wall;	20				
44106	ACTIVE	p	P123-01-3/986	Disused Room - Station Building - Aldwych Disused Stn	Debris: Other	Asbestos	Known				Crocidolite asbestos residue in thread to nut and bolt hole Encapsulated 07/01/2013 approx. 15m from end wall					
25730	ACTIVE	p	P123-01-3/986	Disused Room - Station Building - Aldwych Disused Stn	Noise Reduction Equipment	Asbestos	Known				Crocidolite Debris to Sleeper Ends @ 11m, 13m, 14m, 17m from End Wall - Encapsulated					
25729	ACTIVE	p	P123-01-3/986	Disused Room - Station Building - Aldwych Disused Stn	Noise Reduction Equipment	Asbestos	Known				Asbestos Sacking - Chrysotile - Encapsulated; Part of Experimentl Noise Shelf; 0.3m2;	4				
44109	ACTIVE	p	P123-01-3/986	Disused Room - Station Building - Aldwych Disused Stn	Other Boarding	Asbestos	Presumed				Suspect Board Debris within ring pan - Tunnel Ring 90					
14417	ACTIVE	p	P123-01-4/261	Platform 1 - Single Line Local - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25735	ACTIVE	p	P123-01-4/261	Platform 1 - Single Line Local - Station Building - Aldwych Disused Stn	Caulking	Asbestos	Surveyed – Not Detected				Debris Caulking to Tunnel Rings					
25724	ACTIVE	p	P123-01-4/261	Platform 1 - Single Line Local - Station Building - Aldwych Disused Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse Box - Asbestos within; by CER 4/731		1			
25722	ACTIVE	p	P123-01-4/261	Platform 1 - Single Line Local - Station Building - Aldwych Disused Stn	Cable: Sheath	Asbestos	Strongly Presumed				Various Encapsulated Cables - Head Wall - Going to Invert via 4/731 and Track					
25734	ACTIVE	p	P123-01-4/261	Platform 1 - Single Line Local - Station Building - Aldwych Disused Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel end of Platform					



Hazardous Material Asset Register - Summary



P123-01 - Station Building - Aldwych Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42270	ACTIVE	P	P123-01-4/261	Platform 1 - Single Line Local - Station Building - Aldwych Disused Stn	Cable: Wrap	Asbestos	Presumed				Cable wrap to pipe to gutter adj to 4/662					
25723	ACTIVE	P	P123-01-4/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Aldwych Disused Stn	Gasket :Pipework	Asbestos	Presumed				Gaskets within Bolted Joints to Capped off Pipework - 2no		2			
44108	ACTIVE	P	P123-01-4/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Aldwych Disused Stn	Void	Asbestos	No Access: Presumed				No Access to Invert - Known Asbestos Cables within				Y	
14418	ACTIVE	P	P123-01-4/661	Switch Room - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25700	ACTIVE	P	P123-01-4/661	Switch Room - Station Building - Aldwych Disused Stn	Isolator Switches	Asbestos	Strongly Presumed				2no 60amp Switch Boxes and bus bar - Asbestos Materials within		2			
14419	ACTIVE	P	P123-01-4/662	Switch Room - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25702	ACTIVE	P	P123-01-4/662	Switch Room - Station Building - Aldwych Disused Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Boxes - Asbestos Materials within		1			
25701	ACTIVE	P	P123-01-4/662	Switch Room - Station Building - Aldwych Disused Stn	Isolator Switches	Asbestos	Strongly Presumed				5no Switch Boxes - Asbestos materials within; 1x 60amp & 200amp, 3x 100amp;		5			
14420	ACTIVE	P	P123-01-4/731	CER - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25699	ACTIVE	P	P123-01-4/731	CER - Station Building - Aldwych Disused Stn	Cable: Sheath	Asbestos	Strongly Presumed				Various Sheathed Cables going to Invert					
14421	ACTIVE	P	P123-01-A/131	LMR - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25727	ACTIVE	P	P123-01-A/131/FLR-01	Floor - 1 - LMR - Station Building - Aldwych Disused Stn	Gasket :Pipework	Asbestos	Presumed				Gaskets to Flanged Joints on Pipework		1			
14422	ACTIVE	P	P123-01-A/132	LMR - Station Building - Aldwych Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25696	ACTIVE	P	P123-01-A/132	LMR - Station Building - Aldwych Disused Stn	Cable: Sheath	Asbestos	Strongly Presumed				Various Sheathed Cables behind / within the Lift Isolators, these cables run into conduits on the wall and therefore any conduit throughout the room should be presumed to contain asbestos sheathed cables.					
25692	ACTIVE	P	P123-01-A/132	LMR - Station Building - Aldwych Disused Stn	Boarding: AIB	Asbestos	Known				Panel on Redundant Lift Isolators		1	R19873		
25726	ACTIVE	P	P123-01-A/132	LMR - Station Building - Aldwych Disused Stn	Other Boarding	Asbestos	Presumed				Paxoline Board backing to 4no Lift Switches		1			



Hazardous Material Asset Register - Summary



P123-01 - Station Building - Aldwych Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25695	ACTIVE	P	P123-01-A/132	LMR - Station Building - Aldwych Disused Stn	Control Panels	Asbestos	Known				4no Arc Chutes to Redundant Lift Isolators		4			
42271	ACTIVE	P	P123-01-A/132	LMR - Station Building - Aldwych Disused Stn	Control Panels	Asbestos	Presumed				Lift Equipment Boxes - Components within		2			
25697	ACTIVE	P	P123-01-A/132	LMR - Station Building - Aldwych Disused Stn	Control Panels	Asbestos	Strongly Presumed				Lift Controllers - 2no - Arc Chutes and Cables within		2			
25725	ACTIVE	P	P123-01-A/132/FLR-01	Floor - 1 - LMR - Station Building - Aldwych Disused Stn	Westing house Boxes	Asbestos	Strongly Presumed				4no Westinghouse Boxes on Lift Machinery (which may in turn contain other various asbestos containing components, not readily evident until dismantling occurs)		4			

W012-01 - Station Building - Down Street Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14590	ACTIVE	P	W012-01-1/236	Passage - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14591	ACTIVE	P	W012-01-1/451	Tenancy - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14592	ACTIVE	P	W012-01-1/576	Stairs: Linear - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14593	ACTIVE	P	W012-01-1/776	Fan Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14594	ACTIVE	P	W012-01-1/951	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14595	ACTIVE	P	W012-01-2/236	Passage - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14596	ACTIVE	P	W012-01-2/576	Stairs: Spiral - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14597	ACTIVE	P	W012-01-2/661	Switch Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14598	ACTIVE	P	W012-01-2/951	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14599	ACTIVE	P	W012-01-2/986	Switch Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



W012-01 - Station Building - Down Street Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14600	ACTIVE	P	W012-01-3/905	Store - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14601	ACTIVE	P	W012-01-3/951	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14602	ACTIVE	P	W012-01-3/952	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14603	ACTIVE	P	W012-01-3/953	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14604	ACTIVE	P	W012-01-3/954	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14605	ACTIVE	P	W012-01-3/955	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14606	ACTIVE	P	W012-01-3/956	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14607	ACTIVE	P	W012-01-3/957	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14608	ACTIVE	P	W012-01-3/971	Passage - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14609	ACTIVE	P	W012-01-3/981	Stairs: Linear - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14610	ACTIVE	P	W012-01-3/982	Stairs: Linear - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14611	ACTIVE	P	W012-01-4/081	Lobby - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14612	ACTIVE	P	W012-01-4/236	Passage - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14613	ACTIVE	P	W012-01-4/237	Passage - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14614	ACTIVE	P	W012-01-4/576	Stairs: Linear - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



W012-01 - Station Building - Down Street Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14615	ACTIVE	P	W012-01-4/577	Stairs: Linear - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14616	ACTIVE	P	W012-01-4/636	Passage - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14617	ACTIVE	P	W012-01-4/637	Passage - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14618	ACTIVE	P	W012-01-4/771	Fan Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14619	ACTIVE	P	W012-01-4/986	Void - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14620	ACTIVE	P	W012-01-5/081	Lobby - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14621	ACTIVE	P	W012-01-5/236	Passage - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14622	ACTIVE	P	W012-01-5/237	Passage - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14623	ACTIVE	P	W012-01-5/238	Passage - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14624	ACTIVE	P	W012-01-5/240	Passage - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14625	ACTIVE	P	W012-01-5/241	Passage - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14626	ACTIVE	P	W012-01-5/242	Passage - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14627	ACTIVE	P	W012-01-5/244	Passage - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14628	ACTIVE	P	W012-01-5/245	Passage - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14629	ACTIVE	P	W012-01-5/246	Passage - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



W012-01 - Station Building - Down Street Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14630	ACTIVE	P	W012-01-5/247	Passage - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14631	ACTIVE	P	W012-01-5/371	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14632	ACTIVE	P	W012-01-5/372	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14633	ACTIVE	P	W012-01-5/373	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14634	ACTIVE	P	W012-01-5/374	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14635	ACTIVE	P	W012-01-5/375	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14636	ACTIVE	P	W012-01-5/376	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14637	ACTIVE	P	W012-01-5/560	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14638	ACTIVE	P	W012-01-5/661	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14639	ACTIVE	P	W012-01-5/706	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14640	ACTIVE	P	W012-01-5/707	IMR - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14641	ACTIVE	P	W012-01-5/901	Store - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14642	ACTIVE	P	W012-01-5/902	Store - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14643	ACTIVE	P	W012-01-5/903	Store - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14644	ACTIVE	P	W012-01-5/904	Store - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



W012-01 - Station Building - Down Street Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14645	ACTIVE	P	W012-01-5/907	Store - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14646	ACTIVE	P	W012-01-5/908	Store - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14647	ACTIVE	P	W012-01-5/951	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14648	ACTIVE	P	W012-01-5/952	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14649	ACTIVE	P	W012-01-5/953	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14650	ACTIVE	P	W012-01-5/954	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14651	ACTIVE	P	W012-01-5/955	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14652	ACTIVE	P	W012-01-5/956	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14653	ACTIVE	P	W012-01-5/957	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14654	ACTIVE	P	W012-01-5/958	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14655	ACTIVE	P	W012-01-5/959	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14656	ACTIVE	P	W012-01-5/961	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14657	ACTIVE	P	W012-01-5/962	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14658	ACTIVE	P	W012-01-5/963	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14659	ACTIVE	P	W012-01-5/964	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



W012-01 - Station Building - Down Street Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14660	ACTIVE	p	W012-01-5/965	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14661	ACTIVE	p	W012-01-5/966	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14662	ACTIVE	p	W012-01-5/967	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14663	ACTIVE	p	W012-01-5/969	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14664	ACTIVE	p	W012-01-5/970	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14665	ACTIVE	p	W012-01-5/971	Disused Room - Station Building - Down Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

W013-01 - Station Building - Brompton Road Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14666	ACTIVE	p	W013-01-1/576	Stairs: Linear - Station Building - Brompton Road Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14667	ACTIVE	p	W013-01-2/776	Plant Room - Station Building - Brompton Road Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14668	ACTIVE	p	W013-01-3/236	Passage - Station Building - Brompton Road Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14669	ACTIVE	p	W013-01-3/237	Passage - Station Building - Brompton Road Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14670	ACTIVE	p	W013-01-3/576	Stairs: Linear - Station Building - Brompton Road Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14671	ACTIVE	p	W013-01-3/577	Stairs: Linear - Station Building - Brompton Road Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14672	ACTIVE	p	W013-01-4/261	Platform 1 - Eastbound Local - Piccadilly Line - Station Building - Brompton Road Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



W013-01 - Station Building - Brompton Road Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14673	ACTIVE	p	W013-01-4/262	Platform 2 - Westbound Local - Piccadilly Line - Station Building - Brompton Road Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

W044-01 - Station Building - Osterley Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14674	ACTIVE	p	W044-01-2/261	Platform 1 - Westbound Local - Station Building - Osterley Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14675	ACTIVE	p	W044-01-2/262	Platform 2 - Eastbound Local - Station Building - Osterley Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

X107-01 - Office Building - Frank Pick House

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14691	ACTIVE	p	X107-01-1/041	Mess Room - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14692	ACTIVE	p	X107-01-1/047	Kitchen - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14693	ACTIVE	p	X107-01-1/048	Kitchen - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14694	ACTIVE	p	X107-01-1/081	Lobby - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14695	ACTIVE	p	X107-01-1/082	Lobby - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14696	ACTIVE	p	X107-01-1/083	Lobby - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14697	ACTIVE	p	X107-01-1/084	Lobby - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14698	ACTIVE	p	X107-01-1/236	Passage - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14699	ACTIVE	p	X107-01-1/316	Locker Room - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



X107-01 - Office Building - Frank Pick House

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14700	ACTIVE	p	X107-01-1/317	Locker Room - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14701	ACTIVE	p	X107-01-1/411	Store - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14702	ACTIVE	p	X107-01-1/412	Store - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14703	ACTIVE	p	X107-01-1/413	Store - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14704	ACTIVE	p	X107-01-1/414	Store - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14705	ACTIVE	p	X107-01-1/416	Toilet: Female - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14706	ACTIVE	p	X107-01-1/417	Toilet - Shower Room - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14707	ACTIVE	p	X107-01-1/418	Shower Room - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14708	ACTIVE	p	X107-01-1/419	Toilet: Male - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14709	ACTIVE	p	X107-01-1/420	Toilet: Female - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14710	ACTIVE	p	X107-01-1/576	Stairs: Linear - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14711	ACTIVE	p	X107-01-1/577	Stairs: Linear - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14712	ACTIVE	p	X107-01-1/761	Laboratory - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14713	ACTIVE	p	X107-01-1/801	Office - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14714	ACTIVE	p	X107-01-1/802	Office - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



X107-01 - Office Building - Frank Pick House

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14715	ACTIVE	p	X107-01-1/803	Workshop - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14716	ACTIVE	p	X107-01-1/804	Office - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14717	ACTIVE	p	X107-01-1/805	Office - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14718	ACTIVE	p	X107-01-1/806	Office - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14719	ACTIVE	p	X107-01-1/807	Office - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14720	ACTIVE	p	X107-01-1/808	First Aid Room - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14721	ACTIVE	p	X107-01-A/047	Kitchen - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14722	ACTIVE	p	X107-01-A/048	Kitchen - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14723	ACTIVE	p	X107-01-A/081	Lobby - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14724	ACTIVE	p	X107-01-A/416	Toilet: Unisex - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14725	ACTIVE	p	X107-01-A/731	Plant Room - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14726	ACTIVE	p	X107-01-A/732	Plant Room - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14727	ACTIVE	p	X107-01-A/733	Plant Room - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14728	ACTIVE	p	X107-01-A/734	Plant Room - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14729	ACTIVE	p	X107-01-A/735	Plant Room - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



X107-01 - Office Building - Frank Pick House

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14730	ACTIVE	P	X107-01-A/736	Plant Room - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14731	ACTIVE	P	X107-01-A/737	Plant Room - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14732	ACTIVE	P	X107-01-A/801	Office - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14733	ACTIVE	P	X107-01-A/802	Office - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14734	ACTIVE	P	X107-01-A/803	Office - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14735	ACTIVE	P	X107-01-A/804	Office - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14736	ACTIVE	P	X107-01-A/805	Store - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14737	ACTIVE	P	X107-01-B/771	Plant Room - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

X107-02 - Office Building - Frank Pick House

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14738	ACTIVE	P	X107-02-1/316	Locker Room - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14739	ACTIVE	P	X107-02-1/317	Cupboard - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14740	ACTIVE	P	X107-02-1/416	Toilet: Unisex - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14741	ACTIVE	P	X107-02-1/417	Shower Room - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14742	ACTIVE	P	X107-02-1/418	Toilet: Female - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



X107-03 - Office Building - Frank Pick House

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14743	ACTIVE	P	X107-03-1/371	Store - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14744	ACTIVE	P	X107-03-1/372	Store - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14745	ACTIVE	P	X107-03-1/373	Store - Office Building - Frank Pick House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

X111-01 - Office Complex - 139 Long Acre

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14746	ACTIVE	P	X111-01-1/576	Stairs: Linear - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14747	ACTIVE	P	X111-01-1/577	Stairs: Linear - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14748	ACTIVE	P	X111-01-A/516	Locker Room - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14749	ACTIVE	P	X111-01-A/731	CER - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14750	ACTIVE	P	X111-01-A/732	CER - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14751	ACTIVE	P	X111-01-A/733	CER - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14753	ACTIVE	P	X111-01-A/801	Disused - Disused Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14754	ACTIVE	P	X111-01-B/081	Lobby - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14755	ACTIVE	P	X111-01-B/331	Mess Room - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14756	ACTIVE	P	X111-01-B/416	Toilet: Unisex - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



X111-01 - Office Complex - 139 Long Acre

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14757	ACTIVE	P	X111-01-D/236	Passage - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14758	ACTIVE	P	X111-01-D/237	Passage - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14759	ACTIVE	P	X111-01-D/416	Toilet: Unisex - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14760	ACTIVE	P	X111-01-D/801	Disused - Disused Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14761	ACTIVE	P	X111-01-D/802	Disused - Disused Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14762	ACTIVE	P	X111-01-D/803	Disused - Disused Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14763	ACTIVE	P	X111-01-D/804	Disused - Disused Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14764	ACTIVE	P	X111-01-E/081	Lobby - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14765	ACTIVE	P	X111-01-E/236	Passage - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14766	ACTIVE	P	X111-01-E/237	Passage - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14767	ACTIVE	P	X111-01-E/238	Passage - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14768	ACTIVE	P	X111-01-E/239	Passage - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14769	ACTIVE	P	X111-01-E/331	Mess Room - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14770	ACTIVE	P	X111-01-E/332	Mess Room - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14771	ACTIVE	P	X111-01-E/406	Store - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



X111-01 - Office Complex - 139 Long Acre

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14772	ACTIVE	P	X111-01-E/416	Toilet: Unisex - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14773	ACTIVE	P	X111-01-E/417	Toilet: Unisex - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14774	ACTIVE	P	X111-01-E/731	Equipment Room - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14775	ACTIVE	P	X111-01-E/732	Disused - Disused Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14776	ACTIVE	P	X111-01-E/801	Disused - Disused Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14777	ACTIVE	P	X111-01-E/802	Disused - Disused Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14778	ACTIVE	P	X111-01-E/803	Disused - Disused Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14779	ACTIVE	P	X111-01-E/804	Disused - Disused Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14780	ACTIVE	P	X111-01-E/805	Disused - Disused Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14781	ACTIVE	P	X111-01-E/806	Disused - Disused Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14782	ACTIVE	P	X111-01-F/131	LMR - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14783	ACTIVE	P	X111-01-F/236	Passage - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14784	ACTIVE	P	X111-01-F/237	Passage - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14785	ACTIVE	P	X111-01-F/316	Locker Room - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14786	ACTIVE	P	X111-01-F/331	Mess Room - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



X111-01 - Office Complex - 139 Long Acre

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14787	ACTIVE	P	X111-01-F/416	Toilet: Unisex - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14788	ACTIVE	P	X111-01-F/731	Equipment Room - Office Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14789	ACTIVE	P	X111-01-F/801	Disused - Disused Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14790	ACTIVE	P	X111-01-F/802	Disused - Disused Complex - 139 Long Acre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

X148-01 - Ash House - Arnos Grove To Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14885	ACTIVE	P	X148-01-1/081	Lobby - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14886	ACTIVE	P	X148-01-1/083	Lobby - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14887	ACTIVE	P	X148-01-1/084	Lobby - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14888	ACTIVE	P	X148-01-1/236	Passage - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14889	ACTIVE	P	X148-01-1/237	Passage - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14890	ACTIVE	P	X148-01-1/238	Passage - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14891	ACTIVE	P	X148-01-1/239	Passage - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14892	ACTIVE	P	X148-01-1/291	Office - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14893	ACTIVE	P	X148-01-1/316	Locker Room - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



X148-01 - Ash House - Arnos Grove To Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14894	ACTIVE	p	X148-01-1/317	Cleaners Room - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14895	ACTIVE	p	X148-01-1/331	Mess Room - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14896	ACTIVE	p	X148-01-1/332	Mess Room - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14897	ACTIVE	p	X148-01-1/333	Mess Room - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14898	ACTIVE	p	X148-01-1/351	Mess Room - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14899	ACTIVE	p	X148-01-1/353	Mess Room - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14900	ACTIVE	p	X148-01-1/366	Office - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14901	ACTIVE	p	X148-01-1/406	Kitchen - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14902	ACTIVE	p	X148-01-1/411	Store - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14903	ACTIVE	p	X148-01-1/413	Office - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14904	ACTIVE	p	X148-01-1/414	Store - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14905	ACTIVE	p	X148-01-1/416	Toilet - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14906	ACTIVE	p	X148-01-1/417	Toilet: Unisex - Ash House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14907	ACTIVE	p	X148-01-1/418	Shower Room - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14908	ACTIVE	p	X148-01-1/531	Office - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



X148-01 - Ash House - Arnos Grove To Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14909	ACTIVE	p	X148-01-1/662	Switch Cupboard - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14910	ACTIVE	p	X148-01-1/731	CER - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14911	ACTIVE	p	X148-01-1/732	CER - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14912	ACTIVE	p	X148-01-1/751	Office - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14913	ACTIVE	p	X148-01-1/761	Equipment Room - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14914	ACTIVE	p	X148-01-1/776	Equipment Room - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14915	ACTIVE	p	X148-01-1/801	Workshop - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14916	ACTIVE	p	X148-01-1/802	First Aid Room - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14917	ACTIVE	p	X148-01-1/803	UTS Technicians Office - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14918	ACTIVE	p	X148-01-1/804	Office - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14919	ACTIVE	p	X148-01-A/047	Kitchen - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14920	ACTIVE	p	X148-01-A/081	Lobby - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14921	ACTIVE	p	X148-01-A/085	Lobby - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14922	ACTIVE	p	X148-01-A/236	Passage - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14923	ACTIVE	p	X148-01-A/237	Passage - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



X148-01 - Ash House - Arnos Grove To Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14924	ACTIVE	p	X148-01-A/238	Passage - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14925	ACTIVE	p	X148-01-A/306	Train Ops Manager Office - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14926	ACTIVE	p	X148-01-A/316	Locker Room - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14927	ACTIVE	p	X148-01-A/318	Locker Room - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14928	ACTIVE	p	X148-01-A/405	Store - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14929	ACTIVE	p	X148-01-A/406	Lobby - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14930	ACTIVE	p	X148-01-A/416	Toilet: Male - Ash House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14931	ACTIVE	p	X148-01-A/417	Shower Room - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14932	ACTIVE	p	X148-01-A/578	Stairs: Linear - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14933	ACTIVE	p	X148-01-A/661	Switch Cupboard - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14934	ACTIVE	p	X148-01-A/801	Office - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14935	ACTIVE	p	X148-01-A/802	Office - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14936	ACTIVE	p	X148-01-A/803	Interview Room - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14937	ACTIVE	p	X148-01-A/805	Admin Office - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14938	ACTIVE	p	X148-01-A/806	Office - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



X148-01 - Ash House - Arnos Grove To Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14939	ACTIVE	P	X148-01-A/901	Fitness Room - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14940	ACTIVE	P	X148-01-A/902	Disused Room - Ash House - Arnos Grove To Bounds Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

X149-01 - Bollo House - Acton Town To Turnham Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14941	ACTIVE	P	X149-01-1/081	Lobby - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14942	ACTIVE	P	X149-01-1/082	Lobby - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14943	ACTIVE	P	X149-01-1/083	Lobby - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14944	ACTIVE	P	X149-01-1/236	Passage - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14945	ACTIVE	P	X149-01-1/237	Passage - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14946	ACTIVE	P	X149-01-1/238	Passage - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14947	ACTIVE	P	X149-01-1/239	Passage - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14948	ACTIVE	P	X149-01-1/240	Passage - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14949	ACTIVE	P	X149-01-1/306	Office - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14950	ACTIVE	P	X149-01-1/307	Mess Room - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14951	ACTIVE	P	X149-01-1/331	Mess Room - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



X149-01 - Bollo House - Acton Town To Turnham Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14952	ACTIVE	p	X149-01-1/371	Store - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14953	ACTIVE	p	X149-01-1/372	Store - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14954	ACTIVE	p	X149-01-1/411	Store - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14955	ACTIVE	p	X149-01-1/412	Store - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14956	ACTIVE	p	X149-01-1/413	Store - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14957	ACTIVE	p	X149-01-1/414	Store - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14958	ACTIVE	p	X149-01-1/416	Toilet: Male - Bollo House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14959	ACTIVE	p	X149-01-1/417	Toilet: Female - Bollo House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14960	ACTIVE	p	X149-01-1/436	Office - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14961	ACTIVE	p	X149-01-1/481	Workshop - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14962	ACTIVE	p	X149-01-1/531	Mess Room - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14963	ACTIVE	p	X149-01-1/571	CER - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14964	ACTIVE	p	X149-01-1/572	Locker Room - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14965	ACTIVE	p	X149-01-1/665	Switch Room - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14966	ACTIVE	p	X149-01-1/771	Pump Room - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



X149-01 - Bollo House - Acton Town To Turnham Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14967	ACTIVE	p	X149-01-1/801	Office - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14968	ACTIVE	p	X149-01-1/903	Office - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14969	ACTIVE	p	X149-01-1/904	Store - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14970	ACTIVE	p	X149-01-1/905	Lobby - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14971	ACTIVE	p	X149-01-1/906	Switch Room - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14972	ACTIVE	p	X149-01-A/081	Lobby - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14973	ACTIVE	p	X149-01-A/082	Lobby - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14974	ACTIVE	p	X149-01-A/236	Passage - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14975	ACTIVE	p	X149-01-A/237	Passage - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14976	ACTIVE	p	X149-01-A/238	Passage - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14977	ACTIVE	p	X149-01-A/239	Passage - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14978	ACTIVE	p	X149-01-A/316	Locker Room - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14979	ACTIVE	p	X149-01-A/317	Locker Room - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14980	ACTIVE	p	X149-01-A/319	Locker Room - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14981	ACTIVE	p	X149-01-A/331	Mess Room - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



X149-01 - Bollo House - Acton Town To Turnham Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14982	ACTIVE	p	X149-01-A/332	Mess Room - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14983	ACTIVE	p	X149-01-A/333	Mess Room - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14984	ACTIVE	p	X149-01-A/334	Kitchen - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14985	ACTIVE	p	X149-01-A/406	Store - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14986	ACTIVE	p	X149-01-A/411	Store - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14987	ACTIVE	p	X149-01-A/412	Store - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14988	ACTIVE	p	X149-01-A/413	Store - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14989	ACTIVE	p	X149-01-A/416	Toilet: Male - Bollo House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14990	ACTIVE	p	X149-01-A/417	Toilet: Female - Bollo House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14991	ACTIVE	p	X149-01-A/418	Shower Room - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14992	ACTIVE	p	X149-01-A/419	Shower Room - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14993	ACTIVE	p	X149-01-A/420	Toilet: Unisex - Bollo House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14994	ACTIVE	p	X149-01-A/421	Shower Room - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14995	ACTIVE	p	X149-01-A/422	Shower Room - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14996	ACTIVE	p	X149-01-A/423	Toilet: Unisex - Bollo House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



X149-01 - Bollo House - Acton Town To Turnham Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14997	ACTIVE	p	X149-01-A/481	Mess Room - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14998	ACTIVE	p	X149-01-A/578	Stairs: Linear - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14999	ACTIVE	p	X149-01-A/661	Switch Cupboard - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15000	ACTIVE	p	X149-01-A/662	Switch Cupboard - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15001	ACTIVE	p	X149-01-A/801	Office - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15002	ACTIVE	p	X149-01-A/802	Office - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15003	ACTIVE	p	X149-01-A/803	Office - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15004	ACTIVE	p	X149-01-A/902	Locker Room - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15005	ACTIVE	p	X149-01-B/047	Kitchen - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15006	ACTIVE	p	X149-01-B/081	Lobby - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15007	ACTIVE	p	X149-01-B/082	Plant Room - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15008	ACTIVE	p	X149-01-B/236	Passage - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15009	ACTIVE	p	X149-01-B/237	Passage - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15010	ACTIVE	p	X149-01-B/406	Store - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15011	ACTIVE	p	X149-01-B/416	Toilet: Male - Bollo House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



X149-01 - Bollo House - Acton Town To Turnham Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15012	ACTIVE	p	X149-01-B/417	Shower Room - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15013	ACTIVE	p	X149-01-B/418	Toilet: Female - Bollo House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15014	ACTIVE	p	X149-01-B/576	Stairs: Linear - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15015	ACTIVE	p	X149-01-B/631	Stairs: Spiral - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15016	ACTIVE	p	X149-01-B/661	Switch Cupboard - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15017	ACTIVE	p	X149-01-B/731	CER - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15018	ACTIVE	p	X149-01-B/761	Plant Room - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15019	ACTIVE	p	X149-01-B/786	Service Riser - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15020	ACTIVE	p	X149-01-B/801	Office - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15021	ACTIVE	p	X149-01-B/802	Office - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15022	ACTIVE	p	X149-01-B/803	Office - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15023	ACTIVE	p	X149-01-B/804	Office - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15024	ACTIVE	p	X149-01-B/805	Office - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15025	ACTIVE	p	X149-01-B/806	Store - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15026	ACTIVE	p	X149-01-B/807	Office - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



X149-01 - Bollo House - Acton Town To Turnham Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15027	ACTIVE	p	X149-01-B/808	Office - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15028	ACTIVE	p	X149-01-B/809	Office - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15029	ACTIVE	p	X149-01-B/901	Office - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15030	ACTIVE	p	X149-01-B/902	Office - Bollo House - Acton Town To Turnham Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

DD216-01 - Depot Building - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5968	ACTIVE	p	DD216-01-1/088	Lobby - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5969	ACTIVE	p	DD216-01-1/090	Lobby - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5970	ACTIVE	p	DD216-01-1/091	Lobby - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5971	ACTIVE	p	DD216-01-1/092	Lobby - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5972	ACTIVE	p	DD216-01-1/236	Passage - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5973	ACTIVE	p	DD216-01-1/316	Locker Room - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53920	ACTIVE	p	DD216-01-1/316	Locker Room - Depot Building - Northfields Depot	Cable Duct: Other	Asbestos	Strongly Presumed				Lining to Cable Entry to Wall 2					
5974	ACTIVE	p	DD216-01-1/317	Plant Room - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5975	ACTIVE	p	DD216-01-1/331	Mess Room - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



DD216-01 - Depot Building - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5976	ACTIVE	p	DD216-01-1/406	Store - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5977	ACTIVE	p	DD216-01-1/407	Cleaners Room - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53928	ACTIVE	p	DD216-01-1/407	Cleaners Room - Depot Building - Northfields Depot	LUL Heaters	Asbestos	Known				Lining within brown LTB heater unit - Loose to Wall 1		1	R713903		
5978	ACTIVE	p	DD216-01-1/410	Store - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5979	ACTIVE	p	DD216-01-1/411	Store - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5980	ACTIVE	p	DD216-01-1/412	Store - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5981	ACTIVE	p	DD216-01-1/413	Store - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5982	ACTIVE	p	DD216-01-1/414	Wash Room - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5983	ACTIVE	p	DD216-01-1/415	Store - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5984	ACTIVE	p	DD216-01-1/416	Toilet: Male - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53969	ACTIVE	p	DD216-01-1/416	Toilet: Male - Depot Building - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				Red Gloss Paint to Door 1.81% 320µm White Gloss to Door Frame 1.1% 450µm NB Door Frame not noted on Report R713904			R413376		
5985	ACTIVE	p	DD216-01-1/417	Toilet: Female - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5986	ACTIVE	p	DD216-01-1/418	Toilet: Male - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5987	ACTIVE	p	DD216-01-1/419	Shower Room - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



DD216-01 - Depot Building - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
5988	ACTIVE	p	DD216-01-1/561	Workshop - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53974	ACTIVE	p	DD216-01-1/561	Workshop - Depot Building - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				White Gloss Paint to Ceiling Trusses - 10.7% 680µm			R413776		
53960	ACTIVE	p	DD216-01-1/561	Workshop - Depot Building - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				Red Gloss to Door - 1.84% 470µm White Gloss to Door Frame - 2.02% 230µm			R413376		
53964	ACTIVE	p	DD216-01-1/561	Workshop - Depot Building - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				Drainage pipe by doors to maintenance shed 20 & 21 Grey Gloss 12.3% 330µm NB Not noted on report R713904			R413376		
53963	ACTIVE	p	DD216-01-1/561	Workshop - Depot Building - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				Cream Gloss to Column near window facing sheds 20 & 21 6.96% 420µm NB Not noted on Report R713904			R413376		
53962	ACTIVE	p	DD216-01-1/561	Workshop - Depot Building - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				Red Gloss Paint to Walkway - 3.36% 290µm NB Not noted on R713904			R413376		
53961	ACTIVE	p	DD216-01-1/561	Workshop - Depot Building - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				Pipework Cream Gloss - Upper Layer - 1.85% 420µm Grey Gross - Lower Layer - 2.3% 570µm NB Not noted on R713904			R413376		
53976	ACTIVE	p	DD216-01-1/561	Workshop - Depot Building - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				Light Brown Gloss Paint to Pipework - Ceiling Area - 7.72% 210µm NB Not noted on report R713904			R413776		
53975	ACTIVE	p	DD216-01-1/561	Workshop - Depot Building - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				White Gloss Paint to Wooden Ceiling Panels 1.95% 470µm NB Not noted on Report R713904			R413376		
5989	ACTIVE	p	DD216-01-1/562	Workshop - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53957	ACTIVE	p	DD216-01-1/562	Workshop - Depot Building - Northfields Depot	Rope Gaskets	Asbestos	Known				Gaskets / Washers to Floor Covers throughout Main Shed Gaskets remain where covers welded shut. See HM01195			R711676		
53959	ACTIVE	p	DD216-01-1/562	Workshop - Depot Building - Northfields Depot	Boarding: Cement	Asbestos	Known				Residual asbestos cement remains at the wall junction between the lifting shop and the wash road 19 at both the east and west ends - Chrysotile & Amosite NOTED on Forest Environmental Completion Cert ES2191a			ES2191a		
43608	ACTIVE	p	DD216-01-1/562	Workshop - Depot Building - Northfields Depot	Lagging	Asbestos	Sampled – Not Detected				Pipe lagging & insulation			R508961	N	N



Hazardous Material Asset Register - Summary



DD216-01 - Depot Building - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
53958	ACTIVE	P	DD216-01-1/562	Workshop - Depot Building - Northfields Depot	Debris: Cement	Asbestos	Known				Asbestos within Soils to Ground between Main shed and Depot Roads Surface pick completed by Econ HM00558-001 Additional debris may be present of further excavation is required. EXTERNAL			R724726		
53932	ACTIVE	P	DD216-01-1/562	Workshop - Depot Building - Northfields Depot	Paper Asbestos	Asbestos	Known				Anti Condensation Paper Lining to Pipework under MMMF insulation to pipework by Rd19 east end - Road 19-11			R713903		
53933	ACTIVE	P	DD216-01-1/562	Workshop - Depot Building - Northfields Depot	Gasket :Pipework	Asbestos	Known				CAF Gaskets to joints on Large Pipework Road 19 East End			R713903		
53921	INACTIVE	P	DD216-01-1/562	Workshop - Depot Building - Northfields Depot	Boarding: Cement	Asbestos	Known				Residual asbestos cement remains at the wall junction between the lifting shop and the wash road 19 at both the east and west ends - Chrysotile & Amosite - HIGH LEVEL					
53970	ACTIVE	P	DD216-01-1/562	Workshop - Depot Building - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				White Gloss Paint to Window 5.61% 190µm			R413376		
53977	ACTIVE	P	DD216-01-1/562	Workshop - Depot Building - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				White Gloss Paint to Shutters Columns 28.8% 640µm (Multi-layered white on blue on red) Cross Beams 22.4% 620µm - NB Not noted on report R713904 Steel Beam over Roller Shutters - 2.37% 90µm			R413776		
53973	ACTIVE	P	DD216-01-1/562	Workshop - Depot Building - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				Grey Gloss Paint to Gasket over Water Tank Roof - Roof Area 18.1% 460µm NB Not noted on Report R713904			R413376		
53979	ACTIVE	P	DD216-01-1/562	Workshop - Depot Building - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				Black Gloss Paint to Steal Beam - 10.1% 130µm			R713904		
53972	ACTIVE	P	DD216-01-1/562	Workshop - Depot Building - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				White Gloss Paint to Windows - Roof Area - Over Maintenance Shed External 13.4% 250µm - Internal 1.28% 220µm NB Not noted on report R713904			R413376		
5990	ACTIVE	P	DD216-01-1/563	Workshop - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53956	ACTIVE	P	DD216-01-1/563	Workshop - Depot Building - Northfields Depot	Gasket :Pipework	Asbestos	Presumed				Gaskets to flanges to pipework within floor pit between Roads 20 & 21 - 2no Visible		2	R713903		
53951	ACTIVE	P	DD216-01-1/563	Workshop - Depot Building - Northfields Depot	Cable Ducts: Bitumen	Asbestos	Known				Bitumen Cable Ducts - 3no Visible - Est up to 8no to walls in Cable Pit		8	R713903		
53955	ACTIVE	P	DD216-01-1/563	Workshop - Depot Building - Northfields Depot	Gasket :Pipework	Asbestos	Known				Gaskets to Pipe Flanges to gas pipework along Road 21 - throughout			R713903		
53954	ACTIVE	P	DD216-01-1/563	Workshop - Depot Building - Northfields Depot	Cable Ducts: Bitumen	Asbestos	Known				Bitumen Cable Ducts >10no to walls within Pit by Switch Room 1/665		10	R713903		



Hazardous Material Asset Register - Summary



DD216-01 - Depot Building - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
53950	ACTIVE	p	DD216-01-1/563	Workshop - Depot Building - Northfields Depot	Gasket :Pipework	Asbestos	Known				Pipe Gaskets 4no Visible - to flanged joints above roller shutters at East End		4	R713903		
53968	ACTIVE	p	DD216-01-1/563	Workshop - Depot Building - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				Grey Gloss Paint Larger Sized Bricks of Lower Walls 9.76% 240µm Smaller Sized Bricks of Lower Walls 0.96% 310µm on report R713904 Lower wall by door to workshop 1.48% 140µm			R413776		
53967	ACTIVE	p	DD216-01-1/563	Workshop - Depot Building - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				Window frame outside workshop 1/516 in maintenance shed area. Has red lower paint layer. 2.29% 300µm			R413376		
53966	ACTIVE	p	DD216-01-1/563	Workshop - Depot Building - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				Lower wall outside DDM office seating area - 4.46% 470µm NB Not noted on report R713904			R413776		
53965	ACTIVE	p	DD216-01-1/563	Workshop - Depot Building - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				Dark Grey Gloss to Columns Report R413376 Vertical Column No 1 - 3.73% 430µm Vertical Column No21 - 2.50% 380µm Vertical Column No 9 from door to 1/562 - 6.50% 440µm Report R713904 Column to Door to Loading Bay 1/905 - 5.54% 300µm			R413776		
5991	ACTIVE	p	DD216-01-1/564	Workshop - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5992	ACTIVE	p	DD216-01-1/571	Store Room - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5993	ACTIVE	p	DD216-01-1/572	Store Room - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5994	ACTIVE	p	DD216-01-1/573	Store Room - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5995	ACTIVE	p	DD216-01-1/574	Office - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5996	ACTIVE	p	DD216-01-1/661	Switch Room - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5997	ACTIVE	p	DD216-01-1/662	Switch Room - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



DD216-01 - Depot Building - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
53927	ACTIVE	p	DD216-01-1/662	Switch Room - Depot Building - Northfields Depot	Cable Ducts: Cement	Asbestos	Presumed				6no Cable Ducts - Within pit - further investigation required with an LARC to see if ducts present within concrete slab		6	R713903		
5998	ACTIVE	p	DD216-01-1/664	Switch Room - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
5999	ACTIVE	p	DD216-01-1/665	Switch Room - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6000	ACTIVE	p	DD216-01-1/731	CER - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6001	ACTIVE	p	DD216-01-1/766	Equipment Room - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6002	ACTIVE	p	DD216-01-1/767	Switch Cupboard - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6003	ACTIVE	p	DD216-01-1/802	Office - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6004	ACTIVE	p	DD216-01-1/804	Conference Room - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6005	ACTIVE	p	DD216-01-1/805	Office - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53978	ACTIVE	p	DD216-01-1/805	Office - Depot Building - Northfields Depot	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Above false ceiling known Lead Paint was taken back to a sound finish and re-painted - Lead Paint content liable to be present.					
6006	ACTIVE	p	DD216-01-1/806	Office - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6007	ACTIVE	p	DD216-01-1/807	Office - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6008	ACTIVE	p	DD216-01-1/902	First Aid Room - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6009	ACTIVE	p	DD216-01-1/903	Office - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6010	ACTIVE	p	DD216-01-1/904	Office - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



DD216-01 - Depot Building - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6011	ACTIVE	P	DD216-01-1/905	Workshop - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43384	INACTIVE	P	DD216-01-1/905	Workshop - Depot Building - Northfields Depot	Lead/Leading	Lead Paint/Lead	Sampled – Not Detected				Workshop Mezzanine White Matt Ceiling 290 0.03%			R558551	N	N
6012	ACTIVE	P	DD216-01-1/906	Toilet: Female - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6013	ACTIVE	P	DD216-01-1/907	Toilet: Male - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6014	ACTIVE	P	DD216-01-1/908	Store - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53952	ACTIVE	P	DD216-01-1/908	Store - Depot Building - Northfields Depot	Cement Cowlings/Flues	Asbestos	Known				Cement Flue Pipe / Cowl		1	R713903		
6015	ACTIVE	P	DD216-01-1/909	Office - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53953	ACTIVE	P	DD216-01-1/909	Office - Depot Building - Northfields Depot	Other Electrical Boxes	Asbestos	Presumed				Old Electrical Equipment - asbestos components within - Presumed to Walls 2 & 3		2	R713903		
6016	ACTIVE	P	DD216-01-1/910	Office - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6017	ACTIVE	P	DD216-01-1/911	Store - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6018	ACTIVE	P	DD216-01-1/912	Toilet: Unisex - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6019	ACTIVE	P	DD216-01-1/918	Mess Room - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46696	ACTIVE	P	DD216-01-1/918	Mess Room - Depot Building - Northfields Depot	Bitumen	Asbestos	Sampled – Not Detected				Acoustic panel under sink - 0.03m²					
6020	ACTIVE	P	DD216-01-1/921	Plant Room - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6021	ACTIVE	P	DD216-01-1/926	Shower Room - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6022	ACTIVE	P	DD216-01-A/331	Mess Room - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



DD216-01 - Depot Building - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6023	ACTIVE	P	DD216-01-A/924	Tank Room - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

DD216-02 - Office Building - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6024	ACTIVE	P	DD216-02-1/041	Canteen - Office Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6025	ACTIVE	P	DD216-02-1/047	Kitchen - Office Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6026	ACTIVE	P	DD216-02-1/048	Kitchen - Office Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6027	ACTIVE	P	DD216-02-1/081	Lobby - Office Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6028	ACTIVE	P	DD216-02-1/082	Lobby - Office Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6029	ACTIVE	P	DD216-02-1/083	Lobby - Office Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6031	ACTIVE	P	DD216-02-1/238	Passage - Office Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6032	ACTIVE	P	DD216-02-1/239	Passage - Office Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6033	ACTIVE	P	DD216-02-1/306	Office - Office Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6034	ACTIVE	P	DD216-02-1/333	Kitchen - Office Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6035	ACTIVE	P	DD216-02-1/408	Store Room - Office Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6036	ACTIVE	P	DD216-02-1/412	Store - Depot Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



DD216-02 - Office Building - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6037	ACTIVE	p	DD216-02-1/423	Toilet: Male - Office Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6040	ACTIVE	p	DD216-02-1/663	Switch Room - Office Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6041	ACTIVE	p	DD216-02-1/762	Office - Office Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6042	ACTIVE	p	DD216-02-1/763	Equipment Room - Server Room Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6043	ACTIVE	p	DD216-02-1/764	Equipment Room - Office Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6044	ACTIVE	p	DD216-02-1/778	Equipment Room - Office Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6045	ACTIVE	p	DD216-02-1/779	Fan Room - Office Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6046	ACTIVE	p	DD216-02-1/780	Fan Room - Office Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6047	ACTIVE	p	DD216-02-1/801	Production Office - Office Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6048	ACTIVE	p	DD216-02-1/803	Office - Office Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6049	ACTIVE	p	DD216-02-1/808	Office - Office Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6050	ACTIVE	p	DD216-02-1/809	Store - Store/Locker - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6051	ACTIVE	p	DD216-02-1/810	Training Room - Office Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6052	ACTIVE	p	DD216-02-1/811	Office - Office Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6053	ACTIVE	p	DD216-02-1/914	Toilet: Female - Office Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



DD216-02 - Office Building - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6056	ACTIVE	p	DD216-02-1/928	Store Room - Office Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

DD216-03 - Shunters Cabin (East) - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6057	ACTIVE	p	DD216-03-1/086	Lobby - Shunters Cabin (East) - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6058	ACTIVE	p	DD216-03-1/548	Office - Shunters Cabin (East) - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53938	ACTIVE	p	DD216-03-1/548	Office - Shunters Cabin (East) - Northfields Depot	Other Electrical Boxes	Asbestos	Presumed				Old Electrical Control Panel- Asbestos Components within - Presumed		1	R713903		
6059	ACTIVE	p	DD216-03-1/915	Toilet: Unisex - Shunters Cabin (East) - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

DD216-04 - Shunters Cabin (West) - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6060	ACTIVE	p	DD216-04-1/547	Shunters Cabin Room - Shunters Cabin (West) - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53949	ACTIVE	p	DD216-04-1/547	Shunters Cabin Room - Shunters Cabin (West) - Northfields Depot	Other Electrical Boxes	Asbestos	Presumed				5no Westinghouse & Bell Boxes - Asbestos components within External to Trackside Wall		5	R713903		
53943	ACTIVE	p	DD216-04-1/547	Shunters Cabin Room - Shunters Cabin (West) - Northfields Depot	Other Electrical Boxes	Asbestos	Presumed				Old Electrical / Equipment Boxes - Various - 5no Asbestos Components within Old Silver Control Box Old Rear House Box Transistor Amplifier Box & 2no LNSD Boxes - within Electrical Cupboard		5	R713903		
44052	INACTIVE	p	DD216-04-1/547	Shunters Cabin Room - Shunters Cabin (West) - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				White matt paint applied to outside of the window frame in West End Shunters Cabin, thickness 280 0.23%			R595226	N	N
44051	INACTIVE	p	DD216-04-1/547	Shunters Cabin Room - Shunters Cabin (West) - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				White matt paint applied to the outside of the sill in West End Shunters Cabin, thickness 230 0.02%			R595226	N	N
44049	INACTIVE	p	DD216-04-1/547	Shunters Cabin Room - Shunters Cabin (West) - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				White matt paint applied to the wall by entrance in West End Shunters Cabin, thickness 140 0.02%			R595226	N	N



Hazardous Material Asset Register - Summary



DD216-04 - Shunters Cabin (West) - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44048	ACTIVE	p	DD216-04-1/547	Shunters Cabin Room - Shunters Cabin (West) - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				White matt paint applied to the ceiling in West End Shunters Cabin, Thickness 460 0.98%			R595226	N	N
44050	INACTIVE	p	DD216-04-1/547	Shunters Cabin Room - Shunters Cabin (West) - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				White matt paint applied to the inside of the metal window frame in West End Shunters Cabin, thickness 370 0.16%			R595226	N	N

DD216-05 - Gate House - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6061	ACTIVE	p	DD216-05-1/085	Lobby - Gate House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6062	ACTIVE	p	DD216-05-1/425	Equipment Room - Gate House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6063	ACTIVE	p	DD216-05-1/812	Office - Gate House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

DD216-06 - Shunters Cabin (East) - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6064	ACTIVE	p	DD216-06-1/549	Shunters Cabin Room - Shunters Cabin (East) - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53941	ACTIVE	p	DD216-06-1/549	Shunters Cabin Room - Shunters Cabin (East) - Northfields Depot	Other Boarding	Asbestos	Strongly Presumed				Brown Paxoline Composite Panel to Electrical Equipment within Cupboard	1		R713903		
53942	ACTIVE	p	DD216-06-1/549	Shunters Cabin Room - Shunters Cabin (East) - Northfields Depot	Other Boarding	Asbestos	Presumed				Paxoline - Brown Composite Panel to Old Communications Box to wall by shunters desk		1	R713903		
53939	ACTIVE	p	DD216-06-1/549	Shunters Cabin Room - Shunters Cabin (East) - Northfields Depot	Bitumen	Asbestos	Known				Brown Mastic Strips to Window by PVC Door	1		R713903		
53940	ACTIVE	p	DD216-06-1/549	Shunters Cabin Room - Shunters Cabin (East) - Northfields Depot	Other Electrical Boxes	Asbestos	Presumed				2no Old Silver Electrical Control Boxes - Asbestos components within		2			
44053	INACTIVE	p	DD216-06-1/549	Shunters Cabin Room - Shunters Cabin (East) - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				White matt paint applied to the ceiling in East End Shunters Cabin, thickness 220 0.01%			R595226	N	N



Hazardous Material Asset Register - Summary



DD216-06 - Shunters Cabin (East) - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44054	INACTIVE	p	DD216-06-1/549	Shunters Cabin Room - Shunters Cabin (East) - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				White matt paint applied to the inside of the wall just below the ceiling in East End Shunters Cabin, thickness 550 0.01%			R595226	N	N
44055	INACTIVE	p	DD216-06-1/549	Shunters Cabin Room - Shunters Cabin (East) - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				White matt paint applied to the inside of the metal window frame in East End Shunters Cabin. thickness 710 0.04%			R595226	N	N
44056	INACTIVE	p	DD216-06-1/549	Shunters Cabin Room - Shunters Cabin (East) - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				White matt paint applied to the inside of the wall in East End Shunters Cabin, thickness 120 0.02%			R595226	N	N
44057	INACTIVE	p	DD216-06-1/549	Shunters Cabin Room - Shunters Cabin (East) - Northfields Depot	Lead/Leading	Lead Paint/Lead	Known				White matt paint applied to the outside of the metal window frame in East End Shunters Cabin, thickness 350 0.10%			R595226	N	N

DD216-07 - Pump Room - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6065	ACTIVE	p	DD216-07-1/771	Pump Room - Pump House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6066	ACTIVE	p	DD216-07-A/771	Pump Room - Pump House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46694	ACTIVE	p	DD216-07-A/771	Pump Room - Pump House - Northfields Depot	Isolator Switches	Asbestos	Presumed				7no Switch Boxes - Asbestos components within		7	R20651		

DD216-08 - Gate House - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6067	ACTIVE	p	DD216-08-1/087	Lobby - Gate House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6070	ACTIVE	p	DD216-08-1/922	Office/Mess - Gate House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6071	ACTIVE	p	DD216-08-1/923	Toilet: Unisex - Gate House - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



DD216-09 - Signals Building - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6072	ACTIVE	p	DD216-09-1/807	Switch Room - Signals Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

DD216-10 - Office Building - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6073	ACTIVE	p	DD216-10-1/414	Store - Office Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

DD216-11 - Depot Store - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6074	ACTIVE	p	DD216-11-1/481	Store Room - Depot Store - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6075	ACTIVE	p	DD216-11-1/482	Store Room - Depot Store - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

DD216-12 - P Way Tool Store - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6076	ACTIVE	p	DD216-12-1/916	Store Room - P Way Tool Store - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

DD216-13 - Electrical Building - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6077	ACTIVE	p	DD216-13-1/917	Plant Room - Electrical Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

DD216-14 - Signals Building - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6078	ACTIVE	p	DD216-14-1/664	Switch Room - Signals Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



DD216-14 - Signals Building - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
67794	ACTIVE	p	DD216-14-1/664	Switch Room - Signals Building - Northfields Depot	Other Boarding	Asbestos	Known				Soffit Boards to External of Building Switch Room E18	20		R741327		
67795	ACTIVE	p	DD216-14-1/664	Switch Room - Signals Building - Northfields Depot	Cable Duct: Other	Asbestos	Presumed				Presumed Cable Ducts within Pit / Sump within Switch Room E18 - Pit was flooded at time of survey 4th December 2023			R741327		

DD216-15 - Electrical Building - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6079	ACTIVE	p	DD216-15-1/926	Transformer Room - Electrical Building - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

DD216-16 - Store - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6080	ACTIVE	p	DD216-16-1/761	Equipment Room - Store - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53929	ACTIVE	p	DD216-16-1/761	Equipment Room - Store - Northfields Depot	Cable Ducts: Bitumen	Asbestos	Known				Bitumen Cable Duct to Floor by Wall 4 - 1no		1	R713903		
53923	ACTIVE	p	DD216-16-1/761	Equipment Room - Store - Northfields Depot	Boarding: Cement	Asbestos	Known				4no 0.03m2 Boarding - In air vent holes in brickwork Walls 2 & 4		4	R713903		
53922	ACTIVE	p	DD216-16-1/761	Equipment Room - Store - Northfields Depot	Gasket :Pipework	Asbestos	Known				Approx. 10no Gaskets - On all joints to gate valves		10	R713903		

DD216-17 - Shunters Cabin (West) - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6081	ACTIVE	p	DD216-17-1/550	Shunters Cabin Room - Shunters Cabin (West) - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

DD216-18 - P Way Accommodation - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6082	ACTIVE	p	DD216-18-1/332	Office - P Way Accommodation - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



DD216-18 - P Way Accommodation - Northfields Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6083	ACTIVE	p	DD216-18-1/338	Store - P Way Accommodation - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53926	ACTIVE	p	DD216-18-1/338	Store - P Way Accommodation - Northfields Depot	Boarding: Cement	Asbestos	Known				Cement Flat Panel above door to Wall 4	1		R713903		
53937	ACTIVE	p	DD216-18-1/338	Store - P Way Accommodation - Northfields Depot	Boarding: Cement	Asbestos	Known				Cement Panel to Wall above door	4		R713903		
6084	ACTIVE	p	DD216-18-1/409	Store - P Way Accommodation - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6085	ACTIVE	p	DD216-18-1/420	Shower Room - P Way Accommodation - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6087	ACTIVE	p	DD216-18-1/776	Store - P Way Accommodation - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53924	ACTIVE	p	DD216-18-1/776	Store - P Way Accommodation - Northfields Depot	Isolator Switches	Asbestos	Strongly Presumed				4no Switch Boxes - Asbestos components within Only 1no Switch Box identified on pre-demo survey R713903		1	R713903		
6088	ACTIVE	p	DD216-18-1/777	Plant Room - P Way Accommodation - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53925	ACTIVE	p	DD216-18-1/777	Plant Room - P Way Accommodation - Northfields Depot	Gasket :Pipework	Asbestos	Surveyed – Not Detected				Presumed Gaskets to Pipework - New Green or Cork Gaskets confirmed non-asbestos on R713903					
6089	ACTIVE	p	DD216-18-1/901	Locker Room - P Way Accommodation - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6090	ACTIVE	p	DD216-18-1/913	Mess Room - P Way Accommodation - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6091	ACTIVE	p	DD216-18-1/927	Store - P Way Accommodation - Northfields Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

PD012-01 - Depot Building - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14423	ACTIVE	p	PD012-01-1/041	Canteen - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				No Access on Re Inspection 07/11/2014 / 01/08/2018					
44442	ACTIVE	p	PD012-01-1/041	Canteen - Depot Building - Cockfosters Depot	Void	Asbestos	No Access: Presumed				No Access above Supalux ceiling tiles					



Hazardous Material Asset Register - Summary



PD012-01 - Depot Building - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43289	ACTIVE	P	PD012-01-1/041/WAL-003	Wall: Internal - 3 - Canteen - Depot Building - Cockfosters Depot	Void	Asbestos	No Access: Presumed				W3 Hardboard Panel; Fibreglass Pipe lagging				Y	
43286	ACTIVE	P	PD012-01-1/041/WAL-003	Wall: Internal - 3 - Canteen - Depot Building - Cockfosters Depot	Pipe Lagging	Asbestos	Surveyed – Not Detected				W3 Hardboard Panel Fibreglass Pipe Lagging				N	N
14425	ACTIVE	P	PD012-01-1/083	Lobby - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42617	ACTIVE	P	PD012-01-1/083	Lobby - Depot Building - Cockfosters Depot	Mastic	Asbestos	Sampled – Not Detected				Putty throughout to 2no metal window to wall 2 and 3			R508551	N	N
42640	ACTIVE	P	PD012-01-1/083	Lobby - Depot Building - Cockfosters Depot	Mastic	Asbestos	Room: Surveyed – No Known Asbestos				Putty throughout to 2no metal window to wall 2 and 3			R508551	N	N
42618	ACTIVE	P	PD012-01-1/083	Lobby - Depot Building - Cockfosters Depot	Void	Asbestos	Room: Surveyed – No Known Asbestos				Concrete slab to ceiling in false ceiling			R508551	N	N
43292	ACTIVE	P	PD012-01-1/083	Lobby - Depot Building - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Presumed				Window Frame White Gloss (External) Been re-painted since Lead Paint sampling				N	N
43291	ACTIVE	P	PD012-01-1/083/FLR-01	Floor - 1 - Lobby - Depot Building - Cockfosters Depot	Void	Asbestos	Surveyed – Not Detected				No Access below false floor Confirm solid on report R508551				N	Y
14427	ACTIVE	P	PD012-01-1/239	Passage - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14428	ACTIVE	P	PD012-01-1/321	Locker Room - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				No Access survey 07/11/2014 - Re-inspection 01/08/2018,					
43295	ACTIVE	P	PD012-01-1/321/FLR-01	Floor - 1 - Locker Room - Depot Building - Cockfosters Depot	Void	Asbestos	No Access: Presumed				No Access Above false Ceiling					
43294	ACTIVE	P	PD012-01-1/321/FLR-01	Floor - 1 - Locker Room - Depot Building - Cockfosters Depot	Void	Asbestos	No Access: Presumed				No Access Below False floor				N	Y
14429	ACTIVE	P	PD012-01-1/334	Mess Room - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
42607	ACTIVE	P	PD012-01-1/334	Mess Room - Depot Building - Cockfosters Depot	Cable Duct: Other	Asbestos	Presumed				Cable duct 1no to ceiling in false ceiling (too high to sample)	1		R508551	Y	N
42606	ACTIVE	P	PD012-01-1/334	Mess Room - Depot Building - Cockfosters Depot	Rope Gaskets	Asbestos	Presumed				Rope gaskets within glazing bars 1no to skylight in false ceiling (too high to sample)	1		R508551	Y	N
43298	ACTIVE	P	PD012-01-1/334/CLG-01	Ceiling: Solid - 1 - Mess Room - Depot Building - Cockfosters Depot	Void	Asbestos	Surveyed – Not Detected				No Access Above false Ceiling					



Hazardous Material Asset Register - Summary



PD012-01 - Depot Building - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43297	ACTIVE	P	PD012-01-1/334/FLR-01	Floor - 1 - Mess Room - Depot Building - Cockfosters Depot	Void	Asbestos	Surveyed – Not Detected				No Access Below False Floor - Floor confirmed solid on 4R 2020 re-inspection				N	Y
14430	ACTIVE	P	PD012-01-1/377	Office - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14431	ACTIVE	P	PD012-01-1/413	Cleaners Room - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14432	ACTIVE	P	PD012-01-1/414	Switch Room - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44453	ACTIVE	P	PD012-01-1/414	Switch Room - Depot Building - Cockfosters Depot	Durasteel	Asbestos	Surveyed – Not Detected				New Durasteel Panels to Exterior Wall to where roller shutters were previously					
14433	ACTIVE	P	PD012-01-1/416	Toilet: Female - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43307	ACTIVE	P	PD012-01-1/416/FLR-01	Floor - 1 - Toilet - Depot Building - Cockfosters Depot	Void	Asbestos	No Access: Presumed				Floor - 1 - Toilet No Access through manhole in floor					
14434	ACTIVE	P	PD012-01-1/417	Store - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42636	ACTIVE	P	PD012-01-1/417	Store - Depot Building - Cockfosters Depot	Void	Asbestos	Room: Surveyed – No Known Asbestos				Concrete slab to ceiling and beams within false ceiling			R508551	N	N
14435	ACTIVE	P	PD012-01-1/418	Locker Room - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42635	ACTIVE	P	PD012-01-1/418	Locker Room - Depot Building - Cockfosters Depot		Asbestos	Room: Surveyed – No Known Asbestos				A/C metal ductwork with machine made mineral fibre insulation			R508551	N	N
42634	ACTIVE	P	PD012-01-1/418	Locker Room - Depot Building - Cockfosters Depot	Void	Asbestos	Room: Surveyed – No Known Asbestos				Concrete slab to ceiling and beams within false ceiling			R508551	N	N
14436	ACTIVE	P	PD012-01-1/419	Toilet: Male - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43308	ACTIVE	P	PD012-01-1/419/CLG-01	Ceiling: Solid - 1 - Toilet: Male - Depot Building - Cockfosters Depot	Void	Asbestos	No Access: Presumed				: Ceiling: Solid - 1 - Toilet No Access Above False Ceiling					
14437	ACTIVE	P	PD012-01-1/424	Toilet: Female - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



PD012-01 - Depot Building - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14438	ACTIVE	P	PD012-01-1/425	Shower Room - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14439	ACTIVE	P	PD012-01-1/481	Workshop - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44455	ACTIVE	P	PD012-01-1/481	Workshop - Depot Building - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Window Frames - White Gloss - Internal / External Lead Paint Re-Painted - confirmed on re-inspection 01/08/2018					
43951	ACTIVE	P	PD012-01-1/481/WAL-001	Wall: Internal - 1 - Workshop - Depot Building - Cockfosters Depot		Asbestos	Sampled – Not Detected				Door gasket(1.5Lm) in red spot No 22 in workshop NADIS			R432306	N	N
43954	ACTIVE	P	PD012-01-1/481/WAL-001	Wall: Internal - 1 - Workshop - Depot Building - Cockfosters Depot		Asbestos	Removed				Composite siluminite component blocks within Combined Fuse Switch (CFS) No 26 in workshop Confirmed removed during 4R Re-inspection 2020			R432306	N	N
43953	ACTIVE	P	PD012-01-1/481/WAL-001	Wall: Internal - 1 - Workshop - Depot Building - Cockfosters Depot		Asbestos	Removed				Flash guards (cement) within Combined Fuse Switch (CFS) No 26 in workshop Confirmed removed on 4R re-inspection 2020			R432306	N	N
43952	ACTIVE	P	PD012-01-1/481/WAL-001	Wall: Internal - 1 - Workshop - Depot Building - Cockfosters Depot		Asbestos	Sampled – Not Detected				Lid gasket(0.5Lm) in Combined Fuse Switch (CFS) No 26 in workshop NADIS			R432306	N	N
43315	ACTIVE	P	PD012-01-1/481/WAL-001	Wall: Internal - 1 - Workshop - Depot Building - Cockfosters Depot	Isolator Switches	Asbestos	Removed				W1 1No 60amp Iron Clad Isolators - Insulation within - SP Confirmed removed during 4R re-inspection 2020		1		N	N
43311	INACTIVE	P	PD012-01-1/481/WAL-001	Wall: Internal - 1 - Workshop - Depot Building - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Window Frame - White Gloss (internal). 2.85% Content				N	N
43314	INACTIVE	P	PD012-01-1/481/WAL-001	Wall: Internal - 1 - Workshop - Depot Building - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Window Frame - White Gloss (internal). 4.57% Content				N	N
43313	INACTIVE	P	PD012-01-1/481/WAL-001	Wall: Internal - 1 - Workshop - Depot Building - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Window Frame - White Gloss (internal). 1.17% Content					
14440	ACTIVE	P	PD012-01-1/562	Workshop - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43958	ACTIVE	P	PD012-01-1/562	Workshop - Depot Building - Cockfosters Depot	Other Electrical Boxes	Asbestos	Sampled – Not Detected				Door gasket(1.5Lm) in red spot No 29 in Wash Shed Building at Cockfosters Depot			R432306	N	N
43957	ACTIVE	P	PD012-01-1/562	Workshop - Depot Building - Cockfosters Depot	Other Electrical Boxes	Asbestos	Sampled – Not Detected				Door gasket(1.5Lm) in red spot No 8 in 001/562			R432306	N	N



Hazardous Material Asset Register - Summary



PD012-01 - Depot Building - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43333	ACTIVE	p	PD012-01-1/562	Workshop - Depot Building - Cockfosters Depot	Isolator Switches	Asbestos	Removed				By Roller Shutter Doors 1no 60amp Iron Clad Isolators rd52 - Insulation inside - SP Confirmed removed during 4R re-inspection 2020				N	N
43334	ACTIVE	p	PD012-01-1/562	Workshop - Depot Building - Cockfosters Depot	Other Electrical Boxes	Asbestos	Removed				By Roller Shutter Doors 2no Transformer Boxes H/L rd52 - Insulation inside - P Confirmed removed on 4Rail re-inspection 2020				N	N
43337	ACTIVE	p	PD012-01-1/562	Workshop - Depot Building - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Internal steel girders - Grey coloured paint. 5.9% content				N	N
43941	ACTIVE	p	PD012-01-1/562	Workshop - Depot Building - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Blue Gloss Cross Beam over Roller Shutter No.52 West Side thickness 820 11.6%			R416076	N	N
43934	ACTIVE	p	PD012-01-1/562	Workshop - Depot Building - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Blue Gloss Cross Beam over Roller Shutter No. 52 East Side thickness 760 18.5%			R416076	N	N
43938	ACTIVE	p	PD012-01-1/562	Workshop - Depot Building - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Blue Gloss Cross Beam over Roller Shutter No. 48 East Side thickness 560 20.6%			R416076	N	N
43939	ACTIVE	p	PD012-01-1/562	Workshop - Depot Building - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Blue Gloss Cross Beam over Roller Shutter No. 47 East Side thickness 750 13.0%			R416076	N	N
43336	ACTIVE	p	PD012-01-1/562	Workshop - Depot Building - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Side of steps into pit road - Yellow coating onto floor area around steps. 9.8% content				N	N
43935	ACTIVE	p	PD012-01-1/562	Workshop - Depot Building - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Blue Gloss Cross Beam over Roller Shutter No. 51 thickness 740 16.1%			R416076	N	N
43338	ACTIVE	p	PD012-01-1/562	Workshop - Depot Building - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				External Steel girders along the length of both shed openings Blue coloured paint. 20% content				N	N
43940	ACTIVE	p	PD012-01-1/562	Workshop - Depot Building - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Blue Gloss Cross Beam over Roller Shutter No. 46 East Side thickness 1150 8.44%			R416076	N	N
43937	ACTIVE	p	PD012-01-1/562	Workshop - Depot Building - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Blue Gloss Cross Beam over Roller Shutter No. 49 East Side thickness 670 12.7%			R416076	N	N
43936	ACTIVE	p	PD012-01-1/562	Workshop - Depot Building - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Blue Gloss Cross Beam over Roller Shutter No. 50 East Side thickness 750 26.9%			R416076	N	N
14441	ACTIVE	p	PD012-01-1/563	Workshop - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43339	ACTIVE	p	PD012-01-1/563	Workshop - Depot Building - Cockfosters Depot	Rope Gaskets	Asbestos	Strongly Presumed				Ropes Gaskets - Chrysotile				N	N
43340	ACTIVE	p	PD012-01-1/563	Workshop - Depot Building - Cockfosters Depot	Isolator Switches	Asbestos	Strongly Presumed				By 1/664 Doors 1no 200amp Iron Clad Isolators - Insulation inside - SP No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.				N	N



Hazardous Material Asset Register - Summary



PD012-01 - Depot Building - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43931	ACTIVE	P	PD012-01-1/563	Workshop - Depot Building - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Grey Gloss Cross Beam over Roller Shutter No.54 West Side thickness 610 13.6%			R416076	N	N
43341	ACTIVE	P	PD012-01-1/563	Workshop - Depot Building - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				All Window Frames - White Gloss (External). has been tested and know to contain Lead Paint All Window Frames have been over painted				N	N
43932	ACTIVE	P	PD012-01-1/563	Workshop - Depot Building - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Grey Gloss Cross Beam over Roller Shutter No.53 West Side thickness 470 9.33%			R416076	N	N
43930	ACTIVE	P	PD012-01-1/563	Workshop - Depot Building - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				White Gloss Cross Beam over Roller Shutter No. 53 East Side - thickness 800 6.21%			R416076	N	N
43929	ACTIVE	P	PD012-01-1/563	Workshop - Depot Building - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				White Gloss Cross Beam over Roller Shutter No. 54 East Side thickness 640 22.0%			R416076	N	N
43933	ACTIVE	P	PD012-01-1/563	Workshop - Depot Building - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Blue (Report states Grey) Gloss Cross beams over Roller Shutters Nos. 46 to 51 West Side are same as Cross Beams over Roller Shutter No.52 West Side			R416076	N	N
14443	ACTIVE	P	PD012-01-1/578	Stairs: Linear - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14444	ACTIVE	P	PD012-01-1/663	Store - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14445	ACTIVE	P	PD012-01-1/664	Switch Room - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43344	ACTIVE	P	PD012-01-1/664/WAL-003	Wall: Internal - 3 - Switch Room - Depot Building - Cockfosters Depot	Other Electrical Boxes	Asbestos	Presumed				W3 2no H/L & 2no L/L Transformer Boxes - Presumed 4R Re-inspection 2020 only noted 2no Transformer Boxes? No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		4		N	N
43342	ACTIVE	P	PD012-01-1/664/WAL-003	Wall: Internal - 3 - Switch Room - Depot Building - Cockfosters Depot	Isolator Switches	Asbestos	Strongly Presumed				W3 200amp ,W4 60amp Iron Clad Isolators - Insulation inside - SP No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.				N	N
43972	ACTIVE	P	PD012-01-1/664/WAL-003	Wall: Internal - 3 - Switch Room - Depot Building - Cockfosters Depot	Rope Gaskets	Asbestos	Sampled – Not Detected				Hessian rope gasket (1 no.), asset no. 277255, in CFS to wall 3 of E1 Switch Room, 1/664.			R433751	N	N
43975	ACTIVE	P	PD012-01-1/664/WAL-003	Wall: Internal - 3 - Switch Room - Depot Building - Cockfosters Depot	Rope Gaskets	Asbestos	Sampled – Not Detected				Hessian rope gasket (1 no.), asset no. 277296, in Red Spot box to wall within Workshop area by vending machine			R433751	N	N



Hazardous Material Asset Register - Summary



PD012-01 - Depot Building - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43974	ACTIVE	P	PD012-01-1/664/WAL-003	Wall: Internal - 3 - Switch Room - Depot Building - Cockfosters Depot	Rope Gaskets	Asbestos	Sampled – Not Detected				Hessian rope gasket (1 no.), asset no. 277295, in CFS to wall within Workshop area by vending machine			R433751	N	N
43971	ACTIVE	P	PD012-01-1/664/WAL-003	Wall: Internal - 3 - Switch Room - Depot Building - Cockfosters Depot	Rope Gaskets	Asbestos	Sampled – Not Detected				Hessian rope gasket (1 no.), asset no. 277254, in Red Spot box to wall 3 of E1 Switch Room, 1/664			R433751	N	N
14446	ACTIVE	P	PD012-01-1/665	Plant Room - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14447	ACTIVE	P	PD012-01-1/761	Equipment Room - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14448	ACTIVE	P	PD012-01-1/776	Plant Room - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43976	ACTIVE	P	PD012-01-1/776	Plant Room - Depot Building - Cockfosters Depot	Debris: Other	Asbestos	Presumed				Known acm to wall as per stickers			R432306	N	N
43354	ACTIVE	P	PD012-01-1/776	Plant Room - Depot Building - Cockfosters Depot	Gasket :Pipework	Asbestos	Strongly Presumed				Gaskets on all gate valves in Boiler Room x36 - Chrysotile				N	N
43356	ACTIVE	P	PD012-01-1/776	Plant Room - Depot Building - Cockfosters Depot	Debris: Other	Asbestos	Known				Debris throughout room - Chrysotile & Amphibole				N	N
43351	ACTIVE	P	PD012-01-1/776	Plant Room - Depot Building - Cockfosters Depot	Lagging	Asbestos	Known				Asbestos - Known - Insulation residue on beam beneath supalux cladding (Amosite & Chrysotile).			R343376	N	N
43348	ACTIVE	P	PD012-01-1/776	Plant Room - Depot Building - Cockfosters Depot	Debris: Other	Asbestos	Strongly Presumed				Various Ducts - Possible Debris (Strongly Presumed) To Floor Ducts and to Walls				N	N
43353	ACTIVE	P	PD012-01-1/776	Plant Room - Depot Building - Cockfosters Depot	Other Electrical Boxes	Asbestos	Presumed				1no Transformer Box - Insulation inside - Presumed No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.				N	N
43352	ACTIVE	P	PD012-01-1/776	Plant Room - Depot Building - Cockfosters Depot	Isolator Switches	Asbestos	Strongly Presumed				60amp Iron Clad Isolators on wall under fuse board - Insulation inside - Strongly Presumed No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.				N	N
43345	ACTIVE	P	PD012-01-1/776	Plant Room - Depot Building - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Window Frame - White Gloss (External) 9.6%			R344126	N	N
14449	ACTIVE	P	PD012-01-1/801	Office - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14450	ACTIVE	P	PD012-01-1/803	DDM Office - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



PD012-01 - Depot Building - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42622	ACTIVE	P	PD012-01-1/803	DDM Office - Depot Building - Cockfosters Depot	Void	Asbestos	Surveyed – Not Detected				Plaster on concrete to ceiling and beams in false ceiling			R508551	N	N
42612	ACTIVE	P	PD012-01-1/803	DDM Office - Depot Building - Cockfosters Depot	Lagging	Asbestos	Surveyed – Not Detected				Plaster on concrete to ceiling and beams in false ceiling			R508551	Y	N
43360	ACTIVE	P	PD012-01-1/803/FLR-01	Floor - 1 - DDM Office - Depot Building - Cockfosters Depot	No Access	Asbestos	Surveyed – Not Detected				No Access Below false Floor Report R508551 confirms Floor is Wooden Blockwork on concrete slab;					
14451	ACTIVE	P	PD012-01-1/804	First Aid Room - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42620	ACTIVE	P	PD012-01-1/804	First Aid Room - Depot Building - Cockfosters Depot	Bitumen	Asbestos	Sampled – Not Detected				Bitumen sink pad 2no under sink unit to wall 2	2		R508551	N	N
42611	ACTIVE	P	PD012-01-1/804	First Aid Room - Depot Building - Cockfosters Depot	Mastic	Asbestos	Sampled – Not Detected				Putty throughout to metal window frame to wall 2			R508551	N	N
42609	ACTIVE	P	PD012-01-1/804	First Aid Room - Depot Building - Cockfosters Depot	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panel on brickwork by pipe from sink unit to wall 2			R508551	N	N
42621	ACTIVE	P	PD012-01-1/804	First Aid Room - Depot Building - Cockfosters Depot	Mastic	Asbestos	Sampled – Not Detected				Putty throughout to metal window frame to wall 2			R508551	N	N
42610	ACTIVE	P	PD012-01-1/804	First Aid Room - Depot Building - Cockfosters Depot	Bitumen	Asbestos	Sampled – Not Detected				Bitumen sink pad 2no under sink unit to wall 2	2		R508551	N	N
42619	ACTIVE	P	PD012-01-1/804	First Aid Room - Depot Building - Cockfosters Depot	Void	Asbestos	Surveyed – Not Detected				Concrete slab to ceiling and beams within false ceiling			R508551	Y	N
41955	ACTIVE	P	PD012-01-1/804	First Aid Room - Depot Building - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Surveyed – Not Detected				Walls & Ceiling - Cream Emulsion Paint - Lead Content 0.1%				N	N
43361	ACTIVE	P	PD012-01-1/804/FLR-01	Floor - 1 - First Aid Room - Depot Building - Cockfosters Depot	No Access	Asbestos	Surveyed – Not Detected				No Access below false floor Report R508551 confirms flooring is new Lino on Concrete Slab					
42608	ACTIVE	P	PD012-01-1/804/WAL-002	Wall: Internal - 2 - First Aid Room - Depot Building - Cockfosters Depot	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panel on brickwork by pipe from sink unit to wall 2			R508551	N	N
14452	ACTIVE	P	PD012-01-1/805	Library - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14453	ACTIVE	P	PD012-01-1/902	Store - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43157	INACTIVE	P	PD012-01-1/902	Store - Depot Building - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Presumed				Cream Matt Ceiling 370 0.12%			R528976	N	N
43158	INACTIVE	P	PD012-01-1/902	Store - Depot Building - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Presumed				Cream Matt Wall 330 0.20%			R528976	N	N



Hazardous Material Asset Register - Summary



PD012-01 - Depot Building - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43362	ACTIVE	P	PD012-01-1/902/FLR-01	Floor - 1 - Store - Depot Building - Cockfosters Depot	No Access	Asbestos	No Access: Presumed				No Access Below false floor (Office 1/808???)					
14454	ACTIVE	P	PD012-01-1/903	Workshop - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14457	ACTIVE	P	PD012-01-1/952	Disused Room - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14458	ACTIVE	P	PD012-01-1/953	Disused Room - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14459	ACTIVE	P	PD012-01-A/082	Lobby - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14460	ACTIVE	P	PD012-01-A/084	Lobby - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42638	ACTIVE	P	PD012-01-A/084	Lobby - Depot Building - Cockfosters Depot	Void	Asbestos	Room: Surveyed – No Known Asbestos				Black stair nosing - new 6(l)m to edge of stairs			R508551	N	N
14461	ACTIVE	P	PD012-01-A/085	Lobby - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14462	ACTIVE	P	PD012-01-A/706	IMR - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14463	ACTIVE	P	PD012-01-A/761	Equipment Room - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14464	ACTIVE	P	PD012-01-A/779	Plant Room - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14465	ACTIVE	P	PD012-01-A/801	Conference Room - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14466	ACTIVE	P	PD012-01-A/804	Office - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14467	ACTIVE	P	PD012-01-A/805	Library/Study - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43367	ACTIVE	P	PD012-01-A/805/FLR-01	Floor - 1 - Office - Depot Building - Cockfosters Depot	No Access	Asbestos	No Access: Presumed				No Access below floor					



Hazardous Material Asset Register - Summary



PD012-01 - Depot Building - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14468	ACTIVE	P	PD012-01-A/806	Office - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43368	ACTIVE	P	PD012-01-A/806/FLR-01	Floor - 1 - Office - Depot Building - Cockfosters Depot	No Access	Asbestos	No Access: Presumed				No Access Below False Floor					
14469	ACTIVE	P	PD012-01-A/807	Office - Depot Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42637	ACTIVE	P	PD012-01-A/807	Office - Depot Building - Cockfosters Depot	Mastic	Asbestos	Surveyed – Not Detected				Putty throughout to metal windows by wall 3			R508551	N	N
43369	ACTIVE	P	PD012-01-A/807/FLR-01	Floor - 1 - Office - Depot Building - Cockfosters Depot	No Access	Asbestos	No Access: Presumed				No Access below false floor					

PD012-02 - Paint Store - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14470	ACTIVE	P	PD012-02-1/771	Pump Room - Paint Store - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43349	ACTIVE	P	PD012-02-1/771/FLR-01	Floor - 1 - Pump Room - Paint Store - Cockfosters Depot	No Access	Asbestos	No Access: Presumed				No Access - Manholes					
14471	ACTIVE	P	PD012-02-1/904	Store Room - Paint Store - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14472	ACTIVE	P	PD012-02-1/905	Store Room - Paint Store - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14473	ACTIVE	P	PD012-02-1/906	Workshop - Paint Store - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14474	ACTIVE	P	PD012-02-1/907	Store Room - Paint Store - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53913	ACTIVE	P	PD012-02-1/907	Store Room - Paint Store - Cockfosters Depot	Mastic	Asbestos	Known				Mastic to Window Frame Externals to Building 02	5		R722076		

PD012-03 - Cleaning Shed - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14475	ACTIVE	P	PD012-03-1/238	Lobby - Cleaning Shed - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



PD012-03 - Cleaning Shed - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44447	ACTIVE	P	PD012-03-1/238/CLG-01	Ceiling: Solid - 1 - Lobby - Cleaning Shed - Cockfosters Depot	Void	Asbestos	Surveyed – Not Detected				No Access above Plasterboard Ceiling Checked on 4 Rail report R722026					
14476	ACTIVE	P	PD012-03-1/318	Locker Room - Cleaning Shed - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44448	ACTIVE	P	PD012-03-1/318/CLG-01	Ceiling: Solid - 1 - Locker Room - Cleaning Shed - Cockfosters Depot	Void	Asbestos	Surveyed – Not Detected				No access above plasterboard ceilings					
14477	ACTIVE	P	PD012-03-1/319	Locker Room - Cleaning Shed - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44449	INACTIVE	P	PD012-03-1/319	Locker Room - Cleaning Shed - Cockfosters Depot	Glazing Rope	Asbestos	Strongly Presumed				Glass Panels - Glazing Rope Strongly Presumed Duplicate of HMI 43293?					
53892	ACTIVE	P	PD012-03-1/319	Locker Room - Cleaning Shed - Cockfosters Depot	LUL Heaters	Asbestos	Strongly Presumed				Asbestos Panel within 2no LTB Heaters - SP		2	R722076		
43293	ACTIVE	P	PD012-03-1/319/CLG-01	Ceiling: Solid - 1 - Locker Room - Cleaning Shed - Cockfosters Depot	Glazing Rope	Asbestos	Strongly Presumed				Glass Panels Glazing Rope				Y	N
14478	ACTIVE	P	PD012-03-1/332	Locker Room - Cleaning Shed - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43296	ACTIVE	P	PD012-03-1/332	Locker Room - Cleaning Shed - Cockfosters Depot	No Access	Asbestos	Surveyed – Not Detected				Room surveyed on R722076 - 14/03/2023 - No asbestos detected					
14479	ACTIVE	P	PD012-03-1/373	Office - Cleaning Shed - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44450	ACTIVE	P	PD012-03-1/373	Office - Cleaning Shed - Cockfosters Depot	Isolator Switches	Asbestos	Strongly Presumed				Switch Box 200amp - directly outside 1/373 within Shed 1/561		1			
43299	ACTIVE	P	PD012-03-1/373/FLR-01	Floor - 1 - Office - Cleaning Shed - Cockfosters Depot	Void	Asbestos	Surveyed – Not Detected				No Access Below False Floor Floor recorded as SOLID on 4 Rail report R722076				N	Y
43300	INACTIVE	P	PD012-03-1/373/FLR-01	Floor - 1 - Office - Cleaning Shed - Cockfosters Depot	Isolator Switches	Asbestos	Strongly Presumed				Outside Office 1No 200amp Iron Clad Isolator - Insulation within - SP Duplication = See HMI 44450				N	N
14480	ACTIVE	P	PD012-03-1/374	Store - Cleaning Shed - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43301	ACTIVE	P	PD012-03-1/374	Store - Cleaning Shed - Cockfosters Depot		Asbestos	Surveyed – Not Detected				Room surveyed on R722076 - 14/03/2023					
44451	ACTIVE	P	PD012-03-1/374	Store - Cleaning Shed - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Presumed				Lead Paint to Door Frame and Windows to Car Examiners Hut					



Hazardous Material Asset Register - Summary



PD012-03 - Cleaning Shed - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14481	ACTIVE	P	PD012-03-1/375	Store - Cleaning Shed - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43303	ACTIVE	P	PD012-03-1/375	Store - Cleaning Shed - Cockfosters Depot	Gasket :Pipework	Asbestos	Presumed				Pipe Work Gaskets Flanged Joints					
14482	ACTIVE	P	PD012-03-1/376	Store - Cleaning Shed - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44452	ACTIVE	P	PD012-03-1/376	Store - Cleaning Shed - Cockfosters Depot	Glazing Rope	Asbestos	Sampled – Not Detected				Mastic and Window Putty Sampled - NAD Limited access to intrusively inspect skylights intrusively inspected as far as reasonably practicable without breaking glass glazing panels.					
53874	ACTIVE	P	PD012-03-1/376	Store - Cleaning Shed - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				White Gloss Paint to Walls LP 1.77%			R722078		
43304	ACTIVE	P	PD012-03-1/376/CLG-01	Ceiling: Solid - 1 - Store - Cleaning Shed - Cockfosters Depot	Glazing Rope	Asbestos	Surveyed – Not Detected				Oil Store Glass Panels - Glazing Rope - None Detected - R722076 Limited access to intrusively inspect skylights intrusively inspected as far as reasonably practicable without breaking glass glazing panels.				N	N
14483	ACTIVE	P	PD012-03-1/406	Store - Cleaning Shed - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43305	ACTIVE	P	PD012-03-1/406	Store - Cleaning Shed - Cockfosters Depot	No Access	Asbestos	Surveyed – Not Detected				Surveyed on R722076 14/03/2023 - No asbestos detected					
14484	ACTIVE	P	PD012-03-1/412	Store - Cleaning Shed - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43306	ACTIVE	P	PD012-03-1/412	Store - Cleaning Shed - Cockfosters Depot	No Access	Asbestos	Area Demolished				Store - Cleaning Shed - Cockfosters Depot Not Surveyed - Not on latest Station Layout - DEMOLISHED?					
14485	ACTIVE	P	PD012-03-1/420	Toilet: Female - Cleaning Shed - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53875	ACTIVE	P	PD012-03-1/420	Toilet: Female - Cleaning Shed - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Grey Gloss Paint to Wall in Service Void LP 3.66%			R722078		
43309	ACTIVE	P	PD012-03-1/420/CLG-01	Ceiling: Solid - 1 - Toilet - Cleaning Shed - Cockfosters Depot	Void	Asbestos	Surveyed – Not Detected				Toilet - Cleaning Shed - No Access above False Ceiling Area checked on R722076 - No asbestos detected					
14486	ACTIVE	P	PD012-03-1/421	Toilet: Male - Cleaning Shed - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



PD012-03 - Cleaning Shed - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43310	INACTIVE	P	PD012-03-1/421	Toilet: Male - Cleaning Shed - Cockfosters Depot	Isolator Switches	Asbestos	Removed				By 1/662 1No Grey 100amp Iron Clad Isolator - Insulation within - SP Confirmed removed on re-inspection 01/08/2018				N	N
43950	INACTIVE	P	PD012-03-1/421	Toilet: Male - Cleaning Shed - Cockfosters Depot		Asbestos	Removed				Composite siluminite component blocks within Combination Fuse Switch (CFS) No 39 in in 1/421 Toilet confirmed removed on 01/08/2018			R432306	N	N
43963	INACTIVE	P	PD012-03-1/421	Toilet: Male - Cleaning Shed - Cockfosters Depot		Asbestos	Removed				Gasket to lid (0.5Lm) in Combination Fuse Switch (CFS) No 39 Confirmed on re-inspection 01/08/2018			R432306	N	N
43949	INACTIVE	P	PD012-03-1/421	Toilet: Male - Cleaning Shed - Cockfosters Depot		Asbestos	Removed				Gasket to lid (0.5Lm) in Combination Fuse Switch (CFS) No 39 Confirmed removed on re-inspection 01/08/2018			R432306	N	N
13/11/2014	INACTIVE	P	PD012-03-1/421	Toilet: Male - Cleaning Shed - Cockfosters Depot		Asbestos	Removed				Gasket to lid (0.5Lm) in Combination Fuse Switch (CFS) No 39 Non Asbestos Confirmed removed on re-inspection 01/08/2018			R432306	N	N
44454	ACTIVE	P	PD012-03-1/421	Toilet: Male - Cleaning Shed - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Grey paint on top of dark green colour Internal wall of Toilet in cleaning Shed Lead Paint 1.4% Area was confirmed re-painted 01/08/2018					
14487	ACTIVE	P	PD012-03-1/561	Train Wash Area - Cleaning Shed - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53908	ACTIVE	P	PD012-03-1/561	Train Wash Area - Cleaning Shed - Cockfosters Depot	Mastic	Asbestos	Known				White Mastic to Wall Joints - Throughout			R722076		
43984	ACTIVE	P	PD012-03-1/561	Train Wash Area - Cleaning Shed - Cockfosters Depot	Debris: Other	Asbestos	Sampled – Not Detected				Dust/ debris, >1m2, within collection bin below Hi Vac Cleaning Shed at Cockfosters Depot.			R591276	N	N
53906	ACTIVE	P	PD012-03-1/561	Train Wash Area - Cleaning Shed - Cockfosters Depot	Gasket :Pipework	Asbestos	Presumed				Presumed Asbestos Gaskets to Flanges to Pipework - above room 1/379		1	R722076		
43326	ACTIVE	P	PD012-03-1/561	Train Wash Area - Cleaning Shed - Cockfosters Depot	Gasket :Pipework	Asbestos	Known				Gaskets to Mains Water Pipes - Chrysotile East Wall between Road B&C		3	R722076	N	N
53905	ACTIVE	P	PD012-03-1/561	Train Wash Area - Cleaning Shed - Cockfosters Depot	Gasket :Pipework	Asbestos	Presumed				Presumed Asbestos Gaskets to Pipework Joints at High Level - 4no Visible		4	R722076		
53904	ACTIVE	P	PD012-03-1/561	Train Wash Area - Cleaning Shed - Cockfosters Depot	Gasket :Pipework	Asbestos	Presumed				Asbestos Gaskets to Pipework in Floor Pits adjacent to Road C- 4no		4	R722076		
53903	ACTIVE	P	PD012-03-1/561	Train Wash Area - Cleaning Shed - Cockfosters Depot	Gasket :Pipework	Asbestos	Presumed				Presumed Asbestos Gaskets to flanges in pipework in floor pits at East End of Shed - 6no		6	R722076		
53909	ACTIVE	P	PD012-03-1/561	Train Wash Area - Cleaning Shed - Cockfosters Depot	Cable Ducts: Cement	Asbestos	Known				Asbestos Cement Troughing to floor across walkway by south west corner of the building - EXTERNAL	1		R722076		



Hazardous Material Asset Register - Summary



PD012-03 - Cleaning Shed - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43983	ACTIVE	p	PD012-03-1/561	Train Wash Area - Cleaning Shed - Cockfosters Depot	Debris: Other	Asbestos	Sampled – Not Detected				Dust/ debris, >1m2, within collection bin below Hi Vac Cleaning Shed at Cockfosters Depot			R591276	N	N
53907	ACTIVE	p	PD012-03-1/561	Train Wash Area - Cleaning Shed - Cockfosters Depot	Cable Ducts: Bitumen	Asbestos	Known				Bitumen Cable Ducts 3no To Wall North West Corner - 2no in Cable Pit		3	R722076		
43327	ACTIVE	p	PD012-03-1/561	Train Wash Area - Cleaning Shed - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Internal shed wall lower level - Grey paint on top of dark green colour. 1.4% content NB Not referenced on 4 Rails Report R722078 - however might be the same has HMI53870.			GL0105	N	N
43328	ACTIVE	p	PD012-03-1/561	Train Wash Area - Cleaning Shed - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Grey Gloss Paint Internal Steel Girders LP 32.1%			GL0105	N	N
43329	ACTIVE	p	PD012-03-1/561	Train Wash Area - Cleaning Shed - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				External Steel girders along the length of both shed openings Blue coloured paint. 20% content			GL0105	N	N
53872	ACTIVE	p	PD012-03-1/561	Train Wash Area - Cleaning Shed - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Green Matt Paint to Drain Pipes - EXTERNAL LP 12.7%			R722078		
53873	ACTIVE	p	PD012-03-1/561	Train Wash Area - Cleaning Shed - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Blue Gloss Paint to Cross beams above roller shutters - EXTERNAL LP 15.3%			R416076		
53871	ACTIVE	p	PD012-03-1/561	Train Wash Area - Cleaning Shed - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				White Matt Paint to Window Frames - EXTERNAL LP 14.7%			R722078		
53870	ACTIVE	p	PD012-03-1/561	Train Wash Area - Cleaning Shed - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Grey Matt Paint to Lower Walls inside Shed LP 1.93%			R722078		
43330	ACTIVE	p	PD012-03-1/561/CLG-01	Ceiling: Solid - 1 - Train Wash Area - Cleaning Shed - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Ceiling of cleaning shed - white coloured paint. 1.1% content			GL0106	N	N
14488	ACTIVE	p	PD012-03-1/662	Switch Room - Cleaning Shed - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43948	ACTIVE	p	PD012-03-1/662	Switch Room - Cleaning Shed - Cockfosters Depot	Other Electrical Boxes	Asbestos	Sampled – Not Detected				Gasket to lid (0.5Lm) in CSB No 34 in wall LHS in 1/662 Switch Room E3			R432306	N	N
43946	ACTIVE	p	PD012-03-1/662	Switch Room - Cleaning Shed - Cockfosters Depot	Other Electrical Boxes	Asbestos	Sampled – Not Detected				Gasket to lid (0.5Lm) in Combination Fuse Switch (CFS) No 33 in wall RHS in 1/662 Switch Room E3			R432306	N	N
43947	INACTIVE	p	PD012-03-1/662	Switch Room - Cleaning Shed - Cockfosters Depot	Isolator Switches	Asbestos	Known				Flash guards (cement) in Combination Fuse Switches (CFS's) No 33 & 34 in wall RHS in 1/662 Switch Room E3 Duplication of 43343			R432306	N	N
53882	ACTIVE	p	PD012-03-1/662	Switch Room - Cleaning Shed - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Grey Gloss Paint to Walls - Multi-layered grey on green LP 3.38%			R722078		
43960	ACTIVE	p	PD012-03-1/662/WAL-003	Wall: Internal - 3 - Switch Room - Cleaning Shed - Cockfosters Depot	Other Electrical Boxes	Asbestos	Sampled – Not Detected				Gasket to lid (0.5Lm) in CSB No 34 in wall LHS NAD			R432306	N	N



Hazardous Material Asset Register - Summary



PD012-03 - Cleaning Shed - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43962	ACTIVE	P	PD012-03-1/662/WAL-003	Wall: Internal - 3 - Switch Room - Cleaning Shed - Cockfosters Depot	Other Electrical Boxes	Asbestos	Sampled – Not Detected				Gasket to lid (0.5Lm) in CSB No 34 in wall LHS in 1/662 Switch Room E3			R432306	N	N
43959	ACTIVE	P	PD012-03-1/662/WAL-003	Wall: Internal - 3 - Switch Room - Cleaning Shed - Cockfosters Depot	Other Electrical Boxes	Asbestos	Sampled – Not Detected				Gasket to lid (0.5Lm) in Combination Fuse Switch (CFS) No 33 & 34 in wall RHS NAD			R432306	N	N
43343	ACTIVE	P	PD012-03-1/662/WAL-003	Wall: Internal - 3 - Switch Room - Cleaning Shed - Cockfosters Depot	Isolator Switches	Asbestos	Known				W3 2no 60amp Iron Clad Isolators - Insulation within - Confirmed asbestos components see HMI 43947 & 43961				N	N
43961	INACTIVE	P	PD012-03-1/662/WAL-003	Wall: Internal - 3 - Switch Room - Cleaning Shed - Cockfosters Depot	Isolator Switches	Asbestos	Known				Flash guards (cement) in Combination Fuse Switches (CFS's) No 33 & 34 Covered by HMI 43343			R432306	N	N
14489	ACTIVE	P	PD012-03-1/778	Plant Room - Cleaning Shed - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43359	ACTIVE	P	PD012-03-1/778	Plant Room - Cleaning Shed - Cockfosters Depot	Other Electrical Boxes	Asbestos	Surveyed – Not Detected				: Plant Room - Cleaning Shed - Limited access - Potential components to electrical equipment, potential boarding under one piece of equipment. Room surveyed on R722076 - 14/03/2023 No Asbestos Detected - Potential boarding confirmed Supalux					
14490	ACTIVE	P	PD012-03-1/917	Shower Room - Cleaning Shed - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

PD012-04 - Depot Annex - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14491	ACTIVE	P	PD012-04-1/576	Stairs: Linear - Depot Annex - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14492	ACTIVE	P	PD012-04-1/772	IMR - Depot Annex - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14493	ACTIVE	P	PD012-04-1/802	Store - Depot Annex - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42615	ACTIVE	P	PD012-04-1/802	Store - Depot Annex - Cockfosters Depot	Mastic	Asbestos	Sampled – Not Detected				Putty throughout to metal windows to wall 1			R508551	N	N
42616	ACTIVE	P	PD012-04-1/802	Store - Depot Annex - Cockfosters Depot	Other Boarding	Asbestos	Sampled – Not Detected				Black stair nosing - new 10(l)m to edge of stairs	10		R508551	N	N



Hazardous Material Asset Register - Summary



PD012-04 - Depot Annex - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42639	ACTIVE	P	PD012-04-1/802	Store - Depot Annex - Cockfosters Depot	Void	Asbestos	Room: Surveyed – No Known Asbestos				Plaster on concrete slab to ceiling in false ceiling			R508551	N	N
43357	ACTIVE	P	PD012-04-1/802	Store - Depot Annex - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Window Frame - White Gloss (External)			R344126	N	N
14494	ACTIVE	P	PD012-04-1/911	Store - Depot Annex - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14495	ACTIVE	P	PD012-04-A/047	Kitchen - Depot Annex - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42602	ACTIVE	P	PD012-04-A/047	Kitchen - Depot Annex - Cockfosters Depot	Mastic	Asbestos	Sampled – Not Detected				Putty throughout to metal window to wall 1			R508551	N	N
42601	ACTIVE	P	PD012-04-A/047	Kitchen - Depot Annex - Cockfosters Depot	Bitumen	Asbestos	Sampled – Not Detected				Bitumen sink pad 2no under sink unit to wall 2	2		R508551	N	N
14496	ACTIVE	P	PD012-04-A/081	Lobby - Depot Annex - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42595	ACTIVE	P	PD012-04-A/081	Lobby - Depot Annex - Cockfosters Depot	Mastic	Asbestos	Sampled – Not Detected				Putty to metal windows to wall 2			R508551	N	N
14497	ACTIVE	P	PD012-04-A/236	Passage - Depot Annex - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42592	ACTIVE	P	PD012-04-A/236	Passage - Depot Annex - Cockfosters Depot	Mastic	Asbestos	Sampled – Not Detected				Putty to metal windows and walls 1 & 3			R508551	N	N
14498	ACTIVE	P	PD012-04-A/316	Locker Room - Depot Annex - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42600	ACTIVE	P	PD012-04-A/316	Locker Room - Depot Annex - Cockfosters Depot	Mastic	Asbestos	Sampled – Not Detected				Putty to metal window to wall 2			R508551	N	N
43363	ACTIVE	P	PD012-04-A/316/FLR-01	Floor - 1 - Locker Room - Depot Annex - Cockfosters Depot	No Access	Asbestos	Surveyed – Not Detected				No Access Below False floor Report R508551 confirms floor to be new lino on concrete slab					
14499	ACTIVE	P	PD012-04-A/331	Mess Room - Depot Annex - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42599	ACTIVE	P	PD012-04-A/331	Mess Room - Depot Annex - Cockfosters Depot	Mastic	Asbestos	Sampled – Not Detected				Putty to metal windows to wall 1			R508551	N	N
14500	ACTIVE	P	PD012-04-A/411	Store - Depot Annex - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42594	ACTIVE	P	PD012-04-A/411	Store - Depot Annex - Cockfosters Depot	Mastic	Asbestos	Sampled – Not Detected				Putty to metals windows to wall 3			R508551	N	N



Hazardous Material Asset Register - Summary



PD012-04 - Depot Annex - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14501	ACTIVE	P	PD012-04-A/412	Store - Depot Annex - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14502	ACTIVE	P	PD012-04-A/413	Store - Depot Annex - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14503	ACTIVE	P	PD012-04-A/414	Locker Room - Depot Annex - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14504	ACTIVE	P	PD012-04-A/416	Toilet: Female - Depot Annex - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42590	ACTIVE	P	PD012-04-A/416	Toilet: Female - Depot Annex - Cockfosters Depot	Mastic	Asbestos	Sampled – Not Detected				Putty to metal windows by wall 3			R508551	N	N
14505	ACTIVE	P	PD012-04-A/417	Shower Room - Depot Annex - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14506	ACTIVE	P	PD012-04-A/418	Toilet: Male - Depot Annex - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42605	ACTIVE	P	PD012-04-A/418	Toilet: Male - Depot Annex - Cockfosters Depot	Debris: Other	Asbestos	Room: Surveyed – No Known Asbestos				Metal corrugation - new To ceiling with false ceiling (cupboard rea)			R508551	Y	N
42596	ACTIVE	P	PD012-04-A/418	Toilet: Male - Depot Annex - Cockfosters Depot	Mastic	Asbestos	Sampled – Not Detected				Putty to metal windows to wall			R508551	N	N
42604	ACTIVE	P	PD012-04-A/418	Toilet: Male - Depot Annex - Cockfosters Depot	Mastic	Asbestos	Sampled – Not Detected				Putty throughout to metal window to wall 2			R508551	N	N
14507	ACTIVE	P	PD012-04-A/577	Stairs: Linear - Depot Annex - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43364	ACTIVE	P	PD012-04-A/577	Stairs: Linear - Depot Annex - Cockfosters Depot	No Access	Asbestos	Surveyed – Not Detected				Visually inspected - No Obvious Asbestos					
14508	ACTIVE	P	PD012-04-A/661	Switch Room - Depot Annex - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14509	ACTIVE	P	PD012-04-A/776	Plant Room - Depot Annex - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42632	ACTIVE	P	PD012-04-A/776	Plant Room - Depot Annex - Cockfosters Depot	Void	Asbestos	Room: Surveyed – No Known Asbestos				Cement slab to ceiling in false ceiling			R508551	N	N
14510	ACTIVE	P	PD012-04-A/777	Lobby - Depot Annex - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



PD012-04 - Depot Annex - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14511	ACTIVE	P	PD012-04-A/778	Plant Room - Depot Annex - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14512	ACTIVE	P	PD012-04-A/802	Office - Depot Annex - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Lino on concrete slab to floor - under carpet tiles					
42631	ACTIVE	P	PD012-04-A/802	Office - Depot Annex - Cockfosters Depot	Mastic	Asbestos	Sampled – Not Detected				Putty to window frame to wall 2			R508551	N	N
42630	ACTIVE	P	PD012-04-A/802	Office - Depot Annex - Cockfosters Depot	Void	Asbestos	Sampled – Not Detected				Lino on concrete slab to floor - under carpet tiles			R508551	N	N
42588	ACTIVE	P	PD012-04-A/802	Office - Depot Annex - Cockfosters Depot	Bitumen	Asbestos	Sampled – Not Detected				Bitumen sink pad under sink unit to wall 6			R508551	N	N
42589	ACTIVE	P	PD012-04-A/802	Office - Depot Annex - Cockfosters Depot	Mastic	Asbestos	Sampled – Not Detected				Putty to window frame to wall 2			R508551	N	N
43365	ACTIVE	P	PD012-04-A/802	Office - Depot Annex - Cockfosters Depot	Cement Cowlings/ Flues	Asbestos	Presumed				Roof vent Cowlings 2no Removed by Econ 2013 1no Presumed by 4R 2020 Re-Inspection		1		N	N
14513	ACTIVE	P	PD012-04-A/804	First Aid - Depot Annex - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42603	ACTIVE	P	PD012-04-A/804	First Aid - Depot Annex - Cockfosters Depot	Mastic	Asbestos	Sampled – Not Detected				Putty throughout to 3 no. metal windows to walls 1 and 2			R508551	N	N
43366	ACTIVE	P	PD012-04-A/804/ FLR-01	Floor - 1 - Office - Depot Annex - Cockfosters Depot	No Access	Asbestos	No Access: Presumed				No Access Below Floor					
14514	ACTIVE	P	PD012-04-A/901	Workshop - Depot Annex - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42593	ACTIVE	P	PD012-04-A/901	Workshop - Depot Annex - Cockfosters Depot	Mastic	Asbestos	Sampled – Not Detected				Putty to metals windows to wall 2			R508551	N	N
14515	ACTIVE	P	PD012-04-A/902	Security Room - Depot Annex - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42597	ACTIVE	P	PD012-04-A/902	Security Room - Depot Annex - Cockfosters Depot	Mastic	Asbestos	Sampled – Not Detected				Putty to metal windows to wall 2 & 4			R508551	N	N
43371	ACTIVE	P	PD012-04-A/902	Security Room - Depot Annex - Cockfosters Depot	LUL Heaters	Asbestos	Removed				Old gas heater Removed by Econ ES3589b 13/02/2013				N	N
42598	ACTIVE	P	PD012-04-A/902	Security Room - Depot Annex - Cockfosters Depot	Bitumen	Asbestos	Sampled – Not Detected				Bitumen sink pad under sink unit to wall 3			R508551	N	N



Hazardous Material Asset Register - Summary



PD012-04 - Depot Annex - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43370	ACTIVE	P	PD012-04-A/902/WAL-004	Wall: Internal - 4 - Security Room - Depot Annex - Cockfosters Depot	Boarding: AIB	Asbestos	Presumed				Wall 4 Chrysotile Panel covering Beam Removed by Econ ES3589b 13/02/2013 2020 re-inspection claims item still present				N	N

PD012-05 - Store - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14516	ACTIVE	P	PD012-05-1/910	Plant Room - Store - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43372	ACTIVE	P	PD012-05-1/910	Plant Room - Store - Cockfosters Depot		Asbestos	Surveyed – Not Detected				Not surveyed					

PD012-06 - Shunters Cabin (West) - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14517	ACTIVE	P	PD012-06-1/407	Store - Shunters Cabin (West) - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14518	ACTIVE	P	PD012-06-1/408	Store - Shunters Cabin (West) - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53893	ACTIVE	P	PD012-06-1/408	Store - Shunters Cabin (West) - Cockfosters Depot	Other Boarding	Asbestos	Presumed				Black & Brown Composite / Paxoline Panels to Electrical Equipment Board			R722076		
14519	ACTIVE	P	PD012-06-1/422	Toilet: Unisex - Shunters Cabin (West) - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53887	ACTIVE	P	PD012-06-1/422	Toilet: Unisex - Shunters Cabin (West) - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				White Matt Paint to Ceilings LP 2.59%			R722078		
53888	ACTIVE	P	PD012-06-1/422	Toilet: Unisex - Shunters Cabin (West) - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				White Gloss Paint to Door Frames LP 1%			R722078		
14520	ACTIVE	P	PD012-06-1/546	Shunters Cabin Room - Shunters Cabin (West) - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53899	ACTIVE	P	PD012-06-1/546	Shunters Cabin Room - Shunters Cabin (West) - Cockfosters Depot	Other Electrical Boxes	Asbestos	Presumed				Asbestos Components Presumed within 2no Old Comms Boxes		2	R722076		
53898	ACTIVE	P	PD012-06-1/546	Shunters Cabin Room - Shunters Cabin (West) - Cockfosters Depot	Other Boarding	Asbestos	Presumed				Brown Composite / Paxoline Panel - Presumed		2	R722076		



Hazardous Material Asset Register - Summary



PD012-06 - Shunters Cabin (West) - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
53889	ACTIVE	p	PD012-06-1/546	Shunters Cabin Room - Shunters Cabin (West) - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				White Gloss Paint to Windows - EXTERNAL LP 10.5%			R722078		

PD012-07 - Shunters Cabin (East) - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14521	ACTIVE	p	PD012-07-1/409	Store - Shunters Cabin (East) - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53895	ACTIVE	p	PD012-07-1/409	Store - Shunters Cabin (East) - Cockfosters Depot	Other Electrical Boxes	Asbestos	Presumed				Asbestos Components Presumed within Transistor Box		1	R722076		
14522	ACTIVE	p	PD012-07-1/410	Store - Shunters Cabin (East) - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53896	ACTIVE	p	PD012-07-1/410	Store - Shunters Cabin (East) - Cockfosters Depot	Other Boarding	Asbestos	Known				Asbestos Brown Composite / Paxoline Panel - Loose to Wall 2		1	R722076		
53897	ACTIVE	p	PD012-07-1/410	Store - Shunters Cabin (East) - Cockfosters Depot	Other Boarding	Asbestos	Presumed				Brown & Black Composite / Paxoline Panels to Electrical Equipment Presumed Asbestos			R722076		
14523	ACTIVE	p	PD012-07-1/423	Toilet: Unisex - Shunters Cabin (East) - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53890	ACTIVE	p	PD012-07-1/423	Toilet: Unisex - Shunters Cabin (East) - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Cream Gloss Paint to Walls LP 1.2%			R722078		
14524	ACTIVE	p	PD012-07-1/547	Shunters Cabin Room - Shunters Cabin (East) - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53900	ACTIVE	p	PD012-07-1/547	Shunters Cabin Room - Shunters Cabin (East) - Cockfosters Depot	Other Electrical Boxes	Asbestos	Presumed				Asbestos Components Presumed within 3no Comms Equipment Boxes		3	R722076		
53901	ACTIVE	p	PD012-07-1/547	Shunters Cabin Room - Shunters Cabin (East) - Cockfosters Depot	Westing house Boxes	Asbestos	Presumed				Presumed Asbestos Components within 3no Westinghouse Boxes to walls and concrete post to northside of shunters cabin - EXTERNAL		3	R722076		
53902	ACTIVE	p	PD012-07-1/547	Shunters Cabin Room - Shunters Cabin (East) - Cockfosters Depot	Westing house Boxes	Asbestos	Presumed				Asbestos Components Presumed within Bell & Westinghouse Box		2	R722076		
43325	ACTIVE	p	PD012-07-1/547	Shunters Cabin Room - Shunters Cabin (East) - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				White Gloss Paint to Windows - EXTERNAL LP 15.9%			GL0106	N	N
53891	ACTIVE	p	PD012-07-1/547	Shunters Cabin Room - Shunters Cabin (East) - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				White Matt Paint to Downpipes - EXTERNAL LP 1.18%			R722078		



Hazardous Material Asset Register - Summary



PD012-08 - Store - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14525	ACTIVE	P	PD012-08-1/912	Switch Room - Store - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14526	ACTIVE	P	PD012-08-1/913	Store Room - Store - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14527	ACTIVE	P	PD012-08-1/914	Store Room - Store - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

PD012-09 - Train Wash - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14528	ACTIVE	P	PD012-09-1/482	Train Wash Area - Train Wash - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43955	INACTIVE	P	PD012-09-1/482	Train Wash Area - Train Wash - Cockfosters Depot	Isolator Switches	Asbestos	Sampled – Not Detected				Lid gasket(0.5Lm) in Combination Fuse Switch (CFS) No 30 in Wash Shed Building NAD See 43318			R432306	N	N
43956	ACTIVE	P	PD012-09-1/482	Train Wash Area - Train Wash - Cockfosters Depot	Other Electrical Boxes	Asbestos	Sampled – Not Detected				Door gasket (1.5Lm) in red spot No 29 in Wash Shed NAD			R432306	N	N
46023	ACTIVE	P	PD012-09-1/482	Train Wash Area - Train Wash - Cockfosters Depot	Other Electrical Boxes	Asbestos	Presumed				Presumed components within 4no Wash Motor Equipment Boxes		4			
53881	ACTIVE	P	PD012-09-1/482	Train Wash Area - Train Wash - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				White Matt Paint to Window Frames - EXTERNAL LP 18.9%			R722078		
53876	ACTIVE	P	PD012-09-1/482	Train Wash Area - Train Wash - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				White Gloss Paint - Multi-layered white on blue to Lower Walls LP 3.55%			R722078		
53879	ACTIVE	P	PD012-09-1/482	Train Wash Area - Train Wash - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				White Matt Paint to Downpipe - Multi-layered white on grey LP 5.74%			R722078		
53880	ACTIVE	P	PD012-09-1/482	Train Wash Area - Train Wash - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Green Matt Paint to Pipes - EXTERNAL LP 8.99%			R722078		
43322	ACTIVE	P	PD012-09-1/482/CLG-01	Ceiling: Solid - 1 - Train Wash Area - Train Wash - Cockfosters Depot	Rope Gaskets	Asbestos	Known				Rope Gaskets to Glazing to roof Previously SP - Confirmed asbestos R722076 14/03/2023				N	N
43317	INACTIVE	P	PD012-09-1/482/CLG-01	Ceiling: Solid - 1 - Train Wash Area - Train Wash - Cockfosters Depot	Glazing Rope	Asbestos	Strongly Presumed				Glazing Rope - SP Duplicate see 43322				Y	N
53878	ACTIVE	P	PD012-09-1/482/CLG-01	Ceiling: Solid - 1 - Train Wash Area - Train Wash - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Beige Gloss Paint to High Level Steel Truss Borderline LP 0.58%			R722078		



Hazardous Material Asset Register - Summary



PD012-09 - Train Wash - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
53877	ACTIVE	P	PD012-09-1/482/CLG-01	Ceiling: Solid - 1 - Train Wash Area - Train Wash - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				White Matt Paint to Wood Ceiling Borderline LP 0.59%			R722078		
14529	ACTIVE	P	PD012-09-1/780	Pump Room - Train Wash - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43318	ACTIVE	P	PD012-09-1/780	Pump Room - Train Wash - Cockfosters Depot	Isolator Switches	Asbestos	Strongly Presumed				W1 3No (1no 100amp & 2no 60amp) Iron Clad Isolators - Insulation within - SP NB Lid gasket(0.5Lm) in Combination Fuse Switch (CFS) No 30 in Wash Shed Building NAD				N	N
53884	ACTIVE	P	PD012-09-1/780	Pump Room - Train Wash - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Grey Gloss Paint to RSJ - Multi-layered grey on red LP 35.1%			R722078		
53883	ACTIVE	P	PD012-09-1/780	Pump Room - Train Wash - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				White Gloss Paint to Lower Walls - Multi-layered white on blue/grey Borderline LP 0.58%			R722078		
53910	ACTIVE	P	PD012-09-1/780/FLR-01	Floor - 1 - Pump Room - Train Wash - Cockfosters Depot	Gasket :Pipework	Asbestos	Presumed				Presumed Asbestos Gaskets to Pipework within Sump Pit			R722076		
43316	ACTIVE	P	PD012-09-1/780/WAL-002	Wall: Internal - 2 - Pump Room - Train Wash - Cockfosters Depot	LUL Heaters	Asbestos	Known				LU Heater - Insulation Board - Confirmed Asbestos			R722076	N	N
53911	ACTIVE	P	PD012-09-1/780/WAL-004	Wall: Internal - 4 - Pump Room - Train Wash - Cockfosters Depot	Cable Ducts: Cement	Asbestos	Known				3no Asbestos Cement Cable Ducts - Wall 4		3	R722076		
43319	ACTIVE	P	PD012-09-1/780/WAL-004	Wall: Internal - 4 - Pump Room - Train Wash - Cockfosters Depot	Other Electrical Boxes	Asbestos	Presumed				W4 1no Transformer Box - P				N	N
14530	ACTIVE	P	PD012-09-1/918	Plant Room - Train Wash - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53912	ACTIVE	P	PD012-09-1/918	Plant Room - Train Wash - Cockfosters Depot	Other Electrical Boxes	Asbestos	Presumed				Materials within Old Equipment Boxes		5	R722076		
43320	ACTIVE	P	PD012-09-1/918	Plant Room - Train Wash - Cockfosters Depot	Gasket :Pipework	Asbestos	Known				Pipe Work - Asbestos Gaskets to Flanged Joints - approx. 6no (Pump Room)		6	R722076	N	N
53885	ACTIVE	P	PD012-09-1/918	Plant Room - Train Wash - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				White Gloss Paint to Windows LP 3.1%			R722078		
53886	ACTIVE	P	PD012-09-1/918	Plant Room - Train Wash - Cockfosters Depot	Lead/Leading	Lead Paint/Lead	Known				Red Gloss Paint to Door - LP 1.29% White Gloss to Door Frame - LP 4.55%			R722078		
43321	ACTIVE	P	PD012-09-1/918/WAL-001	Wall: Internal - 1 - Plant Room - Train Wash - Cockfosters Depot	LUL Heaters	Asbestos	Known				LU Heater - Insulation Board W1				N	N



Hazardous Material Asset Register - Summary



PD012-10 - Train Shed Wash Plant Building - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14531	ACTIVE	p	PD012-10-1/916	Plant Room - Train Shed Wash Plant Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

PD012-11 - Signals Building - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14532	ACTIVE	p	PD012-11-1/666	Switch Room - Signals Building - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43346	ACTIVE	p	PD012-11-1/666	Switch Room - Signals Building - Cockfosters Depot		Asbestos	Surveyed – Not Detected				Switch Room Not Surveyed - New Build					

PD012-12 - Substation - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14533	ACTIVE	p	PD012-12-1/781	Substation Room - Substation - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

PD012-13 - Cleaners Accommodation - Cockfosters Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14534	ACTIVE	p	PD012-13-1/320	Locker Room - Cleaners Accommodation - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43373	ACTIVE	p	PD012-13-1/320/FLR-01	Floor - 1 - Locker Room - Cleaners Accommodation - Cockfosters Depot	No Access	Asbestos	No Access: Presumed				No Access below false floor Not on Station Layout Version 2016/2017					
14535	ACTIVE	p	PD012-13-1/335	Mess Room - Cleaners Accommodation - Cockfosters Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									