



# Hazardous Material Asset Register - Summary



Run date: 18/09/2023

Line: Northern

Risk Assessment Status: Active, Inactive

Hazardous Material Status: All

Hazardous Material Type: All

## N021-00 - Station Building - Edgware Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44881	ACTIVE	N	N021-00-0/576	Stairs - Station Building - Edgware Stn	Bakerlite	Asbestos	Presumed				Bakelite switch under stairs cabinet Reinspected 17-03-2023				N	N
44882	ACTIVE	N	N021-00-0/576	Stairs - Station Building - Edgware Stn	Cable: Sheath	Asbestos	Not Found during Inspection				Black Braided Cable to window wall 1, 1st window Reinspection 17-03-2023 - No longer present/possibly removed by 3rd parties.				N	N
44887	ACTIVE	N	N021-00-0/706	Interlocking Machine - Station Building - Edgware Stn	Bitumen	Asbestos	Strongly Presumed				Adhesive to Green & Grey tiles on Walls & Ceilings Reinspected 17-03-2023				N	N
44889	ACTIVE	N	N021-00-0/706	Interlocking Machine - Station Building - Edgware Stn	Other Boarding	Asbestos	Known				4x Light & Dark Brown Composite Panels - 1x to wall to right hand side upper level, 1x to back of fuses, 1x to side of main switch frame Reinspected 17-03-2023		4		N	N
44890	ACTIVE	N	N021-00-0/706	Interlocking Machine - Station Building - Edgware Stn	Rope Gaskets	Asbestos	Known				2x Gaskets to metal tube electric heater to Wall 3 Reinspected 17-03-2023		2		N	N
44888	ACTIVE	N	N021-00-0/706	Interlocking Machine - Station Building - Edgware Stn	Cable Ducts: Bitumen	Asbestos	Strongly Presumed				6x Bitumen Ducts - 2x to Wall 4 & 4x to Wall 1 Reinspected 17-03-2023				N	N
44891	ACTIVE	N	N021-00-0/706	Interlocking Machine - Station Building - Edgware Stn	Other Electrical Boxes	Asbestos	Not Found during Inspection				Materials within Signal cabinet				N	N
44886	ACTIVE	N	N021-00-0/707	Interlocking Machine - Station Building - Edgware Stn	Cable Ducts: Bitumen	Asbestos	Strongly Presumed				Bitumen Ducts to Wall 1 at High Level Reinspected 17-03-2023				N	N
42548	INACTIVE	N	N021-00-0/707 85075940	Interlocking Machine - Station Building - Edgware Stn Room Asset	Other Electrical Boxes	Asbestos	Presumed				This record was incorrectly created. Refer to 25844, 25845 & 25846					
44885	ACTIVE	N	N021-00-0/707	Interlocking Machine - Station Building - Edgware Stn	Cable: Sheath	Asbestos	Presumed				Braided Cable bunches throughout walls Reinspected 17-03-2023				N	N
42324	INACTIVE	N	N021-00-0/707	Interlocking Machine - Station Building - Edgware Stn	PCBs	Polychlorinated biphenyl	Presumed				Duplicate record - Refer to 25847		4		N	N
44883	ACTIVE	N	N021-00-0/707/WAL-001	Wall: Internal - 1 - Interlocking Machine - Station Building - Edgware Stn	Other Boarding	Asbestos	Presumed				Paxoline boarding Reinspected 17-03-2023				N	N
25850	ACTIVE	N	N021-00-0/707/WAL-002	Wall: Internal - 2 - Interlocking Machine - Station Building - Edgware Stn	Other Boarding	Asbestos	Presumed				Approx 12 Paxoline boards Wall 2 Reinspected 17-03-2023		12			
25847	INACTIVE	N	N021-00-0/707/WAL-002	Wall: Internal - 2 - Interlocking Machine - Station Building - Edgware Stn	PCBs	Polychlorinated biphenyl	Presumed				W2 - 18 x medium silver cyclinder PCB's wall mounted on silver plates - faircondition		18		N	N
25845	ACTIVE	N	N021-00-0/707/WAL-003	Wall: Internal - 3 - Interlocking Machine - Station Building - Edgware Stn	Other Electrical Boxes	Asbestos	Presumed				LTE electrical box Wall 3 Reinspected 17-03-2023		1			



# Hazardous Material Asset Register - Summary



## N021-00 - Station Building - Edgware Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25846	ACTIVE	N	N021-00-0/707/WAL-003	Wall: Internal - 3 - Interlocking Machine - Station Building - Edgware Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer box on floor - Insulation within presumed to contain asbestos Reinspected 17-03-2023		2			
25849	ACTIVE	N	N021-00-0/707/WAL-004	Wall: Internal - 4 - Interlocking Machine - Station Building - Edgware Stn	Other Boarding	Asbestos	Presumed				Paxoline Boarding Wall 4 Reinspected 17-03-2023		2			
25844	ACTIVE	N	N021-00-0/707/WAL-004	Wall: Internal - 4 - Interlocking Machine - Station Building - Edgware Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				2x 100amps Electrical boxes Reinspected 17-03-2023		2			
44884	INACTIVE	N	N021-00-0/707/WAL-004	Wall: Internal - 4 - Interlocking Machine - Station Building - Edgware Stn	Other Boarding	Asbestos	Presumed				Duplicate				N	N
44865	ACTIVE	N	N021-00-0/951	Disused - Station Building - Edgware Stn	Bitumen	Asbestos	Known				Adhesive to Green & Grey tiles on Walls & Ceilings Reinspected 17-03-2023				N	N
44866	ACTIVE	N	N021-00-0/951	Disused - Station Building - Edgware Stn	Cable Ducts: Bitumen	Asbestos	Known				2x Bitumen Duct at high level to Wall 3 Reinspected 17-03-2023		2		N	N
44877	ACTIVE	N	N021-00-0/952	Disused - Station Building - Edgware Stn	Isolator Switches	Asbestos	Known				Materials within current rail isolation switch 533 within cess by P-Way Store				N	N
44878	ACTIVE	N	N021-00-0/952	Disused - Station Building - Edgware Stn	Isolator Switches	Asbestos	Known				Materials within current rail isolation switch 534 within cess by P-Way Store				N	N
44880	ACTIVE	N	N021-00-0/952	Disused - Station Building - Edgware Stn	Cement Troughing	Asbestos	Presumed				Cement troughing below current rail isolation section switch 534 within concrete slab				N	N
44879	ACTIVE	N	N021-00-0/952	Disused - Station Building - Edgware Stn	Cement Troughing	Asbestos	Presumed				Cement troughing below current rail isolation section switch 533 within concrete slab				N	N
8230	ACTIVE	N	N021-00-1/001	Booking Hall - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19828	INACTIVE	N	N021-00-1/001	Booking Hall - Station Building - Edgware Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8231	ACTIVE	N	N021-00-1/011	Ticket Office - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
19804	ACTIVE	N	N021-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Edgware Stn	Void	Asbestos	Surveyed - Not Detected				Boarding; Fibreglass - Lagging above Plasterboard Ceiling				YES	
19830	ACTIVE	N	N021-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard					
19831	ACTIVE	N	N021-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Edgware Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden floor					YES
19829	ACTIVE	N	N021-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Edgware Stn	Void	Asbestos	No Access: Presumed				Beneath wooden floor					YES



# Hazardous Material Asset Register - Summary



## N021-00 - Station Building - Edgware Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8232	ACTIVE	N	N021-00-1/021	POM - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
19832	ACTIVE	N	N021-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Edgware Stn	Void	Asbestos	Surveyed - Not Detected				Boarding above Plasterboard				YES	
19430	ACTIVE	N	N021-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard					
8233	ACTIVE	N	N021-00-1/031	Mess Room - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19880	ACTIVE	N	N021-00-1/031	Mess Room - Station Building - Edgware Stn		Asbestos	Surveyed - Not Detected				Acoustic Panel below sink					
8234	ACTIVE	N	N021-00-1/032	Office - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19833	ACTIVE	N	N021-00-1/032	Office - Station Building - Edgware Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8235	ACTIVE	N	N021-00-1/036	Toilet: Unisex - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19834	INACTIVE	N	N021-00-1/036	Toilet: Unisex - Station Building - Edgware Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8236	ACTIVE	N	N021-00-1/047	Kitchen - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19675	INACTIVE	N	N021-00-1/047	Kitchen - Station Building - Edgware Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8237	ACTIVE	N	N021-00-1/071	Circulation Area - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19835	ACTIVE	N	N021-00-1/071/CLG-01	Ceiling: Suspended - 1 - Circulation Area - Station Building - Edgware Stn	Void	Asbestos	Surveyed - Not Detected				Steel Panel Ceiling				YES	
8238	ACTIVE	N	N021-00-1/081	Lobby - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
19837	ACTIVE	N	N021-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Edgware Stn	Void	Asbestos	Surveyed - Not Detected				Boarding above Plasterboard				YES	
19431	ACTIVE	N	N021-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard					
19836	ACTIVE	N	N021-00-1/081/FLR-01	Floor - 1 - Lobby - Station Building - Edgware Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden floor					YES



# Hazardous Material Asset Register - Summary



## N021-00 - Station Building - Edgware Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20333	ACTIVE	N	N021-00-1/081/FLR-01	Floor - 1 - Lobby - Station Building - Edgware Stn	Void	Asbestos	No Access: Presumed				Computer Flooring - No access beneath					N
8239	ACTIVE	N	N021-00-1/082	Lobby - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19838	ACTIVE	N	N021-00-1/082/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard					
19839	ACTIVE	N	N021-00-1/082/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Edgware Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Plasterboard				YES	
8241	ACTIVE	N	N021-00-1/236	Passage - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19842	ACTIVE	N	N021-00-1/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Edgware Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Plasterboard				YES	
19841	ACTIVE	N	N021-00-1/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard					
8242	ACTIVE	N	N021-00-1/237	Passage - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19843	ACTIVE	N	N021-00-1/237/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard					
19844	ACTIVE	N	N021-00-1/237/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Edgware Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Plasterboard				YES	
8243	ACTIVE	N	N021-00-1/238	Passage - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19433	ACTIVE	N	N021-00-1/238/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Edgware Stn	Void	Asbestos	Surveyed - Not Detected				Fibreglass Lagging above Acoustic Panels				YES	
8244	ACTIVE	N	N021-00-1/239	Passage - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19845	ACTIVE	N	N021-00-1/239/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Edgware Stn	Void	Asbestos	Surveyed - Not Detected				Fibreglass Lagging above Acoustic Panels				YES	
8245	ACTIVE	N	N021-00-1/240	Passage - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19846	ACTIVE	N	N021-00-1/240/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Edgware Stn	Void	Asbestos	Surveyed - Not Detected				Fibreglass Lagging above Wood				YES	
19894	ACTIVE	N	N021-00-1/240/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard					



# Hazardous Material Asset Register - Summary



## N021-00 - Station Building - Edgware Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19445	ACTIVE	N	N021-00-1/240/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Edgware Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Fibreglass Lagging above Plasterboard				YES	
8246	ACTIVE	N	N021-00-1/241	Passage - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
8247	ACTIVE	N	N021-00-1/242	Passage - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
19895	ACTIVE	N	N021-00-1/242/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
19680	ACTIVE	N	N021-00-1/242/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Edgware Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Fibreglass Lagging above Plasterboard				YES	
8248	ACTIVE	N	N021-00-1/281	Station Supervisor Office - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
19897	ACTIVE	N	N021-00-1/281/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Edgware Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Plasterboard				YES	
19896	ACTIVE	N	N021-00-1/281/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
8249	ACTIVE	N	N021-00-1/306	Office - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8250	ACTIVE	N	N021-00-1/316	Office - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
19898	ACTIVE	N	N021-00-1/316/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Edgware Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Acoustic Panel				YES	
8251	ACTIVE	N	N021-00-1/317	Locker Room - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
19446	ACTIVE	N	N021-00-1/317/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Edgware Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Plasterboard				YES	
19899	ACTIVE	N	N021-00-1/317/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard, Wood Boxing					
8252	ACTIVE	N	N021-00-1/331	Mess Room - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
19900	ACTIVE	N	N021-00-1/331	Mess Room - Station Building - Edgware Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					



# Hazardous Material Asset Register - Summary



## N021-00 - Station Building - Edgware Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8253	ACTIVE	N	N021-00-1/332	Mess Room - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
19902	ACTIVE	N	N021-00-1/332/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Edgware Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Fibreglass Lagging above false ceiling				YES	
19901	ACTIVE	N	N021-00-1/332/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
8254	ACTIVE	N	N021-00-1/341	Mess Room - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
19903	ACTIVE	N	N021-00-1/341	Mess Room - Station Building - Edgware Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
19447	ACTIVE	N	N021-00-1/341/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
19806	ACTIVE	N	N021-00-1/341/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Edgware Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				YES	
8256	ACTIVE	N	N021-00-1/401	Store - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
19905	INACTIVE	N	N021-00-1/401	Store - Station Building - Edgware Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8257	ACTIVE	N	N021-00-1/402	Store - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
19681	INACTIVE	N	N021-00-1/402	Store - Station Building - Edgware Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8258	ACTIVE	N	N021-00-1/403	Store - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
19906	INACTIVE	N	N021-00-1/403	Store - Station Building - Edgware Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8259	ACTIVE	N	N021-00-1/404	Store - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
19907	INACTIVE	N	N021-00-1/404	Store - Station Building - Edgware Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8260	ACTIVE	N	N021-00-1/411	Store - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									



# Hazardous Material Asset Register - Summary



## N021-00 - Station Building - Edgware Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19883	ACTIVE	N	N021-00-1/411	Store - Station Building - Edgware Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8261	ACTIVE	N	N021-00-1/412	Store - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
19908	ACTIVE	N	N021-00-1/412/DOR-01	Door - 1 - Store - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Panels on Door - Supalux					
8262	ACTIVE	N	N021-00-1/413	Store - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
19448	ACTIVE	N	N021-00-1/413/DOR-01	Door - 1 - Store - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Panels on Door - Supalux					
8263	ACTIVE	N	N021-00-1/414	CER - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
19909	INACTIVE	N	N021-00-1/414	CER - Station Building - Edgware Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8264	ACTIVE	N	N021-00-1/415	Store - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
19910	INACTIVE	N	N021-00-1/415	Store - Station Building - Edgware Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8265	ACTIVE	N	N021-00-1/416	Toilet: Male - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
19305	ACTIVE	N	N021-00-1/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Edgware Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				YES	
19911	ACTIVE	N	N021-00-1/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
8266	ACTIVE	N	N021-00-1/417	Toilet: Female - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
8267	ACTIVE	N	N021-00-1/418	Toilet: Unisex - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
44457	ACTIVE	N	N021-00-1/446	Bicycle Shed - Station Building - Edgware Stn		Asbestos	Room: Surveyed – No Known Asbestos									
8269	ACTIVE	N	N021-00-1/451	Tenancy - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N021-00 - Station Building - Edgware Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19914	ACTIVE	N	N021-00-1/451/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Edgware Stn	No Access	Asbestos	No Access: Presumed				No access above false ceiling					
8270	ACTIVE	N	N021-00-1/452	Disused Room - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19915	INACTIVE	N	N021-00-1/452	Disused Room - Station Building - Edgware Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Tenancy					
8271	ACTIVE	N	N021-00-1/453	Disused Room - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19916	INACTIVE	N	N021-00-1/453	Disused Room - Station Building - Edgware Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Tenancy					
8272	ACTIVE	N	N021-00-1/601	Stairs: Linear - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19917	INACTIVE	N	N021-00-1/601	Stairs: Linear - Station Building - Edgware Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8273	ACTIVE	N	N021-00-1/602	Stairs: Linear - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19450	INACTIVE	N	N021-00-1/602	Stairs: Linear - Station Building - Edgware Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8274	ACTIVE	N	N021-00-1/603	Stairs: Linear - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19918	INACTIVE	N	N021-00-1/603	Stairs: Linear - Station Building - Edgware Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8275	ACTIVE	N	N021-00-1/604	Stairs: Linear - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Asbestos Free									
19919	ACTIVE	N	N021-00-1/636	Overbridge - Station Building - Edgware Stn		Asbestos	Room: Surveyed - No Known Asbestos				No Asbestos Visible					
8276	ACTIVE	N	N021-00-1/661	Switch Room - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19884	INACTIVE	N	N021-00-1/661	Switch Room - Station Building - Edgware Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
45413	ACTIVE	N	N021-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Edgware Stn	Other Electrical Boxes	Asbestos	Presumed				4x Transformer - Presumed asbestos materials within Reinspected 17-03-2023		3			
45412	INACTIVE	N	N021-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Edgware Stn		Asbestos	Presumed				3x Transformers - Presumed asbestos materials within					



# Hazardous Material Asset Register - Summary



## N021-00 - Station Building - Edgware Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44861	ACTIVE	N	N021-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Edgware Stn	Isolator Switches	Asbestos	Strongly Presumed				2x Combination Switches - Strongly presumed asbestos materials within Reinspected 17-03-2023		2		N	N
44862	ACTIVE	N	N021-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Edgware Stn	Isolator Switches	Asbestos	Strongly Presumed				10x Combination Switches - Strongly presumed asbestos materials within Reinspected 17-03-2023		10		N	N
44863	ACTIVE	N	N021-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Edgware Stn	Isolator Switches	Asbestos	Strongly Presumed				4x Combination Switches - Strongly presumed asbestos materials within Reinspected 17-03-2023		4		N	N
8278	ACTIVE	N	N021-00-1/731	CER - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19682	INACTIVE	N	N021-00-1/731	CER - Station Building - Edgware Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8279	ACTIVE	N	N021-00-1/746	SCR - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19921	ACTIVE	N	N021-00-1/746	SCR - Station Building - Edgware Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8280	ACTIVE	N	N021-00-1/761	Disused Room - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
8281	ACTIVE	N	N021-00-1/776	Equipment Room - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19495	INACTIVE	N	N021-00-1/776	Equipment Room - Station Building - Edgware Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8282	ACTIVE	N	N021-00-1/801	Office - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19503	ACTIVE	N	N021-00-1/801/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Edgware Stn	Void	Asbestos	No Access: Presumed				No Access 3m+ High				YES	
19964	ACTIVE	N	N021-00-1/801/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Acoustic Panels					
8283	ACTIVE	N	N021-00-1/802	Office - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19965	ACTIVE	N	N021-00-1/802/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Acoustic Panels					
19966	ACTIVE	N	N021-00-1/802/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Edgware Stn	Void	Asbestos	No Access: Presumed				No Access 3m+ High				YES	
8284	ACTIVE	N	N021-00-1/803	Office - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									



# Hazardous Material Asset Register - Summary



## N021-00 - Station Building - Edgware Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19684	ACTIVE	N	N021-00-1/803/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Edgware Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above False Ceiling				YES	
19967	ACTIVE	N	N021-00-1/803/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Acoustic Panels					
8285	ACTIVE	N	N021-00-1/804	Office - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
19968	ACTIVE	N	N021-00-1/804/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Acoustic Panel, Boxing Wood					
19504	ACTIVE	N	N021-00-1/804/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Edgware Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above False Ceiling				YES	
8287	ACTIVE	N	N021-00-2/081	Lobby - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
19443	ACTIVE	N	N021-00-2/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Edgware Stn	Void	Asbestos	Surveyed – Not Detected				Corrugated Sheets; Breeze Block Walls; Metal Support, Plastic Cable above False Ceiling				YES	
19971	ACTIVE	N	N021-00-2/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Acoustic Panel. Tile 'Ceramaguard'					
8288	ACTIVE	N	N021-00-2/082	Lobby - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
19972	ACTIVE	N	N021-00-2/082/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
19505	ACTIVE	N	N021-00-2/082/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Edgware Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard				YES	
8289	ACTIVE	N	N021-00-2/083	Lobby - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19973	INACTIVE	N	N021-00-2/083	Lobby - Station Building - Edgware Stn	No Access	Asbestos	Surveyed – Not Detected				NAD 26/02/2016					
8290	ACTIVE	N	N021-00-2/131	LEER - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Asbestos Free									
8291	ACTIVE	N	N021-00-2/132	LEER - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Asbestos Free									
8292	ACTIVE	N	N021-00-2/261	Platform 1 - Northbound Main - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – Asbestos Known									
19974	ACTIVE	N	N021-00-2/261	Platform 1 - Northbound Main - Station Building - Edgware Stn	Cable Ducts: Cement	Asbestos	Known				Cable ducts 2 x 100mm under nosing at buffer stop end - Chrysotile Reinspected 17-03-2023 (No access to inspect closely as track area)		2			



# Hazardous Material Asset Register - Summary



## N021-00 - Station Building - Edgware Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8293	ACTIVE	N	N021-00-2/262	Platform 2 - Northbound Local Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – Asbestos Known									
19975	ACTIVE	N	N021-00-2/262	Platform 2 - Northbound Local Station Building - Edgware Stn	Cable: Sheath	Asbestos	Strongly Presumed				3x 10mm Cable nr Signal Box Reinspected 17-03-2023		3			
25835	ACTIVE	N	N021-00-2/262	Platform 2 - Northbound Local Station Building - Edgware Stn	Other Electrical Boxes	Asbestos	Presumed				Signal Cabinet - presumed insulating materials Reinspected 17-03-2023		1			
25836	ACTIVE	N	N021-00-2/262	Platform 2 - Northbound Local Station Building - Edgware Stn	Other Electrical Boxes	Asbestos	Removed				2x Boxes - Insulation within		2			
8294	ACTIVE	N	N021-00-2/263	Platform 3 - Southbound Local Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
19808	ACTIVE	N	N021-00-2/263	Platform 3 - Southbound Local Station Building - Edgware Stn	Cable: Sheath	Asbestos	Strongly Presumed				3x 10mm Cable nr Signal Box Reinspected 17-03-2023		3			
25837	ACTIVE	N	N021-00-2/263	Platform 3 - Southbound Local Station Building - Edgware Stn	Westing house Boxes	Asbestos	Presumed				3x Westinghouse boxes on brick wall Not inspected within as no electrician present in 2023 reinspection		3			
25838	ACTIVE	N	N021-00-2/263	Platform 3 - Southbound Local Station Building - Edgware Stn	Other Electrical Boxes	Asbestos	Presumed				Signal cabinet presumed to contain asbestos Not inspected within as no electrician present during 2023 reinspection. Reinspected 17-03-2023					
8295	ACTIVE	N	N021-00-2/316	Locker Room - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19685	INACTIVE	N	N021-00-2/316	Locker Room - Station Building - Edgware Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction - Portacabin					
8296	ACTIVE	N	N021-00-2/317	Locker Room - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19976	ACTIVE	N	N021-00-2/317	Locker Room - Station Building - Edgware Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction - Portacabin					
19977	INACTIVE	N	N021-00-2/317	Locker Room - Station Building - Edgware Stn	Debris: Cement	Asbestos	Removed				Cement debris external 2/317 by fencing					
8297	ACTIVE	N	N021-00-2/331	Mess Room - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
19506	ACTIVE	N	N021-00-2/331	Mess Room - Station Building - Edgware Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LU Heater - Foam insulation Board					
19978	ACTIVE	N	N021-00-2/331	Mess Room - Station Building - Edgware Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					



# Hazardous Material Asset Register - Summary



## N021-00 - Station Building - Edgware Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19980	ACTIVE	N	N021-00-2/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Edgware Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard				YES	
19979	ACTIVE	N	N021-00-2/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard					
8300	ACTIVE	N	N021-00-2/411	Store - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19686	INACTIVE	N	N021-00-2/411	Store - Station Building - Edgware Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8301	ACTIVE	N	N021-00-2/412	Store - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19983	INACTIVE	N	N021-00-2/412	Store - Station Building - Edgware Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8302	ACTIVE	N	N021-00-2/413	Store - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19984	INACTIVE	N	N021-00-2/413	Store - Station Building - Edgware Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8303	ACTIVE	N	N021-00-2/414	Store - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19985	INACTIVE	N	N021-00-2/414	Store - Station Building - Edgware Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8304	ACTIVE	N	N021-00-2/416	Toilet: Unisex - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19508	ACTIVE	N	N021-00-2/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Acoustic Panels					
19986	ACTIVE	N	N021-00-2/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Edgware Stn	Void	Asbestos	Surveyed - Not Detected				Corrugated Steel Roof; Breeze Block, Concrete, Plaster Walls; Fibreglass packing infill by beams, Plastic Cables above False Ceiling				YES	
8305	ACTIVE	N	N021-00-2/417	Toilet: Unisex - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19987	INACTIVE	N	N021-00-2/417	Toilet: Unisex - Station Building - Edgware Stn	LUL Heaters	Asbestos	Surveyed - Not Detected									
8307	ACTIVE	N	N021-00-2/661	LEER - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Asbestos Free									



# Hazardous Material Asset Register - Summary



## N021-00 - Station Building - Edgware Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8308	ACTIVE	N	N021-00-2/706	IMR - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8309	ACTIVE	N	N021-00-2/707	IMR - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8310	ACTIVE	N	N021-00-2/731	CER - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
19306	INACTIVE	N	N021-00-2/731	CER - Station Building - Edgware Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8311	INACTIVE	N	N021-00-2/761	Auto Kiosk - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19426	ACTIVE	N	N021-00-2/761	Auto Kiosk - Station Building - Edgware Stn	No Access	Asbestos	Room: Surveyed – No Known Asbestos				Green Booth on platform					
8312	ACTIVE	N	N021-00-2/786	Switch Room - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
20031	ACTIVE	N	N021-00-2/786/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Edgware Stn	Isolator Switches	Asbestos	Strongly Presumed				Electrical Boxes Not inspected within as no electrician present during 2023 reinspection.		1			
8313	ACTIVE	N	N021-00-2/787	Switch Room - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20033	ACTIVE	N	N021-00-2/787/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Edgware Stn	Void	Asbestos	No Access: Presumed				Sealed No Access above, presumed same structure as adjacent rooms				YES	
20032	ACTIVE	N	N021-00-2/787/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Supalux					
19887	ACTIVE	N	N021-00-2/787/FLR-01	Floor - 1 - Switch Room - Station Building - Edgware Stn	Void	Asbestos	Surveyed – Not Detected				Metal CMS, Plastic Cables beneath Metal Cased Floor Tiles					YES
20222	ACTIVE	N	N021-00-2/787/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Edgware Stn	Isolator Switches	Asbestos	Strongly Presumed				1x Blue Iron clad isolators Not inspected within as no electrician present during 2023 reinspection.		1			
8314	ACTIVE	N	N021-00-2/801	Training Room - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20035	ACTIVE	N	N021-00-2/801/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Edgware Stn	Void	Asbestos	Surveyed – Not Detected				Corrugated Steel Roof; Breeze Block, Concrete, Plaster Walls; Fibreglass packing infill by beams, Plastic Cables above False Ceiling				YES	



# Hazardous Material Asset Register - Summary



## N021-00 - Station Building - Edgware Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20034	ACTIVE	N	N021-00-2/801/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Acoustic Panel. Tile 'Ceramaguard'					
8315	ACTIVE	N	N021-00-2/802	SCR - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20036	ACTIVE	N	N021-00-2/802/CLG-01	Ceiling: Suspended - 1 - SCR - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Acoustic Panel. Tile 'Ceramaguard'					
20037	ACTIVE	N	N021-00-2/802/CLG-01	Ceiling: Suspended - 1 - SCR - Station Building - Edgware Stn	Void	Asbestos	Surveyed – Not Detected				Corrugated Steel Roof; Breeze Block, Concrete, Plaster Walls; Fibreglass packing infill by beams, Plastic Cables above False Ceiling				YES	
8316	ACTIVE	N	N021-00-2/803	Training Room - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20223	ACTIVE	N	N021-00-2/803/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Edgware Stn	Void	Asbestos	Surveyed – Not Detected				Corrugated Steel Roof, Wooden Panel; Breeze Block, Concrete, Plaster Walls; Fibreglass packing infill by beams, Plastic Cables; W3 Cast iron down pipes, to floor in plasterboard/wood boxing above False Ceiling.				YES	
20038	ACTIVE	N	N021-00-2/803/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Acoustic Panel.					
20039	ACTIVE	N	N021-00-2/803/FLR-01	Floor - 1 - Office - Station Building - Edgware Stn	Void	Asbestos	Surveyed – Not Detected				Metal CMS, Plastic Cables; Metal Cased Floor Tiles beneath Solid Concrete & PVC					YES
20040	ACTIVE	N	N021-00-2/803/FLR-02	Floor - 2 - Office - Station Building - Edgware Stn	Void	Asbestos	Surveyed – Not Detected				Metal CMS, Plastic Cables; Metal Cased Floor Tiles beneath Solid Concrete & PVC					YES
8317	ACTIVE	N	N021-00-2/804	SCR - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
20042	ACTIVE	N	N021-00-2/804/CLG-01	Ceiling: Solid - 1 - SCR - Station Building - Edgware Stn	Void	Asbestos	Surveyed – Not Detected				Corrugated Steel Roof, Wooden Panel; Breeze Block, Concrete, Plaster Walls; Fibreglass packing infill by beams, Plastic Cables above Acoustic Panel				YES	
20041	ACTIVE	N	N021-00-2/804/CLG-01	Ceiling: Solid - 1 - SCR - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Acoustic Panel.					
8318	ACTIVE	N	N021-00-2/805	Store - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
20043	ACTIVE	N	N021-00-2/805/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Edgware Stn	Void	Asbestos	No Access: Presumed				Above Acoustic Panel				YES	
19732	ACTIVE	N	N021-00-2/805/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Acoustic Panel.					
8319	ACTIVE	N	N021-00-2/902	Toilet: Unisex - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									



# Hazardous Material Asset Register - Summary



## N021-00 - Station Building - Edgware Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20045	ACTIVE	N	N021-00-2/902/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Edgware Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard				YES	
20044	ACTIVE	N	N021-00-2/902/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
8320	ACTIVE	N	N021-00-2/903	Toilet: Unisex - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
19215	ACTIVE	N	N021-00-2/903/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Edgware Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
20046	ACTIVE	N	N021-00-2/903/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Edgware Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard				YES	
8321	ACTIVE	N	N021-00-2/952	Disused Room - Station Building - Edgware Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N022-04 - P Way Accommodation - Edgware To Burnt Oak

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8333	ACTIVE	N	N022-04-0/661	Equipment Room - P Way Accommodation - Edgware To Burnt Oak	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N023-00 - Station Building - Burnt Oak Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8335	ACTIVE	N	N023-00-1/001	Booking Hall - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19753	ACTIVE	N	N023-00-1/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Burnt Oak Stn	Void	Asbestos	Surveyed – Not Detected				Tiles, Wooden Struts, Water Tank, Fibreglass Lagging above False Ceiling				YES	
8336	ACTIVE	N	N023-00-1/011	Ticket Office - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19367	ACTIVE	N	N023-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Burnt Oak Stn	Void	Asbestos	Surveyed – Not Detected				All Concrete & Render; W4 Breeze Block & Render; W1 New cement block w/t cables passing through - above Polystyrene Tiles				YES	
19754	ACTIVE	N	N023-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Burnt Oak Stn	Void	Asbestos	Surveyed – Not Detected				Solid Concrete beneath Computer Flooring					YES
8337	ACTIVE	N	N023-00-1/021	POM - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N023-00 - Station Building - Burnt Oak Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19670	ACTIVE	N	N023-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Burnt Oak Stn	Void	Asbestos	No Access: Presumed				Beneath false wooden floor					YES
8338	ACTIVE	N	N023-00-1/031	Mess Room - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19756	ACTIVE	N	N023-00-1/031	Mess Room - Station Building - Burnt Oak Stn	LUL Heaters	Asbestos	Surveyed - Not Detected				Heater - Foam Board Insulation					
19755	ACTIVE	N	N023-00-1/031/WAL-002	Wall: Internal - 2 - Mess Room - Station Building - Burnt Oak Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Boarding					
8339	ACTIVE	N	N023-00-1/037	Toilet: Unisex - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19757	ACTIVE	N	N023-00-1/037	Toilet: Unisex - Station Building - Burnt Oak Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Room					
8340	ACTIVE	N	N023-00-1/071	Circulation Area - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19758	ACTIVE	N	N023-00-1/071	Circulation Area - Station Building - Burnt Oak Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8341	ACTIVE	N	N023-00-1/081	Lobby - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19759	ACTIVE	N	N023-00-1/081/FLR-01	Floor - 1 - Lobby - Station Building - Burnt Oak Stn	Void	Asbestos	No Access: Presumed				Beneath false wooden floor					YES
8342	ACTIVE	N	N023-00-1/281	Station Supervisor Office - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19760	ACTIVE	N	N023-00-1/281	Station Supervisor Office - Station Building - Burnt Oak Stn	LUL Heaters	Asbestos	Surveyed - Not Detected				Heater - Foam Board Insulation					
19368	ACTIVE	N	N023-00-1/281/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Burnt Oak Stn	Void	Asbestos	No Access: Presumed				Above Polystyrene Tiles				YES	
8343	ACTIVE	N	N023-00-1/331	Mess Room - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19762	ACTIVE	N	N023-00-1/331	Mess Room - Station Building - Burnt Oak Stn	LUL Heaters	Asbestos	Surveyed - Not Detected				Heater - Foam Board Insulation					
19761	ACTIVE	N	N023-00-1/331	Mess Room - Station Building - Burnt Oak Stn		Asbestos	Surveyed - Not Detected				Acoustic Panel below sink					
19763	ACTIVE	N	N023-00-1/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Burnt Oak Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Polystyrene Tiles				YES	



# Hazardous Material Asset Register - Summary



## N023-00 - Station Building - Burnt Oak Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8344	ACTIVE	N	N023-00-1/406	Store - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19764	ACTIVE	N	N023-00-1/406	Store - Station Building - Burnt Oak Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8345	ACTIVE	N	N023-00-1/407	Store - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19765	ACTIVE	N	N023-00-1/407	Store - Station Building - Burnt Oak Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8346	ACTIVE	N	N023-00-1/417	Toilet: Disabled - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19671	ACTIVE	N	N023-00-1/417	Toilet: Disabled - Station Building - Burnt Oak Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
8347	ACTIVE	N	N023-00-1/451	Tenancy - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19369	ACTIVE	N	N023-00-1/451/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Burnt Oak Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
19766	ACTIVE	N	N023-00-1/451/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Burnt Oak Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	
8348	ACTIVE	N	N023-00-1/453	Disused Room - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19878	ACTIVE	N	N023-00-1/453	Disused Room - Station Building - Burnt Oak Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8349	ACTIVE	N	N023-00-1/481	Switch Cupboard - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19767	ACTIVE	N	N023-00-1/481	Switch Cupboard - Station Building - Burnt Oak Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8350	ACTIVE	N	N023-00-1/576	Stairs: Linear - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19768	ACTIVE	N	N023-00-1/576	Stairs: Linear - Station Building - Burnt Oak Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8351	ACTIVE	N	N023-00-1/577	Stairs: Linear - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19769	ACTIVE	N	N023-00-1/577	Stairs: Linear - Station Building - Burnt Oak Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N023-00 - Station Building - Burnt Oak Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8352	ACTIVE	N	N023-00-1/601	Stairs: Linear - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19770	ACTIVE	N	N023-00-1/601	Stairs: Linear - Station Building - Burnt Oak Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8353	ACTIVE	N	N023-00-1/602	Stairs: Linear - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19370	ACTIVE	N	N023-00-1/602	Stairs: Linear - Station Building - Burnt Oak Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
19672	ACTIVE	N	N023-00-1/636	Overbridge - Station Building - Burnt Oak Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8354	ACTIVE	N	N023-00-1/747	SCR - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19771	ACTIVE	N	N023-00-1/747	SCR - Station Building - Burnt Oak Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
8355	ACTIVE	N	N023-00-2/261	Platform 1 - Northbound Local - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19773	ACTIVE	N	N023-00-2/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Burnt Oak Stn	Rope Gaskets	Asbestos	Surveyed – Not Detected				No Asbestos in Glazing Rope					
19802	ACTIVE	N	N023-00-2/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Burnt Oak Stn	Void	Asbestos	Surveyed – Not Detected				Beneath Manholes except 4 & 5					YES
19772	ACTIVE	N	N023-00-2/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Burnt Oak Stn	Void	Asbestos	No Access: Presumed				Beneath Manholes 4 & 5					YES
8356	ACTIVE	N	N023-00-2/262	Platform 2 - Southbound Local - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19775	ACTIVE	N	N023-00-2/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - Burnt Oak Stn	Rope Gaskets	Asbestos	Surveyed – Not Detected				No Asbestos in Glazing Rope					
19774	ACTIVE	N	N023-00-2/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Burnt Oak Stn	Void	Asbestos	Surveyed – Not Detected				Beneath Manholes except 4 & 5					YES
19371	ACTIVE	N	N023-00-2/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Burnt Oak Stn	Void	Asbestos	No Access: Presumed				Beneath Manholes 4 & 5					YES
8357	ACTIVE	N	N023-00-2/401	Bin Store - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19673	ACTIVE	N	N023-00-2/401/CLG-01	Ceiling: Solid - 1 - Bin Store - Station Building - Burnt Oak Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					



# Hazardous Material Asset Register - Summary



## N023-00 - Station Building - Burnt Oak Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19776	ACTIVE	N	N023-00-2/401/CLG-01	Ceiling: Solid - 1 - Bin Store - Station Building - Burnt Oak Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard				YES	
8358	ACTIVE	N	N023-00-2/411	Store - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19777	ACTIVE	N	N023-00-2/411/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Burnt Oak Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard					
19372	ACTIVE	N	N023-00-2/411/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Burnt Oak Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard				YES	
8359	ACTIVE	N	N023-00-2/436	Waiting Room - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19778	ACTIVE	N	N023-00-2/436	Waiting Room - Station Building - Burnt Oak Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Room					
8360	ACTIVE	N	N023-00-2/661	Switch Cupboard - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19382	ACTIVE	N	N023-00-2/661	Switch Cupboard - Station Building - Burnt Oak Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Room					
8361	ACTIVE	N	N023-00-2/662	Switch Room - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19822	ACTIVE	N	N023-00-2/662	Switch Room - Station Building - Burnt Oak Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Room					
8362	ACTIVE	N	N023-00-2/711	Relay Room - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
8363	ACTIVE	N	N023-00-2/731	CER - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19824	ACTIVE	N	N023-00-2/731	CER - Station Building - Burnt Oak Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Boxing					
19823	ACTIVE	N	N023-00-2/731/FLR-01	Floor - 1 - CER - Station Building - Burnt Oak Stn	Void	Asbestos	No Access: Presumed				Beneath False Floor					YES
8364	ACTIVE	N	N023-00-2/761	Equipment Room - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19827	ACTIVE	N	N023-00-2/761/CLG-01	Ceiling: Solid - 1 - Equipment Room - Station Building - Burnt Oak Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard					
19384	ACTIVE	N	N023-00-2/761/CLG-01	Ceiling: Solid - 1 - Equipment Room - Station Building - Burnt Oak Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard				YES	



# Hazardous Material Asset Register - Summary



## N023-00 - Station Building - Burnt Oak Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19674	ACTIVE	N	N023-00-2/761/FLR-01	Floor - 1 - Equipment Room - Station Building - Burnt Oak Stn	Void	Asbestos	No Access: Presumed				Beneath wooden floor					YES
8365	ACTIVE	N	N023-00-2/951	Store - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19383	ACTIVE	N	N023-00-2/951	Store - Station Building - Burnt Oak Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8366	ACTIVE	N	N023-00-2/952	Disused Room - Station Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19825	ACTIVE	N	N023-00-2/952	Disused Room - Station Building - Burnt Oak Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					

## N025-00 - Station Building - Colindale Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8368	ACTIVE	N	N025-00-1/001	Booking Hall - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
46516	ACTIVE	N	N025-00-1/001	Booking Hall - Station Building - Colindale Stn	Boarding: Supalux	Asbestos	Sampled - Not Detected				Supalux panel and wood to wall between 1/081 and 1/452 - 3m <sup>2</sup>	3		R647076 Rev3		
46512	ACTIVE	N	N025-00-1/001	Booking Hall - Station Building - Colindale Stn	Boarding: Supalux	Asbestos	Sampled - Not Detected				Supalux panel above door to 1/661 - 1no.x<1m <sup>2</sup>	1	1	R647076 Rev3		
19245	ACTIVE	N	N025-00-1/001	Booking Hall - Station Building - Colindale Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
46513	ACTIVE	N	N025-00-1/001	Booking Hall - Station Building - Colindale Stn	Boarding: Supalux	Asbestos	Sampled - Not Detected				Supalux panel above door to 1/746 - 1no.x<1m <sup>2</sup>	1	1	R647076 Rev3		
46514	ACTIVE	N	N025-00-1/001	Booking Hall - Station Building - Colindale Stn	Boarding: Supalux	Asbestos	Sampled - Not Detected				Supalux panel above door to 1/081 - 1no.x<1m <sup>2</sup>	1	1	R647076 Rev3		
46517	ACTIVE	N	N025-00-1/001	Booking Hall - Station Building - Colindale Stn	Mastic	Asbestos	Sampled - Not Detected				Putty to metal window - Throughout			R647076 Rev3		
46515	ACTIVE	N	N025-00-1/001	Booking Hall - Station Building - Colindale Stn	Boarding: Supalux	Asbestos	Sampled - Not Detected				Supalux panel above door to 1/406 - 1no.x<1m <sup>2</sup>	1	1	R647076 Rev3		
46511	ACTIVE	N	N025-00-1/001/CLG-01	Ceiling: Suspended - 1 - Booking Hall - Station Building - Colindale Stn	Boarding: Supalux	Asbestos	Sampled - Not Detected				Supalux ceiling tiles on metal/ wooden framework to suspended ceiling - 16no.x6m <sup>2</sup>	6	16	R647076 Rev3		
8369	ACTIVE	N	N025-00-1/011	Ticket Office - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19628	ACTIVE	N	N025-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Colindale Stn	Void	Asbestos	No Access: Presumed				Beneath Lino - False Wooden Floor					YES



# Hazardous Material Asset Register - Summary



## N025-00 - Station Building - Colindale Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8370	ACTIVE	N	N025-00-1/021	POM - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19247	ACTIVE	N	N025-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Colindale Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Ceiling Tiles					
19246	ACTIVE	N	N025-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Colindale Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Ceiling Tiles					
19630	ACTIVE	N	N025-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Colindale Stn	Void	Asbestos	Surveyed - Not Detected				Terracotta, Wood, Concrete above False Ceiling				YES	
46518	ACTIVE	N	N025-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Colindale Stn	Boarding: Supalux	Asbestos	Sampled - Not Detected				Supalux ceiling tiles on metal/ wooden framework to suspended ceiling - 8no.x6m <sup>2</sup>	6	8	R647076 Rev3		
19629	ACTIVE	N	N025-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Colindale Stn	Void	Asbestos	No Access: Presumed				Beneath Lino - False Wooden Floor					YES
8371	ACTIVE	N	N025-00-1/031	Mess Room - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19631	ACTIVE	N	N025-00-1/031	Mess Room - Station Building - Colindale Stn		Asbestos	Surveyed - Not Detected				Acoustic Panel below sink					
19874	ACTIVE	N	N025-00-1/031/FLR-01	Floor - 1 - Mess Room - Station Building - Colindale Stn	Void	Asbestos	No Access: Presumed				Beneath Lino - False Wooden Floor					YES
46519	ACTIVE	N	N025-00-1/031/SNK-01	Sink - 1 - Mess Room - Station Building - Colindale Stn	Bitumen	Asbestos	Sampled - Not Detected				Acoustic panel below sink to wall 2 - 2no.		2	R647076 Rev3		
8372	ACTIVE	N	N025-00-1/036	Toilet: Unisex - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19242	ACTIVE	N	N025-00-1/036/FLR-01	Floor - 1 - Toilet - Station Building - Colindale Stn	Void	Asbestos	No Access: Presumed				Beneath Lino - False Wooden Floor					YES
8373	ACTIVE	N	N025-00-1/071	Circulation Area - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19632	ACTIVE	N	N025-00-1/071	Circulation Area - Station Building - Colindale Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8374	ACTIVE	N	N025-00-1/081	Lobby - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19633	ACTIVE	N	N025-00-1/081/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Colindale Stn	Glazing Rope	Asbestos	Surveyed - Not Detected				No Rope in Skylight					
8375	ACTIVE	N	N025-00-1/082	Lobby - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N025-00 - Station Building - Colindale Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46520	ACTIVE	N	N025-00-1/082	Lobby - Station Building - Colindale Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux ceiling tiles on fixed metal/ wooden framework to suspended ceiling - 4m²	4		R647076 Rev3		
19635	ACTIVE	N	N025-00-1/082/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Colindale Stn	Void	Asbestos	Surveyed – Not Detected				Terracotta, Wood, Concrete above False Ceiling				YES	
19634	ACTIVE	N	N025-00-1/082/FLR-01	Floor - 1 - Lobby - Station Building - Colindale Stn	Void	Asbestos	No Access: Presumed				Beneath Vinyl - False Wooden Floor					YES
8376	ACTIVE	N	N025-00-1/201	Passage - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19637	INACTIVE	N	N025-00-1/201	Passage - Station Building - Colindale Stn	Boarding: AIB	Asbestos	Removed				External Cladding Boarding to underside of overbridge - Amosite 3lm- This item now removed under HM00016 by DCUK on 21/08/2021	3			N	N
19638	ACTIVE	N	N025-00-1/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Colindale Stn	Void	Asbestos	Surveyed – Not Detected				Roof Tiles, Fascia Soffit, Rain Water Guttering above Wooden Ceiling				YES	
19636	ACTIVE	N	N025-00-1/201/FLR-01	Floor - 1 - Passage - Station Building - Colindale Stn	Void	Asbestos	Surveyed – Not Detected				Void: Wood - Hardboard					YES
8377	ACTIVE	N	N025-00-1/281	Station Supervisor Office - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19248	ACTIVE	N	N025-00-1/281	Station Supervisor Office - Station Building - Colindale Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard - Walls					
19420	ACTIVE	N	N025-00-1/281/CLG-01	Ceiling: Solid - 1 - Station Supervisor Office - Station Building - Colindale Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard				YES	
19639	ACTIVE	N	N025-00-1/281/CLG-01	Ceiling: Solid - 1 - Station Supervisor Office - Station Building - Colindale Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
8378	ACTIVE	N	N025-00-1/316	Locker Room - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19640	ACTIVE	N	N025-00-1/316	Locker Room - Station Building - Colindale Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8379	ACTIVE	N	N025-00-1/406	Store - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19616	ACTIVE	N	N025-00-1/406	Store - Station Building - Colindale Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8380	ACTIVE	N	N025-00-1/407	Store - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19249	ACTIVE	N	N025-00-1/407	Store - Station Building - Colindale Stn	Cable Duct: Other	Asbestos	No Access: Presumed				Possible redundant cable duct encapsulated below Lino. Re- Inspected 08/07/2014 - Not Found					



# Hazardous Material Asset Register - Summary



## N025-00 - Station Building - Colindale Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8381	ACTIVE	N	N025-00-1/416	Toilet: Unisex - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19641	ACTIVE	N	N025-00-1/416/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Colindale Stn	Glazing Rope	Asbestos	Surveyed - Not Detected				No Rope in Skylight					
8382	ACTIVE	N	N025-00-1/446	Bicycle Shed - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
46521	ACTIVE	N	N025-00-1/446	Bicycle Shed - Station Building - Colindale Stn	Bitumen	Asbestos	Sampled - Not Detected				Bitumen damp proof course to base of walls - 8m throughout	8		R647076 Rev3		
19642	ACTIVE	N	N025-00-1/446	Bicycle Shed - Station Building - Colindale Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8383	ACTIVE	N	N025-00-1/451	Tenancy - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19643	ACTIVE	N	N025-00-1/451	Tenancy - Station Building - Colindale Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access - Tenancy					
8384	ACTIVE	N	N025-00-1/452	Mess Room - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19688	ACTIVE	N	N025-00-1/452	Mess Room - Station Building - Colindale Stn	LUL Heaters	Asbestos	Surveyed - Not Detected				Insulation within Heater - Foam					
19691	ACTIVE	N	N025-00-1/452	Mess Room - Station Building - Colindale Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Boarding within Cupboard					
19690	ACTIVE	N	N025-00-1/452	Mess Room - Station Building - Colindale Stn		Asbestos	Surveyed - Not Detected				Acoustic Panel below sink					
19307	ACTIVE	N	N025-00-1/452/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Colindale Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard					
19689	ACTIVE	N	N025-00-1/452/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Colindale Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above False Ceiling				YES	
19687	ACTIVE	N	N025-00-1/452/FLR-01	Floor - 1 - Mess Room - Station Building - Colindale Stn	Cable Duct: Other	Asbestos	No Access: Presumed				Redundant Cable Duct - Encapsulated. Re inspected 08/07/2014 - The room has since been refurbished					
46522	ACTIVE	N	N025-00-1/452/SNK-01	Sink - 1 - Mess Room - Station Building - Colindale Stn	Bitumen	Asbestos	Sampled - Not Detected				Acoustic panels under sink unit to wall 3 - 2no.		2	R647076 Rev3		
8385	ACTIVE	N	N025-00-1/453	ATM - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
46523	ACTIVE	N	N025-00-1/453	ATM - Station Building - Colindale Stn	Boarding: Supalux	Asbestos	Sampled - Not Detected				Supalux panel to wall 4 - 3m <sup>2</sup>	3		R647076 Rev3		



# Hazardous Material Asset Register - Summary



## N025-00 - Station Building - Colindale Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19692	ACTIVE	N	N025-00-1/453	ATM - Station Building - Colindale Stn	Cable Duct: Other	Asbestos	Presumed				Possible redundant cable duct encapsulated below Lino. (No access 2023 re-inspection. Door way sealed with Supalux)  NO ACCESS DURING 2020 REINSPECTION WITHIN THE ROOM / VOID NOT IN USE AND SEALED UP WITH SUPALUX BOARDING IN MAIN TICKETHALL AREA - SEE PHOTO					
8386	ACTIVE	N	N025-00-1/551	Yard - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
46524	ACTIVE	N	N025-00-1/551	Yard - Station Building - Colindale Stn	Bitumen	Asbestos	Sampled - Not Detected				Bitumen damp proof course to base of brickwork by bike shed - 8m	8		R647076 Rev3		
19693	ACTIVE	N	N025-00-1/551	Yard - Station Building - Colindale Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8387	ACTIVE	N	N025-00-1/601	Stairs: Linear - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19308	ACTIVE	N	N025-00-1/601	Stairs: Linear - Station Building - Colindale Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8388	ACTIVE	N	N025-00-1/602	Stairs: Linear - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19665	ACTIVE	N	N025-00-1/602	Stairs: Linear - Station Building - Colindale Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8389	ACTIVE	N	N025-00-1/661	Switch Room - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19695	ACTIVE	N	N025-00-1/661	Switch Room - Station Building - Colindale Stn	Cable: Wrap	Asbestos	Surveyed - Not Detected				Insulation Tape					
46528	ACTIVE	N	N025-00-1/661	Switch Room - Station Building - Colindale Stn	Boarding: Supalux	Asbestos	Sampled - Not Detected				Supalux panel on concrete slab to ceiling by wall 3 (water leaking from ceiling) - <1m <sup>2</sup>	1		R647076 Rev3		
44348	ACTIVE	N	N025-00-1/661/CLG-01 80892650	Ceiling: Solid - 1 - Switch Room - Station Building - Colindale Stn Ceiling: Solid	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Boarding by light fitting above wall 3 surveyed and is supalux  Panel is supalux in 2020 reinspection however possible cement panel may have been removed historically, possible cement residue could be present		1		N	N
20338	ACTIVE	N	N025-00-1/661/FLR-01	Floor - 1 - Switch Room - Station Building - Colindale Stn	Void	Asbestos	No Access: Presumed				No Access Beneath Hatch in Floor					N



# Hazardous Material Asset Register - Summary



## N025-00 - Station Building - Colindale Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20335	ACTIVE	N	N025-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Colindale Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				4 x Tranformer Boxes by wall 1 No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within		4		N	N
44347	ACTIVE	N	N025-00-1/661/WAL-001 80892646	Wall: Internal - 1 - Switch Room - Station Building - Colindale Stn Wall: Internal	Other Boarding	Asbestos	Presumed				Paxoline boarding to wall 1 Reinspected 17-03-2023 New non acm brown composite panel		1		N	N
20336	ACTIVE	N	N025-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Colindale Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 30amp Switchbox to wall 1 No electrician on site during 2023 reinspection to open box for inspection - therefore cannot score materials within		1		N	N
20337	ACTIVE	N	N025-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Colindale Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 100amp Switch Box to wall 2 No electrician on site during 2023 reinspection to open box for inspection - therefore cannot score material within		1		N	N
46527	ACTIVE	N	N025-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Colindale Stn	Cable: Sheath	Asbestos	Sampled – Not Detected				Cable wrapping to cable (meter box) to wall 2 - 1no. x 2m	2	1	R647076 Rev3		
46525	ACTIVE	N	N025-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Colindale Stn	Cable Ducts: Bitumen	Asbestos	Known				Bitumen cable ducts within cable trench to wall 2 with cables within - 2no. Reinspected 17-03-2023		2	R647076 Rev3		
19694	ACTIVE	N	N025-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Colindale Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes - 5 x 60amp, 1 x 100amp, 3 x 30amp to wall 3 No electrician on site during 2023 reinspection to open box for inspection - therefore cannot score material within		9		N	N
46526	ACTIVE	N	N025-00-1/661/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Colindale Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux panel to wall 4 above door - 1no. x <1m <sup>2</sup>	1	1	R647076 Rev3		
8390	ACTIVE	N	N025-00-1/746	SCR - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46509	ACTIVE	N	N025-00-1/746/CLG-01	Ceiling: Suspended - 1 - SCR - Station Building - Colindale Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Plaster and supalux ceiling tiles on metal framework to fixed suspended ceiling - 4m <sup>2</sup>	4		R647076 Rev03		
19309	ACTIVE	N	N025-00-1/746/CLG-01	Ceiling: Suspended - 1 - SCR - Station Building - Colindale Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Ceiling Tiles					
8391	ACTIVE	N	N025-00-2/081	Lobby - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19697	ACTIVE	N	N025-00-2/081	Lobby - Station Building - Colindale Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
46529	ACTIVE	N	N025-00-2/081/FLR-01	Floor - 1 - Lobby - Station Building - Colindale Stn	Bitumen	Asbestos	Sampled – Not Detected				Asphalt on concrete slab to floor - 10m <sup>2</sup>	10		R647076 Rev3		



# Hazardous Material Asset Register - Summary



## N025-00 - Station Building - Colindale Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8392	ACTIVE	N	N025-00-2/261	Platform 1 - Northbound Local - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44349	ACTIVE	N	N025-00-2/261	Platform 1 - Northbound Local - Station Building - Colindale Stn	Boarding: Cement	Asbestos	Presumed				Corrugated sheeting to both platforms 1 & 2 canopy (top side) Presume rope seals within glazing bars to skylights of platform 1 & 2 canopies throughout. - scaffold required to take sample. Photo DSC05185 Reinspected 17-03-2023				N	N
46532	ACTIVE	N	N025-00-2/261	Platform 1 - Northbound Local - Station Building - Colindale Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Car park side - Supalux panel to platform wall trackside midway - <1m <sup>2</sup>	1		R647076 Rev3		
19700	ACTIVE	N	N025-00-2/261	Platform 1 - Northbound Local - Station Building - Colindale Stn	Isolator Switches	Asbestos	Strongly Presumed				Under Platform Nosing - 2 x Cables to 1/2 Platform terminate in Switch Box Not possible to inspect as on track - PWT-EH needed - (access 2023 was during TH - therefore cannot score material within		1			
46548	ACTIVE	N	N025-00-2/261	Platform 1 - Northbound Local - Station Building - Colindale Stn	Cable: Sheath	Asbestos	Removed				Braided cables to old signal box running from north side of bridge - 3no. x 30m - Removed by DCUK between 08/11/2021- 13/11/2021 under HM00016	30	3	R647076 Rev3		
46550	ACTIVE	N	N025-00-2/261	Platform 1 - Northbound Local - Station Building - Colindale Stn	Cable: Sheath	Asbestos	Strongly Presumed				Braided cables to 2/706 wall end of platform 1 departure end - 2no. Reinspected 17-03-2023		2	R647076 Rev3		
46531	ACTIVE	N	N025-00-2/261	Platform 1 - Northbound Local - Station Building - Colindale Stn	Roofing Tiles	Asbestos	Sampled – Not Detected				Bitumen roof felt under roof tiles to roof of 3/436 - 16m <sup>2</sup>	16		R647076 Rev3		
19666	ACTIVE	N	N025-00-2/261	Platform 1 - Northbound Local - Station Building - Colindale Stn	Cable: Sheath	Asbestos	Removed				3x Braided Cables to signal equipment - attached to underside of Road Bridge crossing Platforms 1 & 2 - Encapsulated - Removed by DCUK between 08/11/2021-13/11/201 under HM00016		3		N	N
46552	ACTIVE	N	N025-00-2/261	Platform 1 - Northbound Local - Station Building - Colindale Stn	Boarding: AIB	Asbestos	Removed				Medium density board to underside of overbridge of Platform 1 canopy adjacent to room 2/081 and 2/761 - 5m Removed 21/08/2021	5		R647076 Rev3		
46554	ACTIVE	N	N025-00-2/261	Platform 1 - Northbound Local - Station Building - Colindale Stn	Cement Cowlings/ Flues	Asbestos	Removed				Cement pipe/sleeve concealed within wall of 2/701 on Platform 1 side - 1no. - Removed by DCUK on 08/11/2021 under HM00016		1	R647076 Rev3		
46551	ACTIVE	N	N025-00-2/261	Platform 1 - Northbound Local - Station Building - Colindale Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Presumed ACM's within old signal lamp to 2/706 wall end of platform 1 departure end - 1no. Reinspected externally 17-03-2023 (No Electrician to inspect internal)		1	R647076 Rev3		



# Hazardous Material Asset Register - Summary



## N025-00 - Station Building - Colindale Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46549	ACTIVE	N	N025-00-2/261	Platform 1 - Northbound Local - Station Building - Colindale Stn	Other Electrical Boxes	Asbestos	Removed				Materials within old signal boxes to north side of bridge wall - 1no. - Removed by DCUK between 8/11/2021 to 13/11/2021 under HM00016		2	R647076 Rev3		
19699	INACTIVE	N	N025-00-2/261	Platform 1 - Northbound Local - Station Building - Colindale Stn	Cable: Sheath	Asbestos	Strongly Presumed				Under Platform Nosing - 2 x Cables to 1/2 Platform terminate in Switch Box  Not possible to inspect as on track - PWT-EH needed - (access 2020 was during TH) - therefore cannot score material within		2			
46530	ACTIVE	N	N025-00-2/261	Platform 1 - Northbound Local - Station Building - Colindale Stn	Roofing Tiles	Asbestos	Sampled – Not Detected				Roof tiles on bitumen on wood to roof of 3/436 - 16m <sup>2</sup>	16		R647076 Rev3		
19698	ACTIVE	N	N025-00-2/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Colindale Stn	Void	Asbestos	Surveyed – Not Detected				No Void beneath concrete; inspection covers - ducts - plastic, ceramic, concrete, pvc cables					YES
8393	ACTIVE	N	N025-00-2/262	Platform 2 - Southbound Local - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46534	ACTIVE	N	N025-00-2/262	Platform 2 - Southbound Local - Station Building - Colindale Stn	Roofing Tiles	Asbestos	Sampled – Not Detected				Bitumen roof felt under roof tiles to roof of 3/436 - 16m <sup>2</sup>	16		R647076 Rev3		
46557	ACTIVE	N	N025-00-2/262	Platform 2 - Southbound Local - Station Building - Colindale Stn	Cable: Sheath	Asbestos	Removed				Braided cables to old signal box running from north side of bridge - 3no. x 30m - Removed by DCUK between 08/11/2021 - 13/11/2021 under HM00016	30	3	R647076 Rev3		
46558	ACTIVE	N	N025-00-2/262	Platform 2 - Southbound Local - Station Building - Colindale Stn	Other Electrical Boxes	Asbestos	Removed				Materials within old signal boxes to north side of bridge wall - 2no. - Removed by DCUK between 08/11/2021 - 13/11/2021 under HM00016		1	R647076 Rev3		
19310	ACTIVE	N	N025-00-2/262	Platform 2 - Southbound Local - Station Building - Colindale Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Southend Platform Ramp - 7 x 15mm & 1 x 35mm white cables  No access during 2023 re-inspection as track access required		8			
46559	INACTIVE	N	N025-00-2/262	Platform 2 - Southbound Local - Station Building - Colindale Stn	Cable: Sheath	Asbestos	Strongly Presumed				Braided cables to 2/706 wall end of platform 1 departure end - 2no.		2	R647076 Rev3		
46560	INACTIVE	N	N025-00-2/262	Platform 2 - Southbound Local - Station Building - Colindale Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Materials within old signal lamp to 2/706 wall end of platform 1 departure end - 1no.  Duplicate of 46551		1	R647076 Rev3		
19702	ACTIVE	N	N025-00-2/262	Platform 2 - Southbound Local - Station Building - Colindale Stn	Westing house Boxes	Asbestos	Strongly Presumed				Platform 2 Southend Platform Ramp - Westhouse Fuse Boxes - Insulation Inside  (NB these may have previously been opened and no asbestos was evident, however unable to trace paperwork to confirm)  No access during 2023 reinspection, track access required		4			



# Hazardous Material Asset Register - Summary



## N025-00 - Station Building - Colindale Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46533	ACTIVE	N	N025-00-2/262	Platform 2 - Southbound Local - Station Building - Colindale Stn	Roofing Tiles	Asbestos	Sampled – Not Detected				Roof tiles on bitumen on wood to roof of 3/436 - 16m <sup>2</sup>	16		R647076 Rev3		
46556	ACTIVE	N	N025-00-2/262	Platform 2 - Southbound Local - Station Building - Colindale Stn	Other Electrical Boxes	Asbestos	Presumed				Platform 2 S/B track side 1 - Materials within 10 core box to platform wall - trackside adjacent to 2/661 - 1no.  No access during 2023 re-inspection. track access required		1	R647076 Rev3		
19703	ACTIVE	N	N025-00-2/262	Platform 2 - Southbound Local - Station Building - Colindale Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Northend Platform Ramp - 7x15mm & 1 x 35mm Cables - Cable Run off along Plt 2 & Cable Run over Track; 4x 35mm Cables - into penetration into IMR  Not closely inspected as beyond platform ramp 17-03-2023		12			
46555	ACTIVE	N	N025-00-2/262	Platform 2 - Southbound Local - Station Building - Colindale Stn	Cable: Sheath	Asbestos	Presumed				Trackside Platform 2 S/B track grounds - Braided cables within cable run composite retaining wall and road bridge - 3no. Small, 1no. large - 3no. small cable Removed by DCUK between 08/11/2021 - 13/11/2021 under HM00016 - one active cable remain on cable run		4	R647076 Rev3		
19704	ACTIVE	N	N025-00-2/262	Platform 2 - Southbound Local - Station Building - Colindale Stn	Westing house Boxes	Asbestos	Presumed				Platform 2 Northend Platform Ramp - Westhouse Fuse Boxes - Insulation Inside Possible removed check at next inspection  No electrician on site during 2023 reinspection to open boxes - therefore cannot score material within. Also track access required with PWT-EH.  1x 10 core present to IMR external wall by OTX structure on ramp at platform 2 at north end.		3		N	N
19701	ACTIVE	N	N025-00-2/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Colindale Stn	Void	Asbestos	Surveyed – Not Detected				No Void beneath concrete; inspection covers - ducts - plastic, ceramic, concrete, pvc cables					YES
8394	ACTIVE	N	N025-00-2/411	Store - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19705	ACTIVE	N	N025-00-2/411/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Colindale Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Ceiling					
46535	ACTIVE	N	N025-00-2/411/FLR-01	Floor - 1 - Store - Station Building - Colindale Stn	Bitumen	Asbestos	Sampled – Not Detected				Asphalt on concrete slab to floor - 4m <sup>2</sup>	4		R647076 Rev3		
19876	ACTIVE	N	N025-00-2/411/FLR-01	Floor - 1 - Store - Station Building - Colindale Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden floor					YES
8395	ACTIVE	N	N025-00-2/412	Store - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N025-00 - Station Building - Colindale Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19311	ACTIVE	N	N025-00-2/412	Store - Station Building - Colindale Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8396	ACTIVE	N	N025-00-2/413	Store - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19421	ACTIVE	N	N025-00-2/413	Store - Station Building - Colindale Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel on wall					
19667	ACTIVE	N	N025-00-2/413/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Colindale Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
46536	ACTIVE	N	N025-00-2/413/FLR-01	Floor - 1 - Store - Station Building - Colindale Stn	Bitumen	Asbestos	Sampled – Not Detected				Asphalt on concrete slab to floor - 4m <sup>2</sup>	4		R647076 Rev3		
8397	ACTIVE	N	N025-00-2/436	Waiting Room - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19706	ACTIVE	N	N025-00-2/436	Waiting Room - Station Building - Colindale Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Insulation within Heater - Foam					
8398	ACTIVE	N	N025-00-2/661	Switch Room - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19312	ACTIVE	N	N025-00-2/661	Switch Room - Station Building - Colindale Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Boarding & Panel above door - Supalux					
44350	ACTIVE	N	N025-00-2/661	Switch Room - Station Building - Colindale Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer No electrician on site during 2023 reinspection to open box - therefore cannot score material within		1		N	N
46537	ACTIVE	N	N025-00-2/661/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Colindale Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux panel to ceiling - no access above as fixed - 2m <sup>2</sup>	2		R647076 Rev3		
46538	ACTIVE	N	N025-00-2/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Colindale Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux panel to wall 2 - 2m <sup>2</sup>	2		R647076 Rev3		
19707	ACTIVE	N	N025-00-2/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Colindale Stn	Isolator Switches	Asbestos	Strongly Presumed				Combination Switch Box Blue 1 x 30amp to wall 2 No electrician on site during 2023 reinspection to open box - therefore cannot score		1		N	N
44351	ACTIVE	N	N025-00-2/706 80100065	Imr - Station Building - Colindale Room Assets	Other Boarding	Asbestos	Presumed				Paxoline boarding throughout Reinspected 17-03-2023				N	N
43215	ACTIVE	N	N025-00-2/706	Imr - Station Building - Colindale	Cable: Sheath	Asbestos	Strongly Presumed				4 x 35mm Cables within J hanger to wall 3 leading outside to track Reinspected 17-03-2023		4		N	N
43214	INACTIVE	N	N025-00-2/706	Imr - Station Building - Colindale	Cable: Sheath	Asbestos	Strongly Presumed				2No Cables - External wall to IMR - Encapsulated DUPLICATE OF 46551		2		N	N
42335	INACTIVE	N	N025-00-2/706	Imr - Station Building - Colindale	PCBs	Polychlorinated biphenyl	Strongly Presumed				2 x blue cylinder PCB's on paxoline board		2		N	N



# Hazardous Material Asset Register - Summary



## N025-00 - Station Building - Colindale Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8399	ACTIVE	N	N025-00-2/761	CER - Station Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
46539	ACTIVE	N	N025-00-2/761	CER - Station Building - Colindale Stn	Mastic	Asbestos	Sampled - Not Detected				Putty to windows to wall 2 and 4 - 3no. x 2m	2	3	R647076 Rev3		
19710	ACTIVE	N	N025-00-2/761	CER - Station Building - Colindale Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Suplax Panel, Boxing - Plasterboard					
19752	ACTIVE	N	N025-00-2/761/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Colindale Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Ceiling					
46545	ACTIVE	N	N025-00-2/761/FLR-01	Floor - 1 - CER - Station Building - Colindale Stn	Vinyl tiles	Asbestos	Known				Grey floor tile and backing - contaminated with asphalts to floor - 8m <sup>2</sup> Reinspected 17-03-2023	8		R647076 Rev3		
46541	ACTIVE	N	N025-00-2/761/FLR-01	Floor - 1 - CER - Station Building - Colindale Stn	Vinyl tiles	Asbestos	Sampled - Not Detected				Grey floor tiles and backing on new screed on asphalt on concrete slab to floor - 8m <sup>2</sup>	8		R647076 Rev3		
46547	ACTIVE	N	N025-00-2/761/FLR-01	Floor - 1 - CER - Station Building - Colindale Stn	Bitumen	Asbestos	Known				Asphalt on concrete slab to floor under new tiles - 8m <sup>2</sup> Reinspected 17-03-2023	8		R647076 Rev3		
46546	ACTIVE	N	N025-00-2/761/FLR-01	Floor - 1 - CER - Station Building - Colindale Stn	Bitumen	Asbestos	Known				Asphalt on concrete to floor - 8m Reinspected 17-03-2023	8		R647076 Rev3		

## N031-00 - Station Building - Hendon Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8403	ACTIVE	N	N031-00-1/001	Booking Hall - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18212	ACTIVE	N	N031-00-1/001	Booking Hall - Station Building - Hendon Central Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8404	ACTIVE	N	N031-00-1/011	Ticket Office - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
53528	ACTIVE	N	N031-00-1/011	Ticket Office - Station Building - Hendon Central Stn	Glazing Rope	Asbestos	Surveyed - Not Detected				Skylight to roof - New rubber gasket. Only visible from Roof (VC)					
46454	ACTIVE	N	N031-00-1/011	Ticket Office - Station Building - Hendon Central Stn	Lead/Leading	Lead Paint/Lead	Sampled - Not Detected				White matt paint applied to the false ceiling - Thickness: 0.09mm Analysis: 0.03%			R661826	N	N
46452	ACTIVE	N	N031-00-1/011	Ticket Office - Station Building - Hendon Central Stn	Lead/Leading	Lead Paint/Lead	Sampled - Not Detected				Cream matt paint applied to walls - Thickness: 0.22mm Analysis: <0.01%			R661826	N	N
46453	ACTIVE	N	N031-00-1/011	Ticket Office - Station Building - Hendon Central Stn	Lead/Leading	Lead Paint/Lead	Sampled - Not Detected				Cream matt paint applied to walls - Thickness: 0.28mm Analysis: 0.02%			R661826	N	N



# Hazardous Material Asset Register - Summary



## N031-00 - Station Building - Hendon Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18138	ACTIVE	N	N031-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Hendon Central Stn	Void	Asbestos	Surveyed – Not Detected				Wood, pvc cables, copper pipe - rock wool lagging above false ceiling				YES	
17881	ACTIVE	N	N031-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Hendon Central Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, PVC Cables, Supalux Debris, Metal beneath Computer Floor					YES
8405	ACTIVE	N	N031-00-1/021	POM - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17689	ACTIVE	N	N031-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Hendon Central Stn	Void	Asbestos	Surveyed – Not Detected				Wood, Air Con, Plaster, Rock Wool above False Ceiling				YES	
17688	ACTIVE	N	N031-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Hendon Central Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Metal, PVC Cables Beneath Computer Floor					YES
8406	ACTIVE	N	N031-00-1/031	Mess Room - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18139	ACTIVE	N	N031-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Hendon Central Stn	Void	Asbestos	Surveyed – Not Detected				Solid Ceiling, Metal Air Con, PVC Cable & Lagging to, Boxing Rock Wool above False Ceiling				YES	
17690	ACTIVE	N	N031-00-1/031/WAL-003	Wall: Internal - 3 - Mess Room - Station Building - Hendon Central Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
17691	ACTIVE	N	N031-00-1/031/WAL-004	Wall: Internal - 4 - Mess Room - Station Building - Hendon Central Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
8407	ACTIVE	N	N031-00-1/036	Toilet: Unisex - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17693	ACTIVE	N	N031-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Hendon Central Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboards Walls Solid, Ceiling Metal Pipe, Lagging, Rock Wool above False Ceiling				YES	
17692	ACTIVE	N	N031-00-1/036/WAL-001	Wall: Internal - 1 - Toilet - Station Building - Hendon Central Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
19072	ACTIVE	N	N031-00-1/036/WAL-004	Wall: Internal - 4 - Toilet - Station Building - Hendon Central Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
8408	ACTIVE	N	N031-00-1/071	Circulation Area - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17694	ACTIVE	N	N031-00-1/071	Circulation Area - Station Building - Hendon Central Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N031-00 - Station Building - Hendon Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8409	ACTIVE	N	N031-00-1/081	Lobby - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18223	ACTIVE	N	N031-00-1/081	Lobby - Station Building - Hendon Central Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8410	ACTIVE	N	N031-00-1/082	Lobby - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17695	ACTIVE	N	N031-00-1/082/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Hendon Central Stn	Void	Asbestos	Surveyed - Not Detected				Wood, PVC Cables, Copper pipe above False Ceiling				YES	
17696	ACTIVE	N	N031-00-1/082/WDW-01	Window - 1 - Lobby - Station Building - Hendon Central Stn	Glazing Rope	Asbestos	Surveyed - Not Detected				Glass Roof/ Window. Skylight to roof. New with rubber gasket only visible from roof (VC)		1		Y	
8411	ACTIVE	N	N031-00-1/083	Lobby - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17697	ACTIVE	N	N031-00-1/083/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Hendon Central Stn	Void	Asbestos	Surveyed - Not Detected				Wood, PVC Cables, Conduit above False Ceiling				YES	
18140	ACTIVE	N	N031-00-1/083/FLR-01	Floor - 1 - Lobby - Station Building - Hendon Central Stn	Void	Asbestos	Surveyed - Not Detected				Concrete, PVC Cable beneath Computer Floor					YES
8412	ACTIVE	N	N031-00-1/084	Lobby - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17698	ACTIVE	N	N031-00-1/084	Lobby - Station Building - Hendon Central Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Room					
18565	ACTIVE	N	N031-00-1/136	Lift Shaft - Station Building - Hendon Central Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Room					
8413	ACTIVE	N	N031-00-1/186	Station Entrance - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18083	ACTIVE	N	N031-00-1/186	Station Entrance - Station Building - Hendon Central Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8414	ACTIVE	N	N031-00-1/236	Passage - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17700	ACTIVE	N	N031-00-1/236	Passage - Station Building - Hendon Central Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
17699	ACTIVE	N	N031-00-1/236	Passage - Station Building - Hendon Central Stn	Void	Asbestos	Surveyed - Not Detected				Fibreglass Lagging above Wooden Hatch					
8415	ACTIVE	N	N031-00-1/237	Passage - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N031-00 - Station Building - Hendon Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17701	ACTIVE	N	N031-00-1/237/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Hendon Central Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18141	ACTIVE	N	N031-00-1/237/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Hendon Central Stn	Void	Asbestos	Surveyed – Not Detected				Skylight to roof. New with rubber gasket. Only visible from roof. (VC)				YES	
8416	ACTIVE	N	N031-00-1/291	Station Supervisor Office - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17703	ACTIVE	N	N031-00-1/291/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Hendon Central Stn	Void	Asbestos	Surveyed – Not Detected				Air Con, Pipe Work Lagging, Rock Wall, Walls Concrete, Plaster Tiles? Above False Ceiling				YES	
17702	ACTIVE	N	N031-00-1/291/WAL-001	Wall: Internal - 1 - Station Supervisor Office - Station Building - Hendon Central Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
8417	ACTIVE	N	N031-00-1/292	Training Room - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17704	ACTIVE	N	N031-00-1/292/CLG-01	Ceiling: Suspended - 1 - Training Room - Station Building - Hendon Central Stn	Void	Asbestos	Surveyed – Not Detected				Breeze Block, Concrete, Pipe Work + Lagging, Rock Wall above False Ceiling				YES	
8418	ACTIVE	N	N031-00-1/311	Office - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53529	ACTIVE	N	N031-00-1/311	Office - Station Building - Hendon Central Stn		Asbestos	Surveyed – Not Detected				Skylight to roof. New with rubber gasket. Only visible from roof. (VC)					
18142	ACTIVE	N	N031-00-1/311/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Hendon Central Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18084	ACTIVE	N	N031-00-1/311/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Hendon Central Stn	Void	Asbestos	Surveyed – Not Detected				Plaster Board, block walls, plaster above Supalux tiles				YES	
8419	ACTIVE	N	N031-00-1/351	Mess Room - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17706	ACTIVE	N	N031-00-1/351/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Hendon Central Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Plasterboard, Conduit, PVC Cable above false Ceiling				YES	
17705	ACTIVE	N	N031-00-1/351/WAL-004	Wall: Internal - 4 - Mess Room - Station Building - Hendon Central Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
8420	ACTIVE	N	N031-00-1/411	Store - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N031-00 - Station Building - Hendon Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17707	ACTIVE	N	N031-00-1/411	Store - Station Building - Hendon Central Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8421	ACTIVE	N	N031-00-1/416	Toilet: Unisex - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17708	ACTIVE	N	N031-00-1/416	Toilet: Unisex - Station Building - Hendon Central Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8422	ACTIVE	N	N031-00-1/426	Toilet: Female - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18143	ACTIVE	N	N031-00-1/426/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Hendon Central Stn	Glazing Rope	Asbestos	Surveyed – Not Detected				Glass Roof - No rope seals present. (VC)					
8423	ACTIVE	N	N031-00-1/427	Toilet: Male - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17709	ACTIVE	N	N031-00-1/427	Toilet: Male - Station Building - Hendon Central Stn	Glazing Rope	Asbestos	Surveyed – Not Detected				Glass Roof - Glazing Rope. Glazing replaced by Close Brothers and no asbestos was detected. Refer to 4-Rail report R681726					
8424	ACTIVE	N	N031-00-1/451	Tenancy - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17710	ACTIVE	N	N031-00-1/451	Tenancy - Station Building - Hendon Central Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8425	ACTIVE	N	N031-00-1/452	Tenancy - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19178	ACTIVE	N	N031-00-1/452/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Hendon Central Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
19548	ACTIVE	N	N031-00-1/452/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Hendon Central Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles				YES	
8426	ACTIVE	N	N031-00-1/453	Tenancy - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19550	ACTIVE	N	N031-00-1/453/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Hendon Central Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles				YES	
19549	ACTIVE	N	N031-00-1/453/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Hendon Central Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					



# Hazardous Material Asset Register - Summary



## N031-00 - Station Building - Hendon Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8427	ACTIVE	N	N031-00-1/454	Tenancy - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
46335	ACTIVE	N	N031-00-1/454	Tenancy - Station Building - Hendon Central Stn	Glazing Rope	Asbestos	Presumed				Room 1/454 & 1/455 Rope within glazing bars to skylights to ceiling - 1no.		1	R685276	N	N
46336	ACTIVE	N	N031-00-1/454	Tenancy - Station Building - Hendon Central Stn	Lead/Leading	Lead Paint/Lead	Sampled - Not Detected				Room 1/454 & 1/455 White matt and cream matt to wall and ceiling Thickness: 610µm Analysis: 0.48%			R685277	N	N
46337	ACTIVE	N	N031-00-1/454	Tenancy - Station Building - Hendon Central Stn	Lead/Leading	Lead Paint/Lead	Sampled - Not Detected				Room 1/454 & 1/455 Cream matt to top wall, boxing and cable management system Thickness: 590µm Analysis: 0.08%			R685277	N	N
8428	ACTIVE	N	N031-00-1/455	Tenancy - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
8429	ACTIVE	N	N031-00-1/576	Stairs: Linear - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19179	ACTIVE	N	N031-00-1/576	Stairs: Linear - Station Building - Hendon Central Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8430	ACTIVE	N	N031-00-1/577	Stairs: Linear - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19551	ACTIVE	N	N031-00-1/577	Stairs: Linear - Station Building - Hendon Central Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8431	ACTIVE	N	N031-00-1/601	Stairs: Linear - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19552	ACTIVE	N	N031-00-1/601	Stairs: Linear - Station Building - Hendon Central Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8432	ACTIVE	N	N031-00-1/603	Stairs: Linear - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19553	ACTIVE	N	N031-00-1/603	Stairs: Linear - Station Building - Hendon Central Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8433	ACTIVE	N	N031-00-1/631	Stairs: Spiral - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19180	ACTIVE	N	N031-00-1/631	Stairs: Spiral - Station Building - Hendon Central Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N031-00 - Station Building - Hendon Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19612	ACTIVE	N	N031-00-1/636	Overbridge - Station Building - Hendon Central Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8434	ACTIVE	N	N031-00-1/746	SCR - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19554	ACTIVE	N	N031-00-1/746	SCR - Station Building - Hendon Central Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8435	ACTIVE	N	N031-00-1/776	Plant Room - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19555	ACTIVE	N	N031-00-1/776/CLG-01 80903936	Ceiling: Solid - 1 - Plant Room - Station Building - Hendon Central Stn Ceiling: Solid	Void	Asbestos	No Access: Presumed				Above false ceiling. Fixed ceiling. No access				YES	
19748	ACTIVE	N	N031-00-1/776/CLG-01	Ceiling: Solid - 1 - Plant Room - Station Building - Hendon Central Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Plasterboard - 4no Pads Supalux					
8436	ACTIVE	N	N031-00-1/777	Plant Room - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19556	ACTIVE	N	N031-00-1/777	Plant Room - Station Building - Hendon Central Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8437	ACTIVE	N	N031-00-1/951	Locker Room - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19181	ACTIVE	N	N031-00-1/951/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Hendon Central Stn	Void	Asbestos	Surveyed – Not Detected				Solid, PVC Cables, Conduit above False Ceiling				YES	
19557	ACTIVE	N	N031-00-1/951/WAL-003	Wall: Internal - 3 - Locker Room - Station Building - Hendon Central Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LUL Heater with foam panel		1			
8438	ACTIVE	N	N031-00-1/952	Mess Room - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19241	ACTIVE	N	N031-00-1/952	Mess Room - Station Building - Hendon Central Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LUL Heater with foam panel		1			
19558	ACTIVE	N	N031-00-1/952	Mess Room - Station Building - Hendon Central Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
8439	ACTIVE	N	N031-00-2/081	Lobby - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19559	ACTIVE	N	N031-00-2/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Hendon Central Stn	Void	Asbestos	Surveyed – Not Detected				Solid, Conduit, PVC Cables, Air Con, Lagging Rock Wool above False Ceiling				YES	



# Hazardous Material Asset Register - Summary



## N031-00 - Station Building - Hendon Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8440	ACTIVE	N	N031-00-2/082	Lobby - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8441	ACTIVE	N	N031-00-2/083	Lobby - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8442	ACTIVE	N	N031-00-2/131	Lift Pump Room - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19560	ACTIVE	N	N031-00-2/131	Lift Pump Room - Station Building - Hendon Central Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
8443	ACTIVE	N	N031-00-2/136	Passage - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8444	ACTIVE	N	N031-00-2/236	Passage - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19820	ACTIVE	N	N031-00-2/236	Passage - Station Building - Hendon Central Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Part Plasterboard					
8445	ACTIVE	N	N031-00-2/261	Platform 1 - Northbound Local - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19182	ACTIVE	N	N031-00-2/261	Platform 1 - Northbound Local - Station Building - Hendon Central Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8446	ACTIVE	N	N031-00-2/262	Platform 2 - Southbound Local - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19561	ACTIVE	N	N031-00-2/262	Platform 2 - Southbound Local - Station Building - Hendon Central Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8447	ACTIVE	N	N031-00-2/301	Office - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19562	ACTIVE	N	N031-00-2/301/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Hendon Central Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
19183	ACTIVE	N	N031-00-2/301/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Hendon Central Stn	Void	Asbestos	Surveyed – Not Detected				Plaster Tiles, Computer Tiles, Solid, PVC Cable, Conduit Lagging to Pipe Rock Wool above Supalux Tiles				YES	
8448	ACTIVE	N	N031-00-2/302	GSM Office - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N031-00 - Station Building - Hendon Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19564	ACTIVE	N	N031-00-2/302/CLG-01	Ceiling: Suspended - 1 - GSM Office - Station Building - Hendon Central Stn	Void	Asbestos	Surveyed – Not Detected				Concrete Ceiling, Copper Pipe, Lagging Rock Wall PVC Cables, Conduit above False Ceiling				YES	
19563	ACTIVE	N	N031-00-2/302/WAL-002	Wall: Internal - 2 - GSM Office - Station Building - Hendon Central Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
8449	ACTIVE	N	N031-00-2/303	Office - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19613	ACTIVE	N	N031-00-2/303/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Hendon Central Stn	Void	Asbestos	Surveyed – Not Detected				Solid, Wood, PVC Cable, Lagging Rock Wool above False Ceiling				YES	
8450	ACTIVE	N	N031-00-2/361	Mess Room - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19565	ACTIVE	N	N031-00-2/361	Mess Room - Station Building - Hendon Central Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
19566	ACTIVE	N	N031-00-2/361/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Hendon Central Stn	Void	Asbestos	Surveyed – Not Detected				Solid, PVC Cable, Pipe Work, Lagging Rock Wool above False Ceiling				YES	
8451	ACTIVE	N	N031-00-2/401	Bin Store - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19567	ACTIVE	N	N031-00-2/401	Bin Store - Station Building - Hendon Central Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8452	ACTIVE	N	N031-00-2/402	Bin Store - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19568	ACTIVE	N	N031-00-2/402	Bin Store - Station Building - Hendon Central Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8453	ACTIVE	N	N031-00-2/406	Store - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19184	ACTIVE	N	N031-00-2/406	Store - Station Building - Hendon Central Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8454	ACTIVE	N	N031-00-2/411	Store - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19569	ACTIVE	N	N031-00-2/411	Store - Station Building - Hendon Central Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8455	ACTIVE	N	N031-00-2/412	Store - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N031-00 - Station Building - Hendon Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19570	ACTIVE	N	N031-00-2/412	Store - Station Building - Hendon Central Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8456	ACTIVE	N	N031-00-2/413	Store - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19185	ACTIVE	N	N031-00-2/413	Store - Station Building - Hendon Central Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8457	ACTIVE	N	N031-00-2/414	Store - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19571	ACTIVE	N	N031-00-2/414	Store - Station Building - Hendon Central Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8458	ACTIVE	N	N031-00-2/415	Store - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19572	ACTIVE	N	N031-00-2/415	Store - Station Building - Hendon Central Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8459	ACTIVE	N	N031-00-2/416	Toilet: Unisex - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19573	ACTIVE	N	N031-00-2/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Hendon Central Stn	Void	Asbestos	Surveyed – Not Detected				Solid - Pointed Artex above False Ceiling				YES	
8460	ACTIVE	N	N031-00-2/436	Waiting Room - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8461	ACTIVE	N	N031-00-2/451	Tenancy - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19186	ACTIVE	N	N031-00-2/451	Tenancy - Station Building - Hendon Central Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8462	ACTIVE	N	N031-00-2/551	Yard - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19619	ACTIVE	N	N031-00-2/551	Yard - Station Building - Hendon Central Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8463	ACTIVE	N	N031-00-2/552	Yard - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19873	ACTIVE	N	N031-00-2/552	Yard - Station Building - Hendon Central Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N031-00 - Station Building - Hendon Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8464	ACTIVE	N	N031-00-2/603	Stairs: Linear - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8465	ACTIVE	N	N031-00-2/661	Switch Room - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19243	ACTIVE	N	N031-00-2/661/ WAL-001 80904302	Wall: Internal - 1 - Switch Room - Station Building - Hendon Central Stn Wall: Internal	Other Electrical Boxes	Asbestos	Strongly Presumed				1 x Transformer Box. Presumed asbestos insulating materials within. No access to inspect internally. Electrical isolation required. 13/09/2023		1			
20340	ACTIVE	N	N031-00-2/661/ WAL-001 80904302	Wall: Internal - 1 - Switch Room - Station Building - Hendon Central Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				2 x 100 amp Switch Boxes. Presumed asbestos insulating materials within. No access to inspect internally. Electrical isolations required 13/09/2023		2			
20339	ACTIVE	N	N031-00-2/661/ WAL-002 80904303	Wall: Internal - 2 - Switch Room - Station Building - Hendon Central Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				7 x 100 amp, 1 x 60 amp Switch Boxes. Presumed asbestos insulating materials within. No access to inspect internally. Electrical isolation required 13/09/2023		8			
20343	INACTIVE	N	N031-00-2/661/ WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Hendon Central Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x Switch Boxes		2			
19620	ACTIVE	N	N031-00-2/661/ WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Hendon Central Stn	Other Electrical Boxes	Asbestos	Room: Surveyed: Asbestos Presumed				1 x Transformer Box		1			
20341	ACTIVE	N	N031-00-2/661/ WAL-003 80904304	Wall: Internal - 3 - Switch Room - Station Building - Hendon Central Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				1 x 100 amp Switch Box. Presumed asbestos insulating materials within. No access to inspect internally. Electrically isolations required 13/09/2023		1			
64654	ACTIVE	N	N031-00-2/661/ WAL-003 80904304	Wall: Internal - 3 - Switch Room - Station Building - Hendon Central Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				1x combination fuse box 100amps. No access to inspect internally. Electrical isolations required. 13/09/2023		1			
20344	INACTIVE	N	N031-00-2/661/ WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Hendon Central Stn	Isolator Switches	Asbestos	Strongly Presumed				8 x Switch Boxes		8			
20342	ACTIVE	N	N031-00-2/661/ WAL-004 80904305	Wall: Internal - 4 - Switch Room - Station Building - Hendon Central Stn Wall: Internal	Other Electrical Boxes	Asbestos	Strongly Presumed				3 x Transformer Boxes. Presumed asbestos containing materials within. No access to inspect internally. Electrical isolations required. 13/09/2023		3			
20346	ACTIVE	N	N031-00-2/661/ WAL-004 80904305	Wall: Internal - 4 - Switch Room - Station Building - Hendon Central Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				1 x Switch Box. Presumed asbestos insulating materials within. No access to inspect internally. Electrical isolations required. 13/09/2023		1			
20345	INACTIVE	N	N031-00-2/661/ WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Hendon Central Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				3 x Transformer Boxes. Presumed asbestos containing materials within		3			



# Hazardous Material Asset Register - Summary



## N031-00 - Station Building - Hendon Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8466	ACTIVE	N	N031-00-2/662	Switch Room - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19621	ACTIVE	N	N031-00-2/662	Switch Room - Station Building - Hendon Central Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8467	ACTIVE	N	N031-00-2/663	Switch Room - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19622	ACTIVE	N	N031-00-2/663	Switch Room - Station Building - Hendon Central Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Room					
8468	ACTIVE	N	N031-00-2/731	CER - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19624	ACTIVE	N	N031-00-2/731/FLR-01	Floor - 1 - CER - Station Building - Hendon Central Stn	Void	Asbestos	Surveyed - Not Detected				PVC Cable, Trunking, Concrete beneath Computer Floor					YES
8469	ACTIVE	N	N031-00-2/761	Equipment Room - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19244	ACTIVE	N	N031-00-2/761	Equipment Room - Station Building - Hendon Central Stn	Gasket :Pipework	Asbestos	Surveyed - Not Detected				Compressed Cardboard					
8470	ACTIVE	N	N031-00-2/951	Disused Room - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19625	ACTIVE	N	N031-00-2/951/WAL-004	Wall: Internal - 4 - Disused Room - Station Building - Hendon Central Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Panels					
8471	ACTIVE	N	N031-00-2/952	Store - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19626	ACTIVE	N	N031-00-2/952	Store - Station Building - Hendon Central Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8472	ACTIVE	N	N031-00-A/778	Plant Room - Station Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19627	ACTIVE	N	N031-00-A/778	Plant Room - Station Building - Hendon Central Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					

## N033-00 - Station Building - Brent Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8479	ACTIVE	N	N033-00-1/001	Booking Hall - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N033-00 - Station Building - Brent Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17851	ACTIVE	N	N033-00-1/001	Booking Hall - Station Building - Brent Cross Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8480	ACTIVE	N	N033-00-1/011	Ticket Office - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17853	ACTIVE	N	N033-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Brent Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Plaster & Tiles				YES	
17852	ACTIVE	N	N033-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Brent Cross Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Floor					YES
8481	ACTIVE	N	N033-00-1/021	POM - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18388	ACTIVE	N	N033-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Brent Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Plaster & Tiles				YES	
18158	ACTIVE	N	N033-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Brent Cross Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Floor					YES
8482	ACTIVE	N	N033-00-1/031	Mess Room - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17854	ACTIVE	N	N033-00-1/031	Mess Room - Station Building - Brent Cross Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
8483	ACTIVE	N	N033-00-1/036	Toilet: Unisex - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17855	ACTIVE	N	N033-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Brent Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Plaster & Tiles				YES	
8484	ACTIVE	N	N033-00-1/071	Circulation Area - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17856	ACTIVE	N	N033-00-1/071	Circulation Area - Station Building - Brent Cross Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8485	ACTIVE	N	N033-00-1/081	Lobby - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17857	ACTIVE	N	N033-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Brent Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Plaster & Tiles				YES	
18389	ACTIVE	N	N033-00-1/081/FLR-01	Floor - 1 - Lobby - Station Building - Brent Cross Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Floor					YES



# Hazardous Material Asset Register - Summary



## N033-00 - Station Building - Brent Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8486	ACTIVE	N	N033-00-1/082	Lobby - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17859	ACTIVE	N	N033-00-1/082/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Brent Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	
17858	ACTIVE	N	N033-00-1/082/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Brent Cross Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
8487	ACTIVE	N	N033-00-1/201	Passage - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17860	ACTIVE	N	N033-00-1/201	Passage - Station Building - Brent Cross Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8488	ACTIVE	N	N033-00-1/316	Locker Room - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17861	ACTIVE	N	N033-00-1/316	Locker Room - Station Building - Brent Cross Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8489	ACTIVE	N	N033-00-1/371	Store - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18390	ACTIVE	N	N033-00-1/371	Store - Station Building - Brent Cross Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8490	ACTIVE	N	N033-00-1/372	Mess Room - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18474	ACTIVE	N	N033-00-1/372/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Brent Cross Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18225	ACTIVE	N	N033-00-1/372/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Brent Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	
8491	ACTIVE	N	N033-00-1/401	Bin Store - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17862	ACTIVE	N	N033-00-1/401	Bin Store - Station Building - Brent Cross Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8492	ACTIVE	N	N033-00-1/402	Bin Store - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17863	ACTIVE	N	N033-00-1/402	Bin Store - Station Building - Brent Cross Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N033-00 - Station Building - Brent Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8493	ACTIVE	N	N033-00-1/406	Store - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17864	ACTIVE	N	N033-00-1/406	Store - Station Building - Brent Cross Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8494	ACTIVE	N	N033-00-1/407	Store - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18391	ACTIVE	N	N033-00-1/407	Store - Station Building - Brent Cross Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8495	ACTIVE	N	N033-00-1/416	Toilet: Female - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19081	ACTIVE	N	N033-00-1/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Brent Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete & Fibre Glass Lagging above Supalux Tiles				YES	
17865	ACTIVE	N	N033-00-1/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Brent Cross Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
17866	ACTIVE	N	N033-00-1/416/WDW-01	Window - 1 - Toilet - Station Building - Brent Cross Stn	Lead/Leading	Lead Paint/Lead	Known				Window Frames : White Gloss Coating - Thickness 0.19mm : Analysis 1.43%					
8496	ACTIVE	N	N033-00-1/417	Toilet: Male - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18392	ACTIVE	N	N033-00-1/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Brent Cross Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
17867	ACTIVE	N	N033-00-1/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Brent Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	
17868	ACTIVE	N	N033-00-1/417/WDW-01	Window - 1 - Toilet - Station Building - Brent Cross Stn	Lead/Leading	Lead Paint/Lead	Known				Window Frames : White Gloss Coating - Thickness 0.19mm : Analysis 1.43%					
17869	ACTIVE	N	N033-00-1/417/WDW-02	Window - 2 - Toilet - Station Building - Brent Cross Stn	Lead/Leading	Lead Paint/Lead	Known				Window Frames : White Gloss Coating - Thickness 0.19mm : Analysis 1.43%					
8497	ACTIVE	N	N033-00-1/418	Shower Room - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18159	ACTIVE	N	N033-00-1/418	Shower Room - Station Building - Brent Cross Stn	Lead/Leading	Lead Paint/Lead	Known				Window Frames : White Gloss Coating - Thickness 0.19mm : Analysis 1.43%					
18393	ACTIVE	N	N033-00-1/418/CLG-01	Ceiling: Suspended - 1 - Shower Room - Station Building - Brent Cross Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	



# Hazardous Material Asset Register - Summary



## N033-00 - Station Building - Brent Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17870	ACTIVE	N	N033-00-1/418/CLG-01	Ceiling: Suspended - 1 - Shower Room - Station Building - Brent Cross Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
8498	ACTIVE	N	N033-00-1/551	Yard - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17871	ACTIVE	N	N033-00-1/551	Yard - Station Building - Brent Cross Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8499	ACTIVE	N	N033-00-1/661	Switch Room - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
17872	ACTIVE	N	N033-00-1/661	Switch Room - Station Building - Brent Cross Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Approx 6x Cable Ducts. To floor by Wall 1 & 4 in corner.					
17873	ACTIVE	N	N033-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Brent Cross Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				4 x Transformer Boxes		4			
20347	ACTIVE	N	N033-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Brent Cross Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x Fuse Box 30 amp. Presumed asbestos insulating materials within.		1			
20348	ACTIVE	N	N033-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Brent Cross Stn	Other Electrical Boxes	Asbestos	Presumed				Electrical Box. Presumed asbestos insulating materials within		1			
19494	ACTIVE	N	N033-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Brent Cross Stn	Isolator Switches	Asbestos	Strongly Presumed				4 x 60 amp, 2 x 100 amp Combination Fuse Switches. Presumed asbestos insulating materials within		6			
8500	ACTIVE	N	N033-00-1/662	Computer Equipment Cupboard - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18394	ACTIVE	N	N033-00-1/662	Computer Equipment Cupboard - Station Building - Brent Cross Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8501	ACTIVE	N	N033-00-1/663	Switch Cupboard - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17874	ACTIVE	N	N033-00-1/663/WLS	Walls: Internal - Switch Cupboard - Station Building - Brent Cross Stn	No Access	Asbestos	Surveyed – Not Detected				New Build - Wall 2 Electrical Equipment					
8502	ACTIVE	N	N033-00-1/746	SCR - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17876	ACTIVE	N	N033-00-1/746	SCR - Station Building - Brent Cross Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N033-00 - Station Building - Brent Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8503	ACTIVE	N	N033-00-A/261	Platform 1 - Northbound Local - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17877	ACTIVE	N	N033-00-A/261	Platform 1 - Northbound Local - Station Building - Brent Cross Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8504	ACTIVE	N	N033-00-A/262	Platform 2 - Southbound Local - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18160	ACTIVE	N	N033-00-A/262	Platform 2 - Southbound Local - Station Building - Brent Cross Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8505	ACTIVE	N	N033-00-A/411	Waiting Room - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18395	ACTIVE	N	N033-00-A/411	Waiting Room - Station Building - Brent Cross Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible				YES	
8506	ACTIVE	N	N033-00-A/601	Stairs: Linear - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17878	ACTIVE	N	N033-00-A/601	Stairs: Linear - Station Building - Brent Cross Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8507	ACTIVE	N	N033-00-A/602	Stairs: Linear - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17879	ACTIVE	N	N033-00-A/602	Stairs: Linear - Station Building - Brent Cross Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8508	ACTIVE	N	N033-00-A/661	Relay Room - Station Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N041-00 - Station Building - Golders Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8512	ACTIVE	N	N041-00-1/001	Booking Hall - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17752	ACTIVE	N	N041-00-1/001/CLG-01	Ceiling: Suspended - 1 - Booking Hall - Station Building - Golders Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18088	ACTIVE	N	N041-00-1/001/CLG-01	Ceiling: Suspended - 1 - Booking Hall - Station Building - Golders Green Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				YES	



# Hazardous Material Asset Register - Summary



## N041-00 - Station Building - Golders Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8513	ACTIVE	N	N041-00-1/011	Ticket Office - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18298	ACTIVE	N	N041-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Golders Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux & Acoustic Tiles					
17754	ACTIVE	N	N041-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Golders Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				YES	
17753	ACTIVE	N	N041-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Golders Green Stn	Void	Asbestos	No Access: Presumed				Beneath tiles					YES
8514	ACTIVE	N	N041-00-1/021	POM - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17755	ACTIVE	N	N041-00-1/021	POM - Station Building - Golders Green Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Boarding on Wall - Non Asbestos					
8515	ACTIVE	N	N041-00-1/031	Office - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17756	ACTIVE	N	N041-00-1/031	Office - Station Building - Golders Green Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater with foam insulation. Vent grid - Solid					
17757	ACTIVE	N	N041-00-1/031/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Golders Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding					
17758	ACTIVE	N	N041-00-1/031/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Golders Green Stn	Void	Asbestos	Surveyed – Not Detected				Fibreglass above false ceiling				YES	
8516	ACTIVE	N	N041-00-1/036	Toilet: Unisex - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18299	ACTIVE	N	N041-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Golders Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
17759	ACTIVE	N	N041-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Golders Green Stn	Void	Asbestos	Surveyed – Not Detected				Plaster, Concrete, Fibreglass lagging above false ceiling				YES	
8517	ACTIVE	N	N041-00-1/047	Kitchen - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18300	ACTIVE	N	N041-00-1/047	Kitchen - Station Building - Golders Green Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
17760	ACTIVE	N	N041-00-1/047/CLG-01	Ceiling: Suspended - 1 - Kitchen - Station Building - Golders Green Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard Tiles					



# Hazardous Material Asset Register - Summary



## N041-00 - Station Building - Golders Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17761	ACTIVE	N	N041-00-1/047/CLG-01	Ceiling: Suspended - 1 - Kitchen - Station Building - Golders Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above plasterboard tiles				YES	
8518	ACTIVE	N	N041-00-1/071	Circulation Area - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17763	ACTIVE	N	N041-00-1/071	Circulation Area - Station Building - Golders Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing					
17762	ACTIVE	N	N041-00-1/071/CLG-01	Ceiling: Suspended - 1 - Circulation Area - Station Building - Golders Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18301	ACTIVE	N	N041-00-1/071/CLG-01	Ceiling: Suspended - 1 - Circulation Area - Station Building - Golders Green Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles				YES	
8519	ACTIVE	N	N041-00-1/081	Lobby - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19414	ACTIVE	N	N041-00-1/081	Lobby - Station Building - Golders Green Stn	Void	Asbestos	No Access: Presumed				Behind wood panels					
18568	ACTIVE	N	N041-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Golders Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Acoustic Panel				YES	
8520	ACTIVE	N	N041-00-1/082	Lobby - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17765	ACTIVE	N	N041-00-1/082/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Golders Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				YES	
17764	ACTIVE	N	N041-00-1/082/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Golders Green Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Lay in tiles/ Plasterboard					
18302	ACTIVE	N	N041-00-1/136	Lift Shaft - Station Building - Golders Green Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
19076	ACTIVE	N	N041-00-1/137	Lift Shaft - Station Building - Golders Green Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
8521	ACTIVE	N	N041-00-1/201	Passage - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17766	ACTIVE	N	N041-00-1/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Golders Green Stn		Asbestos	Surveyed – Not Detected				Bituminous Ceiling					
8522	ACTIVE	N	N041-00-1/202	Passage - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N041-00 - Station Building - Golders Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17767	ACTIVE	N	N041-00-1/202/FLR-01	Floor - 1 - Passage - Station Building - Golders Green Stn		Asbestos	Surveyed – Not Detected				Bituminous Flooring					
8523	ACTIVE	N	N041-00-1/203	Passage - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17768	ACTIVE	N	N041-00-1/203/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Golders Green Stn	Void	Asbestos	No Access: Presumed				No Access above Tiled Ceiling				N	
20350	ACTIVE	N	N041-00-1/203/CLG-02	Ceiling: Solid - 2 - Passage - Station Building - Golders Green Stn	No Access	Asbestos	No Access: Presumed				No Access above Tiled Ceiling				N	
20351	ACTIVE	N	N041-00-1/203/FLR-01	Floor - 1 - Passage - Station Building - Golders Green Stn	No Access	Asbestos	No Access: Presumed				No access beneath Hatch in floor					N
20352	ACTIVE	N	N041-00-1/203/WLS	Walls: Internal - Passage - Station Building - Golders Green Stn	Lead/Leading	Lead Paint/Lead	Presumed				Possible Lead Paint to Walls and Pipework				N	N
8524	ACTIVE	N	N041-00-1/204	Passage - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18148	ACTIVE	N	N041-00-1/204	Passage - Station Building - Golders Green Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
8525	ACTIVE	N	N041-00-1/236	Passage - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17769	ACTIVE	N	N041-00-1/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Golders Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete & Breeze Block beneath false ceiling				YES	
18303	ACTIVE	N	N041-00-1/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Golders Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux & Acoustic Tiles					
8526	ACTIVE	N	N041-00-1/237	Passage - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17770	ACTIVE	N	N041-00-1/237	Passage - Station Building - Golders Green Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
8527	ACTIVE	N	N041-00-1/238	Passage - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17771	ACTIVE	N	N041-00-1/238/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Golders Green Stn	Void	Asbestos	No Access: Presumed				Above steel ceiling				YES	
8528	ACTIVE	N	N041-00-1/239	Lobby - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N041-00 - Station Building - Golders Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17772	ACTIVE	N	N041-00-1/239/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Golders Green Stn	Void	Asbestos	Surveyed – Not Detected				Steel above Acoustic Panels				YES	
8529	ACTIVE	N	N041-00-1/311	Locker Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18304	ACTIVE	N	N041-00-1/311/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Golders Green Stn	Void	Asbestos	Surveyed – Not Detected				Metal Sheets; Lagging - Fibreglass above Lay in tiles				YES	
8530	ACTIVE	N	N041-00-1/316	Locker Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17773	ACTIVE	N	N041-00-1/316/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Golders Green Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard; Fibreglass Lagging above false ceiling				YES	
8531	ACTIVE	N	N041-00-1/317	Locker Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18149	ACTIVE	N	N041-00-1/317	Locker Room - Station Building - Golders Green Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8532	ACTIVE	N	N041-00-1/341	Mess Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17774	ACTIVE	N	N041-00-1/341	Mess Room - Station Building - Golders Green Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
17775	ACTIVE	N	N041-00-1/341/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Golders Green Stn	Void	Asbestos	Surveyed – Not Detected				Steel above Acoustic Panels				YES	
8533	ACTIVE	N	N041-00-1/401	Bin Store - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17776	ACTIVE	N	N041-00-1/401	Bin Store - Station Building - Golders Green Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8534	ACTIVE	N	N041-00-1/402	Bin Store - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18305	ACTIVE	N	N041-00-1/402	Bin Store - Station Building - Golders Green Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8535	ACTIVE	N	N041-00-1/406	Store - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17777	ACTIVE	N	N041-00-1/406	Store - Station Building - Golders Green Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N041-00 - Station Building - Golders Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8536	ACTIVE	N	N041-00-1/407	Store - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17778	ACTIVE	N	N041-00-1/407/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Golders Green Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Acoustic Panels				YES	
8537	ACTIVE	N	N041-00-1/411	Store - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17779	ACTIVE	N	N041-00-1/411	Store - Station Building - Golders Green Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8538	ACTIVE	N	N041-00-1/413	Store - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18150	ACTIVE	N	N041-00-1/413	Store - Station Building - Golders Green Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8539	ACTIVE	N	N041-00-1/414	Store - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19077	ACTIVE	N	N041-00-1/414	Store - Station Building - Golders Green Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8540	ACTIVE	N	N041-00-1/415	Store - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18306	ACTIVE	N	N041-00-1/415	Store - Station Building - Golders Green Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8541	ACTIVE	N	N041-00-1/416	Toilet: Male - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17780	ACTIVE	N	N041-00-1/416	Toilet: Male - Station Building - Golders Green Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Wooden Panels above Windows					
17781	ACTIVE	N	N041-00-1/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Golders Green Stn	Void	Asbestos	Surveyed - Not Detected				Concrete, Fibreglass Lagging above Acoustic Panel				YES	
8542	ACTIVE	N	N041-00-1/417	Toilet: Female - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17782	ACTIVE	N	N041-00-1/417	Toilet: Female - Station Building - Golders Green Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Boxing Plasterboard					
8543	ACTIVE	N	N041-00-1/418	Toilet: Male - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N041-00 - Station Building - Golders Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18569	ACTIVE	N	N041-00-1/418/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Golders Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Acoustic Panels				YES	
8544	ACTIVE	N	N041-00-1/419	Toilet: Female - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17783	ACTIVE	N	N041-00-1/419/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Golders Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Acoustic Panels				YES	
8545	ACTIVE	N	N041-00-1/420	Toilet: Unisex - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17784	ACTIVE	N	N041-00-1/420	Toilet: Unisex - Station Building - Golders Green Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
8546	ACTIVE	N	N041-00-1/451	Tenancy - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18307	ACTIVE	N	N041-00-1/451	Tenancy - Station Building - Golders Green Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Tenancy					
8547	ACTIVE	N	N041-00-1/452	Tenancy - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17785	ACTIVE	N	N041-00-1/452	Tenancy - Station Building - Golders Green Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Tenancy					
8548	ACTIVE	N	N041-00-1/481	Void - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17786	ACTIVE	N	N041-00-1/481	Void - Station Building - Golders Green Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8549	ACTIVE	N	N041-00-1/551	Yard - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20029	ACTIVE	N	N041-00-1/551	Yard - Station Building - Golders Green Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8550	ACTIVE	N	N041-00-1/552	Passage - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17787	ACTIVE	N	N041-00-1/552	Passage - Station Building - Golders Green Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8551	ACTIVE	N	N041-00-1/661	Switch Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N041-00 - Station Building - Golders Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18308	ACTIVE	N	N041-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Golders Green Stn		Asbestos	Surveyed – Not Detected				Re Inspected 24/07/2014					
19493	ACTIVE	N	N041-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Golders Green Stn		Asbestos	Surveyed – Not Detected				Re Inspected 24/07/2014 - nothing on this wall					
20353	ACTIVE	N	N041-00-1/661/WAL-004 80917029	Wall: Internal - 4 - Switch Room - Station Building - Golders Green Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				1 x Switch Box 30amp No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1			
18151	ACTIVE	N	N041-00-1/661/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Golders Green Stn	Other Electrical Boxes	Asbestos	Presumed				3 x Transformer Boxes No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		3		N	N
20357	ACTIVE	N	N041-00-1/661/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Golders Green Stn	Void	Asbestos	No Access: Presumed				No access behind wall hatch					N
20355	ACTIVE	N	N041-00-1/661/WAL-006	Wall: Internal - 6 - Switch Room - Station Building - Golders Green Stn	Other Electrical Boxes	Asbestos	Surveyed – Not Detected				1 x Transformer Box		1		N	N
20354	ACTIVE	N	N041-00-1/661/WAL-006	Wall: Internal - 6 - Switch Room - Station Building - Golders Green Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Switch Boxes - 5 x 100 amp, 3 x 60 amp No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		8		N	N
8552	ACTIVE	N	N041-00-1/731	CER - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17789	ACTIVE	N	N041-00-1/731/FLR-01	Floor - 1 - CER - Station Building - Golders Green Stn	Void	Asbestos	Surveyed – Not Detected				Beneath Computer Tiles					YES
8553	ACTIVE	N	N041-00-1/746	SCR - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17791	ACTIVE	N	N041-00-1/746	SCR - Station Building - Golders Green Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8554	ACTIVE	N	N041-00-1/776	Equipment Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17792	ACTIVE	N	N041-00-1/776	Equipment Room - Station Building - Golders Green Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8555	ACTIVE	N	N041-00-1/801	Mess Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N041-00 - Station Building - Golders Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17793	ACTIVE	N	N041-00-1/801	Mess Room - Station Building - Golders Green Stn	LUL Heaters	Asbestos	Surveyed – Not Detected									
17794	ACTIVE	N	N041-00-1/801	Mess Room - Station Building - Golders Green Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
17795	ACTIVE	N	N041-00-1/801/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Golders Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete & Breeze Block above false ceiling				YES	
18309	ACTIVE	N	N041-00-1/801/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Golders Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
8556	ACTIVE	N	N041-00-1/802	DSM Office - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17797	ACTIVE	N	N041-00-1/802/CLG-01	Ceiling: Suspended - 1 - DSM Office - Station Building - Golders Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				YES	
17796	ACTIVE	N	N041-00-1/802/CLG-01	Ceiling: Suspended - 1 - DSM Office - Station Building - Golders Green Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard Tiles					
8557	ACTIVE	N	N041-00-1/803	DSM Office - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17798	ACTIVE	N	N041-00-1/803/CLG-01	Ceiling: Suspended - 1 - DSM Office - Station Building - Golders Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				YES	
18310	ACTIVE	N	N041-00-1/803/CLG-01	Ceiling: Suspended - 1 - DSM Office - Station Building - Golders Green Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard Tiles					
8558	ACTIVE	N	N041-00-1/804	DSM Office - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18152	ACTIVE	N	N041-00-1/804/CLG-01	Ceiling: Suspended - 1 - DSM Office - Station Building - Golders Green Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard Tiles					
19078	ACTIVE	N	N041-00-1/804/CLG-01	Ceiling: Suspended - 1 - DSM Office - Station Building - Golders Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, metal ducting above false ceiling				YES	
8559	ACTIVE	N	N041-00-1/805	DSM Office - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17799	ACTIVE	N	N041-00-1/805	DSM Office - Station Building - Golders Green Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N041-00 - Station Building - Golders Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8560	ACTIVE	N	N041-00-1/971	Passage - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
25871	ACTIVE	N	N041-00-1/971	Passage - Station Building - Golders Green Stn	Other Electrical Boxes	Asbestos	Presumed				Trunking within E6 switchcupboard by 1/451 (materials within) E switchroom key unlocks padlock) No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
25872	ACTIVE	N	N041-00-1/971	Passage - Station Building - Golders Green Stn	Other Electrical Boxes	Asbestos	No Access: Presumed				Materials within E5 Switchcupboard by 1/452					
17800	ACTIVE	N	N041-00-1/971	Passage - Station Building - Golders Green Stn	Other Electrical Boxes	Asbestos	Presumed				1x Distribution board within E6 Cupboard by 1/451 (E Switch key unlocks padlock) No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
25870	ACTIVE	N	N041-00-1/971	Passage - Station Building - Golders Green Stn	Isolator Switches	Asbestos	Strongly Presumed				1x Switchbox within E6 switchcupboard by 1/451 (E switch key unlocks padlock) No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
8561	ACTIVE	N	N041-00-A/041	Canteen - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17801	ACTIVE	N	N041-00-A/041/CLG-01	Ceiling: Suspended - 1 - Canteen - Station Building - Golders Green Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard Tiles					
18311	ACTIVE	N	N041-00-A/041/CLG-01	Ceiling: Suspended - 1 - Canteen - Station Building - Golders Green Stn	Void	Asbestos	Surveyed - Not Detected				Concrete/ Supalux Panel above false ceiling				YES	
8562	ACTIVE	N	N041-00-A/042	Canteen - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17802	ACTIVE	N	N041-00-A/042/CLG-01	Ceiling: Suspended - 1 - Canteen - Station Building - Golders Green Stn	Void	Asbestos	Surveyed - Not Detected				Concrete Supalux Blocks above Plaster Tiles				YES	
8563	ACTIVE	N	N041-00-A/047	Kitchen - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N041-00 - Station Building - Golders Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17803	ACTIVE	N	N041-00-A/047/CLG-01	Ceiling: Suspended - 1 - Kitchen - Station Building - Golders Green Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard / Tiles					
17804	ACTIVE	N	N041-00-A/047/CLG-01	Ceiling: Suspended - 1 - Kitchen - Station Building - Golders Green Stn	Void	Asbestos	Surveyed – Not Detected				Concreteabove false ceiling				YES	
8564	ACTIVE	N	N041-00-A/050	Larder - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17806	ACTIVE	N	N041-00-A/050	Larder - Station Building - Golders Green Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8565	ACTIVE	N	N041-00-A/051	Larder - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17805	ACTIVE	N	N041-00-A/051	Larder - Station Building - Golders Green Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8566	ACTIVE	N	N041-00-A/081	Lobby - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18312	ACTIVE	N	N041-00-A/081	Lobby - Station Building - Golders Green Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
8567	ACTIVE	N	N041-00-A/082	Lobby - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17807	ACTIVE	N	N041-00-A/082	Lobby - Station Building - Golders Green Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
8568	ACTIVE	N	N041-00-A/084	Lobby - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17808	ACTIVE	N	N041-00-A/084	Lobby - Station Building - Golders Green Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8569	ACTIVE	N	N041-00-A/261	Platform 1 - Northbound Local - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17809	ACTIVE	N	N041-00-A/261	Platform 1 - Northbound Local - Station Building - Golders Green Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Boarding on Wall - Non Asbestos					
18374	ACTIVE	N	N041-00-A/261	Platform 1 - Northbound Local - Station Building - Golders Green Stn	Lagging	Asbestos	Surveyed – Not Detected				Bronzo Tape on Pipes					
44007	ACTIVE	N	N041-00-A/261	Platform 1 - Northbound Local - Station Building - Golders Green Stn		Lead Paint/Lead	Presumed				Upon re - inspection possible lead paint on all upstands and canopy support was reported					



# Hazardous Material Asset Register - Summary



## N041-00 - Station Building - Golders Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17810	ACTIVE	N	N041-00-A/261/ FLR-01	Floor - 1 - Platform 1 - Station Building - Golders Green Stn	Debris: Cement	Asbestos	Known				Extensive cementitious debris below Platform; Extensive surface pick undertaken; however any further excavation will require further investigation  No access beneath platforms during traffic in 2020 re-inspection.					YES
8570	ACTIVE	N	N041-00-A/262	Platform 2 - Northbound Local - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44008	ACTIVE	N	N041-00-A/262	Platform 2 - Northbound Local - Station Building - Golders Green Stn		Lead Caulking	Presumed				Upon re - inspection possible lead paint on all upstands and canopy support was reported					
17811	ACTIVE	N	N041-00-A/262/ FLR-01	Floor - 1 - Platform 2 - Station Building - Golders Green Stn	Debris: Cement	Asbestos	Strongly Presumed				Asbestos debris maybe present within clay bed/soil/rubble beneath platform  No access beneath platforms during traffic in 2020 re-inspection.				N	YES
8571	ACTIVE	N	N041-00-A/263	Platform 3 - Northbound Main - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44009	ACTIVE	N	N041-00-A/263	Platform 3 - Northbound Main - Station Building - Golders Green Stn		Lead Caulking	Presumed				Upon re - inspection possible lead paint on all upstands and canopy support was reported					
18375	ACTIVE	N	N041-00-A/263/ FLR-01	Floor - 1 - Platform 3 - Station Building - Golders Green Stn	Debris: Cement	Asbestos	Strongly Presumed				Asbestos debris maybe present within clay bed/soil/rubble beneath platform  No access to area beneath platform during traffic in 2020 reinspection.					YES
8572	ACTIVE	N	N041-00-A/264	Platform 4 - Northbound Main - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17812	ACTIVE	N	N041-00-A/264/ CLG-01	Ceiling: Solid - 1 - Platform 4 - Station Building - Golders Green Stn	Glazing Rope	Asbestos	Known				Glazing Rope seals from Glazing on Canopy - Chrysotile - Partially Removed				N	N
20358	ACTIVE	N	N041-00-A/264/ CLG-01	Ceiling: Solid - 1 - Platform 4 - Station Building - Golders Green Stn	Lead/Leading	Lead Paint/Lead	Presumed				Upon re - inspection possible lead paint on all upstands and canopy support was reported				N	N
17813	ACTIVE	N	N041-00-A/264/ FLR-01	Floor - 1 - Platform 4 - Station Building - Golders Green Stn	Debris: Cement	Asbestos	Strongly Presumed				Asbestos debris maybe present within clay bed/soil/rubble beneath platform  No access to area beneath platform during traffic in 2020 reinspection.				N	YES
8573	ACTIVE	N	N041-00-A/265	Platform 5 - Southbound Local - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44921	ACTIVE	N	N041-00-A/265	Platform 5 - Southbound Local - Station Building - Golders Green Stn	Lead/Leading	Lead Paint/Lead	Presumed				Possible Green Lead Paint on all Upstands & Canopy support				N	N



# Hazardous Material Asset Register - Summary



## N041-00 - Station Building - Golders Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17814	ACTIVE	N	N041-00-A/265/CLG-01	Ceiling: Solid - 1 - Platform 5 - Station Building - Golders Green Stn	Glazing Rope	Asbestos	Known				Glazing Rope seals from Glazing on Canopy - Chrysotile - Partially Removed				N	N
17815	ACTIVE	N	N041-00-A/265/FLR-01	Floor - 1 - Platform 5 - Station Building - Golders Green Stn	Debris: Cement	Asbestos	Strongly Presumed				Asbestos debris maybe present within clay bed/soil/rubble beneath platform  No access to area beneath platform during traffic in 2020 reinspection				N	YES
8574	ACTIVE	N	N041-00-A/291	DMT Office - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19079	ACTIVE	N	N041-00-A/291/CLG-01	Ceiling: Suspended - 1 - DMT Office - Station Building - Golders Green Stn	Void	Asbestos	Surveyed - Not Detected				Metal Blocks above false ceiling				YES	
8575	ACTIVE	N	N041-00-A/292	Station Supervisor Office - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17816	ACTIVE	N	N041-00-A/292/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Golders Green Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Y	N
8576	ACTIVE	N	N041-00-A/311	Toilet: Unisex - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18376	ACTIVE	N	N041-00-A/311/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Golders Green Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
17818	ACTIVE	N	N041-00-A/311/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Golders Green Stn	Void	Asbestos	Surveyed - Not Detected				Breeze Blocks & Plaster above false ceiling				YES	
17817	ACTIVE	N	N041-00-A/311/CLG-02	Ceiling: Solid - 2 - Toilet - Station Building - Golders Green Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
18153	ACTIVE	N	N041-00-A/311/CLG-02	Ceiling: Solid - 2 - Toilet - Station Building - Golders Green Stn	Void	Asbestos	Surveyed - Not Detected				Breeze Blocks & Plaster above false ceiling				YES	
8577	ACTIVE	N	N041-00-A/312	Office - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17820	ACTIVE	N	N041-00-A/312/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Golders Green Stn	Void	Asbestos	Surveyed - Not Detected				Fibreglass Lagging; Timber, Plaster, Glass Paint; Panels above false ceiling				YES	
17819	ACTIVE	N	N041-00-A/312/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Golders Green Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					



# Hazardous Material Asset Register - Summary



## N041-00 - Station Building - Golders Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8578	ACTIVE	N	N041-00-A/313	Office - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18570	ACTIVE	N	N041-00-A/313	Office - Station Building - Golders Green Stn	LUL Heaters	Asbestos	Surveyed - Not Detected				Supalux panel behind heater					
8579	ACTIVE	N	N041-00-A/316	Locker Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18377	ACTIVE	N	N041-00-A/316	Locker Room - Station Building - Golders Green Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8580	ACTIVE	N	N041-00-A/317	Locker Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17821	ACTIVE	N	N041-00-A/317	Locker Room - Station Building - Golders Green Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
8581	ACTIVE	N	N041-00-A/318	Locker Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17822	ACTIVE	N	N041-00-A/318	Locker Room - Station Building - Golders Green Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
8582	ACTIVE	N	N041-00-A/331	Tea Point - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18378	ACTIVE	N	N041-00-A/331	Tea Point - Station Building - Golders Green Stn		Asbestos	Surveyed - Not Detected				Acoustic Panel below sink					
17823	ACTIVE	N	N041-00-A/331	Tea Point - Station Building - Golders Green Stn	LUL Heaters	Asbestos	Surveyed - Not Detected				Heater					
8583	ACTIVE	N	N041-00-A/332	Mess Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17824	ACTIVE	N	N041-00-A/332/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Golders Green Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Plaster Tiles				YES	
8584	ACTIVE	N	N041-00-A/333	Mess Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17825	ACTIVE	N	N041-00-A/333/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Golders Green Stn	Void	Asbestos	Surveyed - Not Detected				Concrete Supalux Blocks above false ceiling				YES	
8585	ACTIVE	N	N041-00-A/334	Mess Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N041-00 - Station Building - Golders Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18379	ACTIVE	N	N041-00-A/334	Mess Room - Station Building - Golders Green Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
8586	ACTIVE	N	N041-00-A/361	Tea Point - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17826	ACTIVE	N	N041-00-A/361	Tea Point - Station Building - Golders Green Stn		Asbestos	Surveyed - Not Detected				Acoustic Panel below sink					
18154	ACTIVE	N	N041-00-A/361/CLG-01	Ceiling: Suspended - 1 - Tea Point - Station Building - Golders Green Stn	Void	Asbestos	Surveyed - Not Detected				Metal Blocks above false ceiling				YES	
8587	ACTIVE	N	N041-00-A/371	Store - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17827	ACTIVE	N	N041-00-A/371	Store - Station Building - Golders Green Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
8588	ACTIVE	N	N041-00-A/411	Store - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17831	ACTIVE	N	N041-00-A/411	Store - Station Building - Golders Green Stn	Other Electrical Boxes	Asbestos	Surveyed - Not Detected				Grey Metal Box					
17830	ACTIVE	N	N041-00-A/411	Store - Station Building - Golders Green Stn	Other Electrical Boxes	Asbestos	Surveyed - Not Detected				Rope in Electrical Box E8					
18381	ACTIVE	N	N041-00-A/411	Store - Station Building - Golders Green Stn	LUL Heaters	Asbestos	Surveyed - Not Detected				Insulation board within 2x Heaters - Non Asbestos					
18380	ACTIVE	N	N041-00-A/411	Store - Station Building - Golders Green Stn	LUL Heaters	Asbestos	Surveyed - Not Detected				Insulation board within 2x Heaters - Non Asbestos					
17832	ACTIVE	N	N041-00-A/411	Store - Station Building - Golders Green Stn	Durasteel	Asbestos	Surveyed - Not Detected				Boarding to Flame Bin Store					
17829	ACTIVE	N	N041-00-A/411/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Golders Green Stn	Void	Asbestos	Surveyed - Not Detected				Wooden Strut Beams, Metal Flue above false ceiling				YES	
17828	ACTIVE	N	N041-00-A/411/FLR-01	Floor - 1 - Store - Station Building - Golders Green Stn	Void	Asbestos	Surveyed - Not Detected				Wooden Base beneath vinyl tiles					YES
8589	ACTIVE	N	N041-00-A/412	SOM Office - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17834	ACTIVE	N	N041-00-A/412/CLG-01	Ceiling: Suspended - 1 - SOM Office - Station Building - Golders Green Stn	Void	Asbestos	Surveyed - Not Detected				Plasterboard; Fibreglass Lagging above false ceiling				YES	
17833	ACTIVE	N	N041-00-A/412/CLG-01	Ceiling: Suspended - 1 - SOM Office - Station Building - Golders Green Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					



# Hazardous Material Asset Register - Summary



## N041-00 - Station Building - Golders Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8590	ACTIVE	N	N041-00-A/414	Store - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17835	ACTIVE	N	N041-00-A/414	Store - Station Building - Golders Green Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8591	ACTIVE	N	N041-00-A/416	Toilet: Unisex - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18382	ACTIVE	N	N041-00-A/416	Toilet: Unisex - Station Building - Golders Green Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8592	ACTIVE	N	N041-00-A/417	Toilet: Unisex - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17836	ACTIVE	N	N041-00-A/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Golders Green Stn	Void	Asbestos	Surveyed - Not Detected				Metal Blocks above false ceiling				YES	
8593	ACTIVE	N	N041-00-A/418	Toilet: Female - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17837	ACTIVE	N	N041-00-A/418	Toilet: Female - Station Building - Golders Green Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
8594	ACTIVE	N	N041-00-A/419	Toilet: Male - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18383	ACTIVE	N	N041-00-A/419	Toilet: Male - Station Building - Golders Green Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
8595	ACTIVE	N	N041-00-A/420	Toilet: Female - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18155	ACTIVE	N	N041-00-A/420	Toilet: Female - Station Building - Golders Green Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
8596	ACTIVE	N	N041-00-A/437	Waiting Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17838	ACTIVE	N	N041-00-A/437	Waiting Room - Station Building - Golders Green Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
8597	ACTIVE	N	N041-00-A/531	Booking On Point - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17839	ACTIVE	N	N041-00-A/531/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Golders Green Stn	Void	Asbestos	Surveyed - Not Detected				Metal above false ceiling				YES	



# Hazardous Material Asset Register - Summary



## N041-00 - Station Building - Golders Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8598	ACTIVE	N	N041-00-A/576	Stairs: Linear - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19080	ACTIVE	N	N041-00-A/576	Stairs: Linear - Station Building - Golders Green Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8599	ACTIVE	N	N041-00-A/577	Stairs: Linear - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
8600	ACTIVE	N	N041-00-A/578	Stairs: Linear - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17840	ACTIVE	N	N041-00-A/578	Stairs: Linear - Station Building - Golders Green Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Boxing					
8601	ACTIVE	N	N041-00-A/579	Stairs: Linear - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18384	ACTIVE	N	N041-00-A/579	Stairs: Linear - Station Building - Golders Green Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8602	ACTIVE	N	N041-00-A/601	Stairs: Linear - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
8603	ACTIVE	N	N041-00-A/602	Stairs: Linear - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17841	ACTIVE	N	N041-00-A/602	Stairs: Linear - Station Building - Golders Green Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8604	ACTIVE	N	N041-00-A/603	Stairs: Linear - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17842	ACTIVE	N	N041-00-A/603	Stairs: Linear - Station Building - Golders Green Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8605	ACTIVE	N	N041-00-A/604	Stairs: Linear - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17843	ACTIVE	N	N041-00-A/604	Stairs: Linear - Station Building - Golders Green Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux - Above Stairs panels					
8606	ACTIVE	N	N041-00-A/605	Stairs: Linear - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18385	ACTIVE	N	N041-00-A/605	Stairs: Linear - Station Building - Golders Green Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N041-00 - Station Building - Golders Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8607	ACTIVE	N	N041-00-A/661	Switch Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17844	ACTIVE	N	N041-00-A/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Golders Green Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
18156	ACTIVE	N	N041-00-A/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Golders Green Stn	Other Electrical Boxes	Asbestos	Presumed				Electrical Box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
17845	ACTIVE	N	N041-00-A/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Golders Green Stn	Cable Duct: Other	Asbestos	Presumed				Cable Ducts Cable ducts covered by layer of cement on top. Ducts not visible beneath therefore material not scored in 2020 re-inspection.				N	N
8608	ACTIVE	N	N041-00-A/662	Switch Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18386	ACTIVE	N	N041-00-A/662/FLR-01	Floor - 1 - Switch Room - Station Building - Golders Green Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box - between walls 1 & 2 No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
17847	ACTIVE	N	N041-00-A/662/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Golders Green Stn	Cable Duct: Other	Asbestos	Presumed				Cable Ducts Cable ducts are covered by a cement layer on top. Ducts not visible beneath therefore no material score during 2020 re-inspection				N	N
17846	ACTIVE	N	N041-00-A/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Golders Green Stn	Isolator Switches	Asbestos	Presumed				Insulation within 1 x Blue Combination Switch 1 x 100 amps No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
8609	ACTIVE	N	N041-00-A/663	Switch Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17848	ACTIVE	N	N041-00-A/663	Switch Room - Station Building - Golders Green Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8610	ACTIVE	N	N041-00-A/664	Switch Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17849	ACTIVE	N	N041-00-A/664	Switch Room - Station Building - Golders Green Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					



# Hazardous Material Asset Register - Summary



## N041-00 - Station Building - Golders Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8611	ACTIVE	N	N041-00-A/665	Switch Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18571	ACTIVE	N	N041-00-A/665	Switch Room - Station Building - Golders Green Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
8612	ACTIVE	N	N041-00-A/801	Office - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18157	ACTIVE	N	N041-00-A/801	Office - Station Building - Golders Green Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
8613	ACTIVE	N	N041-00-A/951	Disused Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18387	ACTIVE	N	N041-00-A/951/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Golders Green Stn	Void	Asbestos	Surveyed - Not Detected				Wooden Strut Beams, Wooden Slatted above Chipboard Ceiling				YES	
8614	ACTIVE	N	N041-00-A/952	Disused Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19415	ACTIVE	N	N041-00-A/952	Disused Room - Station Building - Golders Green Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
8615	ACTIVE	N	N041-00-A/953	Disused Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17850	ACTIVE	N	N041-00-A/953	Disused Room - Station Building - Golders Green Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
8616	ACTIVE	N	N041-00-A/954	Disused Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
20030	ACTIVE	N	N041-00-A/954	Disused Room - Station Building - Golders Green Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8617	ACTIVE	N	N041-00-A/955	Locker Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
20213	ACTIVE	N	N041-00-A/955	Locker Room - Station Building - Golders Green Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8618	ACTIVE	N	N041-00-A/956	Disused Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19291	ACTIVE	N	N041-00-A/956	Disused Room - Station Building - Golders Green Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N041-00 - Station Building - Golders Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8619	ACTIVE	N	N041-00-A/957	Disused Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
20214	ACTIVE	N	N041-00-A/957	Disused Room - Station Building - Golders Green Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8620	ACTIVE	N	N041-00-A/958	Disused Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
20215	ACTIVE	N	N041-00-A/958	Disused Room - Station Building - Golders Green Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8621	ACTIVE	N	N041-00-A/959	Disused Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19292	ACTIVE	N	N041-00-A/959	Disused Room - Station Building - Golders Green Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8622	ACTIVE	N	N041-00-A/960	Disused Room - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
20216	ACTIVE	N	N041-00-A/960	Disused Room - Station Building - Golders Green Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8623	ACTIVE	N	N041-00-B/576	Stairs: Linear - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
20217	ACTIVE	N	N041-00-B/576	Stairs: Linear - Station Building - Golders Green Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8624	ACTIVE	N	N041-00-B/577	Stairs: Linear - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
20218	ACTIVE	N	N041-00-B/577	Stairs: Linear - Station Building - Golders Green Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8625	ACTIVE	N	N041-00-B/578	Stairs: Linear - Station Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19293	ACTIVE	N	N041-00-B/578	Stairs: Linear - Station Building - Golders Green Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
20219	ACTIVE	N	N041-00-B/636	Overbridge - Station Building - Golders Green Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N043-00 - Station Building - Hampstead Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8652	ACTIVE	N	N043-00-1/001	Booking Hall - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17558	ACTIVE	N	N043-00-1/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Small void above supalux tiles is concrete with metal framework and PVC cables				YES	
8653	ACTIVE	N	N043-00-1/011	Ticket Office - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18072	ACTIVE	N	N043-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				YES	
17560	ACTIVE	N	N043-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
17559	ACTIVE	N	N043-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Hampstead Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
8654	ACTIVE	N	N043-00-1/021	POM - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17561	ACTIVE	N	N043-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above screwed tiles				YES	
17980	ACTIVE	N	N043-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Hampstead Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
8655	ACTIVE	N	N043-00-1/031	Mess Room - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17562	ACTIVE	N	N043-00-1/031	Mess Room - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	No Access: Presumed				Supalux Boxing on Walls					
17563	ACTIVE	N	N043-00-1/031	Mess Room - Station Building - Hampstead Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
17981	ACTIVE	N	N043-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Above false ceiling				YES	
17564	ACTIVE	N	N043-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
8656	ACTIVE	N	N043-00-1/036	Lobby - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17565	ACTIVE	N	N043-00-1/036/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Above false ceiling				YES	



# Hazardous Material Asset Register - Summary



## N043-00 - Station Building - Hampstead Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8657	ACTIVE	N	N043-00-1/037	Toilet: Unisex - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19064	ACTIVE	N	N043-00-1/037/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
17566	ACTIVE	N	N043-00-1/037/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Metal Traywork, Frames, PVC Cables, Rock wall Lagging, Solid Concrete Block work above false ceiling				YES	
8658	ACTIVE	N	N043-00-1/071	Circulation Area - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17567	ACTIVE	N	N043-00-1/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Small void above supalux tiles is concrete with metal framework and PVC cables				YES	
8659	ACTIVE	N	N043-00-1/072	Circulation Area - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17568	ACTIVE	N	N043-00-1/072/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Small void above supalux tiles is concrete with metal framework and PVC cables				YES	
17982	ACTIVE	N	N043-00-1/072/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing into Ceiling					
8660	ACTIVE	N	N043-00-1/236	Lobby - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17569	ACTIVE	N	N043-00-1/236	Lobby - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				White boarding surrounding door way into machine room Supalux					
8661	ACTIVE	N	N043-00-1/237	Lobby - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17571	ACTIVE	N	N043-00-1/237	Lobby - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	No Access: Presumed				Boxing Supalux					
17572	ACTIVE	N	N043-00-1/237/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above screwed tiles				YES	
17570	ACTIVE	N	N043-00-1/237/FLR-01	Floor - 1 - Lobby - Station Building - Hampstead Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
8662	ACTIVE	N	N043-00-1/238	Passage - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17983	ACTIVE	N	N043-00-1/238	Passage - Station Building - Hampstead Stn	Durasteel	Asbestos	Surveyed – Not Detected				Partition Wall - Durasteel - Non Asbestos					



# Hazardous Material Asset Register - Summary



## N043-00 - Station Building - Hampstead Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17573	ACTIVE	N	N043-00-1/239/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Metal Traywork, Frames, PVC Cables above open area				YES	
8664	ACTIVE	N	N043-00-1/412	Store - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17574	ACTIVE	N	N043-00-1/412	Store - Station Building - Hampstead Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
8665	ACTIVE	N	N043-00-1/451	Tenancy - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17575	ACTIVE	N	N043-00-1/451/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Hampstead Stn	Void	Asbestos	No Access: Presumed				No access above tiled ceiling				Y	
8666	ACTIVE	N	N043-00-1/577	Stairs: Linear - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17576	ACTIVE	N	N043-00-1/577	Stairs: Linear - Station Building - Hampstead Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Tenancy					
8667	ACTIVE	N	N043-00-1/578	Stairs: Linear - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17984	ACTIVE	N	N043-00-1/578	Stairs: Linear - Station Building - Hampstead Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Tenancy					
8668	ACTIVE	N	N043-00-1/601	Stairs: Linear - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17577	ACTIVE	N	N043-00-1/601	Stairs: Linear - Station Building - Hampstead Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8669	ACTIVE	N	N043-00-1/631	Stairs: Spiral - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17578	ACTIVE	N	N043-00-1/631/FLR-01	Floor - 1 - Spiral Stairs - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panel bottom of stairs					
8670	ACTIVE	N	N043-00-1/661	Switch Room - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17579	ACTIVE	N	N043-00-1/661/WAL-001/80902826	Wall: Internal - 1 - Switch Room - Station Building - Hampstead Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				4 x Switch Boxes 2 x 60 amp, 2 x 200 amp  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		4		N	N



# Hazardous Material Asset Register - Summary



## N043-00 - Station Building - Hampstead Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17985	ACTIVE	N	N043-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Hampstead Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
20362	ACTIVE	N	N043-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux at lower level					
20360	ACTIVE	N	N043-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Hampstead Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x 60 amp Switch Boxes No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2		N	N
20361	ACTIVE	N	N043-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Hampstead Stn	Isolator Switches	Asbestos	Strongly Presumed				7 x Switch Boxes - 1 x 30amp, 1 x 60amp, 3 x 100amp, 2 x 200amp		7		N	N
8671	ACTIVE	N	N043-00-1/662	Switch Room - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17580	ACTIVE	N	N043-00-1/662	Switch Room - Station Building - Hampstead Stn		Anthrax	Surveyed – Not Detected				No Anthrax Detected					
19065	ACTIVE	N	N043-00-1/662	Switch Room - Station Building - Hampstead Stn	Cable Duct: Other	Asbestos	Presumed				Cable Ducts Cable ducts are not visible beneath layer of cement on floor surface - therefore material not scored in 2020 re-inspection.				N	N
18073	ACTIVE	N	N043-00-1/662/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Boxing - Supalux.					
18469	ACTIVE	N	N043-00-1/662/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Hampstead Stn	Isolator Switches	Asbestos	Strongly Presumed				Insulation within 1x Switch Box - 1 x 30 amps No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
17581	ACTIVE	N	N043-00-1/662/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Hampstead Stn	Other Electrical Boxes	Asbestos	Presumed				3 x Transformer Boxes No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		3		N	N
25719	ACTIVE	N	N043-00-1/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Hampstead Stn	Other Electrical Boxes	Asbestos	Presumed				1x Transformer box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
8672	ACTIVE	N	N043-00-1/663	Switch Cupboard - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N043-00 - Station Building - Hampstead Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17582	ACTIVE	N	N043-00-1/663/WAL-002	Wall: Internal - 2 - Switch Cupboard - Station Building - Hampstead Stn	Isolator Switches	Asbestos	Strongly Presumed				Insulation (arc shutes & flash guards) within 1 x 200 amp Switch Box. Electrical incomer may contain asbestos.  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
8673	ACTIVE	N	N043-00-1/746	SCR - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17583	ACTIVE	N	N043-00-1/746/CLG-01	Ceiling: Suspended - 1 - SCR - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above supalux tiles				YES	
18048	ACTIVE	N	N043-00-1/746/CLG-01	Ceiling: Suspended - 1 - SCR - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				600x600 lay in Supalux Tiles					
8674	ACTIVE	N	N043-00-1/751	Station Supervisor Office - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
17584	INACTIVE	N	N043-00-1/751	Station Supervisor Office - Station Building - Hampstead Stn		Asbestos	Surveyed – Not Detected				Surveyed - No asbestos Detected					
17585	ACTIVE	N	N043-00-1/791	Vent Shaft - Station Building - Hampstead Stn	Caulking	Asbestos	Surveyed – Not Detected				No caulking present in tunnel rings; Only sand and loose concrete material – supalux panels on CER in close proximity to vent shaft. New equipment inside.					
8675	ACTIVE	N	N043-00-2/236	Passage - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17586	ACTIVE	N	N043-00-2/236	Passage - Station Building - Hampstead Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8676	ACTIVE	N	N043-00-2/238	Lobby - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17587	ACTIVE	N	N043-00-2/238/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18049	ACTIVE	N	N043-00-2/238/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Solid & concrete Block work above Supalux Tiles				YES	
8677	ACTIVE	N	N043-00-2/240	Lobby - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17588	ACTIVE	N	N043-00-2/240	Lobby - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	No Access: Presumed				Supalux Boxing					



# Hazardous Material Asset Register - Summary



## N043-00 - Station Building - Hampstead Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8678	ACTIVE	N	N043-00-2/281	Office - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17592	ACTIVE	N	N043-00-2/281	Office - Station Building - Hampstead Stn		Asbestos	Surveyed - Not Detected				Acoustic Panel below sink					
17591	ACTIVE	N	N043-00-2/281	Office - Station Building - Hampstead Stn	LUL Heaters	Asbestos	Surveyed - Not Detected				Heater - white foam backing					
17589	ACTIVE	N	N043-00-2/281	Office - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	No Access: Presumed				Supalux Boxing					
17590	ACTIVE	N	N043-00-2/281/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Hampstead Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above supalux tiles				YES	
18074	ACTIVE	N	N043-00-2/281/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
8679	ACTIVE	N	N043-00-2/316	Locker Room - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18050	ACTIVE	N	N043-00-2/316/CLG-01	Ceiling: Suspended - 1 - Locker - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
17593	ACTIVE	N	N043-00-2/316/CLG-01	Ceiling: Suspended - 1 - Locker - Station Building - Hampstead Stn	Void	Asbestos	Surveyed - Not Detected				Solid & concrete Block work above Supalux Tiles				YES	
8680	ACTIVE	N	N043-00-2/331	Locker Room - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19066	ACTIVE	N	N043-00-2/331	Locker Room - Station Building - Hampstead Stn	LUL Heaters	Asbestos	Surveyed - Not Detected				Heater - foam backing					
18051	ACTIVE	N	N043-00-2/331	Locker Room - Station Building - Hampstead Stn		Asbestos	Surveyed - Not Detected				Acoustic Panel below sink					
17596	ACTIVE	N	N043-00-2/331	Locker Room - Station Building - Hampstead Stn	Lead/Leading	Lead Paint/Lead	Known				Grey & black paint on window frames: EDX analysis indicates in excess of 1%. Now appears to have been painted over in cream.		2		N	N
17595	ACTIVE	N	N043-00-2/331/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Hampstead Stn	Void	Asbestos	Surveyed - Not Detected				Solid & concrete block work above supalux tiles				YES	
17594	ACTIVE	N	N043-00-2/331/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
8681	ACTIVE	N	N043-00-2/411	Store - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N043-00 - Station Building - Hampstead Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18052	ACTIVE	N	N043-00-2/411	Store - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	No Access: Presumed				Supalux Boxing					
8682	ACTIVE	N	N043-00-2/412	Store - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17597	ACTIVE	N	N043-00-2/412	Store - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Shelving					
17598	ACTIVE	N	N043-00-2/412/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux panel					
18053	ACTIVE	N	N043-00-2/412/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Hampstead Stn	Void	Asbestos	No Access: Presumed				Above Supalux panel				YES	
17600	ACTIVE	N	N043-00-2/412/CLG-02	Ceiling: Suspended - 2 - Store - Station Building - Hampstead Stn	Void	Asbestos	No Access: Presumed				Above Supalux panel				YES	
17599	ACTIVE	N	N043-00-2/412/CLG-02	Ceiling: Suspended - 2 - Store - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux panel					
8683	ACTIVE	N	N043-00-2/416	Cleaners Store - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18075	ACTIVE	N	N043-00-2/416/CLG-01	Ceiling: Solid - 1 - Cleaners Store - Station Building - Hampstead Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard					
17601	ACTIVE	N	N043-00-2/416/CLG-01	Ceiling: Solid - 1 - Cleaners Store - Station Building - Hampstead Stn	Void	Asbestos	Surveyed - Not Detected				Solid & concrete block work above plasterboard				YES	
8684	ACTIVE	N	N043-00-2/417	Lobby - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17602	ACTIVE	N	N043-00-2/417/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Hampstead Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard					
17603	ACTIVE	N	N043-00-2/417/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Hampstead Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Plasterboard				YES	
8685	ACTIVE	N	N043-00-2/418	Toilet - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
8686	ACTIVE	N	N043-00-2/419	Toilet: Female - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N043-00 - Station Building - Hampstead Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17605	ACTIVE	N	N043-00-2/419	Toilet: Female - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	No Access: Presumed				Supalux Boxing					
18054	ACTIVE	N	N043-00-2/419/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Hampstead Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard					
17604	ACTIVE	N	N043-00-2/419/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Hampstead Stn	Void	Asbestos	Surveyed - Not Detected				Solid & concrete block work above plasterboard				YES	
8687	ACTIVE	N	N043-00-2/631	Stairs: Spiral - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17606	ACTIVE	N	N043-00-2/631	Stairs: Spiral - Station Building - Hampstead Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8688	ACTIVE	N	N043-00-2/661	Switch Cupboard - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19067	ACTIVE	N	N043-00-2/661	Switch Cupboard - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux panelling around doors					
17607	ACTIVE	N	N043-00-2/661/WAL-002	Wall: Internal - 2 - Switch Cupboard - Station Building - Hampstead Stn	Isolator Switches	Asbestos	Strongly Presumed				Insulation within one grey switch fuse 1 x 100 amps No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
8689	ACTIVE	N	N043-00-2/732	CER - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18055	ACTIVE	N	N043-00-2/732/FLR-01	Floor - 1 - CER - Station Building - Hampstead Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
18221	ACTIVE	N	N043-00-2/732/WAL-002 80903046	Wall: Internal - 2 - CER - Station Building - Hampstead Stn Wall: Internal	Other Boarding	Asbestos	Presumed				2x Paxoline Boards		2		N	N
17608	ACTIVE	N	N043-00-2/732/WAL-004	Wall: Internal - 4 - CER - Station Building - Hampstead Stn	Isolator Switches	Asbestos	Strongly Presumed				Insulation within 2 x 60 amp Grey Switch Fuses No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2		N	N
44004	INACTIVE	N	N043-00-2/732/WAL-010 80903054	Wall: Internal - 10 - CER - Station Building - Hampstead Stn Wall: Internal	Other Boarding	Asbestos	Presumed				Paxoline boarding		1		N	N
8690	ACTIVE	N	N043-00-2/776	Fan Room - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17609	ACTIVE	N	N043-00-2/776	Fan Room - Station Building - Hampstead Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N043-00 - Station Building - Hampstead Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8691	ACTIVE	N	N043-00-2/901	Passage - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17610	ACTIVE	N	N043-00-2/901	Passage - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	No Access: Presumed				Supalux Boxing					
8692	ACTIVE	N	N043-00-2/902	Disused Room - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17611	ACTIVE	N	N043-00-2/902/CLG-01	Ceiling: Solid - 1 - Basement Area - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Roof Area - Concrete Solid above open area				YES	
8693	ACTIVE	N	N043-00-3/201	Passage - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17612	ACTIVE	N	N043-00-3/201	Passage - Station Building - Hampstead Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
18056	ACTIVE	N	N043-00-3/201	Passage - Station Building - Hampstead Stn	Lead/Leading	Lead Paint/Lead	Known				Black Paint: EDX analysis indicates in excess of 1% - Good condition. Black paint has potentially been overpainted with cream/white paint. Potentially black paint below				N	N
8694	ACTIVE	N	N043-00-3/202	Passage - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17613	ACTIVE	N	N043-00-3/202/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Solid & concrete blockwork, PVC cables, tiled walls above false ceiling				YES	
8695	ACTIVE	N	N043-00-3/203	Passage - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17614	ACTIVE	N	N043-00-3/203/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Solid & concrete blockwork, PVC cables, tiled walls above false ceiling				YES	
8696	ACTIVE	N	N043-00-3/204	Passage - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17615	ACTIVE	N	N043-00-3/204/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Solid & concrete blockwork, PVC cables, tiled walls above false ceiling				YES	
8697	ACTIVE	N	N043-00-3/205	Passage - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18076	ACTIVE	N	N043-00-3/205/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Solid & concrete blockwork, PVC cables, tiled walls above false ceiling				YES	



# Hazardous Material Asset Register - Summary



## N043-00 - Station Building - Hampstead Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8698	ACTIVE	N	N043-00-3/206	Passage - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18057	ACTIVE	N	N043-00-3/206/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Solid & concrete blockwork, PVC cables, tiled walls above false ceiling				YES	
8699	ACTIVE	N	N043-00-3/207	Passage - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17711	ACTIVE	N	N043-00-3/207/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Solid & concrete blockwork, PVC cables, tiled walls above false ceiling				YES	
8700	ACTIVE	N	N043-00-3/208	Passage - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17712	ACTIVE	N	N043-00-3/208/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Solid & concrete blockwork, PVC cables, tiled walls above false ceiling				YES	
8701	ACTIVE	N	N043-00-3/209	Passage - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17713	ACTIVE	N	N043-00-3/209/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Solid & concrete blockwork, PVC cables, tiled walls above false ceiling				YES	
17714	ACTIVE	N	N043-00-3/210	Plant Room Access - Station Building - Hampstead Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
18144	ACTIVE	N	N043-00-3/213	Plant Room Access - Station Building - Hampstead Stn	Durasteel	Asbestos	Surveyed – Not Detected				Lift 4 Shaft Access - Durasteel panel inside access door - NAD					
8702	ACTIVE	N	N043-00-3/214	Passage - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17715	ACTIVE	N	N043-00-3/214/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Durasteel side of lifts above metal grid ceiling by lift				YES	
8703	ACTIVE	N	N043-00-3/215	Passage - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17716	ACTIVE	N	N043-00-3/215/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Durasteel side of lifts above metal grid ceiling by lift				YES	
8704	ACTIVE	N	N043-00-3/216	Passage - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N043-00 - Station Building - Hampstead Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17717	ACTIVE	N	N043-00-3/216	Passage - Station Building - Hampstead Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8705	ACTIVE	N	N043-00-3/217	Passage - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17718	ACTIVE	N	N043-00-3/217/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Solid & concrete blockwork, PVC cables, tiled walls above false ceiling				YES	
8706	ACTIVE	N	N043-00-3/411	Store - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17719	ACTIVE	N	N043-00-3/411/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Solid & concrete blockwork, PVC cables, tiled walls above false ceiling				YES	
18145	ACTIVE	N	N043-00-3/411/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
8707	ACTIVE	N	N043-00-3/601	Stairs: Linear - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18224	ACTIVE	N	N043-00-3/601/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Solid & concrete blockwork, PVC cables, tiled walls above false ceiling				YES	
8708	ACTIVE	N	N043-00-3/602	Stairs: Linear - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17720	ACTIVE	N	N043-00-3/602/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Solid & concrete blockwork, PVC cables, tiled walls above false ceiling				YES	
8709	ACTIVE	N	N043-00-3/661	Switch Room - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17722	ACTIVE	N	N043-00-3/661/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Solid & concrete blockwork, PVC cables, tiled walls above false ceiling				YES	
17721	ACTIVE	N	N043-00-3/661/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Metal/ Supalux					
8710	ACTIVE	N	N043-00-3/662	Switch Cupboard - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18146	ACTIVE	N	N043-00-3/662	Switch Cupboard - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels above door					



# Hazardous Material Asset Register - Summary



## N043-00 - Station Building - Hampstead Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor	
8711	ACTIVE	N	N043-00-3/711	SER - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed										
17723	ACTIVE	N	N043-00-3/711	SER - Station Building - Hampstead Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction						
17724	ACTIVE	N	N043-00-3/791	Vent Shaft - Station Building - Hampstead Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible						
8712	ACTIVE	N	N043-00-4/201	Passage - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed										
8713	ACTIVE	N	N043-00-4/202	Passage - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed										
8714	ACTIVE	N	N043-00-4/261	Platform 1 - Northbound Local - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed										
18147	ACTIVE	N	N043-00-4/261	Platform 1 - Northbound Local - Station Building - Hampstead Stn	Cable Ducts: Bitumen	Asbestos	Surveyed - Not Detected				XTX Ducts						
25720	ACTIVE	N	N043-00-4/261	Platform 1 - Northbound Local - Station Building - Hampstead Stn	Cable: Sheath	Asbestos	Known				JH4 1x Cable (Tailwall by 4/771)		1		N	N	
17725	ACTIVE	N	N043-00-4/261	Platform 1 - Northbound Local - Station Building - Hampstead Stn	Cable: Sheath	Asbestos	Strongly Presumed				JH4 1 x cable - (Headwall by 4-711)				N	N	
17727	ACTIVE	N	N043-00-4/261/FLR-01	Floor: Platform - 1 - Platform 1 - Station Building - Hampstead Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - 50mm White Cable to right hand side of cable sleeves, runs along lower J-Hanger, pit side, whole length  No access into platform inverts during 2020 re-inspection - confined space entry required.						YES
17726	ACTIVE	N	N043-00-4/261/FLR-01	Floor: Platform - 1 - Platform 1 - Station Building - Hampstead Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Platform 1 Invert - Cable Sleeves/ Ducts - Mid. Platform  No access into platform inverts during 2020 re-inspection - confined space entry required.						YES
19073	ACTIVE	N	N043-00-4/261/FLR-01	Floor: Platform - 1 - Platform 1 - Station Building - Hampstead Stn	Cable Ducts: Bitumen	Asbestos	Surveyed - Not Detected				Cable Sleeves/ Ducts: Non Asbestos: 4no South End - Concrete, 3no North End Head Wall - Bitumen; 3no Pit Side - Metal; 6no Cable Sleeves by Ladder - Metal						YES
8715	ACTIVE	N	N043-00-4/262	Platform 2 - Southbound Local - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed										



# Hazardous Material Asset Register - Summary



## N043-00 - Station Building - Hampstead Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18085	ACTIVE	N	N043-00-4/262/FLR-01	Floor: Platform - 1 - Platform 2 - Station Building - Hampstead Stn	Cable Ducts: Cement	Asbestos	Known				To lower lift shaft link tunnel Cement Ducts - Chrysotile;  No access into lift shaft link tunnel during 2020 re-inspection - confined space entry via platform inverts required.		2			YES
18566	ACTIVE	N	N043-00-4/262/FLR-01	Floor: Platform - 1 - Platform 2 - Station Building - Hampstead Stn	Cable Ducts: Bitumen	Asbestos	Surveyed – Not Detected				Bitumen Cable Sleeves					YES
17728	ACTIVE	N	N043-00-4/262/FLR-01	Floor: Platform - 1 - Platform 2 - Station Building - Hampstead Stn	Cable: Wrap	Asbestos	Surveyed – Not Detected									YES
18211	ACTIVE	N	N043-00-4/262/FLR-01	Floor: Platform - 1 - Platform 2 - Station Building - Hampstead Stn	Cable: Sheath	Asbestos	Strongly Presumed				Various Cables  No access into platform inverts during 2020 re-inspection - confined space entry required.				N	YES
8716	ACTIVE	N	N043-00-4/661	Switch Room - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20364	ACTIVE	N	N043-00-4/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Hampstead Stn	Cable: Sheath	Asbestos	Surveyed – Not Detected				Red wrapping around cables non asbestos					
17729	ACTIVE	N	N043-00-4/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Hampstead Stn	Isolator Switches	Asbestos	Strongly Presumed				Insulation within 5 x Blue Switch Fuse Boxes 3 x 60 amps, 1 x 100amps, 1 x 200amps  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		5		N	N
17730	ACTIVE	N	N043-00-4/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Hampstead Stn	Other Electrical Boxes	Asbestos	Presumed				2 x Transformer Boxes  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2		N	N
20366	ACTIVE	N	N043-00-4/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Hampstead Stn	Other Boarding	Asbestos	Not Found during Inspection				Paxoline Board					
20363	ACTIVE	N	N043-00-4/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Hampstead Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 60 amp Switch Box  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
8717	ACTIVE	N	N043-00-4/662	Switch Cupboard - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N043-00 - Station Building - Hampstead Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17731	ACTIVE	N	N043-00-4/662/WAL-002	Wall: Internal - 2 - Switch Cupboard - Station Building - Hampstead Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x Switch Fuse Boxes - Insulation within  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2		N	N
8718	ACTIVE	N	N043-00-4/664	Switch Cupboard - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
8719	ACTIVE	N	N043-00-4/701	IMR - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
17732	ACTIVE	N	N043-00-4/701	IMR - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Panel on Walls					
8720	INACTIVE	N	N043-00-4/711	Relay Room - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
44847	INACTIVE	N	N043-00-4/711	Relay Room - Station Building - Hampstead Stn		Asbestos	Strongly Presumed				600v electrical box - insulating materials within removed by DCUK on 14/04/22 as part of TCP					
17733	INACTIVE	N	N043-00-4/711	Relay Room - Station Building - Hampstead Stn	Cable: Sheath	Asbestos	Strongly Presumed				1 x 50mm White Cable, 1x 50mm Green Cable, & 3 x 6mm Cable - removed by DCUK on 14/04/22 as part of TCP		5		N	N
18292	INACTIVE	N	N043-00-4/711	Relay Room - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Partition					
44068	INACTIVE	N	N043-00-4/711	Relay Room - Station Building - Hampstead Stn	Other Boarding	Asbestos	Not Found during Inspection				Paxoline Boarding Walls 1 & 2			Re-Inspection - Alan Hartley		
20365	INACTIVE	N	N043-00-4/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Hampstead Stn	Other Boarding	Asbestos	Strongly Presumed				Paxoline Board - removed by DCUK on 14/04/22 as part of TCP		1		N	N
44005	INACTIVE	N	N043-00-4/711/WAL-001 80903410	Wall: Internal - 1 - Relay Room - Station Building - Hampstead Stn Wall: Internal	PCBs	Polychlorinated biphenyl	Presumed				Blue cylinder, potential PCBS containing		1		N	N
N043	INACTIVE	N	N043-00-4/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Hampstead Stn	Other Boarding	Asbestos	Not Found during Inspection				Paxoline Board					
17734	INACTIVE	N	N043-00-4/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Hampstead Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				8 x PCB's - located within a roller shutter cabinet. Fair Condition. Serial no. not visible		8		N	N
8721	ACTIVE	N	N043-00-4/712	Relay Room - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18293	INACTIVE	N	N043-00-4/712	Relay Room - Station Building - Hampstead Stn	Cable: Sheath	Asbestos	Not Found during Inspection				1 x 0.5m x 20mm Cables  Cable not present during 2020 re-inspection		1		N	N



# Hazardous Material Asset Register - Summary



## N043-00 - Station Building - Hampstead Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20368	ACTIVE	N	N043-00-4/712 80143089	Relay Room - Station Building - Hampstead Stn Room Assets	Other Boarding	Asbestos	Strongly Presumed				3x Paxoline Board on various walls		3		N	N
17735	ACTIVE	N	N043-00-4/712	Relay Room - Station Building - Hampstead Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Cable Ducts				N	N
17736	ACTIVE	N	N043-00-4/712	Relay Room - Station Building - Hampstead Stn	Cable: Sheath	Asbestos	Strongly Presumed				4 x 5m x 20mm Cables		4		N	N
42325	INACTIVE	N	N043-00-4/712	Relay Room - Station Building - Hampstead Stn	PCBs	Polychlorinated biphenyl	Removed				3 x blue cylinder IPCB's ocated on racks - fair condition Re moved buy others date un known		3		N	N
8722	ACTIVE	N	N043-00-4/713	Relay Room - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17738	ACTIVE	N	N043-00-4/713	Relay Room - Station Building - Hampstead Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cable 4x 20mm		4		N	N
20369	ACTIVE	N	N043-00-4/713/ WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Hampstead Stn	Westing house Boxes	Asbestos	Strongly Presumed				2 x Westinghouse Boxes  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2		N	N
18294	INACTIVE	N	N043-00-4/713/ WAL-002 80903427	Wall: Internal - 2 - Relay Room - Station Building - Hampstead Stn Wall: Internal	PCBs	Polychlorinated biphenyl	Strongly Presumed				3 3x black boxes all potential PCBs.Fair Condition. Serial Nos not visible		3		N	N
17737	ACTIVE	N	N043-00-4/713/ WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Hampstead Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Loose Board (1m <sup>2</sup> ) by wall 3		1			
8723	ACTIVE	N	N043-00-4/771	Pump Room - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19074	ACTIVE	N	N043-00-4/771	Pump Room - Station Building - Hampstead Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8724	ACTIVE	N	N043-00-4/901	Store - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17739	ACTIVE	N	N043-00-4/901	Store - Station Building - Hampstead Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8725	ACTIVE	N	N043-00-4/902	Store - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17740	ACTIVE	N	N043-00-4/902	Store - Station Building - Hampstead Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8726	ACTIVE	N	N043-00-4/903	Equipment Room - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N043-00 - Station Building - Hampstead Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17741	ACTIVE	N	N043-00-4/903	Equipment Room - Station Building - Hampstead Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8727	ACTIVE	N	N043-00-4/951	Platform Invert - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18086	ACTIVE	N	N043-00-4/951	Platform Invert - Station Building - Hampstead Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cable 50mm		1			
8728	ACTIVE	N	N043-00-A/131	LMR - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18295	INACTIVE	N	N043-00-A/131	LMR - Station Building - Hampstead Stn	Paper Asbestos	Asbestos	Removed				4 x Drive Controller - Transformer (Paper Wrap) Upon re-inspection surveyor concluded these items were not present/removed 24-07-2014		4			
43332	ACTIVE	N	N043-00-A/131/DOR-01	Door - 1 - LMR - Station Building - Hampstead Stn		Asbestos	Sampled – Not Detected				Durasteel panel 1m2 located above exit doors to Lift No 2			R557001	N	N
18567	ACTIVE	N	N043-00-A/131/DOR-01	Door - 1 - LMR - Station Building - Hampstead Stn	Durasteel	Asbestos	Surveyed – Not Detected				Emergency Exit Door (2m2) - Durasteel					
17742	ACTIVE	N	N043-00-A/131/WAL-003 80903479	Wall: Internal - 3 - LMR - Station Building - Hampstead Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Insulation within 4 x Blue Fuse Switches 2 x 60 amps, 1 x 100 amps, 1 x 200 amps No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		4		N	N
20371	ACTIVE	N	N043-00-A/131/WAL-004	Wall: Internal - 4 - LMR - Station Building - Hampstead Stn	Isolator Switches	Asbestos	Strongly Presumed				Insulation within 4 x Blue Fuse Switches 2 x 60 amps, 1 x 100 amps, 1 x 200 amps No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		4		N	N
8729	ACTIVE	N	N043-00-A/236	Passage - Station Building - Hampstead Stn	Stations: Rooms	Lead Paint/Lead	Room: Not Surveyed – Asbestos Presumed				Lead paint on Wall 3 presumed					
17743	ACTIVE	N	N043-00-A/236/WAL-003	Wall: Internal - 3 - Passage - Station Building - Hampstead Stn	Lead/Leading	Lead Paint/Lead	Presumed				Wall 3 possibly Lead paint				N	N
8730	ACTIVE	N	N043-00-A/237	Passage - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17744	ACTIVE	N	N043-00-A/237	Passage - Station Building - Hampstead Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel					



# Hazardous Material Asset Register - Summary



## N043-00 - Station Building - Hampstead Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8731	INACTIVE	N	N043-00-A/238	Passage - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17745	ACTIVE	N	N043-00-A/238/WAL-003	Wall: Internal - 3 - Passage - Station Building - Hampstead Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access					
8732	ACTIVE	N	N043-00-A/576	Ladder - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17747	ACTIVE	N	N043-00-A/576	Ladder - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels by Door					
17746	ACTIVE	N	N043-00-A/576	Ladder - Station Building - Hampstead Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel					
8733	ACTIVE	N	N043-00-A/661	Switch Cupboard - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18087	ACTIVE	N	N043-00-A/661	Switch Cupboard - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels above door					
8734	ACTIVE	N	N043-00-A/761	Tank Room - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18296	ACTIVE	N	N043-00-A/761	Tank Room - Station Building - Hampstead Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8735	INACTIVE	N	N043-00-A/801	Office - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17748	ACTIVE	N	N043-00-A/801	Office - Station Building - Hampstead Stn	No Access	Asbestos	No Access: Presumed				Restaurant - No Access from Station					
8736	ACTIVE	N	N043-00-B/131	LMR - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17749	ACTIVE	N	N043-00-B/131	LMR - Station Building - Hampstead Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard Panels					
17750	INACTIVE	N	N043-00-B/131	LMR - Station Building - Hampstead Stn	Cable: Sheath	Asbestos	Removed				Cables					
18297	ACTIVE	N	N043-00-B/131/CLG-01	Ceiling: Solid - 1 - Lift Motor Room - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Above false ceiling				YES	
20372	ACTIVE	N	N043-00-B/131/WAL-003	Wall: Internal - 3 - Lift Motor Room - Station Building - Hampstead Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N



# Hazardous Material Asset Register - Summary



## N043-00 - Station Building - Hampstead Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8737	ACTIVE	N	N043-00-B/576	Stairs: Linear - Station Building - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17751	ACTIVE	N	N043-00-B/576/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Metal traywork and PVC cables, solid ceiling above false ceiling				YES	
19075	ACTIVE	N	N043-00-B/576/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					

## N045-00 - Station Building - Belsize Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8739	ACTIVE	N	N045-00-1/001	Booking Hall - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17526	ACTIVE	N	N045-00-1/001	Booking Hall - Station Building - Belsize Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8740	ACTIVE	N	N045-00-1/011	Ticket Office - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17527	ACTIVE	N	N045-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Belsize Park Stn	Void	Asbestos	Surveyed – Not Detected				Concrete/ Plaster above false ceiling				YES	
42551	ACTIVE	N	N045-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Belsize Park Stn	Mastic	Asbestos	Surveyed – Not Detected				Mastic/Putty to ducting above false ceiling throughout			R511551	Y	N
17971	ACTIVE	N	N045-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Belsize Park Stn	Void	Asbestos	Surveyed – Not Detected				Metal Tray Work and Concrete; Non Asbestos Ducts beneath Computer Flooring					YES
8741	ACTIVE	N	N045-00-1/021	POM - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17529	ACTIVE	N	N045-00-1/021	POM - Station Building - Belsize Park Stn	Void	Asbestos	No Access: Presumed				Supalux/ Plasterboard - Boxing to Wall					
17530	ACTIVE	N	N045-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Belsize Park Stn	Void	Asbestos	Surveyed – Not Detected				Concrete/ Plaster above false ceiling				YES	
17528	ACTIVE	N	N045-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Belsize Park Stn	Void	Asbestos	Surveyed – Not Detected				Metal Tray Work and Concrete; Non Asbestos Ducts beneath Computer Flooring					YES
8742	ACTIVE	N	N045-00-1/031	Mess Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N045-00 - Station Building - Belsize Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17531	ACTIVE	N	N045-00-1/031	Mess Room - Station Building - Belsize Park Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
17972	ACTIVE	N	N045-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Belsize Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18069	ACTIVE	N	N045-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Belsize Park Stn	Void	Asbestos	Surveyed – Not Detected				Concrete/ Plaster above false ceiling				YES	
8743	ACTIVE	N	N045-00-1/036	Lobby - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17534	ACTIVE	N	N045-00-1/036	Lobby - Station Building - Belsize Park Stn	Void	Asbestos	No Access: Presumed				Supalux Boxing - No Access within					
17533	ACTIVE	N	N045-00-1/036/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Belsize Park Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				YES	
17532	ACTIVE	N	N045-00-1/036/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Belsize Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
8744	ACTIVE	N	N045-00-1/037	Toilet: Unisex - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17536	ACTIVE	N	N045-00-1/037	Toilet: Unisex - Station Building - Belsize Park Stn	Void	Asbestos	No Access: Presumed				Wooden Boxing - No Access within					
17973	ACTIVE	N	N045-00-1/037/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Belsize Park Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				YES	
17535	ACTIVE	N	N045-00-1/037/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Belsize Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
8745	ACTIVE	N	N045-00-1/071	Circulation Area - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17537	ACTIVE	N	N045-00-1/071	Circulation Area - Station Building - Belsize Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8746	ACTIVE	N	N045-00-1/072	Circulation Area - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17538	ACTIVE	N	N045-00-1/072	Circulation Area - Station Building - Belsize Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8747	ACTIVE	N	N045-00-1/081	Lobby - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N045-00 - Station Building - Belsize Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17539	ACTIVE	N	N045-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Belsize Park Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
17974	ACTIVE	N	N045-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Belsize Park Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above false ceiling				YES	
8748	ACTIVE	N	N045-00-1/181	Forecourt - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
20024	ACTIVE	N	N045-00-1/181	Forecourt - Station Building - Belsize Park Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8749	ACTIVE	N	N045-00-1/182	Yard - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17540	ACTIVE	N	N045-00-1/182	Yard - Station Building - Belsize Park Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8750	ACTIVE	N	N045-00-1/183	Forecourt - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17541	ACTIVE	N	N045-00-1/183	Forecourt - Station Building - Belsize Park Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8751	ACTIVE	N	N045-00-1/236	Lobby - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17543	ACTIVE	N	N045-00-1/236	Lobby - Station Building - Belsize Park Stn	Void	Asbestos	No Access: Presumed				Metal Boxing - No Access within					
17542	ACTIVE	N	N045-00-1/236/CLG-01 80882792	Ceiling: Suspended - 1 - Lobby - Station Building - Belsize Park Stn Ceiling: Suspended	Void	Asbestos	No Access: Presumed				Above screwed tiles above room 1/662				Y	N
18070	ACTIVE	N	N045-00-1/236/FLR-01	Floor - 1 - Lobby - Station Building - Belsize Park Stn	Void	Asbestos	Surveyed - Not Detected				Metal Tray Work and Concrete; Non Asbestos Ducts beneath Computer Flooring					YES
8752	ACTIVE	N	N045-00-1/237	Passage - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17975	ACTIVE	N	N045-00-1/237/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Belsize Park Stn	Durasteel	Asbestos	Surveyed - Not Detected				Durasteel non asbestos					
17616	ACTIVE	N	N045-00-1/237/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Belsize Park Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				YES	
8753	ACTIVE	N	N045-00-1/238	Lobby - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N045-00 - Station Building - Belsize Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17617	ACTIVE	N	N045-00-1/238	Lobby - Station Building - Belsize Park Stn	Void	Asbestos	Surveyed – Not Detected				Supalux Boxing (Hollow with PVC cables passing through)					
8754	ACTIVE	N	N045-00-1/311	Mess Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18058	ACTIVE	N	N045-00-1/311	Mess Room - Station Building - Belsize Park Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Foam backing					
8755	ACTIVE	N	N045-00-1/331	Mess Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17619	ACTIVE	N	N045-00-1/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Belsize Park Stn	Other Boarding	Asbestos	No Access: Presumed				Above false ceiling					
17618	ACTIVE	N	N045-00-1/331/FLR-01	Floor - 1 - Mess Room - Station Building - Belsize Park Stn	Void	Asbestos	No Access: Presumed				Beneath Rubber Flooring					YES
8756	ACTIVE	N	N045-00-1/406	Bin Store - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17620	ACTIVE	N	N045-00-1/406	Bin Store - Station Building - Belsize Park Stn	Void	Asbestos	Surveyed – Not Detected				Supalux Boxing (Hollow with PVC cables passing through)					
8757	ACTIVE	N	N045-00-1/416	Toilet: Unisex - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8758	ACTIVE	N	N045-00-1/417	Toilet: Unisex - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18059	ACTIVE	N	N045-00-1/417	Toilet: Unisex - Station Building - Belsize Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
8759	ACTIVE	N	N045-00-1/426	Toilet: Female - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17621	ACTIVE	N	N045-00-1/426/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Belsize Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
17622	ACTIVE	N	N045-00-1/426/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Belsize Park Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Fibreglass Lagging above false ceiling				YES	
8760	ACTIVE	N	N045-00-1/427	Toilet: Male - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18077	ACTIVE	N	N045-00-1/427/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Belsize Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					



# Hazardous Material Asset Register - Summary



## N045-00 - Station Building - Belsize Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17623	ACTIVE	N	N045-00-1/427/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Belsize Park Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Lagging on Pipes above false ceiling				YES	
8761	ACTIVE	N	N045-00-1/576	Stairs: Linear - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18060	ACTIVE	N	N045-00-1/576	Stairs: Linear - Station Building - Belsize Park Stn	Durasteel	Asbestos	Surveyed – Not Detected				New Durasteel Panels;					
19068	ACTIVE	N	N045-00-1/576	Stairs: Linear - Station Building - Belsize Park Stn	Caulking	Asbestos	Surveyed – Not Detected				Steel Tunnel Rings - Non Asbestos					
8762	ACTIVE	N	N045-00-1/578	Lobby - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17624	ACTIVE	N	N045-00-1/578	Lobby - Station Building - Belsize Park Stn	No Access	Asbestos	No Access: Presumed				New Construction? Stairs leading to passage A/237 - 190 Haverstock?					
8763	ACTIVE	N	N045-00-1/631	Stairs: Spiral - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17625	ACTIVE	N	N045-00-1/631	Stairs: Spiral - Station Building - Belsize Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8764	ACTIVE	N	N045-00-1/661	Switch Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18061	ACTIVE	N	N045-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Belsize Park Stn	Isolator Switches	Asbestos	Strongly Presumed				Insulation with Switch Boxes x 5. 1x 200amp, 1 x 60amp, 3 x 100 amps No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score materials within.		5		N	N
17626	ACTIVE	N	N045-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Belsize Park Stn	Isolator Switches	Asbestos	Strongly Presumed				Insulation with Switch Boxes 1 x 30amp No electrician on site during 2020 reinspection to open box for inspection - therefore cannot score materials within.		1		N	N
25721	ACTIVE	N	N045-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Belsize Park Stn	Other Electrical Boxes	Asbestos	Presumed				3x Transformer boxes No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score materials within.		3		N	N
17627	ACTIVE	N	N045-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Belsize Park Stn	Isolator Switches	Asbestos	Strongly Presumed				Insulation with Switch Boxes x 4 - 2 x 100amps, 2 x 60amps No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score materials within.		4		N	N



# Hazardous Material Asset Register - Summary



## N045-00 - Station Building - Belsize Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17628	ACTIVE	N	N045-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Belsize Park Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box  No electrician on site during 20202 reinspection to open box for inspection - therefore cannot score materials within.		1		N	N
8765	ACTIVE	N	N045-00-1/662	Switch Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17630	ACTIVE	N	N045-00-1/662/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Belsize Park Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Plaster above false ceiling				YES	
17629	ACTIVE	N	N045-00-1/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Belsize Park Stn	Isolator Switches	Asbestos	Strongly Presumed				Insulation within 9 x Switch Fuse Boxes - 2 x 100amp, 1 x 30amp, 5 x 60amp, 1 x 200amps  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score materials within.		9		N	N
8766	ACTIVE	N	N045-00-1/711	Relay Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18078	ACTIVE	N	N045-00-1/711	Relay Room - Station Building - Belsize Park Stn	Vinyl tiles	Asbestos	Strongly Presumed				Vinyl tiles on all walls, (substation)  some tiles have been removed historically and adhesive remains		30			
8767	ACTIVE	N	N045-00-1/746	SCR - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18062	ACTIVE	N	N045-00-1/746/CLG-01	Ceiling: Suspended - 1 - SCR - Station Building - Belsize Park Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Supalux Panel above false ceiling				YES	
8768	ACTIVE	N	N045-00-1/776	Fan Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18561	ACTIVE	N	N045-00-1/776	Fan Room - Station Building - Belsize Park Stn	Durasteel	Asbestos	Sampled – Not Detected									
8769	ACTIVE	N	N045-00-1/781	Transformer Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17631	ACTIVE	N	N045-00-1/781/CLG-01	Ceiling: Solid - 1 - Transformer Room - Station Building - Belsize Park Stn	Cellactite Sheeting	Asbestos	Strongly Presumed				Corrugated sheeting and skylights (substation)  DSC05225 - Corrugated sheets (MMMMF) to ceiling 20mx40m DSC05226 - Rope seals to glazing bars of skylights to ceiling throughout					



# Hazardous Material Asset Register - Summary



## N045-00 - Station Building - Belsize Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8770	ACTIVE	N	N045-00-1/901	Void - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17632	ACTIVE	N	N045-00-1/901	Void - Station Building - Belsize Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8771	ACTIVE	N	N045-00-1/951	Disused Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17633	ACTIVE	N	N045-00-1/951	Disused Room - Station Building - Belsize Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8772	ACTIVE	N	N045-00-2/201	Passage - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17634	ACTIVE	N	N045-00-2/201	Passage - Station Building - Belsize Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8773	ACTIVE	N	N045-00-2/631	Stairs: Spiral - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18063	ACTIVE	N	N045-00-2/631	Stairs: Spiral - Station Building - Belsize Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8774	ACTIVE	N	N045-00-2/661	Switch Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17635	ACTIVE	N	N045-00-2/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Belsize Park Stn	Isolator Switches	Asbestos	Strongly Presumed				4x Switch Boxes No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score materials within.		4			
18222	INACTIVE	N	N045-00-2/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Belsize Park Stn	Isolator Switches	Asbestos	Removed				4 x Switch Boxes		4			
8775	ACTIVE	N	N045-00-2/662	Switch Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8776	ACTIVE	N	N045-00-2/731	CER - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17636	ACTIVE	N	N045-00-2/731/FLR-01	Floor - 1 - CER - Station Building - Belsize Park Stn	Cable Duct: Other	Asbestos	Presumed				Restricted Access - Not possible to sample Duct Material (P); Metal Traywork and PVC Cables observed beneath Computer Flooring  Floor void congested and equipment on false floor fixed restricting access				N	Y



# Hazardous Material Asset Register - Summary



## N045-00 - Station Building - Belsize Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18064	ACTIVE	N	N045-00-2/731/WAL-003	Wall: Internal - 3 - CER - Station Building - Belsize Park Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x Switch Boxes No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score materials within.		2		N	N
20374	ACTIVE	N	N045-00-2/731/WAL-004	Wall: Internal - 4 - CER - Station Building - Belsize Park Stn	Other Boarding	Asbestos	Presumed				Paxoline Board				N	N
17637	ACTIVE	N	N045-00-2/791	Vent Shaft - Station Building - Belsize Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8777	ACTIVE	N	N045-00-2/951	Disused Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17638	ACTIVE	N	N045-00-2/951	Disused Room - Station Building - Belsize Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8778	ACTIVE	N	N045-00-3/201	Passage - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19069	ACTIVE	N	N045-00-3/201	Passage - Station Building - Belsize Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8779	ACTIVE	N	N045-00-3/202	Passage - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18065	ACTIVE	N	N045-00-3/202	Passage - Station Building - Belsize Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8780	ACTIVE	N	N045-00-3/203	Passage - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17639	ACTIVE	N	N045-00-3/203	Passage - Station Building - Belsize Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8781	ACTIVE	N	N045-00-3/411	Store - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17640	ACTIVE	N	N045-00-3/411/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Belsize Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Concrete/ Supalux					
8782	ACTIVE	N	N045-00-3/412	CER - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17641	ACTIVE	N	N045-00-3/412	CER - Station Building - Belsize Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8783	ACTIVE	N	N045-00-3/601	Stairs: Linear - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N045-00 - Station Building - Belsize Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18066	ACTIVE	N	N045-00-3/601	Stairs: Linear - Station Building - Belsize Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8784	ACTIVE	N	N045-00-3/602	Stairs: Linear - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17642	ACTIVE	N	N045-00-3/602	Stairs: Linear - Station Building - Belsize Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
17643	ACTIVE	N	N045-00-3/636	Overbridge - Station Building - Belsize Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
17644	ACTIVE	N	N045-00-3/637	Overbridge - Station Building - Belsize Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8785	ACTIVE	N	N045-00-4/081	Store - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8786	ACTIVE	N	N045-00-4/121	Platform Invert - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18067	ACTIVE	N	N045-00-4/121	Platform Invert - Station Building - Belsize Park Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Rings - Platform Walls					
19070	ACTIVE	N	N045-00-4/121	Platform Invert - Station Building - Belsize Park Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform Invert 1 - 1 x 50mm Cable going to Tunnel Inverts through floor and then back out of invert ceiling  No access during 2020 reinspection - Confined space team required to gain access to invert.					
8787	ACTIVE	N	N045-00-4/122	Platform Invert - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17645	ACTIVE	N	N045-00-4/122	Platform Invert - Station Building - Belsize Park Stn	No Access	Asbestos	No Access: Presumed				Invert only half surveyed - Key Missing					
17646	ACTIVE	N	N045-00-4/122	Platform Invert - Station Building - Belsize Park Stn	Cable: Wrap	Asbestos	Strongly Presumed				Woven insulated cables running in all hangers in platform side cable run and gaskets to metal pipe - runs extra length of Platform 2 invert.  No access during 2020 reinspection - Confined space team required to gain access to invert.					
17647	ACTIVE	N	N045-00-4/122	Platform Invert - Station Building - Belsize Park Stn	Cable Duct: Other	Asbestos	Surveyed – Not Detected				Departure end of invert – all Cable Ducts identified as Ceramic					
8788	ACTIVE	N	N045-00-4/123	Switch Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N045-00 - Station Building - Belsize Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18068	ACTIVE	N	N045-00-4/123	Switch Room - Station Building - Belsize Park Stn	Cable: Sheath	Asbestos	Strongly Presumed				1 x 50mm Cable going to Tunnel Inverts through floor and then back out of invert ceiling  No access during 2020 reinspection - Confined space team required to gain access to invert.					
8789	ACTIVE	N	N045-00-4/201	Passage - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
8790	ACTIVE	N	N045-00-4/202	Passage - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
8791	ACTIVE	N	N045-00-4/203	Passage - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
8792	ACTIVE	N	N045-00-4/261	Platform 1 - Northbound Local - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17649	ACTIVE	N	N045-00-4/261	Platform 1 - Northbound Local - Station Building - Belsize Park Stn	Gasket :Pipework	Asbestos	Known				Platform 1 Invert - N/B Arrivals End Gasket (material within flange to water pipe within invert below valve point midway, Invert Plat 1  No access during 2020 reinspection - Confined space team required to gain access to invert.					Y
17650	ACTIVE	N	N045-00-4/261	Platform 1 - Northbound Local - Station Building - Belsize Park Stn	Gasket :Pipework	Asbestos	Surveyed - Not Detected				Gasket (Material witin flange) to water pipe within invert toward arrivals end, Plat 1 N/B					Y
17648	ACTIVE	N	N045-00-4/261	Platform 1 - Northbound Local - Station Building - Belsize Park Stn	Cable: Sheath	Asbestos	Strongly Presumed				1 x 50mm Cable going to Tunnel Inverts 4/121 through floor of 4/123 and then back out of invert ceiling  Material within 1x Small Westinghouse box and 3x link boxes to wall at tail end - presume ACMs within				N	N
8793	ACTIVE	N	N045-00-4/262	Platform 2 - Southbound Local - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18079	ACTIVE	N	N045-00-4/262	Platform 2 - Southbound Local - Station Building - Belsize Park Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables from 4/711 to tunnel		3		N	N
8794	ACTIVE	N	N045-00-4/661	Store - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
8795	ACTIVE	N	N045-00-4/662	Switch Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N045-00 - Station Building - Belsize Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18128	ACTIVE	N	N045-00-4/662	Switch Room - Station Building - Belsize Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panel above door					
19413	ACTIVE	N	N045-00-4/662/ WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Belsize Park Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x 60amp, 1 x 100 amp Switch Fuse Boxes  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score materials within.		3		N	N
8796	ACTIVE	N	N045-00-4/663	Switch Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17652	ACTIVE	N	N045-00-4/663	Switch Room - Station Building - Belsize Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panel above door					
17651	ACTIVE	N	N045-00-4/663/ WAL-002 80883289	Wall: Internal - 2 - Switch Room - Station Building - Belsize Park Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Insulation within 5 x Switch Fuse Boxes - 1 x 200am, 2 x 100amp, 2 x 60amp  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score materials within.		5		N	N
20377	ACTIVE	N	N045-00-4/663/ WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Belsize Park Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Boxes x 3  2 out of 3 boxes remain at present - 1x box removed historically.		2		N	N
8797	ACTIVE	N	N045-00-4/664	Switch Cupboard - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17653	ACTIVE	N	N045-00-4/664	Switch Cupboard - Station Building - Belsize Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8798	ACTIVE	N	N045-00-4/665	Switch Cupboard - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18129	ACTIVE	N	N045-00-4/665	Switch Cupboard - Station Building - Belsize Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8799	ACTIVE	N	N045-00-4/711	Relay Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53534	ACTIVE	N	N045-00-4/711/ WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Belsize Park Stn	Cable: Sheath	Asbestos	Strongly Presumed				1x asbestos cable, next to lead cables entering duct within first roller shutter to wall 1					
53537	ACTIVE	N	N045-00-4/711/ WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Belsize Park Stn	Cable Ducts: Cement	Asbestos	Presumed				duct to invert - in roller shutter - no access					
53533	ACTIVE	N	N045-00-4/711/ WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Belsize Park Stn	Other Boarding	Asbestos	Presumed				2x brown composite boarding within the first roller shutter to wall 1					



# Hazardous Material Asset Register - Summary



## N045-00 - Station Building - Belsize Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17655	INACTIVE	N	N045-00-4/711/WAL-001 80883314	Wall: Internal - 1 - Relay Room - Station Building - Belsize Park Stn Wall: Internal	PCBs	Polychlorinated biphenyl	Removed				8 x PCB's - very poor condition and showing signs of leakage. Located within a roller shutter cabinet. Serial nos not visible 26/02/2016 still poor condition on re inspection Removed by Edenbeck Feb 2017		8		N	N
17654	ACTIVE	N	N045-00-4/711/WAL-002 80883315	Wall: Internal - 2 - Relay Room - Station Building - Belsize Park Stn Wall: Internal	Cable: Sheath	Asbestos	Strongly Presumed				Asbestos Cables WALL 3 going into trackside				N	N
53535	ACTIVE	N	N045-00-4/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Belsize Park Stn	Cable: Sheath	Asbestos	Strongly Presumed				2 x 50mm asbestos cables from 600v electrical box to wall 2 into wall 3 (track)					
53536	ACTIVE	N	N045-00-4/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Belsize Park Stn	Other Boarding	Asbestos	Strongly Presumed				composite boarding to large metal box electrical wall 2					
8800	ACTIVE	N	N045-00-4/712	Relay Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19542	ACTIVE	N	N045-00-4/712	Relay Room - Station Building - Belsize Park Stn	Cable: Sheath	Asbestos	Strongly Presumed				1 x 50mm Cable going to Tunnel Inverts - Type 3 states 2 x Cables				N	N
18562	ACTIVE	N	N045-00-4/712	Relay Room - Station Building - Belsize Park Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Panels on wall					
53540	ACTIVE	N	N045-00-4/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Belsize Park Stn	Cable Ducts: Cement	Asbestos	Presumed				Duct to floor through to invert , in rack 2 (first roller shutter to door) wall 1					
53539	ACTIVE	N	N045-00-4/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Belsize Park Stn	Other Boarding	Asbestos	Presumed				small composite boarding top and bottom of transformer booster, within rack 2 (first roller shutter to door) wall 1					
17656	INACTIVE	N	N045-00-4/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Belsize Park Stn	PCBs	Polychlorinated biphenyl	Removed				8 x PCB's located within a roller cabinet - very poor condition with signs of Leakage. Serial nos not visible Removed by Edenbeck 2017		8		N	N
20390	ACTIVE	N	N045-00-4/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Belsize Park Stn	Other Boarding	Asbestos	Presumed				1x large composite board approx, 1x2m to wall 3		2		N	N
53538	ACTIVE	N	N045-00-4/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Belsize Park Stn	Other Boarding	Asbestos	Surveyed - Not Detected				smaller composite board to wall 3 (new material)					
8801	ACTIVE	N	N045-00-4/771	Pump Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18130	ACTIVE	N	N045-00-4/771	Pump Room - Station Building - Belsize Park Stn	Cable: Sheath	Asbestos	Removed				20mm Cables going to Invert 1m Cables not present during 2020 reinspection					
20395	ACTIVE	N	N045-00-4/771/FLR-01	Floor - 1 - Pump Room - Station Building - Belsize Park Stn	Gasket :Pipework	Asbestos	Presumed				Gaskets to Flanges - asbestos presumed					



# Hazardous Material Asset Register - Summary



## N045-00 - Station Building - Belsize Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17657	ACTIVE	N	N045-00-5/136	Lift Shaft - Station Building - Belsize Park Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
8802	ACTIVE	N	N045-00-A/081	Lobby - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17658	ACTIVE	N	N045-00-A/081	Lobby - Station Building - Belsize Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel					
8803	ACTIVE	N	N045-00-A/082	Lobby - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17659	ACTIVE	N	N045-00-A/082	Lobby - Station Building - Belsize Park Stn	Durasteel	Asbestos	Surveyed – Not Detected				2 x Trapdoors - Durasteel 1990 Manufactured					
8804	ACTIVE	N	N045-00-A/131	LMR - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18131	ACTIVE	N	N045-00-A/131	LMR - Station Building - Belsize Park Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel Panelling					
17660	ACTIVE	N	N045-00-A/131/WAL-003	Wall: Internal - 3 - LMR - Station Building - Belsize Park Stn	Isolator Switches	Asbestos	Removed				Insulation 5 x Fuse Boxes - 4 x 60amps, 1 x 100 amps  Removed not present during 2020 reinspection within room as new lift equipment, upgrade and works being carried out at present.		5		N	N
8805	ACTIVE	N	N045-00-A/236	Passage - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17661	ACTIVE	N	N045-00-A/236	Passage - Station Building - Belsize Park Stn	No Access	Asbestos	No Access: Presumed				New Construction? Mess Room leading on to passage A/237 - 190 Haverstock?					
8806	ACTIVE	N	N045-00-A/237	Passage - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17662	ACTIVE	N	N045-00-A/237	Passage - Station Building - Belsize Park Stn	No Access	Asbestos	No Access: Presumed				New Construction? Mess Room leading on to passage A/236 - 190 Haverstock?					
8807	ACTIVE	N	N045-00-A/281	Station Supervisor Office - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18080	ACTIVE	N	N045-00-A/281	Station Supervisor Office - Station Building - Belsize Park Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Tiles to Floor and Walls				YES	
17663	ACTIVE	N	N045-00-A/281	Station Supervisor Office - Station Building - Belsize Park Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				White Foam Backing					



# Hazardous Material Asset Register - Summary



## N045-00 - Station Building - Belsize Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17544	ACTIVE	N	N045-00-A/281/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Belsize Park Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				YES	
19002	ACTIVE	N	N045-00-A/281/CLG-02	Ceiling: Suspended - 2 - Station Supervisor Office - Station Building - Belsize Park Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				YES	
8808	ACTIVE	N	N045-00-A/316	Locker Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17545	ACTIVE	N	N045-00-A/316	Locker Room - Station Building - Belsize Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8809	ACTIVE	N	N045-00-A/317	Locker Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17546	ACTIVE	N	N045-00-A/317	Locker Room - Station Building - Belsize Park Stn	No Access	Asbestos	No Access: Presumed				New Construction? Mess Room leading on to passage A/237 - 190 Haverstock?					
8810	ACTIVE	N	N045-00-A/332	Mess Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17976	ACTIVE	N	N045-00-A/332	Mess Room - Station Building - Belsize Park Stn	No Access	Asbestos	No Access: Presumed				New Construction? Mess Room leading on to passage A/236 - 190 Haverstock?					
8811	ACTIVE	N	N045-00-A/333	Mess Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17547	ACTIVE	N	N045-00-A/333	Mess Room - Station Building - Belsize Park Stn	No Access	Asbestos	No Access: Presumed				New Construction? Mess Room leading on to passage A/236 - 190 Haverstock?					
8812	ACTIVE	N	N045-00-A/411	Store - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18498	ACTIVE	N	N045-00-A/411	Store - Station Building - Belsize Park Stn	No Access	Asbestos	No Access: Presumed				New Construction? Store in between room A/317 and A/332 - 190 Haverstock?					
8813	ACTIVE	N	N045-00-A/416	Toilet: Female - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17548	ACTIVE	N	N045-00-A/416	Toilet: Female - Station Building - Belsize Park Stn	No Access	Asbestos	No Access: Presumed				New Construction? Next to Female Toilet - 190 Haverstock?					
8814	ACTIVE	N	N045-00-A/417	Toilet: Male - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17549	ACTIVE	N	N045-00-A/417	Toilet: Male - Station Building - Belsize Park Stn	No Access	Asbestos	No Access: Presumed				New Construction? Next to Male Toilet - 190 Haverstock?					



# Hazardous Material Asset Register - Summary



## N045-00 - Station Building - Belsize Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8815	ACTIVE	N	N045-00-A/418	Shower Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17550	ACTIVE	N	N045-00-A/418	Shower Room - Station Building - Belsize Park Stn	No Access	Asbestos	No Access: Presumed				New Construction? Shower leading out to passage A/237 - 190 Haverstock? Same Room as 1/418?					
8816	ACTIVE	N	N045-00-A/577	Stairs: Linear - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17551	ACTIVE	N	N045-00-A/577	Stairs: Linear - Station Building - Belsize Park Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard Panel on wall					
8817	ACTIVE	N	N045-00-A/661	Switch Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17977	ACTIVE	N	N045-00-A/661	Switch Room - Station Building - Belsize Park Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Boxing					
17552	ACTIVE	N	N045-00-A/661	Switch Room - Station Building - Belsize Park Stn	Void	Asbestos	No Access: Presumed				Within - Supalux Boxing					
18071	ACTIVE	N	N045-00-A/661/FLR-01	Floor - 1 - Switch Room - Station Building - Belsize Park Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Boxing around Floor - Supalux					
8818	ACTIVE	N	N045-00-A/662	Switch Cupboard - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17553	ACTIVE	N	N045-00-A/662	Switch Cupboard - Station Building - Belsize Park Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Walls & Ceiling Panels					
8819	ACTIVE	N	N045-00-A/663	Switch Cupboard - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17554	ACTIVE	N	N045-00-A/663	Switch Cupboard - Station Building - Belsize Park Stn	No Access	Asbestos	No Access: Presumed				New Construction? Switch Room inside passage A/236 - 190 Haverstock?					
8820	ACTIVE	N	N045-00-A/761	Equipment Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
8821	ACTIVE	N	N045-00-A/762	Equipment Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17978	ACTIVE	N	N045-00-A/762	Equipment Room - Station Building - Belsize Park Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
8822	ACTIVE	N	N045-00-A/801	Training Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17555	ACTIVE	N	N045-00-A/801	Training Room - Station Building - Belsize Park Stn	No Access	Asbestos	No Access: Presumed				New Construction? Office Next to room A/802 - 190 Haverstock?					



# Hazardous Material Asset Register - Summary



## N045-00 - Station Building - Belsize Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8823	ACTIVE	N	N045-00-A/802	Training Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17556	ACTIVE	N	N045-00-A/802	Training Room - Station Building - Belsize Park Stn	No Access	Asbestos	No Access: Presumed				New Construction? Office Next to room A/801 - 190 Haverstock?					
8824	ACTIVE	N	N045-00-A/901	Disused Room - Station Building - Belsize Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17979	ACTIVE	N	N045-00-A/901	Disused Room - Station Building - Belsize Park Stn	Isolator Switches	Asbestos	Strongly Presumed				Gallery above 1/781 Substation Isolation switches  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score materials within.  Presumed ACM to existing visible and concealed cable ducts within floor and ceiling slab throughout substation.		14			
17557	ACTIVE	N	N045-00-A/901/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Belsize Park Stn	Cellactite Sheeting	Asbestos	Strongly Presumed				Gallery above 1/781 Substation Corragated sheeting and skylights  2x different material listed rope and corrugated sheets hence 2 x scores given.  Known gaskets to large ductwork / vents (redundant) labelled with ACM. through 2x up-stands on mess level of substation.					

## N047-00 - Station Building - Chalk Farm Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8826	ACTIVE	N	N047-00-1/001	Booking Hall - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17485	ACTIVE	N	N047-00-1/001	Booking Hall - Station Building - Chalk Farm Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8827	ACTIVE	N	N047-00-1/011	Ticket Office - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17897	ACTIVE	N	N047-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Chalk Farm Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				YES	
17487	ACTIVE	N	N047-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
17486	ACTIVE	N	N047-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Chalk Farm Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES



# Hazardous Material Asset Register - Summary



## N047-00 - Station Building - Chalk Farm Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8828	ACTIVE	N	N047-00-1/021	POM - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17488	ACTIVE	N	N047-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Chalk Farm Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
8829	ACTIVE	N	N047-00-1/031	Mess Room - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18006	ACTIVE	N	N047-00-1/031	Mess Room - Station Building - Chalk Farm Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				White Foam Backing					
17490	ACTIVE	N	N047-00-1/031	Mess Room - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing					
18998	ACTIVE	N	N047-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Chalk Farm Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				YES	
17489	ACTIVE	N	N047-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
8830	ACTIVE	N	N047-00-1/036	Toilet: Unisex - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17491	ACTIVE	N	N047-00-1/036	Toilet: Unisex - Station Building - Chalk Farm Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8831	ACTIVE	N	N047-00-1/071	Circulation Area - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17898	ACTIVE	N	N047-00-1/071	Circulation Area - Station Building - Chalk Farm Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Bulkhead to Lift					
17494	ACTIVE	N	N047-00-1/136	Lift Shaft - Station Building - Chalk Farm Stn	Cable: Wrap	Asbestos	Known				9x Woven cables 25m long running from machine chamber to bottom of lift  No access into lift shafts during 2020 re-inspection in traffic hours.					
42961	ACTIVE	N	N047-00-1/136	Lift Shaft - Station Building - Chalk Farm Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel panel, 2m2, to bottom of shaft to side of exit of Lift 2			R521101	N	N
42960	ACTIVE	N	N047-00-1/136	Lift Shaft - Station Building - Chalk Farm Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel panel, 2m2, to bottom of shaft to side of entrance of Lift 2			R521101	N	N
42962	ACTIVE	N	N047-00-1/136	Lift Shaft - Station Building - Chalk Farm Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel panel, <2m2, to top of shaft above exit of Lift 1			R521101	N	N
42963	ACTIVE	N	N047-00-1/136	Lift Shaft - Station Building - Chalk Farm Stn	Durasteel	Asbestos	Sampled – Not Detected				Grout/ hessian, throughout, to caulking within shaft in tunnel ring of Lift 1			R521101	N	N



# Hazardous Material Asset Register - Summary



## N047-00 - Station Building - Chalk Farm Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17492	ACTIVE	N	N047-00-1/136	Lift Shaft - Station Building - Chalk Farm Stn	Caulking	Asbestos	Presumed				Tunnel ring caulking unable to access from lift shaft No access into lift shafts during 2020 re-inspection in traffic hours.					
44920	ACTIVE	N	N047-00-1/136	Lift Shaft - Station Building - Chalk Farm Stn	Other Electrical Boxes	Asbestos	Presumed				Circuit breaker 1 and 2 to wall No access into lift shafts during 2020 re-inspection in traffic hours.		2		N	N
42957	ACTIVE	N	N047-00-1/136	Lift Shaft - Station Building - Chalk Farm Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel panel, 2m2, to top of shaft above entrance of Lift 2			R521101	N	N
44919	ACTIVE	N	N047-00-1/136	Lift Shaft - Station Building - Chalk Farm Stn	Control Panels	Asbestos	Presumed				1x lift control panel number 2 No access into lift shafts during 2020 re-inspection in traffic hours.		1		N	N
44916	ACTIVE	N	N047-00-1/136	Lift Shaft - Station Building - Chalk Farm Stn	Cable: Sheath	Asbestos	Strongly Presumed				7x woven sheath cable running from LMR down shaft connecting to bottom of car in lift shaft 1 No access into lift shafts during 2020 re-inspection in traffic hours.		7		N	N
42958	ACTIVE	N	N047-00-1/136	Lift Shaft - Station Building - Chalk Farm Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel panel, 2m2, to top of shaft above exit of Lift 2			R521101	N	N
42959	ACTIVE	N	N047-00-1/136	Lift Shaft - Station Building - Chalk Farm Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel panel, <2m2, to top of shaft to side of exit of Lift 2			R521101	N	N
42964	ACTIVE	N	N047-00-1/136	Lift Shaft - Station Building - Chalk Farm Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel panel, 2m2, to top of shaft above entrance of Lift 1			R521101	N	N
44918	ACTIVE	N	N047-00-1/137	Lift Shaft - Station Building - Chalk Farm Stn		Asbestos	Strongly Presumed				Redundant cable on landing half way down shaft in lift shaft 2 No access into lift shafts during 2020 re-inspection in traffic hours.				N	N
18999	ACTIVE	N	N047-00-1/137	Lift Shaft - Station Building - Chalk Farm Stn	Cable: Wrap	Asbestos	Known				9x Woven cables 25m long running from machine chamber to bottom of lift No access into lift shafts during 2020 re-inspection in traffic hours.					
17493	ACTIVE	N	N047-00-1/137	Lift Shaft - Station Building - Chalk Farm Stn	Caulking	Asbestos	Presumed				Tunnel ring caulking unable to access from lift shaft No access into lift shafts during 2020 re-inspection in traffic hours.					
44917	ACTIVE	N	N047-00-1/137	Lift Shaft - Station Building - Chalk Farm Stn	Cable: Sheath	Asbestos	Strongly Presumed				6x woven sheath cable running from LMR down shaft connecting to bottom of car in lift shaft 2 No access into lift shafts during 2020 re-inspection in traffic hours.		6		N	N
8832	ACTIVE	N	N047-00-1/236	Lobby - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17899	ACTIVE	N	N047-00-1/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Chalk Farm Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				YES	



# Hazardous Material Asset Register - Summary



## N047-00 - Station Building - Chalk Farm Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18497	ACTIVE	N	N047-00-1/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux tiles - Screwed in					
17495	ACTIVE	N	N047-00-1/236/FLR-01	Floor - 1 - Lobby - Station Building - Chalk Farm Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
8833	ACTIVE	N	N047-00-1/237	Passage - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17496	ACTIVE	N	N047-00-1/237	Passage - Station Building - Chalk Farm Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8834	ACTIVE	N	N047-00-1/238	Lobby - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17497	ACTIVE	N	N047-00-1/238	Lobby - Station Building - Chalk Farm Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8835	ACTIVE	N	N047-00-1/331	Mess Room - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17499	ACTIVE	N	N047-00-1/331	Mess Room - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Panels & Boxing Supalux					
17498	ACTIVE	N	N047-00-1/331	Mess Room - Station Building - Chalk Farm Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				White Foam Backing					
17900	ACTIVE	N	N047-00-1/331/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Chalk Farm Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				YES	
8836	ACTIVE	N	N047-00-1/371	Store - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17500	ACTIVE	N	N047-00-1/371	Store - Station Building - Chalk Farm Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
8837	ACTIVE	N	N047-00-1/401	Bin Store - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17501	ACTIVE	N	N047-00-1/401	Bin Store - Station Building - Chalk Farm Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8838	ACTIVE	N	N047-00-1/411	Lobby - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17503	ACTIVE	N	N047-00-1/411/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Chalk Farm Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				YES	



# Hazardous Material Asset Register - Summary



## N047-00 - Station Building - Chalk Farm Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17502	ACTIVE	N	N047-00-1/411/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux tiles					
8839	ACTIVE	N	N047-00-1/416	Toilet - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8840	ACTIVE	N	N047-00-1/417	Toilet - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8841	ACTIVE	N	N047-00-1/426	Tenancy - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17504	ACTIVE	N	N047-00-1/426/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Chalk Farm Stn	Void	Asbestos	No Access: Presumed				Above Metal Grills				YES	
8842	ACTIVE	N	N047-00-1/631	Stairs: Spiral - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44352	ACTIVE	N	N047-00-1/631	Stairs: Spiral - Station Building - Chalk Farm Stn	Gasket :Pipework	Asbestos	Presumed				Pipe gaskets to ceiling above stairs Presumed gasket - encapsulated medium density		1		N	N
17505	ACTIVE	N	N047-00-1/631	Stairs: Spiral - Station Building - Chalk Farm Stn	Pipe Lagging	Asbestos	Not Found during Inspection				Lagging Fibre Glass					
17901	ACTIVE	N	N047-00-1/631/FLR-01	Floor - 1 - Spiral Stairs - Station Building - Chalk Farm Stn	Void	Asbestos	Surveyed – Not Detected				Beneath Stairs - Metal					YES
8843	ACTIVE	N	N047-00-1/661	Switch Room - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17506	ACTIVE	N	N047-00-1/661/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux tiles - Screwed in					
17507	ACTIVE	N	N047-00-1/661/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Chalk Farm Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling				YES	
17508	ACTIVE	N	N047-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Chalk Farm Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es) No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N



# Hazardous Material Asset Register - Summary



## N047-00 - Station Building - Chalk Farm Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18007	ACTIVE	N	N047-00-1/661/WAL-002 80898811	Wall: Internal - 2 - Switch Room - Station Building - Chalk Farm Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				3 x Grey Switch Boxes - Flash Guards & Blocks within. 1 x 100 amp, 2 x 60 amps; Rope Seals Non - Asbestos. Plus three other grey switch boxes - 1x100 amp, 1 x 160 amp, 1x 200 amp  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		6		N	N
8844	ACTIVE	N	N047-00-1/662	Switch Room - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17513	ACTIVE	N	N047-00-1/662	Switch Room - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Panel					
44915	ACTIVE	N	N047-00-1/662	Switch Room - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Presumed				Superlux panel to ceiling				N	N
19000	ACTIVE	N	N047-00-1/662	Switch Room - Station Building - Chalk Farm Stn	Cable Duct: Other	Asbestos	Presumed				Cement Cable Ducts				N	
17510	ACTIVE	N	N047-00-1/662/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Chalk Farm Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling				YES	
17509	ACTIVE	N	N047-00-1/662/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux tiles - Screwed in					
17511	ACTIVE	N	N047-00-1/662/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Chalk Farm Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
17966	ACTIVE	N	N047-00-1/662/WAL-002 80898820	Wall: Internal - 2 - Switch Room - Station Building - Chalk Farm Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				W2 6 x Switch Boxes - Flash Guards & Blocks within 5 x 60 amp, 1 x 100 amp. Plus three square grey switch boxes: 1 x 160 amp and 2x100 amp.  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		6		N	N
17512	ACTIVE	N	N047-00-1/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Chalk Farm Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
17967	ACTIVE	N	N047-00-1/662/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Chalk Farm Stn	Other Electrical Boxes	Asbestos	Presumed				3 x Transformer Boxes  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N



# Hazardous Material Asset Register - Summary



## N047-00 - Station Building - Chalk Farm Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25736	ACTIVE	N	N047-00-1/662/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Chalk Farm Stn	Isolator Switches	Asbestos	Strongly Presumed				1x Switch box  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
8845	ACTIVE	N	N047-00-1/663	Switch Cupboard - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17514	ACTIVE	N	N047-00-1/663/WAL-002 80898827	Wall: Internal - 2 - Switch Cupboard - Station Building - Chalk Farm Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes - Insulation within 4 x 60 amp, 1 x 100 amps, 1 x 30 amps. Plus two square grey switch boxes: 1x63amp and 1x200amp.  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		8		N	N
8846	ACTIVE	N	N047-00-1/664	Switch Cupboard - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17515	ACTIVE	N	N047-00-1/664	Switch Cupboard - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel					
8847	ACTIVE	N	N047-00-1/665	Switch Cupboard - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17516	ACTIVE	N	N047-00-1/665	Switch Cupboard - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel					
8848	ACTIVE	N	N047-00-1/746	SCR - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17968	ACTIVE	N	N047-00-1/746/CLG-01	Ceiling: Solid - 1 - SCR - Station Building - Chalk Farm Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
17517	ACTIVE	N	N047-00-1/746/CLG-01	Ceiling: Solid - 1 - SCR - Station Building - Chalk Farm Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling				YES	
8849	ACTIVE	N	N047-00-1/951	Tenancy - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8850	ACTIVE	N	N047-00-1/952	Disused Room - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8851	ACTIVE	N	N047-00-1/953	Station Control Room - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17321	ACTIVE	N	N047-00-1/953	Station Control Room - Station Building - Chalk Farm Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				White Foam Backing					



# Hazardous Material Asset Register - Summary



## N047-00 - Station Building - Chalk Farm Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17320	ACTIVE	N	N047-00-1/953/CLG-01	Ceiling: Suspended - 1 - Station Control Room - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18993	ACTIVE	N	N047-00-1/953/CLG-01	Ceiling: Suspended - 1 - Station Control Room - Station Building - Chalk Farm Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				YES	
17319	ACTIVE	N	N047-00-1/953/FLR-01	Floor - 1 - Station Control Room - Station Building - Chalk Farm Stn	Void	Asbestos	No Access: Presumed				Beneath False Floor					YES
19030	ACTIVE	N	N047-00-1/953/FLR-01	Floor - 1 - Station Control Room - Station Building - Chalk Farm Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl					
8852	ACTIVE	N	N047-00-1/971	LMR - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17326	ACTIVE	N	N047-00-1/971	LMR - Station Building - Chalk Farm Stn	Cable: Sheath	Asbestos	Known				Woven Cables 3m long - coming from switch for isolating heating fan in car, and going down to lift shaft  No access into LMR during 2020 re-inspection. Permit with L&E required.		9			
44914	ACTIVE	N	N047-00-1/971	LMR - Station Building - Chalk Farm Stn	Other Electrical Boxes	Asbestos	Presumed				<1m <sup>2</sup> Old Circuit breaker unable  Not observed this visit  No access into LMR during 2020 re-inspection. Permit with L&E required.				N	N
17327	ACTIVE	N	N047-00-1/971	LMR - Station Building - Chalk Farm Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Girder RHS				N	N
19032	ACTIVE	N	N047-00-1/971/FLR-01	Floor - 1 - LMR - Station Building - Chalk Farm Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Cable Ducts Floor RHS  No access into LMR during 2020 re-inspection. Permit with L&E required.					
19031	ACTIVE	N	N047-00-1/971/WAL-001	Wall: Internal - 1 - LMR - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux, 10m <sup>2</sup> Supalux lower level of room on walls 1,2&4 above door NADIS					
17322	ACTIVE	N	N047-00-1/971/WAL-002	Wall: Internal - 2 - LMR - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux, 10m <sup>2</sup> Supalux lower level of room on walls 1,2&4 above door NADIS					
17323	ACTIVE	N	N047-00-1/971/WAL-003	Wall: Internal - 3 - LMR - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux, 10m <sup>2</sup> Supalux lower level of room on walls 1,2&4 above door NADIS					
17324	ACTIVE	N	N047-00-1/971/WAL-004	Wall: Internal - 4 - LMR - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux, 10m <sup>2</sup> Supalux lower level of room on walls 1,2&4 above door NADIS					



# Hazardous Material Asset Register - Summary



## N047-00 - Station Building - Chalk Farm Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8853	ACTIVE	N	N047-00-2/201	Passage - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17328	ACTIVE	N	N047-00-2/201	Passage - Station Building - Chalk Farm Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Boarding above Lift Doors					
8854	ACTIVE	N	N047-00-2/202	Passage - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17329	ACTIVE	N	N047-00-2/202	Passage - Station Building - Chalk Farm Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Boarding above Lift Doors					
8855	ACTIVE	N	N047-00-2/411	Switch Room - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17989	ACTIVE	N	N047-00-2/411	Switch Room - Station Building - Chalk Farm Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8856	ACTIVE	N	N047-00-2/601	Stairs: Linear - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
8857	ACTIVE	N	N047-00-2/602	Stairs: Linear - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
8858	ACTIVE	N	N047-00-2/771	Plant Room - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
44353	ACTIVE	N	N047-00-2/771	Plant Room - Station Building - Chalk Farm Stn	Caulking	Asbestos	Presumed				Tunnel ring caulking Sealed tunnel ring caulking (sealed with grout) - treated highly friable material.				N	N
25737	ACTIVE	N	N047-00-2/771/WAL-003	Wall: Internal - 3 - Plant Room - Station Building - Chalk Farm Stn	Other Electrical Boxes	Asbestos	Presumed				Large Electrical cabinet No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
25645	ACTIVE	N	N047-00-2/771/WAL-005	Wall: Internal - 5 - Plant Room - Station Building - Chalk Farm Stn	Other Electrical Boxes	Asbestos	Presumed				Electrical Box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
17330	ACTIVE	N	N047-00-2/771/WAL-005	Wall: Internal - 5 - Plant Room - Station Building - Chalk Farm Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 60amp Switch Box - Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N



# Hazardous Material Asset Register - Summary



## N047-00 - Station Building - Chalk Farm Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25646	ACTIVE	N	N047-00-2/771/WAL-006	Wall: Internal - 6 - Plant Room - Station Building - Chalk Farm Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
8859	ACTIVE	N	N047-00-2/773	CER - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19033	ACTIVE	N	N047-00-2/773/FLR-01	Floor - 1 - CER - Station Building - Chalk Farm Stn	Void	Asbestos	Surveyed – Not Detected				Concrete/ Conduits beneath Computer Tiles					
17332	ACTIVE	N	N047-00-2/773/WAL-001 80899054	Wall: Internal - 1 - CER - Station Building - Chalk Farm Stn Wall: Internal	Other Boarding	Asbestos	Presumed				Paxoline Board				N	N
17333	ACTIVE	N	N047-00-2/773/WAL-003	Wall: Internal - 3 - CER - Station Building - Chalk Farm Stn	Other Boarding	Asbestos	Presumed				Paxoline Board		1		N	N
17331	ACTIVE	N	N047-00-2/773/WAL-007	Wall: Internal - 7 - CER - Station Building - Chalk Farm Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x 60 amp Switch Boxes No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2		N	N
8860	ACTIVE	N	N047-00-3/201	Passage - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17334	ACTIVE	N	N047-00-3/201	Passage - Station Building - Chalk Farm Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8861	ACTIVE	N	N047-00-3/202	Passage - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17335	ACTIVE	N	N047-00-3/202	Passage - Station Building - Chalk Farm Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8862	ACTIVE	N	N047-00-3/203	Passage - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17990	ACTIVE	N	N047-00-3/203	Passage - Station Building - Chalk Farm Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8863	ACTIVE	N	N047-00-3/261	Platform 1 - Northbound Local - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44913	ACTIVE	N	N047-00-3/261	Platform 1 - Northbound Local - Station Building - Chalk Farm Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables 1x10mm & 1x30mm: Running full length of invert No access into platform inverts during 2020 re-inspection. Confined space.				N	N
17336	ACTIVE	N	N047-00-3/261	Platform 1 - Northbound Local - Station Building - Chalk Farm Stn	Cable: Sheath	Asbestos	Strongly Presumed				Various Cables					



# Hazardous Material Asset Register - Summary



## N047-00 - Station Building - Chalk Farm Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor	
17340	ACTIVE	N	N047-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Chalk Farm Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - Badly encapsulated Cables by 3/731; Cables exit and enter invert by ladder Platform side by 3/731  No access into platform inverts during 2020 re-inspection. Confined space.						YES
17339	ACTIVE	N	N047-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Chalk Farm Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Platform 1 Invert - 4 x Cable Sleeves Far end of Invert  No access into platform inverts during 2020 re-inspection. Confined space.						YES
17337	ACTIVE	N	N047-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Chalk Farm Stn	Cable: Sheath	Asbestos	Room: Surveyed: Asbestos Strongly Presumed				Platform 1 Invert - Cables 1x10mm & 1x30mm: Running full length of invert						YES
17338	ACTIVE	N	N047-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Chalk Farm Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - Cables 3x5mm: Runs across invert from pit wall to back wall, middle of invert  No access into platform inverts during 2020 re-inspection. Confined space.						YES
17664	ACTIVE	N	N047-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Chalk Farm Stn	Cable: Sheath	Asbestos	Strongly Presumed				Various Cables running middle of invert  No access into platform inverts during 2020 re-inspection. Confined space.						YES
17665	ACTIVE	N	N047-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Chalk Farm Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - 4 x Cables (1 x White Encapsulated, 1 x Green, 2 x Orange (1 Green? - Both Encapsulated) & 2 x Asbestos Cables Encapsulated wrapped around lying on Floor by 3/731. All encapsulated except Green Cable  No access into platform inverts during 2020 re-inspection. Confined space.						YES
19034	ACTIVE	N	N047-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Chalk Farm Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - Cables 1x20mm: on J-hangers from ceiling wall side  No access into platform inverts during 2020 re-inspection. Confined space.						YES
19541	ACTIVE	N	N047-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Chalk Farm Stn	Cable: Sheath	Asbestos	Not Found during Inspection				White Cable not Encapsulated from other end 3/731 (South End)						YES
8864	ACTIVE	N	N047-00-3/262	Platform 2 - Southbound Local - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed										
17666	ACTIVE	N	N047-00-3/262	Platform 2 - Southbound Local - Station Building - Chalk Farm Stn	Cable: Sheath	Asbestos	Strongly Presumed				Various Cables - Tail Wall				N	N	



# Hazardous Material Asset Register - Summary



## N047-00 - Station Building - Chalk Farm Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor	
17667	ACTIVE	N	N047-00-3/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Chalk Farm Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - 3 x Cables 20mm white all run length of invert middle j hangers then cross over from j hanger to entrance to track by ladder  No access into platform inverts during 2020 re-inspection. Confined space.						YES
17668	ACTIVE	N	N047-00-3/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Chalk Farm Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - 8 x Cables (3 white, 2 green, 1 brown) & 2 x yellow cables by Entrance/ Exit other end from 2/602  No access into platform inverts during 2020 re-inspection. Confined space.						YES
18132	ACTIVE	N	N047-00-3/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Chalk Farm Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - 3 x Cables exiting by Track by 2/602  No access into platform inverts during 2020 re-inspection. Confined space.						YES
8865	ACTIVE	N	N047-00-3/312	Switch Room - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed										
8866	ACTIVE	N	N047-00-3/381	Switch Cupboard - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed										
17669	ACTIVE	N	N047-00-3/381	Switch Cupboard - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux						
8867	ACTIVE	N	N047-00-3/661	Switch Room - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed										
17671	ACTIVE	N	N047-00-3/661/FLR-01	Floor - 1 - Switch Room - Station Building - Chalk Farm Stn	Void	Asbestos	No Access: Presumed				Beneath Trap Door						
18081	ACTIVE	N	N047-00-3/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Chalk Farm Stn	Other Boarding	Asbestos	Presumed				Transformer Box  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N	
17670	ACTIVE	N	N047-00-3/661/WAL-002 80899087	Wall: Internal - 2 - Switch Room - Station Building - Chalk Farm Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				3 x Switch Boxes - 2 x 100amp, 1 x 100amp. Plus 3x square grey switchboxes: 1x 160amp, 1x 100 amp, 1x 63 amp.  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		3		N	N	
44359	ACTIVE	N	N047-00-3/661/WAL-003 80899088	Wall: Internal - 3 - Switch Room - Station Building - Chalk Farm Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				Transformer box  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N	



# Hazardous Material Asset Register - Summary



## N047-00 - Station Building - Chalk Farm Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25647	ACTIVE	N	N047-00-3/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Chalk Farm Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Box 1 x 60amp No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
8868	ACTIVE	N	N047-00-3/662	Switch Room - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18563	ACTIVE	N	N047-00-3/662	Switch Room - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux					
18133	ACTIVE	N	N047-00-3/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Chalk Farm Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				3 x Electrical Incomer Boxes No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		3		N	N
8869	ACTIVE	N	N047-00-3/663	Switch Room - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17672	ACTIVE	N	N047-00-3/663	Switch Room - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux					
8870	ACTIVE	N	N047-00-3/711	Relay Room - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17674	ACTIVE	N	N047-00-3/711	Relay Room - Station Building - Chalk Farm Stn	Cable: Sheath	Asbestos	Strongly Presumed				2 x Green Cables 50mm to wall 2 back of room going into 600v box (re-inspected 18.05.22 AW VC)		2		N	N
17673	ACTIVE	N	N047-00-3/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux					
46813	ACTIVE	N	N047-00-3/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Chalk Farm Stn	Cable Duct: Other	Asbestos	Presumed				2 Ducts to floor inside roller cabinet - presumed					
46814	ACTIVE	N	N047-00-3/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Chalk Farm Stn	Other Boarding	Asbestos	Presumed				Paxoline board to equipment in roller shutter 2 - 8x to front 8x underneath support.					
25656	INACTIVE	N	N047-00-3/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Chalk Farm Stn	PCBs	Asbestos	Strongly Presumed				8 x PCB's located within roller shutter cabinet. Fair condition - serial numbers not visible.		8		N	N
42326	INACTIVE	N	N047-00-3/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Chalk Farm Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				8 x PCB's - Fair condition, located within roller shutter cabinet In Twice see 25656		8		N	N
25657	ACTIVE	N	N047-00-3/711/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Chalk Farm Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Other Boarding					
25658	ACTIVE	N	N047-00-3/711/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Door Frame - Supalux boarding					



# Hazardous Material Asset Register - Summary



## N047-00 - Station Building - Chalk Farm Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17676	ACTIVE	N	N047-00-3/712	Switch Room - Station Building - Chalk Farm Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Ducts into Invert Ducts not visible beneath filling therefore material not scored in 2020 re-inspection.				N	N
18134	ACTIVE	N	N047-00-3/712	Switch Room - Station Building - Chalk Farm Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables 50mm going Into Invert		2		N	N
44912	ACTIVE	N	N047-00-3/712	Switch Room - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels to the walls and to ducts to inverts				N	N
25739	ACTIVE	N	N047-00-3/712	Switch Room - Station Building - Chalk Farm Stn	Cable: Sheath	Asbestos	Known				Approx 4x Braided Cables within Roller shutter Cabinet		4		N	N
17675	ACTIVE	N	N047-00-3/712	Switch Room - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux; Supalux Panelling					
17677	ACTIVE	N	N047-00-3/712	Switch Room - Station Building - Chalk Farm Stn	Other Boarding	Asbestos	Strongly Presumed				Paxoline Board Wall 3		1		N	N
25738	INACTIVE	N	N047-00-3/712	Switch Room - Station Building - Chalk Farm Stn	PCBs	Polychlorinated biphenyl	Presumed				Approx 8 x PCB's within Roller shutter cabinet - Wall 2		8		N	N
46815	ACTIVE	N	N047-00-3/712/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Chalk Farm Stn	Cable Duct: Other	Asbestos	Presumed				2 x cable ducts to inside roller shutter					
46816	ACTIVE	N	N047-00-3/712/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Chalk Farm Stn	Other Boarding	Asbestos	Presumed				Paxoline board to equipment in rack x8 to front x8 to underneath					
8871	ACTIVE	N	N047-00-3/731	CER - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17678	ACTIVE	N	N047-00-3/731	CER - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panelling					
44358	ACTIVE	N	N047-00-3/731/WAL-002 80899129	Wall: Internal - 2 - CER - Station Building - Chalk Farm Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				3 x electrical boxes: 1x black box and 2x green cylindrical No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		3		N	N
8872	ACTIVE	N	N047-00-3/762	Service Riser - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44355	ACTIVE	N	N047-00-3/762	Service Riser - Station Building - Chalk Farm Stn	Other Boarding	Asbestos	Presumed				Cement panel		1		N	N
44357	ACTIVE	N	N047-00-3/762	Service Riser - Station Building - Chalk Farm Stn	Other Electrical Boxes	Asbestos	Presumed				Electrical box at high level No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N



# Hazardous Material Asset Register - Summary



## N047-00 - Station Building - Chalk Farm Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44356	ACTIVE	N	N047-00-3/762	Service Riser - Station Building - Chalk Farm Stn	Other Boarding	Asbestos	Presumed				Paxoline boarding		1		N	N
44354	ACTIVE	N	N047-00-3/762	Service Riser - Station Building - Chalk Farm Stn	Other Electrical Boxes	Asbestos	Presumed				Westinghouse box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
17679	ACTIVE	N	N047-00-3/762	Service Riser - Station Building - Chalk Farm Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables 50mm		2		N	N
8873	ACTIVE	N	N047-00-A/047	Shower Room - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
46442	ACTIVE	N	N047-00-A/047	Shower Room - Station Building - Chalk Farm Stn	Lead/Leading	Lead Paint/Lead	Sampled - Not Detected				White gloss paint applied to the radiator, LHS - Thickness: 0.3mm Analysis: 0.01%			R674026	N	N
46441	ACTIVE	N	N047-00-A/047	Shower Room - Station Building - Chalk Farm Stn	Lead/Leading	Lead Paint/Lead	Sampled - Not Detected				White gloss paint applied to the radiator, RHS - Thickness: 0.29mm Analysis: 0.03%			R674026	N	N
46443	ACTIVE	N	N047-00-A/047	Shower Room - Station Building - Chalk Farm Stn	Lead/Leading	Lead Paint/Lead	Sampled - Not Detected				White gloss paint applied to the window, RHS - Thickness: 0.71mm Analysis: 0.09%			R674026	N	N
46444	ACTIVE	N	N047-00-A/047	Shower Room - Station Building - Chalk Farm Stn	Lead/Leading	Lead Paint/Lead	Sampled - Not Detected				White gloss paint applied to the window, LHS - Thickness: 0.43mm Analysis: 0.15%			R674026	N	N
18135	ACTIVE	N	N047-00-A/047/CLG-01	Ceiling: Suspended - 1 - Shower Room - Station Building - Chalk Farm Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above false ceiling				YES	
8874	ACTIVE	N	N047-00-A/081	Lobby - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17680	ACTIVE	N	N047-00-A/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Chalk Farm Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above false ceiling				YES	
8875	ACTIVE	N	N047-00-A/131	LMR - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
44087	ACTIVE	N	N047-00-A/131	LMR - Station Building - Chalk Farm Stn		Asbestos	Removed				Paper insulation to door, 0.5m2, within redundant circuit breaker No2 in Lift Motor Room A/131 at Chalk Farm Station.			R602326	N	N
17682	ACTIVE	N	N047-00-A/131	LMR - Station Building - Chalk Farm Stn	Control Panels	Asbestos	Removed				Lift Control Panels					
19491	ACTIVE	N	N047-00-A/131	LMR - Station Building - Chalk Farm Stn	Isolator Switches	Asbestos	Removed				2x Old Circuit breakers & other electrical equipment		1			
44088	ACTIVE	N	N047-00-A/131	LMR - Station Building - Chalk Farm Stn		Asbestos	Removed				Bakelite panel, 0.5m2, within redundant circuit breaker No2 in Lift Motor Room A/131 at Chalk Farm Station			R602326	N	N



# Hazardous Material Asset Register - Summary



## N047-00 - Station Building - Chalk Farm Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44082	ACTIVE	N	N047-00-A/131	LMR - Station Building - Chalk Farm Stn		Asbestos	Sampled – Not Detected				Woven travelling cable insulation, 6mm diameter, underneath half way box in Lift Motor Room A/131 at Chalk Farm Station (cable runs the full length of the lift shaft).			R602326	N	N
44911	ACTIVE	N	N047-00-A/131	LMR - Station Building - Chalk Farm Stn	Control Panels	Asbestos	Presumed				1x lift control panel number 1 No access into LMR during 2020 re-inspection. Permit with L&E required.		1		N	N
44905	ACTIVE	N	N047-00-A/131	LMR - Station Building - Chalk Farm Stn	Cable: Sheath	Asbestos	Strongly Presumed				5x woven cable to isolator for light and heating No access into LMR during 2020 re-inspection. Permit with L&E required.		5		N	N
44089	ACTIVE	N	N047-00-A/131	LMR - Station Building - Chalk Farm Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel panels, 8m2, exit to lift shaft 2 above and to the sides at Ticket Hall level at Chalk Farm Station.			R602326	N	N
44906	ACTIVE	N	N047-00-A/131	LMR - Station Building - Chalk Farm Stn	Cable: Sheath	Asbestos	Strongly Presumed				3x woven cable to isolator for light and heating No access into LMR during 2020 re-inspection. Permit with L&E required.		3		N	N
44085	ACTIVE	N	N047-00-A/131	LMR - Station Building - Chalk Farm Stn		Asbestos	Removed				Cement panel, 2no 0.25m2, within redundant circuit breaker No2 in Lift Motor Room A/131 at Chalk Farm Station			R602326	N	N
17325	ACTIVE	N	N047-00-A/131	LMR - Station Building - Chalk Farm Stn	Durasteel	Asbestos	Sampled – Not Detected				1m <sup>2</sup> Durasteel storage level, upper level					
44086	ACTIVE	N	N047-00-A/131	LMR - Station Building - Chalk Farm Stn		Asbestos	Removed				Woven tape to seal, 2m, within redundant circuit breaker No2 in Lift Motor Room A/131 at Chalk Farm Station			R602326	N	N
44084	ACTIVE	N	N047-00-A/131	LMR - Station Building - Chalk Farm Stn		Asbestos	Sampled – Not Detected				Woven travelling cable insulation, 25mm diameter, underneath half way box in Lift Motor Room A/131 at Chalk Farm Station (cable runs the full length of the lift shaft).			R602326	N	N
44083	ACTIVE	N	N047-00-A/131	LMR - Station Building - Chalk Farm Stn		Asbestos	Sampled – Not Detected				Woven travelling cable insulation, 16mm diameter, underneath half way box in Lift Motor Room A/131 at Chalk Farm Station (cable runs the full length of the lift shaft).			R602326	N	N
19071	ACTIVE	N	N047-00-A/131/WAL-002	Wall: Internal - 2 - LMR - Station Building - Chalk Farm Stn	Other Electrical Boxes	Asbestos	Removed				Lift Circuit Breakers (Redundant)					
18082	ACTIVE	N	N047-00-A/131/WAL-005	Wall: Internal - 5 - LMR - Station Building - Chalk Farm Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes 2 x 60 amp No access into platform inverts during 2020 re-inspection. Confined space.		2			
17681	ACTIVE	N	N047-00-A/131/WAL-005	Wall: Internal - 5 - LMR - Station Building - Chalk Farm Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es) No access into LMR during 2020 re-inspection. Permit with L&E required.		1		N	N



# Hazardous Material Asset Register - Summary



## N047-00 - Station Building - Chalk Farm Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44910	ACTIVE	N	N047-00-A/131/WAL-006	Wall: Internal - 6 - LMR - Station Building - Chalk Farm Stn	Other Electrical Boxes	Asbestos	Presumed				1x auto control panel No access into platform inverts during 2020 re-inspection. Confined space.		1		N	N
44909	ACTIVE	N	N047-00-A/131/WAL-012	Wall: Internal - 12 - LMR - Station Building - Chalk Farm Stn	Other Electrical Boxes	Asbestos	Presumed				1x transformer No access into platform inverts during 2020 re-inspection. Confined space.		1		N	N
44907	ACTIVE	N	N047-00-A/131/WAL-012	Wall: Internal - 12 - LMR - Station Building - Chalk Farm Stn	Other Electrical Boxes	Asbestos	Presumed				3x combination fuse switch boxes No access into platform inverts during 2020 re-inspection. Confined space.		3		N	N
44908	ACTIVE	N	N047-00-A/131/WAL-012	Wall: Internal - 12 - LMR - Station Building - Chalk Farm Stn	Other Electrical Boxes	Asbestos	Presumed				3x red spot boxes No access into platform inverts during 2020 re-inspection. Confined space.		3		N	N
8876	ACTIVE	N	N047-00-A/236	Passage - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17683	ACTIVE	N	N047-00-A/236	Passage - Station Building - Chalk Farm Stn	Isolator Switches	Asbestos	Removed				Combination Fuse Switch - Insulation within		1			
8877	ACTIVE	N	N047-00-A/237	Passage - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18136	ACTIVE	N	N047-00-A/237	Passage - Station Building - Chalk Farm Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8878	ACTIVE	N	N047-00-A/238	Lobby - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17684	ACTIVE	N	N047-00-A/238	Lobby - Station Building - Chalk Farm Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8879	ACTIVE	N	N047-00-A/281	Store - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17685	ACTIVE	N	N047-00-A/281	Store - Station Building - Chalk Farm Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8880	ACTIVE	N	N047-00-A/331	Mess Room - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17687	ACTIVE	N	N047-00-A/331	Mess Room - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Boiler Box Ceiling - Supalux & Plywood					
18137	ACTIVE	N	N047-00-A/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Chalk Farm Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				YES	



# Hazardous Material Asset Register - Summary



## N047-00 - Station Building - Chalk Farm Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18564	ACTIVE	N	N047-00-A/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Chalk Farm Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Tiles					
17686	ACTIVE	N	N047-00-A/331/FLR-01	Floor - 1 - Mess Room - Station Building - Chalk Farm Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
8881	ACTIVE	N	N047-00-A/382	Store - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17518	ACTIVE	N	N047-00-A/382	Store - Station Building - Chalk Farm Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
17525	ACTIVE	N	N047-00-A/382	Store - Station Building - Chalk Farm Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8882	ACTIVE	N	N047-00-A/383	Locker Room - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19001	ACTIVE	N	N047-00-A/383/CLG-01	Ceiling: Solid - 1 - Locker Room - Station Building - Chalk Farm Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				YES	
8883	ACTIVE	N	N047-00-A/384	Locker Room - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17969	ACTIVE	N	N047-00-A/384/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Chalk Farm Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				YES	
8884	ACTIVE	N	N047-00-A/416	Toilet: Male - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17519	ACTIVE	N	N047-00-A/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Chalk Farm Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				YES	
8885	ACTIVE	N	N047-00-A/417	SER - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17520	ACTIVE	N	N047-00-A/417/CLG-01	Ceiling: Suspended - 1 - SER - Station Building - Chalk Farm Stn	Void	Asbestos	No Access: Presumed				Above Soft Board ceiling				YES	
8886	ACTIVE	N	N047-00-A/418	Toilet: Female - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17521	ACTIVE	N	N047-00-A/418/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Chalk Farm Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				YES	



# Hazardous Material Asset Register - Summary



## N047-00 - Station Building - Chalk Farm Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8887	ACTIVE	N	N047-00-A/567	Stairs: Linear - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17522	ACTIVE	N	N047-00-A/567	Stairs: Linear - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Surveyed – Not Detected				Surveyed = No asbestos detected					
8888	ACTIVE	N	N047-00-A/576	Stairs: Linear - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8889	ACTIVE	N	N047-00-A/578	Stairs: Linear - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17523	ACTIVE	N	N047-00-A/578	Stairs: Linear - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
18008	ACTIVE	N	N047-00-A/578/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Chalk Farm Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Concrete/ Supalux					
8890	ACTIVE	N	N047-00-A/761	Equipment Room - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8891	ACTIVE	N	N047-00-A/771	Disused Room - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17970	ACTIVE	N	N047-00-A/791	Vent Shaft - Station Building - Chalk Farm Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8892	ACTIVE	N	N047-00-A/901	Disused Room - Station Building - Chalk Farm Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17524	ACTIVE	N	N047-00-A/901	Disused Room - Station Building - Chalk Farm Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					

## N053-00 - Station Building - Mill Hill East Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8893	ACTIVE	N	N053-00-1/001	Booking Hall - Station Building - Mill Hill East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19733	ACTIVE	N	N053-00-1/001/FLR-01	Floor - 1 - Booking Hall - Station Building - Mill Hill East Stn	Void	Asbestos	No Access: Presumed				Cellar under hatch - not on plan - no access					YES
8894	ACTIVE	N	N053-00-1/011	Ticket Office - Station Building - Mill Hill East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N053-00 - Station Building - Mill Hill East Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19223	ACTIVE	N	N053-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Mill Hill East Stn	Void	Asbestos	Surveyed – Not Detected				Metal Ducting & Pipes above Supalux				YES	
20098	ACTIVE	N	N053-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Mill Hill East Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
19216	ACTIVE	N	N053-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Mill Hill East Stn	Void	Asbestos	No Access: Presumed				Beneath Rubber Tiles					YES
8895	ACTIVE	N	N053-00-1/021	POM - Station Building - Mill Hill East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20099	ACTIVE	N	N053-00-1/021/CLG-01	Ceiling: Solid - 1 - POM - Station Building - Mill Hill East Stn	Void	Asbestos	No Access: Presumed				Beneath Rubber Tiles				YES	YES
8896	ACTIVE	N	N053-00-1/031	Mess Room - Station Building - Mill Hill East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43431	ACTIVE	N	N053-00-1/031	Mess Room - Station Building - Mill Hill East Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux panel, 1m, to cooker divider / panel attached to cooker in Mess Room 1/031 at Mill Hill East Station	1		R562801	N	N
20100	ACTIVE	N	N053-00-1/031/FLR-01	Floor - 1 - Mess Room - Station Building - Mill Hill East Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
19736	ACTIVE	N	N053-00-1/031/FLR-01	Floor - 1 - Mess Room - Station Building - Mill Hill East Stn	LUL Heaters	Asbestos	Surveyed – Not Detected									
8897	ACTIVE	N	N053-00-1/036	Toilet: Unisex - Station Building - Mill Hill East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19810	ACTIVE	N	N053-00-1/036/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Mill Hill East Stn	Void	Asbestos	Surveyed – Not Detected				Roof Area; Fibreglass Lagging above Wooden Hatch				YES	
8898	ACTIVE	N	N053-00-1/071	Circulation Area - Station Building - Mill Hill East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20101	ACTIVE	N	N053-00-1/071	Circulation Area - Station Building - Mill Hill East Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8899	ACTIVE	N	N053-00-1/081	Lobby - Station Building - Mill Hill East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20102	ACTIVE	N	N053-00-1/081	Lobby - Station Building - Mill Hill East Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8900	ACTIVE	N	N053-00-1/406	Store - Station Building - Mill Hill East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N053-00 - Station Building - Mill Hill East Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20103	ACTIVE	N	N053-00-1/406	Store - Station Building - Mill Hill East Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8901	ACTIVE	N	N053-00-1/411	Store - Station Building - Mill Hill East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19890	ACTIVE	N	N053-00-1/411	Store - Station Building - Mill Hill East Stn	LUL Heaters	Asbestos	Surveyed – Not Detected									
8902	ACTIVE	N	N053-00-1/412	Store - Station Building - Mill Hill East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19224	ACTIVE	N	N053-00-1/412	Store - Station Building - Mill Hill East Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8903	ACTIVE	N	N053-00-1/426	Toilet: Unisex - Station Building - Mill Hill East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20104	ACTIVE	N	N053-00-1/426	Toilet: Unisex - Station Building - Mill Hill East Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8904	ACTIVE	N	N053-00-1/551	Yard - Station Building - Mill Hill East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20105	ACTIVE	N	N053-00-1/551	Yard - Station Building - Mill Hill East Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8905	ACTIVE	N	N053-00-1/552	Yard - Station Building - Mill Hill East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20106	ACTIVE	N	N053-00-1/552	Yard - Station Building - Mill Hill East Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8906	ACTIVE	N	N053-00-1/602	Stairs: Linear - Station Building - Mill Hill East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19225	ACTIVE	N	N053-00-1/602	Stairs: Linear - Station Building - Mill Hill East Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8907	ACTIVE	N	N053-00-1/661	Switch Room - Station Building - Mill Hill East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20107	ACTIVE	N	N053-00-1/661	Switch Room - Station Building - Mill Hill East Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es) Presumed asbestos insulating materials within.		3		N	N
44125	ACTIVE	N	N053-00-1/661/WAL-002 80907205	Wall: Internal - 2 - Switch Room - Station Building - Mill Hill East Stn Wall: Internal	Isolator Switches	Asbestos	Presumed				2x switch boxes on wall 2 (1x30amp and 1x100amp) Presumed asbestos insulating materials within		2		N	N
19737	ACTIVE	N	N053-00-1/661/WAL-004 80907207	Wall: Internal - 4 - Switch Room - Station Building - Mill Hill East Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Iron clad Isolators 5x60amps, 2x100amp. Presumed insulating materials within.		9		N	N



# Hazardous Material Asset Register - Summary



## N053-00 - Station Building - Mill Hill East Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8908	ACTIVE	N	N053-00-1/746	SCR - Station Building - Mill Hill East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20108	ACTIVE	N	N053-00-1/746	SCR - Station Building - Mill Hill East Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8909	ACTIVE	N	N053-00-A/261	Platform 1 - Northbound Main - Station Building - Mill Hill East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43199	ACTIVE	N	N053-00-A/261	Platform 1 - Northbound Main - Station Building - Mill Hill East Stn	Bitumen	Asbestos	Sampled – Not Detected				Asphalt/bitumen (old) (0-114m), throughout, to top of timber panels, surface of Platform 1.			R531301	N	N
43195	ACTIVE	N	N053-00-A/261	Platform 1 - Northbound Main - Station Building - Mill Hill East Stn	Mastic	Asbestos	Sampled – Not Detected				Lining, throughout, to undercroft of Platform 1 between beams			R531301	N	N
20109	ACTIVE	N	N053-00-A/261	Platform 1 - Northbound Main - Station Building - Mill Hill East Stn	Cement Cowlings/ Flues	Asbestos	Strongly Presumed				Chimney Pot Roof of SCR Room		1		N	N
43196	ACTIVE	N	N053-00-A/261	Platform 1 - Northbound Main - Station Building - Mill Hill East Stn	Mastic	Asbestos	Sampled – Not Detected				Lining, throughout, to undercroft of Platform 1 between columns and beams			RR531301	N	N
43198	ACTIVE	N	N053-00-A/261	Platform 1 - Northbound Main - Station Building - Mill Hill East Stn	Mastic	Asbestos	Sampled – Not Detected				Mastic (white), throughout, to certain areas of Platform 1 panels at platform edge only			R531301	N	N
43197	ACTIVE	N	N053-00-A/261	Platform 1 - Northbound Main - Station Building - Mill Hill East Stn	Mastic	Asbestos	Sampled – Not Detected				Mastic (black), throughout, to joints of timber panels to Platform 1 surface			R531301	N	N
43209	ACTIVE	N	N053-00-A/261	Platform 1 - Northbound Main - Station Building - Mill Hill East Stn	Lead/Leading	Lead Paint/Lead	Known				Steel Girders for Light Posts to the Platform Undercroft (Grey) 13.5%			R531302	N	N
43208	ACTIVE	N	N053-00-A/261	Platform 1 - Northbound Main - Station Building - Mill Hill East Stn	Lead/Leading	Lead Paint/Lead	Known				Steel Girders for Platform Fence to the Platform Undercroft (Green) 0.2%			R531302	N	N
19226	ACTIVE	N	N053-00-A/261	Platform 1 - Northbound Main - Station Building - Mill Hill East Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Matt Coating - Canopy Beams. Thickness 0.14mm: Analysis 10.68%				N	N
8910	ACTIVE	N	N053-00-A/281	Office - Station Building - Mill Hill East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20110	ACTIVE	N	N053-00-A/281	Office - Station Building - Mill Hill East Stn	LUL Heaters	Asbestos	Surveyed – Not Detected									
20111	ACTIVE	N	N053-00-A/281	Office - Station Building - Mill Hill East Stn	Other Electrical Boxes	Asbestos	Surveyed – Not Detected				Electrical Box					



# Hazardous Material Asset Register - Summary



## N053-00 - Station Building - Mill Hill East Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8911	ACTIVE	N	N053-00-A/331	Mess Room - Station Building - Mill Hill East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20112	ACTIVE	N	N053-00-A/331	Mess Room - Station Building - Mill Hill East Stn	LUL Heaters	Asbestos	Surveyed – Not Detected									
8912	ACTIVE	N	N053-00-A/341	Mess Room - Station Building - Mill Hill East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8913	ACTIVE	N	N053-00-A/416	Toilet: Unisex - Station Building - Mill Hill East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19227	ACTIVE	N	N053-00-A/416/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Mill Hill East Stn	Glazing Rope	Asbestos	Strongly Presumed				Glass Ceiling Roof - Rope Seal				N	N
8914	ACTIVE	N	N053-00-A/436	Waiting Room - Station Building - Mill Hill East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20114	ACTIVE	N	N053-00-A/436	Waiting Room - Station Building - Mill Hill East Stn	LUL Heaters	Asbestos	Surveyed – Not Detected									
8915	ACTIVE	N	N053-00-A/601	Stairs: Linear - Station Building - Mill Hill East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20113	ACTIVE	N	N053-00-A/601	Stairs: Linear - Station Building - Mill Hill East Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					

## N061-00 - Station Building - High Barnet Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8918	ACTIVE	N	N061-00-1/001	Booking Hall - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17419	ACTIVE	N	N061-00-1/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - High Barnet Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				YES	
8919	ACTIVE	N	N061-00-1/011	Ticket Office - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17420	ACTIVE	N	N061-00-1/011	Ticket Office - Station Building - High Barnet Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8920	ACTIVE	N	N061-00-1/021	POM - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N061-00 - Station Building - High Barnet Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19122	ACTIVE	N	N061-00-1/021/FLR-01	Floor - 1 - POM - Station Building - High Barnet Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Tiles					YES
8921	ACTIVE	N	N061-00-1/031	Mess Room - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17421	ACTIVE	N	N061-00-1/031	Mess Room - Station Building - High Barnet Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8922	ACTIVE	N	N061-00-1/036	Toilet: Unisex - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17422	ACTIVE	N	N061-00-1/036	Toilet: Unisex - Station Building - High Barnet Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8923	ACTIVE	N	N061-00-1/081	Lobby - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17423	ACTIVE	N	N061-00-1/081/FLR-01	Floor - 1 - Lobby - Station Building - High Barnet Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Tiles					YES
8924	ACTIVE	N	N061-00-1/082	Lobby - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
8925	ACTIVE	N	N061-00-1/416	Toilet - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19123	ACTIVE	N	N061-00-1/416	Toilet - Station Building - High Barnet Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8926	ACTIVE	N	N061-00-1/417	Toilet - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17426	ACTIVE	N	N061-00-1/417	Toilet - Station Building - High Barnet Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8927	ACTIVE	N	N061-00-1/451	Tenancy - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17999	ACTIVE	N	N061-00-1/451	Tenancy - Station Building - High Barnet Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8928	ACTIVE	N	N061-00-1/452	Tenancy - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17425	ACTIVE	N	N061-00-1/452/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - High Barnet Stn	Void	Asbestos	Surveyed - Not Detected				Above 1st Floor Attic - slate roof & timber boarding; Roof sealant - Horse Hair, Lime Mortar				YES	



# Hazardous Material Asset Register - Summary



## N061-00 - Station Building - High Barnet Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17424	ACTIVE	N	N061-00-1/452/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - High Barnet Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
8929	ACTIVE	N	N061-00-1/453	Tenancy - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8930	ACTIVE	N	N061-00-1/454	Tenancy - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17427	ACTIVE	N	N061-00-1/454	Tenancy - Station Building - High Barnet Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8931	ACTIVE	N	N061-00-1/457	Toilet - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8932	ACTIVE	N	N061-00-1/458	Toilet - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8933	ACTIVE	N	N061-00-1/459	Shower Room - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8934	ACTIVE	N	N061-00-1/576	Stairs: Linear - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19124	ACTIVE	N	N061-00-1/576/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - High Barnet Stn	Void	Asbestos	Surveyed – Not Detected				Brick; Wooden Roof above false ceiling				YES	
8935	ACTIVE	N	N061-00-1/601	Stairs: Linear - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17428	ACTIVE	N	N061-00-1/601	Stairs: Linear - Station Building - High Barnet Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
17429	ACTIVE	N	N061-00-1/601	Stairs: Linear - Station Building - High Barnet Stn	Lead/Leading	Lead Paint/Lead	Known				Upstands & Overbridge: Cream Oil Based Paint. Thickness 0.59mm : Analysis 12.02%				N	N
8936	ACTIVE	N	N061-00-1/602	Stairs: Linear - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18000	ACTIVE	N	N061-00-1/602	Stairs: Linear - Station Building - High Barnet Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
17430	ACTIVE	N	N061-00-1/602	Stairs: Linear - Station Building - High Barnet Stn	Lead/Leading	Lead Paint/Lead	Known				Upstands, banisters & Overbridge: Cream Oil Based Paint. Thickness 0.59mm : Analysis 12.02%				N	N
17431	ACTIVE	N	N061-00-1/636	Overbridge - Station Building - High Barnet Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N061-00 - Station Building - High Barnet Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17432	ACTIVE	N	N061-00-1/636	Overbridge - Station Building - High Barnet Stn	Lead/Leading	Lead Paint/Lead	Known				Upstands & Overbridge: Cream Oil Based Paint. Thickness 0.59mm : Analysis 12.02%				N	N
8937	ACTIVE	N	N061-00-1/661	Switch Room - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17882	ACTIVE	N	N061-00-1/661/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - High Barnet Stn	Void	Asbestos	No Access: Presumed				Above ceiling tiles				YES	
17433	ACTIVE	N	N061-00-1/661/CLG-02	Ceiling: Solid - 2 - Switch Room - Station Building - High Barnet Stn	Void	Asbestos	No Access: Presumed				Above ceiling tiles				YES	
42694	INACTIVE	N	N061-00-1/661/FLR-01	Floor - 1 - Switch Room - Station Building - High Barnet Stn		Asbestos	Presumed									
17434	ACTIVE	N	N061-00-1/661/FLR-01	Floor - 1 - Switch Room - Station Building - High Barnet Stn	Cable Duct: Other	Asbestos	Presumed				Cable ducts by Wall 3 Ducts not visible - Concealed within concrete 17-03-2023		3		N	N
18219	ACTIVE	N	N061-00-1/661/WAL-001 80904720	Wall: Internal - 1 - Switch Room - Station Building - High Barnet Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Switch boxes wall 1: 1 x 60 amps. Presumed asbestos insulating materials within Reinspected 17-03-2023		1		N	N
17435	ACTIVE	N	N061-00-1/661/WAL-003 80904722	Wall: Internal - 3 - Switch Room - Station Building - High Barnet Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es) to Wall 3. Presumed asbestos insulating materials within. No electrician on site inspect within 04-04-2023		3			
44124	ACTIVE	N	N061-00-1/661/WAL-003 80904722	Wall: Internal - 3 - Switch Room - Station Building - High Barnet Stn Wall: Internal	Isolator Switches	Asbestos	Presumed				1 x 30 amp switch box. Presumed asbestos insulating materials within Not inspected within during 2023 reinspection as no electrician present.		1		N	N
44133	ACTIVE	N	N061-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - High Barnet Stn	Cable Ducts: Cement	Asbestos	Presumed				6no Ducts to wall 3 Presumed HMT - Check next reinspection. 4-Rail services could not locate ducts but ducts buried in concrete potentially present. (5475)		6		N	N
8938	ACTIVE	N	N061-00-2/001	Booking Hall - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18996	ACTIVE	N	N061-00-2/001	Booking Hall - Station Building - High Barnet Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8939	ACTIVE	N	N061-00-2/011	Ticket Office - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
17436	ACTIVE	N	N061-00-2/011	Ticket Office - Station Building - High Barnet Stn	No Access	Asbestos	Surveyed – Not Detected				Marble tiles to floor, plaster on brick /block to walls, wooden door, window and framework to wall 4, plasterboard to wall 4 above door, supalux to ceiling. 4Rail R726751					



# Hazardous Material Asset Register - Summary



## N061-00 - Station Building - High Barnet Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8940	ACTIVE	N	N061-00-2/021	POM - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
17437	ACTIVE	N	N061-00-2/021	POM - Station Building - High Barnet Stn	No Access	Asbestos	Presumed				Presumed materials within safe unit to wall 3  Metal/rubber computer tiles to floor, concrete to floor, plaster on brickwork to walls, wooden door and framework to wall 4, supalux to false ceiling, metal to ceiling above false ceiling, modern electrical equipment throughout. 4Rail Report R726751					
8941	ACTIVE	N	N061-00-2/047	Kitchen - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17883	ACTIVE	N	N061-00-2/047	Kitchen - Station Building - High Barnet Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
8942	ACTIVE	N	N061-00-2/053	Mess Room - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17438	ACTIVE	N	N061-00-2/053	Mess Room - Station Building - High Barnet Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
17439	ACTIVE	N	N061-00-2/053	Mess Room - Station Building - High Barnet Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supulux Panels to Outlet Pipes					
17440	ACTIVE	N	N061-00-2/053/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - High Barnet Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				YES	
8943	ACTIVE	N	N061-00-2/054	Mess Room - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17441	ACTIVE	N	N061-00-2/054	Mess Room - Station Building - High Barnet Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
18001	ACTIVE	N	N061-00-2/054/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - High Barnet Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
17442	ACTIVE	N	N061-00-2/054/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - High Barnet Stn	Void	Asbestos	Surveyed – Not Detected				Attic Insulation - Rockwool; Wood - Beams; Walls Brick above false ceiling				YES	
17884	ACTIVE	N	N061-00-2/054/FLR-01	Floor - 1 - Mess Room - Station Building - High Barnet Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl Flooring					
8944	ACTIVE	N	N061-00-2/055	Mess Room - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N061-00 - Station Building - High Barnet Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18494	ACTIVE	N	N061-00-2/055/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - High Barnet Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
17443	ACTIVE	N	N061-00-2/055/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - High Barnet Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				YES	
8945	ACTIVE	N	N061-00-2/056	Mess Room - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17885	ACTIVE	N	N061-00-2/056/FLR-01	Floor - 1 - Mess Room - Station Building - High Barnet Stn	Void	Asbestos	Surveyed – Not Detected				Supalux under stairs					YES
8946	ACTIVE	N	N061-00-2/057	Lobby - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17444	ACTIVE	N	N061-00-2/057	Lobby - Station Building - High Barnet Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8947	ACTIVE	N	N061-00-2/058	Mess Room - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8948	ACTIVE	N	N061-00-2/081	Lobby - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17445	ACTIVE	N	N061-00-2/081	Lobby - Station Building - High Barnet Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
17446	ACTIVE	N	N061-00-2/081	Lobby - Station Building - High Barnet Stn	Lead/Leading	Lead Paint/Lead	Known				Girder: Grey Oil Based Paint. Thickness 0.20mm : Analysis 31.93%				N	N
8949	ACTIVE	N	N061-00-2/082	Lobby - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
17447	ACTIVE	N	N061-00-2/082	Lobby - Station Building - High Barnet Stn	No Access	Asbestos	Surveyed – Not Detected				Marble tiles to floor, brickwork to walls, ceramic tiles to walls, wooden doors and framework to walls, supalux to false ceiling, metal to false ceiling hatch, metal to ceiling above false ceiling					
8950	ACTIVE	N	N061-00-2/201	Passage - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8951	ACTIVE	N	N061-00-2/236	Passage - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17886	ACTIVE	N	N061-00-2/236	Passage - Station Building - High Barnet Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N061-00 - Station Building - High Barnet Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8952	ACTIVE	N	N061-00-2/261	Platform 1 - Northbound Fast - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17449	INACTIVE	N	N061-00-2/261	Platform 1 - Northbound Fast - Station Building - High Barnet Stn	Westing house Boxes	Asbestos	Strongly Presumed				DUPLICATE OF 17449 Asbestos insulation presumed within Westing House Boxes near the end of Platform 1 Not inspected within during 2023 re inspection as no electrician present		2		N	N
17450	ACTIVE	N	N061-00-2/261	Platform 1 - Northbound Fast - Station Building - High Barnet Stn	Isolator Switches	Lead Paint/Lead	Known				Switch Boxes: Grey Oil Based Paint. Thickness 0.38mm : Analysis 12.69% ( same boxes as ref.17449)		2		N	N
17887	ACTIVE	N	N061-00-2/261	Platform 1 - Northbound Fast - Station Building - High Barnet Stn	Lead/Leading	Lead Paint/Lead	Known				Upstands: Green Oil Based Paint. Thickness 0.42mm : Analysis 11.31%				N	N
17448	ACTIVE	N	N061-00-2/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - High Barnet Stn	Void	Asbestos	Surveyed – Not Detected				External Roof - Tile Cement Non Asbestos above Canopy - Wooden Underneath				YES	
8953	ACTIVE	N	N061-00-2/262	Platform 2 - Southbound Fast - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17451	ACTIVE	N	N061-00-2/262	Platform 2 - Southbound Fast - Station Building - High Barnet Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
17452	ACTIVE	N	N061-00-2/262	Platform 2 - Southbound Fast - Station Building - High Barnet Stn	Lead/Leading	Lead Paint/Lead	Known				Upstands: Green Oil Based Paint. Thickness 0.42mm : Analysis 11.31%				N	N
8954	ACTIVE	N	N061-00-2/263	Platform 3 - Southbound Main - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17453	INACTIVE	N	N061-00-2/263	Platform 3 - Southbound Main - Station Building - High Barnet Stn	Westing house Boxes	Asbestos	Strongly Presumed				Insulation within Westing House Boxes (trackside mid-way by platform 3) presumed to contain asbestos R.A.S - This should be on track and is already covered by Record 33909. Deactivated		9		N	N
17454	ACTIVE	N	N061-00-2/263	Platform 3 - Southbound Main - Station Building - High Barnet Stn	Lead/Leading	Lead Paint/Lead	Known				Upstands: Green Oil Based Paint. Thickness 0.42mm : Analysis 11.31%				N	N
8955	ACTIVE	N	N061-00-2/281	Station Supervisor Office - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17888	ACTIVE	N	N061-00-2/281/CLG-01	Ceiling: Solid - 1 - Station Supervisor Office - Station Building - High Barnet Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				YES	



# Hazardous Material Asset Register - Summary



## N061-00 - Station Building - High Barnet Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18997	ACTIVE	N	N061-00-2/281/CLG-01	Ceiling: Solid - 1 - Station Supervisor Office - Station Building - High Barnet Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Fibreboard & Plasterboard					
18002	ACTIVE	N	N061-00-2/281/WDW-01	Window - 1 - Station Supervisor Office - Station Building - High Barnet Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard divide above windows					
18495	ACTIVE	N	N061-00-2/281/WDW-02	Window - 2 - Station Supervisor Office - Station Building - High Barnet Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard divide above windows					
8956	ACTIVE	N	N061-00-2/291	Office - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8957	ACTIVE	N	N061-00-2/316	Locker Room - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17455	ACTIVE	N	N061-00-2/316	Locker Room - Station Building - High Barnet Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8958	ACTIVE	N	N061-00-2/317	Locker Room - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17456	ACTIVE	N	N061-00-2/317	Locker Room - Station Building - High Barnet Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8959	ACTIVE	N	N061-00-2/401	Bin Store - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17457	ACTIVE	N	N061-00-2/401	Bin Store - Station Building - High Barnet Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8960	ACTIVE	N	N061-00-2/411	Store - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17458	ACTIVE	N	N061-00-2/411	Store - Station Building - High Barnet Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
17889	ACTIVE	N	N061-00-2/411	Store - Station Building - High Barnet Stn	Lead/Leading	Lead Paint/Lead	Known				2 x Down Pipes: Green Oil Based Paint. Thickness 0.39mm : Analysis 8.93%		2		N	N
8961	ACTIVE	N	N061-00-2/412	Store - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17459	ACTIVE	N	N061-00-2/412/CLG-01	Ceiling: Solid - 1 - Store - Station Building - High Barnet Stn	Void	Asbestos	Surveyed – Not Detected				Above concrete ceiling is - access hatch to loft area in canopy; metal water tank; bitumen roofing felt - Non Asbestos				YES	
17460	ACTIVE	N	N061-00-2/412/WAL-001	Wall: Internal - 1 - Store - Station Building - High Barnet Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Partition wall between rooms 2/451 & 2/412 Partition wall is plasterboard with patches of supalux above false ceiling 04-04-2023				N	N



# Hazardous Material Asset Register - Summary



## N061-00 - Station Building - High Barnet Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44138	ACTIVE	N	N061-00-2/412/WAL-002	Wall: Internal - 2 - Store - Station Building - High Barnet Stn	Gasket :Pipework	Asbestos	Presumed				Gaskets to Pipework Presumed (potentially concealed at joints) Reinspected 04-04-2023				N	N
8962	ACTIVE	N	N061-00-2/413	Store - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17462	ACTIVE	N	N061-00-2/413	Store - Station Building - High Barnet Stn	Lead/Leading	Lead Paint/Lead	Known				Stairs: White Oil Based Paint. Thickness 0.28mm : Analysis 14.54%				N	N
17461	ACTIVE	N	N061-00-2/413/FLR-01	Floor - 1 - Store - Station Building - High Barnet Stn	Void	Asbestos	Surveyed – Not Detected				Wood under stairs					YES
8963	ACTIVE	N	N061-00-2/414	Office - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
17890	ACTIVE	N	N061-00-2/414	Office - Station Building - High Barnet Stn	No Access	Asbestos	Surveyed – Not Detected				Carpet to floor, plaster on brick/block to walls, plasterboard to partition wall 4, wooden door and framework to wall 4, wooden door and framework to wall 4, wooden window and framework to wall 2, rope to wall 2 window pulley - non asbestos, modern electrical equipment throughout, MMMF tiles to false ceiling, plaster to ceiling above false ceiling. (4Rail Report R726751)					
8964	ACTIVE	N	N061-00-2/415	Store - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
18003	ACTIVE	N	N061-00-2/415	Store - Station Building - High Barnet Stn	No Access	Asbestos	Surveyed – Not Detected				Carpet tiles on quarry tiles to floor, plaster on brick to solid walls, plasterboard to partition walls, wooden doors and framework to walls, wooden window and framework to wall 2, rope to wall 2 window pulleys - non asbestos, modern boiler and cylinder and pipework to boiler cupboard, wooden boxing, unlagged pipework within to walls, MMMF tiles to ceiling, plaster to ceiling above false ceiling, metal pipework with foam insulation, plastic vent to wall 2, 4Rail Report R726751					
8965	ACTIVE	N	N061-00-2/417	Toilet: Female - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17463	ACTIVE	N	N061-00-2/417	Toilet: Female - Station Building - High Barnet Stn	No Access	Asbestos	Surveyed – Not Detected				Quarry tiles on concrete to floor, ceramic tiles to walls, ceramic toilet and sink, metal cistern, plastic and metal pipework unlagged to walls, electrical heater to wall 1, wooden door and framework to wall 4, meter above door, plasterboard to fixed false ceiling - no access above (4Rail Report R726751)					



# Hazardous Material Asset Register - Summary



## N061-00 - Station Building - High Barnet Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
53948	ACTIVE	N	N061-00-2/417/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - High Barnet Stn		Asbestos	Presumed				No access above fixed ceiling					
8966	ACTIVE	N	N061-00-2/418	Toilet: Unisex - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed				No information above wood ceiling					
17464	ACTIVE	N	N061-00-2/418	Toilet: Unisex - Station Building - High Barnet Stn	No Access	Asbestos	No Access: Presumed				No access above wooden ceiling  Quarry tiles on concrete to floor, ceramic tiles to lower walls, brickwork to walls, ceramic toilet, cistern and sink, wooden door, window and framework to walls, wood to ceiling, plastic and metal pipework to walls, foam insulation to pipework, plaster on wood panels to upper walls 1&3. 4Rail Report R726751				YES	
8967	ACTIVE	N	N061-00-2/419	Toilet: Unisex - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
17465	ACTIVE	N	N061-00-2/419	Toilet: Unisex - Station Building - High Barnet Stn	No Access	Asbestos	Surveyed - Not Detected				Modern lino to floor, plaster on brick to solid walls, plasterboard to partition walls, wooden door and framework to wall 4, wooden window and framework to wall 2, rope to walls 2 window pulley - non asbestos, ceramic toilet, cistern and tiles behind toilet, wooden boxing behind toilet, not inspected within as sealed, modern radiator to wall 1, MMMF tiles to false ceiling, plaster to ceiling above false ceiling. 4Rail Report R726751					
8968	ACTIVE	N	N061-00-2/420	Shower Room - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
17891	ACTIVE	N	N061-00-2/420	Shower Room - Station Building - High Barnet Stn	No Access	Asbestos	Surveyed - Not Detected				Modern lino to floor, ceramic tiles to walls, wooden door and framework to wall 4, wooden windows and framework to wall 2, rope to wall 2 window pulley - non asbestos, ceramic toilet, cistern and sink, wood boxing, unlagged pipework within to wall 4, MMMF tiles to false ceiling, plaster to ceiling above false ceiling. 4Rail Report R726751					
8969	ACTIVE	N	N061-00-2/421	Toilet: Male - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17466	ACTIVE	N	N061-00-2/421	Toilet: Male - Station Building - High Barnet Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
8970	ACTIVE	N	N061-00-2/422	Toilet: Female - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N061-00 - Station Building - High Barnet Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17467	ACTIVE	N	N061-00-2/422	Toilet: Female - Station Building - High Barnet Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8971	ACTIVE	N	N061-00-2/426	Toilet - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8972	ACTIVE	N	N061-00-2/427	Toilet: Unisex - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8973	ACTIVE	N	N061-00-2/428	Toilet: Unisex - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17468	ACTIVE	N	N061-00-2/428	Toilet: Unisex - Station Building - High Barnet Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8974	ACTIVE	N	N061-00-2/436	Waiting Room - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18004	ACTIVE	N	N061-00-2/436	Waiting Room - Station Building - High Barnet Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8975	ACTIVE	N	N061-00-2/437	Waiting Room - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17469	ACTIVE	N	N061-00-2/437	Waiting Room - Station Building - High Barnet Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8976	ACTIVE	N	N061-00-2/451	Office - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17892	ACTIVE	N	N061-00-2/451/WAL-002	Wall: Internal - 2 - Office - Station Building - High Barnet Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Partition Wall					
20023	ACTIVE	N	N061-00-2/451/WAL-004	Wall: Internal - 4 - Office - Station Building - High Barnet Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Partition Wall					
8977	ACTIVE	N	N061-00-2/452	Office - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
17470	ACTIVE	N	N061-00-2/452/WAL-002	Wall: Internal - 2 - Office - Station Building - High Barnet Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Carpet tiles on concrete, plasterboard to partition walls, plaster on brick to solid walls, PVC/ wood windows and framework to walls, rope to window pulleys - non asbestos, wooden doors & framework to walls, modern. electrical equipment throughout. MMMF tiles to false. ceiling, plasterboard to second false ceiling, fixed not inspected above. 4Rail Report R726751.				N	N



# Hazardous Material Asset Register - Summary



## N061-00 - Station Building - High Barnet Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17471	ACTIVE	N	N061-00-2/452/WAL-004	Wall: Internal - 4 - Office - Station Building - High Barnet Stn	Other Boarding	Asbestos	No Access: Presumed				No access above fixed false ceiling. 4Rail Report R726751				N	N
8978	ACTIVE	N	N061-00-2/453	Passage - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17472	ACTIVE	N	N061-00-2/453/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - High Barnet Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Panelling to ceiling					
18496	ACTIVE	N	N061-00-2/453/WAL-002	Wall: Internal - 2 - Passage - Station Building - High Barnet Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Partition Wall					
17893	ACTIVE	N	N061-00-2/453/WAL-004	Wall: Internal - 4 - Passage - Station Building - High Barnet Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Partition Wall					
8979	ACTIVE	N	N061-00-2/455	Passage - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
8980	ACTIVE	N	N061-00-2/661	Switch Room - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17477	ACTIVE	N	N061-00-2/661	Switch Room - Station Building - High Barnet Stn		Anthrax	Surveyed - Not Detected				No Anthrax Detected					
17474	ACTIVE	N	N061-00-2/661	Switch Room - Station Building - High Barnet Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux panels above door					
18220	ACTIVE	N	N061-00-2/661/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - High Barnet Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above false ceiling				YES	
17475	ACTIVE	N	N061-00-2/661/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - High Barnet Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux					
17473	ACTIVE	N	N061-00-2/661/FLR-01	Floor - 1 - Switch Room - Station Building - High Barnet Stn	Void	Asbestos	Surveyed - Not Detected				Bituminous Pipe Lining. Floor hatches (no access on re-inspection)					YES
17894	ACTIVE	N	N061-00-2/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - High Barnet Stn	Isolator Switches	Asbestos	Strongly Presumed				Isolation Switches 4 x 100 amp 1 x 300amp. Presumed asbestos insulation within. Not inspected within during 2023 reinspection as no electrician was present		5		N	N
17476	ACTIVE	N	N061-00-2/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - High Barnet Stn	Isolator Switches	Asbestos	Strongly Presumed				Isolation Switches Wall 3: 7 X 60amp 1 x 100 amp 1 x 30amp. Presumed asbestos insulation within. Not Inspected within during 2023 re inspection as no electrician present		9		N	N



# Hazardous Material Asset Register - Summary



## N061-00 - Station Building - High Barnet Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19492	ACTIVE	N	N061-00-2/661/WAL-004 80904934	Wall: Internal - 4 - Switch Room - Station Building - High Barnet Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es) to wall 4. Presumed asbestos insulating materials within. Not inspected within during 2023 re inspection as no electrician present		1		N	N
8981	ACTIVE	N	N061-00-2/662	Switch Room - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17478	ACTIVE	N	N061-00-2/662	Switch Room - Station Building - High Barnet Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x Isolation Switch box to wall 2. Presumed asbestos insulating materials within. Not inspected within during 2023 re inspection as no electrician present.		1		N	N
17479	ACTIVE	N	N061-00-2/662/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - High Barnet Stn	Other Boarding	Asbestos	Strongly Presumed				Panels length of Wall 2 and Wall 3 doorway framework. Possible non ACM supalux for all panels		2		N	N
8982	ACTIVE	N	N061-00-2/746	SCR - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
17480	ACTIVE	N	N061-00-2/746	SCR - Station Building - High Barnet Stn	No Access	Asbestos	Surveyed – Not Detected				Concrete floor & ceiling, plaster on brick to walls, textured coating to walls 1 & 3 - Non asbestos, wooden doors and framework, plasterboard to partition wall, modern electrical equipment throughout, modern firestopping, plastic cables, metal conduits and CMS (4Rail Report R726751)					
8983	ACTIVE	N	N061-00-2/756	Station Control Room - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17481	ACTIVE	N	N061-00-2/756	Station Control Room - Station Building - High Barnet Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
8984	ACTIVE	N	N061-00-2/776	Plant Room - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8985	ACTIVE	N	N061-00-2/801	Office - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17483	ACTIVE	N	N061-00-2/801	Office - Station Building - High Barnet Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
8986	ACTIVE	N	N061-00-2/802	Office - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17896	ACTIVE	N	N061-00-2/802	Office - Station Building - High Barnet Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					



# Hazardous Material Asset Register - Summary



## N061-00 - Station Building - High Barnet Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8987	ACTIVE	N	N061-00-2/803	Office - Station Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N063-00 - Station Building - Totteridge & Whetstone Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9059	ACTIVE	N	N063-00-1/001	Booking Hall - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17387	ACTIVE	N	N063-00-1/001/CLG-01	Ceiling: Suspended - 1 - Booking Hall - Station Building - Totteridge & Whetstone Stn	Void	Asbestos	Surveyed – Not Detected				Tiles above false ceiling				YES	
9060	ACTIVE	N	N063-00-1/011	Ticket Office - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17388	ACTIVE	N	N063-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Totteridge & Whetstone Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
17389	ACTIVE	N	N063-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Totteridge & Whetstone Stn	Void	Asbestos	Surveyed – Not Detected				Timber Rafters; Lagging - Rock Wool above false ceiling				YES	
19112	ACTIVE	N	N063-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Totteridge & Whetstone Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
9061	ACTIVE	N	N063-00-1/021	POM - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17390	ACTIVE	N	N063-00-1/021/CLG-01	Ceiling: Solid - 1 - POM - Station Building - Totteridge & Whetstone Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Fibre Boarding					
18218	ACTIVE	N	N063-00-1/021/CLG-01	Ceiling: Solid - 1 - POM - Station Building - Totteridge & Whetstone Stn	Void	Asbestos	Surveyed – Not Detected				Solid and new metal work, PVC cables above false ceiling				YES	
18994	ACTIVE	N	N063-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Totteridge & Whetstone Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
9062	ACTIVE	N	N063-00-1/031	Mess Room - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17391	ACTIVE	N	N063-00-1/031	Mess Room - Station Building - Totteridge & Whetstone Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					



# Hazardous Material Asset Register - Summary



## N063-00 - Station Building - Totteridge & Whetstone Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19113	ACTIVE	N	N063-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Totteridge & Whetstone Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18493	ACTIVE	N	N063-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Totteridge & Whetstone Stn	Void	Asbestos	Surveyed – Not Detected				Timber Rafters; Lagging - Rock Wool above false ceiling				YES	
9063	ACTIVE	N	N063-00-1/036	Toilet: Unisex - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17392	ACTIVE	N	N063-00-1/036	Toilet: Unisex - Station Building - Totteridge & Whetstone Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing Panel					
18468	ACTIVE	N	N063-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Totteridge & Whetstone Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
19114	ACTIVE	N	N063-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Totteridge & Whetstone Stn	Void	Asbestos	Surveyed – Not Detected				Timber Rafters; Lagging - Rock Wool above false ceiling				YES	
9064	ACTIVE	N	N063-00-1/071	Circulation Area - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18995	ACTIVE	N	N063-00-1/071/CLG-01	Ceiling: Suspended - 1 - Circulation Area - Station Building - Totteridge & Whetstone Stn	Void	Asbestos	Surveyed – Not Detected				Tiles - Non Asbestos; Fibre board / plaster board. No access to loft space. Possible ACM's				YES	
17393	ACTIVE	N	N063-00-1/071/CLG-01	Ceiling: Suspended - 1 - Circulation Area - Station Building - Totteridge & Whetstone Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
17394	ACTIVE	N	N063-00-1/071/CLG-01	Ceiling: Suspended - 1 - Circulation Area - Station Building - Totteridge & Whetstone Stn	Void	Asbestos	No Access: Presumed				No access to loft space above false ceiling. Possible ACM's				YES	
9065	ACTIVE	N	N063-00-1/081	Lobby - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17996	ACTIVE	N	N063-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Totteridge & Whetstone Stn	Void	Asbestos	Surveyed – Not Detected				Timber Rafters; Lagging - Rock Wool above false ceiling				YES	
17395	ACTIVE	N	N063-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Totteridge & Whetstone Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
9066	ACTIVE	N	N063-00-1/281	Office - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19115	ACTIVE	N	N063-00-1/281	Office - Station Building - Totteridge & Whetstone Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					



# Hazardous Material Asset Register - Summary



## N063-00 - Station Building - Totteridge & Whetstone Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19412	ACTIVE	N	N063-00-1/281	Office - Station Building - Totteridge & Whetstone Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Tiles					
17396	ACTIVE	N	N063-00-1/281/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Totteridge & Whetstone Stn	Void	Asbestos	Surveyed – Not Detected				Tiles above false ceiling				YES	
9067	ACTIVE	N	N063-00-1/601	Stairs: Linear - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19116	ACTIVE	N	N063-00-1/601/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Totteridge & Whetstone Stn	Void	Asbestos	Surveyed – Not Detected				Hardboard panels above metal roofing sheets; Tiles				YES	
9068	ACTIVE	N	N063-00-1/602	Stairs: Linear - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17397	ACTIVE	N	N063-00-1/602/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Totteridge & Whetstone Stn	Void	Asbestos	Surveyed – Not Detected				Tiles; Timber rafters above metal roofing sheets; Tiles				YES	
9069	ACTIVE	N	N063-00-1/661	Switch Room - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42699	ACTIVE	N	N063-00-1/661	Switch Room - Station Building - Totteridge & Whetstone Stn	Isolator Switches	Asbestos	Strongly Presumed				W3 1 X 30amp. Presumed asbestos insulating materials within		1		N	N
46167	ACTIVE	N	N063-00-1/661/CTR-01	Contactors: Changeover - 01 - Switch Room - Station Building - Totteridge & Whetstone Stn	Isolator Switches	Asbestos	Strongly Presumed				1x Switch box. Presumed insulating materials within		1			
42697	ACTIVE	N	N063-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Totteridge & Whetstone Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes W1 2 X 60amp, 1 x 100amp, 1 x Bus Bar. Presumed asbestos insulating materials within.		3		N	N
42698	ACTIVE	N	N063-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Totteridge & Whetstone Stn	Isolator Switches	Asbestos	Strongly Presumed				W2 2 X 60amp, 1 X 100amp Switch Boxes. Presumed asbestos insulating materials within		3		N	N
17398	ACTIVE	N	N063-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Totteridge & Whetstone Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				3x Transformer boxes - Presumed asbestos insulating materials within		3			
9070	ACTIVE	N	N063-00-1/746	SCR - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17399	ACTIVE	N	N063-00-1/746/CLG-01	Ceiling: Solid - 1 - SCR - Station Building - Totteridge & Whetstone Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Boarding - Non Asbestos					
17400	ACTIVE	N	N063-00-1/746/CLG-01	Ceiling: Solid - 1 - SCR - Station Building - Totteridge & Whetstone Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				YES	



# Hazardous Material Asset Register - Summary



## N063-00 - Station Building - Totteridge & Whetstone Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9071	ACTIVE	N	N063-00-2/081	Lobby - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19117	ACTIVE	N	N063-00-2/081	Lobby - Station Building - Totteridge & Whetstone Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9072	ACTIVE	N	N063-00-2/082	Lobby - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17401	ACTIVE	N	N063-00-2/082	Lobby - Station Building - Totteridge & Whetstone Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9073	ACTIVE	N	N063-00-2/261	Platform 1 - Northbound Fast - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
17402	ACTIVE	N	N063-00-2/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Totteridge & Whetstone Stn	Void	Asbestos	Surveyed – Not Detected				Wood with metal roof. Inspection carried out within the canopy void did not identify any suspect materials that may contain asbestos, only dirt and rubbish present.				YES	
9074	ACTIVE	N	N063-00-2/262	Platform 2 - Southbound Fast - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
19118	ACTIVE	N	N063-00-2/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - Totteridge & Whetstone Stn	Void	Asbestos	Surveyed – Not Detected				Wood with metal roof. Inspection carried out within the canopy void did not identify any suspect materials that may contain asbestos, only dirt and rubbish present.				YES	
9075	ACTIVE	N	N063-00-2/406	Store - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17403	ACTIVE	N	N063-00-2/406	Store - Station Building - Totteridge & Whetstone Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9076	ACTIVE	N	N063-00-2/416	Toilet: Unisex - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17404	ACTIVE	N	N063-00-2/416	Toilet: Unisex - Station Building - Totteridge & Whetstone Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panelling					
9077	ACTIVE	N	N063-00-2/417	Toilet: Female - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17997	ACTIVE	N	N063-00-2/417	Toilet: Female - Station Building - Totteridge & Whetstone Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9078	ACTIVE	N	N063-00-2/418	Toilet: Male - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N063-00 - Station Building - Totteridge & Whetstone Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17405	ACTIVE	N	N063-00-2/418	Toilet: Male - Station Building - Totteridge & Whetstone Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9079	ACTIVE	N	N063-00-2/419	Store - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17406	ACTIVE	N	N063-00-2/419	Store - Station Building - Totteridge & Whetstone Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9080	ACTIVE	N	N063-00-2/426	Toilet: Unisex - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17407	ACTIVE	N	N063-00-2/426/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Totteridge & Whetstone Stn	Void	Asbestos	Surveyed – Not Detected				Above hatch in ceiling is rafters for roof				YES	
9081	ACTIVE	N	N063-00-2/427	Store - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19119	ACTIVE	N	N063-00-2/427/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Totteridge & Whetstone Stn	Rope Gaskets	Asbestos	Strongly Presumed				Rope Gasket - SP. Timber Glass Roof					
9082	ACTIVE	N	N063-00-2/436	Waiting Room - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17408	ACTIVE	N	N063-00-2/436	Waiting Room - Station Building - Totteridge & Whetstone Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Supalux Panel behind heater					
9083	ACTIVE	N	N063-00-2/437	Waiting Room - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17409	ACTIVE	N	N063-00-2/437	Waiting Room - Station Building - Totteridge & Whetstone Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - White Foam backing					
9084	ACTIVE	N	N063-00-2/481	Store - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17410	ACTIVE	N	N063-00-2/481	Store - Station Building - Totteridge & Whetstone Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9085	ACTIVE	N	N063-00-2/551	Yard - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17998	ACTIVE	N	N063-00-2/551	Yard - Station Building - Totteridge & Whetstone Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9086	ACTIVE	N	N063-00-2/661	Switch Room - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N063-00 - Station Building - Totteridge & Whetstone Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17411	ACTIVE	N	N063-00-2/661	Switch Room - Station Building - Totteridge & Whetstone Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9087	ACTIVE	N	N063-00-2/662	Switch Room - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42696	ACTIVE	N	N063-00-2/662	Switch Room - Station Building - Totteridge & Whetstone Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes W4, W3 2 X 100 amp, 2 x 60 amp 1 x 200amp Bus Bar. Presumed asbestos insulating materials within				N	N
17412	ACTIVE	N	N063-00-2/662	Switch Room - Station Building - Totteridge & Whetstone Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - White Foam backing					
9088	ACTIVE	N	N063-00-2/711	SER - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19120	ACTIVE	N	N063-00-2/711	SER - Station Building - Totteridge & Whetstone Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
9089	ACTIVE	N	N063-00-2/756	Store - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17414	ACTIVE	N	N063-00-2/756	Store - Station Building - Totteridge & Whetstone Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9090	ACTIVE	N	N063-00-2/951	Disused Room - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17415	ACTIVE	N	N063-00-2/951	Disused Room - Station Building - Totteridge & Whetstone Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - White Foam backing					
9091	ACTIVE	N	N063-00-2/952	Disused Room - Station Building - Totteridge & Whetstone Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17417	ACTIVE	N	N063-00-2/952	Disused Room - Station Building - Totteridge & Whetstone Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
17416	ACTIVE	N	N063-00-2/952	Disused Room - Station Building - Totteridge & Whetstone Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - White Foam backing					
17418	ACTIVE	N	N063-00-2/952/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Totteridge & Whetstone Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard				YES	
19121	ACTIVE	N	N063-00-2/952/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Totteridge & Whetstone Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					



# Hazardous Material Asset Register - Summary



## N065-00 - Station Building - Woodside Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9095	ACTIVE	N	N065-00-1/001	Booking Hall - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17351	ACTIVE	N	N065-00-1/001	Booking Hall - Station Building - Woodside Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9096	ACTIVE	N	N065-00-1/011	Ticket Office - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17353	ACTIVE	N	N065-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Woodside Park Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Steel above false ceiling				YES	
17352	ACTIVE	N	N065-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Woodside Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
19037	ACTIVE	N	N065-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Woodside Park Stn	Void	Asbestos	No Access: Presumed				Beneath Rubber Tiles					YES
9097	ACTIVE	N	N065-00-1/021	POM - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17354	ACTIVE	N	N065-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Woodside Park Stn	Void	Asbestos	No Access: Presumed				Beneath Rubber Tiles					YES
9098	ACTIVE	N	N065-00-1/031	Mess Room - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17355	ACTIVE	N	N065-00-1/031	Mess Room - Station Building - Woodside Park Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
9099	ACTIVE	N	N065-00-1/036	Toilet: Unisex - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19038	ACTIVE	N	N065-00-1/036	Toilet: Unisex - Station Building - Woodside Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9100	ACTIVE	N	N065-00-1/053	Mess Room - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17356	ACTIVE	N	N065-00-1/053/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Woodside Park Stn	Void	Asbestos	Surveyed – Not Detected				Wood above false ceiling				YES	
20022	ACTIVE	N	N065-00-1/053/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Woodside Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
17991	ACTIVE	N	N065-00-1/053/FLR-01	Floor - 1 - Mess Room - Station Building - Woodside Park Stn	Void	Asbestos	No Access: Presumed				Beneath Lino, Wood					YES



# Hazardous Material Asset Register - Summary



## N065-00 - Station Building - Woodside Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9101	ACTIVE	N	N065-00-1/081	Lobby - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19039	ACTIVE	N	N065-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Woodside Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18492	ACTIVE	N	N065-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Woodside Park Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles				YES	
17357	ACTIVE	N	N065-00-1/081/FLR-01	Floor - 1 - Lobby - Station Building - Woodside Park Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Tiles					YES
9102	ACTIVE	N	N065-00-1/261	Platform 1 - Northbound Fast - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17358	ACTIVE	N	N065-00-1/261	Platform 1 - Northbound Fast - Station Building - Woodside Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9103	ACTIVE	N	N065-00-1/262	Platform 2 - Southbound Fast - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17359	ACTIVE	N	N065-00-1/262	Platform 2 - Southbound Fast - Station Building - Woodside Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9104	ACTIVE	N	N065-00-1/281	Station Supervisor Office - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17361	ACTIVE	N	N065-00-1/281	Station Supervisor Office - Station Building - Woodside Park Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - White Foam Insulation					
17360	ACTIVE	N	N065-00-1/281	Station Supervisor Office - Station Building - Woodside Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Fireplace					
19040	ACTIVE	N	N065-00-1/281/FLR-01	Floor - 1 - Station Supervisor Office - Station Building - Woodside Park Stn	Void	Asbestos	No Access: Presumed				Beneath Lino, Wood					YES
9105	ACTIVE	N	N065-00-1/282	CER - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9106	ACTIVE	N	N065-00-1/311	Union Office - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17362	ACTIVE	N	N065-00-1/311/CLG-01	Ceiling: Suspended - 1 - Union Office - Station Building - Woodside Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					



# Hazardous Material Asset Register - Summary



## N065-00 - Station Building - Woodside Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17992	ACTIVE	N	N065-00-1/311/CLG-01	Ceiling: Suspended - 1 - Union Office - Station Building - Woodside Park Stn	Void	Asbestos	No Access: Presumed				Above false Ceiling				YES	
9107	ACTIVE	N	N065-00-1/411	Store - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17363	ACTIVE	N	N065-00-1/411	Store - Station Building - Woodside Park Stn		Asbestos	Surveyed - Not Detected				Acoustic Panel below sink					
17364	ACTIVE	N	N065-00-1/411	Store - Station Building - Woodside Park Stn	Lead/Leading	Lead Paint/Lead	Known				Walls & Ceilings: Cream Gloss Paint. Thickness 0.35mm : Analysis 4.83%				N	N
9108	ACTIVE	N	N065-00-1/412	Store - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17365	ACTIVE	N	N065-00-1/412	Store - Station Building - Woodside Park Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9109	ACTIVE	N	N065-00-1/416	Toilet: Male - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17366	ACTIVE	N	N065-00-1/416	Toilet: Male - Station Building - Woodside Park Stn	LUL Heaters	Asbestos	Surveyed - Not Detected				Heater - White Foam Insulation					
17367	ACTIVE	N	N065-00-1/416	Toilet: Male - Station Building - Woodside Park Stn	Lead/Leading	Lead Paint/Lead	Known				Boxing: Cream Gloss Paint. Thickness 0.40mm : Analysis 4.59%				N	N
19106	ACTIVE	N	N065-00-1/416/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Woodside Park Stn	Void	Asbestos	No Access: Presumed				Above Wood Ceiling				YES	
9110	ACTIVE	N	N065-00-1/426	Toilet: Female - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17368	ACTIVE	N	N065-00-1/426	Toilet: Female - Station Building - Woodside Park Stn	LUL Heaters	Asbestos	Surveyed - Not Detected				Heater - White Foam Insulation					
9111	ACTIVE	N	N065-00-1/427	Toilet: Female - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17370	ACTIVE	N	N065-00-1/427	Toilet: Female - Station Building - Woodside Park Stn	LUL Heaters	Asbestos	Surveyed - Not Detected				Heater - White Foam Insulation					
17369	ACTIVE	N	N065-00-1/427/FLR-01	Floor - 1 - Toilet - Station Building - Woodside Park Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden floor					YES
9112	ACTIVE	N	N065-00-1/428	Toilet: Male - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19107	ACTIVE	N	N065-00-1/428	Toilet: Male - Station Building - Woodside Park Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N065-00 - Station Building - Woodside Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9113	ACTIVE	N	N065-00-1/436	Waiting Room - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17371	ACTIVE	N	N065-00-1/436	Waiting Room - Station Building - Woodside Park Stn	LUL Heaters	Asbestos	Surveyed - Not Detected				Heater - White Foam Insulation					
9114	ACTIVE	N	N065-00-1/437	Waiting Room - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17372	ACTIVE	N	N065-00-1/437	Waiting Room - Station Building - Woodside Park Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9115	ACTIVE	N	N065-00-1/438	Waiting Room - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17373	ACTIVE	N	N065-00-1/438	Waiting Room - Station Building - Woodside Park Stn	LUL Heaters	Asbestos	Surveyed - Not Detected				Heater - White Foam Insulation					
19108	ACTIVE	N	N065-00-1/438/FLR-01	Floor - 1 - Waiting Room - Station Building - Woodside Park Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden floor					YES
9116	ACTIVE	N	N065-00-1/451	Tenancy - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17374	ACTIVE	N	N065-00-1/451	Tenancy - Station Building - Woodside Park Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Tenancy					
17993	ACTIVE	N	N065-00-1/451	Tenancy - Station Building - Woodside Park Stn	Roofing Tiles	Asbestos	Surveyed - Not Detected				Roofing Felt to Roof of Tenancy					
9117	ACTIVE	N	N065-00-1/661	Switch Room - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17375	INACTIVE	N	N065-00-1/661	Switch Room - Station Building - Woodside Park Stn	Isolator Switches	Asbestos	Strongly Presumed				Iron Clad Isolators - Insulation Inside Arc chutes have been replaced in box serial no 00185829, leave 8no containing asbestos;		8		N	N
17377	ACTIVE	N	N065-00-1/661	Switch Room - Station Building - Woodside Park Stn	Cable Duct: Other	Asbestos	Presumed				Cable Ducts					
42689	INACTIVE	N	N065-00-1/661	Switch Room - Station Building - Woodside Park Stn	Cable Duct: Other	Asbestos	Presumed				W2 2 X 60				N	N
42687	INACTIVE	N	N065-00-1/661	Switch Room - Station Building - Woodside Park Stn	Cable Duct: Other	Asbestos	Presumed				Wall 1 3 x 60				N	N
17378	ACTIVE	N	N065-00-1/661	Switch Room - Station Building - Woodside Park Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Gloss Paint. Thickness 0.36mm : Analysis 5.24%				N	N



# Hazardous Material Asset Register - Summary



## N065-00 - Station Building - Woodside Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17376	ACTIVE	N	N065-00-1/661/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Woodside Park Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Fibreboard					
19109	ACTIVE	N	N065-00-1/661/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Woodside Park Stn	Void	Asbestos	No Access: Presumed				Above Fibreboard				YES	
42688	ACTIVE	N	N065-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Woodside Park Stn	Isolator Switches	Asbestos	Presumed				Wall 1 4x Isolators presumed to contain asbestos insulating materials within. (1 x 100amps & 3x 60amps)  Arc chutes have been replaced in box serial no 00185829, leaving 8no containing asbestos; Unknown which wall this box is on		4		N	N
42690	ACTIVE	N	N065-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Woodside Park Stn	Isolator Switches	Asbestos	Presumed				Wall 2 - 3x Isolators presumed to contain asbestos insulating materials within. (1x 100amps & 2x 60amps)  Arc chutes have been replaced in box serial no 00185829, leaving 8no containing asbestos; Unknown which wall this box is on		3		N	N
42691	ACTIVE	N	N065-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Woodside Park Stn	Other Electrical Boxes	Asbestos	Presumed				Wall 2 x Transformer box presumed to contain asbestos insulating materials within.		1		N	N
42693	ACTIVE	N	N065-00-1/661/WAL-005	Wall: Internal - 5 - Switch Room - Station Building - Woodside Park Stn	Other Electrical Boxes	Asbestos	Presumed				Wall 5 - 3x Transformer boxes presumed asbestos insulating materials within		3		N	N
42692	ACTIVE	N	N065-00-1/661/WAL-005	Wall: Internal - 5 - Switch Room - Station Building - Woodside Park Stn	Isolator Switches	Asbestos	Presumed				Wall 5 - 1x 30amp Isolator. Presumed asbestos insulating materials within.  Arc chutes have been replaced in box serial no 00185829, leaving 8no containing asbestos; Unknown which wall this box is on		1		N	N
9118	ACTIVE	N	N065-00-1/732	CER - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17381	ACTIVE	N	N065-00-1/732/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Woodside Park Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling				YES	
17380	ACTIVE	N	N065-00-1/732/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Woodside Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
17379	ACTIVE	N	N065-00-1/732/FLR-01	Floor - 1 - CER - Station Building - Woodside Park Stn	Void	Asbestos	No Access: Presumed				Beneath Rubber Tiles					YES
9119	ACTIVE	N	N065-00-1/746	SCR - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17994	ACTIVE	N	N065-00-1/746	SCR - Station Building - Woodside Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N065-00 - Station Building - Woodside Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9120	ACTIVE	N	N065-00-1/901	Disused Room - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19110	ACTIVE	N	N065-00-1/901/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Woodside Park Stn	Void	Asbestos	No Access: Presumed				Above Wood, Corrugated Steel				YES	
9121	ACTIVE	N	N065-00-1/951	Disused Room - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17382	ACTIVE	N	N065-00-1/951/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Woodside Park Stn	Void	Asbestos	No Access: Presumed				Above Concrete, Fibreboard				YES	
9122	ACTIVE	N	N065-00-2/951	Disused Room - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17383	ACTIVE	N	N065-00-2/951	Disused Room - Station Building - Woodside Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9123	ACTIVE	N	N065-00-A/601	Stairs: Linear - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17384	ACTIVE	N	N065-00-A/601	Stairs: Linear - Station Building - Woodside Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9124	ACTIVE	N	N065-00-A/602	Stairs: Linear - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17385	ACTIVE	N	N065-00-A/602	Stairs: Linear - Station Building - Woodside Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9125	ACTIVE	N	N065-00-A/603	Stairs: Linear - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19111	ACTIVE	N	N065-00-A/603	Stairs: Linear - Station Building - Woodside Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9126	ACTIVE	N	N065-00-A/604	Stairs: Linear - Station Building - Woodside Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17995	ACTIVE	N	N065-00-A/604	Stairs: Linear - Station Building - Woodside Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
17386	ACTIVE	N	N065-00-A/636	Overbridge - Station Building - Woodside Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N067-00 - Station Building - West Finchley Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9127	ACTIVE	N	N067-00-1/001	Booking Hall - Station Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20139	ACTIVE	N	N067-00-1/001	Booking Hall - Station Building - West Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9128	ACTIVE	N	N067-00-1/011	Ticket Office - Station Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20140	ACTIVE	N	N067-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - West Finchley Stn	Void	Asbestos	No Access: Presumed				Beneath False Floor					YES
9129	ACTIVE	N	N067-00-1/021	POM - Station Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20141	ACTIVE	N	N067-00-1/021/FLR-01	Floor - 1 - POM - Station Building - West Finchley Stn	Void	Asbestos	No Access: Presumed				Beneath False Floor					YES
9130	ACTIVE	N	N067-00-1/031	Mess Room - Station Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19281	ACTIVE	N	N067-00-1/031	Mess Room - Station Building - West Finchley Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
20142	ACTIVE	N	N067-00-1/031	Mess Room - Station Building - West Finchley Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - Insulation Foam Board					
9131	ACTIVE	N	N067-00-1/036	Toilet: Unisex - Station Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20143	ACTIVE	N	N067-00-1/036	Toilet: Unisex - Station Building - West Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9132	ACTIVE	N	N067-00-1/081	Lobby - Station Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20144	ACTIVE	N	N067-00-1/081/FLR-01	Floor - 1 - Lobby - Station Building - West Finchley Stn	Void	Asbestos	No Access: Presumed				Beneath False Floor					YES
9133	ACTIVE	N	N067-00-1/261	Platform 1 - Northbound Fast - Station Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20145	ACTIVE	N	N067-00-1/261	Platform 1 - Northbound Fast - Station Building - West Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9134	ACTIVE	N	N067-00-1/262	Platform 2 - Southbound Fast - Station Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N067-00 - Station Building - West Finchley Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19282	ACTIVE	N	N067-00-1/262	Platform 2 - Southbound Fast - Station Building - West Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9135	ACTIVE	N	N067-00-1/281	Station Supervisor Office - Station Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20147	ACTIVE	N	N067-00-1/281	Station Supervisor Office - Station Building - West Finchley Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing					
20146	ACTIVE	N	N067-00-1/281	Station Supervisor Office - Station Building - West Finchley Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - Insulation Foam Board					
9136	ACTIVE	N	N067-00-1/401	Bin Store - Station Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20195	ACTIVE	N	N067-00-1/401	Bin Store - Station Building - West Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9137	ACTIVE	N	N067-00-1/406	Store - Station Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20196	ACTIVE	N	N067-00-1/406	Store - Station Building - West Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9138	ACTIVE	N	N067-00-1/411	Store - Station Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20197	ACTIVE	N	N067-00-1/411	Store - Station Building - West Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9139	ACTIVE	N	N067-00-1/412	Store - Station Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20198	ACTIVE	N	N067-00-1/412	Store - Station Building - West Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9140	ACTIVE	N	N067-00-1/416	Toilet: Male - Station Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20199	ACTIVE	N	N067-00-1/416	Toilet: Male - Station Building - West Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9141	ACTIVE	N	N067-00-1/426	Toilet: Female - Station Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20200	ACTIVE	N	N067-00-1/426	Toilet: Female - Station Building - West Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N067-00 - Station Building - West Finchley Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9142	ACTIVE	N	N067-00-1/427	Toilet: Male - Station Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20201	ACTIVE	N	N067-00-1/427	Toilet: Male - Station Building - West Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9143	ACTIVE	N	N067-00-1/436	Waiting Room - Station Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20202	ACTIVE	N	N067-00-1/436	Waiting Room - Station Building - West Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9144	ACTIVE	N	N067-00-1/437	Waiting Room - Station Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20203	ACTIVE	N	N067-00-1/437	Waiting Room - Station Building - West Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9145	ACTIVE	N	N067-00-1/551	Yard - Station Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20204	ACTIVE	N	N067-00-1/551	Yard - Station Building - West Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9146	ACTIVE	N	N067-00-1/552	Yard - Station Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20205	ACTIVE	N	N067-00-1/552	Yard - Station Building - West Finchley Stn	Cement Troughing	Asbestos	Removed				Outside Station 800mm long Cable Troughing. This area was re-inspected in 2020 and the troughing could not be found. It is believed to have been removed by the asbestos surveyor					
9147	ACTIVE	N	N067-00-1/661	Switch Room - Station Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20206	ACTIVE	N	N067-00-1/661	Switch Room - Station Building - West Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9148	ACTIVE	N	N067-00-1/731	CER - Station Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20208	ACTIVE	N	N067-00-1/731	CER - Station Building - West Finchley Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing					
20207	ACTIVE	N	N067-00-1/731/FLR-01	Floor - 1 - CER - Station Building - West Finchley Stn	Void	Asbestos	No Access: Presumed				Beneath False Floor					YES
9149	ACTIVE	N	N067-00-1/746	SCR - Station Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N067-00 - Station Building - West Finchley Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20209	ACTIVE	N	N067-00-1/746	SCR - Station Building - West Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9150	ACTIVE	N	N067-00-1/776	Plant Room - Station Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20210	ACTIVE	N	N067-00-1/776	Plant Room - Station Building - West Finchley Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
9151	ACTIVE	N	N067-00-A/601	Stairs: Linear - Station Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19290	ACTIVE	N	N067-00-A/601	Stairs: Linear - Station Building - West Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9152	ACTIVE	N	N067-00-A/602	Stairs: Linear - Station Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20211	ACTIVE	N	N067-00-A/602	Stairs: Linear - Station Building - West Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
20212	ACTIVE	N	N067-00-A/636	Overbridge - Station Building - West Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					

## N068-02 - Depot Building - West Finchley To Finchley Central

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9168	ACTIVE	N	N068-02-1/417	Workshop - Depot Building - West Finchley To Finchley Central	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N071-00 - Station Building - Finchley Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9169	ACTIVE	N	N071-00-1/001	Booking Hall - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24313	ACTIVE	N	N071-00-1/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Finchley Central Stn	Void	Asbestos	Surveyed – Not Detected				Wood above false ceiling				Yes	
24769	ACTIVE	N	N071-00-1/001/CLG-02	Ceiling: Solid - 2 - Booking Hall - Station Building - Finchley Central Stn	Void	Asbestos	Surveyed – Not Detected				Wood above false ceiling				Yes	
24317	ACTIVE	N	N071-00-1/001/FLR-01	Floor - 1 - Booking Hall - Station Building - Finchley Central Stn	Void	Asbestos	No Access: Presumed				Beneath computer flooring					Yes



# Hazardous Material Asset Register - Summary



## N071-00 - Station Building - Finchley Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor	
24848	ACTIVE	N	N071-00-1/001/FLR-02	Floor - 2 - Booking Hall - Station Building - Finchley Central Stn	Void	Asbestos	No Access: Presumed				Beneath computer flooring					Yes	
9170	ACTIVE	N	N071-00-1/011	Ticket Office - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed										
24850	ACTIVE	N	N071-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Finchley Central Stn	Void	Asbestos	Surveyed - Not Detected				Brick, plastic; timber rafters, felt; supalux boarding W2				Yes		
24849	ACTIVE	N	N071-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Finchley Central Stn		Asbestos	Surveyed - Not Detected				Supalux Tiles						
9171	ACTIVE	N	N071-00-1/021	POM - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed										
24853	ACTIVE	N	N071-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Finchley Central Stn	Void	Asbestos	Surveyed - Not Detected				Timber Rafters above false ceiling				Yes		
24852	ACTIVE	N	N071-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Finchley Central Stn		Asbestos	Surveyed - Not Detected				Supalux						
24851	ACTIVE	N	N071-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Finchley Central Stn	Void	Asbestos	Surveyed - Not Detected				PVC Cable, Metal Cable Tray beneath Tiles, Computer Flooring					Yes	
9172	ACTIVE	N	N071-00-1/031	Mess Room - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed										
24855	ACTIVE	N	N071-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Finchley Central Stn	Void	Asbestos	Surveyed - Not Detected				Timber Rafters, Conduit, Felt, Supalux Board above false ceiling				Yes		
24854	ACTIVE	N	N071-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Finchley Central Stn		Asbestos	Surveyed - Not Detected				Supalux Tiles						
9173	ACTIVE	N	N071-00-1/036	Toilet: Unisex - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed										
24856	ACTIVE	N	N071-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Finchley Central Stn		Asbestos	Surveyed - Not Detected				Supalux Tiles						
24857	ACTIVE	N	N071-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Finchley Central Stn	Void	Asbestos	Surveyed - Not Detected				Timber Rafters, Brick, Block, Rock Wool Pipe Lagging, Copper Pipe above false ceiling				Yes		
9174	ACTIVE	N	N071-00-1/081	Lobby - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed										



# Hazardous Material Asset Register - Summary



## N071-00 - Station Building - Finchley Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24858	ACTIVE	N	N071-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Finchley Central Stn	Void	Asbestos	No Access: Presumed				Walls, Brick, Plaster above false ceiling				Yes	
9175	ACTIVE	N	N071-00-1/082	Lobby - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
24859	ACTIVE	N	N071-00-1/082	Lobby - Station Building - Finchley Central Stn	No Access	Asbestos	Surveyed - Not Detected				Lift Shaft - Not Surveyed - New					
24860	ACTIVE	N	N071-00-1/136	Lift Shaft - Station Building - Finchley Central Stn	No Access	Asbestos	Surveyed - Not Detected				Lift Shaft - Not Surveyed - New					
24861	ACTIVE	N	N071-00-1/137	Lift Shaft - Station Building - Finchley Central Stn	No Access	Asbestos	Surveyed - Not Detected				Lift Shaft - Not Surveyed - New					
9176	ACTIVE	N	N071-00-1/236	Passage - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
24862	ACTIVE	N	N071-00-1/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Finchley Central Stn		Asbestos	Surveyed - Not Detected				Supalux Tiles					
24863	ACTIVE	N	N071-00-1/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Finchley Central Stn	Void	Asbestos	Surveyed - Not Detected				Timber rafters above false ceiling				Yes	
25473	ACTIVE	N	N071-00-1/236/FLR-01	Floor - 1 - Passage - Station Building - Finchley Central Stn	Void	Asbestos	No Access: Presumed				Beneath computer flooring					Yes
9177	ACTIVE	N	N071-00-1/291	Office - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
24864	ACTIVE	N	N071-00-1/291	Office - Station Building - Finchley Central Stn	LUL Heaters	Asbestos	Surveyed - Not Detected				Heater - white foam insulation		1			
24865	ACTIVE	N	N071-00-1/291/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Finchley Central Stn	Void	Asbestos	Surveyed - Not Detected				Plasterboard, Walls Brick, Plaster; Air Con, PVC Cables, Conduit above false ceiling				Yes	
9178	ACTIVE	N	N071-00-1/301	GSM Office - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
24866	ACTIVE	N	N071-00-1/301/CLG-01	Ceiling: Solid - 1 - GSM Office - Station Building - Finchley Central Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard					
25474	ACTIVE	N	N071-00-1/301/CLG-01	Ceiling: Solid - 1 - GSM Office - Station Building - Finchley Central Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard				Yes	
9179	ACTIVE	N	N071-00-1/351	Mess Room - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N071-00 - Station Building - Finchley Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24868	ACTIVE	N	N071-00-1/351	Mess Room - Station Building - Finchley Central Stn	Bitumen	Asbestos	Surveyed – Not Detected				Acoustic Panel under Sink		1			
24867	ACTIVE	N	N071-00-1/351/FLR-01	Floor - 1 - Mess Room - Station Building - Finchley Central Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl Flooring					
9180	ACTIVE	N	N071-00-1/411	Store - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24417	ACTIVE	N	N071-00-1/411/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Finchley Central Stn	Void	Asbestos	Surveyed – Not Detected				Timber joints above false ceiling				Yes	
24869	ACTIVE	N	N071-00-1/411/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Finchley Central Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
9181	ACTIVE	N	N071-00-1/412	Store - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25475	ACTIVE	N	N071-00-1/412/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Finchley Central Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
24870	ACTIVE	N	N071-00-1/412/FLR-01	Floor - 1 - Store - Station Building - Finchley Central Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl Flooring					
9182	ACTIVE	N	N071-00-1/416	Toilet: Unisex - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24871	ACTIVE	N	N071-00-1/416/FLR-01	Floor - 1 - Toilet - Station Building - Finchley Central Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl Flooring					
9183	ACTIVE	N	N071-00-1/601	Stairs: Linear - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24872	ACTIVE	N	N071-00-1/601/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Finchley Central Stn	Void	Asbestos	No Access: Presumed				Above Metal Roof Sheets, Metal Boxing				Yes	
9184	ACTIVE	N	N071-00-1/602	Stairs: Linear - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24873	ACTIVE	N	N071-00-1/602/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Finchley Central Stn	Void	Asbestos	No Access: Presumed				Above Metal Roof Sheets				Yes	
24955	ACTIVE	N	N071-00-1/636	Overbridge - Station Building - Finchley Central Stn	Lead/Leading	Lead Paint/Lead	Known				Blue/Grey Oil Based Paint - Side Exterior Steel Work. Thickness 1.75mm: Analysis 11.1%				N	N
24419	ACTIVE	N	N071-00-1/636	Overbridge - Station Building - Finchley Central Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Oil Based Paint - Support Struts. Thickness 1.04mm: Analysis 7.5%				N	N



# Hazardous Material Asset Register - Summary



## N071-00 - Station Building - Finchley Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24320	ACTIVE	N	N071-00-1/636	Overbridge - Station Building - Finchley Central Stn	Lead/Leading	Lead Paint/Lead	Known				Walls - Green Oil Based Paint. Thickness 1.24mm: Analysis 8.4%				N	N
24954	ACTIVE	N	N071-00-1/636/CLG-01	Ceiling: Solid - 1 - Overbridge - Station Building - Finchley Central Stn	Void	Asbestos	No Access: Presumed				Above Metal Roof Sheets				Yes	
24874	ACTIVE	N	N071-00-1/636/FLR-01	Floor - 1 - Overbridge - Station Building - Finchley Central Stn	Void	Asbestos	No Access: Presumed				Beneath Timber Decking					Yes
9185	ACTIVE	N	N071-00-1/661	Switch Cupboard - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
24956	ACTIVE	N	N071-00-1/661	Switch Cupboard - Station Building - Finchley Central Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
44896	ACTIVE	N	N071-00-1/667	Switch - Station Building - Finchley Central Stn	Cable Duct: Other	Asbestos	Presumed				Cable ducting 1m below ground running from 1/667 switch room to cable pit within hard standing in front of gas locker 1/636				N	N
9186	ACTIVE	N	N071-00-2/081	Lobby - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
24960	ACTIVE	N	N071-00-2/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Finchley Central Stn	Void	Asbestos	Surveyed - Not Detected				Brickwork Arch above false ceiling				Yes	
24959	ACTIVE	N	N071-00-2/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Finchley Central Stn		Asbestos	Surveyed - Not Detected				Supalux Tiles					
9187	ACTIVE	N	N071-00-2/082	Lobby - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
9188	ACTIVE	N	N071-00-2/083	Lobby - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
24961	ACTIVE	N	N071-00-2/083	Lobby - Station Building - Finchley Central Stn		Asbestos	Surveyed - Not Detected				Supalux Cupboard					
9189	ACTIVE	N	N071-00-2/084	Lobby - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
24962	ACTIVE	N	N071-00-2/084	Lobby - Station Building - Finchley Central Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
9190	ACTIVE	N	N071-00-2/131	LMR - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
24963	ACTIVE	N	N071-00-2/131	LMR - Station Building - Finchley Central Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New					



# Hazardous Material Asset Register - Summary



## N071-00 - Station Building - Finchley Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9191	ACTIVE	N	N071-00-2/132	LMR - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24964	ACTIVE	N	N071-00-2/132	LMR - Station Building - Finchley Central Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New					
9192	ACTIVE	N	N071-00-2/261	Platform 1 - Northbound Main - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24966	ACTIVE	N	N071-00-2/261	Platform 1 - Northbound Main - Station Building - Finchley Central Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Southbound end - Main Distribution Framework - Insulation within				N	N
24968	ACTIVE	N	N071-00-2/261	Platform 1 - Northbound Main - Station Building - Finchley Central Stn	Lead/Leading	Lead Paint/Lead	Known				4 x Support Struts to Stairs. Thickness 0.62mm: Analysis 7.9%				N	N
24967	ACTIVE	N	N071-00-2/261	Platform 1 - Northbound Main - Station Building - Finchley Central Stn	Lead/Leading	Lead Paint/Lead	Known				Main Support to Overbridge Cream Oil Based Paint. Thickness 0.30mm: Analysis 4.6%				N	N
24965	ACTIVE	N	N071-00-2/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Finchley Central Stn	Void	Asbestos	No Access: Presumed				Above Wood Tongue & Groove				Yes	
9193	ACTIVE	N	N071-00-2/262	Platform 2 - Northbound Fast - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24970	ACTIVE	N	N071-00-2/262	Platform 2 - Northbound Fast - Station Building - Finchley Central Stn	Lead/Leading	Lead Paint/Lead	Known				4 x Support Struts to Stairs Cream Oil Based Paint. Thickness 0.62mm: Analysis 7.9%				N	N
25484	ACTIVE	N	N071-00-2/262	Platform 2 - Northbound Fast - Station Building - Finchley Central Stn	Lead/Leading	Lead Paint/Lead	Known				Main Support to Overbridge Cream Oil Based Paint. Thickness 0.30mm: Analysis 4.6%				N	N
24969	ACTIVE	N	N071-00-2/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - Finchley Central Stn	Void	Asbestos	No Access: Presumed				Above Metal Roofing Sheets				Yes	
9194	ACTIVE	N	N071-00-2/263	Platform 3 - Southbound Fast - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24973	ACTIVE	N	N071-00-2/263	Platform 3 - Southbound Fast - Station Building - Finchley Central Stn	Debris: Cement	Asbestos	Removed				Embankment behind Platform 3 - Chrysotile Cement debris (1-2m <sup>2</sup> ) The troughing above was removed by the LARC Pectel. This area was re-inspected and there was no visible surface troughing present.					
24971	ACTIVE	N	N071-00-2/263/CLG-01	Ceiling: Solid - 1 - Platform 3 - Station Building - Finchley Central Stn	Void	Asbestos	No Access: Presumed				Above Metal Roofing Sheets				Yes	
9195	ACTIVE	N	N071-00-2/281	Mess Room - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N071-00 - Station Building - Finchley Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25485	ACTIVE	N	N071-00-2/281/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Finchley Central Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
24974	ACTIVE	N	N071-00-2/281/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Finchley Central Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard, Walls Brick, Concrete, PVC All Cables, Rock Wool Pipe Lagging above false ceiling				Yes	
9196	ACTIVE	N	N071-00-2/316	Locker Room - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24975	ACTIVE	N	N071-00-2/316/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Finchley Central Stn	Void	Asbestos	Surveyed – Not Detected				Brickwork Arches, Conduit, PVC Cables above false ceiling				Yes	
9197	ACTIVE	N	N071-00-2/317	Locker Room - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24977	ACTIVE	N	N071-00-2/317/CLG-01	Ceiling: Solid - 1 - Locker Room - Station Building - Finchley Central Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
24976	ACTIVE	N	N071-00-2/317/FLR-01	Floor - 1 - Locker Room - Station Building - Finchley Central Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino, Concrete Brick					
9198	ACTIVE	N	N071-00-2/341	Mess Room - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25486	ACTIVE	N	N071-00-2/341/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Finchley Central Stn		Asbestos	Surveyed – Not Detected				Supalux Tiles					
24978	ACTIVE	N	N071-00-2/341/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Finchley Central Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard, Walls Brick, Concrete, PVC All Cables, Rock Wool Pipe Lagging above false ceiling				Yes	
9199	ACTIVE	N	N071-00-2/411	Store - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24979	ACTIVE	N	N071-00-2/411	Store - Station Building - Finchley Central Stn		Asbestos	Surveyed – Not Detected				Wall - Supalux Panel by Window					
9200	ACTIVE	N	N071-00-2/412	Store - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9201	ACTIVE	N	N071-00-2/413	Store - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46438	ACTIVE	N	N071-00-2/413	Store - Station Building - Finchley Central Stn	Mastic	Asbestos	Sampled – Not Detected				Mastic between sill and frame (small window), Platform Level			R670351	N	N



# Hazardous Material Asset Register - Summary



## N071-00 - Station Building - Finchley Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46439	ACTIVE	N	N071-00-2/413	Store - Station Building - Finchley Central Stn	Mastic	Asbestos	Sampled – Not Detected				Mastic to frame (small window), Platform Level			R670351	N	N
46437	ACTIVE	N	N071-00-2/413	Store - Station Building - Finchley Central Stn	Mastic	Asbestos	Sampled – Not Detected				Putty/mastic to (large) window frame and glass, Platform Level			R670351	N	N
46440	ACTIVE	N	N071-00-2/413	Store - Station Building - Finchley Central Stn	Plaster	Asbestos	Sampled – Not Detected				Plaster to walls around windows, Platform Level			R670351	N	N
46436	ACTIVE	N	N071-00-2/413	Store - Station Building - Finchley Central Stn	Mastic	Asbestos	Sampled – Not Detected				Putty/mastic to (large) window frame (nearest window), Platform Level			R670351	N	N
46435	ACTIVE	N	N071-00-2/413	Store - Station Building - Finchley Central Stn	Mastic	Asbestos	Sampled – Not Detected				Putty/mastic to (large) window frame, Platform Level			R670351	N	N
9202	ACTIVE	N	N071-00-2/414	Store - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9203	ACTIVE	N	N071-00-2/416	Toilet: Female - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24980	ACTIVE	N	N071-00-2/416	Toilet: Female - Station Building - Finchley Central Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - white foam backing		1			
9204	ACTIVE	N	N071-00-2/417	Toilet: Male - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24981	ACTIVE	N	N071-00-2/417	Toilet: Male - Station Building - Finchley Central Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - white foam backing		1			
9205	ACTIVE	N	N071-00-2/426	Toilet: Unisex - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9206	ACTIVE	N	N071-00-2/427	Toilet: Unisex - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
24982	ACTIVE	N	N071-00-2/427/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Finchley Central Stn	Void	Asbestos	Surveyed – Not Detected				Pipe lagging above plaster; hatch - wooden rafters				Yes	
9207	ACTIVE	N	N071-00-2/436	Waiting Room - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25061	ACTIVE	N	N071-00-2/436	Waiting Room - Station Building - Finchley Central Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - white foam backing		1			
25060	ACTIVE	N	N071-00-2/436/FLR-01	Floor - 1 - Waiting Room - Station Building - Finchley Central Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl flooring					
9208	ACTIVE	N	N071-00-2/437	Waiting Room - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N071-00 - Station Building - Finchley Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25062	ACTIVE	N	N071-00-2/437/FLR-01	Floor - 1 - Waiting Room - Station Building - Finchley Central Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl flooring					
9209	ACTIVE	N	N071-00-2/438	Waiting Room - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25063	ACTIVE	N	N071-00-2/438	Waiting Room - Station Building - Finchley Central Stn	LUL Heaters	Asbestos	Presumed				Old Heater by Door		1		N	N
9210	ACTIVE	N	N071-00-2/661	Switch Room - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25064	ACTIVE	N	N071-00-2/661	Switch Room - Station Building - Finchley Central Stn		Asbestos	Surveyed – Not Detected				Supalux Cladding					
25065	ACTIVE	N	N071-00-2/661/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Finchley Central Stn		Asbestos	Surveyed – Not Detected				Supalux Boarding					
25066	ACTIVE	N	N071-00-2/661/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Finchley Central Stn	Void	Asbestos	No Access: Presumed				Above false floor				Yes	
25067	ACTIVE	N	N071-00-2/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Finchley Central Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch box x 1 - 30 amp, W1. Presumed asbestos insulating materials within.		1		N	N
42700	ACTIVE	N	N071-00-2/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Finchley Central Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Wall 2 - 1 x Transformer Box presumed to contain asbestos insulating materials within		1		N	N
46184	ACTIVE	N	N071-00-2/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Finchley Central Stn	Other Electrical Boxes	Asbestos	Presumed				3x Transformer boxes. Presumed asbestos insulation materials within.		3			
25068	ACTIVE	N	N071-00-2/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Finchley Central Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch boxes x 8 - 5 x 60amp, 2 x 100 amp, 1 x 200amp. Presumed insulating materials within.		8		N	N
9211	ACTIVE	N	N071-00-2/662	Switch Room - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25069	ACTIVE	N	N071-00-2/662	Switch Room - Station Building - Finchley Central Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - white foam backing		1			
25070	ACTIVE	N	N071-00-2/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Finchley Central Stn	Other Electrical Boxes	Asbestos	Presumed				1x Transformer boxes - presumed asbestos within (1x modern transformer is adjacent to old transformer.		2		N	N
42701	ACTIVE	N	N071-00-2/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Finchley Central Stn	LUL Heaters	Asbestos	Strongly Presumed				HEATER ON w2 Presumed asbestos panel behind heater.		1			



# Hazardous Material Asset Register - Summary



## N071-00 - Station Building - Finchley Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
24323	ACTIVE	N	N071-00-2/662/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Finchley Central Stn	Isolator Switches	Asbestos	Strongly Presumed				5x Switch boxes 1 x 30 amps, 3 x 60 amps, 1 x 100 amps. Presumed asbestos insulating materials within		5		N	N
9212	ACTIVE	N	N071-00-2/666	Switch Cupboard - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
25071	ACTIVE	N	N071-00-2/666	Switch Cupboard - Station Building - Finchley Central Stn	Isolator Switches	Asbestos	Strongly Presumed				1x Switch Box 60amps. Presumed asbestos insulating materials within.		1		N	N
9213	ACTIVE	N	N071-00-2/667	Switch Cupboard - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
25072	ACTIVE	N	N071-00-2/667	Switch Cupboard - Station Building - Finchley Central Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New					
9214	ACTIVE	N	N071-00-2/731	CER - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
9215	ACTIVE	N	N071-00-2/746	SCR - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
9216	ACTIVE	N	N071-00-2/776	Store - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
25574	ACTIVE	N	N071-00-2/776	Store - Station Building - Finchley Central Stn	LUL Heaters	Asbestos	Surveyed - Not Detected				LTB Heater - No Asbestos Detected (Foam)		1			
25075	ACTIVE	N	N071-00-2/776/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Finchley Central Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard					
25076	ACTIVE	N	N071-00-2/776/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Finchley Central Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
9217	ACTIVE	N	N071-00-2/801	Meeting Room - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
25575	ACTIVE	N	N071-00-2/801/CLG-01	Ceiling: Solid - 1 - Meeting Room - Station Building - Finchley Central Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
25077	ACTIVE	N	N071-00-2/801/CLG-01	Ceiling: Solid - 1 - Meeting Room - Station Building - Finchley Central Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard					
9218	ACTIVE	N	N071-00-2/901	Store - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N071-00 - Station Building - Finchley Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44897	ACTIVE	N	N071-00-2/901/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Finchley Central Stn	Cement Cowlings/Flues	Asbestos	Strongly Presumed				Flue coming from 2/417 toilet and onto Roof				Y	N
25078	ACTIVE	N	N071-00-2/901/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Finchley Central Stn	Cement Cowlings/Flues	Asbestos	Strongly Presumed				Flue coming from 2/417 toilet out of wall		1		N	N
9219	ACTIVE	N	N071-00-2/902	Store - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
25079	ACTIVE	N	N071-00-2/902	Store - Station Building - Finchley Central Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New					
9220	ACTIVE	N	N071-00-2/903	Store - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
25080	ACTIVE	N	N071-00-2/903	Store - Station Building - Finchley Central Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New					
9221	ACTIVE	N	N071-00-2/951	Office - Station Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
25082	ACTIVE	N	N071-00-2/951	Office - Station Building - Finchley Central Stn	Bitumen	Asbestos	Surveyed - Not Detected				Acoustic Panel under Sink		1			
46214	ACTIVE	N	N071-00-2/951	Office - Station Building - Finchley Central Stn	Cement Cowlings/Flues	Asbestos	Presumed				Cement Cows on top of roof 2/951. No access to sample		4			
25576	ACTIVE	N	N071-00-2/951/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Finchley Central Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				Yes	
25081	ACTIVE	N	N071-00-2/951/FLR-01	Floor - 1 - Office - Station Building - Finchley Central Stn	Void	Asbestos	Surveyed - Not Detected				Quarry Tiles beneath Carpet Tiles					Yes

## N072-01 - Signals Building - Finchley Central To East Finchley

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9225	ACTIVE	N	N072-01-2/732	CER - Signals Building - Finchley Central To East Finchley	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									

## N073-00 - Station Building - East Finchley Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9235	ACTIVE	N	N073-00-1/001	Booking Hall - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N073-00 - Station Building - East Finchley Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17915	ACTIVE	N	N073-00-1/001	Booking Hall - Station Building - East Finchley Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Horizontal Supalux Board above Tenancy & Boswick Gates Housing (Entrance A)					
20256	ACTIVE	N	N073-00-1/001/BAT-001	Battery: Mimic Control Panel - Booking Hall - Station Building - East Finchley Stn	Cement Cowlings/Flues	Asbestos	Known				Cement Cowlings on Roof - Staff Offices - South Corner of Building				N	N
9236	ACTIVE	N	N073-00-1/011	Ticket Office - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17190	ACTIVE	N	N073-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - East Finchley Stn	Void	Asbestos	Surveyed – Not Detected				Fibre glass lagged pipes plastic cable; Concrete ceiling galvanised tray works above false ceiling				YES	
18873	ACTIVE	N	N073-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - East Finchley Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
17189	ACTIVE	N	N073-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - East Finchley Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Plastic Cables; Metal ducts beneath Computer flooring					YES
9237	ACTIVE	N	N073-00-1/021	POM - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17191	ACTIVE	N	N073-00-1/021/FLR-01	Floor - 1 - POM - Station Building - East Finchley Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Plastic cables, Supalux firebreak to ticket machines, galvanised duct; No access beyond Supalux firebreak under ticket machine beneath Computer flooring					YES
9238	ACTIVE	N	N073-00-1/081	Lobby - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18874	ACTIVE	N	N073-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - East Finchley Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
17194	ACTIVE	N	N073-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - East Finchley Stn	Void	Asbestos	Surveyed – Not Detected				Cast iron soil pipe, fibreglass pipe insulation plastic cables, metal vent ducts above false ceiling				YES	
17192	ACTIVE	N	N073-00-1/081/FLR-01	Floor - 1 - Lobby - Station Building - East Finchley Stn	Void	Asbestos	Surveyed – Not Detected				Metal duct work beneath Solid tiled to Rear; Computer tiles to front; Concrete, plastic cable					YES
17193	ACTIVE	N	N073-00-1/081/FLR-02	Floor - 2 - Lobby - Station Building - East Finchley Stn	Void	Asbestos	Surveyed – Not Detected				Metal duct work beneath Solid tiled to Rear; Computer tiles to front; Concrete, plastic cable					YES
9239	ACTIVE	N	N073-00-1/201	Passage - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17916	ACTIVE	N	N073-00-1/201	Passage - Station Building - East Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N073-00 - Station Building - East Finchley Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9240	ACTIVE	N	N073-00-1/202	Passage - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17195	ACTIVE	N	N073-00-1/202	Passage - Station Building - East Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
18985	ACTIVE	N	N073-00-1/202	Passage - Station Building - East Finchley Stn	Lead/Leading	Lead Paint/Lead	Known				Bostwick Gate - Brown Matt Paint. Thickness 0.16mm: Analysis 1.96%				N	N
9241	ACTIVE	N	N073-00-1/236	Passage - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17196	ACTIVE	N	N073-00-1/236	Passage - Station Building - East Finchley Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Superlux Panels above Electrical Equipment High Level					
9242	ACTIVE	N	N073-00-1/237	Passage - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17197	ACTIVE	N	N073-00-1/237/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - East Finchley Stn	Void	Asbestos	Surveyed – Not Detected				Cast iron soil pipes, fibre glass insulation on pipes, steel conduit, plastic cables; walls brick; concrete above false ceiling				YES	
18875	ACTIVE	N	N073-00-1/237/FLR-01	Floor - 1 - Passage - Station Building - East Finchley Stn	Void	Asbestos	Surveyed – Not Detected				Cable pits, plastic/lead cables, Terracotta ducts beneath false floor					YES
9243	ACTIVE	N	N073-00-1/281	Station Control Room - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17198	ACTIVE	N	N073-00-1/281	Station Control Room - Station Building - East Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9244	ACTIVE	N	N073-00-1/311	Mess Room - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17199	ACTIVE	N	N073-00-1/311/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - East Finchley Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Ceiling Tiles					
9245	ACTIVE	N	N073-00-1/316	Locker Room - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19410	ACTIVE	N	N073-00-1/316	Locker Room - Station Building - East Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9246	ACTIVE	N	N073-00-1/317	Locker Room - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17200	ACTIVE	N	N073-00-1/317/CLG-01	Ceiling: Solid - 1 - Locker Room - Station Building - East Finchley Stn	No Access	Asbestos	No Access: Presumed				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N073-00 - Station Building - East Finchley Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9247	ACTIVE	N	N073-00-1/332	Mess Room - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17201	ACTIVE	N	N073-00-1/332/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - East Finchley Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Ceiling Tiles					
17202	ACTIVE	N	N073-00-1/332/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - East Finchley Stn	Void	Asbestos	Surveyed - Not Detected				Fibreboard Residue No Asbestos Detected; Concrete above false ceiling				YES	
18876	ACTIVE	N	N073-00-1/332/DOR-01	Door - 1 - Mess Room - Station Building - East Finchley Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Panel on Door					
9248	ACTIVE	N	N073-00-1/333	Office - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18986	ACTIVE	N	N073-00-1/333/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - East Finchley Stn	Void	Asbestos	Surveyed - Not Detected				Solid above false ceiling				YES	
17203	ACTIVE	N	N073-00-1/333/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - East Finchley Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Fibreboard					
9249	ACTIVE	N	N073-00-1/416	Toilet: Unisex - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17204	ACTIVE	N	N073-00-1/416	Toilet: Unisex - Station Building - East Finchley Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9250	ACTIVE	N	N073-00-1/417	Toilet: Unisex - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17205	ACTIVE	N	N073-00-1/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - East Finchley Stn	Void	Asbestos	Surveyed - Not Detected				Fibre glass lagged pipe plastic cables metal CMS; Plaster on Solid above false ceiling				YES	
18877	ACTIVE	N	N073-00-1/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - East Finchley Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux					
9251	ACTIVE	N	N073-00-1/451	Tenancy - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17206	ACTIVE	N	N073-00-1/451	Tenancy - Station Building - East Finchley Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - Tenancy					
9252	ACTIVE	N	N073-00-1/452	Tenancy - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17207	ACTIVE	N	N073-00-1/452	Tenancy - Station Building - East Finchley Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - Tenancy					



# Hazardous Material Asset Register - Summary



## N073-00 - Station Building - East Finchley Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9253	ACTIVE	N	N073-00-1/453	Locker Room - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17917	ACTIVE	N	N073-00-1/453/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - East Finchley Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false friends				YES	
9254	ACTIVE	N	N073-00-1/455	Tenancy - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17208	ACTIVE	N	N073-00-1/455/WAL-001	Wall: Internal - 1 - Tenancy - Station Building - East Finchley Stn	Isolator Switches	Asbestos	Strongly Presumed				Isolators. Presumed asbestos insulating materials within		2		N	N
9255	ACTIVE	N	N073-00-1/661	Switch Cupboard - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18488	ACTIVE	N	N073-00-1/661	Switch Cupboard - Station Building - East Finchley Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch boxes (4 x 60 amps, 2 x 200 amps) Presumed asbestos insulating materials within		6		N	N
9256	ACTIVE	N	N073-00-1/662	Switch Room - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17209	ACTIVE	N	N073-00-1/662	Switch Room - Station Building - East Finchley Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch boxes (7 x 100 amps, 1 x 30 amps, 5 x 60 amps, 1 x 200 amps, 1 x 30 amps) Presumed asbestos insulating materials within		14		N	N
18940	ACTIVE	N	N073-00-1/662	Switch Room - Station Building - East Finchley Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Transformer Box(es) Presumed asbestos insulating materials within		4		N	N
9257	ACTIVE	N	N073-00-1/663	Switch Cupboard - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17210	ACTIVE	N	N073-00-1/663	Switch Cupboard - Station Building - East Finchley Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes (3 x 100 amps, 1 x 300 amps, 1 x 200 amps) Presumed asbestos insulating materials within		5		N	N
9258	ACTIVE	N	N073-00-1/746	SCR - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17211	ACTIVE	N	N073-00-1/746	SCR - Station Building - East Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9259	ACTIVE	N	N073-00-1/786	Service Riser - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18941	ACTIVE	N	N073-00-1/786	Service Riser - Station Building - East Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9260	ACTIVE	N	N073-00-1/801	Office - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N073-00 - Station Building - East Finchley Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17214	ACTIVE	N	N073-00-1/801/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - East Finchley Stn	Void	Asbestos	Surveyed – Not Detected				Solid plaster ceiling; Fibre glass lagged pipe above Fibreboard Tile		1		YES	
17213	ACTIVE	N	N073-00-1/801/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - East Finchley Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Fibreboard					
17212	ACTIVE	N	N073-00-1/801/WAL-001	Wall: Internal - 1 - Office - Station Building - East Finchley Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Doorway blocked off with plasterboard		1			
9261	ACTIVE	N	N073-00-A/236	Passage - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18942	ACTIVE	N	N073-00-A/236/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - East Finchley Stn	Void	Asbestos	Surveyed – Not Detected				Brick Walls; Concrete; Much Cardboard Debris and Boxes above Render on Mesh		1		YES	
9262	ACTIVE	N	N073-00-A/261	Platform 1 - Northbound Fast - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18215	INACTIVE	N	N073-00-A/261	Platform 1 - Northbound Fast - Station Building - East Finchley Stn	Westing house Boxes	Asbestos	Strongly Presumed				By 17B points - Westinghouse Boxes x 10		10		N	N
17218	ACTIVE	N	N073-00-A/261	Platform 1 - Northbound Fast - Station Building - East Finchley Stn	Lead/Leading	Lead Paint/Lead	Known				Seating Area Window Frames - White Matt Paint. Thickness 0.36mm: Analysis 5.03%				N	N
17219	ACTIVE	N	N073-00-A/261	Platform 1 - Northbound Fast - Station Building - East Finchley Stn	Lead/Leading	Lead Paint/Lead	Known				HL Window Frames furthest from building - Light Green Paint Analysis 10.20%					
17220	ACTIVE	N	N073-00-A/261	Platform 1 - Northbound Fast - Station Building - East Finchley Stn	Lead/Leading	Lead Paint/Lead	Known				HL Window Frames closest to building - Light Green Paint Analysis 13.00%				N	N
9263	ACTIVE	N	N073-00-A/262	Platform 2 - Northbound Local - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
54088	ACTIVE	N	N073-00-A/262	Platform 2 - Northbound Local - Station Building - East Finchley Stn		Asbestos	Strongly Presumed				Cement pipe behind barrier gate		1			
18943	ACTIVE	N	N073-00-A/262	Platform 2 - Northbound Local - Station Building - East Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
17222	ACTIVE	N	N073-00-A/262	Platform 2 - Northbound Local - Station Building - East Finchley Stn	Lead/Leading	Lead Paint/Lead	Known				HL Window Frames closest to building - Light Green Paint Analysis 13.00%				N	N
18987	ACTIVE	N	N073-00-A/262	Platform 2 - Northbound Local - Station Building - East Finchley Stn	Lead/Leading	Lead Paint/Lead	Known				HL Window Frames furthest from Building - Light Green Paint. Analysis 10.20%				N	N



# Hazardous Material Asset Register - Summary



## N073-00 - Station Building - East Finchley Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17221	ACTIVE	N	N073-00-A/262	Platform 2 - Northbound Local - Station Building - East Finchley Stn	Lead/Leading	Lead Paint/Lead	Known				Seating Area Window Frames - White Matt Paint. Thickness 0.36mm: Analysis 5.03%				N	N
9264	ACTIVE	N	N073-00-A/263	Platform 3 - Southbound Local - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17223	ACTIVE	N	N073-00-A/263	Platform 3 - Southbound Local - Station Building - East Finchley Stn	Lead/Leading	Lead Paint/Lead	Known				HL Window Frames closest to building - Light Green Paint Analysis 21%				N	N
17224	ACTIVE	N	N073-00-A/263	Platform 3 - Southbound Local - Station Building - East Finchley Stn	Lead/Leading	Lead Paint/Lead	Known				Seating Area Window Frames - White Matt Paint. Thickness 0.36mm: Analysis 5.03%				N	N
18944	ACTIVE	N	N073-00-A/263/ FLR-01	Floor - 1 - Platform 3 - Station Building - East Finchley Stn	Void	Asbestos	Surveyed - Not Detected				Hatch in Floor no asbestos detected beneath false floor					YES
9265	ACTIVE	N	N073-00-A/264	Platform 4 - Southbound Fast - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17226	ACTIVE	N	N073-00-A/264	Platform 4 - Southbound Fast - Station Building - East Finchley Stn	Lead/Leading	Lead Paint/Lead	Known				Seating Area Window Frames - White Matt Paint. Thickness 0.36mm: Analysis 5.03%				N	N
17918	ACTIVE	N	N073-00-A/264	Platform 4 - Southbound Fast - Station Building - East Finchley Stn	Lead/Leading	Lead Paint/Lead	Known				HL Window Frames closest to building - Light Green Paint Analysis 21%				N	N
17225	ACTIVE	N	N073-00-A/264/ FLR-01	Floor - 1 - Platform 4 - Station Building - East Finchley Stn	Void	Asbestos	Surveyed - Not Detected				Hatch in Floor no asbestos detected beneath false floor					YES
9266	ACTIVE	N	N073-00-A/306	Train Ops Manager Office - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17227	ACTIVE	N	N073-00-A/306	Train Ops Manager Office - Station Building - East Finchley Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9267	ACTIVE	N	N073-00-A/311	General Office - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18945	ACTIVE	N	N073-00-A/311/ CLG-01	Ceiling: Solid - 1 - General Office - Station Building - East Finchley Stn	Void	Asbestos	Surveyed - Not Detected				Temptex covering Concrete; Disused GALV Steel Tank; Plasterboard above ceiling				YES	
17228	ACTIVE	N	N073-00-A/311/ CLG-02	Ceiling: Solid - 2 - General Office - Station Building - East Finchley Stn	Void	Asbestos	Surveyed - Not Detected				Temptex covering Concrete; Disused GALV Steel Tank; Plasterboard above ceiling				YES	
9268	ACTIVE	N	N073-00-A/351	Mess Room - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N073-00 - Station Building - East Finchley Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17229	ACTIVE	N	N073-00-A/351/WAL-003	Wall: Internal - 3 - Mess Room - Station Building - East Finchley Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
9269	ACTIVE	N	N073-00-A/411	Store - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17230	ACTIVE	N	N073-00-A/411	Store - Station Building - East Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
17231	ACTIVE	N	N073-00-A/411	Store - Station Building - East Finchley Stn	Lead/Leading	Lead Paint/Lead	Known				Interior Walls - Cream Matt Paint. Thickness 0.22mm: Analysis 1.15%				N	N
17232	ACTIVE	N	N073-00-A/411	Store - Station Building - East Finchley Stn	Lead/Leading	Lead Paint/Lead	Known				Exterior Surround - White Matt Paint. Thickness 0.29mm: Analysis 5.28%				N	N
9270	ACTIVE	N	N073-00-A/416	Toilet: Unisex - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18946	ACTIVE	N	N073-00-A/416/WAL-003	Wall: Internal - 3 - Toilet - Station Building - East Finchley Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
9271	ACTIVE	N	N073-00-A/436	Waiting Room - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17233	ACTIVE	N	N073-00-A/436	Waiting Room - Station Building - East Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9272	ACTIVE	N	N073-00-A/437	Waiting Room - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17234	ACTIVE	N	N073-00-A/437	Waiting Room - Station Building - East Finchley Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Superlux Panels High Level; Wooden Backing for Underground Posters					
9273	ACTIVE	N	N073-00-A/438	Waiting Room - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17919	ACTIVE	N	N073-00-A/438	Waiting Room - Station Building - East Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9274	ACTIVE	N	N073-00-A/439	Waiting Room - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17235	ACTIVE	N	N073-00-A/439	Waiting Room - Station Building - East Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9275	ACTIVE	N	N073-00-A/451	Tenancy - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17237	ACTIVE	N	N073-00-A/451	Tenancy - Station Building - East Finchley Stn	Other Boarding	Asbestos	Strongly Presumed				Fuse Board behind Fuse				N	N



# Hazardous Material Asset Register - Summary



## N073-00 - Station Building - East Finchley Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17236	ACTIVE	N	N073-00-A/451/FLR-01	Floor - 1 - Tenancy - Station Building - East Finchley Stn	Void	Asbestos	No Access: Presumed				Beneath Wood block floor					YES
18947	ACTIVE	N	N073-00-A/451/WAL-003	Wall: Internal - 3 - Tenancy - Station Building - East Finchley Stn	Rope Seals	Asbestos	Known				2 Fuse Boxes Rope Seal - Chrysotile				N	N
9276	ACTIVE	N	N073-00-A/481	CER - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17238	ACTIVE	N	N073-00-A/481/FLR-01	Floor - 1 - CER - Station Building - East Finchley Stn	Cable Duct: Other	Asbestos	Presumed				150mm cores (ducts) to H/L trackside beneath false floor/ concealed within floor slab				N	YES
9277	ACTIVE	N	N073-00-A/576	Stairs: Linear - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17239	ACTIVE	N	N073-00-A/576	Stairs: Linear - Station Building - East Finchley Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9278	ACTIVE	N	N073-00-A/601	Stairs: Linear - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17920	ACTIVE	N	N073-00-A/601	Stairs: Linear - Station Building - East Finchley Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9279	ACTIVE	N	N073-00-A/602	Stairs: Linear - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17240	ACTIVE	N	N073-00-A/602	Stairs: Linear - Station Building - East Finchley Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9280	ACTIVE	N	N073-00-A/801	Office - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18988	ACTIVE	N	N073-00-A/801	Office - Station Building - East Finchley Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9281	ACTIVE	N	N073-00-A/802	Office - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17241	ACTIVE	N	N073-00-A/802	Office - Station Building - East Finchley Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9282	ACTIVE	N	N073-00-B/041	Mess Room - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17242	ACTIVE	N	N073-00-B/041	Mess Room - Station Building - East Finchley Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9283	ACTIVE	N	N073-00-B/047	Kitchen - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N073-00 - Station Building - East Finchley Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18948	ACTIVE	N	N073-00-B/047	Kitchen - Station Building - East Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9284	ACTIVE	N	N073-00-B/050	Store - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17243	ACTIVE	N	N073-00-B/050	Store - Station Building - East Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9285	ACTIVE	N	N073-00-B/081	Passage - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17244	ACTIVE	N	N073-00-B/081/FLR-01	Floor - 1 - Passage - Station Building - East Finchley Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Solid, Lino					
9286	ACTIVE	N	N073-00-B/236	Passage - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18949	ACTIVE	N	N073-00-B/236	Passage - Station Building - East Finchley Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9287	ACTIVE	N	N073-00-B/291	Office - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17921	ACTIVE	N	N073-00-B/291/WAL-003	Wall: Internal - 3 - Office - Station Building - East Finchley Stn	Void	Asbestos	No Access: Presumed				Movement Panel - No Access Behind					
9288	ACTIVE	N	N073-00-B/331	Mess Room - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17245	ACTIVE	N	N073-00-B/331/FLR-01	Floor - 1 - Mess Room - Station Building - East Finchley Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Solid, Lino					
9289	ACTIVE	N	N073-00-B/416	Toilet: Male - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17341	ACTIVE	N	N073-00-B/416/FLR-01	Floor - 1 - Toilet - Station Building - East Finchley Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Solid, Lino					
9290	ACTIVE	N	N073-00-B/417	Toilet: Female - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19035	ACTIVE	N	N073-00-B/417/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - East Finchley Stn	Void	Asbestos	Surveyed – Not Detected				Solid above false ceiling				YES	
9291	ACTIVE	N	N073-00-B/418	Shower Room - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N073-00 - Station Building - East Finchley Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17342	ACTIVE	N	N073-00-B/418/FLR-01	Floor - 1 - Shower Room - Station Building - East Finchley Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Solid, Lino					
9292	ACTIVE	N	N073-00-B/531	Booking On Point - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17343	ACTIVE	N	N073-00-B/531/FLR-01	Floor - 1 - Office - Station Building - East Finchley Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Solid, Lino					
9293	ACTIVE	N	N073-00-B/576	Stairs: Linear - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17344	ACTIVE	N	N073-00-B/576/FLR-01	Floor - 1 - Linear Stairs - Station Building - East Finchley Stn		Asbestos	Surveyed – Not Detected				Bitumen Cover					
17345	ACTIVE	N	N073-00-B/576/WAL-004	Wall: Internal - 4 - Linear Stairs - Station Building - East Finchley Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
9294	ACTIVE	N	N073-00-B/577	Stairs: Linear - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19036	ACTIVE	N	N073-00-B/577/FLR-01	Floor - 1 - Linear Stairs - Station Building - East Finchley Stn		Asbestos	Surveyed – Not Detected				Bitumen Cover					
18217	ACTIVE	N	N073-00-B/577/WAL-004	Wall: Internal - 4 - Linear Stairs - Station Building - East Finchley Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
9295	ACTIVE	N	N073-00-B/951	Disused Room - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
42245	ACTIVE	N	N073-00-B/951	Disused Room - Station Building - East Finchley Stn	Lagging	Asbestos	Surveyed – Not Detected				Concrete, Hessian Lagged Pipes - no visible asbestos				N	N
9296	ACTIVE	N	N073-00-B/952	Office - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42246	ACTIVE	N	N073-00-B/952	Office - Station Building - East Finchley Stn	Lagging	Asbestos	Surveyed – Not Detected				Concrete, Hessian Lagged Pipes				N	N
9297	ACTIVE	N	N073-00-C/761	Equipment Room - Station Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17348	ACTIVE	N	N073-00-C/761	Equipment Room - Station Building - East Finchley Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing around Pipes					



# Hazardous Material Asset Register - Summary



## N073-02 - Signals Building - East Finchley Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9299	ACTIVE	N	N073-02-0/731	CER - Signals Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17349	ACTIVE	N	N073-02-0/731	CER - Signals Building - East Finchley Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					

## N075-00 - Station Building - Highgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9300	ACTIVE	N	N075-00-1/101	Circulation Area - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18866	ACTIVE	N	N075-00-1/101	Circulation Area - Station Building - Highgate Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9301	ACTIVE	N	N075-00-1/151	UMC - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17912	ACTIVE	N	N075-00-1/151/FLR-01	Floor - 1 - UMC - Station Building - Highgate Stn	Durasteel	Asbestos	Surveyed – Not Detected				Flammable Store (Durasteel) - Non Asbestos					
17155	ACTIVE	N	N075-00-1/172	Escalator Incline - Station Building - Highgate Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
19364	ACTIVE	N	N075-00-1/172	Escalator Incline - Station Building - Highgate Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
9302	ACTIVE	N	N075-00-1/201	Passage - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17156	ACTIVE	N	N075-00-1/201	Passage - Station Building - Highgate Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9303	ACTIVE	N	N075-00-1/401	Bin Store - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17159	ACTIVE	N	N075-00-1/401	Bin Store - Station Building - Highgate Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
9304	ACTIVE	N	N075-00-1/411	Store - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18867	ACTIVE	N	N075-00-1/411	Store - Station Building - Highgate Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9305	ACTIVE	N	N075-00-1/426	Toilet: Male - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N075-00 - Station Building - Highgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17160	ACTIVE	N	N075-00-1/426	Toilet: Male - Station Building - Highgate Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LU Heater - White Foam Backing					
18868	ACTIVE	N	N075-00-1/426/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Highgate Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above False Ceiling				YES	
17161	ACTIVE	N	N075-00-1/426/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Highgate Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				False Ceiling					
9306	ACTIVE	N	N075-00-1/427	Switch Room - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18983	ACTIVE	N	N075-00-1/427	Switch Room - Station Building - Highgate Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9307	ACTIVE	N	N075-00-1/451	Tenancy - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17162	ACTIVE	N	N075-00-1/451	Tenancy - Station Building - Highgate Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9308	ACTIVE	N	N075-00-1/576	Stairs: Linear - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17913	ACTIVE	N	N075-00-1/576	Stairs: Linear - Station Building - Highgate Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
9309	ACTIVE	N	N075-00-1/577	Stairs: Linear - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17163	ACTIVE	N	N075-00-1/577	Stairs: Linear - Station Building - Highgate Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
9310	ACTIVE	N	N075-00-1/601	Stairs: Linear - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17164	ACTIVE	N	N075-00-1/601	Stairs: Linear - Station Building - Highgate Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9311	ACTIVE	N	N075-00-1/602	Stairs: Linear - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17166	ACTIVE	N	N075-00-1/602/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Highgate Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Metal Work above False Ceiling				YES	
17165	ACTIVE	N	N075-00-1/602/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Highgate Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
9312	ACTIVE	N	N075-00-1/761	SVC - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N075-00 - Station Building - Highgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18869	ACTIVE	N	N075-00-1/761/CLG-01	Ceiling: Suspended - 1 - SVC - Station Building - Highgate Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
17167	ACTIVE	N	N075-00-1/761/CLG-01	Ceiling: Suspended - 1 - SVC - Station Building - Highgate Stn	Void	Asbestos	No Access: Presumed				Above False eiling				YES	
9313	ACTIVE	N	N075-00-2/001	Booking Hall - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17173	ACTIVE	N	N075-00-2/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Highgate Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Glass Rock Panelling to Beam above False Ceiling				YES	
9314	ACTIVE	N	N075-00-2/011	Ticket Office - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17246	ACTIVE	N	N075-00-2/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Highgate Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
9315	ACTIVE	N	N075-00-2/021	POM - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17247	ACTIVE	N	N075-00-2/021/FLR-01	Floor - 1 - POM - Station Building - Highgate Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
9316	ACTIVE	N	N075-00-2/031	Mess Room - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17248	ACTIVE	N	N075-00-2/031	Mess Room - Station Building - Highgate Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
18489	ACTIVE	N	N075-00-2/031	Mess Room - Station Building - Highgate Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LU Heater - White Foam Backing					
9317	ACTIVE	N	N075-00-2/036	Toilet: Unisex - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17249	ACTIVE	N	N075-00-2/036	Toilet: Unisex - Station Building - Highgate Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel					
9318	ACTIVE	N	N075-00-2/071	Circulation Area - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18950	ACTIVE	N	N075-00-2/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Highgate Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
17250	ACTIVE	N	N075-00-2/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Highgate Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Glass Rock Panelling to Beam; Metal Work above False Ceiling				YES	
9319	ACTIVE	N	N075-00-2/081	Lobby - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N075-00 - Station Building - Highgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17251	ACTIVE	N	N075-00-2/081	Lobby - Station Building - Highgate Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels					
17252	ACTIVE	N	N075-00-2/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Highgate Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel					
9320	ACTIVE	N	N075-00-2/091	Circulation Area - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17253	ACTIVE	N	N075-00-2/091	Circulation Area - Station Building - Highgate Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Rings - Caulking No access above FC during 2020 re-inspection					N
18951	ACTIVE	N	N075-00-2/091/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Highgate Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
17254	ACTIVE	N	N075-00-2/091/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Highgate Stn	Void	Asbestos	Surveyed – Not Detected				Solid Concrete, Metal Work, RSJ Beams above False Ceiling				YES	
9321	ACTIVE	N	N075-00-2/151	UMC - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17255	ACTIVE	N	N075-00-2/151/FLR-01	Floor - 1 - UMC - Station Building - Highgate Stn	Durasteel	Asbestos	Surveyed – Not Detected				Flammable Store (Durasteel) - Non Asbestos					
9322	ACTIVE	N	N075-00-2/161	LMC - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18216	ACTIVE	N	N075-00-2/161	LMC - Station Building - Highgate Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
17256	ACTIVE	N	N075-00-2/171	Escalator Incline - Station Building - Highgate Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
9323	ACTIVE	N	N075-00-2/201	Passage - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17257	ACTIVE	N	N075-00-2/201	Passage - Station Building - Highgate Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Rings - Caulking No access above FC during 2020 re-inspection					N
17258	ACTIVE	N	N075-00-2/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Highgate Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18952	ACTIVE	N	N075-00-2/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Highgate Stn	Void	Asbestos	Surveyed – Not Detected				Solid Concrete, Metal Work, RSJ Beams above False Ceiling				YES	
9324	ACTIVE	N	N075-00-2/202	Passage - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17259	ACTIVE	N	N075-00-2/202	Passage - Station Building - Highgate Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N075-00 - Station Building - Highgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9325	ACTIVE	N	N075-00-2/203	Passage - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17260	ACTIVE	N	N075-00-2/203	Passage - Station Building - Highgate Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9326	ACTIVE	N	N075-00-2/236	Lobby - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17261	ACTIVE	N	N075-00-2/236/ FLR-01	Floor - 1 - Lobby - Station Building - Highgate Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring No access in floor void during 2020 re-inspection					YES
9327	ACTIVE	N	N075-00-2/311	Office - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17922	ACTIVE	N	N075-00-2/311	Office - Station Building - Highgate Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LU Heater - White Foam Backing					
9328	ACTIVE	N	N075-00-2/331	Mess Room - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17262	ACTIVE	N	N075-00-2/331	Mess Room - Station Building - Highgate Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
17263	ACTIVE	N	N075-00-2/331	Mess Room - Station Building - Highgate Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LU Heater - White Foam Backing					
9329	ACTIVE	N	N075-00-2/401	Station Control Room - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17264	ACTIVE	N	N075-00-2/401	Station Control Room - Station Building - Highgate Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
18953	ACTIVE	N	N075-00-2/401/ FLR-01	Floor - 1 - Station Control Room - Station Building - Highgate Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl					
9330	ACTIVE	N	N075-00-2/406	Disused Room - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17265	ACTIVE	N	N075-00-2/406	Disused Room - Station Building - Highgate Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel					
9331	ACTIVE	N	N075-00-2/411	Store - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17266	ACTIVE	N	N075-00-2/411	Store - Station Building - Highgate Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9332	ACTIVE	N	N075-00-2/451	Tenancy - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N075-00 - Station Building - Highgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17267	ACTIVE	N	N075-00-2/451	Tenancy - Station Building - Highgate Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Tenancy					
9333	ACTIVE	N	N075-00-2/452	Tenancy - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17923	ACTIVE	N	N075-00-2/452	Tenancy - Station Building - Highgate Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Tenancy					
9334	ACTIVE	N	N075-00-2/661	Switch Room - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18954	ACTIVE	N	N075-00-2/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Highgate Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Box Insulation within ( 1X 30 Amps) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1		N	N
18989	ACTIVE	N	N075-00-2/661/WAL-001 80916227	Wall: Internal - 1 - Switch Room - Station Building - Highgate Stn Wall: Internal	Other Electrical Boxes	Asbestos	Strongly Presumed				Transformer Box(es) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		3		N	N
18467	ACTIVE	N	N075-00-2/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Highgate Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes - Insulation within (1x100 Amps/8 x 60Amps) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		9		N	N
9335	ACTIVE	N	N075-00-2/662	Switch Room - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
44139	ACTIVE	N	N075-00-2/662	Switch Room - Station Building - Highgate Stn	Cable Ducts: Cement	Asbestos	Presumed				Cable ducts - P - Cement & Bitumen				N	N
19411	ACTIVE	N	N075-00-2/662/FLR-01	Floor - 1 - Switch Room - Station Building - Highgate Stn	Void	Asbestos	No Access: Presumed				Beneath Hatch					YES
17268	ACTIVE	N	N075-00-2/662/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Highgate Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes - Insulation within 3 x 30 Amps/4 x 60 Amps and 1 x 100Amps No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		8		N	N
17269	ACTIVE	N	N075-00-2/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Highgate Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Box - Insulation within ( 1 x 100 Amps) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1		N	N



# Hazardous Material Asset Register - Summary



## N075-00 - Station Building - Highgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9336	ACTIVE	N	N075-00-2/663	Switch Room - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17270	ACTIVE	N	N075-00-2/663	Switch Room - Station Building - Highgate Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9337	ACTIVE	N	N075-00-2/664	Switch Cupboard - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18990	ACTIVE	N	N075-00-2/664/CLG-01	Ceiling: Suspended - 1 - Switch Cupboard - Station Building - Highgate Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux					
9338	ACTIVE	N	N075-00-2/731	CER - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18490	ACTIVE	N	N075-00-2/731/FLR-01	Floor - 1 - CER - Station Building - Highgate Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
17271	ACTIVE	N	N075-00-2/731/WAL-001	Wall: Internal - 1 - CER - Station Building - Highgate Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes - 2 x 60 amps - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		2		N	N
19489	ACTIVE	N	N075-00-2/731/WAL-002	Wall: Internal - 2 - CER - Station Building - Highgate Stn	Other Boarding	Asbestos	Strongly Presumed				Paxoline Board		1		N	N
9339	ACTIVE	N	N075-00-2/746	SCR - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18955	ACTIVE	N	N075-00-2/746	SCR - Station Building - Highgate Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9340	ACTIVE	N	N075-00-2/771	Pump Room - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17272	ACTIVE	N	N075-00-2/771/CLG-01	Ceiling: Solid - 1 - Pump Room - Station Building - Highgate Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Panel					
9341	ACTIVE	N	N075-00-2/901	Void - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17273	ACTIVE	N	N075-00-2/901	Void - Station Building - Highgate Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
9342	ACTIVE	N	N075-00-2/951	UMC - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N075-00 - Station Building - Highgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9343	ACTIVE	N	N075-00-2/TA1	Tenancy - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9344	ACTIVE	N	N075-00-3/081	Circulation Area - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17274	ACTIVE	N	N075-00-3/081	Circulation Area - Station Building - Highgate Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Rings - Caulking No access in FC during 2020 re-inspection				N	N
17275	ACTIVE	N	N075-00-3/081/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Highgate Stn	Void	Asbestos	Surveyed – Not Detected				Solid Concrete, Metal Work, RSJ Beams				YES	
18956	ACTIVE	N	N075-00-3/081/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Highgate Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
9345	ACTIVE	N	N075-00-3/161	LMC - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17276	ACTIVE	N	N075-00-3/161	LMC - Station Building - Highgate Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel					
17277	ACTIVE	N	N075-00-3/161	LMC - Station Building - Highgate Stn	Lead/Leading	Lead Paint/Lead	Known				Black Oil Based Paint - Girders. Thickness .09mm; Est Quantity 6sqm; Analysis 1.5% - Fair Conditioning				N	N
9346	ACTIVE	N	N075-00-3/201	Passage - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17278	ACTIVE	N	N075-00-3/201	Passage - Station Building - Highgate Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
18957	INACTIVE	N	N075-00-3/201/CLG-01 80916557	Ceiling: Solid - 1 - Passage - Station Building - Highgate Stn Ceiling: Solid	Lead/Leading	Lead Paint/Lead	Known				Cream Emulsion Paint. Thickness .43mm; Est Quantity 30sqm; Analysis 2.0% - Poor Condition, flaking paint over walkway				N	N
17924	INACTIVE	N	N075-00-3/201/CLG-02	Ceiling: Solid - 2 - Passage - Station Building - Highgate Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Emulsion Paint. Thickness .43mm; Est Quantity 30sqm; Analysis 2.0% - Ok Fair				N	N
17279	INACTIVE	N	N075-00-3/201/CLG-03	Ceiling: Solid - 3 - Passage - Station Building - Highgate Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Emulsion Paint. Thickness .43mm; Est Quantity 30sqm; Analysis 2.0% - Fair				N	N
9347	ACTIVE	N	N075-00-3/202	Passage - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17280	ACTIVE	N	N075-00-3/202	Passage - Station Building - Highgate Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9348	ACTIVE	N	N075-00-3/203	Passage - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N075-00 - Station Building - Highgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17281	ACTIVE	N	N075-00-3/203	Passage - Station Building - Highgate Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9349	ACTIVE	N	N075-00-3/204	Passage - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17282	ACTIVE	N	N075-00-3/204	Passage - Station Building - Highgate Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9350	ACTIVE	N	N075-00-3/205	Passage - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17283	ACTIVE	N	N075-00-3/205	Passage - Station Building - Highgate Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9351	ACTIVE	N	N075-00-3/206	Passage - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17284	ACTIVE	N	N075-00-3/206	Passage - Station Building - Highgate Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9352	ACTIVE	N	N075-00-3/236	Passage - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18958	ACTIVE	N	N075-00-3/236/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Highgate Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel					
9353	ACTIVE	N	N075-00-3/261	Platform 1 - Northbound Fast - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44129	ACTIVE	N	N075-00-3/261	Platform 1 - Northbound Fast - Station Building - Highgate Stn	Lead/Leading	Lead Paint/Lead	Presumed				Red lead paint at platform end, outside room 3/713				N	N
17285	ACTIVE	N	N075-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Highgate Stn	Cable: Sheath	Asbestos	Strongly Presumed				2 x Cables on top J-Hanger All All other cables - within Invert not visible on Platform  No access as invert - Confined space team required.				N	YES
17286	ACTIVE	N	N075-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Highgate Stn	Cable Duct: Other	Asbestos	Surveyed – Not Detected				All Cable Ducts - Non Asbestos					YES
9354	ACTIVE	N	N075-00-3/262	Platform 2 - Southbound Fast - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17287	ACTIVE	N	N075-00-3/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Highgate Stn	Cable: Sheath	Asbestos	Strongly Presumed				2 x Cables All other cables - In Invert - not visible on platform  No access as invert - Confined space team required.				N	YES
17288	ACTIVE	N	N075-00-3/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Highgate Stn	Cable Duct: Other	Asbestos	Surveyed – Not Detected				All Cable Ducts - Non Asbestos					YES



# Hazardous Material Asset Register - Summary



## N075-00 - Station Building - Highgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9355	ACTIVE	N	N075-00-3/281	CER - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17290	ACTIVE	N	N075-00-3/281/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Highgate Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel					
17289	ACTIVE	N	N075-00-3/281/DOR-01	Door - 1 - CER - Station Building - Highgate Stn	Durasteel	Asbestos	Strongly Presumed				Durasteel Panel above door		1		N	N
19022	ACTIVE	N	N075-00-3/281/FLR-01	Floor - 1 - CER - Station Building - Highgate Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
9356	ACTIVE	N	N075-00-3/381	Switch Room - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17986	ACTIVE	N	N075-00-3/381	Switch Room - Station Building - Highgate Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel					
9357	ACTIVE	N	N075-00-3/382	Store - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17291	ACTIVE	N	N075-00-3/382	Store - Station Building - Highgate Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel					
18991	ACTIVE	N	N075-00-3/382	Store - Station Building - Highgate Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LU Heater White Foam Backing					
9358	ACTIVE	N	N075-00-3/383	SER - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17292	ACTIVE	N	N075-00-3/383	SER - Station Building - Highgate Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LU Heater White Foam Backing					
17293	ACTIVE	N	N075-00-3/383	SER - Station Building - Highgate Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
9359	ACTIVE	N	N075-00-3/406	Store - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19023	ACTIVE	N	N075-00-3/406	Store - Station Building - Highgate Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panelling around ducting					
9360	ACTIVE	N	N075-00-3/411	Disused Room - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17294	ACTIVE	N	N075-00-3/411	Disused Room - Station Building - Highgate Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel		2			
9361	ACTIVE	N	N075-00-3/661	Switch Room - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N075-00 - Station Building - Highgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17295	INACTIVE	N	N075-00-3/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Highgate Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes Insulation within (1 x 60 Amps) - Located on wall 2		1		N	N
44132	ACTIVE	N	N075-00-3/661/WAL-001 80916459	Wall: Internal - 1 - Switch Room - Station Building - Highgate Stn Wall: Internal	Isolator Switches	Asbestos	Presumed				60 amp switch box  No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1		N	N
19488	ACTIVE	N	N075-00-3/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Highgate Stn	Isolator Switches	Asbestos	Strongly Presumed				8 X Switch Boxes Insulation within (5 x 100 Amps/3 x 200 Amps) wall 2  No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		8		N	N
17174	INACTIVE	N	N075-00-3/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Highgate Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes Insulation within - Located on Wall 2 as advised by Alan Hartley		5			
9362	ACTIVE	N	N075-00-3/662	Switch Cupboard - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
9363	ACTIVE	N	N075-00-3/663	Switch Room - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18870	ACTIVE	N	N075-00-3/663/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Highgate Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Panel					
9364	ACTIVE	N	N075-00-3/706	Passage - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
9365	ACTIVE	N	N075-00-3/711	Relay Room - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
17176	INACTIVE	N	N075-00-3/711	Relay Room - Station Building - Highgate Stn	Cable: Sheath	Asbestos	Strongly Presumed				3 x 15mm Cables - 2 x going into Invert		3		N	N
42544	ACTIVE	N	N075-00-3/711	Relay Room - Station Building - Highgate Stn	Cable: Sheath	Asbestos	Strongly Presumed				Various Cables 4m each from rack on wall 2 and onto wall 3				N	N
18984	INACTIVE	N	N075-00-3/711	Relay Room - Station Building - Highgate Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				4 x PCB's - Fair Condition. Serial nos not visible		4		N	N
46857	ACTIVE	N	N075-00-3/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Highgate Stn	Other Boarding	Asbestos	Presumed				Black composite panel to rack on wall 2					
17175	ACTIVE	N	N075-00-3/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Highgate Stn	Westing house Boxes	Asbestos	Presumed				Two Westinghouse Boxes one big, one small on wall 2		2		N	N
46858	ACTIVE	N	N075-00-3/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Highgate Stn	Other Boarding	Asbestos	Presumed				Black Composite panel to underneath top shelf on rack of wall 2					
44127	ACTIVE	N	N075-00-3/711/WAL-002 80916568	Wall: Internal - 2 - Relay Room - Station Building - Highgate Stn Wall: Internal	Other Boarding	Asbestos	Presumed				Brown composite panel to capacitor on rack - wall 2		4		N	N



# Hazardous Material Asset Register - Summary



## N075-00 - Station Building - Highgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44134	INACTIVE	N	N075-00-3/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Highgate Stn	Cable Ducts: Cement	Asbestos	Presumed				No access to cable ducts - Presumed Asbestos  No Access during 2020 re-inspection				N	N
44126	ACTIVE	N	N075-00-3/711/WAL-003 80916569	Wall: Internal - 3 - Relay Room - Station Building - Highgate Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				3no x electrical boxes on wall 3  No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		3		N	N
9366	ACTIVE	N	N075-00-3/712	Relay Room - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17179	INACTIVE	N	N075-00-3/712	Relay Room - Station Building - Highgate Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				3 x PCB's - Fair Condition. Serial Nos Not Visible - Fair		3		N	N
44136	INACTIVE	N	N075-00-3/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Highgate Stn	Cable Ducts: Cement	Asbestos	Presumed				Cable duct wall 1 - No access - P  No access during 2020 re-inspection				N	N
17177	ACTIVE	N	N075-00-3/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Highgate Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				3no electrical boxes wall 1  No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		2		N	N
17178	ACTIVE	N	N075-00-3/712/WAL-001 80916577	Wall: Internal - 1 - Relay Room - Station Building - Highgate Stn Wall: Internal	Cable: Sheath	Asbestos	Presumed				15mm 1 x wrap and 1 x woven Cables going into Invert		2		N	N
46861	ACTIVE	N	N075-00-3/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Highgate Stn	Cable: Sheath	Asbestos	Presumed				braided cable to rack on wall 2					
44131	ACTIVE	N	N075-00-3/712/WAL-002 80916578	Wall: Internal - 2 - Relay Room - Station Building - Highgate Stn Wall: Internal	Other Boarding	Asbestos	Presumed				Black /brown composite board to capacitors on rack of wall 2		3		N	N
46860	ACTIVE	N	N075-00-3/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Highgate Stn	Other Boarding	Asbestos	Presumed				Black composite board to rack wall 2					
18871	INACTIVE	N	N075-00-3/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Highgate Stn	Other Boarding	Asbestos	Presumed				Paxoline Board				N	N
46859	ACTIVE	N	N075-00-3/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Highgate Stn	Other Boarding	Asbestos	Presumed				Black composite board to rack x1 on wall 2					
42545	INACTIVE	N	N075-00-3/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Highgate Stn	Other Boarding	Asbestos	Strongly Presumed				Paxoline Board				N	N
9367	ACTIVE	N	N075-00-3/713	Relay Room - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18487	ACTIVE	N	N075-00-3/713/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Highgate Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				4no Electrical Boxes - Insulation within - wall 1  No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		4		N	N



# Hazardous Material Asset Register - Summary



## N075-00 - Station Building - Highgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17180	ACTIVE	N	N075-00-3/713/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Highgate Stn	Cable: Sheath	Asbestos	Strongly Presumed				10mm Cables - 2 x going into Invert		10		N	N
44128	ACTIVE	N	N075-00-3/713/WAL-002 80916488	Wall: Internal - 2 - Relay Room - Station Building - Highgate Stn Wall: Internal	Other Boarding	Asbestos	Presumed				Paxoline boarding		2		N	N
17181	INACTIVE	N	N075-00-3/713/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Highgate Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				2 x PCB's - Fair Condition. Serial nos not visible		2		N	N
9368	ACTIVE	N	N075-00-3/714	Relay Room - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18872	INACTIVE	N	N075-00-3/714	Relay Room - Station Building - Highgate Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				5 x PCB's - Fair condition. Serial Nos Not Visible - Fair Condition		5		N	N
44137	ACTIVE	N	N075-00-3/714/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Highgate Stn	Cable Ducts: Cement	Asbestos	Presumed				Cable ducts - wall 1 - No access P No access during 2020 re-inspection				N	N
44130	ACTIVE	N	N075-00-3/714/WAL-002 80916500	Wall: Internal - 2 - Relay Room - Station Building - Highgate Stn Wall: Internal	Other Boarding	Asbestos	Presumed				Paxoline boarding		6		N	N
17182	ACTIVE	N	N075-00-3/714/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Highgate Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				3no Electrical Boxes - Insulation within wall 3  No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		3		N	N
17183	ACTIVE	N	N075-00-3/714/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Highgate Stn	Cable: Sheath	Asbestos	Strongly Presumed				15mm Cables going into Invert		2		N	N
9369	ACTIVE	N	N075-00-3/901	Disused Room - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17184	ACTIVE	N	N075-00-3/901	Disused Room - Station Building - Highgate Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9370	ACTIVE	N	N075-00-3/991	Equipment Room - Station Building - Highgate Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17185	ACTIVE	N	N075-00-3/991/CLG-01	Ceiling: Solid - 1 - Equipment Room - Station Building - Highgate Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Panel					

## N081-00 - Station Building - Archway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9377	ACTIVE	N	N081-00-1/001	Booking Hall - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N081-00 - Station Building - Archway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17106	ACTIVE	N	N081-00-1/001/CLG-01	Ceiling: Suspended - 1 - Booking Hall - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
17107	ACTIVE	N	N081-00-1/001/CLG-01	Ceiling: Suspended - 1 - Booking Hall - Station Building - Archway Stn	Void	Asbestos	Surveyed – Not Detected				From 1/021 Concrete; Brick Walls; Metal duct for cable and vent boarding; On duct by end wall is supalux				YES	
9378	ACTIVE	N	N081-00-1/011	Ticket Office - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18789	ACTIVE	N	N081-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
17910	ACTIVE	N	N081-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Archway Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Brick, Metal Ducting above Supalux Tiles				YES	
17108	ACTIVE	N	N081-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Archway Stn	Void	Asbestos	Surveyed – Not Detected				Solid, Concrete; Plastic Cables beneath Computer Flooring					YES
9379	ACTIVE	N	N081-00-1/021	POM - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17111	ACTIVE	N	N081-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Archway Stn		Asbestos	Surveyed – Not Detected				Concrete; Brick Walls; Metal ducting for cables and vent; Fibreglass wadding on ceiling; Plastic Cables above False Ceiling				YES	
17110	ACTIVE	N	N081-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
17109	ACTIVE	N	N081-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Archway Stn	Void	Asbestos	Surveyed – Not Detected				Solid, Concrete; Plastic Cables beneath Computer Flooring					YES
9380	ACTIVE	N	N081-00-1/031	Mess Room - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17112	ACTIVE	N	N081-00-1/031	Mess Room - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board					
17113	ACTIVE	N	N081-00-1/031	Mess Room - Station Building - Archway Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
17115	ACTIVE	N	N081-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Archway Stn		Asbestos	Surveyed – Not Detected				Concrete; Brick Walls; Metal ducting for cables and vent; Fibreglass wadding on ceiling; Plastic Cables above False Ceiling				YES	
17114	ACTIVE	N	N081-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					



# Hazardous Material Asset Register - Summary



## N081-00 - Station Building - Archway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18790	ACTIVE	N	N081-00-1/031/WAL-004	Wall: Internal - 4 - Mess Room - Station Building - Archway Stn	LUL Heaters	Asbestos	Known				LU Heater - Insulation Board - Chrysotile  Original Photo as below is within Gents W/C 1/417 to wall. This is now replaced with new heater (Photo DSC05238).				N	N
9381	ACTIVE	N	N081-00-1/036	Toilet: Unisex - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17116	ACTIVE	N	N081-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
17117	ACTIVE	N	N081-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Archway Stn	Void	Asbestos	Surveyed - Not Detected				All walls brick/ breeze block, ceiling concrete; Metal Duct - Air Conditioning; Plastic Cables above False Ceiling				YES	
9382	ACTIVE	N	N081-00-1/047	Locker Room - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17118	ACTIVE	N	N081-00-1/047/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Archway Stn	Void	Asbestos	Surveyed - Not Detected				All walls brick/ breeze block, ceiling concrete; Metal Duct - Air Conditioning; Plastic Cables above False Ceiling				YES	
18791	ACTIVE	N	N081-00-1/047/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
9383	ACTIVE	N	N081-00-1/071	Circulation Area - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17119	ACTIVE	N	N081-00-1/071/CLG-01	Ceiling: Suspended - 1 - Circulation Area - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
17120	ACTIVE	N	N081-00-1/071/CLG-02	Ceiling: Solid - 2 - Circulation Area - Station Building - Archway Stn	Void	Asbestos	Surveyed - Not Detected				Concrete; PVC Cables above Supalux Tiles				YES	
9384	ACTIVE	N	N081-00-1/201	Passage - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17911	ACTIVE	N	N081-00-1/201	Passage - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles - Above Entrance					
17121	ACTIVE	N	N081-00-1/201/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Archway Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Supalux Tiles				YES	
20017	ACTIVE	N	N081-00-1/201/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
9385	ACTIVE	N	N081-00-1/202	Passage - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N081-00 - Station Building - Archway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17122	ACTIVE	N	N081-00-1/202/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Archway Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Supalux Tiles				YES	
18792	ACTIVE	N	N081-00-1/202/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
9386	ACTIVE	N	N081-00-1/236	Lobby - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17126	ACTIVE	N	N081-00-1/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Archway Stn	Void	Asbestos	Surveyed - Not Detected				All walls brick/ breeze block, ceiling concrete. Metal ducting (Supalux board on duct) above False Ceiling				YES	
17124	ACTIVE	N	N081-00-1/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
17125	ACTIVE	N	N081-00-1/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
18857	ACTIVE	N	N081-00-1/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Archway Stn	Void	Asbestos	Surveyed - Not Detected				Concrete; Plastic Cable; Metal Duct - Air Conditioning; Brick above False Ceiling				YES	
17123	ACTIVE	N	N081-00-1/236/FLR-01	Floor - 1 - Lobby - Station Building - Archway Stn	Void	Asbestos	Surveyed - Not Detected				Plastic Cables; Solid, Concrete beneath Computer Flooring					YES
9387	ACTIVE	N	N081-00-1/237	Lobby - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
9388	ACTIVE	N	N081-00-1/238	Lobby - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17128	ACTIVE	N	N081-00-1/238/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Archway Stn	Void	Asbestos	Surveyed - Not Detected				All walls brick/block, ceiling concrete; All pipe and duct metal (void above 1/406); Plastic Cables above False Ceiling				YES	
17127	ACTIVE	N	N081-00-1/238/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
9389	ACTIVE	N	N081-00-1/311	Office - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17129	ACTIVE	N	N081-00-1/311/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
18981	ACTIVE	N	N081-00-1/311/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Archway Stn	Void	Asbestos	Surveyed - Not Detected				All walls brick, ceiling concrete metal ducting, Supalux Panel, Plastic Cables above Supalux Tiles				YES	
9390	ACTIVE	N	N081-00-1/331	Station Supervisor Office - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18858	ACTIVE	N	N081-00-1/331/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					



# Hazardous Material Asset Register - Summary



## N081-00 - Station Building - Archway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17130	ACTIVE	N	N081-00-1/331/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Archway Stn	Void	Asbestos	Surveyed – Not Detected				Ceiling concrete. All walls brick. Duct Metal with Fibre-Glass insulation PVC Cable above False Ceiling				YES	
9391	ACTIVE	N	N081-00-1/401	Bin Store - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9392	ACTIVE	N	N081-00-1/406	Store - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17131	ACTIVE	N	N081-00-1/406/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
17132	ACTIVE	N	N081-00-1/406/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Archway Stn	Void	Asbestos	Surveyed – Not Detected				All walls brick/block, ceiling concrete. Metal ducting with fibre-glass insulation; Plastic Cables above Supalux Ceiling				YES	
9393	ACTIVE	N	N081-00-1/411	Store - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17133	ACTIVE	N	N081-00-1/411/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18859	ACTIVE	N	N081-00-1/411/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Archway Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	
9394	ACTIVE	N	N081-00-1/416	Toilet: Female - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17134	ACTIVE	N	N081-00-1/416	Toilet: Female - Station Building - Archway Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater Foam Backing					
17136	ACTIVE	N	N081-00-1/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Archway Stn	Void	Asbestos	Surveyed – Not Detected				Ceiling is concrete. All walls brick metal ducting spacer in wall is wood, pipe lagging - Rock Wool; Plastic cable; (roof space split in two) - above False Ceiling				YES	
17135	ACTIVE	N	N081-00-1/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
9395	ACTIVE	N	N081-00-1/417	Toilet: Male - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19416	ACTIVE	N	N081-00-1/417	Toilet: Male - Station Building - Archway Stn	Other Boarding	Asbestos	Surveyed – Not Detected				LTB Fire Door					
18485	ACTIVE	N	N081-00-1/417	Toilet: Male - Station Building - Archway Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater Foam Backing					
17138	ACTIVE	N	N081-00-1/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Archway Stn	Void	Asbestos	Surveyed – Not Detected				Ceiling Concrete. All walls brick; Metal ducting, fibre-glass insulated pipes; Plastic Cables - above False Ceiling				YES	



# Hazardous Material Asset Register - Summary



## N081-00 - Station Building - Archway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17137	ACTIVE	N	N081-00-1/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
9396	ACTIVE	N	N081-00-1/451	Tenancy - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18860	ACTIVE	N	N081-00-1/451	Tenancy - Station Building - Archway Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Tenancy					
9397	ACTIVE	N	N081-00-1/631	Stairs: Spiral - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17139	ACTIVE	N	N081-00-1/631	Stairs: Spiral - Station Building - Archway Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Ring Caulking					
17140	ACTIVE	N	N081-00-1/631/CLG-01	Ceiling: Solid - 1 - Spiral Stairs - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles. Bulkhead - Supalux Tiles					
17141	ACTIVE	N	N081-00-1/631/CLG-01	Ceiling: Solid - 1 - Spiral Stairs - Station Building - Archway Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Brick above False Ceiling				YES	
9398	ACTIVE	N	N081-00-1/661	Switch Room - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18861	ACTIVE	N	N081-00-1/661	Switch Room - Station Building - Archway Stn	Other Electrical Boxes	Asbestos	Presumed				Various Electrical Equipment - Insulation within HMU Re-Inspection ok - 28-08-2015 No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score materials within.				N	N
18214	ACTIVE	N	N081-00-1/661/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
17142	ACTIVE	N	N081-00-1/661/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Archway Stn	Void	Asbestos	Surveyed – Not Detected				Concrete				YES	
17143	ACTIVE	N	N081-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Archway Stn	Other Electrical Boxes	Asbestos	Presumed				3 x Transformer Box(es) HMU Re-Inspection - 28-08-2015 No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score materials within.		3		N	N
42539	ACTIVE	N	N081-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Archway Stn	Isolator Switches	Asbestos	Strongly Presumed				1 X Switch Box No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score materials within.		1		N	N



# Hazardous Material Asset Register - Summary



## N081-00 - Station Building - Archway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42538	ACTIVE	N	N081-00-1/661/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Archway Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1 X Red Spot Box No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score materials within.		1		N	N
9399	ACTIVE	N	N081-00-1/746	SCR - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17144	ACTIVE	N	N081-00-1/746/CLG-01	Ceiling: Suspended - 1 - SCR - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
17145	ACTIVE	N	N081-00-1/746/CLG-01	Ceiling: Suspended - 1 - SCR - Station Building - Archway Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above false ceiling				YES	
9400	ACTIVE	N	N081-00-1/776	Fan Room - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18862	ACTIVE	N	N081-00-1/776	Fan Room - Station Building - Archway Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
18618	ACTIVE	N	N081-00-1/791/CLG-01	Ceiling: Solid - 1 - Vent Shaft - Station Building - Archway Stn	Caulking	Asbestos	Surveyed - Not Detected				Tunnel Rings - Sealed over with Concrete - No Caulking present					
9401	ACTIVE	N	N081-00-1/901	SVC - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18466	ACTIVE	N	N081-00-1/901	SVC - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Boxing					
9402	ACTIVE	N	N081-00-1/951	Mess Room - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16951	ACTIVE	N	N081-00-1/951	Mess Room - Station Building - Archway Stn		Asbestos	Surveyed - Not Detected				Acoustic Panel below sink					
16952	ACTIVE	N	N081-00-1/951/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux					
16953	ACTIVE	N	N081-00-1/951/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Archway Stn	Void	Asbestos	Surveyed - Not Detected				All walls brick/block, ceiling concrete; Metal duct with fibre-glass lagging also on pipe work boxing is Supalux - above false ceiling				YES	
9403	ACTIVE	N	N081-00-2/081	Circulation Area - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19140	ACTIVE	N	N081-00-2/081	Circulation Area - Station Building - Archway Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9404	ACTIVE	N	N081-00-2/082	Lobby - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N081-00 - Station Building - Archway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16954	ACTIVE	N	N081-00-2/082	Lobby - Station Building - Archway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9405	ACTIVE	N	N081-00-2/151	UMC - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44122	ACTIVE	N	N081-00-2/151	UMC - Station Building - Archway Stn		Asbestos	Known				Gasket, 2 no, to A/C metal ductwork in 2/151 UMC 1 & 2 at Archway Station			R605851	N	N
44123	ACTIVE	N	N081-00-2/151	UMC - Station Building - Archway Stn		Asbestos	Known				Gasket, 2 no, to A/C metal ductwork in 2/151 UMC 1 & 2 at Archway Station			R605851	N	N
44121	ACTIVE	N	N081-00-2/151	UMC - Station Building - Archway Stn		Asbestos	Known				Gasket, 2 no, to A/C metal ductwork in 2/151 UMC 1 & 2 at Archway Station			R605851	N	N
16956	ACTIVE	N	N081-00-2/151	UMC - Station Building - Archway Stn	Durasteel	Asbestos	Surveyed – Not Detected				Flammable Store (Durasteel) - Non Asbestos					
16955	ACTIVE	N	N081-00-2/151	UMC - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel;					
18619	ACTIVE	N	N081-00-2/151	UMC - Station Building - Archway Stn	Caulking	Asbestos	Surveyed – Not Detected				Incline from 2/151 to 2/161 - Tunnel Rings - Covered with concrete - No caulking present behind					
9406	ACTIVE	N	N081-00-2/161	LMC - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16958	ACTIVE	N	N081-00-2/161	LMC - Station Building - Archway Stn	Cable Ducts: Bitumen	Asbestos	Surveyed – Not Detected				Bitumen Ducts - Non Asbestos					
16959	ACTIVE	N	N081-00-2/161	LMC - Station Building - Archway Stn	Cable Duct: Other	Asbestos	No Access: Presumed				Cable Sleeve - No Access					
16957	ACTIVE	N	N081-00-2/161/FLR-01	Floor - 1 - LMC - Station Building - Archway Stn	Void	Asbestos	No Access: Presumed				Beneath Hatch on floor					YES
9407	ACTIVE	N	N081-00-2/201	Passage - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19141	ACTIVE	N	N081-00-2/201	Passage - Station Building - Archway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9408	ACTIVE	N	N081-00-2/202	Passage - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16960	ACTIVE	N	N081-00-2/202	Passage - Station Building - Archway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9409	ACTIVE	N	N081-00-2/236	Lobby - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N081-00 - Station Building - Archway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16961	ACTIVE	N	N081-00-2/236	Lobby - Station Building - Archway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9410	ACTIVE	N	N081-00-2/237	Lobby - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18620	ACTIVE	N	N081-00-2/237	Lobby - Station Building - Archway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9411	ACTIVE	N	N081-00-2/238	Lobby - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16962	ACTIVE	N	N081-00-2/238	Lobby - Station Building - Archway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9412	ACTIVE	N	N081-00-2/406	Store - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16963	ACTIVE	N	N081-00-2/406	Store - Station Building - Archway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9413	ACTIVE	N	N081-00-2/411	Disused Room - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18621	ACTIVE	N	N081-00-2/411	Disused Room - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding					
16964	ACTIVE	N	N081-00-2/411	Disused Room - Station Building - Archway Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Ring: Caulking - Non Asbestos					
9414	ACTIVE	N	N081-00-2/601	Stairs: Linear - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19142	ACTIVE	N	N081-00-2/601	Stairs: Linear - Station Building - Archway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9415	ACTIVE	N	N081-00-2/602	Stairs: Linear - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16965	ACTIVE	N	N081-00-2/602	Stairs: Linear - Station Building - Archway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9416	ACTIVE	N	N081-00-2/603	Stairs: Linear - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16966	ACTIVE	N	N081-00-2/603	Stairs: Linear - Station Building - Archway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
16967	ACTIVE	N	N081-00-2/636	Overbridge - Station Building - Archway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N081-00 - Station Building - Archway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16968	ACTIVE	N	N081-00-2/637	Overbridge - Station Building - Archway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9417	ACTIVE	N	N081-00-2/661	Switch Room - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18622	ACTIVE	N	N081-00-2/661	Switch Room - Station Building - Archway Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
9418	ACTIVE	N	N081-00-2/662	Switch Room - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16969	ACTIVE	N	N081-00-2/662	Switch Room - Station Building - Archway Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
9419	ACTIVE	N	N081-00-2/711	SER - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18914	ACTIVE	N	N081-00-2/711	SER - Station Building - Archway Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
9420	ACTIVE	N	N081-00-2/731	CER - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16970	ACTIVE	N	N081-00-2/731/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Archway Stn	Void	Asbestos	Surveyed – Not Detected				Roof - Corrugated Metal Sheet - above Breeze Blocks, Concrete				YES	
19143	ACTIVE	N	N081-00-2/731/FLR-01	Floor - 1 - CER - Station Building - Archway Stn	Void	Asbestos	Surveyed – Not Detected				Solid, new metal work, PVC Cables beneath Wooden floor					YES
16971	ACTIVE	N	N081-00-2/731/WAL-004	Wall: Internal - 4 - CER - Station Building - Archway Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x Grey Switch Boxes - Insultaion within (60amps) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score materials within.		2		N	N
9421	ACTIVE	N	N081-00-2/761	Computer Equipment Cupboard - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18623	ACTIVE	N	N081-00-2/761	Computer Equipment Cupboard - Station Building - Archway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9422	ACTIVE	N	N081-00-2/762	Computer Equipment Cupboard - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16972	ACTIVE	N	N081-00-2/762	Computer Equipment Cupboard - Station Building - Archway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N081-00 - Station Building - Archway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9423	ACTIVE	N	N081-00-2/763	Computer Equipment Cupboard - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16973	ACTIVE	N	N081-00-2/763	Computer Equipment Cupboard - Station Building - Archway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9424	ACTIVE	N	N081-00-2/764	Computer Equipment Cupboard - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18687	ACTIVE	N	N081-00-2/764	Computer Equipment Cupboard - Station Building - Archway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9425	ACTIVE	N	N081-00-2/765	Computer Equipment Cupboard - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16974	ACTIVE	N	N081-00-2/765	Computer Equipment Cupboard - Station Building - Archway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9426	ACTIVE	N	N081-00-2/766	Computer Equipment Cupboard - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16975	ACTIVE	N	N081-00-2/766	Computer Equipment Cupboard - Station Building - Archway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9427	ACTIVE	N	N081-00-2/786	Service Riser - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16976	ACTIVE	N	N081-00-2/786	Service Riser - Station Building - Archway Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Rings; Caulking					
18688	ACTIVE	N	N081-00-2/791/CLG-01	Ceiling: Solid - 1 - Vent Shaft - Station Building - Archway Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Rings - Sealed over with Concrete - No Caulking present					
9428	ACTIVE	N	N081-00-2/951	Switch Room - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16977	ACTIVE	N	N081-00-2/951/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel					
18478	ACTIVE	N	N081-00-2/951/DOR-01	Door - 1 - Switch Room - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel above Door					
16978	ACTIVE	N	N081-00-2/973/CLG-01	Ceiling: Solid - 1 - Vent Shaft - Station Building - Archway Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Rings Caulking					
19024	ACTIVE	N	N081-00-2/973/WAL-001	Wall: Internal - 1 - Vent Shaft - Station Building - Archway Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Rings Caulking					



# Hazardous Material Asset Register - Summary



## N081-00 - Station Building - Archway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17298	ACTIVE	N	N081-00-2/986	Vent Shaft - Station Building - Archway Stn	Gasket :Pipework	Asbestos	Strongly Presumed				Fan Equipment - Gasket and woven materials in equipment  1x presume ACMs within combination fuse switch to wall by entrance gate in 2/786 - Photo DSC05250					
17296	ACTIVE	N	N081-00-2/986	Vent Shaft - Station Building - Archway Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Rings; Caulking - Non Asbestos below Concrete floor					
17297	ACTIVE	N	N081-00-2/986/WAL-001	Wall: Internal - 1 - Vent Shaft - Station Building - Archway Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Rings - Caulking.				N	N
9429	ACTIVE	N	N081-00-3/121	Platform Invert - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17299	ACTIVE	N	N081-00-3/121	Platform Invert - Station Building - Archway Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
9430	ACTIVE	N	N081-00-3/201	Passage - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17300	ACTIVE	N	N081-00-3/201	Passage - Station Building - Archway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9431	ACTIVE	N	N081-00-3/202	Passage - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19025	ACTIVE	N	N081-00-3/202	Passage - Station Building - Archway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9432	ACTIVE	N	N081-00-3/203	Passage - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17301	ACTIVE	N	N081-00-3/203	Passage - Station Building - Archway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9433	ACTIVE	N	N081-00-3/204	Passage - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17302	ACTIVE	N	N081-00-3/204	Passage - Station Building - Archway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9434	ACTIVE	N	N081-00-3/205	Passage - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17303	ACTIVE	N	N081-00-3/205	Passage - Station Building - Archway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9435	ACTIVE	N	N081-00-3/261	Platform 1 - Southbound Fast - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N081-00 - Station Building - Archway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19026	ACTIVE	N	N081-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Archway Stn	Cable Ducts: Cement	Asbestos	Strongly Presumed				Platform Invert - Cable Duct No access within invert 2020 re-inspection as confined space team required.		1		N	YES
19490	ACTIVE	N	N081-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Archway Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform Invert - Various Cables No access within invert 2020 re-inspection as confined space team required.				N	YES
18992	ACTIVE	N	N081-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Archway Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Red Grit Bin - Fair				N	N
9436	ACTIVE	N	N081-00-3/262	Platform 2 - Northbound Fast - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17305	ACTIVE	N	N081-00-3/262	Platform 2 - Northbound Fast - Station Building - Archway Stn	Lead/Leading	Lead Paint/Lead	Known				Trackside - Black Paint at bottom contains lead - Fair				N	N
17306	ACTIVE	N	N081-00-3/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Archway Stn	Cable Ducts: Bitumen	Asbestos	Surveyed - Not Detected				Platform 2 Invert - Bitumen Cable Ducts below 3/731					YES
17987	ACTIVE	N	N081-00-3/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Archway Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - Various Cables No access within invert 2020 re-inspection as confined space team required.				N	YES
17304	ACTIVE	N	N081-00-3/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Archway Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Red Grit Bin - Fair				N	N
9437	ACTIVE	N	N081-00-3/661	Switch Room - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18491	ACTIVE	N	N081-00-3/661/FLR-01	Floor - 1 - Switch Room - Station Building - Archway Stn	Void	Asbestos	No Access: Presumed				Beneath Hatch on floor					YES
17307	ACTIVE	N	N081-00-3/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Archway Stn	Other Electrical Boxes	Asbestos	Presumed				Tunnel Lighting Box - ACM within to wall 1 No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score materials within.		1			
42542	ACTIVE	N	N081-00-3/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Archway Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1 x Tunnel Lighting Box No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score materials within.		1		N	N
9438	ACTIVE	N	N081-00-3/662	Switch Room - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
44950	ACTIVE	N	N081-00-3/662	Switch Room - Station Building - Archway Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Busbar		1		N	N
44951	ACTIVE	N	N081-00-3/662	Switch Room - Station Building - Archway Stn	Other Electrical Boxes	Asbestos	Presumed				1no Low Level Transformer Box - Insulation within		1		N	N



# Hazardous Material Asset Register - Summary



## N081-00 - Station Building - Archway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19027	ACTIVE	N	N081-00-3/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Archway Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes - 2 x 60 amps Insulation within. 1x Switch box removed  No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score materials within.		2		N	N
42540	ACTIVE	N	N081-00-3/662/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Archway Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1 X Train Describer  No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score materials within.		1		N	N
9439	ACTIVE	N	N081-00-3/663	Switch Room - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17309	ACTIVE	N	N081-00-3/663/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Archway Stn	Other Electrical Boxes	Asbestos	Presumed				MCB Distribution - Insulation within  No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score materials within.		1			
17308	INACTIVE	N	N081-00-3/663/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Archway Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes - Insulation within - HMU Re Inspection 20/08/15 - Switch boxes should have been recorded against 3/662 and not 3/663		2			
17310	INACTIVE	N	N081-00-3/663/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Archway Stn	Train Describers	Asbestos	Presumed				Train Describer Box - HMU Re Inspection 20/08/15 - This item should have been recorded against 3/662 and not 3/663		1			
17311	INACTIVE	N	N081-00-3/663/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Archway Stn	Other Electrical Boxes	Asbestos	Presumed				Low Level Transformer Box - Insulation within - HMU Re Inspection 20/08/15 - This item should have been recorded against 3/662 and not 3/663		1			
9440	ACTIVE	N	N081-00-3/664	Switch Room - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17312	ACTIVE	N	N081-00-3/664/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Archway Stn	Isolator Switches	Asbestos	Presumed				Red Spot Fuse Box - Insulation within  Presume 1x Combination Fuse Switch to wall - Photo DSC05260 Presume 1x electrical box to wall - Photo DSC05262  No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score materials within.		1			
44947	ACTIVE	N	N081-00-3/664/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Archway Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				High Level Equipment - Built 21/05/1999; W2 1 x 60amp Switch Box				N	N
9441	ACTIVE	N	N081-00-3/706	IMR - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N081-00 - Station Building - Archway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19028	ACTIVE	N	N081-00-3/706	IMR - Station Building - Archway Stn	Cable: Sheath	Asbestos	Strongly Presumed				15mm Cables going into Invert		2		N	N
17313	ACTIVE	N	N081-00-3/706	IMR - Station Building - Archway Stn	Other Boarding	Asbestos	Strongly Presumed				Paxoline Board				N	N
9442	ACTIVE	N	N081-00-3/712	Relay Room - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19029	ACTIVE	N	N081-00-3/712	Relay Room - Station Building - Archway Stn	Cable: Sheath	Asbestos	Strongly Presumed				50mm Cables going into Invert		1		N	N
17314	ACTIVE	N	N081-00-3/712	Relay Room - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Board					
17988	ACTIVE	N	N081-00-3/712 80143115	Relay Room - Station Building - Archway Stn Room Assets	Other Electrical Boxes	Asbestos	Strongly Presumed				Transformer Box on floor wall 2 and wall 3  No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score materials within.		1		N	N
42327	INACTIVE	N	N081-00-3/712	Relay Room - Station Building - Archway Stn	PCBs	Polychlorinated biphenyl	Presumed				2 x small silver cylinder PCB's - wall mounted 6 x medium silver cylinder - wall mounted		8		N	N
17315	ACTIVE	N	N081-00-3/712/ WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Archway Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse Boxes - Insulation within  No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score materials within.		2		N	N
9443	ACTIVE	N	N081-00-3/713	Relay Room - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17316	ACTIVE	N	N081-00-3/713	Relay Room - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Panels					
17318	INACTIVE	N	N081-00-3/713	Relay Room - Station Building - Archway Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				6 x PCB's - serial no.s not visible - showing signs of leakage. - Leaking as Reported Still Leaking - 16-03-2016		6		N	N
17317	ACTIVE	N	N081-00-3/713/ WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Archway Stn	Cable: Sheath	Asbestos	Strongly Presumed				Electrical box removed - cables cut back to trunking behind cabinet and encapsulated  2 x green 50mm Cables going to Track		2		N	N
53555	INACTIVE	N	N081-00-3/713/ WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Archway Stn	Other Boarding	Asbestos	Presumed				6x brown panels to equipment in cabinet wall 3					
9444	INACTIVE	N	N081-00-3/714	Relay Room - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N081-00 - Station Building - Archway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17146	ACTIVE	N	N081-00-3/714	Relay Room - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board					
41914	INACTIVE	N	N081-00-3/714/FLR-01	Floor - 1 - Relay Room - Station Building - Archway Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				4 x PCB's on floor by wall 1 - serial numbers and condition not visible - no access		4		N	N
17149	INACTIVE	N	N081-00-3/714/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Archway Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				6 x PCB's - Fair condition (1 x upper shelf, 5 x lower shelf)		6			
17147	ACTIVE	N	N081-00-3/714/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Archway Stn	Cable: Sheath	Asbestos	Presumed				Green Cable Cables (green) most likely to be nylon material				N	N
18863	ACTIVE	N	N081-00-3/714/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Archway Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westing House Box - Insulation within 1 x Small Blue Cylinder mounted on rack - Wall 3 - 16-03-2016 1 x Small Blue Cylinder mounted on rack high level wall 3 - 16/03/2016  No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score materials within.		1		N	N
42657	INACTIVE	N	N081-00-3/714/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Archway Stn	PCBs	Polychlorinated biphenyl	Presumed				1 x small blue Cylinder mounted on rack away from wall 3 hard to see Plus Another 1 x small blue Cylinder on rack high Level		1		N	N
17148	ACTIVE	N	N081-00-3/714/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Archway Stn	Other Boarding	Asbestos	Presumed				Paxoline Board  Presume black composite panels throughout to wall 3 - Photo DSC05274 Presume materials with rectifier box to wall 3 - Photo DSC05275 Presume black composite panels throughout to wall 1 - Photo DSC05276				N	N
9445	ACTIVE	N	N081-00-3/715	Relay Room - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18864	INACTIVE	N	N081-00-3/715	Relay Room - Station Building - Archway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
17150	ACTIVE	N	N081-00-3/715	Relay Room - Station Building - Archway Stn	Lead/Leading	Lead Paint/Lead	Known				Brown Paint contains lead					
53556	ACTIVE	N	N081-00-3/715/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Archway Stn	Other Boarding	Asbestos	Sampled – Not Detected				x 4 packing board to rack on wall 2 - ID non asbestos - NO. 4RS-JP-221113-R717876					
46862	ACTIVE	N	N081-00-3/715/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Archway Stn	Other Boarding	Asbestos	Known				Composite brown paxoline board to wall 2 - (Note new brown panel within box/ cabinet, throughout rest of room)					
9446	ACTIVE	N	N081-00-3/716	Relay Room - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17153	ACTIVE	N	N081-00-3/716	Relay Room - Station Building - Archway Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel					



# Hazardous Material Asset Register - Summary



## N081-00 - Station Building - Archway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18486	INACTIVE	N	N081-00-3/716	Relay Room - Station Building - Archway Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				4 x PCB's - Fair Condition. Serial no.s not visible - Fair		4		N	N
17154	ACTIVE	N	N081-00-3/716/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Archway Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westing House Box  Presume x4 Brown composite panels to wall 1 racking - Photo DSC05253  No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score materials within.		1		N	N
9447	ACTIVE	N	N081-00-3/731	Lobby - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18982	ACTIVE	N	N081-00-3/731	Lobby - Station Building - Archway Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9448	ACTIVE	N	N081-00-3/732	CER - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17151	ACTIVE	N	N081-00-3/732	CER - Station Building - Archway Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9449	ACTIVE	N	N081-00-3/761	Equipment Room - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17152	ACTIVE	N	N081-00-3/761	Equipment Room - Station Building - Archway Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9450	ACTIVE	N	N081-00-A/711	Plant Room - Station Building - Archway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
44955	ACTIVE	N	N081-00-A/711	Plant Room - Station Building - Archway Stn		Asbestos	Presumed				Material Within 1no Fan Panel to Floor by Door				N	N
44952	ACTIVE	N	N081-00-A/711	Plant Room - Station Building - Archway Stn	Mastic	Asbestos	Known				Putty to Joint at Fan Exhaust				N	N
44958	ACTIVE	N	N081-00-A/711	Plant Room - Station Building - Archway Stn	Other Electrical Boxes	Asbestos	Presumed				Materials Within Fuse/Switch Box to Micronic Filter Unit				N	N
18865	ACTIVE	N	N081-00-A/711	Plant Room - Station Building - Archway Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
44956	ACTIVE	N	N081-00-A/711	Plant Room - Station Building - Archway Stn	Other Electrical Boxes	Asbestos	Presumed				Materials Within Transformer By Wall 1				N	N
44957	ACTIVE	N	N081-00-A/711	Plant Room - Station Building - Archway Stn	Control Panels	Asbestos	Presumed				Materials Within Control Panel By Wall 1				N	N
44953	ACTIVE	N	N081-00-A/711	Plant Room - Station Building - Archway Stn	Mastic	Asbestos	Known				Mastic to A/C Metal Ductwork Flanges				N	N



# Hazardous Material Asset Register - Summary



## N081-00 - Station Building - Archway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44954	ACTIVE	N	N081-00-A/711/WAL-001	Wall: Internal - 1 - Plant Room - Station Building - Archway Stn	Rope Gaskets	Asbestos	Known				Gasket 1no to Seal of AHU Flange				N	N

## N083-00 - Station Building - Tufnell Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9451	ACTIVE	N	N083-00-1/001	Booking Hall - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
42312	ACTIVE	N	N083-00-1/001	Booking Hall - Station Building - Tufnell Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boxing - cables, cable management system within - Above entrance			R501951	N	N
17023	ACTIVE	N	N083-00-1/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Tufnell Park Stn	No Access	Asbestos	No Access: Presumed				Plaster on concrete slab			R501951	YES	N
42313	ACTIVE	N	N083-00-1/001/FLR-01	Floor - 1 - Booking Hall - Station Building - Tufnell Park Stn		Asbestos	Surveyed – Not Detected				Ceramic tiles on concrete slab			R501951	N	N
9452	ACTIVE	N	N083-00-1/011	Ticket Office - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
42236	ACTIVE	N	N083-00-1/011	Ticket Office - Station Building - Tufnell Park Stn		Asbestos	Surveyed – Not Detected				Above false ceiling - Plaster on concrete slab, plaster coving to main ceiling, A/C metal ductwork - new MMMF and Supalux, Supalux panels, RSJ			R501951	Y	N
42306	ACTIVE	N	N083-00-1/011	Ticket Office - Station Building - Tufnell Park Stn	Other Electrical Boxes	Asbestos	Surveyed – Not Detected				New electrical boxes throughout			R501951	N	N
17024	ACTIVE	N	N083-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Tufnell Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
17027	INACTIVE	N	N083-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Tufnell Park Stn	Void	Asbestos	Surveyed – Not Detected				Plaster, Solid above False Ceiling				YES	
17025	INACTIVE	N	N083-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Tufnell Park Stn	Void	Asbestos	Surveyed – Not Detected				Block Work, Trunking above False Ceiling				YES	
42305	ACTIVE	N	N083-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Tufnell Park Stn		Asbestos	Surveyed – Not Detected				Screed on concrete slab beneath false floor			R501951	N	Y
18703	ACTIVE	N	N083-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Tufnell Park Stn	No Access	Asbestos	No Access: Presumed				Lino (new) on metal / wooden computer tiles			R501951	N	N
9453	ACTIVE	N	N083-00-1/021	POM - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N083-00 - Station Building - Tufnell Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19148	ACTIVE	N	N083-00-1/021/CCO-01	Cash Counter - NC500 - POM - Station Building - Tufnell Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
42310	ACTIVE	N	N083-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Tufnell Park Stn		Asbestos	Surveyed – Not Detected				MMMF ceiling tiles on metal framework. Supalux panels.			R501951	N	N
42311	ACTIVE	N	N083-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Tufnell Park Stn		Asbestos	Surveyed – Not Detected				Concrete slab, A/C metal ducts - new (MMMD & supalux) gaitor new, RSJ above false ceiling			R501951	Y	N
42240	ACTIVE	N	N083-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Tufnell Park Stn		Asbestos	Surveyed – Not Detected				Lino (new) on metal / wooden computer tiles - computer tiles on concrete slab beneath false floor			R501951	Y	N
17026	INACTIVE	N	N083-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Tufnell Park Stn	No Access	Asbestos	No Access: Presumed				Concrete slab below computer tiles			R501951	N	Y
9454	ACTIVE	N	N083-00-1/031	Mess Room - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17028	ACTIVE	N	N083-00-1/031	Mess Room - Station Building - Tufnell Park Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
18704	ACTIVE	N	N083-00-1/031	Mess Room - Station Building - Tufnell Park Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LU Heater (Foam)					
17029	ACTIVE	N	N083-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Tufnell Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
17030	ACTIVE	N	N083-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Tufnell Park Stn	Void	Asbestos	Surveyed – Not Detected				Block Work, Supalux Boxing, Pipe Work, Fibre Glass				YES	
9455	ACTIVE	N	N083-00-1/036	Lobby - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
42307	ACTIVE	N	N083-00-1/036	Lobby - Station Building - Tufnell Park Stn		Asbestos	Surveyed – Not Detected				Above false ceiling - A/C metal ductwork - new (MMMF and Supalux) forming and within the false ceiling, plastic and metal - foam/mmmf insulation throughout			R501951	Y	N
17032	ACTIVE	N	N083-00-1/036/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Tufnell Park Stn		Asbestos	Surveyed – Not Detected				Block Work, Trunking				YES	
17031	ACTIVE	N	N083-00-1/036/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Tufnell Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
42237	ACTIVE	N	N083-00-1/036/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Tufnell Park Stn		Asbestos	Surveyed – Not Detected				MMMF ceiling tiles on metal framework to suspended ceiling, plaster on concrete slab above false ceiling, Supalux panels			R501951	N	N
18705	INACTIVE	N	N083-00-1/036/FLR-01	Floor - 1 - Lobby - Station Building - Tufnell Park Stn	No Access	Asbestos	No Access: Presumed				Ceramic tiles on concrete slab - base floor – no false floor			R501951	N	N



# Hazardous Material Asset Register - Summary



## N083-00 - Station Building - Tufnell Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9456	ACTIVE	N	N083-00-1/037	Toilet: Unisex - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17033	ACTIVE	N	N083-00-1/037/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Tufnell Park Stn	Void	Asbestos	Surveyed – Not Detected				Breeze Block, Glass Window - Wooden Frame; Metal Pipes above False Ceiling				YES	
19363	ACTIVE	N	N083-00-1/037/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Tufnell Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
9457	ACTIVE	N	N083-00-1/071	Circulation Area - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Surveyed – Asbestos Known				Durasteel Panels around all lift doors are a mixture of Asbestos and Non Asbestos types. Please contact the HMU if your work will disturb these panels					
45358	ACTIVE	N	N083-00-1/071	Circulation Area - Station Building - Tufnell Park Stn	Durasteel	Asbestos	Presumed				Durasteel Panels around all lift doors are a mixture of Asbestos and non asbestos types. Please contact the HMU if your work will disturb these panels				N	N
42314	ACTIVE	N	N083-00-1/071	Circulation Area - Station Building - Tufnell Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Above entrance door - Supalux boxing - cables, cable management systems within			R501951	N	N
17034	ACTIVE	N	N083-00-1/071	Circulation Area - Station Building - Tufnell Park Stn	Durasteel	Asbestos	No Access: Presumed				Durasteel Panels around all lift doors are a mixture of Asbestos and Non Asbestos types. Please contact the HMU if your work will disturb these panels					
42439	ACTIVE	N	N083-00-1/071	Circulation Area - Station Building - Tufnell Park Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel panel, <2m2, left hand side of upper landing entry side of lift, to left hand side of lift 1			R504176	N	N
18706	ACTIVE	N	N083-00-1/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Tufnell Park Stn	Void	Asbestos	Not Found during Inspection				Plaster on concrete slab, wooden panels Not Found on last inspection still presume  Not located in 2020 re-inspection.			R501951	N	N
9458	ACTIVE	N	N083-00-1/081	Lobby - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9459	ACTIVE	N	N083-00-1/236	Passage - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17036	ACTIVE	N	N083-00-1/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Tufnell Park Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Fibreglass Lagging; Block Work; Metal Ducts above False Ceiling				YES	
17035	ACTIVE	N	N083-00-1/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Tufnell Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
9460	ACTIVE	N	N083-00-1/237	Lobby - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N083-00 - Station Building - Tufnell Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42308	ACTIVE	N	N083-00-1/237	Lobby - Station Building - Tufnell Park Stn	Other Electrical Boxes	Asbestos	Surveyed – Not Detected				New Electrical Boxes throughout			R501951	N	N
42238	ACTIVE	N	N083-00-1/237	Lobby - Station Building - Tufnell Park Stn		Asbestos	Surveyed – Not Detected				Lino (new) on metal / wooden computer tiles			R501951	N	N
17037	INACTIVE	N	N083-00-1/237/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Tufnell Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
42239	ACTIVE	N	N083-00-1/237/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Tufnell Park Stn		Asbestos	Surveyed – Not Detected				A/C metal ductwork - new (MMMMF and Supalux, MMF ceiling tiles on metal framework, plaster on concrete, Plastic and metal pipework - foam forming and within suspended ceiling			R501951	N	N
17038	ACTIVE	N	N083-00-1/237/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Tufnell Park Stn	Void	Asbestos	Surveyed – Not Detected				Plaster on concrete, plastic and metal pipework, foam, above false ceiling			R501951	YES	N
17902	ACTIVE	N	N083-00-1/237/FLR-01	Floor - 1 - Lobby - Station Building - Tufnell Park Stn	Void	Asbestos	No Access: Presumed				Computer tiles on concrete slab beneath false floor			R501951	N	Y
9461	ACTIVE	N	N083-00-1/281	Locker Room - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18707	ACTIVE	N	N083-00-1/281	Locker Room - Station Building - Tufnell Park Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LU Heater - Foam Board					
17040	ACTIVE	N	N083-00-1/281/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Tufnell Park Stn	Void	Asbestos	Surveyed – Not Detected				Fibreglass Lagging Pipes; Plasterboard; Ducting above False Ceiling				YES	
17039	ACTIVE	N	N083-00-1/281/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Tufnell Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
20289	ACTIVE	N	N083-00-1/281/DORS	Doors - Locker Room - Station Building - Tufnell Park Stn		Lead Paint/Lead	Surveyed – Not Detected				Lead Paint Content. Door to Corridor					
20288	ACTIVE	N	N083-00-1/281/WLS	Walls: Internal - Locker Room - Station Building - Tufnell Park Stn		Lead Paint/Lead	Surveyed – Not Detected				Lead Paint content not detected in Cream Gloss on all walls					
9462	ACTIVE	N	N083-00-1/331	Station Control Room - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17041	ACTIVE	N	N083-00-1/331	Station Control Room - Station Building - Tufnell Park Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LU Heaters - Foam		2			
20273	ACTIVE	N	N083-00-1/331	Station Control Room - Station Building - Tufnell Park Stn		Lead Paint/Lead	Surveyed – Not Detected				Handrail / Ladder Lead Content - Report R410510 02/06/2014					
17043	ACTIVE	N	N083-00-1/331/CLG-01	Ceiling: Suspended - 1 - Station Control Room - Station Building - Tufnell Park Stn	Void	Asbestos	Surveyed – Not Detected				Tank Pipe Lagging - Fibreglass; Plasterboard; Concrete Ceiling above False Ceiling				YES	



# Hazardous Material Asset Register - Summary



## N083-00 - Station Building - Tufnell Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17042	ACTIVE	N	N083-00-1/331/CLG-01	Ceiling: Suspended - 1 - Station Control Room - Station Building - Tufnell Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
20287	ACTIVE	N	N083-00-1/331/DORS	Doors - Station Control Room - Station Building - Tufnell Park Stn		Lead Paint/Lead	Surveyed – Not Detected				Door to Corridor - Brown Varnish					
20281	ACTIVE	N	N083-00-1/331/DORS	Doors - Station Control Room - Station Building - Tufnell Park Stn		Lead Paint/Lead	Surveyed – Not Detected				Door to yard - Lead Paint Content					
18917	ACTIVE	N	N083-00-1/331/WAL-001	Wall: Internal - 1 - Station Control Room - Station Building - Tufnell Park Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
18481	ACTIVE	N	N083-00-1/331/WAL-002	Wall: Internal - 2 - Station Control Room - Station Building - Tufnell Park Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
18773	ACTIVE	N	N083-00-1/331/WAL-003	Wall: Internal - 3 - Station Control Room - Station Building - Tufnell Park Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
20276	ACTIVE	N	N083-00-1/331/WDW-01	Window - 1 - Station Control Room - Station Building - Tufnell Park Stn	Lead/Leading	Lead Paint/Lead	Known				Bars to window - lead content in paint					
20283	ACTIVE	N	N083-00-1/331/WDW-01	Window - 1 - Station Control Room - Station Building - Tufnell Park Stn		Lead Paint/Lead	Surveyed – Not Detected				Window Frame - Lead Paint					
20284	ACTIVE	N	N083-00-1/331/WDW-02	Window - 2 - Station Control Room - Station Building - Tufnell Park Stn		Lead Paint/Lead	Surveyed – Not Detected				Window Frame Lead Paint Content					
20277	ACTIVE	N	N083-00-1/331/WDW-02	Window - 2 - Station Control Room - Station Building - Tufnell Park Stn	Lead/Leading	Lead Paint/Lead	Known				Bars to Window Lead Paint Content					
20279	ACTIVE	N	N083-00-1/331/WDW-03	Window - 3 - Station Control Room - Station Building - Tufnell Park Stn	Lead/Leading	Lead Paint/Lead	Known				Lead Paint Content in Bars to Window					
20285	ACTIVE	N	N083-00-1/331/WDW-03	Window - 3 - Station Control Room - Station Building - Tufnell Park Stn		Lead Paint/Lead	Surveyed – Not Detected				Window frame - Lead Paint Content					
20286	ACTIVE	N	N083-00-1/331/WLS	Walls: Internal - Station Control Room - Station Building - Tufnell Park Stn		Lead Paint/Lead	Surveyed – Not Detected				All Walls - Cream Gloss					
9463	ACTIVE	N	N083-00-1/401	Bin Store - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17903	ACTIVE	N	N083-00-1/401	Bin Store - Station Building - Tufnell Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Cupboard - Supalux Panels					



# Hazardous Material Asset Register - Summary



## N083-00 - Station Building - Tufnell Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17044	ACTIVE	N	N083-00-1/401/CLG-01	Ceiling: Solid - 1 - Bin Store - Station Building - Tufnell Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels					
18774	ACTIVE	N	N083-00-1/401/CLG-01	Ceiling: Solid - 1 - Bin Store - Station Building - Tufnell Park Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling				YES	
9464	ACTIVE	N	N083-00-1/416	Toilet: Male - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17045	ACTIVE	N	N083-00-1/416	Toilet: Male - Station Building - Tufnell Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9465	ACTIVE	N	N083-00-1/417	Toilet: Female - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17046	ACTIVE	N	N083-00-1/417	Toilet: Female - Station Building - Tufnell Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9466	ACTIVE	N	N083-00-1/631	Stairs: Spiral - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17048	ACTIVE	N	N083-00-1/631	Stairs: Spiral - Station Building - Tufnell Park Stn	Pipe Lagging	Asbestos	Surveyed – Not Detected				Non Asbestos					
17047	ACTIVE	N	N083-00-1/631/CLG-01	Ceiling: Suspended - 1 - Spiral Stairs - Station Building - Tufnell Park Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Caulking - Non Asbestos					
9467	ACTIVE	N	N083-00-1/661	Switch Room - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17049	ACTIVE	N	N083-00-1/661	Switch Room - Station Building - Tufnell Park Stn	Isolator Switches	Asbestos	Strongly Presumed				W7,9 Switch Boxes - Insulation within 1 x 30 amps, 6 x 60 amps, 2 x 100 amps  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		9			
18775	ACTIVE	N	N083-00-1/661	Switch Room - Station Building - Tufnell Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels					
17050	ACTIVE	N	N083-00-1/661	Switch Room - Station Building - Tufnell Park Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es)  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		3			
9468	ACTIVE	N	N083-00-1/663	Switch Room - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N083-00 - Station Building - Tufnell Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9469	ACTIVE	N	N083-00-1/664	Switch Cupboard - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17051	ACTIVE	N	N083-00-1/664	Switch Cupboard - Station Building - Tufnell Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9470	ACTIVE	N	N083-00-1/665	Switch Room - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17904	ACTIVE	N	N083-00-1/665	Switch Room - Station Building - Tufnell Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
9471	ACTIVE	N	N083-00-1/746	SCR - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17052	ACTIVE	N	N083-00-1/746	SCR - Station Building - Tufnell Park Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
17053	ACTIVE	N	N083-00-1/746/CLG-01	Ceiling: Solid - 1 - SCR - Station Building - Tufnell Park Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
17054	ACTIVE	N	N083-00-1/791	Vent Shaft - Station Building - Tufnell Park Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Caulking - Non Asbestos					
18776	ACTIVE	N	N083-00-1/901	Vent Shaft - Station Building - Tufnell Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Sealed Door into Vent Shaft					
17055	ACTIVE	N	N083-00-1/901/CLG-01	Ceiling: Solid - 1 - Vent Shaft - Station Building - Tufnell Park Stn	No Access	Asbestos	No Access: Presumed				No Access High Level					
9472	ACTIVE	N	N083-00-1/951	Pump Room - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17056	ACTIVE	N	N083-00-1/951	Pump Room - Station Building - Tufnell Park Stn	No Access	Asbestos	Surveyed – Not Detected				surveyed in original type 2 management survey R19038					
9473	ACTIVE	N	N083-00-1/952	Disused Room - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18777	ACTIVE	N	N083-00-1/952/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Tufnell Park Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
17058	ACTIVE	N	N083-00-1/952/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Tufnell Park Stn	Void	Asbestos	Surveyed – Not Detected				Plaster on Solid Walls & Ceiling; Wooden Match Board above window - above False Ceiling				YES	
17057	ACTIVE	N	N083-00-1/952/FLR-01	Floor - 1 - Disused Room - Station Building - Tufnell Park Stn	Void	Asbestos	Surveyed – Not Detected				Wooden Battens; Loose Clinker Concrete beneath Quarry Tiles; Wooden Floor Boards, Wooden Skirting					YES



# Hazardous Material Asset Register - Summary



## N083-00 - Station Building - Tufnell Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17059	ACTIVE	N	N083-00-1/952/WAL-001	Wall: Internal - 1 - Disused Room - Station Building - Tufnell Park Stn		Anthrax	Surveyed – Not Detected				No Anthrax Detected					
9474	ACTIVE	N	N083-00-2/131	LMR - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9475	ACTIVE	N	N083-00-2/201	Passage - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17060	ACTIVE	N	N083-00-2/201	Passage - Station Building - Tufnell Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed					
9476	ACTIVE	N	N083-00-2/202	Passage - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20016	ACTIVE	N	N083-00-2/202	Passage - Station Building - Tufnell Park Stn	No Access	Asbestos	Surveyed – Not Detected				Lift lobby					
9477	ACTIVE	N	N083-00-2/203	Passage - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17061	ACTIVE	N	N083-00-2/203	Passage - Station Building - Tufnell Park Stn	No Access	Asbestos	Surveyed – Not Detected				Entering to lift lobby					
9478	ACTIVE	N	N083-00-2/204	Passage - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18778	ACTIVE	N	N083-00-2/204	Passage - Station Building - Tufnell Park Stn	No Access	Asbestos	Surveyed – Not Detected				Lift lobby					
9479	ACTIVE	N	N083-00-2/205	Passage - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Surveyed – Asbestos Known									
42067	ACTIVE	N	N083-00-2/205	Passage - Station Building - Tufnell Park Stn	Durasteel	Asbestos	Known				Durasteel Panels around all lift doors are a mixture of Asbestos and Non Asbestos types. Please contact the HMU if your work will disturb these panels					
17062	ACTIVE	N	N083-00-2/205	Passage - Station Building - Tufnell Park Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Ring Caulking - Non Asbestos					
9480	ACTIVE	N	N083-00-2/206	Passage - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Surveyed – Asbestos Known									
17063	ACTIVE	N	N083-00-2/206	Passage - Station Building - Tufnell Park Stn	Durasteel	Asbestos	No Access: Presumed				Durasteel Panels around all lift doors are a mixture of Asbestos and Non Asbestos types. Please contact the HMU if your work will disturb these panels					



# Hazardous Material Asset Register - Summary



## N083-00 - Station Building - Tufnell Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9481	ACTIVE	N	N083-00-2/207	Passage - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17905	ACTIVE	N	N083-00-2/207	Passage - Station Building - Tufnell Park Stn	No Access	Asbestos	Surveyed – Not Detected				Passage way					
9482	ACTIVE	N	N083-00-2/208	Passage - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17064	ACTIVE	N	N083-00-2/208	Passage - Station Building - Tufnell Park Stn	No Access	Asbestos	Surveyed – Not Detected				Passageway					
9483	ACTIVE	N	N083-00-2/209	Passage - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18779	ACTIVE	N	N083-00-2/209	Passage - Station Building - Tufnell Park Stn	No Access	Asbestos	No Access: Presumed				Passageway to stairs					
9484	ACTIVE	N	N083-00-2/261	Platform 1 - Northbound Fast - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17065	ACTIVE	N	N083-00-2/261	Platform 1 - Northbound Fast - Station Building - Tufnell Park Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Ring Caulking - Non Asbestos					
18780	ACTIVE	N	N083-00-2/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Tufnell Park Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - Various Cables					YES
17066	ACTIVE	N	N083-00-2/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Tufnell Park Stn	Gasket :Pipework	Asbestos	Strongly Presumed				Platform 1 Invert - 3 x Gaskets - 20m along from 2/731 platform side					YES
9485	ACTIVE	N	N083-00-2/401	Store - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17069	ACTIVE	N	N083-00-2/401/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Tufnell Park Stn	Void	Asbestos	No Access: Presumed				Above Supalux Ceiling				YES	
17906	ACTIVE	N	N083-00-2/401/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Tufnell Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
17068	ACTIVE	N	N083-00-2/401/FLR-01	Floor - 1 - Store - Station Building - Tufnell Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel under Stairs					
9486	ACTIVE	N	N083-00-2/601	Stairs: Linear - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17070	ACTIVE	N	N083-00-2/601	Stairs: Linear - Station Building - Tufnell Park Stn	No Access	Asbestos	Surveyed – Not Detected				Stairs					



# Hazardous Material Asset Register - Summary



## N083-00 - Station Building - Tufnell Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9487	ACTIVE	N	N083-00-2/602	Stairs: Linear - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17071	ACTIVE	N	N083-00-2/602	Stairs: Linear - Station Building - Tufnell Park Stn	No Access	Asbestos	Surveyed - Not Detected				Stairs					
9488	ACTIVE	N	N083-00-2/603	Stairs: Linear - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18482	ACTIVE	N	N083-00-2/603	Stairs: Linear - Station Building - Tufnell Park Stn	No Access	Asbestos	Surveyed - Not Detected				Lobby to stairs					
9489	ACTIVE	N	N083-00-2/604	Stairs: Linear - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17072	ACTIVE	N	N083-00-2/604	Stairs: Linear - Station Building - Tufnell Park Stn	No Access	Asbestos	Surveyed - Not Detected				Stairs					
18781	ACTIVE	N	N083-00-2/636	Overbridge - Station Building - Tufnell Park Stn	No Access	Asbestos	Surveyed - Not Detected									
17073	ACTIVE	N	N083-00-2/637	Overbridge - Station Building - Tufnell Park Stn	No Access	Asbestos	Surveyed - Not Detected				Over ridge					
9490	ACTIVE	N	N083-00-2/661	Switch Room - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17074	ACTIVE	N	N083-00-2/661	Switch Room - Station Building - Tufnell Park Stn	Isolator Switches	Asbestos	Strongly Presumed				W3,4 Switch Boxes - Insulation Within - 3 x 100 amps, 1 x 200 amps, 3 x 60 amps  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within  Wall 1- 3no. Switch boxes. Strongly presumed chrysotile within - photo DSC04511 Wall 3 - 1no. Transformer box. Presumed chrysotile within - DSC04512		7			
18918	ACTIVE	N	N083-00-2/661	Switch Room - Station Building - Tufnell Park Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Partition Wall					
9491	ACTIVE	N	N083-00-2/711	Relay Room - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
42902	ACTIVE	N	N083-00-2/711	Relay Room - Station Building - Tufnell Park Stn	Other Electrical Boxes	Asbestos	Presumed				600v electrical box - Presumed asbestos insulation within  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1			



# Hazardous Material Asset Register - Summary



## N083-00 - Station Building - Tufnell Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42903	INACTIVE	N	N083-00-2/711	Relay Room - Station Building - Tufnell Park Stn	PCBs	Polychlorinated biphenyl	Presumed				Presumed PCB's within Roller Shutter Cabinet					
17075	INACTIVE	N	N083-00-2/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tufnell Park Stn	Isolator Switches	Asbestos	Strongly Presumed				Electrical Boxes - insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1			
53595	ACTIVE	N	N083-00-2/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tufnell Park Stn	Cable Ducts: Cement	Asbestos	Presumed				filled in duct to cabinet going into invert					
53594	ACTIVE	N	N083-00-2/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tufnell Park Stn	Cable: Sheath	Asbestos	Presumed				presumed asbestos cables to bunch - within cabinet wall 1					
53592	ACTIVE	N	N083-00-2/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tufnell Park Stn	Other Boarding	Asbestos	Presumed				rack 2 inside roller shutter to wall 1 - 6x composite brown boarding to equipment					
53593	ACTIVE	N	N083-00-2/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Tufnell Park Stn	Other Boarding	Asbestos	Presumed				brown composite board to box on wall 2					
18213	ACTIVE	N	N083-00-2/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Tufnell Park Stn	Cable: Sheath	Asbestos	Strongly Presumed				2x Green Cables 600 volts going into Inverts		2			
9492	ACTIVE	N	N083-00-2/731	CER - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18782	ACTIVE	N	N083-00-2/731/WAL-002	Wall: Internal - 2 - CER - Station Building - Tufnell Park Stn	Cable: Sheath	Asbestos	Strongly Presumed				Green Cables going into Inverts		2			
17076	ACTIVE	N	N083-00-2/731/WAL-002	Wall: Internal - 2 - CER - Station Building - Tufnell Park Stn	Cable: Sheath	Asbestos	Strongly Presumed				White Cables going into Inverts		1			
9493	ACTIVE	N	N083-00-2/732	CER - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18783	ACTIVE	N	N083-00-2/732	CER - Station Building - Tufnell Park Stn	Other Boarding	Asbestos	Strongly Presumed				Paxoline Board No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within Additional item - 2no. Switch boxes to wall 4. Strongly presumed chrysotile within - photo DSC04519					
17077	ACTIVE	N	N083-00-2/732/FLR-01	Floor - 1 - CER - Station Building - Tufnell Park Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
17078	ACTIVE	N	N083-00-2/732/WAL-002	Wall: Internal - 2 - CER - Station Building - Tufnell Park Stn	Isolator Switches	Asbestos	No Access: Presumed				Switch Boxes - Insulation within - 2 x 60 amps		2			



# Hazardous Material Asset Register - Summary



## N083-00 - Station Building - Tufnell Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9494	ACTIVE	N	N083-00-2/733	CER - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17079	ACTIVE	N	N083-00-2/733	CER - Station Building - Tufnell Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9495	ACTIVE	N	N083-00-2/761	Computer Equipment Cupboard - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17080	ACTIVE	N	N083-00-2/761	Computer Equipment Cupboard - Station Building - Tufnell Park Stn	No Access	Asbestos	Surveyed – Not Detected				New Electrical Cabinets					
9496	ACTIVE	N	N083-00-2/762	Computer Equipment Cupboard - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17081	ACTIVE	N	N083-00-2/762	Computer Equipment Cupboard - Station Building - Tufnell Park Stn	No Access	Asbestos	Surveyed – Not Detected				New Electrical Cabinets					
9497	ACTIVE	N	N083-00-2/763	Computer Equipment Cupboard - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18784	ACTIVE	N	N083-00-2/763	Computer Equipment Cupboard - Station Building - Tufnell Park Stn	No Access	Asbestos	Surveyed – Not Detected				New Electrical Cabinets					
17082	ACTIVE	N	N083-00-2/791	Vent Shaft - Station Building - Tufnell Park Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Rings - Caulking					
9498	ACTIVE	N	N083-00-3/081	Lobby - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17083	ACTIVE	N	N083-00-3/081	Lobby - Station Building - Tufnell Park Stn	Other Electrical Boxes	Asbestos	Not Found during Inspection				No asbestos containing materials within 3/081 See 3/711 (Rooms connected)					
9499	ACTIVE	N	N083-00-3/121	Platform Invert - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18785	ACTIVE	N	N083-00-3/121	Platform Invert - Station Building - Tufnell Park Stn		Asbestos	Surveyed – Not Detected				Bitumen Cable Ducts & Insulation to Ceiling					
17907	ACTIVE	N	N083-00-3/121	Platform Invert - Station Building - Tufnell Park Stn	Cable Ducts: Cement	Asbestos	Strongly Presumed				Cement Cable Ducts - Chrysotile No access into platform invert during 2020 re-inspection during traffic hours.					
17084	ACTIVE	N	N083-00-3/121	Platform Invert - Station Building - Tufnell Park Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - Various Cables. Encapsulation of up to 10 x Cables					
9500	ACTIVE	N	N083-00-3/262	Platform 2 - Southbound Fast - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N083-00 - Station Building - Tufnell Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17085	ACTIVE	N	N083-00-3/262	Platform 2 - Southbound Fast - Station Building - Tufnell Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9501	ACTIVE	N	N083-00-3/662	Switch Room - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17087	ACTIVE	N	N083-00-3/662	Switch Room - Station Building - Tufnell Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel					
18919	ACTIVE	N	N083-00-3/662/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Tufnell Park Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Westinghouse Box - Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1			
17088	ACTIVE	N	N083-00-3/662/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Tufnell Park Stn	Cable: Sheath	Asbestos	Strongly Presumed				Green Cables going into Inverts No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2			
9502	ACTIVE	N	N083-00-3/663	Switch Cupboard - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18786	ACTIVE	N	N083-00-3/663	Switch Cupboard - Station Building - Tufnell Park Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Transformer Box(es) No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1			
9503	ACTIVE	N	N083-00-3/664	Switch Cupboard - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17089	ACTIVE	N	N083-00-3/664	Switch Cupboard - Station Building - Tufnell Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9504	ACTIVE	N	N083-00-3/711	Relay Room - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42900	ACTIVE	N	N083-00-3/711	Relay Room - Station Building - Tufnell Park Stn	Other Electrical Boxes	Asbestos	Presumed				600v electrical box - Presumed asbestos insulating materials within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1			
42901	INACTIVE	N	N083-00-3/711	Relay Room - Station Building - Tufnell Park Stn	PCBs	Polychlorinated biphenyl	Presumed				Presumed PCB's within Roller Shutter cabinet					
53588	ACTIVE	N	N083-00-3/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tufnell Park Stn	Other Electrical Boxes	Asbestos	Presumed				2 old style CTB boxes wall 1					



# Hazardous Material Asset Register - Summary



## N083-00 - Station Building - Tufnell Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17908	ACTIVE	N	N083-00-3/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Tufnell Park Stn	Cable: Sheath	Asbestos	Strongly Presumed				2x 50cm Green Cables going into Inverts		2			
53587	ACTIVE	N	N083-00-3/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Tufnell Park Stn	Other Boarding	Asbestos	Presumed				brown composite materials to box on wall 2					
53589	ACTIVE	N	N083-00-3/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Tufnell Park Stn	Other Boarding	Asbestos	Presumed				within roller shutter 1 8 x paxoline board to equipment on rack					
53590	ACTIVE	N	N083-00-3/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Tufnell Park Stn	Cable: Sheath	Asbestos	Strongly Presumed				asbestos cables to duct in roller cabinet 2 wall 3					
17090	ACTIVE	N	N083-00-3/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Tufnell Park Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Westinghouse Box - Insulation within		1			
53591	ACTIVE	N	N083-00-3/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Tufnell Park Stn	Cable Ducts: Cement	Asbestos	Presumed				filled in duct to roller cabinet wall 3					
9505	ACTIVE	N	N083-00-3/731	Switch Room - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17091	ACTIVE	N	N083-00-3/731/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Tufnell Park Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling				YES	
18483	ACTIVE	N	N083-00-3/731/FLR-01	Floor - 1 - Switch Room - Station Building - Tufnell Park Stn	Void	Asbestos	No Access: Presumed				Beneath Hatch to flooded Invert					YES
42216	ACTIVE	N	N083-00-A/131	LMR - Station Building - Tufnell Park Stn	Other Boarding	Asbestos	Removed				Lift Controller 2 - 2m <sup>2</sup> Black Composite Panel within Lift Controller 2 Removed by asbestos removal contractors (appointed by HMU) on behalf of the Lift Refurbishment Project ES2953c & ES2953d, Edenbeck, date of removal 18/07/15	2			N	N
42201	ACTIVE	N	N083-00-A/131	LMR - Station Building - Tufnell Park Stn	Durasteel	Asbestos	Room: Surveyed – Asbestos Known				Lift Shaft 2 -30m <sup>2</sup> Durasteel Panels to shaft (PLEASE BE AWARE THAT SOME PANELS HAVE BEEN IDENTIFIED AS CONTAINING ASBESTOS PLEASE CONTACT THIS UNIT IF YOUR WORK WILL DISTURB THESE PANELS)				N	N
42214	ACTIVE	N	N083-00-A/131	LMR - Station Building - Tufnell Park Stn	Other Boarding	Asbestos	Removed				Lift Controller 1 - 2m <sup>2</sup> Black composite panel within Lift Motor Room Removed by asbestos removal contractors (appointed by HMU) on behalf of the Lift Refurbishment Project ES2953c & ES2953d, Edenbeck, date of removal 18/07/15	2			N	N



# Hazardous Material Asset Register - Summary



## N083-00 - Station Building - Tufnell Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42186	ACTIVE	N	N083-00-A/131	LMR - Station Building - Tufnell Park Stn	Other Electrical Boxes	Asbestos	Removed				2 x Circuit Breakers & Busbar Removed by projects		2		N	N
42187	ACTIVE	N	N083-00-A/131	LMR - Station Building - Tufnell Park Stn	Gasket :Pipework	Asbestos	Known				Gasket to Vent Duct				N	N
42191	ACTIVE	N	N083-00-A/131	LMR - Station Building - Tufnell Park Stn	Other Boarding	Asbestos	Strongly Presumed				Material behind joints in the vent chamber				N	N
42196	ACTIVE	N	N083-00-A/131	LMR - Station Building - Tufnell Park Stn	Durasteel	Asbestos	Room: Surveyed – Asbestos Known				Lift Shaft 1 -30m <sup>2</sup> Durasteel Panels to shaft (PLEASE BE AWARE THAT SOME PANELS HAVE BEEN IDENTIFIED AS CONTAINING ASBESTOS PLEASE CONTACT THIS UNIT IF YOUR WORK WILL DISTURB THESE PANELS)				N	N
42195	ACTIVE	N	N083-00-A/131	LMR - Station Building - Tufnell Park Stn	Caulking	Asbestos	Surveyed – Not Detected				Lift Shaft 1 - Tunnel Caulking				N	N
42202	ACTIVE	N	N083-00-A/131	LMR - Station Building - Tufnell Park Stn	Cable: Sheath	Asbestos	Sampled – Not Detected				Lift Shaft 2 - 3 x 25mm Woven Sheath Cables  4-RAIL sampled Cable sheath, 7m, to cables NADIS  No access into lift shaft during 2020 re-inspection. Permit required with L&E		2		N	N
42217	ACTIVE	N	N083-00-A/131	LMR - Station Building - Tufnell Park Stn		Asbestos	Sampled – Not Detected				Lift Controller 2 - 6 x Brown Composite Panels throughout Lift Motor Room to Lift Controller 2					
42199	ACTIVE	N	N083-00-A/131	LMR - Station Building - Tufnell Park Stn	Cable: Sheath	Asbestos	No Access: Presumed				Lift Shaft 1 - 3x 25mm Woven Sheath Cables Possible left in shaft by Projects		1		N	N
42206	ACTIVE	N	N083-00-A/131	LMR - Station Building - Tufnell Park Stn	Durasteel	Asbestos	Room: Surveyed – Asbestos Known				LIFT SHAFT 1 & 2 PLEASE BE AWARE THAT SOME PANELS HAVE BEEN IDENTIFIED AS CONTAINING ASBESTOS PLEASE CONTACT THE HAZARDOUS MATERIALS UNIT IF YOUR WORK WILL DISTURB THESE PANELS				N	N
45357	ACTIVE	N	N083-00-A/131	LMR - Station Building - Tufnell Park Stn	Durasteel	Asbestos	Not Found during Inspection				Lift Shaft 2 - Durasteel panels to lift shaft (See report R488651)				N	N
42215	ACTIVE	N	N083-00-A/131	LMR - Station Building - Tufnell Park Stn	Other Boarding	Asbestos	Sampled – Not Detected				6 x Brown Composite Panels throughout Lift Motor Room - to Lift Controller 1		6		N	N
45356	ACTIVE	N	N083-00-A/131	LMR - Station Building - Tufnell Park Stn	Durasteel	Asbestos	Not Found during Inspection				Lift Shaft 1 - Durasteel panels to lift shaft (See report R488651)				N	N
42200	ACTIVE	N	N083-00-A/131	LMR - Station Building - Tufnell Park Stn	Caulking	Asbestos	Surveyed – Not Detected				Lift Shaft 2 - Tunnel Caulking				N	N
42194	ACTIVE	N	N083-00-A/131	LMR - Station Building - Tufnell Park Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Yellow Steps - lead paint strongly presumed 16/03/2016 steps have been removed				N	N
42193	ACTIVE	N	N083-00-A/131	LMR - Station Building - Tufnell Park Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Red Paint on Beams				N	N



# Hazardous Material Asset Register - Summary



## N083-00 - Station Building - Tufnell Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42184	ACTIVE	N	N083-00-A/131/CLG-01	Ceiling: Solid - 1 - LMR - Station Building - Tufnell Park Stn	No Access	Asbestos	No Access: Presumed				No access above false ceiling					
42189	ACTIVE	N	N083-00-A/131/WAL-001	Wall: Internal - 1 - LMR - Station Building - Tufnell Park Stn	Other Electrical Boxes	Asbestos	Removed				0.5m <sup>2</sup> Controller box 1&2 - Sulluminite within boxes Removed by Projects				N	N
42192	ACTIVE	N	N083-00-A/131/WAL-002	Wall: Internal - 2 - LMR - Station Building - Tufnell Park Stn	Other Electrical Boxes	Asbestos	Removed				0.5m <sup>2</sup> Distribution board - Sulluminite within boxes Removed by Projects				N	N
42190	ACTIVE	N	N083-00-A/131/WAL-004	Wall: Internal - 4 - LMR - Station Building - Tufnell Park Stn	Isolator Switches	Asbestos	Removed				1x Switch box Removed by projects		1		N	N
42188	ACTIVE	N	N083-00-A/131/WAL-004	Wall: Internal - 4 - LMR - Station Building - Tufnell Park Stn	Other Electrical Boxes	Asbestos	Removed				1x Transformer box Removed by Projects		1		N	N
42164	ACTIVE	N	N083-00-A/131/WAL-004	Wall: Internal - 4 - LMR - Station Building - Tufnell Park Stn	Isolator Switches	Asbestos	Removed				3 x Switch Boxes - Insulation within Removed by projects		3		N	N
9506	ACTIVE	N	N083-00-A/576	Ladder - Station Building - Tufnell Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18788	ACTIVE	N	N083-00-A/576	Ladder - Station Building - Tufnell Park Stn	Other Boarding	Asbestos	Surveyed – Not Detected				30m <sup>2</sup> Boarding to lift access - Non Asbestos					
18484	ACTIVE	N	N083-00-A/576	Ladder - Station Building - Tufnell Park Stn	Durasteel	Asbestos	Surveyed – Not Detected				Flammable Store (Durasteel) - Non Asbestos					
42667	ACTIVE	N	N083-00-A/576	Ladder - Station Building - Tufnell Park Stn	Lead/Leading	Lead Paint/Lead	Sampled – Not Detected				Black matt paint to beam in Lift Motor Room A/576 0.11%			R488652	N	N
42666	ACTIVE	N	N083-00-A/576	Ladder - Station Building - Tufnell Park Stn	Lead/Leading	Lead Paint/Lead	Sampled – Not Detected				Red gloss paint to beam in Lift Motor Room A/576 0.69%			R488652	N	N
42665	ACTIVE	N	N083-00-A/576	Ladder - Station Building - Tufnell Park Stn	Lead/Leading	Lead Paint/Lead	Sampled – Not Detected				Red gloss paint to beam in Lift Motor Room A/576 0.52%			R488652	N	N
42664	ACTIVE	N	N083-00-A/576	Ladder - Station Building - Tufnell Park Stn	Lead/Leading	Lead Paint/Lead	Sampled – Not Detected				Red gloss paint to beam in Lift Motor Room A/576 0.58%			R488652	N	N
17105	ACTIVE	N	N083-00-A/576/WAL-001	Wall: Internal - 1 - Ladder - Station Building - Tufnell Park Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel Panel					
17104	ACTIVE	N	N083-00-A/576/WAL-001	Wall: Internal - 1 - Ladder - Station Building - Tufnell Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel					



# Hazardous Material Asset Register - Summary



## N085-00 - Station Building - Kentish Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9507	ACTIVE	N	N085-00-1/001	Booking Hall - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18530	ACTIVE	N	N085-00-1/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Kentish Town Stn		Anthrax	Surveyed - Not Detected				No Anthrax Detected				YES	
16853	ACTIVE	N	N085-00-1/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Kentish Town Stn	Void	Asbestos	Surveyed - Not Detected				Concrete, plaster, render and metal work. All cables PVC above Concrete Ceiling				YES	
9508	ACTIVE	N	N085-00-1/011	Ticket Office - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
9509	ACTIVE	N	N085-00-1/021	POM - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16855	ACTIVE	N	N085-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Kentish Town Stn	Void	Asbestos	Surveyed - Not Detected				Beneath Computer Flooring					YES
9510	ACTIVE	N	N085-00-1/031	Mess Room - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16857	ACTIVE	N	N085-00-1/031	Mess Room - Station Building - Kentish Town Stn		Asbestos	Surveyed - Not Detected				Acoustic Panel below sink					
16856	ACTIVE	N	N085-00-1/031	Mess Room - Station Building - Kentish Town Stn	LUL Heaters	Asbestos	Surveyed - Not Detected				LUL Heater - Foam					
16858	ACTIVE	N	N085-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Kentish Town Stn	Void	Asbestos	Surveyed - Not Detected				Concrete, Plaster above False Ceiling				YES	
9511	ACTIVE	N	N085-00-1/036	Toilet: Unisex - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16859	ACTIVE	N	N085-00-1/036	Toilet: Unisex - Station Building - Kentish Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9512	ACTIVE	N	N085-00-1/071	Circulation Area - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18531	ACTIVE	N	N085-00-1/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Kentish Town Stn	Void	Asbestos	Surveyed - Not Detected				Above False Ceiling - No Anthrax Detected; Above Bulk Heads by escalators Concrete, plaster, render and metal work. All cables PVC.				YES	
9513	ACTIVE	N	N085-00-1/081	Lobby - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N085-00 - Station Building - Kentish Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16860	ACTIVE	N	N085-00-1/081/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Kentish Town Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling				YES	
9514	ACTIVE	N	N085-00-1/201	Passage - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16861	ACTIVE	N	N085-00-1/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Kentish Town Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard					
9515	ACTIVE	N	N085-00-1/236	Lobby - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19132	ACTIVE	N	N085-00-1/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Kentish Town Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux					
16862	ACTIVE	N	N085-00-1/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Kentish Town Stn	Void	Asbestos	No Access: Presumed				Above Supalux				YES	
9516	ACTIVE	N	N085-00-1/237	Passage - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16863	ACTIVE	N	N085-00-1/237	Passage - Station Building - Kentish Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9517	ACTIVE	N	N085-00-1/281	Station Control Room - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16864	ACTIVE	N	N085-00-1/281/CLG-01	Ceiling: Suspended - 1 - Station Control Room - Station Building - Kentish Town Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Skirting Board Plaster					
18908	ACTIVE	N	N085-00-1/281/CLG-01	Ceiling: Suspended - 1 - Station Control Room - Station Building - Kentish Town Stn	Void	Asbestos	No Access: Presumed				Above Soft Board; Skirting Board Plaster False ceiling				YES	
9518	ACTIVE	N	N085-00-1/406	SVC - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16865	ACTIVE	N	N085-00-1/406	SVC - Station Building - Kentish Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9519	ACTIVE	N	N085-00-1/411	Locker Room - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16867	ACTIVE	N	N085-00-1/411/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Kentish Town Stn	Void	Asbestos	No Access: Presumed				Above Supalux				YES	



# Hazardous Material Asset Register - Summary



## N085-00 - Station Building - Kentish Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16866	ACTIVE	N	N085-00-1/411/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Kentish Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
18532	ACTIVE	N	N085-00-1/411/FLR-01	Floor - 1 - Locker Room - Station Building - Kentish Town Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Skirting Board Plaster					
9520	ACTIVE	N	N085-00-1/631	Stairs: Spiral - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16868	ACTIVE	N	N085-00-1/631	Stairs: Spiral - Station Building - Kentish Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9521	ACTIVE	N	N085-00-1/661	Switch Room - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18533	ACTIVE	N	N085-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Kentish Town Stn	Isolator Switches	Asbestos	Known				Switch box, insulation within 1 x 30 amps. Switch Boxes confirmed to contain Flash guards, Arc Chutes & Cementious Blocks - All containing Asbestos have been labelled		1		N	N
9522	ACTIVE	N	N085-00-1/662	Switch Cupboard - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16869	ACTIVE	N	N085-00-1/662	Switch Cupboard - Station Building - Kentish Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9523	ACTIVE	N	N085-00-1/663	Switch Cupboard - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16870	ACTIVE	N	N085-00-1/663/CLG-01	Ceiling: Suspended - 1 - Switch Cupboard - Station Building - Kentish Town Stn	Void	Asbestos	No Access: Presumed				Above Supalux				YES	
19133	ACTIVE	N	N085-00-1/663/CLG-01	Ceiling: Suspended - 1 - Switch Cupboard - Station Building - Kentish Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
9524	ACTIVE	N	N085-00-1/746	SCR - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16871	ACTIVE	N	N085-00-1/746	SCR - Station Building - Kentish Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9525	ACTIVE	N	N085-00-1/991	Lobby - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16872	ACTIVE	N	N085-00-1/991	Lobby - Station Building - Kentish Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N085-00 - Station Building - Kentish Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9526	ACTIVE	N	N085-00-1/992	Locker Room - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16873	ACTIVE	N	N085-00-1/992	Locker Room - Station Building - Kentish Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9527	ACTIVE	N	N085-00-1/993	Store - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16874	ACTIVE	N	N085-00-1/993	Store - Station Building - Kentish Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9528	ACTIVE	N	N085-00-1/994	Store - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16875	ACTIVE	N	N085-00-1/994	Store - Station Building - Kentish Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9529	ACTIVE	N	N085-00-2/151	UMC - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
43249	ACTIVE	N	N085-00-2/151	UMC - Station Building - Kentish Town Stn		Asbestos	Room: Surveyed - No Known Asbestos				MMMFG gaitor 2no to A/C ductwork			R554126	N	N
43247	ACTIVE	N	N085-00-2/151	UMC - Station Building - Kentish Town Stn	Bitumen	Asbestos	Sampled - Not Detected				Bitumen cable duct 1no to under stairs wall adjacent to escalator 2 machine			R554126	N	N
43245	INACTIVE	N	N085-00-2/151	UMC - Station Building - Kentish Town Stn	Isolator Switches	Asbestos	Presumed				Materials within combination fuse switches 5no to wall by 2/953			R554126	N	N
43248	ACTIVE	N	N085-00-2/151	UMC - Station Building - Kentish Town Stn	Isolator Switches	Asbestos	Presumed				Materials within large combination fuse switch 1no to wall by switchboard 1 and 2			R554126	N	N
43243	ACTIVE	N	N085-00-2/151	UMC - Station Building - Kentish Town Stn		Asbestos	Sampled - Not Detected				Plastic cables, metal conduits and cable management system and firestop and mastic - new throughout			R554126	N	N
18414	ACTIVE	N	N085-00-2/151	UMC - Station Building - Kentish Town Stn	Cable Ducts: Cement	Asbestos	Surveyed - Not Detected				Cable Duct & Debris					
43241	ACTIVE	N	N085-00-2/151	UMC - Station Building - Kentish Town Stn		Asbestos	Sampled - Not Detected				Concrete slab to floor, ceiling, pillars and columns			R554126	N	N
43246	ACTIVE	N	N085-00-2/151	UMC - Station Building - Kentish Town Stn		Asbestos	Room: Surveyed - No Known Asbestos				New durasteel panel 2m2 to storage bunker by escalator 2			R554126	N	N
43242	ACTIVE	N	N085-00-2/151	UMC - Station Building - Kentish Town Stn		Asbestos	Sampled - Not Detected				Brickwork to walls columns and pillars			R554126	N	N
43250	ACTIVE	N	N085-00-2/151	UMC - Station Building - Kentish Town Stn	Isolator Switches	Asbestos	Presumed				Materials within fire switch box 1no to column by entrance door			R554126	N	N



# Hazardous Material Asset Register - Summary



## N085-00 - Station Building - Kentish Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43266	ACTIVE	N	N085-00-2/151	UMC - Station Building - Kentish Town Stn		Asbestos	Sampled – Not Detected				Render on concrete has been sampled in several areas throughout this room. Walls and ceiling No asbestos detected. Please see survey report R554128 (27/09/2016)			R554128	N	N
16876	ACTIVE	N	N085-00-2/151	UMC - Station Building - Kentish Town Stn	Isolator Switches	Asbestos	Known				5x Switch Boxes near to wall by 2/953 - Switch Boxes confirmed to contain Flash guards, Arc Chutes & Cementitious Blocks - All containing Asbestos have been labelled. 3 x 100 amps, 1 x 60 amps, 1 x ?		5		N	N
43279	ACTIVE	N	N085-00-2/151	UMC - Station Building - Kentish Town Stn	Lead/Leading	Lead Paint/Lead	Known				UMC 2/151 Yellow(Orange) Matt Beams and handrails 750 2.62%			R554127	N	N
43278	ACTIVE	N	N085-00-2/151	UMC - Station Building - Kentish Town Stn	Lead/Leading	Lead Paint/Lead	Known				UMC 2/151 White Gloss Walls at low level 1250 0.27%			R554127	N	N
43280	ACTIVE	N	N085-00-2/151	UMC - Station Building - Kentish Town Stn	Lead/Leading	Lead Paint/Lead	Known				UMC 2/151 Grey Matt RSJ, Ceiling 530 9.96%			R554127	N	N
43277	ACTIVE	N	N085-00-2/151	UMC - Station Building - Kentish Town Stn	Lead/Leading	Lead Paint/Lead	Known				UMC 2/151 Yellow Gloss Walls at high level 460 0.16%			R554127	N	N
18534	ACTIVE	N	N085-00-2/151/FLR-01	Floor - 1 - UMC - Station Building - Kentish Town Stn	Durasteel	Asbestos	Surveyed – Not Detected				Flammable Store (Durasteel) - Non Asbestos					
9530	ACTIVE	N	N085-00-2/201	Passage - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16877	ACTIVE	N	N085-00-2/201/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Kentish Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels - To false ceiling by stairs (1/631) RSJ (In False ceiling)					
9531	ACTIVE	N	N085-00-2/236	Lobby - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16878	ACTIVE	N	N085-00-2/236	Lobby - Station Building - Kentish Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				Presumed asbestos cables historically identified could not be located during 2020 re-inspections. There is no photo of the original ACM on record. There is also no recorded ACM removals for this room, although a series of removals have taken place over the years at this station. Based on the re-inspection it is likely these cables are no longer present but HMT to carry out internal review/ site inspection prior to removing entry from register. Photos of room attached.					
9532	ACTIVE	N	N085-00-2/237	Lobby - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9533	ACTIVE	N	N085-00-2/331	Mess Room - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N085-00 - Station Building - Kentish Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20077	ACTIVE	N	N085-00-2/331	Mess Room - Station Building - Kentish Town Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
18689	ACTIVE	N	N085-00-2/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Kentish Town Stn	Void	Asbestos	Surveyed – Not Detected				Plaster, Concrete above MMF false ceiling				YES	
9534	ACTIVE	N	N085-00-2/416	Toilet: Female - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16979	ACTIVE	N	N085-00-2/416	Toilet: Female - Station Building - Kentish Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9535	ACTIVE	N	N085-00-2/417	Toilet: Male - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16980	ACTIVE	N	N085-00-2/417	Toilet: Male - Station Building - Kentish Town Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - Foam					
16982	ACTIVE	N	N085-00-2/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Kentish Town Stn	Void	Asbestos	No Access: Presumed				No Access above False Ceiling				YES	
16981	ACTIVE	N	N085-00-2/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Kentish Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
9536	ACTIVE	N	N085-00-2/631	Stairs: Spiral - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18690	ACTIVE	N	N085-00-2/631	Stairs: Spiral - Station Building - Kentish Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
16983	ACTIVE	N	N085-00-2/641	Gantry - Station Building - Kentish Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
16984	ACTIVE	N	N085-00-2/641	Gantry - Station Building - Kentish Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9537	ACTIVE	N	N085-00-2/731	CER - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18479	ACTIVE	N	N085-00-2/731	CER - Station Building - Kentish Town Stn	Isolator Switches	Asbestos	Strongly Presumed				Grey Switch Boxes - Insulation within. Switch Boxes confirmed to contain Flash guards, Arc Chutes & Cementious Blocks - All containing Asbestos have been labelled		2		N	N
16985	ACTIVE	N	N085-00-2/731	CER - Station Building - Kentish Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing					
19144	ACTIVE	N	N085-00-2/731/FLR-01	Floor - 1 - CER - Station Building - Kentish Town Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden Floor					YES



# Hazardous Material Asset Register - Summary



## N085-00 - Station Building - Kentish Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9538	ACTIVE	N	N085-00-2/733	SER - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18691	ACTIVE	N	N085-00-2/733/FLR-01	Floor - 1 - SER - Station Building - Kentish Town Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden Floor					YES
16986	ACTIVE	N	N085-00-2/791	Vent Shaft - Station Building - Kentish Town Stn	Cable: Wrap	Asbestos	Known				Lagging (9m) at bottom of vent shaft	9			N	N
16987	ACTIVE	N	N085-00-2/792	Vent Shaft - Station Building - Kentish Town Stn	Debris: Other	Asbestos	Surveyed – Not Detected				Steel Rings; Debris on Rings - Non Asbestos					
9539	ACTIVE	N	N085-00-2/901	Void - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16988	ACTIVE	N	N085-00-2/901	Void - Station Building - Kentish Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9540	ACTIVE	N	N085-00-2/951	Disused Room - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16989	ACTIVE	N	N085-00-2/951	Disused Room - Station Building - Kentish Town Stn	Pipe Lagging	Asbestos	Surveyed – Not Detected									
9541	ACTIVE	N	N085-00-2/952	Store - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16990	ACTIVE	N	N085-00-2/952	Store - Station Building - Kentish Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cable		1		N	N
9542	ACTIVE	N	N085-00-2/953	Disused Room - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43235	ACTIVE	N	N085-00-2/953	Disused Room - Station Building - Kentish Town Stn		Asbestos	Sampled – Not Detected				Plastic and metal pipework - some within MMMF insulation throughout			R554126	N	N
43232	INACTIVE	N	N085-00-2/953	Disused Room - Station Building - Kentish Town Stn	Isolator Switches	Asbestos	Presumed				Materials within combination fuse switch 1no to wall by stairs			R554126	N	N
43236	ACTIVE	N	N085-00-2/953	Disused Room - Station Building - Kentish Town Stn		Asbestos	Sampled – Not Detected				Loose MMMF insulation to floor			R554126	N	N
43234	ACTIVE	N	N085-00-2/953	Disused Room - Station Building - Kentish Town Stn		Asbestos	Sampled – Not Detected				Ceramic tiles partial on plaster on brickwork			R554126	N	N
43230	ACTIVE	N	N085-00-2/953	Disused Room - Station Building - Kentish Town Stn		Asbestos	Sampled – Not Detected				Concrete Slab to floor and some ceiling			R554126		
43233	ACTIVE	N	N085-00-2/953	Disused Room - Station Building - Kentish Town Stn	Mastic	Asbestos	Sampled – Not Detected				Plastic cables metal conduits and cable management system and firestop and mastic - new throughout			R554126	N	N



# Hazardous Material Asset Register - Summary



## N085-00 - Station Building - Kentish Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18692	ACTIVE	N	N085-00-2/953	Disused Room - Station Building - Kentish Town Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x Switch Box - Insulation within; 100 amps		1			
43264	ACTIVE	N	N085-00-2/953	Disused Room - Station Building - Kentish Town Stn		Asbestos	Sampled – Not Detected				Render on concrete has been sampled in several areas throughout this room. Walls and ceiling No asbestos detected. Please see survey report R554128 (27/09/2016)			R554128	N	N
43231	ACTIVE	N	N085-00-2/953	Disused Room - Station Building - Kentish Town Stn		Asbestos	Sampled – Not Detected				Plaster on Brickwork to walls and ceiling			R554126		
43267	ACTIVE	N	N085-00-2/953	Disused Room - Station Building - Kentish Town Stn	Lead/Leading	Lead Paint/Lead	Known				Disused Room 2/953 Pink Matt Walls 250 3.66%			R554127	N	N
43269	ACTIVE	N	N085-00-2/953	Disused Room - Station Building - Kentish Town Stn	Lead/Leading	Lead Paint/Lead	Known				Disused Room 2/953 Black Gloss RSJ and metal pipework 410 2.68%			R554127	N	N
43268	ACTIVE	N	N085-00-2/953	Disused Room - Station Building - Kentish Town Stn	Lead/Leading	Lead Paint/Lead	Known				Disused Room 2/953 Cream Matt Walls above and below stairs 190 4.08%			R554127	N	N
43271	ACTIVE	N	N085-00-2/953	Disused Room - Station Building - Kentish Town Stn	Lead/Leading	Lead Paint/Lead	Known				Disused Room 2/953 Green Matt Parts of walls 490 0.18%			R554127	N	N
43272	ACTIVE	N	N085-00-2/953	Disused Room - Station Building - Kentish Town Stn	Lead/Leading	Lead Paint/Lead	Known				Disused Room 2/953 Black Gloss Metal framework of skylight 580 0.09%			R554127	N	N
43273	ACTIVE	N	N085-00-2/953	Disused Room - Station Building - Kentish Town Stn	Lead/Leading	Lead Paint/Lead	Known				Disused Room 2/953 - No Paint pavement area outside of the station			R554127	N	N
9543	ACTIVE	N	N085-00-2/954	Disused Room - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18915	ACTIVE	N	N085-00-2/954	Disused Room - Station Building - Kentish Town Stn	Pipe Lagging	Asbestos	Surveyed – Not Detected				Pipe Cladding & Debris					
43238	ACTIVE	N	N085-00-2/954	Disused Room - Station Building - Kentish Town Stn		Asbestos	Sampled – Not Detected				Brickwork to walls and columns			R554126	N	N
43265	ACTIVE	N	N085-00-2/954	Disused Room - Station Building - Kentish Town Stn		Asbestos	Sampled – Not Detected				Render on concrete has been sampled in several areas throughout this room. Walls and ceiling No asbestos detected. Please see survey report R554128 (27/09/2016)			R554128	N	N
43244	ACTIVE	N	N085-00-2/954	Disused Room - Station Building - Kentish Town Stn		Asbestos	Room: Surveyed – No Known Asbestos				A/C metal ductwork - new throughout			R554126	N	N
43240	ACTIVE	N	N085-00-2/954	Disused Room - Station Building - Kentish Town Stn		Asbestos	Sampled – Not Detected				Plastic cables and metal conduits and firestop and mastic - new throughout			R554126	N	N
43237	ACTIVE	N	N085-00-2/954	Disused Room - Station Building - Kentish Town Stn		Asbestos	Sampled – Not Detected				Concrete slab to floor, ceiling and walls			R554126		
43239	ACTIVE	N	N085-00-2/954	Disused Room - Station Building - Kentish Town Stn	Other Electrical Boxes	Asbestos	Presumed				Materials within SPBC electrical box 1no to wall presumed to contain asbestos			R554126	N	N



# Hazardous Material Asset Register - Summary



## N085-00 - Station Building - Kentish Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43275	ACTIVE	N	N085-00-2/954	Disused Room - Station Building - Kentish Town Stn	Lead/Leading	Lead Paint/Lead	Known				Disused Room 2/954 Black Gloss RSJ and metal pipework 230 20.7%			R554127	N	N
43274	ACTIVE	N	N085-00-2/954	Disused Room - Station Building - Kentish Town Stn	Lead/Leading	Lead Paint/Lead	Known				Disused Room 2/954 Grey Matt Down pipe 310 27.5%			R554127	N	N
43276	ACTIVE	N	N085-00-2/954	Disused Room - Station Building - Kentish Town Stn	Lead/Leading	Lead Paint/Lead	Known				Disused Room 2/954 Grey Gloss Metal framework of skylight 740 12.9%			R554127	N	N
9544	ACTIVE	N	N085-00-3/081	Circulation Area - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16991	ACTIVE	N	N085-00-3/081	Circulation Area - Station Building - Kentish Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9545	ACTIVE	N	N085-00-3/121	Platform Invert - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19145	ACTIVE	N	N085-00-3/121	Platform Invert - Station Building - Kentish Town Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
9546	ACTIVE	N	N085-00-3/161	LMC - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16992	ACTIVE	N	N085-00-3/161	LMC - Station Building - Kentish Town Stn	Caulking	Asbestos	Surveyed - Not Detected				within Tunnel Rings					
9547	ACTIVE	N	N085-00-3/162	LMC - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
9548	ACTIVE	N	N085-00-3/201	Passage - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16993	ACTIVE	N	N085-00-3/201	Passage - Station Building - Kentish Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9549	ACTIVE	N	N085-00-3/261	Platform 1 - Northbound Fast - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
44937	ACTIVE	N	N085-00-3/261	Platform 1 - Northbound Fast - Station Building - Kentish Town Stn		Asbestos	Known				Platform 1 Invert - Cables by hydrant				N	N
42534	ACTIVE	N	N085-00-3/261	Platform 1 - Northbound Fast - Station Building - Kentish Town Stn	Cable: Sheath	Asbestos	Removed				Cable wrap (10m) - Removed by Econ under request ES2578b	10		R287952	N	N
44936	ACTIVE	N	N085-00-3/261	Platform 1 - Northbound Fast - Station Building - Kentish Town Stn		Asbestos	Removed				Leaking Hydrant, 2nd & bottom gasket, tap gland - Removed by Econ under request ES2578a/b/c				N	N



# Hazardous Material Asset Register - Summary



## N085-00 - Station Building - Kentish Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18693	ACTIVE	N	N085-00-3/261	Platform 1 - Northbound Fast - Station Building - Kentish Town Stn	Gasket :Pipework	Asbestos	Removed				Gaskets to Joints on Hydrant Pipework - Removed by Econ under request ES2578a/b/c				N	N
16994	ACTIVE	N	N085-00-3/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Kentish Town Stn	Cable: Sheath	Asbestos	Presumed				2 x Braided Cables		2		N	N
16996	ACTIVE	N	N085-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Kentish Town Stn	Cable Duct: Other	Asbestos	Presumed				Platform 1 Invert - Cable Ducts - Presumed Chrysotile				N	YES
16995	ACTIVE	N	N085-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Kentish Town Stn	Cable: Sheath	Asbestos	Known				Platform 1 Invert - Various Cables / Woven insulated cables throughout length of invert.				N	YES
16997	INACTIVE	N	N085-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Kentish Town Stn	Cable: Wrap	Asbestos	Known				Platform 1 Invert - known Chrysotile - woven insulated cables throughout length of platform 1 invert					YES
9550	ACTIVE	N	N085-00-3/411	Disused Room - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
20080	ACTIVE	N	N085-00-3/411/CLG-01	Ceiling: Suspended - 1 - Disused Room - Station Building - Kentish Town Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	
9551	ACTIVE	N	N085-00-3/576	Ladder - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18694	ACTIVE	N	N085-00-3/576	Ladder - Station Building - Kentish Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9552	ACTIVE	N	N085-00-3/601	Stairs: Linear - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16998	ACTIVE	N	N085-00-3/601	Stairs: Linear - Station Building - Kentish Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9553	ACTIVE	N	N085-00-3/602	Stairs: Linear - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16999	ACTIVE	N	N085-00-3/602	Stairs: Linear - Station Building - Kentish Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9554	ACTIVE	N	N085-00-3/603	Stairs: Linear - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17000	ACTIVE	N	N085-00-3/603	Stairs: Linear - Station Building - Kentish Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9555	ACTIVE	N	N085-00-3/604	Disused Room - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N085-00 - Station Building - Kentish Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18695	ACTIVE	N	N085-00-3/604/FLR-01	Floor - 1 - Stairs - Station Building - Kentish Town Stn	Cable Duct: Other	Asbestos	Known				Cable Sleeves - Chrysotile		3		N	N
9556	ACTIVE	N	N085-00-3/661	Relay Room - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17002	ACTIVE	N	N085-00-3/661/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Kentish Town Stn	Isolator Switches	Asbestos	Strongly Presumed				Wall 1 - Switch Boxes - Asbestos Insulation presumed within. Check quantities/wall numbers re-inspections.					
43226	ACTIVE	N	N085-00-3/661/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Kentish Town Stn	Isolator Switches	Asbestos	Strongly Presumed				Wall 2 - 5 Switch boxes strongly presumed to contain asbestos insulating materials within - 2 x 60amps, 2 x 100amps, 1 x 200amps.		5		N	N
43227	ACTIVE	N	N085-00-3/661/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Kentish Town Stn	Isolator Switches	Asbestos	Strongly Presumed				Wall 3 - Switch boxes strongly presumed to contain asbestos insulation within - 4 x 60amps 1 x 100amps. 2x Green electrical boxes.				N	N
17001	ACTIVE	N	N085-00-3/661/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Kentish Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels					
9557	ACTIVE	N	N085-00-3/711	Relay Room - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53660	ACTIVE	N	N085-00-3/711	Relay Room - Station Building - Kentish Town Stn	Other Electrical Boxes	Asbestos	Presumed				Green box with presumed composite boarding inside					
17004	ACTIVE	N	N085-00-3/711	Relay Room - Station Building - Kentish Town Stn	Other Electrical Boxes	Asbestos	Presumed				Electrical Box on Wall presumed to contain asbestos insulating materials within		1		N	N
42046	INACTIVE	N	N085-00-3/711	Relay Room - Station Building - Kentish Town Stn	PCBs	Polychlorinated biphenyl	Removed				7 x PCB's - Fair Condition Re Moved by Edenbeck Feb 2017 Under ES7773a		7		N	N
53616	ACTIVE	N	N085-00-3/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Kentish Town Stn	Cable Duct: Other	Asbestos	Presumed				ducts to floor inside cabinet					
17003	ACTIVE	N	N085-00-3/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Kentish Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				2x Green 50mm Cables		2		N	N
53614	ACTIVE	N	N085-00-3/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Kentish Town Stn	Other Boarding	Asbestos	Presumed				Board to 600v box					
9558	ACTIVE	N	N085-00-3/732	CER - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18696	ACTIVE	N	N085-00-3/732	CER - Station Building - Kentish Town Stn	Isolator Switches	Asbestos	Removed				Switch Boxes strongly presumed to contain asbestos insulating materials within were not present in 2020 re-inspection.		2		N	N
9559	ACTIVE	N	N085-00-3/761	Relay Room - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N085-00 - Station Building - Kentish Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18697	ACTIVE	N	N085-00-3/761	Relay Room - Station Building - Kentish Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
17006	ACTIVE	N	N085-00-3/791	Vent Shaft - Station Building - Kentish Town Stn	Cable: Wrap	Asbestos	Known				Lagging (7m) at bottom of vent shaft	7			N	N
17005	ACTIVE	N	N085-00-3/791	Vent Shaft - Station Building - Kentish Town Stn	Cable: Wrap	Asbestos	Surveyed – Not Detected				LHS to Door					
9560	ACTIVE	N	N085-00-3/951	Disused Room - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17007	ACTIVE	N	N085-00-3/951	Disused Room - Station Building - Kentish Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9561	ACTIVE	N	N085-00-3/952	Void - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18698	ACTIVE	N	N085-00-3/952	Void - Station Building - Kentish Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
17008	ACTIVE	N	N085-00-3/971	Vent Shaft - Station Building - Kentish Town Stn	Caulking	Asbestos	Surveyed – Not Detected				within Tunnel Rings					
9562	ACTIVE	N	N085-00-3/981	Stairs: Linear - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17009	ACTIVE	N	N085-00-3/981	Stairs: Linear - Station Building - Kentish Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9563	ACTIVE	N	N085-00-4/201	Passage - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17010	ACTIVE	N	N085-00-4/201	Passage - Station Building - Kentish Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9564	ACTIVE	N	N085-00-4/202	Passage - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18699	ACTIVE	N	N085-00-4/202	Passage - Station Building - Kentish Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9565	ACTIVE	N	N085-00-4/262	Platform 2 - Southbound Fast - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17011	ACTIVE	N	N085-00-4/262	Platform 2 - Southbound Fast - Station Building - Kentish Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				1 x 20mm, 1 x 50mm & 1 x 10mm Cables going into Track				N	N
17012	ACTIVE	N	N085-00-4/262/ FLR-01	Floor - 1 - Platform 2 - Station Building - Kentish Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - Various Cables				N	YES



# Hazardous Material Asset Register - Summary



## N085-00 - Station Building - Kentish Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9566	ACTIVE	N	N085-00-4/381	Store - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18700	ACTIVE	N	N085-00-4/381	Store - Station Building - Kentish Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9567	ACTIVE	N	N085-00-4/382	Store - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17013	ACTIVE	N	N085-00-4/382	Store - Station Building - Kentish Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9568	ACTIVE	N	N085-00-4/661	Switch Room - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17014	ACTIVE	N	N085-00-4/661	Switch Room - Station Building - Kentish Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables going to Track and 1 x going to Invert - 2 x Green 1 x White		3		N	N
42047	INACTIVE	N	N085-00-4/661	Switch Room - Station Building - Kentish Town Stn	PCBs	Polychlorinated biphenyl	Removed				8 x PCB's - 6 x Fair Condition, 2 x possibly leaking - currently being investigated by HMU Re Moved by Edenbeck Feb 2017 Under ES7773a		8		N	N
9569	ACTIVE	N	N085-00-4/662	Switch Room - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18701	ACTIVE	N	N085-00-4/662	Switch Room - Station Building - Kentish Town Stn	Isolator Switches	Asbestos	Strongly Presumed				Blue Switch Boxes - Asbestos insulation presumed within 3 x 60 amps, 1 x 100 amps		4		N	N
18916	ACTIVE	N	N085-00-4/662	Switch Room - Station Building - Kentish Town Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Transformer Box(es) presumed asbestos insulation within		1		N	N
17015	ACTIVE	N	N085-00-4/662/ WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Kentish Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boarding above Entrance					
9570	ACTIVE	N	N085-00-4/663	Switch Room - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17016	ACTIVE	N	N085-00-4/663	Switch Room - Station Building - Kentish Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9571	ACTIVE	N	N085-00-4/711	Relay Room - Station Building - Kentish Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17017	ACTIVE	N	N085-00-4/711	Relay Room - Station Building - Kentish Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Wall & Ceiling Tiles Supalux					
17019	INACTIVE	N	N085-00-4/711	Relay Room - Station Building - Kentish Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				10 mm Cables going into Invert		1			
19362	ACTIVE	N	N085-00-4/711	Relay Room - Station Building - Kentish Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					



# Hazardous Material Asset Register - Summary



## N085-00 - Station Building - Kentish Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17018	INACTIVE	N	N085-00-4/711/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - Kentish Town Stn	Vinyl tiles	Asbestos	Presumed				Wall & Ceiling Tiles (Duplicate) with 17017					
18702	ACTIVE	N	N085-00-4/711/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - Kentish Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
17021	ACTIVE	N	N085-00-4/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Kentish Town Stn	Other Boarding	Asbestos	Strongly Presumed				1 x Paxoline Board (high to wall 1)				N	N
17067	ACTIVE	N	N085-00-4/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Kentish Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				2x 50 mm green Cables going into Invert		2		N	N
53612	ACTIVE	N	N085-00-4/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Kentish Town Stn	Other Boarding	Asbestos	Presumed				2 x circuit boxes to wall 2 - black composite panels					
53611	ACTIVE	N	N085-00-4/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Kentish Town Stn	Other Electrical Boxes	Asbestos	Presumed				Large free standing electrical equipment - presumed asbestos within					
19147	ACTIVE	N	N085-00-4/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Kentish Town Stn	Westing house Boxes	Asbestos	Strongly Presumed				1 x Westinghouse Box strongly presumed to asbestos insulating materials within.		1		N	N
53613	ACTIVE	N	N085-00-4/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Kentish Town Stn	Other Boarding	Asbestos	Presumed				brown packing panel to front of rectifier					
17020	ACTIVE	N	N085-00-4/711/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Kentish Town Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Electrical Box Presumed to be Lead Paint				N	N
19146	ACTIVE	N	N085-00-4/971	Vent Shaft - Station Building - Kentish Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					

## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9572	ACTIVE	N	N091-00-1/001	Booking Hall - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42909	ACTIVE	N	N091-00-1/001	Booking Hall - Station Building - Camden Town Stn	Boarding: AIB	Asbestos	Presumed				Boarding and associated debris above false ceiling. Asbestos assumed in this location due to its' KNOWN presence confirmed at N091-00-1/071.				Y	N
16594	ACTIVE	N	N091-00-1/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Camden Town Stn	Void	Asbestos	Surveyed – Not Detected				Above Ceiling - Gates - Brick, Concrete				YES	



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9573	ACTIVE	N	N091-00-1/011	Ticket Office - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16595	ACTIVE	N	N091-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Camden Town Stn	Void	Asbestos	Surveyed – Not Detected				Rendered Plaster, Breeze Block above Supalux Tiles				YES	
18280	ACTIVE	N	N091-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
9574	ACTIVE	N	N091-00-1/021	POM - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16597	ACTIVE	N	N091-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels					
16598	ACTIVE	N	N091-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Camden Town Stn	Void	Asbestos	Surveyed – Not Detected				Rendered Plaster above false ceiling				YES	
18281	ACTIVE	N	N091-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				Beneath Rubber Flooring					YES
16596	ACTIVE	N	N091-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
9575	ACTIVE	N	N091-00-1/031	Mess Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16599	ACTIVE	N	N091-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels					
18833	ACTIVE	N	N091-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Camden Town Stn	Void	Asbestos	Surveyed – Not Detected				Above Supalux Panels - ref report R679623 - NAD throughout false ceiling				YES	
9576	ACTIVE	N	N091-00-1/036	Toilet: Unisex - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44788	ACTIVE	N	N091-00-1/036	Toilet: Unisex - Station Building - Camden Town Stn		Lead Paint/Lead	Sampled – Not Detected				Cream matt paint on walls - Analysis Results <0.01% Not lead hazard White powder coated paint on false ceiling - N/A Not lead hazard					
16600	ACTIVE	N	N091-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels					
18403	ACTIVE	N	N091-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				Above Supalux Panels				YES	



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9577	ACTIVE	N	N091-00-1/071	Circulation Area - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16601	ACTIVE	N	N091-00-1/071	Circulation Area - Station Building - Camden Town Stn	Boarding: AIB	Asbestos	Known				Boarding and associated debris above false ceiling. Tiles directly above landing area of Escalators 1 & 2 found to contain amosite asbestos.				YES	N
19046	ACTIVE	N	N091-00-1/071	Circulation Area - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Middle boards - Supalux; Outer boards - Plaster;					
42908	ACTIVE	N	N091-00-1/071/CLG-04	Ceiling: Suspended - 4 - Circulation Area - Station Building - Camden Town Stn	Boarding: AIB	Asbestos	Known				Boarding and associated debris above false ceiling. Tiles directly above landing area of Escalators 1 & 2 found to contain amosite asbestos.			R181476	Y	N
9578	ACTIVE	N	N091-00-1/236	Lobby - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16603	ACTIVE	N	N091-00-1/236/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Camden Town Stn	Void	Asbestos	Surveyed – Not Detected				Rendered Plaster, Concrete, Brick above false ceiling				YES	
18282	ACTIVE	N	N091-00-1/236/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels					
16602	ACTIVE	N	N091-00-1/236/FLR-01	Floor - 1 - Lobby - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
9579	ACTIVE	N	N091-00-1/311	Office - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16606	ACTIVE	N	N091-00-1/311/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Camden Town Stn	Void	Asbestos	Surveyed – Not Detected				Rendered Plaster, Breeze Blocks above Supalux Panels				YES	
16605	ACTIVE	N	N091-00-1/311/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels					
16604	ACTIVE	N	N091-00-1/311/FLR-01	Floor - 1 - Office - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring; Rubber Floor Covering					YES
9580	ACTIVE	N	N091-00-1/331	Mess Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16607	ACTIVE	N	N091-00-1/331	Mess Room - Station Building - Camden Town Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
44787	ACTIVE	N	N091-00-1/331	Mess Room - Station Building - Camden Town Stn		Lead Paint/Lead	Sampled – Not Detected				Cream matt paint on Walls & ceiling - Analysis Results <0.01% & 0.13% Not lead hazard / White power coated paint on false ceiling - N/A Not lead hazard					



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16928	ACTIVE	N	N091-00-1/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles; Inside Fascia around Canopy - Solid					
18612	ACTIVE	N	N091-00-1/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				No Access above False Ceiling				YES	
16929	ACTIVE	N	N091-00-1/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Camden Town Stn	Glazing Rope	Asbestos	Strongly Presumed				Glass Skylight - Rope Seal				N	N
18283	ACTIVE	N	N091-00-1/331/FLR-01	Floor - 1 - Mess Room - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				Beneath Linoleum, Rubber					YES
9581	ACTIVE	N	N091-00-1/401	Bin Store - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16930	ACTIVE	N	N091-00-1/401	Bin Store - Station Building - Camden Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9582	ACTIVE	N	N091-00-1/406	SVC - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16932	ACTIVE	N	N091-00-1/406	SVC - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels					
16933	ACTIVE	N	N091-00-1/406/CLG-01	Ceiling: Solid - 1 - SVC - Station Building - Camden Town Stn	No Access	Asbestos	No Access: Presumed				Above false ceiling				YES	
16931	ACTIVE	N	N091-00-1/406/FLR-01	Floor - 1 - SVC - Station Building - Camden Town Stn	Debris: Cement	Asbestos	Surveyed – Not Detected				Cement Debris - Non Asbestos					
9583	ACTIVE	N	N091-00-1/411	SVC - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18613	ACTIVE	N	N091-00-1/411	SVC - Station Building - Camden Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9584	ACTIVE	N	N091-00-1/412	SCR - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16935	ACTIVE	N	N091-00-1/412	SCR - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding Surround; Inside 4no Metal Doors Supalux Boarding					
19139	ACTIVE	N	N091-00-1/412/CLG-01	Ceiling: Solid - 1 - SCR - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling				YES	
16936	ACTIVE	N	N091-00-1/412/CLG-01	Ceiling: Solid - 1 - SCR - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Frame & Surround					
16934	ACTIVE	N	N091-00-1/412/FLR-01	Floor - 1 - SCR - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				Beneath Linoleum, Rubber					YES



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9585	ACTIVE	N	N091-00-1/551	Yard - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18614	ACTIVE	N	N091-00-1/551	Yard - Station Building - Camden Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9586	ACTIVE	N	N091-00-1/631	Stairs: Spiral - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16937	ACTIVE	N	N091-00-1/631/CLG-01	Ceiling: Solid - 1 - Spiral Stairs - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling				YES	
9587	ACTIVE	N	N091-00-1/661	Switch Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16938	ACTIVE	N	N091-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Camden Town Stn	Isolator Switches	Asbestos	Strongly Presumed				5no Grey Switch Boxes - Insulation within		5		N	N
9588	ACTIVE	N	N091-00-1/662	Switch Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18913	ACTIVE	N	N091-00-1/662	Switch Room - Station Building - Camden Town Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Emulsion Paint - Ceiling and Walls. Thickness .20mm; Est Quantity 30sqm; Analysis 1.8% - Poor Condition				N	N
16940	ACTIVE	N	N091-00-1/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Camden Town Stn	Other Electrical Boxes	Asbestos	Presumed				3no Transformer Boxes		3		N	N
18615	ACTIVE	N	N091-00-1/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Camden Town Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 30 amp Switch Box		1		N	N
16939	ACTIVE	N	N091-00-1/662/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Camden Town Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x 60amp, 2 x 100amp Switch Boxes - Insulation within		4		N	N
16941	ACTIVE	N	N091-00-1/662/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Camden Town Stn	Lead/Leading	Lead Paint/Lead	Known				Blue Oil Based Paint Switch Boxes and Busbar Thickness .09mm; Est Quantity 2sqm; Analysis 1.2%				N	N
18417	ACTIVE	N	N091-00-1/662/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Camden Town Stn	Isolator Switches	Asbestos	Strongly Presumed				4 x 60amp Switch Boxes - Insulation within		4		N	N
9589	ACTIVE	N	N091-00-1/746	Station Control Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16943	ACTIVE	N	N091-00-1/746/CLG-01	Ceiling: Suspended - 1 - Station Control Room - Station Building - Camden Town Stn	Void	Asbestos	Surveyed – Not Detected				Metal Ducting, Fibreglass Lagging, Metal Pipes, Rendered Plaster above False Ceiling				YES	



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18616	ACTIVE	N	N091-00-1/746/CLG-01	Ceiling: Suspended - 1 - Station Control Room - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
20079	ACTIVE	N	N091-00-1/746/CLG-01	Ceiling: Suspended - 1 - Station Control Room - Station Building - Camden Town Stn	Glazing Rope	Asbestos	Strongly Presumed				Above Ceiling: Glass Canopy - Rope Seal				Y	N
16942	ACTIVE	N	N091-00-1/746/FLR-01	Floor - 1 - Station Control Room - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				Beneath Linoleum, Rubber					YES
9590	ACTIVE	N	N091-00-2/151	UMC - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44151	ACTIVE	N	N091-00-2/151	UMC - Station Building - Camden Town Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer box		1		N	N
16945	ACTIVE	N	N091-00-2/151	UMC - Station Building - Camden Town Stn	Pipe Lagging	Asbestos	Surveyed – Not Detected				String around Pipe					
16946	ACTIVE	N	N091-00-2/151	UMC - Station Building - Camden Town Stn	Isolator Switches	Asbestos	Removed				4 x Blue, 1no Grey, 1no Red Switch Boxes - Insulation within		6			
16944	ACTIVE	N	N091-00-2/151	UMC - Station Building - Camden Town Stn	Durasteel	Asbestos	Surveyed – Not Detected				Flammable Store (Durasteel) - Non Asbestos					
16947	ACTIVE	N	N091-00-2/151	UMC - Station Building - Camden Town Stn	Cable Duct: Other	Asbestos	Sampled – Not Detected				Cable sleeve in vault next to switch boxes - NADIS					
9591	ACTIVE	N	N091-00-2/210	Lobby - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18617	ACTIVE	N	N091-00-2/210/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Camden Town Stn	Void	Asbestos	Surveyed – Not Detected				Vermiculite Pipe Lagging; Fibreglass Pipe Lagging above ceiling				YES	
9592	ACTIVE	N	N091-00-2/236	Lobby - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16950	ACTIVE	N	N091-00-2/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Camden Town Stn	Void	Asbestos	Surveyed – Not Detected				Plaster above False Ceiling				YES	
16949	ACTIVE	N	N091-00-2/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
9593	ACTIVE	N	N091-00-2/237	Lobby - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16781	ACTIVE	N	N091-00-2/237/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Camden Town Stn	Void	Asbestos	Surveyed – Not Detected				Plaster above False Ceiling				YES	



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16783	ACTIVE	N	N091-00-2/237/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Camden Town Stn	Void	Asbestos	Surveyed - Not Detected				Plaster above False Ceiling				YES	
18450	ACTIVE	N	N091-00-2/237/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
16782	ACTIVE	N	N091-00-2/237/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
9594	ACTIVE	N	N091-00-2/238	Lobby - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
46450	ACTIVE	N	N091-00-2/238	Lobby - Station Building - Camden Town Stn	Lead/Leading	Lead Paint/Lead	Sampled - Not Detected				White matt paint to walls - Thickness: 0.28mm Analysis: <0.02%			R686776	N	N
9595	ACTIVE	N	N091-00-2/239	Lobby - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16784	ACTIVE	N	N091-00-2/239	Lobby - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Boxing					
9596	ACTIVE	N	N091-00-2/241	Lobby - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16785	ACTIVE	N	N091-00-2/241	Lobby - Station Building - Camden Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9597	ACTIVE	N	N091-00-2/316	Locker Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18451	ACTIVE	N	N091-00-2/316	Locker Room - Station Building - Camden Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
46448	ACTIVE	N	N091-00-2/316	Locker Room - Station Building - Camden Town Stn	Lead/Leading	Lead Paint/Lead	Sampled - Not Detected				White matt paint to walls - Thickness: 0.48mm Analysis: <0.02%			R686776	N	N
9598	ACTIVE	N	N091-00-2/371	CER - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18410	ACTIVE	N	N091-00-2/371	CER - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Boarding; Vermiculite Pipe Lagging					
19125	ACTIVE	N	N091-00-2/371/FLR-01	Floor - 1 - CER - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
16786	ACTIVE	N	N091-00-2/371/FLR-02	Floor - 2 - CER - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
9599	ACTIVE	N	N091-00-2/406	Shower Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16787	ACTIVE	N	N091-00-2/406/CLG-01	Ceiling: Suspended - 1 - Shower Room - Station Building - Camden Town Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Grid				YES	
9600	ACTIVE	N	N091-00-2/407	Lobby - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18452	ACTIVE	N	N091-00-2/407/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Camden Town Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Grid				YES	
9601	ACTIVE	N	N091-00-2/412	Disused Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9602	ACTIVE	N	N091-00-2/416	Toilet: Female - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16788	ACTIVE	N	N091-00-2/416	Toilet: Female - Station Building - Camden Town Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LU Heater Foam Insulation Board					
9603	ACTIVE	N	N091-00-2/417	Disused Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42071	ACTIVE	N	N091-00-2/417/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Camden Town Stn	Mastic	Asbestos	Presumed				Mastic within ventilation equipment					N
19358	ACTIVE	N	N091-00-2/417/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				No Access within Asbestos Boarding				YES	
16789	ACTIVE	N	N091-00-2/417/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Camden Town Stn	Boarding: AIB	Asbestos	Known				Asbestos Boarding - Chrysotile & Amphibole					N
9604	ACTIVE	N	N091-00-2/418	Toilet: Male - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46451	ACTIVE	N	N091-00-2/418	Toilet: Male - Station Building - Camden Town Stn	Lead/Leading	Lead Paint/Lead	Sampled – Not Detected				White matt paint to walls - Thickness: 0.48mm Analysis: <0.02%			R686776	N	N
16790	ACTIVE	N	N091-00-2/418/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Camden Town Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Grid				YES	
9605	ACTIVE	N	N091-00-2/571	Store - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18453	ACTIVE	N	N091-00-2/571	Store - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding and Boxing					



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9606	ACTIVE	N	N091-00-2/664	Switch Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16791	ACTIVE	N	N091-00-2/664	Switch Room - Station Building - Camden Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9607	ACTIVE	N	N091-00-2/731	CER - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18904	ACTIVE	N	N091-00-2/731	CER - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Boarding above Door					
19126	ACTIVE	N	N091-00-2/731/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Plaster; Supalux Boxing					
16792	ACTIVE	N	N091-00-2/731/FLR-01	Floor - 1 - CER - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
16793	ACTIVE	N	N091-00-2/731/WAL-001	Wall: Internal - 1 - CER - Station Building - Camden Town Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x 60amp Grey Switch Boxes - Insulation within		2		N	N
9608	ACTIVE	N	N091-00-2/732	Switch Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
44309	ACTIVE	N	N091-00-2/732	Switch Room - Station Building - Camden Town Stn	Cable Ducts: Cement	Asbestos	Presumed				Ductwork 8no to floor by wall 3					
16794	ACTIVE	N	N091-00-2/732/CLG-01	Ceiling: Solid - 1 - MDF - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux					
18454	ACTIVE	N	N091-00-2/732/FLR-01	Floor - 1 - Switch Room - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
43786	ACTIVE	N	N091-00-2/732/WAL-003 80897411	Wall: Internal - 3 - MDF - Station Building - Camden Town Stn Wall: Internal	Cable Duct: Other	Asbestos	Known				Ductwork, 8no, to floor by wall 3 in CER		8	R589530	N	N
9609	ACTIVE	N	N091-00-2/761	Equipment Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16795	ACTIVE	N	N091-00-2/761	Equipment Room - Station Building - Camden Town Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
46449	ACTIVE	N	N091-00-2/761	Equipment Room - Station Building - Camden Town Stn	Lead/Leading	Lead Paint/Lead	Sampled - Not Detected				White matt paint to walls - Thickness: 0.27mm Analysis: <0.02%			R686776	N	N
9610	ACTIVE	N	N091-00-2/771	Pump Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
9611	ACTIVE	N	N091-00-2/776	Fan Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16797	ACTIVE	N	N091-00-2/776/WAL-004	Wall: Internal - 4 - Fan Room - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding - also above Door to 2/151					
16796	ACTIVE	N	N091-00-2/776/WAL-006	Wall: Internal - 6 - Fan Room - Station Building - Camden Town Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 30amp Switch Box - Insulation within		1		N	N
9612	ACTIVE	N	N091-00-2/993	Disused Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16798	ACTIVE	N	N091-00-2/993	Disused Room - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux White Boarding - Storage					
18455	ACTIVE	N	N091-00-2/993	Disused Room - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing					
16799	ACTIVE	N	N091-00-2/993	Disused Room - Station Building - Camden Town Stn	Lead/Leading	Lead Paint/Lead	Known				Green/ Yellow Oil Based Paint - Girder. Thickness .27mm; Est Quantity 4lm; Analysis 3.9% (LEAD PAINT LIKELY TO HAVE BEEN PAINTED OVER WITH BLACK PAINT)				N	N
9613	ACTIVE	N	N091-00-2/994	Disused Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16800	ACTIVE	N	N091-00-2/994	Disused Room - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing					
16801	INACTIVE	N	N091-00-2/994	Disused Room - Station Building - Camden Town Stn	Lead/Leading	Lead Paint/Lead	Removed				Cream Oil Based Paint - Girder. Thickness .35mm; Est Quantity 2lm; Analysis 4.2% Removed as part of SMEP (PH)					
18456	ACTIVE	N	N091-00-2/994/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding low level					
9614	ACTIVE	N	N091-00-2/995	Equipment Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19127	ACTIVE	N	N091-00-2/995	Equipment Room - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding					
9615	ACTIVE	N	N091-00-3/081	Circulation Area - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16802	ACTIVE	N	N091-00-3/081	Circulation Area - Station Building - Camden Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9616	ACTIVE	N	N091-00-3/121	Platform Invert - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18464	ACTIVE	N	N091-00-3/121/WAL-002	Wall: Internal - 2 - Platform Invert - Station Building - Camden Town Stn	Cable: Sheath	Asbestos	Known				Braided Cable					
25665	ACTIVE	N	N091-00-3/121/WAL-003	Wall: Internal - 3 - Platform Invert - Station Building - Camden Town Stn	Other Boarding	Asbestos	Strongly Presumed				Boarding		1			
9617	ACTIVE	N	N091-00-3/161	LMC - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
46329	ACTIVE	N	N091-00-3/161	LMC - Station Building - Camden Town Stn	Cable Ducts: Bitumen	Asbestos	Sampled - Not Detected				Bitumen Cable Ducts Wall 1 x 3no Wall 3 x 6no		9	R679623		
16803	ACTIVE	N	N091-00-3/161	LMC - Station Building - Camden Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible (REF R679623) NAD to CMS					
9618	ACTIVE	N	N091-00-3/202	Passage - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16804	ACTIVE	N	N091-00-3/202	Passage - Station Building - Camden Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9619	ACTIVE	N	N091-00-3/203	Passage - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16805	ACTIVE	N	N091-00-3/203	Passage - Station Building - Camden Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9620	ACTIVE	N	N091-00-3/204	Passage - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16879	ACTIVE	N	N091-00-3/204	Passage - Station Building - Camden Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9621	ACTIVE	N	N091-00-3/205	Passage - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16880	ACTIVE	N	N091-00-3/205	Passage - Station Building - Camden Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9622	ACTIVE	N	N091-00-3/261	Platform 1 - Northbound Local - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18535	ACTIVE	N	N091-00-3/261	Platform 1 - Northbound Local - Station Building - Camden Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				1x 50mm diameter, 2m long Cable - At the end of the platform in j-hanger running into into tunnel	2			N	N
16881	ACTIVE	N	N091-00-3/261	Platform 1 - Northbound Local - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Panels by Relay Room - Non Asbestos					



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46328	ACTIVE	N	N091-00-3/261	Platform 1 - Northbound Local - Station Building - Camden Town Stn	Void	Asbestos	Surveyed – Not Detected				Platform 1 - Cable Management System - Surveyed no asbestos detected - refer to report R679623			R629623		
46863	INACTIVE	N	N091-00-3/261	Platform 1 - Northbound Local - Station Building - Camden Town Stn		Asbestos	Surveyed – Not Detected				to cable trunking at high level - NAD					
43128	ACTIVE	N	N091-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Camden Town Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel ring caulking, throughout to bolts sprayed in yellow at Camden 20ab point bolt 8.			R512086	N	N
43125	ACTIVE	N	N091-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Camden Town Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel ring caulking, throughout to bolts sprayed in yellow at Camden 20ab point bolt 5.			R512086	N	N
43126	ACTIVE	N	N091-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Camden Town Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel ring caulking, throughout to bolts sprayed in yellow at Camden 20ab point bolt 6.			R512086	N	N
16883	ACTIVE	N	N091-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Camden Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				Various Cables - within invert				N	YES
16882	ACTIVE	N	N091-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Camden Town Stn	Cable Ducts: Bitumen	Asbestos	Surveyed – Not Detected				Platform 1 Invert - Bitumen Ducts to Cross Passage - Middle of Invert - Non Asbestos					YES
43122	ACTIVE	N	N091-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Camden Town Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel ring caulking, throughout to bolts sprayed in yellow at Camden 20ab point bolt 2.			R512086	N	N
43124	ACTIVE	N	N091-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Camden Town Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel ring caulking, throughout to bolts sprayed in yellow at Camden 20ab point bolt 4.			R512086	N	N
43123	ACTIVE	N	N091-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Camden Town Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel ring caulking, throughout to bolts sprayed in yellow at Camden 20ab point bolt 3.			R512086	N	N
43127	ACTIVE	N	N091-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Camden Town Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel ring caulking, throughout to bolts sprayed in yellow at Camden 20ab point bolt 7.			R512086	N	N
43121	ACTIVE	N	N091-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Camden Town Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel ring caulking, throughout to bolts sprayed in yellow at Camden 20ab point bolt 1			R512086	N	N
9623	ACTIVE	N	N091-00-3/263	Platform 3 - Northbound Fast - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18465	ACTIVE	N	N091-00-3/263	Platform 3 - Northbound Fast - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Walls - Supalux					
18536	ACTIVE	N	N091-00-3/263	Platform 3 - Northbound Fast - Station Building - Camden Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				Woven cable (2 x 15 m), at high level into invert. Head wall, platform side,				N	N
16885	ACTIVE	N	N091-00-3/263	Platform 3 - Northbound Fast - Station Building - Camden Town Stn	Cable: Sheath	Asbestos	Not Found during Inspection				Various Cables - within invert				N	
16884	ACTIVE	N	N091-00-3/263	Platform 3 - Northbound Fast - Station Building - Camden Town Stn	Cable Ducts: Bitumen	Asbestos	Surveyed – Not Detected				Bitumen duct (2 x), head wall, platform side, Bitumen duct (2 x), head wall, track side NADIS					



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42625	ACTIVE	N	N091-00-3/263/FLR-01	Floor - 1 - Platform 3 - Station Building - Camden Town Stn	Cable Duct: Other	Asbestos	Sampled – Not Detected				Dust, throughout, to invert floor on Northbound Platform 3 invert at Camden Town Station			R515301	N	N
16887	ACTIVE	N	N091-00-3/263/FLR-01	Floor - 1 - Platform 3 - Station Building - Camden Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 3 Invert - Various Cables					YES
42628	ACTIVE	N	N091-00-3/263/FLR-01	Floor - 1 - Platform 3 - Station Building - Camden Town Stn	Cable Duct: Other	Asbestos	Sampled – Not Detected				Dust, throughout, to LHS cable run on Northbound Platform 3 invert at Camden Town Station			R515301	N	N
16888	ACTIVE	N	N091-00-3/263/FLR-01	Floor - 1 - Platform 3 - Station Building - Camden Town Stn	Isolator Switches	Asbestos	Strongly Presumed				Platform 3 Invert - 1 x Switch Box - Insulation within - Under 3/714 RHS		1		N	YES
42627	ACTIVE	N	N091-00-3/263/FLR-01	Floor - 1 - Platform 3 - Station Building - Camden Town Stn	Cable Duct: Other	Asbestos	Sampled – Not Detected				Dust, throughout, to RHS cable run on Northbound Platform 3 invert at Camden Town Station			R515301	N	N
42626	ACTIVE	N	N091-00-3/263/FLR-01	Floor - 1 - Platform 3 - Station Building - Camden Town Stn	Cable Duct: Other	Asbestos	Sampled – Not Detected				Dust, throughout, within broken concrete to invert floor on Northbound Platform 3 invert at Camden Town Station			R515301	N	N
16886	ACTIVE	N	N091-00-3/263/FLR-01	Floor - 1 - Platform 3 - Station Building - Camden Town Stn	Cable Ducts: Bitumen	Asbestos	Surveyed – Not Detected				Platform 3 Invert - Bitumen Ducts to 4/953, under 3/715 & to track - Non Asbestos					YES
42629	ACTIVE	N	N091-00-3/263/FLR-01	Floor - 1 - Platform 3 - Station Building - Camden Town Stn	Cable Duct: Other	Asbestos	Sampled – Not Detected				Dust, throughout, to invert floor on Northbound Platform 3 invert at Camden Town Station			R515301	N	N
9624	ACTIVE	N	N091-00-3/603	Stairs: Linear - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18537	ACTIVE	N	N091-00-3/603	Stairs: Linear - Station Building - Camden Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9625	ACTIVE	N	N091-00-3/604	Stairs: Linear - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16889	ACTIVE	N	N091-00-3/604	Stairs: Linear - Station Building - Camden Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9626	ACTIVE	N	N091-00-3/605	Stairs: Linear - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19134	ACTIVE	N	N091-00-3/605	Stairs: Linear - Station Building - Camden Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9627	ACTIVE	N	N091-00-3/606	Stairs: Linear - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18909	ACTIVE	N	N091-00-3/606	Stairs: Linear - Station Building - Camden Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
16890	ACTIVE	N	N091-00-3/636	Overbridge - Station Building - Camden Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
19360	ACTIVE	N	N091-00-3/637	Overbridge - Station Building - Camden Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9628	ACTIVE	N	N091-00-3/661	Switch Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18602	ACTIVE	N	N091-00-3/661	Switch Room - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel above door- Non Asbestos					
42073	ACTIVE	N	N091-00-3/661	Switch Room - Station Building - Camden Town Stn	Lead/Leading	Lead Paint/Lead	Presumed				Presumed Cream based Lead paint - to walls and ceiling				N	N
42072	ACTIVE	N	N091-00-3/661/FLR-01	Floor - 1 - Switch Room - Station Building - Camden Town Stn	Cable Ducts: Cement	Asbestos	Presumed				Ducts filled in. Presumed asbestos				N	
16891	ACTIVE	N	N091-00-3/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Camden Town Stn	Isolator Switches	Asbestos	Strongly Presumed				3 x 60amp, 5 x 100amp, 1 x 200amp Switch Boxes - Insulation within		9		N	N
25660	ACTIVE	N	N091-00-3/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Camden Town Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 100 amp, 4 x 60amp Switch Boxes		5		N	N
25659	ACTIVE	N	N091-00-3/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Camden Town Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box		1		N	N
9629	ACTIVE	N	N091-00-3/664	Switch Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16892	ACTIVE	N	N091-00-3/664/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Camden Town Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 60amp, 3 x 60amp Switch Boxes - Insulation within		4		N	N
9630	ACTIVE	N	N091-00-3/671	Switch Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19135	ACTIVE	N	N091-00-3/671	Switch Room - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
9631	ACTIVE	N	N091-00-3/706	IMR - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42076	ACTIVE	N	N091-00-3/706	IMR - Station Building - Camden Town Stn	Other Electrical Boxes	Asbestos	Presumed				Electrical equipment presumed to contain asbestos insulation within		2		N	N
42075	ACTIVE	N	N091-00-3/706	IMR - Station Building - Camden Town Stn	Other Boarding	Asbestos	Presumed				Paxoline Boards to back of room - wall 2				N	N
18603	ACTIVE	N	N091-00-3/706	IMR - Station Building - Camden Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				500m long Cable going into Invert				N	
46830	ACTIVE	N	N091-00-3/706	IMR - Station Building - Camden Town Stn	Other Boarding	Asbestos	Presumed				brown paxoline board to 2boxes wall 3					
46829	ACTIVE	N	N091-00-3/706	IMR - Station Building - Camden Town Stn	Other Boarding	Asbestos	Presumed				Brown paxoline board to wall 1 to 4x boxes					



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46840	ACTIVE	N	N091-00-3/706/CLG-03	Ceiling: Solid - 3 - IMR - Station Building - Camden Town Stn	Other Boarding	Asbestos	Presumed				board to rack - small box shape wall 3					
16893	ACTIVE	N	N091-00-3/706/FLR-01	Floor - 1 - IMR - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux on floors - Non Asbestos					
9632	ACTIVE	N	N091-00-3/713	Relay Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
46831	ACTIVE	N	N091-00-3/713	Relay Room - Station Building - Camden Town Stn	Other Boarding	Asbestos	Presumed				Paxoline Board - wall 3 &4 in first room					
46833	ACTIVE	N	N091-00-3/713	Relay Room - Station Building - Camden Town Stn	Other Boarding	Asbestos	Presumed				Board paxoline to wall 3 & 4					
25673	ACTIVE	N	N091-00-3/713	Relay Room - Station Building - Camden Town Stn	Cable Ducts: Cement	Asbestos	Presumed				Cement Ducts - in two areas of the room				N	
25675	ACTIVE	N	N091-00-3/713	Relay Room - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Boarding					
46832	ACTIVE	N	N091-00-3/713	Relay Room - Station Building - Camden Town Stn	Other Boarding	Asbestos	Presumed				paxoline board to wall 3 & 4 first room					
16895	ACTIVE	N	N091-00-3/713/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - Camden Town Stn	No Access	Asbestos	No Access: Presumed				No Info on Ceiling					
16894	ACTIVE	N	N091-00-3/713/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Camden Town Stn	Vinyl tiles	Asbestos	Surveyed - Not Detected				on Walls (Previously sampled NAD)					
25669	ACTIVE	N	N091-00-3/713/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Camden Town Stn	PCBs	Asbestos	Strongly Presumed				6 x PCB's - fair condition		6		N	N
42328	INACTIVE	N	N091-00-3/713/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Camden Town Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				6 x Silver Cylinder PCB's on Paxo Board		6		N	N
44145	ACTIVE	N	N091-00-3/713/WAL-002 80897650	Wall: Internal - 2 - Relay Room - Station Building - Camden Town Stn Wall: Internal	Other Boarding	Asbestos	Presumed				Paxoline boarding behind PCB cylinders		1		N	N
25676	ACTIVE	N	N091-00-3/713/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Camden Town Stn	Boarding: Cement	Asbestos	Presumed				Approx 40 Arc Chutes		40		N	N
25672	ACTIVE	N	N091-00-3/713/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Camden Town Stn	Other Boarding	Asbestos	Presumed				Paxoline Board		1		N	N
25674	ACTIVE	N	N091-00-3/713/WAL-004 80897652	Wall: Internal - 4 - Relay Room - Station Building - Camden Town Stn Wall: Internal	Cable: Sheath	Asbestos	Sampled - Not Detected				Braided Cables - R713551 - non asbestos - ID confirmed				N	N



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42057	INACTIVE	N	N091-00-3/713/WAL-004 80897652	Wall: Internal - 4 - Relay Room - Station Building - Camden Town Stn Wall: Internal	PCBs	Polychlorinated biphenyl	Strongly Presumed				12 x Silver Cylinder PCB's - Fair condition (above the door & high level); 5 x separate locations on same wall		12		N	N
25670	ACTIVE	N	N091-00-3/713/WAL-009	Wall: Internal - 9 - Relay Room - Station Building - Camden Town Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				2 x Rectifier Boxes		2		N	N
25671	ACTIVE	N	N091-00-3/713/WAL-009	Wall: Internal - 9 - Relay Room - Station Building - Camden Town Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Electrical Box		1		N	N
25668	ACTIVE	N	N091-00-3/713/WAL-010	Wall: Internal - 10 - Relay Room - Station Building - Camden Town Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer		1		N	N
25667	ACTIVE	N	N091-00-3/713/WAL-010	Wall: Internal - 10 - Relay Room - Station Building - Camden Town Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x Switch Boxes (Presumed insulation/rope seal within this older type box)		2		N	N
9633	ACTIVE	N	N091-00-3/714	Relay Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16896	ACTIVE	N	N091-00-3/714	Relay Room - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Boxing - Non Asbestos					
53684	ACTIVE	N	N091-00-3/714	Relay Room - Station Building - Camden Town Stn	Other Boarding	Asbestos	Presumed				composite boarding to wall					
46834	ACTIVE	N	N091-00-3/714	Relay Room - Station Building - Camden Town Stn	Other Boarding	Asbestos	Presumed				paxoline board to wall switch					
18604	ACTIVE	N	N091-00-3/714	Relay Room - Station Building - Camden Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				Various Cables				N	N
46839	ACTIVE	N	N091-00-3/714/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Camden Town Stn	Other Boarding	Asbestos	Presumed				2 x brown paxoline board to boxes wall 3					
9634	ACTIVE	N	N091-00-3/715	Relay Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
16897	ACTIVE	N	N091-00-3/715	Relay Room - Station Building - Camden Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				2x Green Cables feeding electrical box wall 2(back of room)		2			
42079	ACTIVE	N	N091-00-3/715	Relay Room - Station Building - Camden Town Stn	Cable: Sheath	Asbestos	Presumed				Asbestos braided cables presumed within roller shutter cabinet.					
53683	ACTIVE	N	N091-00-3/715	Relay Room - Station Building - Camden Town Stn	Cable Ducts: Cement	Asbestos	Presumed				ducts within roller shutter presumed					
53682	INACTIVE	N	N091-00-3/715	Relay Room - Station Building - Camden Town Stn	Other Boarding	Asbestos	Presumed				brown paxoline board within cupboard					
46838	INACTIVE	N	N091-00-3/715	Relay Room - Station Building - Camden Town Stn	Cable: Sheath	Asbestos	Presumed				2x 50mm green cables into box					



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19136	INACTIVE	N	N091-00-3/715	Relay Room - Station Building - Camden Town Stn	PCBs	Polychlorinated biphenyl	Removed				5 x PCB's (located within roller shutter cabinet) - Poor Condition. Serial Nos not visible - HMU to investigate Removed by Edenbeck Feb 2017		5		N	N
42080	INACTIVE	N	N091-00-3/715/ WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Camden Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				1x Braided cable feeding electrical box					
9635	ACTIVE	N	N091-00-3/716	Relay Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16898	ACTIVE	N	N091-00-3/716	Relay Room - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Panels - Non Asbestos					
18415	ACTIVE	N	N091-00-3/716	Relay Room - Station Building - Camden Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				2m long Cable		1		N	N
42082	ACTIVE	N	N091-00-3/716	Relay Room - Station Building - Camden Town Stn	Cable Ducts: Cement	Asbestos	Presumed				Cable ducts - No access presumed asbestos sleeves within				N	
42081	ACTIVE	N	N091-00-3/716	Relay Room - Station Building - Camden Town Stn	Cable: Sheath	Asbestos	Presumed				Braided cables within roller shutter cabinet				N	N
16899	INACTIVE	N	N091-00-3/716	Relay Room - Station Building - Camden Town Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				3 x PCB's (located within roller shutter cabinet) - Fair Condition. Serial Nos not visible		3		N	N
18910	INACTIVE	N	N091-00-3/791	Vent Shaft - Station Building - Camden Town Stn	Cable: Wrap	Asbestos	Removed				Cable Wrap - Chrysotile Removed by Forest ES5052 15/07/2014					
16900	ACTIVE	N	N091-00-3/791	Vent Shaft - Station Building - Camden Town Stn	Caulking	Asbestos	Surveyed - Not Detected				within Tunnel Rings					
18605	ACTIVE	N	N091-00-3/792	Vent Shaft - Station Building - Camden Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9636	ACTIVE	N	N091-00-3/972	Disused Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16901	ACTIVE	N	N091-00-3/972	Disused Room - Station Building - Camden Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				2m long Cable		1		N	N
16902	ACTIVE	N	N091-00-3/972	Disused Room - Station Building - Camden Town Stn	Cable: Wrap	Asbestos	Surveyed - Not Detected									
9637	ACTIVE	N	N091-00-4/087	Lobby - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18911	ACTIVE	N	N091-00-4/087/ CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Camden Town Stn	Void	Asbestos	Surveyed - Not Detected				Rendered Plaster, Metal Matrix; Sheeting - Non Asbestos				YES	
16903	ACTIVE	N	N091-00-4/087/ CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9638	ACTIVE	N	N091-00-4/204	Passage - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16904	ACTIVE	N	N091-00-4/204	Passage - Station Building - Camden Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9639	ACTIVE	N	N091-00-4/205	Passage - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16905	ACTIVE	N	N091-00-4/205	Passage - Station Building - Camden Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9640	ACTIVE	N	N091-00-4/206	Passage - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16906	ACTIVE	N	N091-00-4/206	Passage - Station Building - Camden Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9641	ACTIVE	N	N091-00-4/601	Stairs: Linear - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18606	ACTIVE	N	N091-00-4/601	Stairs: Linear - Station Building - Camden Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9642	ACTIVE	N	N091-00-4/602	Stairs: Linear - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16907	ACTIVE	N	N091-00-4/602	Stairs: Linear - Station Building - Camden Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9643	ACTIVE	N	N091-00-4/714	Relay Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16908	ACTIVE	N	N091-00-4/714	Relay Room - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel above 4/786					
9644	ACTIVE	N	N091-00-4/715	Relay Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9645	ACTIVE	N	N091-00-4/731	CER - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53617	ACTIVE	N	N091-00-4/731	CER - Station Building - Camden Town Stn	Other Boarding	Asbestos	Sampled – Not Detected				brown composite boarding to wall 2 & 3 - confirmed NAD 4RS- JP-221111-R717826					
9646	ACTIVE	N	N091-00-4/751	Office - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18607	ACTIVE	N	N091-00-4/751/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Camden Town Stn	Void	Asbestos	Surveyed – Not Detected				Sheeting above False Ceiling				YES	
16909	ACTIVE	N	N091-00-4/751/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
9647	ACTIVE	N	N091-00-4/771	Fan Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9648	ACTIVE	N	N091-00-4/776	Fan Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18416	ACTIVE	N	N091-00-4/776	Fan Room - Station Building - Camden Town Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Box - Insulation within		1		N	N
16910	ACTIVE	N	N091-00-4/776	Fan Room - Station Building - Camden Town Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Cementitious Boarding back of Door		1			
9649	ACTIVE	N	N091-00-4/777	Fan Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19361	ACTIVE	N	N091-00-4/777	Fan Room - Station Building - Camden Town Stn	Caulking	Asbestos	Surveyed – Not Detected				within Tunnel Rings					
9650	ACTIVE	N	N091-00-4/778	Fan Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16911	ACTIVE	N	N091-00-4/778/DOR-01	Door - 1 - Fan Room - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Door Panel - Non Asbestos					
9651	ACTIVE	N	N091-00-4/786	Service Riser - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19137	ACTIVE	N	N091-00-4/786	Service Riser - Station Building - Camden Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9652	ACTIVE	N	N091-00-4/952	Disused Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16912	ACTIVE	N	N091-00-4/952/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	
9653	ACTIVE	N	N091-00-4/953	Disused Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18608	ACTIVE	N	N091-00-4/953	Disused Room - Station Building - Camden Town Stn	Cable: Wrap	Asbestos	Surveyed – Not Detected									



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16913	ACTIVE	N	N091-00-4/953	Disused Room - Station Building - Camden Town Stn	Lead/Leading	Lead Paint/Lead	Known				Brown Oil Based Paint - Beam above 4/778. Thickness .24mm; Est Quantity 16sqm; Analysis 6.47%				N	N
9654	ACTIVE	N	N091-00-4/954	Disused Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16914	ACTIVE	N	N091-00-4/954	Disused Room - Station Building - Camden Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9655	ACTIVE	N	N091-00-5/121	Platform Invert - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16915	ACTIVE	N	N091-00-5/121	Platform Invert - Station Building - Camden Town Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Platform Invert - No Access					
9656	ACTIVE	N	N091-00-5/122	Platform Invert - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18609	ACTIVE	N	N091-00-5/122	Platform Invert - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Panel - Non Asbestos					
9657	ACTIVE	N	N091-00-5/201	Passage - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16916	ACTIVE	N	N091-00-5/201	Passage - Station Building - Camden Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9658	ACTIVE	N	N091-00-5/202	Passage - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
20078	ACTIVE	N	N091-00-5/202	Passage - Station Building - Camden Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9659	ACTIVE	N	N091-00-5/203	Passage - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16917	ACTIVE	N	N091-00-5/203	Passage - Station Building - Camden Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9660	ACTIVE	N	N091-00-5/262	Platform 2 - Southbound Local - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16919	ACTIVE	N	N091-00-5/262	Platform 2 - Southbound Local - Station Building - Camden Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				Woven cable at high level into invert. Southbound head wall					
16920	ACTIVE	N	N091-00-5/262	Platform 2 - Southbound Local - Station Building - Camden Town Stn	Cable Ducts: Cement	Asbestos	Known				Cement ducts x 4 southbound Head Wall				N	



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor	
16921	ACTIVE	N	N091-00-5/262	Platform 2 - Southbound Local - Station Building - Camden Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				Approx. 7 x Cables going to Track, 6 x Cables nr 5/121						
46864	ACTIVE	N	N091-00-5/262	Platform 2 - Southbound Local - Station Building - Camden Town Stn	Void	Asbestos	Surveyed – Not Detected				To metal cable trunking CMS						
19138	ACTIVE	N	N091-00-5/262	Platform 2 - Southbound Local - Station Building - Camden Town Stn	Cable Ducts: Cement	Asbestos	Known				2 x Cable Sleeves - Chrysotile near 5/121 invert access						
16918	ACTIVE	N	N091-00-5/262	Platform 2 - Southbound Local - Station Building - Camden Town Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Bitumen duct (2 x) head wall, platform side - NADIS, Bitumen duct (2 x), head wall, below nosing - NADIS Dust, middle of platform 2 in pit - NADIS						
16923	ACTIVE	N	N091-00-5/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Camden Town Stn	Cable Ducts: Cement	Asbestos	Known				Platform 2 Invert - Cable Duct					YES	
18610	ACTIVE	N	N091-00-5/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Camden Town Stn	Cable Ducts: Cement	Asbestos	Known				Cable Sleeve in Floor - Chrysotile Nr 5/706: Cement Around Cable Sleeve - Non Asbestos				N		
16922	ACTIVE	N	N091-00-5/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Camden Town Stn	Cable Ducts: Cement	Asbestos	Known				Platform 2 Invert - 13 x Cables					YES	
9661	ACTIVE	N	N091-00-5/264	Platform 4 - Southbound Fast - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed										
44147	ACTIVE	N	N091-00-5/264	Platform 4 - Southbound Fast - Station Building - Camden Town Stn	Westing house Boxes	Asbestos	Presumed				Westinghouse box located near head wall		1		N	N	
44146	ACTIVE	N	N091-00-5/264	Platform 4 - Southbound Fast - Station Building - Camden Town Stn	Other Electrical Boxes	Asbestos	Presumed				Electrical box located at tail wall, platform 4		1		N	N	
18611	ACTIVE	N	N091-00-5/264	Platform 4 - Southbound Fast - Station Building - Camden Town Stn	Cable: Wrap	Asbestos	Known				1 Lm Wrapping Chrysotile at head wall end of platform				N	N	
44148	ACTIVE	N	N091-00-5/264	Platform 4 - Southbound Fast - Station Building - Camden Town Stn	Lead/Leading	Lead Paint/Lead	Presumed				Blue lead paint paint to Westinghouse box and cream lead paint to pipe work				N	N	
16924	ACTIVE	N	N091-00-5/264/CLG-01	Ceiling: Solid - 1 - Platform 4 - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels above Relay Room - Non Asbestos						
18912	ACTIVE	N	N091-00-5/264/FLR-01	Floor - 1 - Platform 4 - Station Building - Camden Town Stn	Cable Ducts: Cement	Asbestos	No Access: Presumed				2 x Cable Sleeves - Chrysotile - within invert					YES	
16925	ACTIVE	N	N091-00-5/264/FLR-01	Floor - 1 - Platform 4 - Station Building - Camden Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 4 Invert - 6 x Cables					YES	
9662	ACTIVE	N	N091-00-5/406	Store - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed										



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18411	ACTIVE	N	N091-00-5/406	Store - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
16926	ACTIVE	N	N091-00-5/406	Store - Station Building - Camden Town Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
16927	ACTIVE	N	N091-00-5/406	Store - Station Building - Camden Town Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Sink Cabinet & Table - Laminated - Non Asbestos					
16806	ACTIVE	N	N091-00-5/406/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18457	ACTIVE	N	N091-00-5/406/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Camden Town Stn	Void	Asbestos	Surveyed – Not Detected				Metal Roof Beams				YES	
16807	ACTIVE	N	N091-00-5/406/WAL-001	Wall: Internal - 1 - Store - Station Building - Camden Town Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 30amp Grey Switch Box - Insulation within		1		N	N
9663	ACTIVE	N	N091-00-5/591	Disused Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9664	ACTIVE	N	N091-00-5/663	Switch Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16809	ACTIVE	N	N091-00-5/663	Switch Room - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel above entrance					
16808	ACTIVE	N	N091-00-5/663/FLR-01 80897936	Floor - 1 - Switch Room - Station Building - Camden Town Stn Floor	Cable Duct: Other	Asbestos	Presumed				Cable Ducts x 3		3		N	
42084	ACTIVE	N	N091-00-5/663/FLR-01	Floor - 1 - Switch Room - Station Building - Camden Town Stn	Cable Ducts: Cement	Asbestos	Presumed				Potential cable sleeve/sleeves filled in - No access				N	N
42083	ACTIVE	N	N091-00-5/663/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Camden Town Stn	Isolator Switches	Asbestos	Strongly Presumed				1x 100 amps Switch box Wall 1		1		N	N
16810	ACTIVE	N	N091-00-5/663/WAL-002 80897932	Wall: Internal - 2 - Switch Room - Station Building - Camden Town Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				3 x 60amp, 1 x 100amp - Insulation within		4		N	N
25661	ACTIVE	N	N091-00-5/663/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Camden Town Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 30amp Switch Box		1		N	N
9665	ACTIVE	N	N091-00-5/665	Switch Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19486	ACTIVE	N	N091-00-5/665	Switch Room - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding above entrance					



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18519	ACTIVE	N	N091-00-5/665/FLR-01	Floor - 1 - Switch Room - Station Building - Camden Town Stn	Cable Duct: Other	Asbestos	Presumed				Sealed Cable Ducts		3		N	
16811	ACTIVE	N	N091-00-5/665/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Camden Town Stn	Isolator Switches	Asbestos	Strongly Presumed				4 x 60amp Switch Boxes - Insulation within		4		N	N
9666	ACTIVE	N	N091-00-5/670	Switch Cupboard - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16814	ACTIVE	N	N091-00-5/670	Switch Cupboard - Station Building - Camden Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9667	ACTIVE	N	N091-00-5/706	IMR - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
46836	ACTIVE	N	N091-00-5/706	IMR - Station Building - Camden Town Stn	Other Boarding	Asbestos	Presumed				paxoline board to bay sign wall 1					
42085	ACTIVE	N	N091-00-5/706	IMR - Station Building - Camden Town Stn	Other Electrical Boxes	Asbestos	Presumed				1x Switch box presumed to contain asbestos insulation within		1		N	N
16813	ACTIVE	N	N091-00-5/706	IMR - Station Building - Camden Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cable going to Track 1x 30mm diameter white cable		1		N	N
16812	ACTIVE	N	N091-00-5/706	IMR - Station Building - Camden Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables going to Invert 2x 25mm diameter yellow cables 4x 15mm diameter white cables		6		N	N
46837	ACTIVE	N	N091-00-5/706	IMR - Station Building - Camden Town Stn	Other Boarding	Asbestos	Presumed				paxoline board (walls 1 & 3)					
44149	ACTIVE	N	N091-00-5/706 SC10003171	IMR - Station Building - Camden Town Stn Room Assets	Other Boarding	Asbestos	Presumed				Paxoline boarding to wall 1 x 3 boxes				N	N
46835	INACTIVE	N	N091-00-5/706	IMR - Station Building - Camden Town Stn	Other Boarding	Asbestos	Presumed				paxoline board to rack middle					
46841	ACTIVE	N	N091-00-5/706	IMR - Station Building - Camden Town Stn	Other Boarding	Asbestos	Presumed				paxoline board to air off sign to wall 2 back					
9668	ACTIVE	N	N091-00-5/711	Relay Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18520	ACTIVE	N	N091-00-5/711	Relay Room - Station Building - Camden Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9669	ACTIVE	N	N091-00-5/712	Relay Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
44150	ACTIVE	N	N091-00-5/712 SC10003172	Relay Room - Station Building - Camden Town Stn Room Assets	Other Boarding	Asbestos	Presumed				Paxoline boarding in roller shutter cabinets				N	N



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16816	ACTIVE	N	N091-00-5/712/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - Camden Town Stn	Void	Asbestos	Surveyed - Not Detected				Above false Ceiling				YES	
16815	ACTIVE	N	N091-00-5/712/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Board					
25666	ACTIVE	N	N091-00-5/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Camden Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				Braided Cables within roller shutter cabinet				N	N
42087	ACTIVE	N	N091-00-5/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Camden Town Stn	Cable Ducts: Cement	Asbestos	Presumed				Cable sleeves within roller shutter cabinet - No access				N	N
18521	INACTIVE	N	N091-00-5/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Camden Town Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				5 x PCB's - Good Condition. Serial Nos None Visible		5		N	N
9670	ACTIVE	N	N091-00-5/713	Relay Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
42088	ACTIVE	N	N091-00-5/713	Relay Room - Station Building - Camden Town Stn	Cable Ducts: Cement	Asbestos	Presumed				Cable sleeves within roller shutter cabinet filled in - No access				N	
42089	INACTIVE	N	N091-00-5/713	Relay Room - Station Building - Camden Town Stn	Other Electrical Boxes	Asbestos	Presumed				Asbestos flashguards/insulation presumed within this electrical box - box cover removed		1		N	N
19128	ACTIVE	N	N091-00-5/713	Relay Room - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Wall by Door, Fuse Box & Light Switch - Supalux					
16817	INACTIVE	N	N091-00-5/713	Relay Room - Station Building - Camden Town Stn	PCBs	Polychlorinated biphenyl	Removed				5 x PCB's - 4 x Fair Condition, 1 x Possibly leaking - under investigation by the HMU. Serial Nos None Visible. Removed by Edenbeck Feb 2017 ES7773a		5			
46843	ACTIVE	N	N091-00-5/713/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Camden Town Stn	Cable: Sheath	Asbestos	Presumed				white woven cable within 2nd roller shutter cabinet					
46842	ACTIVE	N	N091-00-5/713/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Camden Town Stn	Cable: Sheath	Asbestos	Presumed				2 x 50mm green woven cables to electrical box - within first cabinet and boarding to back of electrical box					
25663	ACTIVE	N	N091-00-5/713/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Camden Town Stn	Cable: Sheath	Asbestos	Strongly Presumed				Braided Cables within roller shutter - may be hidden from view within bunched lead cables				N	N
9671	ACTIVE	N	N091-00-5/951	Disused Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16818	ACTIVE	N	N091-00-5/951	Disused Room - Station Building - Camden Town Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9672	ACTIVE	N	N091-00-A/041	Mess Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18905	ACTIVE	N	N091-00-A/041/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Camden Town Stn	Void	Asbestos	Surveyed – Not Detected				Fibreglass Lagging				YES	
9673	ACTIVE	N	N091-00-A/047	Mess Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16822	ACTIVE	N	N091-00-A/047/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Camden Town Stn	Void	Asbestos	Surveyed – Not Detected				Rock Wool lagging, conduit, all walls plaster				YES	
16819	ACTIVE	N	N091-00-A/047/WAL-002	Wall: Internal - 2 - Mess Room - Station Building - Camden Town Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Acoustic Panel under Sink					
18412	ACTIVE	N	N091-00-A/047/WAL-003	Wall: Internal - 3 - Mess Room - Station Building - Camden Town Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
16820	ACTIVE	N	N091-00-A/047/WAL-004	Wall: Internal - 4 - Mess Room - Station Building - Camden Town Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
18522	ACTIVE	N	N091-00-A/047/WAL-005	Wall: Internal - 5 - Mess Room - Station Building - Camden Town Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
16821	ACTIVE	N	N091-00-A/047/WAL-006	Wall: Internal - 6 - Mess Room - Station Building - Camden Town Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
9674	ACTIVE	N	N091-00-A/048	Locker Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19129	ACTIVE	N	N091-00-A/048	Locker Room - Station Building - Camden Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
9675	ACTIVE	N	N091-00-A/050	Office - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16823	ACTIVE	N	N091-00-A/050/FLR-01	Floor - 1 - Office - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				Beneath Rubber Flooring					YES
9676	ACTIVE	N	N091-00-A/053	Locker Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16824	ACTIVE	N	N091-00-A/053	Locker Room - Station Building - Camden Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9677	ACTIVE	N	N091-00-A/081	Lobby - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18523	ACTIVE	N	N091-00-A/081	Lobby - Station Building - Camden Town Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
9678	ACTIVE	N	N091-00-A/235	Disused Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16825	ACTIVE	N	N091-00-A/235	Disused Room - Station Building - Camden Town Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
9679	ACTIVE	N	N091-00-A/236	Passage - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16826	ACTIVE	N	N091-00-A/236	Passage - Station Building - Camden Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9680	ACTIVE	N	N091-00-A/316	Locker Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
9681	ACTIVE	N	N091-00-A/331	Kitchen - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16827	ACTIVE	N	N091-00-A/331/FLR-01	Floor - 1 - Kitchen - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				Beneath Rubber Flooring					YES
9682	ACTIVE	N	N091-00-A/416	Toilet: Unisex - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18524	ACTIVE	N	N091-00-A/416	Toilet: Unisex - Station Building - Camden Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9683	ACTIVE	N	N091-00-A/418	Toilet: Unisex - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16829	ACTIVE	N	N091-00-A/418/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				Hatch Not Surveyed above False Ceiling				YES	
16828	ACTIVE	N	N091-00-A/418/FLR-01	Floor - 1 - Toilet - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				Beneath Rubber Flooring					YES
9684	ACTIVE	N	N091-00-A/419	Shower Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16830	ACTIVE	N	N091-00-A/419	Shower Room - Station Building - Camden Town Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9685	ACTIVE	N	N091-00-A/578	Stairs: Linear - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16831	ACTIVE	N	N091-00-A/578/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Camden Town Stn	Rope Seals	Asbestos	Strongly Presumed				Glass Canopy - Rope Seal					N
9686	ACTIVE	N	N091-00-A/633	Stairs: Spiral - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16832	ACTIVE	N	N091-00-A/633	Stairs: Spiral - Station Building - Camden Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
16833	ACTIVE	N	N091-00-A/646	Gantry - Station Building - Camden Town Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
9687	ACTIVE	N	N091-00-A/651	Plant Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9688	ACTIVE	N	N091-00-A/661	Switch Room - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16834	ACTIVE	N	N091-00-A/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Camden Town Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x 100amp , 1 x 60amp Switch boxes		3		N	N
18525	ACTIVE	N	N091-00-A/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Camden Town Stn	Rope Gaskets	Asbestos	Sampled – Not Detected				Rope gasket (2 x 2(L)m), within red spot door to wall 2. NADIS					
9689	ACTIVE	N	N091-00-A/731	CER - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18906	ACTIVE	N	N091-00-A/731	CER - Station Building - Camden Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
9690	ACTIVE	N	N091-00-A/801	Lobby - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16836	ACTIVE	N	N091-00-A/801/FLR-01	Floor - 1 - Lobby - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				Beneath Rubber Flooring					YES
20076	INACTIVE	N	N091-00-A/801/FLR-01	Floor - 1 - Lobby - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				Beneath Rubber Flooring					YES
9691	ACTIVE	N	N091-00-A/803	Passage - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16835	ACTIVE	N	N091-00-A/803	Passage - Station Building - Camden Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9692	ACTIVE	N	N091-00-A/804	Office - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46502	ACTIVE	N	N091-00-A/804/FLR-01	Floor - 1 - Office - Station Building - Camden Town Stn	No Access	Asbestos	No Access: Presumed				No Access beneath Flooring					
9693	ACTIVE	N	N091-00-B/236	Passage - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9694	ACTIVE	N	N091-00-B/316	Store - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16837	ACTIVE	N	N091-00-B/316	Store - Station Building - Camden Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
9695	ACTIVE	N	N091-00-B/411	Store - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16838	ACTIVE	N	N091-00-B/411	Store - Station Building - Camden Town Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9696	ACTIVE	N	N091-00-B/412	Store - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9697	ACTIVE	N	N091-00-B/413	Store - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16839	ACTIVE	N	N091-00-B/413	Store - Station Building - Camden Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
9698	ACTIVE	N	N091-00-B/415	Kitchen - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18526	ACTIVE	N	N091-00-B/415/FLR-01	Floor - 1 - Kitchen - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				Beneath Rubber Flooring					YES
9699	ACTIVE	N	N091-00-B/416	Toilet: Female - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16840	ACTIVE	N	N091-00-B/416/FLR-01	Floor - 1 - Toilet - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				Beneath Rubber Flooring					YES
9700	ACTIVE	N	N091-00-B/417	Shower - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16841	ACTIVE	N	N091-00-B/417/FLR-01	Floor - 1 - Shower - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				Beneath Rubber Flooring					YES



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9701	ACTIVE	N	N091-00-B/418	Toilet: Male - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16842	ACTIVE	N	N091-00-B/418	Toilet: Male - Station Building - Camden Town Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
9702	ACTIVE	N	N091-00-B/576	Stairs: Linear - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18413	ACTIVE	N	N091-00-B/576	Stairs: Linear - Station Building - Camden Town Stn	Other Electrical Boxes	Asbestos	No Access: Presumed				Gasket to Lift Motor					
16843	ACTIVE	N	N091-00-B/576	Stairs: Linear - Station Building - Camden Town Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Service Lift Shaft Insulating Board - Non Asbestos					
18527	ACTIVE	N	N091-00-B/576	Stairs: Linear - Station Building - Camden Town Stn	Rope Gaskets	Asbestos	Surveyed – Not Detected				Rope to pulley of sash window , top of stairs - NAD					
9703	ACTIVE	N	N091-00-B/631	Stairs: Spiral - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19130	ACTIVE	N	N091-00-B/631	Stairs: Spiral - Station Building - Camden Town Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
9704	ACTIVE	N	N091-00-B/801	SER - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16844	ACTIVE	N	N091-00-B/801/CLG-01	Ceiling: Solid - 1 - SER - Station Building - Camden Town Stn	Void	Asbestos	Surveyed – Not Detected				Above false Ceiling - Plastic Cable, CMS; Concrete; Artex to Ceiling				YES	
9705	ACTIVE	N	N091-00-B/802	Office - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16845	ACTIVE	N	N091-00-B/802	Office - Station Building - Camden Town Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
16846	ACTIVE	N	N091-00-B/802/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel					
16847	ACTIVE	N	N091-00-B/802/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling				YES	
9706	ACTIVE	N	N091-00-B/803	Store - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18907	ACTIVE	N	N091-00-B/803/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Camden Town Stn	Void	Asbestos	Surveyed – Not Detected				Above Fibre Tiles - Plastic Cables, Armour Flex Lagging; CMS Cable Troughing; Concrete, Metal Mesh; Artex to Ceiling - Non Asbestos - Badly Damaged;				YES	



# Hazardous Material Asset Register - Summary



## N091-00 - Station Building - Camden Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18528	ACTIVE	N	N091-00-B/803/FLR-01	Floor - 1 - Store - Station Building - Camden Town Stn	Void	Asbestos	No Access: Presumed				Concrete, Wood beneath Carpet Tiles, Hard Board and Wood					YES
16848	ACTIVE	N	N091-00-B/803/WAL-002	Wall: Internal - 2 - Store - Station Building - Camden Town Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard					
19359	ACTIVE	N	N091-00-B/803/WAL-003	Wall: Internal - 3 - Store - Station Building - Camden Town Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard					
19131	ACTIVE	N	N091-00-B/803/WAL-004	Wall: Internal - 4 - Store - Station Building - Camden Town Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard					
9707	ACTIVE	N	N091-00-B/804	Store - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
9708	ACTIVE	N	N091-00-B/991	Office - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16849	ACTIVE	N	N091-00-B/991	Office - Station Building - Camden Town Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard					
16850	ACTIVE	N	N091-00-B/991/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Camden Town Stn	Void	Asbestos	Surveyed - Not Detected				Plaster Walls; Wood Panels above Fibreboard Ceiling				YES	
9709	ACTIVE	N	N091-00-B/992	Store - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
9710	ACTIVE	N	N091-00-B/993	Office - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18529	ACTIVE	N	N091-00-B/993	Office - Station Building - Camden Town Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard					
16852	ACTIVE	N	N091-00-B/993/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Camden Town Stn	Void	Asbestos	Surveyed - Not Detected				Rendered Plaster above Supalux Panel				YES	
16851	ACTIVE	N	N091-00-B/993/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Camden Town Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Panel					
9711	ACTIVE	N	N091-00-B/994	Office - Station Building - Camden Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N093-00 - Station Building - Mornington Crescent Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9713	ACTIVE	N	N093-00-1/001	Booking Hall - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19340	ACTIVE	N	N093-00-1/001/FLR-01	Floor - 1 - Booking Hall - Station Building - Mornington Crescent Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl Tiles					
9714	ACTIVE	N	N093-00-1/011	Ticket Office - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19343	ACTIVE	N	N093-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Mornington Crescent Stn	Void	Asbestos	Surveyed – Not Detected				Metal, Fibreglass Lagging above Supalux Tiles				YES	
19342	ACTIVE	N	N093-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Mornington Crescent Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Supalux Tiles					
19341	ACTIVE	N	N093-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Mornington Crescent Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden False Floor					YES
9715	ACTIVE	N	N093-00-1/021	POM - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19385	ACTIVE	N	N093-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Mornington Crescent Stn	Void	Asbestos	Surveyed – Not Detected				Metal, Fibreglass Lagging above Supalux Tiles				YES	
19747	ACTIVE	N	N093-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Mornington Crescent Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Supalux Tiles					
20154	ACTIVE	N	N093-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Mornington Crescent Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden False Floor					YES
9716	ACTIVE	N	N093-00-1/071	Circulation Area - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20153	ACTIVE	N	N093-00-1/071	Circulation Area - Station Building - Mornington Crescent Stn	Lead/Leading	Lead Paint/Lead	Known				Railing & Surround on Staircase: Blue Gloss contains lead levels greater than 1%				N	N
9717	ACTIVE	N	N093-00-1/081	Lobby - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19386	ACTIVE	N	N093-00-1/081/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Mornington Crescent Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
20155	ACTIVE	N	N093-00-1/081/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Mornington Crescent Stn	Void	Asbestos	Surveyed – Not Detected				Above Plasterboard				YES	



# Hazardous Material Asset Register - Summary



## N093-00 - Station Building - Mornington Crescent Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9718	ACTIVE	N	N093-00-1/082	Lobby - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9719	ACTIVE	N	N093-00-1/083	Lobby - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19816	ACTIVE	N	N093-00-1/083	Lobby - Station Building - Mornington Crescent Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
19387	ACTIVE	N	N093-00-1/083/FLR-01	Floor - 1 - Lobby - Station Building - Mornington Crescent Stn	Void	Asbestos	No Access: Presumed				Beneath Lino					YES
9720	ACTIVE	N	N093-00-1/084	Lobby - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19388	ACTIVE	N	N093-00-1/084	Lobby - Station Building - Mornington Crescent Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access Note Building outside Main entrance No key available from StationSupervisor					
9721	ACTIVE	N	N093-00-1/131	LMR - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19389	ACTIVE	N	N093-00-1/131	LMR - Station Building - Mornington Crescent Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard & Superlux Boxing					
19603	ACTIVE	N	N093-00-1/136	Lift Shaft - Station Building - Mornington Crescent Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
9722	ACTIVE	N	N093-00-1/236	Lobby - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20156	ACTIVE	N	N093-00-1/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Mornington Crescent Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Supalux Tiles					
19391	ACTIVE	N	N093-00-1/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Mornington Crescent Stn	Void	Asbestos	Surveyed – Not Detected				Metal, Fibreglass Lagging above Supalux Tiles				YES	
19390	ACTIVE	N	N093-00-1/236/FLR-01	Floor - 1 - Lobby - Station Building - Mornington Crescent Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden False Floor					YES
9723	ACTIVE	N	N093-00-1/341	Mess Room - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9724	ACTIVE	N	N093-00-1/401	Bin Store - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N093-00 - Station Building - Mornington Crescent Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19393	ACTIVE	N	N093-00-1/401/CLG-01	Ceiling: Solid - 1 - Bin Store - Station Building - Mornington Crescent Stn	Void	Asbestos	Surveyed – Not Detected				Above Plasterboard				YES	
19392	ACTIVE	N	N093-00-1/401/CLG-01	Ceiling: Solid - 1 - Bin Store - Station Building - Mornington Crescent Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
9725	ACTIVE	N	N093-00-1/406	Store - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20157	ACTIVE	N	N093-00-1/406	Store - Station Building - Mornington Crescent Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9726	ACTIVE	N	N093-00-1/451	Tenancy - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19394	ACTIVE	N	N093-00-1/451	Tenancy - Station Building - Mornington Crescent Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Tenancy					
19395	ACTIVE	N	N093-00-1/451/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Mornington Crescent Stn	Void	Asbestos	Surveyed – Not Detected				Roof: Bitumen - Non Asbestos				YES	
9727	ACTIVE	N	N093-00-1/551	Yard - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46458	ACTIVE	N	N093-00-1/551	Yard - Station Building - Mornington Crescent Stn		Asbestos	Sampled – Not Detected				Composite strip above guttering and under roof in External area adjacent to Stairs S/576 and Forecourt 1/551	6		R634001	N	N
46456	ACTIVE	N	N093-00-1/551	Yard - Station Building - Mornington Crescent Stn		Asbestos	Sampled – Not Detected				Guttering to fascia timber board in External area adjacent to Stairs S/576 and Forecourt 1/551	6		R634001	N	N
19604	ACTIVE	N	N093-00-1/551	Yard - Station Building - Mornington Crescent Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
46455	ACTIVE	N	N093-00-1/551	Yard - Station Building - Mornington Crescent Stn		Asbestos	Sampled – Not Detected				Composite roofing felt to top of roof in External area adjacent to Stairs S/576 and Forecourt 1/551			R634001	N	N
46457	ACTIVE	N	N093-00-1/551	Yard - Station Building - Mornington Crescent Stn		Asbestos	Sampled – Not Detected				Mastic/sealant to joints of guttering in External area adjacent to Stairs S/576 and Forecourt 1/551	6		R634001	N	N
9728	ACTIVE	N	N093-00-1/576	Stairs: Linear - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19396	ACTIVE	N	N093-00-1/576	Stairs: Linear - Station Building - Mornington Crescent Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9729	ACTIVE	N	N093-00-1/631	Stairs: Spiral - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20158	ACTIVE	N	N093-00-1/631	Stairs: Spiral - Station Building - Mornington Crescent Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N093-00 - Station Building - Mornington Crescent Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9730	ACTIVE	N	N093-00-1/746	Stairs: Linear - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19397	ACTIVE	N	N093-00-1/746	Stairs: Linear - Station Building - Mornington Crescent Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9731	ACTIVE	N	N093-00-1/751	Station Control Room - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20159	ACTIVE	N	N093-00-1/751/CLG-01	Ceiling: Suspended - 1 - Station Control Room - Station Building - Mornington Crescent Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Supalux Tiles					
19817	ACTIVE	N	N093-00-1/751/CLG-01	Ceiling: Suspended - 1 - Station Control Room - Station Building - Mornington Crescent Stn	Void	Asbestos	Surveyed – Not Detected				Metal, Fibreglass Lagging above Supalux Tiles				YES	
19398	ACTIVE	N	N093-00-1/751/FLR-01	Floor - 1 - Station Control Room - Station Building - Mornington Crescent Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
9732	ACTIVE	N	N093-00-2/053	Locker Room - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19399	ACTIVE	N	N093-00-2/053	Locker Room - Station Building - Mornington Crescent Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater Insulation Board Foam					
19400	ACTIVE	N	N093-00-2/053/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Mornington Crescent Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Metal above Supalux Tiles				YES	
19605	ACTIVE	N	N093-00-2/053/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Mornington Crescent Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
9733	ACTIVE	N	N093-00-2/081	Lobby - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19401	ACTIVE	N	N093-00-2/081	Lobby - Station Building - Mornington Crescent Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9734	ACTIVE	N	N093-00-2/201	Passage - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19402	ACTIVE	N	N093-00-2/201	Passage - Station Building - Mornington Crescent Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard Panel, Supalux Boxing					
9735	ACTIVE	N	N093-00-2/236	Passage - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20160	ACTIVE	N	N093-00-2/236	Passage - Station Building - Mornington Crescent Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N093-00 - Station Building - Mornington Crescent Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9736	ACTIVE	N	N093-00-2/281	Locker Room - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19403	ACTIVE	N	N093-00-2/281	Locker Room - Station Building - Mornington Crescent Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9737	ACTIVE	N	N093-00-2/406	Store - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19404	ACTIVE	N	N093-00-2/406	Store - Station Building - Mornington Crescent Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Supalux Boxing					
9738	ACTIVE	N	N093-00-2/411	Store - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19405	ACTIVE	N	N093-00-2/411	Store - Station Building - Mornington Crescent Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9739	ACTIVE	N	N093-00-2/412	Fan Room - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
20161	ACTIVE	N	N093-00-2/412	Fan Room - Station Building - Mornington Crescent Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9740	ACTIVE	N	N093-00-2/416	Toilet: Unisex - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19407	ACTIVE	N	N093-00-2/416/FLR-01	Floor - 1 - Toilet - Station Building - Mornington Crescent Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
19406	ACTIVE	N	N093-00-2/416/FLR-01	Floor - 1 - Toilet - Station Building - Mornington Crescent Stn	Vinyl tiles	Asbestos	Surveyed - Not Detected				Lino					
20162	ACTIVE	N	N093-00-2/416/FLR-01	Floor - 1 - Toilet - Station Building - Mornington Crescent Stn	Void	Asbestos	Surveyed - Not Detected				Metal above Supalux Tiles					YES
9741	ACTIVE	N	N093-00-2/631	Stairs: Spiral - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19408	ACTIVE	N	N093-00-2/631	Stairs: Spiral - Station Building - Mornington Crescent Stn	Caulking	Asbestos	Surveyed - Not Detected				Tunnel ring caulking throughout - Non asbestos					
9742	ACTIVE	N	N093-00-2/632	Stairs: Spiral - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19409	ACTIVE	N	N093-00-2/632	Stairs: Spiral - Station Building - Mornington Crescent Stn		Asbestos	Surveyed - Not Detected				Roof - no asbestos detected					



# Hazardous Material Asset Register - Summary



## N093-00 - Station Building - Mornington Crescent Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19451	ACTIVE	N	N093-00-2/632	Stairs: Spiral - Station Building - Mornington Crescent Stn		Asbestos	Surveyed – Not Detected				Roof - no asbestos detected					
9743	ACTIVE	N	N093-00-2/661	Switch Room - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19452	ACTIVE	N	N093-00-2/661	Switch Room - Station Building - Mornington Crescent Stn	Cable: Sheath	Asbestos	Strongly Presumed				1 x 20mm Cable to Intake Electric Board - poor condition				N	N
20163	ACTIVE	N	N093-00-2/661	Switch Room - Station Building - Mornington Crescent Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				White & Black Lead Paint to Girder above Door - white painted over with black				N	N
9744	ACTIVE	N	N093-00-2/662	Switch Room - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19453	ACTIVE	N	N093-00-2/662	Switch Room - Station Building - Mornington Crescent Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9745	ACTIVE	N	N093-00-2/663	Switch Room - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19454	ACTIVE	N	N093-00-2/663	Switch Room - Station Building - Mornington Crescent Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Supalux Boxing					
9746	ACTIVE	N	N093-00-2/731	Switch Room - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19455	ACTIVE	N	N093-00-2/731/FLR-01	Floor - 1 - Switch Room - Station Building - Mornington Crescent Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden False Floor					YES
9747	ACTIVE	N	N093-00-2/746	SCR - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20164	ACTIVE	N	N093-00-2/746	SCR - Station Building - Mornington Crescent Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9748	ACTIVE	N	N093-00-2/786	Service Riser - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19419	ACTIVE	N	N093-00-2/786	Service Riser - Station Building - Mornington Crescent Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9749	ACTIVE	N	N093-00-2/801	Disused - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20165	ACTIVE	N	N093-00-2/801	Disused - Station Building - Mornington Crescent Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
19456	ACTIVE	N	N093-00-2/801/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Mornington Crescent Stn		Asbestos	Surveyed – Not Detected				Artex - Non Asbestos					



# Hazardous Material Asset Register - Summary



## N093-00 - Station Building - Mornington Crescent Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9750	ACTIVE	N	N093-00-2/802	Disused - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19457	ACTIVE	N	N093-00-2/802	Disused - Station Building - Mornington Crescent Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9751	ACTIVE	N	N093-00-2/991	Store - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19458	ACTIVE	N	N093-00-2/991	Store - Station Building - Mornington Crescent Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Supalux Boxing					
9752	ACTIVE	N	N093-00-2/992	Lobby - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19459	ACTIVE	N	N093-00-2/992	Lobby - Station Building - Mornington Crescent Stn	Other Boarding	Asbestos	Surveyed – Not Detected				New Vermiculite Boxing/Cladding and Supalux Boarding					
9753	ACTIVE	N	N093-00-2/993	Store - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20166	ACTIVE	N	N093-00-2/993	Store - Station Building - Mornington Crescent Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9754	ACTIVE	N	N093-00-3/081	Lobby - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19606	ACTIVE	N	N093-00-3/081	Lobby - Station Building - Mornington Crescent Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Boarding around door					
9755	ACTIVE	N	N093-00-3/731	CER - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19461	ACTIVE	N	N093-00-3/731	CER - Station Building - Mornington Crescent Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Supalux Boxing					
19460	ACTIVE	N	N093-00-3/731/FLR-01	Floor - 1 - CER - Station Building - Mornington Crescent Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden False Floor					YES
9756	ACTIVE	N	N093-00-3/786	Service Riser - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19380	ACTIVE	N	N093-00-3/786	Service Riser - Station Building - Mornington Crescent Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9757	ACTIVE	N	N093-00-4/081	Lobby - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20167	ACTIVE	N	N093-00-4/081/FLR-01	Floor - 1 - Lobby - Station Building - Mornington Crescent Stn	Void	Asbestos	Surveyed – Not Detected				3 x Clay Ducts, PVC Cables beneath Wooden False Floor					YES



# Hazardous Material Asset Register - Summary



## N093-00 - Station Building - Mornington Crescent Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9758	ACTIVE	N	N093-00-4/201	Passage - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19462	ACTIVE	N	N093-00-4/201	Passage - Station Building - Mornington Crescent Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9759	ACTIVE	N	N093-00-4/202	Passage - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19463	ACTIVE	N	N093-00-4/202/FLR-01	Floor - 1 - Passage - Station Building - Mornington Crescent Stn	Void	Asbestos	Surveyed - Not Detected				Clay Ducts beneath Tiles					YES
9760	ACTIVE	N	N093-00-4/203	Passage - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19464	ACTIVE	N	N093-00-4/203	Passage - Station Building - Mornington Crescent Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9761	ACTIVE	N	N093-00-4/204	Passage - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19465	ACTIVE	N	N093-00-4/204/FLR-01	Floor - 1 - Passage - Station Building - Mornington Crescent Stn	Void	Asbestos	Surveyed - Not Detected				Clay Ducts beneath Tiles					YES
9762	ACTIVE	N	N093-00-4/205	Passage - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19607	ACTIVE	N	N093-00-4/205	Passage - Station Building - Mornington Crescent Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9763	ACTIVE	N	N093-00-4/206	Passage - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19466	ACTIVE	N	N093-00-4/206/FLR-01	Floor - 1 - Passage - Station Building - Mornington Crescent Stn	Void	Asbestos	Surveyed - Not Detected				Clay Ducts beneath Tiles					YES
9764	ACTIVE	N	N093-00-4/207	Passage - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19467	ACTIVE	N	N093-00-4/207	Passage - Station Building - Mornington Crescent Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
20168	ACTIVE	N	N093-00-4/207	Passage - Station Building - Mornington Crescent Stn	Lead/Leading	Lead Paint/Lead	Known				Overbridge Panels: Cream Gloss Paint contains lead levels greater than 1%				N	N
9765	ACTIVE	N	N093-00-4/601	Stairs: Linear - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N093-00 - Station Building - Mornington Crescent Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19468	ACTIVE	N	N093-00-4/601	Stairs: Linear - Station Building - Mornington Crescent Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9766	ACTIVE	N	N093-00-4/602	Stairs: Linear - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19469	ACTIVE	N	N093-00-4/602/FLR-01	Floor - 1 - Station Building - Mornington Crescent Stn	Void	Asbestos	Surveyed – Not Detected				Cement & Bitumen Ducts - Non Asbestos					YES
9767	ACTIVE	N	N093-00-4/661	CER - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20169	ACTIVE	N	N093-00-4/661	CER - Station Building - Mornington Crescent Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9768	ACTIVE	N	N093-00-4/731	CER - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19470	ACTIVE	N	N093-00-4/731	CER - Station Building - Mornington Crescent Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard Boxing					
19239	ACTIVE	N	N093-00-4/787	Vent Shaft - Station Building - Mornington Crescent Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9769	ACTIVE	N	N093-00-4/791	Air Plenum - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19472	ACTIVE	N	N093-00-4/791	Air Plenum - Station Building - Mornington Crescent Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
19818	ACTIVE	N	N093-00-4/901	Vent Shaft - Station Building - Mornington Crescent Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board Boxing					
19473	ACTIVE	N	N093-00-4/901	Vent Shaft - Station Building - Mornington Crescent Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Cord Beams					
19169	ACTIVE	N	N093-00-4/901/FLR-01	Floor - 1 - Vent Shaft - Station Building - Mornington Crescent Stn	Void	Asbestos	Surveyed – Not Detected				Metal; Solid, Concrete					YES
9770	ACTIVE	N	N093-00-5/201	Passage - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19474	ACTIVE	N	N093-00-5/201	Passage - Station Building - Mornington Crescent Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9771	ACTIVE	N	N093-00-5/202	Passage - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19475	ACTIVE	N	N093-00-5/202	Passage - Station Building - Mornington Crescent Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N093-00 - Station Building - Mornington Crescent Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9772	ACTIVE	N	N093-00-5/203	Passage - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19476	ACTIVE	N	N093-00-5/203	Passage - Station Building - Mornington Crescent Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard Boxing					
19608	ACTIVE	N	N093-00-5/203/FLR-01	Floor - 1 - Passage - Station Building - Mornington Crescent Stn	Void	Asbestos	Surveyed - Not Detected				Clay Ducts beneath Tiles					YES
9773	ACTIVE	N	N093-00-5/204	Passage - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19321	ACTIVE	N	N093-00-5/204	Passage - Station Building - Mornington Crescent Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard Boxing					
9774	ACTIVE	N	N093-00-5/261	Platform 1 - Northbound Local - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19477	ACTIVE	N	N093-00-5/261	Platform 1 - Northbound Local - Station Building - Mornington Crescent Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Panel inside Auto Phone & Tunnel Phone Panel					
19819	ACTIVE	N	N093-00-5/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Mornington Crescent Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - Cables No access within invert 2020 re-inspection as confined space team required.		6			YES
19515	ACTIVE	N	N093-00-5/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Mornington Crescent Stn	Cable Ducts: Cement	Asbestos	Known				Platform 1 Invert - Cable Sleeves - Chrysotile No access within invert 2020 re-inspection as confined space team required.		4			YES
9775	ACTIVE	N	N093-00-5/262	Platform 2 - Southbound Local - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19516	ACTIVE	N	N093-00-5/262	Platform 2 - Southbound Local - Station Building - Mornington Crescent Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Panel inside Auto Phone & Tunnel Phone Panel					
19517	ACTIVE	N	N093-00-5/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Mornington Crescent Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - 1 x Brown Cable No access within invert 2020 re-inspection as confined space team required.				N	YES
9776	ACTIVE	N	N093-00-5/661	Switch Room - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19518	ACTIVE	N	N093-00-5/661	Switch Room - Station Building - Mornington Crescent Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9777	ACTIVE	N	N093-00-5/662	Switch Room - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N093-00 - Station Building - Mornington Crescent Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19170	ACTIVE	N	N093-00-5/662	Switch Room - Station Building - Mornington Crescent Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9778	ACTIVE	N	N093-00-5/711	IMR - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44167	ACTIVE	N	N093-00-5/711	IMR - Station Building - Mornington Crescent Stn	Other Boarding	Asbestos	Sampled – Not Detected				4 x Paxoline boarding to wall 3 - ID confirmed non asbestos 4RS-JP-211347-R710926					
19519	ACTIVE	N	N093-00-5/711 80143136	IMR - Station Building - Mornington Crescent Stn Room Assets	Cable: Sheath	Asbestos	Known				20mm woven sheath to pipework - confirmed ACM - R710926		1		N	N
42330	INACTIVE	N	N093-00-5/711 80143136	IMR - Station Building - Mornington Crescent Stn Room Assets	PCBs	Polychlorinated biphenyl	Strongly Presumed				1 x 1 x medium silver cylinder PCB wall 3 up high		1		N	N
53624	ACTIVE	N	N093-00-5/711/ WAL-003	Wall: Internal - 3 - IMR - Station Building - Mornington Crescent Stn	Other Electrical Boxes	Asbestos	Presumed				materials within rectifiers x 2 to wall 3					
53625	ACTIVE	N	N093-00-5/711/ WAL-003	Wall: Internal - 3 - IMR - Station Building - Mornington Crescent Stn	Other Electrical Boxes	Asbestos	Presumed				materials within transformers x2 to wall 3					
9779	ACTIVE	N	N093-00-5/712	Relay Room - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19609	ACTIVE	N	N093-00-5/712	Relay Room - Station Building - Mornington Crescent Stn	Cable Duct: Other	Asbestos	Presumed				Ducts behind Shutters				N	N
19520	ACTIVE	N	N093-00-5/712	Relay Room - Station Building - Mornington Crescent Stn	Cable: Sheath	Asbestos	Strongly Presumed				50mm Cable		2			
42153	ACTIVE	N	N093-00-5/712	Relay Room - Station Building - Mornington Crescent Stn	Cable Ducts: Cement	Asbestos	Presumed				Concrete ducts filled in - No access. Presumed asbestos ducts below				N	
44166	ACTIVE	N	N093-00-5/712	Relay Room - Station Building - Mornington Crescent Stn	Other Boarding	Asbestos	Presumed				Paxoline various behind roller shutter				N	N
42329	INACTIVE	N	N093-00-5/712	Relay Room - Station Building - Mornington Crescent Stn	PCBs	Polychlorinated biphenyl	Presumed				1 x medium silver cylinder PCB		1		N	N
25693	INACTIVE	N	N093-00-5/712/ WAL-001 80908298	Wall: Internal - 1 - Relay Room - Station Building - Mornington Crescent Stn Wall: Internal	PCBs	Polychlorinated biphenyl	Strongly Presumed				Approx 5 x PCB's - fair condition black boxes		5		N	N
9780	ACTIVE	N	N093-00-5/771	Pump Room - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19521	ACTIVE	N	N093-00-5/771	Pump Room - Station Building - Mornington Crescent Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Supalux Boxing					
9781	ACTIVE	N	N093-00-A/082	Lobby - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N093-00 - Station Building - Mornington Crescent Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19171	ACTIVE	N	N093-00-A/082	Lobby - Station Building - Mornington Crescent Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9782	ACTIVE	N	N093-00-A/131	LMR - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19523	ACTIVE	N	N093-00-A/131	LMR - Station Building - Mornington Crescent Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Lead paint to Girders					
19522	ACTIVE	N	N093-00-A/131/WAL-001	Wall: Internal - 1 - LMR - Station Building - Mornington Crescent Stn	Isolator Switches	Asbestos	Strongly Presumed				300amp Switch Box - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1		N	N
25694	ACTIVE	N	N093-00-A/131/WAL-001	Wall: Internal - 1 - LMR - Station Building - Mornington Crescent Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
9783	ACTIVE	N	N093-00-A/351	Mess Room - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19172	ACTIVE	N	N093-00-A/351	Mess Room - Station Building - Mornington Crescent Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
19524	ACTIVE	N	N093-00-A/351	Mess Room - Station Building - Mornington Crescent Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
9784	ACTIVE	N	N093-00-A/416	Toilet: Unisex - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19525	ACTIVE	N	N093-00-A/416	Toilet: Unisex - Station Building - Mornington Crescent Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
9785	ACTIVE	N	N093-00-A/576	Stairs: Linear - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
9786	ACTIVE	N	N093-00-A/577	Stairs: Linear - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9787	ACTIVE	N	N093-00-A/781	Transformer Room - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19526	ACTIVE	N	N093-00-A/781	Transformer Room - Station Building - Mornington Crescent Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access Note this room is Alamed, Station Supervisor dose not have access of key number					
9788	ACTIVE	N	N093-00-A/801	Disused - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N093-00 - Station Building - Mornington Crescent Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19240	ACTIVE	N	N093-00-A/801	Disused - Station Building - Mornington Crescent Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
19173	ACTIVE	N	N093-00-A/801/FLR-01	Floor - 1 - Office - Station Building - Mornington Crescent Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Lino					
9789	ACTIVE	N	N093-00-A/803	Office - Station Building - Mornington Crescent Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19527	ACTIVE	N	N093-00-A/803	Office - Station Building - Mornington Crescent Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Supalux Boxing					
19338	ACTIVE	N	N093-00/ROF-01	Structure: Roof - 1 - Station Building - Mornington Crescent Stn		Asbestos	Surveyed – Not Detected				No glazing panels or rope seal; Roof felt - All New					
19339	ACTIVE	N	N093-00/ROF-02	Structure: Roof - 2 - Station Building - Mornington Crescent Stn		Asbestos	Surveyed – Not Detected				No glazing panels or rope seal; Roof felt - All New					

## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9790	ACTIVE	N	N095-00-2/001	Booking Hall - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15257	ACTIVE	N	N095-00-2/001/CLG-01	Ceiling: Suspended - 1 - Booking Hall - Station Building - Euston Stn	Void	Asbestos	Surveyed – Not Detected				Insulated Plastic Cables; Fire Break Panel; Concrete				YES	
9791	ACTIVE	N	N095-00-2/011	Ticket Office - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18016	ACTIVE	N	N095-00-2/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Euston Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Fibreglass Lagging above Acoustic Panel				YES	
15258	ACTIVE	N	N095-00-2/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Beneath False Wooden Floor No access beneath fixed raised floor during 2020 re-inspection.					YES
9792	ACTIVE	N	N095-00-2/021	POM - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15260	ACTIVE	N	N095-00-2/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Euston Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Metal Vent Ducts above Acoustic Panel				YES	
15259	ACTIVE	N	N095-00-2/021/FLR-01	Floor - 1 - POM - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				No Access below Computer Flooring Tiles.					YES



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9793	ACTIVE	N	N095-00-2/031	Mess Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15261	ACTIVE	N	N095-00-2/031	Mess Room - Station Building - Euston Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
15262	ACTIVE	N	N095-00-2/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Euston Stn	Void	Asbestos	Surveyed – Not Detected				Fibreglass Lagging above Acoustic Panel				YES	
9794	ACTIVE	N	N095-00-2/036	Toilet: Unisex - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15263	ACTIVE	N	N095-00-2/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Acoustic Panel No access above acoustic panel during 2020 re-inspection.					
9795	ACTIVE	N	N095-00-2/037	Lobby - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18017	ACTIVE	N	N095-00-2/037/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Acoustic Panel No access above acoustic panel during 2020 re-inspection.					
9796	ACTIVE	N	N095-00-2/071	Circulation Area - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15264	ACTIVE	N	N095-00-2/071/CLG-01	Ceiling: Suspended - 1 - Circulation Area - Station Building - Euston Stn	Void	Asbestos	Surveyed – Not Detected				Above Metal Ceiling - Insulated Plastic Cables; Fire Break Panel - Non Asbestos				YES	
9797	ACTIVE	N	N095-00-2/151	UMC - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15265	ACTIVE	N	N095-00-2/151	UMC - Station Building - Euston Stn	Caulking	Asbestos	Known				Known Asbestos - Caulking in Tunnel Ring Joints and Flanges throughout inclines No access into inclines during 2020 re-inspection - permit required with L&E.					
15269	ACTIVE	N	N095-00-2/151	UMC - Station Building - Euston Stn	Other Electrical Boxes	Asbestos	Presumed				Various Electrical Boxes					
44360	ACTIVE	N	N095-00-2/151	UMC - Station Building - Euston Stn	Gasket :Pipework	Asbestos	Presumed				Gaskets to Bolted Joints on pipe work					
45001	INACTIVE	N	N095-00-2/151	UMC - Station Building - Euston Stn	Rope Gaskets	Asbestos	Strongly Presumed				Gasket to Ventilation Fan				N	N
15268	ACTIVE	N	N095-00-2/151	UMC - Station Building - Euston Stn	Cable Duct: Other	Asbestos	Known				Mastic to Flanges within AC Duct in UMC Active - ductwork with mastic to joints is present in 2020 re-inspection					



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15270	ACTIVE	N	N095-00-2/151	UMC - Station Building - Euston Stn	Westing house Boxes	Asbestos	Removed				Insulation within - 3no Westinghouse Boxes by Access B Removed by others - confirmed 26/06/2014		3			
15267	ACTIVE	N	N095-00-2/151	UMC - Station Building - Euston Stn	Rope Gaskets	Asbestos	Known				Rope Gaskets to Joints to Ventilation Equipment					
18559	ACTIVE	N	N095-00-2/151	UMC - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				Various Cables - SP					
20264	ACTIVE	N	N095-00-2/151	UMC - Station Building - Euston Stn	Other Electrical Boxes	Asbestos	Presumed				Various Pump Controllers - Other Electrical Equipment					
25858	ACTIVE	N	N095-00-2/151	UMC - Station Building - Euston Stn	Rope Seals	Asbestos	Surveyed – Not Detected				New Gaiters to Fan Equipment - Non Asbestos					
18018	ACTIVE	N	N095-00-2/151	UMC - Station Building - Euston Stn	Mastic	Asbestos	Strongly Presumed				Chrysotile Mastic to Flange to AC Duct in UMC					
15266	ACTIVE	N	N095-00-2/151/FLR-01	Floor - 1 - UMC - Station Building - Euston Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes - Insulation within 2no 60amps on freestanding frame		2			
9798	ACTIVE	N	N095-00-2/201	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos				Room Surveyed - No asbestos Detected					
15271	INACTIVE	N	N095-00-2/201	Passage - Station Building - Euston Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - No Access					
9799	ACTIVE	N	N095-00-2/202	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19295	ACTIVE	N	N095-00-2/202/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Fire Break					
9800	ACTIVE	N	N095-00-2/203	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18560	ACTIVE	N	N095-00-2/203	Passage - Station Building - Euston Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9801	ACTIVE	N	N095-00-2/237	Lobby - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15272	ACTIVE	N	N095-00-2/237/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Acoustic Panel No access above acoustic panel during 2020 re-inspection					
18019	ACTIVE	N	N095-00-2/237/FLR-01	Floor - 1 - Lobby - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Beneath - Computer Tiles No access beneath tiles fixed to floor during 2020 re-inspection					YES
9802	ACTIVE	N	N095-00-2/238	Lobby - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15273	ACTIVE	N	N095-00-2/238/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
15274	ACTIVE	N	N095-00-2/238/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Euston Stn	Void	Asbestos	Surveyed – Not Detected				Brick Wall; Fibreglass Lagging; Supalux Boxing; Concrete above Supalux Tiles				YES	
9803	ACTIVE	N	N095-00-2/239	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18581	ACTIVE	N	N095-00-2/239	Passage - Station Building - Euston Stn	No Access	Asbestos	Surveyed – Not Detected				New Construction					
9804	ACTIVE	N	N095-00-2/301	Tenancy - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15275	ACTIVE	N	N095-00-2/301	Tenancy - Station Building - Euston Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - Foam Insulation Board					
18020	ACTIVE	N	N095-00-2/301/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Euston Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Brick Walls; Supalux Fire Break above Plasterboard				YES	
15276	ACTIVE	N	N095-00-2/301/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Euston Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
9805	ACTIVE	N	N095-00-2/306	Station Supervisor Office - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15277	ACTIVE	N	N095-00-2/306/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Euston Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Supalux Fire Break above Acoustic Panel				YES	
9806	ACTIVE	N	N095-00-2/311	Office - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15278	ACTIVE	N	N095-00-2/311/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Acoustic Panel No access above acoustic panel during 2020 re-inspection					
9807	ACTIVE	N	N095-00-2/331	Mess Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15280	ACTIVE	N	N095-00-2/331	Mess Room - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing					
15279	ACTIVE	N	N095-00-2/331	Mess Room - Station Building - Euston Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
18624	ACTIVE	N	N095-00-2/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Euston Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Fibreglass Supalux above Supalux Tiles				YES	



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15281	ACTIVE	N	N095-00-2/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
9808	ACTIVE	N	N095-00-2/366	Mess Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18021	ACTIVE	N	N095-00-2/366	Mess Room - Station Building - Euston Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
15282	ACTIVE	N	N095-00-2/366	Mess Room - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing					
15283	ACTIVE	N	N095-00-2/366/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
15284	ACTIVE	N	N095-00-2/366/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Supalux Boarding No access above supalux ceiling during 2020 re-inspection					
9809	ACTIVE	N	N095-00-2/371	Switch Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18022	ACTIVE	N	N095-00-2/371	Switch Room - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
9810	ACTIVE	N	N095-00-2/406	Locker Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15285	ACTIVE	N	N095-00-2/406	Locker Room - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing					
9811	ACTIVE	N	N095-00-2/411	Locker Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18169	ACTIVE	N	N095-00-2/411	Locker Room - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
15286	ACTIVE	N	N095-00-2/411/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Euston Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Brick Walls above False Ceiling				YES	
9812	ACTIVE	N	N095-00-2/416	Toilet: Male - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15287	ACTIVE	N	N095-00-2/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18476	ACTIVE	N	N095-00-2/416/CLG-02	Ceiling: Suspended - 2 - Toilet - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles No access above fixed supalux tiles during 2020 re-inspection.					



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9813	ACTIVE	N	N095-00-2/417	Toilet: Female - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18023	ACTIVE	N	N095-00-2/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
15288	ACTIVE	N	N095-00-2/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Euston Stn	Void	Asbestos	Surveyed - Not Detected				Above Supalux Tiles - Concrete; Brick Wall; Fibreglass Lagging; Metal Vent Ducts				YES	
9814	ACTIVE	N	N095-00-2/418	Lobby - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15289	ACTIVE	N	N095-00-2/418/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
18625	ACTIVE	N	N095-00-2/418/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles No access above fixed supalux tiles during 2020 re-inspection.					
9815	ACTIVE	N	N095-00-2/419	Lobby - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15291	ACTIVE	N	N095-00-2/419/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Euston Stn	Void	Asbestos	Surveyed - Not Detected				Above Supalux Tiles - Concrete; Brick Wall; Fibreglass Lagging; Metal Vent Ducts				YES	
15290	ACTIVE	N	N095-00-2/419/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
9816	ACTIVE	N	N095-00-2/451	Station Control Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18024	ACTIVE	N	N095-00-2/451	Station Control Room - Station Building - Euston Stn	No Access	Asbestos	Surveyed - Not Detected				No Access - New Construction					
9817	ACTIVE	N	N095-00-2/452	Lobby - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15292	ACTIVE	N	N095-00-2/452	Lobby - Station Building - Euston Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access No access during 2020 re-inspection - private property keys with station office.					
9818	ACTIVE	N	N095-00-2/453	ATM - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15293	ACTIVE	N	N095-00-2/453	ATM - Station Building - Euston Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access ATM - Tenancy - Generally No Access					
9819	ACTIVE	N	N095-00-2/454	ATM - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9820	ACTIVE	N	N095-00-2/665	Switch Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Surveyed – Asbestos Known									
25857	ACTIVE	N	N095-00-2/665	Switch Room - Station Building - Euston Stn	Mastic	Asbestos	Presumed				Mastic Material to Joint in AC Ventilation					
44364	ACTIVE	N	N095-00-2/665	Switch Room - Station Building - Euston Stn	Other Boarding	Asbestos	Presumed				Paxoline packing between electrical boxes					
18025	ACTIVE	N	N095-00-2/665/FLR-01	Floor - 1 - Switch Room - Station Building - Euston Stn	Vinyl tiles	Asbestos	Presumed				Vinyl Tiles 2020 re-inspection - bitumen adhesive beneath tiles also presumed to contain chrysotile					
25859	ACTIVE	N	N095-00-2/665/FLR-01	Floor - 1 - Switch Room - Station Building - Euston Stn	Cable Duct: Other	Asbestos	Presumed				Various Cable Ducts - Sealed over; On Floor by Walls 1,2,4 ducts not visible beneath filling therefore materials not scored during 2020 re-inspection.					
44363	ACTIVE	N	N095-00-2/665/FLR-01 80900513	Floor - 1 - Switch Room - Station Building - Euston Stn Floor	Cable: Sheath	Asbestos	Strongly Presumed				2no 50mm cables from UMC? to electrical boxes					
44362	INACTIVE	N	N095-00-2/665/WAL-001 80900508	Wall: Internal - 1 - Switch Room - Station Building - Euston Stn Wall: Internal	Isolator Switches	Asbestos	Presumed				5no 3x 30amp, 1x 100 1x 200					
15295	ACTIVE	N	N095-00-2/665/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Euston Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes - Insulation within 3x 30amp, 1x 100amp, 1x 200amp		5			
15298	INACTIVE	N	N095-00-2/665/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Euston Stn	Other Boarding	Asbestos	Removed				Paxoline Board to Meter Not found on re-inspection 26/06/2014 - Removed by others?					
15297	ACTIVE	N	N095-00-2/665/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Euston Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es) - Insulation within		1			
20260	ACTIVE	N	N095-00-2/665/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Euston Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes - Insulation within 2x 100amp		2			
20263	ACTIVE	N	N095-00-2/665/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Euston Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es) - Insulation within		1			
20261	ACTIVE	N	N095-00-2/665/WAL-004 80900511	Wall: Internal - 4 - Switch Room - Station Building - Euston Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes - Insulation within; 2no 100amps, 1no 30amps, 1no 200amps		4			
20262	ACTIVE	N	N095-00-2/665/WAL-004 80900511	Wall: Internal - 4 - Switch Room - Station Building - Euston Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es) - Insulation within		2			
15296	ACTIVE	N	N095-00-2/665/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing to Ventilation/Fan Equipment by Door					
9821	ACTIVE	N	N095-00-2/666	Switch Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18626	ACTIVE	N	N095-00-2/666	Switch Room - Station Building - Euston Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes - Insulation within W4 3x60, 1x200; W2 2x 30amp; W3 5x60 2x200		13			



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18170	ACTIVE	N	N095-00-2/666	Switch Room - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing					
25860	ACTIVE	N	N095-00-2/666	Switch Room - Station Building - Euston Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Boxes		6			
9822	ACTIVE	N	N095-00-2/667	Switch Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15299	ACTIVE	N	N095-00-2/667/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
18026	ACTIVE	N	N095-00-2/667/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Supalux Ceiling No access above supalux fixed ceiling during 2020 re-inspection.					
9823	ACTIVE	N	N095-00-2/668	Switch Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15300	ACTIVE	N	N095-00-2/668	Switch Room - Station Building - Euston Stn	No Access	Asbestos	Surveyed – Not Detected				New Construction					
9824	ACTIVE	N	N095-00-2/711	Pump Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9825	ACTIVE	N	N095-00-2/731	CER - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15302	ACTIVE	N	N095-00-2/731	CER - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing					
9826	ACTIVE	N	N095-00-2/746	SCR - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15303	ACTIVE	N	N095-00-2/746	SCR - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing					
9827	ACTIVE	N	N095-00-2/751	Station Control Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18231	ACTIVE	N	N095-00-2/751/CLG-01	Ceiling: Suspended - 1 - Station Control Room - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18027	ACTIVE	N	N095-00-2/751/CLG-01	Ceiling: Suspended - 1 - Station Control Room - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles No access above fixed supalux ceiling tiles during 2020 re-inspection.					
15304	ACTIVE	N	N095-00-2/751/FLR-01	Floor - 1 - Station Control Room - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Beneath False Wooden Floor No access below fixed raised floor during 2020 re-inspection.					YES



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9828	ACTIVE	N	N095-00-2/761	SVC - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15308	ACTIVE	N	N095-00-2/761	SVC - Station Building - Euston Stn	Cable: Wrap	Asbestos	Surveyed – Not Detected				Bonzo Tape on Pipes Non Asbestos					
15307	ACTIVE	N	N095-00-2/761	SVC - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing and Boarding on Wall. Bonzo Tape on Pipes Non Asbestos					
15306	ACTIVE	N	N095-00-2/761/ FLR-01	Floor - 1 - SVC - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
15305	ACTIVE	N	N095-00-2/761/ FLR-01	Floor - 1 - SVC - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Beneath False Wooden / Supalux Floor  No access beneath raised floor during 2020 re-inspection.					YES
9829	ACTIVE	N	N095-00-2/762	Disused Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18028	ACTIVE	N	N095-00-2/762/ CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels, Metal Beam					
9830	ACTIVE	N	N095-00-2/771	Pump Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15309	ACTIVE	N	N095-00-2/771	Pump Room - Station Building - Euston Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9831	ACTIVE	N	N095-00-2/781	Transformer Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15310	ACTIVE	N	N095-00-2/781	Transformer Room - Station Building - Euston Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access UK Power Network Asset					
15311	ACTIVE	N	N095-00-2/791	Vent Shaft - Station Building - Euston Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9832	ACTIVE	N	N095-00-2/901	Disused Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18627	ACTIVE	N	N095-00-2/901	Disused Room - Station Building - Euston Stn	No Access	Asbestos	Surveyed – Not Detected				No Asbestos Detected, but no access to High Level Areas;					
9833	ACTIVE	N	N095-00-2/951	Void - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15312	ACTIVE	N	N095-00-2/951	Void - Station Building - Euston Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9834	ACTIVE	N	N095-00-3/091	Circulation Area - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18089	ACTIVE	N	N095-00-3/091/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling No access above fixed metal false ceiling during 2020 re-inspection.					
15313	ACTIVE	N	N095-00-3/091/FLR-01	Floor - 1 - Circulation Area - Station Building - Euston Stn	Cable Ducts: Cement	Asbestos	Known				Cable Sleeves - Chrysotile (Beneath circulating area facing opposite 3/202) No access into floor duct during 2020 re-inspection. Lifting equipment required.		4			
9835	ACTIVE	N	N095-00-3/092	Circulation Area - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15315	ACTIVE	N	N095-00-3/092	Circulation Area - Station Building - Euston Stn	Caulking	Asbestos	Known				Tunnel Ring Caulking - Amphibole No access above fixed metal false ceiling during 2020 re-inspection.					
15314	ACTIVE	N	N095-00-3/092/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling No access above fixed metal false ceiling during 2020 re-inspection.					
9836	ACTIVE	N	N095-00-3/093	Circulation Area - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15316	ACTIVE	N	N095-00-3/093	Circulation Area - Station Building - Euston Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking No access above fixed metal false ceiling during 2020 re-inspection.					
18582	ACTIVE	N	N095-00-3/093/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling No access above fixed metal false ceiling during 2020 re-inspection.					
9837	ACTIVE	N	N095-00-3/094	Circulation Area - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45002	ACTIVE	N	N095-00-3/094	Circulation Area - Station Building - Euston Stn	Caulking	Asbestos	Presumed				Tunnel ring caulking presumed as no access was possible to sample tunnel rings				N	N
15317	ACTIVE	N	N095-00-3/094/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling - Caulking / Cellactite SP Above					
9838	ACTIVE	N	N095-00-3/121	Service Riser - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18628	ACTIVE	N	N095-00-3/121	Service Riser - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables No access into service riser during 2020 re-inspection. Confined space.		6			



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9839	ACTIVE	N	N095-00-3/122	Service Riser - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18090	ACTIVE	N	N095-00-3/122	Service Riser - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables		3			
15318	ACTIVE	N	N095-00-3/122	Service Riser - Station Building - Euston Stn	Mastic	Asbestos	Presumed				Trunking to Ventilation Equipment - Mastic to Joints					
9840	ACTIVE	N	N095-00-3/123	Service Riser - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15319	ACTIVE	N	N095-00-3/123	Service Riser - Station Building - Euston Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9841	ACTIVE	N	N095-00-3/124	Service Riser - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15320	ACTIVE	N	N095-00-3/124	Service Riser - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables		2			
18091	ACTIVE	N	N095-00-3/124/FLR-01	Floor - 1 - Service Riser - Station Building - Euston Stn	Cable Ducts: Cement	Asbestos	Known				Cable Sleeves - Chrysotile No access into service during 2020 re-inspection. Confined space.		22			
9842	ACTIVE	N	N095-00-3/125	Service Riser - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15321	ACTIVE	N	N095-00-3/125	Service Riser - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables No access into service riser during 2020 re-inspection. Confined space.		4			
19427	ACTIVE	N	N095-00-3/125/FLR-01	Floor - 1 - Service Riser - Station Building - Euston Stn	Cable Ducts: Cement	Asbestos	Known				Cable Sleeves - Chrysotile No access into service riser during 2020 re-inspection. Confined space.		10			
9843	ACTIVE	N	N095-00-3/126	Service Riser - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18629	ACTIVE	N	N095-00-3/126	Service Riser - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables		7			
15322	ACTIVE	N	N095-00-3/126/FLR-01	Floor - 1 - Service Riser - Station Building - Euston Stn	Cable Ducts: Cement	Asbestos	Known				Various Cable Sleeves - Chrysotile					
9844	ACTIVE	N	N095-00-3/151	UMC - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18092	ACTIVE	N	N095-00-3/151	UMC - Station Building - Euston Stn	Cable Ducts: Cement	Asbestos	Known				Cable Sleeve - in Wall - Chrysotile					
15323	ACTIVE	N	N095-00-3/151	UMC - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding					



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25867	ACTIVE	N	N095-00-3/151	UMC - Station Building - Euston Stn	Mastic	Asbestos	Presumed				Mastic to Ventilation Ducting					
15325	ACTIVE	N	N095-00-3/151	UMC - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				Various Asbestos Sheathed Cables		5			
15324	ACTIVE	N	N095-00-3/151	UMC - Station Building - Euston Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking - UMC Access					
45003	INACTIVE	N	N095-00-3/151	UMC - Station Building - Euston Stn		Asbestos	Strongly Presumed				5no Cables		5		N	N
9845	ACTIVE	N	N095-00-3/152	UMC - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18232	ACTIVE	N	N095-00-3/152	UMC - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				Various Cables (7no)		7			
25868	ACTIVE	N	N095-00-3/152	UMC - Station Building - Euston Stn	Mastic	Asbestos	Presumed				Mastic to Joints in Ventilation Ducting					
15326	ACTIVE	N	N095-00-3/152	UMC - Station Building - Euston Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking					
25869	ACTIVE	N	N095-00-3/152	UMC - Station Building - Euston Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box					
9846	ACTIVE	N	N095-00-3/161	LMC - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15327	ACTIVE	N	N095-00-3/161	LMC - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Escalator incline surveyed. Suspect material was a board, tested and found to be Supalux					
15329	ACTIVE	N	N095-00-3/161	LMC - Station Building - Euston Stn	Other Electrical Boxes	Asbestos	Presumed				Insulation within Small Electrical Box		1			
15328	ACTIVE	N	N095-00-3/161	LMC - Station Building - Euston Stn	Caulking	Asbestos	Known				Tunnel Ring Caulking. Access Areas Encapsulated					
18093	ACTIVE	N	N095-00-3/161	LMC - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				50mm Cables		2			
9847	ACTIVE	N	N095-00-3/162	LMC - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15330	ACTIVE	N	N095-00-3/162	LMC - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding					
44361	ACTIVE	N	N095-00-3/162	LMC - Station Building - Euston Stn	Gasket :Pipework	Asbestos	Not Found during Inspection				Gaskets to pipework on pipework to pump equipment Pipework and gaskets not present in 2020 re-inspection. Possibly removed.		5			



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18233	ACTIVE	N	N095-00-3/162	LMC - Station Building - Euston Stn	Caulking	Asbestos	Known				Tunnel Ring Caulking					
15331	ACTIVE	N	N095-00-3/162	LMC - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				Various Cables - SP		7			
9848	ACTIVE	N	N095-00-3/201	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15332	ACTIVE	N	N095-00-3/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal False Ceiling No access above fixed metal false ceiling during 2020 re-inspection.					
9849	ACTIVE	N	N095-00-3/202	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15333	ACTIVE	N	N095-00-3/202/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal False Ceiling No access above fixed metal false ceiling during 2020 re-inspection.					
9850	ACTIVE	N	N095-00-3/203	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18094	ACTIVE	N	N095-00-3/203/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal False Ceiling No access above fixed metal false ceiling during 2020 re-inspection.					
9851	ACTIVE	N	N095-00-3/204	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15334	ACTIVE	N	N095-00-3/204/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal False Ceiling No access above fixed metal false ceiling during 2020 re-inspection.					
15335	ACTIVE	N	N095-00-3/204/FLR-01	Floor - 1 - Passage - Station Building - Euston Stn	Cable Duct: Other	Asbestos	Known				Cable Ducts - Chrysotile No access into floor ducts during 2020 re-inspection.		12			
9852	ACTIVE	N	N095-00-3/205	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15336	ACTIVE	N	N095-00-3/205/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal Tiles No access above fixed metal false ceiling during 2020 re-inspection.					
9853	ACTIVE	N	N095-00-3/206	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15337	ACTIVE	N	N095-00-3/206/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal Tiles No access above fixed metal false ceiling during 2020 re-inspection.					



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9854	ACTIVE	N	N095-00-3/207	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18095	ACTIVE	N	N095-00-3/207/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal Tiles No access above fixed metal false ceiling during 2020 re-inspection.					
9855	ACTIVE	N	N095-00-3/208	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15338	ACTIVE	N	N095-00-3/208/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal Tiles No access above fixed metal false ceiling during 2020 re-inspection.					
9856	ACTIVE	N	N095-00-3/236	Lobby - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18477	ACTIVE	N	N095-00-3/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles				YES	
15339	ACTIVE	N	N095-00-3/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Euston Stn	Void	Asbestos	Surveyed – Not Detected				No Asbestos Visible				YES	
9857	ACTIVE	N	N095-00-3/281	Office - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed				Room is now part of 3/236 along with 3/341;					
15340	ACTIVE	N	N095-00-3/281/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
18583	ACTIVE	N	N095-00-3/281/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Euston Stn	Cellactite Sheeting	Asbestos	Known				Corrugated Sheet - Chrysotile above False Ceiling No access above false ceiling during 2020 re-inspection.				YES	
9858	ACTIVE	N	N095-00-3/341	Mess Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15341	ACTIVE	N	N095-00-3/341	Mess Room - Station Building - Euston Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
18096	ACTIVE	N	N095-00-3/341/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Euston Stn	Cellactite Sheeting	Asbestos	Known				Corrugated Sheet - Chrysotile above False Ceiling No access above false ceiling during 2020 re-inspection.				YES	
9859	ACTIVE	N	N095-00-3/406	Locker Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19296	ACTIVE	N	N095-00-3/406/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15342	ACTIVE	N	N095-00-3/406/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Euston Stn	Cellactite Sheeting	Asbestos	Known				Corrugated Sheet - Chrysotile above Supalux Tiles No access above fixed supalux tiles during 2020 re-inspection.				YES	
9860	ACTIVE	N	N095-00-3/407	Bin Store - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15343	ACTIVE	N	N095-00-3/407/CLG-01	Ceiling: Solid - 1 - Bin Store - Station Building - Euston Stn	Cellactite Sheeting	Asbestos	Known				Cellactite Corrugated Sheet - Chrysotile					
9861	ACTIVE	N	N095-00-3/601	Stairs: Linear - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15344	ACTIVE	N	N095-00-3/601/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal False Ceiling No access above fixed metal false ceiling during 2020 re-inspection.					
9862	ACTIVE	N	N095-00-3/602	Stairs: Linear - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15345	ACTIVE	N	N095-00-3/602/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal False Ceiling No access above fixed metal false ceiling during 2020 re-inspection.					
9863	ACTIVE	N	N095-00-3/603	Stairs: Linear - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18097	ACTIVE	N	N095-00-3/603/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal False Ceiling No access above fixed false ceiling during 2020 re-inspection.					
9864	ACTIVE	N	N095-00-3/631	Stairs: Spiral - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18630	ACTIVE	N	N095-00-3/631	Stairs: Spiral - Station Building - Euston Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
18234	ACTIVE	N	N095-00-3/791	LMC Access - Station Building - Euston Stn	Caulking	Asbestos	Known				Tunnel Ring - Caulkng - Amphipole Encapsualted 04/09/2007					
15346	INACTIVE	N	N095-00-3/791/CLG-01	Ceiling: Solid - 1 - LMC Access - Station Building - Euston Stn	Caulking	Asbestos	Known				Tunnel Ring - Caulkng - Amphipole Encapsualted 04/09/2007					
15347	ACTIVE	N	N095-00-3/792	LMC Access - Station Building - Euston Stn	Caulking	Asbestos	Known				Tunnel Ring - Caulkng - Amphipole Encapsualted 04/09/2007					
15348	INACTIVE	N	N095-00-3/792/CLG-01	Ceiling: Solid - 1 - LMC Access - Station Building - Euston Stn	Caulking	Asbestos	Known				Tunnel Ring - Caulkng - Amphipole Encapsualted 04/09/2007					
15349	ACTIVE	N	N095-00-3/793	UMC Access - Station Building - Euston Stn	Caulking	Asbestos	Known				Tunnel Ring - Caulkng - Amphipole Encapsualted 04/09/2007					



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15350	INACTIVE	N	N095-00-3/793/CLG-01	Ceiling: Solid - 1 - UMC Access - Station Building - Euston Stn	Caulking	Asbestos	Known				Tunnel Ring - Caulking - Amphipole Encapsulated 04/09/2007					
15351	ACTIVE	N	N095-00-3/794	UMC Access - Station Building - Euston Stn	Caulking	Asbestos	Known				Tunnel Ring - Caulking - Chrysotile Encapsulated 04/09/2007					
15352	INACTIVE	N	N095-00-3/794/CLG-01	Ceiling: Solid - 1 - UMC Access - Station Building - Euston Stn	Caulking	Asbestos	Known				Tunnel Ring - Caulking - Chrysotile Encapsulated 04/09/2007					
9865	ACTIVE	N	N095-00-4/201	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18098	ACTIVE	N	N095-00-4/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling No access above fixed false ceiling during 2020 re-inspection.					
9866	ACTIVE	N	N095-00-4/202	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15353	ACTIVE	N	N095-00-4/202/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling No access above fixed false ceiling during 2020 re-inspection.					
9867	ACTIVE	N	N095-00-4/203	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15354	ACTIVE	N	N095-00-4/203/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling No access above fixed metal false ceiling during 020 re-inspection.					
9868	ACTIVE	N	N095-00-4/236	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15355	ACTIVE	N	N095-00-4/236	Passage - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				2no x 20mm Cables		2			
9869	ACTIVE	N	N095-00-4/261	Platform 1 - Northbound Local - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15356	ACTIVE	N	N095-00-4/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Euston Stn	Void	Asbestos	Surveyed - Not Detected				Above False Ceiling - No presumed asbestos					
18099	ACTIVE	N	N095-00-4/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Euston Stn	Cable Ducts: Cement	Asbestos	Known				Platform 1 Invert Various Cable Sleeves - Chrysotile					YES
15357	ACTIVE	N	N095-00-4/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Euston Stn	Cable: Sheath	Asbestos	Known				Platform 1 Invert 3 no. Cables		3			YES



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15358	ACTIVE	N	N095-00-4/261/ FLR-01	Floor - 1 - Platform 1 - Station Building - Euston Stn	Cable: Wrap	Asbestos	Known				Platform 1 Invert Chrysotile Asbestos Material Wrap. Previously Encapsulated. Strongly presumed  No access into platform inverts during 2020 re-inspection. Confined space.					YES
9870	ACTIVE	N	N095-00-4/262	Platform 2 - Southbound Local - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18631	INACTIVE	N	N095-00-4/262	Platform 2 - Southbound Local - Station Building - Euston Stn	Cable: Sheath	Asbestos	No Access: Presumed				25mm Cable near Stairs 3/603; Various Cables going to the Tunnel		1			
15360	ACTIVE	N	N095-00-4/262	Platform 2 - Southbound Local - Station Building - Euston Stn	Cable: Sheath	Asbestos	Known				Various Cables going to the Tunnel					
45004	ACTIVE	N	N095-00-4/262	Platform 2 - Southbound Local - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - 2 No braided cable		2			Y
15359	ACTIVE	N	N095-00-4/262/ CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - Euston Stn	Void	Asbestos	Surveyed – Not Detected				Above Concrete, Metal False Ceiling					
15362	ACTIVE	N	N095-00-4/262/ FLR-01	Floor - 1 - Platform 2 - Station Building - Euston Stn	Cable Ducts: Cement	Asbestos	Known				Under 4/732 Ducts Cement - Asbestos identified.					YES
18647	ACTIVE	N	N095-00-4/262/ FLR-01	Floor - 1 - Platform 2 - Station Building - Euston Stn	Cable Ducts: Bitumen	Asbestos	Strongly Presumed				Platform 2 Invert 2 x Bitumen Ducts H/L under 4/668		2			YES
15363	ACTIVE	N	N095-00-4/262/ FLR-01	Floor - 1 - Platform 2 - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - under 3/603 Braided Cables		3			YES
15361	ACTIVE	N	N095-00-4/262/ FLR-01	Floor - 1 - Platform 2 - Station Building - Euston Stn	Cable: Sheath	Asbestos	Known				Platform 2 Invert Various Cables					YES
18100	ACTIVE	N	N095-00-4/262/ FLR-01	Floor - 1 - Platform 2 - Station Building - Euston Stn	Cable Ducts: Cement	Asbestos	Known				Platform 2 Invert 1x Cement Duct under 4/732 - Chrysotile		1			YES
9871	ACTIVE	N	N095-00-4/381	Switch Cupboard - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18235	ACTIVE	N	N095-00-4/381/ CLG-01	Ceiling: Solid - 1 - Switch Cupboard - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
15364	ACTIVE	N	N095-00-4/381/ CLG-01	Ceiling: Solid - 1 - Switch Cupboard - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Supalux  No access above fixed supalux tiles during 2020 re-inspection.					
9872	ACTIVE	N	N095-00-4/661	Switch Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15365	ACTIVE	N	N095-00-4/661	Switch Room - Station Building - Euston Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes - Insulation within 3x60 amp, 1x 30amp & 100amp		5			



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9873	ACTIVE	N	N095-00-4/668	Switch Cupboard - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15366	ACTIVE	N	N095-00-4/668	Switch Cupboard - Station Building - Euston Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9874	ACTIVE	N	N095-00-4/711	Lobby - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18101	ACTIVE	N	N095-00-4/711	Lobby - Station Building - Euston Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9875	ACTIVE	N	N095-00-4/712	Relay Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18632	INACTIVE	N	N095-00-4/712	Relay Room - Station Building - Euston Stn	Cable: Sheath	Asbestos	Removed				2x Green 50mm Cables to wall 3 - removed as part of TCP project Oct 2022		2			
46821	ACTIVE	N	N095-00-4/712	Relay Room - Station Building - Euston Stn	Bitumen	Asbestos	Known				Bitumen Glue to Marley Tiles on walls					
19297	ACTIVE	N	N095-00-4/712	Relay Room - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				20mm Cables		1		N	N
46820	ACTIVE	N	N095-00-4/712	Relay Room - Station Building - Euston Stn	Vinyl tiles	Asbestos	Known				Marley tiles - (R713576) throughout the room to walls mostly removed on wall 3 . Still remaining on wall 1,2 and ceiling.					
15367	INACTIVE	N	N095-00-4/712	Relay Room - Station Building - Euston Stn	PCBs	Polychlorinated biphenyl	Removed				PCB's - Fair Condition Serial Nos 39519; 19287; 197505; 39232; 40824; 43947 23/02/2017 Inspection still Fair Condition		6			
46822	INACTIVE	N	N095-00-4/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Euston Stn	Other Boarding	Asbestos	Removed				Paxoline board to within equipment rack to wall 3. - removed as part of TCP project - Oct 2022					
46824	INACTIVE	N	N095-00-4/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Euston Stn	Other Boarding	Asbestos	Removed				Brown paxoline board to wall 3 base of transformer - removed as part of TCP project - Oct 2022					
46823	INACTIVE	N	N095-00-4/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Euston Stn	Other Boarding	Asbestos	Removed				Paxoline board to wall plug - black - wall 3 low level - - removed as part of TCP project - Oct 2022					
46825	INACTIVE	N	N095-00-4/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Euston Stn	Other Boarding	Asbestos	Removed				Brown paxoline board wall 3 to front side of frame - removed as part of TCP project - Oct 2022					
9876	ACTIVE	N	N095-00-4/713	Relay Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15370	ACTIVE	N	N095-00-4/713	Relay Room - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				2no x 50mm Cables		2			
44366	ACTIVE	N	N095-00-4/713 80143139	Relay Room - Station Building - Euston Stn Room Assets	Cable: Sheath	Asbestos	Presumed				2no yellow cables within roller shutters					



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44365	ACTIVE	N	N095-00-4/713 80143139	Relay Room - Station Building - Euston Stn Room Assets	Other Boarding	Asbestos	Presumed				Paxoline panelling throughout room					
15371	ACTIVE	N	N095-00-4/713	Relay Room - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				20mm Cables		1			
15369	INACTIVE	N	N095-00-4/713	Relay Room - Station Building - Euston Stn	PCBs	Polychlorinated biphenyl	Removed				8 x PCB's - Fair Condition - located in roller shutter cabinet 23/02/2017 inspection signs of leaking		8		N	N
15368	ACTIVE	N	N095-00-4/713/ CLG-01	Ceiling: Suspended - 1 - Relay Room - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Ceiling					
18102	ACTIVE	N	N095-00-4/713/ CLG-01	Ceiling: Suspended - 1 - Relay Room - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Supalux Boarding No access above fixed supalux panels during 2020 re-inspection.					
9877	ACTIVE	N	N095-00-4/731	CER - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
9878	ACTIVE	N	N095-00-4/732	CER - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
9879	ACTIVE	N	N095-00-4/771	Pump Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15372	ACTIVE	N	N095-00-4/771	Pump Room - Station Building - Euston Stn	Gasket :Pipework	Asbestos	Presumed				Gaskets to Flanged Bolted Joints to Pump Equipment					
18633	ACTIVE	N	N095-00-4/771	Pump Room - Station Building - Euston Stn	Isolator Switches	Asbestos	Strongly Presumed				60amp Switch Box - Insulation within		1			
9880	ACTIVE	N	N095-00-4/781	Fan Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17933	ACTIVE	N	N095-00-4/781	Fan Room - Station Building - Euston Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No access					
9881	ACTIVE	N	N095-00-4/786	Service Riser - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15183	ACTIVE	N	N095-00-4/786	Service Riser - Station Building - Euston Stn	Caulking	Asbestos	Surveyed - Not Detected				Tunnel Ring - Caulking					
17934	ACTIVE	N	N095-00-4/786/ CLG-01	Ceiling: Solid - 1 - Service Shaft - Station Building - Euston Stn	Caulking	Asbestos	No Access: Presumed				Rendered Tunnel Rings - No access to Sample Caulking Tunnel rings not visible behind render during 2020 re-inspection.					
15184	ACTIVE	N	N095-00-4/786/ CLG-01	Ceiling: Solid - 1 - Service Shaft - Station Building - Euston Stn	Caulking	Asbestos	Surveyed - Not Detected				Tunnel Ring - Caulking					



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15185	ACTIVE	N	N095-00-4/791	Vent Shaft - Station Building - Euston Stn	Caulking	Asbestos	No Access: Presumed				Rendered Tunnel Rings - No access to Sample Caulking Tunnel rings not visible behind render during 2020 re-inspection.					
15186	ACTIVE	N	N095-00-4/792	Vent Shaft - Station Building - Euston Stn	Caulking	Asbestos	No Access: Presumed				Rendered Tunnel Rings - No access to Sample Caulking Tunnel rings not visible behind render during 2020 re-inspection.					
15187	ACTIVE	N	N095-00-4/792/CLG-01	Ceiling: Solid - 1 - Vent Shaft - Station Building - Euston Stn	No Access	Asbestos	No Access: Presumed				Ceiling and above not surveyed - too high High level not accessed during 2020 re-inspection.					
9882	ACTIVE	N	N095-00-4/971	Disused Room Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15188	ACTIVE	N	N095-00-4/971	Disused Room Room - Station Building - Euston Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
45005	ACTIVE	N	N095-00-4/972	Vent Shaft - Station Building - Euston Stn	Cable: Sheath	Asbestos	Known				1x Asbestos braided cable to cable run on wall				N	N
45007	ACTIVE	N	N095-00-4/972	Vent Shaft - Station Building - Euston Stn	Cable: Sheath	Asbestos	Known				Braided cable coming out of box				N	N
45006	ACTIVE	N	N095-00-4/972	Vent Shaft - Station Building - Euston Stn	Other Electrical Boxes	Asbestos	Presumed				Materials within ten core box presumed to contain asbestos insulating materials within				N	N
15189	ACTIVE	N	N095-00-4/972	Vent Shaft - Station Building - Euston Stn	Caulking	Asbestos	No Access: Presumed				Rendered Tunnel Rings - No access to Sample Caulking Tunnel rings not visible behind render during 2020 re-inspection.					
18472	INACTIVE	N	N095-00-4/972/CLG-01	Ceiling: Solid - 1 - Vent Shaft - Station Building - Euston Stn	Caulking	Asbestos	No Access: Presumed				Rendered Tunnel Rings - No access to Sample Caulking					
15190	ACTIVE	N	N095-00-4/973	Vent Shaft - Station Building - Euston Stn	Caulking	Asbestos	No Access: Presumed				Rendered Tunnel Rings - No access to Sample Caulking Tunnel rings not visible behind render during 2020 re-inspection.					
17935	INACTIVE	N	N095-00-4/973/CLG-01	Ceiling: Solid - 1 - Vent Shaft - Station Building - Euston Stn	Caulking	Asbestos	No Access: Presumed				Rendered Tunnel Rings - No access to Sample Caulking					
15191	ACTIVE	N	N095-00-4/974	Vent Shaft - Station Building - Euston Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
15192	ACTIVE	N	N095-00-4/975	Vent Shaft - Station Building - Euston Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
15193	ACTIVE	N	N095-00-4/976	Vent Shaft - Station Building - Euston Stn	Caulking	Asbestos	Surveyed - Not Detected				Tunnel Ring Caulking					
15194	ACTIVE	N	N095-00-4/976/CLG-01	Ceiling: Solid - 1 - Vent Shaft - Station Building - Euston Stn	Caulking	Asbestos	Surveyed - Not Detected				Tunnel Ring Caulking					



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
45010	ACTIVE	N	N095-00-4/981	Vent Shaft - Station Building - Euston Stn	Cable: Sheath	Asbestos	Known				Braided cable coming out of box		1		N	N
45008	ACTIVE	N	N095-00-4/981	Vent Shaft - Station Building - Euston Stn	Cable: Sheath	Asbestos	Known				1x Asbestos braided cable to cable run on wall		1		N	N
18577	ACTIVE	N	N095-00-4/981	Vent Shaft - Station Building - Euston Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Ring Caulking					
45009	ACTIVE	N	N095-00-4/981	Vent Shaft - Station Building - Euston Stn	Other Electrical Boxes	Asbestos	Presumed				Materials within ten core box presumed to contain asbestos insulating materials within				N	N
9883	ACTIVE	N	N095-00-4/982	Disused Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15195	ACTIVE	N	N095-00-4/982	Disused Room - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables to Vent Tunnel Slight damage identified during 2020 re-inspection.		3			
9884	ACTIVE	N	N095-00-4/986	Disused Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45011	ACTIVE	N	N095-00-4/986	Disused Room - Station Building - Euston Stn	Gasket :Pipework	Asbestos	Presumed				6x gaskets to flanges of metal pipework centre of shaft		6		N	N
15196	ACTIVE	N	N095-00-4/986/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Euston Stn	No Access	Asbestos	No Access: Presumed				Ceiling and above not surveyed - too high High level not accessed during 2020 re-inspection.					
9885	ACTIVE	N	N095-00-5/201	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18166	ACTIVE	N	N095-00-5/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Rings behind metal panels - Caulking No access above fixed metal false ceiling during 2020 re-inspection.					
9886	ACTIVE	N	N095-00-5/411	Disused Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17936	ACTIVE	N	N095-00-5/411	Disused Room - Station Building - Euston Stn	Caulking	Asbestos	Known				Tunnel Ring - Caulking - Amphibole					
15197	ACTIVE	N	N095-00-5/411	Disused Room - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel above door, Tunnel Rings, Bricks					
15198	ACTIVE	N	N095-00-5/411/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling No access above fixed metal ceiling during 2020 re-inspection.					
9887	ACTIVE	N	N095-00-5/601	Stairs: Linear - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18552	ACTIVE	N	N095-00-5/601/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Euston Stn	Caulking	Asbestos	Known				Caulking, throughout, to tunnel rings above false ceiling (between rings)			R674051		
45012	ACTIVE	N	N095-00-5/601/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Euston Stn	Caulking	Asbestos	Known				Caulking to metal tunnel ring flanges in false ceiling Item sampled again on 04/03/2020 - R674051 Caulking, throughout, to tunnel rings above false ceiling (between rings)				Y	N
9888	ACTIVE	N	N095-00-5/602	Stairs: Linear - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15200	ACTIVE	N	N095-00-5/602/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Board					
15199	ACTIVE	N	N095-00-5/602/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Euston Stn	Void	Asbestos	Surveyed - Not Detected				Above Metal Ceiling					
17937	ACTIVE	N	N095-00-5/602/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Euston Stn	Caulking	Asbestos	Known				Tunnel Ring - Caulking - Chrysotile No access above fixed metal false ceiling during 2020 re-inspection. Item sampled again on 04/03/2020 - R674051 Caulking, throughout, to tunnel rings above false ceiling (between rings)					
15201	ACTIVE	N	N095-00-5/791	Vent Shaft - Station Building - Euston Stn	Caulking	Asbestos	Known				Tunnel Rings to Walls LHS & RHS, Ceiling and below False Floor - Caulking - Chrysotile					
9889	ACTIVE	N	N095-00-6/081	Circulation Area - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15202	ACTIVE	N	N095-00-6/081/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling - Tunnel Ring Caulking Strongly Presumed to be present. No access above fixed metal false ceiling during 2020 re-inspection.					
9890	ACTIVE	N	N095-00-6/082	Circulation Area - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17938	ACTIVE	N	N095-00-6/082	Circulation Area - Station Building - Euston Stn	Caulking	Asbestos	Known				Caulking - Amphibole No access above fixed false ceiling during 2020 re-inspection.				Y	
15203	ACTIVE	N	N095-00-6/082/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling No access above fixed false ceiling during 2020 re-inspection.					
9891	ACTIVE	N	N095-00-6/121	Service Riser - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
45015	INACTIVE	N	N095-00-6/121	Service Riser - Station Building - Euston Stn	Cable Ducts: Cement	Asbestos	Known				10no Cable Sleeves		10		N	N
45014	INACTIVE	N	N095-00-6/121	Service Riser - Station Building - Euston Stn		Asbestos	Known				1no Asbestos Cable				N	N
15204	ACTIVE	N	N095-00-6/121	Service Riser - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				50mm Cables - SP		1			
15205	ACTIVE	N	N095-00-6/121/ WAL-001	Wall: Internal - 1 - Service Riser - Station Building - Euston Stn	Cable Ducts: Cement	Asbestos	Known				Cable Sleeves - Underneath 6/211 - Chrysotile No access into service riser during 2020 re-inspection. Confined space.					
9892	ACTIVE	N	N095-00-6/122	Service Riser - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15206	ACTIVE	N	N095-00-6/122	Service Riser - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables		8			
17939	ACTIVE	N	N095-00-6/122	Service Riser - Station Building - Euston Stn	Cable Ducts: Cement	Asbestos	Known				Cable Sleeves - Chrysotile No access into service riser during 2020 re-inspection. Confined space.					
45016	INACTIVE	N	N095-00-6/122	Service Riser - Station Building - Euston Stn		Asbestos	Known				Asbestos Cables (Below Passage)				N	N
45017	INACTIVE	N	N095-00-6/122	Service Riser - Station Building - Euston Stn	Cable Ducts: Cement	Asbestos	Known				10no Cable Sleeves (Below Passage)		10		N	N
9893	ACTIVE	N	N095-00-6/123	Service Riser - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15207	ACTIVE	N	N095-00-6/123	Service Riser - Station Building - Euston Stn	Cable Ducts: Cement	Asbestos	Known				Cable Sleeves under 6/203 - Chrysotile No access into service riser during 2020 re-inspection. Confined space.		10			
9894	ACTIVE	N	N095-00-6/124	Service Riser - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18553	ACTIVE	N	N095-00-6/124	Service Riser - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables		4			
18263	ACTIVE	N	N095-00-6/124	Service Riser - Station Building - Euston Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Cable Sleeves - Chrysotile		10			
9895	ACTIVE	N	N095-00-6/161	LMC - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15521	ACTIVE	N	N095-00-6/161	LMC - Station Building - Euston Stn	Cable Duct: Other	Asbestos	Strongly Presumed				2 x Cable Sleeves / Ducts		2			
15522	ACTIVE	N	N095-00-6/161	LMC - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				9 x Cables going into Invert		9			



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15519	ACTIVE	N	N095-00-6/161	LMC - Station Building - Euston Stn	Caulking	Asbestos	Known				Tunnel Ring - Caulking - Amphipole - Encapsulated					
15520	INACTIVE	N	N095-00-6/161/CLG-01	Ceiling: Solid - 1 - LMC - Station Building - Euston Stn	Caulking	Asbestos	Known				Tunnel Ring - Caulking - Amphipole - Encapsulated					
9896	ACTIVE	N	N095-00-6/162	LMC - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15525	ACTIVE	N	N095-00-6/162	LMC - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				4no Cables		4			
15524	ACTIVE	N	N095-00-6/162	LMC - Station Building - Euston Stn	Cable Ducts: Cement	Asbestos	Known				Cement cable duct within LMC 3&4					
18264	ACTIVE	N	N095-00-6/162	LMC - Station Building - Euston Stn	Caulking	Asbestos	Known				Encapsulated - Tunnel Ring - Caulking - Chrysotile					
15523	INACTIVE	N	N095-00-6/162/CLG-01	Ceiling: Solid - 1 - LMC - Station Building - Euston Stn	Caulking	Asbestos	Known				Encapsulated - Tunnel Ring - Caulking - Chrysotile					
9897	ACTIVE	N	N095-00-6/201	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15526	ACTIVE	N	N095-00-6/201	Passage - Station Building - Euston Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9898	ACTIVE	N	N095-00-6/202	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18656	ACTIVE	N	N095-00-6/202	Passage - Station Building - Euston Stn	Cable Ducts: Cement	Asbestos	Known				Various Cable Sleeves - Chrysotile No access into floor ducts during 2020 re-inspection. Lifting equipment required.					
18646	ACTIVE	N	N095-00-6/202	Passage - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables No access into floor ducts during 2020 re-inspection. Lifting equipment required.		2			
18265	ACTIVE	N	N095-00-6/202/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling No access above fixed metal false ceiling during 2020 re-inspection.					
9899	ACTIVE	N	N095-00-6/203	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15527	ACTIVE	N	N095-00-6/203/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling No access above fixed metal false ceiling during 2020 re-inspection.					
9900	ACTIVE	N	N095-00-6/204	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15529	ACTIVE	N	N095-00-6/204	Passage - Station Building - Euston Stn	Cable Ducts: Cement	Asbestos	Known				Various Cable Sleeves - Chrysotile No access into floor ducts during 2020 re-inspection.					
15528	ACTIVE	N	N095-00-6/204/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling No access above fixed metal false ceiling during 2020 re-inspection.					
9901	ACTIVE	N	N095-00-6/205	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18242	ACTIVE	N	N095-00-6/205/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling No access above fixed metal false ceiling during 2020 re-inspection.					
9902	ACTIVE	N	N095-00-6/206	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15531	ACTIVE	N	N095-00-6/206	Passage - Station Building - Euston Stn	Cable Ducts: Cement	Asbestos	Known				Cable Sleeves - Chrysotile No access into floor ducts during 2020 re-inspection. Lifting equipment required.		1			
15530	ACTIVE	N	N095-00-6/206/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling No access into fixed metal false ceiling during 2020 re-inspection.					
9903	ACTIVE	N	N095-00-6/207	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18708	ACTIVE	N	N095-00-6/207	Passage - Station Building - Euston Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking No access above fixed metal false ceiling during 2020 re-inspection.					
18266	ACTIVE	N	N095-00-6/207/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling No access above fixed metal false ceiling during 2020 re-inspection.					
9904	ACTIVE	N	N095-00-6/208	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15532	ACTIVE	N	N095-00-6/208/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling No access above fixed metal false ceiling during 2020 re-inspection.					
15533	INACTIVE	N	N095-00-6/208/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling					
9905	ACTIVE	N	N095-00-6/209	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
9906	ACTIVE	N	N095-00-6/210	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
45013	ACTIVE	N	N095-00-6/210/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Caulking	Asbestos	Known				Caulking to metal tunnel ring flanges in false ceiling				N	N
15534	ACTIVE	N	N095-00-6/210/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Caulking	Asbestos	Known				Caulking to metal tunnel rings above false ceiling - Known			R662226		
9907	ACTIVE	N	N095-00-6/211	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15535	ACTIVE	N	N095-00-6/211/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling No access above fixed metal false ceiling during 2020 re-inspection.					
9908	ACTIVE	N	N095-00-6/212	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15537	ACTIVE	N	N095-00-6/212/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling No access above fixed metal false ceiling during 2020 re-inspection.					
9909	ACTIVE	N	N095-00-6/213	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18268	ACTIVE	N	N095-00-6/213/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling No access above fixed metal false ceiling during 2020 re-inspection.					
9910	ACTIVE	N	N095-00-6/214	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15539	ACTIVE	N	N095-00-6/214/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling No access above fixed metal false ceiling during 2020 re-inspection.					
9911	ACTIVE	N	N095-00-6/215	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15540	ACTIVE	N	N095-00-6/215/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Fire Break above Metal Ceiling				YES	
9912	ACTIVE	N	N095-00-6/216	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15541	ACTIVE	N	N095-00-6/216/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Void	Asbestos	Surveyed – Not Detected				Concrete					
9913	ACTIVE	N	N095-00-6/217	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15542	ACTIVE	N	N095-00-6/217/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling No access above fixed metal false ceiling during 2020 re-inspection.					



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9914	ACTIVE	N	N095-00-6/237	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19428	ACTIVE	N	N095-00-6/237	Passage - Station Building - Euston Stn	Caulking	Asbestos	Known				Tunnel rings (not visible) possibly containing caulking material in flanges and joints are present behind corrugated metal sheeting forming structure of all platform tunnels at the station– Known Asbestos.  No access above false ceiling during 2020 re-inspection.					
15373	ACTIVE	N	N095-00-6/237/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Ceiling Tiles					
15374	INACTIVE	N	N095-00-6/237/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Euston Stn	Cellactite Sheeting	Asbestos	Known				Cellactite Corrugated Sheet - Chrysotile above False Ceiling				Y	N
18269	ACTIVE	N	N095-00-6/237/DOR-01	Door - 1 - Passage - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panel on door					
9915	ACTIVE	N	N095-00-6/238	Lobby - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18103	ACTIVE	N	N095-00-6/238	Lobby - Station Building - Euston Stn	No Access	Asbestos	Room: Surveyed – No Known Asbestos				Not Surveyed Management survey completed during 2020 re-inspection. No asbestos containing materials present.					
9916	ACTIVE	N	N095-00-6/239	Lobby - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15375	ACTIVE	N	N095-00-6/239	Lobby - Station Building - Euston Stn	No Access	Asbestos	Room: Surveyed – No Known Asbestos				Not Surveyed Management survey completed during 2020 re-inspection. No asbestos containing materials present.					
9917	ACTIVE	N	N095-00-6/263	Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18709	ACTIVE	N	N095-00-6/263	Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn	Cable Ducts: Cement	Asbestos	Known				Cable Sleeves - Chrysotile (Below Passage 6/212)		10			Y
15538	ACTIVE	N	N095-00-6/263	Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				Asbestos Cables (Below Passage 6/212)					Y
15376	ACTIVE	N	N095-00-6/263	Platform 3 - Northbound Fast - Northern Line - Station Building - Euston Stn	Void	Asbestos	Surveyed – Not Detected				Tiles; Metal behind cable running panels & Panel below Euston Sign					



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15377	ACTIVE	N	N095-00-6/263/CLG-01	Ceiling: Solid - 1 - Platform 3 - Station Building - Euston Stn	Caulking	Asbestos	Known				Localised Encapsulation - Asbestos Caulking behind panelling the length of platform - above Metal Ceiling				YES	
18104	ACTIVE	N	N095-00-6/263/FLR-01	Floor - 1 - Platform 3 - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 3 Invert - 2no Cables nr 6/717		2			YES
15378	ACTIVE	N	N095-00-6/263/FLR-01	Floor - 1 - Platform 3 - Station Building - Euston Stn	Cable: Sheath	Asbestos	Known				Platform 3 Invert - Various Cable Sleeves - Chrysotile					YES
9918	ACTIVE	N	N095-00-6/264	Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18267	ACTIVE	N	N095-00-6/264	Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cable within invert by 6/211		1			
15536	ACTIVE	N	N095-00-6/264	Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn	Cable Ducts: Cement	Asbestos	Known				Cable Sleeves - Chrysotile within invert by 6/211		10			
15380	ACTIVE	N	N095-00-6/264	Platform 4 - Northbound Local - Victoria Line - Station Building - Euston Stn	Cable Ducts: Cement	Asbestos	Presumed				Platform 4 tail wall trackside - Cable Ducts		2			
15379	ACTIVE	N	N095-00-6/264/CLG-01	Ceiling: Solid - 1 - Platform 4 - Station Building - Euston Stn	Caulking	Asbestos	Known				Above Metal Ceiling - Asbestos Caulking behind panelling the length of platform				YES	
15383	ACTIVE	N	N095-00-6/264/FLR-01	Floor - 1 - Platform 4 - Station Building - Euston Stn	Cable Duct: Other	Asbestos	Known				Various Cable Ducts within Invert		6			YES
18105	ACTIVE	N	N095-00-6/264/FLR-01	Floor - 1 - Platform 4 - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 4 Invert - Various Cables					YES
15382	ACTIVE	N	N095-00-6/264/FLR-01	Floor - 1 - Platform 4 - Station Building - Euston Stn	Caulking	Asbestos	Strongly Presumed				Platform 4 Invert - Tunnel Rings - Caulking by 6/715					YES
15381	ACTIVE	N	N095-00-6/264/FLR-01	Floor - 1 - Platform 4 - Station Building - Euston Stn	Cable Ducts: Cement	Asbestos	Known				Platform 4 Invert - Various Cable Sleeves - Chrysotile					YES
9919	ACTIVE	N	N095-00-6/265	Platform 5 - Northbound Local - Victoria Line - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15384	ACTIVE	N	N095-00-6/265/CLG-01	Ceiling: Solid - 1 - Platform 5 - Station Building - Euston Stn	Caulking	Asbestos	Known				Localised Encapsulation - Asbestos Caulking behind panelling the length of platform					
15387	ACTIVE	N	N095-00-6/265/FLR-01	Floor - 1 - Platform 5 - Station Building - Euston Stn	Cable Ducts: Cement	Asbestos	Known				Cement Cable Ducts at Middle of SB Platform within Wall to LMC in Invert - Chrysotile					YES
15386	ACTIVE	N	N095-00-6/265/FLR-01	Floor - 1 - Platform 5 - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 5 Invert - Various Cables					YES
15385	ACTIVE	N	N095-00-6/265/FLR-01	Floor - 1 - Platform 5 - Station Building - Euston Stn	Westing house Boxes	Asbestos	Surveyed - Not Detected				Platform 5 Invert		1			YES



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18634	ACTIVE	N	N095-00-6/265/FLR-01	Floor - 1 - Platform 5 - Station Building - Euston Stn	Cable Ducts: Cement	Asbestos	Known				Platform 5 Invert - Various Cable Sleeves - Chrysotile					YES
9920	ACTIVE	N	N095-00-6/266	Platform 6 - Southbound Fast - Northern Line - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18106	ACTIVE	N	N095-00-6/266/FLR-01	Floor - 1 - Platform 6 - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 6 Invert - Various Cables					YES
9921	ACTIVE	N	N095-00-6/381	Passage - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15389	ACTIVE	N	N095-00-6/381	Passage - Station Building - Euston Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
15388	ACTIVE	N	N095-00-6/381	Passage - Station Building - Euston Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9922	ACTIVE	N	N095-00-6/382	Store - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
9923	ACTIVE	N	N095-00-6/383	Store - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15391	ACTIVE	N	N095-00-6/383	Store - Station Building - Euston Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Boarding in storage - Non Asbestos					
15390	ACTIVE	N	N095-00-6/383	Store - Station Building - Euston Stn		Asbestos	Surveyed - Not Detected				Acoustic Panel below sink					
15393	ACTIVE	N	N095-00-6/383	Store - Station Building - Euston Stn	LUL Heaters	Asbestos	Surveyed - Not Detected				2 x Heaters - Chrysotile Insulation Boards - REMOVED					
18236	ACTIVE	N	N095-00-6/383/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
15392	ACTIVE	N	N095-00-6/383/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Euston Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Supalux Tiles				YES	
18648	ACTIVE	N	N095-00-6/383/DOR-01	Door - 1 - Store - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Panels on doors					
9924	ACTIVE	N	N095-00-6/384	Store - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18107	ACTIVE	N	N095-00-6/384	Store - Station Building - Euston Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9925	ACTIVE	N	N095-00-6/385	Store - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15473	ACTIVE	N	N095-00-6/385	Store - Station Building - Euston Stn	Caulking	Asbestos	Known				Tunnel rings (not visible) possibly containing caulking material in flanges and joints are present behind corrugated metal sheeting forming structure of all platform tunnels at the station- Known Asbestos.  No access above fixed supalux false ceiling during 2020 re-inspection.					
15394	ACTIVE	N	N095-00-6/385/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
15471	ACTIVE	N	N095-00-6/385/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Euston Stn	Cellactite Sheeting	Asbestos	Known				Above False Ceiling - Corrugated Sheet - Chrysotile  No access above fixed supalux false ceiling during 2020 re-inspection.				YES	
15472	ACTIVE	N	N095-00-6/385/CLG-02	Ceiling: Solid - 2 - Store - Station Building - Euston Stn	Cellactite Sheeting	Asbestos	Known				Above False Ceiling - Corrugated Sheet - Chrysotile  No access above fixed supalux false ceiling during 2020 re-inspection.				YES	
19893	ACTIVE	N	N095-00-6/385/CLG-02	Ceiling: Solid - 2 - Store - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
18252	INACTIVE	N	N095-00-6/385/WAL-001	Wall: Internal - 1 - Store - Station Building - Euston Stn	Vinyl tiles	Asbestos	Removed				Marley Tiles on All Walls					
9926	ACTIVE	N	N095-00-6/386	Store - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
9927	ACTIVE	N	N095-00-6/406	Store - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15474	ACTIVE	N	N095-00-6/406/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
15475	ACTIVE	N	N095-00-6/406/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Euston Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Supalux Tiles					
18228	ACTIVE	N	N095-00-6/406/CLG-02	Ceiling: Suspended - 2 - Store - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
15476	ACTIVE	N	N095-00-6/406/CLG-02	Ceiling: Suspended - 2 - Store - Station Building - Euston Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Supalux Tiles					
9928	ACTIVE	N	N095-00-6/411	Store - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15477	ACTIVE	N	N095-00-6/411	Store - Station Building - Euston Stn	Caulking	Asbestos	Surveyed - Not Detected				Tunnel Ring Caulking - Non Asbestos					
15478	ACTIVE	N	N095-00-6/411/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Euston Stn	Caulking	Asbestos	Surveyed - Not Detected				Tunnel Ring Caulking - Non Asbestos					



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9929	ACTIVE	N	N095-00-6/661	Switch Cupboard - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15481	ACTIVE	N	N095-00-6/661	Switch Cupboard - Station Building - Euston Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Electrical Boxes - Insulation within		2		N	N
18253	ACTIVE	N	N095-00-6/661	Switch Cupboard - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel above Door					
18254	ACTIVE	N	N095-00-6/661	Switch Cupboard - Station Building - Euston Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box by Door - Insulation within		1			
15480	ACTIVE	N	N095-00-6/661/CLG-01	Ceiling: Suspended - 1 - Switch Cupboard - Station Building - Euston Stn	Cellactite Sheeting	Asbestos	Known				Chrysotile Corrugated Sheet above Supalux Tiles No access above fixed supalux tiles during 2020 re-inspection.				YES	
15479	ACTIVE	N	N095-00-6/661/CLG-01	Ceiling: Suspended - 1 - Switch Cupboard - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
9930	ACTIVE	N	N095-00-6/663	Switch Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15482	ACTIVE	N	N095-00-6/663	Switch Room - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel above Door					
15483	ACTIVE	N	N095-00-6/663/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
15484	ACTIVE	N	N095-00-6/663/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Euston Stn	Cellactite Sheeting	Asbestos	Known				Chrysotile Corrugated Sheet above Supalux Tiles; No access to reinspect above screwed down ceiling; No access above fixed supalux tiles during 2020 re-inspection.					
18642	ACTIVE	N	N095-00-6/663/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Euston Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box by Door - Insulation within		1			
9931	ACTIVE	N	N095-00-6/664	Switch Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18255	ACTIVE	N	N095-00-6/664	Switch Room - Station Building - Euston Stn	Vinyl tiles	Asbestos	No Access: Presumed				Grey Vinyl Tiles on Walls - Tiles have been removed however there may be some remaining behind equipment to walls - P					
25817	ACTIVE	N	N095-00-6/664/FLR-01	Floor - 1 - Switch Room - Station Building - Euston Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Red & Grey Vinyl Tiles to Floor Sampled negative report R19047 23/01/2002					
19478	ACTIVE	N	N095-00-6/664/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Euston Stn	Other Boarding	Asbestos	Presumed				Transformer Box by Door - Insulation within		1			



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18654	ACTIVE	N	N095-00-6/664/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Euston Stn	Isolator Switches	Asbestos	Strongly Presumed				3 x 60amp Switch Boxes - Insulation within					
25818	ACTIVE	N	N095-00-6/664/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Euston Stn	Other Electrical Boxes	Asbestos	Presumed				Small Controller Box W2		1			
25819	ACTIVE	N	N095-00-6/664/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Euston Stn	Other Electrical Boxes	Asbestos	Presumed				Large Controller W3		1			
9932	ACTIVE	N	N095-00-6/665	SER - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15485	ACTIVE	N	N095-00-6/665	SER - Station Building - Euston Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
9933	ACTIVE	N	N095-00-6/666	Switch Cupboard - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15486	ACTIVE	N	N095-00-6/666	Switch Cupboard - Station Building - Euston Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - new construction					
9934	ACTIVE	N	N095-00-6/711	IMR - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15487	ACTIVE	N	N095-00-6/711	IMR - Station Building - Euston Stn	Vinyl tiles	Asbestos	Known				Grey Marley Tiles (150m <sup>2</sup> ) No access to IMR during 2020 re-inspection in traffic hours. Access is trackside off platform 6.				N	N
44367	ACTIVE	N	N095-00-6/711/WAL-004 80901379	Wall: Internal - 4 - IMR - Station Building - Euston Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Old switch box		1		N	N
9935	ACTIVE	N	N095-00-6/712	Relay Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18256	ACTIVE	N	N095-00-6/712	Relay Room - Station Building - Euston Stn	Other Boarding	Asbestos	Strongly Presumed				Paxoline Packing throughout Room				N	N
15488	ACTIVE	N	N095-00-6/712	Relay Room - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables going into Invert - Some have been Cut Back and all have been encapsulated		25		N	N
9936	ACTIVE	N	N095-00-6/713	Relay Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
25820	ACTIVE	N	N095-00-6/713	Relay Room - Station Building - Euston Stn	Other Boarding	Asbestos	Presumed				Paxoline Packing Material					
15489	ACTIVE	N	N095-00-6/713	Relay Room - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables going into Invert - Majority of cables have been removed remainder have been encapsulated;		25			
9937	ACTIVE	N	N095-00-6/714	Relay Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15490	ACTIVE	N	N095-00-6/714	Relay Room - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				Various Cables - Some cut as they enter room, other remain live - All Encapsulated (Room Redundant - 26/06/2014)  Moderate damage identified during 2020 re-inspection. Terminated cables have been encapsulated on edges.					
18643	ACTIVE	N	N095-00-6/714	Relay Room - Station Building - Euston Stn	Other Boarding	Asbestos	Strongly Presumed				Paxoline Packing throughout Room - Small amounts remain; (Room redundant - 26/06/2014)					
9938	ACTIVE	N	N095-00-6/715	Relay Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18257	ACTIVE	N	N095-00-6/715	Relay Room - Station Building - Euston Stn	Other Boarding	Asbestos	Strongly Presumed				Paxoline Packing throughout Room				N	N
15491	ACTIVE	N	N095-00-6/715	Relay Room - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				Various Cables  Moderate damage identified during 2020 re-inspection. Some cables terminated/cut with edges encapsulated.				N	N
9939	ACTIVE	N	N095-00-6/716	Relay Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18239	ACTIVE	N	N095-00-6/716	Relay Room - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				3no x 10mm Cables - 1no White & 2no Brown		3		N	N
15492	INACTIVE	N	N095-00-6/716	Relay Room - Station Building - Euston Stn	PCBs	Polychlorinated biphenyl	Removed				2 x PCB's - Fair Condition Serial Nos M14160; M14185 23/02/2017 inspection Fair Condition		2		N	
20334	ACTIVE	N	N095-00-6/716/FLR-01	Floor - 1 - Relay Room - Station Building - Euston Stn	Other Electrical Boxes	Asbestos	Presumed				Drum type train describer - On floor centre of room		1		N	N
44368	ACTIVE	N	N095-00-6/716/WAL-001 80901764	Wall: Internal - 1 - Relay Room - Station Building - Euston Stn	Other Electrical Boxes	Asbestos	Presumed				Westinghouse box		1		N	N
44369	ACTIVE	N	N095-00-6/716/WAL-001 80901764	Wall: Internal - 1 - Relay Room - Station Building - Euston Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer box		1		N	N
9940	ACTIVE	N	N095-00-6/717	Relay Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
53980	ACTIVE	N	N095-00-6/717	Relay Room - Station Building - Euston Stn	Other Boarding	Asbestos	Sampled - Not Detected				square brown paxoline board			R729651RevC		
15493	ACTIVE	N	N095-00-6/717	Relay Room - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				10mm Cables		3		N	N
15494	INACTIVE	N	N095-00-6/717	Relay Room - Station Building - Euston Stn	PCBs	Polychlorinated biphenyl	Removed				5 x PCB's - Fair Condition Serial Nos - none visible 23/02/2017 inspection Fair Condition		5			



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46826	INACTIVE	N	N095-00-6/717/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Euston Stn	Other Boarding	Asbestos	Removed				Paxoline board to rack at back of room					
46828	ACTIVE	N	N095-00-6/717/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Euston Stn	Other Boarding	Asbestos	Presumed				Paxoline Board to wall 3					
46827	ACTIVE	N	N095-00-6/717/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Euston Stn	Other Electrical Boxes	Asbestos	Presumed				switch box to wall 3 at low level					
9941	ACTIVE	N	N095-00-6/718	SER - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15495	ACTIVE	N	N095-00-6/718	SER - Station Building - Euston Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
9942	ACTIVE	N	N095-00-6/719	SER - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15496	ACTIVE	N	N095-00-6/719	SER - Station Building - Euston Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - new construction					
9943	ACTIVE	N	N095-00-6/731	CER - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18258	ACTIVE	N	N095-00-6/731	CER - Station Building - Euston Stn	Caulking	Asbestos	Known				Caulking to Tunnel Rings No access above false ceiling during 2020 re-inspection.				Y	
15497	ACTIVE	N	N095-00-6/731	CER - Station Building - Euston Stn	Other Boarding	Asbestos	Presumed				Paxoline Box & Board				N	N
15498	ACTIVE	N	N095-00-6/731	CER - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				10mm Cables		2		N	N
18240	ACTIVE	N	N095-00-6/731/FLR-01	Floor - 1 - CER - Station Building - Euston Stn	Vinyl tiles	Asbestos	Presumed				Green Vinyl Floor Tiles				N	N
9944	ACTIVE	N	N095-00-6/732	CER - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15501	ACTIVE	N	N095-00-6/732	CER - Station Building - Euston Stn	Caulking	Asbestos	Known				Tunnel rings (not visible) possibly containing caulking material in flanges and joints are present behind corrugated metal sheeting forming structure of all platform tunnels at the station– Known Asbestos. No access above fixed supalux tiles during 2020 re-inspection.				Y	N
15499	ACTIVE	N	N095-00-6/732/CLG-01	Ceiling: Suspended - 1 - CER - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19946	ACTIVE	N	N095-00-6/732/CLG-01	Ceiling: Suspended - 1 - CER - Station Building - Euston Stn	Cellactite Sheeting	Asbestos	Known				Cellactite Corrugated Sheet above Supalux Tiles No access above fixed supalux tiles during 2020 re-inspection.				Y	N
15500	ACTIVE	N	N095-00-6/732/WAL-002	Wall: Internal - 2 - CER - Station Building - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				Asbestos cables going into floor		6		N	N
9945	ACTIVE	N	N095-00-6/733	Switch Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15503	ACTIVE	N	N095-00-6/733	Switch Room - Station Building - Euston Stn	Isolator Switches	Asbestos	Not Found during Inspection				Fuse Switch		1			
15502	ACTIVE	N	N095-00-6/733	Switch Room - Station Building - Euston Stn	Cable: Sheath	Asbestos	Not Found during Inspection				Tunnel ring j hangers contain 2 x 30mm Asbestos cables		2			
18259	ACTIVE	N	N095-00-6/733/FLR-01	Floor - 1 - Switch Room - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Beneath - False Wooden floor No access beneath false raised floor during 2020 re-inspection.					
9946	ACTIVE	N	N095-00-6/734	CER - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15505	ACTIVE	N	N095-00-6/734	CER - Station Building - Euston Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes - Insulation within		2			
15504	ACTIVE	N	N095-00-6/734/FLR-01	Floor - 1 - CER - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Beneath - False Wooden floor No access beneath false raised floor during 2020 re-inspection.					
9947	ACTIVE	N	N095-00-6/735	Mess Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15508	ACTIVE	N	N095-00-6/735	Mess Room - Station Building - Euston Stn	Caulking	Asbestos	Known				Tunnel rings (not visible) possibly containing caulking material in flanges and joints are present behind corrugated metal sheeting forming structure of all platform tunnels at the station– Known Asbestos. No access above fixed supalux ceiling during 2020 re-inspection.				Y	N
18260	ACTIVE	N	N095-00-6/735/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles - Screwed down					
15507	ACTIVE	N	N095-00-6/735/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Euston Stn	Cellactite Sheeting	Asbestos	Known				Cellactite Corrugated Sheet above Supalux Tiles No access above fixed supalux ceiling during 2020 re-inspection.				Y	N
9948	ACTIVE	N	N095-00-6/736	CER - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15509	ACTIVE	N	N095-00-6/736/ FLR-01	Floor - 1 - CER - Station Building - Euston Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Tiles  No computer tiles are present to floor during 2020 re-inspection, only solid concrete floor.					YES
9949	ACTIVE	N	N095-00-6/737	CER - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18644	ACTIVE	N	N095-00-6/737	CER - Station Building - Euston Stn	No Access	Asbestos	Room: Surveyed – No Known Asbestos				Not Surveyed  Management survey carried out during 2020 re-inspection. No samples taken.					
9950	ACTIVE	N	N095-00-6/738	CER - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9951	ACTIVE	N	N095-00-6/761	Equipment Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19300	ACTIVE	N	N095-00-6/761	Equipment Room - Station Building - Euston Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl Tiles - Walls					
15511	ACTIVE	N	N095-00-6/761	Equipment Room - Station Building - Euston Stn	Caulking	Asbestos	Known				Caulking to Tunnel Rings  No access above fixed false ceiling during 2020 re-inspection.					
15510	ACTIVE	N	N095-00-6/761/ CLG-01	Ceiling: Suspended - 1 - Equipment Room - Station Building - Euston Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18261	ACTIVE	N	N095-00-6/761/ FLR-01	Floor - 1 - Equipment Room - Station Building - Euston Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl Tiles					
9952	ACTIVE	N	N095-00-6/762	Computer Equipment Cupboard - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9953	ACTIVE	N	N095-00-6/763	Computer Equipment Cupboard - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9954	ACTIVE	N	N095-00-6/764	Computer Equipment Cupboard - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9955	ACTIVE	N	N095-00-6/765	Computer Equipment Cupboard - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9956	ACTIVE	N	N095-00-6/766	Computer Equipment Cupboard - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9957	ACTIVE	N	N095-00-6/767	Computer Equipment Cupboard - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9958	ACTIVE	N	N095-00-6/768	Computer Equipment Cupboard - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9959	ACTIVE	N	N095-00-6/769	Computer Equipment Cupboard - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15513	ACTIVE	N	N095-00-6/792	Vent Shaft - Station Building - Euston Stn	Caulking	Asbestos	Known				Encapsulated - Walls -Tunnel Ring - Caulking - Chrysotile					
15512	INACTIVE	N	N095-00-6/792/CLG-01	Ceiling: Solid - 1 - Vent Shaft - Station Building - Euston Stn	Caulking	Asbestos	Known				Encapsulated - Tunnel Ring - Caulking - Chrysotile					
15514	ACTIVE	N	N095-00-6/793	Vent Shaft - Station Building - Euston Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
18262	ACTIVE	N	N095-00-6/794	Vent Shaft - Station Building - Euston Stn	Caulking	Asbestos	Known				Encapsulated - Tunnel Ring - Caulking - Amphipole					
18655	INACTIVE	N	N095-00-6/794/CLG-01	Ceiling: Solid - 1 - Vent Shaft - Station Building - Euston Stn	Caulking	Asbestos	Known				Encapsulated - Tunnel Ring - Caulking - Amphipole					
18645	ACTIVE	N	N095-00-6/795	Vent Shaft - Station Building - Euston Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
15515	ACTIVE	N	N095-00-6/796	Vent Shaft - Station Building - Euston Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed No access during 2020 re-inspection. Access is down track.					
15517	ACTIVE	N	N095-00-6/797	Vent Shaft - Station Building - Euston Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Ring Caulking - Non Asbestos					
18241	ACTIVE	N	N095-00-6/798/CLG-01	Ceiling: Solid - 1 - Vent Shaft - Station Building - Euston Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Too High No access to high level ceiling during 2020 re-inspection.					
15518	ACTIVE	N	N095-00-6/799	Vent Shaft - Station Building - Euston Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
18649	ACTIVE	N	N095-00-6/800	Vent Shaft - Station Building - Euston Stn	Caulking	Asbestos	Known				Wall - Tunnel Ring - Caulking - Chrysotile Slight damage identified during 2020 re-inspection.					
18171	INACTIVE	N	N095-00-6/800/CLG-01	Ceiling: Solid - 1 - Vent Shaft - Station Building - Euston Stn	Caulking	Asbestos	Known				Tunnel Ring - Caulking - Chrysotile					
9960	ACTIVE	N	N095-00-6/951	Kitchen - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18237	ACTIVE	N	N095-00-6/951	Kitchen - Station Building - Euston Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Ring - Caulking					
15396	ACTIVE	N	N095-00-6/951	Kitchen - Station Building - Euston Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					



# Hazardous Material Asset Register - Summary



## N095-00 - Station Building - Euston Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9961	ACTIVE	N	N095-00-6/952	Mess Room - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15397	ACTIVE	N	N095-00-6/952	Mess Room - Station Building - Euston Stn	Caulking	Asbestos	Known				Tunnel Ring - Caulking No access above fixed false ceiling during 2020 re-inspection.					
15395	ACTIVE	N	N095-00-6/981	Vent Shaft - Station Building - Euston Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9962	ACTIVE	N	N095-00-B/901	Vent Shaft - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9963	ACTIVE	N	N095-00-B/902	Vent Shaft - Station Building - Euston Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46686	ACTIVE	N	N095/00/CS278	Shaft: Cable - SH/CS278 - NOR Line - Euston Stn	Caulking	Asbestos	Known				CS278B - 22Kv Cable Shaft Encapsulated Tunnel rings throughout shaft and tunnels at bottom of shaft			R705151		
46688	ACTIVE	N	N095/00/CS278	Shaft: Cable - SH/CS278 - NOR Line - Euston Stn	Cable Ducts: Bitumen	Asbestos	Known				CS278B - 22kv Cable Shaft Bitumen Ducts (18no) within chamber area beneath durasteel doors		18	R705151		
46687	ACTIVE	N	N095/00/CS278	Shaft: Cable - SH/CS278 - NOR Line - Euston Stn	Cable: Sheath	Asbestos	Strongly Presumed				CS278B - 22Kv Cable Shaft Various Braided (+8) Asbestos Sheathed Cables in vertical cable Run down shaft		8	R705151		
46693	ACTIVE	N	N095/00/CS278	Shaft: Cable - SH/CS278 - NOR Line - Euston Stn	No Access	Asbestos	Presumed				CS278B - 22Kv Cable Shaft Note on Access Tunnel area at bottom of shaft accessed as far as reasonably practicable. Access eventually blocked by narrow cable runs and vicinity to live track.			R705151		
46690	ACTIVE	N	N095/00/CS278	Shaft: Cable - SH/CS278 - NOR Line - Euston Stn	Cable Ducts: Cement	Asbestos	Known				CS278B - 22Kv Cable Shaft 2no Cement Ducts to Bottom of Shaft		2	R705151		
46692	ACTIVE	N	N095/00/CS278	Shaft: Cable - SH/CS278 - NOR Line - Euston Stn	Other Boarding	Asbestos	Sampled – Not Detected				CS278B - 22Kv Cable Shaft Insulating Blocks to floor where cables penetrate into shaft (2x 2m <sup>2</sup> ) - Top of Shaft		2	R705151		
46691	ACTIVE	N	N095/00/CS278	Shaft: Cable - SH/CS278 - NOR Line - Euston Stn	Durasteel	Asbestos	Sampled – Not Detected				CS278B - 22Kv Cable Shaft Durasteel to 3m <sup>2</sup> to Floor and Doors (2x 1m <sup>2</sup> ) to shaft entrances to floor - top of shaft			R705151		
46689	ACTIVE	N	N095/00/CS278	Shaft: Cable - SH/CS278 - NOR Line - Euston Stn	Isolator Switches	Asbestos	Strongly Presumed				CS278B - 22Kv Cable Shaft Asbestos components within Switch Box - Bottom of Shaft		1	R705151		



# Hazardous Material Asset Register - Summary



## N103-00 - Station Building - Goodge Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9966	ACTIVE	N	N103-00-1/001	Booking Hall - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19444	ACTIVE	N	N103-00-1/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Goodge Street Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				YES	
19425	ACTIVE	N	N103-00-1/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Goodge Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
9967	ACTIVE	N	N103-00-1/011	Ticket Office - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20115	ACTIVE	N	N103-00-1/011/CLG-01	Ceiling: Solid - 1 - Ticket Office - Station Building - Goodge Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
19319	ACTIVE	N	N103-00-1/011/CLG-01	Ceiling: Solid - 1 - Ticket Office - Station Building - Goodge Street Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				YES	
20116	ACTIVE	N	N103-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Goodge Street Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
9968	ACTIVE	N	N103-00-1/021	POM - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19228	ACTIVE	N	N103-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Goodge Street Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
9969	ACTIVE	N	N103-00-1/071	Circulation Area - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20117	ACTIVE	N	N103-00-1/071	Circulation Area - Station Building - Goodge Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels by Lift					
44155	ACTIVE	N	N103-00-1/136	Lift Shaft - Station Building - Goodge Street Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel panel, 3m2, behind lift control panel sandwiched between tiles and metal frame in Lift 1&2 1/136 at Goodge Street Station			R607276	N	N
20118	ACTIVE	N	N103-00-1/136	Lift Shaft - Station Building - Goodge Street Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
43112	ACTIVE	N	N103-00-1/136	Lift Shaft - Station Building - Goodge Street Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel panel No. 1, 1.5m <sup>2</sup> , to middle of access door – low level, Lift Shaft 3&4,			R511077	N	N
43110	ACTIVE	N	N103-00-1/136	Lift Shaft - Station Building - Goodge Street Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel panel No. 1, 1.5m <sup>2</sup> , to middle of access door – street level, Lift Shaft 3&4,			R511077	N	N
42448	ACTIVE	N	N103-00-1/136	Lift Shaft - Station Building - Goodge Street Stn	Durasteel	Asbestos	Sampled – Not Detected				Lift Shaft 3&4 - 8m <sup>2</sup> Durasteel panels behind control panel and above doors to top and bottom of lift shaft	8		R504226	N	N



# Hazardous Material Asset Register - Summary



## N103-00 - Station Building - Goodge Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42449	ACTIVE	N	N103-00-1/136	Lift Shaft - Station Building - Goodge Street Stn	Cable: Sheath	Asbestos	Sampled – Not Detected				Lift Shaft 3&4 - 2 x 4 no. braided cables (tracking) between lift cars 3 and 4		8	R504226	N	N
43111	ACTIVE	N	N103-00-1/136	Lift Shaft - Station Building - Goodge Street Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel panel No. 2, 1.5m <sup>2</sup> , to middle of access door – street level, Lift Shaft 3&4,			R511077	N	N
42451	ACTIVE	N	N103-00-1/137	Lift Shaft - Station Building - Goodge Street Stn	Cable: Sheath	Asbestos	Sampled – Not Detected				Lift Shaft 1&2 - 2 x 4no. braided cables (tracking) between lift cars 1 and 2 - NAD as per report R504226.		8	R504226	N	N
20119	ACTIVE	N	N103-00-1/137	Lift Shaft - Station Building - Goodge Street Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
43105	ACTIVE	N	N103-00-1/137	Lift Shaft - Station Building - Goodge Street Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel panel No. 1, 1.5m <sup>2</sup> , to middle of access door – street level, Lift Shaft 1&2,			R511077	N	N
43107	ACTIVE	N	N103-00-1/137	Lift Shaft - Station Building - Goodge Street Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel partel No. 1, 1.5m <sup>2</sup> , to middle access panel, access door – low level, Lift Shaft 1&2,			R511077	N	N
43109	ACTIVE	N	N103-00-1/137	Lift Shaft - Station Building - Goodge Street Stn	Caulking	Asbestos	Sampled – Not Detected				Caulking, throughout, Lift Shaft 1&2,			R511077	N	N
43106	ACTIVE	N	N103-00-1/137	Lift Shaft - Station Building - Goodge Street Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel partel No. 2, 1.5m <sup>2</sup> , to middle of access door – street level, Lift Shaft 1&2,			R511077	N	N
43108	ACTIVE	N	N103-00-1/137	Lift Shaft - Station Building - Goodge Street Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel panel No. 2, 1.5m <sup>2</sup> , surrounded of exit door, Lift Shaft 1&2			R511077	N	N
42450	ACTIVE	N	N103-00-1/137	Lift Shaft - Station Building - Goodge Street Stn	Durasteel	Asbestos	Sampled – Not Detected				Lift Shaft 1&2 - 8m <sup>2</sup> Durasteel panels behind control panel and above doors to top and bottom of lift shaft - NAD as per report R504226.	8		R504226	N	N
9970	ACTIVE	N	N103-00-1/201	Passage - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20120	ACTIVE	N	N103-00-1/201	Passage - Station Building - Goodge Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Access Hatches					
9971	ACTIVE	N	N103-00-1/236	Lobby - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20122	ACTIVE	N	N103-00-1/236/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Goodge Street Stn	Void	Asbestos	Surveyed – Not Detected				Fibreglass Lagging to Pipes above Supalux Tiles				YES	
20121	ACTIVE	N	N103-00-1/236/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Goodge Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
19229	ACTIVE	N	N103-00-1/236/FLR-01	Floor - 1 - Lobby - Station Building - Goodge Street Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
9972	ACTIVE	N	N103-00-1/237	Passage - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N103-00 - Station Building - Goodge Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20123	ACTIVE	N	N103-00-1/237	Passage - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9973	ACTIVE	N	N103-00-1/401	Bin Store - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20124	ACTIVE	N	N103-00-1/401	Bin Store - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9974	ACTIVE	N	N103-00-1/416	Toilet: Unisex - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20170	ACTIVE	N	N103-00-1/416	Toilet: Unisex - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9975	ACTIVE	N	N103-00-1/451	CER - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Ne Access 08 Oct 2014					
20171	ACTIVE	N	N103-00-1/451	CER - Station Building - Goodge Street Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access - Tenancy 08 Oct 2014					
9976	ACTIVE	N	N103-00-1/452	Tenancy - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19283	ACTIVE	N	N103-00-1/452	Tenancy - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9977	ACTIVE	N	N103-00-1/631	Stairs: Spiral - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19741	ACTIVE	N	N103-00-1/631	Stairs: Spiral - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9978	ACTIVE	N	N103-00-1/661	Switch Room - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44189	ACTIVE	N	N103-00-1/661/ WAL-001 80895486	Wall: Internal - 1 - Switch Room - Station Building - Goodge Street Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				1 x switch box  No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
20173	ACTIVE	N	N103-00-1/661/ WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Goodge Street Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				4 x Transformer Boxes  No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within		4		N	N
19284	ACTIVE	N	N103-00-1/661/ WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Goodge Street Stn	Other Electrical Boxes	Asbestos	Removed				1 x Transformer Box - removed by others		1			



# Hazardous Material Asset Register - Summary



## N103-00 - Station Building - Goodge Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20172	ACTIVE	N	N103-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Goodge Street Stn	Isolator Switches	Asbestos	Strongly Presumed				Blue Switch Boxes - Insulation within 6 x 60, 1 x 100 1x 200 amps  No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within		8		N	N
9979	ACTIVE	N	N103-00-1/761	SVC - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
20174	ACTIVE	N	N103-00-1/761	SVC - Station Building - Goodge Street Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9980	ACTIVE	N	N103-00-1/902	Void - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
20175	ACTIVE	N	N103-00-1/902	Void - Station Building - Goodge Street Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9981	ACTIVE	N	N103-00-1/903	Void - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
20176	ACTIVE	N	N103-00-1/903	Void - Station Building - Goodge Street Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9982	ACTIVE	N	N103-00-1/904	Void - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
20177	ACTIVE	N	N103-00-1/904	Void - Station Building - Goodge Street Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9983	ACTIVE	N	N103-00-1/905	Void - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19742	ACTIVE	N	N103-00-1/905	Void - Station Building - Goodge Street Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9984	ACTIVE	N	N103-00-1/906	Void - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
20178	ACTIVE	N	N103-00-1/906	Void - Station Building - Goodge Street Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
9985	ACTIVE	N	N103-00-2/053	Mess Room - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
20179	ACTIVE	N	N103-00-2/053	Mess Room - Station Building - Goodge Street Stn	LUL Heaters	Asbestos	No Access: Presumed				LU Heater Foam Backing					
20181	ACTIVE	N	N103-00-2/053	Mess Room - Station Building - Goodge Street Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Internal panel to wall cavity - plasterboard					



# Hazardous Material Asset Register - Summary



## N103-00 - Station Building - Goodge Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20180	ACTIVE	N	N103-00-2/053/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Goodge Street Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above false ceiling				YES	
19285	ACTIVE	N	N103-00-2/053/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Goodge Street Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
9986	ACTIVE	N	N103-00-2/081	Lobby - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
20182	ACTIVE	N	N103-00-2/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Goodge Street Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
20183	ACTIVE	N	N103-00-2/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Goodge Street Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above false ceiling				YES	
9987	ACTIVE	N	N103-00-2/082	Lobby - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
20184	ACTIVE	N	N103-00-2/082	Lobby - Station Building - Goodge Street Stn	LUL Heaters	Asbestos	Surveyed - Not Detected				Heater White Foam Backing					
19286	ACTIVE	N	N103-00-2/082/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Goodge Street Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
19743	ACTIVE	N	N103-00-2/082/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Goodge Street Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above false ceiling				YES	
9988	ACTIVE	N	N103-00-2/236	Lobby - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19892	INACTIVE	N	N103-00-2/236	Lobby - Station Building - Goodge Street Stn	Lead/Leading	Lead Paint/Lead	Known				White Oil Based Paint - Girder. Thickness .26mm; Est Quantity 3lm; Analysis 9.29%. Not found upon re inspection 08/10/2014					
20185	ACTIVE	N	N103-00-2/236/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Goodge Street Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
20186	ACTIVE	N	N103-00-2/236/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Goodge Street Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above false ceiling				YES	
20187	ACTIVE	N	N103-00-2/236/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Goodge Street Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Fibreboard Tiles				YES	
9989	ACTIVE	N	N103-00-2/237	Passage - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N103-00 - Station Building - Goodge Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19287	ACTIVE	N	N103-00-2/237	Passage - Station Building - Goodge Street Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux Insulation Board					
20188	ACTIVE	N	N103-00-2/237	Passage - Station Building - Goodge Street Stn	Lead/Leading	Lead Paint/Lead	Known				Black Oil Based Paint - Pipework. Thickness .27mm; Est Quantity 3lm; Analysis 2.38%				N	N
9990	ACTIVE	N	N103-00-2/291	Station Supervisor Office - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25824	ACTIVE	N	N103-00-2/291	Station Supervisor Office - Station Building - Goodge Street Stn	Lead/Leading	Lead Paint/Lead	Presumed				Upon re inspection 08/10/14 it was noted that a white oil based painted Girder is present.				N	N
20189	ACTIVE	N	N103-00-2/291/CLG-01	Ceiling: Solid - 1 - Station Supervisor Office - Station Building - Goodge Street Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Supalux Tiles					
19812	ACTIVE	N	N103-00-2/291/CLG-01	Ceiling: Solid - 1 - Station Supervisor Office - Station Building - Goodge Street Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Fibreboard Tiles				YES	
9991	ACTIVE	N	N103-00-2/292	Switch Room - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20190	ACTIVE	N	N103-00-2/292/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Goodge Street Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Supalux Tiles					
19288	ACTIVE	N	N103-00-2/292/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Goodge Street Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	
9992	ACTIVE	N	N103-00-2/351	Locker Room - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20191	ACTIVE	N	N103-00-2/351/CLG-01	Ceiling: Solid - 1 - Locker Room - Station Building - Goodge Street Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Supalux Tiles					
19320	ACTIVE	N	N103-00-2/351/CLG-01	Ceiling: Solid - 1 - Locker Room - Station Building - Goodge Street Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	
9993	ACTIVE	N	N103-00-2/406	Store - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20192	ACTIVE	N	N103-00-2/406	Store - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9994	ACTIVE	N	N103-00-2/411	Store - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20193	ACTIVE	N	N103-00-2/411	Store - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N103-00 - Station Building - Goodge Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9995	ACTIVE	N	N103-00-2/416	Toilet: Male - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20194	ACTIVE	N	N103-00-2/416/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Goodge Street Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Supalux Tiles					
19289	ACTIVE	N	N103-00-2/416/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Goodge Street Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	
9996	ACTIVE	N	N103-00-2/417	Toilet: Female - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20081	ACTIVE	N	N103-00-2/417/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Goodge Street Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles				YES	
19190	ACTIVE	N	N103-00-2/417/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Goodge Street Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Supalux Tiles					
9997	ACTIVE	N	N103-00-2/631	Stairs: Spiral - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19191	ACTIVE	N	N103-00-2/631	Stairs: Spiral - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
9998	ACTIVE	N	N103-00-2/666	Switch Room - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19192	ACTIVE	N	N103-00-2/666/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Goodge Street Stn	Isolator Switches	Asbestos	Strongly Presumed				4 x 60, 2 x 100 amp Switch Boxes - Insulation within No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within		6		N	N
25825	ACTIVE	N	N103-00-2/666/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Goodge Street Stn	Other Electrical Boxes	Asbestos	Presumed				W3 - 1 x Transformer Box No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
9999	ACTIVE	N	N103-00-2/667	Switch Room - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19193	ACTIVE	N	N103-00-2/667/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Goodge Street Stn	Isolator Switches	Asbestos	Strongly Presumed				4 x 60, 1 x 200, 1 x 100amp Switch Boxes - Insulation within No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within		6		N	N



# Hazardous Material Asset Register - Summary



## N103-00 - Station Building - Goodge Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25826	ACTIVE	N	N103-00-2/667/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Goodge Street Stn	Isolator Switches	Asbestos	Strongly Presumed				W2 - 1 x 30amp Red Switch Box No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
10000	ACTIVE	N	N103-00-2/668	Switch Cupboard - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19194	ACTIVE	N	N103-00-2/668/WAL-001	Wall: Internal - 1 - Switch Cupboard - Station Building - Goodge Street Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 300amp Grey Switch Boxes - Insulation within No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
10001	ACTIVE	N	N103-00-2/669	Switch Room - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
20082	ACTIVE	N	N103-00-2/669	Switch Room - Station Building - Goodge Street Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
10002	ACTIVE	N	N103-00-2/731	CER - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
20083	ACTIVE	N	N103-00-2/731/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Goodge Street Stn	Other Boarding	Asbestos	Presumed				Boxing to Beams Re-inspected by 4-Rail 22-03-2023 (possible supalux, no access to inspect closely)				N	N
19195	ACTIVE	N	N103-00-2/731/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Goodge Street Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Supalux panel above door					
19596	ACTIVE	N	N103-00-2/731/FLR-01	Floor - 1 - CER - Station Building - Goodge Street Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
19197	ACTIVE	N	N103-00-2/731/WAL-002	Wall: Internal - 2 - CER - Station Building - Goodge Street Stn	Other Boarding	Asbestos	Presumed				Paxoline Boarding Re-inspected by 4-Rail 22-03-2023		1		N	N
19196	ACTIVE	N	N103-00-2/731/WAL-005	Wall: Internal - 5 - CER - Station Building - Goodge Street Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x 60amp Grey Switch Boxes - Insulation within No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within		2		N	N
10003	ACTIVE	N	N103-00-2/732	Switch Room - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19199	INACTIVE	N	N103-00-2/732	Switch Room - Station Building - Goodge Street Stn	Isolator Switches	Asbestos	Removed				2 x Grey Switch Boxes - Insulation within Not found upon re inspection 08/10/2014 - Removed		2			
19198	ACTIVE	N	N103-00-2/732/FLR-01	Floor - 1 - Switch Room - Station Building - Goodge Street Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					



# Hazardous Material Asset Register - Summary



## N103-00 - Station Building - Goodge Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19200	ACTIVE	N	N103-00-2/732/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Goodge Street Stn	Other Boarding	Asbestos	Presumed				Panels High Level Re-inspected by 4-Rail Services, possible supalux but limited access to check 22-03-2023				N	N
10004	ACTIVE	N	N103-00-2/746	SCR - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
20084	ACTIVE	N	N103-00-2/746/CLG-01	Ceiling: Solid - 1 - SCR - Station Building - Goodge Street Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Supalux Tiles					
19201	ACTIVE	N	N103-00-2/746/CLG-01	Ceiling: Solid - 1 - SCR - Station Building - Goodge Street Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Supalux Tiles				YES	
19202	ACTIVE	N	N103-00-2/746/CLG-02	Ceiling: Suspended - 2 - SCR - Station Building - Goodge Street Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Supalux Tiles					
19418	ACTIVE	N	N103-00-2/746/CLG-02	Ceiling: Suspended - 2 - SCR - Station Building - Goodge Street Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Supalux Tiles				YES	
10005	ACTIVE	N	N103-00-2/776	Fan Room - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
44188	ACTIVE	N	N103-00-2/776	Fan Room - Station Building - Goodge Street Stn	Lead/Leading	Lead Paint/Lead	Presumed				Presumed lead paint - black and cream gloss				N	N
19203	ACTIVE	N	N103-00-2/776/WAL-002	Wall: Internal - 2 - Fan Room - Station Building - Goodge Street Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
20085	ACTIVE	N	N103-00-2/776/WAL-006	Wall: Internal - 6 - Fan Room - Station Building - Goodge Street Stn	Other Electrical Boxes	Asbestos	Presumed				Panel behind Vent Equipment Re-inspected by 4-Rail Services Ltd 22/03/2023		1		N	N
25827	ACTIVE	N	N103-00-2/776/WAL-006	Wall: Internal - 6 - Fan Room - Station Building - Goodge Street Stn	Rope Seals	Asbestos	Presumed				Possible asbestos rope between flanges Re-inspected by 4-Rail Services 22-03-2023				N	N
19597	ACTIVE	N	N103-00-2/776/WAL-007	Wall: Internal - 7 - Fan Room - Station Building - Goodge Street Stn	Isolator Switches	Asbestos	Strongly Presumed				60amp Grey Switch Box - Insulation within No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
10006	ACTIVE	N	N103-00-2/901	Disused Room - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19204	ACTIVE	N	N103-00-2/901	Disused Room - Station Building - Goodge Street Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
10007	ACTIVE	N	N103-00-2/951	Disused Room - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N103-00 - Station Building - Goodge Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19205	ACTIVE	N	N103-00-2/951	Disused Room - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10008	ACTIVE	N	N103-00-2/952	Store - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19206	ACTIVE	N	N103-00-2/952	Store - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10009	ACTIVE	N	N103-00-2/953	Locker Room - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20086	ACTIVE	N	N103-00-2/953	Locker Room - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10010	ACTIVE	N	N103-00-2/954	Passage - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19207	ACTIVE	N	N103-00-2/954	Passage - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10011	ACTIVE	N	N103-00-2/955	Service Riser - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19208	ACTIVE	N	N103-00-2/955/CLG-01	Ceiling: Solid - 1 - Service Riser - Station Building - Goodge Street Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Small Supalux Panels / Concrete					
10012	ACTIVE	N	N103-00-2/956	Disused Room - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19209	ACTIVE	N	N103-00-2/956	Disused Room - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
20087	ACTIVE	N	N103-00-3/131	Lift Shaft - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
19813	ACTIVE	N	N103-00-3/132	Lift Shaft - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10013	ACTIVE	N	N103-00-3/201	Passage - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19598	ACTIVE	N	N103-00-3/201	Passage - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10014	ACTIVE	N	N103-00-3/202	Passage - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19210	ACTIVE	N	N103-00-3/202	Passage - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N103-00 - Station Building - Goodge Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10015	ACTIVE	N	N103-00-3/203	Passage - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19211	ACTIVE	N	N103-00-3/203	Passage - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10016	ACTIVE	N	N103-00-3/601	Stairs: Linear - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19212	ACTIVE	N	N103-00-3/601	Stairs: Linear - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10017	ACTIVE	N	N103-00-3/602	Stairs: Linear - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20088	ACTIVE	N	N103-00-3/602	Stairs: Linear - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
19213	ACTIVE	N	N103-00-3/636	Overbridge - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
19214	ACTIVE	N	N103-00-3/637	Overbridge - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10018	ACTIVE	N	N103-00-3/665	Switch Cupboard - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19744	ACTIVE	N	N103-00-3/665/FLR-01	Floor - 1 - Switch Cupboard - Station Building - Goodge Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels to Stairs					
19599	ACTIVE	N	N103-00-3/665/WAL-005	Wall: Internal - 5 - Switch Cupboard - Station Building - Goodge Street Stn	Isolator Switches	Asbestos	Strongly Presumed				Grey Switch Boxes - Insulation within - 3 x 60, 1 x 100 amps No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within		4		N	N
10019	ACTIVE	N	N103-00-3/951	Disused Room - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19254	ACTIVE	N	N103-00-3/951	Disused Room - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10020	ACTIVE	N	N103-00-4/121	Platform Invert - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19256	ACTIVE	N	N103-00-4/121	Platform Invert - Station Building - Goodge Street Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Platform 1 Invert - Cable Ducts South & North End					
20089	ACTIVE	N	N103-00-4/121	Platform Invert - Station Building - Goodge Street Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - 3 Braided Cables					



# Hazardous Material Asset Register - Summary



## N103-00 - Station Building - Goodge Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19257	ACTIVE	N	N103-00-4/121	Platform Invert - Station Building - Goodge Street Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - J hangers along entire length of invert - 2 x braided cables		2			
19255	ACTIVE	N	N103-00-4/121	Platform Invert - Station Building - Goodge Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Platform 1 invert under 4/712 & 4/713 Ducts - Bitumen - NADIS					
10021	ACTIVE	N	N103-00-4/122	Platform Invert - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19544	ACTIVE	N	N103-00-4/122	Platform Invert - Station Building - Goodge Street Stn	Cable Ducts: Cement	Asbestos	Known				Platform 2 Invert - Cable Duct under 4/711 - Chrysotile Access to invert via 4/792					
19814	ACTIVE	N	N103-00-4/122	Platform Invert - Station Building - Goodge Street Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - 1 x Braided Cable Access to invert via 4/792		1			
19271	ACTIVE	N	N103-00-4/122	Platform Invert - Station Building - Goodge Street Stn	Cable: Sheath	Asbestos	Strongly Presumed				J hangers along entire length of Platform 2 invert - braided cable Access to invert via 4/792		1			
10022	ACTIVE	N	N103-00-4/201	Passage - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19258	ACTIVE	N	N103-00-4/201	Passage - Station Building - Goodge Street Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel ring caulking, near cross passage within Goodge street Deep level shelter					
20090	ACTIVE	N	N103-00-4/201	Passage - Station Building - Goodge Street Stn	Lead/Leading	Lead Paint/Lead	Known				Dark green coloured paint applied to the floodgate. Analysis 1.56%					
10023	ACTIVE	N	N103-00-4/202	Passage - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19259	ACTIVE	N	N103-00-4/202	Passage - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10024	ACTIVE	N	N103-00-4/261	Platform 1 - Northbound Local - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19260	ACTIVE	N	N103-00-4/261	Platform 1 - Northbound Local - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10025	ACTIVE	N	N103-00-4/262	Platform 2 - Southbound Local - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44933	ACTIVE	N	N103-00-4/262	Platform 2 - Southbound Local - Station Building - Goodge Street Stn	Cable: Sheath	Asbestos	Known				Braided cable on cable run at arrival end, going into platform invert  No access for close inspection during traffic hours re-inspection. 4-Rail 22-03-2023				N	N



# Hazardous Material Asset Register - Summary



## N103-00 - Station Building - Goodge Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44932	ACTIVE	N	N103-00-4/262	Platform 2 - Southbound Local - Station Building - Goodge Street Stn	Cable: Sheath	Asbestos	Known				Braided cable on cable run at departure end, going into platform invert Limited access to re-inspect during traffic hour re-inspection 4-Rail 22-03-2023				N	N
19261	ACTIVE	N	N103-00-4/262	Platform 2 - Southbound Local - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10026	ACTIVE	N	N103-00-4/661	Switch Cupboard - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20091	ACTIVE	N	N103-00-4/661	Switch Cupboard - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10027	ACTIVE	N	N103-00-4/662	Switch Cupboard - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19263	ACTIVE	N	N103-00-4/662/FLR-01	Floor - 1 - Switch Cupboard - Station Building - Goodge Street Stn	Cable Duct: Other	Asbestos	Presumed				3 x Ducts - Sealed - 1 located by Wall 1 and 2 located by Wall 2 Ducts not visible beneath covering - therefore not scored in 2023 re-inspection.		3		N	N
19262	ACTIVE	N	N103-00-4/662/WAL-003	Wall: Internal - 3 - Switch Cupboard - Station Building - Goodge Street Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 60amp Grey Switch Boxes - Insulation within No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
10028	ACTIVE	N	N103-00-4/663	Switch Cupboard - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19600	ACTIVE	N	N103-00-4/663/FLR-01	Floor - 1 - Switch Cupboard - Station Building - Goodge Street Stn	Cable Duct: Other	Asbestos	Presumed				Ducts - Sealed by Wall 2 Re-inspection by 4-Rail 22-03-2023		4		N	N
25828	ACTIVE	N	N103-00-4/663/WAL-001	Wall: Internal - 1 - Switch Cupboard - Station Building - Goodge Street Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 100amp Switch Box No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
19264	ACTIVE	N	N103-00-4/663/WAL-002	Wall: Internal - 2 - Switch Cupboard - Station Building - Goodge Street Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x 60, 1 x 100, 1 x 200 amp Switch Boxes - Insulation within No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within		4		N	N
10029	ACTIVE	N	N103-00-4/664	Switch Cupboard - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20092	ACTIVE	N	N103-00-4/664	Switch Cupboard - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N103-00 - Station Building - Goodge Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10030	ACTIVE	N	N103-00-4/711	Relay Room - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44193	ACTIVE	N	N103-00-4/711/ WAL-001 80896130	Wall: Internal - 1 - Relay Room - Station Building - Goodge Street Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				3 x electrical boxes No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within		3		N	N
19745	ACTIVE	N	N103-00-4/711/ WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Goodge Street Stn	Westing house Boxes	Asbestos	Strongly Presumed				1 x Westinghouse Box - Insulation within No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
44194	ACTIVE	N	N103-00-4/711/ WAL-003 80896132	Wall: Internal - 3 - Relay Room - Station Building - Goodge Street Stn Wall: Internal	Other Boarding	Asbestos	Presumed				Various pieces of Paxoline board Re-inspected by 4-Rail 22-03-2023				N	N
10031	ACTIVE	N	N103-00-4/712	Relay Room - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42497	ACTIVE	N	N103-00-4/712	Relay Room - Station Building - Goodge Street Stn	Other Electrical Boxes	Asbestos	Presumed				1x Rectifier box - Asbestos insulating materials within No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within		1		N	N
19266	ACTIVE	N	N103-00-4/712	Relay Room - Station Building - Goodge Street Stn	Cable Ducts: Bitumen	Asbestos	Surveyed – Not Detected				Ducts - Bitumen					
44192	ACTIVE	N	N103-00-4/712 80143147	Relay Room - Station Building - Goodge Street Stn Room Assets	Cable Ducts: Cement	Asbestos	Sampled – Not Detected				Presumed asbestos cable ducts - assumed same material as ducts tested that run to the invert under room 4/712 which were sampled to be NADIS as per report P011738-001		1	P011738-001	N	N
20093	ACTIVE	N	N103-00-4/712	Relay Room - Station Building - Goodge Street Stn	Cable: Sheath	Asbestos	Strongly Presumed				2x 50mm Green Cable going into Invert Re-inspected by 4-Rail Services 22-03-2023		2		N	N
42495	ACTIVE	N	N103-00-4/712	Relay Room - Station Building - Goodge Street Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Asbestos insulating materials within 600v electrical box No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within		1		N	N
44336	ACTIVE	N	N103-00-4/712	Relay Room - Station Building - Goodge Street Stn	Other Electrical Boxes	Asbestos	Presumed				Grey Tencore Box No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
19267	INACTIVE	N	N103-00-4/712	Relay Room - Station Building - Goodge Street Stn	Other Electrical Boxes	Asbestos	Removed				1 x Transformer Box - Removed - noted upon HMU reinspection 08/10/2014		1			



# Hazardous Material Asset Register - Summary



## N103-00 - Station Building - Goodge Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19265	ACTIVE	N	N103-00-4/712/FLR-01	Floor - 1 - Relay Room - Station Building - Goodge Street Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel Floor					
44191	ACTIVE	N	N103-00-4/712/WAL-001 80896137	Wall: Internal - 1 - Relay Room - Station Building - Goodge Street Stn Wall: Internal	Cable: Sheath	Asbestos	Presumed				5mm cable in corner of room Re-inspected by 4-Rail Services 22-03-2023		1		N	N
10032	ACTIVE	N	N103-00-4/713	Relay Room - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19269	ACTIVE	N	N103-00-4/713	Relay Room - Station Building - Goodge Street Stn	Cable Ducts: Bitumen	Asbestos	Surveyed – Not Detected				Ducts - Bitumen					
42498	ACTIVE	N	N103-00-4/713	Relay Room - Station Building - Goodge Street Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1x 600v Electrical box - Asbestos insulating materials within  No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within		1		N	N
42064	INACTIVE	N	N103-00-4/713	Relay Room - Station Building - Goodge Street Stn	PCBs	Polychlorinated biphenyl	Removed				5 x PCB's - located within roller shutter cabinet - 4 x fair condition, 1 possibly leaking Removed by Edenbeck Feb 2017 under E57773a		5		N	N
19268	ACTIVE	N	N103-00-4/713/FLR-01	Floor - 1 - Relay Room - Station Building - Goodge Street Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel Floor					
44934	ACTIVE	N	N103-00-4/713/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Goodge Street Stn	Cable: Sheath	Asbestos	Strongly Presumed				J hangers - braided cable 2no  Only 1no Cable noted on Re-Inspection				N	N
20094	ACTIVE	N	N103-00-4/713/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Goodge Street Stn	Cable: Sheath	Asbestos	Strongly Presumed				2x 50mm Green Cable going into invert Re-inspected by 4-Rail Services 22-03-2023		2		N	N
19270	ACTIVE	N	N103-00-4/713/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Goodge Street Stn	Cable: Sheath	Asbestos	Strongly Presumed				10mm Cables behind within roller Shutter cabinet Re-inspected by 4-Rail Services 22-03-2023		2		N	N
10033	ACTIVE	N	N103-00-4/714	SER - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19272	ACTIVE	N	N103-00-4/714	SER - Station Building - Goodge Street Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
10034	ACTIVE	N	N103-00-4/731	CER - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42499	ACTIVE	N	N103-00-4/731	CER - Station Building - Goodge Street Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1x 600v Electrical box - Insulated materials within. Within roller shutter cabinet  No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within		1		N	N



# Hazardous Material Asset Register - Summary



## N103-00 - Station Building - Goodge Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42500	ACTIVE	N	N103-00-4/731	CER - Station Building - Goodge Street Stn	Cable: Sheath	Asbestos	Strongly Presumed				3x Braided cables (2x green / 1x yellow) to right hand duct in roller shutter cabinet & Asbestos woven cable to bunch of cables from left hand duct to roller cabinet Re-inspected by 4-Rail Services 22-03-2023		3		N	N
53946	ACTIVE	N	N103-00-4/731	CER - Station Building - Goodge Street Stn	Cable: Sheath	Asbestos	Presumed				1 thin cable to equipment above 600v box. -right-hand side cable coming up from equipment (Left side cable is non asbestos aramid cables)					
19237	ACTIVE	N	N103-00-4/731	CER - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
53947	ACTIVE	N	N103-00-4/731	CER - Station Building - Goodge Street Stn	Other Boarding	Asbestos	Presumed				brown packing material to frame behind clear plastic covered electrical box					
42065	INACTIVE	N	N103-00-4/731	CER - Station Building - Goodge Street Stn	PCBs	Polychlorinated biphenyl	Removed				6 x PCB's - Fair Condition - located within roller shutter cabinet Removed by Edenbeck Feb 2017 under ES7773a		6		N	N
53945	ACTIVE	N	N103-00-4/731/ FLR-01	Floor - 1 - CER - Station Building - Goodge Street Stn		Asbestos	No Access: Presumed				No access to manholes trunking					Y
44190	ACTIVE	N	N103-00-4/731/ WAL-001 80896151	Wall: Internal - 1 - CER - Station Building - Goodge Street Stn Wall: Internal	Cable: Sheath	Asbestos	Presumed				2 x sheathed cables 50mm each (coming from electrical box within roller shutter cabinet) Re-inspected by 4-Rail Services 22-03-2023		2		N	N
10035	ACTIVE	N	N103-00-4/732	CER - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19273	ACTIVE	N	N103-00-4/732	CER - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10036	ACTIVE	N	N103-00-4/786	Service Area - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19274	ACTIVE	N	N103-00-4/786	Service Area - Station Building - Goodge Street Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
19379	ACTIVE	N	N103-00-4/791	Vent Shaft - Station Building - Goodge Street Stn	Cable: Sheath	Asbestos	Strongly Presumed				2 x 20mm Green Cable going into invert Re-inspected by 4-Rail Services 22-03-2023		2	R19046		
44195	ACTIVE	N	N103-00-4/791/ WAL-001 80896166	Wall: Internal - 1 - Vent Shaft - Station Building - Goodge Street Stn Wall: Internal	Cable Ducts: Cement	Asbestos	Presumed				3 x cable ducts on wall 1 Re-inspected by 4-Rail Services 22-03-2023		3		N	N
10037	ACTIVE	N	N103-00-4/792	CER - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N103-00 - Station Building - Goodge Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42502	ACTIVE	N	N103-00-4/792	CER - Station Building - Goodge Street Stn	Cable: Sheath	Asbestos	Strongly Presumed				1x 600v electrical box with asbestos insulating materials within  No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
20095	ACTIVE	N	N103-00-4/792	CER - Station Building - Goodge Street Stn	Cable: Sheath	Asbestos	Strongly Presumed				2 x 50mm Green Cable going into invert Re-inspection by 4-Rail Services 22-03-2023		2		N	N
19275	ACTIVE	N	N103-00-4/792/ WAL-001	Wall: Internal - 1 - CER - Station Building - Goodge Street Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Rectifier box high level  No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
19276	ACTIVE	N	N103-00-4/792/ WAL-003	Wall: Internal - 3 - CER - Station Building - Goodge Street Stn	Other Boarding	Asbestos	Presumed				Small Paxoline Board on Frame Re-inspected by 4-Rail Services 22-03-2023		2		N	N
19601	ACTIVE	N	N103-00-4/793	Vent Shaft - Station Building - Goodge Street Stn	Cable: Sheath	Asbestos	Strongly Presumed				20mm Cable going into invert Re-inspected by 4-Rail Services 22-03-2023					
10038	ACTIVE	N	N103-00-4/951	Switch Room - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19277	ACTIVE	N	N103-00-4/951	Switch Room - Station Building - Goodge Street Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
10039	ACTIVE	N	N103-00-4/952	Switch Room - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19278	ACTIVE	N	N103-00-4/952	Switch Room - Station Building - Goodge Street Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
10040	ACTIVE	N	N103-00-A/031	Mess Room - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19279	ACTIVE	N	N103-00-A/031	Mess Room - Station Building - Goodge Street Stn		Asbestos	Surveyed - Not Detected				Acoustic Panel below sink					
20096	ACTIVE	N	N103-00-A/031	Mess Room - Station Building - Goodge Street Stn	LUL Heaters	Asbestos	Surveyed - Not Detected				LH Heater Foam Backing					
19322	ACTIVE	N	N103-00-A/031/ CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Goodge Street Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Supalux Tiles				YES	
20097	ACTIVE	N	N103-00-A/031/ CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Goodge Street Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Supalux Tiles					
10041	ACTIVE	N	N103-00-A/047	Kitchen - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N103-00 - Station Building - Goodge Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19325	ACTIVE	N	N103-00-A/047	Kitchen - Station Building - Goodge Street Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Fibreboard Partition					
19324	ACTIVE	N	N103-00-A/047/CLG-01	Ceiling: Solid - 1 - Kitchen - Station Building - Goodge Street Stn	Void	Asbestos	No Access: Presumed				Above Fibreboard Tiles				YES	
19323	ACTIVE	N	N103-00-A/047/CLG-01	Ceiling: Solid - 1 - Kitchen - Station Building - Goodge Street Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Fibreboard Tiles					
10042	ACTIVE	N	N103-00-A/131	LMR - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42441	INACTIVE	N	N103-00-A/131	LMR - Station Building - Goodge Street Stn	Boarding: AIB	Asbestos	Presumed				2 x 4 no. break pads to fly wheel of 4 lift motors		2	R504226	N	N
44935	INACTIVE	N	N103-00-A/131	LMR - Station Building - Goodge Street Stn	Other Electrical Boxes	Asbestos	Presumed				Flash guards, 8no x 1m, to combination fuse switch box to Switch Gear				N	N
20148	INACTIVE	N	N103-00-A/131	LMR - Station Building - Goodge Street Stn	Isolator Switches	Asbestos	Surveyed – Not Detected				Blue Switch Boxes - New Survey - No Asbestos Found in Isolators & Bus Bar Chamber		8			
44280	ACTIVE	N	N103-00-A/131	LMR - Station Building - Goodge Street Stn		Asbestos	Not Found during Inspection				Machine board, 2m2, inside dismantled lift machinery in the lift machinery room at Goodge Street Station Item not present in 2020 re-inspection. Possibly removed since last inspection.			R611326	N	N
42444	ACTIVE	N	N103-00-A/131/WAL-002	Wall: Internal - 2 - LMR - Station Building - Goodge Street Stn	Isolator Switches	Asbestos	Not Found during Inspection				Materials within combination fuse switch to wall 2 (LEB supply) Item not present in 2020 re-inspection. Possibly removed since last inspection.		1	R504226	N	N
42445	ACTIVE	N	N103-00-A/131/WAL-002	Wall: Internal - 2 - LMR - Station Building - Goodge Street Stn	Control Panels	Asbestos	Not Found during Inspection				4 x materials within control panels to wall 2 Item not present in 2020 re-inspection. Possibly removed since last inspection.		4	R504226	N	N
42442	ACTIVE	N	N103-00-A/131/WAL-002	Wall: Internal - 2 - LMR - Station Building - Goodge Street Stn	Control Panels	Asbestos	Not Found during Inspection				Materials within 4 x circuit breakers and controller panel 1-4 Item not present in 2020 re-inspection. Possibly removed since last inspection.		4	R504226	N	N
42443	ACTIVE	N	N103-00-A/131/WAL-002	Wall: Internal - 2 - LMR - Station Building - Goodge Street Stn	Control Panels	Asbestos	Not Found during Inspection				4 x Materials within controllers 1-4 by wall 2 Item not present in 2020 re-inspection. Possibly removed since last inspection.		4	R504226	N	N



# Hazardous Material Asset Register - Summary



## N103-00 - Station Building - Goodge Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42446	ACTIVE	N	N103-00-A/131/WAL-005	Wall: Internal - 5 - LMR - Station Building - Goodge Street Stn	Isolator Switches	Asbestos	Presumed				Materials within 2 x combination fuse switch  No electrician on site during 2023 reinspection to open boxes for inspection - therefore cannot score material within. Layout changed since previous inspection. Now only 2no. switch boxes are present.		2	R504226	N	N
42447	ACTIVE	N	N103-00-A/131/WAL-005	Wall: Internal - 5 - LMR - Station Building - Goodge Street Stn	Other Electrical Boxes	Asbestos	Presumed				Bus Bar  No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within. Note - layout of equipment changed since previous inspection.		1	R504226	N	N
10043	ACTIVE	N	N103-00-A/236	Passage - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19746	ACTIVE	N	N103-00-A/236/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Goodge Street Stn	Void	Asbestos	No Access: Presumed				Above Fibreboard Tiles				YES	
19326	ACTIVE	N	N103-00-A/236/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Goodge Street Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Fibreboard Tiles					
10044	ACTIVE	N	N103-00-A/301	Mess Room - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19327	ACTIVE	N	N103-00-A/301/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Goodge Street Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Fibreboard Tiles					
19815	ACTIVE	N	N103-00-A/301/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Goodge Street Stn	Void	Asbestos	No Access: Presumed				Above Fibreboard Tiles				YES	
10045	ACTIVE	N	N103-00-A/416	Toilet: Unisex - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19328	ACTIVE	N	N103-00-A/416/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Goodge Street Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Fibreboard Tiles					
19602	ACTIVE	N	N103-00-A/416/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Goodge Street Stn	Void	Asbestos	No Access: Presumed				Above Fibreboard Tiles				YES	
10046	ACTIVE	N	N103-00-A/417	Lobby - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20149	ACTIVE	N	N103-00-A/417/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Goodge Street Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	



# Hazardous Material Asset Register - Summary



## N103-00 - Station Building - Goodge Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19329	ACTIVE	N	N103-00-A/417/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Goodge Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
10047	ACTIVE	N	N103-00-A/418	Toilet: Male - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19330	ACTIVE	N	N103-00-A/418/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Goodge Street Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Fibreboard Tiles					
19331	ACTIVE	N	N103-00-A/418/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Goodge Street Stn	Void	Asbestos	No Access: Presumed				Above Fibreboard Tiles				YES	
10048	ACTIVE	N	N103-00-A/419	Toilet: Unisex - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19333	ACTIVE	N	N103-00-A/419/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Goodge Street Stn	Void	Asbestos	No Access: Presumed				Above Fibreboard Tiles				YES	
19332	ACTIVE	N	N103-00-A/419/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Goodge Street Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Fibreboard Tiles					
10049	ACTIVE	N	N103-00-A/576	Stairs: Linear - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20150	ACTIVE	N	N103-00-A/576	Stairs: Linear - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10050	ACTIVE	N	N103-00-A/578	Stairs: Linear - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19335	ACTIVE	N	N103-00-A/578/CLG-01	Ceiling: Suspended - 1 - Linear Stairs - Station Building - Goodge Street Stn	Void	Asbestos	No Access: Presumed				Above Supalux Board				YES	
19334	ACTIVE	N	N103-00-A/578/CLG-01	Ceiling: Suspended - 1 - Linear Stairs - Station Building - Goodge Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board					
10051	ACTIVE	N	N103-00-A/631	Stairs: Spiral - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20151	ACTIVE	N	N103-00-A/631	Stairs: Spiral - Station Building - Goodge Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
54001	ACTIVE	N	N103-00-A/631	Stairs: Spiral - Station Building - Goodge Street Stn	Lead/Leading	Lead Paint/Lead	Known				Black Gloss Paint to External Emergency Staircase - throughout - highest level 1.81%			R728401		



# Hazardous Material Asset Register - Summary



## N103-00 - Station Building - Goodge Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10052	ACTIVE	N	N103-00-A/786	Service Riser - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19336	ACTIVE	N	N103-00-A/786/CLG-01	Ceiling: Solid - 1 - Service Riser - Station Building - Goodge Street Stn	Void	Asbestos	No Access: Presumed				Above Vermiculite				YES	
10053	ACTIVE	N	N103-00-B/301	Office - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19337	ACTIVE	N	N103-00-B/301/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Goodge Street Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Fibreboard Tiles					
19238	ACTIVE	N	N103-00-B/301/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Goodge Street Stn	Void	Asbestos	No Access: Presumed				Above Fibreboard Tiles				YES	
10054	ACTIVE	N	N103-00-B/303	Office - Station Building - Goodge Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20152	ACTIVE	N	N103-00-B/303	Office - Station Building - Goodge Street Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					

## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10055	INACTIVE	N	N105-00-1/031	Mess Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished - TWBN/Cross Rail project					
10056	INACTIVE	N	N105-00-1/201	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished - TWBN / Cross Rail project					
19529	INACTIVE	N	N105-00-1/201	Passage - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				Demolished - TWBN / Cross Rail project No Asbestos Visible					
19528	INACTIVE	N	N105-00-1/201/WAL-001	Wall: Internal - 1 - Passage - Station Building - Tottenham Court Road Stn		Anthrax	Surveyed – Not Detected				Demolished - TWBN / Cross Rail project No Anthrax Detected					
10057	INACTIVE	N	N105-00-1/202	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished - TWBN / Cross Rail project					
19174	INACTIVE	N	N105-00-1/202	Passage - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				Demolished - TWBN / Cross Rail project No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10058	INACTIVE	N	N105-00-1/203	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished - TWBN / Cross Rail project					
19530	INACTIVE	N	N105-00-1/203	Passage - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				Demolished - TWBN / Cross Rail project No Asbestos Visible					
10059	INACTIVE	N	N105-00-1/236	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished - TWBN / Cross Rail project					
19531	INACTIVE	N	N105-00-1/236	Passage - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				Demolished - TWBN / Cross Rail project No Asbestos Visible					
10060	INACTIVE	N	N105-00-1/237	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished - TWBN / Cross Rail project					
19532	INACTIVE	N	N105-00-1/237	Passage - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				Demolished - TWBN / Cross Rail project No Asbestos Visible					
10061	ACTIVE	N	N105-00-1/238	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				New Construction - TWBN / Cross Rail project Passage Formerly 1/412, 1/781, 1/782 N105-04s Iss 17 2008/9 SID number has been re used in a new location					
19175	ACTIVE	N	N105-00-1/238	Passage - Station Building - Tottenham Court Road Stn	No Access	Asbestos	No Access: Presumed				New Construction - TWBN / Cross Rail project Passage Formerly 1/412, 1/781, 1/782 N105-04s Iss 17 2008/9 SID number has been re used in a new location					
10062	ACTIVE	N	N105-00-1/401	Store - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished - TWBN/CrossRail project					
10063	ACTIVE	N	N105-00-1/411	Store - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished TWBN/CrossRail project					
19610	INACTIVE	N	N105-00-1/411	Store - Station Building - Tottenham Court Road Stn		Asbestos	Area Demolished				Demolished TWBN/CrossRail project No Asbestos Visible					
10064	INACTIVE	N	N105-00-1/412	Store - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished - TWBN/Cross Rail project					
19535	INACTIVE	N	N105-00-1/412	Store - Station Building - Tottenham Court Road Stn	Durasteel	Asbestos	Area Demolished				Demolished - TWBN / Cross Rail project Access door 10m <sup>2</sup> Durasteel access door and panel to right					
19176	INACTIVE	N	N105-00-1/412	Store - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Area Demolished				Demolished - TWBN / Cross Rail project Air con motor with supalux boxing					



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19534	INACTIVE	N	N105-00-1/412/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Tottenham Court Road Stn	Void	Asbestos	Area Demolished				Demolished - TWBN / Cross Rail project Above false ceiling				YES	
19533	INACTIVE	N	N105-00-1/412/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Area Demolished				Demolished - TWBN / Cross Rail project Supalux / Concrete					
10065	INACTIVE	N	N105-00-1/426	SVC - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished - TWBN / Cross Rail project					
19536	INACTIVE	N	N105-00-1/426	SVC - Station Building - Tottenham Court Road Stn		Asbestos	Area Demolished				Demolished - TWBN / Cross Rail project No Asbestos Visible					
10066	INACTIVE	N	N105-00-1/428	Toilet - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished - TWBN / Cross Rail project					
19537	INACTIVE	N	N105-00-1/428	Toilet - Station Building - Tottenham Court Road Stn		Asbestos	Area Demolished				Demolished - TWBN / Cross Rail project					
10067	ACTIVE	N	N105-00-1/451	Tenancy - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished - TWBN / Cross Rail project					
19538	INACTIVE	N	N105-00-1/451/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Area Demolished				Demolished - TWBN / Cross Rail project Supalux panels Wooden Panels		2			
19611	INACTIVE	N	N105-00-1/451/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				Demolished - TWBN / Cross Rail project Plastic cables & metal conduits, metal pipework, concrete above false ceiling (Responsibility of LU Group Properties)		4		YES	
10068	INACTIVE	N	N105-00-1/452	Tenancy - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished - TWBN / Cross Rail project					
19381	INACTIVE	N	N105-00-1/452/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				Demolished - TWBN / Cross Rail project Plastic cables & metal conduits, concrete above false ceiling (responsibility of LU Group Properties)		3		YES	
19177	INACTIVE	N	N105-00-1/452/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Demolished - TWBN / Cross Rail project Supalux panels to false ceiling RSJ beam to ceiling Wooden Panels		3		YES	
10069	INACTIVE	N	N105-00-1/601	Stairs: Linear - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished - TWBN / Cross Rail project					
19539	INACTIVE	N	N105-00-1/601	Stairs: Linear - Station Building - Tottenham Court Road Stn		Asbestos	Area Demolished				Demolished - TWBN / Cross Rail project No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10070	INACTIVE	N	N105-00-1/602	Stairs: Linear - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished - TWBN / Cross Rail project					
19540	INACTIVE	N	N105-00-1/602	Stairs: Linear - Station Building - Tottenham Court Road Stn		Asbestos	Area Demolished				Demolished - TWBN / Cross Rail project No Asbestos Visible					
10071	INACTIVE	N	N105-00-1/603	Stairs: Linear - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished - TWBN / Cross Rail project					
19574	INACTIVE	N	N105-00-1/603	Stairs: Linear - Station Building - Tottenham Court Road Stn		Asbestos	Area Demolished				Demolished - TWBN / Cross Rail project No Asbestos Visible					
10072	INACTIVE	N	N105-00-1/604	Stairs: Linear - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished - TWBN / Cross Rail project					
19575	INACTIVE	N	N105-00-1/604	Stairs: Linear - Station Building - Tottenham Court Road Stn		Asbestos	Area Demolished				Demolished - TWBN / Cross Rail project No Asbestos Visible					
10073	INACTIVE	N	N105-00-1/605	Stairs: Linear - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished - TWBN / Cross Rail project					
19576	INACTIVE	N	N105-00-1/605	Stairs: Linear - Station Building - Tottenham Court Road Stn		Asbestos	Area Demolished				Demolished - TWBN / Cross Rail project No Asbestos Visible					
10074	INACTIVE	N	N105-00-1/606	Stairs: Linear - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished - TWBN / Cross Rail project					
19821	INACTIVE	N	N105-00-1/606	Stairs: Linear - Station Building - Tottenham Court Road Stn		Asbestos	Area Demolished				Demolished - TWBN / Cross Rail project No Asbestos Visible					
10075	INACTIVE	N	N105-00-1/607	Stairs: Linear - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished - TWBN / Cross Rail project					
19187	INACTIVE	N	N105-00-1/607	Stairs: Linear - Station Building - Tottenham Court Road Stn		Asbestos	Area Demolished				Demolished - TWBN / Cross Rail project No Asbestos Visible					
10076	INACTIVE	N	N105-00-1/608	Stairs: Linear - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				As part of the TWBN / Cross Rail project the SID number has been changed to 2/610. 1/608 is no longer in use on the station layouts					
19577	INACTIVE	N	N105-00-1/608	Stairs: Linear - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				SID number changed to 2/610 as part of the TWBN / Cross Rail project No Asbestos Visible					
10077	INACTIVE	N	N105-00-1/609	Stairs: Linear - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				SID number changed to 2/609 as part of the TWBN / Cross Rail project No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19578	INACTIVE	N	N105-00-1/609	Stairs: Linear - Station Building - Tottenham Court Road Stn		Asbestos	Area Demolished				SID number changed to 2/609 as part of the TWBN / Cross Rail project  No Asbestos Visible					
10078	INACTIVE	N	N105-00-1/610	Switch Room - Station Building - Tottenham Court Road Stn (Crossrail)	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished as part of the TWBN/ Cross Rail project					
19579	INACTIVE	N	N105-00-1/610/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Tottenham Court Road Stn (Crossrail)	Void	Asbestos	Area Demolished				Demolished as part of the TWBN/ Cross Rail project Concrete, piro cables, plastic cable above false ceiling				YES	
19188	INACTIVE	N	N105-00-1/610/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Tottenham Court Road Stn (Crossrail)	Boarding: Supalux	Asbestos	Area Demolished				Demolished as part of the TWBN/ Cross Rail project Supalux Tiles					
10079	INACTIVE	N	N105-00-1/781	Switch Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				1/781 has been merged into 1/238 as part of the TWBN / Cross Rail project. Transformer room has been relocated - station layout N105-19s					
19581	INACTIVE	N	N105-00-1/781	Switch Room - Station Building - Tottenham Court Road Stn	No Access	Asbestos	Area Demolished				1/781 has been merged into 1/238 as part of the TWBN / Cross Rail project. Transformer room has been relocated - station layout N105-19s.					
10080	INACTIVE	N	N105-00-1/782	TXR - Falconberg Court - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				1/782 has been merged into 1/238 as part of the TWBN / Cross Rail project. Transformer room has been relocated - station layout N105-19s Responsibility of UK Power networks (old record)					
19749	INACTIVE	N	N105-00-1/782	TXR - Falconberg Court - Station Building - Tottenham Court Road Stn	No Access	Asbestos	Area Demolished				Not Surveyed - Responsibility of UK Power networks (old record) 1/782 has been merged into 1/238 as part of the TWBN / Cross Rail project. Transformer room has been relocated - station layout N105-19s. SID No. re used and remains the same					
10081	ACTIVE	N	N105-00-1/901	Disused Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished SID No. has been re-used for Mezzanine Deck					
10082	INACTIVE	N	N105-00-2/001	Booking Hall - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				As part of the TWBN / Cross Rail project this area has been merged with 2/071					
19584	INACTIVE	N	N105-00-2/001/CLG-01	Ceiling: Suspended - 1 - Booking Hall - Station Building - Tottenham Court Road Stn	Cellactite Sheeting	Asbestos	Removed				As part of the TWBN / Cross Rail project this area has been merged with 2/071 12m <sup>2</sup> Cellactite above false ceiling - Removed December 2014		1		YES	
19583	INACTIVE	N	N105-00-2/001/CLG-01	Ceiling: Suspended - 1 - Booking Hall - Station Building - Tottenham Court Road Stn	Mastic	Asbestos	Removed				As part of the TWBN / Cross Rail project this area has been merged with 2/071 Mastic to ductwork - Removed 2014				YES	



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19189	INACTIVE	N	N105-00-2/001/CLG-01	Ceiling: Suspended - 1 - Booking Hall - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				As part of the TWBN / Cross Rail project this area has been merged with 2/071 Supalux board above column number 1, 10lm Ducting		1			
19582	INACTIVE	N	N105-00-2/001/CLG-01	Ceiling: Suspended - 1 - Booking Hall - Station Building - Tottenham Court Road Stn	Other Boarding	Asbestos	Surveyed – Not Detected				As part of the TWBN / Cross Rail project this area has been merged with 2/071 Master board				YES	
10083	INACTIVE	N	N105-00-2/011	Ticket Office - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished as part of the TWBN / Cross Rail project					
19234	INACTIVE	N	N105-00-2/011/CLG-01	Ceiling: Solid - 1 - Ticket Office - Station Building - Tottenham Court Road Stn	Void	Asbestos	Area Demolished				Demolished as part of the TWBN / Cross Rail project Breeze block, concrete, plastic cable, air con, vermiculite lagging to pipes above false ceiling				YES	
19586	INACTIVE	N	N105-00-2/011/CLG-01	Ceiling: Solid - 1 - Ticket Office - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Area Demolished				Demolished as part of the TWBN / Cross Rail project Supalux Tiles					
19587	INACTIVE	N	N105-00-2/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Tottenham Court Road Stn	Void	Asbestos	Area Demolished				Demolished as part of the TWBN / Cross Rail project Concrete, plastic cable, trunking beneath computer tile (nylon)					YES
19585	INACTIVE	N	N105-00-2/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Tottenham Court Road Stn	Void	Asbestos	Area Demolished				Demolished as part of the TWBN / Cross Rail project Concrete, plastic cables beneath computer flooring					YES
10084	INACTIVE	N	N105-00-2/021	POM - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished as part of the TWBN / Cross Rail project					
19614	INACTIVE	N	N105-00-2/021/CLG-01	Ceiling: Solid - 1 - POM - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Area Demolished				Demolished as part of the TWBN / Cross Rail project Supalux Tiles					
19588	INACTIVE	N	N105-00-2/021/CLG-01	Ceiling: Solid - 1 - POM - Station Building - Tottenham Court Road Stn	Void	Asbestos	Area Demolished				Demolished as part of the TWBN / Cross Rail project Breeze block, concrete, plaster, plastic cable, rock wool above false ceiling				YES	
19872	INACTIVE	N	N105-00-2/021/CLG-01	Ceiling: Solid - 1 - POM - Station Building - Tottenham Court Road Stn	Cellactite Sheeting	Asbestos	Area Demolished				Demolished as part of the TWBN / Cross Rail project 20m <sup>2</sup> Cellactite water management - Removed by Rhodar Dec 2014		1		YES	
25874	INACTIVE	N	N105-00-2/021/WAL-003	Wall: Internal - 3 - POM - Station Building - Tottenham Court Road Stn	Boarding: AIB	Asbestos	Area Demolished				Demolished as part of the TWBN / Cross Rail project Meduim density board >5m to trunking at high level wall 3 - Removed Dec 2014	5			N	N



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10085	INACTIVE	N	N105-00-2/031	Mess Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished as part of the TWBN / Cross Rail project					
19590	INACTIVE	N	N105-00-2/031/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Area Demolished				Demolished as part of the TWBN / Cross Rail project Supalux Tiles					
19591	INACTIVE	N	N105-00-2/031/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Tottenham Court Road Stn	Void	Asbestos	Area Demolished				Demolished as part of the TWBN / Cross Rail project Rock wool, concrete, plaster, plastic cable, air con unit above false ceiling				YES	
19235	INACTIVE	N	N105-00-2/031/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Tottenham Court Road Stn	Cellactite Sheeting	Asbestos	Area Demolished				Demolished as part of the TWBN / Cross Rail project Cellactite, 4m <sup>2</sup> AFC - Removed Dec 2014		1			
19589	INACTIVE	N	N105-00-2/031/WAL-003	Wall: Internal - 3 - Mess Room - Station Building - Tottenham Court Road Stn	LUL Heaters	Asbestos	Area Demolished				Demolished as part of the TWBN / Cross Rail project LTB fire heater pad 12x10		12			
10086	INACTIVE	N	N105-00-2/036	Toilet - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished as part of the TWBN / Cross Rail project					
19595	INACTIVE	N	N105-00-2/036/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Area Demolished				Demolished as part of the TWBN / Cross Rail project Toilet Cubicle - Supalux Tiles		1			
19593	INACTIVE	N	N105-00-2/036/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Tottenham Court Road Stn	Void	Asbestos	Area Demolished				Demolished as part of the TWBN / Cross Rail project Air con, plastic cables, rock wool, concrete, plaster above false ceiling				YES	
19645	INACTIVE	N	N105-00-2/036/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Tottenham Court Road Stn	Cellactite Sheeting	Asbestos	Area Demolished				Demolished as part of the TWBN / Cross Rail project Toilet Cubicle - 10m <sup>2</sup> Cellactite above false ceiling - Removed Dec 2014		1		YES	
19644	INACTIVE	N	N105-00-2/036/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Tottenham Court Road Stn	Void	Asbestos	Area Demolished				Demolished as part of the TWBN / Cross Rail project Toilet Cubicle - Air con, plaster, concrete, rock wool, plastic cables above false ceiling				YES	
19592	INACTIVE	N	N105-00-2/036/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Area Demolished				Demolished as part of the TWBN / Cross Rail project Supalux Tiles					
19594	INACTIVE	N	N105-00-2/036/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Tottenham Court Road Stn	Cellactite Sheeting	Asbestos	Area Demolished				Demolished as part of the TWBN / Cross Rail project 3m <sup>2</sup> Cellactite above false ceiling - Removed Dec 2014		1		YES	



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19236	INACTIVE	N	N105-00-2/036/WAL-004	Wall: Internal - 4 - Toilet - Station Building - Tottenham Court Road Stn	Cellactite Sheeting	Asbestos	Area Demolished				Demolished as part of the TWBN / Cross Rail project  1m <sup>2</sup> Cellactite above wall 4 - Removed Dec 2014		1			
10087	ACTIVE	N	N105-00-2/071	Circulation Area - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Formerly 2/001 - Booking Hall - changes made as part of the TWBN / Cross Rail project.					
19647	ACTIVE	N	N105-00-2/071	Circulation Area - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Esc 5 (Arch 1 from top landing) - supalux debris, debris within arch - NADIS.  2/071 has been merged with 2/001 and is now the Booking Hall - changes made as part of the TWBN / Cross Rail project.					
42501	INACTIVE	N	N105-00-2/071	Circulation Area - Station Building - Tottenham Court Road Stn	Cable Ducts: Bitumen	Asbestos	Removed				Bitumen cable ducts (1 no.), within pit to floor (Record transferred across from 2/001. 2/001 and 2/071 have been merged into 2/071)			R478051	N	
19250	ACTIVE	N	N105-00-2/071/CLG-01	Ceiling: Suspended - 1 - Circulation Area - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles. Metal mesh to false ceiling, metal pipework to false ceiling, steel sheet to high level ceiling, aluminium vent duct  2/071 has been merged with 2/001 and is now the Booking Hall - changes made as part of the TWBN / Cross Rail project.					
19646	ACTIVE	N	N105-00-2/071/CLG-01	Ceiling: Suspended - 1 - Circulation Area - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, plastic cables, master board, steel cable tray in false ceiling, plasterboard to beam in false ceiling above false ceiling  2/071 has been merged with 2/001 and is now the Booking Hall - changes made as part of the TWBN / Cross Rail project.				YES	
10088	INACTIVE	N	N105-00-2/201	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished as part of the TWBN/ CrossRail project					
19648	INACTIVE	N	N105-00-2/201	Passage - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				Demolished as part of the TWBN/ CrossRail project No Asbestos Visible					
41909	INACTIVE	N	N105-00-2/201/FLR-01	Floor - 1 - Passage - Station Building - Tottenham Court Road Stn		Asbestos	Sampled – Not Detected				Demolished as part of the TWBN/ CrossRail project Pipe insulation (1 no.) to pipe within pit to floor slab		1			
10089	INACTIVE	N	N105-00-2/236	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished - TWBN/CrossRail project					
19251	INACTIVE	N	N105-00-2/236/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Tottenham Court Road Stn	Cellactite Sheeting	Asbestos	Area Demolished				Demolished - TWBN/CrossRail project  3m <sup>2</sup> Cellactite water management above false ceiling - Removed Dec 2014		1		YES	



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19365	INACTIVE	N	N105-00-2/236/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Tottenham Court Road Stn	Void	Asbestos	Area Demolished				Demolished - TWBN/CrossRail project Breeze block, concrete, plastic cable, rock wool. Vermiculite lagging to pipes above false ceiling				YES	
19650	INACTIVE	N	N105-00-2/236/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Area Demolished				Demolished - TWBN/CrossRail project Supalux Tiles					
19649	INACTIVE	N	N105-00-2/236/FLR-01	Floor - 1 - Passage - Station Building - Tottenham Court Road Stn	Void	Asbestos	Area Demolished				Demolished - TWBN/CrossRail project Concrete, plastic cables, trunking, fibre glass beneath computer tile (nylon)					YES
10090	INACTIVE	N	N105-00-2/311	Office - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished - TWBN/CrossRail project					
19617	INACTIVE	N	N105-00-2/311/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Area Demolished				Demolished TWBN/CrossRail project Supalux Tiles					
19653	INACTIVE	N	N105-00-2/311/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Tottenham Court Road Stn	Void	Asbestos	Area Demolished				Demolished - TWBN/CrossRail project Air con, rock wool, plastic cables, concrete, breeze block. Packing between pipes. Vermiculite boxing high level				YES	
19654	INACTIVE	N	N105-00-2/311/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Tottenham Court Road Stn	Cellactite Sheeting	Asbestos	Area Demolished				Demolished - TWBN/CrossRail project 14m <sup>2</sup> Cellactite - Removed by Rhodar Dec 2014		1			
19651	INACTIVE	N	N105-00-2/311/DOR-01	Door - 1 - Office - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Area Demolished				Demolished TWBN/CrossRail project Supalux panel low level on access door					
19652	INACTIVE	N	N105-00-2/311/WAL-001	Wall: Internal - 1 - Office - Station Building - Tottenham Court Road Stn	LUL Heaters	Asbestos	Area Demolished				Demolished - TWBN/CrossRail project LTB fire - Heater pad within 10"x12"					
10091	INACTIVE	N	N105-00-2/396	Disused Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished - TWBN / CrossRail project					
19655	INACTIVE	N	N105-00-2/396	Disused Room - Station Building - Tottenham Court Road Stn		Asbestos	Area Demolished				Demolished - TWBN / CrossRail project No Asbestos Visible					
10092	INACTIVE	N	N105-00-2/631	Stairs: Spiral - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished - TWBN / Cross Rail project					



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19252	INACTIVE	N	N105-00-2/631	Stairs: Spiral - Station Building - Tottenham Court Road Stn		Asbestos	Area Demolished				Demolished - TWBN / Cross Rail project No Asbestos Visible					
10093	INACTIVE	N	N105-00-2/746	SCR - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished - TWBN / CrossRail project					
19656	INACTIVE	N	N105-00-2/746	SCR - Station Building - Tottenham Court Road Stn		Asbestos	Area Demolished				Demolished - TWBN / Cross Rail project No Asbestos Visible					
10094	INACTIVE	N	N105-00-2/776	Plant Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Demolished - TWBN / Cross Rail project					
19875	INACTIVE	N	N105-00-2/776/CLG-01	Ceiling: Solid - 1 - Plant Room - Station Building - Tottenham Court Road Stn	Mastic	Asbestos	Area Demolished				Demolished - TWBN / Cross Rail project Mastic to ductwork - Removed Dec 2014					
19657	INACTIVE	N	N105-00-2/776/WAL-001	Wall: Internal - 1 - Plant Room - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Area Demolished				Demolished - TWBN / Cross Rail project Tunnel ring caulking throughout - Non asbestos					
10095	INACTIVE	N	N105-00-2/786	Service Riser - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				As part of the TWBN / Cross Rail project this area has been merged with 2/071					
19253	INACTIVE	N	N105-00-2/786	Service Riser - Station Building - Tottenham Court Road Stn		Asbestos	Area Demolished				No Asbestos Visible As part of the TWBN / Cross Rail project this area has been merged with 2/071					
10096	ACTIVE	N	N105-00-3/151	UMC - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42338	ACTIVE	N	N105-00-3/151	UMC - Station Building - Tottenham Court Road Stn		Asbestos	Sampled – Not Detected				Vermiculite cladding to 1 x sprinkler pipework			R506751	N	N
19660	ACTIVE	N	N105-00-3/151	UMC - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Surveyed – Not Detected				Disused Tunnel off UMC - Caulking throughout - NAD					
19659	ACTIVE	N	N105-00-3/151/CLG-01	Ceiling: Solid - 1 - UMC - Station Building - Tottenham Court Road Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				YES	
19658	ACTIVE	N	N105-00-3/151/CLG-01	Ceiling: Solid - 1 - UMC - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				High level LHS of access door- Supalux panel					
19301	ACTIVE	N	N105-00-3/151/FLR-01	Floor - 1 - UMC - Station Building - Tottenham Court Road Stn	Durasteel	Asbestos	Surveyed – Not Detected				Lid to Storage Bin					



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10097	ACTIVE	N	N105-00-3/201	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19661	ACTIVE	N	N105-00-3/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				Non asbestos pipework & cables. Concrete above false ceiling - concrete, cables, metal & plastic, ducting to ceiling - no asbestos visible, metal mesh				YES	
10098	ACTIVE	N	N105-00-3/396	SVC - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19618	ACTIVE	N	N105-00-3/396	SVC - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux (Walls)					
19663	ACTIVE	N	N105-00-3/396/CLG-01	Ceiling: Solid - 1 - SVC - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				Metal Grill forms Floor to 2/776 above false ceiling		1		YES	
19662	ACTIVE	N	N105-00-3/396/CLG-01	Ceiling: Solid - 1 - SVC - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
10099	ACTIVE	N	N105-00-3/411	Disused Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19302	ACTIVE	N	N105-00-3/411	Disused Room - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel ring caulking					
10100	ACTIVE	N	N105-00-3/631	Stairs: Spiral - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19664	ACTIVE	N	N105-00-3/631	Stairs: Spiral - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel Rings - Solid Caulking - sampled		1			
19711	ACTIVE	N	N105-00-3/631/CLG-01	Ceiling: Suspended - 1 - Spiral Stairs - Station Building - Tottenham Court Road Stn	Void	Asbestos	No Access: Presumed				Above metal ceiling				YES	
10101	ACTIVE	N	N105-00-3/665	Switch Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19713	ACTIVE	N	N105-00-3/665	Switch Room - Station Building - Tottenham Court Road Stn	Isolator Switches	Asbestos	Surveyed – Not Detected				All asbestos insulation materials removed		14			
19712	ACTIVE	N	N105-00-3/665/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel					
10102	ACTIVE	N	N105-00-3/666	Switch Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19313	ACTIVE	N	N105-00-3/666	Switch Room - Station Building - Tottenham Court Road Stn	Isolator Switches	Asbestos	Surveyed – Not Detected				All asbestos insulation materials removed		12			



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10103	ACTIVE	N	N105-00-3/776	Plant Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10104	ACTIVE	N	N105-00-4/081	Circulation Area - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19714	ACTIVE	N	N105-00-4/081/CLG-01	Ceiling: Suspended - 1 - Circulation Area - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				Stainless steel water management & concrete above VE Panel				YES	
10105	ACTIVE	N	N105-00-4/082	Circulation Area - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19715	ACTIVE	N	N105-00-4/082/CLG-01	Ceiling: Suspended - 1 - Circulation Area - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				Stainless steel water management & concrete above VE Panel				YES	
10106	ACTIVE	N	N105-00-4/083	Lobby - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19314	ACTIVE	N	N105-00-4/083/WAL-004	Wall: Internal - 4 - Lobby - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panel above door					
10107	ACTIVE	N	N105-00-4/091	Circulation Area - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Surveyed – Asbestos Known									
42507	ACTIVE	N	N105-00-4/091	Circulation Area - Station Building - Tottenham Court Road Stn	Cable Ducts: Cement	Asbestos	Known				Cement ducting, 7m, running under steps to 4/604 - 4/091	7		R491226	N	
41923	ACTIVE	N	N105-00-4/091	Circulation Area - Station Building - Tottenham Court Road Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				8 x Bitumen Cable Ducts within cable pit to floor towards the Circulation Area within lower intermediate level		8			
41922	ACTIVE	N	N105-00-4/091	Circulation Area - Station Building - Tottenham Court Road Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				11 x Bitumen cable ducts within the cable pit to floor and towards stairs 4/604 within the Circulation Area		11			
19716	ACTIVE	N	N105-00-4/091/CLG-01	Ceiling: Suspended - 1 - Circulation Area - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				New Corrugated Metal Sheeting / Water Management System. Metal Tunnel Rings - Concrete Fill above false ceiling				YES	
10108	ACTIVE	N	N105-00-4/151	UMC Access - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19315	ACTIVE	N	N105-00-4/151	UMC Access - Station Building - Tottenham Court Road Stn	Isolator Switches	Asbestos	Surveyed – Not Detected				All asbestos insulation materials removed		1			



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19719	ACTIVE	N	N105-00-4/151/CLG-01	Ceiling: Solid - 1 - UMC - Station Building - Tottenham Court Road Stn	Void	Asbestos	No Access: Presumed				Above Supalux panel				YES	
19717	ACTIVE	N	N105-00-4/151/CLG-01	Ceiling: Solid - 1 - UMC - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panel at start of incline					
19718	ACTIVE	N	N105-00-4/151/CLG-01	Ceiling: Solid - 1 - UMC - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Ring - Caulking - Solid; Lagging - Non Asbestos					
19668	ACTIVE	N	N105-00-4/151/FLR-01	Floor - 1 - UMC - Station Building - Tottenham Court Road Stn	Durasteel	Asbestos	Surveyed – Not Detected				Lid to Storage Bin					
10109	ACTIVE	N	N105-00-4/152	UMC - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19721	ACTIVE	N	N105-00-4/152	UMC - Station Building - Tottenham Court Road Stn	Isolator Switches	Asbestos	Surveyed – Not Detected				All asbestos insulation materials removed		1			
19720	ACTIVE	N	N105-00-4/152/FLR-01	Floor - 1 - UMC Access - Station Building - Tottenham Court Road Stn	Durasteel	Asbestos	Surveyed – Not Detected				Lid to Storage Bin					
10110	ACTIVE	N	N105-00-4/161	LMC - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19722	ACTIVE	N	N105-00-4/161	LMC - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10111	ACTIVE	N	N105-00-4/162	LMC - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19316	ACTIVE	N	N105-00-4/162	LMC - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Known				30m Cable - Encapsulated No access 2020 re-inspection require L&E pass.		1			
19723	ACTIVE	N	N105-00-4/162	LMC - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Known				10mm Cable - Encapsulated No access 2020 re-inspection require L&E pass.		1			
10112	ACTIVE	N	N105-00-4/201	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19422	ACTIVE	N	N105-00-4/201/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				The Rotunda area was surveyed - No asbestos detected. Dust to tunnel ring throughout above metal ceiling.				YES	
19801	ACTIVE	N	N105-00-4/201/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Ring Caulking				YES	



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10113	ACTIVE	N	N105-00-4/202	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19724	ACTIVE	N	N105-00-4/202/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				Plastic cables. Metal brackets . Concrete slab to horizontal beam. Dust. Cement on mesh above false ceiling				YES	
10114	ACTIVE	N	N105-00-4/203	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19317	ACTIVE	N	N105-00-4/203	Passage - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10115	ACTIVE	N	N105-00-4/204	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19877	ACTIVE	N	N105-00-4/204/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Tottenham Court Road Stn	Void	Asbestos	Sampled – Not Detected				Concrete from void NADIS - above false ceiling				YES	
19725	ACTIVE	N	N105-00-4/204/FLR-01	Floor - 1 - Passage - Station Building - Tottenham Court Road Stn	Void	Asbestos	No Access: Presumed				Beneath false floor - manhole jammed /sealed shut					YES
19727	ACTIVE	N	N105-00-4/205	Overbridge - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	No Access: Presumed				Overbridge - Bitumen to tunnel ring, deep level - unable to sample					
19669	ACTIVE	N	N105-00-4/205/CLG-01	Ceiling: Suspended - 1 - Overbridge - Station building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete screed throughout. Plaster screed above false ceiling				YES	
19726	ACTIVE	N	N105-00-4/205/CLG-02	Ceiling: Solid - 2 - Overbridge - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete screed throughout. Plaster screed above false ceiling				YES	
19318	ACTIVE	N	N105-00-4/205/CLG-03	Ceiling: Solid - 3 - Overbridge - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete screed throughout. Plaster screed above false ceiling				YES	
19779	ACTIVE	N	N105-00-4/206	Overbridge - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	No Access: Presumed				Overbridge - Bitumen to tunnel ring, deep level - unable to sample					
19728	ACTIVE	N	N105-00-4/206/CLG-01	Ceiling: Suspended - 1 - Overbridge - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete screed throughout. Plaster screed above false ceiling				YES	
19729	ACTIVE	N	N105-00-4/206/CLG-02	Ceiling: Solid - 2 - Overbridge - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete screed throughout. Plaster screed above false ceiling				YES	
19730	ACTIVE	N	N105-00-4/206/CLG-03	Ceiling: Solid - 3 - Overbridge - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete screed throughout. Plaster screed above false ceiling				YES	



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10116	ACTIVE	N	N105-00-4/207	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19781	ACTIVE	N	N105-00-4/207	Passage - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				Bitumen Ducts		11			
19780	ACTIVE	N	N105-00-4/207	Passage - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boarding RHS replacing frieze panel					
19803	ACTIVE	N	N105-00-4/207/ FLR-01	Floor - 1 - Passage - Station Building - Tottenham Court Road Stn	Cable Ducts: Cement	Asbestos	Known				Cement Cable ducts manhole nearest to stairs 4/604 (base of stairs) beneath floor		3			Y
10117	ACTIVE	N	N105-00-4/209	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10118	ACTIVE	N	N105-00-4/211	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19783	ACTIVE	N	N105-00-4/211	Passage - Station Building - Tottenham Court Road Stn	Mastic	Asbestos	Surveyed – Not Detected				Mastic to ductwork flanges to ceiling throughout Corridor and Lobby in station entrance, 4/211 & 4/772					
19782	ACTIVE	N	N105-00-4/211	Passage - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux paneling Above doors 4/083 in passage 4/211, Wooden surround - Above doors 4/772 in passage 4/211,					
19373	ACTIVE	N	N105-00-4/211/ FLR-01	Floor - 1 - Passage - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				Manhole - Bitumen cable ducts - Non asbestos near 4/083 (plastic cables within)		39			YES
10119	ACTIVE	N	N105-00-4/212	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19784	ACTIVE	N	N105-00-4/212/ FLR-01	Floor - 1 - Passage - Station Building - Tottenham Court Road Stn	Cable Ducts: Cement	Asbestos	Known				Cement Duct (Below floor hatch no 8)					
42337	ACTIVE	N	N105-00-4/212/ FLR-01	Floor - 1 - Passage - Station Building - Tottenham Court Road Stn	Cable Ducts: Cement	Asbestos	Known				Cement cable ducts (2x4Lm) to floor (within concrete slab)		2	R506751	N	N
42336	ACTIVE	N	N105-00-4/212/ FLR-01	Floor - 1 - Passage - Station Building - Tottenham Court Road Stn	Cable Ducts: Cement	Asbestos	Known				Cement cable ducts (2x3Lm) to floor (within concrete slab)		2	R506751	N	N
19785	ACTIVE	N	N105-00-4/212/ FLR-01	Floor - 1 - Passage - Station Building - Tottenham Court Road Stn	Cable: Wrap	Asbestos	Strongly Presumed				Braided cables in cable hatch manhole					
10120	ACTIVE	N	N105-00-4/213	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19374	ACTIVE	N	N105-00-4/213/FLR-01	Floor - 1 - Passage - Station Building - Tottenham Court Road Stn	Void	Asbestos	No Access: Presumed				No access to floor hatches - Corridor bricked up at both ends					YES
19786	ACTIVE	N	N105-00-4/213/FLR-01	Floor - 1 - Passage - Station Building - Tottenham Court Road Stn	Cable Ducts: Bitumen	Asbestos	Surveyed - Not Detected				Bitumen Ducts below floor hatch		18			
10121	ACTIVE	N	N105-00-4/214	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19423	ACTIVE	N	N105-00-4/214/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed - Not Detected				Tunnel Rings beneath Metal Panels				YES	
19787	ACTIVE	N	N105-00-4/214/FLR-01	Floor - 1 - Passage - Station Building - Tottenham Court Road Stn	Cable Ducts: Bitumen	Asbestos	Surveyed - Not Detected				Manhole 1 - 12+ Bitumen Cable Ducts - to Manhole by door 4/751. 4x Bitumen cable ducts - manhole in corner (inner side ) near station supervisor's office, - Non asbestos (plastic cables within)					
19788	ACTIVE	N	N105-00-4/214/FLR-01	Floor - 1 - Passage - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed - Not Detected				Manhole 5 - 4x Bitumen cable ducts - Manhole in corner (outer side) near escalator 6 - Non asbestos					
19879	ACTIVE	N	N105-00-4/214/FLR-01	Floor - 1 - Passage - Station Building - Tottenham Court Road Stn	Cable Duct: Other	Asbestos	No Access: Presumed				Manhole 1 - other ducts may be present behind concrete / cement panels (12+ Bitumen cable ducts - to manhole by door 4/751 NAD)					
10122	ACTIVE	N	N105-00-4/215	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19789	ACTIVE	N	N105-00-4/215/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed - Not Detected				Above Cable Trays				YES	
10123	ACTIVE	N	N105-00-4/236	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19791	ACTIVE	N	N105-00-4/236	Passage - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed - Not Detected				Walls - Durasteel non asbestos					
19790	ACTIVE	N	N105-00-4/236	Passage - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Presumed				Walls - Concrete - Caulking behind presumed					
19792	ACTIVE	N	N105-00-4/236/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Strongly Presumed				Caulking above Concrete ceiling				YES	
19793	ACTIVE	N	N105-00-4/236/CLG-02	Ceiling: Solid - 2 - Passage - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Strongly Presumed				Caulking above Concrete ceiling				YES	
19375	ACTIVE	N	N105-00-4/236/FLR-01	Floor - 1 - Passage - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Strongly Presumed				Caulking beneath Concrete floor					YES



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19303	ACTIVE	N	N105-00-4/236/FLR-02	Floor - 2 - Passage - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Strongly Presumed				Caulking beneath Concrete floor					YES
10124	ACTIVE	N	N105-00-4/237	Lobby - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19376	ACTIVE	N	N105-00-4/237	Lobby - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10125	ACTIVE	N	N105-00-4/238	Lobby - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19794	ACTIVE	N	N105-00-4/238	Lobby - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10126	ACTIVE	N	N105-00-4/239	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19795	ACTIVE	N	N105-00-4/239	Passage - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panel to cap off duct (Fibreglass Duct Lagging to main passage)					
19796	ACTIVE	N	N105-00-4/239	Passage - Station Building - Tottenham Court Road Stn	Mastic	Asbestos	Surveyed – Not Detected				Mastic to Ductwork NAD					
10127	ACTIVE	N	N105-00-4/240	Lobby - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19377	ACTIVE	N	N105-00-4/240	Lobby - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10128	ACTIVE	N	N105-00-4/241	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19797	ACTIVE	N	N105-00-4/241	Passage - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10129	ACTIVE	N	N105-00-4/316	Locker Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19798	ACTIVE	N	N105-00-4/316	Locker Room - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10130	ACTIVE	N	N105-00-4/317	Locker Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19378	ACTIVE	N	N105-00-4/317	Locker Room - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10131	ACTIVE	N	N105-00-4/331	Mess Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19848	ACTIVE	N	N105-00-4/331	Mess Room - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux paneling above door 4/751					
19434	ACTIVE	N	N105-00-4/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, plastic cable, air con above metal tiles				YES	
19799	ACTIVE	N	N105-00-4/331/FLR-01	Floor - 1 - Mess Room - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, plastic cables, CMS, fire alarm beneath computer tiles - nylon					YES
19800	ACTIVE	N	N105-00-4/331/WAL-001	Wall: Internal - 1 - Mess Room - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boxing, horizontal: low level					
19847	ACTIVE	N	N105-00-4/331/WAL-002	Wall: Internal - 2 - Mess Room - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Up to stairs - Supalux boxing, horizontal: low level					
10132	ACTIVE	N	N105-00-4/332	Office - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19849	ACTIVE	N	N105-00-4/332/WAL-002	Wall: Internal - 2 - Locker Room - Station Building - Tottenham Court Road Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - Insulation Board Foam					
19850	ACTIVE	N	N105-00-4/332/WAL-002	Wall: Internal - 2 - Locker Room - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				High Level Supalux panel					
10133	ACTIVE	N	N105-00-4/401	Disused Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19851	ACTIVE	N	N105-00-4/401	Disused Room - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10134	ACTIVE	N	N105-00-4/406	SVC - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19852	ACTIVE	N	N105-00-4/406	SVC - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10135	ACTIVE	N	N105-00-4/407	Store - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19435	ACTIVE	N	N105-00-4/407	Store - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10136	ACTIVE	N	N105-00-4/408	Store - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19853	ACTIVE	N	N105-00-4/408	Store - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10137	ACTIVE	N	N105-00-4/409	Mess Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19854	ACTIVE	N	N105-00-4/409	Mess Room - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10138	ACTIVE	N	N105-00-4/411	Store - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19677	ACTIVE	N	N105-00-4/411	Store - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boxing to air con motor					
10139	ACTIVE	N	N105-00-4/412	Switch Cupboard - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19881	ACTIVE	N	N105-00-4/412	Switch Cupboard - Station Building - Tottenham Court Road Stn	Isolator Switches	Asbestos	Surveyed – Not Detected				All asbestos insulation materials removed		5			
19855	ACTIVE	N	N105-00-4/412	Switch Cupboard - Station Building - Tottenham Court Road Stn	Isolator Switches	Asbestos	Known				Unable to remove from 1no Switch Box Other cfs have acms removed label acm free No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
19436	ACTIVE	N	N105-00-4/412	Switch Cupboard - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel above door					
10140	ACTIVE	N	N105-00-4/416	Toilet: Male - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19856	ACTIVE	N	N105-00-4/416	Toilet: Male - Station Building - Tottenham Court Road Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - Insulation Board Foam					
10141	ACTIVE	N	N105-00-4/417	Toilet: Female - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19857	ACTIVE	N	N105-00-4/417	Toilet: Female - Station Building - Tottenham Court Road Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - Insulation Board Foam					
10142	ACTIVE	N	N105-00-4/418	Shower Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19437	ACTIVE	N	N105-00-4/418	Shower Room - Station Building - Tottenham Court Road Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - Insulation Board Foam					
10143	ACTIVE	N	N105-00-4/419	Store - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19859	ACTIVE	N	N105-00-4/419/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				No Asbestos Visible				YES	
19858	ACTIVE	N	N105-00-4/419/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
10144	ACTIVE	N	N105-00-4/576	Stairs: Linear - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19860	ACTIVE	N	N105-00-4/576	Stairs: Linear - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels					
10145	ACTIVE	N	N105-00-4/601	Stairs: Linear - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19678	ACTIVE	N	N105-00-4/601	Stairs: Linear - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10146	ACTIVE	N	N105-00-4/602	Stairs: Linear - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19438	ACTIVE	N	N105-00-4/602	Stairs: Linear - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10147	ACTIVE	N	N105-00-4/603	Stairs: Linear - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19861	ACTIVE	N	N105-00-4/603	Stairs: Linear - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10148	ACTIVE	N	N105-00-4/604	Stairs: Linear - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Surveyed – Asbestos Known									
19862	ACTIVE	N	N105-00-4/604	Stairs: Linear - Station Building - Tottenham Court Road Stn	Cable Ducts: Cement	Asbestos	Surveyed – Not Detected				Cement ducting, 7m, running under steps to 4/604 - 4/091	7			N	
10149	ACTIVE	N	N105-00-4/605	Stairs: Linear - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19439	ACTIVE	N	N105-00-4/605	Stairs: Linear - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10150	ACTIVE	N	N105-00-4/606	Stairs: Linear - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19863	ACTIVE	N	N105-00-4/606	Stairs: Linear - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10151	ACTIVE	N	N105-00-4/607	Stairs: Linear - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19864	ACTIVE	N	N105-00-4/607	Stairs: Linear - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
42492	ACTIVE	N	N105-00-4/607	Stairs: Linear - Station Building - Tottenham Court Road Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Bitumen cable ducts, within concrete slab to bottom of stairs Note - these appear to run from Northbound Platform 3 Northern Line (from invert) into stairs area and upstairs.			R505876	N	N
10152	ACTIVE	N	N105-00-4/608	Stairs: Linear - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19865	ACTIVE	N	N105-00-4/608	Stairs: Linear - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10153	ACTIVE	N	N105-00-4/609	Stairs: Linear - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19304	ACTIVE	N	N105-00-4/609	Stairs: Linear - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10154	ACTIVE	N	N105-00-4/661	Switch Cupboard - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19440	ACTIVE	N	N105-00-4/661	Switch Cupboard - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boarding above door					
10155	ACTIVE	N	N105-00-4/662	Switch Cupboard - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19866	ACTIVE	N	N105-00-4/662	Switch Cupboard - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boarding					
10156	ACTIVE	N	N105-00-4/663	Switch Cupboard - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19867	ACTIVE	N	N105-00-4/663	Switch Cupboard - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boarding					
10157	ACTIVE	N	N105-00-4/664	Communications Equipment Cupboard - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19868	ACTIVE	N	N105-00-4/664	Communications Equipment Cupboard - Station Building - Tottenham Court Road Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10158	ACTIVE	N	N105-00-4/665	Communications Equipment Cupboard - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19805	ACTIVE	N	N105-00-4/665	Communications Equipment Cupboard - Station Building - Tottenham Court Road Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
10159	ACTIVE	N	N105-00-4/666	Switch Cupboard - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19441	ACTIVE	N	N105-00-4/666	Switch Cupboard - Station Building - Tottenham Court Road Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
10160	ACTIVE	N	N105-00-4/667	Communications Equipment Cupboard - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19869	ACTIVE	N	N105-00-4/667	Communications Equipment Cupboard - Station Building - Tottenham Court Road Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
10161	ACTIVE	N	N105-00-4/711	Relay Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19882	ACTIVE	N	N105-00-4/711	Relay Room - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Presumed				Walls - Concrete - Caulking behind presumed					
19442	ACTIVE	N	N105-00-4/711	Relay Room - Station Building - Tottenham Court Road Stn	Other Electrical Boxes	Asbestos	Presumed				1no Electrical Box W4, 3no Electrical Boxes W2, 1no Transformer Box W3 - Insulation within  No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		5			
19871	ACTIVE	N	N105-00-4/711	Relay Room - Station Building - Tottenham Court Road Stn	Other Boarding	Asbestos	Presumed				Paxoline Boarding - Various Areas					
19870	ACTIVE	N	N105-00-4/711/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Strongly Presumed				Caulking above Concrete ceiling				YES	
19679	INACTIVE	N	N105-00-4/711/FLR-01	Floor - 1 - Relay Room - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Strongly Presumed				Caulking above Concrete ceiling				YES	
19807	ACTIVE	N	N105-00-4/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Tottenham Court Road Stn	Other Boarding	Asbestos	Presumed				Paxoline Boarding - Various Areas		3			
19546	ACTIVE	N	N105-00-4/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Tottenham Court Road Stn	Other Electrical Boxes	Asbestos	Presumed				Electrical box - Insulation within  No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		3			



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19496	ACTIVE	N	N105-00-4/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
10162	ACTIVE	N	N105-00-4/731	CER - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19922	ACTIVE	N	N105-00-4/731/FLR-01	Floor - 1 - CER - Station Building - Tottenham Court Road Stn	Vinyl tiles	Asbestos	Surveyed - Not Detected				Marley tiles on solid floor 15m <sup>2</sup>					
10163	ACTIVE	N	N105-00-4/732	CER - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19923	ACTIVE	N	N105-00-4/732/FLR-01	Floor - 1 - CER - Station Building - Tottenham Court Road Stn	Vinyl tiles	Asbestos	Surveyed - Not Detected				Marley tiles on solid floor 20m					
10164	ACTIVE	N	N105-00-4/733	CER - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19925	ACTIVE	N	N105-00-4/733	CER - Station Building - Tottenham Court Road Stn	Isolator Switches	Asbestos	Surveyed - Not Detected				All asbestos insulation materials removed		4			
19943	ACTIVE	N	N105-00-4/733	CER - Station Building - Tottenham Court Road Stn	Isolator Switches	Asbestos	Surveyed - Not Detected				All asbestos insulation materials removed		4			
19924	ACTIVE	N	N105-00-4/733/FLR-01	Floor - 1 - CER - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed - Not Detected				No asbestos visible beneath computer flooring					YES
10165	ACTIVE	N	N105-00-4/746	SCR - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
10166	ACTIVE	N	N105-00-4/751	Station Control Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
41946	ACTIVE	N	N105-00-4/751	Station Control Room - Station Building - Tottenham Court Road Stn	Gasket :Pipework	Asbestos	Sampled - Not Detected				1 x Gasket to flange of A/C duct		1		N	N
41944	ACTIVE	N	N105-00-4/751	Station Control Room - Station Building - Tottenham Court Road Stn	Cable Duct: Other	Asbestos	Sampled - Not Detected				Approx 4 x Cable Ducts to riser 1		4		N	N
41945	ACTIVE	N	N105-00-4/751	Station Control Room - Station Building - Tottenham Court Road Stn	Debris: Other	Asbestos	Sampled - Not Detected				<1m <sup>2</sup> Debris to riser 2				N	N
19927	ACTIVE	N	N105-00-4/751/CLG-01	Ceiling: Solid - 1 - Station Control Room - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Surveyed - Not Detected				Concrete, plastic cable, air con, above false ceiling (limited access due to equipment and space) above metal tile				YES	



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19885	ACTIVE	N	N105-00-4/751/FLR-01	Floor - 1 - Station Control Room - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, plastic cable, CMS beneath computer tiles (nylon)					YES
19926	ACTIVE	N	N105-00-4/751/WAL-003	Wall: Internal - 3 - Station Control Room - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding					
19497	ACTIVE	N	N105-00-4/751/WAL-004	Wall: Internal - 4 - Station Control Room - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Boxing - supalux & wood					
10167	ACTIVE	N	N105-00-4/756	Stairs: Linear - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10168	ACTIVE	N	N105-00-4/771	Pump Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19928	ACTIVE	N	N105-00-4/771	Pump Room - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Ring Caulking					
10169	ACTIVE	N	N105-00-4/772	Lobby - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19930	ACTIVE	N	N105-00-4/772/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				Area accessed - no visible asbestos				YES	
19929	ACTIVE	N	N105-00-4/772/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux 6m <sup>2</sup> , to suspended ceiling					
10170	ACTIVE	N	N105-00-4/773	Equipment Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42654	ACTIVE	N	N105-00-4/773	Equipment Room - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Sampled – Not Detected				Braided cables – white, 4 units x 2 cables, within 4x30amp switch boxes to wall 4, equipment room 4/773 (floodgate)			R515576	N	N
19933	ACTIVE	N	N105-00-4/773	Equipment Room - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Known				Sheathed Wiring. Encapsulated where accessible by Econ ES3071 missing presumed 6x cfs to wall 1 photo DSC06427 & DSC06428					
42653	ACTIVE	N	N105-00-4/773	Equipment Room - Station Building - Tottenham Court Road Stn	Rope Gaskets	Asbestos	Sampled – Not Detected				Rope-gasket, 4 x 11lim units, to rear of 4x30amp switch boxes throughout – to wall 4, equipment room 4/773 (floodgate).			R515576	N	N
42655	INACTIVE	N	N105-00-4/773	Equipment Room - Station Building - Tottenham Court Road Stn	Isolator Switches	Asbestos	Room: Surveyed – Asbestos Known				Composite panel, 2 x ½m <sup>2</sup> , 2 x to either side of 30amp switch boxes to wall 4, equipment room 4/773 (floodgate)			R515576	N	N
42656	INACTIVE	N	N105-00-4/773	Equipment Room - Station Building - Tottenham Court Road Stn	Isolator Switches	Asbestos	Removed				Materials within red, x2, to wall 4 by door to track, equipment room 4/773 (floodgate). - REMOVED by Econ 22/11/2012			R515576	N	N



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19931	ACTIVE	N	N105-00-4/773/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Known				All walls - Tunnel Rings Caulking Amphibole. Encapsulated where accessible by Econ ES3071					
19932	ACTIVE	N	N105-00-4/773/WAL-001	Wall: Internal - 1 - Lobby - Station Building - Tottenham Court Road Stn	Boarding: Cement	Asbestos	Known				Composite boarding to wall 1, between 4th & 6th isolators & between 2nd and 3rd isolator Boarding - Chrysotile					
19498	ACTIVE	N	N105-00-4/773/WAL-001	Wall: Internal - 1 - Lobby - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Known				All walls - Tunnel Rings Caulking Amphibole. Encapsulated where accessible by Econ ES3071					
46501	ACTIVE	N	N105-00-4/773/WAL-001	Wall: Internal - 1 - Lobby - Station Building - Tottenham Court Road Stn	Isolator Switches	Asbestos	Presumed				6x Combination Fuse Switches to Wall 1. Presumed asbestos insulating materials within.		6			
10171	ACTIVE	N	N105-00-4/774	Fan Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19499	ACTIVE	N	N105-00-4/774/CLG-01	Ceiling: Solid - 1 - Fan Room - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Strongly Presumed				Above concrete ceiling					
19683	ACTIVE	N	N105-00-4/774/FLR-01	Floor - 1 - Fan Room - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking beneath floor					YES
19934	ACTIVE	N	N105-00-4/774/WAL-001	Wall: Internal - 1 - Fan Room - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Presumed				Tunnel Ring Caulking behind Concrete and Supalux Panel					
10172	ACTIVE	N	N105-00-4/775	Pump Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
43432	ACTIVE	N	N105-00-4/775	Pump Room - Station Building - Tottenham Court Road Stn	Gasket :Pipework	Asbestos	Known				Gaskets to flanges on pump equipment situated on floor				N	N
19935	INACTIVE	N	N105-00-4/775	Pump Room - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
10173	ACTIVE	N	N105-00-4/776	Fan Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19937	ACTIVE	N	N105-00-4/776	Fan Room - Station Building - Tottenham Court Road Stn	Rope Gaskets	Asbestos	Known				Rope Gasket throughout to fan unit flanges					
19936	ACTIVE	N	N105-00-4/776	Fan Room - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux boxing throughout to small air conditioner duct works by stairs/ladder -					
10174	ACTIVE	N	N105-00-4/786	Service Riser - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19938	ACTIVE	N	N105-00-4/786	Service Riser - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19939	ACTIVE	N	N105-00-4/791	Vent Shaft - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
19500	ACTIVE	N	N105-00-4/792	Vent Shaft - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
19940	ACTIVE	N	N105-00-4/793	Vent Shaft - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Concrete. Supalux panel above switch room 4/663					
19941	ACTIVE	N	N105-00-4/793	Vent Shaft - Station Building - Tottenham Court Road Stn	Mastic	Asbestos	Known				Mastic to ductwork					
19501	ACTIVE	N	N105-00-4/795	Vent Shaft - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
25901	ACTIVE	N	N105-00-4/796	Vent Shaft - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux debris (<1m2) to top of ventilation control panel by stairs and to floor.				N	N
19942	ACTIVE	N	N105-00-4/796	Vent Shaft - Station Building - Tottenham Court Road Stn	Rope Gaskets	Asbestos	Known				Gasket to ventilation machinery					
19944	ACTIVE	N	N105-00-4/796	Vent Shaft - Station Building - Tottenham Court Road Stn	Isolator Switches	Asbestos	Known				Insulation within 1 x Switch Boxes No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
19502	ACTIVE	N	N105-00-4/797	Vent Shaft - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10175	ACTIVE	N	N105-00-4/901	Disused Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19509	ACTIVE	N	N105-00-4/901	Disused Room - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Known				Tunnel Rings - Caulking - Amphibole. Encapsulated by Econ ES3071					
19989	ACTIVE	N	N105-00-4/901/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Known				Tunnel Rings - Caulking - Amphibole. Encapsulated by Econ ES3071					
10176	ACTIVE	N	N105-00-4/902	Pump Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19990	ACTIVE	N	N105-00-4/902	Pump Room - Station Building - Tottenham Court Road Stn	Isolator Switches	Asbestos	Known				Insulation within Switch Boxes Missing presumed 2x CFS to wall photo DSC06409 No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
10177	ACTIVE	N	N105-00-4/903	Switch Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19991	ACTIVE	N	N105-00-4/903	Switch Room - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10178	ACTIVE	N	N105-00-4/904	Switch Cupboard - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19510	ACTIVE	N	N105-00-4/904	Switch Cupboard - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10179	ACTIVE	N	N105-00-4/951	Mess Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19992	ACTIVE	N	N105-00-4/951	Mess Room - Station Building - Tottenham Court Road Stn	LUL Heaters	Asbestos	No Access: Presumed				Heater - Insulation Foam Board					
19424	ACTIVE	N	N105-00-4/951	Mess Room - Station Building - Tottenham Court Road Stn	Mastic	Asbestos	Known				Mastic to ductwork					
10180	ACTIVE	N	N105-00-4/953	CER - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19993	ACTIVE	N	N105-00-4/953	CER - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Strongly Presumed				Caulking beneath Tiles, Concrete - Walls					YES
19545	ACTIVE	N	N105-00-4/953/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Strongly Presumed				Caulking above Tiles, Concrete - Walls					YES
19886	ACTIVE	N	N105-00-4/953/FLR-01	Floor - 1 - CER - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Known				Caulking beneath Tiles					YES
10181	ACTIVE	N	N105-00-4/971	CER - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19994	ACTIVE	N	N105-00-4/971	CER - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10182	ACTIVE	N	N105-00-5/201	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19511	ACTIVE	N	N105-00-5/201	Passage - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10183	ACTIVE	N	N105-00-5/202	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19995	ACTIVE	N	N105-00-5/202/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Tottenham Court Road Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				YES	



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10184	ACTIVE	N	N105-00-5/203	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19512	ACTIVE	N	N105-00-5/203/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Tottenham Court Road Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				YES	
10185	ACTIVE	N	N105-00-5/204	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19809	ACTIVE	N	N105-00-5/204	Passage - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panel high level, above bottom of stairs					
19996	ACTIVE	N	N105-00-5/204/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Tottenham Court Road Stn	Void	Asbestos	No Access: Presumed				Above false ceiling				YES	
10186	ACTIVE	N	N105-00-5/205	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42155	ACTIVE	N	N105-00-5/205	Passage - Station Building - Tottenham Court Road Stn	Cable Duct: Other	Asbestos	Removed				Asbestos Duct removal from stairs - breakout of area 12m x 2m x 100mm deep in area					
10187	ACTIVE	N	N105-00-5/261	Platform 1 - Westbound Local - Central Line - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19998	ACTIVE	N	N105-00-5/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				Platform 1 Invert - All bitumen cable ducts have been sampled					YES
19997	ACTIVE	N	N105-00-5/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				Bitumen cable ducts track side wall					
10188	ACTIVE	N	N105-00-5/262	Platform 2 - Eastbound Local - Central Line - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19513	ACTIVE	N	N105-00-5/262	Platform 2 - Eastbound Local - Central Line - Station Building - Tottenham Court Road Stn	Cable Ducts: Cement	Asbestos	Known				4 x cement cable ducts - to top of bank of cable ducts nearest to tunnel		4			
19999	ACTIVE	N	N105-00-5/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				6x Bitumen cable ducts - Trackside wall (concrete block furthese from tunnel)					
20001	ACTIVE	N	N105-00-5/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Tottenham Court Road Stn	Cable Ducts: Cement	Asbestos	Strongly Presumed				Platform 2 Invert - Asbestos duct below 5/661 No access within invert 2020 re-inspection - confined space team required.					YES
20000	ACTIVE	N	N105-00-5/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				Platform 2 Invert - 10x Bitumen Ducts at Departure End of Invert					YES



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10189	ACTIVE	N	N105-00-5/396	SVC - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20002	ACTIVE	N	N105-00-5/396	SVC - Station Building - Tottenham Court Road Stn	Gasket :Pipework	Asbestos	Presumed				Platform 2 Invert - No Gastets visible to Pipework to Fire Hydrants No access within invert 2020 re-inspection - confined space team required.					
10190	ACTIVE	N	N105-00-5/661	Switch Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20005	ACTIVE	N	N105-00-5/661	Switch Room - Station Building - Tottenham Court Road Stn	Cable Duct: Other	Asbestos	Known				Cable sleeve to floor					
20003	ACTIVE	N	N105-00-5/661/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				Above false ceiling				YES	
19514	ACTIVE	N	N105-00-5/661/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux, Concrete					
20004	ACTIVE	N	N105-00-5/661/CLG-02	Ceiling: Suspended - 2 - Switch Room - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				Above false ceiling				YES	
19731	ACTIVE	N	N105-00-5/661/CLG-02	Ceiling: Suspended - 2 - Switch Room - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux, Concrete					
10191	ACTIVE	N	N105-00-5/662	Switch Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20006	ACTIVE	N	N105-00-5/662/DOR-01	Door - 1 - Switch Room - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels around edges of door					
10192	ACTIVE	N	N105-00-5/663	Switch Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20007	ACTIVE	N	N105-00-5/663	Switch Room - Station Building - Tottenham Court Road Stn	Isolator Switches	Asbestos	Surveyed – Not Detected				All asbestos insulation materials removed		4			
20221	ACTIVE	N	N105-00-5/663/DOR-01	Door - 1 - Switch Room - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels above door (firebreak)					
10193	ACTIVE	N	N105-00-5/664	Switch Cupboard - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10194	ACTIVE	N	N105-00-5/670	Switch Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20008	ACTIVE	N	N105-00-5/670/DOR-01	Door - 1 - Switch Room - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding around edges of door					
10195	ACTIVE	N	N105-00-5/711	Relay Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20010	ACTIVE	N	N105-00-5/711	Relay Room - Station Building - Tottenham Court Road Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Durasteel Boarding					
20009	ACTIVE	N	N105-00-5/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boards					
10196	ACTIVE	N	N105-00-5/712	Relay Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20054	ACTIVE	N	N105-00-5/712/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel to RHS W4 Door					
10197	ACTIVE	N	N105-00-5/761	Service Riser - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20055	ACTIVE	N	N105-00-5/761/DOR-01	Door - 1 - Equipment Room - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels above doors					
20056	ACTIVE	N	N105-00-5/761/DOR-02	Door - 2 - Equipment Room - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panels above doors					
10198	ACTIVE	N	N105-00-5/901	Disused Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19217	ACTIVE	N	N105-00-5/901	Disused Room - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10199	ACTIVE	N	N105-00-6/161	LMC - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20057	ACTIVE	N	N105-00-6/161	LMC - Station Building - Tottenham Court Road Stn	Bitumen	Asbestos	Presumed				Ducts - LHS bitumen based. If ducts are to be utilised, HMU to advise  No access 2020 re-inspection as L&E permit required		3			
20058	ACTIVE	N	N105-00-6/161	LMC - Station Building - Tottenham Court Road Stn	Cable Ducts: Bitumen	Asbestos	Presumed				Ducts RHS bitumen based (Visible)  No access 2020 re-inspection as L&E permit required		2			
10200	ACTIVE	N	N105-00-6/201	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20059	ACTIVE	N	N105-00-6/201	Passage - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10201	ACTIVE	N	N105-00-6/202	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19888	ACTIVE	N	N105-00-6/202	Passage - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10202	ACTIVE	N	N105-00-6/203	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19218	ACTIVE	N	N105-00-6/203/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				Solid above VE Panels				YES	
10203	ACTIVE	N	N105-00-6/204	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20060	ACTIVE	N	N105-00-6/204	Passage - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux fire breaks adjacent to both platforms					
20061	ACTIVE	N	N105-00-6/204/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				Solid above VE Panels				YES	
10204	ACTIVE	N	N105-00-6/205	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20062	ACTIVE	N	N105-00-6/205	Passage - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux fire breaks adjacent to both platforms					
10205	ACTIVE	N	N105-00-6/206	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20063	ACTIVE	N	N105-00-6/206/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Tottenham Court Road Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Fibrous Board nr 6/396 & 6/761 above metal ceiling				YES	
10206	ACTIVE	N	N105-00-6/207	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19219	ACTIVE	N	N105-00-6/207	Passage - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux fire breaks adjacent to both platforms					
20064	ACTIVE	N	N105-00-6/207/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				Above metal ceiling				YES	
10207	ACTIVE	N	N105-00-6/208	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20065	ACTIVE	N	N105-00-6/208	Passage - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10208	ACTIVE	N	N105-00-6/209	Passage - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20066	ACTIVE	N	N105-00-6/209	Passage - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10209	ACTIVE	N	N105-00-6/263	Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
41951	ACTIVE	N	N105-00-6/263	Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				3 x Bitumen Cable Ducts - RHS to headwall of arrival end		3		N	N
41953	ACTIVE	N	N105-00-6/263	Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				2 x Bitumen cable ducts - LHS to trackside wall of arrival end		2		N	N
20067	ACTIVE	N	N105-00-6/263	Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Presumed				Braided Cable - used to tie up other cables throughout invert  No access within invert 2020 re-inspection - confined space team required.					
41952	ACTIVE	N	N105-00-6/263	Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn	Cable Ducts: Cement	Asbestos	Known				2 x Cement Cable Ducts - RHS to headwall at arrival end		2		N	N
20068	ACTIVE	N	N105-00-6/263	Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn	Cable Duct: Other	Asbestos	Presumed				Ducts entering invert - arrivals end. If ducts are to be utilised, HMU to advise					
25753	ACTIVE	N	N105-00-6/263	Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Platform 3 Invert - 16 x Ducts  No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		16			
25755	ACTIVE	N	N105-00-6/263	Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn	Cable Duct: Other	Asbestos	Presumed				Platform 3 Invert - 4 x visible ducts  No access within invert 2020 re-inspection - confined space team required.					
25757	ACTIVE	N	N105-00-6/263	Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Known				Yellow braided cable to head wall					
25758	ACTIVE	N	N105-00-6/263	Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn	Westing house Boxes	Asbestos	Presumed				Platform Invert - materials within Westinghouse box to platform wall  No access within invert 2020 re-inspection - confined space team required.					



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25759	ACTIVE	N	N105-00-6/263	Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn		Asbestos	Sampled – Not Detected				Platform Invert - Ducts to wall at end of invert. Gasket to platform wall of invert. Cable duct to trackside wall. Cable duct to platform wall. Caulking to tunnel ring flanges to invert. Cable Ducts throughout to trackside - Asbestos not detected in samples					
25751	ACTIVE	N	N105-00-6/263	Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Known				Platform Invert - Large green encapsulated braided cable along trackside  No access within invert 2020 re-inspection - confined space team required.					
25756	ACTIVE	N	N105-00-6/263	Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Known				Platform Invert - White small braided cable along trackside to Westinghouse electrical box  No access within invert 2020 re-inspection - confined space team required.					
41954	ACTIVE	N	N105-00-6/263	Platform 3 - Northbound Local - Northern Line - Station Building - Tottenham Court Road Stn	Cable Ducts: Bitumen	Asbestos	Surveyed – Not Detected				2 x Bitumen Cable Ducts - LHS to trackside wall at arrival end		2		N	N
19221	ACTIVE	N	N105-00-6/263/FLR-01	Floor - 1 - Platform 3 - Station Building - Tottenham Court Road Stn	Gasket :Pipework	Asbestos	Strongly Presumed				Platform 3 Invert - access to the pipe gaskets was not possible and they must be strongly presumed to contain Chrysotile asbestos.  No access within invert 2020 re-inspection - confined space team required.					YES
20069	ACTIVE	N	N105-00-6/263/FLR-01	Floor - 1 - Platform 3 - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Known				Platform 3 Invert - Various braided cables either end of the invert. Encapsulated by Econ ES3071  No access within invert 2020 re-inspection - confined space team required.					YES
10210	ACTIVE	N	N105-00-6/264	Platform 4 - Southbound Local - Northern Line - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25787	ACTIVE	N	N105-00-6/264	Platform 4 - Southbound Local - Northern Line - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Known				Platform 4 Southbound Invert - Braided cables (>10 no.) to cable run, coming in and going out of invert into Relay Room and Track.  No access within invert 2020 re-inspection - confined space team required.		10			
25792	ACTIVE	N	N105-00-6/264	Platform 4 - Southbound Local - Northern Line - Station Building - Tottenham Court Road Stn	Cable Duct: Other	Asbestos	Presumed				Platform 4 Southbound Invert - 10-core box (1 no.), to wall with 2 no. braided cables within box.  No access within invert 2020 re-inspection - confined space team required.		2			



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41949	ACTIVE	N	N105-00-6/264	Platform 4 - Southbound Local - Northern Line - Station Building - Tottenham Court Road Stn	Cable Duct: Other	Asbestos	Presumed				1 x Cable Duct behind panel to headwall - limited access.		1		N	N
20070	ACTIVE	N	N105-00-6/264	Platform 4 - Southbound Local - Northern Line - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Strongly Presumed				50mm cables nr 6/208		1			
25789	ACTIVE	N	N105-00-6/264	Platform 4 - Southbound Local - Northern Line - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Presumed				Platform 4 Southbound Invert - 1 x 10-core box to wall with 2 no. braided cables within box. No access within invert 2020 re-inspection - confined space team required.					
20071	ACTIVE	N	N105-00-6/264	Platform 4 - Southbound Local - Northern Line - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Strongly Presumed				50mm cable nr 6/712 going to track		1			
25742	ACTIVE	N	N105-00-6/264	Platform 4 - Southbound Local - Northern Line - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Presumed				Platform 4 Invert - 1x 10 Core box with 2 braided cables within box No access within invert 2020 re-inspection - confined space team required.		1			
19734	ACTIVE	N	N105-00-6/264	Platform 4 - Southbound Local - Northern Line - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Strongly Presumed				10mm cables nr 6/208		1			
41947	ACTIVE	N	N105-00-6/264	Platform 4 - Southbound Local - Northern Line - Station Building - Tottenham Court Road Stn	Cable Ducts: Bitumen	Asbestos	Sampled - Not Detected				3 x Bitumen Cable Ducts - RHS to headwall of departure end		3		N	N
25791	ACTIVE	N	N105-00-6/264	Platform 4 - Southbound Local - Northern Line - Station Building - Tottenham Court Road Stn	Other Electrical Boxes	Asbestos	Presumed				Platform 4 Southbound Invert - 1 x 10-core box to wall with 2 no. braided cables within box. No access within invert 2020 re-inspection - confined space team required.					
25786	ACTIVE	N	N105-00-6/264	Platform 4 - Southbound Local - Northern Line - Station Building - Tottenham Court Road Stn	Cable Duct: Other	Asbestos	Sampled - Not Detected				Platform 4 Invert - Cable ducts (>10 no.) to walls and ceiling.					
20072	ACTIVE	N	N105-00-6/264/FLR-01	Floor - 1 - Platform 4 - Station Building - Tottenham Court Road Stn	Cable Duct: Other	Asbestos	Surveyed - Not Detected				Platform 4 Invert - Cable ducts (>10 no.), to walls and ceiling.					YES
20073	ACTIVE	N	N105-00-6/264/FLR-01	Floor - 1 - Platform 4 - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Known				Various braided Cables near to route at arrivals and departure. Encapsulated by Econ ES3071 11 hangers. From floor up the first 5 do not have asbestos cables laying within. From 5 up there is a mismatch of asbestos cables. 2 x green and 1 x yellow. 30m into the invert small bore asbestos cabling has also been used as cable ties.					YES



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19889	INACTIVE	N	N105-00-6/264/FLR-01	Floor - 1 - Platform 4 - Station Building - Tottenham Court Road Stn	Cable Duct: Other	Asbestos	Surveyed – Not Detected				Platform 4 Invert - 1x Cable ducts - Invert departure end. If ducts are to be utilised, HMU to advise					YES
10211	ACTIVE	N	N105-00-6/371	CER - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20074	ACTIVE	N	N105-00-6/371/FLR-01	Floor - 1 - CER - Station Building - Tottenham Court Road Stn	Void	Asbestos	No Access: Presumed				Ducts into floor - Wall 2 and 3 no access due to heavy use of fire stop.					YES
20075	ACTIVE	N	N105-00-6/371/WAL-001	Wall: Internal - 1 - CER - Station Building - Tottenham Court Road Stn	Void	Asbestos	No Access: Presumed				Electrical box - No access, front shutter down					
19222	ACTIVE	N	N105-00-6/371/WAL-002	Wall: Internal - 2 - CER - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Not Found during Inspection				40mm Woven cables sleeve 1LM Room not present 2020 re-inspection - station upgrade / crossrail		2			
19735	ACTIVE	N	N105-00-6/371/WAL-002	Wall: Internal - 2 - CER - Station Building - Tottenham Court Road Stn	Other Electrical Boxes	Asbestos	Not Found during Inspection				Electrical box, suliminite within Room not present 2020 re-inspection - station upgrade / crossrail		1			
19230	ACTIVE	N	N105-00-6/371/WAL-003	Wall: Internal - 3 - CER - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Not Found during Inspection				40mm woven cable exit room into track Room not present 2020 re-inspection - station upgrade / crossrail					
19547	ACTIVE	N	N105-00-6/371/WAL-004	Wall: Internal - 4 - CER - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Not Found during Inspection				5mm Electric cables woven sheath - high level Room not present 2020 re-inspection - station upgrade / crossrail					
10212	ACTIVE	N	N105-00-6/381	Equipment Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20125	ACTIVE	N	N105-00-6/381	Equipment Room - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding & Panel above door					
10213	ACTIVE	N	N105-00-6/396	Disused Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20126	ACTIVE	N	N105-00-6/396	Disused Room - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10214	ACTIVE	N	N105-00-6/401	Store - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20127	ACTIVE	N	N105-00-6/401	Store - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board					



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20128	ACTIVE	N	N105-00-6/401/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Tottenham Court Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Board				YES	
19231	ACTIVE	N	N105-00-6/401/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board					
10215	ACTIVE	N	N105-00-6/481	Stretcher Cupboard - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20129	ACTIVE	N	N105-00-6/481	Stretcher Cupboard - Station Building - Tottenham Court Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10216	ACTIVE	N	N105-00-6/663	Switch Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20131	INACTIVE	N	N105-00-6/663	Switch Room - Station Building - Tottenham Court Road Stn	Isolator Switches	Asbestos	Removed				W3 - 1 x Switch Box - insulation within - Removed		1			
20130	ACTIVE	N	N105-00-6/663	Switch Room - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding & Panels by Door					
10217	ACTIVE	N	N105-00-6/672	Switch Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19232	ACTIVE	N	N105-00-6/672	Switch Room - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boarding around edges of door					
10218	ACTIVE	N	N105-00-6/673	Switch Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19738	ACTIVE	N	N105-00-6/673	Switch Room - Station Building - Tottenham Court Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boarding around edges of door					
10219	ACTIVE	N	N105-00-6/711	Relay Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25882	ACTIVE	N	N105-00-6/711	Relay Room - Station Building - Tottenham Court Road Stn	Westing house Boxes	Asbestos	Removed				2 x Large Westinghouse Boxes - left hand wall		2		N	N
25876	INACTIVE	N	N105-00-6/711	Relay Room - Station Building - Tottenham Court Road Stn	Other Electrical Boxes	Asbestos	Removed				1 x Capacitor Unit		1		N	N
25877	INACTIVE	N	N105-00-6/711	Relay Room - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Removed				Braided cables from Capacitor unit		2		N	N
25883	INACTIVE	N	N105-00-6/711	Relay Room - Station Building - Tottenham Court Road Stn	Other Electrical Boxes	Asbestos	Removed				10 Core Boxes		1		N	N
25879	INACTIVE	N	N105-00-6/711	Relay Room - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Removed				10 + Braided Cables from fuses		10		N	N



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
25780	ACTIVE	N	N105-00-6/711	Relay Room - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Removed				Braided cable within cabinet/box LHS away from door Date identified 08/09/2014					
25878	INACTIVE	N	N105-00-6/711	Relay Room - Station Building - Tottenham Court Road Stn		Asbestos	Removed				10 + Fuses		10		N	N
25884	INACTIVE	N	N105-00-6/711	Relay Room - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Removed				7 x Braided cables from fuse box		7		N	N
25779	INACTIVE	N	N105-00-6/711	Relay Room - Station Building - Tottenham Court Road Stn	Other Boarding	Asbestos	Removed				Melamine board, within cabinet/box LHS away from door.					
41942	ACTIVE	N	N105-00-6/711	Relay Room - Station Building - Tottenham Court Road Stn	Cable Duct: Other	Asbestos	Sampled – Not Detected				4 x 1m Cable Troughing / Ducting	1	4		N	
25885	INACTIVE	N	N105-00-6/711	Relay Room - Station Building - Tottenham Court Road Stn	Other Boarding	Asbestos	Removed				Fuses to Braided cables		10		N	N
25781	ACTIVE	N	N105-00-6/711	Relay Room - Station Building - Tottenham Court Road Stn	Cable Duct: Other	Asbestos	Not Found during Inspection				Ducts within cabinet/box LHS away from door.  Room not present 2020 re-inspection - station upgrade / crossrail					
42491	ACTIVE	N	N105-00-6/711/FLR-01	Floor - 1 - Relay Room - Station Building - Tottenham Court Road Stn	Cable Duct: Other	Asbestos	Not Found during Inspection				5 x cable ducts to floor descending into invert below Platform 3 northbound  Room not present 2020 re-inspection - station upgrade / crossrail			R481901	N	N
19811	ACTIVE	N	N105-00-6/711/FLR-01	Floor - 1 - Relay Room - Station Building - Tottenham Court Road Stn	Cable Ducts: Cement	Asbestos	Not Found during Inspection				Cable Ducts to Corner of Room W2&3; No Access Sealed;  Room not present 2020 re-inspection - station upgrade / crossrail					
20314	ACTIVE	N	N105-00-6/711/FLR-01	Floor - 1 - Relay Room - Station Building - Tottenham Court Road Stn	Cable Duct: Other	Asbestos	Not Found during Inspection				Large Cable Ducts by Wall 1 within Racking  Room not present 2020 re-inspection - station upgrade / crossrail		2			
20315	INACTIVE	N	N105-00-6/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tottenham Court Road Stn	Other Boarding	Asbestos	Removed				Arc Chutes to Fuses within Racking		53			
20317	INACTIVE	N	N105-00-6/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Removed				Woven Sheathed Cables within Racking; Approx 3no		3			
20313	INACTIVE	N	N105-00-6/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tottenham Court Road Stn	Other Electrical Boxes	Asbestos	Removed				Other Electrical Box - Insulation within		1			
20312	INACTIVE	N	N105-00-6/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tottenham Court Road Stn	Westing house Boxes	Asbestos	Removed				Westinghouse Box		1			



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20309	ACTIVE	N	N105-00-6/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Not Found during Inspection				Caulking within Tunnel Rings behind Render  Room not present 2020 re-inspection - station upgrade / crossrail					
20318	INACTIVE	N	N105-00-6/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Removed				Small Woven Cables running between Fuse Box from W1 accross W2 to Fuse Boxes on W3; Potentially only Cotton;					
20316	INACTIVE	N	N105-00-6/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tottenham Court Road Stn	PCBs	Polychlorinated biphenyl	Removed				Relay Boxes - PCBs within; Within Racking		6			
20134	INACTIVE	N	N105-00-6/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Tottenham Court Road Stn	Other Electrical Boxes	Asbestos	Removed				Electrical box H/L - Paxoline Boxing within - Removed		1			
20319	INACTIVE	N	N105-00-6/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Tottenham Court Road Stn	Other Electrical Boxes	Asbestos	Removed				600V Box (+2no Power Feed Cables see 19233)		1			
25776	ACTIVE	N	N105-00-6/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Removed				Braided cable to wall 2 going into floor duct.					
25777	ACTIVE	N	N105-00-6/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Tottenham Court Road Stn	Cable Duct: Other	Asbestos	Not Found during Inspection				Duct - corner of Wall 2 & 3. Date Identified 08/09/2014  Room not present 2020 re-inspection - station upgrade / crossrail					
19233	INACTIVE	N	N105-00-6/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Removed				2no 40mm woven cables from 600V Box (see 20319) - Encapsulated. 1no exits to Invert via Floor; 1no exits to Track W3;		2			
20133	INACTIVE	N	N105-00-6/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Removed				40mm Cable exits room into track - Removed					
20310	INACTIVE	N	N105-00-6/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn	Other Electrical Boxes	Asbestos	Removed				Rectifier Box - Insulation materials within					
25778	INACTIVE	N	N105-00-6/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn	Other Boarding	Asbestos	Removed				Melamine board to high level box					
20308	INACTIVE	N	N105-00-6/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Removed				Small Woven Cables running between Perspex Faced Electrical Fuse Boxes - Potentially only cotton;					
20311	INACTIVE	N	N105-00-6/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn	Other Electrical Boxes	Asbestos	Removed				Tencore Box		1			
20132	INACTIVE	N	N105-00-6/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Removed				5no Sheathed Cables. Encapsulated by Econ E53071		5			



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10220	ACTIVE	N	N105-00-6/712	Relay Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19891	ACTIVE	N	N105-00-6/712	Relay Room - Station Building - Tottenham Court Road Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel panel above door					
41751	ACTIVE	N	N105-00-6/712	Relay Room - Station Building - Tottenham Court Road Stn	Cable Duct: Other	Asbestos	Not Found during Inspection				Large Ducts within Racking Room not present 2020 re-inspection - station upgrade / crossrail				N	N
25899	ACTIVE	N	N105-00-6/712	Relay Room - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Removed				3 x Braided cables to LHS wall going to fuses		3		N	N
25890	INACTIVE	N	N105-00-6/712	Relay Room - Station Building - Tottenham Court Road Stn	Other Electrical Boxes	Asbestos	Removed				1 x FG D/B 17 box		1		N	N
25897	INACTIVE	N	N105-00-6/712	Relay Room - Station Building - Tottenham Court Road Stn	Other Electrical Boxes	Asbestos	Removed				1 x FG D/B 17 box		1		N	N
25895	INACTIVE	N	N105-00-6/712	Relay Room - Station Building - Tottenham Court Road Stn	Other Boarding	Asbestos	Removed				10 + Fuses next to Capacitor unit		10		N	N
25888	INACTIVE	N	N105-00-6/712	Relay Room - Station Building - Tottenham Court Road Stn	Other Boarding	Asbestos	Removed				10 + Fuses next to Capacitor unit		10		N	N
25773	INACTIVE	N	N105-00-6/712	Relay Room - Station Building - Tottenham Court Road Stn	Other Boarding	Asbestos	Removed				Melamine board, within box/ cabinet RHS next to door.					
25774	ACTIVE	N	N105-00-6/712	Relay Room - Station Building - Tottenham Court Road Stn	Cable Duct: Other	Asbestos	Not Found during Inspection				Ducts within cabinet/box next to door in relay room. Date Identified 08/09/2014 Room not present 2020 re-inspection - station upgrade / crossrail					
25892	ACTIVE	N	N105-00-6/712	Relay Room - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Removed				3 x Braided cables going to fuses		3		N	N
25889	ACTIVE	N	N105-00-6/712	Relay Room - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Removed				3 x Braided Cables to Capacitor Unit and Cable Duct Braided Cables and Capacitor removed		3		N	N
25898	INACTIVE	N	N105-00-6/712	Relay Room - Station Building - Tottenham Court Road Stn	Other Boarding	Asbestos	Removed				4 x Fuses		4		N	N
25771	INACTIVE	N	N105-00-6/712	Relay Room - Station Building - Tottenham Court Road Stn	Other Boarding	Asbestos	Removed				Melamine board, to box no. TT12913					
25772	ACTIVE	N	N105-00-6/712	Relay Room - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Removed				Braided cable within box/cabinet next to the door.					
25887	INACTIVE	N	N105-00-6/712	Relay Room - Station Building - Tottenham Court Road Stn	Other Electrical Boxes	Asbestos	Removed				1 x Capacitor Unit		1		N	N
25896	ACTIVE	N	N105-00-6/712	Relay Room - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Removed				3 x Braided cables		3		N	N



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19739	INACTIVE	N	N105-00-6/712	Relay Room - Station Building - Tottenham Court Road Stn	Other Electrical Boxes	Asbestos	Removed				Electric box - Paxoline within box		1			
25894	INACTIVE	N	N105-00-6/712	Relay Room - Station Building - Tottenham Court Road Stn	Other Electrical Boxes	Asbestos	Removed				1 x Capacitor Unit		1		N	N
25891	INACTIVE	N	N105-00-6/712	Relay Room - Station Building - Tottenham Court Road Stn	Other Boarding	Asbestos	Removed				4 x Fuses and braided cables (left hand wall)		4		N	N
20327	ACTIVE	N	N105-00-6/712/ FLR-01	Floor - 1 - Relay Room - Station Building - Tottenham Court Road Stn	Cable Duct: Other	Asbestos	Not Found during Inspection				Cable Ducts to Invert in Corner of Floor by Walls 1&2 - Sealed  Room not present 2020 re-inspection - station upgrade / crossrail					
20332	INACTIVE	N	N105-00-6/712/ FLR-01	Floor - 1 - Relay Room - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Removed				1no 10mm Cable Brown - Attached to Equipment on Racking by W3		1			
20138	INACTIVE	N	N105-00-6/712/ WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Removed				5mm woven sleeve cables - from high level perspex fronted fuse box, exits to floor.		2			
20322	INACTIVE	N	N105-00-6/712/ WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tottenham Court Road Stn	Other Electrical Boxes	Asbestos	Removed				Rectifier Box H/L; Insulation materials within;		1			
20323	INACTIVE	N	N105-00-6/712/ WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Tottenham Court Road Stn	Other Electrical Boxes	Asbestos	Removed				600V Box (+2no Power Feed Cables see 19280)		1			
20324	INACTIVE	N	N105-00-6/712/ WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Tottenham Court Road Stn	Other Electrical Boxes	Asbestos	Removed				Distribution Box - Insulation Materials within		1			
19280	INACTIVE	N	N105-00-6/712/ WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Removed				2no 40mm - from 600v Box exits to floor. Encapsulated.		2			
20320	INACTIVE	N	N105-00-6/712/ WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Removed				Cable Runs from Electrical Box W2 (19739) across to Racking on W3		1			
25770	INACTIVE	N	N105-00-6/712/ WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Removed				Braided Cable to wall 2 going to floor. Date Identified 08/09/2014					
20136	INACTIVE	N	N105-00-6/712/ WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn	Cable: Sheath	Asbestos	Removed				2no 15mm woven cable - 1no Yellow 1no Green from Equipment into Large Ducts within Racking  Cables removed		2			
20331	ACTIVE	N	N105-00-6/712/ WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn	Cable Duct: Other	Asbestos	Not Found during Inspection				Large Cable Ducts by Wall 3 within Racking  Room not present 2020 re-inspection - station upgrade / crossrail		2			



# Hazardous Material Asset Register - Summary



## N105-00 - Station Building - Tottenham Court Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20321	ACTIVE	N	N105-00-6/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn	Caulking	Asbestos	Not Found during Inspection				Tunnel Ring Caulking behind Plaster Room not present 2020 re-inspection - station upgrade / crossrail					
20137	INACTIVE	N	N105-00-6/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn	Other Boarding	Asbestos	Removed				Relay panels - Paxoline in various areas on panel - within Racking adjacent to Relay Boxes		7			
20325	INACTIVE	N	N105-00-6/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn	Other Electrical Boxes	Asbestos	Removed				Electrical Box - Insulation Materials within		1			
20328	INACTIVE	N	N105-00-6/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn	Other Boarding	Asbestos	Removed				Arc Chutes to Fuses within Racking					
20330	INACTIVE	N	N105-00-6/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Tottenham Court Road Stn	PCBs	Polychlorinated biphenyl	Removed				Relay Boxes - PCBs within; Within Racking		6			
10221	ACTIVE	N	N105-00-6/713	Relay Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
10222	ACTIVE	N	N105-00-6/761	Disused Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
10223	ACTIVE	N	N105-00-6/771	Equipment Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
10224	ACTIVE	N	N105-00-6/901	Disused Room - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
10225	ACTIVE	N	N105-00-A/081	Lobby - Station Building - Tottenham Court Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
20135	ACTIVE	N	N105-00-A/081	Lobby - Station Building - Tottenham Court Road Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Responsibility of UK Power networks					

## N125-00 - Station Building - Angel Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10843	ACTIVE	N	N125-00-1/001	Booking Hall - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18358	ACTIVE	N	N125-00-1/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	
16657	ACTIVE	N	N125-00-1/001/FLR-01	Floor - 1 - Booking Hall - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Beneath Rubber Tiles					YES



# Hazardous Material Asset Register - Summary



## N125-00 - Station Building - Angel Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
20026	ACTIVE	N	N125-00-1/001/FLR-01	Floor - 1 - Booking Hall - Station Building - Angel Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux					
16658	ACTIVE	N	N125-00-1/001/FLR-01	Floor - 1 - Booking Hall - Station Building - Angel Stn	Void	Asbestos	Surveyed - Not Detected				Breeze Block Walls; Fibreglass Lagged Pipes above Supalux					YES
10844	ACTIVE	N	N125-00-1/011	Ticket Office - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
10845	ACTIVE	N	N125-00-1/021	POM - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16661	ACTIVE	N	N125-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Angel Stn	Void	Asbestos	Surveyed - Not Detected				Breeze Block Walls; Fibreglass Lagged Pipes above Supalux				YES	
16660	ACTIVE	N	N125-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Angel Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux					
16659	ACTIVE	N	N125-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Beneath Rubber Tiles					YES
10846	ACTIVE	N	N125-00-1/031	Mess Room - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16662	ACTIVE	N	N125-00-1/031	Mess Room - Station Building - Angel Stn		Asbestos	Surveyed - Not Detected				Acoustic Panel below sink					
18359	ACTIVE	N	N125-00-1/031	Mess Room - Station Building - Angel Stn	LUL Heaters	Asbestos	Surveyed - Not Detected				2 x Heaters - Foam Insulation Board					
16664	ACTIVE	N	N125-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Angel Stn	Void	Asbestos	Surveyed - Not Detected				Solid Concrete Roof; Breeze Block Walls; Fibreglass Lagged Pipes above Supalux Ceiling				YES	
16663	ACTIVE	N	N125-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Angel Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux					
10847	ACTIVE	N	N125-00-1/036	Lobby - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16665	ACTIVE	N	N125-00-1/036/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Supalux Tiles				YES	
18360	ACTIVE	N	N125-00-1/036/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
10848	ACTIVE	N	N125-00-1/037	Toilet: Unisex - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19051	ACTIVE	N	N125-00-1/037/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Angel Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Supalux Tiles				YES	



# Hazardous Material Asset Register - Summary



## N125-00 - Station Building - Angel Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16666	ACTIVE	N	N125-00-1/037/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Angel Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
10849	ACTIVE	N	N125-00-1/071	Circulation Area - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16667	ACTIVE	N	N125-00-1/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	
10850	ACTIVE	N	N125-00-1/236	Lobby - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16670	ACTIVE	N	N125-00-1/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn	Void	Asbestos	Surveyed – Not Detected				Breeze Blocks above Supalux Ceiling				YES	
18361	ACTIVE	N	N125-00-1/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
16669	ACTIVE	N	N125-00-1/236/FLR-01	Floor - 1 - Lobby - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Beneath Rubber Tiles					YES
10851	ACTIVE	N	N125-00-1/237	Lobby - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16671	ACTIVE	N	N125-00-1/237/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
16672	ACTIVE	N	N125-00-1/237/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn	Void	Asbestos	Surveyed – Not Detected				Concrete Roof; Breeze Block Walls				YES	
10852	ACTIVE	N	N125-00-1/238	Lobby - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16673	ACTIVE	N	N125-00-1/238/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18362	ACTIVE	N	N125-00-1/238/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Metal Duct above Supalux Tiles				YES	
10853	ACTIVE	N	N125-00-1/239	Lobby - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16674	ACTIVE	N	N125-00-1/239/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles				YES	
19963	ACTIVE	N	N125-00-1/239/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
10854	ACTIVE	N	N125-00-1/331	Mess Room - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N125-00 - Station Building - Angel Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16676	ACTIVE	N	N125-00-1/331	Mess Room - Station Building - Angel Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - Foam Insulation Board					
18363	ACTIVE	N	N125-00-1/331	Mess Room - Station Building - Angel Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
16677	ACTIVE	N	N125-00-1/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Angel Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18836	ACTIVE	N	N125-00-1/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Angel Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	
10855	ACTIVE	N	N125-00-1/341	Station Supervisor Office - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19052	ACTIVE	N	N125-00-1/341	Station Supervisor Office - Station Building - Angel Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - Foam Insulation Board					
16678	ACTIVE	N	N125-00-1/341	Station Supervisor Office - Station Building - Angel Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
16679	ACTIVE	N	N125-00-1/341/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Angel Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18364	ACTIVE	N	N125-00-1/341/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Angel Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	
10856	ACTIVE	N	N125-00-1/416	Toilet: Female - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16684	ACTIVE	N	N125-00-1/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Angel Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	
16683	ACTIVE	N	N125-00-1/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Angel Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
10857	ACTIVE	N	N125-00-1/417	Toilet - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19053	ACTIVE	N	N125-00-1/417/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18365	ACTIVE	N	N125-00-1/417/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	
10858	ACTIVE	N	N125-00-1/418	Toilet: Male - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16686	ACTIVE	N	N125-00-1/418/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Angel Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	



# Hazardous Material Asset Register - Summary



## N125-00 - Station Building - Angel Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16685	ACTIVE	N	N125-00-1/418/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Angel Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
10859	ACTIVE	N	N125-00-1/632	Stairs: Spiral - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16689	ACTIVE	N	N125-00-1/632	Stairs: Spiral - Station Building - Angel Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel Boxing					
10860	ACTIVE	N	N125-00-1/661	Switch Room - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44282	ACTIVE	N	N125-00-1/661	Switch Room - Station Building - Angel Stn	Cable Duct: Other	Asbestos	Presumed				Ducts to floor - Presumed Cable ducts are not visible beneath cement layer on top to floor- therefore material not scored in 2020 re-inspection.				N	N
18366	ACTIVE	N	N125-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Angel Stn	Other Electrical Boxes	Asbestos	Presumed				4 x Transformer Boxes No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		4			
16690	ACTIVE	N	N125-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Angel Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 30 amp Switch Box - Insulation within - No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1			
10861	ACTIVE	N	N125-00-1/731	CER - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16693	ACTIVE	N	N125-00-1/731/FLR-01	Floor - 1 - CER - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
19054	ACTIVE	N	N125-00-1/731/WAL-003	Wall: Internal - 3 - CER - Station Building - Angel Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x 60 amp Switch Boxes - Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2			
10862	ACTIVE	N	N125-00-1/746	SCR - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16696	ACTIVE	N	N125-00-1/746/CLG-01	Ceiling: Suspended - 1 - SCR - Station Building - Angel Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	
16695	ACTIVE	N	N125-00-1/746/CLG-01	Ceiling: Suspended - 1 - SCR - Station Building - Angel Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
16694	ACTIVE	N	N125-00-1/746/DOR-01	Door - 1 - SCR - Station Building - Angel Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Door - Supalux Trim around Glass					



# Hazardous Material Asset Register - Summary



## N125-00 - Station Building - Angel Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10863	ACTIVE	N	N125-00-1/751	Station Control Room - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16698	ACTIVE	N	N125-00-1/751	Station Control Room - Station Building - Angel Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Box - Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2			
16697	ACTIVE	N	N125-00-1/751/CLG-01	Ceiling: Suspended - 1 - Station Control Room - Station Building - Angel Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Metal Duct, Fibreglass Duct Lagging above false ceiling				YES	
18367	ACTIVE	N	N125-00-1/751/FLR-01	Floor - 1 - Station Control Room - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden False Floor					YES
10864	ACTIVE	N	N125-00-1/761	SVC - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18899	ACTIVE	N	N125-00-1/761	SVC - Station Building - Angel Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10865	ACTIVE	N	N125-00-1/776	Plant Room - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16699	ACTIVE	N	N125-00-1/776	Plant Room - Station Building - Angel Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10866	ACTIVE	N	N125-00-1/777	Plant Room - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16700	ACTIVE	N	N125-00-1/777	Plant Room - Station Building - Angel Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10867	ACTIVE	N	N125-00-1/778	Fan Room - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18368	ACTIVE	N	N125-00-1/778	Fan Room - Station Building - Angel Stn	Caulking	Asbestos	Surveyed – Not Detected				No Caulking Identified					
10868	ACTIVE	N	N125-00-2/151	UMC - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16706	ACTIVE	N	N125-00-2/151	UMC - Station Building - Angel Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel Panels, on incline					
16707	ACTIVE	N	N125-00-2/171	Escalator Incline - Station Building - Angel Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10869	ACTIVE	N	N125-00-2/236	Lobby - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N125-00 - Station Building - Angel Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18370	ACTIVE	N	N125-00-2/236	Lobby - Station Building - Angel Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Board High level behind ventilation equipment - access gained by cat ladder - Non asbestos					
10870	ACTIVE	N	N125-00-2/237	Passage - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16708	ACTIVE	N	N125-00-2/237	Passage - Station Building - Angel Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux on Fire Exit					
10871	ACTIVE	N	N125-00-2/240	Lobby - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18900	ACTIVE	N	N125-00-2/240/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Steel Duct above Supalux ceiling				YES	
16710	ACTIVE	N	N125-00-2/240/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
10872	ACTIVE	N	N125-00-2/341	Lobby - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16712	ACTIVE	N	N125-00-2/341/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
16713	ACTIVE	N	N125-00-2/341/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Angel Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Concrete; Steel Duct above Supalux Tiles					
10873	ACTIVE	N	N125-00-2/631	Stairs: Spiral - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Asbestos Free									
18407	ACTIVE	N	N125-00-2/631	Stairs: Spiral - Station Building - Angel Stn	No Access	Asbestos	Surveyed – Not Detected				No known asbestos. Concrete slab to floor and stairs. Brickwork to walls, plastic cables, metal conduits, firestops, cable management system, new mastic, Durasteel panel - Non asbestos. Refer to report R725001					
10874	ACTIVE	N	N125-00-2/661	Switch Room - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16721	ACTIVE	N	N125-00-2/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Angel Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 60amp Switch Box - Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1			
25698	ACTIVE	N	N125-00-2/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Angel Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x 60amp, 1 x 30amp switch boxes - insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		3			



# Hazardous Material Asset Register - Summary



## N125-00 - Station Building - Angel Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16722	ACTIVE	N	N125-00-2/661/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Angel Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1			
10875	ACTIVE	N	N125-00-2/662	Switch Room - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18373	ACTIVE	N	N125-00-2/662	Switch Room - Station Building - Angel Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
10876	ACTIVE	N	N125-00-2/781	Switch Room - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed				No Access Room has Alarm (EDF) Aug 2014					
16723	ACTIVE	N	N125-00-2/781	Switch Room - Station Building - Angel Stn	Isolator Switches	Asbestos	Presumed				Materials within 2x combination fuse switches. Presumed asbestos (R725001)					
10877	ACTIVE	N	N125-00-2/956	Disused Room - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Asbestos Free									
16729	ACTIVE	N	N125-00-2/956	Disused Room - Station Building - Angel Stn	No Access	Asbestos	Surveyed - Not Detected				No known asbestos - Concrete slab to floor, ceiling, columns and beams, brickwork to walls, plastic cables, metal conduits, firestops, cable management system, new mastic, new heater units, new modern sink area, AC ductwork, AC pant units. Refer to report R725001					
10878	ACTIVE	N	N125-00-3/071	Circulation Area - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
46398	ACTIVE	N	N125-00-3/071	Circulation Area - Station Building - Angel Stn		Asbestos	Sampled - Not Detected				Plasterboard, MMMF within matrix behind cable management system metal panels to walls			R679620	N	N
16731	ACTIVE	N	N125-00-3/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above metal ceiling				YES	
10879	ACTIVE	N	N125-00-3/072	Circulation Area - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
46397	ACTIVE	N	N125-00-3/072	Circulation Area - Station Building - Angel Stn	Boarding: AIB	Asbestos	Sampled - Not Detected				Insulation board throughout to the rack of vertical metal panels above 3/201	5		R679620	N	N
44105	ACTIVE	N	N125-00-3/072/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Angel Stn	Caulking	Asbestos	Sampled - Not Detected				Mastic, 4m, to plasterboard panel/metal frame to 3/072 Corridor to Escalators 1,2&3.			R604726	N	N
44101	ACTIVE	N	N125-00-3/072/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Angel Stn	Caulking	Asbestos	Sampled - Not Detected				Tunnel caulking, throughout, to tunnel rings at middle of 3/072 Corridor to Escalators 1,2&3.			R604726	N	N
16732	ACTIVE	N	N125-00-3/072/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above metal ceiling				YES	



# Hazardous Material Asset Register - Summary



## N125-00 - Station Building - Angel Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44103	ACTIVE	N	N125-00-3/072/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Angel Stn	Caulking	Asbestos	Sampled – Not Detected				Clay cable ducts, 4 no, to concrete floor (PVC cables coming out) to 3/072 Corridor to Escalators 1,2&3.			R604726	N	N
44104	ACTIVE	N	N125-00-3/072/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Angel Stn	Caulking	Asbestos	Sampled – Not Detected				New plasterboard panel (plus debris on floor), 1 no, to metal frame behind advertising panel to 3/072 Corridor to Escalators 1,2&3.			R604726	N	N
44102	ACTIVE	N	N125-00-3/072/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Angel Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel caulking, throughout, to tunnel rings at end of 3/072 Corridor to Escalators 1,2&3.			R604726	N	N
44100	ACTIVE	N	N125-00-3/072/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Angel Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel caulking, throughout, to tunnel rings at start of 3/072 Corridor to Escalators 1,2&3.			R604726	N	N
10880	ACTIVE	N	N125-00-3/151	UMC - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18463	ACTIVE	N	N125-00-3/151	UMC - Station Building - Angel Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel Panels - Non Asbestos					
19058	ACTIVE	N	N125-00-3/151/CLG-01	Ceiling: Suspended - 1 - UMC - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Metal, Supalux Ceiling				YES	
16734	ACTIVE	N	N125-00-3/151/CLG-01	Ceiling: Suspended - 1 - UMC - Station Building - Angel Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Ceilings - Metal, Supalux					
10881	ACTIVE	N	N125-00-3/161	LMC - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16736	ACTIVE	N	N125-00-3/161/CLG-01	Ceiling: Solid - 1 - LMC - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	
16735	ACTIVE	N	N125-00-3/161/FLR-02	Floor - 2 - LMC - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Beneath Metal Floor					YES
19357	ACTIVE	N	N125-00-3/171	Escalator Incline - Station Building - Angel Stn	No Access	Asbestos	Surveyed – Not Detected				Concrete to floor, metal tunnel rings to walls & ceiling, plastic cables, metal conduits, firestops, cable management system, new mastic, plastic and metal pipework. New escalator equipment, durasteel to incline walls both sides - Non asbestos, metal cable ducts, RSJs. Refer to Report R725001					
10882	ACTIVE	N	N125-00-3/201	Passage - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18441	ACTIVE	N	N125-00-3/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Angel Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Rings - Cement Grout					
16737	ACTIVE	N	N125-00-3/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	



# Hazardous Material Asset Register - Summary



## N125-00 - Station Building - Angel Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10883	ACTIVE	N	N125-00-4/071	Circulation Area - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46399	ACTIVE	N	N125-00-4/071	Circulation Area - Station Building - Angel Stn	Boarding: AIB	Asbestos	Sampled – Not Detected				Insulation board to the bacm of metal panels	30		R679620	N	N
16745	ACTIVE	N	N125-00-4/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	
10884	ACTIVE	N	N125-00-4/072	Circulation Area - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46400	ACTIVE	N	N125-00-4/072	Circulation Area - Station Building - Angel Stn	Boarding: AIB	Asbestos	Sampled – Not Detected				Insulation board to the back of metal panels	15		R679620	N	N
16746	ACTIVE	N	N125-00-4/072/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	
10885	ACTIVE	N	N125-00-4/081	Lobby - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16747	ACTIVE	N	N125-00-4/081/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	
10886	ACTIVE	N	N125-00-4/161	LMC - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18442	ACTIVE	N	N125-00-4/161	LMC - Station Building - Angel Stn	Caulking	Asbestos	Surveyed – Not Detected				Concrete Caulking (Walls)					
16748	ACTIVE	N	N125-00-4/161/CLG-01	Ceiling: Suspended - 1 - LMC - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	
10887	ACTIVE	N	N125-00-4/201	Passage - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19060	ACTIVE	N	N125-00-4/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	
10888	ACTIVE	N	N125-00-4/202	Passage - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16749	ACTIVE	N	N125-00-4/202/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	
10889	ACTIVE	N	N125-00-4/203	Passage - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16750	ACTIVE	N	N125-00-4/203/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	



# Hazardous Material Asset Register - Summary



## N125-00 - Station Building - Angel Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10890	ACTIVE	N	N125-00-4/204	Passage - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18443	ACTIVE	N	N125-00-4/204/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	
10891	ACTIVE	N	N125-00-4/205	Passage - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16751	ACTIVE	N	N125-00-4/205/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	
10892	ACTIVE	N	N125-00-4/206	Passage - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16752	ACTIVE	N	N125-00-4/206/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	
10893	ACTIVE	N	N125-00-4/207	Passage - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16753	ACTIVE	N	N125-00-4/207/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	
10894	ACTIVE	N	N125-00-4/208	Passage - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16754	ACTIVE	N	N125-00-4/208/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	
10895	ACTIVE	N	N125-00-4/236	Service Area - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18408	ACTIVE	N	N125-00-4/236	Service Area - Station Building - Angel Stn	Caulking	Asbestos	Surveyed - Not Detected				Tunnel Rings - Caulking - Non Asbestos (Walls)					
16756	ACTIVE	N	N125-00-4/236	Service Area - Station Building - Angel Stn	Cement Troughing	Asbestos	Known				Cable Troughing - Chrysotile					
16755	ACTIVE	N	N125-00-4/236/CLG-01	Ceiling: Solid - 1 - Service Area - Station Building - Angel Stn	Caulking	Asbestos	Surveyed - Not Detected				Tunnel Rings - Caulking - Non Asbestos					
10896	ACTIVE	N	N125-00-4/261	Platform 1 - Northbound Fast - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16757	ACTIVE	N	N125-00-4/261	Platform 1 - Northbound Fast - Station Building - Angel Stn	Cement Troughing	Asbestos	Known				Cable Troughing - Chrysotile No access to underside of platform during traffic hours in 2020 re-inspection.					
18902	ACTIVE	N	N125-00-4/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	



# Hazardous Material Asset Register - Summary



## N125-00 - Station Building - Angel Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18444	ACTIVE	N	N125-00-4/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Angel Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert 12mm Cable - Invert Main Wall  No photo in report R56252.  No access into platform invert during 2020 re-inspection - confined space entry required.		1	R56252		YES
10897	ACTIVE	N	N125-00-4/262	Platform 2 - Southbound Fast - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16758	ACTIVE	N	N125-00-4/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	
16760	ACTIVE	N	N125-00-4/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Angel Stn	Void	Asbestos	Surveyed - Not Detected				New Build, All Cables PVC, J Hangers, All New Structure, Ceramic Ducts to 4/207 & 4/702 - NAD, invert to track via 4/711 & track adjacent to 4/662, J Hangers & PVC Cables - NAD					YES
16759	ACTIVE	N	N125-00-4/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Angel Stn	Durasteel	Asbestos	Strongly Presumed				Headwall <0.5m Durasteel panel under nosing of platform  No access to underside of platform during traffic in 2020 re-inspection		1			
10898	ACTIVE	N	N125-00-4/406	Store - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16761	ACTIVE	N	N125-00-4/406	Store - Station Building - Angel Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
10899	ACTIVE	N	N125-00-4/411	SER - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16762	ACTIVE	N	N125-00-4/411	SER - Station Building - Angel Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
10900	ACTIVE	N	N125-00-4/631	Stairs: Spiral - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16763	ACTIVE	N	N125-00-4/631	Stairs: Spiral - Station Building - Angel Stn	Durasteel	Asbestos	Surveyed - Not Detected				Durasteel Panel - Non Asbestos					
18445	ACTIVE	N	N125-00-4/631/CLG-01	Ceiling: Solid - 1 - Spiral Stairs - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	
10901	ACTIVE	N	N125-00-4/632	Lobby - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16764	ACTIVE	N	N125-00-4/632	Lobby - Station Building - Angel Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
44946	ACTIVE	N	N125-00-4/632	Lobby - Station Building - Angel Stn	Lead/Leading	Lead Paint/Lead	Known				Disused Staircase - Bottom of Shaft - Single Width Stairs Grey Gloss				N	N



# Hazardous Material Asset Register - Summary



## N125-00 - Station Building - Angel Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44944	ACTIVE	N	N125-00-4/632	Lobby - Station Building - Angel Stn	Lead/Leading	Lead Paint/Lead	Known				Disused Staircase - Bottom of Shaft - Support steel Grey Gloss				N	N
44945	ACTIVE	N	N125-00-4/632	Lobby - Station Building - Angel Stn	Lead/Leading	Lead Paint/Lead	Known				Disused Staircase - Bottom of Shaft - Hand Rail Grey Gloss				N	N
10902	ACTIVE	N	N125-00-4/661	Switch Room - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16765	ACTIVE	N	N125-00-4/661/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	
20028	ACTIVE	N	N125-00-4/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Angel Stn	Isolator Switches	Asbestos	Strongly Presumed				3 x 100amp, 2 x 200amp, 2 x 60amp Switch Boxes - Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		7			
16766	ACTIVE	N	N125-00-4/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Angel Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1			
10903	ACTIVE	N	N125-00-4/662	Switch Room - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16767	ACTIVE	N	N125-00-4/662/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	
43257	ACTIVE	N	N125-00-4/662/FLR-01	Floor - 1 - Switch Room - Station Building - Angel Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within				N	N
16768	ACTIVE	N	N125-00-4/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Angel Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x 60 amp, 1 x 200 amp, 3 x 100 amp Switch Boxes - Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		6			
10904	ACTIVE	N	N125-00-4/663	Switch Cupboard - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed				No Access Need Track Side Protection Aug 2014					
18446	ACTIVE	N	N125-00-4/663	Switch Cupboard - Station Building - Angel Stn	No Access	Asbestos	Surveyed - Not Detected				No known asbestos. New electrical equipment, boxes, plastic cables, metal conduits, firestops, cable management system, new mastic. Durasteel to door and ceiling - Non asbestos. Refer to report R725001					
10905	ACTIVE	N	N125-00-4/711	Relay Room - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N125-00 - Station Building - Angel Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16769	ACTIVE	N	N125-00-4/711	Relay Room - Station Building - Angel Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10906	ACTIVE	N	N125-00-4/712	Passage - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16770	ACTIVE	N	N125-00-4/712	Passage - Station Building - Angel Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board on Wall					
18409	ACTIVE	N	N125-00-4/712	Passage - Station Building - Angel Stn	Caulking	Asbestos	Surveyed – Not Detected				Walls					
16771	ACTIVE	N	N125-00-4/712/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Angel Stn	Caulking	Asbestos	Surveyed – Not Detected									
10907	ACTIVE	N	N125-00-4/713	Lobby - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44938	ACTIVE	N	N125-00-4/713	Lobby - Station Building - Angel Stn	Other Boarding	Asbestos	Presumed				Paxoline Packing behind metal struts				N	N
19061	ACTIVE	N	N125-00-4/713	Lobby - Station Building - Angel Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10908	ACTIVE	N	N125-00-4/731	CER - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18447	ACTIVE	N	N125-00-4/731/FLR-01	Floor - 1 - CER - Station Building - Angel Stn	Void	Asbestos	Surveyed – Not Detected				PVC Cables, Metal, Trunking beneath Computer Flooring					YES
16772	ACTIVE	N	N125-00-4/731/WAL-005	Wall: Internal - 5 - CER - Station Building - Angel Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x 60 amp Switch Boxes - Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2			
10909	ACTIVE	N	N125-00-4/761	CER - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16773	ACTIVE	N	N125-00-4/791	Vent Shaft - Station Building - Angel Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
16774	ACTIVE	N	N125-00-4/792	Vent Shaft - Station Building - Angel Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access No keys available. Refer to report R725001					
46392	ACTIVE	N	N125-00-4/793	Vent Shaft - Station Building - Angel Stn	Mastic	Asbestos	Sampled – Not Detected				Sealant around the screws to concrete blocks to vent shaft wall Survey of 4/793, 4/794 & 4/795 combined.	1		R683051	N	N
46395	ACTIVE	N	N125-00-4/793	Vent Shaft - Station Building - Angel Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel doors to entrance to vent shaft from staircase Survey of 4/793, 4/794 & 4/795 combined.	4	2	R683051	N	N



# Hazardous Material Asset Register - Summary



## N125-00 - Station Building - Angel Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46394	ACTIVE	N	N125-00-4/793	Vent Shaft - Station Building - Angel Stn	Caulking	Asbestos	Sampled – Not Detected				Caulking throughout to metal tunnel ring joints Survey of 4/793, 4/794 & 4/795 combined.	100		R683051	N	N
46390	ACTIVE	N	N125-00-4/793	Vent Shaft - Station Building - Angel Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel enclosure to stairs to middle of vent Survey of 4/793, 4/794 & 4/795 combined	100		R683051	N	N
46393	ACTIVE	N	N125-00-4/793	Vent Shaft - Station Building - Angel Stn	Mastic	Asbestos	Sampled – Not Detected				Mastic throughout to floor joints Survey of 4/793, 4/794 & 4/795 combined.	100		R683051	N	N
46391	ACTIVE	N	N125-00-4/793	Vent Shaft - Station Building - Angel Stn	Caulking	Asbestos	Sampled – Not Detected				Caulking/bitumen throughout to concrete block joints to vent shaft walls Survey of 4/793, 4/794 & 4/795 combined.	100		R683051	N	N
16776	ACTIVE	N	N125-00-4/794	Vent Shaft - Station Building - Angel Stn	No Access	Asbestos	Surveyed – Not Detected				No known asbestos. Metal panels to ceiling, concrete slab to floor, ceiling and walls, Concrete precast tunnel rings throughout, plastic cables, metal conduits, firestops, cable management system, new mastic, Durasteel to door 4/631 walls and stairs 600m2 non asbestos. New AC duct, terracotta ducts to either side of doors 4/631 and walls. Refer to report R725001					
19062	ACTIVE	N	N125-00-4/795	Vent Shaft - Station Building - Angel Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10910	ACTIVE	N	N125-00-4/951	Disused Room - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18448	ACTIVE	N	N125-00-4/951	Disused Room - Station Building - Angel Stn	Cable Duct: Other	Asbestos	Surveyed – Not Detected				Cable Sleeve					
64513	ACTIVE	N	N125-00-4/951	Disused Room - Station Building - Angel Stn	Cable Ducts: Cement	Asbestos	Sampled – Not Detected				Ducts- Non Asbestos - R736276 Report			R736276		
16777	ACTIVE	N	N125-00-4/951	Disused Room - Station Building - Angel Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Ring - Caulking Solid					
16778	ACTIVE	N	N125-00-4/951/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Tunnel Ring				YES	
18903	ACTIVE	N	N125-00-4/951/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Angel Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Ring - No Caulking Identified					
10911	ACTIVE	N	N125-00-4/952	Disused Room - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N125-00 - Station Building - Angel Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16779	ACTIVE	N	N125-00-4/952	Disused Room - Station Building - Angel Stn	Cement Troughing	Asbestos	Strongly Presumed				Cable Troughing - Chrysotile					
10912	ACTIVE	N	N125-00-4/953	Relay Room - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19063	ACTIVE	N	N125-00-4/953	Relay Room - Station Building - Angel Stn	Westing house Boxes	Asbestos	Presumed				Westinghouse Box		1			
18402	ACTIVE	N	N125-00-4/953	Relay Room - Station Building - Angel Stn	Other Boarding	Asbestos	Presumed				Asbestos Board Top Rack					
16780	ACTIVE	N	N125-00-4/953	Relay Room - Station Building - Angel Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables		3			
18449	ACTIVE	N	N125-00-4/953	Relay Room - Station Building - Angel Stn	Other Boarding	Asbestos	Presumed				Paxoline Board					
42039	INACTIVE	N	N125-00-4/953/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Angel Stn	PCBs	Polychlorinated biphenyl	Known				1 x PCB - Fair Condition		1		N	N
42331	INACTIVE	N	N125-00-4/953/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Angel Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				3 x box style PCB's - Fair Condition 01 March 2017 inspection Fair Condition		3		N	N
10913	ACTIVE	N	N125-00-5/422	Platform Invert - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16585	ACTIVE	N	N125-00-5/422	Platform Invert - Station Building - Angel Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
10914	ACTIVE	N	N125-00-5/771	Pump Room - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16586	ACTIVE	N	N125-00-5/771	Pump Room - Station Building - Angel Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access : Note A Do not enter notice applied to this room					
16587	ACTIVE	N	N125-00-5/791	Vent Shaft - Station Building - Angel Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
10915	ACTIVE	N	N125-00-A/776	Fan Room - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16592	ACTIVE	N	N125-00-A/776	Fan Room - Station Building - Angel Stn	Caulking	Asbestos	Surveyed - Not Detected				Tunnel Rings - Inspected & No Caulking Identified					
10916	ACTIVE	N	N125-00-A/778	Fan Room - Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16593	ACTIVE	N	N125-00-A/778	Fan Room - Station Building - Angel Stn	Caulking	Asbestos	Surveyed - Not Detected				Tunnel Rings - Inspected & No Caulking Identified					



# Hazardous Material Asset Register - Summary



## N127-00 - Station Building - Old Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44308	ACTIVE	N	N127-00-1/171	Escalator Incline - Station Building - Old Street Stn		Asbestos	Sampled – Not Detected				Corrugated sheeting >30m To back of metal panels on escalator wall running throughout			R612151	N	N
16550	ACTIVE	N	N127-00-1/171	Escalator Incline - Station Building - Old Street Stn	No Access	Asbestos	No Access: Presumed				Dust 1m2 to back of advertising				N	N
19355	ACTIVE	N	N127-00-1/172/CLG-01	Ceiling: Solid - 1 - Escalator Incline - Station Building - Old Street Stn	Caulking	Asbestos	Known				Escalator 3 Incline - Caulking to tunnel ring within incline No access 2020 re-inspection no lift escalator ticket					
18208	ACTIVE	N	N127-00-1/172/WAL-001	Wall: Internal - 1 - Escalator Incline - Station Building - Old Street Stn	Caulking	Asbestos	Known				Escalator 3 Incline - Caulking to tunnel ring within incline No access 2020 re-inspection no lift escalator ticket					
16551	ACTIVE	N	N127-00-1/172/WAL-002	Wall: Internal - 2 - Escalator Incline - Station Building - Old Street Stn	Caulking	Asbestos	Known				Escalator 3 Incline - Caulking to tunnel ring within incline No access 2020 re-inspection no lift escalator ticket					
10968	ACTIVE	N	N127-00-2/001	Booking Hall - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16552	ACTIVE	N	N127-00-2/001	Booking Hall - Station Building - Old Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10969	ACTIVE	N	N127-00-2/011	Ticket Office - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16553	ACTIVE	N	N127-00-2/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
18209	ACTIVE	N	N127-00-2/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Old Street Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Walls Breeze Block; Metal Pipe Work above Supalux Ceiling					YES
10970	ACTIVE	N	N127-00-2/021	POM - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16554	ACTIVE	N	N127-00-2/021	POM - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panelling - High Level Back Wall; Supalux Panelling Base of Safe LHS					
18831	ACTIVE	N	N127-00-2/021	POM - Station Building - Old Street Stn	LUL Heaters	Asbestos	Known				LU Heater - Insulation Board - Chrysotile					
16555	ACTIVE	N	N127-00-2/021/CLG-01	Ceiling: Solid - 1 - POM - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing					
10971	ACTIVE	N	N127-00-2/031	Mess Room - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16556	ACTIVE	N	N127-00-2/031/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Old Street Stn	Void	Asbestos	Surveyed – Not Detected				Walls - Brick Work; Metal Duct Work				YES	



# Hazardous Material Asset Register - Summary



## N127-00 - Station Building - Old Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44959	ACTIVE	N	N127-00-2/031/WAL-001	Wall: Internal - 1 - Mess Room - Station Building - Old Street Stn	LUL Heaters	Asbestos	Presumed				Heater				N	N
10972	ACTIVE	N	N127-00-2/036	Lobby - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19043	ACTIVE	N	N127-00-2/036/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux					
16557	ACTIVE	N	N127-00-2/036/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
16558	ACTIVE	N	N127-00-2/036/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Old Street Stn	Void	Asbestos	Surveyed - Not Detected				Concrete; Walls Breeze Block above Supalux Tiles				YES	
10973	ACTIVE	N	N127-00-2/037	Toilet: Unisex - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18210	ACTIVE	N	N127-00-2/037/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Old Street Stn	Void	Asbestos	Surveyed - Not Detected				Concrete; Walls Breeze Block above Supalux Tiles				YES	
10974	ACTIVE	N	N127-00-2/047	Kitchen - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
46347	ACTIVE	N	N127-00-2/047/CLG-01	Ceiling: Solid - 1 - Kitchen - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Sampled - Not Detected				Supalux panels to ceiling			R672526	N	N
16559	ACTIVE	N	N127-00-2/047/CLG-01	Ceiling: Solid - 1 - Kitchen - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
16560	ACTIVE	N	N127-00-2/047/CLG-01	Ceiling: Solid - 1 - Kitchen - Station Building - Old Street Stn	Void	Asbestos	Surveyed - Not Detected				PVC Cable; Concrete; Lagging Fibre glass; Conduits above False Ceiling				YES	
46348	ACTIVE	N	N127-00-2/047/FLR-01	Floor - 1 - Kitchen - Station Building - Old Street Stn	Vinyl tiles	Asbestos	Sampled - Not Detected				Lino flooring on solid concrete floor			R672526	N	N
10975	ACTIVE	N	N127-00-2/071	Circulation Area - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16561	ACTIVE	N	N127-00-2/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Old Street Stn	Void	Asbestos	Surveyed - Not Detected				Loose Rock Wool above False Ceiling				YES	
10976	ACTIVE	N	N127-00-2/081	Lobby - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16562	ACTIVE	N	N127-00-2/081	Lobby - Station Building - Old Street Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
10977	ACTIVE	N	N127-00-2/151	UMC - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N127-00 - Station Building - Old Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18118	ACTIVE	N	N127-00-2/151	UMC - Station Building - Old Street Stn	Lead/Leading	Lead Paint/Lead	Known				Grey Oil Based Paint - Girder. Thickness .44mm; Est Quantity 151m; Analysis 18.9%					
16451	ACTIVE	N	N127-00-2/151	UMC - Station Building - Old Street Stn	Lead/Leading	Lead Paint/Lead	Known				Black & Cream Oil Based Paint - Girder. Thickness .23mm; Est Quantity 41m; Analysis 14.9%					
16452	ACTIVE	N	N127-00-2/151/WAL-001	Wall: Internal - 1 - UMC - Station Building - Old Street Stn		Asbestos	Surveyed - Not Detected				Bitumen Ducts					
16449	ACTIVE	N	N127-00-2/151/WAL-001	Wall: Internal - 1 - UMC - Station Building - Old Street Stn	Cable Duct: Other	Asbestos	Known				Ducts Above Switch Board No 2 - Chrysotile No access 2020 re-inspection no lift escalator ticket		8			
16450	ACTIVE	N	N127-00-2/151/WAL-002	Wall: Internal - 2 - UMC - Station Building - Old Street Stn	Cable Duct: Other	Asbestos	Known				Ducts to RHS of Escalator Sprinkler System - Chrysotile No access 2020 re-inspection no lift escalator ticket		6			
10978	ACTIVE	N	N127-00-2/152	UMC - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16454	ACTIVE	N	N127-00-2/152	UMC - Station Building - Old Street Stn	Gasket :Pipework	Asbestos	Presumed				Gasket to Escalator Motor No access 2020 re-inspection no lift escalator ticket					
16453	ACTIVE	N	N127-00-2/152	UMC - Station Building - Old Street Stn	Durasteel	Asbestos	Sampled - Not Detected				Durasteel (2m2), to storage bin cover.		1			
18119	ACTIVE	N	N127-00-2/152	UMC - Station Building - Old Street Stn	Lead/Leading	Lead Paint/Lead	Known				Black Gloss - Steel Column 20.13%					
25709	ACTIVE	N	N127-00-2/152	UMC - Station Building - Old Street Stn		Lead Paint/Lead	Sampled - Not Detected				Cream Gloss Wall 0.0004%					
25708	ACTIVE	N	N127-00-2/152	UMC - Station Building - Old Street Stn		Lead Paint/Lead	Sampled - Not Detected				Blue Gloss Wall 0.07%					
16455	ACTIVE	N	N127-00-2/152	UMC - Station Building - Old Street Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Gloss - Steel Column & Beam 13.03%					
20020	ACTIVE	N	N127-00-2/152/WAL-002	Wall: Internal - 2 - UMC - Station Building - Old Street Stn	Cable Duct: Other	Asbestos	Known				10 x Ducts No access 2020 re-inspection no lift escalator ticket		10			
10979	ACTIVE	N	N127-00-2/201	Passage - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16456	ACTIVE	N	N127-00-2/201/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Old Street Stn	Void	Asbestos	Surveyed - Not Detected				Concrete; Metal Ducts above False Ceiling				YES	
10980	ACTIVE	N	N127-00-2/202	Passage - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N127-00 - Station Building - Old Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18120	ACTIVE	N	N127-00-2/202	Passage - Station Building - Old Street Stn	Other Electrical Boxes	Asbestos	Known				AFC Lining to Electrical Box - Chrysotile					
16457	ACTIVE	N	N127-00-2/202/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn	Void	Asbestos	Surveyed - Not Detected				PVC Cables, Brick, Concrete, Trunking above False Ceiling Boarding to Bulkhead - Sampled and confirmed non asbestos report R713626 - At top of escalator/ door 2/151				YES	
10981	ACTIVE	N	N127-00-2/203	Passage - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16458	ACTIVE	N	N127-00-2/203/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn	Void	Asbestos	Surveyed - Not Detected				Concrete, Bricks; PVC Cables; Trunking above False Ceiling				YES	
10982	ACTIVE	N	N127-00-2/236	Passage - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18121	ACTIVE	N	N127-00-2/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Old Street Stn	Void	Asbestos	Surveyed - Not Detected				Supalux Sheeting, Concrete above Supalux Tiles				YES	
16460	ACTIVE	N	N127-00-2/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
16459	ACTIVE	N	N127-00-2/236/DOR-01	Door - 1 - Passage - Station Building - Old Street Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Door Panels					
46338	ACTIVE	N	N127-00-2/236/FLR-01	Floor - 1 - Passage - Station Building - Old Street Stn	Vinyl tiles	Asbestos	Sampled - Not Detected				Lino flooring on solid concrete floor			R672526	N	N
10983	ACTIVE	N	N127-00-2/237	Lobby - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16461	ACTIVE	N	N127-00-2/237/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
16462	ACTIVE	N	N127-00-2/237/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Old Street Stn	Void	Asbestos	Surveyed - Not Detected				Concrete; Walls Breeze Block; Fibre glass Lagged Pipe Work above Supalux Tiles				YES	
10984	ACTIVE	N	N127-00-2/238	Lobby - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18826	ACTIVE	N	N127-00-2/238/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Panels					
16464	ACTIVE	N	N127-00-2/238/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Old Street Stn	Void	Asbestos	Surveyed - Not Detected				Concrete; Walls Breeze Block above Supalux Panels				YES	
16463	ACTIVE	N	N127-00-2/238/FLR-01	Floor - 1 - Lobby - Station Building - Old Street Stn	Void	Asbestos	No Access: Presumed				Beneath Lino PVC					YES



# Hazardous Material Asset Register - Summary



## N127-00 - Station Building - Old Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10985	ACTIVE	N	N127-00-2/281	Locker Room - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18973	ACTIVE	N	N127-00-2/281	Locker Room - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing					
46343	ACTIVE	N	N127-00-2/281/DORS	Doors - Locker Room - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux panels to low level of timber door	1		R672526	N	N
46342	ACTIVE	N	N127-00-2/281/FLR-01	Floor - 1 - Locker Room - Station Building - Old Street Stn	Vinyl tiles	Asbestos	Sampled – Not Detected				Lino flooring on solid concrete floor			R672526	N	N
10986	ACTIVE	N	N127-00-2/291	Station Supervisor Office - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46341	ACTIVE	N	N127-00-2/291/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux panels to ceiling			R672526	N	N
18397	ACTIVE	N	N127-00-2/291/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18122	ACTIVE	N	N127-00-2/291/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Old Street Stn	Void	Asbestos	Surveyed – Not Detected				PVC Cable; Concrete; Lagging Fibre glass; Conduits above False Ceiling				YES	
46340	ACTIVE	N	N127-00-2/291/FLR-01	Floor - 1 - Station Supervisor Office - Station Building - Old Street Stn	Vinyl tiles	Asbestos	Sampled – Not Detected				Lino flooring on solid concrete floor			R672526	N	N
16465	ACTIVE	N	N127-00-2/291/WAL-001	Wall: Internal - 1 - Station Supervisor Office - Station Building - Old Street Stn	LUL Heaters	Asbestos	Sampled – Not Detected				Heater - Lining within LTB heater was sampled and no asbestos was detected. Refer to 4-Rail ID report R691926					
10987	ACTIVE	N	N127-00-2/311	Office - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16468	ACTIVE	N	N127-00-2/311	Office - Station Building - Old Street Stn	LUL Heaters	Asbestos	Strongly Presumed				LU Heater - Insulation Board					
16467	ACTIVE	N	N127-00-2/311/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Old Street Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Walls Breeze Block; Fibre glass Lagged Pipe Work above False Ceiling				YES	
16466	ACTIVE	N	N127-00-2/311/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
10988	ACTIVE	N	N127-00-2/331	Mess Room - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18123	ACTIVE	N	N127-00-2/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Old Street Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Fibre glass Lagged Pipe Work above False Ceiling				YES	



# Hazardous Material Asset Register - Summary



## N127-00 - Station Building - Old Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18974	ACTIVE	N	N127-00-2/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels					
46345	ACTIVE	N	N127-00-2/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux panels to ceiling			R672526	N	N
46346	ACTIVE	N	N127-00-2/331/DOR-01	Door: Cubicle - 1 - Mess Room - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux panels to low level of timber door	1		R672526	N	N
46344	ACTIVE	N	N127-00-2/331/FLR-01	Floor - 1 - Mess Room - Station Building - Old Street Stn	Vinyl tiles	Asbestos	Sampled – Not Detected				Lino flooring on solid concrete floor			R672526	N	N
16469	ACTIVE	N	N127-00-2/331/WAL-003	Wall: Internal - 3 - Mess Room - Station Building - Old Street Stn	LUL Heaters	Asbestos	Strongly Presumed				Heater					
10989	ACTIVE	N	N127-00-2/396	SVC - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16470	ACTIVE	N	N127-00-2/396	SVC - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels					
10990	ACTIVE	N	N127-00-2/397	SVC - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18124	ACTIVE	N	N127-00-2/397/DOR-01	Door - 1 - SVC - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel above Door					
10991	ACTIVE	N	N127-00-2/411	Store - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16471	ACTIVE	N	N127-00-2/411	Store - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel - back Ceiling					
10992	ACTIVE	N	N127-00-2/412	Store - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16472	ACTIVE	N	N127-00-2/412	Store - Station Building - Old Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10993	ACTIVE	N	N127-00-2/416	Toilet: Male - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16473	ACTIVE	N	N127-00-2/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
16474	ACTIVE	N	N127-00-2/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Old Street Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Fibre glass Lagged Pipe Work above False Ceiling				YES	
10994	ACTIVE	N	N127-00-2/417	Lobby - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N127-00 - Station Building - Old Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16475	ACTIVE	N	N127-00-2/417/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Old Street Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Fibre glass Lagged Pipe Work above False Ceiling				YES	
18125	ACTIVE	N	N127-00-2/417/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
16476	ACTIVE	N	N127-00-2/417/CLG-02	Ceiling: Suspended - 2 - Lobby - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
16477	ACTIVE	N	N127-00-2/417/CLG-02	Ceiling: Suspended - 2 - Lobby - Station Building - Old Street Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Fibre glass Lagged Pipe Work above False Ceiling				YES	
10995	ACTIVE	N	N127-00-2/418	Toilet: Female - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16478	ACTIVE	N	N127-00-2/418/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18126	ACTIVE	N	N127-00-2/418/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Old Street Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Fibre glass Lagged Pipe Work above False Ceiling				YES	
10996	ACTIVE	N	N127-00-2/455	Tenancy - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				No Access Tenant in place Aug 2014					
16479	ACTIVE	N	N127-00-2/455	Tenancy - Station Building - Old Street Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
10997	ACTIVE	N	N127-00-2/601	Stairs: Linear - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18827	ACTIVE	N	N127-00-2/601/CLG-01	Ceiling: Solid - 1 - Spiral Stairs - Station Building - Old Street Stn	No Access	Asbestos	Surveyed – Not Detected				This location was surveyed on behalf of Morgan Sindall. Please refer to report R655702					
10998	ACTIVE	N	N127-00-2/602	Stairs: Linear - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
46461	ACTIVE	N	N127-00-2/602	Stairs: Linear - Station Building - Old Street Stn		Asbestos	No Access: Presumed				No access under metal nosing plate on steps					
18975	ACTIVE	N	N127-00-2/602/CLG-01	Ceiling: Solid - 1 - Spiral Stairs - Station Building - Old Street Stn	No Access	Asbestos	Surveyed – Not Detected				Surveyed on behalf of Morgan Sindall. Refer to 4-Rail report R655702Rev1.					
10999	ACTIVE	N	N127-00-2/631	Stairs: Spiral - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16480	ACTIVE	N	N127-00-2/631	Stairs: Spiral - Station Building - Old Street Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Ducts		10			
16481	ACTIVE	N	N127-00-2/631	Stairs: Spiral - Station Building - Old Street Stn	Caulking	Asbestos	Known				Asbestos caulking in tunnel ring joints and flanges has been identified at the station. Therefore, all ring joints must be suspected of containing asbestos. Rings forming staircase structure are sealed.					



# Hazardous Material Asset Register - Summary



## N127-00 - Station Building - Old Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11000	ACTIVE	N	N127-00-2/661	Switch Room - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16483	ACTIVE	N	N127-00-2/661	Switch Room - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing - High Level					
18127	ACTIVE	N	N127-00-2/661	Switch Room - Station Building - Old Street Stn	Gasket :Pipework	Asbestos	Strongly Presumed				Gasket missing - presume 1x combination fuse switch box to wall - photo DSC05624					
16482	ACTIVE	N	N127-00-2/661/FLR-01	Floor - 1 - Switch Room - Station Building - Old Street Stn	Vinyl tiles	Asbestos	Known				Grey Marley Tiles - Chrysotile					
44960	ACTIVE	N	N127-00-2/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Old Street Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1 x 60amp Switch Box - Insulation within		1		N	N
11001	ACTIVE	N	N127-00-2/662	Switch Room - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18976	ACTIVE	N	N127-00-2/662	Switch Room - Station Building - Old Street Stn	Other Electrical Boxes	Asbestos	Presumed				EDF in Take Feed - Asbestos components within		1			
25705	ACTIVE	N	N127-00-2/662/FLR-01	Floor - 1 - Switch Room - Station Building - Old Street Stn	Void	Asbestos	Presumed				No access to Floor Hatches		2			
42160	ACTIVE	N	N127-00-2/662/FLR-01	Floor - 1 - Switch Room - Station Building - Old Street Stn	Cable Ducts: Cement	Asbestos	Known				Cement Cable Ducts - by wall 3 - 2no		2	R713626		
16485	ACTIVE	N	N127-00-2/662/FLR-01	Floor - 1 - Switch Room - Station Building - Old Street Stn	Vinyl tiles	Asbestos	Known				Red & Grey Marley Vinyl Tiles 21/11/2022 - 32no Loose floor tiles were removed by Econ for Morgan Sindall / Old St Roundabout Project - Bitumen underneath these tiles was left in-situ.	6				
16486	ACTIVE	N	N127-00-2/662/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Old Street Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Box 1 x 30 amp - Asbestos Insulation within		1			
18191	ACTIVE	N	N127-00-2/662/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Old Street Stn	Other Electrical Boxes	Asbestos	Presumed				3 x Transformer Boxes		3			
11002	ACTIVE	N	N127-00-2/666	Switch Room - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18398	ACTIVE	N	N127-00-2/666	Switch Room - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Walls Supalux Panels					
16489	ACTIVE	N	N127-00-2/666/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel, Concrete, Brick; PVC Cable above False Ceiling				YES	



# Hazardous Material Asset Register - Summary



## N127-00 - Station Building - Old Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16488	ACTIVE	N	N127-00-2/666/FLR-01	Floor - 1 - Switch Room - Station Building - Old Street Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath Supalux Floor					YES
16487	ACTIVE	N	N127-00-2/666/FLR-01	Floor - 1 - Switch Room - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
25706	ACTIVE	N	N127-00-2/666/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Old Street Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Boxes x 3 No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		3			
18192	ACTIVE	N	N127-00-2/666/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Old Street Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 30amp Switch Box - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
25704	ACTIVE	N	N127-00-2/666/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Old Street Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 60amp Switch Box No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
25707	ACTIVE	N	N127-00-2/666/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Old Street Stn	Isolator Switches	Asbestos	Strongly Presumed				9 x 60amp, 1 x 200amp Switch Boxes No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		10			
11003	ACTIVE	N	N127-00-2/746	SCR - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16490	ACTIVE	N	N127-00-2/746	SCR - Station Building - Old Street Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No access					
11004	ACTIVE	N	N127-00-2/776	Plant Room - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25714	ACTIVE	N	N127-00-2/776	Plant Room - Station Building - Old Street Stn	Mastic	Asbestos	Surveyed – Not Detected				Gaskets to vent systems - possible mastic between flanges Report R713626 (23/06/2022) - states New Mastic & Gaiters.					
16491	ACTIVE	N	N127-00-2/776/WAL-001	Wall: Internal - 1 - Plant Room - Station Building - Old Street Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 100amp Switch Box - Insulation within		1			
18977	ACTIVE	N	N127-00-2/777/CLG-01	Ceiling: Suspended - 1 - Vent Shaft - Station Building - Old Street Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; PVC Cable; Conduit above False Ceiling				YES	
16492	ACTIVE	N	N127-00-2/777/CLG-01	Ceiling: Suspended - 1 - Vent Shaft - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					



# Hazardous Material Asset Register - Summary



## N127-00 - Station Building - Old Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16493	ACTIVE	N	N127-00-2/791	Vent Shaft - Station Building - Old Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
18193	ACTIVE	N	N127-00-2/792	Vent Shaft - Station Building - Old Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11005	ACTIVE	N	N127-00-2/951	Store - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19961	ACTIVE	N	N127-00-2/951/WAL-003	Wall: Internal - 3 - Store - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing					
11006	ACTIVE	N	N127-00-2/952	Disused Room - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16494	ACTIVE	N	N127-00-2/952	Disused Room - Station Building - Old Street Stn		Asbestos	Surveyed – Not Detected				Bitumen Ducts					
11007	ACTIVE	N	N127-00-3/207	Passage - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16495	ACTIVE	N	N127-00-3/207	Passage - Station Building - Old Street Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Network Rail Area					
11008	ACTIVE	N	N127-00-3/208	Passage - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16496	ACTIVE	N	N127-00-3/208	Passage - Station Building - Old Street Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Network Rail Area					
11009	ACTIVE	N	N127-00-3/209	Passage - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16497	ACTIVE	N	N127-00-3/209	Passage - Station Building - Old Street Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Network Rail Area					
11010	ACTIVE	N	N127-00-3/281	Office - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16498	ACTIVE	N	N127-00-3/281	Office - Station Building - Old Street Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Network Rail Area					
11011	ACTIVE	N	N127-00-3/605	Stairs: Linear - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16499	ACTIVE	N	N127-00-3/605	Stairs: Linear - Station Building - Old Street Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Network Rail Area					
11012	ACTIVE	N	N127-00-3/606	Stairs: Linear - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N127-00 - Station Building - Old Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18194	ACTIVE	N	N127-00-3/606	Stairs: Linear - Station Building - Old Street Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Network Rail Area					
11013	ACTIVE	N	N127-00-3/661	Switch Cupboard - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16500	ACTIVE	N	N127-00-3/661	Switch Cupboard - Station Building - Old Street Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Network Rail Area					
11014	ACTIVE	N	N127-00-3/662	Switch Room - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16501	ACTIVE	N	N127-00-3/662	Switch Room - Station Building - Old Street Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Network Rail Area					
11015	ACTIVE	N	N127-00-3/663	Switch Room - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
20021	ACTIVE	N	N127-00-3/663	Switch Room - Station Building - Old Street Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Network Rail Area					
11016	ACTIVE	N	N127-00-3/711	Relay Room - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16502	ACTIVE	N	N127-00-3/711	Relay Room - Station Building - Old Street Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Network Rail Area					
11017	ACTIVE	N	N127-00-3/712	Relay Room - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18195	ACTIVE	N	N127-00-3/712	Relay Room - Station Building - Old Street Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Network Rail Area					
11018	ACTIVE	N	N127-00-4/081	Circulation Area - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16504	ACTIVE	N	N127-00-4/081	Circulation Area - Station Building - Old Street Stn	Caulking	Asbestos	Strongly Presumed				Asbestos caulking in tunnel ring joints and flanges has been identified at the station. Therefore, all ring joints must be suspected of containing asbestos. Rings forming staircase structure are sealed.					
16503	ACTIVE	N	N127-00-4/081/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Old Street Stn	Void	Asbestos	No Access: Presumed				Above Metal Panels				YES	
11019	ACTIVE	N	N127-00-4/161	LMC - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N127-00 - Station Building - Old Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18196	ACTIVE	N	N127-00-4/161/CLG-01	Ceiling: Suspended - 1 - LMC - Station Building - Old Street Stn	Caulking	Asbestos	Known				Tunnel Ring Caulking - Chrysotile & Amphibole No access 2020 re-inspection no lift escalator ticket					
16505	ACTIVE	N	N127-00-4/161/CLG-01	Ceiling: Suspended - 1 - LMC - Station Building - Old Street Stn	Cellactite Sheeting	Asbestos	Known				Ceiling above escalator 1 & 2 incline and rooms - Cellactite No access 2020 re-inspection no lift escalator ticket					
11020	ACTIVE	N	N127-00-4/162	LMC - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44962	ACTIVE	N	N127-00-4/162	LMC - Station Building - Old Street Stn	Mastic	Asbestos	Known				Putty to Joint				N	N
25760	ACTIVE	N	N127-00-4/162	LMC - Station Building - Old Street Stn	Cellactite Sheeting	Asbestos	Known				Cellactite sheet No access 2020 re-inspection no lift escalator ticket					
44961	ACTIVE	N	N127-00-4/162	LMC - Station Building - Old Street Stn	Cellactite Sheeting	Asbestos	Known				Bitumen corrugated sheet to wall in front of door and ceiling				N	N
25711	ACTIVE	N	N127-00-4/162	LMC - Station Building - Old Street Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Cream gloss steel column and beam presumed to be 13.03%					
25710	ACTIVE	N	N127-00-4/162	LMC - Station Building - Old Street Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Black gloss steel column lead content persumed to be 20.13%					
16509	ACTIVE	N	N127-00-4/162/CLG-01	Ceiling: Solid - 1 - LMC - Station Building - Old Street Stn	Cellactite Sheeting	Asbestos	Known				Ceiling above escalator 1 & 2 incline and rooms - Cellactite No access 2020 re-inspection no lift escalator ticket					
18197	ACTIVE	N	N127-00-4/162/CLG-01	Ceiling: Solid - 1 - LMC - Station Building - Old Street Stn	Caulking	Asbestos	Known				Caulking behind Cellactite No access 2020 re-inspection no lift escalator ticket					
16506	ACTIVE	N	N127-00-4/162/WAL-001	Wall: Internal - 1 - LMC - Station Building - Old Street Stn	Cable Duct: Other	Asbestos	Known				6 x Cable Ducts to Walls 1&2 No access 2020 re-inspection no lift escalator ticket		6			
18978	ACTIVE	N	N127-00-4/162/WAL-001	Wall: Internal - 1 - LMC - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels					
16508	ACTIVE	N	N127-00-4/162/WAL-002	Wall: Internal - 2 - LMC - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels to ceiling at corner of walls 2 & 3					
16507	ACTIVE	N	N127-00-4/162/WAL-002	Wall: Internal - 2 - LMC - Station Building - Old Street Stn	Cable Duct: Other	Asbestos	Known				Cable Ducts to Walls 1&2 No access 2020 re-inspection no lift escalator ticket		6			
11021	ACTIVE	N	N127-00-4/201	Passage - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16510	ACTIVE	N	N127-00-4/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Tiles above false ceiling				YES	



# Hazardous Material Asset Register - Summary



## N127-00 - Station Building - Old Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11022	ACTIVE	N	N127-00-4/202	Passage - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16511	ACTIVE	N	N127-00-4/202	Passage - Station Building - Old Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11023	ACTIVE	N	N127-00-4/203	Passage - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16512	ACTIVE	N	N127-00-4/203	Passage - Station Building - Old Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11024	ACTIVE	N	N127-00-4/204	Passage - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44292	ACTIVE	N	N127-00-4/204	Passage - Station Building - Old Street Stn		Asbestos	Sampled – Not Detected				Supalux panel, 1m, to ceiling in Passage 4/204 at Old Street Station			R610526	N	N
16513	ACTIVE	N	N127-00-4/204	Passage - Station Building - Old Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11025	ACTIVE	N	N127-00-4/205	Passage - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16514	ACTIVE	N	N127-00-4/205	Passage - Station Building - Old Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11026	ACTIVE	N	N127-00-4/206	Passage - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18198	ACTIVE	N	N127-00-4/206	Passage - Station Building - Old Street Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11027	ACTIVE	N	N127-00-4/207	Passage - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18828	ACTIVE	N	N127-00-4/207/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn	Caulking	Asbestos	Strongly Presumed				By 4/209 Caulking in tunnel in joints (not visible) behind metal and cellactite sheeting - SP - above False Ceiling					
16515	ACTIVE	N	N127-00-4/207/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Melamine Panels - Non Asbestos					
11028	ACTIVE	N	N127-00-4/208	Passage - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16517	ACTIVE	N	N127-00-4/208/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn	Caulking	Asbestos	Strongly Presumed				Caulking within tunnel ring joints not visible behind -SP. Concrete by 4/211 - above False Ceiling				YES	
16516	ACTIVE	N	N127-00-4/208/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Melamine Panels - Non Asbestos					



# Hazardous Material Asset Register - Summary



## N127-00 - Station Building - Old Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18979	ACTIVE	N	N127-00-4/208/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn	Cellactite Sheeting	Asbestos	Strongly Presumed				Cellactite sheeting above False Ceiling					
11029	ACTIVE	N	N127-00-4/209	Passage - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16608	ACTIVE	N	N127-00-4/209/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn	Cellactite Sheeting	Asbestos	Strongly Presumed				Cellactite sheeting above False Ceiling					
18199	ACTIVE	N	N127-00-4/209/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Melamine Panels - Non Asbestos					
16609	ACTIVE	N	N127-00-4/209/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn	Caulking	Asbestos	Strongly Presumed				Caulking within tunnel ring joints not visible behind - SP - above False Ceiling					
11030	ACTIVE	N	N127-00-4/210	Passage - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16611	ACTIVE	N	N127-00-4/210	Passage - Station Building - Old Street Stn	Caulking	Asbestos	Strongly Presumed				Behind metal arch panels Bottom of escalator 3 metal corrugated sheeting - caulking within tunnel rings not visible but suspected behind rock wool lagging - SP					
16610	ACTIVE	N	N127-00-4/210/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn	Cellactite Sheeting	Asbestos	Strongly Presumed				Cellactite Panels above False Ceiling				YES	
18284	ACTIVE	N	N127-00-4/210/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Melamine Panels - Non Asbestos					
11031	ACTIVE	N	N127-00-4/211	Passage - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16612	ACTIVE	N	N127-00-4/211/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn	Cellactite Sheeting	Asbestos	Strongly Presumed				Cellactite Panels above Metal Ceiling				YES	
11032	ACTIVE	N	N127-00-4/236	Passage - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16613	ACTIVE	N	N127-00-4/236	Passage - Station Building - Old Street Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11033	ACTIVE	N	N127-00-4/237	Lobby - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16614	ACTIVE	N	N127-00-4/237	Lobby - Station Building - Old Street Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11034	ACTIVE	N	N127-00-4/601	Stairs: Linear - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19962	ACTIVE	N	N127-00-4/601	Stairs: Linear - Station Building - Old Street Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N127-00 - Station Building - Old Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11035	ACTIVE	N	N127-00-4/602	Stairs: Spiral - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18285	ACTIVE	N	N127-00-4/602/CLG-01	Ceiling: Solid - 1 - Spiral Stairs - Station Building - Old Street Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Melamine Panels					
16615	ACTIVE	N	N127-00-4/602/CLG-01	Ceiling: Solid - 1 - Spiral Stairs - Station Building - Old Street Stn	Void	Asbestos	Surveyed - Not Detected				Above Metal Ceiling - Corrugated Metal; PVC Cables; Cable Tray; Rock Wool; Fire break, Solid Concrete behind				YES	
11036	ACTIVE	N	N127-00-4/603	Stairs: Linear - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18404	ACTIVE	N	N127-00-4/603/CLG-01	Ceiling: Solid - 1 - Spiral Stairs - Station Building - Old Street Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Melamine Panels					
16616	ACTIVE	N	N127-00-4/603/CLG-01	Ceiling: Solid - 1 - Spiral Stairs - Station Building - Old Street Stn	Void	Asbestos	Surveyed - Not Detected				Above False Ceiling - Corrugated Metal; PVC Cables; Cable Tray; Rock Wool; Fire break, Solid concrete behind				YES	
11037	ACTIVE	N	N127-00-4/604	Stairs: Linear - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16617	ACTIVE	N	N127-00-4/604/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Old Street Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Melamine Panels					
16618	ACTIVE	N	N127-00-4/604/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Old Street Stn	Void	Asbestos	Surveyed - Not Detected				Above False Ceiling - Corrugated Metal; PVC Cables; Cable Tray; Rock Wool; Fire break, Solid Concrete behind				YES	
11038	ACTIVE	N	N127-00-4/731	CER - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18286	ACTIVE	N	N127-00-4/731	CER - Station Building - Old Street Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No access					
11039	ACTIVE	N	N127-00-4/732	CER - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19047	ACTIVE	N	N127-00-4/732	CER - Station Building - Old Street Stn	Other Boarding	Asbestos	Presumed				Distribution Board - Paxoline Backing Board - P					
16619	ACTIVE	N	N127-00-4/732/FLR-01	Floor - 1 - CER - Station Building - Old Street Stn	Void	Asbestos	Surveyed - Not Detected				Beneath Computer Flooring Concrete slab to floor within floor void. New Lino on metal/ wood raised computer tiles to raised floor. Plastic cables, metal conduits, cable management system and firestop and mastic - new throughout. MMMF insulation and debris loose fill within floor void. new electrical boxes throughout. non asbestos containing materials. general rubbish within floor void.					YES



# Hazardous Material Asset Register - Summary



## N127-00 - Station Building - Old Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16484	ACTIVE	N	N127-00-4/732/WAL-004	Wall: Internal - 4 - CER - Station Building - Old Street Stn	Isolator Switches	Asbestos	Strongly Presumed				2no x 60amp Switch Boxes- SP - Asbestos Components within		2			
11040	ACTIVE	N	N127-00-4/761	Computer Equipment Cupboard - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16621	ACTIVE	N	N127-00-4/761	Computer Equipment Cupboard - Station Building - Old Street Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
11041	ACTIVE	N	N127-00-4/762	Computer Equipment Cupboard - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18287	ACTIVE	N	N127-00-4/762	Computer Equipment Cupboard - Station Building - Old Street Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
11042	ACTIVE	N	N127-00-4/763	Computer Equipment Cupboard - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16622	ACTIVE	N	N127-00-4/763	Computer Equipment Cupboard - Station Building - Old Street Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
11043	ACTIVE	N	N127-00-4/764	Computer Equipment Cupboard - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16623	ACTIVE	N	N127-00-4/764	Computer Equipment Cupboard - Station Building - Old Street Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
11044	ACTIVE	N	N127-00-4/765	Computer Equipment Cupboard - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16624	ACTIVE	N	N127-00-4/765	Computer Equipment Cupboard - Station Building - Old Street Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
11045	ACTIVE	N	N127-00-4/766	Computer Equipment Cupboard - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18288	ACTIVE	N	N127-00-4/766	Computer Equipment Cupboard - Station Building - Old Street Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
11046	ACTIVE	N	N127-00-4/791	Passage - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16625	ACTIVE	N	N127-00-4/792	Vent Shaft - Station Building - Old Street Stn	Caulking	Asbestos	Strongly Presumed				Asbestos caulking in tunnel ring joints and flanges has been identified at the station. Therefore, all ring joints must be suspected of containing asbestos. Rings are sealed.					



# Hazardous Material Asset Register - Summary



## N127-00 - Station Building - Old Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18834	ACTIVE	N	N127-00-4/792	Vent Shaft - Station Building - Old Street Stn	Gasket :Pipework	Asbestos	Strongly Presumed				Gaskets & Rope - Vent System & Extractor Fan Motor					
16620	ACTIVE	N	N127-00-4/792	Vent Shaft - Station Building - Old Street Stn	Isolator Switches	Asbestos	Strongly Presumed				Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		2			
11047	ACTIVE	N	N127-00-4/793	Switch Cupboard - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16626	ACTIVE	N	N127-00-4/793	Switch Cupboard - Station Building - Old Street Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
11048	ACTIVE	N	N127-00-4/794	SER - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19048	ACTIVE	N	N127-00-4/794	SER - Station Building - Old Street Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard Panel (Walls)					
16628	ACTIVE	N	N127-00-4/794	SER - Station Building - Old Street Stn	Caulking	Asbestos	Strongly Presumed				Asbestos caulking in tunnel ring joints and flanges has been identified at the station. Therefore, all ring joints must be suspected of containing asbestos. Rings are sealed. 2 samples were taken and found not to contain asbestos. Refer to Report R333201.					
18289	ACTIVE	N	N127-00-4/794/CLG-01	Ceiling: Solid - 1 - SER - Station Building - Old Street Stn	Other Boarding	Asbestos	No Access: Presumed				Above Plasterboard Panel					
16627	ACTIVE	N	N127-00-4/794/CLG-01	Ceiling: Solid - 1 - SER - Station Building - Old Street Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard Panel					
11049	ACTIVE	N	N127-00-5/201	Passage - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16629	ACTIVE	N	N127-00-5/201	Passage - Station Building - Old Street Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11050	ACTIVE	N	N127-00-5/202	Passage - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18290	ACTIVE	N	N127-00-5/202/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Old Street Stn	Void	Asbestos	Surveyed - Not Detected				Concrete; Rock Wool above Tiled Ceiling				YES	
11051	ACTIVE	N	N127-00-5/203	Passage - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16630	ACTIVE	N	N127-00-5/203/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn	Void	Asbestos	Surveyed - Not Detected				New Corrugated Metal, Concrete; PVC Cables above Tiled Ceiling				YES	



# Hazardous Material Asset Register - Summary



## N127-00 - Station Building - Old Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11052	ACTIVE	N	N127-00-5/204	Passage - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16631	ACTIVE	N	N127-00-5/204/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access to high Aug 2014					
11053	ACTIVE	N	N127-00-5/205	Passage - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16632	ACTIVE	N	N127-00-5/205/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Old Street Stn	Void	Asbestos	Surveyed – Not Detected				Above False Ceiling - Metal Corrugated Sheets and Rock Wool Lagging, Plastic Cables. Solid Concrete behind				YES	
11054	ACTIVE	N	N127-00-5/206	Passage - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16633	ACTIVE	N	N127-00-5/206/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Old Street Stn	Void	Asbestos	Surveyed – Not Detected				Above Melamine Panels - Metal Corrugated Sheets and Rock Wool Lagging, Plastic Cables. Solid Concrete behind				YES	
11055	ACTIVE	N	N127-00-5/261	Platform 1 - Northbound Fast - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18291	ACTIVE	N	N127-00-5/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Old Street Stn	Cellactite Sheeting	Asbestos	Strongly Presumed				Additional inspection behind large corrugated metal covers over platform and track Cellactite sheeting					
16634	ACTIVE	N	N127-00-5/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Old Street Stn	Caulking	Asbestos	Strongly Presumed				Caulking within tunnel rings strongly presumed to be present but not visible					
16637	ACTIVE	N	N127-00-5/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Old Street Stn	Cable: Wrap	Asbestos	Strongly Presumed				Platform 1 Invert - Woven cable wrapping at both ends of Invert No Access 2020 Re-inspection - confined space team required					YES
16638	ACTIVE	N	N127-00-5/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Old Street Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - Woven cable insulation (sheath?) on J Hanger 2 No Access 2020 Re-inspection - confined space team required					YES
16636	ACTIVE	N	N127-00-5/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Old Street Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - 4 x Cables 2x10mm / 2x8mm / length of invert on JH3 No Access 2020 Re-inspection - confined space team required					YES
16635	ACTIVE	N	N127-00-5/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Old Street Stn		Asbestos	Surveyed – Not Detected				Platform 1 Invert - New Bitumen Ducts.					YES
11056	ACTIVE	N	N127-00-5/262	Platform 2 - Southbound Fast - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N127-00 - Station Building - Old Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16639	ACTIVE	N	N127-00-5/262	Platform 2 - Southbound Fast - Station Building - Old Street Stn	Isolator Switches	Asbestos	Strongly Presumed				Tail Wall: Switch Box - Insulation within  No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.					
16640	ACTIVE	N	N127-00-5/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - Old Street Stn	Caulking	Asbestos	Strongly Presumed				Caulking within tunnel rings strongly presumed to be present but not visible					
18354	ACTIVE	N	N127-00-5/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - Old Street Stn	Cellactite Sheeting	Asbestos	Strongly Presumed				Additional inspection behind large corrugated metal covers over platform and track Cellactite sheeting					
16641	ACTIVE	N	N127-00-5/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Old Street Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables  Note limited information of exact location of cable (need further details)		2			YES
11057	ACTIVE	N	N127-00-5/263	Platform 3 - Network Rail - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16642	ACTIVE	N	N127-00-5/263	Platform 3 - Network Rail - Station Building - Old Street Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - Network Rail Area					
11058	ACTIVE	N	N127-00-5/264	Platform 4 - Network Rail - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16643	ACTIVE	N	N127-00-5/264	Platform 4 - Network Rail - Station Building - Old Street Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - Network Rail Area					
11059	ACTIVE	N	N127-00-5/411	Disused Room - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19049	ACTIVE	N	N127-00-5/411	Disused Room - Station Building - Old Street Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11060	ACTIVE	N	N127-00-5/412	Disused Room - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16644	ACTIVE	N	N127-00-5/412	Disused Room - Station Building - Old Street Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11061	ACTIVE	N	N127-00-5/661	Switch Cupboard - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Asbestos Free									
16645	ACTIVE	N	N127-00-5/661/CLG-01	Ceiling: Solid - 1 - Switch Cupboard - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
18355	ACTIVE	N	N127-00-5/661/CLG-01	Ceiling: Solid - 1 - Switch Cupboard - Station Building - Old Street Stn	Void	Asbestos	No Access: Presumed				Not possible to inspect above supalux panels at time of survey due to electricians working on equipment				YES	



# Hazardous Material Asset Register - Summary



## N127-00 - Station Building - Old Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11062	ACTIVE	N	N127-00-5/662	Switch Cupboard - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Asbestos Free									
18405	ACTIVE	N	N127-00-5/662/CLG-01	Ceiling: Solid - 1 - Switch Cupboard - Station Building - Old Street Stn	Void	Asbestos	No Access: Presumed				Not possible to inspect above supalux panels at time of survey due to electricians working on equipment				YES	
16646	ACTIVE	N	N127-00-5/662/CLG-01	Ceiling: Solid - 1 - Switch Cupboard - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
11063	ACTIVE	N	N127-00-5/663	Switch Cupboard - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16648	ACTIVE	N	N127-00-5/663/CLG-01	Ceiling: Solid - 1 - Switch Cupboard - Station Building - Old Street Stn	Void	Asbestos	No Access: Presumed				Not possible to inspect above supalux panels at time of survey due to electricians working on equipment				YES	
16647	ACTIVE	N	N127-00-5/663/CLG-01	Ceiling: Solid - 1 - Switch Cupboard - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
11064	ACTIVE	N	N127-00-5/664	Switch Cupboard - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19050	ACTIVE	N	N127-00-5/664/CLG-01	Ceiling: Solid - 1 - Switch Cupboard - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Panels					
16649	ACTIVE	N	N127-00-5/664/CLG-01	Ceiling: Solid - 1 - Switch Cupboard - Station Building - Old Street Stn	Void	Asbestos	No Access: Presumed				Above Supalux Panels				YES	
11065	ACTIVE	N	N127-00-5/665	Switch Cupboard - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16651	ACTIVE	N	N127-00-5/665/CLG-01	Ceiling: Solid - 1 - Switch Cupboard - Station Building - Old Street Stn	Void	Asbestos	No Access: Presumed				Above Supalux Panels				YES	
18356	ACTIVE	N	N127-00-5/665/CLG-01	Ceiling: Solid - 1 - Switch Cupboard - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Panels					
16650	ACTIVE	N	N127-00-5/665/WAL-001	Wall: Internal - 1 - Switch Cupboard - Station Building - Old Street Stn	Isolator Switches	Asbestos	Strongly Presumed				1x Switch box Wall 1 Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
42161	ACTIVE	N	N127-00-5/665/WAL-002	Wall: Internal - 2 - Switch Cupboard - Station Building - Old Street Stn	Isolator Switches	Asbestos	Strongly Presumed				4x Switch boxes Wall 2 Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		4			



# Hazardous Material Asset Register - Summary



## N127-00 - Station Building - Old Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11066	ACTIVE	N	N127-00-5/761	CER - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16652	ACTIVE	N	N127-00-5/761	CER - Station Building - Old Street Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
42162	ACTIVE	N	N127-00-5/761	CER - Station Building - Old Street Stn	Other Boarding	Asbestos	Presumed				Paxoline board					
42163	ACTIVE	N	N127-00-5/761/FLR-01	Floor - 1 - CER - Station Building - Old Street Stn	Cable Duct: Other	Asbestos	Presumed				Cable ducts - No access presumed					
11067	ACTIVE	N	N127-00-5/763	Disused Room - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18406	ACTIVE	N	N127-00-5/763/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Old Street Stn	Boarding: AIB	Asbestos	Known				Amosite - AIB Likely to have AIB damage in the false ceiling from previous cutting of board.					
18835	ACTIVE	N	N127-00-5/763/WAL-001	Wall: Internal - 1 - Disused Room - Station Building - Old Street Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Boarding					
16653	ACTIVE	N	N127-00-5/763/WAL-003	Wall: Internal - 3 - Disused Room - Station Building - Old Street Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Boarding					
11068	ACTIVE	N	N127-00-5/771	Pump Room - Station Building - Old Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18357	ACTIVE	N	N127-00-5/771	Pump Room - Station Building - Old Street Stn	Gasket :Pipework	Asbestos	Presumed				Pumps - Old Gaskets					
16655	ACTIVE	N	N127-00-5/771/CLG-01	Ceiling: Solid - 1 - Pump Room - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux; Rock Wool; PVC Cables above Supalux Tiles					
16654	ACTIVE	N	N127-00-5/771/CLG-01	Ceiling: Solid - 1 - Pump Room - Station Building - Old Street Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
25712	ACTIVE	N	N127-00-5/771/WAL-003	Wall: Internal - 3 - Pump Room - Station Building - Old Street Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x switch box No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
16656	ACTIVE	N	N127-00-5/791	Vent Shaft - Station Building - Old Street Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No access					



# Hazardous Material Asset Register - Summary



## N135-00 - Station Building - London Bridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11309	ACTIVE	N	N135-00-5/713	SER - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N137-00 - Station Building - Borough Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44851	ACTIVE	N	N137-00-0/000/CPY-01	Canopy: Station Entrance - 1 - Station Entrance - Station Building - Borough Stn	Glazing Rope	Asbestos	No Access: Presumed				No Access to Glazing Bars/Rope Seals - SP				N	N
11380	ACTIVE	N	N137-00-1/001	Booking Hall - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16572	ACTIVE	N	N137-00-1/001/CLG-01	Ceiling: Suspended - 1 - Booking Hall - Station Building - Borough Stn	Void	Asbestos	Surveyed – Not Detected				Above False Ceiling - W4 2 x Supalux Panels;				YES	
16573	ACTIVE	N	N137-00-1/001/CLG-01	Ceiling: Suspended - 1 - Booking Hall - Station Building - Borough Stn	Debris: Other	Asbestos	Surveyed – Not Detected				Metal Beams - Sprayed Coating				YES	
16571	ACTIVE	N	N137-00-1/001/CLG-01	Ceiling: Suspended - 1 - Booking Hall - Station Building - Borough Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels					
16570	ACTIVE	N	N137-00-1/001/WAL-001	Wall: Internal - 1 - Booking Hall - Station Building - Borough Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Metal Poster Boards on Plasterboard		3			
18274	ACTIVE	N	N137-00-1/001/WAL-004	Wall: Internal - 4 - Booking Hall - Station Building - Borough Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels		2			
11381	ACTIVE	N	N137-00-1/011	Ticket Office - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
19044	ACTIVE	N	N137-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Borough Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
16574	ACTIVE	N	N137-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Borough Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Brick, Breeze Block; Fibreglass Lagging above False Ceiling				YES	
18275	ACTIVE	N	N137-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Borough Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Rubbish beneath Computer Flooring					YES
11382	ACTIVE	N	N137-00-1/021	POM - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
16575	ACTIVE	N	N137-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Borough Stn	Void	Asbestos	Surveyed – Not Detected				Beneath Computer Flooring					YES



# Hazardous Material Asset Register - Summary



## N137-00 - Station Building - Borough Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11383	ACTIVE	N	N137-00-1/031	Mess Room - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
16577	ACTIVE	N	N137-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Borough Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18401	ACTIVE	N	N137-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Borough Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Plaster; Brick Walls; Metal Ducting & Conduits; Fibreglass Lagging above False Ceiling				YES	
16576	ACTIVE	N	N137-00-1/031/FLR-01	Floor - 1 - Mess Room - Station Building - Borough Stn	Void	Asbestos	Surveyed – Not Detected				concrete below raise floor					YES
18276	ACTIVE	N	N137-00-1/031/WAL-003	Wall: Internal - 3 - Mess Room - Station Building - Borough Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
11384	ACTIVE	N	N137-00-1/036	Toilet: Unisex - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16578	ACTIVE	N	N137-00-1/036	Toilet: Unisex - Station Building - Borough Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11385	ACTIVE	N	N137-00-1/071	Circulation Area - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18277	ACTIVE	N	N137-00-1/071/CLG-01	Ceiling: Suspended - 1 - Circulation Area - Station Building - Borough Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Concrete; Supalux Panels; Plasterboard; Metal Sprayed Coating					
19045	ACTIVE	N	N137-00-1/071/CLG-01	Ceiling: Suspended - 1 - Circulation Area - Station Building - Borough Stn	Void	Asbestos	No Access: Presumed				Beneath Panels of False Ceiling				YES	
16579	ACTIVE	N	N137-00-1/071/FLR-01	Floor - 1 - Circulation Area - Station Building - Borough Stn	Void	Asbestos	No Access: Presumed				No Access - Hatches - Hatch nr 1/631 - Rubber Cables & Concrete beneath tiles					YES
19356	ACTIVE	N	N137-00-1/071/WAL-001	Wall: Internal - 1 - Circulation Area - Station Building - Borough Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel					
16580	ACTIVE	N	N137-00-1/071/WAL-003	Wall: Internal - 3 - Circulation Area - Station Building - Borough Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel Panel above Lift in Shaft					
44852	ACTIVE	N	N137-00-1/136	Lift Shaft - Station Building - Borough Stn	Other Electrical Boxes	Asbestos	Presumed				Small electrical boxes on top of lift cars - Presumed ACM inside (No access on re-inspection - Access to lift shaft required 03-03-2023)				N	N
16569	ACTIVE	N	N137-00-1/136	Lift Shaft - Station Building - Borough Stn	No Access	Asbestos	No Access: Presumed				Lift Shaft: Durasteel Panelling Forming internal structure throughout shafts & Woven cable insulation length of shafts					
16568	ACTIVE	N	N137-00-1/136	Lift Shaft - Station Building - Borough Stn		Asbestos	Surveyed – Not Detected				Lift Cars: Small electrical boxes on top of lift cars					



# Hazardous Material Asset Register - Summary



## N137-00 - Station Building - Borough Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11386	ACTIVE	N	N137-00-1/236	Lobby - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18832	ACTIVE	N	N137-00-1/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Borough Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
16582	ACTIVE	N	N137-00-1/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Borough Stn	Void	Asbestos	Surveyed – Not Detected				Painted Concrete; Brick Walls, Breeze Blocks above Supalux Tiles				YES	
16581	ACTIVE	N	N137-00-1/236/FLR-01	Floor - 1 - Lobby - Station Building - Borough Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath Computer Flooring					YES
11387	ACTIVE	N	N137-00-1/237	Lobby - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16583	ACTIVE	N	N137-00-1/237/FLR-01	Floor - 1 - Lobby - Station Building - Borough Stn	Void	Asbestos	No Access: Presumed				To Hatch - Metal Drain					YES
11388	ACTIVE	N	N137-00-1/281	Station Control Room - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18111	ACTIVE	N	N137-00-1/281/CLG-01	Ceiling: Suspended - 1 - Station Control Room - Station Building - Borough Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plaster & Fibreboard; Boarding					
16425	ACTIVE	N	N137-00-1/281/CLG-01	Ceiling: Suspended - 1 - Station Control Room - Station Building - Borough Stn	Void	Asbestos	Surveyed – Not Detected				Above False Ceiling - Metal Roof - Spray Coating (Also on Pipework & Beams), Concrete; Brick Walls; Metal Trunking & Conduits; Fibreglass Lagging;				YES	
16584	ACTIVE	N	N137-00-1/281/WAL-002	Wall: Internal - 2 - Station Control Room - Station Building - Borough Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
11389	ACTIVE	N	N137-00-1/401	Switch Cupboard - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18396	ACTIVE	N	N137-00-1/401/WAL-002	Wall: Internal - 2 - Switch Cupboard - Station Building - Borough Stn	Isolator Switches	Asbestos	Strongly Presumed				Grey Switch Box 300amp - Insulation within No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
16426	ACTIVE	N	N137-00-1/401/WAL-002	Wall: Internal - 2 - Switch Cupboard - Station Building - Borough Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux & Fibreboard Boxing - Pipes behind; Supalux Panels behind Switch Boxes					
16427	ACTIVE	N	N137-00-1/401/WAL-003	Wall: Internal - 3 - Switch Cupboard - Station Building - Borough Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux & Fibreboard Boxing - Pipes behind, Supalux Panels					
11390	ACTIVE	N	N137-00-1/418	Toilet: Unisex - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N137-00 - Station Building - Borough Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16428	ACTIVE	N	N137-00-1/418	Toilet: Unisex - Station Building - Borough Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
11391	ACTIVE	N	N137-00-1/631	Stairs: Spiral - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18112	ACTIVE	N	N137-00-1/631	Stairs: Spiral - Station Building - Borough Stn	Caulking	Asbestos	Surveyed - Not Detected				Tunnel Rings (No Access Behind) - Solid Caulking					
16429	ACTIVE	N	N137-00-1/631	Stairs: Spiral - Station Building - Borough Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Bottom of Stairs nr 2/733 Supalux Panel					
11392	ACTIVE	N	N137-00-1/662	Store - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16430	ACTIVE	N	N137-00-1/662/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Borough Stn	Debris: Other	Asbestos	Surveyed - Not Detected				Sprayed Coating - Ceiling Level and Beams to Ceiling					
11393	ACTIVE	N	N137-00-2/201	Passage - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
18971	ACTIVE	N	N137-00-2/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Borough Stn	Void	Asbestos	Surveyed - Not Detected				Above Ceiling without damage to Tiles				YES	
11394	ACTIVE	N	N137-00-2/202	Passage - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
16431	ACTIVE	N	N137-00-2/202	Passage - Station Building - Borough Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11395	ACTIVE	N	N137-00-2/203	Passage - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18113	ACTIVE	N	N137-00-2/203/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Borough Stn	Void	Asbestos	No Access: Presumed				Above Metal Strip, Plaster				YES	
16432	ACTIVE	N	N137-00-2/203/FLR-01	Floor - 1 - Passage - Station Building - Borough Stn	Void	Asbestos	No Access: Presumed				7 x Hatches - No Access through Hatches - without causing damage					YES
11396	ACTIVE	N	N137-00-2/236	Lobby - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18825	ACTIVE	N	N137-00-2/236/WAL-003	Wall: Internal - 3 - Lobby - Station Building - Borough Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Panel					
11397	ACTIVE	N	N137-00-2/261	Platform 1 - Northbound Fast - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N137-00 - Station Building - Borough Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16435	ACTIVE	N	N137-00-2/261	Platform 1 - Northbound Fast - Station Building - Borough Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse Box nr 2/711 No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
16434	ACTIVE	N	N137-00-2/261	Platform 1 - Northbound Fast - Station Building - Borough Stn	Cable: Sheath	Asbestos	Known				2x10mm Cable going into Track nr 2/711 Reinspected 03-03-2023					
43222	INACTIVE	N	N137-00-2/261	Platform 1 - Northbound Fast - Station Building - Borough Stn	Westing house Boxes	Asbestos	Presumed				DUPLICATE OF 16435 03-03-23 White Westing house box No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1		N	N
16433	ACTIVE	N	N137-00-2/261	Platform 1 - Northbound Fast - Station Building - Borough Stn	Other Boarding	Asbestos	Known				3 sides Horizontal Boxing - Chrysotile nr 2/711 Photo as below as shows other end of platform Re-inspected 03-03-23					
16436	ACTIVE	N	N137-00-2/261/ FLR-01	Floor - 1 - Platform 1 - Station Building - Borough Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Platform 1 Invert Cable Sleeves. Survey 23/03/05 Tested Ducts by Dividing wall - NAD - Bitumen No access during 2023 Re-inspection as confined space team required					YES
11398	ACTIVE	N	N137-00-2/601	Stairs: Linear - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16437	ACTIVE	N	N137-00-2/601	Stairs: Linear - Station Building - Borough Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11399	ACTIVE	N	N137-00-2/602	Stairs: Linear - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18114	ACTIVE	N	N137-00-2/602	Stairs: Linear - Station Building - Borough Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11400	ACTIVE	N	N137-00-2/603	Stairs: Linear - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16438	ACTIVE	N	N137-00-2/603	Stairs: Linear - Station Building - Borough Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11401	ACTIVE	N	N137-00-2/604	Stairs: Linear - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16439	ACTIVE	N	N137-00-2/604	Stairs: Linear - Station Building - Borough Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
16440	ACTIVE	N	N137-00-2/636	Overbridge - Station Building - Borough Stn	Lead/Leading	Lead Paint/Lead	Known				RSJ Cream Gloss Analysis 1.56%					



# Hazardous Material Asset Register - Summary



## N137-00 - Station Building - Borough Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18972	ACTIVE	N	N137-00-2/636/FLR-01	Floor - 1 - Overbridge - Station Building - Borough Stn	Void	Asbestos	No Access: Presumed				Hatches - No Access through Hatches - without causing damage		7			YES
11402	ACTIVE	N	N137-00-2/661	Switch Room - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18115	ACTIVE	N	N137-00-2/661/FLR-01	Floor - 1 - Switch Room - Station Building - Borough Stn	Void	Asbestos	No Access: Presumed				No Access beneath metal check plate					YES
16441	ACTIVE	N	N137-00-2/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Borough Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux & 2 Suplax Panels on top of Board					
11403	ACTIVE	N	N137-00-2/662	Switch Room - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
44854	ACTIVE	N	N137-00-2/662	Switch Room - Station Building - Borough Stn	Other Electrical Boxes	Asbestos	Removed				Blue Trunking & Electrical Equipment - Insulation within Not present during 2023 reinspection				N	N
44855	ACTIVE	N	N137-00-2/662	Switch Room - Station Building - Borough Stn	Other Electrical Boxes	Asbestos	Removed				3no Blue & 1no Grey Switch Boxes on Metal Frame - Insulation within Not present during 2023 reinspection				N	N
16442	ACTIVE	N	N137-00-2/662	Switch Room - Station Building - Borough Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11404	ACTIVE	N	N137-00-2/663	Switch Cupboard - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
44856	ACTIVE	N	N137-00-2/663	Switch Cupboard - Station Building - Borough Stn	Other Electrical Boxes	Asbestos	Removed				Grey Trunking - Insulation within Not present in 2023 reinspection				N	N
44857	ACTIVE	N	N137-00-2/663/WAL-002	Wall: Internal - 2 - Switch Cupboard - Station Building - Borough Stn	Other Electrical Boxes	Asbestos	Removed				3no Grey Switch Boxes - Insulation within Not present in 2023 reinspection		3		N	N
16443	ACTIVE	N	N137-00-2/663/WAL-004	Wall: Internal - 4 - Switch Cupboard - Station Building - Borough Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Panel above Door					
11405	ACTIVE	N	N137-00-2/665	Switch Cupboard - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16444	ACTIVE	N	N137-00-2/665/WAL-003	Wall: Internal - 3 - Switch Cupboard - Station Building - Borough Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux & 2 Suplax Panels on top of Board					
11406	ACTIVE	N	N137-00-2/666	Switch Cupboard - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18116	ACTIVE	N	N137-00-2/666	Switch Cupboard - Station Building - Borough Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N137-00 - Station Building - Borough Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11407	ACTIVE	N	N137-00-2/667	Switch Cupboard - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16445	ACTIVE	N	N137-00-2/667	Switch Cupboard - Station Building - Borough Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
11408	ACTIVE	N	N137-00-2/668	Switch Cupboard - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16446	ACTIVE	N	N137-00-2/668	Switch Cupboard - Station Building - Borough Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
11409	ACTIVE	N	N137-00-2/711	Relay Room - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16447	ACTIVE	N	N137-00-2/711	Relay Room - Station Building - Borough Stn	Vinyl tiles	Asbestos	Known				Green/ Light Grey Vinyl Tiles Some tiles removed Reinspected in 2023					
16519	ACTIVE	N	N137-00-2/711	Relay Room - Station Building - Borough Stn	Cable: Sheath	Asbestos	Known				10mm Cable going into Track from relay room via platform Reinspected 03-03-2023		2			
44323	ACTIVE	N	N137-00-2/711	Relay Room - Station Building - Borough Stn	Other Boarding	Asbestos	Presumed				Paxoline boarding wall 1 & 3 Reinspected 03-03-23					
43219	ACTIVE	N	N137-00-2/711/ WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Borough Stn	Cable: Sheath	Asbestos	Presumed				known asbestos braided cable x2 running along rack to wall 1 Reinspected 03-03-2023				N	N
16520	INACTIVE	N	N137-00-2/711/ WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Borough Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				PCB's -Fair Condition. Serial Nos. 186493; 186491; 186474; 186510		4			
18200	ACTIVE	N	N137-00-2/711/ WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Borough Stn	Boarding: Cement	Asbestos	Strongly Presumed				Boarding to Racking Under PCB's Reinspection 2023					
18117	ACTIVE	N	N137-00-2/711/ WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Borough Stn	Westing house Boxes	Asbestos	Strongly Presumed				600v WB & SC Ltd westernhouse box- Insulation within - wall2  No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
16518	ACTIVE	N	N137-00-2/711/ WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Borough Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es)  No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
16448	ACTIVE	N	N137-00-2/711/ WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Borough Stn	Other Boarding	Asbestos	Removed				Brown composite board to wall 4 Not present during 2023 reinspection		1			
11410	ACTIVE	N	N137-00-2/731	CER - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16521	ACTIVE	N	N137-00-2/731/ FLR-01	Floor - 1 - CER - Station Building - Borough Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath Computer Flooring					YES



# Hazardous Material Asset Register - Summary



## N137-00 - Station Building - Borough Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16522	ACTIVE	N	N137-00-2/731/WAL-004	Wall: Internal - 4 - CER - Station Building - Borough Stn	Isolator Switches	Asbestos	Strongly Presumed				Grey Switch Boxes 60amps - Insulation within  No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within.		2			
11411	ACTIVE	N	N137-00-2/732	Switch Cupboard - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18201	ACTIVE	N	N137-00-2/732	Switch Cupboard - Station Building - Borough Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11412	ACTIVE	N	N137-00-2/733	Switch Room - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18202	ACTIVE	N	N137-00-2/733	Switch Room - Station Building - Borough Stn	Caulking	Asbestos	Surveyed - Not Detected				Caulking within Tunnel Rings					
16523	ACTIVE	N	N137-00-2/733/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Borough Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Panels					
16524	ACTIVE	N	N137-00-2/733/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Borough Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Boxing					
11413	ACTIVE	N	N137-00-2/734	Computer Equipment Cupboard - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16525	ACTIVE	N	N137-00-2/734	Computer Equipment Cupboard - Station Building - Borough Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
11414	ACTIVE	N	N137-00-2/901	Disused Room - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19354	ACTIVE	N	N137-00-2/901	Disused Room - Station Building - Borough Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11415	ACTIVE	N	N137-00-3/081	Pump Room - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16526	ACTIVE	N	N137-00-3/081	Pump Room - Station Building - Borough Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11416	ACTIVE	N	N137-00-3/262	Platform 2 - Southbound Fast - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16527	ACTIVE	N	N137-00-3/262	Platform 2 - Southbound Fast - Station Building - Borough Stn	Cable: Sheath	Asbestos	Known				10mm Cable going into Cable Run Reinspection 2023		1			
18203	ACTIVE	N	N137-00-3/262	Platform 2 - Southbound Fast - Station Building - Borough Stn	Other Boarding	Asbestos	Known				Chrysotile Boarding - nr 3/711 Reinspectws 2023					



# Hazardous Material Asset Register - Summary



## N137-00 - Station Building - Borough Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16528	INACTIVE	N	N137-00-3/262	Platform 2 - Southbound Fast - Station Building - Borough Stn	Cable: Sheath	Asbestos	Known				DUPLICATE TO 16527 10mm Cable going into Track nr 3/711		1			
18399	ACTIVE	N	N137-00-3/262/ FLR-01	Floor - 1 - Platform 2 - Station Building - Borough Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Platform 2 Invert. Cable Sleeves  No access during 2023 re-inspection as confined space team required					YES
11417	ACTIVE	N	N137-00-3/406	Store - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18829	ACTIVE	N	N137-00-3/406	Store - Station Building - Borough Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11418	ACTIVE	N	N137-00-3/711	Relay Room - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16529	ACTIVE	N	N137-00-3/711	Relay Room - Station Building - Borough Stn	Cable: Sheath	Asbestos	Strongly Presumed				10mm Cable going into Track Reinspected 2023		1			
44853	ACTIVE	N	N137-00-3/711	Relay Room - Station Building - Borough Stn	Cable: Wrap	Asbestos	Strongly Presumed				1x10mm Cable Reinspected 2023		1		N	N
18980	ACTIVE	N	N137-00-3/711	Relay Room - Station Building - Borough Stn	Cable: Sheath	Asbestos	Strongly Presumed				vinyl tiles all walls Reinspected 2023		1			
43224	ACTIVE	N	N137-00-3/711/ WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Borough Stn	Boarding: Cement	Asbestos	Presumed				Board under PCB's Reinspected 2023				N	N
43225	ACTIVE	N	N137-00-3/711/ WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Borough Stn	Other Electrical Boxes	Asbestos	Presumed				600 V box silver  No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within.				N	N
16530	INACTIVE	N	N137-00-3/711/ WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Borough Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				PCB's - Good Condition. Serial Nos. 186464; 186476; 186499; 168198; 186516; 392280, 186198, 188516		6			
11419	ACTIVE	N	N137-00-3/733	CER - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16534	ACTIVE	N	N137-00-3/733/ CLG-01	Ceiling: Solid - 1 - CER - Station Building - Borough Stn	Void	Asbestos	No Access: Presumed				Beneath False Ceiling				YES	
16533	ACTIVE	N	N137-00-3/733/ CLG-01	Ceiling: Solid - 1 - CER - Station Building - Borough Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
18204	ACTIVE	N	N137-00-3/733/ WAL-001	Wall: Internal - 1 - CER - Station Building - Borough Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Partition Wall - Supalux					
16531	ACTIVE	N	N137-00-3/733/ WAL-002	Wall: Internal - 2 - CER - Station Building - Borough Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Partition Wall - Supalux					



# Hazardous Material Asset Register - Summary



## N137-00 - Station Building - Borough Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18205	ACTIVE	N	N137-00-3/733/WAL-003	Wall: Internal - 3 - CER - Station Building - Borough Stn	Isolator Switches	Asbestos	Strongly Presumed				Grey Switch Box 60amp - Insulation within  No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
16532	ACTIVE	N	N137-00-3/733/WAL-004	Wall: Internal - 4 - CER - Station Building - Borough Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Partition Wall - Supalux					
11420	ACTIVE	N	N137-00-A/131	LMR - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16536	ACTIVE	N	N137-00-A/131	LMR - Station Building - Borough Stn	Isolator Switches	Asbestos	Removed				Facing Borough High Street - 3 Grey Switch Boxes - Insulation within		3			
19041	ACTIVE	N	N137-00-A/131	LMR - Station Building - Borough Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Lift Motor, Gearbox and Brake Assembly - Gaskets & Rope Seal. Not possible to reinspect as isolations/engineer required to inspect within. 2023					
16541	ACTIVE	N	N137-00-A/131/FLR-01	Floor - 1 - LMR - Station Building - Borough Stn	Durasteel	Asbestos	Presumed				Lid to Storage Bin Reinspected 2023		1			
16535	ACTIVE	N	N137-00-A/131/FLR-01	Floor - 1 - LMR - Station Building - Borough Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Facing Borough High Street - Supalux Panel					
16537	ACTIVE	N	N137-00-A/131/WAL-001	Wall: Internal - 1 - LMR - Station Building - Borough Stn	Other Electrical Boxes	Asbestos	Surveyed – Not Detected				Busbar Chamber. Type 3 States Non Asbestos		2			
16539	ACTIVE	N	N137-00-A/131/WAL-004	Wall: Internal - 4 - LMR - Station Building - Borough Stn	Other Electrical Boxes	Asbestos	Surveyed – Not Detected				H/way Box No 2&1 - Auto Control 1 & 2 - Insulation within - Type 3 States Non Asbestos					
16540	ACTIVE	N	N137-00-A/131/WAL-004	Wall: Internal - 4 - LMR - Station Building - Borough Stn	Other Electrical Boxes	Asbestos	Surveyed – Not Detected				Controllers - Insulation within - Type 3 States Non Asbestos		2			
16538	ACTIVE	N	N137-00-A/131/WAL-004	Wall: Internal - 4 - LMR - Station Building - Borough Stn	Other Electrical Boxes	Asbestos	Surveyed – Not Detected				Fuse Box - Insulation within - Type 3 States Non Asbestos		1			
18206	ACTIVE	N	N137-00-A/131/WAL-050	Wall: Internal - 50 - LMR - Station Building - Borough Stn	Other Electrical Boxes	Asbestos	Removed				Not present in 2023 reinspected  Transformer Box (Redundant)  No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
11421	ACTIVE	N	N137-00-A/236	Passage - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18830	ACTIVE	N	N137-00-A/236	Passage - Station Building - Borough Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
11422	ACTIVE	N	N137-00-A/316	Lobby - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N137-00 - Station Building - Borough Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16544	ACTIVE	N	N137-00-A/316/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Borough Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling				YES	
16543	ACTIVE	N	N137-00-A/316/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Borough Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux & Plasterboard Boxing					
16542	ACTIVE	N	N137-00-A/316/FLR-01	Floor - 1 - Lobby - Station Building - Borough Stn	Void	Asbestos	No Access: Presumed				Beneath Quarry Tiles; Wooden False Floor					YES
11423	ACTIVE	N	N137-00-A/317	Locker Room - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16545	ACTIVE	N	N137-00-A/317	Locker Room - Station Building - Borough Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
11424	ACTIVE	N	N137-00-A/331	Mess Room - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16546	ACTIVE	N	N137-00-A/331	Mess Room - Station Building - Borough Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
11425	ACTIVE	N	N137-00-A/576	Stairs: Linear - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16547	ACTIVE	N	N137-00-A/576/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Borough Stn	Void	Asbestos	Surveyed - Not Detected				Above Entrance - Metal Beam - Sprayed Coating above Metal Ceiling				YES	
18207	ACTIVE	N	N137-00-A/576/WAL-003	Wall: Internal - 3 - Linear Stairs - Station Building - Borough Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Board Panels					
11426	ACTIVE	N	N137-00-A/663	Switch Room - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
11427	ACTIVE	N	N137-00-A/664	Switch Room - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16548	ACTIVE	N	N137-00-A/664	Switch Room - Station Building - Borough Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
11428	ACTIVE	N	N137-00-A/665	Switch Room - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16549	ACTIVE	N	N137-00-A/665	Switch Room - Station Building - Borough Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
11429	ACTIVE	N	N137-00-A/731	CER - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18400	ACTIVE	N	N137-00-A/731	CER - Station Building - Borough Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					



# Hazardous Material Asset Register - Summary



## N137-00 - Station Building - Borough Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11430	ACTIVE	N	N137-00-A/746	SCR - Station Building - Borough Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19042	ACTIVE	N	N137-00-A/746/CLG-01	Ceiling: Solid - 1 - SCR - Station Building - Borough Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	
16567	ACTIVE	N	N137-00/CPY-01	Canopy - 1 - Station Building - Borough Stn	Glazing Rope	Asbestos	No Access: Presumed				No Access to Glazing Bars/Rope Seals					

## N143-00 - Station Building - Kennington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
45089	ACTIVE	N	N143-00-0/001/CPY-02	Canopy: Station Entrance - 1 - Station Entrance - Station Building - Kennington Stn	Lead/Leading	Lead Paint/Lead	Known				Blue Gloss Coating				N	N
11441	ACTIVE	N	N143-00-1/001	Booking Hall - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18821	ACTIVE	N	N143-00-1/001/CLG-01	Ceiling: Suspended - 1 - Booking Hall - Station Building - Kennington Stn	Other Boarding	Asbestos	Presumed				Panel underneath Glass Ceiling - No Access					
11442	ACTIVE	N	N143-00-1/011	Ticket Office - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42587	ACTIVE	N	N143-00-1/011	Ticket Office - Station Building - Kennington Stn		Asbestos	Sampled – Not Detected				Mastic/putty, throughout, to flu pipe and ducting joints above ticket office window in Ticket Office			R512676	N	N
16342	ACTIVE	N	N143-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Kennington Stn	Glazing Rope	Asbestos	Known				Rope seal inside glazing bars - Chrysotile					
18965	ACTIVE	N	N143-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Kennington Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Plaster, Solid above False Ceiling				YES	
42586	ACTIVE	N	N143-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Kennington Stn	Mastic	Asbestos	Sampled – Not Detected				Mastic/putty, throughout, to flu pipe and ducting joints within false ceiling in Ticket Office			R512676	Y	N
16343	ACTIVE	N	N143-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Kennington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles; Wooden Soffit Boards					
18330	ACTIVE	N	N143-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Kennington Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden False Floor, Computer Flooring				YES	
11443	ACTIVE	N	N143-00-1/021	POM - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N143-00 - Station Building - Kennington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17965	ACTIVE	N	N143-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Kennington Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
11444	ACTIVE	N	N143-00-1/031	Mess Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16345	ACTIVE	N	N143-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Kennington Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard					
16346	ACTIVE	N	N143-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Kennington Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux					
18029	ACTIVE	N	N143-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Kennington Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling				YES	
16344	ACTIVE	N	N143-00-1/031/WAL-002	Wall: Internal - 2 - Mess Room - Station Building - Kennington Stn	LUL Heaters	Asbestos	Surveyed - Not Detected				Heater - Foam Insulation Board					
11445	ACTIVE	N	N143-00-1/036	Lobby - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16348	ACTIVE	N	N143-00-1/036/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Kennington Stn	Void	Asbestos	Surveyed - Not Detected				Concrete; Plaster, Solid above false ceiling				YES	
16347	ACTIVE	N	N143-00-1/036/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Kennington Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Boarding					
11446	ACTIVE	N	N143-00-1/037	Toilet: Unisex - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16351	ACTIVE	N	N143-00-1/037/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Kennington Stn	Void	Asbestos	Surveyed - Not Detected				Concrete; Plaster, Solid above false ceiling				YES	
16350	ACTIVE	N	N143-00-1/037/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Kennington Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Boarding					
16349	ACTIVE	N	N143-00-1/037/FLR-01	Floor - 1 - Toilet - Station Building - Kennington Stn	Void	Asbestos	No Access: Presumed				To Manholes beneath Quarry Tiles					
11447	ACTIVE	N	N143-00-1/071	Circulation Area - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18030	ACTIVE	N	N143-00-1/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Kennington Stn	Glazing Rope	Asbestos	Strongly Presumed				Rope Seal behind glazing bars					



# Hazardous Material Asset Register - Summary



## N143-00 - Station Building - Kennington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11448	ACTIVE	N	N143-00-1/082	Lobby - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16352	ACTIVE	N	N143-00-1/082	Lobby - Station Building - Kennington Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction (see 1/632)					
11449	ACTIVE	N	N143-00-1/132	LMR - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45090	ACTIVE	N	N143-00-1/132	LMR - Station Building - Kennington Stn	Rope Gaskets	Asbestos	Strongly Presumed				Lift Motor, Gearbox and Brake Assembly - Gaskets & Rope Seal				N	N
16353	ACTIVE	N	N143-00-1/136	Lift Shaft - Station Building - Kennington Stn	No Access	Asbestos	No Access: Presumed				Shaft not surveyed - Identical from Borough					
20018	ACTIVE	N	N143-00-1/136/CLG-01	Ceiling: Solid - 1 - Lift Shaft - Station Building - Kennington Stn		Asbestos	Surveyed – Not Detected				Lift Cars					
11450	ACTIVE	N	N143-00-1/237	Lobby - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16354	ACTIVE	N	N143-00-1/237/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Kennington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding					
16355	ACTIVE	N	N143-00-1/237/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Kennington Stn	Void	Asbestos	Surveyed – Not Detected				Supalux above Supalux Board				YES	
11451	ACTIVE	N	N143-00-1/238	Passage - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19353	ACTIVE	N	N143-00-1/238	Passage - Station Building - Kennington Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction (see 1/632)					
11452	ACTIVE	N	N143-00-1/317	Locker Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18031	ACTIVE	N	N143-00-1/317	Locker Room - Station Building - Kennington Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
11453	ACTIVE	N	N143-00-1/318	Locker Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16356	ACTIVE	N	N143-00-1/318	Locker Room - Station Building - Kennington Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
11454	ACTIVE	N	N143-00-1/333	Mess Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N143-00 - Station Building - Kennington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16357	ACTIVE	N	N143-00-1/333	Mess Room - Station Building - Kennington Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
11455	ACTIVE	N	N143-00-1/412	Store - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16359	ACTIVE	N	N143-00-1/412/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Kennington Stn	Void	Asbestos	No Access: Presumed				Above Supalux Ceiling				YES	
16358	ACTIVE	N	N143-00-1/412/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Kennington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
11456	ACTIVE	N	N143-00-1/417	Toilet: Male - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16361	ACTIVE	N	N143-00-1/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Kennington Stn	Void	Asbestos	Surveyed – Not Detected				Wooden Boarding; Fibreglass Lagging above Supalux Tiles				YES	
16360	ACTIVE	N	N143-00-1/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Kennington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18032	ACTIVE	N	N143-00-1/417/FLR-01	Floor - 1 - Toilet - Station Building - Kennington Stn	Void	Asbestos	No Access: Presumed				To Manholes beneath Quarry Tiles					YES
11457	ACTIVE	N	N143-00-1/418	Toilet: Female - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16362	ACTIVE	N	N143-00-1/418/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Kennington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
16363	ACTIVE	N	N143-00-1/418/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Kennington Stn	Void	Asbestos	Surveyed – Not Detected				Wooden Boarding; Fibreglass Lagging above Supalux Tiles				YES	
11458	ACTIVE	N	N143-00-1/576	Ladder - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18461	ACTIVE	N	N143-00-1/576	Ladder - Station Building - Kennington Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
11459	ACTIVE	N	N143-00-1/601	Train Maintainers Office - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18966	ACTIVE	N	N143-00-1/601	Train Maintainers Office - Station Building - Kennington Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					



# Hazardous Material Asset Register - Summary



## N143-00 - Station Building - Kennington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11460	ACTIVE	N	N143-00-1/602	Office - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18033	ACTIVE	N	N143-00-1/602	Office - Station Building - Kennington Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
11461	ACTIVE	N	N143-00-1/631	Stairs: Spiral - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42178	ACTIVE	N	N143-00-1/631	Stairs: Spiral - Station Building - Kennington Stn		Asbestos	Surveyed – Not Detected				Central Core of Spiral Stairs - None visible ES7879 Confirms no asbestos				N	N
16365	ACTIVE	N	N143-00-1/631	Stairs: Spiral - Station Building - Kennington Stn	Lead/Leading	Lead Paint/Lead	Known				White Gloss Top and Bottom of Stairs. Thickness 6.10mm: Analysis 1.81%; Thickness 9.10mm: Analysis 26.7%					
16364	ACTIVE	N	N143-00-1/631	Stairs: Spiral - Station Building - Kennington Stn	No Access	Lead Paint/Lead	Known									
11462	ACTIVE	N	N143-00-1/633	Passage - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16366	ACTIVE	N	N143-00-1/633/ FLR-01	Floor - 1 - Passage - Station Building - Kennington Stn	Void	Asbestos	No Access: Presumed				Beneath Manholes					YES
18034	ACTIVE	N	N143-00-1/633/ WAL-004	Wall: Internal - 4 - Passage - Station Building - Kennington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board; Supalux Boarding above door to 1/632					
11463	ACTIVE	N	N143-00-1/661	Station Control Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16367	ACTIVE	N	N143-00-1/661/ CLG-01	Ceiling: Suspended - 1 - Station Control Room - Station Building - Kennington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel					
45091	ACTIVE	N	N143-00-1/661/ WAL-003	Wall: Internal - 3 - Station Control Room - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				7no Dark Blue Switch Box - Insulation within		7		N	N
11464	ACTIVE	N	N143-00-1/666	Service Riser - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16368	ACTIVE	N	N143-00-1/666/ CLG-01	Ceiling: Solid - 1 - Service Riser - Station Building - Kennington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel					
45092	ACTIVE	N	N143-00-1/666/ WAL-003	Wall: Internal - 3 - Service Riser - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1no Red, 1no Grey & 5no Blue Switch Boxes - Insulation within		7		N	N
11465	ACTIVE	N	N143-00-1/667	Switch Cupboard - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N143-00 - Station Building - Kennington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16369	ACTIVE	N	N143-00-1/667/WAL-001	Wall: Internal - 1 - Switch Cupboard - Station Building - Kennington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding					
18035	ACTIVE	N	N143-00-1/667/WAL-002	Wall: Internal - 2 - Switch Cupboard - Station Building - Kennington Stn	Isolator Switches	Asbestos	Strongly Presumed				Grey Switch Box - Insulation within 300amp		1			
16370	ACTIVE	N	N143-00-1/667/WAL-002	Wall: Internal - 2 - Switch Cupboard - Station Building - Kennington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding behind Electrical Box		2			
18967	ACTIVE	N	N143-00-1/667/WAL-004	Wall: Internal - 4 - Switch Cupboard - Station Building - Kennington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding					
11466	ACTIVE	N	N143-00-1/668	Switch Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16371	ACTIVE	N	N143-00-1/668	Switch Room - Station Building - Kennington Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
11467	ACTIVE	N	N143-00-1/669	Switch Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16372	ACTIVE	N	N143-00-1/669	Switch Room - Station Building - Kennington Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
11468	ACTIVE	N	N143-00-1/731	CER - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16373	ACTIVE	N	N143-00-1/731	CER - Station Building - Kennington Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
11469	ACTIVE	N	N143-00-1/747	SCR - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16374	ACTIVE	N	N143-00-1/747	SCR - Station Building - Kennington Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
11470	ACTIVE	N	N143-00-2/137	Fan Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42181	ACTIVE	N	N143-00-2/137	Fan Room - Station Building - Kennington Stn		Asbestos	Surveyed – Not Detected				Fan room beneath lift path - no known asbestos					
16376	ACTIVE	N	N143-00-2/137	Fan Room - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Known				Braided cable to Wall Fan. Braided cable to wall fan cut back to wall and Encapsulated		1			
11471	ACTIVE	N	N143-00-2/201	Passage - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N143-00 - Station Building - Kennington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42180	ACTIVE	N	N143-00-2/201	Passage - Station Building - Kennington Stn	No Access	Asbestos	Surveyed – Not Detected				Concrete services shaft runs beneath public passageway					
16377	ACTIVE	N	N143-00-2/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Kennington Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard; Supalux Panel					
11472	ACTIVE	N	N143-00-2/202	Passage - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18036	ACTIVE	N	N143-00-2/202/FLR-01	Floor - 1 - Passage - Station Building - Kennington Stn	Void	Asbestos	No Access: Presumed				No Access through Manhole					YES
11473	ACTIVE	N	N143-00-2/203	Passage - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16378	ACTIVE	N	N143-00-2/203	Passage - Station Building - Kennington Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11474	ACTIVE	N	N143-00-2/204	Passage - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16379	ACTIVE	N	N143-00-2/204/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Kennington Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
11475	ACTIVE	N	N143-00-2/601	Stairs: Linear - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16380	ACTIVE	N	N143-00-2/601	Stairs: Linear - Station Building - Kennington Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11476	ACTIVE	N	N143-00-2/602	Stairs: Linear - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18968	ACTIVE	N	N143-00-2/602	Stairs: Linear - Station Building - Kennington Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11477	ACTIVE	N	N143-00-2/603	Stairs: Linear - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16381	ACTIVE	N	N143-00-2/603	Stairs: Linear - Station Building - Kennington Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11478	ACTIVE	N	N143-00-2/604	Stairs: Linear - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18822	ACTIVE	N	N143-00-2/604	Stairs: Linear - Station Building - Kennington Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N143-00 - Station Building - Kennington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11479	ACTIVE	N	N143-00-2/661	Switch Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18332	ACTIVE	N	N143-00-2/661/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Kennington Stn	Void	Asbestos	No Access: Presumed				Above Supalux Ceiling				YES	
18037	ACTIVE	N	N143-00-2/661/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Kennington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
18331	ACTIVE	N	N143-00-2/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Kennington Stn	Caulking	Asbestos	Known				Tunnel Rings - Paint on Tunnel Rings Chrysotile					
11480	ACTIVE	N	N143-00-2/776	Fan Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18038	ACTIVE	N	N143-00-2/776	Fan Room - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Strongly Presumed				1m Cable Unencapsulated		1			
45093	ACTIVE	N	N143-00-2/776	Fan Room - Station Building - Kennington Stn	Gasket :Pipework	Asbestos	Strongly Presumed						4		N	N
11481	ACTIVE	N	N143-00-3/081	Lobby - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45095	ACTIVE	N	N143-00-3/081	Lobby - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				1x fuse switch box to tunnel rings		1		N	N
45096	ACTIVE	N	N143-00-3/081	Lobby - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				1x fire isolation equipment		1		N	N
45094	ACTIVE	N	N143-00-3/081	Lobby - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				1x transformer unit to wall		1		N	N
16383	ACTIVE	N	N143-00-3/081/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Kennington Stn	Caulking	Asbestos	Known				Tunnel Ring - Caulking - Chrysotile/ Amphibole ENCAPSULATED					
16382	ACTIVE	N	N143-00-3/081/WAL-001	Wall: Internal - 1 - Lobby - Station Building - Kennington Stn	Caulking	Asbestos	Known				Tunnel Ring - Caulking - Chrysotile/ Amphibole ENCAPSULATED					
18823	ACTIVE	N	N143-00-3/081/WAL-007	Wall: Internal - 7 - Lobby - Station Building - Kennington Stn	Caulking	Asbestos	Known				Switch box 60 amp					
11482	ACTIVE	N	N143-00-3/201	Passage - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16384	ACTIVE	N	N143-00-3/201	Passage - Station Building - Kennington Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N143-00 - Station Building - Kennington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11483	ACTIVE	N	N143-00-3/202	Passage - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16385	ACTIVE	N	N143-00-3/202	Passage - Station Building - Kennington Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11484	ACTIVE	N	N143-00-3/203	Passage - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18039	ACTIVE	N	N143-00-3/203	Passage - Station Building - Kennington Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11485	ACTIVE	N	N143-00-3/204	Passage - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16386	ACTIVE	N	N143-00-3/204	Passage - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Strongly Presumed				Ducts with 16mm woven Cables		5			
11486	ACTIVE	N	N143-00-3/236	Passage - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45113	ACTIVE	N	N143-00-3/236	Passage - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				2x orange fuse switch boxes to wall		2		N	N
45117	ACTIVE	N	N143-00-3/236	Passage - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				2x pump supply fuse boxes to wall		2		N	N
45111	ACTIVE	N	N143-00-3/236	Passage - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				1x combination fuse switch box to wall LHS by door		1		N	N
16388	ACTIVE	N	N143-00-3/236	Passage - Station Building - Kennington Stn	Boarding: Cement	Asbestos	Known				White boarding behind Electrical Equipment - Chrysotile					
16387	ACTIVE	N	N143-00-3/236	Passage - Station Building - Kennington Stn	Caulking	Asbestos	Known				Wall - Tunnel Ring - Caulking - Chrysotile - ENCAPSULATED					
45114	ACTIVE	N	N143-00-3/236	Passage - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				2x pump supply fuse switches to wall		2		N	N
45118	ACTIVE	N	N143-00-3/236	Passage - Station Building - Kennington Stn	Other Boarding	Asbestos	Presumed				6x distribution boards and combination fuse switch boxes to wall		6		N	N
45106	ACTIVE	N	N143-00-3/236	Passage - Station Building - Kennington Stn	Other Boarding	Asbestos	Known				Board to pump supply fuse switches				N	N
45107	ACTIVE	N	N143-00-3/236	Passage - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Known				2x braided cables to cable run going into room 3/415		2		N	N
45108	ACTIVE	N	N143-00-3/236	Passage - Station Building - Kennington Stn	Other Boarding	Asbestos	Known				Board to pump supply fuse boxes				N	N
45116	ACTIVE	N	N143-00-3/236	Passage - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				1x trans rec unit to wall		1		N	N



# Hazardous Material Asset Register - Summary



## N143-00 - Station Building - Kennington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
45115	ACTIVE	N	N143-00-3/236	Passage - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				1x terminal box to floor		1		N	N
45112	ACTIVE	N	N143-00-3/236	Passage - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				1x pump no.1 box to wall LHS by door				N	N
18040	ACTIVE	N	N143-00-3/236/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Kennington Stn	Caulking	Asbestos	Known				Wall - Tunnel Ring - Caulking - Chrysotile - ENCAPSULATED					
20019	ACTIVE	N	N143-00-3/236/FLR-01	Floor - 1 - Passage - Station Building - Kennington Stn	No Access	Asbestos	No Access: Presumed				No Access through Manhole					
16389	ACTIVE	N	N143-00-3/236/WAL-001	Wall: Internal - 1 - Passage - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Strongly Presumed				10mmØ Cables		1			
16390	ACTIVE	N	N143-00-3/236/WAL-009	Wall: Internal - 9 - Passage - Station Building - Kennington Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x Grey Switch Box & 2 x Red Fuse Boxes - Insulation within		4			
11487	ACTIVE	N	N143-00-3/261	Platform 1 - Northbound Local - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
42460	ACTIVE	N	N143-00-3/261	Platform 1 - Northbound Local - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Presumed				Platform Invert - Braided cables (green & white) throughout within j-hanger to platform and trackside walls and ceiling			R414078	N	N
42461	ACTIVE	N	N143-00-3/261	Platform 1 - Northbound Local - Station Building - Kennington Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Invert - Supalux Panels to some walls and ceiling as firebreaks			R414078	N	N
42462	ACTIVE	N	N143-00-3/261	Platform 1 - Northbound Local - Station Building - Kennington Stn	Caulking	Asbestos	Sampled - Not Detected				Invert - Caulking - Wood & Grout throughout within flanges to metal tunnel rings - NADIS			R414078	N	N
16392	ACTIVE	N	N143-00-3/261	Platform 1 - Northbound Local - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform Southend 10mmØ Cables		1			
42459	ACTIVE	N	N143-00-3/261	Platform 1 - Northbound Local - Station Building - Kennington Stn	Caulking	Asbestos	Sampled - Not Detected				Invert - Wood & Grout throughout within flanges to metal tunnel rings - NADIS			R414078	N	N
45097	ACTIVE	N	N143-00-3/261	Platform 1 - Northbound Local - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - Cable wrap on pipe by ladder into invert track wall 0.25m	0			N	N
42463	ACTIVE	N	N143-00-3/261	Platform 1 - Northbound Local - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Presumed				Invert - Braided cables (green & white) throughout within j-hanger to platform and trackside walls and ceiling			R414078	N	N
42464	ACTIVE	N	N143-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Kennington Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Invert - Supalux panels			R414078	N	N
16391	ACTIVE	N	N143-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Kennington Stn	No Access	Asbestos	No Access: Presumed				No Access through Manhole					



# Hazardous Material Asset Register - Summary



## N143-00 - Station Building - Kennington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor	
18041	ACTIVE	N	N143-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - Various Cables					YES	
11488	ACTIVE	N	N143-00-3/263	Platform 3 - Northbound Fast - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed										
43374	ACTIVE	N	N143-00-3/263	Platform 3 - Northbound Fast - Station Building - Kennington Stn		Asbestos	Sampled - Not Detected				Cement cable ducting through invert wall, Platform 3 Invert			R558376	N	N	
42466	ACTIVE	N	N143-00-3/263	Platform 3 - Northbound Fast - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Presumed				Invert - Braided Cables (green & white) throughout within j-hanger to platform and trackside walls and ceiling			R414078	N	N	
42468	ACTIVE	N	N143-00-3/263	Platform 3 - Northbound Fast - Station Building - Kennington Stn	Caulking	Asbestos	Sampled - Not Detected				Caulking - Wood & Grout throughout within flanges to metal tunnel rings			R414078	N	N	
45098	ACTIVE	N	N143-00-3/263	Platform 3 - Northbound Fast - Station Building - Kennington Stn	Other Boarding	Asbestos	Presumed				Boarding/lining to electrical boxes x2, sides & bottom - 100m from North end of Platform 3, left hand side				N	N	
16393	ACTIVE	N	N143-00-3/263	Platform 3 - Northbound Fast - Station Building - Kennington Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Redundant Cable Tray 5m from end of Platform						
42465	ACTIVE	N	N143-00-3/263	Platform 3 - Northbound Fast - Station Building - Kennington Stn	Caulking	Asbestos	Sampled - Not Detected				Invert - Caulking - Wood & Grout throughout within flanges to metal tunnel rings			R414078	N	N	
42467	ACTIVE	N	N143-00-3/263	Platform 3 - Northbound Fast - Station Building - Kennington Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux panels			R414078	N	N	
16394	ACTIVE	N	N143-00-3/263/FLR-01	Floor - 1 - Platform 3 - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 3 Invert - Various Cables					YES	
11489	ACTIVE	N	N143-00-3/381	Disused Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed										
16395	ACTIVE	N	N143-00-3/381/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Kennington Stn	Caulking	Asbestos	Surveyed - Not Detected				Tunnel Rings - Caulking Mastic Metal						
11490	ACTIVE	N	N143-00-3/382	Switch Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed										
16396	ACTIVE	N	N143-00-3/382/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Kennington Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux						
16397	ACTIVE	N	N143-00-3/382/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Kennington Stn	Void	Asbestos	Surveyed - Not Detected				Concrete; Tiles, Plaster, Solid - above False Ceiling				YES		



# Hazardous Material Asset Register - Summary



## N143-00 - Station Building - Kennington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18969	ACTIVE	N	N143-00-3/382/FLR-01	Floor - 1 - Switch Room - Station Building - Kennington Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Grey Vinyl Tiles					YES
11491	ACTIVE	N	N143-00-3/411	Store - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18042	ACTIVE	N	N143-00-3/411	Store - Station Building - Kennington Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
45099	ACTIVE	N	N143-00-3/411/WAL-002	Wall: Internal - 2 - Store - Station Building - Kennington Stn	Caulking	Asbestos	Known				Tunnel ring caulking to flanges to rear of metal panel				N	N
11492	ACTIVE	N	N143-00-3/661	Lobby - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16398	ACTIVE	N	N143-00-3/661	Lobby - Station Building - Kennington Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11493	ACTIVE	N	N143-00-3/662	Service Riser - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16399	ACTIVE	N	N143-00-3/662/WAL-002	Wall: Internal - 2 - Service Riser - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Strongly Presumed				10mmØ Cables		2			
18043	ACTIVE	N	N143-00-3/662/WAL-003	Wall: Internal - 3 - Service Riser - Station Building - Kennington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
11494	ACTIVE	N	N143-00-3/663	Switch Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16400	ACTIVE	N	N143-00-3/663	Switch Room - Station Building - Kennington Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
45100	ACTIVE	N	N143-00-3/663/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1no Grey Switch Box - Insulation within		1		N	N
11495	ACTIVE	N	N143-00-3/664	Switch Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16401	ACTIVE	N	N143-00-3/664	Switch Room - Station Building - Kennington Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11496	ACTIVE	N	N143-00-3/706	IMR - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45109	ACTIVE	N	N143-00-3/706	IMR - Station Building - Kennington Stn	Vinyl tiles	Asbestos	Known				Green marley tiles (partial) on render, brickwork and metal tunnel rings				N	N



# Hazardous Material Asset Register - Summary



## N143-00 - Station Building - Kennington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
45110	ACTIVE	N	N143-00-3/706	IMR - Station Building - Kennington Stn	Vinyl tiles	Asbestos	Known				Grey marley tiles (partial) to upper walls and ceiling some loose				N	N
18044	ACTIVE	N	N143-00-3/706/WAL-001	Wall: Internal - 1 - IMR - Station Building - Kennington Stn	Vinyl tiles	Asbestos	Removed				All Walls - 20sqm Tiles behind Equipment Room being stripped out by NL Signals Recovery Team - Tiles removed by Edenbeck 23/10/2015					
16402	ACTIVE	N	N143-00-3/706/WAL-007	Wall: Internal - 7 - IMR - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Removed				10mmØ Cables Removed by others based on re-inspection October 2016		3			
16403	ACTIVE	N	N143-00-3/706/WAL-008	Wall: Internal - 8 - IMR - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Removed				Green Cable Removed by others based on re-inspection October 2016		1			
11497	ACTIVE	N	N143-00-3/711	Relay Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44322	ACTIVE	N	N143-00-3/711	Relay Room - Station Building - Kennington Stn	Cable Ducts: Cement	Asbestos	Presumed				Filled in cement duct - no access presumed					
16405	ACTIVE	N	N143-00-3/711	Relay Room - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Strongly Presumed				10mmØ Cables - to Platform 1		2			
18046	ACTIVE	N	N143-00-3/711	Relay Room - Station Building - Kennington Stn	Boarding: Cement	Asbestos	Strongly Presumed				Boarding High Level to Racking					
45119	ACTIVE	N	N143-00-3/711	Relay Room - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Known				5x braided cables in cable run to wall 3 and 4 into floor inverts		5		N	N
16406	ACTIVE	N	N143-00-3/711	Relay Room - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Middle of Room 8no 1.5ml Tape within Electrical Equipment - Chrysotile		8			
18045	ACTIVE	N	N143-00-3/711	Relay Room - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Presumed				50mmØ Cables - to Platform 1 Need to check if this item has been removed to confirm		2			
16404	ACTIVE	N	N143-00-3/711/FLR-01	Floor - 1 - Relay Room - Station Building - Kennington Stn	Vinyl tiles	Asbestos	Presumed				Tiles Need to check if this item has been removed to confirm					
16407	ACTIVE	N	N143-00-3/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Kennington Stn	Other Boarding	Asbestos	Presumed				Paxoline Board Need to check if this item has been removed to confirm					
42060	INACTIVE	N	N143-00-3/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Kennington Stn	PCBs	Polychlorinated biphenyl	Removed				2 x PCB's - Fair Condition Need to check if this item has been removed to confirm Removed by NLE date not Known		2		N	N
45120	ACTIVE	N	N143-00-3/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn	Other Boarding	Asbestos	Known				1x brown composite panel		1		N	N
16408	ACTIVE	N	N143-00-3/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es) Need to check if this item has been removed to confirm		1			
45121	ACTIVE	N	N143-00-3/711/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Kennington Stn	Other Boarding	Asbestos	Known				Panel boarding to high level				N	N



# Hazardous Material Asset Register - Summary



## N143-00 - Station Building - Kennington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11498	ACTIVE	N	N143-00-3/712	Relay Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16409	ACTIVE	N	N143-00-3/712	Relay Room - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box (Redundant)		1			
18824	ACTIVE	N	N143-00-3/712	Relay Room - Station Building - Kennington Stn	Other Boarding	Asbestos	Presumed				Paxoline Board (All Walls)					
45123	ACTIVE	N	N143-00-3/712	Relay Room - Station Building - Kennington Stn	Other Boarding	Asbestos	Known				Brown composite panel to base of equipment				N	N
45122	ACTIVE	N	N143-00-3/712/ WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Kennington Stn	Other Boarding	Asbestos	Known				Brown composite panels on equipment				N	N
16410	ACTIVE	N	N143-00-3/712/ WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				Rectifier Box		1			
43287	INACTIVE	N	N143-00-3/712/ WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Kennington Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				Wall 1 PCB's Medium Silver Cylinder Wall Mounted Fair Condition 2016 No Access - 11/01/2017				N	N
45124	ACTIVE	N	N143-00-3/712/ WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Kennington Stn	Boarding: Cement	Asbestos	Known				1x cement panel by 12 fuses				N	N
45125	ACTIVE	N	N143-00-3/712/ WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Known				1x braided cable running into invert		1		N	N
18970	ACTIVE	N	N143-00-3/712/ WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Strongly Presumed				50mmØ Cable		1			
18462	ACTIVE	N	N143-00-3/712/ WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				Black Circuit Breaker Box		1			
45126	ACTIVE	N	N143-00-3/712/ WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				5 materials within transformers and electrical boxes		5		N	N
45127	ACTIVE	N	N143-00-3/712/ WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Strongly Presumed				1no 10mmØ Cable		1		N	N
18047	ACTIVE	N	N143-00-3/712/ WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Kennington Stn	Boarding: Cement	Asbestos	Strongly Presumed				Boarding with Electrical Fuse Equipment attached		1			
11499	ACTIVE	N	N143-00-3/713	Relay Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45102	ACTIVE	N	N143-00-3/713	Relay Room - Station Building - Kennington Stn	Boarding: Cement	Asbestos	Known				Cement panel to racking where relay box sits				N	N



# Hazardous Material Asset Register - Summary



## N143-00 - Station Building - Kennington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43210	ACTIVE	N	N143-00-3/713/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				Black Rectifier Box					
43211	ACTIVE	N	N143-00-3/713/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Kennington Stn	Isolator Switches	Asbestos	Presumed				Switch Box 1 x 60 amp					
16411	ACTIVE	N	N143-00-3/713/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Kennington Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse Brake Box - Insulation within		1			
11500	ACTIVE	N	N143-00-3/714	Relay Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
45129	ACTIVE	N	N143-00-3/714	Relay Room - Station Building - Kennington Stn	Westing house Boxes	Asbestos	Strongly Presumed				2x westinghouse brake boxes to wall		2		N	N
45130	ACTIVE	N	N143-00-3/714	Relay Room - Station Building - Kennington Stn	Other Boarding	Asbestos	Presumed				Brown composite panels to wall				N	N
16412	ACTIVE	N	N143-00-3/714/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse Brake Box - Insulation within		1			
11501	ACTIVE	N	N143-00-3/715	Relay Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
45134	ACTIVE	N	N143-00-3/715	Relay Room - Station Building - Kennington Stn	Westing house Boxes	Asbestos	Presumed				4x westinghouse boxes to walls		4		N	N
45131	ACTIVE	N	N143-00-3/715	Relay Room - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Known				2x braided cables to wall		2		N	N
45132	ACTIVE	N	N143-00-3/715	Relay Room - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Known				2x braided cables to cable run coming in through concrete duct		2		N	N
45135	ACTIVE	N	N143-00-3/715	Relay Room - Station Building - Kennington Stn	Other Boarding	Asbestos	Sampled - Not Detected				4x brown composite panels to walls 1&3 - ID confirmed Non asbestos 4RS-JP-221112-R717851		4		N	N
45133	ACTIVE	N	N143-00-3/715/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				1x rectifier equipment box (black) to wall 1		2		N	N
53622	ACTIVE	N	N143-00-3/715/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Kennington Stn	Boarding: Cement	Asbestos	Presumed				Cement Panel to below capacitor back of room wall 1 (3802r)					
53620	ACTIVE	N	N143-00-3/715/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Kennington Stn	Westing house Boxes	Asbestos	Presumed				Westinghouse Brake Box - Insulation within - Wall 1					
16413	ACTIVE	N	N143-00-3/715/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Kennington Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse Brake Box - Insulation within - wall 1 to back corner of room		4			



# Hazardous Material Asset Register - Summary



## N143-00 - Station Building - Kennington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19485	INACTIVE	N	N143-00-3/715/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Strongly Presumed				10mmØ Cable		1			
16414	ACTIVE	N	N143-00-3/715/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse Brake Box - Insulation within - Wall 3 to front		4			
53619	ACTIVE	N	N143-00-3/715/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn	Westing house Boxes	Asbestos	Presumed				Westinghouse Brake Box - Insulation within - Wall 3 to back					
53621	ACTIVE	N	N143-00-3/715/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				1x rectifier (black) and equipment box to wall 3					
53623	ACTIVE	N	N143-00-3/715/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn	Boarding: Cement	Asbestos	Surveyed – Not Detected				Cement Panel to below capacitor back of room wall 3 (back of room) - confirmed on visual inspection as wood					
11502	ACTIVE	N	N143-00-3/716	Lobby - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45136	ACTIVE	N	N143-00-3/716	Lobby - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				2x orange switch boxes to wall		2		N	N
45137	ACTIVE	N	N143-00-3/716	Lobby - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				1x terminal box to wall		1		N	N
45138	ACTIVE	N	N143-00-3/716	Lobby - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				1x transformer unit to wall		1		N	N
18108	ACTIVE	N	N143-00-3/716	Lobby - Station Building - Kennington Stn	Caulking	Asbestos	Known				Walls - Tunnel Ring - Caulking - Chrysotile -ENCAPSUALTED					
16415	ACTIVE	N	N143-00-3/716/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Kennington Stn	Caulking	Asbestos	Known				Tunnel Ring - Caulking - Chrysotile -ENCAPSUALTED					
11503	ACTIVE	N	N143-00-3/731	CER - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16416	ACTIVE	N	N143-00-3/731/FLR-01	Floor - 1 - CER - Station Building - Kennington Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
16417	ACTIVE	N	N143-00-3/731/WAL-002	Wall: Internal - 2 - CER - Station Building - Kennington Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard Panel above Door - 6x 0.05m <sup>2</sup>					
11504	ACTIVE	N	N143-00-3/791	Passage - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18109	ACTIVE	N	N143-00-3/791	Passage - Station Building - Kennington Stn	Caulking	Asbestos	Known				Wall - Tunnel Ring - Caulking - Chrysotile/ Amphibole ENCAPSULATED					



# Hazardous Material Asset Register - Summary



## N143-00 - Station Building - Kennington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16418	ACTIVE	N	N143-00-3/791/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Kennington Stn	Caulking	Asbestos	Known				Tunnel Ring - Caulking - Chrysotile/ Amphibole ENCAPSULATED					
16419	ACTIVE	N	N143-00-3/791/FLR-01	Floor - 1 - Passage - Station Building - Kennington Stn	Cable Duct: Other	Asbestos	Known				Floor - Cables Sleeves		3			
11505	ACTIVE	N	N143-00-3/792	Passage - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19417	ACTIVE	N	N143-00-3/792	Passage - Station Building - Kennington Stn	Caulking	Asbestos	Known				Wall - Tunnel Ring - Caulking - Chrysotile/ Amphibole ENCAPSULATED					
45101	ACTIVE	N	N143-00-3/792	Passage - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				1x combination fuse switch to wall		1		N	N
16420	ACTIVE	N	N143-00-3/792/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Kennington Stn	Caulking	Asbestos	Known				Tunnel Ring - Caulking - Chrysotile/ Amphibole ENCAPSULATED					
18110	ACTIVE	N	N143-00-3/792/WAL-001	Wall: Internal - 1 - Passage - Station Building - Kennington Stn	Isolator Switches	Asbestos	Strongly Presumed				Grey Switch Box - Insulation within		1			
11506	ACTIVE	N	N143-00-3/793	Passage - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16421	ACTIVE	N	N143-00-3/793	Passage - Station Building - Kennington Stn	Caulking	Asbestos	Known				Wall - Tunnel Ring - Caulking - Chrysotile/ Amphibole ENCAPSULATED					
16235	ACTIVE	N	N143-00-3/793/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Kennington Stn	Caulking	Asbestos	Known				Tunnel Ring - Caulking - Chrysotile/ Amphibole ENCAPSULATED					
16422	ACTIVE	N	N143-00-3/793/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Kennington Stn	Caulking	Asbestos	Known				Tunnel Ring - Caulking - Chrysotile/ Amphibole ENCAPSULATED					
43525	ACTIVE	N	N143-00-3/794	Vent Shaft - Station Building - Kennington Stn	Bitumen	Asbestos	Sampled – Not Detected				Vent Shaft – Bitumen Roof - Weather Proof Covering			R566601	N	N
16423	ACTIVE	N	N143-00-3/794	Vent Shaft - Station Building - Kennington Stn	Caulking	Asbestos	Known				Cast Iron rings at higher level. Asbestos caulking present - ENCAPSULATED					
11507	ACTIVE	N	N143-00-3/796	Passage - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16424	ACTIVE	N	N143-00-3/796	Passage - Station Building - Kennington Stn	Caulking	Asbestos	Known				Walls and Ceiling - Tunnel Ring - Caulking - Chrysotile/ Amphibole ENCAPSULATED					
11508	ACTIVE	N	N143-00-4/201	Passage - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19098	ACTIVE	N	N143-00-4/201	Passage - Station Building - Kennington Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N143-00 - Station Building - Kennington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11509	ACTIVE	N	N143-00-4/202	Passage - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16236	ACTIVE	N	N143-00-4/202	Passage - Station Building - Kennington Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11510	ACTIVE	N	N143-00-4/203	Passage - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16237	ACTIVE	N	N143-00-4/203	Passage - Station Building - Kennington Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11511	ACTIVE	N	N143-00-4/236	Passage - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19099	ACTIVE	N	N143-00-4/236/FLR-01	Floor - 1 - Passage - Station Building - Kennington Stn	Cable Ducts: Bitumen	Asbestos	Presumed				Bitumen Ducts - Known ducts running under floor (invert?) but no direct access from 4/236.		2			YES
43213	ACTIVE	N	N143-00-4/236/WAL-003	Wall: Internal - 3 - Passage - Station Building - Kennington Stn	Westing house Boxes	Asbestos	Presumed				Small green Westinghouse box					
11512	ACTIVE	N	N143-00-4/262	Platform 2 - Southbound Local - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16241	ACTIVE	N	N143-00-4/262	Platform 2 - Southbound Local - Station Building - Kennington Stn	Caulking	Asbestos	Presumed				Tunnel ring caulking to tunnel rings 10m, 13m & 16m from head wall					
42177	ACTIVE	N	N143-00-4/262	Platform 2 - Southbound Local - Station Building - Kennington Stn	Caulking	Asbestos	Known				Platform Invert - Tunnel Ring Caulking - impact zone 2				N	N
45140	ACTIVE	N	N143-00-4/262	Platform 2 - Southbound Local - Station Building - Kennington Stn	Westing house Boxes	Asbestos	Presumed				1x small westinghouse box to wall		1		N	N
42470	ACTIVE	N	N143-00-4/262	Platform 2 - Southbound Local - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Presumed				Invert - Braided cables (green & white) throughout within j-hanger to platform and trackside walls and ceiling			R414078	N	N
16240	ACTIVE	N	N143-00-4/262	Platform 2 - Southbound Local - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Strongly Presumed				Various Cables Nr 4/711					
42473	ACTIVE	N	N143-00-4/262	Platform 2 - Southbound Local - Station Building - Kennington Stn	Caulking	Asbestos	Sampled – Not Detected				Invert - Caulking - Wood & Grout throughout within flanges to metal tunnel rings			R414078	N	N
42475	ACTIVE	N	N143-00-4/262	Platform 2 - Southbound Local - Station Building - Kennington Stn	Caulking	Asbestos	Sampled – Not Detected				Arrivals end (tunnel mouth) - Caulking - Wood & Grout throughout within flanges to metal tunnel rings			R414078	N	N



# Hazardous Material Asset Register - Summary



## N143-00 - Station Building - Kennington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
45139	ACTIVE	N	N143-00-4/262	Platform 2 - Southbound Local - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				1x tunnel telephone box to wall		1		N	N
43375	ACTIVE	N	N143-00-4/262	Platform 2 - Southbound Local - Station Building - Kennington Stn		Asbestos	Sampled – Not Detected				Cable wrapping to cable in cable run (damaged), Platform 2 Invert, Kennington Station			R558376	N	N
42474	ACTIVE	N	N143-00-4/262	Platform 2 - Southbound Local - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Presumed				Invert - Braided cables (green & white) throughout Within j-hanger to platform and trackside walls and ceiling			R414078	N	N
42476	ACTIVE	N	N143-00-4/262	Platform 2 - Southbound Local - Station Building - Kennington Stn	Caulking	Asbestos	Sampled – Not Detected				Departure end (tunnel mouth) Caulking - Wood & Grout throughout within flanges to metal tunnel rings			R414078	N	N
16239	ACTIVE	N	N143-00-4/262	Platform 2 - Southbound Local - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform Southend 10mmØ Cable - Nr 4/951		1			
42469	ACTIVE	N	N143-00-4/262	Platform 2 - Southbound Local - Station Building - Kennington Stn	Caulking	Asbestos	Known				Invert - Caulking - Wood & Grout throughout - NOTE this is believed to be contamination from adjacent woven cable insulation - further samples to be taken			R414078	N	N
18815	ACTIVE	N	N143-00-4/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert 10mmØ Cable		1			YES
16238	ACTIVE	N	N143-00-4/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Kennington Stn	Void	Asbestos	No Access: Presumed				No Access through Manhole					
11513	ACTIVE	N	N143-00-4/264	Platform 4 - Southbound Fast - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42166	ACTIVE	N	N143-00-4/264	Platform 4 - Southbound Fast - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Known				Invert - south end of platform no. 4 2 x Braided cables within cable ducts, to platform side-wall		2		N	N
42169	ACTIVE	N	N143-00-4/264	Platform 4 - Southbound Fast - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Sampled – Not Detected				Invert - south end of platform no. 4 >20 Lm Loose wrapping to cable to wall - track side	20			N	N
42455	ACTIVE	N	N143-00-4/264	Platform 4 - Southbound Fast - Station Building - Kennington Stn	Other Boarding	Asbestos	Sampled – Not Detected				Invert – Board / Panel to Ceiling - platform side by steps			R414081	N	N
42172	ACTIVE	N	N143-00-4/264	Platform 4 - Southbound Fast - Station Building - Kennington Stn	Cable Duct: Other	Asbestos	Sampled – Not Detected				Invert - south end of platform 4. 2 x Cable Ducts to wall - braided cables side of the platform		2		N	N
42174	ACTIVE	N	N143-00-4/264	Platform 4 - Southbound Fast - Station Building - Kennington Stn	Other Boarding	Asbestos	Sampled – Not Detected				Invert - south end of platform 4. 0.5m² Board/Panel to ceiling, by the stairs to the invert platform side				N	N
43376	ACTIVE	N	N143-00-4/264	Platform 4 - Southbound Fast - Station Building - Kennington Stn	Debris: Other	Asbestos	Sampled – Not Detected				Supalux boarding debris to floor, Platform 4 Invert, Kennington Station			R558376	N	N



# Hazardous Material Asset Register - Summary



## N143-00 - Station Building - Kennington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43378	ACTIVE	N	N143-00-4/264	Platform 4 - Southbound Fast - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Sampled – Not Detected				Cable wrapping to cable in cable run (damaged) Platform 4 Invert, Kennington Station			R558376	N	N
45142	ACTIVE	N	N143-00-4/264	Platform 4 - Southbound Fast - Station Building - Kennington Stn	Cable Duct: Other	Asbestos	Known				South end of platform no. 4 - invert (impact zone 3) Asbestos - K - 2 x cable ducts to wall next to terracotta cable ducts		2		N	N
42168	ACTIVE	N	N143-00-4/264	Platform 4 - Southbound Fast - Station Building - Kennington Stn	Caulking	Asbestos	Sampled – Not Detected				Invert - south end of platform no. 4 - Caulking throughout - within flanges to metal rings to wall and floor				N	N
45141	ACTIVE	N	N143-00-4/264	Platform 4 - Southbound Fast - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Known				South end of platform no. 4 - invert (impact zone 3)  Asbestos - K - 2 x braided cables within cable ducts to platform side-wall		2		N	N
42453	ACTIVE	N	N143-00-4/264	Platform 4 - Southbound Fast - Station Building - Kennington Stn	Cable Duct: Other	Asbestos	Known				Invert - Cable Ducts platform side wall. NB:Woven sheathed cables also within ducts			R414081	N	N
43377	ACTIVE	N	N143-00-4/264	Platform 4 - Southbound Fast - Station Building - Kennington Stn	Bitumen	Asbestos	Sampled – Not Detected				Bitumen lining material to floor, Platform 4 Invert, Kennington Station			R558376	N	N
42456	ACTIVE	N	N143-00-4/264	Platform 4 - Southbound Fast - Station Building - Kennington Stn	Pipe Lagging	Asbestos	Sampled – Not Detected				Invert – Loose pipe insulation, to old pipe platform side by steps			R414081	N	N
42165	ACTIVE	N	N143-00-4/264	Platform 4 - Southbound Fast - Station Building - Kennington Stn	Cable Duct: Other	Asbestos	Known				Invert south end of platform no. 4 2 x Cable Ducts to wall - next to terracotta cable ducts		2		N	N
42176	ACTIVE	N	N143-00-4/264	Platform 4 - Southbound Fast - Station Building - Kennington Stn	Lagging	Asbestos	Sampled – Not Detected				Invert - south end of platform 4 <1 Lm Loose pipe insulation from old pipe of platform side wall, by stairs to invert		1		N	N
42170	ACTIVE	N	N143-00-4/264	Platform 4 - Southbound Fast - Station Building - Kennington Stn	Cable Duct: Other	Asbestos	Known				Invert - south end of platform 4. 2 x Cable Ducts to wall, next to terracotta cable ducts. - Inactivated - duplicate record		2		N	N
42167	ACTIVE	N	N143-00-4/264	Platform 4 - Southbound Fast - Station Building - Kennington Stn	Cable Duct: Other	Asbestos	Sampled – Not Detected				Cable pits north-end of platform no. 4 2 x Cable Ducts to platform side wall within pit no.1		2		N	N
42454	ACTIVE	N	N143-00-4/264	Platform 4 - Southbound Fast - Station Building - Kennington Stn	Cable Duct: Other	Asbestos	Sampled – Not Detected				Platform Invert - Cable Ducts platform side wall			R414081	N	N
42457	ACTIVE	N	N143-00-4/264	Platform 4 - Southbound Fast - Station Building - Kennington Stn	Cable Duct: Other	Asbestos	Sampled – Not Detected				Invert - Cable ducts platform side within Pit 1.			R414081	N	N
42452	ACTIVE	N	N143-00-4/264	Platform 4 - Southbound Fast - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Sampled – Not Detected				Invert – Loose cable wrapping			R414081	N	N



# Hazardous Material Asset Register - Summary



## N143-00 - Station Building - Kennington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19100	ACTIVE	N	N143-00-4/264/FLR-01	Floor - 1 - Platform 4 - Station Building - Kennington Stn	Cable Ducts: Bitumen	Asbestos	Surveyed – Not Detected				Bitumen Ducts; Plastic & Ceramic Ducts					YES
16242	ACTIVE	N	N143-00-4/264/FLR-01	Floor - 1 - Platform 4 - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 4 Invert - Various Cables					YES
11514	ACTIVE	N	N143-00-4/281	CER - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16244	ACTIVE	N	N143-00-4/281/CLG-01	Ceiling: Suspended - 1 - CER - Station Building - Kennington Stn	Void	Asbestos	Surveyed – Not Detected				Metal above Supalux Tiles				YES	
16243	ACTIVE	N	N143-00-4/281/CLG-01	Ceiling: Suspended - 1 - CER - Station Building - Kennington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
45144	ACTIVE	N	N143-00-4/281/FLR-01	Floor - 1 - CER - Station Building - Kennington Stn	Bitumen	Asbestos	Known				Bitumen backing and adhesive to rear of tile to floor				N	N
45143	ACTIVE	N	N143-00-4/281/FLR-01	Floor - 1 - CER - Station Building - Kennington Stn	Vinyl tiles	Asbestos	Known				Beige floor tiles on concrete slab to floor				N	N
11515	ACTIVE	N	N143-00-4/376	Switch Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16245	ACTIVE	N	N143-00-4/376	Switch Room - Station Building - Kennington Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11516	ACTIVE	N	N143-00-4/411	Store - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18895	ACTIVE	N	N143-00-4/411	Store - Station Building - Kennington Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11517	ACTIVE	N	N143-00-4/416	Toilet: Female - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16246	ACTIVE	N	N143-00-4/416	Toilet: Female - Station Building - Kennington Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11518	ACTIVE	N	N143-00-4/417	Toilet: Male - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16247	ACTIVE	N	N143-00-4/417/FLR-01	Floor - 1 - Toilet - Station Building - Kennington Stn	Void	Asbestos	No Access: Presumed				No Access through Manhole					YES
11519	ACTIVE	N	N143-00-4/661	Pump Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16248	ACTIVE	N	N143-00-4/661/CLG-01	Ceiling: Solid - 1 - Pump Room - Station Building - Kennington Stn	Void	Asbestos	Surveyed – Not Detected				Wood above false ceiling				YES	



# Hazardous Material Asset Register - Summary



## N143-00 - Station Building - Kennington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19101	ACTIVE	N	N143-00-4/661/CLG-01	Ceiling: Solid - 1 - Pump Room - Station Building - Kennington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding					
11520	ACTIVE	N	N143-00-4/662	Switch Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45145	ACTIVE	N	N143-00-4/662	Switch Room - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				3no Grey Switch Boxes - Insulation within		3		N	N
45146	ACTIVE	N	N143-00-4/662/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				Materials within electrical unit		1		N	N
16249	ACTIVE	N	N143-00-4/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				Large Electrical Box		1			
19351	ACTIVE	N	N143-00-4/662/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Kennington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding					
11521	ACTIVE	N	N143-00-4/663	Switch Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19102	ACTIVE	N	N143-00-4/663	Switch Room - Station Building - Kennington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux above door					
11522	ACTIVE	N	N143-00-4/664	Switch Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42139	ACTIVE	N	N143-00-4/664	Switch Room - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Removed				Various electrical equipment boxes Removed by others based on re-inspection October 2016				N	N
42140	ACTIVE	N	N143-00-4/664	Switch Room - Station Building - Kennington Stn	Other Boarding	Asbestos	Removed				Bakelite Panel Removed by others based on re-inspection October 2016				N	N
42141	ACTIVE	N	N143-00-4/664	Switch Room - Station Building - Kennington Stn	LUL Heaters	Asbestos	Removed				Heater (Bakelite panel within) Removed by others based on re-inspection October 2016		1		N	N
20014	ACTIVE	N	N143-00-4/664	Switch Room - Station Building - Kennington Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
42142	ACTIVE	N	N143-00-4/664	Switch Room - Station Building - Kennington Stn	Other Boarding	Asbestos	Removed				Bakerlite Panel within Connector boxes Removed by others based on re-inspection October 2016				N	N
11523	ACTIVE	N	N143-00-4/665	Switch Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16250	ACTIVE	N	N143-00-4/665	Switch Room - Station Building - Kennington Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N143-00 - Station Building - Kennington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11524	ACTIVE	N	N143-00-4/666	Switch Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16251	ACTIVE	N	N143-00-4/666	Switch Room - Station Building - Kennington Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11525	ACTIVE	N	N143-00-4/711	Relay Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Surveyed – Asbestos Known									
42077	INACTIVE	N	N143-00-4/711	Relay Room - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Removed				600v Box - Removed by Signals supported by Econ 19/07/2015					
42133	ACTIVE	N	N143-00-4/711	Relay Room - Station Building - Kennington Stn	Mastic	Asbestos	Sampled – Not Detected				Mastic throughout - to the joints of the metal cladding				N	N
42132	ACTIVE	N	N143-00-4/711	Relay Room - Station Building - Kennington Stn	Other Boarding	Asbestos	Sampled – Not Detected				Washers to bolts throughout				N	N
42078	ACTIVE	N	N143-00-4/711	Relay Room - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Removed				Feed Cables to 600v Box (42077 - Removed by Signals 19/07/2015) 1no Asbestos Sheathed & 1no Lead Sheathed All items Removed under Northern Line Extension Based on Re-inspection October 2016					
18326	ACTIVE	N	N143-00-4/711	Relay Room - Station Building - Kennington Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel Panel					
16253	ACTIVE	N	N143-00-4/711	Relay Room - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Removed				Various Cables Nr Platform 2 All items Removed under Northern Line Extension Based on Re-inspection October 2016					
42137	ACTIVE	N	N143-00-4/711	Relay Room - Station Building - Kennington Stn	Cellactite Sheeting	Asbestos	Removed				Cellactite sheeting, 50m <sup>2</sup> to the back of Wall 1 Re moved by NLE under ES8225	50			N	N
42138	ACTIVE	N	N143-00-4/711	Relay Room - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Removed				Various electrical equipment boxes All items Removed under Northern Line Extension Based on Re-inspection October 2016				N	N
42136	ACTIVE	N	N143-00-4/711	Relay Room - Station Building - Kennington Stn	Cable: Sheath	Asbestos	Removed				Woven sheath cables in various locations Removed by NLE under ES8225				N	N
42440	ACTIVE	N	N143-00-4/711	Relay Room - Station Building - Kennington Stn	Caulking	Asbestos	Sampled – Not Detected				<1m2 Caulking and Packing to tunnel rings on Platform 2			R501401	N	N
16252	ACTIVE	N	N143-00-4/711/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - Kennington Stn	Void	Asbestos	Removed				Above false ceiling All items Removed under Northern Line Extension Based on Re-inspection October 2016				YES	
42134	ACTIVE	N	N143-00-4/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn	Durasteel	Asbestos	Sampled – Not Detected				Durasteel door - 500x 500				N	N



# Hazardous Material Asset Register - Summary



## N143-00 - Station Building - Kennington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18896	ACTIVE	N	N143-00-4/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Removed				Green Electrical Box All items Removed under Northern Line Extension Based on Re-inspection October 2016		1			
19103	INACTIVE	N	N143-00-4/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Kennington Stn	PCBs	Polychlorinated biphenyl	Removed				6 x PCB's - Fair Condition All items Removed under Northern Line Extension Based on Re-inspection October 2016		6		N	N
11526	ACTIVE	N	N143-00-4/712	Pump Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
45149	ACTIVE	N	N143-00-4/712	Pump Room - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				1x combination fuse switch box to wall		1		N	N
45151	ACTIVE	N	N143-00-4/712	Pump Room - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				1x pump supplies box to wall		1		N	N
45147	ACTIVE	N	N143-00-4/712	Pump Room - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Presumed				1x track loop pump box to wall by door		1		N	N
45148	ACTIVE	N	N143-00-4/712	Pump Room - Station Building - Kennington Stn	Other Boarding	Asbestos	Presumed				1x distributon board to wall		1		N	N
16255	ACTIVE	N	N143-00-4/712/WAL-003	Wall: Internal - 3 - Pump Room - Station Building - Kennington Stn	Isolator Switches	Asbestos	Strongly Presumed				Grey Fuse Box - Insulation within		1			
16254	ACTIVE	N	N143-00-4/712/WAL-004	Wall: Internal - 4 - Pump Room - Station Building - Kennington Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux					
11527	ACTIVE	N	N143-00-4/731	Switch Cupboard - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16256	ACTIVE	N	N143-00-4/731	Switch Cupboard - Station Building - Kennington Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
45105	ACTIVE	N	N143-00-4/731/WAL-002	Wall: Internal - 2 - Switch Cupboard - Station Building - Kennington Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1no Grey Fuse Box - Insulation within		1		N	N
11528	ACTIVE	N	N143-00-4/776	Fan Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19104	ACTIVE	N	N143-00-4/776	Fan Room - Station Building - Kennington Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11529	ACTIVE	N	N143-00-A/132	Pump Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
45104	ACTIVE	N	N143-00-A/132	Pump Room - Station Building - Kennington Stn	Gasket :Pipework	Asbestos	Strongly Presumed				Lift Motor, Gearbox and Brake Assembly - Gaskets & Rope Seal				N	N



# Hazardous Material Asset Register - Summary



## N143-00 - Station Building - Kennington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16258	ACTIVE	N	N143-00-A/132	Pump Room - Station Building - Kennington Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel 35m <sup>2</sup> - Non Asbestos					
16257	ACTIVE	N	N143-00-A/132/FLR-01	Floor - 1 - Pump Room - Station Building - Kennington Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel 8m					
11530	ACTIVE	N	N143-00-A/133	Pump Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16564	ACTIVE	N	N143-00-A/133/CLG-01	Ceiling: Suspended - 1 - Pump Room - Station Building - Kennington Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Above Supalux Ceiling					
16563	ACTIVE	N	N143-00-A/133/FLR-01	Floor - 1 - Pump Room - Station Building - Kennington Stn	Void	Asbestos	No Access: Presumed				Beneath Metal Flooring					YES
11531	ACTIVE	N	N143-00-A/786	Service Area - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11532	ACTIVE	N	N143-00-B/134	Pump Room - Station Building - Kennington Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45103	ACTIVE	N	N143-00-B/134	Pump Room - Station Building - Kennington Stn	Rope Gaskets	Asbestos	Strongly Presumed				Lift Motor, Gearbox and Brake Assembly - Gaskets & Rope Seal				N	N
44247	ACTIVE	N	N143-00-B/134	Pump Room - Station Building - Kennington Stn		Asbestos	Known				Fibrous panel 1x3linm fixed to wooden horizontal beams to wall by the fire exit sign and floor hatch adjacent to controller 1 within the lift motor room B/134 at Kennington Station			R610227	N	N
18273	ACTIVE	N	N143-00-B/134	Pump Room - Station Building - Kennington Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel 35m <sup>2</sup>					
44248	ACTIVE	N	N143-00-B/134	Pump Room - Station Building - Kennington Stn		Asbestos	Known				Fibrous panel 1x3linm fixed to wooden horizontal beams to wall by the fire exit sign and floor hatch adjacent to controller 1 within the lift motor room B/134 at Kennington Station.			R610227	N	N
16566	ACTIVE	N	N143-00-B/134/FLR-01	Floor - 1 - Pump Room - Station Building - Kennington Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel 8m					
16341	ACTIVE	N	N143-00/CPY-01	Canopy - 1 - Station Building - Kennington Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Blue Gloss Coating					

## N145-00 - Station Building - Oval Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11533	ACTIVE	N	N145-00-1/001	Booking Hall - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N145-00 - Station Building - Oval Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16272	ACTIVE	N	N145-00-1/001	Booking Hall - Station Building - Oval Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11534	ACTIVE	N	N145-00-1/011	Ticket Office - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18898	ACTIVE	N	N145-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Oval Stn	Void	Asbestos	Surveyed – Not Detected				W: Rendered Plaster on Brick; C: Plaster on Mesh & Concrete				YES	
16274	ACTIVE	N	N145-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Oval Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
16273	ACTIVE	N	N145-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Oval Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath wooden floor					YES
11535	ACTIVE	N	N145-00-1/021	POM - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17948	ACTIVE	N	N145-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Oval Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
16275	ACTIVE	N	N145-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Oval Stn	Void	Asbestos	Surveyed – Not Detected				W: Rendered Plaster on Brick; C: Concrete				YES	
11536	ACTIVE	N	N145-00-1/031	Mess Room - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16276	ACTIVE	N	N145-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Oval Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
16277	ACTIVE	N	N145-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Oval Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	
11537	ACTIVE	N	N145-00-1/036	Toilet: Unisex - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16278	ACTIVE	N	N145-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Oval Stn	Void	Asbestos	Surveyed – Not Detected				Breeze Block; Plaster above false ceiling				YES	
18816	ACTIVE	N	N145-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Oval Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
11538	ACTIVE	N	N145-00-1/071	Circulation Area - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17949	ACTIVE	N	N145-00-1/071	Circulation Area - Station Building - Oval Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible				YES	



# Hazardous Material Asset Register - Summary



## N145-00 - Station Building - Oval Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11539	ACTIVE	N	N145-00-1/081	Lobby - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16279	ACTIVE	N	N145-00-1/081	Lobby - Station Building - Oval Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible				YES	
11540	ACTIVE	N	N145-00-1/083	Lobby - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18327	ACTIVE	N	N145-00-1/083/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Oval Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Fibreglass Lagging above false ceiling				YES	
16280	ACTIVE	N	N145-00-1/083/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Oval Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
16281	ACTIVE	N	N145-00-1/151	UMC - Station Building - Oval Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Transformer Box(es) presumed asbestos insulating materials within		1			
16283	ACTIVE	N	N145-00-1/151	UMC - Station Building - Oval Stn	Durasteel	Asbestos	Surveyed – Not Detected				Lid to Storage Bin				YES	
17951	ACTIVE	N	N145-00-1/151	UMC - Station Building - Oval Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Boarding above Escalators 1&2				YES	
17950	ACTIVE	N	N145-00-1/151	UMC - Station Building - Oval Stn	Lead/Leading	Lead Paint/Lead	Known				UMC - Red Oil Based Paint - Pipework. Thickness .31mm; Est Quantity 20lm; Analysis 3.85% (not in Maximo)					
16282	ACTIVE	N	N145-00-1/151	UMC - Station Building - Oval Stn	Lead/Leading	Lead Paint/Lead	Known				UMC - Red Oil Based Paint - 2 x Girder to Housing Units. Thickness .36mm; Est Quantity 6 lm; Analysis 29.39% (not in Maximo)					
11541	ACTIVE	N	N145-00-1/236	Lobby - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16284	ACTIVE	N	N145-00-1/236/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Oval Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels					
11542	ACTIVE	N	N145-00-1/237	Lobby - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16286	ACTIVE	N	N145-00-1/237/FLR-01	Floor - 1 - Lobby - Station Building - Oval Stn	Void	Asbestos	Surveyed – Not Detected				W: Rendered Plaster on Brick; C: Concrete					YES
16285	ACTIVE	N	N145-00-1/237/FLR-01	Floor - 1 - Lobby - Station Building - Oval Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
11543	ACTIVE	N	N145-00-1/316	Locker Room - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11544	ACTIVE	N	N145-00-1/332	Mess Room - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N145-00 - Station Building - Oval Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16287	ACTIVE	N	N145-00-1/332/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Oval Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
17952	ACTIVE	N	N145-00-1/332/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Oval Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Fibreglass Lagging; Supalux Boards; No Rope Seals present in Glazing Bars above false ceiling				YES	
11545	ACTIVE	N	N145-00-1/396	SVC - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16288	ACTIVE	N	N145-00-1/396	SVC - Station Building - Oval Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible				YES	
11546	ACTIVE	N	N145-00-1/397	Disused Room - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16289	ACTIVE	N	N145-00-1/397	Disused Room - Station Building - Oval Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible				YES	
11547	ACTIVE	N	N145-00-1/406	Bin Store - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16290	ACTIVE	N	N145-00-1/406	Bin Store - Station Building - Oval Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible				YES	
11548	ACTIVE	N	N145-00-1/407	Store - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11549	ACTIVE	N	N145-00-1/411	Store - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11550	ACTIVE	N	N145-00-1/416	Lobby - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16291	ACTIVE	N	N145-00-1/416/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Oval Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel					
11551	ACTIVE	N	N145-00-1/417	Switch Room - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18817	ACTIVE	N	N145-00-1/417	Switch Room - Station Building - Oval Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible				YES	
11552	ACTIVE	N	N145-00-1/419	Shower Room - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16292	ACTIVE	N	N145-00-1/419	Shower Room - Station Building - Oval Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible				YES	



# Hazardous Material Asset Register - Summary



## N145-00 - Station Building - Oval Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11553	ACTIVE	N	N145-00-1/420	Toilet: Male - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20015	ACTIVE	N	N145-00-1/420	Toilet: Male - Station Building - Oval Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible				YES	
11554	ACTIVE	N	N145-00-1/421	Toilet: Unisex - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16293	ACTIVE	N	N145-00-1/421	Toilet: Unisex - Station Building - Oval Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible				YES	
11555	ACTIVE	N	N145-00-1/451	Tenancy - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16294	ACTIVE	N	N145-00-1/451	Tenancy - Station Building - Oval Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
17953	ACTIVE	N	N145-00-1/451/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Oval Stn	Void	Asbestos	No Access: Presumed				Above Metal Tiles				YES	
11556	ACTIVE	N	N145-00-1/452	Tenancy - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16295	ACTIVE	N	N145-00-1/452	Tenancy - Station Building - Oval Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels					
16296	ACTIVE	N	N145-00-1/452/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Oval Stn	Void	Asbestos	Surveyed – Not Detected				Metal, Concrete above Supalux Tiles				YES	
18328	ACTIVE	N	N145-00-1/452/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Oval Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
11557	ACTIVE	N	N145-00-1/551	Yard - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16297	ACTIVE	N	N145-00-1/551	Yard - Station Building - Oval Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible				YES	
11558	ACTIVE	N	N145-00-1/577	Stairs: Linear - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11559	ACTIVE	N	N145-00-1/631	Stairs: Spiral - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16298	ACTIVE	N	N145-00-1/631/CLG-02	Ceiling: Solid - 2 - Spiral Stairs - Station Building - Oval Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel nr 1/791					



# Hazardous Material Asset Register - Summary



## N145-00 - Station Building - Oval Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11560	ACTIVE	N	N145-00-1/663	Store - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19352	ACTIVE	N	N145-00-1/663/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Oval Stn	Void	Asbestos	Surveyed – Not Detected				Wood Bations & Concrete above Supalux Ceiling				YES	
17954	ACTIVE	N	N145-00-1/663/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Oval Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
11561	ACTIVE	N	N145-00-1/665	Switch Room - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16299	ACTIVE	N	N145-00-1/665/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Oval Stn	Isolator Switches	Asbestos	Surveyed – Not Detected				Iron Clad Isolator - Insulation within - No removal required - Non Asbestos		1			
11562	ACTIVE	N	N145-00-1/751	Station Control Room - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16301	ACTIVE	N	N145-00-1/751/CLG-01	Ceiling: Solid - 1 - Station Control Room - Station Building - Oval Stn	Void	Asbestos	No Access: Presumed				Above Metal Strip				YES	
16300	ACTIVE	N	N145-00-1/751/FLR-01	Floor - 1 - Station Control Room - Station Building - Oval Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden Floor					YES
11563	ACTIVE	N	N145-00-1/781	TXR - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17955	ACTIVE	N	N145-00-1/781	TXR - Station Building - Oval Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
11564	ACTIVE	N	N145-00-1/782	TXR - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18960	ACTIVE	N	N145-00-1/782	TXR - Station Building - Oval Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
20297	ACTIVE	N	N145-00-1/791	Vent Shaft - Station Building - Oval Stn	Cable Ducts: Cement	Asbestos	Sampled – Not Detected				Report R87573 14/05/2014 -High level - Cement Sleeve NADIS High level - Dust/Debris to Gantry Arm NADIS				N	
20267	ACTIVE	N	N145-00-1/791	Vent Shaft - Station Building - Oval Stn	Caulking	Asbestos	Sampled – Not Detected				Report R87573 14/06/2014 - Tunnel Ring Caulking - Middle Level - NADIS				N	
16302	ACTIVE	N	N145-00-1/791	Vent Shaft - Station Building - Oval Stn	Caulking	Asbestos	Surveyed – Not Detected				Solid Caulking					
18818	ACTIVE	N	N145-00-1/791	Vent Shaft - Station Building - Oval Stn	Cable Ducts: Bitumen	Asbestos	Surveyed – Not Detected				Bitumen Cable Sleeves					
11565	ACTIVE	N	N145-00-1/901	Disused Room - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N145-00 - Station Building - Oval Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16303	ACTIVE	N	N145-00-1/901	Disused Room - Station Building - Oval Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11566	ACTIVE	N	N145-00-1/TA1	Tenancy - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16304	ACTIVE	N	N145-00-1/TA1	Tenancy - Station Building - Oval Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Tenancy					
11567	ACTIVE	N	N145-00-2/081	Circulation Area - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11568	ACTIVE	N	N145-00-2/082	Switch Room - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16305	ACTIVE	N	N145-00-2/161	LMC - Station Building - Oval Stn	Caulking	Asbestos	No Access: Presumed				Caulking to Ceiling - Not Surveyed					
17956	ACTIVE	N	N145-00-2/161	LMC - Station Building - Oval Stn	Isolator Switches	Asbestos	Surveyed – Not Detected				Iron Clad Isolator - No removal required - Non Asbestos		1			
16306	ACTIVE	N	N145-00-2/161	LMC - Station Building - Oval Stn	Lead/Leading	Lead Paint/Lead	Known				LMC - Black Oil Based Paint - Girder. Thickness .48mm; Est Quantity 3lm; Analysis 1.32%. (3/161 in Maximo reported as an error)					
11569	ACTIVE	N	N145-00-2/201	Passage - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16307	ACTIVE	N	N145-00-2/201	Passage - Station Building - Oval Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11570	ACTIVE	N	N145-00-2/203	Passage - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18961	ACTIVE	N	N145-00-2/203	Passage - Station Building - Oval Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11571	ACTIVE	N	N145-00-2/236	Lobby - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16308	ACTIVE	N	N145-00-2/236	Lobby - Station Building - Oval Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Walls - Supalux Panels					
11572	ACTIVE	N	N145-00-2/261	Platform 1 - Northbound Local - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16309	ACTIVE	N	N145-00-2/261	Platform 1 - Northbound Local - Station Building - Oval Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables going into Track		2			
46460	ACTIVE	N	N145-00-2/261	Platform 1 - Northbound Local - Station Building - Oval Stn	Debris: Other	Asbestos	Sampled – Not Detected				Dust to cables and floor (small debris pieces too) at Arrival end - Throughout			R633826	N	N



# Hazardous Material Asset Register - Summary



## N145-00 - Station Building - Oval Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46459	ACTIVE	N	N145-00-2/261	Platform 1 - Northbound Local - Station Building - Oval Stn	Debris: Other	Asbestos	Sampled – Not Detected				Dust to cables and floor (small debris pieces too) at Departure end - Throughout			R633826	N	N
16310	ACTIVE	N	N145-00-2/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Oval Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - 20mm Cables - Head Wall		2			YES
16311	ACTIVE	N	N145-00-2/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Oval Stn	Caulking	Asbestos	Surveyed – Not Detected				Culking to Invert					YES
11573	ACTIVE	N	N145-00-2/291	Store - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17957	ACTIVE	N	N145-00-2/291	Store - Station Building - Oval Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board (Walls)					
16312	ACTIVE	N	N145-00-2/291/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Oval Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board					
11574	ACTIVE	N	N145-00-2/411	Disused Room - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18819	ACTIVE	N	N145-00-2/411/CLG-01	Ceiling: Suspended - 1 - Disused Room - Station Building - Oval Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Ceiling - Non Asbestos					
11575	ACTIVE	N	N145-00-2/416	Toilet - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11576	ACTIVE	N	N145-00-2/601	Stairs: Linear - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16313	ACTIVE	N	N145-00-2/601	Stairs: Linear - Station Building - Oval Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11577	ACTIVE	N	N145-00-2/602	Stairs: Linear - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16314	ACTIVE	N	N145-00-2/602	Stairs: Linear - Station Building - Oval Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11578	ACTIVE	N	N145-00-2/661	Switch Room - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17958	ACTIVE	N	N145-00-2/661	Switch Room - Station Building - Oval Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11579	ACTIVE	N	N145-00-2/662	Switch Room - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16315	ACTIVE	N	N145-00-2/662	Switch Room - Station Building - Oval Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Walls - Supalux Boxing					



# Hazardous Material Asset Register - Summary



## N145-00 - Station Building - Oval Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11580	ACTIVE	N	N145-00-2/664	Switch Cupboard - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18329	ACTIVE	N	N145-00-2/664/CLG-01	Ceiling: Suspended - 1 - Switch Cupboard - Station Building - Oval Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling				YES	
18962	ACTIVE	N	N145-00-2/664/CLG-01	Ceiling: Suspended - 1 - Switch Cupboard - Station Building - Oval Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
11581	ACTIVE	N	N145-00-2/665	Switch Cupboard - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16316	ACTIVE	N	N145-00-2/665	Switch Cupboard - Station Building - Oval Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11582	ACTIVE	N	N145-00-2/666	Switch Room - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16317	ACTIVE	N	N145-00-2/666	Switch Room - Station Building - Oval Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11583	ACTIVE	N	N145-00-2/711	Relay Room - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16321	INACTIVE	N	N145-00-2/711	Relay Room - Station Building - Oval Stn	Westing house Boxes	Asbestos	Removed				Westinghouse Box - Removed by Signals supported by Econ 15/07/2015		1			
16319	ACTIVE	N	N145-00-2/711	Relay Room - Station Building - Oval Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables going into Inverts		3			
17959	ACTIVE	N	N145-00-2/711	Relay Room - Station Building - Oval Stn	Vinyl tiles	Asbestos	Strongly Presumed				Tiles under signalling equipment - All others have been removed - Chrysotile; Concrete. Vast majority of tile removed, only those under signalling equipment remain, these can only be removed when signalling equipment is replaced					
19484	INACTIVE	N	N145-00-2/711	Relay Room - Station Building - Oval Stn	Other Electrical Boxes	Asbestos	Removed				Transformer Box(es) Has been removed		1			
46286	ACTIVE	N	N145-00-2/711	Relay Room - Station Building - Oval Stn	Other Boarding	Asbestos	Presumed				1x Brown composite panel to racking presumed to contain asbestos					
16320	ACTIVE	N	N145-00-2/711	Relay Room - Station Building - Oval Stn	Boarding: Cement	Asbestos	Removed				Panels under PCB's. Tested and Confirmed Asbestos - Removed/ not present 2020 re-inspection.		4			
16318	ACTIVE	N	N145-00-2/711/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - Oval Stn	Void	Asbestos	No Access: Presumed				Above partly tiles false ceiling				YES	



# Hazardous Material Asset Register - Summary



## N145-00 - Station Building - Oval Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16322	INACTIVE	N	N145-00-2/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Oval Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				PCB's - Fair Condition Serial Nos. 186616; 186590; 178950; 186634; 186601; 186647; 186527;186333 Re inspected 14/04/2015		9			
11584	ACTIVE	N	N145-00-2/761	CER - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18963	ACTIVE	N	N145-00-2/761	CER - Station Building - Oval Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11585	ACTIVE	N	N145-00-2/786	Service Riser - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16323	ACTIVE	N	N145-00-2/786	Service Riser - Station Building - Oval Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel above Door					
11586	ACTIVE	N	N145-00-2/787	Service Riser - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16324	ACTIVE	N	N145-00-2/787	Service Riser - Station Building - Oval Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel above Door					
17960	ACTIVE	N	N145-00-2/791	Vent Shaft - Station Building - Oval Stn	Caulking	Asbestos	Surveyed – Not Detected				Top Level - Tunnel Rings - Solid Caulking;					
20298	ACTIVE	N	N145-00-2/791	Vent Shaft - Station Building - Oval Stn	Debris: Other	Asbestos	Sampled – Not Detected				R87573 14/05/2014 - Middle level - Tunnel Ring Bolt Flanges NADIS. Middle level - Debris to Tunnel Rings NADIS				N	N
20266	ACTIVE	N	N145-00-2/791	Vent Shaft - Station Building - Oval Stn	Caulking	Asbestos	Sampled – Not Detected				R87573 14/05/2014 - Middle Level Tunnel Ring Caulking NADIS				N	
11587	ACTIVE	N	N145-00-2/992	Pump Room - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16325	ACTIVE	N	N145-00-2/992	Pump Room - Station Building - Oval Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel above Door					
16327	ACTIVE	N	N145-00-2/992/CLG-01	Ceiling: Suspended - 1 - Plant Room - Station Building - Oval Stn	Void	Asbestos	No Access: Presumed				Above Supalux Ceiling				YES	
16326	ACTIVE	N	N145-00-2/992/CLG-01	Ceiling: Suspended - 1 - Plant Room - Station Building - Oval Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				False Ceiling					
11588	ACTIVE	N	N145-00-3/151	UMC - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11589	ACTIVE	N	N145-00-3/161	LMC - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N145-00 - Station Building - Oval Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11590	ACTIVE	N	N145-00-3/201	Passage - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17961	ACTIVE	N	N145-00-3/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Oval Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel					
11591	ACTIVE	N	N145-00-3/202	Passage - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18964	ACTIVE	N	N145-00-3/202/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Oval Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	
11592	ACTIVE	N	N145-00-3/262	Platform 2 - Southbound Local - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16328	ACTIVE	N	N145-00-3/262	Platform 2 - Southbound Local - Station Building - Oval Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables going into Track		1			
16329	ACTIVE	N	N145-00-3/262	Platform 2 - Southbound Local - Station Building - Oval Stn	Cable Ducts: Bitumen	Asbestos	Surveyed – Not Detected				Cable Ducts		6			
16330	ACTIVE	N	N145-00-3/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Oval Stn	Cable Ducts: Bitumen	Asbestos	Surveyed – Not Detected				Bitumen Ducts to concrete Plinth					YES
11593	ACTIVE	N	N145-00-3/406	Pump Room - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16331	ACTIVE	N	N145-00-3/406	Pump Room - Station Building - Oval Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Walls - Supalux					
16332	ACTIVE	N	N145-00-3/406/CLG-01	Ceiling: Solid - 1 - Plant Room - Station Building - Oval Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board					
11594	ACTIVE	N	N145-00-3/412	Store - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17962	ACTIVE	N	N145-00-3/412	Store - Station Building - Oval Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11595	ACTIVE	N	N145-00-3/712	Relay Room - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17963	INACTIVE	N	N145-00-3/712	Relay Room - Station Building - Oval Stn	Westing house Boxes	Asbestos	Removed				Westinghouse Box - removed by signals supported by Econ;		1			
18820	ACTIVE	N	N145-00-3/712	Relay Room - Station Building - Oval Stn	Cable: Sheath	Asbestos	Strongly Presumed				cables		3			
16335	INACTIVE	N	N145-00-3/712	Relay Room - Station Building - Oval Stn	Other Electrical Boxes	Asbestos	Presumed				Westinghouse boxes In twice see 17963		1			



# Hazardous Material Asset Register - Summary



## N145-00 - Station Building - Oval Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16334	ACTIVE	N	N145-00-3/712	Relay Room - Station Building - Oval Stn	Boarding: Cement	Asbestos	Presumed				Panels under PCB's (not to be confused with the vinyl tiles that are present under/behind racking containing signalling equipment).					
46287	ACTIVE	N	N145-00-3/712	Relay Room - Station Building - Oval Stn	Other Boarding	Asbestos	Presumed				7x Brown composite panels to racking. Presumed to contain asbestos		7			
16333	ACTIVE	N	N145-00-3/712	Relay Room - Station Building - Oval Stn	Vinyl tiles	Asbestos	Strongly Presumed				Tiles under signalling equipment - All others have been removed. Vast majority of tile removed only those under signalling equipment remain these can only be removed when signalling equipment is replaced					
16336	INACTIVE	N	N145-00-3/712	Relay Room - Station Building - Oval Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				6 x PCB's - Fair Condition. Serial Nos. 186460; 186622; 186545; 186495; 186500; 186502 Re inspected 14/04/2015		6			
11596	ACTIVE	N	N145-00-A/331	Mess Room - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16337	ACTIVE	N	N145-00-A/331	Mess Room - Station Building - Oval Stn		Asbestos	Surveyed - Not Detected				Acoustic Panel below sink					
11597	ACTIVE	N	N145-00-A/416	Toilet - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
11598	ACTIVE	N	N145-00-A/576	Stairs: Linear - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16338	ACTIVE	N	N145-00-A/576	Stairs: Linear - Station Building - Oval Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11599	ACTIVE	N	N145-00-A/661	Switch Cupboard - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16339	ACTIVE	N	N145-00-A/661	Switch Cupboard - Station Building - Oval Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Ceiling					
11600	ACTIVE	N	N145-00-A/746	SCR - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17964	ACTIVE	N	N145-00-A/746/FLR-01	Floor - 1 - SCR - Station Building - Oval Stn	Void	Asbestos	Removed				Beneath Computer Flooring					YES
11601	ACTIVE	N	N145-00-A/783	CER - Station Building - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16340	ACTIVE	N	N145-00-A/783/FLR-01	Floor - 1 - CER - Station Building - Oval Stn	Void	Asbestos	Sampled - Not Detected				Beneath Computer Flooring					



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11617	ACTIVE	N	N147-00-1/001	Booking Hall - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18855	ACTIVE	N	N147-00-1/001/CLG-01	Ceiling: Suspended - 1 - Booking Hall - Station Building - Stockwell Stn	Vinyl tiles	Asbestos	Surveyed - Not Detected				Above Supalux Tiles - Concrete; Fireboard around Steels; Vermiculite boxing above 1/240; Fibreglass lagging, solid below.				YES	
16043	ACTIVE	N	N147-00-1/001/CLG-01	Ceiling: Suspended - 1 - Booking Hall - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
16042	ACTIVE	N	N147-00-1/001/FLR-01	Floor - 1 - Booking Hall - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				3x Floor Hatches		3			YES
18878	ACTIVE	N	N147-00-1/001/FLR-01	Floor - 1 - Booking Hall - Station Building - Stockwell Stn	Void	Asbestos	Surveyed - Not Detected				Concrete beneath Computer Flooring					
11618	ACTIVE	N	N147-00-1/011	Ticket Office - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
16044	ACTIVE	N	N147-00-1/011	Ticket Office - Station Building - Stockwell Stn	LUL Heaters	Asbestos	Sampled - Not Detected				Foam Insulation - Non Asbestos					
16045	ACTIVE	N	N147-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
16046	ACTIVE	N	N147-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Stockwell Stn	Void	Asbestos	Surveyed - Not Detected				Above Supalux Tiles - Concrete, Solid; Metal Ducting, Vermiculite Boxing over beams				YES	
45018	ACTIVE	N	N147-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Stockwell Stn	Cable Ducts: Cement	Asbestos	Known				Cement cable ducts within concrete floor to rear of wall 2				N	N
41934	ACTIVE	N	N147-00-1/011/WAL-003	Wall: Internal - 3 - Ticket Office - Station Building - Stockwell Stn		Asbestos	Sampled - Not Detected				Plaster / Brickwork throughout NADIS				N	N
41933	ACTIVE	N	N147-00-1/011/WAL-003	Wall: Internal - 3 - Ticket Office - Station Building - Stockwell Stn		Asbestos	Sampled - Not Detected				Metal and wood, 4 x to window frames		4		N	N
11619	ACTIVE	N	N147-00-1/021	POM - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16047	ACTIVE	N	N147-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Stockwell Stn	Void	Asbestos	Surveyed - Not Detected				Concrete beneath Computer Flooring					YES
11620	ACTIVE	N	N147-00-1/031	Mess Room - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18319	ACTIVE	N	N147-00-1/031	Mess Room - Station Building - Stockwell Stn	LUL Heaters	Asbestos	Sampled - Not Detected				Foam Insulation - Non Asbestos					
16049	ACTIVE	N	N147-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Stockwell Stn	Void	Asbestos	Surveyed - Not Detected				Concrete, Solid; Metal Pipes & Ducts above Supalux Tiles				YES	



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16048	ACTIVE	N	N147-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
11621	ACTIVE	N	N147-00-1/036	Lobby - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18856	ACTIVE	N	N147-00-1/036/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
16050	ACTIVE	N	N147-00-1/036/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Solid; Metal Vent Ducting; Solid Walls above Supalux Tiles				YES	
11622	ACTIVE	N	N147-00-1/037	Toilet: Unisex - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11623	ACTIVE	N	N147-00-1/047	Kitchen - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16052	ACTIVE	N	N147-00-1/047/CLG-01	Ceiling: Suspended - 1 - Kitchen - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Solid Walls; Ceiling Vent Ducting above Supalux Tiles				YES	
16051	ACTIVE	N	N147-00-1/047/CLG-01	Ceiling: Suspended - 1 - Kitchen - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
16053	ACTIVE	N	N147-00-1/047/CLG-01	Ceiling: Suspended - 1 - Kitchen - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18921	ACTIVE	N	N147-00-1/047/CLG-01	Ceiling: Suspended - 1 - Kitchen - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	
11624	ACTIVE	N	N147-00-1/071	Circulation Area - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16054	ACTIVE	N	N147-00-1/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
16055	ACTIVE	N	N147-00-1/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Fire board covering Steel; Vermiculite boxing; Solid walls above False Ceiling				YES	
18879	ACTIVE	N	N147-00-1/071/FLR-01	Floor - 1 - Circulation Area - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				No access to Floor Hatches					YES
11625	ACTIVE	N	N147-00-1/151	UMC - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18320	ACTIVE	N	N147-00-1/151	UMC - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cut above Flam Store 1no Redundant Cable j-hanger x 1, along Escalator 4 Incline		1			
45019	ACTIVE	N	N147-00-1/151	UMC - Station Building - Stockwell Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Insulation inside busbar unit				N	N



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16060	ACTIVE	N	N147-00-1/151	UMC - Station Building - Stockwell Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es)		1			
42182	ACTIVE	N	N147-00-1/151	UMC - Station Building - Stockwell Stn	Boarding: Cement	Asbestos	Known				Cement shuttering throughout to ceiling within floor vent ducts					
18745	ACTIVE	N	N147-00-1/151	UMC - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables		2			
18922	ACTIVE	N	N147-00-1/151/CLG-01	Ceiling: Solid - 1 - UMC - Station Building - Stockwell Stn	Durasteel	Asbestos	Surveyed - Not Detected				W4 Durasteel Ceiling Panel					
16056	ACTIVE	N	N147-00-1/151/FLR-01	Floor - 1 - UMC - Station Building - Stockwell Stn	Durasteel	Asbestos	Surveyed - Not Detected				Lid to Storage Bin					
45022	ACTIVE	N	N147-00-1/151/WAL-001	Wall: Internal - 1 - UMC - Station Building - Stockwell Stn	Other Electrical Boxes	Asbestos	Presumed				Materials within 10 core box by escalator 4		10		N	N
45020	ACTIVE	N	N147-00-1/151/WAL-001	Wall: Internal - 1 - UMC - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Presumed				Green braided cable - Within cable run by storage bunker, running perimeter wall into incline				N	N
45021	ACTIVE	N	N147-00-1/151/WAL-004	Wall: Internal - 4 - UMC - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Presumed				Green braided cable - Within cable run by storage bunker, running perimeter wall into incline				N	N
16057	ACTIVE	N	N147-00-1/151/WAL-004	Wall: Internal - 4 - UMC - Station Building - Stockwell Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse Boxes - Insulation within		3			
16058	ACTIVE	N	N147-00-1/151/WAL-005	Wall: Internal - 5 - UMC - Station Building - Stockwell Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				EAC Control Panel - insulation within		1			
18923	ACTIVE	N	N147-00-1/151/WAL-005	Wall: Internal - 5 - UMC - Station Building - Stockwell Stn	Gasket :Pipework	Asbestos	Strongly Presumed				Gasket within ventilation shaft		6			
16059	ACTIVE	N	N147-00-1/151/WAL-006	Wall: Internal - 6 - UMC - Station Building - Stockwell Stn	Gasket :Pipework	Asbestos	Strongly Presumed				Gasket within ventilation shaft		6			
11626	ACTIVE	N	N147-00-1/152	UMC - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
45023	ACTIVE	N	N147-00-1/152	UMC - Station Building - Stockwell Stn	Cable Ducts: Cement	Asbestos	Known				4no cement cable ducts to corner of walls 3 and 4				N	N
18924	ACTIVE	N	N147-00-1/152	UMC - Station Building - Stockwell Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es)		1			
16064	ACTIVE	N	N147-00-1/152/CLG-01	Ceiling: Solid - 1 - UMC - Station Building - Stockwell Stn	Durasteel	Asbestos	Surveyed - Not Detected				W3 Durasteel Ceiling Panel - Non Asbestos					
16061	ACTIVE	N	N147-00-1/152/CLG-01	Ceiling: Solid - 1 - UMC - Station Building - Stockwell Stn	Durasteel	Asbestos	Surveyed - Not Detected				W3 Durasteel Ceiling Panel - Non Asbestos					
16065	ACTIVE	N	N147-00-1/152/CLG-01	Ceiling: Solid - 1 - UMC - Station Building - Stockwell Stn	Durasteel	Asbestos	Surveyed - Not Detected				W5 Durasteel Ceiling Panel - Non Asbestos					
16062	ACTIVE	N	N147-00-1/152/WAL-005	Wall: Internal - 5 - UMC - Station Building - Stockwell Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Cable Sleeves		6			



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16063	ACTIVE	N	N147-00-1/152/WAL-006	Wall: Internal - 6 - UMC - Station Building - Stockwell Stn	Cable Duct: Other	Asbestos	Surveyed – Not Detected				Cable Sleeves		4			
45025	ACTIVE	N	N147-00-1/171	Escalator Incline - Station Building - Stockwell Stn	Cellactite Sheeting	Asbestos	Known				Cellactite - corrugated Throughout 40m visible -To walls and ceiling of incline-				N	N
45024	ACTIVE	N	N147-00-1/171	Escalator Incline - Station Building - Stockwell Stn	Caulking	Asbestos	Known				Caulking - To Flanges of tunnel rings to walls - throughout				N	N
16066	ACTIVE	N	N147-00-1/171	Escalator Incline - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				1x Redundant Cable j-hanger no 1, along Escalator 4 Incline					
11627	ACTIVE	N	N147-00-1/236	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18925	ACTIVE	N	N147-00-1/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
16068	ACTIVE	N	N147-00-1/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Concrete / Metal Ducting / Conduits; Fibreglass lagging above Supalux Tiles				YES	
11628	ACTIVE	N	N147-00-1/237	Lobby - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16071	ACTIVE	N	N147-00-1/237/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
18880	ACTIVE	N	N147-00-1/237/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Vermiculite Panels; Fibreglass Lagging above False Ceiling				YES	
16069	ACTIVE	N	N147-00-1/237/WAL-002	Wall: Internal - 2 - Lobby - Station Building - Stockwell Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
16070	ACTIVE	N	N147-00-1/237/WAL-003	Wall: Internal - 3 - Lobby - Station Building - Stockwell Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
11629	ACTIVE	N	N147-00-1/238	Lobby - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11630	ACTIVE	N	N147-00-1/239	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11631	ACTIVE	N	N147-00-1/240	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16073	ACTIVE	N	N147-00-1/240	Passage - Station Building - Stockwell Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible				YES	
45026	ACTIVE	N	N147-00-1/240	Passage - Station Building - Stockwell Stn	LUL Heaters	Asbestos	Presumed				Heater - Materials within LTB box				N	N



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11632	ACTIVE	N	N147-00-1/241	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18927	ACTIVE	N	N147-00-1/241/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux					
16074	ACTIVE	N	N147-00-1/241/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				Vermiculite on beams; Solid Ceiling above False Ceiling				YES	
11633	ACTIVE	N	N147-00-1/242	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18746	ACTIVE	N	N147-00-1/242/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
16075	ACTIVE	N	N147-00-1/242/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Supalux Tiles				YES	
11634	ACTIVE	N	N147-00-1/243	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16076	ACTIVE	N	N147-00-1/243/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
16077	ACTIVE	N	N147-00-1/243/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	Surveyed - Not Detected				Concrete, Solid. Vermiculite Boxing on Beams above False Ceiling				YES	
11635	ACTIVE	N	N147-00-1/244	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16078	ACTIVE	N	N147-00-1/244	Passage - Station Building - Stockwell Stn	Pipe Lagging	Asbestos	Surveyed - Not Detected									
16079	ACTIVE	N	N147-00-1/244	Passage - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				4m x 15mm Cable. 2no Cables bottom j-hanger both sides		2			
45027	ACTIVE	N	N147-00-1/244	Passage - Station Building - Stockwell Stn	Cable Ducts: Cement	Asbestos	Known				4no cement cable ducts - cables within - to wall 2 by steps		4		N	N
18321	ACTIVE	N	N147-00-1/244/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Steel Clad Boarding					
18928	ACTIVE	N	N147-00-1/244/FLR-01	Floor - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				Beneath Floor Hatch x 2					YES
11636	ACTIVE	N	N147-00-1/291	DMT Office - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15894	ACTIVE	N	N147-00-1/291/CLG-01	Ceiling: Suspended - 1 - DMT Office - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Board					



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18685	ACTIVE	N	N147-00-1/291/CLG-01	Ceiling: Suspended - 1 - DMT Office - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Metal Pipe with Rubber; Vermiculite Boxing above Supalux Board				YES	
15893	ACTIVE	N	N147-00-1/291/FLR-01	Floor - 1 - DMT Office - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				No Access to Floor Hatches beneath Concrete, Rubber Tiles					
11637	ACTIVE	N	N147-00-1/301	Station Supervisor Office - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15897	ACTIVE	N	N147-00-1/301/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Ducts; Vermiculite Boxing above Supalux Tiles				YES	
15896	ACTIVE	N	N147-00-1/301/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
15895	ACTIVE	N	N147-00-1/301/FLR-01	Floor - 1 - Station Supervisor Office - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				Beneath Floor Hatch					YES
11638	ACTIVE	N	N147-00-1/311	Office - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15898	ACTIVE	N	N147-00-1/311/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
15901	ACTIVE	N	N147-00-1/311/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
15899	ACTIVE	N	N147-00-1/311/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Ducting; Cable - Plastic above Supalux Tiles				YES	
15902	ACTIVE	N	N147-00-1/311/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Metal trunking; Pipework; Ducts above Supalux Tiles				YES	
11639	ACTIVE	N	N147-00-1/331	Mess Room - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15900	ACTIVE	N	N147-00-1/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Metal Trays; Vermiculite Laggging				YES	
18686	ACTIVE	N	N147-00-1/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
11640	ACTIVE	N	N147-00-1/361	Kitchen - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11641	ACTIVE	N	N147-00-1/366	Kitchen - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15903	ACTIVE	N	N147-00-1/366/CLG-01	Ceiling: Suspended - 1 - Kitchen - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
18735	ACTIVE	N	N147-00-1/366/CLG-01	Ceiling: Suspended - 1 - Kitchen - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Vermiculite Boxing over Beams and Fibreglass Lagging above False ceiling				YES	
11642	ACTIVE	N	N147-00-1/396	SVC - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45028	ACTIVE	N	N147-00-1/396	SVC - Station Building - Stockwell Stn	Gasket :Pipework	Asbestos	Known				Gasket to 4no flanges of pipework		4		N	N
18801	ACTIVE	N	N147-00-1/396/CLG-01	Ceiling: Suspended - 1 - SVC - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board					
11643	ACTIVE	N	N147-00-1/406	Store - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15904	ACTIVE	N	N147-00-1/406/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Solid Walls; Fibreglass Debris above False Ceiling				YES	
18314	ACTIVE	N	N147-00-1/406/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18753	ACTIVE	N	N147-00-1/406/FLR-01	Floor - 1 - Store - Station Building - Stockwell Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Green Vinyl Tiles (non asbestos)					
11644	ACTIVE	N	N147-00-1/407	Bin Store - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15906	ACTIVE	N	N147-00-1/407	Bin Store - Station Building - Stockwell Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel panels side of Escalator					
15905	ACTIVE	N	N147-00-1/407/CLG-01	Ceiling: Solid - 1 - Bin Store - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels x2; Vermiculite Boxing over beams					
11645	ACTIVE	N	N147-00-1/408	Switch Room - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18754	ACTIVE	N	N147-00-1/408/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux				YES	
15907	ACTIVE	N	N147-00-1/408/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
11646	ACTIVE	N	N147-00-1/409	Cleaners Room - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15908	ACTIVE	N	N147-00-1/409	Cleaners Room - Station Building - Stockwell Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15909	ACTIVE	N	N147-00-1/409/CLG-01	Ceiling: Solid - 1 - Cleaners Room - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Concrete Walls & Ceiling above Supalux Tiles				YES	
19345	ACTIVE	N	N147-00-1/409/CLG-01	Ceiling: Solid - 1 - Cleaners Room - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
11647	ACTIVE	N	N147-00-1/411	Store - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18755	ACTIVE	N	N147-00-1/411/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Above False Ceiling - Concrete; Vermiculite Boxing; Fibreglass Lagging				YES	
18802	ACTIVE	N	N147-00-1/411/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
15910	ACTIVE	N	N147-00-1/411/FLR-01	Floor - 1 - Store - Station Building - Stockwell Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl Tiles (non asbestos)					YES
11648	ACTIVE	N	N147-00-1/416	Toilet: Female - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15911	ACTIVE	N	N147-00-1/416	Toilet: Female - Station Building - Stockwell Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Foam Insulation Board					
15913	ACTIVE	N	N147-00-1/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Ducting above False Ceiling				YES	
15912	ACTIVE	N	N147-00-1/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
11649	ACTIVE	N	N147-00-1/417	Toilet: Male - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16214	ACTIVE	N	N147-00-1/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Fire Board on Steels; Vermiculite over Beams beneath Supalux Tiles				YES	
16213	ACTIVE	N	N147-00-1/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
15914	ACTIVE	N	N147-00-1/417/FLR-01	Floor - 1 - Toilet - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Floor Hatches - Drains Below					YES
19092	ACTIVE	N	N147-00-1/417/WAL-004	Wall: Internal - 4 - Toilet - Station Building - Stockwell Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LU Heater x 2 Foam Insulation Panel		2			
11650	ACTIVE	N	N147-00-1/451	Tenancy - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16216	ACTIVE	N	N147-00-1/451/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles				YES	



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16215	ACTIVE	N	N147-00-1/451/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
11651	ACTIVE	N	N147-00-1/452	Tenancy - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16219	ACTIVE	N	N147-00-1/452/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Fire Board on Steels; Solid Plaster Walls, Breeze Block, Metal Vent Ducts above Supalux Tiles				YES	
16218	ACTIVE	N	N147-00-1/452/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
19093	ACTIVE	N	N147-00-1/452/FLR-01	Floor - 1 - Tenancy - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath Computer Flooring					YES
16217	ACTIVE	N	N147-00-1/452/WAL-001	Wall: Internal - 1 - Tenancy - Station Building - Stockwell Stn	Other Electrical Boxes	Asbestos	Surveyed – Not Detected				Electrical Equipment				YES	
11652	ACTIVE	N	N147-00-1/453	Tenancy - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19094	ACTIVE	N	N147-00-1/453/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles				YES	
16220	ACTIVE	N	N147-00-1/453/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
11653	ACTIVE	N	N147-00-1/511	BTP Office - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16221	ACTIVE	N	N147-00-1/511	BTP Office - Station Building - Stockwell Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11654	ACTIVE	N	N147-00-1/512	BTP Store - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16223	ACTIVE	N	N147-00-1/512/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles				YES	
16222	ACTIVE	N	N147-00-1/512/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
11655	ACTIVE	N	N147-00-1/513	BTP Office - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18752	ACTIVE	N	N147-00-1/513	BTP Office - Station Building - Stockwell Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11656	ACTIVE	N	N147-00-1/576	Stairs: Linear - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18893	ACTIVE	N	N147-00-1/576/WAL-004	Wall: Internal - 4 - Linear Stairs - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels above Entrance Door					
11657	ACTIVE	N	N147-00-1/661	Switch Room - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16224	ACTIVE	N	N147-00-1/661/FLR-01	Floor - 1 - Switch Room - Station Building - Stockwell Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Red & Grey Vinyl Floor Tiles (non asbestos)					
45029	ACTIVE	N	N147-00-1/661/FLR-01	Floor - 1 - Switch Room - Station Building - Stockwell Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer to floor by wall 2				N	N
11658	ACTIVE	N	N147-00-1/663	Switch Room - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19095	ACTIVE	N	N147-00-1/663/FLR-01	Floor - 1 - Switch Room - Station Building - Stockwell Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Red & Grey Vinyl Floor Tiles (non asbestos)					
16225	ACTIVE	N	N147-00-1/663/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Stockwell Stn	Other Electrical Boxes	Asbestos	Surveyed – Not Detected				Electrical Equipment				YES	
16226	ACTIVE	N	N147-00-1/667	Vent Shaft - Station Building - Stockwell Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11659	ACTIVE	N	N147-00-1/668	Switch Room - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18325	ACTIVE	N	N147-00-1/668	Switch Room - Station Building - Stockwell Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Cable Ducts					
43252	ACTIVE	N	N147-00-1/668/FLR-01	Floor - 1 - Switch Room - Station Building - Stockwell Stn	Other Electrical Boxes	Asbestos	Presumed				3 x Transformer boxes				N	N
19096	ACTIVE	N	N147-00-1/668/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Stockwell Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes - Insulation within		6			
16229	ACTIVE	N	N147-00-1/668/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Stockwell Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Trunking Insulation within		1			
16228	ACTIVE	N	N147-00-1/668/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing					
11660	ACTIVE	N	N147-00-1/669	Switch Cupboard - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16227	ACTIVE	N	N147-00-1/669/DOR-01	Door - 1 - Switch Cupboard - Station Building - Stockwell Stn	Durasteel	Asbestos	Sampled – Not Detected				Door for Electric Cupboard to 1/669 - Durasteel					
11661	ACTIVE	N	N147-00-1/700	SER - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11662	ACTIVE	N	N147-00-1/731	CER - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45030	ACTIVE	N	N147-00-1/731	CER - Station Building - Stockwell Stn	Other Boarding	Asbestos	Known				Brown Compostie Boarding Panel				N	N
16230	ACTIVE	N	N147-00-1/731	CER - Station Building - Stockwell Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11663	ACTIVE	N	N147-00-1/746	Telephone Exchange Room - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16232	ACTIVE	N	N147-00-1/746/CLG-01	Ceiling: Suspended - 1 - Telephone Exchange Room - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling				YES	
16231	ACTIVE	N	N147-00-1/746/CLG-01	Ceiling: Suspended - 1 - Telephone Exchange Room - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
11664	ACTIVE	N	N147-00-1/747	SCR - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45034	ACTIVE	N	N147-00-1/747	SCR - Station Building - Stockwell Stn	Other Boarding	Asbestos	Known				Kitchen (On Station Layout as SCR) - Brown composite panels - To electrical equipment to wall 1 (within)				N	N
45033	ACTIVE	N	N147-00-1/747	SCR - Station Building - Stockwell Stn	Bitumen	Asbestos	Known				Kitchen (On Station Layout as SCR) - Bitumen adhesive/backing on concrete slab - To rear of red and grey floor tiles to floor				N	N
45037	ACTIVE	N	N147-00-1/747	SCR - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Known				Red braided cable - Running from electrical equipment to wall 1 and into wall 4				N	N
45035	ACTIVE	N	N147-00-1/747	SCR - Station Building - Stockwell Stn		Asbestos	Known				Kitchen (On Station Layout as SCR) - Brown composite panels/washers - To metal racking throughout - some are new				N	N
16233	ACTIVE	N	N147-00-1/747/CLG-01	Ceiling: Solid - 1 - SCR - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
19097	ACTIVE	N	N147-00-1/747/CLG-01	Ceiling: Solid - 1 - SCR - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Vermiculite Panelling; Concrete above Supalux Ceiling				YES	
18894	ACTIVE	N	N147-00-1/747/FLR-01	Floor - 1 - SCR - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				Floor Hatch - Drains beneath					YES
45032	ACTIVE	N	N147-00-1/747/FLR-01	Floor - 1 - SCR - Station Building - Stockwell Stn	Vinyl tiles	Asbestos	Known				Kitchen (On Station Layout as SCR) - Red & Grey floor tiles on concrete slab				N	N
45036	ACTIVE	N	N147-00-1/747/WAL-001	Wall: Internal - 1 - SCR - Station Building - Stockwell Stn	Other Electrical Boxes	Asbestos	Known				Materials within distribution rectifier and retard boxes				N	N
11665	ACTIVE	N	N147-00-1/751	Station Control Room - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16080	ACTIVE	N	N147-00-1/751/CLG-01	Ceiling: Suspended - 1 - Station Control Room - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Rubber & Plastic Cables above Supalux Tiles				YES	
18929	ACTIVE	N	N147-00-1/751/CLG-01	Ceiling: Suspended - 1 - Station Control Room - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
16234	ACTIVE	N	N147-00-1/751/FLR-01	Floor - 1 - Station Control Room - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath Computer Flooring					YES
11666	ACTIVE	N	N147-00-1/761	Equipment Room - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16081	ACTIVE	N	N147-00-1/761	Equipment Room - Station Building - Stockwell Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
16082	ACTIVE	N	N147-00-1/791	Vent Shaft - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Low Level at Base: Tunnel Ring Caulking Seals					
16271	ACTIVE	N	N147-00-1/792	Vent Shaft - Station Building - Stockwell Stn	Caulking	Asbestos	Known				Tunnel Ring Caulking (VP68)					
16083	ACTIVE	N	N147-00-1/792	Vent Shaft - Station Building - Stockwell Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11667	ACTIVE	N	N147-00-2/091	Circulation Area - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18930	ACTIVE	N	N147-00-2/091/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking - Encapsulated				YES	
11668	ACTIVE	N	N147-00-2/161	LMC - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16085	ACTIVE	N	N147-00-2/161/CLG-01	Ceiling: Solid - 1 - LMC - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel W2					
19955	ACTIVE	N	N147-00-2/161/FLR-01	Floor - 1 - LMC - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				No Access Floor Hatch x 2					YES
16086	ACTIVE	N	N147-00-2/161/WAL-001	Wall: Internal - 1 - LMC - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking - Encapsulated					
16084	ACTIVE	N	N147-00-2/161/WAL-002	Wall: Internal - 2 - LMC - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				1 x Cable					
11669	ACTIVE	N	N147-00-2/201	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19349	ACTIVE	N	N147-00-2/201	Passage - Station Building - Stockwell Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11670	ACTIVE	N	N147-00-2/202	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16087	ACTIVE	N	N147-00-2/202/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking - Encapsulated				YES	
11671	ACTIVE	N	N147-00-2/203	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16088	ACTIVE	N	N147-00-2/203/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking - Encapsulated				YES	
18931	ACTIVE	N	N147-00-2/203/FLR-01	Floor - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				No Access Floor Hatch x 2					YES
11672	ACTIVE	N	N147-00-2/204	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16089	ACTIVE	N	N147-00-2/204/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking - Encapsulated				YES	
11673	ACTIVE	N	N147-00-2/236	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16090	ACTIVE	N	N147-00-2/236	Passage - Station Building - Stockwell Stn	Boarding: Cement	Asbestos	Known				Bricks; Join 0.01m2 - Chrysotile					
16091	ACTIVE	N	N147-00-2/236/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	
11674	ACTIVE	N	N147-00-2/237	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18881	ACTIVE	N	N147-00-2/237	Passage - Station Building - Stockwell Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11675	ACTIVE	N	N147-00-2/577	Stairs: Linear - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18932	ACTIVE	N	N147-00-2/577	Stairs: Linear - Station Building - Stockwell Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11676	ACTIVE	N	N147-00-2/579	Stairs: Linear - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16092	ACTIVE	N	N147-00-2/579	Stairs: Linear - Station Building - Stockwell Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11677	ACTIVE	N	N147-00-2/601	Stairs: Linear - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16094	ACTIVE	N	N147-00-2/601/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Metal Corrugated Sheet				YES	
16093	ACTIVE	N	N147-00-2/601/FLR-01	Floor - 1 - Linear Stairs - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				No Access Floor Hatch x 2					YES
11678	ACTIVE	N	N147-00-2/602	Stairs: Linear - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18933	ACTIVE	N	N147-00-2/602/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Part Supalux, metal corrugated sheet - no access above, metal sheets				YES	
11679	ACTIVE	N	N147-00-2/603	Stairs: Linear - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16095	ACTIVE	N	N147-00-2/603	Stairs: Linear - Station Building - Stockwell Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
16096	ACTIVE	N	N147-00-2/646	Gantry - Station Building - Stockwell Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access - leads to trackside					
11680	ACTIVE	N	N147-00-2/661	Switch Room - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18882	ACTIVE	N	N147-00-2/661	Switch Room - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding					
11681	ACTIVE	N	N147-00-2/662	Switch Room - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16097	ACTIVE	N	N147-00-2/662	Switch Room - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding above door					
11682	ACTIVE	N	N147-00-2/711	CER - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45038	ACTIVE	N	N147-00-2/711	CER - Station Building - Stockwell Stn	Other Electrical Boxes	Asbestos	Known				Transformer Box Insulation within				N	N
16098	ACTIVE	N	N147-00-2/711	CER - Station Building - Stockwell Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
45039	ACTIVE	N	N147-00-2/711	CER - Station Building - Stockwell Stn	Other Boarding	Asbestos	Known				Brown Composite Panel				N	N
11683	ACTIVE	N	N147-00-2/761	Equipment Room - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45031	ACTIVE	N	N147-00-2/761	Equipment Room - Station Building - Stockwell Stn	Caulking	Asbestos	Known				Tunnel Ring Caulking to Tunnel Ring Joints				N	N



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16099	ACTIVE	N	N147-00-2/761	Equipment Room - Station Building - Stockwell Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
18934	ACTIVE	N	N147-00-2/791	Vent Shaft - Station Building - Stockwell Stn	Caulking	Asbestos	Sampled – Not Detected				Fibrous Caulking laid into tunnel ring flange / Cement within uncapped tunnel ring flange					
45040	ACTIVE	N	N147-00-2/791	Vent Shaft - Station Building - Stockwell Stn		Asbestos	Known				Cable - To tunnel ring right hand side				N	N
16100	ACTIVE	N	N147-00-2/791	Vent Shaft - Station Building - Stockwell Stn	Gasket :Pipework	Asbestos	Sampled – Not Detected				Gasket between pipe sections to fire hydrant pipework beside catwalk					
45041	ACTIVE	N	N147-00-2/791	Vent Shaft - Station Building - Stockwell Stn	Caulking	Asbestos	Known				To tunnel ring joints (no access)				N	N
11684	ACTIVE	N	N147-00-3/081	Circulation Area - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45042	ACTIVE	N	N147-00-3/081	Circulation Area - Station Building - Stockwell Stn	Cellactite Sheeting	Asbestos	Strongly Presumed				Cellactite - SP - Behind metal panels to wall - limited access				N	N
20011	ACTIVE	N	N147-00-3/081/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling - Metal Sheeting - No Access Above; Metal Trim				YES	
16101	ACTIVE	N	N147-00-3/081/FLR-01	Floor - 1 - Circulation Area - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Floor Hatches: Cable Shaft & Escalator Chamber beneath false floor					YES
16102	ACTIVE	N	N147-00-3/081/WAL-002	Wall: Internal - 2 - Circulation Area - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
11685	ACTIVE	N	N147-00-3/082	Circulation Area - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45043	ACTIVE	N	N147-00-3/082	Circulation Area - Station Building - Stockwell Stn	Cellactite Sheeting	Asbestos	Strongly Presumed				Cellactite - SP - Behind metal panels to wall - limited access				N	N
16170	ACTIVE	N	N147-00-3/082/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				Metal Corrugated sheets - No access above; Trunking - above Metal Sheeting False Ceiling				YES	
16103	ACTIVE	N	N147-00-3/082/FLR-01	Floor - 1 - Circulation Area - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				No Access Floor Hatch					YES
11686	ACTIVE	N	N147-00-3/161	LMC - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16173	ACTIVE	N	N147-00-3/161	LMC - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boards					
45044	ACTIVE	N	N147-00-3/161	LMC - Station Building - Stockwell Stn	Caulking	Asbestos	Known				Caulking to flanges of metal tunnel walls				N	N



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42183	ACTIVE	N	N147-00-3/161	LMC - Station Building - Stockwell Stn	Boarding: Cement	Asbestos	Known				Cement shuttering throughout to ceiling within vent ducts				N	N
16175	ACTIVE	N	N147-00-3/161	LMC - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				40m x 15mm Green Cable present		1			
16174	ACTIVE	N	N147-00-3/161	LMC - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Lobby: Caulking in between steel tunnel rings - Encapsulated					
16171	ACTIVE	N	N147-00-3/161/FLR-01	Floor - 1 - LMC - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				Floor Hatch beneath Concrete Floor					YES
19016	ACTIVE	N	N147-00-3/161/WAL-002	Wall: Internal - 2 - LMC - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking					
16172	ACTIVE	N	N147-00-3/161/WAL-004	Wall: Internal - 4 - LMC - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking					
11687	ACTIVE	N	N147-00-3/201	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19017	INACTIVE	N	N147-00-3/201/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				Above Supalux Boards				YES	
16176	ACTIVE	N	N147-00-3/201/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	No Access: Presumed				Supalux Boards					
11688	ACTIVE	N	N147-00-3/202	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16178	ACTIVE	N	N147-00-3/202/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				Above Supalux Boards				YES	
16177	ACTIVE	N	N147-00-3/202/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Boards					
11689	ACTIVE	N	N147-00-3/203	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16179	ACTIVE	N	N147-00-3/203/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				Above Supalux Boards				YES	
18890	ACTIVE	N	N147-00-3/203/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Boards					
11690	ACTIVE	N	N147-00-3/204	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16180	ACTIVE	N	N147-00-3/204/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Boards					
16181	ACTIVE	N	N147-00-3/204/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking Encapsulated - above Supalux Board				YES	



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18323	INACTIVE	N	N147-00-3/204/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking Encapsulated - above Supalux Board				YES	
19018	ACTIVE	N	N147-00-3/204/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Boards					
19350	ACTIVE	N	N147-00-3/204/FLR-01	Floor - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				No Access Floor Hatch					YES
11691	ACTIVE	N	N147-00-3/205	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
11692	ACTIVE	N	N147-00-3/206	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16183	ACTIVE	N	N147-00-3/206/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	Surveyed - Not Detected				Metal Trunking / Concrete needs removing from the whole ceiling to see all of area				YES	
16182	ACTIVE	N	N147-00-3/206/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Boards					
11693	ACTIVE	N	N147-00-3/207	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18751	ACTIVE	N	N147-00-3/207/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Boards					
19019	ACTIVE	N	N147-00-3/207/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				Above Supalux Board				YES	
11694	ACTIVE	N	N147-00-3/208	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16184	ACTIVE	N	N147-00-3/208/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Boards					
18891	ACTIVE	N	N147-00-3/208/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	Surveyed - Not Detected				Metal Trunking / Concrete needs removing from the whole ceiling to see all of area				YES	
11695	ACTIVE	N	N147-00-3/209	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16185	ACTIVE	N	N147-00-3/209	Passage - Station Building - Stockwell Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11696	ACTIVE	N	N147-00-3/210	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16186	ACTIVE	N	N147-00-3/210/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16187	ACTIVE	N	N147-00-3/210/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Supalux Tiles				YES	
11697	ACTIVE	N	N147-00-3/211	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19020	ACTIVE	N	N147-00-3/211/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	
11698	ACTIVE	N	N147-00-3/212	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16189	ACTIVE	N	N147-00-3/212/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Supalux Tiles				YES	
16188	ACTIVE	N	N147-00-3/212/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
11699	ACTIVE	N	N147-00-3/213	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16190	ACTIVE	N	N147-00-3/213/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
16191	ACTIVE	N	N147-00-3/213/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Supalux Tiles				YES	
11700	ACTIVE	N	N147-00-3/214	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16192	ACTIVE	N	N147-00-3/214/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
19021	ACTIVE	N	N147-00-3/214/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Supalux Tiles				YES	
11701	ACTIVE	N	N147-00-3/215	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16195	ACTIVE	N	N147-00-3/215/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				Metal Corrugated sheet above False Ceiling - No Access above				YES	
16194	ACTIVE	N	N147-00-3/215/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
16193	ACTIVE	N	N147-00-3/215/FLR-01	Floor - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				No Access beneath Floor Hatch					YES
11702	ACTIVE	N	N147-00-3/216	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16197	ACTIVE	N	N147-00-3/216/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				Metal Corrugated sheet above Supalux Tiles - No Access above				YES	
19087	ACTIVE	N	N147-00-3/216/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
16196	ACTIVE	N	N147-00-3/216/FLR-01	Floor - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				No Access beneath Floor Hatch					YES
11703	ACTIVE	N	N147-00-3/217	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16199	ACTIVE	N	N147-00-3/217/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
16200	ACTIVE	N	N147-00-3/217/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				Metal Corrugated sheet above Supalux Tiles - No Access above				YES	
16198	ACTIVE	N	N147-00-3/217/FLR-01	Floor - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				No Access beneath Floor Hatch					YES
11704	ACTIVE	N	N147-00-3/218	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20013	ACTIVE	N	N147-00-3/218/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
19088	ACTIVE	N	N147-00-3/218/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	
11705	ACTIVE	N	N147-00-3/219	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16202	ACTIVE	N	N147-00-3/219/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	
16201	ACTIVE	N	N147-00-3/219/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
11706	ACTIVE	N	N147-00-3/236	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16203	ACTIVE	N	N147-00-3/236/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking - Encapsulated					
18324	ACTIVE	N	N147-00-3/236/WAL-001	Wall: Internal - 1 - Passage - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				All Walls - Tunnel Ring Caulking - Encapsulated					
11707	ACTIVE	N	N147-00-3/237	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45045	ACTIVE	N	N147-00-3/237	Passage - Station Building - Stockwell Stn	Caulking	Asbestos	Known				Tunnel Ring Caulking To Tunnel Ring Joints Throughout				N	N



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19956	ACTIVE	N	N147-00-3/237	Passage - Station Building - Stockwell Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Cable Ducts					
16205	ACTIVE	N	N147-00-3/237	Passage - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking Halfway to 3/236 Partly Encapsulated					
16206	ACTIVE	N	N147-00-3/237	Passage - Station Building - Stockwell Stn	Lead/Leading	Lead Paint/Lead	Known				Dark brown coloured paint applied to the floodgate. Analysis 13.5%					
19089	ACTIVE	N	N147-00-3/237/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking - Encapsulated					
16204	ACTIVE	N	N147-00-3/237/WAL-001	Wall: Internal - 1 - Passage - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				All Walls - Tunnel Ring Caulking - Encapsulated					
11708	ACTIVE	N	N147-00-3/238	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16208	ACTIVE	N	N147-00-3/238/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking - Chrysotile & Amphibole					
16207	ACTIVE	N	N147-00-3/238/WAL-001	Wall: Internal - 1 - Passage - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking - Chrysotile & Amphibole					
18892	ACTIVE	N	N147-00-3/238/WAL-002	Wall: Internal - 2 - Passage - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking - Chrysotile & Amphibole					
11709	ACTIVE	N	N147-00-3/239	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19090	ACTIVE	N	N147-00-3/239	Passage - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cut Cables on top of Switch Boxes					
16209	ACTIVE	N	N147-00-3/239	Passage - Station Building - Stockwell Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes - Insulation within		2			
16210	ACTIVE	N	N147-00-3/239	Passage - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables					
11710	ACTIVE	N	N147-00-3/240	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18747	ACTIVE	N	N147-00-3/240	Passage - Station Building - Stockwell Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes - Insulation within		2			
16105	ACTIVE	N	N147-00-3/240	Passage - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cut Cables on top of Switch Boxes					
16106	ACTIVE	N	N147-00-3/240	Passage - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables					
16104	ACTIVE	N	N147-00-3/240/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking - Type 3 Confirmed as Non Asbestos					



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16211	ACTIVE	N	N147-00-3/240/WAL-001	Wall: Internal - 1 - Passage - Station Building - Stockwell Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel Ring Caulking - Type 3 Confirmed as Non Asbestos					
16212	ACTIVE	N	N147-00-3/240/WAL-002	Wall: Internal - 2 - Passage - Station Building - Stockwell Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel Ring Caulking - Type 3 Confirmed as Non Asbestos					
19091	ACTIVE	N	N147-00-3/240/WAL-003	Wall: Internal - 3 - Passage - Station Building - Stockwell Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel Ring Caulking - Type 3 Confirmed as Non Asbestos					
11711	ACTIVE	N	N147-00-3/241	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16109	ACTIVE	N	N147-00-3/241/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking - Encapsulated above False Ceiling				YES	
16108	ACTIVE	N	N147-00-3/241/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
16107	ACTIVE	N	N147-00-3/241/FLR-01	Floor - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				No Access Floor Hatch below false floor					
18935	ACTIVE	N	N147-00-3/241/WAL-004	Wall: Internal - 4 - Passage - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board above door					
11712	ACTIVE	N	N147-00-3/242	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18936	ACTIVE	N	N147-00-3/242/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
16112	ACTIVE	N	N147-00-3/242/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stockwell Stn	Caulking	Asbestos	Sampled – Not Detected				Tunnel Ring Caulking - Type 3 Confirmed as Non Asbestos				YES	
16110	ACTIVE	N	N147-00-3/242/FLR-01	Floor - 1 - Passage - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Floor Hatch - Metal to Cable Shaft beneath Concrete floor					
16111	ACTIVE	N	N147-00-3/242/WAL-004	Wall: Internal - 4 - Passage - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel to door					
11713	ACTIVE	N	N147-00-3/243	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16114	ACTIVE	N	N147-00-3/243/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Stockwell Stn	Caulking	Asbestos	Known				Tunnel Ring Caulking - Chrysotile & Amphibole - Encapsulated					
16113	ACTIVE	N	N147-00-3/243/WAL-001	Wall: Internal - 1 - Passage - Station Building - Stockwell Stn	Caulking	Asbestos	Known				All Walls - Tunnel Ring Caulking - Chrysotile & Amphibole - Encapsulated					
11714	ACTIVE	N	N147-00-3/261	Platform 1 - Northbound Local - Victoria Line - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor	
45046	ACTIVE	N	N147-00-3/261	Platform 1 - Northbound Local - Victoria Line - Station Building - Stockwell Stn	Cellactite Sheeting	Asbestos	Known				Cellactite at high level throughout NOTE limited access to metal panels, no access to cellactite at high level				N	N	
18937	ACTIVE	N	N147-00-3/261	Platform 1 - Northbound Local - Victoria Line - Station Building - Stockwell Stn	Cellactite Sheeting	Asbestos	Known				Asbestos ID - Confirmed as Asbestos - Chrysotile - near 3/712						
16115	ACTIVE	N	N147-00-3/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Sealed Tunnel Rings above Metal Sheeting				YES		
16117	ACTIVE	N	N147-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Known				Platform 1 Invert - 23 x various Cables					YES	
16116	ACTIVE	N	N147-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Stockwell Stn	Cable Duct: Other	Asbestos	Known				Platform 1 Invert - 39 x various Cable Sleeves - Chrysotile & Amphibole					YES	
11715	ACTIVE	N	N147-00-3/262	Platform 2 - Northbound Local - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed										
16120	INACTIVE	N	N147-00-3/262	Platform 2 - Northbound Local - Station Building - Stockwell Stn	Westing house Boxes	Asbestos	Presumed				Insulation within Westinghouse Box (trackside)		1				
45047	ACTIVE	N	N147-00-3/262	Platform 2 - Northbound Local - Station Building - Stockwell Stn	Cellactite Sheeting	Asbestos	Strongly Presumed				Cellactite at high level throughout				N	N	
45049	ACTIVE	N	N147-00-3/262	Platform 2 - Northbound Local - Station Building - Stockwell Stn	Cable Ducts: Cement	Asbestos	Strongly Presumed				Platform 2 Invert - 10no cable sleeves near 2/601		10		N	N	
18938	ACTIVE	N	N147-00-3/262	Platform 2 - Northbound Local - Station Building - Stockwell Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Box - Tailwall		1				
45048	ACTIVE	N	N147-00-3/262	Platform 2 - Northbound Local - Station Building - Stockwell Stn	Cable Ducts: Cement	Asbestos	Known				Platform 2 Invert - 18no cable sleeves - Platform 2 Northbound invert 8m and 20m on from 2/601		18		N	N	
19483	ACTIVE	N	N147-00-3/262	Platform 2 - Northbound Local - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				15mm Diameter Cable - near 3/713		1				
18883	ACTIVE	N	N147-00-3/262	Platform 2 - Northbound Local - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				30mm Diameter Cable - near 3/713		1				
16119	ACTIVE	N	N147-00-3/262	Platform 2 - Northbound Local - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				2cm Cable - Tailwall		1				
16121	ACTIVE	N	N147-00-3/262	Platform 2 - Northbound Local - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				15mm Cables		4				
16118	ACTIVE	N	N147-00-3/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Sealed Tunnel Rings above Metal Sheeting				YES		
18748	ACTIVE	N	N147-00-3/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - Various Cables					YES	
11716	ACTIVE	N	N147-00-3/263	Platform 3 - Southbound Local - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed										



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16122	ACTIVE	N	N147-00-3/263	Platform 3 - Southbound Local - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables Trackside		6			
45050	ACTIVE	N	N147-00-3/263	Platform 3 - Southbound Local - Station Building - Stockwell Stn	Other Boarding	Asbestos	Strongly Presumed				Cellactite behind panels to wall				N	N
16123	ACTIVE	N	N147-00-3/263	Platform 3 - Southbound Local - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cable - Trackside Tail Wall Tunnel mouth		1			
18939	ACTIVE	N	N147-00-3/263/CLG-01	Ceiling: Solid - 1 - Platform 3 - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Sealed Tunnel Rings above Metal Sheeting					
18884	ACTIVE	N	N147-00-3/263/FLR-01	Floor - 1 - Platform 3 - Station Building - Stockwell Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Platform 3 Invert - Cable Sleeves, 23no No Access		27			YES
16125	ACTIVE	N	N147-00-3/263/FLR-01	Floor - 1 - Platform 3 - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 3 Invert - Various Cables		6			YES
16124	ACTIVE	N	N147-00-3/263/FLR-01	Floor - 1 - Platform 3 - Station Building - Stockwell Stn	Cable Ducts: Cement	Asbestos	Known				Platform 3 Invert - Cable Sleeves - Chrysotile		24			YES
11717	ACTIVE	N	N147-00-3/264	Platform 4 - Southbound Local - Victoria Line - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16126	ACTIVE	N	N147-00-3/264	Platform 4 - Southbound Local - Victoria Line - Station Building - Stockwell Stn	Other Boarding	Asbestos	No Access: Presumed				Boarding in Tunnel near 3/714					
45051	ACTIVE	N	N147-00-3/264	Platform 4 - Southbound Local - Victoria Line - Station Building - Stockwell Stn	Cellactite Sheeting	Asbestos	Strongly Presumed				Cellactite behind panels to wall				N	N
45052	ACTIVE	N	N147-00-3/264	Platform 4 - Southbound Local - Victoria Line - Station Building - Stockwell Stn	Other Boarding	Asbestos	Strongly Presumed				Boarding in Tunnel near 3/714 - No Access				N	N
19003	ACTIVE	N	N147-00-3/264/CLG-01	Ceiling: Solid - 1 - Platform 4 - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Sealed Tunnel Rings above Metal Sheeting				YES	
18322	ACTIVE	N	N147-00-3/264/FLR-01	Floor - 1 - Platform 4 - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 4 Invert - Various Cables		33		YES	
16128	ACTIVE	N	N147-00-3/264/FLR-01	Floor - 1 - Platform 4 - Station Building - Stockwell Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Platform 4 Invert - Various Cable Sleeves x 42. 10 x Filled in - No Access		42		YES	
16127	ACTIVE	N	N147-00-3/264/FLR-01	Floor - 1 - Platform 4 - Station Building - Stockwell Stn	Cable Duct: Other	Asbestos	Known				Platform 4 Invert - Various Cable Sleeves - 20 x Chrysotile		20		YES	
11718	ACTIVE	N	N147-00-3/381	Store - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16129	ACTIVE	N	N147-00-3/381/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Stockwell Stn	Cellactite Sheeting	Asbestos	Strongly Presumed				Bituminous Corrugated Sheeting					



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11719	ACTIVE	N	N147-00-3/382	Store - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16130	ACTIVE	N	N147-00-3/382/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
18749	ACTIVE	N	N147-00-3/382/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Stockwell Stn	Cellactite Sheeting	Asbestos	Known				Bituminous Corrugated Sheeting in Ceiling - Chrysotile					
18885	ACTIVE	N	N147-00-3/382/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking				YES	
11720	ACTIVE	N	N147-00-3/407	Plant Room - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16131	ACTIVE	N	N147-00-3/407/CLG-01	Ceiling: Suspended - 1 - Cleaners Room - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board					
16132	ACTIVE	N	N147-00-3/407/CLG-01	Ceiling: Suspended - 1 - Cleaners Room - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking				YES	
19004	ACTIVE	N	N147-00-3/407/FLR-01	Floor - 1 - Cleaners Room - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Floor Hatch - Drain Gully beneath Quarry Tiles					
11721	ACTIVE	N	N147-00-3/408	Mess Room - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16133	ACTIVE	N	N147-00-3/408/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board					
16134	ACTIVE	N	N147-00-3/408/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking Encapsulated				YES	
11722	ACTIVE	N	N147-00-3/409	Disused Room - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45053	ACTIVE	N	N147-00-3/409	Disused Room - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Tunnel ring caulking to tunnel ring above false ceiling				N	N
19005	ACTIVE	N	N147-00-3/409/CLG-01	Ceiling: Suspended - 1 - Disused Room - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
16135	ACTIVE	N	N147-00-3/409/CLG-01	Ceiling: Suspended - 1 - Disused Room - Station Building - Stockwell Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Ring Caulking - Type 3 Confirmed as Non Asbestos				YES	
11723	ACTIVE	N	N147-00-3/410	Cleaners Room - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
45054	ACTIVE	N	N147-00-3/410	Cleaners Room - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Tunnel caulking above false ceiling				N	N
16136	ACTIVE	N	N147-00-3/410/CLG-01	Ceiling: Suspended - 1 - Cleaners Room - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
16137	ACTIVE	N	N147-00-3/410/CLG-01	Ceiling: Suspended - 1 - Cleaners Room - Station Building - Stockwell Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Ring Caulking - Type 3 Confirmed as Non Asbestos				YES	
11724	ACTIVE	N	N147-00-3/411	LMC - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16138	ACTIVE	N	N147-00-3/411	LMC - Station Building - Stockwell Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11725	ACTIVE	N	N147-00-3/581	Stairs: Linear - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19006	ACTIVE	N	N147-00-3/581	Stairs: Linear - Station Building - Stockwell Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11726	ACTIVE	N	N147-00-3/662	Switch Room - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45055	ACTIVE	N	N147-00-3/662	Switch Room - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Tunnel ring caulking throughout				N	N
16139	ACTIVE	N	N147-00-3/662/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				Above Supalux Ceiling				YES	
18886	ACTIVE	N	N147-00-3/662/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux					
11727	ACTIVE	N	N147-00-3/663	Switch Room - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45056	ACTIVE	N	N147-00-3/663	Switch Room - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed								N	N
16145	ACTIVE	N	N147-00-3/663	Switch Room - Station Building - Stockwell Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es)		3			
16143	ACTIVE	N	N147-00-3/663/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				Above Supalux Board				YES	
16141	ACTIVE	N	N147-00-3/663/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board					



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16140	ACTIVE	N	N147-00-3/663/FLR-01	Floor - 1 - Switch Room - Station Building - Stockwell Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Red Vinyl - Non Asbestos					
19008	ACTIVE	N	N147-00-3/663/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables		2			
16142	ACTIVE	N	N147-00-3/663/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Stockwell Stn	Other Electrical Boxes	Asbestos	Surveyed – Not Detected				Electrical Equipment					
16144	ACTIVE	N	N147-00-3/663/WAL-005	Wall: Internal - 5 - Switch Room - Station Building - Stockwell Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Box Insulation within		1			
19007	ACTIVE	N	N147-00-3/663/WAL-006	Wall: Internal - 6 - Switch Room - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel above entrance					
11728	ACTIVE	N	N147-00-3/664	Switch Cupboard - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45057	ACTIVE	N	N147-00-3/664	Switch Cupboard - Station Building - Stockwell Stn	Caulking	Asbestos	Known				Tunnel ring caulking to tunnel ring joints on walls and ceiling				N	N
19009	ACTIVE	N	N147-00-3/664	Switch Cupboard - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				New Build Formerly part of 3/238 - therefore Tunnel Ring Caulking - Encapsulated					
11729	ACTIVE	N	N147-00-3/711	Relay Room - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16147	ACTIVE	N	N147-00-3/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables		2			
16148	ACTIVE	N	N147-00-3/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables		31			
16146	ACTIVE	N	N147-00-3/711/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Stockwell Stn	Other Boarding	Asbestos	Strongly Presumed				Packing between Electrical Equipment					
11730	ACTIVE	N	N147-00-3/712	Relay Room - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19010	ACTIVE	N	N147-00-3/712	Relay Room - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				Various Cables 2 cables from invert near wall 1 going to wall 2 duct Approx 12 cut cables from duct wall 1 Approx 7 cables to wall 2 cut		10			
53778	ACTIVE	N	N147-00-3/712	Relay Room - Station Building - Stockwell Stn	Other Boarding	Asbestos	Sampled – Not Detected				packing board throughout frame					
42321	INACTIVE	N	N147-00-3/712	Relay Room - Station Building - Stockwell Stn	PCBs	Polychlorinated biphenyl	Presumed				3 x Blue Cyclinder PCB'S - wall mounted Fair Condition		3		N	N
53777	ACTIVE	N	N147-00-3/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Stockwell Stn	Other Boarding	Asbestos	Presumed				Wall 2 1x Brown composite board long					



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11731	ACTIVE	N	N147-00-3/713	Relay Room - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16149	ACTIVE	N	N147-00-3/713	Relay Room - Station Building - Stockwell Stn	Vinyl tiles	Asbestos	Known				Marley tiles to walls - Known asbestos					
45059	INACTIVE	N	N147-00-3/713	Relay Room - Station Building - Stockwell Stn	Vinyl tiles	Asbestos	Known				Grey marley tiles to walls				N	N
18887	ACTIVE	N	N147-00-3/713/CLG-01	Ceiling: Suspended - 1 - Relay Room - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux					
16151	ACTIVE	N	N147-00-3/713/CLG-01	Ceiling: Suspended - 1 - Relay Room - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling				YES	
16150	ACTIVE	N	N147-00-3/713/FLR-01	Floor - 1 - Relay Room - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Panel by W2					
45058	ACTIVE	N	N147-00-3/713/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Stockwell Stn	Other Boarding	Asbestos	Known				2x brown composite panel to racking				N	N
11732	ACTIVE	N	N147-00-3/714	Relay Room - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
45060	ACTIVE	N	N147-00-3/714	Relay Room - Station Building - Stockwell Stn	Other Boarding	Asbestos	Known				16x brown composite panels to rear of racking to walls				N	N
16152	ACTIVE	N	N147-00-3/714	Relay Room - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables		18			
19011	ACTIVE	N	N147-00-3/714/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Stockwell Stn	Other Boarding	Asbestos	Strongly Presumed				Packing between Electrical Equipment					
11733	ACTIVE	N	N147-00-3/715	Relay Room - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
53779	ACTIVE	N	N147-00-3/715	Relay Room - Station Building - Stockwell Stn	Other Boarding	Asbestos	Sampled - Not Detected				packing board to frame throughout (as 3/712)					
16153	ACTIVE	N	N147-00-3/715	Relay Room - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables various, many cut and encapsulated presumed duct to wall - x16 cables cut approx. x4 cables running length from wall 2 duct to wall 3 invert		18			
11734	ACTIVE	N	N147-00-3/716	SER - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16154	ACTIVE	N	N147-00-3/716	SER - Station Building - Stockwell Stn	Vinyl tiles	Asbestos	Strongly Presumed				Tunnel rings encapsulated					



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11735	ACTIVE	N	N147-00-3/731	CER - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18750	ACTIVE	N	N147-00-3/731	CER - Station Building - Stockwell Stn	Other Electrical Boxes	Asbestos	Surveyed - Not Detected				Electrical Equipment					
16156	ACTIVE	N	N147-00-3/731/CLG-01	Ceiling: Suspended - 1 - CER - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking				YES	
16155	ACTIVE	N	N147-00-3/731/CLG-01	Ceiling: Suspended - 1 - CER - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
11736	ACTIVE	N	N147-00-3/732	CER - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18888	ACTIVE	N	N147-00-3/732	CER - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables		5			
16157	ACTIVE	N	N147-00-3/732/CLG-01	Ceiling: Suspended - 1 - CER - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Board					
19012	ACTIVE	N	N147-00-3/732/CLG-01	Ceiling: Suspended - 1 - CER - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking				YES	
11737	ACTIVE	N	N147-00-3/733	CER - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18459	ACTIVE	N	N147-00-3/733/FLR-01	Floor - 1 - CER - Station Building - Stockwell Stn	Void	Asbestos	Surveyed - Not Detected				Concrete beneath Computer Flooring					YES
16158	ACTIVE	N	N147-00-3/733/WAL-003	Wall: Internal - 3 - CER - Station Building - Stockwell Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes 60amp - Insulation within		2			
11738	ACTIVE	N	N147-00-3/734	Lobby - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16160	ACTIVE	N	N147-00-3/734/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				Above Metal Corrugated Sheeting, Wooden Slats				YES	
16159	ACTIVE	N	N147-00-3/734/FLR-01	Floor - 1 - Lobby - Station Building - Stockwell Stn	Void	Asbestos	Surveyed - Not Detected				Concrete beneath Computer Flooring					YES
11739	ACTIVE	N	N147-00-3/761	Equipment Room - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16162	ACTIVE	N	N147-00-3/761	Equipment Room - Station Building - Stockwell Stn	Vinyl tiles	Asbestos	Surveyed - Not Detected				Walls - Grey Vinyl - Non Asbestos					
19013	ACTIVE	N	N147-00-3/761/CLG-01 80910969	Ceiling: Suspended - 1 - Equipment Room - Station Building - Stockwell Stn Ceiling: Suspended	Caulking	Asbestos	Known				Tunnel Ring Caulking. Type 3 - Confirmed as Asbestos 17/09/03				YES	



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16161	ACTIVE	N	N147-00-3/761/CLG-01	Ceiling: Suspended - 1 - Equipment Room - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
43251	ACTIVE	N	N147-00-3/761/WAL-001	Wall: Internal - 1 - Equipment Room - Station Building - Stockwell Stn	Vinyl tiles	Asbestos	Presumed				Vinyl Tiles on all walls				N	N
11740	ACTIVE	N	N147-00-3/762	Computer Equipment Cupboard - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16163	ACTIVE	N	N147-00-3/762	Computer Equipment Cupboard - Station Building - Stockwell Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
11741	ACTIVE	N	N147-00-3/763	Computer Equipment Cupboard - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20012	ACTIVE	N	N147-00-3/763	Computer Equipment Cupboard - Station Building - Stockwell Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
11742	ACTIVE	N	N147-00-3/764	Computer Equipment Cupboard - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16164	ACTIVE	N	N147-00-3/764	Computer Equipment Cupboard - Station Building - Stockwell Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
11743	ACTIVE	N	N147-00-3/765	Computer Equipment Cupboard - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16165	ACTIVE	N	N147-00-3/765	Computer Equipment Cupboard - Station Building - Stockwell Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
11744	ACTIVE	N	N147-00-3/766	Computer Equipment Cupboard - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16166	ACTIVE	N	N147-00-3/766	Computer Equipment Cupboard - Station Building - Stockwell Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
11745	ACTIVE	N	N147-00-3/767	Computer Equipment Cupboard - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19014	ACTIVE	N	N147-00-3/767	Computer Equipment Cupboard - Station Building - Stockwell Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
11746	ACTIVE	N	N147-00-3/768	Computer Equipment Cupboard - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16167	ACTIVE	N	N147-00-3/768	Computer Equipment Cupboard - Station Building - Stockwell Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
11747	ACTIVE	N	N147-00-3/769	Computer Equipment Cupboard - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16168	ACTIVE	N	N147-00-3/769	Computer Equipment Cupboard - Station Building - Stockwell Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
11748	ACTIVE	N	N147-00-3/770	Computer Equipment Cupboard - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19015	ACTIVE	N	N147-00-3/770	Computer Equipment Cupboard - Station Building - Stockwell Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
45072	ACTIVE	N	N147-00-3/901	Vent Shaft - Station Building - Stockwell Stn	Cable Duct: Other	Asbestos	Presumed				10no Cable ducts - cables within - to walls , not able to sample		10		N	N
16169	ACTIVE	N	N147-00-3/901	Vent Shaft - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cable LHS J-Hanger No1		1			
45062	ACTIVE	N	N147-00-3/901	Vent Shaft - Station Building - Stockwell Stn	Cable Ducts: Cement	Asbestos	Known				10no Cement Cable Ducts - To wall right hand side				N	N
45071	ACTIVE	N	N147-00-3/901	Vent Shaft - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Presumed				1no White braided cable				N	N
45074	ACTIVE	N	N147-00-3/901	Vent Shaft - Station Building - Stockwell Stn	Cable Duct: Other	Asbestos	Presumed				10no Cable ducts - cables within to walls		10		N	N
45075	ACTIVE	N	N147-00-3/901	Vent Shaft - Station Building - Stockwell Stn	Cable Duct: Other	Asbestos	Strongly Presumed				32no Cable ducts		32		N	N
11749	ACTIVE	N	N147-00-4/236	Yard - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18889	ACTIVE	N	N147-00-4/236	Yard - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Westinghouse boxes					
45076	ACTIVE	N	N147-00-4/236	Yard - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Known				Braided cables 2 and 4 J hanger on cable run				N	N
16259	ACTIVE	N	N147-00-4/236	Yard - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking to all Walls and Ceiling					
16260	ACTIVE	N	N147-00-4/236/CLG-01	Ceiling: Solid - 1 - Yard - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above false ceiling				YES	
11750	ACTIVE	N	N147-00-4/237	Passage - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18460	ACTIVE	N	N147-00-4/237	Passage - Station Building - Stockwell Stn	Caulking	Asbestos	Sampled – Not Detected				Ceiling - Type 3 confirmed as Non Asbestos. (CS268B)					
41720	ACTIVE	N	N147-00-4/237	Passage - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Known				1 x Braided cable to middle cable run on side of control panel		1		N	N
45080	ACTIVE	N	N147-00-4/237	Passage - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Known				4no Braided Cables 100m On cable run 6 & 7 J Hanger from top middle passage		4		N	N
41719	ACTIVE	N	N147-00-4/237	Passage - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Known				9 x Braided cable to high level cable run on other side of control panel		9		N	N
45081	ACTIVE	N	N147-00-4/237	Passage - Station Building - Stockwell Stn	Other Boarding	Asbestos	Known				2 x Melamine board, to pump 5 & 6 control box located at existing control panel				N	N
41717	ACTIVE	N	N147-00-4/237	Passage - Station Building - Stockwell Stn	Other Boarding	Asbestos	Known				2 x switch boxes		2		N	N
16263	ACTIVE	N	N147-00-4/237	Passage - Station Building - Stockwell Stn	Cellactite Sheeting	Asbestos	Known				Cellactite Boarding on ceiling - 10m2. Type 3 States 20m2. (CS268B)					
16261	ACTIVE	N	N147-00-4/237	Passage - Station Building - Stockwell Stn	Caulking	Asbestos	Sampled – Not Detected				Walls - Type 3 confirmed as Non Asbestos (CS268B)					
41718	ACTIVE	N	N147-00-4/237	Passage - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Known				4 x Braided cable coming from control panel to track level and 2 x coming in from main sump area and bottom of stairs		4		N	N
41715	ACTIVE	N	N147-00-4/237	Passage - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Known				Braided cable, 1x60m, coming from floor and running along cable run located at bottom of the main stairs up to the existing control panel		1		N	N
45079	ACTIVE	N	N147-00-4/237	Passage - Station Building - Stockwell Stn	Cellactite Sheeting	Asbestos	Known				Cellactite Boarding / Bitumen corrugated sheet to ceiling	250			N	N
41721	ACTIVE	N	N147-00-4/237	Passage - Station Building - Stockwell Stn	Caulking	Asbestos	Known				Caulking within tunnel ring flanges				N	N
41714	ACTIVE	N	N147-00-4/237	Passage - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Known				Braided cable, 1x65m, on cable run between existing control panel and main sump		1		N	N
16262	ACTIVE	N	N147-00-4/237	Passage - Station Building - Stockwell Stn	Other Electrical Boxes	Asbestos	Presumed				Material within electrical box. (CS268B)		1			
45077	ACTIVE	N	N147-00-4/237	Passage - Station Building - Stockwell Stn	Other Electrical Boxes	Asbestos	Known				1no Transformer - To far end wall by IMR		1		N	N
19105	ACTIVE	N	N147-00-4/237	Passage - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Presumed				Cables around pump in shaft. (CS268B)					
45078	ACTIVE	N	N147-00-4/237	Passage - Station Building - Stockwell Stn	Westing house Boxes	Asbestos	Known				2no Westinghouse boxes - To wall, left wall 1 past cable run		2		N	N



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11751	ACTIVE	N	N147-00-4/706	IMR - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16264	ACTIVE	N	N147-00-4/706/CLG-01	Ceiling: Solid - 1 - IMR - Station Building - Stockwell Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	
45082	ACTIVE	N	N147-00-4/706/WAL-001	Wall: Internal - 1 - IMR - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Known				Green Braided cables - To wall 1 above A/C unit far end- numerous				N	N
17946	ACTIVE	N	N147-00-4/706/WAL-001	Wall: Internal - 1 - IMR - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables and wall mounted PCB's Silver wall mounted		6			
45083	ACTIVE	N	N147-00-4/706/WAL-003	Wall: Internal - 3 - IMR - Station Building - Stockwell Stn	Other Boarding	Asbestos	Known				Brown composite panels - throughout to wall 3				N	N
43253	INACTIVE	N	N147-00-4/706/WAL-003	Wall: Internal - 3 - IMR - Station Building - Stockwell Stn	PCBs	Polychlorinated biphenyl	Presumed				8 x green cylinders mounted high on wall Fair Condition				N	N
11752	ACTIVE	N	N147-00-4/707	IMR - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45084	ACTIVE	N	N147-00-4/707	IMR - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Known				Green woven cables - Numerous - Throughout to wall and ceiling				N	N
18897	ACTIVE	N	N147-00-4/707	IMR - Station Building - Stockwell Stn	Isolator Switches	Asbestos	Strongly Presumed				Grey Switch Boxes - Insulation within		2			
16266	ACTIVE	N	N147-00-4/707	IMR - Station Building - Stockwell Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables		8			
16265	ACTIVE	N	N147-00-4/707	IMR - Station Building - Stockwell Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Caulking					
42322	INACTIVE	N	N147-00-4/707	IMR - Station Building - Stockwell Stn	PCBs	Polychlorinated biphenyl	Presumed				8 x Silver Cylinder PCB's - wall mounted Fair Condition		8		N	N
45088	INACTIVE	N	N147-00-4/707	IMR - Station Building - Stockwell Stn	PCBs	Polychlorinated biphenyl	Known				8 x Green Cylinder Wall Mounted PCB		8		N	N
16267	ACTIVE	N	N147-00-4/707/CLG-01	Ceiling: Solid - 1 - IMR - Station Building - Stockwell Stn	Cellactite Sheeting	Asbestos	Known				Cellactite Boarding on ceiling - 10m2					
45085	ACTIVE	N	N147-00-4/707/FLR-01	Floor - 1 - IMR - Station Building - Stockwell Stn	Other Electrical Boxes	Asbestos	Presumed				2no circuit breaker boxes To middle of room frame		2		N	N
45086	ACTIVE	N	N147-00-4/707/WAL-001	Wall: Internal - 1 - IMR - Station Building - Stockwell Stn	Other Boarding	Asbestos	Presumed				Brown composite panel - Throughout				N	N
45087	ACTIVE	N	N147-00-4/707/WAL-003	Wall: Internal - 3 - IMR - Station Building - Stockwell Stn	Other Boarding	Asbestos	Presumed				Brown composite panel - Throughout				N	N
11753	ACTIVE	N	N147-00-4/771	Pump Room - Station Building - Stockwell Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N147-00 - Station Building - Stockwell Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16269	ACTIVE	N	N147-00-4/771/CLG-01	Ceiling: Solid - 1 - Pump Room - Station Building - Stockwell Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board					
16270	ACTIVE	N	N147-00-4/771/CLG-01	Ceiling: Solid - 1 - Pump Room - Station Building - Stockwell Stn	Cellactite Sheeting	Asbestos	Known				Cellactite Roof 15m2				YES	
16268	ACTIVE	N	N147-00-4/771/FLR-01	Floor - 1 - Pump Room - Station Building - Stockwell Stn	Void	Asbestos	Surveyed – Not Detected				Floor Hatch - Sumps beneath Metal Floor					YES
17947	ACTIVE	N	N147-00-4/771/WAL-003	Wall: Internal - 3 - Pump Room - Station Building - Stockwell Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Ring Caulking					

## N153-00 - Station Building - Clapham North Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11754	ACTIVE	N	N153-00-1/001	Booking Hall - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18771	ACTIVE	N	N153-00-1/001	Booking Hall - Station Building - Clapham North Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11755	ACTIVE	N	N153-00-1/011	Ticket Office - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
42488	ACTIVE	N	N153-00-1/011	Ticket Office - Station Building - Clapham North Stn	Void	Asbestos	Surveyed – Not Detected				Beneath False Floor - Concrete, Plastic Cables, Trunking Conduits beneath Computer flooring tiles			R506551	N	Y
42481	ACTIVE	N	N153-00-1/011	Ticket Office - Station Building - Clapham North Stn	Cable Duct: Other	Asbestos	Surveyed – Not Detected				Beneath False Floor - Concrete beneath computer tiles			R506551	N	Y
42477	ACTIVE	N	N153-00-1/011	Ticket Office - Station Building - Clapham North Stn	Mastic	Asbestos	Sampled – Not Detected				Putty throughout joints of Air Conditioning unit			R506551	N	N
42487	ACTIVE	N	N153-00-1/011	Ticket Office - Station Building - Clapham North Stn	Void	Asbestos	Surveyed – Not Detected				Above False Ceiling - Plastic Cables, Trunking and Conduits			R506551	Y	N
42483	ACTIVE	N	N153-00-1/011	Ticket Office - Station Building - Clapham North Stn	Debris: Other	Asbestos	Surveyed – Not Detected				Above False Ceiling - Fibreglass Debris above			R506551	N	Y
15974	ACTIVE	N	N153-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Clapham North Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
15975	ACTIVE	N	N153-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Clapham North Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above False Ceiling				YES	
11756	ACTIVE	N	N153-00-1/021	POM - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
42484	ACTIVE	N	N153-00-1/021	POM - Station Building - Clapham North Stn	Void	Asbestos	Surveyed – Not Detected				Breeze Block, Brick and Concrete above false ceiling			R506551	Y	N



# Hazardous Material Asset Register - Summary



## N153-00 - Station Building - Clapham North Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42479	ACTIVE	N	N153-00-1/021	POM - Station Building - Clapham North Stn	Mastic	Asbestos	Sampled – Not Detected				Putty throughout joints of Air Conditioning unit			R506551	N	N
42490	ACTIVE	N	N153-00-1/021	POM - Station Building - Clapham North Stn	Debris: Other	Asbestos	Surveyed – Not Detected				Below False Floor - Supalux Debris			R506551	N	Y
42485	ACTIVE	N	N153-00-1/021	POM - Station Building - Clapham North Stn	Lagging	Asbestos	Surveyed – Not Detected				Above False Ceiling - A/C Trunking, Fibreglass Lagging, Fibreglass Debris			R506551	Y	N
42489	ACTIVE	N	N153-00-1/021	POM - Station Building - Clapham North Stn	Void	Asbestos	Surveyed – Not Detected				Beneath False Floor - Concrete, plastic cables, trunking and conduits beneath computer floor tiles			R506551	N	Y
42478	ACTIVE	N	N153-00-1/021	POM - Station Building - Clapham North Stn	Debris: Other	Asbestos	Sampled – Not Detected				Above False Ceiling - Dust sample throughout - Note wall 3 seems to be encapsulated - no residue seen.			R506551	Y	N
18772	ACTIVE	N	N153-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Clapham North Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
15976	ACTIVE	N	N153-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Clapham North Stn	Void	Asbestos	Surveyed – Not Detected				Above False Ceiling - Concrete, Breeze Block and Brick			R506551	YES	N
11757	ACTIVE	N	N153-00-1/031	Mess Room - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Below false floor					
15977	ACTIVE	N	N153-00-1/031	Mess Room - Station Building - Clapham North Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - Insulation Foam Board					
11758	ACTIVE	N	N153-00-1/036	Toilet: Unisex - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15978	ACTIVE	N	N153-00-1/036	Toilet: Unisex - Station Building - Clapham North Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Cover to void under sink - Tiles on a Supalux Panel - Supalux Debris in void					
19959	ACTIVE	N	N153-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Clapham North Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Fibreglass Lagging above Supalux Tiles				YES	
15979	ACTIVE	N	N153-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Clapham North Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
11759	ACTIVE	N	N153-00-1/041	Locker Room - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11760	ACTIVE	N	N153-00-1/071	Circulation Area - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18837	ACTIVE	N	N153-00-1/071	Circulation Area - Station Building - Clapham North Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N153-00 - Station Building - Clapham North Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11761	ACTIVE	N	N153-00-1/151	UMC - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
42661	ACTIVE	N	N153-00-1/151	UMC - Station Building - Clapham North Stn	Lead/Leading	Lead Paint/Lead	Sampled - Not Detected				Cream Matt Walls 0.04%			R504501	N	N
15981	ACTIVE	N	N153-00-1/151	UMC - Station Building - Clapham North Stn	Lead/Leading	Lead Paint/Lead	Known				Pipework - Red Oil Based Paint. Thickness .08mm; Est Quantity 30 lm; Analysis 3.08%					
42660	ACTIVE	N	N153-00-1/151	UMC - Station Building - Clapham North Stn	Lead/Leading	Lead Paint/Lead	Sampled - Not Detected				Red Gloss on Floor, Analysis Results 0.09%			R504501	N	N
42663	ACTIVE	N	N153-00-1/151	UMC - Station Building - Clapham North Stn	Lead/Leading	Lead Paint/Lead	Sampled - Not Detected				Cream Matt on Walls at entry level 0.31%			R504501	N	N
44972	ACTIVE	N	N153-00-1/151	UMC - Station Building - Clapham North Stn	Lead/Leading	Lead Paint/Lead	Known				Red Oil Based Paint				N	N
42662	ACTIVE	N	N153-00-1/151	UMC - Station Building - Clapham North Stn	Lead/Leading	Lead Paint/Lead	Sampled - Not Detected				Beige Gloss on Stairs 0.28%			R504501	N	N
15980	ACTIVE	N	N153-00-1/151/FLR-01	Floor - 1 - UMC - Station Building - Clapham North Stn	Durasteel	Asbestos	Surveyed - Not Detected				Lid to Storage Bin					
18740	ACTIVE	N	N153-00-1/151/FLR-01	Floor - 1 - UMC - Station Building - Clapham North Stn	Debris: Cement	Asbestos	Surveyed - Not Detected				Dust / Debris in Duct below Floor					YES
41902	ACTIVE	N	N153-00-1/151/FLR-01	Floor - 1 - UMC - Station Building - Clapham North Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Trasformer Box. Presumed asbestos insulating materials within		1		N	N
15982	ACTIVE	N	N153-00-1/171	Escalator Incline - Station Building - Clapham North Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
11762	ACTIVE	N	N153-00-1/236	Lobby - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15983	ACTIVE	N	N153-00-1/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Clapham North Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Supalux Tiles				YES	
18838	ACTIVE	N	N153-00-1/236/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Clapham North Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
11763	ACTIVE	N	N153-00-1/237	Passage - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15984	ACTIVE	N	N153-00-1/237	Passage - Station Building - Clapham North Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11764	ACTIVE	N	N153-00-1/331	Locker Room - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N153-00 - Station Building - Clapham North Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19348	ACTIVE	N	N153-00-1/331	Locker Room - Station Building - Clapham North Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - Insulation Foam Board					
18839	ACTIVE	N	N153-00-1/331/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Clapham North Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
15985	ACTIVE	N	N153-00-1/331/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Clapham North Stn	Void	Asbestos	No Access: Presumed				No Access above false ceiling - too high				YES	
11765	ACTIVE	N	N153-00-1/401	Locker Room - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15986	ACTIVE	N	N153-00-1/401/CLG-01	Ceiling: Solid - 1 - Locker Room - Station Building - Clapham North Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux, Plaster; Metal Panel					
15987	ACTIVE	N	N153-00-1/401/CLG-01	Ceiling: Solid - 1 - Locker Room - Station Building - Clapham North Stn	Void	Asbestos	No Access: Presumed				No Access under False Ceiling Metal Panel				YES	
11766	ACTIVE	N	N153-00-1/411	Store - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15988	ACTIVE	N	N153-00-1/411	Store - Station Building - Clapham North Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11767	ACTIVE	N	N153-00-1/412	SVC - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18840	ACTIVE	N	N153-00-1/412/CLG-01	Ceiling: Suspended - 1 - SVC - Station Building - Clapham North Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
15989	ACTIVE	N	N153-00-1/412/CLG-01	Ceiling: Suspended - 1 - SVC - Station Building - Clapham North Stn	Void	Asbestos	No Access: Presumed				No Access above false ceiling - too high				YES	
11768	ACTIVE	N	N153-00-1/416	Lobby - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15990	ACTIVE	N	N153-00-1/416/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Clapham North Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
15991	ACTIVE	N	N153-00-1/416/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Clapham North Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Fibreglass above Supalux Tiles				YES	
11769	ACTIVE	N	N153-00-1/417	Toilet: Male - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N153-00 - Station Building - Clapham North Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18809	ACTIVE	N	N153-00-1/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Clapham North Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	
15992	ACTIVE	N	N153-00-1/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Clapham North Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
11770	ACTIVE	N	N153-00-1/418	Toilet: Female - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18841	ACTIVE	N	N153-00-1/418/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Clapham North Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
15993	ACTIVE	N	N153-00-1/418/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Clapham North Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	
11771	ACTIVE	N	N153-00-1/601	Stairs: Linear - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11772	ACTIVE	N	N153-00-1/602	Stairs: Linear - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11773	ACTIVE	N	N153-00-1/603	Stairs: Linear - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11774	ACTIVE	N	N153-00-1/604	Stairs: Linear - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11775	ACTIVE	N	N153-00-1/605	Stairs: Linear - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11776	ACTIVE	N	N153-00-1/631	Stairs: Spiral - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15995	ACTIVE	N	N153-00-1/631	Stairs: Spiral - Station Building - Clapham North Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel Panel					
15994	ACTIVE	N	N153-00-1/631	Stairs: Spiral - Station Building - Clapham North Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - Insulation Foam Board					
15996	ACTIVE	N	N153-00-1/631	Stairs: Spiral - Station Building - Clapham North Stn	Lead/Leading	Lead Paint/Lead	Known				Girder - Cream Oil Based Paint. Thickness .34mm; Est Quantity 50 lm; Analysis 1.32%					
11777	ACTIVE	N	N153-00-1/661	Switch Room - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N153-00 - Station Building - Clapham North Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18741	INACTIVE	N	N153-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Clapham North Stn	Isolator Switches	Asbestos	Removed				5 x Isolator Isolator Switch Boxes - Asbestos free stickers attached.  Flash Guards replaced for SMEP works by EMS Group September 2009		5		N	N
41903	ACTIVE	N	N153-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Clapham North Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box. Presumed asbestos insulating materials within.		1		N	N
11778	ACTIVE	N	N153-00-1/662	Switch Room - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18842	ACTIVE	N	N153-00-1/662	Switch Room - Station Building - Clapham North Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
42040	INACTIVE	N	N153-00-1/662/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Clapham North Stn	Isolator Switches	Asbestos	Room: Asbestos Free				3 x Isolator Switch Boxes - Flash Guards was replaced by EMS Group in September 2009		3		N	N
11779	ACTIVE	N	N153-00-1/663	Switch Room - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42041	INACTIVE	N	N153-00-1/663	Switch Room - Station Building - Clapham North Stn	Isolator Switches	Asbestos	Removed				9 x Isolator Switch Boxes - Flash Guards replaced by EMS Group September 2009		9		N	N
18317	ACTIVE	N	N153-00-1/663/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Clapham North Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				3 x Transformer Boxes. Presumed asbestos insulating materials within		3			
41904	ACTIVE	N	N153-00-1/663/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Clapham North Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box. Presumed asbestos insulation within		1		N	N
11780	ACTIVE	N	N153-00-1/664	Switch Room - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42043	INACTIVE	N	N153-00-1/664	Switch Room - Station Building - Clapham North Stn	Isolator Switches	Asbestos	Removed				5 x Isolator Switch Boxes - Flash Guards replaced by EMS Group September 2009		5		N	N
15997	ACTIVE	N	N153-00-1/664/DOR-01	Door - 1 - Switch Room - Station Building - Clapham North Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel & Door - Non Asbestos					
11781	ACTIVE	N	N153-00-1/746	SCR - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15998	ACTIVE	N	N153-00-1/746	SCR - Station Building - Clapham North Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11782	ACTIVE	N	N153-00-1/751	Station Control Room - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N153-00 - Station Building - Clapham North Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15999	ACTIVE	N	N153-00-1/751/CLG-01	Ceiling: Solid - 1 - Station Control Room - Station Building - Clapham North Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling				YES	
18843	ACTIVE	N	N153-00-1/751/FLR-01	Floor - 1 - Station Control Room - Station Building - Clapham North Stn	Void	Asbestos	No Access: Presumed				Wooden False Floor and Lino					YES
11783	ACTIVE	N	N153-00-2/001	Booking Hall - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
11784	ACTIVE	N	N153-00-2/011	Ticket Office - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
11785	ACTIVE	N	N153-00-2/021	POM - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
11786	ACTIVE	N	N153-00-2/031	Mess Room - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
11787	ACTIVE	N	N153-00-2/071	Circulation Area - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
11788	ACTIVE	N	N153-00-2/081	Circulation Area - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18810	ACTIVE	N	N153-00-2/081	Circulation Area - Station Building - Clapham North Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11789	ACTIVE	N	N153-00-2/161	LMC - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16000	ACTIVE	N	N153-00-2/161	LMC - Station Building - Clapham North Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
16001	ACTIVE	N	N153-00-2/161	LMC - Station Building - Clapham North Stn	Lead/Leading	Lead Paint/Lead	Known				Girder - Cream Oil Based Paint. Thickness .22mm; Est Quantity 6 lm; Analysis 1.38%					
11790	ACTIVE	N	N153-00-2/201	Passage - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16002	ACTIVE	N	N153-00-2/201	Passage - Station Building - Clapham North Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11791	ACTIVE	N	N153-00-2/202	Passage - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16003	ACTIVE	N	N153-00-2/202	Passage - Station Building - Clapham North Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N153-00 - Station Building - Clapham North Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11792	ACTIVE	N	N153-00-2/203	Passage - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18844	ACTIVE	N	N153-00-2/203	Passage - Station Building - Clapham North Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11793	ACTIVE	N	N153-00-2/204	Passage - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16004	ACTIVE	N	N153-00-2/204	Passage - Station Building - Clapham North Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11794	ACTIVE	N	N153-00-2/236	Passage - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11795	ACTIVE	N	N153-00-2/401	Switch Room - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11796	ACTIVE	N	N153-00-2/406	Switch Cupboard - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16005	ACTIVE	N	N153-00-2/406	Switch Cupboard - Station Building - Clapham North Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11797	ACTIVE	N	N153-00-2/416	Mess Room - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11798	ACTIVE	N	N153-00-2/418	Cleaners Room - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11799	ACTIVE	N	N153-00-2/451	Tenancy - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11800	ACTIVE	N	N153-00-2/601	Stairs: Linear - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18811	ACTIVE	N	N153-00-2/601	Stairs: Linear - Station Building - Clapham North Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11801	ACTIVE	N	N153-00-2/661	Equipment Room - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11802	ACTIVE	N	N153-00-2/662	Switch Room - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16006	ACTIVE	N	N153-00-2/662	Switch Room - Station Building - Clapham North Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N153-00 - Station Building - Clapham North Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11803	ACTIVE	N	N153-00-2/663	Switch Cupboard - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18845	ACTIVE	N	N153-00-2/663	Switch Cupboard - Station Building - Clapham North Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11804	ACTIVE	N	N153-00-2/664	Switch Cupboard - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16007	ACTIVE	N	N153-00-2/664	Switch Cupboard - Station Building - Clapham North Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11805	ACTIVE	N	N153-00-2/666	Switch Cupboard - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16008	ACTIVE	N	N153-00-2/666	Switch Cupboard - Station Building - Clapham North Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - No Access					
11806	ACTIVE	N	N153-00-2/731	Passage - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16009	ACTIVE	N	N153-00-2/731	Passage - Station Building - Clapham North Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11807	ACTIVE	N	N153-00-2/732	CER - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18846	ACTIVE	N	N153-00-2/732/FLR-01	Floor - 1 - CER - Station Building - Clapham North Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
42044	INACTIVE	N	N153-00-2/732/WAL-002	Wall: Internal - 2 - CER - Station Building - Clapham North Stn	Isolator Switches	Asbestos	Removed				2 x Isolator Switch Boxes - Flash Guards was replaced for SMEP works by EMS Group September 2009		2		N	N
11808	ACTIVE	N	N153-00-2/746	SCR - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11809	ACTIVE	N	N153-00-2/751	Station Control Room - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11810	ACTIVE	N	N153-00-2/762	SVC - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11811	ACTIVE	N	N153-00-2/901	Disused Room - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11812	ACTIVE	N	N153-00-2/952	CER - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N153-00 - Station Building - Clapham North Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
16010	ACTIVE	N	N153-00-2/952	CER - Station Building - Clapham North Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11813	ACTIVE	N	N153-00-2/953	Switch Room - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18812	ACTIVE	N	N153-00-2/953	Switch Room - Station Building - Clapham North Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11814	ACTIVE	N	N153-00-2/955	CER - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16012	ACTIVE	N	N153-00-2/955/CLG-01	Ceiling: Suspended - 1 - CER - Station Building - Clapham North Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles				YES	
18742	ACTIVE	N	N153-00-2/955/CLG-01	Ceiling: Suspended - 1 - CER - Station Building - Clapham North Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
16011	ACTIVE	N	N153-00-2/955/FLR-01	Floor - 1 - CER - Station Building - Clapham North Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
16013	ACTIVE	N	N153-00-2/986/WAL-001	Wall: Internal - 1 - Vent Shaft - Station Building - Clapham North Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Ring - Concrete Caulking					
18847	ACTIVE	N	N153-00-2/986/WAL-002	Wall: Internal - 2 - Vent Shaft - Station Building - Clapham North Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Ring - Concrete Caulking					
18318	ACTIVE	N	N153-00-2/986/WAL-003	Wall: Internal - 3 - Vent Shaft - Station Building - Clapham North Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Ring - Concrete Caulking					
16014	ACTIVE	N	N153-00-2/986/WAL-004	Wall: Internal - 4 - Vent Shaft - Station Building - Clapham North Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Ring - Concrete Caulking					
11815	ACTIVE	N	N153-00-3/261	Platform 1 - Northbound Local - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16015	ACTIVE	N	N153-00-3/261	Platform 1 - Northbound Local - Station Building - Clapham North Stn	Cable: Sheath	Asbestos	Strongly Presumed				10mm Cable		1			
11816	ACTIVE	N	N153-00-3/262	Platform 2 - Southbound Local - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16016	ACTIVE	N	N153-00-3/262	Platform 2 - Southbound Local - Station Building - Clapham North Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables		2			



# Hazardous Material Asset Register - Summary



## N153-00 - Station Building - Clapham North Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44973	ACTIVE	N	N153-00-3/262	Platform 2 - Southbound Local - Station Building - Clapham North Stn	Cable: Sheath	Asbestos	Known				Braided cable 1no to wall at entrance				N	N
11817	ACTIVE	N	N153-00-3/661	Switch Room - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16017	ACTIVE	N	N153-00-3/661	Switch Room - Station Building - Clapham North Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Panels to outside					
16018	ACTIVE	N	N153-00-3/661/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Clapham North Stn	Void	Asbestos	No Access: Presumed				Above Supalux				YES	
18848	ACTIVE	N	N153-00-3/661/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Clapham North Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux					
11818	ACTIVE	N	N153-00-3/711	SER - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16019	ACTIVE	N	N153-00-3/711	SER - Station Building - Clapham North Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
11819	ACTIVE	N	N153-00-3/731	CER - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16020	ACTIVE	N	N153-00-3/731	CER - Station Building - Clapham North Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
11820	ACTIVE	N	N153-00-3/771	Pump Room - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16021	ACTIVE	N	N153-00-3/771/WAL-001	Wall: Internal - 1 - Pump Room - Station Building - Clapham North Stn	Caulking	Asbestos	Surveyed - Not Detected				Tunnel Ring - Concrete Caulking					
18813	ACTIVE	N	N153-00-3/771/WAL-002	Wall: Internal - 2 - Pump Room - Station Building - Clapham North Stn	Caulking	Asbestos	Surveyed - Not Detected				Tunnel Ring - Concrete Caulking					
18849	ACTIVE	N	N153-00-3/771/WAL-003	Wall: Internal - 3 - Pump Room - Station Building - Clapham North Stn	Caulking	Asbestos	Surveyed - Not Detected				Tunnel Ring - Concrete Caulking					
16022	ACTIVE	N	N153-00-3/771/WAL-004	Wall: Internal - 4 - Pump Room - Station Building - Clapham North Stn	Caulking	Asbestos	Surveyed - Not Detected				Tunnel Ring - Concrete Caulking					
11821	ACTIVE	N	N153-00-3/781	Equipment Room - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16023	ACTIVE	N	N153-00-3/781	Equipment Room - Station Building - Clapham North Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - No Access					



# Hazardous Material Asset Register - Summary



## N153-00 - Station Building - Clapham North Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11822	ACTIVE	N	N153-00-3/782	TXR - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16024	ACTIVE	N	N153-00-3/782	TXR - Station Building - Clapham North Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - No Access					
11823	ACTIVE	N	N153-00-3/783	Switch Room - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44974	ACTIVE	N	N153-00-3/783	Switch Room - Station Building - Clapham North Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1no Auxiliary Transformer to Floor				N	N
44975	ACTIVE	N	N153-00-3/783	Switch Room - Station Building - Clapham North Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1no Remote Control Box to Wall				N	N
16025	ACTIVE	N	N153-00-3/783	Switch Room - Station Building - Clapham North Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - No Access					
44976	ACTIVE	N	N153-00-3/783	Switch Room - Station Building - Clapham North Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1no Marshall Cabinet to Wall				N	N
44977	ACTIVE	N	N153-00-3/783	Switch Room - Station Building - Clapham North Stn	Cable: Sheath	Asbestos	Known				External - Braided cables >4no Going Into Room				N	N
11824	ACTIVE	N	N153-00-3/786	Platform Invert - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16027	ACTIVE	N	N153-00-3/786	Platform Invert - Station Building - Clapham North Stn	Cable Duct: Other	Asbestos	Presumed				Invert. 6 + Ducts at high level (cannot be sampled from out or inside as no safe access via ladder)		6			
16030	ACTIVE	N	N153-00-3/786	Platform Invert - Station Building - Clapham North Stn	Cable: Sheath	Asbestos	Presumed				Invert. - 1 x Green Braided Cable - from track to bottom J hanger		1			
16029	ACTIVE	N	N153-00-3/786	Platform Invert - Station Building - Clapham North Stn	Cable: Sheath	Asbestos	Presumed				Invert. 1 x white braided cable - from track to 3rd J hanger from bottom		1			
16028	ACTIVE	N	N153-00-3/786	Platform Invert - Station Building - Clapham North Stn	Cable Duct: Other	Asbestos	Presumed				Invert. 3+ Ducts at high level (cannot be sampled safely)		3			
16031	ACTIVE	N	N153-00-3/786	Platform Invert - Station Building - Clapham North Stn	Other Electrical Boxes	Asbestos	Presumed				ACMs within electrical equipment between rooms 3/661 & 3/783.					
18851	ACTIVE	N	N153-00-3/786	Platform Invert - Station Building - Clapham North Stn	Cable: Sheath	Asbestos	Presumed				Invert. - 1 x Green Braided Cable - from track to 9th J hanger from top		1			
16026	ACTIVE	N	N153-00-3/786	Platform Invert - Station Building - Clapham North Stn	Cable: Wrap	Asbestos	Surveyed – Not Detected				Tape on Cable & Rope around Cable the length of Cable Run					
18850	ACTIVE	N	N153-00-3/786	Platform Invert - Station Building - Clapham North Stn	Caulking	Asbestos	Sampled – Not Detected				Caulking full length of invert inbetween exposed tunnel rings					
11825	ACTIVE	N	N153-00-3/787	Platform Invert - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N153-00 - Station Building - Clapham North Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18744	ACTIVE	N	N153-00-3/787	Platform Invert - Station Building - Clapham North Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cable Run - Cables SP					
11826	ACTIVE	N	N153-00-3/788	Platform Invert - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16032	ACTIVE	N	N153-00-3/788	Platform Invert - Station Building - Clapham North Stn	Cable Ducts: Bitumen	Asbestos	Strongly Presumed				Bitumen based, at ground level in front of door		4			
19960	ACTIVE	N	N153-00-3/788	Platform Invert - Station Building - Clapham North Stn	Cable Duct: Other	Asbestos	Surveyed – Not Detected				Cable Sleeves					
16033	ACTIVE	N	N153-00-3/788	Platform Invert - Station Building - Clapham North Stn	Isolator Switches	Asbestos	Removed				Presumed rope seal within combination fuse switches flash guards replaced by new electrical boxes		2			
18852	ACTIVE	N	N153-00-3/788	Platform Invert - Station Building - Clapham North Stn	Cable Duct: Other	Asbestos	Surveyed – Not Detected				6+ Ducts at high level (no safe way to sample)		6			
42045	INACTIVE	N	N153-00-3/788	Platform Invert - Station Building - Clapham North Stn	Isolator Switches	Asbestos	Removed				2 x Isolator Switch Boxes - Flash Guards was replaced by EMS Group September 2009		2		N	N
16039	ACTIVE	N	N153-00-3/791	Vent Shaft - Station Building - Clapham North Stn	Cable Duct: Other	Asbestos	Surveyed – Not Detected				Cable Sleeves					
16038	ACTIVE	N	N153-00-3/791/CLG-01	Ceiling: Solid - 1 - Vent Shaft - Station Building - Clapham North Stn	Caulking	Asbestos	Surveyed – Not Detected				Concrete Caulking					
16034	ACTIVE	N	N153-00-3/791/WAL-001	Wall: Internal - 1 - Vent Shaft - Station Building - Clapham North Stn	Caulking	Asbestos	Surveyed – Not Detected				Concrete Caulking					
16035	ACTIVE	N	N153-00-3/791/WAL-002	Wall: Internal - 2 - Vent Shaft - Station Building - Clapham North Stn	Caulking	Asbestos	Surveyed – Not Detected				Concrete Caulking					
16036	ACTIVE	N	N153-00-3/791/WAL-003	Wall: Internal - 3 - Vent Shaft - Station Building - Clapham North Stn	Caulking	Asbestos	Surveyed – Not Detected				Concrete Caulking					
18853	ACTIVE	N	N153-00-3/791/WAL-004	Wall: Internal - 4 - Vent Shaft - Station Building - Clapham North Stn	Caulking	Asbestos	Surveyed – Not Detected				Concrete Caulking					
16037	ACTIVE	N	N153-00-3/791/WAL-005	Wall: Internal - 5 - Vent Shaft - Station Building - Clapham North Stn	Caulking	Asbestos	Surveyed – Not Detected				Concrete Caulking					
11827	ACTIVE	N	N153-00-A/081	Lobby - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18814	ACTIVE	N	N153-00-A/081	Lobby - Station Building - Clapham North Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N153-00 - Station Building - Clapham North Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11828	ACTIVE	N	N153-00-B/081	Lobby - Station Building - Clapham North Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16040	ACTIVE	N	N153-00-B/081	Lobby - Station Building - Clapham North Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					

## N155-00 - Station Building - Clapham Common Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11829	ACTIVE	N	N155-00-1/601	Stairs: Linear - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15920	ACTIVE	N	N155-00-1/601	Stairs: Linear - Station Building - Clapham Common Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11830	ACTIVE	N	N155-00-1/602	Stairs: Linear - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15921	ACTIVE	N	N155-00-1/602	Stairs: Linear - Station Building - Clapham Common Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11831	ACTIVE	N	N155-00-1/603	Stairs: Linear - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15922	ACTIVE	N	N155-00-1/603	Stairs: Linear - Station Building - Clapham Common Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11832	ACTIVE	N	N155-00-1/604	Stairs: Linear - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15923	ACTIVE	N	N155-00-1/604/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Clapham Common Stn	Void	Asbestos	Surveyed – Not Detected				Metal above Metal Ceiling				YES	
11833	ACTIVE	N	N155-00-1/605	Stairs: Linear - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18803	ACTIVE	N	N155-00-1/605	Stairs: Linear - Station Building - Clapham Common Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11834	ACTIVE	N	N155-00-2/001	Booking Hall - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15924	ACTIVE	N	N155-00-2/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Clapham Common Stn	Void	Asbestos	No Access: Presumed				Above Metal Tiles				YES	



# Hazardous Material Asset Register - Summary



## N155-00 - Station Building - Clapham Common Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18757	ACTIVE	N	N155-00-2/001/FLR-01	Floor - 1 - Booking Hall - Station Building - Clapham Common Stn	Cable Ducts: Bitumen	Asbestos	Known				1x Bitumen duct under lifting cover - beneath false floor. Manhole keys and heavy lifting tools required to access.					YES
11835	ACTIVE	N	N155-00-2/011	Ticket Office - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15926	ACTIVE	N	N155-00-2/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Clapham Common Stn	Void	Asbestos	Surveyed - Not Detected				Walls - Brick & Concrete above Fibreboard Ceiling				YES	
15925	ACTIVE	N	N155-00-2/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Clapham Common Stn	Void	Asbestos	Surveyed - Not Detected				Concrete and Concrete Ducts beneath Computer Tiles					YES
11836	ACTIVE	N	N155-00-2/021	POM - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15927	ACTIVE	N	N155-00-2/021/FLR-01	Floor - 1 - POM - Station Building - Clapham Common Stn	Void	Asbestos	Surveyed - Not Detected				Concrete beneath Computer Tiles					YES
11837	ACTIVE	N	N155-00-2/031	Mess Room - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18758	ACTIVE	N	N155-00-2/031	Mess Room - Station Building - Clapham Common Stn	LUL Heaters	Asbestos	Surveyed - Not Detected									
15929	ACTIVE	N	N155-00-2/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Clapham Common Stn	Void	Asbestos	Surveyed - Not Detected				Above False Ceiling - Concrete, Plaster; Fibreglass Lagging; Breeze Block Walls				YES	
15928	ACTIVE	N	N155-00-2/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Clapham Common Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
11838	ACTIVE	N	N155-00-2/036	Toilet: Unisex - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18759	ACTIVE	N	N155-00-2/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Clapham Common Stn	Void	Asbestos	Surveyed - Not Detected				Concrete; Metal Ducting; Fibreglass Lagging - above Supalux Tiles				YES	
18804	ACTIVE	N	N155-00-2/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Clapham Common Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
11839	ACTIVE	N	N155-00-2/071	Circulation Area - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15930	ACTIVE	N	N155-00-2/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Clapham Common Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	



# Hazardous Material Asset Register - Summary



## N155-00 - Station Building - Clapham Common Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11840	ACTIVE	N	N155-00-2/081	Lobby - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15932	ACTIVE	N	N155-00-2/081/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Clapham Common Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Fibreglass Lagging above Supalux Tiles				YES	
15931	ACTIVE	N	N155-00-2/081/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Clapham Common Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
11841	ACTIVE	N	N155-00-2/151	UMC - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42050	ACTIVE	N	N155-00-2/151	UMC - Station Building - Clapham Common Stn	Isolator Switches	Asbestos	Sampled – Not Detected				Rope (1m) to door of switch boxes x 2 NADIS		2		N	N
42051	ACTIVE	N	N155-00-2/151	UMC - Station Building - Clapham Common Stn	Other Boarding	Asbestos	Presumed				Siluminite component blocks within coil to 2KvA TX box x 2. Presumed insulating materials within.				N	N
18760	ACTIVE	N	N155-00-2/151	UMC - Station Building - Clapham Common Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux & Supalux Boarding					
42049	ACTIVE	N	N155-00-2/151	UMC - Station Building - Clapham Common Stn	Other Boarding	Asbestos	Presumed				Siluminite component blocks within 6-way boxes (all boxes)				N	N
42052	ACTIVE	N	N155-00-2/151	UMC - Station Building - Clapham Common Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer box. Presumed asbestos insulating inside.				N	N
15935	ACTIVE	N	N155-00-2/151	UMC - Station Building - Clapham Common Stn	Pipe Lagging	Asbestos	Surveyed – Not Detected				Lagging & Cover to Thermometer					
15933	ACTIVE	N	N155-00-2/151	UMC - Station Building - Clapham Common Stn	Lead/Leading	Lead Paint/Lead	Known				Red Oil Based Paint - 2no Girder to Housing Units. Thickness .13mm; Est Quantity 6 lm; Analysis 3.07%					
15934	ACTIVE	N	N155-00-2/151/FLR-01	Floor - 1 - UMC - Station Building - Clapham Common Stn	Durasteel	Asbestos	Surveyed – Not Detected				Lid to Storage Bin					
15936	ACTIVE	N	N155-00-2/171	Escalator Incline - Station Building - Clapham Common Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Adj Esc 3: Walls above hangers on incline - Supalux boxing					
11842	ACTIVE	N	N155-00-2/201	Passage - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18761	ACTIVE	N	N155-00-2/201	Passage - Station Building - Clapham Common Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11843	ACTIVE	N	N155-00-2/236	Passage - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19958	ACTIVE	N	N155-00-2/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Clapham Common Stn	Void	Asbestos	Surveyed – Not Detected				Concrete & Breeze Block above Fibreboard Ceiling				YES	



# Hazardous Material Asset Register - Summary



## N155-00 - Station Building - Clapham Common Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15937	ACTIVE	N	N155-00-2/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Clapham Common Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Fibreboard Ceiling					
18737	ACTIVE	N	N155-00-2/236/FLR-01	Floor - 1 - Passage - Station Building - Clapham Common Stn	Void	Asbestos	Surveyed - Not Detected				Concrete & Metal Trunking beneath Computer Tiles flooring					YES
11844	ACTIVE	N	N155-00-2/401	Switch Room - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19346	ACTIVE	N	N155-00-2/401	Switch Room - Station Building - Clapham Common Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11845	ACTIVE	N	N155-00-2/416	Mess Room - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18762	ACTIVE	N	N155-00-2/416/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Clapham Common Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Supalux Tiles					
15938	ACTIVE	N	N155-00-2/416/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Clapham Common Stn	Void	Asbestos	Surveyed - Not Detected				Concrete; Fibreglass Lagging above Supalux Tiles				YES	
11846	ACTIVE	N	N155-00-2/417	Toilet: Unisex - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15940	ACTIVE	N	N155-00-2/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Clapham Common Stn	Void	Asbestos	Surveyed - Not Detected				Concrete; Fibreglass Lagging above Supalux Tiles				YES	
15939	ACTIVE	N	N155-00-2/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Clapham Common Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Supalux Tiles					
11847	ACTIVE	N	N155-00-2/418	Cleaners Room - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15941	ACTIVE	N	N155-00-2/418/CLG-01	Ceiling: Suspended - 1 - Cleaners Room - Station Building - Clapham Common Stn	Void	Asbestos	Surveyed - Not Detected				Concrete; Fibreglass Lagging above Supalux Tiles				YES	
18763	ACTIVE	N	N155-00-2/418/CLG-01	Ceiling: Suspended - 1 - Cleaners Room - Station Building - Clapham Common Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Supalux Tiles					
11848	ACTIVE	N	N155-00-2/451	Tenancy - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15942	ACTIVE	N	N155-00-2/451	Tenancy - Station Building - Clapham Common Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Tenancy					



# Hazardous Material Asset Register - Summary



## N155-00 - Station Building - Clapham Common Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11849	ACTIVE	N	N155-00-2/661	Equipment Room - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15943	ACTIVE	N	N155-00-2/661	Equipment Room - Station Building - Clapham Common Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11850	ACTIVE	N	N155-00-2/662	Switch Room - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42055	ACTIVE	N	N155-00-2/662	Switch Room - Station Building - Clapham Common Stn	Other Boarding	Asbestos	Presumed				Siluminite component blocks within combination fuse switches CFS				N	N
42053	ACTIVE	N	N155-00-2/662	Switch Room - Station Building - Clapham Common Stn	Rope Seals	Asbestos	Sampled – Not Detected				Rope (1m) to door of switch box				N	N
42054	ACTIVE	N	N155-00-2/662	Switch Room - Station Building - Clapham Common Stn	Isolator Switches	Asbestos	Known				Some Flash guards may contain asbestos (cement) within Combination Fuse Switches. Please contact the HMU for further information		8		N	N
15944	ACTIVE	N	N155-00-2/662	Switch Room - Station Building - Clapham Common Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Supalux Panels					
11851	ACTIVE	N	N155-00-2/746	SCR - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15945	ACTIVE	N	N155-00-2/746	SCR - Station Building - Clapham Common Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11852	ACTIVE	N	N155-00-2/751	Station Control Room - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18764	ACTIVE	N	N155-00-2/751/CLG-01	Ceiling: Solid - 1 - Station Control Room - Station Building - Clapham Common Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, PVC Cables & Metal Pipes above Metal Ceiling				YES	
19347	ACTIVE	N	N155-00-2/751/FLR-01	Floor - 1 - Station Control Room - Station Building - Clapham Common Stn	Void	Asbestos	Surveyed – Not Detected				Concrete & Metal Trunking - beneath Computer Tiles					YES
11853	ACTIVE	N	N155-00-2/762	SVC - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15946	ACTIVE	N	N155-00-2/762	SVC - Station Building - Clapham Common Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11854	ACTIVE	N	N155-00-2/901	Disused Room - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18738	ACTIVE	N	N155-00-2/901	Disused Room - Station Building - Clapham Common Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Supalux Boarding; Concrete					



# Hazardous Material Asset Register - Summary



## N155-00 - Station Building - Clapham Common Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11855	ACTIVE	N	N155-00-3/081	Circulation Area - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15947	ACTIVE	N	N155-00-3/081	Circulation Area - Station Building - Clapham Common Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11856	ACTIVE	N	N155-00-3/161	LMC - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20271	ACTIVE	N	N155-00-3/161	LMC - Station Building - Clapham Common Stn		Asbestos	Sampled – Not Detected				Boarding (0.25m <sup>2</sup> ), high level, adjacent to Escalator no. 3					
20326	ACTIVE	N	N155-00-3/161	LMC - Station Building - Clapham Common Stn	Other Boarding	Asbestos	Sampled – Not Detected				Boarding (est. 0.25m <sup>2</sup> ), adjacent to Escalator no.3 at high level to concrete wall					
15948	ACTIVE	N	N155-00-3/161	LMC - Station Building - Clapham Common Stn	Cable Ducts: Bitumen	Asbestos	Surveyed – Not Detected				Bitumen Cable Sleeves					
15949	ACTIVE	N	N155-00-3/161	LMC - Station Building - Clapham Common Stn	Lead/Leading	Lead Paint/Lead	Known				Girder - Beige Oil Based Paint. Thickness .33mm; Est Quantity 10 lm; Analysis 21.87%					
18805	ACTIVE	N	N155-00-3/161	LMC - Station Building - Clapham Common Stn	Lead/Leading	Lead Paint/Lead	Known				Girder - Blue Oil Based Paint. Thickness .28mm; Est Quantity 4 lm; Analysis 3.47%					
11857	ACTIVE	N	N155-00-3/201	Passage - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18765	ACTIVE	N	N155-00-3/201	Passage - Station Building - Clapham Common Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11858	ACTIVE	N	N155-00-3/202	Passage - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15950	ACTIVE	N	N155-00-3/202/FLR-01	Floor - 1 - Passage - Station Building - Clapham Common Stn	Cable Ducts: Bitumen	Asbestos	Surveyed – Not Detected				Bitumen Cable Sleeves beneath Tiled False Floor					YES
15951	ACTIVE	N	N155-00-3/202/FLR-01	Floor - 1 - Passage - Station Building - Clapham Common Stn	Cable Ducts: Bitumen	Asbestos	Surveyed – Not Detected				Bitumen Cable Sleeves					YES
11859	ACTIVE	N	N155-00-3/237	Passage - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11860	ACTIVE	N	N155-00-3/238	Passage - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18766	ACTIVE	N	N155-00-3/238	Passage - Station Building - Clapham Common Stn	Cable Ducts: Bitumen	Asbestos	Surveyed – Not Detected				Bitumen Cable Sleeves					
11861	ACTIVE	N	N155-00-3/261	Platform 1 - Northbound Local - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N155-00 - Station Building - Clapham Common Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor	
18315	ACTIVE	N	N155-00-3/261	Platform 1 - Northbound Local - Station Building - Clapham Common Stn	Cable: Sheath	Asbestos	Strongly Presumed				20mm Cables - Encapsulated		3				
46325	ACTIVE	N	N155-00-3/261	Platform 1 - Northbound Local - Station Building - Clapham Common Stn		Asbestos	Presumed				Electrical boxes at the end of island platform near metal stair case, presumed to contain asbestos insulating materials within						
15953	ACTIVE	N	N155-00-3/261	Platform 1 - Northbound Local - Station Building - Clapham Common Stn	Cable: Sheath	Asbestos	Strongly Presumed				10mm Cables - Encapsulated		2				
46326	ACTIVE	N	N155-00-3/261	Platform 1 - Northbound Local - Station Building - Clapham Common Stn	Westing house Boxes	Asbestos	Presumed				Small Westinghouse box to wall within invert		1				
15952	ACTIVE	N	N155-00-3/261	Platform 1 - Northbound Local - Station Building - Clapham Common Stn	Cable Ducts: Bitumen	Asbestos	Surveyed – Not Detected				Bitumen Cable Sleeves						
18767	ACTIVE	N	N155-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Clapham Common Stn	Cement Troughing	Asbestos	Known				Invert under stairs 3/576. 24Lm Cable troughing - floor, under stairs running towards tail wall left hand side wall & head wall right hand side wall					YES	
15954	ACTIVE	N	N155-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Clapham Common Stn	Isolator Switches	Asbestos	Presumed				Invert Tail Wall - 1x Flash Guard left hand side wall Switch Box		1			YES	
15955	ACTIVE	N	N155-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Clapham Common Stn	Cable: Sheath	Asbestos	Presumed				Invert adjacent to markers 110. 4x Textile cable in wood box Encapsulated. This is the same as record 15962. Two entries to cover Platform 1&2					YES	
18806	ACTIVE	N	N155-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Clapham Common Stn	Cable Ducts: Cement	Asbestos	Known				4x Cable ducts - under stairs 3/576. This is the same as record 15961. Two entries to cover Platform 1&2					YES	
11862	ACTIVE	N	N155-00-3/262	Platform 2 - Southbound Local - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed										
15958	ACTIVE	N	N155-00-3/262	Platform 2 - Southbound Local - Station Building - Clapham Common Stn	Cable: Sheath	Asbestos	Strongly Presumed				10mm Cables - Encapsulated		2				
15957	ACTIVE	N	N155-00-3/262	Platform 2 - Southbound Local - Station Building - Clapham Common Stn	Cable: Sheath	Asbestos	Strongly Presumed				20mm Cables - Encapsulated		3				
15956	ACTIVE	N	N155-00-3/262	Platform 2 - Southbound Local - Station Building - Clapham Common Stn	Cable Ducts: Bitumen	Asbestos	Surveyed – Not Detected				Bitumen Cable Sleeves						
15961	ACTIVE	N	N155-00-3/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Clapham Common Stn	Cable Ducts: Cement	Asbestos	Known				4x Cable ducts - under stairs 3/576. This is the same as record 18806. Two entries to cover Platform 1&2					YES	
15960	ACTIVE	N	N155-00-3/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Clapham Common Stn	Isolator Switches	Asbestos	Presumed				Electrical boxes at end of island platform. Presumed asbestos insulating materials within.		1			YES	



# Hazardous Material Asset Register - Summary



## N155-00 - Station Building - Clapham Common Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15959	ACTIVE	N	N155-00-3/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Clapham Common Stn	Cement Troughing	Asbestos	Known				Invert under stairs 3/576. 24Lm Cable troughing - floor, under stairs running towards tail wall left hand side wall & head wall right hand side wall. (Island platform - reference is also under Platform 1 - 18767)					YES
15962	ACTIVE	N	N155-00-3/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Clapham Common Stn	Cable: Sheath	Asbestos	Presumed				Invert adjacent to markers 110. 4x Textile cable in wood box Encapsulated. This is the same as record 15955. Two entries to cover Platform 1&2					YES
11863	ACTIVE	N	N155-00-3/281	Switch Room - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11864	ACTIVE	N	N155-00-3/331	Locker Room - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18768	ACTIVE	N	N155-00-3/331/CLG-01	Ceiling: Solid - 1 - Locker Room - Station Building - Clapham Common Stn	Void	Asbestos	Surveyed – Not Detected				Above Plaster Ceiling				YES	
11865	ACTIVE	N	N155-00-3/406	Store - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11866	ACTIVE	N	N155-00-3/576	Stairs: Linear - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11867	ACTIVE	N	N155-00-3/601	Stairs: Linear - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11868	ACTIVE	N	N155-00-3/661	Disused Room - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15963	ACTIVE	N	N155-00-3/661/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Clapham Common Stn	Void	Asbestos	Surveyed – Not Detected				Above Tiles				YES	
11869	ACTIVE	N	N155-00-3/711	Relay Room - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
54036	ACTIVE	N	N155-00-3/711	Relay Room - Station Building - Clapham Common Stn	Other Boarding	Asbestos	Known				Paxoline boarding x1 - sampled R732251 confirmed asbestos Brown board on the rack on the floor			R732251		
18769	ACTIVE	N	N155-00-3/711	Relay Room - Station Building - Clapham Common Stn	Westing house Boxes	Asbestos	Strongly Presumed				Mesh Area External to. Insulation within 2 x Westinghouse Boxes		2			
44321	ACTIVE	N	N155-00-3/711	Relay Room - Station Building - Clapham Common Stn	Other Boarding	Asbestos	Known				Paxoline boarding x1 - sampled R732251 confirmed asbestos Brown Board to rack 1 on wall 3					



# Hazardous Material Asset Register - Summary



## N155-00 - Station Building - Clapham Common Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
54037	ACTIVE	N	N155-00-3/711	Relay Room - Station Building - Clapham Common Stn	Other Boarding	Asbestos	Known				Paxoline boarding x1 - sampled R732251 confirmed asbestos Brown board to wall 4 in front of main door			R732251		
54038	ACTIVE	N	N155-00-3/711	Relay Room - Station Building - Clapham Common Stn	Bitumen	Asbestos	Sampled – Not Detected				glue to walls			R732251		
54034	ACTIVE	N	N155-00-3/711	Relay Room - Station Building - Clapham Common Stn	Other Boarding	Asbestos	Known				Paxoline boarding x1 - sampled R732251 confirmed asbestos Brown board next to rack 7			R732251		
18316	ACTIVE	N	N155-00-3/711	Relay Room - Station Building - Clapham Common Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Mesh Area External to. Insulation within 3 x Tranformer Boxes		3			
44320	ACTIVE	N	N155-00-3/711	Relay Room - Station Building - Clapham Common Stn	Cable: Wrap	Asbestos	Presumed				Cable Wrap					
15966	ACTIVE	N	N155-00-3/711	Relay Room - Station Building - Clapham Common Stn	Cable: Sheath	Asbestos	Known				10mm Cables - Encapsulated		2			
15965	ACTIVE	N	N155-00-3/711	Relay Room - Station Building - Clapham Common Stn	Cable: Sheath	Asbestos	Known				20mm Cables - Encapsulated		3			
15964	ACTIVE	N	N155-00-3/711/ WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Clapham Common Stn	Vinyl tiles	Asbestos	Known				Green Vinyl Tiles - All Walls - Chrysotile - Some have been removed					
11870	ACTIVE	N	N155-00-3/731	CER - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15967	ACTIVE	N	N155-00-3/731/ FLR-01	Floor - 1 - CER - Station Building - Clapham Common Stn	Void	Asbestos	Surveyed – Not Detected				No Asbestos Visible					YES
11871	ACTIVE	N	N155-00-4/121	Platform Invert - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18807	ACTIVE	N	N155-00-4/121	Platform Invert - Station Building - Clapham Common Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11872	ACTIVE	N	N155-00-4/122	Platform Invert - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15968	ACTIVE	N	N155-00-4/122	Platform Invert - Station Building - Clapham Common Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11873	ACTIVE	N	N155-00-4/123	Platform Invert - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18739	ACTIVE	N	N155-00-4/123	Platform Invert - Station Building - Clapham Common Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11874	ACTIVE	N	N155-00-4/661	Switch Cupboard - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N155-00 - Station Building - Clapham Common Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15969	ACTIVE	N	N155-00-4/661	Switch Cupboard - Station Building - Clapham Common Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11875	ACTIVE	N	N155-00-4/662	Switch Room - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15970	ACTIVE	N	N155-00-4/662	Switch Room - Station Building - Clapham Common Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11876	ACTIVE	N	N155-00-4/663	Switch Room - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18770	ACTIVE	N	N155-00-4/663	Switch Room - Station Building - Clapham Common Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11877	ACTIVE	N	N155-00-4/664	Switch Cupboard - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15971	ACTIVE	N	N155-00-4/664	Switch Cupboard - Station Building - Clapham Common Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11878	ACTIVE	N	N155-00-4/771	Plant Room - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15972	ACTIVE	N	N155-00-4/771	Plant Room - Station Building - Clapham Common Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11879	ACTIVE	N	N155-00-4/781	Transformer Room - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18808	ACTIVE	N	N155-00-4/781	Transformer Room - Station Building - Clapham Common Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
11880	ACTIVE	N	N155-00-4/782	Transformer Room - Station Building - Clapham Common Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15973	ACTIVE	N	N155-00-4/782	Transformer Room - Station Building - Clapham Common Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					

## N163-00 - Station Building - Clapham South Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11881	ACTIVE	N	N163-00-1/001	Booking Hall - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15861	ACTIVE	N	N163-00-1/001	Booking Hall - Station Building - Clapham South Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N163-00 - Station Building - Clapham South Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11882	ACTIVE	N	N163-00-1/011	Ticket Office - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15862	ACTIVE	N	N163-00-1/011/CLG-01	Ceiling: Solid - 1 - Ticket Office - Station Building - Clapham South Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Ceiling					
15863	ACTIVE	N	N163-00-1/011/CLG-01	Ceiling: Solid - 1 - Ticket Office - Station Building - Clapham South Stn	Void	Asbestos	Surveyed – Not Detected				Wood, Fibreglass Lagging above Supalux ceiling				YES	
18676	ACTIVE	N	N163-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Clapham South Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden false floor					YES
11883	ACTIVE	N	N163-00-1/021	POM - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15864	ACTIVE	N	N163-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Clapham South Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden false floor					YES
11884	ACTIVE	N	N163-00-1/031	Mess Room - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15865	ACTIVE	N	N163-00-1/031	Mess Room - Station Building - Clapham South Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater Insulation Board Foam					
18677	ACTIVE	N	N163-00-1/031/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Clapham South Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles Ceiling					
15866	ACTIVE	N	N163-00-1/031/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Clapham South Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles				YES	
11885	ACTIVE	N	N163-00-1/036	Lobby - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15867	ACTIVE	N	N163-00-1/036	Lobby - Station Building - Clapham South Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11886	ACTIVE	N	N163-00-1/037	Toilet: Unisex - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15868	ACTIVE	N	N163-00-1/037	Toilet: Unisex - Station Building - Clapham South Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding					
11887	ACTIVE	N	N163-00-1/071	Circulation Area - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15869	ACTIVE	N	N163-00-1/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Clapham South Stn	Glazing Rope	Asbestos	Strongly Presumed				Rope Seal on Glass Ceiling x2 to ceiling Re-inspected 03-03-2023					



# Hazardous Material Asset Register - Summary



## N163-00 - Station Building - Clapham South Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11888	ACTIVE	N	N163-00-1/151	UMC - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18249	ACTIVE	N	N163-00-1/151	UMC - Station Building - Clapham South Stn	Gasket :Pipework	Asbestos	Presumed				Gaskets to Fan Equipment - None Visible - P No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within.					
15761	ACTIVE	N	N163-00-1/151	UMC - Station Building - Clapham South Stn	Durasteel	Asbestos	Presumed				Durasteel Panel above door to 2/733 Re-inspected 03-03-2023					
15764	ACTIVE	N	N163-00-1/151	UMC - Station Building - Clapham South Stn	Lead/Leading	Lead Paint/Lead	Known				Red Oil Based Paint - 2no Girder to Housing Unit. Thickness .41mm; Est Quantity 4lm; Analysis 12.52%					
15763	ACTIVE	N	N163-00-1/151	UMC - Station Building - Clapham South Stn	Lead/Leading	Lead Paint/Lead	Known				Yellow Oil Based Paint - Stairs. Thickness .38mm; Est Quantity 4sqm; Analysis 1.68%					
18516	ACTIVE	N	N163-00-1/151	UMC - Station Building - Clapham South Stn	Lead/Leading	Lead Paint/Lead	Known				Grey Oil Based Paint - Girder. Thickness .21mm; Est Quantity 5lm; Analysis 1.29% Overpainted with yellow up to head high					
15762	ACTIVE	N	N163-00-1/151	UMC - Station Building - Clapham South Stn	Lead/Leading	Lead Paint/Lead	Known				Red Oil Based Paint - Pipework. Thickness .11mm; Est Quantity 60lm; Analysis 4.04%					
18667	ACTIVE	N	N163-00-1/151/CLG-01	Ceiling: Solid - 1 - UMC - Station Building - Clapham South Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Concrete, Supalux					
18678	ACTIVE	N	N163-00-1/151/FLR-01	Floor - 1 - UMC - Station Building - Clapham South Stn	Durasteel	Asbestos	Surveyed – Not Detected				Lid to Storage Bin					
15759	ACTIVE	N	N163-00-1/151/WAL-001	Wall: Internal - 1 - UMC - Station Building - Clapham South Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es) No electrician present during 2023 reinspection to open electrical equipment.		1			
15758	ACTIVE	N	N163-00-1/151/WAL-002	Wall: Internal - 2 - UMC - Station Building - Clapham South Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x 60amp, 1 x 30amp & 1 x 100amp Switch Boxes - Insulation within No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within.		4			
15760	INACTIVE	N	N163-00-1/151/WAL-003 80891831	Wall: Internal - 3 - UMC - Station Building - Clapham South Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es) in twice 10/3/2016 with 15759		1			
15765	ACTIVE	N	N163-00-1/171	Escalator Incline - Station Building - Clapham South Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
11889	ACTIVE	N	N163-00-1/236	Passage - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15766	ACTIVE	N	N163-00-1/236/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Clapham South Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	



# Hazardous Material Asset Register - Summary



## N163-00 - Station Building - Clapham South Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18728	ACTIVE	N	N163-00-1/236/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Clapham South Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
11890	ACTIVE	N	N163-00-1/237	Lobby - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18517	ACTIVE	N	N163-00-1/237	Lobby - Station Building - Clapham South Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11891	ACTIVE	N	N163-00-1/238	Lobby - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15768	ACTIVE	N	N163-00-1/238/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Clapham South Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	
15767	ACTIVE	N	N163-00-1/238/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Clapham South Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
11892	ACTIVE	N	N163-00-1/239	Lobby - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18518	ACTIVE	N	N163-00-1/239/FLR-01	Floor - 1 - Lobby - Station Building - Clapham South Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden false floor					YES
11893	ACTIVE	N	N163-00-1/301	Locker Room - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15769	ACTIVE	N	N163-00-1/301	Locker Room - Station Building - Clapham South Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding					
11894	ACTIVE	N	N163-00-1/331	Mess Room - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15770	ACTIVE	N	N163-00-1/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Clapham South Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
15771	ACTIVE	N	N163-00-1/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Clapham South Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	
11895	ACTIVE	N	N163-00-1/416	Toilet: Female - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18584	ACTIVE	N	N163-00-1/416/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Clapham South Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	



# Hazardous Material Asset Register - Summary



## N163-00 - Station Building - Clapham South Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15772	ACTIVE	N	N163-00-1/416/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Clapham South Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
11896	ACTIVE	N	N163-00-1/417	Toilet: Male - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15773	ACTIVE	N	N163-00-1/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Clapham South Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
15774	ACTIVE	N	N163-00-1/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Clapham South Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	
11897	ACTIVE	N	N163-00-1/451	Tenancy - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15775	ACTIVE	N	N163-00-1/451/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Clapham South Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles				YES	
19954	ACTIVE	N	N163-00-1/451/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Clapham South Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
11898	ACTIVE	N	N163-00-1/452	Tenancy - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15776	ACTIVE	N	N163-00-1/452	Tenancy - Station Building - Clapham South Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11899	ACTIVE	N	N163-00-1/453	Tenancy - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18585	ACTIVE	N	N163-00-1/453	Tenancy - Station Building - Clapham South Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11900	ACTIVE	N	N163-00-1/661	Switch Room - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15778	ACTIVE	N	N163-00-1/661/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Clapham South Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18586	ACTIVE	N	N163-00-1/661/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Clapham South Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles				YES	
15777	ACTIVE	N	N163-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Clapham South Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes 4 x Grey 60amp & 3 x Blue 100amp & 2 x 60amp - Insulation within No electrician present during 2023 reinspection to open.		9			



# Hazardous Material Asset Register - Summary



## N163-00 - Station Building - Clapham South Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15779	ACTIVE	N	N163-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Clapham South Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Transformer Box(es) No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
11901	ACTIVE	N	N163-00-1/662	Switch Room - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15780	ACTIVE	N	N163-00-1/662/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Clapham South Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles				YES	
18587	ACTIVE	N	N163-00-1/662/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Clapham South Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
15781	ACTIVE	N	N163-00-1/662/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Clapham South Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Transformer Box(es) No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
19950	ACTIVE	N	N163-00-1/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Clapham South Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes 4 x Grey 60amp & 3 x Blue 100amp & 2 x 60amp - Insulation within No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within.		9			
19481	ACTIVE	N	N163-00-1/662/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Clapham South Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Transformer Box(es), 1x combination fuse switch to wall 4 - photo DSC05499 No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within.		3			
11902	ACTIVE	N	N163-00-1/746	SCR - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18730	ACTIVE	N	N163-00-1/746	SCR - Station Building - Clapham South Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11903	ACTIVE	N	N163-00-1/751	Station Control Room - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18588	ACTIVE	N	N163-00-1/751/CLG-01	Ceiling: Solid - 1 - Station Control Room - Station Building - Clapham South Stn	Void	Asbestos	No Access: Presumed				Above Metal Strip; Supalux Boarding				YES	
15782	ACTIVE	N	N163-00-1/751/FLR-01	Floor - 1 - Station Control Room - Station Building - Clapham South Stn	Void	Asbestos	No Access: Presumed				Beneath false Wooden Floor					YES



# Hazardous Material Asset Register - Summary



## N163-00 - Station Building - Clapham South Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11904	ACTIVE	N	N163-00-1/761	SVC - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15783	ACTIVE	N	N163-00-1/761	SVC - Station Building - Clapham South Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11905	ACTIVE	N	N163-00-1/776	Plant Room - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15784	ACTIVE	N	N163-00-1/776/FLR-01	Floor - 1 - Plant Room - Station Building - Clapham South Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden Floor					YES
11906	ACTIVE	N	N163-00-1/901	Yard - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15785	ACTIVE	N	N163-00-1/901	Yard - Station Building - Clapham South Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11907	ACTIVE	N	N163-00-1/951	Void - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15786	ACTIVE	N	N163-00-1/951	Void - Station Building - Clapham South Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
11908	ACTIVE	N	N163-00-1/952	Bin Store - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15787	ACTIVE	N	N163-00-1/952	Bin Store - Station Building - Clapham South Stn	Gasket :Pipework	Asbestos	Presumed				Gaskets to Pipework					
18589	ACTIVE	N	N163-00-1/952	Bin Store - Station Building - Clapham South Stn	Lead/Leading	Lead Paint/Lead	Known				Red Oil Based Paint - Stand. Thickness .05mm; Est Quantity 1 lm; Analysis 2.72%					
11909	ACTIVE	N	N163-00-2/081	Circulation Area - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15788	ACTIVE	N	N163-00-2/081	Circulation Area - Station Building - Clapham South Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11910	ACTIVE	N	N163-00-2/161	LMC - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15789	ACTIVE	N	N163-00-2/161	LMC - Station Building - Clapham South Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11911	ACTIVE	N	N163-00-2/201	Passage - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15790	ACTIVE	N	N163-00-2/201	Passage - Station Building - Clapham South Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N163-00 - Station Building - Clapham South Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11912	ACTIVE	N	N163-00-2/202	Passage - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15791	ACTIVE	N	N163-00-2/202	Passage - Station Building - Clapham South Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11913	ACTIVE	N	N163-00-2/203	Passage - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18590	ACTIVE	N	N163-00-2/203	Passage - Station Building - Clapham South Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11914	ACTIVE	N	N163-00-2/204	Passage - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15792	ACTIVE	N	N163-00-2/204	Passage - Station Building - Clapham South Stn		Asbestos	Surveyed - Not Detected									
11915	ACTIVE	N	N163-00-2/261	Platform 1 - Northbound Local - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15793	ACTIVE	N	N163-00-2/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Clapham South Stn	Cable: Sheath	Asbestos	No Access: Presumed				Braided Cable 100m long					YES
18729	ACTIVE	N	N163-00-2/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Clapham South Stn	Debris: Cement	Asbestos	Strongly Presumed				Platform 1 Invert - Asbestos Cement Debris					YES
11916	ACTIVE	N	N163-00-2/262	Platform 2 - Southbound Local - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18731	ACTIVE	N	N163-00-2/262	Platform 2 - Southbound Local - Station Building - Clapham South Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Panels inside Fire Point					
18591	ACTIVE	N	N163-00-2/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Clapham South Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - Braided Cable 10m long					YES
11917	ACTIVE	N	N163-00-2/406	Switch Room - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15794	ACTIVE	N	N163-00-2/406	Switch Room - Station Building - Clapham South Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11918	ACTIVE	N	N163-00-2/661	Switch Room - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15795	ACTIVE	N	N163-00-2/661	Switch Room - Station Building - Clapham South Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11919	ACTIVE	N	N163-00-2/663	Switch Room - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N163-00 - Station Building - Clapham South Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15797	ACTIVE	N	N163-00-2/663/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Clapham South Stn	Void	Asbestos	No Access: Presumed				Above Supalux Ceiling				YES	
15796	ACTIVE	N	N163-00-2/663/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Clapham South Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
11920	ACTIVE	N	N163-00-2/664	Switch Room - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15798	ACTIVE	N	N163-00-2/664	Switch Room - Station Building - Clapham South Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard Panel above Entrance					
11921	ACTIVE	N	N163-00-2/665	Switch Room - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18592	ACTIVE	N	N163-00-2/665	Switch Room - Station Building - Clapham South Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard Panel above Entrance					
11922	ACTIVE	N	N163-00-2/666	Switch Cupboard - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15799	ACTIVE	N	N163-00-2/666	Switch Cupboard - Station Building - Clapham South Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11923	ACTIVE	N	N163-00-2/667	Switch Cupboard - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15800	ACTIVE	N	N163-00-2/667	Switch Cupboard - Station Building - Clapham South Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11924	ACTIVE	N	N163-00-2/711	Relay Room - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18594	ACTIVE	N	N163-00-2/711	Relay Room - Station Building - Clapham South Stn	Cable: Sheath	Asbestos	Strongly Presumed				10mm / 20mm Cables on lower cable run, to wall 1. 1x cable running to invert (wall 2) and 2x cables running to track (wall 3) Re-inspected 03-03-2023		2			
53549	ACTIVE	N	N163-00-2/711	Relay Room - Station Building - Clapham South Stn	Other Boarding	Asbestos	Surveyed – Not Detected				brown board to new rely on top of dot matrix - NEW - wall 3					
15801	ACTIVE	N	N163-00-2/711	Relay Room - Station Building - Clapham South Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux board, 2no x 0.1m2, to firestop on top of duct to floor by walls 2 and 3 in IMR 2/711. Note no access to duct due to live cables and Supalux firestop on top					
15804	ACTIVE	N	N163-00-2/711/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - Clapham South Stn	Vinyl tiles	Asbestos	Known				Vinyl Tiles. Most tiles removed , still in place behind racking and equipment Re-inspected 03-03-2023					



# Hazardous Material Asset Register - Summary



## N163-00 - Station Building - Clapham South Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18595	ACTIVE	N	N163-00-2/711/FLR-01	Floor - 1 - Relay Room - Station Building - Clapham South Stn	Boarding: Cement	Asbestos	Sampled – Not Detected				Floor (right hand side) damaged Cement Board over Ducts  board is supalux ref report : R616801					
15808	ACTIVE	N	N163-00-2/711/FLR-01	Floor - 1 - Relay Room - Station Building - Clapham South Stn	Cable Ducts: Cement	Asbestos	Surveyed – Not Detected				Ducts (porcelain VC) non asbestos - with supalux panel to front					
18593	ACTIVE	N	N163-00-2/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Clapham South Stn	Vinyl tiles	Asbestos	Known				Vinyl Tiles.  most tiles removed still in place behind racks and equipment Re-inspected 03-03-2023					
19482	INACTIVE	N	N163-00-2/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Clapham South Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse Box In twice see 15807		1			
44318	ACTIVE	N	N163-00-2/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Clapham South Stn	Other Boarding	Asbestos	Presumed				brown composite boarding to rack equipment top shelf wall 1 x5 Re-inspected 03-03-2023					
15807	ACTIVE	N	N163-00-2/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Clapham South Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Westinghouse box to wall 1  No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
44903	INACTIVE	N	N163-00-2/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Clapham South Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box		1		N	N
15809	ACTIVE	N	N163-00-2/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Clapham South Stn	Boarding: Cement	Asbestos	Presumed				Cement panel under equipment to top shelf of rack on wall 1 Re-inspected 03-03-2023					
53547	ACTIVE	N	N163-00-2/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Clapham South Stn	Other Boarding	Asbestos	Presumed				composite boarding x6 to equipment bottom shelf of rack wall 1 Re-inspection 03-03-2023					
15810	INACTIVE	N	N163-00-2/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Clapham South Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				5 x PCB's - Fair Condition Serial Nos. 197459; 197469; 197474; 197454; 197493 Re inspected 14/04/2015 Fair Condition		5			
53548	ACTIVE	N	N163-00-2/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Clapham South Stn	Other Boarding	Asbestos	Presumed				Brown composite board to box wall 2 Re-inspection 03-03-2023					
15802	ACTIVE	N	N163-00-2/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Clapham South Stn	Vinyl tiles	Asbestos	Known				Vinyl Tiles.  most tiles removed still in place behind racks and equipment Re-inspected 03-03-2023					
15805	ACTIVE	N	N163-00-2/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Clapham South Stn	Cable: Sheath	Asbestos	Strongly Presumed				20mm Cable going to the Invert - Moderate Damage Re-inspected 03-03-2023		1			



# Hazardous Material Asset Register - Summary



## N163-00 - Station Building - Clapham South Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15806	ACTIVE	N	N163-00-2/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Clapham South Stn	Cable: Sheath	Asbestos	Strongly Presumed				5mm Cable thin cable going from equipment box wall 2 and down wall behind pipes Re-inspected 03-03-2023		1			
15803	ACTIVE	N	N163-00-2/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Clapham South Stn	Vinyl tiles	Asbestos	Known				Vinyl Tiles. most tiles removed still in place behind racks and equipment Re-inspected 03-03-2023					
18793	ACTIVE	N	N163-00-2/711/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Clapham South Stn	Vinyl tiles	Asbestos	Known				Vinyl Tiles. most tiles removed still in place behind racks and equipment Re-inspected 03-03-2023					
11925	ACTIVE	N	N163-00-2/712	Relay Room - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44603	ACTIVE	N	N163-00-2/712	Relay Room - Station Building - Clapham South Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux board, 1no x 0.1m2, to firestop on top of duct to floor by wall 2 in IMR 2/712. Note, no access to duct as covered under supalux and live cables			R616801		
15815	ACTIVE	N	N163-00-2/712/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - Clapham South Stn	Vinyl tiles	Asbestos	Strongly Presumed				Vinyl Tiles most tiles to wall and ceiling removed some still in place behind racks and equipment Re-inspected 03-03-2023					
18598	ACTIVE	N	N163-00-2/712/FLR-01	Floor - 1 - Relay Room - Station Building - Clapham South Stn	Boarding: Cement	Asbestos	Surveyed – Not Detected				Floor RHS ducts porcelain non asbestos (VC site visit) panel is supalux					
18795	ACTIVE	N	N163-00-2/712/FLR-01	Floor - 1 - Relay Room - Station Building - Clapham South Stn	Cable Ducts: Cement	Asbestos	Surveyed – Not Detected				Ducts under Panel - supalux boarding to front - duct porcelain VC site visit					
15820	ACTIVE	N	N163-00-2/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Clapham South Stn	Boarding: Cement	Asbestos	Removed				Panel under PCB's Not identified during re-inspection 2023		2			
53550	ACTIVE	N	N163-00-2/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Clapham South Stn	Boarding: Cement	Asbestos	Presumed				cement panel - to top shelf of racking on wall 1 Re-inspected 03-03-2023					
15811	ACTIVE	N	N163-00-2/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Clapham South Stn	Vinyl tiles	Asbestos	Strongly Presumed				All Walls Vinyl Tiles Some removal along W1 Re-inspected 03-03-2023 most tiles removed some still in place behind racks and equipment					
15821	INACTIVE	N	N163-00-2/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Clapham South Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				PCB's - Fair Condition Serial Nos. 197491; 197480; 197475; 38131; 197470; 197483 Re inspected 14/04/2015		6			



# Hazardous Material Asset Register - Summary



## N163-00 - Station Building - Clapham South Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18794	ACTIVE	N	N163-00-2/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Clapham South Stn	Vinyl tiles	Asbestos	Strongly Presumed				All Walls Vinyl Tiles most tiles removed some still in place behind racks and equipment Re-inspected 03-03-2023					
15816	ACTIVE	N	N163-00-2/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Clapham South Stn	Cable: Sheath	Asbestos	Strongly Presumed				10mm Cables in cable run going to the Track from wall 3 to wall 5 Re-inspected 03-03-2023		1			
15818	ACTIVE	N	N163-00-2/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Clapham South Stn	Cable: Sheath	Asbestos	Strongly Presumed				5mm thin Cable entering electrical box wall4, running down wall behind pipework Re-inspected 03-03-2023		2			
44904	ACTIVE	N	N163-00-2/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Clapham South Stn	Other Electrical Boxes	Asbestos	Surveyed – Not Detected				Transformer Box - LTE box new (survey AW VC)		1		N	N
18250	ACTIVE	N	N163-00-2/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Clapham South Stn	Other Electrical Boxes	Asbestos	Presumed				Westinghouse Box No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
15817	ACTIVE	N	N163-00-2/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Clapham South Stn	Cable: Sheath	Asbestos	Strongly Presumed				20mm Cables in cable run from wall 3 going to track wall 5 Re-inspected 03-03-2023		1			
18597	ACTIVE	N	N163-00-2/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Clapham South Stn	Cable: Sheath	Asbestos	Strongly Presumed				20mm Cables going to the Track Re-inspected 03-03-2023		1			
15819	INACTIVE	N	N163-00-2/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Clapham South Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse Box In Twice see 18250		1			
53552	ACTIVE	N	N163-00-2/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Clapham South Stn	Other Boarding	Asbestos	Presumed				Brown composite panels x6 to rack at bottom on wall 3 Re-inspected 03-03-2023					
18596	ACTIVE	N	N163-00-2/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Clapham South Stn	Vinyl tiles	Asbestos	Strongly Presumed				All Walls Vinyl Tiles Some tiles removed Re-inspected 03-03-2023					
53551	ACTIVE	N	N163-00-2/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Clapham South Stn	Other Boarding	Asbestos	Presumed				brown composite panels x6 top shelf to rack to wall 3 Re-inspected 03-03-2023					
15812	ACTIVE	N	N163-00-2/712/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Clapham South Stn	Vinyl tiles	Asbestos	Strongly Presumed				All Walls Vinyl Tiles most tiles removed some still in place behind racks and equipment Re-inspected 03-03-2023					
44319	ACTIVE	N	N163-00-2/712/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Clapham South Stn	Other Boarding	Asbestos	Presumed				brown composite boarding to box on wall 4 Re-inspected 03-03-2023					



# Hazardous Material Asset Register - Summary



## N163-00 - Station Building - Clapham South Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15813	ACTIVE	N	N163-00-2/712/WAL-005	Wall: Internal - 5 - Relay Room - Station Building - Clapham South Stn	Vinyl tiles	Asbestos	Strongly Presumed				All Walls Vinyl Tiles Some removal along W5  most tiles removed some still in place behind racks and equipment  Re-inspected 03-03-2023					
15814	ACTIVE	N	N163-00-2/712/WAL-006	Wall: Internal - 6 - Relay Room - Station Building - Clapham South Stn	Vinyl tiles	Asbestos	Strongly Presumed				All Walls Vinyl Tiles Some removal along W6 Most tiles removed some still in place behind racks and equipment Re-inspected 03-03-2023					
11926	ACTIVE	N	N163-00-2/731	Passage - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15822	ACTIVE	N	N163-00-2/731/WAL-004	Wall: Internal - 4 - Passage - Station Building - Clapham South Stn	Isolator Switches	Asbestos	Removed				30amp Switch Boxes - Insulation within  Not present during re-inspection 2023		2			
11927	ACTIVE	N	N163-00-2/732	Lobby - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15915	ACTIVE	N	N163-00-2/732/FLR-01	Floor - 1 - Lobby - Station Building - Clapham South Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					YES
11928	ACTIVE	N	N163-00-2/733	CER - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18736	ACTIVE	N	N163-00-2/733/FLR-01	Floor - 1 - CER - Station Building - Clapham South Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					
15916	ACTIVE	N	N163-00-2/733/WAL-002	Wall: Internal - 2 - CER - Station Building - Clapham South Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes 60amp - Insulation within  No electrician on site during 2023 re-inspection to open boxes for inspection - therefore cannot score material within.		2			
11929	ACTIVE	N	N163-00-2/761	Store - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
11930	ACTIVE	N	N163-00-2/781	TXR - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15917	ACTIVE	N	N163-00-2/781	TXR - Station Building - Clapham South Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
11931	ACTIVE	N	N163-00-2/951	Disused Room - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18756	ACTIVE	N	N163-00-2/951/FLR-01	Floor - 1 - Disused Room - Station Building - Clapham South Stn	Other Boarding	Asbestos	No Access: Presumed				No Access beneath Non Asbestos Boarding					



# Hazardous Material Asset Register - Summary



## N163-00 - Station Building - Clapham South Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11932	ACTIVE	N	N163-00-2/952	SER - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15918	ACTIVE	N	N163-00-2/952	SER - Station Building - Clapham South Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11933	ACTIVE	N	N163-00-3/161	LMC - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
11934	ACTIVE	N	N163-00-A/761	Equipment Room - Station Building - Clapham South Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15919	ACTIVE	N	N163-00-A/761	Equipment Room - Station Building - Clapham South Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					

## N165-00 - Station Building - Balham Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11935	ACTIVE	N	N165-00-1/081	Lobby - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15872	ACTIVE	N	N165-00-1/081	Lobby - Station Building - Balham Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
11936	ACTIVE	N	N165-00-1/181	Station Entrance - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15873	ACTIVE	N	N165-00-1/181	Station Entrance - Station Building - Balham Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11937	ACTIVE	N	N165-00-1/203	Passage - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15874	ACTIVE	N	N165-00-1/203	Passage - Station Building - Balham Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11938	ACTIVE	N	N165-00-1/401	Store - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15878	ACTIVE	N	N165-00-1/401/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Balham Stn	Void	Asbestos	Surveyed - Not Detected				Above False Ceiling - Plasterboard on Metal Ceiling, Ceiling, Durasteel same in room, Plasterboard, Rock Wool,				YES	
15877	ACTIVE	N	N165-00-1/401/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Balham Stn	Durasteel	Asbestos	Surveyed - Not Detected				Durasteel Diamond Holes - No asbestos detected					
15875	ACTIVE	N	N165-00-1/401/WAL-001	Wall: Internal - 1 - Store - Station Building - Balham Stn	Durasteel	Asbestos	Surveyed - Not Detected				Durasteel Diamond Holes - No asbestos detected					



# Hazardous Material Asset Register - Summary



## N165-00 - Station Building - Balham Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18680	ACTIVE	N	N165-00-1/401/WAL-002	Wall: Internal - 2 - Store - Station Building - Balham Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel Diamond Holes - No asbestos detected					
15876	ACTIVE	N	N165-00-1/401/WAL-004	Wall: Internal - 4 - Store - Station Building - Balham Stn	Durasteel	Asbestos	Surveyed – Not Detected				Durasteel Diamond Holes - No asbestos detected					
11939	ACTIVE	N	N165-00-1/402	Bin Store - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15879	ACTIVE	N	N165-00-1/402/CLG-01	Ceiling: Suspended - 1 - Bin Store - Station Building - Balham Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18799	ACTIVE	N	N165-00-1/402/CLG-01	Ceiling: Suspended - 1 - Bin Store - Station Building - Balham Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard above Supalux Tiles				YES	
11940	ACTIVE	N	N165-00-1/406	SVC - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18681	ACTIVE	N	N165-00-1/406	SVC - Station Building - Balham Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11941	ACTIVE	N	N165-00-1/451	Store - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15880	ACTIVE	N	N165-00-1/451/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Balham Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
15881	ACTIVE	N	N165-00-1/451/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Balham Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	
11942	ACTIVE	N	N165-00-1/452	Store - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15882	ACTIVE	N	N165-00-1/452/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Balham Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18682	ACTIVE	N	N165-00-1/452/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Balham Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				YES	
11943	ACTIVE	N	N165-00-1/453	SER - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15883	ACTIVE	N	N165-00-1/453/FLR-01	Floor - 1 - SER - Station Building - Balham Stn	Void	Asbestos	No Access: Presumed				Limited access beneath concrete/ metal false floor					
11944	ACTIVE	N	N165-00-1/454	Tenancy - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15884	ACTIVE	N	N165-00-1/454/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Balham Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Fibreboard Ceiling				YES	



# Hazardous Material Asset Register - Summary



## N165-00 - Station Building - Balham Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11945	ACTIVE	N	N165-00-1/455	Tenancy - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15885	ACTIVE	N	N165-00-1/455/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Balham Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Fibreboard Ceiling				YES	
11946	ACTIVE	N	N165-00-1/601	Stairs: Linear - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18313	ACTIVE	N	N165-00-1/601/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Balham Stn	Void	Asbestos	Surveyed - Not Detected				Concrete and Corrugated Metal above false ceiling - Metal Panels				YES	
11947	ACTIVE	N	N165-00-1/602	Stairs: Linear - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15886	ACTIVE	N	N165-00-1/602	Stairs: Linear - Station Building - Balham Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11948	ACTIVE	N	N165-00-1/603	Stairs: Linear - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18734	ACTIVE	N	N165-00-1/603	Stairs: Linear - Station Building - Balham Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11949	ACTIVE	N	N165-00-1/604	Stairs: Linear - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18683	ACTIVE	N	N165-00-1/604/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Balham Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Metal Strip False Ceiling				YES	
11950	ACTIVE	N	N165-00-1/761	Switch Room - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15887	ACTIVE	N	N165-00-1/761/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Balham Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected									
18800	ACTIVE	N	N165-00-1/761/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Balham Stn	Isolator Switches	Asbestos	Strongly Presumed				100amp Switch Box - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
15889	ACTIVE	N	N165-00-1/791	Vent Shaft - Station Building - Balham Stn	Lead/Leading	Lead Paint/Lead	Known				Black Oil Based Paint - Pipework Thickness .51mm; Est Quantity 8 lm; Analysis 18.02%					
15888	ACTIVE	N	N165-00-1/791/FLR-01	Floor - 1 - Vent Shaft - Station Building - Balham Stn	Lagging	Asbestos	Surveyed - Not Detected				On Floor					
15754	ACTIVE	N	N165-00-1/791/FLR-01	Floor - 1 - Vent Shaft - Station Building - Balham Stn	Lagging	Asbestos	Surveyed - Not Detected				On Floor					



# Hazardous Material Asset Register - Summary



## N165-00 - Station Building - Balham Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11951	ACTIVE	N	N165-00-1/952	Disused Room - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18684	ACTIVE	N	N165-00-1/952/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Balham Stn	Void	Asbestos	No Access: Presumed				Above Wood Slates Damage to Ceiling would occur if to access above Supalux				YES	
15890	ACTIVE	N	N165-00-1/952/FLR-01	Floor - 1 - Disused Room - Station Building - Balham Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden False Floor					YES
11952	ACTIVE	N	N165-00-2/001	Booking Hall - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15891	ACTIVE	N	N165-00-2/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Balham Stn	Void	Asbestos	Surveyed – Not Detected				Metal above Metal Strip - False Ceiling				YES	
11953	ACTIVE	N	N165-00-2/011	Ticket Office - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15734	ACTIVE	N	N165-00-2/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Balham Stn	Void	Asbestos	Surveyed – Not Detected				Metal Corrugated Ceiling, PVC Cables and Metal Trunking above Fibreboard Ceiling				YES	
15892	ACTIVE	N	N165-00-2/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Balham Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath Computer Tiles					YES
11954	ACTIVE	N	N165-00-2/021	POM - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15736	ACTIVE	N	N165-00-2/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Balham Stn	Void	Asbestos	Surveyed – Not Detected				Metal Corrugated Ceiling, PVC Cables and Metal Trunking above Fibreboard Ceiling				YES	
15735	ACTIVE	N	N165-00-2/021/FLR-01	Floor - 1 - POM - Station Building - Balham Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath Computer Tiles					YES
11955	ACTIVE	N	N165-00-2/031	Mess Room - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46576	ACTIVE	N	N165-00-2/031	Mess Room - Station Building - Balham Stn		Lead Paint/Lead	Known				Mess Room & Cupboard. Yellow gloss paint on RSJ & metal ceiling (18.9%)		19			
15737	ACTIVE	N	N165-00-2/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Balham Stn	Void	Asbestos	Surveyed – Not Detected				Metal above Supalux Tiles				YES	
18511	ACTIVE	N	N165-00-2/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Balham Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
11956	ACTIVE	N	N165-00-2/036	Lobby - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N165-00 - Station Building - Balham Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15738	ACTIVE	N	N165-00-2/036/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Balham Stn	Void	Asbestos	Surveyed – Not Detected				Metal; Fibreglass Lagging above Supalux Tiles				YES	
18665	ACTIVE	N	N165-00-2/036/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Balham Stn	Void	Asbestos	Surveyed – Not Detected				Supalux Tiles				YES	
11957	ACTIVE	N	N165-00-2/037	Toilet: Unisex - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15741	ACTIVE	N	N165-00-2/037	Toilet: Unisex - Station Building - Balham Stn		Asbestos	Surveyed – Not Detected				Toilet Cistern - Bakelite				YES	
15739	ACTIVE	N	N165-00-2/037/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Balham Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
15740	ACTIVE	N	N165-00-2/037/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Balham Stn	Void	Asbestos	Surveyed – Not Detected				Metal above Supalux Tiles				YES	
11958	ACTIVE	N	N165-00-2/071	Circulation Area - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18512	ACTIVE	N	N165-00-2/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Balham Stn	Void	Asbestos	Surveyed – Not Detected				Metal above Metal Strip false ceiling				YES	
11959	ACTIVE	N	N165-00-2/151	UMC - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15743	ACTIVE	N	N165-00-2/151	UMC - Station Building - Balham Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Board above door to 1/792					
18248	ACTIVE	N	N165-00-2/151	UMC - Station Building - Balham Stn	Gasket :Pipework	Asbestos	Sampled – Not Detected				Fire Hydrant Gaskets					
44931	ACTIVE	N	N165-00-2/151	UMC - Station Building - Balham Stn	Lead/Leading	Lead Paint/Lead	Known				Handrail - Grey Gloss				N	N
15744	ACTIVE	N	N165-00-2/151	UMC - Station Building - Balham Stn	Lead/Leading	Lead Paint/Lead	Known				Black & White Oil Based Paint - Girder. Thickness .34mm; Est Quantity 10 lm; Analysis 5.55%					
44929	ACTIVE	N	N165-00-2/151	UMC - Station Building - Balham Stn	Lead/Leading	Lead Paint/Lead	Known				Escalator No.1 Metal Housing - Dark Red Gloss				N	N
44930	ACTIVE	N	N165-00-2/151	UMC - Station Building - Balham Stn	Lead/Leading	Lead Paint/Lead	Known				Escalator No.3 Metal support - Orange Gloss				N	N
15745	ACTIVE	N	N165-00-2/151	UMC - Station Building - Balham Stn	Lead/Leading	Lead Paint/Lead	Known				Red Oil Based Paint - 2no Girder to Housing Unit. Thickness .27mm; Est Quantity 25 lm; Analysis 40.23%					
15746	ACTIVE	N	N165-00-2/151	UMC - Station Building - Balham Stn	Lead/Leading	Lead Paint/Lead	Known				Green/ Grey Oil Based Paint - Girder. Thickness .33mm; Est Quantity 6 lm; Analysis 11.24%					
18513	ACTIVE	N	N165-00-2/151	UMC - Station Building - Balham Stn	Lead/Leading	Lead Paint/Lead	Known				Grey Oil Based Paint - Stairs. Thickness .27mm; Est Quantity 5 sqm; Analysis 2.44%					



# Hazardous Material Asset Register - Summary



## N165-00 - Station Building - Balham Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18726	ACTIVE	N	N165-00-2/151	UMC - Station Building - Balham Stn	Lead/Leading	Lead Paint/Lead	Known				Red Oil Based Paint - Pipework Thickness .21mm; Est Quantity 60 lm; Analysis 4.15%					
15742	ACTIVE	N	N165-00-2/151/FLR-01	Floor - 1 - UMC - Station Building - Balham Stn	Durasteel	Asbestos	Surveyed - Not Detected				Lid to Storage Bin					
15747	ACTIVE	N	N165-00-2/171	Escalator Incline - Station Building - Balham Stn		Asbestos	Surveyed - Not Detected				Wooden Caulking					
11960	ACTIVE	N	N165-00-2/201	Passage - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15748	ACTIVE	N	N165-00-2/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Balham Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Metal Strip false ceiling				YES	
11961	ACTIVE	N	N165-00-2/202	Passage - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15749	ACTIVE	N	N165-00-2/202/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Balham Stn	Void	Asbestos	Surveyed - Not Detected				Concrete above Metal Strip false ceiling				YES	
11962	ACTIVE	N	N165-00-2/236	Passage - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18514	ACTIVE	N	N165-00-2/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Balham Stn	Void	Asbestos	Surveyed - Not Detected				Metal Corrugated Ceiling, PVC Cables and Metal Trunking above Fibreboard Ceiling				YES	
15750	ACTIVE	N	N165-00-2/236/FLR-01	Floor - 1 - Passage - Station Building - Balham Stn	Void	Asbestos	Surveyed - Not Detected				Concrete beneath Computer Tiles					YES
11963	ACTIVE	N	N165-00-2/237	Passage - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15752	ACTIVE	N	N165-00-2/237/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Balham Stn	Void	Asbestos	Surveyed - Not Detected				Metal above Supalux Tiles				YES	
15751	ACTIVE	N	N165-00-2/237/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Balham Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux					
11964	ACTIVE	N	N165-00-2/238	Lobby - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15753	ACTIVE	N	N165-00-2/238/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Balham Stn	Void	Asbestos	Surveyed - Not Detected				Metal above Supalux Tiles				YES	
18727	ACTIVE	N	N165-00-2/238/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Balham Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
11965	ACTIVE	N	N165-00-2/311	Switch Room - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N165-00 - Station Building - Balham Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11966	ACTIVE	N	N165-00-2/331	Mess Room - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46578	ACTIVE	N	N165-00-2/331	Mess Room - Station Building - Balham Stn		Lead Paint/Lead	Strongly Presumed				Ticket office, mess room & cupboard 2/331. Yellow gloss paint on pipework (0.81%) It is possible that layers containing lead at a percentage higher than 1% exist below		1			
46574	ACTIVE	N	N165-00-2/331	Mess Room - Station Building - Balham Stn		Lead Paint/Lead	Known				Mess room & cupboard RSJ & Metal Grills in false ceiling - Yellow gloss (23.4%)		23			
15755	ACTIVE	N	N165-00-2/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Balham Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18515	ACTIVE	N	N165-00-2/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Balham Stn	Void	Asbestos	Surveyed – Not Detected				Metal above Supalux Tiles				YES	
11967	ACTIVE	N	N165-00-2/411	Disused Room - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15756	ACTIVE	N	N165-00-2/411	Disused Room - Station Building - Balham Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
46577	ACTIVE	N	N165-00-2/411	Disused Room - Station Building - Balham Stn		Lead Paint/Lead	Known				Mess Room & Cupboard. Yellow gloss paint on RSJ and metal ceiling. (18.9%)		19			
11968	ACTIVE	N	N165-00-2/416	Toilet: Unisex - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18666	ACTIVE	N	N165-00-2/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Balham Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
15757	ACTIVE	N	N165-00-2/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Balham Stn	Void	Asbestos	Surveyed – Not Detected				Metal above Supalux Tiles				YES	
11969	ACTIVE	N	N165-00-2/661	Station Control Room - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18599	ACTIVE	N	N165-00-2/661/CLG-01	Ceiling: Solid - 1 - Station Control Room - Station Building - Balham Stn	Void	Asbestos	Surveyed – Not Detected				Metal above False Ceiling				YES	
11970	ACTIVE	N	N165-00-2/662	Switch Room - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15824	ACTIVE	N	N165-00-2/662/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Balham Stn	Void	Asbestos	Surveyed – Not Detected				Steel Ceiling, Fire Alarm System Brick wall to rear, Solid Plaster above Supalux Ceiling				YES	



# Hazardous Material Asset Register - Summary



## N165-00 - Station Building - Balham Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15825	ACTIVE	N	N165-00-2/662/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Balham Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		3			
15823	ACTIVE	N	N165-00-2/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Balham Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Box 30amp- Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
11971	ACTIVE	N	N165-00-2/663	Switch Room - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18796	ACTIVE	N	N165-00-2/663/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Balham Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	
18600	ACTIVE	N	N165-00-2/663/WAL-002 80890595	Wall: Internal - 2 - Switch Room - Station Building - Balham Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes: 2 x 30amp 2x 60amp 1 x 100amp W2; Red Fuse Box W3 No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		6			
11972	ACTIVE	N	N165-00-2/731	CER - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15826	ACTIVE	N	N165-00-2/731/WAL-006	Wall: Internal - 6 - CER - Station Building - Balham Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes 60amp - Insulation within No access 2020 re-inspection as CER in within the UMC and no Lift & Escalator ticket to gain access.		2			
11973	ACTIVE	N	N165-00-2/732	Switch Room - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15827	ACTIVE	N	N165-00-2/732	Switch Room - Station Building - Balham Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11974	ACTIVE	N	N165-00-2/746	SCR - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15828	ACTIVE	N	N165-00-2/746/CLG-01	Ceiling: Solid - 1 - SCR - Station Building - Balham Stn	Void	Asbestos	No Access: Presumed				Above Corrugated Metal				YES	
11975	ACTIVE	N	N165-00-2/951	Void - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46579	ACTIVE	N	N165-00-2/951	Void - Station Building - Balham Stn		Lead Paint/Lead	Strongly Presumed				Ticket office, mess room & cupboard. Yellow gloss paint on pipework. (0.81%) It is assumed layers containing lead at a percentage higher than 1% maybe present.					



# Hazardous Material Asset Register - Summary



## N165-00 - Station Building - Balham Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46575	ACTIVE	N	N165-00-2/951	Void - Station Building - Balham Stn		Lead Paint/Lead	Known				Mess Room & Cupboard. Yellow gloss paint on RSK and metal grills in false ceiling. (23.4%)		23			
15829	ACTIVE	N	N165-00-2/951/CLG-01	Ceiling: Solid - 1 - Void - Station Building - Balham Stn	Void	Asbestos	No Access: Presumed				Above Corrugated Metal				YES	
11976	ACTIVE	N	N165-00-2/991	UMC - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18458	ACTIVE	N	N165-00-2/991/CLG-01	Ceiling: Solid - 1 - UMC - Station Building - Balham Stn	Void	Asbestos	No Access: Presumed				No access above Supalux Ceiling. Damage to ceiling would occur if accessed above Supalux				YES	
11977	ACTIVE	N	N165-00-2/992	UMC - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15830	ACTIVE	N	N165-00-2/992/CLG-01	Ceiling: Solid - 1 - UMC - Station Building - Balham Stn	Void	Asbestos	No Access: Presumed				No access above Supalux Ceiling. Damage to ceiling would occur if accessed above Supalux				YES	
11978	ACTIVE	N	N165-00-3/081	Circulation Area - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15831	ACTIVE	N	N165-00-3/081	Circulation Area - Station Building - Balham Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11979	ACTIVE	N	N165-00-3/161	LMC - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15833	ACTIVE	N	N165-00-3/161	LMC - Station Building - Balham Stn	Cable: Sheath	Asbestos	Strongly Presumed				Encapsulated - 10mm Asbestos cable next to Earth Terminal Box - SP (on Floor?)  No access 2020 re-inspection within the LMC and no Lift & Escalator ticket to gain access.		1			
18601	ACTIVE	N	N165-00-3/161	LMC - Station Building - Balham Stn	Cable: Sheath	Asbestos	Strongly Presumed				15mm Cables - Encapsulated  No access 2020 re-inspection within the LMC and no Lift & Escalator ticket to gain access.		3			
18797	ACTIVE	N	N165-00-3/161	LMC - Station Building - Balham Stn	Gasket :Pipework	Asbestos	Strongly Presumed				Gaskets on Pump Equipment  No access 2020 re-inspection within the LMC and no Lift & Escalator ticket to gain access.					
15832	ACTIVE	N	N165-00-3/161	LMC - Station Building - Balham Stn	Cable Duct: Other	Asbestos	Surveyed - Not Detected				Cables Sleeves					
15834	ACTIVE	N	N165-00-3/161	LMC - Station Building - Balham Stn	Cable: Sheath	Asbestos	Strongly Presumed				Encapsulated - 1 x Cable J-Hanger No 3  No access 2020 re-inspection within the LMC and no Lift & Escalator ticket to gain access.		1			
44927	ACTIVE	N	N165-00-3/161	LMC - Station Building - Balham Stn	Lead/Leading	Lead Paint/Lead	Known				Column - Grey Gloss				N	N



# Hazardous Material Asset Register - Summary



## N165-00 - Station Building - Balham Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11980	ACTIVE	N	N165-00-3/201	Passage - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18668	ACTIVE	N	N165-00-3/201	Passage - Station Building - Balham Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11981	ACTIVE	N	N165-00-3/202	Passage - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15837	ACTIVE	N	N165-00-3/202	Passage - Station Building - Balham Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11982	ACTIVE	N	N165-00-3/203	Passage - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15838	ACTIVE	N	N165-00-3/203	Passage - Station Building - Balham Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11983	ACTIVE	N	N165-00-3/204	Passage - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18732	ACTIVE	N	N165-00-3/204	Passage - Station Building - Balham Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11984	ACTIVE	N	N165-00-3/205	Passage - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15839	ACTIVE	N	N165-00-3/205	Passage - Station Building - Balham Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11985	ACTIVE	N	N165-00-3/261	Platform 1 - Northbound Local - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15835	ACTIVE	N	N165-00-3/261	Platform 1 - Northbound Local - Station Building - Balham Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Boarding near 3/664					
15836	ACTIVE	N	N165-00-3/261/ FLR-01	Floor - 1 - Platform 1 - Station Building - Balham Stn	Cable: Sheath	Asbestos	Presumed				Platform 1 Invert - 10mm Asbestos Cable on 10th J hanger no access 2020 reinspection as confined space team required		1			YES
11986	ACTIVE	N	N165-00-3/262	Platform 2 - Southbound Local - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18669	ACTIVE	N	N165-00-3/262	Platform 2 - Southbound Local - Station Building - Balham Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Boarding near 3/661					
15840	ACTIVE	N	N165-00-3/262	Platform 2 - Southbound Local - Station Building - Balham Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
15841	ACTIVE	N	N165-00-3/262/ FLR-01	Floor - 1 - Platform 2 - Station Building - Balham Stn	Cable Ducts: Bitumen	Asbestos	Surveyed - Not Detected				Bitumen Cable Sleeves					YES



# Hazardous Material Asset Register - Summary



## N165-00 - Station Building - Balham Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18798	ACTIVE	N	N165-00-3/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Balham Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - 1 x Braided Cable no access 2020 reinspection as confined space team required		1			YES
11987	ACTIVE	N	N165-00-3/661	Switch Cupboard - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15842	ACTIVE	N	N165-00-3/661	Switch Cupboard - Station Building - Balham Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding above door					
11988	ACTIVE	N	N165-00-3/662	Switch Cupboard - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18670	ACTIVE	N	N165-00-3/662	Switch Cupboard - Station Building - Balham Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11989	ACTIVE	N	N165-00-3/663	Switch Room - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15843	ACTIVE	N	N165-00-3/663	Switch Room - Station Building - Balham Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11990	ACTIVE	N	N165-00-3/664	Switch Cupboard - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15844	ACTIVE	N	N165-00-3/664	Switch Cupboard - Station Building - Balham Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11991	ACTIVE	N	N165-00-3/665	Switch Room - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15845	ACTIVE	N	N165-00-3/665	Switch Room - Station Building - Balham Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11992	ACTIVE	N	N165-00-3/666	Switch Room - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18671	ACTIVE	N	N165-00-3/666	Switch Room - Station Building - Balham Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
11993	ACTIVE	N	N165-00-3/711	Relay Room - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44311	ACTIVE	N	N165-00-3/711	Relay Room - Station Building - Balham Stn	Other Boarding	Asbestos	Presumed				Paxoline boarding wall 3					
18673	ACTIVE	N	N165-00-3/711/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - Balham Stn	Vinyl tiles	Asbestos	Known				Vinyl Tiles some tiles removed					
18672	ACTIVE	N	N165-00-3/711/FLR-01	Floor - 1 - Relay Room - Station Building - Balham Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Green & White Tiles					



# Hazardous Material Asset Register - Summary



## N165-00 - Station Building - Balham Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15853	ACTIVE	N	N165-00-3/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Balham Stn	Boarding: Cement	Asbestos	Strongly Presumed				Cement beneath Relay Capacitors - Panel under PCB's					
15849	ACTIVE	N	N165-00-3/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Balham Stn	Vinyl tiles	Asbestos	Known				Grey & Green Vinyl Tiles - Some removed some tiles removed of both grey and green					
15854	INACTIVE	N	N165-00-3/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Balham Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				6 x PCB's - Fair Condition. Serial Nos. 197449; 197466; 197451; 197450; 197455; 197458 Re inspected 14/04/2015		6			
15850	ACTIVE	N	N165-00-3/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Balham Stn	Cable: Sheath	Asbestos	Strongly Presumed				10mm Cable going to track		1			
18251	ACTIVE	N	N165-00-3/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Balham Stn	Cable: Sheath	Asbestos	Strongly Presumed				10mm Cable going into Invert		1			
15851	ACTIVE	N	N165-00-3/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Balham Stn	Cable: Sheath	Asbestos	Strongly Presumed				20mm Cable going to track		1			
15852	ACTIVE	N	N165-00-3/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Balham Stn	Cable: Sheath	Asbestos	Strongly Presumed				5mm Cable		2			
53541	ACTIVE	N	N165-00-3/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Balham Stn	Other Boarding	Asbestos	Presumed				brown composite packing material to framework on wall 3					
44312	ACTIVE	N	N165-00-3/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Balham Stn	Other Boarding	Asbestos	Presumed				1 x brown composite boarding wall 3 behind plastic casing					
18674	ACTIVE	N	N165-00-3/711/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Balham Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse Box - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
11994	ACTIVE	N	N165-00-3/712	Relay Room - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
44313	INACTIVE	N	N165-00-3/712	Relay Room - Station Building - Balham Stn	Cable Ducts: Cement	Asbestos	Presumed				Filled in ductwork					
15855	ACTIVE	N	N165-00-3/712/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - Balham Stn	Vinyl tiles	Asbestos	Known				Green & Grey Vinyl Tiles - to ALL walls and ceiling majority removed to walls both green & grey but still present behind equipment and racking to walls					
18733	INACTIVE	N	N165-00-3/712/FLR-01	Floor - 1 - Relay Room - Station Building - Balham Stn	Vinyl tiles	Asbestos	Surveyed - Not Detected				Green & White Tiles					



# Hazardous Material Asset Register - Summary



## N165-00 - Station Building - Balham Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15859	ACTIVE	N	N165-00-3/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Balham Stn	Westing house Boxes	Asbestos	Strongly Presumed				1 x Westinghouse Box - Insulation within  No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
19957	ACTIVE	N	N165-00-3/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Balham Stn	Boarding: Cement	Asbestos	Strongly Presumed				Cement beneath Relay Capacitors to top shelf of rack on wall 1					
15856	INACTIVE	N	N165-00-3/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Balham Stn	Vinyl tiles	Asbestos	Known				Grey & Green Vinyl Tiles - Majority Removed  majority removed to walls both green & grey.					
53543	ACTIVE	N	N165-00-3/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Balham Stn	Other Boarding	Asbestos	Presumed				brown composite board x6 to equipment top rack of shelving wall 1					
53544	ACTIVE	N	N165-00-3/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Balham Stn	Other Boarding	Asbestos	Presumed				brown composite board x6 to bottom equipment on rack wall 1					
15860	INACTIVE	N	N165-00-3/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Balham Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				6no PCB's - Fair Condition. Serial Nos. 197457; 197486; 186506; 197452; 197484; 197471 Re inspected 14/04/2015		6			
15857	ACTIVE	N	N165-00-3/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Balham Stn	Cable: Sheath	Asbestos	Strongly Presumed				10mm 20mm Cables to cable run around room from wall 1 to wall 3 exit to track - Encapsulated good condition		1			
18675	INACTIVE	N	N165-00-3/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Balham Stn	Cable: Sheath	Asbestos	Strongly Presumed				20mm Cable going to track		1			
15858	ACTIVE	N	N165-00-3/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Balham Stn	Cable: Sheath	Asbestos	Strongly Presumed				thin cable exiting box to wall 2 and running down wall behind pipe.		1			
53542	ACTIVE	N	N165-00-3/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Balham Stn	Other Boarding	Asbestos	Presumed				composite panel box to wall 2 back of room					
53546	ACTIVE	N	N165-00-3/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Balham Stn	Other Boarding	Asbestos	Presumed				brown panel to box on rack wall 3					
53545	ACTIVE	N	N165-00-3/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Balham Stn	Other Boarding	Asbestos	Presumed				brown composite packing board to rack wall 3					
11995	ACTIVE	N	N165-00-3/731	CER - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15846	ACTIVE	N	N165-00-3/731	CER - Station Building - Balham Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
11996	ACTIVE	N	N165-00-3/761	Store - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15847	ACTIVE	N	N165-00-3/761	Store - Station Building - Balham Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N165-00 - Station Building - Balham Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11997	ACTIVE	N	N165-00-3/951	Void - Station Building - Balham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15848	ACTIVE	N	N165-00-3/951	Void - Station Building - Balham Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					

## N167-00 - Station Building - Tooting Bec Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12011	ACTIVE	N	N167-00-1/081	Lobby - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15684	ACTIVE	N	N167-00-1/081	Lobby - Station Building - Tooting Bec Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Wall					
12012	ACTIVE	N	N167-00-1/201	Passage - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18434	ACTIVE	N	N167-00-1/201	Passage - Station Building - Tooting Bec Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12013	ACTIVE	N	N167-00-1/202	Passage - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15685	ACTIVE	N	N167-00-1/202	Passage - Station Building - Tooting Bec Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12014	ACTIVE	N	N167-00-1/451	Tenancy - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15686	ACTIVE	N	N167-00-1/451	Tenancy - Station Building - Tooting Bec Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Tenancy					
12015	ACTIVE	N	N167-00-1/601	Stairs: Linear - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15687	ACTIVE	N	N167-00-1/601	Stairs: Linear - Station Building - Tooting Bec Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12016	ACTIVE	N	N167-00-1/602	Stairs: Linear - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18435	ACTIVE	N	N167-00-1/602/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Tooting Bec Stn	Void	Asbestos	No Access: Presumed				Above Metal Strip					
12017	ACTIVE	N	N167-00-1/603	Stairs: Linear - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N167-00 - Station Building - Tooting Bec Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15688	ACTIVE	N	N167-00-1/603/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Tooting Bec Stn	Void	Asbestos	No Access: Presumed				Above Metal Strip					
12018	ACTIVE	N	N167-00-1/604	Stairs: Linear - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15689	ACTIVE	N	N167-00-1/604/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Tooting Bec Stn	Void	Asbestos	No Access: Presumed				Above Metal Strip					
12019	ACTIVE	N	N167-00-1/781	TXR - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18436	ACTIVE	N	N167-00-1/781	TXR - Station Building - Tooting Bec Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Cable Ducts - In Draw Pit		8			
15690	ACTIVE	N	N167-00-1/781	TXR - Station Building - Tooting Bec Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Box - Arc Chutes and Flash Guards presumed inside switches. May also be present in other equipment inside room  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1			
12020	ACTIVE	N	N167-00-2/001	Booking Hall - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15691	ACTIVE	N	N167-00-2/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Tooting Bec Stn	Void	Asbestos	Surveyed – Not Detected				Metal above Metal Strip false ceiling				YES	
12021	ACTIVE	N	N167-00-2/011	Ticket Office - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18437	ACTIVE	N	N167-00-2/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Tooting Bec Stn	Void	Asbestos	Surveyed – Not Detected				Metal above Plasterboard False Ceiling				YES	
15692	ACTIVE	N	N167-00-2/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Tooting Bec Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden false floor					YES
12022	ACTIVE	N	N167-00-2/021	POM - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15694	ACTIVE	N	N167-00-2/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Tooting Bec Stn	Void	Asbestos	Surveyed – Not Detected				Metal above Plasterboard False Ceiling				YES	
15693	ACTIVE	N	N167-00-2/021/FLR-01	Floor - 1 - POM - Station Building - Tooting Bec Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden false floor					



# Hazardous Material Asset Register - Summary



## N167-00 - Station Building - Tooting Bec Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12023	ACTIVE	N	N167-00-2/031	Mess Room - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15695	ACTIVE	N	N167-00-2/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Tooting Bec Stn	Void	Asbestos	Surveyed – Not Detected				Supalux Board and Metal above Plasterboard False Ceiling				YES	
12024	ACTIVE	N	N167-00-2/036	Store - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15696	ACTIVE	N	N167-00-2/036	Store - Station Building - Tooting Bec Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding					
12025	ACTIVE	N	N167-00-2/037	Toilet: Unisex - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15697	ACTIVE	N	N167-00-2/037	Toilet: Unisex - Station Building - Tooting Bec Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12026	ACTIVE	N	N167-00-2/071	Circulation Area - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18499	ACTIVE	N	N167-00-2/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Tooting Bec Stn	Void	Asbestos	Surveyed – Not Detected				Metal above Metal Strip false ceiling				YES	
12027	ACTIVE	N	N167-00-2/082	Lobby - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15698	ACTIVE	N	N167-00-2/082	Lobby - Station Building - Tooting Bec Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12028	ACTIVE	N	N167-00-2/083	Lobby - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18722	ACTIVE	N	N167-00-2/083/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Tooting Bec Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Plasterboard False Ceiling				YES	
12029	ACTIVE	N	N167-00-2/151	UMC - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15700	ACTIVE	N	N167-00-2/151	UMC - Station Building - Tooting Bec Stn	Rope Gaskets	Asbestos	Surveyed – Not Detected				Cloth Webbing					
15704	ACTIVE	N	N167-00-2/151	UMC - Station Building - Tooting Bec Stn	Lead/Leading	Lead Paint/Lead	Known				Yellow Oil Based Paint - Stairs Thickness .25mm; Est Quantity 6 lm; Analysis 2.84%					
19949	ACTIVE	N	N167-00-2/151	UMC - Station Building - Tooting Bec Stn	Lead/Leading	Lead Paint/Lead	Known				Black & White Oil Based Paint - Girders Thickness .19mm; Est Quantity 18 lm; Analysis 4.87%					



# Hazardous Material Asset Register - Summary



## N167-00 - Station Building - Tooting Bec Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15703	ACTIVE	N	N167-00-2/151	UMC - Station Building - Tooting Bec Stn	Lead/Leading	Lead Paint/Lead	Known				Green/ Grey Oil Based Paint - Girder Thickness .31mm; Est Quantity 15 Im; Analysis 2.85%					
15701	ACTIVE	N	N167-00-2/151	UMC - Station Building - Tooting Bec Stn	Lead/Leading	Lead Paint/Lead	Known				Grey Oil Based Paint - Pipework Thickness .33mm; Est Quantity 15 Im; Analysis 21.45%					
18500	ACTIVE	N	N167-00-2/151	UMC - Station Building - Tooting Bec Stn	Lead/Leading	Lead Paint/Lead	Known				Red Oil Based Paint - 2no Girders to housing units Thickness .08mm; Est Quantity 6 Im; Analysis 32.24%					
15702	ACTIVE	N	N167-00-2/151	UMC - Station Building - Tooting Bec Stn	Lead/Leading	Lead Paint/Lead	Known				Red Oil Based Paint - Pipework Thickness .07mm; Est Quantity 30 Im; Analysis 2.75%					
15699	ACTIVE	N	N167-00-2/151/FLR-01	Floor - 1 - UMC - Station Building - Tooting Bec Stn	Durasteel	Asbestos	Surveyed – Not Detected				Lid to Storage Bin					
18230	ACTIVE	N	N167-00-2/171	Escalator Incline - Station Building - Tooting Bec Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Ring Joints along incline - Rings sealed but may be present behind  No access into esclator incline during 2020 re-inspection. Permit required with L&E					
12030	ACTIVE	N	N167-00-2/201	Passage - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18501	ACTIVE	N	N167-00-2/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Tooting Bec Stn	Void	Asbestos	Surveyed – Not Detected				Metal above Plasterboard False Ceiling				YES	
15706	ACTIVE	N	N167-00-2/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Tooting Bec Stn	Void	Asbestos	No Access: Presumed				Above - Metal Strip					
15705	ACTIVE	N	N167-00-2/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Tooting Bec Stn	Void	Asbestos	Sampled – Not Detected				Cladding to steel within ceiling/ void - NADIS - above metal strip					
12031	ACTIVE	N	N167-00-2/202	Passage - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12032	ACTIVE	N	N167-00-2/236	Passage - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12033	ACTIVE	N	N167-00-2/237	Lobby - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18723	ACTIVE	N	N167-00-2/237/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Tooting Bec Stn	Void	Asbestos	Surveyed – Not Detected				Metal above Plasterboard False Ceiling				YES	
15707	ACTIVE	N	N167-00-2/237/FLR-01	Floor - 1 - Lobby - Station Building - Tooting Bec Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden false floor					



# Hazardous Material Asset Register - Summary



## N167-00 - Station Building - Tooting Bec Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12034	ACTIVE	N	N167-00-2/331	Mess Room - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15708	ACTIVE	N	N167-00-2/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Tooting Bec Stn	Void	Asbestos	Surveyed – Not Detected				Metal above Plasterboard False Ceiling				YES	
15709	ACTIVE	N	N167-00-2/331/CLG-02	Ceiling: Suspended - 2 - Mess Room - Station Building - Tooting Bec Stn	Void	Asbestos	Surveyed – Not Detected				Metal above Plasterboard False Ceiling				YES	
12035	ACTIVE	N	N167-00-2/401	Bin Store - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15710	ACTIVE	N	N167-00-2/401	Bin Store - Station Building - Tooting Bec Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
18502	ACTIVE	N	N167-00-2/401/CLG-01	Ceiling: Solid - 1 - Bin Store - Station Building - Tooting Bec Stn	Lead/Leading	Lead Paint/Lead	Known				White Oil Based Paint - Girder in Ceiling. Thickness .04mm; Est Quantity 4 sqm; Analysis 5.92%					
12036	ACTIVE	N	N167-00-2/406	Store - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18503	ACTIVE	N	N167-00-2/406/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Tooting Bec Stn	Void	Asbestos	Surveyed – Not Detected				Metal above Plasterboard False Ceiling				YES	
12037	ACTIVE	N	N167-00-2/411	SVC - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15711	ACTIVE	N	N167-00-2/411	SVC - Station Building - Tooting Bec Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12038	ACTIVE	N	N167-00-2/416	Toilet: Female - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15712	ACTIVE	N	N167-00-2/416/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Tooting Bec Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Plasterboard False Ceiling				YES	
12039	ACTIVE	N	N167-00-2/417	Toilet: Male - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15713	ACTIVE	N	N167-00-2/417/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Tooting Bec Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Plasterboard False Ceiling				YES	
12040	ACTIVE	N	N167-00-2/661	Switch Room - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N167-00 - Station Building - Tooting Bec Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15714	ACTIVE	N	N167-00-2/661	Switch Room - Station Building - Tooting Bec Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12041	ACTIVE	N	N167-00-2/662	Switch Room - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18504	ACTIVE	N	N167-00-2/662	Switch Room - Station Building - Tooting Bec Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12042	ACTIVE	N	N167-00-2/746	SCR - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15715	ACTIVE	N	N167-00-2/746/CLG-01	Ceiling: Suspended - 1 - SCR - Station Building - Tooting Bec Stn	Void	Asbestos	Surveyed – Not Detected				Metal, Fibreglass Lagging above Plasterboard Ceiling				YES	
15716	ACTIVE	N	N167-00-2/746/FLR-01	Floor - 1 - SCR - Station Building - Tooting Bec Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					
12043	ACTIVE	N	N167-00-2/751	Station Control Room - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15717	ACTIVE	N	N167-00-2/751/FLR-01	Floor - 1 - Station Control Room - Station Building - Tooting Bec Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					
18505	ACTIVE	N	N167-00-2/751/FLR-01	Floor - 1 - Station Control Room - Station Building - Tooting Bec Stn	Void	Asbestos	No Access: Presumed				Above Meal Strip					
12044	ACTIVE	N	N167-00-2/761	Plant Room - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15720	ACTIVE	N	N167-00-2/761	Plant Room - Station Building - Tooting Bec Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing;					
15719	ACTIVE	N	N167-00-2/761/CLG-01	Ceiling: Solid - 1 - Plant Room - Station Building - Tooting Bec Stn	Void	Asbestos	No Access: Presumed				Above Metal Ceiling				YES	
15718	ACTIVE	N	N167-00-2/761/FLR-01	Floor - 1 - Plant Room - Station Building - Tooting Bec Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					
12045	ACTIVE	N	N167-00-2/771	Pump Room - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15721	ACTIVE	N	N167-00-2/771	Pump Room - Station Building - Tooting Bec Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12046	ACTIVE	N	N167-00-2/776	Fan Room - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N167-00 - Station Building - Tooting Bec Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18506	ACTIVE	N	N167-00-2/776	Fan Room - Station Building - Tooting Bec Stn	Durasteel	Asbestos	Surveyed – Not Detected				New Type					
12047	ACTIVE	N	N167-00-2/786	Service Riser - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15722	ACTIVE	N	N167-00-2/786	Service Riser - Station Building - Tooting Bec Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
18664	ACTIVE	N	N167-00-2/901	Vent Shaft - Station Building - Tooting Bec Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
15723	ACTIVE	N	N167-00-2/902	Vent Shaft - Station Building - Tooting Bec Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12048	ACTIVE	N	N167-00-3/081	Circulation Area - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15724	ACTIVE	N	N167-00-3/081	Circulation Area - Station Building - Tooting Bec Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12049	ACTIVE	N	N167-00-3/082	Lobby - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18507	ACTIVE	N	N167-00-3/082	Lobby - Station Building - Tooting Bec Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12050	ACTIVE	N	N167-00-3/161	LMC - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15725	ACTIVE	N	N167-00-3/161	LMC - Station Building - Tooting Bec Stn	Cable Ducts: Cement	Asbestos	Strongly Presumed				Cement Cable Ducts (from Plat from 1 Invert?) Encapsulated					
15726	ACTIVE	N	N167-00-3/161	LMC - Station Building - Tooting Bec Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux by Entrance - Non Asbestos;					
18724	ACTIVE	N	N167-00-3/161	LMC - Station Building - Tooting Bec Stn	Cable: Sheath	Asbestos	Surveyed – Not Detected				Cables - Non Asbestos;					
15727	ACTIVE	N	N167-00-3/161	LMC - Station Building - Tooting Bec Stn	Lead/Leading	Lead Paint/Lead	Known				Blue Oil Based Paint - 2 no Girders. Thickness .20mm; Est Quantity 4 lm; Analysis 8.37%					
18247	ACTIVE	N	N167-00-3/161	LMC - Station Building - Tooting Bec Stn	Lead/Leading	Lead Paint/Lead	Known				Black Oil Based Paint - 2 no Escalators. Thickness .44mm; Est Quantity 4 sqm; Analysis 39.79%					
12051	ACTIVE	N	N167-00-3/201	Passage - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18508	ACTIVE	N	N167-00-3/201	Passage - Station Building - Tooting Bec Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N167-00 - Station Building - Tooting Bec Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12052	ACTIVE	N	N167-00-3/202	Passage - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15728	ACTIVE	N	N167-00-3/202/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Tooting Bec Stn	Void	Asbestos	No Access: Presumed				Above Metal Panels				YES	
12053	ACTIVE	N	N167-00-3/203	Passage - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15729	ACTIVE	N	N167-00-3/203/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Tooting Bec Stn	Void	Asbestos	No Access: Presumed				Above Metal Panels				YES	
12054	ACTIVE	N	N167-00-3/204	Passage - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18509	ACTIVE	N	N167-00-3/204	Passage - Station Building - Tooting Bec Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12055	ACTIVE	N	N167-00-3/261	Platform 1 - Northbound Local - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44924	ACTIVE	N	N167-00-3/261	Platform 1 - Northbound Local - Station Building - Tooting Bec Stn	Cable: Sheath	Asbestos	Strongly Presumed				NB Tunnel - Left hand side of tail end of tunnel, 2nd cable shelf from top - 2x10mm Cables		2		N	N
15731	ACTIVE	N	N167-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Tooting Bec Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Encapsulated - TLL Connect 6 x Cables Ducts - Leading from platform inverts through to concourse inverts/cable ways  No access into platform inverts during 2020 re-inspection. Confined space entry required.					YES
15730	ACTIVE	N	N167-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Tooting Bec Stn	Cable: Sheath	Asbestos	Strongly Presumed				2 x Cables - 2nd J Hanger down on Pit side wall  No access into platform inverts during 2020 re-inspection. Confined space entry required.		2			YES
12056	ACTIVE	N	N167-00-3/262	Platform 2 - Southbound Local - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44926	ACTIVE	N	N167-00-3/262	Platform 2 - Southbound Local - Station Building - Tooting Bec Stn	Cement Troughing	Asbestos	Presumed				SB Tunnel - 2m into Tunnel - Troughing				N	N
44925	ACTIVE	N	N167-00-3/262	Platform 2 - Southbound Local - Station Building - Tooting Bec Stn	Cable: Sheath	Asbestos	Strongly Presumed				SB Tunnel - Head of Tunnel - 3no Cables		3		N	N



# Hazardous Material Asset Register - Summary



## N167-00 - Station Building - Tooting Bec Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18725	ACTIVE	N	N167-00-3/262	Platform 2 - Southbound Local - Station Building - Tooting Bec Stn	Cable: Sheath	Asbestos	Strongly Presumed				15mm Cable No access into platform inverts during 2020 re-inspection. Confined space entry required.		1			
15733	ACTIVE	N	N167-00-3/262/ FLR-01	Floor - 1 - Platform 2 - Station Building - Tooting Bec Stn	Cable Ducts: Bitumen	Asbestos	Surveyed – Not Detected				Plat 2 Invert- LHS Bitumem Ducts Cable Way- Non Asbestos					YES
18510	ACTIVE	N	N167-00-3/262/ FLR-01	Floor - 1 - Platform 2 - Station Building - Tooting Bec Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Plat 2 Invert - 6 x Cables Ducts - Leading from platform inverts through to concourse inverts/cable ways No access into platform inverts during 2020 re-inspection. Confined space entry required.		6			YES
15732	ACTIVE	N	N167-00-3/262/ FLR-01	Floor - 1 - Platform 2 - Station Building - Tooting Bec Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - Located on 2nd J Hanger running length of invert - 2x10mm Cables No access into platform inverts during 2020 re-inspection. Confined space entry required.		2			YES
15543	ACTIVE	N	N167-00-3/262/ FLR-01	Floor - 1 - Platform 2 - Station Building - Tooting Bec Stn	Cable: Wrap	Asbestos	Strongly Presumed				Plat 2 Invert - 1st J Hanger at ends of platform at trackside penetration - Cable Wrapping No access into platform inverts during 2020 re-inspection. Confined space entry required.					YES
12057	ACTIVE	N	N167-00-3/406	CER - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15544	ACTIVE	N	N167-00-3/406/ FLR-01	Floor - 1 - CER - Station Building - Tooting Bec Stn	Void	Asbestos	Surveyed – Not Detected				Beneath Computer Flooring					YES
12058	ACTIVE	N	N167-00-3/661	Switch Room - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18270	ACTIVE	N	N167-00-3/661	Switch Room - Station Building - Tooting Bec Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12059	ACTIVE	N	N167-00-3/664	Switch Room - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15545	ACTIVE	N	N167-00-3/664	Switch Room - Station Building - Tooting Bec Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12060	ACTIVE	N	N167-00-3/665	Service Riser - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15546	ACTIVE	N	N167-00-3/665	Service Riser - Station Building - Tooting Bec Stn	Cable: Sheath	Asbestos	Strongly Presumed				15mm Cable		1			



# Hazardous Material Asset Register - Summary



## N167-00 - Station Building - Tooting Bec Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12061	ACTIVE	N	N167-00-3/667	Switch Room - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18271	ACTIVE	N	N167-00-3/667/FLR-01	Floor - 1 - Switch Room - Station Building - Tooting Bec Stn	Debris: Other	Asbestos	Surveyed – Not Detected				Supalux Debris on Floor					
12062	ACTIVE	N	N167-00-3/668	Switch Room - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15547	ACTIVE	N	N167-00-3/668	Switch Room - Station Building - Tooting Bec Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12063	ACTIVE	N	N167-00-3/669	Switch Cupboard - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18657	ACTIVE	N	N167-00-3/669	Switch Cupboard - Station Building - Tooting Bec Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding above Window					
12064	ACTIVE	N	N167-00-3/711	CER - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15549	ACTIVE	N	N167-00-3/711	CER - Station Building - Tooting Bec Stn	Vinyl tiles	Asbestos	Known				Green & White Tiles - Chrysotile - some removed					
19479	INACTIVE	N	N167-00-3/711	CER - Station Building - Tooting Bec Stn	Boarding: Cement	Asbestos	No Access: Presumed				Boarding - Cement Made inactive duplication with 18710					
18243	ACTIVE	N	N167-00-3/711/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Tooting Bec Stn	Vinyl tiles	Asbestos	Known				Green & White Tiles - Chrysotile Note - Most of the tiles have been removed. Remaining tiles are in good condition.					
15548	ACTIVE	N	N167-00-3/711/FLR-01	Floor - 1 - CER - Station Building - Tooting Bec Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl Tiles					
18710	ACTIVE	N	N167-00-3/711/WAL-001	Wall: Internal - 1 - CER - Station Building - Tooting Bec Stn	Boarding: Cement	Asbestos	Strongly Presumed				Cement Panels under capacitors top shelf wall 3		1			
15552	INACTIVE	N	N167-00-3/711/WAL-001	Wall: Internal - 1 - CER - Station Building - Tooting Bec Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				6 x PCB's - Fair Condition Serial Nos. 186420, 186422, 186481, 186468, 186566, 197489 Re inspected 14/04/2015		6			
53678	ACTIVE	N	N167-00-3/711/WAL-002	Wall: Internal - 2 - CER - Station Building - Tooting Bec Stn	Other Boarding	Asbestos	Presumed				brown panel to 600v box to wall 2					
53679	ACTIVE	N	N167-00-3/711/WAL-002	Wall: Internal - 2 - CER - Station Building - Tooting Bec Stn	Cable: Sheath	Asbestos	Presumed				thin cable to 600v box on wall 2					



# Hazardous Material Asset Register - Summary



## N167-00 - Station Building - Tooting Bec Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15550	ACTIVE	N	N167-00-3/711/WAL-002	Wall: Internal - 2 - CER - Station Building - Tooting Bec Stn	Cable: Sheath	Asbestos	Strongly Presumed				SP Cables - 3 cables running throughout 2 top hanger going to trackside wall 5 1 running to invert in second hanger		5			
53677	ACTIVE	N	N167-00-3/711/WAL-003	Wall: Internal - 3 - CER - Station Building - Tooting Bec Stn	Other Boarding	Asbestos	Presumed				4 brown composite board bottom shelf to rack wall 3					
53675	ACTIVE	N	N167-00-3/711/WAL-003	Wall: Internal - 3 - CER - Station Building - Tooting Bec Stn	Other Boarding	Asbestos	Presumed				Wall 3 To rack 6 x black composite board					
53676	ACTIVE	N	N167-00-3/711/WAL-003	Wall: Internal - 3 - CER - Station Building - Tooting Bec Stn	Other Boarding	Asbestos	Presumed				2 x brown composite board wall 3 To top shelf of rack					
18272	ACTIVE	N	N167-00-3/711/WAL-003	Wall: Internal - 3 - CER - Station Building - Tooting Bec Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse Box - Insulation within  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1			
15551	ACTIVE	N	N167-00-3/711/WAL-005	Wall: Internal - 5 - CER - Station Building - Tooting Bec Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Paxolin Board - onsite inspection confirmed new relay and board					
12065	ACTIVE	N	N167-00-3/712	Relay Room - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15560	ACTIVE	N	N167-00-3/712	Relay Room - Station Building - Tooting Bec Stn	Other Electrical Boxes	Asbestos	Presumed				Small Transformer - Insulation within  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1			
18334	ACTIVE	N	N167-00-3/712	Relay Room - Station Building - Tooting Bec Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables x 4 running from middle fuse bay wall 1 1 on top j hanger to trackside exit wall 2 and 3 cables bottom hanger entering invert to floor wall 1		6			
44317	ACTIVE	N	N167-00-3/712	Relay Room - Station Building - Tooting Bec Stn	Cable Ducts: Cement	Asbestos	Presumed				filled in cement ductwork  Cement ductwork not visible beneath filling on top - therefore not scored during 2020 re-inspection.					
18335	ACTIVE	N	N167-00-3/712	Relay Room - Station Building - Tooting Bec Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				PCB's - Fair Condition Serial Nos. 197473; 197485; 197477; 197479; 197481; 197460; 197478 Inspected 14/04/2015		7			
15557	ACTIVE	N	N167-00-3/712/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - Tooting Bec Stn	Vinyl tiles	Asbestos	Known				Marley Tiles to Wall - known - Chrysotile - some removed					
15558	ACTIVE	N	N167-00-3/712/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - Tooting Bec Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling				YES	



# Hazardous Material Asset Register - Summary



## N167-00 - Station Building - Tooting Bec Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15553	ACTIVE	N	N167-00-3/712/FLR-01	Floor - 1 - Relay Room - Station Building - Tooting Bec Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl Tiles					
15559	ACTIVE	N	N167-00-3/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tooting Bec Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse Box Insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1			
53674	ACTIVE	N	N167-00-3/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tooting Bec Stn	Other Boarding	Asbestos	Presumed				3 long brown composite panels to bottom shelf of rack to wall 1 above presumed cement panel					
15554	ACTIVE	N	N167-00-3/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tooting Bec Stn	Vinyl tiles	Asbestos	Known				Marley Tiles to Wall - known - Chrysotile - some removed					
15561	ACTIVE	N	N167-00-3/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tooting Bec Stn	Boarding: Cement	Asbestos	Strongly Presumed				Rack to wall 1 1 x long brown panel with cement panel base to 3 rd shelf 1 x cracked cement panel to bottom of rack		2			
53671	ACTIVE	N	N167-00-3/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tooting Bec Stn	Other Boarding	Asbestos	Presumed				8 x Black Composite panel to rack - Top of rack to capacitors 693T wall 1					
53672	ACTIVE	N	N167-00-3/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tooting Bec Stn	Other Boarding	Asbestos	Presumed				1 x long brown panel above cement panel to 3rd shelf on rack wall 1					
53670	ACTIVE	N	N167-00-3/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Tooting Bec Stn	Other Boarding	Asbestos	Presumed				600v Box with brown composite panel within					
53673	ACTIVE	N	N167-00-3/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Tooting Bec Stn	Cable: Sheath	Asbestos	Presumed				thin white cable to 600v box wall 2					
18333	ACTIVE	N	N167-00-3/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Tooting Bec Stn	Vinyl tiles	Asbestos	Known				Marley Tiles to Wall - known - Chrysotile - some removed					
15555	ACTIVE	N	N167-00-3/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Tooting Bec Stn	Vinyl tiles	Asbestos	Known				Marley Tiles to Wall - known - Chrysotile - some removed					
15556	ACTIVE	N	N167-00-3/712/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Tooting Bec Stn	Vinyl tiles	Asbestos	Known				Marley Tiles to Wall - known - Chrysotile - some removed					
12066	ACTIVE	N	N167-00-3/731	Switch Cupboard - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18711	ACTIVE	N	N167-00-3/731	Switch Cupboard - Station Building - Tooting Bec Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12067	ACTIVE	N	N167-00-3/732	CER - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N167-00 - Station Building - Tooting Bec Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15564	ACTIVE	N	N167-00-3/732	CER - Station Building - Tooting Bec Stn	Cable Ducts: Bitumen	Asbestos	Surveyed – Not Detected				Bitumem Ducts to Inverts - Non Asbestos					
15563	ACTIVE	N	N167-00-3/732/FLR-01	Floor - 1 - CER - Station Building - Tooting Bec Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
12068	ACTIVE	N	N167-00-3/733	CER - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15870	ACTIVE	N	N167-00-3/733	CER - Station Building - Tooting Bec Stn	Other Boarding	Asbestos	Sampled – Not Detected				Boarding between the distribution board and CMS; also between the Changeover contactor and the CMS					
18679	ACTIVE	N	N167-00-3/733/FLR-01	Floor - 1 - CER - Station Building - Tooting Bec Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Flooring					
15871	ACTIVE	N	N167-00-3/733/WAL-001	Wall: Internal - 1 - CER - Station Building - Tooting Bec Stn	Isolator Switches	Asbestos	Strongly Presumed				Grey Switch Boxes 60amp - Insulation within  No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		2			
12069	ACTIVE	N	N167-00-A/781	TXR - Station Building - Tooting Bec Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18658	ACTIVE	N	N167-00-A/781	TXR - Station Building - Tooting Bec Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
15562	ACTIVE	N	N167-00-B/781	Roof Access - Station Building - Tooting Bec Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					

## N169-00 - Station Building - Tooting Broadway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12070	ACTIVE	N	N169-00-1/001	Booking Hall - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12071	ACTIVE	N	N169-00-1/011	Ticket Office - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18716	ACTIVE	N	N169-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Tooting Broadway Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Fibreglass Pipe Lagging above Plasterboard Ceiling				YES	
15602	ACTIVE	N	N169-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Tooting Broadway Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Metal Tray & PVC Cables beneath False Wooden Floor					YES
12072	ACTIVE	N	N169-00-1/021	POM - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N169-00 - Station Building - Tooting Broadway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15603	ACTIVE	N	N169-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Tooting Broadway Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Fibreglass Pipe Lagging above Plasterboard Ceiling					
18347	ACTIVE	N	N169-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Tooting Broadway Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Metal Tray & PVC Cables beneath False Wooden Floor					YES
12073	ACTIVE	N	N169-00-1/031	Mess Room - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15604	ACTIVE	N	N169-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Tooting Broadway Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Supalux Boarding above Plasterboard Ceiling				YES	
12074	ACTIVE	N	N169-00-1/036	Toilet: Unisex - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18229	ACTIVE	N	N169-00-1/036	Toilet: Unisex - Station Building - Tooting Broadway Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding					
15605	ACTIVE	N	N169-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Tooting Broadway Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Plasterboard Ceiling				YES	
12075	ACTIVE	N	N169-00-1/071	Circulation Area - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15606	ACTIVE	N	N169-00-1/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Tooting Broadway Stn	Glazing Rope	Asbestos	Sampled – Not Detected				Rope Seal on Glass Ceilings. Glazing appears NAD in latest Type 2/3					
12076	ACTIVE	N	N169-00-1/081	Lobby - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12077	ACTIVE	N	N169-00-1/082	Lobby - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12078	ACTIVE	N	N169-00-1/236	Passage - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15608	ACTIVE	N	N169-00-1/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Tooting Broadway Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Plasterboard Ceiling				YES	
12079	ACTIVE	N	N169-00-1/237	Passage - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18661	ACTIVE	N	N169-00-1/237/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Tooting Broadway Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Plasterboard Ceiling				YES	



# Hazardous Material Asset Register - Summary



## N169-00 - Station Building - Tooting Broadway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18349	ACTIVE	N	N169-00-1/237/FLR-01	Floor - 1 - Passage - Station Building - Tooting Broadway Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Metal Tray & PVC Cables beneath False Wooden Floor					YES
12080	ACTIVE	N	N169-00-1/281	Station Control Room - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15609	ACTIVE	N	N169-00-1/281/FLR-01	Floor - 1 - Station Control Room - Station Building - Tooting Broadway Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden Floor					YES
12081	ACTIVE	N	N169-00-1/316	Locker Room - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15610	ACTIVE	N	N169-00-1/316	Locker Room - Station Building - Tooting Broadway Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Supalux; Foam Insulation Board					
15611	ACTIVE	N	N169-00-1/316/WAL-001	Wall: Internal - 1 - Locker Room - Station Building - Tooting Broadway Stn		Anthrax	Surveyed – Not Detected				No Anthrax Detected					
12082	ACTIVE	N	N169-00-1/331	Mess Room - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19951	ACTIVE	N	N169-00-1/331	Mess Room - Station Building - Tooting Broadway Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
15612	ACTIVE	N	N169-00-1/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Tooting Broadway Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Plasterboard Ceiling				YES	
12083	ACTIVE	N	N169-00-1/396	SVC - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12084	ACTIVE	N	N169-00-1/401	Bin Store - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12085	ACTIVE	N	N169-00-1/412	Store - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18350	ACTIVE	N	N169-00-1/412	Store - Station Building - Tooting Broadway Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing					
12086	ACTIVE	N	N169-00-1/416	Toilet: Unisex - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12087	ACTIVE	N	N169-00-1/417	Toilet: Unisex - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18351	ACTIVE	N	N169-00-1/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Tooting Broadway Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Plasterboard Ceiling				YES	



# Hazardous Material Asset Register - Summary



## N169-00 - Station Building - Tooting Broadway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12088	ACTIVE	N	N169-00-1/451	ATM - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12089	ACTIVE	N	N169-00-1/576	Fan Room - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15618	ACTIVE	N	N169-00-1/576	Fan Room - Station Building - Tooting Broadway Stn	Lead/Leading	Lead Paint/Lead	Known				Grey Oil Based Paint - Fan Thickness .08mm; Est Quantity 4sqm; Analysis 1.22%					
25677	ACTIVE	N	N169-00-1/576/CLG-01	Ceiling: Solid - 1 - Fan Room - Station Building - Tooting Broadway Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plaster Board					
25678	ACTIVE	N	N169-00-1/576/CLG-01	Ceiling: Solid - 1 - Fan Room - Station Building - Tooting Broadway Stn	Void	Asbestos	Sampled – Not Detected				Concrete above Plasterboard Ceiling. The filler between the concrete slab - NADIS					
15620	ACTIVE	N	N169-00-1/577	UMC Access - Station Building - Tooting Broadway Stn	Lead/Leading	Lead Paint/Lead	Known				Black Oil Based Paint - Stairs Thickness .12mm; Est Quantity 6 lm; Analysis 28.08%					
12090	ACTIVE	N	N169-00-1/661	Switch Room - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25851	ACTIVE	N	N169-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Tooting Broadway Stn	Rope Gaskets	Asbestos	Sampled – Not Detected				1 x Hessian Rope Gasket to floor of access cover. Red CFS - Asset no. 00136572		1		N	N
18352	ACTIVE	N	N169-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Tooting Broadway Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		2			
15621	ACTIVE	N	N169-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Tooting Broadway Stn	Isolator Switches	Asbestos	Strongly Presumed				Red Switch Box 30amp - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
12091	ACTIVE	N	N169-00-1/761	Service Riser - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12092	ACTIVE	N	N169-00-2/081	Passage - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12093	ACTIVE	N	N169-00-2/151	UMC - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15628	ACTIVE	N	N169-00-2/151	UMC - Station Building - Tooting Broadway Stn	Lead/Leading	Lead Paint/Lead	Known				Red Oil Based Paint - 2no Girder Housing Units Thickness .10mm; Est Quantity 6 lm; Analysis 46.55%		2			



# Hazardous Material Asset Register - Summary



## N169-00 - Station Building - Tooting Broadway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18353	ACTIVE	N	N169-00-2/151	UMC - Station Building - Tooting Broadway Stn	Lead/Leading	Lead Paint/Lead	Known				Red Oil Based Paint - Pipework Thickness .09mm; Est Quantity 20 lm; Analysis 4.21%					
15626	ACTIVE	N	N169-00-2/151/CLG-01	Ceiling: Suspended - 1 - UMC - Station Building - Tooting Broadway Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				To Ceiling					
15625	ACTIVE	N	N169-00-2/151/DOR-01	Door - 1 - UMC - Station Building - Tooting Broadway Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Boarding around Door					
15624	ACTIVE	N	N169-00-2/151/FLR-01	Floor - 1 - UMC - Station Building - Tooting Broadway Stn	Durasteel	Asbestos	Surveyed - Not Detected				Lid to Storage Bin					
25854	ACTIVE	N	N169-00-2/151/WAL-004	Wall: Internal - 4 - UMC - Station Building - Tooting Broadway Stn	Rope Gaskets	Asbestos	Sampled - Not Detected				1 x Hessian Rope Gasket to rear of access cover. Red Spot Fuse Board (new), Asset no.00136615, to wall 4 of UMC 1,2 & 3				N	N
15627	ACTIVE	N	N169-00-2/151/WAL-004	Wall: Internal - 4 - UMC - Station Building - Tooting Broadway Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
18717	ACTIVE	N	N169-00-2/171	Escalator Incline - Station Building - Tooting Broadway Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12094	ACTIVE	N	N169-00-2/236	Lobby - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15629	ACTIVE	N	N169-00-2/236	Lobby - Station Building - Tooting Broadway Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12095	ACTIVE	N	N169-00-2/237	Passage - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15630	ACTIVE	N	N169-00-2/237	Passage - Station Building - Tooting Broadway Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12096	ACTIVE	N	N169-00-2/411	Store - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15631	ACTIVE	N	N169-00-2/411	Store - Station Building - Tooting Broadway Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12097	ACTIVE	N	N169-00-2/551	Yard - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15632	ACTIVE	N	N169-00-2/551	Yard - Station Building - Tooting Broadway Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12098	ACTIVE	N	N169-00-2/552	Yard - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N169-00 - Station Building - Tooting Broadway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12099	ACTIVE	N	N169-00-2/661	Switch Room - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18418	ACTIVE	N	N169-00-2/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Tooting Broadway Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		3			
15633	ACTIVE	N	N169-00-2/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Tooting Broadway Stn	Isolator Switches	Asbestos	Strongly Presumed				Grey Switch Box 30amp - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
12100	ACTIVE	N	N169-00-2/662	Service Riser - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15634	ACTIVE	N	N169-00-2/662	Service Riser - Station Building - Tooting Broadway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12101	ACTIVE	N	N169-00-2/663	Switch Cupboard - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18718	ACTIVE	N	N169-00-2/663	Switch Cupboard - Station Building - Tooting Broadway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12102	ACTIVE	N	N169-00-2/731	CER - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18244	ACTIVE	N	N169-00-2/731/FLR-01	Floor - 1 - CER - Station Building - Tooting Broadway Stn	Void	Asbestos	Surveyed – Not Detected				Concrete & Metal Tray beneath Computer Flooring					YES
25852	ACTIVE	N	N169-00-2/731/WAL-004	Wall: Internal - 4 - CER - Station Building - Tooting Broadway Stn	Rope Gaskets	Asbestos	Sampled – Not Detected				1 x Hessian Rope Gasket to rear of access cover. Red CFS, Asset no. 00136627. NOTE – flash guards within are fibreglass non-ACM				N	N
25853	ACTIVE	N	N169-00-2/731/WAL-004	Wall: Internal - 4 - CER - Station Building - Tooting Broadway Stn	Rope Gaskets	Asbestos	Sampled – Not Detected				1 x Hessian Rope Gasket to rear of access cover. Red CFS Asset no. 00136628. NOTE – flash guards within are fibreglass, non-ACM.				N	N
15635	ACTIVE	N	N169-00-2/731/WAL-004	Wall: Internal - 4 - CER - Station Building - Tooting Broadway Stn	Isolator Switches	Asbestos	Strongly Presumed				2x Switch boxes 60amp No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.					
12103	ACTIVE	N	N169-00-2/746	SCR - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19948	ACTIVE	N	N169-00-2/746	SCR - Station Building - Tooting Broadway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N169-00 - Station Building - Tooting Broadway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12104	ACTIVE	N	N169-00-2/761	Computer Equipment Cupboard - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15636	ACTIVE	N	N169-00-2/761	Computer Equipment Cupboard - Station Building - Tooting Broadway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12105	ACTIVE	N	N169-00-2/762	Computer Equipment Cupboard - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18419	ACTIVE	N	N169-00-2/762	Computer Equipment Cupboard - Station Building - Tooting Broadway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12106	ACTIVE	N	N169-00-2/763	Computer Equipment Cupboard - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19344	ACTIVE	N	N169-00-2/763	Computer Equipment Cupboard - Station Building - Tooting Broadway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12107	ACTIVE	N	N169-00-2/764	Computer Equipment Cupboard - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15637	ACTIVE	N	N169-00-2/764	Computer Equipment Cupboard - Station Building - Tooting Broadway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12108	ACTIVE	N	N169-00-2/765	Computer Equipment Cupboard - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19952	ACTIVE	N	N169-00-2/765	Computer Equipment Cupboard - Station Building - Tooting Broadway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12109	ACTIVE	N	N169-00-2/766	Computer Equipment Cupboard - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18420	ACTIVE	N	N169-00-2/766	Computer Equipment Cupboard - Station Building - Tooting Broadway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12110	ACTIVE	N	N169-00-2/776	Fan Room - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15638	ACTIVE	N	N169-00-2/776	Fan Room - Station Building - Tooting Broadway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12111	ACTIVE	N	N169-00-2/781	TXR - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N169-00 - Station Building - Tooting Broadway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15639	ACTIVE	N	N169-00-2/781	TXR - Station Building - Tooting Broadway Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
12112	ACTIVE	N	N169-00-2/782	TXR - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18421	ACTIVE	N	N169-00-2/782	TXR - Station Building - Tooting Broadway Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
15640	ACTIVE	N	N169-00-2/791	Vent Shaft - Station Building - Tooting Broadway Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12113	ACTIVE	N	N169-00-2/901	SER - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15641	ACTIVE	N	N169-00-2/901	SER - Station Building - Tooting Broadway Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12114	ACTIVE	N	N169-00-3/071	Circulation Area - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15642	ACTIVE	N	N169-00-3/071	Circulation Area - Station Building - Tooting Broadway Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12115	ACTIVE	N	N169-00-3/161	LMC - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18719	ACTIVE	N	N169-00-3/161	LMC - Station Building - Tooting Broadway Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
18422	ACTIVE	N	N169-00-3/161	LMC - Station Building - Tooting Broadway Stn	Lead/Leading	Lead Paint/Lead	Known				Grey Oil Based Paint - Girder Thickness .31mm; Est Quantity 4 lm; Analysis 21.13%					
12116	ACTIVE	N	N169-00-3/201	Passage - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15643	ACTIVE	N	N169-00-3/201	Passage - Station Building - Tooting Broadway Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12117	ACTIVE	N	N169-00-3/202	Passage - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15644	ACTIVE	N	N169-00-3/202	Passage - Station Building - Tooting Broadway Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12118	ACTIVE	N	N169-00-3/203	Passage - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15645	ACTIVE	N	N169-00-3/203	Passage - Station Building - Tooting Broadway Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N169-00 - Station Building - Tooting Broadway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12119	ACTIVE	N	N169-00-3/204	Passage - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15646	ACTIVE	N	N169-00-3/204	Passage - Station Building - Tooting Broadway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12120	ACTIVE	N	N169-00-3/205	Passage - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18423	ACTIVE	N	N169-00-3/205	Passage - Station Building - Tooting Broadway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12121	ACTIVE	N	N169-00-3/206	Passage - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15647	ACTIVE	N	N169-00-3/206	Passage - Station Building - Tooting Broadway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12122	ACTIVE	N	N169-00-3/207	Passage - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15648	ACTIVE	N	N169-00-3/207	Passage - Station Building - Tooting Broadway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12123	ACTIVE	N	N169-00-3/261	Platform 1 - Northbound Local - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15649	ACTIVE	N	N169-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Tooting Broadway Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - Various Cables No access 2020 re-inspection as confined space team required					YES
12124	ACTIVE	N	N169-00-3/262	Platform 2 - Southbound Local - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18424	ACTIVE	N	N169-00-3/262	Platform 2 - Southbound Local - Station Building - Tooting Broadway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12125	ACTIVE	N	N169-00-3/661	Service Riser - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15650	ACTIVE	N	N169-00-3/661	Service Riser - Station Building - Tooting Broadway Stn	Cable: Sheath	Asbestos	Strongly Presumed				1x15mm going to invert 3/661					
12126	ACTIVE	N	N169-00-3/662	Store - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15651	ACTIVE	N	N169-00-3/662	Store - Station Building - Tooting Broadway Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board around door					



# Hazardous Material Asset Register - Summary



## N169-00 - Station Building - Tooting Broadway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12127	ACTIVE	N	N169-00-3/663	Switch Room - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18425	ACTIVE	N	N169-00-3/663	Switch Room - Station Building - Tooting Broadway Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board around door					
12128	ACTIVE	N	N169-00-3/664	Switch Room - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15652	ACTIVE	N	N169-00-3/664	Switch Room - Station Building - Tooting Broadway Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12129	ACTIVE	N	N169-00-3/665	Switch Room - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15653	ACTIVE	N	N169-00-3/665	Switch Room - Station Building - Tooting Broadway Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux & Plasterboard boarding					
12130	ACTIVE	N	N169-00-3/666	Switch Room - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15654	ACTIVE	N	N169-00-3/666	Switch Room - Station Building - Tooting Broadway Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux & Plasterboard boarding					
12131	ACTIVE	N	N169-00-3/667	Switch Cupboard - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18426	ACTIVE	N	N169-00-3/667	Switch Cupboard - Station Building - Tooting Broadway Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux & Plasterboard boarding					
12132	ACTIVE	N	N169-00-3/668	Switch Cupboard - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18662	ACTIVE	N	N169-00-3/668	Switch Cupboard - Station Building - Tooting Broadway Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux & Plasterboard boarding					
12133	ACTIVE	N	N169-00-3/669	Switch Cupboard - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18720	ACTIVE	N	N169-00-3/669	Switch Cupboard - Station Building - Tooting Broadway Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux & Plasterboard boarding					
12134	ACTIVE	N	N169-00-3/706	Lobby - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15655	ACTIVE	N	N169-00-3/706	Lobby - Station Building - Tooting Broadway Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding under Sink					
12135	ACTIVE	N	N169-00-3/707	IMR - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N169-00 - Station Building - Tooting Broadway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15656	ACTIVE	N	N169-00-3/707/WAL-002	Wall: Internal - 2 - IMR - Station Building - Tooting Broadway Stn	Other Boarding	Asbestos	Presumed				Paxoline Boarding above door					
12136	ACTIVE	N	N169-00-3/708	IMR - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Surveyed – Asbestos Known									
53659	ACTIVE	N	N169-00-3/708	IMR - Station Building - Tooting Broadway Stn	Other Boarding	Asbestos	Presumed				Middle of room 3x composite board to Rack next to point control middle of room 1 x board to rack 4 in middle of room					
15662	ACTIVE	N	N169-00-3/708	IMR - Station Building - Tooting Broadway Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Paxoline Boarding x 2 to wall 1 to equipment - new board					
53657	ACTIVE	N	N169-00-3/708	IMR - Station Building - Tooting Broadway Stn	Other Boarding	Asbestos	Presumed				Rack to middle of room 5 x composite brown board to first rack					
53658	ACTIVE	N	N169-00-3/708	IMR - Station Building - Tooting Broadway Stn	Bakerlite	Asbestos	Presumed				presumed Bakerlite telephone to middle of room					
15660	ACTIVE	N	N169-00-3/708	IMR - Station Building - Tooting Broadway Stn	Cable: Sheath	Asbestos	Strongly Presumed				15mm Cables from 3/708 to 3/710- various 2x white asbestos cables 2m approx from wall 1-3 Bay number 3-2 (1x cable running onto wall 2) (1x cable running in j hanger)		2			
18245	ACTIVE	N	N169-00-3/708/CLG-01	Ceiling: Solid - 1 - IMR - Station Building - Tooting Broadway Stn	Vinyl tiles	Asbestos	Known				Marley Tiles - Chrysotile Some tiles loose to wall & on floor					
15657	ACTIVE	N	N169-00-3/708/WAL-001	Wall: Internal - 1 - IMR - Station Building - Tooting Broadway Stn	Vinyl tiles	Asbestos	Known				Marley Tiles - Chrysotile Some tiles loose to wall n floor					
15661	ACTIVE	N	N169-00-3/708/WAL-001	Wall: Internal - 1 - IMR - Station Building - Tooting Broadway Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
53656	ACTIVE	N	N169-00-3/708/WAL-001	Wall: Internal - 1 - IMR - Station Building - Tooting Broadway Stn	Other Boarding	Asbestos	Presumed				9 x brown board to bay 12 wall 1					
18721	INACTIVE	N	N169-00-3/708/WAL-001	Wall: Internal - 1 - IMR - Station Building - Tooting Broadway Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				PCB - Good Condition - Cylindrical, Blue - mounted on Paxoline board Re Inspected 14/04/2015		4			
18427	ACTIVE	N	N169-00-3/708/WAL-002	Wall: Internal - 2 - IMR - Station Building - Tooting Broadway Stn	Vinyl tiles	Asbestos	Known				Tiles - Chrysotile Tiles loose to wall and floor					
15663	ACTIVE	N	N169-00-3/708/WAL-003	Wall: Internal - 3 - IMR - Station Building - Tooting Broadway Stn	Other Boarding	Asbestos	Presumed				2 x paxoline board 1x large Board 1x small board to rack wall 3					
15658	ACTIVE	N	N169-00-3/708/WAL-003	Wall: Internal - 3 - IMR - Station Building - Tooting Broadway Stn	Vinyl tiles	Asbestos	Known				Tiles - Chrysotile Tiles loose to wall and floor					
15659	ACTIVE	N	N169-00-3/708/WAL-004	Wall: Internal - 4 - IMR - Station Building - Tooting Broadway Stn	Vinyl tiles	Asbestos	Known				Tiles - Chrysotile Some tiles loose to wall and floor					



# Hazardous Material Asset Register - Summary



## N169-00 - Station Building - Tooting Broadway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18428	INACTIVE	N	N169-00-3/708/WAL-004	Wall: Internal - 4 - IMR - Station Building - Tooting Broadway Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				PCB - Good Condition - Cylindrical, Blue - wall mounted on Paxoline board still present on 2022 reinspection		2			
12137	ACTIVE	N	N169-00-3/709	IMR - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
42323	INACTIVE	N	N169-00-3/709	IMR - Station Building - Tooting Broadway Stn	PCBs	Polychlorinated biphenyl	Presumed				2 x small cylindrical PCB's wall mounted on paxoline board Fair Condition		2		N	N
15664	ACTIVE	N	N169-00-3/709/WAL-001	Wall: Internal - 1 - IMR - Station Building - Tooting Broadway Stn	Other Boarding	Asbestos	Presumed				Paxoline Boarding throughout Missing 1x presumed composite panel photo DSC05758					
18429	ACTIVE	N	N169-00-3/709/WAL-001	Wall: Internal - 1 - IMR - Station Building - Tooting Broadway Stn	Isolator Switches	Asbestos	Strongly Presumed				Grey Switch Box 100amp - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
15666	ACTIVE	N	N169-00-3/709/WAL-001	Wall: Internal - 1 - IMR - Station Building - Tooting Broadway Stn	Cable: Sheath	Asbestos	Strongly Presumed				15mm Cables from 3/708 to 3/710		2			
15668	ACTIVE	N	N169-00-3/709/WAL-002	Wall: Internal - 2 - IMR - Station Building - Tooting Broadway Stn	Other Electrical Boxes	Asbestos	Presumed				AC Fuse Box 100amps No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
15665	ACTIVE	N	N169-00-3/709/WAL-002	Wall: Internal - 2 - IMR - Station Building - Tooting Broadway Stn	Other Boarding	Asbestos	Presumed				Paxoline Boarding throughout					
15669	INACTIVE	N	N169-00-3/709/WAL-002	Wall: Internal - 2 - IMR - Station Building - Tooting Broadway Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				6 x blue cylindrical PCB's Re inspected 14/04/2015 Fair Condition		6			
15667	ACTIVE	N	N169-00-3/709/WAL-004	Wall: Internal - 4 - IMR - Station Building - Tooting Broadway Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		3			
12138	ACTIVE	N	N169-00-3/710	IMR - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
44316	ACTIVE	N	N169-00-3/710	IMR - Station Building - Tooting Broadway Stn	Other Boarding	Asbestos	Presumed				Paxoline board boxes					
18430	ACTIVE	N	N169-00-3/710	IMR - Station Building - Tooting Broadway Stn	Caulking	Asbestos	Presumed				Caulking Solid					
15670	ACTIVE	N	N169-00-3/710	IMR - Station Building - Tooting Broadway Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Electrical Equipment - Insulation within throughout Room No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.					



# Hazardous Material Asset Register - Summary



## N169-00 - Station Building - Tooting Broadway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18431	ACTIVE	N	N169-00-3/710/WAL-001	Wall: Internal - 1 - IMR - Station Building - Tooting Broadway Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse Box No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		2			
15671	ACTIVE	N	N169-00-3/710/WAL-001	Wall: Internal - 1 - IMR - Station Building - Tooting Broadway Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Transformer Box(es) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
15673	ACTIVE	N	N169-00-3/710/WAL-002	Wall: Internal - 2 - IMR - Station Building - Tooting Broadway Stn	Cable: Sheath	Asbestos	Strongly Presumed				5mm Cables		2			
15674	INACTIVE	N	N169-00-3/710/WAL-003	Wall: Internal - 3 - IMR - Station Building - Tooting Broadway Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				3 x PCB Cylindrical, blue, mounted on metal panel Re inspected 14/04/2015 Fair Condition		3			
15672	ACTIVE	N	N169-00-3/710/WAL-004	Wall: Internal - 4 - IMR - Station Building - Tooting Broadway Stn	Cable: Sheath	Asbestos	Strongly Presumed				15mm Cables from 3/708 to 3/710		2			
12139	ACTIVE	N	N169-00-3/711	Relay Room - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44315	ACTIVE	N	N169-00-3/711	Relay Room - Station Building - Tooting Broadway Stn	Other Boarding	Asbestos	Presumed				Paxoline boarding wall 2 behind glass box					
15680	ACTIVE	N	N169-00-3/711/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - Tooting Broadway Stn	Vinyl tiles	Asbestos	Known				Tiles - Chrysotile White Tiles on Ceiling remain Some tiles loose					
18246	ACTIVE	N	N169-00-3/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tooting Broadway Stn	Vinyl tiles	Asbestos	Known				Tiles - Chrysotile - Green behind Equipment most removed some remain to wall 1					
15682	ACTIVE	N	N169-00-3/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tooting Broadway Stn	Boarding: Cement	Asbestos	Strongly Presumed				Cement panel to racking on wall 1 x2 top and bottom rack		3			
15681	ACTIVE	N	N169-00-3/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tooting Broadway Stn	Cable: Sheath	Asbestos	Strongly Presumed				Asbestos cable Wall 1 coming out of duct and running to trackside wall 2		1			
19953	ACTIVE	N	N169-00-3/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tooting Broadway Stn	Westing house Boxes	Asbestos	Strongly Presumed				W1 Westinghouse Box - Insulation within. Asbestos Cable going into box No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
53654	ACTIVE	N	N169-00-3/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tooting Broadway Stn	Other Boarding	Asbestos	Presumed				1 x brown board to top shelf of rack to wall 1					



# Hazardous Material Asset Register - Summary



## N169-00 - Station Building - Tooting Broadway Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18433	INACTIVE	N	N169-00-3/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tooting Broadway Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Small Transformer Box - Insulation within  No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
53653	ACTIVE	N	N169-00-3/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tooting Broadway Stn	Other Boarding	Asbestos	Presumed				6 x black composite board to top shelf of rack on wall 1					
15683	INACTIVE	N	N169-00-3/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Tooting Broadway Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				PCB's - Fair Condition Serial Nos. 197476; 197490; 197461; 197492; 197472; 197477, 197487; 197488. Re inspected 14/04/2015 Fair Condition		7			
53655	ACTIVE	N	N169-00-3/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Tooting Broadway Stn	Cable: Sheath	Asbestos	Presumed				thin white cable from 600v electrical box wall 2					
18432	INACTIVE	N	N169-00-3/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Tooting Broadway Stn	Vinyl tiles	Asbestos	Known				Tiles - Chrysotile - Green behind Equipment remain  Duplicate entry					
15677	INACTIVE	N	N169-00-3/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Tooting Broadway Stn	Vinyl tiles	Asbestos	Known				Tiles - Chrysotile - Green behind Equipment remain  Duplicate entry					
15679	ACTIVE	N	N169-00-3/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Tooting Broadway Stn	Vinyl tiles	Asbestos	Known				Marley Tiles - Chrysotile - Green - most removed some remain behind Equipment to wall 2-3					
15678	INACTIVE	N	N169-00-3/711/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - Tooting Broadway Stn	Vinyl tiles	Asbestos	Known				Tiles - Chrysotile - Green behind Equipment remain  Duplicate entry					
12140	ACTIVE	N	N169-00-3/956	Disused Room - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15675	ACTIVE	N	N169-00-3/956	Disused Room - Station Building - Tooting Broadway Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12141	ACTIVE	N	N169-00-A/481	Equipment Room - Station Building - Tooting Broadway Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15676	ACTIVE	N	N169-00-A/481	Equipment Room - Station Building - Tooting Broadway Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					

## N173-00 - Station Building - Colliers Wood Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12142	ACTIVE	N	N173-00-1/001	Booking Hall - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N173-00 - Station Building - Colliers Wood Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15453	ACTIVE	N	N173-00-1/001	Booking Hall - Station Building - Colliers Wood Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12143	ACTIVE	N	N173-00-1/011	Ticket Office - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15454	ACTIVE	N	N173-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Colliers Wood Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18186	ACTIVE	N	N173-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Colliers Wood Stn	Void	Asbestos	No Access: Presumed				AboveSupalux Tiles					
42243	ACTIVE	N	N173-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Colliers Wood Stn	Debris: Other	Asbestos	Sampled – Not Detected				Dust - 1m <sup>2</sup> under false floor, Floor tiles, under false floor, Dust & debris under false	1			N	Y
18639	ACTIVE	N	N173-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Colliers Wood Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Tiles					YES
42242	ACTIVE	N	N173-00-1/011/WAL-002	Wall: Internal - 2 - Ticket Office - Station Building - Colliers Wood Stn	Other Boarding	Asbestos	Sampled – Not Detected				Insulation panel, 1m to loose panel in timber cupboard to bottom of wall 2. Insulation panel 1m, to timber box no 3 to wall 2	1			N	N
12144	ACTIVE	N	N173-00-1/021	POM - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15456	ACTIVE	N	N173-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Colliers Wood Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
15457	ACTIVE	N	N173-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Colliers Wood Stn	Void	Asbestos	No Access: Presumed				AboveSupalux Tiles					
15455	ACTIVE	N	N173-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Colliers Wood Stn	Void	Asbestos	No Access: Presumed				Beneath Computer Tiles					YES
12145	ACTIVE	N	N173-00-1/031	Mess Room - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18187	ACTIVE	N	N173-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Colliers Wood Stn	Void	Asbestos	No Access: Presumed				AboveSupalux Tiles					
15458	ACTIVE	N	N173-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Colliers Wood Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
12146	ACTIVE	N	N173-00-1/036	Toilet: Unisex - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N173-00 - Station Building - Colliers Wood Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15460	ACTIVE	N	N173-00-1/036/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Colliers Wood Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles					
15459	ACTIVE	N	N173-00-1/036/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Colliers Wood Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
12147	ACTIVE	N	N173-00-1/071	Circulation Area - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15461	ACTIVE	N	N173-00-1/071	Circulation Area - Station Building - Colliers Wood Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12148	ACTIVE	N	N173-00-1/081	Lobby - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15462	ACTIVE	N	N173-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Colliers Wood Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
18640	ACTIVE	N	N173-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Colliers Wood Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles					
12149	ACTIVE	N	N173-00-1/151	UMC - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18188	ACTIVE	N	N173-00-1/151	UMC - Station Building - Colliers Wood Stn	Durasteel	Asbestos	Surveyed – Not Detected				Lid to Storage Bin					
44979	ACTIVE	N	N173-00-1/151	UMC - Station Building - Colliers Wood Stn	Caulking	Asbestos	Presumed				Tunnel ring caulking to tunnel ring joints				N	N
15464	ACTIVE	N	N173-00-1/151	UMC - Station Building - Colliers Wood Stn	Lead/Leading	Lead Paint/Lead	Known				White Gloss - Column Thickness: 0.26mm. Analysis 3%					
15463	ACTIVE	N	N173-00-1/151	UMC - Station Building - Colliers Wood Stn	Lead/Leading	Lead Paint/Lead	Known				White Gloss - Column Thickness: 0.24mm. Analysis 1.1%					
15465	ACTIVE	N	N173-00-1/151	UMC - Station Building - Colliers Wood Stn	Lead/Leading	Lead Paint/Lead	Known				Blue Gloss - Column Thickness: 0.29mm. Analysis 8.9%					
44980	ACTIVE	N	N173-00-1/151/WAL-004	Wall: Internal - 4 - UMC - Station Building - Colliers Wood Stn	Other Electrical Boxes	Asbestos	Presumed				3x combination fuse switches		3		N	N
12150	ACTIVE	N	N173-00-1/236	Lobby - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18189	ACTIVE	N	N173-00-1/236	Lobby - Station Building - Colliers Wood Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N173-00 - Station Building - Colliers Wood Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12151	ACTIVE	N	N173-00-1/237	Lobby - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15466	ACTIVE	N	N173-00-1/237	Lobby - Station Building - Colliers Wood Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12152	ACTIVE	N	N173-00-1/239	Lobby - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15467	ACTIVE	N	N173-00-1/239	Lobby - Station Building - Colliers Wood Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12153	ACTIVE	N	N173-00-1/281	Lobby - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15468	ACTIVE	N	N173-00-1/281/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Colliers Wood Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
18190	ACTIVE	N	N173-00-1/281/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Colliers Wood Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles					
12154	ACTIVE	N	N173-00-1/316	Locker Room - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15469	ACTIVE	N	N173-00-1/316	Locker Room - Station Building - Colliers Wood Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12155	ACTIVE	N	N173-00-1/396	SVC - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18653	ACTIVE	N	N173-00-1/396	SVC - Station Building - Colliers Wood Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12156	ACTIVE	N	N173-00-1/406	Store - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15470	ACTIVE	N	N173-00-1/406	Store - Station Building - Colliers Wood Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
12157	ACTIVE	N	N173-00-1/411	Store - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19299	ACTIVE	N	N173-00-1/411/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Colliers Wood Stn	Void	Asbestos	Surveyed - Not Detected				Corrugated Material - Non Asbestos above Plasterboard Ceiling				YES	
12158	ACTIVE	N	N173-00-1/417	Toilet: Unisex - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N173-00 - Station Building - Colliers Wood Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18336	ACTIVE	N	N173-00-1/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Colliers Wood Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles					
18641	ACTIVE	N	N173-00-1/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Colliers Wood Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
12159	ACTIVE	N	N173-00-1/551	Yard - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15565	ACTIVE	N	N173-00-1/551	Yard - Station Building - Colliers Wood Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12160	ACTIVE	N	N173-00-1/666	Switch Cupboard - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15566	ACTIVE	N	N173-00-1/666	Switch Cupboard - Station Building - Colliers Wood Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12161	ACTIVE	N	N173-00-1/667	Switch Room - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15567	ACTIVE	N	N173-00-1/667	Switch Room - Station Building - Colliers Wood Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12162	ACTIVE	N	N173-00-1/714	Station Control Room - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
12163	ACTIVE	N	N173-00-1/731	Store - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15568	ACTIVE	N	N173-00-1/731	Store - Station Building - Colliers Wood Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12164	ACTIVE	N	N173-00-1/732	Equipment Room - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15569	ACTIVE	N	N173-00-1/732	Equipment Room - Station Building - Colliers Wood Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
19947	ACTIVE	N	N173-00-1/751	Station Control Room - Station Building - Colliers Wood Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12165	ACTIVE	N	N173-00-1/761	Void - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18337	ACTIVE	N	N173-00-1/761	Void - Station Building - Colliers Wood Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N173-00 - Station Building - Colliers Wood Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12166	ACTIVE	N	N173-00-2/081	Circulation Area - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15570	ACTIVE	N	N173-00-2/081	Circulation Area - Station Building - Colliers Wood Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12167	ACTIVE	N	N173-00-2/161	LMC - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18338	ACTIVE	N	N173-00-2/161	LMC - Station Building - Colliers Wood Stn	Cable: Sheath	Asbestos	Surveyed – Not Detected				Braided Cables 50cm x 0.5cm diameter from redundant equipment		2			
15571	ACTIVE	N	N173-00-2/161	LMC - Station Building - Colliers Wood Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables - Chrysotile		3			
12168	ACTIVE	N	N173-00-2/201	Passage - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15572	ACTIVE	N	N173-00-2/201	Passage - Station Building - Colliers Wood Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12169	ACTIVE	N	N173-00-2/202	Passage - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15573	ACTIVE	N	N173-00-2/202	Passage - Station Building - Colliers Wood Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12170	ACTIVE	N	N173-00-2/203	Passage - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18712	ACTIVE	N	N173-00-2/203	Passage - Station Building - Colliers Wood Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12171	ACTIVE	N	N173-00-2/204	Passage - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15574	ACTIVE	N	N173-00-2/204	Passage - Station Building - Colliers Wood Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12172	ACTIVE	N	N173-00-2/205	Passage - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15575	ACTIVE	N	N173-00-2/205	Passage - Station Building - Colliers Wood Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12173	ACTIVE	N	N173-00-2/261	Platform 1 - Northbound Local - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18339	ACTIVE	N	N173-00-2/261	Platform 1 - Northbound Local - Station Building - Colliers Wood Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables from Invert out of Vent Duct		4			



# Hazardous Material Asset Register - Summary



## N173-00 - Station Building - Colliers Wood Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15576	ACTIVE	N	N173-00-2/261	Platform 1 - Northbound Local - Station Building - Colliers Wood Stn	Other Boarding	Asbestos	Strongly Presumed				Material behind sign outside 2/711					
15577	ACTIVE	N	N173-00-2/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Colliers Wood Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform Invert - 1m of cable wrap slight damage To cable at arrival side & 1m To cable at departure end - Chrysotile Asbestos		3			YES
12174	ACTIVE	N	N173-00-2/262	Platform 2 - Southbound Local - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15578	ACTIVE	N	N173-00-2/262	Platform 2 - Southbound Local - Station Building - Colliers Wood Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board behind termination point box					
18713	ACTIVE	N	N173-00-2/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Colliers Wood Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Platform 2 Invert - Braided Cable Sleeves					YES
15579	ACTIVE	N	N173-00-2/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Colliers Wood Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - Braided Cable					YES
12175	ACTIVE	N	N173-00-2/661	Lobby - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18340	ACTIVE	N	N173-00-2/661	Lobby - Station Building - Colliers Wood Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12176	ACTIVE	N	N173-00-2/662	Toilet - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12177	ACTIVE	N	N173-00-2/663	Disused Room - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15580	ACTIVE	N	N173-00-2/663	Disused Room - Station Building - Colliers Wood Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12178	ACTIVE	N	N173-00-2/664	Switch Room - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15581	ACTIVE	N	N173-00-2/664	Switch Room - Station Building - Colliers Wood Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12179	ACTIVE	N	N173-00-2/665	Switch Cupboard - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18659	ACTIVE	N	N173-00-2/665	Switch Cupboard - Station Building - Colliers Wood Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12180	ACTIVE	N	N173-00-2/666	Switch Cupboard - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N173-00 - Station Building - Colliers Wood Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15582	ACTIVE	N	N173-00-2/666	Switch Cupboard - Station Building - Colliers Wood Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12181	ACTIVE	N	N173-00-2/667	Switch Cupboard - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18341	ACTIVE	N	N173-00-2/667	Switch Cupboard - Station Building - Colliers Wood Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12182	ACTIVE	N	N173-00-2/668	Switch Cupboard - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15583	ACTIVE	N	N173-00-2/668	Switch Cupboard - Station Building - Colliers Wood Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12183	ACTIVE	N	N173-00-2/711	Relay Room - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15585	ACTIVE	N	N173-00-2/711	Relay Room - Station Building - Colliers Wood Stn	Cable: Sheath	Asbestos	Strongly Presumed				4 x Cables		4			
18342	INACTIVE	N	N173-00-2/711/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - Colliers Wood Stn	Vinyl tiles	Asbestos	Strongly Presumed				Grey & Green Vinyl Tiles Duplicate with 15584					
15586	ACTIVE	N	N173-00-2/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Colliers Wood Stn	Other Boarding	Asbestos	Presumed				Panel under PCB's					
15584	ACTIVE	N	N173-00-2/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Colliers Wood Stn	Vinyl tiles	Asbestos	Strongly Presumed				Grey & Green Vinyl Tiles on all walls					
15587	INACTIVE	N	N173-00-2/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Colliers Wood Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				6 x PCB's - Fair Condition Serial Nos. 186453; 186425; 186458; 186434; 186513; 197465 Inspected 14/04/2015		6			
19480	ACTIVE	N	N173-00-2/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Colliers Wood Stn	Westing house Boxes	Asbestos	Strongly Presumed				Insulation within 1x Westinghouse Box					
12184	ACTIVE	N	N173-00-2/712	Relay Room - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15588	ACTIVE	N	N173-00-2/712/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - Colliers Wood Stn	Vinyl tiles	Asbestos	Strongly Presumed				Grey & Brown Vinyl Tiles					
15592	ACTIVE	N	N173-00-2/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Colliers Wood Stn	Boarding: Cement	Asbestos	Presumed				2 x Panel under PCB's		2			
15591	ACTIVE	N	N173-00-2/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Colliers Wood Stn	Westing house Boxes	Asbestos	Strongly Presumed				Insulation within Westinghouse Box		1			



# Hazardous Material Asset Register - Summary



## N173-00 - Station Building - Colliers Wood Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18344	ACTIVE	N	N173-00-2/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Colliers Wood Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Transformer Box(es)		1			
18714	ACTIVE	N	N173-00-2/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Colliers Wood Stn	Vinyl tiles	Asbestos	Strongly Presumed				Grey & Brown Vinyl Tiles					
15600	INACTIVE	N	N173-00-2/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Colliers Wood Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				7 x PCB's - Fair Condition Serial Nos. 186434, 186435; 186610; 186452; 186484; 186432; 186503, 186494 Inspected 14/04/2015		7			
18343	ACTIVE	N	N173-00-2/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Colliers Wood Stn	Cable: Sheath	Asbestos	Known				Cables - Chrysotile		5			
15589	ACTIVE	N	N173-00-2/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Colliers Wood Stn	Other Boarding	Asbestos	Presumed				Small Boarding High Level					
15590	ACTIVE	N	N173-00-2/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Colliers Wood Stn	Other Boarding	Asbestos	Presumed				Small Boarding High Level					
12185	ACTIVE	N	N173-00-2/731	SER - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15593	ACTIVE	N	N173-00-2/731	SER - Station Building - Colliers Wood Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12186	ACTIVE	N	N173-00-2/901	Disused Room - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15594	ACTIVE	N	N173-00-2/901	Disused Room - Station Building - Colliers Wood Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12187	ACTIVE	N	N173-00-2/951	Disused Room - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15595	ACTIVE	N	N173-00-2/951	Disused Room - Station Building - Colliers Wood Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12188	ACTIVE	N	N173-00-A/236	Passage - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15596	ACTIVE	N	N173-00-A/236	Passage - Station Building - Colliers Wood Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12189	ACTIVE	N	N173-00-A/576	Stairs: Linear - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18660	ACTIVE	N	N173-00-A/576	Stairs: Linear - Station Building - Colliers Wood Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N173-00 - Station Building - Colliers Wood Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12190	ACTIVE	N	N173-00-A/731	CER - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18345	ACTIVE	N	N173-00-A/731	CER - Station Building - Colliers Wood Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12191	ACTIVE	N	N173-00-A/732	CER - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18715	ACTIVE	N	N173-00-A/732	CER - Station Building - Colliers Wood Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12192	ACTIVE	N	N173-00-A/761	Void - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15597	ACTIVE	N	N173-00-A/761	Void - Station Building - Colliers Wood Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12193	ACTIVE	N	N173-00-B/576	Stairs: Linear - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15598	ACTIVE	N	N173-00-B/576	Stairs: Linear - Station Building - Colliers Wood Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12194	ACTIVE	N	N173-00-B/661	Void - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15599	ACTIVE	N	N173-00-B/661	Void - Station Building - Colliers Wood Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12195	ACTIVE	N	N173-00-B/746	SCR - Station Building - Colliers Wood Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18346	ACTIVE	N	N173-00-B/746	SCR - Station Building - Colliers Wood Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
15452	ACTIVE	N	N173-00/ROF-01	Structure: Roof - 1 - Station Building - Colliers Wood Stn	Cement Cowlings/ Flues	Asbestos	No Access: Presumed				Cement Flue					

## N175-00 - Station Building - South Wimbledon Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12196	ACTIVE	N	N175-00-1/001	Booking Hall - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
44981	ACTIVE	N	N175-00-1/001	Booking Hall - Station Building - South Wimbledon Stn	Glazing Rope	Asbestos	Presumed				Glazing rope to high level entrance throughout				N	N



# Hazardous Material Asset Register - Summary



## N175-00 - Station Building - South Wimbledon Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19298	INACTIVE	N	N175-00-1/001	Booking Hall - Station Building - South Wimbledon Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible - Relates to 3-5 Morden Road					
12197	ACTIVE	N	N175-00-1/011	Ticket Office - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15398	ACTIVE	N	N175-00-1/011	Ticket Office - Station Building - South Wimbledon Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12198	ACTIVE	N	N175-00-1/021	POM - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15399	ACTIVE	N	N175-00-1/021	POM - Station Building - South Wimbledon Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Foam Backing Non-Asbestos					
12199	ACTIVE	N	N175-00-1/036	Toilet: Unisex - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15400	ACTIVE	N	N175-00-1/036	Toilet: Unisex - Station Building - South Wimbledon Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12200	ACTIVE	N	N175-00-1/071	Circulation Area - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18635	ACTIVE	N	N175-00-1/071	Circulation Area - Station Building - South Wimbledon Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
44982	ACTIVE	N	N175-00-1/071	Circulation Area - Station Building - South Wimbledon Stn	Glazing Rope	Asbestos	Presumed				Glazing rope to skylight				N	N
12201	ACTIVE	N	N175-00-1/151	UMC - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44985	ACTIVE	N	N175-00-1/151	UMC - Station Building - South Wimbledon Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Ducts with cement infill				N	N
15404	ACTIVE	N	N175-00-1/151	UMC - Station Building - South Wimbledon Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer far LHS corner		1			
15402	ACTIVE	N	N175-00-1/151	UMC - Station Building - South Wimbledon Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Vermiculite Cladding to Girders					
44984	ACTIVE	N	N175-00-1/151	UMC - Station Building - South Wimbledon Stn		Asbestos	Presumed				1x Flash guard - transformer far LHS corner		1		N	N
18173	ACTIVE	N	N175-00-1/151	UMC - Station Building - South Wimbledon Stn	Gasket :Pipework	Asbestos	Strongly Presumed				Gaskets on Fire Main and Ventilation Equipment					
18636	ACTIVE	N	N175-00-1/151	UMC - Station Building - South Wimbledon Stn	Lead/Leading	Lead Paint/Lead	Known				Black Gloss on Column. Thickness: 0.26mm Analysis 1.2%					



# Hazardous Material Asset Register - Summary



## N175-00 - Station Building - South Wimbledon Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41805	INACTIVE	N	N175-00-1/151	UMC - Station Building - South Wimbledon Stn	Lead/Leading	Lead Paint/Lead	Sampled – Not Detected				Cream Walls Lead by weight 0.08%				N	N
15405	ACTIVE	N	N175-00-1/151	UMC - Station Building - South Wimbledon Stn	Lead/Leading	Lead Paint/Lead	No Access: Presumed				Green Gloss on Columns under Escalator. Thickness: 0.19mm Analysis 6.1%					
18172	ACTIVE	N	N175-00-1/151/CLG-01	Ceiling: Solid - 1 - UMC - Station Building - South Wimbledon Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux near Stairs					
15401	ACTIVE	N	N175-00-1/151/FLR-01	Floor - 1 - UMC - Station Building - South Wimbledon Stn	Durasteel	Asbestos	Surveyed – Not Detected				Lid to Storage Bin					
15403	ACTIVE	N	N175-00-1/151/WAL-004	Wall: Internal - 4 - UMC - Station Building - South Wimbledon Stn	Isolator Switches	Asbestos	Known				9 x Switch Boxes - Insulation within					
12202	ACTIVE	N	N175-00-1/236	Lobby - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15406	ACTIVE	N	N175-00-1/236	Lobby - Station Building - South Wimbledon Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12203	ACTIVE	N	N175-00-1/237	Passage - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15407	ACTIVE	N	N175-00-1/237	Passage - Station Building - South Wimbledon Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12204	ACTIVE	N	N175-00-1/311	Locker Room - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15408	ACTIVE	N	N175-00-1/311/WAL-005	Wall: Internal - 5 - Locker Room - Station Building - South Wimbledon Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Foam backing - Non asbestos					
12205	ACTIVE	N	N175-00-1/316	SCR - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18174	ACTIVE	N	N175-00-1/316	SCR - Station Building - South Wimbledon Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12206	ACTIVE	N	N175-00-1/331	Locker Room - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15409	ACTIVE	N	N175-00-1/331	Locker Room - Station Building - South Wimbledon Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12207	ACTIVE	N	N175-00-1/396	SVC - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15410	ACTIVE	N	N175-00-1/396	SVC - Station Building - South Wimbledon Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N175-00 - Station Building - South Wimbledon Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12208	ACTIVE	N	N175-00-1/406	Switch Room - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18175	ACTIVE	N	N175-00-1/406/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - South Wimbledon Stn	Void	Asbestos	No Access: Presumed				Above Supalux Panels					
18650	ACTIVE	N	N175-00-1/406/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - South Wimbledon Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels					
44983	ACTIVE	N	N175-00-1/406/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - South Wimbledon Stn	Other Boarding	Asbestos	Presumed				Ceiling panel slight damage				N	N
15411	ACTIVE	N	N175-00-1/406/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - South Wimbledon Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Box 30amp - Insulation within		1			
18637	ACTIVE	N	N175-00-1/406/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - South Wimbledon Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Transformer Box(es)		3			
12209	ACTIVE	N	N175-00-1/411	Store - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15412	ACTIVE	N	N175-00-1/411	Store - Station Building - South Wimbledon Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12210	ACTIVE	N	N175-00-1/416	Toilet: Female - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15413	ACTIVE	N	N175-00-1/416	Toilet: Female - Station Building - South Wimbledon Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12211	ACTIVE	N	N175-00-1/417	Toilet: Male - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12212	ACTIVE	N	N175-00-1/451	Tenancy - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15414	ACTIVE	N	N175-00-1/451/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - South Wimbledon Stn	No Access	Asbestos	No Access: Presumed				No Access above false ceiling				YES	
12213	ACTIVE	N	N175-00-1/452	Tenancy - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18176	ACTIVE	N	N175-00-1/452/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - South Wimbledon Stn	No Access	Asbestos	No Access: Presumed				No Access above false ceiling				YES	



# Hazardous Material Asset Register - Summary



## N175-00 - Station Building - South Wimbledon Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12214	ACTIVE	N	N175-00-1/453	Tenancy - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15415	ACTIVE	N	N175-00-1/453	Tenancy - Station Building - South Wimbledon Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Tenancy					
12215	ACTIVE	N	N175-00-1/576	Stairs: Linear - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15416	ACTIVE	N	N175-00-1/576	Stairs: Linear - Station Building - South Wimbledon Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12216	ACTIVE	N	N175-00-1/661	Switch Room - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15417	ACTIVE	N	N175-00-1/661	Switch Room - Station Building - South Wimbledon Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12217	ACTIVE	N	N175-00-1/664	Locker Room - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15418	ACTIVE	N	N175-00-1/664	Locker Room - Station Building - South Wimbledon Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12218	ACTIVE	N	N175-00-1/666	Switch Cupboard - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15419	ACTIVE	N	N175-00-1/666	Switch Cupboard - Station Building - South Wimbledon Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12219	ACTIVE	N	N175-00-1/751	Station Control Room - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18177	ACTIVE	N	N175-00-1/751	Station Control Room - Station Building - South Wimbledon Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12220	ACTIVE	N	N175-00-2/081	Circulation Area - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15420	ACTIVE	N	N175-00-2/081	Circulation Area - Station Building - South Wimbledon Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
44986	ACTIVE	N	N175-00-2/081	Circulation Area - Station Building - South Wimbledon Stn	Caulking	Asbestos	Presumed				Escalator Incline (Non Public Side) - Tunnel Ring Caulking To Tunnel Joints - No Access				N	N
12221	ACTIVE	N	N175-00-2/161	LMC - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15421	ACTIVE	N	N175-00-2/161	LMC - Station Building - South Wimbledon Stn	Cable Duct: Other	Asbestos	Surveyed - Not Detected				New Cable Ducts		6			



# Hazardous Material Asset Register - Summary



## N175-00 - Station Building - South Wimbledon Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15422	ACTIVE	N	N175-00-2/161	LMC - Station Building - South Wimbledon Stn	Cable Duct: Other	Asbestos	Surveyed – Not Detected				Cable Ducts into Inverts		4			
15423	ACTIVE	N	N175-00-2/161	LMC - Station Building - South Wimbledon Stn	Cable: Sheath	Asbestos	Known				Green Braided Cables		4			
12222	ACTIVE	N	N175-00-2/201	Passage - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15424	ACTIVE	N	N175-00-2/201	Passage - Station Building - South Wimbledon Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12223	ACTIVE	N	N175-00-2/202	Passage - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15425	ACTIVE	N	N175-00-2/202	Passage - Station Building - South Wimbledon Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12224	ACTIVE	N	N175-00-2/203	Passage - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15426	ACTIVE	N	N175-00-2/203	Passage - Station Building - South Wimbledon Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12225	ACTIVE	N	N175-00-2/204	Passage - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18178	ACTIVE	N	N175-00-2/204	Passage - Station Building - South Wimbledon Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12226	ACTIVE	N	N175-00-2/205	Passage - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15427	ACTIVE	N	N175-00-2/205	Passage - Station Building - South Wimbledon Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12227	ACTIVE	N	N175-00-2/261	Platform 1 - Northbound Local - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44988	ACTIVE	N	N175-00-2/261	Platform 1 - Northbound Local - Station Building - South Wimbledon Stn	Westing house Boxes	Asbestos	Presumed				Platform 1 Invert - Small Westinghouse Box to wall trackside				N	N
15428	ACTIVE	N	N175-00-2/261	Platform 1 - Northbound Local - Station Building - South Wimbledon Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
44987	ACTIVE	N	N175-00-2/261	Platform 1 - Northbound Local - Station Building - South Wimbledon Stn	Cable: Sheath	Asbestos	Known				4no cables to tail end of platform on cable run				N	N
15430	ACTIVE	N	N175-00-2/261/FLR-01	Floor - 1 - Platform 1 - Station Building - South Wimbledon Stn	Cable: Sheath	Asbestos	No Access: Presumed				Cables near 2/711		4			YES



# Hazardous Material Asset Register - Summary



## N175-00 - Station Building - South Wimbledon Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18179	ACTIVE	N	N175-00-2/261/FLR-01	Floor - 1 - Platform 1 - Station Building - South Wimbledon Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - White Cable 40ml x 100mm diameter					YES
15429	ACTIVE	N	N175-00-2/261/FLR-01	Floor - 1 - Platform 1 - Station Building - South Wimbledon Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables entire length of Invert		2			YES
12228	ACTIVE	N	N175-00-2/262	Platform 2 - Southbound Local - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
44991	ACTIVE	N	N175-00-2/262	Platform 2 - Southbound Local - Station Building - South Wimbledon Stn	Cable: Sheath	Asbestos	Known				Platform 2 Invert - 5no to cable run running throughout & going out of invert				N	N
44990	ACTIVE	N	N175-00-2/262	Platform 2 - Southbound Local - Station Building - South Wimbledon Stn	Westing house Boxes	Asbestos	Presumed				Platform 2 Invert - Small Westinghouse Box to wall trackside				N	N
15431	ACTIVE	N	N175-00-2/262	Platform 2 - Southbound Local - Station Building - South Wimbledon Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
44989	ACTIVE	N	N175-00-2/262	Platform 2 - Southbound Local - Station Building - South Wimbledon Stn	Cable: Sheath	Asbestos	Known				4no cables to head end on cable run				N	N
18638	ACTIVE	N	N175-00-2/262/FLR-01	Floor - 1 - Platform 2 - Station Building - South Wimbledon Stn	Cable: Sheath	Asbestos	Strongly Presumed				Green Cable 40ml x 20mm diameter		1			YES
12229	ACTIVE	N	N175-00-2/661	Disused Room - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
12230	ACTIVE	N	N175-00-2/662	Lobby - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15432	ACTIVE	N	N175-00-2/662	Lobby - Station Building - South Wimbledon Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12231	ACTIVE	N	N175-00-2/663	Disused Room - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
12232	ACTIVE	N	N175-00-2/664	Switch Cupboard - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15433	ACTIVE	N	N175-00-2/664	Switch Cupboard - Station Building - South Wimbledon Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
44992	ACTIVE	N	N175-00-2/664/FLR-01	Floor - 1 - Switch Cupboard - Station Building - South Wimbledon Stn	Cable Duct: Other	Asbestos	Presumed				Cable ducts to floor - no access for sampling				N	N
12233	ACTIVE	N	N175-00-2/665	Switch Room - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N175-00 - Station Building - South Wimbledon Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18180	ACTIVE	N	N175-00-2/665	Switch Room - Station Building - South Wimbledon Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12234	ACTIVE	N	N175-00-2/666	Switch Room - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15434	ACTIVE	N	N175-00-2/666	Switch Room - Station Building - South Wimbledon Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
44993	ACTIVE	N	N175-00-2/666/FLR-01	Floor - 1 - Switch Room - Station Building - South Wimbledon Stn	Cable Duct: Other	Asbestos	Presumed				Cable ducts to floor - no access for sampling				N	N
12235	ACTIVE	N	N175-00-2/667	Switch Cupboard - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15435	ACTIVE	N	N175-00-2/667	Switch Cupboard - Station Building - South Wimbledon Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12236	ACTIVE	N	N175-00-2/711	Relay Room - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44995	ACTIVE	N	N175-00-2/711	Relay Room - Station Building - South Wimbledon Stn	Cable: Sheath	Asbestos	Known				Green braided cables To ducts and wall 3, first and last J Hangers 2no x 3m	3	2		N	N
44994	ACTIVE	N	N175-00-2/711	Relay Room - Station Building - South Wimbledon Stn	Vinyl tiles	Asbestos	Known				Grey Vinyl tiles to high level walls and ceiling	50			N	N
44996	ACTIVE	N	N175-00-2/711	Relay Room - Station Building - South Wimbledon Stn	Other Boarding	Asbestos	Presumed				Brown composite panel To wall by CR(N) circuit				N	N
44997	ACTIVE	N	N175-00-2/711	Relay Room - Station Building - South Wimbledon Stn	Boarding: Cement	Asbestos	Known				Cement Panels to top and bottom shelves 1no x 1m	1	1		N	N
15438	ACTIVE	N	N175-00-2/711/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - South Wimbledon Stn	Vinyl tiles	Asbestos	Known				Asbestos - K 50sqm Grey Vinyl tiles to high level walls and ceiling					
44998	ACTIVE	N	N175-00-2/711/FLR-01	Floor - 1 - Relay Room - Station Building - South Wimbledon Stn	Cable Duct: Other	Asbestos	Presumed				3no ducts to floor by wall 2 - no access for sampling		3		N	N
18181	ACTIVE	N	N175-00-2/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - South Wimbledon Stn	Vinyl tiles	Asbestos	Known				40sqm Green & White Vinyl tiles					
19945	ACTIVE	N	N175-00-2/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - South Wimbledon Stn	Boarding: Cement	Asbestos	Presumed				Panels under PCB's					
15440	INACTIVE	N	N175-00-2/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - South Wimbledon Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				6 x PCB's - Fair Condition Serial Nos.186508, 186441, 186563, 186565, 186438, 186144, 186566 Re Inspected 14/04/2015		5			



# Hazardous Material Asset Register - Summary



## N175-00 - Station Building - South Wimbledon Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15439	ACTIVE	N	N175-00-2/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - South Wimbledon Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Westinghouse Box		1			
19429	ACTIVE	N	N175-00-2/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - South Wimbledon Stn	Vinyl tiles	Asbestos	Known				40sqm Green & White Vinyl tiles					
18651	ACTIVE	N	N175-00-2/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - South Wimbledon Stn	Cable: Sheath	Asbestos	Presumed				10mm Redundant cable from invert to passage head wall		1			
18182	ACTIVE	N	N175-00-2/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - South Wimbledon Stn	Cable: Sheath	Asbestos	Presumed				Various Cables within J-hangers					
18238	INACTIVE	N	N175-00-2/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - South Wimbledon Stn	Westing house Boxes	Asbestos	Strongly Presumed						1			
15436	ACTIVE	N	N175-00-2/711/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - South Wimbledon Stn	Vinyl tiles	Asbestos	Known				40sqm Green & White Vinyl tiles					
15437	ACTIVE	N	N175-00-2/711/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - South Wimbledon Stn	Vinyl tiles	Asbestos	Known				40sqm Green & White Vinyl tiles					
12237	ACTIVE	N	N175-00-2/712	Relay Room - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15444	ACTIVE	N	N175-00-2/712	Relay Room - Station Building - South Wimbledon Stn	Boarding: Cement	Asbestos	Known				Cement Panels to top and bottom shelving at wall 3 - 2no x 1m - slight damage					
44999	INACTIVE	N	N175-00-2/712	Relay Room - Station Building - South Wimbledon Stn	Boarding: Cement	Asbestos	Known				Cement Panels to top and bottom shelving at wall 3 - 2no x 1m - slight damage	1	2		N	N
18184	INACTIVE	N	N175-00-2/712	Relay Room - Station Building - South Wimbledon Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				6 x PCB's - Fair Condition Serial Nos. 186492; 186488; 186411; 186505; 186522; 186424, 186566, 186563, 186438, 186508 Re inspected 14/04/2015		6			
45000	ACTIVE	N	N175-00-2/712/FLR-01	Floor - 1 - Relay Room - Station Building - South Wimbledon Stn	Cable Duct: Other	Asbestos	Presumed				4no ducts to floor by wall 2 - no access for sampling				N	N
15441	ACTIVE	N	N175-00-2/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - South Wimbledon Stn	Vinyl tiles	Asbestos	Known				Red Vinyl Wall Tiles - poor condition					
18652	ACTIVE	N	N175-00-2/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - South Wimbledon Stn	Cable: Sheath	Asbestos	Strongly Presumed				wall 2-3 Asbestos Cables: 3 cables - 2 white , 1 green 2 white cable approx.2m length going into fuse board wall 3 1 green cable exiting at wall 3 trackside approx.1.5 m length					
15442	ACTIVE	N	N175-00-2/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - South Wimbledon Stn	Vinyl tiles	Asbestos	Known				Red Vinyl Wall Tiles - poor condition					



# Hazardous Material Asset Register - Summary



## N175-00 - Station Building - South Wimbledon Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15445	ACTIVE	N	N175-00-2/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - South Wimbledon Stn	Westinghouse Boxes	Asbestos	Presumed				Westinghouse box to wall 2		1			
15446	ACTIVE	N	N175-00-2/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - South Wimbledon Stn	Other Electrical Boxes	Asbestos	Presumed				Electrical Boxes x2		1			
53652	ACTIVE	N	N175-00-2/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - South Wimbledon Stn	Cable: Sheath	Asbestos	Strongly Presumed				1 white cable running from fuse board exiting trackside length 1m					
53662	ACTIVE	N	N175-00-2/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - South Wimbledon Stn	Other Boarding	Asbestos	Presumed				3x dark brown board to capacitor rack top wall 3					
18183	ACTIVE	N	N175-00-2/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - South Wimbledon Stn	Vinyl tiles	Asbestos	Known				Red Vinyl Wall Tiles					
53663	ACTIVE	N	N175-00-2/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - South Wimbledon Stn	Other Boarding	Asbestos	Presumed				3x light brown board to rack on wall 3					
53661	ACTIVE	N	N175-00-2/712/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - South Wimbledon Stn	Other Boarding	Asbestos	Presumed				Black composite to top shelf of rack on capacitor x2 black - wall 3					
15443	ACTIVE	N	N175-00-2/712/WAL-004	Wall: Internal - 4 - Relay Room - Station Building - South Wimbledon Stn	Vinyl tiles	Asbestos	Known				Red Vinyl Wall Tiles - poor condition					
12238	ACTIVE	N	N175-00-2/761	Cleaners Store - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15447	ACTIVE	N	N175-00-2/761	Cleaners Store - Station Building - South Wimbledon Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12239	ACTIVE	N	N175-00-2/951	SER - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15448	ACTIVE	N	N175-00-2/951	SER - Station Building - South Wimbledon Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12240	ACTIVE	N	N175-00-2/963	Store - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15449	ACTIVE	N	N175-00-2/963	Store - Station Building - South Wimbledon Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12241	ACTIVE	N	N175-00-A/661	CER - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15450	ACTIVE	N	N175-00-A/661/FLR-01	Floor - 1 - CER - Station Building - South Wimbledon Stn	Void	Asbestos	Surveyed - Not Detected				Concrete; Existing Containment beneath Computer Tiles					YES



# Hazardous Material Asset Register - Summary



## N175-00 - Station Building - South Wimbledon Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
45411	ACTIVE	N	N175-00-A/661/WAL-003	Wall: Internal - 3 - CER - Station Building - South Wimbledon Stn	Other Electrical Boxes	Asbestos	Presumed				2no Combination fuse switches		2		N	N
12242	ACTIVE	N	N175-00-A/731	Switch Room - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
12243	ACTIVE	N	N175-00-A/732	Switch Room - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15451	ACTIVE	N	N175-00-A/732	Switch Room - Station Building - South Wimbledon Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12244	ACTIVE	N	N175-00-A/901	Disused Room - Station Building - South Wimbledon Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18185	ACTIVE	N	N175-00-A/901	Disused Room - Station Building - South Wimbledon Stn	No Access	Asbestos	No Access: Presumed				No Access - Not Surveyed					

## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12248	ACTIVE	N	N177-00-1/001	Booking Hall - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15138	ACTIVE	N	N177-00-1/001	Booking Hall - Station Building - Morden Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
42585	ACTIVE	N	N177-00-1/001	Booking Hall - Station Building - Morden Stn	Other Boarding	Asbestos	Room: Surveyed - Asbestos Known				Board, 2m2, on left hand side front of Morden Station	2	2	R508576	N	N
15139	ACTIVE	N	N177-00-1/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				Painted beams supporting the ticket hall					
12249	ACTIVE	N	N177-00-1/011	Ticket Office - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15141	ACTIVE	N	N177-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Morden Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Ceiling					
15142	ACTIVE	N	N177-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Morden Stn	Cable: Wrap	Asbestos	Surveyed - Not Detected				Tape				YES	
18471	ACTIVE	N	N177-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Morden Stn	Void	Asbestos	Surveyed - Not Detected				Metal Ducts; Fibreglass Lagging;				YES	



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43104	ACTIVE	N	N177-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				Wooden windows to North wall (White Gloss) 1.30%			R519077	N	N
43103	ACTIVE	N	N177-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				Brown Gloss Original ceiling within the false ceiling (Brown Gloss) 1.77%			R519077	Y	N
19166	ACTIVE	N	N177-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				Wooden Skylight					
15140	ACTIVE	N	N177-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath wooden false floor					Yes
12250	ACTIVE	N	N177-00-1/021	POM - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19167	ACTIVE	N	N177-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Morden Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
42966	ACTIVE	N	N177-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Morden Stn	Boarding: Supalux	Asbestos	Sampled - Not Detected				Supalux 8m (l), within panel to floor slab under machine, within POM room			R519706	N	N
15144	ACTIVE	N	N177-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Morden Stn	Void	Asbestos	Surveyed - Not Detected				Concrete; Metal Ducts above Supalux Tiles				YES	
15143	ACTIVE	N	N177-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath wooden false floor					YES
12251	ACTIVE	N	N177-00-1/031	Mess Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15146	ACTIVE	N	N177-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Morden Stn	Void	Asbestos	Surveyed - Not Detected				Concrete; Metal Ducts above Supalux Board				YES	
15145	ACTIVE	N	N177-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Morden Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Board					
12252	ACTIVE	N	N177-00-1/036	Toilet: Unisex - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15147	ACTIVE	N	N177-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Morden Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Supalux Tiles					
19168	ACTIVE	N	N177-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Morden Stn	Void	Asbestos	Surveyed - Not Detected				Concrete; Metal Ducts above Supalux Tiles				YES	
12253	ACTIVE	N	N177-00-1/041	Mess Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18576	ACTIVE	N	N177-00-1/041/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Morden Stn	Void	Asbestos	Surveyed - Not Detected				Wood above false ceiling				YES	



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15148	ACTIVE	N	N177-00-1/041/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Morden Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Non Asbestos Boarding					
12254	ACTIVE	N	N177-00-1/042	Mess Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15150	INACTIVE	N	N177-00-1/042/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard above Polystyrene false ceiling / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free				YES	
15149	INACTIVE	N	N177-00-1/042/FLR-01	Floor - 1 - Mess Room - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					YES
12255	ACTIVE	N	N177-00-1/047	Kitchen - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18547	ACTIVE	N	N177-00-1/047/CLG-01	Ceiling: Solid - 1 - Kitchen - Station Building - Morden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
15151	ACTIVE	N	N177-00-1/047/CLG-01	Ceiling: Solid - 1 - Kitchen - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Wood above Supalux Tiles				YES	
12256	ACTIVE	N	N177-00-1/048	Kitchen - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
18164	INACTIVE	N	N177-00-1/048/CLG-01	Ceiling: Solid - 1 - Kitchen - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Above Supalux Board / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
17925	INACTIVE	N	N177-00-1/048/CLG-01	Ceiling: Solid - 1 - Kitchen - Station Building - Morden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
12257	ACTIVE	N	N177-00-1/053	Mess Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15152	ACTIVE	N	N177-00-1/053/DOR-01	Door - 1 - Mess Room - Station Building - Morden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board					
15153	ACTIVE	N	N177-00-1/053/DOR-01	Door - 1 - Mess Room - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Above Supalux Board					



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12258	ACTIVE	N	N177-00-1/054	Switch Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15155	ACTIVE	N	N177-00-1/054/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Above Supalux Boxing					
15154	ACTIVE	N	N177-00-1/054/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Morden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing					
12259	ACTIVE	N	N177-00-1/056	Toilet: Unisex - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17926	ACTIVE	N	N177-00-1/056/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Morden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board					
15156	ACTIVE	N	N177-00-1/056/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Above Supalux Board					
12260	ACTIVE	N	N177-00-1/071	Circulation Area - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15157	ACTIVE	N	N177-00-1/071	Circulation Area - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible				YES	
12261	ACTIVE	N	N177-00-1/081	Lobby - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15158	ACTIVE	N	N177-00-1/081/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Wood above Plaster/Tiles false ceiling				YES	
12263	ACTIVE	N	N177-00-1/083	Lobby - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15160	ACTIVE	N	N177-00-1/083/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Above Wood Ceiling					
12264	ACTIVE	N	N177-00-1/084	Lobby - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15161	ACTIVE	N	N177-00-1/084	Lobby - Station Building - Morden Stn	No Access	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
12265	ACTIVE	N	N177-00-1/086	Lobby - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18548	ACTIVE	N	N177-00-1/086	Lobby - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12266	ACTIVE	N	N177-00-1/087	Lobby - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15162	ACTIVE	N	N177-00-1/087	Lobby - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12267	ACTIVE	N	N177-00-1/092	Lobby - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12268	ACTIVE	N	N177-00-1/131	LMR - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15163	ACTIVE	N	N177-00-1/131	LMR - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12269	ACTIVE	N	N177-00-1/132	LMR - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15164	ACTIVE	N	N177-00-1/132	LMR - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
17928	ACTIVE	N	N177-00-1/136	Lift Shaft - Station Building - Morden Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
15165	ACTIVE	N	N177-00-1/137	Lift Shaft - Station Building - Morden Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
12270	ACTIVE	N	N177-00-1/201	Passage - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15166	ACTIVE	N	N177-00-1/201	Passage - Station Building - Morden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board nr White Door					
12271	ACTIVE	N	N177-00-1/202	Passage - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15167	ACTIVE	N	N177-00-1/202/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Above Wood Ceiling					
12272	ACTIVE	N	N177-00-1/203	Passage - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18549	ACTIVE	N	N177-00-1/203	Passage - Station Building - Morden Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
12273	ACTIVE	N	N177-00-1/236	Passage - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15168	ACTIVE	N	N177-00-1/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Morden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux - Acoustic Panel, Fibreboard					



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
17929	ACTIVE	N	N177-00-1/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Fibreboard; Wooden Roof above false ceiling				YES	
12274	ACTIVE	N	N177-00-1/237	Passage - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43637	ACTIVE	N	N177-00-1/237	Passage - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				White paint to ceiling over head of access door thickness 240 0.01%			R588826	N	N
12275	ACTIVE	N	N177-00-1/238	Lobby - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15170	ACTIVE	N	N177-00-1/238/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Above - Glass, Supalux false ceiling					
15169	ACTIVE	N	N177-00-1/238/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Glass, Supalux					
43528	ACTIVE	N	N177-00-1/238/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Matt Wall 3 thickness 380 1.34%			R564777	N	N
43527	ACTIVE	N	N177-00-1/238/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Matt Pipe to wall thickness 290 0.42%			R564777	N	N
43530	ACTIVE	N	N177-00-1/238/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				Yellow Gloss Handrail thickness 190 0.05%			R564777	N	N
43529	ACTIVE	N	N177-00-1/238/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				White Matt Wooden door frame entrance thickness 720 3.42%			R564777	N	N
43526	ACTIVE	N	N177-00-1/238/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				Cream Matt Wall 4 thickness 390 0.08%			R564777	N	N
12276	ACTIVE	N	N177-00-1/239	Passage - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15172	ACTIVE	N	N177-00-1/239/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Morden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board					
17930	ACTIVE	N	N177-00-1/239/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Metal Ducts above Supalux Board				YES	
15171	ACTIVE	N	N177-00-1/239/FLR-01	Floor - 1 - Passage - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath the Wooden False Floor					YES
12277	ACTIVE	N	N177-00-1/240	Passage - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15173	ACTIVE	N	N177-00-1/240/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Hardboard above Acoustic Panels				YES	



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12278	ACTIVE	N	N177-00-1/241	Passage - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15174	INACTIVE	N	N177-00-1/241/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard above Polystyrene False Ceiling / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free				YES	
18550	INACTIVE	N	N177-00-1/241/FLR-01	Floor - 1 - Passage - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					YES
12279	ACTIVE	N	N177-00-1/242	Passage - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15175	INACTIVE	N	N177-00-1/242/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Above Metal False Ceiling / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
18475	INACTIVE	N	N177-00-1/242/FLR-01	Floor - 1 - Passage - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					YES
12280	ACTIVE	N	N177-00-1/243	Passage - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15176	ACTIVE	N	N177-00-1/243	Passage - Station Building - Morden Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					
12281	ACTIVE	N	N177-00-1/281	Office - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15177	ACTIVE	N	N177-00-1/281/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Wood, Fibreglass Lagging above Tiled Ceiling				YES	
12282	ACTIVE	N	N177-00-1/284	Station Supervisor Office - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17931	ACTIVE	N	N177-00-1/284	Station Supervisor Office - Station Building - Morden Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12283	ACTIVE	N	N177-00-1/291	Office - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15178	INACTIVE	N	N177-00-1/291	Office - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
12284	ACTIVE	N	N177-00-1/301	Passage - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15179	ACTIVE	N	N177-00-1/301/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Wood, above Panels, Glass				YES	
12285	ACTIVE	N	N177-00-1/302	Mess Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18165	ACTIVE	N	N177-00-1/302/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Morden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
15180	ACTIVE	N	N177-00-1/302/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles					
12286	ACTIVE	N	N177-00-1/306	Office - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
18551	INACTIVE	N	N177-00-1/306/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Above Supalux Board / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
17932	INACTIVE	N	N177-00-1/306/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Morden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
12287	ACTIVE	N	N177-00-1/311	Office - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15181	ACTIVE	N	N177-00-1/311	Office - Station Building - Morden Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - Foam Insulation Board					
18161	ACTIVE	N	N177-00-1/311/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Metal Ducts above Supalux Board				YES	
15182	ACTIVE	N	N177-00-1/311/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Morden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board					



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12288	ACTIVE	N	N177-00-1/316	SER - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19082	ACTIVE	N	N177-00-1/316	SER - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible				YES	
12289	ACTIVE	N	N177-00-1/317	Quiet Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18538	ACTIVE	N	N177-00-1/317	Quiet Room - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12291	ACTIVE	N	N177-00-1/331	Mess Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19083	ACTIVE	N	N177-00-1/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Wood - Above Tiles				YES	
43634	ACTIVE	N	N177-00-1/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				Pink flaking paint to walls thickness 330 0.01%			R588826	N	N
12293	ACTIVE	N	N177-00-1/342	Mess Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15058	ACTIVE	N	N177-00-1/342	Mess Room - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
15057	ACTIVE	N	N177-00-1/342/WAL-001	Wall: Internal - 1 - Mess Room - Station Building - Morden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Board					
15059	ACTIVE	N	N177-00-1/342/WAL-002	Wall: Internal - 2 - Mess Room - Station Building - Morden Stn	LUL Heaters	Asbestos	Removed				Insulation within CEH Heater					
12294	ACTIVE	N	N177-00-1/401	Store - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18539	ACTIVE	N	N177-00-1/401/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Morden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel, Concrete					
12295	ACTIVE	N	N177-00-1/402	Store - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15060	ACTIVE	N	N177-00-1/402	Store - Station Building - Morden Stn		Asbestos	Room: Asbestos Free				No Asbestos Visible / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free				YES	
12296	ACTIVE	N	N177-00-1/406	Store - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18572	ACTIVE	N	N177-00-1/406/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Morden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel, Concrete					
12297	ACTIVE	N	N177-00-1/407	Store - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
19084	INACTIVE	N	N177-00-1/407/FLR-01	Floor - 1 - Store - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Rubber Flooring / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					YES
12298	ACTIVE	N	N177-00-1/411	Store - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15061	ACTIVE	N	N177-00-1/411	Store - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12299	ACTIVE	N	N177-00-1/413	Switch Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15062	ACTIVE	N	N177-00-1/413	Switch Room - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12300	ACTIVE	N	N177-00-1/414	Locker Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15064	ACTIVE	N	N177-00-1/414/CLG-01	Ceiling: Solid - 1 - Locker Room - Station Building - Morden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels					
19085	ACTIVE	N	N177-00-1/414/CLG-01	Ceiling: Solid - 1 - Locker Room - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Above Supalux Panels					
15063	ACTIVE	N	N177-00-1/414/FLR-01	Floor - 1 - Locker Room - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Rubber Flooring					YES
12302	ACTIVE	N	N177-00-1/416	Toilet: Female - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15066	ACTIVE	N	N177-00-1/416	Toilet: Female - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
43636	ACTIVE	N	N177-00-1/416/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				White paint to ceiling thickness 110 0.02%			R588826	N	N
43533	ACTIVE	N	N177-00-1/416/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Room: Surveyed – Asbestos Known				White Matt Door frame 810 3.37%			R564777	N	N
43635	ACTIVE	N	N177-00-1/416/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				Cream paint to walls. thickness 160 0.02%			R588826	N	N



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43534	ACTIVE	N	N177-00-1/416/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Room: Surveyed – Asbestos Known				White Matt Door 110 0.05%			R564777	N	N
44965	ACTIVE	N	N177-00-1/416/DOR-01	Door - 1 - Toilet - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				White Matt Door Frame				N	N
44966	ACTIVE	N	N177-00-1/416/DOR-01	Door - 1 - Toilet - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				White Matt Door				N	N
12303	ACTIVE	N	N177-00-1/417	Lobby - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15067	ACTIVE	N	N177-00-1/417/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing					
43532	ACTIVE	N	N177-00-1/417/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Room: Surveyed – Asbestos Known				White Matt Door 110 0.05%			R564777	N	N
43531	ACTIVE	N	N177-00-1/417/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Room: Surveyed – Asbestos Known				White Matt Door frame 680 2.11%			R564777	N	N
44967	ACTIVE	N	N177-00-1/417/DOR-01	Door - 1 - Lobby - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				White Matt Door Frame				N	N
44968	ACTIVE	N	N177-00-1/417/DOR-01	Door - 1 - Lobby - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				White Matt Door				N	N
12304	ACTIVE	N	N177-00-1/418	Toilet: Male - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18540	ACTIVE	N	N177-00-1/418	Toilet: Male - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
15068	ACTIVE	N	N177-00-1/418	Toilet: Male - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				Water Tank - Non Asbestos					
12305	ACTIVE	N	N177-00-1/419	Mess Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15069	ACTIVE	N	N177-00-1/419	Mess Room - Station Building - Morden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel above Heater					
43638	ACTIVE	N	N177-00-1/419	Mess Room - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				White paint around the ceiling roof light thickness 470 0.02%			R588826	N	N
12306	ACTIVE	N	N177-00-1/420	Mess Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19086	ACTIVE	N	N177-00-1/420	Mess Room - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43633	ACTIVE	N	N177-00-1/420	Mess Room - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				White flaking paint to ceiling thickness 750 2.26%			R588826	N	N
43632	ACTIVE	N	N177-00-1/420	Mess Room - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				Cream flaking paint to walls thickness110 0.02%			R588826	N	N
12307	ACTIVE	N	N177-00-1/421	Toilet: Female - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15070	ACTIVE	N	N177-00-1/421	Toilet: Female - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12308	ACTIVE	N	N177-00-1/422	Toilet: Male - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15071	ACTIVE	N	N177-00-1/422/FLR-01	Floor - 1 - Toilet - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Plasterboard Floor					YES
12311	ACTIVE	N	N177-00-1/425	Shower Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18541	ACTIVE	N	N177-00-1/425	Shower Room - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12312	ACTIVE	N	N177-00-1/426	Toilet: Female - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15074	ACTIVE	N	N177-00-1/426	Toilet: Female - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12313	ACTIVE	N	N177-00-1/427	Toilet: Male - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15076	INACTIVE	N	N177-00-1/427/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard Tiles above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free				YES	
15075	INACTIVE	N	N177-00-1/427/FLR-01	Floor - 1 - Toilet - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Metal False Floor /T his room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					YES
12314	ACTIVE	N	N177-00-1/428	Toilet - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19150	INACTIVE	N	N177-00-1/428/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard Tiles above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free				YES	
15077	INACTIVE	N	N177-00-1/428/FLR-01	Floor - 1 - Toilet - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					YES
12315	ACTIVE	N	N177-00-1/429	Toilet - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15078	ACTIVE	N	N177-00-1/429	Toilet - Station Building - Morden Stn	No Access	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
12316	ACTIVE	N	N177-00-1/451	Tenancy - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15108	ACTIVE	N	N177-00-1/451/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Morden Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access				YES	
12317	ACTIVE	N	N177-00-1/576	Stairs: Linear - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15109	ACTIVE	N	N177-00-1/576	Stairs: Linear - Station Building - Morden Stn		Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
12318	ACTIVE	N	N177-00-1/577	Stairs: Linear - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
19158	ACTIVE	N	N177-00-1/577	Stairs: Linear - Station Building - Morden Stn		Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
12319	ACTIVE	N	N177-00-1/601	Stairs: Linear - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15110	ACTIVE	N	N177-00-1/601	Stairs: Linear - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12320	ACTIVE	N	N177-00-1/602	Stairs: Linear - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15111	ACTIVE	N	N177-00-1/602	Stairs: Linear - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12321	ACTIVE	N	N177-00-1/603	Stairs: Linear - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15112	ACTIVE	N	N177-00-1/603	Stairs: Linear - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12322	ACTIVE	N	N177-00-1/604	Stairs: Linear - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19159	ACTIVE	N	N177-00-1/604	Stairs: Linear - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12323	ACTIVE	N	N177-00-1/607	Stairs: Linear - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15113	ACTIVE	N	N177-00-1/607	Stairs: Linear - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
15114	ACTIVE	N	N177-00-1/607	Stairs: Linear - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				Support Steel and Hand Rail to Staircase					
12324	ACTIVE	N	N177-00-1/609	Stairs: Linear - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18470	ACTIVE	N	N177-00-1/609	Stairs: Linear - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12325	ACTIVE	N	N177-00-1/610	Stairs: Linear - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15115	INACTIVE	N	N177-00-1/610/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Above Metal, Glass / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
12326	ACTIVE	N	N177-00-1/611	Stairs: Linear - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19160	ACTIVE	N	N177-00-1/611	Stairs: Linear - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12327	ACTIVE	N	N177-00-1/612	Stairs: Linear - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15116	ACTIVE	N	N177-00-1/612	Stairs: Linear - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
15117	ACTIVE	N	N177-00-1/636	Overbridge - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
15118	ACTIVE	N	N177-00-1/637	Overbridge - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12328	ACTIVE	N	N177-00-1/661	Switch Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19161	ACTIVE	N	N177-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Morden Stn	Isolator Switches	Asbestos	Strongly Presumed				Insulation within Switch Boxes; 3 x 60 amps, & 1 x 100 amps  No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		4			
15119	ACTIVE	N	N177-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Morden Stn	Isolator Switches	Asbestos	Strongly Presumed				Insulation within Switch Boxes; 1x 30 amps, & 1 x 60 amps  No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		2			
12330	ACTIVE	N	N177-00-1/663	Switch Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15121	ACTIVE	N	N177-00-1/663/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Morden Stn	Isolator Switches	Asbestos	Strongly Presumed				Insulation within Switch Boxes; 2no 60amp 1no 100amp  No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		3			
12332	ACTIVE	N	N177-00-1/665	Switch Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15123	ACTIVE	N	N177-00-1/665/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Morden Stn	Isolator Switches	Asbestos	Strongly Presumed				Insulation within Switch Boxes; 1no 60 & 200amp; 3no 100amp  No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		5			
12333	ACTIVE	N	N177-00-1/666	Switch Cupboard - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19162	INACTIVE	N	N177-00-1/666/CLG-01	Ceiling: Solid - 1 - Switch Cupboard - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
18575	INACTIVE	N	N177-00-1/666/FLR-01	Floor - 1 - Switch Cupboard - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					YES
12334	ACTIVE	N	N177-00-1/711	Power Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15124	ACTIVE	N	N177-00-1/711	Power Room - Station Building - Morden Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
12335	ACTIVE	N	N177-00-1/746	Staff IT Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15125	ACTIVE	N	N177-00-1/746	Staff IT Room - Station Building - Morden Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12336	ACTIVE	N	N177-00-1/761	Equipment Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15126	ACTIVE	N	N177-00-1/761/WAL-003	Wall: Internal - 3 - Equipment Room - Station Building - Morden Stn	Isolator Switches	Asbestos	Strongly Presumed				Insulation within Switch Boxes; 1no 60amp  No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
12337	ACTIVE	N	N177-00-1/801	Office - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15127	ACTIVE	N	N177-00-1/801/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Morden Stn	Void	Asbestos	Surveyed - Not Detected				Hardboard; Fibreglass Lagging above Acoustic Panels				YES	
12338	ACTIVE	N	N177-00-1/802	Office - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18545	ACTIVE	N	N177-00-1/802/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Morden Stn	Void	Asbestos	Surveyed - Not Detected				Hardboard; Fibreglass Lagging - above Acoustic Panels				YES	
12339	ACTIVE	N	N177-00-1/804	Office - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15128	ACTIVE	N	N177-00-1/804/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Morden Stn	Void	Asbestos	Surveyed - Not Detected				Hardboard; Fibreglass Lagging above Acoustic Panels				YES	



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12340	ACTIVE	N	N177-00-1/805	Office - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19163	ACTIVE	N	N177-00-1/805/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Hardboard; Fibreglass Lagging above Acoustic Panels				YES	
12344	ACTIVE	N	N177-00-1/809	Office - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15133	ACTIVE	N	N177-00-1/809/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Non Asbestos Ceiling Tiles					
12345	ACTIVE	N	N177-00-1/810	Office - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15080	INACTIVE	N	N177-00-1/810/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard above Polystyrene False Ceiling / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free				YES	
19164	INACTIVE	N	N177-00-1/810/FLR-01	Floor - 1 - Office - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					YES
12346	ACTIVE	N	N177-00-1/811	Office - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15081	INACTIVE	N	N177-00-1/811/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard above Polystyrene False Ceiling / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free				YES	
19151	ACTIVE	N	N177-00-1/811/FLR-01	Floor - 1 - Office - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Metal False Floor					YES
12347	ACTIVE	N	N177-00-1/812	Office - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15082	INACTIVE	N	N177-00-1/812/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Morden Stn	Boarding: Supalux	Asbestos	Room: Asbestos Free				Supalux Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15083	INACTIVE	N	N177-00-1/812/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
12348	ACTIVE	N	N177-00-1/813	Office - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15084	ACTIVE	N	N177-00-1/813	Office - Station Building - Morden Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12349	ACTIVE	N	N177-00-1/814	Playback Suite - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19152	ACTIVE	N	N177-00-1/814/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				No Access through Hatch in ceiling				YES	
12350	ACTIVE	N	N177-00-1/815	Training Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15085	ACTIVE	N	N177-00-1/815	Training Room - Station Building - Morden Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
12351	ACTIVE	N	N177-00-1/816	Technical Support Office - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15086	ACTIVE	N	N177-00-1/816	Technical Support Office - Station Building - Morden Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
12352	ACTIVE	N	N177-00-1/861	Equipment Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
12353	ACTIVE	N	N177-00-1/901	Store - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15087	ACTIVE	N	N177-00-1/901	Store - Station Building - Morden Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12354	ACTIVE	N	N177-00-1/903	Office - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15088	ACTIVE	N	N177-00-1/903/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Morden Stn	Void	Asbestos	Surveyed - Not Detected				Hardboard above Acoustic Panels				YES	
12355	ACTIVE	N	N177-00-1/904	Kitchen - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15089	ACTIVE	N	N177-00-1/904/CLG-01	Ceiling: Solid - 1 - Kitchen - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard					



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12356	ACTIVE	N	N177-00-1/905	Store - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19153	ACTIVE	N	N177-00-1/905	Store - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12357	ACTIVE	N	N177-00-1/906	Store - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15090	ACTIVE	N	N177-00-1/906	Store - Station Building - Morden Stn	No Access	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
12358	ACTIVE	N	N177-00-1/907	Store - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
12359	ACTIVE	N	N177-00-1/908	Store - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18542	ACTIVE	N	N177-00-1/908/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Morden Stn	No Access	Asbestos	No Access: Presumed				No Access above Plasterboard Ceiling				YES	
15091	ACTIVE	N	N177-00-1/909	Gantry - Station Building - Morden Stn	No Access	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
12360	ACTIVE	N	N177-00-1/910	Store - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15092	ACTIVE	N	N177-00-1/910	Store - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12361	ACTIVE	N	N177-00-2/047	Mess Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15094	ACTIVE	N	N177-00-2/047	Mess Room - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
19154	ACTIVE	N	N177-00-2/047/FLR-01	Floor - 1 - Mess Room - Station Building - Morden Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Tiles under Sink					
15093	ACTIVE	N	N177-00-2/047/FLR-01	Floor - 1 - Mess Room - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				No Access beneath Lino, Wooden Floor;					YES



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12362	ACTIVE	N	N177-00-2/081	Lobby - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15095	ACTIVE	N	N177-00-2/081/FLR-01	Floor - 1 - Lobby - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				No Access beneath Lino, Wooden Floor					YES
12363	ACTIVE	N	N177-00-2/261	Platform 1 - Southbound Local - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15096	ACTIVE	N	N177-00-2/261	Platform 1 - Southbound Local - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12364	ACTIVE	N	N177-00-2/262	Platform 2 - Southbound Local - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15097	ACTIVE	N	N177-00-2/262	Platform 2 - Southbound Local - Station Building - Morden Stn	Pipe Lagging	Asbestos	Surveyed – Not Detected				nr 2/662 & 2/731					
19155	ACTIVE	N	N177-00-2/262	Platform 2 - Southbound Local - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				Girders below Stairs					
12365	ACTIVE	N	N177-00-2/263	Platform 3 - Northbound Main - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18162	ACTIVE	N	N177-00-2/263	Platform 3 - Northbound Main - Station Building - Morden Stn	Pipe Lagging	Asbestos	Surveyed – Not Detected				nr 2/662					
15098	ACTIVE	N	N177-00-2/263	Platform 3 - Northbound Main - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				Girders below Stairs					
12366	ACTIVE	N	N177-00-2/264	Platform 4 - Northbound Main - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15099	ACTIVE	N	N177-00-2/264	Platform 4 - Northbound Main - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
15100	ACTIVE	N	N177-00-2/264	Platform 4 - Northbound Main - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				Girders below Stairs					
12367	ACTIVE	N	N177-00-2/265	Platform 5 - Northbound Local - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18543	ACTIVE	N	N177-00-2/265	Platform 5 - Northbound Local - Station Building - Morden Stn	Cable: Sheath	Asbestos	Strongly Presumed				50mm Cable on OTX from 2/666 to Trackside in cess  2x cables partially encapsulated  Missing entry on overbridge presume materials within 1x Small westinghouse to wall of 1/636 by door to lobby 1/237 - Photo DSC5447		2			



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
18574	ACTIVE	N	N177-00-2/265	Platform 5 - Northbound Local - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				Girders below Stairs					
12368	ACTIVE	N	N177-00-2/331	Mess Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15101	ACTIVE	N	N177-00-2/331	Mess Room - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
15102	ACTIVE	N	N177-00-2/331	Mess Room - Station Building - Morden Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - Foam Insulation Board					
19156	ACTIVE	N	N177-00-2/331/FLR-01	Floor - 1 - Mess Room - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Wooden False Floor					YES
12369	ACTIVE	N	N177-00-2/371	Disused Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44969	ACTIVE	N	N177-00-2/371	Disused Room - Station Building - Morden Stn	Westing house Boxes	Asbestos	Strongly Presumed				External - 1x Small Westinghouse box (wall adjacent to track)				N	N
44970	ACTIVE	N	N177-00-2/371	Disused Room - Station Building - Morden Stn	Westing house Boxes	Asbestos	Strongly Presumed				External - 1x Westinghouse box (to wall by door 2/731)				N	N
15103	ACTIVE	N	N177-00-2/371	Disused Room - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible; Recently Refurbished 2013/14;					
12370	ACTIVE	N	N177-00-2/372	Disused Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15104	ACTIVE	N	N177-00-2/372	Disused Room - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible; Recently Refurbished 2013/14;					
15105	ACTIVE	N	N177-00-2/372	Disused Room - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				East Wall matt brown paint - encapsulated. Project have skimmed wall with plaster					
12371	ACTIVE	N	N177-00-2/373	Mess Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19157	ACTIVE	N	N177-00-2/373/WAL-003	Wall: Internal - 3 - Mess Room - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink					
12372	ACTIVE	N	N177-00-2/381	Store - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15106	ACTIVE	N	N177-00-2/381	Store - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12373	ACTIVE	N	N177-00-2/382	Store - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15107	ACTIVE	N	N177-00-2/382	Store - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12374	ACTIVE	N	N177-00-2/406	Store - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18544	ACTIVE	N	N177-00-2/406	Store - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12375	ACTIVE	N	N177-00-2/411	Toilet: Unisex - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15208	ACTIVE	N	N177-00-2/411/FLR-01	Floor - 1 - Toilet - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Lino, False Wooden Floor					YES
12376	ACTIVE	N	N177-00-2/412	Store - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15209	ACTIVE	N	N177-00-2/412	Store - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12377	ACTIVE	N	N177-00-2/413	Store - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15210	ACTIVE	N	N177-00-2/413	Store - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12378	ACTIVE	N	N177-00-2/414	Store - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15211	ACTIVE	N	N177-00-2/414	Store - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12379	ACTIVE	N	N177-00-2/416	Lobby - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17940	ACTIVE	N	N177-00-2/416	Lobby - Station Building - Morden Stn	Cable: Sheath	Asbestos	Presumed				White Cables outside on walkway bridge / otx in cable run		2			
12380	ACTIVE	N	N177-00-2/417	Toilet: Unisex - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15212	ACTIVE	N	N177-00-2/417/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Morden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
15213	ACTIVE	N	N177-00-2/417/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Above Supalux Boarding/ Plasterboard					
12381	ACTIVE	N	N177-00-2/418	Toilet: Unisex - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15214	ACTIVE	N	N177-00-2/418	Toilet: Unisex - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12382	ACTIVE	N	N177-00-2/451	Switch Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17941	ACTIVE	N	N177-00-2/451	Switch Room - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12383	ACTIVE	N	N177-00-2/661	Switch Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15215	ACTIVE	N	N177-00-2/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Morden Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
18554	ACTIVE	N	N177-00-2/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Morden Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		3			
12384	ACTIVE	N	N177-00-2/662	Switch Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15216	ACTIVE	N	N177-00-2/662	Switch Room - Station Building - Morden Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		3			
17942	ACTIVE	N	N177-00-2/662	Switch Room - Station Building - Morden Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
15217	ACTIVE	N	N177-00-2/662/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard Ceiling					
12386	ACTIVE	N	N177-00-2/666	Switch Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18227	ACTIVE	N	N177-00-2/666/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Morden Stn	Cable: Sheath	Asbestos	Strongly Presumed				White 50mmØ Cable to wall 1 and on ceiling above door through duct onto OTX then to Track					
15223	ACTIVE	N	N177-00-2/666/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Morden Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Cable Ducts 6no W1 & W3		6			
15224	ACTIVE	N	N177-00-2/666/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Morden Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Cable Ducts 6no W1 & W3		6			



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15222	ACTIVE	N	N177-00-2/666/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Morden Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes - Insulation within; 3 x 100 amps, 4 x 60 amps, 2 x 200 amps  No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		9			
12387	ACTIVE	N	N177-00-2/667	Switch Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
18555	ACTIVE	N	N177-00-2/667	Switch Room - Station Building - Morden Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Construction					
12388	ACTIVE	N	N177-00-2/706	IMR - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17944	ACTIVE	N	N177-00-2/706	IMR - Station Building - Morden Stn	Cable: Sheath	Asbestos	Presumed				White Cables  Presume 4x brown composite panels to rear of light reels to walls throughout - photo DSC05418		4			
19294	ACTIVE	N	N177-00-2/706/WAL-001	Wall: Internal - 1 - IMR - Station Building - Morden Stn	Vinyl tiles	Asbestos	Known				Red Tiles to lower walls throughout some loose - Chrysotile					
18578	ACTIVE	N	N177-00-2/706/WAL-001	Wall: Internal - 1 - IMR - Station Building - Morden Stn	Vinyl tiles	Asbestos	Presumed				Grey Tiles - Above Head Height to walls throughout - some loose					
15225	ACTIVE	N	N177-00-2/706/WAL-002	Wall: Internal - 2 - IMR - Station Building - Morden Stn	Vinyl tiles	Asbestos	Known				Red Tiles to lower wall throughout some loose - Chrysotile					
15226	ACTIVE	N	N177-00-2/706/WAL-002	Wall: Internal - 2 - IMR - Station Building - Morden Stn	Vinyl tiles	Asbestos	Presumed				Grey Tiles - Above Head Height to upper wall - some loose					
12389	ACTIVE	N	N177-00-2/731	CER - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
17945	ACTIVE	N	N177-00-2/731/FLR-01	Floor - 1 - CER - Station Building - Morden Stn	Vinyl tiles	Asbestos	Surveyed - Not Detected				Floor Tiles					
12390	ACTIVE	N	N177-00-2/732	CER - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15227	ACTIVE	N	N177-00-2/732	CER - Station Building - Morden Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
12391	ACTIVE	N	N177-00-2/746	SCR - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15228	ACTIVE	N	N177-00-2/746	SCR - Station Building - Morden Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12392	ACTIVE	N	N177-00-2/762	Equipment Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15229	ACTIVE	N	N177-00-2/762	Equipment Room - Station Building - Morden Stn	Westing house Boxes	Asbestos	Strongly Presumed				Small Westinhouse Box to external/rear of 2/762 (Trackside) No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
18556	ACTIVE	N	N177-00-2/762	Equipment Room - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible; Recently Refurbished 2013/14;					
44964	ACTIVE	N	N177-00-2/771	Pump Room - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				Green & cream paint to walls				N	N
44963	ACTIVE	N	N177-00-2/771/CLG-01	Ceiling: Solid - 1 - Pump - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				Cream paint to ceiling				N	N
12393	ACTIVE	N	N177-00-2/951	Disused Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15230	ACTIVE	N	N177-00-2/951	Disused Room - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible; Recently Refurbished 2013/14;					
15231	ACTIVE	N	N177-00-2/951	Disused Room - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				East wall matt brown paint - encapsulated. Project have skimmed wall with plaster					
12394	ACTIVE	N	N177-00-A/081	Lobby - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
18009	INACTIVE	N	N177-00-A/081/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard Tiles above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free				YES	
15232	INACTIVE	N	N177-00-A/081/FLR-01	Floor - 1 - Lobby - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					YES
12395	ACTIVE	N	N177-00-A/082	Lobby - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15234	INACTIVE	N	N177-00-A/082/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard Tiles above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free				YES	



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor	
15233	INACTIVE	N	N177-00-A/082/FLR-01	Floor - 1 - Lobby - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					YES	
12396	ACTIVE	N	N177-00-A/083	Lobby - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed										
12397	ACTIVE	N	N177-00-A/084	Lobby - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed										
12398	ACTIVE	N	N177-00-A/085	Lobby - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed										
12399	ACTIVE	N	N177-00-A/086	Lobby - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed										
12400	ACTIVE	N	N177-00-A/087	Lobby - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed										
12401	ACTIVE	N	N177-00-A/236	Passage - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free						
15236	INACTIVE	N	N177-00-A/236/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard Tiles above Polystyrene Tiles /This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free				YES		
15235	INACTIVE	N	N177-00-A/236/FLR-01	Floor - 1 - Passage - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					YES	
12402	ACTIVE	N	N177-00-A/237	Passage - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free						
15237	INACTIVE	N	N177-00-A/237/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free						



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12403	ACTIVE	N	N177-00-A/316	Locker Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15238	INACTIVE	N	N177-00-A/316/CLG-01	Ceiling: Solid - 1 - Locker Room - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard Tiles above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free				YES	
18010	INACTIVE	N	N177-00-A/316/FLR-01	Floor - 1 - Locker Room - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					YES
12404	ACTIVE	N	N177-00-A/317	Locker Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12405	ACTIVE	N	N177-00-A/318	Locker Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12406	ACTIVE	N	N177-00-A/319	Locker Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12407	ACTIVE	N	N177-00-A/331	Mess Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15240	INACTIVE	N	N177-00-A/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard above Plasterboard False Ceiling / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free				YES	
15239	INACTIVE	N	N177-00-A/331/FLR-01	Floor - 1 - Mess Room - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					YES
12408	ACTIVE	N	N177-00-A/332	Mess Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
18011	INACTIVE	N	N177-00-A/332	Mess Room - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15242	INACTIVE	N	N177-00-A/332/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard above Plasterboard False Ceiling / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free				YES	
15241	INACTIVE	N	N177-00-A/332/FLR-01	Floor - 1 - Mess Room - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					YES
12409	ACTIVE	N	N177-00-A/406	Store - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15243	INACTIVE	N	N177-00-A/406/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Above Fibreboard Ceiling / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
18473	INACTIVE	N	N177-00-A/406/FLR-01	Floor - 1 - Store - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Rubber Flooring / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					YES
12410	ACTIVE	N	N177-00-A/411	Store - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
18012	INACTIVE	N	N177-00-A/411/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Above Fibreboard Ceiling / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15244	INACTIVE	N	N177-00-A/411/FLR-01	Floor - 1 - Store - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Rubber Flooring / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					YES
12411	ACTIVE	N	N177-00-A/412	Store - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15245	INACTIVE	N	N177-00-A/412/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12412	ACTIVE	N	N177-00-A/416	Toilet: Female - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
18167	INACTIVE	N	N177-00-A/416/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard Tiles above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free				YES	
18579	INACTIVE	N	N177-00-A/416/FLR-01	Floor - 1 - Toilet - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					YES
12413	ACTIVE	N	N177-00-A/417	Shower Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15247	INACTIVE	N	N177-00-A/417/CLG-01	Ceiling: Solid - 1 - Shower Room - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard Tiles above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free				YES	
15246	INACTIVE	N	N177-00-A/417/FLR-01	Floor - 1 - Shower Room - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					YES
12414	ACTIVE	N	N177-00-A/418	Toilet: Male - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
18013	INACTIVE	N	N177-00-A/418/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard Tiles above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free				YES	
15248	INACTIVE	N	N177-00-A/418/FLR-01	Floor - 1 - Toilet - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					YES
12415	ACTIVE	N	N177-00-A/419	Toilet: Female - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15249	INACTIVE	N	N177-00-A/419/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard Tiles above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free				YES	
18557	INACTIVE	N	N177-00-A/419/FLR-01	Floor - 1 - Toilet - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					YES
12416	ACTIVE	N	N177-00-A/420	Toilet: Male - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12417	ACTIVE	N	N177-00-A/421	Shower Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12418	ACTIVE	N	N177-00-A/422	Shower Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12419	ACTIVE	N	N177-00-A/423	Shower Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12420	ACTIVE	N	N177-00-A/424	Shower Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12421	ACTIVE	N	N177-00-A/425	Shower Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12422	ACTIVE	N	N177-00-A/576	Stairs: Linear - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15251	INACTIVE	N	N177-00-A/576/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Above Fibreboard Ceiling / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
18014	INACTIVE	N	N177-00-A/576/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Above Fibreboard Ceiling / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15250	INACTIVE	N	N177-00-A/576/FLR-01	Floor - 1 - Linear Stairs - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Rubber Flooring / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					YES



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12423	ACTIVE	N	N177-00-A/661	Switch Cupboard - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15252	INACTIVE	N	N177-00-A/661/FLR-01	Floor - 1 - Switch Cupboard - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Rubber Flooring / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					YES
12424	ACTIVE	N	N177-00-A/761	Equipment Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15253	INACTIVE	N	N177-00-A/761/CLG-01	Ceiling: Solid - 1 - Equipment Room - Station Building - Morden Stn	Boarding: Supalux	Asbestos	Surveyed - Not Detected				Ceiling Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15254	INACTIVE	N	N177-00-A/761/CLG-01	Ceiling: Solid - 1 - Equipment Room - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Above Supalux Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
12425	ACTIVE	N	N177-00-A/801	Office - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
18168	INACTIVE	N	N177-00-A/801/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
12426	ACTIVE	N	N177-00-A/802	Office - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
18015	INACTIVE	N	N177-00-A/802/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Morden Stn	Void	Asbestos	Surveyed - Not Detected				Plasterboard Tiles above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free				YES	
18580	INACTIVE	N	N177-00-A/802/FLR-01	Floor - 1 - Office - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					YES



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12427	ACTIVE	N	N177-00-A/803	Office - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15255	INACTIVE	N	N177-00-A/803/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard Tiles above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free				YES	
12428	ACTIVE	N	N177-00-A/901	Store - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12429	ACTIVE	N	N177-00-A/902	Store - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12430	ACTIVE	N	N177-00-A/903	Store - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12431	ACTIVE	N	N177-00-A/904	Store - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12432	ACTIVE	N	N177-00-A/905	Shower Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12433	ACTIVE	N	N177-00-B/576	Stairs: Linear - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					
15256	INACTIVE	N	N177-00-B/576/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Morden Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard Tiles above Polystyrene Tiles / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free				YES	
18558	INACTIVE	N	N177-00-B/576/FLR-01	Floor - 1 - Linear Stairs - Station Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath Metal False Floor / This room is part of Garth House, which is the Train Crew Accommodation at Morden. This building was constructed in the early 2000s and deemed to be asbestos free					YES
12434	ACTIVE	N	N177-00-B/776	Plant Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43405	ACTIVE	N	N177-00/ROF-01	Structure: Roof - 1 - Station Building - Morden Stn		Asbestos	Sampled – Not Detected				Plastic cables, metal conduits and cable management system and fire stop and mastic - new throughout			559476		
43402	ACTIVE	N	N177-00/ROF-01	Structure: Roof - 1 - Station Building - Morden Stn		Asbestos	Sampled – Not Detected				Asphalt on concrete slab 60m2 to roof			R559476		



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43403	ACTIVE	N	N177-00/ROF-01	Structure: Roof - 1 - Station Building - Morden Stn		Asbestos	Sampled – Not Detected				Fibre glass water tank - with MMMF to roof			R559476		
43404	ACTIVE	N	N177-00/ROF-01	Structure: Roof - 1 - Station Building - Morden Stn		Asbestos	Sampled – Not Detected				Roof 1 - Brickwork to walls			R559476		
15134	ACTIVE	N	N177-00/ROF-01	Structure: Roof - 1 - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				Painted structural beams supporting the roof					
43410	ACTIVE	N	N177-00/ROF-02	Structure: Roof - 2 - Station Building - Morden Stn	Mastic	Asbestos	Sampled – Not Detected				Plastic cables, metal conduits and cable management system and firestop and mastic - new throughout			R559476		
43406	ACTIVE	N	N177-00/ROF-02	Structure: Roof - 2 - Station Building - Morden Stn	Bitumen	Asbestos	Sampled – Not Detected				Bitumen on concrete 30m2 to sides and under paving slab to roof	30		R559476		
43411	ACTIVE	N	N177-00/ROF-02	Structure: Roof - 2 - Station Building - Morden Stn		Asbestos	Sampled – Not Detected				Plastic and metal pipework - MMMF /foam insulation throughout			R559476		
43409	ACTIVE	N	N177-00/ROF-02	Structure: Roof - 2 - Station Building - Morden Stn	Ducts	Asbestos	Sampled – Not Detected				A/C Ductwork - new with MMMF insulation throughout			R559476		
43407	ACTIVE	N	N177-00/ROF-02	Structure: Roof - 2 - Station Building - Morden Stn		Asbestos	Sampled – Not Detected				Roof 2 - Brickwork to walls			R559476		
43408	ACTIVE	N	N177-00/ROF-02	Structure: Roof - 2 - Station Building - Morden Stn	Bitumen	Asbestos	Sampled – Not Detected				Stone slab on foam on bitumen on concrete to floor			R559476		
15135	ACTIVE	N	N177-00/ROF-02	Structure: Roof - 2 - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				Painted structural beams supporting the roof					
43412	ACTIVE	N	N177-00/ROF-03	Structure: Roof - 3 - Station Building - Morden Stn		Asbestos	Sampled – Not Detected				Asphalt on concrete 20m2 to floor			R559476		
43416	ACTIVE	N	N177-00/ROF-03	Structure: Roof - 3 - Station Building - Morden Stn		Asbestos	Sampled – Not Detected				Plastic cables, metal conduits and cable management system and firestop and mastic - new throughout			R559476		
43415	ACTIVE	N	N177-00/ROF-03	Structure: Roof - 3 - Station Building - Morden Stn		Asbestos	Sampled – Not Detected				Wooden fascia board to edge of roof 1 side			R559476		
43413	ACTIVE	N	N177-00/ROF-03	Structure: Roof - 3 - Station Building - Morden Stn		Asbestos	Sampled – Not Detected				Brickwork to walls			R559476		
43414	ACTIVE	N	N177-00/ROF-03	Structure: Roof - 3 - Station Building - Morden Stn		Asbestos	Sampled – Not Detected				Wood door and framework to walls			R559476		
18546	ACTIVE	N	N177-00/ROF-03	Structure: Roof - 3 - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				Painted structural beams supporting the roof					
18226	ACTIVE	N	N177-00/ROF-04	Structure: Roof - 4 - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				Painted structural beams supporting the roof					
43401	ACTIVE	N	N177-00/ROF-05	Structure: Roof - 5 - Station Building - Morden Stn	Mastic	Asbestos	Sampled – Not Detected				Plastic cables, metal conduits and cable management system and fire stop and mastic - new throughout			R559476		
43400	ACTIVE	N	N177-00/ROF-05	Structure: Roof - 5 - Station Building - Morden Stn		Asbestos	Sampled – Not Detected				Brickwork to walls			R559476		



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43399	ACTIVE	N	N177-00/ROF-05	Structure: Roof - 5 - Station Building - Morden Stn		Asbestos	Sampled – Not Detected				New skylight - plastic to roof			R559476		
15136	ACTIVE	N	N177-00/ROF-05	Structure: Roof - 5 - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				Painted structural beams supporting the roof					
43388	ACTIVE	N	N177-00/ROF-06	Structure: Roof - 6 - Station Building - Morden Stn	Boarding: Cement	Asbestos	Removed				Cement panel 2 no2m to either sides of skylight (above entrance lobby) Replaced with new supalux material recently	2		R559476	Y	N
43565	ACTIVE	N	N177-00/ROF-06	Structure: Roof - 6 - Station Building - Morden Stn		Asbestos	Sampled – Not Detected				Cement pipe/duct to roof 6 location 9 on photo			R564776	N	N
43386	ACTIVE	N	N177-00/ROF-06	Structure: Roof - 6 - Station Building - Morden Stn	Glazing Rope	Asbestos	Presumed				Rope 3 bars Within glazing bar to skylight. No access to sample without risking smashing glass. To be inspected when glazing removed			R559476		
43390	ACTIVE	N	N177-00/ROF-06	Structure: Roof - 6 - Station Building - Morden Stn		Asbestos	Sampled – Not Detected				Fibre glass water tanks - with MMMF insulation 3no to roof			R559476		
43389	ACTIVE	N	N177-00/ROF-06	Structure: Roof - 6 - Station Building - Morden Stn	Pipe Lagging	Asbestos	Sampled – Not Detected				Plastic and metal pipework - some with MMMF/ foam insulation throughout			R559476	Y	N
43387	ACTIVE	N	N177-00/ROF-06	Structure: Roof - 6 - Station Building - Morden Stn	Bitumen	Asbestos	Sampled – Not Detected				White Roof tile 10no on top of bitumen roof felt where edge protection guards area			R559476		
Y	INACTIVE	N	N177-00/ROF-06	Structure: Roof - 6 - Station Building - Morden Stn	Cement Troughing	Asbestos	Known				Cement Panel 2 no 2m to either sides of Skylight (above entrance lobby)	2		R559476	Y	N
43391	ACTIVE	N	N177-00/ROF-06	Structure: Roof - 6 - Station Building - Morden Stn		Asbestos	Sampled – Not Detected				Asphalt on wood 140m2 to roof - south side	140		R559476		
43421	ACTIVE	N	N177-00/ROF-06	Structure: Roof - 6 - Station Building - Morden Stn	Boarding: Cement	Asbestos	Presumed				Roof 6 - Cement Panel fascia boards to side of roof Undercloaking to sides of roof not panels to skylights as per previous report.			R559476		
19165	ACTIVE	N	N177-00/ROF-06	Structure: Roof - 6 - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				Painted structural beams supporting the roof					
43393	ACTIVE	N	N177-00/ROF-07	Structure: Roof - 7 - Station Building - Morden Stn	Roofing Tiles	Asbestos	Known				Ridge tiles on top of rubber 40m to centre of pitched roof			R559476		
43564	ACTIVE	N	N177-00/ROF-07	Structure: Roof - 7 - Station Building - Morden Stn	Roofing Tiles	Asbestos	Sampled – Not Detected				Slate roof tiles, throughout to roof 7, location 1 to 8 on photo			R564776	N	N
43392	ACTIVE	N	N177-00/ROF-07	Structure: Roof - 7 - Station Building - Morden Stn	Roofing Tiles	Asbestos	Sampled – Not Detected				Roof tile 180m2 to pitched roof	180		R559476		
43396	ACTIVE	N	N177-00/ROF-07	Structure: Roof - 7 - Station Building - Morden Stn		Asbestos	Sampled – Not Detected				Asphalt on brickwork 40m to side of roof (east)	40		R559476		
43394	ACTIVE	N	N177-00/ROF-07	Structure: Roof - 7 - Station Building - Morden Stn	Roofing Tiles	Asbestos	Sampled – Not Detected				Cement under cloaking 12m to edge under roof tile			R559476		



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43639	ACTIVE	N	N177-00/ROF-07	Structure: Roof - 7 - Station Building - Morden Stn		Asbestos	Surveyed – Not Detected				Slate roof tiles throughout to roof 7			R564776	N	N
43398	ACTIVE	N	N177-00/ROF-07	Structure: Roof - 7 - Station Building - Morden Stn		Asbestos	Sampled – Not Detected				Brickwork to sides			R559476		
43395	ACTIVE	N	N177-00/ROF-07	Structure: Roof - 7 - Station Building - Morden Stn	Boarding: Cement	Asbestos	Known				Cement panels on top of wood 1 no 4m2 to lighting post to top of roof Damaged to bottom panel missing corner section			R559476		
43397	ACTIVE	N	N177-00/ROF-07	Structure: Roof - 7 - Station Building - Morden Stn	Roofing Tiles	Asbestos	Sampled – Not Detected				Roof tiles on wood 180m2 under roof tiles	180		R559476		
15137	ACTIVE	N	N177-00/ROF-07	Structure: Roof - 7 - Station Building - Morden Stn	Lead/Leading	Lead Paint/Lead	Known				Painted structural beams supporting the roof					
12385	ACTIVE	N	N177-03-2/664	Switch Room - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15218	ACTIVE	N	N177-03-2/664/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Morden Stn	Other Boarding	Asbestos	Presumed				Paxoline Boarding various locations					
17943	ACTIVE	N	N177-03-2/664/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Morden Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes - Insulation within 100amp No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1			
15221	INACTIVE	N	N177-03-2/664/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Morden Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				10 x PCB's - fair Condition - serial numbers 197448, 197441, 186348, 186597, 38555, 168264, 197409, 36908, 186603, 186551.165254, 30905 1 x black cyclinder, 1 x medium silver cyclinder, 2 x small silver cyclinder, 3 x blue cyclinder PCB's - wall mounted		17		N	N
15219	ACTIVE	N	N177-03-2/664/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Morden Stn	Other Boarding	Asbestos	Presumed				Paxoline Boarding various locations					
15220	ACTIVE	N	N177-03-2/664/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Morden Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Westinghouse Boxes - Insulation within No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		3			
15079	ACTIVE	N	N177-05-1/447	Bicycle Shed - Signals Building - Morden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
12329	ACTIVE	N	N177-07-1/662	Switch Cupboard - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19543	ACTIVE	N	N177-07-1/662/FLR-01 80886386	Floor - 1 - Switch Cupboard - Station Building - Morden Stn	Cable Ducts: Cement Floor	Asbestos	Presumed				Cable Ducts Cement					



# Hazardous Material Asset Register - Summary



## N177-00 - Station Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15120	ACTIVE	N	N177-07-1/662/FLR-01	Floor - 1 - Switch Cupboard - Station Building - Morden Stn	Cable: Sheath	Asbestos	Presumed				Mains Cable		1			
12331	ACTIVE	N	N177-07-1/664	Switch Cupboard - Station Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
15122	ACTIVE	N	N177-07-1/664	Switch Cupboard - Station Building - Morden Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					

## X132-01 - ERU - Camden Town

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14865	ACTIVE	N	X132-01-1/317	Workshop - ERU - Camden Town	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
14866	ACTIVE	N	X132-01-1/661	Switch Room - ERU - Camden Town	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
14867	ACTIVE	N	X132-01-1/801	Office - ERU - Camden Town	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
14868	ACTIVE	N	X132-01-A/047	Mess Room - ERU - Camden Town	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
14869	ACTIVE	N	X132-01-A/331	Mess Room - ERU - Camden Town	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									

## N021-01 - Signal Cabin - Edgware Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8322	ACTIVE	N	N021-01-0/576	Stairs: Linear - Signal Cabin - Edgware Stn	Stations: Rooms	Asbestos	Room: Asbestos Free									
8323	ACTIVE	N	N021-01-0/577	Stairs: Linear - Signal Cabin - Edgware Stn	Stations: Rooms	Asbestos	Room: Asbestos Free									
8324	ACTIVE	N	N021-01-0/706	IMR - Signal Cabin - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
25839	ACTIVE	N	N021-01-0/706	IMR - Signal Cabin - Edgware Stn	Vinyl tiles	Asbestos	Presumed				Green / Grey Vinyl tiles on Walls & Ceilings					
25841	ACTIVE	N	N021-01-0/706	IMR - Signal Cabin - Edgware Stn	Other Boarding	Asbestos	Presumed				Paxoline board					



# Hazardous Material Asset Register - Summary



## N021-01 - Signal Cabin - Edgware Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8325	ACTIVE	N	N021-01-0/707	IMR - Signal Cabin - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
8326	ACTIVE	N	N021-01-0/951	Disused Room - Signal Cabin - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
25840	ACTIVE	N	N021-01-0/951	Disused Room - Signal Cabin - Edgware Stn	Vinyl tiles	Asbestos	Presumed				Green / Grey Vinyl tiles on Walls & Ceilings					
8240	ACTIVE	N	N021-01-1/083	Lobby - Signal Cabin - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed - No Known Asbestos									
19840	INACTIVE	N	N021-01-1/083	Lobby - Signal Cabin - Edgware Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
44859	ACTIVE	N	N021-01-1/083/WAL-001	Wall: Internal - 1 - Lobby - Signal Cabin - Edgware Stn	Cable Wrap	Asbestos	Presumed				Black Braided Cable to window wall 1, 1st window					
19676	ACTIVE	N	N021-01-1/083/WDW-01	Window - 1 - Lobby - Signal Cabin - Edgware Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Lead Paint on Crittle Windows					
19432	ACTIVE	N	N021-01-1/083/WDW-02	Window - 2 - Lobby - Signal Cabin - Edgware Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Lead Paint on Crittle Windows					
8255	ACTIVE	N	N021-01-1/366	Mess Room - Signal Cabin - Edgware Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19904	INACTIVE	N	N021-01-1/366	Mess Room - Signal Cabin - Edgware Stn	No Access	Asbestos	Surveyed - Not Detected				Not Surveyed - New Room					
19913	ACTIVE	N	N021-01-1/366/WAL-002	Wall: Internal - 2 - Mess Room - Signal Cabin - Edgware Stn	Bitumen	Asbestos	Sampled - Not Detected				Acoustic Panel below sink - Sampled as part of management survey R643426 - 2019		1			
8268	ACTIVE	N	N021-01-1/419	Toilet: Unisex - Signal Cabin - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
19449	ACTIVE	N	N021-01-1/419	Toilet: Unisex - Signal Cabin - Edgware Stn	Cement Cowlings/Flues	Asbestos	Removed				Flues - to disused cooker hoods					
19912	ACTIVE	N	N021-01-1/419	Toilet: Unisex - Signal Cabin - Edgware Stn	Lead/Leading	Lead Paint/Lead	Strongly Presumed				Lead Paint on Crittle Windows					
8277	ACTIVE	N	N021-01-1/708	IMR - Signal Cabin - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
19920	INACTIVE	N	N021-01-1/708	IMR - Signal Cabin - Edgware Stn		Asbestos	Surveyed - Not Detected				No Asbestos Visible					
25842	ACTIVE	N	N021-01-1/708	IMR - Signal Cabin - Edgware Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer box - Insulation within		1			
44869	ACTIVE	N	N021-01-1/708	IMR - Signal Cabin - Edgware Stn	Bitumen	Asbestos	Strongly Presumed				Adhesive to Green & Grey tiles on Walls				N	N



# Hazardous Material Asset Register - Summary



## N021-01 - Signal Cabin - Edgware Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44874	ACTIVE	N	N021-01-1/708	IMR - Signal Cabin - Edgware Stn	Cable Wrap	Asbestos	Presumed				Green Braided Cable throughout to wall high level and framework					
25843	ACTIVE	N	N021-01-1/708	IMR - Signal Cabin - Edgware Stn	Vinyl tiles	Asbestos	Presumed				Green / Grey Vinyl tiles on Walls & Ceilings					
44870	ACTIVE	N	N021-01-1/708/WAL-001	Wall: Internal - 1 - IMR - Signal Cabin - Edgware Stn		Asbestos	Strongly Presumed				Brown Composite Panel and Packing				N	N
44872	ACTIVE	N	N021-01-1/708/WAL-001	Wall: Internal - 1 - IMR - Signal Cabin - Edgware Stn	Rope Gaskets	Asbestos	Strongly Presumed				2x Gaskets to metal tube electric heater		2		N	N
44871	ACTIVE	N	N021-01-1/708/WAL-003	Wall: Internal - 3 - IMR - Signal Cabin - Edgware Stn		Asbestos	Strongly Presumed				Brown Composite Panel and Packing				N	N
44873	ACTIVE	N	N021-01-1/708/WAL-006	Wall: Internal - 6 - IMR - Signal Cabin - Edgware Stn	Rope Gaskets	Asbestos	Strongly Presumed				2x Gaskets to metal tube electric heater		2		N	N
8286	ACTIVE	N	N021-01-2/047	Kitchen - Signal Cabin - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
19970	ACTIVE	N	N021-01-2/047/CLG-01	Ceiling: Suspended - 1 - Kitchen - Signal Cabin - Edgware Stn	Void	Asbestos	No Access: Presumed				Above Supalux				YES	
19969	ACTIVE	N	N021-01-2/047/CLG-01	Ceiling: Suspended - 1 - Kitchen - Signal Cabin - Edgware Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Supalux					
44875	ACTIVE	N	N021-01-2/047/FLR-01	Floor - 1 - Kitchen - Station Building - Edgware Stn	Vinyl tiles	Asbestos	Known				Vinyl Tiles to floor				N	N
44876	ACTIVE	N	N021-01-2/047/FLR-01	Floor - 1 - Kitchen - Station Building - Edgware Stn	Bitumen	Asbestos	Known				Adhesive to floor under tile				N	N
8298	ACTIVE	N	N021-01-2/332	Store - Signal Cabin - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
19982	ACTIVE	N	N021-01-2/332/DOR-01	Door - 1 - Store - Signal Cabin - Edgware Stn	Boarding: Cement	Asbestos	Removed				Cement Panel above disused doorway under stairs 2/576 leading to 2/333. Removed by the Licensed Asbestos Removal Contractor EMS					
8299	ACTIVE	N	N021-01-2/333	Mess Room - Signal Cabin - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
19981	ACTIVE	N	N021-01-2/333/CLG-01	Ceiling: Suspended - 1 - Mess Room - Signal Cabin - Edgware Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Supalux					
19507	ACTIVE	N	N021-01-2/333/CLG-01	Ceiling: Suspended - 1 - Mess Room - Signal Cabin - Edgware Stn	Void	Asbestos	No Access: Presumed				Above Supalux				YES	
44867	ACTIVE	N	N021-01-2/333/FLR-01	Floor - 1 - Mess Room - Signal Cabin - Edgware Stn	Vinyl tiles	Asbestos	Known				Vinyl Tiles to floor				N	N



# Hazardous Material Asset Register - Summary



## N021-01 - Signal Cabin - Edgware Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44868	ACTIVE	N	N021-01-2/333/FLR-01	Floor - 1 - Mess Room - Signal Cabin - Edgware Stn	Bitumen	Asbestos	Known				Adhesive to floor under tile				N	N
8306	ACTIVE	N	N021-01-2/576	Stairs: Linear - Signal Cabin - Edgware Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
19988	INACTIVE	N	N021-01-2/576	Stairs: Linear - Signal Cabin - Edgware Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					

## N022-01 - Disused Room - Disused Building - Edgware To Burnt Oak

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8327	ACTIVE	N	N022-01-0/952	Disused Room - Disused Building - Edgware To Burnt Oak	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20052	ACTIVE	N	N022-01-0/952	Disused Room - Disused Building - Edgware To Burnt Oak		Asbestos	Surveyed – Not Detected				No Asbestos Visible					

## N022-02 - Signals Building - Edgware To Burnt Oak

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8328	ACTIVE	N	N022-02-0/661	Switch Room - Signals Building - Edgware To Burnt Oak	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8329	ACTIVE	N	N022-02-0/711	SER - Signals Building - Edgware To Burnt Oak	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20051	ACTIVE	N	N022-02-0/711	SER - Signals Building - Edgware To Burnt Oak	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - deemed to be Asbestos free					

## N022-03 - P Way Accommodation - Edgware To Burnt Oak

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8330	ACTIVE	N	N022-03-0/081	Lobby - P Way Accommodation - Edgware To Burnt Oak	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8331	ACTIVE	N	N022-03-0/416	Toilet: Unisex - P Way Accommodation - Edgware To Burnt Oak	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8332	ACTIVE	N	N022-03-0/701	Equipment Room - P Way Accommodation - Edgware To Burnt Oak	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N022-05 - Traction Control Cabin - Edgware To Burnt Oak

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8334	ACTIVE	N	N022-05-0/661	Equipment Room - Traction Control Cabin - Edgware To Burnt Oak	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N023-01 - Signals Building - Burnt Oak Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8367	ACTIVE	N	N023-01-0/711	SER - Signals Building - Burnt Oak Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N025-01 - Signals Building - Colindale Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8400	ACTIVE	N	N025-01-1/731	CER - Signals Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N025-02 - Signals Building - Colindale Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8401	ACTIVE	N	N025-02-1/711	SER - Signals Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N025-03 - Signals Building - Colindale Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8402	ACTIVE	N	N025-03-2/706	IMR - Signals Building - Colindale Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19708	ACTIVE	N	N025-03-2/706	IMR - Signals Building - Colindale Stn	Cable: Sheath	Asbestos	Strongly Presumed				Cables - External to IMR - Encapsulated		2			
19709	ACTIVE	N	N025-03-2/706	IMR - Signals Building - Colindale Stn	Cable: Sheath	Asbestos	Strongly Presumed				4x 35mm Cables within J hanger to wall 3 leading outside to Track		4			



# Hazardous Material Asset Register - Summary



## N031-01 - Signals Building - Hendon Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8473	ACTIVE	N	N031-01-0/711	SER - Signals Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19615	ACTIVE	N	N031-01-0/711	SER - Signals Building - Hendon Central Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					

## N031-02 - Signals Building - Hendon Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8474	ACTIVE	N	N031-02-2/706	IMR - Signals Building - Hendon Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N032-01 - Store - Hendon Central To Brent Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8476	ACTIVE	N	N032-01-0/411	Store Room - Store - Hendon Central To Brent Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N032-02 - Electrical Building - Hendon Central To Brent Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8477	ACTIVE	N	N032-02-0/711	Relay Room - Electrical Building - Hendon Central To Brent Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8478	ACTIVE	N	N032-02-0/781	Substation Room - Electrical Building - Hendon Central To Brent Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N033-01 - Signals Building - Brent Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8509	ACTIVE	N	N033-01-1/711	SER - Signals Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N033-02 - Signals Building - Brent Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8510	ACTIVE	N	N033-02-0/732	CER - Signals Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N033-03 - Signals Building - Brent Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8511	ACTIVE	N	N033-03-0/731	CER - Signals Building - Brent Cross Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
17880	ACTIVE	N	N033-03-0/731	CER - Signals Building - Brent Cross Stn	No Access	Asbestos	Surveyed – Not Detected				CER near the platforms was constructed Post 2000 and considered asbestos free					

## N041-01 - Signals Building - Golders Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8626	ACTIVE	N	N041-01-0/711	SER - Signals Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46274	ACTIVE	N	N041-01-0/711	SER - Signals Building - Golders Green Stn		Asbestos	Strongly Presumed				see Premises Survey				N	N

## N041-02 - Signals Building - Golders Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8627	ACTIVE	N	N041-02-1/662	Switch Room - Signals Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
41912	ACTIVE	N	N041-02-1/662/WAL-001	Wall: Internal - 1 - Switch Room - Signals Building - Golders Green Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N
41911	ACTIVE	N	N041-02-1/662/WAL-001	Wall: Internal - 1 - Switch Room - Signals Building - Golders Green Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x Switch Box - insulation within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		1		N	N



# Hazardous Material Asset Register - Summary



## N041-03 - Locker Block - Golders Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8628	ACTIVE	N	N041-03-1/316	Locker Room - Locker Block - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8629	ACTIVE	N	N041-03-1/416	Shower Room - Locker Block - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8630	ACTIVE	N	N041-03-1/417	Shower Room - Locker Block - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8631	ACTIVE	N	N041-03-1/418	Toilet: Unisex - Locker Block - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8632	ACTIVE	N	N041-03-A/316	Locker Room - Locker Block - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8633	ACTIVE	N	N041-03-A/416	Shower Room - Locker Block - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8634	ACTIVE	N	N041-03-A/417	Shower Room - Locker Block - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8635	ACTIVE	N	N041-03-A/418	Toilet: Unisex - Locker Block - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8636	ACTIVE	N	N041-03-A/576	Stairs: Linear - Locker Block - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N041-04 - Signals Building - Golders Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8637	ACTIVE	N	N041-04-1/732	CER - Signals Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N041-05 - Signals Building - Golders Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46273	ACTIVE	N	N041-05-0/706	IMR - Signals Building - Golders Green Stn		Asbestos	Strongly Presumed				see Premises Survey				N	N



# Hazardous Material Asset Register - Summary



## N042-02 - Store - Golders Green To Hampstead

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8638	ACTIVE	N	N042-02-0/571	Store Room - Store - Golders Green To Hampstead	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N042-03 - Office Building - Golders Green To Hampstead

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8639	ACTIVE	N	N042-03-A/683	Office - Office Building - Golders Green To Hampstead	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N042-04 - Signals Building - Golders Green To Hampstead

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8640	ACTIVE	N	N042-04-1/706	IMR - Signals Building - Golders Green To Hampstead	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8641	ACTIVE	N	N042-04-1/731	IMR - Signals Building - Golders Green To Hampstead	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N042-05 - Signal Cabin - Golders Green To Hampstead

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8642	ACTIVE	N	N042-05-1/661	Switch Room - Signal Cabin - Golders Green To Hampstead	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8643	ACTIVE	N	N042-05-1/662	Switch Room - Signal Cabin - Golders Green To Hampstead	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8644	ACTIVE	N	N042-05-A/047	Kitchen - Signal Cabin - Golders Green To Hampstead	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8645	ACTIVE	N	N042-05-A/081	Lobby - Signal Cabin - Golders Green To Hampstead	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8646	ACTIVE	N	N042-05-A/416	Toilet: Unisex - Signal Cabin - Golders Green To Hampstead	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8647	ACTIVE	N	N042-05-A/801	Signals Office - Signal Depot - Golders Green To Hampstead	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N042-06 - Union Office - Golders Green To Hampstead

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8648	ACTIVE	N	N042-06-A/047	Kitchen - Union Office - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8649	ACTIVE	N	N042-06-A/081	Lobby - Union Office - Golders Green To Hampstead	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8650	ACTIVE	N	N042-06-A/416	Toilet: Unisex - Union Office - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8651	ACTIVE	N	N042-06-A/801	Union Office - Office Building - Golders Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N043-01 - Substation - Hampstead Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8738	ACTIVE	N	N043-01-1/781	Transformer Room - Substation - Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N053-01 - Signals Building - Mill Hill East Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8916	ACTIVE	N	N053-01-0/731	CER - Signals Building - Mill Hill East Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N054-01 - Signals Building - Mill Hill East To Finchley Central

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8917	ACTIVE	N	N054-01-0/711	SER - Signals Building - Mill Hill East To Finchley Central	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N061-01 - Signals Building - High Barnet Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8988	ACTIVE	N	N061-01-2/731	CER - Signals Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17895	ACTIVE	N	N061-01-2/731	CER - Signals Building - High Barnet Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					



# Hazardous Material Asset Register - Summary



## N061-02 - Signals Building - High Barnet Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8989	ACTIVE	N	N061-02-2/711	SER - Signals Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8990	ACTIVE	N	N061-02-2/731	SER - Signals Building - High Barnet Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N062-02 - Signals Building - High Barnet To Totteridge & Whetstone

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8991	ACTIVE	N	N062-02-1/731	CER - Signals Building - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8992	ACTIVE	N	N062-02-A/706	IMR - Signals Building - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42244	ACTIVE	N	N062-02-A/706	IMR - Signals Building - High Barnet To Totteridge & Whetstone	Cable Ducts: Cement	Asbestos	Surveyed – Not Detected				Packing to concrete ducts within IMR / Relay room A - none detected				N	N

## N062-03 - Abrams House - High Barnet To Totteridge & Whetstone

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8993	ACTIVE	N	N062-03-1/047	Kitchen - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8994	ACTIVE	N	N062-03-1/053	Mess Room - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8995	ACTIVE	N	N062-03-1/081	Lobby - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8996	ACTIVE	N	N062-03-1/082	Lobby - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8997	ACTIVE	N	N062-03-1/083	Lobby - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8998	ACTIVE	N	N062-03-1/084	Lobby - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8999	ACTIVE	N	N062-03-1/316	Locker Room - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N062-03 - Abrams House - High Barnet To Totteridge & Whetstone

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9000	ACTIVE	N	N062-03-1/317	Locker Room - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9001	ACTIVE	N	N062-03-1/318	Locker Room - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9002	ACTIVE	N	N062-03-1/319	Locker Room - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9003	ACTIVE	N	N062-03-1/401	Store - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9004	ACTIVE	N	N062-03-1/406	Store - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9005	ACTIVE	N	N062-03-1/416	Shower Room - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9006	ACTIVE	N	N062-03-1/417	Shower Room - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9007	ACTIVE	N	N062-03-1/418	Toilet: Male - Train Crew Accommodation - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9008	ACTIVE	N	N062-03-1/419	Toilet: Female - Train Crew Accommodation - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9009	ACTIVE	N	N062-03-1/420	Toilet: Unisex - Train Crew Accommodation - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9010	ACTIVE	N	N062-03-1/421	Toilet: Unisex - Train Crew Accommodation - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9011	ACTIVE	N	N062-03-1/422	Toilet - Abrams House - High Barnet to Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9012	ACTIVE	N	N062-03-1/423	Toilet: Unisex - Train Crew Accommodation - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9013	ACTIVE	N	N062-03-1/481	Locker Room - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9014	ACTIVE	N	N062-03-1/482	Locker Room - Abrams House - High Barnet to Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N062-03 - Abrams House - High Barnet To Totteridge & Whetstone

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9015	ACTIVE	N	N062-03-1/576	Stairs: Linear - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9016	ACTIVE	N	N062-03-1/577	Stairs: Linear - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9017	ACTIVE	N	N062-03-1/661	Switch Room - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9018	ACTIVE	N	N062-03-1/767	Service Riser - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9019	ACTIVE	N	N062-03-A/041	Mess Room - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9020	ACTIVE	N	N062-03-A/047	Kitchen - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9021	ACTIVE	N	N062-03-A/081	Lobby - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9022	ACTIVE	N	N062-03-A/082	Lobby - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9023	ACTIVE	N	N062-03-A/083	Lobby - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9024	ACTIVE	N	N062-03-A/084	Lobby - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9025	ACTIVE	N	N062-03-A/086	Lobby - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9026	ACTIVE	N	N062-03-A/316	Locker Room - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9027	ACTIVE	N	N062-03-A/406	Store - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9028	ACTIVE	N	N062-03-A/411	Store - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9029	ACTIVE	N	N062-03-A/412	Store - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N062-03 - Abrams House - High Barnet To Totteridge & Whetstone

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9030	ACTIVE	N	N062-03-A/416	Toilet: Female - Train Crew Accommodation - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9031	ACTIVE	N	N062-03-A/417	Toilet: Unisex - Train Crew Accommodation - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9032	ACTIVE	N	N062-03-A/418	Toilet: Male - Train Crew Accommodation - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9033	ACTIVE	N	N062-03-A/419	Toilet - Abrams House - High Barnet to Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9034	ACTIVE	N	N062-03-A/420	Toilet: Unisex - Train Crew Accommodation - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9035	ACTIVE	N	N062-03-A/421	Shower Room - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9036	ACTIVE	N	N062-03-A/531	DMT Office - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9037	ACTIVE	N	N062-03-A/787	Service Riser - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9038	ACTIVE	N	N062-03-A/801	Interview Room - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9039	ACTIVE	N	N062-03-A/802	Office - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9040	ACTIVE	N	N062-03-B/044	Mess Room - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9041	ACTIVE	N	N062-03-B/081	Lobby - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9042	ACTIVE	N	N062-03-B/082	Lobby - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9043	ACTIVE	N	N062-03-B/236	Passage - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9044	ACTIVE	N	N062-03-B/306	Office - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N062-03 - Abrams House - High Barnet To Totteridge & Whetstone

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9045	ACTIVE	N	N062-03-B/311	Union Office - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9046	ACTIVE	N	N062-03-B/411	Store - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9047	ACTIVE	N	N062-03-B/412	Meeting Room - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9048	ACTIVE	N	N062-03-B/416	Toilet: Female - Train Crew Accommodation - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9049	ACTIVE	N	N062-03-B/417	Toilet: Male - Train Crew Accommodation - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9050	ACTIVE	N	N062-03-B/731	SCR - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9051	ACTIVE	N	N062-03-B/790	Service Riser - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9052	ACTIVE	N	N062-03-B/801	Train Ops Manager Office - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9053	ACTIVE	N	N062-03-B/802	Train Ops Support Manager Office - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9054	ACTIVE	N	N062-03-B/803	Training Room - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9055	ACTIVE	N	N062-03-B/804	Training Room - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9056	ACTIVE	N	N062-03-B/805	Meeting Room - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9057	ACTIVE	N	N062-03-C/776	Plant Room - Abrams House - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N062-05 - Signals Building - High Barnet To Totteridge & Whetstone

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9058	ACTIVE	N	N062-05-2/731	CER - Signals Building - High Barnet To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N064-01 - Signals Building - Totteridge & Whetstone To Woodside Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9092	ACTIVE	N	N064-01-2/731	Relay Room - Signals Building - Woodside Park To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N064-02 - Signals Building - Totteridge & Whetstone To Woodside Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9093	ACTIVE	N	N064-02-2/711	SER - Signals Building - Woodside Park To Totteridge & Whetstone	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N064-03 - Signals Building - Totteridge & Whetstone To Woodside Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9094	ACTIVE	N	N064-03-0/711	SER - Signals Building - Totteridge & Whetstone to Woodside Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46282	ACTIVE	N	N064-03-0/711	SER - Signals Building - Totteridge & Whetstone to Woodside Park	Westinghouse Boxes	Asbestos	Presumed				1x Westinghouse box to rear of building		1			
46277	ACTIVE	N	N064-03-0/711/WAL-002	Wall: Internal - 2 - SER - Signals Building - Totteridge & Whetstone To Woodside Park	Other Electrical Boxes	Asbestos	Strongly Presumed				3x Electrical Equipment		3		N	N
46278	ACTIVE	N	N064-03-0/711/WAL-003	Wall: Internal - 3 - SER - Signals Building - Totteridge & Whetstone To Woodside Park	Westinghouse Boxes	Asbestos	Strongly Presumed				1x Small Westinghouse box		1			
46279	ACTIVE	N	N064-03-0/711/WAL-003	Wall: Internal - 3 - SER - Signals Building - Totteridge & Whetstone To Woodside Park	Cable Duct: Other	Asbestos	Strongly Presumed				1x Cable duct		1		N	N
46281	ACTIVE	N	N064-03-0/711/WAL-004	Wall: Internal - 4 - SER - Signals Building - Totteridge & Whetstone To Woodside Park	Other Boarding	Asbestos	Strongly Presumed				4x Composite Board fuse blocks		4		N	N
46280	ACTIVE	N	N064-03-0/711/WAL-004	Wall: Internal - 4 - SER - Signals Building - Totteridge & Whetstone To Woodside Park	Westinghouse Boxes	Asbestos	Strongly Presumed				1x Small Westinghouse box		1			



# Hazardous Material Asset Register - Summary



## N067-01 - Signals Building - West Finchley Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9153	ACTIVE	N	N067-01-0/661	Switch Room - Signals Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9154	ACTIVE	N	N067-01-0/711	SER - Signals Building - West Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N071-01 - Signals Building - Finchley Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9222	ACTIVE	N	N071-01-0/711	SER - Signals Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N071-02 - Signals Building - Finchley Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9223	ACTIVE	N	N071-02-2/732	CER - Signals Building - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N071-03 - Pump House - Finchley Central Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9224	ACTIVE	N	N071-03-2/771	Pump Room - Pump House - Finchley Central Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25074	ACTIVE	N	N071-03-2/771	Pump Room - Pump House - Finchley Central Stn	Isolator Switches	Asbestos	Presumed				1x Switch box Presumed asbestos insulation within		1		N	N

## N072-02 - Communications Building - Finchley Central To East Finchley

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9226	ACTIVE	N	N072-02-0/741	Telephone Exchange - Communications Building - Finchley Central To East Finchley	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N072-04 - Signal Cabin - Finchley Central To East Finchley

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9227	ACTIVE	N	N072-04-1/081	Lobby - Signal Cabin - Finchley Central To East Finchley	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9228	ACTIVE	N	N072-04-1/576	Stairs: Linear - Signal Cabin - Finchley Central To East Finchley	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9229	ACTIVE	N	N072-04-1/706	IMR - Signal Cabin - Finchley Central To East Finchley	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9230	ACTIVE	N	N072-04-1/711	IMR - Signal Cabin - Finchley Central To East Finchley	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9231	ACTIVE	N	N072-04-1/731	CER - Signal Cabin - Finchley Central To East Finchley	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9232	ACTIVE	N	N072-04-A/706	IMR - Signal Cabin - Finchley Central To East Finchley	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9233	ACTIVE	N	N072-04-A/731	CER - Signal Cabin - Finchley Central To East Finchley	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9234	ACTIVE	N	N072-04-A/771	Store - Signal Cabin - Finchley Central To East Finchley	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N073-01 - Signals Building - East Finchley Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9298	ACTIVE	N	N073-01-0/711	SER - Signals Building - East Finchley Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
17350	ACTIVE	N	N073-01-0/711	SER - Signals Building - East Finchley Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Construction					

## N075-01 - Station Building - Highgate Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9371	ACTIVE	N	N075-01-1/261	Disused Room - Station Building - Highgate Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44169	ACTIVE	N	N075-01-1/261	Disused Room - Station Building - Highgate Disused Stn	Other Boarding	Asbestos	Presumed				Advertising boards located along the platform				N	N



# Hazardous Material Asset Register - Summary



## N075-01 - Station Building - Highgate Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44892	ACTIVE	N	N075-01-1/261	Disused Room - Station Building - Highgate Disused Stn	Other Boarding	Asbestos	Presumed				Advertising Boards along platform				N	N
9372	ACTIVE	N	N075-01-1/262	Disused Room - Station Building - Highgate Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44170	ACTIVE	N	N075-01-1/262	Disused Room - Station Building - Highgate Disused Stn	Other Boarding	Asbestos	Presumed				Advertising boards located along the platform				N	N
44893	ACTIVE	N	N075-01-1/262	Disused Room - Station Building - Highgate Disused Stn	Other Boarding	Asbestos	Presumed				Advertising Boards along platform				N	N
9373	ACTIVE	N	N075-01-1/776	Plant Room - Station Building - Highgate Disused Stn	Stations: Rooms	Asbestos	Room: Surveyed – Asbestos Known									
44895	ACTIVE	N	N075-01-1/776	Plant Room - Station Building - Highgate Disused Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Transformer Box & 1 x 60 amp Switch Box				N	N
42543	ACTIVE	N	N075-01-1/776	Plant Room - Station Building - Highgate Disused Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 60 amp Switch Box No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1		N	N
17168	ACTIVE	N	N075-01-1/776	Plant Room - Station Building - Highgate Disused Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Disused Room - Transformer Box - Fair Condition No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.		1		N	N
44894	ACTIVE	N	N075-01-1/776	Plant Room - Station Building - Highgate Disused Stn	Mastic	Asbestos	Strongly Presumed				Flanges / Mastic within Ductwork				N	N
44168	ACTIVE	N	N075-01-1/776/ WAL-003	Wall: Internal - 3 - Disused Room - Disused Station Building - Highgate Stn	Mastic	Asbestos	Strongly Presumed				Strongly presumed Flanges / Mastic within Ductwork				N	N
9374	ACTIVE	N	N075-01-1/951	Disused Room - Station Building - Highgate Disused Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos				None Visible					
9375	ACTIVE	N	N075-01-1/952	Disused Room - Station Building - Highgate Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9376	ACTIVE	N	N075-01-1/953	CER - Station Building - Highgate Disused Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
42247	ACTIVE	N	N075-01-1/953	CER - Station Building - Highgate Disused Stn		Asbestos	Surveyed – Not Detected				No Asbestos visible					



# Hazardous Material Asset Register - Summary



## N096-01 - Melton Street Vent Shaft - Camden Town To Euston

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
9964	ACTIVE	N	N096-01-1/781	Tunnel Telephone Room - Melton Street Vent Shaft - Camden Town To Euston	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
9965	ACTIVE	N	N096-01-4/781	Plant Room - Melton Street Vent Shaft - Camden Town To Euston	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N124-02 - Substation - Kings Cross To Angel

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10842	ACTIVE	N	N124-02-1/781	Substation Room - Substation - Kings Cross To Angel	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N125-01 - Station Building - Angel Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10917	ACTIVE	N	N125-01-1/081	Lobby - Disused Station Building - Angel Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10918	ACTIVE	N	N125-01-1/083	Lobby - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10919	ACTIVE	N	N125-01-1/240	Passage - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10920	ACTIVE	N	N125-01-1/401	Store - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10921	ACTIVE	N	N125-01-1/411	Store - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10922	ACTIVE	N	N125-01-1/412	Transformer Room - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16682	ACTIVE	N	N125-01-1/412/FLR-01	Floor - 1 - Equipment Room - Disused Station Building - Angel Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Vinyl Tiles - Non Asbestos					
10923	ACTIVE	N	N125-01-1/576	Stairs: Linear - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10924	ACTIVE	N	N125-01-1/631	Stairs: Spiral - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N125-01 - Station Building - Angel Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43968	ACTIVE	N	N125-01-1/631	Stairs: Spiral - Station Building - Angel Disused Stn		Asbestos	Sampled – Not Detected				Bitumen stair treads, disused shaft			R407101	N	N
43969	ACTIVE	N	N125-01-1/631	Stairs: Spiral - Station Building - Angel Disused Stn		Asbestos	Sampled – Not Detected				Caulking, passage at bottom of disused shaft			R407101	N	N
44940	ACTIVE	N	N125-01-1/631	Stairs: Spiral - Station Building - Angel Disused Stn	Lead/Leading	Lead Paint/Lead	Known				Disused Staircase - Top of Stairs - Support Steel - Grey Gloss				N	N
44942	ACTIVE	N	N125-01-1/631	Stairs: Spiral - Station Building - Angel Disused Stn	Lead/Leading	Lead Paint/Lead	Known				Disused Staircase - Bottom of Shaft - Hand Rail Grey Gloss				N	N
44943	ACTIVE	N	N125-01-1/631	Stairs: Spiral - Station Building - Angel Disused Stn	Lead/Leading	Lead Paint/Lead	Known				Disused Staircase - Bottom of Shaft - Single Width Stairs Grey Gloss				N	N
44941	ACTIVE	N	N125-01-1/631	Stairs: Spiral - Station Building - Angel Disused Stn	Lead/Leading	Lead Paint/Lead	Known				Disused Staircase - Bottom of Shaft - Support steel Grey Gloss				N	N
10925	ACTIVE	N	N125-01-1/662	Switch Room - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10926	ACTIVE	N	N125-01-1/663	Switch Room - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10927	ACTIVE	N	N125-01-1/801	Office - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20027	ACTIVE	N	N125-01-1/801/CLG-01	Ceiling: Solid - 1 - Office - Disused Station Building - Angel Stn	Glazing Rope	Asbestos	Strongly Presumed				Roof Light - Glazing Bars  No access to disused ticket hall area during 2020 re-inspection. Keys not available with station supervisor and alternative route via disused lower concourse deemed unsafe.					
10928	ACTIVE	N	N125-01-1/951	Disused Room - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10929	ACTIVE	N	N125-01-1/952	Disused Room - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10930	ACTIVE	N	N125-01-1/953	Disused Room - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10931	ACTIVE	N	N125-01-1/954	Disused Room - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10932	ACTIVE	N	N125-01-1/986	Disused Room - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N125-01 - Station Building - Angel Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10933	ACTIVE	N	N125-01-1/987	Disused Room - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
10934	ACTIVE	N	N125-01-2/238	Disused Room - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16709	ACTIVE	N	N125-01-2/238/WAL-003	Wall: Internal - 3 - Disused Room - Disused Station Building - Angel Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Hardboard Panel					
10935	ACTIVE	N	N125-01-2/239	Passage - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
19055	ACTIVE	N	N125-01-2/239/CLG-01	Ceiling: Solid - 1 - Passage - Disused Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard ceiling				YES	
10936	ACTIVE	N	N125-01-2/331	Mess Room - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16711	ACTIVE	N	N125-01-2/331/CLG-01	Ceiling: Solid - 1 - Mess room - Disused Station Building - Angel Stn	Other Boarding	Asbestos	Surveyed - Not Detected				Plasterboard					
18371	ACTIVE	N	N125-01-2/331/CLG-01	Ceiling: Solid - 1 - Mess room - Disused Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard ceiling				YES	
10937	ACTIVE	N	N125-01-2/371	Store - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
10938	ACTIVE	N	N125-01-2/411	Store - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16715	ACTIVE	N	N125-01-2/411	Store - Station Building - Angel Disused Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed -No Access : Note A Do not Enter notice is applied to the Room					
10939	ACTIVE	N	N125-01-2/412	Store - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16716	ACTIVE	N	N125-01-2/412	Store - Station Building - Angel Disused Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed -No Access : Note A Do not Enter notice is applied to the Room					
10940	ACTIVE	N	N125-01-2/413	Store - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16717	ACTIVE	N	N125-01-2/413	Store - Station Building - Angel Disused Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed -No Access : Note A Do not Enter notice is applied to the Room					



# Hazardous Material Asset Register - Summary



## N125-01 - Station Building - Angel Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10941	ACTIVE	N	N125-01-2/416	Disused Room - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18372	ACTIVE	N	N125-01-2/416/CLG-01	Ceiling: Solid - 1 - Disused Room - Disused Station Building - Angel Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
16718	ACTIVE	N	N125-01-2/416/CLG-01	Ceiling: Solid - 1 - Disused Room - Disused Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard ceiling				YES	
16719	ACTIVE	N	N125-01-2/416/CLG-01	Ceiling: Solid - 1 - Disused Room - Disused Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard ceiling				YES	
10942	ACTIVE	N	N125-01-2/417	Shower Room - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
19056	ACTIVE	N	N125-01-2/417/CLG-01	Ceiling: Solid - 1 - Shower Room - Disused Station Building - Angel Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
10943	ACTIVE	N	N125-01-2/418	Shower Room - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10944	ACTIVE	N	N125-01-2/901	Service Riser - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				No Access, Notice Do Not Enter Aug 2014					
16724	ACTIVE	N	N125-01-2/901	Service Riser - Station Building - Angel Disused Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access : Note A do not Enter notice applied to this room					
10945	ACTIVE	N	N125-01-2/951	Disused Room - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10946	ACTIVE	N	N125-01-2/953	Disused Room - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18438	ACTIVE	N	N125-01-2/953/CLG-01	Ceiling: Solid - 1 - Disused Room - Disused Station Building - Angel Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
16726	ACTIVE	N	N125-01-2/953/CLG-01	Ceiling: Solid - 1 - Disused Room - Disused Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard ceiling				YES	
10947	ACTIVE	N	N125-01-2/954	Office - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
16727	ACTIVE	N	N125-01-2/954/CLG-01	Ceiling: Solid - 1 - Office - Disused Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard ceiling				YES	



# Hazardous Material Asset Register - Summary



## N125-01 - Station Building - Angel Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
19057	ACTIVE	N	N125-01-2/954/CLG-01	Ceiling: Solid - 1 - Office - Disused Station Building - Angel Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
10948	ACTIVE	N	N125-01-2/955	Disused Room - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10949	ACTIVE	N	N125-01-2/988	Disused Room - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10950	ACTIVE	N	N125-01-2/989	Disused Room - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10951	ACTIVE	N	N125-01-3/081	Lobby - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10952	ACTIVE	N	N125-01-3/082	Circulation Area - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44739	ACTIVE	N	N125-01-3/082	Circulation Area - Station Building - Angel Disused Stn		Lead Paint/Lead	Known				High level walls / ceilings - Cream gloss - Lead Content Analysis - 0.63%					
44750	ACTIVE	N	N125-01-3/082	Circulation Area - Station Building - Angel Disused Stn		Lead Paint/Lead	Sampled – Not Detected				Skirting and low level walls - Black matt paint - Lead Analysis - 0.13% - Not considered a lead hazard					
44738	ACTIVE	N	N125-01-3/082	Circulation Area - Station Building - Angel Disused Stn		Lead Paint/Lead	Known				Columns & Beams - Green gloss paint - Lead Content Analysis 1.91%					
18440	ACTIVE	N	N125-01-3/082/FLR-01	Floor - 1 - Circulation Area - Disused Station Building - Angel Stn	Isolator Switches	Asbestos	Not Found during Inspection				Flash Guards - Chrysotile Flash guards not present in 2020 re-inspection - possibly removed		4			
10953	ACTIVE	N	N125-01-3/202	Lobby - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42250	ACTIVE	N	N125-01-3/202	Lobby - Station Building - Angel Disused Stn	Durasteel	Asbestos	Surveyed – Not Detected				Walls - Durasteel				N	N
44939	ACTIVE	N	N125-01-3/202	Lobby - Station Building - Angel Disused Stn	Lead/Leading	Lead Paint/Lead	Known				High level walls / ceiling - Green Gloss				N	N
10954	ACTIVE	N	N125-01-3/203	Passage - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44745	ACTIVE	N	N125-01-3/203	Passage - Station Building - Angel Disused Stn		Lead Paint/Lead	Known				Columns & Beams - Green gloss paint - Lead Content Analysis 1.91%					
44744	ACTIVE	N	N125-01-3/203	Passage - Station Building - Angel Disused Stn		Lead Paint/Lead	Known				Low level wall - Blue gloss - Lead Content Analysis 8.64%					
44747	ACTIVE	N	N125-01-3/203	Passage - Station Building - Angel Disused Stn		Lead Paint/Lead	Sampled – Not Detected				Skirting and low level walls - Black Matt - Lead Paint Analysis 0.14%					



# Hazardous Material Asset Register - Summary



## N125-01 - Station Building - Angel Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44746	ACTIVE	N	N125-01-3/203	Passage - Station Building - Angel Disused Stn		Lead Paint/Lead	Sampled – Not Detected				High level walls / ceiling - Cream Gloss - Lead Paint Analysis 0.18%					
10955	ACTIVE	N	N125-01-3/204	Passage - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44742	ACTIVE	N	N125-01-3/204	Passage - Station Building - Angel Disused Stn		Lead Paint/Lead	Known				High level walls / ceiling - Cream Gloss - Lead Paint Analysis 0.54%					
44743	ACTIVE	N	N125-01-3/204	Passage - Station Building - Angel Disused Stn		Lead Paint/Lead	Sampled – Not Detected				Skirting and low level walls - Black matt paint - Lead Analysis - 0.16% - Not considered a lead hazard					
44741	ACTIVE	N	N125-01-3/204	Passage - Station Building - Angel Disused Stn		Lead Paint/Lead	Known				Columns & Beams - Green gloss paint - Lead Content Analysis 2.54%					
10956	ACTIVE	N	N125-01-3/205	Passage - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10957	ACTIVE	N	N125-01-3/206	Lobby - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44748	ACTIVE	N	N125-01-3/206	Lobby - Station Building - Angel Disused Stn		Lead Paint/Lead	Sampled – Not Detected				High level walls / ceiling - Cream Gloss - Lead Paint Analysis 0.18%					
44749	ACTIVE	N	N125-01-3/206	Lobby - Station Building - Angel Disused Stn		Lead Paint/Lead	Sampled – Not Detected				Skirting and low level walls - Black Matt - Lead Paint Analysis 0.14%					
10958	ACTIVE	N	N125-01-3/632	Lobby - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10959	ACTIVE	N	N125-01-3/661	Switch Cupboard - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				No Access - Presumed to contain Switch Boxes - Insulation within					
10960	ACTIVE	N	N125-01-3/763	Switch Cupboard - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42251	ACTIVE	N	N125-01-3/763	Switch Cupboard - Station Building - Angel Disused Stn	Durasteel	Asbestos	Surveyed – Not Detected				Supalux Boarding				N	N
10961	ACTIVE	N	N125-01-3/986	Disused Room - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42254	ACTIVE	N	N125-01-3/986	Disused Room - Station Building - Angel Disused Stn		Asbestos	Surveyed – Not Detected				Tunnel Rings Caulking - Further investigations required					
10962	ACTIVE	N	N125-01-3/987	Disused Room - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42255	ACTIVE	N	N125-01-3/987	Disused Room - Station Building - Angel Disused Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Rings Caulking - further investigation required				N	N



# Hazardous Material Asset Register - Summary



## N125-01 - Station Building - Angel Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10963	ACTIVE	N	N125-01-A/131	Disused Room - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16589	ACTIVE	N	N125-01-A/131	Disused Room - Station Building - Angel Disused Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch Boxes - Insulation within Area not accessed during 2020 re-inspection. Access via disused ticket hall.		3			
16588	ACTIVE	N	N125-01-A/131/CLG-01	Ceiling: Solid - 1 - Disused Room - Disused Station Building - Angel Stn	Void	Asbestos	No Access: Presumed				Above - Non Asbestos Boards				YES	
18279	ACTIVE	N	N125-01-A/131/FLR-01	Floor - 1 - Stairs - Disused Station Building - Angel Stn	Durasteel	Asbestos	Surveyed - Not Detected				Lid to Storage Bin					
10964	ACTIVE	N	N125-01-A/132	Disused Room - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16590	ACTIVE	N	N125-01-A/132/FLR-01	Floor - 1 - Stairs - Disused Station Building - Angel Stn	Debris: Other	Asbestos	Known				Machine Debris - Chrysotile Area not accessed during 2020 re-inspection. Access via disused ticket hall.					
10965	ACTIVE	N	N125-01-A/291	Disused Room - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
16591	ACTIVE	N	N125-01-A/291/FLR-01	Floor - 1 - Disused Room - Disused Station Building - Angel Stn	Vinyl tiles	Asbestos	Surveyed - Not Detected				Lino, Vinyl Tiles - Non Asbestos					
10966	ACTIVE	N	N125-01-A/411	Disused Room - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
20025	ACTIVE	N	N125-01-A/411/FLR-01	Floor - 1 - Disused Room - Disused Station Building - Angel Stn	Vinyl tiles	Asbestos	Surveyed - Not Detected				Lino, Vinyl Tiles - Non Asbestos					
10967	ACTIVE	N	N125-01-A/578	Stairs: Linear - Station Building - Angel Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									

## N142-01 - Signals Building - Elephant & Castle To Kennington

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11431	ACTIVE	N	N142-01-0/081	Lobby - Signals Building - Elephant & Castle To Kennington	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
11432	ACTIVE	N	N142-01-0/661	Switch Cupboard - Signals Building - Elephant & Castle To Kennington	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N142-01 - Signals Building - Elephant & Castle To Kennington

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11433	ACTIVE	N	N142-01-0/711	SER - Signals Building - Elephant & Castle To Kennington	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11434	ACTIVE	N	N142-01-A/081	Lobby - Signals Building - Elephant & Castle To Kennington	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11435	ACTIVE	N	N142-01-A/082	Lobby - Signals Building - Elephant & Castle To Kennington	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11436	ACTIVE	N	N142-01-A/316	Locker Room - Signals Building - Elephant & Castle To Kennington	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11437	ACTIVE	N	N142-01-A/416	Shower Room - Signals Building - Elephant & Castle To Kennington	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11438	ACTIVE	N	N142-01-A/417	Toilet: Unisex - Signals Building - Elephant & Castle To Kennington	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11439	ACTIVE	N	N142-01-A/481	Signals Office - Signals Office Building - Elephant & Castle To Kennington	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11440	ACTIVE	N	N142-01-A/661	Switch Room - Signals Building - Elephant & Castle To Kennington	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N166-01 - Balham Vent Shaft - Balham To Tooting Bec

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11998	ACTIVE	N	N166-01-1/081	Lobby - Balham Vent Shaft - Balham To Tooting Bec	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11999	ACTIVE	N	N166-01-1/411	Store - Balham Vent Shaft - Balham To Tooting Bec	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12000	ACTIVE	N	N166-01-1/576	Stairs: Linear - Balham Vent Shaft - Balham To Tooting Bec	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12001	ACTIVE	N	N166-01-1/776	Fan Room - Balham Vent Shaft - Balham To Tooting Bec	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12002	ACTIVE	N	N166-01-1/801	Office - Balham Vent Shaft - Balham To Tooting Bec	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N166-01 - Balham Vent Shaft - Balham To Tooting Bec

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12003	ACTIVE	N	N166-01-A/081	Lobby - Balham Vent Shaft - Balham To Tooting Bec	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12004	ACTIVE	N	N166-01-A/416	Disused Room - Balham Vent Shaft - Balham To Tooting Bec	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12005	ACTIVE	N	N166-01-A/776	Fan Room - Balham Vent Shaft - Balham To Tooting Bec	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12006	ACTIVE	N	N166-01-B/081	Lobby - Balham Vent Shaft - Balham To Tooting Bec	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12007	ACTIVE	N	N166-01-B/402	Void - Balham Vent Shaft - Balham To Tooting Bec	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12008	ACTIVE	N	N166-01-B/411	Store - Balham Vent Shaft - Balham To Tooting Bec	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12009	ACTIVE	N	N166-01-B/801	Office - Balham Vent Shaft - Balham To Tooting Bec	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12010	ACTIVE	N	N166-01-B/901	Void - Balham Vent Shaft - Balham To Tooting Bec	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N176-01 - Dorset Road Pump House - South Wimbledon To Morden

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12247	ACTIVE	N	N176-01-1/771	Pump Room - Dorset Road Pump House - South Wimbledon To Morden	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N177-02 - Kenley Road Pump House - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12435	ACTIVE	N	N177-02-1/771	Pump Room - Kenley Road Pump House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N177-03 - Signals Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12436	ACTIVE	N	N177-03-2/706	IMR - Signals Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N177-04 - Signals Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12437	ACTIVE	N	N177-04-1/711	SER - Signals Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## N177-05 - Bicycle Shed - Signals Building - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12438	ACTIVE	N	N177-05-1/731	CER - Signals Building - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
18163	ACTIVE	N	N177-05-1/731/FLR-01	Floor - 1 - CER - Signals Building - Morden Stn	Void	Asbestos	No Access: Presumed				Beneath False Wooden Floor					YES

## N177-06 - Garth House - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12439	ACTIVE	N	N177-06-1/041	Mess Room - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12440	ACTIVE	N	N177-06-1/042	Mess Room - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12441	ACTIVE	N	N177-06-1/047	Kitchen - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12442	ACTIVE	N	N177-06-1/048	Kitchen - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12443	ACTIVE	N	N177-06-1/053	Mess Room - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12444	ACTIVE	N	N177-06-1/054	Switch Room - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N177-06 - Garth House - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12445	ACTIVE	N	N177-06-1/056	Toilet: Unisex - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12446	ACTIVE	N	N177-06-1/081	Lobby - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12447	ACTIVE	N	N177-06-1/083	Lobby - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12448	ACTIVE	N	N177-06-1/084	Lobby - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12449	ACTIVE	N	N177-06-1/092	Lobby - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12450	ACTIVE	N	N177-06-1/237	Passage - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12451	ACTIVE	N	N177-06-1/238	Lobby - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12452	ACTIVE	N	N177-06-1/240	Passage - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12453	ACTIVE	N	N177-06-1/241	Passage - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12454	ACTIVE	N	N177-06-1/242	Passage - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12455	ACTIVE	N	N177-06-1/281	Office - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12456	ACTIVE	N	N177-06-1/291	Office - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12457	ACTIVE	N	N177-06-1/301	Passage - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12458	ACTIVE	N	N177-06-1/302	Mess Room - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12459	ACTIVE	N	N177-06-1/306	Office - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N177-06 - Garth House - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12460	ACTIVE	N	N177-06-1/317	Office - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12461	ACTIVE	N	N177-06-1/331	Mess Room - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12462	ACTIVE	N	N177-06-1/401	Store - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12463	ACTIVE	N	N177-06-1/402	Store - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12464	ACTIVE	N	N177-06-1/406	Store - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12465	ACTIVE	N	N177-06-1/407	Store - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12466	ACTIVE	N	N177-06-1/411	Store - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12467	ACTIVE	N	N177-06-1/414	Locker Room - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12468	ACTIVE	N	N177-06-1/416	Toilet: Male - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12469	ACTIVE	N	N177-06-1/417	Lobby - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12470	ACTIVE	N	N177-06-1/418	Toilet: Female - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12471	ACTIVE	N	N177-06-1/421	Toilet: Female - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12472	ACTIVE	N	N177-06-1/422	Toilet: Male - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12473	ACTIVE	N	N177-06-1/425	Shower Room - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12474	ACTIVE	N	N177-06-1/426	Shower Room - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N177-06 - Garth House - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12475	ACTIVE	N	N177-06-1/427	Toilet: Male - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12476	ACTIVE	N	N177-06-1/610	Stairs: Linear - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12477	ACTIVE	N	N177-06-1/661	Switch Room - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12478	ACTIVE	N	N177-06-1/662	Switch Cupboard - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12479	ACTIVE	N	N177-06-1/664	Switch Cupboard - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12480	ACTIVE	N	N177-06-1/666	Switch Cupboard - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12481	ACTIVE	N	N177-06-1/761	Equipment Room - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12482	ACTIVE	N	N177-06-1/801	Office - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12483	ACTIVE	N	N177-06-1/802	Office - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12484	ACTIVE	N	N177-06-1/804	Office - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12485	ACTIVE	N	N177-06-1/805	Office - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12486	ACTIVE	N	N177-06-1/809	Office - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12487	ACTIVE	N	N177-06-1/810	Office - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12488	ACTIVE	N	N177-06-1/811	Office - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12489	ACTIVE	N	N177-06-1/812	Office - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N177-06 - Garth House - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12490	ACTIVE	N	N177-06-1/813	Office - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12491	ACTIVE	N	N177-06-1/901	Store - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12492	ACTIVE	N	N177-06-1/903	Office - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12493	ACTIVE	N	N177-06-1/904	Kitchen - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12494	ACTIVE	N	N177-06-1/906	Store - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12495	ACTIVE	N	N177-06-1/907	Store - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12496	ACTIVE	N	N177-06-1/908	Store - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12497	ACTIVE	N	N177-06-A/082	Lobby - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12498	ACTIVE	N	N177-06-A/236	Passage - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12499	ACTIVE	N	N177-06-A/237	Passage - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12500	ACTIVE	N	N177-06-A/316	Locker Room - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12501	ACTIVE	N	N177-06-A/331	Mess Room - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12502	ACTIVE	N	N177-06-A/332	Mess Room - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12503	ACTIVE	N	N177-06-A/406	Store - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12504	ACTIVE	N	N177-06-A/411	Store - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## N177-06 - Garth House - Morden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12505	ACTIVE	N	N177-06-A/412	Store - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12506	ACTIVE	N	N177-06-A/417	Shower Room - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12507	ACTIVE	N	N177-06-A/576	Stairs: Linear - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12508	ACTIVE	N	N177-06-A/661	Switch Cupboard - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12509	ACTIVE	N	N177-06-A/761	Equipment Room - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12510	ACTIVE	N	N177-06-A/801	Office - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12511	ACTIVE	N	N177-06-A/802	Office - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12512	ACTIVE	N	N177-06-A/803	Office - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12513	ACTIVE	N	N177-06-B/576	Stairs: Linear - Garth House - Morden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## ND021-02 - Signals Building - Edgware Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12535	ACTIVE	N	ND021-02-0/661	Switch Room - Signals Building - Edgware Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## ND074-02 - Office Building - Highgate Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12552	ACTIVE	N	ND074-02-1/081	Lobby - Office Building - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12553	ACTIVE	N	ND074-02-1/082	Lobby - Office Building - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## ND074-02 - Office Building - Highgate Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12554	ACTIVE	N	ND074-02-1/236	Passage - Office Building - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12555	ACTIVE	N	ND074-02-1/316	Locker Room - Office Building - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12556	ACTIVE	N	ND074-02-1/331	Mess Room - Office Building - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12557	ACTIVE	N	ND074-02-1/416	Toilet: Female - Office Building - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12558	ACTIVE	N	ND074-02-1/417	Toilet: Male - Office Building - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12559	ACTIVE	N	ND074-02-1/661	Switch Room - Office Building - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12560	ACTIVE	N	ND074-02-1/801	Office - Office Building - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12561	ACTIVE	N	ND074-02-1/802	Office - Office Building - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12562	ACTIVE	N	ND074-02-1/803	Office - Office Building - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12563	ACTIVE	N	ND074-02-1/901	Cleaners Room - Office Building - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## ND074-03 - Highgate Service Control Centre - Highgate Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12564	ACTIVE	N	ND074-03-1/081	Lobby - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12565	ACTIVE	N	ND074-03-1/082	Lobby - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12566	ACTIVE	N	ND074-03-1/083	Lobby - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## ND074-03 - Highgate Service Control Centre - Highgate Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12567	ACTIVE	N	ND074-03-1/236	Passage - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12568	ACTIVE	N	ND074-03-1/237	Passage - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12569	ACTIVE	N	ND074-03-1/238	Passage - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12570	ACTIVE	N	ND074-03-1/239	Passage - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12571	ACTIVE	N	ND074-03-1/240	Passage - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12572	ACTIVE	N	ND074-03-1/241	Passage - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12573	ACTIVE	N	ND074-03-1/242	Passage - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12574	ACTIVE	N	ND074-03-1/316	Locker Room - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12575	ACTIVE	N	ND074-03-1/331	Mess Room - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12576	ACTIVE	N	ND074-03-1/332	Mess Room - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12577	ACTIVE	N	ND074-03-1/401	Cleaners Room - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12578	ACTIVE	N	ND074-03-1/411	Store - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12579	ACTIVE	N	ND074-03-1/412	Store - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12580	ACTIVE	N	ND074-03-1/413	Store - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12581	ACTIVE	N	ND074-03-1/416	Shower Room - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## ND074-03 - Highgate Service Control Centre - Highgate Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12582	ACTIVE	N	ND074-03-1/417	Toilet: Unisex - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12583	ACTIVE	N	ND074-03-1/419	Toilet: Female - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12584	ACTIVE	N	ND074-03-1/420	Toilet: Male - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12585	ACTIVE	N	ND074-03-1/421	Shower Room - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12586	ACTIVE	N	ND074-03-1/576	Stairs: Linear - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12587	ACTIVE	N	ND074-03-1/661	Switch Room - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12588	ACTIVE	N	ND074-03-1/662	Switch Room - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12589	ACTIVE	N	ND074-03-1/663	Switch Cupboard - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12590	ACTIVE	N	ND074-03-1/664	Switch Cupboard - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12591	ACTIVE	N	ND074-03-1/665	UPS Room - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12592	ACTIVE	N	ND074-03-1/751	Control Room - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12593	ACTIVE	N	ND074-03-1/761	Equipment Room - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12594	ACTIVE	N	ND074-03-1/776	Plant Room - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12595	ACTIVE	N	ND074-03-1/781	Transformer Room - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12596	ACTIVE	N	ND074-03-1/782	Transformer Room - Highgate Service Control Centre - Highgate Depot		Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## ND074-03 - Highgate Service Control Centre - Highgate Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12597	ACTIVE	N	ND074-03-1/783	Plant Room - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12598	ACTIVE	N	ND074-03-1/791	Service Area - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12599	ACTIVE	N	ND074-03-1/792	Service Area - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12600	ACTIVE	N	ND074-03-1/793	Service Area - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12601	ACTIVE	N	ND074-03-1/801	Training Room - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12602	ACTIVE	N	ND074-03-1/802	Incident Office - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12603	ACTIVE	N	ND074-03-1/803	Technical Support Office - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12604	ACTIVE	N	ND074-03-1/804	Server Room - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12605	ACTIVE	N	ND074-03-1/805	LUL Office - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12606	ACTIVE	N	ND074-03-1/806	LUL Office - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12607	ACTIVE	N	ND074-03-1/807	LUL Office - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12608	ACTIVE	N	ND074-03-1/808	Reception Office - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12609	ACTIVE	N	ND074-03-1/810	Union Office - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12610	ACTIVE	N	ND074-03-1/901	Technical Support Office - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12611	ACTIVE	N	ND074-03-1/902	Office - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## ND074-03 - Highgate Service Control Centre - Highgate Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12612	ACTIVE	N	ND074-03-1/903	Quiet Room - Highgate Service Control Centre - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## ND074-05 - Signals Building - Highgate Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12620	ACTIVE	N	ND074-05-0/661	Switch Room - Signals Building - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12621	ACTIVE	N	ND074-05-0/711	Relay Room - Signals Building - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## W001-01 - Station Building - North End Bull & Bush Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14536	ACTIVE	N	W001-01-1/131	LMR - Station Building - North End Bull & Bush Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14537	ACTIVE	N	W001-01-1/236	Lobby - Station Building - North End Bull & Bush Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14538	ACTIVE	N	W001-01-1/261	Platform 1 - Northern Line - Station Building - North End Bull & Bush Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14539	ACTIVE	N	W001-01-1/781	Substation Room - Station Building - North End Bull & Bush Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14540	ACTIVE	N	W001-01-2/236	Lobby - Station Building - North End Bull & Bush Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14541	ACTIVE	N	W001-01-2/237	Lobby - Station Building - North End Bull & Bush Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14542	ACTIVE	N	W001-01-2/238	Lobby - Station Building - North End Bull & Bush Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14543	ACTIVE	N	W001-01-2/576	Stairs: Linear - Station Building - North End Bull & Bush Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14544	ACTIVE	N	W001-01-2/577	Stairs: Linear - Station Building - North End Bull & Bush Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## W001-01 - Station Building - North End Bull & Bush Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14545	ACTIVE	N	W001-01-2/661	Switch Room - Station Building - North End Bull & Bush Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
14546	ACTIVE	N	W001-01-2/751	Depot Control Room - Station Building - North End Bull & Bush Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
14547	ACTIVE	N	W001-01-3/711	Relay Room - Station Building - North End Bull & Bush Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									

## W002-01 - Station Building - South Kentish Town Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14548	ACTIVE	N	W002-01-1/236	Passage - Station Building - South Kentish Town Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
14549	ACTIVE	N	W002-01-1/576	Stairs: Spiral - Station Building - South Kentish Town Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
14550	ACTIVE	N	W002-01-2/081	Lobby - Station Building - South Kentish Town Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
14551	ACTIVE	N	W002-01-2/661	Switch Room - Station Building - South Kentish Town Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
14552	ACTIVE	N	W002-01-2/776	Plant Room - Station Building - South Kentish Town Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									

## W003-01 - Station Building - City Road Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14553	ACTIVE	N	W003-01-1/576	Stairs: Linear - Station Building - City Road Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
14554	ACTIVE	N	W003-01-1/577	Stairs: Linear - Station Building - City Road Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
14555	ACTIVE	N	W003-01-2/236	Passage - Station Building - City Road Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									
14556	ACTIVE	N	W003-01-3/236	Passage - Station Building - City Road Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed - Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## W003-01 - Station Building - City Road Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14557	ACTIVE	N	W003-01-3/237	Passage - Station Building - City Road Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14558	ACTIVE	N	W003-01-3/261	Platform 1 - Northbound Fast - Northern Line - Station Building - City Road Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14559	ACTIVE	N	W003-01-3/262	Platform 2 - Southbound Fast - Northern Line - Station Building - City Road Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14560	ACTIVE	N	W003-01-3/576	Stairs: Linear - Station Building - City Road Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14561	ACTIVE	N	W003-01-3/577	Stairs: Linear - Station Building - City Road Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14562	ACTIVE	N	W003-01-3/791	Fan Room - Station Building - City Road Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## W006-01 - Station Building - Melton Street Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14579	ACTIVE	N	W006-01-1/081	Disused - Station Building - Melton Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14580	ACTIVE	N	W006-01-1/236	Lobby - Station Building - Melton Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14581	ACTIVE	N	W006-01-1/576	Stairs: Linear - Station Building - Melton Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14582	ACTIVE	N	W006-01-1/577	Stairs: Linear - Station Building - Melton Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14583	ACTIVE	N	W006-01-2/901	Disused - Station Building - Melton Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14584	ACTIVE	N	W006-01-2/902	Disused Room - Station Building - Melton Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14585	ACTIVE	N	W006-01-2/903	Disused Room - Station Building - Melton Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## W006-01 - Station Building - Melton Street Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14586	ACTIVE	N	W006-01-A/236	Passage - Station Building - Melton Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14587	ACTIVE	N	W006-01-A/416	Toilet: Unisex - Station Building - Melton Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14588	ACTIVE	N	W006-01-A/417	Toilet: Unisex - Station Building - Melton Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14589	ACTIVE	N	W006-01-A/801	Disused - Station Building - Melton Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## X113-01 - Control Centre - Cobourg Street

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14791	ACTIVE	N	X113-01-1/081	Lobby - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14792	ACTIVE	N	X113-01-1/082	Lobby - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14793	ACTIVE	N	X113-01-1/236	Passage - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14794	ACTIVE	N	X113-01-1/238	Passage - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14795	ACTIVE	N	X113-01-1/331	Office - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14796	ACTIVE	N	X113-01-1/401	Store - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14797	ACTIVE	N	X113-01-1/411	Store - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14798	ACTIVE	N	X113-01-1/412	Store - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14799	ACTIVE	N	X113-01-1/551	Yard - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## X113-01 - Control Centre - Cobourg Street

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14800	ACTIVE	N	X113-01-1/552	Yard - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14801	ACTIVE	N	X113-01-1/576	Stairs: Linear - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14802	ACTIVE	N	X113-01-1/577	Stairs: Linear - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14803	ACTIVE	N	X113-01-1/578	Stairs: Linear - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14804	ACTIVE	N	X113-01-1/661	Switch Room - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14805	ACTIVE	N	X113-01-1/711	SER - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14806	ACTIVE	N	X113-01-1/761	Equipment Room - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14807	ACTIVE	N	X113-01-1/762	Equipment Room - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14808	ACTIVE	N	X113-01-1/763	Equipment Room - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14809	ACTIVE	N	X113-01-1/781	Transformer Room - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
41706	ACTIVE	N	X113-01-1/781	Transformer Room - Control Centre - Cobourg Street	Rope Gaskets	Asbestos	Known				Fan Head House - Rope Gasket to ventilation ducting				N	N
14810	ACTIVE	N	X113-01-1/782	Transformer Room - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14811	ACTIVE	N	X113-01-1/783	Transformer Room - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14812	ACTIVE	N	X113-01-1/784	Transformer Room - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14813	ACTIVE	N	X113-01-1/801	Office - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## X113-01 - Control Centre - Cobourg Street

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14814	ACTIVE	N	X113-01-1/802	Office - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14815	ACTIVE	N	X113-01-2/236	Passage - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14816	ACTIVE	N	X113-01-2/406	Store - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14817	ACTIVE	N	X113-01-2/711	SER - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14818	ACTIVE	N	X113-01-2/712	SER - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14819	ACTIVE	N	X113-01-2/731	CER - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14820	ACTIVE	N	X113-01-2/761	Equipment Room - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14821	ACTIVE	N	X113-01-2/781	Transformer Room - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14822	ACTIVE	N	X113-01-2/782	Transformer Room - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14823	ACTIVE	N	X113-01-A/081	Lobby - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14824	ACTIVE	N	X113-01-A/082	Lobby - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14825	ACTIVE	N	X113-01-A/083	Lobby - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14826	ACTIVE	N	X113-01-A/236	Passage - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14827	ACTIVE	N	X113-01-A/316	Locker Room - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14828	ACTIVE	N	X113-01-A/411	Office - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## X113-01 - Control Centre - Cobourg Street

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14829	ACTIVE	N	X113-01-A/416	Toilet: Female - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14830	ACTIVE	N	X113-01-A/551	Passage - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14831	ACTIVE	N	X113-01-A/761	Equipment Room - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14832	ACTIVE	N	X113-01-A/786	Service Riser - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14833	ACTIVE	N	X113-01-A/801	Office - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14834	ACTIVE	N	X113-01-A/802	Office - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14835	ACTIVE	N	X113-01-A/803	Office - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14836	ACTIVE	N	X113-01-A/804	Office - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14837	ACTIVE	N	X113-01-A/805	Office - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14838	ACTIVE	N	X113-01-B/047	Kitchen - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14839	ACTIVE	N	X113-01-B/081	Office - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14840	ACTIVE	N	X113-01-B/236	Passage - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14841	ACTIVE	N	X113-01-B/237	Passage - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14842	ACTIVE	N	X113-01-B/411	Store - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14843	ACTIVE	N	X113-01-B/416	Passage - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## X113-01 - Control Centre - Cobourg Street

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14844	ACTIVE	N	X113-01-B/417	Toilet: Male - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14845	ACTIVE	N	X113-01-B/418	Toilet: Unisex - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14846	ACTIVE	N	X113-01-B/576	Stairs: Linear - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14847	ACTIVE	N	X113-01-B/577	Stairs: Linear - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14848	ACTIVE	N	X113-01-B/578	Stairs: Linear - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14849	ACTIVE	N	X113-01-B/579	Stairs: Linear - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14850	ACTIVE	N	X113-01-B/581	Stairs: Linear - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14851	ACTIVE	N	X113-01-B/582	Stairs: Linear - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14852	ACTIVE	N	X113-01-B/589	Stairs: Linear - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14853	ACTIVE	N	X113-01-B/661	Switch Cupboard - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14854	ACTIVE	N	X113-01-B/756	Station Control Room - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14855	ACTIVE	N	X113-01-B/761	Equipment Room - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
41709	ACTIVE	N	X113-01-B/761	Equipment Room - Control Centre - Cobourg Street	Boarding: AIB	Asbestos	Known				Outer Ring - AIB boarding above ducts through outer wall				N	N
41705	ACTIVE	N	X113-01-B/761	Equipment Room - Control Centre - Cobourg Street	Cable Ducts: Cement	Asbestos	Known				Cement Cable Ducts to outer ring wall				N	N
41704	ACTIVE	N	X113-01-B/761/CLG-01	Ceiling: Solid - 1 - Equipment Room - Control Centre - Cobourg Street	Boarding: AIB	Asbestos	Known				AIB panels to false ceiling - no access above				N	N



# Hazardous Material Asset Register - Summary



## X113-01 - Control Centre - Cobourg Street

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14856	ACTIVE	N	X113-01-B/762	Equipment Room - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
41703	ACTIVE	N	X113-01-B/762	Equipment Room - Control Centre - Cobourg Street	Cable Ducts: Cement	Asbestos	Known				Cement Cable Ducts to outer ring wall				N	N
41702	ACTIVE	N	X113-01-B/762	Equipment Room - Control Centre - Cobourg Street	Isolator Switches	Asbestos	Strongly Presumed				Materials within fuse/switch boxes to outer wall				N	N
41710	ACTIVE	N	X113-01-B/762	Equipment Room - Control Centre - Cobourg Street	Boarding: AIB	Asbestos	Known				Outer Ring - AIB Boarding above ducts through outer wall				N	N
41701	ACTIVE	N	X113-01-B/762/CLG-01	Ceiling: Solid - 1 - Equipment Room - Control Centre - Cobourg Street	Boarding: AIB	Asbestos	Known				AIB panel to false ceiling				N	N
14857	ACTIVE	N	X113-01-B/776	Plant Room - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
41711	ACTIVE	N	X113-01-B/776	Plant Room - Control Centre - Cobourg Street	Other Boarding	Asbestos	Presumed				Exterior to Control room walls, composite Roof and possible asbestos within				N	N
41708	ACTIVE	N	X113-01-B/776/CLG-01	Ceiling: Solid - 1 - Plant Room - Control Centre - Cobourg Street	Boarding: AIB	Asbestos	Known				AIB board - Vertical boarding above false ceiling to perimeter of room. Partially covered with Supalux boarding				Y	Y
41707	ACTIVE	N	X113-01-B/776/CLG-01	Ceiling: Solid - 1 - Plant Room - Control Centre - Cobourg Street	Boarding: AIB	Asbestos	Known				AIB board - horizontal boarding above false ceiling to perimeter of room				Y	Y
14858	ACTIVE	N	X113-01-B/777	Plant Room - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14859	ACTIVE	N	X113-01-B/801	Office - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14860	ACTIVE	N	X113-01-B/802	Office - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14861	ACTIVE	N	X113-01-B/803	Office - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14862	ACTIVE	N	X113-01-B/804	Office - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14863	ACTIVE	N	X113-01-B/805	Office - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14864	ACTIVE	N	X113-01-B/806	Office - Control Centre - Cobourg Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## X143-01 - Archer House - Oval Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14870	ACTIVE	N	X143-01-1/081	Lobby - Archer House - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14871	ACTIVE	N	X143-01-1/291	Office - Archer House - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14872	ACTIVE	N	X143-01-1/416	Toilet: Unisex - Office Building - Archer House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14873	ACTIVE	N	X143-01-1/576	Stairs: Linear - Archer House - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14874	ACTIVE	N	X143-01-1/661	Switch Cupboard - Archer House - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14875	ACTIVE	N	X143-01-1/801	Office - Archer House - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14876	ACTIVE	N	X143-01-A/047	Kitchen - Archer House - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14877	ACTIVE	N	X143-01-A/081	Passage - Archer House - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14878	ACTIVE	N	X143-01-A/082	Lobby - Archer House - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14879	ACTIVE	N	X143-01-A/291	Office - Archer House - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14880	ACTIVE	N	X143-01-A/311	Office - Archer House - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14881	ACTIVE	N	X143-01-A/411	Store - Archer House - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14882	ACTIVE	N	X143-01-A/412	Store - Archer House - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14883	ACTIVE	N	X143-01-A/416	Toilet: Unisex - Office Building - Archer House	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14884	ACTIVE	N	X143-01-A/801	Office - Archer House - Oval Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## X164-01 - Office Building - Battersea ERU

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15031	ACTIVE	N	X164-01-1/081	Lobby - Office Building - Battersea ERU	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15032	ACTIVE	N	X164-01-1/236	Passage - Office Building - Battersea ERU	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15033	ACTIVE	N	X164-01-1/331	Cupboard - Office Building - Battersea ERU	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15034	ACTIVE	N	X164-01-1/332	Gym Room - Office Building - Battersea ERU	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15035	ACTIVE	N	X164-01-1/406	Store - Office Building - Battersea ERU	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15036	ACTIVE	N	X164-01-1/416	Toilet: Unisex - Office Building - Battersea ERU	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15037	ACTIVE	N	X164-01-1/417	Shower Room - Office Building - Battersea ERU	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15038	ACTIVE	N	X164-01-1/418	Shower Room - Office Building - Battersea ERU	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15039	ACTIVE	N	X164-01-1/576	Stairs: Linear - Office Building - Battersea ERU	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15040	ACTIVE	N	X164-01-1/577	Stairs: Linear - Office Building - Battersea ERU	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15041	ACTIVE	N	X164-01-1/761	Equipment Room - Office Building - Battersea ERU	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15042	ACTIVE	N	X164-01-1/901	Workshop - Office Building - Battersea ERU	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15043	ACTIVE	N	X164-01-A/047	Kitchen - Office Building - Battersea ERU	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15044	ACTIVE	N	X164-01-A/416	Toilet: Female - Office Building - Battersea ERU	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15045	ACTIVE	N	X164-01-A/417	Toilet: Male - Office Building - Battersea ERU	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## X164-01 - Office Building - Battersea ERU

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
15046	ACTIVE	N	X164-01-A/801	DMT Office - DMT Office Building - Battersea ERU	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15047	ACTIVE	N	X164-01-A/802	Office - Office Building - Battersea ERU	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
15048	ACTIVE	N	X164-01-A/803	Office - Office Building - Battersea ERU	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## ND021-01 - Depot Building - Edgware Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12514	ACTIVE	N	ND021-01-1/081	Lobby - Depot Building - Edgware Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12515	ACTIVE	N	ND021-01-1/332	Mess Room - Depot Building - Edgware Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12516	ACTIVE	N	ND021-01-1/420	Toilet: Unisex - Depot Building - Edgware Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12517	ACTIVE	N	ND021-01-1/561	Workshop - Depot Building - Edgware Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12518	ACTIVE	N	ND021-01-1/573	Equipment Room - Depot Building - Edgware Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12519	ACTIVE	N	ND021-01-1/661	Switch Room - Depot Building - Edgware Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12520	ACTIVE	N	ND021-01-1/662	Switch Room - Depot Building - Edgware Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12521	ACTIVE	N	ND021-01-1/663	Switch Room - Depot Building - Edgware Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12522	ACTIVE	N	ND021-01-1/804	ISS Office- Depot Building - Edgware Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12523	ACTIVE	N	ND021-01-2/081	Lobby - Train Crew Accommodation - Depot Building - Edgware Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## ND021-01 - Depot Building - Edgware Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12524	ACTIVE	N	ND021-01-2/083	Lobby - Train Crew Accommodation - Depot Building - Edgware Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12525	ACTIVE	N	ND021-01-2/316	Locker Room - Train Crew Accommodation - Depot Building - Edgware Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12526	ACTIVE	N	ND021-01-2/317	Locker Room - Train Crew Accommodation - Depot Building - Edgware Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12527	ACTIVE	N	ND021-01-2/731	CER - Train Crew Accommodation - Depot Building - Edgware Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12528	ACTIVE	N	ND021-01-2/786	Switch Room - Train Crew Accommodation - Depot Building - Edgware Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12529	ACTIVE	N	ND021-01-2/787	Switch Room - Train Crew Accommodation - Depot Building - Edgware Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12530	ACTIVE	N	ND021-01-2/801	Training Room - Train Crew Accommodation - Depot Building - Edgware Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12531	ACTIVE	N	ND021-01-2/802	SCR - Train Crew Accommodation - Depot Building - Edgware Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12532	ACTIVE	N	ND021-01-2/803	Training Room - Train Crew Accommodation - Depot Building - Edgware Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12533	ACTIVE	N	ND021-01-2/804	SCR - Train Crew Accommodation - Depot Building - Edgware Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12534	ACTIVE	N	ND021-01-2/805	Store - Train Crew Accommodation - Depot Building - Edgware Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

## ND074-01 - Depot Building - Highgate Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12551	ACTIVE	N	ND074-01-1/561	Workshop - Depot Building - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



# Hazardous Material Asset Register - Summary



## ND074-04 - Gate House - Highgate Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
12613	ACTIVE	N	ND074-04-0/081	Lobby - Gate House - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12614	ACTIVE	N	ND074-04-0/416	Toilet: Unisex - Gate House - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12615	ACTIVE	N	ND074-04-0/481	Store - Gate House - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12616	ACTIVE	N	ND074-04-0/482	Store - Gate House - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12617	ACTIVE	N	ND074-04-0/661	Switch Cupboard - Gate House - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12618	ACTIVE	N	ND074-04-0/751	Station Control Room - Gate House - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
12619	ACTIVE	N	ND074-04-0/786	Service Area - Gate House - Highgate Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									