

Line Performance

PICCADILLY LINE	No of passenger comments received by CSC:	5	Timetable in operation :	WTT 57
Lifts assets unavailable for use (Step Free Routes indicated in bold)		Escalator assets unavailable for use		
<i>Unplanned:</i>				
<i>Planned:</i>				
Comments/Other business Issues:				
04:04 – Earl's Court Station closed due to a fire alert. LFB were tasked a found a burnt out motor associated with lift's 3 & 4. Station reopened at 04:33. LCH = 197				

16.32 – Baron's Court – signal failure – severe delays		Owner – Asset Operations
Summary	Signals A647A and A647B failing to clear	
Impact	17.39 – Minor delays between Acton Town and Cockfosters eastbound 18.33 - Severe delays between Arnos Grove and Cockfosters, minor delays between Acton Town and Arnos Grove. 18.56 – Severe delays between Acton Town and Cockfosters. Minor delays on the rest of the line. 20:46 – Severe delays advertised on the entire line.	
Indicative LCH	30,619	
Stalled trains	Nil	
Response	Technical Officer (TO) and DRM dispatched. Meanwhile trains continue to operate through under failure condition, and Cat 2 implemented. 17.18 – TO in IMR investigating 17.31 – TO on site with DRM for track access to continue with investigation 17.43 – TO continues investigations in trackside kiosks 18.12 – Signal X647C also failing after the relay associated with the service stock detector was identified to be defective. Replacement relay en route. 18.39 - Category one incident declared with Service Manager appointed Silver Control. 18:40 – DSIM en route from Palestra. 19.00 – DSIM on site. 19:19 – DSIM arranges trackside investigation. 19:30 – DSIM and Technical Officer found open circuit within the surface stock detector. Repair made and clear signals obtained on signals A647A and A647B. 19:43 – Replacement relay on site. 19:47 – Relay changed and clear signals obtained on signal X647C. 20:02 – Category one incident stood down.	
Recovery	00:30 – Minor delays between Cockfosters and Heathrow Airport. Good service on the rest of the line. 01:35 – Severe delays between Arnos Grove and Cockfosters. Minor delays on the rest of the line.	
Immediate cause & resolution	Signals A647A and A647B failing to clear. Subsequently signal X647C also found to be failing to clear. Technical staff found an open circuit within the surface stock detector causing signals A647A and A647B to fail. This was fixed and clear signals obtained. A relay was also changed and clear signals obtained on signal X647C.	
Subsequent Actions	See SOO HOT debrief.	