

Delay 5 minutes ([REDACTED])

05:38 King's Cross St. Pancras train delayed arriving

Westbound train 300 was delayed arriving at King's Cross St. Pancras owing to Signal LX790C and Signal L100 remaining displaying Stop signals

Initial 6 minute delay

AP JNP Fault Reference Number 52414205

([REDACTED])
05:45 King's Cross St. Pancras train delayed departing

Westbound train 300 was delayed departing King's Cross St. Pancras owing to Points Signal Track Circuit 'CB' hard down

Initial 40 minute delay

AP JNP Fault Reference Number 52414205

([REDACTED])
05:49 Change of service status

Minor delays were advertised replacing what was a Good service between Arnos Grove and Hammersmith in both directions

([REDACTED])
05:57 Change of service status

Severe delays were advertised replacing what were Minor delays between Arnos Grove and Hammersmith in both directions

([REDACTED])
05:58 Change of service status

Suspension of services were advertised replacing what were Severe delays between Arnos Grove and Hammersmith in both directions

([REDACTED])
06:00 Snapshot

3 trains cancelled

Eastbound 15 minutes, 0 headways

Westbound 25 minutes, 0 headways

No unplanned station closures

([REDACTED])
06:25 Change of service status

Severe delays were advertised replacing what were suspension of services between Arnos Grove and Hammersmith in both directions

[Severe delays were also advertised on the remainder of the line replacing what was a Good service owing to the level of cancellation of train services]

([REDACTED])
06:54 No Okay Stock: 257

Northfields depot

Cancelled in depot due to there being no okay stock available in the depot.

RES: 10.26 Northfields

Delay 4 minutes ([REDACTED])

06:58 ONA: E356

Cockfosters Depot

Cancelled in depot due to there being no available train operator.

RES 09:16 Northfields.

Delay 5 minutes ([REDACTED])

07:00 Service Update

Minor delays Cockfosters to Acton Town both roads. Severe delays on both branches.

11 Trains cancelled.

Late running: -

Eastbound: 7 minutes with 1 missed headway

Westbound: 30 minutes with 0 missed headways ([REDACTED])

07:13 No Okay stock: E260

Northfields Depot

Eastbound train 260 cancelled in depot due to there being no available stock.

RES: 09:39 Acton W/B

Delay 5 minutes ([REDACTED])

08:00 Service Update

Severe delays on both branches with minor delays Acton To Cockfosters both roads.

13 trains cancelled.

Late running: -

Eastbound 2 with 3 missed headways

Westbound 8 with 2 missed headways ([REDACTED])

08:10 Defective in Service

Arnos Grove

Westbound 362 (lead car 155) was with drawn from service due to motor defect as confirmed by train technician.

Detrained and cancelled to Cockfosters depot to finish time of 09:18 Northfields depot

Delay 3 minutes ([REDACTED])

09:00 Service Update

Severe delays both branches with monor delays Acton Town to Cockfosters both roads.

13 trains cancelled.

late Running: -

Eastbound: 11 minutes with 6 missed headways

Westbound: 7 minutes with 6 missed headways ([REDACTED])

10:35 Customer Action

Hammersmith

Eastbound 247 delayed departing awaiting station staff to remove unsavoury customer.

Eastbound held and delayed in consequence.

Delay 6 minutes ([REDACTED])

10:40 ONA: W312

Acton Town

Westbound train 312 was reformed into 317 due to there being no available operator.

RES: 12:44 Arnos Grove E/B

Delay 4 minutes ([REDACTED])

11:44 SPAD: W252 at A680a

South Kensington

Signal A680a passed at danger.

Correct procedure applied via Controller authorisation to proceed.

Lead car 182

Fault ref number: 52415492

Delay 2 minutes ([REDACTED])

12:00 Service Update

Severe delays on both branches. Minor delays Acton To Cockfosters

7 Trains cancelled (2 ONA and 5 CIC signal failure Kings Cross)

Late running:-

Eastbound 5 with 15 missed headways

Westbound 14 with 14 missed headways ([REDACTED])

12:07 Customer Action

Arnos Grove

Westbound train 257 withdrawn from service due to vomit on the seat.

Run out of service to Northfields depot for attention.

Lead car 100

Delay 2 minutes ([REDACTED])

12:36 Wrong Signal accepted: DISTRICT 036

Acton Town

Eastbound train 323 delayed arriving into Acton Town following district line train 036 accepting the incorrect signal at WL99 route 2.

The District T/Op stated they were familiar with the route and took the train up the fast line between Acton Town and Hammersmith departing at 12:42.

Fault reference 1923709

Delay 6 minutes ([REDACTED])

13:30 Service update

The Piccadilly line now has minor delays between Cockfosters and Heathrow, with severe delays on the Uxbridge branch. ([REDACTED])

13:50 A train withdrawn

At Manor House, E226 withdrawn from service due to the T/Op being over the operating parameters. The train re-entered service at Wood Green.

Eastbound service delayed in consequence.

Delay 3 minutes. ([REDACTED])

14:18 A train withdrawn

At Acton Town, W237 withdrawn due to an ONA.

Delay 10 minutes. ([REDACTED])

14:31 A train withdrawn

At Acton Town, W313 withdrawn due to an ONA.

Delay 3 minutes. ([REDACTED])

15:26 Service Update

Services have continued to improve and recover and we are now able to advertise

Good Service Cockfosters to Acton Town

And

Minor Delays the rest. ([REDACTED])

16:00 Service update

Services are now back to timetable working though we still have trains cancelled but we are able to advertise a good service. ([REDACTED])

17:33 Cockfosters

ONA:-

Due to no operator available west bound train 220 was cancelled to the depot.

(Delay 3 Minutes)

([REDACTED])

18:00 Snapshot

We are currently advertising a good service with
2 Trains cancelled Due to ONA's which have dogged us all day.

Some trains running through the centre of town on the west bound have been unable to maintain timetable working this appears to be inconsequence

of headways and increased loading possibly due to the Victoria Line which has been displaying Minor Delays for several hours.

East Bound Late running 2 Minutes

West Bound Late Running 3 Minutes ([REDACTED])

18:01 Arnos Grove

ONA:-

The trains manager at Arnos Grove has advised they are unable to crew 235 due to short notice absenteeism and the train is cancelled to the sidings.

(Delay 2 Minutes) ([REDACTED])

19:30 Service Update

The impact of trains unable to maintain timetabled working has now meant that we are reversing some trains short and reforming others on the west bound.

We are still able to describe the service as Good though the impact of the Victoria advertising Minor delays is still being felt. ([REDACTED])

21:00 Snapshot

1 train cancelled

Eastbound 9 minutes, 34 headways

Westbound 2 minutes, 37 headways

No unplanned station closures

([REDACTED])

22:20 King's Cross St. Pancras train delayed arriving

Eastbound train 315 was delayed arriving at King's Cross St. Pancras owing to being used to afford Protection. Duty Reliability Manager instructed to unsecure Points 5A. However Points 5A were found to have no evidence of being secured

Initial 2 minute delay

([REDACTED])

22:35 Holloway Road train delayed departing

Eastbound train 321 was delayed departing Holloway Road owing to Traction Current being turned OFF between Russell Square and Holloway Road Eastbound. This was a planned exercise

Initial 6 minute delay

([REDACTED])

22:56 Russell Square train delayed arriving

Westbound train 320 was delayed arriving at Russell Square owing to being used to afford Protection. Duty Reliability Manager unsecured Points 5B found secured Normal

Initial 4 minute delay

([REDACTED])

00:00 Snapshot

1 train cancelled

Eastbound 0 minutes, 34 headways

Westbound 1 minute, 37 headways

No unplanned station closures

([REDACTED])

01:59 Line has Engineering Hours

Engineering Hours not frustrated by Traffic Hours

([REDACTED])

Last Trains

Westbound

Train	Location	Due	Actual	Lateness	Comment
232	Arnos Grove	00.04.30	00.05.20	00:00:50	
232	Acton Town	00.57.00	00.56.20	-00:00:40	
232	Heathrow Terminals 123	01.20.30	01.22.00	00:01:30	

Eastbound

Train	Location	Due	Actual	Lateness	Comment
253	Cockfosters	01.13.30	01.13.00	-00:00:30	

Temporary Speed Restrictions

Ref	Start Date	MPH	Dir.	Start Point	End Point	Actual Location	Distance Start	Distance End	Reason	Withdrawn
PD 94	24/10/2005	25	EB	Earls Court Signal A6611	Gloucester Road Signal A665		0	0	SPAD Mitigation	
PD ??	01/01/2007	20	EB	RWDX 643 Ravenscourt Park	Signal RWD 8a Hammersmith		0	0	SPAD Mitigation	
PD218	28/02/2007	20	WB	WD32b	Hammersmith WD29		0	0	Condition of area.	

Daily Duty Allocation

Location	Early	Late	Night
West Area - DRM	██████	██████	██████
Service Manager - Earl's Court	██████	██████	██████
East Area - DRM	██████	██████	
11:00 Duty Reliability Manager ██████			