

Time Printed: 19 May 2022 13:45:49

## Northern Line Service Manager's Daily Review

**Auto: 34408 Fax: 41426**

**For 24 hours commencing: 0200**

**Timetable In Use: TTN2 (NOR)**

**Wednesday 23 February 2022**

### Snapshot Cancellations and Station Closures

Time	Train Cancellations	Cancelled	Scheduled	Station Closures
06:00	Full Service	0	48	Tufnell Park
07:00	No Train Operator (2) : 127, 56 .	2	81	None
08:00	No Train Operator (2) : 35, 7 .	2	87	None
09:00	No Train Operator (1) : 7 .	1	89	None
12:00	No Train Operator (2) : 154, 37 .	2	68	None
15:00	No Train Operator (1) : 143 ONA	1	68	None
17:00	No Train Operator (5) : 144, 152, 2, 25, 35 ONAs	5	87	None
18:00	No Train Operator (4) : 144, 160, 2, 25 ONAs	4	89	None
19:00	No Train Operator (2) : 160, 25 ONAs Defective in Service (1) : 35 Loss of DCV	3	87	None
21:00	No Train Operator (2) : 137, 15 No Train operator Available.	2	69	None
24:00	No Train Operator (1) : 57 No Train Operator available.	1	61	None

### Daily Commentary

**05:41 Tufnell Park - Station Closure - 75 minutes**

The station was closed and non-stopped in both directions due to non-availability of staff. ISF refers. ( )

**06:18 Hendon Central - Passenger Action - 6 minutes**

S023 (51612/409 duty) was delayed departing the platform due to the activation of a PEA in car 2, caused by a passenger altercation. ( ) reporting. ( )

**06:47 West Finchley - Defective in Service - 10 minutes**

S056 (51723/811 duty) was detained and worked empty to depot due to a single leafdoor failing to close in car 5. Station staff and Train Operator attended the issue, managing to force the door closed. ( ) reporting. ( )

**07:20 Clapham South - Defective in Service - 3 minutes**

N131 (51645/632 duty) was delayed departing the platform due to the Train Operator rectifying an audio comms failure. ISF refers. ( )

**07:35 High Barnet - Awaiting T/Op - 3 minutes**

S013 (51539/317 duty) was delayed departing the platform due to the Train Operator not being in position. ( ) reporting. ( )

**07:42 Golders Green - Defective in Service - 4 minutes**

S143 (51716/432 duty) was delayed departing the platform due to requiring assisted despatch for defective in cab CCTV, caused by glare on the monitor. ISF refers. ( )

**08:08 Morden - Awaiting T/Op - 2 minutes**

N141 (51627/605 duty) was delayed departing the platform due to the Train Operator not being in position. ( ) reporting. ( )

**08:44 Stockwell - Passenger Action - 4 minutes**

N101 (51543/428 duty) was delayed departing the platform due to the activation of a PEA in car 1, caused by a passenger taken ill. ( ) reporting. ( )

**08:47 Morden - Awaiting T/Op - 3 minutes**

N145 (51602/603 duty) was delayed departing the platform due to the Train Operator not being in position. ( ) reporting. ( )

**10:27 East Finchley - Defective in Service - 5 minutes**

S057 (51539/317 duty) was delayed departing the platform due to the Train Operator resolving a cross feed and traction auxiliary failure. ISF refers. ( )

**10:32 High Barnet - Awaiting T/Op - 2 minutes**

S133 (**51713/301 duty**) was delayed departing the platform due to the Train Operator not being in position. [REDACTED] reporting. ([REDACTED])

**11:12 Kennington - Defective in Service - 3 minutes**

S057 (**51539/317 duty**) was delayed departing the platform due to the Train Technician attending to a traction auxiliary fault. [REDACTED] reporting. ([REDACTED])

**11:29 Morden - Awaiting T/Op -3 minutes**

N054 (**51501/821 duty**) was delayed departing the platform due to the Train Operator not being in position. [REDACTED] reporting. ([REDACTED])

**11:48 Morden - Train Delayed - 4 minutes**

N040 (**51613/629 duty**) was delayed departing the platform due to the rear cab door being open. [REDACTED] reporting. ([REDACTED])

**16:58 Embankment - Train Delayed - 15 Minutes Delay**

N010 (**51561 / 661 Morden duty**) was delayed owing to a PIOT (Seizure). Further removed by station staff. [REDACTED] investigating. ([REDACTED])

**18:33 Golders Green - Train Delayed - 3 Minutes Delay**

S133 (**51683 / 661 duty**) was delayed owing to rear cab door left open by previous T/Op (**449 Golders Green duty**). Reservations released. [REDACTED] investigating. ([REDACTED])

**18:50 Burnt Oak - Train Withdrawn - 10 Minutes Delay**

N035 (**51630 / 324 High Barnet duty**) was withdrawn from service owing to being unable to obtain the DCV. Detrained and empty to Golders Green depot for changeover. [REDACTED] investigating. ([REDACTED])

**23:04 Embankment train withdrawn from service - 5 Minute delay:**

Southbound train 105 (**51514**) was withdrawn from service due to customer action, youths graffitied car 1. Train 105 departed empty to Morden depot for a change over and cleaning 5 Minute delay, **844 Duty, BTP Ref No. 694**, [REDACTED] reporting. ([REDACTED])

### Last Trains

#### Northbound

Train	Location	Due	Actual	Lateness	Comment
106	Mill Hill East	01.08.15			

#### Southbound

Train	Location	Due	Actual	Lateness	Comment
161	Morden	01.06.50			

### Temporary Speed Restrictions

Ref	Start Date	MPH	Dir.	Start Point	End Point	Actual Location	Distance Start	Distance End	Reason	Withdrawn
994	07/08/2015	10	All	50183	50183	High Barnet platform 1	0	0	Braking Rate	
995	07/08/2015	10	All	80212	80212	Edgware platform 2	0	0	Braking Rate	
996	07/08/2015	10	All	80431	80431	Edgware platform 3	0	0	Braking rate	
997	07/08/2015	10	All	80452	80452	Edgware platform 1	0	0	Braking rate	
1013	04/12/2015	15	SB	60559	60559	Camden - Euston	0	0	ATO Overspeed prevention	
AM001	22/11/2017	35	SB	50335	50275	High Barnet - Totteridge	0	0	Adhesion Manageme	
1186	01/03/2019	28	SB	70518	70518	Golders Green - Hampstead	0	0	Vibration reduction over GGNP33	
1204	09/08/2019	20	NB	60345	60345	Archway - Highgate	0	0	Vibration monitoring	
1280	11/02/2021	20	SB	20752	20761	Waterloo to Kennington	0	0	Flooding in tunnel	
1281	21/02/2021	28	SB	10519	10530	South Wimbledon - Morden	0	0	PV Site Noise Mitigation	
1282	25/02/2021	35	SB	60520	60541	Camden Town (HBT) - Euston (City)	0	0	PV Site Noise mitigation	
1302	27/02/2021	10	SB	60569	60569	Chalk Farm - Camden Town	0	0	WTT 58 Software Issues	
1290	29/06/2021	10	All	80213 / 80432	80217 / 80436	Edgware Platforms 2 & 3	0	0	Trains stopping short mitigation	
1310	16/01/2022	37	NB	30001	30018	Tottenham Court Road - Goodge Street	0	0	Blockade Power Mitigation	14/05/2022
1309	16/01/2022	34	NB	30049	30058	Leicester Square - Tottenham Court Road	0	0	Blockade Power Mitigation	14/05/2022
1311	16/01/2022	31	NB	30092	30104	Goodge Street - Warren Street	0	0	Blockade Power Mitigation	14/05/2022
1308	16/01/2022	37	SB	30206	30197	Tottenham Court Road - Leicester Square	0	0	Blockade Power Mitigation	14/05/2022
1307	16/01/2022	37	SB	30232 / 30302	30213 / 30302	Goodge Street - Tottenham Court Road	0	0	Blockade Power Mitigation	14/05/2022
1306	16/01/2022	31	SB	30240	30249	Warren Street - Goodge Street	0	0	Blockade Power Mitigation	14/05/2022

### Additional Information

#### AM SAB Success:

GG Requested 6 received 2

MN Requested 7 received 6

NIL Test runs requested, received NIL

1 Stock moves requested, received 1

2 Changeover requested, received 2

Stock Balance: GG+2,MN-2.

PM SAB SUCCESS 23/02/2022

GG Requested 7 Received 4

MN Requested 11 Received 7

0 Test Runs requested and 0 achieved.

0 Stock Moves requested and 0 achieved.

5 Changeovers requested and 5 achieved.

Stock balance: GG +2, MN -2

### Infrastructure Incidents

Start Date	End Date	Location	Dir	Asset No	FRC No	Cause	Days On	Manager
11/02/2021		Kennington	SB	Track		Flooding owing to defective pumps and drainage - 20mph TSR in place through area	462	