

Summary of Incidents

Report for Northern line covering period from Wednesday 23-Feb-2022 3:00 to Thursday 24-Feb-2022 2:59

Page 1 of 2

Rec No	ISF ref	IRF ref	Start time	Location	Road	Train No	Involved assets	Incident Description	(M)IRF manager	Infraco Notification Time/Ref	Initial delay	Res/Sab or Sig Fix	C A N	Incident Type	Basic Cause	Proxy LCH	Type C/R	Train No.	New Train	Time	From Location	Time	RES/SAB Location
1	374974	1166970	5:41	Tufnell Park			No assets reported	Customer Service - Station Staff - Station staff not available	Not issued as (M)IRF		75		0	FSC	Cust	111 70							
2	374970	1166944	6:18	Hendon Central	S	023	Incident Car - 51612	Customer Service - Criminal Behaviour - Assault/Fight/Altercation between customers PEA car 2 Passenger action Delayed departure Duty 409			6		0	TDL	Cust	1,542 06							
3	374975	1166949	6:47	West Finchley (Passenger Train (in car))	S	056	Incident Car - 51723	Fleet - DIS - Doors - No pilot light car 5, Single leaf failing to close Detrained and out of service for change over Southbound and northbound held and delayed in consequence, Duty 811			10	7:26	1	TWD	Fleet	3,122 87	R	056	035	7:26	Moorgate	08:24	Golders Green
4	374976	1166971	7:20	Clapham South (Passenger Train (in cab))	N	131	Incident Car - 51645	Fleet - DIS - Safety & Communication Systems (CCTV / PA / PEA) - Audio Comms fault Northbound held and delayed in consequence Delayed departure Duty 632	Not issued as (M)IRF		3		0	TDL	Fleet	1,960 56							
5	374977	1166950	7:35	High Barnet	S	013	Incident Car - 51539	Line Operations - Not in Position - Other Awaiting train operator Delayed departure Duty 317			3		0	TDL	L Ops	325 37							
6	374979	1166972	7:42	Golders Green	S	143	Incident Car - 51716	Fleet - DIS - Safety & Communication Systems (CCTV / PA / PEA) - Glare on in cab Monitor Requested assisted despatch southbound held in consequence Delayed departure Duty 432	Not issued as (M)IRF		4		0	TDL	Fleet	1,640 81							
7	374981	1166954	8:08	Morden	N	141	Incident Car - 51627	Line Operations - Not in Position - Other Awaiting train operator Delayed departure Duty 605			2		0	TDL	L Ops	276 62							
8	374992	1166974	8:44	Stockwell	N	101	Incident Car - 51543	Customer Service - Illness/Accident - Person ill on Train PEA car 1 Train operator investigated Delayed departure Northbound service held in consequence Duty 428			4		0	TDL	Cust	3,519 45							
9	374993	1166975	8:47	Morden	N	145	Incident Car - 51602	Line Operations - Not in Position - Other Awaiting train operator, release taken Delayed departure Duty 603			3		0	TDL	L Ops	499 74							

Summary of Incidents

Report for Northern line covering period from Wednesday 23-Feb-2022 3:00 to Thursday 24-Feb-2022 2:59

Page 2 of 2

Rec No	ISF ref	IRF ref	Start time	Location	Road	Train No	Involved assets	Incident Description	(M)IRF manager	Infraco Notification Time/Ref	Initial delay	Res/Sab or Sig Fix	C A N	Incident Type	Basic Cause	Proxy LCH	Type C/R	Train No.	New Train	Time	From Location	Time	RES/SAB Location
10	374996	1166992	10:27	East Finchley	S	057	Incident Car - 51539	Fleet - DIS - Traction - cross feed fail and traction loss car 6 Soft TAT and TAS Delayed departure Duty 317	Not issued as (M)IRF		5		0	TDL	Fleet	364 26							
11	374997	1166982	10:32	High Barnet	S	133	Incident Car - 51713	Line Operations - Not in Position - Other Train operator not in position Release taken Delayed departure Duty 304			2		0	TDL	L Ops	102 20							
12	375000	1166987	11:12	Kennington	S	057	Incident Car - 51539	Fleet - DIS - Traction - Southbound held while train tech attended to resolve traction issues Delayed departure Duty 317			3		0	TDL	Fleet	67 51							
13	375001	1166991	11:29	Morden	N	054	Incident Car - 51501	Line Operations - Not in Position - Other Awaiting train operator Delayed departure Duty 521			3		0	TDL	L Ops	180 85							
14	375003	1166995	11:48	Morden	N	040	Incident Car - 51613	Line Operations - Operational Reasons - Other Operational reasons no doors closed visual, rear cab door left open Delayed departure Duty 629			4		0	TDL	L Ops	181 01							
15	375016	1167023	16:58	Embankment (Passenger Train (in car))	N	010	Incident Car - 51561	Customer Service - Illness/Accident - Person ill on Train Car 5 Passenger Emergency Alarm operated Car 5 LAS requested Delayed departure Duty 661			15		0	TDL	Cust	10,563 64							
16	375019	1167032	18:33	Golders Green (Passenger Train (in cab))	S	133	Incident Car - 51683	Line Operations - Train Equipment Operation - Failure to shut down rear cab correctly Rear cab door left open by previous Train Operator Duty 449 Release taken Delayed departure Duty 661			3		0	TDL	L Ops	656 88							
17	375023	1167042	18:50	Burnt Oak (Passenger Train (in car))	N	035	Incident Car - 51630	Fleet - DIS - Doors - No door close visual Detrained Empty to Golders Green Depot for changeover Duty 324			10	20:07	1	TWD	Fleet	2,574 69							
18	375035	1167076	23 04	Embankment	S	105	Incident Car - 51514	Pass action graffiti c1 detrained ety to mdn for c/o			5	23:42	1	TWD	Cust	290 76	C	105		23:04	Embankment		