

INSPECTION RECORDS - GREAT SOUTH WEST ROAD - 01/01/2019 TO 01/01/2020

Date Inspected	Inspection Id	Road Id	Road Name	Initiation Type
02-Jan-2019	3298866	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
04-Jan-2019	3300436	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
08-Jan-2019	3303071	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
15-Jan-2019	3314162	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
22-Jan-2019	3321040	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
29-Jan-2019	3328056	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
31-Jan-2019	3331341	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
05-Feb-2019	3336043	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
12-Feb-2019	3343953	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
19-Feb-2019	3351560	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
26-Feb-2019	3358555	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
28-Feb-2019	3362798	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
05-Mar-2019	3367515	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
12-Mar-2019	3377307	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
19-Mar-2019	3383845	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
26-Mar-2019	3392276	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
28-Mar-2019	3395957	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
02-Apr-2019	3399334	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections

INSPECTION RECORDS - GREAT SOUTH WEST ROAD - 01/01/2019 TO 01/01/2020

Date Inspected	Inspection Id	Road Id	Road Name	Initiation Type
09-Apr-2019	3405986	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
16-Apr-2019	3412835	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
23-Apr-2019	3419244	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
26-Apr-2019	3423714	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
30-Apr-2019	3425620	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
07-May-2019	3430421	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
14-May-2019	3436192	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
21-May-2019	3441352	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
23-May-2019	3446341	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
28-May-2019	3448496	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
04-Jun-2019	3453700	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
11-Jun-2019	3460732	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
18-Jun-2019	3466902	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
20-Jun-2019	3469870	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
25-Jun-2019	3473324	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
02-Jul-2019	3477844	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
09-Jul-2019	3484447	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
16-Jul-2019	3489007	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections

INSPECTION RECORDS - GREAT SOUTH WEST ROAD - 01/01/2019 TO 01/01/2020

Date Inspected	Inspection Id	Road Id	Road Name	Initiation Type
18-Jul-2019	3492344	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
23-Jul-2019	3495563	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
30-Jul-2019	3500376	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
06-Aug-2019	3505827	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
13-Aug-2019	3511522	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
15-Aug-2019	3515297	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
20-Aug-2019	3517740	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
27-Aug-2019	3521930	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
03-Sep-2019	3528427	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
10-Sep-2019	3533131	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
12-Sep-2019	3536268	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
17-Sep-2019	3540639	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
24-Sep-2019	3545373	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
01-Oct-2019	3551867	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
08-Oct-2019	3559236	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
11-Oct-2019	3564196	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
11-Oct-2019	3564158	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
15-Oct-2019	3565814	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections

INSPECTION RECORDS - GREAT SOUTH WEST ROAD - 01/01/2019 TO 01/01/2020

Date Inspected	Inspection Id	Road Id	Road Name	Initiation Type
22-Oct-2019	3574962	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
29-Oct-2019	3582894	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
05-Nov-2019	3589588	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
07-Nov-2019	3589671	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
12-Nov-2019	3594351	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
19-Nov-2019	3607207	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
26-Nov-2019	3614327	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
03-Dec-2019	3622688	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
05-Dec-2019	3625150	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
05-Dec-2019	3625247	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
05-Dec-2019	3625181	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
10-Dec-2019	3630063	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
17-Dec-2019	3637778	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
23-Dec-2019	3643426	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections
30-Dec-2019	3647562	0000A30__1/00022	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Safety Inspections

DEFECT RECORDS - GREAT SOUTH WEST ROAD - 01/01/2019 TO 01/01/2020

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
781851	05-Feb-2019	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	A30 GREAT SOUTH WEST RD W/B LANE 1 PAST FAGGS RD BY ENT TO BP B4 L/C 20	FAILED GULLY SURR	COMPLETED	1	Minor Carriageway Repairs	Pothole	Permanent	05-Mar-2019	Priority 1
781851	05-Feb-2019	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	A30 GREAT SOUTH WEST RD W/B LANE 1 PAST FAGGS RD BY ENT TO BP B4 L/C 20	FAILED GULLY SURR	COMPLETED	1	Minor Carriageway Repairs	Pothole	Temporary	06-Feb-2019	Priority 1
782876	12-Feb-2019	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	A30 Great SW Rd W/B L1 just past Faggs Rd 1) past entrance to BP 2) past exit from BP	x3 potholes	COMPLETED	1	Concrete Carriageway Repairs	Failed patch : loss of material	Permanent	12-Mar-2019	Priority 1
782876	12-Feb-2019	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	A30 Great SW Rd W/B L1 just past Faggs Rd 1) past entrance to BP 2) past exit from BP	x3 potholes	COMPLETED	1	Concrete Carriageway Repairs	Failed patch : loss of material	Temporary	13-Feb-2019	Priority 1
783448	16-Feb-2019	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	A30 Gt SW Rd WB opp Hatton-X stn by BP garage	Pothole in L1	INSTRUCTED	1	Minor Carriageway Repairs	Pothole	Permanent	16-Mar-2019	Priority 1
783448	16-Feb-2019	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	A30 Gt SW Rd WB opp Hatton-X stn by BP garage	Pothole in L1	INSTRUCTED	1	Minor Carriageway Repairs	Pothole	Temporary	17-Feb-2019	Priority 1
783794	19-Feb-2019	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	A30 Gt SW Rd WB opp Hatton-X stn by BP garage	20sqm HRA req in L1	AVAILABLE	2L	Concrete Carriageway Repairs	Failed patch : loss of material	Permanent	19-Mar-2019	Low Priority De
786378	07-Mar-2019	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	LC 166 VER	OUT OF LIGHT	COMPLETED	2H	Road Lighting: Lamp Failures	Lamp Out 1	Permanent	14-Mar-2019	7 Day Defect

DEFECT RECORDS - GREAT SOUTH WEST ROAD - 01/01/2019 TO 01/01/2020

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
789127	29-Mar-2019	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	A30 GtSW Rd W/B past Faggs Rd on f/way LC164	Failed DBM f.way	COMPLETED	1	Footways And Cycle Tracks	Subsidence	Permanent	30-Mar-2019	Priority 1
789136	29-Mar-2019	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	A30 GT SW RD E/B PAST ONSLIP FROM TERMINAL 4 ON GRASS VERGE BY L/C 171	COLLAPSED DBL MHC	COMPLETED	1	Covers,Gratings,Frames,Boxes	Damaged/deformed	Permanent	30-Mar-2019	Priority 1
799297	14-Jun-2019	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Dukes River	GI	COMPLETED	2L	General Inspection - Structures	Structure Inspection - Only	Permanent	12-Jul-2019	Low Priority De
799299	14-Jun-2019	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	Dukes River East Extension	GI	COMPLETED	2L	General Inspection - Structures	Structure Inspection - Only	Permanent	12-Jul-2019	Low Priority De
806679	06-Aug-2019	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	509518.5519175233.3486	Deadwood and crown cleanSignificant dieback on east side.	INSTRUCTED	2M	Hedges And Trees: General	Deadwood	Permanent	03-Sep-2019	28 Day Defect
806680	06-Aug-2019	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	509075.1919174920.2086	Deadwood and crown cleanSeveral old pruning wounds on stem Good wound wood.	INSTRUCTED	2M	Hedges And Trees: General	Deadwood	Permanent	03-Sep-2019	28 Day Defect
808465	19-Aug-2019	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	A30 Gt Southwest Rd W/B aft Hatton-X LC:156	Oil & gearbox fluid on cw due to broken down vehicle	COMPLETED	1E	Sweeping And Cleansing	Excessive muck	Permanent	16-Sep-2019	Priority 1 (ECO
816625	23-Oct-2019	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	A30 Great South West Rd btw LC:138 & 140 after j/w Faggs Rd W/B	Damaged ADS sign with bottom bit laying on the grass verge	COMPLETED	1	Signs: Face/Structure/ Fixings	Redundant / Incorrectly Located Sign	Permanent	20-Nov-2019	Priority 1
816625	23-Oct-2019	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	A30 Great South West Rd btw LC:138 & 140 after j/w Faggs Rd W/B	Damaged ADS sign with bottom bit laying on the grass verge	COMPLETED	1	Signs: Face/Structure/ Fixings	Redundant / Incorrectly Located Sign	Temporary	24-Oct-2019	Priority 1

DEFECT RECORDS - GREAT SOUTH WEST ROAD - 01/01/2019 TO 01/01/2020

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
816405	23-Oct-2019	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	508965.5619174843.5436	Fell and remove stumpDead	COMPLETED	2M	Hedges And Trees: General	Young Tree /Planting Defects	Permanent	20-Nov-2019	28 Day Defect
816455	23-Oct-2019	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	508933.3369174820.2086	Fell and remove stumpRecentl y dead tree.	COMPLETED	2M	Hedges And Trees: General	Dead tree	Permanent	20-Nov-2019	28 Day Defect
816456	23-Oct-2019	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	508927.3969174815.0486	Fell and remove stumpRecentl y dead tree	INSTRUCTED	2M	Hedges And Trees: General	Dead tree	Permanent	20-Nov-2019	28 Day Defect
816457	23-Oct-2019	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	508560.2869174528.6486	Fell and remove stumpSignific ant recent dieback/death of tree.	INSTRUCTED	2M	Hedges And Trees: General	Dead tree	Permanent	20-Nov-2019	28 Day Defect
823531	05-Dec-2019	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	A30 GREAT SOUTH WEST RD W/B J/W FAGGS RD BY L/C112	FAILED CONCRETE FILLET AROUND SERVICE COVER	AVAILABLE	2M	Footways And Cycle Tracks	Other	Permanent	02-Jan-2020	28 Day Defect
823569	05-Dec-2019	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	A30 GREAT SOUTH WEST RD W/B J/W FAGGS RD BY L/C112	FAILED CONCRETE FILLET AROUND SERVICE COVER	COMPLETED	2M	Footways And Cycle Tracks	Other	Permanent	02-Jan-2020	28 Day Defect
823645	06-Dec-2019	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	A30 GREAT SOOHT WEST RD W/B AT START OF OFFLSIP TO SWANSEA RD ON FOOTWAY BY L/C 209	DEBRIS ON F/WAY	COMPLETED	1	Footways And Cycle Tracks	Litter grade D	Permanent	07-Dec-2019	Priority 1
825693	23-Dec-2019	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	A30 Gt South West Rd, W/B, past Faggs Rd, after BP, L1, past LC:126	A30 Gt South West Rd, W/B, past Faggs Rd, after BP, L1, past LC:126	COMPLETED	1E	Minor Carriageway Repairs	Pothole	Permanent	20-Jan-2020	Priority 1 (ECO)

DEFECT RECORDS - GREAT SOUTH WEST ROAD - 01/01/2019 TO 01/01/2020

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
825693	23-Dec-2019	A30,GREAT SOUTH WEST ROAD,W/B,(HATTON RD STH TO DUKE NOTHUMB RIVER),TW6	A30 Gt South West Rd, W/B, past Faggs Rd, after BP, L1, past LC:126	A30 Gt South West Rd, W/B, past Faggs Rd, after BP, L1, past LC:126	COMPLETED	1E	Minor Carriageway Repairs	Pothole	Temporary	24-Dec-2019	Priority 1 (ECO

PUBLIC ENQUIRY RECORDS - GREAT SOUTH WEST ROAD - 01/01/2019 TO 01/01/2020

Incident/Recorded Date	Pem Id	Location	Description	Hsc Status Name	Pem Category	Pem Class	Pem Type	Priority	Target Date	Complete Date	Action Remarks
14-Jan-2019	2773115	A30 GREAT SOUTH WEST ROAD W/B J/W DICKTURPIN WAY	DEAD FOX	Not Found	Customer Enquiries	Carriageway	Dead Animal	3	15-JAN-2019 17:35:43	NULL	COMP: 03.28h - Nothing found.
18-Mar-2019	2810855	A30 Great South West Road after the bus shelter outside Kuehne+Nagel	subsidence and ponding	Work Instructed	Customer Enquiries	Footway	Footway Defect	3	19-MAR-2019 09:28:06	NULL	COMP:
12-Apr-2019	2827587	A30 Great South West Road n/bound before j/w The Causeway / Faggs Road	manhole rattling.	Work Instructed	Customer Enquiries	Carriageway	Ironwork	3	15-APR-2019 07:42:55	NULL	COMP:
14-May-2019	2846939	A30 Great South West Road E/B O/S 94 AFTER GRANTLEY RD TW4 7NF	BLOCKED GULLY	Complete	Customer Enquiries	Drainage	Gully	4	21-MAY-2019 18:56:04	23-MAY-2019 18:06:08	COMP:03:35 FTR SILTED GULLY CLEANED RUNNING GOOD
20-Jun-2019	2870628	A30 GREAT SOUTH WEST ROAD W/B PAST OFFSLIP TO TERMINAL 4 IN CENTRE RESERVATION OPP LC2B	OBB BARRIER DAMAGED	Complete	Customer Enquiries	Street Furniture	Barriers	3	21-JUN-2019 13:54:00	08-AUG-2019 13:50:52	Offsite: 20/6 22:31 T: Made safe damaged OBB P: Renew 1x panel & 4x legs
04-Oct-2019	2941320	A30 Great South West Road W/B J/W EXIT TO BEAVER LANE	TREE OBSURING VIEW OF ONCOMING TRAFFIC	Complete	Customer Enquiries	Soft Landscaping	Overhanging Vegetation	4	11-OCT-2019 11:45:02	11-OCT-2019 16:35:48	COMP: 12.02h -FTR: cut back overhanging tree