

NAMS PRD - 4.5.0.0 - Tfl's IM Service Desk - 0343 222 0033

File Edit Block Field Record Query Help Links Window

ORACLE

Inspections - MAI3808 - TMARYNABAXTER@namsprd.TFLWMORA01 MAI v4.5.0.0

Inspection Id: 2953148 Insp Batch: 605052 Date Inspected: 28-DEC-2017

Inspector: LSO [REDACTED] Date Loaded: 28-DEC-2017

2nd Inspector: LSO [REDACTED] Last Updated: 28-DEC-2017

Initiation Type: NRM Safety/Detailed: 0

Weather Condition: FINE Road Surface Condition: DRY

Road Section: 0000A202_1/00040

Description: A202,CAMBERWELL NEW ROAD,,(NUMBER 126 TO JUNCT WYNDHAM RD),SE5

Start Chainage: 0 End Chainage: 978 Number of Defects: 0

Create WO Summary

Activities

Description

SI	Description
SI	

Defects Set Batch Available