

## INSPECTION RECORDS - VICTORIA EMBANKMENT - 01/11/2019 TO 21/04/2020

Date Inspected	Inspection Id	Road Id	Road Name	Initiation Type
05-Nov-2019	3594611	0000A32115/00027	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Safety Inspections
14-Nov-2019	3601714	0000A32115/00027	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Safety Inspections
20-Nov-2019	3608657	0000A32115/00027	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Safety Inspections
27-Nov-2019	3615265	0000A32115/00027	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Safety Inspections
04-Dec-2019	3623238	0000A32115/00027	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Safety Inspections
10-Dec-2019	3629920	0000A32115/00027	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Safety Inspections
18-Dec-2019	3638901	0000A32115/00027	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Safety Inspections
24-Dec-2019	3644158	0000A32115/00027	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Safety Inspections
31-Dec-2019	3653568	0000A32115/00027	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Safety Inspections
09-Jan-2020	3663885	0000A32115/00027	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Safety Inspections
15-Jan-2020	3670180	0000A32115/00027	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Safety Inspections
23-Jan-2020	3680149	0000A32115/00027	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Safety Inspections

## INSPECTION RECORDS - VICTORIA EMBANKMENT - 01/11/2019 TO 21/04/2020

Date Inspected	Inspection Id	Road Id	Road Name	Initiation Type
30-Jan-2020	3687374	0000A32115/00027	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Safety Inspections
06-Feb-2020	3695128	0000A32115/00027	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Safety Inspections
12-Feb-2020	3701104	0000A32115/00027	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Safety Inspections
20-Feb-2020	3724156	0000A32115/00027	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Safety Inspections
26-Feb-2020	3716179	0000A32115/00027	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Safety Inspections
04-Mar-2020	3723922	0000A32115/00027	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Safety Inspections
11-Mar-2020	3731452	0000A32115/00027	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Safety Inspections
18-Mar-2020	3738897	0000A32115/00027	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Safety Inspections
25-Mar-2020	3746714	0000A32115/00027	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Safety Inspections
31-Mar-2020	3751836	0000A32115/00027	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Safety Inspections
08-Apr-2020	3759729	0000A32115/00027	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Safety Inspections
16-Apr-2020	3766715	0000A32115/00027	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Safety Inspections

**DEFECT RECORDS - VICTORIA EMBANKMENT - 01/11/2019 TO 21/04/2020**

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
819853	05-Nov-2019	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	VICTORIA EMBANKMENT JB4 WATERLOO BRIDGE UNDER PASS	POTHOLE ON CW	SELECTED	2M	Minor Carriageway Repairs	Pothole	Permanent	03-Dec-2019	28 Day Defect
820350	14-Nov-2019	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	VIC EMBANKT EB CW OS EMBANKMENT STATION	VIC EMBKT EB CW OS EMABNKMENT STATION - FAILED PATCH AREA 3 SQM	COMPLETED	2M	Minor Carriageway Repairs	Failed patch : loss of material	Permanent	12-Dec-2019	28 Day Defect
820349	14-Nov-2019	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	VIC EMBKT WB FW OS CLEOPATRA NEEDLE APPROX 100M B4 OPP SAVOY ST BY LPA57	VIC EMBKT WB FW OS CLEOPATRS NEEDLE APPROX 100M B4 OPP SAVOY STBY LPA57-RELAY 2 750 1 900	COMPLETED	2H	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	21-Nov-2019	7 Day Defect
821144	20-Nov-2019	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Victoria embankment eb cw approx 5m b4 Northumberland Avenue	Pleeee make safe a pothole	COMPLETED	1	Concrete Carriageway Repairs	Pothole	Permanent	18-Dec-2019	Priority 1
821144	20-Nov-2019	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Victoria embankment eb cw approx 5m b4 Northumberland Avenue	Pleeee make safe a pothole	COMPLETED	1	Concrete Carriageway Repairs	Pothole	Temporary	21-Nov-2019	Priority 1
822317	27-Nov-2019	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	VICTORIA EMBANKMENT OPP HORSE GUARDS AVENUE; LC 31	DEAD SWA	COMPLETED	2H	Road Lighting: Lamp Failures	Lamp failure	Permanent	04-Dec-2019	7 Day Defect
822318	27-Nov-2019	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	VICTORIA EMBANKMENT OPP VICTORIA EMBANKMENT GARDENS; LC 29	DEAD SWA	INSTRUCTED	2H	Road Lighting: Lamp Failures	Lamp failure	Permanent	04-Dec-2019	7 Day Defect
822319	27-Nov-2019	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	VICTORIA EMBANKMENT OPP VICTORIA EMBANKMENT GARDENS; LC 27	DEAD SWA	COMPLETED	2H	Road Lighting: Lamp Failures	Lamp failure	Permanent	04-Dec-2019	7 Day Defect
822320	27-Nov-2019	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	VICTORIA EMBANKMENT OPP CHINDIT MEMORIAL; LC 20	COLUMN OOL	COMPLETED	2H	Road Lighting: Lamp Failures	Lamp failure	Permanent	04-Dec-2019	7 Day Defect
822349	27-Nov-2019	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	WB VICTORIA EMBKMT-AROUND 20 MTRS B4 TEMPLE PIER-OPP TEMPLE STATION	UNEVEN 700'S & 600'S	COMPLETED	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	25-Dec-2019	28 Day Defect
822350	27-Nov-2019	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	SB VICTORIA EMBKMT OPP NO 25- EMBKMT CAFE	X1 SUNKEN 900 ASP	SELECTED	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	25-Dec-2019	28 Day Defect

**DEFECT RECORDS - VICTORIA EMBANKMENT - 01/11/2019 TO 21/04/2020**

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
822351	27-Nov-2019	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	SB VIC EMBKMT OPP EMBKMT STATION-JUST B4 HUNGERFORD FOOT BRIDGE	UNEVEN ASP'S	SELECTED	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	25-Dec-2019	28 Day Defect
823379	04-Dec-2019	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	VICTORIA EMBANKMENT WB FW OPP TEMPLE PLCAE ENTRANCE	VICTORIA EMBAKT WB FW OPP TEMPLE PLACE ENTRANCE - RELAY 1 LOOSE 750	COMPLETED	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	01-Jan-2020	28 Day Defect
823380	04-Dec-2019	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	VIC EMBNKT WB FW BY LPA80 OPP TEMPLE PLACE	VIC EMBKT WB FW BY LPA80- OPP TEMPLE PLACE - LIFT & R 10 UNEVEN 750 SLABS	COMPLETED	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	01-Jan-2020	28 Day Defect
823517	05-Dec-2019	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Victoria Embankment eb cw just after crossing os Embankment Station	make safe failed patch/Trench.	COMPLETED	1	Minor Carriageway Repairs	Pothole	Permanent	06-Dec-2019	Priority 1
824149	10-Dec-2019	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	VIC EMBANKMENT EB FW APPROX 5M AFTER SAVOY ST	VIC EMBANKMENT EB CW APPROX 5M AFTER SAVOY ST - PATCH CRACK AROUND METL COVER AREA 2SQM	INSTRUCTED	2M	Minor Carriageway Repairs	Cracking around ironwork	Permanent	07-Jan-2020	28 Day Defect
824147	10-Dec-2019	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	VIC EMBANKMENT WB FW OPP EMBANKMENT STTION 100M B4 OPP NORTHUMBERLAND AVE	VIC EMBANKMENT WB FW OPP EMBANKMENT STATION APPROX 100MM B4 OPP NORTHUMERLAND AVE - REPLACE 3 900 7 750 SLABS CRACKED	COMPLETED	2M	Footways And Cycle Tracks	Slab cracking	Permanent	07-Jan-2020	28 Day Defect
824148	10-Dec-2019	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	VIC EMBANKMENT WB FW BY LIFE BOAT PIER BY LPA74 B4 OPP SAVOY ST	VIC EMBANKMENT WB FW BY LIFE BOAT PIER BY LPA74 B4 OPP SAVOY ST - REPLACE 15 750 SLABS	COMPLETED	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	07-Jan-2020	28 Day Defect
825226	18-Dec-2019	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	VIC EMBANKMENT IN C.RES NEAR CYCLE LANE OPP SCOTLAND YARD POLICE STATION APPROX 200M B4 WESTMINSTER BRIIDGE	VIC EMBANKMENT IN C.RES NEAR CYCLE LANE OPP SCOTLND YARD POLICE STATION APPROX 200M B4 WESTMINSTER BRIDGE- RESET LEANING SIGN POST	SELECTED	2M	Post Defect	Physical condition of post	Permanent	15-Jan-2020	28 Day Defect

**DEFECT RECORDS - VICTORIA EMBANKMENT - 01/11/2019 TO 21/04/2020**

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
825225	18-Dec-2019	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	VIC EMBANKMENT EB CW APPROX 100M AFTER NORTHUMERLAND AVE OS EMABNKMENT STATION	VIC EMBANKMENT EB CW APPROX 100NM AFTER NORTHUMBERLQND AVE OS EMABNKMENT STATION - PATCH CRACK AROUND METAL COVER AREA 1 SQM	SELECTED	2M	Minor Carriageway Repairs	Cracking around ironwork	Permanent	15-Jan-2020	28 Day Defect
825223	18-Dec-2019	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	VIC EMBANKMENT WB CW NEAR RED PHONE BOX OPP EMBANKMENT STATION APPROX 150M B4OPP NORTHUMBERLAND AVE	VIC EMBANKMENT WB FW OPP EMBANKMENT STTION APPROX 150M B4 OPP NORTHUMERLAND AVE NEAR RED PHONE BOX- RELAY 5 PAVING BLOCKS AND 1 CUT 600 CLAP	SELECTED	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	15-Jan-2020	28 Day Defect
825224	18-Dec-2019	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	VIC EMBANKMENT WB FW OPP TEMPLE PLACE ENTRANCE NEAR	VIC EMBANKMENT WB FW OPP TEMPLE PLACE ENTRANCE NEAR CROSSING B4 LPA82 - RELAY 1 LOOSE 750 SLAB	SELECTED	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	15-Jan-2020	28 Day Defect
827571	09-Jan-2020	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	VIC EMBANKMENT WB FW OPP TEMPLE STATION AFTER TEMPLE PLACE	VIC EMBANKMENT WB FW OPP TEMPLE STATION -	COMPLETED	2M	Hedges And Trees: General	Empty/Redundant Tree Pit/Dead Stump	Permanent	06-Feb-2020	28 Day Defect
837985	10-Jan-2020	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Vic embankment s/b near Tattershall Castle	Offensive bill posting	INSTRUCTED	1	Miscellaneous	Carriageway - Graffiti Other	Permanent	07-Feb-2020	Priority 1
837985	10-Jan-2020	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Vic embankment s/b near Tattershall Castle	Offensive bill posting	INSTRUCTED	1	Miscellaneous	Carriageway - Graffiti Other	Temporary	11-Jan-2020	Priority 1
829991	23-Jan-2020	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	VIC EMBANKMENT EB CW PPROX 100M AFTER NORTHUMBERLAND AVE	VIC EMBANKMENT EB CW PPROX 100M AFTER NORTHUMBERLAND AVE- PATCH CRACKING AROUND 3 COVERS	INSTRUCTED	2M	Minor Carriageway Repairs	Cracking around ironwork	Permanent	20-Feb-2020	28 Day Defect
830822	29-Jan-2020	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	VICTORIA EMBANKMENT OPP DERBY GATE; LC A11	COLUMN OOL	COMPLETED	2H	Road Lighting: Lamp Failures	Lamp failure	Permanent	05-Feb-2020	7 Day Defect

**DEFECT RECORDS - VICTORIA EMBANKMENT - 01/11/2019 TO 21/04/2020**

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
831024	30-Jan-2020	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	TEMPLE PLACE J/W VICTORIA EMBANKMENT WEST ENTRANCE	POTHOLE IN C/W - REPAIR	COMPLETED	1	Minor Carriageway Repairs	Pothole	Permanent	27-Feb-2020	Priority 1
831024	30-Jan-2020	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	TEMPLE PLACE J/W VICTORIA EMBANKMENT WEST ENTRANCE	POTHOLE IN C/W - REPAIR	COMPLETED	1	Minor Carriageway Repairs	Pothole	Temporary	31-Jan-2020	Priority 1
833220	12-Feb-2020	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	VIC EMBANKMENT EB CW APPROX 20M AFTER NORTHUMBERLAND AVE	VIC EMBANKMENT EB CW APPROX 20M AFTERNORTHUMBERLAND AVE- PTCH CRACK AROUND WATER COVER	INSTRUCTED	2H	Minor Carriageway Repairs	Cracking around ironwork	Permanent	19-Feb-2020	7 Day Defect
833221	12-Feb-2020	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	VIC EMBANKMENT WB FW APPROX 20 M AFTER WAR MEMORIAL 200M B4 WESTIMSTER BRIDGE	VIC EMBANKMENT WB FW APPROX 200M B4 WESTMINSTER BRIDGE 10M AFTER WAR MEMORIAL- REPLACE 3 750 L& R 6 750 & REFILL TREE PIT	COMPLETED	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	11-Mar-2020	28 Day Defect
840928	13-Feb-2020	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	victoria embankment e/b just before j/w temple avenue	flooding	INSTRUCTED	1	Hw. Drain: Gullies, Catchpits	Blockage	Permanent	14-Feb-2020	Priority 1
839639	26-Feb-2020	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Victoria embankment wb cw opp Temple Place entrance	Please make safe a failed patch/pothole	INSTRUCTED	1	Minor Carriageway Repairs	Failed patch : loss of material	Permanent	25-Mar-2020	Priority 1
839639	26-Feb-2020	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	Victoria embankment wb cw opp Temple Place entrance	Please make safe a failed patch/pothole	INSTRUCTED	1	Minor Carriageway Repairs	Failed patch : loss of material	Temporary	27-Feb-2020	Priority 1
835406	26-Feb-2020	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	VIC EMBANKMENT EB CW APPROX 20M AFTER NORTHUMBERLAND AVE	VIC EMBANKMENT EB CW APPROX 20M AFTER NORTHUMBERLAND AVE- PATCH CRACK AROUND WATER COVER	INSTRUCTED	2M	Minor Carriageway Repairs	Cracking around ironwork	Permanent	25-Mar-2020	28 Day Defect
840263	31-Mar-2020	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	VICTORIA EMBANKMENT SB OPP NEW SCOTLAND YARD APPROX 230 MTS B4 WESTMINSTER BRIDGE	RAISED ASPS BY TREE ROOTS	COMPLETED	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	28-Apr-2020	28 Day Defect
841688	08-Apr-2020	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	SB VICTORIA EMBANKMENT OPP JW TEMPLE PLACE	TOP UP TREE PIT BY TEMPLE STATION	COMPLETED	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	06-May-2020	28 Day Defect

**DEFECT RECORDS - VICTORIA EMBANKMENT - 01/11/2019 TO 21/04/2020**

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
842481	14-Apr-2020	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	SB VICTORIA EMBANKMENT OPPOSITE RICHMOND TERRACE	CCTE REPLACE MISSING RED ROUTE SIGN DR674	INSTRUCTED	2H	Signs: Face/Structure/ Fixings	Missing	Permanent	21-Apr-2020	7 Day Defect
843046	16-Apr-2020	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	VICTORIA EMBANKMENT WB BY LP A80 BETWEEN TEMPLE PIER AND WATERLOOD BRIDGE	RELAY 3XMODS	INSTRUCTED	2H	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	23-Apr-2020	7 Day Defect
843047	16-Apr-2020	A3211,VICTORIA EMBANKMENT,W/B,(DERBY GATE TO CITY BOUNDARY),WC2N	VICTORIA EMBANKMENT SB BY PHONE BOX OPP EMBANKMENT STATION	RELAY 8XBLOCKS 1X600 1X750 REPLACE 1X600	SELECTED	2M	Footways And Cycle Tracks	Slab profile : uneven/trips/gap	Permanent	14-May-2020	28 Day Defect

**PUBLIC ENQUIRY RECORDS - VICTORIA EMBANKMENT - 01/11/2019 TO 21/04/2020**

Incident/Recorded Date	Pem Id	Location	Description	Hsc Status Name	Pem Category	Pem Class	Pem Type	Priority	Target Date	Action Remarks
02-Nov-2019	2962621	Westminster pier, victoria embankment	ticket office needs opening	Received	Emergency Call Outs	Other	Other (Please state details in 'Descriptions' field)	1	02-NOV-2019 15:29:19	15:36 job done meet up with locksmith opened and delivered the key to ticket shop
05-Nov-2019	2963867	Bridge st nb opp Victoria embankment	Abandoned road work signs	Received	Inspection Response	Footway	Obstruction	3	06-NOV-2019 12:43:09	09:20 nothing found at this location.
18-Nov-2019	2975197	Blackfriars bridge nb approx 150 b4 Victoria Embankment	Loss of material around mhc in bus lane	Received	Inspection Response	Carriageway	Carriageway Defect	3	19-NOV-2019 14:51:25	LEFT: 0044 VIAFIXED POTHOLE AROUND MHC IN C/W - F.T.R
22-Nov-2019	2980185	, bottom of Waterloo Steps on the Victoria Embankment	6 cracked paving slabs,	Work Actioned	Emergency Call Outs	Footway	Footway Defect	2	22-NOV-2019 23:17:11	eru attended - this has already been made temp safe - with barriers around left: 22:37 - PERM 7 X 750 X600 SLABS YORK STONE SLABS NEEDED
25-Nov-2019	2981056	LAMBETH BRIDGE, W/B, (LAMBETH BOUNDARY TO VICTORIA EMBANKMENT	Lights are off during night pls make safe	Received	Inspection Response	Lighting	Damaged	4	02-DEC-2019 13:06:00	NULL
27-Nov-2019	2983209	WB WESTMINSTER BRIDGE ON FW AROUND 15 MTRS B4 J/OF VICTORIA EMBANKMENT	make safe -LOOSE FW MHC	Received	Inspection Response	Carriageway	Carriageway Defect	3	28-NOV-2019 15:55:52	unknown cover needs replaced, nuts and bolts are loose
27-Nov-2019	2983217	WB WESTMINSTER BRIDGE ON FW AROUND 15 MTRS B4 J/OF VICTORIA EMBANKMENT	LOOSE FW MHC	Received	Inspection Response	Carriageway	Ironwork	3	28-NOV-2019 16:00:14	inspection cover open. fixed back and locked with key
02-Dec-2019	2986708	Blackfriars bridge nb approx 150m b4 Victoria embankment	Loss of material and rocking mhc on cw	Received	Inspection Response	Carriageway	Pothole	3	03-DEC-2019 17:37:50	REATTENDED - VIAFIXED AROUND - LOW TW SECT 81 NEEDS TO BE SENT OFF LEFT: 03:46 - 05/12/2019
10-Dec-2019	2993851	Blackfriars bridge nb jb4 Victoria Embankment	Failed patch on cw	Received	Inspection Response	Carriageway	Carriageway Defect	3	11-DEC-2019 12:15:02	16:42 pothole on c/w made safe place with viafix 1x bag of viafix



**PUBLIC ENQUIRY RECORDS - VICTORIA EMBANKMENT - 01/11/2019 TO 21/04/2020**

Incident/Recorded Date	Pem Id	Location	Description	Hsc Status Name	Pem Category	Pem Class	Pem Type	Priority	Target Date	Action Remarks
18-Dec-2019	3000720	WESTMINSTER BRIDGE SB AT CROSSING J/W VICTORIA EMBANKMENT	2 X FAILED PATCHES AND POTHOLES	Received	Inspection Response	Carriageway	Carriageway Defect	3	19-DEC-2019 19:42:49	VIAFIXED AROUND DOUBLE MHC LEFT; 01:23 F.T.R
07-Jan-2020	3008231	o/s embankment underground station. Victoria embankment	1 x L/C OOL	Received	Inspection Response	Lighting	Off At Night	4	14-JAN-2020 09:59:16	NULL
07-Jan-2020	3008606	Blackfriars bridge nb jb4 Victoria embankment	Large ph in Lane 1	Received	Inspection Response	Carriageway	Pothole	3	08-JAN-2020 14:30:46	12:39 1.5 x 1.5 = 2.25sqm
09-Jan-2020	3011119	Horse Gurads Ave jw Victoria embankment	Please make safe a missing island at traffic lights and Crossing.	Work Instructed	Inspection Response	Carriageway	Carriageway Defect	3	10-JAN-2020 11:40:34	04:24, made safe with 2x cones damaged traffic light base on central island  needs to replace broken concrete base around traffic light on central island. Needs to replace new base around traffic light on central island.
15-Jan-2020	3016718	Westminster Bridge SB cw approx 10m after Victoria Embankment	Please make safe a pothole around a metal cover.	Received	Inspection Response	Carriageway	Pothole	3	16-JAN-2020 17:33:30	VIAFIXED POTHOLE F.T.R LEFT; 21:26
15-Jan-2020	3016738	Westminster Bridge SB at lights approx 5m after Victoria Embankment	Pleaaa refix leaning IGP	Received	Inspection Response	Street Furniture	Bollard	3	16-JAN-2020 17:43:17	REPINNED IGP F.T.R LEFT; 21:42
20-Jan-2020	3020824	Blackfriars bridge NB approx 150m b4 Victoria embankment	Loss of material around mhc on cw	Received	Inspection Response	Carriageway	Ironwork	3	21-JAN-2020 22:09:52	made safe with bitmac over badly sunken cracking rocking very noisy MHC on cw on bus lane  needs to pass emergency S/81 to reset 1x badly sunken cracking rocking very noisy MHC on cw

**PUBLIC ENQUIRY RECORDS - VICTORIA EMBANKMENT - 01/11/2019 TO 21/04/2020**

Incident/Recorded Date	Pem Id	Location	Description	Hsc Status Name	Pem Category	Pem Class	Pem Type	Priority	Target Date	Action Remarks
13-Feb-2020	3043726	Embankment Pier - Victoria Embankment	Broken Manhole Cover	Received	Inspection Response	Carriageway	Carriageway Defect	3	14-FEB-2020 07:47:18	10:33 nothing found at location
16-Feb-2020	3046098	temple place along victoria embankment	flooding	Work Instructed	Emergency Call Outs	Carriageway	Flooding	1	16-FEB-2020 15:53:51	18:04, assisted gully tanker.
24-Feb-2020	3052258	Blackfriars Bridge nb approx 120m b4 Victoria embankment	m/s 3x rocking cracked and uneven York slabs	Received	Inspection Response	Footway	Footway Defect	3	25-FEB-2020 12:25:53	NOTHING FOUND LEFT: 21:45
24-Feb-2020	3052263	Blackfriars bridge nb approx 100m b4 Victoria embankment	m/s cracking and rocking slab	Received	Inspection Response	Footway	Footway Defect	3	25-FEB-2020 12:37:06	NOTHING FOUND LEFT: 21:47
11-Mar-2020	3069384	Horse Guards Avenue j/w Victoria Embankment	damaged central island in side road	Received	Inspection Response	Structures	Damaged	3	12-MAR-2020 15:50:22	Damaged island card left; 02:11 perm new island + 3 way lights