



SQA 8181 - Attending TfL Officer Report

Please complete all sections of this form, if not completing this form electronically, please use a Black pen. Date format is DD/MM/YY. Time Format is 24hr HH:MM. When you have completed the form, scan and attach to NAMS and send a copy to the third party claims handler

Incident Details			
Incident location (road name)	A316 Twickenham Road		
Incident type	Fatality car v cyclist		
TLRN (Yes or No)	Yes		
Date of incident	30/03/2021	Time of incident	Approx 16:30
CAD Ref (please ask for one if not given)		NMCC Ref (TIMS) number	
On site contact		Contact number	
Requested to attend site?	Yes	No	If no, reason
Were all Parties Informed?	Yes	No	If no, reason
Was an update received from NMCC supervisor?	Yes	No	Time and details of update

On site details		
Time arrived		
Vehicle Index Number (if still in there)		<i>Check that the number matches front and back</i>
VIN Number in vehicle (if still there)		<i>Located on the front screen and inside by drivers door</i>
Speed Limit of road	30mph	<i>Add multiple required</i>
Type of road	Single carriageway	<i>Dual / Single Carriageway</i>
Geography	Flat surface	<i>Is location on crest of a hill or sharp bend</i>



Asset Condition Details				
Carriageway condition	Are there any potholes?	Yes	No	If yes, details
	Does any area of the carriageway need resurfacing?	Yes	No	If yes, details
Gullies / Drains	Are they blocked?	Yes	No	If yes, details
	Are they damaged?	Yes	No	If yes, details
Studs	Do they need replacing?	Yes	No	If yes, details
Road markings	Are they worn?	Yes	No	If yes, details Double Red line markings are worn (TLRN side)
Iron works (manhole covers/drain covers etc)	Are they damaged?	Yes	No	If yes, details
Light columns	Are they damaged?	Yes	No	If yes, details However light column is day burning (on 24 hrs)
Streetlighting (if attended when on)	Are any not working?	Yes	No	If yes, details
Streetlighting (if attended when on)	Are any obscured by buildings or tress etc?	Yes	No	If yes, details
Trees/Green estate	Are they damaged	Yes	No	If yes, details
Trees/Green estate	Are there any low hanging branches or branches	Yes	No	If yes, details (NON TLRN) Trees/ Hedge holly tree within private residence is obscuring left side of car park exist.



	obscuring assets?			
--	-------------------	--	--	--

Signs	Are they damaged?	Yes	No	If yes, details  (NON TLRN) Triangular (Cycle) warning sign is missing on post on left side of the car park exit.
Traffic Signals/Cabinet	Are they damaged or misaligned?	Yes	No	If yes, details
Flooding/pooling water	Is there any?	Yes	No	If yes, details
Pavement	Any damage?	Yes	No	If yes, details Cross over consisting of HRA is worn.
PGR	Are they damaged?	Yes	No	If yes, details
Any other asset defects to note?		Yes	No	If yes, details Following an inspection, the cross over on TLRN consisting of HRA can be resurfaced but is not immediately creating a hazard for vehicles or MOP's.

**General Observations – check all that are present**

<p>Location information – please tick which are present</p>	<input checked="" type="checkbox"/> Signalled Pedestrian Crossing <input type="checkbox"/> Other Pedestrian Crossing <input checked="" type="checkbox"/> Tactile paving at crossings <input type="checkbox"/> Footbridge <input type="checkbox"/> Subway <input type="checkbox"/> On street parking <input type="checkbox"/> Loading bays <input type="checkbox"/> Bus stop <input type="checkbox"/> Bus stop with shelter <input checked="" type="checkbox"/> Directional or information signs <input type="checkbox"/> Tram tracks <input checked="" type="checkbox"/> Cycle lane <input type="checkbox"/> Roadworks <input type="checkbox"/> Temporary Traffic signals <input type="checkbox"/> Taxi rank <input checked="" type="checkbox"/> Trees/Green estate
---	--






<p>Buildings nearby (can you see)</p>	<p><input checked="" type="checkbox"/> School/college</p> <p><input type="checkbox"/> Hospital/Health Centre</p> <p><input type="checkbox"/> Fire/Ambulance station</p> <p><input type="checkbox"/> New housing or office development,</p> <p><input checked="" type="checkbox"/> Residential home</p> <p><input type="checkbox"/> Petrol station</p> <p><input type="checkbox"/> Supermarket</p>
<p>Any other general observations?</p> <p>TLRN side</p> <ul style="list-style-type: none"> <li>• Crossover on TLRN side of footway exiting the car park is worn however not causing an immediate hazard to all road users.</li> <li>• Kerb line separating Athletic Ground car park and cross over has cracks however not causing an immediate hazard to all road users.</li> <li>• Double Red lining on main drag of A316 Twickenham Road is worn.</li> </ul> <p>Athletic Ground car park</p> <ul style="list-style-type: none"> <li>• Missing triangular (Cycle) warning sign on post at the exit of the car park.</li> <li>• Missing give way and triangle markings within the car park.</li> <li>• New give way triangle sign required as present sign is faded.</li> </ul> <p>Rugby Court apartments</p> <ul style="list-style-type: none"> <li>• Holly bush to left hand side of car park exit is obscuring one side of the exit at the gates.</li> </ul>	





Photos









**Actions**

A large, empty rectangular box with a black border, intended for recording actions.

