

KENNINGTON LOOP - RESIDENTIAL COMPLAINTS FROM TRAIN NOISE

Table includes the average $L_{Amax,fast}$ noise levels (dB(A)) for each set of results. Where a cell is shaded, trains were not audible.

ADDRESS	LOOP LOCATION	KEN-OVL LOCATION	Date	Loop	NB	SB		Comments
DE LAUNE STREET, SE17 3UT								
			30-Oct-13	38	35	33		11/10/13 Resident claims N&V increased in recent months
	N192/NRD01 220m	N144/NSBLO 220m	14-Jan-15	40	33	30		Dec 2014 Resident reports increase in train noise. Further measurements on 14/01/15
		N144/NNBLO 570m	19-May-15	41				April 2015 TSR of 10mph introduced on the loop prior to re-rail in June/July.
			27-Oct-15	31 est				27/10/15 After re-railing approx 100-300m on loop. Train noise not measureable.
			24-Aug-17	38	29	31		Aug 2017 Measurements prior to tunnel rings removal in link with NLE. R2146
			27-Oct-17	39	30	29		Oct 2017 Measurements after tunnel rings removal in link with NLE. R2203
			18-Dec-17	38				Dec 2017 Measurements prior to NLE Step Plate Junction installation
			17-Jan-18	33				Jan 2018 measurements aftr SPJ installation (Report R2256)
STANNARY STREET, SE11 4AA								
	N192/NRD01 570m	N144/NSBLO 265m	17-Nov-17	45	32	31		22/11/17 Initial measurements taken Report R2214
		N144/NNBLO 525m						
RAVENSDON STREET, SE11 4AR								
	N192/NRD01 620m	N144/NSBLO 200m	09-Feb-16	41	31	31	bedroom	2/2/16 Contact passed on by resident [REDACTED] Ravensdon
		N144/NNBLO 580m	13-Sep-16	43	32		bedroom	11/11/16 After partial re-rail of the loop (inc. part of Ravensdon St, but not in proximity of property)
				47	34	34	kitchen	
			11-Nov-16	46	30	29	bedroom	
				48	34	33	kitchen	
RAVENSDON STREET, SE11 4AQ								
	N192/NRD01 600m	N144/NSBLO 245m	10-Nov-17	37	31			22/11/17 Initial measurements taken Report R2213
		N144/NNBLO 545m	09-Feb-18	35	31			9/2/18 Measurements after NLE step plate junction works Christmas 2017 to New Year
RAVENSDON STREET, SE11 4AR								
	N192/NRD01 620m	N144/NSBLO 240m	23-Mar-17	46	32	30		9/3/17 Resident had previously contacted high levels in TfL & London Assembly.
		N144/NNBLO 550m						23/3/17 Initial measurements taken Report R2012
RAVENSDON STREET, SE11 4AQ								
								14/01/14 Visit to house as part of NLE Inspector visits.
	N192/NRD01 600m	N144/NSBLO 240m	11-Feb-14	42	40	29		24/2/14 Report recommended grinding (or re-railing if grinding not possible)
		N144/NNBLO 540m	12-Dec-14	45	35	31		12/12/14 Property measurements. Showed increased noise
			27-Oct-15	43	38	31		27/10/15 After re-railing part of loop (not under Ravensdon St).
			14-Dec-15	42	34	31		14/12/15 After further re-railing on part of loop (not under [REDACTED] Ravensdon St).
			16-Sep-16	49	38	35		
			18-Nov-16	45	34	32		18/11/16 After partial re-rail of the loop (inc. part of Ravensdon St).
			23-Mar-17	48	33	31		23/3/17 Measurements to assess how noise levels have changed. R2011
			30-Aug-17	48	33	28		Aug 2017 Measurements prior to tunnel rings removal in link with NLE. R2149
			27-Oct-17	49	34	30		Oct 2017 Measurements after tunnel rings removal in link with NLE. R2204
			19-Dec-17	48	33	30		Dec 2017 Measurements prior to NLE Step Plate Junction installation
			08-Jan-18	47	32	29		Jan 2018 measurements after SPJ installation (Report R2248)
			17-Apr-18	49	32			April 2018 measurements after resident reported increase in noise

KENNINGTON LOOP - RESIDENTIAL COMPLAINTS FROM TRAIN NOISE

Table includes the average $L_{Amax,fast}$ noise levels (dB(A)) for each set of results. Where a cell is shaded, trains were not audible.

ADDRESS	LOOP LOCATION	KEN-OVL LOCATION	Date	Loop	NB	SB	Comments
RAVENSDON STREET, SE11 4AQ							
	N192/NRD01 600m	N144/NSBLO 240m N144/NNBLO 540m	17-Apr-18	49	37		17/4/18 Initial measurements at request of resident.
RAVENSDON STREET, SE11 4AQ							
	N192/NRD01 620m	N144/NSBLO 220m N144/NNBLO 565m	17-Apr-18	39			17/4/18 Initial measurements prompted by resident contacting MD's office.
METHLEY STREET, SE11 4AJ							
	N192/NRD01 680m	N144/NSBLO 160m N144/NNBLO 620m	15-Feb-16				6/12/15 Resident contacted Community Relations 9/2/16 Property visited. No measurements, as trains barely audible.
METHLEY STREET, SE11 4AL							
			13-Sep-16	38	31	30	Living room 28/8/16 Resident took up MDs offer for any resident to have measurements taken
	N192/NRD01 680m	N144/NSBLO 160m		43	36		kitchen
		N144/NNBLO 620m	18-Nov-16	33	29	29	Living room 18/11/16 After re-rail part of the loop. Noise reduced for trains on the loop. Resident satisfied.
METHLEY STREET, SE11 4AQ							
	N192/NRD01 680m	N144/NSBLO 160m N144/NNBLO 620m	10-Oct-16	30			10/10/16 Accepted MD offer for measurements. After part re-rail of the loop. Levels low.
CLEAVER SQUARE, SE11 4DW							
	N192/NRD01 720m	N144/NSBFA 120m N144/NNBFA 650m	02-Dec-16	29	29	28	2/12/16 Accepted MD offer for measurements. After part re-rail of the loop. Levels low. Resident not disturbed by current train noise level. Concern was that it worse get worse.
CLEAVER SQUARE, SE11 4DW							
	N192/NRD01 720m	N144/NSBFA 120m N144/NNBFA 650m	18-Jan-18	33			18/1/18 Measurements after NLE junction works Christmas 2017 / New Year. R2268

OTHER PROPERTIES WHERE THE RESIDENT HAS COMPLAINED, BUT NO MEASUREMENTS HAVE BEEN TAKEN

- METHLEY STREET, SE11 4AL
- METHLEY STREET, SE11 4AL
- METHLEY STREET, SE11 4AJ
- RAVENSDON STREET, SE11 4AR
- RAVENSDON STREET, SE11 4AR
- RADCOT STREET, SE11 4AH
- STANNARY STREET, SE11 4AA
- DE LAUNE STREET, SE17 3UR