



Hazardous Material Asset Register- Detail



Run date: 26/05/2022 Line: JNP Assessment Status: All Material Status: All Material Type: All

Ref.	Status	Status Date	Main Line	Location Code	Location Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Positio	Notes	Qty. Metre	Qty. Units	Lead Paint %	PCB %	Surface Code	Asbestos Type	Assesme Score	Date Identified	Report Ref.	Above False Ceiling	Below False Floor	
1757	ACTIVE	26/01/2015	J	N135-00-3/793	Vent Shaft - Station Building - London Bridge Stn	No Access	Asbestos	No Access: Presumed				Restricted Access Fans need to be isolated before entry, Two Man team required							0					
Ref.							Material: Asbestos Type	Material: Condition Code	Material: Product Type	Material: Surface Code	Priority: Disturbance	Priority: Exposure	Priority: Maint. Activity	Priority: Occupant Activity										
1757																								
2793	ACTIVE	14/04/2014	J	N135-00-3/794	Vent Shaft - Station Building - London Bridge Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed							0					
Ref.							Material: Asbestos Type	Material: Condition Code	Material: Product Type	Material: Surface Code	Priority: Disturbance	Priority: Exposure	Priority: Maint. Activity	Priority: Occupant Activity										
2793																								
2504	ACTIVE	26/01/2015	J	N135-00-3/795	Vent Shaft - Station Building - London Bridge Stn	No Access	Asbestos	No Access: Presumed				Restricted Access Fans need to be isolated before entry, Two Man team required							0					
Ref.							Material: Asbestos Type	Material: Condition Code	Material: Product Type	Material: Surface Code	Priority: Disturbance	Priority: Exposure	Priority: Maint. Activity	Priority: Occupant Activity										
2504																								
1758	ACTIVE	26/01/2015	J	N135-00-3/796	Vent Shaft - Station Building - London Bridge Stn	No Access	Asbestos	No Access: Presumed				Restricted Access Fans need to be isolated before entry, Two Man team required							0					
Ref.							Material: Asbestos Type	Material: Condition Code	Material: Product Type	Material: Surface Code	Priority: Disturbance	Priority: Exposure	Priority: Maint. Activity	Priority: Occupant Activity										
1758																								
2561	ACTIVE	26/01/2015	J	N135-00-3/797	Vent Shaft - Station Building - London Bridge Stn	No Access	Asbestos	No Access: Presumed				Restricted Access Fans need to be isolated before entry, Two Man team required							0					
Ref.							Material: Asbestos Type	Material: Condition Code	Material: Product Type	Material: Surface Code	Priority: Disturbance	Priority: Exposure	Priority: Maint. Activity	Priority: Occupant Activity										
2561																								
1759	ACTIVE	26/01/2015	J	N135-00-3/798	Vent Shaft - Station Building - London Bridge Stn	No Access	Asbestos	No Access: Presumed				Restricted Access Fans need to be isolated before entry, Two Man team required							0					
Ref.							Material: Asbestos Type	Material: Condition Code	Material: Product Type	Material: Surface Code	Priority: Disturbance	Priority: Exposure	Priority: Maint. Activity	Priority: Occupant Activity										
1759																								
1760	ACTIVE	26/01/2015	J	N135-00-3/988	Vent Shaft - Station Building - London Bridge Stn	No Access	Asbestos	No Access: Presumed				Restricted Access Fans need to be isolated before entry, Two Man team required							0					
Ref.							Material: Asbestos Type	Material: Condition Code	Material: Product Type	Material: Surface Code	Priority: Disturbance	Priority: Exposure	Priority: Maint. Activity	Priority: Occupant Activity										
1760																								
2358	ACTIVE	14/04/2014	J	N135-00-3/989	Vent Shaft - Station Building - London Bridge Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed							0					
Ref.							Material: Asbestos Type	Material: Condition Code	Material: Product Type	Material: Surface Code	Priority: Disturbance	Priority: Exposure	Priority: Maint. Activity	Priority: Occupant Activity										
2358																								
2794	ACTIVE	14/04/2014	J	N135-00-4/071	Circulation Area - Station Building - London Bridge Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed							0					
Ref.							Material: Asbestos Type	Material: Condition Code	Material: Product Type	Material: Surface Code	Priority: Disturbance	Priority: Exposure	Priority: Maint. Activity	Priority: Occupant Activity										
2794																								

