

Incident/Recorded Date	Pem Id	Location	Description	Hsc Status Name	Pem Category	Pem Class	Pem Type	Priority	Target Date	Complete Date	Action Remarks
20-Aug-2018	2695089	ROEHAMPTON LANE J/W CLARENCE LANE NB AT CROSSING POINT	GAP / DEPRESSION IN C/W - NEAR KERB	Work Actioned	Inspection Response	Carriageway	Carriageway Defect	3	21-AUG-2018 11:00:45	NULL	BITMACED - 5 SHOVELS OF BITMAC USED LEFT: 12:16 - PERM 4SQM PATCH WITH H.R.A