

Route: PM1/2 - Nor - NN211 - Camden Town To Kentish Town & Chalk Farm (Both)
 Target Start Date: 10/01/2023 This inspection Work Order: 85188609

Area(s) not inspected: _____ Reasons: _____ To be completed by STM/Inspection Manager: _____
 Key to Fault Action Periods (1-159 Standard Minimum Actions) :- Referred to TLCC (Tick)
 A. 24 Hours D. 1 Week G. 8 Weeks J. 12 Months M. Inspect/Monitor and plan further action if nec.
 B. 36 Hours E. 2 Weeks H. 3 Months K. Before Dec
 C. 48 Hours F. 3 Weeks I. 6 Months L. Before Hot Weather
 Closed no action required (Tick)
 STM to inspect/under observation (Tick)
 CMF Required (Tick)
 Fault Classification (SS/ML/MT/MX/RD)
 Fault Action Period
 Cause Code

Faults identified During Patrol:-					Fix On Find (Y/N)	Failure Class	Problem Code	Work Order No.
Location Code	Start (M)	Finish (M)	Side (L/M/R/B)	Fault Details				
				COMPLETED ON IPAD				

Declaration by person carrying out inspection: Insofar as I am able to determine within the limitations of my formal accreditation and the scope of the inspection which I have undertaken in accordance with the relevant Standards, the assets concerned were safe for their currently authorised use at the time of the inspection and subject to any exception or conditions stated in my report, I have no reason to believe that the inspected assets are likely to become unsafe before the next inspection.

Inspection Carried out by: _____		Checked and Actioned By: _____		Details Entered Into Maximo By: _____	
Print Name: _____	T001 IV Number: _____	Print Name: _____	Print Name: _____	Print Name: _____	Print Name: _____
Signature: _____	Date: 11/01/2023	Signature: _____	Signature: _____	Signature: _____	Signature: _____
Start: 01.10	Finish: 03.30	Date: 11/01/23	Date: 11/01/23	Date: 11/01/2023	Date: 11/01/2023

Work Order: [851388609](#)

PM3 - Nor - NN211 - Camden Town To Kentish Town (Both) (Tue:

Business

Related Work Orders

[Filter](#)

1

-

8 of 8



Work Order	Description	Class	Wor
> 85651225	> Chair-Fixings-Screws/Spikes/Bushes-Missing/Defective/Not Secure-ML: 4 to 7 Per 5 Sleepers. ::(On the same rail.) - Road NBLO - NOR - Camden Town to Chalk Farm	WORKORDER	CM
> 85651226	> Chair-Fixings-Screws/Spikes/Bushes-Missing/Defective/Not Secure-ML: 4 to 7 Per 5 Sleepers. ::(On the same rail.) - Road NBLO - NOR - Camden Town to Chalk Farm	WORKORDER	CM
> 85651227	> Chair-Keys-Missing/Defective/Not Secure-SS: 3 per group Of Five Sleepers on the same rail - Road NBLO - NOR - Camden Town to Chalk Farm	WORKORDER	CM
> 85651228	> Chair-Fixings-Screws/Spikes/Bushes-Missing/Defective/Unsecure-SS: 8 or More Per 5 Sleepers. ::(On the same rail.) - Road NBLO - NOR - Camden Town to Chalk Farm	WORKORDER	CM
> 85651229	> Con Rail-Negi-Vert. Pos from NOMINAL position above RR-SS: -10mm Below RR / +25mm Above RR - Road NBLO - NOR - Camden Town to Chalk Farm	WORKORDER	CM
> 85651231	> ML-NO OPTION-ASM to RAISE NEW STD FAULT - Road NBLO (Pit1) - NOR - Chalk Farm Stn	WORKORDER	CM
> 85651232	> Con Rail-Insulators-SS: 8 per 100m Cracked/Broken/Secured By < 4 screws/Defective Packing - Road SBLO - NOR - Chalk Farm to Camden Town	WORKORDER	CM
> 85651233	> Baseplate-Pandrol Clips-Missing/Defective/Not Secure-SS: 4 per group Of Five (Cat A-C track) - Road SBLO - NOR - Chalk Farm to Camden Town	WORKORDER	CM

[Select Work Orders](#)[New Row](#)