NRM Saloon Cooling and Comfort Audit Location: Hyde Park Corner/Marble Arch

Date: 8.8.14

Route number	Fleet No	Cooling unit operating (cool air from vents) Y/N	Upper saloon temperature comfortable Y/N	Temperature recorded and other comments
148	**LT127**	**Yes**	**No**	
10	**LT160**	**Yes**	**Yes**	**28c Vents Dirty**
148	**LT146**	**Yes**	**No**	
390	**LT40**	**Yes**	**No**	**32c Vents Dirty**
10	**LT153**	**Yes**	**Yes**	
148	**LT141**	**Yes**	**No**	
10	**LT154**	**Yes**	**Yes**	
148	**LT130**	**Yes**	**No**	
148	**LT144**	**Yes**	**No**	
10	**LT162**	**Yes**	**Yes**	
10	**LT148**	**Yes**	**No**	
148	**LT131**	**Yes**	**No**	
10	**LT163**	**Yes**	**No**	
148	**LT143**	**Yes**	**No**	
10	**LT164**	**Yes**	**Yes**	**29c Vents Dirty**
148	**LT84**	**Yes**	**Yes**	
148	**LT139**	**Yes**	**Yes**	