

NRM Saloon Cooling and Comfort Audit Report

Date: 07-08-2014

Oxford Street	Route number	Fleet No	Cooling unit operating (cool air from vents) Y/N	Temperature, centre U/S	Temperature rear of U/S	Comments
---------------	--------------	----------	--	----------------------------	----------------------------	----------

Oxford Street	10	LT156	Y	22	26	
Oxford Street	10	LT149	Y	24	28	
Oxford Street	10	LT162	Y	25	27	
Oxford Street	10	LT168	Y	29	30	
Oxford Street	10	LT153	Y	26	29	
Oxford Street	10	LT175	Y	27	29	
Oxford Street	10	LT91	Y	27	30	
Oxford Street	10	LT157	Y	28	31	
Oxford Street	10	LT170	Y	24	27	
Oxford Street	10	LT80	Y	24	28	
Oxford Street	10	LT160	Y	26	30	
Oxford Street	390	LT37	Y	23	28	
Oxford Street	390	LT117	Y	25	26	
Oxford Street	390	LT32	Y	24	29	
Oxford Street	390	LT106	N	24	28	
Oxford Street	390	LT17	Y	26	31	
Oxford Street	390	LT115	N	30	32	
Oxford Street	390	LT37	Y	25	29	
Oxford Street	390	LT109	Y	26	30	
Oxford Street	390	LT96	Y	24	28	

[illegible]