

Lift and Escalator Inspection Form



Report Of Examination of Escalator / Conveyor - PM45+

 Work Order Number:
 90190387
 Date Inspected:
 10/01/2024
 Issue - 00:

1. Machine Details

Station: Escalator - 09 - Station Building - London Bridge Stn Manufacturer: O&K Line: Jubilee

Date Of Construction: 06/10/1997 Maintainer: LE-INSP

2.1. DESIGN AND CONSTRUCTION, ARE ALL PARTS OF THE ESCALATOR OF GOOD MECHANICAL CONSTRUCTION SOUND MATERIAL & ADEQUATE STRENGTH (SO FAR ASCERTAINABLE)

NOTE: GIVE DETAILS OF RENEWALS OR ALTERATION IN (5) AND (6) BELOW

2.2. MAINTENANCE: ARE THE FOLLOWING PARTS OF THE ESCALATOR PROPERLY MAINTAINED AND IN GOOD WORKING ORDER? IF NOT, STATE WHAT DEFECTS HAVE BEEN FOUND.

NOTE: GIVE DETAILS OF RENEWALS OR ALTERATION IN (5) AND (6) BELOW

3. INSPECTION CHECKLIST: INDICATE IN COLUMN PROVIDED YES, NO OR N/A (NOT APPLICABLE). WHERE "NO" IS INDICATED, RECORD OVERLEAF THE NECESSARY INFORMATION USING THE ITEM REFERENCE LETTER

| | | 1 | |
|------------------------------------------------------------|-----|------------------------------------------|-----|
| a) Engineering Drawings | YES | I) Engineers Barriers | YES |
| b) Combs Combplates & Switches | YES | m) Machine Room Security | YES |
| c) Keyswitches | YES | n) Access/egress | YES |
| d) Handrail System & Entry Guard Switches | YES | o) Cleanliness/tidiness Of Machine Rooms | YES |
| e) Safety Devices | у | p) Lighting | YES |
| e.1.1) Safety Devices: No Volt-circuit | N/A | q) Controller/annunciator/plc | YES |
| e.1.2) Safety Devices: Earth Detection Or Residual Current | YES | r) Motor | YES |
| Device | | s) Gear | YES |
| e.2.1) Safety Devices: Underspeed Governor | YES | t) Brakes | YES |
| e.2.2) Safety Devices: Overspeed Governors/ Encoder | YES | u) Drive Chains | YES |
| e.3.1) Safety Devices: Stop Diamond | YES | v) Newel Wheels & Bearings | YES |
| e.3.2) Safety Devices: Stop Buttons/isolators | YES | w) Inching Stations/buttons | YES |
| e.4.1) Safety Devices: Broken Handrail Detection Switch | N/A | x) Lubricator | YES |
| e.4.2) Safety Devices: Handrail Switches/sensors | YES | y) Load Relieving Ramps | YES |
| e.5.1) Safety Devices: Missing Step/low Step Detectors | YES | z)Tracks | NO |
| e.6.1) Safety Devices: Carriage Switches | YES | aa) Chain & Trailer Wheels | YES |
| e.7.1) Safety Devices: Kinked Link Detector | YES | bb) Steps/pallets | YES |
| f) Passenger Barriers | YES | cc) Tension Carriage | YES |
| g) Step Side Clearances | YES | dd) Guarding | YES |
| h) Brush Guard | YES | ee) Circuit Breaker/main Isolator YES | |
| i) Balustrade & Decking Panels | YES | ff) Other Parts YES | |
| j) Step Chain Condition \ Chain Wear | YES | gg) Cleanliness of Escalator YES | |
| k) Step Treads | YES | 00/ | + |

4. WHAT PARTS (IF ANY) WERE INACCESSIBLE?

All enclosed parts

5. REPAIRS, RENEWALS OR ALTERATIONS REQUIRED TO ENABLE THIS LIFT TO CONTINUE TO BE USED WITH SAFETY.

IF NO SUCH REPAIRS, RENEWALS OR ALTERATIONS ARE REQUIRED, ENTER "NONE" [PLEASE REFER TO PAGES 2 AND 3 FOR INSPECTION DETAILS]

a) IMMEDIATELY

NO

b) WITHIN A SPECIFIED TIME, THE SAID TIME TO BE STATED

NO

OP-BIRT-LE-QR-DE-0092 - JamesDupree 04/08/2024 21:24 1 of 2



Work Order

Number:

Lift and Escalator Inspection Form



| Report | Of Examination of Es | scalator / Conveyor - | PM45+ | |
|--------|----------------------|-----------------------|-------|--|
| | | | | |

10/01/2024

6. DEFECTS (OTHER THAN THOSE SPECIFIED AT 5 ABOVE) WHICH REQUIRE ATTENTION. LIST URGENT AND OTHER

Date Inspected:

Upper comb - 4 4 4 lower comb - 444

Both comb plates were adjusted at the time of the inspection (obs).

Issue - 00:

LH - 3 3 2 3 2 2 2 3 2 4 3 2 2 3 3 4 4 3 3 3 2 3 3 3 2 3 3 g) Step Side Clearances

j) Step Chain Condition \ Chain Wear Step To Step Gap 4mm.

Worn Cleats Throughout Machine. (OBS) k) Step Treads

t) Brakes Stop Distance 720 / 1390mm. Slight Float Both Lower Newel Wheels. (OBS). v) Newel Wheels & Bearings

z)Tracks 3 Off Damaged Track Brackets Upper LH RTN Curve. Work In Progress. (OBS).

7. OTHER OBSERVATIONS

b) Combs Combplates & Switches

Step Band Speed 0.75 M/SEC M/SEC Lh Handrail Speed 0.75 Rh Handrail Speed M/SEC 0.75

8. DATE OF INSPECTION **LAST** DUE

a. WORM GEARS TO BE EXPOSED AT 10 YEARLY INTERVALS

90190387

b. THE OVERSPEED GOVERNOR TO BE TESTED EVERY 5 YEARS (IN ACCORDANCE WITH HEALTH AND SAFETY EXECUTIVE)

IN THE EVENT OF A SERIOUS DEFECT BEING DISCOVERED THE JNP FAULT REPORTING CENTRE MUST BE NOTIFIED IMMEDIATELY

NAME OF THE INSPECTOR:

QUALIFICATION:

I CERTIFY THAT ON

ADDRESS:

10 Jan 2024 23:30

I THOROUGHLY EXAMINED THIS ESCALATOR AND THAT THE FOREGOING IS A CORRECT REPORT OF THE RESULT

SIGNATURE: Number:

APD Lifts and Escalator Inspection Systems and Infrastructure

1st Floor Frank Pick House Bollo Lane Acton W3 8RP

Number of Records:

2 of 2 OP-BIRT-LE-QR-DE-0092 - James Dupree