

Incident Response Report: Id: 711535

Customer Details

Customer:	<input type="text" value="Damien NMCC"/> → ...	Title:	<input type="text" value="Damien"/>
Forenames:	<input type="text"/>	Surname:	<input type="text"/>
Email Address:	<input type="text"/>	Phone Number:	<input type="text"/>
Building Number:	<input type="text"/>	Building Name:	<input type="text"/>
Street:	<input type="text"/>	Town:	<input type="text"/>
Post Code:	<input type="text"/>		

Job Details

Duty Officer:	<input type="text"/> → ...	% Complete:	<input type="text" value="100"/>
Client Reference:	<input type="text"/>	Source:	<input type="text" value="Incident Response Report"/>
Status:	✓ <input type="text" value="Completed"/>	Original Priority:	<input type="text"/>
Priority:	■ <input type="text" value="Emergency Call Out - 1 Hour"/>	Received Date/Time:	<input type="text" value="09/03/2024"/> <input type="text" value="13:08"/>
Dispatched Date/Time:	<input type="text"/>	Area:	<input type="text"/>
District:	<input type="text"/>	On Site Date/Time:	<input type="text" value="09/03/2024"/> <input type="text" value="13:49"/>
Completed Date/Time:	<input type="text" value="09/03/2024"/> <input type="text" value="17:44"/>	SLA Due Date/Time:	<input type="text" value="09/03/2024"/> <input type="text" value="14:08"/>
Reported By:	<input type="text" value="Public Enquiry"/>	SLA Status:	✓ <input type="text" value="Pass"/>
Job Type:	<input type="text" value="Enquiry"/>		
Location:	<input type="text" value="A12, Eastbound, Exit Greenman Tunnel Lane 1,"/>	Details:	<input type="text" value="FTR-[Job Complete Cover Replaced] - ENQ29571 -A12, Eastbound, Exit of Greenman Tunnel Lane 1 - Part Of Manhole cover Sunk[Damien TFL Tunnels confirmed that he is putting up the X;s on the Gantry on both Greenman tunnel and George Green."/>

Notes:

1/ Day NE have left site to go back to the yard to

Estimated Duration:	10.00	Estimated Duration Unit:	Minute(s)
Police Incident Number:	CAD1924	Enquiry Number:	ENQ29571
Party Responsible For FollowUp:		Community Stewards On Duty:	
Additional Attendees:		Action Taken By Duty Officer:	
Inspected By:		Closed:	No
Actual Repair Type:	Permanent	Work Type:	<input type="checkbox"/> LS-P - Core Service – Permanent Repair
Site Made Safe:	09/03/2024 13:51	Job Made Safe:	09/03/2024 17:44
Current Owner:			
Owner Details:		Logged By:	Glen McDonald → ...
Recording Gang:		Out of Hours:	No
Zendesk Ticket Id:			

Works Information

Map Location:

1 Point(s): 51.572518681858796, 0.015031299570353873 OSGR: 539741,187885

Borough: Waltham Forest

USRN/ESU:

22841880 HACKNEY TO M11 LINK
ROAD LEYTONSTONE (ESU:
5396280187890)

ESU Priority:

Notice Type:

Works Date:

Recharge

Damage Report Completed &
Sent:

No

Damage Report Response
Received:

No

Date Of Response:

Rechargeable:

No

Cost Code:

Recharge Applicable:

Recharge Information: