



Hazardous Material Asset Register - Summary



Run date: 19/08/2024

Line:

Risk Assessment Status: Active, Draft, Inactive
Hazardous Material Status: All
Hazardous Material Type: All

M071-M - MET Line - Pinner Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
66061	ACTIVE	M	M071-M-NBLO	Road NBLO (Plt1) - MET - Pinner Stn	Ducts	Asbestos	Known	83		LHS	Bitumen cable duct. To platform side wall (non asbestos cable within)		1	R415540		

M091-M - MET Line - Harrow on the Hill Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
45713	ACTIVE	M	M091-M-SBLO	Road SBLO (Plt5) - MET - Harrow on the Hill Stn	Other Electrical Boxes	Asbestos	Presumed				Trackside equipment electrical box Notes from 2021 re-inspection: CTB box		1		N	N
45714	ACTIVE	M	M091-M-SBLO	Road SBLO (Plt5) - MET - Harrow on the Hill Stn	Westinghouse Boxes	Asbestos	Presumed	69		RHS	Trackside equipment westinghouse small Notes from 2021 re-inspection: EP valve		1			
45715	ACTIVE	M	M091-M-SBLO	Road SBLO (Plt5) - MET - Harrow on the Hill Stn	Other Electrical Boxes	Asbestos	Presumed				Trackside equipment electrical box large Notes from 2021 re-inspection: CTB boxes		1		N	N
45716	ACTIVE	M	M091-M-SBLO	Road SBLO (Plt5) - MET - Harrow on the Hill Stn	Other Electrical Boxes	Asbestos	Presumed				Trackside equipment electrical box large Notes from 2021 re-inspection: CTB box		1		N	N
45717	ACTIVE	M	M091-M-SBLO	Road SBLO (Plt5) - MET - Harrow on the Hill Stn	Cable Ducts: Cement	Asbestos	Known				Cement duct		2		N	N
45718	ACTIVE	M	M091-M-SBLO	Road SBLO (Plt5) - MET - Harrow on the Hill Stn	Cable Ducts: Cement	Asbestos	Known				Cement duct		4		N	N
45719	ACTIVE	M	M091-M-SBLO	Road SBLO (Plt5) - MET - Harrow on the Hill Stn	Other Electrical Boxes	Asbestos	Presumed				Trackside equipment electrical box Notes from 2021 re-inspection: CTB box				N	N

M096-M - MET Line - Preston Road to Wembley Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
27254	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	10		LHS	Trackside equipment westinghouse large		2			
26332	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Signal Boxes	Asbestos	Presumed	12		LHS	Trackside equipment signal MG69		1			



Hazardous Material Asset Register - Summary



M096-M - MET Line - Preston Road to Wembley Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
26331	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	12		LHS	Trackside equipment westinghouse small Notes from 2021 re-inspection: EP valve		1			
26333	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	40		LHS	Trackside equipment westinghouse small		1			
27629	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Track Section Switches	Asbestos	Presumed	52		LHS	Trackside equipment current rail switch box		2			
26334	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	54		LHS	Trackside equipment westinghouse extra large Notes from 2021 re-inspection: Kiosk, not XL WH		1			
26335	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Signal Boxes	Asbestos	Presumed	81		LHS	Trackside equipment tencore		1			
27462	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Track Section Switches	Asbestos	Presumed	300		LHS	Trackside equipment electrical box Notes from 2021 re-inspection: CTB box		1			
26336	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Track Section Switches	Asbestos	Presumed	332		LHS	Trackside equipment electrical box Notes from 2021 re-inspection: CTB box		1			
26337	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Track Section Switches	Asbestos	Presumed	334		LHS	Trackside equipment electrical box Notes from 2021 re-inspection: CTB box		1			
26338	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Signal Boxes	Asbestos	Presumed	344		LHS	Trackside equipment tencore		1			
26339	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Cable Wrap	Asbestos	Known	350		LHS	J hangerno. 2 woven cable					
26340	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Track Section Switches	Asbestos	Presumed	449		LHS	Trackside equipment electrical box Notes from 2021 re-inspection: CTB box		1			
26341	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	542		LHS	Trackside equipment westinghouse large		2			
26342	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	545	548	LHS	Trackside equipment westinghouse large		4			
27566	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Cable Sheath	Asbestos	Known	551		LHS	Woven cable sheath 5mm earth cable, Exit: bottom of box					
26343	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Signal Boxes	Asbestos	Presumed	551		LHS	Trackside equipment signal and tencore box		1			
26344	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	561		LHS	Trackside equipment westinghouse small		2			
27459	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	562		LHS	Trackside equipment westinghouse small		2			



Hazardous Material Asset Register - Summary



M096-M - MET Line - Preston Road to Wembley Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
26345	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Track Section Switches	Asbestos	Presumed	675		LHS	Trackside equipment electrical box Notes from 2021 re-inspection: CTB box		1			
26346	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	682		LHS	Trackside equipment westinghouse large		3			
26347	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	686		LHS	Trackside equipment westinghouse large		3			
26348	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	686		LHS	Trackside equipment westinghouse large		3			
26350	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Signal Boxes	Asbestos	Presumed	693	695	LHS	Trackside equipment tencore		1			
26349	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	693	695	LHS	Trackside equipment westinghouse large		3			
26351	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Removed	698		LHS	Trackside equipment westinghouse large Notes from 2021 re-inspection: Removed		2			
26352	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Removed	700		LHS	Trackside equipment westinghouse large Notes from 2021 re-inspection: Removed		1			
26353	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	702		LHS	Trackside equipment westinghouse small Notes from 2021 re-inspection: EP valve		1			
26354	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Signal Boxes	Asbestos	Presumed	703		LHS	Trackside equipment signal A652 and tencore Notes from 2021 re-inspection: 3x, not 2		3			
26355	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	705		LHS	Trackside equipment westinghouse small		1			
26356	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	706		LHS	Trackside equipment westinghouse small		1			
46807	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	712		LHS	Trackside equipment westinghouse small		1			
46808	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	713		LHS	Trackside equipment westinghouse small		1			
26357	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	958		LHS	Trackside equipment westinghouse small		1			
26358	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	959		LHS	Trackside equipment westinghouse small Notes from 2021 re-inspection: 2x, not 1 SWH		1			



Hazardous Material Asset Register - Summary



M096-M - MET Line - Preston Road to Wembley Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
26359	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	1051		LHS	Trackside equipment westinghouse large		3			
27630	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	1054		LHS	Trackside equipment westinghouse large		3			
27463	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	1059		LHS	Trackside equipment rail gap indicator and westinghouse small		1			
26360	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	1064		LHS	Trackside equipment westinghouse large		1			
26361	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	1067		LHS	Trackside equipment westinghouse large		3			
26370	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Signal Boxes	Asbestos	Removed	1070		LHS	Trackside equipment tencore Notes from 2021 re-inspection: Removed		1			
26371	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Signal Boxes	Asbestos	Presumed	1072		LHS	Trackside equipment signal R654		1			
26372	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Cement Cable Troughing & Debris	Asbestos	Removed	1080		UTX	Cement cable troughing Notes from 2021 re-inspection: Removed		2			
26373	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Cement Cable Troughing & Debris	Asbestos	Removed	1080			Cement asbestos debris Notes from 2021 re-inspection: Removed					
26376	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Cement Cable Troughing & Debris	Asbestos	Removed	1082		LHS	Cement cable troughing, 1/2LM Notes from 2021 re-inspection: Removed		1			
26375	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Cement Cable Troughing & Debris	Asbestos	Removed	1082			Cement asbestos debris Notes from 2021 re-inspection: Removed					
26374	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Cement Cable Troughing & Debris	Asbestos	Removed	1082		UTX	Cement cable troughing Notes from 2021 re-inspection: Removed		1			
27567	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Removed	1083			Trackside equipment westinghouse small Notes from 2021 re-inspection: Removed		1			
26377	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Removed	1083		LHS	Trackside equipment westinghouse small Notes from 2021 re-inspection: Removed		1			
26378	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Removed	1085		LHS	Trackside equipment westinghouse small Notes from 2021 re-inspection: Removed		1			



Hazardous Material Asset Register - Summary



M096-M - MET Line - Preston Road to Wembley Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
26362	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Removed	1086		LHS	Trackside equipment westinghouse small Notes from 2021 re-inspection: Removed		1			
26363	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	1180		LHS	Trackside equipment westinghouse large Notes from 2021 re-inspection: 1x LWH, not 2		2			
46809	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	1182		LHS	Trackside equipment westinghouse small		2			
26364	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	1184		LHS	Trackside equipment westinghouse small		2			
26365	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	1185		LHS	Trackside equipment westinghouse small		2			
27631	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	1295	1303	LHS	Trackside equipment westinghouse large		13			
26366	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Signal Boxes	Asbestos	Presumed	1304		LHS	Trackside equipment tencore		1			
26367	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Signal Boxes	Asbestos	Presumed	1307		LHS	Trackside equipment signal A654		1			
26368	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Signal Boxes	Asbestos	Presumed	1309		LHS	Trackside equipment tencore		1			
26369	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	1319		LHS	Trackside equipment westinghouse small		2			
26379	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Removed	1320		LHS	Trackside equipment westinghouse small Notes from 2021 re-inspection: Removed		1			
26380	ACTIVE	M	M096-M-NBFA	Road NBFA - MET - Wembley Park to Preston Road	Cable Sheath	Asbestos	Removed	1322		LHS	Woven cable insulation asbestos cable and plastic, High level into bridge MR36 Notes from 2021 re-inspection: Removed					
26381	ACTIVE	M	M096-M-NBLO	Road NBLO - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	38		RHS	Trackside equipment westinghouse small TENCORE		1			
26383	ACTIVE	M	M096-M-NBLO	Road NBLO - MET - Wembley Park to Preston Road	Cement Cable Troughing & Debris	Asbestos	Known	43		RHS	Cement debris, Sampled previously Notes from 2021 re-inspection: Fibreglass troughing not ACM					
26382	ACTIVE	M	M096-M-NBLO	Road NBLO - MET - Wembley Park to Preston Road	Track Section Switches	Asbestos	Known	43		RHS	Trackside equipment current rail switch box		2			
27464	ACTIVE	M	M096-M-NBLO	Road NBLO - MET - Wembley Park to Preston Road	Signal Boxes	Asbestos	Known	49		RHS	Trackside equipment current rail switch box		2			



Hazardous Material Asset Register - Summary



M096-M - MET Line - Preston Road to Wembley Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
26384	ACTIVE	M	M096-M-NBLO	Road NBLO - MET - Wembley Park to Preston Road	Cement Cable Troughing & Debris	Asbestos	Known	49		RHS	Cement debris,Sampled previously					
26385	ACTIVE	M	M096-M-NBLO	Road NBLO - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	68		RHS	Trackside equipment westinghouse small		1			
26386	ACTIVE	M	M096-M-NBLO	Road NBLO - MET - Wembley Park to Preston Road	Signal Boxes	Asbestos	Presumed	542		RHS	Trackside equipment signal R546		1			
26388	ACTIVE	M	M096-M-NBLO	Road NBLO - MET - Wembley Park to Preston Road	Cable Sheath	Asbestos	Known	542		RHS	Woven 10mm cable sheath, Cable exits back of box					
26387	ACTIVE	M	M096-M-NBLO	Road NBLO - MET - Wembley Park to Preston Road	Signal Boxes	Asbestos	Presumed	542		RHS	Trackside equipment tencore		1			
27465	ACTIVE	M	M096-M-NBLO	Road NBLO - MET - Wembley Park to Preston Road	Cement Cable Troughing & Debris	Asbestos	Known	585			Cement debris, Sampled previously					
26392	ACTIVE	M	M096-M-NBLO	Road NBLO - MET - Wembley Park to Preston Road	Cable Sheath	Asbestos	Known	691		RHS	Woven 2x10mm cable sheath, Exit: tencore					
26390	ACTIVE	M	M096-M-NBLO	Road NBLO - MET - Wembley Park to Preston Road	Signal Boxes	Asbestos	Presumed	691		RHS	Trackside equipment tencore		1			
26389	ACTIVE	M	M096-M-NBLO	Road NBLO - MET - Wembley Park to Preston Road	Signal Boxes	Asbestos	Presumed	691		RHS	Trackside equipment signal A546		1			
26391	ACTIVE	M	M096-M-NBLO	Road NBLO - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	691		RHS	Trackside equipment westinghouse small Notes from 2021 re-inspection: EP Valve		1			
26394	ACTIVE	M	M096-M-NBLO	Road NBLO - MET - Wembley Park to Preston Road	Signal Boxes	Asbestos	Removed	923		RHS	Trackside equipment tencore Notes from 2021 re-inspection: Removed		1			
26393	ACTIVE	M	M096-M-NBLO	Road NBLO - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Removed	923		RHS	Trackside equipment westinghouse large Notes from 2021 re-inspection: Removed		1			
26395	ACTIVE	M	M096-M-NBLO	Road NBLO - MET - Wembley Park to Preston Road	Signal Boxes	Asbestos	Presumed	1040		RHS	Trackside equipment rail gap indicator		1			
26396	ACTIVE	M	M096-M-NBLO	Road NBLO - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	1040		RHS	Trackside equipment westinghouse small		1			
26399	ACTIVE	M	M096-M-NBLO	Road NBLO - MET - Wembley Park to Preston Road	Cable Sheath	Asbestos	Known	1054		RHS	Woven 10mm cable sheath x 3, Exit: tencore					
27568	ACTIVE	M	M096-M-NBLO	Road NBLO - MET - Wembley Park to Preston Road	Westinghouse Boxes	Asbestos	Presumed	1054		RHS	Trackside equipment westinghouse small Notes from 2021 re-inspection: EP Valve		1			
26398	ACTIVE	M	M096-M-NBLO	Road NBLO - MET - Wembley Park to Preston Road	Signal Boxes	Asbestos	Presumed	1054		RHS	Trackside equipment tencore		2			



Hazardous Material Asset Register - Summary



M096-M - MET Line - Preston Road to Wembley Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
26397	ACTIVE	M	M096-M-NBLO	Road NBLO - MET - Wembley Park to Preston Road	Signal Boxes	Asbestos	Presumed	1054		RHS	Trackside equipment signal R548		1			
27535	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Westinghouse Boxes	Asbestos	Presumed	21	24	LHS	Trackside equipment westinghouse large		5			
27231	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Westinghouse Boxes	Asbestos	Presumed	21	24	LHS	Trackside equipment westinghouse small		1			
27048	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Westinghouse Boxes	Asbestos	Presumed	70		LHS	Trackside equipment westinghouse small		1			
27593	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Westinghouse Boxes	Asbestos	Presumed	140		LHS	Trackside equipment westinghouse small		1			
27050	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Cable Sheath	Asbestos	Known	189		LHS	Woven 10mm earth cable sheath	10				
27049	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Westinghouse Boxes	Asbestos	Presumed	189	193	LHS	Trackside equipment westinghouse large		8			
27052	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Westinghouse Boxes	Asbestos	Presumed	250		LHS	Trackside equipment westinghouse small		1			
27051	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	250		LHS	Trackside equipment rail gap indicator		1			
27054	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Cable Sheath	Asbestos	Presumed	276		LHS	Woven earth cable sheath		1			
27053	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	276		LHS	Trackside equipment tencore box		1			
27055	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	283		LHS	Trackside equipment fog repeater MG 1A		1			
27056	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Westinghouse Boxes	Asbestos	Presumed	320		LHS	Trackside equipment westinghouse small		1			
27057	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	357		LHS	Trackside equipment tencore box		1			
27058	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Other Electrical Boxes	Asbestos	Presumed				Trackside equipment westinghouse small Notes from 2021 re-inspection: EP valve		1			
27059	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	403		LHS	Trackside equipment tencore box		1			
27060	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	404		LHS	Trackside equipment signal RMG 1B, 2A		1			
27061	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	405		LHS	Trackside equipment electrical box Notes from 2021 re-inspection: CTB box		1			



Hazardous Material Asset Register - Summary



M096-M - MET Line - Preston Road to Wembley Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
27062	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	406		LHS	Trackside equipment electrical box Notes from 2021 re-inspection: CTB box		1			
27063	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	407		LHS	Trackside equipment electrical box Notes from 2021 re-inspection: CTB box		1			
27653	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	530		LHS	Trackside equipment extra large electrical kiosk, Behind cable run		1			
27064	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	552		LHS	Trackside equipment tencore box		1			
27521	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	581		LHS	Trackside equipment tencore box		1			
27065	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	589		LHS	Trackside equipment tencore box Notes from 2021 re-inspection: CTB box		1			
27066	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	698		LHS	Trackside equipment tencore box		1			
27067	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	702		LHS	Trackside equipment signal RMG 1B, 2A, 2		1			
27068	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	704		LHS	Trackside equipment electrical box Notes from 2021 re-inspection: CTB box		1			
27069	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	736		LHS	Trackside equipment tencore box		1			
27522	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	742		LHS	Trackside equipment fog repeater MG1B, 2A		1			
27070	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	744		LHS	Trackside equipment tencore box		1			
27071	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	747		LHS	Trackside equipment electrical box Notes from 2021 re-inspection: CTB boxes		2			
27072	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Westinghouse Boxes	Asbestos	Presumed	757		LHS	Trackside equipment westinghouse small		1			
27073	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Other Electrical Boxes	Asbestos	Presumed				Trackside equipment westinghouse small Notes from 2021 re-inspection: EP valve		1			
27255	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	862	865	LHS	Trackside equipment electrical box Notes from 2021 re-inspection: CTB boxes		3			
27594	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	862	865	LHS	Trackside equipment tencore box		1			



Hazardous Material Asset Register - Summary



M096-M - MET Line - Preston Road to Wembley Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
27256	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	870	871	LHS	Trackside equipment electrical box Notes from 2021 re-inspection: CTB boxes		2			
27257	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	878		LHS	Trackside equipment electrical box Notes from 2021 re-inspection: CTB box		1			
27258	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	943		LHS	Trackside equipment electrical box Notes from 2021 re-inspection: CTB box		1			
27443	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Removed	952		LHS	Trackside equipment electrical box Notes from 2021 re-inspection: Removed		1			
27259	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	970		LHS	Trackside equipment tencore box		1			
27612	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	988		LHS	Trackside equipment tencore box		1			
27260	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	994		LHS	Trackside equipment electrical box Notes from 2021 re-inspection: CTB box		1			
27261	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1059		LHS	Trackside equipment tencore box		1			
27262	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Westinghouse Boxes	Asbestos	Presumed	1069		LHS	Trackside equipment westinghouse small		1			
27263	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1077		LHS	Trackside equipment tencore box		1			
27264	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1092		LHS	Trackside equipment tencore box		1			
27265	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Westinghouse Boxes	Asbestos	Presumed	1095	1096	LHS	Trackside equipment westinghouse large		2			
27266	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1100		LHS	Trackside equipment tencore box		1			
27267	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1103		LHS	Trackside equipment fog repeater MG2B		1			
27268	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1104		LHS	Trackside equipment signal bridge MR32		1			
27270	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1106	1108	LHS	Trackside equipment tencore box		1			
27269	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1106	1108	LHS	Trackside equipment electrical box Notes from 2021 re-inspection: CTB boxes		2			



Hazardous Material Asset Register - Summary



M096-M - MET Line - Preston Road to Wembley Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
27271	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1110		LHS	Trackside equipment tencore box		1			
27272	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1112	1116	LHS	Trackside equipment tencore box		1			
27536	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1112	1116	LHS	Trackside equipment electrical box Notes from 2021 re-inspection: CTB boxes		3			
27659	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Westinghouse Boxes	Asbestos	Presumed	1133		LHS	Trackside equipment westinghouse small		1			
27273	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1148		LHS	Trackside equipment tencore box		1			
27274	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1172		LHS	Trackside equipment tencore box		1			
27275	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1184		LHS	Trackside equipment electrical box Notes from 2021 re-inspection: CTB box		1			
27537	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1206	1208	LHS	Trackside equipment electrical box Notes from 2021 re-inspection: CTB boxes		2			
27276	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1226		LHS	Trackside equipment electrical box Notes from 2021 re-inspection: CTB box		1			
27277	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1229		LHS	Trackside equipment electrical box Notes from 2021 re-inspection: CTB box		1			
27278	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Westinghouse Boxes	Asbestos	Presumed	1235		LHS	Trackside equipment westinghouse small		1			
27279	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1253		LHS	Trackside equipment tencore box		1			
27281	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Other Electrical Boxes	Asbestos	Presumed				Trackside equipment westinghouse small Notes from 2021 re-inspection: EP valve		1			
27280	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1256	1257	LHS	Trackside equipment electrical box Notes from 2021 re-inspection: CTB box		1			
27282	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1260		LHS	Trackside equipment signal		1			
27283	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1260		LHS	Trackside equipment tencore box		2			
27286	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1283	1285	LHS	Trackside equipment tencore box		1			



Hazardous Material Asset Register - Summary



M096-M - MET Line - Preston Road to Wembley Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
27284	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Other Electrical Boxes	Asbestos	Presumed				Trackside equipment westinghouse small Notes from 2021 re-inspection: EP valve		2			
27285	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1283	1285	LHS	Trackside equipment electrical box Notes from 2021 re-inspection: CTB box		1			
27444	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1286	1288	LHS	Trackside equipment electrical box Notes from 2021 re-inspection: CTB box		1			
27287	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1286	1288	LHS	Trackside equipment section switch box Notes from 2021 re-inspection: Kiosk not track section switch box		1			
27289	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1304	1307	LHS	Trackside equipment electrical box Notes from 2021 re-inspection: CTB box		1			
27288	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Westinghouse Boxes	Asbestos	Presumed	1304	1307	LHS	Trackside equipment westinghouse small Notes from 2021 re-inspection: 3x EP valves, 1x SWB		4			
27290	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1330		LHS	Trackside equipment fog repeater		1			
27613	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1330		LHS	Trackside equipment tencore box		1			
27291	ACTIVE	M	M096-M-SBFA	Road SBFA - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1330		RHS	Trackside equipment tencore box		1			
27293	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	403		RHS	Trackside equipment tencore box		1			
27292	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	403		RHS	Trackside equipment signal RMG4A		1			
27295	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	577		RHS	Trackside equipment tencore		1			
27294	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	577		RHS	Trackside equipment fog repeater MG4		1			
27296	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	698		RHS	Trackside equipment signal RMG4		1			
27298	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	698		RHS	Trackside equipment tencore		1			
27297	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	698		RHS	Trackside equipment westinghouse small Notes from 2021 re-inspection: EP valve x1 only		1			



Hazardous Material Asset Register - Summary



M096-M - MET Line - Preston Road to Wembley Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
27299	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	701		RHS	Trackside equipment tencore		1			
27538	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	732			Trackside equipment tencore		1			
27660	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	738		RHS	Trackside equipment tencore		1			
27300	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	738		RHS	Trackside equipment fog repeater		1			
27301	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Cement Cable Troughing & Debris	Asbestos	Removed	803		RHS	Cement boxing, Sampled previously Notes from 2021 re-inspection: Removed - MMMF cement troughing		5			
27302	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Cement Cable Troughing & Debris	Asbestos	Removed	847		RHS	Cement boxing Notes from 2021 re-inspection: Removed - MMMF cement troughing		15			
27303	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	854		RHS	Trackside equipment westinghouse small Notes from 2021 re-inspection: EP valve		1			
27539	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	856		OTX	Signal bridge		1			
27304	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	857		RHS	Trackside equipment tencore		1			
27306	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	937		RHS	Trackside equipment tencore		1			
27305	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	937		RHS	Trackside equipment fog repeater		1			
27307	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Cement Cable Troughing & Debris	Asbestos	Removed	968		RHS	Cement boxing, Sampled previously Notes from 2021 re-inspection: Removed - MMMF cement troughing		30			
27308	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	982		RHS	Trackside equipment tencore		1			
27309	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Cement Cable Troughing & Debris	Asbestos	Removed	1020		RHS	Cement boxing Notes from 2021 re-inspection: Removed - MMMF cement troughing		3			
27311	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Cement Cable Troughing & Debris	Asbestos	Removed	1049		RHS	Cement boxing, Sampled previously Notes from 2021 re-inspection: Removed - MMMF cement troughing		20			
27310	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1049		RHS	Trackside equipment tencore		1			



Hazardous Material Asset Register - Summary



M096-M - MET Line - Preston Road to Wembley Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
27312	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Cement Cable Troughing & Debris	Asbestos	Removed	1099		RHS	Cement boxing Notes from 2021 re-inspection: Removed - MMMF cement troughing		6			
27313	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1103		OTX	Construction signal bridge		1			
27314	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1105		RHS	Trackside equipment westinghouse small Notes from 2021 re-inspection: EP valve		1			
27316	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1110		RHS	Trackside equipment tencore		1			
27315	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1110		RHS	Trackside equipment fog repeater MG415		1			
27445	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1172		RHS	Trackside equipment tencore		1			
27317	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Cement Cable Troughing & Debris	Asbestos	Removed	1250		RHS	Cement boxing Notes from 2021 re-inspection: Removed - MMMF cement troughing		10			
27318	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1267		RHS	Trackside equipment signal MG4/5A		1			
27319	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1268		RHS	Trackside equipment westinghouse small Notes from 2021 re-inspection: EP valve		1			
27320	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1269		RHS	Trackside equipment electrical box Notes from 2021 re-inspection: CTB box		1			
27321	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1307		RHS	Trackside equipment tencore		1			
27614	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1310		RHS	Trackside equipment westinghouse large Notes from 2021 re-inspection: Removed - Kiosk		1			
27322	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Removed	1312		RHS	Trackside equipment electrical box Notes from 2021 re-inspection: Removed		1			
27323	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1315		RHS	Trackside equipment contractors box Notes from 2021 re-inspection: Transformer		1			
27324	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1318		RHS	Trackside equipment fuse cabinet		1			



Hazardous Material Asset Register - Summary



M096-M - MET Line - Preston Road to Wembley Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
27325	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Signal Boxes	Asbestos	Presumed	1333		LHS	Trackside equipment shunt signal box		1			
27540	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Westinghouse Boxes	Asbestos	Presumed	1333		LHS	Trackside equipment westinghouse small Notes from 2021 re-inspection: EP valve		2			
27326	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Westinghouse Boxes	Asbestos	Presumed	1333		LHS	Trackside equipment MG28 Notes from 2021 re-inspection: Part of shunt box		1			
27327	ACTIVE	M	M096-M-SBLO	Road SBLO - MET - Preston Road to Wembley Park	Cement Cable Troughing & Debris	Asbestos	Removed	1340		LHS	Cement troughing debris Notes from 2021 re-inspection: Removed or buried in ballast					