



Hazardous Material Asset Register - Summary



Run date: 19/08/2024

Line:

Risk Assessment Status: Active, Draft, Inactive
Hazardous Material Status: All
Hazardous Material Type: All

D182-P - PIC Line - Ravenscourt Park to Stamford Brook

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
53830	ACTIVE	D	D182-P-EBFA	Road EBFA - PIC - Stamford Brook to Ravenscourt Park		Asbestos	Known				Black Mastic - 20m - To bridge D79					
53831	ACTIVE	D	D182-P-EBFA	Road EBFA - PIC - Stamford Brook to Ravenscourt Park	Ducts	Asbestos	Known	417			10 foot - Cement Ducts - to elephant trunking D78B - 8no		8			