



Hazardous Material Asset Register - Summary



Run date: 19/08/2024

Line:

Risk Assessment Status: Active, Draft, Inactive
Hazardous Material Status: All
Hazardous Material Type: All

B061-B - BAK Line - Queens Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47480	ACTIVE	B	B061-B-NBLO	Road NBLO (Plt3) - BAK - Queens Park Stn	Westinghouse Boxes	Asbestos	Presumed	7		LHS	To platform wall					
47483	ACTIVE	B	B061-B-NBLO	Road NBLO (Plt3) - BAK - Queens Park Stn	Signal Boxes	Asbestos	Presumed	35		RHS	To floor					
47485	ACTIVE	B	B061-B-NBLO	Road NBLO (Plt3) - BAK - Queens Park Stn	Signal Boxes	Asbestos	Presumed	35		LHS	To platform wall					
47484	ACTIVE	B	B061-B-NBLO	Road NBLO (Plt3) - BAK - Queens Park Stn	Signal Boxes	Asbestos	Presumed	35		RHS	To floor. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47481	ACTIVE	B	B061-B-NBLO	Road NBLO (Plt3) - BAK - Queens Park Stn	Signal Boxes	Asbestos	Known	35		RHS	To floor. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47482	ACTIVE	B	B061-B-NBLO	Road NBLO (Plt3) - BAK - Queens Park Stn	Signal Boxes	Asbestos	Presumed	35		LHS	To platform wall					
47486	ACTIVE	B	B061-B-NBLO	Road NBLO (Plt3) - BAK - Queens Park Stn	Westinghouse Boxes	Asbestos	Presumed	39		LHS	To platform wall					
47487	ACTIVE	B	B061-B-NBLO	Road NBLO (Plt3) - BAK - Queens Park Stn	Westinghouse Boxes	Asbestos	Presumed	48		LHS	To platform wall					
47488	ACTIVE	B	B061-B-NBLO	Road NBLO (Plt3) - BAK - Queens Park Stn	Signal Boxes	Asbestos	Presumed	62		LHS	To platform wall					
47489	ACTIVE	B	B061-B-NBLO	Road NBLO (Plt3) - BAK - Queens Park Stn	Signal Boxes	Asbestos	Presumed	70		LHS	To platform wall					
47491	ACTIVE	B	B061-B-NBLO	Road NBLO (Plt3) - BAK - Queens Park Stn	Signal Boxes	Asbestos	Presumed	92		RHS	To floor					
47490	ACTIVE	B	B061-B-NBLO	Road NBLO (Plt3) - BAK - Queens Park Stn	Signal Boxes	Asbestos	Known	92		RHS	To floor. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					



Hazardous Material Asset Register - Summary



B061-B - BAK Line - Queens Park Stn																
Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47493	ACTIVE	B	B061-B-NBLO	Road NBLO (Plt3) - BAK - Queens Park Stn	Signal Boxes	Asbestos	Presumed	93		LHS	To platform wall					
47492	ACTIVE	B	B061-B-NBLO	Road NBLO (Plt3) - BAK - Queens Park Stn	Signal Boxes	Asbestos	Known	93		RHS	To floor. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47494	ACTIVE	B	B061-B-NBLO	Road NBLO (Plt3) - BAK - Queens Park Stn	Signal Boxes	Asbestos	Presumed	94		LHS	To platform wall					
47495	ACTIVE	B	B061-B-NBLO	Road NBLO (Plt3) - BAK - Queens Park Stn	Westinghouse Boxes	Asbestos	Presumed	115		LHS	To platform wall					
47496	ACTIVE	B	B061-B-NBLO	Road NBLO (Plt3) - BAK - Queens Park Stn	Signal Boxes	Asbestos	Presumed	120		RHS	To floor					
47497	ACTIVE	B	B061-B-NBLO	Road NBLO (Plt3) - BAK - Queens Park Stn	Westinghouse Boxes	Asbestos	Presumed	121		RHS	To floor					
47957	ACTIVE	B	B061-B-SBLO	Road SBLO (Plt2) - BAK - Queens Park Stn	Westinghouse Boxes	Asbestos	Presumed	6		LHS	Asset located to platform wall					
47958	ACTIVE	B	B061-B-SBLO	Road SBLO (Plt2) - BAK - Queens Park Stn	Westinghouse Boxes	Asbestos	Presumed	10		LHS	Asset located to platform wall					
47959	ACTIVE	B	B061-B-SBLO	Road SBLO (Plt2) - BAK - Queens Park Stn	Westinghouse Boxes	Asbestos	Presumed	44		LHS	Asset located to platform wall					
47960	ACTIVE	B	B061-B-SBLO	Road SBLO (Plt2) - BAK - Queens Park Stn	Signal Boxes	Asbestos	Presumed	45		LHS	Asset located to platform wall					
47961	ACTIVE	B	B061-B-SBLO	Road SBLO (Plt2) - BAK - Queens Park Stn	Signal Boxes	Asbestos	Presumed	54		LHS	Asset located to platform wall					
47962	ACTIVE	B	B061-B-SBLO	Road SBLO (Plt2) - BAK - Queens Park Stn	Signal Boxes	Asbestos	Presumed	56		LHS	Asset located to platform wall					
47963	ACTIVE	B	B061-B-SBLO	Road SBLO (Plt2) - BAK - Queens Park Stn	Signal Boxes	Asbestos	Presumed	62		LHS	Asset located to platform wall					
47965	ACTIVE	B	B061-B-SBLO	Road SBLO (Plt2) - BAK - Queens Park Stn	Signal Boxes	Asbestos	Presumed	62		RHS	Asset located to platform wall					
47964	ACTIVE	B	B061-B-SBLO	Road SBLO (Plt2) - BAK - Queens Park Stn	Signal Boxes	Asbestos	Presumed	62		LHS	Asset located to platform wall					
47966	ACTIVE	B	B061-B-SBLO	Road SBLO (Plt2) - BAK - Queens Park Stn	Signal Boxes	Asbestos	Known	62		RHS	To 6 foot. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					



Hazardous Material Asset Register - Summary



B061-B - BAK Line - Queens Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47967	ACTIVE	B	B061-B-SBLO	Road SBLO (Plt2) - BAK - Queens Park Stn	Westinghouse Boxes	Asbestos	Presumed	115		RHS	Asset located to platform wall					
47968	ACTIVE	B	B061-B-SBLO	Road SBLO (Plt2) - BAK - Queens Park Stn	Westinghouse Boxes	Asbestos	Presumed	119		RHS	Asset located to platform wall					

B062-B - BAK Line - Queens Park to Kilburn Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47409	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Current Rail Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring.					
47416	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Cement Cable Troughing & Debris	Asbestos	Known			RHS	Below cable to floor					
47420	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47419	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47418	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47417	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47414	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring.					
47412	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47413	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Cement Cable Troughing & Debris	Asbestos	Known			LHS	To render to tunnel ring. Note no cables within					
47415	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Cement Cable Troughing & Debris	Asbestos	Known			RHS	Below cable to floor					
47411	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					



Hazardous Material Asset Register - Summary



B062-B - BAK Line - Queens Park to Kilburn Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47410	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47421	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Presumed	435		LHS	Asset located on wall					
47422	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Known	436		LHS	Asset located on wall. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before procee					
47423	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Known	436		LHS	Asset located on wall. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before procee					
47425	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Presumed	438		LHS	Asset located on wall. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47424	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Presumed	438		LHS	Asset located on wall					
47426	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Westinghouse Boxes	Asbestos	Presumed	440		LHS	Asset located on wall					
47427	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Westinghouse Boxes	Asbestos	Presumed	450		LHS	Asset located on wall					
47428	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Westinghouse Boxes	Asbestos	Presumed	504		LHS	Asset located on wall					
47429	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Other Electrical Boxes	Asbestos	Presumed	506		LHS	Asset located on wall					



Hazardous Material Asset Register - Summary



B062-B - BAK Line - Queens Park to Kilburn Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47432	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Known	507		LHS	Asset located on wall. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before procee					
47431	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Known	507		LHS	Asset located on wall. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before procee					
47430	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Other Electrical Boxes	Asbestos	Presumed	507		LHS	Asset located on wall					
47435	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Known	508		LHS	Asset located on wall. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47433	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Presumed	508		LHS	Asset located on wall					
47434	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Known	508		LHS	Asset located on wall. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before procee					
47436	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Westinghouse Boxes	Asbestos	Presumed	509		LHS	Asset located on wall					
47437	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Current Rail Boxes	Asbestos	Presumed	520		LHS	Asset located on wall					
47438	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Westinghouse Boxes	Asbestos	Presumed	550		LHS	Asset located on wall					
47439	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Westinghouse Boxes	Asbestos	Presumed	563		LHS	To lamp to wall					



Hazardous Material Asset Register - Summary



B062-B - BAK Line - Queens Park to Kilburn Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47440	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Westinghouse Boxes	Asbestos	Known	570		LHS	Asset located on wall. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47441	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Presumed	577		LHS	Asset located on wall					
47442	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Westinghouse Boxes	Asbestos	Presumed	583		LHS	Asset located on wall					
47443	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Westinghouse Boxes	Asbestos	Presumed	584		LHS	Asset located on wall					
47444	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Westinghouse Boxes	Asbestos	Presumed	637		LHS	To framework					
47445	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Westinghouse Boxes	Asbestos	Presumed	638		LHS	To framework					
47447	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Known	639		LHS	To framework. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47446	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Known	639		LHS	To framework. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47448	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Known	639		LHS	To framework. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47449	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Cement Cable Troughing & Debris	Asbestos	Known	641		UTX	To under track crossing/ 4 foot and 6 foot (no cables within)					
47450	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Westinghouse Boxes	Asbestos	Presumed	642		LHS	Asset located on cable run					
47451	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Westinghouse Boxes	Asbestos	Presumed	646		LHS	Asset located on cable run					



Hazardous Material Asset Register - Summary



B062-B - BAK Line - Queens Park to Kilburn Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47452	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Presumed	647		LHS	Asset located on cable run					
47453	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Presumed	651		LHS	Asset located on cable run					
47454	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Known	652		LHS	To cable run. Brown composite mount panel/board. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding					
47455	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Presumed	653		LHS	Asset located on cable run					
47456	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Westinghouse Boxes	Asbestos	Presumed	654		LHS	Asset located on cable run					
47457	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Known	655		LHS	To cable run. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47458	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Presumed	655		LHS	Asset located on cable run					
47459	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Known	656		LHS	To cable run. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47460	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Known	658		LHS	To cable run. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47461	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Presumed	659		LHS	Asset located on cable run					
47462	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Westinghouse Boxes	Asbestos	Presumed	660		LHS	Asset located on cable run					
47463	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Known	661		LHS	To cable run. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					



Hazardous Material Asset Register - Summary



B062-B - BAK Line - Queens Park to Kilburn Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47464	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Presumed	662		LHS	Asset located on cable run					
47465	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Westinghouse Boxes	Asbestos	Presumed	663		LHS	Asset located on cable run					
47466	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Presumed	664		LHS	Asset located on cable run					
47467	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Cement Cable Troughing & Debris	Asbestos	Known	664		LHS	To floor by cable run					
47468	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Presumed	665		LHS	Asset located on cable run					
47470	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Presumed	666		LHS	To bridge BT69					
47469	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Westinghouse Boxes	Asbestos	Presumed	666		LHS	To bridge BT69					
47471	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Other Electrical Boxes	Asbestos	Presumed	674		LHS	To bridge BT71					
47472	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Westinghouse Boxes	Asbestos	Presumed	678		LHS	To bridge					
47473	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Known	688		LHS	To wall. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47474	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Presumed	689		LHS	To wall					
47475	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Known	690		LHS	To wall. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47477	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Current Rail Boxes	Asbestos	Presumed	690		LHS	To wall					
47476	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Cement Cable Troughing & Debris	Asbestos	Known	690		LHS	To floor, under ramp					
47479	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Westinghouse Boxes	Asbestos	Presumed	693		LHS	To tail wall					



Hazardous Material Asset Register - Summary



B062-B - BAK Line - Queens Park to Kilburn Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47478	ACTIVE	B	B062-B-NBLO	Road NBLO - BAK - Kilburn Park to Queens Park	Signal Boxes	Asbestos	Known	693		LHS	To tail wall. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47953	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Westinghouse Boxes	Asbestos	Presumed			RHS	To wall					
47951	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Westinghouse Boxes	Asbestos	Presumed			RHS	To wall					
47947	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Signal Boxes	Asbestos	Known			RHS	To wall. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47948	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Signal Boxes	Asbestos	Known			RHS	To wall. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47950	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Westinghouse Boxes	Asbestos	Presumed			RHS	To wall					
47949	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Signal Boxes	Asbestos	Presumed			RHS	To wall					
47946	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Westinghouse Boxes	Asbestos	Presumed			RHS	To wall					
47955	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Westinghouse Boxes	Asbestos	Presumed			RHS	To wall					
47954	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Westinghouse Boxes	Asbestos	Presumed			RHS	To wall					
47952	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Westinghouse Boxes	Asbestos	Presumed			RHS	To wall					
47956	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Cement Cable Troughing & Debris	Asbestos	Known			LHS	To lower wall					
47917	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Westinghouse Boxes	Asbestos	Presumed	1		LHS	Asset located on head wall					
47918	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Signal Boxes	Asbestos	Presumed	2		LHS	Asset located on head wall					



Hazardous Material Asset Register - Summary



B062-B - BAK Line - Queens Park to Kilburn Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47919	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Signal Boxes	Asbestos	Known	2		LHS	Asset located on head wall. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before p					
47922	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Westinghouse Boxes	Asbestos	Presumed	4		LHS	Asset located on head wall					
47921	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Current Rail Boxes	Asbestos	Presumed	4		LHS	Asset located on head wall					
47920	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Signal Boxes	Asbestos	Known	4		LHS	Asset located on head wall. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47923	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Westinghouse Boxes	Asbestos	Presumed	5		LHS	Asset located on head wall					
47924	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Signal Boxes	Asbestos	Known	8		LHS	Asset located on head wall. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47926	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Cable Sheath	Asbestos	Known	9	26	LHS	From cable duct along tunnel into duct					
47925	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Ducts	Asbestos	Known	9		LHS	Asset located on floor					
47927	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Westinghouse Boxes	Asbestos	Presumed	17		LHS	To wall					
47928	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Signal Boxes	Asbestos	Known	25		LHS	To wall. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47929	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Signal Boxes	Asbestos	Known	26		LHS	To wall. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					



Hazardous Material Asset Register - Summary



B062-B - BAK Line - Queens Park to Kilburn Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47931	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Signal Boxes	Asbestos	Known	28		LHS	Asset located on wall on bridge. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance bef					
47930	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Ducts	Asbestos	Known	28		LHS	Asset located on floor					
47932	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Signal Boxes	Asbestos	Known	50		RHS	To 6 foot. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47933	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Westinghouse Boxes	Asbestos	Presumed	60		LHS	To cess					
47935	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Signal Boxes	Asbestos	Presumed	62		LHS	To cess					
47934	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Signal Boxes	Asbestos	Known	62		LHS	To cess. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47936	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Signal Boxes	Asbestos	Presumed	63		LHS	To cess. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47937	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Cable Sheath	Asbestos	Known	100	625	LHS	To cable run along side of sidings into tunnel. Some fraying at edges - encapsulation required					
47938	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Signal Boxes	Asbestos	Presumed	110		LHS	To cess					
47939	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Signal Boxes	Asbestos	Known	113		LHS	To wall. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47941	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Westinghouse Boxes	Asbestos	Presumed	114		LHS	To wall					
47940	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Signal Boxes	Asbestos	Presumed	114		LHS	To wall					



Hazardous Material Asset Register - Summary



B062-B - BAK Line - Queens Park to Kilburn Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47942	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Signal Boxes	Asbestos	Presumed	116		LHS	To wall					
47943	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Westinghouse Boxes	Asbestos	Presumed	120		LHS	To wall					
47944	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Westinghouse Boxes	Asbestos	Presumed	194		LHS	To wall					
47945	ACTIVE	B	B062-B-SBLO	Road SBLO - BAK - Queens Park to Kilburn Park	Westinghouse Boxes	Asbestos	Presumed	220		LHS	To wall					

B063-B - BAK Line - Kilburn Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47408	ACTIVE	B	B063-B-NBLO	Road NBLO (Plt1) - BAK - Kilburn Park Stn	Cable Wrap	Asbestos	Known	80		LHS	From wall to under track crossing					
47407	ACTIVE	B	B063-B-NBLO	Road NBLO (Plt1) - BAK - Kilburn Park Stn	Cable Sheath	Asbestos	Known	80		LHS	From wall to under track crossing					

B064-B - BAK Line - Kilburn Park to Maida Vale

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47389	ACTIVE	B	B064-B-NBLO	Road NBLO - BAK - Maida Vale to Kilburn Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on trackside wall					
47392	ACTIVE	B	B064-B-NBLO	Road NBLO - BAK - Maida Vale to Kilburn Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on trackside wall					
47387	ACTIVE	B	B064-B-NBLO	Road NBLO - BAK - Maida Vale to Kilburn Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on trackside wall					
47386	ACTIVE	B	B064-B-NBLO	Road NBLO - BAK - Maida Vale to Kilburn Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on trackside wall					
47388	ACTIVE	B	B064-B-NBLO	Road NBLO - BAK - Maida Vale to Kilburn Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on trackside wall					
47396	ACTIVE	B	B064-B-NBLO	Road NBLO - BAK - Maida Vale to Kilburn Park	Signal Boxes	Asbestos	Presumed			RHS	Asset located on trackside wall					
47385	ACTIVE	B	B064-B-NBLO	Road NBLO - BAK - Maida Vale to Kilburn Park	Signal Boxes	Asbestos	Presumed			RHS	Asset located on trackside wall					



Hazardous Material Asset Register - Summary



B064-B - BAK Line - Kilburn Park to Maida Vale

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47394	ACTIVE	B	B064-B-NBLO	Road NBLO - BAK - Maida Vale to Kilburn Park	Signal Boxes	Asbestos	Known			RHS	Asset located on trackside wall. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47393	ACTIVE	B	B064-B-NBLO	Road NBLO - BAK - Maida Vale to Kilburn Park	Signal Boxes	Asbestos	Known			RHS	Asset located on trackside wall. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance bef					
47384	ACTIVE	B	B064-B-NBLO	Road NBLO - BAK - Maida Vale to Kilburn Park	Signal Boxes	Asbestos	Known			RHS	Asset located on trackside wall. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance bef					
47383	ACTIVE	B	B064-B-NBLO	Road NBLO - BAK - Maida Vale to Kilburn Park	Signal Boxes	Asbestos	Known			RHS	Asset located on trackside wall. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47403	ACTIVE	B	B064-B-NBLO	Road NBLO - BAK - Maida Vale to Kilburn Park	Cable Wrap	Asbestos	Known				To cable F103 throughout					
47401	ACTIVE	B	B064-B-NBLO	Road NBLO - BAK - Maida Vale to Kilburn Park	Cable Wrap	Asbestos	Known			LHS	To cable F103, under track crossing to cross passage 1499					
47381	ACTIVE	B	B064-B-NBLO	Road NBLO - BAK - Maida Vale to Kilburn Park	Cable Sheath	Asbestos	Known			LHS	To trackside wall running length of tunnel					
47402	ACTIVE	B	B064-B-NBLO	Road NBLO - BAK - Maida Vale to Kilburn Park	Other Electrical Boxes	Asbestos	Presumed			RHS	Asset located on trackside wall					
47382	ACTIVE	B	B064-B-NBLO	Road NBLO - BAK - Maida Vale to Kilburn Park	Other Electrical Boxes	Asbestos	Presumed			RHS	Asset located on trackside wall					
47400	ACTIVE	B	B064-B-NBLO	Road NBLO - BAK - Maida Vale to Kilburn Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on trackside wall					
47399	ACTIVE	B	B064-B-NBLO	Road NBLO - BAK - Maida Vale to Kilburn Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on trackside wall					
47398	ACTIVE	B	B064-B-NBLO	Road NBLO - BAK - Maida Vale to Kilburn Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on trackside wall					



Hazardous Material Asset Register - Summary



B064-B - BAK Line - Kilburn Park to Maida Vale

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47397	ACTIVE	B	B064-B-NBLO	Road NBLO - BAK - Maida Vale to Kilburn Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on trackside wall					
47395	ACTIVE	B	B064-B-NBLO	Road NBLO - BAK - Maida Vale to Kilburn Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on trackside wall					
47391	ACTIVE	B	B064-B-NBLO	Road NBLO - BAK - Maida Vale to Kilburn Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on trackside wall					
47390	ACTIVE	B	B064-B-NBLO	Road NBLO - BAK - Maida Vale to Kilburn Park	Signal Boxes	Lead Paint/Lead	Presumed			RHS	Asset located on trackside wall. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance bef					
47905	ACTIVE	B	B064-B-SBLO	Road SBLO - BAK - Kilburn Park to Maida Vale	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47903	ACTIVE	B	B064-B-SBLO	Road SBLO - BAK - Kilburn Park to Maida Vale	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47897	ACTIVE	B	B064-B-SBLO	Road SBLO - BAK - Kilburn Park to Maida Vale	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47896	ACTIVE	B	B064-B-SBLO	Road SBLO - BAK - Kilburn Park to Maida Vale	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47912	ACTIVE	B	B064-B-SBLO	Road SBLO - BAK - Kilburn Park to Maida Vale	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47904	ACTIVE	B	B064-B-SBLO	Road SBLO - BAK - Kilburn Park to Maida Vale	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47902	ACTIVE	B	B064-B-SBLO	Road SBLO - BAK - Kilburn Park to Maida Vale	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47895	ACTIVE	B	B064-B-SBLO	Road SBLO - BAK - Kilburn Park to Maida Vale	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47911	ACTIVE	B	B064-B-SBLO	Road SBLO - BAK - Kilburn Park to Maida Vale	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47910	ACTIVE	B	B064-B-SBLO	Road SBLO - BAK - Kilburn Park to Maida Vale	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					



Hazardous Material Asset Register - Summary



B064-B - BAK Line - Kilburn Park to Maida Vale

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47900	ACTIVE	B	B064-B-SBLO	Road SBLO - BAK - Kilburn Park to Maida Vale	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47899	ACTIVE	B	B064-B-SBLO	Road SBLO - BAK - Kilburn Park to Maida Vale	Signal Boxes	Asbestos	Known			LHS	Asset located on tunnel wall. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47901	ACTIVE	B	B064-B-SBLO	Road SBLO - BAK - Kilburn Park to Maida Vale	Current Rail Boxes	Asbestos	Presumed			LHS	Asset located on tunnel wall					
47898	ACTIVE	B	B064-B-SBLO	Road SBLO - BAK - Kilburn Park to Maida Vale	Cable Wrap	Asbestos	Known			LHS	To cable out of cable ducts under track crossing. Cable frayed at edges - encapsulation required					
47916	ACTIVE	B	B064-B-SBLO	Road SBLO - BAK - Kilburn Park to Maida Vale	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47915	ACTIVE	B	B064-B-SBLO	Road SBLO - BAK - Kilburn Park to Maida Vale	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47914	ACTIVE	B	B064-B-SBLO	Road SBLO - BAK - Kilburn Park to Maida Vale	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47913	ACTIVE	B	B064-B-SBLO	Road SBLO - BAK - Kilburn Park to Maida Vale	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47909	ACTIVE	B	B064-B-SBLO	Road SBLO - BAK - Kilburn Park to Maida Vale	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47906	ACTIVE	B	B064-B-SBLO	Road SBLO - BAK - Kilburn Park to Maida Vale	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47907	ACTIVE	B	B064-B-SBLO	Road SBLO - BAK - Kilburn Park to Maida Vale	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47908	ACTIVE	B	B064-B-SBLO	Road SBLO - BAK - Kilburn Park to Maida Vale	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					

B065-B - BAK Line - Maida Vale Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47379	ACTIVE	B	B065-B-NBLO	Road NBLO (Plt1) - BAK - Maida Vale Stn	Cable Sheath	Asbestos	Known	1		LHS	Running behind track wall					



Hazardous Material Asset Register - Summary



B065-B - BAK Line - Maida Vale Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47380	ACTIVE	B	B065-B-NBLO	Road NBLO (Plt1) - BAK - Maida Vale Stn	Westinghouse Boxes	Asbestos	Presumed	66		RHS	Under platform					
47894	ACTIVE	B	B065-B-SBLO	Road SBLO (Plt2) - BAK - Maida Vale Stn	Westinghouse Boxes	Asbestos	Presumed	71		RHS	Asset located under platform					

B066-B - BAK Line - Maida Vale to Warwick Avenue

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47377	ACTIVE	B	B066-B-NBLO	Road NBLO - BAK - Warwick Avenue to Maida Vale	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47378	ACTIVE	B	B066-B-NBLO	Road NBLO - BAK - Warwick Avenue to Maida Vale	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47375	ACTIVE	B	B066-B-NBLO	Road NBLO - BAK - Warwick Avenue to Maida Vale	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47371	ACTIVE	B	B066-B-NBLO	Road NBLO - BAK - Warwick Avenue to Maida Vale	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47370	ACTIVE	B	B066-B-NBLO	Road NBLO - BAK - Warwick Avenue to Maida Vale	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47369	ACTIVE	B	B066-B-NBLO	Road NBLO - BAK - Warwick Avenue to Maida Vale	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47367	ACTIVE	B	B066-B-NBLO	Road NBLO - BAK - Warwick Avenue to Maida Vale	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47366	ACTIVE	B	B066-B-NBLO	Road NBLO - BAK - Warwick Avenue to Maida Vale	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47365	ACTIVE	B	B066-B-NBLO	Road NBLO - BAK - Warwick Avenue to Maida Vale	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47364	ACTIVE	B	B066-B-NBLO	Road NBLO - BAK - Warwick Avenue to Maida Vale	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47363	ACTIVE	B	B066-B-NBLO	Road NBLO - BAK - Warwick Avenue to Maida Vale	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47358	ACTIVE	B	B066-B-NBLO	Road NBLO - BAK - Warwick Avenue to Maida Vale	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall.					
47374	ACTIVE	B	B066-B-NBLO	Road NBLO - BAK - Warwick Avenue to Maida Vale	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47362	ACTIVE	B	B066-B-NBLO	Road NBLO - BAK - Warwick Avenue to Maida Vale	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47357	ACTIVE	B	B066-B-NBLO	Road NBLO - BAK - Warwick Avenue to Maida Vale	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall.					



Hazardous Material Asset Register - Summary



B066-B - BAK Line - Maida Vale to Warwick Avenue

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47373	ACTIVE	B	B066-B-NBLO	Road NBLO - BAK - Warwick Avenue to Maida Vale	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47372	ACTIVE	B	B066-B-NBLO	Road NBLO - BAK - Warwick Avenue to Maida Vale	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47368	ACTIVE	B	B066-B-NBLO	Road NBLO - BAK - Warwick Avenue to Maida Vale	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47361	ACTIVE	B	B066-B-NBLO	Road NBLO - BAK - Warwick Avenue to Maida Vale	Signal Boxes	Asbestos	Known			LHS	Asset located on tunnel wall. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47360	ACTIVE	B	B066-B-NBLO	Road NBLO - BAK - Warwick Avenue to Maida Vale	Signal Boxes	Asbestos	Known			LHS	Asset located on tunnel wall. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47359	ACTIVE	B	B066-B-NBLO	Road NBLO - BAK - Warwick Avenue to Maida Vale	Cable Sheath	Asbestos	Known			LHS	Running the length of track					
47376	ACTIVE	B	B066-B-NBLO	Road NBLO - BAK - Warwick Avenue to Maida Vale	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47892	ACTIVE	B	B066-B-SBLO	Road SBLO - BAK - Maida Vale to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47891	ACTIVE	B	B066-B-SBLO	Road SBLO - BAK - Maida Vale to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47890	ACTIVE	B	B066-B-SBLO	Road SBLO - BAK - Maida Vale to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					



Hazardous Material Asset Register - Summary



B066-B - BAK Line - Maida Vale to Warwick Avenue

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47889	ACTIVE	B	B066-B-SBLO	Road SBLO - BAK - Maida Vale to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			LHS	Asset located on tunnel wall					
47887	ACTIVE	B	B066-B-SBLO	Road SBLO - BAK - Maida Vale to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47884	ACTIVE	B	B066-B-SBLO	Road SBLO - BAK - Maida Vale to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47883	ACTIVE	B	B066-B-SBLO	Road SBLO - BAK - Maida Vale to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47881	ACTIVE	B	B066-B-SBLO	Road SBLO - BAK - Maida Vale to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47879	ACTIVE	B	B066-B-SBLO	Road SBLO - BAK - Maida Vale to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47876	ACTIVE	B	B066-B-SBLO	Road SBLO - BAK - Maida Vale to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47875	ACTIVE	B	B066-B-SBLO	Road SBLO - BAK - Maida Vale to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47873	ACTIVE	B	B066-B-SBLO	Road SBLO - BAK - Maida Vale to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47893	ACTIVE	B	B066-B-SBLO	Road SBLO - BAK - Maida Vale to Warwick Avenue	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47886	ACTIVE	B	B066-B-SBLO	Road SBLO - BAK - Maida Vale to Warwick Avenue	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47880	ACTIVE	B	B066-B-SBLO	Road SBLO - BAK - Maida Vale to Warwick Avenue	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47874	ACTIVE	B	B066-B-SBLO	Road SBLO - BAK - Maida Vale to Warwick Avenue	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47888	ACTIVE	B	B066-B-SBLO	Road SBLO - BAK - Maida Vale to Warwick Avenue	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite mount panel/ board Where works/maintenace impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47885	ACTIVE	B	B066-B-SBLO	Road SBLO - BAK - Maida Vale to Warwick Avenue	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenace impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					



Hazardous Material Asset Register - Summary



B066-B - BAK Line - Maida Vale to Warwick Avenue

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47882	ACTIVE	B	B066-B-SBLO	Road SBLO - BAK - Maida Vale to Warwick Avenue	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47878	ACTIVE	B	B066-B-SBLO	Road SBLO - BAK - Maida Vale to Warwick Avenue	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47877	ACTIVE	B	B066-B-SBLO	Road SBLO - BAK - Maida Vale to Warwick Avenue	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47871	ACTIVE	B	B066-B-SBLO	Road SBLO - BAK - Maida Vale to Warwick Avenue	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47872	ACTIVE	B	B066-B-SBLO	Road SBLO - BAK - Maida Vale to Warwick Avenue	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					

B067-B - BAK Line - Warwick Avenue Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47869	ACTIVE	B	B067-B-NBLO	Road NBLO (Plt1) - BAK - Warwick Avenue Stn	Cable Sheath	Asbestos	Known	1	130	LHS	To trackside wall					
47870	ACTIVE	B	B067-B-NBLO	Road NBLO (Plt1) - BAK - Warwick Avenue Stn	Westinghouse Boxes	Asbestos	Presumed	50		RHS	Asset located under platform					



Hazardous Material Asset Register - Summary



B068-B - BAK Line - Warwick Avenue to Paddington

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47337	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47340	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Signal Boxes	Asbestos	Known			LHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47343	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. wn composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before pr					
47344	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47349	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47350	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47323	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47328	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					



Hazardous Material Asset Register - Summary



B068-B - BAK Line - Warwick Avenue to Paddington

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47334	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47338	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47345	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47352	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47356	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47319	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47320	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47324	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47325	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47326	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47327	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47330	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47331	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47333	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47339	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47341	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47342	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47346	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47347	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					



Hazardous Material Asset Register - Summary



B068-B - BAK Line - Warwick Avenue to Paddington

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47348	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47351	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47353	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47354	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47355	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47336	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Boarding / Panels	Asbestos	Known			RHS	To positive and negative current rail switch boxes, 804 and 804A					
47318	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Cable Sheath	Asbestos	Known			LHS	Asset located on cable run					
47332	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Current Rail Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47321	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47322	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47329	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47335	ACTIVE	B	B068-B-NBLO	Road NBLO - BAK - Paddington to Warwick Avenue	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					



Hazardous Material Asset Register - Summary



B068-B - BAK Line - Warwick Avenue to Paddington

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47867	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Current Rail Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47864	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47839	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47840	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47845	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47850	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Signal Boxes	Asbestos	Known			LHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47851	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Signal Boxes	Asbestos	Known			LHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47852	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding					



Hazardous Material Asset Register - Summary



B068-B - BAK Line - Warwick Avenue to Paddington

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47857	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47858	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47865	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47837	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47841	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47846	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47853	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47859	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47868	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47838	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47842	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47843	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47844	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47847	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47848	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					



Hazardous Material Asset Register - Summary



B068-B - BAK Line - Warwick Avenue to Paddington

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47849	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47854	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47855	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47856	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47860	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47861	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47862	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47863	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47866	ACTIVE	B	B068-B-SBLO	Road SBLO - BAK - Warwick Avenue to Paddington	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					

B071-B - BAK Line - Paddington Stn / Praed Street

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47835	ACTIVE	B	B071-B-NBLO	Road NBLO (Plt3) - BAK - Paddington Stn	Cable Sheath	Asbestos	Known	1	115	LHS	To cable run along wall					
47836	ACTIVE	B	B071-B-NBLO	Road NBLO (Plt3) - BAK - Paddington Stn	Cable Sheath	Asbestos	Known	80		LHS	To cable run along wall					



Hazardous Material Asset Register - Summary



B072-B - BAK Line - Paddington to Edgware Road

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47296	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47297	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47302	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47305	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47306	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring.					
47307	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring.					
47311	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47312	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Signal Boxes	Asbestos	Known			LHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					



Hazardous Material Asset Register - Summary



B072-B - BAK Line - Paddington to Edgware Road

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47315	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47317	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47289	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47291	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47288	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47308	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47313	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47292	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47293	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47294	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47295	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47299	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47300	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					



Hazardous Material Asset Register - Summary



B072-B - BAK Line - Paddington to Edgware Road

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47301	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47303	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47304	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47309	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47310	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47314	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47316	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47286	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Westinghouse Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring.					
47290	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47287	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Cable Sheath	Asbestos	Known			LHS	To head wall running along tunnel					
47298	ACTIVE	B	B072-B-NBLO	Road NBLO - BAK - Edgware Road to Paddington	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47806	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47811	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					



Hazardous Material Asset Register - Summary



B072-B - BAK Line - Paddington to Edgware Road

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47819	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47825	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47804	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47805	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47810	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47812	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47817	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47818	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					



Hazardous Material Asset Register - Summary



B072-B - BAK Line - Paddington to Edgware Road

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47820	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47824	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47826	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47832	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47834	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47803	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47807	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47808	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47809	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47813	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47814	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47815	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47816	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47821	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47822	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47823	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47827	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					



Hazardous Material Asset Register - Summary



B072-B - BAK Line - Paddington to Edgware Road

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47828	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47829	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47830	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47831	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47833	ACTIVE	B	B072-B-SBLO	Road SBLO - BAK - Paddington to Edgware Road	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					

B074-B - BAK Line - Edgware Road to Marylebone

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47276	ACTIVE	B	B074-B-NBLO	Road NBLO - BAK - Marylebone to Edgware Road	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47272	ACTIVE	B	B074-B-NBLO	Road NBLO - BAK - Marylebone to Edgware Road	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47278	ACTIVE	B	B074-B-NBLO	Road NBLO - BAK - Marylebone to Edgware Road	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47277	ACTIVE	B	B074-B-NBLO	Road NBLO - BAK - Marylebone to Edgware Road	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47271	ACTIVE	B	B074-B-NBLO	Road NBLO - BAK - Marylebone to Edgware Road	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47270	ACTIVE	B	B074-B-NBLO	Road NBLO - BAK - Marylebone to Edgware Road	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47283	ACTIVE	B	B074-B-NBLO	Road NBLO - BAK - Marylebone to Edgware Road	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47275	ACTIVE	B	B074-B-NBLO	Road NBLO - BAK - Marylebone to Edgware Road	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47267	ACTIVE	B	B074-B-NBLO	Road NBLO - BAK - Marylebone to Edgware Road	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47274	ACTIVE	B	B074-B-NBLO	Road NBLO - BAK - Marylebone to Edgware Road	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					



Hazardous Material Asset Register - Summary



B074-B - BAK Line - Edgware Road to Marylebone

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47273	ACTIVE	B	B074-B-NBLO	Road NBLO - BAK - Marylebone to Edgware Road	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47269	ACTIVE	B	B074-B-NBLO	Road NBLO - BAK - Marylebone to Edgware Road	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47268	ACTIVE	B	B074-B-NBLO	Road NBLO - BAK - Marylebone to Edgware Road	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47285	ACTIVE	B	B074-B-NBLO	Road NBLO - BAK - Marylebone to Edgware Road	Ducts	Asbestos	Known			LHS	To tail wall					
47284	ACTIVE	B	B074-B-NBLO	Road NBLO - BAK - Marylebone to Edgware Road	Westinghouse Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring.					
47282	ACTIVE	B	B074-B-NBLO	Road NBLO - BAK - Marylebone to Edgware Road	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47279	ACTIVE	B	B074-B-NBLO	Road NBLO - BAK - Marylebone to Edgware Road	Westinghouse Boxes	Asbestos	Presumed	322		LHS	Asset located on tunnel ring within cross over					
47281	ACTIVE	B	B074-B-NBLO	Road NBLO - BAK - Marylebone to Edgware Road	Cable Sheath	Asbestos	Known	328	343	LHS	From over track crossing to tail wall					
47280	ACTIVE	B	B074-B-NBLO	Road NBLO - BAK - Marylebone to Edgware Road	Cable Sheath	Asbestos	Known	328			Over track crossing to southbound running tunnel in cross over					
47798	ACTIVE	B	B074-B-SBLO	Road SBLO - BAK - Edgware Road to Marylebone	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47799	ACTIVE	B	B074-B-SBLO	Road SBLO - BAK - Edgware Road to Marylebone	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47800	ACTIVE	B	B074-B-SBLO	Road SBLO - BAK - Edgware Road to Marylebone	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47801	ACTIVE	B	B074-B-SBLO	Road SBLO - BAK - Edgware Road to Marylebone	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					



Hazardous Material Asset Register - Summary



B074-B - BAK Line - Edgware Road to Marylebone

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47788	ACTIVE	B	B074-B-SBLO	Road SBLO - BAK - Edgware Road to Marylebone	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47785	ACTIVE	B	B074-B-SBLO	Road SBLO - BAK - Edgware Road to Marylebone	Westinghouse Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring					
47802	ACTIVE	B	B074-B-SBLO	Road SBLO - BAK - Edgware Road to Marylebone	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47797	ACTIVE	B	B074-B-SBLO	Road SBLO - BAK - Edgware Road to Marylebone	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47796	ACTIVE	B	B074-B-SBLO	Road SBLO - BAK - Edgware Road to Marylebone	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47795	ACTIVE	B	B074-B-SBLO	Road SBLO - BAK - Edgware Road to Marylebone	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47787	ACTIVE	B	B074-B-SBLO	Road SBLO - BAK - Edgware Road to Marylebone	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47786	ACTIVE	B	B074-B-SBLO	Road SBLO - BAK - Edgware Road to Marylebone	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47794	ACTIVE	B	B074-B-SBLO	Road SBLO - BAK - Edgware Road to Marylebone	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47791	ACTIVE	B	B074-B-SBLO	Road SBLO - BAK - Edgware Road to Marylebone	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47789	ACTIVE	B	B074-B-SBLO	Road SBLO - BAK - Edgware Road to Marylebone	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47790	ACTIVE	B	B074-B-SBLO	Road SBLO - BAK - Edgware Road to Marylebone	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					



Hazardous Material Asset Register - Summary



B074-B - BAK Line - Edgware Road to Marylebone

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47792	ACTIVE	B	B074-B-SBLO	Road SBLO - BAK - Edgware Road to Marylebone	Cable Sheath	Asbestos	Known	22			Over track crossing to large bore tunnel from northbound tunnel. some localised damage and fraying - loose fibres - encapsulation					
47793	ACTIVE	B	B074-B-SBLO	Road SBLO - BAK - Edgware Road to Marylebone	Cable Sheath	Asbestos	Known	23			From over track crossing throughout tunnel. some localised damage and fraying - loose fibres - encapsulation					

B076-B - BAK Line - Marylebone to Baker Street

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47243	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47241	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Ducts	Asbestos	Known				Asset located at floor level					
47248	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Current Rail Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring.					
47258	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47259	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47239	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Signal Boxes	Asbestos	Presumed				To wall of cross passage					
47240	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Signal Boxes	Asbestos	Presumed				To wall of cross passage					
47245	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47249	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					



Hazardous Material Asset Register - Summary



B076-B - BAK Line - Marylebone to Baker Street

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47242	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47247	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Ducts	Asbestos	Known			LHS	To floor					
47237	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Other Electrical Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring.					
47260	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47265	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47266	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47235	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47236	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47238	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Westinghouse Boxes	Asbestos	Presumed				To wall of cross passage					
47244	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47246	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47255	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Westinghouse Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring.					
47256	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47257	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47261	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47262	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47263	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					



Hazardous Material Asset Register - Summary



B076-B - BAK Line - Marylebone to Baker Street

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47264	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47234	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Other Electrical Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47233	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Cable Sheath	Asbestos	Known	1		RHS	From head wall running along tunnel					
47253	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Cable Sheath	Asbestos	Known	34		RHS	Cables connected to asset, run into cable run					
47250	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Signal Boxes	Asbestos	Presumed	35		RHS	Asset located on tunnel ring.					
47251	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Signal Boxes	Asbestos	Known	36		RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47254	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Signal Boxes	Asbestos	Known	37		LHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47252	ACTIVE	B	B076-B-NBLO	Road NBLO - BAK - Baker Street to Marylebone	Cable Sheath	Asbestos	Known	39		RHS	Cables connected to asset, run into cable run					
47778	ACTIVE	B	B076-B-SBLO	Road SBLO - BAK - Marylebone to Baker Street	Current Rail Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47768	ACTIVE	B	B076-B-SBLO	Road SBLO - BAK - Marylebone to Baker Street	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate.					
47769	ACTIVE	B	B076-B-SBLO	Road SBLO - BAK - Marylebone to Baker Street	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring					
47773	ACTIVE	B	B076-B-SBLO	Road SBLO - BAK - Marylebone to Baker Street	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					



Hazardous Material Asset Register - Summary



B076-B - BAK Line - Marylebone to Baker Street

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47774	ACTIVE	B	B076-B-SBLO	Road SBLO - BAK - Marylebone to Baker Street	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47780	ACTIVE	B	B076-B-SBLO	Road SBLO - BAK - Marylebone to Baker Street	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47781	ACTIVE	B	B076-B-SBLO	Road SBLO - BAK - Marylebone to Baker Street	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47770	ACTIVE	B	B076-B-SBLO	Road SBLO - BAK - Marylebone to Baker Street	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47776	ACTIVE	B	B076-B-SBLO	Road SBLO - BAK - Marylebone to Baker Street	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47782	ACTIVE	B	B076-B-SBLO	Road SBLO - BAK - Marylebone to Baker Street	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47771	ACTIVE	B	B076-B-SBLO	Road SBLO - BAK - Marylebone to Baker Street	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47772	ACTIVE	B	B076-B-SBLO	Road SBLO - BAK - Marylebone to Baker Street	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47775	ACTIVE	B	B076-B-SBLO	Road SBLO - BAK - Marylebone to Baker Street	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47777	ACTIVE	B	B076-B-SBLO	Road SBLO - BAK - Marylebone to Baker Street	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47779	ACTIVE	B	B076-B-SBLO	Road SBLO - BAK - Marylebone to Baker Street	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47783	ACTIVE	B	B076-B-SBLO	Road SBLO - BAK - Marylebone to Baker Street	Cable Sheath	Asbestos	Known			LHS	Asset located on tunnel exit into cross passage. Remedial works advised. Some localised damage.					
47767	ACTIVE	B	B076-B-SBLO	Road SBLO - BAK - Marylebone to Baker Street	Cable Sheath	Asbestos	Known			LHS	Asset located on head wall to tunnel					
47784	ACTIVE	B	B076-B-SBLO	Road SBLO - BAK - Marylebone to Baker Street	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					



Hazardous Material Asset Register - Summary



B077-B - BAK Line - Baker Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47231	ACTIVE	B	B077-B-NBLO	Road NBLO (Plt9) - BAK - Baker Street Stn	Cable Sheath	Asbestos	Known	1		RHS	From tail wall into tunnel					
47230	ACTIVE	B	B077-B-NBLO	Road NBLO (Plt9) - BAK - Baker Street Stn	Ducts	Asbestos	Known	1		RHS	Asset located on tail wall					
47232	ACTIVE	B	B077-B-NBLO	Road NBLO (Plt9) - BAK - Baker Street Stn	Westinghouse Boxes	Asbestos	Presumed	84		RHS	Below platform					
47765	ACTIVE	B	B077-B-SBLO	Road SBLO (Plt8) - BAK - Baker Street Stn	Signal Boxes	Asbestos	Presumed	1		RHS	Asset located on tunnel wall					
47766	ACTIVE	B	B077-B-SBLO	Road SBLO (Plt8) - BAK - Baker Street Stn	Westinghouse Boxes	Asbestos	Presumed	85		LHS	Asset located beneath platform					

B122-B - BAK Line - Baker Street to Regents Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47755	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47756	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47750	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47749	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47760	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47761	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47762	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47763	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47764	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47728	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Cable Sheath	Asbestos	Known			RHS	On cable run running throughout					
47737	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Cable Sheath	Asbestos	Known			RHS	Over track crossing to Jubilee Line					
47746	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Cable Sheath	Asbestos	Known			RHS	To tunnel wall coming out of 10 core box					



Hazardous Material Asset Register - Summary



B122-B - BAK Line - Baker Street to Regents Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47743	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Current Rail Boxes	Asbestos	Presumed			LHS	Asset located on tunnel wall					
47731	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47744	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47753	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47758	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47730	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47734	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47745	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47751	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47752	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47754	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47757	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					



Hazardous Material Asset Register - Summary



B122-B - BAK Line - Baker Street to Regents Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47759	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47726	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Westinghouse Boxes	Asbestos	Presumed			LHS	Asset located on tunnel wall					
47727	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47729	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47732	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47733	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47735	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47736	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47738	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47739	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47740	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47741	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47742	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47747	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47748	ACTIVE	B	B122-B-SBLO	Road SBLO - BAK - Baker Street to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					

B123-B - BAK Line - Regents Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47405	ACTIVE	B	B123-B-NBLO	Road NBLO (Plt1) - BAK - Regents Park Stn	Pit Blocks	Asbestos	Known			RHS	Platform wall side					
47229	ACTIVE	B	B123-B-NBLO	Road NBLO (Plt1) - BAK - Regents Park Stn	Cable Sheath	Asbestos	Known	105		LHS	Redundant braided cable identified under platform					



Hazardous Material Asset Register - Summary



B123-B - BAK Line - Regents Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47406	ACTIVE	B	B123-B-NBLO	Road NBLO (Plt1) - BAK - Regents Park Stn	Cable Sheath	Asbestos	Known	105		LHS	Under platform					

B124-B - BAK Line - Regents Park to Oxford Circus

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47202	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Signal Boxes	Asbestos	Known			LHS	Asset located on tunnel wall. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47203	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47209	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47210	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47214	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					



Hazardous Material Asset Register - Summary



B124-B - BAK Line - Regents Park to Oxford Circus

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47215	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47222	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47223	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel wall. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47200	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Signal Boxes	Asbestos	Presumed			LHS	To head wall					
47204	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47211	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47216	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47224	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47201	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47205	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47206	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47207	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47208	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47212	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					



Hazardous Material Asset Register - Summary



B124-B - BAK Line - Regents Park to Oxford Circus

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47213	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47217	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47218	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47219	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47220	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47221	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47225	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47227	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47228	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel wall					
47226	ACTIVE	B	B124-B-NBLO	Road NBLO - BAK - Oxford Circus to Regents Park	Westinghouse Boxes	Asbestos	Presumed	582		RHS	Asset located on tunnel wall					

B126-B - BAK Line - Oxford Circus to Piccadilly Circus

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47173	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47171	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47181	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					



Hazardous Material Asset Register - Summary



B126-B - BAK Line - Oxford Circus to Piccadilly Circus

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47182	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47184	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47191	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47193	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47162	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47163	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring.					
47164	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47404	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47148	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47152	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47155	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					



Hazardous Material Asset Register - Summary



B126-B - BAK Line - Oxford Circus to Piccadilly Circus

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47180	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47147	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47146	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47145	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47143	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47142	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47160	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47159	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring.					
47136	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Westinghouse Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring.					
47144	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47168	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Westinghouse Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring.					
47169	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47170	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					



Hazardous Material Asset Register - Summary



B126-B - BAK Line - Oxford Circus to Piccadilly Circus

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47174	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47175	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47177	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47178	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47179	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47183	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47185	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47190	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47194	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47176	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Boarding / Panels	Asbestos	Known			RHS	Asset located on tunnel ring. to positive and negative current rail section switch boxes					
47189	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Cement Cable Troughing & Debris	Asbestos	Known			RHS	To 4 foot and lower horizontal area					
47188	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Tunnel Ring Caulking	Asbestos	Known			LHS	Asset located on tunnel ring.					
47153	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Current Rail Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47186	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Current Rail Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring.					
47187	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Current Rail Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring.					
47149	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenace impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					



Hazardous Material Asset Register - Summary



B126-B - BAK Line - Oxford Circus to Piccadilly Circus

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47150	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47157	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47141	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Known			LHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47165	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47166	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Known			LHS	Asset located on tunnel ring.					
47167	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring.					
47172	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47192	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					



Hazardous Material Asset Register - Summary



B126-B - BAK Line - Oxford Circus to Piccadilly Circus

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47161	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47151	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47154	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47156	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47158	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47132	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Cement Cable Troughing & Debris	Asbestos	Known	1		LHS	To wall within cross over					
47134	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Westinghouse Boxes	Asbestos	Presumed	1		LHS	To wall within cross over					
47133	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Presumed	4		LHS	To wall within cross over					
47135	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Boarding / Panels	Asbestos	Known	11		LHS	To negative current rail section switch					
47137	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Boarding / Panels	Asbestos	Known	13		LHS	To positive current rail section switch					
47139	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Known	14		RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					



Hazardous Material Asset Register - Summary



B126-B - BAK Line - Oxford Circus to Piccadilly Circus

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47138	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Known	14		RHS	To 6 foot within crossover. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before p					
47140	ACTIVE	B	B126-B-NBLO	Road NBLO - BAK - Piccadilly Circus to Oxford Circus	Signal Boxes	Asbestos	Known	19		LHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47692	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Cement Cable Troughing & Debris	Asbestos	Known			RHS	Behind cables to shoulder offender at low level					
47693	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Tunnel Ring Caulking	Asbestos	Known			LHS	To tunnel rings within cable run					
47686	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Current Rail Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring					
47688	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Current Rail Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring					
47685	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Signal Boxes	Asbestos	Known			LHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47689	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47706	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					



Hazardous Material Asset Register - Summary



B126-B - BAK Line - Oxford Circus to Piccadilly Circus

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47712	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47719	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47724	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Signal Boxes	Asbestos	Known			RHS	To framework to 6 foot. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47690	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47704	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47705	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47707	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47711	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					



Hazardous Material Asset Register - Summary



B126-B - BAK Line - Oxford Circus to Piccadilly Circus

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47713	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47716	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Signal Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring					
47718	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47720	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47723	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Signal Boxes	Asbestos	Presumed			RHS	To framework to 6 foot					
47725	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Signal Boxes	Asbestos	Presumed			LHS	To wall to cess					
47684	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring					
47687	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47691	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47694	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47695	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47696	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47697	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47698	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47699	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47700	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47701	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					



Hazardous Material Asset Register - Summary



B126-B - BAK Line - Oxford Circus to Piccadilly Circus

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47702	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47703	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47708	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47709	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47710	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47714	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47715	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47717	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47721	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47722	ACTIVE	B	B126-B-SBLO	Road SBLO - BAK - Oxford Circus to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					

B128-B - BAK Line - Piccadilly Circus to Charing Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47105	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47125	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47128	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47126	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47123	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					



Hazardous Material Asset Register - Summary



B128-B - BAK Line - Piccadilly Circus to Charing Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47118	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47111	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47109	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47104	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47103	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47131	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47129	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47127	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					



Hazardous Material Asset Register - Summary



B128-B - BAK Line - Piccadilly Circus to Charing Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47122	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47121	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47120	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47117	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47116	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47110	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47100	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Cable Wrap	Asbestos	Known			LHS	To cables to head wall					
47108	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					



Hazardous Material Asset Register - Summary



B128-B - BAK Line - Piccadilly Circus to Charing Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47107	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47106	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47102	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47130	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47112	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47113	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47114	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47115	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47119	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47124	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47101	ACTIVE	B	B128-B-NBLO	Road NBLO - BAK - Charing Cross to Piccadilly Circus	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47677	ACTIVE	B	B128-B-SBLO	Road SBLO - BAK - Piccadilly Circus to Charing Cross	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47676	ACTIVE	B	B128-B-SBLO	Road SBLO - BAK - Piccadilly Circus to Charing Cross	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47675	ACTIVE	B	B128-B-SBLO	Road SBLO - BAK - Piccadilly Circus to Charing Cross	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47673	ACTIVE	B	B128-B-SBLO	Road SBLO - BAK - Piccadilly Circus to Charing Cross	Westinghouse Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring.					
47669	ACTIVE	B	B128-B-SBLO	Road SBLO - BAK - Piccadilly Circus to Charing Cross	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47668	ACTIVE	B	B128-B-SBLO	Road SBLO - BAK - Piccadilly Circus to Charing Cross	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47666	ACTIVE	B	B128-B-SBLO	Road SBLO - BAK - Piccadilly Circus to Charing Cross	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47665	ACTIVE	B	B128-B-SBLO	Road SBLO - BAK - Piccadilly Circus to Charing Cross	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					



Hazardous Material Asset Register - Summary



B128-B - BAK Line - Piccadilly Circus to Charing Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47661	ACTIVE	B	B128-B-SBLO	Road SBLO - BAK - Piccadilly Circus to Charing Cross	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47674	ACTIVE	B	B128-B-SBLO	Road SBLO - BAK - Piccadilly Circus to Charing Cross	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47664	ACTIVE	B	B128-B-SBLO	Road SBLO - BAK - Piccadilly Circus to Charing Cross	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47660	ACTIVE	B	B128-B-SBLO	Road SBLO - BAK - Piccadilly Circus to Charing Cross	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47678	ACTIVE	B	B128-B-SBLO	Road SBLO - BAK - Piccadilly Circus to Charing Cross	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47672	ACTIVE	B	B128-B-SBLO	Road SBLO - BAK - Piccadilly Circus to Charing Cross	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47671	ACTIVE	B	B128-B-SBLO	Road SBLO - BAK - Piccadilly Circus to Charing Cross	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47670	ACTIVE	B	B128-B-SBLO	Road SBLO - BAK - Piccadilly Circus to Charing Cross	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47663	ACTIVE	B	B128-B-SBLO	Road SBLO - BAK - Piccadilly Circus to Charing Cross	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					



Hazardous Material Asset Register - Summary



B128-B - BAK Line - Piccadilly Circus to Charing Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47662	ACTIVE	B	B128-B-SBLO	Road SBLO - BAK - Piccadilly Circus to Charing Cross	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47659	ACTIVE	B	B128-B-SBLO	Road SBLO - BAK - Piccadilly Circus to Charing Cross	Cement Cable Troughing & Debris	Asbestos	Known			LHS	To lower horizontal section					
47658	ACTIVE	B	B128-B-SBLO	Road SBLO - BAK - Piccadilly Circus to Charing Cross	Cement Cable Troughing & Debris	Asbestos	Known			LHS	To lower horizontal section					
47667	ACTIVE	B	B128-B-SBLO	Road SBLO - BAK - Piccadilly Circus to Charing Cross	Boarding / Panels	Asbestos	Known			RHS	To positive and negative current rail section switch box 812					
47683	ACTIVE	B	B128-B-SBLO	Road SBLO - BAK - Piccadilly Circus to Charing Cross	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47682	ACTIVE	B	B128-B-SBLO	Road SBLO - BAK - Piccadilly Circus to Charing Cross	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47679	ACTIVE	B	B128-B-SBLO	Road SBLO - BAK - Piccadilly Circus to Charing Cross	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47680	ACTIVE	B	B128-B-SBLO	Road SBLO - BAK - Piccadilly Circus to Charing Cross	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47681	ACTIVE	B	B128-B-SBLO	Road SBLO - BAK - Piccadilly Circus to Charing Cross	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					

B132-B - BAK Line - Charing Cross to Embankment

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47094	ACTIVE	B	B132-B-NBLO	Road NBLO - BAK - Embankment to Charing Cross	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47083	ACTIVE	B	B132-B-NBLO	Road NBLO - BAK - Embankment to Charing Cross	Cable Wrap	Asbestos	Presumed			LHS	To cables					
47093	ACTIVE	B	B132-B-NBLO	Road NBLO - BAK - Embankment to Charing Cross	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47092	ACTIVE	B	B132-B-NBLO	Road NBLO - BAK - Embankment to Charing Cross	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47088	ACTIVE	B	B132-B-NBLO	Road NBLO - BAK - Embankment to Charing Cross	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47086	ACTIVE	B	B132-B-NBLO	Road NBLO - BAK - Embankment to Charing Cross	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					



Hazardous Material Asset Register - Summary



B132-B - BAK Line - Charing Cross to Embankment

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47085	ACTIVE	B	B132-B-NBLO	Road NBLO - BAK - Embankment to Charing Cross	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47082	ACTIVE	B	B132-B-NBLO	Road NBLO - BAK - Embankment to Charing Cross	Westinghouse Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring.					
47081	ACTIVE	B	B132-B-NBLO	Road NBLO - BAK - Embankment to Charing Cross	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47091	ACTIVE	B	B132-B-NBLO	Road NBLO - BAK - Embankment to Charing Cross	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47080	ACTIVE	B	B132-B-NBLO	Road NBLO - BAK - Embankment to Charing Cross	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47090	ACTIVE	B	B132-B-NBLO	Road NBLO - BAK - Embankment to Charing Cross	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47089	ACTIVE	B	B132-B-NBLO	Road NBLO - BAK - Embankment to Charing Cross	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47079	ACTIVE	B	B132-B-NBLO	Road NBLO - BAK - Embankment to Charing Cross	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47078	ACTIVE	B	B132-B-NBLO	Road NBLO - BAK - Embankment to Charing Cross	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate.					
47077	ACTIVE	B	B132-B-NBLO	Road NBLO - BAK - Embankment to Charing Cross	Current Rail Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47084	ACTIVE	B	B132-B-NBLO	Road NBLO - BAK - Embankment to Charing Cross	Cement Cable Troughing & Debris	Asbestos	Known			LHS	To lower horizontal area, note live cable within					
47087	ACTIVE	B	B132-B-NBLO	Road NBLO - BAK - Embankment to Charing Cross	Cement Cable Troughing & Debris	Asbestos	Known			RHS	To render on lower horizontal area, note live cable					
47652	ACTIVE	B	B132-B-SBLO	Road SBLO - BAK - Charing Cross to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47655	ACTIVE	B	B132-B-SBLO	Road SBLO - BAK - Charing Cross to Embankment	Westinghouse Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring.					



Hazardous Material Asset Register - Summary



B132-B - BAK Line - Charing Cross to Embankment

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47647	ACTIVE	B	B132-B-SBLO	Road SBLO - BAK - Charing Cross to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47645	ACTIVE	B	B132-B-SBLO	Road SBLO - BAK - Charing Cross to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47642	ACTIVE	B	B132-B-SBLO	Road SBLO - BAK - Charing Cross to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on head wall					
47650	ACTIVE	B	B132-B-SBLO	Road SBLO - BAK - Charing Cross to Embankment	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47646	ACTIVE	B	B132-B-SBLO	Road SBLO - BAK - Charing Cross to Embankment	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47649	ACTIVE	B	B132-B-SBLO	Road SBLO - BAK - Charing Cross to Embankment	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47648	ACTIVE	B	B132-B-SBLO	Road SBLO - BAK - Charing Cross to Embankment	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47644	ACTIVE	B	B132-B-SBLO	Road SBLO - BAK - Charing Cross to Embankment	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47643	ACTIVE	B	B132-B-SBLO	Road SBLO - BAK - Charing Cross to Embankment	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47641	ACTIVE	B	B132-B-SBLO	Road SBLO - BAK - Charing Cross to Embankment	Ducts	Asbestos	Known			RHS	Asset located on head wall					
47654	ACTIVE	B	B132-B-SBLO	Road SBLO - BAK - Charing Cross to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47653	ACTIVE	B	B132-B-SBLO	Road SBLO - BAK - Charing Cross to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					



Hazardous Material Asset Register - Summary



B132-B - BAK Line - Charing Cross to Embankment

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47651	ACTIVE	B	B132-B-SBLO	Road SBLO - BAK - Charing Cross to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					

B134-B - BAK Line - Embankment to Waterloo

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47068	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47067	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47023	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47027	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47028	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47033	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47039	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47050	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47051	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47053	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47061	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47062	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47063	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47064	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47065	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47069	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					



Hazardous Material Asset Register - Summary



B134-B - BAK Line - Embankment to Waterloo

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47066	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47071	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47072	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47073	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47074	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47075	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring.					
47016	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47017	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47018	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47022	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47024	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47025	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47026	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47029	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47030	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47035	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47038	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47041	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47042	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					



Hazardous Material Asset Register - Summary



B134-B - BAK Line - Embankment to Waterloo

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47043	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47044	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47045	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47046	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47047	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47048	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47052	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47054	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47055	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47056	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47057	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47058	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47059	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47060	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47097	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Cable Wrap	Asbestos	Known			LHS	Redundant cable runs along tunnel and into cable ducts.					
47098	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Cable Wrap	Asbestos	Known			LHS	Located around cable within 4 foot					
47019	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Cement Cable Troughing & Debris	Asbestos	Known			RHS	Asset located on tunnel ring. Note live cables within					
47049	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Cement Cable Troughing & Debris	Asbestos	Known			RHS	Asset located on tunnel ring. Note live cables within					



Hazardous Material Asset Register - Summary



B134-B - BAK Line - Embankment to Waterloo

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47020	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47021	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47031	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47032	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47034	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47036	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					



Hazardous Material Asset Register - Summary



B134-B - BAK Line - Embankment to Waterloo

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47037	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47040	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed	325		RHS	Asset located on tunnel ring.					
47070	ACTIVE	B	B134-B-NBLO	Road NBLO - BAK - Waterloo to Embankment	Westinghouse Boxes	Asbestos	Presumed	325		RHS	Asset located on tunnel ring.					
47627	ACTIVE	B	B134-B-SBLO	Road SBLO - BAK - Embankment to Waterloo	Cable Sheath	Asbestos	Known			RHS	Asset located on tunnel ring running along tunnel					
47619	ACTIVE	B	B134-B-SBLO	Road SBLO - BAK - Embankment to Waterloo	Cable Sheath	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47618	ACTIVE	B	B134-B-SBLO	Road SBLO - BAK - Embankment to Waterloo	Current Rail Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47613	ACTIVE	B	B134-B-SBLO	Road SBLO - BAK - Embankment to Waterloo	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47614	ACTIVE	B	B134-B-SBLO	Road SBLO - BAK - Embankment to Waterloo	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47615	ACTIVE	B	B134-B-SBLO	Road SBLO - BAK - Embankment to Waterloo	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring.					
47628	ACTIVE	B	B134-B-SBLO	Road SBLO - BAK - Embankment to Waterloo	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					



Hazardous Material Asset Register - Summary



B134-B - BAK Line - Embankment to Waterloo

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47629	ACTIVE	B	B134-B-SBLO	Road SBLO - BAK - Embankment to Waterloo	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47635	ACTIVE	B	B134-B-SBLO	Road SBLO - BAK - Embankment to Waterloo	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47637	ACTIVE	B	B134-B-SBLO	Road SBLO - BAK - Embankment to Waterloo	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47630	ACTIVE	B	B134-B-SBLO	Road SBLO - BAK - Embankment to Waterloo	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47616	ACTIVE	B	B134-B-SBLO	Road SBLO - BAK - Embankment to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47617	ACTIVE	B	B134-B-SBLO	Road SBLO - BAK - Embankment to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47620	ACTIVE	B	B134-B-SBLO	Road SBLO - BAK - Embankment to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47621	ACTIVE	B	B134-B-SBLO	Road SBLO - BAK - Embankment to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47622	ACTIVE	B	B134-B-SBLO	Road SBLO - BAK - Embankment to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47623	ACTIVE	B	B134-B-SBLO	Road SBLO - BAK - Embankment to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47631	ACTIVE	B	B134-B-SBLO	Road SBLO - BAK - Embankment to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47632	ACTIVE	B	B134-B-SBLO	Road SBLO - BAK - Embankment to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47633	ACTIVE	B	B134-B-SBLO	Road SBLO - BAK - Embankment to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47634	ACTIVE	B	B134-B-SBLO	Road SBLO - BAK - Embankment to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					



Hazardous Material Asset Register - Summary



B134-B - BAK Line - Embankment to Waterloo

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47636	ACTIVE	B	B134-B-SBLO	Road SBLO - BAK - Embankment to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47638	ACTIVE	B	B134-B-SBLO	Road SBLO - BAK - Embankment to Waterloo	Westinghouse Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring.					
47639	ACTIVE	B	B134-B-SBLO	Road SBLO - BAK - Embankment to Waterloo	Westinghouse Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring.					
47624	ACTIVE	B	B134-B-SBLO	Road SBLO - BAK - Embankment to Waterloo	Signal Boxes	Asbestos	Known	269		RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47625	ACTIVE	B	B134-B-SBLO	Road SBLO - BAK - Embankment to Waterloo	Westinghouse Boxes	Asbestos	Presumed	274		RHS	Asset located on tunnel ring.					
47626	ACTIVE	B	B134-B-SBLO	Road SBLO - BAK - Embankment to Waterloo	Westinghouse Boxes	Asbestos	Presumed	285		RHS	Asset located on tunnel ring.					

B136-B - BAK Line - Waterloo to Lambeth North

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46952	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Known			LHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
46954	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
46955	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding					



Hazardous Material Asset Register - Summary



B136-B - BAK Line - Waterloo to Lambeth North

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46914	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
46920	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46966	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46971	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46972	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46927	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed			LHS	Located in cess within cross over					
46942	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46990	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46991	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46993	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring.					
46994	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46995	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46997	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46999	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47000	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47003	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47005	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					



Hazardous Material Asset Register - Summary



B136-B - BAK Line - Waterloo to Lambeth North

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47006	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47007	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46947	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46956	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46921	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46922	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46965	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46967	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46968	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46973	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46975	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46923	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46940	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46992	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46996	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47001	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47002	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47004	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47008	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					



Hazardous Material Asset Register - Summary



B136-B - BAK Line - Waterloo to Lambeth North

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47009	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47010	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47011	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46944	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46949	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46950	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46951	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46953	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring.					
46957	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46958	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46959	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46960	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47012	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47013	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
46913	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46916	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46917	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46969	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Boarding / Panels	Asbestos	Known			RHS	To current rail section switch boxes					
46962	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Boarding / Panels	Asbestos	Known			RHS	To current rail section switch boxes					



Hazardous Material Asset Register - Summary



B136-B - BAK Line - Waterloo to Lambeth North

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46945	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
46948	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring.Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
46970	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Cable Sheath	Asbestos	Known			RHS	Redundant electric box					
46976	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Cable Sheath	Asbestos	Known			LHS	Cable located in cess within cross over					
46926	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Cable Sheath	Asbestos	Known				Braided cable identified in over track crossing (OTX)					
47015	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Cable Sheath	Asbestos	Known				Braided cable identified in over track crossing (OTX)					
46963	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Cable Sheath	Asbestos	Known			LHS	Within cross passage from northbound tunnel to southbound tunnel					
46964	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Cable Sheath	Asbestos	Known			RHS	Within cross passage from northbound tunnel to southbound tunnel					
46915	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Cable Sheath	Asbestos	Known				Cable runs from head wall, along tunnel to over track crossing					
46918	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Cable Sheath	Asbestos	Known			RHS	Redundant electric box					
46974	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Cement Cable Troughing & Debris	Asbestos	Known			RHS	AC Troughing located at low-level within cross over. Note no cables within troughing					
46925	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Cement Cable Troughing & Debris	Asbestos	Known			RHS	To tunnel ring at low level, note no cables within troughing					
46998	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Current Rail Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring.					
46946	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Current Rail Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring.					



Hazardous Material Asset Register - Summary



B136-B - BAK Line - Waterloo to Lambeth North

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46919	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
46924	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Known			RHS	Located in cess within cross over. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
46938	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
46939	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
46941	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Known			LHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
46943	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
46977	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Cement Cable Troughing & Debris	Asbestos	Known	55		RHS	AC Troughing located at low-level within cross over. Note no cables within troughing					
46978	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Westinghouse Boxes	Asbestos	Presumed	60		RHS	Asset located on tunnel ring.					



Hazardous Material Asset Register - Summary



B136-B - BAK Line - Waterloo to Lambeth North

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46979	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed	78		LHS	Located in cess within cross over					
46980	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed	78		LHS	Located in cess within cross over					
46928	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Known	79		LHS	Located in cess within cross over. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
46981	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed	79		RHS	Located in cess within cross over					
46982	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed	80		RHS	Located in cess within cross over					
46929	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Known	80		LHS	Located in cess within cross over. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
46931	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed	82		LHS	Located in cess within cross over					
46984	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed	82		LHS	Located in cess within cross over					
46983	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed	82		LHS	Located in cess within cross over					
46930	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Known	82		LHS	Located in cess within cross over. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
46932	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Boarding / Panels	Asbestos	Known	114		LHS	To current rail section switch boxes					
46985	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Cement Cable Troughing & Debris	Asbestos	Known	114		LHS	Cement panels to current rail section switch					
46934	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Cement Cable Troughing & Debris	Asbestos	Known	115		LHS	AC Troughing located at low-level. Note no cables within troughing					
46933	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Cement Cable Troughing & Debris	Asbestos	Known	115		LHS	AC Troughing located at low-level. Note no cables within troughing					



Hazardous Material Asset Register - Summary



B136-B - BAK Line - Waterloo to Lambeth North

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46987	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Cement Cable Troughing & Debris	Asbestos	Known	115		LHS	AC Troughing located at low-level within cross over. Note no cables within troughing					
46986	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Cement Cable Troughing & Debris	Asbestos	Known	115		LHS	AC Troughing located at low-level within cross over. Note no cables within troughing					
46988	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed	124		RHS	Located in cess within cross over					
46935	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Presumed	124		RHS	Located in cess within cross over					
46936	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Signal Boxes	Asbestos	Known	124		RHS	Located in cess within cross over					
46937	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Cable Sheath	Asbestos	Known	125			Braided cable identified in over track crossing (OTX)					
46989	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Cable Sheath	Asbestos	Known	125			Braided cable identified in over track crossing (OTX)					
46961	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Ducts	Asbestos	Known	521		LHS	To floor to beginning of suicide pit					
47014	ACTIVE	B	B136-B-NBLO	Road NBLO - BAK - Lambeth North to Waterloo	Ducts	Asbestos	Known	521		LHS	Ducts located at floor level					
47607	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47606	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47576	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47577	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47578	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47579	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47584	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47585	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					



Hazardous Material Asset Register - Summary



B136-B - BAK Line - Waterloo to Lambeth North

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47586	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47587	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47592	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47593	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47605	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47608	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Within cross passage					
47609	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47610	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47612	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47572	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Cement Cable Troughing & Debris	Asbestos	Known			LHS	To lower horizontal and floor, note cables within					
47571	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47602	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47590	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47588	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47581	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					



Hazardous Material Asset Register - Summary



B136-B - BAK Line - Waterloo to Lambeth North

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47591	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Current Rail Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47611	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Current Rail Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47574	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47582	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47583	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring.					
47589	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47594	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47603	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47604	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					



Hazardous Material Asset Register - Summary



B136-B - BAK Line - Waterloo to Lambeth North

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47573	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47575	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47580	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47595	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Signal Boxes	Asbestos	Known	418		RHS	To 6 foot within cross over. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47596	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Signal Boxes	Asbestos	Presumed	419		RHS	To 6 foot within cross over					
47597	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Signal Boxes	Asbestos	Known	419		RHS	To 6 foot within cross over					
47598	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Cement Cable Troughing & Debris	Asbestos	Known	433	440	LHS	To lower horizontal and within cross over, note 2 No. have cables within					
47601	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Signal Boxes	Asbestos	Known	453		RHS	To 6 foot within cross over. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47600	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Cement Cable Troughing & Debris	Asbestos	Known	480		LHS	To floor					
47599	ACTIVE	B	B136-B-SBLO	Road SBLO - BAK - Waterloo to Lambeth North	Boarding / Panels	Asbestos	Known	480		LHS	To positive and negative current rail section switch 814A					



Hazardous Material Asset Register - Summary



B137-B - BAK Line - Lambeth North Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
64532	ACTIVE	B	B137-B-NBLO	Road NBLO (Plt1) - BAK - Lambeth North Stn	Ducts	Asbestos	Sampled – Not Detected	117		LHS	BRS117 - 3no. cable ducts to floor by head wall		3	R401253		
64533	ACTIVE	B	B137-B-SBLO	Road SBLO (Plt2) - BAK - Lambeth North Stn	Ducts	Asbestos	Sampled – Not Detected	4		LHS	BRS4 - 6no. cable cuts to floor		6	R401290		

B138-B - BAK Line - Lambeth North to Elephant & Castle

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46904	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46905	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46909	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46882	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46867	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46868	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46871	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46874	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46886	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46890	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46891	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46893	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46897	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46898	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46899	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					



Hazardous Material Asset Register - Summary



B138-B - BAK Line - Lambeth North to Elephant & Castle

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46903	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46910	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Cable Sheath	Asbestos	Known				Cable identified within cross passage from northbound tunnel to southbound tunnel					
46911	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Cable Sheath	Asbestos	Known			LHS	Cable runs from ventilation shaft and across the track in over track crossing (OTX)					
46912	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Cable Sheath	Asbestos	Known				Cable identified within OTX					
46883	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Current Rail Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46876	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
46877	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring, Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
46902	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46889	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46896	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46879	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
46907	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring, Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					



Hazardous Material Asset Register - Summary



B138-B - BAK Line - Lambeth North to Elephant & Castle

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46908	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Signal Boxes	Asbestos	Known			LHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
46881	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
46884	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
46870	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
46872	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
46887	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					



Hazardous Material Asset Register - Summary



B138-B - BAK Line - Lambeth North to Elephant & Castle

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46888	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
46892	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
46894	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
46895	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
46900	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
46901	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
46875	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46880	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					



Hazardous Material Asset Register - Summary



B138-B - BAK Line - Lambeth North to Elephant & Castle

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46906	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46885	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46869	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46873	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
46878	ACTIVE	B	B138-B-NBLO	Road NBLO - BAK - Elephant & Castle to Lambeth North	Signal Boxes	Asbestos	Known	28		RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47559	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Cable Sheath	Asbestos	Known			RHS	From cross over to tail wall					
47570	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Cement Cable Troughing & Debris	Asbestos	Known			LHS	To lower horizontal, note live cable within (removed)					
47555	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Cement Cable Troughing & Debris	Asbestos	Known			LHS	To lower render within cross over					
47548	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Current Rail Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47562	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Current Rail Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47519	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47520	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					



Hazardous Material Asset Register - Summary



B138-B - BAK Line - Lambeth North to Elephant & Castle

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47531	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Signal Boxes	Asbestos	Known			LHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47532	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Signal Boxes	Asbestos	Known			LHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47536	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Signal Boxes	Asbestos	Known			LHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47539	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47566	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47569	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					



Hazardous Material Asset Register - Summary



B138-B - BAK Line - Lambeth North to Elephant & Castle

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47540	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding					
47545	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47550	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47554	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47560	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47521	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47533	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47567	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47542	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					



Hazardous Material Asset Register - Summary



B138-B - BAK Line - Lambeth North to Elephant & Castle

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47544	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47546	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47553	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47561	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47518	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47522	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47523	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47525	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47526	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47527	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47528	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47529	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47530	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47534	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47537	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Westinghouse Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring.					
47538	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47565	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					



Hazardous Material Asset Register - Summary



B138-B - BAK Line - Lambeth North to Elephant & Castle

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47568	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47541	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47543	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47547	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47549	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47551	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47552	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Westinghouse Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring.					
47563	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47524	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Boarding / Panels	Asbestos	Known			RHS	To positive and negative current rail section switch boxes					
47564	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Boarding / Panels	Asbestos	Known			RHS	To positive and negative current rail section switch 818					
47535	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Other Electrical Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring. Redundant junction box.					
47557	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Cable Sheath	Asbestos	Known	708		RHS	Within 6 foot in cross over					
47556	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Signal Boxes	Asbestos	Known	708		RHS	Within 6 foot in cross over. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47558	ACTIVE	B	B138-B-SBLO	Road SBLO - BAK - Lambeth North to Elephant & Castle	Cable Sheath	Asbestos	Known	708		RHS	From northbound tunnel to high level J hangers within cross over.					



Hazardous Material Asset Register - Summary



B142-B - BAK Line - Elephant & Castle Overrun

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47510	ACTIVE	B	B142-B-NBLO	Road NBLO - BAK - Elephant & Castle to Buffer	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47505	ACTIVE	B	B142-B-NBLO	Road NBLO - BAK - Elephant & Castle to Buffer	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47504	ACTIVE	B	B142-B-NBLO	Road NBLO - BAK - Elephant & Castle to Buffer	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47502	ACTIVE	B	B142-B-NBLO	Road NBLO - BAK - Elephant & Castle to Buffer	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47500	ACTIVE	B	B142-B-NBLO	Road NBLO - BAK - Elephant & Castle to Buffer	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47511	ACTIVE	B	B142-B-NBLO	Road NBLO - BAK - Elephant & Castle to Buffer	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47513	ACTIVE	B	B142-B-NBLO	Road NBLO - BAK - Elephant & Castle to Buffer	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47498	ACTIVE	B	B142-B-NBLO	Road NBLO - BAK - Elephant & Castle to Buffer	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47499	ACTIVE	B	B142-B-NBLO	Road NBLO - BAK - Elephant & Castle to Buffer	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					



Hazardous Material Asset Register - Summary



B142-B - BAK Line - Elephant & Castle Overrun

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47501	ACTIVE	B	B142-B-NBLO	Road NBLO - BAK - Elephant & Castle to Buffer	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47503	ACTIVE	B	B142-B-NBLO	Road NBLO - BAK - Elephant & Castle to Buffer	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47506	ACTIVE	B	B142-B-NBLO	Road NBLO - BAK - Elephant & Castle to Buffer	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47507	ACTIVE	B	B142-B-NBLO	Road NBLO - BAK - Elephant & Castle to Buffer	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47508	ACTIVE	B	B142-B-NBLO	Road NBLO - BAK - Elephant & Castle to Buffer	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47512	ACTIVE	B	B142-B-NBLO	Road NBLO - BAK - Elephant & Castle to Buffer	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47514	ACTIVE	B	B142-B-NBLO	Road NBLO - BAK - Elephant & Castle to Buffer	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47515	ACTIVE	B	B142-B-NBLO	Road NBLO - BAK - Elephant & Castle to Buffer	Westinghouse Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenace impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47516	ACTIVE	B	B142-B-NBLO	Road NBLO - BAK - Elephant & Castle to Buffer	Westinghouse Boxes	Asbestos	Presumed			LHS	Asset located on tunnel ring.					
47517	ACTIVE	B	B142-B-NBLO	Road NBLO - BAK - Elephant & Castle to Buffer	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring.					
47509	ACTIVE	B	B142-B-NBLO	Road NBLO - BAK - Elephant & Castle to Buffer	Boarding / Panels	Asbestos	Known	192		RHS	Asset located on tunnel ring.					
47984	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47978	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47972	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
48002	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
48000	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					



Hazardous Material Asset Register - Summary



B142-B - BAK Line - Elephant & Castle Overrun

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
48001	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47969	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47999	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47977	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47993	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47994	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47997	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
48003	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
48004	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Westinghouse Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47980	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Boarding / Panels	Asbestos	Known			RHS	To negative and positive current rail switched					
47970	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Cement Cable Troughing & Debris	Asbestos	Known				Within 4 foot					
47971	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Cement Cable Troughing & Debris	Asbestos	Known			LHS	To render on tunnel rings					
47975	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Cement Cable Troughing & Debris	Asbestos	Known				From tunnel rings 10 -30 within cess and 4 foot					
47979	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Cement Cable Troughing & Debris	Asbestos	Known				To floor within 4 foot, note live cables					
47981	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Cement Cable Troughing & Debris	Asbestos	Known			RHS	Within cess and lower horizontal section					
47982	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Cement Cable Troughing & Debris	Asbestos	Known			RHS	Within cess and lower horizontal section					



Hazardous Material Asset Register - Summary



B142-B - BAK Line - Elephant & Castle Overrun

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47983	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Cement Cable Troughing & Debris	Asbestos	Known			RHS	Within cess and lower horizontal section					
47995	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Current Rail Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47974	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47976	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47973	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Signal Boxes	Asbestos	Presumed			RHS	Asset located on tunnel ring					
47992	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47996	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite mount panel/ board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47998	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Signal Boxes	Asbestos	Known			RHS	Asset located on tunnel ring. Brown composite component mounting blocks & composite rings/ spacers on supporting baseplate. Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before					
47985	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Westinghouse Boxes	Asbestos	Presumed	103		RHS	Asset located on tunnel ring within cross over					
47986	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Westinghouse Boxes	Asbestos	Presumed	119		RHS	Asset located on tunnel ring within cross over					



Hazardous Material Asset Register - Summary



B142-B - BAK Line - Elephant & Castle Overrun

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47987	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Signal Boxes	Asbestos	Known	154		RHS	Asset located on tunnel ring within cross over. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					
47988	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Signal Boxes	Asbestos	Presumed	160		RHS	Asset located on tunnel ring within cross over					
47991	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Westinghouse Boxes	Asbestos	Presumed	161		RHS	Asset located on tunnel ring within cross over					
47989	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Signal Boxes	Asbestos	Presumed	161		RHS	Asset located on tunnel ring within cross over					
47990	ACTIVE	B	B142-B-SBLO	Road SBLO - BAK - Elephant & Castle to Buffer	Signal Boxes	Asbestos	Known	161		RHS	Asset located on tunnel ring within cross over. Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					

C123-B - BAK Line - Oxford Circus Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47199	ACTIVE	B	C123-B-NBLO	Road NBLO (Plt4) - BAK - Oxford Circus Stn	Westinghouse Boxes	Asbestos	Presumed	1		RHS	To track wall					
47195	ACTIVE	B	C123-B-SBLO	Road SBLO (Plt3) - BAK - Oxford Circus Stn	Signal Boxes	Asbestos	Presumed	1		LHS	Tail wall of platform					
47198	ACTIVE	B	C123-B-SBLO	Road SBLO (Plt3) - BAK - Oxford Circus Stn	Cable Sheath	Asbestos	Known	65		LHS	Redundant braided cable identified under platform					
47196	ACTIVE	B	C123-B-SBLO	Road SBLO (Plt3) - BAK - Oxford Circus Stn	Signal Boxes	Asbestos	Presumed	65		LHS	Cables connected to asset, run into cable run					
47197	ACTIVE	B	C123-B-SBLO	Road SBLO (Plt3) - BAK - Oxford Circus Stn	Signal Boxes	Asbestos	Known	66		LHS	Under platform, Brown composite mount panel/board Where works/maintenance impacts known ACM by drilling, cutting or removal. The HM Team must be contacted for further guidance before proceeding.					



Hazardous Material Asset Register - Summary



N109-B - BAK Line - Charing Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47099	ACTIVE	B	N109-B-NBLO	Road NBLO (Plt1) - BAK - Charing Cross Stn	Cable Wrap	Asbestos	Known	113		LHS	To cable to head wall					
47656	ACTIVE	B	N109-B-SBLO	Road SBLO (Plt2) - BAK - Charing Cross Stn	Westinghouse Boxes	Asbestos	Presumed	30		RHS	Asset located on platform wall					
47657	ACTIVE	B	N109-B-SBLO	Road SBLO (Plt2) - BAK - Charing Cross Stn	Cable Sheath	Asbestos	Known	80		RHS	Asset located on platform wall within metal cable duct					

N113-B - BAK Line - Embankment Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
47096	ACTIVE	B	N113-B-NBLO	Road NBLO (Plt5) - BAK - Embankment Stn	Westinghouse Boxes	Asbestos	Presumed		117		to head wall					
46865	ACTIVE	B	N113-B-NBLO	Road NBLO (Plt5) - BAK - Embankment Stn	Cable Wrap	Asbestos	Presumed	1	4		to floor from tunnel to suicide pit					
47095	ACTIVE	B	N113-B-NBLO	Road NBLO (Plt5) - BAK - Embankment Stn	Cable Wrap	Asbestos	Presumed	1	4		To floor from tunnel to suicide pit					
47076	ACTIVE	B	N113-B-NBLO	Road NBLO (Plt5) - BAK - Embankment Stn	Cable Wrap	Asbestos	Presumed	1	4		Ducts located at floor level					
46866	ACTIVE	B	N113-B-NBLO	Road NBLO (Plt5) - BAK - Embankment Stn	Westinghouse Boxes	Asbestos	Presumed	117		LHS	to head wall					
47640	ACTIVE	B	N113-B-SBLO	Road SBLO (Plt6) - BAK - Embankment Stn	Westinghouse Boxes	Asbestos	Presumed	117		LHS	Asset located on head wall					

N139-B - BAK Line - Elephant & Castle Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
64514	ACTIVE	B	N139-B-NBLO	Road NBLO (Plt3) - BAK - Elephant & Castle Stn	Westinghouse Boxes	Asbestos	Presumed	64		RHS	BRS64 - 1no. small westinghouse box below platform		1	R401251		
64515	ACTIVE	B	N139-B-NBLO	Road NBLO (Plt3) - BAK - Elephant & Castle Stn	Westinghouse Boxes	Asbestos	Presumed	66		RHS	BRS66 - 1no. small westinghouse box below platform		1	R401251		
64516	ACTIVE	B	N139-B-NBLO	Road NBLO (Plt3) - BAK - Elephant & Castle Stn	Westinghouse Boxes	Asbestos	Presumed	67		RHS	BRS67 - 1no. small westinghouse box below platform		1	R401251		
64517	ACTIVE	B	N139-B-NBLO	Road NBLO (Plt3) - BAK - Elephant & Castle Stn	Other Electrical Boxes	Asbestos	Presumed	93		RHS	BRS93 - 1no. 10 core box below platform		1	R401251		
64518	ACTIVE	B	N139-B-NBLO	Road NBLO (Plt3) - BAK - Elephant & Castle Stn	Other Electrical Boxes	Asbestos	Presumed	103		LHS	BRS103 - 1no. EP valve to wall		1	R401251		
64519	ACTIVE	B	N139-B-NBLO	Road NBLO (Plt3) - BAK - Elephant & Castle Stn	Ducts	Asbestos	Sampled – Not Detected	104		LHS	BRS104 - 2no. cable ducts to floor		2	R401251		



Hazardous Material Asset Register - Summary



N139-B - BAK Line - Elephant & Castle Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
64520	ACTIVE	B	N139-B-NBLO	Road NBLO (Pit3) - BAK - Elephant & Castle Stn	Ducts	Asbestos	Sampled – Not Detected	117		LHS	BRS117 - 4no. cable ducts to head wall		4	R401251		
64521	ACTIVE	B	N139-B-SBLO	Road SBLO (Pit4) - BAK - Elephant & Castle Stn	Signal Boxes	Asbestos	Presumed	1			BRS0.5 - 1no. signal to head wall		1	R401288		
64522	ACTIVE	B	N139-B-SBLO	Road SBLO (Pit4) - BAK - Elephant & Castle Stn	Cement Cable Troughing & Debris	Asbestos	Known	28		RHS	BRS28 - Cement troughing (1m) running to platform side wall to invert	1		R401288		
64523	ACTIVE	B	N139-B-SBLO	Road SBLO (Pit4) - BAK - Elephant & Castle Stn	Boarding / Panels	Asbestos	Sampled – Not Detected	32		RHS	BRS32 - Fibre glass panel (<1m²) to platform wall behind cables	1		R401288		
64524	ACTIVE	B	N139-B-SBLO	Road SBLO (Pit4) - BAK - Elephant & Castle Stn	Cement Cable Troughing & Debris	Asbestos	Known	62			BRS 62 - Cement troughing (2no. 8lm) to 4 foot (track)	8	2	R401288		
64525	ACTIVE	B	N139-B-SBLO	Road SBLO (Pit4) - BAK - Elephant & Castle Stn	Other Electrical Boxes	Asbestos	Presumed	74		RHS	BRS74 - 1no. EP valve to platform side wall		1	R401288		
64526	ACTIVE	B	N139-B-SBLO	Road SBLO (Pit4) - BAK - Elephant & Castle Stn	Other Electrical Boxes	Asbestos	Presumed	78		RHS	BRS78 - 1no. 10 core box to platform side wall		1	R401288		
64527	ACTIVE	B	N139-B-SBLO	Road SBLO (Pit4) - BAK - Elephant & Castle Stn	Ducts	Asbestos	Known	81		LHS	BRS81 - Bitumen cable ducts (2no. 3lm) under track crossing running from invert to cable shaft	3	2	R401288		
64528	ACTIVE	B	N139-B-SBLO	Road SBLO (Pit4) - BAK - Elephant & Castle Stn	Other Electrical Boxes	Asbestos	Presumed	99		RHS	BRS99 - 1no. electrical box to platform side wall		1	R401288		
64529	ACTIVE	B	N139-B-SBLO	Road SBLO (Pit4) - BAK - Elephant & Castle Stn	Cement Cable Troughing & Debris	Asbestos	Known	105			BRS105 - Cement troughing (1no. 1lm) to 4 foot	1	1	R401288		
64530	ACTIVE	B	N139-B-SBLO	Road SBLO (Pit4) - BAK - Elephant & Castle Stn	Ducts	Asbestos	Known	112		LHS	BRS112 - Bitumen cable ducts (2no. 3lm) under track crossing	3	2	R401288		
64531	ACTIVE	B	N139-B-SBLO	Road SBLO (Pit4) - BAK - Elephant & Castle Stn	Ducts	Asbestos	Known	113		LHS	BRS113 - Bitumen cable ducts (2no. 3lm) under track crossing	3	2	R401288		