



Hazardous Material Asset Register - Summary



Run date: 19/08/2024

Line: Piccadilly

Risk Assessment Status: Active, Inactive
Hazardous Material Status: All
Hazardous Material Type: All

D109-P - PIC Line - South Kensington Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42772	ACTIVE	p	D109-P-EBLO	Road EBLO (Plt4) - PIC - South Kensington Stn	Pit Blocks	Asbestos	Surveyed – Not Detected				Pit blocks - Non asbestos					
42771	ACTIVE	p	D109-P-WBLO	Road WBLO (Plt3) - PIC - South Kensington Stn	Pit Blocks	Asbestos	Surveyed – Not Detected				Pit blocks - Non asbestos					
41423	ACTIVE	p	D109-P-WBLO	Road WBLO (Plt3) - PIC - South Kensington Stn	Cable Sheath	Asbestos	Removed	53		RHS	Cloth, cable sheathing. 0.1m - removed - confirmed reinspection 2022					
41422	ACTIVE	p	D109-P-WBLO	Road WBLO (Plt3) - PIC - South Kensington Stn	Westinghouse Boxes	Asbestos	Removed	53		RHS	Trackside equipment: Westinghouse small box - confirmed removed 2022 reinspection					
41424	ACTIVE	p	D109-P-WBLO	Road WBLO (Plt3) - PIC - South Kensington Stn	Westinghouse Boxes	Asbestos	Presumed	80		RHS	Trackside equipment: Westinghouse small box. Entry: Westinghouse house small, Route: Back plate insulation. 0 .2m					
41425	ACTIVE	p	D109-P-WBLO	Road WBLO (Plt3) - PIC - South Kensington Stn	Westinghouse Boxes	Asbestos	Presumed	85		RHS	Trackside equipment: Westinghouse small box. Entry: Westinghouse house small, Route: Back plate insulation. 0 .2m					
41426	ACTIVE	p	D109-P-WBLO	Road WBLO (Plt3) - PIC - South Kensington Stn	Cable Sheath	Asbestos	Known	85		RHS	Cloth, cable sheathing. 0.1m					

D212-P - PIC Line - Acton Town to South Ealing

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40591	ACTIVE	p	D212-P-EBFA	Road EBFA - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Known			LHS	Flash guards Signal A477		1			
40592	ACTIVE	p	D212-P-EBFA	Road EBFA - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	441		RHS	Flash guards Signal R483		1			
40593	ACTIVE	p	D212-P-EBFA	Road EBFA - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	520		LHS	Flash guards Fog repeater A483		1			
40594	ACTIVE	p	D212-P-EBFA	Road EBFA - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	610		LHS	Flash guards Marshalling kiosk		1			
40595	ACTIVE	p	D212-P-EBFA	Road EBFA - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	640		LHS	Flash guards Signal A483 on bridge D54B		1			
40596	ACTIVE	p	D212-P-EBFA	Road EBFA - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	982		RHS	Flash guards Fog repeater WLX487		1			
40597	ACTIVE	p	D212-P-EBFA	Road EBFA - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1068		RHS	Flash guards Signal 5RWLX487		1			



Hazardous Material Asset Register - Summary



D212-P - PIC Line - Acton Town to South Ealing

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39781	ACTIVE	P	D212-P-EBFA	Road EBFA - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1103		RHS	Flash guards Signal WLX487		1			
40598	ACTIVE	P	D212-P-EBFA	Road EBFA - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1201		RHS	Flash guards Signal RWL97 A		1			
40599	ACTIVE	P	D212-P-EBFA	Road EBFA - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1264		LHS	Flash guards Switch boxes		2			
40600	ACTIVE	P	D212-P-EBFA	Road EBFA - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1351		LHS	Flash guards Fog repeater WL97A		1			
40601	ACTIVE	P	D212-P-EBFA	Road EBFA - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1472		LHS	Flash guards Signal 4L97A, RWL97B1		1			
40602	ACTIVE	P	D212-P-EBFA	Road EBFA - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1639		RHS	Flash guards Signal RWL97 B2		1			
40605	ACTIVE	P	D212-P-EBFA	Road EBFA - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1679	1682	LHS	Flash guards Switch boxes 487 BTH, 487BT, CZT, CZTH		6			
40606	ACTIVE	P	D212-P-EBFA	Road EBFA - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1754		LHS	Flash guards Switch box 97BGR		1			
39440	ACTIVE	P	D212-P-EBFA	Road EBFA - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1755		RHS	Flash guards Signal WL97B, Rail Gap Indicator		2			
40603	ACTIVE	P	D212-P-EBFA	Road EBFA - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1775		LHS	Flash guards Rail Gap Indicator		1			
40604	ACTIVE	P	D212-P-EBFA	Road EBFA - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1804		LHS	Flash guards Rail Gap Indicator		1			
40607	ACTIVE	P	D212-P-EBFA	Road EBFA - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1870		RHS	Flash guards Switch boxes CYTR, 99FPGR		2			
40608	ACTIVE	P	D212-P-EBFA	Road EBFA - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1949		LHS	Flash guards High level Signal RWL89		1			
40609	ACTIVE	P	D212-P-EBFA	Road EBFA - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1975		RHS	Flash guards Signal RWL89		1			
39980	ACTIVE	P	D212-P-EBFA	Road EBFA - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	2075		LHS	Flash guards Signal WL89		1			
40610	ACTIVE	P	D212-P-EBFA	Road EBFA - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	2076		LHS	Flash guards Switch box		1			
39441	ACTIVE	P	D212-P-EBFA	Road EBFA - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	2083		LHS	Flash guards Rail Gap Indicator		1			
40611	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Known	1		LHS	Flash guards Signal A457		1			
40612	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Cable Wrap	Asbestos	Sampled – Not Detected	1			Bitumen wrap. Cable on J hanger 2					



Hazardous Material Asset Register - Summary



D212-P - PIC Line - Acton Town to South Ealing

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40613	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	2	5	RHS	Flash guards Marshalling kiosk		3			
40614	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	30		LHS	Flash guards Signal break box		1			
40615	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	32		LHS	Flash guards Signal break box		1			
39442	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	35		LHS	Flash guards Signal break box		1			
40693	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	36		LHS	Flash guards Signal break box		1			
40694	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	83		LHS	Flash guards Signal break box		1			
40695	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	252		LHS	Flash guards Switch box		2			
40696	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	259		LHS	Flash guards Signal break box		1			
40698	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Cement Cable Troughing & Debris	Asbestos	Presumed	259		RHS	Cement cable troughing. Troughing under track		1			
40697	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	259		RHS	Flash guards Switch box		1			
40699	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	261		LHS	Flash guards Signal break box - no. 2		2			
40700	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	262		LHS	Flash guards Signal break box		1			
39785	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	264		LHS	Flash guards Signal break box		1			
40701	INACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Removed	335		LHS	Flash guards Signal break box		1			
40702	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	356		LHS	Flash guards Signal break box		1			
40703	INACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Removed	361		LHS	Flash guards Signal break box		1			
40704	INACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Removed	362		LHS	Flash guards Signal break box		1			
40705	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	438		RHS	Flash guards Marshalling kiosk R438		1			
40706	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	441		RHS	Flash guards Marshalling kiosk R463 & Signal R463		2			



Hazardous Material Asset Register - Summary



D212-P - PIC Line - Acton Town to South Ealing

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40707	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	518		LHS	Flash guards Marshalling kiosk FR483 - no. 1		1			
40708	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	522		LHS	Flash guards F Marshalling kiosk FR483 & Fog repeater A463		2			
40709	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	531		LHS	Flash guards Signal break box		1			
39450	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	549		LHS	Flash guards Signal break box - no.2		2			
40710	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	552		LHS	Flash guards Signal break box		1			
40711	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	605		LHS	Flash guards Marshalling kiosk 463/483		1			
39984	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	608		RHS	Flash guards Marshalling kiosk A483		1			
40712	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	615		LHS	Flash guards Marshalling kiosk A463		1			
40713	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	626		LHS	Flash guards Switch box		1			
40714	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	641		LHS	Flash guards Signal A643		1			
40715	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	657		LHS	Flash guards Signal break box 2no		2			
39473	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	660		LHS	Flash guards Signal break box. 2.no.		2			
40716	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	944		LHS	Flash guards Signal break box 2no		2			
40717	INACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Removed	946		LHS	Flash guards Signal break box		1			
40718	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	954		LHS	Flash guards Signal break box		1			
40719	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	955		LHS	Flash guards Signal break box		1			
39474	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	983		RHS	Flash guards Fog repeater WLX467		1			
40799	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1010		RHS	Flash guards Signal RWLX467		1			
40800	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1012		LHS	Flash guards Marshalling kiosk RWLX467		1			



Hazardous Material Asset Register - Summary



D212-P - PIC Line - Acton Town to South Ealing

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40801	INACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1013		LHS	Flash guards Marshalling kiosk & Signal WLX467		2			
40802	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1014		LHS	Flash guards Signal break box		1			
40803	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1015		LHS	Flash guards Signal break box		1			
40804	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1016		LHS	Flash guards Marshalling kiosk RWLX487		1			
40807	INACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1020		LHS	Flash guards Signal break box		1			
40805	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1020		LHS	Flash guards Signal break box		1			
40806	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1021		LHS	Flash guards Signal break box		1			
39789	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Known	1100		LHS	Cement panel Marshalling kiosk WLX487		1			
40808	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1194		LHS	Flash guards Marshalling kiosk rwl97a		1			
40809	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1198		LHS	Flash guards Marshalling kiosk RWL112		1			
40810	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1201		LHS	Flash guards Signal RWL112A		1			
40811	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1225		LHS	Flash guards Signal break box		1			
40812	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1226		LHS	Flash guards Signal break box		1			
40813	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1227		LHS	Flash guards Signal break box		1			
40814	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1233		LHS	Flash guards Signal break box		1			
40815	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1234		LHS	Flash guards Signal break box		1			
40816	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1355		LHS	Flash guards Marshalling kiosk		1			
40817	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1359	1362	LHS	Flash guards Switch box		5			
39481	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1364		LHS	Flash guards Redundant junction box		1			



Hazardous Material Asset Register - Summary



D212-P - PIC Line - Acton Town to South Ealing

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40818	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1381		LHS	Flash guards Signal break box		1			
40819	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1382		LHS	Flash guards Signal break box		1			
39989	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1471		LHS	Flash guards Switch box		1			
40820	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1472	1474	RHS	Flash guards Switch box		3			
39482	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1475		LHS	Flash guards Signal RWL112A2		1			
40821	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1510		LHS	Flash guards Signal break box		1			
40822	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1515		LHS	Flash guards Signal break box		1			
40823	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1613	1618	LHS	Flash guards Switch box		10			
40824	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1621	1622	LHS	Flash guards Switch box 467AT2, 467AT1		2			
40825	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1628		LHS	Flash guards Marshalling kiosk WC112		1			
39483	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1633		LHS	Flash guards Electrical box		1			
40904	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1636		LHS	Flash guards Switch box 112PGR, 112AGR		2			
40905	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1642		LHS	Flash guards Signal WL112A, RWL112B1		2			
40906	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1643		LHS	Flash guards Signal break box		1			
40907	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1661		LHS	Flash guards Signal break box 2no		2			
40908	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1727		LHS	Flash guards Switch box 467CTR		2			
39498	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1733		LHS	Flash guards Signal RWL112B3		1			
40909	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1739		LHS	Flash guards Signal break box		1			
40910	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1740		LHS	Flash guards Signal break box		1			



Hazardous Material Asset Register - Summary



D212-P - PIC Line - Acton Town to South Ealing

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39995	INACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Removed	1783		LHS	Flash guards Signal break box		1			
40912	INACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Removed	1784		LHS	Flash guards Signal break box		1			
40911	INACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Removed	1788		LHS	Flash guards Signal break box		1			
40913	INACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Removed	1796		LHS	Flash guards Signal break box		1			
40914	INACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Removed	1802		LHS	Flash guards Debris Adj. to right hand wall. Small amounts					
40915	INACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Removed	1805		LHS	Flash guards Troughing under track from wall		5			
40916	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1866		LHS	Flash guards Switch box 467DTR		1			
40917	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1870		LHS	Flash guards Switch box 112CFPGR, 112BGR		2			
40918	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1871		LHS	Flash guards Fog repeater WL112C		1			
40919	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1872		LHS	Flash guards Signal WL112B		1			
40920	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1944		LHS	Flash guards Signal break box 3no		3			
40924	INACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Cement Cable Troughing & Debris	Asbestos	Removed	1955		LHS	cement cable troughing. Troughing under track		3			
40921	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1957		LHS	Flash guards Signal 109FPGR		2			
39490	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1960		LHS	Flash guards Signal WL112C, Fog repeater WL109, Rail Gap Indicator		3			
40922	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Cement Cable Troughing & Debris	Asbestos	Known	1962		LHS	cement cable troughing. Troughing to right hand wall		2			
40923	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	1975		LHS	Flash guards Signal break box 2no		2			
40925	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	2004		LHS	Flash guards Signal break box		1			
39793	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	2047		LHS	Flash guards Switch box		2			
40926	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	2054		LHS	Flash guards Signal break box		1			



Hazardous Material Asset Register - Summary



D212-P - PIC Line - Acton Town to South Ealing

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46177	INACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Cement Troughing	Asbestos	Removed				Cement cable troughing 11 Lm troughing under current rail section switch, under ballast heading towards South Ealing	11			N	N
39491	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	2081		LHS	Flash guards Switch box		6			
40927	INACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Cement Cable Troughing & Debris	Asbestos	Removed	2081	2083	LHS	Cement cable troughing. Troughing and Debris (rubble and waste thrown on top). Unable to quantify					
40928	INACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Cement Cable Troughing & Debris	Asbestos	Removed	2081	2083	LHS	Cement cable troughing		5			
40929	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	2084		LHS	Flash guards Switch box					
41007	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	2086		LHS	Flash guards Junction box		1			
41008	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	2087		LHS	Flash guards Switch box 109GR		1			
40000	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	2087		LHS	Flash guards Signal WL109		1			
41009	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	2090		LHS	Flash guards Switch box		1			
41010	ACTIVE	P	D212-P-EBLO	Road EBLO - PIC - South Ealing to Acton Town	Signal Boxes	Asbestos	Presumed	2094		LHS	Flash guards Switch box		1			
36333	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	10		LHS	Flash guards Signal break box		1			
36334	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Cable Sheath	Asbestos	Presumed	12	15	LHS	Braided cable. Switch box 18GR, AJTH, AJT, BJTH, BJT, 32GR		81			
36335	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	25		LHS	Flash guards Signal break box		1			
36336	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Cement Cable Troughing & Debris	Asbestos	Presumed	198		LHS	Asbestos Cement. Cement troughing		1			
36337	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	199		LHS	Flash guards Switch box		1			
36338	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	209		LHS	Flash guards Switch boxes		2			
36339	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	214		LHS	Flash guards Signal break box		1			
36340	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	250		LHS	Flash guards Signal break box		1			
36341	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	257		LHS	Flash guards Signal break box		1			



Hazardous Material Asset Register - Summary



D212-P - PIC Line - Acton Town to South Ealing

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36342	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	264		LHS	Flash guards Signal break box		1			
36343	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	266		LHS	Flash guards Signal break box		1			
36344	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	281		LHS	Flash guards Switch box JYTH & JYT		3			
36345	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	340	342	LHS	Flash guards Switch box		5			
36346	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	344		RHS	Flash guards Fog repeater A490		1			
36347	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	422		LHS	Flash guards Marshalling Kiosk		1			
36348	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	427		RHS	Flash guards Signal A490		1			
36349	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	798		RHS	Flash guards Signal R484		1			
39615	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	895		RHS	Flash guards Fog repeater A484		1			
36350	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1016		RHS	Flash guards Signal A484		1			
36351	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1427		RHS	Flash guards Signal RWRX480		1			
40208	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1569		LHS	Flash guards Signal RWRX480 & Fog repeater WRX480		2			
36352	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1681		LHS	Flash guards Signal WRX480 & RWR34AB		2			
36353	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1741		LHS	Flash guards Fog repeater WR34A		1			
36354	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1874		LHS	Flash guards Signal WR34A		1			
36355	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1937	1941	LHS	Flash guards Marshalling kiosk and Fog Repeater WR34B		3			
40209	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	2052	2057	LHS	Signal WR34B, RWR33A and Fog Repeater WR33A		6			
36356	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	2052	2057	LHS	Flash guards Marshalling Kiosk		3			
36358	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	2052	2063	LHS	Flash guards					



Hazardous Material Asset Register - Summary



D212-P - PIC Line - Acton Town to South Ealing

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36357	ACTIVE	P	D212-P-WBFA	Road WBFA - PIC - Acton Town to South Ealing	Cable Sheath	Asbestos	Presumed	2052	2063	LHS	Braided Cables. J Hanger 2 = 2 x 10mm cables along post route to over bridge and then onto LOCAL post route		2			
36359	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	8		LHS	Flash guards Signal and Rail Gap Indicator		2			
36360	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	35		LHS	Flash guards Switch box		1			
40210	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	36		LHS	Flash guards Transformer		1			
39370	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	46		LHS	Flash guards Signal break boxes		1			
36361	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Ducts	Asbestos	Sampled – Not Detected	49		LHS	Bitumen ducts to elephant trunking - NADIS					
36362	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	67		LHS	Flash guards Signal break boxes		1			
36363	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	68		LHS	Flash guards Signal break boxes		1			
36364	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	70	73	LHS	Flash guards Switch boxes 36FPGR, VTTR, AKTR, 20FPGR		4			
36365	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	75		LHS	Flash guards Fog repeater		1			
36366	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	76		LHS	Flash guards Signal break boxes		1			
36367	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	203		LHS	Flash guards Switch box		1			
36368	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	241	244	LHS	Flash guards Switch boxes 20GR, 20UECPR, AKT, AKTH, 36GR		5			
39371	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	246		LHS	Flash guards Signal break boxes		1			
36369	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	247		LHS	Flash guards Signal & Rail Gap Indicator		2			
39616	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	247		LHS	Flash guards Signal break boxes		1			
36371	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	250		LHS	Flash guards Signal break boxes		1			
36372	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	280		LHS	Flash guards Signal break boxes		1			
36373	INACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Removed	282		LHS	Flash guards Signal break boxes		1			



Hazardous Material Asset Register - Summary



D212-P - PIC Line - Acton Town to South Ealing

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36374	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	358	361	LHS	Flash guards Switch boxes AMTH, AMT, ASTH, BUTH, BUT, BVTH		6			
36375	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	369		LHS	Flash guards Signal break boxes		1			
36376	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	371		LHS	Flash guards Signal break boxes		1			
40211	INACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Removed	388		LHS	Flash guards Signal break boxes		1			
36377	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	389		LHS	Flash guards Signal break boxes		1			
36378	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	471		LHS	Flash guards Signal break boxes		1			
36379	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	551		RHS	Flash guards Switch box 2no		1			
36380	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	699		LHS	Flash guards Signal break boxes 2no		1			
40212	INACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Removed	781		LHS	Flash guards Signal break boxes		1			
36381	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	784		RHS	Flash guards Switch boxes		2			
36382	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	787		RHS	Flash guards Signal R464		1			
36383	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	800		LHS	Flash guards Signal break boxes		1			
39512	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	801		LHS	Flash guards Signal break boxes		1			
36384	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	815		RHS	Flash guards Switch boxes AVT		2			
40213	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	819		RHS	Flash guards Switch Boxes 490AT		2			
36385	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	829		LHS	Flash guards Marshalling Kiosk R464		1			
36386	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	831		LHS	Flash guards Marshalling Kiosk R484		1			
36387	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	873		LHS	Flash guards Switch Box to light		1			
36388	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	888		LHS	Flash guards Fog repeater and marshalling kiosk		2			



Hazardous Material Asset Register - Summary



D212-P - PIC Line - Acton Town to South Ealing

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36389	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	890		LHS	Flash guards Signal break boxes		1			
36390	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	891		LHS	Flash guards Marshalling kiosk		2			
36391	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	892		LHS	Flash guards Signal break boxes		1			
36392	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	893		LHS	Flash guards Signal break boxes		1			
39617	INACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Removed	899		LHS	Flash guards Signal break boxes		1			
36393	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1007		LHS	Flash guards Signal A464		2			
36394	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1008		LHS	Flash guards Signal break boxes		1			
36395	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1009		LHS	Flash guards Signal break boxes		1			
36397	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Cable Sheath	Asbestos	Presumed	1010		LHS	Braided cable. J hanger 3, 1 x 100m cable from MKA464		1			
36398	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Cable Sheath	Asbestos	Presumed	1012		LHS	Braided cable. 1 x 10mm cable from Signal break box to J hanger 3		1			
36400	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Cable Sheath	Asbestos	Presumed	1013		LHS	Braided cable. 9 x 10mm cables from kiosk A484 to J hanger 3		9			
36399	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1013		LHS	Flash guards Marshalling Kiosk A484		1			
36401	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1014		LHS	Flash guards Signal break boxes		1			
36402	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1015		LHS	Flash guards Switch box		1			
36403	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Cable Sheath	Asbestos	Presumed	1213		LHS	Braided cable. 7 x 10mm cables from J hanger 3 to boxes		7			
36405	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Cable Sheath	Asbestos	Presumed	1218		LHS	Braided cable. 1 x 10mm cable from signal break box to J hanger 3		1			
36404	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1218		LHS	Flash guards Signal break boxes		1			
39513	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1399		LHS	Flash guards Marshalling kiosk R460A		1			
40214	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1401		LHS	Flash guards Marshalling kiosk RWRX480		1			



Hazardous Material Asset Register - Summary



D212-P - PIC Line - Acton Town to South Ealing

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36406	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Cable Sheath	Asbestos	Presumed	1401		LHS	Braided cable. 1 x 10mm cable from J hanger 3 to kiosk. 1 x 10mm cable from kiosk to J hanger 3		21			
36408	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Cable Sheath	Asbestos	Presumed	1411		LHS	Braided cable. 2 x 10mm cables from J hanger 3 to box		2			
36409	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1415		LHS	Flash guards Signal R460 A on bridge D55		1			
36410	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Cable Sheath	Asbestos	Presumed	1415		LHS	Braided cable. 4 x10mm cables from box to bridge gantry to signals		4			
40215	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1416		LHS	Flash guards Signal break boxes		1			
36411	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Cable Sheath	Asbestos	Presumed	1416	1417	LHS	Braided cable. 3 x 10mm cables from J hanger 7 to Signal break box		1			
36412	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1417		LHS	Flash guards Signal break boxes		1			
36413	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1418		LHS	Flash guards Signal break boxes		1			
36279	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1555		LHS	Fog repeater A460A & Kiosk R460A		1			
39618	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1555		LHS	Flash guards Signal R460 A		1			
36280	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1558		LHS	Flash guards Marshalling kiosk RWRX480		1			
36281	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1559		LHS	Flash guards Signal break boxes		1			
36282	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1561		LHS	Flash guards Marshalling kiosk 480IND		1			
36283	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1564		LHS	Flash guards Marshalling kiosk 484B		1			
36284	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1567		LHS	Flash guards Signal break boxes		1			
36285	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1674		LHS	Flash guards Signal A460A, WRX460C & Kiosk A460		3			
36286	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1679		LHS	Flash guards Marshalling kiosk WRX480		1			
36289	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1688		LHS	Flash guards Signal break boxes		1			
36290	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1689		LHS	Flash guards Signal break boxes		1			



Hazardous Material Asset Register - Summary



D212-P - PIC Line - Acton Town to South Ealing

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36287	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1690		LHS	Flash guards Signal break boxes		1			
36288	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1694		LHS	Flash guards Signal break boxes		1			
36291	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1733		LHS	Flash guards Signal break boxes		1			
39510	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1735		LHS	Flash guards Fog repeater WRX460B, Kiosk FRWWX460		2			
36292	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1737		LHS	Flash guards Signal break boxes		1			
36293	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1738		LHS	Flash guards Signal break boxes		1			
36294	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1743		LHS	Flash guards Signal break boxes		1			
36295	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1745		LHS	Flash guards Signal break boxes		1			
36296	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1746		LHS	Flash guards Marshalling Kiosk FRWR34		1			
40203	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1748		LHS	Flash guards Marshalling Kiosk 464 D		1			
36297	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1787		LHS	Flash guards Signal break boxes		1			
36298	INACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Removed	1790		LHS	Flash guards Signal break boxes		1			
36299	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1839		LHS	Flash guards Signal break boxes		1			
36300	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1859		LHS	Flash guards Signal break boxes		1			
39613	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1863		LHS	Flash guards Signal WRX460B & Marshalling kiosk		2			
36301	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1870		LHS	Flash guards Signal break boxes		1			
36302	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1875		LHS	Flash guards Signal break boxes		1			
40204	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1876		LHS	Flash guards Signal break boxes		1			
36303	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1931		LHS	Flash guards Fog repeater A460C, Marshalling kiosk & switch box on wall		3			



Hazardous Material Asset Register - Summary



D212-P - PIC Line - Acton Town to South Ealing

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36304	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1933		LHS	Flash guards Marshalling kiosk 26		1			
36305	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1934	1936	LHS	Flash guards Switch box to wall		3			
40205	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Cable Sheath	Asbestos	Presumed	1936		LHS	Braided cable. 2 x 10mm cable from switch box on wall to J hanger 7		2			
36307	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Cable Sheath	Asbestos	Presumed	1937		LHS	Braided cable. 1 x 10mm cable from Marshalling kiosk 26/2 to J hanger 7		1			
36306	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1937		LHS	Marshalling kiosk 26/2 Flash guards		1			
36308	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1939		LHS	Flash guards Marshalling kiosk 27		1			
36309	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1941		LHS	Flash guards Signal break boxes		1			
36310	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1942		LHS	Flash guards Signal break boxes		1			
36311	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1954		LHS	Flash guards Signal break boxes		1			
36312	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1962		LHS	Flash guards Signal break boxes		1			
36313	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	1969		LHS	Flash guards Signal break boxes		1			
36314	INACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Removed	2002		LHS	Flash guards Signal break boxes		1			
39369	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	2054		LHS	Fog repeater A458 Flash guards		1			
39614	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	2054		LHS	Flash guards Signal break boxes		1			
36315	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Cable Sheath	Asbestos	Presumed	2054		LHS	Braided cable. 2 x 10mmm cables from fog repeater to J hanger 8		2			
36316	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	2055		LHS	Flash guards Signal A460C		1			
36319	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Cable Sheath	Asbestos	Presumed	2057		LHS	Braided cable. 5 x 10mm from J hanger 7 & 8 to cleat over OTX to Picc line (fast cable run under bridge into Marshalling kiosk 29 & 28.		1			
36317	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	2064		LHS	Flash guards Signal break boxes		1			
36318	ACTIVE	P	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	2068		LHS	Flash guards Signal break boxes		1			



Hazardous Material Asset Register - Summary



D212-P - PIC Line - Acton Town to South Ealing

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36320	ACTIVE	p	D212-P-WBLO	Road WBLO - PIC - Acton Town to South Ealing	Signal Boxes	Asbestos	Presumed	2074	2076	LHS	Marshalling kiosk 29 & 28 Flash guards		5			

D213-P - PIC Line - South Ealing Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39520	ACTIVE	p	D213-P-EBLO	Road EBLO (Plt1) - PIC - South Ealing Stn	Signal Boxes	Asbestos	Presumed	125			Flash guards Marshalling kiosk		1			

D214-P - PIC Line - South Ealing to Northfields

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38831	ACTIVE	p	D214-P-EBLO	Road EBLO - PIC - Northfields to South Ealing	Cable Wrap	Asbestos	Surveyed – Not Detected	0		LHS	Bitumen Cable wrapping J hanger 1 rear side					
38830	ACTIVE	p	D214-P-EBLO	Road EBLO - PIC - Northfields to South Ealing	Signal Boxes	Asbestos	Presumed	0		RHS	Flash guard Signal WR3		1			
40048	ACTIVE	p	D214-P-EBLO	Road EBLO - PIC - Northfields to South Ealing	Signal Boxes	Asbestos	Presumed	0		LHS	Flash guard Signal WR6		1			
38832	ACTIVE	p	D214-P-EBLO	Road EBLO - PIC - Northfields to South Ealing	Signal Boxes	Asbestos	Presumed	9		LHS	Flash guards Signal break box		1			
38833	ACTIVE	p	D214-P-EBLO	Road EBLO - PIC - Northfields to South Ealing	Signal Boxes	Asbestos	Presumed	10		LHS	Flash guards Signal break box		1			
39894	ACTIVE	p	D214-P-EBLO	Road EBLO - PIC - Northfields to South Ealing	Signal Boxes	Asbestos	Presumed	34		LHS	Flash guards Signal break box		1			
38834	ACTIVE	p	D214-P-EBLO	Road EBLO - PIC - Northfields to South Ealing	Signal Boxes	Asbestos	Presumed	39		LHS	Flash guards Signal break box		1			
38835	ACTIVE	p	D214-P-EBLO	Road EBLO - PIC - Northfields to South Ealing	Signal Boxes	Asbestos	Presumed	82		LHS	Flash guard Marshalling kiosk		1			
38836	ACTIVE	p	D214-P-EBLO	Road EBLO - PIC - Northfields to South Ealing	Signal Boxes	Asbestos	Presumed	88		LHS	Flash guard Marshalling kiosk		1			
38837	ACTIVE	p	D214-P-EBLO	Road EBLO - PIC - Northfields to South Ealing	Signal Boxes	Asbestos	Presumed	124		LHS	Flash guard Signal R455		1			
38838	ACTIVE	p	D214-P-EBLO	Road EBLO - PIC - Northfields to South Ealing	Signal Boxes	Asbestos	Presumed	124		LHS	Flash guard Fog repeater		1			
38839	ACTIVE	p	D214-P-EBLO	Road EBLO - PIC - Northfields to South Ealing	Signal Boxes	Asbestos	Presumed	126		RHS	Flash guard Signal R475		1			
38840	ACTIVE	p	D214-P-EBLO	Road EBLO - PIC - Northfields to South Ealing	Signal Boxes	Asbestos	Presumed	126		RHS	Flash guard Fog repeater A475		1			



Hazardous Material Asset Register - Summary



D214-P - PIC Line - South Ealing to Northfields

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38841	ACTIVE	p	D214-P-EBLO	Road EBLO - PIC - Northfields to South Ealing	Signal Boxes	Asbestos	Presumed	127		LHS	Flash guards Signal break box		1			
38842	ACTIVE	p	D214-P-EBLO	Road EBLO - PIC - Northfields to South Ealing	Signal Boxes	Asbestos	Presumed	131		LHS	Flash guards Signal break box		1			
38843	ACTIVE	p	D214-P-EBLO	Road EBLO - PIC - Northfields to South Ealing	Signal Boxes	Asbestos	Presumed	137		LHS	Flash guards Signal break box		1			
38844	ACTIVE	p	D214-P-EBLO	Road EBLO - PIC - Northfields to South Ealing	Signal Boxes	Asbestos	Presumed	141		LHS	Flash guards Signal break box		1			
38845	ACTIVE	p	D214-P-EBLO	Road EBLO - PIC - Northfields to South Ealing	Signal Boxes	Asbestos	Known	141	144	LHS	Flash guard Switch boxes x4 (EB fast iso trans, EB local iso trans_		4			
38846	ACTIVE	p	D214-P-EBLO	Road EBLO - PIC - Northfields to South Ealing	Signal Boxes	Asbestos	Presumed	181		LHS	Flash guard Signal break box		1			
38847	ACTIVE	p	D214-P-EBLO	Road EBLO - PIC - Northfields to South Ealing	Signal Boxes	Asbestos	Known	240	241	LHS	Flash guard Signals R457, A455 & fog repeater A457		3			
39895	ACTIVE	p	D214-P-EBLO	Road EBLO - PIC - Northfields to South Ealing	Signal Boxes	Asbestos	Known	240	241	LHS	Flash guard Signals R477, A477 & fog repeater A477 to signal stand D51A		3			
38848	ACTIVE	p	D214-P-EBLO	Road EBLO - PIC - Northfields to South Ealing	Signal Boxes	Asbestos	Presumed	243		LHS	Flash guards Signal break box		1			
38849	ACTIVE	p	D214-P-EBLO	Road EBLO - PIC - Northfields to South Ealing	Signal Boxes	Asbestos	Known	245	250	LHS	Flash guard Marshalling kiosk x3		3			
38850	ACTIVE	p	D214-P-EBLO	Road EBLO - PIC - Northfields to South Ealing	Signal Boxes	Asbestos	Presumed	251		LHS	Flash guards Signal break box		1			
38851	ACTIVE	p	D214-P-EBLO	Road EBLO - PIC - Northfields to South Ealing	Signal Boxes	Asbestos	Known	256		LHS	Flash guard Switch box 455 TPPR iso trans		1			
40049	ACTIVE	p	D214-P-EBLO	Road EBLO - PIC - Northfields to South Ealing	Signal Boxes	Asbestos	Known	258		LHS	Flash guard Marshalling kiosk Notes from 12022 re-inspection: And signal		1			
41016	ACTIVE	p	D214-P-WBFA	Road WBFA - PIC - South Ealing to Northfields	Signal Boxes	Asbestos	Presumed	1		RHS	Flash guard Fog repeater WR33B		1			
41015	ACTIVE	p	D214-P-WBFA	Road WBFA - PIC - South Ealing to Northfields	Signal Boxes	Asbestos	Presumed	1		RHS	Flash guard Signal WR33A		1			
39797	ACTIVE	p	D214-P-WBFA	Road WBFA - PIC - South Ealing to Northfields	Signal Boxes	Asbestos	Presumed	124		RHS	Flash guard Signal WR33B		1			
41013	ACTIVE	p	D214-P-WBLO	Road WBLO - PIC - South Ealing to Northfields	Cable Sheath	Asbestos	Presumed	1		LHS	Braided Cable. 1 x 10ml on j hanger 7 Braided cable		1			
41011	ACTIVE	p	D214-P-WBLO	Road WBLO - PIC - South Ealing to Northfields	Signal Boxes	Asbestos	Presumed	1		LHS	Flash guard Signal A458		1			
41012	ACTIVE	p	D214-P-WBLO	Road WBLO - PIC - South Ealing to Northfields	Signal Boxes	Asbestos	Presumed	1		LHS	Flash guard Fog repeater WR36		1			



Hazardous Material Asset Register - Summary



D214-P - PIC Line - South Ealing to Northfields

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41014	ACTIVE	p	D214-P-WBLO	Road WBLO - PIC - South Ealing to Northfields	Cable Wrap	Asbestos	Sampled – Not Detected	1		LHS	bitumen cable wrap on j hanger 2					
41017	ACTIVE	p	D214-P-WBLO	Road WBLO - PIC - South Ealing to Northfields	Signal Boxes	Asbestos	Presumed	2	13	LHS	Flash guard 4x Marshalling kiosk		4			
41018	ACTIVE	p	D214-P-WBLO	Road WBLO - PIC - South Ealing to Northfields	Ducts	Asbestos	Sampled – Not Detected	4		LHS	bitumen cable duct low level					
54028	ACTIVE	p	D214-P-WBLO	Road WBLO - PIC - South Ealing to Northfields	Other Electrical Boxes	Asbestos	Presumed	5		LHS	Flash guard Signal break box Notes from 2022 re-inspection: Added		1			
54029	ACTIVE	p	D214-P-WBLO	Road WBLO - PIC - South Ealing to Northfields	Other Electrical Boxes	Asbestos	Presumed	6		LHS	Flash guard signal break box		2			
41019	ACTIVE	p	D214-P-WBLO	Road WBLO - PIC - South Ealing to Northfields	Signal Boxes	Asbestos	Presumed	7		LHS	Flash guards Signal break box		1			
54030	ACTIVE	p	D214-P-WBLO	Road WBLO - PIC - South Ealing to Northfields	Other Electrical Boxes	Asbestos	Presumed	30		LHS	Flash guard signal break box		1			
54031	ACTIVE	p	D214-P-WBLO	Road WBLO - PIC - South Ealing to Northfields	Other Electrical Boxes	Asbestos	Presumed	35		LHS	Flash guard signal break box		1			
41020	ACTIVE	p	D214-P-WBLO	Road WBLO - PIC - South Ealing to Northfields	Signal Boxes	Asbestos	Presumed	68		LHS	Flash guards Signal break box		1			
41021	ACTIVE	p	D214-P-WBLO	Road WBLO - PIC - South Ealing to Northfields	Signal Boxes	Asbestos	Presumed	73		LHS	Flash guards Signal break box		1			
41022	ACTIVE	p	D214-P-WBLO	Road WBLO - PIC - South Ealing to Northfields	Signal Boxes	Asbestos	Presumed	76		LHS	Flash guards Signal break box		1			
41023	ACTIVE	p	D214-P-WBLO	Road WBLO - PIC - South Ealing to Northfields	Signal Boxes	Asbestos	Known	119	122	LHS	Flash guard 2x Marshalling kiosk		2			
39496	ACTIVE	p	D214-P-WBLO	Road WBLO - PIC - South Ealing to Northfields	Signal Boxes	Asbestos	Known	124		LHS	Flash guard Signal WR36		1			
41024	ACTIVE	p	D214-P-WBLO	Road WBLO - PIC - South Ealing to Northfields	Signal Boxes	Asbestos	Presumed	159		LHS	Flash guards Signal break box		1			
41025	ACTIVE	p	D214-P-WBLO	Road WBLO - PIC - South Ealing to Northfields	Signal Boxes	Asbestos	Presumed	162		LHS	Flash guards Signal break box		1			
54032	ACTIVE	p	D214-P-WBLO	Road WBLO - PIC - South Ealing to Northfields	Cable Sheath	Asbestos	Presumed	202		LHS	Braided cable		1			
41026	ACTIVE	p	D214-P-WBLO	Road WBLO - PIC - South Ealing to Northfields	Signal Boxes	Asbestos	Presumed	202		LHS	Flash guards Signal break box		4			
39519	ACTIVE	p	D214-P-WBLO	Road WBLO - PIC - South Ealing to Northfields	Signal Boxes	Asbestos	Presumed	220		LHS	Flash guards Switch box		1			
41027	ACTIVE	p	D214-P-WBLO	Road WBLO - PIC - South Ealing to Northfields	Signal Boxes	Asbestos	Presumed	241		LHS	Flash guards 2x Switch box		2			



Hazardous Material Asset Register - Summary



D214-P - PIC Line - South Ealing to Northfields

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41028	ACTIVE	p	D214-P-WBLO	Road WBLO - PIC - South Ealing to Northfields	Signal Boxes	Asbestos	Presumed	248	251	LHS	Flash guard 2x Marshalling kiosk		2			
41029	ACTIVE	p	D214-P-WBLO	Road WBLO - PIC - South Ealing to Northfields	Signal Boxes	Asbestos	Presumed	252		LHS	Flash guards Signal break box		1			
41030	ACTIVE	p	D214-P-WBLO	Road WBLO - PIC - South Ealing to Northfields	Signal Boxes	Asbestos	Presumed	253		LHS	Flash guards Signal break box		1			
54033	ACTIVE	p	D214-P-WBLO	Road WBLO - PIC - South Ealing to Northfields	Other Electrical Boxes	Asbestos	Presumed	254		RHS	Flash guard signal break box		1			

D215-P - PIC Line - Northfields Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38799	ACTIVE	p	D215-P-EBLO	Road EBLO (Pit4) - PIC - Northfields Stn	Signal Boxes	Asbestos	Presumed				Flashguards, Marshalling kiosk No 22& 23		2			

D216-P - PIC Line - Northfields to Boston Manor

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36905	ACTIVE	p	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	11		LHS	Flash guard Signal break box		1			
67610	ACTIVE	p	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	14			Flash guard Signal break box x1					
67611	ACTIVE	p	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	15			Flash guard Signal break box					
36906	ACTIVE	p	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	28		LHS	Flash guard Marshalling kiosk 14		1			
67612	ACTIVE	p	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	30			Flash guard Switch boxes					
36907	ACTIVE	p	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	89		LHS	Flash guard Switch boxes		1			
40401	ACTIVE	p	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	93		LHS	Flash guard Switch boxes		1			
36908	ACTIVE	p	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	104		LHS	Flash guard Fog repeater WR 1A		1			
67620	ACTIVE	p	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Other Electrical Boxes	Asbestos	Presumed	112			Flash guarding Marshalling Kiosk 14		1			
67621	ACTIVE	p	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	112			Flash guard signal box		1			



Hazardous Material Asset Register - Summary



D216-P - PIC Line - Northfields to Boston Manor

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36909	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	113		LHS	Flash guard Signal break box		1			
36910	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	114		LHS	Flash guard Marshalling kiosk		1			
36911	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	115		LHS	Flash guard Signal break box		1			
36912	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	119	121	LHS	Flash guard Marshalling kiosk 15/1 & 15/2 & signal RWR1A		3			
36913	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	226		LHS	Flash guard Signal WR1A & marshalling kiosk 16		2			
67622	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	240			Flash guard signal break box		1			
36914	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	335		LHS	Flash guard Signal break box		1			
36915	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	340		LHS	Flash guard Signal break box		1			
36916	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	495		LHS	Flash guard Signal RWR1B, marshalling kiosk 7 & fog repeater WR1B		3			
36917	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	509		LHS	Flash guard Signal break box		1			
39379	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	576		LHS	Flash guard Signal break box		1			
39664	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	579		LHS	Flash guard Signal break box		1			
36918	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	608		LHS	Flash guard Signal break box		1			
36919	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	610	612	LHS	Flash guard Signal WR1B, fog repeater WR1C & marshalling kiosk 18/1 & 18/2		3			
36920	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	615		LHS	Flash guard Signal break box		1			
36921	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	618		LHS	Flash guard Signal break box		1			
36922	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	710		LHS	Flash guard Signal break box		1			
36923	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	714		LHS	Flash guard Marshalling kiosk 19		1			
36924	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	715		LHS	Flash guard Rail gap indicator		1			



Hazardous Material Asset Register - Summary



D216-P - PIC Line - Northfields to Boston Manor

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36925	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	716		LHS	Flash guard Signal WR1C		1			
36926	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	718		LHS	Flash guard Switch box		1			
40402	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Removed	721		RHS	Switch box & rail gap indicator. adjacent to turning track between EB & WB		2			
36927	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Removed	729		RHS	Flash guard Disused switch box. between EB & turning track		1			
67623	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Other Electrical Boxes	Asbestos	Presumed	740			Flash guard Signal break box		1			
67624	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Other Electrical Boxes	Asbestos	Presumed	750			Flash guard Signal break box		1			
67625	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Other Electrical Boxes	Asbestos	Presumed	760			Flash guard Signal break box		1			
36928	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Ducts	Asbestos	Sampled – Not Detected	780		LHS	Bitumen ducts to elephant trunking					
36929	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	781		LHS	Flash guard Marshalling kiosk		1			
36930	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Cement Cable Troughing & Debris	Asbestos	Presumed	783		LHS	cement , debris to floor					
36931	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Cement Cable Troughing & Debris	Asbestos	Known	784		LHS	Cable troughing to UR box Cement		1			
39556	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	785		LHS	Flash guard Switch box		1			
40403	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Cement Cable Troughing & Debris	Asbestos	Presumed	786		LHS	Cement Troughing adjacent to track		1			
36932	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	787	789	LHS	Flash guard Switch boxes x 1 LWH		1			
36933	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	794		LHS	Flash guard Switch box		1			
36934	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Cement Cable Troughing & Debris	Asbestos	Known	825		LHS	Cement Troughing from post & under track		11			
36935	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	826	828	LHS	Flash guard Switch boxes x 1 LWH		1			
36936	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Cement Cable Troughing & Debris	Asbestos	Presumed	827		LHS	troughing to post		1			
39557	ACTIVE	P	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Removed	836		LHS	Flash guard Marshalling kiosk		1			



Hazardous Material Asset Register - Summary



D216-P - PIC Line - Northfields to Boston Manor

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36937	ACTIVE	p	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	862		LHS	Flash guard Signal break box		1			
36938	ACTIVE	p	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Cement Cable Troughing & Debris	Asbestos	Removed	866		RHS	cement debris to floor					
36939	ACTIVE	p	D216-P-EBLO	Road EBLO - PIC - Boston Manor to Northfields	Signal Boxes	Asbestos	Presumed	871	875	LHS	Flash guard Marshalling kiosk 20 & 21		1			
38800	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Cable Sheath	Asbestos	Presumed	0		LHS	Braided Cables. Front hanger: j hangers 1 -6=0, Rear hanger: j hangers 1 -3=0, j hanger 4= 4x10ml		4			
38801	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Signal Boxes	Asbestos	Presumed	4		LHS	Flash guard Rail gap indicator		1			
38802	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Signal Boxes	Asbestos	Presumed	5		LHS	Flash guard Rail gap indicator		1			
38803	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Cable Sheath	Asbestos	Presumed	5		LHS	Braided Cables. J hangers 1 -4 & 6=0, j hanger 5 - 4x10ml		4			
54004	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Other Electrical Boxes	Asbestos	Presumed	5	12	LHS	Flash guard signal break box Notes from 2022 re-inspection: Added 2022 RI		6			
38804	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Cable Sheath	Asbestos	Presumed	10		LHS	Braided Cables. Cables onto j hanger 3		4			
54005	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Other Electrical Boxes	Asbestos	Presumed	11		LHS	Flash guard signal break box Notes from 2022 re-inspection: Added 2022 RI		2			
54006	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Other Electrical Boxes	Asbestos	Presumed	12		LHS	Flash guard switch box Notes from 2022 re-inspection: Added 2022 RI		1			
40046	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Cement Cable Troughing & Debris	Asbestos	Removed	17		LHS	Cement. Troughing running from local to fast Notes from 2022 re-inspection: Removed		8			
38805	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Signal Boxes	Asbestos	Presumed	19		LHS	Flash guard Switch box		1			
38807	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Cable Sheath	Asbestos	Presumed	22		LHS	Braided Cables. Cable from box onto j hanger 3 & 3 cables to kiosk 35 – 2 out of kiosk up to j hanger 3		5			
38806	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Signal Boxes	Asbestos	Presumed	22	25	LHS	Flash guard Marshalling kiosks 35 & 36		2			
54007	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Other Electrical Boxes	Asbestos	Presumed	24			Flash guard signal break box Notes from 2022 re-inspection: Added 2022 RI		1	LHS		
54008	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Other Electrical Boxes	Asbestos	Presumed	26		LHS	Flash guard marshalling kiosks Notes from 2022 re-inspection: Added 2022 RI		1			



Hazardous Material Asset Register - Summary



D216-P - PIC Line - Northfields to Boston Manor

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38808	ACTIVE	P	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Signal Boxes	Asbestos	Known	47		LHS	Flash guard Switch box		1			
54009	ACTIVE	P	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Other Electrical Boxes	Asbestos	Presumed	50		LHS	Flash guard signal break box Notes from 2022 re-inspection: Added 2022 RI		1			
54010	ACTIVE	P	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Other Electrical Boxes	Asbestos	Presumed	70			Flash guard signal break box Notes from 2022 re-inspection: Added 2022 RI		2	LHS		
38809	ACTIVE	P	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Ducts	Asbestos	Sampled – Not Detected	71		LHS	ducts to elephant trunking					
38810	ACTIVE	P	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Ducts	Asbestos	Sampled – Not Detected	111		LHS	ducts to elephant trunking					
38811	ACTIVE	P	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Cable Sheath	Asbestos	Sampled – Not Detected	146		LHS	cable wrap					
39893	ACTIVE	P	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Signal Boxes	Asbestos	Presumed	204		LHS	Flash guard Signal RSX452 & fog repeater WSX452		2			
54011	ACTIVE	P	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Other Electrical Boxes	Asbestos	Presumed	210		LHS	Flash guard signal break box Notes from 2022 re-inspection: Added 2022 RI		1			
54012	ACTIVE	P	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Other Electrical Boxes	Asbestos	Presumed	212		LHS	Flash guard signal break box Notes from 2022 re-inspection: Added 2022 RI		1			
54013	ACTIVE	P	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Other Electrical Boxes	Asbestos	Presumed	280		LHS	Flash guard signal break box Notes from 2022 re-inspection: Added 2022 RI		1			
38812	ACTIVE	P	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Signal Boxes	Asbestos	Presumed	322		LHS	Flash guard Switch box		1			
38813	ACTIVE	P	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Signal Boxes	Asbestos	Known	323		LHS	Flash guard Signal WSX452		1			
38814	ACTIVE	P	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Signal Boxes	Asbestos	Presumed	324		LHS	Flash guard Marshalling kiosk 38		1			
38815	ACTIVE	P	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Signal Boxes	Asbestos	Presumed	331		LHS	Flash guards Signal break box		1			
38816	ACTIVE	P	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Signal Boxes	Asbestos	Presumed	333		LHS	Flash guards Signal break box		1			
54014	ACTIVE	P	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Other Electrical Boxes	Asbestos	Presumed	386		LHS	Flash guard signal break box Notes from 2022 re-inspection: Added 2022 RI		1			
38817	ACTIVE	P	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Signal Boxes	Asbestos	Presumed	474		LHS	Flash guard Signal RWS12A & marshalling kiosk 39		2			



Hazardous Material Asset Register - Summary



D216-P - PIC Line - Northfields to Boston Manor

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38818	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Signal Boxes	Asbestos	Presumed	478		LHS	Flash guards Signal break box		1			
38819	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Signal Boxes	Asbestos	Presumed	480		LHS	Flash guards Signal break box		1			
38820	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Signal Boxes	Asbestos	Presumed	573		LHS	Flash guard Fog repeater W512A & marshalling kiosk 40		2			
38821	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Signal Boxes	Asbestos	Presumed	595		LHS	Cement. Troughing debris under cable run					
38822	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Signal Boxes	Asbestos	Presumed	604		LHS	Flash guards Signal break box		1			
38823	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Signal Boxes	Asbestos	Presumed	608		LHS	Flash guards Signal break box		1			
54015	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Other Electrical Boxes	Asbestos	Presumed	609		LHS	Flash guard signal break box Notes from 2022 re-inspection: Added 2022 RI		1			
39682	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Signal Boxes	Asbestos	Presumed	685		LHS	Flash guard Signal WS12A & marshalling kiosk 41		2			
38824	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Signal Boxes	Asbestos	Presumed	695		LHS	Flash guards Signal break box		1			
38825	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Signal Boxes	Asbestos	Presumed	699		LHS	Flash guards Signal break box		1			
40047	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Signal Boxes	Asbestos	Presumed	726		LHS	Flash guard Signal RWS12B/4, fog repeater WS12B & marshalling kiosk 42		3			
54016	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Other Electrical Boxes	Asbestos	Presumed	770		LHS	Flash guard signal break box		1			
38826	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Signal Boxes	Asbestos	Presumed	837		LHS	Flash guard Marshalling kiosk		1			
38827	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Signal Boxes	Asbestos	Presumed	844		LHS	Flash guard Signal WS12B & marshalling kiosk 43		2			
54017	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Other Electrical Boxes	Asbestos	Presumed	845			Flash guard signal break box Notes from 2022 re-inspection: Added 2022 RI		1	LHS		
38829	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Signal Boxes	Asbestos	Presumed	868		LHS	Flash guards Signal break box		1			
38828	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Signal Boxes	Asbestos	Presumed	896		LHS	Flash guards Signal break box		1			
54018	ACTIVE	p	D216-P-WBLO	Road WBLO - PIC - Northfields to Boston Manor	Other Electrical Boxes	Asbestos	Presumed	898		LHS	Flash guard signal break box Notes from 2022 re-inspection: Added 2022 RI		1			



Hazardous Material Asset Register - Summary



D218-P - PIC Line - Boston Manor to Osterley

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39024	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	9		LHS	Flash guard Signal A42 9		1			
39025	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Ducts	Asbestos	Sampled – Not Detected	18		LHS	Bitumen, Ducts to elephant trunking		4			
39026	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Cable Wrap	Asbestos	Sampled – Not Detected	18		LHS	Bitumen Cable wrap to rear of J hanger 3&4 to elephant trunking					
39027	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	22		LHS	Flash guard Signal break box		1			
39028	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	24		LHS	Flash guard Marshalling kiosk		1			
39029	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	26		LHS	Flash guard Signal break box		1			
39030	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	201		LHS	Flash guard Signal break box		1			
39031	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	204		LHS	Flash guard Signal break box		1			
39032	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Ducts	Asbestos	Sampled – Not Detected	244		LHS	bitumen ducts		4			
39033	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	516		LHS	Flash guard Signal break box		1			
39034	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	517		LHS	Flash guard Marshalling kiosk Notes from 2022 re-inspection: 1 no		1			
39035	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	518		LHS	Flash guard Signal break box		1			
39036	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	605		LHS	Flash guard Marshalling kiosk		1			
39037	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	605		LHS	Flash guard Signal RWSX433(1)		1			
40066	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	607		LHS	Switch boxes		1			
39038	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	610		LHS	Switch boxes		1			
39906	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	613		LHS	Flash guard Signal break box		1			
39039	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	614		LHS	Flash guard Signal break box		1			
39040	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	653		LHS	Flash guard Fog repeater WSX433		1			



Hazardous Material Asset Register - Summary



D218-P - PIC Line - Boston Manor to Osterley

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40067	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	696		LHS	Flash guard Switch boxes		2			
39041	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	699		LHS	Flash guard Marshalling kiosk		1			
39042	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	699		LHS	Flash guard Signal RWSX433(2)		1			
39043	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	707		LHS	Flash guard Signal break box		1			
39044	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	710		LHS	Flash guard Signal break box		1			
39045	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	781		LHS	Flash guard Marshalling kiosk		1			
40068	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	781		LHS	Flash guard Signal WSX433		1			
54078	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	805		LHS	Flash guard signal break box		2			
54079	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	980		LHS	Flash guard signal break box		1			
39046	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1189		LHS	Flash guard Fog repeater		1			
39047	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1193		LHS	Flash guard Signal break box		1			
39048	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1201		LHS	Flash guard Signal break box		1			
39049	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1203		LHS	Flash guard Signal break box		1			
39050	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1308		LHS	Flash guard Signal WS1A		1			
40069	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1308		LHS	Flash guard Marshalling kiosk		1			
39690	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1323		LHS	Flash guard Signal break box		1			
39051	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1324		LHS	Flash guard Signal break box		1			
39053	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1400		LHS	Flash guard Signal RWS1B(1)		1			
39052	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1400		LHS	Flash guard Marshalling kiosk		1			



Hazardous Material Asset Register - Summary



D218-P - PIC Line - Boston Manor to Osterley

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39054	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1404		LHS	Flash guard Signal break box		1			
39055	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1407		LHS	Flash guard Signal break box		1			
39057	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1499		LHS	Flash guard Signal RWS1B(2)		1			
39056	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1499		LHS	Flash guard Marshalling kiosk		1			
39058	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1514		LHS	Flash guard Signal break box		1			
39059	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1515		LHS	Flash guard Signal break box		1			
54080	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1590			Flash guard signal break box		1	LHS		
39060	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Ducts	Asbestos	Sampled – Not Detected	1626		LHS	bitumen ducts		3			
39061	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1663		LHS	Flash guard Fog repeater & marshalling kiosk		1			
39062	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1675		LHS	Flash guard Signal break box		1			
39063	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1676		LHS	Flash guard Signal break box		1			
39064	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1782		LHS	Flash guard Marshalling kiosk & signal WS1B		1			
39065	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1786		LHS	Flash guard Signal break box		1			
39066	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1789		LHS	Flash guard Signal break box		1			
39067	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1861		LHS	Flash guard Marshalling kiosk		1			
39068	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1868		LHS	Flash guard Signal RW53A441		1			
39907	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1954		LHS	Flash guard Fog repeater		1			
40070	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1986		LHS	Flash guard Signal break box		1			
39069	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1987		LHS	Flash guard Marshalling kiosk		1			



Hazardous Material Asset Register - Summary



D218-P - PIC Line - Boston Manor to Osterley

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
54081	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1988		LHS	Flash guard switch boxes		1			
39070	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	1990		LHS	Flash guard Signal break box		1			
39071	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Cement Cable Troughing & Debris	Asbestos	Presumed	2026		LHS	cement troughing debris		1			
39072	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	2049		LHS	Flash guard Marshalling kiosk		1			
39076	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	2060		LHS	Switch box Flash guard Notes from 2022 re-inspection: Flash guard signal break box		1			
39340	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	2071		LHS	Flash guard Signal WS3B		1			
39074	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	2072		LHS	Flash guard Signals WS3A & R441WRX443		2			
39075	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	2072		LHS	Flash guard Rail gap indicator		1			
39073	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	2072		LHS	Flash guard Signal break box		1			
39077	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Removed	2076		LHS	Flash guard Signal break box Notes from 2022 re-inspection: Removed		1			
39341	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Cable Sheath	Asbestos	Presumed	2153		LHS	Braided Cable. 1x braided cable from switch box to j hanger 3 heading into box on BRS 2154					
39078	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Cable Sheath	Asbestos	Presumed	2154		LHS	Braided Cable. 5 x 10ml from power box to j hangers 3 & 4		5			
39079	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Cable Sheath	Asbestos	Presumed	2156		LHS	Braided Cable. 2x 10ml from box to j hanger 3 J hangers 1 & 2=0, j hanger 3=4, j hanger4=3		2			
39080	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	2162		LHS	Flash guard Marshalling kiosk & fog repeater		2			
39082	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Cable Sheath	Asbestos	Presumed	2163		LHS	Braided Cable. 1 x10ml from j hanger 4 to marsh alling kiosk		1			
39081	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	2163		LHS	Flash guard Signal break box		1			
39083	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Cable Sheath	Asbestos	Presumed	2169		LHS	Braided Cable. 7 x 10ml from box to j hanger 3					
39084	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	2173		LHS	Flash guard Switch box		1			
39691	ACTIVE	P	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Cable Sheath	Asbestos	Presumed	2173		LHS	Braided Cable. 2x 10 ml from j hanger 3 to switch box & 2x 10ml box to j hanger 3		4			



Hazardous Material Asset Register - Summary



D218-P - PIC Line - Boston Manor to Osterley

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39085	ACTIVE	p	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	2178		LHS	Flash guard Switch box		1			
39086	ACTIVE	p	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	2181		LHS	Flash guard Switch box		1			
39087	ACTIVE	p	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Cable Sheath	Asbestos	Presumed	2181		LHS	Braided Cable. 2x 10ml from j hanger 3 to switch box & 2x 10ml from box to j hanger 3		4			
39089	ACTIVE	p	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Cable Sheath	Asbestos	Presumed	2183		LHS	Braided Cable. 3x 10ml heading onto j hanger 3 (2 heading WB & 1 heading EB)		3			
39088	ACTIVE	p	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	2183		LHS	Flash guard Switch box		1			
54082	ACTIVE	p	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	2194		LHS	Flash guard signal break box		1			
39090	ACTIVE	p	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Cable Sheath	Asbestos	Presumed	2197		LHS	Braided Cable. 4x 10ml from j hanger 3 into switch box		4			
39091	ACTIVE	p	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Cable Sheath	Asbestos	Presumed	2198		LHS	Braided Cable. 8x 10ml from j hangers 3 & 4 into box		8			
54083	ACTIVE	p	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	2199		LHS	Flash guard signal break box		1			
39092	ACTIVE	p	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	2292		LHS	Flash guard Signal A441		1			
39093	ACTIVE	p	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	2295		LHS	Flash guard Signal break box		1			
39094	ACTIVE	p	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	2297		LHS	Flash guard Signal break box		1			
39095	ACTIVE	p	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	2299		LHS	Flash guard Marshalling kiosk		1			
39096	ACTIVE	p	D218-P-EBLO	Road EBLO - PIC - Osterley to Boston Manor	Signal Boxes	Asbestos	Presumed	2308		LHS	Flash guard Signal break box Notes from 2022 re-inspection: And 10 core box		1			
46151	ACTIVE	p	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	8		LHS	Flash guard Signal WS11		1			
36940	ACTIVE	p	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	116		LHS	Flash guard Switch box		1			
36941	ACTIVE	p	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	120		LHS	Flash guard Switch box		1			
36942	ACTIVE	p	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	130		LHS	Flash guard Marshalling kiosk		1			
36943	ACTIVE	p	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	202		LHS	Flash guard Signal break boxes		1			



Hazardous Material Asset Register - Summary



D218-P - PIC Line - Boston Manor to Osterley

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36944	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	203			Rail gap indicator Flash guard		1			
36945	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	208		LHS	Flash guard Signal break boxes		1			
36946	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	213		LHS	Flash guard Marshalling kiosk		1			
36947	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	215		LHS	Flash guards on Switch box		35			
36948	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	221		LHS	Flash guard Signal break boxes		1			
36949	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	248		LHS	Flash guard Signal break boxes		1			
36950	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	250		LHS	Flash guard Signal break boxes		1			
36951	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	625		LHS	Flash guard Signal break boxes		1			
36952	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	684		LHS	Flash guard Fog repeater 442		1			
36953	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	711		LHS	Flash guard Signal R442		1			
39665	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	711		LHS	Flash guard Marshalling kiosk 48		1			
36954	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	713		LHS	Flash guard Signal break boxes		1			
40404	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	715		LHS	Flash guard Signal break boxes		1			
36955	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	718		LHS	Flash guard Signal break boxes		1			
36956	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	726		LHS	Flash guard Switch boxes		1			
36957	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	729		LHS	Flash guard Switch boxes		1			
36958	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	811		LHS	Flash guard Signal A442		1			
36959	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	811		LHS	Flash guard Marshalling kiosk		1			
40405	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	821		LHS	Flash guard Signal break boxes		1			



Hazardous Material Asset Register - Summary



D218-P - PIC Line - Boston Manor to Osterley

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36960	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	825		LHS	Flash guard Signal break boxes		1			
36961	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	1353		LHS	Flash guard Marshalling kiosk W/ 442A		1			
36962	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	1357		LHS	Flash guard Signal break boxes		1			
36963	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	1658		LHS	Flash guard Signal R432A		1			
36964	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	1700		LHS	Flash guard Marshalling kiosk		1			
40406	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	1700		LHS	Flash guard Fog repeater A432A		1			
39666	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	1703		LHS	Flash guard Signal break boxes		1			
36965	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	1706		LHS	Flash guard Signal break boxes		1			
36966	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	1819		LHS	Flash guard Signal A432A		1			
36967	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	1819		LHS	Flash guard Marshalling kiosk A432A		1			
36968	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	1860		LHS	Flash guard Signal break boxes		1			
36969	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	1864		LHS	Flash guard Signal break boxes		1			
36970	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	2026		LHS	Flash guard Marshalling kiosk FR 4326		1			
36971	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	2062		LHS	Flash guard Signal R432B		1			
36972	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	2062		LHS	Flash guard Fog repeater		1			
36973	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Ducts	Asbestos	Sampled – Not Detected	2085		LHS	bitumen ducts. Disused platform		4			
36974	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	2178		LHS	Flash guard Signal A432B		1			
36975	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	2217		LHS	Flash guard Marshalling kiosk 442E/ 432A		1			
36976	ACTIVE	P	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	2241		LHS	Flash guard Signal break boxes		1			



Hazardous Material Asset Register - Summary



D218-P - PIC Line - Boston Manor to Osterley

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36977	ACTIVE	p	D218-P-WBLO	Road WBLO - PIC - Boston Manor to Osterley	Signal Boxes	Asbestos	Presumed	2302		LHS	Flash guard Marshalling kiosk		1			

D222-P - PIC Line - Osterley to Hounslow East

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37964	ACTIVE	p	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Signal Boxes	Asbestos	Presumed	3		LHS	Flash guards Switch Box		2			
37965	ACTIVE	p	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Signal Boxes	Asbestos	Presumed	6		LHS	Flash guards Marshalling kiosk		1			
37966	ACTIVE	p	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Signal Boxes	Asbestos	Presumed	8		LHS	Flash guards Signal A425		1			
37967	ACTIVE	p	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Signal Boxes	Asbestos	Presumed	13		LHS	Flash guards Signal break box		1			
37968	ACTIVE	p	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Signal Boxes	Asbestos	Presumed	17		LHS	Flash guards Rail Gap Indicator		1			
39887	ACTIVE	p	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Signal Boxes	Asbestos	Presumed	17		LHS	Flash guards Signal break box		1			
37969	ACTIVE	p	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Signal Boxes	Asbestos	Presumed	19		LHS	Flash guards Signal break box		1			
39632	ACTIVE	p	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Signal Boxes	Asbestos	Presumed	26		LHS	Flash guards Switch Box		1			
37970	ACTIVE	p	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Signal Boxes	Asbestos	Presumed	33		LHS	Flash guards Marshalling kiosk		1			
39888	ACTIVE	p	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Ducts	Asbestos	Sampled – Not Detected	45		LHS	ducts to elephant trunking					
37971	ACTIVE	p	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Ducts	Asbestos	Sampled – Not Detected	49		LHS	ducts to elephant trunking					
37972	ACTIVE	p	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Signal Boxes	Asbestos	Presumed	76		LHS	Flash guards Switch Boxes		2			
37973	ACTIVE	p	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Signal Boxes	Asbestos	Presumed	210		LHS	Flash guards Marshalling kiosk, Fog repeater & signal R427 A		3			
37974	ACTIVE	p	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Signal Boxes	Asbestos	Presumed	218		LHS	Flash guards Signal break box		1			
39912	ACTIVE	p	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Signal Boxes	Asbestos	Presumed	219		LHS	Flash guards Signal break box		1			
37975	ACTIVE	p	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Ducts	Asbestos	Sampled – Not Detected	261		LHS	Bitumen ducts to elephant trunking					



Hazardous Material Asset Register - Summary



D222-P - PIC Line - Osterley to Hounslow East

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37976	ACTIVE	P	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Ducts	Asbestos	Sampled – Not Detected	306		LHS	Bitumen ducts to elephant trunking					
37977	ACTIVE	P	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Signal Boxes	Asbestos	Presumed	327		LHS	Flash guards Marshalling kiosk & signal A427A		2			
38184	ACTIVE	P	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Signal Boxes	Asbestos	Presumed	334		LHS	Flash guards Signal break box		1			
38185	ACTIVE	P	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Signal Boxes	Asbestos	Presumed	339		LHS	Flash guards Signal break box		1			
54066	ACTIVE	P	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Other Electrical Boxes	Asbestos	Presumed	558		LHS	Flash guards Marshalling kiosk, rail gap indicator & signal R427AB Notes from 2022 re-inspection: Assets added 2022 as not on initial survey		3			
38186	ACTIVE	P	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Signal Boxes	Asbestos	Presumed	576		LHS	Flash guards Signal break box		1			
38187	ACTIVE	P	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Signal Boxes	Asbestos	Presumed	580		LHS	Flash guards Signal break box		1			
38188	ACTIVE	P	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Cable Sheath	Asbestos	Removed	585		LHS	Cement debris, Debris under and behind post route (unable to quantify) Notes from 2022 re-inspection: Not present during 2022 reinspection					
54067	ACTIVE	P	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Other Electrical Boxes	Asbestos	Presumed	665		LHS	Flash guards Marshalling kiosk & signal A427B		2			
38189	ACTIVE	P	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Signal Boxes	Asbestos	Presumed	676		LHS	Flash guards Signal break box		1			
38190	ACTIVE	P	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Signal Boxes	Asbestos	Presumed	680		LHS	Flash guards Signal break box		1			
38191	ACTIVE	P	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Signal Boxes	Asbestos	Removed	826		LHS	Flash guards Marshalling kiosk, Fog repeater & signal r427b Notes from 2022 re-inspection: Removed		3			
38192	ACTIVE	P	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Signal Boxes	Asbestos	Removed	827		LHS	Flash guards Marshalling kiosk & signal A427B Notes from 2022 re-inspection: Removed		1			
38193	ACTIVE	P	D222-P-EBLO	Road EBLO - PIC - Hounslow East to Osterley	Signal Boxes	Asbestos	Presumed	827		LHS	Flash guards Marshalling kiosk					
39097	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	3		LHS	Flash guards Signal A430		1			
39098	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	4		LHS	Flash guards Switch box		1			



Hazardous Material Asset Register - Summary



D222-P - PIC Line - Osterley to Hounslow East

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39908	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	28		LHS	Flash guard Signal break box		1			
39342	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	30		LHS	Flash guard Marshalling kiosk		1			
39099	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	34		LHS	Flash guard Signal break box		1			
39101	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	221		LHS	Fog repeater WTX424		1			
39102	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	221		LHS	signal RWTX424A		1			
39100	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	221		LHS	Flash guard Marshalling kiosk		1			
39343	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	225		LHS	Flash guard Signal break box		1			
39103	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	229		LHS	Flash guard Signal break box		1			
39104	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	341		LHS	Flash guards Marshalling kiosk & signal WTX424A		2			
39105	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	350		LHS	Flash guard Signal break box		1			
39106	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	353		LHS	Flash guard Signal break box		1			
54041	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Other Electrical Boxes	Asbestos	Presumed	406		LHS	Flash guards signal break box 1x		1			
39344	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	476		LHS	Flash guard Signal break box		1			
39107	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	479		LHS	Flash guard Marshalling kiosk		1			
39108	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	482		LHS	Flash guard Signal break box		1			
39109	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	585		LHS	Flash guards Marshalling kiosk, Fog repeater A424b & R424b		1			
39110	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	608		LHS	Flash guard Signal break box		1			
39111	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	627		LHS	Flash guard Signal break box		1			
39112	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	633		LHS	Flash guard Signal break box		1			



Hazardous Material Asset Register - Summary



D222-P - PIC Line - Osterley to Hounslow East

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39113	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	706		LHS	Flash guards Marshalling kiosk & signal A424A		2			
39114	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	714		LHS	Flash guard Signal break box		1			
39115	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	720		LHS	Flash guard Signal break box		1			
39116	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	773		LHS	Flash guards Switch box Notes from 2022 re-inspection: 1x LWH only		1			
39117	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	804		LHS	Flash guards Switch box		1			
39118	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	813		LHS	Flash guards Switch box		1			
39119	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	817	819	LHS	Flash guards Switch box		3			
39120	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	822		LHS	Flash guard Signal break box		1			
39121	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	823		LHS	Flash guard Signal break box		1			
39909	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	823		LHS	Flash guards Rail Gap Indicator		1			
39122	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	826		LHS	Flash guards Switch box		1			
39123	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Cement Cable Troughing & Debris	Asbestos	Known	827		LHS	Asbestos Cement. Cement debris, Small amounts					
39124	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Cement Cable Troughing & Debris	Asbestos	Known	827		LHS	Asbestos Cement. Cement troughing, Cement troughing from post Adj. to switch box along floor heading to track on BRS 830		6			
39345	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Cement Cable Troughing & Debris	Asbestos	Known	829		LHS	Asbestos Cement. Cement debris, Cement debris behind post route		6			
39460	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	829		LHS	Flash guard Signal break box		1			
39125	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	830		LHS	Flash guard Marshalling kiosk		1			
39126	ACTIVE	P	D222-P-WBLO	Road WBLO - PIC - Osterley to Hounslow East	Signal Boxes	Asbestos	Presumed	833		LHS	Flash guard Signal break box		1			



Hazardous Material Asset Register - Summary



D224-P - PIC Line - Hounslow East to Hounslow Central

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38137	ACTIVE	P	D224-P-EBLO	Road EBLO - PIC - Hounslow Central to Hounslow East	Signal Boxes	Asbestos	Presumed	0		LHS	Flash guards Signal WT2		1			
38138	ACTIVE	P	D224-P-EBLO	Road EBLO - PIC - Hounslow Central to Hounslow East	Signal Boxes	Asbestos	Presumed	6		LHS	Flash guards Signal break box		1			
38139	ACTIVE	P	D224-P-EBLO	Road EBLO - PIC - Hounslow Central to Hounslow East	Signal Boxes	Asbestos	Presumed	11		LHS	Flash guards Signal break box		1			
38140	ACTIVE	P	D224-P-EBLO	Road EBLO - PIC - Hounslow Central to Hounslow East	Signal Boxes	Asbestos	Presumed	14		LHS	Flash guards Signal break box		1			
38141	ACTIVE	P	D224-P-EBLO	Road EBLO - PIC - Hounslow Central to Hounslow East	Signal Boxes	Asbestos	Presumed	22		LHS	Flash guards Switch Box		2			
38142	ACTIVE	P	D224-P-EBLO	Road EBLO - PIC - Hounslow Central to Hounslow East	Signal Boxes	Asbestos	Presumed	64		LHS	Flash guards Switch Box		1			
38143	ACTIVE	P	D224-P-EBLO	Road EBLO - PIC - Hounslow Central to Hounslow East	Signal Boxes	Asbestos	Presumed	68		LHS	Flash guards Switch Box		1			
38144	ACTIVE	P	D224-P-EBLO	Road EBLO - PIC - Hounslow Central to Hounslow East	Signal Boxes	Asbestos	Presumed	151		LHS	Flash guards Signal R421 Band Fog repeater A421A		2			
38145	ACTIVE	P	D224-P-EBLO	Road EBLO - PIC - Hounslow Central to Hounslow East	Signal Boxes	Asbestos	Presumed	158		LHS	Flash guards Signal break box		1			
38146	ACTIVE	P	D224-P-EBLO	Road EBLO - PIC - Hounslow Central to Hounslow East	Signal Boxes	Asbestos	Presumed	162		LHS	Flash guards Signal break box		1			
38147	ACTIVE	P	D224-P-EBLO	Road EBLO - PIC - Hounslow Central to Hounslow East	Signal Boxes	Asbestos	Presumed	267		LHS	Cement debris Switch box 412AVR		1			
38148	ACTIVE	P	D224-P-EBLO	Road EBLO - PIC - Hounslow Central to Hounslow East	Signal Boxes	Asbestos	Presumed	270		LHS	Flash guards Signal A421A		1			
38149	ACTIVE	P	D224-P-EBLO	Road EBLO - PIC - Hounslow Central to Hounslow East	Signal Boxes	Asbestos	Presumed	301		LHS	Flash guards Signal break box		1			
39924	ACTIVE	P	D224-P-EBLO	Road EBLO - PIC - Hounslow Central to Hounslow East	Signal Boxes	Asbestos	Presumed	306		LHS	Flash guards Signal break box		1			
38150	ACTIVE	P	D224-P-EBLO	Road EBLO - PIC - Hounslow Central to Hounslow East	Signal Boxes	Asbestos	Presumed	467		LHS	Flash guards Signal R421B AND Fog repeater A421 B		2			
39826	ACTIVE	P	D224-P-EBLO	Road EBLO - PIC - Hounslow Central to Hounslow East	Signal Boxes	Asbestos	Presumed	490		LHS	Flash guards Signal break box		1			
38151	ACTIVE	P	D224-P-EBLO	Road EBLO - PIC - Hounslow Central to Hounslow East	Signal Boxes	Asbestos	Presumed	493		LHS	Flash guards Signal break box		1			
54045	ACTIVE	P	D224-P-EBLO	Road EBLO - PIC - Hounslow Central to Hounslow East	Other Electrical Boxes	Asbestos	Presumed	580			Flash guards Switch box 1x		1	LHS		
38152	ACTIVE	P	D224-P-EBLO	Road EBLO - PIC - Hounslow Central to Hounslow East	Signal Boxes	Asbestos	Presumed	582		LHS	Flash guards Signal break box		1			



Hazardous Material Asset Register - Summary



D224-P - PIC Line - Hounslow East to Hounslow Central

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38153	ACTIVE	p	D224-P-EBLO	Road EBLO - PIC - Hounslow Central to Hounslow East	Signal Boxes	Asbestos	Presumed	583		LHS	Flash guards Signal break box		1			
39925	ACTIVE	p	D224-P-EBLO	Road EBLO - PIC - Hounslow Central to Hounslow East	Signal Boxes	Asbestos	Presumed	614		LHS	Flash guards Signal A421B		1			
38154	ACTIVE	p	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Signal Boxes	Asbestos	Presumed	0		LHS	Flash guards Signal WT12A		1			
54058	ACTIVE	p	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Other Electrical Boxes	Asbestos	Presumed	32		LHS	Flashguards signal break box Notes from 2022 re-inspection: Added 2022 as missed		1			
54059	ACTIVE	p	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Other Electrical Boxes	Asbestos	Presumed	36		LHS	Flash guards Signal break box Notes from 2022 re-inspection: Added 2022 as missed		1			
54060	ACTIVE	p	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Other Electrical Boxes	Asbestos	Presumed	36		LHS	Flash guards Signal break box Notes from 2022 re-inspection: Added 2022 as missed		1			
38155	ACTIVE	p	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Signal Boxes	Asbestos	Presumed	42		LHS	Flash guards Switch box 12AVCR		1			
38156	ACTIVE	p	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Signal Boxes	Asbestos	Presumed	60		LHS	Flash guards Signal break box		1			
38157	ACTIVE	p	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Signal Boxes	Asbestos	Presumed	61		LHS	Flash guards Signal break box		1			
39926	ACTIVE	p	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Signal Boxes	Asbestos	Presumed	108		LHS	Flash guards Fog repeater WT12B		1			
37950	ACTIVE	p	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Signal Boxes	Asbestos	Presumed	116		LHS	Flash guards Signal break box		1			
54061	ACTIVE	p	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Other Electrical Boxes	Asbestos	Presumed	117		LHS	Flash guards Signal break box Notes from 2022 re-inspection: Added 2022 as missed		1			
37951	ACTIVE	p	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Signal Boxes	Asbestos	Presumed	118		LHS	Flash guards Signal break box		1			
37952	ACTIVE	p	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Signal Boxes	Asbestos	Presumed	223		LHS	Flash guards Switch Box		1			
37953	ACTIVE	p	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Signal Boxes	Asbestos	Presumed	226		LHS	Flash guards Signal WT12B		1			
37954	ACTIVE	p	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Signal Boxes	Asbestos	Presumed	235		LHS	Flash guards Signal break box		1			
39420	ACTIVE	p	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Signal Boxes	Asbestos	Presumed	239		LHS	Flash guards Signal break box		1			
37955	ACTIVE	p	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Signal Boxes	Asbestos	Presumed	390		LHS	Flash guards Signal RWT12 C and Fog Repeater WT12C		2			



Hazardous Material Asset Register - Summary



D224-P - PIC Line - Hounslow East to Hounslow Central

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
54062	ACTIVE	P	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Other Electrical Boxes	Asbestos	Presumed	396		LHS	Flash guards Signal break box Notes from 2022 re-inspection: Added 2022 as missed		1			
54063	ACTIVE	P	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Other Electrical Boxes	Asbestos	Presumed	400		LHS	Flash guards Signal break box Notes from 2022 re-inspection: Added 2022 as missed		1			
37956	ACTIVE	P	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Signal Boxes	Asbestos	Presumed	508		LHS	Cement debris Switch box 12VRS		1			
39774	ACTIVE	P	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Signal Boxes	Asbestos	Presumed	509		LHS	Flash guards Signal break box		1			
37957	ACTIVE	P	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Signal Boxes	Asbestos	Presumed	513		LHS	Flash guards Signal WT12C		1			
54064	ACTIVE	P	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Other Electrical Boxes	Asbestos	Presumed	536		LHS	Flash guards Switch box Notes from 2022 re-inspection: Added 2022 as missed		1			
37958	ACTIVE	P	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Signal Boxes	Asbestos	Presumed	543		LHS	Flash guards Signal break box		1			
37959	ACTIVE	P	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Signal Boxes	Asbestos	Presumed	557		LHS	Flash guards Signal break box		1			
54065	ACTIVE	P	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Other Electrical Boxes	Asbestos	Presumed	613		LHS	EP valve Notes from 2022 re-inspection: Added 2022 as missed		1			
37960	ACTIVE	P	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Signal Boxes	Asbestos	Presumed	613		LHS	Flash guards Signal break box		1			
37961	ACTIVE	P	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Signal Boxes	Asbestos	Presumed	614		LHS	Flash guards Switch Box Notes from 2022 re-inspection: And core box		1			
37963	ACTIVE	P	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Signal Boxes	Asbestos	Presumed	616		LHS	Flash guards Signal WT3		1			
37962	ACTIVE	P	D224-P-WBLO	Road WBLO - PIC - Hounslow East to Hounslow Central	Signal Boxes	Asbestos	Presumed	616		LHS	Flash guards Signal break box		1			

D226-P - PIC Line - Hounslow Central to Hounslow West

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38195	ACTIVE	P	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Cable Sheath	Asbestos	Presumed	0		LHS	Braided Cables.J Hanger 1 = 0 J Hanger 2 = 0 J Hanger 3 = 0 J Hanger 4 = 0 J Hanger 5 = 0 J Hanger 6 = 0 J Hanger 7 = 1x 70mm		1			
38194	ACTIVE	P	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Presumed	0		LHS	Flash guards Signal WTX413		1			



Hazardous Material Asset Register - Summary



D226-P - PIC Line - Hounslow Central to Hounslow West

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38196	ACTIVE	P	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Presumed	2		LHS	Flash guards Switch box		1			
38197	ACTIVE	P	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Presumed	3		LHS	Flash guards Signal break box		1			
39828	ACTIVE	P	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Presumed	8		LHS	Flash guards Signal break box		1			
38198	ACTIVE	P	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Presumed	14		LHS	Flash guards Signal break box		1			
38199	ACTIVE	P	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Presumed	78		LHS	Braided Cables. Cable enters junction box, PVC on other side of box		1			
38200	INACTIVE	P	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Removed	79		LHS	Flash guards Signal break box Notes from 2022 re-inspection: Removed		1			
38201	INACTIVE	P	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Removed	81		LHS	Flash guards Signal break box Notes from 2022 re-inspection: Removed		1			
39928	ACTIVE	P	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Presumed	253		LHS	Flash guards Switch box Notes from 2022 re-inspection: Link box		1			
38202	ACTIVE	P	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Presumed	345		LHS	Signal Boxes		1			
38203	ACTIVE	P	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Presumed	479		LHS	Flash guards Signal break box		1			
38204	ACTIVE	P	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Presumed	481		LHS	Flash guards Signal break box		1			
39424	ACTIVE	P	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Presumed	482	483	LHS	Flash guards Switch box		3			
39929	ACTIVE	P	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Presumed	737		LHS	Flash guards Signal RWT1A and Fog Repeater WT1 A		2			
38205	ACTIVE	P	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Presumed	764		LHS	Flash guards Signal break box		1			
38206	ACTIVE	P	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Presumed	765		LHS	Flash guards Signal break box		1			
38207	ACTIVE	P	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Presumed	853		LHS	Flash guards Switch box		1			
38208	ACTIVE	P	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Presumed	857		LHS	Flash guards Signal WT1 A		1			
38209	ACTIVE	P	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Presumed	865		LHS	Flash guards Signal break box		1			



Hazardous Material Asset Register - Summary



D226-P - PIC Line - Hounslow Central to Hounslow West

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38210	ACTIVE	p	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Presumed	869		LHS	Flash guards Signal break box		1			
39930	ACTIVE	p	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Presumed	900		LHS	Flash guards Signal RWT1 B		1			
54047	ACTIVE	p	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Other Electrical Boxes	Asbestos	Presumed	925		LHS	Fog Repeater		1			
54048	ACTIVE	p	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Other Electrical Boxes	Asbestos	Presumed	948		LHS	Flash guards signal break box		1			
54049	ACTIVE	p	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Other Electrical Boxes	Asbestos	Presumed	950		LHS	Flash guards signal break box		1			
54050	ACTIVE	p	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Other Electrical Boxes	Asbestos	Presumed	1007		LHS	Flash guards switch box		1			
38211	ACTIVE	p	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Presumed	1009		LHS	Flash guards Signal WT1 B		2			
54051	ACTIVE	p	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Other Electrical Boxes	Asbestos	Presumed	1027		LHS	Flash guards signal break box Notes from 2022 re-inspection: Present 2022		1			
39425	ACTIVE	p	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Presumed	1125		LHS	Flash guards Switch box		2			
38212	INACTIVE	p	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Removed	1129		LHS	Flash guards Signal WT1 B Notes from 2022 re-inspection: Removed		2			
38213	INACTIVE	p	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Removed	1139		LHS	Flash guards Signal break box Notes from 2022 re-inspection: Removed		1			
38214	INACTIVE	p	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Removed	1143		LHS	Flash guards Signal break box Notes from 2022 re-inspection: Removed		1			
38215	INACTIVE	p	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Removed	1144		LHS	Flash guards Signal break box Notes from 2022 re-inspection: Removed		1			
38216	ACTIVE	p	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Presumed	1309		LHS	Flash guards Signal break box		1			
38217	ACTIVE	p	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Presumed	1311		LHS	Flash guards Marshalling Kiosk Notes from 2022 re-inspection: 1 x no		1			
38218	ACTIVE	p	D226-P-EBLO	Road EBLO - PIC - Hounslow West to Hounslow Central	Signal Boxes	Asbestos	Presumed	1312		LHS	Flash guards Signal break box		1			
38112	ACTIVE	p	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	1		LHS	Flash guards Signal WT11		1			



Hazardous Material Asset Register - Summary



D226-P - PIC Line - Hounslow Central to Hounslow West

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38113	ACTIVE	P	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	7		LHS	Flash guards Marshalling Kiosk		11			
38114	ACTIVE	P	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	16		LHS	Flash guards Signal break box		1			
38115	ACTIVE	P	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	262		LHS	Flash guards Signal break box		1			
38116	ACTIVE	P	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	263		LHS	Flash guards Signal break box		1			
38117	ACTIVE	P	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	519		LHS	Flash guards Switch box		1			
39780	ACTIVE	P	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	530		LHS	Flash guards Signal break box		1			
38118	ACTIVE	P	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	531		LHS	Flash guards Signal break box		1			
38119	ACTIVE	P	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	678		LHS	Flash guards Signal RX412Aand Fog repeater X412 A		2			
54044	ACTIVE	P	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Other Electrical Boxes	Asbestos	Presumed	690		LHS	Flash guards signal break box 2x		2			
39921	ACTIVE	P	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	784		LHS	Flash guards Switch box		1			
38120	ACTIVE	P	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	799		LHS	Flash guards Signal X412A		1			
38121	ACTIVE	P	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	803		LHS	Flash guards Signal break box		1			
38122	ACTIVE	P	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	808		LHS	Flash guards Signal break box		1			
38123	ACTIVE	P	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	949		LHS	Flash guards Signal R412 B/1		1			
38124	ACTIVE	P	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	959		LHS	Flash guards Signal break box		1			
39922	ACTIVE	P	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	964		LHS	Flash guards Signal break box		1			
38125	ACTIVE	P	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	1009		LHS	Flash guards Fog repeater A412B		1			
38126	ACTIVE	P	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	1019		LHS	Flash guards Signal break box		1			
38127	ACTIVE	P	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	1021		LHS	Flash guards Signal break box		1			



Hazardous Material Asset Register - Summary



D226-P - PIC Line - Hounslow Central to Hounslow West

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38128	ACTIVE	p	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	1022		LHS	Flash guards Signal break box		1			
39923	ACTIVE	p	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	1044		LHS	Flash guards Signal R412 B/ 2		2			
38129	ACTIVE	p	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	1051		LHS	Flash guards Signal break box		1			
38130	ACTIVE	p	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	1056		LHS	Flash guards Signal break box		1			
38131	ACTIVE	p	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	1129		LHS	Flash guards Switch Box		1			
38132	ACTIVE	p	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	1133		LHS	Flash guards Signal A412B		1			
38133	ACTIVE	p	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	1144		LHS	Flash guards Signal break box		1			
38134	ACTIVE	p	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	1149		LHS	Flash guards Signal break box		1			
38135	ACTIVE	p	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	1293		LHS	Flash guards Signal break box		1			
38136	ACTIVE	p	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	1301		LHS	Flash guards Signal break box		1			
39639	ACTIVE	p	D226-P-WBLO	Road WBLO - PIC - Hounslow Central to Hounslow West	Signal Boxes	Asbestos	Presumed	1324		LHS	Flash guards Switch Boxes		2			

D227-P - PIC Line - Hounslow West Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38280	ACTIVE	p	D227-P-EBLO	Road EBLO (Plt2) - PIC - Hounslow West Stn	Ducts	Asbestos	Sampled – Not Detected	0			bitumen ducts					
42729	ACTIVE	p	D227-P-EBLO	Road EBLO (Plt2) - PIC - Hounslow West Stn	Pit Blocks	Asbestos	Removed				Pit blocks HMU Re-Inspection 30/01/2018 Notes from 2022 re-inspection: Put blocks all removed 2019/2021			R610926		
54052	ACTIVE	p	D227-P-EBLO	Road EBLO (Plt2) - PIC - Hounslow West Stn	Other Electrical Boxes	Asbestos	Presumed	1029		LHS	Flash guards signal break box Notes from 2022 re-inspection: Present 2022		1			
38279	ACTIVE	p	D227-P-WBLO	Road WBLO (Plt1) - PIC - Hounslow West Stn	Ducts	Asbestos	Sampled – Not Detected	0			bitumen ducts LHS to UTX					
54046	ACTIVE	p	D227-P-WBLO	Road WBLO (Plt1) - PIC - Hounslow West Stn	Pit Blocks	Asbestos	Removed				Pit Blocks Notes from 2022 re-inspection: Pit blocks all removed 2019/2021					



Hazardous Material Asset Register - Summary



D227-P - PIC Line - Hounslow West Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42120	ACTIVE	p	D227-P-WBLO	Road WBLO (Plt1) - PIC - Hounslow West Stn	Pit Blocks	Asbestos	Removed			RHS	Pitblock number 1, platform side of track - westbound platform Notes from 2022 re-inspection: Put blocks all removed 2019/2021		1			
42119	ACTIVE	p	D227-P-WBLO	Road WBLO (Plt1) - PIC - Hounslow West Stn	Pit Blocks	Asbestos	Removed			LHS	Pitblock number 32, track wall side of track - westbound platform Notes from 2022 re-inspection: Put blocks all removed 2019/2021		1			
42118	ACTIVE	p	D227-P-WBLO	Road WBLO (Plt1) - PIC - Hounslow West Stn	Pit Blocks	Asbestos	Removed			LHS	Pitblock number 1, track wall side of track - westbound Notes from 2022 re-inspection: Put blocks all removed 2019/2021		1			
42121	ACTIVE	p	D227-P-WBLO	Road WBLO (Plt1) - PIC - Hounslow West Stn	Pit Blocks	Asbestos	Removed			RHS	Pitblock number 32, platform side of track - westbound platform Notes from 2022 re-inspection: Put blocks all removed 2019/2021		1			

D228-P - PIC Line - Hounslow West to Hatton Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37799	ACTIVE	p	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	4		LHS	Flash guards Signal WW3		1			
39417	ACTIVE	p	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Cable Sheath	Asbestos	Presumed	5		LHS	Braided Cable, J Hanger 1 = 0 J Hanger 2 = 0 J Hanger 3 = 2 x 10mm & 1 x 20mm J Hanger 4 = 0		3			
37800	ACTIVE	p	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Ducts	Asbestos	Sampled – Not Detected	6		LHS	Bitumen ducts					
37801	ACTIVE	p	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Cable Sheath	Asbestos	Presumed	12		LHS	Braided Cable, 1 x 20mm cable from J hanger 3 to switch box		1			
37802	ACTIVE	p	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	13		LHS	Flash guards Signal break box		1			
39766	ACTIVE	p	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	14		LHS	Flash guards Switch box		1			
37803	ACTIVE	p	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Cable Sheath	Asbestos	Presumed	17		LHS	Braided Cable, 2 x 10mm cables from J hanger 3 to switch box		2			
37804	ACTIVE	p	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	17		LHS	Flash guards Switch box		1			
37805	ACTIVE	p	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Cement Cable Troughing & Debris	Asbestos	Known	18		LHS	Cable troughing from post going under track		3			
37806	ACTIVE	p	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Cable Sheath	Asbestos	Presumed	30		LHS	Braided Cable, 1 x 50mm cable from high level to J hanger 3		1			
37807	ACTIVE	p	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	77		LHS	Flash guards Signal break box		1			



Hazardous Material Asset Register - Summary



D228-P - PIC Line - Hounslow West to Hatton Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37808	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	81		LHS	Flash guards Signal break box		1			
37809	INACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Track Section Switches	Asbestos	Removed	91		LHS	Current rail section switches, 844 & 844A Asbestos Cement Panels removed by Edenbeck ES9541a 17/01/2018		2			
37810	INACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Track Section Switches	Asbestos	Removed	142	145	LHS	Current rail section switches, 843, 843A, 842 & 842A. Asbestos cement panels removed by Edenbeck ES9541a 17/01/2018		4			
37811	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	222		LHS	Flash guards Signal break box		1			
37812	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	223		LHS	Flash guards Signal break box		1			
37813	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	434		LHS	Flash guards Signal break box		1			
37814	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	435		LHS	Flash guards Signal break box		1			
37815	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	642		LHS	Flash guards Signal A407					
39877	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	644		LHS	Flash guards Switch box		1			
37816	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	682		LHS	Flash guards Switch box		1			
37817	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	688		LHS	Flash guards Signal break box		1			
37818	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	689		LHS	Flash guards Signal break box		1			
37819	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	1008		LHS	Flash guards Signal break box		1			
39878	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	1152		LHS	Flash guards Signal break box		1			
37820	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	1153		LHS	Flash guards Signal break box		1			
37821	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Cable Sheath	Asbestos	Presumed	1285		LHS	Braided Cable, 1 x 50mm cable entering high level duct		1			
37822	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Ducts	Asbestos	Presumed	1285	1287	LHS	cement high level ducts		9			
37823	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Cable Sheath	Asbestos	Presumed	1286		LHS	Braided Cable, 3 x 10mm cables from middle high level duct to J hanger 3		3			



Hazardous Material Asset Register - Summary



D228-P - PIC Line - Hounslow West to Hatton Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37824	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Cable Sheath	Asbestos	Presumed	1287		LHS	Braided Cable, 1 x 80mm cable from end high level duct to J hanger 4		1			
37825	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Cement Cable Troughing & Debris	Asbestos	Presumed	1291		LHS	cement cable troughing		3			
37826	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	1524		LHS	Flash guards Signal A409		1			
39767	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	1527		LHS	Flash guards Switch box		1			
37827	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	1530	1531	LHS	Flash guards Switch box		3			
37829	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	1533		LHS	Flash guards Signal break box		1			
37828	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	1534		LHS	Flash guards Signal break box		1			
37831	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	2062		LHS	Flash guards Signal R411 A/2					
37830	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	2071		LHS	Flash guards Signal break box		1			
37832	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	2073		LHS	Flash guards Signal break box		1			
37833	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	2125		LHS	Flash guards Signal A4091		1			
37834	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	2128		LHS	Flash guards Switch box		1			
37835	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	2133		LHS	Flash guards Signal break box		1			
37836	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	2135		LHS	Flash guards Signal break box		1			
37837	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	2186		LHS	Flash guards Signal A411A/2		1			
39605	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	2196		LHS	Flash guards Signal break box		1			
37838	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	2197		LHS	Flash guards Signal break box		1			
37839	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	2302		LHS	Flash guards Signal A411A		1			
39879	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	2303		LHS	Flash guards Switch box		1			



Hazardous Material Asset Register - Summary



D228-P - PIC Line - Hounslow West to Hatton Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37840	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	2329		LHS	Flash guards Signal break box		1			
37841	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	2333		LHS	Flash guards Signal break box		1			
37842	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	2627		LHS	Flash guards Signal A411B		1			
37843	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	2628		LHS	Flash guards Switch box		1			
39880	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	2644		LHS	Flash guards Signal break box		1			
37844	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	2649		LHS	Flash guards Signal break box		1			
37845	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	2790		LHS	Flash guards Signal break box		1			
37846	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Ducts	Asbestos	Sampled – Not Detected	2792		LHS	bitumen ducts					
37847	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Signal Boxes	Asbestos	Presumed	2795		LHS	Flash guards Signal break box					
37848	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Cable Sheath	Asbestos	Presumed	2800		LHS	Braided Cable, 3 x 10mm from J hanger 4 to junction box and into duct No 6		3			
39881	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Ducts	Asbestos	Sampled – Not Detected	2800		LHS	bitumen ducts					
39768	ACTIVE	P	D228-P-EBLO	Road EBLO - PIC - Hatton Cross to Hounslow West	Cable Sheath	Asbestos	Presumed	2800		LHS	Braided Cable, 1 x 80mm cable from J hanger 4 to duct No 2		1			
38219	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Ducts	Asbestos	Sampled – Not Detected	2		LHS	Bitumen ducts					
38220	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	11		LHS	Braided Cable for Signal break box		1			
38221	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Signal Boxes	Asbestos	Presumed	13		LHS	Flash guards Switch box		1			
38222	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	24		LHS	Braided Cable for Signal break box		1			
38223	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	28		LHS	Braided Cable for Signal break box		1			
38224	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	194		LHS	Braided Cable for Signal break box		1			
38225	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	197		LHS	Braided Cable for Signal break box		1			



Hazardous Material Asset Register - Summary



D228-P - PIC Line - Hounslow West to Hatton Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38226	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	493		LHS	Braided Cable for Signal break box		1			
38227	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	494		LHS	Braided Cable for Signal break box		1			
38228	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Signal Boxes	Asbestos	Presumed	567		LHS	Flash guards Signal R408 & R408/1		1			
39931	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	575		LHS	Braided Cable for Signal break box		1			
38229	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	578		LHS	Braided Cable for Signal break box		1			
38234	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	824		LHS	Braided Cable for Signal break box		1			
38235	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	825		LHS	Braided Cable for Signal break box		1			
38236	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	850		LHS	Braided Cable for Signal break box		1			
39933	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	855		LHS	Braided Cable for Signal break box		1			
38237	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	861		LHS	Braided Cable for Signal break box		1			
38238	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	865		LHS	Braided Cable for Signal break box		1			
38242	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cement Cable Troughing & Debris	Asbestos	Known	1521		LHS	Troughing running to eastbound side		3			
38241	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	1613		LHS	Braided Cable for Signal break box		1			
38244	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	1804		LHS	Braided Cable for Signal break box		1			
38245	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	1807		LHS	Braided Cable for Signal break box		1			
38246	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	1809		LHS	Braided Cable for Signal break box		1			
38247	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	1813		LHS	Braided Cable for Signal break box		1			
38248	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	1845			Flash guards Signal RWW1211A/1 and Fog repeater		1			
38250	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	1877		LHS	Braided Cable for Signal break box		1			



Hazardous Material Asset Register - Summary



D228-P - PIC Line - Hounslow West to Hatton Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38251	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	1967		LHS	Flash guards Signal WW12		1			
38252	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	1972		LHS	Braided Cable for Signal break box		1			
39830	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	1976		LHS	Braided Cable for Signal break box		1			
38254	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	2035		LHS	Braided Cable for Signal break box		1			
38255	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	2040		LHS	Braided Cable for Signal break box		1			
38256	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	2113		LHS	Braided Cable for Signal break box		1			
39426	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	2139		LHS	Braided Cable. 1 X 40mm cable from switch box onto j hanger 2 heading to Hatton Cross		1			
38259	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	2147		LHS	Braided Cable for Signal break box		1			
38260	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	2151		LHS	Braided Cable for Signal break box		1			
38261	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	2345		LHS	Braided Cable. 1 x 10mm from rail gap indicator onto J hanger 7 heading towards Hatton Cross		2			
38262	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	2443		LHS	Braided Cable for Signal break box		1			
38265	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	2448		LHS	Braided Cable for Signal break box		1			
39958	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	2549		LHS	Braided Cable for Signal break box		1			
38266	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	2553		LHS	Braided Cable for Signal break box		1			
38268	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	2612		LHS	Braided Cable. 1 x 10mm from box to J hanger 5 towards Hatton Cross		2			
38269	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	2684		LHS	Braided Cable for Signal break box		1			
38270	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	2688		LHS	Braided Cable for Signal break box		1			
38271	ACTIVE	P	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cement Cable Troughing & Debris	Asbestos	Known	2734		LHS	cement troughing		2			



Hazardous Material Asset Register - Summary



D228-P - PIC Line - Hounslow West to Hatton Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38273	ACTIVE	p	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	2790		LHS	Braided Cable. 2 x 10mm on J hanger 6 & 7 & 1 x 40mm on J hanger 5 crossing ceiling to Right hand side cable run high level through concrete ducts into switch room		3			
38276	ACTIVE	p	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	2803		LHS	Braided Cable. 3 Xx10mm from switch box to high level j hanger 3 heading to Hatton cross		3			
39642	ACTIVE	p	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cement Cable Troughing & Debris	Asbestos	Known	2804		LHS	cement troughing		4			
38277	ACTIVE	p	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	2804		LHS	Braided Cables. 1 x 20mm and 1 x 10mm from J hanger 4 dropping into duct at BRS2811		2			
38278	ACTIVE	p	D228-P-WBLO	Road WBLO - PIC - Hounslow West to Hatton Cross	Cable Sheath	Asbestos	Presumed	2806		LHS	Braided Cables. 1 x 10mm cable from box to J hanger 3		1			

D229-P - PIC Line - Hatton Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40120	ACTIVE	p	D229-P-EBLO	Road EBLO (Plt2) - PIC - Hatton Cross Stn	Pit Blocks	Asbestos	Known				Asbestos Pit Blocks HMu Re-Inspection - 02/02/2018 PWT EH required as well as track gang to lift rail to gain access also refer to previous HMPS info for pit block removals.					

D232-P - PIC Line - Hatton Cross to Heathrow Terminals 2&3

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41097	ACTIVE	p	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Tunnel ring caulking, Wide way wihin crossover					
41098	ACTIVE	p	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Tunnel ring caulking, Single bore tunnel after crossover					
41099	ACTIVE	p	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Strongly Presumed				Woven cables, throughout crossover					
41095	ACTIVE	p	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Tunnel ring caulking, To single bore tunnel before crossover					
41096	ACTIVE	p	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Tunnel ring caulking, Sealed with concrete - wide way within crossover					
39999	ACTIVE	p	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known			LHS	Woven cable insulation. Track level, J hanger 4 from top 20mm dia.		4			
40985	ACTIVE	p	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known				Woven cable insulation. Track level J hanger 3 & 4 from top 20mm dia.					



Hazardous Material Asset Register - Summary



D232-P - PIC Line - Hatton Cross to Heathrow Terminals 2&3

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41399	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known			RHS	Cables, Hanger No.2 - 2 x 30mm Ø green cables		2			
41400	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known			LHS	Cables, Hanger No.4 - 1 x 40mm Ø green cable 1 x 10mm Ø green cable		2			
40983	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known				Crossway - Woven cable insulation. High level gantry/walkway, All 4 J hangers					
40984	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known				Crossover - Woven cable insulation, High level gantry/walkway, All 4 J hangers					
40986	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	0		RHS	Cables, 1 x 10mm Ø green cable		1			
40988	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	0		RHS	Cables, Hanger No.3 - 1 x 20mm Ø white cable		1			
40987	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	0		RHS	Cables, Hanger No.2 - 3 x 10mm Ø green cables		3			
40989	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	0		RHS	Cables, Hanger No.4 - 1 x 20mm Ø yellow and 1 x 40mm green cable		2			
40990	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	2		LHS	Cables, 1 x 20mm Ø white cable, Goes from ducts to ceramic block cable cleats on left hand side		1			
40991	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	8		RHS	Cables, More cables join from concrete ducts from signalling equipment room (See next cable entry for count)					
40994	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	10		RHS	Cables, Hanger NO.4 - 2x 40mm Ø green cables, 2 x 10mm Ø white cables, 1 x 20mm Ø green & 1 x 10mm Ø yellow cables		6			
40993	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	10		RHS	Cables, Hanger No.3 - 1 x 20mm white cable		1			
40992	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	10		RHS	Cables, Hanger No.1 (top) 6 x 10mm Ø green cables		6			
39499	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	10		RHS	Cables, Hanger No. 2 - 3 x 30mm Ø white cables 4-6 x 10mm Ø green cables		9			
40995	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	10		RHS	Cables, Hanger No.2 - 1 x 20mm Ø white cable		1			
40996	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	12		RHS	Cables, Goes to hanger No.3 - 1 x 10mm Ø green cable from glass enclosed valve		1			
40998	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Strongly Presumed	13		RHS	Box					
40997	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	13		RHS	Cables, 2 x 10mm Ø green cables from 10 core box and 1 x 5mm Ø cable		3			
41000	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Strongly Presumed	14		RHS	Box					



Hazardous Material Asset Register - Summary



D232-P - PIC Line - Hatton Cross to Heathrow Terminals 2&3

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40999	ACTIVE	p	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	14		RHS	Cables, 1 x 10mm Ø green cable to track disconnection box					
39495	INACTIVE	p	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Removed	15		RHS	Cables, To hanger No.3 - 1 x 10mm Ø green cable to 10 core style box - 2021 REINSPECTION CONFIRMED REMOVED		1			
41003	ACTIVE	p	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Removed	15		RHS	Box - 2021 REINSPECTION CONFIRMED REMOVED					
41002	ACTIVE	p	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Strongly Presumed	15		RHS	Box					
41001	ACTIVE	p	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	15		RHS	Cables, From hanger No.2 - 1 x 10/20mm Ø unite cable to 10 core style box		1			
41005	ACTIVE	p	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Strongly Presumed	16		RHS	Box					
41004	ACTIVE	p	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	16		RHS	Cables, 3 x 10mm Ø green cables to relay style box		3			
41006	ACTIVE	p	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Strongly Presumed	17		RHS	Main Line Link Box					
39796	ACTIVE	p	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	17		RHS	Cables, AC Main Link Box - 1 x 40mm Ø green cable from hanger No.4		1			
40027	ACTIVE	p	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	18		LHS	Cables, 1 x 20mm dia white to hanger 4		1			
41088	ACTIVE	p	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cement Cable Troughing & Debris	Asbestos	Known	20			Troughing. From current on line relay box which if old type contains open mercury pots		4			
41089	ACTIVE	p	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	23		RHS	Cables, 2 x 10mm Ø green cables from hanger No.2 to relay style box		2			
41090	ACTIVE	p	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Strongly Presumed	23		RHS	Relay style box					
41091	ACTIVE	p	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	33		RHS	Cable, 1 x 10mm dia white - Goes from right hand side hanger No.4 OTX to left hand side hanger No.5		1			
41092	ACTIVE	p	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	34		LHS	Cables, 1 x 10mm Ø white on hanger No.5, 1 x 20mm Ø white on hanger No.4		2			
41093	ACTIVE	p	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	36		RHS	Cables, 2 x 10mm Ø green cables and -2 x 10mm Ø green cables		4			
41094	ACTIVE	p	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	37		RHS	1 x 10mm Ø green cable - Goes to glass enclosed valve		1			
41100	ACTIVE	p	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	45		LHS	From hanger ~No.5 - 1 x 10mm Ø white cable to tunnel telephone wires		1			
41101	ACTIVE	p	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	50		RHS	From hanger No.4 - 1 x 10mm Ø white cable to tunnel telephone wires		1			



Hazardous Material Asset Register - Summary



D232-P - PIC Line - Hatton Cross to Heathrow Terminals 2&3

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41102	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	55		RHS	Cables, Cables onto gantry					
41107	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	111		LHS	Cables, Hanger No.5 - 1 x 20mm Ø white cable		1			
41105	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	111		RHS	Cables, Hanger No.3 - 1 x 30mm Ø white cable 1 x 10mm Ø white cable		2			
41103	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	111		RHS	Cables, Hanger No.1 - 5 x 10mm Ø green cables		5			
41104	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	111		RHS	Cables, Hanger No.2 - 1 x 30mm Ø white cable, 2 x 10mm Ø green cables, 1 x 10mm Ø white cable		4			
41106	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	111		RHS	Hanger No. 4 - 1 x 40mm Ø green cable 1 x 10mm Ø white cable		2			
39526	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Track Section Switches	Asbestos	Removed	116		RHS	Section Switch. 846A. Asbestos cement boarding removed by Edenbeck ES9541a 17/01/2018					
41108	INACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Track Section Switches	Asbestos	Removed	117		RHS	Section Switch. 846, 1m2 - removed by Edenbeck ES5941a					
41109	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	118		RHS	Goes from tunnel telephone wires onto hanger No.6 - 1 x 10mm Ø white cable		1			
41110	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	120		RHS	Cables, go to and from glass enclosed valve and signal equipment boxes - -1 x 30mm Ø white from hanger No.3 +4 x 10mm Ø green to hanger No.3					
41111	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	125		RHS	Cable, 1 x 10mm Ø green cable to track disconnection box		1			
41112	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Strongly Presumed	125		RHS	Box					
41195	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Strongly Presumed	128		RHS	Track disconnection box					
41193	INACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Removed	128		RHS	tunnel telephone - 2021 REINSPECTION CONFIRMED REMOVED					
41194	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	128		RHS	Cable, 1 x 10mm Ø green cable to track disconnection box		1			
40028	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	128		RHS	Cable, 1 x 10mm Ø white from tunnel telephone wires goes OTX to right hand side hanger No.2		1			
41197	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Strongly Presumed	132		RHS	Relay style box					
41196	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	132		RHS	Cable, 6 x 10mm Ø green cables to relay style box from hanger 3		6			



Hazardous Material Asset Register - Summary



D232-P - PIC Line - Hatton Cross to Heathrow Terminals 2&3

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41198	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	135		LHS	Cable, 1 x 20mm Ø white in hanger No.3		1			
41200	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Strongly Presumed	190		LHS	Control box					
41199	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	190		LHS	Cable, 1 x 20mm Ø white goes to pump control box		1			
41203	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	200		RHS	Cables, Hanger No.4 - 1 x 40mm Ø green		1			
41201	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	200		RHS	Cables, Hanger No.1 (top) - 3 x 10mm Ø green cables		3			
41202	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	200		RHS	Cables, Hanger No.2 - 2 x 10mm Ø green cables, 1 x 10mm Ø white cables, 1 x 30mm Ø white cable		4			
39802	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	210		RHS	Cables, From hanger No.2 to signal box -1 x 10mm Ø white cable -1 x 10mm Ø green cable		2			
40033	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	260		RHS	Cables, Possible braided cable in conduit to light - -1 x 10mm Ø green cable to track disconnection style box and speed restriction light		1			
41204	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Known	260		RHS	Track disconnection box					
41205	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	300		RHS	Cables, Hanger No.1 (top) - 3 x 10mm Ø green cables		3			
41207	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	300		RHS	Cables, Hanger No 4 - 1 x 40mm Ø green cable		1			
41206	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	300		RHS	Cables, Hanger No.2 - 1 x 30mm Ø white cables		1			
41208	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	490		RHS	Cables, To and from 10 core style box to hanger No.2 - +1 x 30mm Ø white cable -1 x 30mm Ø white cable		2			
41209	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	500		RHS	Cables, Hanger No.2 - 1 x 30mm Ø white cable		1			
41210	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	500		RHS	Cables, Hanger No.4 - 1 x 40mm Ø green cable		1			
39534	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	500		RHS	Cables, Hanger No.1 - 3 x 10mm Ø green cables		3			
41212	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Strongly Presumed	599		RHS	Signal R401					
41211	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	599		RHS	Cables, To hanger No.12 - Signal R401 +2 x 10mm Ø green cables 1 x 5mm Ø to earth		3			
41213	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	600		RHS	Cables, To and from hanger No.2 to/front 10 core -1 x 30mm Ø white cable +1 x 30mm Ø white cable		2			



Hazardous Material Asset Register - Summary



D232-P - PIC Line - Hatton Cross to Heathrow Terminals 2&3																
Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41214	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	610		RHS	Cables, Hanger No.1 to/track disconnection box - -1 x 10mm Ø green cable		1			
41215	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	612		RHS	Cable, Only 1 x 10mm Ø green cable on hanger 1 now		1			
39535	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	612		RHS	Cables, Hanger No.1 to track disconnection box -1 x 10mm Ø green cable		1			
41216	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	614		RHS	To and from hanger No.2 to/from track disconnection box -1 x 10mm Ø green cable +1 x 10mm Ø green cable		2			
41217	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	688		RHS	Cable, To and from hanger No.2 to/from track disconnection box -1 x 10mm Ø green cable +1 x 10mm Ø green cable		2			
41298	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	699		RHS	Cable, Hanger No.2 - 2 x 10mm Ø green cables 1 x 30m Ø white cable		3			
39851	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	699		RHS	Cable, Hanger No.1 - 1 x 10mm Ø green cable		1			
41299	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	699		RHS	Cable, Hanger No.4 - 1 x 40mm Ø green cable		1			
41300	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Known	700		RHS	Signal. Asbestos braided cable foes to and from cable run to this equipment					
41301	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Known	700		RHS	Tencore box. Asbestos braided cable foes to and from cable run to this equipment					
41302	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Westinghouse Boxes	Asbestos	Known	700		RHS	Large iron Westinghouse type boxes. Asbestos braided cable foes to and from cable run to this equipment					
46180	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross		Asbestos	Known				Glass enclosed valve. Asbestos braided cable goes to and from cable run to this equipment				N	N
41303	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Known	700		RHS	Track disconnection box. Asbestos braided cable foes to and from cable run to this equipment					
41304	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Known	716		RHS	Track disconnection box. Asbestos braided cable foes to and from cable run to this equipment					
41305	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	720		RHS	Cable, Hanger No.1 - 1 x 10mm Ø green cable		1			
41306	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	720		RHS	Cable, Hanger No.4 - 1 x 40mm Ø green cable		1			
40037	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	720		RHS	Cable, Hanger No.2 - 2 x 30mm Ø cable green cables		2			
41307	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	760		RHS	Cable, 1 x 40mm Ø green cable joint		1			



Hazardous Material Asset Register - Summary



D232-P - PIC Line - Hatton Cross to Heathrow Terminals 2&3																
Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41308	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	800		RHS	Cables, Cables same as BRS720 right hand side					
41309	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1000		LHS	Cables, Cables same as BRS720 right hand side					
41311	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Strongly Presumed	1090		RHS	Track disconnection box. Goes to hanger No. 1					
41310	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1090		RHS	Cables, Goes to hanger No.1 - +1 x 10mm Ø green cable from track disconnection box		1			
41312	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1091		RHS	Cables, Goes to hanger No.1 - +1 x 10mm Ø green cable from track disconnection box		1			
41313	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Strongly Presumed	1091		RHS	Track disconnection box. Goes to hanger No. 1					
41314	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1100		RHS	Cables, Hanger No.1 - 3 x 10mm Ø green cables		3			
41315	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1100		RHS	Cables, Hanger No.2 - 2 x 30mm Ø green cables		2			
41316	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1100		RHS	Hanger No.4 - 1 x 40mm Ø green cables		1			
41317	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1180		RHS	Cables, To/from track disconnection box to hanger No.2 - +1 x 10mm Ø green cable -1 x 10mm Ø yellow cable		2			
39565	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1195		RHS	Cables, To/from 10 core style box to/from hanger No.2 - +1 x 30mm Ø green cable -1 x 30mm Ø green cable		2			
41318	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1200		RHS	Cables, To/from 10 core style box to/from hanger No.2 - +1 x 30mm Ø green cable -1 x 30mm Ø green cable		2			
41319	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1201		RHS	Hanger No.2 - 1 x 10mm Ø green cable 1 x 40mm Ø green cable		2			
41321	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1205		RHS	Cables, Hanger No.1 - 2 x 30mm Ø green cables		2			
41320	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1205		RHS	Cables, Hanger No.1 - 3 x 10mm Ø green cables		3			
41322	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1285		RHS	Cables, Joint to 1 x 40mm Ø green cable		1			
41398	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1300		RHS	Cables, Hanger No.1 - 3 x 10mm Ø green cables		3			
39855	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1500		RHS	Cables, Hanger No.2 - 2 x 30mm Ø green cables		2			



Hazardous Material Asset Register - Summary



D232-P - PIC Line - Hatton Cross to Heathrow Terminals 2&3

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41401	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1500		RHS	Cables, Hanger No.1 - 3 x 10mm Ø green cables		3			
41402	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1500		RHS	Cables, Hanger No.4 - 1 x 10mm green cable 1 x 40mm green cable		2			
41407	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Known	1508		RHS	Track disconnection box. Asbestos cables go to and from hangers to this equipment					
46181	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1508		RHS	Glass enclosed valve. Asbestos cables go to and from hangers to this equipment					
41408	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Known	1508		RHS	Track disconnection box. Asbestos cables go to and from hangers to this equipment					
41404	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Known	1508		RHS	Signal WW1, Asbestos cables go to and from hangers to this equipment					
41403	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Known	1508		RHS	Signal telephone, Asbestos cables go to and from hangers to this equipment					
41405	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Known	1508		RHS	10 core type box, Asbestos cables go to and from hangers to this equipment					
41406	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Known	1508		RHS	Relay style case, Asbestos cables go to and from hangers to this equipment					
40040	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Known	1508		RHS	10 core type box, Asbestos cables go to and from hangers to this equipment					
41410	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1520		RHS	Cables, Hanger No 2 - 3 x 30mm Ø green cables		3			
41409	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1520		RHS	Cables, Hanger No.1 - 5 x 10mm Ø green cables		5			
41411	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1520		RHS	Cables, Hanger No.4 - 2 x 10mm Ø green cables 1 x 40m Ø green cable		3			
46182	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1600		RHS	Same as 520m right hand side - woven cables					
41412	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1695		RHS	Cables, To/from hanger No.2 - 1 -1 x 30mm Ø green cable to/from 10 core style box		1			
41413	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Strongly Presumed	1695		RHS	Core style box, To/from hanger No. 2 - 1 -1 x 30mm Ø green cable to/ from 10 core style box		10			
41415	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Strongly Presumed	1698		RHS	Core style box, To/from hanger No. 2 - +1 -1 x 30mm Ø green cable to/ from 10 core style box		10			
41414	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1698		RHS	Cables, To/from hanger No.2 - +1 -1 x 30mm Ø green cable to/from 10 core style box		1			
41416	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1700		RHS	Cables, To/from hanger No.1 - +1 -1 x 10mm Ø green cable to/from track disconnection box		1			



Hazardous Material Asset Register - Summary



D232-P - PIC Line - Hatton Cross to Heathrow Terminals 2&3

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41417	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Strongly Presumed	1700		RHS	Track disconnection box. To/from hanger No.1 - +1 -1 x 10mm Ø green cable to/from track disconnection box		1			
41418	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1700		RHS	Cables, Hanger No.1 - 5 x 10mm Ø green cables		5			
39572	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1700		RHS	Cables, Hanger No.2 - 3 x 30mm Ø green cables		3			
41419	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1700		RHS	Cables, Hanger No.4 - 2 x 10mm Ø green cables 1 x 40mm green cables		3			
41420	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1752		RHS	Cables, Cut goes to hanger No.1 - +1 x 20mm Ø white cable		1			
41421	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1760		RHS	Cables, Cut at 1762m left hand side - 1 x 20mm Ø white cable OTS left hand side to right hand side, goes hanger No.1 to No.3 on right hand side		1			
41501	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1761		RHS	Hanger No.4 - 1 x 40mm Ø green cable 2 x 10mm Ø green cable		3			
41498	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1761		RHS	Cables, Hanger No.1 - 1 x 20mm Ø white cable 5 x 10mm Ø green cables		6			
41499	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1761		RHS	Cables, Hanger No.2 - 3 x 30mm Ø green cables		3			
41500	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1761		RHS	Cables, Hanger No.3, this 20mm Ø white cable goes OTX then cut		1			
41502	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1780		RHS	Cables, 1 x 40mm Ø green cable joint		1			
41503	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Presumed	1790		RHS	Box in Cross Passage					
41504	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Strongly Presumed	1800		RHS	3 Track disconnection box, Cables got to/from hanger No.1 3 track disconnection box+1 -3 x 10mm green cables		3			
39859	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1800		RHS	Cables, Cables got to/from hanger No.1 3 track disconnection box+1 -3 x 10mm green cables		3			
41505	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1808		RHS	Cables, To and from track disconnection box to/from hanger No.1 - +1 x 10mm Ø white cable -1 x 10mm Ø green cable		2			
41511	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1840		RHS	Cables, signal WW2					
41507	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1840		RHS	Cables, Hanger No.2 - 3 x 30mm Ø green cables		3			
41508	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1840		RHS	Cables, Hanger No.3 - 1 x 20mm Ø white cable		1			



Hazardous Material Asset Register - Summary



D232-P - PIC Line - Hatton Cross to Heathrow Terminals 2&3

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41510	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1840		RHS	Cables, signal telephone					
41509	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1840		RHS	Cables, Hanger No.4 - 1 x 40mm Ø green cable 2 x 10mm Ø green cables		3			
41506	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1840		RHS	Cables, Hanger No.1 - 4 x 10mm Ø green cables 1 x 10mm Ø white cable		5			
40044	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1860		RHS	Cables, 10 core, glass enclosed valve relay case					
39578	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1860		RHS	Cables, Hanger No.4 - 3 x 10mm Ø green cables 1 x 40mm Ø green cables		4			
41513	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1860		RHS	Cables, Hanger No.2 - 3 x 30mm Ø green cable		3			
41512	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1860		RHS	Cables, Hanger No.1 - 1 x 10mm Ø white cable 4 x 10mm Ø green cable		5			
41514	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1860		RHS	Cables, Hanger No.3 - 1 x 20mm Ø white cable 1 x 10mm green cables		2			
41515	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1870		RHS	Cable, Cut loop of white asbestos cable					
41516	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1880		RHS	Cable, To hanger No.1 - +1 x 10mm Ø white cable to track disconnection box					
41517	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1883		RHS	Cables, Redundant - 5mm Ø cables					
41518	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1885		RHS	Cable, To hanger No.1 - +1 x 10mm Ø white cable to track disconnection box		1			
39579	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1900		RHS	Cables, Hanger No.2 - 3 x 30mm Ø green cables		3			
41520	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1900		RHS	Cables, Hanger No.2 - 3 x 30mm Ø green cables		3			
41522	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1900		RHS	Cable, Hanger No.4 - 1 x 40mm Ø green cable 2 x 10mm Ø green cable		3			
41519	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1900		RHS	Cables, Hanger No.1 - 4 x 10mm Ø green cables 4 x 10mm Ø white cables		8			
41521	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	1900		RHS	Cables, Hanger No.3 - 1 x 30mm Ø green cable 1 x 20mm Ø white cable		1			
41599	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	2000		RHS	Cables, Same as 1900m right hand side					
41600	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cement Cable Troughing & Debris	Asbestos	Known	2000		LHS	Troughing. Under and adjacent to track		3			



Hazardous Material Asset Register - Summary



D232-P - PIC Line - Hatton Cross to Heathrow Terminals 2&3

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41601	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Signal Boxes	Asbestos	Known	2030		LHS	Juice connection box, Current rail section boxing, Boxing to switches. 1m2					
41602	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	2034		RHS	cable same as 2006					
41604	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	2035		RHS	Cables, Gain 1 x 10mm Ø white to hanger 1		1			
41603	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Ducts	Asbestos	Known	2035		RHS	Ducts, 6 off					
41605	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	2035		RHS	Cables, Signal equipments - Cables to and from hangers					
41606	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	2035		RHS	Cables, Signal equipments - Cables to and from hangers					
41607	ACTIVE	P	D232-P-EBLO	Road EBLO - PIC - Heathrow T2&3 to Hatton Cross	Cable Sheath	Asbestos	Known	2042		RHS	Cables, Signal equipments - Cables to and from hangers					
40672	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known				Cables, 2 x 10mm in/out Westinghouse					
40673	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed				Box					
40674	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known				Cables, 1 x 10mm green 1 x 15mm to 10 core an 1 x 5mm Ø					
40679	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known				Cables, 4 x 10mm green +1 x 5mm to right hand side of boxes					
40680	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed				Box					
40681	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known				Cables, 8 x 10mm green +1 x 5mm to 10 core on left hand side of box, +1 x 30mm white					
39987	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known				Cables, (4) 1 x 40mm, 1 x 20mm					
39988	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known				Cables, 7 x 10mm green leave box +1 x 5 - on (7) 1 x 30mm now on (7)					
40671	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known				Cables, 2 x 10mm Ø green 1 x 5mm brown to 10 core					
40485	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known				Cables, 2 x 10mm – top, 2nd – 1 x 10mm – 1 x 20mm, 3rd – 1 x 30mm, 4th – 1 x 40mm					
40366	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	0	6		westinghouse box		4			
40790	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known				Cables, Still (3) 1 x 20, (5) +2 x 30 W					



Hazardous Material Asset Register - Summary



D232-P - PIC Line - Hatton Cross to Heathrow Terminals 2&3

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40666	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known				Cables, J-hanger (3) left hand side still free					
40795	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known				Cables, 1 x 10mm now on (5)					
40675	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed				Box					
40682	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed				Box					
40691	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known				Cables, 1 x 20mm Ø white cut					
46178	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known			RHS	Cables - Cross over to RHS towards H123					
46179	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known				Asbestos cables in all hangers					
40687	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known				Cables, (3) 3x white 40mm Ø, 1 x 10mm Ø white, 210mm green, 1 x 20mm					
40878	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known				Cables, Asbestos on all 4 hangers					
40881	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known				Cables, Now 3 x 10mm green + in (5), 1 x 20 in (3)					
53999	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Ducts	Asbestos	Known	0	20		6no Cables Ducts - run behind wall from platform end to c.20m into tunnel		6	R713726		
40773	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known				Cables, (3) 2 x 10mm green, 1 x 10mm white, 3 x 30mm white					
40783	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known				Cables, OTX cables go to new 5th hanger					
40688	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known				Cables, (4) 1 x 40, 1 x 20 (5) air main - metal compressor					
40367	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	10		RHS	Cable. (Lower hanger) 1x 20mm , 1x 40mm		2			
40368	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	10		RHS	Cable. (Top hanger) 7x10mm		7			
40369	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	14		RHS	Cable at Westinghouse box, 2x10mm		2			
40370	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Westinghouse Boxes	Asbestos	Strongly Presumed	14		RHS	westinghouse box		1			



Hazardous Material Asset Register - Summary



D232-P - PIC Line - Hatton Cross to Heathrow Terminals 2&3

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44196	INACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3		Asbestos	Removed				Cement panel to side and top, 6 no., to 845 and 845A current rail section switch boxes, to RHS cess at BRS 21m on Westbound Road, Piccadilly Line - Hatton Cross to Heathrow. (Note plastic front panel) Reinspection 2021 - REMOVED & REPLACED WITH NON ACM BOARD			R605201	N	N
40371	INACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Current Rail Boxes	Asbestos	Removed	23		RHS	Current rail section switch 845 + 845A. Asbestos cement boarding has been removed and re-instated with a non asbestos substitute by Edenbeck ES9541a 17/01/2018					
40372	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Westinghouse Boxes	Asbestos	Strongly Presumed	35		RHS	westinghouse box		1			
40373	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	80		LHS	Cable, Comes out of concrete block 1x80mm		1			
39950	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	88		LHS	Cable, Looped over 1x30mm		1			
40374	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	120		RHS	Cable, 1 x 20mm into Westlinghouse box loose		1			
40375	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Westinghouse Boxes	Asbestos	Strongly Presumed	120		RHS	westinghouse box, Hanger 3 RHS Side clear		1			
40376	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	150		LHS	Cable, 1x20mm cut off					
40378	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Westinghouse Boxes	Asbestos	Strongly Presumed	242		RHS	westinghouse box		1			
40377	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	242		RHS	Cables, Lose 1x10mm, Gain 1x 10mm at Westinghouse box		2			
40380	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Westinghouse Boxes	Asbestos	Strongly Presumed	255		RHS	westinghouse box		1			
40379	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	255		RHS	Cables, Lose 3x10mm, Gain 3x 10mm at Westinghouse box		6			
39471	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed	322		RHS	TR Boxes - cables		5			
39403	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	336		RHS	Cables, Lose 1x10mm, Gain 1x 10mm at Westinghouse box		2			
40381	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Westinghouse Boxes	Asbestos	Strongly Presumed	336		RHS	westinghouse box		1			
40382	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	410		LHS	Cable, Gain 1z 10mm cut off		1			



Hazardous Material Asset Register - Summary



D232-P - PIC Line - Hatton Cross to Heathrow Terminals 2&3

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40383	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	415		LHS	Cable,1 x 10mm terminates		1			
40384	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	423	425	RHS	Cable, Lose 2x 10mm Cables at Westinghouse box		2			
39728	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Westinghouse Boxes	Asbestos	Strongly Presumed	423	425	RHS	westinghouse box		1			
39404	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	474		LHS	Cable, Lose 1 x 10mm		1			
40385	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	582		RHS	Cable, Lose 1 x 10mm		1			
40386	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	584		RHS	Cable, Lose 1 x 10mm		1			
40460	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Westinghouse Boxes	Asbestos	Strongly Presumed	626		RHS	westinghouse box		1			
39731	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	626		RHS	Cables, Lose 1 x10mm, Gain 1x10mm at Westinghouse box		2			
40461	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	816			Cable, cut off cable 1 x 10mm		1			
40462	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	819		RHS	Cables, Gain 5x10mm, Gain 1x30mm at Westinghouse box		6			
40463	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Westinghouse Boxes	Asbestos	Strongly Presumed	819		RHS	westinghouse box		1			
40464	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	820		LHS	Cables, 2x10m run from signal to Westinghouse box		2			
40465	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Westinghouse Boxes	Asbestos	Strongly Presumed	820		LHS	signal box		1			
40467	INACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Westinghouse Boxes	Asbestos	Removed	821		RHS	westinghouse box		1			
40466	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	821		RHS	Cables, Lose 2 x 10mm, Gain 2 x 10mm at Westinghouse box		4			
40469	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Westinghouse Boxes	Asbestos	Strongly Presumed	822		RHS	westinghouse box					
40468	INACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Removed	822		RHS	Cables, Lose 2x10mm at Westinghouse box		2			
40470	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	823		RHS	Cable, Lose 1 x10mm at relay					
40472	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Westinghouse Boxes	Asbestos	Strongly Presumed	988		RHS	westinghouse box		1			



Hazardous Material Asset Register - Summary



D232-P - PIC Line - Hatton Cross to Heathrow Terminals 2&3

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40471	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	988		RHS	Cables, Lose 1, Gain 1 at westinghouse box					
40475	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1000			Cables, 5th- airman - metal air pipe compressor					
39953	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1000		RHS	Cables, 4TH 1X 20mm, 1 x40mm		2			
40474	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1000			Cables, 3rd 1 x 30 mm		1			
40473	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1000		RHS	Cables, top hanger 2 x 10 mm		2			
40476	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1020		LHS	Cables, 2 x 20 mm gain cut off					
40478	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Westinghouse Boxes	Asbestos	Strongly Presumed	1046		RHS	westinghouse box					
40477	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1046		RHS	Cables, 1x10mm gain, 1x 10mm lose at Westinghouse box					
40480	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Westinghouse Boxes	Asbestos	Strongly Presumed	1074		RHS	westinghouse box					
40479	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1074		RHS	Cables, 1 x 30mm gain, 1 x 30mm lose at Westinghouse box					
39430	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1080		RHS	Cables, Lose 1, Gain 1 at Westinghouse box					
40481	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Westinghouse Boxes	Asbestos	Strongly Presumed	1080		RHS	westinghouse box					
40482	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1165		LHS	Cables, lose 1 x 20 mm to lighting		1			
40483	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1169		RHS	Cables, lose 1 x 20 mm to lighting		1			
40484	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1170		LHS	Cables, 2 x 20 mm gain		2			
40486	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Westinghouse Boxes	Asbestos	Strongly Presumed	1232		RHS	westinghouse box		1			
39431	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1232		RHS	Cables, Gain 1 x 10mm at Westinghouse box		1			
40564	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Westinghouse Boxes	Asbestos	Strongly Presumed	1234		RHS	westinghouse box					
40563	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1234		RHS	Cables, Gain 1 x 10mm at Westinghouse box		1			



Hazardous Material Asset Register - Summary



D232-P - PIC Line - Hatton Cross to Heathrow Terminals 2&3

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40566	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Westinghouse Boxes	Asbestos	Strongly Presumed	1310		RHS	westinghouse box		1			
40565	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1310		RHS	Cables, Gain 1 x 10m + 1 x 5mm at signal		2			
40567	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1414		RHS	Cables, Gain 1 x 10m + 1 x 5mm at signal		2			
40568	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Westinghouse Boxes	Asbestos	Strongly Presumed	1414		RHS	westinghouse box					
40570	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Westinghouse Boxes	Asbestos	Strongly Presumed	1524		RHS	westinghouse box					
40569	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1524		RHS	Cables, Gain 2 x 10mm at Westinghouse box					
40571	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1525		RHS	Cables, Gain 2 x 10mm, 1 x 20mm, 2 x 5mm, 1 x 30mm at Westinghouse box		6			
40572	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Westinghouse Boxes	Asbestos	Strongly Presumed	1525		RHS	westinghouse box		1			
40573	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1526		RHS	Cables, Lose 4 x 10mm, gain 3 x 10mm		7			
40574	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1527		RHS	Cables, Lose 1 x 20m					
40575	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1528		RHS	Cables, Lose 2 x 50mm, gain 2 x 10mm					
40576	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1529		RHS	Cables, Lose 1 x 5mm, 2 x 10mm					
39979	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1532		RHS	Cable, Gain 1x 10mm		1			
40577	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Westinghouse Boxes	Asbestos	Strongly Presumed	1532		RHS	westinghouse box		1			
40578	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1536		RHS	Cable, Gain 1x 10mm					
40579	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Westinghouse Boxes	Asbestos	Strongly Presumed	1536		RHS	westinghouse box					
40584	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1540		RHS	Cables, (3) 1 x 10mm, 2 x 30mm, 1 x 20mm, (4) 1 x 40mm green, 1 x 20mm green					
40583	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1540		RHS	Cables, 1, 8 x 10mm Ø green, (2) 1 x 15mm yellow, 1 x 20mm green. 10 approx					
39438	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Wrap	Asbestos	Surveyed – Not Detected	1540		RHS	Cables Wrap, 1, cloth wrap, 2 cloth wrap, 3, free 4, 4x PVC - 2021 reinspection - wrap NAD					



Hazardous Material Asset Register - Summary



D232-P - PIC Line - Hatton Cross to Heathrow Terminals 2&3

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40580	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1540		RHS	Cables, 8 x 10mm – top hanger		8			
39472	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1540		RHS	Cables, 1x 40mm, 1 x 20mm - 4th		2			
40581	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1540		RHS	Cables, 1 x 10mm, 1 x 20mm - 2nd Hanger					
40582	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1540		RHS	Cables, 2 x 10mm, 1 x 20mm, 1 x 10mm		4			
40585	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1575			Cables, From (3) 1 x 30mm Ø go in and out of box					
39735	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed	1575			Box					
39439	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Westinghouse Boxes	Asbestos	Strongly Presumed	1578			westinghouse box					
40586	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1578			Cables, From (1) 1 x 10mm Ø white into /out Westinghouse Box					
40587	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1605			Cables, 15m yellow to connector to and from (2)					
40588	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1716			Cables, Green 40m to connector to and from					
40669	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed	1744		RHS	Signal Box					
40668	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1744		RHS	Cables, 6 x 10mm Ø green +1 x 5 go to box					
40667	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1744		LHS	Cables, 1m green 10m Ø between 10 core and RGT					
40670	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1745		RHS	Cables, 1 x 10mm Ø green to gev					
39784	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed	1748			Box					
40676	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1748		RHS	Cable, 1 x 10mm white to box					
40678	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed	1749		RHS	Box					
40677	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1749		RHS	Cable, 6mm					
40683	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1751		RHS	Cables, 4 x 10 +1 x 5 to Westinghouse relay case					



Hazardous Material Asset Register - Summary



D232-P - PIC Line - Hatton Cross to Heathrow Terminals 2&3

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39447	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Westinghouse Boxes	Asbestos	Strongly Presumed	1751		RHS	Westinghouse relay case					
40685	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed	1765		RHS	Box					
40684	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1765		RHS	Cables, 30mm Ø white to and from hanger 3 to box					
40686	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1770		RHS	Cables, (1) 9 x 10mm Ø 3 white 6 glass, (2) 1 x 15mm Ø yellow 1 x 20mm					
39448	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed	1852		RHS	Box					
39983	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1852		RHS	Cables, 1 x 10mm white into/out Westinghouse from (3)					
40689	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1890		LHS	Cables, 1 x 20mm Ø starts from box goes to hanger 1					
40690	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed	1890		LHS	Box					
40772	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1890		RHS	Cables, (1) 3 white 8 green (2) 1 x 15mm yellow, 1 x 20mm white					
39449	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1892		LHS	Cables, Cable going hanger 1 to hanger 3 just after loop					
40692	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1892		LHS	Cables, Loop of white cable around J Hangers					
40775	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed	1923			Box					
40774	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1923			Cables, 1 x 10mm from (3) to TDBH 25m					
40777	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed	1932			Box					
40776	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1932			Cables, 1 x 10mm green to TDB from (1)					
40778	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1935			Cables, 2 x 5mm Ø					
40779	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1937		RHS	Cables, 1 x 10mm to TDB					
40780	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed	1937		RHS	Box					
40781	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1938		LHS	Cables, 2 x 30mm Ø white, 3 x 10mm green, 1 x 10mm with OTX to lower					



Hazardous Material Asset Register - Summary



D232-P - PIC Line - Hatton Cross to Heathrow Terminals 2&3

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40784	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1940		LHS	Cables, 2 x 10mm green cut					
40782	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1940		RHS	Cables, hangers too full to count					
39788	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1940		LHS	Cables, 2 x 30, 1 x 10, 1 x 20 go on					
40785	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1942		RHS	Cables, 1 x 10mm JH 1					
40788	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed	1945			Box					
40787	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1945			Cables, Also 10mm cables to box					
40786	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1945		RHS	Cables, W of PNT5BN 1 x 30mm white, 1 x 10mm green, 1 x 5mm 5 to points counting					
40789	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1950		LHS	Cables, 1 x 20mm white still on hanger 3					
39479	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1951		LHS	Cables, 1 x 10mm white to TT wires					
40791	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1960		RHS	Cables, Asbestos cables rise onto gantry					
40792	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1981		LHS	Cables, 1 x 10mm green TDB off (5)					
40793	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed	1981		LHS	Box					
39480	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed	1984		LHS	Box					
40794	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1984		LHS	Cables, 1 x 30mm ends in box from (5)					
40797	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed	1990		LHS	Box					
40796	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1990		LHS	Cables, 1 x 10mm to TDB goes to (5)					
40877	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed	1992		LHS	Box					
40798	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1992		LHS	Cables, 1 x 30mm white +7 x 10mm green, +1 x 15mm go to 10 core box from (7)					
39993	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	1993		LHS	Cables, 2 x 10mm green on No.5, and 1 x 20mm on 3 counting as above					



Hazardous Material Asset Register - Summary



D232-P - PIC Line - Hatton Cross to Heathrow Terminals 2&3

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40879	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Track Section Switches	Asbestos	Removed	2020		RHS	Current Rail Switches 847/847A. Asbestos panels removed by Edenbeck ES9541a					
40880	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	2022		LHS	Cables, 1 x 10mm green from TT to (5)					
40883	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed	2030		RHS	box					
40886	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	2030		RHS	Cables, Also 2 x 10 to JH 4					
40885	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed	2030		RHS	box					
40884	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	2030		RHS	Cables, Then 8 x 10mm 1 x 30mm +1 x 5 to right hand side box					
40882	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	2030		RHS	Cables, 2 x 30mm white +1 x 10 green +1 x 5mm to left hand side box					
40887	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	2035			Cables, 1 x 10mm to JH 2					
40888	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	2038		LHS	Cables, 2 x 10mm, 1 x 20 grey OTX from (5)					
40889	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	2038		LHS	Cables, 1 x 20mm white in (3)					
40890	INACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Removed	2045		RHS	Cables, Relay Box and cable (6mm)- 2021 REINSPECTION CONFIRMED REMOVED.					
39792	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed	2045		RHS	Relay Box					
40892	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed	2046		RHS	Relay Box					
40891	INACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Removed	2046		RHS	Cable, Relay Box and cable (6mm) - 2021 REINSPECTION CONFIRMED REMOVED					
40893	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	2050		RHS	Cables, 1 x 30mm white to box +3 green, to/from (2)					
40894	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	2052		RHS	Cables, 3x green 40 in air main link box					
39488	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed	2052		RHS	box					
40895	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	2053		RHS	Cables, 1 x 10 G					
40897	ACTIVE	P	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed	2054		RHS	Box					



Hazardous Material Asset Register - Summary



D232-P - PIC Line - Hatton Cross to Heathrow Terminals 2&3

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40896	ACTIVE	p	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	2054		RHS	Cables, 2 x 10W + 1 x 5 to 10 core box					
40899	ACTIVE	p	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed	2055		RHS	Box					
40898	ACTIVE	p	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	2055		RHS	Cables, 1 x 10mm to box					
40900	ACTIVE	p	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Signal Boxes	Asbestos	Strongly Presumed	2056		RHS	Box					
39489	ACTIVE	p	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	2056		RHS	Cables, 4 x 10 G/W + 2 x 5m to relay case					
40901	ACTIVE	p	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	2059		RHS	Cables, 2 x 5mm disconnecter box					
40902	ACTIVE	p	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	2059		RHS	Cables, On cable encapsulate					
39994	ACTIVE	p	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	2060		LHS	Cables, 20mm white cable in conduit clips					
40903	ACTIVE	p	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	2064		RHS	Cables, Cables encapsulated all go into relay room and inverts. Encapsulated during recent remedial works by FEL					
40982	ACTIVE	p	D232-P-WBLO	Road WBLO - PIC - Hatton Cross to Heathrow T2&3	Cable Sheath	Asbestos	Known	2065		RHS	Cables, Cut 10m cable – JH 3/4					

D233-P - PIC Line - Heathrow Terminals 123 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42727	ACTIVE	p	D233-P-EBLO	Road EBLO (Plt2) - PIC - Heathrow T2&3 Stn	Pit Blocks	Asbestos	Presumed				Pit blocks presumed					
42726	ACTIVE	p	D233-P-WBLO	Road WBLO (Plt1) - PIC - Heathrow T2&3 Stn	Pit Blocks	Asbestos	Presumed				Pit blocks presumed					

D234-P - PIC Line - Heathrow Terminals 2&3 to Heathrow Terminal 4

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44198	ACTIVE	p	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3		Asbestos	Sampled – Not Detected				Corrugated cement, Ceiling panels 8m2				N	N
44231	ACTIVE	p	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	2	3620	RHS	Westinghouse Large Box Flash Guard - Tunnel Floor					
44199	ACTIVE	p	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Inter-Station Isolator Switches	Asbestos	Presumed	4		RHS	Signal WY390 - Flash Guard 0.10m2					



Hazardous Material Asset Register - Summary



D234-P - PIC Line - Heathrow Terminals 2&3 to Heathrow Terminal 4

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44200	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	5		RHS	Westinghouse Large Box Flash Guards Tunnel Floor		1			
44201	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	6		RHS	Westinghouse Large Box Flash Guards - Tunnel Floor		2			
44202	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Track Section Switches	Asbestos	Removed	16		RHS	875 Track Section Switch Asbestos panels removed by Edenbeck ES9541a 17/01/2018					
44203	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3		Asbestos	Sampled – Not Detected				Loose Tunnel ring packing - Tunnel Floor 1m2				N	N
44204	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	130		RHS	Westinghouse Small Box Flash Guards - Tunnel Floor		2			
44205	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	310		RHS	Westinghouse Small Box Flash Guards - Tunnel Floor		2			
44206	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Inter-Station Isolator Switches	Asbestos	Presumed	860		RHS	Signal R386 - Flash Guard - Tunnel Floor 0.10m2					
44207	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	862		RHS	Westinghouse Small Box Flash Guards - Tunnel Floor		2			
44208	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Inter-Station Isolator Switches	Asbestos	Presumed	1100		RHS	Signal A386 - Flash Guards 0.10m2- Tunnel Floor					
44209	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	1102		RHS	Westinghouse Large Box Flash Guards - Tunnel Floor		1			
44210	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	1104		RHS	Westinghouse Small Box Flash Guards - Tunnel Floor		2			
44211	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	1106		RHS	Westinghouse Large Box Flash Guards - Tunnel Floor		3			
44212	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	1380		RHS	Westinghouse Small Box Flash Guards - Tunnel Floor		2			
44213	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	1800		RHS	Westinghouse Small Box Flash Guards - Tunnel Floor		2			
44214	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Inter-Station Isolator Switches	Asbestos	Presumed	1800		RHS	Signal A382 - Flash Guards 0.10m2 - Tunnel Floor		2			
44233	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	2180		RHS	Westinghouse Large Box Flash Guard - Tunnel Floor		1			
44215	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	2180		RHS	Westinghouse Small Box Flash Guard - Tunnel Floor					
44234	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	2210		RHS	Westinghouse Small Box Flash Guard		2			
44216	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	2212		RHS	Westinghouse Large Box Flash Guard - Tunnel Floor		3			



Hazardous Material Asset Register - Summary



D234-P - PIC Line - Heathrow Terminals 2&3 to Heathrow Terminal 4

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44217	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	2600		RHS	Westinghouse Small Box Flash Guard - Tunnel Floor		2			
44218	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Inter-Station Isolator Switches	Asbestos	Presumed	3000		RHS	Signal RWY100 - Flash Guards 0.10m2 - Tunnel Floor					
44219	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	3002		RHS	Westinghouse Small Box Flash Guard - Tunnel Floor					
44220	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Inter-Station Isolator Switches	Asbestos	Presumed	3250		RHS	Signal WY100 - Flash Guards 0.10m2 - Tunnel Floor					
44221	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	3251		RHS	Westinghouse Large Box Flash Guard - Tunnel Floor		2			
44222	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Inter-Station Isolator Switches	Asbestos	Presumed	3253		LHS	Signal RWY1 - Flash Guards 0.10m2 - Tunnel Floor					
44223	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	3254		RHS	Westinghouse Small Box Flash Guard - Tunnel Floor		2			
44224	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Inter-Station Isolator Switches	Asbestos	Presumed	3255		LHS	Rail Gap Repeater box - Flash Guards 0.10m2 - Tunnel Floor					
44225	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	3256		RHS	Westinghouse Large Box Flash Guard - Tunnel Floor		3			
44226	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Inter-Station Isolator Switches	Asbestos	Presumed	3490		LHS	Signal WY1 - Flash Guards 0.10m2 - Tunnel Floor					
44227	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	3491		RHS	Westinghouse Large Box Flash Guard - Tunnel Floor		1			
44228	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	3494		RHS	Westinghouse Small Box Flash Guard - Tunnel Floor		2			
44229	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Inter-Station Isolator Switches	Asbestos	Presumed	3495		LHS	Rail Gap Repeater Box - Flash Guard 0.10m2 - Tunnel Floor					
44230	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	3605		RHS	Westinghouse Small Box Flash Guard - Tunnel Floor		2			
44232	ACTIVE	P	D234-P-SLLO	Road SLLO - PIC - Heathrow T4 to Heathrow T2&3	Durasteel	Asbestos	Surveyed – Not Detected	3800		RHS	Durasteel surround to fire escape 40m2 - Tunnel Floor					

D235-P - PIC Line - Heathrow Terminal 4 Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42728	ACTIVE	P	D235-P-SLLO	Road SLLO - PIC - Heathrow Terminal 4 Stn	Pit Blocks	Asbestos	Surveyed – Not Detected				Pit blocks Concrete booted - Non asbestos					



Hazardous Material Asset Register - Summary



D236-P - PIC Line - Heathrow Terminal 4 to Hatton Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44235	ACTIVE	P	D236-P-SLLO	Road SLLO - PIC - Hatton Cross to Heathrow Terminal 4	Signal Boxes	Asbestos	Presumed	0		LHS	Signal WW9, Woven Material presumed 0.1m2 - Tunnel Floor					
44237	ACTIVE	P	D236-P-SLLO	Road SLLO - PIC - Hatton Cross to Heathrow Terminal 4	Westinghouse Boxes	Asbestos	Presumed	3		LHS	Westinghouse Large Box Flash Guards - Tunnel Floor Notes from 2022 re-inspection: 4x LWH not 3 LWH		3			
44236	ACTIVE	P	D236-P-SLLO	Road SLLO - PIC - Hatton Cross to Heathrow Terminal 4	Other Electrical Boxes	Asbestos	Presumed	3		LHS	Woven material, rail Gap Indicator 0.10m2 - Tunnel Floor					
44238	ACTIVE	P	D236-P-SLLO	Road SLLO - PIC - Hatton Cross to Heathrow Terminal 4	Other Boarding	Asbestos	Sampled – Not Detected				Boarding, Insulation 8m2, Insulation Boarding to Equipment Room		12		N	N
44239	ACTIVE	P	D236-P-SLLO	Road SLLO - PIC - Hatton Cross to Heathrow Terminal 4	Cable Sheath	Asbestos	Known	12		RHS	Cloth, cable Sheath x4 - x4-28 Linear m - Tunnel Floor		40			
44240	ACTIVE	P	D236-P-SLLO	Road SLLO - PIC - Hatton Cross to Heathrow Terminal 4	Westinghouse Boxes	Asbestos	Presumed	15		RHS	Westinghouse Small Box Flash Guards - Tunnel Floor		2			
44241	ACTIVE	P	D236-P-SLLO	Road SLLO - PIC - Hatton Cross to Heathrow Terminal 4	Westinghouse Boxes	Asbestos	Presumed	16		RHS	Westinghouse Large Box Flash Guards - Tunnel Floor		1			
44242	INACTIVE	P	D236-P-SLLO	Road SLLO - PIC - Hatton Cross to Heathrow Terminal 4	Isolator Switches	Asbestos	Removed				630 DC Volt switches - cement guard surround 2m2 - Tunnel Floor Notes from 2022 re-inspection: Removed now wooden panels				N	N
44243	ACTIVE	P	D236-P-SLLO	Road SLLO - PIC - Hatton Cross to Heathrow Terminal 4	Westinghouse Boxes	Asbestos	Presumed	28		RHS	Westinghouse Large Box Flash Guards - Tunnel Floor		1			
44244	ACTIVE	P	D236-P-SLLO	Road SLLO - PIC - Hatton Cross to Heathrow Terminal 4	Westinghouse Boxes	Asbestos	Known	32		RHS	Westinghouse Large Box Flash Guards - Tunnel Floor		1			
44245	ACTIVE	P	D236-P-SLLO	Road SLLO - PIC - Hatton Cross to Heathrow Terminal 4	Cable Sheath	Asbestos	Known	40		LHS	Cloth - Cable Sheath, 20 linear m - Tunnel Floor					
44246	ACTIVE	P	D236-P-SLLO	Road SLLO - PIC - Hatton Cross to Heathrow Terminal 4	Cable Sheath	Asbestos	Known	90		RHS	Cloth, Cable sheath - 5 linear m - Tunnel Floor		95			
44249	ACTIVE	P	D236-P-SLLO	Road SLLO - PIC - Hatton Cross to Heathrow Terminal 4	Westinghouse Boxes	Asbestos	Presumed	110		RHS	Westinghouse Small Box Flash Guards - Tunnel Floor		2			
44250	ACTIVE	P	D236-P-SLLO	Road SLLO - PIC - Hatton Cross to Heathrow Terminal 4		Asbestos	Sampled – Not Detected				Panels 0.1m2 at end of floor gullies - Tunnel Floor - UTX				N	N
44251	ACTIVE	P	D236-P-SLLO	Road SLLO - PIC - Hatton Cross to Heathrow Terminal 4	Westinghouse Boxes	Asbestos	Presumed	540		RHS	Westinghouse Small Box Flash Guards - Tunnel Floor		2			
44252	ACTIVE	P	D236-P-SLLO	Road SLLO - PIC - Hatton Cross to Heathrow Terminal 4	Westinghouse Boxes	Asbestos	Presumed	1000		RHS	Westinghouse Small Box Flash Guards - Tunnel Floor		2			
44253	ACTIVE	P	D236-P-SLLO	Road SLLO - PIC - Hatton Cross to Heathrow Terminal 4	Isolator Switches	Asbestos	Presumed				Signal A384A Flash Guards - Tunnel Floor				N	N
44254	ACTIVE	P	D236-P-SLLO	Road SLLO - PIC - Hatton Cross to Heathrow Terminal 4	Westinghouse Boxes	Asbestos	Presumed	1401		RHS	Westinghouse Large Box Flash Guards - Tunnel Floor		2			



Hazardous Material Asset Register - Summary



D236-P - PIC Line - Heathrow Terminal 4 to Hatton Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44255	ACTIVE	p	D236-P-SLLO	Road SLLO - PIC - Hatton Cross to Heathrow Terminal 4	Westinghouse Boxes	Asbestos	Presumed	1410		RHS	Westinghouse Small Box Flash Guards - Tunnel Floor		1			
44256	ACTIVE	p	D236-P-SLLO	Road SLLO - PIC - Hatton Cross to Heathrow Terminal 4	Westinghouse Boxes	Asbestos	Presumed	1414		RHS	Westinghouse Small Box Flash Guards - Tunnel Floor		1			
44257	ACTIVE	p	D236-P-SLLO	Road SLLO - PIC - Hatton Cross to Heathrow Terminal 4	Isolator Switches	Asbestos	Presumed				Signal A394B Flash Guards - Tunnel Floor				N	N
44258	ACTIVE	p	D236-P-SLLO	Road SLLO - PIC - Hatton Cross to Heathrow Terminal 4	Westinghouse Boxes	Asbestos	Presumed	1641		RHS	Westinghouse Large Box Flash Guards - Tunnel Floor		1			
44259	ACTIVE	p	D236-P-SLLO	Road SLLO - PIC - Hatton Cross to Heathrow Terminal 4	Westinghouse Boxes	Asbestos	Presumed	1643		RHS	Westinghouse Small Box Flash Guards - Tunnel Floor		1			
44260	ACTIVE	p	D236-P-SLLO	Road SLLO - PIC - Hatton Cross to Heathrow Terminal 4	Westinghouse Boxes	Asbestos	Presumed	1648		RHS	Westinghouse Small Box Flash Guards - Tunnel Floor		1			
44261	INACTIVE	p	D236-P-SLLO	Road SLLO - PIC - Hatton Cross to Heathrow Terminal 4	Track Section Switches	Asbestos	Removed	1720		RHS	874 A&B Track Section Switch Asbestos panels removed by Edenbeck ES9541a 17/01/2018					
44262	ACTIVE	p	D236-P-SLLO	Road SLLO - PIC - Hatton Cross to Heathrow Terminal 4	Westinghouse Boxes	Asbestos	Presumed	1724		RHS	Westinghouse Small Box Flash Guards - Tunnel Floor		1			

D238-P - PIC Line - Heathrow Terminals 2&3 to Heathrow Terminal 5

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
67583	ACTIVE	p	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Cellactite Sheeting	Asbestos	Known			RHS	CELLACTITE TO UPPER WALLS (BEFORE PLATFORM 2 EB / TW) - TUNNEL RINGS 1-5 - TOTAL 6M2	6		R724977		
67582	ACTIVE	p	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Tunnel Ring Caulking	Asbestos	Known				CAULKING - TO TUNNEL RING FLANGES ON BOTH SIDES LHS RHS - (BEFORE PLATFORM 2 EB / TW) THROUGHOUT TUNNEL RING 1-9			R724977		
67544	ACTIVE	p	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Other Electrical Boxes	Asbestos	Presumed	3670		RHS	EP VALVES - TO WALL - 2No		2	R724977		
67546	ACTIVE	p	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Other Electrical Boxes	Asbestos	Presumed	3671			EP VALVE - TO WALL - 1No		1	R724977		
67545	ACTIVE	p	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Other Electrical Boxes	Asbestos	Presumed	3673			CTB BOX - TO WALL 1No		1	R724977		
67547	ACTIVE	p	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	3674			LARGE WESTINGHOUSE BOX - TO WALL No1		1	R724977		
67548	ACTIVE	p	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	3678			LARGE WESTINGHOUSE BOX - TO WALL - 1No		1	R724977		
67549	ACTIVE	p	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	3760		RHS	SMALL WESTINGHOUSE BOX - TO WALL - 1No		1	R724977		
67550	ACTIVE	p	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Other Electrical Boxes	Asbestos	Presumed	3761		RHS	TT BOX - TO WALL - 1No		1	R724977		



Hazardous Material Asset Register - Summary



D238-P - PIC Line - Heathrow Terminals 2&3 to Heathrow Terminal 5

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
67565	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Other Electrical Boxes	Asbestos	Presumed	3776		RHS	SMALL WESTINGHOUSE BOX - TO WALL - 1No		1	R724977		
67551	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Other Electrical Boxes	Asbestos	Presumed	3805		RHS	TT BOX - TO WALL - 1No		1	R724977		
67552	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Other Electrical Boxes	Asbestos	Presumed	3830		LHS	CTB BOX - TO WALL - 1No		1	R724977		
67553	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Other Electrical Boxes	Asbestos	Presumed	3831		LHS	CTB BOX		1	R724977		
67554	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Other Electrical Boxes	Asbestos	Presumed	3834		RHS	CT BOX - TO WALL - 1No		1	R724977		
67555	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Other Electrical Boxes	Asbestos	Presumed	3836		LHS	KIOSK - TO FLOOR - 1 No			R724977		
67557	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Other Electrical Boxes	Asbestos	Presumed	3837		LHS	CTB BOX - TO WALL - 1No		1	R724977		
67556	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Other Electrical Boxes	Asbestos	Presumed	3837		LHS	CTB BOX - TO WALL - 1No		1	R724977		
67558	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Other Electrical Boxes	Asbestos	Presumed	3850	3856	RHS	CTB BOX - TO WALL - 8No		8	R724977		
67561	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Other Electrical Boxes	Asbestos	Presumed	3870		RHS	CTB BOX - TO - WALL - 1No		1	R724977		
67562	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Other Electrical Boxes	Asbestos	Presumed	3871		RHS	SIGNAL WY2A & RWY2B - 2No		2	R724977		
67563	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Other Electrical Boxes	Asbestos	Presumed	3872		RHS	EP VALVE - TO WALL - 1No		1	R724977		
67564	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	3876		RHS	LARGE WESTINGHOUSE BOX - TO WALL - 1No		1	R724977		
67566	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Signal Boxes	Asbestos	Presumed	4110		RHS	SIGNAL WY2B - TO WALL - 1No		1	R724977		
67569	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Other Electrical Boxes	Asbestos	Presumed	4110		RHS	EP VALVE - TO WALL 1No		1	R724977		
67568	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Other Electrical Boxes	Asbestos	Presumed	4110		RHS	10 CORE BOX - TO WALL - 1No		1	R7244977		
67567	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	4110		RHS	LARGE WESTINGHOUSE BOX - TO WALL - 1No		1	R724977		
67570	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	4118			SMALL WESTINGHOUSE BOX - TO WALL - 1No		1	R724977		
67571	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Other Electrical Boxes	Asbestos	Presumed	4120			SMALL WESTINGHOUSE BOX - TO WALL -		1	R724977		



Hazardous Material Asset Register - Summary



D238-P - PIC Line - Heathrow Terminals 2&3 to Heathrow Terminal 5

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
67576	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	4180		RHS	LARGE WESTINGHOUSE BOX - TO WALL - 1No		1	R724977		
67575	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Other Electrical Boxes	Asbestos	Presumed	4180		RHS	10 CORE BOX - TO WALL - 1No		1	R724977		
67574	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Other Electrical Boxes	Asbestos	Presumed	4180			EP VALVE - TO WALL - 1 No		1	R724977		
67573	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Other Electrical Boxes	Asbestos	Presumed	4180			TYPE 7C BOX - TO WALL - No1		1	R724977		
67572	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Other Electrical Boxes	Asbestos	Presumed	4180			SMALL WESTINGHOUSE BOX - TO WALL - 1No		1	R724977		
67577	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	4181		RHS	SMALL WESTINGHOUSE BOXES - TO WALL - 2No		1	R724977		
67578	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Westinghouse Boxes	Asbestos	Presumed	4182		RHS	SMALL WESTINGHOUSE BOX -TO WALL - 1No		1	R724977		
67579	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Signal Boxes	Asbestos	Presumed	4182		RHS	SIGNAL LAMP - TO WALL 1No		1	R724977		
67581	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Cable Sheath	Asbestos	Known	4200		RHS	BRAIDED CABLE - TO J HANGER - 2No		2	R724977		
67580	ACTIVE	P	D238-P-EBLO	Road EBLO - PIC - Heathrow Terminal 5 to Heathrow T2&3	Tunnel Ring Caulking	Asbestos	Known	4201	4210	RHS	CAULKING COATING MATERIAL - TO TUNNEL RING - THROUGHOUT			R724977		
67542	ACTIVE	P	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Tunnel Ring Caulking	Asbestos	Known	0	5	LHS	FIBROUS CAULKING MATERIAL - TUNNEL RING PAN, to TUNNEL RING 3 - 1M2 (AND ASSOCIATED DEBRIS)	1		R724976		
67543	ACTIVE	P	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Cellactite Sheeting	Asbestos	Presumed	0	3	LHS	CELLACTITE - TO UPPER WALLS 6 M2 - 0-3M - TUNNEL RING 1-5 -	6		R724976		
67541	ACTIVE	P	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Tunnel Ring Caulking	Asbestos	Known	0	5		TO TUNNEL RING FLANGES ON BOTH SIDES - CAULKING - THROUGHOUT - TUNNEL RINGS 1-9 - PLATFORM 1 WESTBOUND WE/WH			R724976		
67511	ACTIVE	P	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Tunnel Ring Caulking	Asbestos	Known	0	8	RHS	CAULKING - TO METAL TUNNEL RING FLANGES - THROUGHOUT - PLATFORM 1 WESTBOUND WE/HW			R724976		
67510	ACTIVE	P	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Cable Sheath	Asbestos	Known	0	9	RHS	BRAIDED CABLES - J HANGER - 2 X 1 NO		2	R724976		
67509	ACTIVE	P	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Ducts	Asbestos	Known	2		LHS	BITUMEN CABLE DUCTS - TO CONCRETE CABLE SLAB - 6no		6	R724976		
67515	ACTIVE	P	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Westinghouse Boxes	Asbestos	Presumed	8		RHS	SMALL WESTINGHOUSE BOX - TO WALL - 1No		1	R724976		
67516	ACTIVE	P	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Signal Boxes	Asbestos	Presumed	9			SIGNAL - TO WALL - 1No		1	R724976		



Hazardous Material Asset Register - Summary



D238-P - PIC Line - Heathrow Terminals 2&3 to Heathrow Terminal 5

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
67517	ACTIVE	P	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Westinghouse Boxes	Asbestos	Presumed	10		RHS	SMALL WESTINGHOUSE BOX - TO WALL - 1No		1	R724976		
67518	ACTIVE	P	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Westinghouse Boxes	Asbestos	Presumed	11		RHS	SMALL WESTINGHOUSE BOX - TO WALL - 1No		1	R724976		
67519	ACTIVE	P	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Other Electrical Boxes	Asbestos	Presumed	12		RHS	EP VALVE - TO WALL - 1No		1	R724976		
67521	ACTIVE	P	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Other Electrical Boxes	Asbestos	Presumed	13		RHS	10 CORE BOX - TO WALL -1No		1	R724976		
67520	ACTIVE	P	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Westinghouse Boxes	Asbestos	Presumed	13		RHS	LARGE WESTINGHOUSE BOX - TO WALL - 1No		1	R724976		
67525	ACTIVE	P	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Other Electrical Boxes	Asbestos	Presumed	14			CTB BOX - TO WALL - 1No		1	R724976		
67523	ACTIVE	P	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Westinghouse Boxes	Asbestos	Presumed	14		RHS	SMALL WESTINGHOUSE BOX - TO WALL - 1No		1	R724976		
67522	ACTIVE	P	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Westinghouse Boxes	Asbestos	Presumed	14		RHS	SMALL WESTINGHOUSE BOX - TO WALL - 1No		1	R724976		
67526	ACTIVE	P	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Other Electrical Boxes	Asbestos	Presumed	16		RHS	RAIL GAP INDICATOR - TO WALL 1No		1	R724976		
67527	ACTIVE	P	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Westinghouse Boxes	Asbestos	Presumed	260		RHS	SMALL WESTINGHOUSE BOX - TO WALL - 1 No		1	R724976		
67528	ACTIVE	P	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Westinghouse Boxes	Asbestos	Presumed	262		RHS	SMALL WESTINGHOUSE BOXES - TO WALL - 1No		2	R724976		
67529	ACTIVE	P	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Signal Boxes	Asbestos	Presumed	320		RHS	TYPE 7A BOX - TO WALL - No1		1	R724976		
67530	ACTIVE	P	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Other Electrical Boxes	Asbestos	Presumed	320		RHS	CTB BOX - TO WALL - No1		1	R724976		
67531	ACTIVE	P	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Other Electrical Boxes	Asbestos	Presumed	340		RHS	KIOSK - TO WALL No1		1	R724976		
67532	ACTIVE	P	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Other Electrical Boxes	Asbestos	Presumed	340		RHS	CTB BOX - TO WALL - No1		1	R724976		
67533	ACTIVE	P	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Other Electrical Boxes	Asbestos	Presumed	345		RHS	CTB BOXES - TO WALL - 2No		2	R724976		
67534	ACTIVE	P	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Other Electrical Boxes	Asbestos	Presumed	480		RHS	SMALL WESTINGHOUSE BOXES - TO WALL - No2		2	R724976		
67535	ACTIVE	P	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Other Electrical Boxes	Asbestos	Presumed	481		LHS	TT BOX - TO WALL - No1		1	R724976		
67536	ACTIVE	P	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Westinghouse Boxes	Asbestos	Presumed	540		LHS	LARGE WESTINGHOUSE BOX - TO WALL -1No		1	R724976		



Hazardous Material Asset Register - Summary



D238-P - PIC Line - Heathrow Terminals 2&3 to Heathrow Terminal 5

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
67540	ACTIVE	p	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Other Electrical Boxes	Asbestos	Presumed	542		LHS	EP VALVES - TO WALL - 1No		1			
67537	ACTIVE	p	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Westinghouse Boxes	Asbestos	Presumed	543		LHS	LARGE WESTINGHOUSE BOX - TO WALL - No1		1	R724976		
67538	ACTIVE	p	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Signal Boxes	Asbestos	Presumed	544		LHS	CTB - TO WALL - 1No		1	R724976		
67539	ACTIVE	p	D238-P-WBLO	Road WBLO - PIC - Heathrow T2&3 to Heathrow Terminal 5	Other Electrical Boxes	Asbestos	Presumed	545		LHS	EP VALVE - TO WALL - 1No		1	R724976		

N107-P - PIC Line - Leicester Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
54019	ACTIVE	p	N107-P-EBLO	Road EBLO (Plt2) - PIC - Leicester Square Stn	Westinghouse Boxes	Asbestos	Presumed	35			Westinghouse small box small		1			
38361	ACTIVE	p	N107-P-EBLO	Road EBLO (Plt2) - PIC - Leicester Square Stn	Westinghouse Boxes	Asbestos	Strongly Presumed	69			Trackside equipment: Westinghouse small box		1			
38362	ACTIVE	p	N107-P-EBLO	Road EBLO (Plt2) - PIC - Leicester Square Stn	Westinghouse Boxes	Asbestos	Strongly Presumed	74			Trackside equipment: Westinghouse small box		1			
54020	ACTIVE	p	N107-P-EBLO	Road EBLO (Plt2) - PIC - Leicester Square Stn	Other Electrical Boxes	Asbestos	Presumed	76			10 core		1			
38363	ACTIVE	p	N107-P-EBLO	Road EBLO (Plt2) - PIC - Leicester Square Stn	Signal Boxes	Asbestos	Strongly Presumed	98			630 DR electrical box		1			
38360	ACTIVE	p	N107-P-WBLO	Road WBLO (Plt1) - PIC - Leicester Square Stn	Westinghouse Boxes	Asbestos	Presumed				Trackside equipment: Westinghouse small box					
46175	ACTIVE	p	N107-P-WBLO	Road WBLO (Plt1) - PIC - Leicester Square Stn	Cable Sheath	Asbestos	Known				Woven cable 9 X 2m trackside (head wall)	2	9			
46174	ACTIVE	p	N107-P-WBLO	Road WBLO (Plt1) - PIC - Leicester Square Stn		Asbestos	Strongly Presumed				Woven cable 2 X 8M on W/B left hand side wall	8	2		N	N

N123-P - PIC Line - Kings Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42758	ACTIVE	p	N123-P-EBLO	Road EBLO (Plt6) - PIC - Kings Cross Stn	Pit Blocks	Asbestos	Removed				Pit blocks - Non asbestos (Removed by Forest)					
40200	ACTIVE	p	N123-P-EBLO	Road EBLO (Plt6) - PIC - Kings Cross Stn	Westinghouse Boxes	Asbestos	Presumed				Westinghouse Boxes Notes from 2022 re-inspection: 4 x SWH		4			
38409	ACTIVE	p	N123-P-EBLO	Road EBLO (Plt6) - PIC - Kings Cross Stn	Signal Boxes	Asbestos	Presumed				Trackside equipment: Westinghouse small box					



Hazardous Material Asset Register - Summary



N123-P - PIC Line - Kings Cross Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42756	ACTIVE	P	N123-P-WBLO	Road WBLO (Plt5) - PIC - Kings Cross Stn	Pit Blocks	Asbestos	Removed				Pit blocks - Non asbestos (Removed by Forest Jun 2003)					
40201	ACTIVE	P	N123-P-WBLO	Road WBLO (Plt5) - PIC - Kings Cross Stn	Westinghouse Boxes	Asbestos	Presumed				Westinghouse Boxes Notes from 2022 re-inspection: 2 x SWH					
38410	ACTIVE	P	N123-P-WBLO	Road WBLO (Plt5) - PIC - Kings Cross Stn	Signal Boxes	Asbestos	Presumed				Trackside equipment: Westinghouse small box					

P011-P - PIC Line - Cockfosters Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37196	ACTIVE	P	P011-P-EBLO	Road EBLO (Plt1) - PIC - Cockfosters to Buffer	Cable Sheath	Asbestos	Strongly Presumed	0	101	LHS	Cloth. cable sheath, Entry: N/A, Route: H4 of 4, 1x40mmØ, Exit: Behind concrete hoarding into undergrowth. 1 x 100.5m					
39697	ACTIVE	P	P011-P-EBLO	Road EBLO (Plt1) - PIC - Cockfosters to Buffer	Signal Boxes	Asbestos	Presumed	7		LHS	Trackside equipment: westinghouse kiosk		1			
37198	ACTIVE	P	P011-P-EBLO	Road EBLO (Plt1) - PIC - Cockfosters to Buffer	Signal Boxes	Asbestos	Presumed	30		LHS	Trackside equipment: tencore box		1			
37197	ACTIVE	P	P011-P-EBLO	Road EBLO (Plt1) - PIC - Cockfosters to Buffer	Westinghouse Boxes	Asbestos	Presumed	30		LHS	Trackside equipment: Westinghouse small box		1			
37199	ACTIVE	P	P011-P-EBLO	Road EBLO (Plt1) - PIC - Cockfosters to Buffer	Westinghouse Boxes	Asbestos	Presumed	98		LHS	Trackside equipment: Westinghouse small box		1			
39384	ACTIVE	P	P011-P-EBLO	Road EBLO (Plt1) - PIC - Cockfosters to Buffer	Westinghouse Boxes	Asbestos	Presumed	99		LHS	Trackside equipment: Westinghouse small box		1			
37203	ACTIVE	P	P011-P-EBLO	Road EBLO (Plt1) - PIC - Cockfosters to Buffer	Cable Sheath	Asbestos	Removed	100		UTX	Cloth. cable sheath, small wire to rails. 0.25 lin Notes from 2022 re-inspection: Removed					
37200	ACTIVE	P	P011-P-EBLO	Road EBLO (Plt1) - PIC - Cockfosters to Buffer	Westinghouse Boxes	Asbestos	Presumed	100		LHS	Trackside equipment: Westinghouse small box		1			
37201	ACTIVE	P	P011-P-EBLO	Road EBLO (Plt1) - PIC - Cockfosters to Buffer	Signal Boxes	Asbestos	Presumed	100		LHS	Trackside equipment: tencore box		1			
37202	ACTIVE	P	P011-P-EBLO	Road EBLO (Plt1) - PIC - Cockfosters to Buffer	Signal Boxes	Asbestos	Presumed	100		LHS	Trackside equipment: electrical box		1			
37204	ACTIVE	P	P011-P-EBLO	Road EBLO (Plt1) - PIC - Cockfosters to Buffer	Westinghouse Boxes	Asbestos	Presumed	101		LHS	Trackside equipment: Westinghouse small box		1			
37205	ACTIVE	P	P011-P-EBLO	Road EBLO (Plt1) - PIC - Cockfosters to Buffer	Cable Sheath	Asbestos	Removed	116		UTX	Cloth. cable sheath, small wire to rails. 0.25 lin Notes from 2022 re-inspection: Removed					



Hazardous Material Asset Register - Summary



P011-P - PIC Line - Cockfosters Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37206	ACTIVE	P	P011-P-EBLO	Road EBLO (Plt1) - PIC - Cockfosters to Buffer	Signal Boxes	Asbestos	Presumed	118		LHS	Trackside equipment: signal stop		2			
37207	ACTIVE	P	P011-P-EBLO	Road EBLO (Plt1) - PIC - Cockfosters to Buffer	Cable Sheath	Asbestos	Presumed	120		UTX	Cloth. cable sheath, small wire to rails. 0.25 lin					
37208	ACTIVE	P	P011-P-SLLO	Road SLLO (Plt2/3) - PIC - Cockfosters to Buffer	Signal Boxes	Asbestos	Presumed	30		RHS	Trackside equipment: tencore box		2			
37209	ACTIVE	P	P011-P-SLLO	Road SLLO (Plt2/3) - PIC - Cockfosters to Buffer	Westinghouse Boxes	Asbestos	Removed	33		LHS	Trackside equipment: Westinghouse small box Notes from 2022 re-inspection: Removed		1			
39751	ACTIVE	P	P011-P-SLLO	Road SLLO (Plt2/3) - PIC - Cockfosters to Buffer	Westinghouse Boxes	Asbestos	Removed	33		RHS	Trackside equipment: Westinghouse small box Notes from 2022 re-inspection: Removed		1			
37210	ACTIVE	P	P011-P-SLLO	Road SLLO (Plt2/3) - PIC - Cockfosters to Buffer	Cable Sheath	Asbestos	Removed	33	34	LHS	Cloth. cable sheath, Enters: x3, Route: 3x10mmØ along floor, Exit: x1 Into duct. 3 x 1.5m Notes from 2022 re-inspection: Removed					
37211	ACTIVE	P	P011-P-SLLO	Road SLLO (Plt2/3) - PIC - Cockfosters to Buffer	Cable Sheath	Asbestos	Strongly Presumed	34	35	LHS	Cloth. cable sheath, Enters: N/A, Route: 2x10mmØ along floor, Exit: N/A. 2 x 1m					
39588	ACTIVE	P	P011-P-SLLO	Road SLLO (Plt2/3) - PIC - Cockfosters to Buffer	Ducts	Asbestos	Known	34		RHS	cement, cable duct lining		2			
37212	ACTIVE	P	P011-P-SLLO	Road SLLO (Plt2/3) - PIC - Cockfosters to Buffer	Westinghouse Boxes	Asbestos	Presumed	35		LHS	Trackside equipment: Westinghouse small box		1			
39706	ACTIVE	P	P011-P-SLLO	Road SLLO (Plt2/3) - PIC - Cockfosters to Buffer	Cable Sheath	Asbestos	Strongly Presumed	35	109	RHS	Cloth. cable sheath, Enters: x1 from Westinghouse small box, Route: 3x10mmØ along floor, Exit: x1 to Westinghouse small box. 3 x 73.5m					
54057	ACTIVE	P	P011-P-SLLO	Road SLLO (Plt2/3) - PIC - Cockfosters to Buffer	Westinghouse Boxes	Asbestos	Presumed	36		RHS	Trackside equipment: Westinghouse small box		1			
37418	ACTIVE	P	P011-P-SLLO	Road SLLO (Plt2/3) - PIC - Cockfosters to Buffer	Signal Boxes	Asbestos	Presumed	90		LHS	Trackside equipment: electrical equipment		1			
37422	ACTIVE	P	P011-P-SLLO	Road SLLO (Plt2/3) - PIC - Cockfosters to Buffer	Westinghouse Boxes	Asbestos	Presumed	109		RHS	Trackside equipment: Westinghouse small box		1			
37421	ACTIVE	P	P011-P-SLLO	Road SLLO (Plt2/3) - PIC - Cockfosters to Buffer	Cable Sheath	Asbestos	Strongly Presumed	109	109	RHS	Cloth. cable sheath, Enters: N/A, Route: 2x10mmØ along floor, Exit: x1 to Westinghouse small box. 2 x 0.5m					
37419	ACTIVE	P	P011-P-SLLO	Road SLLO (Plt2/3) - PIC - Cockfosters to Buffer	Westinghouse Boxes	Asbestos	Presumed	109		RHS	Trackside equipment: Westinghouse small box		1			
37420	ACTIVE	P	P011-P-SLLO	Road SLLO (Plt2/3) - PIC - Cockfosters to Buffer	Westinghouse Boxes	Asbestos	Presumed	109		RHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P011-P - PIC Line - Cockfosters Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37423	ACTIVE	P	P011-P-SLLO	Road SLLO (Plt2/3) - PIC - Cockfosters to Buffer	Cable Sheath	Asbestos	Strongly Presumed	109	110	RHS	Cloth. cable sheath, Enters: N/A, Route: 1x10mmØ along floor, Exit: x1 to Westinghouse small box. 1 x 1m					
37424	ACTIVE	P	P011-P-SLLO	Road SLLO (Plt2/3) - PIC - Cockfosters to Buffer	Westinghouse Boxes	Asbestos	Presumed	110		RHS	Trackside equipment: Tencore		1			
37425	ACTIVE	P	P011-P-SLLO	Road SLLO (Plt2/3) - PIC - Cockfosters to Buffer	Signal Boxes	Asbestos	Presumed	114		RHS	Trackside equipment: fixed red light		2			
37426	ACTIVE	P	P011-P-WBLO	Road WBLO (Plt4) - PIC - Cockfosters to Buffer	Cable Sheath	Asbestos	Strongly Presumed	0	1	RHS	Cloth. cable sheath, Enters: Westinghouse small box, Route: H1 of 2, 1x20mmØ, Exits: N/A. 1 X 0.5M					
37427	ACTIVE	P	P011-P-WBLO	Road WBLO (Plt4) - PIC - Cockfosters to Buffer	Westinghouse Boxes	Asbestos	Presumed	0	1	RHS	Trackside equipment: Westinghouse small box		3			
37428	ACTIVE	P	P011-P-WBLO	Road WBLO (Plt4) - PIC - Cockfosters to Buffer	Cable Sheath	Asbestos	Strongly Presumed	1	83	RHS	Cloth. cable sheath, Enters: Westinghouse small box, Route: H1 of 2, 2x20mmØ, Exits: N/A. 2 x 25m					
37429	ACTIVE	P	P011-P-WBLO	Road WBLO (Plt4) - PIC - Cockfosters to Buffer	Signal Boxes	Asbestos	Presumed	17		LHS	Trackside equipment: electric box		1			
37431	ACTIVE	P	P011-P-WBLO	Road WBLO (Plt4) - PIC - Cockfosters to Buffer	Westinghouse Boxes	Asbestos	Presumed	25		LHS	Trackside equipment: Westinghouse small box					
37430	ACTIVE	P	P011-P-WBLO	Road WBLO (Plt4) - PIC - Cockfosters to Buffer	Signal Boxes	Asbestos	Presumed	25		LHS	Trackside equipment: tencore box		1			
37432	ACTIVE	P	P011-P-WBLO	Road WBLO (Plt4) - PIC - Cockfosters to Buffer	Cable Sheath	Asbestos	Strongly Presumed	26	120	LHS	Cloth. cable sheath, Enters: Undergrowth, Route: H4, 1x40mmØ, Exits: N/A. 1 x 94.5m					
37433	ACTIVE	P	P011-P-WBLO	Road WBLO (Plt4) - PIC - Cockfosters to Buffer	Westinghouse Boxes	Asbestos	Presumed	82			Trackside equipment: Westinghouse small box LHS & RHS		1			
37434	ACTIVE	P	P011-P-WBLO	Road WBLO (Plt4) - PIC - Cockfosters to Buffer	Westinghouse Boxes	Asbestos	Presumed	83			Trackside equipment: Westinghouse small box LHS & RHS		1			
39411	ACTIVE	P	P011-P-WBLO	Road WBLO (Plt4) - PIC - Cockfosters to Buffer	Cable Sheath	Asbestos	Removed	83	84	RHS	Cloth. cable sheath, Enters: N/A, Route: H1 of 4, 1x20mmØ, Exits: Westinghouse small box. 1 x1m Notes from 2022 re-inspection: Removed					
37436	ACTIVE	P	P011-P-WBLO	Road WBLO (Plt4) - PIC - Cockfosters to Buffer	Westinghouse Boxes	Asbestos	Presumed	84			Trackside equipment: Westinghouse small box LHS & RHS		1			
37437	ACTIVE	P	P011-P-WBLO	Road WBLO (Plt4) - PIC - Cockfosters to Buffer	Cable Sheath	Asbestos	Removed	84		RHS	Cloth. cable sheath, 1x20mmØ redundant cable on floor. 1 x 1m Notes from 2022 re-inspection: Removed					
37435	ACTIVE	P	P011-P-WBLO	Road WBLO (Plt4) - PIC - Cockfosters to Buffer	Cable Sheath	Asbestos	Removed	84	87	RHS	Cloth. cable sheath, Enters: Westinghouse small box, Route: H4 of 4, 1x15mmØ, Exits: Concrete duct. 1 x 3m Notes from 2022 re-inspection: Removed					



Hazardous Material Asset Register - Summary



P011-P - PIC Line - Cockfosters Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37438	ACTIVE	P	P011-P-WBLO	Road WBLO (Plt4) - PIC - Cockfosters to Buffer	Westinghouse Boxes	Asbestos	Presumed	87	89	RHS	Trackside equipment: Westinghouse small box		2			
39812	ACTIVE	P	P011-P-WBLO	Road WBLO (Plt4) - PIC - Cockfosters to Buffer	Signal Boxes	Asbestos	Presumed	87	89	LHS	Trackside equipment: tencore box		3			
37439	ACTIVE	P	P011-P-WBLO	Road WBLO (Plt4) - PIC - Cockfosters to Buffer	Westinghouse Boxes	Asbestos	Presumed	90		RHS	Trackside equipment: Westinghouse small box		1			
37440	ACTIVE	P	P011-P-WBLO	Road WBLO (Plt4) - PIC - Cockfosters to Buffer	Signal Boxes	Asbestos	Presumed	115		LHS	Trackside equipment: westinghouse kiosk		1			

P012-P - PIC Line - Cockfosters to Oakwood

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38852	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Cable Sheath	Asbestos	Strongly Presumed	2		RHS	Cloth. cable sheath, Entry: Westinghouse large box, Route: Cleat 1, 1x40mmØ, Cleat 2, 1x40mmØ, Exit: OTX to Depot Road. 2 X 10M					
38853	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Westinghouse Boxes	Asbestos	Presumed	2		RHS	Trackside equipment: Westinghouse large box. In compound		14			
38854	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	2		RHS	Trackside equipment: tencore box. In compound		4			
38855	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	3		RHS	Trackside equipment: tencore box. In compound		1			
38856	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Westinghouse Boxes	Asbestos	Removed	3		RHS	Trackside equipment: Westinghouse small box. In compound Notes from 2022 re-inspection: Removed		1			
40050	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	6		RHS	Trackside equipment: tencore box. In compound		1			
38857	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	10		RHS	Trackside equipment: Yellow 630V		2			
38858	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	11		RHS	Trackside equipment: Point heating box		1			
38859	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	18		LHS	Trackside equipment: Yellow 630V		1			
38860	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Westinghouse Boxes	Asbestos	Presumed	46		LHS	Trackside equipment: Westinghouse large box		1			
40051	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Westinghouse Boxes	Asbestos	Presumed	56		LHS	Trackside equipment: Westinghouse large box		1			
38862	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	353		LHS	Trackside equipment: tencore box		1			



Hazardous Material Asset Register - Summary



P012-P - PIC Line - Cockfosters to Oakwood

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39457	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	353		LHS	Trackside equipment: Fog repeater		1			
38861	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	353		LHS	Trackside equipment: Signal (B923)		1			
38863	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	470		LHS	Trackside equipment: Signal (A923)		1			
54003	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Other Electrical Boxes	Asbestos	Presumed	470			Trackside equipment: Ten core box		1			
38865	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	652		LHS	Trackside equipment: tencore box		1			
38864	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	652		LHS	Trackside equipment: Fog repeater		1			
38867	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	770		LHS	Trackside equipment: Fog repeater (PM2)		1			
38866	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	770		LHS	Trackside equipment: Signal (RPM2)		1			
38868	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	770		LHS	Trackside equipment: tencore box		1			
38869	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	811		LHS	Trackside equipment: tencore box		1			
38870	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	929		LHS	Trackside equipment: tencore box		1			
38871	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	930		LHS	Signal (PM2)		1			
38872	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Westinghouse Boxes	Asbestos	Presumed	1017		LHS	Trackside equipment: Westinghouse small box		1			
38873	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Westinghouse Boxes	Asbestos	Presumed	1040		LHS	Trackside equipment: Westinghouse small box		1			
38874	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Westinghouse Boxes	Asbestos	Presumed	1047		LHS	Trackside equipment: Westinghouse small box		1			
38875	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Westinghouse Boxes	Asbestos	Presumed	1060		LHS	Trackside equipment: Westinghouse small box		1			
38876	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Westinghouse Boxes	Asbestos	Presumed	1065		LHS	Trackside equipment: Westinghouse large box		2			
39896	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Westinghouse Boxes	Asbestos	Presumed	1066		LHS	Trackside equipment: Westinghouse small box		1			
38877	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Westinghouse Boxes	Asbestos	Presumed	1080		LHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P012-P - PIC Line - Cockfosters to Oakwood

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38878	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	1081		LHS	Trackside equipment: tencore box		2			
38879	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Westinghouse Boxes	Asbestos	Presumed	1086		LHS	Trackside equipment: Westinghouse small box		1			
38880	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	1086		LHS	Trackside equipment: tencore box		3			
40052	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Westinghouse Boxes	Asbestos	Presumed	1090		LHS	Trackside equipment: Westinghouse small box		1			
38881	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	1118		RHS	Trackside equipment: Yellow 630V		2			
38882	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	1124		LHS	Trackside equipment: tencore box		1			
38883	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Cable Sheath	Asbestos	Strongly Presumed	1144	1156	LHS	Cloth. cable sheath, Entry: Westinghouse large box, Route: H4 of 8, 1x40mmØ, Exit: N/A. 1 x 12m					
38884	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Westinghouse Boxes	Asbestos	Presumed	1144		LHS	Trackside equipment: Westinghouse large box		2			
40053	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	1145		RHS	Trackside equipment: Yellow 630V		2			
38885	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	1148		LHS	Trackside equipment: tencore box		3			
39683	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Cable Sheath	Asbestos	Strongly Presumed	1156	1169	LHS	Cloth. cable sheath, Entry: N/A, Route: H4 of 4, 1x40mmØ, Exit: Platform grounds. 1 x 13m					
38889	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Cable Sheath	Asbestos	Strongly Presumed	1162		LHS	cloth. Cable sheath, Entry: Traction override switch, Route: Between trackside equipment, 4x8mmØ, Exit: Ten Core box. 4 x 1m					
40054	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	1162		LHS	Trackside equipment: Traction override switch		2			
38886	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	1162		LHS	Trackside equipment: Signal (PM35)		1			
39458	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	1162		LHS	Trackside equipment: Signal (PM34)		1			
38887	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	1162		LHS	Trackside equipment: tencore box		8			
38888	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Presumed	1162		RHS	Trackside equipment: tencore box		4			
38890	ACTIVE	P	P012-P-EBLO	Road EBLO - PIC - Oakwood to Cockfosters	Signal Boxes	Asbestos	Removed	1165		LHS	Trackside equipment: Electrical box Notes from 2022 re-inspection: Removed		1			
39388	ACTIVE	P	P012-P-SLLO	Road SLLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	53			Trackside equipment: Points heaters		1			



Hazardous Material Asset Register - Summary



P012-P - PIC Line - Cockfosters to Oakwood

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40121	ACTIVE	P	P012-P-SLLO	Road SLLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	55			Trackside equipment: Yellow 630 Volts DC		1			
40193	ACTIVE	P	P012-P-SLLO	Road SLLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	56			Trackside equipment: Westinghouse small box		1			
40194	ACTIVE	P	P012-P-SLLO	Road SLLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	57	58		Trackside equipment: Tencore box		3			
40195	ACTIVE	P	P012-P-SLLO	Road SLLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	58			Trackside equipment: Westinghouse small box		1			
40196	ACTIVE	P	P012-P-SLLO	Road SLLO - PIC - Cockfosters to Oakwood	Cement Cable Troughing & Debris	Asbestos	Strongly Presumed	61			cement debris, 0.5m					
40199	ACTIVE	P	P012-P-SLLO	Road SLLO - PIC - Cockfosters to Oakwood	Cement Cable Troughing & Debris	Asbestos	Strongly Presumed	69			cement debris, 0.5m					
40197	ACTIVE	P	P012-P-SLLO	Road SLLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	70			Trackside equipment: Signal (PM35 & 32)		1			
39723	ACTIVE	P	P012-P-SLLO	Road SLLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	70			Trackside equipment: Tencore box, below signal		4			
40198	ACTIVE	P	P012-P-SLLO	Road SLLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	70			Trackside equipment: Westinghouse small box, below signal		1			
43766	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood		Asbestos	Sampled – Not Detected				Braided cables (3 x 0.1m), within 26.29 – 33 RUS COLR box, Cess Depot Road, point 23. Leading into 30 Depot Reception Road			R438901	N	N
43765	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood		Asbestos	Sampled – Not Detected				Braided cables (2 x 0.5m), connected to Westinghouse box. Cess Depot road, point 23. Leading into 30 Depot Reception Road			R438901	N	N
39407	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	0	7	LHS	Cloth. cable sheath, Entry: Platform, Route: H4 of 4, 1x40mmØ, Exit: N/A. 1 x 7m					
43767	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood		Asbestos	Strongly Presumed				Bakelite plates (8 no.), within 26.29 – 33 RUS COLR box, Cess Depot Road, point 23. Leading into 30 Depot Reception Road			R438901	N	N
43768	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Strongly Presumed				Westinghouse box – COL.ISOL.TRANS, Cess Depot Road, point 23. Leading into 30 Depot Reception Road. (No access to box).			R438901		
37306	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	1	5	LHS	Trackside equipment: Westinghouse large box		7			
37311	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	7		RHS	Trackside equipment: tencore box		4			
37307	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	7	10	LHS	Trackside equipment: tencore box		7			
37308	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	7	20	LHS	Cloth. cable sheath, Entry: N/A, Route: H4 of 8, 1x40mmØ, Exit: N/A. 1 x 13m					



Hazardous Material Asset Register - Summary



P012-P - PIC Line - Cockfosters to Oakwood

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37309	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	7		LHS	Trackside equipment: Westinghouse large box		1			
39757	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	7		LHS	Trackside equipment: Westinghouse kiosk		1			
37310	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	7		RHS	Trackside equipment: Signal (PM36)		1			
37313	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	10		RHS	Trackside equipment: Westinghouse small box		1			
37312	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	10	11	LHS	Trackside equipment: Westinghouse small box		3			
39803	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	17		LHS	Trackside equipment: tencore box		2			
37314	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	18		LHS	Trackside equipment: Westinghouse small box		1			
37315	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	20	72	LHS	Cloth. cable sheath, Entry: N/A, Route: H4 of 8, 40mmØ, Exit: N/A. 1 x 52m					
37316	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	22		LHS	Trackside equipment: Westinghouse small box		1			
37317	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	26		LHS	Trackside equipment: Yellow 630V		2			
37319	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	27		LHS	Trackside equipment: Electrical box		1			
37318	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	27		LHS	Trackside equipment: Westinghouse small box		1			
37320	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	28		LHS	Trackside equipment: Westinghouse large box		1			
37321	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Cement Cable Troughing & Debris	Asbestos	Strongly Presumed	28			cement. cable trough, Trough runs into sidings with associated debris to floor where damaged LHS & UTX		9			
37322	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Cable Sheath	Asbestos	Presumed	72	229	LHS	Cloth. cable sheath, Entry: N/A, Route: H4 of 8, 1x40mmØ, Exit: Westinghouse kiosk. 1 x 157m					
37323	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	74		LHS	Trackside equipment: Westinghouse small box		1			
37324	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	76		LHS	Trackside equipment: tencore box		1			
37325	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	83		LHS	Trackside equipment: tencore box		1			
37326	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	87		LHS	Trackside equipment: tencore box		1			



Hazardous Material Asset Register - Summary



P012-P - PIC Line - Cockfosters to Oakwood

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37327	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	121		LHS	Trackside equipment: tencore box		2			
39702	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	131		LHS	Trackside equipment: Westinghouse small box		1			
37328	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	134		LHS	Trackside equipment: Westinghouse small box		1			
43751	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Bakerlite	Asbestos	Strongly Presumed				Bakelite plates (8 no.), within WB COLR box. W/B cess, 150m.			R438901	N	N
43749	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood		Asbestos	Sampled – Not Detected				Braided cables (3 x 0.1m), within WB COLR box. W/B cess, 150m			R438901	N	N
43748	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood		Asbestos	Sampled – Not Detected				Braided cables (2 x 0.5m), connected to Westinghouse box. W/B cess, 150m			R438901	N	N
43754	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood		Asbestos	Strongly Presumed				Bakelite plates (4 no.), within COL.ISOL.TRANS box. W/B cess, 150m			R438901	N	N
43753	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood		Asbestos	Sampled – Not Detected				Braided cables (7 no), within COL.ISOL.TRANS box. W/B cess, 150m.			R438901	N	N
43756	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood		Asbestos	Sampled – Not Detected				Braided cables (3 no.), outside box, connected to COLR box and within cable run. W/B cess, 150m.			R438901	N	N
43752	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood		Asbestos	Known				Cement board (1m2), internal lining to COL.ISOL.TRANS box. W/B cess, 150m			R438901	N	N
43755	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Gasket :Pipework	Asbestos	Sampled – Not Detected				Gasket (1m), seal around COL.ISOL.TRANS box. W/B cess, 150m			R438901	N	N
43760	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood		Asbestos	Known				Cement board (1m2), internal lining to COL.ISOL.TRANS box. W/B cess, 160m			R438901	N	N
43763	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Gasket :Pipework	Asbestos	Sampled – Not Detected				Gasket (1m), seal around COL.ISOL.TRANS box. W/B cess, 160m				N	N
43757	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood		Asbestos	Sampled – Not Detected				Braided cables (2 x 0.5m), connected to Westinghouse box. W/B cess, 160m			R438901	N	N
43762	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood		Asbestos	Strongly Presumed				Bakelite plates (4 no.), within COL.ISOL.TRANS box. W/B cess, 160m			R438901	N	N
43764	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood		Asbestos	Sampled – Not Detected				Braided cables (3 no.), outside box, connected to COLR box and within cable run. W/B cess, 160m			R438901	N	N
43761	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood		Asbestos	Sampled – Not Detected				Braided cables (7 no.), within COL.ISOL.TRANS box. W/B cess, 160m			R438901	N	N
43758	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood		Asbestos	Sampled – Not Detected				Braided cables (3 x 0.1m), within EB COLR box. W/B cess, 160m.			R438901	N	N
43759	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood		Asbestos	Strongly Presumed				Bakelite plates (8 no.), within EB COLR box. W/B cess, 160m.			R438901	N	N



Hazardous Material Asset Register - Summary



P012-P - PIC Line - Cockfosters to Oakwood

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37329	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	165		LHS	Trackside equipment: Col Box Relay		1			
37330	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	167		LHS	Trackside equipment: Westinghouse large box		1			
37331	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	184		LHS	Trackside equipment: Col Box Relay		1			
37332	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	185		LHS	Trackside equipment: Westinghouse large box		1			
37333	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	196		LHS	Trackside equipment: Westinghouse small box		1			
39408	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	199		LHS	Trackside equipment: Westinghouse small box		1			
37334	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	203		LHS	Trackside equipment: electrical box		1			
37335	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	213		LHS	Trackside equipment: Westinghouse small box		1			
39804	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	218		LHS	Trackside equipment: Westinghouse small box		1			
37337	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	229		LHS	Trackside equipment: Signal (RG26)					
37336	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	229	250	LHS	Cloth. cable sheath, Entry: Westinghouse kiosk, Route: H4 of 4, 1x40mmØ, Exit: N/A. 1 x 21m					
37338	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	229		LHS	Trackside equipment: westinghouse kiosk		1			
37339	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	249		LHS	Trackside equipment: tencore box		1			
39591	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	250	286	LHS	Cloth. cable sheath, Entry: Westinghouse kiosk, Route: H4 of 4, 2x40mmØ, Exit: Westinghouse large box. 2 x 36m					
39805	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	250		LHS	Trackside equipment: westinghouse kiosk		1			
37340	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	274		LHS	Trackside equipment: Westinghouse small box		1			
37341	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	275		LHS	Trackside equipment: Westinghouse small box		1			
37342	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	286	353	LHS	Cloth. cable sheath, Entry: Westinghouse large box, Route: H4 of 4, 2x40mmØ, Exit: Westinghouse kiosk. 2 x 67m					
37343	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	286		LHS	Trackside equipment: Westinghouse large box		3			



Hazardous Material Asset Register - Summary



P012-P - PIC Line - Cockfosters to Oakwood

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37344	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	290		LHS	Trackside equipment: Westinghouse large box		1			
37345	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	293		LHS	Trackside equipment: Westinghouse large box		1			
37346	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	330		LHS	Trackside equipment: Westinghouse small box		1			
37347	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	332		LHS	Trackside equipment: Westinghouse small box		1			
37348	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	335		LHS	Trackside equipment: Westinghouse small box		1			
37349	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	337		LHS	Trackside equipment: Westinghouse small box		1			
37350	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	353	407	LHS	Cloth. cable sheath, Entry: Westinghouse kiosk, Route: H4 of 4, 2x40mmØ, Exit: Westinghouse kiosk. 2 x 54m					
37351	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	353		LHS	Trackside equipment: westinghouse kiosk		1			
39592	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	363		LHS	Trackside equipment: Westinghouse small box		1			
37352	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	365		LHS	Trackside equipment: Westinghouse small box		1			
37353	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	369		LHS	Trackside equipment: tencore box		1			
37354	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	404		LHS	Trackside equipment: Westinghouse small box		1			
37355	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	405		LHS	Trackside equipment: Westinghouse small box		1			
37356	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	407	695	LHS	Cloth. cable sheath, Entry: Westinghouse kiosk, Route: H4 of 4, 2 x 40mm Ø, Exit: Westinghouse kiosk. 2 x 288m					
37357	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	408		LHS	Trackside equipment: westinghouse kiosk		1			
37358	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	425		LHS	Trackside equipment: Westinghouse small box		1			
37359	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	514		LHS	Trackside equipment: Westinghouse small box		1			
37360	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	517		LHS	Trackside equipment: Westinghouse small box		1			
37361	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	530		LHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P012-P - PIC Line - Cockfosters to Oakwood

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37362	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	530		LHS	Trackside equipment: tencore box		1			
37363	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	557		LHS	Trackside equipment: Westinghouse small box		1			
39806	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	561		LHS	Trackside equipment: Westinghouse small box		1			
39703	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	619		LHS	Trackside equipment: Westinghouse small box		1			
37364	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	695	710	LHS	Cloth. cable sheath, Entry: Westinghouse kiosk, Route: H4 of 4, 2x40mmØ, Exit: Westinghouse kiosk. 2 x 15m					
37365	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	695		LHS	Trackside equipment: westinghouse kiosk		1			
37366	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	700		LHS	Trackside equipment: Fog repeater		1			
37368	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	710		LHS	Trackside equipment: Westinghouse small box		1			
37367	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	710		LHS	Trackside equipment: westinghouse kiosk		1			
39807	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	710	817	LHS	Cloth. cable sheath, Entry: Westinghouse kiosk, Route: H4 of 8, 2x40mmØ, Exit: Westinghouse kiosk. 2 x 107m					
37369	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	713		LHS	Trackside equipment: Westinghouse small box		1			
37370	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	816		LHS	Trackside equipment: Westinghouse small box		1			
37372	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	817		LHS	Trackside equipment: westinghouse kiosk		1			
37371	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	817	908	LHS	Cloth. cable sheath, Entry: Westinghouse kiosk, Route: H4 of 4, 2x40mmØ, Exit: Westinghouse kiosk. 2 x 91m					
37373	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	819		LHS	Trackside equipment: Westinghouse small box		1			
37374	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	822		LHS	Trackside equipment: Signal (PK24A)		1			
37375	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	822		LHS	Trackside equipment: Fog repeater		1			
37376	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	826		LHS	Trackside equipment: tencore box		1			



Hazardous Material Asset Register - Summary



P012-P - PIC Line - Cockfosters to Oakwood

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37377	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	828		LHS	Trackside equipment: Westinghouse large box		1			
37378	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	832		LHS	Trackside equipment: Westinghouse small box		1			
39704	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	838		LHS	Trackside equipment: Westinghouse small box		1			
37379	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	908	960	LHS	Cloth. cable sheath, Entry: Westinghouse kiosk, Route: H4 of 4, 2x40mmØ, Exit: Westinghouse large box. 2 x 52m					
37380	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	908		LHS	Trackside equipment: westinghouse kiosk		1			
37381	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	913		LHS	Trackside equipment: Fog repeater		1			
37382	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	921		LHS	Trackside equipment: Westinghouse small box		1			
37383	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	926		LHS	Trackside equipment: Westinghouse small box		1			
37384	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	960	1006	LHS	Cloth. cable sheath, Entry: Westinghouse large box, Route: H4 of 4, 2x40mmØ, Exit: Westinghouse kiosk. 2 x 45.5m					
37385	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	960		LHS	Trackside equipment: Westinghouse large box		3			
39808	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	1006		LHS	Trackside equipment: westinghouse kiosk		1			
37386	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	1006	1068	LHS	Cloth. cable sheath, Entry: Westinghouse kiosk, Route: H4 of 4, 2x40mmØ, Exit: Westinghouse large box. 2 x 62.5m					
39409	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	1016		LHS	Trackside equipment: Westinghouse small box		1			
37387	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	1022		LHS	Trackside equipment: Westinghouse small box		1			
37388	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	1049		LHS	Trackside equipment: electrical box		1			
37389	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	1057		LHS	Trackside equipment: Westinghouse small box		1			
37390	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	1059		LHS	Trackside equipment: Westinghouse small box		1			
39809	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	1068	1090	LHS	Cloth. cable sheath, Entry: N/A, Route: H4 of 8, 2x40mmØ, Exit: Westinghouse large box. 2 x 22m					



Hazardous Material Asset Register - Summary



P012-P - PIC Line - Cockfosters to Oakwood

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37391	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	1090	1126	LHS	Cloth. cable sheath, Entry: Westinghouse large box, Route: H4 of 8, 3x40mmØ, Exit: OTX to EB. 3 x 35.5m					
39593	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	1126	1172	LHS	Cloth. cable sheath, Entry: N/A, Route: H4 of 8, 1x40mmØ, Exit: Platform CMS. 1 x 46m					
37392	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	1133		LHS	Trackside equipment: Westinghouse small box		1			
37188	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	1149		LHS	Trackside equipment: Westinghouse small box		1			
37189	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	1153		LHS	Trackside equipment: Westinghouse small box		1			
37190	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	1157		LHS	Trackside equipment: Westinghouse large box		1			
37191	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	1172		RHS	Trackside equipment: Yellow 630V		2			
37192	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	1177		LHS	Trackside equipment: tencore box		3			
37193	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Signal Boxes	Asbestos	Presumed	1179		RHS	Trackside equipment: Points heating box. In compound between Oakwood platforms		2			
37195	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	1180		RHS	Cloth. cable sheath, Entry: Westinghouse large box, Route: Cleat 1, 1x40mmØ, Cleat 2, 1x40mmØ, Exit: OTX to LHS. 2 x 10m					
37194	ACTIVE	P	P012-P-WBLO	Road WBLO - PIC - Cockfosters to Oakwood	Westinghouse Boxes	Asbestos	Presumed	1180		RHS	Trackside equipment: Westinghouse large box. In compound between Oakwood platforms		21			
44324	ACTIVE	P	P012/P/GRD-01	Girdering - G324 - Cockfosters To Oakwood		Asbestos	Surveyed – Not Detected				Paint to concrete arches to the underside of Bridge G324 - look to have been shuttered. Caution to be exercised if removed and further intrusive survey behind advised			R596701	N	N
44327	ACTIVE	P	P012/P/GRD-01	Girdering - G324 - Cockfosters To Oakwood	Cement Cable Troughing & Debris	Asbestos	Known				Troughing debris, <0.25m2, adjacent to Piccadilly Line, Eastbound road 15m from Platform 2 on the underside Bridge G324.			R596701		
44800	ACTIVE	P	P012/P/GRD-01	Girdering - G324 - Cockfosters To Oakwood	No Access	Asbestos	Presumed				Paint to concrete arches to the underside of Bride G324 - Look to have been shuttered. Caution to be exercised if removed and further intrusive survey behind advised			R596701		
44325	ACTIVE	P	P012/P/GRD-01	Girdering - G324 - Cockfosters To Oakwood	Cable Sheath	Asbestos	Strongly Presumed				Woven sheath cable, 2 no, to cable run from caged westinghouse box over track crossing to far side of Piccadilly Line, Eastbound Road on the underside of Bridge G324.			R596701		



Hazardous Material Asset Register - Summary



P012-P - PIC Line - Cockfosters to Oakwood

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44326	ACTIVE	P	P012/P/GRD-01	Girdering - G324 - Cockfosters To Oakwood	Cable Sheath	Asbestos	Strongly Presumed				Woven sheath cable, 2 no, to cable run from caged westinghouse box over track crossing to track wall on Piccadilly Line, Westbound Road on the underside Bridge G324			R596701		
44801	ACTIVE	P	P012/P/GRD-01	Girdering - G324 - Cockfosters To Oakwood	Lead/Leading	Lead Paint/Lead	Known				Blue Gloss Support columns thickness 220 1.33%			R596702		
44802	ACTIVE	P	P012/P/GRD-01	Girdering - G324 - Cockfosters To Oakwood	Lead/Leading	Lead Paint/Lead	Known				Blue Gloss Horizontal Support Steel thickness 290 7.51%			R596702		
44804	ACTIVE	P	P012/P/GRD-01	Girdering - G324 - Cockfosters To Oakwood	Lead/Leading	Lead Paint/Lead	Known				Light Blue Matt Horizontal Support Steel thickness 940 14.7%			R596702		
44036	ACTIVE	P	P012/P/GRD-01	Girdering - G324 - Cockfosters To Oakwood	Lead/Leading	Lead Paint/Lead	Known				Blue Gloss Horizontal Support Steel thickness 290 7.51%			R596702	N	N
44037	ACTIVE	P	P012/P/GRD-01	Girdering - G324 - Cockfosters To Oakwood	Lead/Leading	Lead Paint/Lead	Known				Light Blue Matt Support Columns thickness 930 11.5%			R596702	N	N
44038	ACTIVE	P	P012/P/GRD-01	Girdering - G324 - Cockfosters To Oakwood	Lead/Leading	Lead Paint/Lead	Known				Light Blue Matt Horizontal Support Steel thickness 940 14.7%			R596702	N	N
44035	ACTIVE	P	P012/P/GRD-01	Girdering - G324 - Cockfosters To Oakwood	Lead/Leading	Lead Paint/Lead	Known				Blue Gloss Support columns thickness 220 1.33%			R596702	N	N
44039	ACTIVE	P	P012/P/GRD-01	Girdering - G324 - Cockfosters To Oakwood	Lead/Leading	Lead Paint/Lead	Known				White Matt Corrugated Steel Above Platform thickness 120 0.12%			R596702	N	N

P013-P - PIC Line - Oakwood Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38999	ACTIVE	P	P013-P-EBLO	Road EBLO (Plt2) - PIC - Oakwood Stn	Cable Sheath	Asbestos	Strongly Presumed		12	LHS	Cloth. cable sheath, Entry: Platform CMS, Route: H3 of 8, 1x15mmØ, H4, 1x40mmØ, Exit: Ten Core box. 2 X 2M					
39000	ACTIVE	P	P013-P-EBLO	Road EBLO (Plt2) - PIC - Oakwood Stn	Cable Sheath	Asbestos	Strongly Presumed	12	18	LHS	Cloth. cable sheath, Entry:N/A, Route: H4 of 8, 1x40mmØ, Exit: Behind concrete hoarding. 1 x 6m					
39001	ACTIVE	P	P013-P-EBLO	Road EBLO (Plt2) - PIC - Oakwood Stn	Signal Boxes	Asbestos	Presumed	12		LHS	Trackside equipment: tencore box		1			
39002	ACTIVE	P	P013-P-EBLO	Road EBLO (Plt2) - PIC - Oakwood Stn	Westinghouse Boxes	Asbestos	Presumed	18		LHS	Trackside equipment: Westinghouse small box		2			
39003	ACTIVE	P	P013-P-EBLO	Road EBLO (Plt2) - PIC - Oakwood Stn	Cable Sheath	Asbestos	Strongly Presumed	66	123	LHS	Cloth. cable sheath, Entry: Behind concrete hoarding, Route: H4 of 4, 1x40mmØ, Exit: N/A. 1 x 57m					
39004	ACTIVE	P	P013-P-EBLO	Road EBLO (Plt2) - PIC - Oakwood Stn	Signal Boxes	Asbestos	Presumed	74		LHS	Trackside equipment: tencore box		1			
39005	ACTIVE	P	P013-P-EBLO	Road EBLO (Plt2) - PIC - Oakwood Stn	Westinghouse Boxes	Asbestos	Presumed	100		LHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P013-P - PIC Line - Oakwood Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39688	ACTIVE	P	P013-P-EBLO	Road EBLO (Plt2) - PIC - Oakwood Stn	Signal Boxes	Asbestos	Presumed	116		LHS	Trackside equipment: Electrical box		1			
39006	ACTIVE	P	P013-P-EBLO	Road EBLO (Plt2) - PIC - Oakwood Stn	Signal Boxes	Asbestos	Presumed	122		RHS	Trackside equipment: Signal (PK22)		1			
39007	ACTIVE	P	P013-P-EBLO	Road EBLO (Plt2) - PIC - Oakwood Stn	Signal Boxes	Asbestos	Presumed	122		RHS	Trackside equipment: tencore box		1			
39010	ACTIVE	P	P013-P-WBLO	Road WBLO (Plt1) - PIC - Oakwood Stn	Signal Boxes	Asbestos	Presumed	0		RHS	Trackside equipment: Rail Gap Indicator		1			
39008	ACTIVE	P	P013-P-WBLO	Road WBLO (Plt1) - PIC - Oakwood Stn	Cable Sheath	Asbestos	Strongly Presumed	0	15	LHS	Cloth. cable sheath, Entry: N/A, Route: H4 of 4, 1x40mmØ, Exit: Depot Road. 1 x 15m					
39009	ACTIVE	P	P013-P-WBLO	Road WBLO (Plt1) - PIC - Oakwood Stn	Signal Boxes	Asbestos	Presumed	0		RHS	Trackside equipment: Signal (PK21)		1			
39011	ACTIVE	P	P013-P-WBLO	Road WBLO (Plt1) - PIC - Oakwood Stn	Signal Boxes	Asbestos	Presumed	0		RHS	Trackside equipment: tencore box		1			
40064	ACTIVE	P	P013-P-WBLO	Road WBLO (Plt1) - PIC - Oakwood Stn	Westinghouse Boxes	Asbestos	Presumed	3		LHS	Trackside equipment: Westinghouse small box		1			
39012	ACTIVE	P	P013-P-WBLO	Road WBLO (Plt1) - PIC - Oakwood Stn	Signal Boxes	Asbestos	Presumed	4		LHS	Trackside equipment: tencore box		1			
39013	ACTIVE	P	P013-P-WBLO	Road WBLO (Plt1) - PIC - Oakwood Stn	Westinghouse Boxes	Asbestos	Presumed	5		LHS	Trackside equipment: Westinghouse small box		2			
39014	ACTIVE	P	P013-P-WBLO	Road WBLO (Plt1) - PIC - Oakwood Stn	Signal Boxes	Asbestos	Presumed	6		LHS	Trackside equipment: Red Light Trainstop		1			
39015	ACTIVE	P	P013-P-WBLO	Road WBLO (Plt1) - PIC - Oakwood Stn	Westinghouse Boxes	Asbestos	Presumed	6		LHS	Trackside equipment: Westinghouse small box		1			
40065	ACTIVE	P	P013-P-WBLO	Road WBLO (Plt1) - PIC - Oakwood Stn	Signal Boxes	Asbestos	Removed	7		LHS	Trackside equipment: Redifon loop aerial box Notes from 2022 re-inspection: Removed		1			
39016	ACTIVE	P	P013-P-WBLO	Road WBLO (Plt1) - PIC - Oakwood Stn	Westinghouse Boxes	Asbestos	Presumed	7		LHS	Trackside equipment: Westinghouse small box		1			
39905	ACTIVE	P	P013-P-WBLO	Road WBLO (Plt1) - PIC - Oakwood Stn	Westinghouse Boxes	Asbestos	Presumed	8		LHS	Trackside equipment: Westinghouse large box		1			
39017	ACTIVE	P	P013-P-WBLO	Road WBLO (Plt1) - PIC - Oakwood Stn	Signal Boxes	Asbestos	Presumed	10		LHS	Trackside equipment: tencore box		1			
39018	ACTIVE	P	P013-P-WBLO	Road WBLO (Plt1) - PIC - Oakwood Stn	Westinghouse Boxes	Asbestos	Presumed	15		LHS	Trackside equipment: Westinghouse small box		2			
39019	ACTIVE	P	P013-P-WBLO	Road WBLO (Plt1) - PIC - Oakwood Stn	Signal Boxes	Asbestos	Presumed	15		LHS	Trackside equipment: Red Light Trainstop		2			



Hazardous Material Asset Register - Summary



P013-P - PIC Line - Oakwood Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39020	ACTIVE	P	P013-P-WBLO	Road WBLO (Plt1) - PIC - Oakwood Stn	Signal Boxes	Asbestos	Removed	123		RHS	Trackside equipment: Redifon loop aerial box Notes from 2022 re-inspection: Removed		1			
39023	ACTIVE	P	P013-P-WBLO	Road WBLO (Plt1) - PIC - Oakwood Stn	Signal Boxes	Asbestos	Presumed	125		RHS	Trackside equipment: tencore box		1			
39689	ACTIVE	P	P013-P-WBLO	Road WBLO (Plt1) - PIC - Oakwood Stn	Signal Boxes	Asbestos	Presumed	125		RHS	Trackside equipment: Signal (PK3)		1			
39022	ACTIVE	P	P013-P-WBLO	Road WBLO (Plt1) - PIC - Oakwood Stn	Westinghouse Boxes	Asbestos	Presumed	125		RHS	Trackside equipment: Westinghouse small box		1			
39021	ACTIVE	P	P013-P-WBLO	Road WBLO (Plt1) - PIC - Oakwood Stn	Signal Boxes	Asbestos	Presumed	125		RHS	Trackside equipment: Rail Gap Ind. Box		1			

P014-P - PIC Line - Oakwood to Southgate

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40414	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	0	5	RHS	Cloth. cable sheath, Entry: Platform wall, Route: H2 of 4, 3x20mmØ, H3, 2x15mmØ, 1x20mmØ, H4, 1x40mmØ, Exit: N/A. 7 X 5M					
40415	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Ducts	Asbestos	Presumed	1		LHS	cement cable duct lining. Presumed present (In floor & sealed)		4			
40416	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	5	7	RHS	Cloth. cable sheath, Entry: Signals trackside equipment, Route: H3 of 4, 4x15mmØ, H2, 3x20mmØ, H4, 1x40mmØ, Exit: Signals trackside equipment 8 x 1.5m					
40417	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	5		RHS	Trackside equipment: signal A911		1			
39729	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	7		RHS	Trackside equipment: Westinghouse small box		1			
40420	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	7		RHS	Trackside equipment: tencore box		1			
40419	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	7		RHS	Trackside equipment: tencore box		1			
40418	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	7	11	RHS	Cloth. cable sheath, Entry: N/A, Route: Between TE, H3, H4, 15mm to 40mmØ, Exit: N/A. Numerous amounts					
40422	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	8		RHS	Trackside equipment: Westinghouse large box		1			
40421	INACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Removed	8		RHS	Trackside equipment: tencore box Notes from 2022 re-inspection: Removed		1			



Hazardous Material Asset Register - Summary



P014-P - PIC Line - Oakwood to Southgate

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40423	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	10		RHS	Trackside equipment: tencore box		1			
40425	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	11		RHS	Trackside equipment: tencore box		1			
40424	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	11	128	RHS	Cloth. cable sheath, Entry: Signals trackside equipment, Route: H2 of 4, 2x20mmØ, H3, 1x15mmØ, H4, 1x40mmØ, Exit: OTX to LHS. 4 x 117.5m					
40426	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	12		RHS	Trackside equipment: Westinghouse small box		1			
39951	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	14	15	RHS	Cloth. cable sheath, H4, 1x40mmØ, spliced and mounted below H4. 1 x 1m					
40427	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	122	123	RHS	Cloth. cable sheath, H4, 1x40mmØ, spliced and mounted below H4. 1 x 1m					
40428	INACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cable Sheath	Asbestos	Removed	123	124	RHS	Cloth. cable sheath, H4, 1x40mmØ, spliced and mounted below H4. 1 x 1m Notes from 2022 re-inspection: Removed					
40429	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	128	132	LHS	Cloth. cable sheath, Entry: OTX to RHS, Route: H10 of 12, 2x20mmØ, H11, 1x15mmØ, H12, 1x40mmØ, Exit: Ten Core box. 4 x 4m					
39405	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	130		LHS	Trackside equipment: Westinghouse small box Notes from 2022 re-inspection: 4 No		4			
40431	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	132		LHS	Trackside equipment: tencore box		1			
40430	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	132	136	LHS	Cloth. cable sheath, Entry: N/A, Route: H10 of 12, 1x20mmØ, H11, 1x15mmØ, H12, 1x40mmØ, Exit: Westinghouse small box. 3 x 4m					
40433	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	136		LHS	Trackside equipment: Westinghouse small box		3			
40432	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	136	183	LHS	Cloth. cable sheath, Entry: N/A, Route: H11 of 12, 1x15mmØ, H12, 1x40mmØ, Exit: Ten Core box. 2 x 47m					
39427	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	175		LHS	Trackside equipment: Westinghouse small box		1			
40434	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	175		LHS	Trackside equipment: Rail Gap Ind box		1			
40513	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	175		RHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P014-P - PIC Line - Oakwood to Southgate

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40515	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	183		LHS	Trackside equipment: tencore box		1			
40514	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	183	220	LHS	Cloth. cable sheath, Entry: N/A, Route: H12 of 12, 1x40mmØ, Exit: N/A. 1 x37m					
40516	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	220	258	LHS	Cloth. cable sheath, Entry: N/A, Route: H4 of 4, 1x40mmØ, Exit: N/A. 1 x 37.5m		1			
40517	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	250		LHS	Trackside equipment: tencore box		1			
40518	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	251		LHS	Trackside equipment: Westinghouse large box		1			
40519	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	257		LHS	Trackside equipment: rail Gap Ind box		1			
40520	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	258	269	LHS	Cloth. cable sheath, Entry: From undergrowth, Route: H4 of 4, 3x40mmØ, Exit: N/A. 3 x 11.5m					
40522	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	258	259	LHS	Cloth. cable sheath, H4, 1x40mmØ, spliced and mounted above H1. 1 x1m					
40521	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	258		LHS	Trackside equipment: Westinghouse small box		1			
39733	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	267	268	LHS	Cloth. cable sheath, H4, 1x40mmØ, spliced and mounted above H1. 1 x1m					
40523	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	269	498	LHS	Cloth. cable sheath, Entry: N/A, Route: H8 of 8, 3x40mmØ, Exit: N/A. 3 x 229m					
40524	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	383		LHS	Trackside equipment: Main earth terminal box		1			
40525	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	403		LHS	Trackside equipment: Signal R915 & Fog repeater A915		1			
40526	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	413		LHS	Trackside equipment: Westinghouse small box		1			
40527	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	414		LHS	Trackside equipment: Westinghouse small box		1			
40528	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	415		LHS	Trackside equipment: Westinghouse small box		1			
39955	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	498	520	LHS	Cloth. cable sheath, Entry: N/A, Route H4 of 4, 3x40mmØ, Exit: Westinghouse large box via loop to rear. 3 x 22m					
40529	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	517		LHS	Trackside equipment: tencore box		1			
40530	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	518	522	LHS	Trackside equipment: Westinghouse large box		7			



Hazardous Material Asset Register - Summary



P014-P - PIC Line - Oakwood to Southgate

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40531	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	520	841	LHS	Cloth. cable sheath, Entry: Westinghouse large box, Route H4 of 4, 1x40mmØ, Exit: Westinghouse large box. 1 x 321m					
40532	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	523		LHS	Trackside equipment: Westinghouse small box		1			
40533	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	524		LHS	Trackside equipment: signal A915		1			
39434	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	526		LHS	Trackside equipment: tencore box		1			
40534	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	529		LHS	Trackside equipment: Westinghouse small box		1			
40535	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	533		LHS	Trackside equipment: Westinghouse small box		1			
40536	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	616		LHS	Trackside equipment: Westinghouse small box		1			
40537	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	709		LHS	Trackside equipment: Westinghouse small box		1			
39435	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	710		LHS	Trackside equipment: Westinghouse small box		1			
40538	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	839	842	LHS	Trackside equipment: Westinghouse small box		5			
40616	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	841	961	LHS	Cloth. cable sheath, Entry: Westinghouse large box, Route H4 of 4, 1x40mmØ, Exit: Westinghouse large box. 1 X 120					
39782	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	847		LHS	Trackside equipment: Fog Repeater A917		1			
40617	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	849		LHS	Trackside equipment: Westinghouse small box		1			
40618	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	850		LHS	Trackside equipment: Westinghouse small box		1			
40619	INACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Removed	938		LHS	Trackside equipment: Main earth terminal box Notes from 2022 re-inspection: Removed		1			
40620	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	959	963	LHS	Trackside equipment: Westinghouse large box		7			
40621	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	961	1057	LHS	Cloth. cable sheath, Entry: Westinghouse large box, Route: H4 of 4, 1x40mmØ, Exit: N/A. 1 x 96m					
40622	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	967		LHS	Trackside equipment: tencore box		1			



Hazardous Material Asset Register - Summary



P014-P - PIC Line - Oakwood to Southgate

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40623	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	967		LHS	Trackside equipment: Westinghouse small box		1			
40624	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	968		LHS	Trackside equipment: Fog Repeater A917		1			
40625	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	975		LHS	Trackside equipment: Westinghouse small box		1			
40626	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	976		LHS	Trackside equipment: Westinghouse small box		1			
40627	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	987		LHS	Trackside equipment: tencore box		1			
40628	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	1057	1065	LHS	Cloth. cable sheath, Entry: N/A, Route: H4 of 8, 1x40mmØ, Exit: N/A. 1 x 8m					
40629	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	1065	1245	LHS	Cloth. cable sheath, Entry: N/A, Route: H4 of 4, 1x40mmØ, Exit: N/A. 1 x 180m					
39981	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	1187		LHS	Trackside equipment: Westinghouse small box		1			
40630	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	1188		LHS	Trackside equipment: Westinghouse small box		1			
40631	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	1245	1265	LHS	Cloth. cable sheath, Entry: N/A, Route: H4 of 8, 1x40mmØ, Exit: N/A. 1 x 20m					
40632	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	1265	1346	LHS	Cloth. cable sheath, Entry: N/A, Route: H4 of 4, 1x40mmØ, Exit: Westinghouse large box. 1 x 81m					
40633	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	1345	1348	LHS	Trackside equipment: Westinghouse large box		5			
40634	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	1346	1463	LHS	Cloth. cable sheath, Entry: N/A, Route: H4 of 4, 1x40mmØ, Exit: Westinghouse kiosk. 1 x 177m					
40635	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	1349		LHS	Trackside equipment: Signal RPK1(1) & Fog Repeater PK1		1			
39443	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	1379		LHS	Trackside equipment: Westinghouse small box		1			
40636	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	1380		LHS	Trackside equipment: Westinghouse small box		1			
40637	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	1426		RHS	Trackside equipment: tencore box		1			
40638	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	1426		RHS	Trackside equipment: tencore box		1			
40639	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	1430		RHS	Trackside equipment: Fog Repeater RPK1 (2)		1			



Hazardous Material Asset Register - Summary



P014-P - PIC Line - Oakwood to Southgate

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39444	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	1463		LHS	Trackside equipment: Westinghouse kiosk		1			
40640	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	1463	1628	LHS	Cloth. cable sheath, Entry: Westinghouse kiosk, Route H4 of 4, 1x40mmØ, Exit: Westinghouse kiosk . 1 x 165m					
40641	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	1470		LHS	Trackside equipment: tencore box		1			
40720	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	1470		LHS	Trackside equipment: Westinghouse small box		1			
40721	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	1472		LHS	Trackside equipment: Signal PK1 RPK2 & Fog repeater PK2		1			
40722	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	1473		LHS	Trackside equipment: Westinghouse small box		1			
40723	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	1477		LHS	Trackside equipment: Westinghouse small box		1			
40724	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	1603		LHS	Trackside equipment: tencore box		2			
40725	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	1604		RHS	Trackside equipment: tencore box		1			
39786	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	1605		LHS	Trackside equipment: Westinghouse small box		1			
40726	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	1621		LHS	Trackside equipment: Westinghouse small box		1			
40727	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	1623		LHS	Trackside equipment: tencore box		1			
40728	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	1627		LHS	Trackside equipment: Westinghouse small box		1			
40730	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	1628		LHS	Trackside equipment: Westinghouse kiosk		1			
40729	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cable Sheath	Asbestos	Strongly Presumed	1628	1725	LHS	Cloth. cable sheath, Entry: Westinghouse kiosk, Route H4 of 4, 1x40mmØ, Exit: Platform grounds. 1 x 97m					
40731	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	1628		LHS	Trackside equipment: Signal PK2		1			
40732	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	1660		LHS	Trackside equipment: Westinghouse small box		1			
40733	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	1665		LHS	Trackside equipment: Westinghouse small box		1			
40734	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	1676		LHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P014-P - PIC Line - Oakwood to Southgate

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39985	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cement Cable Troughing & Debris	Asbestos	Strongly Presumed	1677	1696		cement cable trough. Between rail and cable hangers. 2 x 19m UTX AND LHS					
40735	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cement Cable Troughing & Debris	Asbestos	Known	1679		LHS	cement debris. By cable trough where damaged. 0.25m²					
40736	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Cement Cable Troughing & Debris	Asbestos	Strongly Presumed	1694		LHS	cement debris. Loose cable trough lid. 0.25m²					
40737	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	1707		LHS	Trackside equipment: tencore box		2			
40738	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	1707		LHS	Trackside equipment: Westinghouse small box		1			
40739	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	1709		LHS	Trackside equipment: tencore box		1			
40740	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	1709		LHS	Trackside equipment: Westinghouse small box		1			
39475	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Westinghouse Boxes	Asbestos	Presumed	1710		LHS	Trackside equipment: Westinghouse small box		1			
40741	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	1716		LHS	Trackside equipment: tencore box		1			
40742	ACTIVE	P	P014-P-EBLO	Road EBLO - PIC - Southgate to Oakwood	Signal Boxes	Asbestos	Presumed	1718		LHS	Trackside equipment: electrical box		1			
38892	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Cable Sheath	Asbestos	Strongly Presumed	0	2	LHS	Cloth. cable sheath, Entry: N/A, Route: H4 of 4, 1x40mmØ, Exit: Westinghouse kiosk. 1 X 2M					
38891	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	0		LHS	Trackside equipment: Westinghouse small box		1			
38893	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1		LHS	Trackside equipment: Westinghouse small box		1			
39897	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Cable Sheath	Asbestos	Strongly Presumed	2	448	LHS	Cloth. cable sheath, Entry: Westinghouse kiosk, Route: H4 of 4, 1x40mmØ, Exit: Westinghouse large box. 1 X 446M					
38894	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	2		LHS	Trackside equipment: Westinghouse kiosk		1			
38896	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	4		LHS	Trackside equipment: tencore box		1			
38895	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	4		LHS	Trackside equipment: Westinghouse small box		1			
38897	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	6		LHS	Trackside equipment: Westinghouse large box		1			
38898	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	14		LHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P014-P - PIC Line - Oakwood to Southgate

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38899	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	58		LHS	Trackside equipment: Westinghouse small box		1			
38900	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	59		LHS	Trackside equipment: Westinghouse small box		1			
38901	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	129		RHS	Trackside equipment: tencore box		1			
38903	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	133		LHS	Trackside equipment: tencore box		2			
38902	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	133		LHS	Trackside equipment: Westinghouse small box		2			
38904	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	134		LHS	Trackside equipment: Westinghouse small box		1			
39459	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	135		LHS	Trackside equipment: Westinghouse small box		1			
38905	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Removed	151		LHS	Trackside equipment: Electrical equipment Notes from 2022 re-inspection: Removed		1			
38906	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	158		LHS	Trackside equipment: type 79		1			
38907	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	316		RHS	Trackside equipment: Signal (RPK.1)		1			
40055	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	316		RHS	Trackside equipment: tencore box		1			
38908	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	447		LHS	Trackside equipment: tencore box		1			
38909	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	448	449	LHS	Trackside equipment: Westinghouse large box		5			
38910	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	454		LHS	Trackside equipment: Fog repeater (A916)		1			
39684	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	460		LHS	Trackside equipment: Westinghouse small box		1			
40056	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	462		LHS	Trackside equipment: Westinghouse small box		1			
38911	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Cable Sheath	Asbestos	Strongly Presumed	465	483	LHS	Cloth. cable sheath, Entry: N/A, Route: H4 of 6, 1x40mmØ, Exit: N/A. 1 x 18m					
38912	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Cable Sheath	Asbestos	Strongly Presumed	483	567	LHS	Cloth. cable sheath, Entry: N/A, Route: H4 of 4, 1x40mmØ, Exit: Westinghouse large box. 1 x 84m					
38913	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	566	568	LHS	Trackside equipment: tencore box		5			



Hazardous Material Asset Register - Summary



P014-P - PIC Line - Oakwood to Southgate

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38914	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Cable Sheath	Asbestos	Strongly Presumed	567	660	LHS	Cloth. cable sheath, Entry: Westinghouse large box, Route: H4 of 4, 1x40mmØ, Exit: N/A. 1 x 93m					
38915	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	573		LHS	Trackside equipment: Westinghouse small box		1			
38916	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	574		LHS	Trackside equipment: Signal (916)		1			
38917	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	576		LHS	Trackside equipment: tencore box		1			
38918	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	580		LHS	Trackside equipment: Westinghouse small box		1			
39898	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	581		LHS	Trackside equipment: Westinghouse small box		1			
38919	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	585		LHS	Trackside equipment: type 79 box		1			
38920	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Cable Sheath	Asbestos	Strongly Presumed	660	668	LHS	Cloth. cable sheath, Entry: N/A, Route: H4 of 6, 1x40mmØ, Exit: N/A. 1 x 8m					
38921	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Cable Sheath	Asbestos	Strongly Presumed	668	849	LHS	Cloth. cable sheath, Entry: N/A, Route: H4 of 4, 1x40mmØ, Exit: N/A. 1 x 181m					
38922	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	678		LHS	Trackside equipment: Westinghouse small box		1			
38923	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	805		LHS	Trackside equipment: Westinghouse large box		1			
38924	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	808		LHS	Trackside equipment: Fog repeater (A194)		1			
38925	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	819		LHS	Trackside equipment: Westinghouse small box		1			
38926	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	821		LHS	Trackside equipment: Westinghouse small box		1			
38927	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Cable Sheath	Asbestos	Strongly Presumed	849	925	LHS	Cloth. cable sheath, Entry: N/A, Route: H3 of 4, 1x40mmØ, Exit: Westinghouse large box. 1 x 76m					
39685	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	925		LHS	Trackside equipment: Westinghouse large box		5			
38928	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Cable Sheath	Asbestos	Strongly Presumed	925	1015	LHS	Cloth. cable sheath, Entry: Westinghouse large box (x2), Route: H3 of 4, 3x40mmØ, Exit: N/A. 3 x 90m					
38929	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	929		LHS	Trackside equipment: Westinghouse small box		1			
38930	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	930		LHS	Trackside equipment: Signal (914A)		1			



Hazardous Material Asset Register - Summary



P014-P - PIC Line - Oakwood to Southgate

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38931	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	932		LHS	Trackside equipment: tencore box		1			
38932	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	935		LHS	Trackside equipment: Westinghouse small box		1			
38933	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	936		LHS	Trackside equipment: Westinghouse small box		1			
40057	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	937		LHS	Trackside equipment: Westinghouse small box		1			
38934	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	940		LHS	Trackside equipment: Westinghouse small box		1			
38935	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1015	1021	LHS	Cloth. cable sheath, Entry: N/A, Route: H3 of 4, 2x40mmØ, H4, 1x40mmØ, Exit: N/A. 3 x6m					
38936	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	1015		LHS	Trackside equipment: type 79		1			
38937	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1019		LHS	Trackside equipment: Westinghouse large box		2			
40058	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	1020		LHS	Trackside equipment: tencore box		1			
38938	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1021	1218	LHS	Cloth. cable sheath, Entry: N/A, Route: H4 of 4, 3x40mmØ, Exit: Westinghouse large box. 3 x 191m					
38939	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	1029		LHS	Trackside equipment: Signal R910A		1			
39899	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1038		LHS	Trackside equipment: Westinghouse small box		1			
38940	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1039		LHS	Trackside equipment: Westinghouse small box		1			
38726	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1134		LHS	Trackside equipment: Westinghouse small box		1			
38727	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1175	1176	LHS	Cloth. cable sheath, H4, 1x40mmØ, spliced & mounted below H4. 1 x 1m					
38728	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1216	1219	LHS	Trackside equipment: Westinghouse large box		7			
38729	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1218	1219	LHS	Cloth. cable sheath, Entry: Westinghouse large box, Route: H4 of 4, 3x40mmØ, Exit: N/A. 3 x 1m					
38730	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1219	1354	LHS	Cloth. cable sheath, Entry: Westinghouse large box, Route: H3 of 4, 1x30mmØ, H4, 3x40mmØ, Exit: Ten Core box. 4 x 135m					
38731	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	1220		LHS	Trackside equipment: tencore box		1			



Hazardous Material Asset Register - Summary



P014-P - PIC Line - Oakwood to Southgate

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38732	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	1229		LHS	Trackside equipment: Fog repeater (A910A)		1			
38733	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	1229		LHS	Trackside equipment: Signal (910ABC)		1			
38734	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1243		LHS	Trackside equipment: Westinghouse small box		1			
38735	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1245		LHS	Trackside equipment: Westinghouse small box		1			
39890	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	1354		LHS	Trackside equipment: tencore box		4			
38736	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1354	1471	LHS	Cloth. cable sheath, Entry: Ten Core box, Route: H7 of 8, 1x30mmØ, H8, 3x40mmØ, Exit: N/ A. 4 x 117m					
38737	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	1354		LHS	Trackside equipment: Signal (R910BC)		1			
39456	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1380		LHS	Trackside equipment: Westinghouse small box		1			
38738	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	1380		LHS	Trackside equipment: Main earth terminal		1			
38739	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1382		LHS	Trackside equipment: Westinghouse small box		1			
38740	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	1419		LHS	Trackside equipment: Fog repeater (A910B)		1			
38741	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1431		LHS	Trackside equipment: Westinghouse small box		1			
38742	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	1432		LHS	Trackside equipment: type 79 box		1			
38743	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1433		LHS	Trackside equipment: Westinghouse small box		1			
38744	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1471	1501	LHS	Cloth. cable sheath, Entry: Ten Core box, Route: H7 of 8, 1x20mmØ, 1x30mmØ, H8, 3x40mmØ, Exit: Undergrowth behind hangers. 5 x 29.5m					
40017	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	1471		LHS	Trackside equipment: tencore box		1			
38746	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	1499		LHS	Trackside equipment: Fog repeater (A910C)		1			
38745	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1499	1500	LHS	Cloth. cable sheath, H4, 1x40mmØ, spliced & mounted above H1. 1 x 1m					



Hazardous Material Asset Register - Summary



P014-P - PIC Line - Oakwood to Southgate

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38747	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1501	1531	LHS	Cloth. cable sheath, Entry: Undergrowth behind hangers, Route: H3 of 4, 1x20mmØ, 1x30mmØ, H4, 1x40mmØ, Exit: N/A. 3 x 30.5m					
39679	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1501	1502	LHS	Cloth. cable sheath, H4, 1x40mmØ, spliced & mounted above H1. 1 x 1m					
38748	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Removed	1507		LHS	Trackside equipment: Electrical equipment Notes from 2022 re-inspection: Removed		1			
40018	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1507		LHS	Trackside equipment: Westinghouse large box		1			
38749	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	1508		LHS	Trackside equipment: Electrical box		1			
38750	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1509		LHS	Trackside equipment: Westinghouse large box		2			
38970	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	1510		LHS	Trackside equipment: tencore box		1			
39902	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1530		LHS	Trackside equipment: Westinghouse large box		1			
38972	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	1531		LHS	Trackside equipment: tencore box		1			
38971	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1531	1546	LHS	Cloth. cable sheath, Entry: Ten Core box, Route: H3 of 4, 1x20mmØ, 2x30mmØ, H4, 1x40mmØ, Exit: N/A. 4 x 14.5m					
38974	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1532		LHS	Trackside equipment: Westinghouse small box		1			
38973	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	1532		LHS	Trackside equipment: tencore box		1			
38975	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	1533		LHS	Trackside equipment: Signal (A910B)		1			
38976	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1542		LHS	Trackside equipment: Westinghouse small box		1			
38977	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1545		LHS	Trackside equipment: Westinghouse small box		1			
38978	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1546	1556	LHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: H2 of 4, 1x20mmØ, H3, 1x20mmØ, 2x30mmØ, H4, 1x40mmØ, Exit: N/A. 5 x 10m					
38979	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1546		LHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P014-P - PIC Line - Oakwood to Southgate

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39687	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1546		LHS	Trackside equipment: Westinghouse small box		1			
38980	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Removed	1547		LHS	Trackside equipment: Westinghouse small box Notes from 2022 re-inspection: Removed		1			
38981	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1556	1602	LHS	Cloth. cable sheath, Entry: N/A, Route: H10 of 12, 1x20mmØ, H11, 1x20mmØ, 2x30mmØ, H12, 1x40mmØ, Exit: N/A. 5 x 46m					
38983	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	1601		LHS	Trackside equipment: tencore box		1			
38982	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1601		LHS	Trackside equipment: Westinghouse large box		1			
38984	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1602	1620	LHS	Cloth. cable sheath, Entry: Ten Core box & Westinghouse large box, Route: H10 of 12, 2x20mmØ, H11, 1x20mmØ, 3x30mmØ, H12, 1x40mmØ, Exit: N/A. 7 x 18.5m					
38986	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	1602		LHS	Trackside equipment: Signal (A910C)		1			
40062	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1602		LHS	Trackside equipment: Westinghouse small box		1			
38985	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	1602		LHS	Trackside equipment: tencore box		1			
38987	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1618		LHS	Trackside equipment: Westinghouse small box		1			
38989	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1620		LHS	Trackside equipment: Westinghouse small box		1			
38988	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1620	1632	LHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: H10 of 12, 3x20mmØ, H11, 1x20mmØ, 3x30mmØ, H12, 1x40mmØ, Exit: OTX to RHS. 8 x 12m					
38990	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1622		LHS	Trackside equipment: Westinghouse small box		1			
40063	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Removed	1623		LHS	Trackside equipment: Westinghouse small box Notes from 2022 re-inspection: Removed		1			
38991	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Removed	1624		LHS	Trackside equipment: Westinghouse small box Notes from 2022 re-inspection: Removed		1			
39903	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	1625		LHS	Trackside equipment: tencore box		1			



Hazardous Material Asset Register - Summary



P014-P - PIC Line - Oakwood to Southgate

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38992	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	1630		LHS	Trackside equipment: tencore box		1			
38993	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1632	1750	RHS	Cloth. cable sheath, Entry: OTX from LHS, Route: H2 of 4, 3x20mmØ, H3, 3x30mmØ, 1x20mmØ, H4, 1x40mmØ, Exit: N/ A. 8 x 117.5m					
38994	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1636	1637	RHS	Cloth. cable sheath, H4, 1x40mmØ, spliced & mounted below H4. 1 x 1m					
38995	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Signal Boxes	Asbestos	Presumed	1708		RHS	Trackside equipment: type 79		1			
39904	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1747		RHS	Trackside equipment: Westinghouse small box		1			
38997	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1750		RHS	Trackside equipment: Westinghouse small box		1			
38996	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1750	1764	RHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: H2 of 4, 4x20mmØ, H3, 3x30mmØ, 1x20mmØ, H4, 1x40mmØ, Exit: Platform wall. 9 x 14m					
38998	ACTIVE	P	P014-P-WBLO	Road WBLO - PIC - Oakwood to Southgate	Westinghouse Boxes	Asbestos	Presumed	1752		RHS	Trackside equipment: Westinghouse small box		1			

P015-P - PIC Line - Southgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42773	ACTIVE	P	P015-P-EBLO	Road EBLO (Plt1) - PIC - Southgate Stn	Pit Blocks	Asbestos	Surveyed – Not Detected				Pit blocks - Non asbestos					
40743	ACTIVE	P	P015-P-EBLO	Road EBLO (Plt1) - PIC - Southgate Stn	Signal Boxes	Asbestos	Presumed	69		RHS	Trackside equipment: T Junction box		1			
40744	ACTIVE	P	P015-P-EBLO	Road EBLO (Plt1) - PIC - Southgate Stn	Signal Boxes	Asbestos	Presumed	112		RHS	Trackside equipment: Redifon loop aerial box		1			
40745	ACTIVE	P	P015-P-EBLO	Road EBLO (Plt1) - PIC - Southgate Stn	Ducts	Asbestos	Presumed	116		LHS	Cement. cable duct lining, Presumed present (In platform wall and sealed)		4			
42774	ACTIVE	P	P015-P-WBLO	Road WBLO (Plt2) - PIC - Southgate Stn		Asbestos	Surveyed – Not Detected				Pit blocks - Non asbestos					
39476	ACTIVE	P	P015-P-WBLO	Road WBLO (Plt2) - PIC - Southgate Stn	Ducts	Asbestos	Presumed	1		LHS	Cement. cable duct lining, Presumed present (In platform wall and sealed)		5			
40746	ACTIVE	P	P015-P-WBLO	Road WBLO (Plt2) - PIC - Southgate Stn	Ducts	Asbestos	Presumed	1		LHS	Bitumen. cable duct lining, in platform wall		4			
54024	ACTIVE	P	P015-P-WBLO	Road WBLO (Plt2) - PIC - Southgate Stn	Other Electrical Boxes	Asbestos	Presumed	45		RHS	Trackside equipment: 630V DC box Notes from 2022 re-inspection: Present		1			



Hazardous Material Asset Register - Summary



P015-P - PIC Line - Southgate Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
54025	ACTIVE	P	P015-P-WBLO	Road WBLO (Plt2) - PIC - Southgate Stn	Other Electrical Boxes	Asbestos	Presumed	46		RHS	Trackside Equipment: Westinghouse small box Notes from 2022 re-inspection: Present		1			
54026	ACTIVE	P	P015-P-WBLO	Road WBLO (Plt2) - PIC - Southgate Stn	Other Electrical Boxes	Asbestos	Presumed	53		RHS	Trackside equipment: Westinghouse small box		1			
54027	ACTIVE	P	P015-P-WBLO	Road WBLO (Plt2) - PIC - Southgate Stn	Other Electrical Boxes	Asbestos	Presumed	64		RHS	Trackside equipment: Westinghouse small box Notes from 2022 re-inspection: Present		1			
40826	ACTIVE	P	P015-P-WBLO	Road WBLO (Plt2) - PIC - Southgate Stn	Westinghouse Boxes	Asbestos	Removed	68		RHS	Trackside equipment: Westinghouse small box Notes from 2022 re-inspection: Removed		1			
40827	ACTIVE	P	P015-P-WBLO	Road WBLO (Plt2) - PIC - Southgate Stn	Signal Boxes	Asbestos	Presumed	113		RHS	Trackside equipment: Redifon loop aerial box		1			

P016-P - PIC Line - Southgate to Arnos Grove

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36663	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	0		LHS	Trackside equipment: tencore box		1			
41609	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	0		LHS	(VIA POINTS 23) Cloth, Entry: Platform Grounds, Route: H4 of 4, 1x30mmØ, Exit: N/A. 1 x 47m.					
41610	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	1		LHS	(VIA POINTS 23) Trackside equipment: Westinghouse small box		1			
41611	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	1		LHS	(VIA POINTS 23) Trackside equipment: tencore box		1			
41612	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	4		LHS	(VIA POINTS 23) Trackside equipment: tencore box		1			
41613	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	4		LHS	(VIA POINTS 23) Trackside equipment: tencore box		1			
41614	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	5		LHS	(VIA POINTS 23) Trackside equipment: Westinghouse small box		2			
39507	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	5			(VIA POINTS 23) Trackside equipment: tencore box		1			
39606	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	7		RHS	(VIA POINTS 23) Trackside equipment: tencore box		1			
36664	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	8		RHS	Trackside equipment: tencore box		1			



Hazardous Material Asset Register - Summary



P016-P - PIC Line - Southgate to Arnos Grove

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36665	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	8		RHS	Trackside equipment: Westinghouse small box		1			
41615	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	10		LHS	(VIA POINTS 23) Trackside equipment: 230V Kiosk		1			
41616	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	11		LHS	(VIA POINTS 23) Trackside equipment: 230V Kiosk		1			
41617	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	12		LHS	(VIA POINTS 23) Trackside equipment: 230V Kiosk		1			
41618	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	18		LHS	(VIA POINTS 23) Trackside equipment: Westinghouse small box		1			
36666	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	20		LHS	trackside equipment: Points heater		1			
41619	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	45		LHS	(VIA POINTS 23) Trackside equipment: Westinghouse small box		1			
41620	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	47		LHS	(VIA POINTS 23) Trackside equipment: Westinghouse small box		1			
39607	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	47	53	LHS	(VIA POINTS 23) Cloth, cable sheath. Entry: Westinghouse small box, Route: H3 of 4, 1x8mmØ, H4, 1x30mmØ, Exit: N/A. 2 x 6m					
41621	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	53	156	LHS	(VIA POINTS 23) Cloth, cable sheath. Entry: Westinghouse small box, Route: H3 of 4, 2x8mmØ, H4, 1x30mmØ, Exit: Into ground, 3 x 83m					
41622	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	53		LHS	(VIA POINTS 23) Trackside equipment: Westinghouse small box		1			
39863	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	100		LHS	(VIA POINTS 23) Trackside equipment: Westinghouse small box		1			
40094	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	136		LHS	(VIA POINTS 23) Trackside equipment: Westinghouse small box		1			
41623	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	136	164	LHS	(VIA POINTS 23) Cloth, cable sheath. Entry: N/A, Route: H3 of 4, 1x8mmØ, H4, 1x30mmØ, Exit: Arnos Grove to Southgate EB P-Way, 2 x 27.5m					
36667	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Track Section Switches	Asbestos	Presumed	154		RHS	trackside equipment: Yellow Current Rail Switch		2			
40095	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	156		LHS	(VIA POINTS 23) Trackside equipment: Westinghouse small box		1			
40096	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	160		LHS	(VIA POINTS 23) Trackside equipment: Points heating box		1			
36669	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	166		LHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P016-P - PIC Line - Southgate to Arnos Grove

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40306	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	166		LHS	Trackside equipment: tencore box		1			
36668	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	166	194	LHS	Cloth. Cable sheath, Entry: Arnos Grove Platform 1 to PTS23 EB P-Way & Ten Core box, Route: H3 of 4, 3x8mmØ, H4, 1x30mmØ, Exit: Westinghouse large box. 4 x 28.5m					
36670	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	167		LHS	Trackside equipment: tencore box		1			
39377	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	167		LHS	Trackside equipment: Westinghouse small box		1			
36671	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	186		LHS	Trackside equipment: Fog Repeater (A903)		1			
36672	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	193		LHS	Trackside equipment: Westinghouse large box		1			
40307	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	194		LHS	Trackside equipment: Westinghouse large box		1			
36673	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	194	200	LHS	Cloth. Cable sheath, Entry: Westinghouse large box, Route: H3 of 4, 2x8mmØ, H4, 1x30mmØ, Exit: Westinghouse large box. 3 x 6m					
36674	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	194		LHS	Trackside equipment: Westinghouse large box		2			
36675	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	195		LHS	Trackside equipment: Westinghouse large box		1			
39546	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	195		LHS	Trackside equipment: Westinghouse large box		1			
36676	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	200	202	LHS	Cloth. Cable sheath, Entry: Ten Core box, Route: H3 of 4, 1x20mmØ, H4, 1x30mmØ, Exit: Westinghouse large box. 2 x 1.5m					
39653	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	200		LHS	Trackside equipment: tencore box		1			
36678	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	201		LHS	Trackside equipment: Westinghouse large box		1			
36677	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	201		LHS	Trackside equipment: Westinghouse large box		1			
36679	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	202	225	LHS	Cloth. Cable sheath, Entry: Westinghouse large box, Route: H3 of 4, 1x20mmØ, H4, 1x30mmØ, Exit: N/A. 2 x 23.5m					
36680	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	202		LHS	Trackside equipment: Westinghouse small box		1			
36682	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	202		LHS	Trackside equipment: Westinghouse large box		1			



Hazardous Material Asset Register - Summary



P016-P - PIC Line - Southgate to Arnos Grove

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36681	ACTIVE	p	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	202		LHS	Trackside equipment: Westinghouse large box		2			
36683	ACTIVE	p	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	203		LHS	Trackside equipment: Westinghouse large box		1			
36684	ACTIVE	p	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	203		LHS	Trackside equipment: tencore box		1			
36685	ACTIVE	p	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Removed	207		LHS	Trackside equipment: COLR box		1			
36686	ACTIVE	p	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	225	300	LHS	Cloth. Cable sheath, Entry: N/A, Route: H11 of 12, 1x20mmØ, H12, 1x30mmØ, Exit: Ten Core box. 2 x 75m					
39547	ACTIVE	p	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	300	543	LHS	Cloth. Cable sheath, Entry: N/A, Route: H12 of 12, 1x30mmØ, Exit: N/A. 1 x 243m					
36687	ACTIVE	p	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	300		LHS	Trackside equipment: tencore box		1			
36688	ACTIVE	p	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	321		LHS	Trackside equipment: Westinghouse small box		1			
36689	ACTIVE	p	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	324		LHS	Trackside equipment: signal (A903)		1			
36690	ACTIVE	p	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	324		LHS	Trackside equipment: tencore box		1			
36691	ACTIVE	p	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	347		LHS	Trackside equipment: Westinghouse small box		1			
40308	ACTIVE	p	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	348		LHS	Trackside equipment: Westinghouse small box		1			
36692	ACTIVE	p	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	474		LHS	Trackside equipment: Westinghouse small box		1			
36693	ACTIVE	p	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	475		LHS	Trackside equipment: Westinghouse small box		1			
36694	ACTIVE	p	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	543	576	LHS	Cloth. Cable sheath, Entry: N/A, Route: H8 of 8, 1x30mmØ, Exit: N/A. 1 x 33m					
36695	ACTIVE	p	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	576	637	LHS	Cloth. Cable sheath, Entry: N/A, Route: H12 of 12, 1x30mmØ, Exit: N/A. 1 x 60m					
36696	ACTIVE	p	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	612		LHS	Trackside equipment: Fog Repeater (A905)		1			
40309	ACTIVE	p	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	618		LHS	Trackside equipment: Westinghouse small box		1			
39654	ACTIVE	p	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	619		LHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P016-P - PIC Line - Southgate to Arnos Grove

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36697	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	620		LHS	Trackside equipment: Westinghouse small box		1			
36698	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	637	670	LHS	Cloth. Cable sheath, Entry: N/A, Route: H8 of 8, 1x30mmØ, Exit: N/A. 1 x 33m					
36699	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	670	694	LHS	Cloth. Cable sheath, Entry: N/A, Route: H12 of 12, 1x30mmØ, Exit: N/A. 1 x 23.5m					
36700	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	694	702	LHS	Cloth. Cable sheath, Entry: N/A, Route: H3 of 4, 1x30mmØ, Exit: Westinghouse large box. 1 x 8m					
36701	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	699		LHS	Trackside equipment: tencore box		1			
36702	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	700		LHS	Trackside equipment: Westinghouse large box		1			
36703	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	700		LHS	Trackside equipment: Westinghouse large box		1			
36704	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	701		LHS	Trackside equipment: Westinghouse large box		1			
39378	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	701		LHS	Trackside equipment: Westinghouse large box		1			
39655	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	702		LHS	Trackside equipment: Westinghouse large box		1			
36705	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	702	713	LHS	Cloth. Cable sheath, Entry: Westinghouse large box, Route: H3 of 4, 1x30mmØ, Exit: N/A. 1 x 11.5					
36706	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	702		LHS	Trackside equipment: Westinghouse large box		2			
36707	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	703		LHS	Trackside equipment: tencore box		2			
36709	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	713		LHS	Trackside equipment: Westinghouse small box		1			
36708	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	713	915	LHS	Cloth. Cable sheath, Entry: N/A, Route: H4 of 4, 1x30mmØ, Exit: Westinghouse large box. 1 x 201.5m					
36710	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	714		LHS	Trackside equipment: tencore box		1			
36711	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	715		LHS	Trackside equipment: Signal (A903)		1			
36712	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	913		LHS	Trackside equipment: tencore box		1			
36713	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	914		LHS	Trackside equipment: Westinghouse large box		1			



Hazardous Material Asset Register - Summary



P016-P - PIC Line - Southgate to Arnos Grove

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36714	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	914		LHS	Trackside equipment: Westinghouse large box		2			
36715	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	915	1194	LHS	Cloth. Cable sheath, Entry: Westinghouse large box, Route: H4 of 4, 1x30mmØ, Exit: Westinghouse large box.		1			
36716	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	915		LHS	Trackside equipment: Westinghouse large box		1			
36717	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	915		LHS	Trackside equipment: tencore box		3			
36718	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	919		LHS	Trackside equipment: Westinghouse small box		1			
39548	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	920		LHS	Trackside equipment: Westinghouse small box		1			
40310	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	1077		LHS	Trackside equipment: Westinghouse small box		1			
36719	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	1078		LHS	Trackside equipment: tencore box		2			
36721	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	1079		LHS	Trackside equipment: Westinghouse large box		1			
36720	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	1079		LHS	Trackside equipment: Westinghouse large box		1			
36722	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	1080		LHS	Trackside equipment: tencore box		1			
40311	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	1089		LHS	Trackside equipment: Fog Repeater (A907)		1			
36723	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	1089		LHS	Trackside equipment: Signal (R907)		1			
36724	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	1103		LHS	Trackside equipment: Westinghouse small box		1			
36725	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	1104		LHS	Trackside equipment: Westinghouse small box		1			
36727	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	1193		LHS	Trackside equipment: Westinghouse small box		1			
36726	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	1193		LHS	Trackside equipment: tencore box		1			
36728	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	1194		LHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P016-P - PIC Line - Southgate to Arnos Grove

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36729	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1194	1195	LHS	Cloth. Cable sheath, Entry: Westinghouse large box, Route: above Westinghouse large box, 1x30mmØ, below Westinghouse large box, 1x15mmØ, Exit: N/A. 2 X 1M					
36730	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	1194		LHS	Trackside equipment: Westinghouse small box		2			
36731	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	1195		LHS	Trackside equipment: Westinghouse small box		1			
36732	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1195	1251	LHS	Cloth. Cable sheath, Entry: Ten Core box, Route: H2 of 4, 1x15mmØ, H3, 1x15mmØ, H4, 1x30mmØ, Exit: N/A 3 X 56m					
36733	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	1195		LHS	Trackside equipment: tencore box		2			
36735	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	1199		LHS	Trackside equipment: Signal (A907)		1			
36734	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	1199		LHS	Trackside equipment: Westinghouse small box		1			
39549	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	1201		LHS	Trackside equipment: tencore box		1			
36736	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	1212		LHS	Trackside equipment: Westinghouse small box		1			
36737	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	1214		LHS	Trackside equipment: Westinghouse small box		1			
36738	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1251	1257	LHS	Cloth. Cable sheath, Entry: N/A, Route: H7 of 9, 1x15mmØ, H8, 1x15mmØ, H9, 1x30mmØ, Exit: OTX to RHS. 3 x 6m					
39656	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1257	1456	RHS	Cloth. Cable sheath, Entry: OTX to LHS, Route: H2 of 4, 1x15mmØ, H3, 1x15mmØ, H4, 1x30mmØ, Exit: Ten Core box. 3 x 198.5m					
36739	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1278	1279	RHS	Cloth. Cable sheath, H4, 1x30mmØ, spliced & mounted below H4. 1 x 1m					
36740	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	1359		RHS	Trackside equipment: tencore box		1			
36741	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1456	1466	RHS	Cloth. Cable sheath, Entry: Ten Core box, Route: H2 of 4, 2x8mmØ, H3, 1x15mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 4 x 8m					
36742	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	1456		RHS	Trackside equipment: tencore box		1			
36743	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	1459		RHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P016-P - PIC Line - Southgate to Arnos Grove

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36744	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	1464		RHS	Trackside equipment: Westinghouse small box		1			
40387	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1464	1661	RHS	Cloth. Cable sheath, Entry: N/A, Route: H2 of 4, 1x8mmØ, H3, 1x15mmØ, H4, 1x30mmØ, Exit: N/A. 3 x 197m					
36745	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	1641		RHS	Trackside equipment: Westinghouse small box		1			
36746	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	1642		RHS	Trackside equipment: Westinghouse small box		1			
36747	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	1658		RHS	Trackside equipment: Signal (R909B)		1			
36749	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	1659		RHS	Trackside equipment: Westinghouse small box		1			
36748	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	1659		RHS	Trackside equipment: Signal (A909A)		1			
36750	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	1660		RHS	Trackside equipment: Westinghouse small box		1			
40388	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	1660		RHS	Trackside equipment: tencore box		1			
36752	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	1661		RHS	Trackside equipment: Westinghouse large box		1			
36751	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1661	1662	RHS	Cloth. Cable sheath, Entry: Westinghouse large box, Route: H2 of 4, 1x8mmØ, H3, 1x8mmØ, 1x15mmØ, H4, 1x30mmØ, Exit: Ten Core box. 4 x 1m					
36754	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	1662		RHS	Trackside equipment: tencore box		1			
36753	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1662	1800	RHS	Cloth. Cable sheath, Entry: Ten Core box, Route: H2 of 4, 1x8mmØ, H3, 1x8mmØ, 1x15mmØ, H4, 1x30mmØ, Exit: Westinghouse large box. 4 x 138.5m					
39657	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	1667		RHS	Trackside equipment: Westinghouse small box		1			
36755	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	1673		RHS	Trackside equipment: Westinghouse small box		1			
36756	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1763	1764	RHS	Cloth. Cable sheath, H4, 1x30mmØ, spliced & mounted below H4. 1 x 1m					
36757	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	1797		RHS	Trackside equipment: Signal (A909B)		1			
36758	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	1798		RHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P016-P - PIC Line - Southgate to Arnos Grove

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36759	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	1799		RHS	Trackside equipment: tencore box		1			
36760	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	1800		RHS	Trackside equipment: Westinghouse small box		1			
36761	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1800	1801	RHS	Cloth. Cable sheath, Entry: Westinghouse large box, Route: H2 of 4, 2x8mmØ, H3, 1x15mmØ, H4, 1x30mmØ, Exit: N/A. 4 x 1m					
36762	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	1800		RHS	Trackside equipment: Westinghouse large box		1			
36763	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1801	1804	RHS	Cloth. Cable sheath, Entry: Ten Core box, Route: H2 of 4, 2x8mmØ, H3, 2x15mmØ, H4, 1x30mmØ, Exit: N/A. 5 x 2.5m					
36764	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Signal Boxes	Asbestos	Presumed	1801		RHS	Trackside equipment: tencore box		1			
36765	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Cable Sheath	Asbestos	Strongly Presumed	1804	1861	RHS	Cloth. Cable sheath, Entry: Westinghouse small box, Route: H2 of 4, 3x8mmØ, H3, 2x15mmØ, H4, 1x30mmØ, Exit: Platform wall. 6 x 57.5m					
39550	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	1853		RHS	Trackside equipment: Westinghouse small box		1			
36766	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Westinghouse Boxes	Asbestos	Presumed	1857		RHS	Trackside equipment: Westinghouse small box		1			
36767	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Ducts	Asbestos	Presumed	1860	1861	LHS	Cement. cable duct lining. Presumed present (In floor & sealed)		3			
36768	ACTIVE	P	P016-P-EBLO	Road EBLO - PIC - Arnos Grove to Southgate	Ducts	Asbestos	Presumed	1861		RHS	Cement. cable duct lining. Presumed present (In platform wall & sealed)		3			
41427	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	1	12	RHS	Cloth. cable sheath, Entry: Platform wall, Route: H2 of 4, 1x15mmØ, H3, 1x20mmØ, H4, 1x30mmØ, Exit: Ten Core box. 3 x 11.5m					
41429	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Ducts	Asbestos	Presumed	1	2	LHS	cement, cable duct lining. Presumed present (In floor & sealed)		1			
41428	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Ducts	Asbestos	Presumed	1		LHS	cement, cable duct lining. Presumed present (In platform wall & sealed)		1			
41430	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cement Cable Troughing & Debris	Asbestos	Strongly Presumed	2		UTX	cement debris in ballast. 0.25m					
41431	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cement Cable Troughing & Debris	Asbestos	Known	2			cement cable trough UTX & LHS		1			
41432	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	7		RHS	Trackside equipment: Signal (A908)		1			
41433	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	8		RHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P016-P - PIC Line - Southgate to Arnos Grove

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41434	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	8		RHS	Trackside equipment: tencore box		1			
39856	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	11		RHS	Trackside equipment: Westinghouse large box		1			
41435	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	12	26	RHS	Cloth, cable sheath, Entry: Ten Core box, Route: H2 of 4, 1x15mmØ, H3, 1x15mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 3 x 13.5m					
41436	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	12		RHS	Trackside equipment: tencore box		1			
41437	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	15	16	RHS	Cloth. cable sheath, H4, 1x30mmØ, spliced & mounted below H4. 1 x1m					
41438	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	23		RHS	Trackside equipment: Westinghouse small box		1			
41439	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	26	530	RHS	Cloth. cable sheath, Entry: N/A, Route: H3 of 4, 1x15mmØ, H4, 1x30mmØ, Exit: Signals trackside equipment. 2 x 504.5m					
41440	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	26		RHS	Trackside equipment: Westinghouse small box		1			
41441	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	29		RHS	Trackside equipment: Westinghouse small box		1			
39573	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	108		RHS	Trackside equipment: type 79		1			
41442	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	110		RHS	Trackside equipment: Westinghouse small box		1			
41443	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	113		RHS	Trackside equipment: Westinghouse small box		1			
40041	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	160		RHS	Trackside equipment: Westinghouse small box		1			
41444	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	165		RHS	Trackside equipment: Westinghouse small box		1			
41445	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	507	508	RHS	Cloth. cable sheath, H4, 1x30mmØ, spliced & mounted below H4. 1 x1m					
41446	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	530		RHS	Trackside equipment: Signal (R. 904/1)		1			
39574	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	530	533	RHS	Cloth. cable sheath, Entry: N/A, Route: Between trackside equipment, H3 & H4, 8mmØ to 30mmØ, Exit: N/A. numerous amounts					
41524	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	531		RHS	Trackside equipment: type 79 box		1			



Hazardous Material Asset Register - Summary



P016-P - PIC Line - Southgate to Arnos Grove

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41523	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	531		RHS	Trackside equipment: Signal (A906)		1			
41525	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	532		RHS	Trackside equipment: tencore box		1			
41526	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	533	537	RHS	Cloth. cable sheath, Entry: Signals trackside equipment, Route: H3 of 4, 7x8mmØ, 1x15mmØ, H4, 1x30mmØ, Exit: Signals trackside equipment. 9 x 4m					
41527	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	533		RHS	Trackside equipment: Westinghouse small box		1			
41528	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	536		RHS	Trackside equipment: Howells box		1			
41529	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	537		RHS	Trackside equipment: Westinghouse large box		1			
39860	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	537	542	RHS	Cloth. cable sheath, Entry: N/A, Route: Between trackside equipment, H2, H3 & H4, 8mmØ to 30mmØ, Exit: N/A. numerous amounts					
41530	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	538		RHS	Trackside equipment: Westinghouse large box		1			
41531	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	539		RHS	Trackside equipment: Westinghouse large box		1			
41532	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	540		RHS	Trackside equipment: Westinghouse large box		2			
41533	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	541		RHS	Trackside equipment: tencore box		1			
41535	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	542	547	RHS	Cloth. cable sheath, Entry: Signals trackside equipment, Route: H2 of 4, 2x15mmØ, H3, 1x8mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 4 x 5m					
41536	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	542		RHS	Trackside equipment: tencore box		1			
41534	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	542		RHS	Trackside equipment: Westinghouse small box		1			
41538	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	547		RHS	Trackside equipment: Westinghouse small box		1			
41537	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	547	599	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, 2x15mmØ, H4, 1x30mmØ, Exit: OTX to LHS. 3 x 51.5m					
41539	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	599	609	LHS	Cloth. cable sheath, Entry: OTX to RHS, Route: H8 of 10, 2x15mmØ, H10, 1x30mmØ, Exit: N/A. 3 x 10.5					



Hazardous Material Asset Register - Summary



P016-P - PIC Line - Southgate to Arnos Grove

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39580	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	609	758	LHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, 2x15mmØ, H4, 1x30mmØ, Exit: Ten Core box. 3 x 149m					
40045	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	621		LHS	Trackside equipment: T Junction box		1			
41540	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	623		LHS	Trackside equipment: Type 79 box		1			
41542	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	758		LHS	Trackside equipment: tencore box		1			
41541	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	758	760	LHS	Cloth. cable sheath, Entry: Ten Core box, Route: H2 of 4, 2x8mmØ, 1x15mmØ, H4, 1x30mmØ, Exit: Westinghouse large box. 3 x 2m					
41543	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	760	766	LHS	Cloth. cable sheath, Entry: Westinghouse large box, Route: H2 of 4, 3x8mmØ, H4, 1x30mmØ, Exit: Fog Repeater. 4 x6m					
41544	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	760		LHS	Trackside equipment: Westinghouse large box		2			
39581	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	766	807	LHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, 2x8mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 3 x 2m					
41545	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	766		LHS	Trackside equipment: Signal (904/2)		1			
41546	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	766		LHS	Trackside equipment: Fog Repeater (A904)		1			
41547	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	784	785	LHS	Cloth. cable sheath, H4, 1x30mmØ, spliced & mounted below H4. 1 x 1					
41625	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	807		LHS	Trackside equipment: Westinghouse small box		1			
41624	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	807	811	LHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, 1x8mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 2 x 4m					
41626	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	811	874	LHS	Cloth. cable sheath, Entry: N/A, Route: H4 of 4, 1x30mmØ, Exit: Signals trackside equipment. 1 x 63m					
41627	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	811		LHS	Trackside equipment: Westinghouse small box		1			
41628	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	873		LHS	Trackside equipment: Westinghouse large box		1			
41630	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	874		LHS	Trackside equipment: Westinghouse large box		2			



Hazardous Material Asset Register - Summary



P016-P - PIC Line - Southgate to Arnos Grove

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41629	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	874	879	LHS	Cloth. cable sheath, Entry: N/A, Route: Between trackside equipment, H2, & H4, 8mmØ to 30mmØ, Exit: N/A. numerous amounts					
41631	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	875		LHS	Trackside equipment: Westinghouse large box		1			
41632	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	876		LHS	Trackside equipment: Westinghouse large box		1			
41633	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	877		LHS	Trackside equipment: Westinghouse small box		1			
39366	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	877		LHS	Trackside equipment: tencore box		1			
41635	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	879		LHS	Trackside equipment: Signal (A904 & R902 PJ350)		2			
41634	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	879	866	LHS	Cloth. cable sheath, Entry: Signals trackside equipment, Route: H2 of 4, 2x8mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 3 x7m					
41637	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	886		LHS	Trackside equipment: Westinghouse small box		1			
41636	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	886	887	LHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, 1x8mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 2 x 1m					
41639	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	887		LHS	Trackside equipment: Westinghouse small box		1			
41638	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	887	1145	LHS	Cloth. cable sheath, Entry: N/A, Route: H4 of 4, 1x30mmØ, Exit: Westinghouse kiosk. 1 x 258m					
41640	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1035		LHS	Trackside equipment: Fog Repeater (A902)		1			
39608	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1065		LHS	Trackside equipment: Westinghouse small box		1			
41641	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1066		LHS	Trackside equipment: Westinghouse small box		1			
41642	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1103		LHS	Trackside equipment: Main earth terminal box		1			
41643	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	1145	1147	LHS	Cloth. cable sheath, Entry: Westinghouse kiosk, Route: Between Westinghouse kiosk, 1x30mmØ, Exit: Westinghouse kiosk. 1 x2m					
39508	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1145		LHS	Trackside equipment: Westinghouse kiosk		1			



Hazardous Material Asset Register - Summary



P016-P - PIC Line - Southgate to Arnos Grove

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39609	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	1147	1151	LHS	Cloth. cable sheath, Entry: Spliced cable, Route: Between Westinghouse kiosk, 1x30mmØ, H3 of 4, 1x15mmØ, Exit: N/A. 2 x10m					
41644	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1148		LHS	Trackside equipment: Westinghouse kiosk		1			
41645	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1150		LHS	Trackside equipment: Westinghouse small box		1			
41646	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	1151	1188	LHS	Cloth. cable sheath, Entry: Westinghouse kiosk, Route: H3 of 4, 2x15mmØ, H4, 1x30mmØ, Exit: N/A. 3 x 37m					
41647	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1151		LHS	Trackside equipment: Westinghouse kiosk		1			
39864	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1152		LHS	Trackside equipment: Westinghouse large box		1			
40123	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1160		LHS	Trackside equipment: Fog Repeater (PJ350)		1			
40122	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1160		LHS	Trackside equipment: Signal (A902)		1			
40124	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1161		LHS	Trackside equipment: Westinghouse small box		1			
40127	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1162		LHS	Trackside equipment: Westinghouse small box		1			
40126	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1162		LHS	Trackside equipment: tencore box		1			
40125	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1162		LHS	Trackside equipment: Westinghouse small box		1			
39467	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1163		LHS	Trackside equipment: Westinghouse small box		1			
39944	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1164		LHS	Trackside equipment: tencore box		1			
40128	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1173		LHS	Trackside equipment: Westinghouse large box		2			
40129	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	1188	1201	LHS	Cloth. cable sheath, Entry: N/A, Route: H11 of 12, 2x15mmØ, H12, 1x30mmØ, Exit: N/A. 3 x 13m					
40130	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	1201	1234	LHS	Cloth. cable sheath, Entry: N/A, Route: H7 of 8, 2x15mmØ, H8, 1x30mmØ, Exit: N/A. 3 x 33m					
40131	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	1234	1271	LHS	Cloth. cable sheath, Entry: N/A, Route: H11 of 12, 2x15mmØ, H12, 1x30mmØ, Exit: N/A. 3 x 37m					
40132	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1252		LHS	Trackside equipment: COLR		1			



Hazardous Material Asset Register - Summary



P016-P - PIC Line - Southgate to Arnos Grove

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40133	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1253		LHS	Trackside equipment: tencore box		1			
40135	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1257		LHS	Trackside equipment: Fog Repeater (PJ25A)		1			
40134	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1257		LHS	Trackside equipment: Signal (PJ350)		1			
40136	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1259		LHS	Trackside equipment: Westinghouse small box		1			
40137	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	1271	1310	LHS	Cloth. cable sheath, Entry: N/A, Route: H7 of 8, 2x15mmØ, H8, 1x30mmØ, Exit: N/A. 3 x 39m					
40138	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1287		LHS	Trackside equipment: Westinghouse small box		1			
39389	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	1310	1384	LHS	Cloth. cable sheath, Entry: N/A, Route: H11 of 12, 2x15mmØ, H12, 1x30mmØ, Exit: N/A. 3 x 74m					
40139	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1343		LHS	Trackside equipment: Westinghouse small box		1			
40140	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	1384	1412	LHS	Cloth. cable sheath, Entry: Spliced cable, Route: H10 of 12, 1x8mmØ, H11, 2x15mmØ, H12, 1x30mmØ, Exit: N/A. 4 x 28m					
39721	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1411		LHS	Trackside equipment: COLR		1			
40141	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	1412	1418	LHS	Cloth. cable sheath, Entry: Ten Core box, Route: H10 of 12, 7x8mmØ, H11, 2x15mmØ, H12, 1x30mmØ, Exit: Signals trackside equipment. 10 x 6m					
40142	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1412		LHS	Trackside equipment: tencore box		2			
40143	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1415		LHS	Trackside equipment: tencore box		1			
39390	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1416		LHS	Trackside equipment: Westinghouse small box		1			
40144	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	1418	1435	LHS	Cloth. cable sheath, Entry: N/A, Route: H11 of 12, 2x15mmØ, H12, 1x30mmØ, Exit: Spliced cable. 3 x 17m					
40145	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1418		LHS	Trackside equipment: Signal (PJ35A & RPJ35B)		2			
40146	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1430		LHS	Trackside equipment: Westinghouse small box		1			
39469	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1431		LHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P016-P - PIC Line - Southgate to Arnos Grove

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40219	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	1435	1634	LHS	Cloth. cable sheath, Entry: N/A, Route: H11 of 12, 1x15mmØ, H12, 1x30mmØ, Exit: N/A. 2 x 199m					
40220	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Strongly Presumed	1471		LHS	Trackside equipment: type 79 box		1			
40221	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1498		LHS	Trackside equipment: Fog Repeater (PJ35B)		1			
40222	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1515		LHS	Trackside equipment: Westinghouse small box		1			
39946	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1516		LHS	Trackside equipment: Westinghouse small box		1			
40223	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1605		LHS	Trackside equipment: Signal (PJ35B)		1			
40224	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1605		LHS	Trackside equipment: Fog Repeater (PJ34)		1			
40225	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1605		LHS	Trackside equipment: tencore box		2			
40226	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1607		LHS	Trackside equipment: Westinghouse small box		1			
40227	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1612		LHS	Trackside equipment: Westinghouse small box		1			
40228	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1613		LHS	Trackside equipment: Westinghouse small box		1			
40229	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	1634	1654	LHS	Cloth. cable sheath, Entry: N/A, Route: H3 of 4, 1x15mmØ, H4, 1x30mmØ, Exit: Westinghouse kiosk. 2 x 19.5m					
40230	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1637		LHS	Trackside equipment: tencore box		1			
40232	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1654		LHS	Trackside equipment: Westinghouse kiosk		1			
40231	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	1654	1665	LHS	Cloth. cable sheath, Entry: Westinghouse kiosk, Route: H3 of 4, 1x15mmØ, H4, 1x30mmØ, Exit: Westinghouse large box. 2 x 11m					
40233	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1664		LHS	Trackside equipment: tencore box		1			
39394	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1665		LHS	Trackside equipment: Westinghouse large box		1			
40235	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1665		LHS	Trackside equipment: Westinghouse large box		1			
40234	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	1665	1666	LHS	Cloth. cable sheath, Entry: N/A, Route: H4 of 4, 1x30mmØ, Exit: Westinghouse large box. 1 x 1m					



Hazardous Material Asset Register - Summary



P016-P - PIC Line - Southgate to Arnos Grove

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40237	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1666		LHS	Trackside equipment: Westinghouse large box		1			
39724	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	1666	1709	LHS	Cloth. cable sheath, Entry: Westinghouse large box, Route: H4 of 4, 1x30mmØ, Exit: Westinghouse large box. 1x 43m					
40236	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1666		LHS	Trackside equipment: Westinghouse large box		2			
40238	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1667		LHS	Trackside equipment: Westinghouse large box		1			
40239	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1670		LHS	Trackside equipment: Westinghouse small box		1			
39395	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1671		LHS	Trackside equipment: Westinghouse small box		1			
40240	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Current Rail Boxes	Asbestos	Presumed	1703		RHS	Yellow Current Rail Section box		2			
40241	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1708		LHS	Trackside equipment: Westinghouse large box		1			
40242	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	1709	1755	LHS	Cloth. cable sheath, Entry: Westinghouse large box, Route: H4 of 4, 1x30mmØ, Exit: N/A. 1 x 46.5m					
40243	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1709		LHS	Trackside equipment: Westinghouse large box		2			
40312	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1709		LHS	Trackside equipment: Westinghouse large box		1			
40313	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1710		LHS	Trackside equipment: Westinghouse large box		1			
40314	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1717		LHS	Trackside equipment: grey box		1			
40315	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1723		LHS	Trackside equipment: tencore box		1			
40316	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1724		LHS	Trackside equipment: Fog Repeater (PJ33)		1			
39947	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1724		LHS	Trackside equipment: Signal (PJ34)		1			
40317	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1725		LHS	Trackside equipment: Westinghouse small box		1			
40318	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1726		LHS	Trackside equipment: Westinghouse small box		1			
40319	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1727		LHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P016-P - PIC Line - Southgate to Arnos Grove

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40320	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	1730		LHS	Cloth. cable sheath, H4, 1x30mmØ, spliced & mounted below H4. 1 x1m					
40321	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1736		LHS	Trackside equipment: Westinghouse small box		1			
40322	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1752		LHS	Trackside equipment: silver box		2			
40323	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1753		LHS	Trackside equipment: silver box		2			
40324	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	1755	1797	LHS	Cloth. cable sheath, Entry: Spliced cable, Route: H2 of 4, 2x15mmØ, H4, 1x30mmØ, Exit: Westinghouse large box. 3 x 41.5m					
40325	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Current Rail Boxes	Asbestos	Presumed	1770		RHS	Yellow Current Rail Section box		2			
40326	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1796		LHS	Trackside equipment: Westinghouse large box		1			
40327	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	1797	1841	LHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 8, 2x15mmØ, Exit: Spliced cable. 3 x 44.5m					
40328	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1797		LHS	Trackside equipment: Westinghouse large box		2			
40329	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1797		LHS	Trackside equipment: Westinghouse large box		1			
39399	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1807		LHS	Trackside equipment: Westinghouse small box		1			
40330	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1807		LHS	Trackside equipment: Signal (PJ33)		1			
40331	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1808		LHS	Trackside equipment: tencore box		1			
40332	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1808		LHS	Trackside equipment: Westinghouse small box					
40333	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1809		LHS	Trackside equipment: 600 Volts Kiosk		1			
40334	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1811		LHS	Trackside equipment: 600 Volts AC box		1			
40335	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1821		LHS	Trackside equipment: 650 Volts Kiosk		1			
39400	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1841		LHS	Trackside equipment: silver box		2			
39726	ACTIVE	p	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1842		RHS	Trackside equipment: silver box		2			



Hazardous Material Asset Register - Summary



P016-P - PIC Line - Southgate to Arnos Grove

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39948	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Cement Cable Troughing & Debris	Asbestos	Strongly Presumed	1842		RHS	cement debris, On floor before Silver box trackside equipment. Further debris likely beneath redundant rails & stored items. 0.25m					
40336	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1855		LHS	Trackside equipment: Westinghouse small box		1			
40410	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1857		LHS	Trackside equipment: Westinghouse small box		1			
40337	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1857		LHS	Trackside equipment: tencore box		1			
40411	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Signal Boxes	Asbestos	Presumed	1857		LHS	Trackside equipment: tencore box		1			
40412	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1859		LHS	Trackside equipment: Westinghouse small box		1			
40413	ACTIVE	P	P016-P-WBLO	Road WBLO - PIC - Southgate to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1861		LHS	Trackside equipment: Westinghouse small box		1			

P021-P - PIC Line - Arnos Grove Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36769	ACTIVE	P	P021-P-EBLO	Road EBLO (Plt1) - PIC - Arnos Grove Stn	Cable Sheath	Asbestos	Strongly Presumed	0	84	LHS	Cloth. Entry: EB P-Way, Route: H6 of 6, 1x30mmØ, Exit: N/A. 1 x 84m					
36772	ACTIVE	P	P021-P-EBLO	Road EBLO (Plt1) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	0		RHS	Trackside equipment: tencore box		1			
40389	ACTIVE	P	P021-P-EBLO	Road EBLO (Plt1) - PIC - Arnos Grove Stn	Westinghouse Boxes	Asbestos	Presumed	0		RHS	Trackside equipment: Westinghouse small box		1			
36770	ACTIVE	P	P021-P-EBLO	Road EBLO (Plt1) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	0		RHS	Trackside equipment: Signal (PJ30 PJ27)		1			
36771	ACTIVE	P	P021-P-EBLO	Road EBLO (Plt1) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	0		RHS	Trackside equipment:Rail Gap Ind. Box		1			
36773	ACTIVE	P	P021-P-EBLO	Road EBLO (Plt1) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	7		RHS	Trackside equipment: Redifon loop aerial box		1			
36774	ACTIVE	P	P021-P-EBLO	Road EBLO (Plt1) - PIC - Arnos Grove Stn	Westinghouse Boxes	Asbestos	Presumed	45		LHS	Trackside equipment: Westinghouse small box		1			
36775	ACTIVE	P	P021-P-EBLO	Road EBLO (Plt1) - PIC - Arnos Grove Stn	Westinghouse Boxes	Asbestos	Presumed	50		LHS	Trackside equipment: Westinghouse small box		1			
36776	ACTIVE	P	P021-P-EBLO	Road EBLO (Plt1) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	64		RHS	Trackside equipment: 230 Volts box		1			



Hazardous Material Asset Register - Summary



P021-P - PIC Line - Arnos Grove Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39658	ACTIVE	P	P021-P-EBLO	Road EBLO (Plt1) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	68		LHS	Trackside equipment: Grey box		1			
36777	ACTIVE	P	P021-P-EBLO	Road EBLO (Plt1) - PIC - Arnos Grove Stn	Cable Sheath	Asbestos	Strongly Presumed	84	116	LHS	Cloth. Cable sheath, Entry: N/A, Route: H3 of 4, 1x30mmØ, Exit: WHL. 1 x 31.5m					
36778	ACTIVE	P	P021-P-EBLO	Road EBLO (Plt1) - PIC - Arnos Grove Stn	Westinghouse Boxes	Asbestos	Presumed	102		LHS	Trackside equipment: Westinghouse small box		1			
36779	ACTIVE	P	P021-P-EBLO	Road EBLO (Plt1) - PIC - Arnos Grove Stn	Westinghouse Boxes	Asbestos	Presumed	115		LHS	Trackside equipment: Westinghouse small box		1			
36783	ACTIVE	P	P021-P-EBLO	Road EBLO (Plt1) - PIC - Arnos Grove Stn	Westinghouse Boxes	Asbestos	Presumed	116		LHS	Trackside equipment: Westinghouse large box		1			
36781	ACTIVE	P	P021-P-EBLO	Road EBLO (Plt1) - PIC - Arnos Grove Stn	Westinghouse Boxes	Asbestos	Presumed	116		LHS	Trackside equipment: Westinghouse large box		2			
36782	ACTIVE	P	P021-P-EBLO	Road EBLO (Plt1) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	116		LHS	trackside equipment: Correct side door enable box		3			
36780	ACTIVE	P	P021-P-EBLO	Road EBLO (Plt1) - PIC - Arnos Grove Stn	Cable Sheath	Asbestos	Strongly Presumed	116	123	LHS	Cloth. Cable sheath, Entry: WHL, Route: H4 of 4, 1x30mmØ, Exit: EB P-Way. 1 x 7.5m					
39551	ACTIVE	P	P021-P-EBLO	Road EBLO (Plt1) - PIC - Arnos Grove Stn	Westinghouse Boxes	Asbestos	Presumed	116		LHS	Trackside equipment: Westinghouse large box		1			
36784	ACTIVE	P	P021-P-EBLO	Road EBLO (Plt1) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	119		RHS	Trackside equipment: Redifon loop aerial box		1			
36785	ACTIVE	P	P021-P-EBLO	Road EBLO (Plt1) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	123		RHS	Trackside equipment: Signal (PJ5)		1			
36786	ACTIVE	P	P021-P-EBLO	Road EBLO (Plt1) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	123		RHS	Trackside equipment: Rail Gap Ind. Box		1			
36787	ACTIVE	P	P021-P-EBLO	Road EBLO (Plt1) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	123		RHS	Trackside equipment: tencore box		1			
36788	ACTIVE	P	P021-P-SLLO	Road SLLO (Plt2/3) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	0		RHS	Trackside equipment: Rail Gap Ind. Box		1			
46149	ACTIVE	P	P021-P-SLLO	Road SLLO (Plt2/3) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	0		RHS	Trackside equipment: Signal (PJ31 PJ28)		1			
36789	ACTIVE	P	P021-P-SLLO	Road SLLO (Plt2/3) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	0		RHS	Trackside equipment: tencore box		3			
36790	ACTIVE	P	P021-P-SLLO	Road SLLO (Plt2/3) - PIC - Arnos Grove Stn	Westinghouse Boxes	Asbestos	Presumed	1		RHS	Trackside equipment: Westinghouse small box		1			
36791	ACTIVE	P	P021-P-SLLO	Road SLLO (Plt2/3) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	7		LHS	Trackside equipment: Redifon loop aerial box		1			
36792	ACTIVE	P	P021-P-SLLO	Road SLLO (Plt2/3) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	22		RHS	Trackside equipment: grey box		1			



Hazardous Material Asset Register - Summary



P021-P - PIC Line - Arnos Grove Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36793	ACTIVE	P	P021-P-SLLO	Road SLLO (Plt2/3) - PIC - Arnos Grove Stn	Westinghouse Boxes	Asbestos	Presumed	45		RHS	Trackside equipment: Westinghouse small box		1			
40390	ACTIVE	P	P021-P-SLLO	Road SLLO (Plt2/3) - PIC - Arnos Grove Stn	Westinghouse Boxes	Asbestos	Presumed	50		LHS	Trackside equipment: Westinghouse small box		1			
36794	ACTIVE	P	P021-P-SLLO	Road SLLO (Plt2/3) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	100		RHS	Trackside equipment: grey box		1			
36795	ACTIVE	P	P021-P-SLLO	Road SLLO (Plt2/3) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	119		RHS	Trackside equipment: Redifon loop aerial box		1			
36796	ACTIVE	P	P021-P-SLLO	Road SLLO (Plt2/3) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	122		RHS	Trackside equipment: tencore box		1			
36797	ACTIVE	P	P021-P-SLLO	Road SLLO (Plt2/3) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	122			Trackside equipment: Signal (PJ6)		1			
39659	ACTIVE	P	P021-P-SLLO	Road SLLO (Plt2/3) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	122			Trackside equipment: Signal (PJ6)		1			
36798	ACTIVE	P	P021-P-SLLO	Road SLLO (Plt2/3) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	122		RHS	Trackside equipment: tencore box		1			
40391	ACTIVE	P	P021-P-SLLO	Road SLLO (Plt2/3) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	122		RHS	Trackside equipment: blue kiosk		1			
46150	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	0		RHS	Trackside equipment: Redifon loop aerial box		1			
36799	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Westinghouse Boxes	Asbestos	Presumed	3		LHS	Trackside equipment: Westinghouse small box		1			
36800	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Westinghouse Boxes	Asbestos	Presumed	6		LHS	Trackside equipment: Westinghouse large box		1			
36801	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Cable Sheath	Asbestos	Strongly Presumed	7	24	LHS	Cloth. Cable sheath, Entry: Westinghouse large box, Route: H3 of 8, 1x8mmØ, H4, 1x30mmØ, Exit: N/A. 2 x 17.5m					
36802	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Westinghouse Boxes	Asbestos	Presumed	7		LHS	Trackside equipment: Westinghouse large box		2			
40392	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Westinghouse Boxes	Asbestos	Presumed	7		LHS	Trackside equipment: Westinghouse large box		1			
36625	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Westinghouse Boxes	Asbestos	Presumed	8		LHS	Trackside equipment: Westinghouse large box		1			
36626	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	11		LHS	Trackside equipment: tencore box		1			
36627	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	15		LHS	Trackside equipment: grey box		1			
36628	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Cable Sheath	Asbestos	Strongly Presumed	24	61	LHS	Cloth. Cable sheath, Entry: N/A, Route: H3 of 4, 1x8mmØ, H4, 1x30mmØ, Exit: Up building wall. 2 x 37m					



Hazardous Material Asset Register - Summary



P021-P - PIC Line - Arnos Grove Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39650	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Westinghouse Boxes	Asbestos	Presumed	32		LHS	Trackside equipment: Westinghouse small box		1			
36629	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	35		LHS	Trackside equipment: Type 79 box		1			
36630	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Westinghouse Boxes	Asbestos	Presumed	37		LHS	Trackside equipment: Westinghouse small box		1			
36632	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	55		LHS	Trackside equipment: Signal (PJ320)		2			
36631	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Westinghouse Boxes	Asbestos	Presumed	55		LHS	Trackside equipment: Westinghouse small box		1			
36633	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	57		LHS	Trackside equipment: tencore box		1			
36634	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Cable Sheath	Asbestos	Strongly Presumed	61	72	LHS	Cloth. Cable sheath, Entry: N/A, Route: H4 of 4, 1x30mmØ, Exit: N/A. 1 x 11m					
36635	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Cable Sheath	Asbestos	Strongly Presumed	67		RHS	Cloth. Cable sheath, Entry: Platform signal, Route: H1 of 1, 1x15mmØ Exit: OTX to LHS					
36636	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Cable Sheath	Asbestos	Strongly Presumed	72	123	LHS	Cloth. Cable sheath, Entry: OTX to RHS, Route: H2 of 4, 1x15mmØ, H4, 1x30mmØ, Exit: WB P-Way. 2 x 51m					
39545	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Westinghouse Boxes	Asbestos	Presumed	76			Trackside equipment: Westinghouse small box		1			
36637	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Westinghouse Boxes	Asbestos	Presumed	76			Trackside equipment: Westinghouse small box		1			
36638	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Westinghouse Boxes	Asbestos	Presumed	81			Trackside equipment: Westinghouse small box		1			
36639	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Westinghouse Boxes	Asbestos	Presumed	81			Trackside equipment: Westinghouse small box		1			
36640	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Westinghouse Boxes	Asbestos	Presumed	83		LHS	Trackside equipment: Westinghouse small box		1			
36641	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	84		LHS	Trackside equipment: tencore box		1			
36642	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	115		RHS	Trackside equipment: Redifon loop aerial box		1			
40304	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Westinghouse Boxes	Asbestos	Presumed	122		LHS	Trackside equipment: Westinghouse small box		1			
36643	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Westinghouse Boxes	Asbestos	Presumed	123		RHS	Trackside equipment: Westinghouse small box		1			
36644	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	123		RHS	Trackside equipment: tencore box		3			



Hazardous Material Asset Register - Summary



P021-P - PIC Line - Arnos Grove Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36645	ACTIVE	P	P021-P-WBLO	Road WBLO (Plt4) - PIC - Arnos Grove Stn	Signal Boxes	Asbestos	Presumed	123		RHS	Trackside equipment: Rail Gap Ind. Box		1			

P022-P - PIC Line - Arnos Grove to Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36978	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	1	14	RHS	Cloth. Cable sheath, Entry: Platform wall, Route: H2 of 4, 4x15mmØ, H3, 1x15mmØ, 1x20mmØ, H4, 1x30mmØ, Exit: Ten Core box. 7 x 12.5m					
36979	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Ducts	Asbestos	Presumed	1		LHS	Cementitious. cable duct lining, Presumed present (in platform wall & sealed).		9			
36980	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Ducts	Asbestos	Presumed	2	3	LHS	Cementitious. cable duct lining, Presumed present (in floor and sealed)		1			
36981	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cement Cable Troughing & Debris	Asbestos	Strongly Presumed	3		LHS	Cementitious. Cable troughing, at floor level. 0.25m					
36982	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	5	6	RHS	Cloth. Cable sheath, H4, 1x30mmØ, spliced & mounted below H4. 1 x 1m					
40407	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	9		RHS	Trackside equipment: Signal (A891)		1			
36984	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	10		RHS	Trackside equipment: tencore box		1			
36983	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	10		RHS	Trackside equipment: Westinghouse small box		1			
36985	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	13		RHS	Trackside equipment: Westinghouse large box		1			
40408	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	14		RHS	Trackside equipment: tencore box		1			
39667	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	14	17	RHS	Cloth. Cable sheath, Entry: Westinghouse small box, Route: H2 of 4, 4x15mmØ, H3, 1x20mmØ, H4, 1x30mmØ, Exit:Ten Core box. 6 x 3m					
36986	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	14	14	RHS	Cloth. Cable sheath, Entry: N/A, Route: H2 of 4, 4x15mmØ, H3, 1x20mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 6 x 0.5m					
36987	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	14		RHS	Trackside equipment: tencore box		1			
39558	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	15		RHS	Trackside equipment: Westinghouse small box		1			
36989	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	17		RHS	Trackside equipment: tencore box		1			



Hazardous Material Asset Register - Summary



P022-P - PIC Line - Arnos Grove to Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36988	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	17	75	RHS	Cloth. Cable sheath, Entry: N/A, Route: H2 of 4, 3x15mmØ, H3, 1x20mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 5 x 58m					
36990	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	20		RHS	Trackside equipment: Westinghouse small box		1			
36992	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	75	171	RHS	Cloth. Cable sheath, Entry: N/A, Route: H2 of 4, 2x15mmØ, H3, 1x20mmØ, H4, 1x30mmØ, Exit: Ten Core box. 4 x 96m					
36993	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	75		RHS	Trackside equipment: Westinghouse small box		1			
36991	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	75		RHS	Trackside equipment: Westinghouse small box		1			
36994	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	80		RHS	Trackside equipment: Westinghouse small box		1			
36995	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	164		RHS	Trackside equipment: Signal (R895)		1			
36996	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	164		RHS	Trackside equipment: Signal (A8911)		1			
36997	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	165		RHS	Trackside equipment: Westinghouse small box		1			
36998	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	166		RHS	Trackside equipment: tencore box		1			
39668	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	169		RHS	Trackside equipment: Westinghouse large box		1			
36999	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	170		RHS	Trackside equipment: Westinghouse large box		1			
37000	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	171	172	RHS	Cloth. Cable sheath, Entry: N/A, Route: H2 of 4, 2x15mmØ, H4, 1x30mmØ, Exit: Ten Core box. 3 x 0.5m					
37001	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	171		RHS	Trackside equipment: tencore box		1			
37004	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	172		RHS	Trackside equipment: Westinghouse small box		1			
37002	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	172	178	RHS	Cloth. Cable sheath, Entry: Ten Core box, Route: H2 of 4, 2x15mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 3 x 6.5m					
37003	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	172		RHS	Trackside equipment: tencore box		1			
37005	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	178	358	RHS	Cloth. Cable sheath, Entry: N/A, Route: H2 of 4, 1x15mmØ, H4, 1x30mmØ, Exit: N/A. 2 x 180m					



Hazardous Material Asset Register - Summary



P022-P - PIC Line - Arnos Grove to Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37006	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	178		RHS	Trackside equipment: Westinghouse small box		1			
39380	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	178		RHS	Trackside equipment: Westinghouse small box		1			
40409	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	292		RHS	Trackside equipment: type 79 box		1			
37007	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	346		RHS	Trackside equipment: tencore box		1			
37008	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	348		RHS	Trackside equipment: Signal (A895)		1			
37009	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	349		RHS	Trackside equipment: Westinghouse small box		1			
37010	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	357	358	RHS	Cloth. Cable sheath, H4, 1x30mmØ, spliced & mounted below H4		1			
37011	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	358		RHS	Trackside equipment: tencore box		1			
39736	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	358	360	RHS	Cloth. Cable sheath, Entry: Ten Core box, Route: H2 of 4, 1x15mmØ, H3, 1x20mmØ, H4, 1x30mmØ, Exit: Ten Core box. 3 x 2m					
37012	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	359		RHS	Trackside equipment: Westinghouse large box		1			
39559	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	360	375	RHS	Cloth. Cable sheath, Entry: N/A, Route: H3 of 4, 1x30mmØ, H4, 1x30mmØ, Exit: N/A. 2 x 15m					
37013	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	360		RHS	Trackside equipment: tencore box		1			
37014	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	370		RHS	Trackside equipment: Westinghouse small box		1			
36803	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	375	544	RHS	Cloth. Cable sheath, Entry: Westinghouse small box, Route: H2 of 4, 1x15mmØ, H3, 1x20mmØ, H4, 1x30mmØ, Exit: N/A. 3 x 168.5m					
36804	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	375		RHS	Trackside equipment: Westinghouse small box		1			
36805	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	511		RHS	Trackside equipment: Main earth terminal box		1			
36806	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	544	618	RHS	Cloth. Cable sheath, Entry: Signals trackside equipment, Route: H2 of 4, 1x15mmØ, H3, 1x15mmØ, 1x20mmØ, H4, 1x30mmØ, Exit: OTX to LHS. 4 x 74.5m					
36807	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	544		RHS	Trackside equipment: Signal (RPJ1)		1			



Hazardous Material Asset Register - Summary



P022-P - PIC Line - Arnos Grove to Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36808	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	563		RHS	Trackside equipment: Westinghouse small box		1			
36809	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	567		RHS	Trackside equipment: Westinghouse small box		1			
36810	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	578		RHS	Trackside equipment: Westinghouse small box		1			
36811	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	614	615	RHS	Cloth. Cable sheath, H4, 1x30mmØ, spliced & mounted below H4. 1 x 1m					
36812	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	618	624	LHS	Cloth. Cable sheath, Entry: OTX to RHS, Route: H2 of rear 4, 1x15mmØ, H3, 1x15mmØ, 1x20mmØ, H4, 1x30mmØ, Exit: N/A. 4 x 6m					
39552	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	624	628	LHS	Entry: N/A, Route: H10 of 12, 1x15mmØ, H11, 1x15mmØ, 1x20mmØ, H12, 1x30mmØ, Exit: Ten Core box. 4 x 4m					
36814	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	628		LHS	Trackside equipment: tencore box		1			
36813	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	628	629	LHS	Entry: N/A, Route: H10 of 12, 1x15mmØ, H11, 1x15mmØ, H12, 1x30mmØ, Exit: Ten Core box. 3 x 1m					
36815	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	629		LHS	Trackside equipment: tencore box		1			
36817	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	629		LHS	Trackside equipment: Fog repeater (PJ1)		1			
36818	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	629		LHS	Trackside equipment: tencore box		2			
36816	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	629	634	LHS	Entry: N/A, Route: H10 of 12, 1x15mmØ, H12, 1x30mmØ, Exit: Westinghouse large box. 2 x 5m					
36819	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	632		LHS	Trackside equipment: Westinghouse large box		1			
40393	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	633		LHS	Trackside equipment: Westinghouse large box		1			
36820	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	633		LHS	Trackside equipment: Westinghouse large box		1			
36821	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	634		LHS	Trackside equipment: Westinghouse large box		2			
39660	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	634		LHS	Trackside equipment: Westinghouse large box		1			
36824	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	635		LHS	Trackside equipment: Westinghouse large box		1			



Hazardous Material Asset Register - Summary



P022-P - PIC Line - Arnos Grove to Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36822	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	635	635	LHS	Cloth. Cable sheath, Entry: Westinghouse large box, Route: Above Westinghouse large box, 1x30mmØ, Below Westinghouse large box, 1x15mmØ, Exit: N/A. 2 x 0.5m					
40394	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	635	636	LHS	Cloth. Cable sheath, Entry: Westinghouse large box, Route: Above Westinghouse large box, 1x30mmØ, Below Westinghouse large box, 3x15mmØ, Exit: Westinghouse large box. 4 x 0.5m					
36823	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	635		LHS	Trackside equipment: Westinghouse large box		2			
37039	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	636		LHS	Trackside equipment: Westinghouse large box		1			
36825	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	636	671	LHS	Cloth. Cable sheath, Entry: N/A, Route: H10 of 12, 2x15mmØ, H11, 1x15mmØ, H12, 1x30mmØ, Exit: Westinghouse small box. 3 x 35.5m					
36826	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	636		LHS	Trackside equipment: Westinghouse large box		1			
37040	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	637		LHS	Trackside equipment: Westinghouse large box		1			
37042	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	671		LHS	Trackside equipment: Westinghouse small box		1			
37041	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	671	740	LHS	Cloth. Cable sheath, Entry: N/A, Route: H10 of 11, 1x15mmØ, H11, 1x15mmØ, H12, 1x30mmØ, Exit: N/A. 3 x 69m					
39382	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	672		LHS	Trackside equipment: Westinghouse small box		1			
39670	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	673		LHS	Trackside equipment: Westinghouse small box		1			
37043	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	723		LHS	Trackside equipment: type 79 box		1			
37044	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	734	735	LHS	Cloth. Cable sheath, H12, 1x30mmØ, spliced & mounted below H12. 1 x 1m					
37045	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	737		LHS	Trackside equipment: Westinghouse small box		1			
37046	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	739		LHS	Trackside equipment: Westinghouse large box		1			
37049	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	740		LHS	Trackside equipment: Westinghouse large box		2			



Hazardous Material Asset Register - Summary



P022-P - PIC Line - Arnos Grove to Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37048	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	740	741	LHS	Cloth. Cable sheath, Entry: Westinghouse large box, Route: Above Westinghouse large box, 1x30mmØ, Below Westinghouse large box, 1x15mmØ, H10 of 12, 1x15mmØ, H12, 2x30mmØ, Exit: Westinghouse large box. 5 x 1m					
37047	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	740		LHS	Trackside equipment: Westinghouse large box		1			
37051	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	741	761	LHS	Cloth. Cable sheath, Entry: N/A, Route: H10 of 12, 1x15mmØ, H12, 3x30mmØ, Exit: Westinghouse small box. 4 x 20m					
37052	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	741		LHS	Trackside equipment: Westinghouse large box		1			
37050	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	741		LHS	Trackside equipment: Westinghouse large box		1			
37053	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	744		LHS	Trackside equipment: tencore box		2			
37054	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	749		LHS	Trackside equipment: Signal (PJ1)		1			
39738	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	750		LHS	Trackside equipment: Westinghouse small box		1			
37055	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	761	805	LHS	Cloth. Cable sheath, Entry: N/A, Route: H12 of 12, 3x30mmØ, Exit: Spliced cable. 3 x 44m					
37056	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	761		LHS	Trackside equipment: Westinghouse small box		1			
37057	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	762		LHS	Trackside equipment: Westinghouse small box		1			
39560	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	805	807	LHS	Cloth. Cable sheath, Entry: N/A, Route: H12 of 12, 2x30mmØ, Exit: N/A. 2 x 2m					
37058	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	807	861	LHS	Cloth. Cable sheath, Entry: N/A, Route: H8 of 8, 3x30mmØ, Exit: N/A. 2 x 54m					
39739	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	856		LHS	Trackside equipment: Westinghouse small box		1			
37059	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	858		LHS	Trackside equipment: Westinghouse small box		1			
37060	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	861	869	LHS	Cloth. Cable sheath, Entry: N/A, Route: H12 of 12, 2x30mmØ, Exit: Spliced cable. 2 x 8m					
37061	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	869	936	LHS	Cloth. Cable sheath, Entry: N/A, Route: H12 of 12, 1x30mmØ, Exit: N/A. 1 x 67m					
37062	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	903		LHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P022-P - PIC Line - Arnos Grove to Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37063	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	905		LHS	Trackside equipment: Westinghouse small box		1			
37064	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	936	948	LHS	Cloth. Cable sheath, Entry: N/A, Route: H4 of 4, 1x30mmØ, Exit: N/A. 1 x 14m					
37065	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	948	950	LHS	Cloth. Cable sheath, Entry: N/A, Route: H4 of 8, 1x30mmØ, Exit: N/A. 1 x 2m					
37066	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	948		LHS	Trackside equipment: Type D box		1			
39383	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	949		LHS	Trackside equipment: Westinghouse small box		1			
37068	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	950		LHS	Trackside equipment: Westinghosue kiosk		1			
37067	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	950	1022	LHS	Cloth. Cable sheath, Entry: Westinghouse kiosk, Route: H4 of 8, 2x30mmØ, Exit: Spliced cable. 2 x 71.5					
37069	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	951		LHS	Trackside equipment: Westinghouse small box		1			
37070	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	953		LHS	trackside equipment: Fog repeater (PJ3.4)		1			
39671	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	953		LHS	Trackside equipment: Signal (PJ2)		1			
37071	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	953		LHS	Trackside equipment: Rail Gap Indicator		1			
37072	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	954		LHS	Trackside equipment: tencore box		1			
37073	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	955		LHS	Trackside equipment: tencore box		1			
37074	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	959		LHS	Trackside equipment: kiosk		1			
37075	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	960		LHS	Trackside equipment: Westinghouse small box		1			
37076	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	979		LHS	Trackside equipment: Westinghouse large box		1			
37077	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	980		LHS	Trackside equipment:electrical box		1			
37078	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	997		LHS	Trackside equipment: Westinghouse small box		1			
37079	ACTIVE	p	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	1004		LHS	Trackside equipment: tencore box		1			



Hazardous Material Asset Register - Summary



P022-P - PIC Line - Arnos Grove to Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37080	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1005		LHS	Trackside equipment: Westinghouse small box		2			
39740	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	1005		LHS	Trackside equipment: tencore box		1			
39561	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	1005		LHS	Trackside equipment: tencore box		1			
37081	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1006		LHS	Trackside equipment: Westinghouse small box		1			
37082	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	1009		LHS	Trackside equipment: tencore box		1			
37084	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	1010		LHS	Trackside equipment: tencore box		1			
37083	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1010		LHS	Trackside equipment: Westinghouse small box		1			
37085	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	1011		LHS	Trackside equipment: tencore box		1			
39741	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1013		LHS	Trackside equipment: Westinghouse small box		1			
37086	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1015		LHS	Trackside equipment: Westinghouse small box		2			
37087	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	1015		LHS	Trackside equipment: tencore box		1			
37088	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cement Cable Troughing & Debris	Asbestos	Strongly Presumed	1016		RHS	Cementitious, debris, in ballast. 0.25m ²					
37089	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	1022	1034	LHS	Cloth. Cable sheath, Entry: N/A, Route: H4 of 8, 1x30mmØ, Exit: OTX to sidings. 1 x 12m					
37090	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Current Rail Boxes	Asbestos	Presumed	1037		LHS	Trackside equipment: Yellow current rail switch box		2			
37092	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	1092		LHS	Trackside equipment: tencore box		1			
37091	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	1092		LHS	Trackside equipment: tencore box		1			
37093	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1101		LHS	Trackside equipment: Westinghouse small box		1			
37096	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	1102		LHS	Trackside equipment: tencore box		1			
37095	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1102		LHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P022-P - PIC Line - Arnos Grove to Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37094	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	1102		LHS	Trackside equipment: tencore box		1			
39562	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	1103		LHS	Trackside equipment: tencore box		1			
37097	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	1131		LHS	Trackside equipment: tencore box		1			
37098	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	1132		LHS	Trackside equipment: Type D box		1			
37099	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	1140		LHS	Trackside equipment: Signal (PJ3/500)		1			
37101	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	1140		LHS	Trackside equipment: tencore box		1			
37100	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1140		LHS	Trackside equipment: Westinghouse small box		1			
37103	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	1149		LHS	Trackside equipment: tencore box		1			
37102	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1149		LHS	Trackside equipment: Westinghouse small box		1			
37104	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	1150		LHS	Trackside equipment: tencore box		2			
37105	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1151		LHS	Trackside equipment: Westinghouse large box		1			
39742	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1151		LHS	Trackside equipment: Westinghouse large box		2			
39693	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1152		LHS	Trackside equipment: Westinghouse large box		2			
37107	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Cable Sheath	Asbestos	Strongly Presumed	1152	1158	LHS	Cloth. Cable sheath, Entry: Westinghouse large box, Route: H6 of 6, 1x30mmØ, Exit: Platform grounds. 1 x10m					
37106	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1152		LHS	Trackside equipment: Westinghouse large box		1			
37108	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1153		LHS	Trackside equipment: Westinghouse large box		1			
39743	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Signal Boxes	Asbestos	Presumed	1155		LHS	Trackside equipment: tencore box		1			
37109	ACTIVE	P	P022-P-EBLO	Road EBLO - PIC - Bounds Green to Arnos Grove	Westinghouse Boxes	Asbestos	Presumed	1155		LHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P022-P - PIC Line - Arnos Grove to Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
69369	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Signal Boxes	Asbestos	Presumed	0	0		MATERIAL DESCRIPTION MATERIALS WITHIN WESTINGHOUSE, 10-CORE AND KIOSK BOXES - TO CABLE RUN BEHIND BUFFER 7 NO		7	R714335		
69368	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Signal Boxes	Asbestos	Presumed	2	2		MATERIALS WITHIN RED LIGHT INDICATOR , IN FRONT OF BUFFER -1 NO		1	R714335		
69350	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Signal Boxes	Asbestos	Presumed	2	2		MATERIALS WITHIN KIOSK, TRANSFORMER AND SMALL WESTINGHOUSE - TO CABLE RUN BY BUFFER		4	R714335		
69365	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Cement Cable Troughing & Debris	Asbestos	Known	2	2		BROKEN CEMENT TOUGHING - LOOSE TO CESS BY BUFFER - VISIBLE PIECE REMOVED <1M2 VISIBLE	1	1	R714335		
69370	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Signal Boxes	Asbestos	Presumed	10	10		MATERIALS WITHIN 10-CORE BOXES - TO CABLE RUN - 3 NO		3	R714335		
69371	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Signal Boxes	Asbestos	Presumed	25	25		MATERIALS WITHIN SMALL WESTINGHOUSE BOXES - TO CABLE RUN - 2 NO		2	R714335		
69385	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Signal Boxes	Asbestos	Presumed	35	35		MATERIALS WITHIN 10-CORE BOXES - TO CABLE RUN - NOTE EP VALVE BOXES ARE MODERN 2016 DATE ON LABEL - 4 No		4	R714335		
69386	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Cable Sheath	Asbestos	Presumed	40	40		BRAIDED CABLES - TO CABLE RUN JOINING CABLE BRIDGE - 4No		4	R714335		
69417	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Other Electrical Boxes	Asbestos	Presumed	40	40		ATERIALS WITHIN TRACKSIDE KIOSK - BEHIND CABLE RUN BY CABLE BRIDGE - 1No		1	R714335		
69423	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Other Electrical Boxes	Asbestos	Presumed	60	60		MATERIALS WITHIN EP VALVE BOXES - TO CABLE RUN BY CABLE BRIDGE - 4No		4	R71433		
69420	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Signal Boxes	Asbestos	Presumed	60	60		MATERIALS WITHIN 10-CORE BOXES - TO CABLE RUN BY CABLE BRIDGE - 2No		2	R714335		
69418	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Westinghouse Boxes	Asbestos	Presumed	60	60		MATERIALS WITHIN WESTINGHOUSE BOXES - TO CABLE RUN BY CABLE BRIDGE 3No		3	R714335		
69425	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Signal Boxes	Asbestos	Presumed	65	65		MATERIALS WITHIN VARIOUS ELECTRICAL BOXES - TO CABLE RUN BY 'N17C POINTS' - 10 No		10	R714335		
69431	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Signal Boxes	Asbestos	Presumed	65	65		MATERIALS WITHIN EP VALVE BOXES - NEXT TO 'N17C' POINTS - 1No		1	R714335		
69427	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Other Electrical Boxes	Asbestos	Presumed	65	65		MATERIALS WITHIN VARIOUS ELECTRICAL BOXES - NEXT TO 'N17C' POINTS - 6No		6	R714335		
69428	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Other Electrical Boxes	Asbestos	Presumed	70	70		MATERIALS WITHIN 10-CORE BOXES - TO CABLE RUN -2no		2	R714335		
69437	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Signal Boxes	Asbestos	Presumed	75	90		MATERIALS WITHIN KIOSK, 10-CORE AND WESTINGHOUSE BOXES - TO CABLE RUN - 5No		5	R714335		



Hazardous Material Asset Register - Summary



P022-P - PIC Line - Arnos Grove to Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
69435	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Westinghouse Boxes	Asbestos	Presumed	75	80		MATERIALS WITHIN WESTINGHOUSE BOXES - TO CABLE RUN - 6No		6	R714335		
69438	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Signal Boxes	Asbestos	Presumed	90	90		MATERIALS WITHIN 10-CORE BOX - BY 15 N POINT - 1No		1	R714335		
69439	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Cement Cable Troughing & Debris	Asbestos	Presumed	100	100		CEMENT TROUGHING - BURIED BETWEEN TRACK AND WALKWAY - 2M VISIBLE	2	1	R714335		
69440	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Signal Boxes	Asbestos	Presumed	105	115		MATERIALS WITHIN 10-CORE AND WESTINGHOUSE BOXES - TO CABLE RUN - 2No		2	R714335		
69446	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Signal Boxes	Asbestos	Presumed	105	105		MATERIALS WITHIN EP VALVE BOXES - TO CABLE RUN - NO DATE ON LABEL - 2No BROWN COMPOSITE MOUNT PANEL/BOARD. WHERE WORKS/MAINTENANCE IMPACTS KNOWN ACM BY DRILLING, CUTTING OR REMOVAL. THE HM TEAM MUST BE CONTACTED FOR FURTHER GUIDANCE BEFORE PROCEEDING.		2	R714335		
69447	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Signal Boxes	Asbestos	Presumed	130	140		MATERIAL DESCRIPTION MATERIALS WITHIN 10-CORE AND WESTINGHOUSE BOXES - TO CABLE RUN BY 10 N POINTS - 10 No		10	R714335		
69448	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Signal Boxes	Asbestos	Presumed	180	180		MATERIALS WITHIN TRACKSIDE KIOSK 3 - NEXT TO TRACK - 1No		1	R71433		
69449	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Other Electrical Boxes	Asbestos	Presumed	185	185		MATERIALS WITHIN KIOSK NO 10 AND WESTINGHOUSE BOXES - TO CABLE RUN - 3No		3	R71433		
69451	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Other Electrical Boxes	Asbestos	Presumed	190	190		MATERIALS WITHIN EP VALVE BOXES - BY TRAIN STOP - NO DATE ON LABEL - 2 No		2	R714335		
69450	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Other Electrical Boxes	Asbestos	Presumed	190	190		MATERIALS WITHIN 10-CORE AND WESTINGHOUSE BOXES - TO CABLE RUN AND BY TRAIN STOP - 10No		10	R714335		
69452	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Signal Boxes	Asbestos	Presumed	195	195		MATERIALS WITHIN SMALL WESTINGHOUSE AND 10-CORE BOXES - BY WALKWAY CROSSING TO CABLE RUN - 6 No		6	R714335		
69453	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Signal Boxes	Asbestos	Presumed	320	330		MATERIAL DESCRIPTION MATERIALS WITHIN RED LIGHT INDICATOR - AT END OF ROAD - 3 No		3	R714335		
69454	ACTIVE	P	P022-P-RD25	Road 25 - PIC - Arnos Grove Sidings	Westinghouse Boxes	Asbestos	Presumed	334	334		MATERIALS WITHIN WESTINGHOUSE BOXES - TO CABLE RUN BEHIND ROAD - 8No		8	-R714335		
36519	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	0	2	LHS	Cloth. cable sheath. Entry: Platform grounds, Route: H2 of 4, 1x15mmØ, H4, 1x30mmØ, Exit: Ten Core box. 2 x 1.5m					
36520	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	1		LHS	Trackside equipment: tencore box		1			



Hazardous Material Asset Register - Summary



P022-P - PIC Line - Arnos Grove to Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36521	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	1		LHS	Trackside equipment: Westinghouse small box		1			
36522	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	1		LHS	Trackside equipment: tencore box		1			
36524	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	2		LHS	Trackside equipment: tencore box		1			
36523	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	2	6	LHS	Cloth. cable sheath, Entry: N/A, Route: H4 of 4, 1x30mm, Exit: N/A. 1 x 4m					
36525	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	6	23	LHS	Cloth. cable sheath, Entry: Ten Core box, Route:H4 of 4, 2x15mmØ, 1x30mmØ, Exit: N/A. 3 x 17.5m					
36526	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	6		LHS	Trackside equipment: tencore box		1			
36527	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	6		LHS	Trackside equipment: tencore box		1			
36528	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	7		LHS	Trackside equipment: tencore box		1			
39517	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	8		RHS	Trackside equipment: tencore box		4			
36529	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	8		LHS	Trackside equipment: Westinghouse small box		1			
36530	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	16		LHS	Trackside equipment: Westinghouse small box		1			
36531	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	16		LHS	Trackside equipment: Westinghouse small box		1			
36533	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	19		LHS	Trackside equipment: tencore box		1			
36532	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	19		LHS	Trackside equipment: Westinghouse small box		1			
46103	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green		Asbestos	Presumed				Points 22C				N	N
36534	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	20		LHS	Trackside equipment: tencore box		1			
36536	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	21		LHS	Trackside equipment: tencore box		1			
36535	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	21		LHS	Trackside equipment: Westinghouse small box		1			
36537	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	22		LHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P022-P - PIC Line - Arnos Grove to Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36538	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	23	40	LHS	Cloth. cable sheath, Entry: Ten Core box, Route: H2 of 4, 1x15mmØ, H3, 1x15mmØ, H4, 2x15mmØ, 1x30mmØ, Exit: Westinghouse large box. 5 x 17m					
36539	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	23		LHS	Trackside equipment: tencore box		1			
36540	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	24		RHS	Trackside equipment: tencore box		1			
39624	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	36		LHS	Trackside equipment: Westinghouse small box		1			
36541	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	40		LHS	Trackside equipment: Westinghouse large box		1			
40296	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	40	41	LHS	Cloth. Cable sheath, Entry; Westinghouse large box, Route:H2 of 4, 1x15mmØ, H3, 1x15mmØ, above Westinghouse large box, 1x30mmØ, below Westinghouse large box, 1x15mmØ, Exit: Westinghouse large box. 4 x 1m					
36543	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	41	53	LHS	cloth. Cable sheath, Entry: Westinghouse large box, Route: H2 of 4, 2x15mmØ, H3, 1x15mmØ, H4, 1x30mmØ, Exit: N/A. 4 x 11.5m					
36542	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	41		LHS	Trackside equipment: Westinghouse large box		1			
36544	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	41		LHS	Trackside equipment: Westinghouse large box		2			
36545	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	45		LHS	trackside equipment: kiosk		1			
36546	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	51		LHS	Trackside equipment: Westinghouse large box		1			
36547	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	53	58	LHS	cloth. Cable sheath, Entry: Westinghouse large box, Route: H2 of 4, 2x15mmØ, H3, 1x15mmØ, H4, 1x30mmØ, Exit: N/A. 4 x 55m					
40297	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	53		LHS	Trackside equipment: Westinghouse large box		1			
36548	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	53		LHS	Trackside equipment: Westinghouse large box		2			
36549	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	54		LHS	trackside equipment: Howells box		1			
36550	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cement Cable Troughing & Debris	Asbestos	Strongly Presumed	54	57	LHS	Cement, debris, in front of cable hangers. 0.25m ²					
36552	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	58		LHS	Trackside equipment: Westinghouse large box		1			



Hazardous Material Asset Register - Summary



P022-P - PIC Line - Arnos Grove to Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36551	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	58	73	LHS	cloth. Cable sheath, Entry: Westinghouse large box, Route: H2 of 4, 2x15mmØ, H3, 1x8mmØ, 1x15mmØ, H4, 1x30mmØ, Exit: Ten Core box. 5 x 14.5m					
36553	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	60		LHS	Trackside equipment: COLR box		1			
36555	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	73		LHS	Trackside equipment: tencore box		1			
36554	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	73	90	LHS	cloth. Cable sheath, Entry: Ten Core box & Westinghouse large box, Route: H2 of 4, 2x8mmØ, 2x15mmØ, H3, 1x8mmØ, 1x15mmØ, H4, 1x30mmØ, Exit: Kiosk. 7 x 17.5m					
39375	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	73		LHS	Trackside equipment: Westinghouse small box		1			
36556	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	78		LHS	Trackside equipment: tencore box		1			
39625	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	79		LHS	Trackside equipment: tencore box		1			
36558	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	79		LHS	Trackside equipment: tencore box		1			
36557	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	79		LHS	Trackside equipment: Westinghouse small box		1			
36559	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	80		LHS	Trackside equipment: tencore box		1			
36560	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	80		LHS	Trackside equipment: Westinghouse small box		1			
36561	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	80		LHS	Trackside equipment: tencore box		1			
36563	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	81		RHS	Trackside equipment: tencore box		1			
36562	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	81		RHS	Trackside equipment: Westinghouse small box		1			
36564	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cement Cable Troughing & Debris	Asbestos	Presumed	82		RHS	cement, debris, buried by ballast. 0.25m²					
36566	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	86		LHS	Trackside equipment: Westinghouse large box		1			
36565	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	86		LHS	Trackside equipment: Westinghouse small box		1			
36567	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	87		LHS	Trackside equipment: Electrical box		1			



Hazardous Material Asset Register - Summary



P022-P - PIC Line - Arnos Grove to Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40298	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	90		LHS	trackside equipment: kiosk		1			
39518	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	90		RHS	Trackside equipment: Westinghouse small box		1			
36568	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Presumed	90	118	LHS	cloth. Cable sheath, Entry: N/A, Route: H4 of 4, 1x30mm, Exit: N/A. 1 x 27.5m					
36569	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	92		LHS	Trackside equipment: Westinghouse large box		1			
36570	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	92		LHS	trackside equipment: COLR box		1			
36571	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	95		LHS	Trackside equipment: Westinghouse small box		1			
40299	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	113		LHS	trackside equipment: telephone kiosk		1			
36572	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	118	119	LHS	cloth. Cable sheath, Entry: OTX to Sidings, Route: H4 of 4, 3x30mmØ, Exit: N/A. 3 x 1m					
36574	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	119		LHS	trackside equipment: electrical box		1			
36575	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	119	190	LHS	Cloth. Cable sheath, Entry: N/A, Route: H4 of 4, 3x33mmØ, Exit: Westinghouse large box. 3 x 69m					
36573	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	119	119	LHS	cloth. Cable sheath, Entry: Electrical box, Route: H4 of 4, 1x8mmØ, 3x30mmØ, Exit: OTX to Sidings. 4 x 0.5m					
39626	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	125	126	LHS	Cloth. Cable sheath, H4, 1x30mmØ, spliced and mounted below H4. 1 x 1m					
36576	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	128	129	LHS	Cloth. Cable sheath, H4, 1x30mmØ, spliced and mounted below H4. 1 x 1m					
36578	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	129		LHS	Trackside equipment: Westinghouse small box		1			
36577	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	129		LHS	Trackside equipment: Westinghouse small box		1			
36579	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	132	133	LHS	Cloth. Cable sheath, H4, 1x30mmØ, spliced and mounted below H4. 1 x 1m					
36582	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	190		LHS	Trackside equipment: Westinghouse large box		2			
36580	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	190		LHS	Trackside equipment: Westinghouse large box		1			
36581	ACTIVE	p	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	190	224	LHS	Cloth. Cable sheath, Entry: Westinghouse large box, H4 of 4, 1x30mmØ, Exit: N/A. 1 x 34m					



Hazardous Material Asset Register - Summary



P022-P - PIC Line - Arnos Grove to Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36584	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	191		LHS	Trackside equipment: Westinghouse large box		1			
36583	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	191		LHS	Trackside equipment: Westinghouse large box		1			
36587	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cement Cable Troughing & Debris	Asbestos	Strongly Presumed	196		LHS	cement. Cable trough, by point heater box. 0.25m²					
36585	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	196		LHS	Trackside equipment: Westinghouse small box		2			
36586	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	196		LHS	Trackside equipment: Point Heater box		1			
36589	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	199		LHS	Trackside equipment: tencore box		1			
36588	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	199		LHS	Trackside equipment: Westinghouse small box		2			
36590	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	200		LHS	Trackside equipment: tencore box		1			
39543	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	202		LHS	Trackside equipment: Fog Repeater A896		1			
46104	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green		Asbestos	Presumed				Points 19B				N	N
40300	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	205		LHS	Trackside equipment: Westinghouse small box		1			
36591	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	205		LHS	Trackside equipment: Westinghouse small box		1			
36592	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	209		LHS	Trackside equipment: Westinghouse large box		2			
36593	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	224	287	LHS	cloth. Cable sheath, Entry: N/A, Route: H12 of 12, 1x30mmØ, Exit: N/A. 1 x 63m					
36594	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	270		LHS	Trackside equipment: Westinghouse small box		1			
36595	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	287	341	LHS	Cloth. Cable sheath, Entry: N/A, Route: H8 of 8, 1x30mmØ, Exit: N/A. 1 x 53.5m					
40301	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	322		LHS	trackside equipment: electrical box		1			
36597	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	341		LHS	trackside equipment: Signal A896		1			
36596	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	341	465	LHS	Cloth. Cable sheath, Entry: N/A, Route: H12 of 12, 1x30mmØ, Exit: Westinghouse large box. 1 x 124.5m					



Hazardous Material Asset Register - Summary



P022-P - PIC Line - Arnos Grove to Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36598	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	342		LHS	Trackside equipment: tencore box		1			
36599	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	343		LHS	Trackside equipment: Westinghouse small box		1			
39627	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	347		LHS	Trackside equipment: Westinghouse small box		1			
36600	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	348		LHS	Trackside equipment: Westinghouse small box		1			
46477	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Ballast	Asbestos	Sampled – Not Detected	420	1148		Hazardous Landfill			R667927		
36601	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	426		LHS	trackside equipment: type 79		1			
36603	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	464		LHS	Trackside equipment: Westinghouse large box		1			
36602	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	464		LHS	Trackside equipment: Westinghouse large box		1			
36605	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	465	532	LHS	cloth. Cable sheath, Entry: Westinghouse large box & Ten Core box, Route: H10 of 12, 1x15mmØ, H12, 1x30mmØ, Exit: N/ A. 2 x 66.5m					
36607	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	465		LHS	Trackside equipment: Westinghouse large box		2			
36606	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	465		LHS	Trackside equipment: tencore box		1			
36604	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	465		LHS	Trackside equipment: Westinghouse large box		1			
39628	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	466		LHS	Trackside equipment: Westinghouse large box		1			
36609	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	466		LHS	Trackside equipment: Westinghouse large box		1			
36608	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	466		LHS	Trackside equipment: tencore box		1			
36611	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	470		LHS	Trackside equipment: Westinghouse small box		1			
36610	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	470		LHS	Trackside equipment: tencore box		1			
39376	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	472		LHS	trackside equipment: Signal A8961 R894		1			
36612	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	491		LHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P022-P - PIC Line - Arnos Grove to Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36613	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	492		LHS	Trackside equipment: Westinghouse small box		3			
44566	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cement Cable Troughing & Debris	Asbestos	Presumed	500	550		Suspect troughing - FRC5261388 Location is Arnos Grove to Bounds Green on Piccadilly Line, southbound road, at tunnel portal entrance. Location is marked up with a sprayed cross on ballast - please see attached photos					
36614	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	532	548	LHS	Cloth. Cable sheath, Entry: N/A, Route: H2 of 18, 1x15mmØ, H4, 1x30mmØ, Exit: OTX to RHS. 2 x 16m					
36615	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	548	553	RHS	Cloth. Cable sheath, Entry: OTX to LHS, Route: H2 of 4, 1x15mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 2 x 2.5m					
36616	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	553	657	RHS	Cloth. Cable sheath, Entry: N/A, Route: H4 of 4, 1x30mmØ, Exit: Westinghouse large box. 1 x 104m					
36617	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	553		RHS	Trackside equipment: Westinghouse small box		1			
40302	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	554			Trackside equipment: Westinghouse small box		1			
36618	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	555		RHS	Trackside equipment: Westinghouse small box		1			
36619	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	576	577	RHS	Cloth. Cable sheath, H4, 1x30mmØ, spliced and mounted below H4. 1 x 1m					
39544	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	643		RHS	trackside equipment: Signal R890AB		1			
36620	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	644		RHS	trackside equipment: Signal A894		1			
36621	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	645		RHS	Trackside equipment: Westinghouse small box		1			
40303	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	645		RHS	Trackside equipment: tencore box		1			
36622	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	654		RHS	Trackside equipment: Westinghouse large box		1			
36623	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	655		RHS	Trackside equipment: Westinghouse large box		1			
36624	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	656		RHS	Trackside equipment: Westinghouse large box		1			
36414	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	657	811	RHS	Cloth. Cable sheath, Entry: Westinghouse large box, Route: H4 of 4, 1x30mmØ, Exit: N/A. 1 x 153.5m					



Hazardous Material Asset Register - Summary



P022-P - PIC Line - Arnos Grove to Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36415	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	657		RHS	Trackside equipment: Westinghouse large box		2			
36416	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	682		RHS	Trackside equipment: Westinghouse small box		1			
36417	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	684		RHS	Trackside equipment: Westinghouse small box		1			
36419	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	807		RHS	trackside equipment: Signal A890A		1			
36418	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	807		RHS	trackside equipment: Signal R890BC		1			
36421	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	808		RHS	Trackside equipment: tencore box		1			
36420	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	808		RHS	Trackside equipment: Westinghouse small box		1			
39619	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	809		RHS	Trackside equipment: Westinghouse large box		1			
36422	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	810		RHS	Trackside equipment: Westinghouse large box		1			
36423	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	811	815	RHS	Cloth. Cable sheath, Entry: Ten Core box, Route: H3 of 4, 1x20mmØ, H4, 1x30mmØ, Exit: N/A. 2 x 4.5m					
36424	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	811		RHS	Trackside equipment: tencore box		1			
36425	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	815	891	RHS	Cloth. Cable sheath, Entry: Westinghouse small box, Route: H2 of 4, 1x15mmØ, H3, 1x20mmØ, H4, 1x30mmØ, Exit: N/A. 3 x 75.5m					
36426	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	815		RHS	Trackside equipment: Westinghouse small box		1			
39372	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	816		RHS	Trackside equipment: Westinghouse small box		1			
36427	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	817		RHS	Trackside equipment: Westinghouse small box		1			
36428	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	845		RHS	trackside equipment: type 79 box		1			
36429	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	884		RHS	trackside equipment: Signal A890B		1			
36430	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	885		RHS	Trackside equipment: Westinghouse small box		1			
36431	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	886		RHS	Trackside equipment: tencore box		1			



Hazardous Material Asset Register - Summary



P022-P - PIC Line - Arnos Grove to Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40216	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	890		RHS	Trackside equipment: Westinghouse large box		1			
36432	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	891	895	RHS	Cloth. Cable sheath, Entry: Ten Core box, Route: H2 of 4, 1x15mmØ, H3, 2x20mmØ, H4, 1x30mmØ, Exit: N/A. 4 x 4m					
36433	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	891		RHS	Trackside equipment: tencore box		1			
36434	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	893		RHS	Trackside equipment: Westinghouse small box		1			
36435	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Presumed	895	955	RHS	Cloth. Cable sheath, Entry: Westinghouse small box, Route: H2 of 4, 2x15mmØ, H3, 2x20mmØ, H4, 1x30mmØ, Exit: N/A. 5 x 60m					
39514	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	895		RHS	Trackside equipment: Westinghouse small box		1			
40217	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	898		RHS	Trackside equipment: Westinghouse small box		1			
36436	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	953		RHS	trackside equipment: Signal A890B		1			
36437	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	954		RHS	Trackside equipment: Westinghouse small box		1			
36438	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	955		RHS	Trackside equipment: tencore box		1			
36651	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Presumed	955	970	RHS	Cloth. Cable sheath, Entry: Ten Core box, Route: H2 of 4, 2x15mmØ, H3, 3x20mmØ, H4, 1x30mmØ, Exit: N/A. 6 x 14.5m					
36652	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	955		RHS	Trackside equipment: tencore box		1			
36653	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	956		RHS	Trackside equipment: Westinghouse large box		1			
36654	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	969		RHS	Trackside equipment: Westinghouse small box		1			
36655	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	970		RHS	Trackside equipment: Westinghouse small box		1			
39652	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Presumed	970	1149	RHS	Cloth. Cable sheath, Entry: Westinghouse small box, Route:H2 of 4, 3x15mmØ, H3, 3x20mmØ, H4, 1x30mmØ, Exit: N/A. 7 x 179m					
36656	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	975		RHS	Trackside equipment: Westinghouse small box		1			
36657	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Cable Sheath	Asbestos	Presumed	1051	1052	RHS	Cloth. Cable sheath, H4, 1x30mmØ, spliced and mounted below H4. 1 x 1m					



Hazardous Material Asset Register - Summary



P022-P - PIC Line - Arnos Grove to Bounds Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36658	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Signal Boxes	Asbestos	Presumed	1059		RHS	trackside equipment: 415V box					
36659	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	1136		RHS	Trackside equipment: Westinghouse small box		1			
36660	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	1140		RHS	Trackside equipment: Westinghouse small box		1			
36661	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Ducts	Asbestos	Presumed	1147	1148	LHS	Cement. Cable duct lining. Presumed present (In floor and sealed)		2			
36662	ACTIVE	P	P022-P-WBLO	Road WBLO - PIC - Arnos Grove to Bounds Green	Ducts	Asbestos	Presumed	1149		LHS	Cement. Cable duct lining. Presumed present (In platform wall and sealed)		5			

P023-P - PIC Line - Bounds Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42781	ACTIVE	P	P023-P-EBLO	Road EBLO (Plt1) - PIC - Bounds Green Stn	Pit Blocks	Asbestos	Removed				Pit blocks - Non asbestos (Removed by Forest 2002)					
37241	ACTIVE	P	P023-P-EBLO	Road EBLO (Plt1) - PIC - Bounds Green Stn	Signal Boxes	Asbestos	Presumed	48		RHS	Trackside equipment: 630V DC HMU Re-Inspection ok- 10-03-2015		1			
37242	ACTIVE	P	P023-P-EBLO	Road EBLO (Plt1) - PIC - Bounds Green Stn	Westinghouse Boxes	Asbestos	Presumed	94		RHS	Trackside equipment: Westinghouse small box HMU Re-Inspection ok 10-03-2015		1			
37243	ACTIVE	P	P023-P-EBLO	Road EBLO (Plt1) - PIC - Bounds Green Stn	Westinghouse Boxes	Asbestos	Presumed	99		RHS	Trackside equipment: Westinghouse small box HMU Re-Inspection ok - 10-03-2015		1			
37244	ACTIVE	P	P023-P-EBLO	Road EBLO (Plt1) - PIC - Bounds Green Stn	Signal Boxes	Asbestos	Presumed	112		RHS	Trackside equipment: Redifon loop aerial HMU Re-Inspection Not Found - 10-03-2015		1			
37245	ACTIVE	P	P023-P-EBLO	Road EBLO (Plt1) - PIC - Bounds Green Stn	Signal Boxes	Asbestos	Presumed	114		RHS	Trackside equipment: Type 79 HMU Re-Inspection ok - 10-03-2015		1			
37246	ACTIVE	P	P023-P-WBLO	Road WBLO (Plt2) - PIC - Bounds Green Stn	Ducts	Asbestos	Presumed	0		LHS	Cement. cable duct lining, Presumed present in platform wall where ducts are sealed HMU Re-Inspection ok - 10-03-2015		5			
42783	ACTIVE	P	P023-P-WBLO	Road WBLO (Plt2) - PIC - Bounds Green Stn	Pit Blocks	Asbestos	Removed				Pit blocks - Non asbestos (Removed by Forest 2005 ES1113)					
37247	ACTIVE	P	P023-P-WBLO	Road WBLO (Plt2) - PIC - Bounds Green Stn	Westinghouse Boxes	Asbestos	Presumed	40		RHS	Trackside equipment: Westinghouse small box HMU Re-Inspection ok - 10-03-2015		1			
37248	ACTIVE	P	P023-P-WBLO	Road WBLO (Plt2) - PIC - Bounds Green Stn	Westinghouse Boxes	Asbestos	Presumed	44		RHS	Trackside equipment: Westinghouse small box HMU Re-Inspection ok - 10-03-2015		1			
37249	ACTIVE	P	P023-P-WBLO	Road WBLO (Plt2) - PIC - Bounds Green Stn	Signal Boxes	Asbestos	Presumed	68		RHS	Trackside equipment: 630V DC HMU Re-Inspection ok - 10-03-2015		1			



Hazardous Material Asset Register - Summary



P023-P - PIC Line - Bounds Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37250	ACTIVE	p	P023-P-WBLO	Road WBLO (Plt2) - PIC - Bounds Green Stn	Westinghouse Boxes	Asbestos	Presumed	77		RHS	Trackside equipment: Westinghouse small box HMU Re-Inspection ok - 10-03-2015		1			
46152	ACTIVE	p	P023-P-WBLO	Road WBLO (Plt2) - PIC - Bounds Green Stn	Westinghouse Boxes	Asbestos	Presumed	81		RHS	Trackside equipment:		1			
46153	ACTIVE	p	P023-P-WBLO	Road WBLO (Plt2) - PIC - Bounds Green Stn	Signal Boxes	Asbestos	Presumed	112		RHS	Trackside equipment: Redifon loop aerial		1			

P024-P - PIC Line - Bounds Green to Wood Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40764	ACTIVE	p	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Ducts	Asbestos	Presumed	1		RHS	Cement. cable duct lining, Presumed present (In platform wall & sealed)		3			
40765	ACTIVE	p	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Ducts	Asbestos	Presumed	1		RHS	Cement. cable duct lining, Presumed present (In platform wall & sealed)		3			
40763	ACTIVE	p	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	1	4	RHS	Cloth. cable sheath, Entry: Platform wall, Route: H2 of 4, ~8x8mmØ, H3, 7x8mmØ, 1x15mmØ, 2x20mmØ, H4, 2x30mmØ, Exit: Rail Gap Ind. Box. 20 x 2.5m					
39477	ACTIVE	p	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Ducts	Asbestos	Presumed	2	3	LHS	Cement. cable duct lining, Presumed present (In floor & sealed)		3			
40766	ACTIVE	p	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	3		RHS	Trackside equipment: tencore box		1			
40767	ACTIVE	p	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	4	6	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, ~7x8mmØ, H3, 7x8mmØ, 1x15mmØ, 2x20mmØ, H4, 2x30mmØ, Exit: Signals trackside equipment. 19 x 2m					
40768	ACTIVE	p	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	4		RHS	Trackside equipment: westinghouse small box		1			
40769	ACTIVE	p	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	4		RHS	Trackside equipment: Rail Gap Ind. Box		1			
39478	ACTIVE	p	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	6		RHS	Trackside equipment: Signal (PG2)		1			
40771	ACTIVE	p	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	6		RHS	Trackside equipment: tencore box		1			
40770	ACTIVE	p	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	6	12	RHS	Cloth. cable sheath, Entry: N/A, Route: Between trackside equipment, H2, H3, H4, 8mmØ to 30mmØ, Exit: N/A. numerous amounts					
40853	ACTIVE	p	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	7		RHS	Trackside equipment: Signal (PG3)		1			



Hazardous Material Asset Register - Summary



P024-P - PIC Line - Bounds Green to Wood Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40854	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	8		RHS	Trackside equipment: westinghouse small box		1			
39991	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	8		RHS	Trackside equipment: westinghouse small box		1			
40855	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	9		RHS	Trackside equipment: westinghouse small box		1			
40857	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	10		RHS	Trackside equipment: westinghouse small box		1			
40858	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	10		RHS	Trackside equipment: westinghouse large box		1			
40856	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	10		RHS	Trackside equipment: tencore box		1			
40859	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	11		RHS	Trackside equipment: tencore box		1			
40861	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	12		RHS	Trackside equipment: tencore box		1			
40860	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	12	23	RHS	Cloth. cable sheath, Entry: Signals trackside equipment, Route: H2 of 4, 8x8mmØ, H3, 5x8mmØ, 2x20mmØ, H4, 2x30mmØ, Exit: N/ A. 17 x 11m					
42095	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Removed	21			2 x Washers within Box B5326N Westinghouse, EB cess 21m Notes from 2022 re-inspection: Removed		2			
42093	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Sampled – Not Detected	21			Dust within Box B5326N Westinghouse, EB cess 21m.					
42091	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable: Sheath	Asbestos	Removed				3 x 0.5m Braided Cables within box, COLR, EB cess 21m. Notes from 2022 re-inspection: Removed	5	3		N	N
42090	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Other Electrical Boxes	Asbestos	Sampled – Not Detected				Dust within box, COLR EB Cess 21m				N	N
42092	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Other Electrical Boxes	Asbestos	Removed				8 x Bakelite Plates within box, COLR, EB Cess 21m. Notes from 2022 re-inspection: Removed		8		N	N
42096	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Removed	21			1 x Bakelite plates within in box B5326N Westinghouse, EB cess 21m. Notes from 2022 re-inspection: Removed		1			



Hazardous Material Asset Register - Summary



P024-P - PIC Line - Bounds Green to Wood Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42094	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Removed	21			2 x 5mm & 2 x 10mm Braided Cables within box B5326N Westinghouse, EB Cess 21m Notes from 2022 re-inspection: Removed		4			
40863	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	23		RHS	Trackside equipment: westinghouse small box		1			
40862	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	23	27	RHS	Cloth. cable sheath,Entry: Westinghouse small box, Route: H2 of 4, 10x8mmØ, H3, 5x8mmØ, 2x20mmØ, H4, 2x30mmØ, Exit: Points/trackside equipment. 19 x 4m					
40864	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Removed	23		RHS	Trackside equipment: COLR box Notes from 2022 re-inspection: Removed		1			
39791	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	27		RHS	Trackside equipment: westinghouse small box		1			
40866	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	27		RHS	Trackside equipment: tencore box		1			
40865	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	27	31	RHS	Cloth. cable sheath, Entry: N/A, Route: Between trackside equipment, H2, H3, H4, 8mmØ to 30mmØ, Exit: Wood Green Sidings EB Spur. Numerous amounts					
40868	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	28		RHS	Trackside equipment: tencore box		1			
40867	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	28		RHS	Trackside equipment: tencore box		1			
40869	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	29		RHS	Trackside equipment: tencore box		1			
40871	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	30			Trackside equipment: Westinghouse's Cross Passage 30m off Platform: to Wall 1 - Chrysotile					
40872	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	30			Trackside equipment: Green Braided Cable. Cross Passage 30m off Platform: to Wall 1 - Chrysotile					
40870	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	30		RHS	Trackside equipment: westinghouse small box		1			
42100	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Sampled – Not Detected	50			Dust within Box B5326 Westinghouse, EB cess 50m					
42101	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Removed	50			2 x 5mm & 2 x 10mm Braided cables within Box B5326 Westinghouse, EB Cess 50m. Notes from 2022 re-inspection: Removed		4			



Hazardous Material Asset Register - Summary



P024-P - PIC Line - Bounds Green to Wood Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42099	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Other Electrical Boxes	Asbestos	Removed				8 x Bakelite plates within Box, COLR, EB Cess 50m. Notes from 2022 re-inspection: Removed		8		N	N
42103	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Removed	50			1 x Bakelite plates within Box B5326 Westinghouse, EB Cess 50m. Notes from 2022 re-inspection: Removed		1			
42102	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westing house Boxes	Asbestos	Removed				2 x Washers within Box B5326 Westinghouse, EB Cess 50m. Notes from 2022 re-inspection: Removed		2		N	N
42098	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Other Electrical Boxes	Asbestos	Removed				1 x 0.5m Braided Cables within Box, COLR, EB Cess 50m. Notes from 2022 re-inspection: Removed		1		N	N
42097	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Other Electrical Boxes	Asbestos	Sampled – Not Detected				Dust within Box, COLR, EB Cess 50m.				N	N
40873	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	60	66	RHS	Cloth. cable sheath, Entry: Wood Green Sidings P-Way EB Spur, Route: H2 of 4, 10x8mmØ, H3, 1x8mmØ, 1x20mmØ, Exit: Westinghouse small box. 12 x 6m					
39487	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	60		LHS	Trackside equipment: Tunnel lighting box		2			
39992	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	66		RHS	Trackside equipment: westinghouse small box		1			
40874	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	66	70	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, ~9x8mmØ, H3, 1x8mmØ, 1x20mmØ, Exit: N/A. 11 x 3.5m					
40875	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	70	72	RHS	Cloth. cable sheath, Entry: Spliced, Route: H2 of 4, ~9x8mmØ, H3, 1x8mmØ, 1x20mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 12 x 2.5m					
40958	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	72		RHS	Trackside equipment: westinghouse small box		1			
40876	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	72	154	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, ~8x8mmØ, H3, 1x8mmØ, 1x20mmØ, H4, 1x30mmØ, Exit: Electrical box. 11 x 3m					
40959	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	154	240	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, 7x8mmØ, H3, 1x20mmØ, H4, 1x30mmØ, Exit: N/A. 9 x 85.5m					
40960	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	154		RHS	Trackside equipment: electrical box		1			



Hazardous Material Asset Register - Summary



P024-P - PIC Line - Bounds Green to Wood Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40961	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	240	241	RHS	Cloth. cable sheath, Entry: Signal (RX883), Route: H2 of 4, 9x8mmØ, H3, 1x30mmØ, H4, 1x30mmØ, Exit: Westinghouse large box. 11 x 1m					
39795	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	240		RHS	Trackside equipment: Signal (RX883)		1			
39998	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	241	247	RHS	Cloth. cable sheath, Entry: Westinghouse large box, Route: H2 of 4, 8x8mmØ, H3, 1x20mmØ, H4, 1x8mmØ, 1x30mmØ, Exit: Westinghouse small box. 11 x 6m					
40962	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	241		RHS	Trackside equipment: westinghouse large box		1			
40964	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	247		RHS	Trackside equipment: westinghouse small box		1			
40963	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	247	251	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, 7x8mmØ, H3, 1x8mmØ, 1x20mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 10 x 5.5m					
40966	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	251		RHS	Trackside equipment: westinghouse small box		1			
40965	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	251	347	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, 6x8mmØ, H3, 1x8mmØ, 1x20mmØ, H4, 1x30mmØ, Exit: Signals trackside equipment. 9 x 96m					
40970	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	348		RHS	Trackside equipment: westinghouse small box		1			
40969	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	348		RHS	Trackside equipment: Signal (X883)		1			
40968	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	348		RHS	Trackside equipment: westinghouse small box		1			
40967	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	348	351	RHS	Cloth. cable sheath, Entry: N/A, Route: Between trackside equipment, H2, H3, H4, 8mmØ to 30mmØ, Exit: N/A. numerous amounts					
40972	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	350		RHS	Trackside equipment: westinghouse large box		1			
40973	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	350		RHS	Trackside equipment: tencore box		1			
40971	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	350		RHS	Trackside equipment: tencore box		1			
40974	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	351	356	RHS	Cloth. cable sheath, Entry: Signals trackside equipment, Route; H2 of 4, 5x8mmØ, H3, 1x8mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 7 x 5.5m					



Hazardous Material Asset Register - Summary



P024-P - PIC Line - Bounds Green to Wood Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40975	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	351		RHS	Trackside equipment: westinghouse small box		1			
39494	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	356	361	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, 4x8mmØ, H3, 1x8mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 6 x 4.5m					
40976	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	356		RHS	Trackside equipment: westinghouse small box		1			
40977	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	361	500	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, 3x8mmØ, H3, 1x8mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 5 x 139.5m					
40978	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	361		RHS	Trackside equipment: westinghouse small box		1			
40980	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	500		RHS	Trackside equipment: westinghouse small box		1			
40979	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	500	547	RHS	Cloth. cable sheath, Entry: N/A, H2 of 4, 3x8mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 4 x 47m					
40981	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	547	552	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, 2x8mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 3 x 4.5m					
41063	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	547		RHS	Trackside equipment: westinghouse small box		1			
41064	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	552	684	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, 1x8mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 2 x 132m					
41065	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	552		RHS	Trackside equipment: westinghouse small box		1			
41066	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	559	560	RHS	Cloth. cable sheath, H4, 1x30mm, spliced & mounted below H4. 1 x 1m					
41067	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	564		RHS	Trackside equipment: type 79 box		1			
41068	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	683		RHS	Trackside equipment: Signal (RX887)		1			
40026	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	684		RHS	Trackside equipment: westinghouse small box		1			
41069	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	684	851	RHS	Cloth. cable sheath, Entry: N/A, Route: H4 of 4, 1x30mmØ, Exit: Westinghouse large box. 1 x 167.5m					
41070	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	686		RHS	Trackside equipment: westinghouse large box		1			
41071	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	687		RHS	Trackside equipment: westinghouse large box		1			



Hazardous Material Asset Register - Summary



P024-P - PIC Line - Bounds Green to Wood Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41072	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	688		RHS	Trackside equipment: westinghouse small box		1			
41073	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	824		RHS	Trackside equipment: Signal (X887)		1			
41074	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	825		RHS	Trackside equipment: westinghouse small box		1			
41075	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	826		RHS	Trackside equipment: tencore box		1			
41076	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	844	845	RHS	Cloth. cable sheath, H4, 1x30mm, spliced & mounted below H4. 1 x 1m					
41077	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	847		RHS	Trackside equipment: westinghouse small box		1			
41078	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	850		RHS	Trackside equipment: westinghouse large box		1			
41079	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	851		RHS	Trackside equipment: westinghouse large box		2			
39501	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	851	853	RHS	Cloth. cable sheath, Entry: Westinghouse large box, Route: H4 of 4, 1x30mmØ, Exit: N/A. 1 x 2.5m					
39524	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	852		RHS	Trackside equipment: westinghouse small box		1			
41080	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	853		RHS	Trackside equipment: westinghouse large box		1			
41081	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	854	855	RHS	Cloth. cable sheath, Entry: Westinghouse large box, Route: H2 of 4, 1x15mmØ, H4, 1x30mmØ, Exit: N/A. 2 x 1m					
41082	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	854		RHS	Trackside equipment: westinghouse large box		1			
41084	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	855		RHS	Trackside equipment: westinghouse small box		2			
41083	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	855	961	RHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: H2 of 4, 3x15mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 4 x 106.5m					
39525	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	958		RHS	Trackside equipment: westinghouse small box		1			
41086	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	961		RHS	Trackside equipment: westinghouse small box		1			
41085	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	961	962	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, 2x15mmØ, H4, 1x30mmØ, Exit: N/A. 3 x 0.5m					



Hazardous Material Asset Register - Summary



P024-P - PIC Line - Bounds Green to Wood Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41087	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	962	1119	RHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: H2 of 4, 3x15mmØ, H4, 1x30mmØ, Exit: Ten Core box. 4 x 157.5m					
41168	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	962		RHS	Trackside equipment: westinghouse small box		1			
41169	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	963		RHS	Trackside equipment: westinghouse small box		1			
41170	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	995		RHS	Trackside equipment: type 79 box		1			
41171	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	996	997	RHS	Cloth. cable sheath, H4, 1x30mm, spliced & mounted below H4. 1 x 1m					
41172	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	1119	1150	RHS	Cloth. cable sheath, Entry: Ten Core box, Route: H2 of 4, 3x15mmØ, H4, 1x30mmØ, Exit: N/A. 4 x 30.5m					
41173	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	1119		RHS	Trackside equipment: tencore box		1			
41174	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	1145		RHS	Trackside equipment: Signal (R889A)		1			
41175	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	1148		RHS	Trackside equipment: westinghouse large box		1			
41176	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	1149		RHS	Trackside equipment: westinghouse small box		1			
39801	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	1150		RHS	Trackside equipment: westinghouse small box		1			
41177	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	1150	1129	RHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: H2 of 4, 4x15mmØ, H4, 1x30mmØ, Exit: Ten Core box. 5 x 79.5m					
41178	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	1154		RHS	Trackside equipment: westinghouse small box		1			
41179	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	1212		RHS	Trackside equipment: Signal (R889AB)		1			
41180	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	1215		RHS	Trackside equipment: westinghouse large box		1			
41182	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	1229		RHS	Trackside equipment: tencore box		1			
41181	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	1229	1230	RHS	Cloth. cable sheath, Entry: Ten Core box, Route: H2 of 4, 3x15mmØ, H4, 1x30mmØ, Exit: Ten Core box. 4 x 0.5m					
41184	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	1230		RHS	Trackside equipment: tencore box		1			



Hazardous Material Asset Register - Summary



P024-P - PIC Line - Bounds Green to Wood Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41183	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	1230	1286	RHS	Cloth. cable sheath, Entry: Ten Core box, Route: H2 of 4, 3x15mmØ, H4, 1x30mmØ, Exit: N/A. 4 x 56m					
41185	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	1231		RHS	Trackside equipment: westinghouse small box		1			
41186	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	1232		RHS	Trackside equipment: westinghouse small box		1			
41187	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	1281		RHS	Trackside equipment: westinghouse small box		1			
40032	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	1285		RHS	Trackside equipment: Signal (A889A)		1			
39532	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	1285		RHS	Trackside equipment: westinghouse small box		1			
41188	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	1286	1286	RHS	Cloth. cable sheath, Entry: Ten Core box, Route: H2 of 4, 5x15mmØ, H4, 1x30mmØ, Exit: N/A. 6 x 0.5m					
41191	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	1286		RHS	Trackside equipment: tencore box		1			
41189	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	1286		RHS	Trackside equipment: tencore box		1			
41190	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	1286	1315	RHS	Cloth. cable sheath, Entry: Ten Core box, Route H2 of 4, 5x15mmØ, H3, 1x20mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 7 x 28.5m					
39533	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	1287		RHS	Trackside equipment: westinghouse large box		1			
41192	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	1287		RHS	Trackside equipment: tencore box		1			
41273	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	1313		RHS	Trackside equipment: westinghouse small box		1			
41275	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	1315		RHS	Trackside equipment: westinghouse small box		1			
41274	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	1315	1375	RHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: H2 of 4, 4x15mmØ, H3,1x20mmØ, H4, 1x30mmØ, Exit: N/A. 6 x 60m					
41276	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	1317		RHS	Trackside equipment: westinghouse small box		1			
41277	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	1374		RHS	Trackside equipment: Signal (A889B)		1			
41278	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	1374		RHS	Trackside equipment: westinghouse small box		1			



Hazardous Material Asset Register - Summary



P024-P - PIC Line - Bounds Green to Wood Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41281	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	1375		RHS	Trackside equipment: westinghouse large box		1			
41279	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Cable Sheath	Asbestos	Strongly Presumed	1375	1427	RHS	Cloth. cable sheath, Entry: Ten Core box, Route: H2 of 4, 4x15mmØ, H3, 2x20, H4, 1x30mmØ, Exit: Platform wall. 7 x 52.5m					
41280	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	1375		RHS	Trackside equipment: tencore box		1			
39850	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	1375		RHS	Trackside equipment: tencore box		1			
41282	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	1413		RHS	Trackside equipment: westinghouse small box		1			
41283	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Signal Boxes	Asbestos	Presumed	1417		RHS	Trackside equipment: type 79 box		1			
41284	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	1420		RHS	Trackside equipment: westinghouse small box		1			
41285	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Westinghouse Boxes	Asbestos	Presumed	1425		RHS	Trackside equipment: westinghouse small box		1			
41286	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Ducts	Asbestos	Presumed	1426	1427	LHS	cement cable duct lining. Presumed present (in floor & sealed)		1			
41287	ACTIVE	P	P024-P-EBLO	Road EBLO - PIC - Wood Green to Bounds Green	Ducts	Asbestos	Presumed	1428		LHS	cement cable duct lining. Presumed present (in platform wall & sealed)		6			
46246	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cement Troughing	Asbestos	Known				5B/6B Points EB Approach - Troughing	15			N	N
46247	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cement Troughing	Asbestos	Known				WB Approach - Troughing	10			N	N
46249	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Isolator Switches	Asbestos	Known				Entrance to siding - Current rail section boxing on four switches	20			N	N
44097	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Track Section Switches	Asbestos	Removed				Asbestos Cement panels surround section switch 371 & 371a removed by Edenbeck ES9951 08/06/2017		3			
41688	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	0		LHS	Trackside equipment: lamp		1			
41690	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1		LHS	Trackside equipment: westinghouse small box		1			
41689	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1	10	LHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: Along tunnel rings, 1x8mmØ, Exit: Westinghouse small box. 1 x9.5m					



Hazardous Material Asset Register - Summary



P024-P - PIC Line - Bounds Green to Wood Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46248	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Boarding: Cement	Asbestos	Known				Entrance into signing RHS - Cementitious sheeting & cubical box FORMING Small room in cross passage built out of cementitious sheeting and cubicle box	50			N	N
39612	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	10		LHS	Trackside equipment: westinghouse large box		1			
39509	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	10	17	LHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: H1 of 1, 1x8mmØ, Exit: N/A. 1 x 6.5m					
41691	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	10		LHS	Trackside equipment: westinghouse small box		1			
41692	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	11		RHS	Trackside equipment: C.Zang box		1			
41693	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	13	23	RHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: H2 of 4, 1x8mmØ, Exit: N/A. 1 x 10.5m					
41694	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	13		RHS	Trackside equipment: westinghouse small box		1			
46252	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Known	16		LHS	Westinghouse electrical and signal box		1			
46251	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Known	16		RHS	Woven cable insulation; 2 x 20mm. 1 x 20mm starts 16m into siding RHS. All cables in only JH	20	2			
40072	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	17		RHS	Trackside equipment: lamp		1			
40071	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	17	40	LHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: H1 of 1, 4x8mmØ, Exit: Lamp					
41695	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	17	17	LHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: H1 of 1, 2x8mmØ, Exit: N/A. 2 x 0.5m					
40074	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	23		RHS	Trackside equipment: Electrical Box		1			
40073	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	23	89	RHS	Cloth. cable sheath, Entry: Electrical box, Route: H2 of 4, 3x8mmØ, Exit: N/A. 3 x 66m					
46250	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Known	30		LHS	Woven cable insulation; JH 2, 2 x 20mm, 1 x 40mm. 40mm terminates 30m into siding LHS	40	1			
46253	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Known	35		LHS	Westinghouse electrical and signal box		1			
40076	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	40		LHS	Trackside equipment: lamp		1			
40075	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	40	56	LHS	Cloth. cable sheath, Entry: Lamp, Route: H1 of 1, 4x8mmØ, Exit: Lamp. 4 x 15.5m					
40078	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	56		LHS	Trackside equipment: lamp		1			



Hazardous Material Asset Register - Summary



P024-P - PIC Line - Bounds Green to Wood Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40077	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	56	67	RHS	Cloth. cable sheath, Entry: Lamp, Route: H1 of 1, 4x8mmØ, Exit: CP. 11. 4 x 11.5m					
39942	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Removed	67		LHS	Trackside equipment: lamp Notes from 2022 re-inspection: Removed		1			
40079	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	67	71	LHS	Cloth. cable sheath, Entry: N/A, Route: H1 of 1, 2x8mmØ, Exit: Lamp. 2 x 2.5m					
40081	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	71		LHS	Trackside equipment: lamp		1			
40080	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	71	86	LHS	Cloth. cable sheath, Entry: Lamp, Route: H1 of 1, 2x8mmØ, Exit: Lamp. 2 x 15m					
40083	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	86		LHS	Trackside equipment: lamp		1			
40082	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	86	89	LHS	Cloth. cable sheath, Entry: Lamp, Route: H1 of 1, Exit: N/A. 2 x 3m					
40084	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	88	89	LHS	Cloth. cable sheath, 3x8mmØ passing between trackside equipment. 3 x 0.5m					
40086	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	89		LHS	Trackside equipment: westinghouse small box		1			
40089	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	89	130	RHS	Cloth. cable sheath, Entry: OTX to LHS, Route: H2 of 4, 1x15mmØ, 2x8mmØ Exit: N/A. 4 x 40.5m					
40087	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	89		LHS	Trackside equipment: tencore box		1			
40088	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	89	101	LHS	Cloth. cable sheath, Entry: N/A, Route: H1 of 1, 2x8mmØ, Exit: Lamp. 2 x 11.5m					
40085	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	89	89	LHS	Cloth. cable sheath, Entry: Ten Core box, Route: H1 of 1, 2x8mmØ, 1x15mmØ, Exit: OTX to RHS. 3 x 0.5m					
40090	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	101		LHS	Trackside equipment: lamp		1			
39385	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	101	116	LHS	Cloth. cable sheath, Entry: Lamp, Route: H1 of 1, 2x8mmØ, Exit: Lamp. 2 x 15m					
40091	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	116	132	LHS	Cloth. cable sheath, Entry: N/A, Route: H1 of 1, 1x8mmØ, Exit: Lamp. 1. 1 x 16m					
40092	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	116		LHS	Trackside equipment: lamp		1			
39465	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	130		RHS	Trackside equipment: westinghouse small box		1			



Hazardous Material Asset Register - Summary



P024-P - PIC Line - Bounds Green to Wood Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40093	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	130	132	RHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: H2 of 4, 4x8mmØ, 1x15mmØ, Exit: N/A. 5 x 2.5m					
40173	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	132	133	RHS	Cloth. cable sheath, Entry: Tunnel Telephone, Route: H2 of 4, 1x15mmØ, 5x8mmØ, Exit: Signals trackside equipment. 6 x 0.5m					
40171	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	132	133	LHS	Cloth. cable sheath, Entry: Lamp, Route: H1 of 1, 1x8mmØ, Exit: N/A. 1 x 1.5m					
40172	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	132		LHS	Trackside equipment: lamp		1			
40178	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	133		RHS	Trackside equipment: Rail Gap Ind. Box		1			
40177	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	133		RHS	Trackside equipment: tencore box		1			
40175	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	133		RHS	Trackside equipment: Signal (PG10)		1			
40174	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	133	135	RHS	Cloth. cable sheath, Entry: N/A, Route: Between trackside equipment, H2 & from OTX to LHS, 8mmØ to 20mmØ, Exit: N/A. numerous amounts					
40176	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	133	134	LHS	Cloth. cable sheath, Entry: Rail Gap Ind. box, Route: H1 of 1, 2x8mmØ, Exit: OTX to RHS. 2 x 1m					
40180	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	134		RHS	Trackside equipment: westinghouse small box		1			
40179	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	134		RHS	Trackside equipment: tencore box		1			
40181	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	134		RHS	Trackside equipment: tencore box		1			
40184	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	135		RHS	Trackside equipment: westinghouse small box		1			
40182	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	135	142	RHS	Cloth. cable sheath, Entry: Signals trackside equipment, Route: H2 of 4, 1x20mmØ, 1x15mmØ, 6x8mmØ, Exit: Points trackside equipment. 8 x 7.5m					
40183	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	135		RHS	Trackside equipment: westinghouse small box		2			
40185	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	142	146	RHS	Cloth. cable sheath, Entry: N/A, Route: Between trackside equipment, H2, H3, 8mmØ to 20mmØ, Exit: N/A. numerous amounts					
40186	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	143		RHS	Trackside equipment: tencore box		2			



Hazardous Material Asset Register - Summary



P024-P - PIC Line - Bounds Green to Wood Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39722	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	143		RHS	Trackside equipment: tencore box		2			
40187	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	144		RHS	Trackside equipment: westinghouse small box		2			
40188	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	145		RHS	Trackside equipment: westinghouse small box		2			
39945	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	146		RHS	Trackside equipment: tencore box		1			
40190	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	146	151	RHS	Cloth. cable sheath, Entry: Points trackside equipment, Route: H1 of 4, 1x20mmØ, 1x15mmØ, 5x8mmØ, H2, 2x8mmØ, 2x20mmØ, Exit: N/A. 7 x 5m					
40189	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	146		RHS	Trackside equipment: tencore box		1			
39393	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Removed	151	156	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, 1x20mmØ, 1x15mmØ, 5x8mmØ, H3, 2x8mmØ, 2x20mmØ, Exit: OTX to LHS. 7 x 5m Notes from 2022 re-inspection: Removed					
40191	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	155		RHS	Trackside equipment: westinghouse small box		1			
40192	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	156	170	RHS	Cloth. cable sheath, Entry: OTX to LHS, Route: H2 of 4, 1x20mmØ, 1x15mmØ, 4x8mmØ, H3, 2x8mmØ, 2x20mmØ, H4, 1x8mmØ, Exit: UTX cement cable trough. 11 x 4m					
39725	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	156		LHS	Trackside equipment: westinghouse small box		1			
40268	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	156		LHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: OTX, 2x8mmØ, Exit: RHS. 2 x 8m					
40269	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cement Cable Troughing & Debris	Asbestos	Strongly Presumed	160		LHS	cement, wall and door. 4m²					
40270	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cement Cable Troughing & Debris	Asbestos	Known	168		UTX	cement, cable trough. 4m					
40283	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cement Cable Troughing & Debris	Asbestos	Known	170		UTX	cement cable trough		4			
40282	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	170	172	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, 4x8mmØ, 1x15mmØ, 1x20mmØ, H3, 2x8mmØ, 2x20mmØ, Exit: UTX to EB Spur LHS & WB Spur RHS. 10 x 1.5m					
40281	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	170	172	RHS	Cloth. cable sheath, Entry: UTX cement cable trough, Route: In rubber hosing, 1x8mmØ, Exit: WB RHS. 1 x 55m					



Hazardous Material Asset Register - Summary



P024-P - PIC Line - Bounds Green to Wood Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40284	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	171		RHS	Trackside equipment: westinghouse box		1			
40271	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	172	196	RHS	Cloth. cable sheath, Entry: OTX, Route: H2 of 4, 4x8mmØ, 1x15mmØ, 1x20mmØ, H3, 1x8mmØ, 1x20mmØ, H4, 1x8mmØ Exit: Westinghouse small box. 9 x 14.5m					
40285	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	172	178	LHS	Cloth. cable sheath, Entry: OTX to RHS, Route: H3 of 4, 1x8mmØ, 1x20mmØ, Exit: N/A. 2 x 6m					
40286	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	178	189	LHS	Cloth. cable sheath, Entry: OTX to Wood Green to Bounds Green EB P-Way, Route: H2 of 4, 11x8mm, H3, 2x8mm, 2x20mm, Exit: N/A. 15 x 11.5m					
40287	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	179		LHS	Trackside equipment: tunnel lighting box		2			
39398	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cement Cable Troughing & Debris	Asbestos	Removed	188		LHS	cement cable trough. Extends from COLR box on LHS to Wood Green to Bounds Green EB P-Way on RHS Notes from 2022 re-inspection: Removed		4			
40288	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	188		LHS	Trackside equipment: COLR box		1			
40363	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	189		LHS	Trackside equipment: westinghouse small box		2			
40362	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	189	204	LHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: H2 of 4, 12x8mm, H3, 2x8mm, 2x20mm, Exit: Cross Passage CP.13. 16 x 14.5m					
40273	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	196		RHS	Trackside equipment: westinghouse box		1			
40272	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	196	197	RHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: H2 of 4, 4x8mmØ, 1x15mmØ, 1x20mmØ, H3, 1x8mmØ, 1x20mmØ, H4, 1x8mmØ, Exit: N/A. 8 x 1m					
40275	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	197		RHS	Trackside equipment: T Junction box		1			
40274	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	197	200	RHS	Cloth. cable sheath, Entry: Splice cable, Route: H2 of 4, 5x8mmØ, 1x20mmØ, 1x15mmØ, H3, 1x8mmØ, 1x20mmØ, H4, 1x8mmØ, Exit: N/A. 10 x 3m					
40276	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	199		RHS	Trackside equipment: main Earth Terminal box		1			



Hazardous Material Asset Register - Summary



P024-P - PIC Line - Bounds Green to Wood Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40277	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	200	202	RHS	Cloth. cable sheath, Entry: Splice below H4, Route: H2 of 4, 5x8mmØ, 1x20mmØ, 1x15mmØ, H3, 1x8mmØ, 1x20mmØ, H4, 1x8mmØ, 2x30mmØ, Exit: OTX to LHS.12 x 1.5m					
40278	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	202	205	RHS	Cloth. cable sheath, Entry: OTX to RHS of P-Way, Route: H1 of 4, 1x30mmØ, H2, ~16x8mmØ, 1x15mmØ, 1x20mmØ, H3, 4x8mmØ, 3x15mmØ, 1x20mmØ, H4, 1x30mmØ, Exit: CP.13. 28 x 4.5m					
40279	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	203		LHS	Trackside equipment: COLR box		1			
40364	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	204	205	LHS	Cloth. cable sheath, Entry: CP.13, Route: H2 of 4, 12x8mm, H3, 2x8mm,2x20mm, H4, 2x30mm, Exit: Points trackside equipment on Wood Green to Bounds Green EB P-Way. 18 x 4m					
40365	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cement Cable Troughing & Debris	Asbestos	Presumed	204		LHS	cement cable duct lining. Presumed present (Above door & sealed)		10			
40280	ACTIVE	P	P024-P-RD01	Road 01 - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	205	206	RHS	Cloth. cable sheath, Entry: CP.13, Route: H2 of 4, ~15x8mmØ, 1x15mmØ, 1x20mmØ, H3, 6x8mmØ, 3x15mmØ, 1x20mmØ, H4, 2x30mmØ, Exit: Bounds Green to Wood Green WB P-Way. 29 x 1m					
37113	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Ducts	Asbestos	Presumed	1		RHS	Cement. cable duct lining, Presumed present (In platform wall and sealed)		1			
37112	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cement Cable Troughing & Debris	Asbestos	Known	1			cement, cable trough. 1.5m					
37110	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1	13	RHS	Cloth. Cable sheath, Entry: Platform wall, Route: H2 of 4, 4x15mmØ, H3, 2x25mmØ, H4, 1x30mmØ, Exit: Ten Core box. 7 x 12m					
37111	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Ducts	Asbestos	Presumed	1		RHS	Cement. cable duct lining, Presumed present (In floor and sealed)		3			
39744	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	5		RHS	Cloth. Cable sheath, H4, 1x30mmØ, spliced & mounted below H4. 1 x1m					
37114	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	5		RHS	Trackside equipment: Westinghouse small box		1			
37115	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	8		RHS	Trackside equipment: Signal (A888)		1			
37116	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	9		RHS	Trackside equipment: Westinghouse small box		1			
37117	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	9		RHS	Trackside equipment: tencore box		1			



Hazardous Material Asset Register - Summary



P024-P - PIC Line - Bounds Green to Wood Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37118	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	12		RHS	Trackside equipment: Westinghouse large box		1			
39563	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	13		RHS	Trackside equipment: tencore box		1			
37121	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	13	14	RHS	Cloth. Cable sheath, Entry: N/A, H2 of 4, 4x15mmØ, H3, 1x25mmØ, H4, 1x30mmØ, Exit: Ten Core box. 6 x 0.5m					
37119	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	13	13	RHS	Cloth. Cable sheath, Entry: Ten Core box, Route: H2 of 4, 4x15mmØ, H3, 2x25mmØ, H4, 1x30mmØ, Exit: Ten Core box. 7 x 0.5m					
37120	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	13		RHS	Trackside equipment: tencore box		1			
37122	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	14	18	RHS	Cloth. Cable sheath, Entry: Ten Core box, Route: H2 of 4, 4x15mmØ, H3, 1x25mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 6 x 4.5m					
37123	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	14		RHS	Trackside equipment: tencore box		1			
37125	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	18	75	RHS	Cloth. Cable sheath, Entry: N/A, Route: H2 of 4, 3x15mmØ, H3, 1x25mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 5 x 56.5m					
37126	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	18		RHS	Trackside equipment: Westinghouse small box		1			
37124	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	18		RHS	Trackside equipment: Westinghouse small box		1			
37127	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	23		RHS	Trackside equipment: Westinghouse small box		1			
37129	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	75		RHS	Trackside equipment: Westinghouse small box		1			
37130	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	75		RHS	Trackside equipment: Westinghouse small box		1			
37128	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	75	495	RHS	Cloth. Cable sheath, Entry: N/A, Route: H2 of 4, 2x15mmØ, H3, 1x25mmØ, H4, 1x30mmØ, Exit: Ten Core box. 4 x 420.5m					
37131	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	77		RHS	Trackside equipment: Westinghouse small box		1			
37132	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	420		RHS	Trackside equipment: type 79 box		1			
37133	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	467		RHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P024-P - PIC Line - Bounds Green to Wood Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39694	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	492		RHS	Trackside equipment: Signal (A886)		1			
37134	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	494		RHS	Trackside equipment: Westinghouse small box		1			
39745	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	494		RHS	Trackside equipment: tencore box		1			
37135	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	495		RHS	Trackside equipment: Westinghouse small box		1			
37137	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	495		RHS	Trackside equipment: tencore box		1			
37136	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	495	509	RHS	Cloth. Cable sheath, Entry: N/A, Route: H2 of 4, 2x15mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 3 x 14m					
37138	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	499	500	RHS	Cloth. Cable sheath, H4, 1x30mmØ, spliced & mounted below H4. 1 x 1m					
39746	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	509	514	RHS	Cloth. Cable sheath, Entry: N/A, Route: H2 of 4, 1x15mmØ, H4, 1x30mmØ, Exit: N/A. 2 x 5m					
37139	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	509		RHS	Trackside equipment: Westinghouse small box		1			
37140	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	510		RHS	Trackside equipment: Westinghouse small box		1			
37141	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	514	515	RHS	Cloth. Cable sheath, Entry: Westinghouse small box, Route: H2 of 4, 2x15mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 3 x 0.5m					
37142	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	514		RHS	Trackside equipment: Westinghouse small box		1			
37143	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	515	647	RHS	Cloth. Cable sheath, Entry: N/A, Route: H2 of 4, 1x15mmØ, H4, 1x30mmØ, Exit: N/A. 2 x 132.5m					
37144	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	515		RHS	Trackside equipment: Westinghouse small box		1			
39586	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	531	532	RHS	Cloth. Cable sheath, H4, 1x30mmØ, spliced & mounted below H4. 1 x 1m					
37145	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	624		RHS	Trackside equipment: Westinghouse small box		1			
37146	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	647	653	RHS	Cloth. Cable sheath, Entry: Westinghouse small box, Route: H2 of 4, 1x8mmØ, 1x15mmØ, H4, 1x30mmØ, Exit: N/A. 3 x 5.5m					
37147	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	647		RHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P024-P - PIC Line - Bounds Green to Wood Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37148	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	653	744	RHS	Cloth. Cable sheath, Entry: Westinghouse small box, Route: H2 of 4, 2x8mmØ, 1x15mmØ, H4, 1x30mmØ, Exit: N/A. 4 x 91m					
37149	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	653		RHS	Trackside equipment: Westinghouse small box		1			
37150	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	730	731	RHS	Trackside equipment: Main Earth Terminal box		1			
37151	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	742		RHS	Trackside equipment: Westinghouse small box		1			
37153	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	744		RHS	Trackside equipment: Westinghouse small box		1			
37152	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	744	827	RHS	Cloth. Cable sheath, Entry: N/A, Route: H2 of 4, 2x8mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 3 x 83.5m					
37154	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	827	865	RHS	Cloth. Cable sheath, Entry: Westinghouse small box, Route: H2 of 4, 2x8mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 3 x 38.5m					
37155	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	827		RHS	Trackside equipment: Westinghouse small box		1			
39695	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	842		RHS	Trackside equipment: type 79 box		1			
37157	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	865		RHS	Trackside equipment: Westinghouse small box		1			
37156	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	865	1077	RHS	Cloth. Cable sheath, Entry: Westinghouse small box, Route: H2 of 4, 2x8mmØ, H4, 1x30mmØ, Exit: Signals trackside equipment. 3 x 212m					
39747	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	896		RHS	Trackside equipment: Westinghouse small box		1			
37158	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1028	1029	RHS	Cloth. Cable sheath, H4, 1x30mmØ, spliced & mounted below H4.. 1 x 1m					
37160	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1077	1084	RHS	Cloth. Cable sheath, Entry: N/A, Route: Between trackside equipment, H2, H3 & H4, 8mmØ to 30mmØ, Exit: N/A. numerous amounts					
37161	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1077		RHS	Trackside equipment: Signal (PG12B)		1			
37159	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1077		RHS	Trackside equipment: Signal (PG12A)		1			
39748	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1078		RHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P024-P - PIC Line - Bounds Green to Wood Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37162	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1078		RHS	Trackside equipment: tencore box		1			
37163	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1079		RHS	Trackside equipment: Westinghouse large box		1			
37164	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1080		RHS	Trackside equipment: Westinghouse large box		1			
37165	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1081		RHS	Trackside equipment: tencore box		1			
37166	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1082		RHS	Trackside equipment: Westinghouse large box		1			
37167	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1082		RHS	Trackside equipment: Westinghouse small box		1			
37168	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1083		RHS	Trackside equipment: Westinghouse large box		1			
37169	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1084		RHS	Trackside equipment: Westinghouse small box		1			
39587	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1084	1090	RHS	Cloth. Cable sheath, Entry: Signals trackside equipment, Route: H2 of 4, 5x8mmØ, H3, 5x8mmØ, 3x15mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 14 x 6m					
37170	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1090	1121	RHS	Cloth. Cable sheath, Entry: N/A, Route: H2 of 4, 5x8mmØ, H3, 4x8mmØ, 2x15mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 13 x 31 m					
37171	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1090		RHS	Trackside equipment: Westinghouse small box		1			
37172	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1096		LHS	Trackside equipment: Tunnel lighting box		2			
37174	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1121		RHS	Trackside equipment: Westinghouse small box		1			
37173	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1121	1203	RHS	Cloth. Cable sheath, Entry: N/A, Route: H2 of 4, 5x8mmØ, H3, 3x8mmØ, 3x15mmØ, H4, 1x30mmØ, Exit: Signals trackside equipment. 12 x 82m					
39696	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1189	1190	RHS	Cloth. Cable sheath, H4, 1x30mmØ, spliced & mounted below H4. 1 x 1m					
37175	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1203	1208	RHS	Cloth. Cable sheath, Entry: N/A, Route: Between trackside equipment, H2, H3 & H4, 8mmØ to 30mmØ, Exit: N/A. numerous amounts					
37177	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1204		RHS	Trackside equipment: Signal (RPG12C)		1			



Hazardous Material Asset Register - Summary



P024-P - PIC Line - Bounds Green to Wood Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37176	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1204		RHS	Trackside equipment: Signal (PG12B)		1			
37178	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1205		RHS	Trackside equipment: Westinghouse small box		1			
37179	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1205		RHS	Trackside equipment: Westinghouse large box		1			
37181	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1206		RHS	Trackside equipment: Westinghouse large box		1			
37180	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1206		RHS	Trackside equipment: tencore box		1			
39749	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1207		RHS	Trackside equipment: tencore box		1			
37182	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1208	1214	RHS	Cloth. Cable sheath, Entry: Signals trackside equipment, Route: H2 of 4, ~8x8mmØ, H3, 5x8mmØ, 2x15mmØ, H4, 3x30mmØ, Exit: Westinghouse small box. 18 x 6m					
37183	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1208		RHS	Trackside equipment: Rail Gap Ind.		1			
37184	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1209		RHS	Trackside equipment: Westinghouse small box		1			
39750	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1214		RHS	Trackside equipment: Westinghouse small box		1			
37185	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1214	1257	RHS	Cloth. Cable sheath, Entry: N/A, Route: H2 of 4, ~8x8mmØ, H3, 4x8mmØ, 2x15mmØ, H4, 3x30mmØ, Exit: Westinghouse small box. 17 x 42.5m					
37186	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1216	1217	RHS	Cloth. Cable sheath, H4, 1x30mmØ, spliced & mounted below H4. 1 x 1m					
37015	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1257		RHS	Trackside equipment: Westinghouse small box		1			
37187	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1257	1264	RHS	Cloth. Cable sheath, Entry: Westinghouse small box, Route: H2 of 4, ~8x8mmØ, H3, 4x8mmØ, 2x15mmØ, H4, 3x30mmØ, Exit: CP. 11. 17 x 7.5m					
37016	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1261		RHS	Trackside equipment: type 79 box		1			
37017	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1263		LHS	Trackside equipment: tunnel lighting box		2			
37018	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1264	1296	RHS	Cloth. Cable sheath, Entry: N/A, Route: H2 of 4, ~6x8mmØ, H3, 4x8mmØ, 2x15mmØ, H4, 3x30mmØ, Exit: Signals trackside equipment. 15 x 32m					



Hazardous Material Asset Register - Summary



P024-P - PIC Line - Bounds Green to Wood Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39669	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1264	1268	RHS	Cloth. Cable sheath, Entry: WB P-Way, Route: along top of wall, 2x8mmØ, Exit: Sidings P-Way WB & EB Section. 2 x 4m					
37019	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1296	1301	RHS	Cloth. Cable sheath, Entry: N/A, Route: Between trackside equipment, H2, H3 & H4, 8mmØ to 30mmØ, Exit: N/A. numerous amounts					
37021	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1297		RHS	Trackside equipment: tencore box		1			
37020	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1297		RHS	Trackside equipment: Signal (PG12C)		1			
37022	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1298		RHS	Trackside equipment: Westinghouse small box		1			
37023	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1298		RHS	Trackside equipment: tencore box		1			
37024	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1299		RHS	Trackside equipment: Westinghouse large box		1			
37025	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1299		RHS	Trackside equipment: tencore box		1			
37026	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1301	1305	RHS	Cloth. Cable sheath, Entry: Signals trackside equipment, Route: H2 of 4, ~8x8mmØ, H3, 1x8mmØ, 3x15mmØ, H4, 3x30mmØ, Exit: N/A. 15 x 4.5m					
37027	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1301		RHS	Trackside equipment: Westinghouse small box		1			
37028	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1305	1392	RHS	Cloth. Cable sheath, Entry: Westinghouse small box, Route: H2 of 4, ~9x8mmØ, H3, 1x8mmØ, 3x15mmØ, H4, 3x30mmØ, Exit: N/A. 16 x 86.5m					
37029	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1305		RHS	Trackside equipment: Westinghouse small box		1			
37033	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cement Cable Troughing & Debris	Asbestos	Strongly Presumed	1357	1363		Cement. wall and door. 8m²					
37030	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cement Cable Troughing & Debris	Asbestos	Known	1357	1360		Cement. wall and door. 8m²					
37031	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cement Cable Troughing & Debris	Asbestos	Strongly Presumed	1357	1361		Cement. ceiling panels. Over Circuit Breaker. 2m²					
37032	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1357	1361		Trackside equipment: Circuit breaker		1			
42108	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Sampled – Not Detected	1390			Dust within small Westinghouse box, WB Cess 1390m.					



Hazardous Material Asset Register - Summary



P024-P - PIC Line - Bounds Green to Wood Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42106	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Other Electrical Boxes	Asbestos	Known				2 x 0.5m Braided cables within box, COLR, WB Cess 1390m.	0	2		N	N
46166	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Known	1390			2 x 5mm & 2 x 10mm braided cables within small Westinghouse box, WB Cess					
42105	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Other Electrical Boxes	Asbestos	Sampled – Not Detected				Dust within box, COLR, WB cess 1390m.				N	N
42109	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Strongly Presumed	1390			1 x Bakelite plates within small Westinghouse box, Cess 1390m		1			
42107	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Other Electrical Boxes	Asbestos	Strongly Presumed				1 x Silluminite plates within box, COLR, WB Cess 1390m.		1		N	N
42110	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Strongly Presumed	1390			2 x Washers within Small Westinghouse box, WB cess 1390m.		1			
39737	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1392	1395		Cloth. Cable sheath, Entry: OTX to RHS, Route: H1 of 10, 2x8mmØ, Exit: Rail Gap Ind. 2 x 3m					
37034	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1392	1398		Cloth. Cable sheath, Entry: OTX to LHS, Route: H2 of 4, ~11x8mmØ, H3, 1x8mmØ, 3x15mmØ, H4, 3x30mmØ, Exit: N/A. 18 x 6m					
37035	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1395		LHS	Trackside equipment: Rail Gap Ind.		1			
37036	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1398	1398	RHS	Cloth. Cable sheath, Entry: Westinghouse small box, Route: H2 of 4, ~12x8mmØ, H3, 1x8mmØ, 3x15mmØ, H4, 3x30mmØ, Exit: N/ A. 19 x 0.5m					
39381	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1398	1399	RHS	Cloth. Cable sheath, Entry: Westinghouse small box @ 1400.5m, Route: H2 of 4, ~12x8mmØ, H3, 3x8mmØ, 3x15mmØ, H4, 3x30mmØ, Exit: N/ A. 21 x 1m					
37037	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1398		RHS	Trackside equipment: Westinghouse small box		1			
37213	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1399		RHS	Trackside equipment: Westinghouse small box		1			
37038	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1399	1400		Cloth. Cable sheath, Entry: Westinghouse small box, Route: H2 of 4, ~13x8mmØ, H3, 3x8mmØ, 3x15mmØ, H4, 3x30mmØ, Exit: OTX to Sidings P-Way & OTX to LHS. 22 x 0.5m					
37215	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1400			Trackside equipment: Westinghouse small box		1			
37214	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1400	1404		Cloth. Cable sheath, Entry: OTX to RHS, Route: H8 of 10, 2x30mmØ, Exit: Cable Tunnel CT.01. 2 x 4m					
37216	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1401		LHS	Trackside equipment: 630V DC box		3			



Hazardous Material Asset Register - Summary



P024-P - PIC Line - Bounds Green to Wood Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37217	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1401		RHS	Trackside equipment: Westinghouse small box		1			
37218	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1401		RHS	Trackside equipment: electrical box					
37219	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1404		LHS	Cloth. Cable sheath, Entry: WB P-Way, Route: H8 of 10, 2x30mmØ, Exit: Overhead shaft via cable duct. 2 x 5.5m					
37220	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cement Cable Troughing & Debris	Asbestos	Known	1404	1410	RHS	Cement. cable duct lining & debris, Duct goes into floor. Loose debris where duct is damaged. 1 x 1m					
37221	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1408	1411	RHS	Cloth. Cable sheath, Entry: Wood Green Sidings WB Spur & Ten Core box, Route: H2 of 4, ~15x8mmØ, 1x15mmØ, 1x20mmØ, H3, 6x8mmØ, 3x15mmØ, 1x20mmØ, H4, 1x15mmØ, 2x30mmØ, Exit: N/A. 30 x 3m					
37222	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1408		RHS	Trackside equipment: tencore box		1			
37223	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1411	1424	RHS	Cloth. Cable sheath, Entry: Westinghouse small box, Route: H2 of 4, ~16x8mmØ, 1x15mmØ, 1x20mmØ, H3, 6x8mmØ, 3x15mmØ, 1x20mmØ, H4, 1x15mmØ, 2x30mmØ, Exit: N/A. 31 x 12.5 m					
37224	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1411		RHS	Trackside equipment: Westinghouse small box		1			
37225	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1424	1427	RHS	Cloth. Cable sheath, Entry: Westinghouse small box, Route: H2 of 4, ~16x8mmØ, 1x15mmØ, 1x20mmØ, H3, 6x8mmØ, 3x15mmØ, 1x20mmØ, H4, 1x15mmØ, 2x30mmØ, Exit: Westinghouse small box. 31 x 1.5m					
37227	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1427		RHS	Trackside equipment: Westinghouse small box		1			
37226	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1427	1433	RHS	Cloth. Cable sheath, Entry: Westinghouse small box, Route: H2 of 4, ~16x8mmØ, 1x15mmØ, 1x20mmØ, H3, 6x8mmØ, 3x15mmØ, 1x20mmØ, H4, 1x15mmØ, 2x30mmØ, Exit: Signals trackside equipment. 31 x 6m					
37228	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1433		RHS	Trackside equipment: tencore box		1			
39406	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1433	1437	RHS	Cloth. Cable sheath, Entry: N/A, Route: Between trackside equipment, H2, H3 & H4, 8mmØ to 30mmØ, Exit: N/A. numerous amounts					
37230	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1434		RHS	Trackside equipment: tencore box		1			



Hazardous Material Asset Register - Summary



P024-P - PIC Line - Bounds Green to Wood Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37229	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1434		RHS	Trackside equipment: Westinghouse small box		1			
37231	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1434		RHS	Trackside equipment: Westinghouse small box		1			
37232	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1435		RHS	Trackside equipment: tencore box		1			
39752	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1435		RHS	Trackside equipment: tencore box		1			
37233	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1435		RHS	Trackside equipment: Westinghouse small box		1			
37234	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1436		RHS	Trackside equipment: tencore box		1			
37235	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Ducts	Asbestos	Presumed	1436	1437	LHS	Cement. cable duct lining, Presumed present (In floor & sealed)		1			
37236	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1437		RHS	Trackside equipment: tencore box		2			
37237	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1437		RHS	Trackside equipment: Westinghouse small box		1			
39753	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1437	1437	RHS	Cloth. Cable sheath, Entry: Signals trackside equipment, Route: H2 of 4, ~12x8mmØ, 1x15mmØ, 1x20mmØ, H3, 6x8mmØ, 4x15mmØ, H4, 1x15mmØ, 2x30mmØ, Exit: Platform wall. 27 x 0.5m					
39698	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Westinghouse Boxes	Asbestos	Presumed	1437		RHS	Trackside equipment: Westinghouse small box		1			
37238	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Signal Boxes	Asbestos	Presumed	1437		RHS	Trackside equipment: Signal (PG4)		1			
37239	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Ducts	Asbestos	Presumed	1438		LHS	Cement. cable duct lining, Presumed present (In platform wall & sealed)		1			
37240	ACTIVE	P	P024-P-WBLO	Road WBLO - PIC - Bounds Green to Wood Green	Ducts	Asbestos	Presumed	1438		RHS	Cement. cable duct lining, Presumed present (In platform wall & sealed)		3			

P025-P - PIC Line - Wood Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42777	ACTIVE	P	P025-P-EBLO	Road EBLO (Pit1) - PIC - Wood Green Stn	Pit Blocks	Asbestos	Removed				Pit blocks - Non asbestos (Removed by Forest 2007 ES2020)					



Hazardous Material Asset Register - Summary



P025-P - PIC Line - Wood Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41679	ACTIVE	P	P025-P-EBLO	Road EBLO (Plt1) - PIC - Wood Green Stn	Westinghouse Boxes	Asbestos	Removed	3		RHS	Trackside equipment: westinghouse small box Notes from 2022 re-inspection: Removed		1			
41680	ACTIVE	P	P025-P-EBLO	Road EBLO (Plt1) - PIC - Wood Green Stn	Signal Boxes	Asbestos	Removed	36		RHS	Trackside equipment: 630V DC box Notes from 2022 re-inspection: Removed		1			
41681	ACTIVE	P	P025-P-EBLO	Road EBLO (Plt1) - PIC - Wood Green Stn	Westinghouse Boxes	Asbestos	Removed	40		RHS	Trackside equipment: westinghouse small box Notes from 2022 re-inspection: Removed		2			
41682	ACTIVE	P	P025-P-EBLO	Road EBLO (Plt1) - PIC - Wood Green Stn	Signal Boxes	Asbestos	Removed	112		RHS	Trackside equipment: redifon loop aerial Notes from 2022 re-inspection: Removed		1			
41683	ACTIVE	P	P025-P-EBLO	Road EBLO (Plt1) - PIC - Wood Green Stn	Ducts	Asbestos	Presumed	117		LHS	cement cable duct lining. Presumed present (In platform wall & sealed)		4			
42778	ACTIVE	P	P025-P-WBLO	Road WBLO (Plt2) - PIC - Wood Green Stn	Pit Blocks	Asbestos	Surveyed – Not Detected				Pit blocks - Non asbestos					
41684	ACTIVE	P	P025-P-WBLO	Road WBLO (Plt2) - PIC - Wood Green Stn	Westinghouse Boxes	Asbestos	Removed	64		RHS	Trackside equipment: westinghouse small box Notes from 2022 re-inspection: Removed		1			
41685	ACTIVE	P	P025-P-WBLO	Road WBLO (Plt2) - PIC - Wood Green Stn	Westinghouse Boxes	Asbestos	Removed	71		RHS	Trackside equipment: westinghouse small box Notes from 2022 re-inspection: Removed		1			
41686	ACTIVE	P	P025-P-WBLO	Road WBLO (Plt2) - PIC - Wood Green Stn	Signal Boxes	Asbestos	Removed	81		RHS	Trackside equipment: 630V DC box Notes from 2022 re-inspection: Removed		1			
41687	ACTIVE	P	P025-P-WBLO	Road WBLO (Plt2) - PIC - Wood Green Stn	Signal Boxes	Asbestos	Presumed	113		RHS	Trackside equipment: redifon loop aerial Notes from 2022 re-inspection: EP valve		1			

P026-P - PIC Line - Wood Green to Turnpike Lane

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40436	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Ducts	Asbestos	Presumed	1		RHS	Cement. Cable duct lining, Presumed present (In platform wall & sealed)		3			
40435	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	1	9	RHS	Cloth. cable sheath, Entry: Platform wall, Route: H2 of 4, 2x8mmØ, H3 1x15mmØ, 1x20mmØ, H4, 1x40mmØ, Exit: Signals trackside equipment. 5 x 8m					
39402	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Ducts	Asbestos	Presumed	1	2	LHS	Cement. Cable duct lining, Presumed present (In floor & sealed)		2			



Hazardous Material Asset Register - Summary



P026-P - PIC Line - Wood Green to Turnpike Lane

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40437	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	4	5	RHS	Cloth. cable sheath, H4, 1x40mmØ spliced & mounted below H4. 1 x1m					
40439	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Signal Boxes	Asbestos	Presumed	9		RHS	Trackside equipment: Signal (A871)		1			
40438	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	9	12	RHS	Cloth. cable sheath, Entry: N/A, Route: Between trackside equipment, H2, H3 & H4, 8mmØ to 40mmØ, Exit: N/A. numerous amounts					
40440	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	11		RHS	Trackside equipment: westinghouse small box		1			
40441	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Signal Boxes	Asbestos	Presumed	11		RHS	Trackside equipment: tencore box		1			
40443	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Signal Boxes	Asbestos	Presumed	12		RHS	Trackside equipment: tencore box		1			
40442	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	12	16	RHS	Cloth. cable sheath, Entry: Signals trackside equipment, Route: H2 of 4, 1x8mmØ, H3, 1x8mmØ, 1x20mmØ, H4, 1x40mmØ, Exit: Ten Core box. 4 x4m					
40444	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	12		RHS	Trackside equipment: westinghouse large box		1			
40445	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	16	78	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, 1x8mmØ, H3, 1x8mmØ, H4, 1x40mmØ, Exit: Westinghouse small box. 3 x 62.5m					
40446	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Signal Boxes	Asbestos	Presumed	16		RHS	Trackside equipment: tencore box		1			
39952	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	17		RHS	Trackside equipment: westinghouse small box		1			
40447	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Signal Boxes	Asbestos	Presumed	18		RHS	Trackside equipment: tencore box		1			
40448	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Signal Boxes	Asbestos	Presumed	20		RHS	Trackside equipment: tencore box		1			
40449	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	21		RHS	Trackside equipment: westinghouse small box		1			
40451	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	78		RHS	Trackside equipment: westinghouse small box		1			
40450	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	78	80	RHS	Cloth. cable sheath, Entry: N/A, Route: H3 of 4, 1x8mmØ, H4, 1x40mmØ, Exit: Westinghouse small box. 2 x2m					
40452	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	80		RHS	Trackside equipment: westinghouse small box		1			



Hazardous Material Asset Register - Summary



P026-P - PIC Line - Wood Green to Turnpike Lane

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39428	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	80	471	RHS	Cloth. cable sheath, Entry: N/A, Route: H4 of 4, 1x40mmØ, Exit: Signals trackside equipment. 1 x 391m					
40453	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	144	145	RHS	Cloth. cable sheath, H4, 1x40mmØ spliced & mounted below H4. 1 x1m					
40454	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Signal Boxes	Asbestos	Presumed	299		RHS	Trackside equipment: type 79 box		1			
40455	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	331		RHS	Trackside equipment: westinghouse small box		1			
40456	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Signal Boxes	Asbestos	Presumed	439		RHS	Trackside equipment: Main Earth Terminal box		1			
40457	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	471	475	RHS	Cloth. cable sheath, H4, Entry: N/A, Route: Between trackside equipment, H2 & H4, 8mmØ to 40mmØ, Exit: N/A. numerous amounts					
39429	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Signal Boxes	Asbestos	Presumed	471		RHS	Trackside equipment: Signal (A875)		1			
40458	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	472		RHS	Trackside equipment: westinghouse small box		1			
40459	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Signal Boxes	Asbestos	Presumed	473		RHS	Trackside equipment: tencore box		1			
40539	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	473		RHS	Trackside equipment: westinghouse large box		1			
40540	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	474		RHS	Trackside equipment: westinghouse large box Notes from 2022 re-inspection: Removed LWH but now 10 core		1			
40541	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	475	579	RHS	Cloth. cable sheath, Entry: Signals trackside equipment, Route: H2 of 4, 1x8mmØ, H3, 1x8mmØ, H4, 1x40mmØ, Exit: Signals trackside equipment. 4 x 104m					
40542	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	475		RHS	Trackside equipment: westinghouse small box		1			
40543	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	477		RHS	Trackside equipment: westinghouse small box		1			
40544	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	478		RHS	Trackside equipment: westinghouse small box		1			
40546	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Signal Boxes	Asbestos	Presumed	588		RHS	Trackside equipment: Signal (R879AB)		1			
40547	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	588	724	RHS	Cloth. cable sheath, Entry: Signals trackside equipment, Route: H2 of 4, 2x8mmØ, H3, 2x8mmØ, H4, 1x40mmØ, Exit: Signals trackside equipment. 5 x 136m					



Hazardous Material Asset Register - Summary



P026-P - PIC Line - Wood Green to Turnpike Lane

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40545	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	588	588	RHS	Cloth. cable sheath, Entry: N/A, Route: Between trackside equipment, H2, H3 & H4, 8mmØ to 40mmØ, Exit: N/A. numerous amounts					
40548	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	588		RHS	Trackside equipment: westinghouse large box		1			
40549	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	613		RHS	Trackside equipment: westinghouse small box		1			
39734	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	614		RHS	Trackside equipment: westinghouse small box		1			
40551	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	617		RHS	Cloth. cable sheath, 1x8mmØ from Westinghouse small box severed & tied around H3. 1 x1m					
40550	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	617		RHS	Trackside equipment: westinghouse small box		1			
40552	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	643	644	RHS	Cloth. cable sheath, H4, 1x40mmØ spliced & mounted below H4. 1 x 1m					
40553	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	673	674	RHS	Cloth. cable sheath, H4, 1x40mmØ spliced & mounted below H4. 1 x 1m					
40554	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Signal Boxes	Asbestos	Presumed	717		RHS	Trackside equipment: type 79 box		1			
40556	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Signal Boxes	Asbestos	Presumed	724		RHS	Trackside equipment: Signal (R879B PG1)		1			
40555	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	724	729	RHS	Cloth. cable sheath, Entry: N/A, Route: Between trackside equipment, H2, H3 & H4, 8mmØ to 40mmØ, Exit: N/A. numerous amounts					
40557	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Signal Boxes	Asbestos	Presumed	725		RHS	Trackside equipment: Signal (A879 A)		1			
39956	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	726		RHS	Trackside equipment: westinghouse large box		1			
40558	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	726		RHS	Trackside equipment: westinghouse small box		1			
40559	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Signal Boxes	Asbestos	Presumed	727		RHS	Trackside equipment: Ten core box		1			
39436	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	727		RHS	Trackside equipment: Westinghouse large box		1			
40561	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Signal Boxes	Asbestos	Presumed	729		RHS	Trackside equipment: tencore box		1			



Hazardous Material Asset Register - Summary



P026-P - PIC Line - Wood Green to Turnpike Lane

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40560	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	729	738	RHS	Cloth. cable sheath, Entry: Signals trackside equipment, Route: H3 of 4, 6x8mmØ, 1x20mmØ, H4, 1x40mmØ, Exit: Westinghouse small box. 8 x 9.5m					
39437	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	738		RHS	Trackside equipment: westinghouse small box		1			
40562	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	738	748	RHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: H3 of 4, 6x8mmØ, 1x20mmØ, H4, 1x40mmØ, Exit: N/A. 8 X 10M					
40642	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	748	753	RHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: H3 of 4, 7x8mmØ, 1x20mmØ, H4, 1x40mmØ, Exit: Westinghouse small box. 9 x 4.5m					
40643	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	748		RHS	Trackside equipment: westinghouse small box		1			
40645	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	753		RHS	Trackside equipment: westinghouse small box		1			
40644	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	753	799	RHS	Cloth. cable sheath, Entry: N/A, Route: H3 of 4, 6x8mmØ, 1x20mmØ, H4, 1x40mmØ, Exit: Signals trackside equipment					
40648	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Signal Boxes	Asbestos	Presumed	799		RHS	Trackside equipment: Signal (A879B)		1			
40647	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	799	803	RHS	Cloth. cable sheath, Entry: N/A, Route: Between trackside equipment, H2,H3 & H4, 8mmØ to 40mmØ, Exit: N/A. numerous amounts					
40646	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Signal Boxes	Asbestos	Presumed	799		RHS	Trackside equipment: Signal (RPG1)		1			
40649	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	800		RHS	Trackside equipment: westinghouse small box		1			
40650	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Signal Boxes	Asbestos	Presumed	801		RHS	Trackside equipment: tencore box		1			
40651	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	802		RHS	Trackside equipment: westinghouse large box		1			
40652	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	803		RHS	Trackside equipment: westinghouse small box		1			
39982	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	803	808	RHS	Cloth. cable sheath, Entry: Signals trackside equipment, Route: H2 of 4, 1x8 mmØ, H3, ~6x8mmØ, 2x20mmØ, H4, 1x40mmØ, Exit: Westinghouse small box. 10 x 5m					
39783	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Signal Boxes	Asbestos	Presumed	803		RHS	Trackside equipment: tencore box		1			



Hazardous Material Asset Register - Summary



P026-P - PIC Line - Wood Green to Turnpike Lane

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40653	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	808	851	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, 1x8 mmØ, H3, ~5x8mmØ, 2x20mmØ, H4, 1x40mmØ, Exit: Signals trackside equipment. 9 x 42.5m					
40654	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	808		RHS	Trackside equipment: westinghouse small box		1			
40656	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Signal Boxes	Asbestos	Presumed	851		RHS	Trackside equipment: Signal (PG1)		1			
40655	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	851	854	RHS	Cloth. cable sheath, Entry: N/A, Route: Between trackside equipment, H2,H3 & H4, 8mmØ to 40mmØ, Exit: N/A. numerous amounts					
40657	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	852		RHS	Trackside equipment: westinghouse small box		1			
40658	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Signal Boxes	Asbestos	Presumed	853		RHS	Trackside equipment: tencore box		1			
39445	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	853		RHS	Trackside equipment: westinghouse large box		1			
40660	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Signal Boxes	Asbestos	Presumed	854		RHS	Trackside equipment: tencore box		1			
40659	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	854	866	RHS	Cloth. cable sheath, Entry: Signals trackside equipment, Route: H2 of 4, 1x8 mmØ, H3, ~5x8mmØ, 1x15mmØ, 2x20mmØ, H4, 1x8 mmØ, 1x40mmØ, Exit: N/A. 11 x 12m					
40661	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	861		RHS	Trackside equipment: westinghouse small box		1			
40662	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cement Cable Troughing & Debris	Asbestos	Known	863			Cement, cable trough. Loose cover, 1.5m² UTX & RHS					
39446	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cement Cable Troughing & Debris	Asbestos	Strongly Presumed	863	864	RHS	Cement. Boxes, Casings to Current Rail Section switches. 2x1m² Removed by Edenbeck 08-06-2017 (ES9951) Re-inspection carried out 27/05/2018 states item is still present					
40663	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cement Cable Troughing & Debris	Asbestos	Strongly Presumed	864			Cement, cable trough.1.5m² UTX & RHS					
40664	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cement Cable Troughing & Debris	Asbestos	Strongly Presumed	865			Cement, cable trough. Loose cover. 2 x 1.5m² UTX RHS					
40747	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	866		RHS	Trackside equipment: westinghouse small box		1			



Hazardous Material Asset Register - Summary



P026-P - PIC Line - Wood Green to Turnpike Lane

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40665	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	866	870	RHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: H2 of 4, 2x8 mmØ, H3, ~5x8mmØ, 1x15mmØ, 2x20mmØ, H4, 1x8 mmØ, 1x40mmØ, Exit: N/A. 12 x 4m					
40748	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Signal Boxes	Asbestos	Presumed	869		RHS	Trackside equipment: signal		1			
40749	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	870	878	RHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: H2 of 4, 2x8 mmØ, H3, ~6x8mmØ, 1x15mmØ, 2x20mmØ, H4, 1x8 mmØ, 1x40mmØ, Exit: Platform wall. 13 x 8.5m					
40750	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Westinghouse Boxes	Asbestos	Presumed	870		RHS	Trackside equipment: westinghouse small box		1			
40751	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cable Sheath	Asbestos	Strongly Presumed	875	876	RHS	Cloth. cable sheath, H4, 1x40mmØ spliced & mounted below H4. 1 x 1m					
39787	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Ducts	Asbestos	Presumed	877	878	RHS	cement cable duct lining. Presumed present (In floor & sealed)		4			
40754	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cement Cable Troughing & Debris	Asbestos	Strongly Presumed	877		LHS	cement cable trough. 0 .25m					
40755	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Cement Cable Troughing & Debris	Asbestos	Removed	877			cement cable trough. 0.5m UTX & LHS Notes from 2022 re-inspection: Removed					
40753	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Ducts	Asbestos	Presumed	878		RHS	bitumen cable duct lining. In platform wall		4			
40752	ACTIVE	P	P026-P-EBLO	Road EBLO - PIC - Turnpike Lane to Wood Green	Ducts	Asbestos	Presumed	878		RHS	cement cable duct lining. Presumed present (In platform wall & sealed)		4			
41288	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	1	5	RHS	Cloth. cable sheath, Entry: Platform wall, Route: H2 of 4, 8x8mmØ, 2x15mmØ, H4, 1x30mmØ, Exit: Signals trackside equipment. 11 X 4m					
41289	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Ducts	Asbestos	Presumed	1		RHS	Cement. cable duct lining, Presumed present (In platform wall & sealed)		1			
41290	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Ducts	Asbestos	Presumed	2	2	RHS	Cement. cable duct lining, Presumed present (In floor & sealed)		5			
39542	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cement Cable Troughing & Debris	Asbestos	Known	2		LHS	cement cable trough. 0.25m					
41291	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	5	8	RHS	Cloth. cable sheath, Entry: N/A, Route: Between trackside equipment, H2, H3 & H4, 8 to 30mmØ, Exit: N/A. numerous amounts					
40036	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Signal Boxes	Asbestos	Presumed	5		RHS	Trackside equipment: Signal (PG11)		1			



Hazardous Material Asset Register - Summary



P026-P - PIC Line - Wood Green to Turnpike Lane

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41292	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	6		RHS	Trackside equipment: westinghouse large box		1			
41294	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Signal Boxes	Asbestos	Presumed	7		RHS	Trackside equipment: tencore box		1			
41293	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Signal Boxes	Asbestos	Presumed	7		RHS	Trackside equipment: tencore box		1			
41295	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	8		RHS	Trackside equipment: westinghouse small box		1			
39564	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	8	11	RHS	Cloth. cable sheath, Entry: Signals trackside equipment, Route: H2 of 4, ~7x8mmØ, 1x20mmØ, H3, 1x8mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 10 x 3m					
41297	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	11		RHS	Trackside equipment: westinghouse small box		1			
41296	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	11	17	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, ~6x8mmØ, 1x20mmØ, H3, 1x8mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 9 x 6m					
41376	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	17		RHS	Trackside equipment: westinghouse small box		1			
41375	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	17	18	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, ~5x8mmØ, 1x20mmØ, H3, 1x8mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 8 x 1m					
41378	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	18		RHS	Trackside equipment: westinghouse small box		1			
41377	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	18	23	RHS	Cloth. cable sheath, Entry:N/A, Route: H2 of 4, ~4x8mmØ, 1x20mmØ, H3 1x8mmØ, H4 1x30mmØ, Exit: Westinghouse small box. 7 x 5.5m					
41379	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Track Section Switches	Asbestos	Removed	20	21	RHS	Cement boxes, Casings to Current Rail Section switches. 2x1m² Removed by Edenbeck 08-06-2017 (ES9951)					
41380	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	23	52	RHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: H2 of 4, ~4x8mmØ, 1x20mmØ, H3, 1x8mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 7 x 29m					
41381	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	23		RHS	Trackside equipment: westinghouse small box		1			
41382	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Signal Boxes	Asbestos	Presumed	44		RHS	Trackside equipment: type 79 box		1			
41383	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	52		RHS	Trackside equipment: westinghouse small box		1			



Hazardous Material Asset Register - Summary



P026-P - PIC Line - Wood Green to Turnpike Lane

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40039	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	52	74	RHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: H2 of 4, ~4x8mmØ, 1x20mmØ, H3, 1x8mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 7 x 22m					
41385	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	74		RHS	Trackside equipment: westinghouse small box		1			
41384	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	74	80	RHS	Cloth. cable sheath, Entry:N/A, Route: H2 of 4, ~3x8mmØ, 1x20mmØ, H3, 1x8mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 6 x 6m					
39854	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	80	245	RHS	Cloth. cable sheath, Entry:N/A, Route: H2 of 4, ~2x8mmØ, 1x20mmØ, H3 1x8mmØ, H4 1x30mmØ, Exit: N/A. 5 x 164.5m					
41386	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	80		RHS	Trackside equipment: westinghouse small box		1			
41387	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	240	241	RHS	Cloth. cable sheath, H4, 1x30mmØ cable spliced & mounted below H4. 1 x 1m					
41388	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	245	246	RHS	Cloth. cable sheath, Entry: Signal (R876), Route: H2 of 4, ~4x8mmØ, 1x20mmØ, H3, 1x8mmØ, H4, 1x30mmØ, Exit: Westinghouse large box. 7 x 1m					
41389	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Signal Boxes	Asbestos	Presumed	245		RHS	Trackside equipment: Signal (R876)		1			
41390	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	246	253	RHS	Cloth. cable sheath, Entry: Westinghouse large box, Route: H2 of 4, ~4x8mmØ, 1x20mmØ, H3, 1x8mmØ, H4, 1x30mmØ, Exit: Ten Core box. 7 x 7.5m					
41391	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	246		RHS	Trackside equipment: westinghouse large box		1			
41392	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	253	255	RHS	Cloth. cable sheath, Entry:Ten Core box, Route: H2 of 4, ~5x8mmØ, H3, 1x8mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 7 x 1.5m					
41393	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Signal Boxes	Asbestos	Presumed	253		RHS	Trackside equipment: tencore box		1			
39571	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	255		RHS	Trackside equipment: westinghouse small box		1			
41394	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	255	259	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, ~4x8mmØ, H3, 1x8mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 6 x 4m					
41395	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	259	435	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, ~4x8mmØ, H4, 1x30mmØ, Exit: Signals trackside equipment. 5 x 176m					
41396	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	259		RHS	Trackside equipment: westinghouse small box		1			



Hazardous Material Asset Register - Summary



P026-P - PIC Line - Wood Green to Turnpike Lane

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41397	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Signal Boxes	Asbestos	Presumed	265		RHS	Trackside equipment: type 79 box		1			
41474	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	291		RHS	Trackside equipment: westinghouse small box		1			
41477	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Signal Boxes	Asbestos	Presumed	435		RHS	Trackside equipment: Signal (R870A)		1			
41476	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Signal Boxes	Asbestos	Presumed	435		RHS	Trackside equipment: Signal (R870A)		1			
41475	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	435	438	RHS	Cloth. cable sheath, Entry: N/A, Route: Between trackside equipment, H2, H3 & H4, 8mmØ to 30mmØ, Exit: N/A. numerous amounts					
41478	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	436		RHS	Trackside equipment: westinghouse large box Notes from 2022 re-inspection: Removed LWH now SWH		1			
41479	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Signal Boxes	Asbestos	Presumed	436		RHS	Trackside equipment: tencore box		1			
40043	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	437		RHS	Trackside equipment: westinghouse large box		1			
41481	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	437		RHS	Trackside equipment: westinghouse small box		1			
41480	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Signal Boxes	Asbestos	Presumed	437		RHS	Trackside equipment: tencore box		1			
41483	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	438		RHS	Trackside equipment: westinghouse large box		1			
41482	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	438	444	RHS	Cloth. cable sheath, Entry: Signals trackside equipment, Route: H2 of 4, ~4x8mmØ, H3, 1x20mm, H4, 1x30mmØ, Exit: Westinghouse small box. 6 x 6m					
41484	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Signal Boxes	Asbestos	Presumed	439		RHS	Trackside equipment: tencore box		1			
41485	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Signal Boxes	Asbestos	Presumed	439		RHS	Trackside equipment: Main Earth Terminal box		1			
41486	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	444	446	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, ~3x8mmØ, H3, 1x20mmØ, H4, 1x30mmØ, Exit: Westinghouse small box					
41487	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	444		RHS	Trackside equipment: westinghouse small box		1			
41489	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	446		RHS	Trackside equipment: westinghouse small box		1			



Hazardous Material Asset Register - Summary



P026-P - PIC Line - Wood Green to Turnpike Lane

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41488	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	446	448	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, ~3x8mmØ, H3, 1x20mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 5 x 2.5m					
39506	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	448		RHS	Trackside equipment: westinghouse small box		1			
41490	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	448	630	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, ~2x8mmØ, H3, 1x20mmØ, H4, 1x30mmØ, Exit: Signals trackside equipment. 4 x 182m					
41492	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Signal Boxes	Asbestos	Presumed	630		RHS	Trackside equipment: Signal (A870A)		1			
41491	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	630	634	RHS	Cloth. cable sheath, Entry: N/A, Route: Between trackside equipment, H2, H3 & H4, 8mmØ to 30mmØ, Exit: N/A. numerous amounts					
41494	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	631		RHS	Trackside equipment: westinghouse small box		1			
41493	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Signal Boxes	Asbestos	Presumed	631		RHS	Trackside equipment: Signal (R870BC)		1			
41495	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	632		RHS	Trackside equipment: westinghouse large box		1			
39577	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Signal Boxes	Asbestos	Presumed	632		RHS	Trackside equipment: tencore box		1			
41496	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	633		RHS	Trackside equipment: westinghouse large box		1			
41497	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	634	657	RHS	Cloth. cable sheath, Entry: Signal trackside equipment, Route: H2 of 4, ~6x8mmØ, H3, 2x20mmØ, H4, 1x30mmØ, Exit: N/A. 9 x 23.5m					
39858	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Signal Boxes	Asbestos	Presumed	634		RHS	Trackside equipment: tencore box		1			
41575	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	657	662	RHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: H2 of 4, ~7x8mmØ, H3, 2x20mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 10 x 5m					
41576	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	657		RHS	Trackside equipment: westinghouse small box		1			
41577	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	662	706	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, ~6x8mmØ, H3, 2x20mmØ, H4, 1x30mmØ, Exit: Signals trackside equipment. 9 x 43.5m					
41578	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	662		RHS	Trackside equipment: westinghouse small box		1			



Hazardous Material Asset Register - Summary



P026-P - PIC Line - Wood Green to Turnpike Lane

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41579	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Signal Boxes	Asbestos	Presumed	697		RHS	Trackside equipment: type 79 box		1			
41580	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	698		RHS	Trackside equipment: westinghouse small box		1			
41581	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	706	707	RHS	Cloth. cable sheath, Entry: N/A, Route: Between trackside equipment, H2, H3 & H4, 8mmØ to 30mmØ, Exit: N/A. numerous amounts					
41582	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Signal Boxes	Asbestos	Presumed	706		RHS	Trackside equipment: Signal (A8706)					
41583	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	707		RHS	Trackside equipment: westinghouse large box		1			
39862	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	707		RHS	Trackside equipment: westinghouse small box		1			
39364	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	707	715	RHS	Cloth. cable sheath, Entry: Signals trackside equipment, Route: H2 of 4, ~8x8mmØ, H3, 2x20mmØ, H4, 1x30mmØ, Exit: N/A. 11 x 75m					
41584	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Signal Boxes	Asbestos	Presumed	707		RHS	Trackside equipment: tencore box		1			
41585	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	715	720	RHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: H2 of 4, ~8x8mmØ, H3, 2x20mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 12 x 5m					
41586	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	715		RHS	Trackside equipment: westinghouse small box		1			
41587	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	716		RHS	Trackside equipment: westinghouse small box		1			
41588	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	720	773	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, ~8x8mmØ, H3, 2x20mmØ, H4, 1x30mmØ, Exit: Signals trackside equipment. 11 x 53m					
41589	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	720		RHS	Trackside equipment: westinghouse small box		1			
41595	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	734		RHS	Trackside equipment: westinghouse small box		1			
41590	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	738	739	RHS	Cloth. cable sheath, H4, 1x30mmØ cable spliced & mounted below H4. 1 x 1m					
41592	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Signal Boxes	Asbestos	Presumed	773		RHS	Trackside equipment: Signal (A870C)		1			
41591	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	773	775	RHS	Cloth. cable sheath, Entry: N/A, Route: Between trackside equipment, H2, H3 & H4, 8mmØ to 30mmØ, Exit: N/A. numerous amounts					



Hazardous Material Asset Register - Summary



P026-P - PIC Line - Wood Green to Turnpike Lane

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41594	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	773		RHS	Trackside equipment: westinghouse small box		1			
41593	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Signal Boxes	Asbestos	Presumed	773		RHS	Trackside equipment: tencore box		1			
41596	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Signal Boxes	Asbestos	Presumed	774		RHS	Trackside equipment: tencore box		1			
39585	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	774		RHS	Trackside equipment: westinghouse large box		1			
41597	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	775	796	RHS	Cloth. cable sheath, Entry: Signals trackside equipment, Route: H2 of 4, ~6x8mmØ, H3, 2x20mmØ, H4, 1x30mmØ, Exit: N/A. 10 x 21.5m					
41598	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Signal Boxes	Asbestos	Presumed	775		RHS	Trackside equipment: tencore box		1			
41672	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	796	800	RHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: H2 of 4, ~7x8mmØ, H3, 3x20mmØ, H4, 1x30mmØ, Exit: N/A. 11 x 4m					
41673	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	796		RHS	Trackside equipment: westinghouse small box		1			
41675	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	800		RHS	Trackside equipment: westinghouse small box		1			
41674	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	800	864	RHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: H2 of 4, ~8x8mmØ, H3, 3x20mmØ, H4, 1x30mmØ, Exit: N/A. 12 x 64m					
41676	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	864	869	RHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: H2 of 4, ~9x8mmØ, H3, 3x20mmØ, H4, 1x30mmØ, Exit: N/A. 13 x 4.5m					
41677	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	864		RHS	Trackside equipment: westinghouse small box		1			
39368	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	869		RHS	Trackside equipment: westinghouse small box		1			
41678	ACTIVE	P	P026-P-WBLO	Road WBLO - PIC - Wood Green to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	869	880	RHS	Cloth. cable sheath, Entry: Westinghouse small box, Route: H2 of 4, ~10x8mmØ, H3, 3x20mmØ, H4, 1x30mmØ, Exit: Platform Wall. 14 x 11.5m					

P027-P - PIC Line - Turnpike Lane Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42775	ACTIVE	P	P027-P-EBLO	Road EBLO (Plt1) - PIC - Turnpike Lane Stn	Pit Blocks	Asbestos	Surveyed – Not Detected				Pit blocks - Non asbestos					



Hazardous Material Asset Register - Summary



P027-P - PIC Line - Turnpike Lane Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40756	ACTIVE	P	P027-P-EBLO	Road EBLO (Plt1) - PIC - Turnpike Lane Stn	Westinghouse Boxes	Asbestos	Presumed	62		RHS	Trackside equipment: westinghouse small box					
40757	ACTIVE	P	P027-P-EBLO	Road EBLO (Plt1) - PIC - Turnpike Lane Stn	Westinghouse Boxes	Asbestos	Presumed	65		RHS	Trackside equipment: westinghouse small box					
40758	ACTIVE	P	P027-P-EBLO	Road EBLO (Plt1) - PIC - Turnpike Lane Stn	Signal Boxes	Asbestos	Removed	82		RHS	Trackside equipment: 630V DC box Notes from 2022 re-inspection: Removed					
40759	ACTIVE	P	P027-P-EBLO	Road EBLO (Plt1) - PIC - Turnpike Lane Stn	Signal Boxes	Asbestos	Presumed	112		RHS	Trackside equipment: Redifon loop aerial box					
42776	ACTIVE	P	P027-P-WBLO	Road WBLO (Plt2) - PIC - Turnpike Lane Stn	Pit Blocks	Asbestos	Surveyed – Not Detected				Pit blocks - Non asbestos					
40760	ACTIVE	P	P027-P-WBLO	Road WBLO (Plt2) - PIC - Turnpike Lane Stn	Signal Boxes	Asbestos	Removed	36		RHS	Trackside equipment: 630V DC connection Notes from 2022 re-inspection: Removed		1			
39986	ACTIVE	P	P027-P-WBLO	Road WBLO (Plt2) - PIC - Turnpike Lane Stn	Westinghouse Boxes	Asbestos	Presumed	60		RHS	Trackside equipment: westinghouse small box		1			
40761	ACTIVE	P	P027-P-WBLO	Road WBLO (Plt2) - PIC - Turnpike Lane Stn	Westinghouse Boxes	Asbestos	Presumed	65		RHS	Trackside equipment: westinghouse small box		1			
40762	ACTIVE	P	P027-P-WBLO	Road WBLO (Plt2) - PIC - Turnpike Lane Stn	Signal Boxes	Asbestos	Presumed	112		RHS	Trackside equipment: Redifon loop aerial box		1			

P028-P - PIC Line - Turnpike Lane to Manor House

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40007	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cement Cable Troughing & Debris	Asbestos	Known	1	5		Cement, cable trough LHS & UTX		3			
38619	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	9	12	RHS	Cloth cable sheath. Entry: N/A, Route: Between trackside equipment, H2 & H3, 8mm to 15mmØ, Exit: N/A. numerous amounts					
38620	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Signal Boxes	Asbestos	Presumed	9		RHS	Trackside equipment: Signal (A851)		1			
38621	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	10		RHS	Trackside equipment: Westinghouse small box		1			
38622	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Signal Boxes	Asbestos	Presumed	11		RHS	Trackside equipment: tencore box		1			
38624	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Signal Boxes	Asbestos	Presumed	12		RHS	Trackside equipment: tencore box		1			



Hazardous Material Asset Register - Summary



P028-P - PIC Line - Turnpike Lane to Manor House

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38623	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	12	68	RHS	Cloth cable sheath. Entry: Signals trackside equipment, Route: H2 of 5, 1x8mmØ, H3, 1x15mmØ, Exit: Westinghouse small box. 2 x 56m					
38625	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Signal Boxes	Asbestos	Presumed	13	15	LHS	Trackside equipment: Tunnel lighting box		3			
38626	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Westinghouse Boxes	Asbestos	Presumed	20		RHS	Trackside equipment: Westinghouse small box		1			
38629	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	68	115	RHS	Cloth cable sheath. Entry: N/A, Route: H3 of 5, 1x15mmØ, Exit: N/A. 1 x 47m					
38634	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	115	200	RHS	Cloth cable sheath. Entry: CT.01, Route: H3 of 4, 1x15mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 2 x 84.5m					
39675	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	121	123	RHS	Cloth cable sheath. 2x30mmØ on cleats mounted below H4. 2 x 2m					
38637	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cement Cable Troughing & Debris	Asbestos	Strongly Presumed	121		RHS	cement, cable trough. 0 .25m Below COLR box					
38641	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	193	194	RHS	Cloth cable sheath. 2x4mmØ from Ten Core box to H1 via H2. 2 x 3m					
40010	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	200	364	RHS	Cloth cable sheath. Entry: Westinghouse small box, Route: H3 of 4, 1x15mmØ, H4, 1x30mmØ, Exit: Ten Core box. 2 x 164.5m					
38648	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	252		RHS	Cloth cable sheath. 1x4mmØ from Westinghouse large box to H1. 1 x 1m					
38652	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	364	376	RHS	Cloth cable sheath. Entry: Ten Core box, Route:H3 of 4, 1x15mmØ, H4, 1x30mmØ, Exit: Signals trackside equipment. 2 x 12m					
38656	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	376	379	RHS	Cloth cable sheath. Entry: N/A, Route: Between trackside equipment, H3 & H4, 8mmØ to 30mmØ, Exit: N/A, numerous amounts					
38662	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	379	384	RHS	Cloth cable sheath. Entry: Signals trackside equipment, Route: H3 of 4, 1x8mmØ, 1x15mmØ, H4, 1x30mmØ, Exit: Severed. 3 x 4.5m					
38665	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	384	450	RHS	Cloth cable sheath. Entry: N/A, Route: H3 of 4, 1x15mmØ, H4, 1x30mmØ, Exit: Severed. 2 x 66.5m					
38666	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	450	540	RHS	Cloth cable sheath. Entry: N/A, Route: H4 of 4, 1x30mmØ, Exit: N/A. 1 x 90m					
38668	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	540	673	RHS	Cloth cable sheath. Entry: Spliced, Route: H3 of 4, 1x15mmØ, H4, 1x30mmØ, Exit: Severed. 2 x 133m					
38669	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	576	578	RHS	Cloth cable sheath. 1x30mmØ from H4 spliced & mounted below H4. 1 x2m					



Hazardous Material Asset Register - Summary



P028-P - PIC Line - Turnpike Lane to Manor House

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38670	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	665		RHS	Cloth cable sheath. 1x4mmØ from Westinghouse large box to H1		1			
38672	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	673	836	RHS	Cloth cable sheath. Entry: N/A, Route: H4 of 4, 1x30mmØ, Exit: Signal trackside equipment. 1 x 163m					
38681	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	836	839	RHS	Cloth cable sheath. Entry: N/A, Route: Between trackside equipment, H3 & H4, 8mmØ to 30mmØ, Exit: N/A, numerous amounts					
38686	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	839	1347	RHS	Cloth cable sheath. Entry: Signals trackside equipment, Route: H4 of 4, 1x30mmØ, Exit: Westinghouse large box. 1 x 508m					
38689	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	1072	1074	RHS	Cloth cable sheath. 1x30mmØ from H4 spliced & mounted below H4. 1 x 2m					
40014	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	1347	1647	RHS	Cloth cable sheath. Entry: Westinghouse large box, Route: H4 of 4, 1x30mmØ, Exit: N/A. 1 x 300.5m					
38705	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	1565	1567	RHS	Cloth cable sheath. 1x30mmØ from H4 spliced & mounted below H4. 1 x 2m					
39678	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	1647	1648	RHS	Cloth cable sheath. 2x8mmØ between Westinghouse large box & Westinghouse small box. 2 x 1m					
38708	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	1647	1795	RHS	Cloth cable sheath. Entry: Westinghouse large box, Route: H3 of 4, 1x8mmØ, H4, 1x30mmØ, Exit: Signals trackside equipment. 2 x 148m					
38715	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	1795	1799	RHS	Cloth cable sheath. Entry: N/A, Route: Between trackside equipment, H2, H3 & H4, 4mmØ to 30mmØ, Exit: N/A, numerous amounts					
38720	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	1799	1913	RHS	Cloth cable sheath. Entry: Signals trackside equipment, Route: H3 of 4, 2x8mmØ, H4, 1x30mmØ, Exit: Signals trackside equipment. 3 x 114m					
38723	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	1913	1916	RHS	Cloth cable sheath. Entry: N/A, Route: Between trackside equipment, H2, H3 & H4, 4mmØ to 30mmØ, Exit: N/A. numerous amounts					
38545	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	1916	1995	RHS	Cloth cable sheath. Entry: Signals trackside equipment, Route: H3 of 4, 1x8mmØ, H4, 1x30mmØ, Exit: Signals trackside equipment. 2 x 79m					
38546	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Signal Boxes	Asbestos	Presumed	1916		RHS	Trackside equipment: tencore box		1			



Hazardous Material Asset Register - Summary



P028-P - PIC Line - Turnpike Lane to Manor House

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38549	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	1995	1999	RHS	Cloth cable sheath. Entry: N/A, Route: Between trackside equipment, H3 & H4, 8mmØ to 30mmØ, Exit: N/A, numerous amounts					
38554	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	1999	2060	RHS	Cloth cable sheath. Entry: Signals trackside equipment, Route: H3 of 4, 1x8mmØ, 1x15mmØ, H4, 1x30mmØ, Exit: Westinghouse large box. 3 x 61.5m					
38559	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	2060	2069	RHS	Cloth cable sheath. Entry: Westinghouse small box, Route: H3 of 4, 2x8mmØ, 1x15mmØ, H4, 1x30mmØ, Exit: Westinghouse large box. 4 x 8.5m					
38561	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	2063	2065	RHS	Cloth cable sheath. 1x30mmØ from H4 spliced & mounted below H4. 1 x 2m					
38564	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	2069	2070	RHS	Cloth cable sheath. Entry: N/A, Route: H3 of 4, 1x8mmØ, 1x15mmØ, H4, 1x30mmØ, Exit: N/A. 3 x 1m					
38566	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	2070	2199	RHS	Cloth cable sheath. Entry: Ten Core box Route: H3 of 4, 1x8mmØ, 2x15mmØ, H4, 1x30mmØ, Exit: Platform wall. 4 x 129m					
38755	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Cable Sheath	Asbestos	Strongly Presumed	2193	2195	RHS	Cloth cable sheath. 1x30mmØ from H4 spliced & mounted below H4. 1 x 2m					
39680	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Ducts	Asbestos	Presumed	2197		LHS	cement cable duct lining . Presumed present (In floor, sealed by plaster)		2			
38757	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Ducts	Asbestos	Presumed	2199		LHS	cement cable duct lining . Presumed present (In platform wall, sealed by plaster)		1			
38758	ACTIVE	P	P028-P-EBLO	Road EBLO - PIC - Manor House to Turnpike Lane	Ducts	Asbestos	Presumed	2199		RHS	cement cable duct lining .Presumed present (In platform wall, sealed by plaster)		2			
41560	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Presumed	960		RHS	Trackside equipment: Type 79 box		1			
41561	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Presumed	1102		RHS	Trackside equipment: Mains earth terminal		1			
41562	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1104		RHS	Trackside equipment: westinghouse small box		1			
41563	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1106		RHS	Trackside equipment: westinghouse small box		1			
41564	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1294		RHS	Trackside equipment: westinghouse small box		1			
41565	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Presumed	1307		RHS	Trackside equipment: Signal box (A856)		1			
39582	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	1307	1318	RHS	cloth. cable sheath, Entry: N/A, Route: Between TE, H2, H3 & H4, Exit: N/A (numerous amounts)					



Hazardous Material Asset Register - Summary



P028-P - PIC Line - Turnpike Lane to Manor House

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41566	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1308		RHS	Trackside equipment: westinghouse small box		1			
41568	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1309		RHS	Trackside equipment: westinghouse small box		1			
41567	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Presumed	1309		RHS	Trackside equipment: tencore box		1			
39363	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1312		RHS	Trackside equipment: westinghouse large box		2			
41569	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1314		RHS	Trackside equipment: westinghouse small box		1			
39583	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1314		RHS	Trackside equipment: westinghouse large box		1			
41570	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1315		RHS	Trackside equipment: westinghouse small box		1			
41571	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1315		RHS	Trackside equipment: westinghouse large box		1			
41572	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1316		RHS	Trackside equipment: westinghouse small box		1			
41573	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1316		RHS	Trackside equipment: westinghouse large box		1			
39584	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1317		RHS	Trackside equipment: westinghouse large box		1			
41574	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1317		RHS	Trackside equipment: westinghouse small box		1			
41650	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1318		RHS	Trackside equipment: westinghouse large box Notes from 2022 re-inspection: 2x		2			
41649	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1318		RHS	Trackside equipment: westinghouse small box		1			
41648	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	1318	1352	RHS	cloth. cable sheath, Entry: Signals trackside equipment, Route: H2 of 4, 4x8mmØ, H3, 2x8mmØ, H4, 1x25mmØ, Exit: Westinghouse small box. 7 x 34m					
41651	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	1352	1399	RHS	cloth. cable sheath, Entry: N/A, Route: H2 of 4, 4x8mmØ, H3, 1x8mmØ, H4, 1x25mmØ, Exit: Westinghouse small box. 6 x 47m					
41652	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1352		RHS	Trackside equipment: westinghouse small box		1			
41653	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Presumed	1385		RHS	Trackside equipment: Type 79 box		1			



Hazardous Material Asset Register - Summary



P028-P - PIC Line - Turnpike Lane to Manor House

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41655	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1399		RHS	Trackside equipment: westinghouse small box		1			
41654	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	1399	1503	RHS	cloth. cable sheath, Entry: Westinghouse small box, Route: H2 of 4, 4x8mmØ, H3, 1x8mmØ, H4, 1x25mmØ, Exit: Westinghouse small box. 6 x 104m					
41656	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1418		RHS	Trackside equipment: westinghouse small box		1			
41657	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1436		RHS	Trackside equipment: westinghouse small box		1			
41658	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	1465	1466	RHS	cloth. cable sheath, H4, 1x25mmØ cable spliced & mounted below H4. 1 x 1m					
41660	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1503		RHS	Trackside equipment: westinghouse small box		1			
41659	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	1503	1508	RHS	cloth. cable sheath, Entry: N/A, Route: H2 of 4, 3x8mmØ, H3, 1x8mmØ, H4, 1x25mmØ, Exit: Westinghouse small box. 5 x 5m					
41661	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1508		RHS	Trackside equipment: westinghouse small box		1			
39865	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	1508	1718	RHS	cloth. cable sheath, Entry: N/A, Route: H2 of 4, 2x8mmØ, H3, 1x8mmØ, H4, 1x25mmØ, Exit: Signals trackside equipment, 4 x 110m					
41662	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1545		RHS	Trackside equipment: westinghouse small box		1			
41663	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	1552	1553	RHS	cloth. cable sheath, H4, 1x25mmØ cable spliced & mounted below H4. 1 x 1m					
41664	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1603		RHS	Trackside equipment: westinghouse large box		2			
41665	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1712		RHS	Trackside equipment: westinghouse small box		1			
41666	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	1718	1730	RHS	cloth. cable sheath, Entry: N/A, Route: Between TE, H2, H3 & H4, 8mmØ to 25mmØ, Exit: N/A. numerous amounts					
41667	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Presumed	1718		RHS	Trackside equipment: Signal box (A854)		1			
41668	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1719		RHS	Trackside equipment: westinghouse small box		1			
39610	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Presumed	1720		RHS	Trackside equipment: tencore box		1			



Hazardous Material Asset Register - Summary



P028-P - PIC Line - Turnpike Lane to Manor House

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39367	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1723		RHS	Trackside equipment: westinghouse large box		1			
41669	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1725		RHS	Trackside equipment: westinghouse small box		1			
41670	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Presumed	1725		RHS	Trackside equipment: tencore box		1			
41671	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1725		RHS	Trackside equipment: westinghouse large box		1			
39611	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1726		RHS	Trackside equipment: westinghouse large box		1			
40147	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1727		RHS	Trackside equipment: westinghouse large box		1			
40149	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1728		RHS	Trackside equipment: westinghouse large box		1			
40148	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Presumed	1728		RHS	Trackside equipment: tencore box		1			
40151	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1730		RHS	Trackside equipment: westinghouse large box		1			
40150	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	1730	1750	RHS	cloth. cable sheath, Entry: Signals trackside equipment, Route: H2 of 4, 4x8mmØ, H3, 1x25mmØ, H4, 1x25mmØ, Exit: N/A. 6 x 20.5m					
40152	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1732		RHS	Trackside equipment: westinghouse small box		1			
40153	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	1750	1751	RHS	cloth. cable sheath, Entry: UTX, Route: H2 of 4, 4x8mmØ, H3, 1x25mmØ, H4, 1x25mmØ, below H4, 1x30mmØ, Exit: Westinghouse small box. 7 x1m					
40155	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1751		RHS	Trackside equipment: westinghouse small box		1			
40154	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	1751	1758	RHS	cloth. cable sheath, Entry: N/A, Route: H2 of 4, 3x8mmØ, H3, 1x25mmØ, H4, 1x25mmØ, below H4, 1x30mmØ, Exit: Westinghouse small box. 6 x 7m					
40156	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1758		RHS	Trackside equipment: westinghouse small box		1			
39468	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	1758	1759	RHS	cloth. cable sheath, Entry: N/A, Route: H2 of 4, 2x8mmØ, H3, 1x25mmØ, H4, 1x25mmØ, below H4, 1x30mmØ, Exit: UTX. 5 x 1m					
40157	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	1759	1890	RHS	cloth. cable sheath, Entry: N/A, Route: H2 of 4, 2x8mmØ, H3, 1x25mmØ, H4, 1x25mmØ, Exit: Signals trackside equipment. 4 x 131m					



Hazardous Material Asset Register - Summary



P028-P - PIC Line - Turnpike Lane to Manor House

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40158	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Presumed	1808		RHS	Trackside equipment: Type 79 box		1			
40160	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Presumed	1890		RHS	Trackside equipment: Signal box (R850AB)		1			
40159	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	1890	1896	RHS	cloth. cable sheath, Entry: N/A, Route: Between TE, H2, H3 & H4, 8mmØ to 25mmØ, Exit: N/A. numerous amounts					
40162	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1891		RHS	Trackside equipment: westinghouse small box		1			
40161	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Presumed	1891		RHS	Trackside equipment: Signal box (A854)		1			
40163	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Presumed	1892		RHS	Trackside equipment: tencore box		1			
40164	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1894		RHS	Trackside equipment: westinghouse large box		1			
40165	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1895		RHS	Trackside equipment: westinghouse large box		1			
40166	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	1896	1916	RHS	cloth. cable sheath, Entry: Signals trackside equipment, Route: H2 of 4, 4x8mmØ, H3, 2x25mmØ, H4, 1x25mmØ, Exit: N/A. 7 x 20.5m					
39391	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Presumed	1896		RHS	Trackside equipment: tencore box		1			
40167	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1901		RHS	Trackside equipment: westinghouse small box		1			
40169	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	1916		RHS	Trackside equipment: westinghouse small box		1			
40168	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	1916	1922	RHS	cloth. cable sheath, Entry: Westinghouse small box, Route: H2 of 4, 5x8mmØ, H3, 2x25mmØ, H4, 1x25mmØ, Exit: Westinghouse small box. 8 x6m					
40170	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	1922	2048	RHS	cloth. cable sheath, Entry: N/A, Route: H2 of 4, 4x8mmØ, H3, 2x25mmØ, H4, 1x25mmØ, Exit: Signals trackside equipment. 7 x 125.5m					
39392	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	2048	2051	RHS	cloth. cable sheath, Entry: N/A, Route: Between TE, H2, H3 & H4, 8mmØ to 25mmØ, Exit: N/A. numerous amounts					
40245	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Presumed	2048		RHS	Trackside equipment: Signal box (A850A)		1			
40244	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Presumed	2048		RHS	Trackside equipment: Signal box (R850BC)		1			



Hazardous Material Asset Register - Summary



P028-P - PIC Line - Turnpike Lane to Manor House

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40246	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	2049		RHS	Trackside equipment: westinghouse small box		1			
40247	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Presumed	2049		RHS	Trackside equipment: tencore box		1			
40248	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	2049		RHS	Trackside equipment: westinghouse large box		1			
40249	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	2050		RHS	Trackside equipment: westinghouse large box		1			
40251	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Presumed	2051		RHS	Trackside equipment: tencore box		1			
40250	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	2051	2079	RHS	cloth. cable sheath, Entry: Signal trackside equipment, Route: H2 of 4, 6x8mmØ, H3, 3x25mmØ, H4, 1x25mmØ, Exit: N/A. 10 x 28m					
40252	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	2052	2053	RHS	cloth. cable sheath, H4, 1x25mmØ cable spliced & mounted below H4, 1 x1m					
40253	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	2079	2085	RHS	cloth. cable sheath, Entry: Westinghouse small box, Route: H2 of 4, 7x8mmØ, H3, 3x25mmØ, H4, 1x25mmØ, Exit: Westinghouse small box. 11 x 6m					
40255	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	2079		RHS	Trackside equipment: westinghouse small box		1			
40254	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	2079		RHS	cloth, debris. Cable remains in brackets by cable from Westinghouse small box. 2 x 0.1m					
39470	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	2085	2096	RHS	cloth. cable sheath, Entry: N/A, Route: H2 of 4, 6x8mmØ, H3, 3x25mmØ, H4, 1x25mmØ, Exit: N/A. 10 x 11m					
40257	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	2085		RHS	Trackside equipment: westinghouse small box		1			
40256	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	2085		RHS	cloth, debris. Cable remains in brackets by cable from Westinghouse small box. 2 x 0.1m					
40258	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	2093	2095	RHS	cloth. cable sheath, 2x30mmØ in cleats mounted below H4. 2 x2m					
40260	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Presumed	2096		LHS	Trackside equipment: Rail Gap indicator		1			
40261	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	2096			cloth. cable sheath, Entry: Rail Gap indicator, Route: OTX, 1x8mmØ, Exit: RHS. 1 x4m LHS & OTX					
40259	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	2096	2101	RHS	cloth. cable sheath, Entry: OTX, Route: H2 of 4, 7x8mmØ, H3, 3x25mmØ, H4, 1x25mmØ, Exit: CT. 01. 11 x 5m					
39396	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	2101	2102	RHS	cloth. cable sheath, Entry: N/A, Route: H2 of 4, 7x8mmØ, H3, 3x25mmØ, Exit: N/A. 10 x 1m					



Hazardous Material Asset Register - Summary



P028-P - PIC Line - Turnpike Lane to Manor House

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40266	INACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Removed	2101		LHS	Trackside equipment: westinghouse large box Notes from 2022 re-inspection: Removed		1			
40265	INACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Removed	2101		LHS	cloth. cable sheath, Entry: Overhead shaft, Route: H1 of 1, 1x25mmØ, Exit: Westinghouse large box .1 x 4m Notes from 2022 re-inspection: Removed					
40264	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	2101		LHS	cloth. cable sheath, Entry: Westinghouse large box, Route: H1 of 1, 1x25mmØ, Exit: Overhead shaft. 1 x 2.5m					
40262	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	2101		LHS	cloth. cable sheath, Entry: WB P-Way, Route: along ceiling, 1x25mmØ, Exit: Westinghouse large box. 1 x 5.5m					
40263	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	2101		RHS	Trackside equipment: westinghouse large box		1			
40267	INACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Removed	2101		LHS	cloth. cable sheath, Entry: Westinghouse large box, Route: H1 of 1, 1x25mmØ, Exit: EB P-Way. 1 x 5.5m Notes from 2022 re-inspection: Removed					
39397	INACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Removed	2102	2104	LHS	cloth. cable sheath, Entry: Westinghouse small box & Gap Relay box, Route: H2 of 4, 9x8mmØ, H3, 3x25mmØ, 1x4mmØ, Exit: Westinghouse large box. 1 3 x 2m Notes from 2022 re-inspection: Removed					
40338	INACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cement Cable Troughing & Debris	Asbestos	Removed	2102		LHS	cement cable trough. Leads to gap relay box Notes from 2022 re-inspection: Removed		3			
40340	INACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Removed	2104		RHS	Trackside equipment: westinghouse small box Notes from 2022 re-inspection: Removed		1			
40339	INACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Removed	2104	2111	RHS	cloth. cable sheath, Entry: Westinghouse large box, Route: H2 of 4, 7x8mmØ, H3, 3x25mmØ, 1x4mmØ Exit: Ten Core box. 11 x 6.5m Notes from 2022 re-inspection: Removed					
40342	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Presumed	2111		RHS	Trackside equipment: tencore box		1			



Hazardous Material Asset Register - Summary



P028-P - PIC Line - Turnpike Lane to Manor House

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40341	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	2111	2133	RHS	cloth. cable sheath, Entry: Ten Core box, Route: H2 of 4, 7x8mmØ, H3, 3x25mmØ, 1x4mmØ Exit: Signals trackside equipment. 11 x 22.5m					
40343	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	2133	2139	RHS	cloth. cable sheath, Entry: N/A, Route: Between TE, H2 & H3, 8mmØ to 25mmØ, Exit: N/A. numerous amounts					
40344	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Presumed	2133		RHS	Trackside equipment: Signal box (A850B)		1			
40345	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	2134		RHS	Trackside equipment: westinghouse small box		1			
40346	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Presumed	2135		RHS	Trackside equipment: tencore box		1			
40347	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	2135		RHS	Trackside equipment: westinghouse small box		1			
40348	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	2136		RHS	Trackside equipment: westinghouse small box		1			
40349	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Presumed	2137		RHS	Trackside equipment: tencore box		1			
40350	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	2139	2194	RHS	cloth. cable sheath, Entry: Signals trackside equipment, Route: H2 of 4, 8x8mmØ, H3, 4x25mmØ, Exit: Signals trackside equipment. 12 x 54.5m					
40351	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	2139		RHS	Trackside equipment: westinghouse small box		1			
40352	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Presumed	2193		RHS	Trackside equipment: Signal box (A850C)		1			
40354	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	2194		RHS	Trackside equipment: westinghouse small box		1			
40353	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	2194	2196	RHS	cloth. cable sheath, Entry: N/A, Route: Between TE, H2 & H3, 8mmØ to 25mmØ, Exit: N/A. numerous amounts					
40355	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	2194		RHS	Trackside equipment: westinghouse large box		1			
40356	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Presumed	2195		RHS	Trackside equipment: tencore box		1			
39727	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Presumed	2195		RHS	Trackside equipment: tencore box		1			
39401	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	2196	2215	RHS	cloth. cable sheath, Entry: Signals trackside equipment, Route: H2 of 4, 10x8mmØ, H3, 4x25mmØ, Exit: N/A. 14 x 19m					



Hazardous Material Asset Register - Summary



P028-P - PIC Line - Turnpike Lane to Manor House

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40357	INACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Removed	2196		RHS	Trackside equipment: 630V box Notes from 2022 re-inspection: Removed		1			
40359	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Westinghouse Boxes	Asbestos	Presumed	2215		RHS	Trackside equipment: westinghouse small box		1			
40358	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	2215	2219	RHS	cloth. cable sheath, Entry: Spliced cable & Westinghouse small box, Route: H2 of 4, 11x8mmØ, H3, 4x25mmØ, H4, 1x30mmØ, Exit: Westinghouse small box. 16 x 4m					
39949	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	2215		RHS	cloth. Debris, Cable remains in brackets by cable from Westinghouse small box. 1 x 0.1m					
40360	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Signal Boxes	Asbestos	Presumed	2219		RHS	Trackside equipment: type 79 box		1			
40361	ACTIVE	P	P028-P-WBLO	Road WBLO - PIC - Turnpike Lane to Manor House	Cable Sheath	Asbestos	Strongly Presumed	2219	2221	RHS	cloth. cable sheath, Entry: N/A, Route: H2 of 4, 10x8mmØ, H3, 4x25mmØ, H4, 1x30mmØ Exit: Platform. 15 x 4m					

P029-P - PIC Line - Manor House Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42765	ACTIVE	P	P029-P-EBLO	Road EBLO (Plt1) - PIC - Manor House Stn	Pit Blocks	Asbestos	Surveyed – Not Detected				Pit blocks - Non asbestos					
42766	ACTIVE	P	P029-P-WBLO	Road WBLO (Plt2) - PIC - Manor House Stn	Pit Blocks	Asbestos	Surveyed – Not Detected				Pit blocks - Non asbestos					

P032-P - PIC Line - Manor House to Finsbury Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37618	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Cable Sheath	Asbestos	Presumed	4		RHS	Braided Cable. J hangers 1=0, J hanger 2=0. J hanger 3=1x20mm , J hanger 4=0		1			
46164	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Cable Sheath	Asbestos	Known	5		RHS	Approx x 4 un-encapsulated braided cable right hand side to signal cabin BRS 5. (BRS location not provided in report location added is an approximate)		4			
37619	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	12		LHS	Flash guards for Signal A841		1			
37621	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Cable Sheath	Asbestos	Presumed	15	17	RHS	Braided Cable. Between switch boxes 10x 10mm cables		10			



Hazardous Material Asset Register - Summary



P032-P - PIC Line - Manor House to Finsbury Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37620	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	15	17	RHS	Flash guards Switch boxes. Switch box 853gr, 839 bTR, 841aTR Notes from 2022 re-inspection: Plus 3x SWH		6			
37622	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	18		RHS	Flash guard Signal break box Notes from 2022 re-inspection: 2x SWH		2			
37623	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	21		RHS	Flash guard Signal break box		1			
37624	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	26		RHS	Flash guard Signal break box		1			
39600	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	43	45	RHS	Flashguards for switch boxes. Switch boxes 839, 839ab, 839b		3			
37625	INACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Track Section Switches	Asbestos	Removed	46	48	RHS	Asbestos Cement. Current trail section switches 367 & 367A Notes from 2022 re-inspection: Cement removed		1			
37626	INACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Cement Cable Troughing & Debris	Asbestos	Removed	47		RHS	Asbestos Cement. Cable troughing Notes from 2022 re-inspection: Removed		2			
37627	INACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Cement Cable Troughing & Debris	Asbestos	Removed	48		RHS	Asbestos Cement. Cable troughing Notes from 2022 re-inspection: Removed		2			
37628	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	80		RHS	Flash guard Signal break box		1			
37629	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	85		RHS	Flash guard Signal break box		1			
37630	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	110		RHS	Flash guard Signal break box		1			
37632	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Cable Sheath	Asbestos	Presumed	199		RHS	Braided Cable. Cable from signal to J hanger 3 (1x5mm)		1			
37631	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	199		RHS	Flash guards for Signal A4811 & R843		2			
37633	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	202	206	RHS	Flash guards to Switch box 8411GR, 843 PGR, 841 bTR, 841AT		5			
37634	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Cable Sheath	Asbestos	Presumed	203	205	RHS	Braided Cable. 8x10mm Cables between switch boxes via J hanger 2		8			
39823	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Cable Sheath	Asbestos	Presumed	205		RHS	Braided Cable. 3x 10mm Cables from switch box via J hanger 2 to box on BRS 208		3			
37635	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Cable Sheath	Asbestos	Presumed	208		RHS	Braided Cable. J hanger 1=0, J hanger 2=1x10mm, J hanger 3=2x20mm, J hanger 4 = 0		3			



Hazardous Material Asset Register - Summary



P032-P - PIC Line - Manor House to Finsbury Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37636	ACTIVE	p	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	267		RHS	Flash guard Signal break box		1			
37637	ACTIVE	p	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	373		RHS	Flash guards from Signal A843		1			
37638	ACTIVE	p	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	376		RHS	Flashguards for 843GR		1			
37639	ACTIVE	p	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	377		RHS	Flash guard Signal break box Notes from 2022 re-inspection: EP valve		1			
39759	ACTIVE	p	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	377		RHS	Flashguards for 841CTR		1			
39824	ACTIVE	p	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	380		RHS	Flash guard Signal break box		1			
37640	ACTIVE	p	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	381		RHS	Flash guard Signal break box		1			
37641	ACTIVE	p	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Cable Sheath	Asbestos	Presumed	387		RHS	Braided Cable. Cross passage 37 J hanger No 3 1x10mm Cable towards vent shaft		1			
37642	ACTIVE	p	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	474		RHS	Flash guard Signal break box		1			
37643	ACTIVE	p	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	539		RHS	Flash guards for Signal R849ab		1			
39825	ACTIVE	p	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	540	543	RHS	Flash guards Switch box 849abPGR, 843aTR, 843aTH, 841cTH, 841c		5			
37644	ACTIVE	p	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	541		RHS	Flash guard Signal break box		1			
37645	ACTIVE	p	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Cable Sheath	Asbestos	Presumed	541		RHS	Braided Cable. 2x 10mm Cables running from break signal box to switch box 843aTR		2			
37646	ACTIVE	p	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	573		RHS	Flash guard Signal break box		1			
37647	ACTIVE	p	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	574		RHS	Flash guard Signal break box		1			
37648	ACTIVE	p	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	610		RHS	Flash guard Signal break box		1			
37649	ACTIVE	p	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	672		RHS	Flash guards for Signal Signal R849 abcPGR		1			
37650	ACTIVE	p	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	673		RHS	Flash guards for Switch Box 849abcPGR		1			
37651	ACTIVE	p	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	712		RHS	Flash guards for Signal A84 9A		1			



Hazardous Material Asset Register - Summary



P032-P - PIC Line - Manor House to Finsbury Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37652	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	715		RHS	Flash guards for Switch Box box 849AGR		1			
37653	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	716		RHS	Flash guard Signal break box		1			
37654	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	721		RHS	Flash guard Signal break box		1			
37655	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	728		RHS	Flash guard Signal break box		1			
37656	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	780		RHS	Flash guards for Signal A849b		1			
37657	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	783		RHS	Flash guards for Switch box 849bGR		1			
37658	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	786		RHS	Flash guard Signal break box		1			
37659	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	789		RHS	Flash guard Signal break box		1			
37660	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	793		RHS	Flash guard Signal break box		1			
39760	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	794		RHS	Flash guard Signal break box		1			
37661	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	852		RHS	Flash guards for Signal A849c		1			
39866	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	855		RHS	Flash guards for Switch box 849cGR		1			
37662	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	858		RHS	Flash guard Signal break box					
37663	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	863		RHS	Flash guard Signal break box					
37664	INACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Removed	921		RHS	Flash guard Signal break box Notes from 2022 re-inspection: Removed					
37665	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	922		RHS	Flash guard Signal break box					
37666	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Signal Boxes	Asbestos	Presumed	926		RHS	Flash guard Signal break box					
39867	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Cable Sheath	Asbestos	Presumed	930		RHS	Braided Cables.1x 40mm cable from joint to J hanger No 4		1			
37667	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Cable Sheath	Asbestos	Presumed	932		RHS	Braided Cables.1x 10mm redundant cable from J hanger No 2		1			



Hazardous Material Asset Register - Summary



P032-P - PIC Line - Manor House to Finsbury Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37668	ACTIVE	P	P032-P-EBLO	Road EBLO - PIC - Finsbury Park to Manor House	Ducts	Asbestos	Sampled – Not Detected	932		LHS	bitumen ducts to UTX					
39964	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Cable Sheath	Asbestos	Presumed	1		RHS	Braided Cables. J hanger 1 = 0, J hanger 2 = 6x 10mm, J hanger 3 = 1x 20mm & 1x30mm, J hanger 4 = 1x50mm		9			
38364	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Ducts	Asbestos	Sampled – Not Detected	2		LHS	Bitumen ducts					
38365	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	8		RHS	Flash guards in Signal box A848		1			
54021	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Other Electrical Boxes	Asbestos	Presumed	9		RHS	Flash guards in signal box A848GR Notes from 2022 re-inspection: Present		1			
38366	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Cable Sheath	Asbestos	Presumed	9		RHS	Braided Cables. J hanger 2 = 1x 30mm & J hanger 3 = 2x 10mm cables from hangers to switch box		3			
38367	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Cable Sheath	Asbestos	Presumed	10		RHS	Braided Cables. J hangers 2&3 = 9x10mm cables from hangers to switch boxes		9			
38368	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	11		RHS	Flash guards in signal break box					
38369	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Cable Sheath	Asbestos	Presumed	11		RHS	Braided Cables. J hanger 3=2x 10mm cables from hanger to signal box		2			
38569	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	14		RHS	Flash guards in signal break box		1			
38570	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	16		RHS	Flash guards in signal break box		1			
38571	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	17		RHS	Flash guards in signal break box		1			
38573	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Cable Sheath	Asbestos	Presumed	78		RHS	Braided Cables.J hanger 2=1x 10mm cable from hanger to signal box		1			
38572	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	78		RHS	Flash guards in signal break box		1			
38574	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	81		RHS	Flash guards in signal break box		1			
38575	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Cable Sheath	Asbestos	Presumed	81		RHS	Braided Cables. J hanger 2= 2x 10mm cable from haner to signal box		2			
38576	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	165		RHS	Flash guards in signal break box		1			
38577	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	190		RHS	Flash guards in signal break box		1			



Hazardous Material Asset Register - Summary



P032-P - PIC Line - Manor House to Finsbury Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38578	INACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Removed	249		RHS	Flash guards from Signal A846 Notes from 2022 re-inspection: Removed		1			
38579	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	279			asbestos cement, Flash guards for Signal R846		1			
38580	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	280		RHS	Flash guards fro switch box 846PGR		1			
38581	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	281		RHS	Flash guards for switch box 848TR		1			
38582	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	282		RHS	Flash guards in signal break box		1			
38584	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	292		RHS	Flash guards in signal break box		1			
39842	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	293		RHS	Flash guards in signal break box		1			
38585	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	352		RHS	Flash guards in signal break box		1			
38586	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	427		RHS	Flash guards from Signal A846		1			
38587	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	428	432	RHS	Switch boxes. Switch boxes 846GR, 848CTR, 848BTH, 848BT		5			
40003	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	440		RHS	Flash guards in signal break box		1			
38588	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	443		RHS	Flash guards in signal break box		1			
38589	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	447		RHS	Flash guards in signal break box		1			
38590	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	518		RHS	Flash guards in signal break box		1			
38591	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	557		RHS	Flash guards in signal break box		1			
40004	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	560		RHS	Flash guards for Signal R840		1			
38592	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	565		RHS	Asbestos Cement. Flash guards fro Switch box 840PGR					
38593	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	581		RHS	Flash guards in signal break box		1			
38594	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	585		RHS	Flash guards in signal break box		1			



Hazardous Material Asset Register - Summary



P032-P - PIC Line - Manor House to Finsbury Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39455	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	586	589	RHS	Flash guards in switch boxes. Switch box 847TR, 846T, 848T, 864T		4			
38595	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	587		RHS	Flash guards in signal break box		1			
40005	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	589		RHS	Flash guards in signal break box		1			
38596	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	590		RHS	Flash guards in signal break box Notes from 2022 re-inspection: 2x SWH		1			
38598	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	647		RHS	Flash guards For Signal VK9 R840		1			
38597	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Removed	648		RHS	Flash guards in signal break box Notes from 2022 re-inspection: Removed		1			
38599	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	650		RHS	Switch boxes, Switch box 846TR, 846T, 848T, 846TH		3			
39674	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	652		RHS	Flash guards in signal break box		1			
38600	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	654		RHS	Flash guards in signal break box Notes from 2022 re-inspection: 2x SWH		1			
38601	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	727		RHS	Flash guards in signal break box		1			
38602	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Cable Sheath	Asbestos	Known	728			Rolled steel joist woven cable (3 no.), to left hand side of high level tunnel ring within bolt hole.		3			
38603	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	744		RHS	Flash guards in signal A840		1			
38604	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	746		RHS	Flash guards in switch box 840		1			
38605	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	768	771	RHS	Flash guards in switch boxes. Switch box 846 BTH, 846BT, 846CT, 846CTH		4			
38606	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	775		RHS	Flash guards in signal break box		1			
38607	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	777		RHS	Flash guards in signal break box		1			
38608	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	780		RHS	Flash guards in signal break box		1			
38609	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	816		RHS	Flash guards in signal break box		1			



Hazardous Material Asset Register - Summary



P032-P - PIC Line - Manor House to Finsbury Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38610	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	816		RHS	Flash guards in Signal A840B		1			
38611	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	818		RHS	Switch box 840BGR		1			
38612	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	820		RHS	Flash guards in signal break box		1			
38613	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	821		RHS	Flash guards in signal break box		1			
39843	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	880		RHS	Flash guards in Signal VK9		1			
40006	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	883		RHS	Flash guards in switch boc VK9GR		1			
38614	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	913		RHS	Flash guards in signal break box		1			
38615	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	918		RHS	Flash guards in signal break box		1			
38616	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Signal Boxes	Asbestos	Presumed	928		RHS	Flash guards in Switch box		1			
46176	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Cable Sheath	Asbestos	Known	930		LHS	Approx x 7 un-encapsulated braided cable from tunnel wall into signal cabin, left hand side. Approx 930 BRS		7			
38617	ACTIVE	P	P032-P-WBLO	Road WBLO - PIC - Manor House to Finsbury Park	Ducts	Asbestos	Known	930		LHS	bitumen ducts to UTX		6			

P041-P - PIC Line - Finsbury Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37669	ACTIVE	P	P041-P-EBLO	Road EBLO (Plt1) - PIC - Finsbury Park Stn	Ducts	Asbestos	Sampled – Not Detected	0			bitumen ducts to invert					
37670	ACTIVE	P	P041-P-EBLO	Road EBLO (Plt1) - PIC - Finsbury Park Stn	Cement Cable Troughing & Debris	Asbestos	Sampled – Not Detected	0			concrete nosing					
42737	ACTIVE	P	P041-P-EBLO	Road EBLO (Plt1) - PIC - Finsbury Park Stn	Pit Blocks	Asbestos	Surveyed – Not Detected				Pit blocks - Non asbestos					
43857	ACTIVE	P	P041-P-WBLO	Road WBLO (Plt3) - PIC - Finsbury Park Stn		Asbestos	Sampled – Not Detected				Braided cables, 2 no, behind brick wall on RHS at Platform 3 Northbound Invert on Piccadilly Line			R492026	N	N
42738	ACTIVE	P	P041-P-WBLO	Road WBLO (Plt3) - PIC - Finsbury Park Stn	Pit Blocks	Asbestos	Surveyed – Not Detected				Pit blocks - Non asbestos					



Hazardous Material Asset Register - Summary



P042-P - PIC Line - Finsbury Park to Arsenal

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36647	ACTIVE	P	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Cable Sheath	Asbestos	Presumed	0		RHS	Braided cable. J hanger 1= 1 x 20mm, J hanger 2=0, J hanger 3= 0, J hanger 4=1 x 20mm		2			
36646	ACTIVE	P	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Ducts	Asbestos	Sampled – Not Detected	0		LHS	Bitumen ducts					
36648	ACTIVE	P	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Signal Boxes	Asbestos	Presumed	1		RHS	Flash guard Signal A831		1			
40305	ACTIVE	P	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Signal Boxes	Asbestos	Presumed	5		RHS	Flash guard Switch box		1			
36649	ACTIVE	P	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Signal Boxes	Asbestos	Presumed	16			Flash guard Signal break box		1			
36650	ACTIVE	P	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Signal Boxes	Asbestos	Presumed	21			Flash guard Signal break box		1			
39651	ACTIVE	P	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Signal Boxes	Asbestos	Presumed	37			Flash guard Signal break box		1			
36827	ACTIVE	P	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Signal Boxes	Asbestos	Presumed	62			Flash guard Signal break box		1			
36828	ACTIVE	P	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Signal Boxes	Asbestos	Presumed	63			Flash guard Signal break box		1			
36829	ACTIVE	P	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Signal Boxes	Asbestos	Presumed	217		RHS	Flash guard Signal RVK1		1			
39553	ACTIVE	P	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Signal Boxes	Asbestos	Presumed	218		RHS	Flash guard Switch box 1PGR		1			
36830	ACTIVE	P	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Cable Sheath	Asbestos	Presumed	218			Braided cable. Cable from J hanger 2 into single 5 core Braided cable		1			
36831	ACTIVE	P	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Signal Boxes	Asbestos	Presumed	220		RHS	Flash guard Switch box		1			
36832	ACTIVE	P	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Signal Boxes	Asbestos	Presumed	226			Flash guard Signal break box		1			
36833	ACTIVE	P	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Signal Boxes	Asbestos	Presumed	231			Flash guard Signal break box		1			
36834	ACTIVE	P	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Signal Boxes	Asbestos	Presumed	292		RHS	Flash guard Signal VK1, RVK2		2			
36835	ACTIVE	P	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Signal Boxes	Asbestos	Presumed	294	296	RHS	Flash guard Switch boxes 2PGR & 1GR		3			
36836	ACTIVE	P	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Signal Boxes	Asbestos	Presumed	298	300	RHS	Flash guard Switch boxes 843 CT, 831CTR		4			
36837	ACTIVE	P	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Signal Boxes	Asbestos	Presumed	301		RHS	Flash guard Switch box		1			



Hazardous Material Asset Register - Summary



P042-P - PIC Line - Finsbury Park to Arsenal

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36838	ACTIVE	p	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Signal Boxes	Asbestos	Presumed	410		RHS	Flash guard Signals VK2 & R839 A		2			
39661	ACTIVE	p	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Cable Sheath	Asbestos	Presumed	412		RHS	Braided cable. 2 x 20mm & 6 x 10mm cables from hangers to 2 No single 5 core boxes and 2 x 10mm out of core up to hangers		8			
36839	ACTIVE	p	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Signal Boxes	Asbestos	Presumed	413		RHS	Flash guard Switch box 2GR		1			
36840	ACTIVE	p	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Signal Boxes	Asbestos	Presumed	414	416	RHS	Flash guard Switch boxes		2			
36841	ACTIVE	p	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Signal Boxes	Asbestos	Presumed	490		LHS	Flash guard Signal A839A		1			
36842	ACTIVE	p	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Signal Boxes	Asbestos	Presumed	492		RHS	Flash guard Switch box		1			
36843	ACTIVE	p	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Signal Boxes	Asbestos	Presumed	499		RHS	Signal R389 A Flash guard		1			
40395	ACTIVE	p	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Signal Boxes	Asbestos	Presumed	500		RHS	Flash guard Switch box 839BPGR		1			
36844	ACTIVE	p	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Signal Boxes	Asbestos	Presumed	566		RHS	Flash guard Signal A839B		1			
36845	ACTIVE	p	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Signal Boxes	Asbestos	Presumed	567		RHS	Flash guard Switch box 839bgr		1			
36846	ACTIVE	p	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Cable Sheath	Asbestos	Presumed	589		RHS	Braided cable Cables on J hangers		2			
36847	ACTIVE	p	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Ducts	Asbestos	Sampled – Not Detected	590		LHS	Bitumen ducts					
36848	ACTIVE	p	P042-P-EBLO	Road EBLO - PIC - Arsenal to Finsbury Park	Signal Boxes	Asbestos	Presumed	591		LHS	Flash guard Switch box		1			
37616	ACTIVE	p	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Cable Sheath	Asbestos	Presumed				Vent VP116A Braided Cable. 1x 10ml left hand side cable run		1			
37617	ACTIVE	p	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Signal Boxes	Asbestos	Presumed				Vent VP116A bottom of emergency exit - Flash guard Switch box		1			
39810	ACTIVE	p	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Signal Boxes	Asbestos	Presumed	6			Flash guard Signal break box		1			
39410	ACTIVE	p	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Signal Boxes	Asbestos	Presumed	7			Flash guard Signal break box		1			
37411	ACTIVE	p	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Signal Boxes	Asbestos	Presumed	12			Flash guard Signal break box		1			
37412	ACTIVE	p	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Cable Sheath	Asbestos	Presumed	13			Braided Cable. J hanger 1= 3x 30ml, 5x 10ml, J hanger 2=1x, 30ml, 1x 20ml, 5x 10ml, J hanger 3= 1x 40 ml, 1x 30 ml, 1x 20ml, 2x 10ml		19			



Hazardous Material Asset Register - Summary



P042-P - PIC Line - Finsbury Park to Arsenal

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37414	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Ducts	Asbestos	Sampled – Not Detected	14		RHS	bitumen ducts		8			
37413	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Cable Sheath	Asbestos	Presumed	14		LHS	Braided Cable. From j hanger 4 1x 3 0ml, 2x 20ml, 2x 10ml, running along left hand side cable run		5			
39811	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Cable Sheath	Asbestos	Presumed	14		LHS	Braided Cable. Cables from j hanger 1 & j hanger 2 over OTX to right hand side cable run		5			
37415	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Signal Boxes	Asbestos	Presumed	17			Flash guard Signal break box		1			
37416	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Signal Boxes	Asbestos	Presumed	20	27		Flash guard Signal break box		7			
39594	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Signal Boxes	Asbestos	Presumed	20			Flash guard Signal break box		1			
37417	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Cable Sheath	Asbestos	Presumed	24			Braided Cable. 2x 10ml, 1x 20ml from j hanger to switch box		3			
37589	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Cable Sheath	Asbestos	Presumed	26			Braided Cable. 2x 10ml from j hanger 4 to signal break box		2			
37590	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Signal Boxes	Asbestos	Presumed	69			Flash guard Signal break box		1			
37591	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Signal Boxes	Asbestos	Presumed	70			Flash guard Signal break box		1			
37592	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Cable Sheath	Asbestos	Presumed	70		LHS	Braided Cable. Left hand side cables go up to high level gantry					
39413	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Cable Sheath	Asbestos	Presumed	111		RHS	Braided Cable. 2x 20ml crossing passage and heading down right hand side cable run onto j hanger 4		2			
37593	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Cable Sheath	Asbestos	Presumed	111		RHS	Braided Cable. Right hand side cable run running into crosspassage towards VIC line					
37594	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Signal Boxes	Asbestos	Removed	115			Flash guards Switch boxes Notes from 2022 re-inspection: Removed		1			
37595	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Cable Sheath	Asbestos	Presumed	116		RHS	Braided Cable. Cable from high level gantry across to right hand side cable run j hanger 1= 1x 10ml		1			
37596	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Signal Boxes	Asbestos	Presumed	125			Flash guards Switch boxes		1			
39758	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Signal Boxes	Asbestos	Presumed	126			Flash guards Switch boxes		1			
37597	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Cable Sheath	Asbestos	Presumed	126		LHS	Braided Cable. J hanger 1= 1x10ml, J hanger 2= 2x 20ml, J hangers 3 & 4=0		3			
37598	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Signal Boxes	Asbestos	Presumed	129			Flash guard Signal break box		1			



Hazardous Material Asset Register - Summary



P042-P - PIC Line - Finsbury Park to Arsenal

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37599	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Signal Boxes	Asbestos	Presumed	288		RHS	Flash guard Signal break lights box right hand side		1			
37600	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Signal Boxes	Asbestos	Presumed	326		LHS	Flash guard Signal R830A left hand side		1			
37601	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Signal Boxes	Asbestos	Presumed	327		LHS	Flash guards Switch boxes		1			
37602	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Signal Boxes	Asbestos	Presumed	328		LHS	Flash guards Switch boxes		1			
37603	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Signal Boxes	Asbestos	Presumed	333		LHS	Flash guard Signal break box		1			
46160	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Cable Sheath	Asbestos	Known	355			2x14mm braided cable right side J-Hanger second from top	14	2			
46159	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Cable Sheath	Asbestos	Known	355			1x16mm braided cable right side J-Hanger top J-Hanger	16	1			
37604	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Ducts	Asbestos	Sampled – Not Detected	382			bitumen ducts LHS/RHS		4			
37606	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Signal Boxes	Asbestos	Presumed	390	391	LHS	Flash guard Signals R830B & A830A		2			
37605	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Signal Boxes	Asbestos	Presumed	391			Flash guard Signal break box		1			
37607	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Signal Boxes	Asbestos	Presumed	392			Flash guards Switch boxes		1			
37608	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Signal Boxes	Asbestos	Presumed	394			Flash guards Switch boxes		1			
46161	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Cable Sheath	Asbestos	Known	400			Cable top J-Hanger clear after vent shaft					
46162	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Cable Sheath	Asbestos	Removed	410			3x10mm braided cable. 2x Westinghouse earth on bottom of J-hanger right side after vent shaft Notes from 2022 re-inspection: Removed	10	3			
39821	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Signal Boxes	Asbestos	Presumed	427			Flash guard Signal break box		1			
46163	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Cable Sheath	Asbestos	Known	466			3x10mm braided cable. 1x Westinghouse Box cables running from box to bottom J-Hanger	10	3			
37609	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Cable Sheath	Asbestos	Presumed	467		LHS	Braided Cable. 1x 10ml from switch box GR830B onto j hanger 3 towards tunnel mouth		1			
37610	ACTIVE	P	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Signal Boxes	Asbestos	Presumed	468			Flash guards Switch boxes		1			



Hazardous Material Asset Register - Summary



P042-P - PIC Line - Finsbury Park to Arsenal

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37611	ACTIVE	p	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Signal Boxes	Asbestos	Presumed	470			Flash guard Signal A830B		1			
37612	ACTIVE	p	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Signal Boxes	Asbestos	Presumed	483			Flash guard Signal break box		1			
37613	ACTIVE	p	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Cable Sheath	Asbestos	Presumed	527			Braided Cable. 1x 20ml goes from j hanger 3 to j hanger 2		1			
39822	ACTIVE	p	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Cable Sheath	Asbestos	Presumed	589			Braided Cable. 1x 40ml from tunnel ring to j hanger 4 into relay room		1			
37614	ACTIVE	p	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Signal Boxes	Asbestos	Presumed	591			Flash guard Signal break box Notes from 2022 re-inspection: 3 no		3			
37615	ACTIVE	p	P042-P-WBLO	Road WBLO - PIC - Finsbury Park to Arsenal	Cable Sheath	Asbestos	Presumed	592			Braided Cable. J hanger 1= 1x20ml, J hanger 2= 1x 20ml, J hanger 3=0, J hanger 4= 1x 40ml		3			

P043-P - PIC Line - Arsenal Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42779	ACTIVE	p	P043-P-EBLO	Road EBLO (Plt1) - PIC - Arsenal Stn	Pit Blocks	Asbestos	Removed				Pit blocks - Non asbestos					
42780	ACTIVE	p	P043-P-WBLO	Road WBLO (Plt2) - PIC - Arsenal Stn	Pit Blocks	Asbestos	Removed				Pit blocks - Confirmed asbestos pit block was removed by DCUK ES11160 19/03/2019					
41608	ACTIVE	p	P043-P-WBLO	Road WBLO (Plt2) - PIC - Arsenal Stn	Ducts	Asbestos	Sampled – Not Detected	2			Bitumen Ducts					
36870	ACTIVE	p	P043-P-WBLO	Road WBLO (Plt2) - PIC - Arsenal Stn	Ducts	Asbestos	Sampled – Not Detected	2			bitumen ducts					

P044-P - PIC Line - Arsenal to Holloway Road

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38110	ACTIVE	p	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Cable Sheath	Asbestos	Presumed	0			Braided Cables. J hanger 1=1x30mm, J hanger 2=0, J hanger 3=1x20mm, J hanger 4=0		2			
38087	ACTIVE	p	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Ducts	Asbestos	Known	0		LHS	Bitumen ducts		3			
38088	ACTIVE	p	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Cable Sheath	Asbestos	Presumed	0			Braided Cables. J hanger 1=0, J hanger 2=0, J hanger 3=1x30mm, J hanger 4=1x 20mm R TO LHS		2			
38089	ACTIVE	p	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Signal Boxes	Asbestos	Presumed	12		RHS	Flash guards for Signal break box		1			
38090	ACTIVE	p	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Signal Boxes	Asbestos	Presumed	15		RHS	Flash guards for Signal A821		1			



Hazardous Material Asset Register - Summary



P044-P - PIC Line - Arsenal to Holloway Road

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38092	ACTIVE	P	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Cable Sheath	Asbestos	Presumed	16		RHS	Braided Cables. 1x 30mm cable from J hanger to switch box 821GR					
38091	ACTIVE	P	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Signal Boxes	Asbestos	Presumed	16		RHS	Flash guards for Switch box 821GR		1			
38093	ACTIVE	P	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Signal Boxes	Asbestos	Presumed	20		RHS	Flash guards for Signal break box		1			
38094	ACTIVE	P	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Signal Boxes	Asbestos	Presumed	24		RHS	Flash guards for Signal break box		1			
39919	ACTIVE	P	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Signal Boxes	Asbestos	Presumed	29		RHS	Flash guards for Signal break box		1			
39637	ACTIVE	P	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Signal Boxes	Asbestos	Presumed	34		RHS	Flash guards for Signal break box		1			
38095	ACTIVE	P	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Cement Cable Troughing & Debris	Asbestos	Presumed	38		LHS	Asbestos Cement. Cable troughing		1			
38096	ACTIVE	P	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Signal Boxes	Asbestos	Presumed	40	44	RHS	Flash guards for Switch boxes x5		5			
38097	ACTIVE	P	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Signal Boxes	Asbestos	Presumed	80		RHS	Flash guards for Signal break box		1			
38098	ACTIVE	P	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Signal Boxes	Asbestos	Presumed	82		RHS	Flash guards for Signal break box		1			
39920	ACTIVE	P	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Signal Boxes	Asbestos	Presumed	457	458	RHS	Flash guards for Signals R829 b & a829A x2		2			
38099	ACTIVE	P	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Signal Boxes	Asbestos	Presumed	459	461		Flash guards Switch box 829aGR & 829 bPGR x2		2			
38100	ACTIVE	P	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Cable Sheath	Asbestos	Presumed	460			Braided Cables. 1 x 30mm from switch box 829aGR onto J hanger 2 to Arsenal		1			
38101	ACTIVE	P	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Signal Boxes	Asbestos	Presumed	488		RHS	Flash guards for Signal break box		1			
39638	ACTIVE	P	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Signal Boxes	Asbestos	Presumed	493		RHS	Flash guards for Signal break box		1			
38102	ACTIVE	P	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Signal Boxes	Asbestos	Presumed	545			Flash guards Signal A829b		1			
38103	ACTIVE	P	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Signal Boxes	Asbestos	Presumed	546			Flash guards Switch box 829bGR		1			
38104	ACTIVE	P	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Signal Boxes	Asbestos	Presumed	554		RHS	Flash guards for Signal break box		1			
38105	ACTIVE	P	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Signal Boxes	Asbestos	Presumed	559		RHS	Flash guards for Signal break box		1			



Hazardous Material Asset Register - Summary



P044-P - PIC Line - Arsenal to Holloway Road

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38106	ACTIVE	P	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Signal Boxes	Asbestos	Removed	616		RHS	Flash guards for Signal break box Notes from 2022 re-inspection: Removed		1			
38107	ACTIVE	P	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Signal Boxes	Asbestos	Presumed	618		RHS	Flash guards for Signal break box		1			
38108	ACTIVE	P	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Signal Boxes	Asbestos	Presumed	621		RHS	Flash guards for Signal break box		1			
38111	ACTIVE	P	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Cable Sheath	Asbestos	Presumed	630		RHS	Asbestos cement. Sheeting, Within hole of steel tunnel lining		1			
38109	ACTIVE	P	P044-P-EBLO	Road EBLO - PIC - Holloway Road to Arsenal	Signal Boxes	Asbestos	Presumed	633		RHS	Flash guards for Signal break box		1			
40396	ACTIVE	P	P044-P-WBLO	Road WBLO - PIC - Arsenal to Holloway Road	Cable Sheath	Asbestos	Presumed	0		RHS	Braided Cables. J hanger 1 = 0, J hanger 2 = 2x 20mm, J hnager 3=0, J hanger 4=0		2			
36849	ACTIVE	P	P044-P-WBLO	Road WBLO - PIC - Arsenal to Holloway Road	Signal Boxes	Asbestos	Presumed	8		RHS	Flashguards for Signal A828		1			
36850	ACTIVE	P	P044-P-WBLO	Road WBLO - PIC - Arsenal to Holloway Road	Signal Boxes	Asbestos	Presumed	9		RHS	Flash guards for switch box 828 GR		1			
36851	ACTIVE	P	P044-P-WBLO	Road WBLO - PIC - Arsenal to Holloway Road	Cable Sheath	Asbestos	Presumed	9		RHS	Braided Cables. 3x 10mm cable from switch box 828G onto J hanger 1 then terminates		3			
36852	ACTIVE	P	P044-P-WBLO	Road WBLO - PIC - Arsenal to Holloway Road	Signal Boxes	Asbestos	Presumed	11		RHS	Flash guards for Signal break box		1			
36853	ACTIVE	P	P044-P-WBLO	Road WBLO - PIC - Arsenal to Holloway Road	Signal Boxes	Asbestos	Presumed	13		RHS	Flash guards for Signal break box		1			
40397	ACTIVE	P	P044-P-WBLO	Road WBLO - PIC - Arsenal to Holloway Road	Signal Boxes	Asbestos	Presumed	18		RHS	Flash guards for Signal break box		1			
36854	ACTIVE	P	P044-P-WBLO	Road WBLO - PIC - Arsenal to Holloway Road	Signal Boxes	Asbestos	Presumed	75		RHS	Flash guards for Signal break box		1			
36855	ACTIVE	P	P044-P-WBLO	Road WBLO - PIC - Arsenal to Holloway Road	Signal Boxes	Asbestos	Presumed	76		RHS	Flash guards for Signal break box		1			
39554	ACTIVE	P	P044-P-WBLO	Road WBLO - PIC - Arsenal to Holloway Road	Signal Boxes	Asbestos	Presumed	159		RHS	Flash guards for Signal break box		1			
36858	ACTIVE	P	P044-P-WBLO	Road WBLO - PIC - Arsenal to Holloway Road	Cable Sheath	Asbestos	Presumed	408		RHS	Braided Cables. 3x 10mm cable from boxes onto J hanger 2 towards Holloway Road		3			
36856	ACTIVE	P	P044-P-WBLO	Road WBLO - PIC - Arsenal to Holloway Road	Signal Boxes	Asbestos	Presumed	408		LHS	Flash guards for Signal A820a		1			
36857	ACTIVE	P	P044-P-WBLO	Road WBLO - PIC - Arsenal to Holloway Road	Signal Boxes	Asbestos	Presumed	408		RHS	Flashguards for Switch box 802aGR		1			
36859	ACTIVE	P	P044-P-WBLO	Road WBLO - PIC - Arsenal to Holloway Road	Signal Boxes	Asbestos	Removed	410		RHS	Flash guards for Signal break box Notes from 2022 re-inspection: Removed		1			



Hazardous Material Asset Register - Summary



P044-P - PIC Line - Arsenal to Holloway Road

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36860	ACTIVE	p	P044-P-WBLO	Road WBLO - PIC - Arsenal to Holloway Road	Signal Boxes	Asbestos	Presumed	448		RHS	Flash guards for Signal break box		1			
36861	ACTIVE	p	P044-P-WBLO	Road WBLO - PIC - Arsenal to Holloway Road	Signal Boxes	Asbestos	Presumed	454		RHS	Flash guards for Signal break box		1			
36862	ACTIVE	p	P044-P-WBLO	Road WBLO - PIC - Arsenal to Holloway Road	Signal Boxes	Asbestos	Presumed	528		LHS	Flash guards for Signal A820b		1			
36863	ACTIVE	p	P044-P-WBLO	Road WBLO - PIC - Arsenal to Holloway Road	Signal Boxes	Asbestos	Presumed	528		RHS	Flash guards for Switch box 820bGR		1			
39662	ACTIVE	p	P044-P-WBLO	Road WBLO - PIC - Arsenal to Holloway Road	Cable Sheath	Asbestos	Presumed	528		RHS	Braided Cables. 1x 10mm from J hanger 3 to box, 2x 30mm from switch box box 820bG onto J hanger 3		2			
36864	ACTIVE	p	P044-P-WBLO	Road WBLO - PIC - Arsenal to Holloway Road	Signal Boxes	Asbestos	Presumed	539		RHS	Flash guards for Signal break box		1			
36865	ACTIVE	p	P044-P-WBLO	Road WBLO - PIC - Arsenal to Holloway Road	Signal Boxes	Asbestos	Presumed	544		RHS	Flash guards for Signal break box		1			
36866	ACTIVE	p	P044-P-WBLO	Road WBLO - PIC - Arsenal to Holloway Road	Signal Boxes	Asbestos	Presumed	582		LHS	Flashguards for Rail Gap indicators		1			
36867	ACTIVE	p	P044-P-WBLO	Road WBLO - PIC - Arsenal to Holloway Road	Signal Boxes	Asbestos	Presumed	616			Flash guards for Signal break box		1			
36868	ACTIVE	p	P044-P-WBLO	Road WBLO - PIC - Arsenal to Holloway Road	Signal Boxes	Asbestos	Presumed	622		RHS	Flash guards for Signal break box		1			
36869	ACTIVE	p	P044-P-WBLO	Road WBLO - PIC - Arsenal to Holloway Road	Signal Boxes	Asbestos	Presumed	637		RHS	Flash guards for Signal break box		1			

P045-P - PIC Line - Holloway Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42750	ACTIVE	p	P045-P-EBLO	Road EBLO (Plt2) - PIC - Holloway Road Stn	Pit Blocks	Asbestos	Removed				Pit blocks - Non asbestos (Removed by Forest 2003)					
42752	ACTIVE	p	P045-P-WBLO	Road WBLO (Plt1) - PIC - Holloway Road Stn	Pit Blocks	Asbestos	Removed				Pit blocks - Non asbestos (Removed by Forest 2003)					

P046-P - PIC Line - Holloway Road to Caledonian Road

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37277	ACTIVE	p	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Cable Sheath	Asbestos	Presumed	0		RHS	Braided cables. J hanger 1 = 0, J hanger 2 = 1 x 30mm , J hanger 3 =0 , J hanger 4 = 1 x 20mm		2			
37279	ACTIVE	p	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Signal Boxes	Asbestos	Presumed	4		RHS	Flash guards Signal A811		1			



Hazardous Material Asset Register - Summary



P046-P - PIC Line - Holloway Road to Caledonian Road

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37278	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Cement Cable Troughing & Debris	Asbestos	Known	4	0		Asbestos cement. Cable troughing R TO LHS		3			
37280	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Signal Boxes	Asbestos	Presumed	5		RHS	Flash guards Switch box 811GR		1			
37281	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Cable Sheath	Asbestos	Presumed	5		RHS	Braided cables.1 x 30mm cable from J hanger 2 to switch box		1			
37282	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Signal Boxes	Asbestos	Presumed	18		RHS	Flash guards Signal break box		1			
39700	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Signal Boxes	Asbestos	Presumed	22		RHS	Flash guards Signal break box		1			
37283	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Signal Boxes	Asbestos	Presumed	71		RHS	Flash guards Signal break box		1			
37284	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Signal Boxes	Asbestos	Presumed	73		RHS	Flash guards Signal break box		1			
37292	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Signal Boxes	Asbestos	Presumed	230			Flash guards Signal R819 ab		1			
37293	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Signal Boxes	Asbestos	Presumed	231		RHS	Flash guards Switch box 819abPGR		1			
37294	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Cable Sheath	Asbestos	Presumed	231		RHS	Braided cables. 1 x 20mm from switch box to J hanger 3		1			
39755	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Signal Boxes	Asbestos	Presumed	276		RHS	Flash guards Signal break box		1			
37295	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Signal Boxes	Asbestos	Presumed	277		RHS	Flash guards Switch box 833aT		2			
37285	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Signal Boxes	Asbestos	Presumed	281		RHS	Flash guards Signal break box		1			
37296	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Signal Boxes	Asbestos	Presumed	363		LHS	Flash guards Signal A819a		1			
37299	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Cable Sheath	Asbestos	Presumed	363		RHS	Braided cables.1 x 20mm cable from J hanger 3 to switch box					
37297	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Signal Boxes	Asbestos	Presumed	363		RHS	Flash guards Switch box 819aGR		1			
37298	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Cable Sheath	Asbestos	Presumed	364		RHS	Braided cables.1 x 20mm cable from switch box to J hanger 3		1			
37286	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Signal Boxes	Asbestos	Presumed	384		RHS	Flash guards Signal break box		1			
37287	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Signal Boxes	Asbestos	Presumed	389		RHS	Flash guards Signal break box		1			



Hazardous Material Asset Register - Summary



P046-P - PIC Line - Holloway Road to Caledonian Road

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37300	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Signal Boxes	Asbestos	Presumed	417		RHS	Flash guards Signal A819b		1			
39701	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Signal Boxes	Asbestos	Presumed	418		RHS	Flash guards Switch box 819bGR		1			
37301	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Cable Sheath	Asbestos	Presumed	418		RHS	Braided cables. 1 x 20mm cable from switch box to J hanger 2		2			
37288	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Signal Boxes	Asbestos	Presumed	426		RHS	Flash guards Signal break box		1			
39756	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Signal Boxes	Asbestos	Presumed	431		RHS	Flash guards Signal break box		1			
37302	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Signal Boxes	Asbestos	Presumed	461		RHS	Flash guards Rail gap Indicator		1			
37289	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Signal Boxes	Asbestos	Presumed	490			Flash guards Signal break box		1			
37290	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Signal Boxes	Asbestos	Presumed	496			Flash guards Signal break box		1			
37291	ACTIVE	P	P046-P-EBLO	Road EBLO - PIC - Caledonian Road to Holloway Road	Signal Boxes	Asbestos	Presumed	510			Flash guards Signal break box		1			
38049	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Cable Sheath	Asbestos	Presumed	0		RHS	Braided Cables. J hanger 1=0, J hanger 2 = 2x 10mm, J hanger 3=1x30mm, J hanger 4=0		3			
43427	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road		Asbestos	Removed				Troughing, 1m, against LHS of tunnel wall 20m Westbound Piccadilly Line towards Caledonian Road. Notes from 2022 re-inspection: Removed	20		R560451	N	N
43380	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Cable Sheath	Asbestos	Sampled – Not Detected			RHS	Braided cables, 6 no, in 4 foot outside of running rail on RHS of yellow cable, 30m off Westbound Platform Holloway Road (towards Caledonian Road). Piccadilly Line			R558526		
43381	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road		Asbestos	Sampled – Not Detected				Braided cables, 1 no, yellow cables in 4 foot, 30m off Westbound Platform Holloway Road (towards Caledonian Road). Piccadilly Line			R558526	N	N
43379	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Cable Duct: Other	Asbestos	Sampled – Not Detected				Braided cables, 6 no, in 4 foot outside of running rail on LHS of yellow cable, 30m off Westbound Platform Holloway Road (towards Caledonian Road). Piccadilly Line			R558526	N	N
38050	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Presumed	11			Flash guards Signal 818 R TO LHS		1			
38052	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Cable Sheath	Asbestos	Presumed	12		RHS	Braided Cables. 1x 30mm cable from J hanger 3 to break box		1			
38051	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Presumed	12		RHS	Flash guards Switch box 818GR		1			



Hazardous Material Asset Register - Summary



P046-P - PIC Line - Holloway Road to Caledonian Road

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38053	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Presumed	14		RHS	Flash guards for Signal break box		1			
38054	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Presumed	21		RHS	Flash guards for Signal break box		1			
38055	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Presumed	25		RHS	Flash guards for Signal break box		1			
38056	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Presumed	30		RHS	Flash guards for Signal break box		1			
68634	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Cable Sheath	Asbestos	Sampled – Not Detected	36	36		Cable to negative rail in 4 foot		1	R739026		
38057	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Cement Cable Troughing & Debris	Asbestos	Removed	37			Asbestos Cement. Cable troughing RHS TO LHS Removed by Edenbeck ES7494 27/10/2016		5			
38058	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Presumed	76		RHS	Flash guards for Signal break box		1			
38059	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Presumed	77		RHS	Flash guards for Signal break box		1			
39778	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Presumed	184	185	RHS	Flash guards Signal 8181 & R810 a		2			
38060	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Cable Sheath	Asbestos	Presumed	184	185	RHS	Braided Cables. 4 x 10mm cables from signals to J hanger 3		4			
38061	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Cable Sheath	Asbestos	Presumed	187		RHS	Braided Cables. 4 x 10mm from Rail stop to J hanger 3		4			
38063	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Cable Sheath	Asbestos	Presumed	189		RHS	Braided Cables. 8 x 10mm cables from J hanger 3 to switch boxes		8			
38062	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Presumed	189	190	RHS	Switch box 810aPGR & 8181GR		2			
38064	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Cable Sheath	Asbestos	Presumed	189		RHS	Braided Cables. 2 x 10mm cables from switch boxes to J hanger 3		2			
38065	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Presumed	193		RHS	Flash guards for Signal break box		1			
38066	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Presumed	194		RHS	Flash guards for Signal break box		1			
39422	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Presumed	231		RHS	Flash guards Switch box 844AT		1			
38067	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Presumed	284		RHS	Flash guards for Signal break box		1			
38068	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Presumed	320		RHS	Flash guards Signal A810aPGR & 810aPGR		1			



Hazardous Material Asset Register - Summary



P046-P - PIC Line - Holloway Road to Caledonian Road

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39917	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Presumed	321	322	RHS	Flash guards Switch box 821GR		1			
38069	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Cable Sheath	Asbestos	Presumed	322		RHS	Braided Cables. 1 x 30 mm from switch box to J hanger 3		1			
38070	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Presumed	323		RHS	Flash guards for Signal break box		1			
39636	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Presumed	335		RHS	Flash guards for Signal break box		1			
38071	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Presumed	339		RHS	Flash guards for Signal break box		1			
38072	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Presumed	403		RHS	Flash guards Signal 810 b		1			
38074	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Cable Sheath	Asbestos	Presumed	404		RHS	3 x 10mm from j hanger to switch boxes		3			
39918	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Presumed	404		RHS	Flash guards Switch box 810bGR		1			
38073	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Cable Sheath	Asbestos	Presumed	404		RHS	Braided Cables. 1 x 20mm from switch box to J hanger 3		1			
38075	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Presumed	407		RHS	Flash guards for Signal break box		1			
38076	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Presumed	409		RHS	Flash guards for Signal break box		1			
38077	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Presumed	415		RHS	Flash guards for Signal break box		1			
38078	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Presumed	454		RHS	Flash guards for Signal break box		1			
38079	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Presumed	489		RHS	Flash guards for Signal break box		1			
38080	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Presumed	493		RHS	Flash guards for Signal break box		1			
39423	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Cable Sheath	Asbestos	Presumed	500		RHS	Braided Cables. 1 x 40mm from cable joint to J hanger 4		1			
38081	ACTIVE	P	P046-P-WBLO	Road WBLO - PIC - Holloway Road to Caledonian Road	Signal Boxes	Asbestos	Removed	506		RHS	Flash guards for Signal break box Notes from 2022 re-inspection: Removed		1			



Hazardous Material Asset Register - Summary



P047-P - PIC Line - Caledonian Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42784	ACTIVE	P	P047-P-EBLO	Road EBLO (Plt1) - PIC - Caledonian Road Stn	Pit Blocks	Asbestos	Surveyed – Not Detected				Pit blocks - Non asbestos					
37303	ACTIVE	P	P047-P-EBLO	Road EBLO (Plt1) - PIC - Caledonian Road Stn	Westinghouse Boxes	Asbestos	Presumed	87			Trackside equipment: Westinghouse small box					
37304	ACTIVE	P	P047-P-EBLO	Road EBLO (Plt1) - PIC - Caledonian Road Stn	Westinghouse Boxes	Asbestos	Presumed	88			Trackside equipment: Westinghouse small box					
53987	ACTIVE	P	P047-P-WBLO	Road WBLO (Plt2) - PIC - Caledonian Road Stn	Other Electrical Boxes	Asbestos	Presumed				630VDC Electrical Notes from 2022 re-inspection: Present not removed		1			
42785	ACTIVE	P	P047-P-WBLO	Road WBLO (Plt2) - PIC - Caledonian Road Stn	Pit Blocks	Asbestos	Removed				Pit blocks - Non asbestos (Removed by Forest 25/11/2013 ES4986)					
69784	ACTIVE	P	P047-P-WBLO	Road WBLO (Plt2) - PIC - Caledonian Road Stn	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Tunnel Ring Caulking Wood/ grout to metal tunnel ring flange to rear of room 3/382			R749776		
37305	ACTIVE	P	P047-P-WBLO	Road WBLO (Plt2) - PIC - Caledonian Road Stn	Westinghouse Boxes	Asbestos	Presumed	87	88		Trackside equipment: Westinghouse small box throughout					

P048-P - PIC Line - Caledonian Road to Kings Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38412	ACTIVE	P	P048-P-EBLO	Road EBLO - PIC - Kings Cross to Caledonian Road	Cable Sheath	Asbestos	Known	0		RHS	Cloth cable sheath. Route: JH2 5x15mm, 1x20mm, JH3 1x25mm, 1x10mm, JH4 1x25mm		9			
38411	ACTIVE	P	P048-P-EBLO	Road EBLO - PIC - Kings Cross to Caledonian Road	Ducts	Asbestos	Strongly Presumed	0		LHS	Cable duct lining		2			
38413	ACTIVE	P	P048-P-EBLO	Road EBLO - PIC - Kings Cross to Caledonian Road	Cable Sheath	Asbestos	Known	2		RHS	Cloth cable sheath. Route: 1x10mm JH3, Exit: WHS small		1			
38414	ACTIVE	P	P048-P-EBLO	Road EBLO - PIC - Kings Cross to Caledonian Road	Cable Sheath	Asbestos	Known	11	14	RHS	Cloth cable sheath. Route: between Trackside Equipment 10-25mm, Exit: Trackside Equipment, Numerous amounts					
39967	ACTIVE	P	P048-P-EBLO	Road EBLO - PIC - Kings Cross to Caledonian Road	Cable Sheath	Asbestos	Known	14		RHS	Cloth cable sheath. Route: JH2 2x15mm, 1x20mm, JH4 1x25mm		4			
38415	ACTIVE	P	P048-P-EBLO	Road EBLO - PIC - Kings Cross to Caledonian Road	Cable Sheath	Asbestos	Known	64		RHS	Cloth cable sheath. Route: Losing 15x1mm JH2		3			
38416	ACTIVE	P	P048-P-EBLO	Road EBLO - PIC - Kings Cross to Caledonian Road	Cable Sheath	Asbestos	Known	68		RHS	Cloth cable sheath. Route: Losing 15x1mm JH2		2			
38417	ACTIVE	P	P048-P-EBLO	Road EBLO - PIC - Kings Cross to Caledonian Road	Cable Sheath	Asbestos	Known	404	405	RHS	Cloth cable sheath. Route: Between Trackside Equipment 10-25mm, numerous amounts					
38418	ACTIVE	P	P048-P-EBLO	Road EBLO - PIC - Kings Cross to Caledonian Road	Cable Sheath	Asbestos	Known	405		RHS	Cloth cable sheath. Route: JH2 1x25mm, 1x20mm, JH4 1x25mm		3			



Hazardous Material Asset Register - Summary



P048-P - PIC Line - Caledonian Road to Kings Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38419	ACTIVE	P	P048-P-EBLO	Road EBLO - PIC - Kings Cross to Caledonian Road	Cable Sheath	Asbestos	Known	549	562	RHS	Cloth cable sheath. Route: Between trackside equipment, numerous amounts					
39968	INACTIVE	P	P048-P-EBLO	Road EBLO - PIC - Kings Cross to Caledonian Road	Cable Sheath	Asbestos	Removed	562		RHS	Cloth cable sheath. Route: Between JH3-JH4 Notes from 2022 re-inspection: Removed		3			
38420	ACTIVE	P	P048-P-EBLO	Road EBLO - PIC - Kings Cross to Caledonian Road	Cable Sheath	Asbestos	Known	696		RHS	Cloth cable sheath. Route: Limited access due to height: Exit: Wall					
38421	ACTIVE	P	P048-P-EBLO	Road EBLO - PIC - Kings Cross to Caledonian Road	Cable Sheath	Asbestos	Known	701		RHS	Cloth cable sheath. Entry: Wall, Route: Limited access due to height					
38422	ACTIVE	P	P048-P-EBLO	Road EBLO - PIC - Kings Cross to Caledonian Road	Cable Sheath	Asbestos	Known	705	709	RHS	Cloth cable sheath. Route: Losing 1x25mm					
38423	ACTIVE	P	P048-P-EBLO	Road EBLO - PIC - Kings Cross to Caledonian Road	Cable Sheath	Asbestos	Known	730		LHS	insulating boarding, <0.1m2					
38424	ACTIVE	P	P048-P-EBLO	Road EBLO - PIC - Kings Cross to Caledonian Road	Cable Sheath	Asbestos	Known	788		RHS	Cloth cable sheath. Route: Limited access due to height, Exit: Wall		2			
38425	ACTIVE	P	P048-P-EBLO	Road EBLO - PIC - Kings Cross to Caledonian Road	Cable Sheath	Asbestos	Known	800		RHS	Cloth cable sheath. Entry wall					
38426	ACTIVE	P	P048-P-EBLO	Road EBLO - PIC - Kings Cross to Caledonian Road	Cable Sheath	Asbestos	Known	802		RHS	Cloth cable sheath. Route: 1x20mm drop into JH3					
38427	ACTIVE	P	P048-P-EBLO	Road EBLO - PIC - Kings Cross to Caledonian Road	Cable Sheath	Asbestos	Known	810	812	RHS	Cloth cable sheath. Route: Between JH2-JH3, Exit: Track. Numerous amounts					
38428	ACTIVE	P	P048-P-EBLO	Road EBLO - PIC - Kings Cross to Caledonian Road	Cable Sheath	Asbestos	Known	812		RHS	Cloth cable sheath. Route: JH4 1x20mm		1			
38429	ACTIVE	P	P048-P-EBLO	Road EBLO - PIC - Kings Cross to Caledonian Road	Cable Sheath	Asbestos	Known	1260	1267	RHS	Cloth cable sheath. Route: Between trackside equipment, numerous amounts					
38430	ACTIVE	P	P048-P-EBLO	Road EBLO - PIC - Kings Cross to Caledonian Road	Cable Sheath	Asbestos	Known	1267		RHS	Cloth cable sheath. Entry: Trackside Equipment, Route: JH3 1x30mm, JH2 1x25mm		2			
39837	ACTIVE	P	P048-P-EBLO	Road EBLO - PIC - Kings Cross to Caledonian Road	Cable Sheath	Asbestos	Known	1392		RHS	Cloth cable sheath. Entry: Tencore, Route: JH3 1x30mm, 1x10mm, Exit: Tencore		2			
38431	ACTIVE	P	P048-P-EBLO	Road EBLO - PIC - Kings Cross to Caledonian Road	Cable Sheath	Asbestos	Known	1707	1709	RHS	Cloth cable sheath. Route: Between Trackside Equipment 10-30mm, numerous amounts					
38432	ACTIVE	P	P048-P-EBLO	Road EBLO - PIC - Kings Cross to Caledonian Road	Cable Sheath	Asbestos	Known	1709		RHS	Cloth cable sheath. Route: JH2 1x20mm, JH3 1x30mm, JH4 1x25mm		3			
38433	ACTIVE	P	P048-P-EBLO	Road EBLO - PIC - Kings Cross to Caledonian Road	Cable Sheath	Asbestos	Known	1801		RHS	Cloth cable sheath. Route: JH2 2x20mm, JH3 1x30mm, JH4 1x25mm		4			
37251	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cable Sheath	Asbestos	Known	0			Woven cable sheath. Route: JH2 1x25mm		1			



Hazardous Material Asset Register - Summary



P048-P - PIC Line - Caledonian Road to Kings Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37252	INACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cement Cable Troughing & Debris	Asbestos	Removed	1		OTX	cement, troughing Notes from 2022 re-inspection: Removed		1			
37253	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Signal Boxes	Asbestos	Presumed	1			Signal A808					
37272	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cable Sheath	Asbestos	Known	177		RHS	Woven cable sheath. Route: JH2 2x25, 2x35, JH3 10x20mm		14			
39589	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cable Sheath	Asbestos	Known	300	479		Signal Section. Entry: Westinghouse small box large, Route: JH2 1x25mm, Exit: Westinghouse small box large		1			
37254	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cable Sheath	Asbestos	Known	479			Woven cable sheath. Entry: Trackside Equipment, Route: JH2 1x25, JH3 1x30mm		2			
37255	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Signal Boxes	Asbestos	Presumed	840			Signal R802					
37256	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cable Sheath	Asbestos	Known	1024		RHS	Woven cable sheath. Exit: OTX		2			
53982	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cement Cable Troughing & Debris	Asbestos	Known	1055			Cement Troughing Notes from 2022 re-inspection: Remains not removed					
37257	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cable Sheath	Asbestos	Known	1068			Woven cable sheath. Entry: Trackside Equipment, Route: JH3 1x25, 3x20mm		4			
37258	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cable Sheath	Asbestos	Known	1072			Woven cable sheath. Entry: Wall, Route: JH3 1x25, 3x20mm		4			
39754	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cable Sheath	Asbestos	Known	1078			Woven cable sheath. Route: JH3 1x25mm, 3x20mm, Exit: Wall		4			
37259	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cable Sheath	Asbestos	Known	1082			Kiosk 806A. Entry: JH3 1x25mm, Route: JH3 2x25, 3x20mm		5			
37260	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cable Sheath	Asbestos	Known	1170			Woven cable sheath. Entry: Wall, Route: JH3 2x25, 3x20mm		5			
37261	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cable Sheath	Asbestos	Known	1174			Woven cable sheath. Route: JH3 2x25, 3x20mm, Exit:Wall		5			
39699	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cable Sheath	Asbestos	Removed	1180			Woven cable sheath. Route: JH2 1x25, JH3 3x20mm, Exit: Trackside Equipment		4			
37262	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cable Sheath	Asbestos	Known	1520			Woven cable sheath. Route: JH3 1x20mm, Gaining & losing		4			
37263	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cable Sheath	Asbestos	Known	1574			Woven cable sheath. Entry: Trackside Equipment, Route: JH2 1x25, 1x35, JH3 7x20, JH4 7x20mm					
37264	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cable Sheath	Asbestos	Known	1583			Woven cable sheath. Route: 1x20mm-JH3 gaining					



Hazardous Material Asset Register - Summary



P048-P - PIC Line - Caledonian Road to Kings Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37265	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cable Sheath	Asbestos	Known	1588			Woven cable sheath. Route: 1x20mm-JH3 losing					
37266	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cable Sheath	Asbestos	Known	1589			Woven cable sheath. Route: JH3 1x20mm Gaining & losing					
37267	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cable Sheath	Asbestos	Known	1657	1671		Signal Section. Route: 10-35mm and between trackside equipment box, Exit: Trackside equipment, numerous amounts					
37268	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cable Sheath	Asbestos	Known	1671			Woven cable sheath. Route: JH2 1x25, 1x35, JH3 10x20mm		12			
37269	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Signal Boxes	Asbestos	Known	1717			Signal RLx790C, L100 A790C		2			
37270	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cable Sheath	Asbestos	Known	1720			Woven cable sheath. Route: JH2 2x35, 1x25, JH3 11x25mm		14			
39590	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cable Sheath	Asbestos	Known	1741			Woven cable sheath. Entry: Westinghouse small box small, Route: Gaining 1x20mm JH3		15			
37271	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cable Sheath	Asbestos	Known	1752			Woven cable sheath. Route: losing 1x20mm JH3, Exit: Westinghouse small box small		14			
37273	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cable Sheath	Asbestos	Known	1790		RHS	Woven cable sheath. Route: JH3 2x25, 2x35, JH3 10x20mm		14			
37274	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cable Sheath	Asbestos	Known	1820		RHS	Woven cable sheath. Route: JH3 1x25mm Gaining and loss		14			
37275	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cable Sheath	Asbestos	Known	1847	1871		Signal section. Between cable hangers, numerous amounts					
37276	ACTIVE	P	P048-P-WBLO	Road WBLO - PIC - Caledonian Road to Kings Cross	Cable Sheath	Asbestos	Known	1871			Woven cable sheath. Route: JH2 2x25, 2x35, JH3 14x20mm		18			

P052-P - PIC Line - Kings Cross to Russell Square

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40499	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	0		LHS	Cloth. cable sheath, route: jh2 30mmØx1, jh6 35mmØx1		2			
40500	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	2		LHS	Cloth. cable sheath, entry: otx		2			
46216	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	3		RHS	7 no. cable sheath 4x10mmØ on 2nd hanger 2x10mmØ on 3rd hanger 1x20mmØ on 3rd hanger		7			
46215	INACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cement Troughing	Asbestos	Removed				Cementitious troughing encased in cement Notes from 2022 re-inspection: Removed				N	N



Hazardous Material Asset Register - Summary



P052-P - PIC Line - Kings Cross to Russell Square

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46217	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	15		RHS	1 no. cable sheath 1x10mmØ		1			
46218	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	18			2 no. cable sheath 1x20mmØ on 3rd hanger 1x10mmØ on 2nd hanger		2			
46219	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	18			2 no. cable sheath 2x20mmØ loose on 2nd hanger		2			
46220	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	22			6 no. cable sheath 1x10mmØ on 2nd hanger 5x10mmØ on cross over		6			
40501	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	27		RHS	Cloth. cable sheath, route: jh5 40mmØx1		2			
46221	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	29			6 no. cable sheath 1x10mmØ on 2nd hanger 5x10mmØ on cross over		6			
40502	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	40		RHS	Cloth. cable sheath, route: jh2 30mmØ x 1, jh4 45mmØx2, jh3 20mmØ x 2		5			
46222	INACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cement Troughing	Asbestos	Removed				1x4m length in cementitious troughing in track bed Notes from 2022 re-inspection: Removed	4	1		N	N
46223	INACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cement Troughing	Asbestos	Removed				2x4m length cementitious troughing in track bed Notes from 2022 re-inspection: Removed	4	2		N	N
46224	INACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Other Boarding	Asbestos	Removed				Panel material to CRSS units Notes from 2022 re-inspection: Removed	3			N	N
46225	INACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cement Troughing	Asbestos	Removed				Troughing cemented into track bed Notes from 2022 re-inspection: Removed	3			N	N
46226	INACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cement Troughing	Asbestos	Removed				Disused troughing encased in concrete Notes from 2022 re-inspection: Removed	3			N	N
46227	INACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Removed	200			2 no. cable sheath 2x10mmØ Notes from 2022 re-inspection: Removed		2			
40503	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	266		RHS	Splice cable, route: jh4 30mmØx1m. 2.5m					
40504	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	277		RHS	Cloth. cable sheath, route: jh2 30mmØx1, jh4 30mmØx1m		2			
46228	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	330			1 no. cable sheath 1x40mmØ on 2nd hanger		1			



Hazardous Material Asset Register - Summary



P052-P - PIC Line - Kings Cross to Russell Square

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46229	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	340			1 no. cable sheath 1x40mmØ on bottom hanger		1			
46230	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	350			1 no. cable sheath 1x40mmØ on bottom hanger	40	1			
46231	INACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cement Troughing	Asbestos	Removed				Troughing encased in concrete Notes from 2022 re-inspection: Removed	8			N	N
46232	INACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Other Boarding	Asbestos	Removed				Panel material to CRSS units Notes from 2022 re-inspection: Removed	3			N	N
46233	INACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cement Troughing	Asbestos	Removed				Troughing encased in concrete Notes from 2022 re-inspection: Removed	8			N	N
46234	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	470			1 no. cable sheath 1x30mmØ	30	1			
46235	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	570			1 no. cable sheath 1x30mmØ	30	1			
40505	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	571		RHS	Cloth. cable sheath, route: jh2 30mmØx1, jh4 30mmØx1		2			
46236	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	580			1 no. cable sheath 1x30mmØ	30	1			
46237	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	630			1 no. cable sheath 1x30mmØ	30	1			
40506	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	675		RHS	Cloth. cable sheath, route: jh2 30mmØx1, jh4 30mmØx1		2			
39432	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	690		RHS	Cloth. cable sheath, exit: otx					
40507	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	694		RHS	Cloth. cable sheath, entry: side, route: jh2 4x10mmØ. Numerous amounts					
40508	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	694		RHS	Cloth. cable sheath, route: between jh1 - jh5, 10-45mmØ. Numerous amounts					
40509	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	746	776	RHS	Cloth. cable sheath, route: jh2 - jh5, 5mmØ - 30mmØ. Numerous amounts					
46238	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	750			4 no. cable sheath 4x30mmØ	30	4			
40511	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Westinghouse Boxes	Asbestos	Presumed	801		LHS	Westinghouse small		1			
40510	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Signal Boxes	Asbestos	Presumed	801		LHS	tencore		1			



Hazardous Material Asset Register - Summary



P052-P - PIC Line - Kings Cross to Russell Square

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40512	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	801	805	LHS	Cloth. cable sheath, entry: vent shaft, route: jh1 2x30mmØ, exit: otx					
39433	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Signal Boxes	Asbestos	Presumed	801		LHS	signal box x1		1			
40589	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	805		RHS	Cloth. cable sheath. entry: otx, route jh1 - jh10, 5mmØ - 30mmØ, numerous amounts					
40590	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	814		RHS	Cloth. cable sheath, exit: platform wall. Numerous amounts					
46239	ACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cable Sheath	Asbestos	Known	818			Cable sheath All asbestos cables cross over to left side					
46240	INACTIVE	P	P052-P-EBLO	Road EBLO - PIC - Russell Square to Kings Cross	Cement Troughing	Asbestos	Removed				Troughing encased in concrete Notes from 2022 re-inspection: Removed	3			N	N
38172	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Known	0		RHS	Cloth cable sheath. Route: Between JH1-JH5 15-25mm		11			
38173	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Known	0	15	RHS	Cloth cable sheath. Route: JH2 1x25mm, 2x20mm, JH3 7x15mm		10			
38174	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Known	15	28	RHS	Cloth cable sheath. Route: Between JH2-JH4 & Trackside Equipment 15-25mm, Exit: Trackside Equipment, numerous amounts					
38175	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Known	28		RHS	Cloth cable sheath. Route: JH2 2x20mm, JH3 1x15mm		3			
38176	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Known	77		RHS	Cloth cable sheath. Route: Losing 1x15mm JH3, Exit: WHS small		2			
38177	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Known	130		RHS	cable, spliced. Route: JH2 1x20mm		1			
39927	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Known	157			WB-EB points joining cloth cable sheath. Entry: JH2 Engineering Section from points, Route: JH2 4x15mm, numerous amounts					
38178	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Known	190	203	RHS	Cloth cable sheath. Numerous amounts					
38179	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Known	205		RHS	cable spliced		2			
38180	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Known	207		RHS	Cloth cable sheath. Route: JH2 2x20mm		2			
38181	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Known	325		RHS	cable spliced, Route: JH2 1x20mm		1			
38182	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Known	333	336	RHS	Cloth cable sheath. Numerous amounts					



Hazardous Material Asset Register - Summary



P052-P - PIC Line - Kings Cross to Russell Square

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38183	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Known	336		RHS	Cloth cable sheath. Route: JH2 2x20mm, JH3 1x30mm, Numerous amounts					
38370	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Known	344		RHS	cable spliced, Route: JH4 1x45mm		1			
42976	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Wrap	Asbestos	Sampled – Not Detected	345		LHS	Braided cable, 6 no, to inside of running rails BRS 345m, on the left hand side, Piccadilly Line W/B – between Kings Cross and Russell Square stations			R524201		
44069	INACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Removed	345	350		Braided cable, 1 no, to wall on the left hand side, BRS 345-350, going undertrack crossing to concrete into 4 foot, Piccadilly Line W/B, between Kings Cross and Russell Square stations Removed by Edenbeck on 30/06/2016 (E56584)			R524201		
N	INACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Wrap	Asbestos	Removed	345	350	LHS	Braided cable, 1 no, to wall on the left hand side, BRS 345-350, going undertrack crossing to concrete into 4 foot, Piccadilly Line W/B, between Kings Cross and Russell Square stations Removed by Edenbeck on 30/06/2016			R524201		
38371	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Known	353		RHS	cable spliced, Route: JH4 1x45mm		1			
38372	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Known	473	476	RHS	Cloth cable sheath. Numerous amounts					
38373	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Known	476		RHS	Cloth cable sheath. Route: JH2 2x20mm, JH3 1x30mm, 2x25mm		5			
39646	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Known	498		RHS	Cloth cable sheath. Entry: Trackside Equipment, Route: 1x30mm, JH3		1			
38374	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Known	580		RHS	cable spliced, Route: JH4 1x45mm		1			
38375	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Known	588		RHS	cable spliced, Route: JH4 1x45mm		1			
38376	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Known	590		RHS	Cloth cable sheath. Route: JH2 2x20mm, JH3 2x25mm, 1x30mm		5			
38377	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Known	626	630	RHS	Cloth cable sheath. Route: Between JH2-JH4 & Trackside Equipment 10-30mm. Numerous amounts					
38378	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Known	630		RHS	Cloth cable sheath. Route: JH2 2x20mm, JH3 2x30mm, 2x25mm		6			
38379	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Known	706	710	RHS	Cloth cable sheath. Route: Between JH2-JH4 & Trackside Equipment 10-30mm, numerous amounts					



Hazardous Material Asset Register - Summary



P052-P - PIC Line - Kings Cross to Russell Square

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38380	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Known	710		RHS	Cloth cable sheath. Route: JH2 2x20mm, JH3 2x25mm, 2x30mm		6			
38381	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Known	774		RHS	Cloth cable sheath. Route: JH2 2x30mm, JH3 2x25mm, 2x25mm		6			
38382	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cement Cable Troughing & Debris	Asbestos	Removed	819		RHS	Cement Cable Trough - Removed by Edenbeck 27/04/2015		1			
38383	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Cable Sheath	Asbestos	Known	821	824		Cloth cable sheath. Route: OTX from right side LHS. Track re-inspection by Project 03/05/2014 - Area marked with yellow chalk to indicate presence of asbestos. Fault no 50026747.RHS/OTX		6			
38384	ACTIVE	P	P052-P-WBLO	Road WBLO - PIC - Kings Cross to Russell Square	Ducts	Asbestos	Strongly Presumed	829		LHS	bitumen cable duct lining		4			

P053-P - PIC Line - Russell Square Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42769	INACTIVE	P	P053-P-EBLO	Road EBLO (Plt1) - PIC - Russell Square Stn		Asbestos	Surveyed – Not Detected				Pit blocks - Non asbestos					
40491	ACTIVE	P	P053-P-EBLO	Road EBLO (Plt1) - PIC - Russell Square Stn	Westinghouse Boxes	Asbestos	Presumed	59		RHS	Trackside equipment: Westinghouse small box		1			
40492	ACTIVE	P	P053-P-EBLO	Road EBLO (Plt1) - PIC - Russell Square Stn	Westinghouse Boxes	Asbestos	Presumed	63		RHS	Trackside equipment: Westinghouse small box		1			
40493	ACTIVE	P	P053-P-EBLO	Road EBLO (Plt1) - PIC - Russell Square Stn	Signal Boxes	Asbestos	Presumed	86		RHS	Trackside equipment: 630V DC box		1			
40494	ACTIVE	P	P053-P-EBLO	Road EBLO (Plt1) - PIC - Russell Square Stn	Signal Boxes	Asbestos	Presumed	106		RHS	Trackside equipment: Redifon loop aerial box		1			
42770	INACTIVE	P	P053-P-WBLO	Road WBLO (Plt2) - PIC - Russell Square Stn		Asbestos	Surveyed – Not Detected				Pit blocks - Non asbestos					
40495	ACTIVE	P	P053-P-WBLO	Road WBLO (Plt2) - PIC - Russell Square Stn	Signal Boxes	Asbestos	Presumed	76		LHS	Trackside equipment: 630V DC box		1			
40496	ACTIVE	P	P053-P-WBLO	Road WBLO (Plt2) - PIC - Russell Square Stn	Westinghouse Boxes	Asbestos	Presumed	89		LHS	Trackside equipment: Westinghouse small box		1			
40497	ACTIVE	P	P053-P-WBLO	Road WBLO (Plt2) - PIC - Russell Square Stn	Westinghouse Boxes	Asbestos	Presumed	94		LHS	Trackside equipment: Westinghouse small box		1			
40498	ACTIVE	P	P053-P-WBLO	Road WBLO (Plt2) - PIC - Russell Square Stn	Cable Sheath	Asbestos	Removed	104		RHS	Cloth. cable sheath Notes from 2022 re-inspection: Removed		1			
39954	ACTIVE	P	P053-P-WBLO	Road WBLO (Plt2) - PIC - Russell Square Stn	Signal Boxes	Asbestos	Presumed	105		LHS	Trackside equipment: Redifon loop aerial box		1			



Hazardous Material Asset Register - Summary



P054-P - PIC Line - Russell Square to Holborn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37944	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	0	4	RHS	Cloth, cable sheath, Entry: Platform wall, Route: H2 of 4, ~7x8mmØ, 1x15mmØ, H4, 1x15mmØ, Exit: Westinghouse small box. 9 x 4M					
37945	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	4	8	RHS	Cloth, cable sheath, Entry: N/A, Route: H2 of 4, 6x8mmØ, 1x15mmØ, H4 1x15mmØ, Exit: Signals trackside equipment. 8 x 4m					
37946	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	4		RHS	Trackside equipment: Westinghouse small box		1			
37947	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	8	11	RHS	Cloth, cable sheath, Entry: N/A, Route: Between trackside equipment, H2 & H4, 8mmØ to 15mmØ, Exit: N/A. numerous amounts					
37948	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	8		RHS	Trackside equipment: Signal (PD3)		1			
37773	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	10		RHS	Trackside equipment: tencore box		1			
37772	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	10		RHS	Trackside equipment: Westinghouse small box		1			
37949	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	10		RHS	Trackside equipment: Westinghouse small box		1			
37775	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	11	14	RHS	Cloth, cable sheath, Entry: Signals trackside equipment, Route: H2 of 4, 2x8mmØ, H4 1x15mmØ, Exit: Westinghouse small box. 3 x 2.5m					
37774	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	11		RHS	Trackside equipment: Westinghouse large box		1			
37776	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	11		RHS	Trackside equipment: tencore box		1			
37777	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	14	48	RHS	Cloth, cable sheath, Entry: N/A, Route: H2 of 4, 1x8mmØ, H4 1x15mmØ, Exit: N/A. 2 x 34.5m					
37778	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	14		RHS	Trackside equipment: Westinghouse small box		1			
39765	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	16		RHS	Trackside equipment: Tunnel Lighting box		1			
37779	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	25		RHS	Trackside equipment: Type 79 box		1			
37780	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	45		RHS	Trackside equipment: Type 79 box		1			
37781	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	47		RHS	Trackside equipment: COLR box		1			



Hazardous Material Asset Register - Summary



P054-P - PIC Line - Russell Square to Holborn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37782	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	48	50	RHS	Cloth, cable sheath, Entry: Westinghouse large box, Route: H2 of 4, 3x8mmØ, H4, 1x15mmØ, Exit: OTX to EB P-Way. 4 x 2m					
37783	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	51		LHS	Trackside equipment: Tunnel Lighting box		1			
37784	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	85	87	RHS	Cloth, cable sheath, Entry: N/A, Route: Between Points trackside equipment, 8mmØ to 30mmØ, Exit: High level CMS. Numerous amounts					
39416	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	87		LHS	Trackside equipment: tencore box		3			
37785	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	92	95	RHS	Cloth, cable sheath, Entry: High level CMS, Route: H2 of 4, ~5x8mmØ, 2x20mmØ, H3, 5x8mmØ, 4x15mmØ, 1x20mmØ, H4, 4x8mmØ, 1x15mmØ, 1x30mmØ, Exit: Westinghouse small box. 23 x 2.5m					
37787	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	95		RHS	Trackside equipment: Westinghouse small box		1			
37786	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	95	97	RHS	Cloth, cable sheath, Entry: N/A, Route: H2 of 4, ~6x8mmØ, 2x20mmØ, H3, 5x8mmØ, 4x15mmØ, 1x20mmØ, H4, 3x8mmØ, 1x30mmØ, 1x15mmØ, Exit: Spliced cable. 23 x 2m					
37788	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	97	100	RHS	Cloth, cable sheath, Entry: N/A, Route: H2 of 4, ~6x8mmØ, 2x20mmØ, H3, 5x8mmØ, 4x15mmØ, 1x20mmØ, H4, 3x8mmØ, 1x15mmØ, Exit N/A. 22 x 3m					
37790	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	100		RHS	Trackside equipment: tencore box		1			
37789	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	100	106	RHS	Cloth, cable sheath, Entry: Ten Core box, Route: H2 of 4, ~6x8mmØ, 2x20mmØ, H3, 7x8mmØ, 4x15mmØ, 1x20mmØ, H4, 3x8mmØ, 1x15mmØ, Exit: Westinghouse small box. 24 x 6m					
37791	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	104		LHS	Trackside equipment: tencore box		1			
39604	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	105		RHS	Trackside equipment: Westinghouse small box		1			
39876	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	105		RHS	Trackside equipment: Signal (RFPX777)		1			
37793	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	106		RHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P054-P - PIC Line - Russell Square to Holborn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37792	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	106	110	RHS	Cloth, cable sheath, Entry: N/A, Route: H2 of 4, ~6x8mmØ, 2x20mmØ, H3, 7x8mmØ, 4x15mmØ, H4, 3x8mmØ, 1x15mmØ, Exit: Westinghouse small box. 23 x 4.5m					
37794	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	106		RHS	Trackside equipment: Westinghouse large box		1			
37979	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	110		RHS	Trackside equipment: Westinghouse small box		1			
37978	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	110	118	RHS	Cloth, cable sheath, Entry: N/A, H2 of 4, ~4x8mmØ, 2x20mmØ, H3, 7x8mmØ, 4x15mmØ, H4, 3x8mmØ, 1x15mmØ, Exit: Signals trackside equipment. 21 x 7.5m					
37980	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	118	120	RHS	Cloth, cable sheath, Entry: N/A, Between trackside equipment, H2, H3 & H4, 8mmØ to 20mmØ, Exit: N/A. numerous amounts					
37983	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	118		RHS	Trackside equipment: Square electrical box		1			
37982	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	118		RHS	Trackside equipment: tencore box		1			
37981	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	118		RHS	Trackside equipment: Westinghouse small box		1			
37984	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	119		RHS	Trackside equipment: Rail Gap Ind. Box		1			
37985	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	120	130	RHS	Cloth, cable sheath, Entry: Signals trackside equipment, Route: H2 of 4, ~1x8mmØ, 2x20mmØ, H3, 4x8mmØ, 2x15mmØ, H4 2x8mmØ, 1x15mmØ Exit: Westinghouse small box. 12 x 10.5m					
37987	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	130		RHS	Trackside equipment: Westinghouse small box		1			
37986	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	130	180	RHS	Cloth, cable sheath, Entry: Westinghouse small box, H2 of 4, ~1x8mmØ, 2x20mmØ, H3, 5x8mmØ, 1x15mmØ, H4, 2x8mmØ, 1x15mmØ, Exit: Ten Core box. 12 x 50m					
37989	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	180		RHS	Trackside equipment: tencore box		1			
37988	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	180	226	RHS	Cloth, cable sheath, Entry: Ten Core box, H2 of 4, ~1x8mmØ, 2x20mmØ, H3, 5x8mmØ, 1x15mmØ, H4, 2x8mmØ, 1x15mmØ, Exit: N/A. 12 x 45.5m					
37990	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	223		RHS	Trackside equipment: Signal (FPX777)		1			



Hazardous Material Asset Register - Summary



P054-P - PIC Line - Russell Square to Holborn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37991	ACTIVE	p	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	224		RHS	Trackside equipment: Westinghouse small box		1			
37992	ACTIVE	p	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	225		RHS	Trackside equipment: tencore box		1			
39633	ACTIVE	p	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	225		RHS	Trackside equipment: Westinghouse large box		1			
37993	ACTIVE	p	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	226	227	RHS	Cloth, cable sheath, Entry: Ten Core box, H2 of 4, ~1x8mmØ, 1x15mmØ, 1x20mmØ, H3, 5x8mmØ, 1x15mmØ, H4, 2x8mmØ, 1x15mmØ, Exit: Ten Core box. 12 x 1m					
37994	ACTIVE	p	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	226		RHS	Trackside equipment: tencore box		1			
37996	ACTIVE	p	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	227		RHS	Trackside equipment: tencore box		1			
37995	ACTIVE	p	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	227	230	RHS	Cloth, cable sheath, Entry: N/A, Route: H2 of 4, ~1x8mmØ, 1x15mmØ, 1x20mmØ, H3, 5x8mmØ, H4, 2x8mmØ, 1x15mmØ, Exit: Grey electrical box. 11 x 3.5m					
37998	ACTIVE	p	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	230		RHS	Trackside equipment: Grey electrical box		1			
37997	ACTIVE	p	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	230	233	RHS	Cloth, cable sheath, Entry: N/A, Route: H2 of 4, ~1x15mmØ, 2x20mmØ, H3, 4x8mmØ, H4, 2x8mmØ, 1x15mmØ, Exit: Westinghouse small box. 10 x 3m					
39775	ACTIVE	p	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	233		RHS	Trackside equipment: Westinghouse small box		1			
37999	ACTIVE	p	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	233	238	RHS	Cloth, cable sheath, Entry: N/A, Route: H2 of 4, ~1x15mmØ, 2x20mmØ, H3, 3x8mmØ, H4, 2x8mmØ, 1x15mmØ, Exit: Westinghouse small box. 9 x 5m					
39913	ACTIVE	p	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	238	252	RHS	Cloth, cable sheath, Entry: N/A, Route: H2 of 4, ~1x15mmØ, 2x20mmØ, H3, 2x8mmØ, H4, 2x8mmØ, 1x15mmØ, Exit: N/A. 8 x 14m					
38000	ACTIVE	p	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	238		RHS	Trackside equipment: Westinghouse small box		1			
38001	ACTIVE	p	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	252	256	RHS	Cloth, cable sheath, Entry: Spliced cable, Route: H2 of 4, ~1x15mmØ, 2x20mmØ, H3, 2x8mmØ, H4, 2x8mmØ, 1x15mmØ, 1x30mmØ, Exit: Spliced cable. 9 x 4m					
38002	ACTIVE	p	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	256	315	RHS	Cloth, cable sheath, Entry: N/A, Route: H2 of 4, ~1x15mmØ, 2x20mmØ, H3, 2x8mmØ, H4, 2x8mmØ, 1x15mmØ, Exit: Westinghouse small box. 8 x 59m					



Hazardous Material Asset Register - Summary



P054-P - PIC Line - Russell Square to Holborn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38003	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	269		RHS	Trackside equipment: Main earth terminal box		1			
38004	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	279		RHS	Trackside equipment: Westinghouse small box		1			
38006	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	315		RHS	Trackside equipment: Westinghouse small box		1			
38005	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	315	474	RHS	Cloth, cable sheath, Entry: N/A, Route: H2 of 4, ~1x15mmØ, 2x20mmØ, H3, 1x8mmØ, H4, 2x8mmØ, 1x15mmØ, Exit: N/A. 7 x 159m					
38007	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	376		RHS	Trackside equipment: Type 79 box		1			
38008	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	392		RHS	Trackside equipment: Westinghouse small box		1			
39776	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	472		RHS	Trackside equipment: Signal (FPX779A)		1			
38009	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	472		RHS	Trackside equipment: Signal (RFPX779B)		1			
38012	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	473		RHS	Trackside equipment: Westinghouse large box		1			
38011	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	473		RHS	Trackside equipment: tencore box		1			
38010	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	473		RHS	Trackside equipment: Westinghouse small box					
38014	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	474		RHS	Trackside equipment: Westinghouse large box		1			
38013	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	474	575	RHS	Cloth, cable sheath, Entry: Ten Core box, Route: H2 of 4, ~2x15mmØ, 2x20mmØ, H3, 1x8mmØ, H4, 2x8mmØ, 1x15mmØ, Exit: OTX to LHS. 8 x 101m					
39421	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	474		RHS	Trackside equipment: tencore box		1			
38015	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	478		RHS	Trackside equipment: Westinghouse small box		1			
38016	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	482		RHS	Trackside equipment: Westinghouse small box		1			
38017	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	533		RHS	Trackside equipment: Westinghouse large box		1			
39914	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	533		RHS	Trackside equipment: Signal (FPX779B779C)		1			



Hazardous Material Asset Register - Summary



P054-P - PIC Line - Russell Square to Holborn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38018	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	569		RHS	Trackside equipment: Westinghouse small box		1			
38019	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	574		RHS	Trackside equipment: Westinghouse small box		1			
38021	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	575	601	LHS	Cloth, cable sheath, Entry: OTX to RHS, Route: H1 of 10, 2x20mmØ, 1x15mmØ, H2, 1x8mmØ, Exit: Cable Tunnel CT.01. 4 x 25.5m					
38020	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	575	579	RHS	Cloth, cable sheath, Entry: N/A, Route: H2 of 8, 2x20mmØ, H6, 1x8mmØ, H8, 1x20mmØ, Exit: Cross Passage CP.02. 4 x 3.5m					
39915	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	579	594	RHS	Cloth, cable sheath, Entry: N/A, Route: H2 of 4, 1x20mmØ, Exit: Ten Core box. 1 x 15m					
39634	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	591		RHS	Trackside equipment: Signal (FPX779B)		1			
38022	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	592		RHS	Trackside equipment: Westinghouse large box		1			
38024	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	593		RHS	Trackside equipment: Westinghouse small box		1			
38023	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	593		RHS	Trackside equipment: tencore box		1			
38025	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	594		RHS	Trackside equipment: tencore box		1			
38027	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Ducts	Asbestos	Presumed	601	608		Cement. cable duct lining, Presumed present in wall (Stored items prevented access) unknown					
38026	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	601	608	LHS	Cloth, cable sheath, Entry: EB P-Way, Route: Various hangers, 8mmØ to 20mmØ, Exit: Wall in CT. 01. 4 x 75m					
39635	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	601	608	LHS	Cloth, cable sheath, Entry: Wall in CT.01, Route: Various hangers, 8mmØ to 20mmØ, Exit: WB P-Way. 4 x15m					
38028	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	607		RHS	Trackside equipment: Westinghouse small box		1			
38029	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	608		RHS	Trackside equipment: Westinghouse small box		1			
38030	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	611			Trackside equipment: Electrical box LHS & RHS, OTX		3			
38031	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	612		RHS	Trackside equipment: Westinghouse small box		2			
38032	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	615		RHS	Trackside equipment: Electrical box		1			



Hazardous Material Asset Register - Summary



P054-P - PIC Line - Russell Square to Holborn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38033	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	622	630	RHS	Cloth, cable sheath, Entry: Cable Shaft CS.01, Route: H2 of 8, ~2x8mmØ, 2x15mmØ, H3, 1x8mmØ, 2x20mmØ, H7, 1x15mmØ, Exit: OTX to LHS. 7 x 8m					
38034	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	628	630	LHS	Cloth, cable sheath, Entry: Cable Tunnel CT.01, Route: H1 of 10, ~3x8mmØ, 1x20mmØ, H2, 1x20mmØ, Exit: N/A. 5 x 2m					
38036	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	630	666	LHS	Cloth, cable sheath, Entry: OTX to RHS, Route: H1 of 10, ~4x8mmØ, 2x20mmØ, H2, 1x20mmØ, Exit: N/A. 7 x 36m					
38035	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	630	633	RHS	Cloth, cable sheath, Entry: N/A, Route: H2 of 8, ~2x8mmØ, 2x15mmØ, H3, 1x20mmØ, H7, 1x15mmØ, Exit: Cross Passage CP. 01. 5 x 3m					
38037	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	633	642	RHS	Cloth, cable sheath, Entry: N/A, Route: H4 of 4, 1x15mmØ, Exit: N/A. 1 x 9.5m					
38038	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	635		RHS	Trackside equipment: Westinghouse large box		1			
39777	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	640		RHS	Trackside equipment: Signal (A779C)		1			
38039	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	640		RHS	Trackside equipment: Westinghouse large box		1			
38040	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	641		RHS	Trackside equipment: tencore box		1			
38041	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	642		RHS	Trackside equipment: Westinghouse small box		1			
38043	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	642		RHS	Trackside equipment: tencore box		1			
38042	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	642	666	RHS	Cloth, cable sheath, Entry: Ten Core box, Route: H3 of 4, 1x20mmØ, H4, 1x15mmØ, Exit: OTX to LHS. 2 x 23.5m					
38044	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	666	667	RHS	Cloth, cable sheath, Entry: N/A, Route: H4 of 4, 1x15mmØ, Exit: OTX to LHS. 1 x 1m					
38045	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Signal Boxes	Asbestos	Presumed	666		RHS	Trackside equipment: Rail Gap Ind. Box		1			
39916	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	666	667	RHS	Cloth, cable sheath, Entry: OTX to RHS, Route: H2 of 12, 1x20mmØ, H3, 4x8mmØ, 2x20mmØ, H4, 1x20mmØ, Exit: N/A. 8 x 1m					
38046	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Cable Sheath	Asbestos	Strongly Presumed	667	677	LHS	Cloth, cable sheath, Entry: OTX to RHS, Route: H2 of 12, 1x20mmØ, H3, 4x8mmØ, 3x20mmØ, H4, 1x20mmØ, Exit: Platform wall. 9 x 10.5m					



Hazardous Material Asset Register - Summary



P054-P - PIC Line - Russell Square to Holborn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38047	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	670		RHS	Trackside equipment: Westinghouse small box		1			
38048	ACTIVE	P	P054-P-EBLO	Road EBLO - PIC - Holborn to Russell Square	Westinghouse Boxes	Asbestos	Presumed	674		RHS	Trackside equipment: Westinghouse small box		1			
44342	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Caulking	Asbestos	Sampled – Not Detected				Caulking, West on Westbound road, on right hand side, on T/R No. 1150	590		R615126		
39275	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	0	2	LHS	Cloth. cable sheath, Entry: Platform, Route: H1 of 12, 2x15mmØ, H4, 2x15mmØ, 2x20mmØ, Exit: OTX to RHS. 6 X 2M					
39276	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	2		LHS	Trackside equipment: Red electrical box		1			
39278	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	2	5	RHS	Cloth. cable sheath, Entry: OTX to LHS, Route: H2 of 4, 2x15mmØ, Exit: N/A. 2 x 2.5m					
39277	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	2	5	LHS	Cloth. cable sheath, Entry: N/A, Route: H1 of 8, 2x15mmØ, 2x20mmØ, Exit: OTX to RHS. 4 X 2.5M					
39279	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	5	11	RHS	Cloth. cable sheath, Entry: OTX to LHS, Route: H2 of 4, 2x15mmØ, H4, 2x15mmØ, 2x20mmØ, Exit: Ten Core box. 6 x 6.5m					
39280	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	8		RHS	Trackside equipment: Westinghouse small box		1			
39939	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	8		RHS	Trackside equipment: Rail Gap Ind. Box		1			
39281	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	10		RHS	Trackside equipment: Westinghouse small box		1			
39283	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	11	19	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, 2x15mmØ, H4, 1x15mmØ, 2x20mmØ, Exit: N/A. 5 x 7m					
39282	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	11		RHS	Trackside equipment: Westinghouse small box		1			
39284	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	11		RHS	Trackside equipment: tencore box		1			
39358	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	14		RHS	Signal (A)		1			
39285	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	15		RHS	Trackside equipment: Westinghouse small box		1			
39286	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	15		RHS	Trackside equipment: Westinghouse large box		1			
39288	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	16		RHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P054-P - PIC Line - Russell Square to Holborn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39287	ACTIVE	p	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	16		RHS	Trackside equipment: tencore box		1			
39289	ACTIVE	p	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Presumed	18	19	RHS	plastic, backing plates, to cable termination points. 2 x 0.5m					
39359	ACTIVE	p	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	18		RHS	Trackside equipment: Westinghouse small box		1			
39291	ACTIVE	p	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	19		RHS	Trackside equipment: tencore box		1			
39290	ACTIVE	p	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	19	37	RHS	Cloth. cable sheath, Entry: Ten Core box, Route: H2 of 4, 2x15mmØ, H4, 1x15mmØ, 3x20mmØ, Exit: CP.01. 6 x 18.5m					
39292	ACTIVE	p	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	21		RHS	Trackside equipment: Westinghouse small box		1			
39293	ACTIVE	p	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	22		LHS	Trackside equipment: 630V DC box		1			
39294	ACTIVE	p	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	23		RHS	Trackside equipment: 600 volt box		1			
39295	ACTIVE	p	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	24		RHS	Trackside equipment: Westinghouse large box		1			
39719	ACTIVE	p	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	25		RHS	Trackside equipment: Westinghouse small box					
39296	ACTIVE	p	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	27	28	RHS	Cloth. cable sheath, H2, 1x15mmØ, spliced & mounted below H4. 1 x 1m					
39297	ACTIVE	p	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	30	31	RHS	Cloth. cable sheath, H2, 1x15mmØ, spliced & mounted below H4. 1 x 1m		1			
39298	ACTIVE	p	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	34		RHS	Trackside equipment: Westinghouse large box					
39299	ACTIVE	p	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	37	39	RHS	Cloth. cable sheath, Entry: WB P-way, Route: H1 of 4 (front), 2x15mmØ, H2 of 4 (rear), 1x15mmØ, 3x20mmØ, Exit: EB P-way. 6 x 1.5m					
39301	ACTIVE	p	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Ducts	Asbestos	Known	41		LHS	cement. Cable duct lining, in wall		18			
39300	ACTIVE	p	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Known	41		LHS	Rope packing. To cement cable duct linings in wall. Further packing presumed present behind ducts with metal covers		5			
39302	ACTIVE	p	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	44		RHS	Trackside equipment: grey electrical box		1			



Hazardous Material Asset Register - Summary



P054-P - PIC Line - Russell Square to Holborn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39303	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Known	46		LHS	Rope packing. To cement cable duct linings in wall. To cement cable duct linings in wall. Further packing presumed present behind ducts with metal covers		1			
39304	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Ducts	Asbestos	Known	46		LHS	cement. Cable duct lining, in wall		18			
39305	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	46		RHS	Trackside equipment: Westinghouse small box		2			
39306	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	47		RHS	Trackside equipment: grey electrical box		3			
39940	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	47		RHS	Trackside equipment: grey electrical box		1			
44343	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Caulking	Asbestos	Sampled – Not Detected				Caulking, on right hand side, 48m West on Westbound road			R615126		
39307	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	50	91	RHS	Cloth. cable sheath, Entry: Metal cable duct linings, Route: H2 of 8, 2x8mmØ, H3, 1x20mmØ, H5, 1x8mmØ, H8, 1x15mmØ, Exit: CP. 02. 5 x 41m					
44344	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn		Asbestos	Sampled – Not Detected				Grout to bolt hole, on right hand side, 50m West on Westbound road			R615126		
39308	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	55		RHS	Trackside equipment: Westinghouse small box		1			
39309	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	81		RHS	Trackside equipment: Westinghouse small box		1			
39310	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	82		RHS	Trackside equipment: Westinghouse small box		1			
39311	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	91	134	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, 2x8mmØ, Exit: N/A. 2 x 43m					
39360	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	91	94	RHS	Cloth. cable sheath, Entry: WB P-way, Route: H1 of 4, 1x20mmØ, 1x8mmØ, H4, 1x15mmØ, Exit: EB P-way. 3 x 1.5m					
39312	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	91	94	RHS	Cloth. cable sheath, Entry: H1 on LHS, Route: H1 of 1, 1x20mmØ, Exit: EB P-way. 1 x 1.5m					
39313	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	133		RHS	Trackside equipment: Signal (R770A)		1			
39315	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	134	140	RHS	Cloth. cable sheath, Entry: Spliced cable, Route: H2 of 4, 2x8mmØ, H4, 1x30mmØ, Exit: Westinghouse large box. 3 x 5.5m					
39314	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	134		RHS	Trackside equipment: Signal (A7781)		1			



Hazardous Material Asset Register - Summary



P054-P - PIC Line - Russell Square to Holborn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39316	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	135		RHS	Trackside equipment: Westinghouse small box		1			
39317	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	135		RHS	Trackside equipment: tencore box		1			
39318	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	136		RHS	Trackside equipment: Westinghouse small box		1			
39319	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	138		RHS	Trackside equipment: Westinghouse large box		1			
39320	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	139		RHS	Trackside equipment: Westinghouse large box		1			
39720	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	140		RHS	Trackside equipment: Westinghouse large box		2			
39322	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	140		RHS	Trackside equipment: Westinghouse small box		1			
39321	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	140	142	RHS	Cloth. cable sheath, Entry: Westinghouse large box, Route: H2 of 4, 2x8mmØ, H4, 1x30mmØ, Exit: N/A. 3 x 2m					
39323	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	141		RHS	Trackside equipment: Westinghouse large box		1			
39325	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	142		RHS	Trackside equipment: tencore box		1			
39324	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	142	143	RHS	Cloth. cable sheath, Entry: Ten Core box, Route: H2 of 4, 1x15mmØ, 2x8mmØ, H4, 1x30mmØ, Exit: Spliced cable. 4 x 1m					
39326	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	143	404	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 4, 1x15mmØ, 2x8mmØ, Exit: N/A. 3 x 261m					
39327	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	145		RHS	Trackside equipment: Westinghouse small box		1			
39328	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	255	256	RHS	Cloth. cable sheath, H2, 1x8mmØ, spliced & mounted below H4. 1 x 1m					
39329	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	309		RHS	Trackside equipment: Westinghouse small box		1			
39330	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	318		RHS	Trackside equipment: Westinghouse small box		1			
39331	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	350		RHS	Trackside equipment: main earth terminal box		1			
39332	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	377		RHS	Trackside equipment: type 79 box		1			



Hazardous Material Asset Register - Summary



P054-P - PIC Line - Russell Square to Holborn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39941	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	402		RHS	Trackside equipment: Signal (R770BC)		1			
39333	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	402		RHS	Trackside equipment: Signal (A770)		1			
39361	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	403		RHS	Trackside equipment: tencore box		1			
39335	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	403	406	RHS	Cloth. cable sheath, Entry: Ten Core box, Route: H2 of 4, 2x15mmØ, 2x8mmØ, Exit: N/A. 4 x 2.5m					
39334	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	403		RHS	Trackside equipment: Westinghouse large box		1			
39336	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	404		RHS	Trackside equipment: Westinghouse large box		1			
39337	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	404		RHS	Trackside equipment: tencore box		1			
39338	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	405		RHS	Trackside equipment: Westinghouse small box		1			
39362	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	406		RHS	Trackside equipment: tencore box		1			
39339	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	406	466		Cloth. cable sheath, Entry: Ten Core box, Route: H2 of 4, 3x15mmØ, 2x8mmØ, Exit: N/A. 5 x 60.5m					
39135	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	435		RHS	Trackside equipment: Westinghouse small box		1			
39136	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	440		RHS	Trackside equipment: Westinghouse small box		1			
39137	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	462		RHS	Trackside equipment: Signal (R770C)		1			
39138	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	463		RHS	Trackside equipment: Signal (A770B)		1			
39910	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	464		RHS	Trackside equipment: Westinghouse large box		1			
39139	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	465		RHS	Trackside equipment: tencore box		1			
39140	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	465		RHS	Trackside equipment: Westinghouse large box		1			
39143	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	466		RHS	Trackside equipment: tencore box		1			
39141	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	466		RHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P054-P - PIC Line - Russell Square to Holborn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39142	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	466	527	RHS	Cloth. cable sheath, Entry: Ten Core box, Route: H2 of 8, 3x15mmØ, 2x8mmØ, H5, 1x15mmØ, Exit: N/A. 6 x 61m					
39144	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	476		RHS	Trackside equipment: Westinghouse small box		1			
39145	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	480		RHS	Trackside equipment: Westinghouse small box		1			
39146	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	524		RHS	Trackside equipment: Signal (A770C)		1			
39147	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	525		RHS	Trackside equipment: Westinghouse large box		1			
39149	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	526		RHS	Trackside equipment: Westinghouse small box		1			
39148	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	526		RHS	Trackside equipment: tencore box		1			
39150	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	527	568	RHS	Cloth. cable sheath, Entry: Ten Core box, Route: H2 of 8, 3x15mmØ, 2x8mmØ, H5, 2x15mmØ, Exit: Ten Core box. 7 x 41m					
39151	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	527		RHS	Trackside equipment: tencore box		1			
39715	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	558		RHS	Trackside equipment: Westinghouse small box		1			
39152	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	563		RHS	Trackside equipment: Westinghouse small box		1			
39153	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	568	577	RHS	Cloth. cable sheath, Entry: Ten Core box, Route: H2 of 8, 3x15mmØ, 2x8mmØ, H5, 2x15mmØ, Exit: Ten Core box. 7 x 9m					
39154	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	568		RHS	Trackside equipment: tencore box		1			
39155	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	577		RHS	Trackside equipment: tencore box		1			
39348	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	577	579		Cloth. cable sheath, Entry: Ten Core box, Route: H2 of 8, 3x15mmØ, 2x8mmØ, H5, 2x15mmØ, Exit: Ten Core box. 7 x 2m					
39157	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Signal Boxes	Asbestos	Presumed	579		RHS	Trackside equipment: tencore box		1			
39156	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	579	587	RHS	Cloth. cable sheath, Entry: Ten Core box, Route: H2 of 8, 3x15mmØ, 2x8mmØ, H5, 2x15mmØ, Exit: Ten Core box. 7 x 7.5m					



Hazardous Material Asset Register - Summary



P054-P - PIC Line - Russell Square to Holborn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39158	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	587	630	RHS	Cloth. cable sheath, Entry: Ten Core, Route: H2 of 8, 3x15mmØ, 2x8mmØ, H5, 2x15mmØ, Exit: Westinghouse large box. 7 x 43.5m					
39159	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	610	611	RHS	Cloth. cable sheath, H2, 1x8mmØ, spliced & mounted below H8. 1 x 1m					
43428	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Duct: Other	Asbestos	Presumed				Braided cable, 1 no 5m, to cable run on LHS going in to 4 foot BRS 617 - 622 on Westbound Piccadilly Line - Russell Square to Holborn	5		R564276	N	N
39911	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	618		RHS	Trackside equipment: Westinghouse small box		1			
40487	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Westinghouse Boxes	Asbestos	Presumed	623		RHS	Trackside equipment: Westinghouse small box		1			
43429	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn		Asbestos	Presumed				Braided cables, 6 no, to running rail in 4 foot on RHS BRS625 on Westbound Piccadilly Line - Russell Square to Holborn.	6		R564276	N	N
39732	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	627	628	RHS	Cloth. cable sheath, H2, 1x8mmØ, spliced & mounted below H8. 1 x1m					
40489	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	630	633	LHS	Cloth. cable sheath, Entry: OTX to RHS, Route: H3 of 8, 5x15mmØ, Exit: N/A. 5 x 2.5m					
40488	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	630	633	RHS	Cloth. cable sheath, Entry: N/A, Route: H2 of 8, 2x8mmØ, Exit: OTX to LHS. 2 x 2.5m					
40490	ACTIVE	P	P054-P-WBLO	Road WBLO - PIC - Russell Square to Holborn	Cable Sheath	Asbestos	Strongly Presumed	633	634	LHS	Cloth. cable sheath, Entry: OTX to RHS, Route: H3 of 11, 5x15mmØ, 2x8mmØ, Exit: Platform wall. 7 x 1.5m					

P055-P - PIC Line - Holborn Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38085	ACTIVE	P	P055-P-EBLO	Road EBLO (Plt4) - PIC - Holborn Stn	Westinghouse Boxes	Asbestos	Presumed				Trackside equipment: Westinghouse small box					
42746	ACTIVE	P	P055-P-EBLO	Road EBLO (Plt4) - PIC - Holborn Stn	Pit Blocks	Asbestos	Surveyed – Not Detected				Pit blocks - Non asbestos					
44143	ACTIVE	P	P055-P-EBLO	Road EBLO (Plt4) - PIC - Holborn Stn	Cable Sheath	Asbestos	Presumed				Jumper cable sheath. While no asbestos cables have been identified, a buried asbestos jumper cable was identified on platform 3 (Maximo Reference 44135) and there is grounds to presume a similar jumper cable may be present on this platform. R.A.S					
42749	ACTIVE	P	P055-P-SLLO	Road SLLO (Plt5) - PIC - Holborn Stn	Pit Blocks	Asbestos	Surveyed – Not Detected				Pit block - Non asbestos					



Hazardous Material Asset Register - Summary



P055-P - PIC Line - Holborn Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44144	ACTIVE	p	P055-P-SLLO	Road SLLO (Plt5) - PIC - Holborn Stn	Cable Sheath	Asbestos	Presumed				Jumper cable sheath. While no asbestos cables have been identified, a buried asbestos jumper cable was identified on platform 3 (Maximo Reference 44135) and there is grounds to presume a similar jumper cable may be present on this platform. R.A.S					
54002	ACTIVE	p	P055-P-SLLO	Road SLLO (Plt5) - PIC - Holborn Stn	Other Electrical Boxes	Asbestos	Presumed				630V DC Electrical		1			
38086	ACTIVE	p	P055-P-SLLO	Road SLLO (Plt5) - PIC - Holborn Stn	Westinghouse Boxes	Asbestos	Presumed				Trackside equipment: Westinghouse small box					
42744	ACTIVE	p	P055-P-WBLO	Road WBLO (Plt3) - PIC - Holborn Stn	Pit Blocks	Asbestos	Surveyed – Not Detected				Pit blocks - Non asbestos					
44135	ACTIVE	p	P055-P-WBLO	Road WBLO (Plt3) - PIC - Holborn Stn	Cable Sheath	Asbestos	Strongly Presumed	60			Jumper cable sheath buried within concrete at approx. 60m Cable identified during track works.	0	1			
39779	ACTIVE	p	P055-P-WBLO	Road WBLO (Plt3) - PIC - Holborn Stn	Westinghouse Boxes	Asbestos	Presumed	60		LHS	Trackside equipment: Westinghouse small box		1			
38082	ACTIVE	p	P055-P-WBLO	Road WBLO (Plt3) - PIC - Holborn Stn	Westinghouse Boxes	Asbestos	Presumed	64		LHS	Trackside equipment: Westinghouse small box		1			
38083	ACTIVE	p	P055-P-WBLO	Road WBLO (Plt3) - PIC - Holborn Stn	Signal Boxes	Asbestos	Presumed	89		LHS	Trackside equipment: 630V DC		1			
38084	ACTIVE	p	P055-P-WBLO	Road WBLO (Plt3) - PIC - Holborn Stn	Signal Boxes	Asbestos	Presumed	106		LHS	Trackside equipment: Redifon aerial loop		1			

P056-P - PIC Line - Holborn to Covent Garden

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37441	ACTIVE	p	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Cable Sheath	Asbestos	Known	0		RHS	Cloth. cable sheath, Route: JH 1x25mm, JH2 1x20mm, 1x30mm, 5x15mm		8			
44156	ACTIVE	p	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Westinghouse Boxes	Asbestos	Strongly Presumed	5	11		Trackside equipment strongly presumed to contain asbestos insulating materials within					
37442	ACTIVE	p	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Cable Sheath	Asbestos	Known	6	11		Cloth. cable sheath, Route: Between JH2-JH4 & Trackside Equipment 15-30mm. Numerous amounts RHS/UTX					
37443	ACTIVE	p	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Cable Sheath	Asbestos	Known	11			Cloth. cable sheath, Route: JH2 1x20mm, 1x15mm, JH3 1x20mm, 1x15mm, Exit: Trackside Equipment RHS/UTX		4			
37445	ACTIVE	p	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Cable Sheath	Asbestos	Known	48	78	LHS	Cloth. cable sheath, Route: On JH's at high level. Numerous amounts					



Hazardous Material Asset Register - Summary



P056-P - PIC Line - Holborn to Covent Garden

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37444	ACTIVE	p	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Cable Sheath	Asbestos	Known	48		OTX	Cloth. cable sheath, Route: Restricted access due to height. Numerous amounts					
39707	ACTIVE	p	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Cable Sheath	Asbestos	Known	78		OTX	Cloth. cable sheath, Numerous amounts					
37446	ACTIVE	p	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Cable Sheath	Asbestos	Known	109		RHS	Cloth. cable sheath, Entry: Westinghouse small box small, Route: Gaining 1x15mm JH2		7			
44157	ACTIVE	p	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Westinghouse Boxes	Asbestos	Strongly Presumed	109			Trackside equipment strongly presumed to contain asbestos insulating materials within					
44158	ACTIVE	p	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Westinghouse Boxes	Asbestos	Strongly Presumed	112			Trackside equipment strongly presumed to contain asbestos insulating materials within Notes from 2022 re-inspection: 2no LWB					
37447	ACTIVE	p	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Cable Sheath	Asbestos	Known	112		RHS	Cloth. cable sheath, Entry: Westinghouse small box large, Route: JH4 1x45mm Gaining		9			
37448	ACTIVE	p	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Cable Sheath	Asbestos	Known	148	156	RHS	Cloth. cable sheath, Route: Between JH2-JH4 & Trackside Equipment 15-45mm, Exit: Trackside Equipment. Numerous amounts					
44159	ACTIVE	p	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Westinghouse Boxes	Asbestos	Strongly Presumed	148	156		Trackside equipment: Electrical box strongly presumed to contain asbestos insulating materials within					
37449	ACTIVE	p	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Cable Sheath	Asbestos	Known	156		RHS	Cloth. cable sheath, Route: JH2 1x15mm, 2x20mm, JH3 1x3mm, JH 1x45mm, 1x25mm		6			
44160	ACTIVE	p	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Westinghouse Boxes	Asbestos	Strongly Presumed	308	310		Trackside equipment strongly presumed to contain asbestos insulating materials within					
37450	ACTIVE	p	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Cable Sheath	Asbestos	Known	308	310	RHS	Cloth. cable sheath, Route: Between JH2-JH4 & Trackside Equipment, Exit: Trackside Equipment. Numerous amounts					
37451	ACTIVE	p	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Cable Sheath	Asbestos	Known	310		RHS	Cloth. cable sheath, Route: JH2 2x20mm, 3x15mm, JH3 1x20mm, 1x30mm, JH4 1x25mm, 1x45mm		9			
44161	ACTIVE	p	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Westinghouse Boxes	Asbestos	Strongly Presumed	325			Trackside equipment strongly presumed to contain asbestos insulating materials within					
37452	ACTIVE	p	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Cable Sheath	Asbestos	Known	325		RHS	Cloth. cable sheath, Route: Gaining JH2 1x15mm		10			
44162	ACTIVE	p	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Westinghouse Boxes	Asbestos	Strongly Presumed	330			Trackside equipment strongly presumed to contain asbestos insulating materials within					
37453	ACTIVE	p	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Cable Sheath	Asbestos	Known	330		RHS	Cloth. cable sheath, Route: Losing JH2 1x15mm		9			
46154	ACTIVE	p	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Other Electrical Boxes	Asbestos	Strongly Presumed				Trackside equipment: Electrical box				N	N



Hazardous Material Asset Register - Summary



P056-P - PIC Line - Holborn to Covent Garden

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37454	ACTIVE	P	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Cable Sheath	Asbestos	Known	347		RHS	Cloth. cable sheath, Route: Gaining JH2 1x15mm		10			
44163	ACTIVE	P	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Westinghouse Boxes	Asbestos	Strongly Presumed	361	372		Trackside equipment strongly presumed to contain asbestos insulating within					
37455	ACTIVE	P	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Cable Sheath	Asbestos	Known	361	372	RHS	Cloth. cable sheath, Route: Between JH2-JH4 & Trackside Equipment. Numerous amounts					
37456	ACTIVE	P	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Cable Sheath	Asbestos	Known	372		RHS	Cloth. cable sheath, Entry: Trackside Equipment, Route: JH2 2x20mm, 3x15mm, JH2 2x25mm, 1x20mm, JH4 1x45mm, 1x20mm		15			
44164	ACTIVE	P	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Westinghouse Boxes	Asbestos	Strongly Presumed	423			Trackside equipment strongly presumed to contain asbestos insulating materials within					
37457	ACTIVE	P	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Cable Sheath	Asbestos	Known	423		RHS	Telephone Box/cloth. cable sheath, Entry: Telephone box, Route: Gaining 1x15mm JH2		16			
44165	ACTIVE	P	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Westinghouse Boxes	Asbestos	Strongly Presumed	424	435		Trackside equipment strongly presumed to contain asbestos insulating materials within					
37458	ACTIVE	P	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Cable Sheath	Asbestos	Known	424	435	RHS	Cloth. cable sheath, Route: Between Trackside Equipment & JH2-JH4. numerous amounts					
37459	ACTIVE	P	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Cable Sheath	Asbestos	Known	435			Cloth. cable sheath, Route: JH2 2x20mm, 11x15mm, JH3 3x30mm, 2x20mm, JH4 1x45mm, 1x25mm					
39595	ACTIVE	P	P056-P-EBLO	Road EBLO - PIC - Covent Garden to Holborn	Cable Sheath	Asbestos	Known	440			Cloth. cable sheath					
37872	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	0	3	LHS	Cloth, cable sheath. Entry: Platform, Route: H2 of 3, 25mmØ, 2x15mmØ, Exit: OTX. 3 x 2.5m					
39883	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	3		OTX	Cloth, cable sheath. 1x25mmØ. 1 x 4m					
39629	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	3	3	LHS	Cloth, cable sheath. Entry: OTX, Route: H4 of 4, 2x15mmØ, Exit: N/A, 2 x 0.5m					
37873	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	3	3	LHS	Cloth, cable sheath. Entry: N/A, Route: H1 of 7, 1x25mmØ, Exit: OTX. 1 x 0.5m					
37875	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	3	11	RHS	Cloth, cable sheath, Entry: OTX, Route: H2 of 4, 1x25mmØ, H4, 2x15mmØ, Exit: Ten Core box. 3 x 6.5m					
37874	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	3		OTX	Cloth, cable sheath. 2x15mmØ, 2 x 4m					
37877	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Signal Boxes	Asbestos	Presumed	11		RHS	Trackside equipment: tencore box		1			
37876	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	11	141	RHS	Cloth, cable sheath, Entry: N/A, Route: H4 of 4, 2x15mmØ, Exit: N/A. 2 x 130.5m					
39770	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	13		RHS	Trackside equipment: Westinghouse large box		1			



Hazardous Material Asset Register - Summary



P056-P - PIC Line - Holborn to Covent Garden

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37878	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Signal Boxes	Asbestos	Presumed	13		RHS	Trackside equipment: Signal (A768)		1			
37879	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	14		RHS	Trackside equipment: Westinghouse small box		1			
37880	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	15		RHS	Trackside equipment: Westinghouse small box		1			
37882	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	16		RHS	Trackside equipment: Westinghouse small box		1			
37881	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Signal Boxes	Asbestos	Presumed	16		RHS	Trackside equipment: tencore box		1			
37883	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	20		RHS	Trackside equipment: Westinghouse small box		1			
37884	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Signal Boxes	Asbestos	Presumed	47		RHS	Trackside equipment: type 79		1			
37885	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	72		RHS	Trackside equipment: Westinghouse small box		1			
37886	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	75		RHS	Trackside equipment: Westinghouse small box		1			
39630	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	141	142	RHS	Cloth, cable sheath, Entry: Signal, Route: H4 of 4, 2x15mmØ, below Signal, 2x8mmØ, Exit: Westinghouse large box. 4 x 1m					
37887	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Signal Boxes	Asbestos	Presumed	141		RHS	Trackside equipment: Signal (A7681)					
37888	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Signal Boxes	Asbestos	Presumed	142		RHS	Trackside equipment: tencore box		1			
37890	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	142	143	RHS	Cloth, cable sheath, Entry: Westinghouse large box & Ten Core box, Route: H4 of 4, 2x15mmØ, below Westinghouse large box, 4x8mmØ, 1x15mmØ, Exit: Westinghouse small box. 7 x 0.5m					
37889	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	142		RHS	Trackside equipment: Westinghouse large box		1			
37892	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	143	143	RHS	Cloth, cable sheath, Entry: N/A, Route: H3 of 4, 1x15mmØ, H4, 2x15mmØ, below Ten Core box, 3x8mmØ, Exit: Ten Core box. 6 x 0.5m					
37891	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	143		RHS	Trackside equipment: Westinghouse small box		1			
37894	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	143	146	RHS	Cloth, cable sheath, Entry: N/A, Route: H3 of 4, 1x15mmØ, H4, 2x15mmØ, Exit: N/A. 3 x 2.5m					



Hazardous Material Asset Register - Summary



P056-P - PIC Line - Holborn to Covent Garden

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37893	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Signal Boxes	Asbestos	Presumed	143		RHS	Trackside equipment: tencore box		1			
37895	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	146	148	RHS	Cloth, cable sheath, Entry: H5 Spliced cable, Route: H3 of 5, 1x15mmØ, H4, 2x15mmØ, H5, 1x30mmØ, Exit: H5 Spliced cable. 4 x 2.5m					
37896	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	148	268	RHS	Cloth, cable sheath, Entry: N/A, Route: H3 of 4, 1x15mmØ, H4, 2x15mmØ, Exit: N/A. 3 x 120m					
37897	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	150		RHS	Trackside equipment: Westinghouse small box		1			
39884	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	155		RHS	Trackside equipment: Westinghouse small box		1			
37898	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Signal Boxes	Asbestos	Presumed	239		RHS	Trackside equipment: Main earth terminal		1			
39771	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Signal Boxes	Asbestos	Presumed	268		RHS	Trackside equipment: Signal (A764)		1			
37899	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Wrap	Asbestos	Strongly Presumed	268	269	RHS	Cloth, cable sheath, Entry: Signal, Route: H3 of 4, 1x15mmØ, H4, 2x15mmØ, Below Signal, 2x8mmØ, Exit: Westinghouse large box. 5 x 1m					
37902	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	269	270	RHS	Cloth, cable sheath, Entry: Westinghouse large box & Ten Core box, Route: H2 of 4, 1x8mmØ, 2x4mmØ, H3, 2x15mmØ, H4, 2x15mmØ, Below Westinghouse large box, 4x8mmØ, Exit: Westinghouse small box & Ten Core box. 11 x 1m					
37900	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Signal Boxes	Asbestos	Presumed	269		RHS	Trackside equipment: tencore box		1			
37901	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	269		RHS	Trackside equipment: Westinghouse large box		1			
37904	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	270	271	RHS	Cloth, cable sheath, Entry: N/A, Route: H2 of 4, 1x8mmØ, H3, 2x15mmØ, H4, 2x15mmØ, Exit: Westinghouse small box & Unknown. 5 x 1m					
39631	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	270		RHS	Trackside equipment: Westinghouse small box		1			
37903	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Signal Boxes	Asbestos	Presumed	270		RHS	Trackside equipment: tencore box		1			
37905	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	271		RHS	Trackside equipment: Westinghouse small box		1			
37906	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	271		RHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P056-P - PIC Line - Holborn to Covent Garden

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37907	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	271	323	RHS	Cloth, cable sheath, Entry: N/A, Route: H3 of 4, 2x15mmØ, H4, 2x15mmØ, Exit: N/A. 4 x 52m					
37908	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	275		RHS	Trackside equipment: Westinghouse small box		1			
37909	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	290		RHS	Trackside equipment: Westinghouse large box		2			
37911	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Signal Boxes	Asbestos	Presumed	323		RHS	Trackside equipment: Signal (R760A)		1			
37910	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	323	324	RHS	Cloth, cable sheath, Entry: Signal, Route: H3 of 4, 2x15mmØ, H4, 2x15mmØ, Below Signal, 2x8mmØ, Exit: Westinghouse large box. 6 x 0.5m					
37913	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	324	380	RHS	Cloth, cable sheath, Entry: N/A, Route: H3 of 4, 2x15mmØ, H4, 2x15mmØ, Below Westinghouse large box, 4x8mmØ, Exit: N/A. 4 x 56.5m					
37912	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	324		RHS	Trackside equipment: Westinghouse large box		1			
37914	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	324		RHS	Cloth, cable sheath, 4mmØ from Westinghouse large box to H1 only. 1 x 1m					
39772	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	356		RHS	Trackside equipment: Westinghouse small box		1			
37915	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	357		RHS	Trackside equipment: Westinghouse small box		1			
37917	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	380	381	RHS	Cloth, cable sheath, Entry: Westinghouse large box, Route: H3 of 4, 2x15mmØ, H4, 2x15mmØ, Below Westinghouse large box, 1x4mmØ, 4x8mmØ, Exit: N/A. 9 x1m					
37916	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	380		RHS	Trackside equipment: Westinghouse large box		1			
37918	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Signal Boxes	Asbestos	Presumed	381		RHS	Trackside equipment: tencore box		1			
37919	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	381		RHS	Trackside equipment: Westinghouse large box		1			
37920	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	381	382	RHS	Cloth, cable sheath, Entry: Westinghouse large box & Ten Core box, Route: H3 of 4, 1x20mmØ, 2x15mmØ, +9x8mmØ, 1x4mmØ, H4, 2x15mmØ, Below Westinghouse large box, 4x8mmØ, Exit: Westinghouse small box (x2). +19x0.5m					



Hazardous Material Asset Register - Summary



P056-P - PIC Line - Holborn to Covent Garden

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37922	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	382		RHS	Cloth, cable sheath debris, Remnants of cut cables in brackets to side of Westinghouse small box. 8 x 0.1m					
39885	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	382	384	RHS	Cloth, cable sheath, Entry: N/A, Route: H3 of 4, 1x20mmØ, 2x15mmØ, +7x8mmØ, 1x4mmØ, H4, 2x15mmØ, Exit: Westinghouse small box & Ten Core box. '+13x0.5m					
37921	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	382		RHS	Trackside equipment: Westinghouse small box		2			
37923	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Signal Boxes	Asbestos	Presumed	382		LHS	Trackside equipment: Signal (A760)		1			
37925	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	384		RHS	Trackside equipment: Westinghouse small box		1			
37926	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	384	406	RHS	Cloth, cable sheath, Entry: N/A, Route: H3 of 4, 1x20mmØ, H4, 2x15mmØ, Exit: OTX. 5 x 22m					
37924	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Signal Boxes	Asbestos	Presumed	384		RHS	Trackside equipment: tencore box		1			
37927	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	388		RHS	Trackside equipment: Westinghouse large box		1			
39773	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	406		RHS	Trackside equipment: Westinghouse small box		1			
39419	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	406	437	LHS	cloth, cable sheath. Presumed cables as RHS on high level hangers (H1 of 10, 2x15mmØ, H2, 1x20mmØ & 2x15mmØ) 5 x 31m					
37928	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Presumed	406		RHS	Cloth, cable sheath. Presumed cables as RHS on high level OTX (1x20mmØ & 4x15mmØ) 5 x 6m					
37929	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	412		LHS	Trackside equipment: Westinghouse small box		1			
37930	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	437		RHS	Cloth, cable sheath. Presumed cables as RHS on high level OTX (1x20mmØ & 4x15mmØ) 5 x 6m					
37931	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	437	478	RHS	Cloth, cable sheath. Entry: OTX, Route: H3 of 4, 1x20mmØ, 2x15mmØ, H4, 2x15mmØ, Exit: N/A. 5 x 41m					
37932	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	476		RHS	Trackside equipment: Westinghouse large box		2			
37933	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	478	482	RHS	Cloth, cable sheath. Entry: N/A, Route: H3 of 5, 1x20mmØ, 2x15mmØ, H4, 2x15mmØ, H5, 1x15mmØ, Exit: N/A. 5 x 4m					
37935	ACTIVE	P	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	482	483	RHS	Cloth, cable sheath. Entry: Signal, Route: H3 of 4, 1x20mmØ, 2x15mmØ, H4, 2x15mmØ, Below Signal, 2x8mmØ, Exit: Westinghouse large box. 7 x 1m					



Hazardous Material Asset Register - Summary



P056-P - PIC Line - Holborn to Covent Garden

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37934	ACTIVE	p	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Signal Boxes	Asbestos	Presumed	482		RHS	Trackside equipment: Signal (A760B)		1			
37936	ACTIVE	p	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Signal Boxes	Asbestos	Presumed	483		RHS	Trackside equipment: tencore box		1			
37937	ACTIVE	p	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	483		RHS	Trackside equipment: Westinghouse large box		1			
37938	ACTIVE	p	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	483	484	RHS	Cloth, cable sheath. Entry: Westinghouse large box & Ten Core box, Route: H3 of 4, 1x20mmØ, 3x15mmØ, 1x8mmØ, 3x4mmØ, H4, 2x15mmØ, Below Westinghouse large box, 7x8mmØ, Exit: Westinghouse small box, Ten Core box & Unknown. '+18x1m					
37940	ACTIVE	p	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	484		RHS	Trackside equipment: Westinghouse small box		1			
37941	ACTIVE	p	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	484	493	RHS	Cloth, cable sheath, Entry: N/A, Route: H2 of 4, 1x8mmØ, H3, 1x20mmØ, 3x15mmØ, H4, 2x15mmØ, Exit: Westinghouse small box. 7 x 9m					
37939	ACTIVE	p	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Signal Boxes	Asbestos	Presumed	484		RHS	Trackside equipment: tencore box		1			
37942	ACTIVE	p	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	488		RHS	Trackside equipment: Westinghouse small box		1			
39886	ACTIVE	p	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	493	496	RHS	Cloth, cable sheath,Entry: N/A, Route: H3 of 4, 1x20mmØ, 3x15mmØ, H4, 2x15mmØ, Exit: Platform. 6 x 3m					
37943	ACTIVE	p	P056-P-WBLO	Road WBLO - PIC - Holborn to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	493		RHS	Trackside equipment: Westinghouse small box		1			

P057-P - PIC Line - Covent Garden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42732	ACTIVE	p	P057-P-EBLO	Road EBLO (Plt2) - PIC - Covent Garden Stn	Pit Blocks	Asbestos	Surveyed – Not Detected				Pit block - Non asbestos					
37495	ACTIVE	p	P057-P-EBLO	Road EBLO (Plt2) - PIC - Covent Garden Stn	Westinghouse Boxes	Asbestos	Presumed				Trackside equipment: Westinghouse small box throughout					
42733	ACTIVE	p	P057-P-WBLO	Road WBLO (Plt1) - PIC - Covent Garden Stn	Pit Blocks	Asbestos	Surveyed – Not Detected				Pit blocks - Non asbestos					
37488	ACTIVE	p	P057-P-WBLO	Road WBLO (Plt1) - PIC - Covent Garden Stn	Ducts	Asbestos	Presumed	1		LHS	cement. Cable duct lining,Presumed present beneath firestopping		5			
37489	ACTIVE	p	P057-P-WBLO	Road WBLO (Plt1) - PIC - Covent Garden Stn	Westinghouse Boxes	Asbestos	Presumed	44		RHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P057-P - PIC Line - Covent Garden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39710	ACTIVE	P	P057-P-WBLO	Road WBLO (Plt1) - PIC - Covent Garden Stn	Westinghouse Boxes	Asbestos	Presumed	47		RHS	Trackside equipment: Westinghouse small box		1			
37490	ACTIVE	P	P057-P-WBLO	Road WBLO (Plt1) - PIC - Covent Garden Stn	Westinghouse Boxes	Asbestos	Presumed	48		RHS	Trackside equipment: Westinghouse small box		1			
37491	ACTIVE	P	P057-P-WBLO	Road WBLO (Plt1) - PIC - Covent Garden Stn	Westinghouse Boxes	Asbestos	Presumed	75		RHS	Trackside equipment: Westinghouse small box		1			
37492	ACTIVE	P	P057-P-WBLO	Road WBLO (Plt1) - PIC - Covent Garden Stn	Westinghouse Boxes	Asbestos	Presumed	79		RHS	Trackside equipment: Westinghouse small box		1			
37493	ACTIVE	P	P057-P-WBLO	Road WBLO (Plt1) - PIC - Covent Garden Stn	Signal Boxes	Asbestos	Presumed	88		RHS	Trackside equipment: 630V DC		1			
37494	ACTIVE	P	P057-P-WBLO	Road WBLO (Plt1) - PIC - Covent Garden Stn	Signal Boxes	Asbestos	Presumed	104		RHS	Trackside equipment: Redifon aerial loop		1			

P058-P - PIC Line - Covent Garden to Leicester Square

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38510	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	0	1	RHS	Bitumen, cable sheath, Entry: Platform wall, Route: H4 of 8, 1x15mmØ, H6, 1x8 mmØ, H7, ~13x8mmØ, 1x15mmØ, Exit: Westinghouse large box. 16 x 1m					
38511	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Ducts	Asbestos	Presumed	0		RHS	Cementitious, cable duct lining. Presumed present (in platform wall & sealed)		3			
38513	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	1		RHS	Trackside equipment: Westinghouse large box		1			
38512	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	1	8	RHS	Cloth cable sheath. Entry: Westinghouse large box, Route: H4 of 8, 1x15mmØ, H6, 1x8 mmØ, H7, ~13x8mmØ, 1x15mmØ, Exit: Signals trackside equipment. 16 x 7m					
38514	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Signal Boxes	Asbestos	Presumed	3		RHS	Trackside equipment: Current online relay box		1			
39975	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	8	10	RHS	Cloth cable sheath. Entry: N/A, Route: Between trackside equipment, H4, H6 & H7, 8mmØ to 15mmØ. Numerous amounts					
38515	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	8		RHS	Cloth cable sheath. Train stop cable at floor level. 0.25m					
38516	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	8		RHS	Trackside equipment: Westinghouse large box		1			
39672	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Signal Boxes	Asbestos	Presumed	9		RHS	Trackside equipment: Signal (A759A)		1			



Hazardous Material Asset Register - Summary



P058-P - PIC Line - Covent Garden to Leicester Square

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38518	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Signal Boxes	Asbestos	Presumed	10		RHS	Trackside equipment: tencore box		1			
38517	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	10	11	RHS	Cloth cable sheath. Entry: Signals trackside equipment, Route: H4 of 8, 1x15mmØ, H6, 1x8 mmØ, H7, 3x8mmØ, 1x15mmØ, Exit: OTX to LHS. 6 x 1m					
38520	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	10		RHS	Trackside equipment: Westinghouse small box		1			
38519	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	10		RHS	Trackside equipment: Westinghouse small box		1			
38521	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	11		LHS	Cloth cable sheath. Entry: RHS, Route: OTX, 1x8mmØ, Exit: Rail Gap Indicator. 1 x 4m					
38522	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	11		RHS	Trackside equipment: Westinghouse small box		1			
38523	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Signal Boxes	Asbestos	Presumed	11		LHS	Trackside equipment: Rail Gap Indicator		1			
39976	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	11	15	RHS	Cloth cable sheath. Entry: N/A, Route: H4 of 8, 1x15mmØ, H6, 1x8 mmØ, H7, 2x8mmØ, 1x15mmØ, Exit: Westinghouse small box. 5 x 4m					
38524	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Signal Boxes	Asbestos	Presumed	13		LHS	Trackside equipment: 630V DC box		1			
38528	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	15	94	RHS	Cloth cable sheath. Entry: N/A, Route: H4 of 8, 1x15mmØ, H6, 1x8 mmØ, H7, 1x8mmØ, 1x15mmØ, Exit: N/A, 4 x 79m					
38526	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Cable Sheath	Asbestos	Presumed	15	16	LHS	Plastic, backing panel. Presumed asbestos at HV cable termination points, 2x0.5m					
38527	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Cement Cable Troughing & Debris	Asbestos	Removed	15	16		Cementitious. cable troughing, On floor for HV cables. 2x0.5m LHS & UTX Removed					
38525	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	15	16	LHS	Cementitious, soffit. Above HV cable termination points, 2x0.5m²					
38529	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	15		RHS	Trackside equipment: Westinghouse small box		1			
39673	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	16	19	RHS	Cloth cable sheath. In cleats below H8, 2 x 5m					
38530	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Cement Cable Troughing & Debris	Asbestos	Strongly Presumed	18		LHS	Cementitious. cable troughing, on floor. 2x0.5m					
38531	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Cable Sheath	Asbestos	Presumed	76		RHS	Trackside equipment: Main earth terminal box		1			
38533	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Signal Boxes	Asbestos	Presumed	94		RHS	Trackside equipment: Signal (R759C)		1			



Hazardous Material Asset Register - Summary



P058-P - PIC Line - Covent Garden to Leicester Square

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38532	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	94	99	RHS	Cloth cable sheath. Entry: Signal, Route: H4 of 8, 1x15mmØ, H6, 3x8 mmØ, H7, 1x8mmØ, 1x15mmØ, Exit: Signals trackside equipment. 6 x 5m					
38535	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Signal Boxes	Asbestos	Presumed	99		RHS	Trackside equipment: Signal (A759B)		1			
38534	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	99	101	RHS	Cloth cable sheath. Entry: N/A, Route: Between trackside equipment, H4, H6 & H7, 8mmØ to 15mmØ, Exit: N/A. numerous amounts					
38536	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	100		RHS	Trackside equipment: Westinghouse large box		1			
38537	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	101		RHS	Trackside equipment: Westinghouse small box		1			
38538	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	101	119	RHS	Cloth cable sheath. Entry: Signals trackside equipment, Route: H4 of 8, 1x15mmØ, H6, 1x8 mmØ, H7, ~8x8mmØ, 1x15mmØ, Exit: Westinghouse small box. 11 x 18m					
39977	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	101		RHS	Trackside equipment: Westinghouse large box		1			
39840	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Signal Boxes	Asbestos	Presumed	101		RHS	Trackside equipment: tencore box		1			
38540	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	119		RHS	Trackside equipment: Westinghouse small box		1			
38539	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	119	124	RHS	Cloth cable sheath. Entry: N/A, Route: H4 of 8, 1x15mmØ, H6, 1x8 mmØ, H7, ~7x8mmØ, 1x15mmØ, Exit: Westinghouse small box. 10 x 5m					
38542	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	124		RHS	Trackside equipment: Westinghouse small box		1			
38541	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	124	135	RHS	Cloth cable sheath. Entry: N/A, Route: H4 of 8, 1x15mmØ, H6, 1x8 mmØ, H7, ~6x8mmØ, 1x15mmØ, Exit: Signals trackside equipment. 9 x 10.5m					
38543	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	135	137	RHS	Cloth cable sheath. Entry: N/A, Route: Between trackside equipment, H4, H6 & H7, Exit: N/A, numerous amounts					
39978	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Signal Boxes	Asbestos	Presumed	135		RHS	Trackside equipment: Signal (A759C)		1			
39645	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	136		RHS	Trackside equipment: Westinghouse large box		1			



Hazardous Material Asset Register - Summary



P058-P - PIC Line - Covent Garden to Leicester Square

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38344	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	137	139	RHS	Cloth cable sheath. Entry: Signals trackside equipment, Route: H4 of 8, 1x15mmØ, H6, 1x8 mmØ, H7, ~16x8mmØ, 1x15mmØ, Exit: Westinghouse small box. 19 x 2.5m					
38345	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	137		RHS	Trackside equipment: Westinghouse small box		1			
39834	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	139	143	RHS	Cloth cable sheath. Entry: N/A, Route: H4 of 8, 1x15mmØ, H6, 1x8 mmØ, H7, ~15x8mmØ, 1x15mmØ, Exit: Westinghouse small box. 18 x 4m					
38346	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	140		RHS	Trackside equipment: Westinghouse small box		1			
38347	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Cable Sheath	Asbestos	Strongly Presumed	143	153	RHS	Cloth cable sheath. Entry: N/A, Route: H4 of 8, 1x15mmØ, H6, 1x8 mmØ, H7, ~14x8mmØ, 1x15mmØ, Exit: Platform wall, 17 x 10m					
38348	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Signal Boxes	Asbestos	Presumed	147		RHS	Trackside equipment: Electrical box		1			
38349	ACTIVE	P	P058-P-EBLO	Road EBLO - PIC - Leicester Square to Covent Garden	Westinghouse Boxes	Asbestos	Presumed	151		RHS	Trackside equipment: Westinghouse small box		1			
37460	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Ducts	Asbestos	Strongly Presumed	0	1	LHS	Bitumen. Cable duct lining, in floor					
37461	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Cable Sheath	Asbestos	Strongly Presumed	0	6	RHS	Cloth. cable sheath, Entry: Platform grounds, Route: H3 of 4, 11x8mmØ, 1x15mmØ, H4, 2x10mmØ, Exit: Signals trackside equipment					
37462	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Cement Cable Troughing & Debris	Asbestos	Strongly Presumed	3		RHS	cement, cable trough. At floor level					
39813	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Signal Boxes	Asbestos	Presumed	6		RHS	Trackside equipment: Signal (A750A)					
37463	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Cable Sheath	Asbestos	Strongly Presumed	6	8	RHS	Cloth. cable sheath, Entry: N/A, Route: Between TE, H3 & H4, 8mmØ to 15mmØ, Exit: N/A					
37464	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Westinghouse Boxes	Asbestos	Presumed	7		RHS	Trackside equipment: Westinghouse large box					
37466	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Signal Boxes	Asbestos	Presumed	8		RHS	Trackside equipment: tencore box					
37465	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Cable Sheath	Asbestos	Strongly Presumed	8	14	RHS	Cloth. cable sheath, Entry: Signals trackside equipment, Route: H3 of 4, 4x8mmØ, 1x15mmØ, H4, 2x10mmØ, Exit: Westinghouse small box					
39708	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Westinghouse Boxes	Asbestos	Presumed	8		RHS	Trackside equipment: Westinghouse small box					



Hazardous Material Asset Register - Summary



P058-P - PIC Line - Covent Garden to Leicester Square

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37467	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Cable Sheath	Asbestos	Strongly Presumed	14	17	RHS	Cloth. cable sheath, Entry: N/A, Route: H3 of 4, 3x8mmØ, 1x15mmØ, H4, 2x10mmØ, Exit: Westinghouse small box					
39709	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Westinghouse Boxes	Asbestos	Presumed	14		RHS	Trackside equipment: Westinghouse small box					
37469	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Westinghouse Boxes	Asbestos	Presumed	17		RHS	Trackside equipment: Westinghouse small box					
37468	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Cable Sheath	Asbestos	Strongly Presumed	17	21	RHS	Cloth. cable sheath, Entry: N/A, Route: H3 of 4, 2x8mmØ, 1x15mmØ, H4, 2x10mmØ, Exit: Westinghouse small box					
37471	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Westinghouse Boxes	Asbestos	Presumed	21		RHS	Trackside equipment: Westinghouse small box					
37470	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Cable Sheath	Asbestos	Strongly Presumed	21	83	RHS	Cloth. cable sheath, Entry: N/A, Route: H3 of 4, 1x8mmØ, 1x15mmØ, H4, 2x10mmØ, Exit: N/A					
37472	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Signal Boxes	Asbestos	Presumed	74		RHS	Trackside equipment: Main earth terminal box					
37475	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Cable Sheath	Asbestos	Strongly Presumed	83		LHS	Cloth. cable sheath, Entry: Signal (A750B), Route: OTX, 2x8mmØ, Exit: RHS					
37474	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Signal Boxes	Asbestos	Presumed	83		LHS	Trackside equipment: Signal (A750B)					
37473	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Cable Sheath	Asbestos	Strongly Presumed	83	85	RHS	Cloth. cable sheath, Entry: OTX to LHS, Route: H3 of 4, 3x8mmØ, 1x15mmØ, H4, 2x10mmØ, Exit: Signals trackside equipment					
37478	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Signal Boxes	Asbestos	Presumed	85		RHS	Trackside equipment: tencore box					
37477	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Westinghouse Boxes	Asbestos	Presumed	85		RHS	Trackside equipment: Westinghouse large box					
37476	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Cable Sheath	Asbestos	Strongly Presumed	85	86	RHS	Cloth. cable sheath, Entry: N/A, Route: Between TE, 8mmØ to 15mmØ, Exit: N/A					
37480	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Westinghouse Boxes	Asbestos	Presumed	86		RHS	Trackside equipment: Westinghouse small box					
37481	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Signal Boxes	Asbestos	Presumed	86		RHS	Trackside equipment: tencore box					
37479	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Cable Sheath	Asbestos	Strongly Presumed	86	155	RHS	Cloth. cable sheath, Entry: Signals trackside equipment, Route: H3 of 4, 1x8mmØ, 2x15mmØ, H4, 2x10mmØ, Exit: Platform wall					
37482	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Westinghouse Boxes	Asbestos	Presumed	111		RHS	Trackside equipment: Westinghouse small box					
39596	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Westinghouse Boxes	Asbestos	Presumed	117		RHS	Trackside equipment: Westinghouse small box					



Hazardous Material Asset Register - Summary



P058-P - PIC Line - Covent Garden to Leicester Square

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37483	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Ducts	Asbestos	Presumed	151	152	LHS	cement. Cable duct lining, presumed present (in floor & sealed)					
37484	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Westinghouse Boxes	Asbestos	Presumed	152		RHS	Trackside equipment: Westinghouse large box					
37487	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Ducts	Asbestos	Presumed	153	154	RHS	cement. Cable duct lining, presumed present (in floor & sealed)					
39814	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Cable Sheath	Asbestos	Presumed	153	154	RHS	Plastic, backing panel. Presumed asbestos behind HV cable termination points					
37486	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Cement Cable Troughing & Debris	Asbestos	Removed	153	154	RHS	cement, cable trough. For HV cables at floor level Notes from 2022 re-inspection: Removed					
37485	ACTIVE	P	P058-P-WBLO	Road WBLO - PIC - Covent Garden to Leicester Square	Cement Cable Troughing & Debris	Asbestos	Removed	153	154	RHS	Cement, soffit, Above HV cable termination points Notes from 2022 re-inspection: Removed					

P062-P - PIC Line - Leicester Square to Piccadilly Circus

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39194	ACTIVE	P	P062-P-EBLO	Road EBLO - PIC - Piccadilly Circus to Leicester Square	Cable Sheath	Asbestos	Known	0		RHS	Woven cable insulation. Entry: Platform, Route: Numerous cables					
39195	ACTIVE	P	P062-P-EBLO	Road EBLO - PIC - Piccadilly Circus to Leicester Square	Cable Sheath	Asbestos	Known	8		RHS	Woven cable insulation. Route: JH3, 1x50mm, JH5, 6x10m, JH4, 1x30mm		7			
39196	ACTIVE	P	P062-P-EBLO	Road EBLO - PIC - Piccadilly Circus to Leicester Square	Cable Sheath	Asbestos	Known	12		RHS	Woven cable insulation. Entry: Lost, 1x10mm, JH2, Exit: Westinghouse small box		6			
39197	ACTIVE	P	P062-P-EBLO	Road EBLO - PIC - Piccadilly Circus to Leicester Square	Cable Sheath	Asbestos	Known	18		RHS	Woven cable insulation. Entry: Lost, 1x10mm, JH5, Exit: Westinghouse small box		5			
39198	ACTIVE	P	P062-P-EBLO	Road EBLO - PIC - Piccadilly Circus to Leicester Square	Cable Sheath	Asbestos	Known	22		RHS	Woven cable insulation. Entry: Lost, 1x10mm, JH5		4			
39936	ACTIVE	P	P062-P-EBLO	Road EBLO - PIC - Piccadilly Circus to Leicester Square	Cable Sheath	Asbestos	Known	72		RHS	Woven cable insulation. Entry: Lost, 1x10mm, JH5		3			
39199	ACTIVE	P	P062-P-EBLO	Road EBLO - PIC - Piccadilly Circus to Leicester Square	Cable Sheath	Asbestos	Known	74		RHS	Woven cable insulation. Entry: Lost, 1x10mm, JH5		2			
39200	ACTIVE	P	P062-P-EBLO	Road EBLO - PIC - Piccadilly Circus to Leicester Square	Signal Boxes	Asbestos	Known	175			Signal A7411 R749		2			
39201	ACTIVE	P	P062-P-EBLO	Road EBLO - PIC - Piccadilly Circus to Leicester Square	Cable Sheath	Asbestos	Known	176	190	RHS	Signal section. Route: Numerous cables in between track side equipment boxes					
39202	ACTIVE	P	P062-P-EBLO	Road EBLO - PIC - Piccadilly Circus to Leicester Square	Cable Sheath	Asbestos	Known	190		RHS	Woven cable insulation. Entry: Track side equipment, Route: JH3, 1x50, J7, 1x30, 2x10, JH4, 1x30, J8, 1x10mm		6			



Hazardous Material Asset Register - Summary



P062-P - PIC Line - Leicester Square to Piccadilly Circus

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39203	ACTIVE	P	P062-P-EBLO	Road EBLO - PIC - Piccadilly Circus to Leicester Square	Signal Boxes	Asbestos	Known	317		RHS	Signal A749a					
39204	ACTIVE	P	P062-P-EBLO	Road EBLO - PIC - Piccadilly Circus to Leicester Square	Cable Sheath	Asbestos	Known	317	334	RHS	Signal section. Route: Numerous cables in between track JH6, 2x30mm					
39205	ACTIVE	P	P062-P-EBLO	Road EBLO - PIC - Piccadilly Circus to Leicester Square	Cable Sheath	Asbestos	Known	334		RHS	Woven cable insulation. Entry: Track side equipment, Route: JH5, 1x30, 6x10, JH4, 1x30, JH8, 1x10mm		9			
39352	ACTIVE	P	P062-P-EBLO	Road EBLO - PIC - Piccadilly Circus to Leicester Square	Cable Sheath	Asbestos	Known	350	352	RHS	Signal section					
39206	ACTIVE	P	P062-P-EBLO	Road EBLO - PIC - Piccadilly Circus to Leicester Square	Signal Boxes	Asbestos	Known	350		RHS	Signal A749b					
39207	ACTIVE	P	P062-P-EBLO	Road EBLO - PIC - Piccadilly Circus to Leicester Square	Cable Sheath	Asbestos	Known	352		RHS	Woven cable insulation. Route: JH7, 2x30, 5x10, JH8, 3x30mm		10			
39208	ACTIVE	P	P062-P-EBLO	Road EBLO - PIC - Piccadilly Circus to Leicester Square	Cable Sheath	Asbestos	Known	392		RHS	Woven cable insulation. Entry: Westinghouse small box, Route: JH7, 1x10, gain		11			
39462	ACTIVE	P	P062-P-EBLO	Road EBLO - PIC - Piccadilly Circus to Leicester Square	Cable Sheath	Asbestos	Known	398		RHS	Woven cable insulation. Entry: Log JH7, 4x10mm, Exit: Westinghouse small box		10			
54040	ACTIVE	P	P062-P-EBLO	Road EBLO - PIC - Piccadilly Circus to Leicester Square		Asbestos	Presumed				Signal A749c		1			
39209	ACTIVE	P	P062-P-EBLO	Road EBLO - PIC - Piccadilly Circus to Leicester Square	Cable Sheath	Asbestos	Known	436		RHS	Woven cable insulation. Route: JH3,1x50, JH6, 1x10, JH4, 1x30, JH7, 3x30mm, Exit: track side equipment		6			
39210	ACTIVE	P	P062-P-EBLO	Road EBLO - PIC - Piccadilly Circus to Leicester Square	Cable Sheath	Asbestos	Known	442		RHS	Vent Shaft. Route: JH8, 5x10mm					
39353	ACTIVE	P	P062-P-EBLO	Road EBLO - PIC - Piccadilly Circus to Leicester Square	Cable Sheath	Asbestos	Known	460			Woven cable insulation. limited access due to height, Numerous amounts RHS & OTX					
39211	ACTIVE	P	P062-P-EBLO	Road EBLO - PIC - Piccadilly Circus to Leicester Square	Cable Sheath	Asbestos	Known	474		RHS	Woven cable insulation. Platform wall, numerous amounts					
38350	ACTIVE	P	P062-P-WBLO	Road WBLO - PIC - Leicester Square to Piccadilly Circus	Ducts	Asbestos	Strongly Presumed	0		LHS	Bitumen cable duct lining		6			
41726	ACTIVE	P	P062-P-WBLO	Road WBLO - PIC - Leicester Square to Piccadilly Circus	Cable Sheath	Asbestos	Known				Woven cable (9 x 2m), trackside (head wall)	2	9			
41725	ACTIVE	P	P062-P-WBLO	Road WBLO - PIC - Leicester Square to Piccadilly Circus	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux firebreak (2m2) behind trackside wall (head wall) - NADIS	2				
41723	ACTIVE	P	P062-P-WBLO	Road WBLO - PIC - Leicester Square to Piccadilly Circus	Bitumen	Asbestos	Sampled – Not Detected				Bitumen / paint coating throughout lower trackside wall (head wall) - NADIS					
46173	ACTIVE	P	P062-P-WBLO	Road WBLO - PIC - Leicester Square to Piccadilly Circus	Cable Sheath	Asbestos	Strongly Presumed	0		LHS	Cable wrap 9no x 2m	2	9			
38351	ACTIVE	P	P062-P-WBLO	Road WBLO - PIC - Leicester Square to Piccadilly Circus	Cable Sheath	Asbestos	Known	19		RHS	Woven cable insulation. JH4, 2x20mm					



Hazardous Material Asset Register - Summary



P062-P - PIC Line - Leicester Square to Piccadilly Circus

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41727	ACTIVE	P	P062-P-WBLO	Road WBLO - PIC - Leicester Square to Piccadilly Circus	Cable Sheath	Asbestos	Strongly Presumed	20		LHS	2 x 8m woven cable - 20m west on W/B left hand side wall.	8	2			
38352	ACTIVE	P	P062-P-WBLO	Road WBLO - PIC - Leicester Square to Piccadilly Circus	Cable Sheath	Asbestos	Known	21	23	RHS	Spliced cable, insulation. Route: JH4, 1x20mm					
38353	ACTIVE	P	P062-P-WBLO	Road WBLO - PIC - Leicester Square to Piccadilly Circus	Signal Boxes	Asbestos	Presumed	247		LHS	Trackside equipment: Signal R740bc		1			
38354	ACTIVE	P	P062-P-WBLO	Road WBLO - PIC - Leicester Square to Piccadilly Circus	Signal Boxes	Asbestos	Presumed	258		LHS	Trackside equipment: Signal R740a					
38355	ACTIVE	P	P062-P-WBLO	Road WBLO - PIC - Leicester Square to Piccadilly Circus	Cable Sheath	Asbestos	Known	267		RHS	Woven cable insulation. Route: JH4, 2x30, JH6, 1x30mm					
38356	ACTIVE	P	P062-P-WBLO	Road WBLO - PIC - Leicester Square to Piccadilly Circus	Cable Sheath	Asbestos	Known	270		RHS	Spliced cable, insulation. route: JH4, 1x20mm		2			
38357	ACTIVE	P	P062-P-WBLO	Road WBLO - PIC - Leicester Square to Piccadilly Circus	Cable Sheath	Asbestos	Known	295		RHS	Spliced cable, insulation		2			
38358	ACTIVE	P	P062-P-WBLO	Road WBLO - PIC - Leicester Square to Piccadilly Circus	Cable Sheath	Asbestos	Known	334		RHS	Woven cable insulation. Route:JH4 2x20, JH5, 1x30mm					
38359	ACTIVE	P	P062-P-WBLO	Road WBLO - PIC - Leicester Square to Piccadilly Circus	Cable Sheath	Asbestos	Known	352		RHS	Woven cable insulation. Route: JH4 2 2x20, JH6, 2x30mm					

P063-P - PIC Line - Piccadilly Circus Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42767	ACTIVE	P	P063-P-EBLO	Road EBLO (Pit3) - PIC - Piccadilly Circus Stn	Pit Blocks	Asbestos	Removed				Pit blocks - Non asbestos (Removed by Silverdell 1998)					
39212	ACTIVE	P	P063-P-EBLO	Road EBLO (Pit3) - PIC - Piccadilly Circus Stn	Westinghouse Boxes	Asbestos	Strongly Presumed	35			Westinghouse small box. Presumed ACM inside		1			
39213	ACTIVE	P	P063-P-EBLO	Road EBLO (Pit3) - PIC - Piccadilly Circus Stn	Westinghouse Boxes	Asbestos	Strongly Presumed	40			Westinghouse small box signal. Presumed ACM inside		1			
39214	ACTIVE	P	P063-P-EBLO	Road EBLO (Pit3) - PIC - Piccadilly Circus Stn	Westinghouse Boxes	Asbestos	Strongly Presumed	56			Westinghouse small box end. Presumed ACM inside		1			
54039	ACTIVE	P	P063-P-WBLO	Road WBLO (Pit4) - PIC - Piccadilly Circus Stn	Westinghouse Boxes	Asbestos	Presumed				Trackside equipment: Westinghouse small box 2x no. Presumed ACM inside Notes from 2022 re-inspection: Present not removed		2			
42768	ACTIVE	P	P063-P-WBLO	Road WBLO (Pit4) - PIC - Piccadilly Circus Stn	Pit Blocks	Asbestos	Surveyed – Not Detected				Pit blocks - Non asbestos					



Hazardous Material Asset Register - Summary



P064-P - PIC Line - Piccadilly Circus to Green Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37573	ACTIVE	P	P064-P-EBLO	Road EBLO - PIC - Green Park to Piccadilly Circus	Cable Sheath	Asbestos	Known	0	1	RHS	Cloth. Cable sheath, Route: JH7 6x30m, JH8 1x25m, Exit: N/A					
37572	ACTIVE	P	P064-P-EBLO	Road EBLO - PIC - Green Park to Piccadilly Circus	Cable Sheath	Asbestos	Known	0	1	RHS	Cloth. Cable sheath, Entry: Platform, Route: JH6 7x25m, 1x30m, JH1 2x30m, Exit: N/A. 1 x 16no					
37575	ACTIVE	P	P064-P-EBLO	Road EBLO - PIC - Green Park to Piccadilly Circus	Cable Sheath	Asbestos	Known	1	3	RHS	Cloth. Cable sheath, Route: JH7 7x30m, JH8 1x25m					
37574	ACTIVE	P	P064-P-EBLO	Road EBLO - PIC - Green Park to Piccadilly Circus	Cable Sheath	Asbestos	Known	1	3	RHS	Cloth. Cable sheath, Entry: Westinghouse small box, Route: JH6 7x25m, 1x30m, JH1 2x30m. 2 x 18no					
37577	ACTIVE	P	P064-P-EBLO	Road EBLO - PIC - Green Park to Piccadilly Circus	Cable Sheath	Asbestos	Known	3	9	RHS	Cloth. Cable sheath, Route: JH6 6x25m, 2x30m, JH2 2x30m, JH7 2x25m, Exit: Track side. Numerous amounts					
37578	ACTIVE	P	P064-P-EBLO	Road EBLO - PIC - Green Park to Piccadilly Circus	Cable Sheath	Asbestos	Known	3	9	RHS	Cloth. Cable sheath, Route: JH8 1x25m					
37576	ACTIVE	P	P064-P-EBLO	Road EBLO - PIC - Green Park to Piccadilly Circus	Cable Sheath	Asbestos	Known	3	9	RHS	Cloth. Cable sheath, Route: JH1-8 1m-30m. Numerous amounts					
37579	ACTIVE	P	P064-P-EBLO	Road EBLO - PIC - Green Park to Piccadilly Circus	Cable Sheath	Asbestos	Known	9	11	RHS	Cloth. Cable sheath, Entry: N/A, Route: JH6 5x25m, Exit: Westinghouse small box. Numerous amounts					
37584	ACTIVE	P	P064-P-EBLO	Road EBLO - PIC - Green Park to Piccadilly Circus	Cable Sheath	Asbestos	Known	11	56	RHS	Cloth. Cable sheath, Entry: N/A, Route: JH7 less 1425m, Exit: Westinghouse small box. Numerous amounts					
37581	ACTIVE	P	P064-P-EBLO	Road EBLO - PIC - Green Park to Piccadilly Circus	Ducts	Asbestos	Sampled – Not Detected	45			cable duct, 2nd cable duct in tunnel					
37583	ACTIVE	P	P064-P-EBLO	Road EBLO - PIC - Green Park to Piccadilly Circus	Ducts	Asbestos	Known	50		LHS	bitumen cable duct lining		26			
37582	ACTIVE	P	P064-P-EBLO	Road EBLO - PIC - Green Park to Piccadilly Circus	Ducts	Asbestos	Known	50		LHS	bitumen cable duct lining		8			
37580	ACTIVE	P	P064-P-EBLO	Road EBLO - PIC - Green Park to Piccadilly Circus	Cable Sheath	Asbestos	Known	50		RHS	Flood gate area. Route: Numerous cables, Between JH1-JH8, 10m-35m					
37585	ACTIVE	P	P064-P-EBLO	Road EBLO - PIC - Green Park to Piccadilly Circus	Cable Sheath	Asbestos	Known	55	227	RHS	Cloth. Cable sheath, Entry: N/A, Route: Numerous, numerous amounts					
39819	ACTIVE	P	P064-P-EBLO	Road EBLO - PIC - Green Park to Piccadilly Circus	Cable Sheath	Asbestos	Known	57		RHS	Cloth. Cable sheath, Entry: N/A, Route: JH7 less 1 1x25m, Exit: Westinghouse small box		14			
39599	ACTIVE	P	P064-P-EBLO	Road EBLO - PIC - Green Park to Piccadilly Circus	Cable Sheath	Asbestos	Known	227	266	RHS	Cloth. Cable sheath, Entry: N/A, Route: JH4 1x30m, JH6, 5x25m, JH7 1x25m, Exit: N/A. numerous amounts					
37586	ACTIVE	P	P064-P-EBLO	Road EBLO - PIC - Green Park to Piccadilly Circus	Cable Sheath	Asbestos	Known	266	272	RHS	Cloth. Cable sheath, Entry: Signal box, Route: Numerous less JH4 1x25m, JH6 less 1x25m, Exit: Westinghouse small box. Numerous amounts					



Hazardous Material Asset Register - Summary



P064-P - PIC Line - Piccadilly Circus to Green Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37587	ACTIVE	P	P064-P-EBLO	Road EBLO - PIC - Green Park to Piccadilly Circus	Cable Sheath	Asbestos	Known	272	296	RHS	Cloth. Cable sheath, Route: Numerous					
37588	ACTIVE	P	P064-P-EBLO	Road EBLO - PIC - Green Park to Piccadilly Circus	Cable Sheath	Asbestos	Known	296	345	RHS	Cloth. Cable sheath, Entry: N/A, Route: Numerous, Exit: Signal box. Numerous amounts					
39714	ACTIVE	P	P064-P-EBLO	Road EBLO - PIC - Green Park to Piccadilly Circus	Cable Sheath	Asbestos	Known	348	392	RHS	Cloth. Cable sheath, Entry: Westinghouse small box, Route: 1x25m, JH6 plus. Numerous amounts					
39820	ACTIVE	P	P064-P-EBLO	Road EBLO - PIC - Green Park to Piccadilly Circus	Cable Sheath	Asbestos	Known	392	396	RHS	Cloth. Cable sheath, Entry: N/A, Route: less JH6, Exit: N/A. numerous amounts					
37796	ACTIVE	P	P064-P-EBLO	Road EBLO - PIC - Green Park to Piccadilly Circus	Cable Sheath	Asbestos	Known	396	406	RHS	Cloth. Cable sheath, Entry: N/A, Route: Between JH1-JH6 10-30m, Exit: Platform wall. Numerous amounts					
37795	ACTIVE	P	P064-P-EBLO	Road EBLO - PIC - Green Park to Piccadilly Circus	Signal Boxes	Asbestos	Known	404		RHS	Full possible track trolleys equipment					
39215	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Cable Sheath	Asbestos	Strongly Presumed	0	8	RHS	Cloth, cable sheath. Entry: Platform grounds, Route: H4 of 8, 2x30mmØ, H5, 1x30mmØ, H7, 1x25mm, Exit: Signals trackside equipment. 4 X 8M					
43149	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Caulking	Asbestos	Sampled – Not Detected				Tunnel caulking, throughout, to tunnel rings P064/PWBLO/0154			R523901	N	N
39216	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Cement Cable Troughing & Debris	Asbestos	Removed	2			Cement, Cable trough. at floor level. The asbestos troughing was removed by Econ Construction on 07/08/2019. Job Reference ES8756.		3			
39219	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Westinghouse Boxes	Asbestos	Presumed	8		RHS	Trackside equipment: Westinghouse large box		1			
39220	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Signal Boxes	Asbestos	Presumed	8		RHS	Trackside equipment: Ten Core box		3			
39218	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Signal Boxes	Asbestos	Presumed	8		RHS	Trackside equipment: Signal (FPX738)		1			
39217	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Cable Sheath	Asbestos	Strongly Presumed	8	10	RHS	Cloth, cable sheath. Entry: N/A, Route: Between TE, 30mmØ to 25mmØ, Exit: N/A. numerous amounts					
39221	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Westinghouse Boxes	Asbestos	Presumed	8		RHS	Trackside equipment: Westinghouse small box		1			
39222	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Westinghouse Boxes	Asbestos	Presumed	10		RHS	Trackside equipment: Westinghouse small box		1			
39223	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Westinghouse Boxes	Asbestos	Presumed	20		RHS	Trackside equipment: Westinghouse small box		1			
39224	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Westinghouse Boxes	Asbestos	Presumed	74		RHS	Trackside equipment: Westinghouse small box		1			



Hazardous Material Asset Register - Summary



P064-P - PIC Line - Piccadilly Circus to Green Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39225	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Westinghouse Boxes	Asbestos	Presumed	75		RHS	Trackside equipment: Westinghouse small box		1			
43150	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Caulking	Asbestos	Sampled – Not Detected				Tunnel caulking, throughout, to tunnel rings P064/PWBLO/0156			R523901	N	N
43151	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Caulking	Asbestos	Sampled – Not Detected				Tunnel caulking, throughout, to tunnel rings P064/PWBLO/0159			R523901	N	N
39937	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Signal Boxes	Asbestos	Presumed	211		RHS	Trackside equipment: Type 79 box		1			
39226	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Cable Sheath	Asbestos	Strongly Presumed	225	226	RHS	Cloth, cable sheath. Cable splice from H4 down below H8 then back to H4. 1 x 1m					
43152	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Caulking	Asbestos	Sampled – Not Detected				Tunnel caulking, throughout, to tunnel rings P064/PWBLO/0249			R523901	N	N
39227	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Cable Sheath	Asbestos	Strongly Presumed	281		RHS	Cloth, cable sheath. Entry: N/A, Route: Between TE, 30mmØ to 25mmØ, Exit: N/A. numerous amounts					
39231	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Westinghouse Boxes	Asbestos	Presumed	281			Trackside equipment: Westinghouse small box		2			
39230	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Signal Boxes	Asbestos	Presumed	281			Trackside equipment: Ten Core box		3			
39229	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Westinghouse Boxes	Asbestos	Presumed	281			Trackside equipment: Westinghouse large box		2			
39228	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Signal Boxes	Asbestos	Presumed	281		RHS	Trackside equipment: Signal (FPX734)		1			
39354	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Cable Sheath	Asbestos	Strongly Presumed	289		RHS	Cloth, cable sheath. Cable tally: H4, 3x30mmØ, H6, 1x35mmØ, H8, 2x25mmØ					
39232	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Cable Sheath	Asbestos	Strongly Presumed	291	292	RHS	Cloth, cable sheath. Cable splice from H4 down below H8 then back to H4. 1 x1m					
39233	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Cable Sheath	Asbestos	Strongly Presumed	320	325	RHS	Cloth, cable sheath. 2x25mmØ move between H7 and H8. 2 x 5m					
39235	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Signal Boxes	Asbestos	Presumed	327		RHS	Trackside equipment: Signal (FPX730A)		1			
39355	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Westinghouse Boxes	Asbestos	Presumed	327		RHS	Trackside equipment: Westinghouse small box		1			
39463	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Signal Boxes	Asbestos	Presumed	327		RHS	Trackside equipment: Ten Core box		3			
39240	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Cable Sheath	Asbestos	Strongly Presumed	327	361	RHS	Cloth, cable sheath. 1x 25mmØ exits to box from H6, 1 x 34m					
39236	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Westinghouse Boxes	Asbestos	Presumed	327		RHS	Trackside equipment: Westinghouse large box		2			



Hazardous Material Asset Register - Summary



P064-P - PIC Line - Piccadilly Circus to Green Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39234	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Cable Sheath	Asbestos	Strongly Presumed	327		RHS	Cloth, cable sheath. Entry: N/A, Route: Between TE, 30mmØ to 25mmØ, Exit: N/A. numerous amounts					
39237	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Cable Sheath	Asbestos	Strongly Presumed	332		RHS	Cloth, cable sheath. Cable tally: H4, 2x35mmØ, H6, 3x25mmØ, H7, 2x25mmØ, H8, 3 x 25mmØ, difficult to assess exact number in H6					
39238	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Westinghouse Boxes	Asbestos	Presumed	357		RHS	Trackside equipment: Westinghouse small box		1			
39239	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Westinghouse Boxes	Asbestos	Presumed	358		RHS	Trackside equipment: Westinghouse small box		1			
43153	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Caulking	Asbestos	Sampled – Not Detected				Tunnel caulking, throughout, to tunnel rings P064/PWBLO/0359			R523901	N	N
39241	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Westinghouse Boxes	Asbestos	Presumed	361		RHS	Trackside equipment: Westinghouse small box		1			
39243	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Ducts	Asbestos	Known	402		LHS	Cement, cable duct lining. In wall of floodgate assembly		18			
39938	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Westinghouse Boxes	Asbestos	Presumed	402			Trackside equipment: Westinghouse small box		4			
39245	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Westinghouse Boxes	Asbestos	Presumed	402			Trackside equipment: Westinghouse large box		4			
39244	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Cement Cable Troughing & Debris	Asbestos	Removed	402			Cement, cable trough. At floor level. Econ Construction carried out asbestos troughing removals within the floodgate chamber. A small piece of asbestos located underneath a sleeper could not be removed as a track gang is required. This has been encapsulated and the location has been sprayed up to advise others of its presence Notes from 2022 re-inspection: Removed. No more sleepers		20			
39242	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Ducts	Asbestos	Known	402		RHS	Cement, cable duct lining. In wall of floodgate assembly		18			
39246	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Cable Sheath	Asbestos	Strongly Presumed	411		RHS	Cloth, cable sheath. Route: Between equipment room to side of floodgate and onto running tunnel hangers. Difficult to quantify exact numbers in each hanger. Numerous amounts					
43154	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Caulking	Asbestos	Sampled – Not Detected				Tunnel caulking, throughout, to tunnel rings P064/PWBLO/0430			R523901	N	N
43155	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Caulking	Asbestos	Sampled – Not Detected				Tunnel caulking, throughout, to tunnel rings P064/PWBLO/0442			R523901	N	N



Hazardous Material Asset Register - Summary



P064-P - PIC Line - Piccadilly Circus to Green Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39249	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Signal Boxes	Asbestos	Presumed	444		RHS	Trackside equipment: Ten Core box Notes from 2022 re-inspection: 2x 10 core		2			
39464	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Westinghouse Boxes	Asbestos	Presumed	444		RHS	Trackside equipment: Westinghouse large box Notes from 2022 re-inspection: 1x LWH		1			
39247	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Cable Sheath	Asbestos	Strongly Presumed	444		RHS	Cloth, cable sheath. Entry: N/A, Route: Between TE, 30mmØ to 25mmØ, Exit: N/A. numerous amounts					
39250	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Westinghouse Boxes	Asbestos	Presumed	444		RHS	Trackside equipment: Westinghouse small box		1			
39248	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Signal Boxes	Asbestos	Presumed	444		RHS	Trackside equipment: Signal (A730B)		1			
39252	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Westinghouse Boxes	Asbestos	Presumed	444	452	RHS	Trackside equipment: Westinghouse small box		1			
39251	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Cable Sheath	Asbestos	Strongly Presumed	452		RHS	Cloth, cable sheath. 1x 25mmØ exits to box from H7. 1 x 8m					
39253	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Signal Boxes	Asbestos	Presumed	453		RHS	Trackside equipment: Signal light box		1			
39254	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Westinghouse Boxes	Asbestos	Presumed	460		RHS	Trackside equipment: Westinghouse small box		1			
39256	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Ducts	Asbestos	Known	465		RHS	cement, cable duct lining		2			
39255	ACTIVE	P	P064-P-WBLO	Road WBLO - PIC - Piccadilly Circus to Green Park	Cable Sheath	Asbestos	Strongly Presumed	465		RHS	Cloth, cable sheath. Cable tally: H2, H3, H6, H7, H8 various size cables 25mmØ to 35mmØ. Difficult to quantify exact numbers in each hanger. Numerous amounts					

P065-P - PIC Line - Green Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
45314	ACTIVE	P	P065-P-EBLO	Road EBLO (Plt2) - PIC - Green Park Stn	Pit Blocks	Asbestos	Known				Pit blocks, Eastbound 5 Inner & Eastbound 2 Outer - Amosite & Chrysotile (Significant)					
37798	ACTIVE	P	P065-P-EBLO	Road EBLO (Plt2) - PIC - Green Park Stn	Westinghouse Boxes	Asbestos	Removed				Trackside equipment: Small Equipment Box - Asbestos components presumed within; Notes from 2022 re-inspection: Removed					
42742	ACTIVE	P	P065-P-EBLO	Road EBLO (Plt2) - PIC - Green Park Stn	Pit Blocks	Asbestos	Removed				Pit blocks - Non asbestos (Removed by Forest May 2003)					
37797	ACTIVE	P	P065-P-WBLO	Road WBLO (Plt1) - PIC - Green Park Stn	Westinghouse Boxes	Asbestos	Presumed				Trackside equipment: Small Equipment Box - Asbestos components presumed within;					



Hazardous Material Asset Register - Summary



P065-P - PIC Line - Green Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42741	ACTIVE	P	P065-P-WBLO	Road WBLO (Plt1) - PIC - Green Park Stn	Pit Blocks	Asbestos	Removed				Pit blocks - Non asbestos (Removed by Forest May 2003)					

P066-P - PIC Line - Green Park to Hyde Park Corner

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39959	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	0		RHS	Cloth cable sheath, Route: JH2 1x15, JH3 1x30, 1x20, JH4 3x15, 1x45, 1x15, 1x25		9			
38288	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	6	10	RHS	Cloth cable sheath, Route: Between JH2 - JH4, 15m - 45m. Numerous amounts					
38289	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	10		RHS	Cloth cable sheath, Route: JH2, 8x15, JH4, 1x15, 1x45, JH3, 1x30, 1x20, 1x15		13			
38290	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	15		RHS	cable, spliced. Route: JH4, 1x45		2			
38305	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	23		RHS	Cloth cable sheath, Route: gaining 2x15, JH2 & JH3		17			
38291	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	26		RHS	Cloth cable sheath, Entry: Westinghouse small box small, Route: Gaining 1x15 JH2		14			
38292	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Westinghouse Boxes	Asbestos	Known	27	31	RHS	Trackside equipment: Large westinghouse box, Numerous cables between Westinghouse small box box		4			
38293	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	31		RHS	Cloth cable sheath, Entry: Westinghouse small box large, Route: Gaining 2x15		15			
39960	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	35		RHS	cable, spliced. Route: JH3, 1x20		2			
38294	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	39		RHS	Cloth cable sheath, Entry: JH2, 5x15, Route: Tencore Box, Exit: JH3, 1x30		15			
38295	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	45		RHS	Cloth cable sheath, Entry: JH2, 1x30, Route: Tencore Box, Exit: JH3, 1x30		15			
38296	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	81	83	RHS	Cloth cable sheath, Entry: JH3, Route: JH2 - JH4, 5m - 30m, between track side equipment, Exit: JH3, track side equipment. Numerous amounts					
38297	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	83		RHS	Cloth cable sheath, Route: JH2, 2x15, JH3, 3x30, 1x15, 1x20, JH4, 1x25, 1x45, 15x1		10			
38298	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	112			Cloth cable sheath, Entry: OTX, Route: 2x15, Exit: Tencore LHS/OTX		2			
38299	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	112		RHS	Cloth cable sheath, Entry: Westinghouse small box signal, Route: gaining 1x15, JH2		11			



Hazardous Material Asset Register - Summary



P066-P - PIC Line - Green Park to Hyde Park Corner

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38300	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	113		RHS	Cloth cable sheath, Route: gaining 1x15, JH2		12			
38301	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	117		RHS	Cloth cable sheath, Route: gaining 1x15, JH2		13			
38302	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	119	121	RHS	Cloth cable sheath, Route: Between JH2 - JH4 and track side equipment, Exit: Track side equipment. PB18 points equipment. Numerous amounts					
39643	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	121		RHS	Cloth cable sheath, Route: JH2, 3x15, JH3, 4x30, 1x15, JH4, 1x15, 1x25, 1x45		11			
38303	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	202	203	RHS	Cloth cable sheath, Route: Between JH2 - JH4, 15m - 45m, trackside equipment. Numerous amounts					
38304	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	203		RHS	Cloth cable sheath, Route: JH2, 5x15, JH3, 4x30, 2x15, 1x25, JH4, 1x45, 1x15, 1x25		15			
38306	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	223		RHS	cable, spliced. Route: JH3, 1x15		2			
38307	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	244	246	RHS	Cloth cable sheath, Route: Between JH2 - JH4, trackside equipment, Exit: track. Numerous amounts					
38308	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	246		RHS	Cloth cable sheath, Route: JH2, 7x15, 1x30, JH3, 4x30, 2x15, 1x25, JH4, 1x45, 1x25		17			
38309	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	251		RHS	Cloth cable sheath, Entry: Westinghouse small box Smal, Route: gaining 1x15, JH2		18			
38310	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	256		RHS	Cloth cable sheath, Entry: Westinghouse small box Smal, Route: gaining 1x15, JH3		19			
38314	INACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Current Rail Boxes	Asbestos	Removed	258		RHS	Cover for current section rail switch 351 EB. 2.5m Asbestos board removed by Forest Environmental and replaced with a non asbestos substitute ES1178 13/02/2006					
38311	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cement Cable Troughing & Debris	Asbestos	Removed	258			trough, 3.5m RHS/UTX Notes from 2022 re-inspection: Removed					
38312	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Removed	259			trough, 7.5m RHS/UTX Notes from 2022 re-inspection: Removed					
39961	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Surveyed – Not Detected	259		RHS	Cover for current section rail switch 351 EB. 2.5m Asbestos board removed by Forest Environmental and replaced with a non asbestos substitute ES1178 13/02/2006					



Hazardous Material Asset Register - Summary



P066-P - PIC Line - Green Park to Hyde Park Corner

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38313	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Removed	260			trough, 3.5m RHS/UTX Notes from 2022 re-inspection: Removed					
38315	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	375		RHS	Cloth cable sheath					
39832	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	398		RHS	Cloth cable sheath					
38316	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	403		RHS	Cloth cable sheath					
38318	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	465		LHS	Cloth cable sheath. Route: Between JH2 - JH4, trackside equipment, numerous amounts					
38317	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	465		RHS	Cloth cable sheath. route: JH2 - JH4 observed,k asbestos cable unable to determine due to height, numerous amounts					
39962	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	466		RHS	Cloth cable sheath. entry: Tencore, route: 10m-15m, numerous amounts					
38319	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	468		RHS	Cloth cable sheath. Entry: Westinghouse small box Smal, Route: gaining 1x15, JH. Numerous amounts					
38320	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	522	532	RHS	Cloth cable sheath. Route: Between JH2 - JH4, trackside equipment. Numerous amounts					
38321	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	532		RHS	Cloth cable sheath. Route: JH2, 7x15, 1x25, 1x30, JH3, 2x15, 1x20, JH4, 1x45, 1x25, 1x20, 1x15		16			
38322	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	593		RHS	Cloth cable sheath. Route: Losing 2x15, JH2		15			
38323	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	598	601	RHS	Cloth cable sheath. Route: Between JH2 - JH4, 15m - 45m, trackside equipment, numerous amounts					
39833	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	601		RHS	Cloth cable sheath. Route: JH2, 7x15, 1x25, JH3, 1x15, JH4, 1x45, 1x25, 1x20, 1x15		15			
38324	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	606		RHS	Cloth cable sheath. Route: Losing 1x15, JH3					
38325	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	608		RHS	Cloth cable sheath. Route: Losing 1x15, JH2					
38326	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cement Cable Troughing & Debris	Asbestos	Removed	609			trough RHS/UTX Notes from 2022 re-inspection: Removed		1			
38329	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Current Rail Boxes	Asbestos	Removed	610		RHS	Current rail switch section 354 EB					



Hazardous Material Asset Register - Summary



P066-P - PIC Line - Green Park to Hyde Park Corner

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38327	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cement Cable Troughing & Debris	Asbestos	Removed	610			trough RHS/UTX Notes from 2022 re-inspection: Removed		1			
38328	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cement Cable Troughing & Debris	Asbestos	Removed	611			trough RHS/UTX Notes from 2022 re-inspection: Removed		1			
39451	INACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Current Rail Boxes	Asbestos	Removed	611		RHS	Current rail switch section 354 EB Asbestos board surround removed by Edenbeck Services Ltd ES9541e 27/09/2018					
38330	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	616		RHS	cable, spliced. Route: 1x20 JH4		2			
38331	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	701		RHS	Cloth cable sheath. Route: Gaining 2x15 JH2		16			
38332	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	768		RHS	Cloth cable sheath. Entry: Track side equipment, Route: Between JH2 - JH3, between track side equipment, numerous amounts					
38333	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	777		RHS	Cloth cable sheath. Route: JH2, 9x15, 1x25, JH3, 1x30, 1x20, JH4, 1x45, 1x25, 1x20, 2x15		17			
38334	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	829		RHS	Cloth cable sheath. Entry: Track side equipment, Route: JH2, 10x15, JH3, 2x15, 1x25, JH4, 1x45, 2x25, 4x20, 1x15		18			
38335	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	840		RHS	Cloth cable sheath. Route: Gaining 1 x15 JH2					
38336	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	910	915	RHS	Cloth cable sheath. Route: Between JH2 - JH4, track side equipment. Numerous amounts					
38337	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	915		RHS	Cloth cable sheath. Route: JH2, 8x15, 1x20, 2x25, JH3, 2x15, 4x20, 2x20, JH4, 2x15, 2x20, 1x45		22			
38338	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	930		RHS	Cloth cable sheath. Entry: JH4, Route: Tencore, Exit: JH4		22			
39644	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	955		RHS	Cloth cable sheath. Entry: Westinghouse small box small, Route: Gaining 1x15 JH2		23			
39963	ACTIVE	P	P066-P-EBLO	Road EBLO - PIC - Hyde Park Corner to Green Park	Cable Sheath	Asbestos	Known	960			Entry: Westinghouse small box small, Route: Gaining 1x15 JH2		22			
37500	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	0			Woven cable insulation. Numerous amounts. Exit: RHS					
39711	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	0			Woven cable insulation. Entry: West Pway Green HPC, Route: JH2 2x20, 2x25, JH3 2x25, 1x35, JH4 1x20mm					
37496	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Westinghouse Boxes	Asbestos	Presumed	0			Trackside equipment: Westinghouse large box. Route: JH2 9x20, 2x35, JH4 1x20mm					



Hazardous Material Asset Register - Summary



P066-P - PIC Line - Green Park to Hyde Park Corner

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46170	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Westinghouse Boxes	Asbestos	Strongly Presumed			RHS	Westinghouse Boxes a>10x20mm cables on LHS cross to RHS and run into Westinghouse box. All other cables in RHS cable run terminate at start of Siging					
46171	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known			RHS	Woven cable insulation a>10x20mm cables on LHS cross to RHS and run into Westinghouse box. All other cables in RHS cable run terminate at start of Siging					
46169	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known			LHS	Woven cable insulation JH2, 2x30mm, JH3, >10x25mm, 2x30mm					
46168	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Cement Troughing	Asbestos	Removed				Troughing 20no. each approach both siding approaches (LHS & RHS) Notes from 2022 re-inspection: Removed		20		N	N
37497	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Westinghouse Boxes	Asbestos	Presumed	1		LHS	Trackside equipment: Westinghouse small box. Route: losing 1x20mm JH2					
37501	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	5		RHS	Route: JH2 2x20, 2x25, 2x30, JH3 4x20, 2x35mm		13			
37498	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Westinghouse Boxes	Asbestos	Presumed	10		RHS	Trackside equipment: Westinghouse large box Notes from 2022 re-inspection: 1x LWH not 2x LWH. 1x removed		1			
37499	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	10	11	RHS	Woven cable insulation. Numerous amounts					
37502	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	15		OTX	Woven cable insulation. Entry: LHS, Route: JH2 1x30 remainder on RHS, Exit: OTX		14			
37503	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Signal Boxes	Asbestos	Presumed	23			tencore		1			
37506	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Westinghouse Boxes	Asbestos	Presumed	23		LHS	Trackside equipment: Westinghouse small box		2			
37505	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	24		RHS	Woven cable insulation. Entry: Trackside equipment, Exit: OTX. Numerous amounts					
37504	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Westinghouse Boxes	Asbestos	Presumed	24		RHS	Trackside equipment: Westinghouse small box		2			
37507	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Signal Boxes	Asbestos	Presumed	25		RHS	tencore		2			
37508	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Signal Boxes	Asbestos	Presumed	27		LHS	tencore		1			
37509	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Westinghouse Boxes	Asbestos	Presumed	30		LHS	Trackside equipment: Westinghouse small box					
37510	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	30		LHS	Woven cable insulation. Entry: WHS, Route: 2x20mm JH3 & Earth cable					



Hazardous Material Asset Register - Summary



P066-P - PIC Line - Green Park to Hyde Park Corner

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37511	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Westinghouse Boxes	Asbestos	Presumed	35			Trackside equipment: Westinghouse small box		1			
37512	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Westinghouse Boxes	Asbestos	Presumed	36			Trackside equipment: Westinghouse small box		1			
39815	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Signal Boxes	Asbestos	Presumed	37			tencore		2			
37513	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Westinghouse Boxes	Asbestos	Presumed	38			Trackside equipment: Westinghouse small box		1			
39412	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Westinghouse Boxes	Asbestos	Presumed	39			Trackside equipment: Westinghouse large box		1			
37514	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Westinghouse Boxes	Asbestos	Removed	40			Trackside equipment: Westinghouse small box Notes from 2022 re-inspection: Removed		1			
37515	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Signal Boxes	Asbestos	Presumed	40			tencore		1			
37516	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	41		LHS	Woven cable insulation. Entry: LHS, Exit: OTX. Numerous amounts					
37517	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	42		LHS	Woven cable insulation. Route: JH2 2x25, JH3 3x20, 2x25mm					
37518	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	57		LHS	Orange lamp CAS. Route: Gaining 1x20mm JH3					
39597	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	72		LHS	Orange lamp CAS. Route: losing 1x20mm JH3, Gaining 1x20mm JH3					
37519	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	85		LHS	Orange lamp CAS. Route: losing 1x20mm JH3, Gaining 1x20mm JH3					
37520	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	99		LHS	Orange lamp CAS. Route: losing 1x20mm JH3, Gaining 1x20mm JH3					
37521	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	112		LHS	Orange lamp CAS. Route: losing 1x20mm JH3, Gaining 1x20mm JH3					
37522	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	126		LHS	Orange lamp CAS. Route: losing 1x20mm JH3, Gaining 1x20mm JH3					
37523	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	140		LHS	Orange lamp CAS. Route: losing 1x20mm JH3, Gaining 1x20mm JH3					
37524	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Signal Boxes	Asbestos	Known	150		RHS	Red lamp CAS					
37525	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Signal Boxes	Asbestos	Known	150		RHS	Red lamp CAS. Route: 1x20mm, Exit: OTX					



Hazardous Material Asset Register - Summary



P066-P - PIC Line - Green Park to Hyde Park Corner

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37526	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Track Section Switches	Asbestos	Removed	177		RHS	Current rail isolating switch 352 & 352a Asbestos board surrounding removed by Edenbeck Services Ltd ES9541e 27/09/2018		2			
39712	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Cement Cable Troughing & Debris	Asbestos	Known	177		LHS	cement troughing . 2m x 3					
37527	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Westinghouse Boxes	Asbestos	Presumed	285		LHS	Trackside equipment: Westinghouse small box. Route: losing 1x20mm JH3					
37528	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Westinghouse Boxes	Asbestos	Presumed	292		LHS	Trackside equipment: Westinghouse small box. Route: Gaining 1x20mm, losing 1x20mm					
37529	ACTIVE	P	P066-P-RD01	Road 01 - PIC - Green Park to Hyde Park Corner	Westinghouse Boxes	Asbestos	Presumed	292		LHS	Trackside equipment: Westinghouse small box. Route: losing 1x20mm JH3					
37771	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	0	20	LHS	Cloth. Cable sheath, Route: JH2 2x15mm, 20mmx1		3			
37722	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	0			Cloth. Cable sheath. Entry: Platform head wall, Route: JH1 1x15mm, 1x25mm, JH3 2 x 20mm, 2 x 15mm, JH4 1 x 20mm, 1 x 25mm		8			
37723	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Ducts	Asbestos	Strongly Presumed	1		LHS	Bitumen. cable duct lining		2			
37724	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	3		RHS	Cloth. Cable sheath. Route: Cable merge onto 4JH. Numerous amounts					
37565	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	4		RHS	Cloth. Cable sheath,Route: Gaining 1x15mm JH1. numerous amounts					
37725	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	15	18	RHS	Cloth. Cable sheath. Route: Between JH2-JH4 and between trackside equipment 10-12mm, Exit: Trackside equipment. Numerous amounts					
37564	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	15		RHS	Cloth. Cable sheath,Route: Joining JH1, numerous amounts					
37726	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	18		RHS	Cloth. Cable sheath. Route: JH2 1x25, 1x15mm, JH3 1x25mm, JH4 1x15mm, 1x25mm		5			
39603	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	47		RHS	Cloth. Cable sheath. Entry: Westinghouse small box Small, Route: JH2 1x15mm		1			
37727	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	277		RHS	Cloth. Cable sheath. Entry: Westinghouse small box large, Route: Gaining JH4 1x45mm		6			
37728	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	279		RHS	Cloth. Cable sheath. Entry: Westinghouse small box large, Route: JH4 1x45mm, Exit: Westinghouse small box large		7			
37729	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	285	289	RHS	Cloth. Cable sheath. Route: Between JH2-JH4 & Trackside equipment. Numerous amounts					



Hazardous Material Asset Register - Summary



P066-P - PIC Line - Green Park to Hyde Park Corner

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37730	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	289		RHS	Cloth. Cable sheath. Route: JH2 2x25mm, 3x15mm, JH3 2x20mm, JH4 1x45mm, 2x20mm, 1x15mm		11			
37731	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	301		RHS	Cloth. Cable sheath. Route: Gaining JH3 1x15mm		12			
37732	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	302		RHS	Cloth. Cable sheath. Route: Losing JH3 1x15mm		11			
37733	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	315		RHS	Cloth. Cable sheath. Entry: JH3 Westinghouse small box small, Route: 1x15mm JH3, Exit: JH3 Westinghouse small box small		1			
37734	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	407		RHS	Cloth. Cable sheath. Route: Gaining 2x15mm					
39763	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	411	413	RHS	Cloth. Cable sheath. Route: JH2-JH3 & Trackside equipment Between 10-45mm					
37735	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	413	414	RHS	Cloth. Cable sheath. Route: JH2 5x15mm, 3x20mm, 1x25mm, JH3 2x20mm, 1x15mm, JH4 2x20mm, 1x15mm, 1x45mm		16			
37736	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	426		RHS	Spliced cable sheath. Route: JH4 1x20mm		2			
37737	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	430		RHS	Cloth. Cable sheath. Route: Losing 1x15mm JH2		15			
39873	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	435		RHS	Cloth. Cable sheath. Route: Gaining 1x15mm JH2		16			
37738	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	450		RHS	Cloth. Cable sheath. Route: Limited access due to height, numerous amounts					
37739	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	455	457	RHS	Cloth. Cable sheath. Entry: Disused CMS, numerous amounts					
37741	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	457	560	RHS	Cloth. Cable sheath. Route: On JH7. numerous amounts					
37740	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	499		RHS	Cloth. Cable sheath. Route: JH7 1x10mm Severed cable		1			
37742	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	524		RHS	Cloth. Cable sheath. Entry: Trackside equipment, Route: JH6 1x45mm Limited access due to height, numerous amounts					
37743	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Track Section Switches	Asbestos	Removed	538	539	RHS	Current rail isolating switches, <2m2 353 & 353A Asbestos board surround no longer present					
39874	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	539		RHS	Cloth. Cable sheath. Entry: Tencore, Route: JH2 1x30mm Gaining, numerous amounts					
37744	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Signal Boxes	Asbestos	Known	539		RHS	Traction circuit breaker kiosk. 16m2					



Hazardous Material Asset Register - Summary



P066-P - PIC Line - Green Park to Hyde Park Corner

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37745	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cement Cable Troughing & Debris	Asbestos	Known	539		RHS	cement troughing		3			
37746	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cement Cable Troughing & Debris	Asbestos	Removed	553		RHS	cement troughing Notes from 2022 re-inspection: Removed		3			
37747	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cement Cable Troughing & Debris	Asbestos	Removed	558		RHS	cement troughing Notes from 2022 re-inspection: Removed		9			
37748	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	559			Cloth. Cable sheath. numerous amounts OTX/RHS					
37749	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	563			Spliced cable. Route: 1x45mm JH6 OTX/RHS		2			
37751	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	573		OTX	Cloth. Cable sheath. Route: 2x15mm OTX, Exit: Signal NI, numerous amounts					
37750	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Signal Boxes	Asbestos	Known	573		LHS	Signal RPB13 AR					
39764	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	573	586	RHS	Cloth. Cable sheath.Route: Between JH2-JH4 & Trackside equipment 15-45mm, numerous amounts					
37752	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	586		RHS	Cloth. Cable sheath. Route: JH2 16x15mm, 2x20mm, JH3 2x35mm, 4x25mm, 1x20mm, JH4 1x20mm, 1x45mm		27			
37753	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	665		RHS	Cloth. Cable sheath. Route: JH3 1x15mm Losing, Exit: Electrical box		1			
37754	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	706	719	RHS	Cloth. Cable sheath. Route: Between JH2-JH4 & Trackside equipment 10-45mm, Exit: Trackside equipment, Numerous amounts					
37755	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	707			Cloth. Cable sheath. Route: 4x15mm, Exit: Signal box OTX/RHS		5			
37756	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	719		RHS	Cloth. Cable sheath, Route: JH2 16x15mm, 1x20mm, 1x25mm, JH3 2x25mm, 1x20mm, JH4 1x45mm, 2x20mm		24			
54068	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Other Electrical Boxes	Asbestos	Presumed	779		LHS	Signal PB13B, RPB13C		2			
37758	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	779	782	RHS	Cloth. Cable sheath, Route: Between JH2-JH4 & Trackside 10-45mm, Exit: Trackside equipment. Numerous amounts					
37757	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	780			Cloth. Cable sheath, Route: 4x15mm, Exit: LHS Trackside equipment OTX/LHS		4			



Hazardous Material Asset Register - Summary



P066-P - PIC Line - Green Park to Hyde Park Corner

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37759	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	782		RHS	Cloth. Cable sheath, Route: JH2 2x20mm, 1x25mm, 12x15mm, JH3 3x25mm, 1x20mm, JH4 1x45mm, 1x20mm		21			
37760	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	799		RHS	Cloth. Cable sheath, Route: Losing 1x15mm JH2		20			
37761	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	804		RHS	Cloth. Cable sheath, Route: Losing 1x15mm JH2		19			
37762	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	865		RHS	Cloth. Cable sheath, Entry: JH2, Route: Westinghouse small box small, Exit: JH3		1			
37763	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	868		RHS	Cloth. Cable sheath, Entry: Westinghouse small box small, Route: JH2 1x25mm		20			
37764	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	873		RHS	Cloth. Cable sheath, Entry: JH2, Route: Westinghouse small box small, Exit: JH2		1			
37765	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	920		RHS	Spliced cable. Route: JH4 1x45mm		2			
39415	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	923	930	RHS	Cloth. Cable sheath, Route: Between JH2-JH4 & Trackside equipment 10-45mm. Numerous amounts					
37766	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cement Cable Troughing & Debris	Asbestos	Removed	926			cement troughing RHS-UTX Notes from 2022 re-inspection: Removed		3			
37768	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Track Section Switches	Asbestos	Removed	926			Current rail section switch. <0.4m2 RHS/UTX 350 & 350A Asbestos board surround removed by Edenbeck Services Ltd ES9541e 27/09/2018					
37769	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Track Section Switches	Asbestos	Removed	926			Current rail section switch. <0.4m2 RHS/UTX 350 Asbestos board removed by Edenbeck Services Ltd ES9541 27/09/2018					
37767	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cement Cable Troughing & Debris	Asbestos	Removed	927			cement troughing RHS/UTX Notes from 2022 re-inspection: Removed		3			
39875	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cement Cable Troughing & Debris	Asbestos	Removed	928			cement troughing RHS/UTX Notes from 2022 re-inspection: Removed		3			
37770	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	930			Cloth. Cable sheath, Route: Limited access due to height. Numerous amounts RHS/OTX					
37569	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	944	970	RHS	Cloth. Cable sheath, Route: Between JH & trackside equipment 10-45mm. Numerous amounts					
37566	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	944		RHS	Spliced cable. Route: JH4 1x20mm		2			



Hazardous Material Asset Register - Summary



P066-P - PIC Line - Green Park to Hyde Park Corner

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37567	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	957			Cloth. Cable sheath, Route: 1x10mm, 5x15mm OTX, Exit: Trackside equipment RHS/OTX		6			
37568	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cement Cable Troughing & Debris	Asbestos	Surveyed – Not Detected	958			cement troughing RHS/OTX - 4RS 2022 Reinspection confirmed concrete		3			
37570	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Ducts	Asbestos	Known	969		LHS	bitumen, cable duct lining		2			
37571	ACTIVE	P	P066-P-WBLO	Road WBLO - PIC - Green Park to Hyde Park Corner	Cable Sheath	Asbestos	Known	970			Cloth in passageway at end, cable sheath. Entry: Platform head wall					

P067-P - PIC Line - Hyde Park Corner Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42730	ACTIVE	P	P067-P-EBLO	Road EBLO (Plt1) - PIC - Hyde Park Corner Stn	Pit Blocks	Asbestos	Surveyed – Not Detected				Pit blocks - Non asbestos					
46245	ACTIVE	P	P067-P-EBLO	Road EBLO (Plt1) - PIC - Hyde Park Corner Stn	Cement Cable Troughing & Debris	Asbestos	Strongly Presumed			UTX	Suspect Asbestos Troughing - E/B road tail wall end towards Knightsbridge. FRC 55452889					
38281	ACTIVE	P	P067-P-EBLO	Road EBLO (Plt1) - PIC - Hyde Park Corner Stn	Signal Boxes	Asbestos	Presumed	30		RHS	630V DC box					
38282	ACTIVE	P	P067-P-EBLO	Road EBLO (Plt1) - PIC - Hyde Park Corner Stn	Westinghouse Boxes	Asbestos	Presumed	90		RHS	Trackside equipment: Westinghosue small box					
38283	ACTIVE	P	P067-P-EBLO	Road EBLO (Plt1) - PIC - Hyde Park Corner Stn	Westinghouse Boxes	Asbestos	Presumed	96		RHS	Trackside equipment: Westinghosue small box					
42731	ACTIVE	P	P067-P-WBLO	Road WBLO (Plt2) - PIC - Hyde Park Corner Stn	Pit Blocks	Asbestos	Removed				Pit blocks - Non asbestos (Removed by Forest 13/08/2008 ES2175)					
38284	ACTIVE	P	P067-P-WBLO	Road WBLO (Plt2) - PIC - Hyde Park Corner Stn	Signal Boxes	Asbestos	Presumed	2			Trackside equipment box: Westinghosue small brake signal box					
38285	ACTIVE	P	P067-P-WBLO	Road WBLO (Plt2) - PIC - Hyde Park Corner Stn	Signal Boxes	Asbestos	Presumed	30			Trackside equipment box: Westinghosue small brake signal box					
38286	ACTIVE	P	P067-P-WBLO	Road WBLO (Plt2) - PIC - Hyde Park Corner Stn	Signal Boxes	Asbestos	Presumed	34			Trackside equipment box: Westinghosue small brake signal box					
38287	ACTIVE	P	P067-P-WBLO	Road WBLO (Plt2) - PIC - Hyde Park Corner Stn	Signal Boxes	Asbestos	Presumed	83			630V DC box					
39831	ACTIVE	P	P067-P-WBLO	Road WBLO (Plt2) - PIC - Hyde Park Corner Stn	Ducts	Asbestos	Sampled – Not Detected	105			bitumen ducts. Floor ducts to UTX					



Hazardous Material Asset Register - Summary



P068-P - PIC Line - Hyde Park Corner to Knightsbridge

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38434	ACTIVE	P	P068-P-EBLO	Road EBLO - PIC - Knightsbridge to Hyde Park Corner	Cable Sheath	Asbestos	Strongly Presumed	0		RHS	Cloth cable sheath. Entry: Platform, Route: JH1 1x15m, 6x25m, 2x35m, JH3 1x15m, JH4 1x45m		1			
38435	ACTIVE	P	P068-P-EBLO	Road EBLO - PIC - Knightsbridge to Hyde Park Corner	Cement Cable Troughing & Debris	Asbestos	Removed	3		RHS	Cement troughing, 0.5m Asbestos Troughing was removed by Edenbeck ES11165 28/03/2019					
38436	ACTIVE	P	P068-P-EBLO	Road EBLO - PIC - Knightsbridge to Hyde Park Corner	Cable Sheath	Asbestos	Strongly Presumed	5		OTX	Cloth cable sheath. Entry: N/A, Route: JH2 2x25, Exit: Signal A701		2			
38437	ACTIVE	P	P068-P-EBLO	Road EBLO - PIC - Knightsbridge to Hyde Park Corner	Cable Sheath	Asbestos	Strongly Presumed	5	8	LHS	Cloth cable sheath. Exit: OTX		1			
38438	ACTIVE	P	P068-P-EBLO	Road EBLO - PIC - Knightsbridge to Hyde Park Corner	Cable Sheath	Asbestos	Strongly Presumed	7	9	RHS	Cloth cable sheath. Entry: Track side, Route: In between JH2 - JH4 15mm - 35mm, numerous amounts					
38439	ACTIVE	P	P068-P-EBLO	Road EBLO - PIC - Knightsbridge to Hyde Park Corner	Cable Sheath	Asbestos	Strongly Presumed	9		RHS	Cloth cable sheath. Route: JH2 6x25mm, 1x15mm, JH3 1x15mm, JH4 1x45mm		9			
38440	ACTIVE	P	P068-P-EBLO	Road EBLO - PIC - Knightsbridge to Hyde Park Corner	Cable Sheath	Asbestos	Strongly Presumed	10		RHS	Cloth cable sheath. Entry: WHS, Route: JH2 1x25mm gain		8			
39969	ACTIVE	P	P068-P-EBLO	Road EBLO - PIC - Knightsbridge to Hyde Park Corner	Cable Sheath	Asbestos	Strongly Presumed	10		RHS	Cloth cable sheath. Route: JH2 2x25 lossing, Exit: WHS		7			
38441	ACTIVE	P	P068-P-EBLO	Road EBLO - PIC - Knightsbridge to Hyde Park Corner	Cable Sheath	Asbestos	Strongly Presumed	15		RHS	Cloth cable sheath. Entry: WHS, Route: JH2 1x25mm gain		9			
38442	ACTIVE	P	P068-P-EBLO	Road EBLO - PIC - Knightsbridge to Hyde Park Corner	Cable Sheath	Asbestos	Strongly Presumed	19		RHS	Cloth cable sheath. Route: Lossing JH2 1x25m, Exit: WHS		9			
38443	ACTIVE	P	P068-P-EBLO	Road EBLO - PIC - Knightsbridge to Hyde Park Corner	Cable Sheath	Asbestos	Strongly Presumed	66		RHS	Cloth cable sheath. Route: Lossing JH2 1x25m, Exit: WHS		8			
38444	ACTIVE	P	P068-P-EBLO	Road EBLO - PIC - Knightsbridge to Hyde Park Corner	Cable Sheath	Asbestos	Strongly Presumed	67		RHS	Cloth cable sheath. Route: Lossing JH2 1x25m, Exit: WHS		7			
39970	ACTIVE	P	P068-P-EBLO	Road EBLO - PIC - Knightsbridge to Hyde Park Corner	Cable Sheath	Asbestos	Strongly Presumed	124		RHS	Cloth cable sheath splice. Route: JH4 1x45m		2			
38445	ACTIVE	P	P068-P-EBLO	Road EBLO - PIC - Knightsbridge to Hyde Park Corner	Cable Sheath	Asbestos	Strongly Presumed	167		RHS	Cloth cable sheath. Entry: Trackside equipment, Route: JH2 7x25m, 1x30m, JH3 1x30m 1x25m, JH4 1x45m		11			
39452	ACTIVE	P	P068-P-EBLO	Road EBLO - PIC - Knightsbridge to Hyde Park Corner	Cable Sheath	Asbestos	Strongly Presumed	174		RHS	Cloth cable sheath. Route: Lossing JH2 1x25m, Exit: WHS		10			
38446	ACTIVE	P	P068-P-EBLO	Road EBLO - PIC - Knightsbridge to Hyde Park Corner	Cable Sheath	Asbestos	Strongly Presumed	179		RHS	Cloth cable sheath. Route: Lossing JH2 1x25m, Exit: WHS		9			
38447	ACTIVE	P	P068-P-EBLO	Road EBLO - PIC - Knightsbridge to Hyde Park Corner	Cable Sheath	Asbestos	Strongly Presumed	182		RHS	Cloth cable sheath. Route: Lossing JH2 1x25m, Exit: WHS		8			
38448	ACTIVE	P	P068-P-EBLO	Road EBLO - PIC - Knightsbridge to Hyde Park Corner	Cable Sheath	Asbestos	Strongly Presumed	294	296	RHS	Cloth cable sheath. Route: In between J2 - JH4 15-45mm, Exit: WHS, numerous amounts					
38449	ACTIVE	P	P068-P-EBLO	Road EBLO - PIC - Knightsbridge to Hyde Park Corner	Cable Sheath	Asbestos	Strongly Presumed	296		RHS	Cloth cable sheath. Route: JH2 1x30mm, 1x25mm, JH3 2x25mm, 1x35mm, JH4 1x45mm		6			



Hazardous Material Asset Register - Summary



P068-P - PIC Line - Hyde Park Corner to Knightsbridge

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38450	ACTIVE	P	P068-P-EBLO	Road EBLO - PIC - Knightsbridge to Hyde Park Corner	Cable Sheath	Asbestos	Strongly Presumed	359	363	RHS	Cloth cable sheath. Entry: Trackside equipment, Route: In between JH2-JH4 25-45mm. Numerous amounts					
38451	ACTIVE	P	P068-P-EBLO	Road EBLO - PIC - Knightsbridge to Hyde Park Corner	Cable Sheath	Asbestos	Strongly Presumed	363		RHS	Cloth cable sheath. Entry: WHS, Route: JH2 1x30mm, 2x25mm, JH3 2x25mm, 1x35mm, JH4 1x45mm		7			
38452	ACTIVE	P	P068-P-EBLO	Road EBLO - PIC - Knightsbridge to Hyde Park Corner	Cable Sheath	Asbestos	Strongly Presumed	409	412	RHS	Cloth cable sheath. Entry: Trackside equipment, Route: In between JH2-JH4 25-45mm, Exit: Ten Core and Trackside Equipment. Numerous amounts					
38453	ACTIVE	P	P068-P-EBLO	Road EBLO - PIC - Knightsbridge to Hyde Park Corner	Cable Sheath	Asbestos	Strongly Presumed	412		RHS	Cloth cable sheath. Route: JH2 1x30mm, 2x25mm, JH3 2x35mm, 2x25mm, JH4 1x45mm		8			
38454	ACTIVE	P	P068-P-EBLO	Road EBLO - PIC - Knightsbridge to Hyde Park Corner	Cable Sheath	Asbestos	Strongly Presumed	424		RHS	Cable sheath splice, Route: JH2 1x45m		2			
39648	ACTIVE	P	P068-P-EBLO	Road EBLO - PIC - Knightsbridge to Hyde Park Corner	Cable Sheath	Asbestos	Strongly Presumed	428		RHS	Cloth cable sheath. Route: 2 cables 2x25m lossing, Exit: WHS		6			
38455	ACTIVE	P	P068-P-EBLO	Road EBLO - PIC - Knightsbridge to Hyde Park Corner	Cement Cable Troughing & Debris	Asbestos	Removed	428		RHS	Cement troughing, 6m Asbestos cement troughing was removed by Edenbeck ES11165 28/03/2019					
38456	ACTIVE	P	P068-P-EBLO	Road EBLO - PIC - Knightsbridge to Hyde Park Corner	Cable Sheath	Asbestos	Strongly Presumed	433		RHS	Cloth cable sheath. Route: Exit into storage centre box (Limited access cables bundled up sitted with cable ties)					
38339	ACTIVE	P	P068-P-WBLO	Road WBLO - PIC - Hyde Park Corner to Knightsbridge	Cable Sheath	Asbestos	Known	0		RHS	Cloth cable sheath. Route: JH1 2x15, JH2 4x25, 2x15, 1x35, JH4 1x45, JH6 2x45					
38343	ACTIVE	P	P068-P-WBLO	Road WBLO - PIC - Hyde Park Corner to Knightsbridge	Cable Sheath	Asbestos	Known	7	30	RHS	Cloth cable sheath. Route: Between JH2-JH4 15-45mm, Exit, AV Box					
38340	ACTIVE	P	P068-P-WBLO	Road WBLO - PIC - Hyde Park Corner to Knightsbridge	Cable Sheath	Asbestos	Known	8	10	RHS	Cloth cable sheath. Route: Loss 2x45 into wall, Exit: Into wall					
38341	ACTIVE	P	P068-P-WBLO	Road WBLO - PIC - Hyde Park Corner to Knightsbridge	Cable Sheath	Asbestos	Known	14	17	RHS	cable, spliced. Route: JH3 1x25m					
38342	ACTIVE	P	P068-P-WBLO	Road WBLO - PIC - Hyde Park Corner to Knightsbridge	Cable Sheath	Asbestos	Known	23		RHS	cable, spliced. Route: JH4 1x35mm					
39640	ACTIVE	P	P068-P-WBLO	Road WBLO - PIC - Hyde Park Corner to Knightsbridge	Cable Sheath	Asbestos	Known	30		RHS	Cloth cable sheath. Route: JH3 4x25mm, JH4 1x35mm					
38158	ACTIVE	P	P068-P-WBLO	Road WBLO - PIC - Hyde Park Corner to Knightsbridge	Cable Sheath	Asbestos	Known	75		RHS	cable, spliced. Route: JH3 1x25mm					
38159	ACTIVE	P	P068-P-WBLO	Road WBLO - PIC - Hyde Park Corner to Knightsbridge	Cable Sheath	Asbestos	Known	115	127	RHS	Cloth cable sheath. Entry: Trackside Equipment, Route: JH2 4x15, JH3 4x20, JH4 1x35					
38160	ACTIVE	P	P068-P-WBLO	Road WBLO - PIC - Hyde Park Corner to Knightsbridge	Cable Sheath	Asbestos	Known	257		RHS	Cloth cable sheath. Entry: Trackside Equipment, Route: JH2 1x25mm, 7x15, JH3 4x25, JH4 1x35mm					
38161	ACTIVE	P	P068-P-WBLO	Road WBLO - PIC - Hyde Park Corner to Knightsbridge	Cable Sheath	Asbestos	Known	277		RHS	Cloth cable sheath. Entry: Westinghouse small box small, Route: Gaining 1x15 JH2					



Hazardous Material Asset Register - Summary



P068-P - PIC Line - Hyde Park Corner to Knightsbridge

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38162	ACTIVE	P	P068-P-WBLO	Road WBLO - PIC - Hyde Park Corner to Knightsbridge	Cable Sheath	Asbestos	Known	282		RHS	Cloth cable sheath. Route: Lossing 1x15 JH2					
38163	ACTIVE	P	P068-P-WBLO	Road WBLO - PIC - Hyde Park Corner to Knightsbridge	Cable Sheath	Asbestos	Known	328	331	RHS	Cloth cable sheath. Entry: Trackside Equipment, Route: Between JH2-JH4 15-35mm					
39827	ACTIVE	P	P068-P-WBLO	Road WBLO - PIC - Hyde Park Corner to Knightsbridge	Cable Sheath	Asbestos	Known	331		RHS	Cloth cable sheath. Entry: Westinghouse small box small, Route: JH2 1x30mm, 1x20mm, 7x15mm, JH3 4x20mm, JH4 1x35					
38164	ACTIVE	P	P068-P-WBLO	Road WBLO - PIC - Hyde Park Corner to Knightsbridge	Cable Sheath	Asbestos	Known	342		RHS	Cloth cable sheath. Entry: Westinghouse small box small, Route: Gain 1x15mm JH2					
38165	ACTIVE	P	P068-P-WBLO	Road WBLO - PIC - Hyde Park Corner to Knightsbridge	Cable Sheath	Asbestos	Known	346		RHS	Cloth cable sheath. Route: Lossing 1x15 , Exit: Westinghouse small box					
38166	ACTIVE	P	P068-P-WBLO	Road WBLO - PIC - Hyde Park Corner to Knightsbridge	Cable Sheath	Asbestos	Known	394	397	RHS	Cloth cable sheath. Route: between JH2-JH4 15-35mm					
38167	ACTIVE	P	P068-P-WBLO	Road WBLO - PIC - Hyde Park Corner to Knightsbridge	Cable Sheath	Asbestos	Known	397		RHS	Cloth cable sheath. Entry: Tencore/ Trackside Equipment, Route: JH2 1x30, 1x20, 8x15, JH3 4x20, JH4 1x35					
38168	ACTIVE	P	P068-P-WBLO	Road WBLO - PIC - Hyde Park Corner to Knightsbridge	Cable Sheath	Asbestos	Known	406		RHS	Cloth cable sheath. Entry: Westinghouse small box, Route: Gaining 1x15mm JH2					
38169	ACTIVE	P	P068-P-WBLO	Road WBLO - PIC - Hyde Park Corner to Knightsbridge	Cable Sheath	Asbestos	Known	410		RHS	Cloth cable sheath. Route: Lossing 1x15 JH2, Exit: Westinghouse small box					
38170	ACTIVE	P	P068-P-WBLO	Road WBLO - PIC - Hyde Park Corner to Knightsbridge	Ducts	Asbestos	Known	422		RHS	cable duct lining. Entry: SP Platform Head Wall, Route: Seal with concreted					
38171	ACTIVE	P	P068-P-WBLO	Road WBLO - PIC - Hyde Park Corner to Knightsbridge	Cable Sheath	Asbestos	Known	424		RHS	Cloth cable sheath.					

P069-P - PIC Line - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44709	ACTIVE	P	P069-P-EBLO	Road EBLO (Plt1) - PIC - Knightsbridge Stn	Westinghouse Boxes	Asbestos	Presumed				Small Westinghouse Boxes - Throughout Notes from 2022 re-inspection: 2 x SWH			R173944		
42763	ACTIVE	P	P069-P-EBLO	Road EBLO (Plt1) - PIC - Knightsbridge Stn	Pit Blocks	Asbestos	Known				Pit blocks - Non asbestos Asbestos ID Report R40226 found substantial Amosite within the following locations: Pitblock (100 outer) Pitblock (105 outer) Pitblock (53 inner)					
44708	ACTIVE	P	P069-P-WBLO	Road WBLO (Plt2) - PIC - Knightsbridge Stn	Westinghouse Boxes	Asbestos	Presumed				Small Westinghouse Boxes - Throughout Notes from 2022 re-inspection: 2 x SWH			R173943		



Hazardous Material Asset Register - Summary



P069-P - PIC Line - Knightsbridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42764	ACTIVE	P	P069-P-WBLO	Road WBLO (Plt2) - PIC - Knightsbridge Stn	Pit Blocks	Asbestos	Known				Pit blocks - Non asbestos Asbestos ID Report R40226 found substantial Amosite within the following locations: Pitblock (100 outer) Pitblock (105 outer) Pitblock (53 inner)					

P072-P - PIC Line - Knightsbridge to South Kensington

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42986	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable: Wrap	Asbestos	Known				Braided cables, throughout, to J Hangers 2, 3 and 4 from 0m to 1141m RHS and 0m to 2209m RHS on South Kensington to Knightsbridge			R525426	N	N
42987	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Wrap	Asbestos	Known	0	2209	RHS	Braided cables, throughout, to J Hangers 2, 3 and 4 from 0m to 1141m RHS and 0m to 2209m RHS on South Kensington to Knightsbridge			R525426		
42978	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Caulking	Asbestos	Sampled – Not Detected				Caulking - grout, wood, throughout between flanges to metal tunnel ring TR10 at BRS 5m LHS on South Kensington to Knightsbridge. Note start at South Kensington Platform 4.			R525426	N	N
46254	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Westinghouse Boxes	Asbestos	Known	6		LHS	Signal box A681 3x 10 core 1x Westinghouse box Large					
40828	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Removed	6	27	RHS	Cloth. cable sheath					
41755	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Ducts: Cement	Asbestos	Sampled – Not Detected				4 x Cable Ducts to tunnel wall. 15m from platform 4 E/B Piccadilly Line				N	N
46255	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Wrap	Asbestos	Removed	27		LHS	Cable wrapping Notes from 2022 re-inspection: Removed	1				
40829	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Removed	27		RHS	Cloth. cable sheath		8			
40830	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	27	31	RHS	Cloth. cable sheath		7			
40831	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cement Cable Troughing & Debris	Asbestos	Removed	32		RHS	Cement troughing Notes from 2022 re-inspection: Removed		1			
42979	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Caulking	Asbestos	Sampled – Not Detected				Caulking - grout, wood, clay, throughout between flanges to metal tunnel ring TR38 at BRS 35m LHS on South Kensington to Knightsbri			R525426	N	N
40832	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cement Cable Troughing & Debris	Asbestos	Known	60		RHS	Cement troughing		1			



Hazardous Material Asset Register - Summary



P072-P - PIC Line - Knightsbridge to South Kensington

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40833	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cement Cable Troughing & Debris	Asbestos	Known	64		RHS	Cement troughing. 1.5m					
40835	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	65	68	RHS	Cloth. cable sheath 2x Westinghouse box Small		3			
40834	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	65		RHS	Cloth. cable sheath 1x Westinghouse box Large		4			
40836	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	170	173	RHS	Cloth. cable sheath, numerous amounts 1x Westinghouse box Large 1x Signal 2x 10 core					
39990	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	173		RHS	Cloth. cable sheath		8			
40837	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	213		RHS	Cloth. cable sheath 2x Westinghouse box Small 1x Westinghouse box Large 1x Signal		7			
39497	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	218	321	RHS	Cloth. cable sheath		4			
42980	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Caulking	Asbestos	Sampled – Not Detected				Caulking - grout, wood, throughout between flanges to metal tunnel ring TR465 at BRS 241m RHS on South Kensington to Knightsbridge			R525426	N	N
40838	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	251		RHS	Cloth. cable sheath		25			
40839	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	322		RHS	Cloth. cable sheath 1x Westinghouse box Large 1x Signal		9			
40840	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Wrap	Asbestos	Known	326		RHS	cable wrap 2x 10 core		2			
40841	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	340		RHS	Cloth. cable sheath 1x Westinghouse box Small		10			
40842	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	344		RHS	Cloth. cable sheath 1x Westinghouse box Small		9			
40843	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	445		RHS	Cloth. cable sheath splice		9			
40844	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	446	449	LHS	Cloth. cable sheath, numerous amounts 1x Westinghouse box Large 2x 10 core					
39484	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	446		OTX	Cloth. cable sheath		6			
40845	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	456		RHS	Cloth. cable sheath 1x Westinghouse box Small		8			
39790	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	460		RHS	Cloth. cable sheath 1x Westinghouse box Small		9			



Hazardous Material Asset Register - Summary



P072-P - PIC Line - Knightsbridge to South Kensington

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42981	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Caulking	Asbestos	Sampled – Not Detected				Caulking - grout, wood, clay, throughout between flanges to metal tunnel ring TR883 at BRS 461m RHS on South Kensington to Knightsbridge			R525426	N	N
40846	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	476			Cloth. cable sheaths enter disused station, numerous amounts 1x Westinghouse box Large					
39485	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Signal Boxes	Asbestos	Presumed	476	480	RHS	electrical kiosk		2			
40847	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Presumed	483		RHS	Cloth. cable sheath		7			
42982	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge		Asbestos	Sampled – Not Detected				Brompton Road Disused Start at tunnel ring 906 BRS 485m			R525426	N	N
42983	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Caulking	Asbestos	Sampled – Not Detected				Caulking - grout, wood, clay, throughout between flanges to metal tunnel ring TR1012 at BRS 523m LHS on South Kensington to Knightsbridge			R525426	N	N
40848	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Wrap	Asbestos	Known	586		LHS	cable wrap		2			
42984	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge		Asbestos	Sampled – Not Detected				Brompton Road Disused End at tunnel ring 1046 BRS 586m			R525426	N	N
40849	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	603		LHS	Cloth. cable sheath 1x Westinghouse box Large 1x Signal 2x 10 core		8			
40850	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	610		RHS	Cloth. cable sheath 1x Westinghouse box Small		7			
40851	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	615		RHS	Cloth. cable sheath 1x Westinghouse box Small		6			
42985	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Caulking	Asbestos	Sampled – Not Detected				Caulking - grout, wood, throughout between flanges to metal tunnel ring TR1368 at BRS 701m RHS on South Kensington to Knightsbridge			R525426	N	N
39486	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Wrap	Asbestos	Known	722		LHS	cable wrap		2			
40852	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	737		RHS	Cloth. cable sheath splice		1			
39996	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	747		RHS	Cloth. cable sheath 1x Westinghouse box Small		5			
40930	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	752		RHS	Cloth. cable sheath 1x Westinghouse box Small		4			
40931	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	917		RHS	Cloth. cable sheath splice		1			



Hazardous Material Asset Register - Summary



P072-P - PIC Line - Knightsbridge to South Kensington

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40932	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	946	948	RHS	Cloth. cable sheath, numerous amounts 1x Westinghouse box Large 1x Signal					
40933	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	948		LHS	Cloth. cable sheath 2x 10 core EP Valve		6			
40934	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	962		LHS	Cloth. cable sheath 3x Westinghouse box Small		5			
39794	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Wrap	Asbestos	Strongly Presumed	997		LHS	cable wrap		1			
40935	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	1022		RHS	Cloth. cable sheath 1x Westinghouse box Small		4			
40936	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	1022		OTX	Cloth. cable sheath		3			
40937	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	1036	1041	RHS	Cloth. cable sheath, numerous amounts 2x Signal boxes 2x Westinghouse box Large 3x 10 core 1x EP Valve					
40938	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	1048		RHS	Cloth. cable sheath 1x Westinghouse box Small		7			
40939	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	1052		RHS	Cloth. cable sheath 1x Westinghouse box Small		6			
42988	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Caulking	Asbestos	Sampled – Not Detected				Caulking - grout, wood, throughout between flanges to metal tunnel ring TR2061 at BRS 1061m RHS on South Kensington to Knightsbridge. Note end at Knightsbridge Platform 1			R525426	N	N
40940	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	1113	1116	RHS	Cloth. cable sheath, numerous amounts 1x Westinghouse box Large 3x 10 core 1x Signal 1x EP Valve					
40941	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	1119		OTX	Cloth. cable sheath 1x Westinghouse box Small		6			
40942	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	1124		RHS	Cloth. cable sheath 1x Westinghouse box Small		7			
40943	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	1129		RHS	Cloth. cable sheath 1x 10 core		8			
40944	ACTIVE	P	P072-P-EBLO	Road EBLO - PIC - South Kensington to Knightsbridge	Cable Sheath	Asbestos	Strongly Presumed	1134		RHS	Cloth. cable sheath		7			
38458	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	0	5	RHS	Cloth cable sheath. Entry: Platform end wall, Route: JH2 7x15mm, 1x30mm, JH3 4x20mm, JH4 1x20mm, 1x45mm		14			



Hazardous Material Asset Register - Summary



P072-P - PIC Line - Knightsbridge to South Kensington

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38509	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Westinghouse Boxes	Asbestos	Presumed				Trackside equipment: Westinghouse small box					
38457	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Strongly Presumed	1		LHS	Cloth cable sheath. Sealed with concrete					
38459	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	5		RHS	Cloth cable sheath. Entry: WHS small, Route: JH2 1x15mm gained		15			
38460	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	9	14	RHS	Cable sheath 1x 10 core 1x Signal 1x Westinghouse Small Box 1x Westinghouse Large Box 1x EP Valve Route: Between JH2-JH4 15mm-45mm, Exit: Trackside Equipment, numerous amounts					
38461	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	15		RHS	Cloth cable sheath. Route: JH3 1x25mm		2			
38462	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	18		RHS	Cloth cable sheath. Route: JH3 1x25mm		2			
38463	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	19		RHS	Cloth cable sheath. Route: JH2 6x15mm, JH3 3x25mm, 1x15mm, JH4 1x45mm		11			
39838	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	43		RHS	Cloth cable sheath. Route: lossing JH2 1x15mm		10			
39971	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	47		RHS	Cloth cable sheath. Route: Lossing 1x15 JH2, Exit: WHS small		9			
38464	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	76		RHS	Cloth cable sheath. Route: Lossing 1x15 JH2, Exit: WHS small		8			
38465	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	77		RHS	Cloth cable sheath. Route: Lossing 1x15 JH2, Exit: WHS small		7			
38466	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	161		RHS	Cloth cable sheath. Route: JH3 25x1		2			
38467	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	314		RHS	Cloth cable sheath. Entry: JH3, Route: 1x25mm of JH3, Exit: JH3		2			



Hazardous Material Asset Register - Summary



P072-P - PIC Line - Knightsbridge to South Kensington

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38468	ACTIVE	p	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	352		RHS	Cloth cable sheath. Entry: JH3, Route: 1x25mm of JH3, Exit: JH3		2			
38469	ACTIVE	p	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	353		RHS	Cloth cable sheath. Entry: JH3, Route: 1x25mm of JH3, Exit: JH3		2			
39972	ACTIVE	p	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	358		RHS	Cloth cable sheath. Entry: JH4, Route: 1x45mm of JH4, Exit: JH4		2			
38470	ACTIVE	p	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	397	400	RHS	Cloth cable sheath. Route: Between JH2-JH4, 15-35mm, numerous amounts					
38471	ACTIVE	p	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	400		RHS	Cable sheath 1x 10 core 1x EP Valve 1x Signal 1x Westinghouse Large Box Entry:Trackside equipment/Ten Core, Route: JH2 5x15mm, 1x25mm, JH3 4x25mm, JH4 1x45mm		11			
38472	ACTIVE	p	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	406		RHS	Cloth cable sheath. Route: Lossing 1x15mm JH2, Exit: WHS small		10			
38473	ACTIVE	p	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	408		RHS	Cloth cable sheath. Entry:WHS small, Route: Gain 1x15 JH2		11			
38474	ACTIVE	p	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	552		RHS	Cloth cable sheath. Entry: WHS large, Route: gain 2x15 JH2		13			
38475	ACTIVE	p	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	558		RHS	Cloth cable sheath. Entry: WHS small, Route: Gain 1x15 JH2		14			
38476	ACTIVE	p	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	563		RHS	Cloth cable sheath. Route: Lossing 1x15 JH2, Exit: WHS small		13			
46196	ACTIVE	p	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Westinghouse Boxes	Asbestos	Known	577		RHS	1x Westinghouse Small Box		1			
38477	ACTIVE	p	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	626		RHS	Cloth cable sheath. Entry: WHS small, Route: Gain 1x15mm JH2		14			
38478	ACTIVE	p	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	673		RHS	Cloth cable sheath. Entry: JH2, Route: 30x1 JH2, Exit: JH2		2			



Hazardous Material Asset Register - Summary



P072-P - PIC Line - Knightsbridge to South Kensington

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38479	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	679		RHS	Cloth cable sheath.		2			
38480	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	679	685	RHS	kiosk, 1x Westinghouse Large Box Entry: Trackside Equipment, Route: JH1-JH5 between 15-45mm, Exit: Trackside Equipment. Numerous amounts					
38481	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	685		RHS	Cloth cable sheath. Route: JH2 1x35mm, 1x25mm, 8x15mm, JH3 3x20mm, JH4 1x45mm		14			
38482	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	698	707	RHS	Cloth cable sheath. Route: Between JH2-JH4 15-45mm, numerous amounts					
38483	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	706		RHS	Cloth cable sheath 1x Westinghouse Box 1x EP Valve 1x 10 core 1x Signal Route: Lossing 1x15mm, JH2, Exit: WHS small		13			
38484	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	800	803	RHS	Cloth cable sheath. Route: Between JH2-JH4 15-45mm, numerous amounts					
39649	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	803		RHS	Cable sheath 1x Westinghouse Box 1x EP Valve 1x 10 core 1x Signal Route: JH2 8x15, JH3 3x25, JH4 1x45		12			
38485	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	810		RHS	Cloth cable sheath. Route: Loss 1x15mm JH2, Exit: WHS		11			
38486	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	815		RHS	Cloth cable sheath. Route: Loss 1x15mm JH2, Exit: WHS		10			
38487	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	831		RHS	Cloth cable sheath. Route: 1x45 JH4		2			
38488	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	867		RHS	Cable sheath 1x Westinghouse Large Box 1x Signal Entry: WHS large, Route: Gain JH2 2x15mm		12			
38489	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	894		RHS	Cloth cable sheath. Route: Loss 25x1 JH2, Exit: WHS		11			



Hazardous Material Asset Register - Summary



P072-P - PIC Line - Knightsbridge to South Kensington

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38490	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	898		RHS	Cloth cable sheath. Route: Loss 25x1 JH2		10			
39973	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	921	925	RHS	Cable sheath 2x Signal boxes 1x Westinghouse Large Box Entry: Trackside Equipment, numerous amounts					
39839	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	925		RHS	Cable sheath 1x Westinghouse Large Box 1x EP Valve 1x 10 core Route: JH2 1x35, 4x15, JH3 3x20, JH 1x45, Exit: Ten Core small		9			
38491	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	956		RHS	Cloth cable sheath, Route: Lossing 1x15 JH2, Exit: WHS small		8			
38492	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	960		RHS	Cloth cable sheath. Route: Lossing 1x15 JH2, Exit: WHS small		7			
38493	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	996	1000	RHS	Cloth cable sheath 2x Signal boxes Entry: Trackside Equipment, Route: JH1-JH4 between 15-45mm, numerous amounts					
38494	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	1000		RHS	Cable sheath 2x Westinghouse Large Box 1x 10 core 1x EP Valve Route: JH2 1x35, 1x25, 5x15, JH3 3x20, JH4 + 5		10			
54086	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Signal Boxes	Asbestos	Presumed	1003		LHS	Entry: JH8, Route 1x15mm Notes from 2022 re-inspection: Present rail cap rep x1 n cable x1		1			
38495	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	1004		RHS	Cloth cable sheath. Entry: WHS small, Route: Gain 1x15 JH2		11			
39974	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	1008		RHS	Cloth cable sheath. Entry: WHS small, Route: Gain 1x15 JH2		12			
38496	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	1064		RHS	Cloth cable sheath. Entry: WHS small, Route: Gain 1x15 JH2		13			
38497	ACTIVE	P	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	1069		RHS	Cloth cable sheath. Entry: WHS small, Route: Gain 1x15 JH2		14			



Hazardous Material Asset Register - Summary



P072-P - PIC Line - Knightsbridge to South Kensington

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
54087	ACTIVE	p	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Signal Boxes	Asbestos	Presumed	1094		LHS	Cable sheath Entry: WHS small, Route: Gain 1x15 JH2 Notes from 2022 re-inspection: Present rail gap ind n cable		1			
38498	ACTIVE	p	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	1095	1097	RHS	Cable sheath 1x Westinghouse Large Box 1x 10 core 1x Signal 1x EP Valve Route: Between JH2-JH4 15-45mm. Numerous amounts					
38499	ACTIVE	p	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	1097		RHS	Cloth cable sheath. Route: JH2 2x35, 1x25, 7x15, JH3 3x20, JH 1x45		14			
38500	ACTIVE	p	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	1100		RHS	Cloth cable sheath. Route: 1x15 JH2		13			
38501	ACTIVE	p	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Removed	1102		OTX	cement. Route: 4x45mm, 2x15mm Notes from 2022 re-inspection: Removed		6			
38502	ACTIVE	p	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Removed	1102	1105	OTX	Cement. Numerous amounts Notes from 2022 re-inspection: Removed					
38504	ACTIVE	p	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	1118		RHS	Cloth cable sheath. Route: Into overhead shaft		4			
38503	ACTIVE	p	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	1119		RHS	Cloth cable sheath Troughing x2 Entry: K, 0.5m					
46197	ACTIVE	p	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington		Asbestos	Known				Route: Lossing 2 JH2, Exit: WHS large				N	N
38505	ACTIVE	p	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	1125		RHS	Cloth cable sheath Troughing x1 0.5m					
39453	ACTIVE	p	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	1130		RHS	Cloth cable sheath. Entry: WHS small, Gain 1x15 JH2		7			
38506	ACTIVE	p	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	1135		RHS	Cloth cable sheath 1x Westinghouse Small Box Route: Loss 1x15 JH2		6			
38507	ACTIVE	p	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	1141		OTX	Cloth cable sheath.					
38508	ACTIVE	p	P072-P-WBLO	Road WBLO - PIC - Knightsbridge to South Kensington	Cable Sheath	Asbestos	Known	1143		LHS	Cement		11			



Hazardous Material Asset Register - Summary



P074-P - PIC Line - South Kensington to Gloucester Road

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37671	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	0		RHS	cloth. Cable sheathing, Route: JH2 1x15mm, JH3 Numerous (10 15-25m) JH4 1x45, 1x15mm)		13			
54053	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Ducts	Asbestos	Presumed	0		LHS	Cement cable duct lining 4no.		4			
53998	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Signal Boxes	Asbestos	Presumed	5		RHS	Signal A671		1			
39868	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cement Cable Troughing & Debris	Asbestos	Removed	5			cement troughing . Under track RHS/UTX Removed by Econ Construction on 01/08/2019. Please refer to job reference no: ES9048.		3			
39414	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	5	7	RHS	cloth. Cable sheathing, Route: Between JH2-JH4 (10-45mm), Exit: Trackside Equipment. Numerous amounts					
37672	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	7		RHS	cloth. Cable sheathing, Route: JH2 1x15, JH3 8x15, 1x25, JH4 1x45mm		11			
37673	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	14		RHS	cloth. Cable sheathing, Route: Losing 1x15mm JH3, Exit: Westinghouse small box		10			
37674	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	19		RHS	cloth. Cable sheathing, Route: Losing 1x15mm JH3, Exit: Westinghouse small box		9			
37675	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	65		RHS	cloth. Cable sheathing, Route: Losing 1x15mm JH3, Exit: Westinghouse small box		8			
37676	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	67		RHS	cloth. Cable sheathing, Route: Losing 1x15mm JH4, Exit: Westinghouse small box		7			
37677	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	210		RHS	cable spliced. Route: JH4 1x45mm		2			
37678	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	255		RHS	cable spliced. Route: JH2 1x25mm		2			
37679	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	285	285	RHS	cloth. Cable sheathing, Entry: Trackside Equipment, Route: Between JH2-JH4 15-25mm, Exit: Trackside Equipment. Numerous amounts					
37680	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	285		RHS	cloth. Cable sheathing, Route: JH2 1x20, JH3 5x15, JH4 1x45mm		7			
37681	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	310		RHS	cloth. Cable sheathing, Route: Losing JH3 1x15mm		6			
37682	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	315		RHS	cloth. Cable sheathing, Route: Losing JH3 1x15mm		5			
37683	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	326		RHS	cable spliced. Route: JH4 1x45mm		2			



Hazardous Material Asset Register - Summary



P074-P - PIC Line - South Kensington to Gloucester Road

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37684	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	416	420	RHS	cloth. Cable sheathing, Entry: Trackside Equipment, Route: Between JH2-JH4 15-25mm, Exit: Tracksdie Equipment. Numerous amounts					
37685	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	420		RHS	Cloth. Cable sheathing, Route: JH2 1x20, JH3 1x25, 5x15, JH4mm. Numerous amounts					
39601	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	426		RHS	Cloth. Cable sheathing, Route: Losing JH3 1x15mm, Exit: Westinghouse small box		4			
37686	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	431		RHS	Cloth. Cable sheathing, Route: Losing JH3 1x15mm, Exit: Westinghouse small box		3			
37687	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	497	501	RHS	Cloth. Cable sheathing, Entry: Trackside Equipment, Route: Between JH2-JH4 15-25mm. Numerous amounts					
37688	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	501		RHS	Cloth. Cable sheathing, Route: JH2 1x25, JH3 2x25, 6x15, JH4 1x45mm		10			
37689	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	518		RHS	Cloth. Cable sheathing, Entry: Westinghouse small box, Route: Gaining JH3 1x15mm		11			
39869	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	523		RHS	Cloth. Cable sheathing, Route: Losing JH 1x15mm, Exit: Westinghouse small box		10			
37690	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	560		UTX	Cloth. Cable sheathing, Entry: JH2 2x15mm, Route: JH2 2x15mm, Exit: Signal Box A679C		7			
37691	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	560	563	RHS	Cloth. Cable sheathing, Entry: Trackside Equipment, Route: Between JH1-JH4 10-45mm. Numerous amounts					
39761	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	563		RHS	Cloth. Cable sheathing, Route: JH2 1x20, JH3 2x25, 7x15, 1x30, JH4 1x45mm		13			
37692	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	569		RHS	Cloth. Cable sheathing, Entry: Westinghouse small box, Route: Gaining JH3 1x15mm		14			
37693	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	574		RHS	Cloth. Cable sheathing, Route: Losing JH3 1x15mm, Exit: Westinghouse small box		13			
37694	ACTIVE	P	P074-P-EBLO	Road EBLO - PIC - Gloucester Road to South Kensington	Cable Sheath	Asbestos	Known	595		RHS	Cloth. Cable sheathing, Exit: Platform head wall. Numerous amounts					
41238	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	0		LHS	Cloth, cable sheathing. Entry: Platform head wall, Route: JH2 7x15, 1x25, 1x20, 1x30, JH3 2x20, 1x35, JH4 1x25mm.		14			
40034	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	3		LHS	Cloth, cable sheathing. Route: Cable drop down from initial top		14			
41239	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	11	13	LHS	Cloth, cable sheathing. Route: Trackside Equipment, numerous amounts					
39537	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	11		RHS	Cloth, cable sheathing. Route: JH2 1x15mm		1			



Hazardous Material Asset Register - Summary



P074-P - PIC Line - South Kensington to Gloucester Road

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41240	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	17			Cloth, cable sheathing. Route: Between JH1-JH3 15-35mm, numerous amounts RHS & OTX					
41241	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	17		RHS	Cloth, cable sheathing. Route: JH2 6x15, JH3 4x25, JH4 1x35mm		15			
41242	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	17		LHS	Cloth, cable sheathing. Exit: Westinghouse small box large Ten Core, numerous amounts					
41243	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	23		RHS	Cloth, cable sheathing. Route: Losing JH2 1x15mm, Exit: Westinghouse small box small		14			
39538	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	26		RHS	Cloth, cable sheathing. Route: Losing JH2 1x15mm, Exit: Westinghouse small box small		13			
41244	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	27		RHS	spliced cable, Route: JH4 1x35mm		2			
41323	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	31		RHS	spliced cable, Route: JH3 1x25mm		2			
41324	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	65		RHS	spliced cable, Route: JH3 1x25mm		2			
39503	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	74		RHS	spliced cable, Route: JH3 1x25mm		2			
41325	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	76		RHS	Cloth, cable sheathing. Route: Losing JH2 1x15mm, Exit: Westinghouse small box small		12			
41326	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	77		RHS	Cloth, cable sheathing. Route: Losing JH2 1x15mm, Exit: Westinghouse small box small		11			
41327	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	228	230	RHS	Cloth, cable sheathing. Route: Between JH2-JH4 15-35mm					
41328	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	230		RHS	Cloth, cable sheathing. Route: JH2 1x30, 6x15, JH4 1x35, JH3 4x20mm		12			
41329	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	244		RHS	Cloth, cable sheathing. Route: Losing JH2 1x15mm, Exit: Westinghouse small box small		11			
41330	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	249		RHS	Cloth, cable sheathing. Entry: Westinghouse small box small, Route: Gaining JH2 1x15mm		12			
41331	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	338	340	RHS	Cloth, cable sheathing. Numerous amounts					
41332	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	340		RHS	Cloth, cable sheathing. Route: JH2 2x30, 5x15, JH3 4x20, JH1 1x35mm		12			
41333	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	347		RHS	Cloth, cable sheathing. Entry: Westinghouse small box small, Route: Gaining JH2 1x15mm		13			
41334	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	352		RHS	Cloth, cable sheathing. Route: JH2 1x15mm, Exit: Westinghouse small box small		12			



Hazardous Material Asset Register - Summary



P074-P - PIC Line - South Kensington to Gloucester Road

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41335	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	460	465	RHS	Cloth, cable sheathing. Route: between JH2-JH4. numerous amounts					
41336	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	465		RHS	Cloth, cable sheathing. Route: JH2 1x30, 8x15, JH3 4x20, JH4 1x35mm		14			
41337	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	488		RHS	Cloth, cable sheathing. Entry: Westinghouse small box small, Route: Gaining 1x15mm JH2		15			
41338	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	492		RHS	Cloth, cable sheathing. Route: Losing 1x15mm JH2, Exit: Westinghouse small box small		14			
41339	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	525		RHS	Cloth, cable sheathing. Route: Losing 1x15mm JH2, Exit: Westinghouse small box small		13			
41340	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	526		RHS	spliced cable, Route: JH4 1x35mm		2			
41341	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	538	542	RHS	Cloth, cable sheathing. Route: Between JH2-JH4 15-35mm, Exit: Trackside Equipment, numerous amounts					
39566	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	542		RHS	Cloth, cable sheathing. Route: JH2 10x15, 2x25, 1x30, JH3 4x20, JH4 1x35mm		8			
39852	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	546		RHS	Cloth, cable sheathing. Entry: Westinghouse small box small, Route: Gain 1x15mm JH2		9			
41342	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	551		RHS	Cloth, cable sheathing. Route: Lose 1x15mm JH2, Exit: Westinghouse small box small		8			
41343	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	593	596	RHS	Cloth, cable sheathing. Entry: Trackside Equipment, Route: Between JH2-JH4. numerous amounts					
41344	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	596		RHS	Cloth, cable sheathing. Route: JH2 9x15, 2x25, 2x30, JH3 4x20, JH4 1x35mm		18			
41345	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	601		RHS	Cloth, cable sheathing. Entry: Westinghouse small box small, Route: Gain 1x15mm JH2		19			
41346	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	605		RHS	Cloth, cable sheathing. Route: Lose 1x15mm JH2, Exit: Westinghouse small box small		18			
39567	ACTIVE	P	P074-P-WBLO	Road WBLO - PIC - South Kensington to Gloucester Road	Cable Sheath	Asbestos	Known	620		RHS	Cloth, cable sheathing. Route: JH2, JH3, JH4, Exit: Platform head wall		18			

P075-P - PIC Line - Gloucester Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42740	ACTIVE	P	P075-P-EBLO	Road EBLO (Pit5) - PIC - Gloucester Road Stn	Pit Blocks	Asbestos	Surveyed – Not Detected				Pit blocks - Non asbestos					



Hazardous Material Asset Register - Summary



P075-P - PIC Line - Gloucester Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39870	ACTIVE	P	P075-P-EBLO	Road EBLO (Plt5) - PIC - Gloucester Road Stn	Westinghouse Boxes	Asbestos	Presumed				Trackside equipment: westinghouse small box throughout Notes from 2022 re-inspection: 2x SWH					
37695	ACTIVE	P	P075-P-WBLO	Road WBLO (Plt4) - PIC - Gloucester Road Stn	Westinghouse Boxes	Asbestos	Presumed				Trackside equipment: westinghouse small box throughout Notes from 2022 re-inspection: 2x SWH					
42739	ACTIVE	P	P075-P-WBLO	Road WBLO (Plt4) - PIC - Gloucester Road Stn	Pit Blocks	Asbestos	Surveyed – Not Detected				Pit blocks - Non asbestos					

P076-P - PIC Line - Gloucester Road to Earls Court

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37552	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	0		RHS	Cloth. cable sheathing, Route: JH2 1x20mm, JH3 1x30mm, 9x15mm, 1x25mm, JH4 1x45mm		13			
37553	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	9	10	RHS	Cloth. cable sheathing, Route: Between JH2-JH4 15-45mm, Exit: Trackside Equipment. Numerous amounts					
39598	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	10		RHS	Cloth. cable sheathing,Route: JH2 1x20mm, JH3 1x30mm, 6x15mm, JH4 1x45mm		9			
37554	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	18		RHS	Cloth. cable sheathing, Route: Losing 1x15mm JH3, Exit: Westinghouse small box small		8			
37555	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	23		RHS	Cloth. cable sheathing, Route: Losing 1x15mm JH3, Exit: Westinghouse small box small		7			
37556	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	78		RHS	Cloth. cable sheathing, Route: Losing 1x15mm JH3		6			
37557	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	79		RHS	Cloth. cable sheathing, Route: Losing 1x15mm JH3		5			
37558	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	219		RHS	cable splice. Route: 1x45mm JH4		2			
39817	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	262		RHS	Cloth. cable sheathing, Route: OTX 2x15mm, Exit: Signal box		2			
37559	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	262	263	RHS	Cloth. cable sheathing, Route: Between JH2-JH4 15-45mm. Numerous amounts					
39713	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	263		RHS	Cloth. cable sheathing, Route: JH2 1x20mm, JH3 5x15mm, JH4 1x45mm		7			
37560	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	291		RHS	Cloth. cable sheathing, Route: Losing 1x15mm JH3, Exit: Westinghouse small box small		6			
37561	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	292		RHS	Cloth. cable sheathing, Route: Losing 1x15mm JH3, Exit: Westinghouse small box small		5			



Hazardous Material Asset Register - Summary



P076-P - PIC Line - Gloucester Road to Earls Court

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39818	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	414	419	RHS	Cloth. cable sheathing,Route: Between JH2-JH4 15-45mm. Numerous amounts					
37562	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	415			Cloth. cable sheathing, Route: 4x15mm OTX, Exit: Signal box LHS/ OTX		4			
37393	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	419	429	RHS	Cloth. cable sheathing, Route: Between JH2-JH4 15-45mm. Numerous amounts					
37563	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	419		RHS	Cloth. cable sheathing, Route: JH2 1x20mm, JH4 1x45mm, JH3 12x15mm		14			
37394	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	429		RHS	Cloth. cable sheath, Route: JH2 1x20mm, JH4 1x45mm, JH3 1x30mm, 6x15mm		9			
37396	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	543	546	RHS	Cloth. cable sheath, Route: JH2 1x20mm, JH3 1x30mm, 7x15mm, JH4 1x45mm		10			
37395	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	544			Cloth. cable sheath, Route: 4x15mm OTX, Exit: Signal box LHS/ OTX		4			
37397	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	591			Cloth. cable sheath, Route: 2x15mm OTX LHS		2			
37398	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	591	593	RHS	Cloth. cable sheath, Route: Between JH2-JH4 15-45mm. Numerous amounts					
37399	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	593		RHS	Cloth. cable sheath, Route: JH2 1x20mm, JH3 1x30mm, 1x25mm, 6x15mm, JH4 1x45mm		10			
39705	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	603		RHS	Cloth. cable sheath, Entry: Westinghouse small box small, Route: Gaining 1x15mm		11			
37400	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	605		RHS	Cloth. cable sheath, Route: Losing 1x15mm, Exit: Westinghouse small box small		10			
37401	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	656			Cloth. cable sheath, Route: 2x15mm OTX, Exit: Signal box LHS/ OTX		2			
37402	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	656	660	RHS	Cloth. cable sheath, Route: Between JH2-JH4 15-45mm. Numerous amounts					
37403	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	660		RHS	Cloth. cable sheath, Route: JH2 1x20mm, JH3 1x30mm, 1x25mm, 1x20mm, 6x15mm, JH4 1x45mm		11			
37404	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	667		RHS	Cloth. cable sheath, Entry: Westinghouse small box small, Route: Gaining 1x15mm JH3		12			
37405	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	669		RHS	Cloth. cable sheath, Entry: Westinghouse small box small, Route: Gaining 1x15mm JH3		13			
37406	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	716		RHS	Cloth. cable sheath, Entry: Westinghouse small box small, Route: Gaining 1x15mm JH3		14			
37407	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	721		RHS	Cloth. cable sheath, Entry: Westinghouse small box small, Route: Gaining 1x15mm JH		15			



Hazardous Material Asset Register - Summary



P076-P - PIC Line - Gloucester Road to Earls Court

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37408	ACTIVE	P	P076-P-EBLO	Road EBLO - PIC - Earls Court to Gloucester Road	Cable Sheath	Asbestos	Known	725		RHS	cable splice. Route: 1x45mm JH4		2			
37696	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Known	0		RHS	Cloth. Cable sheath, Route: JH2 3x20mm, JH3 1x20mm, 7x15mm, 1x30mm, JH4 1x45mm		13			
37697	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Known	13		RHS	Cloth. Cable sheath, Route: Losing 1x15mm JH2, Exit: Westinghouse small box small		12			
37698	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Known	15	18	RHS	Cloth. Cable sheath, Route: Between JH2-JH4 15-45mm. numerous amounts					
37699	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Known	18		RHS	Cloth. Cable sheath, Route: JH2 3x20mm, 1x20mm, 6x15mm JH3 1x20mm, 6x15mm, JH4 1x45mm		18			
37700	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Known	33		RHS	Cloth. Cable sheath, Route: Losing 1x15mm JH3, Exit: Westinghouse small box small		17			
37701	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Known	84		RHS	Cloth. Cable sheath, Route: Losing 1x15mm JH3, Exit: Westinghouse small box small		16			
37702	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Known	85		RHS	Cloth. Cable sheath, Route: Losing 1x15mm JH3, Exit: Westinghouse small box small		15			
37703	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Signal Boxes	Asbestos	Known	140		RHS	Signal A6681, R664. Route: JH2 2x20mm, JH3 1x20mm, 9x15mm, JH 1x45mm		13			
37704	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Signal Boxes	Asbestos	Known	152		RHS	Signal A6681, R664. Route: Losing 1x15mm JH3, Exit: Westinghouse small box		12			
37705	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Known	157		RHS	Cloth. Cable sheath, Route: Losing 1x15mm JH3, Exit: Westinghouse small box		11			
37706	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Known	161		RHS	Spliced cable. Route: JH3 1x20mm		2			
37707	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Known	176		RHS	Spliced cable. Route: JH2 1x20mm		2			
39602	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Known	192		RHS	Spliced cable. Route: JH2 1x20mm		2			
37708	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Known	244		RHS	Spliced cable. Route: JH4 1x45mm					
37709	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Known	315	318	RHS	Cloth. Cable sheath. Route: Between JH2-JH4 15-45mm, numerous amounts					
37710	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Known	318		RHS	Cloth. Cable sheath. Route: JH2 3x20mm, JH3 1x20mm, 1x35mm, 6x15mm, JH4 1x45mm		11			
37711	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Known	328		RHS	Cloth. Cable sheath. Route: Losing 1x15mm JH3, Exit: Westinghouse small box		10			
54069	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Presumed	330		RHS	Cloth cable sheath Route: Losing 1x15mm JH3, Exit: Westinghouse small box		9			



Hazardous Material Asset Register - Summary



P076-P - PIC Line - Gloucester Road to Earls Court

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37712	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Known	515	517	RHS	Cloth. Cable sheath. Numerous amounts					
37713	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Known	517		RHS	Cloth. Cable sheath. Route: JH2 3x20, JH3 2x35, 7x15, JH4 1x45, Exit: 1x20		14			
39762	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Known	523		RHS	Cloth. Cable sheath. Entry: Westinghouse small box small, Route: Gaining JH3 1x15		15			
39871	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Known	527		RHS	Cloth. Cable sheath. Route: Losing JH 1x15, Exit: Westinghouse small box small		14			
37714	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Signal Boxes	Asbestos	Known	584		RHS	Signal A660B. Route: 7x15 JH4 1x45					
37715	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Known	588		RHS	Cloth. Cable sheath. Route: JH2 3x20, JH3 1x20, 1x25, 2x35		13			
37716	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Known	594		RHS	Cloth. Cable sheath. Entry: Westinghouse small box, Route: Gaining 1x15 JH3		13			
37717	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Known	599		RHS	Cloth. Cable sheath. Route: Losing 1x15 JH3, Exit: Westinghouse small box		13			
37718	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Known	650	652	RHS	Cloth. Cable sheath. Route: Between JH2-JH4. numerous amounts					
37719	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Known	652		RHS	Cloth. Cable sheath. Entry: Trackside Equipment, Route: JH2 3x20, JH3 1x20, 2x25, 2x35, JH4 1x45, Exit: 10x15		19			
39872	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Known	685		RHS	Cloth. Cable sheath. Entry: Westinghouse small box small, Route: Gaining 1x15 JH3		20			
37720	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Known	690		RHS	Cloth. Cable sheath. Route: Losing 1x15 JH3, Exit: Westinghouse small box small		19			
37721	ACTIVE	P	P076-P-WBLO	Road WBLO - PIC - Gloucester Road to Earls Court	Cable Sheath	Asbestos	Known	709		RHS	Cloth. Cable sheath. Entry: Platform					

P077-P - PIC Line - Earls Court Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37409	ACTIVE	P	P077-P-EBLO	Road EBLO (Plt5) - PIC - Earls Court Stn	Westinghouse Boxes	Asbestos	Presumed				Trackside equipment: Westinghouse small box throughout Notes from 2022 re-inspection: 2x SWH					
42734	ACTIVE	P	P077-P-EBLO	Road EBLO (Plt5) - PIC - Earls Court Stn	Pit Blocks	Asbestos	Surveyed – Not Detected				Pit blocks - Non asbestos					



Hazardous Material Asset Register - Summary



P077-P - PIC Line - Earls Court Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37410	ACTIVE	p	P077-P-WBLO	Road WBLO (Plt6) - PIC - Earls Court Stn	Westinghouse Boxes	Asbestos	Presumed				Trackside equipment: Westinghouse small box throughout Notes from 2022 re-inspection: 2x SWH					
42736	ACTIVE	p	P077-P-WBLO	Road WBLO (Plt6) - PIC - Earls Court Stn	Pit Blocks	Asbestos	Surveyed – Not Detected				Pit blocks - Non asbestos					

P078-P - PIC Line - Earls Court to Barons Court

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36871	ACTIVE	p	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	2		LHS	Woven cable sheath. Entry: Earth cable, Route: 1x10m		1			
46198	ACTIVE	p	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Presumed	5			Green fibres. Possibly from asbestos cable					
46200	ACTIVE	p	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Debris: Other	Asbestos	Strongly Presumed				Rope debris in surface 2.7m ²	3			N	N
46199	ACTIVE	p	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)		Asbestos	Strongly Presumed				Asbestos containing plaster to foot of tunnel wall	5			N	N
46201	ACTIVE	p	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)		Asbestos	Strongly Presumed				Example of friable edge 2.7m ²	3			N	N
46202	ACTIVE	p	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Debris: Other	Asbestos	Strongly Presumed				Rope debris In middle of yellow arrow delineating extent of recon site 2.7m ²	3			N	N
46203	ACTIVE	p	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Debris: Other	Asbestos	Strongly Presumed				Rope debris in surface 2.7m ²	3			N	N
46204	ACTIVE	p	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Debris: Other	Asbestos	Strongly Presumed				Trace rope debris in surface 2.7m ²	3			N	N
46205	ACTIVE	p	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Debris: Other	Asbestos	Strongly Presumed				Trace rope debris in surface 2.7m ²	3			N	N
46206	ACTIVE	p	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Debris: Other	Asbestos	Strongly Presumed				Rope debris in surface 2.7m ²	3			N	N
46207	ACTIVE	p	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Debris: Other	Asbestos	Strongly Presumed				Rope debris in surface 2.7m ²	3			N	N



Hazardous Material Asset Register - Summary



P078-P - PIC Line - Earls Court to Barons Court

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
46208	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Debris: Other	Asbestos	Strongly Presumed				Rope debris in surface 2.7m ²	3			N	N
36872	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	236		LHS	Woven cable sheath. Entry: Signal, Route: 2x20, 1x10mm, JH1		3			
36873	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	244		LHS	Woven cable sheath. Entry: Cable Run Structure, Route: JH2 1x20, 1x45, JH3 1x20mm (45mm damaged)		3			
36874	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	313			Woven cable sheath. Entry: District Line Above, numerous amounts					
40398	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	407			Woven cable sheath OTX, numerous amounts					
36875	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	409			Woven cable sheath. Entry: Westinghouse small box small, Route: Gain 1x15mm onto JH3, numerous amounts					
36876	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	417			Woven cable sheath. Route: JH3 2x20, JH4 1x45mm		3			
36877	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	420		RHS	Spliced cable		2			
36878	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	484	605	RHS	Signal section Woven cable sheath. Route: (10-45mm) In between trackside equipment box, numerous amounts					
36879	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	605		RHS	Woven cable sheath. Route: JH3 3x20, JH4 1x45, 1x30mm		5			
40399	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cement Cable Troughing & Debris	Asbestos	Known	632			cement troughing 5m x 2. On both sides LHS/UTX					
36880	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Ducts	Asbestos	Strongly Presumed	635		LHS	bitumen, cable duct lining		5			
36881	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	661		RHS	Woven cable sheath. Route: Losing JH3 1x20mm, Exit: Westinghouse small box small		4			
36882	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	663		RHS	Woven cable sheath. Route: Losing JH3 1x20mm, Exit: Westinghouse small box small		3			
36883	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	723	761		Signal Section Woven cable sheath. Route: (10-45mm) In between track side equipment, numerous amounts					



Hazardous Material Asset Register - Summary



P078-P - PIC Line - Earls Court to Barons Court

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36884	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	764		OTX	Woven cable sheath. Route: 2x20mm, numerous amounts					
36885	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	774		RHS	Woven cable sheath. Route: JH3 6x20, JH4 1x45mm		7			
36886	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	818		OTX	Woven cable sheath. Route: 2x20mm, numerous amounts					
36887	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	821		RHS	Woven cable sheath. Route: JH3 2x20, 1x35, JH4 1x45mm, Exit: Westinghouse small box small		4			
36888	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	841		RHS	Woven cable sheath. Route: Losing 1x20mm of JH3, Exit: Westinghouse small box		3			
39555	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	843			Woven cable sheath. Route: Losing 1x20mm of JH3, Exit: Westinghouse small box		2			
36889	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	910		RHS	Spliced cable. Route: JH4 1x45mm		2			
36890	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Signal Boxes	Asbestos	Known	952	968		Signal equipment. Route: (10-45mm) In between track side equipment box, numerous amounts					
36891	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	968		RHS	Woven cable sheath. Route: JH3 8x20, JH4 1x45mm		9			
36892	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	999		RHS	Woven cable sheath. Route: Losing 20mm x1 of JH5, Exit: Westinghouse small box		8			
36893	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	1004		RHS	Woven cable sheath. Route: Losing 20mm x1 of JH5, Exit: Westinghouse small box					
36894	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	1086		RHS	Woven cable sheath. Entry: Trackside equipment, Route: JH3 8x20, 1x25, JH4 1x45mm, numerous amounts					
36896	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	1169	1182		Woven cable sheath Signal section. Route: in between trackside equipment (10-45mm), Exit: Trackside equipment, numerous amounts					
36895	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	1182			Woven cable sheath. Route: JH3 8x20mm		9			
36897	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	1241			Woven cable sheath. Route: JH3 6x20, 1x35, JH4 1x45mm, numerous amounts		8			



Hazardous Material Asset Register - Summary



P078-P - PIC Line - Earls Court to Barons Court

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36899	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Signal Boxes	Asbestos	Known	1286	1306		Signal equipment, numerous amounts					
36898	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	1300			Woven cable sheath. Entry: Trackside equipment, Route: JH3 8x20, 1x35, JH4 1x45mm		10			
39663	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Ducts	Asbestos	Strongly Presumed	1335		LHS	bitumen, cable duct lining		5			
36900	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	1360		RHS	Woven cable sheath. Entry: Trackside Equipment, Route: JH3 6x20, 2x35, 1x35, JH4 1x45mm		10			
36901	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	1375			Spliced cable		2			
40400	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	1398			Woven cable sheath. Route: Gaining 1x20mm JH3		11			
36902	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	1403			Woven cable sheath. Route: Gaining 1x20mm JH3		12			
36903	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	1475			Woven cable sheath. Route: Gaining 1x20mm JH3		13			
36904	ACTIVE	P	P078-P-EBLO	Road EBLO - PIC - Barons Court to Earls Court (Invalid code. Use P078-P-EBFA)	Cable Sheath	Asbestos	Known	1479			Woven cable sheath. Route: Gaining 1x20mm JH3		14			
37530	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Sheath	Asbestos	Known	0		RHS	Cloth. cable sheathing, Route: JH3 6x15mm, 1x25mm, JH4 1x45mm, 1x15mm		9			
41784	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Sheath	Asbestos	Known	0		RHS	BRS 0 RHS - 7 x Braded cables with J hanger		7			
41795	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed		73	RHS	1 x small westinghouse box		1			
41785	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Signal Boxes	Asbestos	Presumed	5		RHS	BRS 5 RHS - 1 x Signal A658 to wall		1			
37531	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Sheath	Asbestos	Known	5	8	RHS	Cloth. cable sheathing, Route: Between JH3-JH4 & Trackside Equipment 5-45mm, Exit: Trackside Equipment. Numerous amounts					



Hazardous Material Asset Register - Summary



P078-P - PIC Line - Earls Court to Barons Court

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41787	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	6		RHS	BRS 6 RHS - 1 x Large Westinhouse Box to wall		1			
41786	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Other Electrical Boxes	Asbestos	Presumed				BRS 6 RHS - 1 x 10 core to wall		10		N	N
41789	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Other Electrical Boxes	Asbestos	Presumed				1 x 10 Core		1		N	N
41788	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Signal Boxes	Asbestos	Presumed	7		RHS	BRS 7 RHS - 1 x EP Valve to wall		1			
37532	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Sheath	Asbestos	Known	8		RHS	Cloth. cable sheathing, Route: JH3 6x15mm, JH 1x45mm		7			
41790	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Isolator Switches	Asbestos	Presumed				1 x Rail Gap Indicator		1		N	N
37533	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Sheath	Asbestos	Known	14			Cloth. cable sheathing, Route: Of JH3 on RHS, Exit: Rail gap Indicator OTX/LHS		1			
41792	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	16		LHS	1 x Small westinghouse box to wall		1			
41791	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	16		LHS	1 x Small westinghouse box to wall		1			
37534	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Sheath	Asbestos	Known	16			Cloth. cable sheathing, Route: Losing JH3, Exit: Westinghouse small box small OTX/LHS		6			
37535	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Sheath	Asbestos	Known	22			Cloth. cable sheathing, Route: Losing 15x1mm JH3, Exit: Westinghouse small box small OTX/LHS		5			
41793	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	71		RHS	1 x Small westinghouse box to wall		1			



Hazardous Material Asset Register - Summary



P078-P - PIC Line - Earls Court to Barons Court

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41798	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Other Electrical Boxes	Asbestos	Presumed				1 x 10 core to wall		1		N	N
41794	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	71		RHS	1 x small westinghouse box		1			
37536	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Sheath	Asbestos	Known	73			Cloth. cable sheathing, Route: Losing 1x15mm JH3, Exit: Westinghouse small box small OTX/LHS		4			
39816	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Sheath	Asbestos	Known	74			Cloth. cable sheathing, Entry: Westinghouse small box small, Route: Gain 1x15mm JH3 OTX/LHS		5			
41797	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	77		RHS	1 x Large westinghouse box to wall		1			
37538	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Sheath	Asbestos	Known	78			Cloth. cable sheathing, Route: JH3 6x15mm, JH 1x45mm OTX/LHS		7			
37537	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Sheath	Asbestos	Known	78			Cloth. cable sheathing, Entry: Trackside Equipment, Exit:Trackside Equipment. Numerous amounts OTX/LHS					
37539	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Ducts	Asbestos	Strongly Presumed	157	160		Bitumen. cable duct lining		16			
41799	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Wrap	Asbestos	Known	157		RHS	1m Cable wrapping to metal bar on metal run	1				
41801	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Ducts: Cement	Asbestos	Known				6 x Cement Cable Ducts HV Cable to sides of cross passage		6		N	N
41802	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Ducts: Bitumen	Asbestos	Known				10 x Bitumen Cable Ducts HV Cable above cross passage		10		N	N
41804	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Other Electrical Boxes	Asbestos	Presumed				1 x Rail Gap Indicator to wall		1		N	N



Hazardous Material Asset Register - Summary



P078-P - PIC Line - Earls Court to Barons Court

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37540	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Sheath	Asbestos	Known	162			Cloth. cable sheathing, Route: 2x15mm of JH3, Exit: Rail Gap Indicator OTX/LHS		2			
41808	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	170		RHS	Large westinghouse box		1			
41809	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Other Electrical Boxes	Asbestos	Presumed				1 x Junction volt box		1		N	N
37541	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Sheath	Asbestos	Known	175		RHS	Cloth. cable sheathing, Entry: Trackside Equipment, Route: Between JH3-JH4 & Trackside Equipment 5-45mm. Numerous amounts					
37542	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Sheath	Asbestos	Known	176		RHS	Cloth. cable sheathing, Entry: Trackside Equipment, Route: Between JH3-JH4 & Trackside Equipment 5-45mm, Exit: Trackside Equipment. Numerous amounts					
37543	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Sheath	Asbestos	Known	177		RHS	Cloth. cable sheathing, Route: JH3 6x15mm, JH4 1x45mm		7			
41810	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Signal Boxes	Asbestos	Presumed	216		LHS	1 x Signal - R656		1			
41817	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westing house Boxes	Asbestos	Presumed				Large Westinghouse Box		1		N	N
41811	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Other Electrical Boxes	Asbestos	Presumed				1 x 10 core		1		N	N
41812	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	218		RHS	1 x Large Westinghouse Box		1			
37544	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Sheath	Asbestos	Known	221	234	RHS	Cloth. cable sheathing, Entry: Trackside Equipment, Route: Between JH3-JH4 & Trackside Equipment 5-45mm, Exit: Trackside Equipment. numerous amounts					
41813	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	225		RHS	1 x Small Westinghouse Box		1			



Hazardous Material Asset Register - Summary



P078-P - PIC Line - Earls Court to Barons Court

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41814	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	231			1 x Small Westinghouse Box		1			
37545	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Sheath	Asbestos	Known	234		RHS	Cloth. cable sheathing, Route: JH3 6x15mm, JH4 1x45mm		4			
41816	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Other Electrical Boxes	Asbestos	Presumed				1 x 10 core		1		N	N
41815	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Signal Boxes	Asbestos	Presumed	304		LHS	1 x Signal A656		1			
41818	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Signal Boxes	Asbestos	Presumed	306		RHS	1 x EP valve		1			
41819	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Other Electrical Boxes	Asbestos	Presumed				1 x 10 core		1		N	N
41820	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	307		RHS	1 x Small Westinghouse Box		1			
41821	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westing house Boxes	Asbestos	Presumed				1 x Large Westinghouse Box		1		N	N
41822	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	309		RHS	1 x Westinghouse - Black Signal Box		1			
41823	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westing house Boxes	Asbestos	Presumed				Large Westinghouse Box and Link Box		2		N	N
37546	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Sheath	Asbestos	Known	310	323	RHS	Cloth. cable sheathing, Route: Between JH3-JH4 & Trackside Equipment 5-45mm. Numerous amounts					
41824	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westing house Boxes	Asbestos	Presumed				1 x Small Westinghouse Box		1		N	N



Hazardous Material Asset Register - Summary



P078-P - PIC Line - Earls Court to Barons Court

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41825	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westing house Boxes	Asbestos	Presumed				1 x Small Westinghouse Box		1		N	N
37547	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Sheath	Asbestos	Known	323		RHS	Cloth. cable sheathing, Route: JH3 2x15mm, JH4 1x45mm		4			
37548	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Sheath	Asbestos	Known	362		RHS	Cable splice. Route: 1x45mm JH4		2			
41826	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Signal Boxes	Asbestos	Presumed	368		RHS	Type 79 box		1			
41827	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westing house Boxes	Asbestos	Presumed				Large - Westinghouse Box		1		N	N
37550	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Sheath	Asbestos	Known	382		RHS	Cloth. cable sheathing, Route: 4x15mm Between Signals Box, OTX, Exit: Signal Box					
37549	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Sheath	Asbestos	Known	382			Cloth. cable sheathing, Route: 1x15mm, Exit: Westinghouse small box small LHS/OTX		1			
41829	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Signal Boxes	Asbestos	Presumed	451		LHS	1 x Signal - A6561		1			
41828	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Signal Boxes	Asbestos	Presumed	455		LHS	1 x Signal - R654		1			
41830	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Other Electrical Boxes	Asbestos	Presumed				1 x 10 core		1		N	N
41831	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	457		RHS	1 x Large Westinghouse Box		1			
41832	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Signal Boxes	Asbestos	Presumed	458		RHS	1 x EP valve		1			



Hazardous Material Asset Register - Summary



P078-P - PIC Line - Earls Court to Barons Court

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41833	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Other Electrical Boxes	Asbestos	Presumed				1 x 10 core		1		N	N
41834	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westing house Boxes	Asbestos	Presumed				Large Westinghouse Box		1		N	N
41835	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westing house Boxes	Asbestos	Presumed				1 x Large Westinghouse Box		1		N	N
41836	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	460		RHS	1 x Break signal - Westinghouse Box		1			
41837	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	461		RHS	1 x Large Westinghouse and Link Box		1			
37551	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Sheath	Asbestos	Known	462	466	RHS	Cloth. cable sheathing, numerous amounts					
41838	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westing house Boxes	Asbestos	Presumed				1 x Small Westinghouse Box		1		N	N
41839	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	505		RHS	1 x Small Westinghouse Box		1			
41840	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Signal Boxes	Asbestos	Presumed	617		RHS	1 x Signal - A654		1			
41842	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	618		RHS	1 x Large westinghouse box		1			
41841	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Other Electrical Boxes	Asbestos	Presumed				1 x 10 core		1		N	N
41843	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Other Electrical Boxes	Asbestos	Presumed				1 x EP valve		1		N	N



Hazardous Material Asset Register - Summary



P078-P - PIC Line - Earls Court to Barons Court

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41844	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Other Electrical Boxes	Asbestos	Presumed				1 x 10 core		1		N	N
41845	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westing house Boxes	Asbestos	Presumed				1 x Large westinghouse box		1		N	N
41846	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Other Electrical Boxes	Asbestos	Presumed				1 x 10 core		1		N	N
41847	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	626		RHS	1 x Small Westinghouse Box		1			
41848	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	631		RHS	1 x Small Westinghouse Box		1			
41849	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	674		RHS	1 x Lamp - Small Westinghouse Box		1			
41850	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Signal Boxes	Asbestos	Presumed	791		RHS	Type 79 box		1			
41851	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Signal Boxes	Asbestos	Presumed	798		RHS	1 x Signal A654		1			
41852	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Other Electrical Boxes	Asbestos	Presumed				1 x 10 core		1		N	N
41853	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Signal Boxes	Asbestos	Presumed	800		RHS	1 x EP valve		1			
41854	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Other Electrical Boxes	Asbestos	Presumed				1x 10 core		1		N	N
41855	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	802		RHS	1 x Large Westinghouse Box		1			



Hazardous Material Asset Register - Summary



P078-P - PIC Line - Earls Court to Barons Court

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41856	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westing house Boxes	Asbestos	Presumed				1 x Large westinghouse box		1		N	N
41858	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	804		RHS	1 x Break Signal Westinghouse Box		1			
41857	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westing house Boxes	Asbestos	Presumed				1 x Small Westinghouse Box		1		N	N
41859	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	805		RHS	1 x Large Westinghouse Box and Link Box		1			
41860	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	809		RHS	1 x Small Westinghouse Box		1			
41861	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	816		RHS	Small westinghouse box		1			
41862	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	985		RHS	1 x Lamp - Small Westinghouse Box		1			
41863	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Signal Boxes	Asbestos	Presumed	991		RHS	1 x Signal A652		1			
41864	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	992		RHS	1 x Large Westinghouse Box		1			
41866	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Signal Boxes	Asbestos	Presumed	994		RHS	1 x EP valve		1			
41865	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Other Electrical Boxes	Asbestos	Presumed				1 x 10 core		1		N	N
41867	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	1008		RHS	1 x Small Westinghouse Box		1			



Hazardous Material Asset Register - Summary



P078-P - PIC Line - Earls Court to Barons Court

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41868	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	1013		RHS	1 x Large Westinghouse Box		1			
41869	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	1014		RHS	1 x Large Westinghouse Box		1			
41870	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	1016		RHS	1 x Large Westinghouse Box		1			
41871	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	1017		RHS	2 x Large Westinghouse Box and Link Box		1			
41872	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	1018		RHS	1 x Large Westinghouse Box		1			
41873	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	1020		RHS	1 x Small Westinghouse Box		1			
41874	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	1025		RHS	1 x Small Westinghouse Box		1			
41875	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Signal Boxes	Asbestos	Presumed	1083		RHS	1 x Signal - R650		1			
41876	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	1084		RHS	1 x Large Westinghouse Box		1			
41877	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Signal Boxes	Asbestos	Presumed	1087		RHS	1 x Type 74 Box		1			
41878	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Other Electrical Boxes	Asbestos	Presumed				1 x 10 core		1		N	N
41879	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Sheath	Asbestos	Known	1090		LHS	Braided cable throughout - from RHS to LHS over track crossing to J hanger					



Hazardous Material Asset Register - Summary



P078-P - PIC Line - Earls Court to Barons Court

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41880	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Signal Boxes	Asbestos	Presumed	1248		LHS	1 x Fog repeater - A6501 to cable run		1			
41881	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Cable Sheath	Asbestos	Known	1252		LHS	Braided cable throughout - disused to over track crossing District Line					
41882	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Signal Boxes	Asbestos	Presumed	1330		LHS	1 x Signal - A650 - Over track crossing structure D87		1			
41883	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Signal Boxes	Asbestos	Presumed	1330		LHS	1 x Fog repeater - WPX652 - Over track crossing structure D87		1			
41886	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Signal Boxes	Asbestos	Presumed	1442		LHS	1 x EP Valve - Over track crossing structure D87		1			
41884	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Signal Boxes	Asbestos	Presumed	1448		LHS	1 x Signal - WPX650X - Over track crossing structure D87		1			
41885	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Other Electrical Boxes	Asbestos	Presumed				1 x 10 Core - Over track crossing structure D87		1		N	N
41887	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	1470		LHS	1 x Small Westinghouse Box		1			
41888	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	1480		LHS	1 x Lamp - Small Westinghouse Box		1			
41889	ACTIVE	P	P078-P-WBLO	Road WBLO - PIC - Earls Court to Barons Court (Boundary) (Invalid code. Use P078-P-WBFA)	Westinghouse Boxes	Asbestos	Presumed	1484		LHS	2 x Small Westinghouse Boxes		2			

P082-P - PIC Line - Ealing Common to North Ealing

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38759	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Presumed	3	6	LHS	Flash guards Switch box 2GR, 545BTR, 545ATH, 545AT, 2GRCR		6			



Hazardous Material Asset Register - Summary



P082-P - PIC Line - Ealing Common to North Ealing

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38761	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Presumed	7		LHS	Flash guards Signal break box		1			
38760	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Presumed	7		LHS	Flash guards Signal WM2		1			
38762	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Presumed	12		LHS	Flash guards Signal break box		1			
38763	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Presumed	17		LHS	Flash guards Signal break box		1			
38764	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Ducts	Asbestos	Sampled – Not Detected	28		LHS	Bitumen ducts					
38765	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Presumed	32		LHS	Flash guards Switch box		1			
38766	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Cement Cable Troughing & Debris	Asbestos	Removed	33		LHS	Cement cable troughing, Cable troughing to post REMOVED BY ECON CONSTRUCTION ON 20/01/2020		2			
38767	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Presumed	46		LHS	Flash guards Signal break box					
38768	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Presumed	200		LHS	Flash guards Signal break box					
40019	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Presumed	200		LHS	Flash guards Marshalling kiosk		1			
38769	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Presumed	225		LHS	Flash guards Signal break box		1			
38770	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Presumed	227		LHS	Flash guards Signal break box		1			
39891	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Presumed	229		LHS	Flash guards Signal break box		1			
38771	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Presumed	236		LHS	Flash guards Signal break box		1			
38772	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Presumed	238	240	LHS	Flash guards Switch boxes AATR, AATH, AAT		5			
40020	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Presumed	300		LHS	Flash guards Fog repeater RWM3		1			
38773	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Presumed	305		LHS	Flash guards Switch boxes BTR, 3PGR		2			
38774	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Presumed	327		LHS	Flash guards Marshalling kiosk		1			
38775	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Presumed	371	374	LHS	Flash guards Switch boxes BBTR, BBTH, BBT, 3GR, 4004AGR		6			



Hazardous Material Asset Register - Summary



P082-P - PIC Line - Ealing Common to North Ealing

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38776	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Presumed	377		LHS	Flash guards Signal WM3, RWM400		2			
38777	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Presumed	507	510	LHS	Flash guards Switch boxes 400GR, GTR, WM4AFPGR		5			
40021	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Presumed	513		LHS	Flash guards Fog repeater FRWM4 A, Signal WM400		2			
38778	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Presumed	582	584	LHS	Flash guards Switch boxes DTH, CT, 4GR, 4PGR		5			
38779	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Presumed	589		LHS	Flash guards Fog repeater FRWM4 B, Signal WM4		2			
38780	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Presumed	753		LHS	Flash guards Switch boxes ETH, ET, 5PGR, 4GR		5			
38781	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Sampled – Not Detected	753		LHS	bitumen ducts					
39681	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Presumed	759		LHS	Flash guards Signal WM4 B, RWM5		2			
38782	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Presumed	995		LHS	Flash guards Signal break box		1			
38783	ACTIVE	P	P082-P-EBMA	Road EBMA - PIC - North Ealing to Hanger Lane Junction	Signal Boxes	Asbestos	Presumed	996		LHS	Flash guards Signal break box		1			
40097	ACTIVE	P	P082-P-WBMA	Road WBMA - PIC - Hanger Lane Junction to North Ealing	Signal Boxes	Asbestos	Presumed	2		LHS	Flash guards Signal break box		1			
40099	ACTIVE	P	P082-P-WBMA	Road WBMA - PIC - Hanger Lane Junction to North Ealing	Ducts	Asbestos	Sampled – Not Detected	6		LHS	Bitumen Ducts					
40098	ACTIVE	P	P082-P-WBMA	Road WBMA - PIC - Hanger Lane Junction to North Ealing	Cement Cable Troughing & Debris	Asbestos	Known	6		LHS	Cement troughing		1			
40100	ACTIVE	P	P082-P-WBMA	Road WBMA - PIC - Hanger Lane Junction to North Ealing	Signal Boxes	Asbestos	Presumed	9		LHS	Flash guards Signal break box		1			
40101	ACTIVE	P	P082-P-WBMA	Road WBMA - PIC - Hanger Lane Junction to North Ealing	Signal Boxes	Asbestos	Presumed	20		LHS	Flash guards Signal WM22		1			
40102	ACTIVE	P	P082-P-WBMA	Road WBMA - PIC - Hanger Lane Junction to North Ealing	Signal Boxes	Asbestos	Presumed	21		LHS	Flash guards Signal break box		1			
40103	ACTIVE	P	P082-P-WBMA	Road WBMA - PIC - Hanger Lane Junction to North Ealing	Signal Boxes	Asbestos	Removed	25		LHS	Flash guards Signal break box Notes from 2022 re-inspection: Removed		1			
40104	ACTIVE	P	P082-P-WBMA	Road WBMA - PIC - Hanger Lane Junction to North Ealing	Signal Boxes	Asbestos	Presumed	47	52	LHS	Flash guards Switch boxes		5			
40105	ACTIVE	P	P082-P-WBMA	Road WBMA - PIC - Hanger Lane Junction to North Ealing	Signal Boxes	Asbestos	Presumed	110		LHS	Flash guards Junction box		1			



Hazardous Material Asset Register - Summary



P082-P - PIC Line - Ealing Common to North Ealing

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40106	ACTIVE	p	P082-P-WBMA	Road WBMA - PIC - Hanger Lane Junction to North Ealing	Signal Boxes	Asbestos	Presumed	353	356	LHS	Flash guards Switch boxes RTR, RRTR, OT, RTH, 20PGR		7			
40107	ACTIVE	p	P082-P-WBMA	Road WBMA - PIC - Hanger Lane Junction to North Ealing	Signal Boxes	Asbestos	Presumed	360		LHS	Flash guards Signal RWM20/21		1			
39943	ACTIVE	p	P082-P-WBMA	Road WBMA - PIC - Hanger Lane Junction to North Ealing	Signal Boxes	Asbestos	Presumed	363		LHS	Flash guards Signal break box		1			
40108	ACTIVE	p	P082-P-WBMA	Road WBMA - PIC - Hanger Lane Junction to North Ealing	Signal Boxes	Asbestos	Presumed	364		LHS	Flash guards Signal break box		1			
40109	ACTIVE	p	P082-P-WBMA	Road WBMA - PIC - Hanger Lane Junction to North Ealing	Signal Boxes	Asbestos	Presumed	412		LHS	Flash guards Fog repeater RWM20/21		1			
40110	ACTIVE	p	P082-P-WBMA	Road WBMA - PIC - Hanger Lane Junction to North Ealing	Signal Boxes	Asbestos	Presumed	422		LHS	Flash guards Marshalling kiosk		1			
40111	ACTIVE	p	P082-P-WBMA	Road WBMA - PIC - Hanger Lane Junction to North Ealing	Signal Boxes	Asbestos	Presumed	479		LHS	Flash guards Signal WM20/21		1			
39386	ACTIVE	p	P082-P-WBMA	Road WBMA - PIC - Hanger Lane Junction to North Ealing	Signal Boxes	Asbestos	Presumed	641		LHS	Flash guards Switch boxes UTR Notes from 2022 re-inspection: 2xLWH not 1x LWH		2			
40112	ACTIVE	p	P082-P-WBMA	Road WBMA - PIC - Hanger Lane Junction to North Ealing	Signal Boxes	Asbestos	Presumed	644		LHS	Flash guards Signal R550(1)		1			
46156	INACTIVE	p	P082-P-WBMA	Road WBMA - PIC - Hanger Lane Junction to North Ealing	Signal Boxes	Asbestos	Presumed	644		LHS	Flash guards Signal R550(1)		1			
40113	ACTIVE	p	P082-P-WBMA	Road WBMA - PIC - Hanger Lane Junction to North Ealing	Signal Boxes	Asbestos	Presumed	646		LHS	Flash guards Marshalling kiosk		1			
40114	ACTIVE	p	P082-P-WBMA	Road WBMA - PIC - Hanger Lane Junction to North Ealing	Signal Boxes	Asbestos	Presumed	684		LHS	Flash guards Fog repeater A550		1			
40115	ACTIVE	p	P082-P-WBMA	Road WBMA - PIC - Hanger Lane Junction to North Ealing	Signal Boxes	Asbestos	Presumed	704		LHS	Flash guards Switch box UUTR, 550PGR		2			
40116	ACTIVE	p	P082-P-WBMA	Road WBMA - PIC - Hanger Lane Junction to North Ealing	Signal Boxes	Asbestos	Presumed	712		LHS	Flash guards Signal R550		1			
39387	ACTIVE	p	P082-P-WBMA	Road WBMA - PIC - Hanger Lane Junction to North Ealing	Signal Boxes	Asbestos	Presumed	788		LHS	Flash guards Switch boxes VTR, UTH, UT, 248PGR, 55UGR		6			
39466	ACTIVE	p	P082-P-WBMA	Road WBMA - PIC - Hanger Lane Junction to North Ealing	Signal Boxes	Asbestos	Presumed	803		LHS	Flash guards Signal A550, R548		2			
40117	ACTIVE	p	P082-P-WBMA	Road WBMA - PIC - Hanger Lane Junction to North Ealing	Signal Boxes	Asbestos	Presumed	817		LHS	Flash guards Signal break box		1			
40118	ACTIVE	p	P082-P-WBMA	Road WBMA - PIC - Hanger Lane Junction to North Ealing	Signal Boxes	Asbestos	Presumed	821		LHS	Flash guards Signal break box		1			



Hazardous Material Asset Register - Summary



P084-P - PIC Line - North Ealing to Park Royal

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38945	ACTIVE	p	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	1		LHS	Flash guards Signal A541		1			
38946	ACTIVE	p	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	6		LHS	Flash guards Marshalling kiosk 541		1			
38947	ACTIVE	p	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	9		LHS	Flash guards Marshalling kiosk 541		1			
38948	ACTIVE	p	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	9		LHS	Flash guard Signal break box		1			
38949	ACTIVE	p	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	14		LHS	Flash guard Signal break box		1			
38950	ACTIVE	p	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	16		LHS	Flash guards Signal box 540PGR & 542ATR		2			
38951	ACTIVE	p	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	18		LHS	Flash guard Signal break box		1			
38952	ACTIVE	p	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	23		LHS	Flash guard Signal break box		1			
39686	ACTIVE	p	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Removed	26		LHS	Flash guard Signal break box Notes from 2022 re-inspection: Removed		1			
38953	ACTIVE	p	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	135		LHS	Flash guard Signal break box		1			
38954	ACTIVE	p	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	140		LHS	Flash guard Signal break box		1			
38955	ACTIVE	p	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	141		LHS	Flash guard Signal break box		1			
38956	ACTIVE	p	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	148		LHS	Flash guards Box RA4/81/09		1			
38957	ACTIVE	p	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	160		LHS	Flash guards Marshalling kiosk		1			
40059	ACTIVE	p	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	206		LHS	Flash guard Signal break box		1			
38958	ACTIVE	p	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	208		LHS	Flash guard Signal break box		1			
38959	ACTIVE	p	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	268		LHS	Flash guards Signal R545		1			
38960	ACTIVE	p	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	270		LHS	Flash guard Signal break box		1			
38961	ACTIVE	p	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	276		LHS	Flash guard Signal break box		1			



Hazardous Material Asset Register - Summary



P084-P - PIC Line - North Ealing to Park Royal

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38962	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	280		LHS	Flash guards Marshalling kiosk		1			
40060	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	282		LHS	Flash guards Fog repeater		1			
38963	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	286		LHS	Flash guard Breaker box		1			
38964	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	288		LHS	Flash guards Switch box 542BPGR & 548DTR		2			
39901	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	295		LHS	Flash guard Signal break box		1			
38965	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	296		LHS	Flash guard Signal break box		1			
40061	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	297		LHS	Flash guard Signal break box		1			
38966	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	300		LHS	Flash guards Marshalling kiosk		1			
38967	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	315		LHS	Flash guards Breaker box		1			
38968	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	403		LHS	Flash guards Marshalling kiosk		1			
38969	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	406		LHS	Flash guards Signal A545A & RWMK545B		1			
39160	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	425		LHS	Flash guard Signal break box		1			
39161	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	429		LHS	Flash guard Signal break box		1			
39162	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	446		LHS	Flash guards Fog repeater WMX545B		1			
39163	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	447		LHS	Flash guard Signal break box		1			
39164	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	452		LHS	Flash guard Signal break box		1			
39165	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	458		LHS	Flash guards Marshalling kiosk 542a		1			
39166	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	496		LHS	Flash guard Signal break box		1			
39167	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	500		LHS	Flash guards Marshalling kiosk		1			



Hazardous Material Asset Register - Summary



P084-P - PIC Line - North Ealing to Park Royal

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39168	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	526		LHS	Flash guards Switch box 541aTR		1			
39169	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	527		LHS	Flash guard Signal break box		1			
39170	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	532		LHS	Flash guard Signal break box		1			
39171	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	564		LHS	Flash guards Box RA4/81/10		1			
39172	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	571	575	LHS	Flash guards Switch box x 8 & signal R545C(1) Notes from 2022 re-inspection: 6x LWH 1x Signal		7			
39173	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	581		LHS	Flash guard Signal break box					
39935	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	582		LHS	Flash guard Signal break box					
39174	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	585		LHS	Flash guards Marshalling kiosk FR542					
39175	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Ducts	Asbestos	Sampled – Not Detected	587		LHS	Bitumen, Bitumen ducts, elephant trunking					
39176	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	591		LHS	Flash guard Signal break box		1			
39177	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	593		LHS	Flash guard Signal break box		1			
39461	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	627		LHS	Flash guards Breaker box		1			
39178	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	735		LHS	Flash guard Signal break box		1			
39349	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	741		LHS	Flash guards Signal		1			
39179	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	747	748	LHS	Flash guards Switch box and Fog repeater A545C Notes from 2022 re-inspection: 2 boxes and fog repeater		2			
39180	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	782		LHS	Flash guard Signal break box		1			
39181	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	787		LHS	Flash guard Signal break box		1			
39182	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	788		LHS	Flash guard Signal break box		1			



Hazardous Material Asset Register - Summary



P084-P - PIC Line - North Ealing to Park Royal

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39350	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	793		LHS	Flash guard Signal break box		1			
39183	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	796		LHS	Flash guards Marshalling kiosk		1			
39184	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	818		LHS	Flash guard Signal break box		1			
39185	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	819		LHS	Flash guard Signal break box		1			
39716	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	857	864	LHS	Flash guards Switch box Notes from 2022 re-inspection: 7x LWH		7			
39186	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	869		LHS	Flash guard Signal break box		1			
39351	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	869		LHS	Flash guards Signal A545C		1			
39187	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	878		LHS	Flash guard Signal break box		1			
39188	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	883		LHS	Flash guard Signal break box		1			
39189	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Westinghouse Boxes	Asbestos	Presumed	926		LHS	Flash guards Switch box Notes from 2022 re-inspection: 1x LWH		1			
39190	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Cement Cable Troughing & Debris	Asbestos	Known	926			Cement cable troughing. Under track crossing , est 3(l)m					
39191	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	952		LHS	Flash guard Signal break box		1			
39192	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	954		LHS	Flash guards Marshalling kiosk 548		1			
39193	ACTIVE	P	P084-P-EBMA	Road EBMA - PIC - Park Royal to North Ealing	Signal Boxes	Asbestos	Presumed	955		LHS	Flash guards Breaker box		1			
38784	ACTIVE	P	P084-P-WBMA	Road WBMA - PIC - North Ealing to Park Royal	Signal Boxes	Asbestos	Presumed	1		LHS	Flash guards Signal A548		1			
38785	ACTIVE	P	P084-P-WBMA	Road WBMA - PIC - North Ealing to Park Royal	Signal Boxes	Asbestos	Presumed	1		LHS	Flash guards Rail Gap Indicator		1			
38786	ACTIVE	P	P084-P-WBMA	Road WBMA - PIC - North Ealing to Park Royal	Signal Boxes	Asbestos	Presumed	12		LHS	Flash guards Switch box		1			
38787	ACTIVE	P	P084-P-WBMA	Road WBMA - PIC - North Ealing to Park Royal	Signal Boxes	Asbestos	Presumed	39	43	LHS	Flash guards Signal break boxes		6			
38788	ACTIVE	P	P084-P-WBMA	Road WBMA - PIC - North Ealing to Park Royal	Cement Cable Troughing & Debris	Asbestos	Known	42	43	LHS	Asbestos cement. Cement troughing		1			



Hazardous Material Asset Register - Summary



P084-P - PIC Line - North Ealing to Park Royal

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38789	ACTIVE	p	P084-P-WBMA	Road WBMA - PIC - North Ealing to Park Royal	Signal Boxes	Asbestos	Presumed	322		LHS	Flash guards Signal R542 A		1			
38790	ACTIVE	p	P084-P-WBMA	Road WBMA - PIC - North Ealing to Park Royal	Ducts	Asbestos	Sampled – Not Detected	324		LHS	Bitumen ducts, elephant trunking					
38791	ACTIVE	p	P084-P-WBMA	Road WBMA - PIC - North Ealing to Park Royal	Ducts	Asbestos	Sampled – Not Detected	327		LHS	Bitumen ducts, elephant trunking					
38792	ACTIVE	p	P084-P-WBMA	Road WBMA - PIC - North Ealing to Park Royal	Ducts	Asbestos	Sampled – Not Detected	348		LHS	Bitumen ducts, elephant trunking					
38793	ACTIVE	p	P084-P-WBMA	Road WBMA - PIC - North Ealing to Park Royal	Ducts	Asbestos	Sampled – Not Detected	351		LHS	Bitumen ducts, elephant trunking					
38794	ACTIVE	p	P084-P-WBMA	Road WBMA - PIC - North Ealing to Park Royal	Signal Boxes	Asbestos	Presumed	362		LHS	Flash guards Fog repeater A542A		1			
38795	ACTIVE	p	P084-P-WBMA	Road WBMA - PIC - North Ealing to Park Royal	Signal Boxes	Asbestos	Presumed	484		LHS	Flash guards Signal A542A		1			
40022	ACTIVE	p	P084-P-WBMA	Road WBMA - PIC - North Ealing to Park Royal	Signal Boxes	Asbestos	Presumed	620		LHS	Flash guards Signal R542 B		1			
38796	ACTIVE	p	P084-P-WBMA	Road WBMA - PIC - North Ealing to Park Royal	Signal Boxes	Asbestos	Presumed	630		LHS	Flash guards Fog repeater A542B		1			
39892	ACTIVE	p	P084-P-WBMA	Road WBMA - PIC - North Ealing to Park Royal	Signal Boxes	Asbestos	Presumed	774		LHS	Flash guards Signal A542B		1			
38797	ACTIVE	p	P084-P-WBMA	Road WBMA - PIC - North Ealing to Park Royal	Signal Boxes	Asbestos	Presumed	923		LHS	Flash guards Signal R450		1			
38798	ACTIVE	p	P084-P-WBMA	Road WBMA - PIC - North Ealing to Park Royal	Cement Cable Troughing & Debris	Asbestos	Known	938		LHS	Cement debris. Adj end of platform ramp, Small amounts					
40023	ACTIVE	p	P084-P-WBMA	Road WBMA - PIC - North Ealing to Park Royal	Cement Cable Troughing & Debris	Asbestos	Known	938			asbestos cement. Extensive sheet Cement debris below elderberry bush. Unable to qualify Notes from 2022 re-inspection: Heavy veg present					

P086-P - PIC Line - Park Royal to Alperton

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36322	ACTIVE	p	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Cable Sheath	Asbestos	Known	2		LHS	Cement troughing. Cable troughing to wall and down to track		1			
36323	ACTIVE	p	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	3		LHS	Flash guards Signal break boxes		1			
36324	ACTIVE	p	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	3	6	LHS	Flash guards Switch boxes A529, 527 BTR, 527ATH, 527AT, 529GR		6			



Hazardous Material Asset Register - Summary



P086-P - PIC Line - Park Royal to Alperton

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40206	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Cement Cable Troughing & Debris	Asbestos	Presumed	5	7	LHS	Cement troughing. Cable troughing within ballast running parallel to ramp. Small amounts					
36325	INACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Removed	7		LHS	Flash guards Signal break boxes		1			
36326	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	8		LHS	Flash guards Signal break boxes		1			
36327	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	9		LHS	Flash guards Signal break boxes		1			
36328	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	9		LHS	Flash guards Rail Gap Indicator		1			
39511	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	40	42	LHS	Flash guards Switch boxes		5			
36329	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Ducts	Asbestos	Sampled – Not Detected	59		LHS	Bitumen ducts					
40207	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	91		LHS	Flash guards Signal break boxes		1			
36330	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	94		LHS	Flash guards Signal break boxes		1			
36331	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	108		LHS	Flash guards Switch boxes 530 BGR, 536FTR		5			
36332	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Ducts	Asbestos	Sampled – Not Detected	202		LHS	Bitumen ducts					
36439	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	208		LHS	Flash guards Signal break boxes		1			
36440	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	210		LHS	Flash guards Signal break boxes		1			
36441	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	214		LHS	Flash guards Signal break boxes		1			
36443	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	304		LHS	Flash guards Switch box 527CTR		1			
36442	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	304		LHS	Flash guards Signal break boxes		1			
36444	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	308		LHS	Flash guards Signal break boxes		1			
36445	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	309		LHS	Flash guards Signal break boxes		1			
36446	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	317	321	LHS	Flash guards Switch boxes 536 FTR, 536DTR, 530BPR, 536DTH, 536DT, 530BPGR		7			



Hazardous Material Asset Register - Summary



P086-P - PIC Line - Park Royal to Alperton

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36447	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	444		LHS	Flash guards Signal break boxes		1			
36448	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	487		LHS	Flash guards Signal break boxes		1			
36449	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	516	518	LHS	Flash guards Switch boxes 536 BTH, 536BT, 530AGR, 536CTR		5			
39620	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	525	527	LHS	Flash guards Switch boxes 529 ATH, 529AT, 529ATR		4			
36450	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	530		LHS	Flash guards Signal break boxes		1			
36451	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	534	537	LHS	Flash guards Switch boxes 536 BTR, 536ATH, 536AT, 536ATR, 530APGR		6			
39373	INACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Removed	551		LHS	Flash guards Signal break boxes		1			
36453	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	560		LHS	Flash guards Signal break boxes		1			
36452	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	561		LHS	Flash guards Signal break boxes		1			
36454	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	612		LHS	Flash guards Signal break boxes		1			
36455	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	613		LHS	Flash guards Signal break boxes		1			
40218	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	728	729	LHS	Flash guards Switch boxes 529 BTR, 535PGR		2			
36456	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	733		LHS	Flash guards Fog repeater A535		1			
36457	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	747		LHS	Flash guards Signal break boxes		1			
36458	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	748		LHS	Flash guards Signal break boxes		1			
36459	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	826	829	LHS	Flash guards Switch boxes 529BTH, 529BT, 529CTR, 535GR		5			
36460	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	832		LHS	Flash guards Signal A535		1			
40289	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	846		LHS	Flash guards Signal break box		1			
36461	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	848		LHS	Flash guards Signal break box		1			



Hazardous Material Asset Register - Summary



P086-P - PIC Line - Park Royal to Alperton

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39515	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1120		LHS	Flash guards Signal break box		1			
36462	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1121		LHS	Flash guards Signal break box		1			
36463	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1139		LHS	Flash guards Switch boxes 540 BTH, 540BT, 540CTR, 536GR		5			
40290	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1143	1145	LHS	Flash guards Switch boxes 529 CTH, 529CT, 529DTR, 539APGR		5			
36464	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1190		LHS	Flash guards Signal R539 A		1			
36465	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1191		LHS	Flash guards Signal break box		1			
36466	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1192		LHS	Flash guards Signal break box		1			
36467	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1194		LHS	Flash guards Signal break box		1			
36468	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1198		LHS	Flash guards Signal break box		1			
36469	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1244	1245	LHS	Flash guards Switch boxes 535 ATR, 539APGR		2			
36470	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1246		LHS	Flash guards Fog repeater A539A		1			
36471	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1247		LHS	Flash guards Signal break box		1			
36472	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1248		LHS	Flash guards Signal break box		1			
36473	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1249		LHS	Flash guards Signal break box		1			
36474	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1251		LHS	Flash guards Signal break box		1			
36475	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1255		LHS	Flash guards Signal break box		1			
36476	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1319		LHS	Flash guards Signal break box		1			
36477	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1320		LHS	Flash guards Signal break box		1			
36478	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1351	1355	LHS	Flash guards Switch boxes 536PGR, 540A, 540AT, 536PGR1, 540 BTR, 540ATR		7			



Hazardous Material Asset Register - Summary



P086-P - PIC Line - Park Royal to Alperton

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36479	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1360		LHS	Flash guards Signal break box		1			
36480	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1373		LHS	Flash guards Signal break box		1			
36481	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1380	1383	LHS	Flash guards Switch boxes 535 BTR, 535ATH, 535AT, 539BPGR, 539AGR		6			
36482	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1387		LHS	Flash guards Signal A539A		1			
39621	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1391		LHS	Flash guards Signal break box		1			
36483	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1406		LHS	Flash guards Signal break box		1			
36484	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1411		LHS	Flash guards Signal break box		1			
36485	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1541		LHS	Flash guards Signal R539 B		1			
36486	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1577		LHS	Flash guards Fog repeater A539B		1			
40291	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1578		LHS	Flash guards Signal break box		1			
36487	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1583		LHS	Flash guards Signal break box		1			
36488	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1592		LHS	Flash guards Signal break box		1			
39374	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1652		LHS	Flash guards Electrical box attached to bridge D23		1			
36489	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1655		LHS	Flash guards Marshalling kiosk 539BIND		1			
36490	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1677		LHS	Flash guards Signal break box		1			
40292	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1703		LHS	Flash guards Marshalling kiosk 539 B		1			
36491	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1706		LHS	Flash guards Signal A539B		1			
36492	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1721		LHS	Flash guards Signal break box		1			
36493	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1725		LHS	Flash guards Signal break box		1			



Hazardous Material Asset Register - Summary



P086-P - PIC Line - Park Royal to Alperton

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36494	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1800	1801	LHS	Flash guards Switch boxes 539 ATR, 541PGR		2			
40293	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1804		LHS	Flash guards Signal break box		1			
36495	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1807		LHS	Flash guards Signal R541		1			
36496	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1815		LHS	Flash guards Switch box Adj. to post route on bridge		1			
39622	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1816		LHS	Flash guards Marshalling kiosk 540		1			
36497	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1835		LHS	Flash guards Signal break box		1			
36498	ACTIVE	P	P086-P-EBMA	Road EBMA - PIC - Alperton to Park Royal	Signal Boxes	Asbestos	Presumed	1837		LHS	Flash guards Signal break box		1			
39127	ACTIVE	P	P086-P-WBMA	Road WBMA - PIC - Park Royal to Alperton	Signal Boxes	Asbestos	Known	7		LHS	Flash guards Signal A540		1			
39128	ACTIVE	P	P086-P-WBMA	Road WBMA - PIC - Park Royal to Alperton	Signal Boxes	Asbestos	Presumed	503		LHS	Flash guards Signal R536		1			
39129	ACTIVE	P	P086-P-WBMA	Road WBMA - PIC - Park Royal to Alperton	Signal Boxes	Asbestos	Presumed	599		LHS	Flash guards Fog repeater A536		1			
39130	ACTIVE	P	P086-P-WBMA	Road WBMA - PIC - Park Royal to Alperton	Signal Boxes	Asbestos	Presumed	720		LHS	Flash guards Signal A536		1			
39346	ACTIVE	P	P086-P-WBMA	Road WBMA - PIC - Park Royal to Alperton	Signal Boxes	Asbestos	Presumed	1288		LHS	Flash guards Fog repeater A530A		1			
39131	ACTIVE	P	P086-P-WBMA	Road WBMA - PIC - Park Royal to Alperton	Signal Boxes	Asbestos	Presumed	1408		LHS	Flash guards Signal A530A		1			
39132	ACTIVE	P	P086-P-WBMA	Road WBMA - PIC - Park Royal to Alperton	Signal Boxes	Asbestos	Presumed	1546		LHS	Flash guards Signal 530 b		1			
39133	ACTIVE	P	P086-P-WBMA	Road WBMA - PIC - Park Royal to Alperton	Ducts	Asbestos	Sampled – Not Detected	1619		LHS	Bitumen ducts					
39692	ACTIVE	P	P086-P-WBMA	Road WBMA - PIC - Park Royal to Alperton	Signal Boxes	Asbestos	Presumed	1626		LHS	Flash guards Fog repeater A530B		1			
39347	ACTIVE	P	P086-P-WBMA	Road WBMA - PIC - Park Royal to Alperton	Ducts	Asbestos	Sampled – Not Detected	1656		LHS	Bitumen ducts					
39134	ACTIVE	P	P086-P-WBMA	Road WBMA - PIC - Park Royal to Alperton	Signal Boxes	Asbestos	Presumed	1750		LHS	Flash guards Signal A530B		1			
38941	ACTIVE	P	P086-P-WBMA	Road WBMA - PIC - Park Royal to Alperton	Ducts	Asbestos	Sampled – Not Detected	1793		LHS	Bitumen ducts					



Hazardous Material Asset Register - Summary



P086-P - PIC Line - Park Royal to Alperton

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
38942	ACTIVE	p	P086-P-WBMA	Road WBMA - PIC - Park Royal to Alperton	Ducts	Asbestos	Sampled – Not Detected	1797		LHS	Bitumen ducts					
38943	ACTIVE	p	P086-P-WBMA	Road WBMA - PIC - Park Royal to Alperton	Signal Boxes	Asbestos	Presumed	1823		LHS	Flash guards Signal R528		1			
38944	ACTIVE	p	P086-P-WBMA	Road WBMA - PIC - Park Royal to Alperton	Ducts	Asbestos	Sampled – Not Detected	1830		LHS	Bitumen ducts					
39900	ACTIVE	p	P086-P-WBMA	Road WBMA - PIC - Park Royal to Alperton	Signal Boxes	Asbestos	Removed	1855			Flash guards Switch box Notes from 2022 re-inspection: Removed		1			

P088-P - PIC Line - Alperton to Sudbury Town

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40945	ACTIVE	p	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alperton	Signal Boxes	Asbestos	Presumed	11		LHS	Flash guards Signal A521		1			
40946	ACTIVE	p	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alperton	Ducts	Asbestos	Sampled – Not Detected	12		LHS	Bitumen ducts					
40947	ACTIVE	p	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alperton	Signal Boxes	Asbestos	Presumed	295		LHS	Flash guards Signal break box		1			
40948	ACTIVE	p	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alperton	Signal Boxes	Asbestos	Presumed	298		LHS	Flash guards Signal break box		1			
40949	ACTIVE	p	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alperton	Signal Boxes	Asbestos	Presumed	306		LHS	Flash guards Switch box 522BPGR, 526 ATR		2			
39492	ACTIVE	p	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alperton	Signal Boxes	Asbestos	Presumed	432		LHS	Flash guards Signal break box		1			
40950	ACTIVE	p	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alperton	Signal Boxes	Asbestos	Presumed	435		LHS	Flash guards Signal break box		1			
54075	ACTIVE	p	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alperton	Other Electrical Boxes	Asbestos	Presumed	465	467	LHS	Flash guards Switch box 522 AGR, 528DTH, 528DT, 528ETR Notes from 2022 re-inspection: Present 2022		5			
40951	ACTIVE	p	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alperton	Signal Boxes	Asbestos	Presumed	522	524	LHS	Flash guards Switch box519CTH, 521ATR		4			
39997	ACTIVE	p	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alperton	Signal Boxes	Asbestos	Presumed	526		LHS	Flash guards Signal break box		1			
40952	ACTIVE	p	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alperton	Signal Boxes	Asbestos	Presumed	527		LHS	Flash guards Signal break box		1			
39493	ACTIVE	p	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alperton	Signal Boxes	Asbestos	Presumed	549		LHS	Flash guards Signal break box		1			



Hazardous Material Asset Register - Summary



P088-P - PIC Line - Alpertown to Sudbury Town

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
40953	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	550		LHS	Flash guards Signal break box		1			
40954	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	558		LHS	Flash guards Switch box 522APGR(2), 528TR		2			
40955	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	725	727	LHS	Flash guards Switch box 521ATH, 521TR, 527APGR(1)		5			
40956	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	729		LHS	Flash guards Signal break box		1			
40957	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	731		LHS	Flash guards Signal break box		1			
41035	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	731		LHS	Flash guards Signal R527A(1)		1			
41036	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	736	739	LHS	Flash guards Switch box 526GR, 528BTH, 522APG(1), 528CTR		6			
41037	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	741		LHS	Flash guards Signal break box		1			
41038	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	743		LHS	Flash guards Signal break box		1			
41039	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	833		LHS	Flash guards Switch box 521CTR, 527APGR(2)		2			
41040	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	836		LHS	Flash guards Signal break box		1			
41041	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	836		LHS	Flash guards Fog repeater A527A		1			
39500	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	838		LHS	Flash guards Signal break box		1			
40025	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	853		LHS	Flash guards Signal R527 A(2)		1			
41042	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	858		LHS	Flash guards Signal break box		1			
41043	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	859		LHS	Flash guards Signal break box		1			
41044	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	892	895	LHS	Flash guards Switch box 526PG, 528 ATH, 528AT, 526TR, 528TR		6			
41045	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	947	949	LHS	Flash guards Switch box 521CTH, 521DTR, 527AGR		5			
41046	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	952		LHS	Flash guards Signal break box		1			



Hazardous Material Asset Register - Summary



P088-P - PIC Line - Alpertown to Sudbury Town

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41048	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	953		LHS	Flash guards Signal A527A		1			
41047	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	953		LHS	Flash guards Signal break box		1			
41049	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	971		LHS	Flash guards Signal break box		1			
41050	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	974		LHS	Flash guards Signal break box		1			
39521	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	1139	1141	LHS	Flash guards Switch boxes 521DTH, 521DT, 521ETR, 527BPGR		4			
41051	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	1146		LHS	Flash guards Signal R527 B(1)		1			
41052	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	1161		LHS	Flash guards Signal break box		1			
41053	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	1165		LHS	Flash guards Signal break box		1			
41054	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	1205		LHS	Flash guards Signal break box		1			
39798	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	1206		LHS	Flash guards Signal break box		1			
39522	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	1228		LHS	Flash guards Switch box 521FTR, 527BPGR		2			
41055	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	1232		LHS	Flash guards Fog Repeater 527B		1			
41056	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	1241		LHS	Flash guards Signal R527 B(2)		1			
41057	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	1248		LHS	Flash guards Signal break box		1			
41058	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	1252		LHS	Flash guards Signal break box		1			
41059	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	1348		LHS	Flash guards Signal A527B		1			
41060	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	1353	1355	LHS	Flash guards Switch box 527 BGR, 521GTR, 521FT, 521 FTH		5			
39523	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	1353		LHS	Flash guards Signal break box		1			
41061	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	1357		LHS	Flash guards Signal break box		1			



Hazardous Material Asset Register - Summary



P088-P - PIC Line - Alpertown to Sudbury Town

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
54076	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Other Electrical Boxes	Asbestos	Presumed	1392		LHS	Flash guards Signal break box Notes from 2022 re-inspection: still present		1			
41141	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Cement Cable Troughing & Debris	Asbestos	Presumed	1411		LHS	Cement cable troughing		1			
41062	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	1412		LHS	Flash guards Switch box RGIATA528		1			
41140	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	1413		LHS	Flash guards Signal break box		1			
41142	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	1418		LHS	Flash guards Switch box 527atr, 529PGR		2			
41143	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	1419		LHS	Flash guards Signal break box		1			
40030	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	1425		LHS	Flash guards Signal R529		1			
41144	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	1426		LHS	Flash guards Signal break box		1			
41145	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	1431		LHS	Flash guards Signal break box		1			
41146	ACTIVE	P	P088-P-EBMA	Road EBMA - PIC - Sudbury Town to Alpertown	Signal Boxes	Asbestos	Presumed	1439		LHS	Flash guards Switch box 528GR, 530 ATH, 530AT, 530CTR, 530BTR		6			
36499	ACTIVE	P	P088-P-WBMA	Road WBMA - PIC - Alpertown to Sudbury Town	Signal Boxes	Asbestos	Presumed	15		LHS	Flash guards Signal A528		1			
36500	ACTIVE	P	P088-P-WBMA	Road WBMA - PIC - Alpertown to Sudbury Town	Signal Boxes	Asbestos	Presumed	15		LHS	Flash guards Rail Gap Indicator		1			
36501	ACTIVE	P	P088-P-WBMA	Road WBMA - PIC - Alpertown to Sudbury Town	Signal Boxes	Asbestos	Presumed	556		LHS	Flash guards Signal R526		1			
36502	ACTIVE	P	P088-P-WBMA	Road WBMA - PIC - Alpertown to Sudbury Town	Signal Boxes	Asbestos	Presumed	588		LHS	Flash guards Fog Repeater A526		1			
39516	ACTIVE	P	P088-P-WBMA	Road WBMA - PIC - Alpertown to Sudbury Town	Signal Boxes	Asbestos	Presumed	708		LHS	Flash guards Signal A526		1			
36503	ACTIVE	P	P088-P-WBMA	Road WBMA - PIC - Alpertown to Sudbury Town	Signal Boxes	Asbestos	Presumed	708		LHS	Flash guards Signal R522 A(1)		2			
36504	ACTIVE	P	P088-P-WBMA	Road WBMA - PIC - Alpertown to Sudbury Town	Signal Boxes	Asbestos	Presumed	848		LHS	Flash guards Signal R522 A(2)		1			
36505	ACTIVE	P	P088-P-WBMA	Road WBMA - PIC - Alpertown to Sudbury Town	Signal Boxes	Asbestos	Presumed	860		LHS	Flash guards Fog Repeater A522A		1			
36506	ACTIVE	P	P088-P-WBMA	Road WBMA - PIC - Alpertown to Sudbury Town	Signal Boxes	Asbestos	Presumed	980		LHS	Flash guards Signal A 522A		1			



Hazardous Material Asset Register - Summary



P088-P - PIC Line - Alperton to Sudbury Town

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
36507	ACTIVE	P	P088-P-WBMA	Road WBMA - PIC - Alperton to Sudbury Town	Signal Boxes	Asbestos	Presumed	1137		LHS	Flash guards Signal R522 B		1			
36508	ACTIVE	P	P088-P-WBMA	Road WBMA - PIC - Alperton to Sudbury Town	Signal Boxes	Asbestos	Presumed	1140		LHS	Flash guards Fog repeater A552B		1			
36509	ACTIVE	P	P088-P-WBMA	Road WBMA - PIC - Alperton to Sudbury Town	Signal Boxes	Asbestos	Presumed	1244		LHS	Flash guards Signal break box		1			
36510	ACTIVE	P	P088-P-WBMA	Road WBMA - PIC - Alperton to Sudbury Town	Signal Boxes	Asbestos	Presumed	1248		LHS	Flash guards Signal break box		1			
36511	ACTIVE	P	P088-P-WBMA	Road WBMA - PIC - Alperton to Sudbury Town	Signal Boxes	Asbestos	Presumed	1271		LHS	Flash guards Switch boxes 526 ATH, 526T, 526BTR, 522BGR		1			
36512	ACTIVE	P	P088-P-WBMA	Road WBMA - PIC - Alperton to Sudbury Town	Signal Boxes	Asbestos	Presumed	1278		LHS	Flash guards Signal A522B		1			
36513	ACTIVE	P	P088-P-WBMA	Road WBMA - PIC - Alperton to Sudbury Town	Signal Boxes	Asbestos	Presumed	1288		LHS	Flash guards Signal break box		1			
54055	ACTIVE	P	P088-P-WBMA	Road WBMA - PIC - Alperton to Sudbury Town	Other Electrical Boxes	Asbestos	Presumed	1294		LHS	Flash guards Signal break box Notes from 2022 re-inspection: Present not removed 2022		1			
36514	ACTIVE	P	P088-P-WBMA	Road WBMA - PIC - Alperton to Sudbury Town	Signal Boxes	Asbestos	Presumed	1413		LHS	Flash guards Switch boxes 520 ATR & 520PGR Notes from 2022 re-inspection: 1x box		1			
36515	ACTIVE	P	P088-P-WBMA	Road WBMA - PIC - Alperton to Sudbury Town	Signal Boxes	Asbestos	Presumed	1418		LHS	Flash guards Switch box		1			
40294	ACTIVE	P	P088-P-WBMA	Road WBMA - PIC - Alperton to Sudbury Town	Signal Boxes	Asbestos	Presumed	1421		LHS	Flash guards Signal break box		1			
36516	ACTIVE	P	P088-P-WBMA	Road WBMA - PIC - Alperton to Sudbury Town	Signal Boxes	Asbestos	Presumed	1422		LHS	Flash guards Signal break box		1			
39623	ACTIVE	P	P088-P-WBMA	Road WBMA - PIC - Alperton to Sudbury Town	Signal Boxes	Asbestos	Presumed	1424		LHS	Flash guards Signal R520		1			
36517	ACTIVE	P	P088-P-WBMA	Road WBMA - PIC - Alperton to Sudbury Town	Signal Boxes	Asbestos	Presumed	1424		LHS	Flash guards Signal break box		1			
54056	ACTIVE	P	P088-P-WBMA	Road WBMA - PIC - Alperton to Sudbury Town	Other Electrical Boxes	Asbestos	Presumed	1426		LHS	Flash guards Signal break box		2			
36518	ACTIVE	P	P088-P-WBMA	Road WBMA - PIC - Alperton to Sudbury Town	Signal Boxes	Asbestos	Presumed	1427	1430	LHS	Flash guards Switch boxes 519 CTR, 519ATH, 519AT, 519BTR, 521GR		1			
40295	ACTIVE	P	P088-P-WBMA	Road WBMA - PIC - Alperton to Sudbury Town	Signal Boxes	Asbestos	Presumed	1436		LHS	Flash guards Signal break box		1			



Hazardous Material Asset Register - Summary



P092-P - PIC Line - Sudbury Town to Sudbury Hill

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39541	ACTIVE	P	P092-P-EBMA	Road EBMA - PIC - Sudbury Hill to Sudbury Town	Signal Boxes	Asbestos	Presumed	10		LHS	Flash guards Signal A513 & Rail Gap Indicator		2			
41347	ACTIVE	P	P092-P-EBMA	Road EBMA - PIC - Sudbury Hill to Sudbury Town	Cement Cable Troughing & Debris	Asbestos	Known	17	18	LHS	cement troughing		3			
41348	ACTIVE	P	P092-P-EBMA	Road EBMA - PIC - Sudbury Hill to Sudbury Town	Cement Cable Troughing & Debris	Asbestos	Known	17	18	LHS	cement debris on floor		2			
41349	ACTIVE	P	P092-P-EBMA	Road EBMA - PIC - Sudbury Hill to Sudbury Town	Signal Boxes	Asbestos	Presumed	23		LHS	Flash guards Switch box to bridge		1			
41350	ACTIVE	P	P092-P-EBMA	Road EBMA - PIC - Sudbury Hill to Sudbury Town	Signal Boxes	Asbestos	Presumed	23		LHS	Flash guards Signal break box		1			
41351	ACTIVE	P	P092-P-EBMA	Road EBMA - PIC - Sudbury Hill to Sudbury Town	Ducts	Asbestos	Sampled – Not Detected	26		LHS	bitumen ducts					
39504	ACTIVE	P	P092-P-EBMA	Road EBMA - PIC - Sudbury Hill to Sudbury Town	Cement Cable Troughing & Debris	Asbestos	Presumed	26		LHS	Cement panel. Embankment floor		1			
40038	ACTIVE	P	P092-P-EBMA	Road EBMA - PIC - Sudbury Hill to Sudbury Town	Signal Boxes	Asbestos	Presumed	458		LHS	Flash guards Fog repeater A515		1			
41352	ACTIVE	P	P092-P-EBMA	Road EBMA - PIC - Sudbury Hill to Sudbury Town	Signal Boxes	Asbestos	Presumed	474		LHS	Flash guards Signal R515		1			
41353	ACTIVE	P	P092-P-EBMA	Road EBMA - PIC - Sudbury Hill to Sudbury Town	Signal Boxes	Asbestos	Presumed	580		LHS	Flash guards Signal A515		1			
41354	ACTIVE	P	P092-P-EBMA	Road EBMA - PIC - Sudbury Hill to Sudbury Town	Signal Boxes	Asbestos	Presumed	837		LHS	Flash guards Fog repeater A519A		1			
41355	ACTIVE	P	P092-P-EBMA	Road EBMA - PIC - Sudbury Hill to Sudbury Town	Signal Boxes	Asbestos	Presumed	959		LHS	Flash guards Signal A519A		1			
41356	ACTIVE	P	P092-P-EBMA	Road EBMA - PIC - Sudbury Hill to Sudbury Town	Signal Boxes	Asbestos	Presumed	1168		LHS	Flash guards Signal R519 B		1			
41357	ACTIVE	P	P092-P-EBMA	Road EBMA - PIC - Sudbury Hill to Sudbury Town	Signal Boxes	Asbestos	Presumed	1192		LHS	Flash guards Fog repeater A519B		1			
41358	ACTIVE	P	P092-P-EBMA	Road EBMA - PIC - Sudbury Hill to Sudbury Town	Signal Boxes	Asbestos	Presumed	1311		LHS	Flash guards Signal A519B		1			
41359	ACTIVE	P	P092-P-EBMA	Road EBMA - PIC - Sudbury Hill to Sudbury Town	Signal Boxes	Asbestos	Presumed	1513		LHS	Flash guards Switch box		1			
41360	ACTIVE	P	P092-P-EBMA	Road EBMA - PIC - Sudbury Hill to Sudbury Town	Signal Boxes	Asbestos	Presumed	1514		LHS	Flash guards Signal RR521		1			
41361	ACTIVE	P	P092-P-EBMA	Road EBMA - PIC - Sudbury Hill to Sudbury Town	Ducts	Asbestos	Sampled – Not Detected	1518		LHS	bitumen ducts					
41362	ACTIVE	P	P092-P-EBMA	Road EBMA - PIC - Sudbury Hill to Sudbury Town	Signal Boxes	Asbestos	Presumed	1532		LHS	Flash guards Switch box		2			



Hazardous Material Asset Register - Summary



P092-P - PIC Line - Sudbury Town to Sudbury Hill

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41363	ACTIVE	p	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	1		LHS	Flash guards Signal break box		1			
39568	ACTIVE	p	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	8		LHS	Flash guards Signal A52 0		1			
41364	ACTIVE	p	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	12		LHS	Flash guards Signal break box		1			
41365	ACTIVE	p	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	14		LHS	Flash guards Electrical Kiosk		1			
41366	ACTIVE	p	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	15	18	LHS	Flash guards Switch boxes Notes from 2022 re-inspection: 2 small, 1 large		3			
41367	ACTIVE	p	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	21	24	LHS	Flash guards Switch boxes 520GR, 522ATH, TAAAT, 522BTR, 522CTR		6			
39569	ACTIVE	p	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	25		LHS	Flash guards Signal break box		1			
41368	ACTIVE	p	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	30		LHS	Flash guards Switch boxes 521PGR, 519ATR		2			
41369	ACTIVE	p	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	36		LHS	Flash guards Signal break box		1			
41370	ACTIVE	p	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	39		LHS	Flash guards Signal break box		1			
39853	ACTIVE	p	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	84		LHS	Flash guards Signal break box		1			
41371	ACTIVE	p	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	143		LHS	Flash guards Signal break box		1			
39570	ACTIVE	p	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	144		LHS	Flash guards Signal break box		1			
41372	ACTIVE	p	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	229	233	LHS	Flash guards Switch boxes 519GR, 515BTH, 515BT, 515CTR		5			
41373	ACTIVE	p	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	335		LHS	Flash guards Signal break box		1			
41374	ACTIVE	p	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	339		LHS	Flash guards Signal break box		1			
41447	ACTIVE	p	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	349	351	LHS	Flash guards Switch boxes 519 BGR, 515ATH, 515AT, 515BTR, 515ATR		6			
41448	ACTIVE	p	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	415	417	LHS	Flash guards Switch boxes 522 CTH, 522CT, 520ATR, 516BTR		4			
41449	ACTIVE	p	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	422		LHS	Flash guards Fog repeater A516		1			



Hazardous Material Asset Register - Summary



P092-P - PIC Line - Sudbury Town to Sudbury Hill

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41450	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	436		LHS	Flash guards Signal break box		1			
41451	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	437		LHS	Flash guards Signal break box		1			
41452	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	535	583	LHS	Flash guards Switch boxes 520 ATH, 520AT, 520BTR, 516GR		5			
41453	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	544		LHS	Flash guards Signal A516		1			
41454	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	551		LHS	Flash guards Signal break box		1			
41455	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	553		LHS	Flash guards Signal break box		1			
40042	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	554		LHS	Flash guards Signal break box		1			
41456	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	559		LHS	Flash guards Signal break box		1			
41457	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	581	583	LHS	Flash guards Switch boxes 519 BGR, 515ATH, 515AT, 515BTR, 515ATR		5			
41458	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	706		LHS	Flash guards Switch boxes 519 APGR, 513CTR		2			
41459	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	765		LHS	Flash guards Signal break box		1			
39505	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	837		LHS	Flash guards Fog repeater A514A		1			
41460	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	865		LHS	Flash guards Switch box 514APGR, 520CTR		2			
41461	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	871		LHS	Flash guards Signal R514 A		1			
41462	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	874		LHS	Flash guards Signal break box		1			
41463	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	876		LHS	Flash guards Signal break box		1			
41464	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	931		LHS	Flash guards Signal break box		1			
41465	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	950	952	LHS	Flash guards Switch boxes 520 C, T20CT, 516ATR, 514BGR		5			
41466	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	955		LHS	Flash guards Signal A514A		1			



Hazardous Material Asset Register - Summary



P092-P - PIC Line - Sudbury Town to Sudbury Hill

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41467	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	960	962	LHS	Flash guards Switch boxes 515GR, 513ATH, 513AT, 513BTR		4			
39575	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	999		LHS	Flash guards Signal break box		1			
41468	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	1001		LHS	Flash guards Signal break box		1			
41469	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	1052		LHS	Flash guards Signal break box		1			
41470	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	1054		LHS	Flash guards Signal break box		1			
39857	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	1063	1065	LHS	Flash guards Switch boxes 515PGR, 511CTH, 511CT, 513ATR		5			
39576	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	1088		LHS	Flash guards Signal break box		1			
41471	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	1156	1158	LHS	Flash guards Switch boxes 516 ATH, 516AT, 516BTR, 14BPGR		5			
41472	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	1164		LHS	Flash guards Signal R514 B		1			
41473	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	1190		LHS	Flash guards Fog repeater A514B		1			
41548	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	1307	1309	LHS	Flash guards Switch boxes 516 BTH, 516BT, 516CTR, 514BGR		5			
41549	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	1313		LHS	Flash guards Signal A514B		1			
41550	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	1330		LHS	Flash guards Signal break box		1			
41551	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	1334		LHS	Flash guards Signal break box		1			
41552	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	1372		LHS	Flash guards Signal break box		1			
41553	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	1375		LHS	Flash guards Signal break box Notes from 2022 re-inspection: 2x		2			
39861	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	1491		LHS	Flash guards Switch boxes 514 ATR, 512PGR		2			
41558	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	1503		LHS	Flash guards Signal R512		1			
41554	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	1503		LHS	Flash guards Signal break box		1			



Hazardous Material Asset Register - Summary



P092-P - PIC Line - Sudbury Town to Sudbury Hill

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41559	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	1504	1507	LHS	Flash guards Switch boxes 511 CTR, 511ATH, 511AT, 511BTR, 513GR		6			
41555	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	1513		LHS	Flash guards Signal break box		1			
41556	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	1518		LHS	Flash guards Signal break box		1			
54074	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Other Electrical Boxes	Asbestos	Presumed	1523		LHS	Flash guards Signal break box		1			
41557	ACTIVE	P	P092-P-WBMA	Road WBMA - PIC - Sudbury Town to Sudbury Hill	Signal Boxes	Asbestos	Presumed	1525		LHS	Flash guards Signal break box		1			

P093-P - PIC Line - Sudbury Hill Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
53681	ACTIVE	P	P093-P-EBMA	Road EBMA (Plt2) - PIC - Sudbury Hill Stn	Ducts	Asbestos	Strongly Presumed				P093/CTP0020 - P093/CTP0020A Pipe material lining VC Pipework presumed to contain asbestos. Refer to Drawing 15F09-DJNP0204-DWG-DRN-P094-410_AFC Plan and Long Section. Sampling to be carried out when access is possible. RAS (associated document attached under maximo record 53680)	10				

P094-P - PIC Line - Sudbury Hill to South Harrow (incl Sth Harrow Sidings)

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41218	ACTIVE	P	P094-P-EBMA	Road EBMA - PIC - South Harrow to Sudbury Hill	Signal Boxes	Asbestos	Presumed	10		LHS	Board Lining to Circuit Breaker / Westinghouse Box (+ Paxoline panels) on walkway from South Harrow Station to Sidings by IMR 1/706		1			
41219	ACTIVE	P	P094-P-EBMA	Road EBMA - PIC - South Harrow to Sudbury Hill	Signal Boxes	Asbestos	Presumed	13		LHS	Flash guards Switch box		1			
41220	ACTIVE	P	P094-P-EBMA	Road EBMA - PIC - South Harrow to Sudbury Hill	Signal Boxes	Asbestos	Presumed	18		LHS	Lining to Circuit Breaker / Westinghouse Box On walkway to sidings by cable run		1			
41221	ACTIVE	P	P094-P-EBMA	Road EBMA - PIC - South Harrow to Sudbury Hill	Signal Boxes	Asbestos	Presumed	22		LHS	Flash guards Switch box					
41222	ACTIVE	P	P094-P-EBMA	Road EBMA - PIC - South Harrow to Sudbury Hill	Cement Cable Troughing & Debris	Asbestos	Known	48		LHS	Cement troughing. Cable troughing running under track		2			
41223	ACTIVE	P	P094-P-EBMA	Road EBMA - PIC - South Harrow to Sudbury Hill	Signal Boxes	Asbestos	Presumed	49		LHS	Flash guards Switch box		1			



Hazardous Material Asset Register - Summary



P094-P - PIC Line - Sudbury Hill to South Harrow (incl Sth Harrow Sidings)

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41224	ACTIVE	P	P094-P-EBMA	Road EBMA - PIC - South Harrow to Sudbury Hill	Signal Boxes	Asbestos	Presumed	50		LHS	Flash guards Signal break box		1			
41227	ACTIVE	P	P094-P-EBMA	Road EBMA - PIC - South Harrow to Sudbury Hill	Signal Boxes	Asbestos	Presumed	130		LHS	Flash guards Signal break box		1			
41228	ACTIVE	P	P094-P-EBMA	Road EBMA - PIC - South Harrow to Sudbury Hill	Signal Boxes	Asbestos	Presumed	133		LHS	Flash guards Signal break box		1			
41229	ACTIVE	P	P094-P-EBMA	Road EBMA - PIC - South Harrow to Sudbury Hill	Signal Boxes	Asbestos	Presumed	135	136	LHS	Flash guards Switch boxes BLTH, GAT, GATH		4			
41230	ACTIVE	P	P094-P-EBMA	Road EBMA - PIC - South Harrow to Sudbury Hill	Cement Cable Troughing & Debris	Asbestos	Known	140		LHS	Cement debris. Debris behind post route, unable to quantify					
41231	ACTIVE	P	P094-P-EBMA	Road EBMA - PIC - South Harrow to Sudbury Hill	Signal Boxes	Asbestos	Presumed	141		LHS	Flash guards Rail Gap Indicator		1			
39848	ACTIVE	P	P094-P-EBMA	Road EBMA - PIC - South Harrow to Sudbury Hill	Signal Boxes	Asbestos	Presumed	144		LHS	Flash guards Circuit Breaker		1			
41232	ACTIVE	P	P094-P-EBMA	Road EBMA - PIC - South Harrow to Sudbury Hill	Signal Boxes	Asbestos	Presumed	497		LHS	Flash guards Signal R511 A		1			
41233	ACTIVE	P	P094-P-EBMA	Road EBMA - PIC - South Harrow to Sudbury Hill	Signal Boxes	Asbestos	Presumed	524		LHS	Flash guards Fog repeater A511A		1			
41234	ACTIVE	P	P094-P-EBMA	Road EBMA - PIC - South Harrow to Sudbury Hill	Signal Boxes	Asbestos	Presumed	649		LHS	Flash guards Signal A511A, R511B(1)		2			
39536	ACTIVE	P	P094-P-EBMA	Road EBMA - PIC - South Harrow to Sudbury Hill	Signal Boxes	Asbestos	Presumed	857		LHS	Flash guards Signal R511 B(2		1			
41235	ACTIVE	P	P094-P-EBMA	Road EBMA - PIC - South Harrow to Sudbury Hill	Signal Boxes	Asbestos	Presumed	875		LHS	Flash guards Fog Repeater A511B		1			
41236	ACTIVE	P	P094-P-EBMA	Road EBMA - PIC - South Harrow to Sudbury Hill	Signal Boxes	Asbestos	Presumed	1002		LHS	Flash guards Signal A511B		1			
41237	ACTIVE	P	P094-P-EBMA	Road EBMA - PIC - South Harrow to Sudbury Hill	Signal Boxes	Asbestos	Presumed	1200		LHS	Flash guards Signal R513		1			
43980	ACTIVE	P	P094-P-EBMA	Road EBMA - PIC - South Harrow to Sudbury Hill		Other Hazardous Materials	Known				Coal Tar Analysis of Sample Taken from Underbridge D3 Between Sth Harrow and Sudbury Hill: Ref: ES9594 The sample analysed is classified as Hazardous Waste and can be given the EWC code 17 03 01			R501203	N	N
41147	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	5	8	LHS	Flash guards Switch boxes		6			
41148	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	15		LHS	Flash guards Signal A152 & Rail Gap Indicator		2			



Hazardous Material Asset Register - Summary



P094-P - PIC Line - Sudbury Hill to South Harrow (incl Sth Harrow Sidings)

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41149	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Removed	16	19	LHS	Flash guards Link boxes Notes from 2022 re-inspection: Removed		4			
41150	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	17		LHS	Flash guards Signal break box		1			
41151	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	27		LHS	Flash guards Signal break box		1			
41152	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	28		LHS	Flash guards Switch box		1			
41153	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	47		LHS	Flash guards Switch boxes		2			
39800	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	164		LHS	Flash guards Signal break box		1			
41154	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	165		LHS	Flash guards Signal break box		1			
41155	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	199		LHS	Flash guards Signal break box		1			
39529	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	204		LHS	Flash guards Signal Circuit breaker - Westinghouse box		1			
41156	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	276	278	LHS	Flash guards Switch boxes511BGR, BWTH, BWT, BXTB		5			
41157	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	365		LHS	Flash guards Switch boxes BETR, 511 BPGR		2			
41158	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	460	462	LHS	Flash guards Switch boxes 514 TH, 514CT, 512ATR		4			
41159	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	512		LHS	Flash guards Signal RWVX508		1			
41160	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	525		LHS	Flash guards Switch boxes 508PGR, 512BTRF		2			
39530	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	527		LHS	Flash guards Fog repeater WVX508		1			
41161	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	553		LHS	Flash guards Signal break box		1			
41162	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	564		LHS	Flash guards Signal break box		1			
41163	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	573		LHS	Flash guards Signal break box		1			
41164	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	577		LHS	Flash guards Signal break box		1			



Hazardous Material Asset Register - Summary



P094-P - PIC Line - Sudbury Hill to South Harrow (incl Sth Harrow Sidings)

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39531	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	588	591	LHS	Flash guards Switch boxes		6			
41165	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	643	645	LHS	Flash guards Switch boxes 512TR, 512BTH, 512BT, 508GR		5			
40031	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	650		LHS	Flash guards Signal WVX508		1			
41166	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	665		LHS	Flash guards Signal break box		1			
41167	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	667		LHS	Flash guards Signal break box		1			
41245	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	715		LHS	Flash guards Signal break box		1			
41246	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	725	727	LHS	Flash guards Switch boxes BPTH, BPT, B9TR, 511APGR		5			
41247	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	836		LHS	Flash guards Switch boxes 512DTR, 1PGR		2			
41248	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	839		LHS	Flash guards Fog repeater WV1		1			
41249	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	842		LHS	Flash guards Signal break box		1			
41250	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	844		LHS	Flash guards Signal break box		1			
39849	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	926	930	LHS	Flash guards Switch boxes 512DTH, 512DT, 512ETR, 1GR, 2PGR		7			
41251	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	932		LHS	Flash guards Signal WV1, Fog repeater WV2		2			
41252	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	933		LHS	Flash guards Signal break box		1			
41253	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	934		LHS	Flash guards Signal break box		1			
41254	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	1015		LHS	Flash guards Signal break box		1			
41255	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	1082		LHS	Flash guards side Switch boxes 512GTH, 512 ETH		3			
41256	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	1087		LHS	Flash guards Switch box 2GR		1			
41257	ACTIVE	P	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	1088		LHS	Flash guards Signal WV2 & Rail Gap Indicator		2			



Hazardous Material Asset Register - Summary



P094-P - PIC Line - Sudbury Hill to South Harrow (incl Sth Harrow Sidings)

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41258	ACTIVE	p	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	1090		LHS	Flash guards Signal break box		1			
41259	ACTIVE	p	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	1091		LHS	Flash guards Signal break box		1			
41260	ACTIVE	p	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	1152		LHS	Flash guards Switch box 12PH		1			
41261	ACTIVE	p	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	1155		LHS	Flash guards Signal break box		1			
41263	ACTIVE	p	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Removed	1169	1172	LHS	Flash guards Link boxes Notes from 2022 re-inspection: Removed		4			
41262	ACTIVE	p	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	1169		LHS	Flash guards Signal break box		1			
41264	ACTIVE	p	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	1171		LHS	Flash guards Signal break box		1			
39539	ACTIVE	p	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	1172		LHS	Flash guards Signal break box		1			
41265	ACTIVE	p	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	1173		LHS	Flash guards Signal break box		1			
40035	ACTIVE	p	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	1177		LHS	Flash guards Junction box		1			
41266	ACTIVE	p	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	1179		LHS	Flash guards Signal break box		1			
41267	ACTIVE	p	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	1184		LHS	Flash guards Signal break box		1			
39540	ACTIVE	p	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	1186		LHS	Flash guards Signal break box		1			
41268	ACTIVE	p	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	1203		LHS	Flash guards Signal break box		1			
41269	ACTIVE	p	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Cement Cable Troughing & Debris	Asbestos	Known	1215		LHS	Cement debris. Debris to floor behind post route					
41270	ACTIVE	p	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Cement Cable Troughing & Debris	Asbestos	Known	1230		LHS	Troughing from track to post route up to box on 1233 Flash guards		6			
41271	ACTIVE	p	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	1233		LHS	Flash guards Switch box WBCOC					
41272	ACTIVE	p	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow	Signal Boxes	Asbestos	Presumed	1235		LHS	Flash guards Switch box					



Hazardous Material Asset Register - Summary



P094-P - PIC Line - Sudbury Hill to South Harrow (incl Sth Harrow Sidings)

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43982	ACTIVE	p	P094-P-WBMA	Road WBMA - PIC - Sudbury Hill to South Harrow		Other Hazardous Materials	Known				Coal Tar Analysis of Sample Taken from Underbridge D3. Ref: ES9594 The sample analysed is classified as Hazardous Waste and can be given the EWC code 17 03 01*.				N	N

P095-P - South Harrow Stn - PIC Line

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
67604	ACTIVE	p	P095-P-EBMA	Road EBMA (Plt2) - PIC - South Harrow Stn	Cable Sheath	Asbestos	Surveyed – Not Detected				Concrete & pvc cables					
67603	ACTIVE	p	P095-P-EBMA	Road EBMA (Plt2) - PIC - South Harrow Stn	Ducts	Asbestos	Surveyed – Not Detected	0			Bitumen ducts platform 2					
67602	ACTIVE	p	P095-P-WBMA	Road WBMA (Plt1) - PIC - South Harrow Stn	Cable Sheath	Asbestos	Surveyed – Not Detected				Concrete & pvc cables					
67601	ACTIVE	p	P095-P-WBMA	Road WBMA (Plt1) - PIC - South Harrow Stn	Ducts	Asbestos	Surveyed – Not Detected	143			platform 1 ducts					

P102-P - PIC Line - South Harrow to Rayners Lane

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39356	ACTIVE	p	P102-P-EBMA	Road EBMA - PIC - Rayners Lane Jct to South Harrow	Ducts	Asbestos	Sampled – Not Detected	29		LHS	Bitumen ducts to left hand side					
39257	ACTIVE	p	P102-P-EBMA	Road EBMA - PIC - Rayners Lane Jct to South Harrow	Signal Boxes	Asbestos	Presumed	37		LHS	Flash guards Switch box ECOTE - R.LA.EB Notes from 2022 re-inspection: Loose to floor disconnected		1			
39258	ACTIVE	p	P102-P-EBMA	Road EBMA - PIC - Rayners Lane Jct to South Harrow	Signal Boxes	Asbestos	Presumed	42		LHS	Flash guards Marshalling Kiosk No 1		1			
39259	ACTIVE	p	P102-P-EBMA	Road EBMA - PIC - Rayners Lane Jct to South Harrow	Signal Boxes	Asbestos	Presumed	213		LHS	Flash guard Signal break box		1			
39717	ACTIVE	p	P102-P-EBMA	Road EBMA - PIC - Rayners Lane Jct to South Harrow	Signal Boxes	Asbestos	Presumed	242		LHS	Flash guards Switch box		1			
39260	ACTIVE	p	P102-P-EBMA	Road EBMA - PIC - Rayners Lane Jct to South Harrow	Signal Boxes	Asbestos	Presumed	242		LHS	Flash guard Signal break box		1			
39357	ACTIVE	p	P102-P-EBMA	Road EBMA - PIC - Rayners Lane Jct to South Harrow	Signal Boxes	Asbestos	Presumed	364		LHS	Flash guards Fog repeater WVX505		1			
39261	ACTIVE	p	P102-P-EBMA	Road EBMA - PIC - Rayners Lane Jct to South Harrow	Signal Boxes	Asbestos	Presumed	501		LHS	Flash guards Signal WVX505		1			
39263	ACTIVE	p	P102-P-EBMA	Road EBMA - PIC - Rayners Lane Jct to South Harrow	Cement Cable Troughing & Debris	Asbestos	Presumed	532		LHS	debris to floor. Small amounts					



Hazardous Material Asset Register - Summary



P102-P - PIC Line - South Harrow to Rayners Lane

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39262	ACTIVE	P	P102-P-EBMA	Road EBMA - PIC - Rayners Lane Jct to South Harrow	Signal Boxes	Asbestos	Known	532		LHS	Asbestos cement. Boxing to electrical equipment (supalux panel to top of box). 4sqm					
39264	ACTIVE	P	P102-P-EBMA	Road EBMA - PIC - Rayners Lane Jct to South Harrow	Signal Boxes	Asbestos	Presumed	537		LHS	Flash guards Switch box		1			
39265	ACTIVE	P	P102-P-EBMA	Road EBMA - PIC - Rayners Lane Jct to South Harrow	Signal Boxes	Asbestos	Presumed	541		LHS	Flash guards Switch box		1			
39266	ACTIVE	P	P102-P-EBMA	Road EBMA - PIC - Rayners Lane Jct to South Harrow	Ducts	Asbestos	Sampled – Not Detected	557		LHS	Bitumen ducts to elephant trunking					
39718	ACTIVE	P	P102-P-EBMA	Road EBMA - PIC - Rayners Lane Jct to South Harrow	Signal Boxes	Asbestos	Presumed	748		LHS	Flash guard Signal break box 2no Notes from 2022 re-inspection: 2x SWH not 1x SWH		2			
39268	ACTIVE	P	P102-P-EBMA	Road EBMA - PIC - Rayners Lane Jct to South Harrow	Signal Boxes	Asbestos	Presumed	849	850	LHS	Flash guards Switch boxes 503 BT & 503CTR		4			
39267	ACTIVE	P	P102-P-EBMA	Road EBMA - PIC - Rayners Lane Jct to South Harrow	Signal Boxes	Asbestos	Removed	853		LHS	Flash guard Signal break box Notes from 2022 re-inspection: Removed		1			
39269	ACTIVE	P	P102-P-EBMA	Road EBMA - PIC - Rayners Lane Jct to South Harrow	Signal Boxes	Asbestos	Presumed	1309		LHS	Flash guards Switch box redundant, left hand side of post route		3			
39270	ACTIVE	P	P102-P-EBMA	Road EBMA - PIC - Rayners Lane Jct to South Harrow	Signal Boxes	Asbestos	Presumed	1376	1378	LHS	Flash guards Switch boxes 24PGR, 505CT & 505AT		5			
39271	ACTIVE	P	P102-P-EBMA	Road EBMA - PIC - Rayners Lane Jct to South Harrow	Signal Boxes	Asbestos	Presumed	1379		LHS	Flash guards Fog repeater RWV24		1			
39272	ACTIVE	P	P102-P-EBMA	Road EBMA - PIC - Rayners Lane Jct to South Harrow	Signal Boxes	Asbestos	Presumed	1476	1478	LHS	Flash guards Switch boxes 505 CTR, 24GR, 505BT		3			
39273	ACTIVE	P	P102-P-EBMA	Road EBMA - PIC - Rayners Lane Jct to South Harrow	Signal Boxes	Asbestos	Presumed	1479		LHS	Flash guards Signal WV24		1			
39274	ACTIVE	P	P102-P-EBMA	Road EBMA - PIC - Rayners Lane Jct to South Harrow	Signal Boxes	Asbestos	Presumed	1717	1718	LHS	Flash guards Switch box BBT		3			
41031	ACTIVE	P	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	0		LHS	Flash guards Signal WV4		1			
41032	ACTIVE	P	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Cable Sheath	Asbestos	Sampled – Not Detected	0		LHS	Braided cable on J hanger No.2					
40024	ACTIVE	P	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	10		LHS	Flash guards Signal break box Notes from 2022 re-inspection: 2x SWH not 1x SWH		2			
41033	ACTIVE	P	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	34	36	LHS	Flash guards Switch boxes GR, ADTH, ADT, AHTH		5			
41034	ACTIVE	P	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	137	138	LHS	Flash guards Switch boxes AJT, AJTH		2			



Hazardous Material Asset Register - Summary



P102-P - PIC Line - South Harrow to Rayners Lane

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41113	ACTIVE	p	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	235		LHS	Flash guards Switch box		1			
41114	ACTIVE	p	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	357		LHS	Flash guards Fog repeater A506		1			
41115	ACTIVE	p	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Cement Cable Troughing & Debris	Asbestos	Known	496		LHS	Cable troughing, to bridge Cement troughing		2			
41116	ACTIVE	p	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	497		LHS	Flash guards Signal A506		1			
46243	ACTIVE	p	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Isolator Switches	Asbestos	Removed				Disused P-Way Building - Combination switch with braided cable to wall 4 Notes from 2022 re-inspection: Removed		1		N	N
46244	ACTIVE	p	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Bakerlite	Asbestos	Removed				Disused P-Way Building - Bakelite switches to wall 3 and 4 Notes from 2022 re-inspection: Removed		3		N	N
46242	ACTIVE	p	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Debris: Cement	Asbestos	Known				Disused P-Way Building - Cement debris to floor RHS of door <0.1m				N	N
40029	ACTIVE	p	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	554		LHS	Flash guards Junction box		1			
39502	ACTIVE	p	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	651		LHS	Flash guards Switch box		1			
41117	ACTIVE	p	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	674		LHS	Flash guards Switch box		1			
41118	ACTIVE	p	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	936		LHS	Flash guards Fog repeater MP240		1			
41119	ACTIVE	p	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Removed	952		LHS	Flash guards Signal break box Notes from 2022 re-inspection: Removed		1			
41120	ACTIVE	p	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	1055		LHS	Flash guards Signal rMP23/24, MP240		2			
41121	ACTIVE	p	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	1098		LHS	Flash guards Fog Repeater MP24		1			
41122	ACTIVE	p	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	1126		LHS	Flash guards Switch box		1			
41123	ACTIVE	p	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Ducts	Asbestos	Sampled – Not Detected	1176		LHS	bitumen ducts					
41124	ACTIVE	p	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Ducts	Asbestos	Sampled – Not Detected	1202		LHS	bitumen ducts					



Hazardous Material Asset Register - Summary



P102-P - PIC Line - South Harrow to Rayners Lane

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
41125	ACTIVE	P	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	1212		LHS	Flash guards Junction box		1			
41126	ACTIVE	P	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	1233		LHS	Flash guards Switch box		1			
41127	ACTIVE	P	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	1245		LHS	Flash guards Marshalling kiosk		1			
41128	ACTIVE	P	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	1260		LHS	Flash guards Signal RMP22/23, MP24		2			
41129	ACTIVE	P	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	1264		LHS	Flash guards Fog repeater MP23		1			
41130	ACTIVE	P	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	1401		LHS	Flash guards Signal RMP19/22, MP23		2			
41131	ACTIVE	P	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	1407		LHS	Flash guards Fog repeater MP22		1			
41132	ACTIVE	P	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Removed	1490		LHS	Flash guards Signal break box Notes from 2022 re-inspection: Removed		1			
39527	ACTIVE	P	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	1498		LHS	Flash guards Switch box		1			
41133	ACTIVE	P	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	1506		LHS	Flash guards Signal break box		1			
41134	ACTIVE	P	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	1535		LHS	Flash guards Signal break box		1			
39799	ACTIVE	P	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	1554		LHS	Flash guards Fog repeater MP19/1, Signal MP22 & Rail Gap Indicator		3			
41135	ACTIVE	P	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	1643		LHS	Flash guards Switch box		1			
39528	ACTIVE	P	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	1649		LHS	Flash guards Switch box		1			
41136	ACTIVE	P	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	1652		LHS	Flash guards Signal break box		1			
41137	ACTIVE	P	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	1661		LHS	Flash guards Switch box		1			
41138	ACTIVE	P	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Removed	1703		LHS	Flash guards Switch box Notes from 2022 re-inspection: Removed		1			
41139	ACTIVE	P	P102-P-WBMA	Road WBMA - PIC - South Harrow to Rayners Lane	Signal Boxes	Asbestos	Presumed	1714		LHS	Flash guards Signal MP19		1			



Hazardous Material Asset Register - Summary



P122-P - PIC Line - Holborn to Aldwych

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
37849	ACTIVE	P	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Cable Sheath	Asbestos	Known	0		RHS	Cloth. cable sheath, Route: JH2, 1x45, JH3, 2x30, 8x15		10			
37850	ACTIVE	P	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Cement Cable Troughing & Debris	Asbestos	Known	3		RHS	trough		3			
37851	ACTIVE	P	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Cable Sheath	Asbestos	Known	23		RHS	Cloth. Cable sheath, Route: Between JH2-JH4, 10-45, & track side equipment. Numerous amounts					
37852	ACTIVE	P	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Cable Sheath	Asbestos	Known	24			Cloth. Cable sheath, Route: 6x15, 1x10, JH2 OTX/LHS		7			
37853	ACTIVE	P	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Cable Sheath	Asbestos	Known	27			Cloth. Cable sheath, Route: 2x15, JH2 OTX/LHS		2			
37855	ACTIVE	P	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Cable Sheath	Asbestos	Known	27		RHS	Cloth. Cable sheath, Route: JH2, 1x45, JH3, 1x30, 3x15		5			
37854	ACTIVE	P	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Cable Sheath	Asbestos	Known	44		LHS	Cloth. Cable sheath, Route: Served cables on tunnel walls		5			
37856	ACTIVE	P	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Cable Sheath	Asbestos	Known	58		RHS	Cloth. Cable sheath, Route: Losing 2x15, JH3					
37857	ACTIVE	P	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Cable Sheath	Asbestos	Removed	71		LHS	Cloth. Cable sheath, Route: 2x10 laid on floor Notes from 2022 re-inspection: Removed		2			
37858	ACTIVE	P	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Cable Sheath	Asbestos	Known	76		RHS	Cloth. Cable sheath, entry: JH5 WHS small, route: 1x15, Exit: JH3 WHS small		1			
37862	ACTIVE	P	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Cable Sheath	Asbestos	Known	76	135	RHS	Cloth. Cable sheath, Route: Limited access due to height. Numerous amounts					
37859	ACTIVE	P	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Ducts	Asbestos	Strongly Presumed	104		RHS	cable duct lining		4			
37860	ACTIVE	P	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Ducts	Asbestos	Strongly Presumed	104		RHS	cable duct lining		5			
37865	ACTIVE	P	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Cable Sheath	Asbestos	Known	104	135	RHS	Cloth. Cable sheath, Entry: Wall, Route: 4x10		4			
37866	ACTIVE	P	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Cable Sheath	Asbestos	Known	135	186	RHS	Cloth. Cable sheath, on ceramic insulation, Route: 5-10 above JH1 on ceramic insulator		10			
37863	ACTIVE	P	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Cable Sheath	Asbestos	Known	135	166	LHS	Cloth. Cable sheath, Route: JH3, 1x15, 1x30, JH2 1x45		1			
37861	ACTIVE	P	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Cable Sheath	Asbestos	Known	135		LHS	Cloth. Cable sheath, route: 1x30, Exit: Tencore		1			
37864	ACTIVE	P	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Cable Sheath	Asbestos	Known	166		LHS	Cloth. Cable sheath, Route: JH3, 1x15, 1x30, JH2 1x45		3			



Hazardous Material Asset Register - Summary



P122-P - PIC Line - Holborn to Aldwych

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39769	ACTIVE	p	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Cable Sheath	Asbestos	Known	166		LHS	Cloth. Cable sheath, Route: Losing 1x15 JH3		1			
37867	ACTIVE	p	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Cable Sheath	Asbestos	Known	206		LHS	Cloth. Splice, Route: JH2 1x45		2			
54070	ACTIVE	p	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Signal Boxes	Asbestos	Presumed	231		RHS	Signal box					
37868	ACTIVE	p	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Cable Sheath	Asbestos	Known	328		RHS	Cloth. Cable sheath, on ceramic insulation. Route: 4x10 above JH1 on ceramic insulator		4			
54071	ACTIVE	p	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Signal Boxes	Asbestos	Presumed	342		RHS	Signal R1002					
37869	ACTIVE	p	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Cable Sheath	Asbestos	Known	342		RHS	Cloth. Cable sheath, Entry: Track side equipment, Route: 1x10, Exit: JH3		1			
37870	ACTIVE	p	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Cable Sheath	Asbestos	Known	408		LHS	Cloth. Cable sheath, route: Gaining 2x15 onto JH2		5			
39882	ACTIVE	p	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Cable Sheath	Asbestos	Known	440	445	RHS	Cloth. Cable sheath, Route: Between JH2-JH4 track side equipment, 100-45. numerous amounts					
54072	ACTIVE	p	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Signal Boxes	Asbestos	Presumed	440		RHS	Signal A1002					
39418	ACTIVE	p	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Cable Sheath	Asbestos	Known	445		RHS	Cloth. Cable sheath, Route: JH3, 5x15, 2x30, JH2, 1x45		8			
37871	ACTIVE	p	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Cable Sheath	Asbestos	Known	454		LHS	Cloth. Cable sheath,Route: JH2 1x45		2			
54073	ACTIVE	p	P122-P-SLLO	Road SLLO - PIC - Holborn to Aldwych	Other Electrical Boxes	Asbestos	Presumed	456		LHS	Trackside equipment box: Tencore box		1			

P123-P - PIC Line - Aldwych Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
39365	INACTIVE	p	P123-P-SLLO	Road SLLO - PIC - Aldwych Stn	Westinghouse Boxes	Asbestos	Presumed				Trackside equipment: Westinghouse small box					
54054	ACTIVE	p	P123-P-SLLO	Road SLLO - PIC - Aldwych Stn	Cable Sheath	Asbestos	Presumed				Braided cables to platform wall under nosing		2			
36321	ACTIVE	p	P123-P-SLLO	Road SLLO - PIC - Aldwych Stn	Westinghouse Boxes	Asbestos	Presumed				Trackside equipment: Westinghouse small box throughout Platform 1 - 4/261					
42725	ACTIVE	p	P123-P-SLLO	Road SLLO - PIC - Aldwych Stn	Pit Blocks	Asbestos	Strongly Presumed				Pit blocks strongly presumed Platform 1 - 4/261					