



Hazardous Material Asset Register - Summary



Run date: 19/08/2024

Line: Jubilee

Risk Assessment Status: Active, Inactive
Hazardous Material Status: All
Hazardous Material Type: All

B081-00 - Station Building - Stanmore Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2941	ACTIVE	J	B081-00-1/081	Lobby - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2524	ACTIVE	J	B081-00-1/081	Lobby - Station Building - Stanmore Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2942	ACTIVE	J	B081-00-1/186	Station Entrance (London Road A) - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1052	ACTIVE	J	B081-00-1/186	Station Entrance (London Road A) - Station Building - Stanmore Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2943	ACTIVE	J	B081-00-1/236	Passage - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1054	ACTIVE	J	B081-00-1/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Above - Supalux Tiles				YES	
2448	INACTIVE	J	B081-00-1/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Stanmore Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected								YES	
1053	ACTIVE	J	B081-00-1/236/FLR-01 80833757	Floor - 1 - Passage - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Beneath - Rubber Tiles possibly beneath modern Lino floor covering.					YES
2944	ACTIVE	J	B081-00-1/291	DSM Office - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1055	INACTIVE	J	B081-00-1/291/CLG-01	Ceiling: Suspended - 1 - DSM Office - Station Building - Stanmore Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected								YES	
2401	ACTIVE	J	B081-00-1/291/CLG-01	Ceiling: Suspended - 1 - DSM Office - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Above - Supalux Tiles				YES	
2945	ACTIVE	J	B081-00-1/316	Locker Room - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2280	ACTIVE	J	B081-00-1/316/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Above - Supalux Tiles				YES	
1056	ACTIVE	J	B081-00-1/316/FLR-01 80833730	Floor - 1 - Locker Room - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Beneath - Rubber Tiles possibly beneath modern Lino floor covering.					Yes



Hazardous Material Asset Register - Summary



B081-00 - Station Building - Stanmore Stn																
Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2946	ACTIVE	J	B081-00-1/317	Locker Room - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1058	ACTIVE	J	B081-00-1/317/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Above - Supalux Tiles				Yes	
1057	INACTIVE	J	B081-00-1/317/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Stanmore Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected								Yes	
2449	ACTIVE	J	B081-00-1/317/FLR-01 80833715	Floor - 1 - Locker Room - Station Building - Stanmore Stn Floor	Void	Asbestos	No Access: Presumed				Beneath - Rubber Tiles possibly beneath modern Lino floor covering.					YES
2947	ACTIVE	J	B081-00-1/411	Equipment Room - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2327	ACTIVE	J	B081-00-1/411	Equipment Room - Station Building - Stanmore Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2948	ACTIVE	J	B081-00-1/412	Store - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1060	ACTIVE	J	B081-00-1/412/CLG-01 80833692	Ceiling: Solid - 1 - Store - Station Building - Stanmore Stn Ceiling: Solid	Void	Asbestos	Surveyed – Not Detected				Solid plastered ceiling with fixed/ mounted modern services including ventilation ducting system.				Yes	
1059	INACTIVE	J	B081-00-1/412/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Stanmore Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected								Yes	
2949	ACTIVE	J	B081-00-1/416	Toilet: Unisex - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1061	ACTIVE	J	B081-00-1/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Stanmore Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above False Ceiling		1		yes	
2450	ACTIVE	J	B081-00-1/416/WAL-002	Wall: Internal - 2 - Toilet - Station Building - Stanmore Stn	LUL Heaters	Asbestos	Surveyed – Not Detected						1			
2950	ACTIVE	J	B081-00-1/451	Tenancy - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1062	ACTIVE	J	B081-00-1/451/FLR-01	Floor - 1 - Tenancy - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Beneath - Wooden Floor					YES
2951	ACTIVE	J	B081-00-1/452	Tenancy - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2931	INACTIVE	J	B081-00-1/452/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Stanmore Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									



Hazardous Material Asset Register - Summary



B081-00 - Station Building - Stanmore Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1064	INACTIVE	J	B081-00-1/452/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Stanmore Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1063	ACTIVE	J	B081-00-1/452/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Above - Supalux Tiles				yes	
2525	ACTIVE	J	B081-00-1/452/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Above - Supalux Tiles				yes	
2952	ACTIVE	J	B081-00-1/453	Tenancy - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2953	ACTIVE	J	B081-00-1/488	Lobby - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1065	ACTIVE	J	B081-00-1/488/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Above - Supalux				yes	
2451	INACTIVE	J	B081-00-1/488/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Stanmore Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected								yes	
2954	ACTIVE	J	B081-00-1/601	Stairs: Linear - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1066	ACTIVE	J	B081-00-1/601/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Stanmore Stn	Glazing Rope	Asbestos	Sampled – Not Detected				Stairs - Rope Seal Tested -Non Asbestos. Glass Roof					
2955	ACTIVE	J	B081-00-1/663	Switch Cupboard - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1067	INACTIVE	J	B081-00-1/663	Switch Cupboard - Station Building - Stanmore Stn		Asbestos	Presumed				This record is inactivated as the Attribute information is invalid. Record 20226 replaces this record. Sue Blumsom 23/06/2014					
20226	ACTIVE	J	B081-00-1/663	Switch Cupboard - Station Building - Stanmore Stn	Other Electrical Boxes	Asbestos	Presumed				Electrical box within locked high level cabinet.					
2956	ACTIVE	J	B081-00-1/802	Training Room - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2452	ACTIVE	J	B081-00-1/802/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Stanmore Stn	Gasket :Pipework	Asbestos	Surveyed – Not Detected				15m Visible Pipe		15		Yes	
1069	ACTIVE	J	B081-00-1/802/SNK-01	Sink - 1 - Office - Station Building - Stanmore Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink		1			
2957	ACTIVE	J	B081-00-1/951	Disused Room - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2402	ACTIVE	J	B081-00-1/951	Disused Room - Station Building - Stanmore Stn	No Access	Asbestos	No Access: Presumed				Room Not Surveyed. No access within location at time of HMT inspection. Keys not held with CSS.					



Hazardous Material Asset Register - Summary



B081-00 - Station Building - Stanmore Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2958	ACTIVE	J	B081-00-2/001	Booking Hall - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1070	ACTIVE	J	B081-00-2/001	Booking Hall - Station Building - Stanmore Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2959	ACTIVE	J	B081-00-2/011	Ticket Office - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1071	ACTIVE	J	B081-00-2/011/CLG-01	Ceiling: Solid - 1 - Ticket Office - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Above - Plasterboard				Yes	
1072	ACTIVE	J	B081-00-2/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Beneath - Rubber Tiles					YES
2960	ACTIVE	J	B081-00-2/021	POM - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1073	ACTIVE	J	B081-00-2/021/CLG-01	Ceiling: Solid - 1 - POM - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Above - Plasterboard				Yes	
1074	ACTIVE	J	B081-00-2/021/FLR-01	Floor - 1 - POM - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Beneath - Rubber Tiles					YES
2453	ACTIVE	J	B081-00-2/021/WAL-003	Wall: Internal - 3 - POM - Station Building - Stanmore Stn	LUL Heaters	Asbestos	Surveyed – Not Detected						1			
2961	ACTIVE	J	B081-00-2/031	Mess Room - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2454	ACTIVE	J	B081-00-2/031/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Above - Plasterboard				Yes	
1075	ACTIVE	J	B081-00-2/031/SNK-01	Sink - 1 - Mess Room - Station Building - Stanmore Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel below sink		1			
2962	ACTIVE	J	B081-00-2/036	Toilet: Unisex - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1076	ACTIVE	J	B081-00-2/036	Toilet: Unisex - Station Building - Stanmore Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2963	ACTIVE	J	B081-00-2/081	Lobby - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1077	ACTIVE	J	B081-00-2/081/FLR-01	Floor - 1 - Lobby - Station Building - Stanmore Stn	Void	Asbestos	No Access: Presumed				Beneath - Rubber Tiles					YES
2964	ACTIVE	J	B081-00-2/082	Lobby - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B081-00 - Station Building - Stanmore Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1078	ACTIVE	J	B081-00-2/082	Lobby - Station Building - Stanmore Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2965	ACTIVE	J	B081-00-2/201	Footpath - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1079	ACTIVE	J	B081-00-2/201	Footpath - Station Building - Stanmore Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2966	ACTIVE	J	B081-00-2/236	Passage - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2967	ACTIVE	J	B081-00-2/261	Platform 1 - Northbound Local - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45152	ACTIVE	J	B081-00-2/261	Platform 1 - Northbound Local - Station Building - Stanmore Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Track - Signalling Equipment				N	N
2526	ACTIVE	J	B081-00-2/261	Platform 1 - Northbound Local - Station Building - Stanmore Stn		Asbestos	Surveyed – Not Detected				NB Asbestos Containing Materials Trackside					
2968	ACTIVE	J	B081-00-2/262	Platform 2 - Southbound Local - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2403	ACTIVE	J	B081-00-2/262	Platform 2 - Southbound Local - Station Building - Stanmore Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2969	ACTIVE	J	B081-00-2/263	Platform 3 - Single Line Local - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1080	ACTIVE	J	B081-00-2/263	Platform 3 - Single Line Local - Station Building - Stanmore Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2970	ACTIVE	J	B081-00-2/291	Station Supervisor Office - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2455	INACTIVE	J	B081-00-2/291/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Stanmore Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected								Yes	
1081	ACTIVE	J	B081-00-2/291/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Stanmore Stn	Void	Asbestos	Surveyed – Not Detected				Plaster Board above Supalux				Yes	
2971	ACTIVE	J	B081-00-2/311	Office - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1083	ACTIVE	J	B081-00-2/311/CLG-01	Ceiling: Solid - 1 - Office - Station Building - Stanmore Stn		Anthrax	Surveyed – Not Detected				No Anthrax Detected					
1082	ACTIVE	J	B081-00-2/311/WAL-002	Wall: Internal - 2 - Office - Station Building - Stanmore Stn		Anthrax	Surveyed – Not Detected				No Anthrax Detected					



Hazardous Material Asset Register - Summary



B081-00 - Station Building - Stanmore Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2972	ACTIVE	J	B081-00-2/331	Mess Room - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2281	ACTIVE	J	B081-00-2/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Stanmore Stn		Anthrax	Surveyed – Not Detected				No Anthrax Detected					
1085	ACTIVE	J	B081-00-2/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Stanmore Stn	Void	Asbestos	Surveyed – Not Detected				Above - Concrete, Plaster, Metal Pipes				Yes	
1084	INACTIVE	J	B081-00-2/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Stanmore Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2456	ACTIVE	J	B081-00-2/331/WAL-004	Wall: Internal - 4 - Mess Room - Station Building - Stanmore Stn	LUL Heaters	Asbestos	Surveyed – Not Detected						1			
2973	ACTIVE	J	B081-00-2/332	Store - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45153	ACTIVE	J	B081-00-2/332	Store - Station Building - Stanmore Stn	Cement Cowlings/Flues	Asbestos	Known				Cement Cowl - Amosite & Chrysotile - Externals (Platform 2 side), To wall, from extractor fan of centre of room 2/332		1	R660751	N	N
2457	ACTIVE	J	B081-00-2/332/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Stanmore Stn	Void	Asbestos	Surveyed – Not Detected				Concrete - above False Ceiling				Yes	
2404	INACTIVE	J	B081-00-2/332/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Stanmore Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1086	ACTIVE	J	B081-00-2/332/WAL-002	Wall: Internal - 2 - Store - Station Building - Stanmore Stn	LUL Heaters	Asbestos	Surveyed – Not Detected						1			
1087	ACTIVE	J	B081-00-2/332/WAL-004	Wall: Internal - 4 - Store - Station Building - Stanmore Stn		Anthrax	Surveyed – Not Detected				No Anthrax Detected					
2974	ACTIVE	J	B081-00-2/333	Tea Point - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2480	ACTIVE	J	B081-00-2/333	Tea Point - Station Building - Stanmore Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2975	ACTIVE	J	B081-00-2/371	Mess Room - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1089	ACTIVE	J	B081-00-2/371/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Stanmore Stn	Void	Asbestos	Surveyed – Not Detected				Plaster Board Fascias above Window; Supalux				Yes	
1088	INACTIVE	J	B081-00-2/371/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Stanmore Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected								Yes	



Hazardous Material Asset Register - Summary



B081-00 - Station Building - Stanmore Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2893	ACTIVE	J	B081-00-2/371/WAL-002	Wall: Internal - 2 - Mess Room - Station Building - Stanmore Stn	LUL Heaters	Asbestos	Surveyed – Not Detected						1			
2976	ACTIVE	J	B081-00-2/372	Mess Room - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1091	ACTIVE	J	B081-00-2/372/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Stanmore Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard - above False Ceiling				Yes	
2458	INACTIVE	J	B081-00-2/372/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Stanmore Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1090	ACTIVE	J	B081-00-2/372/WAL-001	Wall: Internal - 1 - Mess Room - Station Building - Stanmore Stn	LUL Heaters	Asbestos	Surveyed – Not Detected						1			
2977	ACTIVE	J	B081-00-2/412	Store - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2527	ACTIVE	J	B081-00-2/412	Store - Station Building - Stanmore Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2978	ACTIVE	J	B081-00-2/416	Toilet: Unisex - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1093	ACTIVE	J	B081-00-2/416	Toilet: Unisex - Station Building - Stanmore Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2979	ACTIVE	J	B081-00-2/417	Toilet: Unisex - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1094	ACTIVE	J	B081-00-2/417	Toilet: Unisex - Station Building - Stanmore Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2980	ACTIVE	J	B081-00-2/426	Toilet: Male - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2908	ACTIVE	J	B081-00-2/426/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Stanmore Stn	Void	Asbestos	Surveyed – Not Detected				Plastic Sheeting above Metal Tiles		1		Yes	
2981	ACTIVE	J	B081-00-2/427	Toilet: Female - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2459	ACTIVE	J	B081-00-2/427/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Stanmore Stn	Void	Asbestos	Surveyed – Not Detected				Plastic Sheeting above Metal Tiles		1		Yes	
2982	ACTIVE	J	B081-00-2/428	Toilet: Disabled - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1095	ACTIVE	J	B081-00-2/428/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Stanmore Stn	Void	Asbestos	Surveyed – Not Detected				Concrete; Fibreglass Lagging above False Ceiling		1		Yes	



Hazardous Material Asset Register - Summary



B081-00 - Station Building - Stanmore Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2983	ACTIVE	J	B081-00-2/436	Waiting Room - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1096	ACTIVE	J	B081-00-2/436/ WAL-003	Wall: Internal - 3 - Waiting Room - Station Building - Stanmore Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				5 x LUL Heater - Foam Insulation		5			
2984	ACTIVE	J	B081-00-2/437	Waiting Room - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1097	ACTIVE	J	B081-00-2/437	Waiting Room - Station Building - Stanmore Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2985	ACTIVE	J	B081-00-2/551	Yard - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1098	ACTIVE	J	B081-00-2/551	Yard - Station Building - Stanmore Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2986	ACTIVE	J	B081-00-2/661	Switch Room - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1099	ACTIVE	J	B081-00-2/661/ WAL-001 80833828	Wall: Internal - 1 - Switch Room - Station Building - Stanmore Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				5 x Isolater Switches - 1 x 30 amps, & 3 x 60 amps, & 1 x 100 amps.		5			
1100	ACTIVE	J	B081-00-2/661/ WAL-002 80833829	Wall: Internal - 2 - Switch Room - Station Building - Stanmore Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				1 x Isolater Switches - 1 x 60 amps.		1			
2460	ACTIVE	J	B081-00-2/661/ WAL-003 80833830	Wall: Internal - 3 - Switch Room - Station Building - Stanmore Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				8 x Isolater Switches - 7 x 60 amps, & 1 x 200 amps.		8			
1101	ACTIVE	J	B081-00-2/661/ WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Stanmore Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1 x Transformer Box		1			
2987	ACTIVE	J	B081-00-2/662	Switch Room - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
20224	ACTIVE	J	B081-00-2/662/ WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Stanmore Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				2x Tencore Boxes		2			
1102	ACTIVE	J	B081-00-2/662/ WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Stanmore Stn	Isolator Switches	Asbestos	Strongly Presumed				1no Switch Boxes - Wall 3 Insulation within (1x30amps)		1			
1103	ACTIVE	J	B081-00-2/662/ WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Stanmore Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es)		3			



Hazardous Material Asset Register - Summary



B081-00 - Station Building - Stanmore Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2988	ACTIVE	J	B081-00-2/667	Switch Room - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1106	ACTIVE	J	B081-00-2/667	Switch Room - Station Building - Stanmore Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2989	ACTIVE	J	B081-00-2/668	Switch Room - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1107	ACTIVE	J	B081-00-2/668	Switch Room - Station Building - Stanmore Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2990	ACTIVE	J	B081-00-2/669	Switch Room - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1108	ACTIVE	J	B081-00-2/669	Switch Room - Station Building - Stanmore Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2991	ACTIVE	J	B081-00-2/731	CER - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1109	ACTIVE	J	B081-00-2/731	CER - Station Building - Stanmore Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2992	ACTIVE	J	B081-00-2/746	SCR - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1110	ACTIVE	J	B081-00-2/746	SCR - Station Building - Stanmore Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2993	INACTIVE	J	B081-00-2/786	Service Area - Station Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
1111	ACTIVE	J	B081-00-2/786	Service Area - Station Building - Stanmore Stn	No Access	Asbestos	Room: Surveyed – No Known Asbestos				Room surveyed - No asbestos visible					

B083-00 - Station Building - Canons Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3010	ACTIVE	J	B083-00-0/196	Footpath - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2283	ACTIVE	J	B083-00-0/196	Footpath - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access					



Hazardous Material Asset Register - Summary



B083-00 - Station Building - Canons Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3011	ACTIVE	J	B083-00-1/001	Booking Hall - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44445	ACTIVE	J	B083-00-1/001	Booking Hall - Station Building - Canons Park Stn	Glazing Rope	Asbestos	Presumed				Glazing Rope under glazing bars on dome					
44444	ACTIVE	J	B083-00-1/001	Booking Hall - Station Building - Canons Park Stn	Glazing Rope	Asbestos	Presumed				Glazing panels within roof of staircases					
2932	ACTIVE	J	B083-00-1/001	Booking Hall - Station Building - Canons Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2462	ACTIVE	J	B083-00-1/001/ GTE-01	Gate: Collapsible - 1 - Booking Hall - Station Building - Canons Park Stn	Lead/Leading	Lead Paint/Lead	Known				Beam above Entrance Gate - Black Gloss ***Potentially removed by SMEP - Surfaces need to be checked first opportunity***					
2528	ACTIVE	J	B083-00-1/001/ GTE-02	Gate: Collapsible - 2 - Booking Hall - Station Building - Canons Park Stn	Lead/Leading	Lead Paint/Lead	Known				Beam above Entrance Gate - Black Gloss ***Potentially removed by SMEP - Surfaces need to be checked first opportunity***					
3012	ACTIVE	J	B083-00-1/011	Ticket Office - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1114	INACTIVE	J	B083-00-1/011/ CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Canons Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1115	ACTIVE	J	B083-00-1/011/ CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Canons Park Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles		1		Yes	
1113	ACTIVE	J	B083-00-1/011/ FLR-01	Floor - 1 - Ticket Office - Station Building - Canons Park Stn	Void	Asbestos	No Access: Presumed				Beneath - Computer Flooring					YES
3013	ACTIVE	J	B083-00-1/021	POM - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1116	ACTIVE	J	B083-00-1/021/ FLR-01	Floor - 1 - POM - Station Building - Canons Park Stn	Void	Asbestos	No Access: Presumed				Beneath - Computer Flooring					YES
3014	ACTIVE	J	B083-00-1/031	Mess Room - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2463	ACTIVE	J	B083-00-1/031/ CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Canons Park Stn	Void	Asbestos	Surveyed – Not Detected				Concrete/supalux panel above window		1		Yes	
2406	INACTIVE	J	B083-00-1/031/ CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Canons Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected								yes	



Hazardous Material Asset Register - Summary



B083-00 - Station Building - Canons Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1117	ACTIVE	J	B083-00-1/031/WDW-01	Window - 1 - Mess Room - Station Building - Canons Park Stn	Lead/Leading	Lead Paint/Lead	Known				Window frame - Cream gloss Thickness : 0.25mm Analysis : 2.9% ***Potentially removed by SMEP - Surfaces need to be checked first opportunity***					
3015	ACTIVE	J	B083-00-1/036	Toilet: Unisex - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1118	ACTIVE	J	B083-00-1/036	Toilet: Unisex - Station Building - Canons Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3016	ACTIVE	J	B083-00-1/081	Lobby - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1119	ACTIVE	J	B083-00-1/081/FLR-01	Floor - 1 -Lobby - Station Building - Canons Park Stn	Void	Asbestos	No Access: Presumed				Beneath - Computer Flooring					YES
3017	ACTIVE	J	B083-00-1/082	Store - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1120	ACTIVE	J	B083-00-1/082	Store - Station Building - Canons Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3018	ACTIVE	J	B083-00-1/083	Lobby - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2464	ACTIVE	J	B083-00-1/083/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Canons Park Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Metal Tiles				Yes	
3019	ACTIVE	J	B083-00-1/084	Lobby - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1121	ACTIVE	J	B083-00-1/084	Lobby - Station Building - Canons Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3020	ACTIVE	J	B083-00-1/085	Lobby - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1122	ACTIVE	J	B083-00-1/085	Lobby - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
3021	ACTIVE	J	B083-00-1/236	Passage - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1008	ACTIVE	J	B083-00-1/236	Passage - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
3022	ACTIVE	J	B083-00-1/411	Store - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B083-00 - Station Building - Canons Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1009	ACTIVE	J	B083-00-1/411	Store - Station Building - Canons Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3023	ACTIVE	J	B083-00-1/412	Store - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1010	ACTIVE	J	B083-00-1/412	Store - Station Building - Canons Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3024	ACTIVE	J	B083-00-1/413	Store - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1011	ACTIVE	J	B083-00-1/413	Store - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
3025	ACTIVE	J	B083-00-1/414	Store - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2438	ACTIVE	J	B083-00-1/414	Store - Station Building - Canons Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3026	ACTIVE	J	B083-00-1/415	Store - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1012	ACTIVE	J	B083-00-1/415	Store - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
3027	ACTIVE	J	B083-00-1/416	Lobby - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1013	ACTIVE	J	B083-00-1/416	Lobby - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
3028	ACTIVE	J	B083-00-1/417	Toilet - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1014	ACTIVE	J	B083-00-1/417	Toilet - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
3029	ACTIVE	J	B083-00-1/418	Lobby - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2909	INACTIVE	J	B083-00-1/418	Lobby - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Room Not Surveyed - No access					
3030	ACTIVE	J	B083-00-1/426	Toilet: Male - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1015	ACTIVE	J	B083-00-1/426/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Canons Park Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Metal Tiles					



Hazardous Material Asset Register - Summary



B083-00 - Station Building - Canons Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1016	ACTIVE	J	B083-00-1/426/WCP-01	WC Pan - 1 - Toilet - Station Building - Canons Park Stn	Pipe Lagging	Asbestos	Surveyed – Not Detected				Tank pipe work - Fibreglass Lagging					
3031	ACTIVE	J	B083-00-1/427	Toilet: Female - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2439	ACTIVE	J	B083-00-1/427/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Canons Park Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Metal Tiles		1		Yes	
1017	ACTIVE	J	B083-00-1/427/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Canons Park Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Metal Tiles		1		Yes	
3032	ACTIVE	J	B083-00-1/428	Toilet: Disabled - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3033	ACTIVE	J	B083-00-1/451	Tenancy - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2891	ACTIVE	J	B083-00-1/451/WAL-004	Wall: Internal - 4 - Tenancy - Station Building - Canons Park Stn	Other Boarding	Asbestos	Surveyed – Not Detected				External Boarding panel below side window- NAD, External Boarding panel below front window - NAD, Internal Boarding panel below front window behind electric box - NAD		1			
3034	ACTIVE	J	B083-00-1/452	Tenancy - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1018	ACTIVE	J	B083-00-1/452	Tenancy - Station Building - Canons Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3035	ACTIVE	J	B083-00-1/453	Disused Room - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1112	INACTIVE	J	B083-00-1/453	Disused Room - Station Building - Canons Park Stn	Boarding: AIB	Asbestos	Removed				5m² Infill panel above roller shutter on side elevation					
2397	ACTIVE	J	B083-00-1/453	Disused Room - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
2481	ACTIVE	J	B083-00-1/453	Disused Room - Station Building - Canons Park Stn	Boarding: Cement	Asbestos	Strongly Presumed				6m² Concrete panels - High level on front elevation					
3036	ACTIVE	J	B083-00-1/661	Switch Room - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1019	ACTIVE	J	B083-00-1/661/WAL-001 80805416	Wall: Internal - 1 - Switch Room - Station Building - Canons Park Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				4 x Switch Fuse Boxes 2x30, 1x60, 1x200amps - Asbestos Components Within		4			



Hazardous Material Asset Register - Summary



B083-00 - Station Building - Canons Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1020	ACTIVE	J	B083-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Canons Park Stn	Cable Ducts: Bitumen	Asbestos	Strongly Presumed				Cable Duct		1			
2781	ACTIVE	J	B083-00-1/661/WAL-002 80805417	Wall: Internal - 2 - Switch Room - Station Building - Canons Park Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				1 x Switch Fuse Boxes 1x200amp - Asbestos Components Within		1			
1021	ACTIVE	J	B083-00-1/661/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Canons Park Stn	LUL Heaters	Asbestos	Strongly Presumed				LU Heater		1			
2440	ACTIVE	J	B083-00-1/661/WAL-006	Wall: Internal - 6 - Switch Room - Station Building - Canons Park Stn	Lead/Leading	Lead Paint/Lead	Presumed				Canopy Beam - Cream gloss Thickness : 0.45mm Analysis : 7.49% ***Potentially removed by SMEP - Cream beam not found during Survey					
3037	ACTIVE	J	B083-00-1/662	Switch Room - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1022	ACTIVE	J	B083-00-1/662/WAL-001 80805425	Wall: Internal - 1 - Switch Room - Station Building - Canons Park Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				3 x Switch Fuse Boxes - Asbestos Components Within		3			
2441	ACTIVE	J	B083-00-1/662/WAL-002 80805426	Wall: Internal - 2 - Switch Room - Station Building - Canons Park Stn Wall: Internal	Other Electrical Boxes	Asbestos	Strongly Presumed				Transformer Box(es) - Asbestos Components Within		1			
1023	ACTIVE	J	B083-00-1/662/WAL-002 80805426	Wall: Internal - 2 - Switch Room - Station Building - Canons Park Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				4 x Switch Fuse Boxes 60amp - Asbestos Components Within		4			
1024	ACTIVE	J	B083-00-1/662/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Canons Park Stn	Isolator Switches	Asbestos	Strongly Presumed				1x Switch fuse boxes 1 x 30amps		1			
2325	ACTIVE	J	B083-00-1/662/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Canons Park Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Transformer Box(es)		3			
3038	ACTIVE	J	B083-00-1/746	SCR - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2398	ACTIVE	J	B083-00-1/746/CLG-01	Ceiling: Solid - 1 - SCR - Station Building - Canons Park Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard				Yes	
3039	ACTIVE	J	B083-00-1/801	Office - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1025	ACTIVE	J	B083-00-1/801	Office - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
3040	ACTIVE	J	B083-00-1/802	Office - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B083-00 - Station Building - Canons Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1026	ACTIVE	J	B083-00-1/802	Office - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
3041	ACTIVE	J	B083-00-1/803	Office - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1027	ACTIVE	J	B083-00-1/803	Office - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
3042	ACTIVE	J	B083-00-1/804	Office - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2884	ACTIVE	J	B083-00-1/804	Office - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
3043	ACTIVE	J	B083-00-A/047	Kitchen - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1028	ACTIVE	J	B083-00-A/047	Kitchen - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
3044	ACTIVE	J	B083-00-A/048	Kitchen - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1029	ACTIVE	J	B083-00-A/048	Kitchen - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
3045	ACTIVE	J	B083-00-A/050	Store - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1030	ACTIVE	J	B083-00-A/050	Store - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
3046	ACTIVE	J	B083-00-A/261	Platform 1 - Northbound Local - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45155	ACTIVE	J	B083-00-A/261	Platform 1 - Northbound Local - Station Building - Canons Park Stn	Glazing Rope	Asbestos	Strongly Presumed				Glazing rope under glazing bars				N	N
2442	ACTIVE	J	B083-00-A/261	Platform 1 - Northbound Local - Station Building - Canons Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3047	ACTIVE	J	B083-00-A/262	Platform 2 - Southbound Local - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1031	ACTIVE	J	B083-00-A/262	Platform 2 - Southbound Local - Station Building - Canons Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



Hazardous Material Asset Register - Summary



B083-00 - Station Building - Canons Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
45156	ACTIVE	J	B083-00-A/262	Platform 2 - Southbound Local - Station Building - Canons Park Stn	Glazing Rope	Asbestos	Strongly Presumed				Glazing rope under glazing bars				N	N
1032	ACTIVE	J	B083-00-A/262/CLG-01	Ceiling: Suspended - 1 - Platform 2 - Station Building - Canons Park Stn	Lead/Leading	Lead Paint/Lead	Known				Canopy Support - Cream Gloss Thickness : 0.95mm Analysis : 4.7% ***Potentially removed by SMEP - Surfaces need to be checked first opportunity***					
1033	ACTIVE	J	B083-00-A/262/CLG-01	Ceiling: Suspended - 1 - Platform 2 - Station Building - Canons Park Stn	Lead/Leading	Lead Paint/Lead	Presumed				Canopy Support - Black Gloss Thickness : 0.79mm Analysis : 4.8% ***Potentially removed by SMEP - Black Gloss not found assumed over painted or removed now covered with cream paint					
2443	ACTIVE	J	B083-00-A/262/WAL-004	Wall: Internal - 4 - Platform 2 - Station Building - Canons Park Stn	Lead/Leading	Lead Paint/Lead	Known				Advertising board - White emulsion Thickness : 0.48mm Analysis : 3.4% ***Potentially removed by SMEP - Surfaces need to be checked first opportunity***					
3048	ACTIVE	J	B083-00-A/281	Station Supervisor Office - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2326	ACTIVE	J	B083-00-A/281	Station Supervisor Office - Station Building - Canons Park Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				White foam backing		1			
2279	ACTIVE	J	B083-00-A/281/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Canons Park Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Metal Tiles		1		Yes	
1034	ACTIVE	J	B083-00-A/281/WDW-01	Window - 1 - Station Supervisor Office - Station Building - Canons Park Stn	Lead/Leading	Lead Paint/Lead	Known				Window Frame - White Matt Thickness : 0.15mmAnalysis : 4.0% ***Potentially removed by SMEP - Surfaces need to be checked first opportunity***					
3049	ACTIVE	J	B083-00-A/341	Mess Room - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1036	ACTIVE	J	B083-00-A/341/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Canons Park Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Metal Tiles		1		Yes	
1035	ACTIVE	J	B083-00-A/341/FLR-01	Floor - 1 - Mess Room - Station Building - Canons Park Stn	Vinyl tiles	Asbestos	Removed				Previously sampled NADIS					
1037	ACTIVE	J	B083-00-A/341/WDW-01	Window - 1 - Mess Room - Station Building - Canons Park Stn	Lead/Leading	Lead Paint/Lead	Known				Window Frame - White Matt Thickness : 0.15mmAnalysis : 4.0% ***Potentially removed by SMEP - Surfaces need to be checked first opportunity***					
3050	ACTIVE	J	B083-00-A/411	Store - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2444	ACTIVE	J	B083-00-A/411	Store - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					



Hazardous Material Asset Register - Summary



B083-00 - Station Building - Canons Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3051	ACTIVE	J	B083-00-A/412	Store - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1038	ACTIVE	J	B083-00-A/412	Store - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
3052	ACTIVE	J	B083-00-A/413	Store - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2399	ACTIVE	J	B083-00-A/413	Store - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
3053	ACTIVE	J	B083-00-A/414	Store - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1039	ACTIVE	J	B083-00-A/414	Store - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
3054	ACTIVE	J	B083-00-A/415	Store - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1040	ACTIVE	J	B083-00-A/415	Store - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
3055	ACTIVE	J	B083-00-A/416	Shower Room - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1041	ACTIVE	J	B083-00-A/416	Shower Room - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
3056	ACTIVE	J	B083-00-A/417	Toilet - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1042	ACTIVE	J	B083-00-A/417	Toilet - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
3057	ACTIVE	J	B083-00-A/418	Toilet - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2445	ACTIVE	J	B083-00-A/418	Toilet - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
3058	ACTIVE	J	B083-00-A/436	Waiting Room - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1044	ACTIVE	J	B083-00-A/436/WAL-002	Wall: Internal - 2 - Waiting Room - Station Building - Canons Park Stn	Lead/Leading	Lead Paint/Lead	Known				Window Frame - White Matt Thickness : 0.15mmAnalysis : 4.0% ***Potentially removed by SMEP - Surfaces need to be checked first oppurtunity***					



Hazardous Material Asset Register - Summary



B083-00 - Station Building - Canons Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2446	ACTIVE	J	B083-00-A/436/WAL-003 80805465	Wall: Internal - 3 - Waiting Room - Station Building - Canons Park Stn Wall: Internal	LUL Heaters	Asbestos	Strongly Presumed				LUL Heater - Asbestos Materials Within		1			
1043	ACTIVE	J	B083-00-A/436/WAL-004	Wall: Internal - 4 - Waiting Room - Station Building - Canons Park Stn	Lead/Leading	Lead Paint/Lead	Known				Window Frame - White Matt Thickness : 0.15mmAnalysis : 4.0% ***Potentially removed by SMEP - Surfaces need to be checked first opportunity***					
3059	ACTIVE	J	B083-00-A/437	Waiting Room - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1046	ACTIVE	J	B083-00-A/437	Waiting Room - Station Building - Canons Park Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				White foam backing		1			
1045	ACTIVE	J	B083-00-A/437/CLG-01	Ceiling: Suspended - 1 - Waiting Room - Station Building - Canons Park Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Metal Tiles		1		Yes	
3060	ACTIVE	J	B083-00-A/576	Stairs: Linear - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2400	ACTIVE	J	B083-00-A/576	Stairs: Linear - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
3061	ACTIVE	J	B083-00-A/577	Stairs: Linear - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1047	ACTIVE	J	B083-00-A/577	Stairs: Linear - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
3062	ACTIVE	J	B083-00-A/601	Stairs: Linear - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2523	ACTIVE	J	B083-00-A/601	Stairs: Linear - Station Building - Canons Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
45157	ACTIVE	J	B083-00-A/601	Stairs: Linear - Station Building - Canons Park Stn	Glazing Rope	Asbestos	Strongly Presumed				Glazing rope on canopy				N	N
20242	ACTIVE	J	B083-00-A/601/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Canons Park Stn	Lead/Leading	Lead Paint/Lead	Presumed				The lead paint within this station was due to be removed by SMEP. No confirmation has been provided so this need to be tested as soon as possible.					
3063	ACTIVE	J	B083-00-A/602	Stairs: Linear - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45158	ACTIVE	J	B083-00-A/602	Stairs: Linear - Station Building - Canons Park Stn	Glazing Rope	Asbestos	Strongly Presumed				Glazing rope on canopy				N	N
1048	ACTIVE	J	B083-00-A/602	Stairs: Linear - Station Building - Canons Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



Hazardous Material Asset Register - Summary



B083-00 - Station Building - Canons Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2892	ACTIVE	J	B083-00-A/602/CLG-01	Ceiling: Solid - 1 - Stairs - Station Building - Canons Park Stn	Lead/Leading	Lead Paint/Lead	Known				Ceiling Beam - Cream Gloss Thickness : 0.15 Analysis : 8.1% The lead paint within this station was due to be removed by SMEP. No confirmation has been provided so this need to be tested as soon as possible.					
3064	ACTIVE	J	B083-00-A/662	Switch Cupboard - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Surveyed – Asbestos Known									
2447	ACTIVE	J	B083-00-A/662/FLR-01 80805491	Floor - 1 - Switch Cupboard - Station Building - Canons Park Stn Floor	Other Electrical Boxes	Asbestos	Presumed				Transformer box - Asbestos Components Within					
3065	ACTIVE	J	B083-00-A/801	Disused Room - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1049	ACTIVE	J	B083-00-A/801	Disused Room - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
3066	ACTIVE	J	B083-00-A/802	Disused Room - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1050	ACTIVE	J	B083-00-A/802	Disused Room - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
3067	ACTIVE	J	B083-00-A/803	Disused Room - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2791	ACTIVE	J	B083-00-A/803	Disused Room - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
3068	ACTIVE	J	B083-00-A/901	Disused Room - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1051	ACTIVE	J	B083-00-A/901	Disused Room - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
3069	ACTIVE	J	B083-00-A/902	Disused Room - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2465	ACTIVE	J	B083-00-A/902	Disused Room - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					
3070	ACTIVE	J	B083-00-A/903	Disused Room - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1123	ACTIVE	J	B083-00-A/903	Disused Room - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					



Hazardous Material Asset Register - Summary



B083-00 - Station Building - Canons Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3071	ACTIVE	J	B083-00-A/904	Disused Room - Station Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1124	ACTIVE	J	B083-00-A/904	Disused Room - Station Building - Canons Park Stn	No Access	Asbestos	No Access: Presumed				Not surveyed - No access (LU properties have rented as private dwellings)					

B085-00 - Station Building - Queensbury Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3083	ACTIVE	J	B085-00-1/001	Booking Hall - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2407	ACTIVE	J	B085-00-1/001	Booking Hall - Station Building - Queensbury Stn	Pipe Lagging	Asbestos	Surveyed – Not Detected				Fibreglass					
2466	ACTIVE	J	B085-00-1/001	Booking Hall - Station Building - Queensbury Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux facia above ticket office					
1128	ACTIVE	J	B085-00-1/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Queensbury Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Concrete, Supalux Facia above Ticket Office					
3084	ACTIVE	J	B085-00-1/011	Ticket Office - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1129	ACTIVE	J	B085-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Queensbury Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above False Ceiling		1		Yes	
2529	ACTIVE	J	B085-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Queensbury Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
3085	ACTIVE	J	B085-00-1/021	POM - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1130	ACTIVE	J	B085-00-1/021	POM - Station Building - Queensbury Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3086	ACTIVE	J	B085-00-1/031	Mess Room - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1131	ACTIVE	J	B085-00-1/031/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Queensbury Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Concrete & Supalux					
3087	ACTIVE	J	B085-00-1/036	Toilet: Unisex - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B085-00 - Station Building - Queensbury Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2467	ACTIVE	J	B085-00-1/036/WHB-01	Wash Hand Basin - 1 - Toilet - Station Building - Queensbury Stn		Asbestos	Surveyed – Not Detected				Acoustic panel by sink - Non asbestos		1			
3088	ACTIVE	J	B085-00-1/081	Lobby - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1132	ACTIVE	J	B085-00-1/081	Lobby - Station Building - Queensbury Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3089	ACTIVE	J	B085-00-1/083	Lobby - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1133	ACTIVE	J	B085-00-1/083/CLG-01 80812209	Ceiling: Solid - 1 - Lobby - Station Building - Queensbury Stn Ceiling: Solid	Void	Asbestos	No Access: Presumed				Above - Plasterboard				Yes	
3090	ACTIVE	J	B085-00-1/084	Lobby - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2408	ACTIVE	J	B085-00-1/084	Lobby - Station Building - Queensbury Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3091	ACTIVE	J	B085-00-1/201	Passage - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1134	ACTIVE	J	B085-00-1/201	Passage - Station Building - Queensbury Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3092	ACTIVE	J	B085-00-1/202	Passage - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1135	ACTIVE	J	B085-00-1/202	Passage - Station Building - Queensbury Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3093	ACTIVE	J	B085-00-1/281	Station Supervisor Office - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2468	ACTIVE	J	B085-00-1/281/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Queensbury Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux				Yes	
1136	ACTIVE	J	B085-00-1/281/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Queensbury Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected								yes	
3094	ACTIVE	J	B085-00-1/406	Store - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1137	ACTIVE	J	B085-00-1/406	Store - Station Building - Queensbury Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



Hazardous Material Asset Register - Summary



B085-00 - Station Building - Queensbury Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3095	ACTIVE	J	B085-00-1/426	Toilet: Male - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1138	ACTIVE	J	B085-00-1/426/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Queensbury Stn	No Access	Asbestos	No Access: Presumed				Above - Plasterboard					
3096	ACTIVE	J	B085-00-1/427	Toilet: Female - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1139	ACTIVE	J	B085-00-1/427/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Queensbury Stn	No Access	Asbestos	No Access: Presumed				Above - Plasterboard					
3097	ACTIVE	J	B085-00-1/428	Toilet: Disabled - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2933	ACTIVE	J	B085-00-1/428/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Queensbury Stn	No Access	Asbestos	No Access: Presumed				Above - Plasterboard					
3098	ACTIVE	J	B085-00-1/451	Tenancy - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1140	ACTIVE	J	B085-00-1/451	Tenancy - Station Building - Queensbury Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Tenancy. This ISR is found on Places for London.					
3099	ACTIVE	J	B085-00-1/452	Tenancy - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2469	ACTIVE	J	B085-00-1/452	Tenancy - Station Building - Queensbury Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Tenancy. This ISR is found on Places for London.					
3100	ACTIVE	J	B085-00-1/661	Switch Room - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1143	ACTIVE	J	B085-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Queensbury Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1 x Transformer Box		1			
1142	ACTIVE	J	B085-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Queensbury Stn	Cable Duct: Other	Asbestos	Presumed				3 x Cable Ducts Filled in 2020 re-inspection- The cable ducts are not visible beneath cement filling above therefore the material could not be assessed.		3			
1141	ACTIVE	J	B085-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Queensbury Stn	Isolator Switches	Asbestos	Strongly Presumed				1 Iron clad Isolators x 60amps		1			
1144	ACTIVE	J	B085-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Queensbury Stn	Cable Duct: Other	Asbestos	Surveyed – Not Detected				6 x Cable Ducts - Ceramic					



Hazardous Material Asset Register - Summary



B085-00 - Station Building - Queensbury Stn																
Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2470	ACTIVE	J	B085-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Queensbury Stn	Isolator Switches	Asbestos	Strongly Presumed				9 Iron Clad Isolator 7x60amps, 1x100amps, 1x200amps		9			
3101	ACTIVE	J	B085-00-1/662	Switch Room - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1146	ACTIVE	J	B085-00-1/662/FLR-01	Floor - 1 - Switch Room - Station Building - Queensbury Stn	Void	Asbestos	No Access: Presumed				Beneath - Hatch / Manhole					YES
1145	ACTIVE	J	B085-00-1/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Queensbury Stn	Cable Duct: Other	Asbestos	No Access: Presumed				Cable Ducts filled in		4			
2782	ACTIVE	J	B085-00-1/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Queensbury Stn	Isolator Switches	Asbestos	Strongly Presumed				5 Iron clad isolators 4x60amps, 1x200amps		5			
2471	ACTIVE	J	B085-00-1/662/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Queensbury Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 30amp		1			
2911	ACTIVE	J	B085-00-1/662/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Queensbury Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				3 x Transformer Boxes		1			
3102	ACTIVE	J	B085-00-1/746	SCR - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1148	ACTIVE	J	B085-00-1/746	SCR - Station Building - Queensbury Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3103	ACTIVE	J	B085-00-2/406	Store - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1149	ACTIVE	J	B085-00-2/406	Store - Station Building - Queensbury Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3104	ACTIVE	J	B085-00-2/661	Switch Room - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1151	ACTIVE	J	B085-00-2/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Queensbury Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x Isolators x200amps		1			
1150	ACTIVE	J	B085-00-2/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Queensbury Stn	Isolator Switches	Asbestos	Strongly Presumed				5 x Isolators 2x30amps, 2x 60amps, 1x200amps		5			
3105	ACTIVE	J	B085-00-A/261	Platform 1 - Northbound Local - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B085-00 - Station Building - Queensbury Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2409	ACTIVE	J	B085-00-A/261	Platform 1 - Northbound Local - Station Building - Queensbury Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3106	ACTIVE	J	B085-00-A/262	Platform 2 - Southbound Local - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2472	ACTIVE	J	B085-00-A/262	Platform 2 - Southbound Local - Station Building - Queensbury Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3107	ACTIVE	J	B085-00-A/331	Mess Room - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1152	ACTIVE	J	B085-00-A/331	Mess Room - Station Building - Queensbury Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3108	ACTIVE	J	B085-00-A/436	Waiting Room - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1153	ACTIVE	J	B085-00-A/436	Waiting Room - Station Building - Queensbury Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3109	ACTIVE	J	B085-00-A/437	Waiting Room - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2473	ACTIVE	J	B085-00-A/437	Waiting Room - Station Building - Queensbury Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3110	ACTIVE	J	B085-00-A/481	Store - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1154	ACTIVE	J	B085-00-A/481	Store - Station Building - Queensbury Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3111	ACTIVE	J	B085-00-A/482	Equipment Room - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1155	ACTIVE	J	B085-00-A/482	Equipment Room - Station Building - Queensbury Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3112	ACTIVE	J	B085-00-A/483	Equipment Room - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1156	ACTIVE	J	B085-00-A/483	Equipment Room - Station Building - Queensbury Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3113	ACTIVE	J	B085-00-A/601	Stairs: Linear - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B085-00 - Station Building - Queensbury Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2474	ACTIVE	J	B085-00-A/601	Stairs: Linear - Station Building - Queensbury Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3114	ACTIVE	J	B085-00-A/602	Stairs: Linear - Station Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2410	ACTIVE	J	B085-00-A/602	Stairs: Linear - Station Building - Queensbury Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2530	ACTIVE	J	B085-00-A/713	SER - Station Building - Queensbury Stn	No Access	Asbestos	Surveyed – Not Detected				New Build					

B087-00 - Station Building - Kingsbury Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
45161	ACTIVE	J	B087-00-0/711	SER - Station Building - Kingsbury Stn	Other Boarding	Asbestos	Presumed				Paxoline boards throughout room				N	N
45160	ACTIVE	J	B087-00-0/711	SER - Station Building - Kingsbury Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				1x Combination Fuse switch		1		N	N
3122	ACTIVE	J	B087-00-1/001	Booking Hall - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1159	ACTIVE	J	B087-00-1/001	Booking Hall - Station Building - Kingsbury Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Melamine boarding by telephone					
2475	ACTIVE	J	B087-00-1/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Kingsbury Stn	Glazing Rope	Asbestos	Surveyed – Not Detected				Glazing Rope in Entrance Canopy - Type 3 Survey Confirms Non Asbestos					
3123	ACTIVE	J	B087-00-1/011	Ticket Office - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1160	ACTIVE	J	B087-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Kingsbury Stn	Void	Asbestos	Surveyed – Not Detected				Fibreboard above false ceiling				Yes	
2411	ACTIVE	J	B087-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Kingsbury Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2482	ACTIVE	J	B087-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Kingsbury Stn	Void	Asbestos	No Access: Presumed				No access beneath false floor					yes
3124	ACTIVE	J	B087-00-1/021	POM - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1161	ACTIVE	J	B087-00-1/021	POM - Station Building - Kingsbury Stn	Lagging	Asbestos	Surveyed – Not Detected				Fibreglass					



Hazardous Material Asset Register - Summary



B087-00 - Station Building - Kingsbury Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2284	ACTIVE	J	B087-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Kingsbury Stn	Void	Asbestos	No Access: Presumed				No access below False Floor					yes
3125	ACTIVE	J	B087-00-1/031	Mess Room - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1164	ACTIVE	J	B087-00-1/031	Mess Room - Station Building - Kingsbury Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				White foam backing. Wood boxing		1			
1163	ACTIVE	J	B087-00-1/031/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Kingsbury Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux				Yes	
1162	ACTIVE	J	B087-00-1/031/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Kingsbury Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
3126	ACTIVE	J	B087-00-1/036	Toilet: Unisex - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1166	ACTIVE	J	B087-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Kingsbury Stn	Void	Asbestos	Surveyed – Not Detected				Above - Metal Conduits & Air Ducts - Concrete				Yes	
2476	ACTIVE	J	B087-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Kingsbury Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Fibreboard					
3127	ACTIVE	J	B087-00-1/081	Lobby - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1168	ACTIVE	J	B087-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Kingsbury Stn	Void	Asbestos	Surveyed – Not Detected				Plaster above Supalux				Yes	
1167	ACTIVE	J	B087-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Kingsbury Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
3128	ACTIVE	J	B087-00-1/082	Lobby - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2412	ACTIVE	J	B087-00-1/136	Lift Shaft - Station Building - Kingsbury Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
1170	ACTIVE	J	B087-00-1/137	Lift Shaft - Station Building - Kingsbury Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3129	ACTIVE	J	B087-00-1/201	Passage - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2477	ACTIVE	J	B087-00-1/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Kingsbury Stn	Glazing Rope	Asbestos	Surveyed – Not Detected				Glazing Rope in Entrance Canopy - Type 3 Survey Confirms Non Asbestos					
3130	ACTIVE	J	B087-00-1/202	Passage - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B087-00 - Station Building - Kingsbury Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1171	ACTIVE	J	B087-00-1/202	Passage - Station Building - Kingsbury Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3131	ACTIVE	J	B087-00-1/203	Passage - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2486	ACTIVE	J	B087-00-1/203	Passage - Station Building - Kingsbury Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3132	ACTIVE	J	B087-00-1/236	Passage - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1269	ACTIVE	J	B087-00-1/236	Passage - Station Building - Kingsbury Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3133	ACTIVE	J	B087-00-1/237	Passage - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1270	ACTIVE	J	B087-00-1/237	Passage - Station Building - Kingsbury Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3134	ACTIVE	J	B087-00-1/311	Mess Room - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1272	ACTIVE	J	B087-00-1/311	Mess Room - Station Building - Kingsbury Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				White foam backing		1			
1165	ACTIVE	J	B087-00-1/311	Mess Room - Station Building - Kingsbury Stn	Void	Asbestos	No Access: Presumed				Wood boxing located behind lockers vertically situated.					
1271	ACTIVE	J	B087-00-1/311/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Kingsbury Stn	Void	Asbestos	Surveyed – Not Detected				Above - Metal Conduits & Air Ducts - Concrete				Yes	
2573	ACTIVE	J	B087-00-1/311/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Kingsbury Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Fibreboard					
3135	ACTIVE	J	B087-00-1/316	Locker Room - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2251	ACTIVE	J	B087-00-1/316/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Kingsbury Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1274	ACTIVE	J	B087-00-1/316/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Kingsbury Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux				Yes	
1273	ACTIVE	J	B087-00-1/316/FLR-01	Floor - 1 - Locker Room - Station Building - Kingsbury Stn	Void	Asbestos	No Access: Presumed				No access below False Floor					yes



Hazardous Material Asset Register - Summary



B087-00 - Station Building - Kingsbury Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3136	ACTIVE	J	B087-00-1/401	Store - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3137	ACTIVE	J	B087-00-1/402	Bin Store - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2574	ACTIVE	J	B087-00-1/402	Bin Store - Station Building - Kingsbury Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3138	ACTIVE	J	B087-00-1/406	Store - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3139	ACTIVE	J	B087-00-1/407	Store - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1275	ACTIVE	J	B087-00-1/407	Store - Station Building - Kingsbury Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3140	ACTIVE	J	B087-00-1/408	Store - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1276	ACTIVE	J	B087-00-1/408	Store - Station Building - Kingsbury Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3141	ACTIVE	J	B087-00-1/426	Toilet: Female - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3142	ACTIVE	J	B087-00-1/427	Toilet - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2536	ACTIVE	J	B087-00-1/428	Toilet: Male - Station Building - Kingsbury Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
2289	ACTIVE	J	B087-00-1/429	Toilet: Disabled - Station Building - Kingsbury Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3143	ACTIVE	J	B087-00-1/601	Stairs: Linear - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2575	ACTIVE	J	B087-00-1/601/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Kingsbury Stn	Glazing Rope	Asbestos	Surveyed – Not Detected				Glass, Glazing Rope under Glazing Bars - Type 3 Survey Confirms Non Asbestos					
1277	ACTIVE	J	B087-00-1/601/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Kingsbury Stn	Glazing Rope	Asbestos	Surveyed – Not Detected				Glass, Glazing Rope under Glazing Bars - Type 3 Survey Confirms Non Asbestos					
3144	ACTIVE	J	B087-00-1/602	Stairs: Linear - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B087-00 - Station Building - Kingsbury Stn																
Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3145	ACTIVE	J	B087-00-1/661	Switch Room - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1278	ACTIVE	J	B087-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Kingsbury Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 30amp Combination fuse switch		1			
42034	ACTIVE	J	B087-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Kingsbury Stn	Other Electrical Boxes	Asbestos	Presumed				3 x Transformer Boxes		3		N	N
42035	ACTIVE	J	B087-00-1/661/WAL-002 80823501	Wall: Internal - 2 - Switch Room - Station Building - Kingsbury Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Boxes		1		N	N
1279	ACTIVE	J	B087-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Kingsbury Stn	Isolator Switches	Asbestos	Strongly Presumed				4 x Combination fuse switches - 1 x 100, 3 x 60amps		4		N	N
3146	ACTIVE	J	B087-00-1/662	Switch Room - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3147	ACTIVE	J	B087-00-1/663	Switch Cupboard - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1280	ACTIVE	J	B087-00-1/663	Switch Cupboard - Station Building - Kingsbury Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3148	ACTIVE	J	B087-00-1/664	Switch Cupboard - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2252	ACTIVE	J	B087-00-1/664	Switch Cupboard - Station Building - Kingsbury Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3149	ACTIVE	J	B087-00-1/746	SCR - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3150	ACTIVE	J	B087-00-1/748	SCR - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1281	ACTIVE	J	B087-00-1/748	SCR - Station Building - Kingsbury Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3151	ACTIVE	J	B087-00-2/081	Lobby - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1282	ACTIVE	J	B087-00-2/081	Lobby - Station Building - Kingsbury Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3152	ACTIVE	J	B087-00-2/131	LMR - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B087-00 - Station Building - Kingsbury Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2576	ACTIVE	J	B087-00-2/131	LMR - Station Building - Kingsbury Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3153	ACTIVE	J	B087-00-2/133	LMR - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1285	ACTIVE	J	B087-00-2/133	LMR - Station Building - Kingsbury Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3154	ACTIVE	J	B087-00-2/134	LMR - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1286	ACTIVE	J	B087-00-2/134	LMR - Station Building - Kingsbury Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3155	ACTIVE	J	B087-00-2/261	Platform 1 - Northbound Local - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2577	ACTIVE	J	B087-00-2/261/ BAR-01	Platform End Barrier - Platform 1 (North End) - Station Building - Kingsbury Stn	Westing house Boxes	Asbestos	Strongly Presumed				2 Signal boxes (Previously 3no - the Large Westinghouse box has been removed -2020 re-inspection)		3			
3156	ACTIVE	J	B087-00-2/262	Platform 2 - Southbound Local - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2253	ACTIVE	J	B087-00-2/262/ CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - Kingsbury Stn	Glazing Rope	Asbestos	Surveyed – Not Detected				Glass, Glazing Rope under Glazing Bars - Type 3 Survey Confirms Non Asbestos					
3157	ACTIVE	J	B087-00-2/281	Station Supervisor Office - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1287	ACTIVE	J	B087-00-2/281	Station Supervisor Office - Station Building - Kingsbury Stn	LUL Heaters	Asbestos	Surveyed – Not Detected						1			
3158	ACTIVE	J	B087-00-2/371	Store - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1289	ACTIVE	J	B087-00-2/371	Store - Station Building - Kingsbury Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Foam Backing		1			
1288	ACTIVE	J	B087-00-2/371/ SNK-01	Sink - 1 - Store - Station Building - Kingsbury Stn		Asbestos	Surveyed – Not Detected				Acoustic Sink Panel		1			
3159	ACTIVE	J	B087-00-2/396	Store - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2487	ACTIVE	J	B087-00-2/396	Store - Station Building - Kingsbury Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3160	ACTIVE	J	B087-00-2/411	Store - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B087-00 - Station Building - Kingsbury Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1290	ACTIVE	J	B087-00-2/411	Store - Station Building - Kingsbury Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3161	ACTIVE	J	B087-00-2/412	Store - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1291	ACTIVE	J	B087-00-2/412	Store - Station Building - Kingsbury Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3162	ACTIVE	J	B087-00-2/436	Waiting Room - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2537	ACTIVE	J	B087-00-2/436	Waiting Room - Station Building - Kingsbury Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3163	ACTIVE	J	B087-00-2/437	Waiting Room - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1292	ACTIVE	J	B087-00-2/437	Waiting Room - Station Building - Kingsbury Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3164	ACTIVE	J	B087-00-2/661	Switch Room - Station Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1294	INACTIVE	J	B087-00-2/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Kingsbury Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box - box removed - 2020 re-inspection - see photo		1			
2578	ACTIVE	J	B087-00-2/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Kingsbury Stn	Isolator Switches	Asbestos	Strongly Presumed				7 x Isolaters 2x30amp 5x60amp		7			
1293	ACTIVE	J	B087-00-2/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Kingsbury Stn	Isolator Switches	Asbestos	Strongly Presumed				4 x Grey 2x30amp 1x200amp 1x100amp		4			

B088-07 - Signals Building (WEP) - Kingsbury To Wembley Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3182	ACTIVE	J	B088-07-0/712	SER - Signals Building (WEP) - Kingsbury To Wembley Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B091-00 - Station Building - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3185	ACTIVE	J	B091-00-1/001	Booking Hall - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1802	ACTIVE	J	B091-00-1/001/CLG-01	Ceiling: Suspended - 1 - Booking Hall - Station Building - Wembley Park Stn	Void	Asbestos	Surveyed – Not Detected				All beams Wood. New Cables throughout. No visible ACM's found. Pipe Lagging Fibre Glass. Fibre Glass also covering tank. 2nd tank had no cover.				Yes	
2807	ACTIVE	J	B091-00-1/001/CLG-01	Ceiling: Suspended - 1 - Booking Hall - Station Building - Wembley Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
3186	ACTIVE	J	B091-00-1/002	Booking Hall - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1803	ACTIVE	J	B091-00-1/002	Booking Hall - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3187	ACTIVE	J	B091-00-1/011	Ticket Office - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1805	ACTIVE	J	B091-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Wembley Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2808	ACTIVE	J	B091-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Wembley Park Stn	Void	Asbestos	Surveyed – Not Detected				Pasterboard above Supalux Tiles				Yes	
1804	ACTIVE	J	B091-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Wembley Park Stn	Void	Asbestos	Surveyed – Not Detected				Concrete - beneath Computer Tiles					yes
3188	ACTIVE	J	B091-00-1/015	Ticket Office - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1806	ACTIVE	J	B091-00-1/015	Ticket Office - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room				yes	
3189	ACTIVE	J	B091-00-1/021	POM - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2507	ACTIVE	J	B091-00-1/021	POM - Station Building - Wembley Park Stn	No Access	Asbestos	No Access: Presumed				No access to boxing behind cupboard					
2363	ACTIVE	J	B091-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Wembley Park Stn	Void	Asbestos	No Access: Presumed				Beneath - Computer Flooring					yes
3190	ACTIVE	J	B091-00-1/022	POM - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1807	ACTIVE	J	B091-00-1/022	POM - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					



Hazardous Material Asset Register - Summary



B091-00 - Station Building - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3191	ACTIVE	J	B091-00-1/031	Mess Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1810	ACTIVE	J	B091-00-1/031	Mess Room - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel under Sink		1			
2809	ACTIVE	J	B091-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Wembley Park Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard above Supalux Tiles				Yes	
1809	ACTIVE	J	B091-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Wembley Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1808	ACTIVE	J	B091-00-1/031/WAL-002	Wall: Internal - 2 - Mess Room - Station Building - Wembley Park Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater with Foam Insulation		1			
3192	ACTIVE	J	B091-00-1/032	Mess Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1811	ACTIVE	J	B091-00-1/032	Mess Room - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3193	ACTIVE	J	B091-00-1/036	Toilet: Unisex - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1813	ACTIVE	J	B091-00-1/036/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Wembley Park Stn	Void	Asbestos	No Access: Presumed				No access to loft				Yes	
2563	ACTIVE	J	B091-00-1/036/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Wembley Park Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
1812	ACTIVE	J	B091-00-1/036/WAL-003	Wall: Internal - 3 - Toilet - Station Building - Wembley Park Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Melamine					
3194	ACTIVE	J	B091-00-1/037	Toilet: Unisex - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1814	ACTIVE	J	B091-00-1/037	Toilet: Unisex - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3195	ACTIVE	J	B091-00-1/038	Toilet: Unisex - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2306	ACTIVE	J	B091-00-1/038	Toilet: Unisex - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3196	ACTIVE	J	B091-00-1/047	Kitchen - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B091-00 - Station Building - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2810	ACTIVE	J	B091-00-1/047	Kitchen - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3197	ACTIVE	J	B091-00-1/071	Circulation Area - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1815	ACTIVE	J	B091-00-1/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Wembley Park Stn	Void	Asbestos	Surveyed – Not Detected				Wooden Board				Yes	
2564	ACTIVE	J	B091-00-1/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Wembley Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
3198	ACTIVE	J	B091-00-1/081	Lobby - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2811	ACTIVE	J	B091-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Wembley Park Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard above Supalux Tiles				Yes	
1816	ACTIVE	J	B091-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Wembley Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2364	ACTIVE	J	B091-00-1/081/FLR-01	Floor - 1 - Lobby - Station Building - Wembley Park Stn	Void	Asbestos	No Access: Presumed				Beneath - Computer Flooring					yes
3199	ACTIVE	J	B091-00-1/082	Lobby - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1817	ACTIVE	J	B091-00-1/082/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Wembley Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1818	ACTIVE	J	B091-00-1/082/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Wembley Park Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard, Supalux boarding above Supalux Tiles				Yes	
1819	ACTIVE	J	B091-00-1/082/WAL-002	Wall: Internal - 2 - Lobby - Station Building - Wembley Park Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater with Foam Insulation		1			
3200	ACTIVE	J	B091-00-1/083	Lobby - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1820	ACTIVE	J	B091-00-1/083	Lobby - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3201	ACTIVE	J	B091-00-1/084	Lobby - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1821	ACTIVE	J	B091-00-1/084	Lobby - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					



Hazardous Material Asset Register - Summary



B091-00 - Station Building - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2812	ACTIVE	J	B091-00-1/136	Lift Shaft - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
1822	ACTIVE	J	B091-00-1/137	Lift Shaft - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
1823	ACTIVE	J	B091-00-1/138	Lift Shaft - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
2508	ACTIVE	J	B091-00-1/139	Lift Shaft - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
1824	ACTIVE	J	B091-00-1/140	Lift Shaft - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3202	ACTIVE	J	B091-00-1/201	Passage - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2813	ACTIVE	J	B091-00-1/201	Passage - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3203	ACTIVE	J	B091-00-1/236	Passage - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2924	ACTIVE	J	B091-00-1/236	Passage - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3204	ACTIVE	J	B091-00-1/237	Passage - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1825	ACTIVE	J	B091-00-1/237	Passage - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3205	ACTIVE	J	B091-00-1/238	Passage - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1826	ACTIVE	J	B091-00-1/238	Passage - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3206	ACTIVE	J	B091-00-1/282	Station Control Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3207	ACTIVE	J	B091-00-1/302	Mess Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3208	ACTIVE	J	B091-00-1/311	ATM - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1829	ACTIVE	J	B091-00-1/311/CLG-01	Ceiling: Solid - 1 - ATM - Station Building - Wembley Park Stn	Void	Asbestos	No Access: Presumed				Above - Plasterboard / Supalux Boarding				Yes	



Hazardous Material Asset Register - Summary



B091-00 - Station Building - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1828	ACTIVE	J	B091-00-1/311/CLG-01	Ceiling: Solid - 1 - ATM - Station Building - Wembley Park Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard / Supalux Boarding					
2814	ACTIVE	J	B091-00-1/311/WAL-003	Wall: Internal - 3 - ATM - Station Building - Wembley Park Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Foam insulation		1			
3209	ACTIVE	J	B091-00-1/316	Locker Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2307	ACTIVE	J	B091-00-1/316	Locker Room - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3210	ACTIVE	J	B091-00-1/317	Locker Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1830	ACTIVE	J	B091-00-1/317	Locker Room - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3211	ACTIVE	J	B091-00-1/331	Mess Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2365	ACTIVE	J	B091-00-1/331	Mess Room - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3212	ACTIVE	J	B091-00-1/406	Office - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1831	ACTIVE	J	B091-00-1/406	Office - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3213	ACTIVE	J	B091-00-1/413	Store - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1832	ACTIVE	J	B091-00-1/413	Store - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3214	ACTIVE	J	B091-00-1/414	Store - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2815	ACTIVE	J	B091-00-1/414	Store - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3215	ACTIVE	J	B091-00-1/416	Toilet: Unisex - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1833	ACTIVE	J	B091-00-1/416	Toilet: Unisex - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3216	ACTIVE	J	B091-00-1/417	Toilet: Unisex - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B091-00 - Station Building - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2565	ACTIVE	J	B091-00-1/417	Toilet: Unisex - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3217	ACTIVE	J	B091-00-1/576	Stairs: Linear - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1834	ACTIVE	J	B091-00-1/576	Stairs: Linear - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3218	ACTIVE	J	B091-00-1/603	Stairs: Linear - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1835	ACTIVE	J	B091-00-1/603	Stairs: Linear - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3219	ACTIVE	J	B091-00-1/604	Stairs: Linear - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1836	ACTIVE	J	B091-00-1/604	Stairs: Linear - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3220	ACTIVE	J	B091-00-1/605	Stairs: Linear - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2366	ACTIVE	J	B091-00-1/605	Stairs: Linear - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3221	ACTIVE	J	B091-00-1/606	Stairs: Linear - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2816	ACTIVE	J	B091-00-1/606	Stairs: Linear - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3222	ACTIVE	J	B091-00-1/607	Stairs: Linear - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1837	ACTIVE	J	B091-00-1/607	Stairs: Linear - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3223	ACTIVE	J	B091-00-1/608	Stairs: Linear - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3224	ACTIVE	J	B091-00-1/609	Stairs: Linear - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3225	ACTIVE	J	B091-00-1/610	Stairs: Linear - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1838	ACTIVE	J	B091-00-1/610	Stairs: Linear - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



Hazardous Material Asset Register - Summary



B091-00 - Station Building - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3226	ACTIVE	J	B091-00-1/611	Stairs: Linear - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2900	ACTIVE	J	B091-00-1/611	Stairs: Linear - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3227	ACTIVE	J	B091-00-1/613	Stairs: Linear - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2817	ACTIVE	J	B091-00-1/613	Stairs: Linear - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3228	ACTIVE	J	B091-00-1/614	Stairs: Linear - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1839	ACTIVE	J	B091-00-1/614	Stairs: Linear - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3229	ACTIVE	J	B091-00-1/615	Stairs: Linear - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1840	ACTIVE	J	B091-00-1/615	Stairs: Linear - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3230	ACTIVE	J	B091-00-1/616	Stairs: Linear - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1683	ACTIVE	J	B091-00-1/616	Stairs: Linear - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3231	ACTIVE	J	B091-00-1/631	Stairs: Spiral - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1684	ACTIVE	J	B091-00-1/631	Stairs: Spiral - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3232	ACTIVE	J	B091-00-1/632	Stairs: Spiral - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1685	ACTIVE	J	B091-00-1/632	Stairs: Spiral - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3233	ACTIVE	J	B091-00-1/636	Passage - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1686	ACTIVE	J	B091-00-1/636	Passage - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
1687	ACTIVE	J	B091-00-1/637	Overbridge - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



Hazardous Material Asset Register - Summary



B091-00 - Station Building - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2629	ACTIVE	J	B091-00-1/638	Overbridge - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3234	ACTIVE	J	B091-00-1/661	Switch Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1688	ACTIVE	J	B091-00-1/661	Switch Room - Station Building - Wembley Park Stn	Isolator Switches	Asbestos	Strongly Presumed				EXTERNAL - 4 x Switch boxes - containment to nosing on platform 3 2 x 30 amp, 2 x 60 amps		4			
3235	ACTIVE	J	B091-00-1/664	Switch Cupboard - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1689	ACTIVE	J	B091-00-1/664	Switch Cupboard - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3236	ACTIVE	J	B091-00-1/665	Switch Cupboard - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1690	ACTIVE	J	B091-00-1/665	Switch Cupboard - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3237	ACTIVE	J	B091-00-1/666	Switch Cupboard - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3238	ACTIVE	J	B091-00-1/706	IMR - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3239	ACTIVE	J	B091-00-1/731	IMR - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3240	ACTIVE	J	B091-00-1/732	CER - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
2630	ACTIVE	J	B091-00-1/732	CER - Station Building - Wembley Park Stn	No Access	Asbestos	No Access: Presumed									
3241	ACTIVE	J	B091-00-1/746	SCR - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3242	ACTIVE	J	B091-00-1/747	SCR - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1691	ACTIVE	J	B091-00-1/747	SCR - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3243	ACTIVE	J	B091-00-1/751	Station Control Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B091-00 - Station Building - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1692	ACTIVE	J	B091-00-1/751	Station Control Room - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3244	ACTIVE	J	B091-00-1/786	Service Riser - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1693	ACTIVE	J	B091-00-1/786	Service Riser - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3245	ACTIVE	J	B091-00-1/787	Service Riser - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2631	ACTIVE	J	B091-00-1/787	Service Riser - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3246	ACTIVE	J	B091-00-1/788	Service Riser - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1694	ACTIVE	J	B091-00-1/788	Service Riser - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3247	ACTIVE	J	B091-00-2/081	Lobby - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2557	ACTIVE	J	B091-00-2/081	Lobby - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3248	ACTIVE	J	B091-00-2/082	Lobby - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1695	ACTIVE	J	B091-00-2/082	Lobby - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3249	ACTIVE	J	B091-00-2/083	Lobby - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1696	ACTIVE	J	B091-00-2/083	Lobby - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3250	ACTIVE	J	B091-00-2/131	LMR - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1697	ACTIVE	J	B091-00-2/131	LMR - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3251	ACTIVE	J	B091-00-2/132	LMR - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2632	ACTIVE	J	B091-00-2/132	LMR - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					



Hazardous Material Asset Register - Summary



B091-00 - Station Building - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3252	ACTIVE	J	B091-00-2/133	LMR - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1698	ACTIVE	J	B091-00-2/133	LMR - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3253	ACTIVE	J	B091-00-2/134	LMR - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2351	ACTIVE	J	B091-00-2/134	LMR - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3254	ACTIVE	J	B091-00-2/236	Passage - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1699	ACTIVE	J	B091-00-2/236	Passage - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3255	ACTIVE	J	B091-00-2/241	Disused Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3256	ACTIVE	J	B091-00-2/248	Toilet - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3257	ACTIVE	J	B091-00-2/249	Toilet - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3258	ACTIVE	J	B091-00-2/261	Platform 1 - Northbound Fast - Metropolitan Line - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45416	ACTIVE	J	B091-00-2/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Wembley Park Stn		Asbestos	Sampled – Not Detected				The flat roof on platform 1 was surveyed for asbestos containing materials. No asbestos was detected. (Asphalt on concrete slab 120m2 topside of canopy. New membrane on wood.) 06/08/2020. Report R681801					
1700	ACTIVE	J	B091-00-2/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Wembley Park Stn	Glazing Rope	Asbestos	Sampled – Not Detected				11m² Rope Seals under Glazing Bars of Ceiling Canopy Type 3 Confirms Non Asbestos					
3259	ACTIVE	J	B091-00-2/262	Platform 2 - Northbound Local - Metropolitan Line - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1701	ACTIVE	J	B091-00-2/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - Wembley Park Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling				Yes	
2633	ACTIVE	J	B091-00-2/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - Wembley Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Part Strawboard/part Wooden Slats Vertical supalux boarding by stairs 1/603					



Hazardous Material Asset Register - Summary



B091-00 - Station Building - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1702	ACTIVE	J	B091-00-2/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - Wembley Park Stn	Glazing Rope	Asbestos	Sampled – Not Detected				Rope Seal under Glazing Bars of Ceiling Skylight Type 3 Confirms Non Asbestos					
3260	ACTIVE	J	B091-00-2/263	Platform 3 - Northbound Local - Jubilee Line - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1703	ACTIVE	J	B091-00-2/263/CLG-01	Ceiling: Solid - 1 - Platform 3 - Station Building - Wembley Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Part Strawboard/part Wooden Slats Vertical supalux boarding by stairs 1/603					
2352	ACTIVE	J	B091-00-2/263/CLG-01	Ceiling: Solid - 1 - Platform 3 - Station Building - Wembley Park Stn	Glazing Rope	Asbestos	Sampled – Not Detected				Rope Seal under Glazing Bars of Ceiling Skylight. Type 3 Confirms Non Asbestos					
1704	ACTIVE	J	B091-00-2/263/CLG-01	Ceiling: Solid - 1 - Platform 3 - Station Building - Wembley Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux north end of canopy - non asbestos					
2634	ACTIVE	J	B091-00-2/263/FLR-01	Floor - 1 - Platform 3 - Station Building - Wembley Park Stn	Cable Ducts: Bitumen	Asbestos	Surveyed – Not Detected				Bituminous Duct 230mm below Platform 3 surface outside 2/910& 2/416 - No Asbestos detected					
2786	ACTIVE	J	B091-00-2/263/PLN-01	Nosing: Platform - Platform 3 - Station Building - Wembley Park Stn	Cable: Sheath	Asbestos	Surveyed – Not Detected				Metal J Hangers & PVC Cables on Nosing (Jubilee line platform) End of Platform 3 Signal Building - New Metal J Hangers on Wall. South End OTX (new & existing OTX) & track - Metal & PVC Cables					
3261	ACTIVE	J	B091-00-2/264	Platform 4 - Southbound Local - Jubilee Line - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1707	ACTIVE	J	B091-00-2/264/BAR-01	Platform End Barrier - Platform 4 (North End) - Station Building - Wembley Park Stn	Westing house Boxes	Asbestos	Strongly Presumed				1x Insulation inside Westinghouse Brake Box - on the Head Wall					
2558	ACTIVE	J	B091-00-2/264/CLG-01	Ceiling: Solid - 1 - Platform 4 - Station Building - Wembley Park Stn	Glazing Rope	Asbestos	Sampled – Not Detected				Type 3 Confirms Non Asbestos - Rope Seal under Glazing Bars of Ceiling Skylight					
1706	ACTIVE	J	B091-00-2/264/CLG-01	Ceiling: Solid - 1 - Platform 4 - Station Building - Wembley Park Stn	Void	Asbestos	No Access: Presumed				Above Metal, Cladding				Yes	
1705	ACTIVE	J	B091-00-2/264/FLR-01	Floor - 1 - Platform 4 - Station Building - Wembley Park Stn	Void	Asbestos	No Access: Presumed				Beneath - Hatch / Manhole					yes
3262	ACTIVE	J	B091-00-2/265	Platform 5 - Southbound Local - Metropolitan Line - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1768	ACTIVE	J	B091-00-2/265	Platform 5 - Southbound Local - Metropolitan Line - Station Building - Wembley Park Stn	Westing house Boxes	Asbestos	Strongly Presumed				1x Insulation inside Westinghouse Brake Box - Head Wall		1		N	N
1766	ACTIVE	J	B091-00-2/265/BAR-02	Platform End Barrier - Platform 5 (South End) - Station Building - Wembley Park Stn	Cable Duct: Other	Asbestos	Surveyed – Not Detected				Head Wall 1x Cable sleeve - Non asbestos					



Hazardous Material Asset Register - Summary



B091-00 - Station Building - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2505	ACTIVE	J	B091-00-2/265/CLG-01	Ceiling: Solid - 1 - Platform 5 - Station Building - Wembley Park Stn	Glazing Rope	Asbestos	Sampled – Not Detected				Type 3 Confirms Non Asbestos - Rope Seal under Glazing Bars of Ceiling Skylight					
2796	ACTIVE	J	B091-00-2/265/CLG-01	Ceiling: Solid - 1 - Platform 5 - Station Building - Wembley Park Stn	Void	Asbestos	No Access: Presumed				Above Metal, Cladding				Yes	
1767	ACTIVE	J	B091-00-2/265/CLG-01	Ceiling: Solid - 1 - Platform 5 - Station Building - Wembley Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux, North end of Canopy - Non Asbestos					
1765	ACTIVE	J	B091-00-2/265/FLR-01	Floor - 1 - Platform 5 - Station Building - Wembley Park Stn	Void	Asbestos	No Access: Presumed				Beneath - Hatch / Manhole					yes
3263	ACTIVE	J	B091-00-2/266	Platform 6 - Southbound Fast - Metropolitan Line - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45169	ACTIVE	J	B091-00-2/266	Platform 6 - Southbound Fast - Metropolitan Line - Station Building - Wembley Park Stn	Debris: Other	Asbestos	Known				Asbestos cement board debris, to floor, post route behind platform 6 N.B. Not found on 2012 re-inspection but may still be present				N	N
1769	ACTIVE	J	B091-00-2/266	Platform 6 - Southbound Fast - Metropolitan Line - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				Hanger route - Node point 13-17 Existing J Hangers, all Cables PVC along J hangers to CER.					
44949	ACTIVE	J	B091-00-2/266	Platform 6 - Southbound Fast - Metropolitan Line - Station Building - Wembley Park Stn	Boarding: AIB	Asbestos	Known				Asbestos cement board debris, to floor, post route behind platform 6 (not found on 2012 re-inspection but may still be present)				N	N
3264	ACTIVE	J	B091-00-2/281	Mess Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1770	ACTIVE	J	B091-00-2/281	Mess Room - Station Building - Wembley Park Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LTB Heater - Metal backing		1			
2797	ACTIVE	J	B091-00-2/281	Mess Room - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				Acoustic Panel on underside of Sink - Non asbestos		1			
3265	ACTIVE	J	B091-00-2/291	Station Supervisor Office - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1771	ACTIVE	J	B091-00-2/291/WAL-004	Wall: Internal - 4 - Station Supervisor Office - Station Building - Wembley Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boxing					
1772	ACTIVE	J	B091-00-2/291/WAL-004	Wall: Internal - 4 - Station Supervisor Office - Station Building - Wembley Park Stn	Other Boarding	Asbestos	Strongly Presumed				0.02m² Inside boxing (grey boarding, no sample -live electrics)Note - cabinet bolted closed and not opened during 2020 inspection due to live electrics within.					
3266	ACTIVE	J	B091-00-2/301	Office - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B091-00 - Station Building - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2798	ACTIVE	J	B091-00-2/301	Office - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3267	ACTIVE	J	B091-00-2/317	Disused Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1773	ACTIVE	J	B091-00-2/317/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Wembley Park Stn	Void	Asbestos	No Access: Presumed				Above Hatches / Plasterboard Ceiling				Yes	
2359	ACTIVE	J	B091-00-2/317/WAL-002	Wall: Internal - 2 - Disused Room - Station Building - Wembley Park Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater has a metal backing		1			
3268	ACTIVE	J	B091-00-2/318	Disused Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1774	ACTIVE	J	B091-00-2/318/WAL-002	Wall: Internal - 2 - Disused Room - Station Building - Wembley Park Stn	LUL Heaters	Asbestos	Surveyed – Not Detected						1			
3269	ACTIVE	J	B091-00-2/319	Locker Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2799	ACTIVE	J	B091-00-2/319	Locker Room - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3270	ACTIVE	J	B091-00-2/332	Store - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2562	ACTIVE	J	B091-00-2/332/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Wembley Park Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard Ceiling				Yes	
3271	ACTIVE	J	B091-00-2/333	Mess Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3272	ACTIVE	J	B091-00-2/341	Disused Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1775	ACTIVE	J	B091-00-2/341/WAL-003	Wall: Internal - 3 - Disused Room - Station Building - Wembley Park Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Supalux, Bakerlite boarding					
3273	ACTIVE	J	B091-00-2/351	Mess Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2800	ACTIVE	J	B091-00-2/351	Mess Room - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				Acoustic panel by Sink unit - Non asbestos		1			



Hazardous Material Asset Register - Summary



B091-00 - Station Building - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1776	ACTIVE	J	B091-00-2/351/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Wembley Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1777	ACTIVE	J	B091-00-2/351/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Wembley Park Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard, Supalux boarding, Hatch				Yes	
3274	ACTIVE	J	B091-00-2/361	Mess Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1778	ACTIVE	J	B091-00-2/361	Mess Room - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3275	ACTIVE	J	B091-00-2/371	Switch Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1779	ACTIVE	J	B091-00-2/371	Switch Room - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3276	ACTIVE	J	B091-00-2/372	Disused Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1780	ACTIVE	J	B091-00-2/372	Disused Room - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3277	ACTIVE	J	B091-00-2/373	Store - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1781	ACTIVE	J	B091-00-2/373	Store - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				Acoustic panel under Sink unit non asbestos		1			
2360	ACTIVE	J	B091-00-2/373	Store - Station Building - Wembley Park Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding by Sink					
2801	ACTIVE	J	B091-00-2/373/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Wembley Park Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard				Yes	
3278	ACTIVE	J	B091-00-2/406	Lobby - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1782	ACTIVE	J	B091-00-2/406	Lobby - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3279	ACTIVE	J	B091-00-2/411	Locker Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1783	ACTIVE	J	B091-00-2/411/WAL-001	Wall: Internal - 1 - Locker Room - Station Building - Wembley Park Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Foam insulated LTB Heater, Metal backing		1			



Hazardous Material Asset Register - Summary



B091-00 - Station Building - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3280	ACTIVE	J	B091-00-2/413	Switch Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1784	ACTIVE	J	B091-00-2/413	Switch Room - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3281	ACTIVE	J	B091-00-2/415	Store - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1785	ACTIVE	J	B091-00-2/415	Store - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3282	ACTIVE	J	B091-00-2/416	Toilet: Unisex - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2802	ACTIVE	J	B091-00-2/416	Toilet: Unisex - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3283	ACTIVE	J	B091-00-2/417	Toilet: Unisex - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1786	ACTIVE	J	B091-00-2/417	Toilet: Unisex - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3284	ACTIVE	J	B091-00-2/418	Toilet: Unisex - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1787	ACTIVE	J	B091-00-2/418	Toilet: Unisex - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3285	ACTIVE	J	B091-00-2/419	Toilet: Unisex - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1788	ACTIVE	J	B091-00-2/419	Toilet: Unisex - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3286	ACTIVE	J	B091-00-2/420	Toilet: Unisex - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2803	ACTIVE	J	B091-00-2/420	Toilet: Unisex - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3287	ACTIVE	J	B091-00-2/426	Toilet: Female - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2923	ACTIVE	J	B091-00-2/426/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Wembley Park Stn	Void	Asbestos	No Access: Presumed				Above Metal panelling				Yes	



Hazardous Material Asset Register - Summary



B091-00 - Station Building - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3288	ACTIVE	J	B091-00-2/427	Toilet: Unisex - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1708	ACTIVE	J	B091-00-2/427/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Wembley Park Stn	Void	Asbestos	No Access: Presumed				Above Metal panelling				Yes	
3289	ACTIVE	J	B091-00-2/428	Toilet: Male - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1709	ACTIVE	J	B091-00-2/428/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Wembley Park Stn	Void	Asbestos	No Access: Presumed				Above Metal Tiles				Yes	
3290	ACTIVE	J	B091-00-2/429	Toilet: Male - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2635	ACTIVE	J	B091-00-2/429/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Wembley Park Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Metal Tiles				Yes	
3291	ACTIVE	J	B091-00-2/436	Waiting Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1710	ACTIVE	J	B091-00-2/436/WAL-001	Wall: Internal - 1 - Waiting Room - Station Building - Wembley Park Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Foam insulated LTB heater, metal backing		1			
3292	ACTIVE	J	B091-00-2/437	Waiting Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1711	ACTIVE	J	B091-00-2/437	Waiting Room - Station Building - Wembley Park Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Foam insulated LTB heater, metal back panel		1			
3293	ACTIVE	J	B091-00-2/481	Baby Changing Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1712	ACTIVE	J	B091-00-2/481/CLG-01	Ceiling: Suspended - 1 - Baby Changing Room - Station Building - Wembley Park Stn	Void	Asbestos	No Access: Presumed				Above Metal Tiles				Yes	
3294	ACTIVE	J	B091-00-2/482	Cupboard - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1713	ACTIVE	J	B091-00-2/482	Cupboard - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3295	ACTIVE	J	B091-00-2/483	Baby Changing Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B091-00 - Station Building - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2636	ACTIVE	J	B091-00-2/483/CLG-01	Ceiling: Solid - 1 - Baby Changing Room - Station Building - Wembley Park Stn	Void	Asbestos	No Access: Presumed				Above Metal Tiles				Yes	
3296	ACTIVE	J	B091-00-2/661	Switch Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1716	INACTIVE	J	B091-00-2/661	Switch Room - Station Building - Wembley Park Stn	Other Boarding	Asbestos	Strongly Presumed				Bakelite Box - Noted as having been removed by HMU re inspection team 14/01/2015					
2502	ACTIVE	J	B091-00-2/661/FLR-01	Floor - 1 - Switch Room - Station Building - Wembley Park Stn	Cable Duct: Other	Asbestos	Known				5x Cable Sleeves in Hatch below False Floor (no access to hatch on 2020 re-inspection)		5			yes
1714	ACTIVE	J	B091-00-2/661/FLR-01	Floor - 1 - Switch Room - Station Building - Wembley Park Stn	Cable Ducts: Bitumen	Asbestos	Surveyed – Not Detected				Bituminous Pipe Duct Concreted in Floor					
2921	ACTIVE	J	B091-00-2/661/FLR-01	Floor - 1 - Switch Room - Station Building - Wembley Park Stn	Void	Asbestos	No Access: Presumed				Beneath - Hatch / Manhole					yes
1715	ACTIVE	J	B091-00-2/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Wembley Park Stn	Isolator Switches	Asbestos	Strongly Presumed				12 x Insulation inside iron clad isolators - 7 x 60 amps, 3 x 100 amps, 2 x 200amps		12		N	N
3297	ACTIVE	J	B091-00-2/662	Switch Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2889	ACTIVE	J	B091-00-2/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Wembley Park Stn	Isolator Switches	Asbestos	Strongly Presumed				6x Insulation in Iron clad isolators 4x grey - 2x60amp 2x100amp, 2x blue 1x300amp 1x60amp 100A bus bar		6			
3298	INACTIVE	J	B091-00-2/663	Disused Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44029	ACTIVE	J	B091-00-2/663	Disused Room - Station Building - Wembley Park Stn		Asbestos	Room: Surveyed – Asbestos Known				Cement arc chutes, 3 no <0.1m2, located by top left combination fuse switch box within switch room E4 at Wembley Park Station. Removed wholly as samples			R595201	N	N
3299	ACTIVE	J	B091-00-2/664	Switch Cupboard - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1717	ACTIVE	J	B091-00-2/664	Switch Cupboard - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3300	ACTIVE	J	B091-00-2/665	Switch Cupboard - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2637	ACTIVE	J	B091-00-2/665	Switch Cupboard - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					



Hazardous Material Asset Register - Summary



B091-00 - Station Building - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3301	ACTIVE	J	B091-00-2/666	Switch Cupboard - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1718	ACTIVE	J	B091-00-2/666	Switch Cupboard - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3302	ACTIVE	J	B091-00-2/667	Switch Cupboard - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1719	ACTIVE	J	B091-00-2/667	Switch Cupboard - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3303	ACTIVE	J	B091-00-2/668	Store - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2638	ACTIVE	J	B091-00-2/668	Store - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3304	ACTIVE	J	B091-00-2/786	Service Riser - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1720	ACTIVE	J	B091-00-2/786	Service Riser - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3305	ACTIVE	J	B091-00-2/787	Service Riser - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1721	ACTIVE	J	B091-00-2/787	Service Riser - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3306	ACTIVE	J	B091-00-2/801	Office - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2303	ACTIVE	J	B091-00-2/801	Office - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3307	ACTIVE	J	B091-00-2/802	Office - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1722	ACTIVE	J	B091-00-2/802	Office - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3308	ACTIVE	J	B091-00-2/901	Store - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2353	ACTIVE	J	B091-00-2/901	Store - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3309	ACTIVE	J	B091-00-2/902	Disused Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B091-00 - Station Building - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1723	ACTIVE	J	B091-00-2/902	Disused Room - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3310	ACTIVE	J	B091-00-2/903	Disused Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2639	ACTIVE	J	B091-00-2/903	Disused Room - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3311	ACTIVE	J	B091-00-2/904	Disused Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1724	ACTIVE	J	B091-00-2/904	Disused Room - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3312	ACTIVE	J	B091-00-2/905	Disused Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1725	ACTIVE	J	B091-00-2/905	Disused Room - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3313	ACTIVE	J	B091-00-2/951	Switch Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1726	ACTIVE	J	B091-00-2/951	Switch Room - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3314	ACTIVE	J	B091-00-2/952	Lobby - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2640	ACTIVE	J	B091-00-2/952	Lobby - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3315	ACTIVE	J	B091-00-2/953	Store - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1727	ACTIVE	J	B091-00-2/953	Store - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3316	ACTIVE	J	B091-00-2/954	Disused Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3317	ACTIVE	J	B091-00-2/955	Store - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1728	ACTIVE	J	B091-00-2/955	Store - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3318	ACTIVE	J	B091-00-2/956	Disused Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B091-00 - Station Building - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2354	ACTIVE	J	B091-00-2/956	Disused Room - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3319	ACTIVE	J	B091-00-3/081	Lobby - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1729	ACTIVE	J	B091-00-3/081	Lobby - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3320	ACTIVE	J	B091-00-3/131	LMR - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2641	ACTIVE	J	B091-00-3/131	LMR - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3321	ACTIVE	J	B091-00-3/236	Passage - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1730	ACTIVE	J	B091-00-3/236	Passage - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3322	ACTIVE	J	B091-00-3/237	Passage - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1731	ACTIVE	J	B091-00-3/237	Passage - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3323	ACTIVE	J	B091-00-3/661	Switch Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1732	ACTIVE	J	B091-00-3/661	Switch Room - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3324	ACTIVE	J	B091-00-3/662	Switch Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2642	ACTIVE	J	B091-00-3/662	Switch Room - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3325	ACTIVE	J	B091-00-3/731	CER - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1733	ACTIVE	J	B091-00-3/731	CER - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3326	ACTIVE	J	B091-00-3/776	Plant Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1734	ACTIVE	J	B091-00-3/776	Plant Room - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					



Hazardous Material Asset Register - Summary



B091-00 - Station Building - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3327	ACTIVE	J	B091-00-3/781	Substation Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2355	ACTIVE	J	B091-00-3/781	Substation Room - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3328	ACTIVE	J	B091-00-3/786	Back Up Control Facility (BUCF) - Service Area - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1735	ACTIVE	J	B091-00-3/786	Back Up Control Facility (BUCF) - Service Area - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3329	ACTIVE	J	B091-00-A/132	Office - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3330	ACTIVE	J	B091-00-A/312	Office - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2503	ACTIVE	J	B091-00-A/312	Office - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3331	ACTIVE	J	B091-00-A/321	Office - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3332	ACTIVE	J	B091-00-A/353	Mess Room - Train Crew Accommodation - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3333	ACTIVE	J	B091-00-A/423	Toilet: Unisex - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2643	ACTIVE	J	B091-00-A/423	Toilet: Unisex - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3334	ACTIVE	J	B091-00-A/551	Yard - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
1736	ACTIVE	J	B091-00-A/551	Yard - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected									
3335	ACTIVE	J	B091-00-A/576	Stairs: Linear - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
1737	ACTIVE	J	B091-00-A/576	Stairs: Linear - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected									
3336	ACTIVE	J	B091-00-A/577	Stairs: Linear - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									



Hazardous Material Asset Register - Summary



B091-00 - Station Building - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1738	ACTIVE	J	B091-00-A/577	Stairs: Linear - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected									
3337	ACTIVE	J	B091-00-A/578	Stairs: Linear - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1739	ACTIVE	J	B091-00-A/578	Stairs: Linear - Station Building - Wembley Park Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3338	ACTIVE	J	B091-00-A/579	Store - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2356	ACTIVE	J	B091-00-A/579	Store - Station Building - Wembley Park Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access					
2644	ACTIVE	J	B091-00-A/636	Overbridge - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected				Removed During SMEP					
3339	ACTIVE	J	B091-00-A/904	Switch Cupboard - Train Crew Accommodation - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3340	ACTIVE	J	B091-00-A/951	Waiting Room - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
1740	ACTIVE	J	B091-00-A/951	Waiting Room - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected									
3341	ACTIVE	J	B091-00-A/952	Booking On Point - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1741	ACTIVE	J	B091-00-A/952	Booking On Point - Station Building - Wembley Park Stn	No Access	Asbestos	Surveyed – Not Detected									

B091-15 - Signals Building - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3439	ACTIVE	J	B091-15-1/711	SER - Signals Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3440	ACTIVE	J	B091-15-A/311	SER - Signals Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B093-00 - Station Building - Neasden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3574	ACTIVE	J	B093-00-1/001	Booking Hall - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1296	ACTIVE	J	B093-00-1/001	Booking Hall - Station Building - Neasden Stn	Boarding: Cement	Asbestos	Known				Cementitious horizontal board above window		1			
1297	ACTIVE	J	B093-00-1/001/CLG-01	Ceiling: Suspended - 1 - Booking Hall - Station Building - Neasden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2290	ACTIVE	J	B093-00-1/001/CLG-01	Ceiling: Suspended - 1 - Booking Hall - Station Building - Neasden Stn	Void	Asbestos	Surveyed – Not Detected				Corrugated Steel, Metal Cladding above Supalux tiles				Yes	
3575	ACTIVE	J	B093-00-1/011	Ticket Office - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1299	ACTIVE	J	B093-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Neasden Stn	Void	Asbestos	Surveyed – Not Detected				Supalux tiles, Metal Pipes above False Ceiling				Yes	
2580	ACTIVE	J	B093-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Neasden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Plaster/Supalux					
1298	ACTIVE	J	B093-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Neasden Stn	Void	Asbestos	Surveyed – Not Detected				Debris under Computer Flooring non asbestos					yes
3576	ACTIVE	J	B093-00-1/021	POM - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1300	ACTIVE	J	B093-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Neasden Stn	Void	Asbestos	No Access: Presumed				No access below Computer Flooring					yes
1301	ACTIVE	J	B093-00-1/021/WAL-003	Wall: Internal - 3 - POM - Station Building - Neasden Stn	Other Boarding	Asbestos	Surveyed – Not Detected									
3577	ACTIVE	J	B093-00-1/031	Mess Room - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2488	ACTIVE	J	B093-00-1/031	Mess Room - Station Building - Neasden Stn		Asbestos	Surveyed – Not Detected				0.02m² Acoustic board near sink unit		1			
1302	ACTIVE	J	B093-00-1/031	Mess Room - Station Building - Neasden Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater with rubber backing		1			
3578	ACTIVE	J	B093-00-1/036	Toilet: Unisex - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2581	ACTIVE	J	B093-00-1/036	Toilet: Unisex - Station Building - Neasden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
1303	ACTIVE	J	B093-00-1/082	GLAP - Station Building - Neasden Stn	No Access	Asbestos	Surveyed – Not Detected				New SMEP					



Hazardous Material Asset Register - Summary



B093-00 - Station Building - Neasden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3579	ACTIVE	J	B093-00-1/451	Tenancy - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1304	ACTIVE	J	B093-00-1/451	Tenancy - Station Building - Neasden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3580	ACTIVE	J	B093-00-1/481	Equipment Room - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1305	ACTIVE	J	B093-00-1/481	Equipment Room - Station Building - Neasden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3581	ACTIVE	J	B093-00-1/601	Stairs: Linear - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2582	ACTIVE	J	B093-00-1/601	Stairs: Linear - Station Building - Neasden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3582	ACTIVE	J	B093-00-1/602	Stairs: Linear - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1306	ACTIVE	J	B093-00-1/602	Stairs: Linear - Station Building - Neasden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3583	ACTIVE	J	B093-00-1/603	Stairs: Linear - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1307	ACTIVE	J	B093-00-1/603	Stairs: Linear - Station Building - Neasden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
1308	ACTIVE	J	B093-00-1/636	Overbridge - Station Building - Neasden Stn	Pipe Lagging	Asbestos	Surveyed – Not Detected				Fibreglass					
2538	ACTIVE	J	B093-00-1/637	Overbridge - Station Building - Neasden Stn	Pipe Lagging	Asbestos	Surveyed – Not Detected				Fibreglass					
2583	ACTIVE	J	B093-00-1/637/CLG-01	Ceiling: Solid - 1 - Overbridge - Station Building - Neasden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1309	ACTIVE	J	B093-00-1/637/CLG-01	Ceiling: Solid - 1 - Overbridge - Station Building - Neasden Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				Yes	
3584	ACTIVE	J	B093-00-1/661	Switch Room - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1310	ACTIVE	J	B093-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Neasden Stn	Isolator Switches	Asbestos	Strongly Presumed				1x 100amp iron clad isolator		1			
3585	ACTIVE	J	B093-00-2/081	Lobby - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B093-00 - Station Building - Neasden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2775	ACTIVE	J	B093-00-2/081/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Neasden Stn	Void	Asbestos	No Access: Presumed				No access above Metal Ceiling				Yes	
1311	ACTIVE	J	B093-00-2/081/FLR-01	Floor - 1 - Lobby - Station Building - Neasden Stn	Cable Ducts: Bitumen	Asbestos	Surveyed – Not Detected				0.5m² black cable sleeve - Non asbestos					
3586	ACTIVE	J	B093-00-2/082	Lobby - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1312	ACTIVE	J	B093-00-2/082	Lobby - Station Building - Neasden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3587	ACTIVE	J	B093-00-2/083	Lobby - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2584	ACTIVE	J	B093-00-2/083	Lobby - Station Building - Neasden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3588	ACTIVE	J	B093-00-2/247	Toilet - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3589	ACTIVE	J	B093-00-2/261	Platform 1 - Northbound Fast - Metropolitan Line - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2585	ACTIVE	J	B093-00-2/261	Platform 1 - Northbound Fast - Metropolitan Line - Station Building - Neasden Stn	Pipe Lagging	Asbestos	Surveyed – Not Detected				Fibreglass					
1313	ACTIVE	J	B093-00-2/261	Platform 1 - Northbound Fast - Metropolitan Line - Station Building - Neasden Stn	Lead/Leading	Lead Paint/Lead	Known				Doors - Blue gloss - 50m²				N	N
1314	ACTIVE	J	B093-00-2/261	Platform 1 - Northbound Fast - Metropolitan Line - Station Building - Neasden Stn	Lead/Leading	Lead Paint/Lead	Known				Canopy - Blue gloss - 150m²					
1315	ACTIVE	J	B093-00-2/261	Platform 1 - Northbound Fast - Metropolitan Line - Station Building - Neasden Stn	Lead/Leading	Lead Paint/Lead	Known				Wood beams on stairs - Blue gloss - 30m²					
3590	ACTIVE	J	B093-00-2/262	Platform 2 - Northbound Local - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1316	ACTIVE	J	B093-00-2/262	Platform 2 - Northbound Local - Station Building - Neasden Stn	Lead/Leading	Lead Paint/Lead	Known				Beams - Blue gloss - 150m²					
3591	ACTIVE	J	B093-00-2/263	Platform 3 - Southbound Local - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1317	ACTIVE	J	B093-00-2/263	Platform 3 - Southbound Local - Station Building - Neasden Stn	Lead/Leading	Lead Paint/Lead	Known				Beams - Blue gloss - 150m²					



Hazardous Material Asset Register - Summary



B093-00 - Station Building - Neasden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3592	ACTIVE	J	B093-00-2/264	Platform 4 - Southbound Fast - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2586	ACTIVE	J	B093-00-2/264	Platform 4 - Southbound Fast - Station Building - Neasden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
1318	ACTIVE	J	B093-00-2/264	Platform 4 - Southbound Fast - Station Building - Neasden Stn	Lead/Leading	Lead Paint/Lead	Known				Doors - Blue gloss - 4m²					
3593	ACTIVE	J	B093-00-2/281	Station Supervisor Office - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1319	ACTIVE	J	B093-00-2/281/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Neasden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux and Metal					
2894	ACTIVE	J	B093-00-2/281/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Neasden Stn	Void	Asbestos	Surveyed – Not Detected				Wood boards, Fibre glass Pipe Lagging				Yes	
3594	ACTIVE	J	B093-00-2/331	Mess Room - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1172	ACTIVE	J	B093-00-2/331	Mess Room - Station Building - Neasden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3595	ACTIVE	J	B093-00-2/332	Mess Room - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1173	ACTIVE	J	B093-00-2/332	Mess Room - Station Building - Neasden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3596	ACTIVE	J	B093-00-2/333	Mess Room - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1175	ACTIVE	J	B093-00-2/333	Mess Room - Station Building - Neasden Stn	LUL Heaters	Asbestos	Surveyed – Not Detected						1			
1174	ACTIVE	J	B093-00-2/333/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Neasden Stn	Void	Asbestos	No Access: Presumed				Above Supalux				Yes	
2478	ACTIVE	J	B093-00-2/333/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Neasden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles/Plaster					
3597	ACTIVE	J	B093-00-2/401	CER - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1176	ACTIVE	J	B093-00-2/401/WAL-001	Wall: Internal - 1 - CER - Station Building - Neasden Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 100amp Combination Fuse Switch		1			



Hazardous Material Asset Register - Summary



B093-00 - Station Building - Neasden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3598	ACTIVE	J	B093-00-2/411	Store - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2413	ACTIVE	J	B093-00-2/411	Store - Station Building - Neasden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3599	ACTIVE	J	B093-00-2/412	Store - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1177	ACTIVE	J	B093-00-2/412/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Neasden Stn	Void	Asbestos	No Access: Presumed				Above - Wood Ceiling				Yes	
3600	ACTIVE	J	B093-00-2/413	CER - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2479	ACTIVE	J	B093-00-2/413/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Neasden Stn	Void	Asbestos	No Access: Presumed				Above - Plaster on Wood Ceiling				Yes	
3601	ACTIVE	J	B093-00-2/414	Store - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1178	ACTIVE	J	B093-00-2/414/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Neasden Stn	Void	Asbestos	No Access: Presumed				Above - Wood Ceiling				Yes	
3602	ACTIVE	J	B093-00-2/416	Shower Room - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1179	ACTIVE	J	B093-00-2/416	Shower Room - Station Building - Neasden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3603	ACTIVE	J	B093-00-2/426	Toilet: Female - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1181	ACTIVE	J	B093-00-2/426	Toilet: Female - Station Building - Neasden Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater in Nappy Changing area		1			
1180	ACTIVE	J	B093-00-2/426/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Neasden Stn	Void	Asbestos	No Access: Presumed				Above - Metal Panels, Plasterboards				Yes	
3604	ACTIVE	J	B093-00-2/427	Toilet: Male - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2934	ACTIVE	J	B093-00-2/427/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Neasden Stn	Void	Asbestos	Surveyed – Not Detected				Above Metal Panels - Concrete Fibre glass backing on metal tiles Fibre glass pipe lagging				Yes	
3605	ACTIVE	J	B093-00-2/428	Toilet: Disabled - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2285	ACTIVE	J	B093-00-2/428/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Neasden Stn	Void	Asbestos	Surveyed – Not Detected				Side Wood Panels		1		Yes	



Hazardous Material Asset Register - Summary



B093-00 - Station Building - Neasden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3606	ACTIVE	J	B093-00-2/436	Waiting Room - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1182	ACTIVE	J	B093-00-2/436	Waiting Room - Station Building - Neasden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3607	ACTIVE	J	B093-00-2/551	Yard - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2708	ACTIVE	J	B093-00-2/551	Yard - Station Building - Neasden Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3608	ACTIVE	J	B093-00-2/661	Switch Room - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2483	ACTIVE	J	B093-00-2/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Neasden Stn	Isolator Switches	Asbestos	Strongly Presumed				9x Combination Fuse Switches (3 blue & 3 grey isolator supported on iron framework, 2 blue isolators - 3x30amps, 4x60amps, 2x100amps		9			
3609	ACTIVE	J	B093-00-2/662	Switch Room - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1184	ACTIVE	J	B093-00-2/662/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Neasden Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				3 x Transformer Boxes		2		N	N
42036	ACTIVE	J	B093-00-2/662/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Neasden Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 30amp Isolator Switch		1		N	N
1183	ACTIVE	J	B093-00-2/662/WAL-007	Wall: Internal - 7 - Switch Room - Station Building - Neasden Stn	Isolator Switches	Asbestos	Strongly Presumed				4 x Combination fuse switches 3 x 60, 1x100amp		4		N	N
3610	ACTIVE	J	B093-00-2/663	Switch Room - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed				Note: on Door SID Number 0/661, and not 2/663, Station Layout Incorrect 2x Combination fuse switch 1x60amp, 1x30amp					
2709	ACTIVE	J	B093-00-2/663/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Neasden Stn	Isolator Switches	Asbestos	Strongly Presumed				2x Combination fuse switch 1x60amp, 1x30amp		2		N	N
3611	ACTIVE	J	B093-00-2/711	CER - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
1185	ACTIVE	J	B093-00-2/711	CER - Station Building - Neasden Stn		Asbestos	Surveyed – Not Detected				Not Surveyed - New Build					
3612	ACTIVE	J	B093-00-2/731	CER - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3613	ACTIVE	J	B093-00-2/732	CER - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									



Hazardous Material Asset Register - Summary



B093-00 - Station Building - Neasden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1186	ACTIVE	J	B093-00-2/732	CER - Station Building - Neasden Stn	No Access	Asbestos	Surveyed – Not Detected									
3614	ACTIVE	J	B093-00-2/746	SCR - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1187	ACTIVE	J	B093-00-2/746	SCR - Station Building - Neasden Stn	No Access	Asbestos	Surveyed – Not Detected									
3615	ACTIVE	J	B093-00-2/761	Equipment Room - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1189	INACTIVE	J	B093-00-2/761/CLG-01	Ceiling: Suspended - 1 - Equipment Room - Station Building - Neasden Stn	Void	Asbestos	No Access: Presumed				Above - Metal Panels				Yes	
1188	INACTIVE	J	B093-00-2/761/FLR-01	Floor - 1 - Equipment Room - Station Building - Neasden Stn	Void	Asbestos	No Access: Presumed				Beneath - Metal Panels					YES
3616	ACTIVE	J	B093-00-2/901	Store - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1191	ACTIVE	J	B093-00-2/901/CLG-01 80824011	Ceiling: Solid - 1 - Store - Station Building - Neasden Stn Ceiling: Solid	Void	Asbestos	No Access: Presumed				Above - New suspended & Wooden Slats				Yes	
2414	ACTIVE	J	B093-00-2/901/WAL-002	Wall: Internal - 2 - Store - Station Building - Neasden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2710	ACTIVE	J	B093-00-2/901/WAL-004	Wall: Internal - 4 - Store - Station Building - Neasden Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
3617	ACTIVE	J	B093-00-2/951	Disused Room - Station Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2531	ACTIVE	J	B093-00-2/951	Disused Room - Station Building - Neasden Stn		Asbestos	Surveyed – Not Detected				Toilet Cistern					
1193	ACTIVE	J	B093-00-2/951	Disused Room - Station Building - Neasden Stn	Cable Ducts: Bitumen	Asbestos	Surveyed – Not Detected				4x 100mm Ducts to Invert - Non Asbestos (Bitumen)		4			
67866	ACTIVE	J	B093-00-2/951	Disused Room - Station Building - Neasden Stn	Bitumen	Asbestos	Presumed				Composite toilet cistern. Identified within cubicle at time of HMT Re-inspection.		1			
1194	ACTIVE	J	B093-00-2/951	Disused Room - Station Building - Neasden Stn	Pipe Lagging	Asbestos	Surveyed – Not Detected				Fibre Glass Pipe Lagging, Cistern - Non asbestos					
1192	ACTIVE	J	B093-00-2/951/CLG-01 80824020	Ceiling: Suspended - 1 - Disused Room - Station Building - Neasden Stn Ceiling: Suspended	Void	Asbestos	No Access: Presumed				Above - suspended tiles and wood				Yes	



Hazardous Material Asset Register - Summary



B095-00 - Station Building - Dollis Hill Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3621	ACTIVE	J	B095-00-1/001	Booking Hall - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2711	ACTIVE	J	B095-00-1/001	Booking Hall - Station Building - Dollis Hill Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Glass Rock Boxing Board on wall					
1195	ACTIVE	J	B095-00-1/001/CLG-01	Ceiling: Suspended - 1 - Booking Hall - Station Building - Dollis Hill Stn	Void	Asbestos	Surveyed – Not Detected				Above - 2 No. 8m Pipes above False Ceiling				Yes	
3622	ACTIVE	J	B095-00-1/011	Ticket Office - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1196	ACTIVE	J	B095-00-1/011	Ticket Office - Station Building - Dollis Hill Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3623	ACTIVE	J	B095-00-1/021	POM - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1249	ACTIVE	J	B095-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Dollis Hill Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Soft tiles					
1247	ACTIVE	J	B095-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Dollis Hill Stn	Void	Asbestos	Surveyed – Not Detected				Block Work, Concrete, Metal Pipes above False Ceiling				Yes	
1245	ACTIVE	J	B095-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Dollis Hill Stn	Other Boarding	Asbestos	Sampled – Not Detected				Soft tiles (sampled - non asbestos)					
2725	ACTIVE	J	B095-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Dollis Hill Stn	Void	Asbestos	Sampled – Not Detected				Boarding on LHS (sampled - non asbestos) AFC				Yes	
3624	ACTIVE	J	B095-00-1/031	Mess Room - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1248	ACTIVE	J	B095-00-1/031	Mess Room - Station Building - Dollis Hill Stn	LUL Heaters	Asbestos	Surveyed – Not Detected						1			
1246	ACTIVE	J	B095-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Dollis Hill Stn	Other Boarding	Asbestos	Sampled – Not Detected				Soft tiles (sampled - non asbestos)					
3625	ACTIVE	J	B095-00-1/036	Toilet: Unisex - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2249	ACTIVE	J	B095-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Dollis Hill Stn	Void	Asbestos	No Access: Presumed				Above - Soft Ceiling Tiles				Yes	
3626	ACTIVE	J	B095-00-1/081	Lobby - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2534	ACTIVE	J	B095-00-1/081	Lobby - Station Building - Dollis Hill Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



Hazardous Material Asset Register - Summary



B095-00 - Station Building - Dollis Hill Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3627	ACTIVE	J	B095-00-1/201	Passage - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2288	ACTIVE	J	B095-00-1/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Dollis Hill Stn	Void	Asbestos	No Access: Presumed				Above - Metal Slots				Yes	
3628	ACTIVE	J	B095-00-1/202	Passage - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1250	ACTIVE	J	B095-00-1/202/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Dollis Hill Stn	Void	Asbestos	No Access: Presumed				Above - Corrugated Roof				Yes	
3629	ACTIVE	J	B095-00-1/406	Store - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2726	ACTIVE	J	B095-00-1/406	Store - Station Building - Dollis Hill Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3630	ACTIVE	J	B095-00-1/411	Store - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1251	ACTIVE	J	B095-00-1/411	Store - Station Building - Dollis Hill Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3631	ACTIVE	J	B095-00-1/412	Station Supervisor Office - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1252	ACTIVE	J	B095-00-1/412	Station Supervisor Office - Station Building - Dollis Hill Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3632	ACTIVE	J	B095-00-1/551	Yard - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1253	ACTIVE	J	B095-00-1/551	Yard - Station Building - Dollis Hill Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3633	ACTIVE	J	B095-00-1/661	Switch Room - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2727	ACTIVE	J	B095-00-1/661	Switch Room - Station Building - Dollis Hill Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
45065	ACTIVE	J	B095-00-1/661	Switch Room - Station Building - Dollis Hill Stn	Other Electrical Boxes	Asbestos	Presumed				1 x transformer box - to wall 3		1			



Hazardous Material Asset Register - Summary



B095-00 - Station Building - Dollis Hill Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
45067	ACTIVE	J	B095-00-1/661	Switch Room - Station Building - Dollis Hill Stn	Other Electrical Boxes	Asbestos	Removed				7 combination fuse switches to wall 2 - Combination Fuse switches removed on 18/11/2007 PH HMU Serial Isolator Asset Asbestos no no 000043 00387432 No 000044 00387431 No 000045 00387430 No 000046 00387433 No 000047 00387426 No 000048 00387424 No 000049					
45068	ACTIVE	J	B095-00-1/661	Switch Room - Station Building - Dollis Hill Stn	Other Electrical Boxes	Asbestos	Presumed				1 x combination fuse switch to wall 4		1			
45066	ACTIVE	J	B095-00-1/661	Switch Room - Station Building - Dollis Hill Stn	Other Boarding	Asbestos	Presumed				1 x transformer box wall 1		1			
2485	ACTIVE	J	B095-00-1/661	Switch Room - Station Building - Dollis Hill Stn	Lead/Leading	Lead Paint/Lead	Known				Blue Oil based - 2sqm Thickness : 0.10mm Analysis : 1.4%					
67867	ACTIVE	J	B095-00-1/661/ WAL-002 80818400	Wall: Internal - 2 - Switch Room - Station Building - Dollis Hill Stn Wall: Internal	Isolator Switches	Asbestos	Presumed				Combination fuse switches 5x Blue 2x Grey		7			
1254	ACTIVE	J	B095-00-1/661/ WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Dollis Hill Stn	Other Electrical Boxes	Asbestos	Presumed				3 x Transformer Boxes		3		N	N
3634	ACTIVE	J	B095-00-1/662	Switch Cupboard - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1255	ACTIVE	J	B095-00-1/662/ FLR-01	Floor - 1 - Switch Cupboard - Station Building - Dollis Hill Stn	Cable Duct: Other	Asbestos	Sampled – Not Detected				2 No. Pipe Sleeves (sampled - non asbestos)		2			
2570	ACTIVE	J	B095-00-1/662/ WAL-001	Wall: Internal - 1 - Switch Cupboard - Station Building - Dollis Hill Stn	Isolator Switches	Asbestos	Strongly Presumed				1x 200amp Combination Fuse Switch		1			
3635	ACTIVE	J	B095-00-1/746	SCR - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2250	ACTIVE	J	B095-00-1/746	SCR - Station Building - Dollis Hill Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3636	ACTIVE	J	B095-00-1/771	Pump Room - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1257	ACTIVE	J	B095-00-1/771/ WAL-001	Wall: Internal - 1 - Pump Room - Station Building - Dollis Hill Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x 30amp Iron Clad Isolators		2		N	N
1256	ACTIVE	J	B095-00-1/771/ WAL-002	Wall: Internal - 2 - Pump Room - Station Building - Dollis Hill Stn	Gasket :Pipework	Asbestos	Surveyed – Not Detected				Gasket around Pipe - Rubber		1			



Hazardous Material Asset Register - Summary



B095-00 - Station Building - Dollis Hill Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3637	ACTIVE	J	B095-00-1/951	Disused Room - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1259	ACTIVE	J	B095-00-1/951	Disused Room - Station Building - Dollis Hill Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3638	ACTIVE	J	B095-00-A/261	Platform 1 - Northbound Local - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1260	ACTIVE	J	B095-00-A/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Dollis Hill Stn	Other Boarding	Asbestos	Sampled – Not Detected				Boarding over Canopy		1			
3639	ACTIVE	J	B095-00-A/262	Platform 2 - Southbound Local - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1261	ACTIVE	J	B095-00-A/262	Platform 2 - Southbound Local - Station Building - Dollis Hill Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3640	ACTIVE	J	B095-00-A/281	Office - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2571	ACTIVE	J	B095-00-A/281/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Dollis Hill Stn	Void	Asbestos	No Access: Presumed				Above - Plasterboard				Yes	
3641	ACTIVE	J	B095-00-A/341	CER - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2535	ACTIVE	J	B095-00-A/341	CER - Station Building - Dollis Hill Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - No Asbestos Detected		1			
2774	INACTIVE	J	B095-00-A/341/FLR-01	Floor - 1 - CER - Station Building - Dollis Hill Stn	Vinyl tiles	Asbestos	Removed				Previously sampled NADIS - Floor Tiles have since been removed - confirmed by HMU re inspection team 30/01/2015				N	N
3642	ACTIVE	J	B095-00-A/411	Store - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1262	ACTIVE	J	B095-00-A/411/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Dollis Hill Stn	Other Boarding	Asbestos	Surveyed – Not Detected									
1263	ACTIVE	J	B095-00-A/411/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Dollis Hill Stn	Void	Asbestos	No Access: Presumed				Above - Boarding (non asbestos)				Yes	
3643	ACTIVE	J	B095-00-A/426	Toilet: Female - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1265	ACTIVE	J	B095-00-A/426/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Dollis Hill Stn	Void	Asbestos	No Access: Presumed				Above - Boarding				Yes	
1264	ACTIVE	J	B095-00-A/426/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Dollis Hill Stn	Other Boarding	Asbestos	Sampled – Not Detected				Boarding sampled - non asbestos					



Hazardous Material Asset Register - Summary



B095-00 - Station Building - Dollis Hill Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3644	ACTIVE	J	B095-00-A/427	Toilet: Male - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1266	ACTIVE	J	B095-00-A/427	Toilet: Male - Station Building - Dollis Hill Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Hatch above toilet on the right - Board above (non asbestos),				yes	
1267	ACTIVE	J	B095-00-A/427	Toilet: Male - Station Building - Dollis Hill Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater inside Cupboard		1			
1268	ACTIVE	J	B095-00-A/427	Toilet: Male - Station Building - Dollis Hill Stn	Void	Asbestos	Surveyed – Not Detected				Hatch above cleaning cupboard - Timber plus tiled outside, heater inside					
2572	ACTIVE	J	B095-00-A/427/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Dollis Hill Stn	Glazing Rope	Asbestos	Surveyed – Not Detected				Glass - no asbestos detected					
3645	ACTIVE	J	B095-00-A/428	Toilet: Disabled - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1197	ACTIVE	J	B095-00-A/428/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Dollis Hill Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plaster Board					
1198	ACTIVE	J	B095-00-A/428/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Dollis Hill Stn	Void	Asbestos	Surveyed – Not Detected				Timber Boarding above Plaster Board				Yes	
3646	ACTIVE	J	B095-00-A/436	Waiting Room - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2712	ACTIVE	J	B095-00-A/436/CLG-01	Ceiling: Solid - 1 - Waiting Room - Station Building - Dollis Hill Stn	No Access	Asbestos	No Access: Presumed				Above - Boards					
3647	ACTIVE	J	B095-00-A/601	Stairs: Linear - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1199	ACTIVE	J	B095-00-A/601	Stairs: Linear - Station Building - Dollis Hill Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3648	ACTIVE	J	B095-00-A/661	Switch Room - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1200	ACTIVE	J	B095-00-A/661/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Dollis Hill Stn	Void	Asbestos	No Access: Presumed				Above - Boards				Yes	
2415	ACTIVE	J	B095-00-A/661/WAL-002 80818486	Wall: Internal - 2 - Switch Room - Station Building - Dollis Hill Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Wall 2 - 4 x Combination fuse switches - 3 x 60amps, 1 x 100 amps		4		N	N
3649	ACTIVE	J	B095-00-A/662	CEC - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1201	INACTIVE	J	B095-00-A/662/WAL-001	Wall: Internal - 1 - CEC - Station Building - Dollis Hill Stn	Isolator Switches	Asbestos	Removed				2 x Isolators switches		2		N	N



Hazardous Material Asset Register - Summary



B095-00 - Station Building - Dollis Hill Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3650	ACTIVE	J	B095-00-A/761	Equipment Room - Station Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1203	ACTIVE	J	B095-00-A/761	Equipment Room - Station Building - Dollis Hill Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					

B097-00 - Station Building - Willesden Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
45165	ACTIVE	J	B097-00-0/001	Station Entrance (Walm Lane A & B) - Station Building - Willesden Green Stn	Glazing Rope	Asbestos	Presumed				Entrance A - Canopy Skylight - Rope Seal				N	N
45166	ACTIVE	J	B097-00-0/001	Station Entrance (Walm Lane A & B) - Station Building - Willesden Green Stn	Glazing Rope	Asbestos	Presumed				Entrance B - Canopy Skylight - Rope Seal				N	N
45168	ACTIVE	J	B097-00-0/001	Station Entrance (Walm Lane A & B) - Station Building - Willesden Green Stn	Lead/Leading	Lead Paint/Lead	Known				Entrance B - Mixed Green/White Gloss Paint to South Canopy				N	N
45167	ACTIVE	J	B097-00-0/001	Station Entrance (Walm Lane A & B) - Station Building - Willesden Green Stn	Lead/Leading	Lead Paint/Lead	Known				Entrance A - Mixed Green/White Gloss Paint to North Canopy				N	N
3659	ACTIVE	J	B097-00-1/001	Booking Hall - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2286	ACTIVE	J	B097-00-1/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Willesden Green Stn	Glazing Rope	Asbestos	Surveyed – Not Detected				Walls - Glazing - Rope Seal not found					
3660	ACTIVE	J	B097-00-1/011	Ticket Office - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1205	ACTIVE	J	B097-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Willesden Green Stn	Glazing Rope	Asbestos	Surveyed – Not Detected				Roof - Removed					
2484	ACTIVE	J	B097-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Willesden Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Metal Pipe, Fibreglass Lagging above Supalux Board		1		Yes	
1204	ACTIVE	J	B097-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Willesden Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected								yes	
2713	ACTIVE	J	B097-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Willesden Green Stn	Void	Asbestos	No Access: Presumed				Beneath - Rubber Tiles					YES
3661	ACTIVE	J	B097-00-1/021	POM - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B097-00 - Station Building - Willesden Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2714	ACTIVE	J	B097-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Willesden Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Supalux Boarding, Ducting Pipe, Tank, Fibreglass above Supalux				Yes	
1207	ACTIVE	J	B097-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Willesden Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1206	ACTIVE	J	B097-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Willesden Green Stn	Void	Asbestos	No Access: Presumed				Beneath - Rubber Tiles					YES
3662	ACTIVE	J	B097-00-1/031	Mess Room - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1208	ACTIVE	J	B097-00-1/031	Mess Room - Station Building - Willesden Green Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - Foam		1			
2532	ACTIVE	J	B097-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Willesden Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Fibreglass Lagging, Solid Pipe above Non Asbestos Board		1		Yes	
41924	ACTIVE	J	B097-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Willesden Green Stn	Void	Asbestos	No Access: Presumed				Ceiling: Suspended - 1 - Mess Room -				Y	N
1209	ACTIVE	J	B097-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Willesden Green Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Boards		1		yes	
1210	ACTIVE	J	B097-00-1/031/SNK-01	Sink - 1 - Mess Room - Station Building - Willesden Green Stn		Asbestos	Surveyed – Not Detected				Acoustic sink panel - Non asbestos		1			
3663	ACTIVE	J	B097-00-1/036	Toilet: Unisex - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1211	ACTIVE	J	B097-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Willesden Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2416	ACTIVE	J	B097-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Willesden Green Stn	Void	Asbestos	Surveyed – Not Detected				Wood, Fibre-Glass, Insulation, Solid above Supalux				Yes	
3664	ACTIVE	J	B097-00-1/081	Lobby - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1213	ACTIVE	J	B097-00-1/081	Lobby - Station Building - Willesden Green Stn	LUL Heaters	Asbestos	Surveyed – Not Detected						1			
1212	ACTIVE	J	B097-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Willesden Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux				Yes	
2715	ACTIVE	J	B097-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Willesden Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									



Hazardous Material Asset Register - Summary



B097-00 - Station Building - Willesden Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3665	ACTIVE	J	B097-00-1/082	Lobby - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1214	ACTIVE	J	B097-00-1/082/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Willesden Green Stn	Void	Asbestos	Surveyed – Not Detected				Above False Ceiling - Wood, Fibre-Glass, Insulation, Solid		1		Yes	
3666	ACTIVE	J	B097-00-1/083	Lobby - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1215	ACTIVE	J	B097-00-1/083/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Willesden Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Fibreglass Lagging above Metal Tiles		1		Yes	
3667	ACTIVE	J	B097-00-1/084	Lobby - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2716	ACTIVE	J	B097-00-1/084	Lobby - Station Building - Willesden Green Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Tennancy lobby for ATM Room					
64547	ACTIVE	J	B097-00-1/085	Lobby - Station Building - Willesden Green Stn		Asbestos	Room: Not Surveyed – Asbestos Presumed				Survey Required					
3668	ACTIVE	J	B097-00-1/236	Passage - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1217	ACTIVE	J	B097-00-1/236	Passage - Station Building - Willesden Green Stn	No Access	Asbestos	No Access: Presumed				Room Not Surveyed - Private Dwelling					
3669	ACTIVE	J	B097-00-1/311	Office - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2533	ACTIVE	J	B097-00-1/311/CLG-01 80846258	Ceiling: Suspended - 1 - Office - Station Building - Willesden Green Stn Ceiling: Suspended	Glazing Rope	Asbestos	Presumed				No access to windows to sample rope AFC (behind ATM)				yes	
1221	ACTIVE	J	B097-00-1/311/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Willesden Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1222	ACTIVE	J	B097-00-1/311/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Willesden Green Stn	Void	Asbestos	Surveyed – Not Detected				Above Supalux - Concrete, Metal Pipes		1		Yes	
3670	ACTIVE	J	B097-00-1/411	Store - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1225	ACTIVE	J	B097-00-1/411	Store - Station Building - Willesden Green Stn	No Access	Asbestos	Surveyed – Not Detected									



Hazardous Material Asset Register - Summary



B097-00 - Station Building - Willesden Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3671	ACTIVE	J	B097-00-1/412	Toilet: Disabled - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1226	ACTIVE	J	B097-00-1/412	Toilet: Disabled - Station Building - Willesden Green Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3672	ACTIVE	J	B097-00-1/426	Toilet: Male - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1229	ACTIVE	J	B097-00-1/426	Toilet: Male - Station Building - Willesden Green Stn	Glazing Rope	Asbestos	Presumed				No access to windows to sample rope, no access above false ceiling tiles No access above false ceiling during 2020 re-inspection. Photo of false ceiling					
3673	ACTIVE	J	B097-00-1/427	Toilet: Female - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1230	ACTIVE	J	B097-00-1/427/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Willesden Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Metal Piping, Fibreglass Lagging, Wood Framed Window - above Metal Tiles		1		Yes	
3674	ACTIVE	J	B097-00-1/451	Tenancy - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1231	ACTIVE	J	B097-00-1/451	Tenancy - Station Building - Willesden Green Stn	No Access	Asbestos	Surveyed – Not Detected									
3675	ACTIVE	J	B097-00-1/452	Tenancy - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2721	ACTIVE	J	B097-00-1/452	Tenancy - Station Building - Willesden Green Stn	No Access	Asbestos	Surveyed – Not Detected									
3676	ACTIVE	J	B097-00-1/453	Tenancy - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1232	ACTIVE	J	B097-00-1/453	Tenancy - Station Building - Willesden Green Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Tenancy					
3677	ACTIVE	J	B097-00-1/454	Tenancy - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1233	ACTIVE	J	B097-00-1/454	Tenancy - Station Building - Willesden Green Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Tenancy					
3678	ACTIVE	J	B097-00-1/455	Tenancy - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B097-00 - Station Building - Willesden Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1234	ACTIVE	J	B097-00-1/455	Tenancy - Station Building - Willesden Green Stn	No Access	Asbestos	Surveyed – Not Detected									
3679	ACTIVE	J	B097-00-1/456	Tenancy - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2722	ACTIVE	J	B097-00-1/456	Tenancy - Station Building - Willesden Green Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Tenancy					
3680	ACTIVE	J	B097-00-1/457	Tenancy - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1235	ACTIVE	J	B097-00-1/457	Tenancy - Station Building - Willesden Green Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Tenancy					
3681	ACTIVE	J	B097-00-1/458	ATM - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2287	ACTIVE	J	B097-00-1/458/ WAL-001	Wall: Internal - 1 - ATM - Station Building - Willesden Green Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Wall 1-5 -30-60m² Suspect boarding panel -front set of panels 30-60m² Boarding behind front panels					
1236	ACTIVE	J	B097-00-1/458/ WAL-002	Wall: Internal - 2 - ATM - Station Building - Willesden Green Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Wall 1-5 -30-60m² Suspect boarding panel -front set of panels 30-60m² Boarding behind front panels					
2418	ACTIVE	J	B097-00-1/458/ WAL-003	Wall: Internal - 3 - ATM - Station Building - Willesden Green Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Wall 1-5 -30-60m² Suspect boarding panel -front set of panels- Non Asbestos 30-60m² Boarding behind front panels - Non Asbestos					
1237	ACTIVE	J	B097-00-1/458/ WAL-004	Wall: Internal - 4 - ATM - Station Building - Willesden Green Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Wall 1-5 -30-60m² Suspect boarding panel -front set of panels 30-60m² Boarding behind front panels					
2723	ACTIVE	J	B097-00-1/458/ WAL-005	Wall: Internal - 5 - ATM - Station Building - Willesden Green Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Wall 1-5 -30-60m² Suspect boarding panel -front set of panels 30-60m² Boarding behind front panels					
3682	ACTIVE	J	B097-00-1/459	Tenancy - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1238	ACTIVE	J	B097-00-1/459	Tenancy - Station Building - Willesden Green Stn	No Access	Asbestos	No Access: Presumed				Room Not Surveyed					
3683	ACTIVE	J	B097-00-1/460	Office - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1239	ACTIVE	J	B097-00-1/460	Office - Station Building - Willesden Green Stn	No Access	Asbestos	No Access: Presumed				Room Not Surveyed					



Hazardous Material Asset Register - Summary



B097-00 - Station Building - Willesden Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3684	ACTIVE	J	B097-00-1/461	Tenancy - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1240	ACTIVE	J	B097-00-1/461	Tenancy - Station Building - Willesden Green Stn	No Access	Asbestos	No Access: Presumed				Room Not Surveyed					
3685	ACTIVE	J	B097-00-1/462	Tenancy - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1241	ACTIVE	J	B097-00-1/462	Tenancy - Station Building - Willesden Green Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Tennancy					
3686	ACTIVE	J	B097-00-1/576	Stairs: Linear - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1242	ACTIVE	J	B097-00-1/576	Stairs: Linear - Station Building - Willesden Green Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3687	ACTIVE	J	B097-00-1/601	Stairs: Linear - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1243	ACTIVE	J	B097-00-1/601/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Willesden Green Stn	Glazing Rope	Asbestos	Surveyed – Not Detected				Type 3 Survey confirms Rubber Window Seals					
3688	ACTIVE	J	B097-00-1/602	Stairs: Linear - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2724	ACTIVE	J	B097-00-1/602/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Willesden Green Stn	Glazing Rope	Asbestos	Surveyed – Not Detected				Type 3 Survey confirms Rubber Window Seals					
3689	ACTIVE	J	B097-00-1/603	Stairs: Linear - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1244	ACTIVE	J	B097-00-1/603/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Willesden Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete - Above False Ceiling		1		Yes	
3690	ACTIVE	J	B097-00-1/661	Switch Room - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1321	ACTIVE	J	B097-00-1/661/FLR-01	Floor - 1 - Switch Room - Station Building - Willesden Green Stn	Cable Duct: Other	Asbestos	Presumed				Filled in. Fire stopping appears - New (2020 re inspection)		6		N	N
2587	ACTIVE	J	B097-00-1/661/WAL-002 80846443	Wall: Internal - 2 - Switch Room - Station Building - Willesden Green Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				1 x 30 amps switch box		1		N	N



Hazardous Material Asset Register - Summary



B097-00 - Station Building - Willesden Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1320	ACTIVE	J	B097-00-1/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Willesden Green Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				3 x Transformer Boxes		3		N	N
1323	ACTIVE	J	B097-00-1/711	SER - Station Building - Willesden Green Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
64581	ACTIVE	J	B097-00-1/732	Central Equipment - Station Building - Willesden Green Stn	Other Electrical Boxes	Asbestos	Presumed				Wall 4 Combination fuse switch x 2 - SP 2 x 60 amp		2			
3691	ACTIVE	J	B097-00-1/746	SCR - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2588	ACTIVE	J	B097-00-1/746	SCR - Station Building - Willesden Green Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3692	ACTIVE	J	B097-00-2/066	Car Park - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1327	ACTIVE	J	B097-00-2/066	Car Park - Station Building - Willesden Green Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3693	ACTIVE	J	B097-00-2/081	Lobby - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1328	ACTIVE	J	B097-00-2/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Willesden Green Stn	Void	Asbestos	No Access: Presumed				Above - Supalux Ceiling				Yes	
2539	ACTIVE	J	B097-00-2/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Willesden Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
3694	ACTIVE	J	B097-00-2/082	Lobby - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1329	ACTIVE	J	B097-00-2/082/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Willesden Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2783	ACTIVE	J	B097-00-2/082/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Willesden Green Stn	Void	Asbestos	Surveyed – Not Detected				Brick, Timber & Fibre Glass Lagging - Above Supalux Ceiling		1		Yes	
3695	ACTIVE	J	B097-00-2/236	Passage - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3696	ACTIVE	J	B097-00-2/237	Passage - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2590	ACTIVE	J	B097-00-2/237	Passage - Station Building - Willesden Green Stn	Pipe Lagging	Asbestos	Surveyed – Not Detected				Pipe lagging throughout - Non asbestos		1			



Hazardous Material Asset Register - Summary



B097-00 - Station Building - Willesden Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3697	ACTIVE	J	B097-00-2/238	Passage - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2255	ACTIVE	J	B097-00-2/238	Passage - Station Building - Willesden Green Stn	Pipe Lagging	Asbestos	Surveyed – Not Detected				Pipe lagging throughout - Non asbestos		1			
3698	ACTIVE	J	B097-00-2/261	Platform 1 - Northbound Fast - Metropolitan Line - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1453	INACTIVE	J	B097-00-2/261	Platform 1 - Northbound Fast - Metropolitan Line - Station Building - Willesden Green Stn	Cable: Sheath	Asbestos	Presumed				Black Cables - Platform 1 Tail Wall near IMR Black cables not present during 2020 re-inspection					
1330	ACTIVE	J	B097-00-2/261	Platform 1 - Northbound Fast - Metropolitan Line - Station Building - Willesden Green Stn		Asbestos	Surveyed – Not Detected				Cable runs trackside to platforms - All Cables - PVC		1			
69472	ACTIVE	J	B097-00-2/261	Platform 1 - Northbound Fast - Metropolitan Line - Station Building - Willesden Green Stn	Lead/Leading	Lead Paint/Lead	Known				White gloss paint applied to column - 1.68%			R739610		
69475	ACTIVE	J	B097-00-2/261	Platform 1 - Northbound Fast - Metropolitan Line - Station Building - Willesden Green Stn	Lead/Leading	Lead Paint/Lead	Known				Green gloss paint applied to column - 17.9%			R739610		
69471	ACTIVE	J	B097-00-2/261	Platform 1 - Northbound Fast - Metropolitan Line - Station Building - Willesden Green Stn	Lead/Leading	Lead Paint/Lead	Known				Green gloss paint applied to column - 5.48%			R739610		
69477	ACTIVE	J	B097-00-2/261	Platform 1 - Northbound Fast - Metropolitan Line - Station Building - Willesden Green Stn	Lead/Leading	Lead Paint/Lead	Known				Green gloss paint applied to column - 18.1%			R739610		
69476	ACTIVE	J	B097-00-2/261	Platform 1 - Northbound Fast - Metropolitan Line - Station Building - Willesden Green Stn	Lead/Leading	Lead Paint/Lead	Known				White gloss paint applied to column - 20.7%			R739610		
1331	ACTIVE	J	B097-00-2/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Willesden Green Stn	Glazing Rope	Asbestos	Surveyed – Not Detected				Rope Seal Removed - Glass Roof, Window					
3699	ACTIVE	J	B097-00-2/262	Platform 2 - Northbound Local - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1332	ACTIVE	J	B097-00-2/262	Platform 2 - Northbound Local - Station Building - Willesden Green Stn		Asbestos	Surveyed – Not Detected				Cable runs trackside to platforms - All Cables - PVC		1			
2650	ACTIVE	J	B097-00-2/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - Willesden Green Stn	Glazing Rope	Asbestos	Surveyed – Not Detected				Rope Seal Removed - Glass Roof, Window					
3700	ACTIVE	J	B097-00-2/263	Platform 3 - Southbound Local - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B097-00 - Station Building - Willesden Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2489	ACTIVE	J	B097-00-2/263	Platform 3 - Southbound Local - Station Building - Willesden Green Stn		Asbestos	Surveyed – Not Detected				Cable runs trackside to platforms - All Cables - PVC		1			
1333	ACTIVE	J	B097-00-2/263/CLG-01	Ceiling: Solid - 1 - Platform 3 - Station Building - Willesden Green Stn	Glazing Rope	Asbestos	Surveyed – Not Detected				Rope Seal Removed - Glass Roof, Window					
3701	ACTIVE	J	B097-00-2/264	Platform 4 - Southbound Fast - Metropolitan Line - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1334	ACTIVE	J	B097-00-2/264	Platform 4 - Southbound Fast - Metropolitan Line - Station Building - Willesden Green Stn		Asbestos	Surveyed – Not Detected				Cable runs trackside to platforms - All Cables - PVC		1			
3702	ACTIVE	J	B097-00-2/281	Station Supervisor Office - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1335	ACTIVE	J	B097-00-2/281	Station Supervisor Office - Station Building - Willesden Green Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater x 2 - Foam		2			
1336	ACTIVE	J	B097-00-2/281/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Willesden Green Stn	Glazing Rope	Asbestos	Surveyed – Not Detected				Rope Seal around Window has been removed, Glass Roof					
3703	ACTIVE	J	B097-00-2/291	Admin Office - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2651	ACTIVE	J	B097-00-2/291	Admin Office - Station Building - Willesden Green Stn	LUL Heaters	Asbestos	Surveyed – Not Detected						1			
2256	ACTIVE	J	B097-00-2/291/CLG-01	Ceiling: Suspended - 1 - Admin Office - Station Building - Willesden Green Stn	Void	Asbestos	No Access: Presumed				Above - False Ceiling - Wooden Slabs, Bricks				Yes	
3704	ACTIVE	J	B097-00-2/316	Locker Room - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2652	ACTIVE	J	B097-00-2/316	Locker Room - Station Building - Willesden Green Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater x 2 - Foam		2			
1337	ACTIVE	J	B097-00-2/316/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Willesden Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected								yes	
1338	ACTIVE	J	B097-00-2/316/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Willesden Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux		1		Yes	
3705	ACTIVE	J	B097-00-2/341	Locker Room - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B097-00 - Station Building - Willesden Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3706	ACTIVE	J	B097-00-2/351	Mess Room - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1339	ACTIVE	J	B097-00-2/351	Mess Room - Station Building - Willesden Green Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Heater - Foam		1			
1341	ACTIVE	J	B097-00-2/351/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Willesden Green Stn	Void	Asbestos	Surveyed – Not Detected				Brick Wall, Timber Roof, Fibre Glass		1		Yes	
1340	ACTIVE	J	B097-00-2/351/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Willesden Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
3707	ACTIVE	J	B097-00-2/406	Store - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2653	ACTIVE	J	B097-00-2/406	Store - Station Building - Willesden Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Wall - Supalux Panel Above Box					
3708	ACTIVE	J	B097-00-2/411	Store - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1342	ACTIVE	J	B097-00-2/411/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Willesden Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1437	ACTIVE	J	B097-00-2/411/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Willesden Green Stn	Void	Asbestos	No Access: Presumed				Above - Supalux				Yes	
3709	ACTIVE	J	B097-00-2/412	Store - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2680	ACTIVE	J	B097-00-2/412/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Willesden Green Stn	Glazing Rope	Asbestos	No Access: Presumed				No Access to Window to Sample AFC				yes	
1438	ACTIVE	J	B097-00-2/412/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Willesden Green Stn	Void	Asbestos	Surveyed – Not Detected				Above False Ceiling - All walls - Solid				Yes	
3710	INACTIVE	J	B097-00-2/413	Store - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2295	ACTIVE	J	B097-00-2/413/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Willesden Green Stn	Glazing Rope	Asbestos	Known				Rope Seal Glass roof, Window					
1439	ACTIVE	J	B097-00-2/413/WAL-00180846947	Wall: Internal - 1 - Store - Station Building - Willesden Green Stn Wall: Internal	Boarding: AIB	Asbestos	Strongly Presumed				High level boards on walls (8m2) - Amosite. Enclosed behind cladding panels.					



Hazardous Material Asset Register - Summary



B097-00 - Station Building - Willesden Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1440	ACTIVE	J	B097-00-2/413/ WAL-003 80846949	Wall: Internal - 3 - Store - Station Building - Willesden Green Stn Wall: Internal	Boarding: AIB	Asbestos	Known				External High level boards on walls (8m2) - Amosite. Enclosed behind cladding panels.	8				
3711	ACTIVE	J	B097-00-2/414	Toilet - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1441	ACTIVE	J	B097-00-2/414	Toilet - Station Building - Willesden Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux partition wall and on the inside of door					
2493	ACTIVE	J	B097-00-2/414/ CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Willesden Green Stn	Glazing Rope	Asbestos	Surveyed – Not Detected				Glass, no rope detected					
3712	ACTIVE	J	B097-00-2/415	Store - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1442	ACTIVE	J	B097-00-2/415	Store - Station Building - Willesden Green Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3713	ACTIVE	J	B097-00-2/416	Toilet: Unisex - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2681	ACTIVE	J	B097-00-2/416	Toilet: Unisex - Station Building - Willesden Green Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Supalux partition wall and on the inside of door		1			
3714	ACTIVE	J	B097-00-2/417	Toilet: Unisex - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2543	ACTIVE	J	B097-00-2/417	Toilet: Unisex - Station Building - Willesden Green Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - No Access					
3715	ACTIVE	J	B097-00-2/426	Mess Room - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1443	ACTIVE	J	B097-00-2/426/ CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Willesden Green Stn	Glazing Rope	Asbestos	Surveyed – Not Detected				Rope Seal has been removed.Glass Roof.					
3716	ACTIVE	J	B097-00-2/436	Waiting Room - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1444	ACTIVE	J	B097-00-2/436	Waiting Room - Station Building - Willesden Green Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Window Heater - Reinforced Glass		1			
3717	ACTIVE	J	B097-00-2/451	Tenancy - Station Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1445	ACTIVE	J	B097-00-2/451	Tenancy - Station Building - Wembley Park Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Tenancy					



Hazardous Material Asset Register - Summary



B097-00 - Station Building - Willesden Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3718	ACTIVE	J	B097-00-2/576	Stairs: Linear - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2682	ACTIVE	J	B097-00-2/576	Stairs: Linear - Station Building - Willesden Green Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3719	ACTIVE	J	B097-00-2/577	Stairs: Linear - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2792	ACTIVE	J	B097-00-2/577	Stairs: Linear - Station Building - Willesden Green Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed					
3720	ACTIVE	J	B097-00-2/578	Stairs: Linear - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1446	ACTIVE	J	B097-00-2/578	Stairs: Linear - Station Building - Willesden Green Stn	Pipe Lagging	Asbestos	Surveyed – Not Detected				Pipe lagging throughout non asbestos		1			
3721	ACTIVE	J	B097-00-2/661	Switch Room - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2683	INACTIVE	J	B097-00-2/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Willesden Green Stn	Isolator Switches	Asbestos	Strongly Presumed				1x 30 amp Combination fuse switch. Flash Guards removed 17/11/07 Pectel		1			
1448	ACTIVE	J	B097-00-2/661/WAL-001 80846771	Wall: Internal - 1 - Switch Room - Station Building - Willesden Green Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				(9) 1 x 300 amps, 1 x 30 amps, 7 x 100 amps		9			
43979	ACTIVE	J	B097-00-2/661/WAL-002 80846772	Wall: Internal - 2 - Switch Room - Station Building - Willesden Green Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				1 switch box wall 2 with asbestos free sticker (presumed - unable to open and confirm NAD)		1			
1449	ACTIVE	J	B097-00-2/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Willesden Green Stn	Isolator Switches	Asbestos	Surveyed – Not Detected				1 x 60 amps		1			
43978	ACTIVE	J	B097-00-2/661/WAL-004 80846774	Wall: Internal - 4 - Switch Room - Station Building - Willesden Green Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				2 x switch boxes		2			
1447	ACTIVE	J	B097-00-2/661/WAL-005 80846775	Wall: Internal - 5 - Switch Room - Station Building - Willesden Green Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box - black		1			
64607	ACTIVE	J	B097-00-2/662	Central Equipment - Station Building - Willesden Green Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				combination fuse switches x 2 - SP wall 4 1 x 30amp 1 x60amp		2			
64608	ACTIVE	J	B097-00-2/663	Signal Equipment - Station Building - Willesden Green Stn		Asbestos	Room: Not Surveyed – Asbestos Presumed				Survey Required					
3722	ACTIVE	J	B097-00-2/706	IMR - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B097-00 - Station Building - Willesden Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1452	INACTIVE	J	B097-00-2/706	IMR - Station Building - Willesden Green Stn	Cable: Sheath	Asbestos	Presumed				Black Cables - Platform 1 Tail Wall near IMR Confirmed not found - 2020 re inspection					
2333	ACTIVE	J	B097-00-2/706/WAL-002	Wall: Internal - 2 - - Station Building - Willesden Green Stn	Cable: Sheath	Asbestos	Presumed				Yellow Cables to Electricity Switch					
43991	INACTIVE	J	B097-00-2/706/WAL-002	Wall: Internal - 2 - - Station Building - Willesden Green Stn	PCBs	Polychlorinated biphenyl	Presumed				5 x PCB's Wall 2					
3723	ACTIVE	J	B097-00-2/732	CER - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2684	ACTIVE	J	B097-00-2/732	CER - Station Building - Willesden Green Stn	No Access	Asbestos	Surveyed – Not Detected				New Room - Not Surveyed					
3724	ACTIVE	J	B097-00-2/801	Office - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1457	ACTIVE	J	B097-00-2/801	Office - Station Building - Willesden Green Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Foam boarding		1			
1456	ACTIVE	J	B097-00-2/801/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Willesden Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Fibreglass Lagging above Supalux		1		Yes	
1455	ACTIVE	J	B097-00-2/801/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Willesden Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
3725	ACTIVE	J	B097-00-2/901	GSM Office - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2685	ACTIVE	J	B097-00-2/901	GSM Office - Station Building - Willesden Green Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Foam boarding		1			
3726	ACTIVE	J	B097-00-2/902	Store - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1458	ACTIVE	J	B097-00-2/902	Store - Station Building - Willesden Green Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3727	ACTIVE	J	B097-00-2/903	Store - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2887	ACTIVE	J	B097-00-2/903	Store - Station Building - Willesden Green Stn	Lagging	Asbestos	Surveyed – Not Detected				Old Boiler					
3728	ACTIVE	J	B097-00-2/951	Store - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1459	ACTIVE	J	B097-00-2/951	Store - Station Building - Willesden Green Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



Hazardous Material Asset Register - Summary



B097-00 - Station Building - Willesden Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3729	ACTIVE	J	B097-00-2/952	CER - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2686	ACTIVE	J	B097-00-2/952/WAL-001 80846845	Wall: Internal - 1 - CER - Station Building - Willesden Green Stn Wall: Internal	Other Boarding	Asbestos	Removed				Paxoline Board. Now removed.		1			
2687	ACTIVE	J	B097-00-2/952/WAL-002	Wall: Internal - 2 - CER - Station Building - Willesden Green Stn	Cable Duct: Other	Asbestos	Presumed				Ducts Sealed		8			
1460	ACTIVE	J	B097-00-2/952/WAL-004	Wall: Internal - 4 - CER - Station Building - Willesden Green Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box		1			
3730	ACTIVE	J	B097-00-2/953	Disused Room - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1461	ACTIVE	J	B097-00-2/953	Disused Room - Station Building - Willesden Green Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3731	ACTIVE	J	B097-00-3/732	CER - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3732	ACTIVE	J	B097-00-A/047	Kitchen - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2544	ACTIVE	J	B097-00-A/047	Kitchen - Station Building - Willesden Green Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Private Dwelling					
3733	ACTIVE	J	B097-00-A/236	Passage - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1462	ACTIVE	J	B097-00-A/236	Passage - Station Building - Willesden Green Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Private Dwelling					
3734	ACTIVE	J	B097-00-A/411	Store - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1463	ACTIVE	J	B097-00-A/411	Store - Station Building - Willesden Green Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Private Dwelling					
3735	ACTIVE	J	B097-00-A/416	Toilet: Female - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1464	ACTIVE	J	B097-00-A/416	Toilet: Female - Station Building - Willesden Green Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Private Dwelling					
3736	ACTIVE	J	B097-00-A/417	Toilet: Male - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1465	ACTIVE	J	B097-00-A/417	Toilet: Male - Station Building - Willesden Green Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Private Dwelling					



Hazardous Material Asset Register - Summary



B097-00 - Station Building - Willesden Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3737	ACTIVE	J	B097-00-A/576	Stairs: Linear - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2688	ACTIVE	J	B097-00-A/576	Stairs: Linear - Station Building - Willesden Green Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Private Dwelling					
3738	ACTIVE	J	B097-00-A/801	Office - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2334	ACTIVE	J	B097-00-A/801	Office - Station Building - Willesden Green Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Private Dwelling					
3739	ACTIVE	J	B097-00-A/802	Office - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1466	ACTIVE	J	B097-00-A/802	Office - Station Building - Willesden Green Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Private Dwelling					
3740	ACTIVE	J	B097-00-A/803	Office - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1467	ACTIVE	J	B097-00-A/803	Office - Station Building - Willesden Green Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Private Dwelling					
3741	ACTIVE	J	B097-00-A/804	Office - Station Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2494	ACTIVE	J	B097-00-A/804	Office - Station Building - Willesden Green Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Private Dwelling					

B103-00 - Station Building - Kilburn Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3758	ACTIVE	J	B103-00-1/001	Booking Hall - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45173	ACTIVE	J	B103-00-1/001	Booking Hall - Station Building - Kilburn Stn	Cellactite Sheeting	Asbestos	Known				10m² Cellactite corrugated tunnel lining (black fibrous) - in ceiling void above false ceiling	10			Y	N
1468	ACTIVE	J	B103-00-1/001	Booking Hall - Station Building - Kilburn Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3759	ACTIVE	J	B103-00-1/011	Ticket Office - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
42220	ACTIVE	J	B103-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Kilburn Stn	Mastic	Asbestos	Sampled – Not Detected				3m light grey mastic to A/C ductwork above false ceiling	3			Y	N



Hazardous Material Asset Register - Summary



B103-00 - Station Building - Kilburn Stn																
Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42222	ACTIVE	J	B103-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Kilburn Stn	Other Boarding	Asbestos	Presumed				Brown composite panel to wall above false ceiling (limited access)				Y	N
42219	ACTIVE	J	B103-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Kilburn Stn	Mastic	Asbestos	Sampled – Not Detected				2m yellow mastic to A/C ductwork above false ceiling - NADIS	2			Y	N
2689	ACTIVE	J	B103-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Kilburn Stn	Cable Duct: Other	Asbestos	Surveyed – Not Detected				Terracotta duct with foam insulation				N	N
42218	ACTIVE	J	B103-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Kilburn Stn	Debris: Other	Asbestos	Sampled – Not Detected				Dust and Debris beneath the floor throughout - NADIS Dust and Debris to Cable Pit beneath false floor - NADIS				N	Y
42221	ACTIVE	J	B103-00-1/011/WLS	Walls: Internal - Ticket Office - Station Building - Kilburn Stn		Asbestos	Surveyed – Not Detected				Plasterboard panels to partition wall above false ceiling. A/C ductwork some with MMMF to walls above false ceiling. MMMF insulation debris				Y	N
3760	ACTIVE	J	B103-00-1/021	POM - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45174	ACTIVE	J	B103-00-1/021	POM - Station Building - Kilburn Stn	Other Electrical Boxes	Asbestos	Presumed				In metal POM cabins				N	N
1469	ACTIVE	J	B103-00-1/021	POM - Station Building - Kilburn Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3761	ACTIVE	J	B103-00-1/031	Mess Room - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1470	ACTIVE	J	B103-00-1/031	Mess Room - Station Building - Kilburn Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
45175	ACTIVE	J	B103-00-1/031	Mess Room - Station Building - Kilburn Stn	LUL Heaters	Asbestos	Presumed				LBT Heater				N	N
3762	ACTIVE	J	B103-00-1/036	Toilet: Unisex - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1471	ACTIVE	J	B103-00-1/036	Toilet: Unisex - Station Building - Kilburn Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3763	ACTIVE	J	B103-00-1/081	Lobby - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2690	ACTIVE	J	B103-00-1/081/FLR-01	Floor - 1 - Lobby - Station Building - Kilburn Stn	Void	Asbestos	No Access: Presumed				Beneath - Rubber Tiles					YES
45265	INACTIVE	J	B103-00-1/081/WAL-004 80819448	Wall: Internal - 4 - Lobby - Station Building - Kilburn Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				7 no Electrical boxes. No electrical equipment identified.		7		N	N



Hazardous Material Asset Register - Summary



B103-00 - Station Building - Kilburn Stn																
Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3764	ACTIVE	J	B103-00-1/082	Passage - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2335	ACTIVE	J	B103-00-1/082/FLR-01	Floor - 1 - Passage - Station Building - Kilburn Stn	Void	Asbestos	No Access: Presumed				Beneath - Rubber Tiles					YES
1472	INACTIVE	J	B103-00-1/082/WAL-003 80819461	Wall: Internal - 3 - Passage - Station Building - Kilburn Stn Wall: Internal	Other Boarding	Asbestos	Presumed				Paxoline Board. Removed.					
3765	ACTIVE	J	B103-00-1/083	Lobby - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1473	ACTIVE	J	B103-00-1/083/FLR-01	Floor - 1 - Lobby - Station Building - Kilburn Stn	Void	Asbestos	No Access: Presumed				Beneath - Rubber Tiles					YES
3766	ACTIVE	J	B103-00-1/084	Lobby - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1474	ACTIVE	J	B103-00-1/084	Lobby - Station Building - Kilburn Stn	No Access	Asbestos	Surveyed – Not Detected				New Room - Not Surveyed					
3767	ACTIVE	J	B103-00-1/131	LMR - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1475	ACTIVE	J	B103-00-1/131	LMR - Station Building - Kilburn Stn	No Access	Asbestos	Surveyed – Not Detected				New Room - Not Surveyed					
2784	ACTIVE	J	B103-00-1/136	Lift Shaft - Station Building - Kilburn Stn	No Access	Asbestos	Surveyed – Not Detected				New Room - Not Surveyed					
3768	ACTIVE	J	B103-00-1/236	Passage - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1476	ACTIVE	J	B103-00-1/236/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Kilburn Stn	Boarding: Cement	Asbestos	Known				Asbestos known area under stairs - panels between stair cases - Cement		2			
45266	INACTIVE	J	B103-00-1/236/WAL-003 80819511	Wall: Internal - 3 - Passage - Station Building - Kilburn Stn Wall: Internal	Other Electrical Boxes	Asbestos	Known				Isolator switch box. No older electrical equipment identified.		1		N	N
3769	ACTIVE	J	B103-00-1/281	Station Supervisor Office - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2691	ACTIVE	J	B103-00-1/281	Station Supervisor Office - Station Building - Kilburn Stn	No Access	Asbestos	Surveyed – Not Detected				New Room - Not Surveyed					
3770	ACTIVE	J	B103-00-1/311	Office - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1477	ACTIVE	J	B103-00-1/311	Office - Station Building - Kilburn Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



Hazardous Material Asset Register - Summary



B103-00 - Station Building - Kilburn Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3771	ACTIVE	J	B103-00-1/407	Store - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2545	ACTIVE	J	B103-00-1/407	Store - Station Building - Kilburn Stn	No Access	Asbestos	Surveyed – Not Detected				New Room - Not Surveyed					
3772	ACTIVE	J	B103-00-1/412	Store - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1478	ACTIVE	J	B103-00-1/412	Store - Station Building - Kilburn Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3773	ACTIVE	J	B103-00-1/426	Toilet: Female - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1479	ACTIVE	J	B103-00-1/426/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Kilburn Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling - Fibreglass insulation on Ceiling Tiles		1		Yes	
3774	ACTIVE	J	B103-00-1/427	Toilet: Male - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2917	ACTIVE	J	B103-00-1/427/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Kilburn Stn	Void	Asbestos	Surveyed – Not Detected				Above False Ceiling - Fibreglass insulation on ceiling tiles & pipework		1		Yes	
2692	ACTIVE	J	B103-00-1/427/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Kilburn Stn	Cellactite Sheeting	Asbestos	Known				Corrugated tunnel lining -Chrysotile (Non Visible No Access above ceiling)				Yes	
3775	ACTIVE	J	B103-00-1/451	Tenancy - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1480	ACTIVE	J	B103-00-1/451	Tenancy - Station Building - Kilburn Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3776	ACTIVE	J	B103-00-1/452	Tenancy - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1481	ACTIVE	J	B103-00-1/452	Tenancy - Station Building - Kilburn Stn	No Access	Asbestos	No Access: Presumed				Room Not Surveyed					
3777	ACTIVE	J	B103-00-1/551	Yard - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1482	ACTIVE	J	B103-00-1/551	Yard - Station Building - Kilburn Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3778	ACTIVE	J	B103-00-1/661	Switch Cupboard - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1483	ACTIVE	J	B103-00-1/661	Switch Cupboard - Station Building - Kilburn Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



Hazardous Material Asset Register - Summary



B103-00 - Station Building - Kilburn Stn																
Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
45267	INACTIVE	J	B103-00-1/661/WAL-002 80819661	Wall: Internal - 2 - Switch Cupboard - Station Building - Kilburn Stn Wall: Internal		Asbestos	Presumed				Distribution board red spot. Now removed. No older electrical equipment identified.				N	N
3779	ACTIVE	J	B103-00-1/662	Switch Room - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45268	INACTIVE	J	B103-00-1/662	Switch Room - Station Building - Kilburn Stn		Asbestos	Presumed				Red Spot Board - electrical insulation. Now removed.				N	N
1484	ACTIVE	J	B103-00-1/662/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Kilburn Stn	Isolator Switches	Asbestos	Strongly Presumed				Electrical Box X 2 Wall 1		2			
2693	ACTIVE	J	B103-00-1/662/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Kilburn Stn	Other Electrical Boxes	Asbestos	Presumed				1 x Transformer Box		1			
1485	ACTIVE	J	B103-00-1/662/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Kilburn Stn	Isolator Switches	Asbestos	Strongly Presumed				6 x Isolators 3 x 100 amps, 1 x 200 amps, 2 x 60amp		6			
25715	ACTIVE	J	B103-00-1/662/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Kilburn Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x 60amp Switch Box		1			
3780	ACTIVE	J	B103-00-1/663	Passage - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45271	ACTIVE	J	B103-00-1/663	Passage - Station Building - Kilburn Stn	Cable Duct: Other	Asbestos	Presumed				Cable Ducts to ceiling at high level				N	N
1343	ACTIVE	J	B103-00-1/663	Passage - Station Building - Kilburn Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
45270	ACTIVE	J	B103-00-1/663	Passage - Station Building - Kilburn Stn		Asbestos	Presumed				Metal trunking and supply fan to ceiling at high level				N	N
3781	ACTIVE	J	B103-00-1/664	Switch Room - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1344	ACTIVE	J	B103-00-1/664	Switch Room - Station Building - Kilburn Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3782	ACTIVE	J	B103-00-1/665	Switch Cupboard - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
41913	ACTIVE	J	B103-00-1/665	Switch Cupboard - Station Building - Kilburn Stn	Isolator Switches	Asbestos	Strongly Presumed				1 x Switch Box				N	N
2654	ACTIVE	J	B103-00-1/665	Switch Cupboard - Station Building - Kilburn Stn	No Access	Asbestos	Room: Surveyed: Asbestos Strongly Presumed				Room Not Surveyed					
45269	ACTIVE	J	B103-00-1/665	Switch Cupboard - Station Building - Kilburn Stn	Other Electrical Boxes	Asbestos	Presumed				3 x Transformer Boxes		3		N	N



Hazardous Material Asset Register - Summary



B103-00 - Station Building - Kilburn Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3783	ACTIVE	J	B103-00-1/712	SER - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1345	ACTIVE	J	B103-00-1/712	SER - Station Building - Kilburn Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
3784	ACTIVE	J	B103-00-1/731	CER - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3785	ACTIVE	J	B103-00-1/746	SCR - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3786	ACTIVE	J	B103-00-1/776	Plant Room - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3787	ACTIVE	J	B103-00-A/081	Lobby - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1346	ACTIVE	J	B103-00-A/081	Lobby - Station Building - Kilburn Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3788	ACTIVE	J	B103-00-A/261	Platform 1 - Northbound Local - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1348	ACTIVE	J	B103-00-A/261	Platform 1 - Northbound Local - Station Building - Kilburn Stn	Boarding: Cement	Asbestos	Surveyed – Not Detected				Cement boarding (shuttering) to foot of bridge					
45272	ACTIVE	J	B103-00-A/261	Platform 1 - Northbound Local - Station Building - Kilburn Stn	Glazing Rope	Asbestos	Presumed				Rope gaskets - Skylight to canopy				N	N
1347	ACTIVE	J	B103-00-A/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Kilburn Stn		Asbestos	Surveyed – Not Detected				Fire rated Ceiling Material Mineral Felt on Roof					
2655	ACTIVE	J	B103-00-A/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Kilburn Stn		Asbestos	Surveyed – Not Detected				Fire rated ceiling material, wooden structure above false ceiling				yes	
3789	ACTIVE	J	B103-00-A/262	Platform 2 - Southbound Local - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45273	ACTIVE	J	B103-00-A/262	Platform 2 - Southbound Local - Station Building - Kilburn Stn	Glazing Rope	Asbestos	Presumed				Rope gaskets - Skylight to canopy				N	N
3790	ACTIVE	J	B103-00-A/331	Mess Room - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1349	ACTIVE	J	B103-00-A/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Kilburn Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									



Hazardous Material Asset Register - Summary



B103-00 - Station Building - Kilburn Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1350	ACTIVE	J	B103-00-A/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Kilburn Stn	Void	Asbestos	No Access: Presumed				Above Sulalux Ceiling				Yes	
3791	ACTIVE	J	B103-00-A/411	Store - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1352	ACTIVE	J	B103-00-A/411/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Kilburn Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard Ceiling				Yes	
1351	ACTIVE	J	B103-00-A/411/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Kilburn Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
3792	ACTIVE	J	B103-00-A/412	Store - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2656	ACTIVE	J	B103-00-A/412/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Kilburn Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
1353	ACTIVE	J	B103-00-A/412/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Kilburn Stn	Void	Asbestos	No Access: Presumed				Above Plasterboard Ceiling				Yes	
3793	ACTIVE	J	B103-00-A/426	Toilet: Female - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2257	ACTIVE	J	B103-00-A/426/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Kilburn Stn	Void	Asbestos	No Access: Presumed				Above the Supalux Ceiling				Yes	
1354	ACTIVE	J	B103-00-A/426/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Kilburn Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1355	ACTIVE	J	B103-00-A/426/WCP-01	WC Pan - 1 - Toilet - Station Building - Kilburn Stn	Void	Asbestos	No Access: Presumed				No access to Riser behind toilet					
3794	ACTIVE	J	B103-00-A/427	Toilet: Male - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1356	ACTIVE	J	B103-00-A/427/WCP-01	WC Pan - 1 - Toilet - Station Building - Kilburn Stn	Void	Asbestos	No Access: Presumed				No access to Riser behind toilet					
3795	ACTIVE	J	B103-00-A/428	Toilet: Disabled - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1357	ACTIVE	J	B103-00-A/428/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Kilburn Stn	Void	Asbestos	No Access: Presumed				Above the Supalux Ceiling				Yes	
2657	ACTIVE	J	B103-00-A/428/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Kilburn Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1358	ACTIVE	J	B103-00-A/428/WCP-01	WC Pan - 1 - Toilet - Station Building - Kilburn Stn	Void	Asbestos	No Access: Presumed				No access to Boxing behind toilet					



Hazardous Material Asset Register - Summary



B103-00 - Station Building - Kilburn Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3796	ACTIVE	J	B103-00-A/429	Toilet: Unisex - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1359	ACTIVE	J	B103-00-A/429/ SNK-01	Sink - 1 - Toilet - Station Building - Kilburn Stn	Void	Asbestos	No Access: Presumed				No access to Boxing below sink					
3797	ACTIVE	J	B103-00-A/436	Waiting Room - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2658	ACTIVE	J	B103-00-A/436/ CLG-01	Ceiling: Suspended - 1 - Waiting Room - Station Building - Kilburn Stn	Glazing Rope	Asbestos	Strongly Presumed				4m Rope Seal on Skylight					
1360	ACTIVE	J	B103-00-A/436/ CLG-01	Ceiling: Suspended - 1 - Waiting Room - Station Building - Kilburn Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Ceiling 35m²					
3798	ACTIVE	J	B103-00-A/601	Stairs: Linear - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1361	ACTIVE	J	B103-00-A/601	Stairs: Linear - Station Building - Kilburn Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3799	ACTIVE	J	B103-00-A/661	Switch Room - Station Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1362	ACTIVE	J	B103-00-A/661/ CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Kilburn Stn	Durasteel	Asbestos	Surveyed – Not Detected				8m² Durasteel false ceiling					
2291	ACTIVE	J	B103-00-A/661/ CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Kilburn Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				6m² Supalux					
1363	ACTIVE	J	B103-00-A/661/ CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Kilburn Stn	Void	Asbestos	No Access: Presumed				Above- false ceiling				Yes	
2490	ACTIVE	J	B103-00-A/661/ WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Kilburn Stn	Isolator Switches	Asbestos	Strongly Presumed				1x Isolator -1 x 60 amps		1			
2659	ACTIVE	J	B103-00-A/661/ WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Kilburn Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				2x Blue electric boxes (no access due to live electricity		2			
1364	ACTIVE	J	B103-00-A/661/ WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Kilburn Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es)		2			
2258	ACTIVE	J	B103-00-A/661/ WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Kilburn Stn	No Access	Asbestos	No Access: Presumed				No access to Metal Trunking					



Hazardous Material Asset Register - Summary



B105-00 - Station Building - West Hampstead Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3804	ACTIVE	J	B105-00-1/001	Booking Hall - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Stone Tiled					
2540	ACTIVE	J	B105-00-1/001	Booking Hall - Station Building - West Hampstead Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible - Suspended Tiles					
3805	ACTIVE	J	B105-00-1/011	Ticket Office - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2673	ACTIVE	J	B105-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - West Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected								yes	
1414	ACTIVE	J	B105-00-1/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - West Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				In Void above Ceiling				Yes	
1365	ACTIVE	J	B105-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - West Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				No Asbestos beneath Suspended Tiles					yes
3806	ACTIVE	J	B105-00-1/021	POM - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1416	ACTIVE	J	B105-00-1/021	POM - Station Building - West Hampstead Stn	Mastic	Asbestos	Surveyed – Not Detected				Air Duct Seal - Non Asbestos Webbing					
1415	ACTIVE	J	B105-00-1/021/FLR-01	Floor - 1 - POM - Station Building - West Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				No Asbestos beneath Suspended Tiles					yes
3807	ACTIVE	J	B105-00-1/031	Mess Room - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1417	ACTIVE	J	B105-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - West Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected								yes	
2674	ACTIVE	J	B105-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - West Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Supalux above Supalux Ceiling				Yes	
3808	ACTIVE	J	B105-00-1/036	Toilet: Unisex - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1421	ACTIVE	J	B105-00-1/036	Toilet: Unisex - Station Building - West Hampstead Stn	Void	Asbestos	No Access: Presumed				Within Supalux Boxing					
1420	ACTIVE	J	B105-00-1/036	Toilet: Unisex - Station Building - West Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Boxing - Supalux					
1418	ACTIVE	J	B105-00-1/036/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - West Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									



Hazardous Material Asset Register - Summary



B105-00 - Station Building - West Hampstead Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1419	ACTIVE	J	B105-00-1/036/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - West Hampstead Stn	Void	Asbestos	No Access: Presumed				Above Supalux Ceiling				Yes	
3809	ACTIVE	J	B105-00-1/081	Lobby - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2330	ACTIVE	J	B105-00-1/081	Lobby - Station Building - West Hampstead Stn	Void	Asbestos	No Access: Presumed				Within Supalux Boxing					
1423	ACTIVE	J	B105-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - West Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Ceiling Void - Concrete				Yes	
1422	ACTIVE	J	B105-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - West Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Ceiling Tiles				yes	
2675	ACTIVE	J	B105-00-1/081/FLR-01	Floor - 1 - Lobby - Station Building - West Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				No Asbestos detected beneath Suspended Tiles					yes
1424	ACTIVE	J	B105-00-1/081/WAL-002	Wall: Internal - 2 - Lobby - Station Building - West Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Boxing - Supalux					
3810	ACTIVE	J	B105-00-1/082	Lobby - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2676	ACTIVE	J	B105-00-1/082/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - West Hampstead Stn	Void	Asbestos	No Access: Presumed				Above Supalux Ceiling				Yes	
1425	ACTIVE	J	B105-00-1/082/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - West Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
3811	ACTIVE	J	B105-00-1/236	Passage - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2331	ACTIVE	J	B105-00-1/236	Passage - Station Building - West Hampstead Stn	Void	Asbestos	No Access: Presumed				Within Supalux Boxing					
1429	ACTIVE	J	B105-00-1/236	Passage - Station Building - West Hampstead Stn	Mastic	Asbestos	Surveyed – Not Detected				Air Duct Seal - Non Asbestos Webbing					
1430	ACTIVE	J	B105-00-1/236	Passage - Station Building - West Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Boxing - Supalux					
1426	ACTIVE	J	B105-00-1/236/WAL-003	Wall: Internal - 3 - Passage - Station Building - West Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1427	ACTIVE	J	B105-00-1/236/WAL-004	Wall: Internal - 4 - Passage - Station Building - West Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									



Hazardous Material Asset Register - Summary



B105-00 - Station Building - West Hampstead Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1428	ACTIVE	J	B105-00-1/236/WAL-022	Wall: Internal - 22 - Passage - Station Building - West Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2677	ACTIVE	J	B105-00-1/236/WAL-023	Wall: Internal - 23 - Passage - Station Building - West Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
3812	ACTIVE	J	B105-00-1/281	Station Supervisor Office - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3813	ACTIVE	J	B105-00-1/406	Store - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1431	ACTIVE	J	B105-00-1/406/CLG-01	Ceiling: Solid - 1 - Store - Station Building - West Hampstead Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling - Fibreboard				Yes	
2294	ACTIVE	J	B105-00-1/406/CLG-01	Ceiling: Solid - 1 - Store - Station Building - West Hampstead Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Fibreboard					
3814	ACTIVE	J	B105-00-1/426	Toilet: Male - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1432	ACTIVE	J	B105-00-1/426/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - West Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Above False Ceiling - Metal Plaster, Fibre Glass backing on Metal Ceiling Tiles				Yes	
3815	ACTIVE	J	B105-00-1/452	Tenancy - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1433	ACTIVE	J	B105-00-1/452/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - West Hampstead Stn	Void	Asbestos	No Access: Presumed				Above Supalux Ceiling				Yes	
2678	ACTIVE	J	B105-00-1/452/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - West Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
3816	ACTIVE	J	B105-00-1/453	Tenancy - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1434	ACTIVE	J	B105-00-1/453	Tenancy - Station Building - West Hampstead Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3817	ACTIVE	J	B105-00-1/454	Tenancy - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1435	ACTIVE	J	B105-00-1/454	Tenancy - Station Building - West Hampstead Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



Hazardous Material Asset Register - Summary



B105-00 - Station Building - West Hampstead Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3818	ACTIVE	J	B105-00-1/601	Stairs: Linear - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1436	ACTIVE	J	B105-00-1/601	Stairs: Linear - Station Building - West Hampstead Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3819	ACTIVE	J	B105-00-1/661	Switch Room - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2332	ACTIVE	J	B105-00-1/661/FLR-01	Floor - 1 - Switch Room - Station Building - West Hampstead Stn	Vinyl tiles	Asbestos	Surveyed – Not Detected				Previously sampled NADIS				N	N
2679	ACTIVE	J	B105-00-1/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - West Hampstead Stn	Isolator Switches	Asbestos	Presumed				1x Isolator Switches wall 1		1		N	N
1366	ACTIVE	J	B105-00-1/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - West Hampstead Stn	Isolator Switches	Asbestos	Presumed				Total -5x Isolator Switches - 4 x 60 amps, 1 x 100 amps wall 3		5		N	N
2879	ACTIVE	J	B105-00-1/661/WAL-003 80842592	Wall: Internal - 3 - Switch Room - Station Building - West Hampstead Stn Wall: Internal	Other Electrical Boxes	Asbestos	Strongly Presumed				1 x Blue Transformer Box wall 3		1		N	N
3820	ACTIVE	J	B105-00-1/746	SCR - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1372	ACTIVE	J	B105-00-1/746	SCR - Station Building - West Hampstead Stn	Void	Asbestos	No Access: Presumed				Within Supalux Boxing					
1371	ACTIVE	J	B105-00-1/746	SCR - Station Building - West Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing					
3821	ACTIVE	J	B105-00-1/786	Service Riser - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1373	ACTIVE	J	B105-00-1/786	Service Riser - Station Building - West Hampstead Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New. Service Riser Cupboard					
3822	ACTIVE	J	B105-00-2/081	Lobby - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1374	ACTIVE	J	B105-00-2/081	Lobby - Station Building - West Hampstead Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3823	ACTIVE	J	B105-00-2/261	Platform 1 - Northbound Local - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2259	ACTIVE	J	B105-00-2/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - West Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Canopy Tile above Train Indicator				yes	



Hazardous Material Asset Register - Summary



B105-00 - Station Building - West Hampstead Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44473	ACTIVE	J	B105-00-2/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - West Hampstead Stn	Rope Gaskets	Asbestos	Presumed				Rope Gaskets to skylight glazing bar across platform 1 & 2				N	N
2292	ACTIVE	J	B105-00-2/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - West Hampstead Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Internal Canopy Tiles				yes	
3824	ACTIVE	J	B105-00-2/262	Platform 2 - Southbound Local - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2661	ACTIVE	J	B105-00-2/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - West Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Canopy Tile above Train Indicator				yes	
1375	ACTIVE	J	B105-00-2/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - West Hampstead Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Internal Canopy Tiles				yes	
3825	ACTIVE	J	B105-00-2/371	Store - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1377	INACTIVE	J	B105-00-2/371	Store - Station Building - West Hampstead Stn	Bitumen	Asbestos	Removed				Acoustic Panel under Sink new New steel sink and worktop confirmed on Management Survey (use changed from store to mess room)		1		N	N
1376	ACTIVE	J	B105-00-2/371/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - West Hampstead Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling				Yes	
3826	ACTIVE	J	B105-00-2/372	Store - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1378	ACTIVE	J	B105-00-2/372/CLG-01	Ceiling: Solid - 1 - Store - Station Building - West Hampstead Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling ? Photo (attached) from premises shows brick with metal girders (Lead Paint?)				Yes	
3827	ACTIVE	J	B105-00-2/401	Bin Store - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1379	ACTIVE	J	B105-00-2/401	Bin Store - Station Building - West Hampstead Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3828	ACTIVE	J	B105-00-2/406	Store - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2662	ACTIVE	J	B105-00-2/406	Store - Station Building - West Hampstead Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3829	ACTIVE	J	B105-00-2/411	Store - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B105-00 - Station Building - West Hampstead Stn																
Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
44601	ACTIVE	J	B105-00-2/411	Store - Station Building - West Hampstead Stn	Other Boarding	Asbestos	Presumed				Brown composite boarding panel		1			
1380	ACTIVE	J	B105-00-2/411	Store - Station Building - West Hampstead Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3830	ACTIVE	J	B105-00-2/416	Toilet: Unisex - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1381	ACTIVE	J	B105-00-2/416	Toilet: Unisex - Station Building - West Hampstead Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3831	ACTIVE	J	B105-00-2/426	Toilet: Female - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Surveyed – Asbestos Known									
2491	ACTIVE	J	B105-00-2/426	Toilet: Female - Station Building - West Hampstead Stn	Paper Asbestos	Asbestos	Known				Anti condensation paper to pipework within false ceiling 30m	30		R731401		
3832	ACTIVE	J	B105-00-2/436	Waiting Room - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2895	ACTIVE	J	B105-00-2/436/CLG-01	Ceiling: Suspended - 1 - Waiting Room - Station Building - West Hampstead Stn	Void	Asbestos	No Access: Presumed				Above Tiles				Yes	
3833	ACTIVE	J	B105-00-2/481	Equipment Room - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2663	ACTIVE	J	B105-00-2/481	Equipment Room - Station Building - West Hampstead Stn	Pipe Lagging	Asbestos	Surveyed – Not Detected				Fibreglass					
3834	ACTIVE	J	B105-00-2/661	Switch Room - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43166	ACTIVE	J	B105-00-2/661	Switch Room - Station Building - West Hampstead Stn	Other Electrical Boxes	Asbestos	Presumed				6x Switch boxes (2x 60amps wall 3 / 3x 100amps wall 2 / 1x20amps wall 2)		6		N	N
1382	ACTIVE	J	B105-00-2/661/FLR-01	Floor - 1 - Switch Room - Station Building - West Hampstead Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				6x Cable sleeves under floor -3x Bitumous,/3x Ceramic 4-rail Survey Non asbestos ducts		3		N	yes
44476	ACTIVE	J	B105-00-2/661/WAL-002 80842771	Wall: Internal - 2 - Switch Room - Station Building - West Hampstead Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				2 transformer boxes to floor by wall 2		2		N	N
3835	ACTIVE	J	B105-00-2/731	CER - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2776	ACTIVE	J	B105-00-2/731	CER - Station Building - West Hampstead Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



Hazardous Material Asset Register - Summary



B105-00 - Station Building - West Hampstead Stn																
Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3836	ACTIVE	J	B105-00-2/761	Equipment Room - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1383	ACTIVE	J	B105-00-2/761	Equipment Room - Station Building - West Hampstead Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
45164	ACTIVE	J	B105-00-2/761/WAL-002	Wall: Internal - 2 - Equipment Room - Station Building - West Hampstead Stn	Other Boarding	Asbestos	Presumed				Black composite panel within cabinet				N	N
3837	ACTIVE	J	B105-00-2/801	Locker Room - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2664	ACTIVE	J	B105-00-2/801/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - West Hampstead Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1385	ACTIVE	J	B105-00-2/801/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - West Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Wood beam painted grey - Bitumous wrapping on pipes				Yes	
1384	ACTIVE	J	B105-00-2/801/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - West Hampstead Stn	Void	Asbestos	Surveyed – Not Detected				Plaster above Supalux				Yes	
2541	ACTIVE	J	B105-00-2/801/FLR-01 80842810	Floor - 1 - Locker Room - Station Building - West Hampstead Stn Floor	Cable: Wrap	Asbestos	Presumed				Bitumous wrapping on pipes - AFC no access on 2024 re-inspection				yes	N
3838	ACTIVE	J	B105-00-2/901	Disused Room - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1386	ACTIVE	J	B105-00-2/901/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - West Hampstead Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling				Yes	
3839	ACTIVE	J	B105-00-2/951	Toilet: Unisex - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1387	ACTIVE	J	B105-00-2/951	Toilet: Unisex - Station Building - West Hampstead Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling					
3840	ACTIVE	J	B105-00-2/952	Toilet: Disabled - Station Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2260	ACTIVE	J	B105-00-2/952	Toilet: Disabled - Station Building - West Hampstead Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling					
71005	ACTIVE	J	B105/J/GRD-01	Girdering - G209 - Station Building - West Hampstead Stn	Lead/Leading	Lead Paint/Lead	Known				Known Lead Paint to Girders G209 Full Report Attached.			R739614		



Hazardous Material Asset Register - Summary



B107-00 - Station Building - Finchley Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3877	ACTIVE	J	B107-00-1/001	Booking Hall - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2665	ACTIVE	J	B107-00-1/001	Booking Hall - Station Building - Finchley Road Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Report Board					
3878	ACTIVE	J	B107-00-1/011	Ticket Office - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1389	ACTIVE	J	B107-00-1/011/CLG-01	Ceiling: Solid - 1 - Ticket Office - Station Building - Finchley Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2666	ACTIVE	J	B107-00-1/011/CLG-01	Ceiling: Solid - 1 - Ticket Office - Station Building - Finchley Road Stn	Void	Asbestos	Surveyed – Not Detected				Wood and Concrete above Supalux Panels				Yes	
1388	ACTIVE	J	B107-00-1/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Finchley Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete and PVC cables					yes
3879	ACTIVE	J	B107-00-1/021	POM - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1392	ACTIVE	J	B107-00-1/021	POM - Station Building - Finchley Road Stn	Pipe Lagging	Asbestos	Surveyed – Not Detected				MMMF lagging to pipe at high level					
2492	ACTIVE	J	B107-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Finchley Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1391	ACTIVE	J	B107-00-1/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Finchley Road Stn	Void	Asbestos	No Access: Presumed				No Access above Supalux Panels due to electric fire alarm				Yes	
1390	ACTIVE	J	B107-00-1/021/FLR-01	Floor - 1 - POM - Station Building - Finchley Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete and PVC cables					yes
3880	ACTIVE	J	B107-00-1/031	Mess Room - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2293	ACTIVE	J	B107-00-1/031	Mess Room - Station Building - Finchley Road Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LUL Heater with foam panel		1			
2261	ACTIVE	J	B107-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Finchley Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels/Fibreboard					
2542	ACTIVE	J	B107-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Finchley Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Panels/ Fibreboard				Yes	
3881	ACTIVE	J	B107-00-1/036	Toilet: Unisex - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B107-00 - Station Building - Finchley Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1393	ACTIVE	J	B107-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Finchley Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels					
2667	ACTIVE	J	B107-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Finchley Road Stn	Void	Asbestos	Surveyed – Not Detected				Above False Ceiling - Concrete				Yes	
3882	ACTIVE	J	B107-00-1/081	Lobby - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1395	ACTIVE	J	B107-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Finchley Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1396	ACTIVE	J	B107-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Finchley Road Stn	Void	Asbestos	Surveyed – Not Detected				Wood and Concrete above Supalux Panels				Yes	
1394	ACTIVE	J	B107-00-1/081/FLR-01	Floor - 1 - Lobby - Station Building - Finchley Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete and PVC Cables beneath Computer Tiles					yes
3883	ACTIVE	J	B107-00-1/082	Lobby - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1397	ACTIVE	J	B107-00-1/082	Lobby - Station Building - Finchley Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3884	ACTIVE	J	B107-00-1/083	Passage - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2668	ACTIVE	J	B107-00-1/083	Passage - Station Building - Finchley Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3885	ACTIVE	J	B107-00-1/181	Forecourt - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1398	ACTIVE	J	B107-00-1/181/CLG-01	Ceiling: Solid - 1 - Forecourt - Station Building - Finchley Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux panel at high level near 1/456					
3886	ACTIVE	J	B107-00-1/401	Bin Store - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1399	ACTIVE	J	B107-00-1/401	Bin Store - Station Building - Finchley Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3887	ACTIVE	J	B107-00-1/407	Store - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1400	ACTIVE	J	B107-00-1/407/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Finchley Road Stn	Void	Asbestos	Surveyed – Not Detected				Solid Above Metal Panels				Yes	



Hazardous Material Asset Register - Summary



B107-00 - Station Building - Finchley Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3888	ACTIVE	J	B107-00-1/426	Toilet: Male - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2328	ACTIVE	J	B107-00-1/426/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Finchley Road Stn	Void	Asbestos	Surveyed – Not Detected				Solid Above Metal Panels				Yes	
3889	ACTIVE	J	B107-00-1/427	SCR - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2669	ACTIVE	J	B107-00-1/427/CLG-01	Ceiling: Suspended - 1 - SCR - Station Building - Finchley Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1402	ACTIVE	J	B107-00-1/427/CLG-01	Ceiling: Suspended - 1 - SCR - Station Building - Finchley Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Panels				Yes	
3890	ACTIVE	J	B107-00-1/429	Toilet: Female - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1403	ACTIVE	J	B107-00-1/429/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Finchley Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1404	ACTIVE	J	B107-00-1/429/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Finchley Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Panels				Yes	
3891	ACTIVE	J	B107-00-1/430	Toilet: Disabled - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1405	ACTIVE	J	B107-00-1/430	Toilet: Disabled - Station Building - Finchley Road Stn	Void	Asbestos	No Access: Presumed				Wooden Boxing to Wall					
2670	ACTIVE	J	B107-00-1/430/CLG-01 80818748	Ceiling: Suspended - 1 - Toilet - Station Building - Finchley Road Stn Ceiling: Suspended	Void	Asbestos	Surveyed – Not Detected				No tiles present. Ceiling is solid concrete.				Yes	
3892	ACTIVE	J	B107-00-1/451	Tenancy - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1406	ACTIVE	J	B107-00-1/451/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Finchley Road Stn	No Access	Asbestos	No Access: Presumed				Above Tiled Ceiling - Visual inspection only					
3893	ACTIVE	J	B107-00-1/453	ATM - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1407	ACTIVE	J	B107-00-1/453	ATM - Station Building - Finchley Road Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - No Access to Lobby					



Hazardous Material Asset Register - Summary



B107-00 - Station Building - Finchley Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3894	ACTIVE	J	B107-00-1/455	Tenancy - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
46351	ACTIVE	J	B107-00-1/455	Tenancy - Station Building - Finchley Road Stn	Non Asbestos Boarding	Asbestos	Sampled – Not Detected				Fibreboard boxing, 2m², to wall	2		R685701	N	N
46349	ACTIVE	J	B107-00-1/455	Tenancy - Station Building - Finchley Road Stn	Gasket :Pipework	Asbestos	Sampled – Not Detected				Hessian gasket, 2no.x1m, to 2no. Inspection access to 2no. Pipes		2	R685701	N	N
1409	ACTIVE	J	B107-00-1/455	Tenancy - Station Building - Finchley Road Stn	Void	Asbestos	No Access: Presumed				Metal Cladding to Wall					
46353	ACTIVE	J	B107-00-1/455	Tenancy - Station Building - Finchley Road Stn	Textured Coating	Asbestos	Known				Textured coating on brickwork, throughout 10m², to walls - Presumed to still be present behind decorative partitioned walls	10		R685701	N	N
46350	ACTIVE	J	B107-00-1/455	Tenancy - Station Building - Finchley Road Stn	Lagging	Asbestos	Sampled – Not Detected				Wire wool packing/insulation, throughout, within and outside boxing to pipework			R685701	N	N
46352	ACTIVE	J	B107-00-1/455	Tenancy - Station Building - Finchley Road Stn	Cable: Sheath	Asbestos	Sampled – Not Detected				Cable wrapping, 1no.x2m, to base of wall from electrical box into riser wall	2	1	R685701	N	N
1408	ACTIVE	J	B107-00-1/455/CLG-01 80818809	Ceiling: Solid - 1 - Tenancy - Station Building - Finchley Road Stn Ceiling: Solid	No Access	Asbestos	Surveyed – Not Detected				Above Tiled Ceiling - No longer a ceiling void, solid ceiling					
3895	ACTIVE	J	B107-00-1/456	Tenancy - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2671	ACTIVE	J	B107-00-1/456/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Finchley Road Stn	Void	Asbestos	No Access: Presumed				Above Tiled Ceiling				Yes	
3896	ACTIVE	J	B107-00-1/551	Yard - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2329	ACTIVE	J	B107-00-1/551	Yard - Station Building - Finchley Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3897	ACTIVE	J	B107-00-1/601	Stairs: Linear - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1410	ACTIVE	J	B107-00-1/601	Stairs: Linear - Station Building - Finchley Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3898	ACTIVE	J	B107-00-1/602	Stairs: Linear - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1411	ACTIVE	J	B107-00-1/602	Stairs: Linear - Station Building - Finchley Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
1412	ACTIVE	J	B107-00-1/636	Overbridge - Station Building - Finchley Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



Hazardous Material Asset Register - Summary



B107-00 - Station Building - Finchley Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3899	ACTIVE	J	B107-00-1/661	Switch Room - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3900	ACTIVE	J	B107-00-1/664	Switch Room - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43167	ACTIVE	J	B107-00-1/664/WAL-001 80818870	Wall: Internal - 1 - Switch Room - Station Building - Finchley Road Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				3 Transformer Box - Asbestos Components Within		3		N	N
68698	ACTIVE	J	B107-00-1/664/WAL-001 80818870	Wall: Internal - 1 - Switch Room - Station Building - Finchley Road Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				1x 30Amps, 2x 60Amps - Asbestos Components Within		3			
2546	ACTIVE	J	B107-00-1/664/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Finchley Road Stn	Other Electrical Boxes	Asbestos	Surveyed – Not Detected				Transformer Boxes		3			
1413	ACTIVE	J	B107-00-1/664/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Finchley Road Stn	Isolator Switches	Asbestos	Surveyed – Not Detected				3 x 60 amp NAD		3			
45359	ACTIVE	J	B107-00-1/664/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Finchley Road Stn	Cable Duct: Other	Asbestos	Presumed				Cable ducts filled in				N	N
2672	ACTIVE	J	B107-00-1/664/WAL-002 80818871	Wall: Internal - 2 - Switch Room - Station Building - Finchley Road Stn Wall: Internal	Isolator Switches	Asbestos	Presumed				5 x 60amps, 1 x 100amps - Asbestos Components Within		6		N	N
43168	ACTIVE	J	B107-00-1/664/WAL-003 80818872	Wall: Internal - 3 - Switch Room - Station Building - Finchley Road Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				1 Transformer Box - Asbestos Components Within		1		N	N
3901	ACTIVE	J	B107-00-1/665	Switch Room - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1486	ACTIVE	J	B107-00-1/665/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Finchley Road Stn	Isolator Switches	Asbestos	Strongly Presumed				Combination Fuse Switches x 4 - 2 x 60 amps, 1 x 100 amps, 1 x 30 amps Labels on Switch Box (NAD) Note Should have a sticker, No asbestos remaining inside, removed as part of SMEP works		4		N	N
3902	ACTIVE	J	B107-00-1/666	Switch Room - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2495	ACTIVE	J	B107-00-1/666	Switch Room - Station Building - Finchley Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Boarding above Door					
3903	ACTIVE	J	B107-00-1/731	Switch Room - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1487	ACTIVE	J	B107-00-1/731	Switch Room - Station Building - Finchley Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



Hazardous Material Asset Register - Summary



B107-00 - Station Building - Finchley Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3904	ACTIVE	J	B107-00-1/732	CER - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43913	ACTIVE	J	B107-00-1/732	CER - Station Building - Finchley Road Stn	Other Boarding	Asbestos	Presumed				Wall 4 - presumed Paxoline boarding behind black box units		1		N	N
2296	ACTIVE	J	B107-00-1/732/FLR-01	Floor - 1 - CER - Station Building - Finchley Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath Computer Tiles					yes
1488	ACTIVE	J	B107-00-1/732/WAL-002	Wall: Internal - 2 - CER - Station Building - Finchley Road Stn	Isolator Switches	Asbestos	Removed				Combination Fuse Switches x 2 - 2 x 60 Amps Boxes of Stickers (NAD) Note Should have a sticker, No asbestos remaining inside, removed as part of SMEP works		2		N	N
3905	ACTIVE	J	B107-00-1/746	SCR - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2694	ACTIVE	J	B107-00-1/746/WAL-003	Wall: Internal - 3 - SCR - Station Building - Finchley Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
3906	ACTIVE	J	B107-00-1/801	Office - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1491	ACTIVE	J	B107-00-1/801	Office - Station Building - Finchley Road Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				LUL Heater with Foam Panel		1			
1490	ACTIVE	J	B107-00-1/801/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Finchley Road Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Panels				Yes	
1489	ACTIVE	J	B107-00-1/801/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Finchley Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
3907	ACTIVE	J	B107-00-2/082	Lobby - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1492	ACTIVE	J	B107-00-2/082/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Finchley Road Stn	Cable: Sheath	Asbestos	Strongly Presumed				One braided green cable at high level on Platform 2, Tail wall, high level cable going into 2/082		1		N	N
3908	ACTIVE	J	B107-00-2/261	Platform 1 - Northbound Fast - Metropolitan Line - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1495	ACTIVE	J	B107-00-2/261	Platform 1 - Northbound Fast - Metropolitan Line - Station Building - Finchley Road Stn	Cable: Sheath	Asbestos	Presumed				Tail Wall 3 x Braided Cable - Existing J hanger Route Not visible from platform		3		N	N
2695	ACTIVE	J	B107-00-2/261	Platform 1 - Northbound Fast - Metropolitan Line - Station Building - Finchley Road Stn	Cable Ducts: Cement	Asbestos	Strongly Presumed				Tail Wall outside 2/661 - 2x high level cable sleeve - Chrysotile		2		N	N



Hazardous Material Asset Register - Summary



B107-00 - Station Building - Finchley Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1493	ACTIVE	J	B107-00-2/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Finchley Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux PanelsFibreboard with Plastic Veneer and					
1494	ACTIVE	J	B107-00-2/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Finchley Road Stn	Void	Asbestos	Surveyed – Not Detected				Wood panels and RSJ's above false ceiling				Yes	
2696	ACTIVE	J	B107-00-2/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Finchley Road Stn	Void	Lead Paint/Lead	Known				High level Steel Supports from Station Canopy Encapsulated				Yes	N
1496	ACTIVE	J	B107-00-2/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Finchley Road Stn	Other Boarding	Asbestos	Strongly Presumed				Boarding in Invert Platform 1				N	N
3909	ACTIVE	J	B107-00-2/262	Platform 2 - Northbound Local - Jubilee Line - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1501	ACTIVE	J	B107-00-2/262	Platform 2 - Northbound Local - Jubilee Line - Station Building - Finchley Road Stn	Other Boarding	Asbestos	Strongly Presumed				Supalux & Panels by 2/436 - Asbestos Strongly Presumed				N	N
1500	INACTIVE	J	B107-00-2/262	Platform 2 - Northbound Local - Jubilee Line - Station Building - Finchley Road Stn	Cement Cowlings/ Flues	Asbestos	Strongly Presumed				Cementitious Flue behind 2/341				N	N
1499	ACTIVE	J	B107-00-2/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - Finchley Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux above Canopy Panels,					
1497	ACTIVE	J	B107-00-2/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - Finchley Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Fibreboard with Plastic Veneer and Supalux Panels					
1498	ACTIVE	J	B107-00-2/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - Finchley Road Stn	Void	Asbestos	Surveyed – Not Detected				Wood panels and RSJ's above False Ceiling				Yes	
2336	ACTIVE	J	B107-00-2/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - Finchley Road Stn	Void	Lead Paint/Lead	Known				High level Steel Supports from Station Canopy Encapsulated				Yes	N
3910	ACTIVE	J	B107-00-2/263	Platform 3 - Southbound Local - Jubilee Line - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1503	ACTIVE	J	B107-00-2/263	Platform 3 - Southbound Local - Jubilee Line - Station Building - Finchley Road Stn	Cable: Sheath	Asbestos	Presumed				1x Braided Cable - end of Platform adjacent to Station Supervisors Office Not visible during inspection could be part of platform grounds		1		N	N
2697	ACTIVE	J	B107-00-2/263/CLG-01	Ceiling: Solid - 1 - Platform 3 - Station Building - Finchley Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Fibreboard with Plastic Veneer and Supalux Panels					
1502	ACTIVE	J	B107-00-2/263/CLG-01	Ceiling: Solid - 1 - Platform 3 - Station Building - Finchley Road Stn	Void	Asbestos	Surveyed – Not Detected				Wood panels and RSJ's above False Ceiling				Yes	



Hazardous Material Asset Register - Summary



B107-00 - Station Building - Finchley Road Stn																
Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1504	ACTIVE	J	B107-00-2/263/CLG-01	Ceiling: Solid - 1 - Platform 3 - Station Building - Finchley Road Stn	Void	Lead Paint/Lead	Known				Steel Supports running through waiting room from Station Canopy Encapsulated				Yes	N
3911	ACTIVE	J	B107-00-2/264	Platform 4 - Southbound Fast - Metropolitan Line - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1505	ACTIVE	J	B107-00-2/264/CLG-01	Ceiling: Solid - 1 - Platform 4 - Station Building - Finchley Road Stn	Void	Lead Paint/Lead	Known				High level Steel Supports from Station Canopy Encapsulated				Yes	N
3912	ACTIVE	J	B107-00-2/271	Pump Room - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3913	ACTIVE	J	B107-00-2/281	Station Supervisor Office - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2698	ACTIVE	J	B107-00-2/281	Station Supervisor Office - Station Building - Finchley Road Stn	Cement Cowlings/ Flues	Asbestos	Known				External wall, 2m from ground - Broken flue - Chrysotile NB Unable to locate at time of 2024 inspection				N	N
3914	ACTIVE	J	B107-00-2/331	Mess Room - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2547	ACTIVE	J	B107-00-2/331	Mess Room - Station Building - Finchley Road Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				One LUL Heater with Foam Panel		1			
2888	ACTIVE	J	B107-00-2/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Finchley Road Stn	Void	Asbestos	Surveyed – Not Detected				Solid above False Ceiling				Yes	
1506	ACTIVE	J	B107-00-2/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Finchley Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
3915	ACTIVE	J	B107-00-2/341	Mess Room - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1507	ACTIVE	J	B107-00-2/341	Mess Room - Station Building - Finchley Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3916	ACTIVE	J	B107-00-2/406	Store - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1508	ACTIVE	J	B107-00-2/406/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Finchley Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2699	ACTIVE	J	B107-00-2/406/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Finchley Road Stn	Void	Asbestos	Surveyed – Not Detected				Solid above False Ceiling				Yes	



Hazardous Material Asset Register - Summary



B107-00 - Station Building - Finchley Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1509	ACTIVE	J	B107-00-2/406/DOR-01	Door - 1 - Store - Station Building - Finchley Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panel above Door					
3917	ACTIVE	J	B107-00-2/407	Store - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3918	ACTIVE	J	B107-00-2/411	Store - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43922	ACTIVE	J	B107-00-2/411	Store - Station Building - Finchley Road Stn	Lead/Leading	Lead Paint/Lead	Presumed				Red grit bin by door to 2/411		1		N	N
43921	ACTIVE	J	B107-00-2/411/DOR-01 80819034	Door - 1 - Store - Station Building - Finchley Road Stn Door	Lead/Leading	Lead Paint/Lead	Presumed				Green lead paint				N	N
3919	ACTIVE	J	B107-00-2/412	Store - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3920	ACTIVE	J	B107-00-2/436	Waiting Room - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2496	ACTIVE	J	B107-00-2/436	Waiting Room - Station Building - Finchley Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				External North Side Wall - Supalux					
1510	ACTIVE	J	B107-00-2/436/CLG-01	Ceiling: Suspended - 1 - Waiting Room - Station Building - Finchley Road Stn	Void	Asbestos	Surveyed – Not Detected				Wooden Beams above False Ceiling				Yes	
3921	ACTIVE	J	B107-00-2/437	Waiting Room - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2297	ACTIVE	J	B107-00-2/437	Waiting Room - Station Building - Finchley Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				External North Side Wall - Supalux					
1511	ACTIVE	J	B107-00-2/437/CLG-01 80819056	Ceiling: Suspended - 1 - Waiting Room - Station Building - Finchley Road Stn Ceiling: Suspended	Void	Asbestos	No Access: Presumed				No Access to Wooden Boxing, presumably within ceiling void				Yes	
3922	ACTIVE	J	B107-00-2/451	Tenancy - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3923	ACTIVE	J	B107-00-2/452	Tenancy - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3924	ACTIVE	J	B107-00-2/481	Computer Equipment Cupboard - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1512	ACTIVE	J	B107-00-2/481/WAL-001	Wall: Internal - 1 - Computer Equipment Cupboard - Station Building - Finchley Road Stn	Void	Asbestos	No Access: Presumed				No Access to Wooden Boxing				yes	



Hazardous Material Asset Register - Summary



B107-00 - Station Building - Finchley Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2700	ACTIVE	J	B107-00-2/481/WAL-003	Wall: Internal - 3 - Computer Equipment Cupboard - Station Building - Finchley Road Stn	Void	Asbestos	No Access: Presumed				No Access to Wooden Boxing				yes	
3925	ACTIVE	J	B107-00-2/487	Store - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1513	ACTIVE	J	B107-00-2/487	Store - Station Building - Finchley Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3926	ACTIVE	J	B107-00-2/661	Switch Room - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2337	ACTIVE	J	B107-00-2/661	Switch Room - Station Building - Finchley Road Stn	Isolator Switches	Asbestos	Strongly Presumed				Note not all switch boxes are not asbestos free 200amp, 2 x 100amp. 15amp, & 30amp, strongly Presumed All others 8 x 60amps, & 1x 100amp should have asbestos free stickers Asset No 387515 Baker Street & No 387514 Finchley Road Substation also should assume asbestos		9			
45361	ACTIVE	J	B107-00-2/661	Switch Room - Station Building - Finchley Road Stn	Other Boarding	Asbestos	Known				6x small panels at rear of box inside isolator - Asbestos Components Within - Unable to inspect to determine quantity of material		6		N	N
1514	ACTIVE	J	B107-00-2/661	Switch Room - Station Building - Finchley Road Stn	Other Electrical Boxes	Asbestos	Presumed				Wall 2 - Transformer Box(es) - Asbestos Components Within		1		N	N
45363	INACTIVE	J	B107-00-2/661	Switch Room - Station Building - Finchley Road Stn	Other Boarding	Asbestos	Known				6x small panel - same for large dark blue CFS		6		N	N
45362	ACTIVE	J	B107-00-2/661	Switch Room - Station Building - Finchley Road Stn	Other Boarding	Asbestos	Known				1x Siluminite panel at rear of box - Asbestos Components Within - Unable to inspect to determine quantity		1		N	N
45364	ACTIVE	J	B107-00-2/661/WAL-003 80819087	Wall: Internal - 3 - Switch Room - Station Building - Finchley Road Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				Transformer Box - Asbestos Components Within		1		N	N
68699	ACTIVE	J	B107-00-2/661/WAL-004 80819088	Wall: Internal - 4 - Switch Room - Station Building - Finchley Road Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				1 x 300Amps Combination Switch - Asbestos Components Within		1			
3927	ACTIVE	J	B107-00-2/662	Switch Room - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1515	ACTIVE	J	B107-00-2/662/WAL-002 80819093	Wall: Internal - 2 - Switch Room - Station Building - Finchley Road Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Note not all switch boxes are not asbestos free 1 x 63amp The other boxes Should have a stickers, No asbestos remaining inside, removed as part of SMEP works 1 x 100amps, 2 x 30amps, 1 x 60amps		5		N	N
3928	ACTIVE	J	B107-00-2/663	Switch Room - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B107-00 - Station Building - Finchley Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1516	ACTIVE	J	B107-00-2/663/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Finchley Road Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				3x Supalux Panels					
2701	ACTIVE	J	B107-00-2/663/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Finchley Road Stn	Void	Asbestos	No Access: Presumed				No Access above Supalux Panels				Yes	
3929	ACTIVE	J	B107-00-2/665	Switch Room - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43914	ACTIVE	J	B107-00-2/665	Switch Room - Station Building - Finchley Road Stn	No Access	Asbestos	No Access: Presumed				No access below man-holes				N	Y
1517	ACTIVE	J	B107-00-2/665/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Finchley Road Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected									
43915	ACTIVE	J	B107-00-2/665/WAL-007 80819116	Wall: Internal - 7 - Switch Room - Station Building - Finchley Road Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				3x transformer boxes hidden behind metal mesh - Asbestos Components Within		3		N	N
3930	ACTIVE	J	B107-00-2/711	Relay Room - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1519	ACTIVE	J	B107-00-2/711/CLG-01	Ceiling: Solid - 1 - Relay Room - Station Building - Finchley Road Stn	Void	Asbestos	No Access: Presumed				No Access above Metal Panels				Yes	
45360	ACTIVE	J	B107-00-2/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Finchley Road Stn		Asbestos	No Access: Presumed				Metal panels				N	N
1518	ACTIVE	J	B107-00-2/711/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Finchley Road Stn	Cable: Sheath	Asbestos	Strongly Presumed				Walls - 3no Braided Cables		3		N	N
43918	ACTIVE	J	B107-00-2/711/WAL-002 80819126	Wall: Internal - 2 - Relay Room - Station Building - Finchley Road Stn Wall: Internal	Other Boarding	Asbestos	Presumed				Paxoline boarding				N	N
43919	ACTIVE	J	B107-00-2/711/WAL-003 80819127	Wall: Internal - 3 - Relay Room - Station Building - Finchley Road Stn Wall: Internal	Other Boarding	Asbestos	Presumed				Various bits of Paxoline boarding				N	N
43916	INACTIVE	J	B107-00-2/711/WAL-003 80819127	Wall: Internal - 3 - Relay Room - Station Building - Finchley Road Stn Wall: Internal	PCBs	Polychlorinated biphenyl	Presumed				Presumed PCBs; 7 x black units. No signs of leakage.		7		N	N
43917	ACTIVE	J	B107-00-2/711/WAL-004 80819128	Wall: Internal - 4 - Relay Room - Station Building - Finchley Road Stn Wall: Internal	Other Boarding	Asbestos	Presumed				Various bits of paxoline boarding				N	N
3931	ACTIVE	J	B107-00-2/762	Equipment Room - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B107-00 - Station Building - Finchley Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1520	ACTIVE	J	B107-00-2/762	Equipment Room - Station Building - Finchley Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3932	ACTIVE	J	B107-00-2/763	Equipment Room - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2702	ACTIVE	J	B107-00-2/763	Equipment Room - Station Building - Finchley Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3933	INACTIVE	J	B107-00-2/771	Pump Room - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2338	ACTIVE	J	B107-00-2/771/WAL-001	Wall: Internal - 1 - Pump Room - Station Building - Finchley Road Stn	Isolator Switches	Asbestos	Known				5 x Iron Clad Isolators 1 x 30amps, 2 x 60amps, 2 x 100amps Note one 100 amp box still has Moulded section and contains asbestos, no sticker The other boxes Should have a stickers, No asbestos remaining inside, removed as part of SMEP works		5		N	N
2548	INACTIVE	J	B107-00-2/771/WAL-004	Wall: Internal - 4 - Pump Room - Station Building - Finchley Road Stn	Isolator Switches	Asbestos	Removed				1 x Blue & 2x Grey Iron Clad Isolators		2			
43173	ACTIVE	J	B107-00-2/771/WAL-005 80819143	Wall: Internal - 5 - Pump Room - Station Building - Finchley Road Stn Wall: Internal	Gasket :Pipework	Asbestos	Known				Pipework gaskets				N	N
43172	ACTIVE	J	B107-00-2/771/WAL-006	Wall: Internal - 6 - Pump Room - Station Building - Finchley Road Stn	Isolator Switches	Asbestos	Removed				W6 1 Switch Box 1 x 200 amps Note Should have a sticker, No asbestos remaining inside, removed as part of SMEP works				N	N
68700	ACTIVE	J	B107-00-2/771/WAL-008 80819146	Wall: Internal - 8 - Pump Room - Station Building - Finchley Road Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				1 x 200Amps Combination Switch - Asbestos Components Within		1			
1521	ACTIVE	J	B107-00-2/771/WAL-009 80819147	Wall: Internal - 9 - Pump Room - Station Building - Finchley Road Stn Wall: Internal	Isolator Switches	Asbestos	Removed				1 x Grey Iron Clad Isolators x 200 amps Note Should have a sticker, No asbestos remaining inside, removed as part of SMEP works		1		N	N
43171	ACTIVE	J	B107-00-2/771/WAL-012 80819150	Wall: Internal - 12 - Pump Room - Station Building - Finchley Road Stn Wall: Internal	Isolator Switches	Asbestos	Presumed				Transformer Box far corner right hand side on floor - Asbestos Components Within		1		N	N
43920	INACTIVE	J	B107-00-2/771/WAL-013 80819151	Wall: Internal - 13 - Pump Room - Station Building - Finchley Road Stn Wall: Internal	Gasket :Pipework	Asbestos	Presumed				W13 presumed asbestos gaskets within flange joints to pump equipment				N	N
1522	INACTIVE	J	B107-00-2/771/WAL-017 100002571	Wall: Internal - 17 - Pump Room - Station Building - Finchley Road Stn Wall: Internal	Other Electrical Boxes	Asbestos	Known				Transformer Box(es) Duplicate this box is on wall 12		1		N	N
3934	ACTIVE	J	B107-00-2/951	Equipment Room - Station Building - Finchley Road Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B107-00 - Station Building - Finchley Road Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2703	ACTIVE	J	B107-00-2/951	Equipment Room - Station Building - Finchley Road Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					

B111-00 - Station Building - Swiss Cottage Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3935	ACTIVE	J	B111-00-1/201	Passage - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2896	ACTIVE	J	B111-00-1/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Within metal cable trunking and above ceiling panels			R748601	Yes	
1523	ACTIVE	J	B111-00-1/201/FLR-01	Floor - 1 - Passage - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				No access below 2 x Floor Hatches					yes
3936	ACTIVE	J	B111-00-1/202	Passage - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1524	ACTIVE	J	B111-00-1/202	Passage - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Walls - Supalux Tiles					
3937	ACTIVE	J	B111-00-1/203	Passage - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1525	ACTIVE	J	B111-00-1/203/FLR-01	Floor - 1 - Passage - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				No access below Floor Hatch					yes
2704	ACTIVE	J	B111-00-1/203/GTE-01	Gate: Collapsible - 1 - Passage - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux tiles by Gateline					
3938	ACTIVE	J	B111-00-1/236	Passage - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1526	ACTIVE	J	B111-00-1/236	Passage - Station Building - Swiss Cottage Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3939	ACTIVE	J	B111-00-1/237	Passage - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1527	ACTIVE	J	B111-00-1/237	Passage - Station Building - Swiss Cottage Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3940	ACTIVE	J	B111-00-1/238	Lobby - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1528	ACTIVE	J	B111-00-1/238	Lobby - Station Building - Swiss Cottage Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



Hazardous Material Asset Register - Summary



B111-00 - Station Building - Swiss Cottage Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3941	ACTIVE	J	B111-00-1/239	Switch Room - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1615	ACTIVE	J	B111-00-1/239	Switch Room - Station Building - Swiss Cottage Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3942	ACTIVE	J	B111-00-1/412	Store - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1616	ACTIVE	J	B111-00-1/412/WAL-001	Wall: Internal - 1 - Store - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels					
2611	ACTIVE	J	B111-00-1/412/WAL-003	Wall: Internal - 3 - Store - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels					
1617	ACTIVE	J	B111-00-1/412/WAL-004	Wall: Internal - 4 - Store - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Panels					
3943	ACTIVE	J	B111-00-1/576	Stairs: Linear - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2898	ACTIVE	J	B111-00-1/576	Stairs: Linear - Station Building - Swiss Cottage Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3944	ACTIVE	J	B111-00-1/601	Stairs: Linear - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1618	ACTIVE	J	B111-00-1/601	Stairs: Linear - Station Building - Swiss Cottage Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3945	ACTIVE	J	B111-00-1/602	Stairs: Linear - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
43159	ACTIVE	J	B111-00-1/602/GTE-01	Gate: Collapsible - 1 - Linear Stairs - Station Building - Swiss Cottage Stn	Non Asbestos Boarding	Asbestos	Sampled – Not Detected				Firebreak board, 0.3m, to gate/ceiling above Bostwick gate by the stairs (exit/entrance) 1/602 at Swiss Cottage Station			R530476	Y	N
1619	ACTIVE	J	B111-00-1/602/GTE-01	Gate: Collapsible - 1 - Linear Stairs - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles near gate					
43161	ACTIVE	J	B111-00-1/602/GTE-01	Gate: Collapsible - 1 - Linear Stairs - Station Building - Swiss Cottage Stn	Non Asbestos Boarding	Asbestos	Sampled – Not Detected				Mastics, throughout. firebreak to gate/ceiling above Bostwick gate by the stairs (exit/entrance) 1/602 at Swiss Cottage Station			R530476	Y	N
3946	ACTIVE	J	B111-00-1/603	Stairs: Linear - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B111-00 - Station Building - Swiss Cottage Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1620	ACTIVE	J	B111-00-1/603/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
2612	ACTIVE	J	B111-00-1/603/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux tiles				Yes	
3947	ACTIVE	J	B111-00-1/604	Stairs: Linear - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2346	ACTIVE	J	B111-00-1/604	Stairs: Linear - Station Building - Swiss Cottage Stn	No Access	Asbestos	No Access: Presumed				Metal trunking at ceiling level No access					
3948	ACTIVE	J	B111-00-1/605	Stairs: Linear - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1621	ACTIVE	J	B111-00-1/605/CLG-01	Ceiling: Suspended - 1 - Linear Stairs - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected								yes	
1622	ACTIVE	J	B111-00-1/605/CLG-01	Ceiling: Suspended - 1 - Linear Stairs - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux tiles				Yes	
3949	ACTIVE	J	B111-00-1/701	CER - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2300	ACTIVE	J	B111-00-1/701/WAL-003	Wall: Internal - 3 - CER - Station Building - Swiss Cottage Stn	Other Boarding	Asbestos	Strongly Presumed				Bakelite Boarding		1		N	N
1623	ACTIVE	J	B111-00-1/701/WAL-003	Wall: Internal - 3 - CER - Station Building - Swiss Cottage Stn	Isolator Switches	Asbestos	Strongly Presumed				2x Combination fuse switches 2 x 60 amps		2		N	N
3950	ACTIVE	J	B111-00-1/732	CER - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1624	ACTIVE	J	B111-00-1/732/WAL-003	Wall: Internal - 3 - CER - Station Building - Swiss Cottage Stn	Isolator Switches	Asbestos	Strongly Presumed				Combination Fuse Switches 2 x 30 amps		2		N	N
2613	ACTIVE	J	B111-00-1/732/WAL-005	Wall: Internal - 5 - CER - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
3951	ACTIVE	J	B111-00-2/001	Booking Hall - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1626	ACTIVE	J	B111-00-2/001/CLG-01	Ceiling: Suspended - 1 - Booking Hall - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Metal Trunking and ducting above False Ceiling				Yes	
1625	ACTIVE	J	B111-00-2/001/FLR-01	Floor - 1 - Booking Hall - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				No access below Floor Hatches					yes



Hazardous Material Asset Register - Summary



B111-00 - Station Building - Swiss Cottage Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3952	ACTIVE	J	B111-00-2/011	Ticket Office - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2553	ACTIVE	J	B111-00-2/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Concrete and brick above Supalux Tiles				Yes	
1628	ACTIVE	J	B111-00-2/011/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1627	ACTIVE	J	B111-00-2/011/FLR-01	Floor - 1 - Ticket Office - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Concrete and Rubber Cables beneath Computer Tiles					yes
2614	ACTIVE	J	B111-00-2/011/WAL-003	Wall: Internal - 3 - Ticket Office - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				No Access to inside of Metal Boxing					
3953	ACTIVE	J	B111-00-2/021	POM - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1630	ACTIVE	J	B111-00-2/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Concrete Ceiling and Brick Walls above Supalux Tiles				Yes	
2499	ACTIVE	J	B111-00-2/021/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
2919	ACTIVE	J	B111-00-2/021/FLR-01	Floor - 1 - POM - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Concrete and Rubber Cables beneath Computer Tiles					yes
1629	ACTIVE	J	B111-00-2/021/WAL-001	Wall: Internal - 1 - POM - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing					
3954	ACTIVE	J	B111-00-2/031	Mess Room - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1632	ACTIVE	J	B111-00-2/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1633	ACTIVE	J	B111-00-2/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Concrete Ceiling & Brick Walls above Supalux Tiles				Yes	
1631	ACTIVE	J	B111-00-2/031/FLR-01	Floor - 1 - Mess Room - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				No Access beneath Vinyl and Manholes					yes
2615	ACTIVE	J	B111-00-2/031/WAL-002	Wall: Internal - 2 - Mess Room - Station Building - Swiss Cottage Stn	LUL Heaters	Asbestos	Surveyed – Not Detected						1			



Hazardous Material Asset Register - Summary



B111-00 - Station Building - Swiss Cottage Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1636	ACTIVE	J	B111-00-2/031/WAL-002	Wall: Internal - 2 - Mess Room - Station Building - Swiss Cottage Stn	Boarding: AIB	Asbestos	Known				White boarding protruding from wall 2 - Chrysotile & Amphibole	6			N	N
1635	ACTIVE	J	B111-00-2/031/WAL-004	Wall: Internal - 4 - Mess Room - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				No Access through Supalux Boxing				yes	
1634	INACTIVE	J	B111-00-2/031/WAL-004	Wall: Internal - 4 - Mess Room - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				Supalux Boxing				yes	
3955	ACTIVE	J	B111-00-2/071	Circulation Area - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1637	ACTIVE	J	B111-00-2/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Metal Trunking and ducting above False Ceiling				Yes	
2616	ACTIVE	J	B111-00-2/071/FLR-01	Floor - 1 - Circulation Area - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				No access below Floor Hatches					yes
3956	ACTIVE	J	B111-00-2/081	Lobby - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2301	ACTIVE	J	B111-00-2/081	Lobby - Station Building - Swiss Cottage Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Lobby to ATM's					
43985	ACTIVE	J	B111-00-2/081	Lobby - Station Building - Swiss Cottage Stn		Asbestos	Sampled – Not Detected				MMMF plasterboard, 3m2, to the false ceiling panel by wall 4,5, 6 in ATM 2/081 at Swiss Cottage Station			R594576	Y	N
3957	ACTIVE	J	B111-00-2/151	UMC - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1639	ACTIVE	J	B111-00-2/151	UMC - Station Building - Swiss Cottage Stn	Rope Gaskets	Asbestos	Presumed				Gaskets to Ventilation System	10			N	N
1640	ACTIVE	J	B111-00-2/151	UMC - Station Building - Swiss Cottage Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box		1		N	N
1641	ACTIVE	J	B111-00-2/151	UMC - Station Building - Swiss Cottage Stn	Isolator Switches	Asbestos	Strongly Presumed				100amp Isolator Box		1		N	N
1638	ACTIVE	J	B111-00-2/151/WAL-001	Wall: Internal - 1 - UMC - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Boarding by Wall 1 - Supalux					
2617	ACTIVE	J	B111-00-2/171	Escalator Incline - Station Building - Swiss Cottage Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3958	ACTIVE	J	B111-00-2/201	Passage - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B111-00 - Station Building - Swiss Cottage Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1642	ACTIVE	J	B111-00-2/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1643	ACTIVE	J	B111-00-2/201/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Brick & Concrete Walls beneath Plaster & Supalux Tiles				Yes	
2347	ACTIVE	J	B111-00-2/201/FLR-01	Floor - 1 - Passage - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				No access below Floor Hatches					yes
3959	ACTIVE	J	B111-00-2/202	Passage - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2914	ACTIVE	J	B111-00-2/202	Passage - Station Building - Swiss Cottage Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
69709	ACTIVE	J	B111-00-2/202/CLG-02	Ceiling: Suspended - 1 - Passage - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				No ACMs identified within ceiling void			R748601	Y	
3960	ACTIVE	J	B111-00-2/204	Passage - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1644	ACTIVE	J	B111-00-2/204/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Metal Tiles				Yes	
2618	ACTIVE	J	B111-00-2/204/FLR-01	Floor - 1 - Passage - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				No access below Floor Hatches					yes
3961	ACTIVE	J	B111-00-2/205	Passage - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1645	ACTIVE	J	B111-00-2/205	Passage - Station Building - Swiss Cottage Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3962	ACTIVE	J	B111-00-2/236	Passage - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2554	ACTIVE	J	B111-00-2/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Plasterboard above Supalux Tiles				Yes	
2619	ACTIVE	J	B111-00-2/236/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1647	ACTIVE	J	B111-00-2/236/FLR-01	Floor - 1 - Passage - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				No access beneath Computer Tiles					yes
3963	ACTIVE	J	B111-00-2/237	Lobby - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B111-00 - Station Building - Swiss Cottage Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2500	ACTIVE	J	B111-00-2/237/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux Tiles				Yes	
1649	ACTIVE	J	B111-00-2/237/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1648	ACTIVE	J	B111-00-2/237/FLR-01	Floor - 1 - Lobby - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath Computer Tiles					yes
3964	ACTIVE	J	B111-00-2/240	Lobby - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1650	ACTIVE	J	B111-00-2/240	Lobby - Station Building - Swiss Cottage Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3965	ACTIVE	J	B111-00-2/281	Station Supervisor Office - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1651	ACTIVE	J	B111-00-2/281	Station Supervisor Office - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing					
2620	ACTIVE	J	B111-00-2/281/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Superlux Tiles					
1652	ACTIVE	J	B111-00-2/281/CLG-01	Ceiling: Suspended - 1 - Station Supervisor Office - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Brick Walls above Supalux Tiles				Yes	
2348	ACTIVE	J	B111-00-2/281/WAL-006	Wall: Internal - 6 - Station Supervisor Office Office - Station Building - Swiss Cottage Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Foam		1			
3966	ACTIVE	J	B111-00-2/311	Office - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1654	ACTIVE	J	B111-00-2/311/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing Ceiling Panel, 1m2, to top of lockers, within Station Supervisor Compound, Room 2/311 = ES10978.					
1655	ACTIVE	J	B111-00-2/311/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				No Access above Supalux Tiles				Yes	
1653	ACTIVE	J	B111-00-2/311/WAL-002	Wall: Internal - 2 - Office - Station Building - Swiss Cottage Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Foam		1			
3967	ACTIVE	J	B111-00-2/331	Mess Room - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B111-00 - Station Building - Swiss Cottage Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1646	ACTIVE	J	B111-00-2/331	Mess Room - Station Building - Swiss Cottage Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2302	ACTIVE	J	B111-00-2/331	Mess Room - Station Building - Swiss Cottage Stn	LUL Heaters	Asbestos	Surveyed – Not Detected				Foam		1			
1656	ACTIVE	J	B111-00-2/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Brick Walls above Supalux Tiles				Yes	
2621	ACTIVE	J	B111-00-2/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Superlux Tiles					
3968	ACTIVE	J	B111-00-2/396	SVC - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42292	ACTIVE	J	B111-00-2/396	SVC - Station Building - Swiss Cottage Stn	Mastic	Asbestos	Sampled – Not Detected				Gasket/mastic throughout to bottom flanges of old sprinkler valve set - Note the rest of the gasket has been removed as precautionary measure			R496626	N	N
1657	ACTIVE	J	B111-00-2/396	SVC - Station Building - Swiss Cottage Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3969	ACTIVE	J	B111-00-2/397	SVC - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1658	ACTIVE	J	B111-00-2/397	SVC - Station Building - Swiss Cottage Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3970	ACTIVE	J	B111-00-2/411	UMC - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2705	ACTIVE	J	B111-00-2/411	UMC - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Superlux Boarding					
1529	ACTIVE	J	B111-00-2/411/WAL-002	Wall: Internal - 2 - UMC - Station Building - Swiss Cottage Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard					
3971	ACTIVE	J	B111-00-2/416	Toilet: Unisex - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2706	ACTIVE	J	B111-00-2/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Brick Walls above Supalux Tiles				Yes	
1531	ACTIVE	J	B111-00-2/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Superlux Tiles					
1530	ACTIVE	J	B111-00-2/416/WAL-002	Wall: Internal - 2 - Toilet - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Superlux Boarding					



Hazardous Material Asset Register - Summary



B111-00 - Station Building - Swiss Cottage Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3972	ACTIVE	J	B111-00-2/417	Toilet: Unisex - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1533	ACTIVE	J	B111-00-2/417	Toilet: Unisex - Station Building - Swiss Cottage Stn	Gasket :Pipework	Asbestos	Surveyed – Not Detected				Fire Hydrant				yes	
1532	ACTIVE	J	B111-00-2/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Plaster, Solid above Metal Tiles				Yes	
2497	ACTIVE	J	B111-00-2/417/FLR-01	Floor - 1 - Toilet - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				No Access below Floor Hatches					yes
3973	ACTIVE	J	B111-00-2/418	Lobby - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2549	ACTIVE	J	B111-00-2/418/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Concrete, Brick Walls above Supalux Tiles				Yes	
1534	ACTIVE	J	B111-00-2/418/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Superlux Tiles					
3974	ACTIVE	J	B111-00-2/451	Tenancy - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1535	ACTIVE	J	B111-00-2/451	Tenancy - Station Building - Swiss Cottage Stn	Non Asbestos Boarding	Asbestos	Surveyed – Not Detected				Plastered Plasterboard ceiling.					
3975	ACTIVE	J	B111-00-2/452	ATM - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1536	ACTIVE	J	B111-00-2/452	ATM - Station Building - Swiss Cottage Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed - Tennancy - No Access					
3976	ACTIVE	J	B111-00-2/661	Switch Room - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2339	ACTIVE	J	B111-00-2/661/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Swiss Cottage Stn	Isolator Switches	Asbestos	Strongly Presumed				W3 4x Combination fuse switches 2 x 60 amp, 1 x 200 amp, 1 x 100 amp		4		N	N
3977	ACTIVE	J	B111-00-2/662	Switch Room - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1537	ACTIVE	J	B111-00-2/662	Switch Room - Station Building - Swiss Cottage Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box		1		N	N
2707	ACTIVE	J	B111-00-2/662/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Swiss Cottage Stn	Isolator Switches	Asbestos	Strongly Presumed				Walls 1, x 6, 2 x 30 amps, 3 x 60amps, 1 x 100amps		6		N	N



Hazardous Material Asset Register - Summary



B111-00 - Station Building - Swiss Cottage Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43923	ACTIVE	J	B111-00-2/662/WAL-001 80834348	Wall: Internal - 1 - Switch Room - Station Building - Swiss Cottage Stn Wall: Internal	Isolator Switches	Asbestos	Presumed				Busbar		1		N	N
43924	ACTIVE	J	B111-00-2/662/WAL-002 80834349	Wall: Internal - 2 - Switch Room - Station Building - Swiss Cottage Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				Busbar		1		N	N
1538	ACTIVE	J	B111-00-2/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Swiss Cottage Stn	Isolator Switches	Asbestos	Strongly Presumed				Walls 2 x 7, 5 x 60amps, 1 x 100amps, 1 x 200amps		7		N	N
1539	INACTIVE	J	B111-00-2/662/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Swiss Cottage Stn	Isolator Switches	Asbestos	Strongly Presumed				Walls 3 x,2 , 2 x 60amps		2		N	N
3978	ACTIVE	J	B111-00-2/663	Switch Room - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2591	ACTIVE	J	B111-00-2/663	Switch Room - Station Building - Swiss Cottage Stn	Other Electrical Boxes	Asbestos	Presumed				Transformer Box(es)		3		N	N
45275	INACTIVE	J	B111-00-2/663/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Swiss Cottage Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				2 x 30 amp, 3 x 60amp, 1 x 100 amp - Fuse Switches		7		N	N
43176	ACTIVE	J	B111-00-2/663/WAL-001 80834356	Wall: Internal - 1 - Switch Room - Station Building - Swiss Cottage Stn Wall: Internal	Isolator Switches	Asbestos	Presumed				W1 x1, 1 x 300amps		1		N	N
1540	ACTIVE	J	B111-00-2/663/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				Wooden Boarding - No Access to Cavity					
1541	INACTIVE	J	B111-00-2/663/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				Wooden Boarding - No Access to Cavity					
43174	ACTIVE	J	B111-00-2/663/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Swiss Cottage Stn	Isolator Switches	Asbestos	Presumed				Wall 2, 1 x 300amps		1		N	N
43175	ACTIVE	J	B111-00-2/663/WAL-003	Wall: Internal - 3 - Switch Room - Station Building - Swiss Cottage Stn	Isolator Switches	Asbestos	Presumed				Wall 3 1 x 30amps		2		N	N
3979	ACTIVE	J	B111-00-2/664	Switch Room - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2592	ACTIVE	J	B111-00-2/664/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Tiles					
1545	ACTIVE	J	B111-00-2/664/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				No Access above Supalux Tiles				Yes	



Hazardous Material Asset Register - Summary



B111-00 - Station Building - Swiss Cottage Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1542	ACTIVE	J	B111-00-2/664/FLR-01	Floor - 1 - Switch Room - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Concrete beneath Wood Flooring					yes
1543	ACTIVE	J	B111-00-2/664/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				No Access behind Wooden Boarding					
1544	ACTIVE	J	B111-00-2/664/WAL-004	Wall: Internal - 4 - Switch Room - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				No access behind Supalux Boarding					
3980	ACTIVE	J	B111-00-2/665	Disused Room - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1547	ACTIVE	J	B111-00-2/665/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Swiss Cottage Stn	Boarding: AIB	Asbestos	Known				Boarding under stairs	6			N	N
1548	INACTIVE	J	B111-00-2/665/WAL-002	Wall: Internal - 2 - Disused Room - Station Building - Swiss Cottage Stn	Isolator Switches	Asbestos	Strongly Presumed				Walls 1, 2, 3 - Combination fuse switches x 13		13		N	N
2918	ACTIVE	J	B111-00-2/665/WAL-003 80834510	Wall: Internal - 3 - Disused Room - Station Building - Swiss Cottage Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Wall 3 - combination switches x 2, both 30 amp.		2		N	N
43927	ACTIVE	J	B111-00-2/665/WAL-003 80834510	Wall: Internal - 3 - Disused Room - Station Building - Swiss Cottage Stn Wall: Internal	Isolator Switches	Asbestos	Presumed				Busbar		1		N	N
1546	ACTIVE	J	B111-00-2/665/WAL-004 80834511	Wall: Internal - 4 - Disused Room - Station Building - Swiss Cottage Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Walls 4 - Combination fuse switches x 1		1		N	N
3981	ACTIVE	J	B111-00-2/666	Switch Room - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44567	ACTIVE	J	B111-00-2/666	Switch Room - Station Building - Swiss Cottage Stn	Isolator Switches	Asbestos	Presumed				Asbestos - SP - Wall 1 - 4x Combination Fuse switches 2 x 30 amps, 2 x 60 amps		4		N	N
2593	ACTIVE	J	B111-00-2/666	Switch Room - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boxing around ducting above Door					
3982	ACTIVE	J	B111-00-2/706	IMR - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1549	INACTIVE	J	B111-00-2/706	IMR - Station Building - Swiss Cottage Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				PCB's Plessey oblong grey, rack mounted behind glass panel x 15 plus					
1593	ACTIVE	J	B111-00-2/706/WAL-001	Wall: Internal - 1 - IMR - Station Building - Swiss Cottage Stn	Vinyl tiles	Asbestos	Presumed				Wall Mounted Marley Tiles	42			N	N
2605	ACTIVE	J	B111-00-2/706/WAL-002	Wall: Internal - 2 - IMR - Station Building - Swiss Cottage Stn	Vinyl tiles	Asbestos	Presumed				Wall Mounted Marley Tiles	9			N	N



Hazardous Material Asset Register - Summary



B111-00 - Station Building - Swiss Cottage Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2916	ACTIVE	J	B111-00-2/706/WAL-003	Wall: Internal - 3 - IMR - Station Building - Swiss Cottage Stn	Vinyl tiles	Asbestos	Presumed				Wall Mounted Marley Tiles	42			N	N
1594	ACTIVE	J	B111-00-2/706/WAL-004	Wall: Internal - 4 - IMR - Station Building - Swiss Cottage Stn	Vinyl tiles	Asbestos	Presumed				Wall Mounted Marley Tiles	12			N	N
3983	ACTIVE	J	B111-00-2/731	CER - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1595	ACTIVE	J	B111-00-2/731	CER - Station Building - Swiss Cottage Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3984	ACTIVE	J	B111-00-2/747	SCR - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2606	ACTIVE	J	B111-00-2/747/CLG-01	Ceiling: Solid - 1 - SCR - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				No Access above Supalux Boarding				Yes	
1597	ACTIVE	J	B111-00-2/747/CLG-01	Ceiling: Solid - 1 - SCR - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2299	ACTIVE	J	B111-00-2/747/WAL-002	Wall: Internal - 2 - SCR - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1596	ACTIVE	J	B111-00-2/747/WAL-002	Wall: Internal - 2 - SCR - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				No access to Cavity					
3985	ACTIVE	J	B111-00-2/761	Equipment Room - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2552	ACTIVE	J	B111-00-2/761/WAL-001	Wall: Internal - 1 - Equipment Room - Station Building - Swiss Cottage Stn	Isolator Switches	Asbestos	Strongly Presumed				Walls 1 - Combination Fuse Switch		1		N	N
1598	ACTIVE	J	B111-00-2/761/WAL-001	Wall: Internal - 1 - Equipment Room - Station Building - Swiss Cottage Stn	Other Boarding	Asbestos	Presumed				Paxoline Board		1		N	N
1599	ACTIVE	J	B111-00-2/761/WAL-001	Wall: Internal - 1 - Equipment Room - Station Building - Swiss Cottage Stn	Other Boarding	Asbestos	Presumed				Bakelite Boarding		3		N	N
1600	ACTIVE	J	B111-00-2/761/WAL-002 80834538	Wall: Internal - 2 - Equipment Room - Station Building - Swiss Cottage Stn Wall: Internal	Other Boarding	Asbestos	Presumed				Bakelite Boarding located above entrance door		1		N	N
3986	ACTIVE	J	B111-00-2/951	Store - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1601	ACTIVE	J	B111-00-2/951	Store - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2344	INACTIVE	J	B111-00-2/951	Store - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				No access above Supalux Boarding					



Hazardous Material Asset Register - Summary



B111-00 - Station Building - Swiss Cottage Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3987	ACTIVE	J	B111-00-2/992	Passage - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2607	ACTIVE	J	B111-00-2/992	Passage - Station Building - Swiss Cottage Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3988	ACTIVE	J	B111-00-3/081	Circulation Area - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2897	ACTIVE	J	B111-00-3/081	Circulation Area - Station Building - Swiss Cottage Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Board above Fire Hydrant					
1602	ACTIVE	J	B111-00-3/081/FLR-01	Floor - 1 - Circulation Area - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				No access below Floor Hatches					yes
3989	ACTIVE	J	B111-00-3/161	LMC - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1603	ACTIVE	J	B111-00-3/161	LMC - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				Beneath - Hatch / Manhole					YES
2608	ACTIVE	J	B111-00-3/162	LMC Access - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				Beneath - Hatch / Manhole					YES
1604	ACTIVE	J	B111-00-3/162	LMC Access - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing, Supalux panel near stairs					
3990	ACTIVE	J	B111-00-3/201	Passage - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1605	ACTIVE	J	B111-00-3/201	Passage - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				No Access above Metal Trunking					
3991	ACTIVE	J	B111-00-3/202	Passage - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1606	ACTIVE	J	B111-00-3/202	Passage - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				No Access above Metal Trunking					
3992	ACTIVE	J	B111-00-3/203	Passage - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2609	ACTIVE	J	B111-00-3/203	Passage - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				No Access above Metal Trunking					
3993	ACTIVE	J	B111-00-3/204	Passage - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1607	ACTIVE	J	B111-00-3/204	Passage - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				No Access above Metal Trunking					



Hazardous Material Asset Register - Summary



B111-00 - Station Building - Swiss Cottage Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3994	ACTIVE	J	B111-00-3/205	Passage - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1608	ACTIVE	J	B111-00-3/205	Passage - Station Building - Swiss Cottage Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
3995	ACTIVE	J	B111-00-3/236	Lobby - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2345	ACTIVE	J	B111-00-3/236	Lobby - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding - middle of corridor by ducting					
1609	ACTIVE	J	B111-00-3/236/DOR-01	Door - 1 - Lobby - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux boarding above door to 3/162					
3996	ACTIVE	J	B111-00-3/261	Platform 1 - Northbound Local - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45276	ACTIVE	J	B111-00-3/261	Platform 1 - Northbound Local - Station Building - Swiss Cottage Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - 1x 40mm green cable	40	1		N	N
69490	ACTIVE	J	B111-00-3/261	Platform 1 - Northbound Local - Station Building - Swiss Cottage Stn	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Invert - Grout - To tunnel rings on wood.			R709002		
69489	ACTIVE	J	B111-00-3/261	Platform 1 - Northbound Local - Station Building - Swiss Cottage Stn	Cable Ducts: Bitumen	Asbestos	Known				Invert - Bitumen ducts - total 3 no - To track side wall.		3	R709002		Y
69488	ACTIVE	J	B111-00-3/261	Platform 1 - Northbound Local - Station Building - Swiss Cottage Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen ducts - total 6 no - To track side wall.		6	R709002		Y
69485	ACTIVE	J	B111-00-3/261	Platform 1 - Northbound Local - Station Building - Swiss Cottage Stn	Westinghouse Boxes	Asbestos	Presumed				Invert - Small Westinghouse box - total 1 no - To track side wall.		1	R709002		
69483	ACTIVE	J	B111-00-3/261	Platform 1 - Northbound Local - Station Building - Swiss Cottage Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen ducts - total 6 no - To platform side wall.		6	R709002		Y
69482	ACTIVE	J	B111-00-3/261	Platform 1 - Northbound Local - Station Building - Swiss Cottage Stn	Westinghouse Boxes	Asbestos	Presumed				Invert - Small Westinghouse box - total 1 no - To platform side wall.		1	R709002		
1611	ACTIVE	J	B111-00-3/261	Platform 1 - Northbound Local - Station Building - Swiss Cottage Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Red Boarding by Relay Room 3/714 - Metal					
1551	ACTIVE	J	B111-00-3/261	Platform 1 - Northbound Local - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Platform 1 Invert - 6x Cable Sleeves - Bitumen - Non asbestos Trackside opposite end head wall		6			



Hazardous Material Asset Register - Summary



B111-00 - Station Building - Swiss Cottage Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
69491	ACTIVE	J	B111-00-3/261	Platform 1 - Northbound Local - Station Building - Swiss Cottage Stn	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Invert - Metal tunnel rings - Throughout.			R709002		
69486	ACTIVE	J	B111-00-3/261	Platform 1 - Northbound Local - Station Building - Swiss Cottage Stn	Other Electrical Boxes	Asbestos	Presumed				Invert - Materials within electrical box - total 1 no - To track side wall.		1	R709002		
69484	ACTIVE	J	B111-00-3/261	Platform 1 - Northbound Local - Station Building - Swiss Cottage Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen ducts - total 4 no - To platform side wall.		4	R709002		Y
69481	ACTIVE	J	B111-00-3/261	Platform 1 - Northbound Local - Station Building - Swiss Cottage Stn	Westinghouse Boxes	Asbestos	Presumed				Invert - Small Westinghouse box - total 1 no - To track side wall.		1	R709002		
69480	ACTIVE	J	B111-00-3/261	Platform 1 - Northbound Local - Station Building - Swiss Cottage Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen ducts - total 6 no - To track side wall.		6	R709002		Y
69479	ACTIVE	J	B111-00-3/261	Platform 1 - Northbound Local - Station Building - Swiss Cottage Stn	Cable Sheath	Asbestos	Known				Invert - Green braided cables - total 6 no - Throughout.		6	R709002		
2594	ACTIVE	J	B111-00-3/261	Platform 1 - Northbound Local - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Platform 1 Invert - 3x Cable Sleeves - Bitumen - Non asbestos - Trackside 3m back from hatch		3			
69487	ACTIVE	J	B111-00-3/261	Platform 1 - Northbound Local - Station Building - Swiss Cottage Stn	Cable Ducts: Bitumen	Asbestos	Known				Invert - Bitumen ducts - total 3 no - To ceiling of invert.		3	R709002		Y
1552	ACTIVE	J	B111-00-3/261	Platform 1 - Northbound Local - Station Building - Swiss Cottage Stn	Lead/Leading	Lead Paint/Lead	Removed				Red Lead Paint Wall Mounted Grit Bin				N	N
2610	ACTIVE	J	B111-00-3/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Swiss Cottage Stn	Other Boarding	Asbestos	No Access: Presumed				No Access to Blue Boarding above Relay Room 3/714 - Melamine					
1610	ACTIVE	J	B111-00-3/261/CLG-01	Ceiling: Solid - 1 - Platform 1 - Station Building - Swiss Cottage Stn	Other Boarding	Asbestos	No Access: Presumed				No Access to Boarding above Relay Room 3/712 - Melamine					
1550	ACTIVE	J	B111-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Swiss Cottage Stn	Cable Ducts: Cement	Asbestos	Strongly Presumed				Platform 1 Invert - 6x Cable Sleeves -10m on platform side		6		N	yes
1613	ACTIVE	J	B111-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Swiss Cottage Stn	Cable: Sheath	Asbestos	Removed				Platform 1 Invert - 1x 40mm Green Cable Removed by Pectel ES726		1		N	yes
2912	ACTIVE	J	B111-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Swiss Cottage Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - One 40mm diameter green cable, cut, 5m from hatch, track side		2		N	yes
2298	ACTIVE	J	B111-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Swiss Cottage Stn	Cable Ducts: Bitumen	Asbestos	Strongly Presumed				Platform 1 Invert - 3x Cable Sleeves - 20m past cross passage platform side		3		N	yes
1614	ACTIVE	J	B111-00-3/261/FLR-01	Floor - 1 - Platform 1 - Station Building - Swiss Cottage Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 1 Invert - 2x 20mm Green Cables		2		N	yes



Hazardous Material Asset Register - Summary



B111-00 - Station Building - Swiss Cottage Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1612	ACTIVE	J	B111-00-3/261/ PLN-01	Nosing: Platform - Platform 1 - Station Building - Swiss Cottage Stn	Boarding: AIB	Asbestos	Known				Platform Nosing in front of 3/412 - Amosite				N	N
3997	ACTIVE	J	B111-00-3/262	Platform 2 - Southbound Local - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2595	ACTIVE	J	B111-00-3/262	Platform 2 - Southbound Local - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Platform 2 Invert - 6x Cable sleeves - Bitumen - Non asbestos - 20m from Hatch		6			
1555	ACTIVE	J	B111-00-3/262	Platform 2 - Southbound Local - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Platform 2 Invert - 6x Cable sleeves - Bitumen - Non Asbestos - Trackside by Headwall		6			
1557	ACTIVE	J	B111-00-3/262	Platform 2 - Southbound Local - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Platform 2 Invert - 6x Cable Sleeves - Bitumen - Non asbestos - Head Wall opposite side		6			
1558	ACTIVE	J	B111-00-3/262	Platform 2 - Southbound Local - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Platform 2 Invert - 3x Cable Sleeves - Bitumen - Non asbestos - 3m back from hatch		3			
69496	ACTIVE	J	B111-00-3/262	Platform 2 - Southbound Local - Station Building - Swiss Cottage Stn	Westinghouse Boxes	Asbestos	Presumed				Invert - Small Westinghouse box - total 1 no -To platform side wall.		1	R709002		
69497	ACTIVE	J	B111-00-3/262	Platform 2 - Southbound Local - Station Building - Swiss Cottage Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen ducts - total 3 no - To platform side wall.		3	R709002		Y
69498	ACTIVE	J	B111-00-3/262	Platform 2 - Southbound Local - Station Building - Swiss Cottage Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen ducts - total 7 no - To track side wall.		7	R709002		Y
69499	ACTIVE	J	B111-00-3/262	Platform 2 - Southbound Local - Station Building - Swiss Cottage Stn	Cable Ducts: Bitumen	Asbestos	Known				Invert - Bitumen ducts - total 3 no - To track side wall.		3	R709002		Y
69500	ACTIVE	J	B111-00-3/262	Platform 2 - Southbound Local - Station Building - Swiss Cottage Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen ducts - total 6 no - To track side wall.		6	R709002		Y
67880	ACTIVE	J	B111-00-3/262	Platform 2 - Southbound Local - Station Building - Swiss Cottage Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 invert, 5m from hatch, track side -One 40mm diameter green cable, cut			R54876		
69492	ACTIVE	J	B111-00-3/262	Platform 2 - Southbound Local - Station Building - Swiss Cottage Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen ducts - total 6 no - To track side wall.		6	R709002		Y
69494	ACTIVE	J	B111-00-3/262	Platform 2 - Southbound Local - Station Building - Swiss Cottage Stn	Cable Sheath	Asbestos	Known				Invert - Green braided cables - total 2 no - Throughout to track wall.		2	R709002		
69495	ACTIVE	J	B111-00-3/262	Platform 2 - Southbound Local - Station Building - Swiss Cottage Stn	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Inver t- Grout on wood - To tunnel rings.			R709002		



Hazardous Material Asset Register - Summary



B111-00 - Station Building - Swiss Cottage Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
69501	ACTIVE	J	B111-00-3/262	Platform 2 - Southbound Local - Station Building - Swiss Cottage Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen duct - total 1 no - To track side wall.		1	R709002		Y
1556	ACTIVE	J	B111-00-3/262	Platform 2 - Southbound Local - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Platform 2 Invert - 3x Cable sleeves - Bitumen - Non asbestos - 5m on		3			
1559	ACTIVE	J	B111-00-3/262	Platform 2 - Southbound Local - Station Building - Swiss Cottage Stn	Void	Asbestos	Surveyed – Not Detected				Platform 2 Invert - 3x 100mm Cable Ducts - Non Asbestos		3			
1554	ACTIVE	J	B111-00-3/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - Swiss Cottage Stn	Other Boarding	Asbestos	No Access: Presumed				No Access to Blue Boarding above Relay Room 3/713 - Melamine					
1553	ACTIVE	J	B111-00-3/262/CLG-01	Ceiling: Solid - 1 - Platform 2 - Station Building - Swiss Cottage Stn	Other Boarding	Asbestos	No Access: Presumed				No Access to Blue Boarding above Relay Room 3/711 - Melamine					
2880	ACTIVE	J	B111-00-3/262/FLR-01	Floor - 1 - Platform 2 - Station Building - Swiss Cottage Stn	Cable: Sheath	Asbestos	Strongly Presumed				Platform 2 Invert - 2 x 20mm Green Cables length of the invert		2		N	yes
3998	ACTIVE	J	B111-00-3/411	Switch Room - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2596	ACTIVE	J	B111-00-3/411	Switch Room - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Archway					
1561	ACTIVE	J	B111-00-3/411/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				Above Concrete/Supalux False Ceiling				Yes	
1560	ACTIVE	J	B111-00-3/411/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux/Concrete					
3999	ACTIVE	J	B111-00-3/412	Store - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1562	ACTIVE	J	B111-00-3/412	Store - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Archway					
2597	ACTIVE	J	B111-00-3/412/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux/Concrete					
2340	ACTIVE	J	B111-00-3/412/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Swiss Cottage Stn	Void	Asbestos	No Access: Presumed				Metal Trunking				Yes	
4000	ACTIVE	J	B111-00-3/413	Switch Room - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1563	ACTIVE	J	B111-00-3/413	Switch Room - Station Building - Swiss Cottage Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



Hazardous Material Asset Register - Summary



B111-00 - Station Building - Swiss Cottage Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
68062	ACTIVE	J	B111-00-3/413/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Swiss Cottage Stn		Asbestos	Surveyed – Not Detected								Y	
4001	ACTIVE	J	B111-00-3/661	Switch Room - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1564	ACTIVE	J	B111-00-3/661/FLR-01	Floor - 1 - Switch Room - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Concrete, Supalux Boxing on floor					
2550	ACTIVE	J	B111-00-3/661/WAL-001 80834620	Wall: Internal - 1 - Switch Room - Station Building - Swiss Cottage Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				Transformer Box		1		N	N
1565	ACTIVE	J	B111-00-3/661/WAL-002 80834621	Wall: Internal - 2 - Switch Room - Station Building - Swiss Cottage Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				Transformer Box		1		N	N
2598	ACTIVE	J	B111-00-3/661/WAL-003 80834622	Wall: Internal - 3 - Switch Room - Station Building - Swiss Cottage Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Wall 3 Total 7 x switch boxes = 2x 60 amp; 2x 200 amp; 2x 100 amp; 1 x 30 amp		7		N	N
43925	ACTIVE	J	B111-00-3/661/WAL-003 80834622	Wall: Internal - 3 - Switch Room - Station Building - Swiss Cottage Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				Busbar		1		N	N
1566	ACTIVE	J	B111-00-3/661/WAL-004 80834623	Wall: Internal - 4 - Switch Room - Station Building - Swiss Cottage Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Wall 4 total 3 x switch boxes = 1x 200amp; 1x60amp; 1x30amp		3		N	N
4002	ACTIVE	J	B111-00-3/711	Relay Room - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
67833	ACTIVE	J	B111-00-3/711	Relay Room - Station Building - Swiss Cottage Stn	Mastic	Asbestos	Sampled – Not Detected				MASTIC, >10M, TO EDGES OF ALL METAL SHEETS, RELAY ROOM, 3/711			R692926		
67832	ACTIVE	J	B111-00-3/711	Relay Room - Station Building - Swiss Cottage Stn	Caulking	Asbestos	Strongly Presumed				CAULKING, >1M, TO TUNNEL RING JOINTS, RELAY ROOM, 3/711 (TUNNEL RING VISIBLE THROUGH GAP IN WALL)			R692926		
1568	ACTIVE	J	B111-00-3/711	Relay Room - Station Building - Swiss Cottage Stn	Cable: Sheath	Asbestos	Strongly Presumed				10x Braided Cable Insulation 2021 Re-inspection - Cables removed as part of ESN/TCP but terminated ends remain (encapsulated).		10		N	N
42061	INACTIVE	J	B111-00-3/711	Relay Room - Station Building - Swiss Cottage Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				5 x PCB's - 10 March 2017 inspection signs of leaking		5		N	N
1567	INACTIVE	J	B111-00-3/711/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Swiss Cottage Stn	Other Boarding	Asbestos	Removed				DARK BROWN BOARD, THROUGHOUT, TO CEILING/WALLS AND METAL FRAMES (SOME LOOSE ON FLOOR), RELAY ROOM, 3/711 Removed as part of ESN / TCP			R699651	N	N
4003	ACTIVE	J	B111-00-3/712	Relay Room - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B111-00 - Station Building - Swiss Cottage Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1570	ACTIVE	J	B111-00-3/712	Relay Room - Station Building - Swiss Cottage Stn	Cable: Sheath	Asbestos	Strongly Presumed				7 x Braided Cable Insulation		7		N	N
1569	ACTIVE	J	B111-00-3/712/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Swiss Cottage Stn	Other Boarding	Asbestos	Presumed				Bakelite Boarding				N	N
4004	ACTIVE	J	B111-00-3/713	Relay Room - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2913	ACTIVE	J	B111-00-3/713	Relay Room - Station Building - Swiss Cottage Stn	Cable: Sheath	Asbestos	Strongly Presumed				2 x Braided Cable Insulation		2		N	N
43926	ACTIVE	J	B111-00-3/713 80100000	Relay Room - Station Building - Swiss Cottage Stn Room Assets	Other Boarding	Asbestos	Presumed				Paxoline boarding throughout	1			N	N
4005	ACTIVE	J	B111-00-3/714	Relay Room - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
67836	ACTIVE	J	B111-00-3/714	Relay Room - Station Building - Swiss Cottage Stn	Other Boarding	Asbestos	Sampled – Not Detected				LIGHT BROWN BOARD, THROUGHOUT, TO CEILING/WALLS AND METAL FRAMES (SOME LOOSE ON FLOOR), RELAY ROOM, 3/714			R699651		
67834	ACTIVE	J	B111-00-3/714	Relay Room - Station Building - Swiss Cottage Stn	Mastic	Asbestos	Sampled – Not Detected				ASTIC, >10M, TO EDGES OF ALL METAL SHEETS, RELAY ROOM, 3/714			R692926		
67835	ACTIVE	J	B111-00-3/714	Relay Room - Station Building - Swiss Cottage Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				RUBBER/ MASTIC, 6 NO, TO DUCTS IN CORNER OF WALL 1 AND 2, RELAY ROOM, 3/714			R699651		
1571	INACTIVE	J	B111-00-3/714	Relay Room - Station Building - Swiss Cottage Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				6 x PCB's - Fair condition (1 x possibly leaking - HMU to investigate) 10 March 2017 inspection signs of leaking		6		N	N
2599	INACTIVE	J	B111-00-3/714/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Swiss Cottage Stn	Other Boarding	Asbestos	Removed				DARK BROWN BOARD, THROUGHOUT, TO CEILING/WALLS AND METAL FRAMES (SOME LOOSE ON FLOOR), RELAY ROOM, 3/714 - 2021 Re-inspection confirmed removed as part of TCN ESN.			R699651	N	N
1572	ACTIVE	J	B111-00-3/714/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Swiss Cottage Stn	Cable: Sheath	Asbestos	Strongly Presumed				9 x Braided Cable Insulation 2021-Re-inspection 8 of 9 cables have been removed for TCP ESN but terminated ends remain (encapslated)		9		N	N
4006	ACTIVE	J	B111-00-3/715	SER - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1573	ACTIVE	J	B111-00-3/715/WAL-002	Wall: Internal - 2 - SER - Station Building - Swiss Cottage Stn	Boarding: Cement	Asbestos	Surveyed – Not Detected				Cement Boarding					
1574	ACTIVE	J	B111-00-3/715/WAL-002	Wall: Internal - 2 - SER - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing, Plaster / Solid					



Hazardous Material Asset Register - Summary



B111-00 - Station Building - Swiss Cottage Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1575	ACTIVE	J	B111-00-3/715/WAL-003	Wall: Internal - 3 - SER - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing, Plaster / Solid					
4007	ACTIVE	J	B111-00-3/716	SER - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2600	ACTIVE	J	B111-00-3/716	SER - Station Building - Swiss Cottage Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Plasterboard Boxing on Wall					
4008	ACTIVE	J	B111-00-3/761	CER - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1576	ACTIVE	J	B111-00-3/761/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Swiss Cottage Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boxing around Ducting					
2341	ACTIVE	J	B111-00-3/761/WAL-001	Wall: Internal - 1 - CER - Station Building - Swiss Cottage Stn	Isolator Switches	Asbestos	Strongly Presumed				2x Combination Fuse Switches 2 x 30 amps		2		N	N
68156	INACTIVE	J	B111-00-3/761/WAL-003 80834681	Wall: Internal - 3 - CER - Station Building - Swiss Cottage Stn Wall: Internal	Other Boarding	Asbestos	Strongly Presumed				Cladding fillets to floor of telephone cabinet	1				

C091-00 - Station Building - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4071	ACTIVE	J	C091-00-0/731	CER - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4072	ACTIVE	J	C091-00-0/751	Station Control Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4073	ACTIVE	J	C091-00-0/761	Equipment Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4074	ACTIVE	J	C091-00-0/781	Substation Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4075	ACTIVE	J	C091-00-0/901	Disused Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4076	ACTIVE	J	C091-00-1/001	Booking Hall - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4077	ACTIVE	J	C091-00-1/002	Booking Hall - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



C091-00 - Station Building - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4078	ACTIVE	J	C091-00-1/011	Ticket Office - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4079	ACTIVE	J	C091-00-1/012	Ticket Office - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4080	ACTIVE	J	C091-00-1/013	Ticket Office - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4081	ACTIVE	J	C091-00-1/021	POM - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4082	ACTIVE	J	C091-00-1/022	POM - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4083	ACTIVE	J	C091-00-1/023	POM - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4084	ACTIVE	J	C091-00-1/031	Mess Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4085	ACTIVE	J	C091-00-1/032	Mess Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4086	ACTIVE	J	C091-00-1/036	Toilet: Male - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4087	ACTIVE	J	C091-00-1/037	Toilet: Female - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4088	ACTIVE	J	C091-00-1/038	Toilet: Unisex - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4089	ACTIVE	J	C091-00-1/071	Circulation Area - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4090	ACTIVE	J	C091-00-1/072	Circulation Area - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4091	ACTIVE	J	C091-00-1/083	Lobby - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4092	ACTIVE	J	C091-00-1/084	Lobby - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



C091-00 - Station Building - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4093	ACTIVE	J	C091-00-1/085	Lobby - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4094	ACTIVE	J	C091-00-1/086	Lobby - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4095	ACTIVE	J	C091-00-1/087	Lobby - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4096	ACTIVE	J	C091-00-1/088	Lobby - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4097	ACTIVE	J	C091-00-1/089	Lobby - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4098	ACTIVE	J	C091-00-1/090	Lobby - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4099	ACTIVE	J	C091-00-1/091	Lobby - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4100	ACTIVE	J	C091-00-1/092	Lobby - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4101	ACTIVE	J	C091-00-1/093	Lobby - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4102	ACTIVE	J	C091-00-1/094	Lobby - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4103	ACTIVE	J	C091-00-1/131	Lift Pump Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4104	ACTIVE	J	C091-00-1/132	Lift Pump Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4105	ACTIVE	J	C091-00-1/133	Lift Pump Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4106	ACTIVE	J	C091-00-1/134	LMR - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4107	ACTIVE	J	C091-00-1/135	LMR - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



C091-00 - Station Building - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4108	ACTIVE	J	C091-00-1/201	Passage - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4109	ACTIVE	J	C091-00-1/205	Passage - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45379	ACTIVE	J	C091-00-1/205	Passage - Station Building - Stratford Stn		Asbestos	Strongly Presumed				Cables 2No/10mm - SP Running from caged area to end of corridor - 65metres away	10	2		N	N
4110	ACTIVE	J	C091-00-1/206	Passage - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4111	ACTIVE	J	C091-00-1/207	Passage - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4112	ACTIVE	J	C091-00-1/209	Passage - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4113	ACTIVE	J	C091-00-1/210	Passage - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4114	ACTIVE	J	C091-00-1/230	Toilet: Female - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4115	ACTIVE	J	C091-00-1/238	Passage - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4116	ACTIVE	J	C091-00-1/239	Passage - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4117	ACTIVE	J	C091-00-1/240	Passage - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4118	ACTIVE	J	C091-00-1/241	Passage - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4119	ACTIVE	J	C091-00-1/242	Passage - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4120	ACTIVE	J	C091-00-1/243	Passage - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4121	ACTIVE	J	C091-00-1/244	Passage - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



C091-00 - Station Building - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4122	ACTIVE	J	C091-00-1/261	Platform 13 - Eastbound Local - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4123	ACTIVE	J	C091-00-1/262	Platform 14 - Westbound Local - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4124	ACTIVE	J	C091-00-1/263	Platform 15 - Single Line Local - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4125	ACTIVE	J	C091-00-1/267	Platform 17 - DLR - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4126	ACTIVE	J	C091-00-1/268	Platform 16 - DLR - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4127	ACTIVE	J	C091-00-1/291	DMT Office - Station building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4128	ACTIVE	J	C091-00-1/311	Office - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4129	ACTIVE	J	C091-00-1/316	Toilet: Unisex - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4130	ACTIVE	J	C091-00-1/332	Mess Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4131	ACTIVE	J	C091-00-1/333	Mess Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4132	ACTIVE	J	C091-00-1/334	Mess Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4133	ACTIVE	J	C091-00-1/335	Disused Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4134	ACTIVE	J	C091-00-1/401	Store - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4135	ACTIVE	J	C091-00-1/407	Store - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4136	ACTIVE	J	C091-00-1/408	Switch Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



C091-00 - Station Building - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4137	ACTIVE	J	C091-00-1/413	Store - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4138	ACTIVE	J	C091-00-1/414	Store - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4139	ACTIVE	J	C091-00-1/415	Store - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4140	ACTIVE	J	C091-00-1/417	Toilet: Male - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4141	ACTIVE	J	C091-00-1/418	Locker Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4142	ACTIVE	J	C091-00-1/419	Locker Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4143	ACTIVE	J	C091-00-1/420	Toilet: Disabled - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4144	ACTIVE	J	C091-00-1/421	Toilet: Unisex - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4145	ACTIVE	J	C091-00-1/422	Toilet: Unisex - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4146	ACTIVE	J	C091-00-1/423	Toilet: Unisex - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4147	ACTIVE	J	C091-00-1/424	Toilet: Unisex - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4148	ACTIVE	J	C091-00-1/426	Toilet: Female - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4149	ACTIVE	J	C091-00-1/427	Toilet: Unisex - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4150	ACTIVE	J	C091-00-1/428	Toilet: Disabled - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4151	ACTIVE	J	C091-00-1/429	Toilet: Male - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



C091-00 - Station Building - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4152	ACTIVE	J	C091-00-1/451	Office - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4153	ACTIVE	J	C091-00-1/452	Tenancy - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4154	ACTIVE	J	C091-00-1/453	Tenancy - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4155	ACTIVE	J	C091-00-1/454	Tenancy - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4156	ACTIVE	J	C091-00-1/455	Tenancy - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4157	ACTIVE	J	C091-00-1/458	ATM - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4158	ACTIVE	J	C091-00-1/459	Tenancy - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4159	ACTIVE	J	C091-00-1/460	Tenancy - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4160	ACTIVE	J	C091-00-1/601	Stairs: Linear - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4161	ACTIVE	J	C091-00-1/602	Stairs: Linear - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4162	ACTIVE	J	C091-00-1/603	Stairs: Linear - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4163	ACTIVE	J	C091-00-1/604	Stairs: Linear - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4164	ACTIVE	J	C091-00-1/605	Stairs: Linear - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4165	ACTIVE	J	C091-00-1/606	Stairs: Linear - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4166	ACTIVE	J	C091-00-1/607	Stairs: Linear - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



C091-00 - Station Building - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4167	ACTIVE	J	C091-00-1/617	Stairs: Linear - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4168	ACTIVE	J	C091-00-1/624	Stairs: Linear - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4169	ACTIVE	J	C091-00-1/667	Switch Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4170	ACTIVE	J	C091-00-1/668	Switch Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4171	ACTIVE	J	C091-00-1/669	Switch Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4172	ACTIVE	J	C091-00-1/670	Switch Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4173	ACTIVE	J	C091-00-1/671	Switch Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4174	ACTIVE	J	C091-00-1/672	Switch Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4175	ACTIVE	J	C091-00-1/673	Switch Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4176	ACTIVE	J	C091-00-1/674	Switch Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4177	ACTIVE	J	C091-00-1/675	Switch Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4178	ACTIVE	J	C091-00-1/676	Switch Cupboard - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4179	ACTIVE	J	C091-00-1/677	Switch Cupboard - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4180	ACTIVE	J	C091-00-1/732	CER - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4181	ACTIVE	J	C091-00-1/735	CER - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



C091-00 - Station Building - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4182	ACTIVE	J	C091-00-1/746	SCR - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4183	ACTIVE	J	C091-00-1/751	Station Control Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4184	ACTIVE	J	C091-00-1/771	Pump Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4185	ACTIVE	J	C091-00-1/772	Pump Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4186	ACTIVE	J	C091-00-1/778	Fan Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4187	ACTIVE	J	C091-00-1/779	Plant Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4188	ACTIVE	J	C091-00-1/783	Plant Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4189	ACTIVE	J	C091-00-1/787	Service Riser - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4190	ACTIVE	J	C091-00-1/801	Mess Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4191	ACTIVE	J	C091-00-1/802	Office - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4192	ACTIVE	J	C091-00-1/803	Office - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4193	ACTIVE	J	C091-00-1/804	Office - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4194	ACTIVE	J	C091-00-1/901	Store - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4195	ACTIVE	J	C091-00-1/902	Store - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4196	ACTIVE	J	C091-00-1/904	Store - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



C091-00 - Station Building - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4197	ACTIVE	J	C091-00-1/912	Store - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4198	ACTIVE	J	C091-00-1/915	LMR - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4199	ACTIVE	J	C091-00-1/916	LMR - Station building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4200	ACTIVE	J	C091-00-1/917	Store - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4201	ACTIVE	J	C091-00-1/918	Store - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4202	ACTIVE	J	C091-00-1/919	Store - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4203	ACTIVE	J	C091-00-1/920	Store - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4204	ACTIVE	J	C091-00-2/131	LMC - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4205	ACTIVE	J	C091-00-2/208	Passage - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4206	ACTIVE	J	C091-00-2/576	Stairs: Linear - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4207	ACTIVE	J	C091-00-2/577	Stairs: Linear - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4208	ACTIVE	J	C091-00-3/131	LMC - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4209	ACTIVE	J	C091-00-A/001	Booking Hall - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4210	ACTIVE	J	C091-00-A/021	POM - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4211	ACTIVE	J	C091-00-A/071	Circulation Area - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



C091-00 - Station Building - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4212	ACTIVE	J	C091-00-A/082	Lobby - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4213	ACTIVE	J	C091-00-A/083	Lobby - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4214	ACTIVE	J	C091-00-A/084	Lobby - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4215	ACTIVE	J	C091-00-A/131	LEER - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4216	ACTIVE	J	C091-00-A/132	LEER- Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4217	ACTIVE	J	C091-00-A/133	LMR - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4218	ACTIVE	J	C091-00-A/134	LMR - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4219	ACTIVE	J	C091-00-A/135	LMR - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4220	ACTIVE	J	C091-00-A/151	UMC - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4221	ACTIVE	J	C091-00-A/152	UMC - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4222	ACTIVE	J	C091-00-A/204	Passage - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4223	ACTIVE	J	C091-00-A/205	Passage - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4224	ACTIVE	J	C091-00-A/206	Passage - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4225	ACTIVE	J	C091-00-A/234	Shower Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4226	ACTIVE	J	C091-00-A/237	Passage - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



C091-00 - Station Building - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4227	ACTIVE	J	C091-00-A/239	Passage - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4228	ACTIVE	J	C091-00-A/240	Lobby - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4229	ACTIVE	J	C091-00-A/241	Passage - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4230	ACTIVE	J	C091-00-A/242	Toilet: Unisex - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4231	ACTIVE	J	C091-00-A/261	Platform 3A - Network Rail - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4232	ACTIVE	J	C091-00-A/262	Platform 3 - Network Rail - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4233	ACTIVE	J	C091-00-A/263	Platform 5 - Network Rail - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4234	ACTIVE	J	C091-00-A/264	Platform 6 - Network Rail - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4235	ACTIVE	J	C091-00-A/265	Platform 8 - Network Rail - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4236	ACTIVE	J	C091-00-A/266	Platform 9 - Network Rail - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4237	ACTIVE	J	C091-00-A/267	Platform 10 - Network Rail - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4238	ACTIVE	J	C091-00-A/268	Platform 10A - Network Rail - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4239	ACTIVE	J	C091-00-A/269	Platform 11 - Network Rail - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4240	ACTIVE	J	C091-00-A/270	Platform 12 - Network Rail - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4241	ACTIVE	J	C091-00-A/272	Platform 2 - London Overground - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



C091-00 - Station Building - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4242	ACTIVE	J	C091-00-A/320	Locker Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4243	ACTIVE	J	C091-00-A/323	First Aid Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4244	ACTIVE	J	C091-00-A/336	Mess Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4245	ACTIVE	J	C091-00-A/337	Locker Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4246	ACTIVE	J	C091-00-A/339	Mess Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4247	ACTIVE	J	C091-00-A/406	Store - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4248	ACTIVE	J	C091-00-A/407	Switch Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4249	ACTIVE	J	C091-00-A/408	Store - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4250	ACTIVE	J	C091-00-A/409	Store - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4251	ACTIVE	J	C091-00-A/412	Store - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4252	ACTIVE	J	C091-00-A/413	Store - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4253	ACTIVE	J	C091-00-A/424	Toilet: Unisex - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4254	ACTIVE	J	C091-00-A/451	Tenancy - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4255	ACTIVE	J	C091-00-A/661	Switch Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4256	ACTIVE	J	C091-00-A/662	Switch Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



C091-00 - Station Building - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4257	ACTIVE	J	C091-00-A/663	Switch Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4258	ACTIVE	J	C091-00-A/664	Switch Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4259	ACTIVE	J	C091-00-A/665	UPS Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4260	ACTIVE	J	C091-00-A/666	Switch Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4261	ACTIVE	J	C091-00-A/668	Switch Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4262	ACTIVE	J	C091-00-A/672	Switch Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4263	ACTIVE	J	C091-00-A/731	CER - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4264	ACTIVE	J	C091-00-A/746	SCR - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4265	ACTIVE	J	C091-00-A/751	Station Control Room - Station building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4266	ACTIVE	J	C091-00-A/752	Station Control Room - Station building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4267	ACTIVE	J	C091-00-A/761	Equipment Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4268	ACTIVE	J	C091-00-A/762	Equipment Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4269	ACTIVE	J	C091-00-A/776	Plant Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4270	ACTIVE	J	C091-00-A/777	Plant Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4271	ACTIVE	J	C091-00-A/778	Plant Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



C091-00 - Station Building - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4272	ACTIVE	J	C091-00-A/801	Office - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4273	ACTIVE	J	C091-00-A/806	Office - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4274	ACTIVE	J	C091-00-A/807	Office - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4275	ACTIVE	J	C091-00-A/903	LMR - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4276	ACTIVE	J	C091-00-A/907	LMR - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4277	ACTIVE	J	C091-00-A/908	LMR - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4278	ACTIVE	J	C091-00-A/911	Void - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4279	ACTIVE	J	C091-00-B/001	Booking Hall - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4280	ACTIVE	J	C091-00-B/011	Ticket Office - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4281	ACTIVE	J	C091-00-B/012	Ticket Office - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4282	ACTIVE	J	C091-00-B/013	Ticket Office - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4283	ACTIVE	J	C091-00-B/021	POM - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4284	ACTIVE	J	C091-00-B/031	Mess Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4285	ACTIVE	J	C091-00-B/032	Mess Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4286	ACTIVE	J	C091-00-B/033	Mess Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



C091-00 - Station Building - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4287	ACTIVE	J	C091-00-B/036	Toilet: Male - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4288	ACTIVE	J	C091-00-B/037	Toilet: Female - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4289	ACTIVE	J	C091-00-B/047	Kitchen - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4290	ACTIVE	J	C091-00-B/048	Kitchen - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4291	ACTIVE	J	C091-00-B/071	Circulation Area - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4292	ACTIVE	J	C091-00-B/081	Lobby - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4293	ACTIVE	J	C091-00-B/082	Lobby - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4294	ACTIVE	J	C091-00-B/083	Lobby - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4295	ACTIVE	J	C091-00-B/084	Lobby - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4296	ACTIVE	J	C091-00-B/236	Passage - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4297	ACTIVE	J	C091-00-B/237	Passage - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4298	ACTIVE	J	C091-00-B/238	Passage - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4299	ACTIVE	J	C091-00-B/316	Locker Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4300	ACTIVE	J	C091-00-B/317	Locker Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4301	ACTIVE	J	C091-00-B/331	Mess Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



C091-00 - Station Building - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4302	ACTIVE	J	C091-00-B/332	Mess Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4303	ACTIVE	J	C091-00-B/402	Store - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4304	ACTIVE	J	C091-00-B/406	Store - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4305	ACTIVE	J	C091-00-B/407	Store - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4306	ACTIVE	J	C091-00-B/408	Store - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4307	ACTIVE	J	C091-00-B/411	Store - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4308	ACTIVE	J	C091-00-B/412	Store - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4309	ACTIVE	J	C091-00-B/416	Toilet: Female - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4310	ACTIVE	J	C091-00-B/417	Toilet: Male - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4311	ACTIVE	J	C091-00-B/426	Toilet: Male - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4312	ACTIVE	J	C091-00-B/427	Toilet: Female - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4313	ACTIVE	J	C091-00-B/451	ATM - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4314	ACTIVE	J	C091-00-B/452	Tenancy - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4315	ACTIVE	J	C091-00-B/576	Stairs: Linear - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4316	ACTIVE	J	C091-00-B/577	Stairs: Linear - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



C091-00 - Station Building - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4317	ACTIVE	J	C091-00-B/601	Stairs: Linear - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4318	ACTIVE	J	C091-00-B/602	Stairs: Linear - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4319	ACTIVE	J	C091-00-B/631	Stairs: Spiral - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4320	ACTIVE	J	C091-00-B/661	Switch Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4321	ACTIVE	J	C091-00-B/662	Cupboard - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4322	ACTIVE	J	C091-00-B/746	SCR - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4323	ACTIVE	J	C091-00-B/751	Station Control Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4324	ACTIVE	J	C091-00-B/771	SVC - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4325	ACTIVE	J	C091-00-B/786	Service Riser - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4326	ACTIVE	J	C091-00-B/787	Service Riser - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4327	ACTIVE	J	C091-00-B/789	Service Riser - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4328	ACTIVE	J	C091-00-B/790	Service Riser - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4329	ACTIVE	J	C091-00-B/801	Revenue Office - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4330	ACTIVE	J	C091-00-B/802	Training Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4331	ACTIVE	J	C091-00-B/901	Service Riser - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



C091-00 - Station Building - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4332	ACTIVE	J	C091-00-B/902	Store - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4333	ACTIVE	J	C091-00-C/776	Plant Room - Station Building - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

C125-00 - Station Building - Bond Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
68410	ACTIVE	J	C125-00-5/261	Platform 1 - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Known				Invert - Bitumen cable ducts To platform wall total 21 no.		21	R718686		Y
68416	ACTIVE	J	C125-00-5/261	Platform 1 - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Known				Invert - Bitumen cable ducts To platform wall total 3 no.		3	R718686		Y
68415	ACTIVE	J	C125-00-5/261	Platform 1 - Station Building - Bond Street Stn	Cable Sheath	Asbestos	Known				Invert - Cable wrapping/cloth To pipe by trackside wall<1m.	1		R718686		
68419	ACTIVE	J	C125-00-5/261	Platform 1 - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Known				Invert - Bitumen cable ducts To platform wall total 6 no.		6	R718686		Y
68420	ACTIVE	J	C125-00-5/261	Platform 1 - Station Building - Bond Street Stn	Westinghouse Boxes	Asbestos	Presumed				Invert - Materials within small Westinghouse box To J Hanger - middle wall total 1 no.		1	R718686		
68423	ACTIVE	J	C125-00-5/261	Platform 1 - Station Building - Bond Street Stn	Cable Sheath	Asbestos	Known				Invert - Braided cable To trackside wall - head wall total 1 no.		1	R718686		
68411	ACTIVE	J	C125-00-5/261	Platform 1 - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen cable duct To trackside wall total 1 no.		1	R718686		Y
68417	ACTIVE	J	C125-00-5/261	Platform 1 - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Known				Invert - Bitumen cable ducts To platform wall total 8 no.		8	R718686		Y
68412	ACTIVE	J	C125-00-5/261	Platform 1 - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Known				Invert - Bitumen cable ducts To platform side wall total 4 no.		4	R718686		Y
68414	ACTIVE	J	C125-00-5/261	Platform 1 - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen cable ducts To platform side wall total 5 no.		5	R718686		Y
68418	ACTIVE	J	C125-00-5/261	Platform 1 - Station Building - Bond Street Stn	Cable Sheath	Asbestos	Known				Invert - Braided cables To J Hanger - middle wall total 2 no.		2	R718686		
68422	ACTIVE	J	C125-00-5/261	Platform 1 - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen cable ducts To trackside wall - head wall total 6 no.		6	R718686		Y
68424	ACTIVE	J	C125-00-5/261	Platform 1 - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Known				Invert - Bitumen cable ducts To platform side wall total 6 no.		6	R718686		Y
68736	ACTIVE	J	C125-00-5/261	Platform 1 - Station Building - Bond Street Stn	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Invert - Metal tunnel rings - concrete infill To walls, floor throughout.			R718686		



Hazardous Material Asset Register - Summary



C125-00 - Station Building - Bond Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
68737	ACTIVE	J	C125-00-5/261	Platform 1 - Station Building - Bond Street Stn	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Invert - Grout/ wood/ lead To tunnel rings flanges throughout.			R718686		
68413	ACTIVE	J	C125-00-5/261	Platform 1 - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Known				Invert - Bitumen cable ducts To platform side wall total 6 no.		6	R718686		Y
68407	ACTIVE	J	C125-00-5/261	Platform 1 - Station Building - Bond Street Stn	Caulking	Asbestos	Sampled – Not Detected				Invert - Metal tunnel rings - concrete infill To walls, floor throughout.			R718686		Y
68408	ACTIVE	J	C125-00-5/261	Platform 1 - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen cable ducts To tail wall total 6 no.		6	R718686		Y
68409	ACTIVE	J	C125-00-5/261	Platform 1 - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen cable ducts To trackside wall total 6 no.		6	R718686		Y
68425	ACTIVE	J	C125-00-5/261	Platform 1 - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen cable duct To platform side wall total 1 no.		1	R718686		Y
68439	ACTIVE	J	C125-00-5/262	Platform 2 - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen cable ducts To trackside wall total 2 no.		2	R718686		Y
68739	ACTIVE	J	C125-00-5/262	Platform 2 - Station Building - Bond Street Stn	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Invert - Grout/ wood/ lead To tunnel rings flanges throughout.			R718686		
68437	ACTIVE	J	C125-00-5/262	Platform 2 - Station Building - Bond Street Stn	Cable Ducts: Cement	Asbestos	Known				Invert - Cement cable ducts To trackside wall total 4 no.		4	R718686		Y
68436	ACTIVE	J	C125-00-5/262	Platform 2 - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Known				Invert - Bitumen cable ducts To platform side wall total 6 no.		6	R718686		Y
68434	ACTIVE	J	C125-00-5/262	Platform 2 - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen cable ducts To trackside wall total 2 no.		2	R718686		Y
68433	ACTIVE	J	C125-00-5/262	Platform 2 - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen cable ducts To platform wall total 8 no.		8	R718686		Y
68432	ACTIVE	J	C125-00-5/262	Platform 2 - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen cable ducts To platform wall total 8 no.		8	R718686		Y
68431	ACTIVE	J	C125-00-5/262	Platform 2 - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen cable ducts To platform wall total 6 no.		6	R718686		Y
68738	ACTIVE	J	C125-00-5/262	Platform 2 - Station Building - Bond Street Stn	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Invert - Metal tunnel rings - concrete infill To walls, floor throughout.			R718686		
68429	ACTIVE	J	C125-00-5/262	Platform 2 - Station Building - Bond Street Stn	Westinghouse Boxes	Asbestos	Presumed				Invert - Materials within small Westinghouse box To J Hanger - middle wall Total 1 no.		1	R718686		
68428	ACTIVE	J	C125-00-5/262	Platform 2 - Station Building - Bond Street Stn	Cable Sheath	Asbestos	Known				Invert - Braided cable To J Hanger - trackside wall total 1 no.		1	R718686		
68427	ACTIVE	J	C125-00-5/262	Platform 2 - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen cable ducts To head wall total 6 no.		6	R718686		Y
68426	ACTIVE	J	C125-00-5/262	Platform 2 - Station Building - Bond Street Stn	Caulking	Asbestos	Sampled – Not Detected				Invert - Metal tunnel rings - concrete infill To walls, floor throughout.			R718686		Y



Hazardous Material Asset Register - Summary



C125-00 - Station Building - Bond Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
68438	ACTIVE	J	C125-00-5/262	Platform 2 - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen cable ducts To trackside wall total 6 no.		6	R718686		Y
68435	ACTIVE	J	C125-00-5/262	Platform 2 - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Known				Invert - Bitumen cable ducts To platform side wall total 8 no.		8	R718686		Y
68440	ACTIVE	J	C125-00-5/262	Platform 2 - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen cable ducts To trackside wall - head wall total 4 no.		4	R718686		Y
4456	ACTIVE	J	C125-00-6/261	Platform 3 - Northbound Local - Station Building - Bond Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
68471	ACTIVE	J	C125-00-6/261	Platform 3 - Northbound Local - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen cable ducts To tail wall total 2 no.		2	R718687		Y
68743	ACTIVE	J	C125-00-6/261	Platform 3 - Northbound Local - Station Building - Bond Street Stn	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Invert - Caulking To tunnel rings flanges throughout.			R718687		
68468	ACTIVE	J	C125-00-6/261	Platform 3 - Northbound Local - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen cable ducts To platform wall total 1 no.		1	R718687		Y
68466	ACTIVE	J	C125-00-6/261	Platform 3 - Northbound Local - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen cable ducts To platform wall total 11 no.		11	R718687		Y
68462	ACTIVE	J	C125-00-6/261	Platform 3 - Northbound Local - Station Building - Bond Street Stn	Cable Sheath	Asbestos	Known				Invert - Braided cables To platform wall total 1 no.		1	R718687		
68453	ACTIVE	J	C125-00-6/261	Platform 3 - Northbound Local - Station Building - Bond Street Stn	Caulking	Asbestos	Sampled – Not Detected				Invert - Metal tunnel rings - concrete infill To walls, floor.			R718687		Y
68458	ACTIVE	J	C125-00-6/261	Platform 3 - Northbound Local - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen cable ducts To trackside wall total 6 no.		6	R718687		Y
68460	ACTIVE	J	C125-00-6/261	Platform 3 - Northbound Local - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert -Bitumen cable ducts To head wall total 2 no.		2	R718687		Y
68465	ACTIVE	J	C125-00-6/261	Platform 3 - Northbound Local - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen cable ducts To platform wall total 10 no.		10	R718687		Y
68461	ACTIVE	J	C125-00-6/261	Platform 3 - Northbound Local - Station Building - Bond Street Stn	Cable Sheath	Asbestos	Known				Invert - Braided cables To trackside wall total 15 no.		15	R718687		
68455	ACTIVE	J	C125-00-6/261	Platform 3 - Northbound Local - Station Building - Bond Street Stn	Caulking	Asbestos	Known				Invert - Caulking Concealed beneath concrete floor and wall throughout, unable to make material assessment throughout.			R718687		Y



Hazardous Material Asset Register - Summary



C125-00 - Station Building - Bond Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
68454	ACTIVE	J	C125-00-6/261	Platform 3 - Northbound Local - Station Building - Bond Street Stn	Caulking	Asbestos	Sampled – Not Detected				Invert - Caulking To tunnel rings flanges throughout.			R718687		Y
68742	ACTIVE	J	C125-00-6/261	Platform 3 - Northbound Local - Station Building - Bond Street Stn	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Invert - Metal tunnel rings - concrete infill To walls, floor.			R718687		
68469	ACTIVE	J	C125-00-6/261	Platform 3 - Northbound Local - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen cable ducts To trackside wall total 6 no.		6	R718687		Y
4457	ACTIVE	J	C125-00-6/262	Platform 4 - Southbound Local - Station Building - Bond Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
68741	ACTIVE	J	C125-00-6/262	Platform 4 - Southbound Local - Station Building - Bond Street Stn	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Invert - Caulking To tunnel rings flanges throughout.			R718687		
68740	ACTIVE	J	C125-00-6/262	Platform 4 - Southbound Local - Station Building - Bond Street Stn	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Invert - Metal tunnel rings - concrete infill To walls, floor.			R718687		
68441	ACTIVE	J	C125-00-6/262	Platform 4 - Southbound Local - Station Building - Bond Street Stn	Caulking	Asbestos	Sampled – Not Detected				Invert - Metal tunnel rings - concrete infill To walls, floor.			R718687		Y
68443	ACTIVE	J	C125-00-6/262	Platform 4 - Southbound Local - Station Building - Bond Street Stn	Cable Sheath	Asbestos	Known				Invert - Braided cables To trackside wall - throughout total 15 no.		15	R718687		
68445	ACTIVE	J	C125-00-6/262	Platform 4 - Southbound Local - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen cable ducts To trackside wall- tail end total 6 no.		6	R718687		Y
68446	ACTIVE	J	C125-00-6/262	Platform 4 - Southbound Local - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen cable ducts To platform wall total 8 no.		8	R718687		Y
68447	ACTIVE	J	C125-00-6/262	Platform 4 - Southbound Local - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen cable ducts To platform wall total 11 no.		11	R718687		Y
68448	ACTIVE	J	C125-00-6/262	Platform 4 - Southbound Local - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen duct To platform wall total 1 no.		1	R718687		Y
68450	ACTIVE	J	C125-00-6/262	Platform 4 - Southbound Local - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen cable ducts Trackside wall - head end total 6 no.		6	R718687		Y
68451	ACTIVE	J	C125-00-6/262	Platform 4 - Southbound Local - Station Building - Bond Street Stn	Caulking	Asbestos	Known				Invert - Caulking Concealed beneath concrete floor and wall throughout, unable to make material assessment - throughout.			R718687		Y
68442	ACTIVE	J	C125-00-6/262	Platform 4 - Southbound Local - Station Building - Bond Street Stn	Caulking	Asbestos	Sampled – Not Detected				Invert - Caulking To tunnel rings flanges throughout.			R718687		Y



Hazardous Material Asset Register - Summary



C125-00 - Station Building - Bond Street Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
68444	ACTIVE	J	C125-00-6/262	Platform 4 - Southbound Local - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen cable ducts To tail wall total 2 no.		2	R718687		Y
68449	ACTIVE	J	C125-00-6/262	Platform 4 - Southbound Local - Station Building - Bond Street Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen cable ducts To head wall total 2 no.		2	R718687		Y
53688	ACTIVE	J	C125-00-6/711	Relay Room - Station Building - Bond Street Stn		Asbestos	Room: Not Surveyed – Asbestos Presumed									
53691	ACTIVE	J	C125-00-6/711	Relay Room - Station Building - Bond Street Stn	Other Boarding	Asbestos	Sampled – Not Detected				brown composite panels throughout used as packing to framework					
53689	ACTIVE	J	C125-00-6/711	Relay Room - Station Building - Bond Street Stn	Cable: Sheath	Asbestos	Strongly Presumed				Woven Cables 2 no x 40mm diameter cable, 1 no x 15mm diameter cable, 25 no x 10mm diameter cable, 2 no x 20mm diameter cable, 2 no x 10mm diameter cable running to platform via wall 4, high level 32no					
53690	ACTIVE	J	C125-00-6/711	Relay Room - Station Building - Bond Street Stn	Other Electrical Boxes	Asbestos	Presumed				600v electrical box with board backing and 2 x green asbestos cables					
53687	ACTIVE	J	C125-00-6/711/ WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Bond Street Stn	Other Boarding	Asbestos	Strongly Presumed				Wall 1 rack 6 x square brown panels and 12 x long brown panels to rack no 1 12 x base panels					
4458	ACTIVE	J	C125-00-6/716	SER - Station Building - Bond Street Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

D039-00 - Station Building - West Ham Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4514	ACTIVE	J	D039-00-1/001	Booking Hall - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4515	ACTIVE	J	D039-00-1/011	Ticket Office - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4516	ACTIVE	J	D039-00-1/022	POM - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4517	ACTIVE	J	D039-00-1/036	Toilet: Unisex - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4518	ACTIVE	J	D039-00-1/071	Circulation Area - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D039-00 - Station Building - West Ham Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4519	ACTIVE	J	D039-00-1/072	Circulation Area - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4520	ACTIVE	J	D039-00-1/073	Circulation Area - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4521	ACTIVE	J	D039-00-1/074	Circulation Area - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4522	ACTIVE	J	D039-00-1/081	Lobby - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4523	ACTIVE	J	D039-00-1/082	Lobby - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4524	ACTIVE	J	D039-00-1/083	Lobby - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4525	ACTIVE	J	D039-00-1/100	Service Riser - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4526	ACTIVE	J	D039-00-1/121	Platform Invert - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4527	ACTIVE	J	D039-00-1/122	Platform Invert - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4528	ACTIVE	J	D039-00-1/123	Platform Invert - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4529	ACTIVE	J	D039-00-1/124	Platform Invert - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4530	ACTIVE	J	D039-00-1/125	Platform Invert - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4531	ACTIVE	J	D039-00-1/126	Platform Invert - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4532	ACTIVE	J	D039-00-1/127	Platform Invert - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4533	ACTIVE	J	D039-00-1/128	Platform Invert - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D039-00 - Station Building - West Ham Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4534	ACTIVE	J	D039-00-1/129	Platform Invert - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4535	ACTIVE	J	D039-00-1/130	Platform Invert - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4536	ACTIVE	J	D039-00-1/131	Platform Invert - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4537	ACTIVE	J	D039-00-1/132	Platform Invert - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4538	ACTIVE	J	D039-00-1/133	Platform Invert - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4539	ACTIVE	J	D039-00-1/134	Platform Invert - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4540	ACTIVE	J	D039-00-1/135	Platform Invert - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4541	ACTIVE	J	D039-00-1/140	Lift Pump Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4542	ACTIVE	J	D039-00-1/174	Store - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4543	ACTIVE	J	D039-00-1/236	Passage - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4544	ACTIVE	J	D039-00-1/237	Passage - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4545	ACTIVE	J	D039-00-1/238	Passage - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4546	ACTIVE	J	D039-00-1/239	Passage - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4547	ACTIVE	J	D039-00-1/240	Passage - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4548	ACTIVE	J	D039-00-1/241	Passage - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D039-00 - Station Building - West Ham Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4549	ACTIVE	J	D039-00-1/263	Platform 3 - DLR - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4550	ACTIVE	J	D039-00-1/264	Platform 4 - DLR - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4551	ACTIVE	J	D039-00-1/265	Platform 5 - Westbound Local - Jubilee Line - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4552	ACTIVE	J	D039-00-1/266	Platform 6 - Eastbound Local - Jubilee Line - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4553	ACTIVE	J	D039-00-1/371	Store - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4554	ACTIVE	J	D039-00-1/372	Shower Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4555	ACTIVE	J	D039-00-1/396	SVC - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4556	ACTIVE	J	D039-00-1/401	Bin Store - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4557	ACTIVE	J	D039-00-1/406	Store - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4558	ACTIVE	J	D039-00-1/407	Store - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4559	ACTIVE	J	D039-00-1/411	Store - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4560	ACTIVE	J	D039-00-1/412	Office - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4561	ACTIVE	J	D039-00-1/413	Cleaners Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4562	ACTIVE	J	D039-00-1/414	Service Riser - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4563	ACTIVE	J	D039-00-1/415	Locker Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D039-00 - Station Building - West Ham Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4564	ACTIVE	J	D039-00-1/420	Toilet: Unisex - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4565	ACTIVE	J	D039-00-1/451	Tenancy - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4566	ACTIVE	J	D039-00-1/452	Tenancy - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4567	ACTIVE	J	D039-00-1/453	Tenancy - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4568	ACTIVE	J	D039-00-1/481	Store - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4569	ACTIVE	J	D039-00-1/482	Store - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4570	ACTIVE	J	D039-00-1/576	Stairs: Linear - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4571	ACTIVE	J	D039-00-1/577	Stairs: Linear - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4572	ACTIVE	J	D039-00-1/578	Stairs: Linear - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4573	ACTIVE	J	D039-00-1/579	Stairs: Linear - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4574	ACTIVE	J	D039-00-1/580	Stairs: Linear - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4575	ACTIVE	J	D039-00-1/601	Stairs: Linear - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4576	ACTIVE	J	D039-00-1/602	Stairs: Linear - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4577	ACTIVE	J	D039-00-1/603	Stairs: Linear - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4578	ACTIVE	J	D039-00-1/604	Stairs: Linear - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D039-00 - Station Building - West Ham Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4579	ACTIVE	J	D039-00-1/631	Stairs: Spiral - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4580	ACTIVE	J	D039-00-1/661	Switch Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4581	ACTIVE	J	D039-00-1/662	Switch Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4582	ACTIVE	J	D039-00-1/664	Switch Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4583	ACTIVE	J	D039-00-1/665	Switch Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4584	ACTIVE	J	D039-00-1/666	Switch Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4585	ACTIVE	J	D039-00-1/701	SER - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4586	ACTIVE	J	D039-00-1/731	CER - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4587	ACTIVE	J	D039-00-1/732	CER - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4588	ACTIVE	J	D039-00-1/733	CER - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4589	ACTIVE	J	D039-00-1/746	SCR - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4590	ACTIVE	J	D039-00-1/751	Station Control Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4591	ACTIVE	J	D039-00-1/752	CER - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4592	ACTIVE	J	D039-00-1/761	Switch Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4593	ACTIVE	J	D039-00-1/762	Equipment Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D039-00 - Station Building - West Ham Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4594	ACTIVE	J	D039-00-1/771	Lift Pump Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4595	ACTIVE	J	D039-00-1/781	Substation Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4596	ACTIVE	J	D039-00-1/782	Substation Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4597	ACTIVE	J	D039-00-1/783	Substation Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4598	ACTIVE	J	D039-00-1/784	TXR - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4599	ACTIVE	J	D039-00-1/785	TXR - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4600	ACTIVE	J	D039-00-1/786	Service Riser - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4601	ACTIVE	J	D039-00-1/801	Station Supervisor Office - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4602	ACTIVE	J	D039-00-1/905	Service Area - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4603	ACTIVE	J	D039-00-1/906	Service Area - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4604	ACTIVE	J	D039-00-1/907	Void - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4605	ACTIVE	J	D039-00-1/908	Service Riser - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4606	ACTIVE	J	D039-00-1/909	Void - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4607	ACTIVE	J	D039-00-1/910	Store - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4608	ACTIVE	J	D039-00-1/911	Plant Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D039-00 - Station Building - West Ham Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4609	ACTIVE	J	D039-00-1/912	Platform Invert - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4610	ACTIVE	J	D039-00-2/131	LMR - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4611	ACTIVE	J	D039-00-2/136	LMC - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4612	ACTIVE	J	D039-00-2/161	LMC - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4613	ACTIVE	J	D039-00-2/162	LMC - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4614	ACTIVE	J	D039-00-2/163	LMC - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4615	ACTIVE	J	D039-00-2/236	Passage - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4616	ACTIVE	J	D039-00-2/237	Passage - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4617	ACTIVE	J	D039-00-A/151	UMC - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4618	ACTIVE	J	D039-00-A/152	UMC - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4619	ACTIVE	J	D039-00-A/153	UMC - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4620	ACTIVE	J	D039-00-A/236	Passage - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4621	ACTIVE	J	D039-00-A/261	Platform 1 - Wesbound Local - District/Hammersmith & City Line - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4622	ACTIVE	J	D039-00-A/262	Platform 2 - Eastbound Local - District/Hammersmith & City Line - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D039-00 - Station Building - West Ham Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4623	ACTIVE	J	D039-00-A/316	Locker Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4624	ACTIVE	J	D039-00-A/331	Mess Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4625	ACTIVE	J	D039-00-A/332	Kitchen - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4626	ACTIVE	J	D039-00-A/411	Store - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4627	ACTIVE	J	D039-00-A/416	Toilet: Male - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4628	ACTIVE	J	D039-00-A/417	Toilet: Female - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4629	ACTIVE	J	D039-00-A/576	Stairs: Linear - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4630	ACTIVE	J	D039-00-A/577	Stairs: Linear - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4631	ACTIVE	J	D039-00-A/578	Stairs: Linear - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4632	ACTIVE	J	D039-00-A/601	Stairs: Linear - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4633	ACTIVE	J	D039-00-A/661	Switch Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4634	ACTIVE	J	D039-00-A/662	Switch Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4635	ACTIVE	J	D039-00-A/701	Fan Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4636	ACTIVE	J	D039-00-A/731	CER - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4637	ACTIVE	J	D039-00-A/761	Fan Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D039-00 - Station Building - West Ham Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4638	ACTIVE	J	D039-00-A/776	Fan Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4639	ACTIVE	J	D039-00-A/777	Fan Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4640	ACTIVE	J	D039-00-A/778	Fan Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4641	ACTIVE	J	D039-00-A/779	Fan Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4642	ACTIVE	J	D039-00-A/780	Fan Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4643	ACTIVE	J	D039-00-A/786	Service Riser - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4644	ACTIVE	J	D039-00-A/901	Service Riser - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4645	ACTIVE	J	D039-00-A/904	Fan Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4646	ACTIVE	J	D039-00-A/905	Service Area - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4647	ACTIVE	J	D039-00-A/906	Fan Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4648	ACTIVE	J	D039-00-B/071	Circulation Area - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4649	ACTIVE	J	D039-00-B/072	Circulation Area - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4650	ACTIVE	J	D039-00-B/074	Circulation Area - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4651	ACTIVE	J	D039-00-B/201	Passage - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4652	ACTIVE	J	D039-00-B/202	Passage - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D039-00 - Station Building - West Ham Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4653	ACTIVE	J	D039-00-B/203	Passage - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4654	ACTIVE	J	D039-00-B/204	Passage - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4655	ACTIVE	J	D039-00-B/576	Stairs: Linear - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4656	ACTIVE	J	D039-00-B/577	Stairs: Linear - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4657	ACTIVE	J	D039-00-B/632	Stairs: Spiral - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4658	ACTIVE	J	D039-00-B/661	Switch Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4659	ACTIVE	J	D039-00-B/662	Switch Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4660	ACTIVE	J	D039-00-B/731	CER - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4661	ACTIVE	J	D039-00-B/779	Plant Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4662	ACTIVE	J	D039-00-C/761	Equipment Room - Station Building - West Ham Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

D101-00 - Station Building - Westminster Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4663	ACTIVE	J	D101-00-10/081	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4664	ACTIVE	J	D101-00-10/082	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4665	ACTIVE	J	D101-00-10/166	LMC - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D101-00 - Station Building - Westminster Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4666	ACTIVE	J	D101-00-10/167	LMC - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4667	ACTIVE	J	D101-00-10/236	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4668	ACTIVE	J	D101-00-10/237	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4669	ACTIVE	J	D101-00-10/238	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4670	ACTIVE	J	D101-00-10/239	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4671	ACTIVE	J	D101-00-10/240	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4672	ACTIVE	J	D101-00-10/261	Platform Invert - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4673	ACTIVE	J	D101-00-10/481	Pump Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4674	ACTIVE	J	D101-00-10/576	Stairs: Linear - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4675	ACTIVE	J	D101-00-10/711	SER - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4676	ACTIVE	J	D101-00-10/771	Pump Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4677	ACTIVE	J	D101-00-10/776	Pump Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4678	ACTIVE	J	D101-00-10/902	Store - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4679	ACTIVE	J	D101-00-10/903	Disused Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4680	ACTIVE	J	D101-00-10/904	Disused Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D101-00 - Station Building - Westminster Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4681	ACTIVE	J	D101-00-10/905	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4682	ACTIVE	J	D101-00-2/001	Booking Hall - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4683	ACTIVE	J	D101-00-2/011	Ticket Office - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4684	ACTIVE	J	D101-00-2/021	POM - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4685	ACTIVE	J	D101-00-2/031	Mess Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4686	ACTIVE	J	D101-00-2/036	Toilet: Unisex - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4687	ACTIVE	J	D101-00-2/047	Kitchen - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4688	ACTIVE	J	D101-00-2/071	Circulation Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4689	ACTIVE	J	D101-00-2/081	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4690	ACTIVE	J	D101-00-2/082	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4691	ACTIVE	J	D101-00-2/084	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4692	ACTIVE	J	D101-00-2/085	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4693	ACTIVE	J	D101-00-2/086	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4694	ACTIVE	J	D101-00-2/201	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4695	ACTIVE	J	D101-00-2/202	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D101-00 - Station Building - Westminster Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4696	ACTIVE	J	D101-00-2/236	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4697	ACTIVE	J	D101-00-2/238	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4698	ACTIVE	J	D101-00-2/240	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4699	ACTIVE	J	D101-00-2/241	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4700	ACTIVE	J	D101-00-2/281	Reception Office - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4701	ACTIVE	J	D101-00-2/301	Office - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4702	ACTIVE	J	D101-00-2/302	Equipment Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4703	ACTIVE	J	D101-00-2/311	Office - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4704	ACTIVE	J	D101-00-2/331	Locker Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4705	ACTIVE	J	D101-00-2/341	Mess Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4706	ACTIVE	J	D101-00-2/396	SVC - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4707	ACTIVE	J	D101-00-2/406	Store - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4708	ACTIVE	J	D101-00-2/411	Store - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4709	ACTIVE	J	D101-00-2/412	Bin Store - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4710	ACTIVE	J	D101-00-2/413	Store - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D101-00 - Station Building - Westminster Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4711	ACTIVE	J	D101-00-2/416	Toilet: Unisex - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4712	ACTIVE	J	D101-00-2/417	Toilet: Male - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4713	ACTIVE	J	D101-00-2/418	Toilet: Female - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4714	ACTIVE	J	D101-00-2/419	Disused Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4715	ACTIVE	J	D101-00-2/451	Tenancy - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4716	ACTIVE	J	D101-00-2/452	Tenancy - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4717	ACTIVE	J	D101-00-2/453	Tenancy - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4718	ACTIVE	J	D101-00-2/501	BTP Office - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4719	ACTIVE	J	D101-00-2/601	Stairs: Linear - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4720	ACTIVE	J	D101-00-2/603	Stairs: Linear - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4721	ACTIVE	J	D101-00-2/631	Stairs: Linear - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4722	ACTIVE	J	D101-00-2/661	Switch Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4723	ACTIVE	J	D101-00-2/663	Switch Cupboard - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4724	ACTIVE	J	D101-00-2/701	Circulation Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4725	ACTIVE	J	D101-00-2/731	CER - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D101-00 - Station Building - Westminster Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4726	ACTIVE	J	D101-00-2/746	SCR - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4727	ACTIVE	J	D101-00-2/751	Station Control Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4728	ACTIVE	J	D101-00-2/761	Equipment Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4729	ACTIVE	J	D101-00-2/781	Switch Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4730	ACTIVE	J	D101-00-2/787	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4731	ACTIVE	J	D101-00-2/788	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4732	ACTIVE	J	D101-00-2/789	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4733	ACTIVE	J	D101-00-2/790	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4734	ACTIVE	J	D101-00-2/901	Disused Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4735	ACTIVE	J	D101-00-2/902	Disused Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4736	ACTIVE	J	D101-00-2/903	Void - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4737	ACTIVE	J	D101-00-2/904	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4738	ACTIVE	J	D101-00-2/905	Pump Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4739	ACTIVE	J	D101-00-2/906	Equipment Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4740	ACTIVE	J	D101-00-2/TA1	Tenancy - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D101-00 - Station Building - Westminster Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4741	ACTIVE	J	D101-00-2/TA2	Tenancy - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4742	ACTIVE	J	D101-00-3/081	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4743	ACTIVE	J	D101-00-3/082	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4744	ACTIVE	J	D101-00-3/083	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4745	ACTIVE	J	D101-00-3/084	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4746	ACTIVE	J	D101-00-3/085	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4747	ACTIVE	J	D101-00-3/086	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4748	ACTIVE	J	D101-00-3/087	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4749	ACTIVE	J	D101-00-3/088	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4750	ACTIVE	J	D101-00-3/151	UMC - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4751	ACTIVE	J	D101-00-3/236	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4752	ACTIVE	J	D101-00-3/261	Platform 1 - Westbound Local - District/Circle - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4753	ACTIVE	J	D101-00-3/262	Platform 2 - Eastbound Local - District/Circle - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4754	ACTIVE	J	D101-00-3/331	Locker Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4755	ACTIVE	J	D101-00-3/371	Store - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D101-00 - Station Building - Westminster Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4756	ACTIVE	J	D101-00-3/406	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4757	ACTIVE	J	D101-00-3/412	Store - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4758	ACTIVE	J	D101-00-3/416	Shower Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4759	ACTIVE	J	D101-00-3/417	Toilet: Unisex - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4760	ACTIVE	J	D101-00-3/418	Toilet: Unisex - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4761	ACTIVE	J	D101-00-3/419	Shower Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4762	ACTIVE	J	D101-00-3/481	Store - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4763	ACTIVE	J	D101-00-3/601	Stairs: Linear - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4764	ACTIVE	J	D101-00-3/602	Stairs: Linear - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4765	ACTIVE	J	D101-00-3/631	Stairs: Spiral - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4766	ACTIVE	J	D101-00-3/632	Stairs: Spiral - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4767	ACTIVE	J	D101-00-3/633	Stairs: Spiral - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4768	ACTIVE	J	D101-00-3/661	Switch Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4769	ACTIVE	J	D101-00-3/662	Switch Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4770	ACTIVE	J	D101-00-3/664	Switch Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D101-00 - Station Building - Westminster Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4771	ACTIVE	J	D101-00-3/665	Switch Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4772	ACTIVE	J	D101-00-3/731	Relay Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4773	ACTIVE	J	D101-00-3/733	CER - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4774	ACTIVE	J	D101-00-3/771	Lift Pump Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4775	ACTIVE	J	D101-00-3/778	Fan Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4776	ACTIVE	J	D101-00-3/786	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42993	ACTIVE	J	D101-00-3/786	Service Area - Station Building - Westminster Stn	Cable Ducts: Bitumen	Asbestos	Known				Bitumen ducts, 22 no, entering at trackside at corner of room in Service Area 3/786 at Westminster Station. Re-inspection by HMT.			R525826	N	N
42992	ACTIVE	J	D101-00-3/786	Service Area - Station Building - Westminster Stn	Cable Ducts: Bitumen	Asbestos	Known				Bitumen ducts, 20 no, entering from Platform 2 side RHS of door in Service Area 3/786 at Westminster Station. Re-inspection by HMT.			R525826	N	N
4777	ACTIVE	J	D101-00-3/787	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4778	ACTIVE	J	D101-00-3/788	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4779	ACTIVE	J	D101-00-3/901	Locker Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4780	ACTIVE	J	D101-00-3/902	Disused Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4781	ACTIVE	J	D101-00-3/904	ATM - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4782	ACTIVE	J	D101-00-4/121	Platform Invert - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4783	ACTIVE	J	D101-00-4/122	Platform Invert - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D101-00 - Station Building - Westminster Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4784	ACTIVE	J	D101-00-4/152	UMC - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4785	ACTIVE	J	D101-00-4/153	UMC - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4786	ACTIVE	J	D101-00-4/576	Stairs: Linear - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4787	ACTIVE	J	D101-00-4/577	Stairs: Linear - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4788	ACTIVE	J	D101-00-4/578	Stairs: Linear - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4789	ACTIVE	J	D101-00-4/776	Fan Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4790	ACTIVE	J	D101-00-4/777	Fan Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4791	ACTIVE	J	D101-00-4/778	Bin Store - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4792	ACTIVE	J	D101-00-4/786	Service Riser - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4793	ACTIVE	J	D101-00-4/903	Service Riser - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4794	ACTIVE	J	D101-00-4/904	Disused Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4795	ACTIVE	J	D101-00-4/905	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4796	ACTIVE	J	D101-00-4/906	Disused Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4797	ACTIVE	J	D101-00-4/907	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4798	ACTIVE	J	D101-00-4/908	Disused Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D101-00 - Station Building - Westminster Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4799	ACTIVE	J	D101-00-4/910	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4800	ACTIVE	J	D101-00-5/071	Circulation Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4801	ACTIVE	J	D101-00-5/072	Circulation Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4802	ACTIVE	J	D101-00-5/073	Circulation Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4803	ACTIVE	J	D101-00-5/074	Circulation Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4804	ACTIVE	J	D101-00-5/081	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4805	ACTIVE	J	D101-00-5/082	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4806	ACTIVE	J	D101-00-5/083	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4807	ACTIVE	J	D101-00-5/084	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4808	ACTIVE	J	D101-00-5/085	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4809	ACTIVE	J	D101-00-5/236	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4810	ACTIVE	J	D101-00-5/237	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4811	ACTIVE	J	D101-00-5/238	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4812	ACTIVE	J	D101-00-5/576	Stairs: Linear - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4813	ACTIVE	J	D101-00-5/601	Stairs: Linear - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D101-00 - Station Building - Westminster Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4814	ACTIVE	J	D101-00-5/602	Stairs: Linear - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4815	ACTIVE	J	D101-00-5/631	Stairs: Spiral - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4816	ACTIVE	J	D101-00-5/633	Stairs: Spiral - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4817	ACTIVE	J	D101-00-5/776	Fan Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4818	ACTIVE	J	D101-00-5/777	Fan Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4819	ACTIVE	J	D101-00-5/785	Fan Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4820	ACTIVE	J	D101-00-5/786	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4821	ACTIVE	J	D101-00-5/787	Fan Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4822	ACTIVE	J	D101-00-5/788	Fan Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4823	ACTIVE	J	D101-00-5/901	CER - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4824	ACTIVE	J	D101-00-5/902	Disused Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4825	ACTIVE	J	D101-00-5/903	Void - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4826	ACTIVE	J	D101-00-6/081	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4827	ACTIVE	J	D101-00-6/082	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4828	ACTIVE	J	D101-00-6/083	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D101-00 - Station Building - Westminster Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4829	ACTIVE	J	D101-00-6/084	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4830	ACTIVE	J	D101-00-6/154	UMC - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4831	ACTIVE	J	D101-00-6/155	UMC - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4832	ACTIVE	J	D101-00-6/161	LMC - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4833	ACTIVE	J	D101-00-6/162	LMC - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4834	ACTIVE	J	D101-00-6/163	UMC - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4835	ACTIVE	J	D101-00-6/164	LMC - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4836	ACTIVE	J	D101-00-6/165	LMC - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4837	ACTIVE	J	D101-00-6/236	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4838	ACTIVE	J	D101-00-6/237	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4839	ACTIVE	J	D101-00-6/238	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4840	ACTIVE	J	D101-00-6/239	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4841	ACTIVE	J	D101-00-6/632	Stairs: Spiral - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4842	ACTIVE	J	D101-00-6/661	Switch Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4843	ACTIVE	J	D101-00-6/771	Lift Pump Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D101-00 - Station Building - Westminster Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4844	ACTIVE	J	D101-00-6/776	Fan Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4845	ACTIVE	J	D101-00-6/777	Fan Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4846	ACTIVE	J	D101-00-6/778	Plant Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4847	ACTIVE	J	D101-00-6/779	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4848	ACTIVE	J	D101-00-6/780	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4849	ACTIVE	J	D101-00-6/781	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4850	ACTIVE	J	D101-00-6/782	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4851	ACTIVE	J	D101-00-6/787	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4852	ACTIVE	J	D101-00-6/788	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4853	ACTIVE	J	D101-00-6/789	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4854	ACTIVE	J	D101-00-6/790	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4855	ACTIVE	J	D101-00-6/791	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4856	ACTIVE	J	D101-00-6/901	Disused Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4857	ACTIVE	J	D101-00-6/902	Disused Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4858	ACTIVE	J	D101-00-7/071	Circulation Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D101-00 - Station Building - Westminster Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4859	ACTIVE	J	D101-00-7/072	Circulation Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4860	ACTIVE	J	D101-00-7/081	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4861	ACTIVE	J	D101-00-7/082	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4862	ACTIVE	J	D101-00-7/083	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4863	ACTIVE	J	D101-00-7/084	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4864	ACTIVE	J	D101-00-7/085	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4865	ACTIVE	J	D101-00-7/086	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4866	ACTIVE	J	D101-00-7/201	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4867	ACTIVE	J	D101-00-7/202	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4868	ACTIVE	J	D101-00-7/203	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4869	ACTIVE	J	D101-00-7/204	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4870	ACTIVE	J	D101-00-7/205	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4871	ACTIVE	J	D101-00-7/206	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4872	ACTIVE	J	D101-00-7/207	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4873	ACTIVE	J	D101-00-7/208	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D101-00 - Station Building - Westminster Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4874	ACTIVE	J	D101-00-7/209	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4875	ACTIVE	J	D101-00-7/210	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4876	ACTIVE	J	D101-00-7/263	Platform 3 - Eastbound Local - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4877	ACTIVE	J	D101-00-7/481	Computer Equipment Cupboard - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4878	ACTIVE	J	D101-00-7/576	Stairs: Linear - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4879	ACTIVE	J	D101-00-7/661	Switch Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4880	ACTIVE	J	D101-00-7/662	Substation Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4881	ACTIVE	J	D101-00-7/663	Switch Cupboard - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4882	ACTIVE	J	D101-00-7/664	Switch Cupboard - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4883	ACTIVE	J	D101-00-7/665	Switch Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4884	ACTIVE	J	D101-00-7/666	CER - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4885	ACTIVE	J	D101-00-7/667	Switch Cupboard - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4886	ACTIVE	J	D101-00-7/668	Switch Cupboard - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4887	ACTIVE	J	D101-00-7/731	CER - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4888	ACTIVE	J	D101-00-7/776	Fan Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D101-00 - Station Building - Westminster Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4889	ACTIVE	J	D101-00-7/786	Service Riser - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4890	ACTIVE	J	D101-00-7/787	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4891	ACTIVE	J	D101-00-7/788	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4892	ACTIVE	J	D101-00-7/789	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4893	ACTIVE	J	D101-00-7/901	Disused Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4894	ACTIVE	J	D101-00-7/902	Void - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4895	ACTIVE	J	D101-00-7/903	Void - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4896	ACTIVE	J	D101-00-7/904	Void - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4897	ACTIVE	J	D101-00-7/905	Void - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4898	ACTIVE	J	D101-00-8/081	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4899	ACTIVE	J	D101-00-8/082	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4900	ACTIVE	J	D101-00-8/083	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4901	ACTIVE	J	D101-00-8/084	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4902	ACTIVE	J	D101-00-8/156	UMC - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4903	ACTIVE	J	D101-00-8/157	UMC - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D101-00 - Station Building - Westminster Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4904	ACTIVE	J	D101-00-8/164	LMC - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4905	ACTIVE	J	D101-00-8/165	LMC - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4906	ACTIVE	J	D101-00-8/236	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4907	ACTIVE	J	D101-00-8/237	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4908	ACTIVE	J	D101-00-8/238	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4909	ACTIVE	J	D101-00-8/261	Platform Invert - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4910	ACTIVE	J	D101-00-8/331	Mess Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4911	ACTIVE	J	D101-00-8/406	Store - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4912	ACTIVE	J	D101-00-8/661	Switch Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4913	ACTIVE	J	D101-00-8/662	Battery Invert - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4914	ACTIVE	J	D101-00-8/663	Switch Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4915	ACTIVE	J	D101-00-8/664	Substation Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4916	ACTIVE	J	D101-00-8/665	Switch Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4917	ACTIVE	J	D101-00-8/666	Switch Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4918	ACTIVE	J	D101-00-8/731	CER - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D101-00 - Station Building - Westminster Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4919	ACTIVE	J	D101-00-8/732	CER - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4920	ACTIVE	J	D101-00-8/733	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4921	ACTIVE	J	D101-00-8/776	Fan Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4922	ACTIVE	J	D101-00-8/777	Fan Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4923	ACTIVE	J	D101-00-8/781	Service Riser - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4924	ACTIVE	J	D101-00-8/786	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4925	ACTIVE	J	D101-00-8/787	Service Riser - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4926	ACTIVE	J	D101-00-8/901	Disused Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4927	ACTIVE	J	D101-00-8/903	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4928	ACTIVE	J	D101-00-9/071	Circulation Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4929	ACTIVE	J	D101-00-9/072	Circulation Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4930	ACTIVE	J	D101-00-9/081	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4931	ACTIVE	J	D101-00-9/082	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4932	ACTIVE	J	D101-00-9/083	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4933	ACTIVE	J	D101-00-9/084	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D101-00 - Station Building - Westminster Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4934	ACTIVE	J	D101-00-9/085	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4935	ACTIVE	J	D101-00-9/086	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4936	ACTIVE	J	D101-00-9/087	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4937	ACTIVE	J	D101-00-9/088	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4938	ACTIVE	J	D101-00-9/201	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4939	ACTIVE	J	D101-00-9/202	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4940	ACTIVE	J	D101-00-9/203	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4941	ACTIVE	J	D101-00-9/204	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4942	ACTIVE	J	D101-00-9/205	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4943	ACTIVE	J	D101-00-9/206	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4944	ACTIVE	J	D101-00-9/207	Lobby - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4945	ACTIVE	J	D101-00-9/209	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4946	ACTIVE	J	D101-00-9/210	Passage - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4947	ACTIVE	J	D101-00-9/264	Platform 4 - Westbound Local - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4948	ACTIVE	J	D101-00-9/481	Computer Equipment Cupboard - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D101-00 - Station Building - Westminster Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4949	ACTIVE	J	D101-00-9/601	Stairs: Linear - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4950	ACTIVE	J	D101-00-9/602	Stairs: Linear - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4951	ACTIVE	J	D101-00-9/631	Stairs: Spiral - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4952	ACTIVE	J	D101-00-9/632	Stairs: Spiral - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4953	ACTIVE	J	D101-00-9/661	Switch Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4954	ACTIVE	J	D101-00-9/662	Substation Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4955	ACTIVE	J	D101-00-9/663	Switch Cupboard - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4956	ACTIVE	J	D101-00-9/664	Switch Cupboard - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4957	ACTIVE	J	D101-00-9/665	Substation Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4958	ACTIVE	J	D101-00-9/666	Switch Cupboard - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4959	ACTIVE	J	D101-00-9/712	Relay Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4960	ACTIVE	J	D101-00-9/713	Relay Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4961	ACTIVE	J	D101-00-9/771	Lift Pump Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4962	ACTIVE	J	D101-00-9/776	Fan Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4963	ACTIVE	J	D101-00-9/783	Service Area - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



D101-00 - Station Building - Westminster Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4964	ACTIVE	J	D101-00-9/786	Service Riser - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4965	ACTIVE	J	D101-00-9/787	Service Riser - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4966	ACTIVE	J	D101-00-9/788	Service Riser - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4967	ACTIVE	J	D101-00-9/901	Void - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4968	ACTIVE	J	D101-00-9/902	Disused Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4969	ACTIVE	J	D101-00-9/903	Disused Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4970	ACTIVE	J	D101-00-9/904	Disused Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4971	ACTIVE	J	D101-00-9/906	Disused Room - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4972	ACTIVE	J	D101-00-9/907	Void - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4973	ACTIVE	J	D101-00-A/786	Roof - Station Building - Westminster Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

J003-00 - Station Building - Canning Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6165	ACTIVE	J	J003-00-1/011	Disused Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6166	ACTIVE	J	J003-00-1/041	Tenancy - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6167	ACTIVE	J	J003-00-1/081	Lobby - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J003-00 - Station Building - Canning Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6168	ACTIVE	J	J003-00-1/082	Lobby - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6169	ACTIVE	J	J003-00-1/083	Lobby - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6170	ACTIVE	J	J003-00-1/111	Disused Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6171	ACTIVE	J	J003-00-1/113	Disused Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6172	ACTIVE	J	J003-00-1/121	Platform Invert - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6173	ACTIVE	J	J003-00-1/122	Platform Invert - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6174	ACTIVE	J	J003-00-1/123	Platform Invert - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6175	ACTIVE	J	J003-00-1/124	Platform Invert - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6176	ACTIVE	J	J003-00-1/125	Platform Invert - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6177	ACTIVE	J	J003-00-1/126	Platform Invert - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6178	ACTIVE	J	J003-00-1/127	Platform Invert - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6179	ACTIVE	J	J003-00-1/236	Passage - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6180	ACTIVE	J	J003-00-1/237	Passage - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6181	ACTIVE	J	J003-00-1/238	Passage - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6182	ACTIVE	J	J003-00-1/261	Platform 6 - Eastbound Local - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J003-00 - Station Building - Canning Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6183	ACTIVE	J	J003-00-1/262	Platform 5 - Westbound Local - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6184	ACTIVE	J	J003-00-1/263	Platform 1 - DLR - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6185	ACTIVE	J	J003-00-1/264	Platform 2 - DLR - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6186	ACTIVE	J	J003-00-1/371	Store - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6187	ACTIVE	J	J003-00-1/401	Store - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6188	ACTIVE	J	J003-00-1/408	Store - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6189	ACTIVE	J	J003-00-1/409	Store - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6190	ACTIVE	J	J003-00-1/413	Store - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6191	ACTIVE	J	J003-00-1/414	Store - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6192	ACTIVE	J	J003-00-1/436	Waiting Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6193	ACTIVE	J	J003-00-1/451	Store - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6194	ACTIVE	J	J003-00-1/452	Tenancy - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6195	ACTIVE	J	J003-00-1/453	Tenancy - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6196	ACTIVE	J	J003-00-1/454	Tenancy - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6197	ACTIVE	J	J003-00-1/577	Stairs: Linear - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J003-00 - Station Building - Canning Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6198	ACTIVE	J	J003-00-1/578	Stairs: Linear - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6199	ACTIVE	J	J003-00-1/601	Stairs: Linear - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6200	ACTIVE	J	J003-00-1/602	Stairs: Linear - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6201	ACTIVE	J	J003-00-1/603	Stairs: Linear - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6202	ACTIVE	J	J003-00-1/604	Stairs: Linear - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6203	ACTIVE	J	J003-00-1/605	Stairs: Linear - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6204	ACTIVE	J	J003-00-1/631	Stairs: Spiral - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6205	ACTIVE	J	J003-00-1/632	Stairs: Spiral - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6206	ACTIVE	J	J003-00-1/633	Stairs: Spiral - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6207	ACTIVE	J	J003-00-1/661	Switch Cupboard - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6208	ACTIVE	J	J003-00-1/662	Switch Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6209	ACTIVE	J	J003-00-1/713	Store - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6210	ACTIVE	J	J003-00-1/731	Computer Equipment Cupboard - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6211	ACTIVE	J	J003-00-1/751	Computer Equipment Cupboard - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6212	ACTIVE	J	J003-00-1/761	SVC - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J003-00 - Station Building - Canning Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6213	ACTIVE	J	J003-00-1/781	Service Riser - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6214	ACTIVE	J	J003-00-1/782	Switch Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6215	ACTIVE	J	J003-00-1/786	Service Riser - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6216	ACTIVE	J	J003-00-1/787	Service Riser - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6217	ACTIVE	J	J003-00-1/788	Service Riser - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6218	ACTIVE	J	J003-00-1/901	Plant Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6219	ACTIVE	J	J003-00-2/001	Booking Hall - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6220	ACTIVE	J	J003-00-2/011	Ticket Office - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6221	ACTIVE	J	J003-00-2/021	POM - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6222	ACTIVE	J	J003-00-2/022	POM - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6223	ACTIVE	J	J003-00-2/031	Mess Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6224	ACTIVE	J	J003-00-2/032	Kitchen - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6225	ACTIVE	J	J003-00-2/036	Toilet: Unisex - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6226	ACTIVE	J	J003-00-2/071	Circulation Area - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6227	ACTIVE	J	J003-00-2/072	Lobby - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J003-00 - Station Building - Canning Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6228	ACTIVE	J	J003-00-2/073	Circulation Area - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6229	ACTIVE	J	J003-00-2/074	Circulation Area - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6230	ACTIVE	J	J003-00-2/076	Circulation Area - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6231	ACTIVE	J	J003-00-2/081	Lobby - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6232	ACTIVE	J	J003-00-2/083	Lobby - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6233	ACTIVE	J	J003-00-2/084	Lobby - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6234	ACTIVE	J	J003-00-2/085	Lobby - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6235	ACTIVE	J	J003-00-2/086	Lobby - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6236	ACTIVE	J	J003-00-2/138	Lift Shaft - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6237	ACTIVE	J	J003-00-2/151	UMC - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6238	ACTIVE	J	J003-00-2/152	UMC - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6239	ACTIVE	J	J003-00-2/153	UMC - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6240	ACTIVE	J	J003-00-2/201	Passage - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6241	ACTIVE	J	J003-00-2/202	Passage - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6242	ACTIVE	J	J003-00-2/203	Passage - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J003-00 - Station Building - Canning Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6243	ACTIVE	J	J003-00-2/236	Passage - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6244	ACTIVE	J	J003-00-2/237	Passage - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6245	ACTIVE	J	J003-00-2/238	Passage - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6246	ACTIVE	J	J003-00-2/239	Passage - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6247	ACTIVE	J	J003-00-2/240	Passage - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6248	ACTIVE	J	J003-00-2/241	Passage - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6249	ACTIVE	J	J003-00-2/242	Passage - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6250	ACTIVE	J	J003-00-2/243	Passage - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6251	ACTIVE	J	J003-00-2/244	Passage - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6252	ACTIVE	J	J003-00-2/246	Passage - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6253	ACTIVE	J	J003-00-2/247	Passage - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6254	ACTIVE	J	J003-00-2/248	Passage - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6255	ACTIVE	J	J003-00-2/249	Passage - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6256	ACTIVE	J	J003-00-2/295	Passage - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6257	ACTIVE	J	J003-00-2/311	Station Supervisor Office - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J003-00 - Station Building - Canning Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6258	ACTIVE	J	J003-00-2/316	Locker Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6259	ACTIVE	J	J003-00-2/317	Locker Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6260	ACTIVE	J	J003-00-2/331	Mess Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6261	ACTIVE	J	J003-00-2/332	Kitchen - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6262	ACTIVE	J	J003-00-2/406	Store - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6263	ACTIVE	J	J003-00-2/411	Store - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6264	ACTIVE	J	J003-00-2/412	Store - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6265	ACTIVE	J	J003-00-2/413	Store - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6266	ACTIVE	J	J003-00-2/414	Store - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6267	ACTIVE	J	J003-00-2/416	Toilet: Male - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6268	ACTIVE	J	J003-00-2/417	Toilet: Female - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6269	ACTIVE	J	J003-00-2/418	Toilet: Unisex - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6270	ACTIVE	J	J003-00-2/451	Tenancy - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6271	ACTIVE	J	J003-00-2/452	Tenancy - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6272	ACTIVE	J	J003-00-2/453	Store - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J003-00 - Station Building - Canning Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6273	ACTIVE	J	J003-00-2/501	BTP Office - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6274	ACTIVE	J	J003-00-2/576	Stairs: Linear - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6275	ACTIVE	J	J003-00-2/577	Stairs: Linear - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6276	ACTIVE	J	J003-00-2/578	Stairs: Linear - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6277	ACTIVE	J	J003-00-2/579	Stairs: Linear - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6278	ACTIVE	J	J003-00-2/580	Stairs: Linear - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6279	ACTIVE	J	J003-00-2/601	Stairs: Linear - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6280	ACTIVE	J	J003-00-2/602	Stairs: Spiral - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6281	ACTIVE	J	J003-00-2/603	Stairs: Linear - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6282	ACTIVE	J	J003-00-2/661	Switch Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6283	ACTIVE	J	J003-00-2/662	Switch Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6284	ACTIVE	J	J003-00-2/663	Switch Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6285	ACTIVE	J	J003-00-2/664	Switch Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6286	ACTIVE	J	J003-00-2/665	Switch Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6287	ACTIVE	J	J003-00-2/666	Store - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J003-00 - Station Building - Canning Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6288	ACTIVE	J	J003-00-2/667	Switch Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6289	ACTIVE	J	J003-00-2/668	Switch Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6290	ACTIVE	J	J003-00-2/669	Switch Cupboard - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6291	ACTIVE	J	J003-00-2/711	SER - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6292	ACTIVE	J	J003-00-2/731	CER - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6293	ACTIVE	J	J003-00-2/732	CER - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6294	ACTIVE	J	J003-00-2/746	SCR - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6295	ACTIVE	J	J003-00-2/756	Station Control Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6296	ACTIVE	J	J003-00-2/761	Equipment Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6297	ACTIVE	J	J003-00-2/762	Equipment Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6298	ACTIVE	J	J003-00-2/771	LEER - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6299	ACTIVE	J	J003-00-2/772	Pump Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6300	ACTIVE	J	J003-00-2/773	LMR - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6301	ACTIVE	J	J003-00-2/776	Plant Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6302	ACTIVE	J	J003-00-2/777	Fan Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J003-00 - Station Building - Canning Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6303	ACTIVE	J	J003-00-2/778	Fan Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6304	ACTIVE	J	J003-00-2/779	Plant Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6305	ACTIVE	J	J003-00-2/781	Substation Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6306	ACTIVE	J	J003-00-2/782	Substation Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6307	ACTIVE	J	J003-00-2/786	Service Riser - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6308	ACTIVE	J	J003-00-2/787	Service Riser - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6309	ACTIVE	J	J003-00-2/788	Service Riser - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6310	ACTIVE	J	J003-00-2/789	Service Riser - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6311	ACTIVE	J	J003-00-2/792	Service Riser - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6312	ACTIVE	J	J003-00-2/801	Office - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6313	ACTIVE	J	J003-00-2/901	Switch Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6314	ACTIVE	J	J003-00-2/902	Switch Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6315	ACTIVE	J	J003-00-2/903	SER - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6316	ACTIVE	J	J003-00-2/904	Void - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6317	ACTIVE	J	J003-00-2/971	Disused Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J003-00 - Station Building - Canning Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6318	ACTIVE	J	J003-00-3/081	Lobby - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6319	ACTIVE	J	J003-00-3/161	LMC - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6320	ACTIVE	J	J003-00-3/162	LMC - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6321	ACTIVE	J	J003-00-3/163	LMC - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6322	ACTIVE	J	J003-00-3/236	Passage - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6323	ACTIVE	J	J003-00-3/237	Passage - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6324	ACTIVE	J	J003-00-3/771	Pump Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6325	ACTIVE	J	J003-00-3/772	Pump Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6326	ACTIVE	J	J003-00-3/786	Service Riser - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6327	ACTIVE	J	J003-00-A/081	Switch Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6328	ACTIVE	J	J003-00-A/082	Lobby - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6329	ACTIVE	J	J003-00-A/151	UMC - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6330	ACTIVE	J	J003-00-A/152	UMC - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6331	ACTIVE	J	J003-00-A/153	UMC - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6332	ACTIVE	J	J003-00-A/154	UMC - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J003-00 - Station Building - Canning Town Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6333	ACTIVE	J	J003-00-A/265	Platform 4 - DLR - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6334	ACTIVE	J	J003-00-A/266	Platform 3 - DLR - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6335	ACTIVE	J	J003-00-A/331	Mess Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6336	ACTIVE	J	J003-00-A/411	Store - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6337	ACTIVE	J	J003-00-A/412	Store - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6338	ACTIVE	J	J003-00-A/416	Toilet: Unisex - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6339	ACTIVE	J	J003-00-A/481	Disused Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6340	ACTIVE	J	J003-00-A/482	Disused Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6341	ACTIVE	J	J003-00-A/661	Switch Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6342	ACTIVE	J	J003-00-A/711	SER - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6343	ACTIVE	J	J003-00-A/731	SER - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6344	ACTIVE	J	J003-00-A/901	Disused Room - Station Building - Canning Town Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6345	ACTIVE	J	J005-00-1/071	Circulation Area - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6346	ACTIVE	J	J005-00-1/081	Store - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6347	ACTIVE	J	J005-00-1/082	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6348	ACTIVE	J	J005-00-1/083	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6349	ACTIVE	J	J005-00-1/084	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6350	ACTIVE	J	J005-00-1/085	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6351	ACTIVE	J	J005-00-1/201	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6352	ACTIVE	J	J005-00-1/202	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6353	ACTIVE	J	J005-00-1/311	Mess Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6354	ACTIVE	J	J005-00-1/331	Mess Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6355	ACTIVE	J	J005-00-1/406	Store - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6356	ACTIVE	J	J005-00-1/411	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6357	ACTIVE	J	J005-00-1/412	Disused Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6358	ACTIVE	J	J005-00-1/413	Store - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6359	ACTIVE	J	J005-00-1/414	Store - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6360	ACTIVE	J	J005-00-1/415	Toilet: Unisex - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6361	ACTIVE	J	J005-00-1/426	Toilet: Female - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6362	ACTIVE	J	J005-00-1/427	Toilet: Male - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6363	ACTIVE	J	J005-00-1/428	Toilet: Disabled - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6364	ACTIVE	J	J005-00-1/429	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6365	ACTIVE	J	J005-00-1/451	Tenancy - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6366	ACTIVE	J	J005-00-1/452	Tenancy - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6367	ACTIVE	J	J005-00-1/453	Tenancy - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6368	ACTIVE	J	J005-00-1/454	ATM - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6369	ACTIVE	J	J005-00-1/481	Service Riser - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6370	ACTIVE	J	J005-00-1/482	SVC - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6371	ACTIVE	J	J005-00-1/555	Yard - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6372	ACTIVE	J	J005-00-1/661	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6373	ACTIVE	J	J005-00-1/662	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6374	ACTIVE	J	J005-00-1/663	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6375	ACTIVE	J	J005-00-1/756	Station Control Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6376	ACTIVE	J	J005-00-1/786	Service Riser - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6377	ACTIVE	J	J005-00-1/787	Disused Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6378	ACTIVE	J	J005-00-1/788	Service Riser - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6379	ACTIVE	J	J005-00-1/789	Service Riser - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6380	ACTIVE	J	J005-00-1/790	Service Riser - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6381	ACTIVE	J	J005-00-1/801	Office - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6382	ACTIVE	J	J005-00-1/901	Service Riser - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6383	ACTIVE	J	J005-00-2/072	Disused Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6384	ACTIVE	J	J005-00-2/151	UMC - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6385	ACTIVE	J	J005-00-2/236	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6386	ACTIVE	J	J005-00-2/237	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6387	ACTIVE	J	J005-00-2/238	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6388	ACTIVE	J	J005-00-2/239	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6389	ACTIVE	J	J005-00-2/396	SVC - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6390	ACTIVE	J	J005-00-2/951	Disused Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6391	ACTIVE	J	J005-00-3/081	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6392	ACTIVE	J	J005-00-3/082	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6393	ACTIVE	J	J005-00-3/083	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6394	ACTIVE	J	J005-00-3/084	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6395	ACTIVE	J	J005-00-3/151	UMC - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6396	ACTIVE	J	J005-00-3/661	Switch Cupboard - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6397	ACTIVE	J	J005-00-3/662	Switch Cupboard - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6398	ACTIVE	J	J005-00-3/663	Switch Cupboard - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6399	ACTIVE	J	J005-00-3/664	Switch Cupboard - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6400	ACTIVE	J	J005-00-3/665	Switch Cupboard - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6401	ACTIVE	J	J005-00-3/666	Equipment Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6402	ACTIVE	J	J005-00-3/776	Service Area - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6403	ACTIVE	J	J005-00-3/777	Service Area - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6404	ACTIVE	J	J005-00-3/778	Service Area - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6405	ACTIVE	J	J005-00-3/779	Plant Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6406	ACTIVE	J	J005-00-3/780	Plant Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6407	ACTIVE	J	J005-00-3/903	Disused Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6408	ACTIVE	J	J005-00-3/904	Disused Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6409	ACTIVE	J	J005-00-3/905	Disused Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6410	ACTIVE	J	J005-00-4/001	Booking Hall - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6411	ACTIVE	J	J005-00-4/002	Locker Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6412	ACTIVE	J	J005-00-4/011	Ticket Office - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6413	ACTIVE	J	J005-00-4/021	POM - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6414	ACTIVE	J	J005-00-4/036	Toilet: Male - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6415	ACTIVE	J	J005-00-4/037	Toilet: Female - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6416	ACTIVE	J	J005-00-4/071	Circulation Area - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6417	ACTIVE	J	J005-00-4/072	Circulation Area - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6418	ACTIVE	J	J005-00-4/073	Circulation Area - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6419	ACTIVE	J	J005-00-4/074	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6420	ACTIVE	J	J005-00-4/075	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6421	ACTIVE	J	J005-00-4/076	Circulation Area - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6422	ACTIVE	J	J005-00-4/077	Circulation Area - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6423	ACTIVE	J	J005-00-4/078	Circulation Area - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6424	ACTIVE	J	J005-00-4/079	Circulation Area - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6425	ACTIVE	J	J005-00-4/082	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6426	ACTIVE	J	J005-00-4/083	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6427	ACTIVE	J	J005-00-4/084	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6428	ACTIVE	J	J005-00-4/085	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6429	ACTIVE	J	J005-00-4/086	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6430	ACTIVE	J	J005-00-4/087	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6431	ACTIVE	J	J005-00-4/089	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6432	ACTIVE	J	J005-00-4/090	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6433	ACTIVE	J	J005-00-4/091	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6434	ACTIVE	J	J005-00-4/092	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6435	ACTIVE	J	J005-00-4/093	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6436	ACTIVE	J	J005-00-4/094	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6437	ACTIVE	J	J005-00-4/095	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6438	ACTIVE	J	J005-00-4/096	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6439	ACTIVE	J	J005-00-4/097	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6440	ACTIVE	J	J005-00-4/236	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6441	ACTIVE	J	J005-00-4/237	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6442	ACTIVE	J	J005-00-4/238	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6443	ACTIVE	J	J005-00-4/239	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6444	ACTIVE	J	J005-00-4/241	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6445	ACTIVE	J	J005-00-4/242	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6446	ACTIVE	J	J005-00-4/243	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6447	ACTIVE	J	J005-00-4/244	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6448	ACTIVE	J	J005-00-4/245	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6449	ACTIVE	J	J005-00-4/246	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6450	ACTIVE	J	J005-00-4/247	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6451	ACTIVE	J	J005-00-4/311	Office - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6452	ACTIVE	J	J005-00-4/316	Locker Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6453	ACTIVE	J	J005-00-4/331	Kitchen - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6454	ACTIVE	J	J005-00-4/332	Mess Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6455	ACTIVE	J	J005-00-4/333	Tea Point - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6456	ACTIVE	J	J005-00-4/371	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6457	ACTIVE	J	J005-00-4/372	Kitchen - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6458	ACTIVE	J	J005-00-4/406	Store - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6459	ACTIVE	J	J005-00-4/411	Store - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6460	ACTIVE	J	J005-00-4/412	Store - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6461	ACTIVE	J	J005-00-4/413	Store - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6462	ACTIVE	J	J005-00-4/414	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6463	ACTIVE	J	J005-00-4/415	Store - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6464	ACTIVE	J	J005-00-4/416	Toilet: Female - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6465	ACTIVE	J	J005-00-4/417	Toilet: Male - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6466	ACTIVE	J	J005-00-4/418	Toilet: Female - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6467	ACTIVE	J	J005-00-4/419	Toilet: Male - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6468	ACTIVE	J	J005-00-4/420	Toilet: Female - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6469	ACTIVE	J	J005-00-4/451	ATM - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6470	ACTIVE	J	J005-00-4/452	Tenancy - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6471	ACTIVE	J	J005-00-4/481	Mess Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6472	ACTIVE	J	J005-00-4/501	Office - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6473	ACTIVE	J	J005-00-4/531	Mess Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6474	ACTIVE	J	J005-00-4/576	Stairs: Linear - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6475	ACTIVE	J	J005-00-4/577	Stairs: Linear - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6476	ACTIVE	J	J005-00-4/578	Stairs: Linear - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6477	ACTIVE	J	J005-00-4/579	Stairs: Linear - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6478	ACTIVE	J	J005-00-4/580	Stairs: Linear - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6479	ACTIVE	J	J005-00-4/581	Stairs: Linear - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6480	ACTIVE	J	J005-00-4/582	Stairs: Spiral - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6481	ACTIVE	J	J005-00-4/583	Stairs: Linear - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6482	ACTIVE	J	J005-00-4/631	Stairs: Linear - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6483	ACTIVE	J	J005-00-4/650	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6484	ACTIVE	J	J005-00-4/661	Switch Cupboard - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6485	ACTIVE	J	J005-00-4/662	Switch Cupboard - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6486	ACTIVE	J	J005-00-4/663	Equipment Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6487	ACTIVE	J	J005-00-4/664	TXR - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6488	ACTIVE	J	J005-00-4/665	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6489	ACTIVE	J	J005-00-4/666	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6490	ACTIVE	J	J005-00-4/667	TXR - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6491	ACTIVE	J	J005-00-4/668	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6492	ACTIVE	J	J005-00-4/670	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6493	ACTIVE	J	J005-00-4/671	Switch Cupboard - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6494	ACTIVE	J	J005-00-4/672	Switch Cupboard - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6495	ACTIVE	J	J005-00-4/731	CER - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6496	ACTIVE	J	J005-00-4/732	CER - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6497	ACTIVE	J	J005-00-4/741	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6498	ACTIVE	J	J005-00-4/742	TXR - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6499	ACTIVE	J	J005-00-4/743	TXR - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6500	ACTIVE	J	J005-00-4/744	TXR - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6501	ACTIVE	J	J005-00-4/746	SCR - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6502	ACTIVE	J	J005-00-4/751	Station Control Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6503	ACTIVE	J	J005-00-4/753	Station Control Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6504	ACTIVE	J	J005-00-4/761	Equipment Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6505	ACTIVE	J	J005-00-4/771	Lift Pump Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6506	ACTIVE	J	J005-00-4/776	Fan Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6507	ACTIVE	J	J005-00-4/777	Fan Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6508	ACTIVE	J	J005-00-4/778	Fan Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6509	ACTIVE	J	J005-00-4/779	Fan Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6510	ACTIVE	J	J005-00-4/780	Fan Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6511	ACTIVE	J	J005-00-4/781	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6512	ACTIVE	J	J005-00-4/782	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6513	ACTIVE	J	J005-00-4/783	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6514	ACTIVE	J	J005-00-4/784	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6515	ACTIVE	J	J005-00-4/801	Office - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6516	ACTIVE	J	J005-00-4/901	Disused Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6517	ACTIVE	J	J005-00-4/902	SER - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6518	ACTIVE	J	J005-00-4/903	Disused Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6519	ACTIVE	J	J005-00-5/047	Kitchen - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6520	ACTIVE	J	J005-00-5/053	Mess Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6521	ACTIVE	J	J005-00-5/081	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6522	ACTIVE	J	J005-00-5/082	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6523	ACTIVE	J	J005-00-5/083	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6524	ACTIVE	J	J005-00-5/085	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6525	ACTIVE	J	J005-00-5/086	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6526	ACTIVE	J	J005-00-5/087	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6527	ACTIVE	J	J005-00-5/088	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6528	ACTIVE	J	J005-00-5/089	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6529	ACTIVE	J	J005-00-5/090	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6530	ACTIVE	J	J005-00-5/091	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6531	ACTIVE	J	J005-00-5/092	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6532	ACTIVE	J	J005-00-5/093	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6533	ACTIVE	J	J005-00-5/151	UMC - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6534	ACTIVE	J	J005-00-5/152	UMC - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6535	ACTIVE	J	J005-00-5/153	UMC - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6536	ACTIVE	J	J005-00-5/154	UMC - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6537	ACTIVE	J	J005-00-5/155	UMC - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6538	ACTIVE	J	J005-00-5/156	UMC - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6539	ACTIVE	J	J005-00-5/161	LMC - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6540	ACTIVE	J	J005-00-5/236	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6541	ACTIVE	J	J005-00-5/237	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6542	ACTIVE	J	J005-00-5/238	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6543	ACTIVE	J	J005-00-5/239	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6544	ACTIVE	J	J005-00-5/240	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6545	ACTIVE	J	J005-00-5/242	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6546	ACTIVE	J	J005-00-5/243	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6547	ACTIVE	J	J005-00-5/244	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6548	ACTIVE	J	J005-00-5/245	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6549	ACTIVE	J	J005-00-5/246	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6550	ACTIVE	J	J005-00-5/247	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6551	ACTIVE	J	J005-00-5/248	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6552	ACTIVE	J	J005-00-5/249	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6553	ACTIVE	J	J005-00-5/251	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6554	ACTIVE	J	J005-00-5/252	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6555	ACTIVE	J	J005-00-5/253	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6556	ACTIVE	J	J005-00-5/254	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6557	ACTIVE	J	J005-00-5/291	Office - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6558	ACTIVE	J	J005-00-5/292	Office - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6559	ACTIVE	J	J005-00-5/316	Locker Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6560	ACTIVE	J	J005-00-5/351	Kitchen - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6561	ACTIVE	J	J005-00-5/371	Store - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6562	ACTIVE	J	J005-00-5/396	Plant Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6563	ACTIVE	J	J005-00-5/406	Store - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6564	ACTIVE	J	J005-00-5/416	Toilet: Female - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6565	ACTIVE	J	J005-00-5/417	Toilet: Male - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6566	ACTIVE	J	J005-00-5/481	Service Area - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6567	ACTIVE	J	J005-00-5/482	Service Area - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6568	ACTIVE	J	J005-00-5/483	Service Area - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6569	ACTIVE	J	J005-00-5/531	Booking On Point - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6570	ACTIVE	J	J005-00-5/532	Office - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6571	ACTIVE	J	J005-00-5/533	Office - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6572	ACTIVE	J	J005-00-5/576	Stairs: Linear - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6573	ACTIVE	J	J005-00-5/577	Stairs: Linear - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6574	ACTIVE	J	J005-00-5/578	Stairs: Linear - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6575	ACTIVE	J	J005-00-5/604	Stairs: Spiral - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6576	ACTIVE	J	J005-00-5/631	Stairs: Spiral - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6577	ACTIVE	J	J005-00-5/632	Stairs: Spiral - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6578	ACTIVE	J	J005-00-5/633	Stairs: Spiral - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6579	ACTIVE	J	J005-00-5/635	Stairs: Spiral - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6580	ACTIVE	J	J005-00-5/648	Stairs: Linear - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6581	ACTIVE	J	J005-00-5/661	Switch Cupboard - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6582	ACTIVE	J	J005-00-5/662	Switch Cupboard - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6583	ACTIVE	J	J005-00-5/663	Switch Cupboard - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6584	ACTIVE	J	J005-00-5/664	Store - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6585	ACTIVE	J	J005-00-5/665	Switch Cupboard - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6586	ACTIVE	J	J005-00-5/666	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6587	ACTIVE	J	J005-00-5/667	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6588	ACTIVE	J	J005-00-5/668	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6589	ACTIVE	J	J005-00-5/669	Switch Cupboard - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6590	ACTIVE	J	J005-00-5/731	CER - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6591	ACTIVE	J	J005-00-5/776	Fan Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6592	ACTIVE	J	J005-00-5/777	Fan Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6593	ACTIVE	J	J005-00-5/778	Fan Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6594	ACTIVE	J	J005-00-5/779	Equipment Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6595	ACTIVE	J	J005-00-5/781	Substation Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6596	ACTIVE	J	J005-00-5/782	Substation Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6597	ACTIVE	J	J005-00-5/787	Air Plenum - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6598	ACTIVE	J	J005-00-5/788	Air Plenum - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6599	ACTIVE	J	J005-00-5/789	Void - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6600	ACTIVE	J	J005-00-5/790	Service Area - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6601	ACTIVE	J	J005-00-5/791	Service Riser - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6602	ACTIVE	J	J005-00-5/792	Service Riser - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6603	ACTIVE	J	J005-00-5/793	Service Riser - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6604	ACTIVE	J	J005-00-5/901	Disused Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6605	ACTIVE	J	J005-00-5/902	Disused Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6606	ACTIVE	J	J005-00-5/903	Disused Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6607	ACTIVE	J	J005-00-5/904	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6608	ACTIVE	J	J005-00-5/906	Disused Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6609	ACTIVE	J	J005-00-5/907	Fan Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6610	ACTIVE	J	J005-00-6/047	Tea Point - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6611	ACTIVE	J	J005-00-6/081	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6612	ACTIVE	J	J005-00-6/082	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6613	ACTIVE	J	J005-00-6/083	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6614	ACTIVE	J	J005-00-6/084	Toilet: Unisex - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6615	ACTIVE	J	J005-00-6/085	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6616	ACTIVE	J	J005-00-6/086	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6617	ACTIVE	J	J005-00-6/087	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6618	ACTIVE	J	J005-00-6/088	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6619	ACTIVE	J	J005-00-6/089	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6620	ACTIVE	J	J005-00-6/090	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6621	ACTIVE	J	J005-00-6/091	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6622	ACTIVE	J	J005-00-6/092	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6623	ACTIVE	J	J005-00-6/093	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6624	ACTIVE	J	J005-00-6/094	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6625	ACTIVE	J	J005-00-6/095	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6626	ACTIVE	J	J005-00-6/201	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6627	ACTIVE	J	J005-00-6/237	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6628	ACTIVE	J	J005-00-6/238	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6629	ACTIVE	J	J005-00-6/239	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6630	ACTIVE	J	J005-00-6/240	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6631	ACTIVE	J	J005-00-6/241	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6632	ACTIVE	J	J005-00-6/242	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6633	ACTIVE	J	J005-00-6/261	Platform 1 - Westbound Local - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6634	ACTIVE	J	J005-00-6/262	Platform 2 - Single Line Local - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6635	ACTIVE	J	J005-00-6/263	Platform 3 - Eastbound Local - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6636	ACTIVE	J	J005-00-6/291	Store - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6637	ACTIVE	J	J005-00-6/292	Store - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6638	ACTIVE	J	J005-00-6/371	Office - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6639	ACTIVE	J	J005-00-6/372	Office - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6640	ACTIVE	J	J005-00-6/406	Cleaners Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6641	ACTIVE	J	J005-00-6/407	Store - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6642	ACTIVE	J	J005-00-6/408	Store - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6643	ACTIVE	J	J005-00-6/411	Disused Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6644	ACTIVE	J	J005-00-6/412	Store - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6645	ACTIVE	J	J005-00-6/413	Store - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6646	ACTIVE	J	J005-00-6/414	Store - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6647	ACTIVE	J	J005-00-6/416	Toilet: Unisex - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6648	ACTIVE	J	J005-00-6/481	Store - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6649	ACTIVE	J	J005-00-6/576	Stairs: Linear - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6650	ACTIVE	J	J005-00-6/577	Stairs: Linear - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6651	ACTIVE	J	J005-00-6/578	Stairs: Linear - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6652	ACTIVE	J	J005-00-6/579	Stairs: Linear - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6653	ACTIVE	J	J005-00-6/581	Stairs: Linear - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6654	ACTIVE	J	J005-00-6/582	Stairs: Linear - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6655	ACTIVE	J	J005-00-6/583	Stairs: Linear - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6656	ACTIVE	J	J005-00-6/584	Stairs: Linear - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6657	ACTIVE	J	J005-00-6/603	Stairs: Spiral - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6658	ACTIVE	J	J005-00-6/631	Stairs: Spiral - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6659	ACTIVE	J	J005-00-6/632	Stairs: Spiral - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6660	ACTIVE	J	J005-00-6/633	Stairs: Spiral - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6661	ACTIVE	J	J005-00-6/634	Stairs: Spiral - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6662	ACTIVE	J	J005-00-6/635	Stairs: Spiral - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6663	ACTIVE	J	J005-00-6/661	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6664	ACTIVE	J	J005-00-6/662	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6665	ACTIVE	J	J005-00-6/663	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6666	ACTIVE	J	J005-00-6/664	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6667	ACTIVE	J	J005-00-6/706	IMR - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6668	ACTIVE	J	J005-00-6/711	Disused Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6669	ACTIVE	J	J005-00-6/731	CER - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6670	ACTIVE	J	J005-00-6/732	Disused Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6671	ACTIVE	J	J005-00-6/761	Equipment Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6672	ACTIVE	J	J005-00-6/901	Store - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6673	ACTIVE	J	J005-00-6/903	Store - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6674	ACTIVE	J	J005-00-6/904	Service Riser - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6675	ACTIVE	J	J005-00-6/905	Disused Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6676	ACTIVE	J	J005-00-6/906	Disused Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6677	ACTIVE	J	J005-00-7/081	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6678	ACTIVE	J	J005-00-7/083	Lobby - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6679	ACTIVE	J	J005-00-7/131	Lift Pump Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6680	ACTIVE	J	J005-00-7/132	Lift Pump Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6681	ACTIVE	J	J005-00-7/161	LMC - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6682	ACTIVE	J	J005-00-7/162	LMC - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6683	ACTIVE	J	J005-00-7/163	LMC - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6684	ACTIVE	J	J005-00-7/164	LMC - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6685	ACTIVE	J	J005-00-7/165	LMC - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6686	ACTIVE	J	J005-00-7/166	LMC - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6687	ACTIVE	J	J005-00-7/236	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6688	ACTIVE	J	J005-00-7/237	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6689	ACTIVE	J	J005-00-7/238	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6690	ACTIVE	J	J005-00-7/239	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6691	ACTIVE	J	J005-00-7/240	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6692	ACTIVE	J	J005-00-7/241	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6693	ACTIVE	J	J005-00-7/242	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6694	ACTIVE	J	J005-00-7/243	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6695	ACTIVE	J	J005-00-7/244	Passage - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6696	ACTIVE	J	J005-00-7/416	Cleaners Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6697	ACTIVE	J	J005-00-7/481	Pump Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6698	ACTIVE	J	J005-00-7/482	Pump Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6699	ACTIVE	J	J005-00-7/661	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6700	ACTIVE	J	J005-00-7/662	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6701	ACTIVE	J	J005-00-7/663	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6702	ACTIVE	J	J005-00-7/664	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6703	ACTIVE	J	J005-00-7/665	Switch Cupboard - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6704	ACTIVE	J	J005-00-7/666	Switch Cupboard - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6705	ACTIVE	J	J005-00-7/667	Switch Cupboard - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6706	ACTIVE	J	J005-00-7/668	Switch Cupboard - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6707	ACTIVE	J	J005-00-7/771	Pump Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6708	ACTIVE	J	J005-00-7/772	Pump Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6709	ACTIVE	J	J005-00-7/773	Lift Pump Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6710	ACTIVE	J	J005-00-7/776	Fan Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6711	ACTIVE	J	J005-00-7/778	Fan Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6712	ACTIVE	J	J005-00-7/786	Service Riser - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6713	ACTIVE	J	J005-00-7/787	Service Riser - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6714	ACTIVE	J	J005-00-7/788	Service Riser - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6715	ACTIVE	J	J005-00-7/901	Service Duct - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6716	ACTIVE	J	J005-00-7/902	Service Duct - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6717	ACTIVE	J	J005-00-7/903	Service Duct - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6718	ACTIVE	J	J005-00-7/904	Service Duct- Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6719	ACTIVE	J	J005-00-7/905	Service Duct - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6720	ACTIVE	J	J005-00-7/906	Service Duct - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6721	ACTIVE	J	J005-00-7/907	Service Duct - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6722	ACTIVE	J	J005-00-7/908	Void - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6723	ACTIVE	J	J005-00-7/909	Void - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6724	ACTIVE	J	J005-00-7/910	Void - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6725	ACTIVE	J	J005-00-7/911	Void - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6726	ACTIVE	J	J005-00-7/912	Void - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6727	ACTIVE	J	J005-00-7/913	Void - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6728	ACTIVE	J	J005-00-7/951	Disused Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6729	ACTIVE	J	J005-00-7/952	Disused Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6730	ACTIVE	J	J005-00-A/645	Roof - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6731	ACTIVE	J	J005-00-A/646	Roof - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6732	ACTIVE	J	J005-00-A/777	Fan Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6733	ACTIVE	J	J005-00-A/778	Fan Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6734	ACTIVE	J	J005-00-A/779	Plant Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6735	ACTIVE	J	J005-00-A/780	Plant Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J005-00 - Station Building - North Greenwich Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6736	ACTIVE	J	J005-00-A/781	Switch Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6737	ACTIVE	J	J005-00-B/777	Roof - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6738	ACTIVE	J	J005-00-B/778	Disused Room - Station Building - North Greenwich Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6773	ACTIVE	J	J007-00-1/071	Circulation Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6774	ACTIVE	J	J007-00-1/081	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6775	ACTIVE	J	J007-00-1/082	Overbridge - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6776	ACTIVE	J	J007-00-1/083	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6777	ACTIVE	J	J007-00-1/084	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6778	ACTIVE	J	J007-00-1/085	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6779	ACTIVE	J	J007-00-1/151	UMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6780	ACTIVE	J	J007-00-1/152	UMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6781	ACTIVE	J	J007-00-1/153	UMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6782	ACTIVE	J	J007-00-1/186	Station Entrance - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6783	ACTIVE	J	J007-00-1/187	Station Entrance - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6784	ACTIVE	J	J007-00-1/188	Station Entrance - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6785	ACTIVE	J	J007-00-1/189	Station Entrance - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6786	ACTIVE	J	J007-00-1/190	Station Entrance - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6787	ACTIVE	J	J007-00-1/236	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6788	ACTIVE	J	J007-00-1/401	Bin Store - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6789	ACTIVE	J	J007-00-1/481	Equipment Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6790	ACTIVE	J	J007-00-1/601	Stairs: Linear - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6791	ACTIVE	J	J007-00-1/602	Stairs: Linear - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6792	ACTIVE	J	J007-00-1/661	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6793	ACTIVE	J	J007-00-1/662	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6794	ACTIVE	J	J007-00-1/663	Pump Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6795	ACTIVE	J	J007-00-1/751	Station Control Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2645	ACTIVE	J	J007-00-1/751	Station Control Room - Station Building - Canary Wharf Stn	Odour	Other Hazardous Materials	Known				Ammonia Odour - Below OEL					
6796	ACTIVE	J	J007-00-1/776	Fan Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6797	ACTIVE	J	J007-00-1/777	Fan Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6798	ACTIVE	J	J007-00-1/791	Pump Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6799	ACTIVE	J	J007-00-1/901	Void - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6800	ACTIVE	J	J007-00-1/TA1	Tenancy - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6801	ACTIVE	J	J007-00-2/071	Circulation Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6802	ACTIVE	J	J007-00-2/081	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6803	ACTIVE	J	J007-00-2/082	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6804	ACTIVE	J	J007-00-2/083	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6805	ACTIVE	J	J007-00-2/085	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6806	ACTIVE	J	J007-00-2/086	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6807	ACTIVE	J	J007-00-2/087	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6808	ACTIVE	J	J007-00-2/088	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6809	ACTIVE	J	J007-00-2/151	UMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6810	ACTIVE	J	J007-00-2/236	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6811	ACTIVE	J	J007-00-2/237	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6812	ACTIVE	J	J007-00-2/481	Disused Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6813	ACTIVE	J	J007-00-2/482	Disused Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6814	ACTIVE	J	J007-00-2/483	Fan Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6815	ACTIVE	J	J007-00-2/576	Stairs: Linear - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6816	ACTIVE	J	J007-00-2/577	Stairs: Linear - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6817	ACTIVE	J	J007-00-2/661	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6818	ACTIVE	J	J007-00-2/662	Switch Cupboard - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6819	ACTIVE	J	J007-00-2/663	Switch Cupboard - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6820	ACTIVE	J	J007-00-2/761	Fan Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6821	ACTIVE	J	J007-00-2/762	Fan Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6822	ACTIVE	J	J007-00-2/763	Fan Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6823	ACTIVE	J	J007-00-2/765	Fan Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6824	ACTIVE	J	J007-00-2/766	Fan Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6825	ACTIVE	J	J007-00-2/779	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6826	ACTIVE	J	J007-00-2/780	Fan Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6827	ACTIVE	J	J007-00-2/791	Air Plenum - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6828	ACTIVE	J	J007-00-2/792	Air Plenum - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6829	ACTIVE	J	J007-00-2/793	Air Plenum - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6830	ACTIVE	J	J007-00-2/794	Air Plenum - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6831	ACTIVE	J	J007-00-2/901	Disused Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2277	ACTIVE	J	J007-00-2/901	Disused Room - Station Building - Canary Wharf Stn	Odour	Other Hazardous Materials	Known				Ammonia Odour - Below OEL					
6832	ACTIVE	J	J007-00-3/081	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6833	ACTIVE	J	J007-00-3/082	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6834	ACTIVE	J	J007-00-3/083	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6835	ACTIVE	J	J007-00-3/085	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6836	ACTIVE	J	J007-00-3/086	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6837	ACTIVE	J	J007-00-3/087	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6838	ACTIVE	J	J007-00-3/151	UMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6839	ACTIVE	J	J007-00-3/152	UMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6840	ACTIVE	J	J007-00-3/161	LMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6841	ACTIVE	J	J007-00-3/162	UMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6842	ACTIVE	J	J007-00-3/163	UMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6843	ACTIVE	J	J007-00-3/236	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6844	ACTIVE	J	J007-00-3/481	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6845	ACTIVE	J	J007-00-3/482	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6846	ACTIVE	J	J007-00-3/483	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6847	ACTIVE	J	J007-00-3/484	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6848	ACTIVE	J	J007-00-3/485	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6849	ACTIVE	J	J007-00-3/486	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6850	ACTIVE	J	J007-00-3/487	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6851	ACTIVE	J	J007-00-3/488	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6852	ACTIVE	J	J007-00-3/489	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6853	ACTIVE	J	J007-00-3/490	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6854	ACTIVE	J	J007-00-3/491	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6855	ACTIVE	J	J007-00-3/494	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6856	ACTIVE	J	J007-00-3/495	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6857	ACTIVE	J	J007-00-3/496	Equipment Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6858	ACTIVE	J	J007-00-3/497	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6859	ACTIVE	J	J007-00-3/578	Stairs: Linear - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6860	ACTIVE	J	J007-00-3/661	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6861	ACTIVE	J	J007-00-3/662	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6862	ACTIVE	J	J007-00-3/663	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6863	ACTIVE	J	J007-00-3/664	Switch Cupboard - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6864	ACTIVE	J	J007-00-3/665	Switch Cupboard - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6865	ACTIVE	J	J007-00-3/761	Fan Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6866	ACTIVE	J	J007-00-3/762	Fan Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6867	ACTIVE	J	J007-00-3/779	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6868	ACTIVE	J	J007-00-3/780	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6869	ACTIVE	J	J007-00-3/786	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6870	ACTIVE	J	J007-00-3/791	Disused Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6871	ACTIVE	J	J007-00-3/942	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6872	ACTIVE	J	J007-00-3/943	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6873	ACTIVE	J	J007-00-3/951	Disused Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6874	ACTIVE	J	J007-00-4/002	Booking Hall - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6875	ACTIVE	J	J007-00-4/011	Tenancy - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6876	ACTIVE	J	J007-00-4/012	Store - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6877	ACTIVE	J	J007-00-4/021	Tenancy - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6878	ACTIVE	J	J007-00-4/022	Plant Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6879	ACTIVE	J	J007-00-4/031	Plant Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6880	ACTIVE	J	J007-00-4/032	Tenancy - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6881	ACTIVE	J	J007-00-4/036	Tenancy - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6882	ACTIVE	J	J007-00-4/037	Tenancy - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6883	ACTIVE	J	J007-00-4/038	Store - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6884	ACTIVE	J	J007-00-4/071	Circulation Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6885	ACTIVE	J	J007-00-4/072	Circulation Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6886	ACTIVE	J	J007-00-4/081	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6887	ACTIVE	J	J007-00-4/082	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6888	ACTIVE	J	J007-00-4/083	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6889	ACTIVE	J	J007-00-4/084	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6890	ACTIVE	J	J007-00-4/085	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6891	ACTIVE	J	J007-00-4/086	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6892	ACTIVE	J	J007-00-4/087	Tenancy - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6893	ACTIVE	J	J007-00-4/088	Tenancy - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6894	ACTIVE	J	J007-00-4/089	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6895	ACTIVE	J	J007-00-4/090	Plant Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6896	ACTIVE	J	J007-00-4/091	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6897	ACTIVE	J	J007-00-4/092	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6898	ACTIVE	J	J007-00-4/093	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6899	ACTIVE	J	J007-00-4/094	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6900	ACTIVE	J	J007-00-4/095	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6901	ACTIVE	J	J007-00-4/096	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6902	ACTIVE	J	J007-00-4/097	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6903	ACTIVE	J	J007-00-4/099	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6904	ACTIVE	J	J007-00-4/100	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6905	ACTIVE	J	J007-00-4/101	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6906	ACTIVE	J	J007-00-4/102	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6907	ACTIVE	J	J007-00-4/103	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6908	ACTIVE	J	J007-00-4/104	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6909	ACTIVE	J	J007-00-4/105	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6910	ACTIVE	J	J007-00-4/106	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6911	ACTIVE	J	J007-00-4/107	Tenancy - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6912	ACTIVE	J	J007-00-4/108	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6913	ACTIVE	J	J007-00-4/109	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6914	ACTIVE	J	J007-00-4/146	Toilet: Male - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6915	ACTIVE	J	J007-00-4/147	Toilet: Male - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6916	ACTIVE	J	J007-00-4/148	Toilet: Female - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6917	ACTIVE	J	J007-00-4/149	Toilet: Female - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6918	ACTIVE	J	J007-00-4/201	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6919	ACTIVE	J	J007-00-4/202	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6920	ACTIVE	J	J007-00-4/203	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6921	ACTIVE	J	J007-00-4/204	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6922	ACTIVE	J	J007-00-4/205	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6923	ACTIVE	J	J007-00-4/236	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6924	ACTIVE	J	J007-00-4/237	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6925	ACTIVE	J	J007-00-4/238	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6926	ACTIVE	J	J007-00-4/239	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6927	ACTIVE	J	J007-00-4/240	Tenancy - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6928	ACTIVE	J	J007-00-4/291	Office - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6929	ACTIVE	J	J007-00-4/301	Training Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6930	ACTIVE	J	J007-00-4/311	Tenancy - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6931	ACTIVE	J	J007-00-4/316	Locker Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6932	ACTIVE	J	J007-00-4/317	Baby Changing Unit - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6933	ACTIVE	J	J007-00-4/318	Disused Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6934	ACTIVE	J	J007-00-4/319	Tenancy - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6935	ACTIVE	J	J007-00-4/341	Mess Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6936	ACTIVE	J	J007-00-4/342	Kitchen - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6937	ACTIVE	J	J007-00-4/361	Mess Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6938	ACTIVE	J	J007-00-4/362	Tea Point - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6939	ACTIVE	J	J007-00-4/396	SVC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6940	ACTIVE	J	J007-00-4/401	Bin Store - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6941	ACTIVE	J	J007-00-4/406	Store - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6942	ACTIVE	J	J007-00-4/407	Store - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6943	ACTIVE	J	J007-00-4/408	Store - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6944	ACTIVE	J	J007-00-4/409	Store - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6945	ACTIVE	J	J007-00-4/411	Tenancy - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6946	ACTIVE	J	J007-00-4/412	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6947	ACTIVE	J	J007-00-4/413	Store - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6948	ACTIVE	J	J007-00-4/414	Store - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6949	ACTIVE	J	J007-00-4/415	Store - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6950	ACTIVE	J	J007-00-4/416	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6951	ACTIVE	J	J007-00-4/417	Shower Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6952	ACTIVE	J	J007-00-4/420	Toilet: Male - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6953	ACTIVE	J	J007-00-4/421	Toilet: Female - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6954	ACTIVE	J	J007-00-4/426	Toilet: Female - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6955	ACTIVE	J	J007-00-4/427	Toilet: Male - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6956	ACTIVE	J	J007-00-4/428	Baby Changing Unit - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6957	ACTIVE	J	J007-00-4/429	Toilet: Disabled - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6958	ACTIVE	J	J007-00-4/430	Shower Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6959	ACTIVE	J	J007-00-4/481	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6960	ACTIVE	J	J007-00-4/484	Tenancy - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6961	ACTIVE	J	J007-00-4/485	Tenancy - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6962	ACTIVE	J	J007-00-4/486	Tenancy - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6963	ACTIVE	J	J007-00-4/488	Tenancy - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6964	ACTIVE	J	J007-00-4/489	Disused Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6965	ACTIVE	J	J007-00-4/492	Void - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6966	ACTIVE	J	J007-00-4/501	Office - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6967	ACTIVE	J	J007-00-4/631	Stairs: Spiral - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6968	ACTIVE	J	J007-00-4/661	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6969	ACTIVE	J	J007-00-4/662	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6970	ACTIVE	J	J007-00-4/663	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6971	ACTIVE	J	J007-00-4/664	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6972	ACTIVE	J	J007-00-4/665	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6973	ACTIVE	J	J007-00-4/666	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6974	ACTIVE	J	J007-00-4/667	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6975	ACTIVE	J	J007-00-4/668	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6976	ACTIVE	J	J007-00-4/669	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6977	ACTIVE	J	J007-00-4/670	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6978	ACTIVE	J	J007-00-4/671	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6979	ACTIVE	J	J007-00-4/672	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6980	ACTIVE	J	J007-00-4/673	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6981	ACTIVE	J	J007-00-4/674	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6982	ACTIVE	J	J007-00-4/675	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6983	ACTIVE	J	J007-00-4/676	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6984	ACTIVE	J	J007-00-4/677	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6985	ACTIVE	J	J007-00-4/679	Switch Cupboard - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6986	ACTIVE	J	J007-00-4/731	CER - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6987	ACTIVE	J	J007-00-4/732	Station Supervisor Office - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6988	ACTIVE	J	J007-00-4/733	CER - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6989	ACTIVE	J	J007-00-4/746	SCR - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6990	ACTIVE	J	J007-00-4/751	Station Control Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6991	ACTIVE	J	J007-00-4/752	Office - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6992	ACTIVE	J	J007-00-4/776	Fan Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6993	ACTIVE	J	J007-00-4/777	Fan Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6994	ACTIVE	J	J007-00-4/778	Fan Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6995	ACTIVE	J	J007-00-4/779	Fan Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6996	ACTIVE	J	J007-00-4/781	TXR - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6997	ACTIVE	J	J007-00-4/782	TXR - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6998	ACTIVE	J	J007-00-4/783	TXR - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6999	ACTIVE	J	J007-00-4/784	TXR - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7000	ACTIVE	J	J007-00-4/785	TXR - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7001	ACTIVE	J	J007-00-4/791	Service Riser - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7002	ACTIVE	J	J007-00-4/792	Service Riser - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7003	ACTIVE	J	J007-00-4/801	Office - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7004	ACTIVE	J	J007-00-4/802	Office - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7005	ACTIVE	J	J007-00-4/803	Interview Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7006	ACTIVE	J	J007-00-4/804	Office - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7007	ACTIVE	J	J007-00-4/901	Disused Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7008	ACTIVE	J	J007-00-4/902	Void - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7009	ACTIVE	J	J007-00-4/903	Void - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7010	ACTIVE	J	J007-00-4/904	Store - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7011	ACTIVE	J	J007-00-4/905	Tenancy - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7012	ACTIVE	J	J007-00-4/906	SCR - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7013	ACTIVE	J	J007-00-4/907	Store - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7014	ACTIVE	J	J007-00-4/908	Cupboard - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7015	ACTIVE	J	J007-00-4/909	Cupboard - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7016	ACTIVE	J	J007-00-4/910	Tenancy - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7017	ACTIVE	J	J007-00-4/911	Tenancy - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7018	ACTIVE	J	J007-00-4/912	Plant Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7019	ACTIVE	J	J007-00-4/951	Void - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7020	ACTIVE	J	J007-00-4/952	Disused Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1744	ACTIVE	J	J007-00-4/952	Disused Room - Station Building - Canary Wharf Stn	Odour	Other Hazardous Materials	Known				Ammonia Odour - Below OEL					
7021	ACTIVE	J	J007-00-4/TA1	Tenancy - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7022	ACTIVE	J	J007-00-5/081	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7023	ACTIVE	J	J007-00-5/082	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7024	ACTIVE	J	J007-00-5/083	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7025	ACTIVE	J	J007-00-5/084	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7026	ACTIVE	J	J007-00-5/099	Stairs: Linear - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7027	ACTIVE	J	J007-00-5/151	UMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7028	ACTIVE	J	J007-00-5/152	UMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7029	ACTIVE	J	J007-00-5/153	UMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7030	ACTIVE	J	J007-00-5/154	UMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7031	ACTIVE	J	J007-00-5/155	UMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7032	ACTIVE	J	J007-00-5/156	UMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7033	ACTIVE	J	J007-00-5/157	UMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7034	ACTIVE	J	J007-00-5/158	UMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7035	ACTIVE	J	J007-00-5/159	UMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7036	ACTIVE	J	J007-00-5/161	LMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7037	ACTIVE	J	J007-00-5/162	LMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7038	ACTIVE	J	J007-00-5/163	LMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7039	ACTIVE	J	J007-00-5/164	LMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7040	ACTIVE	J	J007-00-5/201	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7041	ACTIVE	J	J007-00-5/202	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7042	ACTIVE	J	J007-00-5/236	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7043	ACTIVE	J	J007-00-5/481	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7044	ACTIVE	J	J007-00-5/482	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7045	ACTIVE	J	J007-00-5/483	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7046	ACTIVE	J	J007-00-5/484	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7047	ACTIVE	J	J007-00-5/485	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7048	ACTIVE	J	J007-00-5/486	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7049	ACTIVE	J	J007-00-5/487	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7050	ACTIVE	J	J007-00-5/488	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7051	ACTIVE	J	J007-00-5/489	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7052	ACTIVE	J	J007-00-5/490	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7053	ACTIVE	J	J007-00-5/491	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7054	ACTIVE	J	J007-00-5/492	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7055	ACTIVE	J	J007-00-5/493	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7056	ACTIVE	J	J007-00-5/494	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7057	ACTIVE	J	J007-00-5/576	Stairs: Linear - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7058	ACTIVE	J	J007-00-5/577	Stairs: Linear - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7059	ACTIVE	J	J007-00-5/578	Stairs: Linear - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7060	ACTIVE	J	J007-00-5/579	Stairs: Linear - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7061	ACTIVE	J	J007-00-5/580	Stairs: Linear - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7062	ACTIVE	J	J007-00-5/631	Stairs: Spiral - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7063	ACTIVE	J	J007-00-5/661	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7064	ACTIVE	J	J007-00-5/662	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7065	ACTIVE	J	J007-00-5/663	Switch Cupboard- Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7066	ACTIVE	J	J007-00-5/664	Switch Cupboard - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7067	ACTIVE	J	J007-00-5/665	Switch Cupboard - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7068	ACTIVE	J	J007-00-5/666	Switch Cupboard - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7069	ACTIVE	J	J007-00-5/667	Switch Cupboard - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7070	ACTIVE	J	J007-00-5/668	Switch Cupboard - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7071	ACTIVE	J	J007-00-5/669	Switch Cupboard - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7072	ACTIVE	J	J007-00-5/670	Switch Cupboard - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7073	ACTIVE	J	J007-00-5/671	Switch Cupboard - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7074	ACTIVE	J	J007-00-5/672	Switch Cupboard - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7075	ACTIVE	J	J007-00-5/673	Switch Cupboard - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7076	ACTIVE	J	J007-00-5/674	Switch Cupboard - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7077	ACTIVE	J	J007-00-5/731	CER - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7078	ACTIVE	J	J007-00-5/761	Equipment Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7079	ACTIVE	J	J007-00-5/771	Lift Pump Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7080	ACTIVE	J	J007-00-5/776	Fan Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7081	ACTIVE	J	J007-00-5/777	Plant Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7082	ACTIVE	J	J007-00-5/778	Service Riser - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7083	ACTIVE	J	J007-00-5/901	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7084	ACTIVE	J	J007-00-5/902	Disused Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7085	ACTIVE	J	J007-00-5/903	Disused Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7086	ACTIVE	J	J007-00-5/904	Service Riser - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7087	ACTIVE	J	J007-00-5/905	Service Riser - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7088	ACTIVE	J	J007-00-5/906	Service Riser - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7089	ACTIVE	J	J007-00-5/907	Service Riser - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7090	ACTIVE	J	J007-00-5/908	Disused Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7091	ACTIVE	J	J007-00-5/910	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7092	ACTIVE	J	J007-00-5/911	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7093	ACTIVE	J	J007-00-5/912	Disused Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7094	ACTIVE	J	J007-00-6/081	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7095	ACTIVE	J	J007-00-6/082	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7096	ACTIVE	J	J007-00-6/083	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7097	ACTIVE	J	J007-00-6/084	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7098	ACTIVE	J	J007-00-6/085	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7099	ACTIVE	J	J007-00-6/086	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7100	ACTIVE	J	J007-00-6/087	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7101	ACTIVE	J	J007-00-6/236	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7102	ACTIVE	J	J007-00-6/237	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7103	ACTIVE	J	J007-00-6/238	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7104	ACTIVE	J	J007-00-6/239	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7105	ACTIVE	J	J007-00-6/261	Platform 1 - Westbound Local - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7106	ACTIVE	J	J007-00-6/262	Platform 2 - Eastbound Local - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7107	ACTIVE	J	J007-00-6/371	Store - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7108	ACTIVE	J	J007-00-6/406	Store - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7109	ACTIVE	J	J007-00-6/576	Stairs: Linear - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7110	ACTIVE	J	J007-00-6/577	Stairs: Linear - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7111	ACTIVE	J	J007-00-6/578	Stairs: Linear - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7112	ACTIVE	J	J007-00-6/579	Stairs: Linear - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7113	ACTIVE	J	J007-00-6/631	Stairs: Spiral - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7114	ACTIVE	J	J007-00-6/633	Stairs: Spiral - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7115	ACTIVE	J	J007-00-6/634	Stairs: Spiral - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7116	ACTIVE	J	J007-00-6/635	Stairs: Spiral - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7117	ACTIVE	J	J007-00-6/711	SER - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7118	ACTIVE	J	J007-00-6/756	Stairs: Linear - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7119	ACTIVE	J	J007-00-6/901	Disused Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7120	ACTIVE	J	J007-00-6/902	Disused Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1745	ACTIVE	J	J007-00-6/902	Disused Room - Station Building - Canary Wharf Stn	Odour	Other Hazardous Materials	Known				Ammonia Odour - Below OEL					
7121	ACTIVE	J	J007-00-6/903	Disused Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7122	ACTIVE	J	J007-00-6/904	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7123	ACTIVE	J	J007-00-6/905	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7124	ACTIVE	J	J007-00-6/906	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7125	ACTIVE	J	J007-00-6/907	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7126	ACTIVE	J	J007-00-6/908	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7127	ACTIVE	J	J007-00-6/909	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7128	ACTIVE	J	J007-00-6/910	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7129	ACTIVE	J	J007-00-6/911	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7130	ACTIVE	J	J007-00-6/912	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7131	ACTIVE	J	J007-00-6/951	Disused Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7132	ACTIVE	J	J007-00-6/952	Disused Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7133	ACTIVE	J	J007-00-7/032	Equipment Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7134	ACTIVE	J	J007-00-7/081	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7135	ACTIVE	J	J007-00-7/082	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7136	ACTIVE	J	J007-00-7/083	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7137	ACTIVE	J	J007-00-7/084	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7138	ACTIVE	J	J007-00-7/085	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7139	ACTIVE	J	J007-00-7/086	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7140	ACTIVE	J	J007-00-7/087	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7141	ACTIVE	J	J007-00-7/088	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7142	ACTIVE	J	J007-00-7/089	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7143	ACTIVE	J	J007-00-7/090	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7144	ACTIVE	J	J007-00-7/091	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7145	ACTIVE	J	J007-00-7/092	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7146	ACTIVE	J	J007-00-7/093	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7147	ACTIVE	J	J007-00-7/094	Service Riser - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7148	ACTIVE	J	J007-00-7/095	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7149	ACTIVE	J	J007-00-7/161	LMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7150	ACTIVE	J	J007-00-7/162	LMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7151	ACTIVE	J	J007-00-7/163	LMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7152	ACTIVE	J	J007-00-7/164	LMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7153	ACTIVE	J	J007-00-7/165	LMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7154	ACTIVE	J	J007-00-7/166	LMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7155	ACTIVE	J	J007-00-7/167	LMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7156	ACTIVE	J	J007-00-7/168	LMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7157	ACTIVE	J	J007-00-7/169	LMC - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7158	ACTIVE	J	J007-00-7/170	Disused Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2646	ACTIVE	J	J007-00-7/170	Disused Room - Station Building - Canary Wharf Stn	Odour	Other Hazardous Materials	Known				Ammonia Odour - Below OEL					
7159	ACTIVE	J	J007-00-7/236	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7160	ACTIVE	J	J007-00-7/237	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7161	ACTIVE	J	J007-00-7/238	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7162	ACTIVE	J	J007-00-7/239	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7163	ACTIVE	J	J007-00-7/240	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7164	ACTIVE	J	J007-00-7/241	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7165	ACTIVE	J	J007-00-7/242	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7166	ACTIVE	J	J007-00-7/243	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7167	ACTIVE	J	J007-00-7/244	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7168	ACTIVE	J	J007-00-7/245	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7169	ACTIVE	J	J007-00-7/246	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7170	ACTIVE	J	J007-00-7/247	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7171	ACTIVE	J	J007-00-7/248	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7172	ACTIVE	J	J007-00-7/249	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7173	ACTIVE	J	J007-00-7/250	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7174	ACTIVE	J	J007-00-7/251	Lobby - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7175	ACTIVE	J	J007-00-7/252	Passage - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7176	ACTIVE	J	J007-00-7/481	Service Riser - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7177	ACTIVE	J	J007-00-7/482	Service Riser - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7178	ACTIVE	J	J007-00-7/483	Service Riser - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7179	ACTIVE	J	J007-00-7/484	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7180	ACTIVE	J	J007-00-7/485	Service Riser - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7181	ACTIVE	J	J007-00-7/486	Service Riser - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7182	ACTIVE	J	J007-00-7/487	Service Riser - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7183	ACTIVE	J	J007-00-7/488	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7184	ACTIVE	J	J007-00-7/489	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7185	ACTIVE	J	J007-00-7/490	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7186	ACTIVE	J	J007-00-7/661	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7187	ACTIVE	J	J007-00-7/662	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7188	ACTIVE	J	J007-00-7/663	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7189	ACTIVE	J	J007-00-7/664	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7190	ACTIVE	J	J007-00-7/665	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7191	ACTIVE	J	J007-00-7/666	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7192	ACTIVE	J	J007-00-7/667	Switch Cupboard - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7193	ACTIVE	J	J007-00-7/668	Switch Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7194	ACTIVE	J	J007-00-7/706	SER - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7195	ACTIVE	J	J007-00-7/731	CER - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7196	ACTIVE	J	J007-00-7/771	Lift Pump Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7197	ACTIVE	J	J007-00-7/772	Pump Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7198	ACTIVE	J	J007-00-7/773	Lift Pump Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7199	ACTIVE	J	J007-00-7/774	Pump Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7200	ACTIVE	J	J007-00-7/775	Pump Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7201	ACTIVE	J	J007-00-7/786	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7202	ACTIVE	J	J007-00-7/787	Service Area - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7203	ACTIVE	J	J007-00-7/901	Pump Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7204	ACTIVE	J	J007-00-7/902	Disused Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1746	ACTIVE	J	J007-00-7/902	Disused Room - Station Building - Canary Wharf Stn	Odour	Other Hazardous Materials	Known				Ammonia Odour - Below OEL					
7205	ACTIVE	J	J007-00-7/903	Disused Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1747	ACTIVE	J	J007-00-7/903	Disused Room - Station Building - Canary Wharf Stn	Odour	Other Hazardous Materials	Known				Ammonia Odour - Below OEL					
7206	ACTIVE	J	J007-00-7/904	Disused Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2647	ACTIVE	J	J007-00-7/904	Disused Room - Station Building - Canary Wharf Stn	Odour	Other Hazardous Materials	Known				Ammonia Odour - Below OEL					
7207	ACTIVE	J	J007-00-7/905	Disused Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2278	ACTIVE	J	J007-00-7/905	Disused Room - Station Building - Canary Wharf Stn	Odour	Other Hazardous Materials	Known				Ammonia Odour - Below OEL					
7208	ACTIVE	J	J007-00-7/906	Disused Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1748	ACTIVE	J	J007-00-7/906	Disused Room - Station Building - Canary Wharf Stn	Odour	Other Hazardous Materials	Known				Ammonia Odour - Below OEL					



Hazardous Material Asset Register - Summary



J007-00 - Station Building - Canary Wharf Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7209	ACTIVE	J	J007-00-7/907	Disused Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2560	ACTIVE	J	J007-00-7/907	Disused Room - Station Building - Canary Wharf Stn	Odour	Other Hazardous Materials	Known				Ammonia Odour - Below OEL					
7210	ACTIVE	J	J007-00-7/951	Disused Room - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7211	ACTIVE	J	J007-00-A/576	Stairs: Linear - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7212	ACTIVE	J	J007-00-A/577	Stairs: Linear - Station Building - Canary Wharf Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

J009-00 - Station Building - Canada Water Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7236	ACTIVE	J	J009-00-1/081	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7237	ACTIVE	J	J009-00-1/082	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7238	ACTIVE	J	J009-00-1/083	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7239	ACTIVE	J	J009-00-1/084	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7240	ACTIVE	J	J009-00-1/085	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7241	ACTIVE	J	J009-00-1/401	Bin Store - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7242	ACTIVE	J	J009-00-1/551	Yard - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7243	ACTIVE	J	J009-00-1/601	Stairs: Linear - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J009-00 - Station Building - Canada Water Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7244	ACTIVE	J	J009-00-1/602	Stairs: Linear - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7245	ACTIVE	J	J009-00-1/603	Stairs: Linear - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7246	ACTIVE	J	J009-00-1/631	Stairs: Spiral - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7247	ACTIVE	J	J009-00-1/632	Stairs: Spiral - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7248	ACTIVE	J	J009-00-1/633	Stairs: Spiral - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7249	ACTIVE	J	J009-00-1/634	Stairs: Spiral - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7250	ACTIVE	J	J009-00-1/635	Stairs: Spiral - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7251	ACTIVE	J	J009-00-1/636	Stairs: Spiral - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7252	ACTIVE	J	J009-00-1/637	Stairs: Spiral - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7253	ACTIVE	J	J009-00-1/638	Stairs: Spiral - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7254	ACTIVE	J	J009-00-1/776	Fan Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7255	ACTIVE	J	J009-00-1/777	Vent Fan Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7256	ACTIVE	J	J009-00-1/778	Fan Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7257	ACTIVE	J	J009-00-1/779	Service Area - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7258	ACTIVE	J	J009-00-1/780	Service Area - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J009-00 - Station Building - Canada Water Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7259	ACTIVE	J	J009-00-1/901	Service Area - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7260	ACTIVE	J	J009-00-1/902	Disused Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7261	ACTIVE	J	J009-00-2/081	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7262	ACTIVE	J	J009-00-2/090	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7263	ACTIVE	J	J009-00-2/238	Passage - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7264	ACTIVE	J	J009-00-2/291	Office - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7265	ACTIVE	J	J009-00-2/776	Fan Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7266	ACTIVE	J	J009-00-3/001	Booking Hall - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7267	ACTIVE	J	J009-00-3/011	Ticket Office - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7268	ACTIVE	J	J009-00-3/021	POM - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7269	ACTIVE	J	J009-00-3/036	Toilet: Unisex - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7270	ACTIVE	J	J009-00-3/071	Circulation Area - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7271	ACTIVE	J	J009-00-3/081	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7272	ACTIVE	J	J009-00-3/082	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7273	ACTIVE	J	J009-00-3/083	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J009-00 - Station Building - Canada Water Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7274	ACTIVE	J	J009-00-3/084	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7275	ACTIVE	J	J009-00-3/085	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7276	ACTIVE	J	J009-00-3/086	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7277	ACTIVE	J	J009-00-3/087	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7278	ACTIVE	J	J009-00-3/088	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7279	ACTIVE	J	J009-00-3/089	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7280	ACTIVE	J	J009-00-3/201	Passage - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7281	ACTIVE	J	J009-00-3/202	Passage - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7282	ACTIVE	J	J009-00-3/203	Passage - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7283	ACTIVE	J	J009-00-3/236	Passage - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7284	ACTIVE	J	J009-00-3/237	Passage - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7285	ACTIVE	J	J009-00-3/238	Passage - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7286	ACTIVE	J	J009-00-3/291	Station Supervisor Office - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7287	ACTIVE	J	J009-00-3/316	Locker Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7288	ACTIVE	J	J009-00-3/317	Locker Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J009-00 - Station Building - Canada Water Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7289	ACTIVE	J	J009-00-3/331	Mess Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7290	ACTIVE	J	J009-00-3/332	Mess Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7291	ACTIVE	J	J009-00-3/333	Kitchen - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7292	ACTIVE	J	J009-00-3/371	Store - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7293	ACTIVE	J	J009-00-3/396	SVC - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7294	ACTIVE	J	J009-00-3/406	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7295	ACTIVE	J	J009-00-3/413	Store - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7296	ACTIVE	J	J009-00-3/415	Store - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7297	ACTIVE	J	J009-00-3/416	Toilet: Female - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7298	ACTIVE	J	J009-00-3/417	Toilet: Male - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7299	ACTIVE	J	J009-00-3/451	Tenancy - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7300	ACTIVE	J	J009-00-3/452	Tenancy - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7301	ACTIVE	J	J009-00-3/453	Tenancy - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7302	ACTIVE	J	J009-00-3/454	ATM - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7303	ACTIVE	J	J009-00-3/501	Office - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J009-00 - Station Building - Canada Water Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7304	ACTIVE	J	J009-00-3/576	Stairs: Linear - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7305	ACTIVE	J	J009-00-3/601	Stairs: Linear - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7306	ACTIVE	J	J009-00-3/602	Stairs: Linear - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7307	ACTIVE	J	J009-00-3/631	Stairs: Spiral - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7308	ACTIVE	J	J009-00-3/632	Stairs: Spiral - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7309	ACTIVE	J	J009-00-3/661	Switch Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7310	ACTIVE	J	J009-00-3/664	Switch Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7311	ACTIVE	J	J009-00-3/665	Switch Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7312	ACTIVE	J	J009-00-3/731	CER - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7313	ACTIVE	J	J009-00-3/746	SCR - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7314	ACTIVE	J	J009-00-3/751	Station Control Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7315	ACTIVE	J	J009-00-3/771	LMR - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7316	ACTIVE	J	J009-00-3/776	Plant Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7317	ACTIVE	J	J009-00-3/777	Fan Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7318	ACTIVE	J	J009-00-3/778	Fan Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J009-00 - Station Building - Canada Water Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7319	ACTIVE	J	J009-00-3/786	Service Riser - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7320	ACTIVE	J	J009-00-3/791	Vent Shaft - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7321	ACTIVE	J	J009-00-4/081	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7322	ACTIVE	J	J009-00-4/082	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7323	ACTIVE	J	J009-00-4/084	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7324	ACTIVE	J	J009-00-4/085	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7325	ACTIVE	J	J009-00-4/151	UMC - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7326	ACTIVE	J	J009-00-4/152	UMC - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7327	ACTIVE	J	J009-00-4/236	Passage - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7328	ACTIVE	J	J009-00-4/237	Passage - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7329	ACTIVE	J	J009-00-4/577	Stairs: Linear - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7330	ACTIVE	J	J009-00-4/661	Switch Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7331	ACTIVE	J	J009-00-4/662	Switch Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7332	ACTIVE	J	J009-00-4/731	CER - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7333	ACTIVE	J	J009-00-4/776	Fan Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J009-00 - Station Building - Canada Water Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7334	ACTIVE	J	J009-00-5/071	Circulation Area - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7335	ACTIVE	J	J009-00-5/072	Circulation Area - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7336	ACTIVE	J	J009-00-5/073	Circulation Area - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7337	ACTIVE	J	J009-00-5/081	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7338	ACTIVE	J	J009-00-5/082	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7339	ACTIVE	J	J009-00-5/083	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7340	ACTIVE	J	J009-00-5/084	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7341	ACTIVE	J	J009-00-5/085	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7342	ACTIVE	J	J009-00-5/086	Stairs: Linear - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7343	ACTIVE	J	J009-00-5/087	Stairs: Linear - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7344	ACTIVE	J	J009-00-5/089	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7345	ACTIVE	J	J009-00-5/090	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7346	ACTIVE	J	J009-00-5/091	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7347	ACTIVE	J	J009-00-5/092	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7348	ACTIVE	J	J009-00-5/093	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J009-00 - Station Building - Canada Water Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7349	ACTIVE	J	J009-00-5/094	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7350	ACTIVE	J	J009-00-5/236	Passage - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7351	ACTIVE	J	J009-00-5/237	Passage - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7352	ACTIVE	J	J009-00-5/263	Platform 3 - DLR - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7353	ACTIVE	J	J009-00-5/264	Platform 4 - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7354	ACTIVE	J	J009-00-5/406	Store - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7355	ACTIVE	J	J009-00-5/411	Store - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7356	ACTIVE	J	J009-00-5/412	Store - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7357	ACTIVE	J	J009-00-5/416	Disused Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7358	ACTIVE	J	J009-00-5/576	Stairs: Linear - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7359	ACTIVE	J	J009-00-5/577	Stairs: Linear - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7360	ACTIVE	J	J009-00-5/601	Stairs: Linear - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7361	ACTIVE	J	J009-00-5/602	Stairs: Linear - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7362	ACTIVE	J	J009-00-5/661	Switch Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7363	ACTIVE	J	J009-00-5/662	Switch Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J009-00 - Station Building - Canada Water Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7364	ACTIVE	J	J009-00-5/663	Switch Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7365	ACTIVE	J	J009-00-5/664	Switch Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7366	ACTIVE	J	J009-00-5/665	Switch Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7367	ACTIVE	J	J009-00-5/666	Switch Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7368	ACTIVE	J	J009-00-5/667	Switch Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7369	ACTIVE	J	J009-00-5/668	Switch Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7370	ACTIVE	J	J009-00-5/669	Switch Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7371	ACTIVE	J	J009-00-5/711	Relay Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7372	ACTIVE	J	J009-00-5/731	CER - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7373	ACTIVE	J	J009-00-5/761	Equipment Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7374	ACTIVE	J	J009-00-5/762	Equipment Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7375	ACTIVE	J	J009-00-5/771	Lift Pump Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7376	ACTIVE	J	J009-00-5/781	TXR - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7377	ACTIVE	J	J009-00-5/782	TXR - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7378	ACTIVE	J	J009-00-5/783	TXR - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J009-00 - Station Building - Canada Water Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7379	ACTIVE	J	J009-00-5/784	TXR - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7380	ACTIVE	J	J009-00-5/786	Service Area - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7381	ACTIVE	J	J009-00-5/787	Service Riser - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7382	ACTIVE	J	J009-00-5/788	Service Area - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7383	ACTIVE	J	J009-00-5/789	Service Area - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7384	ACTIVE	J	J009-00-5/790	Service Riser - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7385	ACTIVE	J	J009-00-5/791	Service Area - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7386	ACTIVE	J	J009-00-5/792	Disused Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7387	ACTIVE	J	J009-00-5/793	Void - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7388	ACTIVE	J	J009-00-5/801	Switch Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7389	ACTIVE	J	J009-00-5/901	Switch Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7390	ACTIVE	J	J009-00-5/902	Service Area - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7391	ACTIVE	J	J009-00-5/903	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7392	ACTIVE	J	J009-00-5/904	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7393	ACTIVE	J	J009-00-6/081	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J009-00 - Station Building - Canada Water Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7394	ACTIVE	J	J009-00-6/082	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7395	ACTIVE	J	J009-00-6/083	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7396	ACTIVE	J	J009-00-6/084	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7397	ACTIVE	J	J009-00-6/085	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7398	ACTIVE	J	J009-00-6/151	UMC - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7399	ACTIVE	J	J009-00-6/152	UMC - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7400	ACTIVE	J	J009-00-6/162	LMC - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7401	ACTIVE	J	J009-00-6/163	LMC - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7402	ACTIVE	J	J009-00-6/164	LMC - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7403	ACTIVE	J	J009-00-6/236	Passage - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7404	ACTIVE	J	J009-00-6/786	Service Riser - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7405	ACTIVE	J	J009-00-6/787	Service Area - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7406	ACTIVE	J	J009-00-6/788	Service Area - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7407	ACTIVE	J	J009-00-6/789	Service Riser - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7408	ACTIVE	J	J009-00-6/790	Service Riser - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J009-00 - Station Building - Canada Water Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7409	ACTIVE	J	J009-00-7/081	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7410	ACTIVE	J	J009-00-7/082	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7411	ACTIVE	J	J009-00-7/083	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7412	ACTIVE	J	J009-00-7/084	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7413	ACTIVE	J	J009-00-7/085	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7414	ACTIVE	J	J009-00-7/261	Platform 1 - Westbound Local - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7415	ACTIVE	J	J009-00-7/262	Platform 2 - Eastbound Local - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7416	ACTIVE	J	J009-00-7/406	Store - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7417	ACTIVE	J	J009-00-7/411	Store - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7418	ACTIVE	J	J009-00-7/414	CER - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7419	ACTIVE	J	J009-00-7/661	Switch Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7420	ACTIVE	J	J009-00-7/662	Switch Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7421	ACTIVE	J	J009-00-7/663	Switch Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7422	ACTIVE	J	J009-00-7/664	Switch Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7423	ACTIVE	J	J009-00-7/731	CER - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J009-00 - Station Building - Canada Water Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7424	ACTIVE	J	J009-00-7/771	Pump Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7425	ACTIVE	J	J009-00-7/772	Lift Pump Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7426	ACTIVE	J	J009-00-7/773	Lift Pump Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7427	ACTIVE	J	J009-00-7/776	Fan Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7428	ACTIVE	J	J009-00-7/777	Fan Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7429	ACTIVE	J	J009-00-7/786	Service Area - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7430	ACTIVE	J	J009-00-7/787	Service Area - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7431	ACTIVE	J	J009-00-7/792	Fan Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7432	ACTIVE	J	J009-00-7/901	Store - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7433	ACTIVE	J	J009-00-8/081	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7434	ACTIVE	J	J009-00-8/082	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7435	ACTIVE	J	J009-00-8/083	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7436	ACTIVE	J	J009-00-8/084	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7437	ACTIVE	J	J009-00-8/085	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7438	ACTIVE	J	J009-00-8/086	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J009-00 - Station Building - Canada Water Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7439	ACTIVE	J	J009-00-8/087	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7440	ACTIVE	J	J009-00-8/088	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7441	ACTIVE	J	J009-00-8/121	Platform Invert - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7442	ACTIVE	J	J009-00-8/122	Platform Invert - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7443	ACTIVE	J	J009-00-8/123	Platform Invert - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7444	ACTIVE	J	J009-00-8/124	Platform Invert - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7445	ACTIVE	J	J009-00-8/125	Platform Invert - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7446	ACTIVE	J	J009-00-8/126	Platform Invert - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7447	ACTIVE	J	J009-00-8/161	LMC - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7448	ACTIVE	J	J009-00-8/162	LMC - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7449	ACTIVE	J	J009-00-8/163	LMC - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7450	ACTIVE	J	J009-00-8/164	LMC - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7451	ACTIVE	J	J009-00-8/576	Stairs: Linear - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7452	ACTIVE	J	J009-00-8/577	Stairs: Linear - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7453	ACTIVE	J	J009-00-8/661	Switch Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J009-00 - Station Building - Canada Water Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7454	ACTIVE	J	J009-00-8/711	SER - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7455	ACTIVE	J	J009-00-8/712	SER - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7456	ACTIVE	J	J009-00-8/771	Pump Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7457	ACTIVE	J	J009-00-8/786	Fan Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7458	ACTIVE	J	J009-00-8/787	Fan Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7459	ACTIVE	J	J009-00-8/788	Service Riser - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7460	ACTIVE	J	J009-00-8/901	Service Area - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7461	ACTIVE	J	J009-00-8/902	Service Area - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7462	ACTIVE	J	J009-00-8/903	Plant Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7463	ACTIVE	J	J009-00-8/904	Service Area - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7464	ACTIVE	J	J009-00-8/905	Service Area - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7465	ACTIVE	J	J009-00-8/906	Service Area - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7466	ACTIVE	J	J009-00-8/907	Service Area - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7467	ACTIVE	J	J009-00-8/908	Service Area - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7468	ACTIVE	J	J009-00-A/081	Lobby - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J009-00 - Station Building - Canada Water Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7469	ACTIVE	J	J009-00-A/481	Equipment Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7470	ACTIVE	J	J009-00-A/776	Fan Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7471	ACTIVE	J	J009-00-A/777	Fan Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7472	ACTIVE	J	J009-00-A/778	Service Riser - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7473	ACTIVE	J	J009-00-A/779	Service Area - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7474	ACTIVE	J	J009-00-A/780	Fan Room - Station Building - Canada Water Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

J011-00 - Station Building - Bermondsey Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7475	ACTIVE	J	J011-00-1/001	Booking Hall - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7476	ACTIVE	J	J011-00-1/011	Ticket Office - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7477	ACTIVE	J	J011-00-1/021	POM - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7478	ACTIVE	J	J011-00-1/031	Station Supervisor Office - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7479	ACTIVE	J	J011-00-1/032	Kitchen - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7480	ACTIVE	J	J011-00-1/036	Toilet: Unisex - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7481	ACTIVE	J	J011-00-1/071	Circulation Area - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J011-00 - Station Building - Bermondsey Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7482	ACTIVE	J	J011-00-1/081	Yard - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7483	ACTIVE	J	J011-00-1/082	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7484	ACTIVE	J	J011-00-1/237	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7485	ACTIVE	J	J011-00-1/238	Passage - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7486	ACTIVE	J	J011-00-1/239	Passage - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7487	ACTIVE	J	J011-00-1/240	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7488	ACTIVE	J	J011-00-1/241	Passage - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7489	ACTIVE	J	J011-00-1/242	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7490	ACTIVE	J	J011-00-1/243	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7491	ACTIVE	J	J011-00-1/244	Passage - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7492	ACTIVE	J	J011-00-1/245	Passage - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7493	ACTIVE	J	J011-00-1/247	Passage - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7494	ACTIVE	J	J011-00-1/317	Locker Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7495	ACTIVE	J	J011-00-1/318	Store - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7496	ACTIVE	J	J011-00-1/331	Kitchen - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J011-00 - Station Building - Bermondsey Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7497	ACTIVE	J	J011-00-1/341	Quiet Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7498	ACTIVE	J	J011-00-1/371	Office - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7499	ACTIVE	J	J011-00-1/401	Bin Store - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7500	ACTIVE	J	J011-00-1/406	Store - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7501	ACTIVE	J	J011-00-1/411	Store - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7502	ACTIVE	J	J011-00-1/416	Toilet: Female - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7503	ACTIVE	J	J011-00-1/417	Toilet: Male - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7504	ACTIVE	J	J011-00-1/452	Tenancy - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7505	ACTIVE	J	J011-00-1/453	ATM - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7506	ACTIVE	J	J011-00-1/576	Stairs: Linear - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7507	ACTIVE	J	J011-00-1/577	Stairs: Linear - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7508	ACTIVE	J	J011-00-1/601	Stairs: Linear - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7509	ACTIVE	J	J011-00-1/631	Stairs: Spiral - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7510	ACTIVE	J	J011-00-1/632	Stairs: Spiral - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7511	ACTIVE	J	J011-00-1/633	Stairs: Spiral - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J011-00 - Station Building - Bermondsey Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7512	ACTIVE	J	J011-00-1/634	Stairs: Spiral - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7513	ACTIVE	J	J011-00-1/661	Switch Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7514	ACTIVE	J	J011-00-1/662	Switch Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7515	ACTIVE	J	J011-00-1/663	Disused Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7516	ACTIVE	J	J011-00-1/746	SCR - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7517	ACTIVE	J	J011-00-1/751	Station Control Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7518	ACTIVE	J	J011-00-1/752	Office - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7519	ACTIVE	J	J011-00-1/901	Service Riser - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7520	ACTIVE	J	J011-00-2/072	Circulation Area - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7521	ACTIVE	J	J011-00-2/081	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7522	ACTIVE	J	J011-00-2/082	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7523	ACTIVE	J	J011-00-2/236	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7524	ACTIVE	J	J011-00-2/238	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7525	ACTIVE	J	J011-00-2/239	Passage - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7526	ACTIVE	J	J011-00-2/240	Passage - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J011-00 - Station Building - Bermondsey Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7527	ACTIVE	J	J011-00-2/396	SVC - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7528	ACTIVE	J	J011-00-2/397	SVC - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7529	ACTIVE	J	J011-00-2/416	Cleaners Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7530	ACTIVE	J	J011-00-2/635	Ladder Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7531	ACTIVE	J	J011-00-2/661	Switch Cupboard - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7532	ACTIVE	J	J011-00-2/662	Switch Cupboard - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7533	ACTIVE	J	J011-00-2/771	Pump Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7534	ACTIVE	J	J011-00-2/776	Fan Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7535	ACTIVE	J	J011-00-2/901	Service Riser - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7536	ACTIVE	J	J011-00-3/151	UMC - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7537	ACTIVE	J	J011-00-3/236	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7538	ACTIVE	J	J011-00-3/237	Passage - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7539	ACTIVE	J	J011-00-3/239	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7540	ACTIVE	J	J011-00-3/240	Passage - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7541	ACTIVE	J	J011-00-3/241	Passage - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J011-00 - Station Building - Bermondsey Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7542	ACTIVE	J	J011-00-3/242	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7543	ACTIVE	J	J011-00-3/243	Passage - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7544	ACTIVE	J	J011-00-3/244	Passage - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7545	ACTIVE	J	J011-00-3/245	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7546	ACTIVE	J	J011-00-3/246	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7547	ACTIVE	J	J011-00-3/411	Disused Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7548	ACTIVE	J	J011-00-3/664	Switch Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7549	ACTIVE	J	J011-00-3/665	Switch Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7550	ACTIVE	J	J011-00-3/731	CER - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7551	ACTIVE	J	J011-00-3/761	Equipment Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7552	ACTIVE	J	J011-00-3/776	Fan Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7553	ACTIVE	J	J011-00-3/777	Fan Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7554	ACTIVE	J	J011-00-3/778	Plant Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7555	ACTIVE	J	J011-00-3/901	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7556	ACTIVE	J	J011-00-3/902	Service Riser - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J011-00 - Station Building - Bermondsey Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7557	ACTIVE	J	J011-00-4/236	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7558	ACTIVE	J	J011-00-4/237	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7559	ACTIVE	J	J011-00-4/238	Passage - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7560	ACTIVE	J	J011-00-4/239	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7561	ACTIVE	J	J011-00-4/240	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7562	ACTIVE	J	J011-00-4/241	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7563	ACTIVE	J	J011-00-4/242	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7564	ACTIVE	J	J011-00-4/243	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7565	ACTIVE	J	J011-00-4/666	Switch Cupboard - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7566	ACTIVE	J	J011-00-4/667	Switch Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7567	ACTIVE	J	J011-00-4/668	Switch Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7568	ACTIVE	J	J011-00-4/733	CER - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7569	ACTIVE	J	J011-00-4/777	Service Area - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7570	ACTIVE	J	J011-00-4/781	TXR - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7571	ACTIVE	J	J011-00-4/782	TXR - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J011-00 - Station Building - Bermondsey Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7572	ACTIVE	J	J011-00-4/786	Service Riser - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7573	ACTIVE	J	J011-00-4/787	Service Riser - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7574	ACTIVE	J	J011-00-4/901	Disused Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7575	ACTIVE	J	J011-00-4/902	Service Riser - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7576	ACTIVE	J	J011-00-4/903	Service Riser - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7577	ACTIVE	J	J011-00-4/904	Void - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7578	ACTIVE	J	J011-00-4/905	Void - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7579	ACTIVE	J	J011-00-4/906	Void - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7580	ACTIVE	J	J011-00-5/071	Circulation Area - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7581	ACTIVE	J	J011-00-5/081	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7582	ACTIVE	J	J011-00-5/082	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7583	ACTIVE	J	J011-00-5/083	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7584	ACTIVE	J	J011-00-5/201	Passage - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7585	ACTIVE	J	J011-00-5/236	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7586	ACTIVE	J	J011-00-5/237	Passage - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J011-00 - Station Building - Bermondsey Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7587	ACTIVE	J	J011-00-5/239	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7588	ACTIVE	J	J011-00-5/240	Passage - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7589	ACTIVE	J	J011-00-5/241	Passage - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7590	ACTIVE	J	J011-00-5/242	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7591	ACTIVE	J	J011-00-5/243	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7592	ACTIVE	J	J011-00-5/245	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7593	ACTIVE	J	J011-00-5/246	Passage - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7594	ACTIVE	J	J011-00-5/248	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7595	ACTIVE	J	J011-00-5/249	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7596	ACTIVE	J	J011-00-5/250	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7597	ACTIVE	J	J011-00-5/261	Platform 1 - Westbound Local - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7598	ACTIVE	J	J011-00-5/262	Platform 2 - Eastbound Local - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7599	ACTIVE	J	J011-00-5/406	Store - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7600	ACTIVE	J	J011-00-5/576	Stairs: Linear - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7601	ACTIVE	J	J011-00-5/631	Stairs: Spiral - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J011-00 - Station Building - Bermondsey Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7602	ACTIVE	J	J011-00-5/632	Stairs: Spiral - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7603	ACTIVE	J	J011-00-5/661	Switch Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7604	ACTIVE	J	J011-00-5/662	Switch Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7605	ACTIVE	J	J011-00-5/663	Switch Cupboard - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7606	ACTIVE	J	J011-00-5/669	Switch Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7607	ACTIVE	J	J011-00-5/711	SER - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7608	ACTIVE	J	J011-00-5/712	SER - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7609	ACTIVE	J	J011-00-5/734	CER - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7610	ACTIVE	J	J011-00-5/771	Lift Pump Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7611	ACTIVE	J	J011-00-5/776	Plant Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7612	ACTIVE	J	J011-00-5/786	Plant Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7613	ACTIVE	J	J011-00-5/787	Service Riser - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7614	ACTIVE	J	J011-00-5/788	Service Riser - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7615	ACTIVE	J	J011-00-5/789	Service Riser - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7616	ACTIVE	J	J011-00-5/790	Service Riser - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J011-00 - Station Building - Bermondsey Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7617	ACTIVE	J	J011-00-5/901	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7618	ACTIVE	J	J011-00-5/902	Store - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7619	ACTIVE	J	J011-00-5/903	Disused Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7620	ACTIVE	J	J011-00-5/904	Disused Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7621	ACTIVE	J	J011-00-5/951	Disused Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7622	ACTIVE	J	J011-00-6/121	Platform Invert - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7623	ACTIVE	J	J011-00-6/122	Platform Invert - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7624	ACTIVE	J	J011-00-6/161	LMC - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7625	ACTIVE	J	J011-00-6/236	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7626	ACTIVE	J	J011-00-6/771	Switch Cupboard - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7627	ACTIVE	J	J011-00-A/131	LMR - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7628	ACTIVE	J	J011-00-A/236	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7629	ACTIVE	J	J011-00-A/237	Lobby - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7630	ACTIVE	J	J011-00-A/776	Fan Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7631	ACTIVE	J	J011-00-A/777	Plant Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J011-00 - Station Building - Bermondsey Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7632	ACTIVE	J	J011-00-A/779	Equipment Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7633	ACTIVE	J	J011-00-A/780	Fan Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7634	ACTIVE	J	J011-00-A/781	Fan Room - Station Building - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

J013-00 - Station Building - Southwark Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7699	ACTIVE	J	J013-00-1/002	Booking Hall - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7700	ACTIVE	J	J013-00-1/012	Ticket Office - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7701	ACTIVE	J	J013-00-1/022	POM - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7702	ACTIVE	J	J013-00-1/032	Mess Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7703	ACTIVE	J	J013-00-1/037	Toilet: Unisex - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7704	ACTIVE	J	J013-00-1/073	Circulation Area - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7705	ACTIVE	J	J013-00-1/081	Lobby - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7706	ACTIVE	J	J013-00-1/082	Lobby - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7707	ACTIVE	J	J013-00-1/083	Lobby - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7708	ACTIVE	J	J013-00-1/084	Lobby - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J013-00 - Station Building - Southwark Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7709	ACTIVE	J	J013-00-1/085	Lobby - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7710	ACTIVE	J	J013-00-1/086	Lobby - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7711	ACTIVE	J	J013-00-1/087	Lobby - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7712	ACTIVE	J	J013-00-1/088	Lobby - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7713	ACTIVE	J	J013-00-1/089	Lobby - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7714	ACTIVE	J	J013-00-1/090	Lobby - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7715	ACTIVE	J	J013-00-1/091	Lobby - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7716	ACTIVE	J	J013-00-1/201	Passage - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7717	ACTIVE	J	J013-00-1/202	Passage - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7718	ACTIVE	J	J013-00-1/203	Passage - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7719	ACTIVE	J	J013-00-1/236	Passage - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7720	ACTIVE	J	J013-00-1/242	Passage - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7721	ACTIVE	J	J013-00-1/243	Passage - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7722	ACTIVE	J	J013-00-1/244	Passage - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7723	ACTIVE	J	J013-00-1/396	SVC - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J013-00 - Station Building - Southwark Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7724	ACTIVE	J	J013-00-1/401	Store - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7725	ACTIVE	J	J013-00-1/409	Store - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7726	ACTIVE	J	J013-00-1/413	Store - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7727	ACTIVE	J	J013-00-1/578	Stairs: Linear - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7728	ACTIVE	J	J013-00-1/587	Stairs: Linear - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7729	ACTIVE	J	J013-00-1/601	Stairs: Linear - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7730	ACTIVE	J	J013-00-1/602	Stairs: Linear - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7731	ACTIVE	J	J013-00-1/603	Stairs: Linear - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7732	ACTIVE	J	J013-00-1/604	Stairs: Linear - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7733	ACTIVE	J	J013-00-1/661	Switch Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7734	ACTIVE	J	J013-00-1/662	Switch Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7735	ACTIVE	J	J013-00-1/663	Switch Cupboard - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7736	ACTIVE	J	J013-00-1/664	Switch Cupboard - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7737	ACTIVE	J	J013-00-1/666	Switch Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7738	ACTIVE	J	J013-00-1/667	Switch Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J013-00 - Station Building - Southwark Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7739	ACTIVE	J	J013-00-1/731	CER - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7740	ACTIVE	J	J013-00-1/756	Fan Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7741	ACTIVE	J	J013-00-1/762	Disused Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7742	ACTIVE	J	J013-00-1/776	Fan Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7743	ACTIVE	J	J013-00-1/777	Fan Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7744	ACTIVE	J	J013-00-1/778	Air Plenum - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7745	ACTIVE	J	J013-00-1/779	Fan Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7746	ACTIVE	J	J013-00-1/780	Air Plenum - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7747	ACTIVE	J	J013-00-1/781	TXR - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7748	ACTIVE	J	J013-00-1/782	TXR - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7749	ACTIVE	J	J013-00-1/905	Disused Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7750	ACTIVE	J	J013-00-1/906	Disused Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7751	ACTIVE	J	J013-00-1/911	Service Riser - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7752	ACTIVE	J	J013-00-1/912	Plant Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7753	ACTIVE	J	J013-00-1/951	Disused Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J013-00 - Station Building - Southwark Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7754	ACTIVE	J	J013-00-1/953	Disused Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7755	ACTIVE	J	J013-00-2/001	Booking Hall - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7756	ACTIVE	J	J013-00-2/011	Ticket Office - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7757	ACTIVE	J	J013-00-2/021	POM - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7758	ACTIVE	J	J013-00-2/031	Mess Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7759	ACTIVE	J	J013-00-2/036	Toilet: Unisex - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7760	ACTIVE	J	J013-00-2/047	Mess Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7761	ACTIVE	J	J013-00-2/071	Circulation Area - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7762	ACTIVE	J	J013-00-2/072	Circulation Area - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7763	ACTIVE	J	J013-00-2/081	Lobby - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7764	ACTIVE	J	J013-00-2/082	Lobby - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7765	ACTIVE	J	J013-00-2/083	Lobby - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7766	ACTIVE	J	J013-00-2/084	Lobby - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7767	ACTIVE	J	J013-00-2/131	Plant Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7768	ACTIVE	J	J013-00-2/152	UMC - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J013-00 - Station Building - Southwark Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7769	ACTIVE	J	J013-00-2/237	Passage - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7770	ACTIVE	J	J013-00-2/238	Passage - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7771	ACTIVE	J	J013-00-2/239	Passage - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7772	ACTIVE	J	J013-00-2/240	Passage - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7773	ACTIVE	J	J013-00-2/241	Passage - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7774	ACTIVE	J	J013-00-2/311	Station Supervisor Office - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7775	ACTIVE	J	J013-00-2/316	Locker Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7776	ACTIVE	J	J013-00-2/406	Store - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7777	ACTIVE	J	J013-00-2/411	Store - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7778	ACTIVE	J	J013-00-2/412	Store - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7779	ACTIVE	J	J013-00-2/416	Toilet: Female - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7780	ACTIVE	J	J013-00-2/417	Toilet: Male - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7781	ACTIVE	J	J013-00-2/481	Store - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7782	ACTIVE	J	J013-00-2/482	Store - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7783	ACTIVE	J	J013-00-2/483	Service Riser - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J013-00 - Station Building - Southwark Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7784	ACTIVE	J	J013-00-2/501	Office - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7785	ACTIVE	J	J013-00-2/576	Stairs: Linear - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7786	ACTIVE	J	J013-00-2/661	Switch Cupboard - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7787	ACTIVE	J	J013-00-2/662	Switch Cupboard - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7788	ACTIVE	J	J013-00-2/663	Switch Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7789	ACTIVE	J	J013-00-2/664	Switch Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7790	ACTIVE	J	J013-00-2/665	Switch Cupboard - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7791	ACTIVE	J	J013-00-2/731	CER - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7792	ACTIVE	J	J013-00-2/732	CER - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7793	ACTIVE	J	J013-00-2/746	SCR - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7794	ACTIVE	J	J013-00-2/751	Station Control Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7795	ACTIVE	J	J013-00-2/761	Equipment Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7796	ACTIVE	J	J013-00-2/776	Fan Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7797	ACTIVE	J	J013-00-2/786	Service Riser - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7798	ACTIVE	J	J013-00-2/787	Service Area - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J013-00 - Station Building - Southwark Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7799	ACTIVE	J	J013-00-2/788	Service Riser - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7800	ACTIVE	J	J013-00-2/789	Service Area - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7801	ACTIVE	J	J013-00-2/790	Service Riser - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7802	ACTIVE	J	J013-00-2/801	Office - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7803	ACTIVE	J	J013-00-2/901	Service Riser - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7804	ACTIVE	J	J013-00-2/902	Disused Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7805	ACTIVE	J	J013-00-2/903	Service Riser - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7806	ACTIVE	J	J013-00-2/912	Service Area - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7807	ACTIVE	J	J013-00-2/952	Disused Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7808	ACTIVE	J	J013-00-3/151	UMC - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7809	ACTIVE	J	J013-00-3/576	Ladder - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7810	ACTIVE	J	J013-00-3/786	Service Area - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7811	ACTIVE	J	J013-00-3/787	Service Area - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7812	ACTIVE	J	J013-00-4/071	Circulation Area - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7813	ACTIVE	J	J013-00-4/201	Passage - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J013-00 - Station Building - Southwark Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7814	ACTIVE	J	J013-00-4/236	Passage - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7815	ACTIVE	J	J013-00-4/576	Stairs: Linear - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7816	ACTIVE	J	J013-00-4/577	Stairs: Linear - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7817	ACTIVE	J	J013-00-4/601	Stairs: Linear - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7818	ACTIVE	J	J013-00-5/151	UMC - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7819	ACTIVE	J	J013-00-5/152	UMC - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7820	ACTIVE	J	J013-00-5/153	UMC - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7821	ACTIVE	J	J013-00-5/161	LMC - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7822	ACTIVE	J	J013-00-5/162	LMC - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7823	ACTIVE	J	J013-00-5/236	Passage - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7824	ACTIVE	J	J013-00-5/237	Passage - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7825	ACTIVE	J	J013-00-5/238	Passage - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7826	ACTIVE	J	J013-00-5/661	Switch Cupboard - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7827	ACTIVE	J	J013-00-5/662	Switch Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7828	ACTIVE	J	J013-00-5/711	SER - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J013-00 - Station Building - Southwark Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7829	ACTIVE	J	J013-00-5/712	SER - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7830	ACTIVE	J	J013-00-5/761	Equipment Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7831	ACTIVE	J	J013-00-5/762	Equipment Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7832	ACTIVE	J	J013-00-5/776	Fan Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7833	ACTIVE	J	J013-00-5/902	Lobby - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7834	ACTIVE	J	J013-00-6/071	Circulation Area - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7835	ACTIVE	J	J013-00-6/601	Stairs: Linear - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7836	ACTIVE	J	J013-00-6/602	Stairs: Linear - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7837	ACTIVE	J	J013-00-6/603	Stairs: Linear - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7838	ACTIVE	J	J013-00-6/604	Stairs: Linear - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7839	ACTIVE	J	J013-00-6/903	Disused Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7840	ACTIVE	J	J013-00-6/904	Disused Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7841	ACTIVE	J	J013-00-7/071	Circulation Area - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7842	ACTIVE	J	J013-00-7/072	Circulation Area - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7843	ACTIVE	J	J013-00-7/081	Lobby - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J013-00 - Station Building - Southwark Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7844	ACTIVE	J	J013-00-7/082	Lobby - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7845	ACTIVE	J	J013-00-7/083	Lobby - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7846	ACTIVE	J	J013-00-7/084	Lobby - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7847	ACTIVE	J	J013-00-7/085	Lobby - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7848	ACTIVE	J	J013-00-7/131	Pump Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7849	ACTIVE	J	J013-00-7/161	LMC - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7850	ACTIVE	J	J013-00-7/162	LMC - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7851	ACTIVE	J	J013-00-7/163	LMC - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7852	ACTIVE	J	J013-00-7/201	Passage - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7853	ACTIVE	J	J013-00-7/202	Passage - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7854	ACTIVE	J	J013-00-7/203	Passage - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7855	ACTIVE	J	J013-00-7/204	Passage - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7856	ACTIVE	J	J013-00-7/205	Passage - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7857	ACTIVE	J	J013-00-7/206	Passage - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7858	ACTIVE	J	J013-00-7/207	Passage - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J013-00 - Station Building - Southwark Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7859	ACTIVE	J	J013-00-7/208	Passage - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7860	ACTIVE	J	J013-00-7/236	Passage - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7861	ACTIVE	J	J013-00-7/237	Passage - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7862	ACTIVE	J	J013-00-7/261	Platform 1 - Westbound Local - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7863	ACTIVE	J	J013-00-7/262	Platform 2 - Eastbound Local - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7864	ACTIVE	J	J013-00-7/396	SVC - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7865	ACTIVE	J	J013-00-7/397	SVC - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7866	ACTIVE	J	J013-00-7/398	Disused Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7867	ACTIVE	J	J013-00-7/399	Disused Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7868	ACTIVE	J	J013-00-7/406	Store - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7869	ACTIVE	J	J013-00-7/576	Stairs: Linear - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7870	ACTIVE	J	J013-00-7/631	Stairs: Spiral - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7871	ACTIVE	J	J013-00-7/632	Stairs: Spiral - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7872	ACTIVE	J	J013-00-7/633	Stairs: Spiral - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7873	ACTIVE	J	J013-00-7/634	Stairs: Spiral - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J013-00 - Station Building - Southwark Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7874	ACTIVE	J	J013-00-7/661	Switch Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7875	ACTIVE	J	J013-00-7/662	Switch Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7876	ACTIVE	J	J013-00-7/663	Switch Cupboard - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7877	ACTIVE	J	J013-00-7/664	Switch Cupboard - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7878	ACTIVE	J	J013-00-7/665	Switch Cupboard - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7879	ACTIVE	J	J013-00-7/666	Switch Cupboard - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7880	ACTIVE	J	J013-00-7/731	CER - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7881	ACTIVE	J	J013-00-7/786	Service Riser - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7882	ACTIVE	J	J013-00-7/787	Service Riser - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7883	ACTIVE	J	J013-00-7/788	Service Riser - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7884	ACTIVE	J	J013-00-7/789	Service Riser - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7885	ACTIVE	J	J013-00-8/771	Pump Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7886	ACTIVE	J	J013-00-8/772	Pump Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7887	ACTIVE	J	J013-00-A/782	Fan Room - Station Building - Southwark Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10399	ACTIVE	J	N115-00-1/001	Booking Hall (Shell Entrance) - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Asbestos Free				New Construction as part of the Shell Ticket Hall Revelopment					
2818	INACTIVE	J	N115-00-1/001/CLG-01	Ceiling: Solid - 1 - Booking Hall - Station Building - Waterloo Stn	Debris: Other	Asbestos	Known				All Asbestos above the false ceiling has been removed, However the perimeter brick work could not be thouroughly cleaned and so these areas have been encapsulated; Asbestos contamination may also be present beneath sprayed coating on RSJ's				Yes	
10400	ACTIVE	J	N115-00-1/004	Booking Hall - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1846	ACTIVE	J	N115-00-1/004	Booking Hall - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10401	INACTIVE	J	N115-00-1/011	Ticket Office - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1847	INACTIVE	J	N115-00-1/011/CLG-01	Ceiling: Solid - 1 - Ticket Office - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected				Metal Work, PVC Cables				Yes	
10402	ACTIVE	J	N115-00-1/012	Ticket Office - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
1848	INACTIVE	J	N115-00-1/012	Ticket Office - Station Building - Waterloo Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
42203	ACTIVE	J	N115-00-1/012/WAL-003	Wall: Internal - 3 - Ticket Office - Station Building - Waterloo Stn	Other Boarding	Asbestos	Sampled – Not Detected				Boarding (0.75m2) to boxing - low level				N	N
10403	ACTIVE	J	N115-00-1/013	Ticket Office - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2901	ACTIVE	J	N115-00-1/013/CLG-01	Ceiling: Suspended - 1 - Ticket Office - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected				Metal Work, PVC Cables				Yes	
10404	ACTIVE	J	N115-00-1/014	Ticket Office - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1849	ACTIVE	J	N115-00-1/014	Ticket Office - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10405	ACTIVE	J	N115-00-1/020	Office - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
44142	ACTIVE	J	N115-00-1/020	Office - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Sampled – Not Detected				Supalux debris panel, 2m2, to floor and by entrance in Office 1/020 at Waterloo Station			R606401	N	N



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1850	ACTIVE	J	N115-00-1/020/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
10406	ACTIVE	J	N115-00-1/021	POM (Shell Entrance) - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Asbestos Free									
1851	ACTIVE	J	N115-00-1/021/CLG-01	Ceiling: Solid - 1 - POM - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected				New Construction as part of the Shell Ticket Hall Development				Yes	
10407	ACTIVE	J	N115-00-1/022	POM - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2367	ACTIVE	J	N115-00-1/022	POM - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Walls and floor solid construction.					
10408	ACTIVE	J	N115-00-1/023	POM - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1852	ACTIVE	J	N115-00-1/023	POM - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10409	ACTIVE	J	N115-00-1/029	POM - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1854	ACTIVE	J	N115-00-1/029/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above False Ceiling				Yes	
1853	ACTIVE	J	N115-00-1/029/CLG-01	Ceiling: Suspended - 1 - POM - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2819	ACTIVE	J	N115-00-1/029/FLR-01 80835075	Floor - 1 - POM - Station Building - Waterloo Stn Floor	Void	Asbestos	No Access: Presumed				Beneath - Suspended Tiles					yes
10410	ACTIVE	J	N115-00-1/030	Office - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1855	ACTIVE	J	N115-00-1/030/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2890	ACTIVE	J	N115-00-1/030/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected				Metal Work, PVC Cables				Yes	
10411	ACTIVE	J	N115-00-1/031	Mess Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1856	INACTIVE	J	N115-00-1/031/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Waterloo Stn	Debris: Other	Asbestos	Strongly Presumed				All Asbestos above the false ceiling has been removed, However the perimeter brick work could not be thoroughly cleaned and so these areas have been encapsulated; Asbestos contamination may also be present beneath sprayed coating on RSJ's				Yes	



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10412	ACTIVE	J	N115-00-1/032	Kitchen - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1857	ACTIVE	J	N115-00-1/032	Kitchen - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10413	ACTIVE	J	N115-00-1/033	Mess Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2368	ACTIVE	J	N115-00-1/033	Mess Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10414	ACTIVE	J	N115-00-1/035	Mess Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2820	ACTIVE	J	N115-00-1/035/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected				Metal Work, PVC Cables				Yes	
2308	ACTIVE	J	N115-00-1/035/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
10415	ACTIVE	J	N115-00-1/036	Toilet (Shell Entrance) - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Asbestos Free									
1858	ACTIVE	J	N115-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				New Construction as part of the Shell Ticket Hall Redevelopment					
2509	ACTIVE	J	N115-00-1/036/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected				Metal Work, PVC Cables New Construction as part of the Shell Ticket Hall Redevelopment				Yes	
10416	ACTIVE	J	N115-00-1/037	Toilet: Male - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1859	ACTIVE	J	N115-00-1/037	Toilet: Male - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10417	ACTIVE	J	N115-00-1/038	Toilet: Female - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1860	ACTIVE	J	N115-00-1/038	Toilet: Female - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10418	ACTIVE	J	N115-00-1/040	Toilet: Unisex - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2821	ACTIVE	J	N115-00-1/040/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected				Metal Work, PVC Cables				Yes	
1861	ACTIVE	J	N115-00-1/040/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10419	ACTIVE	J	N115-00-1/055	Mess Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1862	ACTIVE	J	N115-00-1/055/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected				Block, Concrete, plaster, PVC cables, lagging, rock wool, conduit, air con				Yes	
2925	ACTIVE	J	N115-00-1/055/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
10420	ACTIVE	J	N115-00-1/071	Circulation Area - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1863	ACTIVE	J	N115-00-1/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected				Metal Work, PVC Cables				Yes	
10421	ACTIVE	J	N115-00-1/072	Circulation Area - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1864	ACTIVE	J	N115-00-1/072/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected				Metal trunking & Concrete; rock wool fire stop metal pipes				Yes	
1865	ACTIVE	J	N115-00-1/072/FLR-01	Floor - 1 - Circulation Area - Station Building - Waterloo Stn	Void	Asbestos	No Access: Presumed				Not surveyed - Manhole 1					yes
2822	ACTIVE	J	N115-00-1/072/FLR-01	Floor - 1 - Circulation Area - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected				All cable sleeves terracotta, all cables plastic, fibreglass lagging - Manhole 2&3					yes
10422	ACTIVE	J	N115-00-1/074	Circulation Area - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1866	ACTIVE	J	N115-00-1/074	Circulation Area - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10423	ACTIVE	J	N115-00-1/081	Lobby (Shell Entrance) - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1867	ACTIVE	J	N115-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected				Metal Work, PVC Cables				Yes	
2309	ACTIVE	J	N115-00-1/081/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
10424	ACTIVE	J	N115-00-1/082	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1869	ACTIVE	J	N115-00-1/082/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected				Block, Concrete, plaster, PVC cables, lagging, rock wool, conduit, air con				Yes	
1868	ACTIVE	J	N115-00-1/082/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10425	ACTIVE	J	N115-00-1/083	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1870	ACTIVE	J	N115-00-1/083/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2369	ACTIVE	J	N115-00-1/083/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected				Metal Work, PVC Cables				Yes	
10426	ACTIVE	J	N115-00-1/087	Circulation Area - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2823	ACTIVE	J	N115-00-1/087/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1871	ACTIVE	J	N115-00-1/087/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Waterloo Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling - Not Surveyed				Yes	
2566	ACTIVE	J	N115-00-1/087/FLR-01	Floor - 1 - Circulation Area - Station Building - Waterloo Stn	Void	Asbestos	No Access: Presumed									yes
10427	ACTIVE	J	N115-00-1/088	Circulation Area - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1872	ACTIVE	J	N115-00-1/088/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Waterloo Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling - Not Surveyed				Yes	
2915	ACTIVE	J	N115-00-1/088/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1873	ACTIVE	J	N115-00-1/088/FLR-01	Floor - 1 - Circulation Area - Station Building - Waterloo Stn	Void	Asbestos	No Access: Presumed				Manhole No 5 - Tile damage, No access					yes
2824	ACTIVE	J	N115-00-1/088/FLR-01	Floor - 1 - Circulation Area - Station Building - Waterloo Stn	Void	Asbestos	No Access: Presumed				Manhole No. 4 - Tile damage, No access					yes
10428	ACTIVE	J	N115-00-1/089	Circulation Area - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1874	ACTIVE	J	N115-00-1/089/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1875	ACTIVE	J	N115-00-1/089/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Waterloo Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling - Not Surveyed				Yes	
10429	ACTIVE	J	N115-00-1/090	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1876	ACTIVE	J	N115-00-1/090	Lobby - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10430	ACTIVE	J	N115-00-1/091	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1877	ACTIVE	J	N115-00-1/091	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10431	ACTIVE	J	N115-00-1/092	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2370	ACTIVE	J	N115-00-1/092	Lobby - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10432	ACTIVE	J	N115-00-1/093	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2825	ACTIVE	J	N115-00-1/093	Lobby - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10433	ACTIVE	J	N115-00-1/094	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1878	ACTIVE	J	N115-00-1/094	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10434	ACTIVE	J	N115-00-1/095	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2881	ACTIVE	J	N115-00-1/095	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10435	ACTIVE	J	N115-00-1/096	Service Area - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1879	ACTIVE	J	N115-00-1/096	Service Area - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10436	ACTIVE	J	N115-00-1/098	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1881	ACTIVE	J	N115-00-1/098	Lobby - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10437	ACTIVE	J	N115-00-1/099	Circulation Area (Shell Entrance) - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
25856	INACTIVE	J	N115-00-1/099	Circulation Area (Shell Entrance) - Station Building - Waterloo Stn		Asbestos	Sampled – Not Detected				Firebreak across top bulkhead of both escalators 4 & 6, Shell Centre				N	N



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2826	INACTIVE	J	N115-00-1/099/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Waterloo Stn	Debris: Other	Asbestos	Known				All Asbestos above the false ceiling has been removed, However the perimeter brick work could not be thoroughly cleaned and so these areas have been encapsulated; Asbestos contamination may also be present beneath sprayed coating on RSJ's				Yes	
10438	ACTIVE	J	N115-00-1/131	LMR - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1882	ACTIVE	J	N115-00-1/131	LMR - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
1883	ACTIVE	J	N115-00-1/136	Lift Shaft - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10439	ACTIVE	J	N115-00-1/151	UMC - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1885	INACTIVE	J	N115-00-1/151	UMC - Station Building - Waterloo Stn	Cable: Sheath	Asbestos	Surveyed – Not Detected				Existing Cable Tray					
2371	INACTIVE	J	N115-00-1/151	UMC - Station Building - Waterloo Stn	Durasteel	Asbestos	Surveyed – Not Detected				Lid to Flammable store bin					
1884	INACTIVE	J	N115-00-1/151	UMC - Station Building - Waterloo Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Rings, Concrete sealed, Presumed caulking behind;					
1887	INACTIVE	J	N115-00-1/151	UMC - Station Building - Waterloo Stn	Lead/Leading	Lead Paint/Lead	Known				Girder - Brown oil based - 20 Lm					
1889	INACTIVE	J	N115-00-1/151	UMC - Station Building - Waterloo Stn	Lead/Leading	Lead Paint/Lead	Known				Concrete stand to motor x2 - Cream oil based - 10sqm					
1888	INACTIVE	J	N115-00-1/151	UMC - Station Building - Waterloo Stn	Lead/Leading	Lead Paint/Lead	Known				Girder to housing unit x3 - Grey oil based - 24Lm					
1886	INACTIVE	J	N115-00-1/151	UMC - Station Building - Waterloo Stn	Lead/Leading	Lead Paint/Lead	Known				Upstand girder - Grey based oil - 10 Lm					
2787	INACTIVE	J	N115-00-1/151	UMC - Station Building - Waterloo Stn	Lead/Leading	Lead Paint/Lead	Known				Stairs - Grey oil based - 5sqm					
10440	ACTIVE	J	N115-00-1/152	UMC - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2855	ACTIVE	J	N115-00-1/152	UMC - Station Building - Waterloo Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Rings, Concrete sealed, Presumed caulking behind					
1890	ACTIVE	J	N115-00-1/152	UMC - Station Building - Waterloo Stn	Durasteel	Asbestos	Surveyed – Not Detected				Lid to Flammable store bin					
1997	ACTIVE	J	N115-00-1/152	UMC - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	No Access: Presumed				Cable Ducts/Sleeves in Wall by Vent Grid					



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1998	ACTIVE	J	N115-00-1/152	UMC - Station Building - Waterloo Stn	Lead/Leading	Lead Paint/Lead	Known				Pipe work - Red oil based - 40Lm				N	N
1999	ACTIVE	J	N115-00-1/152	UMC - Station Building - Waterloo Stn	Lead/Leading	Lead Paint/Lead	Known				Girder - Cream/red oil based paint - 40Lm				N	N
2000	ACTIVE	J	N115-00-1/152	UMC - Station Building - Waterloo Stn	Lead/Leading	Lead Paint/Lead	Known				Walls - Cream emulsion - 110sqm				N	N
44471	ACTIVE	J	N115-00-1/152/ WAL-001 80839637	Wall: Internal - 1 - UMC - Station Building - Waterloo Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				Transformer box x1 Wall 4 - Presumed asbestos materials within		1			
10441	ACTIVE	J	N115-00-1/153	UMC - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2001	ACTIVE	J	N115-00-1/153	UMC - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Panel by Door					
2002	ACTIVE	J	N115-00-1/153	UMC - Station Building - Waterloo Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Rings, Concrete sealed, Presumed caulking behind					
46355	ACTIVE	J	N115-00-1/153	UMC - Station Building - Waterloo Stn	Cellactite Sheeting	Asbestos	Known				Cellactite sheeting, throughout, in back of VE panels and inside escalator chamber at high level - No access boarded over, refurbishment undertaken of area			R676501	N	N
2856	ACTIVE	J	N115-00-1/153	UMC - Station Building - Waterloo Stn	Cable: Sheath	Asbestos	Known				1x60mm white woven insulated cable located to wall adjacent to stairs		1			
10442	ACTIVE	J	N115-00-1/154	UMC - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2003	ACTIVE	J	N115-00-1/154	UMC - Station Building - Waterloo Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Rings, Concrete sealed, Presumed caulking behind					
10443	ACTIVE	J	N115-00-1/155	UMC - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2314	ACTIVE	J	N115-00-1/155	UMC - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10444	ACTIVE	J	N115-00-1/156	UMC - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2004	ACTIVE	J	N115-00-1/156	UMC - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
2005	ACTIVE	J	N115-00-1/172	Escalator Incline - Station Building - Waterloo Stn	Caulking	Asbestos	Strongly Presumed				Tunnel ring caulking all rings - caulking suspected in ring joints throughout incline shaft and UMC/ LMC's No access into escalator inclines during 2024 re-inspection. permit required with L&E					



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2424	ACTIVE	J	N115-00-1/173	Escalator Incline - Station Building - Waterloo Stn	Caulking	Asbestos	Strongly Presumed				Tunnel ring caulking all rings - caulking suspected in ring joints throughout incline shaft and UMC/LMC's No access into escalator inclines during 2024 re-inspection. permit required with L&E					
2857	ACTIVE	J	N115-00-1/174	Escalator Incline - Station Building - Waterloo Stn	Caulking	Asbestos	Strongly Presumed				Tunnel ring caulking all rings - caulking suspected in ring joints throughout incline shaft and UMC/LMC's No access into escalator inclines during 2024 re-inspection. permit required with L&E					
2928	ACTIVE	J	N115-00-1/175	Escalator Incline - Station Building - Waterloo Stn	Caulking	Asbestos	Strongly Presumed				Tunnel ring caulking all rings - caulking suspected in ring joints throughout incline shaft and UMC/LMC's No access into escalator inclines during 2024 re-inspection. permit required with L&E					
10445	ACTIVE	J	N115-00-1/205	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2006	ACTIVE	J	N115-00-1/205	Passage - Station Building - Waterloo Stn	Void	Asbestos	No Access: Presumed				Trunking					
10446	ACTIVE	J	N115-00-1/206	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2007	ACTIVE	J	N115-00-1/206	Passage - Station Building - Waterloo Stn	Lagging	Asbestos	Surveyed – Not Detected				Residue to and Debris Adjacent to Pipe in Riser					
10447	ACTIVE	J	N115-00-1/207	Circulation Area - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2008	ACTIVE	J	N115-00-1/207	Circulation Area - Station Building - Waterloo Stn	Void	Asbestos	No Access: Presumed				Cable Trunking					
10448	ACTIVE	J	N115-00-1/208	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2904	ACTIVE	J	N115-00-1/208	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10449	ACTIVE	J	N115-00-1/235	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10450	ACTIVE	J	N115-00-1/236	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2009	ACTIVE	J	N115-00-1/236	Lobby - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10451	ACTIVE	J	N115-00-1/238	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2011	INACTIVE	J	N115-00-1/238/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Waterloo Stn	Debris: Other	Asbestos	Known				All Asbestos above the false ceiling has been removed, However the perimeter brick work could not be thoroughly cleaned and so these areas have been encapsulated; Asbestos contamination may also be present beneath sprayed coating on RSJ's				Yes	
10452	ACTIVE	J	N115-00-1/239	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2858	ACTIVE	J	N115-00-1/239	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
2012	ACTIVE	J	N115-00-1/240/CLG-01	Ceiling: Solid - 1 - Overbridge - Station Building - Waterloo Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling - Not Surveyed				Yes	
10453	ACTIVE	J	N115-00-1/241	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2013	ACTIVE	J	N115-00-1/241/CLG-01 80836511	Ceiling: Solid - 1 - Passage - Station Building - Waterloo Stn Ceiling: Solid	Boarding: Cement	Asbestos	Known				Corrugated cementitious Chrysotile sheeting near 1/611, 1/206&1/205? - Asbestos Material not visible. Possibly located above false ceiling not accessed during 2024 re-inspection				YES	
10454	ACTIVE	J	N115-00-1/242	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2014	ACTIVE	J	N115-00-1/242	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10455	ACTIVE	J	N115-00-1/245	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2859	ACTIVE	J	N115-00-1/245	Passage - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2384	ACTIVE	J	N115-00-1/246	Plant Room Access - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Walls and floor solid construction. Ceiling fixed panels identified as Supalux boarding. No suspect CAF gaskets to pipework flanges.					
10456	ACTIVE	J	N115-00-1/247	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2513	ACTIVE	J	N115-00-1/247	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Walls and floor solid construction.					
2016	ACTIVE	J	N115-00-1/248	Overbridge - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not surveyed					
10457	ACTIVE	J	N115-00-1/250	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2017	ACTIVE	J	N115-00-1/250	Passage - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10458	ACTIVE	J	N115-00-1/252	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2860	ACTIVE	J	N115-00-1/252/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected				Metal Work, PVC Cables				Yes	
2018	ACTIVE	J	N115-00-1/252/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
45389	ACTIVE	J	N115-00-1/253	Lobby - Station Building - Waterloo Stn	Caulking	Asbestos	Presumed				LMC Access - All tunnel rings caulking presumed behind Concrete				N	N
10459	ACTIVE	J	N115-00-1/254	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2315	ACTIVE	J	N115-00-1/254/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2019	ACTIVE	J	N115-00-1/254/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected				Breeze Block				Yes	
10460	ACTIVE	J	N115-00-1/255	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2385	ACTIVE	J	N115-00-1/255	Lobby - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Walls and floor solid construction.					
10461	ACTIVE	J	N115-00-1/257	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2020	ACTIVE	J	N115-00-1/257	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10462	ACTIVE	J	N115-00-1/258	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2021	ACTIVE	J	N115-00-1/258	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10463	ACTIVE	J	N115-00-1/259	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2022	ACTIVE	J	N115-00-1/259	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10464	ACTIVE	J	N115-00-1/260	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2861	ACTIVE	J	N115-00-1/260	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10465	ACTIVE	J	N115-00-1/291	Office - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2023	ACTIVE	J	N115-00-1/291	Office - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10466	ACTIVE	J	N115-00-1/301	Office - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2025	ACTIVE	J	N115-00-1/301/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected				Concrete				Yes	
2024	ACTIVE	J	N115-00-1/301/CLG-01	Ceiling: Suspended - 1 - Office - Station Building - Waterloo Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Fibreboard					
10467	ACTIVE	J	N115-00-1/302	Office - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2862	ACTIVE	J	N115-00-1/302	Office - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10468	ACTIVE	J	N115-00-1/311	Office - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2026	ACTIVE	J	N115-00-1/311	Office - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Walls and floor solid construction.					
10469	ACTIVE	J	N115-00-1/319	Mess Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10470	ACTIVE	J	N115-00-1/320	Locker Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2863	ACTIVE	J	N115-00-1/320	Locker Room - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Boxing					
2030	ACTIVE	J	N115-00-1/320/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected				Breeze Block				Yes	
2029	ACTIVE	J	N115-00-1/320/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
10471	ACTIVE	J	N115-00-1/321	Toilet - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2031	ACTIVE	J	N115-00-1/321	Toilet - Station Building - Waterloo Stn	No Access	Asbestos	No Access: Presumed				Walls and floor solid construction.					



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10472	ACTIVE	J	N115-00-1/331	Mess Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2033	ACTIVE	J	N115-00-1/331	Mess Room - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Boxing					
2032	ACTIVE	J	N115-00-1/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2386	ACTIVE	J	N115-00-1/331/CLG-01	Ceiling: Solid - 1 - Mess Room - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected				Walls and floor solid construction. Modern Lino coverings over floor.				Yes	
10473	ACTIVE	J	N115-00-1/333	Locker Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2034	ACTIVE	J	N115-00-1/333/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2035	ACTIVE	J	N115-00-1/333/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected								Yes	
10474	ACTIVE	J	N115-00-1/334	Tea Point - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2425	ACTIVE	J	N115-00-1/334	Tea Point - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10475	ACTIVE	J	N115-00-1/351	Mess Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2036	ACTIVE	J	N115-00-1/351	Mess Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10476	ACTIVE	J	N115-00-1/396	SVC - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2865	ACTIVE	J	N115-00-1/396	SVC - Station Building - Waterloo Stn	No Access	Asbestos	No Access: Presumed				Ceiling, Walls and floor solid construction. Bolted Flanged Gaskets to Pipework was removed at Projects Request 26/04/2015					
10477	ACTIVE	J	N115-00-1/397	SVC - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2037	ACTIVE	J	N115-00-1/397	SVC - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10478	ACTIVE	J	N115-00-1/401	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2866	INACTIVE	J	N115-00-1/401	Switch Room - Station Building - Waterloo Stn	Isolator Switches	Asbestos	Strongly Presumed						2			
2038	INACTIVE	J	N115-00-1/401/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2039	INACTIVE	J	N115-00-1/401/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Waterloo Stn	Debris: Other	Asbestos	Known				All Asbestos above the false ceiling has been removed, However the perimeter brick work could not be thoroughly cleaned and so these areas have been encapsulated; Asbestos contamination may also be present beneath sprayed coating on RSJ's				Yes	
10479	ACTIVE	J	N115-00-1/402	Store (Shell Entrance) - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2387	INACTIVE	J	N115-00-1/402/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Waterloo Stn	Debris: Other	Asbestos	Known				All Asbestos above the false ceiling has been removed, However the perimeter brick work could not be thoroughly cleaned and so these areas have been encapsulated; Asbestos contamination may also be present beneath sprayed coating on RSJ's				Yes	
10480	ACTIVE	J	N115-00-1/403	Bin Store - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2040	ACTIVE	J	N115-00-1/403	Bin Store - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10481	ACTIVE	J	N115-00-1/404	Tenancy (Shell Entrance) - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2041	INACTIVE	J	N115-00-1/404/CLG-01	Ceiling: Suspended - 1 - Bin Store - Station Building - Waterloo Stn	Debris: Other	Asbestos	Known				All Asbestos above the false ceiling has been removed, However the perimeter brick work could not be thoroughly cleaned and so these areas have been encapsulated; Asbestos contamination may also be present beneath sprayed coating on RSJ's				Yes	
10482	ACTIVE	J	N115-00-1/406	Shower Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2042	ACTIVE	J	N115-00-1/406	Shower Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Walls and floor solid construction.					
10483	ACTIVE	J	N115-00-1/407	Store - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2043	ACTIVE	J	N115-00-1/407	Store - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10484	ACTIVE	J	N115-00-1/411	Store - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2867	ACTIVE	J	N115-00-1/411	Store - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Walls and floor solid construction.					
10485	ACTIVE	J	N115-00-1/412	Store (Shell Entrance) - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2316	ACTIVE	J	N115-00-1/412/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Waterloo Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Fibreboard					
2044	ACTIVE	J	N115-00-1/412/CLG-01	Ceiling: Suspended - 1 - Store - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected								Yes	
45390	INACTIVE	J	N115-00-1/413	Cleaners Room (Shell Entrance) - Station Building - Waterloo Stn		Asbestos	No Access: Presumed				S & T Depot - Corrugated steel sheets - No access above				Y	N
10486	ACTIVE	J	N115-00-1/414	Store - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2045	ACTIVE	J	N115-00-1/414	Store - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10487	ACTIVE	J	N115-00-1/415	Store - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2046	ACTIVE	J	N115-00-1/415	Store - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10488	ACTIVE	J	N115-00-1/416	Toilet: Female - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2868	INACTIVE	J	N115-00-1/416/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Waterloo Stn	Debris: Other	Asbestos	Known				All Asbestos above the false ceiling has been removed, However the perimeter brick work could not be thoroughly cleaned and so these areas have been encapsulated; Asbestos contamination may also be present beneath sprayed coating on RSJ's				Yes	
10489	ACTIVE	J	N115-00-1/417	Toilet: Male - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1891	INACTIVE	J	N115-00-1/417/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Waterloo Stn	Debris: Other	Asbestos	Known				All Asbestos above the false ceiling has been removed, However the perimeter brick work could not be thoroughly cleaned and so these areas have been encapsulated; Asbestos contamination may also be present beneath sprayed coating on RSJ's				Yes	



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10490	ACTIVE	J	N115-00-1/419	Toilet - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1893	ACTIVE	J	N115-00-1/419	Toilet - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Boxing					
2827	ACTIVE	J	N115-00-1/419/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1892	ACTIVE	J	N115-00-1/419/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected								Yes	
10491	ACTIVE	J	N115-00-1/420	Shower Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2567	ACTIVE	J	N115-00-1/420	Shower Room - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Boxing & Panel					
1895	ACTIVE	J	N115-00-1/420/CLG-01	Ceiling: Suspended - 1 - Shower Room - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected								Yes	
1894	ACTIVE	J	N115-00-1/420/CLG-01	Ceiling: Suspended - 1 - Shower Room - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
10492	ACTIVE	J	N115-00-1/421	Toilet: Unisex - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2828	ACTIVE	J	N115-00-1/421	Toilet: Unisex - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Walls and floor solid construction.					
10493	ACTIVE	J	N115-00-1/422	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2510	ACTIVE	J	N115-00-1/422/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected								Yes	
1896	ACTIVE	J	N115-00-1/422/CLG-01	Ceiling: Suspended - 1 - Lobby - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
10494	ACTIVE	J	N115-00-1/423	Toilet: Unisex - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2829	ACTIVE	J	N115-00-1/423/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected								Yes	
1897	ACTIVE	J	N115-00-1/423/CLG-01	Ceiling: Suspended - 1 - Toilet - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
10495	ACTIVE	J	N115-00-1/425	Shower Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1898	ACTIVE	J	N115-00-1/425	Shower Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Walls and floor solid construction.					
10496	ACTIVE	J	N115-00-1/427	Toilet: Unisex - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1899	ACTIVE	J	N115-00-1/427	Toilet: Unisex - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10497	ACTIVE	J	N115-00-1/428	Shower Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1900	ACTIVE	J	N115-00-1/428/CLG-01	Ceiling: Solid - 1 - Shower Room - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected								Yes	
2372	ACTIVE	J	N115-00-1/428/CLG-01	Ceiling: Solid - 1 - Shower Room - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
10498	ACTIVE	J	N115-00-1/435	Office - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1901	ACTIVE	J	N115-00-1/435	Office - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10499	ACTIVE	J	N115-00-1/436	Reception Office - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1902	ACTIVE	J	N115-00-1/436	Reception Office - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10500	ACTIVE	J	N115-00-1/451	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1903	INACTIVE	J	N115-00-1/451/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Waterloo Stn	Debris: Other	Asbestos	Known				All Asbestos above the false ceiling has been removed, However the perimeter brick work could not be thoroughly cleaned and so these areas have been encapsulated; Asbestos contamination may also be present beneath sprayed coating on RSJ's				Yes	
2830	INACTIVE	J	N115-00-1/451/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
10501	ACTIVE	J	N115-00-1/452	Tenancy - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1904	ACTIVE	J	N115-00-1/452/CLG-01	Ceiling: Solid - 1 - Tenancy - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected								Yes	



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10502	ACTIVE	J	N115-00-1/453	Tenancy - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2310	ACTIVE	J	N115-00-1/453	Tenancy - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10503	ACTIVE	J	N115-00-1/454	ATM (Shell Entrance) - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1905	ACTIVE	J	N115-00-1/454	ATM (Shell Entrance) - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10504	ACTIVE	J	N115-00-1/481	Consolidation Office - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1906	ACTIVE	J	N115-00-1/481	Consolidation Office - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10505	ACTIVE	J	N115-00-1/482	Store - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2831	ACTIVE	J	N115-00-1/482	Store - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10506	ACTIVE	J	N115-00-1/483	Store - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1907	ACTIVE	J	N115-00-1/483	Store - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10507	ACTIVE	J	N115-00-1/484	Disused Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1908	ACTIVE	J	N115-00-1/484	Disused Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10508	ACTIVE	J	N115-00-1/486	Tenancy - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10509	ACTIVE	J	N115-00-1/501	Store - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2373	ACTIVE	J	N115-00-1/501	Store - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10510	ACTIVE	J	N115-00-1/577	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2568	ACTIVE	J	N115-00-1/577	Stairs: Linear - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10511	ACTIVE	J	N115-00-1/578	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1909	ACTIVE	J	N115-00-1/578	Stairs: Linear - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10512	ACTIVE	J	N115-00-1/601	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1910	ACTIVE	J	N115-00-1/601	Stairs: Linear - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10513	ACTIVE	J	N115-00-1/605	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2832	ACTIVE	J	N115-00-1/605/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1911	ACTIVE	J	N115-00-1/605/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected								Yes	
10514	ACTIVE	J	N115-00-1/606	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1912	ACTIVE	J	N115-00-1/606/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1913	ACTIVE	J	N115-00-1/606/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected								Yes	
10515	ACTIVE	J	N115-00-1/607	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1914	ACTIVE	J	N115-00-1/607/CLG-01	Ceiling: Suspended - 1 - Linear Stairs - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2926	ACTIVE	J	N115-00-1/607/CLG-01	Ceiling: Suspended - 1 - Linear Stairs - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected								Yes	
10516	ACTIVE	J	N115-00-1/609	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2833	ACTIVE	J	N115-00-1/609	Passage - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10517	ACTIVE	J	N115-00-1/610	Switch Cupboard (Shell Entrance) - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1915	ACTIVE	J	N115-00-1/610	Switch Cupboard (Shell Entrance) - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10518	ACTIVE	J	N115-00-1/611	Switch Cupboard - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1971	ACTIVE	J	N115-00-1/611/CLG-01	Ceiling: Suspended - 1 - Linear Stairs - Station Building - Waterloo Stn	Boarding: Cement	Asbestos	Known				Corrugated sheets - By pillar near/ at stairs Corrugated sheets not visible. Possibly located above false ceiling not accessed during 2024 re-inspection.					
10519	ACTIVE	J	N115-00-1/633	Stairs: Spiral - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1974	ACTIVE	J	N115-00-1/633	Stairs: Spiral - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
2849	ACTIVE	J	N115-00-1/636	Overbridge - Station Building - Waterloo Stn	Boarding: Cement	Asbestos	Strongly Presumed				No access but presumed corrugated sheeting based on 1/205 findings					
10520	ACTIVE	J	N115-00-1/661	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1977	INACTIVE	J	N115-00-1/661	Switch Room - Station Building - Waterloo Stn	Westing house Boxes	Asbestos	Strongly Presumed				Insulation materials within		16			
1976	INACTIVE	J	N115-00-1/661/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Waterloo Stn	Debris: Other	Asbestos	Known				All Asbestos above the false ceiling has been removed, However the perimeter brick work could not be thoroughly cleaned and so these areas have been encapsulated; Asbestos contamination may also be present beneath sprayed coating on RSJ's				Yes	
1975	INACTIVE	J	N115-00-1/661/FLR-01	Floor - 1 - Switch Room - Station Building - Waterloo Stn	Vinyl tiles	Asbestos	Known									
10521	ACTIVE	J	N115-00-1/662	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1978	INACTIVE	J	N115-00-1/662/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Waterloo Stn	Debris: Other	Asbestos	Known				Ticket Hall Void above 1/662 - All Asbestos above the false ceiling has been removed, However the perimeter brick work could not be thoroughly cleaned and so these areas have been encapsulated; Asbestos contamination may also be present beneath sprayed coating on RSJ's				Yes	
2422	INACTIVE	J	N115-00-1/662/CLG-01	Ceiling: Suspended - 1 - Switch Room - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10522	ACTIVE	J	N115-00-1/663	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1979	ACTIVE	J	N115-00-1/663	Switch Room - Station Building - Waterloo Stn	Isolator Switches	Asbestos	Surveyed – Not Detected				14 x Grey fuse switch, 2x Bus Bar Chamber;		14			
2850	ACTIVE	J	N115-00-1/663/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Steel covered with Supalux					
10523	ACTIVE	J	N115-00-1/664	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2882	ACTIVE	J	N115-00-1/664	Switch Room - Station Building - Waterloo Stn	Isolator Switches	Asbestos	Strongly Presumed				Combination Fuse Switch boxes - 18x Wall 2&3, Asbestos materials within.		18			
2788	ACTIVE	J	N115-00-1/664/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Waterloo Stn	Cellactite Sheeting	Asbestos	Strongly Presumed				18sqm Cellactite sheets to high level ceiling.					
10524	ACTIVE	J	N115-00-1/665	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1980	ACTIVE	J	N115-00-1/665	Switch Room - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10525	ACTIVE	J	N115-00-1/666	Locker Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2903	ACTIVE	J	N115-00-1/666	Locker Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10526	ACTIVE	J	N115-00-1/667	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2381	ACTIVE	J	N115-00-1/667	Switch Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10527	ACTIVE	J	N115-00-1/668	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1981	ACTIVE	J	N115-00-1/668	Switch Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10528	ACTIVE	J	N115-00-1/669	Battery Invert - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1982	ACTIVE	J	N115-00-1/669	Battery Invert - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10529	ACTIVE	J	N115-00-1/670	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2851	ACTIVE	J	N115-00-1/670	Switch Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10530	ACTIVE	J	N115-00-1/671	Switch Cupboard - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1983	ACTIVE	J	N115-00-1/671	Switch Cupboard - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10531	ACTIVE	J	N115-00-1/672	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1984	ACTIVE	J	N115-00-1/672	Switch Room - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10532	ACTIVE	J	N115-00-1/673	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1985	ACTIVE	J	N115-00-1/673	Switch Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10533	ACTIVE	J	N115-00-1/674	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2852	ACTIVE	J	N115-00-1/674	Switch Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10534	ACTIVE	J	N115-00-1/675	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1986	ACTIVE	J	N115-00-1/675	Switch Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10535	ACTIVE	J	N115-00-1/679	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1987	ACTIVE	J	N115-00-1/679	Switch Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10536	ACTIVE	J	N115-00-1/680	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1988	ACTIVE	J	N115-00-1/680	Switch Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10537	ACTIVE	J	N115-00-1/681	Switch Cupboard - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2853	ACTIVE	J	N115-00-1/681	Switch Cupboard - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10538	ACTIVE	J	N115-00-1/682	Switch Cupboard - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1989	ACTIVE	J	N115-00-1/682	Switch Cupboard - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10540	ACTIVE	J	N115-00-1/731	CER - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1991	ACTIVE	J	N115-00-1/731	CER - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	Known				Cable sleeves		10			
1992	ACTIVE	J	N115-00-1/731	CER - Station Building - Waterloo Stn	Isolator Switches	Asbestos	Presumed				Combination Fuse Switches, 2x Wall 1 - Presumed asbestos materials within					
10541	ACTIVE	J	N115-00-1/732	CER - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2854	ACTIVE	J	N115-00-1/732/ WAL-002 80835297	Wall: Internal - 2 - CER - Station Building - Waterloo Stn Wall: Internal	Isolator Switches	Asbestos	Strongly Presumed				Combination Fuse Switches - 3x Wall 1, Asbestos materials within	3				
10542	ACTIVE	J	N115-00-1/733	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2383	ACTIVE	J	N115-00-1/733/ FLR-01	Floor - 1 - Switch Room - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected									yes
10543	ACTIVE	J	N115-00-1/734	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1993	ACTIVE	J	N115-00-1/734	Switch Room - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	Known				Cable ducts Cable ducts not visible beneath layer of cement on top.		2			
1994	ACTIVE	J	N115-00-1/734	Switch Room - Station Building - Waterloo Stn	Other Electrical Boxes	Asbestos	Removed				Fuse Boxes		2			
2423	ACTIVE	J	N115-00-1/734	Switch Room - Station Building - Waterloo Stn	Isolator Switches	Asbestos	Removed				Fuse Switches		3			
45392	INACTIVE	J	N115-00-1/734	Switch Room - Station Building - Waterloo Stn		Asbestos	Known				Cable Sleeve		2		N	N
45391	ACTIVE	J	N115-00-1/734	Switch Room - Station Building - Waterloo Stn		Asbestos	Known				Duct Near 1/734 - 25x Cable sleeves (12 by passage, 1 away from passage far side, 12 in duration) Unable to identify at time of 2024 re-inspection.		25		N	N
10544	ACTIVE	J	N115-00-1/736	CER - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1995	ACTIVE	J	N115-00-1/736	CER - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10545	ACTIVE	J	N115-00-1/737	CER - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1996	ACTIVE	J	N115-00-1/737	CER - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10546	ACTIVE	J	N115-00-1/741	Telephone Exchange - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2834	ACTIVE	J	N115-00-1/741/FLR-01 80836587	Floor - 1 - Telephone Exchange - Station Building - Waterloo Stn Floor	Void	Asbestos	Surveyed – Not Detected				Fixed Ceiling, Walls and floor solid construction. Modern electrics and equipment throughout.					yes
10547	ACTIVE	J	N115-00-1/746	SCR - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1916	INACTIVE	J	N115-00-1/746	SCR - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1917	INACTIVE	J	N115-00-1/746/CLG-01	Ceiling: Suspended - 1 - SCR - Station Building - Waterloo Stn	Debris: Other	Asbestos	Known				All Asbestos above the false ceiling has been removed, However the perimeter brick work could not be thoroughly cleaned and so these areas have been encapsulated; Asbestos contamination may also be present beneath sprayed coating on RSJ's				Yes	
10548	ACTIVE	J	N115-00-1/747	SVC - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2569	ACTIVE	J	N115-00-1/747	SVC - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Walls and floor solid construction. Ceiling fixed panels identified as Supalux boarding including loose panels. No suspect CAF gaskets to pipework flanges. Mastic to tank modern.					
10549	ACTIVE	J	N115-00-1/748	SCR - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1919	ACTIVE	J	N115-00-1/748/CLG-01 80931219	Ceiling: Solid - 1 - SCR - Station Building - Waterloo Stn Ceiling: Solid	Void	Asbestos	Surveyed – Not Detected				Ceiling, Walls and Floor is solid construction				Yes	
1918	INACTIVE	J	N115-00-1/748/FLR-01 80931220	Floor - 1 - SCR - Station Building - Waterloo Stn Floor	Void	Asbestos	No Access: Presumed				No access below false floor					yes
10550	ACTIVE	J	N115-00-1/749	SCR - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2835	ACTIVE	J	N115-00-1/749	SCR - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10551	ACTIVE	J	N115-00-1/754	Station Control Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1921	ACTIVE	J	N115-00-1/754/CLG-01	Ceiling: Solid - 1 - SCR - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected				Metal Work, PVC Cables				Yes	
1920	ACTIVE	J	N115-00-1/754/CLG-01	Ceiling: Solid - 1 - SCR - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
10552	ACTIVE	J	N115-00-1/755	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1922	ACTIVE	J	N115-00-1/755/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2374	ACTIVE	J	N115-00-1/755/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected				Metal Work, PVC Cables				Yes	
10553	ACTIVE	J	N115-00-1/756	Station Control Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2511	ACTIVE	J	N115-00-1/756	Station Control Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Walls and floor solid construction. Modern electrics and equipment throughout.					
10554	ACTIVE	J	N115-00-1/762	Services Riser (Shell Entrance) - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1925	INACTIVE	J	N115-00-1/762/CLG-01	Ceiling: Solid - 1 - Service Riser - Station Building - Waterloo Stn	Debris: Other	Asbestos	Known				All Asbestos above the false ceiling has been removed, However the perimeter brick work could not be thoroughly cleaned and so these areas have been encapsulated; Asbestos contamination may also be present beneath sprayed coating on RSJ's				Yes	
2836	INACTIVE	J	N115-00-1/762/CLG-01	Ceiling: Solid - 1 - Service Riser - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
10555	ACTIVE	J	N115-00-1/770	Plant Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1926	ACTIVE	J	N115-00-1/770	Plant Room - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10556	ACTIVE	J	N115-00-1/771	Plant Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45380	ACTIVE	J	N115-00-1/771	Plant Room - Station Building - Waterloo Stn	Other Electrical Boxes	Asbestos	Presumed				Combination fuse switch box, 1x wall 4 by entrance - Presumed asbestos materials within		1		N	N
1927	ACTIVE	J	N115-00-1/771	Plant Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10557	ACTIVE	J	N115-00-1/772	Plant Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
1928	ACTIVE	J	N115-00-1/772	Plant Room - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10558	ACTIVE	J	N115-00-1/776	Plant Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2837	ACTIVE	J	N115-00-1/776	Plant Room - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10559	ACTIVE	J	N115-00-1/777	Plant Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1929	ACTIVE	J	N115-00-1/777	Plant Room - Station Building - Waterloo Stn	Isolator Switches	Asbestos	Presumed				Combination Fuse Switch, 1x Wall 2 - Presumed asbestos materials within		1			
10560	ACTIVE	J	N115-00-1/781	TXR - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1931	ACTIVE	J	N115-00-1/781	TXR - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10561	ACTIVE	J	N115-00-1/782	TXR - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1932	ACTIVE	J	N115-00-1/782	TXR - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10562	ACTIVE	J	N115-00-1/785	Plant Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2311	ACTIVE	J	N115-00-1/785	Plant Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10563	ACTIVE	J	N115-00-1/786	Service Riser - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2838	ACTIVE	J	N115-00-1/786	Service Riser - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not surveyed					
10564	ACTIVE	J	N115-00-1/787	Service Area - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1933	ACTIVE	J	N115-00-1/787	Service Area - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10565	ACTIVE	J	N115-00-1/788	Service Area - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1934	ACTIVE	J	N115-00-1/788	Service Area - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10566	ACTIVE	J	N115-00-1/789	Service Riser - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1935	ACTIVE	J	N115-00-1/789	Service Riser - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10567	ACTIVE	J	N115-00-1/790	Service Riser - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2376	ACTIVE	J	N115-00-1/790	Service Riser - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10568	ACTIVE	J	N115-00-1/792	Service Area - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2839	ACTIVE	J	N115-00-1/792	Service Area - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10569	ACTIVE	J	N115-00-1/801	Locker Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2840	ACTIVE	J	N115-00-1/801	Locker Room - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Panel					
1939	ACTIVE	J	N115-00-1/801/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected								Yes	
1938	ACTIVE	J	N115-00-1/801/CLG-01	Ceiling: Suspended - 1 - Locker Room - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
10570	ACTIVE	J	N115-00-1/802	Store - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2902	ACTIVE	J	N115-00-1/802	Store - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10571	ACTIVE	J	N115-00-1/803	Training Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1940	ACTIVE	J	N115-00-1/803	Training Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10572	ACTIVE	J	N115-00-1/900	Locker Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1941	ACTIVE	J	N115-00-1/900	Locker Room - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10573	ACTIVE	J	N115-00-1/905	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2841	ACTIVE	J	N115-00-1/905	Passage - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10574	ACTIVE	J	N115-00-1/906	Disused Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Surveyed – Asbestos Known									
43433	ACTIVE	J	N115-00-1/906	Disused Room - Station Building - Waterloo Stn	Gasket :Pipework	Asbestos	Sampled – Not Detected				Gaskets, <1m2, to flanges of metal pipework, tank/system RTV64 in Sprinkler Room 1/906 at Waterloo Station			R532377	N	N
43435	ACTIVE	J	N115-00-1/906	Disused Room - Station Building - Waterloo Stn	Gasket :Pipework	Asbestos	Sampled – Not Detected				Gaskets, <1m2, to flanges of metal pipework, water tank/system RTV57 in Sprinkler Room 1/906 at Waterloo Station	1		R532377	N	N
43434	ACTIVE	J	N115-00-1/906	Disused Room - Station Building - Waterloo Stn	Gasket :Pipework	Asbestos	Sampled – Not Detected				Gaskets, <1m2, to flanges of metal pipework, water tank/system RTV63 in Sprinkler Room 1/906 at Waterloo Station	1		R532377	N	N
43184	ACTIVE	J	N115-00-1/906	Disused Room - Station Building - Waterloo Stn	Other Boarding	Asbestos	Sampled – Not Detected				Plasterboard MMMF within matrix1m2 loose to floor by wall 1 door way			R532376	N	N
43182	ACTIVE	J	N115-00-1/906	Disused Room - Station Building - Waterloo Stn	Control Panels	Asbestos	Removed				Materials within control panel 1no to pumps by door All electrical boxes/equipment inspected internally in Sprinkler Room 1/906 have been surveyed Room 1/906 not found in 2020 re-inspection. not on station layout plans. possible change in station layout since survey?	1		R532376	N	N
43180	ACTIVE	J	N115-00-1/906	Disused Room - Station Building - Waterloo Stn	Gasket :Pipework	Asbestos	Sampled – Not Detected				Green CAF Gaskets 12no to burgundy pipework flanges	12		R532376	N	N
43179	ACTIVE	J	N115-00-1/906	Disused Room - Station Building - Waterloo Stn	Mastic	Asbestos	Surveyed – Not Detected				Mastic selalant throughout to 4no galvernised sprinkler supply tanks	4		R532376	N	N
43436	ACTIVE	J	N115-00-1/906	Disused Room - Station Building - Waterloo Stn	Gasket :Pipework	Asbestos	Sampled – Not Detected				Gaskets, <1m2, to flanges of metal pipework, water tank/system RTV50 in Sprinkler Room 1/906 at Waterloo Station	1		R532377	N	N
43424	ACTIVE	J	N115-00-1/906	Disused Room - Station Building - Waterloo Stn		Asbestos	Sampled – Not Detected				All electrical boxes/equipment inspected internally in Sprinkler Room 1/906					
43183	ACTIVE	J	N115-00-1/906	Disused Room - Station Building - Waterloo Stn	Control Panels	Asbestos	Removed				Materials within control panel 1no to pumps All electrical boxes/equipment inspected internally in Sprinkler Room 1/906 have been surveyed Room 1/906 not found in 2020 re-inspection. not on station layout plans. possible change in station layout since survey?			R532376	N	N



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43181	ACTIVE	J	N115-00-1/906	Disused Room - Station Building - Waterloo Stn	Gasket :Pipework	Asbestos	Removed				CAF Gaskets 6no to large flanges to pipework Removed by Edenbeck on 20/10/2016			R532376	N	N
43178	ACTIVE	J	N115-00-1/906	Disused Room - Station Building - Waterloo Stn	Gasket :Pipework	Asbestos	Removed				Sprinkler Room - CAF Gaskets 28 to red pipework flanges Removed by Edenbeck on 20/10/2016	28		R532376	N	N
1944	INACTIVE	J	N115-00-1/906	Disused Room - Station Building - Waterloo Stn	No Access	Asbestos	Removed				Not surveyed					
10575	ACTIVE	J	N115-00-1/908	Store - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1945	ACTIVE	J	N115-00-1/908	Store - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10576	ACTIVE	J	N115-00-1/909	Service Area - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1946	INACTIVE	J	N115-00-1/909	Service Area - Station Building - Waterloo Stn	No Access	Asbestos	No Access: Presumed				Not surveyed					
10577	ACTIVE	J	N115-00-1/910	Service Riser - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2842	ACTIVE	J	N115-00-1/910	Service Riser - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10578	ACTIVE	J	N115-00-1/911	Void - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2312	ACTIVE	J	N115-00-1/911	Void - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10579	ACTIVE	J	N115-00-1/912	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1947	ACTIVE	J	N115-00-1/912	Stairs: Linear - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10580	ACTIVE	J	N115-00-1/913	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2378	ACTIVE	J	N115-00-1/913	Stairs: Linear - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10581	ACTIVE	J	N115-00-1/914	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2420	ACTIVE	J	N115-00-1/914	Stairs: Linear - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10582	ACTIVE	J	N115-00-1/915	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1948	ACTIVE	J	N115-00-1/915	Stairs: Linear - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10583	ACTIVE	J	N115-00-1/916	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1949	ACTIVE	J	N115-00-1/916	Stairs: Linear - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
2843	ACTIVE	J	N115-00-1/919	UMC - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10584	ACTIVE	J	N115-00-1/920	Disused Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1951	ACTIVE	J	N115-00-1/920	Disused Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10585	ACTIVE	J	N115-00-1/921	Void - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1952	ACTIVE	J	N115-00-1/921	Void - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10586	ACTIVE	J	N115-00-1/922	Store - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1953	ACTIVE	J	N115-00-1/922	Store - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10587	ACTIVE	J	N115-00-1/923	Store - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1954	ACTIVE	J	N115-00-1/923	Store - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10588	ACTIVE	J	N115-00-1/924	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2379	ACTIVE	J	N115-00-1/924	Switch Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10589	ACTIVE	J	N115-00-1/925	Store - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2844	ACTIVE	J	N115-00-1/925	Store - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10590	ACTIVE	J	N115-00-1/929	Toilet: Male - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1955	ACTIVE	J	N115-00-1/929	Toilet: Male - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10591	ACTIVE	J	N115-00-1/930	Toilet: Female - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1956	ACTIVE	J	N115-00-1/930	Toilet: Female - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10592	ACTIVE	J	N115-00-1/951	Service Area - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1957	ACTIVE	J	N115-00-1/951/CLG-01 80836607	Ceiling: Solid - 1 - Service Area - Station Building - Waterloo Stn Ceiling: Solid	Void	Asbestos	Surveyed – Not Detected				Ceiling, Walls and floor solid construction. Modern electrics and equipment throughout.				Yes	
10593	ACTIVE	J	N115-00-1/971	Void - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10594	ACTIVE	J	N115-00-1/TA1	Tenancy - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2845	ACTIVE	J	N115-00-1/TA1	Tenancy - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10595	ACTIVE	J	N115-00-1/TA2	Tenancy - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1958	ACTIVE	J	N115-00-1/TA2	Tenancy - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10596	ACTIVE	J	N115-00-1/TA3	Tenancy - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1959	ACTIVE	J	N115-00-1/TA3	Tenancy - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10597	ACTIVE	J	N115-00-2/071	Circulation Area - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1960	ACTIVE	J	N115-00-2/071	Circulation Area - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10598	ACTIVE	J	N115-00-2/072	Circulation Area - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2927	ACTIVE	J	N115-00-2/072	Circulation Area - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10599	ACTIVE	J	N115-00-2/073	Circulation Area - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2421	ACTIVE	J	N115-00-2/073	Circulation Area - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10600	ACTIVE	J	N115-00-2/074	Circulation Area - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2512	ACTIVE	J	N115-00-2/074	Circulation Area - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10601	ACTIVE	J	N115-00-2/075	Circulation Area - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2846	ACTIVE	J	N115-00-2/075	Circulation Area - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10602	ACTIVE	J	N115-00-2/076	Circulation Area - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1961	ACTIVE	J	N115-00-2/076	Circulation Area - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10603	ACTIVE	J	N115-00-2/081	Circulation Area - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1962	ACTIVE	J	N115-00-2/081	Circulation Area - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected				Cavity behind Facia Panels, Circulating Area, towards over bridge 2/639.					
10604	ACTIVE	J	N115-00-2/082	Circulation Area - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2380	ACTIVE	J	N115-00-2/082	Circulation Area - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	Known				7 x cement sleeves, under manhole bottom of escalator 7&8 No access into floor ducts during 2024 re-inspection. lifting equipment required.		7			yes
2847	ACTIVE	J	N115-00-2/082	Circulation Area - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	Known				4x Ducts under manhole into 2/202 x2 ducts No access into floor ducts during 2024 re-inspection. lifting equipment required.		6			yes
1963	ACTIVE	J	N115-00-2/082/CLG-01	Ceiling: Suspended - 1 - Circulation Area - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Contain supalux boards behind fascia					
2313	ACTIVE	J	N115-00-2/082/CLG-01 80836244	Ceiling: Suspended - 1 - Circulation Area - Station Building - Waterloo Stn Ceiling: Suspended	Void	Asbestos	No Access: Presumed				No access above ceiling				Yes	



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10605	ACTIVE	J	N115-00-2/083	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1964	ACTIVE	J	N115-00-2/083	Lobby - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10606	ACTIVE	J	N115-00-2/084	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1965	ACTIVE	J	N115-00-2/084	Lobby - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10607	ACTIVE	J	N115-00-2/085	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1966	ACTIVE	J	N115-00-2/085	Lobby - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10608	ACTIVE	J	N115-00-2/121	Platform Invert - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1967	ACTIVE	J	N115-00-2/121	Platform Invert - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10609	ACTIVE	J	N115-00-2/161	LMC - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2869	ACTIVE	J	N115-00-2/161	LMC - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	Known				Undercroft - 10no Cable Ducts		10			
45394	ACTIVE	J	N115-00-2/161	LMC - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	Known				LMC Undercroft - 10x cement ducts to wall at cable exit point		10		N	N
45393	ACTIVE	J	N115-00-2/161	LMC - Station Building - Waterloo Stn	Cable: Sheath	Asbestos	No Access: Presumed				LMC 7&8 Undercroft - 1x40mm Cable	40	1		N	N
2049	ACTIVE	J	N115-00-2/161	LMC - Station Building - Waterloo Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Rings, Concrete sealed, Presumed caulking behind					
45395	ACTIVE	J	N115-00-2/161	LMC - Station Building - Waterloo Stn	Cable: Sheath	Asbestos	Known				LMC Undercroft - 1x50m braided cable to cement duct (1no)	50	1		N	N
1970	ACTIVE	J	N115-00-2/161	LMC - Station Building - Waterloo Stn	Cable: Sheath	Asbestos	Known				Undercroft - 60mm Cable		1			
2051	ACTIVE	J	N115-00-2/161	LMC - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	Known				Undercroft - 5no Cable Ducts		5			
2047	ACTIVE	J	N115-00-2/161	LMC - Station Building - Waterloo Stn	Cable: Sheath	Asbestos	Known				Undercroft - 40mm Cable		1			
2048	ACTIVE	J	N115-00-2/161	LMC - Station Building - Waterloo Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Circuit Breakers		2			



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2050	ACTIVE	J	N115-00-2/161	LMC - Station Building - Waterloo Stn	Lead/Leading	Lead Paint/Lead	Known				Girder - Red Based Paint					
1969	ACTIVE	J	N115-00-2/161/CLG-01	Ceiling: Solid - 1 - LMC - Station Building - Waterloo Stn	Void	Asbestos	No Access: Presumed				No access above Cellactite Sheeting				Yes	
1968	ACTIVE	J	N115-00-2/161/CLG-01	Ceiling: Solid - 1 - LMC - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Supalux Boarding					
2848	ACTIVE	J	N115-00-2/161/CLG-01 80839722	Ceiling: Solid - 1 - LMC - Station Building - Waterloo Stn Ceiling: Solid	Cellactite Sheeting	Asbestos	Known				Cellactite Sheeting					
10610	ACTIVE	J	N115-00-2/162	LMC - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2317	ACTIVE	J	N115-00-2/162	LMC - Station Building - Waterloo Stn	Caulking	Asbestos	Known				Tunnel Rings, Concrete sealed, confirmed caulking behind rings 2,6&10					
10611	ACTIVE	J	N115-00-2/163	LMC - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2052	ACTIVE	J	N115-00-2/163	LMC - Station Building - Waterloo Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Rings, Concrete sealed, Presumed caulking behind					
10612	ACTIVE	J	N115-00-2/164	LMC - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2053	ACTIVE	J	N115-00-2/164	LMC - Station Building - Waterloo Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Rings, Concrete sealed, Presumed caulking behind					
2054	ACTIVE	J	N115-00-2/164/CLG-01	Ceiling: Solid - 1 - LMC - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
10613	ACTIVE	J	N115-00-2/165	LMC - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2870	ACTIVE	J	N115-00-2/165	LMC - Station Building - Waterloo Stn	Caulking	Asbestos	Strongly Presumed				Tunnel Rings, Concrete sealed, Presumed caulking behind					
10614	ACTIVE	J	N115-00-2/201	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2057	ACTIVE	J	N115-00-2/201	Passage - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	Known				Ducts going into room 2/791 No access into floor ducts during 2024 re-inspection. lifting equipment required.					
2426	ACTIVE	J	N115-00-2/201	Passage - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	Known				Ducts into 2/082 - 2x 100mm No access into floor ducts during 2024 re-inspection. lifting equipment required.		2			
2055	ACTIVE	J	N115-00-2/201/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected				Metal work & Solid Concrete all cables - PVC				Yes	



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2056	ACTIVE	J	N115-00-2/201/FLR-01	Floor - 1 - Passage - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected				Manholes - Ducts New Bitumen & PVC Cables					yes
10615	ACTIVE	J	N115-00-2/202	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2058	ACTIVE	J	N115-00-2/202	Passage - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10616	ACTIVE	J	N115-00-2/203	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2388	ACTIVE	J	N115-00-2/203	Passage - Station Building - Waterloo Stn	No Access	Asbestos	No Access: Presumed				No access above and below passage					
10617	ACTIVE	J	N115-00-2/204	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2059	ACTIVE	J	N115-00-2/204	Passage - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	Known				Cable ducts No access into floor ducts during 2024 re-inspection. lifting equipment required.		12			
45402	ACTIVE	J	N115-00-2/204	Passage - Station Building - Waterloo Stn	Cable: Sheath	Asbestos	Known				1x50m braided cable to 1 duct in passage manhole No access into floor ducts during 2024 re-inspection. lifting equipment required.	50	1		N	N
45401	ACTIVE	J	N115-00-2/204	Passage - Station Building - Waterloo Stn		Asbestos	Not Found during Inspection				12x Cable sleeves		12		N	N
10618	ACTIVE	J	N115-00-2/205	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2871	ACTIVE	J	N115-00-2/205	Passage - Station Building - Waterloo Stn	No Access	Asbestos	No Access: Presumed				No access above false ceiling					
10619	ACTIVE	J	N115-00-2/206	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2515	ACTIVE	J	N115-00-2/206/CLG-01	Ceiling: Suspended - 1 - Passage - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected				Trunking metal all cables PVC, ceiling Concrete				Yes	
10620	ACTIVE	J	N115-00-2/207	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2060	ACTIVE	J	N115-00-2/207	Passage - Station Building - Waterloo Stn	Void	Asbestos	No Access: Presumed				Cable Trunking					
10621	ACTIVE	J	N115-00-2/211	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2061	ACTIVE	J	N115-00-2/211	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10622	ACTIVE	J	N115-00-2/212	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2062	ACTIVE	J	N115-00-2/212	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10623	ACTIVE	J	N115-00-2/213	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2872	ACTIVE	J	N115-00-2/213	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10624	ACTIVE	J	N115-00-2/214	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2929	ACTIVE	J	N115-00-2/214	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10625	ACTIVE	J	N115-00-2/236	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2064	ACTIVE	J	N115-00-2/236	Lobby - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	No Access: Presumed				Ducts top of stairs 2/606		8			
45387	ACTIVE	J	N115-00-2/236	Lobby - Station Building - Waterloo Stn	Cable Duct: Other	Asbestos	Not Found during Inspection				8x Ducts top of stairs 2/606		8		N	N
2063	ACTIVE	J	N115-00-2/236	Lobby - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Panel above Door					
10626	ACTIVE	J	N115-00-2/237	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
42997	ACTIVE	J	N115-00-2/237	Passage - Station Building - Waterloo Stn	Other Boarding	Asbestos	Known				Supalux ceiling panels on metal framework 6m2 to suspended ceiling - No safe access during 2024 re-inspection.			R524326		
2065	ACTIVE	J	N115-00-2/237	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
42998	ACTIVE	J	N115-00-2/237	Passage - Station Building - Waterloo Stn		Asbestos	Room: Not Surveyed – Asbestos Presumed				MMMF insulation - loose throughout In cable management system to ceiling					
43000	ACTIVE	J	N115-00-2/237/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Waterloo Stn	Caulking	Asbestos	Room: Not Surveyed – Asbestos Presumed				Metal corrugated on concrete on metal tunnel rings to ceiling in false ceiling			R524326		N
43001	ACTIVE	J	N115-00-2/237/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Waterloo Stn	Other Boarding	Asbestos	Room: Not Surveyed – Asbestos Presumed				Plaster with hessian			R524326		N



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
43002	ACTIVE	J	N115-00-2/237/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Waterloo Stn		Asbestos	Room: Not Surveyed – Asbestos Presumed				Plaster on wire mesh			R524326		N
42999	ACTIVE	J	N115-00-2/237/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Waterloo Stn		Asbestos	Room: Not Surveyed – Asbestos Presumed				Grey Mastic throughout to metal A/C ductwork to wall 3 and ceiling			R524326		N
42995	ACTIVE	J	N115-00-2/237/WAL-003	Wall: Internal - 3 - Passage - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Room: Not Surveyed – Asbestos Presumed				Supalux panel 1/4 m2 to wall 3 above fire junction box			R524326	N	N
42994	ACTIVE	J	N115-00-2/237/WAL-003	Wall: Internal - 3 - Passage - Station Building - Waterloo Stn	Cable Duct: Other	Asbestos	Room: Not Surveyed – Asbestos Presumed				A/C metal ductwork - MMMF insulation to wall 3			R524326	N	N
10627	ACTIVE	J	N115-00-2/256	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2066	ACTIVE	J	N115-00-2/256	Lobby - Station Building - Waterloo Stn	Isolator Switches	Asbestos	Strongly Presumed				Switches (Possibly Duplicate item)					
45388	ACTIVE	J	N115-00-2/256	Lobby - Station Building - Waterloo Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Iron clad isolators - x 1 CFS to Wall 8 - SP Asbestos Materials Within		1		N	N
2873	ACTIVE	J	N115-00-2/256/WAL-002 80839780	Wall: Internal - 2 - Lobby - Station Building - Waterloo Stn Wall: Internal	Cable Ducts: Cement	Asbestos	Known				Cable ducts to wall 5		4			
10628	ACTIVE	J	N115-00-2/264	Platform 4 - Southbound Local - Bakerloo Line - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45397	ACTIVE	J	N115-00-2/264	Platform 4 - Southbound Local - Bakerloo Line - Station Building - Waterloo Stn	Caulking	Asbestos	No Access: Presumed				Through 2nd Hatch - Caulking - No access within platform inverts during 2024 re-inspection. Confined Space.				N	N
45398	ACTIVE	J	N115-00-2/264	Platform 4 - Southbound Local - Bakerloo Line - Station Building - Waterloo Stn	Cable: Sheath	Asbestos	No Access: Presumed				Through 5th Hatch, at end near 2/667 - 1x 80mm Cable (From platform side 40m towards middle arch) - No access within platform inverts during 2024 re-inspection. Confined Space.	80	1		N	N
2067	ACTIVE	J	N115-00-2/264	Platform 4 - Southbound Local - Bakerloo Line - Station Building - Waterloo Stn	Cable: Sheath	Asbestos	Known				0.20mm Cable - No access within platform inverts during 2024 re-inspection. Confined Space.		1			
2318	ACTIVE	J	N115-00-2/264	Platform 4 - Southbound Local - Bakerloo Line - Station Building - Waterloo Stn	Caulking	Asbestos	Surveyed – Not Detected				(Hatch 5)					yes
45396	ACTIVE	J	N115-00-2/264	Platform 4 - Southbound Local - Bakerloo Line - Station Building - Waterloo Stn	Caulking	Asbestos	No Access: Presumed				Southbound Platform 4 Invert, by 2/761 through 1st hatch - Caulking - No access within platform inverts during 2024 re-inspection. Confined Space.				N	N
2389	ACTIVE	J	N115-00-2/264	Platform 4 - Southbound Local - Bakerloo Line - Station Building - Waterloo Stn	Cable: Sheath	Asbestos	Strongly Presumed				80mm (Hatch 4 & 5) - No access within platform inverts during 2024 re-inspection. Confined Space.		1			



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2070	ACTIVE	J	N115-00-2/264	Platform 4 - Southbound Local - Bakerloo Line - Station Building - Waterloo Stn	Cable: Wrap	Asbestos	Surveyed – Not Detected				(Hatch 5)		2			
2874	ACTIVE	J	N115-00-2/264/FLR-01 80837242	Floor - 1 - Platform 4 - Station Building - Waterloo Stn Floor	Cable Ducts: Cement	Asbestos	Strongly Presumed				All Cable Ducts / Sleeves in invert - No access within platform inverts during 2024 re-inspection. Confined Space.					yes
2068	ACTIVE	J	N115-00-2/264/FLR-01	Floor - 1 - Platform 4 - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected				Cable sleeves -13x Head wall plastic/ 1x ceramic, cables - rubber, Wrap - Non asbestos - (Around Block platform side near head wall), Cable ducts - New Bitumen - Non asbestos					yes
2069	ACTIVE	J	N115-00-2/264/FLR-01 80837242	Floor - 1 - Platform 4 - Station Building - Waterloo Stn Floor	Caulking	Asbestos	Strongly Presumed				Within Invert (Hatches 1 & 2) - No access within platform inverts during 2024 re-inspection. Confined Space.				YES	
10629	ACTIVE	J	N115-00-2/265	Platform 26 - Arrival - Waterloo & City Line - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2071	ACTIVE	J	N115-00-2/265	Platform 26 - Arrival - Waterloo & City Line - Station Building - Waterloo Stn	No Access	Asbestos	No Access: Presumed				No access above false ceiling					
10630	ACTIVE	J	N115-00-2/266	Platform 25 - Departure - Waterloo & City Line - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2072	ACTIVE	J	N115-00-2/266	Platform 25 - Departure - Waterloo & City Line - Station Building - Waterloo Stn	No Access	Asbestos	No Access: Presumed				No access above false ceiling					
10631	ACTIVE	J	N115-00-2/291	Office - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2427	ACTIVE	J	N115-00-2/291	Office - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				Acoustic panel under Sink unit non asbestos		1			
2755	ACTIVE	J	N115-00-2/291/CLG-01 80836691	Ceiling: Solid - 1 - Office - Station Building - Waterloo Stn Ceiling: Solid	Void	Asbestos	Surveyed – Not Detected				Ceiling fixed panels identified as plasterboard to fixed timber within void.				Yes	
10632	ACTIVE	J	N115-00-2/292	Disused Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2184	ACTIVE	J	N115-00-2/292	Disused Room - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				Acoustic panel under Sink unit non asbestos		1			
2185	ACTIVE	J	N115-00-2/292/CLG-01 80836698	Ceiling: Solid - 1 - Disused Room - Station Building - Waterloo Stn Ceiling: Solid	Void	Asbestos	No Access: Presumed				No access above ceiling				Yes	
10633	ACTIVE	J	N115-00-2/331	Mess Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2186	ACTIVE	J	N115-00-2/331	Mess Room - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10634	ACTIVE	J	N115-00-2/341	Disused Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2435	INACTIVE	J	N115-00-2/341/CLG-01 80836304	Ceiling: Solid - 1 - Disused Room - Station Building - Waterloo Stn Ceiling: Solid	Void	Asbestos	No Access: Presumed				Not found				Yes	
10635	ACTIVE	J	N115-00-2/381	Store - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2188	ACTIVE	J	N115-00-2/381	Store - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Top Wall Panels					
2187	ACTIVE	J	N115-00-2/381/CLG-01 80836712	Ceiling: Solid - 1 - Store - Station Building - Waterloo Stn Ceiling: Solid	Void	Asbestos	Surveyed – Not Detected				Solid brick arched throughout				Yes	
10636	ACTIVE	J	N115-00-2/391	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2756	ACTIVE	J	N115-00-2/391	Switch Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Ceiling, Wall and low level boxing panels identified as Supalux boarding. Solid floor with modern cable ducts. Modern electrical equipment throughout.					
10637	ACTIVE	J	N115-00-2/406	Store - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2271	ACTIVE	J	N115-00-2/406/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Waterloo Stn	Other Boarding	Asbestos	Surveyed – Not Detected									
2189	INACTIVE	J	N115-00-2/406/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Waterloo Stn	Void	Asbestos	No Access: Presumed								Yes	
10638	ACTIVE	J	N115-00-2/407	Disused Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2190	ACTIVE	J	N115-00-2/407	Disused Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10639	ACTIVE	J	N115-00-2/411	Store - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2757	ACTIVE	J	N115-00-2/411/CLG-01 80836320	Ceiling: Solid - 1 - Store - Station Building - Waterloo Stn Ceiling: Solid	Void	Asbestos	Surveyed – Not Detected								Yes	
2191	ACTIVE	J	N115-00-2/411/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Waterloo Stn	Other Boarding	Asbestos	Surveyed – Not Detected									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10640	ACTIVE	J	N115-00-2/413	Store - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2192	ACTIVE	J	N115-00-2/413	Store - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Ceiling and Wall panels identified as Supalux boarding. Solid floor with modern cable duct. Modern electrical equipment throughout.					
10641	ACTIVE	J	N115-00-2/414	Disused Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2193	ACTIVE	J	N115-00-2/414	Disused Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Ceiling fixed panels identified as Supalux boarding. Solid Walls and Floor construction.					
10642	ACTIVE	J	N115-00-2/416	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2194	ACTIVE	J	N115-00-2/416	Lobby - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10643	ACTIVE	J	N115-00-2/417	Toilet: Unisex - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2195	ACTIVE	J	N115-00-2/417	Toilet: Unisex - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10644	ACTIVE	J	N115-00-2/546	Store - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2323	ACTIVE	J	N115-00-2/546/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				End of arrivals platform					
2272	ACTIVE	J	N115-00-2/546/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Waterloo Stn	Other Boarding	Asbestos	Surveyed – Not Detected				False ceiling boxing - new vermiculite cladding					
2197	ACTIVE	J	N115-00-2/546/CLG-01	Ceiling: Solid - 1 - Store - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected								Yes	
2198	ACTIVE	J	N115-00-2/546/FLR-01 80836779	Floor - 1 - Store - Station Building - Waterloo Stn Floor	Void	Asbestos	Surveyed – Not Detected				Ceiling fixed panels identified as plasterboard. Solid Walls and Floor construction. Timber constructed cabinet. Modern electrical equipment.					yes
10645	ACTIVE	J	N115-00-2/601	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2759	ACTIVE	J	N115-00-2/601	Stairs: Linear - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10646	ACTIVE	J	N115-00-2/602	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2199	ACTIVE	J	N115-00-2/602	Stairs: Linear - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10647	ACTIVE	J	N115-00-2/603	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2200	ACTIVE	J	N115-00-2/603	Stairs: Linear - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	Known				Ducts into 2/082 - 2x 100mm No access into floor ducts during 2024 re-inspection. lifting equipment required.		2			
10648	ACTIVE	J	N115-00-2/604	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2521	ACTIVE	J	N115-00-2/604	Stairs: Linear - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10649	ACTIVE	J	N115-00-2/605	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2201	ACTIVE	J	N115-00-2/605	Stairs: Linear - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10650	ACTIVE	J	N115-00-2/606	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2202	ACTIVE	J	N115-00-2/606	Stairs: Linear - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10651	ACTIVE	J	N115-00-2/607	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2760	ACTIVE	J	N115-00-2/607	Stairs: Linear - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10652	ACTIVE	J	N115-00-2/608	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2203	ACTIVE	J	N115-00-2/608	Stairs: Linear - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10653	ACTIVE	J	N115-00-2/609	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2935	ACTIVE	J	N115-00-2/609	Stairs: Linear - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2204	ACTIVE	J	N115-00-2/609/CLG-01	Ceiling: Suspended - 1 - Linear Stairs - Station Building - Waterloo Stn	Other Boarding	Asbestos	Surveyed – Not Detected									
2205	ACTIVE	J	N115-00-2/636	Overbridge - Station Building - Waterloo Stn	No Access	Asbestos	No Access: Presumed				No access above false ceiling				Y	



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2779	ACTIVE	J	N115-00-2/637	Overbridge - Station Building - Waterloo Stn	No Access	Asbestos	No Access: Presumed				Not access above false ceiling				Y	
2761	ACTIVE	J	N115-00-2/637	Overbridge - Station Building - Waterloo Stn	Lead/Leading	Lead Paint/Lead	Known				Over bridge- Black oil based - 4sqm					
2206	ACTIVE	J	N115-00-2/638	Overbridge - Station Building - Waterloo Stn	No Access	Asbestos	No Access: Presumed				No access above false ceiling				Y	
2207	ACTIVE	J	N115-00-2/639	Overbridge - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10654	ACTIVE	J	N115-00-2/661	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2208	ACTIVE	J	N115-00-2/661	Switch Room - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10655	ACTIVE	J	N115-00-2/662	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2762	ACTIVE	J	N115-00-2/662	Switch Room - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10656	ACTIVE	J	N115-00-2/663	Service Riser - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2210	ACTIVE	J	N115-00-2/663	Service Riser - Station Building - Waterloo Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse Box to Wall 2 - Asbestos materials within		1			
2209	ACTIVE	J	N115-00-2/663	Service Riser - Station Building - Waterloo Stn	Cable: Wrap	Asbestos	Surveyed – Not Detected				1 metre					
10657	ACTIVE	J	N115-00-2/664	Switch Cupboard - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2211	ACTIVE	J	N115-00-2/664	Switch Cupboard - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10658	ACTIVE	J	N115-00-2/665	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2273	ACTIVE	J	N115-00-2/665	Switch Room - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10659	ACTIVE	J	N115-00-2/666	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2763	ACTIVE	J	N115-00-2/666 80837104	Switch Room - Station Building - Waterloo Stn Ceiling: Solid	Isolator Switches	Asbestos	Strongly Presumed				Combination Fuse Switches - Asbestos materials within		7		N	



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2212	ACTIVE	J	N115-00-2/666/FLR-01 80837105	Floor - 1 - Switch Room - Station Building - Waterloo Stn Floor	Void	Asbestos	No Access: Presumed				No access below floor (man hole covers 2/662)					yes
10660	ACTIVE	J	N115-00-2/667	Switch Cupboard - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2213	ACTIVE	J	N115-00-2/667	Switch Cupboard - Station Building - Waterloo Stn	Isolator Switches	Asbestos	Removed				Switches		7			
10661	ACTIVE	J	N115-00-2/683	Switch Cupboard - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2214	ACTIVE	J	N115-00-2/683	Switch Cupboard - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10662	ACTIVE	J	N115-00-2/712	Disused Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2764	ACTIVE	J	N115-00-2/712	Disused Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Ceiling, Walls and Floor construction solid. Timber backing panel to ventilation fan.					
10663	ACTIVE	J	N115-00-2/713	IMR - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2215	ACTIVE	J	N115-00-2/713	IMR - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not surveyed - new					
10664	ACTIVE	J	N115-00-2/714	Disused Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2274	ACTIVE	J	N115-00-2/714	Disused Room - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10665	ACTIVE	J	N115-00-2/715	SER - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2216	ACTIVE	J	N115-00-2/715	SER - Station Building - Waterloo Stn	Caulking	Asbestos	Presumed				2/162 Presumed to contain caulking - therefore it is possible that 2/715 could contain caulking Behind block walls					
10666	ACTIVE	J	N115-00-2/731	CER - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2217	ACTIVE	J	N115-00-2/731/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2765	ACTIVE	J	N115-00-2/731/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Waterloo Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling - Not Surveyed				Yes	



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2219	ACTIVE	J	N115-00-2/731/FLR-01	Floor - 1 - CER - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	Removed				Cables sleeves on floor & Wall 1 Not accessed during 2020 re-inspection. key not available with station supervisor		13			
2218	ACTIVE	J	N115-00-2/731/WAL-001	Wall: Internal - 1 - CER - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	Removed				Cables sleeves on floor & Wall 1 Not accessed during 2020 re-inspection. key not available with station supervisor		13			
10667	ACTIVE	J	N115-00-2/732	CER - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2220	ACTIVE	J	N115-00-2/732	CER - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10668	ACTIVE	J	N115-00-2/733	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2766	ACTIVE	J	N115-00-2/733/CLG-01	Ceiling: Solid - 1 - Passage - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected				Ceiling by wall 1&3					
2221	ACTIVE	J	N115-00-2/733/WAL-001	Wall: Internal - 1 - Passage - Station Building - Waterloo Stn	Caulking	Asbestos	Strongly Presumed				Caulking between Tunnel Ring Flanges					
2275	INACTIVE	J	N115-00-2/733/WAL-003	Wall: Internal - 3 - Passage - Station Building - Waterloo Stn	Caulking	Asbestos	Strongly Presumed				Caulking between Tunnel Ring Flanges Duplicate item					
2222	ACTIVE	J	N115-00-2/733/WAL-003	Wall: Internal - 3 - Passage - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	Known				Cable Sleeves / Ducts					
10669	ACTIVE	J	N115-00-2/734	CER - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2223	ACTIVE	J	N115-00-2/734	CER - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10670	ACTIVE	J	N115-00-2/751	CER - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2224	ACTIVE	J	N115-00-2/751/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2225	ACTIVE	J	N115-00-2/751/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Waterloo Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling - Not Surveyed				Yes	
10671	ACTIVE	J	N115-00-2/761	Equipment Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2227	ACTIVE	J	N115-00-2/761	Equipment Room - Station Building - Waterloo Stn	Cable: Sheath	Asbestos	No Access: Presumed				2mm Cable on Floodgate		1			



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
45384	ACTIVE	J	N115-00-2/761	Equipment Room - Station Building - Waterloo Stn	Cable: Sheath	Asbestos	Not Found during Inspection				1x2mm Cable on floodgate	2	1		N	N
2226	ACTIVE	J	N115-00-2/761	Equipment Room - Station Building - Waterloo Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Floodgate Equipment - Asbestos materials within					
2522	ACTIVE	J	N115-00-2/761/ WAL-002 80837123	Wall: Internal - 2 - Equipment Room - Station Building - Waterloo Stn Wall: Internal	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse boxes - Asbestos materials within		4			
2767	INACTIVE	J	N115-00-2/761/ WAL-004	Wall: Internal - 4 - Equipment Room - Station Building - Waterloo Stn	Westing house Boxes	Asbestos	Strongly Presumed				Insulation materials within No electrician on site during 2020 reinspection to open boxes for inspection - therefore cannot score material within		4			
2436	ACTIVE	J	N115-00-2/761/ WAL-004 80837125	Wall: Internal - 4 - Equipment Room - Station Building - Waterloo Stn Wall: Internal	Cable: Sheath	Asbestos	Strongly Presumed				2x 0.01m ² Cable within switch box on Wall 4		2			
10672	ACTIVE	J	N115-00-2/786	Service Riser - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2228	ACTIVE	J	N115-00-2/786	Service Riser - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2780	ACTIVE	J	N115-00-2/791	Vent Shaft - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	Not Found during Inspection				Cable ducts Not located during 2020 re-inspection.		2			
2230	ACTIVE	J	N115-00-2/791	Vent Shaft - Station Building - Waterloo Stn	Caulking	Asbestos	Sampled – Not Detected									
2229	ACTIVE	J	N115-00-2/791	Vent Shaft - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	Sampled – Not Detected									
2231	ACTIVE	J	N115-00-2/791	Vent Shaft - Station Building - Waterloo Stn	Lead/Leading	Lead Paint/Lead	Known				Wall panels at entrance - Green matt					
2768	ACTIVE	J	N115-00-2/791	Vent Shaft - Station Building - Waterloo Stn	Lead/Leading	Lead Paint/Lead	Known				Entrance & exit to Lift, above entrance - Cream gloss					
2324	ACTIVE	J	N115-00-2/791/ CLG-01	Ceiling: Solid - 1 - Vent Shaft - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
45382	ACTIVE	J	N115-00-2/792	Vent Shaft - Station Building - Waterloo Stn	Cable Duct: Other	Asbestos	Not Found during Inspection				Cable duct outside - Cable Duct				N	N
2235	ACTIVE	J	N115-00-2/792	Vent Shaft - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	No Access: Presumed				Cable ducts No access below floor plates		1			Y
2232	ACTIVE	J	N115-00-2/792	Vent Shaft - Station Building - Waterloo Stn	Caulking	Asbestos	Surveyed – Not Detected									
2234	ACTIVE	J	N115-00-2/792	Vent Shaft - Station Building - Waterloo Stn	Lead/Leading	Lead Paint/Lead	Known				Entrance & exit to Lift, above entrance - Cream gloss					



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2233	ACTIVE	J	N115-00-2/792	Vent Shaft - Station Building - Waterloo Stn	Lead/Leading	Lead Paint/Lead	Known				Wall panels at entrance - Green matt					
10673	ACTIVE	J	N115-00-2/793	Air Plenum - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2428	ACTIVE	J	N115-00-2/793	Air Plenum - Station Building - Waterloo Stn	Durasteel	Asbestos	Not Found during Inspection				Durasteel panels upper level Durasteel not located during 2020 re-inspection. possibly removed.					
2276	ACTIVE	J	N115-00-2/793	Air Plenum - Station Building - Waterloo Stn	Gasket :Pipework	Asbestos	Strongly Presumed				Pipe-work gaskets intermediate level					
2236	ACTIVE	J	N115-00-2/793	Air Plenum - Station Building - Waterloo Stn	Other Electrical Boxes	Asbestos	No Access: Presumed				Intermediate level - Tunnel cooling fan equipment - flash guards & gaskets - No access into area during 2024 re-inspection. Task lighting equipment required.					
45383	INACTIVE	J	N115-00-2/793	Air Plenum - Station Building - Waterloo Stn		Asbestos	Strongly Presumed				Tunnel cooling fan equipment - flash guards & gaskets - Intermediate level				N	N
2769	ACTIVE	J	N115-00-2/793/FLR-01	Floor - 1 - Air Plenum - Station Building - Waterloo Stn	Cable Ducts: Bitumen	Asbestos	Strongly Presumed				Cable ducts on lower level floor		10			
10674	ACTIVE	J	N115-00-2/794	Air Relief Shaft - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45400	ACTIVE	J	N115-00-2/794	Air Relief Shaft - Station Building - Waterloo Stn		Asbestos	Not Found during Inspection				Middle Section - Paper lining within cooling fan starter <1 sqm				N	N
45399	ACTIVE	J	N115-00-2/794	Air Relief Shaft - Station Building - Waterloo Stn		Asbestos	Not Found during Inspection				Middle Section - Spark guards within cooling fan starter <1 sqm				N	N
2073	ACTIVE	J	N115-00-2/794	Air Relief Shaft - Station Building - Waterloo Stn	Caulking	Asbestos	Surveyed – Not Detected									
42516	ACTIVE	J	N115-00-2/794	Air Relief Shaft - Station Building - Waterloo Stn	Other Boarding	Asbestos	Sampled – Not Detected				Middle Section - 1 sqm floor within cooling fan starter	1		37773/004R	N	N
42514	ACTIVE	J	N115-00-2/794	Air Relief Shaft - Station Building - Waterloo Stn	Other Electrical Boxes	Asbestos	Sampled – Not Detected				Middle Section - <1 sqm Fuses from within cooling fan starter			37773/004R	N	N
42509	ACTIVE	J	N115-00-2/794	Air Relief Shaft - Station Building - Waterloo Stn	Gasket :Pipework	Asbestos	No Access: Presumed				Middle Section of Vent Shaft - <1 sqm Spark guards within Cooling Fan Starter - No access into area during 2024 re-inspection. Task lighting equipment required.			37773/004R	N	N
42513	ACTIVE	J	N115-00-2/794	Air Relief Shaft - Station Building - Waterloo Stn	Paper Asbestos	Asbestos	No Access: Presumed				Middle Section - <1 sqm Paper lining within cooling fan starter - No access into area during 2024 re-inspection. Task lighting equipment required.			37773/004R	N	N
42512	ACTIVE	J	N115-00-2/794	Air Relief Shaft - Station Building - Waterloo Stn	Other Boarding	Asbestos	Sampled – Not Detected				Middle Section - <1 sqm Bakelite type boarding within cooling fan starter			37773/004R	N	N
2074	ACTIVE	J	N115-00-2/794	Air Relief Shaft - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	Sampled – Not Detected									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
42515	ACTIVE	J	N115-00-2/794	Air Relief Shaft - Station Building - Waterloo Stn	Paper Asbestos	Asbestos	Sampled – Not Detected				Middle Section - <1 sqm Paper within Cooling Fan Starter			37773/004R	N	N
2875	ACTIVE	J	N115-00-2/794	Air Relief Shaft - Station Building - Waterloo Stn	Lead/Leading	Lead Paint/Lead	Known				Fan - Blue oil based paint - 60sqm - No access into area during 2024 re-inspection. Task lighting equipment required.					
10675	ACTIVE	J	N115-00-2/903	Store - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2075	ACTIVE	J	N115-00-2/903	Store - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10676	ACTIVE	J	N115-00-2/951	Service Riser - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2076	ACTIVE	J	N115-00-2/951	Service Riser - Station Building - Waterloo Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse break box		1			
10677	ACTIVE	J	N115-00-2/972	Void - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10678	ACTIVE	J	N115-00-3/081	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2077	ACTIVE	J	N115-00-3/081	Lobby - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10679	ACTIVE	J	N115-00-3/121	Platform Invert - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2078	ACTIVE	J	N115-00-3/121	Platform Invert - Station Building - Waterloo Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed New Room invert - No access within platform inverts during 2024 re-inspection. Confined Space.					
10680	ACTIVE	J	N115-00-3/151	UMC - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2876	ACTIVE	J	N115-00-3/151	UMC - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10681	ACTIVE	J	N115-00-3/152	UMC - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2079	ACTIVE	J	N115-00-3/152	UMC - Station Building - Waterloo Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Rings - No Caulking					
10682	ACTIVE	J	N115-00-3/153	LMC - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2390	ACTIVE	J	N115-00-3/153	LMC - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10683	ACTIVE	J	N115-00-3/156	UMC - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10684	ACTIVE	J	N115-00-3/161	LMC - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2080	ACTIVE	J	N115-00-3/161	LMC - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10685	ACTIVE	J	N115-00-3/162	LMC - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2516	ACTIVE	J	N115-00-3/162	LMC - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10686	ACTIVE	J	N115-00-3/163	UMC - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2081	ACTIVE	J	N115-00-3/163	UMC - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
2877	ACTIVE	J	N115-00-3/171	Escalator Incline - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
2082	ACTIVE	J	N115-00-3/172	Escalator Incline - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
2083	ACTIVE	J	N115-00-3/173	Escalator Incline - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10687	ACTIVE	J	N115-00-3/201	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2084	ACTIVE	J	N115-00-3/201	Passage - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10688	ACTIVE	J	N115-00-3/202	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2085	ACTIVE	J	N115-00-3/202	Passage - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	Known				Cable ducts No access into floor ducts during 2024 re-inspection.lifting equipment required.					
10689	ACTIVE	J	N115-00-3/203	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2391	ACTIVE	J	N115-00-3/203	Passage - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10690	ACTIVE	J	N115-00-3/204	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2878	ACTIVE	J	N115-00-3/204	Passage - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	Known				Cable ducts No access into floor duct during 2024 re-inspection. lifting equipment required.		12			
10691	ACTIVE	J	N115-00-3/205	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2086	ACTIVE	J	N115-00-3/205	Passage - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10692	ACTIVE	J	N115-00-3/206	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2087	ACTIVE	J	N115-00-3/206	Passage - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10693	ACTIVE	J	N115-00-3/207	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2088	ACTIVE	J	N115-00-3/207	Passage - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	Known				Cable ducts No access into floor duct during 2024 re-inspection. lifting equipment required.		8			
2429	ACTIVE	J	N115-00-3/207/ FLR-01 80836875	Floor - 1 - Passage - Station Building - Waterloo Stn Floor	Debris: Cement	Asbestos	Known				Broken ducts & debris within manhole No access into floor duct during 2024 re-inspection. lifting equipment required.					yes
10694	ACTIVE	J	N115-00-3/208	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2728	ACTIVE	J	N115-00-3/208	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10695	ACTIVE	J	N115-00-3/209	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2089	ACTIVE	J	N115-00-3/209	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10696	ACTIVE	J	N115-00-3/210	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2392	ACTIVE	J	N115-00-3/210	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10697	ACTIVE	J	N115-00-3/211	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2789	ACTIVE	J	N115-00-3/211	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10698	ACTIVE	J	N115-00-3/261	Platform 1 - Northbound Local - Northern Line - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
69514	ACTIVE	J	N115-00-3/261	Platform 1 - Northbound Local - Northern Line - Station Building - Waterloo Stn	Cable Sheath	Asbestos	Known				Invert - White braided cable - total 1 no -To platform wall. No access, engineering hours required		1	R709003		
69517	ACTIVE	J	N115-00-3/261	Platform 1 - Northbound Local - Northern Line - Station Building - Waterloo Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen ducts - total 2 no - To track wall.		2	R709003		Y
69513	ACTIVE	J	N115-00-3/261	Platform 1 - Northbound Local - Northern Line - Station Building - Waterloo Stn	Cable Sheath	Asbestos	Known				Invert - Green and white braided cables - total 5 no - Throughout. No access, engineering hours required		5	R709003		
69516	ACTIVE	J	N115-00-3/261	Platform 1 - Northbound Local - Northern Line - Station Building - Waterloo Stn	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Invert - Grout on wood packing - To tunnel rings.			R709003		
69515	ACTIVE	J	N115-00-3/261	Platform 1 - Northbound Local - Northern Line - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	Known				Invert - Cement ducts To platform wall - No access within platform inverts during 2024 re-inspection. Confined Space.		6	R709003		Y
69512	ACTIVE	J	N115-00-3/261	Platform 1 - Northbound Local - Northern Line - Station Building - Waterloo Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen ducts - total 12 no - To track wall.		12	R709003		Y
2905	ACTIVE	J	N115-00-3/261/ FLR-01 80837032	Floor - 1 - Platform 1 - Station Building - Waterloo Stn Floor	Cable Ducts: Cement	Asbestos	Known				Platform Invert Cable sleeves 14m down into cross passage - No access within platform inverts during 2024 re-inspection. Confined Space.					yes
2090	ACTIVE	J	N115-00-3/261/ FLR-01	Floor - 1 - Platform 1 - Station Building - Waterloo Stn	Cable: Wrap	Asbestos	Surveyed – Not Detected				nr3/714 - Cable - plastic with wrap around rubber - Non asbestos (Pit side)					yes
2091	ACTIVE	J	N115-00-3/261/ FLR-01	Floor - 1 - Platform 1 - Station Building - Waterloo Stn	Cable: Wrap	Asbestos	Surveyed – Not Detected				Hessian					yes
2729	ACTIVE	J	N115-00-3/261/ FLR-01	Floor - 1 - Platform 1 - Station Building - Waterloo Stn	Caulking	Asbestos	Surveyed – Not Detected				Tunnel Ring Flanges					yes
2092	ACTIVE	J	N115-00-3/261/ FLR-01 80837032	Floor - 1 - Platform 1 - Station Building - Waterloo Stn Floor	Cable: Sheath	Asbestos	Known				Platform Invert Various Asbestos Cables "Asbestos - K - 1x 20mm white cable, 1x 20mm white cable pit side, Platform side all asbestos (10m down) cables exit" - No access within platform inverts during 2024 re-inspection. Confined Space.					yes
10699	ACTIVE	J	N115-00-3/262	Platform 2 - Southbound Local - Northern Line - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
69506	ACTIVE	J	N115-00-3/262	Platform 2 - Southbound Local - Northern Line - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	Known				Invert - Cement ducts To platform wall - No access within platform inverts during 2024 re-inspection. Confined Space.		6	R709003		Y



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
69504	ACTIVE	J	N115-00-3/262	Platform 2 - Southbound Local - Northern Line - Station Building - Waterloo Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen ducts - total 7 no - To track wall.		7	R709003		Y
69505	ACTIVE	J	N115-00-3/262	Platform 2 - Southbound Local - Northern Line - Station Building - Waterloo Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen duct - total 1 no - To track wall.		1	R709003		Y
69511	ACTIVE	J	N115-00-3/262	Platform 2 - Southbound Local - Northern Line - Station Building - Waterloo Stn	Cable Ducts: Bitumen	Asbestos	Known				Invert - Bitumen ducts To ceiling - No access within platform inverts during 2024 re-inspection. Confined Space.		2	R709003		Y
69503	ACTIVE	J	N115-00-3/262	Platform 2 - Southbound Local - Northern Line - Station Building - Waterloo Stn	Cable Sheath	Asbestos	Known				Invert - Green/ white braided cables - total ~6 no - To platform wall 6 visible. No access, engineering hours required		6	R709003		
69502	ACTIVE	J	N115-00-3/262	Platform 2 - Southbound Local - Northern Line - Station Building - Waterloo Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen ducts - total 4 no - To track wall.		4	R709003		Y
69507	ACTIVE	J	N115-00-3/262	Platform 2 - Southbound Local - Northern Line - Station Building - Waterloo Stn	Debris: Other	Asbestos	Sampled – Not Detected				Invert - Firestop - total <1m2 - To ceiling of invert.	1		R709003		Y
69508	ACTIVE	J	N115-00-3/262	Platform 2 - Southbound Local - Northern Line - Station Building - Waterloo Stn	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Invert - Grout on wood packing - To tunnel rings.			R709003		
69510	ACTIVE	J	N115-00-3/262	Platform 2 - Southbound Local - Northern Line - Station Building - Waterloo Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen duct - total 1 no - To ceiling.		1	R709003		Y
69509	ACTIVE	J	N115-00-3/262	Platform 2 - Southbound Local - Northern Line - Station Building - Waterloo Stn	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Invert - Metal tunnel rings - Throughout.			R709003		
2093	ACTIVE	J	N115-00-3/262/ FLR-01 80837053	Floor - 1 - Platform 2 - Station Building - Waterloo Stn Floor	Cable Ducts: Cement	Asbestos	Known				Cable ducts within manhole halfway along platform - No access within platform inverts during 2024 re-inspection. Confined Space.					yes
2094	ACTIVE	J	N115-00-3/262/ FLR-01 80837053	Floor - 1 - Platform 2 - Station Building - Waterloo Stn Floor	Cable: Sheath	Asbestos	Known				Platform side cable run - Cables 5x 30mm/3x 40mm, 30 mm cables only run half the length of invert - drop from ceiling next to green cables, 40mm cables run for the length of invert. Two exit invert through ceiling to room above at end. All woven cables enter/exit into relay rooms above invert - No access within platform inverts during 2024 re-inspection. Confined Space.					yes
10700	ACTIVE	J	N115-00-3/263	Platform 3 - Northbound Local - Bakerloo Line - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
69528	ACTIVE	J	N115-00-3/263	Platform 3 - Northbound Local - Bakerloo Line - Station Building - Waterloo Stn	Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen coating - 3m2 - To electrical box at end wall.	3		R709004		Y



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
69529	ACTIVE	J	N115-00-3/263	Platform 3 - Northbound Local - Bakerloo Line - Station Building - Waterloo Stn	Cable: Wrap	Asbestos	Sampled – Not Detected				Invert - Woven packing - <1m2 - To top of electrical box.	1		R709004		Y
69533	ACTIVE	J	N115-00-3/263	Platform 3 - Northbound Local - Bakerloo Line - Station Building - Waterloo Stn	Debris: Cement	Asbestos	Known				Invert - Cement debris, 4m2 Loose to wall/ ledge of invert approx. 20m from south end manhole - No access within platform inverts during 2024 re-inspection. Confined Space.	4		R709004		Y
2730	ACTIVE	J	N115-00-3/263	Platform 3 - Northbound Local - Bakerloo Line - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
69530	ACTIVE	J	N115-00-3/263	Platform 3 - Northbound Local - Bakerloo Line - Station Building - Waterloo Stn	Other Electrical Boxes	Asbestos	Presumed				Invert - Materials within electrical box - total 1 no - To floor. No access, engineering hours required		1	R709004		
69531	ACTIVE	J	N115-00-3/263	Platform 3 - Northbound Local - Bakerloo Line - Station Building - Waterloo Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen ducts - total 7 no - To platform wall.		7	R709004		Y
69532	ACTIVE	J	N115-00-3/263	Platform 3 - Northbound Local - Bakerloo Line - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	Known				Invert - Cement ducts To platform wall - No access within platform inverts during 2024 re-inspection. Confined Space.		10	R709004		Y
69534	ACTIVE	J	N115-00-3/263	Platform 3 - Northbound Local - Bakerloo Line - Station Building - Waterloo Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen ducts - total 6 no - To track wall.		6	R709004		Y
69526	ACTIVE	J	N115-00-3/263	Platform 3 - Northbound Local - Bakerloo Line - Station Building - Waterloo Stn	Gasket :Pipework	Asbestos	Known				Invert - Gaskets Throughout pipework flanges and platform wall - No access within platform inverts during 2024 re-inspection. Confined Space.			R709004		Y
69527	ACTIVE	J	N115-00-3/263	Platform 3 - Northbound Local - Bakerloo Line - Station Building - Waterloo Stn	Cable Ducts: Bitumen	Asbestos	Presumed				Invert - Bitumen ducts To end wall - No access within platform inverts during 2024 re-inspection. Confined Space.		2	R709004		Y
2930	ACTIVE	J	N115-00-3/263/ FLR-01	Floor - 1 - Platform 3 - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	Surveyed – Not Detected				Cable ducts throughout Invert - Non asbestos					yes
10701	ACTIVE	J	N115-00-3/264	Platform 4 - Southbound Local - Bakerloo Line - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
69518	ACTIVE	J	N115-00-3/264	Platform 4 - Southbound Local - Bakerloo Line - Station Building - Waterloo Stn	Tunnel Ring Caulking	Asbestos	Sampled – Not Detected				Invert - Grout to tunnel rings - Throughout.			R709004		
69520	ACTIVE	J	N115-00-3/264	Platform 4 - Southbound Local - Bakerloo Line - Station Building - Waterloo Stn	Westinghouse Boxes	Asbestos	Presumed				Invert - Small Westinghouse box - total 1 no - To platform wall. No access, engineering hours required		1	R709004		
69521	ACTIVE	J	N115-00-3/264	Platform 4 - Southbound Local - Bakerloo Line - Station Building - Waterloo Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen ducts - total 2 no - To platform wall.		2	R709004		Y



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
69525	ACTIVE	J	N115-00-3/264	Platform 4 - Southbound Local - Bakerloo Line - Station Building - Waterloo Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen ducts - total 16 no - To platform wall.		16	R709004		Y
69523	ACTIVE	J	N115-00-3/264	Platform 4 - Southbound Local - Bakerloo Line - Station Building - Waterloo Stn	Cable Sheath	Asbestos	Known				Invert - White braided cable - total 1 no - To platform wall. No access, engineering hours required		1	R709004		
69522	ACTIVE	J	N115-00-3/264	Platform 4 - Southbound Local - Bakerloo Line - Station Building - Waterloo Stn	Gasket :Pipework	Asbestos	Sampled – Not Detected				Invert - Gaskets - throughout - To flanges in pipework.			R709004		Y
69524	ACTIVE	J	N115-00-3/264	Platform 4 - Southbound Local - Bakerloo Line - Station Building - Waterloo Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected				Invert - Bitumen ducts - total 12 no -To track wall.		12	R709004		Y
10702	ACTIVE	J	N115-00-3/381	Store - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2095	ACTIVE	J	N115-00-3/381	Store - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10703	ACTIVE	J	N115-00-3/382	Store - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2096	ACTIVE	J	N115-00-3/382	Store - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10704	ACTIVE	J	N115-00-3/576	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2159	ACTIVE	J	N115-00-3/576	Stairs: Linear - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10705	ACTIVE	J	N115-00-3/577	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2907	ACTIVE	J	N115-00-3/577	Stairs: Linear - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10706	ACTIVE	J	N115-00-3/578	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2160	ACTIVE	J	N115-00-3/578	Stairs: Linear - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10707	ACTIVE	J	N115-00-3/601	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2749	ACTIVE	J	N115-00-3/601	Stairs: Linear - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10708	ACTIVE	J	N115-00-3/602	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2161	ACTIVE	J	N115-00-3/602	Stairs: Linear - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10709	ACTIVE	J	N115-00-3/603	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2162	ACTIVE	J	N115-00-3/603	Stairs: Linear - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10710	ACTIVE	J	N115-00-3/604	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2268	ACTIVE	J	N115-00-3/604	Stairs: Linear - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10711	ACTIVE	J	N115-00-3/633	Stairs: Spiral - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2750	ACTIVE	J	N115-00-3/633	Stairs: Spiral - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10712	ACTIVE	J	N115-00-3/634	Stairs: Spiral - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2322	ACTIVE	J	N115-00-3/634	Stairs: Spiral - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10713	ACTIVE	J	N115-00-3/661	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2166	ACTIVE	J	N115-00-3/661/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Waterloo Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling - Not Surveyed				Yes	
2165	ACTIVE	J	N115-00-3/661/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
10714	ACTIVE	J	N115-00-3/662	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45403	ACTIVE	J	N115-00-3/662	Switch Room - Station Building - Waterloo Stn		Asbestos	Strongly Presumed				Combination fuse switches 4 x Wall 2 - Asbestos materials within		4		N	N
2778	ACTIVE	J	N115-00-3/662	Switch Room - Station Building - Waterloo Stn	Isolator Switches	Asbestos	Strongly Presumed				Combination fuse switches 2x 30amps 2x 60amps - Asbestos materials within		4			
2751	ACTIVE	J	N115-00-3/662/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2167	ACTIVE	J	N115-00-3/662/CLG-01 80836906	Ceiling: Solid - 1 - Switch Room - Station Building - Waterloo Stn Ceiling: Solid	Void	Asbestos	Surveyed – Not Detected				Solid ceiling				Yes	
45404	ACTIVE	J	N115-00-3/662/FLR-01	Floor - 1 - Switch Room - Station Building - Waterloo Stn	Cable Duct: Other	Asbestos	Strongly Presumed				4x ducts to floor		4		N	N
10715	ACTIVE	J	N115-00-3/663	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2434	ACTIVE	J	N115-00-3/663	Switch Room - Station Building - Waterloo Stn	Isolator Switches	Asbestos	Strongly Presumed				Combination fuse switch boxes 1x Wall 1 6x Wall 2 - Asbestos materials within		7			
2168	ACTIVE	J	N115-00-3/663/CLG-01	Ceiling: Solid - 1 - Switch Room - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2169	ACTIVE	J	N115-00-3/663/WAL-003 80836912	Wall: Internal - 3 - Switch Room - Station Building - Waterloo Stn Wall: Internal	Other Electrical Boxes	Asbestos	Presumed				Transformer box 1 x to floor - Presumed asbestos materials within				Yes	
10716	ACTIVE	J	N115-00-3/664	Disused Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2171	ACTIVE	J	N115-00-3/664	Disused Room - Station Building - Waterloo Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse box - Asbestos materials within		1			
2170	ACTIVE	J	N115-00-3/664/CLG-01	Ceiling: Solid - 1 - Disused Room - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2752	ACTIVE	J	N115-00-3/664/CLG-01 80836924	Ceiling: Solid - 1 - Disused Room - Station Building - Waterloo Stn Ceiling: Solid	Cable Ducts: Bitumen	Asbestos	Strongly Presumed				Bitumen Cable Duct (filled-in)				Y	
10717	ACTIVE	J	N115-00-3/665	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2172	ACTIVE	J	N115-00-3/665	Switch Room - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10718	ACTIVE	J	N115-00-3/666	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2269	ACTIVE	J	N115-00-3/666	Switch Room - Station Building - Waterloo Stn	Isolator Switches	Asbestos	Strongly Presumed				Combination fuse switch boxes - Asbestos materials within		5			
10719	ACTIVE	J	N115-00-3/667	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2173	ACTIVE	J	N115-00-3/667	Switch Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10720	ACTIVE	J	N115-00-3/668	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2174	ACTIVE	J	N115-00-3/668	Switch Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10721	ACTIVE	J	N115-00-3/669	Switch Cupboard - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2175	ACTIVE	J	N115-00-3/669	Switch Cupboard - Station Building - Waterloo Stn	Isolator Switches	Asbestos	Removed				Insulation materials within		5			
10722	ACTIVE	J	N115-00-3/670	Switch Cupboard - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2753	ACTIVE	J	N115-00-3/670	Switch Cupboard - Station Building - Waterloo Stn	Other Electrical Boxes	Asbestos	Presumed				Asbestos Materials Within equipment					
10723	ACTIVE	J	N115-00-3/711	Relay Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2176	ACTIVE	J	N115-00-3/711 85075928	Relay Room - Station Building - Waterloo Stn Room Asset	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse box to high level wall		1			
2177	ACTIVE	J	N115-00-3/711	Relay Room - Station Building - Waterloo Stn	Boarding: Cement	Asbestos	Strongly Presumed				0.5m² panels under live equipment		2			
2520	ACTIVE	J	N115-00-3/711	Relay Room - Station Building - Waterloo Stn	Cable: Sheath	Asbestos	Removed				75mm woven cable insulation - Terminating in equipment & entering invert		2			
42059	INACTIVE	J	N115-00-3/711	Relay Room - Station Building - Waterloo Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				8 x PCB's - Fair condition		8		N	N
10724	ACTIVE	J	N115-00-3/712	Relay Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2180	ACTIVE	J	N115-00-3/712 80143170	Relay Room - Station Building - Waterloo Stn Room Assets	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse box - Asbestos materials within		1			
2754	ACTIVE	J	N115-00-3/712	Relay Room - Station Building - Waterloo Stn	Cable Ducts: Cement	Asbestos	Known				Cable ducts to floor					
2178	ACTIVE	J	N115-00-3/712	Relay Room - Station Building - Waterloo Stn	Cable: Sheath	Asbestos	No Access: Presumed				75mm woven cable insulation - Terminating in equipment & entering invert					
45385	ACTIVE	J	N115-00-3/712	Relay Room - Station Building - Waterloo Stn	Cable: Sheath	Asbestos	Strongly Presumed				2x75mm woven cable insulation - Terminating in equipment & entering invert	75	2		N	N
2179	ACTIVE	J	N115-00-3/712	Relay Room - Station Building - Waterloo Stn	Cable: Sheath	Asbestos	Known				Cable - White, un-encapsulated (left hand side of MDF)		1			
2270	ACTIVE	J	N115-00-3/712	Relay Room - Station Building - Waterloo Stn	Boarding: Cement	Asbestos	Strongly Presumed				0.5m² panels under live equipment		2			
42058	INACTIVE	J	N115-00-3/712	Relay Room - Station Building - Waterloo Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				4 x PCB's - Fair Condition (covered by a silver temporary protection sheet)		4		N	N



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2790	ACTIVE	J	N115-00-3/712/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
10725	ACTIVE	J	N115-00-3/713	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2181	ACTIVE	J	N115-00-3/713	Switch Room - Station Building - Waterloo Stn	Westing house Boxes	Asbestos	Removed				Insulation materials within		4			
10726	ACTIVE	J	N115-00-3/714	Relay Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2182	INACTIVE	J	N115-00-3/714	Relay Room - Station Building - Waterloo Stn	No Access	Asbestos	No Access: Presumed									
46844	ACTIVE	J	N115-00-3/714	Relay Room - Station Building - Waterloo Stn	Vinyl tiles	Asbestos	Known				Marley Tiles (ID confirm asbestos) to wall 1,2,3.					
46845	ACTIVE	J	N115-00-3/714	Relay Room - Station Building - Waterloo Stn	Cable: Sheath	Asbestos	Known				2 known asbestos cables within non asbestos duct					
42334	INACTIVE	J	N115-00-3/714	Relay Room - Station Building - Waterloo Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				3 x silver cylinder PCB's - (re-inspected VC 31.5.22)		3		N	N
42333	INACTIVE	J	N115-00-3/714	Relay Room - Station Building - Waterloo Stn	PCBs	Polychlorinated biphenyl	Strongly Presumed				3 x PCB's - fair condition		3		N	N
46852	ACTIVE	J	N115-00-3/714/WAL-001	Wall: Internal - 1 - Relay Room - Station Building - Waterloo Stn	Cable: Sheath	Asbestos	Known				asbestos braided cables green & white running from non-asbestos duct to rack on wall 1					
46851	ACTIVE	J	N115-00-3/714/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Waterloo Stn	Boarding: Cement	Asbestos	Strongly Presumed				3x cement panels to metal rack on wall 2					
46849	ACTIVE	J	N115-00-3/714/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Waterloo Stn	Other Boarding	Asbestos	Presumed				Brown composite panels to rack wall 2					
46847	ACTIVE	J	N115-00-3/714/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Waterloo Stn	Other Boarding	Asbestos	Presumed				Brown composite panel to rack on wall 2					
46846	ACTIVE	J	N115-00-3/714/WAL-002	Wall: Internal - 2 - Relay Room - Station Building - Waterloo Stn	Other Boarding	Asbestos	Presumed				Black composite panel to capacitor on rack - wall 2					
46848	ACTIVE	J	N115-00-3/714/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Waterloo Stn	Other Boarding	Asbestos	Presumed				Brown composite board to white capacitor wall 3					
46850	ACTIVE	J	N115-00-3/714/WAL-003	Wall: Internal - 3 - Relay Room - Station Building - Waterloo Stn	Other Boarding	Asbestos	Presumed				Brown composite panels to rack wall 3					
10727	ACTIVE	J	N115-00-3/715	Relay Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2183	ACTIVE	J	N115-00-3/715	Relay Room - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10728	ACTIVE	J	N115-00-3/716	Relay Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2099	ACTIVE	J	N115-00-3/716	Relay Room - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10729	ACTIVE	J	N115-00-3/731	CER - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2101	ACTIVE	J	N115-00-3/731	CER - Station Building - Waterloo Stn	Cable: Sheath	Asbestos	Presumed				Insulated cables					
2731	ACTIVE	J	N115-00-3/731/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Waterloo Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2100	ACTIVE	J	N115-00-3/731/CLG-01	Ceiling: Solid - 1 - CER - Station Building - Waterloo Stn	Void	Asbestos	Surveyed – Not Detected								Yes	
10730	ACTIVE	J	N115-00-3/761	Equipment Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2393	ACTIVE	J	N115-00-3/761	Equipment Room - Station Building - Waterloo Stn	Cable: Wrap	Asbestos	Strongly Presumed				Woven cable insulation material		1			
2906	ACTIVE	J	N115-00-3/761	Equipment Room - Station Building - Waterloo Stn	Westing house Boxes	Asbestos	Strongly Presumed				Westinghouse box low level to wall 1					
10731	ACTIVE	J	N115-00-3/762	Equipment Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2732	ACTIVE	J	N115-00-3/762	Equipment Room - Station Building - Waterloo Stn	Cable: Sheath	Asbestos	Known				50mm white Cable Platform side		1			
2103	ACTIVE	J	N115-00-3/762	Equipment Room - Station Building - Waterloo Stn	Cable: Sheath	Asbestos	Known				30mm Green Cable Platform side		3			
2102	ACTIVE	J	N115-00-3/762	Equipment Room - Station Building - Waterloo Stn	Cable Ducts: Bitumen	Asbestos	Sampled – Not Detected									
10732	ACTIVE	J	N115-00-3/763	Equipment Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2104	ACTIVE	J	N115-00-3/763	Equipment Room - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10733	ACTIVE	J	N115-00-3/771	Pump Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45405	ACTIVE	J	N115-00-3/771	Pump Room - Station Building - Waterloo Stn	Other Electrical Boxes	Asbestos	Presumed				1x earth terminal box to concrete wall		1		N	N



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2319	ACTIVE	J	N115-00-3/771	Pump Room - Station Building - Waterloo Stn	No Access	Asbestos	No Access: Presumed				Not surveyed					
45406	ACTIVE	J	N115-00-3/771	Pump Room - Station Building - Waterloo Stn	Isolator Switches	Asbestos	Presumed				1x combination fuse switch box to concrete wall		1		N	N
10734	ACTIVE	J	N115-00-3/787	Service Area - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2105	ACTIVE	J	N115-00-3/787	Service Area - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10735	ACTIVE	J	N115-00-3/901	Disused Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2430	ACTIVE	J	N115-00-3/901	Disused Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10736	ACTIVE	J	N115-00-3/902	Disused Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2394	ACTIVE	J	N115-00-3/902	Disused Room - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10737	ACTIVE	J	N115-00-4/071	Circulation Area - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2108	ACTIVE	J	N115-00-4/071	Circulation Area - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10738	ACTIVE	J	N115-00-4/072	Circulation Area - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2109	ACTIVE	J	N115-00-4/072	Circulation Area - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10739	ACTIVE	J	N115-00-4/073	Circulation Area - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2734	ACTIVE	J	N115-00-4/073	Circulation Area - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10740	ACTIVE	J	N115-00-4/074	Circulation Area - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2110	ACTIVE	J	N115-00-4/074	Circulation Area - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10741	ACTIVE	J	N115-00-4/081	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2111	ACTIVE	J	N115-00-4/081	Lobby - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10742	ACTIVE	J	N115-00-4/082	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2112	ACTIVE	J	N115-00-4/082	Lobby - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10743	ACTIVE	J	N115-00-4/083	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2735	ACTIVE	J	N115-00-4/083	Lobby - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
2395	ACTIVE	J	N115-00-4/137	Lift Shaft - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
2113	ACTIVE	J	N115-00-4/138	Lift Shaft - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10744	ACTIVE	J	N115-00-4/201	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2114	ACTIVE	J	N115-00-4/201	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10745	ACTIVE	J	N115-00-4/202	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2115	ACTIVE	J	N115-00-4/202	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10746	ACTIVE	J	N115-00-4/203	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2116	ACTIVE	J	N115-00-4/203	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10747	ACTIVE	J	N115-00-4/204	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2736	ACTIVE	J	N115-00-4/204	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10748	ACTIVE	J	N115-00-4/205	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2117	ACTIVE	J	N115-00-4/205	Lobby - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10749	ACTIVE	J	N115-00-4/206	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2118	ACTIVE	J	N115-00-4/206	Lobby - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10750	ACTIVE	J	N115-00-4/207	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2119	ACTIVE	J	N115-00-4/207	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10751	ACTIVE	J	N115-00-4/208	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2396	ACTIVE	J	N115-00-4/208	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10752	ACTIVE	J	N115-00-4/209	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2320	ACTIVE	J	N115-00-4/209	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10753	ACTIVE	J	N115-00-4/210	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2120	ACTIVE	J	N115-00-4/210	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10754	ACTIVE	J	N115-00-4/211	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2431	ACTIVE	J	N115-00-4/211	Lobby - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10755	ACTIVE	J	N115-00-4/212	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2737	ACTIVE	J	N115-00-4/212	Lobby - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10756	ACTIVE	J	N115-00-4/213	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2121	ACTIVE	J	N115-00-4/213	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10757	ACTIVE	J	N115-00-4/265	Platform 5 - Westbound Local - Jubilee Line - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2122	ACTIVE	J	N115-00-4/265	Platform 5 - Westbound Local - Jubilee Line - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10758	ACTIVE	J	N115-00-4/266	Platform 6 - Eastbound Local - Jubilee Line - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2123	ACTIVE	J	N115-00-4/266	Platform 6 - Eastbound Local - Jubilee Line - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10759	ACTIVE	J	N115-00-4/406	Store - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2518	ACTIVE	J	N115-00-4/406	Store - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10760	ACTIVE	J	N115-00-4/411	Store - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2738	ACTIVE	J	N115-00-4/411	Store - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10761	ACTIVE	J	N115-00-4/481	Disused Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2262	ACTIVE	J	N115-00-4/481	Disused Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10762	ACTIVE	J	N115-00-4/576	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2124	ACTIVE	J	N115-00-4/576	Stairs: Linear - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10763	ACTIVE	J	N115-00-4/577	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2125	ACTIVE	J	N115-00-4/577	Stairs: Linear - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10764	ACTIVE	J	N115-00-4/634	Stairs: Spiral - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2126	ACTIVE	J	N115-00-4/634	Stairs: Spiral - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10765	ACTIVE	J	N115-00-4/661	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2127	ACTIVE	J	N115-00-4/661	Switch Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10766	ACTIVE	J	N115-00-4/662	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2739	ACTIVE	J	N115-00-4/662	Switch Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10767	ACTIVE	J	N115-00-4/776	Pump Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2519	ACTIVE	J	N115-00-4/776	Pump Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10768	ACTIVE	J	N115-00-4/790	Service Riser - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2128	ACTIVE	J	N115-00-4/790	Service Riser - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
2263	ACTIVE	J	N115-00-4/791	Vent Shaft - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
2129	ACTIVE	J	N115-00-4/792	Vent Shaft - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
2130	ACTIVE	J	N115-00-4/793	Vent Shaft - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
2740	ACTIVE	J	N115-00-4/794	Vent Shaft - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10769	ACTIVE	J	N115-00-4/795	Pump Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2131	ACTIVE	J	N115-00-4/795	Pump Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
2132	ACTIVE	J	N115-00-4/796	Vent Shaft - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
2432	ACTIVE	J	N115-00-4/797	Vent Shaft - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
2133	ACTIVE	J	N115-00-4/798	Vent Shaft - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10770	ACTIVE	J	N115-00-4/901	Service Area - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2134	ACTIVE	J	N115-00-4/901	Service Area - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10771	ACTIVE	J	N115-00-5/081	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2741	ACTIVE	J	N115-00-5/081	Lobby - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10772	ACTIVE	J	N115-00-5/082	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2264	ACTIVE	J	N115-00-5/082	Lobby - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10773	ACTIVE	J	N115-00-5/121	Platform Invert - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2135	ACTIVE	J	N115-00-5/121	Platform Invert - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10774	ACTIVE	J	N115-00-5/122	Service Riser - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2136	ACTIVE	J	N115-00-5/122	Service Riser - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10775	ACTIVE	J	N115-00-5/123	Platform Invert - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2137	ACTIVE	J	N115-00-5/123	Platform Invert - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10776	ACTIVE	J	N115-00-5/161	LMC - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2742	ACTIVE	J	N115-00-5/161	LMC - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10777	ACTIVE	J	N115-00-5/162	LMC - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2138	ACTIVE	J	N115-00-5/162	LMC - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10778	ACTIVE	J	N115-00-5/236	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2139	ACTIVE	J	N115-00-5/236	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10779	ACTIVE	J	N115-00-5/237	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2140	ACTIVE	J	N115-00-5/237	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10780	ACTIVE	J	N115-00-5/371	SER - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2743	ACTIVE	J	N115-00-5/371	SER - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10781	ACTIVE	J	N115-00-5/576	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2777	ACTIVE	J	N115-00-5/576	Stairs: Linear - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10782	ACTIVE	J	N115-00-5/661	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2321	ACTIVE	J	N115-00-5/661	Switch Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10783	ACTIVE	J	N115-00-5/662	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2141	ACTIVE	J	N115-00-5/662	Switch Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10784	ACTIVE	J	N115-00-5/663	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2142	ACTIVE	J	N115-00-5/663	Switch Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10785	ACTIVE	J	N115-00-5/706	IMR - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2143	ACTIVE	J	N115-00-5/706	IMR - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10786	ACTIVE	J	N115-00-5/731	CER - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2144	ACTIVE	J	N115-00-5/731	CER - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10787	ACTIVE	J	N115-00-5/772	Pump Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2744	ACTIVE	J	N115-00-5/772	Pump Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10788	ACTIVE	J	N115-00-5/901	Pump Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2145	ACTIVE	J	N115-00-5/901	Pump Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10789	ACTIVE	J	N115-00-5/902	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2433	ACTIVE	J	N115-00-5/902	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10790	ACTIVE	J	N115-00-5/903	Pump Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2265	ACTIVE	J	N115-00-5/903	Pump Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10791	ACTIVE	J	N115-00-5/904	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2146	ACTIVE	J	N115-00-5/904	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10792	ACTIVE	J	N115-00-5/906	Disused Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2147	ACTIVE	J	N115-00-5/906	Disused Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10793	ACTIVE	J	N115-00-A/081	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2745	ACTIVE	J	N115-00-A/081	Lobby - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
10794	ACTIVE	J	N115-00-A/082	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2148	ACTIVE	J	N115-00-A/082	Passage - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10795	ACTIVE	J	N115-00-A/151	UMC - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2149	ACTIVE	J	N115-00-A/151	UMC - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2883	ACTIVE	J	N115-00-A/171	Escalator Incline - Station Building - Waterloo Stn	No Access	Asbestos	No Access: Presumed				Not surveyed					



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
45386	ACTIVE	J	N115-00-A/171	Escalator Incline - Station Building - Waterloo Stn		Asbestos	Presumed				1x switch panel to wall		1			
10796	ACTIVE	J	N115-00-A/201	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2150	INACTIVE	J	N115-00-A/201	Passage - Station Building - Waterloo Stn	No Access	Asbestos	No Access: Presumed				Network Rail - N115-14s					
46354	ACTIVE	J	N115-00-A/201	Passage - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				Limited visual access within false ceiling, very shallow void AFC, and congested - No sample taken			R676026	N	N
10797	ACTIVE	J	N115-00-A/202	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2746	INACTIVE	J	N115-00-A/202	Passage - Station Building - Waterloo Stn	No Access	Asbestos	No Access: Presumed				Network Rail - N115-14s					
10798	ACTIVE	J	N115-00-A/203	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2266	INACTIVE	J	N115-00-A/203	Passage - Station Building - Waterloo Stn	No Access	Asbestos	No Access: Presumed				Network Rail - N115-14s					
10799	ACTIVE	J	N115-00-A/204	Passage - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2151	ACTIVE	J	N115-00-A/204	Passage - Station Building - Waterloo Stn	No Access	Asbestos	No Access: Presumed				Not surveyed					
10800	ACTIVE	J	N115-00-A/236	Lobby - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2153	ACTIVE	J	N115-00-A/236/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Waterloo Stn	Void	Asbestos	No Access: Presumed				Above False Ceiling - Not Surveyed				Yes	
10801	ACTIVE	J	N115-00-A/601	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2156	ACTIVE	J	N115-00-A/601	Stairs: Linear - Station Building - Waterloo Stn	No Access	Asbestos	No Access: Presumed				Not surveyed					
10802	ACTIVE	J	N115-00-A/608	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2157	ACTIVE	J	N115-00-A/608	Stairs: Linear - Station Building - Waterloo Stn		Asbestos	Surveyed – Not Detected				No Asbestos Visible					
2770	ACTIVE	J	N115-00-A/608/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Waterloo Stn	Lead/Leading	Lead Paint/Lead	Known				Grey/cream emulsion 46sqm					



Hazardous Material Asset Register - Summary



N115-00 - Station Building - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10803	ACTIVE	J	N115-00-A/611	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2237	ACTIVE	J	N115-00-A/611/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Waterloo Stn	Void	Asbestos	No Access: Presumed								Yes	
10804	ACTIVE	J	N115-00-A/612	Stairs: Linear - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2238	ACTIVE	J	N115-00-A/612/CLG-01	Ceiling: Solid - 1 - Linear Stairs - Station Building - Waterloo Stn	Void	Asbestos	No Access: Presumed								Yes	
10805	ACTIVE	J	N115-00-A/661	Switch Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2240	ACTIVE	J	N115-00-A/661	Switch Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10806	ACTIVE	J	N115-00-A/801	Disused Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2245	ACTIVE	J	N115-00-A/801	Disused Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10807	ACTIVE	J	N115-00-A/901	Void - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2246	ACTIVE	J	N115-00-A/901	Void - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
2247	ACTIVE	J	N115-00-A/926	Vent Shaft - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
2773	ACTIVE	J	N115-00-A/927	Vent Shaft - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
2437	ACTIVE	J	N115-00-A/928	Vent Shaft - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10808	ACTIVE	J	N115-00-A/951	Disused Room - Station Building - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2248	ACTIVE	J	N115-00-A/951	Disused Room - Station Building - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Ceiling. Walls and Floor solid construction.					
42910	ACTIVE	J	N115/N/UMC-08 80801270	Upper Machine Chamber Access - Waterloo Stn Upper Machine Chamber	Other Boarding	Asbestos	Presumed				Suspect boarding top of incline RHS					



Hazardous Material Asset Register - Summary



N135-00 - Station Building - London Bridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11070	ACTIVE	J	N135-00-1/081	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11071	ACTIVE	J	N135-00-1/082	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11072	ACTIVE	J	N135-00-1/083	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11073	ACTIVE	J	N135-00-1/186	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11074	ACTIVE	J	N135-00-1/236	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11075	ACTIVE	J	N135-00-1/237	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11076	ACTIVE	J	N135-00-1/291	Office - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11077	ACTIVE	J	N135-00-1/301	Locker Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11078	ACTIVE	J	N135-00-1/401	Bin Store - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11079	ACTIVE	J	N135-00-1/406	Store - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11080	ACTIVE	J	N135-00-1/411	Mess Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11081	ACTIVE	J	N135-00-1/412	Switch Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11082	ACTIVE	J	N135-00-1/416	Shower Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11083	ACTIVE	J	N135-00-1/417	Toilet: Unisex - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11084	ACTIVE	J	N135-00-1/451	Disused Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N135-00 - Station Building - London Bridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11085	ACTIVE	J	N135-00-1/481	Store - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11086	ACTIVE	J	N135-00-1/577	Stairs: Linear - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11087	ACTIVE	J	N135-00-1/580	Stairs: Linear - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11088	ACTIVE	J	N135-00-1/581	Stairs: Linear - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11089	ACTIVE	J	N135-00-1/582	Service Riser - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11090	ACTIVE	J	N135-00-1/601	Stairs: Linear - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11091	ACTIVE	J	N135-00-1/602	Stairs: Linear - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11092	ACTIVE	J	N135-00-1/665	Disused Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11093	ACTIVE	J	N135-00-1/666	Switch Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11094	ACTIVE	J	N135-00-1/667	Switch Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11095	ACTIVE	J	N135-00-1/679	Switch Cupboard - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45365	ACTIVE	J	N135-00-1/679	Switch Cupboard - Station Building - London Bridge Stn	Other Electrical Boxes	Asbestos	Removed				Materials within electrical equipment				N	N
11096	ACTIVE	J	N135-00-1/680	Switch Cupboard - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45366	ACTIVE	J	N135-00-1/680	Switch Cupboard - Station Building - London Bridge Stn	Other Electrical Boxes	Asbestos	Removed				Materials within electrical equipment				N	N
11097	ACTIVE	J	N135-00-1/777	Fan Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N135-00 - Station Building - London Bridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
45367	ACTIVE	J	N135-00-1/777	Fan Room - Station Building - London Bridge Stn	Other Electrical Boxes	Asbestos	Removed				Materials within electrical equipment				N	N
11098	ACTIVE	J	N135-00-1/781	TXR - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11099	ACTIVE	J	N135-00-1/782	TXR - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11100	ACTIVE	J	N135-00-1/793	Service Riser - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11101	ACTIVE	J	N135-00-1/801	Office - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11102	ACTIVE	J	N135-00-1/901	Service Riser - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11103	ACTIVE	J	N135-00-2/001	Booking Hall - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11104	ACTIVE	J	N135-00-2/002	Booking Hall - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11105	ACTIVE	J	N135-00-2/011	Ticket Office - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11106	ACTIVE	J	N135-00-2/012	Ticket Office - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11107	ACTIVE	J	N135-00-2/013	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11108	ACTIVE	J	N135-00-2/021	POM - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11109	ACTIVE	J	N135-00-2/022	POM - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11110	ACTIVE	J	N135-00-2/023	POM - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11111	ACTIVE	J	N135-00-2/024	POM - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N135-00 - Station Building - London Bridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11112	ACTIVE	J	N135-00-2/025	POM - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11113	ACTIVE	J	N135-00-2/031	Locker Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11114	ACTIVE	J	N135-00-2/032	Kitchen - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11115	ACTIVE	J	N135-00-2/033	Mess Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11116	ACTIVE	J	N135-00-2/036	Toilet: Female - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11117	ACTIVE	J	N135-00-2/037	Toilet: Male - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11118	ACTIVE	J	N135-00-2/038	Toilet: Unisex - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11119	ACTIVE	J	N135-00-2/071	Circulation Area - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11120	ACTIVE	J	N135-00-2/072	Circulation Area - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11121	ACTIVE	J	N135-00-2/074	Circulation Area - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11122	ACTIVE	J	N135-00-2/075	Circulation Area - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11123	ACTIVE	J	N135-00-2/081	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11124	ACTIVE	J	N135-00-2/082	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11125	ACTIVE	J	N135-00-2/083	Service Riser - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11126	ACTIVE	J	N135-00-2/084	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N135-00 - Station Building - London Bridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11127	ACTIVE	J	N135-00-2/085	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11128	ACTIVE	J	N135-00-2/086	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11129	ACTIVE	J	N135-00-2/087	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11130	ACTIVE	J	N135-00-2/088	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11131	ACTIVE	J	N135-00-2/089	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11132	ACTIVE	J	N135-00-2/090	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11133	ACTIVE	J	N135-00-2/092	Ticket Office - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11134	ACTIVE	J	N135-00-2/093	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11135	ACTIVE	J	N135-00-2/094	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11136	ACTIVE	J	N135-00-2/095	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11137	ACTIVE	J	N135-00-2/096	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11138	ACTIVE	J	N135-00-2/156	UMC - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11139	ACTIVE	J	N135-00-2/201	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11140	ACTIVE	J	N135-00-2/202	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11141	ACTIVE	J	N135-00-2/236	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N135-00 - Station Building - London Bridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11142	ACTIVE	J	N135-00-2/237	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11143	ACTIVE	J	N135-00-2/238	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11144	ACTIVE	J	N135-00-2/239	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11145	ACTIVE	J	N135-00-2/240	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11146	ACTIVE	J	N135-00-2/241	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1751	ACTIVE	J	N135-00-2/241	Passage - Station Building - London Bridge Stn	No Access	Asbestos	Removed				Not Surveyed					
45368	ACTIVE	J	N135-00-2/241/DORS	Doors - Passage - Station Building - London Bridge Stn	Durasteel	Asbestos	Removed				Fire door (durasteel) 3 no to doors		3		N	N
11147	ACTIVE	J	N135-00-2/242	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2304	ACTIVE	J	N135-00-2/242	Passage - Station Building - London Bridge Stn	No Access	Asbestos	Surveyed – Not Detected				New Build					
45369	ACTIVE	J	N135-00-2/242	Passage - Station Building - London Bridge Stn	Durasteel	Asbestos	Removed				Asbestos K (1 & 2) - Durasteel fire door 1 no				N	N
45370	ACTIVE	J	N135-00-2/242	Passage - Station Building - London Bridge Stn	Durasteel	Asbestos	Removed				Asbestos K (1 & 2) - Fire door (durasteel) 3 no to door frames				N	N
11148	ACTIVE	J	N135-00-2/243	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11149	ACTIVE	J	N135-00-2/244	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11150	ACTIVE	J	N135-00-2/245	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11151	ACTIVE	J	N135-00-2/246	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11152	ACTIVE	J	N135-00-2/311	Station Supervisor Office - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N135-00 - Station Building - London Bridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11153	ACTIVE	J	N135-00-2/331	Mess Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11154	ACTIVE	J	N135-00-2/396	SVC - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11155	ACTIVE	J	N135-00-2/398	SVC - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11156	ACTIVE	J	N135-00-2/406	SVC - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11157	ACTIVE	J	N135-00-2/411	Store - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11158	ACTIVE	J	N135-00-2/412	Store - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11159	ACTIVE	J	N135-00-2/414	Store - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11160	ACTIVE	J	N135-00-2/416	Toilet: Female - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11161	ACTIVE	J	N135-00-2/417	Toilet: Male - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11162	ACTIVE	J	N135-00-2/451	Consolidation Office - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11163	ACTIVE	J	N135-00-2/452	ATM - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11164	ACTIVE	J	N135-00-2/453	ATM - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11165	ACTIVE	J	N135-00-2/456	ATM - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11166	ACTIVE	J	N135-00-2/481	Store - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11167	ACTIVE	J	N135-00-2/482	Switch Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N135-00 - Station Building - London Bridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11168	ACTIVE	J	N135-00-2/483	Fan Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11169	ACTIVE	J	N135-00-2/484	Store - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11170	ACTIVE	J	N135-00-2/486	Store - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11171	ACTIVE	J	N135-00-2/501	Store - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11172	ACTIVE	J	N135-00-2/577	Stairs: Linear - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11173	ACTIVE	J	N135-00-2/578	Stairs: Linear - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11174	ACTIVE	J	N135-00-2/579	Stairs: Linear - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11175	ACTIVE	J	N135-00-2/581	Stairs: Linear - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11176	ACTIVE	J	N135-00-2/663	Switch Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11177	ACTIVE	J	N135-00-2/664	Transformer Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11178	ACTIVE	J	N135-00-2/665	Switch Cupboard - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11179	ACTIVE	J	N135-00-2/666	Switch Cupboard - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11180	ACTIVE	J	N135-00-2/667	Switch Cupboard - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11181	ACTIVE	J	N135-00-2/668	Switch Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11182	ACTIVE	J	N135-00-2/669	Switch Cupboard (Access for MDF) - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N135-00 - Station Building - London Bridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11183	ACTIVE	J	N135-00-2/731	CER - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2648	ACTIVE	J	N135-00-2/731	CER - Station Building - London Bridge Stn	No Access	Asbestos	Surveyed – Not Detected				Refurbishment of location visible. No ACM present.					
45372	ACTIVE	J	N135-00-2/731	CER - Station Building - London Bridge Stn	Durasteel	Asbestos	Removed				Fire door (durasteel) new to doorways				N	N
45371	ACTIVE	J	N135-00-2/731/WAL-001	Wall: Internal - 1 - CER - Station Building - London Bridge Stn	Other Electrical Boxes	Asbestos	Removed				Materials within 2no. switchboxes		2		N	N
11184	ACTIVE	J	N135-00-2/732	Switch Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45373	ACTIVE	J	N135-00-2/732	Switch Room - Station Building - London Bridge Stn	Durasteel	Asbestos	Removed				Fire door (durasteel) 2 no to doorway				N	N
1752	ACTIVE	J	N135-00-2/732	Switch Room - Station Building - London Bridge Stn	No Access	Asbestos	Removed				Not Surveyed					
11185	ACTIVE	J	N135-00-2/733	CER - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
11186	ACTIVE	J	N135-00-2/747	SCR - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11187	ACTIVE	J	N135-00-2/751	Station Control Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11188	ACTIVE	J	N135-00-2/761	Fan Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11189	ACTIVE	J	N135-00-2/762	Fan Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11190	ACTIVE	J	N135-00-2/771	Lift Pump Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11191	ACTIVE	J	N135-00-2/776	Fan Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11192	ACTIVE	J	N135-00-2/777	Disused Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11193	ACTIVE	J	N135-00-2/778	Fan Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N135-00 - Station Building - London Bridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11194	ACTIVE	J	N135-00-2/779	Fan Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11195	ACTIVE	J	N135-00-2/780	Fan Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11196	ACTIVE	J	N135-00-2/781	SCR - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11197	ACTIVE	J	N135-00-2/782	Transformer Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11198	ACTIVE	J	N135-00-2/783	Switch Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11199	ACTIVE	J	N135-00-2/784	Fan Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11200	ACTIVE	J	N135-00-2/785	Switch Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11201	ACTIVE	J	N135-00-2/786	Service Riser - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11202	ACTIVE	J	N135-00-2/787	Service Riser - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11203	ACTIVE	J	N135-00-2/788	Service Area - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11204	ACTIVE	J	N135-00-2/789	Service Riser - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1753	ACTIVE	J	N135-00-2/799	Vent Shaft - Station Building - London Bridge Stn	No Access	Asbestos	Surveyed – Not Detected				New build					
11205	ACTIVE	J	N135-00-2/801	Office - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11206	ACTIVE	J	N135-00-2/901	Office- Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11207	ACTIVE	J	N135-00-2/902	Disused Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N135-00 - Station Building - London Bridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11208	ACTIVE	J	N135-00-2/903	Void - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11209	ACTIVE	J	N135-00-2/904	Fan Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11210	ACTIVE	J	N135-00-2/951	Disused Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1754	ACTIVE	J	N135-00-2/951	Disused Room - Station Building - London Bridge Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
11211	ACTIVE	J	N135-00-2/952	Disused Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2649	ACTIVE	J	N135-00-2/952	Disused Room - Station Building - London Bridge Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
45378	ACTIVE	J	N135-00-2/952/DOR-01	Door - 1 - Disused Room - Station Building - London Bridge Stn	Durasteel	Asbestos	Presumed				Fire door (durasteel) to door		1		N	N
11212	ACTIVE	J	N135-00-2/953	Disused Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45374	ACTIVE	J	N135-00-2/953	Disused Room - Station Building - London Bridge Stn	Boarding: AIB	Asbestos	Known				Asbestos insulation board 1m² to firebreak to ceiling above door	1			N	N
1755	ACTIVE	J	N135-00-2/953	Disused Room - Station Building - London Bridge Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
11213	ACTIVE	J	N135-00-2/981	Stairs: Linear - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Restricted Access Fans need to be isolated before entry, Two Man team required					
1756	ACTIVE	J	N135-00-2/981	Stairs: Linear - Station Building - London Bridge Stn	No Access	Asbestos	No Access: Presumed				Restricted Access Fans need to be isolated before entry, Two Man team required					
11214	ACTIVE	J	N135-00-2/TA1	Tenancy - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11215	ACTIVE	J	N135-00-3/082	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11216	ACTIVE	J	N135-00-3/151	UMC - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Box Under Escalator No Access					
1750	ACTIVE	J	N135-00-3/151	UMC - Station Building - London Bridge Stn	Paper Asbestos	Asbestos	Known				<1m2 - Paper lining within auxillary break switch of red box Box is at horizontal level underneath Escalator 11	1				



Hazardous Material Asset Register - Summary



N135-00 - Station Building - London Bridge Stn																
Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11217	ACTIVE	J	N135-00-3/152	UMC - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11218	ACTIVE	J	N135-00-3/153	UMC - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11219	ACTIVE	J	N135-00-3/154	UMC - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11220	ACTIVE	J	N135-00-3/155	UMC - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
11221	ACTIVE	J	N135-00-3/161	LMC - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2922	ACTIVE	J	N135-00-3/171	Escalator Incline - Station Building - London Bridge Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
11222	ACTIVE	J	N135-00-3/236	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11223	ACTIVE	J	N135-00-3/576	Stairs: Linear - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11224	ACTIVE	J	N135-00-3/577	Stairs: Linear - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11225	ACTIVE	J	N135-00-3/661	Switch Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11226	ACTIVE	J	N135-00-3/662	Switch Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11227	ACTIVE	J	N135-00-3/771	Plant Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11228	ACTIVE	J	N135-00-3/776	Fan Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11229	ACTIVE	J	N135-00-3/792	Service Riser - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1757	ACTIVE	J	N135-00-3/793	Vent Shaft - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos				Restricted Access Fans need to be isolated before entry, Two Man team required			R679101		



Hazardous Material Asset Register - Summary



N135-00 - Station Building - London Bridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2793	ACTIVE	J	N135-00-3/794	Vent Shaft - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos							R679101		
2504	ACTIVE	J	N135-00-3/795	Vent Shaft - Station Building - London Bridge Stn	No Access	Asbestos	No Access: Presumed				Restricted Access Fans need to be isolated before entry, Two Man team required					
1758	ACTIVE	J	N135-00-3/796	Vent Shaft - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos				Restricted Access Fans need to be isolated before entry, Two Man team required			R679101		
2561	ACTIVE	J	N135-00-3/797	Vent Shaft - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos				Restricted Access Fans need to be isolated before entry, Two Man team required			R679101		
1759	ACTIVE	J	N135-00-3/798	Vent Shaft - Station Building - London Bridge Stn	No Access	Asbestos	No Access: Presumed				Restricted Access Fans need to be isolated before entry, Two Man team required					
1760	ACTIVE	J	N135-00-3/988	Vent Shaft - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos				Restricted Access Fans need to be isolated before entry, Two Man team required			R679101		
2358	ACTIVE	J	N135-00-3/989	Vent Shaft - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos							R679101		
11230	ACTIVE	J	N135-00-4/071	Circulation Area - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2794	ACTIVE	J	N135-00-4/071	Circulation Area - Station Building - London Bridge Stn		Asbestos	Surveyed – Not Detected				NAD			R679101		
11231	ACTIVE	J	N135-00-4/072	Circulation Area - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11232	ACTIVE	J	N135-00-4/073	Circulation Area - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11233	ACTIVE	J	N135-00-4/081	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11234	ACTIVE	J	N135-00-4/082	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11235	ACTIVE	J	N135-00-4/151	UMC - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11236	ACTIVE	J	N135-00-4/161	LMC - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N135-00 - Station Building - London Bridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11237	ACTIVE	J	N135-00-4/162	LMC - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11238	ACTIVE	J	N135-00-4/163	LMC - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11239	ACTIVE	J	N135-00-4/201	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11240	ACTIVE	J	N135-00-4/202	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11241	ACTIVE	J	N135-00-4/203	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11242	ACTIVE	J	N135-00-4/204	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11243	ACTIVE	J	N135-00-4/205	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11244	ACTIVE	J	N135-00-4/206	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11245	ACTIVE	J	N135-00-4/207	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11246	ACTIVE	J	N135-00-4/208	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11247	ACTIVE	J	N135-00-4/209	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11248	ACTIVE	J	N135-00-4/210	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11249	ACTIVE	J	N135-00-4/455	POM - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11250	ACTIVE	J	N135-00-4/601	Stairs: Linear - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11251	ACTIVE	J	N135-00-4/602	Stairs: Linear - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N135-00 - Station Building - London Bridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11252	ACTIVE	J	N135-00-4/603	Stairs: Linear - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11253	ACTIVE	J	N135-00-4/604	Stairs: Linear - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11254	ACTIVE	J	N135-00-4/605	Stairs: Linear - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11255	ACTIVE	J	N135-00-4/631	Stairs: Spiral - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45376	ACTIVE	J	N135-00-4/631	Stairs: Spiral - Station Building - London Bridge Stn	Durasteel	Asbestos	Presumed				Fire door (durasteel) 2 no to doors. No access to stairs via padlocked double doors.		2		N	N
45375	ACTIVE	J	N135-00-4/631	Stairs: Spiral - Station Building - London Bridge Stn	Lead/Leading	Lead Paint/Lead	Known				Confirmed Lead paint on underside of stairs within void 4/903. No access to stairs via padlocked double doors.				N	N
11256	ACTIVE	J	N135-00-4/632	Stairs: Spiral - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11257	ACTIVE	J	N135-00-4/633	Stairs: Spiral - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11258	ACTIVE	J	N135-00-4/771	Pump Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11259	ACTIVE	J	N135-00-4/786	Service Riser - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1761	ACTIVE	J	N135-00-4/793	Vent Shaft - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos							R679101		
11260	ACTIVE	J	N135-00-4/902	Disused Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11261	ACTIVE	J	N135-00-4/903	Void - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
45377	ACTIVE	J	N135-00-4/903	Void - Station Building - London Bridge Stn	Lead/Leading	Lead Paint/Lead	Known				Lead paint confirmed on Stair strings / Vertical support girder / Stair support girders				N	N
11262	ACTIVE	J	N135-00-4/951	Locker Room- Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N135-00 - Station Building - London Bridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11263	ACTIVE	J	N135-00-4/986	Disused Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11264	ACTIVE	J	N135-00-4/987	Disused Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11265	ACTIVE	J	N135-00-5/071	Circulation Area - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11266	ACTIVE	J	N135-00-5/072	Circulation Area - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11267	ACTIVE	J	N135-00-5/081	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11268	ACTIVE	J	N135-00-5/082	Service Riser - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11269	ACTIVE	J	N135-00-5/083	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11270	ACTIVE	J	N135-00-5/131	Lift Pump Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11271	ACTIVE	J	N135-00-5/161	LMC - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos							R679101		
11272	ACTIVE	J	N135-00-5/201	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11273	ACTIVE	J	N135-00-5/202	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11274	ACTIVE	J	N135-00-5/203	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11275	ACTIVE	J	N135-00-5/204	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11276	ACTIVE	J	N135-00-5/205	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11277	ACTIVE	J	N135-00-5/206	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N135-00 - Station Building - London Bridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11278	ACTIVE	J	N135-00-5/207	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11279	ACTIVE	J	N135-00-5/208	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11280	ACTIVE	J	N135-00-5/209	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11281	ACTIVE	J	N135-00-5/210	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11282	ACTIVE	J	N135-00-5/211	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11283	ACTIVE	J	N135-00-5/212	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11284	ACTIVE	J	N135-00-5/213	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11285	ACTIVE	J	N135-00-5/214	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11286	ACTIVE	J	N135-00-5/215	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11287	ACTIVE	J	N135-00-5/236	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11288	ACTIVE	J	N135-00-5/238	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11289	ACTIVE	J	N135-00-5/239	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11290	ACTIVE	J	N135-00-5/240	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11291	ACTIVE	J	N135-00-5/248	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11292	ACTIVE	J	N135-00-5/261	Platform 1 - Northbound Local - Northern Line - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N135-00 - Station Building - London Bridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11293	ACTIVE	J	N135-00-5/262	Platform 2 - Southbound Local - Northern Line - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11294	ACTIVE	J	N135-00-5/406	Store - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11295	ACTIVE	J	N135-00-5/481	Switch Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11296	ACTIVE	J	N135-00-5/482	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11297	ACTIVE	J	N135-00-5/483	Switch Cupboard - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11298	ACTIVE	J	N135-00-5/484	Fan Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11299	ACTIVE	J	N135-00-5/661	Switch Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11300	ACTIVE	J	N135-00-5/662	Switch Cupboard (Access for MDF) - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11301	ACTIVE	J	N135-00-5/663	Switch Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11302	ACTIVE	J	N135-00-5/667	Relay Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11303	ACTIVE	J	N135-00-5/668	Switch Cupboard - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11304	ACTIVE	J	N135-00-5/669	Switch Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11305	ACTIVE	J	N135-00-5/670	Switch Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11306	ACTIVE	J	N135-00-5/671	Switch Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11307	ACTIVE	J	N135-00-5/711	Relay Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N135-00 - Station Building - London Bridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11308	ACTIVE	J	N135-00-5/712	Relay Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11310	ACTIVE	J	N135-00-5/731	CER - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11311	ACTIVE	J	N135-00-5/732	CER - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11312	ACTIVE	J	N135-00-5/733	CER - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
11313	ACTIVE	J	N135-00-5/734	CER - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11314	ACTIVE	J	N135-00-5/735	CER - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11315	ACTIVE	J	N135-00-5/736	CER - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11316	ACTIVE	J	N135-00-5/771	Pump Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11317	ACTIVE	J	N135-00-5/772	Pump Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11318	ACTIVE	J	N135-00-5/791	Disused Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Restricted Access Fans need to be isolated before entry, Two Man team required					
1762	ACTIVE	J	N135-00-5/791	Disused Room - Station Building - London Bridge Stn	No Access	Asbestos	No Access: Presumed				Restricted Access Fans need to be isolated before entry, Two Man team required					
11319	ACTIVE	J	N135-00-5/902	Disused Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Strongly Presumed									
25908	ACTIVE	J	N135-00-5/902	Disused Room - Station Building - London Bridge Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Asbestos presumed within equipment to floodgate mechanism		2			
2357	ACTIVE	J	N135-00-5/902	Disused Room - Station Building - London Bridge Stn	Other Electrical Boxes	Asbestos	Presumed				Watford box presumed to contain - Chrysotile asbestos components		1		N	N
11320	ACTIVE	J	N135-00-5/951	Store - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N135-00 - Station Building - London Bridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11321	ACTIVE	J	N135-00-5/952	Disused Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1763	ACTIVE	J	N135-00-5/952	Disused Room - Station Building - London Bridge Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed					
11322	ACTIVE	J	N135-00-5/971	Disused Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				Restricted Access Fans need to be isolated before entry, Two Man team required					
2795	ACTIVE	J	N135-00-5/971	Disused Room - Station Building - London Bridge Stn	No Access	Asbestos	No Access: Presumed				Restricted Access Fans need to be isolated before entry, Two Man team required					
1764	ACTIVE	J	N135-00-5/981	Vent Shaft - Station Building - London Bridge Stn	No Access	Asbestos	No Access: Presumed				Restricted Access Fans need to be isolated before entry, Two Man team required					
11323	ACTIVE	J	N135-00-6/071	Circulation Area - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11324	ACTIVE	J	N135-00-6/072	Circulation Area - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11325	ACTIVE	J	N135-00-6/073	Circulation Area - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11326	ACTIVE	J	N135-00-6/081	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11327	ACTIVE	J	N135-00-6/082	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11328	ACTIVE	J	N135-00-6/083	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11329	ACTIVE	J	N135-00-6/084	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11330	ACTIVE	J	N135-00-6/085	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11331	ACTIVE	J	N135-00-6/131	Lift Pump Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11332	ACTIVE	J	N135-00-6/201	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N135-00 - Station Building - London Bridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11333	ACTIVE	J	N135-00-6/202	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11334	ACTIVE	J	N135-00-6/203	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11335	ACTIVE	J	N135-00-6/204	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11336	ACTIVE	J	N135-00-6/205	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11337	ACTIVE	J	N135-00-6/206	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11338	ACTIVE	J	N135-00-6/207	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11339	ACTIVE	J	N135-00-6/208	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11340	ACTIVE	J	N135-00-6/209	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11341	ACTIVE	J	N135-00-6/210	Lobby - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11342	ACTIVE	J	N135-00-6/236	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11343	ACTIVE	J	N135-00-6/237	Disused Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11344	ACTIVE	J	N135-00-6/238	Disused Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11345	ACTIVE	J	N135-00-6/263	Platform 3 - Westbound Local - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11346	ACTIVE	J	N135-00-6/264	Platform 4 - Eastbound Local - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11347	ACTIVE	J	N135-00-6/371	SER - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N135-00 - Station Building - London Bridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11348	ACTIVE	J	N135-00-6/372	Switch Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11349	ACTIVE	J	N135-00-6/401	Bin Store - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11350	ACTIVE	J	N135-00-6/576	Stairs: Linear - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11351	ACTIVE	J	N135-00-6/631	Stairs: Spiral - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11352	ACTIVE	J	N135-00-6/632	Stairs: Spiral - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11353	ACTIVE	J	N135-00-6/633	Stairs: Spiral - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11354	ACTIVE	J	N135-00-6/634	Stairs: Spiral - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11355	ACTIVE	J	N135-00-6/661	Switch Cupboard - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11356	ACTIVE	J	N135-00-6/662	Switch Cupboard - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11357	ACTIVE	J	N135-00-6/706	IMR - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11358	ACTIVE	J	N135-00-6/761	Fan Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11359	ACTIVE	J	N135-00-6/762	Fan Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11360	ACTIVE	J	N135-00-6/777	Fan Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11361	ACTIVE	J	N135-00-6/780	Service Riser - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11362	ACTIVE	J	N135-00-6/781	Service Area - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N135-00 - Station Building - London Bridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11363	ACTIVE	J	N135-00-6/786	Service Riser - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11364	ACTIVE	J	N135-00-6/900	Void - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11365	ACTIVE	J	N135-00-7/121	Platform Invert - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11366	ACTIVE	J	N135-00-7/122	Platform Invert - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11367	ACTIVE	J	N135-00-7/161	LMC - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11368	ACTIVE	J	N135-00-7/162	LMC - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11369	ACTIVE	J	N135-00-7/236	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11370	ACTIVE	J	N135-00-7/237	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11371	ACTIVE	J	N135-00-7/238	Passage - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11372	ACTIVE	J	N135-00-7/661	Switch Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11373	ACTIVE	J	N135-00-7/662	Switch Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11374	ACTIVE	J	N135-00-7/731	CER - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos									
11375	ACTIVE	J	N135-00-7/771	Pump Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11376	ACTIVE	J	N135-00-7/776	Fan Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11377	ACTIVE	J	N135-00-7/901	Fan Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N135-00 - Station Building - London Bridge Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
11378	ACTIVE	J	N135-00-7/902	Service Riser - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
11379	ACTIVE	J	N135-00-7/903	Disused Room - Station Building - London Bridge Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B081-01 - Store - Stanmore Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2994	ACTIVE	J	B081-01-2/373	Store Room - Store - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B081-10 - Signals Building - Stanmore Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2995	ACTIVE	J	B081-10-2/411	Store - Signals Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2996	ACTIVE	J	B081-10-2/665	Switch Room - Signals Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
2282	ACTIVE	J	B081-10-2/665/CLG-01	Ceiling: Solid - 1 - Switch Room - Signals Building - Stanmore Stn	Roofing Tiles	Asbestos	Surveyed – Not Detected				Solid Felt Roof - Non Asbestos		1			
2461	ACTIVE	J	B081-10-2/665/WAL-001	Wall: Internal - 1 - Switch Room - Signals Building - Stanmore Stn	Isolator Switches	Asbestos	Strongly Presumed				4x Switch Boxes - Wall 1 (3x60amp, 1x 30amp). Re-inspection by HMT.		4			
1105	ACTIVE	J	B081-10-2/665/WAL-002	Wall: Internal - 2 - Switch Room - Signals Building - Stanmore Stn	Cable Ducts: Bitumen	Asbestos	Presumed				2x Bitumen Ducts to external wall. Re-inspection by HMT.		2			

B081-11 - Signals Building - Stanmore Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2997	ACTIVE	J	B081-11-2/666	Switch Room - Signals Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B081-12 - Signals Building - Stanmore Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2998	ACTIVE	J	B081-12-0/661	SER - Signals Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2999	ACTIVE	J	B081-12-2/663	Switch Room - Signals Building - Stanmore Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B082-01 - P Way Accommodation - Stanmore To Canons Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3000	ACTIVE	J	B082-01-1/371	Mess Room - P Way Accommodation - Stanmore To Canons Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B082-02 - Signals Building - Stanmore To Canons Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3001	ACTIVE	J	B082-02-0/711	SER - Signals Building - Stanmore To Canons Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3002	ACTIVE	J	B082-02-0/712	Relay Room - Signals Building - Stanmore To Canons Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B082-04 - Signals Building - Stanmore To Canons Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3003	ACTIVE	J	B082-04-0/731	CER - Signals Building - Stanmore To Canons Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B082-05 - Signals Building - Stanmore To Canons Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3004	ACTIVE	J	B082-05-0/711	SER - Signals Building - Stanmore To Canons Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B082-07 - Electrical Building - Stanmore To Canons Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3007	ACTIVE	J	B082-07-0/706	IMR - Electrical Building - Stanmore To Canons Park	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
53865	INACTIVE	J	B082-07-0/706	IMR - Electrical Building - Stanmore To Canons Park		Polychlorinated biphenyl	Presumed				14x PCB's (Type D/S22946)					
53864	ACTIVE	J	B082-07-0/706/WAL-002	Wall: Internal - 2 - IMR - Electrical Building - Stanmore To Canons Park	Other Electrical Boxes	Asbestos	Presumed				2 x Switch boxes to wall 2					
3008	ACTIVE	J	B082-07-0/713	Relay Room - Electrical Building - Stanmore To Canons Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53866	ACTIVE	J	B082-07-0/713	Relay Room - Electrical Building - Stanmore To Canons Park	Boarding / Panels	Asbestos	Presumed				Asbestos - P - Paxoline Boards - Throughout Room. Re-inspected by HMT.		2			

B082-08 - Signals Building - Stanmore To Canons Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3009	ACTIVE	J	B082-08-0/712	SER - Signals Building - Stanmore To Canons Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B083-01 - Signals Building - Canons Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3072	ACTIVE	J	B083-01-0/713	SER - Signals Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B083-02 - Signals Building - Canons Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3073	ACTIVE	J	B083-02-0/711	SER - Signals Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Surveyed: Asbestos Presumed									
54084	ACTIVE	J	B083-02-0/711	SER - Signals Building - Canons Park Stn	Other Electrical Boxes	Asbestos	Presumed				Grey electrical switch box 1no				N	N



Hazardous Material Asset Register - Summary



B083-03 - Signals Building - Canons Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3074	ACTIVE	J	B083-03-0/711	CER - Signals Building - Canons Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B084-01 - Substation - Canons Park To Queensbury

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3076	ACTIVE	J	B084-01-1/781	Substation Room - Substation - Canons Park To Queensbury	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B084-02 - Signals Building - Canons Park To Queensbury

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3077	ACTIVE	J	B084-02-0/661	Switch Room - Signals Building - Canons Park To Queensbury	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3078	ACTIVE	J	B084-02-A/711	Switch Room - Signals Building - Canons Park To Queensbury	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B084-03 - Signals Building - Canons Park To Queensbury

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3079	ACTIVE	J	B084-03-0/711	SER - Signals Building - Canons Park To Queensbury	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3080	ACTIVE	J	B084-03-A/713	SER - Signals Building - Canons Park To Queensbury	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B085-01 - Signals Building - Queensbury Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3115	ACTIVE	J	B085-01-0/731	CER - Signals Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
67792	ACTIVE	J	B085-01-0/731	CER - Signals Building - Queensbury Stn	Boarding / Panels	Asbestos	Presumed				Asbestos - P - Paxoline Boards throughout room					



Hazardous Material Asset Register - Summary



B085-02 - Signals Building - Queensbury Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3116	ACTIVE	J	B085-02-A/711	SER - Signals Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1157	ACTIVE	J	B085-02-A/711/WAL-004	Wall: Internal - 4 - SER - Signals Building - Queensbury Stn	Isolator Switches	Asbestos	Strongly Presumed				Switch box insulation within (30amp)		1			

B085-03 - Signals Building - Queensbury Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3117	ACTIVE	J	B085-03-0/661	SER - Signals Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3118	ACTIVE	J	B085-03-0/663	UPS Room - Signals Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
67791	ACTIVE	J	B085-03-0/663	UPS Room - Signals Building - Queensbury Stn	Other Electrical Boxes	Asbestos	Presumed				all 4 Asbestos - SP - 1x Switch box Insulation within (30amp)		1			

B085-04 - Electrical Building - Queensbury Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3119	ACTIVE	J	B085-04-0/761	Electrical Intake Room - Electrical Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3120	ACTIVE	J	B085-04-0/781	Switch Room - Electrical Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B085-06 - Signals Building - Queensbury Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3121	ACTIVE	J	B085-06-A/713	SER - Signals Building - Queensbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B087-01 - Signals Building - Kingsbury Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
45163	ACTIVE	J	B087-00-0/662/WAL-001	Wall: Internal - 1 - CER - Signals Building - Kingsbury Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				2x Isolators (1x 30amp)				N	N



Hazardous Material Asset Register - Summary



B087-01 - Signals Building - Kingsbury Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
45159	ACTIVE	J	B087-00-0/731	CER - Signals Building - Kingsbury Stn	Other Boarding	Asbestos	Presumed				Paxoline boards throughout room				N	N

B087-03 - Signal Cabin - Kingsbury Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3165	ACTIVE	J	B087-03-2/701	IMR - Signal Cabin - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2579	ACTIVE	J	B087-03-2/701/CLG-01	Ceiling: Suspended - 1 - IMR - Signal Cabin - Kingsbury Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1295	ACTIVE	J	B087-03-2/701/CLG-01	Ceiling: Suspended - 1 - IMR - Signal Cabin - Kingsbury Stn	Void	Asbestos	Surveyed – Not Detected				Concrete aboveSupalux				Yes	

B087-09 - Signals Building - Kingsbury Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3166	ACTIVE	J	B087-09-2/712	SER - Signals Building - Kingsbury Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2885	ACTIVE	J	B087-09-2/712	SER - Signals Building - Kingsbury Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					

B088-01 - Signals Building - Kingsbury To Wembley Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3167	ACTIVE	J	B088-01-0/711	Relay Room - Signals Building - Kingsbury To Wembley Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B088-02 - Signals Building - Kingsbury To Wembley Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3168	ACTIVE	J	B088-02-0/081	Lobby - Signals Building - Kingsbury To Wembley Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3169	ACTIVE	J	B088-02-0/316	Locker Room - Signals Building - Kingsbury To Wembley Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B088-02 - Signals Building - Kingsbury To Wembley Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3170	ACTIVE	J	B088-02-0/371	Store - Signals Building - Kingsbury To Wembley Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3171	ACTIVE	J	B088-02-0/416	Shower Room - Signals Building - Kingsbury To Wembley Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3172	ACTIVE	J	B088-02-0/417	Shower Room - Signals Building - Kingsbury To Wembley Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3173	ACTIVE	J	B088-02-0/561	Workshop - Signals Building - Kingsbury To Wembley Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3174	ACTIVE	J	B088-02-0/571	Store - Signals Building - Kingsbury To Wembley Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B088-03 - Store - Kingsbury To Wembley Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3175	ACTIVE	J	B088-03-0/712	SER - Kingsbury To Wembley Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3176	ACTIVE	J	B088-03-0/714	Store Room - Store - Kingsbury To Wembley Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B088-04 - Store - Kingsbury To Wembley Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3177	ACTIVE	J	B088-04-0/713	Store Room - Store - Kingsbury To Wembley Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B088-05 - Electrical Building - Kingsbury To Wembley Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3178	ACTIVE	J	B088-05-0/662	Electrical Intake Room - Electrical Building - Kingsbury To Wembley Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3179	ACTIVE	J	B088-05-0/663	Electrical Intake Room - Electrical Building - Kingsbury To Wembley Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B088-06 - Signals Building - Kingsbury To Wembley Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3180	ACTIVE	J	B088-06-0/662	Switch Room - Signals Building - Kingsbury To Wembley Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3181	ACTIVE	J	B088-06-0/731	CER - Signals Building - Kingsbury To Wembley Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B088-08 - Signals Building (KIN) - Kingsbury To Wembley Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3183	ACTIVE	J	B088-08-2/712	SER - Signals Building (KIN) - Kingsbury To Wembley Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B088-11 - Signals Building - Kingsbury To Wembley Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3184	ACTIVE	J	B088-11-1/711	SER - Signals Building - Kingsbury To Wembley Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B091-02 - Signals Building - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3342	ACTIVE	J	B091-02-0/661	Switch Room - Signals Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B091-03 - Crowne House - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3343	ACTIVE	J	B091-03-1/081	Lobby - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3344	ACTIVE	J	B091-03-1/082	Lobby - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3345	ACTIVE	J	B091-03-1/083	Lobby - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B091-03 - Crowne House - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3346	ACTIVE	J	B091-03-1/084	Lobby - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3347	ACTIVE	J	B091-03-1/085	Lobby - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3348	ACTIVE	J	B091-03-1/086	Lobby - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3349	ACTIVE	J	B091-03-1/237	Passage - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3350	ACTIVE	J	B091-03-1/316	Locker Room - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3351	ACTIVE	J	B091-03-1/317	Locker Room - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3352	ACTIVE	J	B091-03-1/318	Locker Room - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3353	ACTIVE	J	B091-03-1/406	Store - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3354	ACTIVE	J	B091-03-1/420	Toilet - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3355	ACTIVE	J	B091-03-1/421	Shower Room - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3356	ACTIVE	J	B091-03-1/422	Shower Room - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3357	ACTIVE	J	B091-03-1/481	Store - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3358	ACTIVE	J	B091-03-1/576	Stairs: Linear - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3359	ACTIVE	J	B091-03-1/577	Stairs: Linear - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3360	ACTIVE	J	B091-03-1/578	Stairs: Linear - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B091-03 - Crowne House - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3361	ACTIVE	J	B091-03-1/664	Switch Room - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3362	ACTIVE	J	B091-03-1/665	Switch Room - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3363	ACTIVE	J	B091-03-1/666	Switch Room - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3364	ACTIVE	J	B091-03-1/731	CER - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3365	ACTIVE	J	B091-03-1/776	Plant Room - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3366	ACTIVE	J	B091-03-1/802	Office - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3367	ACTIVE	J	B091-03-1/803	Office - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3368	ACTIVE	J	B091-03-1/804	Office - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3369	ACTIVE	J	B091-03-1/805	Office - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3370	ACTIVE	J	B091-03-1/901	Service Riser - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3371	ACTIVE	J	B091-03-A/041	Mess Room - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3372	ACTIVE	J	B091-03-A/042	Toilet - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3373	ACTIVE	J	B091-03-A/044	Office - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3374	ACTIVE	J	B091-03-A/045	Office - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3375	ACTIVE	J	B091-03-A/047	Kitchen - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B091-03 - Crowne House - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3376	ACTIVE	J	B091-03-A/050	Store - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3377	ACTIVE	J	B091-03-A/056	Toilet: Unisex - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3378	ACTIVE	J	B091-03-A/085	Lobby - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3379	ACTIVE	J	B091-03-A/086	Lobby - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3380	ACTIVE	J	B091-03-A/087	Lobby - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3381	ACTIVE	J	B091-03-A/090	Lobby - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3382	ACTIVE	J	B091-03-A/236	Passage - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3383	ACTIVE	J	B091-03-A/237	Lobby - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3384	ACTIVE	J	B091-03-A/238	Lobby - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3385	ACTIVE	J	B091-03-A/239	Lobby - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3386	ACTIVE	J	B091-03-A/240	Lobby - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3387	ACTIVE	J	B091-03-A/241	Lobby - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3388	ACTIVE	J	B091-03-A/242	Passage - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3389	ACTIVE	J	B091-03-A/316	Locker Room - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3390	ACTIVE	J	B091-03-A/317	Locker Room - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B091-03 - Crowne House - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3391	ACTIVE	J	B091-03-A/318	Locker Room - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3392	ACTIVE	J	B091-03-A/331	Meeting Room - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3393	ACTIVE	J	B091-03-A/351	Mess Room - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3394	ACTIVE	J	B091-03-A/352	Mess Room - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3395	ACTIVE	J	B091-03-A/353	Mess Room - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3396	ACTIVE	J	B091-03-A/407	Store - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3397	ACTIVE	J	B091-03-A/411	Office - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3398	ACTIVE	J	B091-03-A/416	Toilet: Male - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3399	ACTIVE	J	B091-03-A/417	Toilet: Male - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3400	ACTIVE	J	B091-03-A/418	Toilet: Female - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3401	ACTIVE	J	B091-03-A/419	Shower Room - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3402	ACTIVE	J	B091-03-A/420	Toilet: Disabled - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3403	ACTIVE	J	B091-03-A/422	Toilet: Unisex - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3404	ACTIVE	J	B091-03-A/423	Shower Room - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3405	ACTIVE	J	B091-03-A/531	Mess Room - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B091-03 - Crowne House - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3406	ACTIVE	J	B091-03-A/532	Booking On Point - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3407	ACTIVE	J	B091-03-A/576	Stairs: Linear - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3408	ACTIVE	J	B091-03-A/577	Stairs: Linear - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3409	ACTIVE	J	B091-03-A/661	Switch Room - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3410	ACTIVE	J	B091-03-A/805	Train Ops Manager Office - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3411	ACTIVE	J	B091-03-A/807	Train Ops Manager Office - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3412	ACTIVE	J	B091-03-A/808	DSM Office - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3413	ACTIVE	J	B091-03-A/809	Office - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3414	ACTIVE	J	B091-03-A/810	Office - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3415	ACTIVE	J	B091-03-A/811	Union Office - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3416	ACTIVE	J	B091-03-A/901	Office - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3417	ACTIVE	J	B091-03-A/902	Equipment Room - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3418	ACTIVE	J	B091-03-A/903	Service Riser - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3419	ACTIVE	J	B091-03-A/904	Switch Cupboard - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3420	ACTIVE	J	B091-03-A/905	Store - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B091-03 - Crowne House - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3421	ACTIVE	J	B091-03-A/906	Locker Room - Crowne House - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B091-04 - Store - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3422	ACTIVE	J	B091-04-0/571	Store Room - Store - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B091-05 - Signals Building - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3423	ACTIVE	J	B091-05-0/041	Mess Room - Signals Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3424	ACTIVE	J	B091-05-0/047	Kitchen - Signals Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3425	ACTIVE	J	B091-05-0/236	Passage - Signals Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3426	ACTIVE	J	B091-05-0/237	Passage - Signals Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3427	ACTIVE	J	B091-05-0/316	Locker Room - Signals Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3428	ACTIVE	J	B091-05-0/371	Store - Signals Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3429	ACTIVE	J	B091-05-0/416	Toilet: Unisex - Signals Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3430	ACTIVE	J	B091-05-0/417	Toilet: Unisex - Signals Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3431	ACTIVE	J	B091-05-0/418	Cleaners Room - Signals Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3432	ACTIVE	J	B091-05-0/571	Store - Signals Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B091-05 - Signals Building - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3433	ACTIVE	J	B091-05-0/572	Store - Signals Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3434	ACTIVE	J	B091-05-0/661	Switch Room - Signals Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3435	ACTIVE	J	B091-05-0/761	Equipment Room - Signals Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3436	ACTIVE	J	B091-05-0/801	Signals Office - Signals Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3437	ACTIVE	J	B091-05-0/802	Signals Office - Signals Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B091-07 - Signals Building - Wembley Park Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3438	ACTIVE	J	B091-07-0/711	SER - Signals Building - Wembley Park Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B092-02 - Pump House - Wembley Park To Neasden

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3568	ACTIVE	J	B092-02-0/131	Pump Room - Pump House - Wembley Park To Neasden	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B092-03 - Pump House North - Wembley Park To Neasden

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3569	ACTIVE	J	B092-03-1/771	Pump Room - Pump House North - Wembley Park To Neasden	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3570	ACTIVE	J	B092-03-A/761	Plant Room - Pump House North - Wembley Park To Neasden	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B092-04 - Electrical Building - Wembley Park To Neasden

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3571	ACTIVE	J	B092-04-0/711	Relay Room - Electrical Building - Wembley Park To Neasden	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B092-07 - Signal Cabin - Wembley Park To Neasden

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3572	ACTIVE	J	B092-07-0/711	SER - Signal Cabin - Wembley Park To Neasden	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B092-09 - Signals Building - Wembley Park To Neasden

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3573	ACTIVE	J	B092-09-0/711	SER - Signals Building - Wembley Park To Neasden	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B093-01 - Signals Building - Neasden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3618	ACTIVE	J	B093-01-0/711	SER - Signals Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3619	ACTIVE	J	B093-01-1/711	Relay Room - Signals Building - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B093-02 - Pump House South - Neasden Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3620	ACTIVE	J	B093-02-2/771	Pump Room - Pump House South - Neasden Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B095-01 - Signals Building - Dollis Hill Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3651	ACTIVE	J	B095-01-0/713	Relay Room - Signals Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B095-02 - Signals Building - Dollis Hill Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3652	ACTIVE	J	B095-02-0/711	Relay Room - Signals Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
67868	ACTIVE	J	B095-02-0/711/WAL-001	Wall: Internal - 1 - Relay Room - Signals Building - Dollis Hill Stn	Other Electrical Boxes	Asbestos	Presumed				Combination fuse switch boxes. 2x Grey on wall 1. Re-inspection by HMT.		2			
3653	ACTIVE	J	B095-02-0/731	CER - Signals Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B095-03 - Substation - Dollis Hill Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3654	ACTIVE	J	B095-03-1/781	Substation Room - Substation - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B095-04 - Signals Building - Dollis Hill Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3655	ACTIVE	J	B095-04-A/711	Relay Room - Signals Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B095-05 - Signals Building - Dollis Hill Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3656	ACTIVE	J	B095-05-0/712	SER - Signals Building - Dollis Hill Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B096-01 - Signals Building - Dollis Hill To Willesden Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3657	ACTIVE	J	B096-01-0/711	Relay Room - Signals Building - Dollis Hill To Willesden Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B096-02 - Signals Building - Dollis Hill To Willesden Green

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3658	ACTIVE	J	B096-02-1/711	SCR - Signals Building - Dollis Hill To Willesden Green	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B097-01 - Signals Building - Willesden Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3742	ACTIVE	J	B097-01-1/706	IMR - Signals Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Surveyed – No Known Asbestos				HMU re inspection 17/02/2015 - NAD					
1322	ACTIVE	J	B097-01-1/706	IMR - Signals Building - Willesden Green Stn	No Access	Asbestos	No Access: Presumed				Room Not Surveyed					
3743	ACTIVE	J	B097-01-1/731	CER - Signals Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3744	ACTIVE	J	B097-01-1/732	CER - Signals Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1324	ACTIVE	J	B097-01-1/732/WAL-004	Wall: Internal - 4 - CER - Signals Building - Willesden Green Stn	Isolator Switches	Asbestos	Strongly Presumed				Combination fuse switch x 2 - SP 2 x 60 amp		2			
3745	ACTIVE	J	B097-01-2/661	Switch Room - Signals Building - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B097-03 - Signal Cabin - Willesden Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3746	ACTIVE	J	B097-03-1/085	Lobby - Signal Cabin - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3747	ACTIVE	J	B097-03-1/237	Passage - Signal Cabin - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2717	ACTIVE	J	B097-03-1/237	Passage - Signal Cabin - Willesden Green Stn	LUL Heaters	Asbestos	Surveyed – Not Detected						1			
1219	ACTIVE	J	B097-03-1/237/CLG-01	Ceiling: Solid - 1 - Passage - Signal Cabin - Willesden Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux		1		Yes	
1218	ACTIVE	J	B097-03-1/237/CLG-01	Ceiling: Solid - 1 - Passage - Signal Cabin - Willesden Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									



Hazardous Material Asset Register - Summary



B097-03 - Signal Cabin - Willesden Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3748	ACTIVE	J	B097-03-1/301	Office - Signal Cabin - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2718	ACTIVE	J	B097-03-1/301/CLG-01	Ceiling: Solid - 1 - Office - Signal Cabin - Willesden Green Stn	Void	Asbestos	No Access: Presumed				Concrete - above Supalux		1		Yes	
1220	ACTIVE	J	B097-03-1/301/CLG-01	Ceiling: Solid - 1 - Office - Signal Cabin - Willesden Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected								yes	
3749	ACTIVE	J	B097-03-1/361	Mess Room - Signal Cabin - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2719	ACTIVE	J	B097-03-1/361	Mess Room - Signal Cabin - Willesden Green Stn		Asbestos	Surveyed – Not Detected				Sink Panels x 2 - Non Asbestos		2			
1224	ACTIVE	J	B097-03-1/361/CLG-01	Ceiling: Solid - 1 - Mess Room - Signal Cabin - Willesden Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux		1		Yes	
1223	ACTIVE	J	B097-03-1/361/CLG-01	Ceiling: Solid - 1 - Mess Room - Signal Cabin - Willesden Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected								yes	
3750	ACTIVE	J	B097-03-1/416	Toilet: Male - Signal Cabin - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1227	ACTIVE	J	B097-03-1/416/CLG-01	Ceiling: Solid - 1 - Toilet - Signal Cabin - Willesden Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2720	ACTIVE	J	B097-03-1/416/CLG-01	Ceiling: Solid - 1 - Toilet - Signal Cabin - Willesden Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux		1		Yes	
3751	ACTIVE	J	B097-03-1/417	Toilet: Female - Signal Cabin - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1228	ACTIVE	J	B097-03-1/417/CLG-01	Ceiling: Solid - 1 - Toilet - Signal Cabin - Willesden Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
2417	ACTIVE	J	B097-03-1/417/CLG-01	Ceiling: Solid - 1 - Toilet - Signal Cabin - Willesden Green Stn	Void	Asbestos	Surveyed – Not Detected				Concrete above Supalux		1		Yes	
3752	ACTIVE	J	B097-03-1/801	P Way Office - Signal Cabin - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2589	ACTIVE	J	B097-03-1/801	P Way Office - Signal Cabin - Willesden Green Stn	LUL Heaters	Asbestos	Surveyed – Not Detected						1			
1325	ACTIVE	J	B097-03-1/801/CLG-01	Ceiling: Solid - 1 - P Way Office - Signal Cabin - Willesden Green Stn	Boarding: Supalux	Asbestos	Surveyed – Not Detected									
1326	ACTIVE	J	B097-03-1/801/CLG-01	Ceiling: Solid - 1 - P Way Office - Signal Cabin - Willesden Green Stn	Void	Asbestos	No Access: Presumed				Above - Supalux Ceiling				Yes	



Hazardous Material Asset Register - Summary



B097-03 - Signal Cabin - Willesden Green Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3753	ACTIVE	J	B097-03-2/236	Passage - Signal Cabin - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3754	ACTIVE	J	B097-03-2/662	Switch Room - Signal Cabin - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1450	ACTIVE	J	B097-03-2/662/WAL-004	Wall: Internal - 4 - Switch Room - Signal Cabin - Willesden Green Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x Combination fuse switches - 1x 30 amps, 1 x 60amps		2			
3755	ACTIVE	J	B097-03-2/663	Switch Room - Signal Cabin - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3756	ACTIVE	J	B097-03-2/731	SER - Signal Cabin - Willesden Green Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B102-05 - Signal Cabin - Willesden Green To Kilburn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3757	ACTIVE	J	B102-05-2/731	SER - Signal Cabin - Willesden Green To Kilburn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B103-01 - Substation - Kilburn Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3800	ACTIVE	J	B103-01-0/713	SER - Substation - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3801	ACTIVE	J	B103-01-1/781	Electrical Room - Substation - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B103-02 - Signals Building - Kilburn Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3802	ACTIVE	J	B103-02-0/711	Relay Room - Signals Building - Kilburn Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed				No access - survey required.					



Hazardous Material Asset Register - Summary



B104-02 - Signals Building - Kilburn To West Hampstead

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3803	ACTIVE	J	B104-02-1/661	UPS Room - Signals Building - Kilburn To West Hampstead	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B105-01 - Signals Building - West Hampstead Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3841	ACTIVE	J	B105-01-0/711	CER - Signals Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3842	ACTIVE	J	B105-01-1/711	Relay Room - Signals Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2886	ACTIVE	J	B105-01-1/711	Relay Room - Signals Building - West Hampstead Stn	Void	Asbestos	No Access: Presumed				No Access behind Metal Sheeting					
1370	ACTIVE	J	B105-01-1/711	Relay Room - Signals Building - West Hampstead Stn	Other Boarding	Asbestos	Surveyed – Not Detected				Paxoline Board					

B105-03 - Signals Building - West Hampstead Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3843	ACTIVE	J	B105-03-1/662	Switch Room - Signals Building - West Hampstead Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
1367	ACTIVE	J	B105-03-1/662/WAL-002	Wall: Internal - 2 - Switch Room - Signals Building - West Hampstead Stn	Isolator Switches	Asbestos	Strongly Presumed				W2 1 x 20 Box only		1		N	N
2660	INACTIVE	J	B105-03-1/662/WAL-003	Wall: Internal - 3 - Switch Room - Signals Building - West Hampstead Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x Isolator Switches		2		N	N

B106-01 - Signals Building - West Hampstead To Finchley Road

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3844	ACTIVE	J	B106-01-0/706	Equipment Room - Signals Building - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3845	ACTIVE	J	B106-01-0/711	CER - Signals Building - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B106-02 - Signals Building - West Hampstead To Finchley Road

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3846	ACTIVE	J	B106-02-0/706	IMR - Signals Building - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3847	ACTIVE	J	B106-02-1/416	Toilet: Male - Signals Building - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3848	ACTIVE	J	B106-02-1/417	Toilet: Female - Signals Building - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3849	ACTIVE	J	B106-02-1/661	Switch Room - Signals Building - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3850	ACTIVE	J	B106-02-1/711	Relay Room - Signals Building - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3851	ACTIVE	J	B106-02-1/801	Office - Signals Building - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B106-04 - Signals Building - West Hampstead To Finchley Road

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3852	ACTIVE	J	B106-04-1/081	Lobby - Signals Building - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3853	ACTIVE	J	B106-04-1/576	Stairs: Linear - Signals Building - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3854	ACTIVE	J	B106-04-1/711	SER - Signals Building - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3855	ACTIVE	J	B106-04-A/711	CER - Signals Building - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B106-05 - Substation - West Hampstead To Finchley Road

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3856	ACTIVE	J	B106-05-1/781	Substation Room - Substation - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B106-06 - Signals Building - West Hampstead To Finchley Road

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3857	ACTIVE	J	B106-06-0/711	UPS Room - Signals Building - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3858	ACTIVE	J	B106-06-0/731	CER - Signals Building - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B106-07 - Signal Cabin - West Hampstead To Finchley Road

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3859	ACTIVE	J	B106-07-1/081	Passage - Signal Cabin - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3860	ACTIVE	J	B106-07-1/661	Switch Room - Signals Cabin - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3861	ACTIVE	J	B106-07-1/662	UPS Room - Signals Cabin - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3862	ACTIVE	J	B106-07-1/712	SER - Signals Cabin - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3863	ACTIVE	J	B106-07-1/731	CER - Signals Cabin - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3864	ACTIVE	J	B106-07-1/761	Equipment Room - Signals Cabin - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3865	ACTIVE	J	B106-07-1/781	Transformer Room - Signals Cabin - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3866	ACTIVE	J	B106-07-A/047	Kitchen - Signals Cabin - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3867	ACTIVE	J	B106-07-A/082	Lobby - Signals Cabin - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3868	ACTIVE	J	B106-07-A/236	Passage - Signal Cabin - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3869	ACTIVE	J	B106-07-A/416	Toilet: Male - Signal Cabin - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B106-07 - Signal Cabin - West Hampstead To Finchley Road

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3870	ACTIVE	J	B106-07-A/417	Shower Room - Signals Cabin - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3871	ACTIVE	J	B106-07-A/418	Toilet: Female - Signal Cabin - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3872	ACTIVE	J	B106-07-A/551	Passage - Signal Cabin - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3873	ACTIVE	J	B106-07-A/576	Stairs: Linear - Signal Cabin - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3874	ACTIVE	J	B106-07-A/801	Office - Signals Cabin - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3875	ACTIVE	J	B106-07-A/802	Office - Signals Cabin - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3876	ACTIVE	J	B106-07-A/951	Disused Room - Signals Cabin - West Hampstead To Finchley Road	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B114-01 - Lission Green Vent Shaft - St Johns Wood To Baker Street

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4069	ACTIVE	J	B114-01-1/576	Stairs: Linear - Lission Green Vent Shaft - St Johns Wood To Baker Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

C091-01 - Train Crew Accommodation - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4334	ACTIVE	J	C091-01-1/081	Lobby - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4335	ACTIVE	J	C091-01-1/236	Passage - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4336	ACTIVE	J	C091-01-1/237	Passage - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4337	ACTIVE	J	C091-01-1/331	Mess Room - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



C091-01 - Train Crew Accommodation - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4338	ACTIVE	J	C091-01-1/371	SER - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4339	ACTIVE	J	C091-01-1/372	Store - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4340	ACTIVE	J	C091-01-1/396	SVC - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4341	ACTIVE	J	C091-01-1/401	Store - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4342	ACTIVE	J	C091-01-1/406	Store - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4343	ACTIVE	J	C091-01-1/411	Store - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4344	ACTIVE	J	C091-01-1/412	Store - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4345	ACTIVE	J	C091-01-1/416	Toilet: Female - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4346	ACTIVE	J	C091-01-1/576	Stairs: Linear - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4347	ACTIVE	J	C091-01-1/577	Stairs: Linear - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4348	ACTIVE	J	C091-01-1/578	Stairs: Linear - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4349	ACTIVE	J	C091-01-1/661	Switch Room - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4350	ACTIVE	J	C091-01-1/662	Switch Room - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4351	ACTIVE	J	C091-01-1/663	Switch Room - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4352	ACTIVE	J	C091-01-1/664	Switch Room - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



C091-01 - Train Crew Accommodation - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4353	ACTIVE	J	C091-01-1/665	Switch Room - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4354	ACTIVE	J	C091-01-1/666	Switch Room - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4355	ACTIVE	J	C091-01-1/701	SER - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4356	ACTIVE	J	C091-01-1/731	CER - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4357	ACTIVE	J	C091-01-1/732	CER - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4358	ACTIVE	J	C091-01-1/733	CER - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4359	ACTIVE	J	C091-01-1/734	CER - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4360	ACTIVE	J	C091-01-1/776	Plant Room - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4361	ACTIVE	J	C091-01-1/777	Plant Room - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4362	ACTIVE	J	C091-01-1/786	Office - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4363	ACTIVE	J	C091-01-1/788	Service Riser - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4364	ACTIVE	J	C091-01-1/903	Store - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4365	ACTIVE	J	C091-01-A/047	Kitchen - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4366	ACTIVE	J	C091-01-A/053	Office - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4367	ACTIVE	J	C091-01-A/081	Lobby - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



C091-01 - Train Crew Accommodation - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4368	ACTIVE	J	C091-01-A/236	Passage - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4369	ACTIVE	J	C091-01-A/291	Signals Office - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4370	ACTIVE	J	C091-01-A/316	Locker Room - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4371	ACTIVE	J	C091-01-A/317	Locker Room - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4372	ACTIVE	J	C091-01-A/318	Locker Room - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4373	ACTIVE	J	C091-01-A/319	Locker Room - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4374	ACTIVE	J	C091-01-A/351	Kitchen - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4375	ACTIVE	J	C091-01-A/371	Office - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4376	ACTIVE	J	C091-01-A/411	Locker Room - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4377	ACTIVE	J	C091-01-A/416	Locker Room - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4378	ACTIVE	J	C091-01-A/417	Toilet: Male - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4379	ACTIVE	J	C091-01-A/418	Toilet: Unisex - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4380	ACTIVE	J	C091-01-A/419	Disused Room - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4381	ACTIVE	J	C091-01-A/420	Switch Cupboard - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4382	ACTIVE	J	C091-01-A/421	Toilet: Unisex - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



C091-01 - Train Crew Accommodation - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4383	ACTIVE	J	C091-01-A/422	Toilet: Unisex - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4384	ACTIVE	J	C091-01-A/423	Shower Room - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4385	ACTIVE	J	C091-01-A/501	Office - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4386	ACTIVE	J	C091-01-A/786	Service Riser - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4387	ACTIVE	J	C091-01-A/801	Signals Office - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4388	ACTIVE	J	C091-01-A/802	Office - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4389	ACTIVE	J	C091-01-A/803	Office - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4390	ACTIVE	J	C091-01-A/804	Office - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4391	ACTIVE	J	C091-01-A/805	Training Room - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4392	ACTIVE	J	C091-01-A/901	Train Ops Manager Office - Train Crew Accommodation - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

C091-02 - Fleet House - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4393	ACTIVE	J	C091-02-1/071	Circulation Area - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4394	ACTIVE	J	C091-02-1/236	Passage - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4395	ACTIVE	J	C091-02-1/237	Passage - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



C091-02 - Fleet House - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4396	ACTIVE	J	C091-02-1/291	DMT Office - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4397	ACTIVE	J	C091-02-1/292	Mobile DMT Office - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4398	ACTIVE	J	C091-02-1/293	Train Ops Manager Office - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4399	ACTIVE	J	C091-02-1/294	Interview Room - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4400	ACTIVE	J	C091-02-1/311	Train Ops Support Manager Office - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4401	ACTIVE	J	C091-02-1/316	Locker Room - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4402	ACTIVE	J	C091-02-1/331	Mess Room - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4403	ACTIVE	J	C091-02-1/371	Store - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4404	ACTIVE	J	C091-02-1/372	Store - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4405	ACTIVE	J	C091-02-1/373	Store - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4406	ACTIVE	J	C091-02-1/406	Cleaners Room - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4407	ACTIVE	J	C091-02-1/407	Cleaners Room - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4408	ACTIVE	J	C091-02-1/416	Toilet: Disabled - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4409	ACTIVE	J	C091-02-1/576	Stairs: Linear - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4410	ACTIVE	J	C091-02-1/577	Stairs: Linear - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



C091-02 - Fleet House - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4411	ACTIVE	J	C091-02-1/731	CER - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4412	ACTIVE	J	C091-02-1/761	Equipment Room - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4413	ACTIVE	J	C091-02-1/762	Equipment Room - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4414	ACTIVE	J	C091-02-1/776	Plant Room - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4415	ACTIVE	J	C091-02-1/786	Service Riser - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4416	ACTIVE	J	C091-02-A/081	Lobby - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4417	ACTIVE	J	C091-02-A/082	Lobby - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4418	ACTIVE	J	C091-02-A/236	Passage - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4419	ACTIVE	J	C091-02-A/237	Passage - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4420	ACTIVE	J	C091-02-A/316	Locker Room - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4421	ACTIVE	J	C091-02-A/317	Locker Room - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4422	ACTIVE	J	C091-02-A/331	Mess Room - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4423	ACTIVE	J	C091-02-A/332	Mess Room - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4424	ACTIVE	J	C091-02-A/333	Mess Room - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4425	ACTIVE	J	C091-02-A/406	Cleaners Room - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



C091-02 - Fleet House - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4426	ACTIVE	J	C091-02-A/407	Cleaners Room - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4427	ACTIVE	J	C091-02-A/416	Toilet: Male - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4428	ACTIVE	J	C091-02-A/417	Toilet: Disabled - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4429	ACTIVE	J	C091-02-A/418	Toilet: Female - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4430	ACTIVE	J	C091-02-A/419	Shower Room - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4431	ACTIVE	J	C091-02-A/420	Toilet: Disabled - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4432	ACTIVE	J	C091-02-A/571	Store - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4433	ACTIVE	J	C091-02-A/572	Store - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4434	ACTIVE	J	C091-02-A/786	Service Riser - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4435	ACTIVE	J	C091-02-A/801	Union Office - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4436	ACTIVE	J	C091-02-A/802	Server Room - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4437	ACTIVE	J	C091-02-B/041	Mess Room - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4438	ACTIVE	J	C091-02-B/047	Kitchen - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4439	ACTIVE	J	C091-02-B/050	Store - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4440	ACTIVE	J	C091-02-B/081	Lobby - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



C091-02 - Fleet House - Stratford Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
4441	ACTIVE	J	C091-02-B/082	Lobby - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4442	ACTIVE	J	C091-02-B/083	Lobby - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4443	ACTIVE	J	C091-02-B/236	Passage - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4444	ACTIVE	J	C091-02-B/316	Locker Room - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4445	ACTIVE	J	C091-02-B/331	Mess Room - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4446	ACTIVE	J	C091-02-B/406	Cleaners Room - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4447	ACTIVE	J	C091-02-B/416	Toilet: Female - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4448	ACTIVE	J	C091-02-B/417	Toilet: Male - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4449	ACTIVE	J	C091-02-B/418	Toilet: Disabled - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4450	ACTIVE	J	C091-02-B/419	Toilet: Unisex - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4451	ACTIVE	J	C091-02-B/786	Service Riser - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4452	ACTIVE	J	C091-02-B/801	Manager Office - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4453	ACTIVE	J	C091-02-B/802	Training Manager Office - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4454	ACTIVE	J	C091-02-B/803	Training Room - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
4455	ACTIVE	J	C091-02-B/804	Training Room - Fleet House - Stratford Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



F042-01 - Park Square Gardens Vent Shaft - Baker Street To Bond Street

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6156	ACTIVE	J	F042-01-1/661	Switch Cupboard - Park Square Gardens Vent Shaft - Baker Street To Bond Street	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

F046-01 - Cambridge Green Vent Shaft - Green Park To Charing Cross

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6158	ACTIVE	J	F046-01-1/081	Lobby - Cambridge Green Vent Shaft - Green Park To Charing Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6159	ACTIVE	J	F046-01-1/401	Store - Cambridge Green Vent Shaft - Green Park To Charing Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6160	ACTIVE	J	F046-01-1/576	Stairs: Linear - Cambridge Green Vent Shaft - Green Park To Charing Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6161	ACTIVE	J	F046-01-1/661	Switch Room - Cambridge Green Vent Shaft - Green Park To Charing Cross	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

F048-01 - Southampton Street Vent Shaft - Charing Cross To Aldwych

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6162	ACTIVE	J	F048-01-1/551	Yard - Southampton Street Vent Shaft - Charing Cross To Aldwych	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6163	ACTIVE	J	F048-01-1/576	Stairs: Linear - Southampton Street Vent Shaft - Charing Cross To Aldwych	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6164	ACTIVE	J	F048-01-1/661	Switch Room - Southampton Street Vent Shaft - Charing Cross To Aldwych	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

J006-01 - Canning Town Portal Vent Shaft - Canning Town To North Greenwich

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6739	ACTIVE	J	J006-01-1/631	Stairs: Spiral - Canning Town Portal Vent Shaft - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6740	ACTIVE	J	J006-01-2/081	Lobby - Canning Town Portal Vent Shaft - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J006-01 - Canning Town Portal Vent Shaft - Canning Town To North Greenwich

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6741	ACTIVE	J	J006-01-2/661	Switch Room - Canning Town Portal Vent Shaft - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6742	ACTIVE	J	J006-01-2/776	Fan Room - Canning Town Portal Vent Shaft - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6743	ACTIVE	J	J006-01-3/081	Lobby - Canning Town Portal Vent Shaft - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6744	ACTIVE	J	J006-01-3/632	Stairs: Spiral - Canning Town Portal Vent Shaft - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6745	ACTIVE	J	J006-01-B/081	Lobby - Canning Town Portal Vent Shaft - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6746	ACTIVE	J	J006-01-B/082	Lobby - Canning Town Portal Vent Shaft - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6747	ACTIVE	J	J006-01-B/731	CER - Canning Town Portal Vent Shaft - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6748	ACTIVE	J	J006-01-B/776	Fan Room - Canning Town Portal Vent Shaft - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6749	ACTIVE	J	J006-01-B/777	Equipment Room - Canning Town Portal Vent Shaft - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6750	ACTIVE	J	J006-01-B/786	Service Riser - Canning Town Portal Vent Shaft - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6751	ACTIVE	J	J006-01-B/903	Plant Room - Canning Town Portal Vent Shaft - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

J006-02 - Canning Town Portal Tunnel Fan - Canning Town To North Greenwich

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6752	ACTIVE	J	J006-02-1/236	Passage - Canning Town Portal Tunnel Fan - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6753	ACTIVE	J	J006-02-1/576	Stairs: Linear - Canning Town Portal Tunnel Fan - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J006-02 - Canning Town Portal Tunnel Fan - Canning Town To North Greenwich

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6754	ACTIVE	J	J006-02-1/776	Fan Room - Canning Town Portal Tunnel Fan - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6755	ACTIVE	J	J006-02-1/777	Fan Room - Canning Town Portal Tunnel Fan - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6756	ACTIVE	J	J006-02-1/778	Air Plenum - Canning Town Portal Tunnel Fan - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6757	ACTIVE	J	J006-02-1/779	Air Plenum - Canning Town Portal Tunnel Fan - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6758	ACTIVE	J	J006-02-A/081	Lobby - Canning Town Portal Tunnel Fan - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6759	ACTIVE	J	J006-02-A/236	Passage - Canning Town Portal Tunnel Fan - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6760	ACTIVE	J	J006-02-A/237	Passage - Canning Town Portal Tunnel Fan - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6761	ACTIVE	J	J006-02-A/238	Passage - Canning Town Portal Tunnel Fan - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6762	ACTIVE	J	J006-02-A/239	Passage - Canning Town Portal Tunnel Fan - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6763	ACTIVE	J	J006-02-A/240	Passage - Canning Town Portal Tunnel Fan - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6764	ACTIVE	J	J006-02-A/576	Stairs: Linear - Canning Town Portal Tunnel Fan - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6765	ACTIVE	J	J006-02-A/661	Switch Room - Canning Town Portal Tunnel Fan - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6766	ACTIVE	J	J006-02-A/662	Switch Room - Canning Town Portal Tunnel Fan - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6767	ACTIVE	J	J006-02-A/663	Switch Room - Canning Town Portal Tunnel Fan - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6768	ACTIVE	J	J006-02-A/776	Fan Control Room - Canning Town Portal Tunnel Fan - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J006-02 - Canning Town Portal Tunnel Fan - Canning Town To North Greenwich

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6769	ACTIVE	J	J006-02-A/903	Void - Canning Town Portal Tunnel Fan - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6770	ACTIVE	J	J006-02-A/904	Void - Canning Town Portal Tunnel Fan - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

J006-03 - Canning Town Portal Floodgate Building - Canning Town To North Greenwich

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
6771	ACTIVE	J	J006-03-1/577	Stairs: Linear - Canning Town Portal Floodgate Building - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
6772	ACTIVE	J	J006-03-A/777	Plant Room - Canning Town Portal Floodgate Building - Canning Town To North Greenwich	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

J008-01 - Prestons Road Vent Shaft (Harbour Quay) - North Greenwich To Canary Wharf

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7213	ACTIVE	J	J008-01-1/236	Passage - Prestons Road Vent Shaft (Harbour Quay) - North Greenwich To Canary Wharf	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7214	ACTIVE	J	J008-01-1/631	Stairs: Spiral - Prestons Road Vent Shaft (Harbour Quay) - North Greenwich To Canary Wharf	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7215	ACTIVE	J	J008-01-1/661	Switch Room - Prestons Road Vent Shaft (Harbour Quay) - North Greenwich To Canary Wharf	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7216	ACTIVE	J	J008-01-1/662	Switch Room - Prestons Road Vent Shaft (Harbour Quay) - North Greenwich To Canary Wharf	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7217	ACTIVE	J	J008-01-1/776	Fan Room - Prestons Road Vent Shaft (Harbour Quay) - North Greenwich To Canary Wharf	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7218	ACTIVE	J	J008-01-1/786	Service Riser - Prestons Road Vent Shaft (Harbour Quay) - North Greenwich To Canary Wharf	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J008-01 - Prestons Road Vent Shaft (Harbour Quay) - North Greenwich To Canary Wharf

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7219	ACTIVE	J	J008-01-2/632	Stairs: Linear - Prestons Road Vent Shaft (Harbour Quay) - North Greenwich To Canary Wharf	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7220	ACTIVE	J	J008-01-3/081	Lobby - Prestons Road Vent Shaft - North Greenwich To Canary Wharf	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7221	ACTIVE	J	J008-01-3/082	Lobby - Prestons Road Vent Shaft (Harbour Quay) - North Greenwich To Canary Wharf	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7222	ACTIVE	J	J008-01-3/236	Passage - Prestons Road Vent Shaft (Harbour Quay) - North Greenwich To Canary Wharf	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7223	ACTIVE	J	J008-01-3/576	Stairs: Linear - Prestons Road Vent Shaft (Harbour Quay) - North Greenwich To Canary Wharf	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7224	ACTIVE	J	J008-01-4/081	Lobby - Prestons Road Vent Shaft (Harbour Quay) - North Greenwich To Canary Wharf	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7225	ACTIVE	J	J008-01-4/901	Plant Room - Prestons Road Vent Shaft (Harbour Quay) - North Greenwich To Canary Wharf	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7226	ACTIVE	J	J008-01-A/236	Passage - Prestons Road Vent Shaft (Harbour Quay) - North Greenwich To Canary Wharf	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7227	ACTIVE	J	J008-01-A/576	Stairs: Linear - Prestons Road Vent Shaft (Harbour Quay) - North Greenwich To Canary Wharf	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7228	ACTIVE	J	J008-01-A/661	Equipment Room - Prestons Road Vent Shaft (Harbour Quay) - North Greenwich To Canary Wharf	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7229	ACTIVE	J	J008-01-A/731	CER - Prestons Road Vent Shaft (Harbour Quay) - North Greenwich To Canary Wharf	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7230	ACTIVE	J	J008-01-A/776	Fan Room - Prestons Road Vent Shaft (Harbour Quay) - North Greenwich To Canary Wharf	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7231	ACTIVE	J	J008-01-A/777	Plant Room - Prestons Road Vent Shaft (Harbour Quay) - North Greenwich To Canary Wharf	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J008-01 - Prestons Road Vent Shaft (Harbour Quay) - North Greenwich To Canary Wharf

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7232	ACTIVE	J	J008-01-A/778	Service Riser - Prestons Road Vent Shaft (Harbour Quay) - North Greenwich To Canary Wharf	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7233	ACTIVE	J	J008-01-B/236	Passage - Prestons Road Vent Shaft (Harbour Quay) - North Greenwich To Canary Wharf	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7234	ACTIVE	J	J008-01-B/776	Fan Room - Prestons Road Vent Shaft (Harbour Quay) - North Greenwich To Canary Wharf	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7235	ACTIVE	J	J008-01-B/777	Fan Room - Prestons Road Vent Shaft (Harbour Quay) - North Greenwich To Canary Wharf	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

J011-01 - Ben Smith Way Vent Shaft - Bermondsey Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7635	ACTIVE	J	J011-01-1/081	Yard - Ben Smith Way Vent Shaft - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7636	ACTIVE	J	J011-01-1/631	Stairs: Spiral - Ben Smith Way Vent Shaft - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7637	ACTIVE	J	J011-01-2/081	Lobby - Ben Smith Way Vent Shaft - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7638	ACTIVE	J	J011-01-2/082	Lobby - Ben Smith Way Vent Shaft - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7639	ACTIVE	J	J011-01-2/416	Shower Room - Ben Smith Way Vent Shaft - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7640	ACTIVE	J	J011-01-2/661	Switch Cupboard - Ben Smith Way Vent Shaft - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7641	ACTIVE	J	J011-01-2/662	Switch Cupboard - Ben Smith Way Vent Shaft - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7642	ACTIVE	J	J011-01-2/771	Plant Room - Ben Smith Way Vent Shaft - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7643	ACTIVE	J	J011-01-2/776	Fan Room - Ben Smith Way Vent Shaft - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J011-01 - Ben Smith Way Vent Shaft - Bermondsey Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7644	ACTIVE	J	J011-01-5/081	Lobby - Ben Smith Way Vent Shaft - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7645	ACTIVE	J	J011-01-5/082	Lobby - Ben Smith Way Vent Shaft - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7646	ACTIVE	J	J011-01-5/083	Lobby - Ben Smith Way Vent Shaft - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7647	ACTIVE	J	J011-01-5/631	Stairs: Spiral - Ben Smith Way Vent Shaft - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7648	ACTIVE	J	J011-01-5/632	Stairs: Spiral - Ben Smith Way Vent Shaft - Bermondsey Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

J012-01 - Pioneer Wharf Vent Shaft - Canary Wharf To Canada Water

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7649	ACTIVE	J	J012-01-1/081	Lobby - Pioneer Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7650	ACTIVE	J	J012-01-1/082	Lobby - Pioneer Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7651	ACTIVE	J	J012-01-1/551	Yard - Pioneer Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7652	ACTIVE	J	J012-01-1/631	Stairs: Spiral - Pioneer Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7653	ACTIVE	J	J012-01-1/661	Switch Room - Pioneer Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7654	ACTIVE	J	J012-01-1/662	Switch Room - Pioneer Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7655	ACTIVE	J	J012-01-1/663	Equipment Room - Pioneer Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7656	ACTIVE	J	J012-01-1/731	SCR - Pioneer Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J012-01 - Pioneer Wharf Vent Shaft - Canary Wharf To Canada Water

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7657	ACTIVE	J	J012-01-1/776	Fan Room - Pioneer Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7658	ACTIVE	J	J012-01-1/786	Service Riser - Pioneer Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7659	ACTIVE	J	J012-01-2/081	Lobby - Pioneer Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7660	ACTIVE	J	J012-01-2/082	Lobby - Pioneer Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

J012-02 - Durands Wharf Vent Shaft - Canary Wharf To Canada Water

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7661	ACTIVE	J	J012-02-1/083	Lobby - Durands Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7662	ACTIVE	J	J012-02-1/236	Passage - Durands Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7663	ACTIVE	J	J012-02-1/552	Yard - Durands Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7664	ACTIVE	J	J012-02-1/553	Yard - Durands Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7665	ACTIVE	J	J012-02-1/576	Stairs: Linear - Durands Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7666	ACTIVE	J	J012-02-1/577	Stairs: Linear - Durands Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7667	ACTIVE	J	J012-02-1/664	Switch Room - Durands Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7668	ACTIVE	J	J012-02-1/665	Switch Room - Durands Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7669	ACTIVE	J	J012-02-2/083	Lobby - Durands Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J012-02 - Durands Wharf Vent Shaft - Canary Wharf To Canada Water

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7670	ACTIVE	J	J012-02-2/084	Lobby - Durands Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7671	ACTIVE	J	J012-02-2/236	Passage - Durands Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7672	ACTIVE	J	J012-02-2/576	Stairs: Linear - Durands Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7673	ACTIVE	J	J012-02-2/776	Equipment Room - Durands Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7674	ACTIVE	J	J012-02-2/777	Fan Room - Durands Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7675	ACTIVE	J	J012-02-2/778	Fan Room - Durands Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7676	ACTIVE	J	J012-02-3/236	Passage - Durands Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7677	ACTIVE	J	J012-02-3/661	Equipment Room - Durands Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7678	ACTIVE	J	J012-02-3/731	CER - Durands Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7679	ACTIVE	J	J012-02-3/776	Computer Equipment Cupboard - Durands Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7680	ACTIVE	J	J012-02-3/901	Disused Room - Durands Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7681	ACTIVE	J	J012-02-3/902	Disused Room - Durands Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7682	ACTIVE	J	J012-02-4/481	Stairs: Linear - Durands Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7683	ACTIVE	J	J012-02-5/083	Lobby - Durands Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7684	ACTIVE	J	J012-02-5/084	Lobby - Durands Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J012-02 - Durands Wharf Vent Shaft - Canary Wharf To Canada Water

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7685	ACTIVE	J	J012-02-6/771	Plant Room - Durands Wharf Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

J012-03 - Downtown Road Vent Shaft - Canary Wharf To Canada Water

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7686	ACTIVE	J	J012-03-1/084	Lobby - Downtown Road Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7687	ACTIVE	J	J012-03-1/085	Lobby - Downtown Road Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7688	ACTIVE	J	J012-03-1/555	Yard - Downtown Road Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7689	ACTIVE	J	J012-03-1/631	Stairs: Linear - Downtown Road Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7690	ACTIVE	J	J012-03-1/666	Switch Room - Downtown Road Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7691	ACTIVE	J	J012-03-1/667	Switch Room - Downtown Road Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7692	ACTIVE	J	J012-03-1/668	Switch Room - Downtown Road Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7693	ACTIVE	J	J012-03-1/731	CER - Downtown Road Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7694	ACTIVE	J	J012-03-1/777	Fan Room - Downtown Road Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7695	ACTIVE	J	J012-03-1/778	Air Plenum - Downtown Road Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7696	ACTIVE	J	J012-03-1/787	Service Riser - Downtown Road Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7697	ACTIVE	J	J012-03-2/085	Lobby - Downtown Road Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J012-03 - Downtown Road Vent Shaft - Canary Wharf To Canada Water

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7698	ACTIVE	J	J012-03-2/086	Lobby - Downtown Road Vent Shaft - Canary Wharf To Canada Water	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

J014-01 - Culling Road Vent Shaft - Canada Water To Bermondsey

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7888	ACTIVE	J	J014-01-1/081	Lobby - Culling Road Vent Shaft - Canada Water To Bermondsey	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7889	ACTIVE	J	J014-01-1/236	Passage - Culling Road Vent Shaft - Canada Water To Bermondsey	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7890	ACTIVE	J	J014-01-1/551	Yard - Culling Road Vent Shaft - Canada Water To Bermondsey	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7891	ACTIVE	J	J014-01-1/661	Switch Room - Culling Road Vent Shaft - Canada Water To Bermondsey	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7892	ACTIVE	J	J014-01-1/662	Switch Room - Culling Road Vent Shaft - Canada Water To Bermondsey	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7893	ACTIVE	J	J014-01-1/731	CER - Culling Road Vent Shaft - Canada Water To Bermondsey	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7894	ACTIVE	J	J014-01-1/761	Equipment Room - Culling Road Vent Shaft - Canada Water To Bermondsey	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7895	ACTIVE	J	J014-01-1/776	Fan Room - Culling Road Vent Shaft - Canada Water To Bermondsey	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7896	ACTIVE	J	J014-01-1/777	Fan Room - Culling Road Vent Shaft - Canada Water To Bermondsey	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7897	ACTIVE	J	J014-01-1/778	Plant Room - Culling Road Vent Shaft - Canada Water To Bermondsey	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7898	ACTIVE	J	J014-01-1/786	Service Riser - Culling Road Vent Shaft - Canada Water To Bermondsey	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7899	ACTIVE	J	J014-01-1/787	Service Riser - Culling Road Vent Shaft - Canada Water To Bermondsey	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J014-01 - Culling Road Vent Shaft - Canada Water To Bermondsey

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7900	ACTIVE	J	J014-01-2/081	Lobby - Culling Road Vent Shaft - Canada Water To Bermondsey	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7901	ACTIVE	J	J014-01-2/082	Lobby - Culling Road Vent Shaft - Canada Water To Bermondsey	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7902	ACTIVE	J	J014-01-2/236	Passage - Culling Road Vent Shaft - Canada Water To Bermondsey	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

J016-01 - Druid Street Vent Shaft - Bermondsey To London Bridge

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7903	ACTIVE	J	J016-01-1/236	Passage - Druid Street Vent Shaft - Bermondsey To London Bridge	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7904	ACTIVE	J	J016-01-1/237	Passage - Druid Street Vent Shaft - Bermondsey To London Bridge	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7905	ACTIVE	J	J016-01-1/238	Passage - Druid Street Vent Shaft - Bermondsey To London Bridge	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7906	ACTIVE	J	J016-01-1/239	Passage - Druid Street Vent Shaft - Bermondsey To London Bridge	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7907	ACTIVE	J	J016-01-1/240	Passage - Druid Street Vent Shaft - Bermondsey To London Bridge	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7908	ACTIVE	J	J016-01-1/241	Passage - Druid Street Vent Shaft - Bermondsey To London Bridge	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7909	ACTIVE	J	J016-01-1/242	Passage - Druid Street Vent Shaft - Bermondsey To London Bridge	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7910	ACTIVE	J	J016-01-1/631	Stairs: Spiral - Druid Street Vent Shaft - Bermondsey To London Bridge	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7911	ACTIVE	J	J016-01-1/661	Switch Room - Druid Street Vent Shaft - Bermondsey To London Bridge	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7912	ACTIVE	J	J016-01-1/662	Switch Room - Druid Street Vent Shaft - Bermondsey To London Bridge	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J016-01 - Druid Street Vent Shaft - Bermondsey To London Bridge

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7913	ACTIVE	J	J016-01-1/731	SCR - Druid Street Vent Shaft - Bermondsey To London Bridge	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7914	ACTIVE	J	J016-01-1/761	Equipment Room - Druid Street Vent Shaft - Bermondsey To London Bridge	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7915	ACTIVE	J	J016-01-1/776	Fan Room - Druid Street Vent Shaft - Bermondsey To London Bridge	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7916	ACTIVE	J	J016-01-1/777	Equipment Room - Druid Street Vent Shaft - Bermondsey To London Bridge	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7917	ACTIVE	J	J016-01-1/778	Fan Room - Druid Street Vent Shaft - Bermondsey To London Bridge	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7918	ACTIVE	J	J016-01-1/779	Fan Room - Druid Street Vent Shaft - Bermondsey To London Bridge	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7919	ACTIVE	J	J016-01-1/791	Fan Room - Druid Street Vent Shaft - Bermondsey To London Bridge	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7920	ACTIVE	J	J016-01-1/793	Passage - Druid Street Vent Shaft - Bermondsey To London Bridge	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7921	ACTIVE	J	J016-01-1/796	Fan Room - Druid Street Vent Shaft - Bermondsey To London Bridge	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7922	ACTIVE	J	J016-01-2/081	Lobby - Druid Street Vent Shaft - Bermondsey To London Bridge	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7923	ACTIVE	J	J016-01-2/082	Lobby - Druid Street Vent Shaft - Bermondsey To London Bridge	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7924	ACTIVE	J	J016-01-2/083	Lobby - Druid Street Vent Shaft - Bermondsey To London Bridge	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7925	ACTIVE	J	J016-01-2/771	Pump Room - Druid Street Vent Shaft - Bermondsey To London Bridge	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7926	ACTIVE	J	J016-01-2/772	Plant Room - Druid Street Vent Shaft - Bermondsey To London Bridge	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J018-01 - Wardens Grove Vent Shaft - London Bridge To Southwark

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7942	ACTIVE	J	J018-01-1/082	Lobby - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7943	ACTIVE	J	J018-01-1/083	Lobby - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7944	ACTIVE	J	J018-01-1/084	Lobby - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7945	ACTIVE	J	J018-01-1/085	Lobby - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7946	ACTIVE	J	J018-01-1/201	Passage - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7947	ACTIVE	J	J018-01-1/237	Passage - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7948	ACTIVE	J	J018-01-1/238	Passage - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7949	ACTIVE	J	J018-01-1/661	Switch Room - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7950	ACTIVE	J	J018-01-1/662	Switch Room - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7951	ACTIVE	J	J018-01-1/731	CER - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7952	ACTIVE	J	J018-01-1/756	Fan Room - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7953	ACTIVE	J	J018-01-1/776	Fan Room - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7954	ACTIVE	J	J018-01-1/777	Fan Room - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7955	ACTIVE	J	J018-01-1/778	Fan Room - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7956	ACTIVE	J	J018-01-1/779	Fan Room - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J018-01 - Wardens Grove Vent Shaft - London Bridge To Southwark

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7957	ACTIVE	J	J018-01-1/780	Fan Room - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7958	ACTIVE	J	J018-01-1/781	Substation Room - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7959	ACTIVE	J	J018-01-1/782	Substation Room - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7960	ACTIVE	J	J018-01-1/901	Plant Room - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7961	ACTIVE	J	J018-01-1/902	Plant Room - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7962	ACTIVE	J	J018-01-1/903	Equipment Room - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7963	ACTIVE	J	J018-01-1/904	Fan Room - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7964	ACTIVE	J	J018-01-2/081	Lobby - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7965	ACTIVE	J	J018-01-2/082	Lobby - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7966	ACTIVE	J	J018-01-2/631	Stairs: Spiral - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7967	ACTIVE	J	J018-01-2/632	Stairs: Spiral - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7968	ACTIVE	J	J018-01-2/786	Service Riser - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7969	ACTIVE	J	J018-01-2/787	Service Riser - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7970	ACTIVE	J	J018-01-A/761	Tank Room - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7971	ACTIVE	J	J018-01-A/776	Plant Room - Wardens Grove Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J018-03 - Scoresby Street Vent Shaft - London Bridge To Southwark

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
7994	ACTIVE	J	J018-03-1/092	Lobby - Scoresby Street Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7995	ACTIVE	J	J018-03-1/093	Lobby - Scoresby Street Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7996	ACTIVE	J	J018-03-1/094	Lobby - Scoresby Street Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7997	ACTIVE	J	J018-03-1/095	Lobby - Scoresby Street Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7998	ACTIVE	J	J018-03-1/245	Lobby - Scoresby Street Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
7999	ACTIVE	J	J018-03-1/678	Switch Room - Scoresby Street Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8000	ACTIVE	J	J018-03-1/679	Switch Room - Scoresby Street Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8001	ACTIVE	J	J018-03-1/907	Fan Room - Scoresby Street Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8002	ACTIVE	J	J018-03-1/908	Fan Room - Scoresby Street Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8003	ACTIVE	J	J018-03-1/909	Fan Control Room - Scoresby Street Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8004	ACTIVE	J	J018-03-1/910	Equipment Room - Scoresby Street Vent Shaft - London Bridge To Southwark	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

J026-01 - Storeys Gate Vent Shaft - Westminster To Green Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8005	ACTIVE	J	J026-01-1/631	Stairs: Spiral - Storeys Gate Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8006	ACTIVE	J	J026-01-1/776	Plant Room - Storeys Gate Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J026-01 - Storeys Gate Vent Shaft - Westminster To Green Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8007	ACTIVE	J	J026-01-1/786	Service Riser - Storeys Gate Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8008	ACTIVE	J	J026-01-1/787	Service Riser - Storeys Gate Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8009	ACTIVE	J	J026-01-10/481	Plant Room - Storeys Gate Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8010	ACTIVE	J	J026-01-10/971	Service Area - Storeys Gate Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8011	ACTIVE	J	J026-01-3/237	Passage - Storeys Gate Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8012	ACTIVE	J	J026-01-3/238	Passage - Storeys Gate Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8013	ACTIVE	J	J026-01-3/239	Passage - Storeys Gate Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8014	ACTIVE	J	J026-01-3/632	Stairs: Spiral - Storeys Gate Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8015	ACTIVE	J	J026-01-3/661	Switch Room - Storeys Gate Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8016	ACTIVE	J	J026-01-3/662	Switch Room - Storeys Gate Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8017	ACTIVE	J	J026-01-3/663	UPS Room - Storeys Gate Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8018	ACTIVE	J	J026-01-3/731	CER - Storeys Gate Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8019	ACTIVE	J	J026-01-3/777	Fan Room - Storeys Gate Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8020	ACTIVE	J	J026-01-3/778	Fan Room - Storeys Gate Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8021	ACTIVE	J	J026-01-3/901	Void - Storeys Gate Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J026-01 - Storeys Gate Vent Shaft - Westminster To Green Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8022	ACTIVE	J	J026-01-7/201	Passage - Storeys Gate Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8023	ACTIVE	J	J026-01-7/202	Lobby - Storeys Gate Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8024	ACTIVE	J	J026-01-9/201	Passage - Storeys Gate Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8025	ACTIVE	J	J026-01-9/202	Lobby - Storeys Gate Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8026	ACTIVE	J	J026-01-9/631	Stairs: Spiral - Storeys Gate Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8027	ACTIVE	J	J026-01-9/632	Stairs: Spiral - Storeys Gate Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

J026-02 - Blue Ball Yard Vent Shaft - Westminster To Green Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8028	ACTIVE	J	J026-02-1/236	Passage - Blue Ball Yard Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8029	ACTIVE	J	J026-02-1/416	Toilet: Unisex - Blue Ball Yard Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8030	ACTIVE	J	J026-02-1/576	Stairs: Linear - Blue Ball Yard Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8031	ACTIVE	J	J026-02-1/577	Stairs: Linear - Blue Ball Yard Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8032	ACTIVE	J	J026-02-2/551	Passage - Blue Ball Yard Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8033	ACTIVE	J	J026-02-2/761	Switch Room - Blue Ball Yard Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8034	ACTIVE	J	J026-02-A/081	Lobby - Blue Ball Yard Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



J026-02 - Blue Ball Yard Vent Shaft - Westminster To Green Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8035	ACTIVE	J	J026-02-A/661	Switch Room - Blue Ball Yard Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8036	ACTIVE	J	J026-02-A/662	Switch Room - Blue Ball Yard Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8037	ACTIVE	J	J026-02-A/731	CER - Blue Ball Yard Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8038	ACTIVE	J	J026-02-A/732	Fan Room - Blue Ball Yard Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8039	ACTIVE	J	J026-02-B/701	SER - Blue Ball Yard Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8040	ACTIVE	J	J026-02-C/776	Plant Room - Blue Ball Yard Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8041	ACTIVE	J	J026-02-C/777	Plant Room - Blue Ball Yard Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8042	ACTIVE	J	J026-02-C/778	Plant Room - Blue Ball Yard Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8043	ACTIVE	J	J026-02-C/779	Plant Room - Blue Ball Yard Vent Shaft - Westminster To Green Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

J027-02 - Signals Building - Canning Town To West Ham

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8054	ACTIVE	J	J027-02-0/711	SER - Signal Building - Canning Town To West Ham	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

JD004-04 - Substation - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8161	ACTIVE	J	JD004-04-0/662	Switch Room - Signals Building - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8162	ACTIVE	J	JD004-04-1/236	Passage - Substation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



JD004-04 - Substation - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8163	ACTIVE	J	JD004-04-1/416	Toilet: Unisex - Substation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8164	ACTIVE	J	JD004-04-1/576	Stairs: Linear - Substation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8165	ACTIVE	J	JD004-04-1/577	Stairs: Linear - Substation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8166	ACTIVE	J	JD004-04-1/661	Switch Room - Substation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8167	ACTIVE	J	JD004-04-1/662	Switch Room - Substation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8168	ACTIVE	J	JD004-04-1/663	Equipment Room - Substation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8169	ACTIVE	J	JD004-04-1/664	Switch Room - Substation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8170	ACTIVE	J	JD004-04-1/731	CER - Substation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8171	ACTIVE	J	JD004-04-1/761	Transformer Room - Substation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8172	ACTIVE	J	JD004-04-1/762	Transformer Room - Substation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8173	ACTIVE	J	JD004-04-1/763	Transformer Room - Substation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8174	ACTIVE	J	JD004-04-1/764	Transformer Room - Substation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8175	ACTIVE	J	JD004-04-1/776	Plant Room - Substation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8176	ACTIVE	J	JD004-04-1/781	Transformer Room - Substation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8177	ACTIVE	J	JD004-04-1/782	Transformer Room - Substation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



JD004-04 - Substation - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8178	ACTIVE	J	JD004-04-1/783	Switch Room - Substation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8179	ACTIVE	J	JD004-04-1/801	Mess Room - Substation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8180	ACTIVE	J	JD004-04-2/781	Substation Room - Substation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

N115-01 - Alaska Street Vent Shaft - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10809	ACTIVE	J	N115-01-1/097	Passage - Alaska Street Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10810	ACTIVE	J	N115-01-1/631	Stairs: Spiral - Alaska Street Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10811	ACTIVE	J	N115-01-1/632	Stairs: Spiral - Alaska Street Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10812	ACTIVE	J	N115-01-2/485	Service Riser - Alaska Street Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2758	ACTIVE	J	N115-01-2/485	Service Riser - Alaska Street Vent Shaft - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10813	ACTIVE	J	N115-01-2/486	Service Riser - Alaska Street Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2196	ACTIVE	J	N115-01-2/486	Service Riser - Alaska Street Vent Shaft - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10814	ACTIVE	J	N115-01-3/481	Disused Room - Alaska Street Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10815	ACTIVE	J	N115-01-3/482	Disused Room - Alaska Street Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10816	ACTIVE	J	N115-01-3/483	Disused Room - Alaska Street Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10817	ACTIVE	J	N115-01-3/484	Disused Room - Alaska Street Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N115-01 - Alaska Street Vent Shaft - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10818	ACTIVE	J	N115-01-3/631	Stairs: Spiral - Alaska Street Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2163	ACTIVE	J	N115-01-3/631	Stairs: Spiral - Alaska Street Vent Shaft - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10819	ACTIVE	J	N115-01-3/632	Stairs: Spiral - Alaska Street Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2164	ACTIVE	J	N115-01-3/632	Stairs: Spiral - Alaska Street Vent Shaft - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10820	ACTIVE	J	N115-01-3/786	Service Riser - Alaska Street Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10821	ACTIVE	J	N115-01-3/788	Service Riser - Alaska Street Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2106	ACTIVE	J	N115-01-3/788	Service Riser - Alaska Street Vent Shaft - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10822	ACTIVE	J	N115-01-3/789	Service Riser - Alaska Street Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2733	ACTIVE	J	N115-01-3/789	Service Riser - Alaska Street Vent Shaft - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10823	ACTIVE	J	N115-01-3/790	Service Riser - Alaska Street Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2107	ACTIVE	J	N115-01-3/790	Service Riser - Alaska Street Vent Shaft - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10824	ACTIVE	J	N115-01-4/138	Lift Shaft - Alaska Street Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10825	ACTIVE	J	N115-01-A/576	Stairs: Linear - Alaska Street Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2155	ACTIVE	J	N115-01-A/576	Stairs: Linear - Alaska Street Vent Shaft - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10826	ACTIVE	J	N115-01-A/776	Fan Room - Alaska Street Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10827	ACTIVE	J	N115-01-A/778	Fan Room - Alaska Street Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N115-01 - Alaska Street Vent Shaft - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
2771	ACTIVE	J	N115-01-A/778	Fan Room - Alaska Street Vent Shaft - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10828	ACTIVE	J	N115-01-A/779	Fan Room - Alaska Street Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2242	ACTIVE	J	N115-01-A/779	Fan Room - Alaska Street Vent Shaft - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10829	ACTIVE	J	N115-01-A/780	Plant Room - Alaska Street Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2243	ACTIVE	J	N115-01-A/780	Plant Room - Alaska Street Vent Shaft - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10830	ACTIVE	J	N115-01-A/793	Air Plenum - Alaska Street Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2244	ACTIVE	J	N115-01-A/793	Air Plenum - Alaska Street Vent Shaft - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					
10831	ACTIVE	J	N115-01-A/794	Air Plenum - Alaska Street Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2772	ACTIVE	J	N115-01-A/794	Air Plenum - Alaska Street Vent Shaft - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					

N115-02 - Mephram Street/Tenison Link Vent Shaft - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10832	ACTIVE	J	N115-02-1/237	Passage - Mephram Street/Tenison Link Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10833	ACTIVE	J	N115-02-1/678	Disused Room - Mephram Street/Tenison Link Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10834	ACTIVE	J	N115-02-1/778	Fan Room - Mephram Street/Tenison Link Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10835	ACTIVE	J	N115-02-1/779	Fan Room - Mephram Street/Tenison Link Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10836	ACTIVE	J	N115-02-1/780	TXR - Mephram Street/Tenison Link Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



N115-02 - Mephram Street/Tenison Link Vent Shaft - Waterloo Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
10837	ACTIVE	J	N115-02-1/791	Service Area - Mephram Street/ Tenison Link Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10838	ACTIVE	J	N115-02-1/793	Service Area - Mephram Street/ Tenison Link Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10839	ACTIVE	J	N115-02-3/633	Stairs: Spiral - Mephram Street/ Tenison Link Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10840	ACTIVE	J	N115-02-3/634	Stairs: Spiral - Mephram Street/ Tenison Link Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
10841	ACTIVE	J	N115-02-A/777	Fan Room - Mephram Street/ Tenison Link Vent Shaft - Waterloo Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
2241	ACTIVE	J	N115-02-A/777	Fan Room - Mephram Street/ Tenison Link Vent Shaft - Waterloo Stn	No Access	Asbestos	Surveyed – Not Detected				Not Surveyed - New Room					

W004-01 - Station Building - King William Street Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14563	ACTIVE	J	W004-01-1/236	Passage - Station Building - King William Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14564	ACTIVE	J	W004-01-1/576	Stairs: Linear - Station Building - King William Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14565	ACTIVE	J	W004-01-2/071	Circulation Area - Station Building - King William Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14566	ACTIVE	J	W004-01-2/236	Passage - Station Building - King William Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14567	ACTIVE	J	W004-01-2/237	Passage - Station Building - King William Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14568	ACTIVE	J	W004-01-2/416	Disused Room - Station Building - King William Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14569	ACTIVE	J	W004-01-2/417	Disused Room - Station Building - King William Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



W004-01 - Station Building - King William Street Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14570	ACTIVE	J	W004-01-2/577	Stairs: Linear - Station Building - King William Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14571	ACTIVE	J	W004-01-2/578	Stairs: Linear - Station Building - King William Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14572	ACTIVE	J	W004-01-2/661	Switch Room - Station Building - King William Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14573	ACTIVE	J	W004-01-2/662	Switch Room - Station Building - King William Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14574	ACTIVE	J	W004-01-2/771	Pump Room - Station Building - King William Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14575	ACTIVE	J	W004-01-2/951	Disused Room - Station Building - King William Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14576	ACTIVE	J	W004-01-2/952	Disused Room - Station Building - King William Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14577	ACTIVE	J	W004-01-2/953	Disused Room - Station Building - King William Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14578	ACTIVE	J	W004-01-2/954	Disused Room - Station Building - King William Street Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

W048-01 - Station Building - Swiss Cottage Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14676	ACTIVE	J	W048-01-1/236	Passage - Station Building - Swiss Cottage Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14677	ACTIVE	J	W048-01-1/237	Passage - Station Building - Swiss Cottage Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14678	ACTIVE	J	W048-01-1/238	Lobby - Station Building - Swiss Cottage Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14679	ACTIVE	J	W048-01-1/239	Switch Room - Station Building - Swiss Cottage Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



W048-01 - Station Building - Swiss Cottage Disused Stn

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
14680	ACTIVE	J	W048-01-1/576	Stairs: Linear - Station Building - Swiss Cottage Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14681	ACTIVE	J	W048-01-1/604	Stairs: Linear - Station Building - Swiss Cottage Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14682	ACTIVE	J	W048-01-1/701	CER - Station Building - Swiss Cottage Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14683	ACTIVE	J	W048-01-1/732	CER - Station Building - Swiss Cottage Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14684	ACTIVE	J	W048-01-2/240	Lobby - Station Building - Swiss Cottage Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14685	ACTIVE	J	W048-01-2/665	Disused Room - Station Building - Swiss Cottage Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14686	ACTIVE	J	W048-01-2/666	Switch Room - Station Building - Swiss Cottage Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14687	ACTIVE	J	W048-01-2/706	IMR - Station Building - Swiss Cottage Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14688	ACTIVE	J	W048-01-2/731	CER - Station Building - Swiss Cottage Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14689	ACTIVE	J	W048-01-2/761	Equipment Room - Station Building - Swiss Cottage Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
14690	ACTIVE	J	W048-01-2/992	Passage - Station Building - Swiss Cottage Disused Stn	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

X658-01 - Electrical Building - Stanmore To Canons Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3005	ACTIVE	J	B082-06-1/706	IMR - Electrical Building - Stanmore To Canons Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
53869	ACTIVE	J	B082-06-2/267	Switch Room - Electrical Building - Stanmore To Canons Park	Other Electrical Boxes	Asbestos	Presumed				1no Switch Boxes - Insulation within -					



Hazardous Material Asset Register - Summary



X658-01 - Electrical Building - Stanmore To Canons Park

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3006	ACTIVE	J	X658-01-1/781	Substation Room - Electrical Building - Stanmore To Canons Park	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

B092-01 - Neasden Service Control Centre

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3441	ACTIVE	J	B092-01-0/711	SER - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3442	ACTIVE	J	B092-01-1/081	Lobby - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3443	ACTIVE	J	B092-01-1/082	Lobby - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3444	ACTIVE	J	B092-01-1/083	Lobby - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3445	ACTIVE	J	B092-01-1/084	Lobby - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3446	ACTIVE	J	B092-01-1/085	Lobby - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3447	ACTIVE	J	B092-01-1/086	Lobby - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3448	ACTIVE	J	B092-01-1/087	Lobby - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3449	ACTIVE	J	B092-01-1/088	Lobby - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3450	ACTIVE	J	B092-01-1/089	Lobby - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3451	ACTIVE	J	B092-01-1/131	IMR - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3452	ACTIVE	J	B092-01-1/331	Kitchen - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B092-01 - Neasden Service Control Centre

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3453	ACTIVE	J	B092-01-1/396	Tank Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3454	ACTIVE	J	B092-01-1/401	Store - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3455	ACTIVE	J	B092-01-1/406	Store - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3456	ACTIVE	J	B092-01-1/411	Store - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3457	ACTIVE	J	B092-01-1/416	Toilet: Female - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3458	ACTIVE	J	B092-01-1/417	Toilet: Male - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3459	ACTIVE	J	B092-01-1/418	Toilet: Disabled - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3460	ACTIVE	J	B092-01-1/419	Toilet: Unisex - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3461	ACTIVE	J	B092-01-1/436	Reception - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3462	ACTIVE	J	B092-01-1/481	Shower Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3463	ACTIVE	J	B092-01-1/482	Shower Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3464	ACTIVE	J	B092-01-1/485	First Aid Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3465	ACTIVE	J	B092-01-1/531	Security Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3466	ACTIVE	J	B092-01-1/576	Stairs: Linear - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3467	ACTIVE	J	B092-01-1/577	Stairs: Linear - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B092-01 - Neasden Service Control Centre

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3468	ACTIVE	J	B092-01-1/578	Stairs: Linear - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3469	ACTIVE	J	B092-01-1/661	Switch Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3470	ACTIVE	J	B092-01-1/662	Switch Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3471	ACTIVE	J	B092-01-1/663	Switch Cupboard - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3472	ACTIVE	J	B092-01-1/731	CER - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3473	ACTIVE	J	B092-01-1/732	CER - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3474	ACTIVE	J	B092-01-1/761	Plant Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3475	ACTIVE	J	B092-01-1/781	Plant Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3476	ACTIVE	J	B092-01-1/782	Transformer Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3477	ACTIVE	J	B092-01-1/783	Transformer Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3478	ACTIVE	J	B092-01-1/786	Cable Shaft - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3479	ACTIVE	J	B092-01-1/787	Cable Shaft - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3480	ACTIVE	J	B092-01-1/801	Office - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3481	ACTIVE	J	B092-01-1/810	Lobby - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3482	ACTIVE	J	B092-01-1/811	Lobby - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B092-01 - Neasden Service Control Centre

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3483	ACTIVE	J	B092-01-1/813	Store - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3484	ACTIVE	J	B092-01-1/814	Store - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3485	ACTIVE	J	B092-01-1/815	Store - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3486	ACTIVE	J	B092-01-1/816	Store - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3487	ACTIVE	J	B092-01-1/817	Office - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3488	ACTIVE	J	B092-01-1/818	Office - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3489	ACTIVE	J	B092-01-1/901	Disused Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3490	ACTIVE	J	B092-01-A/047	Kitchen - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3491	ACTIVE	J	B092-01-A/081	Lobby - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3492	ACTIVE	J	B092-01-A/082	Lobby - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3493	ACTIVE	J	B092-01-A/083	Lobby - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3494	ACTIVE	J	B092-01-A/084	Lobby - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3495	ACTIVE	J	B092-01-A/085	Lobby - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3496	ACTIVE	J	B092-01-A/086	Lobby - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3497	ACTIVE	J	B092-01-A/087	Lobby - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B092-01 - Neasden Service Control Centre

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3498	ACTIVE	J	B092-01-A/236	Passage - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3499	ACTIVE	J	B092-01-A/237	Passage - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3500	ACTIVE	J	B092-01-A/238	Passage - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3501	ACTIVE	J	B092-01-A/239	Passage - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3502	ACTIVE	J	B092-01-A/240	Passage - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3503	ACTIVE	J	B092-01-A/331	Mess Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3504	ACTIVE	J	B092-01-A/406	Store - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3505	ACTIVE	J	B092-01-A/411	Store - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3506	ACTIVE	J	B092-01-A/412	Store - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3507	ACTIVE	J	B092-01-A/416	Toilet: Male - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3508	ACTIVE	J	B092-01-A/417	Toilet: Unisex - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3509	ACTIVE	J	B092-01-A/418	Toilet: Female - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3510	ACTIVE	J	B092-01-A/419	Toilet: Disabled - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3511	ACTIVE	J	B092-01-A/420	Lobby - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3512	ACTIVE	J	B092-01-A/421	Shower Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B092-01 - Neasden Service Control Centre

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3513	ACTIVE	J	B092-01-A/422	Shower Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3514	ACTIVE	J	B092-01-A/436	Reception - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3515	ACTIVE	J	B092-01-A/481	Equipment Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3516	ACTIVE	J	B092-01-A/482	Simulator Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3517	ACTIVE	J	B092-01-A/483	Simulator Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3518	ACTIVE	J	B092-01-A/484	Office - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3519	ACTIVE	J	B092-01-A/661	Switch Cupboard - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3520	ACTIVE	J	B092-01-A/662	Equipment Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3521	ACTIVE	J	B092-01-A/663	Equipment Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3522	ACTIVE	J	B092-01-A/664	Equipment Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3523	ACTIVE	J	B092-01-A/711	SER - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3524	ACTIVE	J	B092-01-A/761	Plant Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3525	ACTIVE	J	B092-01-A/762	Fan Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3526	ACTIVE	J	B092-01-A/763	Plant Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3527	ACTIVE	J	B092-01-A/765	Fan Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B092-01 - Neasden Service Control Centre

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3528	ACTIVE	J	B092-01-A/802	Exhibition Area - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3529	ACTIVE	J	B092-01-A/803	Office - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3530	ACTIVE	J	B092-01-A/804	Office - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3531	ACTIVE	J	B092-01-A/805	Meeting Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3532	ACTIVE	J	B092-01-A/806	Office - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3533	ACTIVE	J	B092-01-B/082	Lobby - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3534	ACTIVE	J	B092-01-B/083	Lobby - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3535	ACTIVE	J	B092-01-B/085	Lobby - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3536	ACTIVE	J	B092-01-B/086	Lobby - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3537	ACTIVE	J	B092-01-B/236	Passage - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3538	ACTIVE	J	B092-01-B/237	Passage - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3539	ACTIVE	J	B092-01-B/291	Office - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3540	ACTIVE	J	B092-01-B/316	Locker Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3541	ACTIVE	J	B092-01-B/317	Locker Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3542	ACTIVE	J	B092-01-B/318	Locker Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B092-01 - Neasden Service Control Centre

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3543	ACTIVE	J	B092-01-B/331	Kitchen - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3544	ACTIVE	J	B092-01-B/366	Mess Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3545	ACTIVE	J	B092-01-B/406	Store - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3546	ACTIVE	J	B092-01-B/411	Store - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3547	ACTIVE	J	B092-01-B/416	Store - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3548	ACTIVE	J	B092-01-B/417	Store - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3549	ACTIVE	J	B092-01-B/418	Store - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3550	ACTIVE	J	B092-01-B/419	Store - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3551	ACTIVE	J	B092-01-B/420	Store - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3552	ACTIVE	J	B092-01-B/421	Store - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3553	ACTIVE	J	B092-01-B/422	Store - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3554	ACTIVE	J	B092-01-B/481	Simulator Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3555	ACTIVE	J	B092-01-B/661	Switch Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3556	ACTIVE	J	B092-01-B/751	Depot Control Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3557	ACTIVE	J	B092-01-B/761	Fan Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



B092-01 - Neasden Service Control Centre

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
3558	ACTIVE	J	B092-01-B/762	Fan Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3559	ACTIVE	J	B092-01-B/763	Fan Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3560	ACTIVE	J	B092-01-B/776	Plant Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3561	ACTIVE	J	B092-01-B/777	Tank Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3562	ACTIVE	J	B092-01-B/801	Office - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3563	ACTIVE	J	B092-01-B/802	Incident Room - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3564	ACTIVE	J	B092-01-B/803	Office - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3565	ACTIVE	J	B092-01-B/804	Office - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3566	ACTIVE	J	B092-01-B/805	Office - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
3567	ACTIVE	J	B092-01-B/901	Lobby - Neasden Service Control Centre	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

JD004-01 - Depot Building - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8056	ACTIVE	J	JD004-01-1/411	Store - Depot Building - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8057	ACTIVE	J	JD004-01-1/412	Store - Depot Building - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8058	ACTIVE	J	JD004-01-1/413	Store - Depot Building - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



JD004-01 - Depot Building - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8059	ACTIVE	J	JD004-01-1/416	Toilet: Unisex - Depot Building - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8060	ACTIVE	J	JD004-01-1/417	Toilet: Unisex - Depot Building - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8061	ACTIVE	J	JD004-01-1/418	Toilet: Unisex - Depot Building - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8062	ACTIVE	J	JD004-01-1/419	Toilet: Unisex - Depot Building - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8063	ACTIVE	J	JD004-01-1/562	Workshop - Depot Building - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8064	ACTIVE	J	JD004-01-1/563	Workshop - Depot Building - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8065	ACTIVE	J	JD004-01-1/564	Store - Depot Building - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8066	ACTIVE	J	JD004-01-1/565	Under Car Cleaning Area - Depot Building - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8067	ACTIVE	J	JD004-01-1/576	Stairs: Linear - Depot Building - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8068	ACTIVE	J	JD004-01-1/577	Stairs: Linear - Depot Building - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8069	ACTIVE	J	JD004-01-1/772	Pump Room - Pump House South - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8070	ACTIVE	J	JD004-01-1/807	Office - Depot Building - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8071	ACTIVE	J	JD004-01-1/898	Office - Depot Building - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8072	ACTIVE	J	JD004-01-A/646	Equipment Room - Depot Building - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



JD004-02 - Workshop & Stores - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8073	ACTIVE	J	JD004-02-1/236	Passage - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8074	ACTIVE	J	JD004-02-1/237	Passage - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8075	ACTIVE	J	JD004-02-1/238	Tank Room - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8076	ACTIVE	J	JD004-02-1/331	Mess Room - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8077	ACTIVE	J	JD004-02-1/396	Plant Room - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8078	ACTIVE	J	JD004-02-1/411	Store - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8079	ACTIVE	J	JD004-02-1/416	Toilet: Unisex - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8080	ACTIVE	J	JD004-02-1/417	Toilet: Unisex - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8081	ACTIVE	J	JD004-02-1/418	Toilet: Unisex - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8082	ACTIVE	J	JD004-02-1/419	Toilet: Unisex - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8083	ACTIVE	J	JD004-02-1/481	Workshop - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8084	ACTIVE	J	JD004-02-1/482	Workshop - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8085	ACTIVE	J	JD004-02-1/483	Steam Cleaning Room - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8086	ACTIVE	J	JD004-02-1/571	Store - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8087	ACTIVE	J	JD004-02-1/572	Store - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



JD004-02 - Workshop & Stores - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8088	ACTIVE	J	JD004-02-1/578	Stairs: Linear - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8089	ACTIVE	J	JD004-02-1/661	Switch Room - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8090	ACTIVE	J	JD004-02-1/731	CER - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8091	ACTIVE	J	JD004-02-1/761	Equipment Room - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8092	ACTIVE	J	JD004-02-1/776	Equipment Room - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8093	ACTIVE	J	JD004-02-1/777	Equipment Room - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8094	ACTIVE	J	JD004-02-1/778	Plant Room - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8095	ACTIVE	J	JD004-02-1/781	TXR - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8096	ACTIVE	J	JD004-02-1/782	TXR - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8097	ACTIVE	J	JD004-02-1/801	Office - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8098	ACTIVE	J	JD004-02-1/802	Office - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8099	ACTIVE	J	JD004-02-1/803	Office - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8100	ACTIVE	J	JD004-02-1/804	Office - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8101	ACTIVE	J	JD004-02-1/901	Equipment Room - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8102	ACTIVE	J	JD004-02-1/902	First Aid Room - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



JD004-02 - Workshop & Stores - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8103	ACTIVE	J	JD004-02-1/903	Store - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8104	ACTIVE	J	JD004-02-A/236	Passage - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8105	ACTIVE	J	JD004-02-A/661	Switch Room - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8106	ACTIVE	J	JD004-02-A/662	Switch Room - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8107	ACTIVE	J	JD004-02-A/731	CER - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8108	ACTIVE	J	JD004-02-A/761	Switch Room - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8109	ACTIVE	J	JD004-02-A/901	Tank Room - Workshop & Stores - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

JD004-03 - Office Complex - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8110	ACTIVE	J	JD004-03-1/041	Mess Room - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8111	ACTIVE	J	JD004-03-1/047	Kitchen - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8112	ACTIVE	J	JD004-03-1/050	Store - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8113	ACTIVE	J	JD004-03-1/056	Toilet: Unisex - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8114	ACTIVE	J	JD004-03-1/081	Lobby - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8115	ACTIVE	J	JD004-03-1/236	Passage - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



JD004-03 - Office Complex - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8116	ACTIVE	J	JD004-03-1/237	Passage - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8117	ACTIVE	J	JD004-03-1/238	Passage - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8118	ACTIVE	J	JD004-03-1/239	Passage - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8119	ACTIVE	J	JD004-03-1/240	Passage - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8120	ACTIVE	J	JD004-03-1/241	Passage - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8121	ACTIVE	J	JD004-03-1/316	Locker Room - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8122	ACTIVE	J	JD004-03-1/317	Locker Room - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8123	ACTIVE	J	JD004-03-1/318	Locker Room - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8124	ACTIVE	J	JD004-03-1/401	Store - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8125	ACTIVE	J	JD004-03-1/406	Store - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8126	ACTIVE	J	JD004-03-1/416	Toilet: Female - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8127	ACTIVE	J	JD004-03-1/417	Shower Room - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8128	ACTIVE	J	JD004-03-1/418	Toilet: Male - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8129	ACTIVE	J	JD004-03-1/419	Shower Room - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8130	ACTIVE	J	JD004-03-1/420	Toilet: Female - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



JD004-03 - Office Complex - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8131	ACTIVE	J	JD004-03-1/421	Toilet: Male - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8132	ACTIVE	J	JD004-03-1/422	Toilet - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8133	ACTIVE	J	JD004-03-1/423	Toilet: Female - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8134	ACTIVE	J	JD004-03-1/661	Switch Room - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8135	ACTIVE	J	JD004-03-1/662	Switch Room - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8136	ACTIVE	J	JD004-03-1/776	Plant Room - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8137	ACTIVE	J	JD004-03-1/801	Reception - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8138	ACTIVE	J	JD004-03-1/802	Office - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8139	ACTIVE	J	JD004-03-1/803	Office - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8140	ACTIVE	J	JD004-03-1/804	Office - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8141	ACTIVE	J	JD004-03-1/805	Office - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8142	ACTIVE	J	JD004-03-1/806	Office - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8143	ACTIVE	J	JD004-03-1/808	Office - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8144	ACTIVE	J	JD004-03-1/809	Office - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8145	ACTIVE	J	JD004-03-1/810	Office - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



JD004-03 - Office Complex - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8146	ACTIVE	J	JD004-03-1/811	Office - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8147	ACTIVE	J	JD004-03-1/890	Office - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8148	ACTIVE	J	JD004-03-1/891	Office - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8149	ACTIVE	J	JD004-03-1/892	Depot Computer Room - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8150	ACTIVE	J	JD004-03-1/893	Office - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8151	ACTIVE	J	JD004-03-1/894	Office - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8152	ACTIVE	J	JD004-03-1/895	Office - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8153	ACTIVE	J	JD004-03-1/896	Office - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8154	ACTIVE	J	JD004-03-1/897	Office - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8155	ACTIVE	J	JD004-03-1/899	Office - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8156	ACTIVE	J	JD004-03-1/900	Office - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8157	ACTIVE	J	JD004-03-1/901	Service Riser - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8158	ACTIVE	J	JD004-03-1/902	Service Riser - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8159	ACTIVE	J	JD004-03-1/903	Service Riser - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8160	ACTIVE	J	JD004-03-1/989	Office - Office Complex - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



JD004-05 - Control Tower - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8181	ACTIVE	J	JD004-05-1/236	Passage - Control Tower - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8182	ACTIVE	J	JD004-05-1/416	Toilet: Unisex - Control Tower - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8183	ACTIVE	J	JD004-05-1/546	Office - Control Tower - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8184	ACTIVE	J	JD004-05-1/547	Mess Room - Control Tower - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8185	ACTIVE	J	JD004-05-1/548	Office - Control Tower - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8186	ACTIVE	J	JD004-05-1/576	Stairs: Linear - Control Tower - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8187	ACTIVE	J	JD004-05-1/577	Stairs: Linear - Control Tower - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8188	ACTIVE	J	JD004-05-1/661	Switch Room - Control Tower - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8189	ACTIVE	J	JD004-05-1/706	SER - Control Tower - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8190	ACTIVE	J	JD004-05-1/731	CER - Control Tower - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8191	ACTIVE	J	JD004-05-1/776	Plant Room - Control Tower - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8192	ACTIVE	J	JD004-05-A/236	Passage - Control Tower - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8193	ACTIVE	J	JD004-05-A/316	Locker Room - Control Tower - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8194	ACTIVE	J	JD004-05-A/331	Mess Room - Control Tower - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8195	ACTIVE	J	JD004-05-A/371	Office - Control Tower - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



JD004-05 - Control Tower - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8196	ACTIVE	J	JD004-05-A/416	Toilet: Unisex - Control Tower - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8197	ACTIVE	J	JD004-05-A/417	Toilet: Unisex - Control Tower - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8198	ACTIVE	J	JD004-05-A/756	Depot Control Room - Control Tower - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

JD004-06 - Gate House - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8199	ACTIVE	J	JD004-06-1/081	Lobby - Gate House - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8200	ACTIVE	J	JD004-06-1/331	Mess Room - Gate House - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8201	ACTIVE	J	JD004-06-1/416	Toilet: Unisex - Gate House - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8202	ACTIVE	J	JD004-06-1/756	Depot Control Room - Gate House - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

JD004-07 - Electrical Building - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8203	ACTIVE	J	JD004-07-1/481	Plant Room - Electrical Building - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

JD004-08 - P Way Accommodation - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8204	ACTIVE	J	JD004-08-1/082	Lobby - P Way Accommodation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8205	ACTIVE	J	JD004-08-1/371	Switch Room - P Way Accommodation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



JD004-08 - P Way Accommodation - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8206	ACTIVE	J	JD004-08-1/372	Mess Room - P Way Accommodation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8207	ACTIVE	J	JD004-08-1/416	Toilet: Unisex - P Way Accommodation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8208	ACTIVE	J	JD004-08-1/417	Shower Room - P Way Accommodation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8209	ACTIVE	J	JD004-08-1/482	Cupboard - P Way Accommodation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8210	ACTIVE	J	JD004-08-1/901	Tank Room - P Way Accommodation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

JD004-09 - Store - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8211	ACTIVE	J	JD004-09-1/481	Store Room - Store - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

JD004-10 - Bicycle Shed - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8212	ACTIVE	J	JD004-10-1/446	Bicycle Area - Bicycle Shed - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

JD004-11 - External And Flammable Store - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8213	ACTIVE	J	JD004-11-1/901	Store - External & Flammable Store - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8214	ACTIVE	J	JD004-11-1/902	Store - External & Flammable Store - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8215	ACTIVE	J	JD004-11-1/903	Store - External & Flammable Store - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



JD004-12 - Cleaners Store - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8216	ACTIVE	J	JD004-12-1/482	Store Room - Cleaners Store - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

JD004-13 - Cleaners Accommodation - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8217	ACTIVE	J	JD004-13-1/053	Mess Room - Cleaners Accommodation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8218	ACTIVE	J	JD004-13-1/083	Lobby - Cleaners Accommodation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8219	ACTIVE	J	JD004-13-1/316	Locker Room - Cleaners Accommodation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8220	ACTIVE	J	JD004-13-1/406	Store - Cleaners Accommodation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8221	ACTIVE	J	JD004-13-1/416	Toilet: Female - Cleaners Accommodation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									
8222	ACTIVE	J	JD004-13-1/417	Toilet: Male - Cleaners Accommodation - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

JD004-14 - Train Wash - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8223	ACTIVE	J	JD004-14-1/561	Train Wash Area - Train Wash - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

JD004-15 - Pump House North - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8224	ACTIVE	J	JD004-15-1/771	Pump Room - Pump House North - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									



Hazardous Material Asset Register - Summary



JD004-16 - Signals Building - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8225	ACTIVE	J	JD004-16-0/711	SER - Signals Building - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

JD004-17 - Signals Building - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8226	ACTIVE	J	JD004-17-0/661	UPS Room - Signals Building - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

JD004-18 - Pump House South - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8227	ACTIVE	J	JD004-18-1/772	Pump Room - Pump House South - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									

JD004-19 - Signals Building - Stratford Market Depot

Ref.	Status	Maint. Line	Location/Asset Code	Location/Asset Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Position	Notes	Qty. Metres	Qty. Units	Report Ref.	Above False Ceiling	Below False Floor
8228	ACTIVE	J	JD004-19-0/711	SER - Signals Building - Stratford Market Depot	Stations: Rooms	Asbestos	Room: Not Surveyed – Asbestos Presumed									