

Layout of

Interpreted Listings - typical example

The example shown below of an Interpreted Listing of an collision is how the user would see the printed report.

The example shown overleaf shows the field positions of each of the items of information contained in the Interpreted Listing, with the collision split into the Attendant, Casualty and Vehicle components, each of which are shown in a different colour for ease of reference.

XY00199 MON 08, EPT-AT SCENE	/06 08.45 LIGHT HIGH ROAD 30M E J/W ROAD-DRY WEATHER-FINE S	INGLE 2 NO JUN IN 20M	11 LINK 022-717 52597/17 ZEBRA CROSSING SCH XING PTRL 2 ROAD WORKS OTHER OBJECT IN CWY	
1 TRAVELLING A ARKED V3. V3 S	F SPEED STRUCK V2 PUSHING IT INTO ON TRUCK PED			
ASUALTY 02(02)	(29YRS-F SE20) SERIOUS PEDESTRIAN (45YRS-M SE15) SLIGHT DRIVER (37YRS-M SW18) SLIGHT DRIVER	CROSSING ROAD (NOT ON CROSSING N BOUND) FROM DRIVERS N/SIDE	651
• •	(-YRS-F UNKN) SLIGHT PASSENGER (09YRS-F SE15) SLIGHT PASSENGER JOURNEY TO/FROM SCHOOL SCH ATT	BACK SEAT		
EHICLE 01(02)	CAR (37YRS-M SW18) CARAVAN BT - NOT REQUESTED LEFT CWY OFFSIDE			225
EHICLE 02(01)	CAR (45YRS-M SE15) BT - NEGATIVE OVERTU LEFT CWY NEARSIDE/REBOUND		DAMAGE BACK.ROOF.FRONT	601
EHICLE 03(02)	CAR (29YRS-F SE20) BT - DRV NOT CONTACTED			600
EHICLE 04(02)	CAR (26YRS-M UNKN) BT - NEGATIVE	GOING AHEAD OTHER SW TO NE ON M O/S HIT FIRST		601

INTERPRETED LISTINGS MAP 27032003.doc