CAR TYPE: **DM, UNDM**
TITLE: **RECEPTACLE BOX**

**NOTE:** 1. DM SHOWN
UNDM SIMILAR

CAR TYPE: **DM, UNDM**
TITLE: **FUSE BOXES - POSITIVE AND NEGATIVE**




CAR TYPE: **DM, UNDM, T, SpT**
TITLE: **CONTACTORS**




CAR TYPE: **DM, UNDM**
TITLE: **EQUIPMENT CASE NO.1 GA**




CAR TYPE: **DM, UNDM**
TITLE: **RESISTANCE GRIDS GA**
**INSULATORS**




# 1972 Mark II Bakerloo Line Rolling Stock

**Location of Hazardous Materials Pictogram**

**Please read:**

**These Pictograms are representative and should not be taken to indicate that all these items will be found on every car type or every car of that type; Also items noted may be found in similar locations throughout the stock;**

**Neither should it be taken to represent all Hazardous Materials, as historically asbestos has been used in unusual applications throughout the LU (Tube Lines) network;**

**However we are confident that all known asbestos items are known, but if you do believe you encounter any suspect material please pass your concerns to the Duty Depot Manager who will contact the Tube Lines Hazardous Materials Unit for confirmation;**

**If any items on this Pictogram are found to be damaged, please report this to the Duty Depot Manager; Who will either:**

- **arrange for the damaged item to be replaced, if a safe system of works is in place;**
- **will inform the Tube Lines Hazardous Materials Unit, who will arrange for the necessary remedial works;**

**This document was produced by the Tube Lines Hazardous Materials Unit on the 23rd March 2011;**

CAR TYPE: **DM, UNDM**
TITLE: **EQUIPMENT CASE NO.2 GA**




CAR TYPE: **DM,UNDM**
TITLE: **DURASTEEL INSULATION**




CAR TYPE: **DM**
TITLE: **P.E.A.B. JUNCTION AND RELAY BOXES**




CAR TYPE: **DM,UNDM**
TITLE: **UNDERFRAME DURASTEEL INSULATION**