



Hazardous Material Asset Register - Detail for SharePoint



The purpose of this report is to detail the presence of any known (K), Presumed (P) or Strongly Presumed (SP) Asbestos Containing Materials (ACMs) within this location / asset. Any areas inaccessible during previous asbestos surveys are presumed (P) to contain ACMs until confirmed otherwise. All inaccessible areas will need to be surveyed prior to work being undertaken in these areas. Prior to any intrusive works commencing a Hazardous Materials Impact Assessment (F6048) must be submitted to hazardousmaterials@tfl.gov.uk All staff / contractors working on this property must remain vigilant during their works and if any suspect material is encountered which is likely to be disturbed, contact the Hazardous Materials team prior to continuing the impacted works. Associated photographs can be found listed against the Maximo Reference number on the subsequent report.

Run date: 19/12/2022 Line: JNP Assessment Status: All Material Status: All Material Type: All

Ref.	Status	Status Date	Main Line	Location Code	Location Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Positio	Notes	Qty. Metre	Qty. Units	Lead Paint %	Surface Code	Asbestos Type	Assessme Score	Date of Last Reinspectio	Report Ref.	Above False Ceiling	Below False Floor	
24276	ACTIVE	26/08/2014	P	D235-00-1/776	Plant Room - Station Building - Heathrow Terminal 4 Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed						0					
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							24276																
25552	ACTIVE	08/06/2021	P	D235-00-2/084/CLG-01	Ceiling: Solid - 1 - Lobby - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				No access above 2 x metal vent hatches						0					
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							25552																
24125	ACTIVE	08/06/2021	P	D235-00-2/244/FLR-01	Floor - 1 - Gantry - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				No access behind Metal Cable Tray						0					Yes
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							24125																
24208	ACTIVE	08/06/2021	P	D235-00-2/331/CLG-01	Ceiling: Suspended - 1 - Mess Room - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				No access above supalux ceiling tiles						0					
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							24208																
25568	ACTIVE	26/08/2014	P	D235-00-2/381	Disused Room - Station Building - Heathrow Terminal 4 Stn	No Access	Asbestos	No Access: Presumed				(Disused on station layout) Not Surveyed - none visible					Unencapsula medium density or encapsulated highly friable materials	Chrysotile	12				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							25568	1	0	2	2	2	1	2	2								
24217	ACTIVE	08/06/2021	P	D235-00-2/416/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				No access above 2 x metal Vent hatches						0					
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							24217																
24084	ACTIVE	08/06/2021	P	D235-00-2/417/CLG-01	Ceiling: Solid - 1 - Toilet - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				No access above false ceiling						0					
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							24084																
24088	ACTIVE	26/08/2014	P	D235-00-2/631	Stairs: Spiral - Station Building - Heathrow Terminal 4 Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed						0					



Hazardous Material Asset Register - Detail for SharePoint



Ref.	Status	Status Date	Main Line	Location Code	Location Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Positio	Notes	Qty. Metre	Qty. Units	Lead Paint %	Surface Code	Asbestos Type	Assessme Score	Date of Last Reinspectio	Report Ref.	Above False Ceiling	Below False Floor	
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							24088																
25089	ACTIVE	08/06/2021	P	D235-00-3/001/FLR-01	Floor - 1 - Booking Hall - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				No access to Inspection Chambers						0					Yes
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							25089																
24100	ACTIVE	08/06/2021	P	D235-00-3/071	Circulation Area - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				No access to Fire Cupboard						0					
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							24100																
25551	ACTIVE	08/06/2021	P	D235-00-3/071	Circulation Area - Station Building - Heathrow Terminal 4 Stn	Cable Duct: Other	Asbestos	Known				Cement cable duct - Exact location to be confirmed	1			Asbestos reinforced composites	Chrysotile	7					
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							25551	1	1	1	0	1	1	1	1								
24099	ACTIVE	08/06/2021	P	D235-00-3/071/CLG-01	Ceiling: Solid - 1 - Circulation Area - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				No access to access hatches within ceiling x4						0					Yes
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							24099																
25170	ACTIVE	08/06/2021	P	D235-00-3/071/FLR-01	Floor - 1 - Circulation Area - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				No access to below 13 x hatches to floor						0					Yes
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							25170																
24101	ACTIVE	16/11/2016	P	D235-00-3/201/FLR-01	Floor - 1 - Passage - Station Building - Heathrow Terminal 4 Stn	No Access	Asbestos	No Access: Presumed				Beneath 1 x hatch						0					Yes
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							24101																
24686	ACTIVE	08/06/2021	P	D235-00-3/243/WAL-001	Wall: Internal - 1 - Lobby - Station Building - Heathrow Terminal 4 Stn	Isolator Switches	Asbestos	Strongly Presumed				Iron clad isolator - Asbestos Components within Noted on survey as 2/243, incorrect SID number should be 3/243 and duplicated. no CFS within 2/243. No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.	1			Encapsulated medium density materials	Chrysotile	10	16/06/2003		N	N	
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							24686	1	1	2	1	1	1	1	2								



Hazardous Material Asset Register - Detail for SharePoint



Ref.	Status	Status Date	Main Line	Location Code	Location Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Positio	Notes	Qty. Metre	Qty. Units	Lead Paint %	Surface Code	Asbestos Type	Assessme Score	Date of Last Reinspectio	Report Ref.	Above False Ceiling	Below False Floor	
25173	ACTIVE	26/08/2014	P	D235-00-3/412/FLR-01	Floor - 1 - Store - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				Beneath 1 x hatch							0				Yes
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							25173																
24175	ACTIVE	26/08/2014	P	D235-00-3/415/FLR-01	Floor - 1 - Store - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				Beneath hatch							0				Yes
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							24175																
24178	ACTIVE	08/06/2021	P	D235-00-3/451	Tenancy - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				Supalux boxing back part of Tenancy - No access behind NB this property is managed by TFL Commercial Property							0				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							24178																
25175	ACTIVE	26/08/2014	P	D235-00-3/661/FLR-01	Floor - 1 - Switch Room - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				Beneath hatch							0				Yes
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							25175																
43216	ACTIVE	08/06/2021	P	D235-00-3/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Heathrow Terminal 4 Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Transformer Box Wall 1					Asbestos reinforced composites	Chrysotile	2	23/06/2015		N	N
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							43216	1	0	1	0												
43217	ACTIVE	08/06/2021	P	D235-00-3/661/WAL-001	Wall: Internal - 1 - Switch Room - Station Building - Heathrow Terminal 4 Stn	Cable Duct: Other	Asbestos	Strongly Presumed				Cable Ducts Wall 1					Asbestos reinforced composites	Chrysotile	2	23/06/2015		N	N
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							43217	1	0	1	0												
24254	ACTIVE	08/06/2021	P	D235-00-3/661/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminal 4 Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Electrical equipment					Asbestos reinforced composites	Chrysotile	6	16/06/2003		N	N
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							24254	1	0	2	0	1	1	0	1								
24255	ACTIVE	26/08/2014	P	D235-00-3/662/FLR-01	Floor - 1 - Switch Room - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				Beneath hatch							0				Yes
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							24255																
24256	ACTIVE	08/06/2021	P	D235-00-3/662/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminal 4 Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Electrical equipment					Asbestos reinforced composites	Chrysotile	6	16/06/2003		N	N
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							24256																



Hazardous Material Asset Register - Detail for SharePoint



Ref.	Status	Status Date	Main Line	Location Code	Location Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Positio	Notes	Qty. Metre	Qty. Units	Lead Paint %	Surface Code	Asbestos Type	Assessme Score	Date of Last Reinspectio	Report Ref.	Above False Ceiling	Below False Floor
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							24256	1	0	2	0	1	1	0	1							
24258	ACTIVE	08/06/2021	P	D235-00-3/663/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminal 4 Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Trunking				Asbestos reinforced composites	Chrysotile	6			N	N
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							24258	1	0	2	0	1	1	0	1							
43218	ACTIVE	08/06/2021	P	D235-00-3/663/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminal 4 Stn	Isolator Switches	Asbestos	Strongly Presumed				Wall 2, 6 Switch Box 4 x 60amps, 2 x 30amps				Encapsulated medium density materials	Chrysotile	3	23/06/2015		N	N
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							43218	1	0	1	1											
24221	ACTIVE	08/06/2021	P	D235-00-3/664/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminal 4 Stn	Isolator Switches	Asbestos	Strongly Presumed				1x Iron clad isolators, 1 X 30amps	1			Encapsulated medium density materials	Chrysotile	10	22/11/2007			
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							24221	1	1	2	1											2
24428	ACTIVE	08/06/2021	P	D235-00-3/665/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminal 4 Stn	Isolator Switches	Asbestos	Strongly Presumed				1x Iron clad isolators 1 x 30amps	1			Encapsulated medium density materials	Chrysotile	10	16/06/2003		N	N
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							24428	1	1	2	1											2
43223	ACTIVE	08/06/2021	P	D235-00-3/665/WAL-002	Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminal 4 Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				3 Transformer Boxes Wall 2				Asbestos reinforced composites	Chrysotile	2	23/06/2015		N	N
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							43223	1	0	1	0											
24260	ACTIVE	08/06/2021	P	D235-00-3/731/WAL-002	Wall: Internal - 2 - CER - Station Building - Heathrow Terminal 4 Stn	Isolator Switches	Asbestos	Strongly Presumed				2 x Iron clad isolators 2 x 60amps	2			Encapsulated medium density materials	Chrysotile	10	16/06/2003		N	N
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							24260	1	1	2	1											2
45205	ACTIVE	08/06/2021	P	D235-00-3/762	Vent Shaft - Station Building - Heathrow Terminal 4 Stn	Rope Gaskets	Asbestos	Strongly Presumed				Top level - Vent equipment				Chrysotile	1	16/06/2003			N	N
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							45205	1														
24265	ACTIVE	17/12/2020	P	D235-00-3/762	Vent Shaft - Station Building - Heathrow Terminal 4 Stn	Cable Duct: Other	Asbestos	Strongly Presumed				4x cable ducts	4			Asbestos reinforced composites	Chrysotile	7	29/06/2012		N	N



Hazardous Material Asset Register - Detail for SharePoint



Ref.	Status	Status Date	Main Line	Location Code	Location Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Positio	Notes	Qty. Metre	Qty. Units	Lead Paint %	Surface Code	Asbestos Type	Assessme Score	Date of Last Reinspectio	Report Ref.	Above False Ceiling	Below False Floor	
24265	ACTIVE	17/12/2020	P	D235-00-3/762	Vent Shaft - Station Building - Heathrow Terminal 4 Stn	Rope Gaskets	Asbestos	Strongly Presumed				Fan & ventilation equipment - no access to gaskets				Unencapsula medium density or encapsulated highly friable materials	Chrysotile	12	16/06/2003		N	N	
																							Ref.
24262	ACTIVE	08/06/2021	P	D235-00-3/762/FLR-01	Floor - 1 - Vent Shaft - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				Beneath hatch by wall 2						0				Yes	
																							Ref.
24264	ACTIVE	17/12/2020	P	D235-00-3/762/WAL-002	Wall: Internal - 2 - Vent Shaft - Station Building - Heathrow Terminal 4 Stn	LUL Heaters	Asbestos	Strongly Presumed				2 x Wall heaters		2		Unencapsula medium density or encapsulated highly friable materials	Chrysotile	10	29/06/2012		N	N	
																							Ref.
24263	ACTIVE	08/06/2021	P	D235-00-3/762/WAL-003	Wall: Internal - 3 - Vent Shaft - Station Building - Heathrow Terminal 4 Stn	Isolator Switches	Asbestos	Strongly Presumed				3x Iron clad isolators - 2x 200amps & 1x 100 amps		3		Encapsulatec medium density materials	Chrysotile	10	16/06/2003		N	N	
																							Ref.
24267	ACTIVE	26/08/2014	P	D235-00-3/771/FLR-01	Floor - 1 - Pump Room - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				Beneath hatch						0				Yes	
																							Ref.
25183	ACTIVE	08/06/2021	P	D235-00-3/771/WAL-004	Wall: Internal - 4 - Pump Room - Station Building - Heathrow Terminal 4 Stn	Other Electrical Boxes	Asbestos	Strongly Presumed				Trunking				Asbestos reinforced composites	Chrysotile	6	16/06/2003		N	N	
																							Ref.
24268	ACTIVE	08/06/2021	P	D235-00-3/771/WAL-004	Wall: Internal - 4 - Pump Room - Station Building - Heathrow Terminal 4 Stn	Isolator Switches	Asbestos	Strongly Presumed				5x Iron clad isolators - 4x30amps, 1x 60amps		5		Encapsulatec medium density materials	Chrysotile	10	16/06/2003		N	N	
																							Ref.



Hazardous Material Asset Register - Detail for SharePoint



Ref.	Status	Status Date	Main Line	Location Code	Location Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Positio	Notes	Qty. Metre	Qty. Units	Lead Paint %	Surface Code	Asbestos Type	Assessme Score	Date of Last Reinspectio	Report Ref.	Above False Ceiling	Below False Floor
24269	ACTIVE	16/11/2016	P	D235-00-3/771/WAL-004	Wall: Internal - 4 - Pump Room - Station Building - Heathrow Terminal 4 Stn	Gasket :Pipewo	Asbestos	No Access: Presumed				Gaskets in pumps equipment				Encapsulatec medium density materials	Chrysotile	8	16/06/2003			
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							24269	1	0	2	1	1	1	1	1							



Hazardous Material Asset Register - Detail for SharePoint



Ref.	Status	Status Date	Main Line	Location Code	Location Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Positio	Notes	Qty. Metre	Qty. Units	Lead Paint %	Surface Code	Asbestos Type	Assessme Score	Date of Last Reinspectio	Report Ref.	Above False Ceiling	Below False Floor	
24270	ACTIVE	26/08/2014	P	D235-00-3/786	Service Area - Station Building - Heathrow Terminal 4 Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed						0					
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							24270																
25184	ACTIVE	08/06/2021	P	D235-00-3/901/CLG-01	Ceiling: Suspended - 1 - Tenancy - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				Above false ceiling NB Property managed by TFL Commercial Property						0				Yes	
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							25184																
24274	ACTIVE	26/08/2014	P	D235-00-3/902/FLR-01	Floor - 1 - Store - Station Building - Heathrow Terminal 4 Stn	Void	Asbestos	No Access: Presumed				Beneath computer tiles						0					Yes
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							24274																
24277	ACTIVE	08/06/2021	P	D235-00-A/776	Plant Room - Station Building - Heathrow Terminal 4 Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed NB Managed by LU Power & Electrical						0					
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							24277																
24278	ACTIVE	08/06/2021	P	D235-00-B/776	Plant Room - Station Building - Heathrow Terminal 4 Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed NB Managed by LU Power & Electrical						0					
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							24278																
25185	ACTIVE	08/06/2021	P	D235-00-C/776	Plant Room - Station Building - Heathrow Terminal 4 Stn	No Access	Asbestos	No Access: Presumed				Not Surveyed NB Managed by LU Power & Electrical						0					
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							25185																

Hazardous Materials - Photographs for SharePoint

Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register


Reference:	24276
Description:	Asbestos: No Access: Presumed D235-00-1/776: Plant Room - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	No Access
Comments:	Not Surveyed

Reference:	25552
Description:	Asbestos: No Access: Presumed D235-00-2/084/CLG-01: Ceiling: Solid - 1 - Lobby - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Void
Comments:	No access above 2 x metal vent hatches

Reference:	24125
Description:	Asbestos: No Access: Presumed D235-00-2/244/FLR-01: Floor - 1 - Gantry - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Void
Comments:	No access behind Metal Cable Tray

Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	24208
Description:	Asbestos: No Access: Presumed D235-00-2/331/CLG-01: Ceiling: Suspended - 1 - Mess Room - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Void
Comments:	No access above supalux ceiling tiles
Reference:	25568
Description:	Asbestos: No Access: Presumed D235-00-2/381: Disused Room - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	No Access
Comments:	(Disused on station layout) Not Surveyed - none visible
Reference:	24217
Description:	Asbestos: No Access: Presumed D235-00-2/416/CLG-01: Ceiling: Solid - 1 - Toilet - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Void
Comments:	No access above 2 x metal Vent hatches
Reference:	24084
Description:	Asbestos: No Access: Presumed D235-00-2/417/CLG-01: Ceiling: Solid - 1 - Toilet - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Void
Comments:	No access above false ceiling



Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	24088
Description:	Asbestos: No Access: Presumed D235-00-2/631: Stairs: Spiral - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	No Access
Comments:	Not Surveyed

Reference:	25089
Description:	Asbestos: No Access: Presumed D235-00-3/001/FLR-01: Floor - 1 - Booking Hall - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Void
Comments:	No access to Inspection Chambers

Reference:	24100
Description:	Asbestos: No Access: Presumed D235-00-3/071: Circulation Area - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Void
Comments:	No access to Fire Cupboard

Reference:	25551
Description:	Asbestos: Known D235-00-3/071: Circulation Area - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Cable Duct: Other
Comments:	Cement cable duct - Exact location to be confirmed

Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	24099
Description:	Asbestos: No Access: Presumed D235-00-3/071/CLG-01: Ceiling: Solid - 1 - Circulation Area - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Void
Comments:	No access to access hatches within ceiling x4

Reference:	25170
Description:	Asbestos: No Access: Presumed D235-00-3/071/FLR-01: Floor - 1 - Circulation Area - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Void
Comments:	No access to below 13 x hatches to floor

Reference:	24101
Description:	Asbestos: No Access: Presumed D235-00-3/201/FLR-01: Floor - 1 - Passage - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	No Access
Comments:	Beneath 1 x hatch

Reference:	24686
Description:	Asbestos: Strongly Presumed D235-00-3/243/WAL-001: Wall: Internal - 1 - Lobby - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Isolator Switches
Comments:	Iron clad isolator - Asbestos Components within Noted on survey as 2/243, incorrect SID number should be 3/243 and duplicated. no CFS within 2/243. No electrician on site during 2020 re-inspection to open boxes for inspection - therefore cannot score material within.

Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	25173
Description:	Asbestos: No Access: Presumed D235-00-3/412/FLR-01: Floor - 1 - Store - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Void
Comments:	Beneath 1 x hatch


Reference:	24175
Description:	Asbestos: No Access: Presumed D235-00-3/415/FLR-01: Floor - 1 - Store - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Void
Comments:	Beneath hatch

Reference:	24178
Description:	Asbestos: No Access: Presumed D235-00-3/451: Tenancy - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Void
Comments:	Supalux boxing back part of Tenancy - No access behind NB this property is managed by TFL Commercial Property

Reference:	25175
Description:	Asbestos: No Access: Presumed D235-00-3/661/FLR-01: Floor - 1 - Switch Room - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Void
Comments:	Beneath hatch


Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	43217
Description:	Asbestos: Strongly Presumed D235-00-3/661/WAL-001: Wall: Internal - 1 - Switch Room - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Cable Duct: Other
Comments:	Cable Ducts Wall 1
Reference:	43216
Description:	Asbestos: Strongly Presumed D235-00-3/661/WAL-001: Wall: Internal - 1 - Switch Room - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Other Electrical Boxes
Comments:	Transformer Box Wall 1
Reference:	24254
Description:	Asbestos: Strongly Presumed D235-00-3/661/WAL-002: Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Other Electrical Boxes
Comments:	Electrical equipment



Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	24255
Description:	Asbestos: No Access: Presumed D235-00-3/662/FLR-01: Floor - 1 - Switch Room - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Void
Comments:	Beneath hatch
Reference:	24256
Description:	Asbestos: Strongly Presumed D235-00-3/662/WAL-002: Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Other Electrical Boxes
Comments:	Electrical equipment
Reference:	24258
Description:	Asbestos: Strongly Presumed D235-00-3/663/WAL-002: Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Other Electrical Boxes
Comments:	Trunking



Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	43218
Description:	Asbestos: Strongly Presumed D235-00-3/663/WAL-002: Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Isolator Switches
Comments:	Wall 2, 6 Switch Box 4 x 60amps, 2 x 30amps
Reference:	24221
Description:	Asbestos: Strongly Presumed D235-00-3/664/WAL-002: Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Isolator Switches
Comments:	1x Iron clad isolators, 1 X 30amps
Reference:	24428
Description:	Asbestos: Strongly Presumed D235-00-3/665/WAL-002: Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Isolator Switches
Comments:	1x Iron clad isolators 1 x 30amps
Reference:	43223
Description:	Asbestos: Strongly Presumed D235-00-3/665/WAL-002: Wall: Internal - 2 - Switch Room - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Other Electrical Boxes
Comments:	3 Transformer Boxes Wall 2



Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	24260
Description:	Asbestos: Strongly Presumed D235-00-3/731/WAL-002: Wall: Internal - 2 - CER - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Isolator Switches
Comments:	2 x Iron clad isolators 2 x 60amps

Reference:	45205
Description:	Asbestos: Strongly Presumed D235-00-3/762: Vent Shaft - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Rope Gaskets
Comments:	Top level - Vent equipment

Reference:	24266
Description:	Asbestos: Strongly Presumed D235-00-3/762: Vent Shaft - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Rope Gaskets
Comments:	Fan & ventilation equipment - no access to gaskets

Reference:	24265
Description:	Asbestos: Strongly Presumed D235-00-3/762: Vent Shaft - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Cable Duct: Other
Comments:	4x cable ducts

Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	24262
Description:	Asbestos: No Access: Presumed D235-00-3/762/FLR-01: Floor - 1 - Vent Shaft - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Void
Comments:	Beneath hatch by wall 2

Reference:	24264
Description:	Asbestos: Strongly Presumed D235-00-3/762/WAL-002: Wall: Internal - 2 - Vent Shaft - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	LUL Heaters
Comments:	2 x Wall heaters

Reference:	24263
Description:	Asbestos: Strongly Presumed D235-00-3/762/WAL-003: Wall: Internal - 3 - Vent Shaft - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Isolator Switches
Comments:	3x Iron clad isolators - 2x 200amps & 1x 100 amps

Reference:	24267
Description:	Asbestos: No Access: Presumed D235-00-3/771/FLR-01: Floor - 1 - Pump Room - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Void
Comments:	Beneath hatch

Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	25183
Description:	Asbestos: Strongly Presumed D235-00-3/771/WAL-004: Wall: Internal - 4 - Pump Room - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Other Electrical Boxes
Comments:	Trunking
Reference:	24268
Description:	Asbestos: Strongly Presumed D235-00-3/771/WAL-004: Wall: Internal - 4 - Pump Room - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Isolator Switches
Comments:	5x Iron clad isolators - 4x30amps, 1x 60amps
Reference:	24269
Description:	Asbestos: No Access: Presumed D235-00-3/771/WAL-004: Wall: Internal - 4 - Pump Room - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified
Hazard Area:	Gasket :Pipework
Comments:	Gaskets in pumps equipment

Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	24270	
Description:	Asbestos: No Access: Presumed D235-00-3/786: Service Area - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified	
Hazard Area:	No Access	
Comments:	Not Surveyed	
Reference:	25184	
Description:	Asbestos: No Access: Presumed D235-00-3/901/CLG-01: Ceiling: Suspended - 1 - Tenancy - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified	
Hazard Area:	Void	
Comments:	Above false ceiling NB Property managed by TFL Commercial Property	
Reference:	24274	
Description:	Asbestos: No Access: Presumed D235-00-3/902/FLR-01: Floor - 1 - Store - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified	
Hazard Area:	Void	
Comments:	Beneath computer tiles	
Reference:	24277	
Description:	Asbestos: No Access: Presumed D235-00-A/776: Plant Room - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified	
Hazard Area:	No Access	
Comments:	Not Surveyed NB Managed by LU Power & Electrical	





Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	24278	
Description:	Asbestos: No Access: Presumed D235-00-B/776: Plant Room - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified	
Hazard Area:	No Access	
Comments:	Not Surveyed NB Managed by LU Power & Electrical	
Reference:	25185	
Description:	Asbestos: No Access: Presumed D235-00-C/776: Plant Room - Station Building - Heathrow Terminal 4 Stn Start(m): Not Specified Finish(m): Not Specified	
Hazard Area:	No Access	
Comments:	Not Surveyed NB Managed by LU Power & Electrical	