

Id 2775246 Status RE Received Navigator Source T Telephone  
Recorded By [Redacted] Admin Unit LOHAC\_CX  
Responsibility Of [Redacted]  Open Enquiries  All Enquiries

Enquiry Details Further Details Actions Damage Associations Items

Name [Redacted] Type ENQUIRER Ref [Redacted]  
Organisation ASSET OPS - TFL Email [Redacted]  
Postcode [Redacted] Number [Redacted] Building [Redacted] Sub. [Redacted] Home [Redacted] Flag [Redacted]  
Street [Redacted] Work [Redacted]  
Dependant Street [Redacted] Locality [Redacted] Mobile [Redacted]  
Town [Redacted] Fax [Redacted] Primary Contact   
County [Redacted] Property Type [Redacted] Search Contacts Summary View Contact Det...

Category ECO Emergency Call Outs Class FWY Footway  
Enquiry Type BOL Bollards - Conc/Plastic/Metal  
Location walworth road o/s elephant and castle shopping centre e/b  
Description Stumped column requires barriers to be placed. Dangerous trip hazard  
Action/Remarks 12:51 made safe with 2 barriers and 1 cone  
Injuries  
Damage

Date Recorded 17-JAN-2019 12:09 Incident Date & Time 17-JAN-2019 12:09 Correspondence Date [Redacted] Corr Received Date [Redacted]  
Follow Up 1 [Redacted] Acknowledgment [Redacted] Follow Up 2 [Redacted] Follow Up 3 [Redacted]  
Priority 2 Target Date 17-JAN-2019 14:09 Complete Date [Redacted] Reference No [Redacted]  
Date/Time Arrived 17-JAN-2019 12:42 Reason for Late Arrival [Redacted]

**Associated Asset** Find [Redacted] Create Start [Redacted] End [Redacted] XSP [Redacted]  
**Associated Network** Road Type [Redacted] Closed  Easting [Redacted]  
Road [Redacted] Northing [Redacted]  
Get From Map [Redacted]