

Full information from our Network Asset Management System (NAMS) in relation to potholes on Grosvenor Place.  
Public Enquiries Management (PEM) records:

Incident Date	Location	Description	Category	Class	Type	Actions Taken
15-Oct-19	Opposite 18 Grosvenor place	Large pothole	Inspection Response	Carriageway	Pothole	JOB ALREADY DONE = 03:13 PERM 1 X LARGER PATCH NEEDED WITH H.R.A
09-Dec-19	OS NO 18 GROSVENOR PLACE	POTHOLE & ROAD DAMAGE	Inspection Response	Carriageway	Carriageway Defect	VIAFIXED - LARGE POTHOLE AREA VIAFIXED - PERM MISSING SETS NEEDS REPLACING LEFT: 23:13
12-Dec-19	Opposite 19 Grosvenor Place"	: large pothole on double red lines	Emergency Call Outs	Carriageway	Carriageway Defect	POTHOLE VIAFIXED LEFT: 13:06 F.T.R

17-Dec-19	Grosvenor Place sb os no 18	large pothole on lane 1	Emergency Call Outs	Carriageway	Carriageway Defect	make safe large pothole in failed patch with viafix , new patch required
24-Dec-19	Grosvenor Place s/b opposite no 18	pothole in lane 1 to make safe	Inspection Response	Carriageway	Pothole	09:06 make safe recurring large pothole in failed patch

Defect Records:

Inspection date	Road Name	Location	Description	Status	Activity Type	Defect Type	Action Type	Due Date
12/12/2019	A302, GROSVENOR PLACE,,(LWR GROSVENOR PL TO DUKE OF WELLINGTON PL),SW1X	18 Grosvenor Place	Pothole and Road Damage	Completed	Concrete Carriageway Repairs	Pothole	Permanent	09/01/2020