

1.2 Data Sheet

Structure No.	NT 24
Line	Northern Line
Over	Track and platform
Location	Colindale Station
Obstruction	Colindale Avenue
Span	Three simply supported spans: west span 7.12m, centre span 6.84m, east span 4.56m
Date of Construction	circa 1922
Form of Construction	Filler beam deck, brick faced abutments and brick piers
key Constructional Materials	steel, concrete and stock brick
Date of Principal Inspection	25 June 1998
Minimum Condition Score	76%
Assessed Capacity	Deck under carriageway: 40 Tonnes Deck under verges: 3 Tonnes