

INSPECTION RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Date Inspected	Inspection Id	Road Id	Road Name	Initiation Type
03-Mar-2018	3020522	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
05-Mar-2018	3020627	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
06-Mar-2018	3022663	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
06-Mar-2018	3022642	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
08-Mar-2018	3026560	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
15-Mar-2018	3034019	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
22-Mar-2018	3041755	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
23-Mar-2018	3042967	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
29-Mar-2018	3048757	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
29-Mar-2018	3048756	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
05-Apr-2018	3055547	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
12-Apr-2018	3062291	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
19-Apr-2018	3067446	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
26-Apr-2018	3075619	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
03-May-2018	3079666	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
10-May-2018	3086951	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
17-May-2018	3090520	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
24-May-2018	3093864	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
31-May-2018	3099022	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
07-Jun-2018	3107124	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
14-Jun-2018	3111457	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
15-Jun-2018	3112166	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
21-Jun-2018	3118050	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections

INSPECTION RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Date Inspected	Inspection Id	Road Id	Road Name	Initiation Type
28-Jun-2018	3123331	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
05-Jul-2018	3129381	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
12-Jul-2018	3133854	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
26-Jul-2018	3144736	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
02-Aug-2018	3150959	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
07-Aug-2018	3153831	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
07-Aug-2018	3153572	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
07-Aug-2018	3153571	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
09-Aug-2018	3156030	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
16-Aug-2018	3162212	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
16-Aug-2018	3162279	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
03-Sep-2018	3175770	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
03-Sep-2018	3175769	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
03-Sep-2018	3175808	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
04-Sep-2018	3176749	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
04-Sep-2018	3176748	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
04-Sep-2018	3176810	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
02-Oct-2018	3200825	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
11-Oct-2018	3214545	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
18-Oct-2018	3221518	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
18-Oct-2018	3221517	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
06-Nov-2018	3240745	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections

INSPECTION RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Date Inspected	Inspection Id	Road Id	Road Name	Initiation Type
22-Nov-2018	3260063	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
22-Nov-2018	3260222	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
22-Nov-2018	3260872	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
04-Dec-2018	3271456	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
04-Dec-2018	3271455	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
04-Dec-2018	3271452	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
08-Jan-2019	3303761	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
08-Jan-2019	3303760	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
10-Jan-2019	3330202	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
11-Jan-2019	3330203	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
17-Jan-2019	3330205	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
24-Jan-2019	3330208	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
24-Jan-2019	3330209	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
31-Jan-2019	3330218	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
04-Feb-2019	3333925	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
05-Feb-2019	3335533	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
14-Feb-2019	3352792	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
21-Feb-2019	3357998	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
28-Feb-2019	3361285	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
05-Mar-2019	3366252	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
14-Mar-2019	3380612	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
14-Mar-2019	3380610	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections

INSPECTION RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Date Inspected	Inspection Id	Road Id	Road Name	Initiation Type
16-Mar-2019	3442003	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
21-Mar-2019	3395184	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
28-Mar-2019	3399610	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
04-Apr-2019	3403693	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
11-Apr-2019	3410275	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
17-Apr-2019	3417812	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
25-Apr-2019	3421291	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
02-May-2019	3428701	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
07-May-2019	3436907	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
16-May-2019	3442192	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
23-May-2019	3448025	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
30-May-2019	3451654	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
06-Jun-2019	3456798	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
13-Jun-2019	3464582	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
20-Jun-2019	3472977	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
27-Jun-2019	3475843	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
02-Jul-2019	3477502	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
12-Jul-2019	3489187	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
18-Jul-2019	3495130	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
25-Jul-2019	3498630	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
01-Aug-2019	3505022	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
08-Aug-2019	3509700	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections

INSPECTION RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Date Inspected	Inspection Id	Road Id	Road Name	Initiation Type
15-Aug-2019	3516770	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
22-Aug-2019	3519743	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
29-Aug-2019	3524881	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
29-Aug-2019	3524880	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
03-Sep-2019	3529413	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
05-Sep-2019	3529611	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
12-Sep-2019	3538682	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
19-Sep-2019	3541496	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
26-Sep-2019	3550141	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
03-Oct-2019	3554552	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
08-Oct-2019	3561810	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
10-Oct-2019	3561814	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
10-Oct-2019	3563245	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
17-Oct-2019	3580535	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
24-Oct-2019	3580623	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
31-Oct-2019	3586924	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
04-Nov-2019	3600768	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
14-Nov-2019	3606852	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
21-Nov-2019	3610728	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
28-Nov-2019	3618792	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
03-Dec-2019	3620992	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
12-Dec-2019	3635532	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections

INSPECTION RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Date Inspected	Inspection Id	Road Id	Road Name	Initiation Type
19-Dec-2019	3643350	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
27-Dec-2019	3645861	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
02-Jan-2020	3656971	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
07-Jan-2020	3665403	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
07-Jan-2020	3659612	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
07-Jan-2020	3659615	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
16-Jan-2020	3671918	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
16-Jan-2020	3671919	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
23-Jan-2020	3679506	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
30-Jan-2020	3695092	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
06-Feb-2020	3697099	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
13-Feb-2020	3704915	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections
20-Feb-2020	3714064	0000A232_3/00030	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Safety Inspections

DEFECT RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
737421	06-Mar-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon flyover jc violet lane A232 cro	remove graffiti from subway wall 4D GRGE Graffiti General (XY:531879.8 164897) (Ref:LSO311759) LSO311759_DSCI0008.JPG LSO311759_DSCI0009.JPG	COMPLETED	2L	TFL: Structures	Graffiti General	Permanent	03-Apr-2018	Low Priority De
737401	06-Mar-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 duppas hill road jn hillside rd wb A232	kerbs req reset 3n@ CHAL Kerb/channel block alignment (XY:531835.5 164889.1) (Ref:LSO208306) LSO208306_DSCI0005.JPG LSO208306_DSCI0006.JPG	SELECTED	2M	Kerbs,Edging,P reformed Channels	Kerb/channel block alignment	Permanent	03-Apr-2018	28 Day Defect
738956	15-Mar-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon flyover jc pump pail sth sb A23	T73347 req sma 4N POTH Pothole (XY:532323.2 165216.8) (Ref:LSO311840) LSO311840_DSCI0031.JPG LSO311840_DSCI0032.JPG	COMPLETED	1	Minor Carriageway Repairs	Pothole	Permanent	12-Apr-2018	Priority 1
738956	15-Mar-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon flyover jc pump pail sth sb A23	T73347 req sma 4N POTH Pothole (XY:532323.2 165216.8) (Ref:LSO311840) LSO311840_DSCI0031.JPG LSO311840_DSCI0032.JPG	COMPLETED	1	Minor Carriageway Repairs	Pothole	Temporary	16-Mar-2018	Priority 1
739962	21-Mar-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon Flyover//River Wandle Car Park	Remove fallen bricks from below - River Wandle Car Park	COMPLETED	1E	Sweeping And Cleansing	Debris in hard shoulder	Permanent	18-Apr-2018	Priority 1 (ECO
740271	22-Mar-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) a232 croydon flyover wb jct pump p	NULL	COMPLETED	1	Minor Carriageway Repairs	Pothole	Permanent	19-Apr-2018	Priority 1
740271	22-Mar-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) a232 croydon flyover wb jct pump p	NULL	COMPLETED	1	Minor Carriageway Repairs	Pothole	Temporary	23-Mar-2018	Priority 1
740450	24-Mar-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Sheldon St, Croydon CR0 1SS	oil spill	CANCELLED	1E	Sweeping And Cleansing	Debris in traffic lane	Permanent	21-Apr-2018	Priority 1 (ECO

DEFECT RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
740454	24-Mar-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Sheldon St, Croydon CR0 1SS	OIL SPILL	COMPLETED	1E	Sweeping And Cleansing	Debris in traffic lane	Permanent	21-Apr-2018	Priority 1 (ECO)
740760	27-Mar-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon Flyover approx 10m before the exit to Pump pail South Lane 1	Make safe deep carriageway pothole. (T73627)	COMPLETED	1E	Minor Carriageway Repairs	Pothole	Permanent	24-Apr-2018	Priority 1 (ECO)
740760	27-Mar-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon Flyover approx 10m before the exit to Pump pail South Lane 1	Make safe deep carriageway pothole. (T73627)	COMPLETED	1E	Minor Carriageway Repairs	Pothole	Temporary	28-Mar-2018	Priority 1 (ECO)
741058	28-Mar-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon Flyover J/W Davenant Rd	klb/cone replacement	COMPLETED	1	Safety Bollards: Face/Structure/ Fixings	Damaged/deformed	Permanent	29-Mar-2018	Priority 1
741158	29-Mar-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a23 croydon flyover wb jct pump pail sth	T73710 pothole req sma 4n POTH Pothole (XY:532323.1 165216.8) (Ref:LSO406942)	COMPLETED	1	Minor Carriageway Repairs	Pothole	Permanent	26-Apr-2018	Priority 1
741158	29-Mar-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a23 croydon flyover wb jct pump pail sth	T73710 pothole req sma 4n POTH Pothole (XY:532323.1 165216.8) (Ref:LSO406942)	COMPLETED	1	Minor Carriageway Repairs	Pothole	Temporary	30-Mar-2018	Priority 1
741159	29-Mar-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a23 croydon flyover eb jct duppas hill road	T73711 pothole on GY req rst Gy 4n CKIR Cracking around ironwork (XY:531827.6 164902.6) (Ref:LSO406943)	COMPLETED	1	Covers,Gratings,Frames,Boxes	Cracking around ironwork	Permanent	26-Apr-2018	Priority 1
741159	29-Mar-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a23 croydon flyover eb jct duppas hill road	T73711 pothole on GY req rst Gy 4n CKIR Cracking around ironwork (XY:531827.6 164902.6) (Ref:LSO406943)	COMPLETED	1	Covers,Gratings,Frames,Boxes	Cracking around ironwork	Temporary	30-Mar-2018	Priority 1
741452	03-Apr-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Duppas Hill Road, Croydon (j/w hillside road)	RTC - Damaged PGR	COMPLETED	1E	Safety Fences: Metal/Concrete	Accident damage	Permanent	01-May-2018	Priority 1 (ECO)
741452	03-Apr-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Duppas Hill Road, Croydon (j/w hillside road)	RTC - Damaged PGR	COMPLETED	1E	Safety Fences: Metal/Concrete	Accident damage	Temporary	04-Apr-2018	Priority 1 (ECO)

DEFECT RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
743087	12-Apr-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 croydon flyover wb jct hillside rd	T74073 2x sites req rst/new kerb 4n CHAL Kerb/channel block alignment (XY:531838.8 164893.8) (Ref:LSO407000) LSO407000_DSCI0019.JPG LSO407000_DSCI0020.JPG	COMPLETED	1	Kerbs,Edging,P reformed Channels	Kerb/channel block alignment	Permanent	10-May-2018	Priority 1
743087	12-Apr-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 croydon flyover wb jct hillside rd	T74073 2x sites req rst/new kerb 4n CHAL Kerb/channel block alignment (XY:531838.8 164893.8) (Ref:LSO407000) LSO407000_DSCI0019.JPG LSO407000_DSCI0020.JPG	COMPLETED	1	Kerbs,Edging,P reformed Channels	Kerb/channel block alignment	Temporary	13-Apr-2018	Priority 1
744297	19-Apr-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 croydon flyover wb jct pump pail Sth	T74220 pothole req sma 4n POTH Pothole (XY:532286.8 165208.3) (Ref:LSO407028)	COMPLETED	1	Minor Carriageway Repairs	Pothole	Permanent	20-Apr-2018	Priority 1
748620	23-May-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) @A232 CROYDON FLYOVER W/B	NULL	AVAILABLE	2H	Safety Bollards: Face/Structure/ Fixings	Lamp failure	Permanent	30-May-2018	7 Day Defect
748621	23-May-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) @A232 CROYDON FLYOVER W/B	NULL	AVAILABLE	2H	Road Lighting: Lamp Failures	Lamp Out 1	Permanent	30-May-2018	7 Day Defect
748622	23-May-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) @A232 CROYDON FLYOVER W/B	NULL	INSTRUCTED	2H	Road Lighting: Lamp Failures	Lamp Out 1	Permanent	30-May-2018	7 Day Defect
748623	23-May-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) @A232 CROYDON FLYOVER E/B	NULL	AVAILABLE	2H	Road Lighting: Lamp Failures	Lamp Out 1	Permanent	30-May-2018	7 Day Defect
748624	23-May-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) @A232 CROYDON FLYOVER W/B	NULL	INSTRUCTED	2H	Road Lighting: Lamp Failures	Lamp Out 1	Permanent	30-May-2018	7 Day Defect
748625	23-May-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) @A232 CROYDON FLYOVER E/B	NULL	CANCELLED	2H	Road Lighting: Lamp Failures	Lamp Out 1	Permanent	30-May-2018	7 Day Defect

DEFECT RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
748626	23-May-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) @A232 CROYDON FLYOVER W/B	NULL	COMPLETED	2H	Road Lighting: Lamp Failures	Lamp Out 1	Permanent	30-May-2018	7 Day Defect
748627	23-May-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) @A232 CROYDON FLYOVER E/B	NULL	AVAILABLE	2H	Road Lighting: Lamp Failures	Lamp Out 1	Permanent	30-May-2018	7 Day Defect
750700	07-Jun-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon flyover jc vio;et lan	NULL	COMPLETED	1	Safety Bollards: Face/Structure/ Fixings	Accident damage	Permanent	05-Jul-2018	Priority 1
750700	07-Jun-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon flyover jc vio;et lan	NULL	COMPLETED	1	Safety Bollards: Face/Structure/ Fixings	Accident damage	Temporary	08-Jun-2018	Priority 1
758768	07-Aug-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon flyover @ davenant rd wb A232 c	kerbs req reset 3n@ CHAL Kerb/channel block alignment (XY:531836.2 164889) (Ref:LSO209135) LSO209135_DSCI0005.JPG LSO209135_DSCI0006.JPG	COMPLETED	2M	Kerbs,Edging,P reformed Channels	Kerb/channel block alignment	Permanent	04-Sep-2018	28 Day Defect
758760	07-Aug-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 duppas hill violet lane S Way A232 du	graff remove 3D @ GRGE Graffiti General (XY:531881.1 164890.2) (Ref:LSO112847) LSO112847_DSCN6551.JPG LSO112847_DSCN6552.JPG	COMPLETED	2M	TFL: Structures	Graffiti General	Permanent	04-Sep-2018	28 Day Defect
758761	07-Aug-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 duppas hill violet lane S Way A232 du	graff 3D @ GRGE Graffiti General (XY:531879 164906.7) (Ref:LSO112848) LSO112848_DSCN6553.JPG LSO112848_DSCN6554.JPG	COMPLETED	2M	TFL: Structures	Graffiti General	Permanent	04-Sep-2018	28 Day Defect
760299	16-Aug-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) a232 croydon flyover wb jct edridg	NULL	COMPLETED	1	Safety Bollards: Face/Structure/ Fixings	Shell Missing/Detached	Permanent	13-Sep-2018	Priority 1

DEFECT RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
760299	16-Aug-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) a232 croydon flyover wb jct edridg	NULL	COMPLETED	1	Safety Bollards: Face/Structure/ Fixings	Shell Missing/Detached	Temporary	17-Aug-2018	Priority 1
762561	03-Sep-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 croydon flyover wb jct park lane	req remark 3n WEAR Wear (XY:532552.1 165240) (Ref:LSO407707) LSO407707_DSC06135.JPG LSO407707_DSC06136.JPG	COMPLETED	2M	Road Markings:	Wear	Permanent	01-Oct-2018	28 Day Defect
762560	03-Sep-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 croydon flyover wb jct park lane	sunken req rst GY 3n CKIR Cracking around ironwork (XY:532544.6 165241.1) (Ref:LSO407706) LSO407706_DSC06133.JPG LSO407706_DSC06134.JPG	SELECTED	2M	Covers,Gratings, Frames, Boxes	Cracking around ironwork	Permanent	01-Oct-2018	28 Day Defect
762593	03-Sep-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon f over sb o/s quaker hse A232 c	req sma patch BECK Blacktop : extensive cracking (XY:532540.1 165249.6) (Ref:LSO112993) LSO112993_DSCN6988.JPG LSO112993_DSCN6989.JPG	SELECTED	2M	Minor Carriageway Repairs	Blacktop : extensive cracking	Permanent	01-Oct-2018	28 Day Defect
762778	04-Sep-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 croydon fly SU jct duppas hill park	graf req clean 3d GRGE Graffiti General (XY:531879 164910.7) (Ref:LSO407718) LSO407718_DSC06176.JPG LSO407718_DSC06177.JPG	SELECTED	2L	TFL: Structures	Graffiti General	Permanent	02-Oct-2018	Low Priority De
762779	04-Sep-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 croydon fly SU jct duppas hill rd	req graf clean 3d GRGE Graffiti General (XY:531882.1 164882.3) (Ref:LSO407719) LSO407719_DSC06178.JPG LSO407719_DSC06179.JPG	SELECTED	2M	TFL: Structures	Graffiti General	Permanent	02-Oct-2018	28 Day Defect

DEFECT RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
762833	04-Sep-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 duppas hill subway nb side A232 duppas	graff 3D GRGE Graffiti General (XY:531878.4 164915.7) (Ref:LSO113009) LSO113009_DSCN7041.JPG LSO113009_DSCN7042.JPG	COMPLETED	2M	TFL: Structures	Graffiti General	Permanent	02-Oct-2018	28 Day Defect
767028	02-Oct-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon fover jn hillside ro	NULL	COMPLETED	1	Kerbs,Edging,P reformed Channels	Kerb/channel block alignment	Permanent	30-Oct-2018	Priority 1
767028	02-Oct-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon fover jn hillside ro	NULL	COMPLETED	1	Kerbs,Edging,P reformed Channels	Kerb/channel block alignment	Temporary	03-Oct-2018	Priority 1
768380	11-Oct-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon flyover os unitarian church A23	T1825 animal carcass req clean 3d ANCS Ancillaries defective (XY:532525 165250.5) (Ref:LSO209542) LSO209542_DSCI0015.JPG LSO209542_DSCI0016.JPG	COMPLETED	1	Sweeping And Cleansing	Animal Carcass	Permanent	08-Nov-2018	Priority 1
768380	11-Oct-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon flyover os unitarian church A23	T1825 animal carcass req clean 3d ANCS Ancillaries defective (XY:532525 165250.5) (Ref:LSO209542) LSO209542_DSCI0015.JPG LSO209542_DSCI0016.JPG	COMPLETED	1	Sweeping And Cleansing	Animal Carcass	Temporary	12-Oct-2018	Priority 1
768891	17-Oct-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(A232) Croydon Flyover jnc Edridge Rd	KLB re-pin	COMPLETED	1	Safety Bollards: Face/Structure/ Fixings	Shell Missing/Detached	Permanent	18-Oct-2018	Priority 1
768898	17-Oct-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon Flyover just B4 off slip to Pump Pail South	c/w Pothole	COMPLETED	1	Minor Carriageway Repairs	Pothole	Permanent	14-Nov-2018	Priority 1
768898	17-Oct-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon Flyover just B4 off slip to Pump Pail South	c/w Pothole	COMPLETED	1	Minor Carriageway Repairs	Pothole	Temporary	18-Oct-2018	Priority 1

DEFECT RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
769200	18-Oct-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon flyover jc pump pail sth off sl	T1889 req sma 4N NO PHOTOS POTH Pothole (XY:532296.6 165210.1) (Ref:LSO313026)	COMPLETED	1	Minor Carriageway Repairs	Pothole	Permanent	15-Nov-2018	Priority 1
769200	18-Oct-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon flyover jc pump pail sth off sl	T1889 req sma 4N NO PHOTOS POTH Pothole (XY:532296.6 165210.1) (Ref:LSO313026)	COMPLETED	1	Minor Carriageway Repairs	Pothole	Temporary	19-Oct-2018	Priority 1
769201	18-Oct-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon flyover jc park lane so 60 wb A	reset kerb 3D CHAL Kerb/channel block alignment (XY:532541.4 165240.9) (Ref:LSO313031) LSO313031_DSCN7092.jpg LSO313031_DSCN7093.jpg	COMPLETED	2M	Kerbs,Edging,P reformed Channels	Kerb/channel block alignment	Permanent	15-Nov-2018	28 Day Defect
769241	19-Oct-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 croydon fly over jc pump pail south off slip	¿cw pothole make safe 24hr CAT1 red check	COMPLETED	1	Minor Carriageway Repairs	Pothole	Permanent	16-Nov-2018	Priority 1
769241	19-Oct-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 croydon fly over jc pump pail south off slip	¿cw pothole make safe 24hr CAT1 red check	COMPLETED	1	Minor Carriageway Repairs	Pothole	Temporary	20-Oct-2018	Priority 1
771463	06-Nov-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 duppas hill rd jc duppas hill terrace e	remove graffiti from subway 4D GRGE Graffiti General (XY:531888.3 164919.9) (Ref:LSO313164) LSO313164_DSCN7373.jpg LSO313164_DSCN7374.jpg	COMPLETED	2M	TFL: Structures	Graffiti General	Permanent	04-Dec-2018	28 Day Defect
771690	08-Nov-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon Flyover w/b	¿Debris - Wood 2x4 moved to the corner need removing) few pieces	COMPLETED	1	Sweeping And Cleansing	Debris in hard shoulder	Permanent	09-Nov-2018	Priority 1
772003	11-Nov-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	STATION ROAD WEST CROYDON-cr02rb	Make safe light fitting plus restore power to other fittings.	CANCELLED	1	Road Lighting: Columns	Damaged	Permanent	12-Nov-2018	Priority 1
773306	21-Nov-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon Flyover westbound j/before exit the A232	POTHOLE	COMPLETED	1	Minor Carriageway Repairs	Pothole	Permanent	19-Dec-2018	Priority 1

DEFECT RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
773306	21-Nov-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon Flyover westbound j/before exit the A232	POTHOLE	COMPLETED	1	Minor Carriageway Repairs	Pothole	Temporary	22-Nov-2018	Priority 1
773499	22-Nov-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A316 Manor Circus RAB (Lower Richmond Road) jw Sandycombe Road - op BP Garage on island	semi lifted kerb	COMPLETED	1	Kerbs,Edging,P reformed Channels	Kerb/channel block alignment	Permanent	23-Nov-2018	Priority 1
773502	22-Nov-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon Flyover westbound adjacent to the off slip to the roundabout below.	POTHOLE	CANCELLED	1	Concrete Carriageway Repairs	Pothole	Permanent	23-Nov-2018	Priority 1
773503	22-Nov-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon Flyover westbound adjacent to the off slip to the roundabout below.	POTHOLE	INSTRUCTED	1	Minor Carriageway Repairs	Pothole	Permanent	20-Dec-2018	Priority 1
773503	22-Nov-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon Flyover westbound adjacent to the off slip to the roundabout below.	POTHOLE	INSTRUCTED	1	Minor Carriageway Repairs	Pothole	Temporary	23-Nov-2018	Priority 1
773573	22-Nov-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon flyover jn park lane	NULL	INSTRUCTED	1	Sweeping And Cleansing	Animal Carcass	Permanent	20-Dec-2018	Priority 1
773573	22-Nov-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon flyover jn park lane	NULL	INSTRUCTED	1	Sweeping And Cleansing	Animal Carcass	Temporary	23-Nov-2018	Priority 1

DEFECT RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
773849	27-Nov-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon Flyover westbound adjacent to the off slip to the roundabout below.	POTHOLE	COMPLETED	1	Minor Carriageway Repairs	Pothole	Permanent	28-Nov-2018	Priority 1
774142	28-Nov-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon Flyover eastbound	fibre Glass board on c/w	COMPLETED	1E	Sweeping And Cleansing	Debris in traffic lane	Permanent	26-Dec-2018	Priority 1 (ECO
774859	04-Dec-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 duppas terrace subway A232 duppas terra	graff 4D GRGE Graffiti General (XY:531879.8 164902.6) (Ref:LSO313369) LSO313369_December 005.jpg LSO313369_December 006.jpg	SELECTED	2M	TFL: Structures	Graffiti General	Permanent	01-Jan-2019	28 Day Defect
774857	04-Dec-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 davenant rd jn A232 davenant rd jn	2410MS req sma patch 3N TTRO POTH Pothole (XY:531864.8 164886.8) (Ref:LSO313368) LSO313368_December 003.jpg LSO313368_December 004.jpg	COMPLETED	1	Minor Carriageway Repairs	Pothole	Permanent	01-Jan-2019	Priority 1
774857	04-Dec-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 davenant rd jn A232 davenant rd jn	2410MS req sma patch 3N TTRO POTH Pothole (XY:531864.8 164886.8) (Ref:LSO313368) LSO313368_December 003.jpg LSO313368_December 004.jpg	COMPLETED	1	Minor Carriageway Repairs	Pothole	Temporary	05-Dec-2018	Priority 1
774855	04-Dec-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon flyover jn hillside rd wb A232	blocks req new 3n@ BKPF Block profile (XY:531813.8 164908.5) (Ref:LSO209778) LSO209778_DSCI0004.JPG LSO209778_DSCI0005.JPG	COMPLETED	2M	Minor Carriageway Repairs	Block profile	Permanent	01-Jan-2019	28 Day Defect
776667	19-Dec-2018	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon flyover, Lane 1, EB CW	¿Pothole	CANCELLED	1	Minor Carriageway Repairs	Pothole	Permanent	20-Dec-2018	Priority 1

DEFECT RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
778119	08-Jan-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon flyover jc duppas hill terrace	remove graffiti from subway 4D GROB Graffiti obscene/racist (XY:531878.6 164902.5) (Ref:LSO313526) LSO313526_DSCN8167.jpg LSO313526_DSCN8168.jpg	COMPLETED	1	TFL: Structures	Graffiti obscene/racist	Permanent	05-Feb-2019	Priority 1
778119	08-Jan-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon flyover jc duppas hill terrace	remove graffiti from subway 4D GROB Graffiti obscene/racist (XY:531878.6 164902.5) (Ref:LSO313526) LSO313526_DSCN8167.jpg LSO313526_DSCN8168.jpg	COMPLETED	1	TFL: Structures	Graffiti obscene/racist	Temporary	09-Jan-2019	Priority 1
778120	08-Jan-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon flyover jc duppas hill terrace	remove graffiti from subway 4D GRGE Graffiti General (XY:531880.9 164906.6) (Ref:LSO313537) LSO313537_DSCN8169.jpg LSO313537_DSCN8170.jpg	SELECTED	2M	TFL: Structures	Graffiti General	Permanent	05-Feb-2019	28 Day Defect
778965	14-Jan-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon Flyover Duppass Hill Subwa	¿Racist Graffiti in Subway	COMPLETED	1	Tunnel Portal	Graffiti - Racial	Permanent	15-Jan-2019	Priority 1
781253	31-Jan-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon flyover jc violet lane on slip	T3054 req sma line 4N @ POTH Pothole (XY:531895.2 164891.5) (Ref:LSO313677) LSO313677_DSCN8472.jpg LSO313677_DSCN8473.jpg	COMPLETED	1	Minor Carriageway Repairs	Pothole	Permanent	28-Feb-2019	Priority 1
781253	31-Jan-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon flyover jc violet lane on slip	T3054 req sma line 4N @ POTH Pothole (XY:531895.2 164891.5) (Ref:LSO313677) LSO313677_DSCN8472.jpg LSO313677_DSCN8473.jpg	COMPLETED	1	Minor Carriageway Repairs	Pothole	Temporary	01-Feb-2019	Priority 1
781573	04-Feb-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon flyover os friends house wb A23	kerbs req reset 4n CHAL Kerb/channel block alignment (XY:532538.3 165241) (Ref:LSO210055) LSO210055_DSCI0009.JPG LSO210055_DSCI0010.JPG	COMPLETED	2M	Kerbs,Edging,P reformed Channels	Kerb/channel block alignment	Permanent	04-Mar-2019	28 Day Defect

DEFECT RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
781768	05-Feb-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 the croydon flyover wb jct hillside rd	T3121 req rst kerbs 3n ? CHAL Kerb/channel block alignment (XY:531836.4 164888.6) (Ref:LSO408275) LSO408275_DSC07921.JPG LSO408275_DSC07923.JPG	COMPLETED	1	Kerbs,Edging,P reformed Channels	Kerb/channel block alignment	Permanent	05-Mar-2019	Priority 1
781768	05-Feb-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 the croydon flyover wb jct hillside rd	T3121 req rst kerbs 3n ? CHAL Kerb/channel block alignment (XY:531836.4 164888.6) (Ref:LSO408275) LSO408275_DSC07921.JPG LSO408275_DSC07923.JPG	COMPLETED	1	Kerbs,Edging,P reformed Channels	Kerb/channel block alignment	Temporary	06-Feb-2019	Priority 1
785266	28-Feb-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 the crordon flyover wb jct park lane	T3541 dislodged req rst kerbs 3n CHAL Kerb/channel block alignment (XY:532544.8 165240.6) (Ref:LSO408467) LSO408467_DSC08759.JPG LSO408467_DSC08760.JPG	COMPLETED	1	Kerbs,Edging,P reformed Channels	Kerb/channel block alignment	Permanent	28-Mar-2019	Priority 1
785266	28-Feb-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 the crordon flyover wb jct park lane	T3541 dislodged req rst kerbs 3n CHAL Kerb/channel block alignment (XY:532544.8 165240.6) (Ref:LSO408467) LSO408467_DSC08759.JPG LSO408467_DSC08760.JPG	COMPLETED	1	Kerbs,Edging,P reformed Channels	Kerb/channel block alignment	Temporary	01-Mar-2019	Priority 1
785834	05-Mar-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon flyover jn violet lane wb A232	T3630 kerbs req reset 3n@ CHAL Kerb/channel block alignment (XY:531834.7 164888.4) (Ref:LSO210182) LSO210182_DSC10008.JPG LSO210182_DSC10009.JPG	COMPLETED	1	Kerbs,Edging,P reformed Channels	Kerb/channel block alignment	Permanent	02-Apr-2019	Priority 1

DEFECT RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
785834	05-Mar-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon flyover jn violet lane wb A232	T3630 kerbs req reset 3n@ CHAL Kerb/channel block alignment (XY:531834.7 164888.4) (Ref:LSO210182) LSO210182_DSCI0008.JPG LSO210182_DSCI0009.JPG	COMPLETED	1	Kerbs,Edging,P reformed Channels	Kerb/channel block alignment	Temporary	06-Mar-2019	Priority 1
787276	14-Mar-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 the croydon flyover wb jct pump pail S	T3830 pothole req sma 4n NO PHOTOS BECK Blacktop : extensive cracking (XY:532322.9 165215.6) (Ref:LSO408556)	COMPLETED	1	Minor Carriageway Repairs	Blacktop : extensive cracking	Permanent	11-Apr-2019	Priority 1
787276	14-Mar-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 the croydon flyover wb jct pump pail S	T3830 pothole req sma 4n NO PHOTOS BECK Blacktop : extensive cracking (XY:532322.9 165215.6) (Ref:LSO408556)	COMPLETED	1	Minor Carriageway Repairs	Blacktop : extensive cracking	Temporary	15-Mar-2019	Priority 1
787277	14-Mar-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a23 croydon fly wb opp 21-23 sheldon st	T3831 pothole req sma 4n NO PHOTOS BECK Blacktop : extensive cracking (XY:532164.2 165116.3) (Ref:LSO408557)	COMPLETED	1	Minor Carriageway Repairs	Blacktop : extensive cracking	Permanent	11-Apr-2019	Priority 1
787277	14-Mar-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a23 croydon fly wb opp 21-23 sheldon st	T3831 pothole req sma 4n NO PHOTOS BECK Blacktop : extensive cracking (XY:532164.2 165116.3) (Ref:LSO408557)	COMPLETED	1	Minor Carriageway Repairs	Blacktop : extensive cracking	Temporary	15-Mar-2019	Priority 1
788832	27-Mar-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon Flyover NR JW Edridge Road	Debris	COMPLETED	1E	Sweeping And Cleansing	Debris in traffic lane	Permanent	24-Apr-2019	Priority 1 (ECO)
792635	25-Apr-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 the croydon flyover wb jct park lane	T4353 pothole on cover 3n CKIR Cracking around ironwork (XY:532552.9 165241.7) (Ref:LSO408901) LSO408901_DSC00570.JPG LSO408901_DSC00571.JPG	INSTRUCTED	1	Covers,Gratings,Frames,Boxes	Cracking around ironwork	Permanent	23-May-2019	Priority 1

DEFECT RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
792635	25-Apr-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 the croydon flyover wb jct park lane	T4353 pothole on cover 3n CKIR Cracking around ironwork (XY:532552.9 165241.7) (Ref:LSO408901) LSO408901_DSC00570.JPG LSO408901_DSC00571.JPG	INSTRUCTED	1	Covers,Gratings,Frames,Boxes	Cracking around ironwork	Temporary	26-Apr-2019	Priority 1
798270	06-Jun-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 the croydn flyover wb jct park lane	T4861 req rst kerbs 3n CHAL Kerb/channel block alignment (XY:532542 165241.3) (Ref:LSO409285) LSO409285_DSCI0502.JPG LSO409285_DSCI0503.JPG	COMPLETED	1	Kerbs,Edging,Performed Channels	Kerb/channel block alignment	Permanent	04-Jul-2019	Priority 1
798270	06-Jun-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 the croydn flyover wb jct park lane	T4861 req rst kerbs 3n CHAL Kerb/channel block alignment (XY:532542 165241.3) (Ref:LSO409285) LSO409285_DSCI0502.JPG LSO409285_DSCI0503.JPG	COMPLETED	1	Kerbs,Edging,Performed Channels	Kerb/channel block alignment	Temporary	07-Jun-2019	Priority 1
801793	02-Jul-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 the croydon flyover wb jct park lane	T5175 dislodged req rst kerbs 3n CHAL Kerb/channel block alignment (XY:532546.6 165240.5) (Ref:LSO409468) LSO409468_DSCI0570.JPG LSO409468_DSCI0571.JPG	COMPLETED	1	Kerbs,Edging,Performed Channels	Kerb/channel block alignment	Permanent	30-Jul-2019	Priority 1
801793	02-Jul-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 the croydon flyover wb jct park lane	T5175 dislodged req rst kerbs 3n CHAL Kerb/channel block alignment (XY:532546.6 165240.5) (Ref:LSO409468) LSO409468_DSCI0570.JPG LSO409468_DSCI0571.JPG	COMPLETED	1	Kerbs,Edging,Performed Channels	Kerb/channel block alignment	Temporary	03-Jul-2019	Priority 1
809808	29-Aug-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon flyover jc park lane wb eb A232	day burning lamps 4D LPON Lamp on during day (XY:532506.2 165247.6) (Ref:LSO314622) LSO314622_DSCN0706.jpg LSO314622_DSCN0707.jpg	COMPLETED	2L	Road Lighting: Lamp Failures	Day Burner 1	Permanent	26-Sep-2019	Low Priority De

DEFECT RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
809807	29-Aug-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon flyover jc park lane wb A232 cr	T5719 reset kerb 3N CHAL Kerb/channel block alignment (XY:532537.5 165241) (Ref:LSO314615) LSO314615_DSCN0704.jpg LSO314615_DSCN0705.jpg	COMPLETED	1	Kerbs,Edging,P reformed Channels	Kerb/channel block alignment	Permanent	26-Sep-2019	Priority 1
809807	29-Aug-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croydon flyover jc park lane wb A232 cr	T5719 reset kerb 3N CHAL Kerb/channel block alignment (XY:532537.5 165241) (Ref:LSO314615) LSO314615_DSCN0704.jpg LSO314615_DSCN0705.jpg	COMPLETED	1	Kerbs,Edging,P reformed Channels	Kerb/channel block alignment	Temporary	30-Aug-2019	Priority 1
812415	19-Sep-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 the croydon flyover wb jct park lane	T5935 req rst kerbs 3n CHAL Kerb/channel block alignment (XY:532548.6 165240.1) (Ref:LSO409760) LSO409760_DSCI0200.JPG LSO409760_DSCI0201.JPG	COMPLETED	1	Kerbs,Edging,P reformed Channels	Kerb/channel block alignment	Permanent	17-Oct-2019	Priority 1
812415	19-Sep-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 the croydon flyover wb jct park lane	T5935 req rst kerbs 3n CHAL Kerb/channel block alignment (XY:532548.6 165240.1) (Ref:LSO409760) LSO409760_DSCI0200.JPG LSO409760_DSCI0201.JPG	COMPLETED	1	Kerbs,Edging,P reformed Channels	Kerb/channel block alignment	Temporary	20-Sep-2019	Priority 1
813998	03-Oct-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croyd flyover wb jw 103 high st A232 cr	T6096ms req sma 4D@ POTH Pothole (XY:532356.1 165221.8) (Ref:LSO210902) LSO210902_DSCI1145.JPG LSO210902_DSCI1146.JPG	INSTRUCTED	1	Minor Carriageway Repairs	Pothole	Permanent	31-Oct-2019	Priority 1
813998	03-Oct-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 croyd flyover wb jw 103 high st A232 cr	T6096ms req sma 4D@ POTH Pothole (XY:532356.1 165221.8) (Ref:LSO210902) LSO210902_DSCI1145.JPG LSO210902_DSCI1146.JPG	INSTRUCTED	1	Minor Carriageway Repairs	Pothole	Temporary	04-Oct-2019	Priority 1

DEFECT RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
814921	10-Oct-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A23 croydonj flyover jn off slip pump pail	T6205MS 2x site req sma 4N ? BECK Blacktop : extensive cracking (XY:532335.4 165219.3) (Ref:LSO115890) LSO115890_DSCI217.jpg LSO115890_DSCI2176.jpg	INSTRUCTED	1	Minor Carriageway Repairs	Blacktop : extensive cracking	Permanent	07-Nov-2019	Priority 1
814921	10-Oct-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A23 croydonj flyover jn off slip pump pail	T6205MS 2x site req sma 4N ? BECK Blacktop : extensive cracking (XY:532335.4 165219.3) (Ref:LSO115890) LSO115890_DSCI217.jpg LSO115890_DSCI2176.jpg	INSTRUCTED	1	Minor Carriageway Repairs	Blacktop : extensive cracking	Temporary	11-Oct-2019	Priority 1
815059	11-Oct-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon flyover, Lane 1, WB	¿Pothole	COMPLETED	1	Minor Carriageway Repairs	Pothole	Permanent	12-Oct-2019	Priority 1
821358	21-Nov-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 CROYDON FLYOVER IN LINE WITH HIGH ST	POTHOLE	COMPLETED	1	Minor Carriageway Repairs	Pothole	Permanent	22-Nov-2019	Priority 1
821706	23-Nov-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 CROYDON FLYOVER BTWN EDRIDGE RD & PARK LANE	Pothole	COMPLETED	1A	Minor Carriageway Repairs	Pothole	Permanent	21-Dec-2019	EMG - 24hr Defe
821706	23-Nov-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 CROYDON FLYOVER BTWN EDRIDGE RD & PARK LANE	Pothole	COMPLETED	1A	Minor Carriageway Repairs	Pothole	Temporary	24-Nov-2019	EMG - 24hr Defe
821816	24-Nov-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon flyover Pump pail south	Pothole	COMPLETED	1A	Minor Carriageway Repairs	Pothole	Permanent	22-Dec-2019	EMG - 24hr Defe
821816	24-Nov-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon flyover Pump pail south	Pothole	COMPLETED	1A	Minor Carriageway Repairs	Pothole	Temporary	25-Nov-2019	EMG - 24hr Defe

DEFECT RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
821830	24-Nov-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon Flyover b4 off slip to Lower Coombe St	Pothole	COMPLETED	1A	Minor Carriageway Repairs	Pothole	Permanent	22-Dec-2019	EMG - 24hr Defe
822333	27-Nov-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	90 High St, Croydon CR0 1ND Croydon Flyover, just before the off slip, south bound	Pothole	COMPLETED	1A	Minor Carriageway Repairs	Pothole	Permanent	25-Dec-2019	EMG - 24hr Defe
822333	27-Nov-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	90 High St, Croydon CR0 1ND Croydon Flyover, just before the off slip, south bound	Pothole	COMPLETED	1A	Minor Carriageway Repairs	Pothole	Temporary	28-Nov-2019	EMG - 24hr Defe
823095	03-Dec-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 (west bound - opposite to innova, inspired homes), within 100m of getting onto the flyover the High Street, on the left hand lane	Make safe pothole	INSTRUCTED	1A	Minor Carriageway Repairs	Pothole	Permanent	31-Dec-2019	EMG - 24hr Defe
823095	03-Dec-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 (west bound - opposite to innova, inspired homes), within 100m of getting onto the flyover the High Street, on the left hand lane	Make safe pothole	INSTRUCTED	1A	Minor Carriageway Repairs	Pothole	Temporary	04-Dec-2019	EMG - 24hr Defe

DEFECT RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
823120	03-Dec-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 the croydon flyover wb jct hillside rd	damaged req new PGR 3d ACCD Accident damage (XY:531814 164895) (Ref:LSO410067) LSO410067_DSCI1113.JPG LSO410067_DSCI1114.JPG	COMPLETED	2M	Safety Fences: Metal/Concrete	Accident damage	Permanent	31-Dec-2019	28 Day Defect
823549	05-Dec-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon flyover jn pump pail south	NULL	INSTRUCTED	1	Concrete Carriageway Repairs	Other	Permanent	02-Jan-2020	Priority 1
823549	05-Dec-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon flyover jn pump pail south	NULL	INSTRUCTED	1	Concrete Carriageway Repairs	Other	Temporary	06-Dec-2019	Priority 1
824928	17-Dec-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon Flyover W/B B4 The second Off-Slip	Potholes	COMPLETED	1E	Minor Carriageway Repairs	Pothole	Permanent	14-Jan-2020	Priority 1 (ECO
825159	18-Dec-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon Flyover j/w Edridge Road (Croydon)	Sign Light	INSTRUCTED	1A	Road Lighting: Columns	Electrical condition	Permanent	15-Jan-2020	EMG - 24hr Defe
825159	18-Dec-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon Flyover j/w Edridge Road (Croydon)	Sign Light	INSTRUCTED	1A	Road Lighting: Columns	Electrical condition	Temporary	19-Dec-2019	EMG - 24hr Defe
825160	18-Dec-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon Flyover j/w Edridge Road	KLB	COMPLETED	1A	Safety Bollards: Face/Structure/ Fixings	Damaged/deformed	Permanent	15-Jan-2020	EMG - 24hr Defe
825160	18-Dec-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon Flyover j/w Edridge Road	KLB	COMPLETED	1A	Safety Bollards: Face/Structure/ Fixings	Damaged/deformed	Temporary	19-Dec-2019	EMG - 24hr Defe
825291	19-Dec-2019	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon flyover, lane 1 , EB, Just before Pump Pail South Off Slip	Pothole	COMPLETED	1	Minor Carriageway Repairs	Other	Permanent	20-Dec-2019	Priority 1

DEFECT RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
826976	07-Jan-2020	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	(CRO) A232 davenant rd sb cw jn hillside rd A232 d	TTRO req sma lines 3N BECK Blacktop : extensive cracking (XY:531854.1 164888.5) (Ref:LSO116473) LSO116473_DSCN0027.jpg LSO116473_DSCN0028.jpg	INSTRUCTED	2M	Minor Carriageway Repairs	Blacktop : extensive cracking	Permanent	04-Feb-2020	28 Day Defect
828783	16-Jan-2020	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon flyover. CR0 1AQ	¿REMOVE DAMAGED TREE BRANCH	COMPLETED	1	Footways And Cycle Tracks	Other	Permanent	17-Jan-2020	Priority 1
828796	16-Jan-2020	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 the croydon flyover wb o/s 103 high st	T7940 2x potholes req sma 4n No Photos BECK Blacktop : extensive cracking (XY:532366.5 165223.6) (Ref:LSO410248)	COMPLETED	1	Minor Carriageway Repairs	Blacktop : extensive cracking	Permanent	13-Feb-2020	Priority 1
828796	16-Jan-2020	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 the croydon flyover wb o/s 103 high st	T7940 2x potholes req sma 4n No Photos BECK Blacktop : extensive cracking (XY:532366.5 165223.6) (Ref:LSO410248)	COMPLETED	1	Minor Carriageway Repairs	Blacktop : extensive cracking	Temporary	17-Jan-2020	Priority 1
828797	16-Jan-2020	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 croydon flyover wb jct pump pail S	T7941 2x potholes req sma 4n No Photos POTH Pothole (XY:532290.1 165209.3) (Ref:LSO410249)	COMPLETED	1	Minor Carriageway Repairs	Pothole	Permanent	13-Feb-2020	Priority 1
828797	16-Jan-2020	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 croydon flyover wb jct pump pail S	T7941 2x potholes req sma 4n No Photos POTH Pothole (XY:532290.1 165209.3) (Ref:LSO410249)	COMPLETED	1	Minor Carriageway Repairs	Pothole	Temporary	17-Jan-2020	Priority 1
828811	16-Jan-2020	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon flyover s/b b4 The Slip	¿Potholes	INSTRUCTED	1	Concrete Carriageway Repairs	Pothole	Permanent	13-Feb-2020	Priority 1
828811	16-Jan-2020	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	A232 Croydon flyover s/b b4 The Slip	¿Potholes	INSTRUCTED	1	Concrete Carriageway Repairs	Pothole	Temporary	17-Jan-2020	Priority 1

DEFECT RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Defect Id	Date Inspected	Road Name	Location	Description	Status	Priority Code	Activity Type	Defect Type	Action Type	Due Date	Priority
829935	23-Jan-2020	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 the croydon flyover wb jct edridge road	T8083 missing req new LP sign KLB 4n ACCD Accident damage (XY:532464.9 165233.5) (Ref:LSO410277) LSO410277_DSCI0351.JPG LSO410277_DSCI0352.JPG	INSTRUCTED	1	Road Lighting: Electrical	Other	Permanent	20-Feb-2020	Priority 1
829935	23-Jan-2020	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	a232 the croydon flyover wb jct edridge road	T8083 missing req new LP sign KLB 4n ACCD Accident damage (XY:532464.9 165233.5) (Ref:LSO410277) LSO410277_DSCI0351.JPG LSO410277_DSCI0352.JPG	INSTRUCTED	1	Road Lighting: Electrical	Other	Temporary	24-Jan-2020	Priority 1

PUBLIC ENQUIRY RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Incident/Recorded Date	Pem Id	Location	Description	Hsc Status Name	Pem Category	Pem Class	Pem Type	Priority	Corr Recv Date	Target Date	Complete Date
16-Mar-18	2632913	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Claimant alleges they collided with a pothole resulting in vehicle damage.	Complete	Claim	Jackson Legislation	Legal Liability	20	03-APR-2018 00:00:00	05-APR-2018 18:30:00	24-APR-2018 14:43:13
29-Mar-18	2621290	A232 The Croydon flyover wb jct pump pail south	Make safe c/w Potholes	Received	Inspection Response	Carriageway	Pothole	3	NULL	03-APR-2018 13:33:02	NULL
10-Apr-18	2632921	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Claimant alleges they collided with a pothole resulting in vehicle damage.	Complete	Claim	Jackson Legislation	Legal Liability	20	18-APR-2018 00:00:00	30-APR-2018 00:00:00	24-APR-2018 16:16:17
10-Apr-18	2679934	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Claimant alleges they collided with a pothole resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	04-JUL-2018 00:00:00	30-APR-2018 00:00:00	02-AUG-2018 14:00:11
10-Apr-18	2684893	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Claimant alleges they collided with a pothole resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	30-JUL-2018 00:00:00	30-APR-2018 00:00:00	20-AUG-2018 15:42:46
10-Apr-18	2700948	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Claimant alleges they collidede with a pothole resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	31-AUG-2018 00:00:00	30-APR-2018 00:00:00	13-SEP-2018 15:26:15

PUBLIC ENQUIRY RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Incident/Recorded Date	Pem Id	Location	Description	Hsc Status Name	Pem Category	Pem Class	Pem Type	Priority	Corr Recv Date	Target Date	Complete Date
10-Apr-18	2645358	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Claimant alleges they collided with a pothole resulting in vehicle damage.	Complete	Claim	Jackson Legislation	Legal Liability	20	10-MAY-2018 00:00:00	30-APR-2018 11:30:00	02-AUG-2018 14:20:22
11-Apr-18	2679360	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Claimant alleges they collided with a pothole resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	05-JUN-2018 00:00:00	01-MAY-2018 00:00:00	02-AUG-2018 14:08:55
12-Apr-18	2628828	A232 the croydon flyover wb jct hillside road (end of flyover jct duppas hill)	Make safe dislodged Kerb	Received	Inspection Response	Footway	Kerbs	3	NULL	13-APR-2018 10:34:25	NULL
31-May-18	2722274	A232,THE CROYDON FLYOVER,E/B, (EB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Claimant alleges they parked under the Flyover when debris fell on their car resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	24-SEP-2018 00:00:00	20-JUN-2018 00:00:00	29-OCT-2018 15:46:00
11-Oct-18	2725769	A232 the croydon flyover os unitarian church wb	¿animal carcass	Received	Inspection Response	Carriageway	Dead Animal	3	NULL	12-OCT-2018 13:38:00	NULL
11-Nov-18	2771689	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH),CR0	Claimant alleges they collided with a pothole resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	28-DEC-2018 00:00:00	01-DEC-2018 00:00:00	22-JAN-2020 11:31:49

PUBLIC ENQUIRY RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Incident/Recorded Date	Pem Id	Location	Description	Hsc Status Name	Pem Category	Pem Class	Pem Type	Priority	Corr Recv Date	Target Date	Complete Date
12-Nov-18	2757769	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CR0	Claimant alleges they collided with a pothole resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	06-DEC-2018 00:00:00	02-DEC-2018 00:00:00	17-DEC-2018 15:11:38
12-Nov-18	2761981	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CR0	Claimant alleges they collided with a pothole resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	12-DEC-2018 00:00:00	02-DEC-2018 00:00:00	22-JAN-2020 11:36:15
12-Nov-18	2764593	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CR0	Claimant alleges they collided with a pothole resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	20-DEC-2018 00:00:00	02-DEC-2018 00:00:00	22-JAN-2020 11:36:29
12-Nov-18	2771143	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CR0	Claimant alleges they collided with a pothole resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	08-JAN-2019 00:00:00	02-DEC-2018 00:00:00	11-JAN-2019 08:30:52
12-Nov-18	2774340	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CR0	Claimant alleges they collided with a pothole resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	15-JAN-2019 00:00:00	02-DEC-2018 00:00:00	16-JAN-2019 14:27:07
12-Nov-18	2774627	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CR0	Claimant alleges they collided with a pothole resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	15-JAN-2019 00:00:00	02-DEC-2018 00:00:00	17-JAN-2019 09:43:42

PUBLIC ENQUIRY RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Incident/Recorded Date	Pem Id	Location	Description	Hsc Status Name	Pem Category	Pem Class	Pem Type	Priority	Corr Recv Date	Target Date	Complete Date
12-Nov-18	2777829	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CRO	Claimant alleges they collided with a pothole resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	16-JAN-2019 00:00:00	02-DEC-2018 00:00:00	23-JAN-2019 12:16:26
12-Nov-18	2782505	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CRO	Claimant alleges they collided with a pothole resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	26-JAN-2019 00:00:00	02-DEC-2018 00:00:00	31-JAN-2019 10:47:29
12-Nov-18	2787366	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CRO	Claimant alleges they collided with a pothole resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	08-FEB-2019 00:00:00	02-DEC-2018 00:00:00	08-FEB-2019 12:25:07
12-Nov-18	2790918	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CRO	Claimant alleges they collided with a pothole resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	12-FEB-2019 00:00:00	02-DEC-2018 00:00:00	15-FEB-2019 11:46:28
12-Nov-18	2807605	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CRO	claimant alleges they collided with a pothole resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	11-MAR-2019 00:00:00	02-DEC-2018 00:00:00	13-MAR-2019 13:21:48
12-Nov-18	3015393	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CRO	Claimant alleges they collided with a pothole resulting in vehicle	Received	Claim	Jackson Legislation	Legal Liability	20	31-DEC-2019 00:00:00	02-DEC-2018 00:00:00	NULL

PUBLIC ENQUIRY RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Incident/Recorded Date	Pem Id	Location	Description	Hsc Status Name	Pem Category	Pem Class	Pem Type	Priority	Corr Recv Date	Target Date	Complete Date
05-Feb-19	2785075	A232 the croydon flyover wb jct hillside road	¿Kerb Damaged	Received	Inspection Response	Footway	Kerbs	3	NULL	06-FEB-2019 14:03:11	NULL
28-Feb-19	2799893	A232 the Croydon flyover wb jct Park lane (o/s friends meeting house)	¿dislodged kerbs - make safe	Received	Inspection Response	Carriageway	Kerbs	3	NULL	01-MAR-2019 11:44:35	NULL
28-Feb-19	2799901	A232 park lane roundabout jct the croydon flyover (o/s taberner house)	sunken/rocking cover	Complete	Inspection Response	Carriageway	Section 81 Defect	3	NULL	01-MAR-2019 11:51:53	01-MAR-2019 08:36:20
14-Mar-19	2809001	a232 the croydon flyover wb jct pump pail south	¿PH on CW - make safe req'd	Received	Inspection Response	Carriageway	Pothole	3	NULL	15-MAR-2019 12:03:14	NULL
14-Mar-19	2809002	A232 the croydon flyover wb level with 21-23 sheldon street	¿Pothole	Received	Inspection Response	Carriageway	Pothole	3	NULL	15-MAR-2019 12:15:07	NULL
25-Apr-19	2835237	a232 the croydon flyover wb jct park lane (o/s the friends meeting house)	¿PH - make safe	Received	Inspection Response	Carriageway	Pothole	3	NULL	26-APR-2019 12:54:27	NULL
06-Jun-19	2861213	a232 the croydon flyover wb jct park lane (o/s the friends meeting house)	¿dislodged kerbs	Received	Inspection Response	Carriageway	Kerbs	3	NULL	07-JUN-2019 12:46:29	NULL

PUBLIC ENQUIRY RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Incident/Recorded Date	Pem Id	Location	Description	Hsc Status Name	Pem Category	Pem Class	Pem Type	Priority	Corr Recv Date	Target Date	Complete Date
02-Jul-19	2876942	A232 the croydon flyover wb jct park lane (o/s friends meeting house)	dislodged kerbs	Received	Inspection Response	Carriageway	Pothole	3	NULL	03-JUL-2019 13:06:25	NULL
02-Jul-19	2876943	A232 the croydon flyover eb jct park lane (o/s tabener house) CAT1 24hr amber check	2150 2210 1 bag m90 Perm fix No further action required NFA	Received	Inspection Response	Carriageway	Pothole	3	NULL	03-JUL-2019 13:08:44	NULL
07-Aug-19	2899902	A232 The Croydon Flyover/Duppas Hill road/Davenant road J/w Violet lane.	¿Missing bollard make safe	Complete	Inspection Response	Street Furniture	Safety Bollard	3	NULL	08-AUG-2019 12:19:50	11-SEP-2019 14:36:15
19-Sep-19	2930182	A232 the croydon flyover wb jct park lane	¿Dislodged kerbs.	Received	Inspection Response	Footway	Kerbs	3	NULL	20-SEP-2019 11:35:00	NULL
03-Oct-19	2965207	A232,THE CROYDON FLYOVER,E/B,(WB START CROY F-OVER TO JCT PUMP PAIL STH) CRO	Claimant alleges they collided with a pothole resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	05-NOV-2019 00:00:00	23-OCT-2019 00:00:00	22-JAN-2020 11:59:25

PUBLIC ENQUIRY RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Incident/Recorded Date	Pem Id	Location	Description	Hsc Status Name	Pem Category	Pem Class	Pem Type	Priority	Corr Recv Date	Target Date	Complete Date
17-Oct-19	2984060	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CR0	Claimant alleges they collided with pothole resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	27-NOV-2019 00:00:00	06-NOV-2019 00:00:00	23-DEC-2019 08:50:02
17-Oct-19	2956251	A232 the croydon flyover wb jct pump pail south	¿Pothole	Received	Inspection Response	Carriageway	Pothole	3	NULL	18-OCT-2019 11:36:00	NULL
18-Oct-19	2969720	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CR0	claimant alleges they collided with a pothole resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	11-NOV-2019 00:00:00	07-NOV-2019 00:00:00	19-DEC-2019 13:56:19
18-Oct-19	3002973	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CR0	Claimant alleges they collided with a pothole resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	18-DEC-2019 00:00:00	07-NOV-2019 00:00:00	23-DEC-2019 10:46:50
19-Oct-19	3015503	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CR0	Claimant alleges they collided with a pothole resulting in vehicle damage	Received	Claim	Jackson Legislation	Legal Liability	20	08-JAN-2020 00:00:00	08-NOV-2019 00:00:00	NULL
19-Oct-19	3027104	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CR0	Claimant alleges they collided with a pothole resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	22-JAN-2020 00:00:00	08-NOV-2019 00:00:00	18-FEB-2020 12:53:37

PUBLIC ENQUIRY RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Incident/Recorded Date	Pem Id	Location	Description	Hsc Status Name	Pem Category	Pem Class	Pem Type	Priority	Corr Recv Date	Target Date	Complete Date
19-Oct-19	3039902	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CRO	Claimant alleges they collided with a pothole resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	30-JAN-2020 00:00:00	08-NOV-2019 00:00:00	18-FEB-2020 13:19:29
18-Nov-19	3015280	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CRO	Claimant alleges they collided with a pothole resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	16-DEC-2019 00:00:00	08-DEC-2019 00:00:00	22-JAN-2020 09:00:55
20-Nov-19	2988625	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CRO	Claimant alleges they collided with a pothole resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	02-DEC-2019 00:00:00	10-DEC-2019 00:00:00	08-JAN-2020 15:44:15
20-Nov-19	2992560	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CRO	Claimant alleges they collided with a pothole resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	09-DEC-2019 00:00:00	10-DEC-2019 00:00:00	08-JAN-2020 15:46:40
20-Nov-19	3027908	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CRO	Claimant alleges they collided with a pothole resulting in vehicle damage	Received	Claim	Jackson Legislation	Legal Liability	20	27-JAN-2020 00:00:00	10-DEC-2019 00:00:00	NULL
21-Nov-19	2978860	A232 the croydon flyover wb jct park lane (o/s friends meeting house)	¿rocking cover	Received	Inspection Response	Carriageway	Section 81 Defect	3	NULL	22-NOV-2019 13:18:28	NULL

PUBLIC ENQUIRY RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Incident/Recorded Date	Pem Id	Location	Description	Hsc Status Name	Pem Category	Pem Class	Pem Type	Priority	Corr Recv Date	Target Date	Complete Date
14-Dec-19	3043028	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CR0	Claimant alleges they collided with a pothole resulting in vehicle damage	Received	Claim	Jackson Legislation	Legal Liability	20	11-FEB-2020 00:00:00	03-JAN-2020 00:00:00	NULL
16-Dec-19	3015358	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CR0	Claimant alleges they collided with a pothole resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	23-DEC-2019 00:00:00	05-JAN-2020 00:00:00	22-JAN-2020 09:00:19
16-Dec-19	3027064	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CR0	Claimant alleges they collided with a pothole resulting in vehicle damage	Complete	Claim	Jackson Legislation	Legal Liability	20	21-JAN-2020 00:00:00	05-JAN-2020 00:00:00	10-FEB-2020 09:50:31
16-Dec-19	3042644	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CR0	Claimant alleges they collided with a pothole resulting in vehicle damage	Received	Claim	Jackson Legislation	Legal Liability	20	07-FEB-2020 00:00:00	05-JAN-2020 00:00:00	NULL
16-Dec-19	3043147	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CR0	Claimant alleges they collided with a pothole resulting in vehicle damage	Received	Claim	Jackson Legislation	Legal Liability	20	11-FEB-2020 00:00:00	05-JAN-2020 00:00:00	NULL
15-Jan-20	3039955	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CR0	Claimant alleges they collided with a pothole resulting in vehicle damage	Received	Claim	Jackson Legislation	Legal Liability	20	30-JAN-2020 00:00:00	04-FEB-2020 00:00:00	NULL

PUBLIC ENQUIRY RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Incident/Recorded Date	Pem Id	Location	Description	Hsc Status Name	Pem Category	Pem Class	Pem Type	Priority	Corr Recv Date	Target Date	Complete Date
16-Jan-20	3040039	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CRO	Claimant alleges they collided with a pothole resulting in vehicle damage	Received	Claim	Jackson Legislation	Legal Liability	20	03-FEB-2020 00:00:00	05-FEB-2020 00:00:00	NULL
16-Jan-20	3040266	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CRO	Claimant alleges they collided with a pothole resulting in vehicle damage	Received	Claim	Jackson Legislation	Legal Liability	20	05-FEB-2020 00:00:00	05-FEB-2020 00:00:00	NULL
16-Jan-20	3050683	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CRO	claimant alleges they collided with a pothole resulting in vehicle damage	Received	Claim	Jackson Legislation	Legal Liability	20	19-FEB-2020 00:00:00	05-FEB-2020 00:00:00	NULL
16-Jan-20	3050943	A232,THE CROYDON FLYOVER,E/B, (WB START CROY F-OVER TO JCT PUMP PAIL STH) CRO	Claimant alleges they collided with a pothole resulting in vehicle damage	Received	Claim	Jackson Legislation	Legal Liability	20	20-FEB-2020 00:00:00	05-FEB-2020 00:00:00	NULL
16-Jan-20	3017943	a232 the croydon flyover wb o/s 103 high street (50m before jct pump pail south)	¿potholes	Received	Inspection Response	Carriageway	Pothole	3	NULL	17-JAN-2020 14:31:55	NULL
16-Jan-20	3017957	a232 the croydon flyover wb jct pump pail south	¿2x pothole	Received	Inspection Response	Carriageway	Pothole	3	NULL	17-JAN-2020 14:40:15	NULL
23-Jan-20	3024342	A212 Park lane nb jct the croydon flyover	¿Potholes x 2	Received	Inspection Response	Carriageway	Pothole	3	NULL	24-JAN-2020 12:43:01	NULL

PUBLIC ENQUIRY RECORDS - THE CROYDON FLYOVER - 25/02/2018 TO 25/02/2020

Incident/Recorded Date	Pem Id	Location	Description	Hsc Status Name	Pem Category	Pem Class	Pem Type	Priority	Corr Recv Date	Target Date	Complete Date
23-Jan-20	3024363	A232 the croydon flyover wb jct edridge road	¿missing klb shell/damaged missing LP	Received	Inspection Response	Street Furniture	Bollard	3	NULL	24-JAN-2020 12:50:22	NULL