

Full Details Report Summary - A20 Sidcup Bypass Road

Accidents Found Date Range: 04/11/2020 - 30/07/2022

Grid Coordinate Range: 548030,169956-549501,170066

Accident Severity

	2020	2021	2022	Total
Serious	0	1	0	1
Slight	2	1	3	6
Total	2	2	3	7

Casualty Severity

	2020	2021	2022	Total
Serious	0	1	0	1
Slight	2	5	3	10
Total	2	6	3	11

Casualty KSI

	2020	2021	2022	Total
Adult KSI	0	1	0	1
Slight	2	5	3	10
Total	2	6	3	11

1.3 Accident Slight On A20, 800 Metres East Of The Junction With Sidcup Bypass. Accident 2 of 7
 Reference:200283206
 1.7 Date & 1.9 Time.....Monday 07/12/2020 09:15
 1.11 Grid co-ordinates.....548483/169997
 1.10 Local Authority.....Bromley
 1.12/1.13 1st road identity..A20
 1.18/1.19 2nd road identity..U
 1.22 Weather.....Fog Mist
 1.21 Light conditions.....Daylight
 1.20a Crossing(human).....No Human control within
 1.20b Crossing(physical).....No crossing facility wit
 1.15 Speed limit.....70 Mph
 1.14 Road type.....Dual c'way
 1.16 Junction detail.....Not at or within 20m of junct
 1.17 Junction control.....
 1.24 Special conditions...None
 1.25 Carriageway hazards..None
 1.5 Number of vehicles...2
 1.6 Number of casualties.1
 1.23 Surface.....Wet

Did a police officer attend?
Yes

Accident Description
Not Known How Collision Occurred

2 Vehicles

2.4 Veh ref no.....1
 2.17 Other vehicle.....0
 2.5 Vehicle class.....Car
 2.10 Junction location...Not at junction
 2.9 Restricted location.On main carriageway
 2.8 Movement from/to....West East
 2.7 Manoeuvres.....Stopping
 2.11 Skidding.....No
 2.13 Left c'way.....Did not leave c'way
 2.6 Towing.....No
 2.28 Foreign vehicle.....Not foreign
 2.16 First impact.....Did not impact
 2.12 Hit object in c'way..None
 2.14 Hit object off c'way.None
 2.18 Parts damaged..... / /
 2.21 Driver gender.....Male
 2.22 Driver age.....54
 2.24 Hit and Run.....No
 2.23 Breath test.....Not requested
 2.29 Journey purpose.....Commuting to/from work

2.4 Veh ref no.....2
 2.17 Other vehicle.....0
 2.5 Vehicle class.....Car
 2.10 Junction location...Not at junction
 2.9 Restricted location.On main carriageway
 2.8 Movement from/to....West East
 2.7 Manoeuvres.....Going ahead other
 2.11 Skidding.....No
 2.13 Left c'way.....Did not leave c'way
 2.6 Towing.....No
 2.28 Foreign vehicle.....Not foreign
 2.16 First impact.....Front
 2.12 Hit object in c'way..None
 2.14 Hit object off c'way.None
 2.18 Parts damaged..... / /
 2.21 Driver gender.....Male
 2.22 Driver age.....43
 2.24 Hit and Run.....No
 2.23 Breath test.....Not requested
 2.29 Journey purpose.....Commuting to/from work

1 Casualty

3.5 Cas ref no.....1
 3.6 Casualty class.....Driver or Rider
 3.7 Gender.....Male
 3.8 Age.....54
 3.9 Severity.....Slight
 3.4 Vehicle no.....1
 3.12 Ped Direction.....Not a pedestrian
 3.15 Car passenger.....No
 3.16 PSV passenger.....No
 3.14 Seat belt usage.....Not worn
 3.13 School pupil.....Other
 (3.19 School)
 3.10 Pedestrian location..Not a pedestrian
 3.11 Pedestrian movement..Not a pedestrian
 3.19 Roadworker injured...No

A20 Sidcup Bypass Road

1.3 Accident Slight On A20, 800 Metres East Of The Junction With Severnoaks Way. Accident 3 of 7
 Reference:210340574
 1.7 Date & 1.9 Time.....Saturday 30/10/2021 09:2
 1.11 Grid co-ordinates.....548030/170066
 1.10 Local Authority.....Bromley
 1.12/1.13 1st road identity..A20
 1.18/1.19 2nd road identity..U
 1.22 Weather.....Rain
 1.21 Light conditions.....Daylight
 1.20a Crossing(human).....No Human control within
 1.20b Crossing(physical).....No crossing facility wit
 1.15 Speed limit.....70 Mph
 1.14 Road type.....Dual c'way
 1.16 Junction detail.....Not at or within 20m of junct
 1.17 Junction control.....
 1.24 Special conditions...None
 1.25 Carriageway hazards..None
 1.5 Number of vehicles...1
 1.6 Number of casualties.2
 1.23 Surface.....Wet

Did a police officer attend?
Yes

Accident Description
Not Known How Collision Occurred

1 Vehicle

2.4 Veh ref no.....1
 2.17 Other vehicle.....0
 2.5 Vehicle class.....Car
 2.10 Junction location...Not at junction
 2.9 Restricted location.On main carriageway
 2.8 Movement from/to....East West
 2.7 Manoeuvres.....Going ahead other
 2.11 Skidding.....No
 2.13 Left c'way.....Left c'way near-side
 2.6 Towing.....No
 2.28 Foreign vehicle.....Not foreign
 2.16 First impact.....Front
 2.12 Hit object in c'way..None
 2.14 Hit object off c'way.Nearside/offside crash
 2.18 Parts damaged..... / /
 2.21 Driver gender.....Female
 2.22 Driver age.....21
 2.24 Hit and Run.....No
 2.23 Breath test.....Negative
 2.29 Journey purpose.....Other

2 Casualties

3.5 Cas ref no.....1
 3.6 Casualty class.....Driver or Rider
 3.7 Gender.....Female
 3.8 Age.....21
 3.9 Severity.....Slight
 3.4 Vehicle no.....1
 3.12 Ped Direction.....Not a pedestrian
 3.15 Car passenger.....No
 3.16 PSV passenger.....No
 3.14 Seat belt usage.....Not worn
 3.13 School pupil.....Other
 (3.19 School)
 3.10 Pedestrian location..Not a pedestrian
 3.11 Pedestrian movement..Not a pedestrian
 3.19 Roadworker injured...No

3.5 Cas ref no.....2
 3.6 Casualty class.....Passenger
 3.7 Gender.....Male
 3.8 Age.....21
 3.9 Severity.....Slight
 3.4 Vehicle no.....1
 3.12 Ped Direction.....Not a pedestrian
 3.15 Car passenger.....Front
 3.16 PSV passenger.....No
 3.14 Seat belt usage.....Not worn
 3.13 School pupil.....Other
 (3.19 School)
 3.10 Pedestrian location..Not a pedestrian
 3.11 Pedestrian movement..Not a pedestrian
 3.19 Roadworker injured...No

1.3 Accident Serious On A20, 1900 Metres East Of The Junction With Accident 4 of 7

Reference:210346647
 1.7 Date & 1.9 Time.....Saturday 27/11/2021 18:20 Crittalls Corner.
 1.11 Grid co-ordinates.....549033/169996
 1.10 Local Authority.....Bromley
 1.12/1.13 1st road identity..A20
 1.18/1.19 2nd road identity..U
 1.22 Weather.....Rain Wind
 1.21 Light conditions.....Dark/no lights
 1.20a Crossing(human).....No Human control within
 1.20b Crossing(physical).....No crossing facility wit
 1.15 Speed limit.....70 Mph
 1.14 Road type.....Dual c'way
 1.16 Junction detail.....Not at or within 20m of junct
 1.17 Junction control.....
 1.24 Special conditions...None
 1.25 Carriageway hazards..None
 1.5 Number of vehicles...5
 1.6 Number of casualties.4
 1.23 Surface.....Wet

Did a police officer attend?
 Yes

Accident Description
 Not Known How Collision Occurred

5 Vehicles

2.4 Veh ref no.....1
 2.17 Other vehicle.....0
 2.5 Vehicle class.....Car
 2.10 Junction location...Not at junction
 2.9 Restricted location.On main carriageway
 2.8 Movement from/to....East West
 2.7 Manoeuvres.....Going ahead other
 2.11 Skidding.....Yes
 2.13 Left c'way.....Did not leave c'way
 2.6 Towing.....No
 2.28 Foreign vehicle.....Not foreign
 2.16 First impact.....Offside
 2.12 Hit object in c'way..None
 2.14 Hit object off c'way.None
 2.18 Parts damaged..... / /
 2.21 Driver gender.....Female
 2.22 Driver age.....41
 2.24 Hit and Run.....No
 2.23 Breath test.....Not requested
 2.29 Journey purpose.....Other

2.4 Veh ref no.....2
 2.17 Other vehicle.....0
 2.5 Vehicle class.....Car
 2.10 Junction location...Not at junction
 2.9 Restricted location.On main carriageway
 2.8 Movement from/to....East West
 2.7 Manoeuvres.....Going ahead other
 2.11 Skidding.....Yes
 2.13 Left c'way.....Did not leave c'way
 2.6 Towing.....No
 2.28 Foreign vehicle.....Not foreign
 2.16 First impact.....Front
 2.12 Hit object in c'way..None
 2.14 Hit object off c'way.None
 2.18 Parts damaged..... / /
 2.21 Driver gender.....Male
 2.22 Driver age.....35
 2.24 Hit and Run.....No
 2.23 Breath test.....Not requested
 2.29 Journey purpose.....Other

2.4 Veh ref no.....3
 2.17 Other vehicle.....0
 2.5 Vehicle class.....Car
 2.10 Junction location...Not at junction
 2.9 Restricted location.On main carriageway
 2.8 Movement from/to....East West
 2.7 Manoeuvres.....Going ahead other
 2.11 Skidding.....Yes
 2.13 Left c'way.....Did not leave c'way
 2.6 Towing.....No
 2.28 Foreign vehicle.....Not foreign
 2.16 First impact.....Back
 2.12 Hit object in c'way..None
 2.14 Hit object off c'way.None
 2.18 Parts damaged..... / /
 2.21 Driver gender.....Male
 2.22 Driver age.....31
 2.24 Hit and Run.....No
 2.23 Breath test.....Not requested
 2.29 Journey purpose.....Other

2.4 Veh ref no.....4
 2.17 Other vehicle.....0
 2.5 Vehicle class.....Car
 2.10 Junction location...Not at junction
 2.9 Restricted location.On main carriageway
 2.8 Movement from/to....East West
 2.7 Manoeuvres.....Going ahead other
 2.11 Skidding.....Yes
 2.13 Left c'way.....Did not leave c'way
 2.6 Towing.....No
 2.28 Foreign vehicle.....Not foreign
 2.16 First impact.....Front
 2.12 Hit object in c'way..None
 2.14 Hit object off c'way.None
 2.18 Parts damaged..... / /
 2.21 Driver gender.....Female
 2.22 Driver age.....20
 2.24 Hit and Run.....No
 2.23 Breath test.....Not requested
 2.29 Journey purpose.....Other

2.4 Veh ref no.....5
 2.17 Other vehicle.....0
 2.5 Vehicle class.....Car
 2.10 Junction location...Not at junction
 2.9 Restricted location.On main carriageway
 2.8 Movement from/to....East West
 2.7 Manoeuvres.....Going ahead other
 2.11 Skidding.....No
 2.13 Left c'way.....Did not leave c'way
 2.6 Towing.....No
 2.28 Foreign vehicle.....Not foreign
 2.16 First impact.....Offside
 2.12 Hit object in c'way..None
 2.14 Hit object off c'way.None
 2.18 Parts damaged..... / /
 2.21 Driver gender.....Male
 2.22 Driver age.....39
 2.24 Hit and Run.....No
 2.23 Breath test.....Not requested
 2.29 Journey purpose.....Other

4 Casualties

3.5 Cas ref no.....1	3.15 Car passenger.....Front
3.6 Casualty class.....Passenger	3.16 PSV passenger.....No
3.7 Gender.....Male	3.14 Seat belt usage.....Not worn
3.8 Age.....9	3.13 School pupil.....Other (3.19 School
3.9 Severity.....Slight	3.10 Pedestrian location..Not a pedestrian
3.4 Vehicle no.....1	3.11 Pedestrian movement..Not a pedestrian
3.12 Ped Direction.....Not a pedestrian	3.19 Roadworker injured...No
3.5 Cas ref no.....2	3.15 Car passenger.....Rear
3.6 Casualty class.....Passenger	3.16 PSV passenger.....No
3.7 Gender.....Male	3.14 Seat belt usage.....Not worn
3.8 Age.....17	3.13 School pupil.....Other (3.19 School
3.9 Severity.....Slight	3.10 Pedestrian location..Not a pedestrian
3.4 Vehicle no.....1	3.11 Pedestrian movement..Not a pedestrian
3.12 Ped Direction.....Not a pedestrian	3.19 Roadworker injured...No
3.5 Cas ref no.....3	3.15 Car passenger.....No
3.6 Casualty class.....Driver or Rider	3.16 PSV passenger.....No
3.7 Gender.....Male	3.14 Seat belt usage.....Not worn
3.8 Age.....35	3.13 School pupil.....Other (3.19 School
3.9 Severity.....Slight	3.10 Pedestrian location..Not a pedestrian
3.4 Vehicle no.....2	3.11 Pedestrian movement..Not a pedestrian
3.12 Ped Direction.....Not a pedestrian	3.19 Roadworker injured...No
3.5 Cas ref no.....4	3.15 Car passenger.....Front
3.6 Casualty class.....Passenger	3.16 PSV passenger.....No
3.7 Gender.....Female	3.14 Seat belt usage.....Not worn
3.8 Age.....58	3.13 School pupil.....Other (3.19 School
3.9 Severity.....Serious	3.10 Pedestrian location..Not a pedestrian
3.4 Vehicle no.....2	3.11 Pedestrian movement..Not a pedestrian
3.12 Ped Direction.....Not a pedestrian	3.19 Roadworker injured...No

A20 Sidcup Bypass Road

1.3 Accident	Slight	On Maidstone Road, Bexley, Kent, Near The Junction With Old London Road	Accident 5 of 7
Reference: 220353616			
1.7 Date & 1.9 Time.....	Saturday 08/01/2022 18:0	1.15 Speed limit.....	40 Mph
1.11 Grid co-ordinates.....	549501/169956	1.14 Road type.....	Single c'way
1.10 Local Authority.....	Bexley	1.16 Junction detail.....	T or Staggered junction
1.12/1.13 1st road identity..	B2173	1.17 Junction control.....	Give way sign or uncontrolled
1.18/1.19 2nd road identity..	U	1.24 Special conditions...	None
1.22 Weather.....	Rain	1.25 Carriageway hazards..	None
1.21 Light conditions.....	Dark/lights lit	1.5 Number of vehicles...	3
1.20a Crossing(human).....	No Human control within	1.6 Number of casualties..	1
1.20b Crossing(physical).....	No crossing facility wit	1.23 Surface.....	Wet

Did a police officer attend?
Yes

Accident Description
Not Known How Collision Occurred

3 Vehicles

2.4 Veh ref no.....1	2.16 First impact.....Nearside
2.17 Other vehicle.....0	2.12 Hit object in c'way..None
2.5 Vehicle class.....Car	2.14 Hit object off c'way.None
2.10 Junction location...Approaching or parked on appr	2.18 Parts damaged..... / /
2.9 Restricted location.On main carriageway	2.21 Driver gender.....Female
2.8 Movement from/to....East West	2.22 Driver age.....28
2.7 Manoeuvres.....Going ahead other	2.24 Hit and Run.....No
2.11 Skidding.....No	2.23 Breath test.....Not requested
2.13 Left c'way.....Did not leave c'way	2.29 Journey purpose.....Other
2.6 Towing.....No	
2.28 Foreign vehicle.....Not foreign	

2.4 Veh ref no.....2	2.16 First impact.....Front
2.17 Other vehicle.....0	2.12 Hit object in c'way..None
2.5 Vehicle class.....Car	2.14 Hit object off c'way.None
2.10 Junction location...Approaching or parked on appr	2.18 Parts damaged..... / /
2.9 Restricted location.On main carriageway	2.21 Driver gender.....Female
2.8 Movement from/to....West East	2.22 Driver age.....52
2.7 Manoeuvres.....Going ahead other	2.24 Hit and Run.....No
2.11 Skidding.....No	2.23 Breath test.....Not requested
2.13 Left c'way.....Left c'way Offside	2.29 Journey purpose.....Other
2.6 Towing.....No	
2.28 Foreign vehicle.....Not foreign	

2.4 Veh ref no.....3	2.16 First impact.....Front
2.17 Other vehicle.....0	2.12 Hit object in c'way..None
2.5 Vehicle class.....Car	2.14 Hit object off c'way.None
2.10 Junction location...Mid junction	2.18 Parts damaged..... / /
2.9 Restricted location.On main carriageway	2.21 Driver gender.....Male
2.8 Movement from/to....North South east	2.22 Driver age.....86
2.7 Manoeuvres.....Turning left	2.24 Hit and Run.....No
2.11 Skidding.....No	2.23 Breath test.....Not requested
2.13 Left c'way.....Did not leave c'way	2.29 Journey purpose.....Other
2.6 Towing.....No	
2.28 Foreign vehicle.....Not foreign	

1 Casualty

3.5 Cas ref no.....1	3.15 Car passenger.....No
3.6 Casualty class.....Driver or Rider	3.16 PSV passenger.....No
3.7 Gender.....Male	3.14 Seat belt usage.....Not worn
3.8 Age.....86	3.13 School pupil.....Other (3.19 School
3.9 Severity.....Slight	3.10 Pedestrian location..Not a pedestrian
3.4 Vehicle no.....3	3.11 Pedestrian movement..Not a pedestrian
3.12 Ped Direction.....Not a pedestrian	3.19 Roadworker injured...No

A20 Sidcup Bypass Road

1.3 Accident	Slight	On Sidcup Bypass A20, 400 Metres East Of Sandy	Accident 7 of 7
--------------	--------	--	-----------------

Reference: 220391274 Lane: _____

1.7 Date & 1.9 Time.....Saturday 30/07/2022 12:1	1.15 Speed limit.....70 Mph
1.11 Grid co-ordinates.....548340/169990	1.14 Road type.....Dual c'way
1.10 Local Authority.....Bromley	1.16 Junction detail.....Not at or within 20m of junct
1.12/1.13 1st road identity..A20	1.17 Junction control.....
1.18/1.19 2nd road identity..U	1.24 Special conditions...None
1.22 Weather.....Fine	1.25 Carriageway hazards..None
1.21 Light conditions.....Daylight	1.5 Number of vehicles...1
1.20a Crossing(human).....No Human control within	1.6 Number of casualties..1
1.20b Crossing(physical).....No crossing facility wit	1.23 Surface.....Drv

**Did a police
officer
attend?**
Yes

Accident Description
Not Known How Collision Occurred

1 Vehicle

2.4 Veh ref no.....1	2.16 First impact.....Front
2.17 Other vehicle.....0	2.12 Hit object in c'way..None
2.5 Vehicle class.....Car	2.14 Hit object off c'way.Central crash barrier
2.10 Junction location...Not at junction	2.18 Parts damaged..... / /
2.9 Restricted location.On main carriageway	2.21 Driver gender.....Female
2.8 Movement from/to....West East	2.22 Driver age.....49
2.7 Manoeuvres.....Changing lane to right	2.24 Hit and Run.....No
2.11 Skidding.....No	2.23 Breath test.....Not requested
2.13 Left c'way.....Left c'way offside onto	2.29 Journey purpose.....Other
2.6 Towing.....No	
2.28 Foreign vehicle.....Not foreign	

1 Casualty

3.5 Cas ref no.....1	3.15 Car passenger.....No
3.6 Casualty class.....Driver or Rider	3.16 PSV passenger.....No
3.7 Gender.....Female	3.14 Seat belt usage.....Not worn
3.8 Age.....49	3.13 School pupil.....Other (3.19 School
3.9 Severity.....Slight	3.10 Pedestrian location..Not a pedestrian
3.4 Vehicle no.....1	3.11 Pedestrian movement..Not a pedestrian
3.12 Ped Direction.....Not a pedestrian	3.19 Roadworker injured...No