



Hazardous Material Asset Register - Detail for SharePoint



The purpose of this report is to detail the presence of any known (K), Presumed (P) or Strongly Presumed (SP) Asbestos Containing Materials (ACMs) within this location / asset. Any areas inaccessible during previous asbestos surveys are presumed (P) to contain ACMs until confirmed otherwise. All inaccessible areas will need to be surveyed prior to work being undertaken in these areas. Prior to any intrusive works commencing a Hazardous Materials Impact Assessment (F6048) must be submitted to [redacted]@tfl.gov.uk All staff / contractors working on this property must remain vigilant during their works and if any suspect material is encountered which is likely to be disturbed, contact the Hazardous Materials team prior to continuing the impacted works. Associated photographs can be found listed against the Maximo Reference number on the subsequent report.

Run date: 20/02/2024 Line: JNP Assessment Status: All Material Status: All Material Type: All

Ref.	Status	Status Date	Main Line	Location Code	Location Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Positio	Notes	Qty. Metre	Qty. Units	Lead Paint %	Surface Code	Asbestos Type	Assessme Score	Date of Last Reinspectio	Report Ref.	Above False Ceiling	Below False Floor	
31993	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	12			Westinghouse large		1			Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
31993							1																
31658	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	16		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
31658							1																
31661	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	23		RHS	Trackside equipment Westinghouse large					Chrysotile	2	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
31661							1	1															
46060	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	24		RHS	Trackside equipment: Westinghouse large					Chrysotile	2	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
46060							1	1															
31662	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Cable Sheath	Asbestos	Known	24		RHS	Woven cable sheath. Entry: JH, route: 1x5mmØ severed cables. 0.7x1 no					Unencapsula highly friable	Chrysotile	12	23/10/2008			
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
31662							1	3	2	3	3												
31663	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	25		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
31663							1																
35301	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	26		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
35301							1																
31664	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Cable Sheath	Asbestos	Known	26		RHS	Woven cable sheath. Entry: JH, route: 1x5mmØ severed cables. 0.7x1 no					Unencapsula highly friable	Chrysotile	12	23/10/2008			
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								



Hazardous Material Asset Register - Detail for SharePoint



Ref.	Status	Status Date	Main Line	Location Code	Location Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Positio	Notes	Qty. Metre	Qty. Units	Lead Paint %	Surface Code	Asbestos Type	Assessme Score	Date of Last Reinspectio	Report Ref.	Above False Ceiling	Below False Floor		
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity									
							31664	1	3	2	3	3												
31666	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	26		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008					
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity									
							31666	1																
34498	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	27		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008					
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity									
							34498	1																
31674	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	158		RHS	Trackside equipment Westinghouse large Notes from 2021 re-inspection: and small westinghouse box				2		Chrysotile	2	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity									
							31674	1	1															
31675	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	159		RHS	Trackside equipment Westinghouse large					Chrysotile	2	23/10/2008					
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity									
							31675	1	1															
31676	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	160		RHS	Trackside equipment Westinghouse large					Chrysotile	2	23/10/2008					
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity									
							31676	1	1															
31759	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	161		RHS	Trackside equipment Westinghouse large					Chrysotile	2	17/01/2013					
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity									
							31759	1	1															
31758	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	161		RHS	Trackside equipment Westinghouse large					Chrysotile	2	23/10/2008					
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity									
							31758	1	1															
46061	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Cable Sheath	Asbestos	Known	210		RHS	numerous woven cable sheath Entry: JH4, route: 2x15mmØ					Unencapsula medium density or encapsulatec highly friable materials	Chrysotile	8	23/10/2008				



Hazardous Material Asset Register - Detail for SharePoint



Ref.	Status	Status Date	Main Line	Location Code	Location Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Positio	Notes	Qty. Metre	Qty. Units	Lead Paint %	Surface Code	Asbestos Type	Assessme Score	Date of Last Reinspectio	Report Ref.	Above False Ceiling	Below False Floor		
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity									
							46061	1	1	2	2	2												
31763	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	234		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008					
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity									
							31763	1																
31764	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	234		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008					
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity									
							31764	1																
31766	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	235		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008					
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity									
							31766	1																
31768	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	236		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008					
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity									
							31768	1																
31767	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	236		RHS	Trackside equipment Westinghouse large					Chrysotile	1	17/01/2013					
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity									
							31767	1																
31769	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	236		RHS	Trackside equipment Westinghouse large					Chrysotile	2	23/10/2008					
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity									
							31769	1	1															
31774	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	392		RHS	Trackside equipment Westinghouse small					Chrysotile	2	23/10/2008					
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity									
							31774	1	1															
31776	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Cable Sheath	Asbestos	Known	465		RHS	Signal section cloth. Entry: trackside equipment boxes, route 5-35mmØ in between trackside. Numerous amounts					Unencapsula medium density or encapsulated highly friable materials	Chrysotile	8	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity									
							31776	1	1	2	2	2												
31777	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	465		RHS	Trackside equipment Westinghouse large					Chrysotile	2	23/10/2008					



Hazardous Material Asset Register - Detail for SharePoint



Ref.	Status	Status Date	Main Line	Location Code	Location Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Positio	Notes	Qty. Metre	Qty. Units	Lead Paint %	Surface Code	Asbestos Type	Assessme Score	Date of Last Reinspectio	Report Ref.	Above False Ceiling	Below False Floor	
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							31777	1	1														
35389	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	466		RHS	Trackside equipment Westinghouse large					Chrysotile	2	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							35389	1	1														
31778	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	467		RHS	Trackside equipment Westinghouse large					Chrysotile	2	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							31778	1	1														
31780	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	469		RHS	Trackside equipment Westinghouse large					Chrysotile	2	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							31780	1	1														
31781	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	470		RHS	Trackside equipment Westinghouse large					Chrysotile	2	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							31781	1	1														
35390	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	470		RHS	Trackside equipment Westinghouse large					Chrysotile	2	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							35390	1	1														
31782	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	480		RHS	Trackside equipment Westinghouse large					Chrysotile	2	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							31782	1	1														
31869	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Cable Sheath	Asbestos	Known	632		RHS	2 x 30mm cable leaving box					Chrysotile	2	17/01/2013				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							31869	1	1														
31871	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	640		RHS	Trackside equipment Westinghouse small					Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							31871	1															
31872	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	757		RHS	Trackside equipment Westinghouse small		1			Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							31872	1															



Hazardous Material Asset Register - Detail for SharePoint



Ref.	Status	Status Date	Main Line	Location Code	Location Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Positio	Notes	Qty. Metre	Qty. Units	Lead Paint %	Surface Code	Asbestos Type	Assessme Score	Date of Last Reinspectio	Report Ref.	Above False Ceiling	Below False Floor
31873	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Cable Sheath	Asbestos	Known	757	796	LHS	Woven cable sheath. Entry: trackside equipment, route: 5-30mmØ, JH1-JH2 in between trackside equipment boxes				Unencapsula medium density or encapsulated highly friable materials	Chrysotile	8	23/10/2008			
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							31873	1	1	2	2	2										
31874	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	788		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008			
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							31874	1														
31875	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Cable Sheath	Asbestos	Known	788		RHS	2 x 15mm cable					Chrysotile	2	17/01/2013			
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							31875	1	1													
31876	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	789		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008			
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							31876	1														
31878	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	790		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008			
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							31878	1														
31877	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	790		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008			
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity							
							31877	1														



Hazardous Material Asset Register - Detail for SharePoint



Ref.	Status	Status Date	Main Line	Location Code	Location Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Positio	Notes	Qty. Metre	Qty. Units	Lead Paint %	Surface Code	Asbestos Type	Assessme Score	Date of Last Reinspectio	Report Ref.	Above False Ceiling	Below False Floor	
31881	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	792		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							31881	1															
31880	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	792		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							31880	1															
31882	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Cable Sheath	Asbestos	Known	792		RHS	1 x 15mm cable					Chrysotile	2	17/01/2013				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							31882	1	1														
31883	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	793		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							31883	1															
53858	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Other Electrical Boxes	Asbestos	Presumed	794			Tencore		1				0	11/12/2021				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							53858																
35399	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Cable Sheath	Asbestos	Known	917		LHS	Woven cable sheath. Limited access due to height. Numerous amounts					Unencapsula medium density or encapsulated highly friable materials	Chrysotile	8	23/10/2008			
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							35399	1	1	2	2	2											
46134	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Ducts	Asbestos	Known	919		LHS	Cement troughing x6 Notes from 2021 reinspection: Bitumen cables not troughing		6				0	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							46134																
31887	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Ducts	Asbestos	Known	920		RHS	Cement troughing Notes from 2021 reinspection: Bitumen cables not troughing		2			Chrysotile	1	23/10/2008				
							Ref.	Material: Asbestos Type	Material : Condition Code	Material : Product Type	Material : Surface Code	Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity								
							31887	1															
31891	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	1143		RHS	Trackside equipment Westinghouse small					Chrysotile	1	23/10/2008				






Hazardous Material Asset Register - Detail for SharePoint






Ref.	Status	Status Date	Main Line	Location Code	Location Description	Area	Material Type	Material Status	Start(m)	Finish(m)	Linear Positio	Notes	Qty. Metre	Qty. Units	Lead Paint %	Surface Code	Asbestos Type	Assessme Score	Date of Last Reinspectio	Report Ref.	Above False Ceiling	Below False Floor
							Ref.	Material: Asbestos Type			Material : Condition Code	Material : Product Type	Material : Surface Code			Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity			
							31891	1														
35400	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	1144		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008			
							Ref.	Material: Asbestos Type			Material : Condition Code	Material : Product Type	Material : Surface Code			Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity			
							35400	1														
31894	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	1145		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008			
							Ref.	Material: Asbestos Type			Material : Condition Code	Material : Product Type	Material : Surface Code			Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity			
							31894	1														
31892	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	1145		RHS	Trackside equipment Westinghouse large					Chrysotile	1	23/10/2008			
							Ref.	Material: Asbestos Type			Material : Condition Code	Material : Product Type	Material : Surface Code			Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity			
							31892	1														
31980	ACTIVE	20/02/2023	N	N126-N-NBFA	Road NBFA - NOR - Old Street to Angel	Westinghouse Boxes	Asbestos	Presumed	1311		RHS	Trackside equipment Westinghouse small					Chrysotile	1	23/10/2008			
							Ref.	Material: Asbestos Type			Material : Condition Code	Material : Product Type	Material : Surface Code			Priority : Disturbance	Priority : Exposure	Priority : Maint. Activity	Priority : Occupant Activity			
							31980	1														

Hazardous Materials - Photographs for SharePoint

Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	31993	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 12 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Westinghouse large	
Reference:	31658	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 16 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	31661	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 23 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	31662	
Description:	Asbestos: Known N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 24 Finish(m): Not Specified	
Hazard Area:	Cable Sheath	
Comments:	Woven cable sheath. Entry: JH, route: 1x5mmØ severed cables. 0.7x1 no	




Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	46060	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 24 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment: Westinghouse large	
Reference:	31663	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 25 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	31664	
Description:	Asbestos: Known N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 26 Finish(m): Not Specified	
Hazard Area:	Cable Sheath	
Comments:	Woven cable sheath. Entry: JH, route: 1x5mmØ severed cables. 0.7x1 no	
Reference:	35301	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 26 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	

Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	31666	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 26 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	34498	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 27 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	31674	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 158 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large Notes from 2021 re-inspection: and small westinghouse box	
Reference:	31675	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 159 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	





Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	31676	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 160 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	31759	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 161 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	31758	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 161 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	46061	
Description:	Asbestos: Known N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 210 Finish(m): Not Specified	
Hazard Area:	Cable Sheath	
Comments:	numerous woven cable sheath Entry: JH4, route: 2x15mmØ	

Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	31764	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 234 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	31763	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 234 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	31766	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 235 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	31768	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 236 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	

Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	31769	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 236 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	31767	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 236 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	31774	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 392 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse small	
Reference:	31777	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 465 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	


Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	31776	
Description:	Asbestos: Known N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 465 Finish(m): Not Specified	
Hazard Area:	Cable Sheath	
Comments:	Signal section cloth. Entry: trackside equipment boxes, route 5-35mmØ in between trackside. Numerous amounts	
Reference:	35389	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 466 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	31778	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 467 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	31780	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 469 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	

Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	31781	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 470 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	35390	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 470 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	31782	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 480 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	31869	
Description:	Asbestos: Known N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 632 Finish(m): Not Specified	
Hazard Area:	Cable Sheath	
Comments:	2 x 30mm cable leaving box	

Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	31871	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 640 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse small	
Reference:	31873	
Description:	Asbestos: Known N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 757 Finish(m): 796	
Hazard Area:	Cable Sheath	
Comments:	Woven cable sheath. Entry: trackside equipment, route: 5-30mmØ, JH1-JH2 in between trackside equipment boxes	
Reference:	31872	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 757 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse small	
Reference:	31874	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 788 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	

Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	31875	
Description:	Asbestos: Known N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 788 Finish(m): Not Specified	
Hazard Area:	Cable Sheath	
Comments:	2 x 15mm cable	
Reference:	31876	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 789 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	31877	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 790 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	31878	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 790 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	





Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	31881	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 792 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	31880	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 792 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	31882	
Description:	Asbestos: Known N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 792 Finish(m): Not Specified	
Hazard Area:	Cable Sheath	
Comments:	1 x 15mm cable	
Reference:	31883	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 793 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	


Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	53858	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 794 Finish(m): Not Specified	
Hazard Area:	Other Electrical Boxes	
Comments:	Tencore	
Reference:	35399	
Description:	Asbestos: Known N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 917 Finish(m): Not Specified	
Hazard Area:	Cable Sheath	
Comments:	Woven cable sheath. Limited access due to height. Numerous amounts	
Reference:	46134	
Description:	Asbestos: Known N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 919 Finish(m): Not Specified	
Hazard Area:	Ducts	
Comments:	Cement troughing x6 Notes from 2021 reinspection: Bitumen cables not troughing	
Reference:	31887	
Description:	Asbestos: Known N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 920 Finish(m): Not Specified	
Hazard Area:	Ducts	
Comments:	Cement troughing Notes from 2021 re-inspection: Bitumen cables not troughing	

Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	31891	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 1143 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse small	
Reference:	35400	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 1144 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	31894	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 1145 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	
Reference:	31892	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 1145 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse large	

Photographs are provided below against each Maximo reference number as per the above Hazardous Material Asset Register

Reference:	31980	
Description:	Asbestos: Presumed N126-N-NBFA: Road NBFA - NOR - Old Street to Angel Start(m): 1311 Finish(m): Not Specified	
Hazard Area:	Westinghouse Boxes	
Comments:	Trackside equipment Westinghouse small	